

LICENSEE EVENT REPORT

CONTROL BLOCK: [][][][][][] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [C][T][M][N][S][I] [2] [0][0]-[0][0][0][0][0][0]-[0][0] [3] [4][1][1][1][1][1] [4] [5]

CON'T [0][1] REPORT SOURCE [L][6] [0][5][0][0][0][2][4][5] [7] [0][8][2][7][7][9] [8] [0][9][2][4][7][9] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0][2] On August 27, 1979, at 0900 hours, it was discovered that the semiannual functional [0][3] test of the cable vault smoke detection system had been inadvertently overlooked. [0][4] No consequences.

[0][9] SYSTEM CODE [A][B] (11) CAUSE CODE [A] (12) CAUSE SUBCODE [C] (13) COMPONENT CODE [I][N][S][T][R][U] (14) COMP. SUBCODE [E] (15) VALVE SUBCODE [Z] (16) LER RD REPORT NUMBER [7][9] (17) EVENT YEAR [7][9] (21) SEQUENTIAL REPORT NO. [0][2][7] (24) OCCURRENCE CODE [0][3] (28) REPORT TYPE [L] (30) REVISION NO. [0] (32) ACTION TAKEN [X] (18) FUTURE ACTION [X] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0][0][0] (22) ATTACHMENT SUBMITTED [Y] (23) NPRD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [Z] (25) COMPONENT MANUFACTURER [Z][9][9][9] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1][0] The subject surveillance was inadvertently overlooked because it was not listed on [1][1] either the vendor computer schedule or the unit's surveillance schedule. The [1][2] surveillance was accomplished and added to the surveillance schedules. [1][3] [1][4]

[1][5] FACILITY STATUS [E] (28) % POWER [1][0][0] (29) OTHER STATUS NA (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION: Surveillance Review (32) [1][6] ACTIVITY CONTENT [Z] (33) [Z] (34) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)

[1][7] PERSONNEL EXPOSURES NUMBER [0][0][0] (37) TYPE [Z] (38) DESCRIPTION NA (39)

[1][8] PERSONNEL INJURIES NUMBER [0][0][0] (40) DESCRIPTION NA (41)

[1][9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION NA (43) 1065 312

[2][0] PUBLICITY ISSUED [Z] (44) DESCRIPTION NA (45) 7910010356 NRC USE ONLY

NAME OF PREPARER: Ralph H. Young, Jr.

PHONE: 203-447-1792 X-475