FORM NRC-591 (3-77)

U.S. NUCLEAR REGULATORY COMMISSION

E, TV, Ionitiel C. Fires

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

P. O. Box 1166 Cusyens, Puerto Eleo 06654 3. DOCKET HUMBER(S) 4. LICENSE HUMB 070-02871 SEM-182		T. N. 31 16 76	
6. INSPECTION FINDINGS The inspection was an examination Commission's rules and regulations a	of the activities conducted under you not the conditions of your license. The	er lice as they relate to radiation safety and to inspection consisted of selective examinations of	f procedures and repre-
	ce or unsafe conditions were four	tor. The findings as a result of this inspection are and.	as idilows.
The following items of noncom	pliance related to records, signs, a	and labels were found:	
☐ A. Rooms or areas were n	ot properly posted to indicate the	e presence of a RADIATION AREA. 10 CF	R 20.203(b) or 34.43
	ot properly posted to indicate the	e presence of a HIGH RADIATION AREA.	
C. Rooms or areas were n 10 CFR 20.203(d)	ot properly posted to indicate the	e presence of an AIRBORNE RADIOACTI	VITY AREA.
D. Rooms or areas were n	ot properly posted to indicate the	presence of RADIOACTIVE MATERIAL	. 10 CFR 20.203(e)
E. Containers were not pr 10 CFR 20.203(f) (1)		sence of RADIOACTIVE MATERIAL.	
F. A current copy of 10 0 made available. 10 CF		a copy of the operating procedures was not	properly posted or
G. Form NRC-3 was not p	properly posted. 10 CFR 20.206		
☐ H. Records of the radiation	on exposure of individuals were no	ot properly maintained. 10 CFR 20.401(a)	or 34.33(b)
☐ 1. Records of surveys or	disposals were not properly maint	ained. 10 CFR 20.401(b) or 34.43(d)	
J. Records of receipt, tra 10 CFR 30.51, 40.61		ry of licensed material were not properly m	aintained.
K. Records of leak tests w	ere not maintained as paraged	in your license, or 10 CFR 34.25(c)	
☐ L. Records of inventories	were not maintained. 10 CFR 34	.26	50
M. Utilization logs were no	ot maintained. 10 CFR 34.27		= 70
☐ N. Records of radiation so	urvey instrument calibration were	not maintained. 10 CFR 34.24	
O. Records of teletherapy	electrical interlock tests were no	t maintained as prescribed in your license.	
P. Other			
-	- Sich	(NRC Inspector)	
	lained and I understand the ite ected within the next 30 days.	ems of noncompliance listed above. The	items of
July 31, 19	79 -111	Massey, In (vie ?	j. M.
(Date)		(Licensee Representative - Title or Position	,