



MAINE YANKEE ATOMIC POWER COMPANY •

Box 450, RFD 2
Wiscasset, Maine 04578

September 25, 1979

POOR ORIGINAL

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attention: Mr. Boyce H. Grier, Director

Reference: a) License No. DPR-36 (Docket No. 50-309)

Dear Sir:

Subject: Maine Yankee Reportable Occurrence #79-017/99X-0

Please find enclosed the Licensee Event Report for Maine Yankee Reportable Occurrence No. 79-017/99X-0. This event does not represent a violation of Technical Specifications but is submitted as part of the reporting requirements of Technical Specification 3.2.

Enclosed is a summary report required by Technical Specification 3.2.4 describing the events and conditions relative to exceeding a reactor coolant Dose Equivalent Iodine value of 1.0 uc/gram.

We trust this information will be satisfactory. Should additional information be required, please feel free to contact us.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

Edwin C. Wood

Edwin C. Wood
Plant Manager

ECW/ds
enclosures

1071 001

*1002
5/11*

S 7910020400