

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 26, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - TENSILE ANCHOR CAPACITIES LOWER
THAN DESIGN ALLOWABLES - NCR CEB 79-5 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
T. E. Burdette on February 12, 1979, in accordance with 10 CFR 50.55(e).
Interim reports were submitted on March 14, 1979, and May 14, 1979.
Enclosed is our final report.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stallo, Jr., Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1071 178

B019
S10

7910020 502