

ARKANSAS POWER & LIGHT COMPANY POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

October 19, 1979

2-109-13

Mr. K. V. Seyfrit, Director Office of Inspection and Enforcement Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76011

Subject: Arkansas Nuclear One-Unit 2

Docket No. 50-368 License No. NPF-6 LER 79-080/03L-0 and LER 79-081/03L-0 (File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 2 Technical Specification 6.9.1.9b, we have attached the subject reports concerning the loss of indication for the NaOH addition tank discharge valve (IER 79-80/03L-0) and the tripping of the Turbine Driver for the Steam Driven Pump 2P7A (LER 79-081/03L-0).

Very truly yours,

David C. Trimble

David C. Trimble Manager, Licensing

DCT:MAS:gp

Attachments

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and
Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. W. D. Johnson
U. S. Nuclear Regulatory Commission
P. O. Box 2090
Russellville, AR. 72801

Mr. Norman Haller, Director
Office of Management and
Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

1203 128