

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 7, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - PIPE SUPPORT DESIGNERS DID NOT
IN SOME CASES CONSIDER THE SUM OF DEFLECTIONS DUE TO THERMAL, STATIC,
AND SAFE SHUTDOWN EARTHQUAKE - NCR SWP 79-S-7 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
W. T. Cottle on May 22, 1979, in accordance with 10 CFR 50.55(e).
An interim report was submitted on June 21, 1979. Enclosed is our
final report.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Bo 19
S 1
948324

7909140 4/0 S