

LICENSEE EVENT REPORT

CONTROL BLOCK: [1] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: M D C C I N [2] LICENSE NUMBER: 0 0 0 - 1 0 0 0 0 0 0 - 0 0 [3] LICENSE TYPE: 4 1 1 1 1 1 [4] CAT 58 [5]

CON'T REPORT SOURCE: L [6] DOCKET NUMBER: 0 5 0 0 0 3 1 1 7 [7] EVENT DATE: 0 8 0 6 1 7 1 9 [8] REPORT DATE: 0 8 1 3 1 1 7 1 9 [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES [10]

[0 2] At 0845, 12 charging pump was placed out of service because of pump trips due to [0 3] low suction pressure and unsuccessful attempts to restart the pumps and maintain [0 4] it in operation. Placing this pump out of service reduced the number of operable [0 5] charging pumps to one (as number 11 charging pump was isolated because of a packing [0 6] leak). #11 charging pump was repaired and placed back into service at 1530 on 8/6/79, [0 7] bringing the number of operable pumps to two as required by T.S.3.1.2.4. #13 [0 8] charging pump remained operable during event. This is not a repetitive occurrence. [9]

SYSTEM CODE: P I C [11] CAUSE CODE: E [12] CAUSE SUBCODE: F [13] COMPONENT CODE: I N S T R U [14] COMP. SUBCODE: E [15] VALVE SUBCODE: Z [16]

LER NO REPORT NUMBER: [17] EVENT YEAR: 7 9 [21] SHUTDOWN METHOD: [23] HOURS: 0 0 0 [22] ATTACHMENT SUBMITTED: [23] REPORT TYPE: L [30] REVISION NO.: 0 [32]

ACTION TAKEN: A [18] FUTURE ACTION: Z [19] EFFECT ON PLANT: Z [20] SHUTDOWN METHOD: Z [21] HOURS: 0 0 0 [22] ATTACHMENT SUBMITTED: N [23] NPRD-4 FORM SUB.: N [24] PRIME COMP. SUPPLIER: A [25] COMPONENT MANUFACTURER: A 5 0 1 [26]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS [27]

[1 0] #12 charging pump low suction pressure trips were caused by a faulty pressure [1 1] indicating switch: 1-PC-224Y. This Ashcroft model 1379 TAXEF was repaired by [1 2] replacement of gauge internals which were worn. This is being considered as an [1 3] isolated failure and no further corrective action is to be taken. [1 4]

FACILITY STATUS: E [28] % POWER: 0 8 7 [29] OTHER STATUS: NA [30] METHOD OF DISCOVERY: A [31] DISCOVERY DESCRIPTION: Operator Observation [32]

ACTIVITY CONTENT: Z [33] RELEASED: Z [34] AMOUNT OF ACTIVITY: NA [35] LOCATION OF RELEASE: NA [36]

PERSONNEL EXPOSURES: 0 0 0 [37] TYPE: Z [38] DESCRIPTION: NA [39]

PERSONNEL INJURIES: 0 0 0 [40] DESCRIPTION: NA [41]

LOSS OF OR DAMAGE TO FACILITY: Z [42] TYPE: NA [43]

PUBLICITY ISSUED: Z [44] DESCRIPTION: NA [45]

NAME OF PREPARER: R. P. Heibel/P. G. Rizzo PHONE: (301) 234-7942/7986

POOR ORIGINAL 343360 7909140 444