#### OPERATING DATA REPORT

DOCKET NO. 50-321

DATE 10-1-79

COMPLETED BY G. L. Johnson
TELEPHONE 912-367-7781

OPERATING STATUS						
1. Unit Name: Hatch - 1		Notes				
2. Reporting Period: September 1979						
3. Licensed Thermal Power (MWt): 2436						
4. Nameplate Rating (Gross MWe): 809.3						
5. Design Electrical Rating (Net MWe): 786.3						
6. Maximum Dependable Capacity (Gross MWe):	797.3 Gross MWe					
7. Maximum Dependable Capacity (Net MWe):	864.3 Net MWe					
8. If Changes Occur in Capacity Ratings (Items N	umber 3 Through 7) Sind	ce Last Report, Give R	easons:			
9. Power Level To Which Restricted, If Any (Net 0. Reasons For Restrictions, If Any:	MWe):					
	This Month	Yrto-Date	Cumulative			
1. Hours In Reporting Period	720	6551	32855			
2. Number Of Hours Reactor Was Critical	692.5	3313.5	24001.9			
3. Reactor Reserve Shutdown Hours	0.0	0.0	0.0			
4. Hours Generator On-Line	614.6	3083.3	22567.8			
5. Unit Reserve Shutdown Hours	0.0	0.0	0.0			
6. Gross Thermal Energy Generated (MWH)	1250835	6784835	46393092			
7. Gross Electrical Energy Generated (MWH)	397410	2206070	14961580			
3. Net Electrical Energy Generated (MWH)	378002	2086319	14210377			
O. Unit Service Factor	85.4	47.1	68.7			
D. Unit Availability Factor	85.4	47.1	68.7			
. Unit Capacity Factor (Using MDC Net)	68.7	41.7	56.6			
2. Unit Capacity Factor (Using DER Net)	66.8	40.5	55.0			
Unit Forced Outage Rate	13.3	10.1	15.7			
Shutdowns Scheduled Over Next 6 Months (Ty	pe, Date, and Duration of	of Each):				
If Shut Down At End Of Report Period, Estima	ted Date of Startup:					
. Units In Test Status (Prior to Commercial Opera	ation):	Forecast	Achieved			
INITIAL CRITICALITY						
INITIAL ELECTRICITY			2.7415			

79102202741

#### AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-321

UNIT Hatch 1

DATE 10-1-79

COMPLETED BY C. L. Johnson
TELEPHONE 912-367-7781

MONTH	September	1979	3
-------	-----------	------	---

AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
402	17	491
554	18	257
644	19	-18
671	20	346
404	21	676
619	22	704
715	23	671
309	24	752
-11	25	760
19	26	760
435	27	754
615	28	750
653	29	761
699	30	757
498	31	Tribute respect to the second
106		

#### INSTRUCTIONS

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt.

(9/77)

#### UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO.

UNIT NAME
DATE

COMPLETED BY
TELEPHONE

DOCKET NO.

10-321

Hatch 1

10-10-79

6. L. Johnson

912-367-7781

## REPORT MONTH September

No.	Date	Type1	Duration (Hours)	Reason?	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
79-13 79-14 79-15	79-09-08 79-09-15 79-09-18	S F S	50:41 19:29 35:15	A A A	1 3 1		CF IA XX	PUMPXX VALVOP TRANSF	Off line due to inop RHRSW pumps  Rx Scram TCVFC  Shutdown to repair Alterrex System

5 F:

F: Forced S: Scheduled Reason

A-Equipment Failure (Explain)

B-Maintenance of Test

C-Refueling

D-Regulatory Restriction

E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain)

H-Other (Explain)

3

Method:

1-Manual 2-Manual Scram.

3-Automatic Scrain.

4-Other (Explain)

4

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

5

Exhibit 1 - Same Source

364

(9/77)

# NARRATIVE REPORT

September 8th

Shutdown to repair inop RHRSW pumps

September 10th

Generator tied to line 17:05 CST

Rx Scram TCVFC due to Alterrex Problems

September 16th

Generator on line at 14:20 CST

September 18th

Shutdown to repair Alterrex System

September 20th

Generator on line at 04:06 CST

## HATCH 1 SAFETY - RELATED MAINTE, ANCE REQUESTS TO BE REPORTED FOR SEPTEMBER 1979

NUMBER 78-4277	DATE COMPLETED	DESCRIPTION Installed seal between RWCU pump and motor
79-4699	9-6-79	Replaced all bushings and gaskets on RHR Service Water Pump "B"
79-4865	9-6-79	Replaced all bushings and gaskets on RHR Service Water Pump "1C"
79-5012	9-2-79	Investigated and repaired steam flow; feedwater flow recorder
79-4934	9-2-79	Repaired IRM "C"
79-2157	8-7-79	Installed conduit and pulled cable in RPS MG set "1A" per DCR 78-419
79-2158	8-7-79	Installed conduit and pulled cables in RPS Alternate Supply Class IE Breaker Panels per DCR 48-419
79-4046	8-24-79	Installed conduit and pulled cables in RPS Alternate Supply Class IE Breaker Panels per DCR 48-419
79-4067	8-24-79	Completed conduit installation and terminated cables for RPS Alternate Supply Class IE Breaker Panels per DCR 78-419
79-4617	8-13-79	Removed two under frequency relays from panel in warehouse and installed and calibrated in RPS MG Set Breaker Panels
79-4782	9-6-79	Installed new impellors and bushing in RHR Service Water Pump
79-4764	8-31-79	Repaired Core Spray Jockey Pump
79-4933	9-6-79	Repaired HPCI Vacuum Pump 1150 066

79-4929	8-31-79	Uncoupled the RCIC Turbine from pump for overspeed test, then coupled the RCIC Turbine back to pump
79-5021	9-2-7	Rod can not be selected on the Control Rod matrix per HNP-1-9402 for Control Rod Scram Time Testing. Investigated and repaired
79-5018	8-31-79	Replaced Unit 1 airlock door with a 3-hour rated door
79-4703	9-5-79	Repaired 4 hangers on East Wall of '58 elev. Rx building per DCR 1-7-187
79-727	8-13-79	Rerouted offgas drain lines per DCR 78-186
79-1302	8-15-79	Replaced offgas Drain Valves per DCR 78-248
79-4341	8-27-79	Wired new solenoids to offgas Drain valves to existing circuits per DCR 78-248
79-3992	9-25-79	Replaced defective Reactor Vessel Thermocouples
79-5448	9-16-79	Replaced limit switch and junction box cover on "C" outboard MSIV
79-5341	9-10-79	Checked low stops on Recirc. MG Set Scoop Tube
79-5374	9~21-79	Performed aonthly electrical PM per procedure HNP-1-6220
79-4584	9-22-79	Investigated and repaired Control Rod Drive 46-43
79-4585	9-22-79.	Investigated and repaired Control Rod Drive 30-39
79-4586	9-22-79	Investigated and repaired Control Rod Drive 22-39
79-4587	9-22-79	Investigated and repaired Control Rod Drive 38-43

79-4588	9-28-79	Repaired control rod drive accumulator solenoid valve
79-5344	9-16-79	Rod Sequence Control; page test does not work at 50% rod density. Investigated and repaired
79-5097	9-19-79	Investigated why process computer receives no signal for LPRMs
79 -5171	9-9-79	"1B" RBM is not working properly; investigated and repaired
79-5293	9-17-79	Repaired recirc flow units B and D
79-3683	9-28-79	Repaired RHR S/W strainer outlet valve
79-4813	9-17-79	Checked calibration for RHR S/W "B" Loop flow transmitter
79-4814	9-17-79	Checked calibration on RHR S/" "A" Loop flow transmitter
79-5304	9-11-79	Raplaced RHR S/W Discharge Pressure Guage on "B" Pump
79-5419	9-17-79	Repaired RHR Hx Bypass Valve "A" Loop indicator light
79-4901	9-9-79	Replaced oil in HPCI turbine
79-5024	9-6-79	Repaired HPCI Aux. oil pump
79-5054	9-9-79	Repaired HPC1 turbine oil pump
79-1608	9-18-79	Repaired oil leak from gear reducer on trolley drive on refueling platform
79-3404	9-22-79	Replaced the main hoist joy lever on the refueling platform
79-5514	9-21-79	Repaired R/W flow to canal recorder

79-5373	9-13-79	Repaired "Cooling Malfunction Bay C" alarm in the EHC cabinets
79-4294	9-19-79	Checked the validity of the calibration of instrumentation on attached list (SRM recorder, MSL leak detector, Topaz inverter)
79-4913	9-10-79	Adjusted main steam line hanger
79-5320	9-20-79	Repaired snubber MSH-30- oil leak
79-4996	9-17-79	RFPT 1A; repaired oil leaks on hydraulic control system
79-4874	9-14-79	Replaced 3 cells in R42-S005 DCR 79-216
79-5569	9-20-79	Performed battery chargers inspection
79-5244	9-11-79	Repaired N <sub>2</sub> makeup flow recorder
79-4499	9 79	Repaired motor M2, M3 Louvers in Gen. (D/G) room

Georgia Power Company Post Office Box 442 Baxley, Georgia 31513 Telephone 912 367-7781 912 537-9444

Edwin I. Hatch Nuclear Plant



the southern electric system

October 10, 1979 PM-79-893

PLANT E. I. HATCH NRC Monthly Report Docket No. 50-366

Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Sirs:

Pursuant to Section 6.9.1.6 of the Hatch Unit 2 Technical Specifications, please find attached the NRC Monthly Operating Report.

Plant Manager

MM/peb

xc: C. T. Moore

T. V. Greene

File

# OPERATING DATA REPORT

DOCKET NO. 50-366

DATE 10-1-79

COMPLETED BY G. L. Johnson 912-367-7781

OPERATING STATUS									
1. Unit Name: Hatch 2	Notes								
2. Reporting Period: September 1979									
3. Licensed Thermal Power (MWt): 2436 M									
4. Nameplate Rating (Gross MWe): 809.3									
5. Design Electrical Rating (Net MWe):									
6. Maximum Dependable Capacity (Gross MWe)									
7. Maximum Dependable Capacity (Net MWe):	764.3 Net MWe								
3. If Changes Occur in Capacity Ratings (Items Number 3 Through 7) Since Last Report, Give Reasons:									
9. Power Level To Which Restricted, If Any (Ne D. Reasons For Restrictions, If Any:									
	This Month	Yrto-Date	Cumulative						
. Hours In Reporting Period	720	624	624						
. Number Of Hours Reactor Was Critical	641.8	554.3	554.3						
. Reactor Reserve Shutdown Hours	0.0	0.0	0.0						
. Hours Generator On-Line	515.9	435.3	435.3						
. Unit Reserve Shutdown Hours	0.0	0.0	0.0						
Gross Thermal Energy Generated (MWH)	1054355	892611	892611						
Gross Electrical Energy Generated (MWH)	340620	292500	292500						
Net Electrical Energy Generated (MWH)	323398	277366	277366						
Unit Service Factor	71.6	69.8	69.8						
Unit Availability Factor	71.6	69.8	69.8						
. Unit Capacity Factor (Using MDC Net)	58.8	58.2	58.2						
Unit Capacity Factor (Using DER Net)	57.1	56.5	56.5						
Unit Forced Outage Rate	24.0	25.3	25.3						
Shutdowns Scheduled Over Next 6 Months (T	ype, Date, and Duration	of Each):							
If Sharp and Fallows									
If Shut Down At End Of Report Period, Estin	nated Date of Startup: .								
Units In Test Status (Prior to Commercial Ope	eration):	Forecast	Achieved						
INITIAL CRITICALITY									
INITIAL ELECTRICITY		Mark	1 1 115-15						
COMMERCIAL OPERATIO	N.								

# AVERAGE DAILY UNIT POWER LEVIL

DOCKET NO.	50-366		
UNIT	Hatch 2		
DATE	10-1-79		
COMPLETED BY	G. L. Johnson		
	912-367-7781		
	The second secon		

AVFRAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
602	17	54
658	18	419
340	19	720
318	20	756
707	21	671
742	22	186
680	23	507
-2	24	764
-17	25	764
-18	26	772
-13	27	770
124	28	739
627	29	10
745	30	368
495	21	Area Care and the control of the con
-17		

#### INSTRUCTIONS

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt.

(9/77)

#### REPORT MONTH September

No.	Date	Type1	Duration (Hours)	Reason?	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code5	Cause & Corrective Action to Prevent Recurrence
79-21	79-09-03	F	15:23	В	3	N/A	1A	INSTRU	Rx Scram Turbine Trip on Low Vacuum
79-22	79-09-08	S	106:45	В	1	NA	н	xxxxxx	Shutdown to repair MSR Steam Leaks
79-23	79-09-15	S	7:32	В	N/A	N/A	ZZ	ZZZZZZ	Turbine Testing
79-24	79-09-15	F	40:43	.: <sub>B</sub>	3	NA	1A	VALVOP	Rx Scram TCV Fast Closure
79-25	73-09-22	S	13:00	ь	1	NA	xx	TRANSF	Shutdown to repair Alterrex System
79-26	79-09-29	S	27:52	В	1	NA	XX	xxxxxx	Shutdown to repair EHC Oil Leak
								V	

F: Forced S: Scheduled Reason:

A-Equipment Failure (Explain)

B-Maintenance of Test

C-Refueling

D-Regulatory Restriction

E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain)

II-Other (Explain)

3 Method:

1-Manual

2-Manual Scram.

3 Automatic Scram.

4-Other (Explain)

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

(9/77)

Exhibit 1 - Same Source

## NARRATIVE REPORT UNIT 2

September	3rd	Rx Scram Turbine Trip on Low Vacuum
September	4th	Generator tied to line 0400 CST
September	8th	Shutdown to repair MSR Steam Leaks
September	12th	Generator tied to line 1315 CST
September	15th	Reduction due to Turbine Testing
September	15th	Rx Scram TCV Fast Closure
September	17th	Generator tied to line 1139 CST
September	22nd	Shutdown to repair Alterrex System
September	22nd	Generator tied to line 2350 CST
September	29th	Shutdown to repair EHC oil leak
September	30th	Generator tied to line 0714 CST

# HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS TO BE REPORTED FOR SEPTEMBER 1979

NUMBER	DATE COMPLETED	DESCRIPTION
78-4486	9-12-79	LPCI meter; repaired frequency meter
79-1506	8-29-79	Installed pressure transducrs in the Main Steam piping in Drywell
79-4211	9-5-79	Repaired Rod Block Monitor
79-4122	8-30-79	Recalibrated HPCI Turbine Temp. Recorder
79-2815	8-28-79	Repaired disc in check valve
79-3825	8-24-79	Repaired seals in Rx H <sub>2</sub> O Clean-up Pump 2B
79-3509	9-19-79	Replaced diaphragms in SRVDL pressure switches
79-3563	9-21-79	Repaired inboard MSIV "B"
79-3898	9-21-79	Negative ground on "B" SS battery recorded; investigated and repaired as needed
79-4347	9-21-79	Repaired indication light for inboard MSIV
79-4500	9-18-79	Repaired indication light for Primary Containment Isolation Check Valve
79-4509	9-21-79	Repaired bad pressure seal in main steam line drain valve
79-4252	9-21-79	Repaired reactor water sample inboard isolation valve
79-4379	9-21-79	Repaired reactor water sample inboard isolation valve
79-4388	9-21-79	Repaired IRM"F"
79-4501	9-21-79	Repaired IRM"F"

1150 075

79-4508	9-21-79	repaired IRM"E"
79-4154	9-7-79	repaired RHR SW pump 2D discharge pressure guage
79-4539	9-21-79	Calibrated jockey pump suction pressure guage
79-4540	9-21-79	Recalibrated jockey pump suction pressure guage
79-4153	9-18-79	Repaired HPCI steam line low pressure instrument isolation valve
79-4385	9-13-79	Removed agastat time delay relays which were installed per DCR 79-312 and replaced with instantaneous pickup relays
79-3490	9-11-79	Repaired RCIC isolation valve
79-2644	9-18-79	Installed stainless steel cotter pin per DCR 79-170 on refueling platform
79-4090	9-19-79	Disconnected temporary wires from Yarway column thermocouples and placed them in the junction box
79-3351	9-14-79	Repaired chemical waste sample pump B
79-3913	9-19-79	Revised mode switches and program logic in Radwaste Panel per DCR 79-314
79-3930	9-13-79	Repaired CBWRT to CPSA valve
79-4084	9-20-79	Made wiring changes to F384A control logic per DCR 79-341
79-4085	9-20-79	Made wiring changes to F538 control logic per DCR 79-315
79-4459	9-26-79	Repaired 2A diesel jacket coolant heater
79-3154	9-21-79	Repaired reaction chamber temperature control on post-LOCA H2 recombiner