

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION V

TIC

1990 N. CALIFORNIA BOULEVARD SUITE 202, WALNUT CREEK PLAZA WALNUT CREEK, CALIFORNIA 9450

Docket No. 50-94

Rockwell International Corporation Energy Systems Group 8900 DeSoto Avenue Canoga Park, California 91304

Attention: Mr. H. Weiseneak

Director, Research and Engineering

Gentlemen:

Subject: NRC Inspection of L-77 Facility


This refers to the inspection conducted by Mr. J. R. Curtis of this office on September 4-6, 1979 of facilities possessed under the NRC License No. R-40, and to the discussion of our findings held by Mr. Curtis with you and Dr. M. Remley at the conclusion of the inspection.

This inspection was an examination of the status of the reactor facility possessed under the license, and of the storage and surveillance of reactor components as presently held under NRC Dismantling Order (letter to Atomics International from K. Goller, dated September 29, 1976.)

No items of noncompliance with NRC requirements were identified within the scope of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office, within 20 days of the date of this letter, requesting that such information be withheld from public disclosure. The application must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

1504 012



-2-

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,

H. E. Book, Chief Fuel Facility and

A.E. Book

Materials Safety Branch

Enclosure: IE Inspection Report No. 50-94/79-01

1504 013