

## NUCLEAR REGULATORY COMMISSION REGION I

631 PARE AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

Docket No. 50-272

SEP 1 2 1979

Public Service Electric and Gas Company ATTN: Mr. F. W. Schneider Vice President - Production 80 Park Place Newark, Mew Jersey 07101

Gentlemen:

Subject: Inspection No. 50-272/79-09

This refers to the inspection conducted by Mr. M. Rogers of this office on March 12-16 and April 18, 1979, at Salem Nuclear Generating Station, Unit 1, Mancocks Bridge, New Jersey, of activities authorized by NRC License No. DPR-70 and to the discussions of our findings held by Mr. Rogers with Mr. Midura and other member of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of elective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Our inspector also verified the steps you have taken to correct the item of noncompliance brought to your attention in a letter dated August 4, 1978. We have no further questions regarding your action at this time.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. This item of noncompliance has been categorized into the levels as dereibed in our correspondence to you dated December 31, 1974. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Although Section 2.201 requires you to submit to this office, within 20 days of your receipt of this notice, a written statement of explanation, we note that this item of noncompliance was corrected prior to the completion of our inspection, and therefore, no response with respect to this matter is required.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, doc mentation of findings of your control and accounting procedures for safeguarding special nuclear materials and your facility security procedures are exempt from disclosure; therefore, the enclosures to this letter, will not be placed in the Public Document Room and will receive limited distribution.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Walter G. Martin, Chief Safeguards Branch

Offin 14. Blut

Enclosures:

1. Appendix A, Notice of Violation (Contains 2.790 Information)

 Office of Inspection and Enforcement Inspection Report Number 50-272/79-09 (Contains 2.790 Information)

cc w rpt cover sheet:

F. P. Librizzi, General Manager - Electric Production

E. N. Schwalje, Manager - Quality Assurance

H. J. Midura, Manager - Salem Generating Station

R. L. Mittl, General Manager - Licensing and Environment

1268 352