## Appendix A

## NOTICE OF VIOLATION

Cincinnatí Gas and Electric Company

Docket No. 50-358

Based on the inspection conducted on September 10 and 11, 1979, it appears that certain of your activities were not conducted in full compliance with NRC requirements as noted below. This item is a deficiency.

Contrary to 10 CFR 50 Appendix B, Criterion XIII and the Zimmer Nuclear Power Station FSAR Chapter 17 paragraph 17.1.13, the following unacceptable conditions were observed:

- On September 10, 1979, the floor above the switchgear room adjacent to the control room was observed to have excess sandlike dust as a result of disentegration out of the Zonolite floorings due to walking. Miscellaneous construction debris was observed to be scattered on the floor.
- b. Welding activities were in progress without adequately protecting the installed cables.

1302 003