50-328

TENNESSEE VALLEY AUTHORITY

ADR

CHATTANOOGA, TENNESSEE 37401

830 Power Building

October 16, 1978

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - PLANT CONFIGURATION DIFFERENT THAN DRAWINGS OF RECORD - NCR 2P - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Region II Inspector Tom Burdette on September 15, 1978. Enclosed is our first interim report. We will submit our next report by January 5, 1979.

If you have any questions regarding this matter, please get in touch with M. R. Wisenburg at FTS 854-2581.

Very truly yours,

My. E. Gilleland

Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

7811030263

14:01A 81130 81

ATLANTA, GEORGIA