



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TIC

AREA

APR 4 1979

Docket No. 50-341

The Detroit Edison Company
ATTN: Mr. Edward Hines
Assistant Vice President
and Manager Quality
Assurance
2000 Second Avenue
Detroit, MI 48226

Gentlemen:

This refers to the inspection conducted by Mr. I. T. Yin of this office at the Enrico Fermi 2 site on March 14-16, 1979, of activities authorized by NRC Construction Permit No. CPPR-87 and to the discussion of our findings with Mr. T. A. Alessi and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within thirty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

During a telephone conversation, on March 21, 1979, between Messrs. T. A. Alessi, T. H. Dickson and others of your staff and Messrs. I. T. Yin, H. S. Phillips and D. H. Danielson of this office, your company agreed to inform this office of changes made to your program and frequently report

2282 188

7906140647


APR 4 1979

the progress relative to correcting hanger installation problems. In addition, you agreed to inform this office, prior to lifting the stop work order on QA Level I hanger installations, so a member of my staff can observe and evaluate hanger work performed to demonstrate the effectiveness of the corrective action and the steps taken to prevent recurrence.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room, except as follows. If the enclosures contain information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



G. Fiorelli, Chief
Reactor Construction and
Engineering Support Branch

Enclosures:

1. Appendix A, Notice of Violation
2. IE Inspection Report
No. 50-341/79-07

cc w/encls:

Central Files
Reproduction NRC 20b
PDR
Local PDR
NSIC
TIC
Ronald Callen, Michigan Public
Service Commission
Eugene B. Thomas, Jr.,
Attorney

2282 189