

**Florida  
Power**  
CORPORATION

October 30, 1979

File: 3-0-3-a-3

Mr. J. P. O'Reilly  
Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Suite 3100  
101 Marietta Street, N.W.  
Atlanta, GA 30303

Subject: Crystal River Unit 3  
Docket No. 50-302  
Operating License No. DPR-72  
IE Bulletin 79-14

Dear Mr. O'Reilly:

Enclosed is a copy of the IE Bulletin 79-14 Report for Florida Power Corporation's Crystal River Unit 3 Nuclear Plant, which was prepared by Gilbert Associates, Inc.

This report is the response of the Florida Power Corporation to NRC IE Bulletin 79-14, dated July 2, 1979, including Revision 1, dated July 18, 1978, Supplement 1, dated August 15, 1979, and Supplement 2, dated September 7, 1979, for the Crystal River Unit No. 3 power plant.

It is the conclusion of this report that, having completed the actions required by the Bulletin, the seismic analysis, as originally done, applies to the actual configuration of safety-related piping systems. Exceptions to this conclusion were of a type which do not compromise the safe operation of the plant and for which remedial actions have been completed or for which actions will be completed by the end of the next scheduled plant shutdown.

1382 119

7911210/26 Q


79C773

October 30, 1979

If you have any questions regarding this report, please contact this office.

Very truly yours,

FLORIDA POWER CORPORATION



W. P. Stewart  
Manager  
Nuclear Operations

Simpson(IEBul79-14)DN75

Enclosure

cc: Director  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director  
Division of Operating Reactors  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

1382 120