

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

November 8, 1979

TELEPHONE: AREA 701
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII:WDJ
50-269/79-10
50-270/79-10
50-287/79-10

Dear Mr. O'Reilly:


With regard to the above referenced inspection report my letter of August 6, 1979 stated that Duke Power Company considered Items C and D not to represent valid items of noncompliance. In order to resolve any future disagreements that may arise in these areas, we are planning to amend our Quality Assurance Program Topical Report to reflect our present mode of operation as follows:

With regard to Item C, Paragraph 17.2.3 of the Topical Report will be amended to state that design changes, including field changes, shall be subject to design control measures commensurate with those applied to the original design and be approved by the organization that performed the original design unless the applicant designates another responsible organization.

With regard to Item D, Paragraph 17.2.12 and the commitment to ANSI N45.2.4 - 1972 (IEEE Std. 366-1971) in the Topical Report will be amended to state that the requirements concerning tagging and marking are not applicable to installed instrumentation.

It is considered that these corrective actions are sufficient to resolve these outstanding items of noncompliance.

Very truly yours,


William O. Parker, Jr.

NAR:scs

1518 027

790646

7912100165

CCPY