

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
500C Chestnut Street Tower II

FEB 20 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - ADDITIONAL FIRE DAMPERS AND
FIRE DOORS IN CONTROL AND AUXILIARY BUILDINGS - NCR SWP-78-S-2 -
FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
C. R. McFarland on December 18, 1978. An interim report was submitted
on January 17, 1979. Enclosed is our final report.

If you have any questions concerning this matter, please get in touch
with M. R. Wisenburg at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

79022803 31

Boia
5/1
5