

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION V

1990 N. CALIFORNIA BOULEVARD SUITE 202, WALNUT CREEK PLAZA WALNUT CREEK, CALIFORNIA 94596

MOV 13 19/9

Docket No. 50-243

Oregon State University Corvallis, Oregon 97331

Attention: Dr. C. H. Wang

Reactor Administrator

Gentlemen:

This letter refers to the inspection of your activities authorized under NRC License No. R-51 conducted by Messrs. W. P. Mortensen and D. W. Schaefer of this office on October 16 and 17th, 1979. It also refers to the discussion of our inspection findings held by the inspectors with you and members of your staff on October 17, 1979.

The inspection included examination of activities related to physical protection against industrial sabotage and against theft of special nuclear material in accordance with applicable requirements of Title 10, Code of Federal Regulations, Part 73, "Physical Protection of Plants and Materials," your Security Plan, and license conditions pertaining to physical protection as described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and records, interviews with facility personnel and observations by the inspectors.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of the findings of your safeguards and security measures are exempt from public disclosure; therefore, the enclosed inspection report will not be placed in the Public Document Room.

1530 174

-2- NOV 13 1979

Oregon State University

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

LeRoy R. Norderhaug, Chief Safeguards Branch

Enclosure:

Inspection Report - 50-243/79-02