



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

APR 30 1979

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. J. Williamson
President and Chief
Executive Officer
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the enforcement conference conducted by me, and others of this office on April 18, 1979, at the Toledo, Ohio Corporate offices with you, Mr. W. Johnson and others of your staff.

The enclosed copy of our inspection report identifies areas discussed during this conference. As indicated in the enclosed report, this meeting represents the first of a series of meetings that we have requested to be held in order to achieve both immediate and long-term improvements in the regulatory performance of the Davis-Besse 1 facility.

No items of noncompliance with NRC requirements were identified during the course of this conference.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

2133 310

7906260636


Toledo Edison Company

- 2 -

APR 30 1979

We will gladly discuss any questions you have concerning this conference.

Sincerely,


James G. Keppler
Director

Enclosure: IE Inspection
Report No. 50-346/79-08

cc w/encl:

T. D. Murray, Station
Superintendent

Central Files

Reproduction Unit NRC 20b

PDR

Local PDR

NSIC

✓TIC

Harold W. Kohn, Power
Siting Commission

2133 311