

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION Y

SUITE 202, WALNUT CREEK PLAZA 1990 N. CALIFORNIA BOULEVARD WALNUT CREEK, CALIFORNIA 94596

W. . . . 0 1979

Docket Nos. 50-460 50-513

Washington Public Power Supply System P. O. Box 968 Richland, Washington 99352

Attention: Mr. N. O. Strand

Managing Director

Gentlemen:

Subject: Report on WKM Valve Overpressurization,

WNP No. 1/4 (your letter of March 9, 1979)

Thank you for your letter, referenced above, which forwarded a report pursuant to 10 CFR 50.55(e) regarding the subject matter.

Your report will be reviewed and evaluated and should we require additional information concerning this matter, we will contact you.


Your cooperation with us is appreciated.

Sincerely,

R. H. Engelken

Rainedon

Director



## Washington Public Power Supply System

P. O. Box 968 3000 GEO. WASHINGTON WAY RICHLAND, WASHINGTON 99352 PHONE (509) 946-1611

March 9, 1979 G01-79-154

Nuclear Regulatory Commission Region V Suite 202 Walnut Creek Plaza 1900 N. California Boulevard Walnut Creek, California 94596

Attention:

Mr. R. H. Engelken

Director

Dear Mr. Engelken:

Subject:

WPPSS Nuclear Project Nos. 1/4
Docket Numbers 50-460 and 50-513
Reportable Condition 10CFR50.55(e)
WKM Valve Overpressurization

Your staff was informed of a reportable deficiency under the provisions of 10CFR50.55(e) by telecon on February 9, 1979.

Appendix A to this letter contains the WPPSS final report on the subject condition.

If you have any questions, or desire further information, please advise.

Very truly yours,

D1 Reulerger

D. L. Renberger Assistant Director-Technology

Attachment

DLR:TJH:jds

cc: CR Bryant - BPA

BD Redd - UE&C, Phil. JG Davis - NRC Region 1

Desp 7903150340