FORM (080-59 77	1	U.S. NUCLEAR REGU	LATORY COMMISSIO				
		INSP	ECTION FINDINGS AND L	ICENSEE ACKNOWLED	GMENT			
N X B	he'c om	on, Jue. 22 erville, n.	J.08876	U. S. Nuclear Regulatory Commission Uffice of Inspection & Enforcement Region I 631 rark Avenue King of Prussia, PA 10406				
3. DO	CKETN	UMBER(S)	A LICENSE NUMBER	6-05, -06	2-7-79			
The in Comm	nspectio hission's ive reco	i rules and regulations and t rds, interviews with personn	he activities conducted under yo he conditions of your license. T el, and observations by the inspe	our license as they relate to r he inspection consisted of sele ector. The findings as a result of	adiation safety and to compliance with the retive examinations of procedures and repre of this inspection are as follows:			
V			r unsafe conditions were for					
The			nce related to records, signs,					
	A. R	looms or areas were not p	properly posted to indicate t	he presence of a RADIAT	ION AREA. 10 CFR 20.203(b) or 34.42			
		ooms or areas were not p 0 CFR 20.203(c) (1) or 3	properly posted to indicate to 84.42	he presence of a HIGH RA	DIATION AREA.			
	C. R 10	cooms or areas were not p 0 CFR 20.203(d)	properly posted to indicate the	he presence of an AIRBOI	RNE RADIOACTIVITY AREA.			
	D. R	ooms or areas were not p	properly posted to indicate the	he presence of RADIOAC	TIVE MATERIAL. 16 CFR 20.203(e)			
		ontainers were not prope 0 CFR 20.203(f) (1) or (rly labeled to indicate the p f) (2)	resence of RADIOACTIVI	EMATERIAL.			
		F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)						
	G. FormNRC-3 was not properly posted. 10 CFR 20.206(c)							
	H. R	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)						
	I. R	Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)						
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51							
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)							
	L. Records of investories were not maintained. 10 CFR 34.26							
	M. U	tilization logs were not n	naintained. 10 CFR 34.27					
	N. R	ecords of radiation surve	y instrument calibration wer	re not maintained. 10 CFR	34.24			
	0. R	ecords of teletherapy ele	ctrical interlock tests were n	ot maintained as prescribe	d in your license.			
	P. 01							
			Laur	ence 7. The	Fiedman, Ph. D.			
no	ncomp		ed and I understand the i d within the next 30 days		isted above. The items of			

ORIGINAL TO LICENSEE

DISTRIBUTION: Docket Files (w/o encl) NRR Reading File (w/o encl) ETSB Reading File (w/o encl) . ETSB Docket File (w/encl) FEB 0 8 1980 RLBangart (w/encl)

A. Schwencer

February 27, 1980. If a meeting is indicated by PSE&G, please inform us no later than five (5) days before the meeting date, if possible. Otherwise, PSE&G should submit revised Radiological Effluent Technical Specifications within thirty (30) days of receipt of our comments.

Criginal Streed By: Richard L. Bangart

Richard L. Bangart, Acting Chief Effluent Treatment Systems Branch Division of Site Safety and Environmental Analysis

Enclosures: 1. ETSB Comments on List of Changes to RETS

- 2. ETSB Comments on RETS
- ETSB Comments on ODCM and PCP

cc: w/o enclosure

- W. Kreger
- J. Collins
- F. Congel
- E. Markee
- W. Burke

with enclosure G. Knighton H. Ross J. Boegli

	dB	· · · ·		
OFFICE	DSE:SA:	DSE:SA:ETSB	DSE SA: ETSB	
DATE				