## TENNESSEE VALLEY AUTHORITY

400 Chestnut Street Tower II

13 ( = 27 All: 0 September 26, 1979

Mr. James P. G'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - TENSILE ANCHOR CAPACITIES LOWER THAN DESIGN ALLOWABLES - NCR CEB 79-5 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector T. E. Burdette on February 12, 1979, in accordance with 10 CFR 50.55(e). Interim reports were submitted on March 14, 1979, and May 14, 1979. Enclosed is our final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager

Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

1678 039

B013,/1

8001030639

9
790518
5 GEFICIAL COPY.