U.S. NUCLEAK REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Report No. 50-156/78-05

Docket No. 50-156

Licensee: University of Wisconsin Nuclear Engineering Department Madison, WI 53705

Facility Name: Nuclear Reactor Laboratory

Inspection At: Nuclear Reactor Laboratory, Mechanical Engineering Building

Inspection Conducted: December 5-7, 1978

Inspectors: T. J. Madeda J. M. Sodeda J. M. Cogburn Gefrem Approved By: D. A. Hind, Chief Safeguards Branch

License No. R-47

·· 1/15/29 1/15/29 1/15/29

Inspection Summary

Inspection on December 5-7, 1978 (Report No. 50-156/78-05)

Areas Inspected: Routine, unannounced inspection of the approved security plan and its implementation relative to the protection of SNM; security organization; access controls; alarm systems; surveillance procedures; security prog am review; and protection against radiological sabotage. Additionally, the inspectors reviewed the licensee's action on a previous item of noncompliance identified during a physical inspection conducted on June 19-21, 1978. The inspection involved 29 inspector-hours onsite by two NRC inspectors.

ş

Results: Of the nine areas inspected, no items of noncompliance were identified.

Attachment: (Details Part 2.790(d) Information)

7902010394