

Part 2.790(d) Information

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Report No. 50-331/79-08

Docket No. 50-331

License No. DPR-49

Safeguards Group No. IV

Licensee: Iowa Electric Light and Power Company
Post Office Box 351
Cedar Rapids, IA 52406

Facility Name: Duane Arnold Energy Center

Inspection At: Duane Arnold Site, Palo, Iowa

Inspection Conducted: February 26 - March 1, 1979

Inspectors: *Terry J. Mededa*
T. J. Mededa

3/15/79
(Date)

Approved By: *J. A. Hind*
J. A. Hind, Chief
Safeguards Branch

3/14/79
(Date)

Inspection Summary

Inspection on February 26 - March 1, 1979 (Report No. 50-331/79-08)

Areas Inspected: Special unannounced inspection regarding the licensee's corrective action on previously identified items of noncompliance, and outstanding and unresolved items identified during the last three security inspections. In addition, the inspection covered areas relative to 10 CFR 73.55 requirements, specifically, security organization, physical barriers, access controls, communication requirements and testing and maintenance. The inspection involved 32.5 inspection hours onsite by one NRC inspector.

Results: Of the five areas inspected, no apparent items of noncompliance were identified in one area; four items of noncompliance were identified in three areas (Physical Barriers - Paragraph 4, and 4b; Communication Requirements - Paragraph 5; Testing and Maintenance - Paragraph 6). All four items are considered infractions. All previous items of noncompliance, outstanding items, and unresolved items are considered closed.

(Details: Part 2.790(d) Information)