

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

April 12, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:


PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42
50-306 DPR-60

Potential Nonconservatism in SAR

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is being reported in accordance with Technical Specification 6.7.B.1.h in that a potential nonconservatism may exist in the single rod drop analysis as reported in the safety analysis report.

Yours very truly,


L. O. Mayer, PE
Manager of Nuclear Support Services

LOM/JAG/deh

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

7904170178

-over-