TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 3740;

400 Chestnut Street Tower II

August 16, 1979

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - ELECTRICAL HANDHOLE STRUCTURAL INTEGRITY - NCR CDB 79-4 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector T. J. Donat on July 30, 1979, in accordance with 10 CFR 50.55(e). Enclosed is our final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Regulation and Safety

Enclosure

office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

2031 531

7908300682

B019