



CENTRAL FILES  
PDR:HQ  
LPDR  
HC  
NSIC

ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 5, 1979

1-099-1  
2-099-2

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Units 1 & 2  
Docket Nos. 50-313 & 50-368  
License Nos. DPR-51 & NPF-6  
IE Bulletin No. 79-02  
(File: 1510.1, 2-1510.1)

The following is provided in order to keep you informed as to our progress in satisfying the requirements of IE Bulletin 79-02 and in meeting the date which we committed to in our August 15, 1979, letter number 2-089-9.

We have completed our CEB load analysis assuming flexible base plates for ANO-2. A total of ten supports having safety factors of less than two were identified. These have been corrected to within bulletin specifications. A total of 71 supports have been identified with safety factors greater than two but less than the safety factors required by IE Bulletin 79-02. These will be processed as indicated in our July 6, 1979, letter number 2-079-1.

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:sh

cc: Mr. Norman C. Moseley  
Director, Division of Reactor  
Operations Inspection  
Nuclear Regulatory Commission  
4350 East West Highway  
Bethesda, Maryland 20555

Mr. Bill Johnson  
U.S. Nuclear Regulatory Comm.  
Post Office Box 2090  
Russellville, Arkansas 72801

1101 195

7910040 634 P