

1 4.

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION I 631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

Decket No. 30-14899

FEB 1 5 :330

National Inspection and Consultants, Inc. ATTN: Mr. Charles R. Vigne President P. O. Box 10 Coraopolis, Pennsylvania 15108

Gentlemen:

Subject: Inspection 30-14899/80-01

This refers to the inspection conducted by Mr. C. Stearns of this office on January 21, 1980 of activities authorized by NRC License No. 37-18348-01 and to the discussions of our findings held by Mr. Stearns with yourself and Mr. Lake of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Based on the results of this inspection, it appears that certain of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. These items of noncompliance have been categorized into the levels as described in our correspondence to you dated December 31, 1974. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

8006050 707

National Inspection and Consultants, 2 Inc.

.....

1 5 1 5 1380

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

John E. Glenn

Robert O. McClintock, Chief Materials Radiological Protection Section

Enclosure: Appendix A. Notice of Violation