

December 5, 1978

Mr. Uldis Potapovs
United States Nuclear
Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

Reference: Docket No. 99900036/78-03

Dear Mr. Potapovs:

Regarding your letter of 8 November 1978 and the attached Report No. 99900036/78-03, Combustion Engineering, Inc. wishes to advise that the report does not contain information believed to be of a proprietary nature; however, we do wish to advise that the following minor changes need to be made:

Page 3

B. 3. Observations

The sentence should be changed to read, "... since C-E identified a potentially serious problem ...".

Page 5

(2) Third sentence should read, "All core lug welds ...".

Page 6


E. (1) Should be revised from "...both the 1-G and 2-G positions ..." to "...in the 1-G or 2-G position...".

(4) Same as E(1).

We will appreciate these minor changes being made to the referenced report.

Very truly yours,

COMBUSTION ENGINEERING, INC.


W. A. Stone, Jr., Manager
Nuclear Quality Assurance

WAS:sh

7901080066