License No. 22-13585-02G


License No. 22-13585-03



REGION III 799 ROOSEVELT ROAD

GLEN ELLYN, ILLINOIS 60137

FEB 12 379



Mr. J. A. Santiago Directors

Post Office Box O Rosemount, MN 55068

Gentlemen:

CLEAR REGULA

This refers to the inspection conducted by Mr. C. T. Oberg of this office on January 24, 1979, of activities at the Nite-Site, Inc. authorized by NRC Byproduct Material Licenses No. 22-13585-02G and No. 22-13585-03 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

inspection.

cc w/encl: Central Files

NSIC

Enclosure: Appendix A, Notice of Violation

Reproduction Unit NRC 20b