				FI
	\$¢ ∪. s. c	OVERNMENT PRINTING	OFFICE 1977-231-370	
		U.S. NUCLEAR REGULATORY COMMISSION		
	INSPECTIO	N FINDINGS AND LI	CENSFE ACKNOWLED	GMENT
Burnham City Hospital 407 5.4# Street Champaign, Il. 61820			2. REGIONAL OFFICE U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region III 799 Roosevelt Road Glen Ellyn, IL 60137	
3. DC	CKET NUMBER(S)	4. LICENSE NUMBER		S. DATE OF INSPECTION
0	070-02830	SNN	1-1812	2/20/78
The i Comm		ditions of your license. The observations by the inspect	inspection consisted of sele tor. The findings as a result	radiation safety and to compliance with the ective examinations of procedures and repre- of this inspection the as follows:
The	following items of noncompliance rel	lated to records, signs, a	nd labels were found:	
	A. Rooms or areas were not proper	ly posted to indicate the	e presence of a RADIAT	ION AREA. 10 CFR 20.203(b) or 34.43
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42			
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)			
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)			
	G. FormNRC-3 was not properly p	osted. 10 CFR 20.206(:)	
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(z) or 34.33(b)			
	1. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)			
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51			
	K. Records of leak tests were not m	naintained as prescribed	in your license, or 10 CI	FR 34.25(c)
	L. Records of inventories were not maintained. 10 CFR 34.26			
	M. Utilization logs were not maintained. 10 CFR 34.27			
	N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24			
	O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.			
C		interiock tests were no	e maintained as prescribe	ed in your needse.
	P. Other	Rot	hert E. But (NRC Inspec	igin 2/2/19
	the NRC Inspector has explained an encompliance will be corrected with 7903200454			The second secon
	(Date)	-	(Licensee Representati	ine - Title or Position)

ORIGINAL TO LICENSEE