

UNITED STATES ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATIONS

REGION 1 631 PARK AVENUE

KING OF PRUSSIA, PENNSYLVANIA 19406

Central felis

MAR 2 5 1974

Metropolitan Edison Company Attention: Mr. J. G. Miller Vice President

Box 542 Reading, Pennsylvania 19603 License No. CPPR-40 Docket No. 50-289 Inspection No. (74-11

Gentlemen:

This refers to the inspection conducted by Mr. Folsom of this office on March 7-9, 1974 at Middletown, Pennsylvania, of activities authorized by AEC License No. CPPR-40 and to the discussions of our findings held by Mr. Folsom with Mr. Stromberg of your staff at the conclusion of the inspection.

Areas examined during the inspection are described in the Regulatory Operations Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations or safety items were observed.

In accordance with Section 2.790 of the AEC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Robert T. Carlson, Chief

Facility Construction and Engineering

Support Lranch

Enclosure:

· RO Inspection Report No. 50-289/74-11

bcc (w/encls):
RO Chief, FS&EB
RO:HQ (5)
DL (4 w/encls plus 9 cys of Report Only)
DR Central Files
RS (3)
PDR
Local PDR
RO Files
NSIC
DTIE
State of Pennsylvania