



MATERIAL TRANSMITTED HERewith  
 CONTAINS 2.750 INFORMATION STATES  
 NUCLEAR REGULATORY COMMISSION  
 REGION II  
 101 MARIETTA STREET, N.W.  
 ATLANTA, GEORGIA 30303

Report Nos.: 50-250/78-31 and 50-251/78-31

Docket Nos.: 50-250 and 50-251

License Nos.: DPR-31 and DPR-41

Safeguards Group No.: IV

Licensee: Florida Power and Light Company  
 Advanced Systems and Technology  
 P. O. Box 529100  
 Miami, Florida 33152

Facility Name: Turkey Point 3 and 4

Inspection at: Homestead, Florida

Inspection Conducted: December 5-7, 1978

Inspectors: K. H. Besecker  
 J. M. Fuchko

Reviewed by: *SD Gillespie*  
 F. P. Gillespie, Chief  
 Security and Investigation Section  
 Safeguards Branch

12/28/78  
 Date

Inspection Summary

Inspection of December 5-7, 1978 (Report Nos. 50-250/78-31 and 50-251/78-31)

Areas Inspected: Routine unannounced inspection of physical security program. Areas inspected were selected portions of the Security Plan, and applicable portions of 10 CFR 73.55 that were to be implemented by May 25, 1977, including Security Organization, Access Controls, Physical Barriers and Detection Aids. The inspection involved 40 manhours onsite by two NRC inspectors.

Results: Of the four areas inspected no items of noncompliance were identified in two areas; three items of noncompliance were identified in two areas (deficiency - failure to develop procedures - Paragraph 3 (250/251/78-31-01); infraction - failure to search hand-carried packages - Paragraph 4 (250/251/78-31-02); deficiency-inadequate designated vehicle list - Paragraph 4 (250/251/78-31-03)).

S-F2 78 - 168  
 Copy 6 of 168 Copies  
6 Pages

This Document is not to be reproduced without specific approval of IE:II

7903070069