



72

LONG ISLAND LIGHTING COMPANY

175 EAST OLD COUNTRY ROAD · HICKSVILLE, NEW YORK 11801

January 7, 1980

JNRC-242

Mr. Boyce Grier, Director
Office of Inspection & Enforcement, Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Jamesport Nuclear Power Station - Units 1 & 2
Inspection & Enforcement Bulletin No. 79-25
Docket Nos. 50-516
50-517

Dear Mr. Grier:

This letter is submitted in reply to Inspection & Enforcement Bulletin 79-25, "Failure of Westinghouse BFD Relays in Safety-Related Systems". A review of the Jamesport Nuclear Power Station has indicated that no Westinghouse BFD/DBFD relays are being used or planned for use in safety-related systems.

Should you require further information, please do not hesitate to contact us.

Very truly yours,

R. E. Plaskon
Assistant Project Manager
Jamesport Nuclear Power Station

LG/dm

cc: Mr. Victor Stello, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20545

8002150 476