



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TERA

FEB 15 1979

Docket No. 50-10
Docket No. 50-237
Docket No. 50-249

Commonwealth Edison Company
ATTN: Mr. Byron Lee, Jr.
Vice President
P.O. Box 767
Chicago, IL 60690

Gentlemen:

Please replace the second page and Appendix A of the correspondence transmitted February 7, 1979, with the attached corrected pages.

Sincerely,

Gaston Fiorelli
Gaston Fiorelli, Chief
Reactor Operations and
Nuclear Support Branch

cc w/corrected pages:
Mr. B. B. Stephenson,
Station Superintendent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Anthony Roisman, Esq.,
Attorney
Mr. Dean Hansell, Office of
Assistant Attorney General


7903080490

Q

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



Gaston Fiorelli, Chief
Reactor Operations and
Nuclear Support Branch

Enclosures:

1. Appendix A, Notice of
Deviation
2. IE Inspection Rpts
No. 50-10/78-35,
No. 50-273/78-34, and
No. 50-249/78-35

cc w/encls:

Mr. B. B. Stephenson, Station
Superintendent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Anthony Roisman, Esq.,
Attorney
Mr. Dean Hansell, Office
of Assistant Attorney
General

Appendix A

NOTICE OF DEVIATION

Commonwealth Edison
Company

Docket No. 50-10
Docket No. 50-237
Docket No. 50-249

Based on the inspection conducted on December 1-29, 1978, it appears that certain of your activities were not in accordance with commitments, codes, standards, guides or acceptable practices, as noted below.

Regulatory Guide 1.38 states in part that the requirements for packaging, shipping, receiving, storage, and handling of items for watercooled nuclear plants that are included in ANSI N45.2.2 - 1972 are acceptable to the NRC staff and provide an adequate basis for complying with Appendix B to 10 CFR 50.

ANSI N45.2.2, Section 6.1.2.(2) requires that equipment stored in Class B areas be placed on pallets or shoring to permit air circulation.

Contrary to the above on December 21, 1978, the licensee placed Class B stored switchgear on the turbine building floor with no pallets or shoring beneath the switchgear.