



Nebraska Public Power District

May 4, 1979

Mr. Karl V. Seyfrit, Director
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
Region IV
611 Ryan Plaza
Suite 1000
Arlington, Texas 76011

Subject: IE Bulletin No. 79-09
Failures of GE Type AK-2 Circuit Breakers
in Safety Related Systems

Dear Mr. Seyfrit:

This letter is in response to the subject bulletin which requested a determination as to the use, or planned use, of the subject circuit breakers in safety-related systems at Cooper Nuclear Station.

Following a review of this subject by appropriate District personnel, we have concluded that GE Type AK-2 circuit breakers are not in use or planned for use at Cooper Nuclear Station.

Should you desire further discussion of this subject, please do not hesitate to contact me.

Sincerely,

A handwritten signature in dark ink, appearing to read 'Jay M. Pilant'.

Jay M. Pilant
Director of Licensing
and Quality Assurance

JDW/cmk

2230 247

cc: Mr. John G. Davis, Director
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
Division of Reactor Operations Inspection
Washington, DC 20555

7906110043

Q