BOSTON EDISON COMPANY

GENERAL OFFICES 800 BOYLSTON STREET BOSTON, MASSACHUSETTS 02199

G. CARL ANODBNINI
SUPERINTENDENT
NUCLEAR OPERATIONS DEPARTMENT

January 11, 1980

BECo. Ltr. #80-10

Mr. Boyce H. Grier, Director Office C. Inspection and Enforcement Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

> License No. DPR-35 Docket No. 50-293

Response to IE Bulletin No. 79-28 NAMCO Model EA180 Limit Switches

Dear Sir:

In your letter dated December 7, 1979, you transmitted IE Bulletin 79-28 - Possible Malfunction of "NAMCO Model EA150 Limit Switches at Elevated Temperatures". Boston Edison was requested to perform a review to determine if certain NAMCO EA180 limit switches were installed or were planned to be installed on safety related equipment.

We have completed the necessary review and have determined that there are no NAMCO Model EA180 limit switches coded 02-79 through 08-79, either presently installed or planned for installation in the future on safety related equipment at Pilgrim Station.

We trust that this information is responsive to your request; however, should you have any further questions or concerns in this area, please do not hesitate to contact us.

Very truly yours,

A fall flulgreen

cc: United States Nuclear Regulatory Commission Effice of Inspection and Enforcement vision of Reactor Operation Inspection ashington, D. C. 20555