



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

April 26, 1979

H. Denton
E. Case
D. Eisenhut
D. Ross
R. Tedesco
S. Hanauer
Z. Rosztoczy

Attached is a document concerning B&W transient and accident analysis methods I received this morning. This is the subject of today's meeting with B&W.

Roger J. Mattson, Director
Division of Systems Safety

7905080364

5/3 Karen - please see that
this got (or gets)
to PDR.
R

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES