



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

1782

JAN 11 1980

Docket No. 50-440
Docket No. 50-441

The Cleveland Electric Illuminating
Company

ATTN: Dalwyn R. Davidson
Vice President - System
Engineering and Construction

Post Office Box 5000
Cleveland, OH 44101

Gentlemen:

Thank you for your final report dated December 19, 1979, pursuant to 10 CFR 50.55(e) regarding the deficiency concerning slits in the jackets of Rockbestos Class IE small power and control cable. We will complete our review of this matter during a future inspection.

Your cooperation with us is appreciated.

Sincerely,

G. Fiorelli, Chief
Reactor Construction and
Engineering Support Branch

cc: Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Harold W. Kohn, Power Siting
Commission
Mr. Daniel D. Wilt, Attorney
Helen W. Evans, State
of Ohio

315
1795-314

8001240 362

5