

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

0 1 M D C C N I 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T

0 1 7 8

REPORT SOURCE

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 2134 while performing a routine surveillance test, control element

03 assembly (CEA) 35 dropped into the core (T.S. 3.1.3.1). CEA-35 was

04 withdrawn and leveled with its group at 2152. All other CEA's remained

05 operable during the event. The reactor was in Mode 2 at 1% power during

06 the event. LER's 80-6 (U-1) and 80-9 (U-2) describe similar events.

07 _____

08 _____

7 8 9 10 11 12 13 14 15 16 17 18 19 20

0 9 R B X Z Z Z Z Z X Z

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

(17) LER/RO REPORT NUMBER [8 | 0]
 21 22
 []
 23
 REPORT NO. [0 | 1 | 2]
 24 25 26
 [/]
 27
 CODE [0 | 3]
 28 29
 TYPE [L]
 30
 []
 31
 NO. [0]
 32
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
 [Z | 18 | X] (19) [Z] (20) [Z] (21) [0 | 0 | 0 | 0] (22) [N] (23) [N] (24) [Z] (25) [C | 4 | 9 | 0] (26)
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE L DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 It is unknown why CEA-35 dropped; the rod was raised by the operators

11 18 minutes after it dropped. It is planned during the next STP 0-29

1 2 to have a technician monitor the operating parameter of all CEA's in

13 | order to detect any intermittent problems and take corrective action.

1	4	
---	---	--

FACILITY STATUS (28) 1 5 E 30 OTHER STATUS NA 32 DISCOVERY DESCRIPTION B Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 8 9 10 11

2 3 4 5 6 7 8 9 10 11

NA

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES		NUMBER		TYPE	DESCRIPTION
1	7	0	0	0	0
		37	7	38	N A

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
1 8 0 0 0 0 40	NA

		8		9		11		12		
		LOSS OF OR DAMAGE TO FACILITY						(43)		
		TYPE DESCRIPTION								
1	9	Z	(42)					NA	8003050 476	

7		8		9		10		80	
		PUBLICITY							
ISSUED		DESCRIPTION		(45)				NRC USE ONLY	
2	0	N	(44)	NA					

NAME OF PREPARER S. M. Davis/E. R. Bauer

PHONE: (301) 269-4742/4728

5PO 917-926