

PDR



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V
1990 N. CALIFORNIA BOULEVARD
SUITE 202, WALNUT CREEK PLAZA
WALNUT CREEK, CALIFORNIA 94596

OCT 1 1980

License No. 50-17314-01

Arctic Pipe Inspection, Inc.
P. O. Box 1296
Kenai, Alaska 99611

Attention: Mr. Royce Roberts
President

Gentlemen:

Subject: NRC Inspection

This refers to the routine inspection conducted by Mr. Paul R. Zurakowski of this office on September 17, 1980 of activities authorized by NRC License No. 50-17314-01 and to the discussion of our findings held by Mr. Zurakowski with Mr. Roberts at the conclusion of the inspection.

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel and observations by the inspector.

During this inspection it was found that one of your activities appeared to be in noncompliance with NRC requirements. The item and references to the pertinent requirements are listed in the enclosure to this letter. Items of this type have been categorized into levels as described in our correspondence to all NRC licensees dated December 31, 1974.


This notice is sent to you pursuant to the provisions of Section 2.201, of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or

OCT 1 1980

explanation in reply including (1) corrective steps which have been taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,



H. E. Book, Chief
Fuel Facility and
Materials Safety Branch

Enclosure:
Notice of Violation