## SCHERING CORPORATION

60 ORANGE STREET



BLOOMFIELD, N. J. 07003

TELEPHONE: (201) 743-6000
TELEX: 138183
CABLES: SCHERING BLOOMFIELD, N. L.

September 24, 1980

Mr. John D. Kinneman Chief, Materials Radiological Protection Section United States Nuclear Regulatory Commission Ragion 1, 631 Park Avenue King of Prussia, Pa. 19406

Dear Mr. Kinneman:

Docket - #30-5230, Inspection 80-01, License #29-00244-02

The 100 mCi Cessium 137 sealed source referred to in your letter of September 11, 1980 was leak tested for loose contamination on August 19, 1980. No contamination was found above the reportable limit of .005  $\mu\text{Ci}$ . A page containing documentation of this leak test was added to the sealed source leak test log book on August 19, 1980 eliminating this item of non-compliance. The addition of this page to the log book will serve as an additional check to insure that this device is leak tested every 6 months when all the sealed sources in our possession are leak tested. If you have any further questions concerning this matter, please contact me at the above address.

Please be assured of our continuing cooperation.

Sincerely yours,

Nelson H. Schimmel, M.D.

Vice President Regulatory Affairs

/tb