

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | R | A | N | 0 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 0 | 5  
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49

CON'T  
01 | REPORT SOURCE | L | 0 | 1 | 5 | 0 | 0 | 0 | 3 | 1 | 6 | 8 | 7 | 0 | 1 | 1 | 2 | 3 | 1 | 8 | 0 | 0 | 1 | 2 | 1 | 1 | 3 | 8 | 1 | 0 | 9  
7 8 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 | During steady state Mode 1 operation, the Reactor Coolant Leakage calcu-  
03 | lation indicated approximately 3.6 GPM unidentified leakage exceeding that  
04 | allowed by T.S.3.4.6.2.b. A containment building entry was made and it  
05 | was verified that no pressure boundary leakage existed. The majority of  
06 | the calculated leakage was identified as that defined by T.S.1.14.a. No  
07 | similar occurrences. Reportable per T.S.6.9.1.9.b.  
08 | \_\_\_\_\_

09 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE  
10 | L | A | 11 | E | 12 | B | 13 | V | A | L | V | E | X | 14 | F | 15 | X | 16  
17 | LER/RG REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.  
18 | X | 19 | B | 20 | L | Z | 21 | 0 | 0 | 1 | 5 | 22 | 0 | 1 | 3 | 23 | L | 24 | 0 | 25 | 0 | 26 | 0 | 27 | 0 | 28 | 3 | 29 | 0 | 30 | 0 | 31 | 0 | 32 | 0 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 | Packing on Pressurizer Spray valves, 2CV-4651 and 2CV-4652, were found to  
11 | be leaking excessively. Leakage from packing was routed through leak-off  
12 | lines to the Containment Building sump. Minor leakage was identified at  
13 | Reactor Coolant Pump "C" seal. Maintenance will be performed on leak  
14 | sources during February outage.

15 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION  
16 | B | 28 | 1 | 1 | 0 | 1 | 0 | 29 | L | NA | 30 | C | 31 | NA | 32

16 | ACTIVITY CONTENT | AMOUNT OF ACTIVITY | LOCATION OF RELEASE  
17 | Z | 33 | Z | 34 | NA | 35 | NA | 36

17 | PERSONNEL EXPOSURES | TYPE | DESCRIPTION  
18 | 0 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

18 | PERSONNEL INJURIES | TYPE | DESCRIPTION  
19 | 0 | 0 | 0 | 0 | 40 | NA | 41

19 | LOSS OF OR DAMAGE TO FACILITY | TYPE | DESCRIPTION  
20 | Z | 42 | NA | 43

20 | PUBLICITY | TYPE | DESCRIPTION  
21 | N | 44 | NA | 45

NAME OF PREPARER: Chris N. Shively PHONE: 501/968-2519

8002200

Handwritten notes: 453, 45-8