

Detroit
Edison

7900 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

February 14, 1980
EF2- 48062

Mr. James C. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) on Non-Seismic Equipment Installed
over Seismic.


Dear Mr. Keppler:

On January 18, 1980, Detroit Edison's Mr. R.W. Barr, Project Quality Assurance
Director, telephoned Mr. J. Conklin of NRC Region III to report on non-seismic
equipment installed over seismic equipment at the Fermi 2 Site.

To date, all affected equipment has been identified in the Reactor and Auxiliary
Buildings. Edison Engineering continues the review of this problem and a final
report will be submitted to you by June 14, 1980.

If you have any questions on this matter, please contact Mr. H.A. Walker, Site
Project Quality Assurance Engineer.

Sincerely,



W.J. Fahrner
Project Manager
Enrico Fermi II

cc: Mr. John G. Davis, Acting Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

B019
2/10

8003040518

Mr. James G. Keppler
February 14, 1980
Page Two

CF2-48062

bcc: T.A. Alessi/U.G. Orlando
C.R. Bacon
J.G. Bolt
W.F. Colbert
T.H. Dickson
W.M. Everett
F.E. Gregor
Edward Hines
P.A. Marquardt/Docket File (2)
E.H. Newton
L.E. Schuerman
M.G. Sigetich
W.M. Street
H. Tauber
H.A. Walker
W.W. White
Document Control
50.55(e) File

G.W. Richards