



EDISON PLAZA
300 MADISON AVENUE
TOLEDO, OHIO 43652

February 28, 1980

L80-142

FILE: RR 2 (NP-33-80-15)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 80-011
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: January 31, 1980

Enclosed are three copies of Licensee Event Report 80-011 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Encl: 30 copies LER 80-011

Mr. Norman Haller, Director
Office of Management Program Analysis
Encl: 3 copies LER 80-011

8003040 597