Appendix A

NOTICE OF DEVIATION

Based on the results of the NRC inspection conducted on January 8-11, 1980, it appears that certain of your activities related to Black Fox Station, Unit 1 deviate from commitments made in your Preliminary Safety Analysis Report (PSAR) as indicated below:

Section 17.D.1.5 of the PSAR states that all Field Project Management activities that affect the quality of safety-related items will be performed in accordance with documented procedures.

Procedure FPPM 4.8, "Storage and Preservation of Material and Equipment," Revision 1 requires that maintenance records shall be kept in plastic envelopes attached to items requiring preservation and maintenance.

Contrary to the above:

On January 8, 1980, the IE inspector found that maintenance records were not attached to three residual heat removal heat exchangers stored in the outdoor storage area.

This is a deviation.