NRC FORM 591M PART 1 (07-2012) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEE/LOCATIO	N INSPECTED:		2. NRC/REGIONAL OFFICE						
Sigma Aldrich MFG LLC 3050 Spruce Street St. Louis, MO 63103 REPORT NUMBER(S) 2019001			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
3. DOCKET NUMBER(S)		4. LICENSE NUMBE	ER(S)	5. DATE(S) OF INSPECTION	1				
030-39156		24-35528-011	E	October 18, 2019					
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: 1. Based on the inspection findings, no violations were identified.									
2. Previous									
3. The violat									
	Non-cited violation(s) were discussed involving the following requirement(s):								
 During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions) 									
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of									
corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.									
TITLE	PRINTED NAME		SIGNATURE		DATE				
LICENSEE'S REPRESENTATIVE				71					
NRC INSPECTOR	Deborah A. Piskura, Senior Heal Robert Ruiz, Acting Chief, MIB	th Physicist	Nelional HI	Slave	10/23/19				
NRC FORM 591M PART		(11imes.		10[24/18				

IRC FORM 591M PART 3 U.S. NUCLEAR REGULATORY COMMISSION Docket File Information									
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEE/LOCATION INSPECT	ED:		2. NRC/REGIONAL OFFICE						
Sigma Aldrich MFG LLC 3050 Spruce Street St. Louis, MO 63103	2		Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
REPORT NUMBER(S) 2019(001		, i i i i i i i i i i i i i i i i i i i						
3. DOCKET NUMBER(S)		4. LICENSE NUMBER	3)	5. DATE(S) OF INSPECTION					
030-39156		24-35528-01E		October 18, 2019					
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCUS	AREAS						
87128		03.01 - 03.07							
	SUPPLE	EMENTAL INSPECT	ON INFORMATION						
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTAC	т	4. TELEPHONE NUMBER					
03253	5	Robert E. Lee M	cVay -X7889	(314) 286-6600					
✓ Main Office Inspection Next Inspection Date: October 18, 2020 Field Office Inspection									
		PROGRAM SC	OPE						
This was an initial, announced inspection of a large biomedical R&D company authorized to possess and distribute various models of exempt analytical laboratory instruments containing carbon-14. The possession license (License No. 24-26445-01) was previously inspected on February 8-22, 2019; no violations of NRC requirements were identified. The exempt distribution license was issued on April 19, 2019. All licensed material distributed under this license was to be obtained from an authorized source manufacturer and intended to be transferred to customers within the US. At the time of this inspection, the licensee was utilizing the services of the device manufacturer (authorized under its Agreement State distribution license) to directly distribute exempt sources to the licensee's customers on its behalf. As of the date of this inspection, the licensee reported that it distributed zero sources (no principal activities have been conduct to date). In accordance with MC 2800, the next inspection date is scheduled for one year. This inspection consisted of interviews with licensee of the annual transfer reporting requirements in 10 CFR 32.20. No violations of NRC requirements were identified during this inspection.									