

| Text | Channel | Rcvr_Type | GPS_Date | GPS_Time | Feat_Name | Datafile | Data_Dicti | GNSS_Heigh | Northing | Easting | Point_ID | BUFF_DIST | CPM |
|--------|---------|------------|------------|------------|-----------|----------------------|------------|------------|-----------|----------|----------|---------------|-------|
| 011722 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:21pm | Sensor | 1797-S0058-G-636-DTE | | 6861.1 | 1597112.0 | 513885.8 | 99779 | 1.64041666667 | 11722 |
| 012121 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:22pm | Sensor | 1797-S0058-G-636-DTE | | 6861.1 | 1597112.0 | 513885.8 | 99782 | 1.64041666667 | 12121 |
| 011423 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:23pm | Sensor | 1797-S0058-G-636-DTE | | 6861.2 | 1597112.0 | 513885.8 | 99784 | 1.64041666667 | 11423 |
| 011450 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:24pm | Sensor | 1797-S0058-G-636-DTE | | 6861.2 | 1597112.0 | 513885.7 | 99786 | 1.64041666667 | 11450 |
| 011518 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:25pm | Sensor | 1797-S0058-G-636-DTE | | 6861.2 | 1597112.0 | 513885.8 | 99788 | 1.64041666667 | 11518 |
| 011331 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:26pm | Sensor | 1797-S0058-G-636-DTE | | 6861.2 | 1597112.0 | 513885.9 | 99790 | 1.64041666667 | 11331 |
| 011234 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:27pm | Sensor | 1797-S0058-G-636-DTE | | 6861.2 | 1597112.0 | 513885.9 | 99792 | 1.64041666667 | 11234 |
| 011989 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:28pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.8 | 99794 | 1.64041666667 | 11989 |
| 012233 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:29pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.8 | 99796 | 1.64041666667 | 12233 |
| 011824 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:30pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.8 | 99798 | 1.64041666667 | 11824 |
| 011781 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:31pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.8 | 99800 | 1.64041666667 | 11781 |
| 012034 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:32pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.8 | 99802 | 1.64041666667 | 12034 |
| 011809 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:33pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.8 | 99804 | 1.64041666667 | 11809 |
| 011427 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:34pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.9 | 99806 | 1.64041666667 | 11427 |
| 011693 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:35pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.9 | 99808 | 1.64041666667 | 11693 |
| 011902 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:36pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.9 | 99810 | 1.64041666667 | 11902 |
| 011990 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:37pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.8 | 99812 | 1.64041666667 | 11990 |
| 012077 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:38pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.8 | 99814 | 1.64041666667 | 12077 |
| 011825 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:39pm | Sensor | 1797-S0058-G-636-DTE | | 6861.4 | 1597112.0 | 513885.8 | 99816 | 1.64041666667 | 11825 |
| 012127 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:40pm | Sensor | 1797-S0058-G-636-DTE | | 6861.4 | 1597112.0 | 513885.8 | 99818 | 1.64041666667 | 12127 |
| 011381 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:41pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.8 | 99820 | 1.64041666667 | 11381 |
| 011734 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:42pm | Sensor | 1797-S0058-G-636-DTE | | 6861.4 | 1597112.0 | 513885.8 | 99822 | 1.64041666667 | 11734 |
| 011475 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:43pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.8 | 99824 | 1.64041666667 | 11475 |
| 011690 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:44pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.8 | 99826 | 1.64041666667 | 11690 |
| 011968 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:45pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.8 | 99828 | 1.64041666667 | 11968 |
| 011794 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:46pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.8 | 99830 | 1.64041666667 | 11794 |
| 011509 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:47pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.8 | 99832 | 1.64041666667 | 11509 |
| 011821 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:48pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.8 | 99834 | 1.64041666667 | 11821 |
| 012102 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:49pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.7 | 99836 | 1.64041666667 | 12102 |
| 011690 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:50pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.7 | 99838 | 1.64041666667 | 11690 |
| 011630 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:51pm | Sensor | 1797-S0058-G-636-DTE | | 6861.2 | 1597111.9 | 513885.7 | 99840 | 1.64041666667 | 11630 |
| 011349 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:52pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.8 | 99842 | 1.64041666667 | 11349 |
| 011484 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:53pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.7 | 99844 | 1.64041666667 | 11484 |
| 011477 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:54pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.7 | 99846 | 1.64041666667 | 11477 |
| 011038 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:55pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597111.9 | 513885.7 | 99848 | 1.64041666667 | 11038 |
| 011961 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:56pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597112.0 | 513885.6 | 99850 | 1.64041666667 | 11961 |
| 011813 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:57pm | Sensor | 1797-S0058-G-636-DTE | | 6861.3 | 1597113.0 | 513885.2 | 99852 | 1.64041666667 | 11813 |
| 011497 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:58pm | Sensor | 1797-S0058-G-636-DTE | | 6861.2 | 1597114.5 | 513884.8 | 99854 | 1.64041666667 | 11497 |
| 012190 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:59pm | Sensor | 1797-S0058-G-636-DTE | | 6861.0 | 1597116.2 | 513885.4 | 99856 | 1.64041666667 | 12190 |
| 012594 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:00pm | Sensor | 1797-S0058-G-636-DTE | | 6861.0 | 1597116.8 | 513886.0 | 99858 | 1.64041666667 | 12594 |
| 012784 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:01pm | Sensor | 1797-S0058-G-636-DTE | | 6861.0 | 1597116.8 | 513886.2 | 99860 | 1.64041666667 | 12784 |
| 012418 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:02pm | Sensor | 1797-S0058-G-636-DTE | | 6861.0 | 1597116.8 | 513886.0 | 99862 | 1.64041666667 | 12418 |
| 011898 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:03pm | Sensor | 1797-S0058-G-636-DTE | | 6861.0 | 1597116.9 | 513885.7 | 99864 | 1.64041666667 | 11898 |
| 011740 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:04pm | Sensor | 1797-S0058-G-636-DTE | | 6861.0 | 1597117.0 | 513885.6 | 99866 | 1.64041666667 | 11740 |
| 011193 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:05pm | Sensor | 1797-S0058-G-636-DTE | | 6861.0 | 1597117.0 | 513885.5 | 99868 | 1.64041666667 | 11193 |
| 011696 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:06pm | Sensor | 1797-S0058-G-636-DTE | | 6861.1 | 1597116.9 | 513885.5 | 99870 | 1.64041666667 | 11696 |
| 011634 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:07pm | Sensor | 1797-S0058-G-636-DTE | | 6861.1 | 1597116.8 | 513885.7 | 99872 | 1.64041666667 | 11634 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011006 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597116.7 | 513885.7 | 99874 | 1.64041666667 | 11006 |
| 011291 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597116.7 | 513885.7 | 99876 | 1.64041666667 | 11291 |
| 011504 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597116.6 | 513885.7 | 99878 | 1.64041666667 | 11504 |
| 010941 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:11pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597116.6 | 513885.7 | 99880 | 1.64041666667 | 10941 |
| 011561 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:12pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597116.6 | 513885.8 | 99882 | 1.64041666667 | 11561 |
| 011168 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:13pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597116.6 | 513885.8 | 99884 | 1.64041666667 | 11168 |
| 012469 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:14pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597116.7 | 513885.8 | 99886 | 1.64041666667 | 12469 |
| 012346 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:15pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597116.8 | 513885.7 | 99888 | 1.64041666667 | 12346 |
| 012255 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:16pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597116.8 | 513885.7 | 99890 | 1.64041666667 | 12255 |
| 012233 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597116.8 | 513885.7 | 99892 | 1.64041666667 | 12233 |
| 012018 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:18pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597116.8 | 513885.7 | 99894 | 1.64041666667 | 12018 |
| 012250 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:19pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597117.0 | 513885.7 | 99896 | 1.64041666667 | 12250 |
| 012313 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:20pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597117.9 | 513885.2 | 99898 | 1.64041666667 | 12313 |
| 012498 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:21pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597120.4 | 513883.9 | 99900 | 1.64041666667 | 12498 |
| 012790 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597122.4 | 513882.8 | 99902 | 1.64041666667 | 12790 |
| 012647 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597125.4 | 513881.9 | 99904 | 1.64041666667 | 12647 |
| 012536 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:24pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597127.7 | 513880.7 | 99906 | 1.64041666667 | 12536 |
| 011859 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:25pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597129.9 | 513879.4 | 99908 | 1.64041666667 | 11859 |
| 012018 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:26pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597131.8 | 513878.5 | 99910 | 1.64041666667 | 12018 |
| 011695 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:27pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597133.5 | 513877.2 | 99912 | 1.64041666667 | 11695 |
| 011806 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:28pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597135.3 | 513876.5 | 99914 | 1.64041666667 | 11806 |
| 012828 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:29pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597136.1 | 513875.5 | 99916 | 1.64041666667 | 12828 |
| 012631 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597136.2 | 513875.5 | 99918 | 1.64041666667 | 12631 |
| 012542 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597136.2 | 513875.6 | 99920 | 1.64041666667 | 12542 |
| 012260 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597136.2 | 513875.6 | 99922 | 1.64041666667 | 12260 |
| 012138 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597136.2 | 513875.6 | 99924 | 1.64041666667 | 12138 |
| 012438 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:34pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597136.2 | 513875.6 | 99926 | 1.64041666667 | 12438 |
| 011834 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:35pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597136.2 | 513875.7 | 99928 | 1.64041666667 | 11834 |
| 012154 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:36pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597136.3 | 513875.9 | 99930 | 1.64041666667 | 12154 |
| 012086 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:37pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597137.6 | 513876.4 | 99932 | 1.64041666667 | 12086 |
| 011336 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:38pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597140.1 | 513876.7 | 99934 | 1.64041666667 | 11336 |
| 011124 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:39pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597142.0 | 513876.9 | 99936 | 1.64041666667 | 11124 |
| 010757 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:40pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597142.4 | 513877.2 | 99938 | 1.64041666667 | 10757 |
| 010956 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:41pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597142.5 | 513877.2 | 99940 | 1.64041666667 | 10956 |
| 010362 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:42pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597142.5 | 513877.1 | 99942 | 1.64041666667 | 10362 |
| 011499 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:43pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597142.6 | 513877.4 | 99944 | 1.64041666667 | 11499 |
| 011815 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:44pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597143.0 | 513878.1 | 99946 | 1.64041666667 | 11815 |
| 011116 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:45pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.0 | 513879.9 | 99948 | 1.64041666667 | 11116 |
| 011915 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:46pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.1 | 513881.2 | 99950 | 1.64041666667 | 11915 |
| 011277 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:47pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.4 | 513881.8 | 99952 | 1.64041666667 | 11277 |
| 011638 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:48pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.5 | 513882.0 | 99954 | 1.64041666667 | 11638 |
| 011556 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:49pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.5 | 513882.1 | 99956 | 1.64041666667 | 11556 |
| 011698 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:50pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.5 | 513882.2 | 99958 | 1.64041666667 | 11698 |
| 011140 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:51pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.4 | 513882.3 | 99960 | 1.64041666667 | 11140 |
| 010826 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:52pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.2 | 513882.4 | 99962 | 1.64041666667 | 10826 |
| 011002 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:53pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.2 | 513882.4 | 99964 | 1.64041666667 | 11002 |
| 011408 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:54pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597144.3 | 513882.5 | 99966 | 1.64041666667 | 11408 |
| 011922 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:55pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597145.3 | 513882.2 | 99968 | 1.64041666667 | 11922 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 011273 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:56pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597147.0 | 513880.8 | 99970 | 1.64041666667 | 11273 |
| 011321 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:57pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597149.1 | 513877.9 | 99972 | 1.64041666667 | 11321 |
| 010920 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:58pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597150.9 | 513875.3 | 99974 | 1.64041666667 | 10920 |
| 010673 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:59pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597151.7 | 513873.1 | 99976 | 1.64041666667 | 10673 |
| 011808 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:00pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597151.7 | 513872.6 | 99978 | 1.64041666667 | 11808 |
| 011427 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:01pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597151.6 | 513872.5 | 99980 | 1.64041666667 | 11427 |
| 011497 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:02pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597150.6 | 513871.5 | 99982 | 1.64041666667 | 11497 |
| 011485 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:03pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597148.0 | 513870.1 | 99984 | 1.64041666667 | 11485 |
| 012130 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:04pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597145.7 | 513869.8 | 99986 | 1.64041666667 | 12130 |
| 012958 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:05pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597144.1 | 513869.5 | 99988 | 1.64041666667 | 12958 |
| 013064 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:06pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597143.7 | 513868.8 | 99990 | 1.64041666667 | 13064 |
| 013341 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:07pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597143.6 | 513868.8 | 99992 | 1.64041666667 | 13341 |
| 013099 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:08pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597142.9 | 513868.9 | 99994 | 1.64041666667 | 13099 |
| 012506 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:09pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597140.7 | 513869.2 | 99996 | 1.64041666667 | 12506 |
| 012787 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:10pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597139.3 | 513868.8 | 99998 | 1.64041666667 | 12787 |
| 012915 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:11pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597139.0 | 513868.8 | 100000 | 1.64041666667 | 12915 |
| 012762 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:12pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597139.0 | 513868.8 | 100002 | 1.64041666667 | 12762 |
| 013546 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:13pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597139.0 | 513868.8 | 100004 | 1.64041666667 | 13546 |
| 012847 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:14pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597139.0 | 513868.9 | 100006 | 1.64041666667 | 12847 |
| 012379 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:15pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597139.0 | 513869.0 | 100008 | 1.64041666667 | 12379 |
| 011238 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:16pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597139.0 | 513869.0 | 100010 | 1.64041666667 | 11238 |
| 010949 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:17pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597139.0 | 513869.3 | 100012 | 1.64041666667 | 10949 |
| 011363 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:18pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.7 | 513869.9 | 100014 | 1.64041666667 | 11363 |
| 011694 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:19pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.5 | 513870.4 | 100016 | 1.64041666667 | 11694 |
| 011093 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:20pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.5 | 513870.4 | 100018 | 1.64041666667 | 11093 |
| 010590 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:21pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.6 | 513870.1 | 100020 | 1.64041666667 | 10590 |
| 012481 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:22pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.9 | 513870.5 | 100022 | 1.64041666667 | 12481 |
| 012038 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:23pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597138.7 | 513871.2 | 100024 | 1.64041666667 | 12038 |
| 011391 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:24pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597138.7 | 513870.7 | 100026 | 1.64041666667 | 11391 |
| 012242 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:25pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.8 | 513870.3 | 100028 | 1.64041666667 | 12242 |
| 011919 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:26pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.8 | 513870.2 | 100030 | 1.64041666667 | 11919 |
| 011557 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:27pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.7 | 513870.2 | 100032 | 1.64041666667 | 11557 |
| 011743 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:28pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597138.8 | 513871.0 | 100034 | 1.64041666667 | 11743 |
| 010655 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:29pm | Sensor | 1797-S0058-G-636-DTE | 6859.4 | 1597139.0 | 513872.6 | 100036 | 1.64041666667 | 10655 |
| 010936 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:30pm | Sensor | 1797-S0058-G-636-DTE | 6859.2 | 1597139.0 | 513872.7 | 100038 | 1.64041666667 | 10936 |
| 010614 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:31pm | Sensor | 1797-S0058-G-636-DTE | 6859.3 | 1597138.9 | 513872.7 | 100040 | 1.64041666667 | 10614 |
| 010342 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:32pm | Sensor | 1797-S0058-G-636-DTE | 6859.7 | 1597138.8 | 513872.5 | 100042 | 1.64041666667 | 10342 |
| 011030 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:33pm | Sensor | 1797-S0058-G-636-DTE | 6860.0 | 1597138.8 | 513872.2 | 100044 | 1.64041666667 | 11030 |
| 011522 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:34pm | Sensor | 1797-S0058-G-636-DTE | 6859.7 | 1597138.7 | 513872.2 | 100046 | 1.64041666667 | 11522 |
| 011423 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:35pm | Sensor | 1797-S0058-G-636-DTE | 6860.0 | 1597138.1 | 513872.2 | 100048 | 1.64041666667 | 11423 |
| 010715 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:36pm | Sensor | 1797-S0058-G-636-DTE | 6858.5 | 1597138.3 | 513872.8 | 100050 | 1.64041666667 | 10715 |
| 010835 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:37pm | Sensor | 1797-S0058-G-636-DTE | 6855.3 | 1597138.7 | 513874.1 | 100052 | 1.64041666667 | 10835 |
| 011202 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:38pm | Sensor | 1797-S0058-G-636-DTE | 6855.6 | 1597138.9 | 513874.2 | 100054 | 1.64041666667 | 11202 |
| 010726 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:39pm | Sensor | 1797-S0058-G-636-DTE | 6858.1 | 1597138.8 | 513872.4 | 100056 | 1.64041666667 | 10726 |
| 012071 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:40pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597138.5 | 513870.7 | 100058 | 1.64041666667 | 12071 |
| 013780 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:41pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597138.7 | 513870.4 | 100060 | 1.64041666667 | 13780 |
| 013391 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:42pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597138.9 | 513870.7 | 100062 | 1.64041666667 | 13391 |
| 011830 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:43pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597139.2 | 513872.8 | 100064 | 1.64041666667 | 11830 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 011889 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:44pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597139.3 | 513874.9 | 100066 | 1.64041666667 | 11889 |
| 011330 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:45pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597137.3 | 513877.6 | 100068 | 1.64041666667 | 11330 |
| 011107 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:46pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597135.2 | 513879.5 | 100070 | 1.64041666667 | 11107 |
| 010901 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:47pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597133.3 | 513881.1 | 100072 | 1.64041666667 | 10901 |
| 012169 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:48pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597131.5 | 513882.0 | 100074 | 1.64041666667 | 12169 |
| 011615 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:49pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597129.6 | 513883.0 | 100076 | 1.64041666667 | 11615 |
| 011948 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:50pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597128.4 | 513885.0 | 100078 | 1.64041666667 | 11948 |
| 012908 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:51pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597127.4 | 513887.2 | 100080 | 1.64041666667 | 12908 |
| 012496 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:52pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.7 | 513888.6 | 100082 | 1.64041666667 | 12496 |
| 013824 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:53pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.3 | 513890.1 | 100084 | 1.64041666667 | 13824 |
| 013476 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:54pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.2 | 513891.3 | 100086 | 1.64041666667 | 13476 |
| 013107 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:55pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.3 | 513891.6 | 100088 | 1.64041666667 | 13107 |
| 013095 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:56pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.3 | 513891.6 | 100090 | 1.64041666667 | 13095 |
| 013111 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:57pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.4 | 513891.6 | 100092 | 1.64041666667 | 13111 |
| 013135 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:58pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.4 | 513891.7 | 100094 | 1.64041666667 | 13135 |
| 013186 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:59pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.3 | 513891.7 | 100096 | 1.64041666667 | 13186 |
| 013972 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:00pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.3 | 513891.8 | 100098 | 1.64041666667 | 13972 |
| 013762 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:01pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.3 | 513891.8 | 100100 | 1.64041666667 | 13762 |
| 013598 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:02pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597126.6 | 513891.8 | 100102 | 1.64041666667 | 13598 |
| 013761 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:03pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597128.0 | 513892.0 | 100104 | 1.64041666667 | 13761 |
| 012278 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:04pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597128.7 | 513892.3 | 100106 | 1.64041666667 | 12278 |
| 011324 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:05pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597128.8 | 513892.5 | 100108 | 1.64041666667 | 11324 |
| 011687 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:06pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597128.9 | 513892.6 | 100110 | 1.64041666667 | 11687 |
| 011764 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:07pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597128.9 | 513892.8 | 100112 | 1.64041666667 | 11764 |
| 011319 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:08pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597128.8 | 513892.9 | 100114 | 1.64041666667 | 11319 |
| 012255 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:09pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597129.0 | 513893.0 | 100116 | 1.64041666667 | 12255 |
| 012105 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:10pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597129.3 | 513893.0 | 100118 | 1.64041666667 | 12105 |
| 011504 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:11pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597129.9 | 513893.2 | 100120 | 1.64041666667 | 11504 |
| 010978 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:12pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597130.3 | 513893.4 | 100122 | 1.64041666667 | 10978 |
| 011125 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:13pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597130.6 | 513893.9 | 100124 | 1.64041666667 | 11125 |
| 010743 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:14pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597130.3 | 513894.8 | 100126 | 1.64041666667 | 10743 |
| 010385 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:15pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597130.2 | 513895.2 | 100128 | 1.64041666667 | 10385 |
| 010739 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:16pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597130.2 | 513895.1 | 100130 | 1.64041666667 | 10739 |
| 010668 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:17pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597130.2 | 513895.2 | 100132 | 1.64041666667 | 10668 |
| 009878 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:18pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597130.2 | 513895.2 | 100134 | 1.64041666667 | 9878 |
| 010364 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:19pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597130.1 | 513895.3 | 100136 | 1.64041666667 | 10364 |
| 010299 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:20pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597130.2 | 513895.3 | 100138 | 1.64041666667 | 10299 |
| 010556 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:21pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597130.3 | 513895.3 | 100140 | 1.64041666667 | 10556 |
| 011427 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:22pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597130.3 | 513895.3 | 100142 | 1.64041666667 | 11427 |
| 011213 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:23pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597130.5 | 513895.1 | 100144 | 1.64041666667 | 11213 |
| 011857 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:24pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597131.4 | 513894.6 | 100146 | 1.64041666667 | 11857 |
| 011559 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:25pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597132.6 | 513894.6 | 100148 | 1.64041666667 | 11559 |
| 010725 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:26pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597132.4 | 513894.7 | 100150 | 1.64041666667 | 10725 |
| 010660 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:27pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597131.8 | 513894.6 | 100152 | 1.64041666667 | 10660 |
| 011253 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:28pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597131.6 | 513894.6 | 100154 | 1.64041666667 | 11253 |
| 010837 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:29pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597131.5 | 513894.9 | 100156 | 1.64041666667 | 10837 |
| 010903 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:30pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597132.0 | 513895.6 | 100158 | 1.64041666667 | 10903 |
| 010618 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:31pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597132.5 | 513895.9 | 100160 | 1.64041666667 | 10618 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 010263 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:32pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597132.4 | 513896.1 | 100162 | 1.64041666667 | 10263 |
| 009830 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:33pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597132.2 | 513896.2 | 100164 | 1.64041666667 | 9830 |
| 010629 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:34pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597132.2 | 513896.3 | 100166 | 1.64041666667 | 10629 |
| 011461 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:35pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597132.3 | 513896.2 | 100168 | 1.64041666667 | 11461 |
| 010737 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:36pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597132.4 | 513896.2 | 100170 | 1.64041666667 | 10737 |
| 010419 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:37pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597132.4 | 513896.3 | 100172 | 1.64041666667 | 10419 |
| 010383 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:38pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597132.3 | 513896.3 | 100174 | 1.64041666667 | 10383 |
| 009958 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:39pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597132.2 | 513896.3 | 100176 | 1.64041666667 | 9958 |
| 010371 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:40pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597132.2 | 513896.2 | 100178 | 1.64041666667 | 10371 |
| 010191 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:41pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597132.3 | 513896.2 | 100180 | 1.64041666667 | 10191 |
| 010420 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:42pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597132.4 | 513896.3 | 100182 | 1.64041666667 | 10420 |
| 010271 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:43pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597133.4 | 513896.5 | 100184 | 1.64041666667 | 10271 |
| 011282 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:44pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597134.6 | 513897.4 | 100186 | 1.64041666667 | 11282 |
| 010944 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:45pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597134.8 | 513897.6 | 100188 | 1.64041666667 | 10944 |
| 011136 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:46pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597134.7 | 513897.6 | 100190 | 1.64041666667 | 11136 |
| 010494 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:47pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597134.6 | 513897.5 | 100192 | 1.64041666667 | 10494 |
| 012022 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:48pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597134.5 | 513897.4 | 100194 | 1.64041666667 | 12022 |
| 010992 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:49pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597134.0 | 513897.1 | 100196 | 1.64041666667 | 10992 |
| 011418 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:50pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597133.9 | 513897.3 | 100198 | 1.64041666667 | 11418 |
| 011868 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:51pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597134.3 | 513898.0 | 100200 | 1.64041666667 | 11868 |
| 011543 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:52pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597134.9 | 513898.9 | 100202 | 1.64041666667 | 11543 |
| 010858 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:53pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597134.0 | 513899.9 | 100204 | 1.64041666667 | 10858 |
| 011050 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:54pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597133.4 | 513901.2 | 100206 | 1.64041666667 | 11050 |
| 010678 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:55pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597132.4 | 513902.9 | 100208 | 1.64041666667 | 10678 |
| 010776 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:56pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597131.3 | 513904.1 | 100210 | 1.64041666667 | 10776 |
| 010749 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:57pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597130.2 | 513905.7 | 100212 | 1.64041666667 | 10749 |
| 011499 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:58pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597129.5 | 513906.2 | 100214 | 1.64041666667 | 11499 |
| 011290 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:59pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597129.5 | 513906.1 | 100216 | 1.64041666667 | 11290 |
| 010903 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597129.5 | 513906.1 | 100218 | 1.64041666667 | 10903 |
| 010190 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597129.4 | 513906.1 | 100220 | 1.64041666667 | 10190 |
| 010884 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597129.4 | 513906.1 | 100222 | 1.64041666667 | 10884 |
| 010757 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597129.4 | 513906.1 | 100224 | 1.64041666667 | 10757 |
| 010093 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597129.4 | 513906.1 | 100226 | 1.64041666667 | 10093 |
| 010132 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597129.4 | 513906.1 | 100228 | 1.64041666667 | 10132 |
| 010147 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597129.4 | 513906.1 | 100230 | 1.64041666667 | 10147 |
| 010260 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597129.4 | 513906.1 | 100232 | 1.64041666667 | 10260 |
| 010061 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597129.4 | 513906.1 | 100234 | 1.64041666667 | 10061 |
| 009739 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597129.4 | 513906.2 | 100236 | 1.64041666667 | 9739 |
| 037616 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:47pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.2 | 514010.4 | 100237 | 1.64041666667 | 37616 |
| 036684 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:48pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.3 | 514010.6 | 100239 | 1.64041666667 | 36684 |
| 036857 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:49pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597167.2 | 514010.6 | 100241 | 1.64041666667 | 36857 |
| 036767 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:50pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597167.2 | 514010.6 | 100243 | 1.64041666667 | 36767 |
| 037586 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:51pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.1 | 514010.6 | 100245 | 1.64041666667 | 37586 |
| 037545 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:52pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.1 | 514010.7 | 100247 | 1.64041666667 | 37545 |
| 037559 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:53pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.2 | 514010.6 | 100249 | 1.64041666667 | 37559 |
| 037462 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:54pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.2 | 514010.6 | 100251 | 1.64041666667 | 37462 |
| 036889 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.2 | 514010.6 | 100253 | 1.64041666667 | 36889 |
| 036808 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.2 | 514010.6 | 100255 | 1.64041666667 | 36808 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 036882 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.2 | 514010.6 | 100257 | 1.64041666667 | 36882 |
| 012369 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:23pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597091.8 | 513976.3 | 100258 | 1.64041666667 | 12369 |
| 012470 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:25pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597091.7 | 513976.4 | 100261 | 1.64041666667 | 12470 |
| 012632 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:25pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597091.7 | 513976.5 | 100262 | 1.64041666667 | 12632 |
| 012768 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:26pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597091.8 | 513976.4 | 100264 | 1.64041666667 | 12768 |
| 012252 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:27pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597092.1 | 513976.0 | 100266 | 1.64041666667 | 12252 |
| 012539 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:29pm | Sensor | 1797-S0058-G-636-DTE | 6863.8 | 1597091.5 | 513973.9 | 100269 | 1.64041666667 | 12539 |
| 012716 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:29pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597092.3 | 513972.1 | 100270 | 1.64041666667 | 12716 |
| 011960 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:31pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597093.0 | 513968.8 | 100273 | 1.64041666667 | 11960 |
| 012667 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:31pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597094.0 | 513966.7 | 100274 | 1.64041666667 | 12667 |
| 013290 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:33pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597094.9 | 513963.0 | 100277 | 1.64041666667 | 13290 |
| 013118 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:33pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597094.6 | 513960.3 | 100278 | 1.64041666667 | 13118 |
| 013386 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:34pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597094.9 | 513957.0 | 100280 | 1.64041666667 | 13386 |
| 015877 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:35pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597096.2 | 513954.4 | 100282 | 1.64041666667 | 15877 |
| 017301 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:36pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597097.3 | 513950.6 | 100284 | 1.64041666667 | 17301 |
| 028091 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:37pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597097.7 | 513947.6 | 100286 | 1.64041666667 | 28091 |
| 031544 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:38pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597097.9 | 513945.6 | 100288 | 1.64041666667 | 31544 |
| 038743 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:39pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597097.2 | 513945.7 | 100290 | 1.64041666667 | 38743 |
| 041653 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:40pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597096.8 | 513945.1 | 100292 | 1.64041666667 | 41653 |
| 045592 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:41pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597097.9 | 513944.0 | 100294 | 1.64041666667 | 45592 |
| 050748 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:43pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597098.2 | 513944.0 | 100297 | 1.64041666667 | 50748 |
| 053228 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:43pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597098.2 | 513944.0 | 100298 | 1.64041666667 | 53228 |
| 054286 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:44pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597098.3 | 513944.0 | 100300 | 1.64041666667 | 54286 |
| 053426 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:45pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597098.3 | 513943.9 | 100302 | 1.64041666667 | 53426 |
| 056564 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:46pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597097.4 | 513942.7 | 100304 | 1.64041666667 | 56564 |
| 056020 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:47pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597097.3 | 513943.0 | 100306 | 1.64041666667 | 56020 |
| 056066 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597097.1 | 513942.9 | 100308 | 1.64041666667 | 56066 |
| 055297 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:49pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597097.3 | 513942.9 | 100310 | 1.64041666667 | 55297 |
| 054159 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:50pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597098.9 | 513942.8 | 100312 | 1.64041666667 | 54159 |
| 054202 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:51pm | Sensor | 1797-S0058-G-636-DTE | 6859.5 | 1597099.2 | 513944.0 | 100314 | 1.64041666667 | 54202 |
| 056596 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:52pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597098.0 | 513943.5 | 100316 | 1.64041666667 | 56596 |
| 060020 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:53pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597099.5 | 513942.8 | 100318 | 1.64041666667 | 60020 |
| 055841 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:54pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597101.1 | 513940.5 | 100320 | 1.64041666667 | 55841 |
| 056288 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:55pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597102.1 | 513938.3 | 100322 | 1.64041666667 | 56288 |
| 057867 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:56pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597103.8 | 513935.9 | 100324 | 1.64041666667 | 57867 |
| 061807 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597104.5 | 513932.6 | 100326 | 1.64041666667 | 61807 |
| 059306 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597104.9 | 513929.5 | 100328 | 1.64041666667 | 59306 |
| 050782 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597105.9 | 513926.9 | 100330 | 1.64041666667 | 50782 |
| 043640 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:00pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597107.8 | 513923.9 | 100332 | 1.64041666667 | 43640 |
| 033532 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597109.1 | 513921.1 | 100334 | 1.64041666667 | 33532 |
| 025364 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597110.7 | 513918.1 | 100337 | 1.64041666667 | 25364 |
| 019382 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597112.4 | 513915.6 | 100338 | 1.64041666667 | 19382 |
| 015650 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597114.4 | 513912.8 | 100340 | 1.64041666667 | 15650 |
| 014090 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597115.5 | 513910.2 | 100342 | 1.64041666667 | 14090 |
| 013273 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597117.5 | 513908.1 | 100344 | 1.64041666667 | 13273 |
| 012071 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597119.9 | 513906.9 | 100346 | 1.64041666667 | 12071 |
| 012460 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597121.2 | 513904.3 | 100348 | 1.64041666667 | 12460 |
| 011531 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:09pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597123.1 | 513901.6 | 100350 | 1.64041666667 | 11531 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 011016 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:11pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597125.2 | 513898.2 | 100353 | 1.64041666667 | 11016 |
| 011229 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:11pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597125.6 | 513895.0 | 100354 | 1.64041666667 | 11229 |
| 011349 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:13pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597125.7 | 513891.9 | 100357 | 1.64041666667 | 11349 |
| 012728 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:13pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597127.7 | 513889.4 | 100358 | 1.64041666667 | 12728 |
| 011720 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:14pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597130.0 | 513886.3 | 100360 | 1.64041666667 | 11720 |
| 011557 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:15pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597131.3 | 513883.8 | 100362 | 1.64041666667 | 11557 |
| 011091 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:17pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597132.6 | 513880.7 | 100365 | 1.64041666667 | 11091 |
| 011128 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:17pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597134.4 | 513878.1 | 100366 | 1.64041666667 | 11128 |
| 011217 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:18pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597136.5 | 513876.1 | 100368 | 1.64041666667 | 11217 |
| 011522 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:19pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597137.2 | 513874.3 | 100370 | 1.64041666667 | 11522 |
| 011731 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:21pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597138.7 | 513872.6 | 100373 | 1.64041666667 | 11731 |
| 011136 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:21pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597139.1 | 513871.7 | 100374 | 1.64041666667 | 11136 |
| 011499 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:22pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597139.0 | 513871.6 | 100376 | 1.64041666667 | 11499 |
| 012438 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:23pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597139.2 | 513871.7 | 100378 | 1.64041666667 | 12438 |
| 012434 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:24pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597139.1 | 513871.8 | 100380 | 1.64041666667 | 12434 |
| 012401 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:25pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597139.3 | 513871.7 | 100382 | 1.64041666667 | 12401 |
| 012713 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:27pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597139.3 | 513871.8 | 100385 | 1.64041666667 | 12713 |
| 012656 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:27pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597139.3 | 513871.8 | 100386 | 1.64041666667 | 12656 |
| 012991 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:28pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597139.4 | 513871.7 | 100388 | 1.64041666667 | 12991 |
| 013465 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:29pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597139.4 | 513871.8 | 100390 | 1.64041666667 | 13465 |
| 012546 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:30pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597139.6 | 513871.5 | 100392 | 1.64041666667 | 12546 |
| 012195 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:31pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597140.7 | 513872.0 | 100394 | 1.64041666667 | 12195 |
| 012319 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:32pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597142.9 | 513873.2 | 100396 | 1.64041666667 | 12319 |
| 011887 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:33pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597145.4 | 513874.7 | 100398 | 1.64041666667 | 11887 |
| 011351 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:35pm | Sensor | 1797-S0058-G-636-DTE | 6860.1 | 1597149.8 | 513876.8 | 100401 | 1.64041666667 | 11351 |
| 010862 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:35pm | Sensor | 1797-S0058-G-636-DTE | 6860.1 | 1597152.2 | 513878.3 | 100402 | 1.64041666667 | 10862 |
| 010572 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:37pm | Sensor | 1797-S0058-G-636-DTE | 6860.1 | 1597154.6 | 513880.4 | 100405 | 1.64041666667 | 10572 |
| 010537 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:37pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597157.1 | 513881.6 | 100406 | 1.64041666667 | 10537 |
| 010539 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:39pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597160.0 | 513881.2 | 100409 | 1.64041666667 | 10539 |
| 011163 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:39pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597162.8 | 513881.4 | 100410 | 1.64041666667 | 11163 |
| 011162 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:40pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597166.1 | 513881.6 | 100412 | 1.64041666667 | 11162 |
| 011378 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:41pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597168.6 | 513881.1 | 100414 | 1.64041666667 | 11378 |
| 011080 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:42pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597171.6 | 513881.4 | 100416 | 1.64041666667 | 11080 |
| 010432 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:43pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597174.3 | 513880.9 | 100418 | 1.64041666667 | 10432 |
| 010481 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:44pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597177.5 | 513880.3 | 100420 | 1.64041666667 | 10481 |
| 010530 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:45pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597180.2 | 513880.5 | 100422 | 1.64041666667 | 10530 |
| 010228 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:47pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597183.4 | 513881.6 | 100425 | 1.64041666667 | 10228 |
| 011116 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:47pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597186.3 | 513882.4 | 100426 | 1.64041666667 | 11116 |
| 011285 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:49pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597188.5 | 513883.4 | 100429 | 1.64041666667 | 11285 |
| 010600 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:49pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597189.1 | 513884.7 | 100430 | 1.64041666667 | 10600 |
| 010342 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:51pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597191.9 | 513885.4 | 100433 | 1.64041666667 | 10342 |
| 010460 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:51pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597194.4 | 513887.5 | 100434 | 1.64041666667 | 10460 |
| 010578 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:53pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597196.4 | 513890.3 | 100437 | 1.64041666667 | 10578 |
| 010060 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:53pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597198.5 | 513892.6 | 100438 | 1.64041666667 | 10060 |
| 010609 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:55pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597201.4 | 513894.5 | 100441 | 1.64041666667 | 10609 |
| 010115 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:55pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597204.0 | 513896.3 | 100442 | 1.64041666667 | 10115 |
| 009964 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:56pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597207.3 | 513899.0 | 100444 | 1.64041666667 | 9964 |
| 010157 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:57pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597210.1 | 513900.6 | 100446 | 1.64041666667 | 10157 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 010116 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:58pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597213.1 | 513902.0 | 100448 | 1.64041666667 | 10116 |
| 010745 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:59pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597215.4 | 513903.6 | 100450 | 1.64041666667 | 10745 |
| 010836 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597218.6 | 513905.5 | 100452 | 1.64041666667 | 10836 |
| 011150 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597221.3 | 513906.6 | 100454 | 1.64041666667 | 11150 |
| 010967 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597224.0 | 513908.5 | 100456 | 1.64041666667 | 10967 |
| 010616 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597226.0 | 513910.8 | 100458 | 1.64041666667 | 10616 |
| 010666 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597228.1 | 513913.8 | 100461 | 1.64041666667 | 10666 |
| 010005 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597230.4 | 513915.0 | 100462 | 1.64041666667 | 10005 |
| 009610 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597233.2 | 513916.0 | 100464 | 1.64041666667 | 9610 |
| 009680 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597235.9 | 513916.8 | 100466 | 1.64041666667 | 9680 |
| 009900 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597238.7 | 513917.5 | 100468 | 1.64041666667 | 9900 |
| 010481 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597240.2 | 513917.8 | 100470 | 1.64041666667 | 10481 |
| 010193 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597241.0 | 513916.8 | 100472 | 1.64041666667 | 10193 |
| 010803 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:11pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597240.1 | 513914.9 | 100474 | 1.64041666667 | 10803 |
| 010832 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:12pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597240.0 | 513914.8 | 100476 | 1.64041666667 | 10832 |
| 011328 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:13pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597240.4 | 513915.0 | 100478 | 1.64041666667 | 11328 |
| 010744 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:14pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597239.9 | 513915.7 | 100480 | 1.64041666667 | 10744 |
| 010063 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:15pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597239.7 | 513916.0 | 100482 | 1.64041666667 | 10063 |
| 011323 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597239.7 | 513916.2 | 100485 | 1.64041666667 | 11323 |
| 011424 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597239.6 | 513916.2 | 100486 | 1.64041666667 | 11424 |
| 011863 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:19pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597239.4 | 513916.4 | 100489 | 1.64041666667 | 11863 |
| 012141 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:19pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597239.3 | 513916.4 | 100490 | 1.64041666667 | 12141 |
| 011621 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:20pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.4 | 513916.4 | 100492 | 1.64041666667 | 11621 |
| 011247 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:21pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.3 | 513916.5 | 100494 | 1.64041666667 | 11247 |
| 010954 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.2 | 513916.5 | 100496 | 1.64041666667 | 10954 |
| 011396 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.2 | 513916.5 | 100498 | 1.64041666667 | 11396 |
| 011345 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:24pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.2 | 513916.4 | 100500 | 1.64041666667 | 11345 |
| 012119 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:25pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.1 | 513916.4 | 100502 | 1.64041666667 | 12119 |
| 011219 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:27pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.2 | 513916.4 | 100505 | 1.64041666667 | 11219 |
| 011028 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:27pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.2 | 513916.5 | 100506 | 1.64041666667 | 11028 |
| 011423 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:29pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.1 | 513916.5 | 100509 | 1.64041666667 | 11423 |
| 011000 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:29pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.0 | 513916.5 | 100510 | 1.64041666667 | 11000 |
| 011010 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.1 | 513916.5 | 100512 | 1.64041666667 | 11010 |
| 011525 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.1 | 513916.5 | 100514 | 1.64041666667 | 11525 |
| 011321 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.1 | 513916.5 | 100516 | 1.64041666667 | 11321 |
| 011625 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597239.1 | 513916.6 | 100518 | 1.64041666667 | 11625 |
| 010747 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.1 | 513916.6 | 100520 | 1.64041666667 | 10747 |
| 010710 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597239.2 | 513916.7 | 100522 | 1.64041666667 | 10710 |
| 010764 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:36pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597239.1 | 513916.7 | 100524 | 1.64041666667 | 10764 |
| 011140 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:37pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597239.1 | 513916.6 | 100526 | 1.64041666667 | 11140 |
| 010383 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:38pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597239.8 | 513916.2 | 100528 | 1.64041666667 | 10383 |
| 010183 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:39pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597240.8 | 513915.7 | 100530 | 1.64041666667 | 10183 |
| 011458 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:40pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597240.3 | 513917.3 | 100532 | 1.64041666667 | 11458 |
| 011882 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:41pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597239.2 | 513920.1 | 100534 | 1.64041666667 | 11882 |
| 010996 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:42pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597237.5 | 513923.3 | 100536 | 1.64041666667 | 10996 |
| 011690 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:43pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597235.6 | 513926.2 | 100538 | 1.64041666667 | 11690 |
| 011413 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:44pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597234.0 | 513929.7 | 100540 | 1.64041666667 | 11413 |
| 010642 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:45pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597232.8 | 513932.8 | 100542 | 1.64041666667 | 10642 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 010156 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:47pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597231.1 | 513937.2 | 100545 | 1.64041666667 | 10156 |
| 009950 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:47pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597229.7 | 513940.5 | 100546 | 1.64041666667 | 9950 |
| 009729 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:48pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597228.0 | 513943.5 | 100548 | 1.64041666667 | 9729 |
| 009395 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:49pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597226.5 | 513946.4 | 100550 | 1.64041666667 | 9395 |
| 009469 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597224.4 | 513950.0 | 100553 | 1.64041666667 | 9469 |
| 010066 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597222.8 | 513952.5 | 100554 | 1.64041666667 | 10066 |
| 010770 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597220.5 | 513956.7 | 100557 | 1.64041666667 | 10770 |
| 010738 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597219.9 | 513959.8 | 100558 | 1.64041666667 | 10738 |
| 010577 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:54pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597219.1 | 513964.0 | 100560 | 1.64041666667 | 10577 |
| 009977 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:55pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597218.2 | 513967.1 | 100562 | 1.64041666667 | 9977 |
| 010765 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:56pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597216.7 | 513971.2 | 100564 | 1.64041666667 | 10765 |
| 010645 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:57pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597215.1 | 513974.3 | 100566 | 1.64041666667 | 10645 |
| 010293 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:58pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597213.5 | 513977.8 | 100568 | 1.64041666667 | 10293 |
| 010447 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:59pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597212.3 | 513981.4 | 100570 | 1.64041666667 | 10447 |
| 010114 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597210.9 | 513985.8 | 100572 | 1.64041666667 | 10114 |
| 009821 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:01pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597209.4 | 513988.7 | 100574 | 1.64041666667 | 9821 |
| 009799 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:02pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597207.4 | 513992.1 | 100576 | 1.64041666667 | 9799 |
| 010140 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:03pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597206.4 | 513995.3 | 100578 | 1.64041666667 | 10140 |
| 010353 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:04pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597205.0 | 513998.9 | 100580 | 1.64041666667 | 10353 |
| 010841 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:05pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597202.9 | 514001.8 | 100582 | 1.64041666667 | 10841 |
| 010680 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:06pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597199.8 | 514005.1 | 100584 | 1.64041666667 | 10680 |
| 010995 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:07pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597197.7 | 514007.4 | 100586 | 1.64041666667 | 10995 |
| 011442 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:08pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597194.8 | 514010.0 | 100588 | 1.64041666667 | 11442 |
| 010546 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:09pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597191.9 | 514011.3 | 100590 | 1.64041666667 | 10546 |
| 010252 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:10pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597187.7 | 514011.8 | 100592 | 1.64041666667 | 10252 |
| 010814 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597184.0 | 514011.5 | 100594 | 1.64041666667 | 10814 |
| 011445 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597180.0 | 514011.2 | 100596 | 1.64041666667 | 11445 |
| 013855 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597176.8 | 514011.1 | 100598 | 1.64041666667 | 13855 |
| 017896 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597172.8 | 514010.9 | 100600 | 1.64041666667 | 17896 |
| 023634 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597169.8 | 514011.1 | 100602 | 1.64041666667 | 23634 |
| 026051 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597166.8 | 514010.9 | 100604 | 1.64041666667 | 26051 |
| 023826 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597164.6 | 514011.4 | 100606 | 1.64041666667 | 23826 |
| 021517 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597161.2 | 514010.8 | 100608 | 1.64041666667 | 21517 |
| 020076 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597158.3 | 514009.1 | 100610 | 1.64041666667 | 20076 |
| 017262 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597155.1 | 514007.4 | 100612 | 1.64041666667 | 17262 |
| 016070 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597152.2 | 514006.4 | 100614 | 1.64041666667 | 16070 |
| 013959 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:22pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597148.8 | 514004.8 | 100616 | 1.64041666667 | 13959 |
| 012990 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:23pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597145.9 | 514003.6 | 100618 | 1.64041666667 | 12990 |
| 013426 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:24pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597142.8 | 514002.8 | 100620 | 1.64041666667 | 13426 |
| 015555 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597139.8 | 514001.5 | 100622 | 1.64041666667 | 15555 |
| 014247 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597137.3 | 513999.6 | 100624 | 1.64041666667 | 14247 |
| 013504 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597134.8 | 513998.8 | 100626 | 1.64041666667 | 13504 |
| 014503 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597131.9 | 513996.8 | 100628 | 1.64041666667 | 14503 |
| 014990 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597130.2 | 513994.4 | 100630 | 1.64041666667 | 14990 |
| 015662 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:30pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597127.3 | 513992.9 | 100632 | 1.64041666667 | 15662 |
| 016962 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:31pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597124.8 | 513990.9 | 100634 | 1.64041666667 | 16962 |
| 018991 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597121.9 | 513990.0 | 100636 | 1.64041666667 | 18991 |
| 017515 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597118.5 | 513989.4 | 100638 | 1.64041666667 | 17515 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 015019 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:34pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597115.8 | 513987.3 | 100640 | 1.64041666667 | 15019 |
| 014096 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:35pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597113.1 | 513986.8 | 100642 | 1.64041666667 | 14096 |
| 012541 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:36pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597110.4 | 513984.6 | 100644 | 1.64041666667 | 12541 |
| 012139 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:37pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597107.6 | 513983.6 | 100646 | 1.64041666667 | 12139 |
| 012221 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:38pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597104.4 | 513981.9 | 100648 | 1.64041666667 | 12221 |
| 011884 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:39pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597102.3 | 513980.1 | 100650 | 1.64041666667 | 11884 |
| 011717 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:40pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597099.4 | 513979.8 | 100652 | 1.64041666667 | 11717 |
| 012261 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:41pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597098.0 | 513977.7 | 100654 | 1.64041666667 | 12261 |
| 011884 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:42pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597095.9 | 513976.3 | 100656 | 1.64041666667 | 11884 |
| 011972 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:43pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597094.9 | 513975.0 | 100658 | 1.64041666667 | 11972 |
| 011444 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:44pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597094.2 | 513974.7 | 100660 | 1.64041666667 | 11444 |
| 010900 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:45pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597093.9 | 513974.7 | 100662 | 1.64041666667 | 10900 |
| 010976 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:46pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597093.8 | 513974.8 | 100664 | 1.64041666667 | 10976 |
| 010666 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:47pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597093.8 | 513974.8 | 100666 | 1.64041666667 | 10666 |
| 011565 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597093.7 | 513974.8 | 100668 | 1.64041666667 | 11565 |
| 011305 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:49pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597093.6 | 513974.9 | 100670 | 1.64041666667 | 11305 |
| 011354 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:50pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597093.7 | 513975.1 | 100672 | 1.64041666667 | 11354 |
| 010999 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:51pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597093.6 | 513975.1 | 100674 | 1.64041666667 | 10999 |
| 011324 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:52pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597093.5 | 513975.0 | 100676 | 1.64041666667 | 11324 |
| 011477 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:53pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597093.5 | 513974.9 | 100678 | 1.64041666667 | 11477 |
| 011443 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:54pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597093.6 | 513974.9 | 100680 | 1.64041666667 | 11443 |
| 011679 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597093.5 | 513974.9 | 100682 | 1.64041666667 | 11679 |
| 011190 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597093.4 | 513974.9 | 100684 | 1.64041666667 | 11190 |
| 010419 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597093.4 | 513974.9 | 100686 | 1.64041666667 | 10419 |
| 010878 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597093.4 | 513974.9 | 100688 | 1.64041666667 | 10878 |
| 011091 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597093.4 | 513974.9 | 100690 | 1.64041666667 | 11091 |
| 010506 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:00pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597093.3 | 513974.7 | 100692 | 1.64041666667 | 10506 |
| 011002 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:01pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597093.5 | 513974.6 | 100694 | 1.64041666667 | 11002 |
| 010943 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:02pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597094.9 | 513974.6 | 100696 | 1.64041666667 | 10943 |
| 011826 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:03pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597095.5 | 513974.3 | 100698 | 1.64041666667 | 11826 |
| 011849 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:04pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597095.1 | 513971.7 | 100700 | 1.64041666667 | 11849 |
| 012440 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:05pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597095.8 | 513969.2 | 100702 | 1.64041666667 | 12440 |
| 011955 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:06pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597095.9 | 513965.7 | 100704 | 1.64041666667 | 11955 |
| 011494 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:07pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597095.4 | 513963.1 | 100706 | 1.64041666667 | 11494 |
| 011603 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:08pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597096.8 | 513960.6 | 100708 | 1.64041666667 | 11603 |
| 012287 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:09pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597098.2 | 513957.6 | 100710 | 1.64041666667 | 12287 |
| 013818 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:10pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597099.4 | 513954.4 | 100712 | 1.64041666667 | 13818 |
| 015363 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597100.6 | 513952.2 | 100714 | 1.64041666667 | 15363 |
| 016201 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597100.5 | 513949.4 | 100716 | 1.64041666667 | 16201 |
| 022628 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597101.7 | 513947.2 | 100718 | 1.64041666667 | 22628 |
| 025103 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597101.5 | 513944.9 | 100720 | 1.64041666667 | 25103 |
| 031573 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597102.4 | 513943.3 | 100722 | 1.64041666667 | 31573 |
| 035122 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597103.9 | 513940.8 | 100724 | 1.64041666667 | 35122 |
| 042871 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597103.6 | 513939.1 | 100726 | 1.64041666667 | 42871 |
| 048047 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597103.6 | 513937.8 | 100728 | 1.64041666667 | 48047 |
| 047914 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597103.7 | 513937.8 | 100730 | 1.64041666667 | 47914 |
| 047606 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597103.7 | 513937.8 | 100732 | 1.64041666667 | 47606 |
| 050178 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597103.6 | 513938.6 | 100734 | 1.64041666667 | 50178 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 049143 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:22pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597104.3 | 513938.5 | 100736 | 1.64041666667 | 49143 |
| 049940 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:23pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597105.4 | 513936.9 | 100738 | 1.64041666667 | 49940 |
| 055593 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:24pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597107.1 | 513935.2 | 100740 | 1.64041666667 | 55593 |
| 054724 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597108.3 | 513933.3 | 100742 | 1.64041666667 | 54724 |
| 054024 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597109.8 | 513930.8 | 100744 | 1.64041666667 | 54024 |
| 049724 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597111.5 | 513928.6 | 100746 | 1.64041666667 | 49724 |
| 040877 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597112.0 | 513925.7 | 100748 | 1.64041666667 | 40877 |
| 030493 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597113.6 | 513923.6 | 100750 | 1.64041666667 | 30493 |
| 023115 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597114.6 | 513920.5 | 100752 | 1.64041666667 | 23115 |
| 018064 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597115.8 | 513918.0 | 100754 | 1.64041666667 | 18064 |
| 015306 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597118.3 | 513915.2 | 100756 | 1.64041666667 | 15306 |
| 013417 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597119.1 | 513912.9 | 100758 | 1.64041666667 | 13417 |
| 012647 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597121.4 | 513910.2 | 100760 | 1.64041666667 | 12647 |
| 011584 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597123.0 | 513908.1 | 100762 | 1.64041666667 | 11584 |
| 012006 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:36pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597123.7 | 513904.8 | 100764 | 1.64041666667 | 12006 |
| 011096 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:37pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597124.7 | 513902.9 | 100766 | 1.64041666667 | 11096 |
| 011244 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:38pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597125.9 | 513900.5 | 100768 | 1.64041666667 | 11244 |
| 010569 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:39pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597128.3 | 513899.1 | 100770 | 1.64041666667 | 10569 |
| 010685 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:40pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597130.2 | 513896.3 | 100772 | 1.64041666667 | 10685 |
| 010480 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:41pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597131.2 | 513893.7 | 100774 | 1.64041666667 | 10480 |
| 010515 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:42pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597133.1 | 513890.8 | 100776 | 1.64041666667 | 10515 |
| 011044 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:43pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597133.7 | 513888.7 | 100778 | 1.64041666667 | 11044 |
| 011672 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:44pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597134.8 | 513885.9 | 100780 | 1.64041666667 | 11672 |
| 012011 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:45pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597135.9 | 513884.0 | 100782 | 1.64041666667 | 12011 |
| 011436 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:46pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597136.4 | 513881.3 | 100784 | 1.64041666667 | 11436 |
| 011382 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:47pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597136.7 | 513879.6 | 100786 | 1.64041666667 | 11382 |
| 012905 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:48pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597136.9 | 513878.7 | 100788 | 1.64041666667 | 12905 |
| 012336 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:49pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.0 | 513878.6 | 100790 | 1.64041666667 | 12336 |
| 010884 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:50pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.0 | 513878.7 | 100792 | 1.64041666667 | 10884 |
| 011365 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:51pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.0 | 513878.7 | 100794 | 1.64041666667 | 11365 |
| 011290 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:52pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.0 | 513878.7 | 100796 | 1.64041666667 | 11290 |
| 012028 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:53pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.0 | 513878.7 | 100798 | 1.64041666667 | 12028 |
| 011723 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:54pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.1 | 513878.7 | 100800 | 1.64041666667 | 11723 |
| 011514 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:55pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.1 | 513878.7 | 100802 | 1.64041666667 | 11514 |
| 011801 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:56pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597137.1 | 513878.7 | 100804 | 1.64041666667 | 11801 |
| 011566 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:57pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.1 | 513878.7 | 100806 | 1.64041666667 | 11566 |
| 010428 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:58pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597137.2 | 513878.7 | 100808 | 1.64041666667 | 10428 |
| 010343 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:59pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.2 | 513878.7 | 100810 | 1.64041666667 | 10343 |
| 010355 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:00pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.2 | 513878.7 | 100812 | 1.64041666667 | 10355 |
| 011360 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:01pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.2 | 513878.7 | 100814 | 1.64041666667 | 11360 |
| 011812 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:02pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.2 | 513878.7 | 100816 | 1.64041666667 | 11812 |
| 011062 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:03pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.2 | 513878.7 | 100818 | 1.64041666667 | 11062 |
| 011930 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:04pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597137.2 | 513878.7 | 100820 | 1.64041666667 | 11930 |
| 011210 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:05pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597137.4 | 513878.7 | 100822 | 1.64041666667 | 11210 |
| 010723 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:06pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597137.9 | 513878.2 | 100824 | 1.64041666667 | 10723 |
| 011282 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:07pm | Sensor | 1797-S0058-G-636-DTE | 6860.2 | 1597138.7 | 513877.4 | 100826 | 1.64041666667 | 11282 |
| 011378 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:08pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597141.0 | 513876.9 | 100828 | 1.64041666667 | 11378 |
| 011673 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:09pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597143.3 | 513878.6 | 100830 | 1.64041666667 | 11673 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 010976 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:10pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597145.6 | 513880.8 | 100832 | 1.64041666667 | 10976 |
| 011592 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:11pm | Sensor | 1797-S0058-G-636-DTE | 6860.1 | 1597148.7 | 513882.1 | 100834 | 1.64041666667 | 11592 |
| 010704 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:12pm | Sensor | 1797-S0058-G-636-DTE | 6860.1 | 1597152.8 | 513883.4 | 100836 | 1.64041666667 | 10704 |
| 009989 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:13pm | Sensor | 1797-S0058-G-636-DTE | 6860.1 | 1597156.0 | 513885.0 | 100838 | 1.64041666667 | 9989 |
| 010478 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:14pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597159.7 | 513886.7 | 100840 | 1.64041666667 | 10478 |
| 010641 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:15pm | Sensor | 1797-S0058-G-636-DTE | 6860.3 | 1597163.0 | 513887.7 | 100842 | 1.64041666667 | 10641 |
| 010936 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:16pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597166.4 | 513889.3 | 100844 | 1.64041666667 | 10936 |
| 010291 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:17pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597168.7 | 513891.0 | 100846 | 1.64041666667 | 10291 |
| 010469 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:18pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597173.0 | 513893.0 | 100848 | 1.64041666667 | 10469 |
| 010936 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:19pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597175.9 | 513893.7 | 100850 | 1.64041666667 | 10936 |
| 010591 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:20pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597178.6 | 513895.7 | 100852 | 1.64041666667 | 10591 |
| 011507 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:21pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597181.0 | 513897.4 | 100854 | 1.64041666667 | 11507 |
| 011130 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597183.9 | 513898.7 | 100856 | 1.64041666667 | 11130 |
| 010926 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597186.6 | 513900.0 | 100858 | 1.64041666667 | 10926 |
| 010143 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:24pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597190.5 | 513901.5 | 100860 | 1.64041666667 | 10143 |
| 009260 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:25pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597194.0 | 513902.4 | 100862 | 1.64041666667 | 9260 |
| 010279 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:26pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597196.9 | 513903.8 | 100864 | 1.64041666667 | 10279 |
| 010019 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:27pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597200.1 | 513904.4 | 100866 | 1.64041666667 | 10019 |
| 009513 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:28pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597204.1 | 513906.1 | 100868 | 1.64041666667 | 9513 |
| 008793 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:29pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597207.0 | 513907.6 | 100870 | 1.64041666667 | 8793 |
| 010294 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597211.0 | 513908.9 | 100872 | 1.64041666667 | 10294 |
| 010237 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597213.9 | 513909.6 | 100874 | 1.64041666667 | 10237 |
| 010176 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597216.8 | 513910.6 | 100876 | 1.64041666667 | 10176 |
| 010246 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597219.7 | 513911.2 | 100878 | 1.64041666667 | 10246 |
| 010638 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597222.6 | 513912.7 | 100880 | 1.64041666667 | 10638 |
| 010379 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597225.1 | 513914.3 | 100882 | 1.64041666667 | 10379 |
| 010451 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:36pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597228.1 | 513914.7 | 100884 | 1.64041666667 | 10451 |
| 010881 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:37pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597230.6 | 513915.3 | 100886 | 1.64041666667 | 10881 |
| 011190 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:38pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597232.9 | 513915.8 | 100888 | 1.64041666667 | 11190 |
| 010614 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:39pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597233.7 | 513917.7 | 100890 | 1.64041666667 | 10614 |
| 010440 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:40pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597233.3 | 513920.5 | 100892 | 1.64041666667 | 10440 |
| 010327 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:41pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597232.2 | 513923.3 | 100894 | 1.64041666667 | 10327 |
| 010549 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:42pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597229.9 | 513926.4 | 100896 | 1.64041666667 | 10549 |
| 010636 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:43pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597228.1 | 513928.7 | 100898 | 1.64041666667 | 10636 |
| 011398 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:44pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597226.2 | 513932.4 | 100900 | 1.64041666667 | 11398 |
| 011699 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:45pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597224.1 | 513934.9 | 100902 | 1.64041666667 | 11699 |
| 011065 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:46pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597222.5 | 513936.9 | 100904 | 1.64041666667 | 11065 |
| 010312 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:47pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597222.8 | 513938.5 | 100906 | 1.64041666667 | 10312 |
| 010150 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:48pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597222.5 | 513938.1 | 100908 | 1.64041666667 | 10150 |
| 009782 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:49pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597221.9 | 513938.5 | 100910 | 1.64041666667 | 9782 |
| 010182 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:50pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597220.1 | 513940.7 | 100912 | 1.64041666667 | 10182 |
| 010272 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597219.1 | 513943.4 | 100914 | 1.64041666667 | 10272 |
| 009641 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:52pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597217.1 | 513946.4 | 100916 | 1.64041666667 | 9641 |
| 009833 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597215.3 | 513948.7 | 100918 | 1.64041666667 | 9833 |
| 010301 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:54pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597214.0 | 513951.9 | 100920 | 1.64041666667 | 10301 |
| 009604 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:55pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597212.7 | 513953.3 | 100922 | 1.64041666667 | 9604 |
| 010315 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:56pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597211.2 | 513956.0 | 100924 | 1.64041666667 | 10315 |
| 009882 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:57pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597210.3 | 513959.2 | 100926 | 1.64041666667 | 9882 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 009923 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:58pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597208.3 | 513962.8 | 100928 | 1.64041666667 | 9923 |
| 009677 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:59pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597206.5 | 513965.6 | 100930 | 1.64041666667 | 9677 |
| 009553 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597205.0 | 513969.4 | 100932 | 1.64041666667 | 9553 |
| 009791 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597203.7 | 513972.4 | 100934 | 1.64041666667 | 9791 |
| 009812 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597202.1 | 513975.7 | 100936 | 1.64041666667 | 9812 |
| 010867 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597200.6 | 513978.5 | 100938 | 1.64041666667 | 10867 |
| 010192 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597198.8 | 513982.1 | 100940 | 1.64041666667 | 10192 |
| 009881 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597197.9 | 513984.9 | 100942 | 1.64041666667 | 9881 |
| 009270 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597197.3 | 513988.8 | 100944 | 1.64041666667 | 9270 |
| 010007 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597197.0 | 513992.2 | 100946 | 1.64041666667 | 10007 |
| 009859 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597196.5 | 513995.5 | 100948 | 1.64041666667 | 9859 |
| 009175 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:09pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597195.8 | 513998.1 | 100950 | 1.64041666667 | 9175 |
| 010073 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:10pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597195.8 | 514000.9 | 100952 | 1.64041666667 | 10073 |
| 010856 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597196.0 | 514002.7 | 100954 | 1.64041666667 | 10856 |
| 010899 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:12pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597195.5 | 514003.1 | 100956 | 1.64041666667 | 10899 |
| 010691 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597193.5 | 514002.4 | 100958 | 1.64041666667 | 10691 |
| 010543 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:14pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597190.4 | 514000.9 | 100960 | 1.64041666667 | 10543 |
| 009973 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:15pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597186.8 | 514000.8 | 100962 | 1.64041666667 | 9973 |
| 010192 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597183.3 | 514001.2 | 100964 | 1.64041666667 | 10192 |
| 010931 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597179.9 | 514000.6 | 100966 | 1.64041666667 | 10931 |
| 011826 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597176.0 | 513999.3 | 100968 | 1.64041666667 | 11826 |
| 012869 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597173.5 | 513998.5 | 100970 | 1.64041666667 | 12869 |
| 012466 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597170.6 | 513996.5 | 100972 | 1.64041666667 | 12466 |
| 011655 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.7 | 513995.5 | 100974 | 1.64041666667 | 11655 |
| 011633 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:22pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597164.2 | 513995.9 | 100976 | 1.64041666667 | 11633 |
| 011471 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:23pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597161.3 | 513994.9 | 100978 | 1.64041666667 | 11471 |
| 012362 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:24pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597159.1 | 513992.6 | 100980 | 1.64041666667 | 12362 |
| 011844 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597157.2 | 513991.0 | 100982 | 1.64041666667 | 11844 |
| 012197 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:26pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597155.0 | 513989.5 | 100984 | 1.64041666667 | 12197 |
| 012171 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597152.2 | 513988.2 | 100986 | 1.64041666667 | 12171 |
| 012411 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597148.7 | 513987.5 | 100988 | 1.64041666667 | 12411 |
| 011616 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597145.7 | 513987.6 | 100990 | 1.64041666667 | 11616 |
| 012279 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:30pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597141.2 | 513987.2 | 100992 | 1.64041666667 | 12279 |
| 012022 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597137.8 | 513986.1 | 100994 | 1.64041666667 | 12022 |
| 013489 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597133.9 | 513984.5 | 100996 | 1.64041666667 | 13489 |
| 015058 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597130.8 | 513983.7 | 100998 | 1.64041666667 | 15058 |
| 023575 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597127.5 | 513983.2 | 101000 | 1.64041666667 | 23575 |
| 029281 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597125.0 | 513982.3 | 101002 | 1.64041666667 | 29281 |
| 029873 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:36pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597122.4 | 513981.1 | 101004 | 1.64041666667 | 29873 |
| 026583 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:37pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597119.8 | 513980.9 | 101006 | 1.64041666667 | 26583 |
| 020720 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:38pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597117.2 | 513979.3 | 101008 | 1.64041666667 | 20720 |
| 019470 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:39pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597114.3 | 513978.9 | 101010 | 1.64041666667 | 19470 |
| 022134 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:40pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597110.9 | 513977.8 | 101012 | 1.64041666667 | 22134 |
| 022133 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:41pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597108.2 | 513977.1 | 101014 | 1.64041666667 | 22133 |
| 017842 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:42pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597104.9 | 513976.4 | 101016 | 1.64041666667 | 17842 |
| 015503 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:43pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597103.1 | 513974.9 | 101018 | 1.64041666667 | 15503 |
| 013483 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:44pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597100.7 | 513974.0 | 101020 | 1.64041666667 | 13483 |
| 012669 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:45pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597100.7 | 513973.1 | 101022 | 1.64041666667 | 12669 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 012219 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:46pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597101.1 | 513970.6 | 101024 | 1.64041666667 | 12219 |
| 012145 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:47pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597102.3 | 513968.5 | 101026 | 1.64041666667 | 12145 |
| 012502 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597102.6 | 513965.4 | 101028 | 1.64041666667 | 12502 |
| 012087 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:49pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597103.5 | 513962.7 | 101030 | 1.64041666667 | 12087 |
| 012094 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:50pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597104.6 | 513959.8 | 101032 | 1.64041666667 | 12094 |
| 012570 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:51pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597105.7 | 513957.2 | 101034 | 1.64041666667 | 12570 |
| 013220 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:52pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597107.9 | 513954.9 | 101036 | 1.64041666667 | 13220 |
| 012244 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:53pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597108.4 | 513952.7 | 101038 | 1.64041666667 | 12244 |
| 012670 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:54pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597110.1 | 513950.0 | 101040 | 1.64041666667 | 12670 |
| 012811 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597111.4 | 513947.7 | 101042 | 1.64041666667 | 12811 |
| 013491 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597112.8 | 513944.6 | 101044 | 1.64041666667 | 13491 |
| 013656 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597114.6 | 513942.8 | 101046 | 1.64041666667 | 13656 |
| 013314 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597115.5 | 513940.1 | 101048 | 1.64041666667 | 13314 |
| 014014 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597117.2 | 513937.8 | 101050 | 1.64041666667 | 14014 |
| 013980 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597119.0 | 513934.8 | 101052 | 1.64041666667 | 13980 |
| 014014 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597120.0 | 513932.2 | 101054 | 1.64041666667 | 14014 |
| 013132 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597122.1 | 513929.5 | 101056 | 1.64041666667 | 13132 |
| 011932 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597122.3 | 513927.0 | 101058 | 1.64041666667 | 11932 |
| 011534 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597123.3 | 513923.8 | 101060 | 1.64041666667 | 11534 |
| 010568 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597124.7 | 513920.8 | 101062 | 1.64041666667 | 10568 |
| 010782 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597125.6 | 513917.3 | 101064 | 1.64041666667 | 10782 |
| 010504 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597126.9 | 513914.6 | 101066 | 1.64041666667 | 10504 |
| 010469 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597128.7 | 513911.0 | 101068 | 1.64041666667 | 10469 |
| 010958 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597129.7 | 513907.9 | 101070 | 1.64041666667 | 10958 |
| 010702 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:10pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597130.9 | 513905.1 | 101072 | 1.64041666667 | 10702 |
| 010294 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:11pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597132.8 | 513902.4 | 101074 | 1.64041666667 | 10294 |
| 010695 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:12pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597134.6 | 513898.9 | 101076 | 1.64041666667 | 10695 |
| 010733 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:13pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597134.6 | 513895.9 | 101078 | 1.64041666667 | 10733 |
| 011257 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:14pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597135.2 | 513892.2 | 101080 | 1.64041666667 | 11257 |
| 011380 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:15pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597136.4 | 513890.0 | 101082 | 1.64041666667 | 11380 |
| 012033 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:16pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597137.7 | 513887.9 | 101084 | 1.64041666667 | 12033 |
| 011749 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:17pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597139.4 | 513887.5 | 101086 | 1.64041666667 | 11749 |
| 011146 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:18pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597140.3 | 513887.5 | 101088 | 1.64041666667 | 11146 |
| 010942 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:19pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597140.5 | 513887.6 | 101090 | 1.64041666667 | 10942 |
| 010572 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:20pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597140.4 | 513887.8 | 101092 | 1.64041666667 | 10572 |
| 010552 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:21pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597140.4 | 513887.8 | 101094 | 1.64041666667 | 10552 |
| 010645 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:22pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597140.4 | 513887.8 | 101096 | 1.64041666667 | 10645 |
| 010840 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:23pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597140.4 | 513887.8 | 101098 | 1.64041666667 | 10840 |
| 011280 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:24pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597140.8 | 513887.7 | 101100 | 1.64041666667 | 11280 |
| 011430 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:25pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597142.3 | 513888.3 | 101102 | 1.64041666667 | 11430 |
| 012204 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:26pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597144.7 | 513889.7 | 101104 | 1.64041666667 | 12204 |
| 012032 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:27pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597146.6 | 513891.9 | 101106 | 1.64041666667 | 12032 |
| 011261 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:28pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597150.0 | 513894.8 | 101108 | 1.64041666667 | 11261 |
| 010916 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:29pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597153.4 | 513896.7 | 101110 | 1.64041666667 | 10916 |
| 010430 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597156.8 | 513898.3 | 101112 | 1.64041666667 | 10430 |
| 010502 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597160.1 | 513900.0 | 101114 | 1.64041666667 | 10502 |
| 010962 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597164.0 | 513902.0 | 101116 | 1.64041666667 | 10962 |
| 011858 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597167.8 | 513902.7 | 101118 | 1.64041666667 | 11858 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 011058 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597171.9 | 513903.7 | 101120 | 1.64041666667 | 11058 |
| 011477 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597175.3 | 513905.4 | 101122 | 1.64041666667 | 11477 |
| 011008 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:36pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597179.3 | 513906.5 | 101124 | 1.64041666667 | 11008 |
| 010587 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:37pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597182.5 | 513907.1 | 101126 | 1.64041666667 | 10587 |
| 010372 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:38pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597186.4 | 513908.6 | 101128 | 1.64041666667 | 10372 |
| 009817 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:39pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597189.1 | 513909.6 | 101130 | 1.64041666667 | 9817 |
| 009729 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:40pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597192.8 | 513911.2 | 101132 | 1.64041666667 | 9729 |
| 009800 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:41pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597195.7 | 513912.0 | 101134 | 1.64041666667 | 9800 |
| 009705 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:42pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597199.0 | 513913.6 | 101136 | 1.64041666667 | 9705 |
| 009951 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:43pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597201.5 | 513914.6 | 101138 | 1.64041666667 | 9951 |
| 009640 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:44pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597205.8 | 513915.2 | 101140 | 1.64041666667 | 9640 |
| 009127 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:45pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597209.7 | 513914.7 | 101142 | 1.64041666667 | 9127 |
| 009686 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:46pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597212.9 | 513914.9 | 101144 | 1.64041666667 | 9686 |
| 009468 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:47pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597215.5 | 513915.9 | 101146 | 1.64041666667 | 9468 |
| 009436 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:48pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597219.1 | 513917.0 | 101148 | 1.64041666667 | 9436 |
| 009673 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:49pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597222.1 | 513917.8 | 101150 | 1.64041666667 | 9673 |
| 009911 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:50pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597225.1 | 513919.7 | 101152 | 1.64041666667 | 9911 |
| 009505 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597227.8 | 513922.1 | 101154 | 1.64041666667 | 9505 |
| 009666 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:52pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597230.3 | 513924.7 | 101156 | 1.64041666667 | 9666 |
| 009240 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597231.4 | 513927.3 | 101158 | 1.64041666667 | 9240 |
| 009705 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:54pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597231.1 | 513930.5 | 101160 | 1.64041666667 | 9705 |
| 009726 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:55pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597229.9 | 513932.7 | 101162 | 1.64041666667 | 9726 |
| 009723 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:56pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597227.4 | 513935.6 | 101164 | 1.64041666667 | 9723 |
| 010517 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:57pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597224.3 | 513936.9 | 101166 | 1.64041666667 | 10517 |
| 010341 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:58pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597220.8 | 513936.1 | 101168 | 1.64041666667 | 10341 |
| 009941 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:59pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597217.9 | 513935.3 | 101170 | 1.64041666667 | 9941 |
| 009447 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597214.7 | 513934.9 | 101172 | 1.64041666667 | 9447 |
| 009664 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597211.4 | 513934.2 | 101174 | 1.64041666667 | 9664 |
| 010393 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597207.6 | 513932.9 | 101176 | 1.64041666667 | 10393 |
| 010518 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597204.9 | 513931.4 | 101178 | 1.64041666667 | 10518 |
| 010229 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597202.0 | 513929.1 | 101180 | 1.64041666667 | 10229 |
| 010651 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597199.3 | 513927.0 | 101182 | 1.64041666667 | 10651 |
| 010769 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597196.4 | 513924.8 | 101184 | 1.64041666667 | 10769 |
| 009710 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597193.3 | 513923.8 | 101186 | 1.64041666667 | 9710 |
| 010007 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597189.4 | 513922.9 | 101188 | 1.64041666667 | 10007 |
| 009536 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597185.7 | 513921.4 | 101190 | 1.64041666667 | 9536 |
| 009286 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597182.0 | 513919.1 | 101192 | 1.64041666667 | 9286 |
| 010361 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:11pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597179.0 | 513917.2 | 101194 | 1.64041666667 | 10361 |
| 010035 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:12pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597175.0 | 513915.2 | 101196 | 1.64041666667 | 10035 |
| 009725 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:13pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597172.7 | 513913.2 | 101198 | 1.64041666667 | 9725 |
| 010135 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:14pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597169.9 | 513910.5 | 101200 | 1.64041666667 | 10135 |
| 009623 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:15pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597167.0 | 513909.5 | 101202 | 1.64041666667 | 9623 |
| 010453 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:16pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597164.2 | 513907.8 | 101204 | 1.64041666667 | 10453 |
| 011190 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597161.9 | 513905.9 | 101206 | 1.64041666667 | 11190 |
| 010734 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:18pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597159.3 | 513904.0 | 101208 | 1.64041666667 | 10734 |
| 010350 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:19pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597156.7 | 513902.5 | 101210 | 1.64041666667 | 10350 |
| 010682 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:20pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597152.6 | 513900.5 | 101212 | 1.64041666667 | 10682 |
| 010328 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:21pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597149.5 | 513899.4 | 101214 | 1.64041666667 | 10328 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 011367 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597145.9 | 513898.6 | 101216 | 1.64041666667 | 11367 |
| 010901 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597142.6 | 513898.0 | 101218 | 1.64041666667 | 10901 |
| 010774 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:24pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597139.2 | 513896.5 | 101220 | 1.64041666667 | 10774 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:25pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597136.8 | 513894.5 | 101222 | 1.64041666667 | 11205 |
| 011755 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:26pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597134.3 | 513892.2 | 101224 | 1.64041666667 | 11755 |
| 011757 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:27pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597132.0 | 513890.1 | 101226 | 1.64041666667 | 11757 |
| 012756 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:28pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597129.6 | 513887.3 | 101228 | 1.64041666667 | 12756 |
| 012447 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:29pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597127.8 | 513885.5 | 101230 | 1.64041666667 | 12447 |
| 012349 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:30pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597125.8 | 513884.5 | 101232 | 1.64041666667 | 12349 |
| 012969 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:31pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597124.8 | 513883.8 | 101234 | 1.64041666667 | 12969 |
| 014217 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:32pm | Sensor | 1797-S0058-G-636-DTE | 6860.5 | 1597124.1 | 513885.6 | 101236 | 1.64041666667 | 14217 |
| 013975 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:33pm | Sensor | 1797-S0058-G-636-DTE | 6860.4 | 1597123.4 | 513888.0 | 101238 | 1.64041666667 | 13975 |
| 013148 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:34pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597122.1 | 513890.8 | 101240 | 1.64041666667 | 13148 |
| 012706 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:35pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597121.8 | 513892.2 | 101242 | 1.64041666667 | 12706 |
| 012134 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:36pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597121.2 | 513893.2 | 101244 | 1.64041666667 | 12134 |
| 011955 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:37pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597121.2 | 513893.6 | 101246 | 1.64041666667 | 11955 |
| 011742 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:38pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597123.0 | 513894.6 | 101248 | 1.64041666667 | 11742 |
| 011150 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:39pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597125.5 | 513896.2 | 101250 | 1.64041666667 | 11150 |
| 011184 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:40pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597129.4 | 513898.8 | 101252 | 1.64041666667 | 11184 |
| 010881 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:41pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597132.3 | 513900.6 | 101254 | 1.64041666667 | 10881 |
| 010635 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:42pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597136.3 | 513902.9 | 101256 | 1.64041666667 | 10635 |
| 010662 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:43pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597139.5 | 513905.0 | 101258 | 1.64041666667 | 10662 |
| 009710 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:44pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597143.0 | 513907.6 | 101260 | 1.64041666667 | 9710 |
| 010029 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:45pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597146.0 | 513909.8 | 101262 | 1.64041666667 | 10029 |
| 010231 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:46pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597149.0 | 513911.5 | 101264 | 1.64041666667 | 10231 |
| 009722 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:47pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597152.1 | 513912.8 | 101266 | 1.64041666667 | 9722 |
| 010111 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:48pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597156.0 | 513913.9 | 101268 | 1.64041666667 | 10111 |
| 010225 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:49pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597159.0 | 513914.9 | 101270 | 1.64041666667 | 10225 |
| 010866 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:50pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597162.8 | 513916.5 | 101272 | 1.64041666667 | 10866 |
| 010950 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597165.7 | 513917.9 | 101274 | 1.64041666667 | 10950 |
| 010382 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:52pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597169.5 | 513920.3 | 101276 | 1.64041666667 | 10382 |
| 009927 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597172.7 | 513922.5 | 101278 | 1.64041666667 | 9927 |
| 009649 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:54pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597176.6 | 513924.8 | 101280 | 1.64041666667 | 9649 |
| 010122 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:55pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597179.5 | 513925.6 | 101282 | 1.64041666667 | 10122 |
| 010059 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:56pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597183.3 | 513926.4 | 101284 | 1.64041666667 | 10059 |
| 009910 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:57pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597186.4 | 513927.6 | 101286 | 1.64041666667 | 9910 |
| 010427 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:58pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597189.1 | 513929.4 | 101288 | 1.64041666667 | 10427 |
| 010575 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:59pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597191.9 | 513931.2 | 101290 | 1.64041666667 | 10575 |
| 011078 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597196.0 | 513933.2 | 101292 | 1.64041666667 | 11078 |
| 010866 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597198.9 | 513935.1 | 101294 | 1.64041666667 | 10866 |
| 011010 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597202.3 | 513937.5 | 101296 | 1.64041666667 | 11010 |
| 011045 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597205.7 | 513939.7 | 101298 | 1.64041666667 | 11045 |
| 010600 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597208.8 | 513941.9 | 101300 | 1.64041666667 | 10600 |
| 009990 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597211.8 | 513943.7 | 101302 | 1.64041666667 | 9990 |
| 009639 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597215.2 | 513945.2 | 101304 | 1.64041666667 | 9639 |
| 009585 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597218.4 | 513946.7 | 101306 | 1.64041666667 | 9585 |
| 008939 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597221.5 | 513948.2 | 101308 | 1.64041666667 | 8939 |
| 009610 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597224.6 | 513948.9 | 101310 | 1.64041666667 | 9610 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 010063 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597227.7 | 513949.6 | 101312 | 1.64041666667 | 10063 |
| 010730 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:11pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597229.0 | 513951.7 | 101314 | 1.64041666667 | 10730 |
| 009696 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:12pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597228.3 | 513955.0 | 101316 | 1.64041666667 | 9696 |
| 009661 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:13pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597227.3 | 513957.3 | 101318 | 1.64041666667 | 9661 |
| 009447 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:14pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597224.9 | 513959.4 | 101320 | 1.64041666667 | 9447 |
| 009379 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:15pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597222.3 | 513958.9 | 101322 | 1.64041666667 | 9379 |
| 009558 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:16pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597219.3 | 513957.3 | 101324 | 1.64041666667 | 9558 |
| 010131 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597216.6 | 513955.6 | 101326 | 1.64041666667 | 10131 |
| 010274 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:18pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597213.8 | 513953.8 | 101328 | 1.64041666667 | 10274 |
| 009979 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:19pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597211.9 | 513952.3 | 101330 | 1.64041666667 | 9979 |
| 009325 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:20pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597209.3 | 513949.6 | 101332 | 1.64041666667 | 9325 |
| 009663 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:21pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597206.9 | 513947.3 | 101334 | 1.64041666667 | 9663 |
| 009665 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597204.4 | 513945.5 | 101336 | 1.64041666667 | 9665 |
| 009254 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597202.2 | 513944.0 | 101338 | 1.64041666667 | 9254 |
| 009915 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:24pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597198.9 | 513942.5 | 101340 | 1.64041666667 | 9915 |
| 009905 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:25pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597195.5 | 513941.5 | 101342 | 1.64041666667 | 9905 |
| 009531 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:26pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597191.5 | 513940.7 | 101344 | 1.64041666667 | 9531 |
| 010469 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:27pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597188.3 | 513939.2 | 101346 | 1.64041666667 | 10469 |
| 011086 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:28pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597185.8 | 513936.8 | 101348 | 1.64041666667 | 11086 |
| 010721 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:29pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597183.6 | 513935.7 | 101350 | 1.64041666667 | 10721 |
| 010898 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597180.4 | 513935.1 | 101352 | 1.64041666667 | 10898 |
| 009730 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597176.9 | 513934.9 | 101354 | 1.64041666667 | 9730 |
| 010265 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597172.7 | 513934.7 | 101356 | 1.64041666667 | 10265 |
| 010387 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597169.4 | 513934.3 | 101358 | 1.64041666667 | 10387 |
| 010320 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597165.3 | 513933.4 | 101360 | 1.64041666667 | 10320 |
| 010980 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597162.1 | 513932.2 | 101362 | 1.64041666667 | 10980 |
| 010676 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:36pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597158.3 | 513930.6 | 101364 | 1.64041666667 | 10676 |
| 010310 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:37pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597155.2 | 513929.0 | 101366 | 1.64041666667 | 10310 |
| 010374 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:38pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597151.7 | 513927.1 | 101368 | 1.64041666667 | 10374 |
| 010815 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:39pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597148.8 | 513926.0 | 101370 | 1.64041666667 | 10815 |
| 010666 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:40pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597145.7 | 513924.4 | 101372 | 1.64041666667 | 10666 |
| 010522 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:41pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597143.5 | 513922.2 | 101374 | 1.64041666667 | 10522 |
| 010636 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:42pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597140.5 | 513920.0 | 101376 | 1.64041666667 | 10636 |
| 010467 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:43pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597138.1 | 513918.5 | 101378 | 1.64041666667 | 10467 |
| 010245 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:44pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597135.1 | 513916.3 | 101380 | 1.64041666667 | 10245 |
| 010204 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:45pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597132.4 | 513914.8 | 101382 | 1.64041666667 | 10204 |
| 009967 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:46pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597129.4 | 513913.7 | 101384 | 1.64041666667 | 9967 |
| 010376 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:47pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597127.0 | 513911.9 | 101386 | 1.64041666667 | 10376 |
| 010861 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:48pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597124.0 | 513910.0 | 101388 | 1.64041666667 | 10861 |
| 010842 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:49pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597121.2 | 513909.8 | 101390 | 1.64041666667 | 10842 |
| 011063 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:50pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597118.0 | 513910.0 | 101392 | 1.64041666667 | 11063 |
| 010738 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597116.4 | 513911.8 | 101394 | 1.64041666667 | 10738 |
| 011268 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:52pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597114.7 | 513914.2 | 101396 | 1.64041666667 | 11268 |
| 012435 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597113.5 | 513916.8 | 101398 | 1.64041666667 | 12435 |
| 012950 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:54pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597113.9 | 513918.9 | 101400 | 1.64041666667 | 12950 |
| 012557 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:55pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597115.7 | 513920.7 | 101402 | 1.64041666667 | 12557 |
| 012215 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:56pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597118.7 | 513922.6 | 101404 | 1.64041666667 | 12215 |
| 011611 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:57pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597121.1 | 513924.3 | 101406 | 1.64041666667 | 11611 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 011519 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:58pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597124.0 | 513926.0 | 101408 | 1.64041666667 | 11519 |
| 010964 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:59pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597126.9 | 513926.8 | 101410 | 1.64041666667 | 10964 |
| 010817 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597129.9 | 513928.7 | 101412 | 1.64041666667 | 10817 |
| 011410 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597132.4 | 513930.1 | 101414 | 1.64041666667 | 11410 |
| 011810 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597134.9 | 513931.9 | 101416 | 1.64041666667 | 11810 |
| 011346 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597137.4 | 513932.1 | 101418 | 1.64041666667 | 11346 |
| 011789 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597140.8 | 513932.3 | 101420 | 1.64041666667 | 11789 |
| 011281 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597143.4 | 513933.3 | 101422 | 1.64041666667 | 11281 |
| 011108 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597146.2 | 513934.7 | 101424 | 1.64041666667 | 11108 |
| 011198 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597148.6 | 513935.6 | 101426 | 1.64041666667 | 11198 |
| 011684 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597151.9 | 513937.1 | 101428 | 1.64041666667 | 11684 |
| 010727 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597154.9 | 513938.3 | 101430 | 1.64041666667 | 10727 |
| 010736 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597158.4 | 513939.2 | 101432 | 1.64041666667 | 10736 |
| 010719 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:11pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597161.9 | 513940.0 | 101434 | 1.64041666667 | 10719 |
| 010327 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:12pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597166.1 | 513941.0 | 101436 | 1.64041666667 | 10327 |
| 010886 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:13pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597168.9 | 513941.4 | 101438 | 1.64041666667 | 10886 |
| 010713 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:14pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597172.4 | 513941.4 | 101440 | 1.64041666667 | 10713 |
| 010256 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:15pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597175.1 | 513942.0 | 101442 | 1.64041666667 | 10256 |
| 010096 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:16pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597178.4 | 513944.0 | 101444 | 1.64041666667 | 10096 |
| 009684 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597181.5 | 513945.8 | 101446 | 1.64041666667 | 9684 |
| 009467 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:18pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597185.5 | 513947.8 | 101448 | 1.64041666667 | 9467 |
| 009380 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:19pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597188.9 | 513949.1 | 101450 | 1.64041666667 | 9380 |
| 010167 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:20pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597193.3 | 513950.6 | 101452 | 1.64041666667 | 10167 |
| 009904 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:21pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597196.6 | 513952.3 | 101454 | 1.64041666667 | 9904 |
| 009696 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597199.9 | 513953.6 | 101456 | 1.64041666667 | 9696 |
| 010044 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597202.9 | 513954.4 | 101458 | 1.64041666667 | 10044 |
| 010757 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:24pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597207.1 | 513955.5 | 101460 | 1.64041666667 | 10757 |
| 010521 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:25pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597210.0 | 513957.0 | 101462 | 1.64041666667 | 10521 |
| 009600 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:26pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597213.7 | 513958.9 | 101464 | 1.64041666667 | 9600 |
| 009555 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:27pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597216.9 | 513959.7 | 101466 | 1.64041666667 | 9555 |
| 009837 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:28pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597221.4 | 513960.4 | 101468 | 1.64041666667 | 9837 |
| 010191 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:29pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597224.4 | 513961.1 | 101470 | 1.64041666667 | 10191 |
| 009857 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597227.6 | 513962.0 | 101472 | 1.64041666667 | 9857 |
| 010314 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597229.7 | 513963.1 | 101474 | 1.64041666667 | 10314 |
| 010159 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597231.0 | 513965.6 | 101476 | 1.64041666667 | 10159 |
| 010079 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597230.1 | 513968.3 | 101478 | 1.64041666667 | 10079 |
| 009885 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597227.9 | 513971.4 | 101480 | 1.64041666667 | 9885 |
| 009827 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597225.9 | 513973.1 | 101482 | 1.64041666667 | 9827 |
| 010770 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:36pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597222.8 | 513973.6 | 101484 | 1.64041666667 | 10770 |
| 010153 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:37pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597219.5 | 513972.8 | 101486 | 1.64041666667 | 10153 |
| 009761 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:38pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597216.6 | 513971.0 | 101488 | 1.64041666667 | 9761 |
| 009563 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:39pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597213.9 | 513969.3 | 101490 | 1.64041666667 | 9563 |
| 009556 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:40pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597210.8 | 513967.3 | 101492 | 1.64041666667 | 9556 |
| 009740 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:41pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597208.0 | 513965.0 | 101494 | 1.64041666667 | 9740 |
| 009836 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:42pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597204.7 | 513962.6 | 101496 | 1.64041666667 | 9836 |
| 010243 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:43pm | Sensor | 1797-S0058-G-636-DTE | 6860.7 | 1597201.4 | 513961.0 | 101498 | 1.64041666667 | 10243 |
| 009714 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:44pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597197.2 | 513959.4 | 101500 | 1.64041666667 | 9714 |
| 009829 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:45pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597193.7 | 513958.4 | 101502 | 1.64041666667 | 9829 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 010066 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:46pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597189.9 | 513957.3 | 101504 | 1.64041666667 | 10066 |
| 010455 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:47pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597186.5 | 513955.5 | 101506 | 1.64041666667 | 10455 |
| 010523 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:48pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597182.2 | 513953.1 | 101508 | 1.64041666667 | 10523 |
| 010606 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:49pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597178.8 | 513952.0 | 101510 | 1.64041666667 | 10606 |
| 010128 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:50pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597174.7 | 513950.4 | 101512 | 1.64041666667 | 10128 |
| 010476 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597171.1 | 513948.4 | 101514 | 1.64041666667 | 10476 |
| 009351 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:52pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597167.0 | 513945.5 | 101516 | 1.64041666667 | 9351 |
| 010555 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597163.4 | 513944.0 | 101518 | 1.64041666667 | 10555 |
| 010474 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:54pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597158.8 | 513943.1 | 101520 | 1.64041666667 | 10474 |
| 009814 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:55pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597155.1 | 513942.2 | 101522 | 1.64041666667 | 9814 |
| 009353 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:56pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597151.2 | 513940.6 | 101524 | 1.64041666667 | 9353 |
| 009513 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:57pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597147.4 | 513939.2 | 101526 | 1.64041666667 | 9513 |
| 010143 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:58pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597143.4 | 513938.2 | 101528 | 1.64041666667 | 10143 |
| 010851 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:59pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597140.3 | 513937.0 | 101530 | 1.64041666667 | 10851 |
| 010956 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597136.6 | 513935.3 | 101532 | 1.64041666667 | 10956 |
| 010572 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597133.5 | 513934.6 | 101534 | 1.64041666667 | 10572 |
| 011362 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597129.6 | 513933.7 | 101536 | 1.64041666667 | 11362 |
| 012091 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597126.2 | 513932.7 | 101538 | 1.64041666667 | 12091 |
| 012073 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597122.8 | 513930.9 | 101540 | 1.64041666667 | 12073 |
| 012739 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597120.3 | 513928.9 | 101542 | 1.64041666667 | 12739 |
| 012633 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597117.4 | 513927.1 | 101544 | 1.64041666667 | 12633 |
| 014275 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597114.7 | 513926.2 | 101546 | 1.64041666667 | 14275 |
| 019916 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597111.6 | 513924.4 | 101548 | 1.64041666667 | 19916 |
| 022617 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597109.0 | 513923.8 | 101550 | 1.64041666667 | 22617 |
| 026425 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597106.0 | 513924.0 | 101552 | 1.64041666667 | 26425 |
| 033171 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:11pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597103.9 | 513925.6 | 101554 | 1.64041666667 | 33171 |
| 044256 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597103.7 | 513928.1 | 101556 | 1.64041666667 | 44256 |
| 053394 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597103.1 | 513930.3 | 101558 | 1.64041666667 | 53394 |
| 064211 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597102.9 | 513931.3 | 101560 | 1.64041666667 | 64211 |
| 070986 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597103.1 | 513931.5 | 101562 | 1.64041666667 | 70986 |
| 074250 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597103.1 | 513931.5 | 101564 | 1.64041666667 | 74250 |
| 076610 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597103.4 | 513932.4 | 101566 | 1.64041666667 | 76610 |
| 074301 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597102.6 | 513934.9 | 101568 | 1.64041666667 | 74301 |
| 069529 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597101.5 | 513937.5 | 101570 | 1.64041666667 | 69529 |
| 068465 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597100.1 | 513940.3 | 101572 | 1.64041666667 | 68465 |
| 060974 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597098.8 | 513941.7 | 101574 | 1.64041666667 | 60974 |
| 060653 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:22pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597098.4 | 513941.9 | 101576 | 1.64041666667 | 60653 |
| 055972 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:23pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597098.7 | 513942.0 | 101578 | 1.64041666667 | 55972 |
| 053879 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:24pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597099.9 | 513942.1 | 101580 | 1.64041666667 | 53879 |
| 049282 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597100.9 | 513941.5 | 101582 | 1.64041666667 | 49282 |
| 047528 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597102.0 | 513939.7 | 101584 | 1.64041666667 | 47528 |
| 051154 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597102.3 | 513937.8 | 101586 | 1.64041666667 | 51154 |
| 053869 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597103.4 | 513936.0 | 101588 | 1.64041666667 | 53869 |
| 055359 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597104.6 | 513934.6 | 101590 | 1.64041666667 | 55359 |
| 058267 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:30pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597106.8 | 513935.1 | 101592 | 1.64041666667 | 58267 |
| 050587 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:31pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597109.9 | 513936.3 | 101594 | 1.64041666667 | 50587 |
| 039383 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597113.5 | 513937.0 | 101596 | 1.64041666667 | 39383 |
| 027973 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597116.3 | 513937.7 | 101598 | 1.64041666667 | 27973 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 021877 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597120.0 | 513938.5 | 101600 | 1.64041666667 | 21877 |
| 017031 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597123.2 | 513939.2 | 101602 | 1.64041666667 | 17031 |
| 015032 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:36pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597127.3 | 513940.2 | 101604 | 1.64041666667 | 15032 |
| 012910 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:37pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597130.5 | 513941.8 | 101606 | 1.64041666667 | 12910 |
| 012534 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:38pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597134.3 | 513944.2 | 101608 | 1.64041666667 | 12534 |
| 011160 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:39pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597136.9 | 513946.2 | 101610 | 1.64041666667 | 11160 |
| 012075 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:40pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597139.7 | 513948.2 | 101612 | 1.64041666667 | 12075 |
| 011209 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:41pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597142.2 | 513950.2 | 101614 | 1.64041666667 | 11209 |
| 011803 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:42pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597145.4 | 513953.2 | 101616 | 1.64041666667 | 11803 |
| 011686 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:43pm | Sensor | 1797-S0058-G-636-DTE | 6860.8 | 1597147.9 | 513955.8 | 101618 | 1.64041666667 | 11686 |
| 012401 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:44pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597151.2 | 513958.7 | 101620 | 1.64041666667 | 12401 |
| 011843 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:45pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597154.2 | 513960.4 | 101622 | 1.64041666667 | 11843 |
| 011776 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:46pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597157.9 | 513962.4 | 101624 | 1.64041666667 | 11776 |
| 011469 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:47pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597161.0 | 513964.7 | 101626 | 1.64041666667 | 11469 |
| 010741 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:48pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597164.1 | 513967.0 | 101628 | 1.64041666667 | 10741 |
| 010902 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:49pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597167.5 | 513967.9 | 101630 | 1.64041666667 | 10902 |
| 010460 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:50pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597171.3 | 513967.3 | 101632 | 1.64041666667 | 10460 |
| 010496 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597174.6 | 513967.2 | 101634 | 1.64041666667 | 10496 |
| 010059 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:52pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597178.5 | 513968.0 | 101636 | 1.64041666667 | 10059 |
| 010045 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597182.2 | 513969.0 | 101638 | 1.64041666667 | 10045 |
| 010285 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:54pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597186.0 | 513970.5 | 101640 | 1.64041666667 | 10285 |
| 010968 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:55pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597189.2 | 513972.7 | 101642 | 1.64041666667 | 10968 |
| 010654 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:56pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597192.1 | 513976.0 | 101644 | 1.64041666667 | 10654 |
| 010208 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:57pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597194.7 | 513978.7 | 101646 | 1.64041666667 | 10208 |
| 010339 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:58pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597198.0 | 513981.7 | 101648 | 1.64041666667 | 10339 |
| 010616 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:59pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597200.8 | 513984.0 | 101650 | 1.64041666667 | 10616 |
| 009991 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597204.2 | 513986.2 | 101652 | 1.64041666667 | 9991 |
| 011432 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597206.7 | 513988.0 | 101654 | 1.64041666667 | 11432 |
| 010736 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597209.2 | 513990.5 | 101656 | 1.64041666667 | 10736 |
| 010861 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597210.5 | 513992.9 | 101658 | 1.64041666667 | 10861 |
| 010212 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597210.0 | 513995.8 | 101660 | 1.64041666667 | 10212 |
| 010319 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597207.8 | 513997.7 | 101662 | 1.64041666667 | 10319 |
| 009719 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:06pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597203.9 | 513998.6 | 101664 | 1.64041666667 | 9719 |
| 009427 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597200.7 | 513998.2 | 101666 | 1.64041666667 | 9427 |
| 010087 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:08pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597197.1 | 513996.4 | 101668 | 1.64041666667 | 10087 |
| 010174 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597194.5 | 513994.3 | 101670 | 1.64041666667 | 10174 |
| 009855 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597191.4 | 513991.5 | 101672 | 1.64041666667 | 9855 |
| 010598 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:11pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597188.4 | 513989.4 | 101674 | 1.64041666667 | 10598 |
| 010417 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:12pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597184.3 | 513987.8 | 101676 | 1.64041666667 | 10417 |
| 010292 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:13pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597180.6 | 513987.2 | 101678 | 1.64041666667 | 10292 |
| 010446 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:14pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597176.1 | 513986.2 | 101680 | 1.64041666667 | 10446 |
| 010256 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:15pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597172.9 | 513985.2 | 101682 | 1.64041666667 | 10256 |
| 009909 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:16pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597168.8 | 513983.8 | 101684 | 1.64041666667 | 9909 |
| 010201 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597165.6 | 513982.5 | 101686 | 1.64041666667 | 10201 |
| 011235 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597161.7 | 513980.4 | 101688 | 1.64041666667 | 11235 |
| 010797 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597159.3 | 513978.9 | 101690 | 1.64041666667 | 10797 |
| 010716 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597156.1 | 513976.7 | 101692 | 1.64041666667 | 10716 |
| 010595 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:21pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597153.3 | 513975.5 | 101694 | 1.64041666667 | 10595 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 010654 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597149.3 | 513974.1 | 101696 | 1.64041666667 | 10654 |
| 010560 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597146.2 | 513972.4 | 101698 | 1.64041666667 | 10560 |
| 010913 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:24pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597142.3 | 513970.8 | 101700 | 1.64041666667 | 10913 |
| 011126 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:25pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597138.4 | 513970.0 | 101702 | 1.64041666667 | 11126 |
| 010518 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:26pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597134.6 | 513969.0 | 101704 | 1.64041666667 | 10518 |
| 011061 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:27pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597131.5 | 513967.7 | 101706 | 1.64041666667 | 11061 |
| 011419 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:28pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597127.8 | 513965.7 | 101708 | 1.64041666667 | 11419 |
| 012213 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597124.8 | 513964.1 | 101710 | 1.64041666667 | 12213 |
| 013050 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597122.0 | 513962.4 | 101712 | 1.64041666667 | 13050 |
| 013850 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:31pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597119.3 | 513961.0 | 101714 | 1.64041666667 | 13850 |
| 013873 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597116.3 | 513958.5 | 101716 | 1.64041666667 | 13873 |
| 013233 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597113.7 | 513956.2 | 101718 | 1.64041666667 | 13233 |
| 013451 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:34pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597110.0 | 513954.1 | 101720 | 1.64041666667 | 13451 |
| 013086 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:35pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597107.7 | 513952.8 | 101722 | 1.64041666667 | 13086 |
| 014553 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:36pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597106.2 | 513951.7 | 101724 | 1.64041666667 | 14553 |
| 016061 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:37pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597106.1 | 513951.5 | 101726 | 1.64041666667 | 16061 |
| 016827 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:38pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597105.1 | 513951.5 | 101728 | 1.64041666667 | 16827 |
| 016087 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:39pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597103.4 | 513950.4 | 101730 | 1.64041666667 | 16087 |
| 019294 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:40pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597100.0 | 513947.9 | 101732 | 1.64041666667 | 19294 |
| 030188 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:41pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597097.3 | 513946.6 | 101734 | 1.64041666667 | 30188 |
| 043043 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:42pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597094.6 | 513945.1 | 101736 | 1.64041666667 | 43043 |
| 054872 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:43pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597092.4 | 513944.1 | 101738 | 1.64041666667 | 54872 |
| 060378 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:44pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597089.8 | 513942.6 | 101740 | 1.64041666667 | 60378 |
| 063040 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:45pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597087.6 | 513940.5 | 101742 | 1.64041666667 | 63040 |
| 056835 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:46pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597084.5 | 513937.7 | 101744 | 1.64041666667 | 56835 |
| 044307 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:47pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597081.3 | 513935.7 | 101746 | 1.64041666667 | 44307 |
| 036375 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:48pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597078.2 | 513933.6 | 101748 | 1.64041666667 | 36375 |
| 028403 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:49pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597075.1 | 513931.7 | 101750 | 1.64041666667 | 28403 |
| 021857 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:50pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597071.6 | 513931.2 | 101752 | 1.64041666667 | 21857 |
| 019194 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:51pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597070.1 | 513933.4 | 101754 | 1.64041666667 | 19194 |
| 017112 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:52pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597069.6 | 513937.0 | 101756 | 1.64041666667 | 17112 |
| 015873 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:53pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597068.9 | 513940.3 | 101758 | 1.64041666667 | 15873 |
| 014366 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:54pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597068.5 | 513944.3 | 101760 | 1.64041666667 | 14366 |
| 014111 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597068.8 | 513947.9 | 101762 | 1.64041666667 | 14111 |
| 013810 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:56pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597068.5 | 513951.8 | 101764 | 1.64041666667 | 13810 |
| 014128 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:57pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597069.1 | 513954.9 | 101766 | 1.64041666667 | 14128 |
| 015124 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:58pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597071.1 | 513957.8 | 101768 | 1.64041666667 | 15124 |
| 015287 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:59pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597073.9 | 513959.7 | 101770 | 1.64041666667 | 15287 |
| 014464 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:00pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597077.8 | 513961.0 | 101772 | 1.64041666667 | 14464 |
| 012928 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:01pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597080.6 | 513960.8 | 101774 | 1.64041666667 | 12928 |
| 011967 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:02pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597083.7 | 513960.3 | 101776 | 1.64041666667 | 11967 |
| 011996 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:03pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597086.7 | 513960.2 | 101778 | 1.64041666667 | 11996 |
| 012530 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:04pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597090.2 | 513959.6 | 101780 | 1.64041666667 | 12530 |
| 013281 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:05pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597093.3 | 513959.0 | 101782 | 1.64041666667 | 13281 |
| 012263 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:06pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597097.3 | 513958.6 | 101784 | 1.64041666667 | 12263 |
| 012238 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:07pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597100.4 | 513957.3 | 101786 | 1.64041666667 | 12238 |
| 012726 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:08pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597103.5 | 513954.6 | 101788 | 1.64041666667 | 12726 |
| 013023 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:09pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597106.2 | 513952.6 | 101790 | 1.64041666667 | 13023 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 013063 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:10pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597109.5 | 513949.9 | 101792 | 1.64041666667 | 13063 |
| 013288 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597111.4 | 513946.8 | 101794 | 1.64041666667 | 13288 |
| 013107 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597113.5 | 513943.0 | 101796 | 1.64041666667 | 13107 |
| 014010 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597115.4 | 513940.4 | 101798 | 1.64041666667 | 14010 |
| 013940 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597116.8 | 513936.8 | 101800 | 1.64041666667 | 13940 |
| 015514 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597117.8 | 513933.6 | 101802 | 1.64041666667 | 15514 |
| 014621 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:16pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597119.0 | 513929.7 | 101804 | 1.64041666667 | 14621 |
| 013489 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:17pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597119.1 | 513926.5 | 101806 | 1.64041666667 | 13489 |
| 012395 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:18pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597118.8 | 513922.1 | 101808 | 1.64041666667 | 12395 |
| 011772 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:19pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597118.4 | 513918.7 | 101810 | 1.64041666667 | 11772 |
| 011992 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:20pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597116.8 | 513914.5 | 101812 | 1.64041666667 | 11992 |
| 011065 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:21pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597114.7 | 513911.7 | 101814 | 1.64041666667 | 11065 |
| 010867 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597111.3 | 513908.4 | 101816 | 1.64041666667 | 10867 |
| 010080 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597108.8 | 513906.6 | 101818 | 1.64041666667 | 10080 |
| 011047 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:24pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597105.0 | 513905.8 | 101820 | 1.64041666667 | 11047 |
| 010999 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:25pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597101.7 | 513906.1 | 101822 | 1.64041666667 | 10999 |
| 011354 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:26pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597098.5 | 513906.5 | 101824 | 1.64041666667 | 11354 |
| 011817 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:27pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597096.1 | 513905.9 | 101826 | 1.64041666667 | 11817 |
| 011619 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:28pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597093.0 | 513903.7 | 101828 | 1.64041666667 | 11619 |
| 011336 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:29pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597091.2 | 513902.3 | 101830 | 1.64041666667 | 11336 |
| 011851 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597090.3 | 513902.4 | 101832 | 1.64041666667 | 11851 |
| 012089 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597090.8 | 513904.0 | 101834 | 1.64041666667 | 12089 |
| 011997 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:32pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597090.4 | 513907.0 | 101836 | 1.64041666667 | 11997 |
| 012823 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:33pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597089.0 | 513909.8 | 101838 | 1.64041666667 | 12823 |
| 012748 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:34pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597087.1 | 513913.2 | 101840 | 1.64041666667 | 12748 |
| 012841 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:35pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597085.1 | 513915.8 | 101842 | 1.64041666667 | 12841 |
| 012458 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:36pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597082.5 | 513917.9 | 101844 | 1.64041666667 | 12458 |
| 013187 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:37pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597080.4 | 513919.3 | 101846 | 1.64041666667 | 13187 |
| 013088 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:38pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597077.5 | 513919.4 | 101848 | 1.64041666667 | 13088 |
| 013692 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:39pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597075.0 | 513918.6 | 101850 | 1.64041666667 | 13692 |
| 016484 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:40pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597072.4 | 513919.0 | 101852 | 1.64041666667 | 16484 |
| 017590 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:41pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597070.2 | 513920.0 | 101854 | 1.64041666667 | 17590 |
| 015594 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:42pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597067.8 | 513922.0 | 101856 | 1.64041666667 | 15594 |
| 014126 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:43pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597066.0 | 513924.1 | 101858 | 1.64041666667 | 14126 |
| 012881 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:44pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597063.3 | 513926.1 | 101860 | 1.64041666667 | 12881 |
| 011933 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:45pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597060.9 | 513927.5 | 101862 | 1.64041666667 | 11933 |
| 012052 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:46pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597057.8 | 513929.2 | 101864 | 1.64041666667 | 12052 |
| 015974 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:47pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597055.6 | 513931.3 | 101866 | 1.64041666667 | 15974 |
| 015128 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597054.9 | 513933.3 | 101868 | 1.64041666667 | 15128 |
| 014277 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:49pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597055.2 | 513935.1 | 101870 | 1.64041666667 | 14277 |
| 013528 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:50pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597056.1 | 513938.2 | 101872 | 1.64041666667 | 13528 |
| 013107 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:51pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597057.9 | 513940.1 | 101874 | 1.64041666667 | 13107 |
| 012975 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:52pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597061.3 | 513940.9 | 101876 | 1.64041666667 | 12975 |
| 011746 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:53pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597064.1 | 513940.5 | 101878 | 1.64041666667 | 11746 |
| 012697 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:54pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597067.0 | 513938.7 | 101880 | 1.64041666667 | 12697 |
| 013112 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597069.4 | 513936.2 | 101882 | 1.64041666667 | 13112 |
| 014073 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597072.5 | 513932.7 | 101884 | 1.64041666667 | 14073 |
| 014876 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597075.0 | 513930.4 | 101886 | 1.64041666667 | 14876 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 015740 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597078.1 | 513927.5 | 101888 | 1.64041666667 | 15740 |
| 016533 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597080.6 | 513925.0 | 101890 | 1.64041666667 | 16533 |
| 016125 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597084.2 | 513922.0 | 101892 | 1.64041666667 | 16125 |
| 016953 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:01pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597087.8 | 513920.1 | 101894 | 1.64041666667 | 16953 |
| 017298 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597091.3 | 513917.6 | 101896 | 1.64041666667 | 17298 |
| 015573 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597094.2 | 513915.0 | 101898 | 1.64041666667 | 15573 |
| 015089 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597097.9 | 513912.2 | 101900 | 1.64041666667 | 15089 |
| 013610 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597101.0 | 513910.0 | 101902 | 1.64041666667 | 13610 |
| 013145 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597104.5 | 513907.3 | 101904 | 1.64041666667 | 13145 |
| 012367 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597107.2 | 513905.6 | 101906 | 1.64041666667 | 12367 |
| 012784 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.1 | 1597109.9 | 513905.6 | 101908 | 1.64041666667 | 12784 |
| 011256 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597109.9 | 513907.2 | 101910 | 1.64041666667 | 11256 |
| 011784 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597107.4 | 513909.9 | 101912 | 1.64041666667 | 11784 |
| 012156 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:11pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597104.1 | 513911.9 | 101914 | 1.64041666667 | 12156 |
| 013077 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:12pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597100.5 | 513914.6 | 101916 | 1.64041666667 | 13077 |
| 014488 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:13pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597097.5 | 513917.1 | 101918 | 1.64041666667 | 14488 |
| 015455 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597094.1 | 513919.2 | 101920 | 1.64041666667 | 15455 |
| 017355 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597091.4 | 513921.2 | 101922 | 1.64041666667 | 17355 |
| 024380 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597088.6 | 513923.9 | 101924 | 1.64041666667 | 24380 |
| 026336 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597086.1 | 513925.6 | 101926 | 1.64041666667 | 26336 |
| 024556 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597082.9 | 513928.0 | 101928 | 1.64041666667 | 24556 |
| 022527 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597079.9 | 513929.7 | 101930 | 1.64041666667 | 22527 |
| 019915 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597076.7 | 513931.6 | 101932 | 1.64041666667 | 19915 |
| 019850 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597074.1 | 513934.0 | 101934 | 1.64041666667 | 19850 |
| 018058 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:22pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597070.8 | 513936.8 | 101936 | 1.64041666667 | 18058 |
| 016120 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:23pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597068.3 | 513938.9 | 101938 | 1.64041666667 | 16120 |
| 014407 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:24pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597067.1 | 513941.8 | 101940 | 1.64041666667 | 14407 |
| 014089 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597067.9 | 513944.1 | 101942 | 1.64041666667 | 14089 |
| 013632 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597070.8 | 513944.1 | 101944 | 1.64041666667 | 13632 |
| 016136 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597073.5 | 513942.6 | 101946 | 1.64041666667 | 16136 |
| 025261 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597076.5 | 513939.8 | 101948 | 1.64041666667 | 25261 |
| 035937 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597078.5 | 513937.6 | 101950 | 1.64041666667 | 35937 |
| 035169 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:30pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597077.7 | 513936.7 | 101952 | 1.64041666667 | 35169 |
| 036785 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:31pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597076.7 | 513936.9 | 101954 | 1.64041666667 | 36785 |
| 037251 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597076.6 | 513937.5 | 101956 | 1.64041666667 | 37251 |
| 043469 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597077.0 | 513937.4 | 101958 | 1.64041666667 | 43469 |
| 049591 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:34pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597078.1 | 513937.3 | 101960 | 1.64041666667 | 49591 |
| 047402 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:35pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597079.8 | 513936.7 | 101962 | 1.64041666667 | 47402 |
| 037561 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:36pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597081.9 | 513934.5 | 101964 | 1.64041666667 | 37561 |
| 035385 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:37pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597083.9 | 513932.8 | 101966 | 1.64041666667 | 35385 |
| 042217 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:38pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597086.7 | 513930.6 | 101968 | 1.64041666667 | 42217 |
| 042512 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:39pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597088.3 | 513928.2 | 101970 | 1.64041666667 | 42512 |
| 044403 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:40pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597090.5 | 513925.9 | 101972 | 1.64041666667 | 44403 |
| 039684 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:41pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597091.7 | 513923.9 | 101974 | 1.64041666667 | 39684 |
| 033272 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:42pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597094.1 | 513921.6 | 101976 | 1.64041666667 | 33272 |
| 027580 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:43pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597096.4 | 513919.5 | 101978 | 1.64041666667 | 27580 |
| 022849 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:44pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597098.8 | 513916.5 | 101980 | 1.64041666667 | 22849 |
| 019077 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:45pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597101.1 | 513914.4 | 101982 | 1.64041666667 | 19077 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 016896 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:46pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597103.8 | 513912.2 | 101984 | 1.64041666667 | 16896 |
| 013884 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:47pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597106.0 | 513909.9 | 101986 | 1.64041666667 | 13884 |
| 012714 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:48pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597108.8 | 513908.3 | 101988 | 1.64041666667 | 12714 |
| 012297 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:49pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597111.3 | 513907.7 | 101990 | 1.64041666667 | 12297 |
| 012009 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:50pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597113.4 | 513908.2 | 101992 | 1.64041666667 | 12009 |
| 011653 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:51pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597113.7 | 513909.9 | 101994 | 1.64041666667 | 11653 |
| 011354 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:52pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597111.4 | 513912.5 | 101996 | 1.64041666667 | 11354 |
| 012454 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597109.3 | 513914.7 | 101998 | 1.64041666667 | 12454 |
| 014325 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:54pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597106.1 | 513917.6 | 102000 | 1.64041666667 | 14325 |
| 014770 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:55pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597103.3 | 513919.8 | 102002 | 1.64041666667 | 14770 |
| 020931 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597100.7 | 513922.7 | 102004 | 1.64041666667 | 20931 |
| 030801 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597097.9 | 513924.8 | 102006 | 1.64041666667 | 30801 |
| 035505 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597094.7 | 513926.9 | 102008 | 1.64041666667 | 35505 |
| 047122 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597092.6 | 513929.0 | 102010 | 1.64041666667 | 47122 |
| 051406 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:00pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597089.8 | 513931.6 | 102012 | 1.64041666667 | 51406 |
| 052601 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:01pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597087.0 | 513933.8 | 102014 | 1.64041666667 | 52601 |
| 047265 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:02pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597084.1 | 513936.8 | 102016 | 1.64041666667 | 47265 |
| 045487 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:03pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597081.6 | 513939.0 | 102018 | 1.64041666667 | 45487 |
| 043788 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:04pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597078.1 | 513941.7 | 102020 | 1.64041666667 | 43788 |
| 034508 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:05pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597075.7 | 513943.6 | 102022 | 1.64041666667 | 34508 |
| 026626 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:06pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597072.2 | 513945.9 | 102024 | 1.64041666667 | 26626 |
| 021217 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:07pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597069.8 | 513947.6 | 102026 | 1.64041666667 | 21217 |
| 017132 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:08pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597068.4 | 513950.3 | 102028 | 1.64041666667 | 17132 |
| 015337 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:09pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597069.3 | 513952.6 | 102030 | 1.64041666667 | 15337 |
| 019622 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:10pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597072.6 | 513952.9 | 102032 | 1.64041666667 | 19622 |
| 024619 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597075.3 | 513950.9 | 102034 | 1.64041666667 | 24619 |
| 024768 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597078.2 | 513947.9 | 102036 | 1.64041666667 | 24768 |
| 026517 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597081.0 | 513945.3 | 102038 | 1.64041666667 | 26517 |
| 033733 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597083.6 | 513942.2 | 102040 | 1.64041666667 | 33733 |
| 042412 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597085.6 | 513938.8 | 102042 | 1.64041666667 | 42412 |
| 051787 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597088.4 | 513935.9 | 102044 | 1.64041666667 | 51787 |
| 059865 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597089.7 | 513933.3 | 102046 | 1.64041666667 | 59865 |
| 057269 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597091.6 | 513930.2 | 102048 | 1.64041666667 | 57269 |
| 057256 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597093.9 | 513927.9 | 102050 | 1.64041666667 | 57256 |
| 048601 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597095.8 | 513925.5 | 102052 | 1.64041666667 | 48601 |
| 038881 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597097.6 | 513922.9 | 102054 | 1.64041666667 | 38881 |
| 031650 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:22pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597100.6 | 513919.6 | 102056 | 1.64041666667 | 31650 |
| 025401 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:23pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597102.9 | 513916.9 | 102058 | 1.64041666667 | 25401 |
| 020093 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:24pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597105.4 | 513914.1 | 102060 | 1.64041666667 | 20093 |
| 016582 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:25pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597108.1 | 513912.0 | 102062 | 1.64041666667 | 16582 |
| 013805 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:26pm | Sensor | 1797-S0058-G-636-DTE | 6861.3 | 1597110.9 | 513909.8 | 102064 | 1.64041666667 | 13805 |
| 013165 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:27pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597113.0 | 513909.2 | 102066 | 1.64041666667 | 13165 |
| 012033 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:28pm | Sensor | 1797-S0058-G-636-DTE | 6861.2 | 1597114.3 | 513910.8 | 102068 | 1.64041666667 | 12033 |
| 011658 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:29pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597113.9 | 513913.1 | 102070 | 1.64041666667 | 11658 |
| 012048 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:30pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597111.7 | 513915.7 | 102072 | 1.64041666667 | 12048 |
| 013339 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:31pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597109.3 | 513917.6 | 102074 | 1.64041666667 | 13339 |
| 015356 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597106.8 | 513920.6 | 102076 | 1.64041666667 | 15356 |
| 020915 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597104.5 | 513923.1 | 102078 | 1.64041666667 | 20915 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 031137 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:34pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597101.7 | 513926.3 | 102080 | 1.64041666667 | 31137 |
| 047627 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:35pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597100.2 | 513928.9 | 102082 | 1.64041666667 | 47627 |
| 058245 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:36pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597097.8 | 513932.1 | 102084 | 1.64041666667 | 58245 |
| 067225 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:37pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597095.5 | 513934.7 | 102086 | 1.64041666667 | 67225 |
| 069224 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:38pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597093.5 | 513937.9 | 102088 | 1.64041666667 | 69224 |
| 067888 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:39pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597091.5 | 513940.9 | 102090 | 1.64041666667 | 67888 |
| 066529 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:40pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597089.5 | 513944.1 | 102092 | 1.64041666667 | 66529 |
| 065458 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:41pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597087.9 | 513947.2 | 102094 | 1.64041666667 | 65458 |
| 051895 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:42pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597085.6 | 513950.5 | 102096 | 1.64041666667 | 51895 |
| 040576 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:43pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597083.5 | 513953.2 | 102098 | 1.64041666667 | 40576 |
| 033114 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:44pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597081.7 | 513956.4 | 102100 | 1.64041666667 | 33114 |
| 026344 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:45pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597080.3 | 513959.4 | 102102 | 1.64041666667 | 26344 |
| 019783 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:46pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597081.5 | 513962.0 | 102104 | 1.64041666667 | 19783 |
| 016460 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:47pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597084.0 | 513962.2 | 102106 | 1.64041666667 | 16460 |
| 014441 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597086.7 | 513960.7 | 102108 | 1.64041666667 | 14441 |
| 015075 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:49pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597089.3 | 513958.2 | 102110 | 1.64041666667 | 15075 |
| 016700 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:50pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597091.0 | 513955.0 | 102112 | 1.64041666667 | 16700 |
| 022781 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:51pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597092.4 | 513951.9 | 102114 | 1.64041666667 | 22781 |
| 030679 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:52pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597094.5 | 513949.2 | 102116 | 1.64041666667 | 30679 |
| 037905 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:53pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597096.5 | 513946.6 | 102118 | 1.64041666667 | 37905 |
| 046559 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:54pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597098.6 | 513944.2 | 102120 | 1.64041666667 | 46559 |
| 048899 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597100.8 | 513941.7 | 102122 | 1.64041666667 | 48899 |
| 052953 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597102.4 | 513938.7 | 102124 | 1.64041666667 | 52953 |
| 054843 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597104.2 | 513936.2 | 102126 | 1.64041666667 | 54843 |
| 058434 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597106.5 | 513933.2 | 102128 | 1.64041666667 | 58434 |
| 055632 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597108.0 | 513930.5 | 102130 | 1.64041666667 | 55632 |
| 052000 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:00pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597110.5 | 513927.7 | 102132 | 1.64041666667 | 52000 |
| 039682 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:01pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597112.9 | 513925.1 | 102134 | 1.64041666667 | 39682 |
| 028224 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:02pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597115.0 | 513921.9 | 102136 | 1.64041666667 | 28224 |
| 021493 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:03pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597117.1 | 513919.6 | 102138 | 1.64041666667 | 21493 |
| 016620 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:04pm | Sensor | 1797-S0058-G-636-DTE | 6861.4 | 1597119.4 | 513918.1 | 102140 | 1.64041666667 | 16620 |
| 014261 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597121.4 | 513918.7 | 102142 | 1.64041666667 | 14261 |
| 012942 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:06pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597123.1 | 513921.6 | 102144 | 1.64041666667 | 12942 |
| 012627 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:07pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597123.6 | 513924.3 | 102146 | 1.64041666667 | 12627 |
| 012862 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:08pm | Sensor | 1797-S0058-G-636-DTE | 6861.8 | 1597122.9 | 513927.6 | 102148 | 1.64041666667 | 12862 |
| 012192 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:09pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597120.9 | 513929.8 | 102150 | 1.64041666667 | 12192 |
| 013766 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:10pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597118.0 | 513931.9 | 102152 | 1.64041666667 | 13766 |
| 019488 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597115.4 | 513934.2 | 102154 | 1.64041666667 | 19488 |
| 024349 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597112.2 | 513937.0 | 102156 | 1.64041666667 | 24349 |
| 027616 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597109.7 | 513939.4 | 102158 | 1.64041666667 | 27616 |
| 023056 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597107.3 | 513942.2 | 102160 | 1.64041666667 | 23056 |
| 023507 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597105.1 | 513944.6 | 102162 | 1.64041666667 | 23507 |
| 026235 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597102.9 | 513947.3 | 102164 | 1.64041666667 | 26235 |
| 023382 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597101.1 | 513949.6 | 102166 | 1.64041666667 | 23382 |
| 022010 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597099.0 | 513952.5 | 102168 | 1.64041666667 | 22010 |
| 018793 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597098.1 | 513955.3 | 102170 | 1.64041666667 | 18793 |
| 017246 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:20pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597096.9 | 513957.8 | 102172 | 1.64041666667 | 17246 |
| 015543 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:21pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597096.2 | 513959.9 | 102174 | 1.64041666667 | 15543 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 014930 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:22pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597096.0 | 513962.8 | 102176 | 1.64041666667 | 14930 |
| 013521 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:23pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597095.9 | 513965.4 | 102178 | 1.64041666667 | 13521 |
| 013073 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:24pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597096.6 | 513968.0 | 102180 | 1.64041666667 | 13073 |
| 012858 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:25pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597098.2 | 513970.0 | 102182 | 1.64041666667 | 12858 |
| 012963 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597101.3 | 513971.6 | 102184 | 1.64041666667 | 12963 |
| 012594 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597103.9 | 513973.0 | 102186 | 1.64041666667 | 12594 |
| 013024 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597107.4 | 513974.4 | 102188 | 1.64041666667 | 13024 |
| 014458 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597110.9 | 513974.8 | 102190 | 1.64041666667 | 14458 |
| 016848 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:30pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597114.1 | 513975.7 | 102192 | 1.64041666667 | 16848 |
| 016354 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:31pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597115.4 | 513976.5 | 102194 | 1.64041666667 | 16354 |
| 017314 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597115.1 | 513976.7 | 102196 | 1.64041666667 | 17314 |
| 019871 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597114.7 | 513977.2 | 102198 | 1.64041666667 | 19871 |
| 022075 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:34pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597114.8 | 513977.9 | 102200 | 1.64041666667 | 22075 |
| 021147 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:35pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597114.4 | 513978.5 | 102202 | 1.64041666667 | 21147 |
| 024465 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:36pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597114.5 | 513979.0 | 102204 | 1.64041666667 | 24465 |
| 022559 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:37pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597116.7 | 513979.6 | 102206 | 1.64041666667 | 22559 |
| 020302 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:38pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597120.3 | 513980.0 | 102208 | 1.64041666667 | 20302 |
| 025692 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:39pm | Sensor | 1797-S0058-G-636-DTE | 6861.6 | 1597123.6 | 513981.3 | 102210 | 1.64041666667 | 25692 |
| 029399 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:40pm | Sensor | 1797-S0058-G-636-DTE | 6861.5 | 1597127.1 | 513983.4 | 102212 | 1.64041666667 | 29399 |
| 027314 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:41pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597130.2 | 513984.6 | 102214 | 1.64041666667 | 27314 |
| 021469 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:42pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597133.8 | 513985.8 | 102216 | 1.64041666667 | 21469 |
| 017791 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:43pm | Sensor | 1797-S0058-G-636-DTE | 6861.7 | 1597136.9 | 513986.9 | 102218 | 1.64041666667 | 17791 |
| 016270 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:44pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597140.4 | 513987.5 | 102220 | 1.64041666667 | 16270 |
| 014507 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:45pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597144.0 | 513987.9 | 102222 | 1.64041666667 | 14507 |
| 013762 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:46pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597147.7 | 513989.4 | 102224 | 1.64041666667 | 13762 |
| 013816 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:47pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597150.0 | 513991.4 | 102226 | 1.64041666667 | 13816 |
| 014266 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:48pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597153.2 | 513993.7 | 102228 | 1.64041666667 | 14266 |
| 013342 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:49pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597156.4 | 513995.0 | 102230 | 1.64041666667 | 13342 |
| 013040 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:50pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597160.1 | 513996.0 | 102232 | 1.64041666667 | 13040 |
| 012330 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:51pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597163.1 | 513996.4 | 102234 | 1.64041666667 | 12330 |
| 012065 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:52pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597166.4 | 513996.2 | 102236 | 1.64041666667 | 12065 |
| 011789 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:53pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597168.9 | 513996.0 | 102238 | 1.64041666667 | 11789 |
| 012054 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:54pm | Sensor | 1797-S0058-G-636-DTE | 6861.9 | 1597171.7 | 513996.7 | 102240 | 1.64041666667 | 12054 |
| 011737 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597174.0 | 513997.8 | 102242 | 1.64041666667 | 11737 |
| 012092 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597176.5 | 513999.6 | 102244 | 1.64041666667 | 12092 |
| 011864 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597178.2 | 514001.6 | 102246 | 1.64041666667 | 11864 |
| 011991 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597180.0 | 514004.2 | 102248 | 1.64041666667 | 11991 |
| 015070 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597181.2 | 514007.0 | 102250 | 1.64041666667 | 15070 |
| 013599 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:00pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597183.1 | 514010.1 | 102252 | 1.64041666667 | 13599 |
| 012779 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:01pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597185.0 | 514011.4 | 102254 | 1.64041666667 | 12779 |
| 011838 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:02pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597187.3 | 514013.0 | 102256 | 1.64041666667 | 11838 |
| 011091 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:03pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597188.8 | 514015.0 | 102258 | 1.64041666667 | 11091 |
| 011406 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:04pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597190.4 | 514017.6 | 102260 | 1.64041666667 | 11406 |
| 010728 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:05pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597191.6 | 514019.7 | 102262 | 1.64041666667 | 10728 |
| 011344 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:06pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597192.9 | 514023.1 | 102264 | 1.64041666667 | 11344 |
| 010956 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:07pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597193.7 | 514026.2 | 102266 | 1.64041666667 | 10956 |
| 011690 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:08pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597193.7 | 514029.9 | 102268 | 1.64041666667 | 11690 |
| 011271 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:09pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597193.2 | 514032.9 | 102270 | 1.64041666667 | 11271 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 011717 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:10pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597193.0 | 514036.6 | 102272 | 1.64041666667 | 11717 |
| 011623 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597192.7 | 514039.1 | 102274 | 1.64041666667 | 11623 |
| 011413 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597191.0 | 514040.7 | 102276 | 1.64041666667 | 11413 |
| 011445 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597188.6 | 514041.3 | 102278 | 1.64041666667 | 11445 |
| 010352 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597184.7 | 514041.8 | 102280 | 1.64041666667 | 10352 |
| 010691 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597181.1 | 514042.3 | 102282 | 1.64041666667 | 10691 |
| 010258 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597176.5 | 514043.1 | 102284 | 1.64041666667 | 10258 |
| 011425 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597172.8 | 514043.8 | 102286 | 1.64041666667 | 11425 |
| 011504 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597168.4 | 514044.7 | 102288 | 1.64041666667 | 11504 |
| 010791 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597164.8 | 514044.9 | 102290 | 1.64041666667 | 10791 |
| 010682 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597161.2 | 514044.2 | 102292 | 1.64041666667 | 10682 |
| 010531 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597158.0 | 514043.2 | 102294 | 1.64041666667 | 10531 |
| 010446 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:22pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597153.9 | 514041.4 | 102296 | 1.64041666667 | 10446 |
| 010256 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:23pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597150.7 | 514040.1 | 102298 | 1.64041666667 | 10256 |
| 010381 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:24pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597146.4 | 514039.4 | 102300 | 1.64041666667 | 10381 |
| 010992 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597143.0 | 514039.6 | 102302 | 1.64041666667 | 10992 |
| 012138 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597138.4 | 514039.6 | 102304 | 1.64041666667 | 12138 |
| 018370 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597135.1 | 514039.4 | 102306 | 1.64041666667 | 18370 |
| 025640 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597131.7 | 514039.5 | 102308 | 1.64041666667 | 25640 |
| 028072 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597128.6 | 514039.4 | 102310 | 1.64041666667 | 28072 |
| 027183 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:30pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597124.8 | 514038.8 | 102312 | 1.64041666667 | 27183 |
| 022183 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:31pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597121.7 | 514039.0 | 102314 | 1.64041666667 | 22183 |
| 017735 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597118.6 | 514039.1 | 102316 | 1.64041666667 | 17735 |
| 015016 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597115.3 | 514038.8 | 102318 | 1.64041666667 | 15016 |
| 013659 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:34pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597111.4 | 514038.6 | 102320 | 1.64041666667 | 13659 |
| 013360 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:35pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597107.8 | 514037.9 | 102322 | 1.64041666667 | 13360 |
| 013455 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:36pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597103.9 | 514036.4 | 102324 | 1.64041666667 | 13455 |
| 014438 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:37pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597100.9 | 514035.6 | 102326 | 1.64041666667 | 14438 |
| 014721 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:38pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597096.7 | 514035.2 | 102328 | 1.64041666667 | 14721 |
| 015068 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:39pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597093.5 | 514034.7 | 102330 | 1.64041666667 | 15068 |
| 017671 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:40pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597089.7 | 514034.4 | 102332 | 1.64041666667 | 17671 |
| 016135 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:41pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597086.3 | 514034.7 | 102334 | 1.64041666667 | 16135 |
| 015285 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:42pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597083.0 | 514034.5 | 102336 | 1.64041666667 | 15285 |
| 015558 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:43pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597080.5 | 514034.3 | 102338 | 1.64041666667 | 15558 |
| 016109 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:44pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597078.0 | 514034.3 | 102340 | 1.64041666667 | 16109 |
| 017281 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:45pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597075.9 | 514033.6 | 102342 | 1.64041666667 | 17281 |
| 015600 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:46pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597072.9 | 514033.1 | 102344 | 1.64041666667 | 15600 |
| 014827 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:47pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597070.2 | 514032.6 | 102346 | 1.64041666667 | 14827 |
| 014873 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597067.3 | 514031.9 | 102348 | 1.64041666667 | 14873 |
| 015663 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:49pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597064.4 | 514031.6 | 102350 | 1.64041666667 | 15663 |
| 014450 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:50pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597061.1 | 514030.5 | 102352 | 1.64041666667 | 14450 |
| 014263 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:51pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597058.4 | 514029.8 | 102354 | 1.64041666667 | 14263 |
| 013993 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:52pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597055.1 | 514028.6 | 102356 | 1.64041666667 | 13993 |
| 014921 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:53pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597052.6 | 514027.1 | 102358 | 1.64041666667 | 14921 |
| 014603 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:54pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597049.8 | 514025.6 | 102360 | 1.64041666667 | 14603 |
| 014611 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:55pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597048.4 | 514024.0 | 102362 | 1.64041666667 | 14611 |
| 013484 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:56pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597048.8 | 514021.6 | 102364 | 1.64041666667 | 13484 |
| 013232 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:57pm | Sensor | 1797-S0058-G-636-DTE | 6863.9 | 1597050.3 | 514020.2 | 102366 | 1.64041666667 | 13232 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 013113 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:58pm | Sensor | 1797-S0058-G-636-DTE | 6863.9 | 1597053.8 | 514019.9 | 102368 | 1.64041666667 | 13113 |
| 013586 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:59pm | Sensor | 1797-S0058-G-636-DTE | 6863.8 | 1597056.9 | 514020.3 | 102370 | 1.64041666667 | 13586 |
| 013949 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:00pm | Sensor | 1797-S0058-G-636-DTE | 6863.9 | 1597061.0 | 514020.4 | 102372 | 1.64041666667 | 13949 |
| 014116 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:01pm | Sensor | 1797-S0058-G-636-DTE | 6863.9 | 1597064.5 | 514020.5 | 102374 | 1.64041666667 | 14116 |
| 014848 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:02pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597068.4 | 514021.5 | 102376 | 1.64041666667 | 14848 |
| 016009 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:03pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597071.6 | 514022.3 | 102378 | 1.64041666667 | 16009 |
| 020367 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:04pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597075.7 | 514022.4 | 102380 | 1.64041666667 | 20367 |
| 020824 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:05pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597079.1 | 514022.5 | 102382 | 1.64041666667 | 20824 |
| 029031 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:06pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597082.1 | 514023.3 | 102384 | 1.64041666667 | 29031 |
| 036400 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:07pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597083.8 | 514023.7 | 102386 | 1.64041666667 | 36400 |
| 042495 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:08pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597085.5 | 514023.7 | 102388 | 1.64041666667 | 42495 |
| 047281 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:09pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597087.2 | 514024.0 | 102390 | 1.64041666667 | 47281 |
| 049980 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:10pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597089.9 | 514024.5 | 102392 | 1.64041666667 | 49980 |
| 046039 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:11pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597092.7 | 514024.3 | 102394 | 1.64041666667 | 46039 |
| 038699 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:12pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597095.5 | 514024.4 | 102396 | 1.64041666667 | 38699 |
| 034931 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:13pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597098.1 | 514024.7 | 102398 | 1.64041666667 | 34931 |
| 032188 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:14pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597101.0 | 514024.5 | 102400 | 1.64041666667 | 32188 |
| 031733 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:15pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597103.6 | 514024.8 | 102402 | 1.64041666667 | 31733 |
| 032955 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:16pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597106.2 | 514025.0 | 102404 | 1.64041666667 | 32955 |
| 031069 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:17pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597108.5 | 514025.0 | 102406 | 1.64041666667 | 31069 |
| 036534 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:18pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597111.3 | 514025.6 | 102408 | 1.64041666667 | 36534 |
| 039120 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:19pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597112.5 | 514026.3 | 102410 | 1.64041666667 | 39120 |
| 050400 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:20pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597112.6 | 514027.1 | 102412 | 1.64041666667 | 50400 |
| 055567 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:21pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597112.8 | 514027.7 | 102414 | 1.64041666667 | 55567 |
| 056156 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:22pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.3 | 514028.9 | 102416 | 1.64041666667 | 56156 |
| 056908 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:23pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.3 | 514029.2 | 102418 | 1.64041666667 | 56908 |
| 061178 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:24pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.2 | 514028.8 | 102420 | 1.64041666667 | 61178 |
| 064075 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:25pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.3 | 514028.6 | 102422 | 1.64041666667 | 64075 |
| 066432 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:26pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.5 | 514028.7 | 102424 | 1.64041666667 | 66432 |
| 067825 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:27pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.5 | 514028.8 | 102426 | 1.64041666667 | 67825 |
| 069464 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:28pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597113.5 | 514028.8 | 102428 | 1.64041666667 | 69464 |
| 068218 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:29pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.5 | 514028.8 | 102430 | 1.64041666667 | 68218 |
| 069813 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:30pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.5 | 514028.8 | 102432 | 1.64041666667 | 69813 |
| 069322 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:31pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.6 | 514028.7 | 102434 | 1.64041666667 | 69322 |
| 067411 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:32pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.5 | 514028.7 | 102436 | 1.64041666667 | 67411 |
| 067633 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:33pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597113.4 | 514028.7 | 102438 | 1.64041666667 | 67633 |
| 067324 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:34pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.2 | 514028.8 | 102440 | 1.64041666667 | 67324 |
| 067329 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:35pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.1 | 514029.1 | 102442 | 1.64041666667 | 67329 |
| 065773 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:36pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.1 | 514029.2 | 102444 | 1.64041666667 | 65773 |
| 065137 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:37pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597112.9 | 514029.1 | 102446 | 1.64041666667 | 65137 |
| 064487 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:38pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597112.6 | 514029.0 | 102448 | 1.64041666667 | 64487 |
| 065051 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:39pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597112.7 | 514029.0 | 102450 | 1.64041666667 | 65051 |
| 064791 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:40pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.0 | 514028.9 | 102452 | 1.64041666667 | 64791 |
| 063092 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:41pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.3 | 514028.7 | 102454 | 1.64041666667 | 63092 |
| 061957 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:42pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.4 | 514028.8 | 102456 | 1.64041666667 | 61957 |
| 061978 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:43pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.4 | 514029.1 | 102458 | 1.64041666667 | 61978 |
| 063550 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:44pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.5 | 514029.2 | 102460 | 1.64041666667 | 63550 |
| 063594 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:45pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597113.8 | 514028.6 | 102462 | 1.64041666667 | 63594 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 060747 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:46pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597115.6 | 514028.6 | 102464 | 1.64041666667 | 60747 |
| 057960 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:47pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597117.8 | 514029.7 | 102466 | 1.64041666667 | 57960 |
| 046507 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597120.4 | 514031.0 | 102468 | 1.64041666667 | 46507 |
| 037785 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:49pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597122.4 | 514031.9 | 102470 | 1.64041666667 | 37785 |
| 041744 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:50pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597125.4 | 514032.8 | 102472 | 1.64041666667 | 41744 |
| 039778 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:51pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597128.2 | 514032.7 | 102474 | 1.64041666667 | 39778 |
| 039820 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:52pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597131.7 | 514033.1 | 102476 | 1.64041666667 | 39820 |
| 035021 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:53pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597134.6 | 514032.9 | 102478 | 1.64041666667 | 35021 |
| 025647 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:54pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597138.0 | 514032.3 | 102480 | 1.64041666667 | 25647 |
| 018686 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597141.1 | 514032.1 | 102482 | 1.64041666667 | 18686 |
| 015123 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597144.4 | 514031.3 | 102484 | 1.64041666667 | 15123 |
| 014552 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597147.2 | 514030.3 | 102486 | 1.64041666667 | 14552 |
| 013368 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597150.7 | 514030.2 | 102488 | 1.64041666667 | 13368 |
| 012139 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597153.3 | 514030.1 | 102490 | 1.64041666667 | 12139 |
| 012048 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:00pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597156.8 | 514030.1 | 102492 | 1.64041666667 | 12048 |
| 011892 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:01pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597159.7 | 514030.3 | 102494 | 1.64041666667 | 11892 |
| 011437 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:02pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597163.0 | 514029.7 | 102496 | 1.64041666667 | 11437 |
| 011308 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:03pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597165.7 | 514028.8 | 102498 | 1.64041666667 | 11308 |
| 010920 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:04pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597169.3 | 514028.1 | 102500 | 1.64041666667 | 10920 |
| 011130 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:05pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597171.7 | 514027.2 | 102502 | 1.64041666667 | 11130 |
| 010956 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:06pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597175.2 | 514026.4 | 102504 | 1.64041666667 | 10956 |
| 011435 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:07pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597178.4 | 514026.4 | 102506 | 1.64041666667 | 11435 |
| 010684 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:08pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597182.0 | 514025.7 | 102508 | 1.64041666667 | 10684 |
| 010667 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:09pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597184.3 | 514024.7 | 102510 | 1.64041666667 | 10667 |
| 010703 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:10pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597187.2 | 514023.8 | 102512 | 1.64041666667 | 10703 |
| 011728 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597190.1 | 514022.8 | 102514 | 1.64041666667 | 11728 |
| 011697 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597193.0 | 514021.1 | 102516 | 1.64041666667 | 11697 |
| 010869 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597194.2 | 514019.2 | 102518 | 1.64041666667 | 10869 |
| 010801 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597193.1 | 514017.9 | 102520 | 1.64041666667 | 10801 |
| 010470 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597190.2 | 514018.2 | 102522 | 1.64041666667 | 10470 |
| 010457 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597186.8 | 514018.8 | 102524 | 1.64041666667 | 10457 |
| 010427 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597183.6 | 514018.6 | 102526 | 1.64041666667 | 10427 |
| 010395 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597180.2 | 514018.3 | 102528 | 1.64041666667 | 10395 |
| 010819 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597177.2 | 514017.9 | 102530 | 1.64041666667 | 10819 |
| 011178 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597174.2 | 514016.8 | 102532 | 1.64041666667 | 11178 |
| 011373 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597171.9 | 514015.1 | 102534 | 1.64041666667 | 11373 |
| 018217 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:22pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597169.7 | 514013.0 | 102536 | 1.64041666667 | 18217 |
| 024294 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:23pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597168.7 | 514011.7 | 102538 | 1.64041666667 | 24294 |
| 030285 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:24pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597168.0 | 514010.7 | 102540 | 1.64041666667 | 30285 |
| 033235 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597167.6 | 514010.5 | 102542 | 1.64041666667 | 33235 |
| 036297 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.6 | 514010.4 | 102544 | 1.64041666667 | 36297 |
| 036797 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.5 | 514010.4 | 102546 | 1.64041666667 | 36797 |
| 036898 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597167.5 | 514010.4 | 102548 | 1.64041666667 | 36898 |
| 037225 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:29pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.5 | 514010.4 | 102550 | 1.64041666667 | 37225 |
| 036404 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:30pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597167.6 | 514010.4 | 102552 | 1.64041666667 | 36404 |
| 036152 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:31pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.7 | 514010.5 | 102554 | 1.64041666667 | 36152 |
| 036453 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.7 | 514010.5 | 102556 | 1.64041666667 | 36453 |
| 037680 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.7 | 514010.5 | 102558 | 1.64041666667 | 37680 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 037380 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:34pm | Sensor | 1797-S0058-G-636-DTE | 6862.0 | 1597167.3 | 514010.6 | 102560 | 1.64041666667 | 37380 |
| 037548 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:35pm | Sensor | 1797-S0058-G-636-DTE | 6862.1 | 1597167.1 | 514010.9 | 102562 | 1.64041666667 | 37548 |
| 036353 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:36pm | Sensor | 1797-S0058-G-636-DTE | 6862.2 | 1597166.3 | 514012.0 | 102564 | 1.64041666667 | 36353 |
| 029921 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:37pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597164.6 | 514013.7 | 102566 | 1.64041666667 | 29921 |
| 023760 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:38pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597161.4 | 514016.2 | 102568 | 1.64041666667 | 23760 |
| 019883 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:39pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597158.3 | 514017.3 | 102570 | 1.64041666667 | 19883 |
| 018294 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:40pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597154.5 | 514017.8 | 102572 | 1.64041666667 | 18294 |
| 015457 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:41pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597151.2 | 514018.2 | 102574 | 1.64041666667 | 15457 |
| 014350 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:42pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597147.6 | 514018.7 | 102576 | 1.64041666667 | 14350 |
| 014537 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:43pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597144.3 | 514018.5 | 102578 | 1.64041666667 | 14537 |
| 013869 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:44pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597140.3 | 514017.1 | 102580 | 1.64041666667 | 13869 |
| 015399 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:45pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597137.0 | 514016.5 | 102582 | 1.64041666667 | 15399 |
| 014939 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:46pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597133.5 | 514017.1 | 102584 | 1.64041666667 | 14939 |
| 015063 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:47pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597130.4 | 514018.6 | 102586 | 1.64041666667 | 15063 |
| 014518 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:48pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597126.9 | 514020.8 | 102588 | 1.64041666667 | 14518 |
| 014594 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:49pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597124.4 | 514022.2 | 102590 | 1.64041666667 | 14594 |
| 014389 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:50pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597121.0 | 514024.0 | 102592 | 1.64041666667 | 14389 |
| 019741 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:51pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597118.1 | 514024.9 | 102594 | 1.64041666667 | 19741 |
| 028572 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:52pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597116.3 | 514025.9 | 102596 | 1.64041666667 | 28572 |
| 035519 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:53pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597115.2 | 514027.0 | 102598 | 1.64041666667 | 35519 |
| 041984 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:54pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597112.2 | 514027.5 | 102600 | 1.64041666667 | 41984 |
| 044309 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:55pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597109.5 | 514027.0 | 102602 | 1.64041666667 | 44309 |
| 039188 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:56pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597106.2 | 514026.5 | 102604 | 1.64041666667 | 39188 |
| 034778 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:57pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597103.2 | 514026.3 | 102606 | 1.64041666667 | 34778 |
| 031278 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:58pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597099.9 | 514026.0 | 102608 | 1.64041666667 | 31278 |
| 029511 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:59pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597098.3 | 514025.5 | 102610 | 1.64041666667 | 29511 |
| 027872 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:00pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597098.7 | 514024.3 | 102612 | 1.64041666667 | 27872 |
| 028316 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:01pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597101.0 | 514023.7 | 102614 | 1.64041666667 | 28316 |
| 028595 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:02pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597104.0 | 514024.2 | 102616 | 1.64041666667 | 28595 |
| 029464 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:03pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597106.4 | 514024.8 | 102618 | 1.64041666667 | 29464 |
| 033711 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:04pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597109.1 | 514025.3 | 102620 | 1.64041666667 | 33711 |
| 037157 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:05pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597111.4 | 514025.6 | 102622 | 1.64041666667 | 37157 |
| 041893 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:06pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597113.3 | 514026.0 | 102624 | 1.64041666667 | 41893 |
| 042840 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:07pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597114.0 | 514026.3 | 102626 | 1.64041666667 | 42840 |
| 045232 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:08pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597114.1 | 514026.3 | 102628 | 1.64041666667 | 45232 |
| 047921 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:09pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597114.0 | 514026.3 | 102630 | 1.64041666667 | 47921 |
| 052073 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:10pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597113.9 | 514026.6 | 102632 | 1.64041666667 | 52073 |
| 054266 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:11pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.7 | 514026.8 | 102634 | 1.64041666667 | 54266 |
| 054172 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:12pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597113.2 | 514027.0 | 102636 | 1.64041666667 | 54172 |
| 054277 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:13pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597112.8 | 514027.8 | 102638 | 1.64041666667 | 54277 |
| 054890 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597112.6 | 514028.4 | 102640 | 1.64041666667 | 54890 |
| 059181 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597112.6 | 514028.4 | 102642 | 1.64041666667 | 59181 |
| 063776 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:16pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597112.9 | 514028.2 | 102644 | 1.64041666667 | 63776 |
| 064517 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:17pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597113.4 | 514028.1 | 102646 | 1.64041666667 | 64517 |
| 064108 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:18pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.4 | 514028.4 | 102648 | 1.64041666667 | 64108 |
| 065303 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:19pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.4 | 514028.5 | 102650 | 1.64041666667 | 65303 |
| 065398 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:20pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.5 | 514028.5 | 102652 | 1.64041666667 | 65398 |
| 066411 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:21pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.5 | 514028.6 | 102654 | 1.64041666667 | 66411 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 066876 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:22pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597113.5 | 514028.7 | 102656 | 1.64041666667 | 66876 |
| 066808 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:23pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.6 | 514028.7 | 102658 | 1.64041666667 | 66808 |
| 066597 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:24pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.6 | 514028.6 | 102660 | 1.64041666667 | 66597 |
| 068968 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.6 | 514028.6 | 102662 | 1.64041666667 | 68968 |
| 068749 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.5 | 514028.7 | 102664 | 1.64041666667 | 68749 |
| 067329 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597113.5 | 514028.6 | 102666 | 1.64041666667 | 67329 |
| 066905 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597113.2 | 514028.7 | 102668 | 1.64041666667 | 66905 |
| 064484 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:29pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597113.5 | 514029.0 | 102670 | 1.64041666667 | 64484 |
| 059852 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:30pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597115.0 | 514029.1 | 102672 | 1.64041666667 | 59852 |
| 057089 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:31pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597116.5 | 514028.2 | 102674 | 1.64041666667 | 57089 |
| 045792 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:32pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597117.5 | 514026.9 | 102676 | 1.64041666667 | 45792 |
| 044561 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:33pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597117.1 | 514026.4 | 102678 | 1.64041666667 | 44561 |
| 044018 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:34pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597116.1 | 514026.3 | 102680 | 1.64041666667 | 44018 |
| 046525 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:35pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597114.9 | 514026.5 | 102682 | 1.64041666667 | 46525 |
| 045640 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:36pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597113.3 | 514026.5 | 102684 | 1.64041666667 | 45640 |
| 046657 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:37pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597112.5 | 514026.2 | 102686 | 1.64041666667 | 46657 |
| 036512 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:38pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597112.1 | 514024.8 | 102688 | 1.64041666667 | 36512 |
| 037076 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:39pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597112.5 | 514024.2 | 102690 | 1.64041666667 | 37076 |
| 032517 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:40pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597114.5 | 514024.1 | 102692 | 1.64041666667 | 32517 |
| 030823 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:41pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597116.0 | 514024.5 | 102694 | 1.64041666667 | 30823 |
| 034101 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:42pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597117.4 | 514025.4 | 102696 | 1.64041666667 | 34101 |
| 038554 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:43pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597117.8 | 514027.2 | 102698 | 1.64041666667 | 38554 |
| 043586 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:44pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597118.4 | 514028.8 | 102700 | 1.64041666667 | 43586 |
| 045142 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:45pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597119.9 | 514029.8 | 102702 | 1.64041666667 | 45142 |
| 038922 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:46pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597122.3 | 514031.2 | 102704 | 1.64041666667 | 38922 |
| 035551 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:47pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597124.7 | 514031.7 | 102706 | 1.64041666667 | 35551 |
| 037997 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:48pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597127.2 | 514032.2 | 102708 | 1.64041666667 | 37997 |
| 037033 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:49pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597129.8 | 514032.5 | 102710 | 1.64041666667 | 37033 |
| 034631 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:50pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597132.2 | 514032.5 | 102712 | 1.64041666667 | 34631 |
| 031652 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:51pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597134.7 | 514032.8 | 102714 | 1.64041666667 | 31652 |
| 024157 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:52pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597137.9 | 514031.6 | 102716 | 1.64041666667 | 24157 |
| 018793 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:53pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597140.5 | 514031.1 | 102718 | 1.64041666667 | 18793 |
| 015498 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:54pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597143.4 | 514030.7 | 102720 | 1.64041666667 | 15498 |
| 014358 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:55pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597145.3 | 514029.8 | 102722 | 1.64041666667 | 14358 |
| 012966 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597145.0 | 514028.7 | 102724 | 1.64041666667 | 12966 |
| 012633 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.4 | 1597142.7 | 514028.5 | 102726 | 1.64041666667 | 12633 |
| 011831 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:58pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597139.4 | 514029.4 | 102728 | 1.64041666667 | 11831 |
| 012662 | 0 | GeoXH 6000 | 08/20/2015 | 01:47:59pm | Sensor | 1797-S0058-G-636-DTE | 6862.5 | 1597136.7 | 514030.2 | 102730 | 1.64041666667 | 12662 |
| 018500 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:00pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597133.5 | 514031.3 | 102732 | 1.64041666667 | 18500 |
| 023951 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:01pm | Sensor | 1797-S0058-G-636-DTE | 6862.6 | 1597131.1 | 514031.5 | 102734 | 1.64041666667 | 23951 |
| 026627 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:02pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597128.4 | 514031.5 | 102736 | 1.64041666667 | 26627 |
| 031793 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:03pm | Sensor | 1797-S0058-G-636-DTE | 6862.7 | 1597126.3 | 514031.6 | 102738 | 1.64041666667 | 31793 |
| 032523 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:04pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597124.7 | 514031.5 | 102740 | 1.64041666667 | 32523 |
| 033692 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:05pm | Sensor | 1797-S0058-G-636-DTE | 6862.8 | 1597124.0 | 514031.8 | 102742 | 1.64041666667 | 33692 |
| 030344 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:06pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597122.7 | 514031.7 | 102744 | 1.64041666667 | 30344 |
| 031063 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:07pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597121.5 | 514031.1 | 102746 | 1.64041666667 | 31063 |
| 037408 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:08pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597120.2 | 514030.3 | 102748 | 1.64041666667 | 37408 |
| 045784 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:09pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597119.5 | 514030.3 | 102750 | 1.64041666667 | 45784 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 052071 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:10pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597119.3 | 514029.9 | 102752 | 1.64041666667 | 52071 |
| 055517 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:11pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597118.9 | 514029.9 | 102754 | 1.64041666667 | 55517 |
| 056436 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:12pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597118.9 | 514029.8 | 102756 | 1.64041666667 | 56436 |
| 056532 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:13pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597118.9 | 514029.8 | 102758 | 1.64041666667 | 56532 |
| 056339 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:14pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597118.9 | 514029.8 | 102760 | 1.64041666667 | 56339 |
| 057131 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:15pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597119.2 | 514029.5 | 102762 | 1.64041666667 | 57131 |
| 053278 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:16pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597118.8 | 514028.7 | 102764 | 1.64041666667 | 53278 |
| 051186 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:17pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597117.4 | 514027.5 | 102766 | 1.64041666667 | 51186 |
| 050647 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:18pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597116.6 | 514026.8 | 102768 | 1.64041666667 | 50647 |
| 048424 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:19pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597116.2 | 514027.3 | 102770 | 1.64041666667 | 48424 |
| 050496 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:20pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597115.5 | 514027.6 | 102772 | 1.64041666667 | 50496 |
| 054091 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:21pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597114.9 | 514028.0 | 102774 | 1.64041666667 | 54091 |
| 056811 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:22pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597114.4 | 514028.5 | 102776 | 1.64041666667 | 56811 |
| 059039 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:23pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597114.2 | 514028.7 | 102778 | 1.64041666667 | 59039 |
| 063832 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:24pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597113.9 | 514028.5 | 102780 | 1.64041666667 | 63832 |
| 063640 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:25pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597113.7 | 514028.4 | 102782 | 1.64041666667 | 63640 |
| 065070 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:26pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597113.7 | 514028.3 | 102784 | 1.64041666667 | 65070 |
| 065192 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:27pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597113.7 | 514028.3 | 102786 | 1.64041666667 | 65192 |
| 066250 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:28pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597113.7 | 514028.3 | 102788 | 1.64041666667 | 66250 |
| 065038 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:29pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597113.5 | 514028.1 | 102790 | 1.64041666667 | 65038 |
| 062639 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:30pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597113.1 | 514027.8 | 102792 | 1.64041666667 | 62639 |
| 065362 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:31pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597112.8 | 514027.6 | 102794 | 1.64041666667 | 65362 |
| 063983 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:32pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597112.8 | 514027.6 | 102796 | 1.64041666667 | 63983 |
| 064070 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:33pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597112.8 | 514027.5 | 102798 | 1.64041666667 | 64070 |
| 063437 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:34pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597113.1 | 514027.2 | 102800 | 1.64041666667 | 63437 |
| 056893 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:35pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597113.4 | 514026.9 | 102802 | 1.64041666667 | 56893 |
| 052957 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:36pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597113.7 | 514027.1 | 102804 | 1.64041666667 | 52957 |
| 053668 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:37pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597114.2 | 514027.4 | 102806 | 1.64041666667 | 53668 |
| 052823 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:38pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597115.2 | 514027.5 | 102808 | 1.64041666667 | 52823 |
| 049877 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:39pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597116.0 | 514027.6 | 102810 | 1.64041666667 | 49877 |
| 044793 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:40pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597116.5 | 514027.8 | 102812 | 1.64041666667 | 44793 |
| 043968 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:41pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597116.4 | 514027.8 | 102814 | 1.64041666667 | 43968 |
| 044247 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:42pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597116.4 | 514027.9 | 102816 | 1.64041666667 | 44247 |
| 044164 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:43pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597116.4 | 514028.0 | 102818 | 1.64041666667 | 44164 |
| 045902 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:44pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597117.2 | 514027.9 | 102820 | 1.64041666667 | 45902 |
| 042665 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:45pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597119.0 | 514027.5 | 102822 | 1.64041666667 | 42665 |
| 037439 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:46pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597121.1 | 514027.3 | 102824 | 1.64041666667 | 37439 |
| 030929 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:47pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597121.4 | 514027.0 | 102826 | 1.64041666667 | 30929 |
| 029382 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597120.0 | 514026.7 | 102828 | 1.64041666667 | 29382 |
| 034085 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:49pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597118.1 | 514026.6 | 102830 | 1.64041666667 | 34085 |
| 035433 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:50pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597116.3 | 514026.1 | 102832 | 1.64041666667 | 35433 |
| 041741 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:51pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597114.1 | 514026.5 | 102834 | 1.64041666667 | 41741 |
| 042199 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:52pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597111.4 | 514026.2 | 102836 | 1.64041666667 | 42199 |
| 042269 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:53pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597108.9 | 514025.9 | 102838 | 1.64041666667 | 42269 |
| 039556 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:54pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597105.8 | 514026.3 | 102840 | 1.64041666667 | 39556 |
| 036328 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:55pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597102.8 | 514026.0 | 102842 | 1.64041666667 | 36328 |
| 032757 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:56pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597099.6 | 514025.3 | 102844 | 1.64041666667 | 32757 |
| 032270 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:57pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597096.6 | 514025.3 | 102846 | 1.64041666667 | 32270 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 034360 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:58pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597092.7 | 514025.4 | 102848 | 1.64041666667 | 34360 |
| 042982 | 0 | GeoXH 6000 | 08/20/2015 | 01:48:59pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597089.7 | 514024.8 | 102850 | 1.64041666667 | 42982 |
| 047007 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:00pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597086.3 | 514024.5 | 102852 | 1.64041666667 | 47007 |
| 046256 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:01pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597083.8 | 514024.6 | 102854 | 1.64041666667 | 46256 |
| 040172 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:02pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597080.3 | 514024.3 | 102856 | 1.64041666667 | 40172 |
| 032136 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:03pm | Sensor | 1797-S0058-G-636-DTE | 6863.8 | 1597079.3 | 514024.8 | 102858 | 1.64041666667 | 32136 |
| 034719 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:04pm | Sensor | 1797-S0058-G-636-DTE | 6863.8 | 1597080.8 | 514025.6 | 102860 | 1.64041666667 | 34719 |
| 039584 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:05pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597082.7 | 514025.8 | 102862 | 1.64041666667 | 39584 |
| 043866 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:06pm | Sensor | 1797-S0058-G-636-DTE | 6863.8 | 1597084.0 | 514025.6 | 102864 | 1.64041666667 | 43866 |
| 048705 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:07pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597084.4 | 514025.4 | 102866 | 1.64041666667 | 48705 |
| 050751 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:08pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597084.6 | 514025.2 | 102868 | 1.64041666667 | 50751 |
| 052862 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:09pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597084.6 | 514025.2 | 102870 | 1.64041666667 | 52862 |
| 053510 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:10pm | Sensor | 1797-S0058-G-636-DTE | 6863.8 | 1597084.6 | 514025.5 | 102872 | 1.64041666667 | 53510 |
| 053792 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:11pm | Sensor | 1797-S0058-G-636-DTE | 6863.9 | 1597085.3 | 514025.7 | 102874 | 1.64041666667 | 53792 |
| 052750 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:12pm | Sensor | 1797-S0058-G-636-DTE | 6863.8 | 1597087.4 | 514025.5 | 102876 | 1.64041666667 | 52750 |
| 056777 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:13pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597089.5 | 514025.9 | 102878 | 1.64041666667 | 56777 |
| 052749 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:14pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597090.5 | 514026.5 | 102880 | 1.64041666667 | 52749 |
| 054624 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:15pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597089.9 | 514026.7 | 102882 | 1.64041666667 | 54624 |
| 055843 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:16pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597089.7 | 514026.8 | 102884 | 1.64041666667 | 55843 |
| 055944 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:17pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597089.7 | 514026.7 | 102886 | 1.64041666667 | 55944 |
| 054928 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:18pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597089.6 | 514026.7 | 102888 | 1.64041666667 | 54928 |
| 054297 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:19pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597089.5 | 514026.7 | 102890 | 1.64041666667 | 54297 |
| 055989 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:20pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597089.6 | 514026.5 | 102892 | 1.64041666667 | 55989 |
| 056596 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:21pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597090.0 | 514025.8 | 102894 | 1.64041666667 | 56596 |
| 051140 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:22pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597090.2 | 514025.2 | 102896 | 1.64041666667 | 51140 |
| 049256 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:23pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597090.6 | 514025.2 | 102898 | 1.64041666667 | 49256 |
| 048046 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:24pm | Sensor | 1797-S0058-G-636-DTE | 6863.7 | 1597091.4 | 514025.4 | 102900 | 1.64041666667 | 48046 |
| 044103 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:25pm | Sensor | 1797-S0058-G-636-DTE | 6863.6 | 1597092.1 | 514025.0 | 102902 | 1.64041666667 | 44103 |
| 040266 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:26pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597093.6 | 514024.8 | 102904 | 1.64041666667 | 40266 |
| 035954 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:27pm | Sensor | 1797-S0058-G-636-DTE | 6863.5 | 1597095.3 | 514025.1 | 102906 | 1.64041666667 | 35954 |
| 032059 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:28pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597097.7 | 514025.5 | 102908 | 1.64041666667 | 32059 |
| 032718 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:29pm | Sensor | 1797-S0058-G-636-DTE | 6863.4 | 1597099.9 | 514026.3 | 102910 | 1.64041666667 | 32718 |
| 032084 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:30pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597102.6 | 514026.6 | 102912 | 1.64041666667 | 32084 |
| 033879 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:31pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597105.0 | 514027.1 | 102914 | 1.64041666667 | 33879 |
| 036585 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:32pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597108.1 | 514027.0 | 102916 | 1.64041666667 | 36585 |
| 045006 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:33pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597109.4 | 514026.6 | 102918 | 1.64041666667 | 45006 |
| 048146 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:34pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597108.9 | 514027.1 | 102920 | 1.64041666667 | 48146 |
| 055829 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:35pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597108.3 | 514027.3 | 102922 | 1.64041666667 | 55829 |
| 058224 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:36pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597108.1 | 514027.3 | 102924 | 1.64041666667 | 58224 |
| 061858 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:37pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597108.2 | 514027.4 | 102926 | 1.64041666667 | 61858 |
| 063498 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:38pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597108.6 | 514028.1 | 102928 | 1.64041666667 | 63498 |
| 061000 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:39pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597108.9 | 514029.4 | 102930 | 1.64041666667 | 61000 |
| 057255 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:40pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597108.9 | 514029.6 | 102932 | 1.64041666667 | 57255 |
| 060391 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:41pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597109.0 | 514029.5 | 102934 | 1.64041666667 | 60391 |
| 060175 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:42pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597109.1 | 514029.4 | 102936 | 1.64041666667 | 60175 |
| 059760 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:43pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597109.2 | 514029.4 | 102938 | 1.64041666667 | 59760 |
| 057300 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:44pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597109.3 | 514029.2 | 102940 | 1.64041666667 | 57300 |
| 054986 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:45pm | Sensor | 1797-S0058-G-636-DTE | 6863.3 | 1597109.7 | 514028.8 | 102942 | 1.64041666667 | 54986 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|--------|---------------|-------|
| 056160 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:46pm | Sensor | 1797-S0058-G-636-DTE | 6863.2 | 1597110.8 | 514028.6 | 102944 | 1.64041666667 | 56160 |
| 060150 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:47pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597111.7 | 514029.2 | 102946 | 1.64041666667 | 60150 |
| 062079 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:48pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597111.8 | 514029.4 | 102948 | 1.64041666667 | 62079 |
| 063194 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:49pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597111.9 | 514029.5 | 102950 | 1.64041666667 | 63194 |
| 066597 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:50pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597111.9 | 514029.5 | 102952 | 1.64041666667 | 66597 |
| 067243 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:51pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597111.9 | 514029.4 | 102954 | 1.64041666667 | 67243 |
| 068072 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:52pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597111.8 | 514029.4 | 102956 | 1.64041666667 | 68072 |
| 069363 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:53pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597111.8 | 514029.4 | 102958 | 1.64041666667 | 69363 |
| 071904 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:54pm | Sensor | 1797-S0058-G-636-DTE | 6863.0 | 1597111.9 | 514029.3 | 102960 | 1.64041666667 | 71904 |
| 070423 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:55pm | Sensor | 1797-S0058-G-636-DTE | 6863.1 | 1597111.9 | 514028.8 | 102962 | 1.64041666667 | 70423 |
| 070070 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:56pm | Sensor | 1797-S0058-G-636-DTE | 6862.9 | 1597112.5 | 514028.3 | 102964 | 1.64041666667 | 70070 |
| 071402 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:57pm | Sensor | 1797-S0058-G-636-DTE | 6862.3 | 1597113.4 | 514028.4 | 102966 | 1.64041666667 | 71402 |
| 070441 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:58pm | Sensor | 1797-S0058-G-636-DTE | 6860.6 | 1597113.9 | 514028.7 | 102968 | 1.64041666667 | 70441 |
| 070688 | 0 | GeoXH 6000 | 08/20/2015 | 01:49:59pm | Sensor | 1797-S0058-G-636-DTE | 6859.0 | 1597114.1 | 514029.3 | 102970 | 1.64041666667 | 70688 |
| 071464 | 0 | GeoXH 6000 | 08/20/2015 | 01:50:00pm | Sensor | 1797-S0058-G-636-DTE | 6859.1 | 1597114.1 | 514029.1 | 102972 | 1.64041666667 | 71464 |
| 071271 | 0 | GeoXH 6000 | 08/20/2015 | 01:50:01pm | Sensor | 1797-S0058-G-636-DTE | 6859.0 | 1597114.1 | 514029.2 | 102974 | 1.64041666667 | 71271 |
| 072850 | 0 | GeoXH 6000 | 08/20/2015 | 01:50:02pm | Sensor | 1797-S0058-G-636-DTE | 6858.7 | 1597114.1 | 514029.4 | 102976 | 1.64041666667 | 72850 |
| 072920 | 0 | GeoXH 6000 | 08/20/2015 | 01:50:03pm | Sensor | 1797-S0058-G-636-DTE | 6859.5 | 1597113.4 | 514029.3 | 102978 | 1.64041666667 | 72920 |
| 068272 | 0 | GeoXH 6000 | 08/20/2015 | 01:50:04pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597112.2 | 514029.5 | 102980 | 1.64041666667 | 68272 |
| 057476 | 0 | GeoXH 6000 | 08/20/2015 | 01:50:05pm | Sensor | 1797-S0058-G-636-DTE | 6861.0 | 1597111.6 | 514029.9 | 102982 | 1.64041666667 | 57476 |
| 052197 | 0 | GeoXH 6000 | 08/20/2015 | 01:50:06pm | Sensor | 1797-S0058-G-636-DTE | 6860.9 | 1597111.7 | 514029.9 | 102984 | 1.64041666667 | 52197 |
| 013151 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:33pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97915 | 1.64041666667 | 13151 |
| 013292 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:34pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97918 | 1.64041666667 | 13292 |
| 014039 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:35pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.8 | 97920 | 1.64041666667 | 14039 |
| 014339 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:36pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.8 | 97922 | 1.64041666667 | 14339 |
| 013818 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:37pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597189.9 | 513337.8 | 97924 | 1.64041666667 | 13818 |
| 012843 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:38pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97926 | 1.64041666667 | 12843 |
| 012489 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:39pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97928 | 1.64041666667 | 12489 |
| 011157 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:40pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97930 | 1.64041666667 | 11157 |
| 012321 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:41pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97932 | 1.64041666667 | 12321 |
| 012390 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:42pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97934 | 1.64041666667 | 12390 |
| 013074 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:43pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97936 | 1.64041666667 | 13074 |
| 012912 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:44pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97938 | 1.64041666667 | 12912 |
| 013143 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:45pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97940 | 1.64041666667 | 13143 |
| 013565 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:46pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97942 | 1.64041666667 | 13565 |
| 013510 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:47pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597190.0 | 513338.0 | 97944 | 1.64041666667 | 13510 |
| 013734 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:48pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513338.0 | 97946 | 1.64041666667 | 13734 |
| 013560 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:49pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97948 | 1.64041666667 | 13560 |
| 012577 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:50pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97950 | 1.64041666667 | 12577 |
| 012947 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:51pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97952 | 1.64041666667 | 12947 |
| 013335 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:52pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597190.0 | 513337.9 | 97954 | 1.64041666667 | 13335 |
| 013231 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:53pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97956 | 1.64041666667 | 13231 |
| 013307 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:54pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597190.0 | 513337.9 | 97958 | 1.64041666667 | 13307 |
| 013508 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:55pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97960 | 1.64041666667 | 13508 |
| 012570 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:56pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597190.0 | 513337.9 | 97962 | 1.64041666667 | 12570 |
| 012621 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:57pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.0 | 513337.9 | 97964 | 1.64041666667 | 12621 |
| 012544 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:58pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597189.9 | 513338.0 | 97966 | 1.64041666667 | 12544 |
| 013453 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:59pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597189.7 | 513338.1 | 97968 | 1.64041666667 | 13453 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013575 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:00pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597189.2 | 513338.3 | 97970 | 1.64041666667 | 13575 |
| 013268 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:01pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597189.0 | 513338.3 | 97972 | 1.64041666667 | 13268 |
| 013801 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:02pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597189.1 | 513338.3 | 97974 | 1.64041666667 | 13801 |
| 012938 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:03pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597189.1 | 513338.3 | 97976 | 1.64041666667 | 12938 |
| 013495 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:04pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597189.0 | 513338.1 | 97978 | 1.64041666667 | 13495 |
| 013591 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:05pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597189.6 | 513336.2 | 97980 | 1.64041666667 | 13591 |
| 014185 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:06pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597188.4 | 513334.4 | 97982 | 1.64041666667 | 14185 |
| 014526 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:07pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597188.8 | 513331.8 | 97984 | 1.64041666667 | 14526 |
| 014313 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:08pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597189.1 | 513329.2 | 97986 | 1.64041666667 | 14313 |
| 014186 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:09pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597189.5 | 513326.1 | 97988 | 1.64041666667 | 14186 |
| 013312 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:10pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597190.1 | 513323.5 | 97990 | 1.64041666667 | 13312 |
| 013863 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:11pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597191.0 | 513319.8 | 97992 | 1.64041666667 | 13863 |
| 013970 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:12pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597192.2 | 513317.0 | 97994 | 1.64041666667 | 13970 |
| 014878 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:13pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597192.4 | 513313.7 | 97996 | 1.64041666667 | 14878 |
| 014556 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:14pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597193.1 | 513311.5 | 97998 | 1.64041666667 | 14556 |
| 014015 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:15pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597192.1 | 513309.3 | 98000 | 1.64041666667 | 14015 |
| 014588 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:16pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597192.1 | 513307.6 | 98002 | 1.64041666667 | 14588 |
| 014378 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:17pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597192.9 | 513305.1 | 98004 | 1.64041666667 | 14378 |
| 013570 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:18pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597195.3 | 513303.9 | 98006 | 1.64041666667 | 13570 |
| 013828 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:19pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597197.7 | 513302.0 | 98008 | 1.64041666667 | 13828 |
| 014048 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:20pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597198.6 | 513299.6 | 98010 | 1.64041666667 | 14048 |
| 014037 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:21pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597200.4 | 513298.3 | 98012 | 1.64041666667 | 14037 |
| 014038 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:22pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597201.3 | 513297.3 | 98014 | 1.64041666667 | 14038 |
| 014560 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:23pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597203.9 | 513296.2 | 98016 | 1.64041666667 | 14560 |
| 014850 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:24pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597206.0 | 513296.3 | 98018 | 1.64041666667 | 14850 |
| 014488 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:25pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597208.6 | 513296.0 | 98020 | 1.64041666667 | 14488 |
| 014817 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:26pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597210.4 | 513297.0 | 98022 | 1.64041666667 | 14817 |
| 014402 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:27pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597213.2 | 513297.6 | 98024 | 1.64041666667 | 14402 |
| 013703 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:28pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597215.5 | 513297.4 | 98026 | 1.64041666667 | 13703 |
| 014045 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:29pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597217.9 | 513295.3 | 98028 | 1.64041666667 | 14045 |
| 013271 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:30pm | Sensor | 1797-S0057-G-637-DTE | 6858.0 | 1597218.6 | 513292.7 | 98030 | 1.64041666667 | 13271 |
| 013217 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:31pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597220.5 | 513289.3 | 98032 | 1.64041666667 | 13217 |
| 012609 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:32pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597222.4 | 513286.5 | 98034 | 1.64041666667 | 12609 |
| 013040 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:33pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597223.6 | 513283.4 | 98036 | 1.64041666667 | 13040 |
| 014482 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:34pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597225.1 | 513280.8 | 98038 | 1.64041666667 | 14482 |
| 014656 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:35pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597225.4 | 513277.2 | 98040 | 1.64041666667 | 14656 |
| 015129 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:36pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597225.5 | 513274.2 | 98042 | 1.64041666667 | 15129 |
| 014817 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:37pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597226.4 | 513270.5 | 98044 | 1.64041666667 | 14817 |
| 014485 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:38pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597226.7 | 513267.4 | 98046 | 1.64041666667 | 14485 |
| 014193 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:39pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597226.8 | 513264.3 | 98048 | 1.64041666667 | 14193 |
| 014238 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:40pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597227.7 | 513261.3 | 98050 | 1.64041666667 | 14238 |
| 013851 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:41pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597227.7 | 513258.1 | 98052 | 1.64041666667 | 13851 |
| 014121 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:42pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597228.7 | 513255.4 | 98054 | 1.64041666667 | 14121 |
| 014400 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:43pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597230.0 | 513252.5 | 98056 | 1.64041666667 | 14400 |
| 013920 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:44pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597230.7 | 513249.8 | 98058 | 1.64041666667 | 13920 |
| 013500 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:45pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597232.9 | 513247.1 | 98060 | 1.64041666667 | 13500 |
| 013338 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:46pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597234.4 | 513244.1 | 98062 | 1.64041666667 | 13338 |
| 013488 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:47pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597235.6 | 513240.4 | 98064 | 1.64041666667 | 13488 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013827 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:48pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597237.5 | 513238.2 | 98066 | 1.64041666667 | 13827 |
| 014107 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:49pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597239.1 | 513235.1 | 98068 | 1.64041666667 | 14107 |
| 014138 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:50pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597239.4 | 513232.7 | 98070 | 1.64041666667 | 14138 |
| 014095 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:51pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597240.5 | 513230.9 | 98072 | 1.64041666667 | 14095 |
| 013786 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:52pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597240.4 | 513230.9 | 98074 | 1.64041666667 | 13786 |
| 014039 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:53pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597240.5 | 513231.0 | 98076 | 1.64041666667 | 14039 |
| 014122 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:54pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597240.6 | 513230.9 | 98078 | 1.64041666667 | 14122 |
| 013253 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:55pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597240.6 | 513230.8 | 98080 | 1.64041666667 | 13253 |
| 014145 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:56pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597240.5 | 513231.0 | 98082 | 1.64041666667 | 14145 |
| 013956 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:57pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597240.0 | 513231.1 | 98084 | 1.64041666667 | 13956 |
| 014435 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:58pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597239.1 | 513230.9 | 98086 | 1.64041666667 | 14435 |
| 014450 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:59pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597238.9 | 513231.0 | 98088 | 1.64041666667 | 14450 |
| 014075 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:00pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597238.8 | 513231.0 | 98090 | 1.64041666667 | 14075 |
| 012995 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:01pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597238.8 | 513230.9 | 98092 | 1.64041666667 | 12995 |
| 012567 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:02pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597238.9 | 513231.0 | 98094 | 1.64041666667 | 12567 |
| 014081 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:03pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597238.9 | 513231.0 | 98096 | 1.64041666667 | 14081 |
| 014041 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:04pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597239.0 | 513231.4 | 98098 | 1.64041666667 | 14041 |
| 014636 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:05pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597238.2 | 513232.5 | 98100 | 1.64041666667 | 14636 |
| 014158 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:06pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597237.0 | 513233.5 | 98102 | 1.64041666667 | 14158 |
| 014646 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:07pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597234.8 | 513232.4 | 98104 | 1.64041666667 | 14646 |
| 014801 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:08pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597233.1 | 513230.6 | 98106 | 1.64041666667 | 14801 |
| 014865 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:09pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597231.9 | 513229.5 | 98108 | 1.64041666667 | 14865 |
| 014999 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:10pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597230.5 | 513229.9 | 98110 | 1.64041666667 | 14999 |
| 014294 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:11pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597229.0 | 513229.0 | 98112 | 1.64041666667 | 14294 |
| 015315 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:12pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597228.7 | 513228.7 | 98114 | 1.64041666667 | 15315 |
| 014360 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:13pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597228.6 | 513229.0 | 98116 | 1.64041666667 | 14360 |
| 014055 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:14pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597229.1 | 513230.2 | 98118 | 1.64041666667 | 14055 |
| 014176 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:15pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597228.3 | 513231.5 | 98120 | 1.64041666667 | 14176 |
| 014671 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:16pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597228.6 | 513232.6 | 98122 | 1.64041666667 | 14671 |
| 015632 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:17pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597228.2 | 513233.3 | 98124 | 1.64041666667 | 15632 |
| 015011 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:18pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597227.3 | 513233.5 | 98126 | 1.64041666667 | 15011 |
| 014871 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:19pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597226.0 | 513234.9 | 98128 | 1.64041666667 | 14871 |
| 014365 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:20pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597224.8 | 513234.6 | 98130 | 1.64041666667 | 14365 |
| 014470 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:21pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597223.2 | 513234.4 | 98132 | 1.64041666667 | 14470 |
| 014837 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:22pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597221.7 | 513234.4 | 98134 | 1.64041666667 | 14837 |
| 015141 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:23pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597219.5 | 513233.6 | 98136 | 1.64041666667 | 15141 |
| 014014 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:24pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597217.5 | 513233.0 | 98138 | 1.64041666667 | 14014 |
| 013913 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:25pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597215.6 | 513231.6 | 98140 | 1.64041666667 | 13913 |
| 013743 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:26pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597214.0 | 513230.6 | 98142 | 1.64041666667 | 13743 |
| 013730 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:27pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597212.6 | 513229.1 | 98144 | 1.64041666667 | 13730 |
| 013566 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:28pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597211.5 | 513227.6 | 98146 | 1.64041666667 | 13566 |
| 013398 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:29pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597209.8 | 513225.5 | 98148 | 1.64041666667 | 13398 |
| 014174 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:30pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597208.3 | 513222.7 | 98150 | 1.64041666667 | 14174 |
| 014917 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:31pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597206.0 | 513220.3 | 98152 | 1.64041666667 | 14917 |
| 014421 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:32pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597203.2 | 513218.6 | 98154 | 1.64041666667 | 14421 |
| 013774 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:33pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597199.8 | 513216.5 | 98156 | 1.64041666667 | 13774 |
| 014055 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:34pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597197.0 | 513214.7 | 98158 | 1.64041666667 | 14055 |
| 014131 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:35pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597193.3 | 513213.3 | 98160 | 1.64041666667 | 14131 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014301 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:36pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597190.6 | 513212.2 | 98162 | 1.64041666667 | 14301 |
| 013992 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:37pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597187.4 | 513210.7 | 98164 | 1.64041666667 | 13992 |
| 014065 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:38pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597184.1 | 513209.1 | 98166 | 1.64041666667 | 14065 |
| 014174 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:39pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597180.5 | 513208.0 | 98168 | 1.64041666667 | 14174 |
| 014498 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:40pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597177.8 | 513207.1 | 98170 | 1.64041666667 | 14498 |
| 014807 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:41pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597174.1 | 513205.5 | 98172 | 1.64041666667 | 14807 |
| 015259 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:42pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597171.1 | 513204.3 | 98174 | 1.64041666667 | 15259 |
| 015813 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:43pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597167.4 | 513202.9 | 98176 | 1.64041666667 | 15813 |
| 015352 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:44pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597164.4 | 513201.9 | 98178 | 1.64041666667 | 15352 |
| 014163 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:45pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597160.8 | 513200.0 | 98180 | 1.64041666667 | 14163 |
| 013592 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:46pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597158.2 | 513198.1 | 98182 | 1.64041666667 | 13592 |
| 014290 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:47pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597155.2 | 513196.5 | 98184 | 1.64041666667 | 14290 |
| 014533 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:48pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597152.1 | 513194.9 | 98186 | 1.64041666667 | 14533 |
| 014257 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:49pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597148.8 | 513193.2 | 98188 | 1.64041666667 | 14257 |
| 015685 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:50pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597145.5 | 513191.7 | 98190 | 1.64041666667 | 15685 |
| 016067 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:51pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597141.2 | 513191.2 | 98192 | 1.64041666667 | 16067 |
| 014678 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:52pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597138.3 | 513192.5 | 98194 | 1.64041666667 | 14678 |
| 014714 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:53pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597135.7 | 513195.7 | 98196 | 1.64041666667 | 14714 |
| 014081 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:54pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597133.7 | 513199.1 | 98198 | 1.64041666667 | 14081 |
| 013875 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:55pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597131.9 | 513202.3 | 98200 | 1.64041666667 | 13875 |
| 014510 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:56pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597130.7 | 513205.3 | 98202 | 1.64041666667 | 14510 |
| 014664 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:57pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597129.6 | 513209.0 | 98204 | 1.64041666667 | 14664 |
| 014654 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:58pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597128.4 | 513211.9 | 98206 | 1.64041666667 | 14654 |
| 015765 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:59pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597125.8 | 513214.9 | 98208 | 1.64041666667 | 15765 |
| 015340 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:00pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597123.8 | 513217.6 | 98210 | 1.64041666667 | 15340 |
| 015596 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:01pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597122.1 | 513221.5 | 98212 | 1.64041666667 | 15596 |
| 014848 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:02pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597120.8 | 513224.5 | 98214 | 1.64041666667 | 14848 |
| 014787 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:03pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597118.9 | 513227.8 | 98216 | 1.64041666667 | 14787 |
| 014692 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:04pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597117.1 | 513230.6 | 98218 | 1.64041666667 | 14692 |
| 015254 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:05pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597115.4 | 513234.0 | 98220 | 1.64041666667 | 15254 |
| 014445 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:06pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597114.4 | 513236.6 | 98222 | 1.64041666667 | 14445 |
| 013998 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:07pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597112.9 | 513239.8 | 98224 | 1.64041666667 | 13998 |
| 014579 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:08pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597111.1 | 513242.7 | 98226 | 1.64041666667 | 14579 |
| 017815 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:09pm | Sensor | 1797-S0057-G-637-DTE | 6854.7 | 1597108.9 | 513245.6 | 98228 | 1.64041666667 | 17815 |
| 019351 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:10pm | Sensor | 1797-S0057-G-637-DTE | 6854.7 | 1597108.5 | 513247.3 | 98230 | 1.64041666667 | 19351 |
| 020147 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:11pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597108.7 | 513247.0 | 98232 | 1.64041666667 | 20147 |
| 022343 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:12pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597108.8 | 513247.0 | 98234 | 1.64041666667 | 22343 |
| 022850 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:13pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597108.7 | 513247.0 | 98236 | 1.64041666667 | 22850 |
| 023510 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:14pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597108.4 | 513247.8 | 98238 | 1.64041666667 | 23510 |
| 022772 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:15pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597106.9 | 513249.5 | 98240 | 1.64041666667 | 22772 |
| 020677 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:16pm | Sensor | 1797-S0057-G-637-DTE | 6854.7 | 1597106.5 | 513251.8 | 98242 | 1.64041666667 | 20677 |
| 018793 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:17pm | Sensor | 1797-S0057-G-637-DTE | 6854.7 | 1597106.0 | 513254.1 | 98244 | 1.64041666667 | 18793 |
| 017531 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:18pm | Sensor | 1797-S0057-G-637-DTE | 6854.7 | 1597105.9 | 513255.2 | 98246 | 1.64041666667 | 17531 |
| 016874 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:19pm | Sensor | 1797-S0057-G-637-DTE | 6854.7 | 1597104.3 | 513257.0 | 98248 | 1.64041666667 | 16874 |
| 015581 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:20pm | Sensor | 1797-S0057-G-637-DTE | 6854.6 | 1597102.7 | 513259.8 | 98250 | 1.64041666667 | 15581 |
| 014832 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:21pm | Sensor | 1797-S0057-G-637-DTE | 6854.7 | 1597102.0 | 513263.2 | 98252 | 1.64041666667 | 14832 |
| 015468 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:22pm | Sensor | 1797-S0057-G-637-DTE | 6854.6 | 1597100.9 | 513266.6 | 98254 | 1.64041666667 | 15468 |
| 015900 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:23pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597099.2 | 513270.0 | 98256 | 1.64041666667 | 15900 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015206 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:24pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597098.2 | 513273.0 | 98258 | 1.64041666667 | 15206 |
| 016121 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:25pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597097.2 | 513276.8 | 98260 | 1.64041666667 | 16121 |
| 018053 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:26pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597096.4 | 513279.5 | 98262 | 1.64041666667 | 18053 |
| 017542 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:27pm | Sensor | 1797-S0057-G-637-DTE | 6854.3 | 1597095.2 | 513283.0 | 98264 | 1.64041666667 | 17542 |
| 016887 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:28pm | Sensor | 1797-S0057-G-637-DTE | 6854.3 | 1597094.4 | 513286.0 | 98266 | 1.64041666667 | 16887 |
| 016076 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:29pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597094.3 | 513289.1 | 98268 | 1.64041666667 | 16076 |
| 016535 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:30pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597095.3 | 513291.6 | 98270 | 1.64041666667 | 16535 |
| 018646 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:31pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597098.4 | 513293.6 | 98272 | 1.64041666667 | 18646 |
| 018303 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:32pm | Sensor | 1797-S0057-G-637-DTE | 6854.6 | 1597101.3 | 513293.8 | 98274 | 1.64041666667 | 18303 |
| 018718 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:33pm | Sensor | 1797-S0057-G-637-DTE | 6854.6 | 1597105.0 | 513293.3 | 98276 | 1.64041666667 | 18718 |
| 018681 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:34pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597107.9 | 513292.8 | 98278 | 1.64041666667 | 18681 |
| 019373 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:35pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597111.1 | 513291.9 | 98280 | 1.64041666667 | 19373 |
| 018127 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:36pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597114.4 | 513291.1 | 98282 | 1.64041666667 | 18127 |
| 017216 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:37pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597117.8 | 513290.5 | 98284 | 1.64041666667 | 17216 |
| 016404 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:38pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597120.6 | 513289.3 | 98286 | 1.64041666667 | 16404 |
| 015362 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:39pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597123.7 | 513288.1 | 98288 | 1.64041666667 | 15362 |
| 015121 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:40pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597127.0 | 513288.3 | 98290 | 1.64041666667 | 15121 |
| 016140 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:41pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597130.8 | 513288.6 | 98292 | 1.64041666667 | 16140 |
| 014756 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:42pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597134.1 | 513288.7 | 98294 | 1.64041666667 | 14756 |
| 015088 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:43pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597137.9 | 513289.3 | 98296 | 1.64041666667 | 15088 |
| 015912 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:44pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597141.1 | 513289.8 | 98298 | 1.64041666667 | 15912 |
| 017163 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:45pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597145.2 | 513290.0 | 98300 | 1.64041666667 | 17163 |
| 018286 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:46pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597148.3 | 513290.1 | 98302 | 1.64041666667 | 18286 |
| 018911 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:47pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597151.5 | 513290.8 | 98304 | 1.64041666667 | 18911 |
| 017635 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:48pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597154.6 | 513291.8 | 98306 | 1.64041666667 | 17635 |
| 016699 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:49pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597158.0 | 513293.0 | 98308 | 1.64041666667 | 16699 |
| 016136 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:50pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597161.5 | 513293.5 | 98310 | 1.64041666667 | 16136 |
| 015639 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:51pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597165.2 | 513293.8 | 98312 | 1.64041666667 | 15639 |
| 014834 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:52pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597168.0 | 513293.8 | 98314 | 1.64041666667 | 14834 |
| 014501 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:53pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597171.6 | 513293.6 | 98316 | 1.64041666667 | 14501 |
| 014637 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:54pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597174.7 | 513293.7 | 98318 | 1.64041666667 | 14637 |
| 014413 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:55pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597178.1 | 513293.6 | 98320 | 1.64041666667 | 14413 |
| 013560 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:56pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597181.2 | 513293.1 | 98322 | 1.64041666667 | 13560 |
| 015135 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:57pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597184.9 | 513293.0 | 98324 | 1.64041666667 | 15135 |
| 014581 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:58pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597187.7 | 513293.4 | 98326 | 1.64041666667 | 14581 |
| 014606 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:59pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597190.4 | 513292.6 | 98328 | 1.64041666667 | 14606 |
| 014156 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:00pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597193.0 | 513292.5 | 98330 | 1.64041666667 | 14156 |
| 014038 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:01pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597196.1 | 513293.2 | 98332 | 1.64041666667 | 14038 |
| 014016 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:02pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597198.7 | 513294.1 | 98334 | 1.64041666667 | 14016 |
| 015076 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:03pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597201.5 | 513296.1 | 98336 | 1.64041666667 | 15076 |
| 014608 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:04pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597202.8 | 513297.6 | 98338 | 1.64041666667 | 14608 |
| 016114 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:05pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597204.5 | 513299.1 | 98340 | 1.64041666667 | 16114 |
| 015334 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:06pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597205.7 | 513299.9 | 98342 | 1.64041666667 | 15334 |
| 015023 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:07pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597207.2 | 513298.8 | 98344 | 1.64041666667 | 15023 |
| 015800 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:08pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597207.7 | 513298.2 | 98346 | 1.64041666667 | 15800 |
| 014707 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:09pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597207.9 | 513298.1 | 98348 | 1.64041666667 | 14707 |
| 015968 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:10pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597207.9 | 513298.1 | 98350 | 1.64041666667 | 15968 |
| 014929 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:11pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597207.8 | 513298.1 | 98352 | 1.64041666667 | 14929 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014960 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:12pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597207.7 | 513298.1 | 98354 | 1.64041666667 | 14960 |
| 014550 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:13pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597207.6 | 513298.1 | 98356 | 1.64041666667 | 14550 |
| 014949 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:14pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597207.6 | 513297.9 | 98358 | 1.64041666667 | 14949 |
| 014424 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:15pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597207.4 | 513297.3 | 98360 | 1.64041666667 | 14424 |
| 014076 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:16pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597206.0 | 513296.2 | 98362 | 1.64041666667 | 14076 |
| 014195 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:17pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597203.3 | 513294.8 | 98364 | 1.64041666667 | 14195 |
| 014322 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:18pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597200.6 | 513293.2 | 98366 | 1.64041666667 | 14322 |
| 014678 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:19pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597196.8 | 513291.9 | 98368 | 1.64041666667 | 14678 |
| 014294 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:20pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597193.6 | 513291.4 | 98370 | 1.64041666667 | 14294 |
| 013733 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:21pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597189.7 | 513290.8 | 98372 | 1.64041666667 | 13733 |
| 014235 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:22pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597186.4 | 513290.0 | 98374 | 1.64041666667 | 14235 |
| 014239 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:23pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597182.6 | 513289.1 | 98376 | 1.64041666667 | 14239 |
| 014024 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:24pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597179.1 | 513288.9 | 98378 | 1.64041666667 | 14024 |
| 014706 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:25pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597175.4 | 513288.7 | 98380 | 1.64041666667 | 14706 |
| 014287 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:26pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597172.0 | 513288.1 | 98382 | 1.64041666667 | 14287 |
| 014516 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:27pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597167.7 | 513287.1 | 98384 | 1.64041666667 | 14516 |
| 015080 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:28pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597164.5 | 513286.6 | 98386 | 1.64041666667 | 15080 |
| 016027 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:29pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597160.3 | 513286.4 | 98388 | 1.64041666667 | 16027 |
| 016193 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:30pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597156.9 | 513286.0 | 98390 | 1.64041666667 | 16193 |
| 017088 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:31pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597152.8 | 513285.3 | 98392 | 1.64041666667 | 17088 |
| 015942 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:32pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597149.4 | 513285.3 | 98394 | 1.64041666667 | 15942 |
| 016145 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:33pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597145.9 | 513285.1 | 98396 | 1.64041666667 | 16145 |
| 015914 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:34pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597142.4 | 513284.5 | 98398 | 1.64041666667 | 15914 |
| 015191 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:35pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597138.6 | 513283.8 | 98400 | 1.64041666667 | 15191 |
| 015505 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:36pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597135.0 | 513283.8 | 98402 | 1.64041666667 | 15505 |
| 014661 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:37pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597131.3 | 513284.3 | 98404 | 1.64041666667 | 14661 |
| 015582 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:38pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597127.6 | 513284.6 | 98406 | 1.64041666667 | 15582 |
| 016407 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:39pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597123.8 | 513284.0 | 98408 | 1.64041666667 | 16407 |
| 015829 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:40pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597120.7 | 513283.3 | 98410 | 1.64041666667 | 15829 |
| 015271 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:41pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597116.8 | 513282.8 | 98412 | 1.64041666667 | 15271 |
| 015302 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:42pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597113.8 | 513282.8 | 98414 | 1.64041666667 | 15302 |
| 014900 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:43pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597109.9 | 513282.8 | 98416 | 1.64041666667 | 14900 |
| 015348 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:44pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597106.5 | 513282.6 | 98418 | 1.64041666667 | 15348 |
| 017371 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:45pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597102.8 | 513282.6 | 98420 | 1.64041666667 | 17371 |
| 016611 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:46pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597099.8 | 513282.8 | 98422 | 1.64041666667 | 16611 |
| 015824 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:47pm | Sensor | 1797-S0057-G-637-DTE | 6854.3 | 1597097.3 | 513282.3 | 98424 | 1.64041666667 | 15824 |
| 016146 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:48pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597097.8 | 513281.0 | 98426 | 1.64041666667 | 16146 |
| 015704 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:49pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597099.0 | 513278.4 | 98428 | 1.64041666667 | 15704 |
| 016334 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:50pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597099.4 | 513276.2 | 98430 | 1.64041666667 | 16334 |
| 016545 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:51pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597100.5 | 513274.2 | 98432 | 1.64041666667 | 16545 |
| 016604 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:52pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597100.8 | 513272.5 | 98434 | 1.64041666667 | 16604 |
| 015865 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:53pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597101.1 | 513271.9 | 98436 | 1.64041666667 | 15865 |
| 015329 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:54pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597101.4 | 513271.9 | 98438 | 1.64041666667 | 15329 |
| 016595 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:55pm | Sensor | 1797-S0057-G-637-DTE | 6854.6 | 1597102.3 | 513270.9 | 98440 | 1.64041666667 | 16595 |
| 016189 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:56pm | Sensor | 1797-S0057-G-637-DTE | 6854.6 | 1597104.2 | 513271.7 | 98442 | 1.64041666667 | 16189 |
| 017221 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:57pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597107.3 | 513273.8 | 98444 | 1.64041666667 | 17221 |
| 016219 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:58pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597110.5 | 513274.7 | 98446 | 1.64041666667 | 16219 |
| 015791 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:59pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597114.5 | 513275.6 | 98448 | 1.64041666667 | 15791 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015182 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:00pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597117.8 | 513276.2 | 98450 | 1.64041666667 | 15182 |
| 014937 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:01pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597122.2 | 513276.3 | 98452 | 1.64041666667 | 14937 |
| 013765 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:02pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597125.1 | 513276.3 | 98454 | 1.64041666667 | 13765 |
| 013472 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:03pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597128.9 | 513276.9 | 98456 | 1.64041666667 | 13472 |
| 014456 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:04pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597132.0 | 513277.8 | 98458 | 1.64041666667 | 14456 |
| 014626 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:05pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597135.9 | 513278.3 | 98460 | 1.64041666667 | 14626 |
| 015165 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:06pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597139.2 | 513278.2 | 98462 | 1.64041666667 | 15165 |
| 015460 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:07pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597143.4 | 513278.2 | 98464 | 1.64041666667 | 15460 |
| 015131 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:08pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597147.0 | 513278.4 | 98466 | 1.64041666667 | 15131 |
| 014804 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:09pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597151.1 | 513278.8 | 98468 | 1.64041666667 | 14804 |
| 014994 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:10pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597154.5 | 513278.8 | 98470 | 1.64041666667 | 14994 |
| 015057 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:11pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597158.8 | 513279.0 | 98472 | 1.64041666667 | 15057 |
| 015377 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:12pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597162.1 | 513279.4 | 98474 | 1.64041666667 | 15377 |
| 014964 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:13pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597166.5 | 513279.8 | 98476 | 1.64041666667 | 14964 |
| 014725 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:14pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597170.1 | 513280.1 | 98478 | 1.64041666667 | 14725 |
| 014365 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:15pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597174.2 | 513280.6 | 98480 | 1.64041666667 | 14365 |
| 015723 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:16pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597177.6 | 513281.2 | 98482 | 1.64041666667 | 15723 |
| 014641 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:17pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597181.7 | 513281.7 | 98484 | 1.64041666667 | 14641 |
| 014160 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:18pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597185.2 | 513282.3 | 98486 | 1.64041666667 | 14160 |
| 014273 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:19pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597189.2 | 513283.2 | 98488 | 1.64041666667 | 14273 |
| 014216 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:20pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597192.5 | 513284.5 | 98490 | 1.64041666667 | 14216 |
| 015594 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:21pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597196.2 | 513285.7 | 98492 | 1.64041666667 | 15594 |
| 015604 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:22pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597199.2 | 513285.8 | 98494 | 1.64041666667 | 15604 |
| 015324 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:23pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597202.7 | 513286.5 | 98496 | 1.64041666667 | 15324 |
| 014747 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:24pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597205.6 | 513287.8 | 98498 | 1.64041666667 | 14747 |
| 015038 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:25pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597209.3 | 513289.2 | 98500 | 1.64041666667 | 15038 |
| 014774 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:26pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597212.1 | 513289.9 | 98502 | 1.64041666667 | 14774 |
| 014392 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:27pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597215.2 | 513291.2 | 98504 | 1.64041666667 | 14392 |
| 013398 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:28pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597217.3 | 513289.7 | 98506 | 1.64041666667 | 13398 |
| 013536 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:29pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597218.1 | 513286.9 | 98508 | 1.64041666667 | 13536 |
| 013936 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:30pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597217.4 | 513284.2 | 98510 | 1.64041666667 | 13936 |
| 014387 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:31pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597215.1 | 513281.4 | 98512 | 1.64041666667 | 14387 |
| 014760 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:32pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597212.5 | 513279.8 | 98514 | 1.64041666667 | 14760 |
| 014347 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:33pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597209.2 | 513278.5 | 98516 | 1.64041666667 | 14347 |
| 014280 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:34pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597205.9 | 513277.6 | 98518 | 1.64041666667 | 14280 |
| 014940 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:35pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597201.7 | 513277.1 | 98520 | 1.64041666667 | 14940 |
| 015228 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:36pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597198.0 | 513277.3 | 98522 | 1.64041666667 | 15228 |
| 015248 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:37pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597194.0 | 513276.9 | 98524 | 1.64041666667 | 15248 |
| 014712 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:38pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597190.8 | 513276.5 | 98526 | 1.64041666667 | 14712 |
| 015565 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:39pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597186.9 | 513276.2 | 98528 | 1.64041666667 | 15565 |
| 016420 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:40pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597183.4 | 513276.5 | 98530 | 1.64041666667 | 16420 |
| 017179 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:41pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597179.7 | 513276.9 | 98532 | 1.64041666667 | 17179 |
| 017200 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:42pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597176.5 | 513276.5 | 98534 | 1.64041666667 | 17200 |
| 016875 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:43pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597172.6 | 513275.7 | 98536 | 1.64041666667 | 16875 |
| 016369 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:44pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597169.0 | 513275.5 | 98538 | 1.64041666667 | 16369 |
| 015628 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:45pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597165.4 | 513275.9 | 98540 | 1.64041666667 | 15628 |
| 016208 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:46pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597162.6 | 513276.1 | 98542 | 1.64041666667 | 16208 |
| 015342 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:47pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597158.8 | 513275.5 | 98544 | 1.64041666667 | 15342 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015537 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:48pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597155.5 | 513275.0 | 98546 | 1.64041666667 | 15537 |
| 014634 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:49pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597151.7 | 513274.8 | 98548 | 1.64041666667 | 14634 |
| 015889 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:50pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597148.6 | 513274.8 | 98550 | 1.64041666667 | 15889 |
| 015575 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:51pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597144.9 | 513274.2 | 98552 | 1.64041666667 | 15575 |
| 015556 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:52pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597141.9 | 513273.6 | 98554 | 1.64041666667 | 15556 |
| 015087 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:53pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597138.4 | 513273.7 | 98556 | 1.64041666667 | 15087 |
| 014696 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:54pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597136.6 | 513273.8 | 98558 | 1.64041666667 | 14696 |
| 014289 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:55pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597136.0 | 513273.8 | 98560 | 1.64041666667 | 14289 |
| 014240 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:56pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597135.0 | 513273.4 | 98562 | 1.64041666667 | 14240 |
| 014475 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:57pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597132.5 | 513271.8 | 98564 | 1.64041666667 | 14475 |
| 014982 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:58pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597129.7 | 513271.2 | 98566 | 1.64041666667 | 14982 |
| 014615 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:59pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597125.8 | 513271.4 | 98568 | 1.64041666667 | 14615 |
| 014213 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:00pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597122.7 | 513271.3 | 98570 | 1.64041666667 | 14213 |
| 015052 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:01pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597118.9 | 513270.4 | 98572 | 1.64041666667 | 15052 |
| 016012 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:02pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597115.6 | 513269.7 | 98574 | 1.64041666667 | 16012 |
| 015569 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:03pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597111.8 | 513269.3 | 98576 | 1.64041666667 | 15569 |
| 015230 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:04pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597108.8 | 513269.2 | 98578 | 1.64041666667 | 15230 |
| 014477 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:05pm | Sensor | 1797-S0057-G-637-DTE | 6854.6 | 1597104.4 | 513268.8 | 98580 | 1.64041666667 | 14477 |
| 014968 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:06pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597101.4 | 513268.3 | 98582 | 1.64041666667 | 14968 |
| 015777 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:07pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597098.0 | 513267.3 | 98584 | 1.64041666667 | 15777 |
| 015564 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:08pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597095.4 | 513266.6 | 98586 | 1.64041666667 | 15564 |
| 015752 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:09pm | Sensor | 1797-S0057-G-637-DTE | 6854.2 | 1597094.1 | 513264.4 | 98588 | 1.64041666667 | 15752 |
| 016248 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:10pm | Sensor | 1797-S0057-G-637-DTE | 6854.3 | 1597094.8 | 513262.3 | 98590 | 1.64041666667 | 16248 |
| 015514 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:11pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597096.4 | 513259.5 | 98592 | 1.64041666667 | 15514 |
| 016204 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:12pm | Sensor | 1797-S0057-G-637-DTE | 6854.4 | 1597098.0 | 513258.1 | 98594 | 1.64041666667 | 16204 |
| 015257 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:13pm | Sensor | 1797-S0057-G-637-DTE | 6854.5 | 1597100.7 | 513257.3 | 98596 | 1.64041666667 | 15257 |
| 015617 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:14pm | Sensor | 1797-S0057-G-637-DTE | 6854.6 | 1597104.1 | 513257.3 | 98598 | 1.64041666667 | 15617 |
| 014439 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:15pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597107.8 | 513257.6 | 98600 | 1.64041666667 | 14439 |
| 015450 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:16pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597111.1 | 513258.4 | 98602 | 1.64041666667 | 15450 |
| 014630 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:17pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597115.0 | 513259.6 | 98604 | 1.64041666667 | 14630 |
| 014649 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:18pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597117.6 | 513260.7 | 98606 | 1.64041666667 | 14649 |
| 014195 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:19pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597120.6 | 513262.3 | 98608 | 1.64041666667 | 14195 |
| 015252 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:20pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597123.6 | 513263.8 | 98610 | 1.64041666667 | 15252 |
| 015502 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:21pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597127.4 | 513264.6 | 98612 | 1.64041666667 | 15502 |
| 014607 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:22pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597131.0 | 513264.6 | 98614 | 1.64041666667 | 14607 |
| 015994 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:23pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597134.9 | 513264.9 | 98616 | 1.64041666667 | 15994 |
| 015679 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:24pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597138.6 | 513265.9 | 98618 | 1.64041666667 | 15679 |
| 014992 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:25pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597142.4 | 513267.3 | 98620 | 1.64041666667 | 14992 |
| 015363 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:26pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597145.4 | 513267.9 | 98622 | 1.64041666667 | 15363 |
| 014746 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:27pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597149.3 | 513268.0 | 98624 | 1.64041666667 | 14746 |
| 015000 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:28pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597152.6 | 513268.4 | 98626 | 1.64041666667 | 15000 |
| 015255 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:29pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597156.4 | 513269.1 | 98628 | 1.64041666667 | 15255 |
| 015008 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:30pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597160.3 | 513269.8 | 98630 | 1.64041666667 | 15008 |
| 015252 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:31pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597163.9 | 513270.3 | 98632 | 1.64041666667 | 15252 |
| 015689 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:32pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597167.5 | 513271.2 | 98634 | 1.64041666667 | 15689 |
| 015395 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:33pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597171.3 | 513272.4 | 98636 | 1.64041666667 | 15395 |
| 014832 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:34pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597175.0 | 513273.3 | 98638 | 1.64041666667 | 14832 |
| 015978 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:35pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597178.4 | 513273.9 | 98640 | 1.64041666667 | 15978 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016442 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:36pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597181.6 | 513274.6 | 98642 | 1.64041666667 | 16442 |
| 016494 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:37pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597185.1 | 513275.6 | 98644 | 1.64041666667 | 16494 |
| 015705 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:38pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597188.1 | 513276.3 | 98646 | 1.64041666667 | 15705 |
| 015284 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:39pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597191.8 | 513276.3 | 98648 | 1.64041666667 | 15284 |
| 015497 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:40pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597195.3 | 513276.4 | 98650 | 1.64041666667 | 15497 |
| 015129 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:41pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597199.4 | 513276.9 | 98652 | 1.64041666667 | 15129 |
| 015478 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:42pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597202.7 | 513277.2 | 98654 | 1.64041666667 | 15478 |
| 014586 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:43pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597206.6 | 513277.8 | 98656 | 1.64041666667 | 14586 |
| 014287 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:44pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597209.8 | 513278.9 | 98658 | 1.64041666667 | 14287 |
| 014494 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:45pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597213.7 | 513279.6 | 98660 | 1.64041666667 | 14494 |
| 014235 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:46pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597216.9 | 513279.8 | 98662 | 1.64041666667 | 14235 |
| 014412 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:47pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597219.7 | 513279.3 | 98664 | 1.64041666667 | 14412 |
| 014947 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:48pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597221.8 | 513277.5 | 98666 | 1.64041666667 | 14947 |
| 014445 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:49pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597223.4 | 513274.4 | 98668 | 1.64041666667 | 14445 |
| 014658 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:50pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597222.1 | 513272.0 | 98670 | 1.64041666667 | 14658 |
| 015430 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:51pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597219.0 | 513271.0 | 98672 | 1.64041666667 | 15430 |
| 015084 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:52pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597215.9 | 513270.5 | 98674 | 1.64041666667 | 15084 |
| 015062 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:53pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597212.2 | 513269.8 | 98676 | 1.64041666667 | 15062 |
| 015012 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:54pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597208.8 | 513269.4 | 98678 | 1.64041666667 | 15012 |
| 014962 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:55pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597204.9 | 513268.8 | 98680 | 1.64041666667 | 14962 |
| 015001 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:56pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597201.8 | 513267.8 | 98682 | 1.64041666667 | 15001 |
| 015660 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:57pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597198.4 | 513266.6 | 98684 | 1.64041666667 | 15660 |
| 015566 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:58pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597195.3 | 513265.8 | 98686 | 1.64041666667 | 15566 |
| 015731 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:59pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597191.5 | 513265.3 | 98688 | 1.64041666667 | 15731 |
| 016596 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:00pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597188.3 | 513265.0 | 98690 | 1.64041666667 | 16596 |
| 016408 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:01pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597184.3 | 513264.5 | 98692 | 1.64041666667 | 16408 |
| 015401 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:02pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597181.3 | 513264.4 | 98694 | 1.64041666667 | 15401 |
| 015848 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:03pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597177.8 | 513264.9 | 98696 | 1.64041666667 | 15848 |
| 016009 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:04pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597175.1 | 513264.6 | 98698 | 1.64041666667 | 16009 |
| 016595 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:05pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597172.0 | 513263.5 | 98700 | 1.64041666667 | 16595 |
| 015492 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:06pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597169.5 | 513262.7 | 98702 | 1.64041666667 | 15492 |
| 015967 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:07pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597166.1 | 513261.5 | 98704 | 1.64041666667 | 15967 |
| 015828 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:08pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597163.0 | 513260.6 | 98706 | 1.64041666667 | 15828 |
| 015953 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:09pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597159.5 | 513259.9 | 98708 | 1.64041666667 | 15953 |
| 016001 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:10pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597156.2 | 513259.5 | 98710 | 1.64041666667 | 16001 |
| 015743 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:11pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597152.8 | 513258.5 | 98712 | 1.64041666667 | 15743 |
| 015508 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:12pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597149.8 | 513257.4 | 98714 | 1.64041666667 | 15508 |
| 014685 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:13pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597146.1 | 513257.1 | 98716 | 1.64041666667 | 14685 |
| 014081 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:14pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597142.9 | 513257.4 | 98718 | 1.64041666667 | 14081 |
| 013913 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:15pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597139.1 | 513257.2 | 98720 | 1.64041666667 | 13913 |
| 014103 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:16pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597136.1 | 513256.4 | 98722 | 1.64041666667 | 14103 |
| 014443 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:17pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597132.3 | 513255.3 | 98724 | 1.64041666667 | 14443 |
| 014124 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:18pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597129.1 | 513255.0 | 98726 | 1.64041666667 | 14124 |
| 014245 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:19pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597125.6 | 513254.8 | 98728 | 1.64041666667 | 14245 |
| 014845 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:20pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597122.5 | 513254.4 | 98730 | 1.64041666667 | 14845 |
| 014448 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:21pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597118.9 | 513253.9 | 98732 | 1.64041666667 | 14448 |
| 014314 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:22pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597115.6 | 513253.1 | 98734 | 1.64041666667 | 14314 |
| 014899 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:23pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597112.2 | 513251.8 | 98736 | 1.64041666667 | 14899 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016226 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:24pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597109.5 | 513250.6 | 98738 | 1.64041666667 | 16226 |
| 018202 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:25pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597106.4 | 513249.3 | 98740 | 1.64041666667 | 18202 |
| 019133 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:26pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597103.4 | 513248.9 | 98742 | 1.64041666667 | 19133 |
| 018480 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:27pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597100.4 | 513248.8 | 98744 | 1.64041666667 | 18480 |
| 017527 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:28pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597098.3 | 513248.4 | 98746 | 1.64041666667 | 17527 |
| 016744 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:29pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597097.2 | 513247.5 | 98748 | 1.64041666667 | 16744 |
| 016108 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:30pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597097.8 | 513246.3 | 98750 | 1.64041666667 | 16108 |
| 015353 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:31pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597100.1 | 513246.7 | 98752 | 1.64041666667 | 15353 |
| 016496 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:32pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597102.5 | 513247.4 | 98754 | 1.64041666667 | 16496 |
| 017806 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:33pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597104.9 | 513245.9 | 98756 | 1.64041666667 | 17806 |
| 019331 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:34pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597106.3 | 513243.9 | 98758 | 1.64041666667 | 19331 |
| 022004 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:35pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597107.3 | 513241.4 | 98760 | 1.64041666667 | 22004 |
| 023169 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:36pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597107.7 | 513240.2 | 98762 | 1.64041666667 | 23169 |
| 023060 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:37pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597107.5 | 513240.3 | 98764 | 1.64041666667 | 23060 |
| 022931 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:38pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597107.0 | 513240.8 | 98766 | 1.64041666667 | 22931 |
| 022536 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:39pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597106.6 | 513241.6 | 98768 | 1.64041666667 | 22536 |
| 022696 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:40pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597106.3 | 513242.2 | 98770 | 1.64041666667 | 22696 |
| 021129 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:41pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597106.3 | 513242.3 | 98772 | 1.64041666667 | 21129 |
| 022085 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:42pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597106.4 | 513241.0 | 98774 | 1.64041666667 | 22085 |
| 021978 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:43pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597107.4 | 513238.8 | 98776 | 1.64041666667 | 21978 |
| 022907 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:44pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597108.1 | 513237.1 | 98778 | 1.64041666667 | 22907 |
| 021788 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:45pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597109.0 | 513235.8 | 98780 | 1.64041666667 | 21788 |
| 019328 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:46pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597108.2 | 513236.3 | 98782 | 1.64041666667 | 19328 |
| 020157 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:47pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597107.2 | 513237.1 | 98784 | 1.64041666667 | 20157 |
| 023361 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:48pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597106.9 | 513237.5 | 98786 | 1.64041666667 | 23361 |
| 025875 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:49pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597106.9 | 513237.5 | 98788 | 1.64041666667 | 25875 |
| 026150 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:50pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597106.9 | 513237.5 | 98790 | 1.64041666667 | 26150 |
| 025209 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:51pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.0 | 513237.5 | 98792 | 1.64041666667 | 25209 |
| 025362 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:52pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.0 | 513237.6 | 98794 | 1.64041666667 | 25362 |
| 024984 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:53pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597107.6 | 513237.2 | 98796 | 1.64041666667 | 24984 |
| 025581 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:54pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597107.9 | 513237.5 | 98798 | 1.64041666667 | 25581 |
| 026171 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:55pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.8 | 98800 | 1.64041666667 | 26171 |
| 025979 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:56pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597107.8 | 513237.8 | 98802 | 1.64041666667 | 25979 |
| 026350 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:57pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.8 | 98804 | 1.64041666667 | 26350 |
| 028134 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:58pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.9 | 98806 | 1.64041666667 | 28134 |
| 029198 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:59pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.9 | 98808 | 1.64041666667 | 29198 |
| 028536 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:00pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.9 | 98810 | 1.64041666667 | 28536 |
| 028659 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:01pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.8 | 98812 | 1.64041666667 | 28659 |
| 027963 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:02pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.8 | 98814 | 1.64041666667 | 27963 |
| 027954 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:03pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.8 | 98816 | 1.64041666667 | 27954 |
| 029149 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:04pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597107.9 | 513237.8 | 98818 | 1.64041666667 | 29149 |
| 027714 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:05pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597107.8 | 513237.8 | 98820 | 1.64041666667 | 27714 |
| 028706 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:06pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597107.9 | 513237.9 | 98822 | 1.64041666667 | 28706 |
| 030765 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:07pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597108.0 | 513237.9 | 98824 | 1.64041666667 | 30765 |
| 031982 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:08pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597108.0 | 513237.9 | 98826 | 1.64041666667 | 31982 |
| 032592 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:09pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597108.0 | 513237.9 | 98828 | 1.64041666667 | 32592 |
| 033948 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:10pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597108.0 | 513237.9 | 98830 | 1.64041666667 | 33948 |
| 033016 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:11pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597108.0 | 513237.9 | 98832 | 1.64041666667 | 33016 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 035169 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:12pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597108.0 | 513237.9 | 98834 | 1.64041666667 | 35169 |
| 034422 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:13pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597108.0 | 513237.9 | 98836 | 1.64041666667 | 34422 |
| 033815 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:14pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597108.0 | 513237.9 | 98838 | 1.64041666667 | 33815 |
| 035206 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:15pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597108.0 | 513237.9 | 98840 | 1.64041666667 | 35206 |
| 022025 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:36pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597106.5 | 513236.5 | 98843 | 1.64041666667 | 22025 |
| 021944 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:37pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597106.5 | 513236.5 | 98845 | 1.64041666667 | 21944 |
| 021208 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:38pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597106.5 | 513236.6 | 98847 | 1.64041666667 | 21208 |
| 021199 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:39pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597106.8 | 513236.5 | 98849 | 1.64041666667 | 21199 |
| 020280 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:40pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597107.6 | 513236.4 | 98851 | 1.64041666667 | 20280 |
| 021215 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:41pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597109.1 | 513236.4 | 98853 | 1.64041666667 | 21215 |
| 021796 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:42pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597111.2 | 513236.2 | 98855 | 1.64041666667 | 21796 |
| 018372 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:43pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597114.3 | 513235.9 | 98857 | 1.64041666667 | 18372 |
| 016942 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:44pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597117.6 | 513236.4 | 98859 | 1.64041666667 | 16942 |
| 015335 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:45pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597121.2 | 513237.4 | 98861 | 1.64041666667 | 15335 |
| 015750 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:46pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597124.7 | 513237.9 | 98863 | 1.64041666667 | 15750 |
| 015302 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:47pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597128.0 | 513238.3 | 98865 | 1.64041666667 | 15302 |
| 014547 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:48pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597130.7 | 513239.4 | 98867 | 1.64041666667 | 14547 |
| 014303 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:49pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597134.0 | 513240.7 | 98869 | 1.64041666667 | 14303 |
| 015013 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:50pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597136.2 | 513241.2 | 98871 | 1.64041666667 | 15013 |
| 014857 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:51pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597137.0 | 513241.6 | 98873 | 1.64041666667 | 14857 |
| 014649 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:52pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597136.6 | 513243.1 | 98875 | 1.64041666667 | 14649 |
| 015095 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:53pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597134.3 | 513244.9 | 98877 | 1.64041666667 | 15095 |
| 014656 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:54pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597130.9 | 513245.4 | 98879 | 1.64041666667 | 14656 |
| 014229 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:55pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597126.5 | 513246.0 | 98881 | 1.64041666667 | 14229 |
| 015863 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:56pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597122.8 | 513246.7 | 98883 | 1.64041666667 | 15863 |
| 015111 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:57pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597118.9 | 513246.7 | 98885 | 1.64041666667 | 15111 |
| 014620 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:58pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597115.8 | 513245.4 | 98887 | 1.64041666667 | 14620 |
| 014816 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:59pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597113.4 | 513243.1 | 98889 | 1.64041666667 | 14816 |
| 013951 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:00pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597113.2 | 513241.5 | 98891 | 1.64041666667 | 13951 |
| 013412 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:01pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597115.9 | 513241.2 | 98893 | 1.64041666667 | 13412 |
| 014289 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:02pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597119.5 | 513242.4 | 98895 | 1.64041666667 | 14289 |
| 014297 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:03pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597123.2 | 513243.7 | 98897 | 1.64041666667 | 14297 |
| 014612 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:04pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597126.1 | 513244.5 | 98899 | 1.64041666667 | 14612 |
| 014264 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:05pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597129.3 | 513245.8 | 98901 | 1.64041666667 | 14264 |
| 014121 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:06pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597131.6 | 513247.1 | 98903 | 1.64041666667 | 14121 |
| 013635 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:07pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597135.5 | 513248.8 | 98905 | 1.64041666667 | 13635 |
| 014870 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:08pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597139.1 | 513249.7 | 98907 | 1.64041666667 | 14870 |
| 014972 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:09pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597143.1 | 513250.3 | 98909 | 1.64041666667 | 14972 |
| 015479 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:10pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597146.7 | 513250.7 | 98911 | 1.64041666667 | 15479 |
| 014864 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:11pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597151.0 | 513251.4 | 98913 | 1.64041666667 | 14864 |
| 014361 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:12pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597155.0 | 513252.4 | 98915 | 1.64041666667 | 14361 |
| 013748 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:13pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597158.8 | 513253.4 | 98917 | 1.64041666667 | 13748 |
| 014160 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:14pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597161.5 | 513253.9 | 98919 | 1.64041666667 | 14160 |
| 013905 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:15pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597163.9 | 513253.7 | 98921 | 1.64041666667 | 13905 |
| 015179 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:16pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597165.5 | 513253.0 | 98923 | 1.64041666667 | 15179 |
| 014756 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:17pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597166.7 | 513251.0 | 98925 | 1.64041666667 | 14756 |
| 015470 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:18pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597167.5 | 513249.7 | 98927 | 1.64041666667 | 15470 |
| 016772 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:19pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597168.4 | 513248.1 | 98929 | 1.64041666667 | 16772 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016049 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:20pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597169.9 | 513246.0 | 98931 | 1.64041666667 | 16049 |
| 015740 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:21pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597171.1 | 513243.5 | 98933 | 1.64041666667 | 15740 |
| 016233 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:22pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597173.1 | 513241.7 | 98935 | 1.64041666667 | 16233 |
| 016264 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:23pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597175.9 | 513240.5 | 98937 | 1.64041666667 | 16264 |
| 015268 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:24pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597178.3 | 513241.2 | 98939 | 1.64041666667 | 15268 |
| 015901 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:25pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597180.1 | 513243.3 | 98941 | 1.64041666667 | 15901 |
| 014861 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:26pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597181.7 | 513245.4 | 98943 | 1.64041666667 | 14861 |
| 014832 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:27pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597183.1 | 513247.6 | 98945 | 1.64041666667 | 14832 |
| 014545 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:28pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597183.7 | 513250.0 | 98947 | 1.64041666667 | 14545 |
| 014579 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:29pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597184.7 | 513252.2 | 98949 | 1.64041666667 | 14579 |
| 014426 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:30pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597185.6 | 513254.5 | 98951 | 1.64041666667 | 14426 |
| 014662 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:31pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597187.5 | 513257.3 | 98953 | 1.64041666667 | 14662 |
| 016730 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:32pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597190.0 | 513258.6 | 98955 | 1.64041666667 | 16730 |
| 016370 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:33pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597192.4 | 513261.0 | 98957 | 1.64041666667 | 16370 |
| 017811 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:34pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597194.3 | 513263.3 | 98959 | 1.64041666667 | 17811 |
| 016858 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:35pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597197.5 | 513265.0 | 98961 | 1.64041666667 | 16858 |
| 015543 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:36pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597200.2 | 513265.7 | 98963 | 1.64041666667 | 15543 |
| 015478 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:37pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597203.6 | 513266.8 | 98965 | 1.64041666667 | 15478 |
| 014331 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:38pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597207.2 | 513267.3 | 98967 | 1.64041666667 | 14331 |
| 014811 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:39pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597211.2 | 513267.6 | 98969 | 1.64041666667 | 14811 |
| 014324 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:40pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597214.4 | 513268.5 | 98971 | 1.64041666667 | 14324 |
| 015122 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:41pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597217.4 | 513269.8 | 98973 | 1.64041666667 | 15122 |
| 015511 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:42pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597220.0 | 513271.0 | 98975 | 1.64041666667 | 15511 |
| 014845 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:43pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597222.5 | 513271.7 | 98977 | 1.64041666667 | 14845 |
| 015483 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:44pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597224.6 | 513270.6 | 98979 | 1.64041666667 | 15483 |
| 014686 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:45pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597226.0 | 513268.1 | 98981 | 1.64041666667 | 14686 |
| 015183 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:46pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597226.7 | 513265.9 | 98983 | 1.64041666667 | 15183 |
| 015305 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:47pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597226.3 | 513263.0 | 98985 | 1.64041666667 | 15305 |
| 015862 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:48pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597224.4 | 513261.6 | 98987 | 1.64041666667 | 15862 |
| 016025 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:49pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597221.1 | 513260.0 | 98989 | 1.64041666667 | 16025 |
| 015674 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:50pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597217.6 | 513258.2 | 98991 | 1.64041666667 | 15674 |
| 015251 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:51pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597213.9 | 513256.5 | 98993 | 1.64041666667 | 15251 |
| 014534 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:52pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597210.7 | 513255.3 | 98995 | 1.64041666667 | 14534 |
| 013792 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:53pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597207.1 | 513254.1 | 98997 | 1.64041666667 | 13792 |
| 014756 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:54pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597204.5 | 513252.8 | 98999 | 1.64041666667 | 14756 |
| 014855 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:55pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597201.1 | 513251.1 | 99001 | 1.64041666667 | 14855 |
| 014918 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:56pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597198.1 | 513250.0 | 99003 | 1.64041666667 | 14918 |
| 015156 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:57pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597194.4 | 513248.5 | 99005 | 1.64041666667 | 15156 |
| 015485 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:58pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597191.8 | 513247.3 | 99007 | 1.64041666667 | 15485 |
| 015078 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:59pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597188.2 | 513245.7 | 99009 | 1.64041666667 | 15078 |
| 015276 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:00pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597184.9 | 513244.8 | 99011 | 1.64041666667 | 15276 |
| 015770 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:01pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597181.2 | 513243.5 | 99013 | 1.64041666667 | 15770 |
| 015193 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:02pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597178.1 | 513242.0 | 99015 | 1.64041666667 | 15193 |
| 015656 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:03pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597174.8 | 513240.5 | 99017 | 1.64041666667 | 15656 |
| 014799 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:04pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597171.7 | 513239.8 | 99019 | 1.64041666667 | 14799 |
| 014992 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:05pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597168.2 | 513238.9 | 99021 | 1.64041666667 | 14992 |
| 015618 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:06pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597165.6 | 513238.2 | 99023 | 1.64041666667 | 15618 |
| 014807 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:07pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597162.1 | 513238.4 | 99025 | 1.64041666667 | 14807 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014666 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:08pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597159.2 | 513239.0 | 99027 | 1.64041666667 | 14666 |
| 013927 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:09pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597156.6 | 513238.9 | 99029 | 1.64041666667 | 13927 |
| 014014 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:10pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597153.9 | 513238.6 | 99031 | 1.64041666667 | 14014 |
| 013485 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:11pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597150.9 | 513238.0 | 99033 | 1.64041666667 | 13485 |
| 013240 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:12pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597147.8 | 513237.1 | 99035 | 1.64041666667 | 13240 |
| 013590 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:13pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597144.3 | 513236.2 | 99037 | 1.64041666667 | 13590 |
| 013974 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:14pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597141.4 | 513235.1 | 99039 | 1.64041666667 | 13974 |
| 013455 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:15pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597138.4 | 513233.5 | 99041 | 1.64041666667 | 13455 |
| 012638 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:16pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597135.5 | 513232.6 | 99043 | 1.64041666667 | 12638 |
| 013432 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:17pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597132.4 | 513231.6 | 99045 | 1.64041666667 | 13432 |
| 013758 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:18pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597129.8 | 513230.6 | 99047 | 1.64041666667 | 13758 |
| 014286 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:19pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597127.3 | 513229.6 | 99049 | 1.64041666667 | 14286 |
| 014606 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:20pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597125.2 | 513227.7 | 99051 | 1.64041666667 | 14606 |
| 014793 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:21pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597123.0 | 513225.0 | 99053 | 1.64041666667 | 14793 |
| 014838 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:22pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597120.4 | 513223.1 | 99055 | 1.64041666667 | 14838 |
| 015389 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:23pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597117.4 | 513221.8 | 99057 | 1.64041666667 | 15389 |
| 014844 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:24pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597115.0 | 513220.2 | 99059 | 1.64041666667 | 14844 |
| 014792 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:25pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597113.4 | 513219.1 | 99061 | 1.64041666667 | 14792 |
| 014208 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:26pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597113.4 | 513217.5 | 99063 | 1.64041666667 | 14208 |
| 014209 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:27pm | Sensor | 1797-S0057-G-637-DTE | 6854.8 | 1597115.1 | 513215.7 | 99065 | 1.64041666667 | 14209 |
| 014142 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:28pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597117.8 | 513214.4 | 99067 | 1.64041666667 | 14142 |
| 014120 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:29pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597120.8 | 513214.1 | 99069 | 1.64041666667 | 14120 |
| 014535 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:30pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597124.0 | 513214.8 | 99071 | 1.64041666667 | 14535 |
| 014716 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:31pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597127.9 | 513216.5 | 99073 | 1.64041666667 | 14716 |
| 014157 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:32pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597131.0 | 513217.7 | 99075 | 1.64041666667 | 14157 |
| 015088 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:33pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597134.2 | 513218.6 | 99077 | 1.64041666667 | 15088 |
| 014172 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:34pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597137.2 | 513219.5 | 99079 | 1.64041666667 | 14172 |
| 014864 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:35pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597141.1 | 513221.1 | 99081 | 1.64041666667 | 14864 |
| 014293 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:36pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597144.2 | 513222.1 | 99083 | 1.64041666667 | 14293 |
| 014887 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:37pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597147.7 | 513222.8 | 99085 | 1.64041666667 | 14887 |
| 015566 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:38pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597150.9 | 513224.0 | 99087 | 1.64041666667 | 15566 |
| 014981 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:39pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597154.4 | 513225.2 | 99089 | 1.64041666667 | 14981 |
| 014569 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:40pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597157.3 | 513225.8 | 99091 | 1.64041666667 | 14569 |
| 014278 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:41pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597160.7 | 513226.8 | 99093 | 1.64041666667 | 14278 |
| 013648 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:42pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597162.9 | 513228.4 | 99095 | 1.64041666667 | 13648 |
| 013940 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:43pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597165.9 | 513230.7 | 99097 | 1.64041666667 | 13940 |
| 014156 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:44pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597168.8 | 513232.0 | 99099 | 1.64041666667 | 14156 |
| 013797 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:45pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597172.2 | 513233.4 | 99101 | 1.64041666667 | 13797 |
| 014841 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:46pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597175.2 | 513235.2 | 99103 | 1.64041666667 | 14841 |
| 014910 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:47pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597178.8 | 513236.8 | 99105 | 1.64041666667 | 14910 |
| 013854 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:48pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597181.8 | 513237.9 | 99107 | 1.64041666667 | 13854 |
| 014115 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:49pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597185.0 | 513239.1 | 99109 | 1.64041666667 | 14115 |
| 014352 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:50pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597187.3 | 513240.4 | 99111 | 1.64041666667 | 14352 |
| 014028 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:51pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597190.3 | 513242.2 | 99113 | 1.64041666667 | 14028 |
| 014663 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:52pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597193.2 | 513243.7 | 99115 | 1.64041666667 | 14663 |
| 014383 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:53pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597196.5 | 513245.3 | 99117 | 1.64041666667 | 14383 |
| 014503 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:54pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597199.9 | 513246.7 | 99119 | 1.64041666667 | 14503 |
| 014885 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:55pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597203.5 | 513248.0 | 99121 | 1.64041666667 | 14885 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014883 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:56pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597206.8 | 513249.1 | 99123 | 1.64041666667 | 14883 |
| 015519 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:57pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597210.2 | 513250.8 | 99125 | 1.64041666667 | 15519 |
| 015442 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:58pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597212.9 | 513252.7 | 99127 | 1.64041666667 | 15442 |
| 015076 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:59pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597216.5 | 513254.5 | 99129 | 1.64041666667 | 15076 |
| 016077 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:00pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597219.1 | 513255.2 | 99131 | 1.64041666667 | 16077 |
| 015628 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:01pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597222.6 | 513256.1 | 99133 | 1.64041666667 | 15628 |
| 016621 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:02pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597225.6 | 513256.6 | 99135 | 1.64041666667 | 16621 |
| 015851 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:03pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597228.7 | 513255.0 | 99137 | 1.64041666667 | 15851 |
| 015659 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:04pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597230.0 | 513252.7 | 99139 | 1.64041666667 | 15659 |
| 015468 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:05pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597230.6 | 513249.5 | 99141 | 1.64041666667 | 15468 |
| 015496 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:06pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597228.8 | 513247.6 | 99143 | 1.64041666667 | 15496 |
| 014896 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:07pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597225.5 | 513246.9 | 99145 | 1.64041666667 | 14896 |
| 015099 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:08pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597222.3 | 513246.0 | 99147 | 1.64041666667 | 15099 |
| 015371 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:09pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597218.7 | 513244.6 | 99149 | 1.64041666667 | 15371 |
| 014443 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:10pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597215.9 | 513243.6 | 99151 | 1.64041666667 | 14443 |
| 014222 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:11pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597211.8 | 513242.3 | 99153 | 1.64041666667 | 14222 |
| 013842 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:12pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597208.8 | 513241.3 | 99155 | 1.64041666667 | 13842 |
| 013523 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:13pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597205.0 | 513240.0 | 99157 | 1.64041666667 | 13523 |
| 013172 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:14pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597201.5 | 513238.9 | 99159 | 1.64041666667 | 13172 |
| 014609 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:15pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597197.6 | 513237.8 | 99161 | 1.64041666667 | 14609 |
| 013752 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:16pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597194.3 | 513236.1 | 99163 | 1.64041666667 | 13752 |
| 014711 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:17pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597191.1 | 513234.0 | 99165 | 1.64041666667 | 14711 |
| 014545 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:18pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597188.5 | 513232.4 | 99167 | 1.64041666667 | 14545 |
| 014046 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:19pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597185.1 | 513231.0 | 99169 | 1.64041666667 | 14046 |
| 014178 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:20pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597181.9 | 513229.7 | 99171 | 1.64041666667 | 14178 |
| 014898 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:21pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597178.3 | 513227.8 | 99173 | 1.64041666667 | 14898 |
| 014192 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:22pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597175.1 | 513226.0 | 99175 | 1.64041666667 | 14192 |
| 014778 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:23pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597171.5 | 513224.4 | 99177 | 1.64041666667 | 14778 |
| 015130 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:24pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597168.4 | 513223.6 | 99179 | 1.64041666667 | 15130 |
| 014510 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:25pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597164.3 | 513222.8 | 99181 | 1.64041666667 | 14510 |
| 015062 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:26pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597160.9 | 513222.1 | 99183 | 1.64041666667 | 15062 |
| 014622 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:27pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597156.9 | 513221.6 | 99185 | 1.64041666667 | 14622 |
| 014285 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:28pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597153.5 | 513221.4 | 99187 | 1.64041666667 | 14285 |
| 014598 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:29pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597149.3 | 513221.0 | 99189 | 1.64041666667 | 14598 |
| 014106 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:30pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597146.3 | 513219.9 | 99191 | 1.64041666667 | 14106 |
| 015067 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:31pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597142.3 | 513218.5 | 99193 | 1.64041666667 | 15067 |
| 014032 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:32pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597139.3 | 513217.7 | 99195 | 1.64041666667 | 14032 |
| 014013 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:33pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597135.8 | 513215.9 | 99197 | 1.64041666667 | 14013 |
| 014017 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:34pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597133.5 | 513213.7 | 99199 | 1.64041666667 | 14017 |
| 014087 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:35pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597130.6 | 513210.5 | 99201 | 1.64041666667 | 14087 |
| 014435 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:36pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597128.8 | 513207.8 | 99203 | 1.64041666667 | 14435 |
| 014801 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:37pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597128.3 | 513204.3 | 99205 | 1.64041666667 | 14801 |
| 014123 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:38pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597130.0 | 513201.8 | 99207 | 1.64041666667 | 14123 |
| 014604 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:39pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597133.4 | 513201.6 | 99209 | 1.64041666667 | 14604 |
| 014290 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:40pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597136.8 | 513202.8 | 99211 | 1.64041666667 | 14290 |
| 014330 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:41pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597141.3 | 513204.7 | 99213 | 1.64041666667 | 14330 |
| 015178 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:42pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597144.6 | 513206.3 | 99215 | 1.64041666667 | 15178 |
| 014710 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:43pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597148.4 | 513208.6 | 99217 | 1.64041666667 | 14710 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014462 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:44pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597151.6 | 513210.8 | 99219 | 1.64041666667 | 14462 |
| 014097 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:45pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597154.9 | 513213.2 | 99221 | 1.64041666667 | 14097 |
| 014492 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:46pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597158.1 | 513214.6 | 99223 | 1.64041666667 | 14492 |
| 014347 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:47pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597162.4 | 513216.3 | 99225 | 1.64041666667 | 14347 |
| 014047 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:48pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597165.2 | 513217.8 | 99227 | 1.64041666667 | 14047 |
| 013676 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:49pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597168.1 | 513219.7 | 99229 | 1.64041666667 | 13676 |
| 013340 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:50pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597171.1 | 513221.0 | 99231 | 1.64041666667 | 13340 |
| 014134 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:51pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597175.4 | 513222.0 | 99233 | 1.64041666667 | 14134 |
| 014257 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:52pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597178.8 | 513223.1 | 99235 | 1.64041666667 | 14257 |
| 014462 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:53pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597182.9 | 513225.0 | 99237 | 1.64041666667 | 14462 |
| 014262 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:54pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597186.2 | 513226.5 | 99239 | 1.64041666667 | 14262 |
| 013767 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:55pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597190.2 | 513227.9 | 99241 | 1.64041666667 | 13767 |
| 013309 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:56pm | Sensor | 1797-S0057-G-637-DTE | 6857.4 | 1597193.4 | 513228.4 | 99243 | 1.64041666667 | 13309 |
| 012976 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:57pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597197.4 | 513228.3 | 99245 | 1.64041666667 | 12976 |
| 013666 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:58pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597200.3 | 513228.4 | 99247 | 1.64041666667 | 13666 |
| 013777 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:59pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597203.9 | 513229.0 | 99249 | 1.64041666667 | 13777 |
| 013967 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:00pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597207.3 | 513230.2 | 99251 | 1.64041666667 | 13967 |
| 013894 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:01pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597211.0 | 513232.2 | 99253 | 1.64041666667 | 13894 |
| 014152 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:02pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597213.7 | 513234.0 | 99255 | 1.64041666667 | 14152 |
| 014246 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:03pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597216.7 | 513235.9 | 99257 | 1.64041666667 | 14246 |
| 013721 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:04pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597219.1 | 513237.0 | 99259 | 1.64041666667 | 13721 |
| 013950 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:05pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597221.4 | 513238.7 | 99261 | 1.64041666667 | 13950 |
| 014739 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:06pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597222.9 | 513240.5 | 99263 | 1.64041666667 | 14739 |
| 014823 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:07pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597224.6 | 513243.1 | 99265 | 1.64041666667 | 14823 |
| 013910 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:08pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597226.5 | 513245.3 | 99267 | 1.64041666667 | 13910 |
| 014574 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:09pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597229.7 | 513246.4 | 99269 | 1.64041666667 | 14574 |
| 014115 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:10pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597232.5 | 513245.5 | 99271 | 1.64041666667 | 14115 |
| 014525 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:11pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597234.7 | 513243.1 | 99273 | 1.64041666667 | 14525 |
| 014725 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:12pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597235.6 | 513240.3 | 99275 | 1.64041666667 | 14725 |
| 015453 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:13pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597235.3 | 513237.8 | 99277 | 1.64041666667 | 15453 |
| 015375 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:14pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597233.9 | 513235.9 | 99279 | 1.64041666667 | 15375 |
| 014895 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:15pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597231.6 | 513235.0 | 99281 | 1.64041666667 | 14895 |
| 015023 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:16pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597229.7 | 513234.2 | 99283 | 1.64041666667 | 15023 |
| 014271 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:17pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597227.3 | 513233.6 | 99285 | 1.64041666667 | 14271 |
| 014665 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:18pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597226.6 | 513233.6 | 99287 | 1.64041666667 | 14665 |
| 014369 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:19pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597226.5 | 513233.6 | 99289 | 1.64041666667 | 14369 |
| 014307 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:20pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597226.3 | 513233.3 | 99291 | 1.64041666667 | 14307 |
| 013560 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:21pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597225.4 | 513232.4 | 99293 | 1.64041666667 | 13560 |
| 013485 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:22pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597224.0 | 513232.3 | 99295 | 1.64041666667 | 13485 |
| 013098 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:23pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597221.4 | 513232.2 | 99297 | 1.64041666667 | 13098 |
| 013427 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:24pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597219.1 | 513231.6 | 99299 | 1.64041666667 | 13427 |
| 013485 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:25pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597216.1 | 513230.0 | 99301 | 1.64041666667 | 13485 |
| 013413 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:26pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597213.6 | 513228.0 | 99303 | 1.64041666667 | 13413 |
| 012840 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:27pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597210.6 | 513226.2 | 99305 | 1.64041666667 | 12840 |
| 012345 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:28pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597207.8 | 513225.1 | 99307 | 1.64041666667 | 12345 |
| 013251 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:29pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597204.6 | 513223.5 | 99309 | 1.64041666667 | 13251 |
| 014414 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:30pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597201.2 | 513221.6 | 99311 | 1.64041666667 | 14414 |
| 015472 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:31pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597197.8 | 513220.2 | 99313 | 1.64041666667 | 15472 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015228 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:32pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597195.0 | 513219.2 | 99315 | 1.64041666667 | 15228 |
| 014933 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:33pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597191.6 | 513217.7 | 99317 | 1.64041666667 | 14933 |
| 014032 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:34pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597188.9 | 513216.9 | 99319 | 1.64041666667 | 14032 |
| 014148 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:35pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597185.0 | 513216.2 | 99321 | 1.64041666667 | 14148 |
| 014648 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:36pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597181.7 | 513215.0 | 99323 | 1.64041666667 | 14648 |
| 015259 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:37pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597178.1 | 513213.4 | 99325 | 1.64041666667 | 15259 |
| 014733 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:38pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597174.9 | 513212.6 | 99327 | 1.64041666667 | 14733 |
| 014632 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:39pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597170.7 | 513211.8 | 99329 | 1.64041666667 | 14632 |
| 014463 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:40pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597167.8 | 513210.9 | 99331 | 1.64041666667 | 14463 |
| 015058 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:41pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597164.5 | 513209.4 | 99333 | 1.64041666667 | 15058 |
| 015283 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:42pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597161.1 | 513207.8 | 99335 | 1.64041666667 | 15283 |
| 014754 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:43pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597157.5 | 513206.2 | 99337 | 1.64041666667 | 14754 |
| 014584 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:44pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597154.6 | 513204.7 | 99339 | 1.64041666667 | 14584 |
| 014023 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:45pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597151.2 | 513203.0 | 99341 | 1.64041666667 | 14023 |
| 014008 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:46pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597148.4 | 513201.5 | 99343 | 1.64041666667 | 14008 |
| 015094 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:47pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597144.6 | 513199.5 | 99345 | 1.64041666667 | 15094 |
| 014858 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:48pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597141.4 | 513198.2 | 99347 | 1.64041666667 | 14858 |
| 014927 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:49pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597138.6 | 513197.5 | 99349 | 1.64041666667 | 14927 |
| 015071 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:50pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597136.8 | 513196.6 | 99351 | 1.64041666667 | 15071 |
| 015273 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:51pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597136.0 | 513195.8 | 99353 | 1.64041666667 | 15273 |
| 014756 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:52pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597136.0 | 513196.0 | 99355 | 1.64041666667 | 14756 |
| 014180 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:53pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597136.0 | 513196.0 | 99357 | 1.64041666667 | 14180 |
| 014216 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:54pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597136.1 | 513196.0 | 99359 | 1.64041666667 | 14216 |
| 014161 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:55pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597136.1 | 513195.9 | 99361 | 1.64041666667 | 14161 |
| 015266 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:44pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597222.9 | 513264.1 | 99363 | 1.64041666667 | 15266 |
| 015067 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:45pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597223.4 | 513264.5 | 99365 | 1.64041666667 | 15067 |
| 015180 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:46pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597223.4 | 513264.5 | 99367 | 1.64041666667 | 15180 |
| 015461 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:47pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597223.1 | 513264.8 | 99369 | 1.64041666667 | 15461 |
| 015199 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:48pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597223.2 | 513266.1 | 99371 | 1.64041666667 | 15199 |
| 014962 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:49pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597223.3 | 513269.4 | 99373 | 1.64041666667 | 14962 |
| 014761 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:50pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597222.8 | 513272.9 | 99375 | 1.64041666667 | 14761 |
| 013958 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:51pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597222.0 | 513276.9 | 99377 | 1.64041666667 | 13958 |
| 013724 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:52pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597221.5 | 513280.4 | 99379 | 1.64041666667 | 13724 |
| 013869 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:53pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597221.1 | 513284.8 | 99381 | 1.64041666667 | 13869 |
| 013522 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:54pm | Sensor | 1797-S0057-G-637-DTE | 6858.0 | 1597220.8 | 513288.4 | 99383 | 1.64041666667 | 13522 |
| 014033 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:55pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597220.3 | 513292.5 | 99385 | 1.64041666667 | 14033 |
| 013863 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:56pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597219.8 | 513296.3 | 99387 | 1.64041666667 | 13863 |
| 014511 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:57pm | Sensor | 1797-S0057-G-637-DTE | 6858.1 | 1597219.6 | 513300.8 | 99389 | 1.64041666667 | 14511 |
| 014500 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:58pm | Sensor | 1797-S0057-G-637-DTE | 6858.1 | 1597220.0 | 513304.9 | 99391 | 1.64041666667 | 14500 |
| 014456 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:59pm | Sensor | 1797-S0057-G-637-DTE | 6858.3 | 1597220.3 | 513309.4 | 99393 | 1.64041666667 | 14456 |
| 013899 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:00pm | Sensor | 1797-S0057-G-637-DTE | 6858.3 | 1597220.2 | 513313.0 | 99395 | 1.64041666667 | 13899 |
| 013720 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:01pm | Sensor | 1797-S0057-G-637-DTE | 6858.2 | 1597220.2 | 513317.8 | 99397 | 1.64041666667 | 13720 |
| 013305 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:02pm | Sensor | 1797-S0057-G-637-DTE | 6858.3 | 1597220.4 | 513321.2 | 99399 | 1.64041666667 | 13305 |
| 014136 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:03pm | Sensor | 1797-S0057-G-637-DTE | 6858.4 | 1597220.8 | 513325.9 | 99401 | 1.64041666667 | 14136 |
| 014529 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:04pm | Sensor | 1797-S0057-G-637-DTE | 6858.4 | 1597221.3 | 513329.5 | 99403 | 1.64041666667 | 14529 |
| 015875 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:05pm | Sensor | 1797-S0057-G-637-DTE | 6858.5 | 1597222.0 | 513333.8 | 99405 | 1.64041666667 | 15875 |
| 015942 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:06pm | Sensor | 1797-S0057-G-637-DTE | 6858.6 | 1597222.2 | 513337.3 | 99407 | 1.64041666667 | 15942 |
| 014547 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:07pm | Sensor | 1797-S0057-G-637-DTE | 6858.7 | 1597222.2 | 513341.8 | 99409 | 1.64041666667 | 14547 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014280 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:08pm | Sensor | 1797-S0057-G-637-DTE | 6858.8 | 1597222.0 | 513345.4 | 99411 | 1.64041666667 | 14280 |
| 013687 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:09pm | Sensor | 1797-S0057-G-637-DTE | 6858.8 | 1597222.1 | 513349.2 | 99413 | 1.64041666667 | 13687 |
| 013789 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:10pm | Sensor | 1797-S0057-G-637-DTE | 6858.8 | 1597221.9 | 513352.4 | 99415 | 1.64041666667 | 13789 |
| 013816 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:11pm | Sensor | 1797-S0057-G-637-DTE | 6858.6 | 1597220.5 | 513356.4 | 99417 | 1.64041666667 | 13816 |
| 014701 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:12pm | Sensor | 1797-S0057-G-637-DTE | 6858.7 | 1597219.1 | 513359.4 | 99419 | 1.64041666667 | 14701 |
| 013819 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:13pm | Sensor | 1797-S0057-G-637-DTE | 6858.7 | 1597217.7 | 513363.5 | 99421 | 1.64041666667 | 13819 |
| 014268 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:14pm | Sensor | 1797-S0057-G-637-DTE | 6858.8 | 1597217.0 | 513366.6 | 99423 | 1.64041666667 | 14268 |
| 014431 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:15pm | Sensor | 1797-S0057-G-637-DTE | 6858.9 | 1597216.3 | 513370.8 | 99425 | 1.64041666667 | 14431 |
| 014822 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:16pm | Sensor | 1797-S0057-G-637-DTE | 6858.8 | 1597215.9 | 513374.1 | 99427 | 1.64041666667 | 14822 |
| 015740 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:17pm | Sensor | 1797-S0057-G-637-DTE | 6858.9 | 1597216.3 | 513377.9 | 99429 | 1.64041666667 | 15740 |
| 015738 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:18pm | Sensor | 1797-S0057-G-637-DTE | 6858.9 | 1597217.1 | 513381.0 | 99431 | 1.64041666667 | 15738 |
| 014553 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:19pm | Sensor | 1797-S0057-G-637-DTE | 6858.9 | 1597217.4 | 513384.6 | 99433 | 1.64041666667 | 14553 |
| 014936 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:20pm | Sensor | 1797-S0057-G-637-DTE | 6858.9 | 1597217.3 | 513388.0 | 99435 | 1.64041666667 | 14936 |
| 014671 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:21pm | Sensor | 1797-S0057-G-637-DTE | 6859.0 | 1597216.9 | 513391.9 | 99437 | 1.64041666667 | 14671 |
| 014267 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:22pm | Sensor | 1797-S0057-G-637-DTE | 6859.1 | 1597216.2 | 513395.2 | 99439 | 1.64041666667 | 14267 |
| 014483 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:23pm | Sensor | 1797-S0057-G-637-DTE | 6859.1 | 1597215.4 | 513399.4 | 99441 | 1.64041666667 | 14483 |
| 014049 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:24pm | Sensor | 1797-S0057-G-637-DTE | 6859.1 | 1597215.2 | 513402.9 | 99443 | 1.64041666667 | 14049 |
| 015020 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:25pm | Sensor | 1797-S0057-G-637-DTE | 6859.0 | 1597215.3 | 513407.3 | 99445 | 1.64041666667 | 15020 |
| 015453 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:26pm | Sensor | 1797-S0057-G-637-DTE | 6859.1 | 1597215.4 | 513410.7 | 99447 | 1.64041666667 | 15453 |
| 015862 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:27pm | Sensor | 1797-S0057-G-637-DTE | 6859.2 | 1597215.6 | 513414.4 | 99449 | 1.64041666667 | 15862 |
| 015582 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:28pm | Sensor | 1797-S0057-G-637-DTE | 6859.2 | 1597215.3 | 513417.9 | 99451 | 1.64041666667 | 15582 |
| 014555 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:29pm | Sensor | 1797-S0057-G-637-DTE | 6859.3 | 1597214.1 | 513421.7 | 99453 | 1.64041666667 | 14555 |
| 014974 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:30pm | Sensor | 1797-S0057-G-637-DTE | 6859.3 | 1597213.2 | 513424.4 | 99455 | 1.64041666667 | 14974 |
| 014138 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:31pm | Sensor | 1797-S0057-G-637-DTE | 6859.3 | 1597212.2 | 513427.8 | 99457 | 1.64041666667 | 14138 |
| 013833 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:32pm | Sensor | 1797-S0057-G-637-DTE | 6859.2 | 1597210.5 | 513430.5 | 99459 | 1.64041666667 | 13833 |
| 014958 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:33pm | Sensor | 1797-S0057-G-637-DTE | 6858.8 | 1597207.9 | 513433.2 | 99461 | 1.64041666667 | 14958 |
| 015081 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:34pm | Sensor | 1797-S0057-G-637-DTE | 6858.6 | 1597205.7 | 513435.7 | 99463 | 1.64041666667 | 15081 |
| 015308 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:35pm | Sensor | 1797-S0057-G-637-DTE | 6858.6 | 1597203.1 | 513438.4 | 99465 | 1.64041666667 | 15308 |
| 014011 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:36pm | Sensor | 1797-S0057-G-637-DTE | 6858.6 | 1597200.5 | 513440.6 | 99467 | 1.64041666667 | 14011 |
| 012868 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:37pm | Sensor | 1797-S0057-G-637-DTE | 6858.5 | 1597197.3 | 513443.0 | 99469 | 1.64041666667 | 12868 |
| 012863 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:38pm | Sensor | 1797-S0057-G-637-DTE | 6858.5 | 1597194.6 | 513445.4 | 99471 | 1.64041666667 | 12863 |
| 013753 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:39pm | Sensor | 1797-S0057-G-637-DTE | 6858.5 | 1597192.3 | 513448.6 | 99473 | 1.64041666667 | 13753 |
| 013616 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:40pm | Sensor | 1797-S0057-G-637-DTE | 6858.4 | 1597191.0 | 513450.9 | 99475 | 1.64041666667 | 13616 |
| 013336 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:41pm | Sensor | 1797-S0057-G-637-DTE | 6858.3 | 1597188.7 | 513454.3 | 99477 | 1.64041666667 | 13336 |
| 012894 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:42pm | Sensor | 1797-S0057-G-637-DTE | 6858.3 | 1597186.7 | 513456.7 | 99479 | 1.64041666667 | 12894 |
| 012188 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:43pm | Sensor | 1797-S0057-G-637-DTE | 6858.1 | 1597184.1 | 513459.7 | 99481 | 1.64041666667 | 12188 |
| 012270 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:44pm | Sensor | 1797-S0057-G-637-DTE | 6858.0 | 1597182.1 | 513462.6 | 99483 | 1.64041666667 | 12270 |
| 013119 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:45pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597179.6 | 513466.2 | 99485 | 1.64041666667 | 13119 |
| 013192 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:46pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597177.4 | 513469.4 | 99487 | 1.64041666667 | 13192 |
| 013698 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:47pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597176.4 | 513473.0 | 99489 | 1.64041666667 | 13698 |
| 013217 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:48pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597176.9 | 513476.3 | 99491 | 1.64041666667 | 13217 |
| 014500 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:49pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597177.6 | 513479.8 | 99493 | 1.64041666667 | 14500 |
| 014418 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:50pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597177.9 | 513483.3 | 99495 | 1.64041666667 | 14418 |
| 014463 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:51pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597177.9 | 513487.4 | 99497 | 1.64041666667 | 14463 |
| 014533 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:52pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597178.3 | 513490.6 | 99499 | 1.64041666667 | 14533 |
| 013664 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:53pm | Sensor | 1797-S0057-G-637-DTE | 6857.1 | 1597177.9 | 513494.1 | 99501 | 1.64041666667 | 13664 |
| 012921 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:54pm | Sensor | 1797-S0057-G-637-DTE | 6856.9 | 1597176.6 | 513497.0 | 99503 | 1.64041666667 | 12921 |
| 012698 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:55pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597174.8 | 513500.5 | 99505 | 1.64041666667 | 12698 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012992 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:56pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597173.4 | 513503.7 | 99507 | 1.64041666667 | 12992 |
| 014036 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:57pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597171.6 | 513507.4 | 99509 | 1.64041666667 | 14036 |
| 013887 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:58pm | Sensor | 1797-S0057-G-637-DTE | 6856.6 | 1597169.6 | 513510.7 | 99511 | 1.64041666667 | 13887 |
| 013308 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:59pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597166.7 | 513513.1 | 99513 | 1.64041666667 | 13308 |
| 012908 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:00pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597163.5 | 513514.7 | 99515 | 1.64041666667 | 12908 |
| 013403 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:01pm | Sensor | 1797-S0057-G-637-DTE | 6856.3 | 1597160.0 | 513516.8 | 99517 | 1.64041666667 | 13403 |
| 013712 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:02pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597157.1 | 513518.9 | 99519 | 1.64041666667 | 13712 |
| 013480 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:03pm | Sensor | 1797-S0057-G-637-DTE | 6856.2 | 1597154.2 | 513521.2 | 99521 | 1.64041666667 | 13480 |
| 013950 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:04pm | Sensor | 1797-S0057-G-637-DTE | 6856.0 | 1597151.3 | 513523.4 | 99523 | 1.64041666667 | 13950 |
| 013839 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:05pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597148.4 | 513526.0 | 99525 | 1.64041666667 | 13839 |
| 014467 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:06pm | Sensor | 1797-S0057-G-637-DTE | 6855.9 | 1597146.2 | 513528.8 | 99527 | 1.64041666667 | 14467 |
| 014745 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:07pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597144.2 | 513532.2 | 99529 | 1.64041666667 | 14745 |
| 014144 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:08pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597142.1 | 513534.9 | 99531 | 1.64041666667 | 14144 |
| 016138 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:09pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597139.0 | 513536.8 | 99533 | 1.64041666667 | 16138 |
| 014935 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:10pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597135.4 | 513538.1 | 99535 | 1.64041666667 | 14935 |
| 014078 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:11pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597132.1 | 513539.8 | 99537 | 1.64041666667 | 14078 |
| 013319 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:12pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597129.4 | 513541.7 | 99539 | 1.64041666667 | 13319 |
| 013552 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:13pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597125.8 | 513544.1 | 99541 | 1.64041666667 | 13552 |
| 012850 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:14pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597123.0 | 513546.2 | 99543 | 1.64041666667 | 12850 |
| 012418 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:15pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597120.5 | 513549.4 | 99545 | 1.64041666667 | 12418 |
| 013060 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:16pm | Sensor | 1797-S0057-G-637-DTE | 6855.4 | 1597119.0 | 513552.3 | 99547 | 1.64041666667 | 13060 |
| 012281 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:17pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597117.4 | 513555.9 | 99549 | 1.64041666667 | 12281 |
| 012068 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:18pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597116.3 | 513559.5 | 99551 | 1.64041666667 | 12068 |
| 012331 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:19pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597115.5 | 513563.7 | 99553 | 1.64041666667 | 12331 |
| 012688 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:20pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597115.0 | 513566.8 | 99555 | 1.64041666667 | 12688 |
| 012147 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:21pm | Sensor | 1797-S0057-G-637-DTE | 6855.1 | 1597114.1 | 513571.0 | 99557 | 1.64041666667 | 12147 |
| 011520 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:22pm | Sensor | 1797-S0057-G-637-DTE | 6854.9 | 1597112.9 | 513575.0 | 99559 | 1.64041666667 | 11520 |
| 012060 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:23pm | Sensor | 1797-S0057-G-637-DTE | 6855.0 | 1597111.9 | 513579.1 | 99561 | 1.64041666667 | 12060 |
| 012363 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:24pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597111.0 | 513582.6 | 99563 | 1.64041666667 | 12363 |
| 012122 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:25pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597109.4 | 513586.0 | 99565 | 1.64041666667 | 12122 |
| 011866 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:26pm | Sensor | 1797-S0057-G-637-DTE | 6855.3 | 1597107.7 | 513589.2 | 99567 | 1.64041666667 | 11866 |
| 011497 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:27pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597105.8 | 513593.0 | 99569 | 1.64041666667 | 11497 |
| 012249 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:28pm | Sensor | 1797-S0057-G-637-DTE | 6855.2 | 1597104.4 | 513596.3 | 99571 | 1.64041666667 | 12249 |
| 012245 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:29pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597103.3 | 513600.6 | 99573 | 1.64041666667 | 12245 |
| 012535 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:30pm | Sensor | 1797-S0057-G-637-DTE | 6855.5 | 1597102.6 | 513604.0 | 99575 | 1.64041666667 | 12535 |
| 011903 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:31pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597101.3 | 513607.9 | 99577 | 1.64041666667 | 11903 |
| 011683 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:32pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597100.6 | 513611.2 | 99579 | 1.64041666667 | 11683 |
| 011342 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:33pm | Sensor | 1797-S0057-G-637-DTE | 6855.6 | 1597101.1 | 513615.5 | 99581 | 1.64041666667 | 11342 |
| 011232 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:34pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597101.0 | 513619.0 | 99583 | 1.64041666667 | 11232 |
| 012055 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:35pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597099.2 | 513622.7 | 99585 | 1.64041666667 | 12055 |
| 012353 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:36pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597096.4 | 513625.3 | 99587 | 1.64041666667 | 12353 |
| 011786 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:37pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597092.9 | 513627.4 | 99589 | 1.64041666667 | 11786 |
| 011152 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:38pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597089.9 | 513628.4 | 99591 | 1.64041666667 | 11152 |
| 012333 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:39pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597085.3 | 513629.0 | 99593 | 1.64041666667 | 12333 |
| 012070 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:40pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597082.1 | 513630.1 | 99595 | 1.64041666667 | 12070 |
| 011332 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:41pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597079.0 | 513632.6 | 99597 | 1.64041666667 | 11332 |
| 011159 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:42pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597076.6 | 513634.8 | 99599 | 1.64041666667 | 11159 |
| 010777 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:43pm | Sensor | 1797-S0057-G-637-DTE | 6855.7 | 1597073.0 | 513637.2 | 99601 | 1.64041666667 | 10777 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010914 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:44pm | Sensor | 1797-S0057-G-637-DTE | 6855.8 | 1597070.1 | 513639.0 | 99603 | 1.64041666667 | 10914 |
| 010819 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:45pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597067.2 | 513641.5 | 99605 | 1.64041666667 | 10819 |
| 010856 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:46pm | Sensor | 1797-S0057-G-637-DTE | 6856.1 | 1597064.8 | 513643.5 | 99607 | 1.64041666667 | 10856 |
| 010711 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:47pm | Sensor | 1797-S0057-G-637-DTE | 6856.4 | 1597061.2 | 513645.4 | 99609 | 1.64041666667 | 10711 |
| 010720 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:48pm | Sensor | 1797-S0057-G-637-DTE | 6856.5 | 1597057.7 | 513647.2 | 99611 | 1.64041666667 | 10720 |
| 011280 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:49pm | Sensor | 1797-S0057-G-637-DTE | 6856.7 | 1597054.5 | 513649.9 | 99613 | 1.64041666667 | 11280 |
| 009442 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:50pm | Sensor | 1797-S0057-G-637-DTE | 6856.8 | 1597052.9 | 513652.9 | 99615 | 1.64041666667 | 9442 |
| 010074 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:51pm | Sensor | 1797-S0057-G-637-DTE | 6857.0 | 1597051.7 | 513656.8 | 99617 | 1.64041666667 | 10074 |
| 009551 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:52pm | Sensor | 1797-S0057-G-637-DTE | 6857.2 | 1597049.9 | 513659.8 | 99619 | 1.64041666667 | 9551 |
| 009542 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:53pm | Sensor | 1797-S0057-G-637-DTE | 6857.3 | 1597047.1 | 513662.6 | 99621 | 1.64041666667 | 9542 |
| 010070 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:54pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597044.6 | 513665.4 | 99623 | 1.64041666667 | 10070 |
| 010179 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:55pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597042.5 | 513668.9 | 99625 | 1.64041666667 | 10179 |
| 009851 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:56pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597041.5 | 513672.3 | 99627 | 1.64041666667 | 9851 |
| 010858 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:57pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597040.6 | 513675.8 | 99629 | 1.64041666667 | 10858 |
| 011305 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:58pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597039.6 | 513679.2 | 99631 | 1.64041666667 | 11305 |
| 010724 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:59pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597038.9 | 513682.9 | 99633 | 1.64041666667 | 10724 |
| 010630 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:00pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597038.4 | 513686.7 | 99635 | 1.64041666667 | 10630 |
| 010884 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:01pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597037.7 | 513690.8 | 99637 | 1.64041666667 | 10884 |
| 011012 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:02pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597037.5 | 513694.1 | 99639 | 1.64041666667 | 11012 |
| 010672 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:03pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597038.3 | 513698.4 | 99641 | 1.64041666667 | 10672 |
| 011005 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:04pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597039.8 | 513702.0 | 99643 | 1.64041666667 | 11005 |
| 011440 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:05pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597041.9 | 513706.0 | 99645 | 1.64041666667 | 11440 |
| 011895 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:06pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597043.3 | 513709.5 | 99647 | 1.64041666667 | 11895 |
| 012121 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:07pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597045.0 | 513714.0 | 99649 | 1.64041666667 | 12121 |
| 011355 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:08pm | Sensor | 1797-S0057-G-637-DTE | 6857.5 | 1597046.2 | 513718.0 | 99651 | 1.64041666667 | 11355 |
| 011442 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:09pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597047.0 | 513722.2 | 99653 | 1.64041666667 | 11442 |
| 011394 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:10pm | Sensor | 1797-S0057-G-637-DTE | 6857.6 | 1597047.0 | 513725.8 | 99655 | 1.64041666667 | 11394 |
| 010924 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:11pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597046.1 | 513730.3 | 99657 | 1.64041666667 | 10924 |
| 011349 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:12pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597045.4 | 513733.8 | 99659 | 1.64041666667 | 11349 |
| 011371 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:13pm | Sensor | 1797-S0057-G-637-DTE | 6857.7 | 1597044.5 | 513738.7 | 99661 | 1.64041666667 | 11371 |
| 010904 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:14pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597044.3 | 513742.2 | 99663 | 1.64041666667 | 10904 |
| 010521 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:15pm | Sensor | 1797-S0057-G-637-DTE | 6857.8 | 1597044.5 | 513746.3 | 99665 | 1.64041666667 | 10521 |
| 010673 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:16pm | Sensor | 1797-S0057-G-637-DTE | 6857.9 | 1597044.8 | 513750.2 | 99667 | 1.64041666667 | 10673 |
| 010796 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:17pm | Sensor | 1797-S0057-G-637-DTE | 6858.2 | 1597044.2 | 513754.4 | 99669 | 1.64041666667 | 10796 |
| 009837 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:18pm | Sensor | 1797-S0057-G-637-DTE | 6858.2 | 1597043.4 | 513757.3 | 99671 | 1.64041666667 | 9837 |
| 010041 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:19pm | Sensor | 1797-S0057-G-637-DTE | 6858.3 | 1597042.8 | 513760.5 | 99673 | 1.64041666667 | 10041 |
| 010560 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:20pm | Sensor | 1797-S0057-G-637-DTE | 6858.4 | 1597043.4 | 513763.4 | 99675 | 1.64041666667 | 10560 |
| 010680 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:21pm | Sensor | 1797-S0057-G-637-DTE | 6858.5 | 1597044.2 | 513766.3 | 99677 | 1.64041666667 | 10680 |
| 010905 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:22pm | Sensor | 1797-S0057-G-637-DTE | 6858.6 | 1597044.5 | 513767.4 | 99679 | 1.64041666667 | 10905 |
| 010979 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:23pm | Sensor | 1797-S0057-G-637-DTE | 6858.7 | 1597044.8 | 513767.6 | 99681 | 1.64041666667 | 10979 |
| 010908 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:24pm | Sensor | 1797-S0057-G-637-DTE | 6858.7 | 1597045.1 | 513768.4 | 99683 | 1.64041666667 | 10908 |
| 010801 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:25pm | Sensor | 1797-S0057-G-637-DTE | 6858.7 | 1597046.7 | 513770.6 | 99685 | 1.64041666667 | 10801 |
| 010770 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:26pm | Sensor | 1797-S0057-G-637-DTE | 6858.7 | 1597048.6 | 513773.5 | 99687 | 1.64041666667 | 10770 |
| 011203 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:27pm | Sensor | 1797-S0057-G-637-DTE | 6858.7 | 1597050.8 | 513777.7 | 99689 | 1.64041666667 | 11203 |
| 011394 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:28pm | Sensor | 1797-S0057-G-637-DTE | 6858.8 | 1597052.7 | 513781.4 | 99691 | 1.64041666667 | 11394 |
| 010316 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:29pm | Sensor | 1797-S0057-G-637-DTE | 6859.1 | 1597054.6 | 513786.0 | 99693 | 1.64041666667 | 10316 |
| 010813 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:30pm | Sensor | 1797-S0057-G-637-DTE | 6859.2 | 1597055.9 | 513789.3 | 99695 | 1.64041666667 | 10813 |
| 011700 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:31pm | Sensor | 1797-S0057-G-637-DTE | 6859.3 | 1597056.8 | 513793.7 | 99697 | 1.64041666667 | 11700 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011261 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:32pm | Sensor | 1797-S0057-G-637-DTE | 6859.4 | 1597056.2 | 513797.2 | 99699 | 1.64041666667 | 11261 |
| 011014 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:33pm | Sensor | 1797-S0057-G-637-DTE | 6859.4 | 1597054.5 | 513801.0 | 99701 | 1.64041666667 | 11014 |
| 010875 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:34pm | Sensor | 1797-S0057-G-637-DTE | 6859.7 | 1597053.3 | 513804.5 | 99703 | 1.64041666667 | 10875 |
| 011330 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:35pm | Sensor | 1797-S0057-G-637-DTE | 6859.8 | 1597053.4 | 513809.0 | 99705 | 1.64041666667 | 11330 |
| 011690 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:36pm | Sensor | 1797-S0057-G-637-DTE | 6859.9 | 1597054.3 | 513812.6 | 99707 | 1.64041666667 | 11690 |
| 012283 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:37pm | Sensor | 1797-S0057-G-637-DTE | 6860.1 | 1597054.8 | 513816.7 | 99709 | 1.64041666667 | 12283 |
| 012834 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:38pm | Sensor | 1797-S0057-G-637-DTE | 6860.4 | 1597054.6 | 513819.8 | 99711 | 1.64041666667 | 12834 |
| 012049 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:39pm | Sensor | 1797-S0057-G-637-DTE | 6860.5 | 1597053.9 | 513823.0 | 99713 | 1.64041666667 | 12049 |
| 012717 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:40pm | Sensor | 1797-S0057-G-637-DTE | 6860.3 | 1597053.4 | 513825.5 | 99715 | 1.64041666667 | 12717 |
| 012673 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:41pm | Sensor | 1797-S0057-G-637-DTE | 6860.5 | 1597053.2 | 513829.1 | 99717 | 1.64041666667 | 12673 |
| 012356 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:42pm | Sensor | 1797-S0057-G-637-DTE | 6860.5 | 1597053.5 | 513832.9 | 99719 | 1.64041666667 | 12356 |
| 011878 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:43pm | Sensor | 1797-S0057-G-637-DTE | 6860.8 | 1597054.3 | 513836.9 | 99721 | 1.64041666667 | 11878 |
| 012224 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:44pm | Sensor | 1797-S0057-G-637-DTE | 6861.1 | 1597055.2 | 513840.4 | 99723 | 1.64041666667 | 12224 |
| 012831 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:45pm | Sensor | 1797-S0057-G-637-DTE | 6861.4 | 1597055.9 | 513844.3 | 99725 | 1.64041666667 | 12831 |
| 013150 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:46pm | Sensor | 1797-S0057-G-637-DTE | 6861.6 | 1597056.5 | 513847.7 | 99727 | 1.64041666667 | 13150 |
| 014004 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:47pm | Sensor | 1797-S0057-G-637-DTE | 6861.8 | 1597058.3 | 513851.1 | 99729 | 1.64041666667 | 14004 |
| 014320 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:48pm | Sensor | 1797-S0057-G-637-DTE | 6861.8 | 1597061.0 | 513853.3 | 99731 | 1.64041666667 | 14320 |
| 014137 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:49pm | Sensor | 1797-S0057-G-637-DTE | 6861.6 | 1597064.7 | 513855.2 | 99733 | 1.64041666667 | 14137 |
| 013014 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:50pm | Sensor | 1797-S0057-G-637-DTE | 6861.4 | 1597067.8 | 513857.8 | 99735 | 1.64041666667 | 13014 |
| 012023 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:51pm | Sensor | 1797-S0057-G-637-DTE | 6861.1 | 1597070.6 | 513861.7 | 99737 | 1.64041666667 | 12023 |
| 011675 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:52pm | Sensor | 1797-S0057-G-637-DTE | 6861.0 | 1597072.7 | 513865.1 | 99739 | 1.64041666667 | 11675 |
| 011502 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:53pm | Sensor | 1797-S0057-G-637-DTE | 6861.1 | 1597074.5 | 513869.4 | 99741 | 1.64041666667 | 11502 |
| 012162 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:54pm | Sensor | 1797-S0057-G-637-DTE | 6861.1 | 1597075.6 | 513872.3 | 99743 | 1.64041666667 | 12162 |
| 012406 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:55pm | Sensor | 1797-S0057-G-637-DTE | 6861.2 | 1597077.6 | 513875.6 | 99745 | 1.64041666667 | 12406 |
| 012753 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:56pm | Sensor | 1797-S0057-G-637-DTE | 6861.2 | 1597079.7 | 513877.7 | 99747 | 1.64041666667 | 12753 |
| 013946 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:57pm | Sensor | 1797-S0057-G-637-DTE | 6861.1 | 1597083.3 | 513879.4 | 99749 | 1.64041666667 | 13946 |
| 014370 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:58pm | Sensor | 1797-S0057-G-637-DTE | 6861.2 | 1597086.9 | 513880.1 | 99751 | 1.64041666667 | 14370 |
| 015245 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:59pm | Sensor | 1797-S0057-G-637-DTE | 6861.2 | 1597091.2 | 513880.5 | 99753 | 1.64041666667 | 15245 |
| 014553 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:00pm | Sensor | 1797-S0057-G-637-DTE | 6861.0 | 1597095.1 | 513881.3 | 99755 | 1.64041666667 | 14553 |
| 014906 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:01pm | Sensor | 1797-S0057-G-637-DTE | 6860.9 | 1597099.5 | 513883.0 | 99757 | 1.64041666667 | 14906 |
| 014302 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:02pm | Sensor | 1797-S0057-G-637-DTE | 6860.9 | 1597102.9 | 513884.7 | 99759 | 1.64041666667 | 14302 |
| 013385 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:03pm | Sensor | 1797-S0057-G-637-DTE | 6860.9 | 1597106.5 | 513886.0 | 99761 | 1.64041666667 | 13385 |
| 012861 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:04pm | Sensor | 1797-S0057-G-637-DTE | 6860.8 | 1597109.2 | 513886.2 | 99763 | 1.64041666667 | 12861 |
| 011914 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:05pm | Sensor | 1797-S0057-G-637-DTE | 6861.0 | 1597111.3 | 513885.7 | 99765 | 1.64041666667 | 11914 |
| 011517 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:06pm | Sensor | 1797-S0057-G-637-DTE | 6861.0 | 1597111.9 | 513885.8 | 99767 | 1.64041666667 | 11517 |
| 011593 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:07pm | Sensor | 1797-S0057-G-637-DTE | 6861.0 | 1597112.0 | 513886.0 | 99769 | 1.64041666667 | 11593 |
| 011178 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:08pm | Sensor | 1797-S0057-G-637-DTE | 6861.0 | 1597112.0 | 513886.1 | 99772 | 1.64041666667 | 11178 |
| 014073 | 0 | GeoXH 6000 | 08/20/2015 | 09:30:53am | Sensor | 1797-S0056-G-TJV.cor | 6849.3 | 1597260.2 | 512854.5 | 96030 | 1.64041666667 | 14073 |
| 013748 | 0 | GeoXH 6000 | 08/20/2015 | 09:30:54am | Sensor | 1797-S0056-G-TJV.cor | 6849.3 | 1597260.2 | 512854.5 | 96033 | 1.64041666667 | 13748 |
| 014117 | 0 | GeoXH 6000 | 08/20/2015 | 09:30:55am | Sensor | 1797-S0056-G-TJV.cor | 6849.3 | 1597260.0 | 512854.4 | 96035 | 1.64041666667 | 14117 |
| 014179 | 0 | GeoXH 6000 | 08/20/2015 | 09:30:56am | Sensor | 1797-S0056-G-TJV.cor | 6849.2 | 1597260.0 | 512854.4 | 96037 | 1.64041666667 | 14179 |
| 014194 | 0 | GeoXH 6000 | 08/20/2015 | 09:30:57am | Sensor | 1797-S0056-G-TJV.cor | 6849.2 | 1597260.1 | 512854.3 | 96039 | 1.64041666667 | 14194 |
| 013748 | 0 | GeoXH 6000 | 08/20/2015 | 09:30:58am | Sensor | 1797-S0056-G-TJV.cor | 6849.2 | 1597260.0 | 512854.4 | 96041 | 1.64041666667 | 13748 |
| 014747 | 0 | GeoXH 6000 | 08/20/2015 | 09:30:59am | Sensor | 1797-S0056-G-TJV.cor | 6849.2 | 1597260.0 | 512854.4 | 96048 | 1.64041666667 | 14747 |
| 013069 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:11am | Sensor | 1797-S0056-G-TJV.cor | 6849.4 | 1597261.1 | 512849.5 | 96049 | 1.64041666667 | 13069 |
| 014427 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:13am | Sensor | 1797-S0056-G-TJV.cor | 6849.4 | 1597261.1 | 512849.5 | 96053 | 1.64041666667 | 14427 |
| 015037 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:13am | Sensor | 1797-S0056-G-TJV.cor | 6849.4 | 1597261.1 | 512849.5 | 96054 | 1.64041666667 | 15037 |
| 013359 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:15am | Sensor | 1797-S0056-G-TJV.cor | 6849.3 | 1597261.1 | 512849.5 | 96057 | 1.64041666667 | 13359 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013299 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:15am | Sensor | 1797-S0056-G-TJV.cor | 6849.4 | 1597261.1 | 512849.6 | 96058 | 1.64041666667 | 13299 |
| 013315 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:16am | Sensor | 1797-S0056-G-TJV.cor | 6849.4 | 1597261.2 | 512849.5 | 96060 | 1.64041666667 | 13315 |
| 013768 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:18am | Sensor | 1797-S0056-G-TJV.cor | 6849.3 | 1597261.2 | 512849.5 | 96063 | 1.64041666667 | 13768 |
| 012982 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:19am | Sensor | 1797-S0056-G-TJV.cor | 6849.3 | 1597261.2 | 512849.5 | 96065 | 1.64041666667 | 12982 |
| 012425 | 0 | GeoXH 6000 | 08/20/2015 | 09:41:19am | Sensor | 1797-S0056-G-TJV.cor | 6849.3 | 1597261.2 | 512849.5 | 96066 | 1.64041666667 | 12425 |
| 011825 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:11pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.6 | 511973.2 | 91202 | 1.64041666667 | 11825 |
| 013052 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:11pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.5 | 511973.2 | 91204 | 1.64041666667 | 13052 |
| 011501 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:13pm | Sensor | 1797-S0055-G-TJV.cor | 6851.6 | 1596736.7 | 511973.3 | 91208 | 1.64041666667 | 11501 |
| 010255 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:14pm | Sensor | 1797-S0055-G-TJV.cor | 6850.0 | 1596737.4 | 511973.6 | 91210 | 1.64041666667 | 10255 |
| 010424 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:15pm | Sensor | 1797-S0055-G-TJV.cor | 6850.8 | 1596736.8 | 511973.6 | 91212 | 1.64041666667 | 10424 |
| 010346 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:16pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.5 | 511973.2 | 91214 | 1.64041666667 | 10346 |
| 011946 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:17pm | Sensor | 1797-S0055-G-TJV.cor | 6851.7 | 1596736.6 | 511973.3 | 91216 | 1.64041666667 | 11946 |
| 010126 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:17pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.5 | 511973.2 | 91217 | 1.64041666667 | 10126 |
| 011231 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:18pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.5 | 511973.2 | 91219 | 1.64041666667 | 11231 |
| 011478 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:19pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.5 | 511973.2 | 91221 | 1.64041666667 | 11478 |
| 010609 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:21pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.5 | 511973.2 | 91224 | 1.64041666667 | 10609 |
| 010932 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:22pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.5 | 511973.2 | 91226 | 1.64041666667 | 10932 |
| 011553 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:23pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.5 | 511973.2 | 91228 | 1.64041666667 | 11553 |
| 011348 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:24pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.5 | 511973.2 | 91230 | 1.64041666667 | 11348 |
| 011087 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:25pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.6 | 511973.3 | 91232 | 1.64041666667 | 11087 |
| 012041 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:25pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.7 | 511973.3 | 91233 | 1.64041666667 | 12041 |
| 011290 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:27pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.7 | 511973.4 | 91236 | 1.64041666667 | 11290 |
| 010742 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:27pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.7 | 511973.4 | 91237 | 1.64041666667 | 10742 |
| 010575 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:29pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.7 | 511973.4 | 91240 | 1.64041666667 | 10575 |
| 012963 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:29pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.7 | 511973.4 | 91241 | 1.64041666667 | 12963 |
| 011221 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:31pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.7 | 511973.4 | 91244 | 1.64041666667 | 11221 |
| 011475 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:31pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.6 | 511973.4 | 91245 | 1.64041666667 | 11475 |
| 011328 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:33pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.7 | 511973.4 | 91248 | 1.64041666667 | 11328 |
| 010692 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:33pm | Sensor | 1797-S0055-G-TJV.cor | 6852.1 | 1596736.7 | 511973.4 | 91249 | 1.64041666667 | 10692 |
| 012633 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:35pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.6 | 511973.5 | 91252 | 1.64041666667 | 12633 |
| 012188 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:35pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.5 | 511973.3 | 91253 | 1.64041666667 | 12188 |
| 011717 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:37pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.4 | 511973.7 | 91256 | 1.64041666667 | 11717 |
| 012139 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:37pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.6 | 511973.8 | 91257 | 1.64041666667 | 12139 |
| 010954 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:38pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.5 | 511973.8 | 91259 | 1.64041666667 | 10954 |
| 011357 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:39pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.5 | 511973.8 | 91261 | 1.64041666667 | 11357 |
| 011289 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:41pm | Sensor | 1797-S0055-G-TJV.cor | 6852.1 | 1596736.3 | 511973.7 | 91264 | 1.64041666667 | 11289 |
| 011852 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:41pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.3 | 511973.6 | 91265 | 1.64041666667 | 11852 |
| 011243 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:42pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.6 | 511973.6 | 91267 | 1.64041666667 | 11243 |
| 011810 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:43pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.8 | 511973.6 | 91269 | 1.64041666667 | 11810 |
| 011712 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:44pm | Sensor | 1797-S0055-G-TJV.cor | 6851.9 | 1596736.7 | 511973.6 | 91271 | 1.64041666667 | 11712 |
| 012708 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:45pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.7 | 511973.5 | 91273 | 1.64041666667 | 12708 |
| 011097 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:47pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.7 | 511973.6 | 91276 | 1.64041666667 | 11097 |
| 012254 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:47pm | Sensor | 1797-S0055-G-TJV.cor | 6852.0 | 1596736.6 | 511973.6 | 91277 | 1.64041666667 | 12254 |
| 011313 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:49pm | Sensor | 1797-S0055-G-TJV.cor | 6852.1 | 1596736.1 | 511973.9 | 91280 | 1.64041666667 | 11313 |
| 010478 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:49pm | Sensor | 1797-S0055-G-TJV.cor | 6853.0 | 1596736.5 | 511974.3 | 91281 | 1.64041666667 | 10478 |
| 011199 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:50pm | Sensor | 1797-S0055-G-TJV.cor | 6853.5 | 1596736.1 | 511974.6 | 91283 | 1.64041666667 | 11199 |
| 012100 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:51pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596736.0 | 511975.1 | 91285 | 1.64041666667 | 12100 |
| 011905 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:52pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596735.8 | 511975.1 | 91287 | 1.64041666667 | 11905 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012126 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:53pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596735.9 | 511974.9 | 91289 | 1.64041666667 | 12126 |
| 011461 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:54pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596736.0 | 511974.9 | 91291 | 1.64041666667 | 11461 |
| 012495 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:55pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596736.0 | 511974.9 | 91293 | 1.64041666667 | 12495 |
| 012993 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:57pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596735.9 | 511974.9 | 91296 | 1.64041666667 | 12993 |
| 013148 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:57pm | Sensor | 1797-S0055-G-TJV.cor | 6853.5 | 1596735.9 | 511974.8 | 91297 | 1.64041666667 | 13148 |
| 013367 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:59pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596736.0 | 511974.9 | 91300 | 1.64041666667 | 13367 |
| 011471 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:59pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596736.0 | 511975.1 | 91301 | 1.64041666667 | 11471 |
| 011868 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:01pm | Sensor | 1797-S0055-G-TJV.cor | 6853.5 | 1596736.9 | 511975.2 | 91304 | 1.64041666667 | 11868 |
| 012057 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:01pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596737.6 | 511976.3 | 91305 | 1.64041666667 | 12057 |
| 011504 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:02pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596739.8 | 511977.5 | 91307 | 1.64041666667 | 11504 |
| 012296 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:03pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596741.8 | 511979.1 | 91309 | 1.64041666667 | 12296 |
| 012314 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:05pm | Sensor | 1797-S0055-G-TJV.cor | 6853.1 | 1596744.8 | 511980.8 | 91312 | 1.64041666667 | 12314 |
| 013068 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:05pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596747.1 | 511982.0 | 91313 | 1.64041666667 | 13068 |
| 013167 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:06pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596749.4 | 511983.5 | 91315 | 1.64041666667 | 13167 |
| 013731 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:07pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596751.8 | 511984.4 | 91317 | 1.64041666667 | 13731 |
| 013693 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:09pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596754.4 | 511985.8 | 91320 | 1.64041666667 | 13693 |
| 013563 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:09pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596757.0 | 511986.9 | 91321 | 1.64041666667 | 13563 |
| 014820 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:11pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596759.9 | 511987.4 | 91324 | 1.64041666667 | 14820 |
| 012795 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:11pm | Sensor | 1797-S0055-G-TJV.cor | 6853.1 | 1596762.4 | 511987.4 | 91325 | 1.64041666667 | 12795 |
| 010548 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:13pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596765.4 | 511987.5 | 91328 | 1.64041666667 | 10548 |
| 010707 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:13pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596765.9 | 511987.2 | 91329 | 1.64041666667 | 10707 |
| 012427 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:15pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596765.9 | 511987.1 | 91332 | 1.64041666667 | 12427 |
| 011836 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:15pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596765.9 | 511987.1 | 91333 | 1.64041666667 | 11836 |
| 013279 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:16pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596765.9 | 511987.1 | 91335 | 1.64041666667 | 13279 |
| 013009 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:17pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596765.9 | 511987.1 | 91337 | 1.64041666667 | 13009 |
| 013182 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:19pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596766.2 | 511986.6 | 91340 | 1.64041666667 | 13182 |
| 012505 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:19pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596767.8 | 511987.1 | 91341 | 1.64041666667 | 12505 |
| 011976 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:21pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596770.9 | 511987.3 | 91344 | 1.64041666667 | 11976 |
| 011514 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:21pm | Sensor | 1797-S0055-G-TJV.cor | 6853.3 | 1596773.4 | 511988.1 | 91345 | 1.64041666667 | 11514 |
| 011788 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:23pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596776.8 | 511988.8 | 91348 | 1.64041666667 | 11788 |
| 012997 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:23pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596779.2 | 511988.4 | 91349 | 1.64041666667 | 12997 |
| 013059 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:25pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596782.4 | 511988.4 | 91352 | 1.64041666667 | 13059 |
| 011934 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:25pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1596784.9 | 511988.5 | 91353 | 1.64041666667 | 11934 |
| 012823 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:27pm | Sensor | 1797-S0055-G-TJV.cor | 6853.6 | 1596788.1 | 511987.7 | 91356 | 1.64041666667 | 12823 |
| 014216 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:27pm | Sensor | 1797-S0055-G-TJV.cor | 6853.5 | 1596790.2 | 511987.3 | 91357 | 1.64041666667 | 14216 |
| 014474 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:28pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1596793.3 | 511986.3 | 91359 | 1.64041666667 | 14474 |
| 013218 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:29pm | Sensor | 1797-S0055-G-TJV.cor | 6853.6 | 1596796.1 | 511985.3 | 91361 | 1.64041666667 | 13218 |
| 012184 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:30pm | Sensor | 1797-S0055-G-TJV.cor | 6853.7 | 1596798.8 | 511984.5 | 91363 | 1.64041666667 | 12184 |
| 013036 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:31pm | Sensor | 1797-S0055-G-TJV.cor | 6853.6 | 1596801.6 | 511982.8 | 91365 | 1.64041666667 | 13036 |
| 013609 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:32pm | Sensor | 1797-S0055-G-TJV.cor | 6853.7 | 1596804.2 | 511981.1 | 91367 | 1.64041666667 | 13609 |
| 013692 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:33pm | Sensor | 1797-S0055-G-TJV.cor | 6853.7 | 1596806.7 | 511980.0 | 91369 | 1.64041666667 | 13692 |
| 011973 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:34pm | Sensor | 1797-S0055-G-TJV.cor | 6853.8 | 1596809.0 | 511977.9 | 91371 | 1.64041666667 | 11973 |
| 012953 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:35pm | Sensor | 1797-S0055-G-TJV.cor | 6853.9 | 1596810.8 | 511976.0 | 91373 | 1.64041666667 | 12953 |
| 013828 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:37pm | Sensor | 1797-S0055-G-TJV.cor | 6854.1 | 1596813.0 | 511973.6 | 91376 | 1.64041666667 | 13828 |
| 012817 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:37pm | Sensor | 1797-S0055-G-TJV.cor | 6854.0 | 1596814.7 | 511971.5 | 91377 | 1.64041666667 | 12817 |
| 012804 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:38pm | Sensor | 1797-S0055-G-TJV.cor | 6854.1 | 1596817.3 | 511969.3 | 91379 | 1.64041666667 | 12804 |
| 011031 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:39pm | Sensor | 1797-S0055-G-TJV.cor | 6854.1 | 1596819.7 | 511968.5 | 91381 | 1.64041666667 | 11031 |
| 011067 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:41pm | Sensor | 1797-S0055-G-TJV.cor | 6854.2 | 1596823.1 | 511967.2 | 91384 | 1.64041666667 | 11067 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012097 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:41pm | Sensor | 1797-S0055-G-TJV.cor | 6854.4 | 1596825.6 | 511966.4 | 91385 | 1.64041666667 | 12097 |
| 011784 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:43pm | Sensor | 1797-S0055-G-TJV.cor | 6854.3 | 1596828.5 | 511965.1 | 91388 | 1.64041666667 | 11784 |
| 013866 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:43pm | Sensor | 1797-S0055-G-TJV.cor | 6854.3 | 1596830.4 | 511963.9 | 91389 | 1.64041666667 | 13866 |
| 012436 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:45pm | Sensor | 1797-S0055-G-TJV.cor | 6854.4 | 1596833.1 | 511962.6 | 91392 | 1.64041666667 | 12436 |
| 012679 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:45pm | Sensor | 1797-S0055-G-TJV.cor | 6854.6 | 1596835.0 | 511961.8 | 91393 | 1.64041666667 | 12679 |
| 013219 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:47pm | Sensor | 1797-S0055-G-TJV.cor | 6854.5 | 1596837.7 | 511960.0 | 91396 | 1.64041666667 | 13219 |
| 010715 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:47pm | Sensor | 1797-S0055-G-TJV.cor | 6854.4 | 1596840.1 | 511959.0 | 91397 | 1.64041666667 | 10715 |
| 010808 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:49pm | Sensor | 1797-S0055-G-TJV.cor | 6854.4 | 1596843.0 | 511958.1 | 91400 | 1.64041666667 | 10808 |
| 010622 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:49pm | Sensor | 1797-S0055-G-TJV.cor | 6854.4 | 1596845.2 | 511956.7 | 91401 | 1.64041666667 | 10622 |
| 009525 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:51pm | Sensor | 1797-S0055-G-TJV.cor | 6854.4 | 1596848.4 | 511955.3 | 91404 | 1.64041666667 | 9525 |
| 009821 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:51pm | Sensor | 1797-S0055-G-TJV.cor | 6854.5 | 1596850.5 | 511955.0 | 91405 | 1.64041666667 | 9821 |
| 010945 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:53pm | Sensor | 1797-S0055-G-TJV.cor | 6854.6 | 1596853.8 | 511954.4 | 91408 | 1.64041666667 | 10945 |
| 010476 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:53pm | Sensor | 1797-S0055-G-TJV.cor | 6854.6 | 1596856.3 | 511954.4 | 91409 | 1.64041666667 | 10476 |
| 011259 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:54pm | Sensor | 1797-S0055-G-TJV.cor | 6854.7 | 1596859.4 | 511953.8 | 91411 | 1.64041666667 | 11259 |
| 011874 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:55pm | Sensor | 1797-S0055-G-TJV.cor | 6854.7 | 1596861.6 | 511952.4 | 91413 | 1.64041666667 | 11874 |
| 011248 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:56pm | Sensor | 1797-S0055-G-TJV.cor | 6854.6 | 1596864.8 | 511950.5 | 91415 | 1.64041666667 | 11248 |
| 010402 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:57pm | Sensor | 1797-S0055-G-TJV.cor | 6854.8 | 1596867.2 | 511949.3 | 91417 | 1.64041666667 | 10402 |
| 011060 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:58pm | Sensor | 1797-S0055-G-TJV.cor | 6854.8 | 1596869.7 | 511947.9 | 91419 | 1.64041666667 | 11060 |
| 012335 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:59pm | Sensor | 1797-S0055-G-TJV.cor | 6854.9 | 1596872.2 | 511947.3 | 91421 | 1.64041666667 | 12335 |
| 013673 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:01pm | Sensor | 1797-S0055-G-TJV.cor | 6854.9 | 1596875.6 | 511947.7 | 91424 | 1.64041666667 | 13673 |
| 011908 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:01pm | Sensor | 1797-S0055-G-TJV.cor | 6854.9 | 1596878.4 | 511948.3 | 91425 | 1.64041666667 | 11908 |
| 010297 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:02pm | Sensor | 1797-S0055-G-TJV.cor | 6855.0 | 1596881.5 | 511948.7 | 91427 | 1.64041666667 | 10297 |
| 010884 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:03pm | Sensor | 1797-S0055-G-TJV.cor | 6854.9 | 1596884.4 | 511949.5 | 91429 | 1.64041666667 | 10884 |
| 012291 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:04pm | Sensor | 1797-S0055-G-TJV.cor | 6855.1 | 1596887.8 | 511950.0 | 91431 | 1.64041666667 | 12291 |
| 012822 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:05pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1596890.6 | 511950.1 | 91433 | 1.64041666667 | 12822 |
| 014155 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:06pm | Sensor | 1797-S0055-G-TJV.cor | 6855.1 | 1596893.7 | 511950.8 | 91435 | 1.64041666667 | 14155 |
| 011849 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:07pm | Sensor | 1797-S0055-G-TJV.cor | 6855.1 | 1596896.4 | 511950.9 | 91437 | 1.64041666667 | 11849 |
| 013432 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:08pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1596899.5 | 511950.2 | 91439 | 1.64041666667 | 13432 |
| 014398 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:09pm | Sensor | 1797-S0055-G-TJV.cor | 6855.2 | 1596902.2 | 511949.7 | 91441 | 1.64041666667 | 14398 |
| 014879 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:10pm | Sensor | 1797-S0055-G-TJV.cor | 6855.2 | 1596904.7 | 511948.6 | 91443 | 1.64041666667 | 14879 |
| 014010 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:11pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1596907.6 | 511947.6 | 91445 | 1.64041666667 | 14010 |
| 013732 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:12pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1596910.6 | 511947.4 | 91447 | 1.64041666667 | 13732 |
| 013243 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:13pm | Sensor | 1797-S0055-G-TJV.cor | 6855.2 | 1596913.5 | 511947.7 | 91449 | 1.64041666667 | 13243 |
| 012610 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:14pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1596916.8 | 511947.8 | 91451 | 1.64041666667 | 12610 |
| 013202 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:15pm | Sensor | 1797-S0055-G-TJV.cor | 6855.2 | 1596920.1 | 511947.9 | 91453 | 1.64041666667 | 13202 |
| 013980 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:16pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1596923.3 | 511947.8 | 91455 | 1.64041666667 | 13980 |
| 014715 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:17pm | Sensor | 1797-S0055-G-TJV.cor | 6855.4 | 1596926.2 | 511947.6 | 91457 | 1.64041666667 | 14715 |
| 013968 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:19pm | Sensor | 1797-S0055-G-TJV.cor | 6855.4 | 1596930.2 | 511947.5 | 91460 | 1.64041666667 | 13968 |
| 011442 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:19pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1596933.1 | 511947.6 | 91461 | 1.64041666667 | 11442 |
| 011740 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:20pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1596936.6 | 511947.2 | 91463 | 1.64041666667 | 11740 |
| 010585 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:21pm | Sensor | 1797-S0055-G-TJV.cor | 6855.5 | 1596939.2 | 511946.7 | 91465 | 1.64041666667 | 10585 |
| 009906 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:22pm | Sensor | 1797-S0055-G-TJV.cor | 6855.4 | 1596943.0 | 511946.5 | 91467 | 1.64041666667 | 9906 |
| 010426 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:23pm | Sensor | 1797-S0055-G-TJV.cor | 6855.5 | 1596945.9 | 511946.4 | 91469 | 1.64041666667 | 10426 |
| 009896 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:24pm | Sensor | 1797-S0055-G-TJV.cor | 6855.5 | 1596949.4 | 511946.3 | 91471 | 1.64041666667 | 9896 |
| 011264 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:25pm | Sensor | 1797-S0055-G-TJV.cor | 6855.6 | 1596950.6 | 511946.0 | 91473 | 1.64041666667 | 11264 |
| 010796 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:26pm | Sensor | 1797-S0055-G-TJV.cor | 6855.7 | 1596950.8 | 511946.0 | 91475 | 1.64041666667 | 10796 |
| 009839 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:27pm | Sensor | 1797-S0055-G-TJV.cor | 6855.6 | 1596950.7 | 511946.1 | 91477 | 1.64041666667 | 9839 |
| 009449 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:28pm | Sensor | 1797-S0055-G-TJV.cor | 6855.6 | 1596950.6 | 511946.3 | 91479 | 1.64041666667 | 9449 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009022 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:29pm | Sensor | 1797-S0055-G-TJV.cor | 6855.5 | 1596951.6 | 511946.2 | 91481 | 1.64041666667 | 9022 |
| 008525 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:30pm | Sensor | 1797-S0055-G-TJV.cor | 6855.5 | 1596954.2 | 511946.1 | 91483 | 1.64041666667 | 8525 |
| 010141 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:31pm | Sensor | 1797-S0055-G-TJV.cor | 6855.7 | 1596957.2 | 511945.7 | 91485 | 1.64041666667 | 10141 |
| 010155 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:32pm | Sensor | 1797-S0055-G-TJV.cor | 6855.6 | 1596960.8 | 511945.3 | 91487 | 1.64041666667 | 10155 |
| 009708 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:33pm | Sensor | 1797-S0055-G-TJV.cor | 6855.8 | 1596963.8 | 511944.7 | 91489 | 1.64041666667 | 9708 |
| 009267 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:34pm | Sensor | 1797-S0055-G-TJV.cor | 6855.7 | 1596966.9 | 511943.8 | 91491 | 1.64041666667 | 9267 |
| 009157 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:35pm | Sensor | 1797-S0055-G-TJV.cor | 6855.8 | 1596969.5 | 511943.2 | 91493 | 1.64041666667 | 9157 |
| 009219 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:36pm | Sensor | 1797-S0055-G-TJV.cor | 6855.8 | 1596973.0 | 511942.5 | 91495 | 1.64041666667 | 9219 |
| 009954 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:37pm | Sensor | 1797-S0055-G-TJV.cor | 6855.7 | 1596976.1 | 511942.0 | 91497 | 1.64041666667 | 9954 |
| 009778 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:38pm | Sensor | 1797-S0055-G-TJV.cor | 6855.6 | 1596979.7 | 511941.0 | 91499 | 1.64041666667 | 9778 |
| 010574 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:39pm | Sensor | 1797-S0055-G-TJV.cor | 6855.6 | 1596983.0 | 511940.2 | 91501 | 1.64041666667 | 10574 |
| 009363 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:40pm | Sensor | 1797-S0055-G-TJV.cor | 6855.7 | 1596986.0 | 511940.0 | 91503 | 1.64041666667 | 9363 |
| 010410 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:41pm | Sensor | 1797-S0055-G-TJV.cor | 6855.7 | 1596989.5 | 511939.4 | 91505 | 1.64041666667 | 10410 |
| 010222 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:42pm | Sensor | 1797-S0055-G-TJV.cor | 6855.8 | 1596992.4 | 511938.7 | 91507 | 1.64041666667 | 10222 |
| 011435 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:43pm | Sensor | 1797-S0055-G-TJV.cor | 6855.7 | 1596995.4 | 511938.3 | 91509 | 1.64041666667 | 11435 |
| 010869 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:44pm | Sensor | 1797-S0055-G-TJV.cor | 6855.9 | 1596999.0 | 511937.9 | 91511 | 1.64041666667 | 10869 |
| 009647 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:45pm | Sensor | 1797-S0055-G-TJV.cor | 6855.8 | 1597001.6 | 511937.4 | 91513 | 1.64041666667 | 9647 |
| 009311 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:46pm | Sensor | 1797-S0055-G-TJV.cor | 6856.0 | 1597004.7 | 511936.9 | 91515 | 1.64041666667 | 9311 |
| 009018 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:47pm | Sensor | 1797-S0055-G-TJV.cor | 6856.1 | 1597007.8 | 511936.7 | 91517 | 1.64041666667 | 9018 |
| 008824 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:48pm | Sensor | 1797-S0055-G-TJV.cor | 6856.1 | 1597010.9 | 511936.3 | 91519 | 1.64041666667 | 8824 |
| 008926 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:49pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597013.8 | 511936.0 | 91521 | 1.64041666667 | 8926 |
| 008921 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:51pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597017.7 | 511935.9 | 91524 | 1.64041666667 | 8921 |
| 009730 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:51pm | Sensor | 1797-S0055-G-TJV.cor | 6856.3 | 1597020.5 | 511935.4 | 91525 | 1.64041666667 | 9730 |
| 009002 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:52pm | Sensor | 1797-S0055-G-TJV.cor | 6856.3 | 1597023.3 | 511934.0 | 91527 | 1.64041666667 | 9002 |
| 008700 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:53pm | Sensor | 1797-S0055-G-TJV.cor | 6856.3 | 1597025.9 | 511932.5 | 91529 | 1.64041666667 | 8700 |
| 011055 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:54pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597028.6 | 511931.6 | 91531 | 1.64041666667 | 11055 |
| 009873 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:55pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597031.1 | 511930.8 | 91533 | 1.64041666667 | 9873 |
| 010208 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:56pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597034.5 | 511930.0 | 91535 | 1.64041666667 | 10208 |
| 011222 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597037.2 | 511929.8 | 91537 | 1.64041666667 | 11222 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597040.7 | 511929.4 | 91539 | 1.64041666667 | 11205 |
| 009941 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:59pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597043.4 | 511929.0 | 91541 | 1.64041666667 | 9941 |
| 010285 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:00pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597046.8 | 511929.0 | 91543 | 1.64041666667 | 10285 |
| 009831 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:01pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597049.7 | 511928.9 | 91545 | 1.64041666667 | 9831 |
| 011247 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:02pm | Sensor | 1797-S0055-G-TJV.cor | 6856.3 | 1597053.7 | 511928.2 | 91547 | 1.64041666667 | 11247 |
| 012472 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:03pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597056.4 | 511927.2 | 91549 | 1.64041666667 | 12472 |
| 012238 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:04pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597058.5 | 511926.5 | 91551 | 1.64041666667 | 12238 |
| 012059 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:05pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597059.0 | 511926.0 | 91553 | 1.64041666667 | 12059 |
| 012255 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:06pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597059.0 | 511925.8 | 91555 | 1.64041666667 | 12255 |
| 013053 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:07pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597058.9 | 511925.8 | 91557 | 1.64041666667 | 13053 |
| 013043 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:08pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597059.0 | 511925.8 | 91559 | 1.64041666667 | 13043 |
| 014510 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:09pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597058.9 | 511926.2 | 91561 | 1.64041666667 | 14510 |
| 013647 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:10pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597060.4 | 511925.4 | 91563 | 1.64041666667 | 13647 |
| 014722 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:11pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597062.6 | 511925.1 | 91565 | 1.64041666667 | 14722 |
| 014030 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:12pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597065.8 | 511924.1 | 91567 | 1.64041666667 | 14030 |
| 014337 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:13pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597068.3 | 511922.9 | 91569 | 1.64041666667 | 14337 |
| 012734 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:14pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597070.7 | 511922.0 | 91571 | 1.64041666667 | 12734 |
| 012063 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:15pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597072.9 | 511920.9 | 91573 | 1.64041666667 | 12063 |
| 010695 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:16pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597075.0 | 511920.3 | 91575 | 1.64041666667 | 10695 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012363 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597076.5 | 511919.3 | 91577 | 1.64041666667 | 12363 |
| 011011 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:19pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597078.9 | 511919.0 | 91580 | 1.64041666667 | 11011 |
| 011362 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:19pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597081.1 | 511918.7 | 91581 | 1.64041666667 | 11362 |
| 013700 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:20pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597084.3 | 511918.4 | 91583 | 1.64041666667 | 13700 |
| 016805 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597086.9 | 511917.2 | 91585 | 1.64041666667 | 16805 |
| 018301 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.3 | 511915.1 | 91587 | 1.64041666667 | 18301 |
| 017835 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:23pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597090.3 | 511914.4 | 91589 | 1.64041666667 | 17835 |
| 016938 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:24pm | Sensor | 1797-S0055-G-TJV.cor | 6852.9 | 1597091.6 | 511915.0 | 91591 | 1.64041666667 | 16938 |
| 016234 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:25pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1597091.1 | 511914.3 | 91593 | 1.64041666667 | 16234 |
| 017948 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:26pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1597091.1 | 511914.2 | 91595 | 1.64041666667 | 17948 |
| 017717 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:27pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1597091.1 | 511914.3 | 91597 | 1.64041666667 | 17717 |
| 016159 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:28pm | Sensor | 1797-S0055-G-TJV.cor | 6854.3 | 1597090.6 | 511914.9 | 91599 | 1.64041666667 | 16159 |
| 017959 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:29pm | Sensor | 1797-S0055-G-TJV.cor | 6854.2 | 1597090.1 | 511916.9 | 91601 | 1.64041666667 | 17959 |
| 017960 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.8 | 511916.2 | 91603 | 1.64041666667 | 17960 |
| 018560 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597088.5 | 511916.3 | 91605 | 1.64041666667 | 18560 |
| 016370 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.5 | 511916.4 | 91607 | 1.64041666667 | 16370 |
| 014502 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597088.5 | 511916.4 | 91609 | 1.64041666667 | 14502 |
| 016495 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597088.6 | 511916.1 | 91611 | 1.64041666667 | 16495 |
| 016424 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597088.5 | 511915.9 | 91613 | 1.64041666667 | 16424 |
| 016736 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597088.6 | 511915.9 | 91615 | 1.64041666667 | 16736 |
| 017084 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597088.6 | 511915.9 | 91617 | 1.64041666667 | 17084 |
| 017621 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597088.6 | 511916.1 | 91619 | 1.64041666667 | 17621 |
| 017275 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.6 | 511916.2 | 91621 | 1.64041666667 | 17275 |
| 016498 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597088.6 | 511916.2 | 91623 | 1.64041666667 | 16498 |
| 018494 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.5 | 511916.3 | 91625 | 1.64041666667 | 18494 |
| 015993 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.5 | 511916.3 | 91627 | 1.64041666667 | 15993 |
| 016598 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.5 | 511916.3 | 91629 | 1.64041666667 | 16598 |
| 015999 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.5 | 511916.2 | 91632 | 1.64041666667 | 15999 |
| 015490 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.5 | 511916.3 | 91633 | 1.64041666667 | 15490 |
| 016622 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.5 | 511916.3 | 91635 | 1.64041666667 | 16622 |
| 015375 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.5 | 511916.3 | 91637 | 1.64041666667 | 15375 |
| 016083 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.6 | 511916.2 | 91639 | 1.64041666667 | 16083 |
| 016321 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.6 | 511916.1 | 91641 | 1.64041666667 | 16321 |
| 016110 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.6 | 511916.1 | 91643 | 1.64041666667 | 16110 |
| 015667 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.7 | 511916.1 | 91645 | 1.64041666667 | 15667 |
| 017417 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.7 | 511916.2 | 91647 | 1.64041666667 | 17417 |
| 015994 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.6 | 511916.3 | 91649 | 1.64041666667 | 15994 |
| 019538 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597089.0 | 511916.4 | 91651 | 1.64041666667 | 19538 |
| 017814 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.7 | 511915.7 | 91653 | 1.64041666667 | 17814 |
| 016603 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:56pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597089.1 | 511914.2 | 91655 | 1.64041666667 | 16603 |
| 016451 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:57pm | Sensor | 1797-S0055-G-TJV.cor | 6855.8 | 1597089.7 | 511913.6 | 91657 | 1.64041666667 | 16451 |
| 019082 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:58pm | Sensor | 1797-S0055-G-TJV.cor | 6852.9 | 1597090.9 | 511914.3 | 91659 | 1.64041666667 | 19082 |
| 018420 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:59pm | Sensor | 1797-S0055-G-TJV.cor | 6852.9 | 1597090.9 | 511914.5 | 91661 | 1.64041666667 | 18420 |
| 017115 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:00pm | Sensor | 1797-S0055-G-TJV.cor | 6852.7 | 1597091.0 | 511914.4 | 91663 | 1.64041666667 | 17115 |
| 017688 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:01pm | Sensor | 1797-S0055-G-TJV.cor | 6852.8 | 1597091.0 | 511914.4 | 91665 | 1.64041666667 | 17688 |
| 017172 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:02pm | Sensor | 1797-S0055-G-TJV.cor | 6852.8 | 1597091.0 | 511914.3 | 91667 | 1.64041666667 | 17172 |
| 017223 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:03pm | Sensor | 1797-S0055-G-TJV.cor | 6853.0 | 1597090.3 | 511913.8 | 91669 | 1.64041666667 | 17223 |
| 018555 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:04pm | Sensor | 1797-S0055-G-TJV.cor | 6853.1 | 1597090.2 | 511913.7 | 91671 | 1.64041666667 | 18555 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017778 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:05pm | Sensor | 1797-S0055-G-TJV.cor | 6853.1 | 1597090.2 | 511913.7 | 91673 | 1.64041666667 | 17778 |
| 016474 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:06pm | Sensor | 1797-S0055-G-TJV.cor | 6853.1 | 1597090.2 | 511913.7 | 91675 | 1.64041666667 | 16474 |
| 015068 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:07pm | Sensor | 1797-S0055-G-TJV.cor | 6853.1 | 1597090.2 | 511913.7 | 91677 | 1.64041666667 | 15068 |
| 016457 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:08pm | Sensor | 1797-S0055-G-TJV.cor | 6853.1 | 1597090.1 | 511913.7 | 91679 | 1.64041666667 | 16457 |
| 016714 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:09pm | Sensor | 1797-S0055-G-TJV.cor | 6853.2 | 1597090.1 | 511913.8 | 91681 | 1.64041666667 | 16714 |
| 015428 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:10pm | Sensor | 1797-S0055-G-TJV.cor | 6852.6 | 1597090.2 | 511913.7 | 91683 | 1.64041666667 | 15428 |
| 017267 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:11pm | Sensor | 1797-S0055-G-TJV.cor | 6853.8 | 1597089.3 | 511913.7 | 91685 | 1.64041666667 | 17267 |
| 015686 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:12pm | Sensor | 1797-S0055-G-TJV.cor | 6854.1 | 1597088.3 | 511915.5 | 91687 | 1.64041666667 | 15686 |
| 017631 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:13pm | Sensor | 1797-S0055-G-TJV.cor | 6854.1 | 1597088.9 | 511916.2 | 91689 | 1.64041666667 | 17631 |
| 017308 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:14pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511917.2 | 91691 | 1.64041666667 | 17308 |
| 016597 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.4 | 511918.9 | 91693 | 1.64041666667 | 16597 |
| 018639 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.6 | 511921.1 | 91695 | 1.64041666667 | 18639 |
| 017829 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597090.0 | 511922.9 | 91697 | 1.64041666667 | 17829 |
| 016457 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.3 | 511925.1 | 91699 | 1.64041666667 | 16457 |
| 017794 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.5 | 511927.0 | 91701 | 1.64041666667 | 17794 |
| 019508 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.2 | 511927.9 | 91703 | 1.64041666667 | 19508 |
| 018047 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.1 | 511928.0 | 91705 | 1.64041666667 | 18047 |
| 018491 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.0 | 511928.1 | 91707 | 1.64041666667 | 18491 |
| 020913 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597088.9 | 511928.1 | 91709 | 1.64041666667 | 20913 |
| 020228 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:24pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.7 | 511928.2 | 91711 | 1.64041666667 | 20228 |
| 021587 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:25pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.7 | 511928.3 | 91713 | 1.64041666667 | 21587 |
| 020006 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597088.9 | 511928.3 | 91715 | 1.64041666667 | 20006 |
| 019461 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.2 | 511928.3 | 91717 | 1.64041666667 | 19461 |
| 018995 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.4 | 511928.2 | 91719 | 1.64041666667 | 18995 |
| 019478 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.4 | 511928.6 | 91721 | 1.64041666667 | 19478 |
| 020349 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597089.4 | 511928.8 | 91723 | 1.64041666667 | 20349 |
| 021287 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597089.3 | 511928.9 | 91725 | 1.64041666667 | 21287 |
| 022001 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.7 | 511928.7 | 91727 | 1.64041666667 | 22001 |
| 020980 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.3 | 511928.5 | 91729 | 1.64041666667 | 20980 |
| 021865 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.1 | 511928.7 | 91731 | 1.64041666667 | 21865 |
| 021366 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.3 | 511928.7 | 91733 | 1.64041666667 | 21366 |
| 020701 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.4 | 511928.8 | 91735 | 1.64041666667 | 20701 |
| 020085 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.5 | 511928.8 | 91737 | 1.64041666667 | 20085 |
| 020081 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.4 | 511928.8 | 91739 | 1.64041666667 | 20081 |
| 020140 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:39pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597089.8 | 511928.5 | 91741 | 1.64041666667 | 20140 |
| 021325 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.6 | 511928.5 | 91743 | 1.64041666667 | 21325 |
| 020061 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.6 | 511928.6 | 91745 | 1.64041666667 | 20061 |
| 019595 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.6 | 511928.5 | 91747 | 1.64041666667 | 19595 |
| 019358 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:43pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597089.6 | 511928.7 | 91749 | 1.64041666667 | 19358 |
| 019539 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.5 | 511928.7 | 91751 | 1.64041666667 | 19539 |
| 019825 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.4 | 511928.7 | 91753 | 1.64041666667 | 19825 |
| 018666 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.3 | 511928.7 | 91755 | 1.64041666667 | 18666 |
| 018346 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597089.3 | 511928.7 | 91757 | 1.64041666667 | 18346 |
| 017726 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597089.2 | 511928.7 | 91759 | 1.64041666667 | 17726 |
| 021171 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597089.2 | 511928.8 | 91761 | 1.64041666667 | 21171 |
| 020263 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597089.3 | 511928.9 | 91763 | 1.64041666667 | 20263 |
| 020365 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597089.1 | 511929.1 | 91765 | 1.64041666667 | 20365 |
| 019911 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.9 | 511929.2 | 91767 | 1.64041666667 | 19911 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 018987 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.9 | 511929.2 | 91769 | 1.64041666667 | 18987 |
| 017347 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597088.5 | 511929.2 | 91771 | 1.64041666667 | 17347 |
| 017656 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597088.5 | 511929.0 | 91773 | 1.64041666667 | 17656 |
| 018244 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597088.5 | 511928.8 | 91775 | 1.64041666667 | 18244 |
| 017131 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597088.6 | 511928.9 | 91777 | 1.64041666667 | 17131 |
| 018892 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.7 | 511928.9 | 91779 | 1.64041666667 | 18892 |
| 018583 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.7 | 511928.8 | 91781 | 1.64041666667 | 18583 |
| 019226 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.6 | 511928.8 | 91783 | 1.64041666667 | 19226 |
| 022116 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.6 | 511928.8 | 91785 | 1.64041666667 | 22116 |
| 018699 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.6 | 511928.8 | 91787 | 1.64041666667 | 18699 |
| 018684 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.9 | 511928.5 | 91789 | 1.64041666667 | 18684 |
| 018111 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:04pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.8 | 511928.2 | 91791 | 1.64041666667 | 18111 |
| 018327 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.1 | 511928.1 | 91793 | 1.64041666667 | 18327 |
| 017392 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597088.5 | 511928.5 | 91795 | 1.64041666667 | 17392 |
| 020518 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597088.4 | 511928.7 | 91797 | 1.64041666667 | 20518 |
| 020969 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.5 | 511928.4 | 91799 | 1.64041666667 | 20969 |
| 021592 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.8 | 511928.2 | 91801 | 1.64041666667 | 21592 |
| 020368 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.9 | 511927.7 | 91803 | 1.64041666667 | 20368 |
| 021352 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.7 | 511927.7 | 91805 | 1.64041666667 | 21352 |
| 019228 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597088.7 | 511927.9 | 91807 | 1.64041666667 | 19228 |
| 021127 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597088.6 | 511928.6 | 91809 | 1.64041666667 | 21127 |
| 022801 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:14pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.5 | 511928.6 | 91811 | 1.64041666667 | 22801 |
| 022860 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:15pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.4 | 511928.6 | 91813 | 1.64041666667 | 22860 |
| 022305 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:16pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.5 | 511928.6 | 91815 | 1.64041666667 | 22305 |
| 023096 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:17pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.6 | 511928.7 | 91817 | 1.64041666667 | 23096 |
| 020864 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:18pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.6 | 511928.7 | 91819 | 1.64041666667 | 20864 |
| 018566 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:19pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.4 | 511928.6 | 91821 | 1.64041666667 | 18566 |
| 018711 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:20pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.5 | 511928.5 | 91823 | 1.64041666667 | 18711 |
| 019257 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:21pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.5 | 511928.5 | 91825 | 1.64041666667 | 19257 |
| 017324 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:22pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.6 | 511928.6 | 91827 | 1.64041666667 | 17324 |
| 018641 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:23pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.6 | 511928.6 | 91829 | 1.64041666667 | 18641 |
| 017440 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:24pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.4 | 511928.5 | 91831 | 1.64041666667 | 17440 |
| 017590 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:25pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.5 | 511928.6 | 91833 | 1.64041666667 | 17590 |
| 017117 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:26pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.5 | 511928.6 | 91835 | 1.64041666667 | 17117 |
| 018229 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:27pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.5 | 511928.7 | 91837 | 1.64041666667 | 18229 |
| 018657 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:28pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.8 | 91839 | 1.64041666667 | 18657 |
| 017564 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:29pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.3 | 511928.7 | 91841 | 1.64041666667 | 17564 |
| 016871 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:30pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.4 | 511928.7 | 91843 | 1.64041666667 | 16871 |
| 017897 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:31pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.4 | 511928.7 | 91845 | 1.64041666667 | 17897 |
| 017494 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:32pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.4 | 511928.6 | 91847 | 1.64041666667 | 17494 |
| 017783 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:33pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.6 | 91849 | 1.64041666667 | 17783 |
| 016626 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:34pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.4 | 511928.6 | 91851 | 1.64041666667 | 16626 |
| 017716 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:35pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.3 | 511928.7 | 91853 | 1.64041666667 | 17716 |
| 017029 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:36pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.1 | 511928.7 | 91855 | 1.64041666667 | 17029 |
| 016887 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:37pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.1 | 511928.7 | 91857 | 1.64041666667 | 16887 |
| 016822 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:38pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.2 | 511928.7 | 91859 | 1.64041666667 | 16822 |
| 016115 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:39pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.2 | 511928.7 | 91861 | 1.64041666667 | 16115 |
| 015848 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:40pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.3 | 511928.7 | 91863 | 1.64041666667 | 15848 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016592 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:41pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.4 | 511928.7 | 91865 | 1.64041666667 | 16592 |
| 016538 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:42pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.3 | 511928.7 | 91867 | 1.64041666667 | 16538 |
| 018384 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:43pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.3 | 511928.7 | 91869 | 1.64041666667 | 18384 |
| 018036 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:44pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.3 | 511928.7 | 91871 | 1.64041666667 | 18036 |
| 017709 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:45pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.4 | 511928.7 | 91873 | 1.64041666667 | 17709 |
| 017777 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:46pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.3 | 511928.7 | 91875 | 1.64041666667 | 17777 |
| 016924 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:47pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.7 | 91877 | 1.64041666667 | 16924 |
| 017221 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:48pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.3 | 511928.7 | 91879 | 1.64041666667 | 17221 |
| 018225 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:49pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.3 | 511928.7 | 91881 | 1.64041666667 | 18225 |
| 017726 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:50pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.3 | 511928.7 | 91883 | 1.64041666667 | 17726 |
| 016671 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:51pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.3 | 511928.8 | 91885 | 1.64041666667 | 16671 |
| 017698 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:52pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.7 | 91887 | 1.64041666667 | 17698 |
| 017384 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:53pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.7 | 91889 | 1.64041666667 | 17384 |
| 018116 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:54pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.7 | 91891 | 1.64041666667 | 18116 |
| 019229 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:55pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.7 | 91893 | 1.64041666667 | 19229 |
| 017377 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:56pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.7 | 91895 | 1.64041666667 | 17377 |
| 016404 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.4 | 511928.7 | 91897 | 1.64041666667 | 16404 |
| 019251 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.3 | 511928.7 | 91899 | 1.64041666667 | 19251 |
| 018192 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:59pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.3 | 511928.7 | 91901 | 1.64041666667 | 18192 |
| 017838 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:00pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.3 | 511928.7 | 91903 | 1.64041666667 | 17838 |
| 017989 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:01pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.4 | 511928.7 | 91905 | 1.64041666667 | 17989 |
| 017937 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:02pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.4 | 511928.7 | 91907 | 1.64041666667 | 17937 |
| 017984 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:03pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.5 | 511928.7 | 91909 | 1.64041666667 | 17984 |
| 018356 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:04pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.5 | 511928.8 | 91911 | 1.64041666667 | 18356 |
| 018299 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:05pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.6 | 511928.7 | 91913 | 1.64041666667 | 18299 |
| 016934 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:06pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.6 | 511928.7 | 91915 | 1.64041666667 | 16934 |
| 018663 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:07pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.5 | 511928.7 | 91917 | 1.64041666667 | 18663 |
| 017805 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:08pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.5 | 511928.7 | 91919 | 1.64041666667 | 17805 |
| 018131 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:09pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.6 | 511928.7 | 91921 | 1.64041666667 | 18131 |
| 018453 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:10pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.5 | 511928.7 | 91923 | 1.64041666667 | 18453 |
| 020633 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:11pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.5 | 511928.8 | 91925 | 1.64041666667 | 20633 |
| 017188 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:12pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.6 | 511928.8 | 91927 | 1.64041666667 | 17188 |
| 018007 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:13pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.6 | 511928.7 | 91929 | 1.64041666667 | 18007 |
| 018961 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:14pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597088.6 | 511928.7 | 91931 | 1.64041666667 | 18961 |
| 019500 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:15pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.6 | 511928.7 | 91933 | 1.64041666667 | 19500 |
| 019995 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:16pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.8 | 511928.8 | 91935 | 1.64041666667 | 19995 |
| 018378 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:17pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597089.0 | 511929.3 | 91937 | 1.64041666667 | 18378 |
| 018244 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:18pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597089.6 | 511928.6 | 91939 | 1.64041666667 | 18244 |
| 017581 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:19pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597090.8 | 511926.3 | 91941 | 1.64041666667 | 17581 |
| 018885 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:20pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597091.6 | 511924.0 | 91943 | 1.64041666667 | 18885 |
| 018761 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:21pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597091.8 | 511923.8 | 91945 | 1.64041666667 | 18761 |
| 016900 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:22pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597091.4 | 511923.4 | 91947 | 1.64041666667 | 16900 |
| 017815 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:23pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597093.7 | 511923.3 | 91949 | 1.64041666667 | 17815 |
| 017533 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:24pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597094.5 | 511923.1 | 91951 | 1.64041666667 | 17533 |
| 016833 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:25pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597094.5 | 511923.2 | 91953 | 1.64041666667 | 16833 |
| 017258 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:26pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597094.5 | 511923.4 | 91955 | 1.64041666667 | 17258 |
| 015624 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:27pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597094.5 | 511923.4 | 91957 | 1.64041666667 | 15624 |
| 017136 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:28pm | Sensor | 1797-S0055-G-TJV.cor | 6856.3 | 1597094.4 | 511923.5 | 91959 | 1.64041666667 | 17136 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017034 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:29pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597093.8 | 511923.5 | 91961 | 1.64041666667 | 17034 |
| 016108 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:30pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597091.7 | 511923.0 | 91963 | 1.64041666667 | 16108 |
| 016507 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:31pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597090.6 | 511923.1 | 91965 | 1.64041666667 | 16507 |
| 016306 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:32pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597090.7 | 511922.6 | 91967 | 1.64041666667 | 16306 |
| 016706 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:33pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597091.0 | 511922.4 | 91969 | 1.64041666667 | 16706 |
| 017346 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:34pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597091.0 | 511922.4 | 91971 | 1.64041666667 | 17346 |
| 017356 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:35pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597091.0 | 511922.5 | 91973 | 1.64041666667 | 17356 |
| 016699 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:36pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597090.3 | 511923.3 | 91975 | 1.64041666667 | 16699 |
| 015244 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:37pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597090.3 | 511924.5 | 91977 | 1.64041666667 | 15244 |
| 015871 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:38pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597089.4 | 511925.5 | 91979 | 1.64041666667 | 15871 |
| 016117 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:39pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597089.1 | 511925.4 | 91981 | 1.64041666667 | 16117 |
| 018969 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:40pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597089.2 | 511926.2 | 91983 | 1.64041666667 | 18969 |
| 018662 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:41pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597088.2 | 511927.4 | 91985 | 1.64041666667 | 18662 |
| 017505 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:42pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597087.9 | 511927.3 | 91987 | 1.64041666667 | 17505 |
| 018386 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:43pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597087.7 | 511927.4 | 91989 | 1.64041666667 | 18386 |
| 016386 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:44pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597087.6 | 511927.3 | 91991 | 1.64041666667 | 16386 |
| 017776 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:45pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597087.7 | 511927.4 | 91993 | 1.64041666667 | 17776 |
| 019654 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:46pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597088.8 | 511928.1 | 91995 | 1.64041666667 | 19654 |
| 021173 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:47pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597089.2 | 511928.9 | 91997 | 1.64041666667 | 21173 |
| 018913 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:48pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597089.5 | 511929.4 | 91999 | 1.64041666667 | 18913 |
| 015048 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:49pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597090.7 | 511929.8 | 92001 | 1.64041666667 | 15048 |
| 014142 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:50pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597091.5 | 511930.8 | 92003 | 1.64041666667 | 14142 |
| 012955 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597092.5 | 511931.0 | 92005 | 1.64041666667 | 12955 |
| 011999 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.4 | 511931.7 | 92007 | 1.64041666667 | 11999 |
| 012329 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.9 | 511932.3 | 92009 | 1.64041666667 | 12329 |
| 012202 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597096.8 | 511933.2 | 92011 | 1.64041666667 | 12202 |
| 013280 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597097.9 | 511932.2 | 92013 | 1.64041666667 | 13280 |
| 012590 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597099.5 | 511932.0 | 92015 | 1.64041666667 | 12590 |
| 012567 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597101.3 | 511931.4 | 92017 | 1.64041666667 | 12567 |
| 011212 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597103.7 | 511931.4 | 92019 | 1.64041666667 | 11212 |
| 012103 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597105.7 | 511931.0 | 92021 | 1.64041666667 | 12103 |
| 011845 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597107.9 | 511931.4 | 92023 | 1.64041666667 | 11845 |
| 010491 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597110.2 | 511930.6 | 92025 | 1.64041666667 | 10491 |
| 010392 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597111.8 | 511931.0 | 92027 | 1.64041666667 | 10392 |
| 010338 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597113.8 | 511931.2 | 92029 | 1.64041666667 | 10338 |
| 012064 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597115.8 | 511931.7 | 92031 | 1.64041666667 | 12064 |
| 012766 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597117.1 | 511931.0 | 92033 | 1.64041666667 | 12766 |
| 011021 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597118.0 | 511931.3 | 92035 | 1.64041666667 | 11021 |
| 012295 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597120.0 | 511932.2 | 92037 | 1.64041666667 | 12295 |
| 013094 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597121.6 | 511933.2 | 92039 | 1.64041666667 | 13094 |
| 011823 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597123.2 | 511933.8 | 92041 | 1.64041666667 | 11823 |
| 010995 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597124.9 | 511934.6 | 92043 | 1.64041666667 | 10995 |
| 012828 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597126.7 | 511935.7 | 92045 | 1.64041666667 | 12828 |
| 011037 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597128.2 | 511937.0 | 92047 | 1.64041666667 | 11037 |
| 011909 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597129.5 | 511938.1 | 92049 | 1.64041666667 | 11909 |
| 012367 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597131.4 | 511940.0 | 92051 | 1.64041666667 | 12367 |
| 013261 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597133.2 | 511940.9 | 92053 | 1.64041666667 | 13261 |
| 011535 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597135.0 | 511942.1 | 92055 | 1.64041666667 | 11535 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012333 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597137.0 | 511943.3 | 92057 | 1.64041666667 | 12333 |
| 012983 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597139.1 | 511944.6 | 92059 | 1.64041666667 | 12983 |
| 012696 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597140.9 | 511945.6 | 92061 | 1.64041666667 | 12696 |
| 012384 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597142.9 | 511946.7 | 92063 | 1.64041666667 | 12384 |
| 011526 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597145.0 | 511948.2 | 92065 | 1.64041666667 | 11526 |
| 012391 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597147.3 | 511949.7 | 92067 | 1.64041666667 | 12391 |
| 015277 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597148.9 | 511951.0 | 92069 | 1.64041666667 | 15277 |
| 015129 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597151.3 | 511952.5 | 92071 | 1.64041666667 | 15129 |
| 016652 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597152.7 | 511953.6 | 92073 | 1.64041666667 | 16652 |
| 016403 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597154.9 | 511954.5 | 92075 | 1.64041666667 | 16403 |
| 015050 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597156.2 | 511955.9 | 92077 | 1.64041666667 | 15050 |
| 014952 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597158.4 | 511956.9 | 92079 | 1.64041666667 | 14952 |
| 015678 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597159.7 | 511958.2 | 92081 | 1.64041666667 | 15678 |
| 012229 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597162.0 | 511959.5 | 92083 | 1.64041666667 | 12229 |
| 014907 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597163.7 | 511960.8 | 92085 | 1.64041666667 | 14907 |
| 015577 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597166.2 | 511961.7 | 92087 | 1.64041666667 | 15577 |
| 014634 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597167.9 | 511963.1 | 92089 | 1.64041666667 | 14634 |
| 012808 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597170.2 | 511963.9 | 92091 | 1.64041666667 | 12808 |
| 012622 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597172.0 | 511965.3 | 92093 | 1.64041666667 | 12622 |
| 011465 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597174.2 | 511966.7 | 92095 | 1.64041666667 | 11465 |
| 011776 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597175.8 | 511967.9 | 92097 | 1.64041666667 | 11776 |
| 013024 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597177.9 | 511968.9 | 92099 | 1.64041666667 | 13024 |
| 013066 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597179.8 | 511969.7 | 92101 | 1.64041666667 | 13066 |
| 013226 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597181.8 | 511970.2 | 92103 | 1.64041666667 | 13226 |
| 012396 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597182.7 | 511970.8 | 92105 | 1.64041666667 | 12396 |
| 012249 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597185.0 | 511971.9 | 92107 | 1.64041666667 | 12249 |
| 011972 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597186.5 | 511972.9 | 92109 | 1.64041666667 | 11972 |
| 015683 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597188.5 | 511974.1 | 92111 | 1.64041666667 | 15683 |
| 014900 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597189.2 | 511975.0 | 92113 | 1.64041666667 | 14900 |
| 013415 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597191.1 | 511976.0 | 92115 | 1.64041666667 | 13415 |
| 013373 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597193.1 | 511976.7 | 92117 | 1.64041666667 | 13373 |
| 012823 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597195.4 | 511978.0 | 92119 | 1.64041666667 | 12823 |
| 012656 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597197.5 | 511979.3 | 92121 | 1.64041666667 | 12656 |
| 014924 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597199.4 | 511980.9 | 92123 | 1.64041666667 | 14924 |
| 013871 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597201.0 | 511981.4 | 92125 | 1.64041666667 | 13871 |
| 011807 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597201.6 | 511982.3 | 92127 | 1.64041666667 | 11807 |
| 011921 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597201.4 | 511982.7 | 92129 | 1.64041666667 | 11921 |
| 012160 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597201.6 | 511982.7 | 92131 | 1.64041666667 | 12160 |
| 014290 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597201.6 | 511982.7 | 92133 | 1.64041666667 | 14290 |
| 013172 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597201.6 | 511982.8 | 92135 | 1.64041666667 | 13172 |
| 012653 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597201.5 | 511982.8 | 92137 | 1.64041666667 | 12653 |
| 012913 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597201.6 | 511982.3 | 92139 | 1.64041666667 | 12913 |
| 014538 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597201.8 | 511981.6 | 92141 | 1.64041666667 | 14538 |
| 013654 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597203.7 | 511981.0 | 92143 | 1.64041666667 | 13654 |
| 013613 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597205.5 | 511980.0 | 92145 | 1.64041666667 | 13613 |
| 014563 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597206.5 | 511979.9 | 92147 | 1.64041666667 | 14563 |
| 013601 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597206.9 | 511980.0 | 92149 | 1.64041666667 | 13601 |
| 014410 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597207.8 | 511978.4 | 92151 | 1.64041666667 | 14410 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015182 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597209.6 | 511976.5 | 92153 | 1.64041666667 | 15182 |
| 013365 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:06pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597210.5 | 511974.7 | 92155 | 1.64041666667 | 13365 |
| 013631 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597210.5 | 511974.5 | 92157 | 1.64041666667 | 13631 |
| 013098 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597210.5 | 511974.6 | 92159 | 1.64041666667 | 13098 |
| 012394 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597210.5 | 511974.7 | 92161 | 1.64041666667 | 12394 |
| 012968 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597210.5 | 511974.7 | 92163 | 1.64041666667 | 12968 |
| 012452 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597210.5 | 511974.8 | 92165 | 1.64041666667 | 12452 |
| 012893 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597210.9 | 511974.8 | 92167 | 1.64041666667 | 12893 |
| 013423 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597211.9 | 511974.3 | 92169 | 1.64041666667 | 13423 |
| 013316 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597212.5 | 511974.3 | 92171 | 1.64041666667 | 13316 |
| 014639 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:15pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597212.7 | 511974.9 | 92173 | 1.64041666667 | 14639 |
| 013199 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597210.9 | 511973.9 | 92175 | 1.64041666667 | 13199 |
| 013860 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597210.2 | 511974.2 | 92177 | 1.64041666667 | 13860 |
| 012615 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597210.3 | 511974.9 | 92179 | 1.64041666667 | 12615 |
| 014403 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597210.2 | 511975.7 | 92181 | 1.64041666667 | 14403 |
| 015060 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:20pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597209.4 | 511977.1 | 92183 | 1.64041666667 | 15060 |
| 013455 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597208.5 | 511977.9 | 92185 | 1.64041666667 | 13455 |
| 013023 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:22pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597208.1 | 511978.1 | 92187 | 1.64041666667 | 13023 |
| 013696 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:23pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597207.8 | 511978.4 | 92189 | 1.64041666667 | 13696 |
| 012364 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597207.6 | 511978.5 | 92191 | 1.64041666667 | 12364 |
| 012571 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597207.1 | 511978.2 | 92193 | 1.64041666667 | 12571 |
| 013522 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597206.3 | 511976.8 | 92195 | 1.64041666667 | 13522 |
| 012110 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597204.6 | 511975.2 | 92197 | 1.64041666667 | 12110 |
| 013767 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597201.5 | 511974.1 | 92199 | 1.64041666667 | 13767 |
| 012442 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597199.6 | 511973.6 | 92201 | 1.64041666667 | 12442 |
| 013130 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:30pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597197.7 | 511973.3 | 92203 | 1.64041666667 | 13130 |
| 011802 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:31pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597196.0 | 511972.5 | 92205 | 1.64041666667 | 11802 |
| 013720 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597194.0 | 511971.1 | 92207 | 1.64041666667 | 13720 |
| 013420 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597193.0 | 511969.3 | 92209 | 1.64041666667 | 13420 |
| 013945 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597190.8 | 511968.6 | 92211 | 1.64041666667 | 13945 |
| 013866 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597188.7 | 511967.7 | 92213 | 1.64041666667 | 13866 |
| 014986 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597186.0 | 511967.0 | 92215 | 1.64041666667 | 14986 |
| 014606 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597184.2 | 511965.6 | 92217 | 1.64041666667 | 14606 |
| 013401 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597181.8 | 511963.8 | 92219 | 1.64041666667 | 13401 |
| 014150 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597179.9 | 511962.9 | 92221 | 1.64041666667 | 14150 |
| 013317 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597177.7 | 511961.5 | 92223 | 1.64041666667 | 13317 |
| 013379 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597175.9 | 511960.4 | 92225 | 1.64041666667 | 13379 |
| 012585 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597174.4 | 511958.5 | 92227 | 1.64041666667 | 12585 |
| 012356 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597173.4 | 511958.2 | 92229 | 1.64041666667 | 12356 |
| 013799 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597171.7 | 511957.3 | 92231 | 1.64041666667 | 13799 |
| 014009 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597169.8 | 511956.8 | 92233 | 1.64041666667 | 14009 |
| 014152 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597167.3 | 511955.5 | 92235 | 1.64041666667 | 14152 |
| 016408 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:47pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597164.8 | 511954.9 | 92237 | 1.64041666667 | 16408 |
| 016282 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:48pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597162.6 | 511953.6 | 92239 | 1.64041666667 | 16282 |
| 017030 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:49pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597160.3 | 511952.6 | 92241 | 1.64041666667 | 17030 |
| 017697 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:50pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597158.4 | 511951.1 | 92243 | 1.64041666667 | 17697 |
| 019454 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:51pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597156.4 | 511949.5 | 92245 | 1.64041666667 | 19454 |
| 019863 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:52pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597154.0 | 511948.0 | 92247 | 1.64041666667 | 19863 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016875 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597151.9 | 511946.5 | 92249 | 1.64041666667 | 16875 |
| 014838 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:54pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597149.2 | 511945.2 | 92251 | 1.64041666667 | 14838 |
| 013069 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597147.5 | 511943.4 | 92253 | 1.64041666667 | 13069 |
| 012507 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597144.8 | 511942.4 | 92255 | 1.64041666667 | 12507 |
| 013057 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597142.9 | 511941.1 | 92257 | 1.64041666667 | 13057 |
| 013524 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597140.2 | 511940.1 | 92259 | 1.64041666667 | 13524 |
| 012861 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597137.8 | 511939.4 | 92261 | 1.64041666667 | 12861 |
| 011285 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597135.1 | 511937.9 | 92263 | 1.64041666667 | 11285 |
| 011701 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597132.8 | 511936.8 | 92265 | 1.64041666667 | 11701 |
| 011535 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597130.1 | 511935.4 | 92267 | 1.64041666667 | 11535 |
| 011403 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597127.9 | 511934.9 | 92269 | 1.64041666667 | 11403 |
| 012361 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597125.4 | 511934.0 | 92271 | 1.64041666667 | 12361 |
| 011160 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597123.1 | 511934.1 | 92273 | 1.64041666667 | 11160 |
| 011970 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597121.6 | 511932.8 | 92275 | 1.64041666667 | 11970 |
| 011152 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597119.7 | 511932.0 | 92277 | 1.64041666667 | 11152 |
| 012358 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597118.2 | 511930.4 | 92279 | 1.64041666667 | 12358 |
| 011879 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597116.5 | 511929.1 | 92281 | 1.64041666667 | 11879 |
| 012630 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597114.2 | 511928.4 | 92283 | 1.64041666667 | 12630 |
| 011377 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597112.1 | 511927.9 | 92285 | 1.64041666667 | 11377 |
| 014004 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597111.1 | 511927.2 | 92287 | 1.64041666667 | 14004 |
| 012561 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597109.4 | 511926.0 | 92289 | 1.64041666667 | 12561 |
| 010190 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597107.2 | 511925.0 | 92291 | 1.64041666667 | 10190 |
| 009657 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:15pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597105.1 | 511924.4 | 92293 | 1.64041666667 | 9657 |
| 010334 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:16pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597103.0 | 511924.6 | 92295 | 1.64041666667 | 10334 |
| 009633 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:17pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597101.3 | 511924.8 | 92297 | 1.64041666667 | 9633 |
| 009128 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:18pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597098.9 | 511924.6 | 92299 | 1.64041666667 | 9128 |
| 011312 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597098.2 | 511924.4 | 92301 | 1.64041666667 | 11312 |
| 011378 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.7 | 511924.3 | 92303 | 1.64041666667 | 11378 |
| 010494 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.5 | 511924.3 | 92305 | 1.64041666667 | 10494 |
| 010813 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.6 | 511924.2 | 92307 | 1.64041666667 | 10813 |
| 011163 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597097.4 | 511924.5 | 92309 | 1.64041666667 | 11163 |
| 011430 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:24pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597097.8 | 511923.5 | 92311 | 1.64041666667 | 11430 |
| 010477 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597098.5 | 511922.1 | 92313 | 1.64041666667 | 10477 |
| 012069 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597099.5 | 511920.2 | 92315 | 1.64041666667 | 12069 |
| 012077 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597098.9 | 511919.1 | 92317 | 1.64041666667 | 12077 |
| 009889 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597098.2 | 511918.4 | 92319 | 1.64041666667 | 9889 |
| 010332 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.8 | 511918.3 | 92321 | 1.64041666667 | 10332 |
| 010593 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597098.2 | 511918.5 | 92323 | 1.64041666667 | 10593 |
| 010838 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:31pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597097.8 | 511916.6 | 92325 | 1.64041666667 | 10838 |
| 011619 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:32pm | Sensor | 1797-S0055-G-TJV.cor | 6854.3 | 1597098.0 | 511915.7 | 92327 | 1.64041666667 | 11619 |
| 011095 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:33pm | Sensor | 1797-S0055-G-TJV.cor | 6853.5 | 1597098.5 | 511915.9 | 92329 | 1.64041666667 | 11095 |
| 010483 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:34pm | Sensor | 1797-S0055-G-TJV.cor | 6852.4 | 1597098.3 | 511916.8 | 92331 | 1.64041666667 | 10483 |
| 010301 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:35pm | Sensor | 1797-S0055-G-TJV.cor | 6855.7 | 1597098.0 | 511917.7 | 92333 | 1.64041666667 | 10301 |
| 010885 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597096.9 | 511917.8 | 92335 | 1.64041666667 | 10885 |
| 012561 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597097.6 | 511918.5 | 92337 | 1.64041666667 | 12561 |
| 011150 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597099.4 | 511919.5 | 92339 | 1.64041666667 | 11150 |
| 011757 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597099.3 | 511920.2 | 92341 | 1.64041666667 | 11757 |
| 011489 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597098.9 | 511921.9 | 92343 | 1.64041666667 | 11489 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012292 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597097.8 | 511922.0 | 92345 | 1.64041666667 | 12292 |
| 013513 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597095.9 | 511923.1 | 92347 | 1.64041666667 | 13513 |
| 012978 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.1 | 511923.2 | 92349 | 1.64041666667 | 12978 |
| 017974 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597092.3 | 511924.1 | 92351 | 1.64041666667 | 17974 |
| 019103 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597091.0 | 511924.0 | 92353 | 1.64041666667 | 19103 |
| 018396 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597089.5 | 511925.6 | 92355 | 1.64041666667 | 18396 |
| 018789 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:47pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597088.1 | 511925.8 | 92357 | 1.64041666667 | 18789 |
| 014627 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597086.7 | 511927.0 | 92359 | 1.64041666667 | 14627 |
| 013526 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597085.5 | 511926.6 | 92361 | 1.64041666667 | 13526 |
| 012831 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597083.8 | 511926.3 | 92363 | 1.64041666667 | 12831 |
| 011638 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597082.4 | 511925.4 | 92365 | 1.64041666667 | 11638 |
| 010979 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:52pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597080.5 | 511925.3 | 92367 | 1.64041666667 | 10979 |
| 010875 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:53pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597080.0 | 511924.0 | 92369 | 1.64041666667 | 10875 |
| 010758 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:54pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597079.4 | 511922.5 | 92371 | 1.64041666667 | 10758 |
| 010159 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:55pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597079.4 | 511921.8 | 92373 | 1.64041666667 | 10159 |
| 010879 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:56pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597079.1 | 511921.5 | 92375 | 1.64041666667 | 10879 |
| 010580 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597079.0 | 511921.5 | 92377 | 1.64041666667 | 10580 |
| 009155 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597079.0 | 511921.5 | 92379 | 1.64041666667 | 9155 |
| 009428 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:59pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597079.1 | 511921.3 | 92381 | 1.64041666667 | 9428 |
| 010307 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:00pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597079.5 | 511920.7 | 92383 | 1.64041666667 | 10307 |
| 010886 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:01pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597080.2 | 511920.6 | 92385 | 1.64041666667 | 10886 |
| 010341 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:02pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597081.4 | 511919.8 | 92387 | 1.64041666667 | 10341 |
| 012065 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:03pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597083.4 | 511919.1 | 92389 | 1.64041666667 | 12065 |
| 015526 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:04pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597085.6 | 511918.1 | 92391 | 1.64041666667 | 15526 |
| 016241 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:05pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597086.9 | 511918.5 | 92393 | 1.64041666667 | 16241 |
| 017140 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:06pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.1 | 511919.3 | 92395 | 1.64041666667 | 17140 |
| 018415 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.4 | 511919.9 | 92397 | 1.64041666667 | 18415 |
| 018853 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597090.6 | 511920.9 | 92399 | 1.64041666667 | 18853 |
| 018333 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597091.7 | 511921.3 | 92401 | 1.64041666667 | 18333 |
| 016433 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597092.9 | 511922.1 | 92403 | 1.64041666667 | 16433 |
| 013588 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.6 | 511922.2 | 92405 | 1.64041666667 | 13588 |
| 011047 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597096.4 | 511922.6 | 92407 | 1.64041666667 | 11047 |
| 011401 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.9 | 511921.6 | 92409 | 1.64041666667 | 11401 |
| 010680 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597098.9 | 511921.5 | 92411 | 1.64041666667 | 10680 |
| 010470 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597099.2 | 511921.4 | 92413 | 1.64041666667 | 10470 |
| 010657 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.3 | 511921.4 | 92415 | 1.64041666667 | 10657 |
| 012804 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.2 | 511921.4 | 92417 | 1.64041666667 | 12804 |
| 013461 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597099.2 | 511921.4 | 92419 | 1.64041666667 | 13461 |
| 010835 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.2 | 511921.5 | 92421 | 1.64041666667 | 10835 |
| 010838 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.2 | 511921.5 | 92423 | 1.64041666667 | 10838 |
| 011109 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.2 | 511921.5 | 92425 | 1.64041666667 | 11109 |
| 010787 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.2 | 511921.5 | 92427 | 1.64041666667 | 10787 |
| 011456 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.2 | 511921.5 | 92429 | 1.64041666667 | 11456 |
| 012764 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597099.6 | 511921.0 | 92431 | 1.64041666667 | 12764 |
| 010931 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597099.9 | 511920.7 | 92433 | 1.64041666667 | 10931 |
| 011402 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597099.3 | 511920.9 | 92435 | 1.64041666667 | 11402 |
| 012030 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597099.6 | 511921.3 | 92437 | 1.64041666667 | 12030 |
| 011437 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597100.8 | 511922.1 | 92439 | 1.64041666667 | 11437 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011919 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597101.4 | 511923.0 | 92441 | 1.64041666667 | 11919 |
| 011980 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597102.9 | 511923.3 | 92443 | 1.64041666667 | 11980 |
| 011395 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597104.0 | 511924.0 | 92445 | 1.64041666667 | 11395 |
| 010948 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597104.9 | 511923.7 | 92447 | 1.64041666667 | 10948 |
| 010567 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597106.0 | 511924.5 | 92449 | 1.64041666667 | 10567 |
| 011041 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597108.0 | 511924.9 | 92451 | 1.64041666667 | 11041 |
| 011220 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597109.4 | 511925.3 | 92453 | 1.64041666667 | 11220 |
| 010995 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597111.5 | 511925.4 | 92455 | 1.64041666667 | 10995 |
| 010278 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597113.0 | 511925.8 | 92457 | 1.64041666667 | 10278 |
| 010159 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597114.5 | 511926.5 | 92459 | 1.64041666667 | 10159 |
| 009920 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597115.9 | 511927.0 | 92461 | 1.64041666667 | 9920 |
| 012200 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597118.3 | 511927.4 | 92463 | 1.64041666667 | 12200 |
| 010850 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597120.5 | 511928.0 | 92465 | 1.64041666667 | 10850 |
| 009762 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597122.8 | 511928.7 | 92467 | 1.64041666667 | 9762 |
| 012460 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597123.6 | 511928.8 | 92469 | 1.64041666667 | 12460 |
| 012535 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597124.9 | 511928.0 | 92471 | 1.64041666667 | 12535 |
| 011113 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597126.6 | 511927.8 | 92473 | 1.64041666667 | 11113 |
| 010548 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597128.4 | 511927.7 | 92475 | 1.64041666667 | 10548 |
| 011727 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597128.9 | 511927.8 | 92477 | 1.64041666667 | 11727 |
| 011991 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597128.9 | 511928.0 | 92479 | 1.64041666667 | 11991 |
| 010858 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597128.7 | 511928.0 | 92481 | 1.64041666667 | 10858 |
| 012314 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597128.7 | 511927.9 | 92483 | 1.64041666667 | 12314 |
| 012948 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597129.1 | 511927.5 | 92485 | 1.64041666667 | 12948 |
| 011127 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597130.6 | 511927.4 | 92487 | 1.64041666667 | 11127 |
| 012801 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597132.3 | 511926.9 | 92489 | 1.64041666667 | 12801 |
| 012530 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597134.4 | 511927.2 | 92491 | 1.64041666667 | 12530 |
| 012402 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597136.4 | 511927.4 | 92493 | 1.64041666667 | 12402 |
| 012100 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597138.1 | 511928.0 | 92495 | 1.64041666667 | 12100 |
| 012445 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597140.0 | 511927.8 | 92497 | 1.64041666667 | 12445 |
| 010911 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597141.7 | 511928.6 | 92499 | 1.64041666667 | 10911 |
| 011607 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597143.5 | 511929.0 | 92501 | 1.64041666667 | 11607 |
| 011452 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597145.0 | 511930.3 | 92503 | 1.64041666667 | 11452 |
| 012013 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597146.5 | 511932.0 | 92505 | 1.64041666667 | 12013 |
| 012573 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597147.7 | 511934.1 | 92507 | 1.64041666667 | 12573 |
| 012803 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597149.2 | 511936.2 | 92509 | 1.64041666667 | 12803 |
| 011690 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597150.9 | 511937.8 | 92511 | 1.64041666667 | 11690 |
| 011725 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:05pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597152.5 | 511939.1 | 92513 | 1.64041666667 | 11725 |
| 013405 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:06pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597154.8 | 511940.6 | 92515 | 1.64041666667 | 13405 |
| 014121 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597156.7 | 511942.4 | 92517 | 1.64041666667 | 14121 |
| 016040 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597159.2 | 511944.2 | 92519 | 1.64041666667 | 16040 |
| 018590 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597160.8 | 511945.8 | 92521 | 1.64041666667 | 18590 |
| 018297 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597162.8 | 511947.1 | 92523 | 1.64041666667 | 18297 |
| 017564 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597163.1 | 511947.5 | 92525 | 1.64041666667 | 17564 |
| 017981 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597163.1 | 511947.6 | 92527 | 1.64041666667 | 17981 |
| 018295 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597163.1 | 511947.7 | 92529 | 1.64041666667 | 18295 |
| 017713 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597163.2 | 511947.9 | 92531 | 1.64041666667 | 17713 |
| 019098 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597163.3 | 511947.6 | 92533 | 1.64041666667 | 19098 |
| 019444 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597162.3 | 511947.8 | 92535 | 1.64041666667 | 19444 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 020461 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597161.5 | 511948.2 | 92537 | 1.64041666667 | 20461 |
| 020115 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597161.6 | 511948.0 | 92539 | 1.64041666667 | 20115 |
| 019758 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597162.4 | 511947.0 | 92541 | 1.64041666667 | 19758 |
| 016549 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:20pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597162.8 | 511947.6 | 92543 | 1.64041666667 | 16549 |
| 017727 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597164.2 | 511948.4 | 92545 | 1.64041666667 | 17727 |
| 018802 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:22pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597166.7 | 511950.7 | 92547 | 1.64041666667 | 18802 |
| 019310 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597167.8 | 511951.1 | 92549 | 1.64041666667 | 19310 |
| 015627 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597169.5 | 511952.3 | 92551 | 1.64041666667 | 15627 |
| 012787 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597171.4 | 511952.9 | 92553 | 1.64041666667 | 12787 |
| 012406 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597173.0 | 511954.3 | 92555 | 1.64041666667 | 12406 |
| 012851 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597174.4 | 511954.9 | 92557 | 1.64041666667 | 12851 |
| 012363 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597175.9 | 511956.2 | 92559 | 1.64041666667 | 12363 |
| 012390 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597177.5 | 511955.8 | 92561 | 1.64041666667 | 12390 |
| 012187 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:30pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597179.9 | 511956.2 | 92563 | 1.64041666667 | 12187 |
| 013217 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:31pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597182.0 | 511955.5 | 92565 | 1.64041666667 | 13217 |
| 012004 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597184.5 | 511956.5 | 92567 | 1.64041666667 | 12004 |
| 012091 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597186.5 | 511957.5 | 92569 | 1.64041666667 | 12091 |
| 013612 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597187.8 | 511959.3 | 92571 | 1.64041666667 | 13612 |
| 012763 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597189.2 | 511960.5 | 92573 | 1.64041666667 | 12763 |
| 012911 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597191.4 | 511961.7 | 92575 | 1.64041666667 | 12911 |
| 014927 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597193.0 | 511963.1 | 92577 | 1.64041666667 | 14927 |
| 013991 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:38pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597195.4 | 511964.4 | 92579 | 1.64041666667 | 13991 |
| 013848 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:39pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597196.6 | 511965.8 | 92581 | 1.64041666667 | 13848 |
| 014772 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:40pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597198.6 | 511967.5 | 92583 | 1.64041666667 | 14772 |
| 014613 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:41pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597199.8 | 511969.0 | 92585 | 1.64041666667 | 14613 |
| 015323 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597202.1 | 511970.6 | 92587 | 1.64041666667 | 15323 |
| 013400 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597204.2 | 511971.8 | 92589 | 1.64041666667 | 13400 |
| 013880 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597207.0 | 511972.8 | 92591 | 1.64041666667 | 13880 |
| 014180 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597209.3 | 511973.6 | 92593 | 1.64041666667 | 14180 |
| 014495 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597211.3 | 511974.1 | 92595 | 1.64041666667 | 14495 |
| 013013 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:47pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597211.3 | 511974.5 | 92597 | 1.64041666667 | 13013 |
| 014023 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:48pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597211.5 | 511973.7 | 92599 | 1.64041666667 | 14023 |
| 013586 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:49pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597212.6 | 511972.0 | 92601 | 1.64041666667 | 13586 |
| 012696 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:50pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597213.6 | 511969.9 | 92603 | 1.64041666667 | 12696 |
| 015804 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:51pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597214.5 | 511969.1 | 92605 | 1.64041666667 | 15804 |
| 012981 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:52pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597214.6 | 511969.5 | 92607 | 1.64041666667 | 12981 |
| 013655 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597215.0 | 511968.0 | 92609 | 1.64041666667 | 13655 |
| 015683 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:54pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597216.0 | 511965.6 | 92611 | 1.64041666667 | 15683 |
| 014601 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597216.8 | 511963.5 | 92613 | 1.64041666667 | 14601 |
| 014000 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597217.3 | 511962.6 | 92615 | 1.64041666667 | 14000 |
| 014570 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597217.6 | 511962.7 | 92617 | 1.64041666667 | 14570 |
| 014322 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597217.5 | 511964.3 | 92619 | 1.64041666667 | 14322 |
| 013660 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:59pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597216.5 | 511964.5 | 92621 | 1.64041666667 | 13660 |
| 013525 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:00pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597216.8 | 511965.1 | 92623 | 1.64041666667 | 13525 |
| 014121 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:01pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597216.8 | 511966.6 | 92625 | 1.64041666667 | 14121 |
| 014300 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597215.7 | 511968.3 | 92627 | 1.64041666667 | 14300 |
| 013145 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:03pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597214.6 | 511969.4 | 92629 | 1.64041666667 | 13145 |
| 012826 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:04pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597214.5 | 511969.7 | 92631 | 1.64041666667 | 12826 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014306 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:05pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597214.6 | 511969.7 | 92633 | 1.64041666667 | 14306 |
| 014496 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:06pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597214.7 | 511969.6 | 92635 | 1.64041666667 | 14496 |
| 014244 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597214.6 | 511969.6 | 92637 | 1.64041666667 | 14244 |
| 013971 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597214.1 | 511969.3 | 92639 | 1.64041666667 | 13971 |
| 014322 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597212.4 | 511968.4 | 92641 | 1.64041666667 | 14322 |
| 014830 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597210.5 | 511967.5 | 92643 | 1.64041666667 | 14830 |
| 014477 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597208.6 | 511966.3 | 92645 | 1.64041666667 | 14477 |
| 013489 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597206.5 | 511965.5 | 92647 | 1.64041666667 | 13489 |
| 012252 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597204.8 | 511965.1 | 92649 | 1.64041666667 | 12252 |
| 013293 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597202.8 | 511965.0 | 92651 | 1.64041666667 | 13293 |
| 016373 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597201.1 | 511964.0 | 92653 | 1.64041666667 | 16373 |
| 013933 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597198.5 | 511963.0 | 92655 | 1.64041666667 | 13933 |
| 013413 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597197.0 | 511961.7 | 92657 | 1.64041666667 | 13413 |
| 013313 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597194.8 | 511960.3 | 92659 | 1.64041666667 | 13313 |
| 013648 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597193.2 | 511958.8 | 92661 | 1.64041666667 | 13648 |
| 014332 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:20pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597191.0 | 511957.8 | 92663 | 1.64041666667 | 14332 |
| 013483 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597189.3 | 511956.6 | 92665 | 1.64041666667 | 13483 |
| 013420 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:22pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597187.2 | 511955.2 | 92667 | 1.64041666667 | 13420 |
| 014785 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:23pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597185.9 | 511953.9 | 92669 | 1.64041666667 | 14785 |
| 014196 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597184.3 | 511953.3 | 92671 | 1.64041666667 | 14196 |
| 013989 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597183.9 | 511953.1 | 92673 | 1.64041666667 | 13989 |
| 011927 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597183.9 | 511953.1 | 92675 | 1.64041666667 | 11927 |
| 014501 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597183.9 | 511953.1 | 92677 | 1.64041666667 | 14501 |
| 014185 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597183.9 | 511953.1 | 92679 | 1.64041666667 | 14185 |
| 014946 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597183.9 | 511953.0 | 92681 | 1.64041666667 | 14946 |
| 014896 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597183.9 | 511953.0 | 92683 | 1.64041666667 | 14896 |
| 014824 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597183.9 | 511953.0 | 92685 | 1.64041666667 | 14824 |
| 012916 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597183.8 | 511953.3 | 92687 | 1.64041666667 | 12916 |
| 011719 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597184.0 | 511953.5 | 92689 | 1.64041666667 | 11719 |
| 012859 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597184.0 | 511953.5 | 92691 | 1.64041666667 | 12859 |
| 012095 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597184.4 | 511952.3 | 92693 | 1.64041666667 | 12095 |
| 013583 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597184.4 | 511951.4 | 92695 | 1.64041666667 | 13583 |
| 011886 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597183.8 | 511951.0 | 92697 | 1.64041666667 | 11886 |
| 013201 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597183.9 | 511950.4 | 92699 | 1.64041666667 | 13201 |
| 013350 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597184.2 | 511949.3 | 92701 | 1.64041666667 | 13350 |
| 013027 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597184.4 | 511948.0 | 92703 | 1.64041666667 | 13027 |
| 013127 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597184.4 | 511949.5 | 92705 | 1.64041666667 | 13127 |
| 012191 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597184.4 | 511950.9 | 92707 | 1.64041666667 | 12191 |
| 012648 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597183.3 | 511951.2 | 92709 | 1.64041666667 | 12648 |
| 013752 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597181.2 | 511951.4 | 92711 | 1.64041666667 | 13752 |
| 013518 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597180.4 | 511950.8 | 92713 | 1.64041666667 | 13518 |
| 013789 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597178.0 | 511950.1 | 92715 | 1.64041666667 | 13789 |
| 014337 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:47pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597175.9 | 511949.1 | 92717 | 1.64041666667 | 14337 |
| 014144 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:48pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597173.5 | 511947.9 | 92719 | 1.64041666667 | 14144 |
| 014512 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597171.4 | 511947.0 | 92721 | 1.64041666667 | 14512 |
| 015089 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597168.6 | 511946.0 | 92723 | 1.64041666667 | 15089 |
| 017302 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597165.9 | 511945.1 | 92725 | 1.64041666667 | 17302 |
| 018245 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597163.3 | 511943.4 | 92727 | 1.64041666667 | 18245 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016171 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597161.0 | 511942.2 | 92729 | 1.64041666667 | 16171 |
| 015112 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597158.8 | 511940.4 | 92731 | 1.64041666667 | 15112 |
| 013078 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597156.6 | 511939.2 | 92733 | 1.64041666667 | 13078 |
| 012089 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597154.4 | 511937.7 | 92735 | 1.64041666667 | 12089 |
| 014002 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597152.2 | 511936.5 | 92737 | 1.64041666667 | 14002 |
| 012140 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597149.1 | 511935.5 | 92739 | 1.64041666667 | 12140 |
| 012455 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597146.9 | 511934.4 | 92741 | 1.64041666667 | 12455 |
| 012533 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597144.2 | 511933.8 | 92743 | 1.64041666667 | 12533 |
| 011306 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597141.9 | 511932.9 | 92745 | 1.64041666667 | 11306 |
| 011568 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597139.0 | 511932.2 | 92747 | 1.64041666667 | 11568 |
| 012684 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597137.0 | 511931.2 | 92749 | 1.64041666667 | 12684 |
| 011365 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597134.6 | 511930.7 | 92751 | 1.64041666667 | 11365 |
| 010851 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597132.8 | 511929.8 | 92753 | 1.64041666667 | 10851 |
| 011412 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597130.4 | 511929.1 | 92755 | 1.64041666667 | 11412 |
| 011823 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597128.6 | 511927.8 | 92757 | 1.64041666667 | 11823 |
| 010965 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597126.4 | 511926.8 | 92759 | 1.64041666667 | 10965 |
| 012131 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597124.6 | 511925.8 | 92761 | 1.64041666667 | 12131 |
| 010263 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597122.2 | 511924.6 | 92763 | 1.64041666667 | 10263 |
| 009555 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597120.3 | 511923.2 | 92765 | 1.64041666667 | 9555 |
| 011238 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597118.0 | 511923.0 | 92767 | 1.64041666667 | 11238 |
| 010729 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597117.6 | 511921.8 | 92769 | 1.64041666667 | 10729 |
| 012342 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597116.4 | 511920.5 | 92771 | 1.64041666667 | 12342 |
| 012685 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597114.2 | 511919.1 | 92773 | 1.64041666667 | 12685 |
| 011301 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597111.7 | 511919.6 | 92775 | 1.64041666667 | 11301 |
| 009725 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597109.7 | 511919.2 | 92777 | 1.64041666667 | 9725 |
| 010771 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597107.4 | 511919.0 | 92779 | 1.64041666667 | 10771 |
| 011152 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597106.0 | 511918.5 | 92781 | 1.64041666667 | 11152 |
| 011548 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597104.1 | 511919.0 | 92783 | 1.64041666667 | 11548 |
| 010357 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597103.2 | 511919.3 | 92785 | 1.64041666667 | 10357 |
| 010269 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597103.2 | 511919.4 | 92787 | 1.64041666667 | 10269 |
| 012827 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597103.7 | 511919.4 | 92789 | 1.64041666667 | 12827 |
| 011516 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597104.3 | 511919.2 | 92791 | 1.64041666667 | 11516 |
| 010409 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597104.3 | 511919.1 | 92793 | 1.64041666667 | 10409 |
| 010012 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597104.0 | 511919.3 | 92795 | 1.64041666667 | 10012 |
| 009613 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:27pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597103.7 | 511919.4 | 92797 | 1.64041666667 | 9613 |
| 010443 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:28pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597103.6 | 511918.3 | 92799 | 1.64041666667 | 10443 |
| 011280 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:29pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597103.4 | 511915.6 | 92801 | 1.64041666667 | 11280 |
| 010260 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:30pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597103.3 | 511913.2 | 92803 | 1.64041666667 | 10260 |
| 008655 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:31pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597104.3 | 511911.3 | 92805 | 1.64041666667 | 8655 |
| 008373 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:32pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597105.2 | 511909.0 | 92807 | 1.64041666667 | 8373 |
| 010313 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:33pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597105.6 | 511908.7 | 92809 | 1.64041666667 | 10313 |
| 010258 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:34pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597105.9 | 511908.2 | 92811 | 1.64041666667 | 10258 |
| 010574 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:35pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597106.0 | 511908.0 | 92813 | 1.64041666667 | 10574 |
| 010113 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:36pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597104.9 | 511908.8 | 92815 | 1.64041666667 | 10113 |
| 010838 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:37pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597104.5 | 511909.4 | 92817 | 1.64041666667 | 10838 |
| 010389 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:38pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597104.7 | 511911.6 | 92819 | 1.64041666667 | 10389 |
| 009287 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:39pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597104.7 | 511914.8 | 92821 | 1.64041666667 | 9287 |
| 010631 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:40pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597104.2 | 511917.0 | 92823 | 1.64041666667 | 10631 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009858 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:41pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597102.3 | 511918.6 | 92825 | 1.64041666667 | 9858 |
| 011374 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597100.5 | 511918.0 | 92827 | 1.64041666667 | 11374 |
| 010343 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:43pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597098.8 | 511917.3 | 92829 | 1.64041666667 | 10343 |
| 010806 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:44pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597097.1 | 511916.6 | 92831 | 1.64041666667 | 10806 |
| 011731 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:45pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597097.0 | 511916.7 | 92833 | 1.64041666667 | 11731 |
| 012472 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:46pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597095.1 | 511917.1 | 92835 | 1.64041666667 | 12472 |
| 014968 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:47pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597092.5 | 511917.4 | 92837 | 1.64041666667 | 14968 |
| 017152 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:48pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597089.9 | 511916.8 | 92839 | 1.64041666667 | 17152 |
| 015028 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:49pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597087.7 | 511917.0 | 92841 | 1.64041666667 | 15028 |
| 014437 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:50pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597086.0 | 511916.4 | 92843 | 1.64041666667 | 14437 |
| 013089 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:51pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597084.5 | 511915.4 | 92845 | 1.64041666667 | 13089 |
| 013982 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:52pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597084.6 | 511913.7 | 92847 | 1.64041666667 | 13982 |
| 014805 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:53pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597085.5 | 511912.1 | 92849 | 1.64041666667 | 14805 |
| 014351 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:54pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597087.2 | 511912.0 | 92851 | 1.64041666667 | 14351 |
| 015408 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:55pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597088.9 | 511911.8 | 92853 | 1.64041666667 | 15408 |
| 013992 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:56pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597090.1 | 511912.2 | 92855 | 1.64041666667 | 13992 |
| 014508 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597090.4 | 511912.5 | 92857 | 1.64041666667 | 14508 |
| 014247 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597090.3 | 511912.6 | 92859 | 1.64041666667 | 14247 |
| 012861 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:59pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597090.4 | 511912.8 | 92861 | 1.64041666667 | 12861 |
| 014345 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:00pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597090.4 | 511912.8 | 92863 | 1.64041666667 | 14345 |
| 012976 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:01pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597090.8 | 511911.9 | 92865 | 1.64041666667 | 12976 |
| 012844 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597091.2 | 511911.6 | 92867 | 1.64041666667 | 12844 |
| 011341 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:03pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597092.2 | 511910.6 | 92869 | 1.64041666667 | 11341 |
| 010485 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:04pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597093.0 | 511907.7 | 92871 | 1.64041666667 | 10485 |
| 010721 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597093.4 | 511906.2 | 92873 | 1.64041666667 | 10721 |
| 010090 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597093.7 | 511905.5 | 92875 | 1.64041666667 | 10090 |
| 010442 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597093.8 | 511905.2 | 92877 | 1.64041666667 | 10442 |
| 009810 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:08pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597093.0 | 511905.1 | 92879 | 1.64041666667 | 9810 |
| 010492 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:09pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597093.0 | 511906.8 | 92881 | 1.64041666667 | 10492 |
| 010723 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:10pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597092.7 | 511909.8 | 92883 | 1.64041666667 | 10723 |
| 012971 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:11pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597092.2 | 511911.4 | 92885 | 1.64041666667 | 12971 |
| 011732 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597093.4 | 511911.8 | 92887 | 1.64041666667 | 11732 |
| 010546 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597095.0 | 511912.5 | 92889 | 1.64041666667 | 10546 |
| 011308 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597097.1 | 511913.5 | 92891 | 1.64041666667 | 11308 |
| 009667 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:15pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597099.0 | 511914.3 | 92893 | 1.64041666667 | 9667 |
| 010846 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:16pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597101.3 | 511914.7 | 92895 | 1.64041666667 | 10846 |
| 009611 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:17pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597103.4 | 511914.9 | 92897 | 1.64041666667 | 9611 |
| 009603 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:18pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597105.7 | 511915.6 | 92899 | 1.64041666667 | 9603 |
| 010020 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597107.7 | 511916.2 | 92901 | 1.64041666667 | 10020 |
| 010575 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597110.1 | 511916.7 | 92903 | 1.64041666667 | 10575 |
| 010983 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597112.6 | 511917.3 | 92905 | 1.64041666667 | 10983 |
| 012496 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597114.5 | 511918.7 | 92907 | 1.64041666667 | 12496 |
| 010744 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597116.3 | 511919.6 | 92909 | 1.64041666667 | 10744 |
| 010936 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597118.6 | 511921.0 | 92911 | 1.64041666667 | 10936 |
| 010654 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597120.8 | 511921.3 | 92913 | 1.64041666667 | 10654 |
| 010973 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597123.1 | 511922.1 | 92915 | 1.64041666667 | 10973 |
| 010903 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597125.1 | 511922.4 | 92917 | 1.64041666667 | 10903 |
| 011666 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597126.8 | 511923.5 | 92919 | 1.64041666667 | 11666 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012396 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597128.4 | 511924.1 | 92921 | 1.64041666667 | 12396 |
| 011799 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597131.0 | 511924.9 | 92923 | 1.64041666667 | 11799 |
| 011649 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597133.3 | 511925.2 | 92925 | 1.64041666667 | 11649 |
| 011942 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597135.2 | 511926.4 | 92927 | 1.64041666667 | 11942 |
| 011475 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597137.3 | 511927.1 | 92929 | 1.64041666667 | 11475 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597138.9 | 511928.2 | 92931 | 1.64041666667 | 11928 |
| 011184 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597139.8 | 511928.6 | 92933 | 1.64041666667 | 11184 |
| 012333 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597142.0 | 511929.1 | 92935 | 1.64041666667 | 12333 |
| 011423 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597144.6 | 511929.7 | 92937 | 1.64041666667 | 11423 |
| 011435 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.9 | 511930.9 | 92939 | 1.64041666667 | 11435 |
| 011259 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597149.5 | 511931.4 | 92941 | 1.64041666667 | 11259 |
| 011814 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597151.6 | 511932.3 | 92943 | 1.64041666667 | 11814 |
| 011953 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597153.7 | 511932.9 | 92945 | 1.64041666667 | 11953 |
| 012708 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597155.6 | 511934.2 | 92947 | 1.64041666667 | 12708 |
| 013197 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597157.4 | 511934.7 | 92949 | 1.64041666667 | 13197 |
| 012899 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597159.0 | 511935.3 | 92951 | 1.64041666667 | 12899 |
| 013095 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597161.1 | 511935.4 | 92953 | 1.64041666667 | 13095 |
| 014043 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597163.3 | 511936.0 | 92955 | 1.64041666667 | 14043 |
| 014280 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597165.7 | 511936.2 | 92957 | 1.64041666667 | 14280 |
| 011160 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597167.9 | 511937.1 | 92959 | 1.64041666667 | 11160 |
| 011490 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597170.2 | 511938.1 | 92961 | 1.64041666667 | 11490 |
| 012982 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597171.8 | 511939.9 | 92963 | 1.64041666667 | 12982 |
| 012815 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597173.5 | 511941.2 | 92965 | 1.64041666667 | 12815 |
| 012414 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597175.8 | 511942.7 | 92967 | 1.64041666667 | 12414 |
| 014173 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597178.1 | 511944.0 | 92969 | 1.64041666667 | 14173 |
| 013473 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:54pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597180.1 | 511945.3 | 92971 | 1.64041666667 | 13473 |
| 014978 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597181.4 | 511946.2 | 92973 | 1.64041666667 | 14978 |
| 013434 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:56pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597183.3 | 511947.1 | 92975 | 1.64041666667 | 13434 |
| 014068 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:57pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597184.9 | 511947.3 | 92977 | 1.64041666667 | 14068 |
| 012247 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:58pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597185.1 | 511947.8 | 92979 | 1.64041666667 | 12247 |
| 012811 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:59pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597184.5 | 511948.1 | 92981 | 1.64041666667 | 12811 |
| 013702 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:00pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597184.5 | 511947.5 | 92983 | 1.64041666667 | 13702 |
| 012725 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:01pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597184.8 | 511946.7 | 92985 | 1.64041666667 | 12725 |
| 013201 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597185.6 | 511945.0 | 92987 | 1.64041666667 | 13201 |
| 012870 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:03pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597186.0 | 511943.3 | 92989 | 1.64041666667 | 12870 |
| 013267 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:04pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597186.5 | 511943.1 | 92991 | 1.64041666667 | 13267 |
| 013097 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:05pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597186.4 | 511942.5 | 92993 | 1.64041666667 | 13097 |
| 014554 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:06pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597187.0 | 511940.7 | 92995 | 1.64041666667 | 14554 |
| 013388 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597187.5 | 511939.1 | 92997 | 1.64041666667 | 13388 |
| 012737 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597188.2 | 511937.2 | 92999 | 1.64041666667 | 12737 |
| 011974 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597188.9 | 511935.9 | 93001 | 1.64041666667 | 11974 |
| 014573 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597189.0 | 511935.5 | 93003 | 1.64041666667 | 14573 |
| 013603 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597187.8 | 511936.3 | 93005 | 1.64041666667 | 13603 |
| 013991 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597187.7 | 511938.2 | 93007 | 1.64041666667 | 13991 |
| 013037 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597186.9 | 511940.1 | 93009 | 1.64041666667 | 13037 |
| 011599 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597186.2 | 511942.7 | 93011 | 1.64041666667 | 11599 |
| 012289 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597185.1 | 511944.8 | 93013 | 1.64041666667 | 12289 |
| 013752 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597185.8 | 511946.6 | 93015 | 1.64041666667 | 13752 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013788 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597187.0 | 511948.0 | 93017 | 1.64041666667 | 13788 |
| 013557 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597189.2 | 511950.0 | 93019 | 1.64041666667 | 13557 |
| 014369 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597191.2 | 511951.3 | 93021 | 1.64041666667 | 14369 |
| 013012 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:20pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597193.7 | 511952.7 | 93023 | 1.64041666667 | 13012 |
| 012643 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597196.0 | 511952.9 | 93025 | 1.64041666667 | 12643 |
| 013570 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:22pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597198.3 | 511953.9 | 93027 | 1.64041666667 | 13570 |
| 012752 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:23pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597200.1 | 511954.5 | 93029 | 1.64041666667 | 12752 |
| 012698 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597202.5 | 511955.7 | 93031 | 1.64041666667 | 12698 |
| 013914 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597204.7 | 511956.2 | 93033 | 1.64041666667 | 13914 |
| 016708 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597207.0 | 511957.2 | 93035 | 1.64041666667 | 16708 |
| 014467 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597208.8 | 511958.3 | 93037 | 1.64041666667 | 14467 |
| 014626 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597211.0 | 511959.4 | 93039 | 1.64041666667 | 14626 |
| 013226 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597212.8 | 511960.8 | 93041 | 1.64041666667 | 13226 |
| 015546 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:30pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597215.1 | 511961.8 | 93043 | 1.64041666667 | 15546 |
| 013156 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:31pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597216.8 | 511962.0 | 93045 | 1.64041666667 | 13156 |
| 013429 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597216.6 | 511962.7 | 93047 | 1.64041666667 | 13429 |
| 014697 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597216.3 | 511962.4 | 93049 | 1.64041666667 | 14697 |
| 012884 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597217.1 | 511960.3 | 93051 | 1.64041666667 | 12884 |
| 014321 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597217.5 | 511957.9 | 93053 | 1.64041666667 | 14321 |
| 013690 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597217.5 | 511956.4 | 93055 | 1.64041666667 | 13690 |
| 013592 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597217.5 | 511956.6 | 93057 | 1.64041666667 | 13592 |
| 013988 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:38pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597218.6 | 511955.3 | 93059 | 1.64041666667 | 13988 |
| 014387 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:39pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597219.6 | 511952.6 | 93061 | 1.64041666667 | 14387 |
| 013586 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:40pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597220.3 | 511950.8 | 93063 | 1.64041666667 | 13586 |
| 013806 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:41pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597220.6 | 511949.8 | 93065 | 1.64041666667 | 13806 |
| 014431 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597220.2 | 511951.0 | 93067 | 1.64041666667 | 14431 |
| 013567 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597220.2 | 511951.9 | 93069 | 1.64041666667 | 13567 |
| 013082 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597220.7 | 511952.7 | 93071 | 1.64041666667 | 13082 |
| 013590 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597219.9 | 511954.5 | 93073 | 1.64041666667 | 13590 |
| 014437 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597218.8 | 511956.3 | 93075 | 1.64041666667 | 14437 |
| 014439 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:47pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597218.0 | 511957.3 | 93077 | 1.64041666667 | 14439 |
| 014110 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:48pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597217.9 | 511957.5 | 93079 | 1.64041666667 | 14110 |
| 014177 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597217.7 | 511957.5 | 93081 | 1.64041666667 | 14177 |
| 012634 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597216.0 | 511957.6 | 93083 | 1.64041666667 | 12634 |
| 012248 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597214.2 | 511956.9 | 93085 | 1.64041666667 | 12248 |
| 013352 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:52pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597211.6 | 511955.8 | 93087 | 1.64041666667 | 13352 |
| 013838 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:53pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597209.4 | 511955.0 | 93089 | 1.64041666667 | 13838 |
| 014109 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597207.1 | 511953.9 | 93091 | 1.64041666667 | 14109 |
| 012437 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:55pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597204.8 | 511953.0 | 93093 | 1.64041666667 | 12437 |
| 012799 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:56pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597202.7 | 511951.8 | 93095 | 1.64041666667 | 12799 |
| 013009 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:57pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597200.6 | 511950.8 | 93097 | 1.64041666667 | 13009 |
| 013122 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:58pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597198.7 | 511948.9 | 93099 | 1.64041666667 | 13122 |
| 014200 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:59pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597196.7 | 511947.6 | 93101 | 1.64041666667 | 14200 |
| 013480 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:00pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597194.0 | 511946.4 | 93103 | 1.64041666667 | 13480 |
| 011890 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:01pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597191.9 | 511945.8 | 93105 | 1.64041666667 | 11890 |
| 012752 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597189.2 | 511944.9 | 93107 | 1.64041666667 | 12752 |
| 011708 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:03pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597187.4 | 511943.9 | 93109 | 1.64041666667 | 11708 |
| 013607 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:04pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597185.4 | 511943.3 | 93111 | 1.64041666667 | 13607 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012191 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:05pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597183.3 | 511942.6 | 93113 | 1.64041666667 | 12191 |
| 013728 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:06pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597180.7 | 511942.6 | 93115 | 1.64041666667 | 13728 |
| 013512 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597178.9 | 511942.2 | 93117 | 1.64041666667 | 13512 |
| 012948 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597176.5 | 511941.5 | 93119 | 1.64041666667 | 12948 |
| 013677 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597174.7 | 511940.2 | 93121 | 1.64041666667 | 13677 |
| 014009 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597172.4 | 511938.6 | 93123 | 1.64041666667 | 14009 |
| 012892 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597170.4 | 511936.9 | 93125 | 1.64041666667 | 12892 |
| 013033 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597168.4 | 511934.5 | 93127 | 1.64041666667 | 13033 |
| 012948 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597166.2 | 511933.0 | 93129 | 1.64041666667 | 12948 |
| 014097 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597164.0 | 511931.8 | 93131 | 1.64041666667 | 14097 |
| 014234 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597161.9 | 511931.4 | 93133 | 1.64041666667 | 14234 |
| 013518 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597159.7 | 511930.5 | 93135 | 1.64041666667 | 13518 |
| 011809 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597157.9 | 511929.5 | 93137 | 1.64041666667 | 11809 |
| 012702 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597155.7 | 511927.8 | 93139 | 1.64041666667 | 12702 |
| 012895 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597153.5 | 511926.6 | 93141 | 1.64041666667 | 12895 |
| 012014 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597150.9 | 511925.4 | 93143 | 1.64041666667 | 12014 |
| 011793 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597148.9 | 511925.2 | 93145 | 1.64041666667 | 11793 |
| 011438 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597146.7 | 511924.6 | 93147 | 1.64041666667 | 11438 |
| 012379 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597144.5 | 511923.9 | 93149 | 1.64041666667 | 12379 |
| 013277 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597142.4 | 511922.8 | 93151 | 1.64041666667 | 13277 |
| 011809 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597140.4 | 511922.4 | 93153 | 1.64041666667 | 11809 |
| 011472 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597138.6 | 511921.3 | 93155 | 1.64041666667 | 11472 |
| 012018 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597136.9 | 511920.2 | 93157 | 1.64041666667 | 12018 |
| 011524 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597134.4 | 511919.1 | 93159 | 1.64041666667 | 11524 |
| 011131 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597132.7 | 511919.0 | 93161 | 1.64041666667 | 11131 |
| 010942 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597131.0 | 511918.2 | 93163 | 1.64041666667 | 10942 |
| 010595 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597129.3 | 511917.0 | 93165 | 1.64041666667 | 10595 |
| 010719 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597127.0 | 511915.5 | 93167 | 1.64041666667 | 10719 |
| 009609 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597124.7 | 511914.4 | 93169 | 1.64041666667 | 9609 |
| 010232 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597122.0 | 511914.1 | 93171 | 1.64041666667 | 10232 |
| 009638 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597120.2 | 511913.4 | 93173 | 1.64041666667 | 9638 |
| 009879 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597118.1 | 511912.8 | 93175 | 1.64041666667 | 9879 |
| 010750 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597116.1 | 511912.0 | 93177 | 1.64041666667 | 10750 |
| 010997 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597113.6 | 511911.4 | 93179 | 1.64041666667 | 10997 |
| 010729 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597111.5 | 511910.6 | 93181 | 1.64041666667 | 10729 |
| 010842 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597109.0 | 511909.9 | 93183 | 1.64041666667 | 10842 |
| 008530 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597106.7 | 511909.3 | 93185 | 1.64041666667 | 8530 |
| 010172 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:42pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597103.8 | 511908.5 | 93187 | 1.64041666667 | 10172 |
| 010793 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:43pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597101.9 | 511907.7 | 93189 | 1.64041666667 | 10793 |
| 010108 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.7 | 511906.6 | 93191 | 1.64041666667 | 10108 |
| 010357 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:45pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597097.8 | 511905.5 | 93193 | 1.64041666667 | 10357 |
| 012489 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597096.1 | 511905.2 | 93195 | 1.64041666667 | 12489 |
| 010562 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:47pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597094.9 | 511904.3 | 93197 | 1.64041666667 | 10562 |
| 010530 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:48pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597093.0 | 511904.6 | 93199 | 1.64041666667 | 10530 |
| 009772 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:49pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597091.4 | 511904.5 | 93201 | 1.64041666667 | 9772 |
| 010333 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:50pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597089.5 | 511904.0 | 93203 | 1.64041666667 | 10333 |
| 009693 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597089.0 | 511903.9 | 93205 | 1.64041666667 | 9693 |
| 010433 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:52pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597089.2 | 511903.0 | 93207 | 1.64041666667 | 10433 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010228 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:53pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597089.9 | 511900.8 | 93209 | 1.64041666667 | 10228 |
| 010987 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:54pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597090.6 | 511898.2 | 93211 | 1.64041666667 | 10987 |
| 009616 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597090.4 | 511897.5 | 93213 | 1.64041666667 | 9616 |
| 010384 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597090.7 | 511897.1 | 93215 | 1.64041666667 | 10384 |
| 009406 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597091.6 | 511895.2 | 93217 | 1.64041666667 | 9406 |
| 009641 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597092.8 | 511892.7 | 93219 | 1.64041666667 | 9641 |
| 009100 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:59pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597093.2 | 511891.2 | 93221 | 1.64041666667 | 9100 |
| 008155 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:00pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597093.3 | 511890.2 | 93223 | 1.64041666667 | 8155 |
| 009838 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:01pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597093.5 | 511890.2 | 93225 | 1.64041666667 | 9838 |
| 010889 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:02pm | Sensor | 1797-S0055-G-TJV.cor | 6856.3 | 1597093.7 | 511890.2 | 93227 | 1.64041666667 | 10889 |
| 010552 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:03pm | Sensor | 1797-S0055-G-TJV.cor | 6856.0 | 1597093.8 | 511889.9 | 93229 | 1.64041666667 | 10552 |
| 010198 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:04pm | Sensor | 1797-S0055-G-TJV.cor | 6856.0 | 1597093.7 | 511889.9 | 93231 | 1.64041666667 | 10198 |
| 008879 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:05pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597093.3 | 511890.4 | 93233 | 1.64041666667 | 8879 |
| 009780 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:06pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597092.5 | 511891.2 | 93235 | 1.64041666667 | 9780 |
| 009990 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597092.6 | 511891.4 | 93237 | 1.64041666667 | 9990 |
| 010383 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597092.9 | 511891.3 | 93239 | 1.64041666667 | 10383 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597092.7 | 511892.4 | 93241 | 1.64041666667 | 11205 |
| 011171 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597092.6 | 511894.5 | 93243 | 1.64041666667 | 11171 |
| 010743 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.0 | 511896.9 | 93245 | 1.64041666667 | 10743 |
| 010335 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597094.4 | 511899.4 | 93247 | 1.64041666667 | 10335 |
| 009603 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:13pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597096.7 | 511900.7 | 93249 | 1.64041666667 | 9603 |
| 009391 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:14pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597099.5 | 511902.0 | 93251 | 1.64041666667 | 9391 |
| 008887 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:15pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597101.9 | 511903.8 | 93253 | 1.64041666667 | 8887 |
| 009452 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:16pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597104.4 | 511906.3 | 93255 | 1.64041666667 | 9452 |
| 010043 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:17pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597104.4 | 511905.8 | 93257 | 1.64041666667 | 10043 |
| 010970 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:18pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597102.7 | 511904.4 | 93259 | 1.64041666667 | 10970 |
| 011412 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:19pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597101.0 | 511903.0 | 93261 | 1.64041666667 | 11412 |
| 010923 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:20pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597099.1 | 511900.8 | 93263 | 1.64041666667 | 10923 |
| 011010 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:21pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597098.5 | 511899.0 | 93265 | 1.64041666667 | 11010 |
| 010072 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597098.7 | 511897.7 | 93267 | 1.64041666667 | 10072 |
| 010378 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597098.7 | 511897.3 | 93269 | 1.64041666667 | 10378 |
| 010724 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:24pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597097.6 | 511896.8 | 93271 | 1.64041666667 | 10724 |
| 010181 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:25pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597095.6 | 511896.7 | 93273 | 1.64041666667 | 10181 |
| 011245 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.6 | 511896.7 | 93275 | 1.64041666667 | 11245 |
| 011091 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597092.6 | 511897.2 | 93277 | 1.64041666667 | 11091 |
| 009792 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597091.9 | 511898.1 | 93279 | 1.64041666667 | 9792 |
| 009798 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:29pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597092.5 | 511898.4 | 93281 | 1.64041666667 | 9798 |
| 010549 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:30pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597094.6 | 511898.9 | 93283 | 1.64041666667 | 10549 |
| 011307 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:31pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597097.6 | 511899.6 | 93285 | 1.64041666667 | 11307 |
| 009307 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:32pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597100.3 | 511901.0 | 93287 | 1.64041666667 | 9307 |
| 009256 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:33pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597102.4 | 511901.5 | 93289 | 1.64041666667 | 9256 |
| 008764 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:34pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597105.0 | 511902.3 | 93291 | 1.64041666667 | 8764 |
| 010321 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:35pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597107.3 | 511903.2 | 93293 | 1.64041666667 | 10321 |
| 011190 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597109.7 | 511904.1 | 93295 | 1.64041666667 | 11190 |
| 009787 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597111.8 | 511904.7 | 93297 | 1.64041666667 | 9787 |
| 009947 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597114.4 | 511904.7 | 93299 | 1.64041666667 | 9947 |
| 009866 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:39pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597116.3 | 511904.7 | 93301 | 1.64041666667 | 9866 |
| 009306 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:40pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597119.0 | 511904.4 | 93303 | 1.64041666667 | 9306 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009256 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597121.1 | 511905.1 | 93305 | 1.64041666667 | 9256 |
| 010354 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597123.9 | 511905.7 | 93307 | 1.64041666667 | 10354 |
| 011048 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597125.5 | 511906.7 | 93309 | 1.64041666667 | 11048 |
| 010562 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597127.3 | 511907.4 | 93311 | 1.64041666667 | 10562 |
| 009540 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597128.4 | 511907.9 | 93313 | 1.64041666667 | 9540 |
| 010725 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597130.2 | 511907.8 | 93315 | 1.64041666667 | 10725 |
| 009611 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597131.7 | 511907.8 | 93317 | 1.64041666667 | 9611 |
| 011133 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597133.7 | 511907.1 | 93319 | 1.64041666667 | 11133 |
| 010583 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597135.5 | 511907.0 | 93321 | 1.64041666667 | 10583 |
| 010775 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597137.7 | 511907.3 | 93323 | 1.64041666667 | 10775 |
| 010374 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597139.8 | 511908.0 | 93325 | 1.64041666667 | 10374 |
| 009733 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597141.9 | 511909.6 | 93327 | 1.64041666667 | 9733 |
| 009033 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597143.7 | 511911.2 | 93329 | 1.64041666667 | 9033 |
| 010268 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597145.4 | 511913.4 | 93331 | 1.64041666667 | 10268 |
| 011267 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597147.2 | 511915.0 | 93333 | 1.64041666667 | 11267 |
| 013046 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597149.0 | 511916.4 | 93335 | 1.64041666667 | 13046 |
| 011871 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597151.0 | 511917.0 | 93337 | 1.64041666667 | 11871 |
| 012238 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597153.5 | 511918.0 | 93339 | 1.64041666667 | 12238 |
| 012959 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597155.4 | 511918.8 | 93341 | 1.64041666667 | 12959 |
| 012870 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:00pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597157.2 | 511919.6 | 93343 | 1.64041666667 | 12870 |
| 012427 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:01pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597159.2 | 511920.3 | 93345 | 1.64041666667 | 12427 |
| 012166 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597161.8 | 511921.5 | 93347 | 1.64041666667 | 12166 |
| 012131 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:03pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597163.9 | 511922.3 | 93349 | 1.64041666667 | 12131 |
| 012213 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:04pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597166.2 | 511923.8 | 93351 | 1.64041666667 | 12213 |
| 012323 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:05pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597168.4 | 511924.8 | 93353 | 1.64041666667 | 12323 |
| 012860 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:06pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597170.5 | 511926.0 | 93355 | 1.64041666667 | 12860 |
| 013535 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597172.1 | 511926.9 | 93357 | 1.64041666667 | 13535 |
| 013463 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597174.4 | 511928.0 | 93359 | 1.64041666667 | 13463 |
| 013626 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597176.5 | 511928.7 | 93361 | 1.64041666667 | 13626 |
| 013216 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597178.8 | 511929.8 | 93363 | 1.64041666667 | 13216 |
| 012784 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597180.7 | 511931.0 | 93365 | 1.64041666667 | 12784 |
| 013096 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597182.4 | 511932.0 | 93367 | 1.64041666667 | 13096 |
| 011464 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597183.9 | 511932.6 | 93369 | 1.64041666667 | 11464 |
| 011146 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:14pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597185.3 | 511933.6 | 93371 | 1.64041666667 | 11146 |
| 011336 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:15pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597187.1 | 511934.3 | 93373 | 1.64041666667 | 11336 |
| 011564 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:16pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597188.3 | 511934.8 | 93375 | 1.64041666667 | 11564 |
| 013301 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:17pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597188.1 | 511934.2 | 93377 | 1.64041666667 | 13301 |
| 013045 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:18pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597187.9 | 511933.2 | 93379 | 1.64041666667 | 13045 |
| 014271 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:19pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597187.9 | 511931.5 | 93381 | 1.64041666667 | 14271 |
| 011727 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:20pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597188.3 | 511928.8 | 93383 | 1.64041666667 | 11727 |
| 011872 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:21pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597188.4 | 511927.2 | 93385 | 1.64041666667 | 11872 |
| 014818 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:22pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597188.5 | 511926.0 | 93387 | 1.64041666667 | 14818 |
| 012464 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:23pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597188.2 | 511926.8 | 93389 | 1.64041666667 | 12464 |
| 011756 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:24pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597188.0 | 511928.6 | 93391 | 1.64041666667 | 11756 |
| 012509 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:25pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597187.7 | 511929.7 | 93393 | 1.64041666667 | 12509 |
| 011737 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:26pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597187.8 | 511932.1 | 93395 | 1.64041666667 | 11737 |
| 013224 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:27pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597188.1 | 511934.1 | 93397 | 1.64041666667 | 13224 |
| 014166 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597189.0 | 511935.5 | 93399 | 1.64041666667 | 14166 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014191 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597190.6 | 511936.3 | 93401 | 1.64041666667 | 14191 |
| 013117 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:30pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597193.0 | 511937.1 | 93403 | 1.64041666667 | 13117 |
| 013119 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:31pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597195.2 | 511937.7 | 93405 | 1.64041666667 | 13119 |
| 013270 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597197.4 | 511938.9 | 93407 | 1.64041666667 | 13270 |
| 012887 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597199.3 | 511940.0 | 93409 | 1.64041666667 | 12887 |
| 012791 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597201.5 | 511941.2 | 93411 | 1.64041666667 | 12791 |
| 013098 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597203.7 | 511941.6 | 93413 | 1.64041666667 | 13098 |
| 014314 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597206.0 | 511942.1 | 93415 | 1.64041666667 | 14314 |
| 013868 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597208.2 | 511943.1 | 93417 | 1.64041666667 | 13868 |
| 012497 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:38pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597210.8 | 511944.4 | 93419 | 1.64041666667 | 12497 |
| 013864 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:39pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597212.8 | 511945.6 | 93421 | 1.64041666667 | 13864 |
| 013726 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:40pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597215.2 | 511946.8 | 93423 | 1.64041666667 | 13726 |
| 012371 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:41pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597216.4 | 511947.9 | 93425 | 1.64041666667 | 12371 |
| 013443 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597217.9 | 511948.7 | 93427 | 1.64041666667 | 13443 |
| 012990 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597219.5 | 511949.0 | 93429 | 1.64041666667 | 12990 |
| 014377 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597220.0 | 511949.6 | 93431 | 1.64041666667 | 14377 |
| 013734 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597219.9 | 511950.0 | 93433 | 1.64041666667 | 13734 |
| 012313 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597219.8 | 511950.2 | 93435 | 1.64041666667 | 12313 |
| 011778 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:47pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597219.8 | 511950.2 | 93437 | 1.64041666667 | 11778 |
| 013444 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:48pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597219.7 | 511949.4 | 93439 | 1.64041666667 | 13444 |
| 015181 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:49pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597220.1 | 511948.2 | 93441 | 1.64041666667 | 15181 |
| 015465 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:50pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597220.9 | 511946.4 | 93443 | 1.64041666667 | 15465 |
| 014966 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597221.5 | 511944.9 | 93445 | 1.64041666667 | 14966 |
| 013581 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:52pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597221.8 | 511944.5 | 93447 | 1.64041666667 | 13581 |
| 014315 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:53pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597222.1 | 511944.3 | 93449 | 1.64041666667 | 14315 |
| 014078 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597222.4 | 511942.5 | 93451 | 1.64041666667 | 14078 |
| 015009 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597223.4 | 511939.8 | 93453 | 1.64041666667 | 15009 |
| 015632 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:56pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597224.7 | 511937.2 | 93455 | 1.64041666667 | 15632 |
| 015398 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:57pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597224.9 | 511936.6 | 93457 | 1.64041666667 | 15398 |
| 015039 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:58pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597224.2 | 511936.9 | 93459 | 1.64041666667 | 15039 |
| 014830 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:59pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597224.3 | 511937.2 | 93461 | 1.64041666667 | 14830 |
| 015197 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:00pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597224.0 | 511938.2 | 93463 | 1.64041666667 | 15197 |
| 012229 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:01pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597223.1 | 511939.9 | 93465 | 1.64041666667 | 12229 |
| 011397 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:02pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597221.7 | 511941.8 | 93467 | 1.64041666667 | 11397 |
| 011759 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:03pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597221.0 | 511943.1 | 93469 | 1.64041666667 | 11759 |
| 014100 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:04pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597220.0 | 511943.6 | 93471 | 1.64041666667 | 14100 |
| 013425 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597218.1 | 511943.4 | 93473 | 1.64041666667 | 13425 |
| 015116 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597215.4 | 511942.8 | 93475 | 1.64041666667 | 15116 |
| 013109 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:07pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597213.2 | 511942.1 | 93477 | 1.64041666667 | 13109 |
| 014257 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597210.1 | 511941.4 | 93479 | 1.64041666667 | 14257 |
| 012444 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597207.6 | 511940.3 | 93481 | 1.64041666667 | 12444 |
| 012981 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597205.0 | 511939.3 | 93483 | 1.64041666667 | 12981 |
| 012845 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:11pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597203.0 | 511938.3 | 93485 | 1.64041666667 | 12845 |
| 014701 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597200.8 | 511937.6 | 93487 | 1.64041666667 | 14701 |
| 012705 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597199.0 | 511936.6 | 93489 | 1.64041666667 | 12705 |
| 014396 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597196.7 | 511935.2 | 93491 | 1.64041666667 | 14396 |
| 013498 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597195.5 | 511934.0 | 93493 | 1.64041666667 | 13498 |
| 014182 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597193.5 | 511933.2 | 93495 | 1.64041666667 | 14182 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013295 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597191.8 | 511932.7 | 93497 | 1.64041666667 | 13295 |
| 012773 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:18pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597189.6 | 511932.7 | 93499 | 1.64041666667 | 12773 |
| 013483 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:19pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597188.0 | 511932.5 | 93501 | 1.64041666667 | 13483 |
| 012521 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:20pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597186.1 | 511932.0 | 93503 | 1.64041666667 | 12521 |
| 012610 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597184.5 | 511931.2 | 93505 | 1.64041666667 | 12610 |
| 014042 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:22pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597182.7 | 511929.7 | 93507 | 1.64041666667 | 14042 |
| 013920 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:23pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597181.3 | 511928.3 | 93509 | 1.64041666667 | 13920 |
| 013140 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597179.2 | 511926.3 | 93511 | 1.64041666667 | 13140 |
| 012195 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597176.8 | 511925.1 | 93513 | 1.64041666667 | 12195 |
| 012258 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597174.2 | 511924.0 | 93515 | 1.64041666667 | 12258 |
| 013594 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597172.2 | 511923.3 | 93517 | 1.64041666667 | 13594 |
| 013988 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597170.3 | 511922.1 | 93519 | 1.64041666667 | 13988 |
| 013097 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597168.4 | 511921.1 | 93521 | 1.64041666667 | 13097 |
| 011974 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:30pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597166.2 | 511919.8 | 93523 | 1.64041666667 | 11974 |
| 010133 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597164.2 | 511918.9 | 93525 | 1.64041666667 | 10133 |
| 011893 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597161.8 | 511917.8 | 93527 | 1.64041666667 | 11893 |
| 011643 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597159.6 | 511916.8 | 93529 | 1.64041666667 | 11643 |
| 011910 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597157.1 | 511915.8 | 93531 | 1.64041666667 | 11910 |
| 011107 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597155.0 | 511914.9 | 93533 | 1.64041666667 | 11107 |
| 011537 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597152.2 | 511913.7 | 93535 | 1.64041666667 | 11537 |
| 011224 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597150.5 | 511912.5 | 93537 | 1.64041666667 | 11224 |
| 010096 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597148.1 | 511911.3 | 93539 | 1.64041666667 | 10096 |
| 010864 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597145.9 | 511909.8 | 93541 | 1.64041666667 | 10864 |
| 010336 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597143.5 | 511908.9 | 93543 | 1.64041666667 | 10336 |
| 011074 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597141.6 | 511908.0 | 93545 | 1.64041666667 | 11074 |
| 010388 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597139.3 | 511907.0 | 93547 | 1.64041666667 | 10388 |
| 011987 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597137.5 | 511906.3 | 93549 | 1.64041666667 | 11987 |
| 012266 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597135.2 | 511905.6 | 93551 | 1.64041666667 | 12266 |
| 010476 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597133.2 | 511904.7 | 93553 | 1.64041666667 | 10476 |
| 010449 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597130.6 | 511903.8 | 93555 | 1.64041666667 | 10449 |
| 010412 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597127.9 | 511902.9 | 93557 | 1.64041666667 | 10412 |
| 009413 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:48pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597125.3 | 511902.0 | 93559 | 1.64041666667 | 9413 |
| 009793 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:49pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597123.2 | 511901.4 | 93561 | 1.64041666667 | 9793 |
| 009798 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:50pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597120.5 | 511900.7 | 93563 | 1.64041666667 | 9798 |
| 012079 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:51pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597118.3 | 511900.0 | 93565 | 1.64041666667 | 12079 |
| 009979 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:52pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597115.9 | 511898.9 | 93567 | 1.64041666667 | 9979 |
| 009635 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:53pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597114.0 | 511897.9 | 93569 | 1.64041666667 | 9635 |
| 009038 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:54pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597111.3 | 511896.7 | 93571 | 1.64041666667 | 9038 |
| 009379 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:55pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597108.9 | 511896.1 | 93573 | 1.64041666667 | 9379 |
| 010682 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:56pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597106.9 | 511895.0 | 93575 | 1.64041666667 | 10682 |
| 009990 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597105.3 | 511893.7 | 93577 | 1.64041666667 | 9990 |
| 008917 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597103.0 | 511892.0 | 93579 | 1.64041666667 | 8917 |
| 009009 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:59pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597101.0 | 511890.9 | 93581 | 1.64041666667 | 9009 |
| 009392 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:00pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597098.4 | 511890.2 | 93583 | 1.64041666667 | 9392 |
| 008318 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:01pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597096.5 | 511890.1 | 93585 | 1.64041666667 | 8318 |
| 009429 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:02pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597094.3 | 511890.0 | 93587 | 1.64041666667 | 9429 |
| 010847 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:03pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597093.3 | 511889.5 | 93589 | 1.64041666667 | 10847 |
| 010451 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:04pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597093.6 | 511890.0 | 93591 | 1.64041666667 | 10451 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009753 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:05pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597094.0 | 511890.4 | 93593 | 1.64041666667 | 9753 |
| 010208 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:06pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597094.0 | 511890.5 | 93595 | 1.64041666667 | 10208 |
| 008432 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:07pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597094.0 | 511890.6 | 93597 | 1.64041666667 | 8432 |
| 008258 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:08pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597093.5 | 511890.2 | 93599 | 1.64041666667 | 8258 |
| 008484 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:09pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597093.3 | 511889.0 | 93601 | 1.64041666667 | 8484 |
| 009771 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597093.3 | 511886.8 | 93603 | 1.64041666667 | 9771 |
| 010032 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597093.3 | 511885.4 | 93605 | 1.64041666667 | 10032 |
| 009648 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597093.3 | 511885.2 | 93607 | 1.64041666667 | 9648 |
| 009252 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597093.5 | 511884.9 | 93609 | 1.64041666667 | 9252 |
| 009453 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.2 | 511883.1 | 93611 | 1.64041666667 | 9453 |
| 009383 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.9 | 511881.4 | 93613 | 1.64041666667 | 9383 |
| 009155 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597095.9 | 511880.4 | 93615 | 1.64041666667 | 9155 |
| 009729 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:17pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597096.9 | 511879.9 | 93617 | 1.64041666667 | 9729 |
| 010322 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:18pm | Sensor | 1797-S0055-G-TJV.cor | 6855.1 | 1597097.5 | 511879.7 | 93619 | 1.64041666667 | 10322 |
| 010200 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:19pm | Sensor | 1797-S0055-G-TJV.cor | 6855.6 | 1597097.0 | 511880.0 | 93621 | 1.64041666667 | 10200 |
| 010500 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:20pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597097.2 | 511880.4 | 93623 | 1.64041666667 | 10500 |
| 010305 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:21pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597098.6 | 511880.4 | 93625 | 1.64041666667 | 10305 |
| 010106 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:22pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597099.3 | 511880.4 | 93627 | 1.64041666667 | 10106 |
| 009786 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:23pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597099.2 | 511880.3 | 93629 | 1.64041666667 | 9786 |
| 010606 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:24pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597098.0 | 511879.8 | 93631 | 1.64041666667 | 10606 |
| 010631 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:25pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597097.2 | 511879.5 | 93633 | 1.64041666667 | 10631 |
| 010308 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:26pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597097.2 | 511879.6 | 93635 | 1.64041666667 | 10308 |
| 010257 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:27pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597097.2 | 511879.6 | 93637 | 1.64041666667 | 10257 |
| 011114 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:28pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597097.2 | 511879.4 | 93639 | 1.64041666667 | 11114 |
| 010158 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597097.1 | 511879.4 | 93641 | 1.64041666667 | 10158 |
| 010399 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.2 | 511879.5 | 93643 | 1.64041666667 | 10399 |
| 008929 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.7 | 511879.7 | 93645 | 1.64041666667 | 8929 |
| 010392 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.3 | 511880.2 | 93647 | 1.64041666667 | 10392 |
| 009558 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597096.5 | 511881.9 | 93649 | 1.64041666667 | 9558 |
| 010999 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.9 | 511883.6 | 93651 | 1.64041666667 | 10999 |
| 011239 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.4 | 511884.5 | 93653 | 1.64041666667 | 11239 |
| 010490 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.1 | 511885.5 | 93655 | 1.64041666667 | 10490 |
| 011022 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.5 | 511886.0 | 93657 | 1.64041666667 | 11022 |
| 010015 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597096.4 | 511887.1 | 93659 | 1.64041666667 | 10015 |
| 009374 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:39pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597098.5 | 511888.4 | 93661 | 1.64041666667 | 9374 |
| 009423 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:40pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597101.1 | 511890.1 | 93663 | 1.64041666667 | 9423 |
| 009315 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:41pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597103.1 | 511890.9 | 93665 | 1.64041666667 | 9315 |
| 012078 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:42pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597105.5 | 511891.6 | 93667 | 1.64041666667 | 12078 |
| 009889 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:43pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597107.5 | 511892.4 | 93669 | 1.64041666667 | 9889 |
| 011022 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:44pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597109.7 | 511893.5 | 93671 | 1.64041666667 | 11022 |
| 009055 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:45pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597111.6 | 511894.8 | 93673 | 1.64041666667 | 9055 |
| 011234 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597114.1 | 511896.0 | 93675 | 1.64041666667 | 11234 |
| 010098 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597115.8 | 511896.9 | 93677 | 1.64041666667 | 10098 |
| 009934 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597118.1 | 511897.6 | 93679 | 1.64041666667 | 9934 |
| 008813 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597119.7 | 511897.9 | 93681 | 1.64041666667 | 8813 |
| 010183 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597122.1 | 511897.9 | 93683 | 1.64041666667 | 10183 |
| 009866 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597124.0 | 511898.5 | 93685 | 1.64041666667 | 9866 |
| 009366 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597126.5 | 511899.9 | 93687 | 1.64041666667 | 9366 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010651 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597128.0 | 511901.1 | 93689 | 1.64041666667 | 10651 |
| 011632 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597129.7 | 511901.8 | 93691 | 1.64041666667 | 11632 |
| 009748 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597131.3 | 511902.2 | 93693 | 1.64041666667 | 9748 |
| 010327 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597133.3 | 511903.7 | 93695 | 1.64041666667 | 10327 |
| 012181 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597134.9 | 511904.6 | 93697 | 1.64041666667 | 12181 |
| 010455 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597136.8 | 511905.7 | 93699 | 1.64041666667 | 10455 |
| 010863 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597138.6 | 511906.6 | 93701 | 1.64041666667 | 10863 |
| 010366 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597141.0 | 511907.5 | 93703 | 1.64041666667 | 10366 |
| 010571 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597143.3 | 511908.0 | 93705 | 1.64041666667 | 10571 |
| 011133 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597145.3 | 511908.8 | 93707 | 1.64041666667 | 11133 |
| 012653 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597147.0 | 511909.4 | 93709 | 1.64041666667 | 12653 |
| 011653 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597149.0 | 511910.2 | 93711 | 1.64041666667 | 11653 |
| 011883 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597151.2 | 511910.8 | 93713 | 1.64041666667 | 11883 |
| 011040 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597153.6 | 511911.6 | 93715 | 1.64041666667 | 11040 |
| 012120 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597155.5 | 511912.1 | 93717 | 1.64041666667 | 12120 |
| 012510 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597158.1 | 511912.8 | 93719 | 1.64041666667 | 12510 |
| 011917 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597160.2 | 511913.3 | 93721 | 1.64041666667 | 11917 |
| 012459 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597162.3 | 511914.5 | 93723 | 1.64041666667 | 12459 |
| 011965 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597164.1 | 511915.5 | 93725 | 1.64041666667 | 11965 |
| 013011 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597166.6 | 511916.6 | 93727 | 1.64041666667 | 13011 |
| 013782 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597168.9 | 511916.9 | 93729 | 1.64041666667 | 13782 |
| 012415 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597171.3 | 511917.2 | 93731 | 1.64041666667 | 12415 |
| 013604 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597172.9 | 511917.2 | 93733 | 1.64041666667 | 13604 |
| 014771 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597174.9 | 511917.7 | 93735 | 1.64041666667 | 14771 |
| 014312 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597176.8 | 511918.9 | 93737 | 1.64041666667 | 14312 |
| 014108 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597178.9 | 511920.3 | 93739 | 1.64041666667 | 14108 |
| 012137 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597180.7 | 511921.2 | 93741 | 1.64041666667 | 12137 |
| 012964 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:20pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597183.0 | 511921.7 | 93743 | 1.64041666667 | 12964 |
| 013381 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597184.7 | 511922.3 | 93745 | 1.64041666667 | 13381 |
| 012705 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:22pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597186.5 | 511923.2 | 93747 | 1.64041666667 | 12705 |
| 012416 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:23pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597187.5 | 511924.0 | 93749 | 1.64041666667 | 12416 |
| 011384 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597188.0 | 511924.4 | 93751 | 1.64041666667 | 11384 |
| 011966 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597188.1 | 511924.4 | 93753 | 1.64041666667 | 11966 |
| 012171 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597187.6 | 511924.0 | 93755 | 1.64041666667 | 12171 |
| 013692 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597187.2 | 511923.6 | 93757 | 1.64041666667 | 13692 |
| 013323 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597187.2 | 511923.4 | 93759 | 1.64041666667 | 13323 |
| 011130 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:29pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597187.5 | 511923.3 | 93761 | 1.64041666667 | 11130 |
| 011962 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:30pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597188.6 | 511923.2 | 93763 | 1.64041666667 | 11962 |
| 011330 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:31pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597190.1 | 511922.9 | 93765 | 1.64041666667 | 11330 |
| 015642 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597192.4 | 511923.1 | 93767 | 1.64041666667 | 15642 |
| 014050 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597194.6 | 511923.8 | 93769 | 1.64041666667 | 14050 |
| 013892 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597197.0 | 511925.0 | 93771 | 1.64041666667 | 13892 |
| 015323 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597198.7 | 511925.8 | 93773 | 1.64041666667 | 15323 |
| 014060 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597201.0 | 511926.5 | 93775 | 1.64041666667 | 14060 |
| 013625 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597203.2 | 511927.2 | 93777 | 1.64041666667 | 13625 |
| 014416 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:38pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597205.4 | 511927.9 | 93779 | 1.64041666667 | 14416 |
| 013414 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:39pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597207.2 | 511928.8 | 93781 | 1.64041666667 | 13414 |
| 012863 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:40pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597209.9 | 511930.1 | 93783 | 1.64041666667 | 12863 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014796 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:41pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597211.9 | 511931.0 | 93785 | 1.64041666667 | 14796 |
| 013179 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597214.3 | 511932.0 | 93787 | 1.64041666667 | 13179 |
| 013704 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597216.3 | 511933.1 | 93789 | 1.64041666667 | 13704 |
| 013716 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597218.9 | 511934.4 | 93791 | 1.64041666667 | 13716 |
| 013839 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597220.8 | 511935.3 | 93793 | 1.64041666667 | 13839 |
| 014019 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597223.0 | 511935.9 | 93795 | 1.64041666667 | 14019 |
| 013015 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:47pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597224.3 | 511935.6 | 93797 | 1.64041666667 | 13015 |
| 013303 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:48pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597225.1 | 511935.8 | 93799 | 1.64041666667 | 13303 |
| 013196 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597225.2 | 511935.6 | 93801 | 1.64041666667 | 13196 |
| 012599 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597226.0 | 511933.7 | 93803 | 1.64041666667 | 12599 |
| 012779 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597227.0 | 511931.7 | 93805 | 1.64041666667 | 12779 |
| 015555 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:52pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597227.7 | 511929.8 | 93807 | 1.64041666667 | 15555 |
| 013368 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:53pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597227.9 | 511929.2 | 93809 | 1.64041666667 | 13368 |
| 012732 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597227.7 | 511929.0 | 93811 | 1.64041666667 | 12732 |
| 012693 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597228.2 | 511928.2 | 93813 | 1.64041666667 | 12693 |
| 014243 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:56pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597229.3 | 511926.3 | 93815 | 1.64041666667 | 14243 |
| 014660 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:57pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597230.7 | 511924.7 | 93817 | 1.64041666667 | 14660 |
| 014885 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:58pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597231.5 | 511923.8 | 93819 | 1.64041666667 | 14885 |
| 013861 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:59pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597230.7 | 511922.9 | 93821 | 1.64041666667 | 13861 |
| 013245 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:00pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597229.7 | 511922.0 | 93823 | 1.64041666667 | 13245 |
| 012041 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597230.5 | 511922.5 | 93825 | 1.64041666667 | 12041 |
| 012430 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:02pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597231.5 | 511923.7 | 93827 | 1.64041666667 | 12430 |
| 011627 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:03pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597231.4 | 511924.8 | 93829 | 1.64041666667 | 11627 |
| 012566 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:04pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597230.8 | 511926.5 | 93831 | 1.64041666667 | 12566 |
| 012861 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597230.0 | 511928.2 | 93833 | 1.64041666667 | 12861 |
| 014015 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597228.6 | 511929.5 | 93835 | 1.64041666667 | 14015 |
| 015173 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:07pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597227.3 | 511929.4 | 93837 | 1.64041666667 | 15173 |
| 013783 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:08pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597225.1 | 511929.0 | 93839 | 1.64041666667 | 13783 |
| 013106 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:09pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597223.3 | 511928.3 | 93841 | 1.64041666667 | 13106 |
| 013536 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:10pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597221.3 | 511927.2 | 93843 | 1.64041666667 | 13536 |
| 014364 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:11pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597219.9 | 511926.9 | 93845 | 1.64041666667 | 14364 |
| 013881 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:12pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597218.9 | 511925.8 | 93847 | 1.64041666667 | 13881 |
| 013040 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:13pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597217.2 | 511924.7 | 93849 | 1.64041666667 | 13040 |
| 012140 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:14pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597215.5 | 511924.4 | 93851 | 1.64041666667 | 12140 |
| 013445 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:15pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597213.6 | 511924.0 | 93853 | 1.64041666667 | 13445 |
| 012001 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:16pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597211.5 | 511923.3 | 93855 | 1.64041666667 | 12001 |
| 014640 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:17pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597209.7 | 511922.5 | 93857 | 1.64041666667 | 14640 |
| 015270 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:18pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597208.0 | 511921.3 | 93859 | 1.64041666667 | 15270 |
| 012787 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:19pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597206.5 | 511920.8 | 93861 | 1.64041666667 | 12787 |
| 012587 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:20pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597203.8 | 511919.9 | 93863 | 1.64041666667 | 12587 |
| 012626 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:21pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597201.7 | 511919.3 | 93865 | 1.64041666667 | 12626 |
| 012786 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:22pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597199.1 | 511918.2 | 93867 | 1.64041666667 | 12786 |
| 013486 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:23pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597196.9 | 511917.6 | 93869 | 1.64041666667 | 13486 |
| 012131 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:24pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597194.7 | 511916.6 | 93871 | 1.64041666667 | 12131 |
| 012633 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:25pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597192.8 | 511915.6 | 93873 | 1.64041666667 | 12633 |
| 012068 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597189.7 | 511914.7 | 93875 | 1.64041666667 | 12068 |
| 011957 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597187.6 | 511914.2 | 93877 | 1.64041666667 | 11957 |
| 012199 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597184.8 | 511913.6 | 93879 | 1.64041666667 | 12199 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013099 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597182.7 | 511912.5 | 93881 | 1.64041666667 | 13099 |
| 012635 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:30pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597180.7 | 511910.9 | 93883 | 1.64041666667 | 12635 |
| 012908 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:31pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597178.8 | 511909.2 | 93885 | 1.64041666667 | 12908 |
| 013667 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597176.7 | 511907.8 | 93887 | 1.64041666667 | 13667 |
| 012086 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597174.5 | 511906.9 | 93889 | 1.64041666667 | 12086 |
| 012081 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597172.5 | 511905.8 | 93891 | 1.64041666667 | 12081 |
| 013310 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597170.4 | 511904.7 | 93893 | 1.64041666667 | 13310 |
| 012357 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597168.3 | 511903.4 | 93895 | 1.64041666667 | 12357 |
| 011489 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597166.2 | 511902.3 | 93897 | 1.64041666667 | 11489 |
| 012142 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597163.8 | 511901.0 | 93899 | 1.64041666667 | 12142 |
| 012245 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597161.9 | 511900.0 | 93901 | 1.64041666667 | 12245 |
| 010831 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597159.4 | 511898.8 | 93903 | 1.64041666667 | 10831 |
| 013477 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597157.2 | 511898.4 | 93905 | 1.64041666667 | 13477 |
| 010569 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597154.7 | 511897.7 | 93907 | 1.64041666667 | 10569 |
| 010892 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597152.7 | 511896.8 | 93909 | 1.64041666667 | 10892 |
| 010613 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597150.4 | 511895.7 | 93911 | 1.64041666667 | 10613 |
| 011023 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597148.1 | 511894.7 | 93913 | 1.64041666667 | 11023 |
| 010766 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597145.1 | 511893.9 | 93915 | 1.64041666667 | 10766 |
| 009981 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597143.0 | 511893.3 | 93917 | 1.64041666667 | 9981 |
| 010775 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597141.4 | 511892.6 | 93919 | 1.64041666667 | 10775 |
| 010163 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597139.4 | 511891.7 | 93921 | 1.64041666667 | 10163 |
| 009951 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597136.7 | 511891.3 | 93923 | 1.64041666667 | 9951 |
| 010017 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597134.4 | 511890.8 | 93925 | 1.64041666667 | 10017 |
| 009254 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597131.8 | 511889.9 | 93927 | 1.64041666667 | 9254 |
| 009513 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597129.8 | 511889.2 | 93929 | 1.64041666667 | 9513 |
| 011498 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597127.2 | 511888.4 | 93931 | 1.64041666667 | 11498 |
| 011334 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597125.2 | 511887.8 | 93933 | 1.64041666667 | 11334 |
| 009253 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597122.6 | 511887.0 | 93935 | 1.64041666667 | 9253 |
| 010233 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597120.2 | 511886.6 | 93937 | 1.64041666667 | 10233 |
| 010148 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597117.4 | 511886.3 | 93939 | 1.64041666667 | 10148 |
| 011087 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:59pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597115.1 | 511885.8 | 93941 | 1.64041666667 | 11087 |
| 009671 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:00pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597112.5 | 511884.7 | 93943 | 1.64041666667 | 9671 |
| 009798 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:01pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597110.2 | 511884.2 | 93945 | 1.64041666667 | 9798 |
| 010369 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:02pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597107.5 | 511883.9 | 93947 | 1.64041666667 | 10369 |
| 010722 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597105.4 | 511883.3 | 93949 | 1.64041666667 | 10722 |
| 009790 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597103.5 | 511882.4 | 93951 | 1.64041666667 | 9790 |
| 011087 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597102.3 | 511881.2 | 93953 | 1.64041666667 | 11087 |
| 010871 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597101.3 | 511880.7 | 93955 | 1.64041666667 | 10871 |
| 011298 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597101.8 | 511881.2 | 93957 | 1.64041666667 | 11298 |
| 009934 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597101.4 | 511881.9 | 93959 | 1.64041666667 | 9934 |
| 009233 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597099.5 | 511881.5 | 93961 | 1.64041666667 | 9233 |
| 009448 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597097.1 | 511880.3 | 93963 | 1.64041666667 | 9448 |
| 010192 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597094.9 | 511879.0 | 93965 | 1.64041666667 | 10192 |
| 009958 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597092.9 | 511877.8 | 93967 | 1.64041666667 | 9958 |
| 010199 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597091.7 | 511877.4 | 93969 | 1.64041666667 | 10199 |
| 009840 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597091.3 | 511877.2 | 93971 | 1.64041666667 | 9840 |
| 010080 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597091.3 | 511877.1 | 93973 | 1.64041666667 | 10080 |
| 011520 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597091.7 | 511876.6 | 93975 | 1.64041666667 | 11520 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010860 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:17pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597092.6 | 511875.0 | 93977 | 1.64041666667 | 10860 |
| 009525 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:18pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597093.9 | 511872.9 | 93979 | 1.64041666667 | 9525 |
| 010181 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597094.5 | 511872.3 | 93981 | 1.64041666667 | 10181 |
| 010495 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597094.5 | 511872.3 | 93983 | 1.64041666667 | 10495 |
| 010633 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597094.7 | 511871.1 | 93985 | 1.64041666667 | 10633 |
| 009258 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597095.8 | 511868.8 | 93987 | 1.64041666667 | 9258 |
| 009814 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597096.7 | 511867.5 | 93989 | 1.64041666667 | 9814 |
| 010943 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597097.7 | 511866.9 | 93991 | 1.64041666667 | 10943 |
| 010686 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597098.6 | 511866.7 | 93993 | 1.64041666667 | 10686 |
| 009961 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597098.5 | 511866.4 | 93995 | 1.64041666667 | 9961 |
| 009570 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597098.8 | 511866.6 | 93997 | 1.64041666667 | 9570 |
| 010582 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597099.2 | 511866.8 | 93999 | 1.64041666667 | 10582 |
| 009965 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597099.1 | 511866.7 | 94001 | 1.64041666667 | 9965 |
| 010321 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597098.5 | 511866.3 | 94003 | 1.64041666667 | 10321 |
| 010140 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597097.7 | 511866.0 | 94005 | 1.64041666667 | 10140 |
| 011137 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597096.9 | 511867.1 | 94007 | 1.64041666667 | 11137 |
| 010434 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597095.7 | 511869.0 | 94009 | 1.64041666667 | 10434 |
| 010798 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.5 | 511870.8 | 94011 | 1.64041666667 | 10798 |
| 009959 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597093.9 | 511871.9 | 94013 | 1.64041666667 | 9959 |
| 010560 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.6 | 511872.2 | 94015 | 1.64041666667 | 10560 |
| 009750 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.6 | 511872.3 | 94017 | 1.64041666667 | 9750 |
| 009907 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.7 | 511872.3 | 94019 | 1.64041666667 | 9907 |
| 008296 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.7 | 511872.3 | 94021 | 1.64041666667 | 8296 |
| 010834 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.7 | 511872.5 | 94023 | 1.64041666667 | 10834 |
| 009878 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.0 | 511871.9 | 94025 | 1.64041666667 | 9878 |
| 010569 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.4 | 511871.7 | 94027 | 1.64041666667 | 10569 |
| 009752 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.7 | 511872.4 | 94029 | 1.64041666667 | 9752 |
| 011048 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.9 | 511872.6 | 94031 | 1.64041666667 | 11048 |
| 010142 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.9 | 511872.5 | 94033 | 1.64041666667 | 10142 |
| 010365 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597095.4 | 511872.6 | 94035 | 1.64041666667 | 10365 |
| 010181 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597096.5 | 511873.1 | 94037 | 1.64041666667 | 10181 |
| 009595 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597097.8 | 511873.9 | 94039 | 1.64041666667 | 9595 |
| 009299 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597098.7 | 511874.2 | 94041 | 1.64041666667 | 9299 |
| 009794 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597100.0 | 511873.6 | 94043 | 1.64041666667 | 9794 |
| 011538 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597101.7 | 511873.5 | 94045 | 1.64041666667 | 11538 |
| 011884 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597104.0 | 511874.2 | 94047 | 1.64041666667 | 11884 |
| 010141 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597105.6 | 511874.7 | 94049 | 1.64041666667 | 10141 |
| 011805 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597106.6 | 511875.1 | 94051 | 1.64041666667 | 11805 |
| 012491 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597106.9 | 511875.3 | 94053 | 1.64041666667 | 12491 |
| 011943 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597106.7 | 511875.4 | 94055 | 1.64041666667 | 11943 |
| 011115 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597106.7 | 511875.5 | 94057 | 1.64041666667 | 11115 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597106.8 | 511875.5 | 94059 | 1.64041666667 | 11928 |
| 013452 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597106.9 | 511875.6 | 94061 | 1.64041666667 | 13452 |
| 011463 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597107.3 | 511875.7 | 94063 | 1.64041666667 | 11463 |
| 010515 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597107.6 | 511875.5 | 94065 | 1.64041666667 | 10515 |
| 010518 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597108.2 | 511875.6 | 94067 | 1.64041666667 | 10518 |
| 010939 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597109.6 | 511876.0 | 94069 | 1.64041666667 | 10939 |
| 011225 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597111.7 | 511876.6 | 94071 | 1.64041666667 | 11225 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011416 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597113.6 | 511877.6 | 94073 | 1.64041666667 | 11416 |
| 009364 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597115.6 | 511879.1 | 94075 | 1.64041666667 | 9364 |
| 010981 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597117.4 | 511880.3 | 94077 | 1.64041666667 | 10981 |
| 010425 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597119.9 | 511880.9 | 94079 | 1.64041666667 | 10425 |
| 009086 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597121.5 | 511881.0 | 94081 | 1.64041666667 | 9086 |
| 009861 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597123.1 | 511880.3 | 94083 | 1.64041666667 | 9861 |
| 011225 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597124.4 | 511880.4 | 94085 | 1.64041666667 | 11225 |
| 009946 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597126.6 | 511880.8 | 94087 | 1.64041666667 | 9946 |
| 011726 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597128.2 | 511881.1 | 94089 | 1.64041666667 | 11726 |
| 011031 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597130.0 | 511881.4 | 94091 | 1.64041666667 | 11031 |
| 013138 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597131.6 | 511881.7 | 94093 | 1.64041666667 | 13138 |
| 011294 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597133.3 | 511882.2 | 94095 | 1.64041666667 | 11294 |
| 012693 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597135.0 | 511882.6 | 94097 | 1.64041666667 | 12693 |
| 010253 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597137.1 | 511883.1 | 94099 | 1.64041666667 | 10253 |
| 011533 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597139.1 | 511884.0 | 94101 | 1.64041666667 | 11533 |
| 011013 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597141.5 | 511885.3 | 94103 | 1.64041666667 | 11013 |
| 011963 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597143.4 | 511886.2 | 94105 | 1.64041666667 | 11963 |
| 011930 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597145.7 | 511887.6 | 94107 | 1.64041666667 | 11930 |
| 010782 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597147.3 | 511888.4 | 94109 | 1.64041666667 | 10782 |
| 011875 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597149.2 | 511888.9 | 94111 | 1.64041666667 | 11875 |
| 011669 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597151.1 | 511889.1 | 94113 | 1.64041666667 | 11669 |
| 010987 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597153.3 | 511890.3 | 94115 | 1.64041666667 | 10987 |
| 010426 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597155.3 | 511891.6 | 94117 | 1.64041666667 | 10426 |
| 010046 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597157.4 | 511892.8 | 94119 | 1.64041666667 | 10046 |
| 009501 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597159.2 | 511893.7 | 94121 | 1.64041666667 | 9501 |
| 009035 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597161.5 | 511895.1 | 94123 | 1.64041666667 | 9035 |
| 010328 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597163.5 | 511896.4 | 94125 | 1.64041666667 | 10328 |
| 012992 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597165.5 | 511897.4 | 94127 | 1.64041666667 | 12992 |
| 011468 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597167.2 | 511897.8 | 94129 | 1.64041666667 | 11468 |
| 010817 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597169.3 | 511898.2 | 94131 | 1.64041666667 | 10817 |
| 012664 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597170.9 | 511899.1 | 94133 | 1.64041666667 | 12664 |
| 012226 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597173.1 | 511899.9 | 94135 | 1.64041666667 | 12226 |
| 012536 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597175.2 | 511900.7 | 94137 | 1.64041666667 | 12536 |
| 013574 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:38pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597177.4 | 511901.6 | 94139 | 1.64041666667 | 13574 |
| 013413 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:39pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597179.2 | 511902.8 | 94141 | 1.64041666667 | 13413 |
| 014873 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:40pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597181.7 | 511904.1 | 94143 | 1.64041666667 | 14873 |
| 013978 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:41pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597184.0 | 511904.9 | 94145 | 1.64041666667 | 13978 |
| 012824 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597186.5 | 511905.4 | 94147 | 1.64041666667 | 12824 |
| 012386 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597188.5 | 511905.8 | 94149 | 1.64041666667 | 12386 |
| 013296 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597191.0 | 511906.5 | 94151 | 1.64041666667 | 13296 |
| 013854 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:45pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597192.7 | 511907.3 | 94153 | 1.64041666667 | 13854 |
| 015103 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:46pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597195.0 | 511908.1 | 94155 | 1.64041666667 | 15103 |
| 014216 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:47pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597196.9 | 511908.5 | 94157 | 1.64041666667 | 14216 |
| 013904 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:48pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597199.2 | 511909.1 | 94159 | 1.64041666667 | 13904 |
| 012956 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597201.1 | 511909.5 | 94161 | 1.64041666667 | 12956 |
| 011339 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.6 | 1597202.7 | 511909.9 | 94163 | 1.64041666667 | 11339 |
| 010664 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.9 | 1597203.7 | 511910.5 | 94165 | 1.64041666667 | 10664 |
| 012356 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:52pm | Sensor | 1797-S0055-G-TJV.cor | 6860.1 | 1597205.0 | 511911.4 | 94167 | 1.64041666667 | 12356 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012569 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:53pm | Sensor | 1797-S0055-G-TJV.cor | 6859.9 | 1597206.3 | 511912.5 | 94169 | 1.64041666667 | 12569 |
| 014482 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.6 | 1597208.3 | 511913.4 | 94171 | 1.64041666667 | 14482 |
| 013130 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:55pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597209.8 | 511914.1 | 94173 | 1.64041666667 | 13130 |
| 013242 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:56pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597211.8 | 511914.2 | 94175 | 1.64041666667 | 13242 |
| 013570 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:57pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597213.2 | 511914.8 | 94177 | 1.64041666667 | 13570 |
| 013802 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:58pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597215.0 | 511915.6 | 94179 | 1.64041666667 | 13802 |
| 013710 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:59pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597217.0 | 511916.3 | 94181 | 1.64041666667 | 13710 |
| 013927 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:00pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597219.2 | 511917.5 | 94183 | 1.64041666667 | 13927 |
| 013382 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597221.2 | 511918.5 | 94185 | 1.64041666667 | 13382 |
| 012315 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:02pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597223.4 | 511919.3 | 94187 | 1.64041666667 | 12315 |
| 013548 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:03pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597225.0 | 511919.6 | 94189 | 1.64041666667 | 13548 |
| 011997 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:04pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597226.9 | 511920.6 | 94191 | 1.64041666667 | 11997 |
| 012449 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597227.2 | 511920.7 | 94193 | 1.64041666667 | 12449 |
| 011152 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597225.6 | 511920.5 | 94195 | 1.64041666667 | 11152 |
| 011548 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:07pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597225.3 | 511920.6 | 94197 | 1.64041666667 | 11548 |
| 012217 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:08pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597225.7 | 511920.6 | 94199 | 1.64041666667 | 12217 |
| 013014 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:09pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597226.2 | 511919.5 | 94201 | 1.64041666667 | 13014 |
| 013513 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:10pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597227.4 | 511917.0 | 94203 | 1.64041666667 | 13513 |
| 013998 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:11pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597228.2 | 511915.6 | 94205 | 1.64041666667 | 13998 |
| 012589 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:12pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597228.6 | 511914.3 | 94207 | 1.64041666667 | 12589 |
| 013227 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:13pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597229.0 | 511913.8 | 94209 | 1.64041666667 | 13227 |
| 012127 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:14pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597229.0 | 511914.1 | 94211 | 1.64041666667 | 12127 |
| 013141 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:15pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597229.1 | 511913.2 | 94213 | 1.64041666667 | 13141 |
| 013995 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:16pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597230.2 | 511910.5 | 94215 | 1.64041666667 | 13995 |
| 013698 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:17pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597231.4 | 511908.6 | 94217 | 1.64041666667 | 13698 |
| 014374 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597232.0 | 511907.0 | 94219 | 1.64041666667 | 14374 |
| 013553 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597232.0 | 511907.0 | 94221 | 1.64041666667 | 13553 |
| 015628 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:20pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597231.0 | 511907.8 | 94223 | 1.64041666667 | 15628 |
| 016027 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597230.8 | 511909.3 | 94225 | 1.64041666667 | 16027 |
| 016096 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:22pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597231.1 | 511911.2 | 94227 | 1.64041666667 | 16096 |
| 013984 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:23pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597230.2 | 511912.6 | 94229 | 1.64041666667 | 13984 |
| 013726 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:24pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597229.6 | 511913.5 | 94231 | 1.64041666667 | 13726 |
| 013601 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:25pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597229.1 | 511913.9 | 94233 | 1.64041666667 | 13601 |
| 013090 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:26pm | Sensor | 1797-S0055-G-TJV.cor | 6854.6 | 1597228.1 | 511913.8 | 94235 | 1.64041666667 | 13090 |
| 014132 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:27pm | Sensor | 1797-S0055-G-TJV.cor | 6855.2 | 1597226.1 | 511912.7 | 94237 | 1.64041666667 | 14132 |
| 014543 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597223.9 | 511911.1 | 94239 | 1.64041666667 | 14543 |
| 013265 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:29pm | Sensor | 1797-S0055-G-TJV.cor | 6855.9 | 1597222.4 | 511910.5 | 94241 | 1.64041666667 | 13265 |
| 013666 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:30pm | Sensor | 1797-S0055-G-TJV.cor | 6855.5 | 1597219.9 | 511909.5 | 94243 | 1.64041666667 | 13666 |
| 013526 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597217.6 | 511908.4 | 94245 | 1.64041666667 | 13526 |
| 011691 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:32pm | Sensor | 1797-S0055-G-TJV.cor | 6856.3 | 1597215.3 | 511908.1 | 94247 | 1.64041666667 | 11691 |
| 013183 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597213.5 | 511907.1 | 94249 | 1.64041666667 | 13183 |
| 012205 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:34pm | Sensor | 1797-S0055-G-TJV.cor | 6856.0 | 1597212.4 | 511906.7 | 94251 | 1.64041666667 | 12205 |
| 016641 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:35pm | Sensor | 1797-S0055-G-TJV.cor | 6852.5 | 1597212.2 | 511905.7 | 94253 | 1.64041666667 | 16641 |
| 016640 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:36pm | Sensor | 1797-S0055-G-TJV.cor | 6853.6 | 1597211.5 | 511904.4 | 94255 | 1.64041666667 | 16640 |
| 012890 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:37pm | Sensor | 1797-S0055-G-TJV.cor | 6853.4 | 1597211.8 | 511903.6 | 94257 | 1.64041666667 | 12890 |
| 015132 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:38pm | Sensor | 1797-S0055-G-TJV.cor | 6852.8 | 1597212.2 | 511901.9 | 94259 | 1.64041666667 | 15132 |
| 014013 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:39pm | Sensor | 1797-S0055-G-TJV.cor | 6854.0 | 1597212.3 | 511901.2 | 94261 | 1.64041666667 | 14013 |
| 013583 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:40pm | Sensor | 1797-S0055-G-TJV.cor | 6855.8 | 1597212.3 | 511900.5 | 94263 | 1.64041666667 | 13583 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013415 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:41pm | Sensor | 1797-S0055-G-TJV.cor | 6855.9 | 1597212.3 | 511900.4 | 94265 | 1.64041666667 | 13415 |
| 013374 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:42pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597212.4 | 511900.4 | 94267 | 1.64041666667 | 13374 |
| 012733 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:43pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597212.5 | 511900.4 | 94269 | 1.64041666667 | 12733 |
| 012873 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:44pm | Sensor | 1797-S0055-G-TJV.cor | 6856.2 | 1597212.6 | 511900.5 | 94271 | 1.64041666667 | 12873 |
| 011798 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:45pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597212.2 | 511900.9 | 94273 | 1.64041666667 | 11798 |
| 012189 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597211.4 | 511901.9 | 94275 | 1.64041666667 | 12189 |
| 013607 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:47pm | Sensor | 1797-S0055-G-TJV.cor | 6859.6 | 1597211.2 | 511903.0 | 94277 | 1.64041666667 | 13607 |
| 013691 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:48pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597211.2 | 511903.9 | 94279 | 1.64041666667 | 13691 |
| 012483 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.7 | 1597209.6 | 511904.4 | 94281 | 1.64041666667 | 12483 |
| 014640 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597207.3 | 511904.3 | 94283 | 1.64041666667 | 14640 |
| 016350 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597205.5 | 511903.5 | 94285 | 1.64041666667 | 16350 |
| 013807 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:52pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597202.7 | 511902.8 | 94287 | 1.64041666667 | 13807 |
| 013622 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:53pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597200.8 | 511902.0 | 94289 | 1.64041666667 | 13622 |
| 011835 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597198.6 | 511901.1 | 94291 | 1.64041666667 | 11835 |
| 012588 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597196.8 | 511899.8 | 94293 | 1.64041666667 | 12588 |
| 014577 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:56pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597195.1 | 511898.1 | 94295 | 1.64041666667 | 14577 |
| 014534 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:57pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597193.0 | 511897.0 | 94297 | 1.64041666667 | 14534 |
| 013983 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:58pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597190.6 | 511896.4 | 94299 | 1.64041666667 | 13983 |
| 013245 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:59pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597188.7 | 511896.4 | 94301 | 1.64041666667 | 13245 |
| 012701 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:00pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597186.0 | 511895.9 | 94303 | 1.64041666667 | 12701 |
| 013435 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:01pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597183.7 | 511895.4 | 94305 | 1.64041666667 | 13435 |
| 014339 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597181.4 | 511894.6 | 94307 | 1.64041666667 | 14339 |
| 013784 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:03pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597179.7 | 511893.8 | 94309 | 1.64041666667 | 13784 |
| 012776 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:04pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597177.8 | 511892.9 | 94311 | 1.64041666667 | 12776 |
| 012194 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:05pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597175.7 | 511892.3 | 94313 | 1.64041666667 | 12194 |
| 011298 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:06pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597173.2 | 511891.5 | 94315 | 1.64041666667 | 11298 |
| 012364 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597171.1 | 511890.7 | 94317 | 1.64041666667 | 12364 |
| 013831 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597168.9 | 511889.6 | 94319 | 1.64041666667 | 13831 |
| 012337 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597166.6 | 511889.1 | 94321 | 1.64041666667 | 12337 |
| 012834 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597164.3 | 511888.9 | 94323 | 1.64041666667 | 12834 |
| 011158 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597162.1 | 511888.8 | 94325 | 1.64041666667 | 11158 |
| 011639 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597159.5 | 511888.5 | 94327 | 1.64041666667 | 11639 |
| 012720 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597157.3 | 511887.5 | 94329 | 1.64041666667 | 12720 |
| 011280 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597154.9 | 511886.3 | 94331 | 1.64041666667 | 11280 |
| 012480 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597153.2 | 511885.2 | 94333 | 1.64041666667 | 12480 |
| 012180 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597150.7 | 511884.3 | 94335 | 1.64041666667 | 12180 |
| 014655 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597148.6 | 511883.8 | 94337 | 1.64041666667 | 14655 |
| 012843 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597146.1 | 511883.5 | 94339 | 1.64041666667 | 12843 |
| 015780 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597144.3 | 511883.1 | 94341 | 1.64041666667 | 15780 |
| 013785 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597141.8 | 511882.0 | 94343 | 1.64041666667 | 13785 |
| 015056 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597140.1 | 511881.0 | 94345 | 1.64041666667 | 15056 |
| 014354 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597137.7 | 511880.4 | 94347 | 1.64041666667 | 14354 |
| 012408 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597135.5 | 511880.2 | 94349 | 1.64041666667 | 12408 |
| 011982 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597132.7 | 511880.0 | 94351 | 1.64041666667 | 11982 |
| 011365 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597130.6 | 511880.1 | 94353 | 1.64041666667 | 11365 |
| 012021 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597128.1 | 511880.2 | 94355 | 1.64041666667 | 12021 |
| 011735 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597126.1 | 511880.1 | 94357 | 1.64041666667 | 11735 |
| 011783 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597123.6 | 511879.2 | 94359 | 1.64041666667 | 11783 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010146 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597122.2 | 511878.3 | 94361 | 1.64041666667 | 10146 |
| 012946 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597120.7 | 511876.1 | 94363 | 1.64041666667 | 12946 |
| 012866 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597119.2 | 511874.6 | 94365 | 1.64041666667 | 12866 |
| 012576 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597116.6 | 511873.4 | 94367 | 1.64041666667 | 12576 |
| 010644 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597114.7 | 511872.8 | 94369 | 1.64041666667 | 10644 |
| 013311 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597112.6 | 511871.4 | 94371 | 1.64041666667 | 13311 |
| 011367 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597111.0 | 511870.2 | 94373 | 1.64041666667 | 11367 |
| 012112 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597108.8 | 511868.8 | 94375 | 1.64041666667 | 12112 |
| 012028 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597106.8 | 511868.0 | 94377 | 1.64041666667 | 12028 |
| 011437 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597104.4 | 511867.7 | 94379 | 1.64041666667 | 11437 |
| 011409 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597102.9 | 511867.6 | 94381 | 1.64041666667 | 11409 |
| 011642 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597101.9 | 511868.1 | 94383 | 1.64041666667 | 11642 |
| 009930 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597100.4 | 511867.9 | 94385 | 1.64041666667 | 9930 |
| 011782 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597098.0 | 511867.2 | 94387 | 1.64041666667 | 11782 |
| 011435 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597095.8 | 511866.5 | 94389 | 1.64041666667 | 11435 |
| 011409 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.6 | 511865.6 | 94391 | 1.64041666667 | 11409 |
| 010652 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597092.4 | 511865.1 | 94393 | 1.64041666667 | 10652 |
| 010553 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597092.0 | 511864.1 | 94395 | 1.64041666667 | 10553 |
| 009988 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597092.9 | 511862.1 | 94397 | 1.64041666667 | 9988 |
| 010807 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597093.8 | 511860.5 | 94399 | 1.64041666667 | 10807 |
| 010201 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.5 | 511860.1 | 94401 | 1.64041666667 | 10201 |
| 010050 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.8 | 511860.1 | 94403 | 1.64041666667 | 10050 |
| 009862 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597094.9 | 511859.1 | 94405 | 1.64041666667 | 9862 |
| 009965 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597095.9 | 511856.5 | 94407 | 1.64041666667 | 9965 |
| 010441 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597097.0 | 511855.2 | 94409 | 1.64041666667 | 10441 |
| 011610 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597099.1 | 511854.9 | 94411 | 1.64041666667 | 11610 |
| 016582 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597100.7 | 511855.7 | 94413 | 1.64041666667 | 16582 |
| 018215 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597102.7 | 511856.6 | 94415 | 1.64041666667 | 18215 |
| 019314 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597103.8 | 511857.2 | 94417 | 1.64041666667 | 19314 |
| 020428 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597103.8 | 511857.0 | 94419 | 1.64041666667 | 20428 |
| 019814 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597103.2 | 511856.6 | 94421 | 1.64041666667 | 19814 |
| 018256 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597103.0 | 511856.6 | 94423 | 1.64041666667 | 18256 |
| 016264 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597102.0 | 511856.7 | 94425 | 1.64041666667 | 16264 |
| 016096 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597099.5 | 511856.4 | 94427 | 1.64041666667 | 16096 |
| 013084 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597096.9 | 511856.7 | 94429 | 1.64041666667 | 13084 |
| 009931 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.8 | 511858.1 | 94431 | 1.64041666667 | 9931 |
| 009952 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597093.8 | 511859.4 | 94433 | 1.64041666667 | 9952 |
| 010468 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597093.5 | 511860.2 | 94435 | 1.64041666667 | 10468 |
| 009727 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597094.3 | 511860.3 | 94437 | 1.64041666667 | 9727 |
| 011281 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597096.0 | 511860.9 | 94439 | 1.64041666667 | 11281 |
| 012480 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597097.9 | 511861.7 | 94441 | 1.64041666667 | 12480 |
| 014220 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597100.1 | 511862.5 | 94443 | 1.64041666667 | 14220 |
| 010575 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597101.9 | 511863.9 | 94445 | 1.64041666667 | 10575 |
| 009813 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597104.0 | 511865.3 | 94447 | 1.64041666667 | 9813 |
| 011993 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597106.1 | 511866.3 | 94449 | 1.64041666667 | 11993 |
| 009598 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597108.5 | 511867.6 | 94451 | 1.64041666667 | 9598 |
| 010019 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597110.5 | 511868.7 | 94453 | 1.64041666667 | 10019 |
| 011415 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597112.9 | 511869.8 | 94455 | 1.64041666667 | 11415 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012273 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597114.9 | 511870.2 | 94457 | 1.64041666667 | 12273 |
| 014048 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597117.3 | 511870.9 | 94459 | 1.64041666667 | 14048 |
| 013922 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597119.6 | 511871.2 | 94461 | 1.64041666667 | 13922 |
| 013110 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597122.3 | 511871.8 | 94463 | 1.64041666667 | 13110 |
| 011857 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597125.0 | 511872.0 | 94465 | 1.64041666667 | 11857 |
| 013194 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597127.7 | 511872.5 | 94467 | 1.64041666667 | 13194 |
| 011338 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597130.0 | 511873.3 | 94469 | 1.64041666667 | 11338 |
| 010754 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597132.1 | 511874.7 | 94471 | 1.64041666667 | 10754 |
| 011988 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597134.0 | 511875.8 | 94473 | 1.64041666667 | 11988 |
| 012567 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597136.6 | 511876.5 | 94475 | 1.64041666667 | 12567 |
| 015051 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597138.4 | 511877.3 | 94477 | 1.64041666667 | 15051 |
| 017743 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597141.3 | 511877.9 | 94479 | 1.64041666667 | 17743 |
| 018505 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597143.4 | 511878.1 | 94481 | 1.64041666667 | 18505 |
| 016896 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:30pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597145.5 | 511878.0 | 94483 | 1.64041666667 | 16896 |
| 015834 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:31pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597147.3 | 511878.2 | 94485 | 1.64041666667 | 15834 |
| 016078 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597149.7 | 511878.2 | 94487 | 1.64041666667 | 16078 |
| 014369 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597151.6 | 511878.3 | 94489 | 1.64041666667 | 14369 |
| 016582 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597153.9 | 511878.6 | 94491 | 1.64041666667 | 16582 |
| 016895 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597156.1 | 511879.8 | 94493 | 1.64041666667 | 16895 |
| 015173 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597157.7 | 511881.1 | 94495 | 1.64041666667 | 15173 |
| 013783 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597158.8 | 511881.8 | 94497 | 1.64041666667 | 13783 |
| 016586 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:38pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597161.4 | 511882.3 | 94499 | 1.64041666667 | 16586 |
| 016236 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:39pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597163.1 | 511882.7 | 94501 | 1.64041666667 | 16236 |
| 016629 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:40pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597165.3 | 511883.1 | 94503 | 1.64041666667 | 16629 |
| 017657 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:41pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597167.5 | 511883.9 | 94505 | 1.64041666667 | 17657 |
| 017404 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597169.9 | 511884.4 | 94507 | 1.64041666667 | 17404 |
| 014911 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597172.0 | 511884.7 | 94509 | 1.64041666667 | 14911 |
| 013297 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597174.6 | 511885.3 | 94511 | 1.64041666667 | 13297 |
| 013134 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597176.5 | 511885.8 | 94513 | 1.64041666667 | 13134 |
| 011233 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597178.0 | 511886.6 | 94515 | 1.64041666667 | 11233 |
| 013518 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:47pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597179.9 | 511887.7 | 94517 | 1.64041666667 | 13518 |
| 014449 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:48pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597182.7 | 511888.8 | 94519 | 1.64041666667 | 14449 |
| 013422 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:49pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597185.0 | 511889.2 | 94521 | 1.64041666667 | 13422 |
| 013555 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:50pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597187.1 | 511889.9 | 94523 | 1.64041666667 | 13555 |
| 012599 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:51pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597189.0 | 511890.4 | 94525 | 1.64041666667 | 12599 |
| 013709 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:52pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597191.3 | 511891.2 | 94527 | 1.64041666667 | 13709 |
| 013327 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597193.2 | 511891.9 | 94529 | 1.64041666667 | 13327 |
| 013891 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:54pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597195.1 | 511893.4 | 94531 | 1.64041666667 | 13891 |
| 014002 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597196.4 | 511894.5 | 94533 | 1.64041666667 | 14002 |
| 015620 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:56pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597197.9 | 511895.8 | 94535 | 1.64041666667 | 15620 |
| 015395 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:57pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597199.3 | 511895.9 | 94537 | 1.64041666667 | 15395 |
| 013268 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:58pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597201.4 | 511896.1 | 94539 | 1.64041666667 | 13268 |
| 012887 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:59pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597203.5 | 511896.8 | 94541 | 1.64041666667 | 12887 |
| 013721 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:00pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597206.4 | 511897.6 | 94543 | 1.64041666667 | 13721 |
| 014830 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597208.5 | 511898.3 | 94545 | 1.64041666667 | 14830 |
| 013337 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:02pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597210.4 | 511899.2 | 94547 | 1.64041666667 | 13337 |
| 013234 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:03pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597211.6 | 511899.8 | 94549 | 1.64041666667 | 13234 |
| 013718 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:04pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597211.3 | 511899.7 | 94551 | 1.64041666667 | 13718 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013029 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597210.8 | 511899.1 | 94553 | 1.64041666667 | 13029 |
| 013097 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597211.7 | 511899.5 | 94555 | 1.64041666667 | 13097 |
| 014134 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:07pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597212.9 | 511900.2 | 94557 | 1.64041666667 | 14134 |
| 014063 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:08pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597214.7 | 511901.1 | 94559 | 1.64041666667 | 14063 |
| 012816 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:09pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597217.0 | 511901.8 | 94561 | 1.64041666667 | 12816 |
| 013284 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:10pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597219.8 | 511902.6 | 94563 | 1.64041666667 | 13284 |
| 013461 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:11pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597222.5 | 511903.4 | 94565 | 1.64041666667 | 13461 |
| 012845 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:12pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597225.0 | 511904.0 | 94567 | 1.64041666667 | 12845 |
| 014281 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:13pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597226.9 | 511905.3 | 94569 | 1.64041666667 | 14281 |
| 014670 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:14pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597229.3 | 511906.5 | 94571 | 1.64041666667 | 14670 |
| 015037 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:15pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597230.7 | 511907.2 | 94573 | 1.64041666667 | 15037 |
| 015129 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:16pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597231.0 | 511906.7 | 94575 | 1.64041666667 | 15129 |
| 015962 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:17pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597230.6 | 511906.8 | 94577 | 1.64041666667 | 15962 |
| 015810 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:18pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597230.4 | 511906.9 | 94579 | 1.64041666667 | 15810 |
| 016552 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:19pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597230.6 | 511905.5 | 94581 | 1.64041666667 | 16552 |
| 014218 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:20pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597231.5 | 511902.8 | 94583 | 1.64041666667 | 14218 |
| 015014 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:21pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597231.8 | 511901.0 | 94585 | 1.64041666667 | 15014 |
| 014823 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:22pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597232.4 | 511900.6 | 94587 | 1.64041666667 | 14823 |
| 014595 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:23pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597232.4 | 511900.3 | 94589 | 1.64041666667 | 14595 |
| 013368 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:24pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597232.4 | 511899.5 | 94591 | 1.64041666667 | 13368 |
| 012762 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:25pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597232.8 | 511897.4 | 94593 | 1.64041666667 | 12762 |
| 011650 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:26pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597233.3 | 511894.9 | 94595 | 1.64041666667 | 11650 |
| 012602 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:27pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597233.9 | 511893.7 | 94597 | 1.64041666667 | 12602 |
| 013830 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:28pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597234.2 | 511892.5 | 94599 | 1.64041666667 | 13830 |
| 013297 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:29pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597233.9 | 511893.0 | 94601 | 1.64041666667 | 13297 |
| 012714 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:30pm | Sensor | 1797-S0055-G-TJV.cor | 6859.7 | 1597233.6 | 511893.9 | 94603 | 1.64041666667 | 12714 |
| 012178 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:31pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597233.7 | 511893.9 | 94605 | 1.64041666667 | 12178 |
| 012944 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:32pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597233.5 | 511893.8 | 94607 | 1.64041666667 | 12944 |
| 012416 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:33pm | Sensor | 1797-S0055-G-TJV.cor | 6859.9 | 1597233.4 | 511893.7 | 94609 | 1.64041666667 | 12416 |
| 012824 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:34pm | Sensor | 1797-S0055-G-TJV.cor | 6859.9 | 1597233.4 | 511893.7 | 94611 | 1.64041666667 | 12824 |
| 013376 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:35pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597233.5 | 511894.8 | 94613 | 1.64041666667 | 13376 |
| 013244 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:36pm | Sensor | 1797-S0055-G-TJV.cor | 6859.6 | 1597233.6 | 511896.8 | 94615 | 1.64041666667 | 13244 |
| 012941 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:37pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597233.0 | 511897.9 | 94617 | 1.64041666667 | 12941 |
| 013075 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:38pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597232.4 | 511899.4 | 94619 | 1.64041666667 | 13075 |
| 011728 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:39pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597231.8 | 511899.4 | 94621 | 1.64041666667 | 11728 |
| 013402 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:40pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597230.4 | 511899.1 | 94623 | 1.64041666667 | 13402 |
| 013130 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:41pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597228.9 | 511898.4 | 94625 | 1.64041666667 | 13130 |
| 013392 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:42pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597226.2 | 511897.3 | 94627 | 1.64041666667 | 13392 |
| 014238 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:43pm | Sensor | 1797-S0055-G-TJV.cor | 6859.7 | 1597224.4 | 511896.2 | 94629 | 1.64041666667 | 14238 |
| 012259 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:44pm | Sensor | 1797-S0055-G-TJV.cor | 6859.9 | 1597223.0 | 511895.4 | 94631 | 1.64041666667 | 12259 |
| 010654 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:45pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597221.3 | 511894.9 | 94633 | 1.64041666667 | 10654 |
| 011573 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:46pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597218.9 | 511894.2 | 94635 | 1.64041666667 | 11573 |
| 012643 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:47pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597216.7 | 511893.7 | 94637 | 1.64041666667 | 12643 |
| 012911 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:48pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597214.4 | 511892.8 | 94639 | 1.64041666667 | 12911 |
| 013427 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597212.7 | 511892.1 | 94641 | 1.64041666667 | 13427 |
| 014696 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597211.0 | 511891.0 | 94643 | 1.64041666667 | 14696 |
| 012914 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597208.9 | 511890.4 | 94645 | 1.64041666667 | 12914 |
| 014568 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:52pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597206.9 | 511888.8 | 94647 | 1.64041666667 | 14568 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015102 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:53pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597205.1 | 511887.9 | 94649 | 1.64041666667 | 15102 |
| 014575 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597202.7 | 511887.0 | 94651 | 1.64041666667 | 14575 |
| 014954 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:55pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597200.3 | 511886.7 | 94653 | 1.64041666667 | 14954 |
| 013698 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:56pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597198.1 | 511886.2 | 94655 | 1.64041666667 | 13698 |
| 014644 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:57pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597196.4 | 511885.4 | 94657 | 1.64041666667 | 14644 |
| 013711 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:58pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597194.5 | 511884.0 | 94659 | 1.64041666667 | 13711 |
| 013477 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:59pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597192.3 | 511883.4 | 94661 | 1.64041666667 | 13477 |
| 014529 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:00pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597189.7 | 511883.1 | 94663 | 1.64041666667 | 14529 |
| 014552 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597187.7 | 511883.0 | 94665 | 1.64041666667 | 14552 |
| 013868 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:02pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597185.1 | 511882.8 | 94667 | 1.64041666667 | 13868 |
| 012707 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:03pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597183.0 | 511882.1 | 94669 | 1.64041666667 | 12707 |
| 013316 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:04pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597180.8 | 511881.5 | 94671 | 1.64041666667 | 13316 |
| 012689 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597179.2 | 511880.9 | 94673 | 1.64041666667 | 12689 |
| 013702 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597177.0 | 511880.5 | 94675 | 1.64041666667 | 13702 |
| 016805 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597174.7 | 511879.7 | 94677 | 1.64041666667 | 16805 |
| 015121 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597172.1 | 511879.2 | 94679 | 1.64041666667 | 15121 |
| 015630 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597169.5 | 511878.6 | 94681 | 1.64041666667 | 15630 |
| 017527 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597166.7 | 511878.3 | 94683 | 1.64041666667 | 17527 |
| 016292 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597164.6 | 511877.6 | 94685 | 1.64041666667 | 16292 |
| 016763 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597161.8 | 511876.5 | 94687 | 1.64041666667 | 16763 |
| 016910 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597159.7 | 511875.8 | 94689 | 1.64041666667 | 16910 |
| 015237 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597156.8 | 511875.5 | 94691 | 1.64041666667 | 15237 |
| 013949 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597154.8 | 511875.6 | 94693 | 1.64041666667 | 13949 |
| 015127 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597152.4 | 511874.8 | 94695 | 1.64041666667 | 15127 |
| 014521 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597150.6 | 511874.2 | 94697 | 1.64041666667 | 14521 |
| 011250 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597148.2 | 511872.7 | 94699 | 1.64041666667 | 11250 |
| 011182 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597145.9 | 511872.1 | 94701 | 1.64041666667 | 11182 |
| 011075 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597143.3 | 511871.1 | 94703 | 1.64041666667 | 11075 |
| 010179 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597141.4 | 511870.5 | 94705 | 1.64041666667 | 10179 |
| 010644 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597139.4 | 511869.8 | 94707 | 1.64041666667 | 10644 |
| 015261 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:23pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597137.1 | 511869.7 | 94709 | 1.64041666667 | 15261 |
| 013265 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597134.9 | 511869.5 | 94711 | 1.64041666667 | 13265 |
| 012826 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597133.3 | 511868.8 | 94713 | 1.64041666667 | 12826 |
| 012206 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597130.7 | 511868.7 | 94715 | 1.64041666667 | 12206 |
| 014331 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597128.5 | 511868.2 | 94717 | 1.64041666667 | 14331 |
| 012403 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597126.4 | 511867.9 | 94719 | 1.64041666667 | 12403 |
| 013480 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597124.6 | 511867.3 | 94721 | 1.64041666667 | 13480 |
| 013750 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597121.9 | 511866.8 | 94723 | 1.64041666667 | 13750 |
| 014987 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597119.6 | 511866.1 | 94725 | 1.64041666667 | 14987 |
| 013316 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597117.8 | 511864.3 | 94727 | 1.64041666667 | 13316 |
| 011639 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597116.1 | 511862.7 | 94729 | 1.64041666667 | 11639 |
| 011130 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597114.1 | 511861.2 | 94731 | 1.64041666667 | 11130 |
| 011662 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597112.0 | 511860.4 | 94733 | 1.64041666667 | 11662 |
| 011045 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597110.0 | 511859.0 | 94735 | 1.64041666667 | 11045 |
| 010711 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597108.0 | 511857.6 | 94737 | 1.64041666667 | 10711 |
| 011407 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597105.6 | 511856.2 | 94739 | 1.64041666667 | 11407 |
| 014312 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597103.4 | 511856.2 | 94741 | 1.64041666667 | 14312 |
| 013868 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597100.9 | 511855.6 | 94743 | 1.64041666667 | 13868 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011597 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597098.6 | 511854.6 | 94745 | 1.64041666667 | 11597 |
| 009409 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597096.7 | 511853.6 | 94747 | 1.64041666667 | 9409 |
| 009582 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597095.8 | 511852.9 | 94749 | 1.64041666667 | 9582 |
| 010045 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597096.2 | 511853.2 | 94751 | 1.64041666667 | 10045 |
| 010551 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597097.8 | 511854.5 | 94753 | 1.64041666667 | 10551 |
| 013167 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597100.1 | 511856.1 | 94755 | 1.64041666667 | 13167 |
| 017392 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597101.8 | 511857.0 | 94757 | 1.64041666667 | 17392 |
| 020428 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597103.3 | 511857.6 | 94759 | 1.64041666667 | 20428 |
| 018157 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597103.8 | 511857.5 | 94761 | 1.64041666667 | 18157 |
| 019539 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597103.0 | 511858.0 | 94763 | 1.64041666667 | 19539 |
| 016854 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597102.7 | 511859.4 | 94765 | 1.64041666667 | 16854 |
| 011443 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597101.6 | 511860.9 | 94767 | 1.64041666667 | 11443 |
| 010541 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597101.1 | 511860.9 | 94769 | 1.64041666667 | 10541 |
| 016255 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597101.4 | 511859.0 | 94771 | 1.64041666667 | 16255 |
| 017773 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597101.9 | 511857.3 | 94773 | 1.64041666667 | 17773 |
| 015213 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597102.2 | 511854.9 | 94775 | 1.64041666667 | 15213 |
| 012893 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597103.1 | 511852.4 | 94777 | 1.64041666667 | 12893 |
| 011803 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597103.8 | 511850.6 | 94779 | 1.64041666667 | 11803 |
| 011651 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597103.7 | 511850.4 | 94781 | 1.64041666667 | 11651 |
| 011192 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597103.9 | 511850.6 | 94783 | 1.64041666667 | 11192 |
| 010778 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597104.2 | 511850.6 | 94785 | 1.64041666667 | 10778 |
| 010524 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597104.2 | 511850.5 | 94787 | 1.64041666667 | 10524 |
| 011181 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597104.2 | 511849.5 | 94789 | 1.64041666667 | 11181 |
| 011135 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597104.9 | 511847.2 | 94791 | 1.64041666667 | 11135 |
| 012743 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597105.9 | 511846.0 | 94793 | 1.64041666667 | 12743 |
| 011856 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597106.2 | 511845.5 | 94795 | 1.64041666667 | 11856 |
| 011244 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597106.1 | 511845.6 | 94797 | 1.64041666667 | 11244 |
| 010041 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597106.2 | 511845.2 | 94799 | 1.64041666667 | 10041 |
| 009290 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597106.7 | 511844.9 | 94801 | 1.64041666667 | 9290 |
| 010182 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597108.2 | 511846.1 | 94803 | 1.64041666667 | 10182 |
| 010825 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597110.0 | 511847.1 | 94805 | 1.64041666667 | 10825 |
| 012066 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597109.9 | 511847.1 | 94807 | 1.64041666667 | 12066 |
| 012226 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597109.3 | 511846.3 | 94809 | 1.64041666667 | 12226 |
| 012416 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597108.1 | 511845.3 | 94811 | 1.64041666667 | 12416 |
| 013424 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597106.6 | 511846.2 | 94813 | 1.64041666667 | 13424 |
| 009986 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597104.4 | 511847.5 | 94815 | 1.64041666667 | 9986 |
| 010776 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597103.3 | 511849.2 | 94817 | 1.64041666667 | 10776 |
| 012084 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597102.9 | 511850.3 | 94819 | 1.64041666667 | 12084 |
| 010401 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597103.3 | 511850.3 | 94821 | 1.64041666667 | 10401 |
| 010400 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597104.8 | 511850.6 | 94823 | 1.64041666667 | 10400 |
| 011620 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597106.5 | 511851.1 | 94825 | 1.64041666667 | 11620 |
| 012237 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597109.3 | 511851.3 | 94827 | 1.64041666667 | 12237 |
| 011009 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597111.5 | 511851.8 | 94829 | 1.64041666667 | 11009 |
| 009652 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597113.9 | 511851.9 | 94831 | 1.64041666667 | 9652 |
| 010033 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597115.9 | 511852.9 | 94833 | 1.64041666667 | 10033 |
| 009258 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597118.6 | 511854.0 | 94835 | 1.64041666667 | 9258 |
| 010894 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597120.7 | 511854.7 | 94837 | 1.64041666667 | 10894 |
| 010433 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597123.5 | 511855.3 | 94839 | 1.64041666667 | 10433 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010618 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597125.8 | 511855.4 | 94841 | 1.64041666667 | 10618 |
| 010634 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597128.2 | 511855.5 | 94843 | 1.64041666667 | 10634 |
| 011178 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597130.2 | 511855.3 | 94845 | 1.64041666667 | 11178 |
| 010234 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597132.6 | 511855.9 | 94847 | 1.64041666667 | 10234 |
| 009428 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597135.0 | 511856.6 | 94849 | 1.64041666667 | 9428 |
| 009647 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597137.1 | 511858.5 | 94851 | 1.64041666667 | 9647 |
| 008351 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597139.1 | 511859.9 | 94853 | 1.64041666667 | 8351 |
| 008958 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597141.7 | 511861.6 | 94855 | 1.64041666667 | 8958 |
| 008869 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597143.7 | 511862.4 | 94857 | 1.64041666667 | 8869 |
| 009837 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597145.9 | 511863.2 | 94859 | 1.64041666667 | 9837 |
| 009899 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:39pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597147.8 | 511864.2 | 94861 | 1.64041666667 | 9899 |
| 010395 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:40pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597150.0 | 511865.6 | 94863 | 1.64041666667 | 10395 |
| 011598 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:41pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597151.9 | 511866.8 | 94865 | 1.64041666667 | 11598 |
| 011599 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597154.3 | 511867.6 | 94867 | 1.64041666667 | 11599 |
| 011119 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597156.4 | 511867.8 | 94869 | 1.64041666667 | 11119 |
| 012230 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597158.4 | 511867.7 | 94871 | 1.64041666667 | 12230 |
| 013737 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597160.3 | 511868.4 | 94873 | 1.64041666667 | 13737 |
| 012914 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597162.3 | 511869.3 | 94875 | 1.64041666667 | 12914 |
| 012798 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:47pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597163.8 | 511870.4 | 94877 | 1.64041666667 | 12798 |
| 013189 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:48pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597166.0 | 511871.2 | 94879 | 1.64041666667 | 13189 |
| 013497 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:49pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597168.0 | 511872.0 | 94881 | 1.64041666667 | 13497 |
| 013934 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:50pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597169.9 | 511872.7 | 94883 | 1.64041666667 | 13934 |
| 014403 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:51pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597171.6 | 511873.8 | 94885 | 1.64041666667 | 14403 |
| 013890 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:52pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597174.0 | 511874.7 | 94887 | 1.64041666667 | 13890 |
| 015622 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597176.2 | 511875.3 | 94889 | 1.64041666667 | 15622 |
| 013745 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597178.9 | 511875.9 | 94891 | 1.64041666667 | 13745 |
| 013546 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:55pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597180.9 | 511876.5 | 94893 | 1.64041666667 | 13546 |
| 012566 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:56pm | Sensor | 1797-S0055-G-TJV.cor | 6859.7 | 1597182.7 | 511877.9 | 94895 | 1.64041666667 | 12566 |
| 011991 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:57pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597184.6 | 511878.9 | 94897 | 1.64041666667 | 11991 |
| 012598 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:58pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597187.0 | 511880.0 | 94899 | 1.64041666667 | 12598 |
| 012419 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:59pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597189.3 | 511880.5 | 94901 | 1.64041666667 | 12419 |
| 012795 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:00pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597191.7 | 511881.4 | 94903 | 1.64041666667 | 12795 |
| 012397 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597193.7 | 511882.0 | 94905 | 1.64041666667 | 12397 |
| 014239 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597195.9 | 511883.2 | 94907 | 1.64041666667 | 14239 |
| 014959 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:03pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597198.3 | 511884.3 | 94909 | 1.64041666667 | 14959 |
| 013520 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:04pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597201.2 | 511885.0 | 94911 | 1.64041666667 | 13520 |
| 013610 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597203.4 | 511885.0 | 94913 | 1.64041666667 | 13610 |
| 014412 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597205.8 | 511885.1 | 94915 | 1.64041666667 | 14412 |
| 013353 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:07pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597207.7 | 511885.8 | 94917 | 1.64041666667 | 13353 |
| 013898 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:08pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597210.0 | 511886.0 | 94919 | 1.64041666667 | 13898 |
| 013974 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:09pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597211.8 | 511886.9 | 94921 | 1.64041666667 | 13974 |
| 014113 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:10pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597213.9 | 511887.6 | 94923 | 1.64041666667 | 14113 |
| 014448 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:11pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597215.7 | 511888.7 | 94925 | 1.64041666667 | 14448 |
| 014742 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:12pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597218.5 | 511889.2 | 94927 | 1.64041666667 | 14742 |
| 014155 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:13pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597220.8 | 511889.8 | 94929 | 1.64041666667 | 14155 |
| 014639 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:14pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597223.3 | 511890.5 | 94931 | 1.64041666667 | 14639 |
| 012509 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:15pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597225.7 | 511890.7 | 94933 | 1.64041666667 | 12509 |
| 011977 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:16pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597228.4 | 511891.4 | 94935 | 1.64041666667 | 11977 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013374 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597230.9 | 511891.8 | 94937 | 1.64041666667 | 13374 |
| 014923 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:18pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597231.9 | 511892.7 | 94939 | 1.64041666667 | 14923 |
| 015461 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:19pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1597230.8 | 511892.4 | 94941 | 1.64041666667 | 15461 |
| 013465 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:20pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597230.7 | 511890.4 | 94943 | 1.64041666667 | 13465 |
| 013386 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:21pm | Sensor | 1797-S0055-G-TJV.cor | 6853.9 | 1597231.0 | 511889.3 | 94945 | 1.64041666667 | 13386 |
| 012166 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:22pm | Sensor | 1797-S0055-G-TJV.cor | 6854.0 | 1597230.8 | 511887.7 | 94947 | 1.64041666667 | 12166 |
| 013301 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:23pm | Sensor | 1797-S0055-G-TJV.cor | 6855.3 | 1597230.8 | 511886.9 | 94949 | 1.64041666667 | 13301 |
| 012625 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597231.2 | 511884.9 | 94951 | 1.64041666667 | 12625 |
| 012276 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597231.9 | 511883.2 | 94953 | 1.64041666667 | 12276 |
| 013359 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:26pm | Sensor | 1797-S0055-G-TJV.cor | 6853.9 | 1597233.6 | 511881.7 | 94955 | 1.64041666667 | 13359 |
| 013449 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:27pm | Sensor | 1797-S0055-G-TJV.cor | 6853.6 | 1597234.8 | 511880.0 | 94957 | 1.64041666667 | 13449 |
| 013082 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:28pm | Sensor | 1797-S0055-G-TJV.cor | 6854.1 | 1597235.8 | 511879.2 | 94959 | 1.64041666667 | 13082 |
| 011910 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:29pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597235.8 | 511878.5 | 94961 | 1.64041666667 | 11910 |
| 012727 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:30pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597235.8 | 511878.4 | 94963 | 1.64041666667 | 12727 |
| 014252 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:31pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597235.4 | 511878.5 | 94965 | 1.64041666667 | 14252 |
| 012953 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597234.0 | 511878.7 | 94967 | 1.64041666667 | 12953 |
| 012748 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:33pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597232.9 | 511878.8 | 94969 | 1.64041666667 | 12748 |
| 011647 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:34pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597233.0 | 511878.8 | 94971 | 1.64041666667 | 11647 |
| 012811 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:35pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597233.0 | 511878.7 | 94973 | 1.64041666667 | 12811 |
| 011482 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:36pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597232.9 | 511878.6 | 94975 | 1.64041666667 | 11482 |
| 011450 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:37pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597232.8 | 511878.7 | 94977 | 1.64041666667 | 11450 |
| 013092 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:38pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597233.2 | 511879.4 | 94979 | 1.64041666667 | 13092 |
| 013323 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:39pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597233.8 | 511880.8 | 94981 | 1.64041666667 | 13323 |
| 013560 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:40pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597233.2 | 511882.3 | 94983 | 1.64041666667 | 13560 |
| 012540 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:41pm | Sensor | 1797-S0055-G-TJV.cor | 6859.6 | 1597232.5 | 511883.8 | 94985 | 1.64041666667 | 12540 |
| 012075 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:42pm | Sensor | 1797-S0055-G-TJV.cor | 6859.6 | 1597231.1 | 511885.1 | 94987 | 1.64041666667 | 12075 |
| 011598 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:43pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597230.5 | 511886.2 | 94989 | 1.64041666667 | 11598 |
| 012769 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:44pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597230.7 | 511886.0 | 94991 | 1.64041666667 | 12769 |
| 012792 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:45pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597230.5 | 511885.7 | 94993 | 1.64041666667 | 12792 |
| 012318 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:46pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597229.5 | 511885.3 | 94995 | 1.64041666667 | 12318 |
| 013279 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:47pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597227.3 | 511884.9 | 94997 | 1.64041666667 | 13279 |
| 013099 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:48pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597225.0 | 511883.6 | 94999 | 1.64041666667 | 13099 |
| 014915 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597222.8 | 511882.5 | 95001 | 1.64041666667 | 14915 |
| 012548 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597220.9 | 511881.1 | 95003 | 1.64041666667 | 12548 |
| 013067 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:51pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597218.8 | 511879.8 | 95005 | 1.64041666667 | 13067 |
| 013496 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:52pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597216.3 | 511878.8 | 95007 | 1.64041666667 | 13496 |
| 014504 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597214.2 | 511877.7 | 95009 | 1.64041666667 | 14504 |
| 014516 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597211.6 | 511876.9 | 95011 | 1.64041666667 | 14516 |
| 013769 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:55pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597209.6 | 511875.9 | 95013 | 1.64041666667 | 13769 |
| 014932 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:56pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597207.0 | 511875.1 | 95015 | 1.64041666667 | 14932 |
| 013873 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:57pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597204.9 | 511874.1 | 95017 | 1.64041666667 | 13873 |
| 012738 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:58pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597202.2 | 511873.6 | 95019 | 1.64041666667 | 12738 |
| 012964 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:59pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597200.5 | 511872.9 | 95021 | 1.64041666667 | 12964 |
| 013801 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:00pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597198.2 | 511872.4 | 95023 | 1.64041666667 | 13801 |
| 014220 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597196.4 | 511871.3 | 95025 | 1.64041666667 | 14220 |
| 013485 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:02pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597193.8 | 511870.8 | 95027 | 1.64041666667 | 13485 |
| 013031 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:03pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597191.8 | 511870.2 | 95029 | 1.64041666667 | 13031 |
| 013218 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:04pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597189.6 | 511869.7 | 95031 | 1.64041666667 | 13218 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012064 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597187.9 | 511869.1 | 95033 | 1.64041666667 | 12064 |
| 013546 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597185.2 | 511868.8 | 95035 | 1.64041666667 | 13546 |
| 012296 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:07pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597183.2 | 511868.3 | 95037 | 1.64041666667 | 12296 |
| 013214 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:08pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597180.5 | 511868.1 | 95039 | 1.64041666667 | 13214 |
| 014373 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:09pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597178.3 | 511867.8 | 95041 | 1.64041666667 | 14373 |
| 013133 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:10pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597176.0 | 511867.0 | 95043 | 1.64041666667 | 13133 |
| 013153 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597173.6 | 511866.1 | 95045 | 1.64041666667 | 13153 |
| 013428 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597171.4 | 511865.1 | 95047 | 1.64041666667 | 13428 |
| 013737 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597169.1 | 511864.3 | 95049 | 1.64041666667 | 13737 |
| 012254 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597166.7 | 511863.1 | 95051 | 1.64041666667 | 12254 |
| 010263 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597164.5 | 511862.3 | 95053 | 1.64041666667 | 10263 |
| 010095 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597162.2 | 511860.9 | 95055 | 1.64041666667 | 10095 |
| 011133 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597159.9 | 511860.2 | 95057 | 1.64041666667 | 11133 |
| 010943 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597157.5 | 511859.6 | 95059 | 1.64041666667 | 10943 |
| 011106 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597155.3 | 511858.5 | 95061 | 1.64041666667 | 11106 |
| 011026 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597152.7 | 511857.3 | 95063 | 1.64041666667 | 11026 |
| 010046 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597150.3 | 511856.0 | 95065 | 1.64041666667 | 10046 |
| 009381 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597148.1 | 511855.1 | 95067 | 1.64041666667 | 9381 |
| 011075 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597146.5 | 511853.8 | 95069 | 1.64041666667 | 11075 |
| 009788 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597143.8 | 511853.2 | 95071 | 1.64041666667 | 9788 |
| 009767 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597141.4 | 511852.8 | 95073 | 1.64041666667 | 9767 |
| 010181 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597138.6 | 511852.6 | 95075 | 1.64041666667 | 10181 |
| 009985 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597136.3 | 511852.1 | 95077 | 1.64041666667 | 9985 |
| 010746 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597133.6 | 511851.4 | 95079 | 1.64041666667 | 10746 |
| 009616 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597130.9 | 511850.9 | 95081 | 1.64041666667 | 9616 |
| 008884 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597128.5 | 511850.3 | 95083 | 1.64041666667 | 8884 |
| 009061 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597126.6 | 511850.4 | 95085 | 1.64041666667 | 9061 |
| 009015 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597124.0 | 511849.9 | 95087 | 1.64041666667 | 9015 |
| 009933 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597121.9 | 511850.0 | 95089 | 1.64041666667 | 9933 |
| 011843 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597119.4 | 511849.4 | 95091 | 1.64041666667 | 11843 |
| 011511 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597117.2 | 511849.2 | 95093 | 1.64041666667 | 11511 |
| 011097 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597115.2 | 511848.2 | 95095 | 1.64041666667 | 11097 |
| 011114 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597113.3 | 511848.2 | 95097 | 1.64041666667 | 11114 |
| 011358 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597111.8 | 511846.9 | 95099 | 1.64041666667 | 11358 |
| 013429 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597110.8 | 511846.6 | 95101 | 1.64041666667 | 13429 |
| 011757 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597108.6 | 511846.8 | 95103 | 1.64041666667 | 11757 |
| 010258 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597106.6 | 511846.9 | 95105 | 1.64041666667 | 10258 |
| 010627 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597104.3 | 511847.1 | 95107 | 1.64041666667 | 10627 |
| 010036 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597102.4 | 511847.3 | 95109 | 1.64041666667 | 10036 |
| 009949 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:44pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597100.4 | 511846.7 | 95111 | 1.64041666667 | 9949 |
| 010587 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:45pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597099.7 | 511845.5 | 95113 | 1.64041666667 | 10587 |
| 011017 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597100.1 | 511843.4 | 95115 | 1.64041666667 | 11017 |
| 011064 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597100.7 | 511841.8 | 95117 | 1.64041666667 | 11064 |
| 009876 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597101.3 | 511841.6 | 95119 | 1.64041666667 | 9876 |
| 009879 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597101.8 | 511841.3 | 95121 | 1.64041666667 | 9879 |
| 009639 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597102.0 | 511840.3 | 95123 | 1.64041666667 | 9639 |
| 009040 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597102.6 | 511838.2 | 95125 | 1.64041666667 | 9040 |
| 009850 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597103.2 | 511836.6 | 95127 | 1.64041666667 | 9850 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010802 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597103.6 | 511836.3 | 95129 | 1.64041666667 | 10802 |
| 011310 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:54pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597104.4 | 511836.6 | 95131 | 1.64041666667 | 11310 |
| 010987 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:55pm | Sensor | 1797-S0055-G-TJV.cor | 6856.0 | 1597105.6 | 511836.8 | 95133 | 1.64041666667 | 10987 |
| 009857 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:56pm | Sensor | 1797-S0055-G-TJV.cor | 6855.9 | 1597105.6 | 511837.0 | 95135 | 1.64041666667 | 9857 |
| 010174 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.3 | 1597105.2 | 511836.7 | 95137 | 1.64041666667 | 10174 |
| 010373 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597104.2 | 511836.3 | 95139 | 1.64041666667 | 10373 |
| 010363 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597103.6 | 511836.5 | 95141 | 1.64041666667 | 10363 |
| 010151 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597102.7 | 511837.2 | 95143 | 1.64041666667 | 10151 |
| 010187 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597102.2 | 511839.0 | 95145 | 1.64041666667 | 10187 |
| 009596 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597101.4 | 511840.8 | 95147 | 1.64041666667 | 9596 |
| 009479 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597101.3 | 511842.0 | 95149 | 1.64041666667 | 9479 |
| 011010 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597103.3 | 511842.8 | 95151 | 1.64041666667 | 11010 |
| 010942 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597105.1 | 511843.7 | 95153 | 1.64041666667 | 10942 |
| 010985 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597107.6 | 511844.7 | 95155 | 1.64041666667 | 10985 |
| 011116 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597109.5 | 511845.7 | 95157 | 1.64041666667 | 11116 |
| 011989 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597112.3 | 511846.5 | 95159 | 1.64041666667 | 11989 |
| 011997 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597114.6 | 511847.5 | 95161 | 1.64041666667 | 11997 |
| 009449 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597117.4 | 511847.8 | 95163 | 1.64041666667 | 9449 |
| 011482 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597119.6 | 511848.6 | 95165 | 1.64041666667 | 11482 |
| 010490 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597122.0 | 511849.1 | 95167 | 1.64041666667 | 10490 |
| 009282 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597124.4 | 511849.9 | 95169 | 1.64041666667 | 9282 |
| 009550 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597127.4 | 511850.6 | 95171 | 1.64041666667 | 9550 |
| 010637 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597129.7 | 511851.1 | 95173 | 1.64041666667 | 10637 |
| 009499 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597131.8 | 511852.6 | 95175 | 1.64041666667 | 9499 |
| 009574 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597133.8 | 511853.5 | 95177 | 1.64041666667 | 9574 |
| 010823 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597136.1 | 511854.3 | 95179 | 1.64041666667 | 10823 |
| 010986 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597138.4 | 511854.5 | 95181 | 1.64041666667 | 10986 |
| 009586 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597140.4 | 511855.5 | 95183 | 1.64041666667 | 9586 |
| 011006 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597142.3 | 511856.2 | 95185 | 1.64041666667 | 11006 |
| 010851 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597144.5 | 511857.0 | 95187 | 1.64041666667 | 10851 |
| 009823 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597146.9 | 511856.9 | 95189 | 1.64041666667 | 9823 |
| 011065 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597149.1 | 511857.2 | 95191 | 1.64041666667 | 11065 |
| 010536 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597151.4 | 511856.7 | 95193 | 1.64041666667 | 10536 |
| 010014 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597153.9 | 511857.1 | 95195 | 1.64041666667 | 10014 |
| 010903 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597156.4 | 511857.1 | 95197 | 1.64041666667 | 10903 |
| 010586 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597159.0 | 511857.9 | 95199 | 1.64041666667 | 10586 |
| 011106 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597161.4 | 511858.2 | 95201 | 1.64041666667 | 11106 |
| 011446 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:30pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597163.7 | 511858.9 | 95203 | 1.64041666667 | 11446 |
| 012071 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:31pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597166.0 | 511859.9 | 95205 | 1.64041666667 | 12071 |
| 011328 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597168.4 | 511860.4 | 95207 | 1.64041666667 | 11328 |
| 012852 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597170.4 | 511861.0 | 95209 | 1.64041666667 | 12852 |
| 013353 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597172.7 | 511861.9 | 95211 | 1.64041666667 | 13353 |
| 013118 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597174.8 | 511862.5 | 95213 | 1.64041666667 | 13118 |
| 012129 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597176.7 | 511862.9 | 95215 | 1.64041666667 | 12129 |
| 011882 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597178.6 | 511862.9 | 95217 | 1.64041666667 | 11882 |
| 011880 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:38pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597180.5 | 511864.0 | 95219 | 1.64041666667 | 11880 |
| 012660 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:39pm | Sensor | 1797-S0055-G-TJV.cor | 6859.7 | 1597181.5 | 511864.5 | 95221 | 1.64041666667 | 12660 |
| 013155 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:40pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597182.0 | 511865.0 | 95223 | 1.64041666667 | 13155 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012078 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:41pm | Sensor | 1797-S0055-G-TJV.cor | 6859.7 | 1597181.9 | 511865.1 | 95225 | 1.64041666667 | 12078 |
| 012019 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:42pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597182.0 | 511865.1 | 95227 | 1.64041666667 | 12019 |
| 011255 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:43pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597182.0 | 511864.8 | 95229 | 1.64041666667 | 11255 |
| 013463 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:44pm | Sensor | 1797-S0055-G-TJV.cor | 6859.8 | 1597181.7 | 511863.7 | 95231 | 1.64041666667 | 13463 |
| 014256 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:45pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597182.3 | 511862.3 | 95233 | 1.64041666667 | 14256 |
| 013644 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:46pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597182.5 | 511861.4 | 95235 | 1.64041666667 | 13644 |
| 012081 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:47pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597182.0 | 511863.2 | 95237 | 1.64041666667 | 12081 |
| 011960 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:48pm | Sensor | 1797-S0055-G-TJV.cor | 6859.6 | 1597183.1 | 511864.7 | 95239 | 1.64041666667 | 11960 |
| 012470 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597184.1 | 511865.7 | 95241 | 1.64041666667 | 12470 |
| 012507 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597186.8 | 511866.3 | 95243 | 1.64041666667 | 12507 |
| 013027 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597189.1 | 511866.9 | 95245 | 1.64041666667 | 13027 |
| 012226 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:52pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597192.0 | 511866.8 | 95247 | 1.64041666667 | 12226 |
| 013796 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597194.4 | 511867.6 | 95249 | 1.64041666667 | 13796 |
| 013409 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:54pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597197.4 | 511867.8 | 95251 | 1.64041666667 | 13409 |
| 013462 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597199.9 | 511868.1 | 95253 | 1.64041666667 | 13462 |
| 013925 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:56pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597202.7 | 511868.7 | 95255 | 1.64041666667 | 13925 |
| 012421 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:57pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597204.4 | 511869.1 | 95257 | 1.64041666667 | 12421 |
| 013365 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:58pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597206.9 | 511870.4 | 95259 | 1.64041666667 | 13365 |
| 014261 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:59pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597209.1 | 511871.3 | 95261 | 1.64041666667 | 14261 |
| 012265 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:00pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597211.9 | 511872.7 | 95263 | 1.64041666667 | 12265 |
| 012846 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597214.1 | 511873.1 | 95265 | 1.64041666667 | 12846 |
| 014911 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597216.8 | 511874.3 | 95267 | 1.64041666667 | 14911 |
| 015007 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:03pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597218.9 | 511874.9 | 95269 | 1.64041666667 | 15007 |
| 013022 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:04pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597221.5 | 511875.5 | 95271 | 1.64041666667 | 13022 |
| 014445 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597223.8 | 511875.8 | 95273 | 1.64041666667 | 14445 |
| 013481 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:06pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597226.6 | 511876.6 | 95275 | 1.64041666667 | 13481 |
| 011920 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:07pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597228.9 | 511876.7 | 95277 | 1.64041666667 | 11920 |
| 013120 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:08pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597231.2 | 511876.9 | 95279 | 1.64041666667 | 13120 |
| 013240 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:09pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597232.5 | 511877.1 | 95281 | 1.64041666667 | 13240 |
| 013450 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:10pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597234.0 | 511877.7 | 95283 | 1.64041666667 | 13450 |
| 015122 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597235.2 | 511878.0 | 95285 | 1.64041666667 | 15122 |
| 014160 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:12pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597233.7 | 511878.0 | 95287 | 1.64041666667 | 14160 |
| 014310 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:13pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597234.4 | 511876.7 | 95289 | 1.64041666667 | 14310 |
| 012187 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:14pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597235.5 | 511874.5 | 95291 | 1.64041666667 | 12187 |
| 011867 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:15pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597235.9 | 511872.4 | 95293 | 1.64041666667 | 11867 |
| 011816 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:16pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597235.9 | 511872.0 | 95295 | 1.64041666667 | 11816 |
| 012614 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:17pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597235.8 | 511872.1 | 95297 | 1.64041666667 | 12614 |
| 012723 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597236.0 | 511870.7 | 95299 | 1.64041666667 | 12723 |
| 011550 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:19pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597236.2 | 511868.4 | 95301 | 1.64041666667 | 11550 |
| 012517 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:20pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597236.2 | 511866.0 | 95303 | 1.64041666667 | 12517 |
| 012549 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597236.9 | 511864.5 | 95305 | 1.64041666667 | 12549 |
| 012527 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597237.6 | 511863.3 | 95307 | 1.64041666667 | 12527 |
| 013061 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597237.4 | 511863.3 | 95309 | 1.64041666667 | 13061 |
| 013345 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597236.6 | 511864.1 | 95311 | 1.64041666667 | 13345 |
| 012306 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597235.8 | 511864.9 | 95313 | 1.64041666667 | 12306 |
| 012586 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:26pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597235.7 | 511864.9 | 95315 | 1.64041666667 | 12586 |
| 012326 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:27pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597235.2 | 511865.0 | 95317 | 1.64041666667 | 12326 |
| 013611 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:28pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597234.9 | 511865.0 | 95319 | 1.64041666667 | 13611 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011923 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:29pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597234.8 | 511865.1 | 95321 | 1.64041666667 | 11923 |
| 012190 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:30pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597235.1 | 511865.6 | 95323 | 1.64041666667 | 12190 |
| 012467 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:31pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597236.3 | 511867.0 | 95325 | 1.64041666667 | 12467 |
| 012896 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:32pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597236.6 | 511868.8 | 95327 | 1.64041666667 | 12896 |
| 012164 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:33pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597237.0 | 511870.7 | 95329 | 1.64041666667 | 12164 |
| 012971 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:34pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597236.5 | 511872.1 | 95331 | 1.64041666667 | 12971 |
| 012062 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:35pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597236.1 | 511872.9 | 95333 | 1.64041666667 | 12062 |
| 013275 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597234.7 | 511872.7 | 95335 | 1.64041666667 | 13275 |
| 014388 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597232.9 | 511872.1 | 95337 | 1.64041666667 | 14388 |
| 013917 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:38pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597230.6 | 511871.4 | 95339 | 1.64041666667 | 13917 |
| 012629 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:39pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597228.1 | 511870.4 | 95341 | 1.64041666667 | 12629 |
| 011587 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:40pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597225.2 | 511869.8 | 95343 | 1.64041666667 | 11587 |
| 013726 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:41pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597223.1 | 511869.1 | 95345 | 1.64041666667 | 13726 |
| 013661 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:42pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597219.9 | 511868.5 | 95347 | 1.64041666667 | 13661 |
| 013225 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:43pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597217.9 | 511867.6 | 95349 | 1.64041666667 | 13225 |
| 014226 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:44pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597215.2 | 511867.3 | 95351 | 1.64041666667 | 14226 |
| 014146 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:45pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597212.8 | 511866.7 | 95353 | 1.64041666667 | 14146 |
| 014186 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:46pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597209.9 | 511866.4 | 95355 | 1.64041666667 | 14186 |
| 014046 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:47pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597207.7 | 511865.8 | 95357 | 1.64041666667 | 14046 |
| 012961 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:48pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597204.8 | 511865.0 | 95359 | 1.64041666667 | 12961 |
| 012690 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597202.6 | 511864.4 | 95361 | 1.64041666667 | 12690 |
| 012892 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597199.6 | 511863.2 | 95363 | 1.64041666667 | 12892 |
| 013153 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597197.3 | 511862.8 | 95365 | 1.64041666667 | 13153 |
| 013428 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:52pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597195.0 | 511861.6 | 95367 | 1.64041666667 | 13428 |
| 013677 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:53pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597192.5 | 511861.0 | 95369 | 1.64041666667 | 13677 |
| 014669 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:54pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597190.0 | 511860.4 | 95371 | 1.64041666667 | 14669 |
| 014587 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:55pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597188.0 | 511860.0 | 95373 | 1.64041666667 | 14587 |
| 014476 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:56pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597185.9 | 511859.1 | 95375 | 1.64041666667 | 14476 |
| 012439 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:57pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597183.9 | 511858.6 | 95377 | 1.64041666667 | 12439 |
| 013069 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:58pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597183.8 | 511858.7 | 95379 | 1.64041666667 | 13069 |
| 015867 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:59pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597183.9 | 511859.0 | 95381 | 1.64041666667 | 15867 |
| 013837 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:00pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597184.2 | 511859.4 | 95383 | 1.64041666667 | 13837 |
| 014229 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597184.6 | 511858.4 | 95385 | 1.64041666667 | 14229 |
| 013577 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597185.4 | 511855.0 | 95387 | 1.64041666667 | 13577 |
| 014464 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:03pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597185.8 | 511852.8 | 95389 | 1.64041666667 | 14464 |
| 013516 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:04pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597185.7 | 511854.7 | 95391 | 1.64041666667 | 13516 |
| 013489 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597185.8 | 511855.8 | 95393 | 1.64041666667 | 13489 |
| 014112 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597185.8 | 511857.4 | 95395 | 1.64041666667 | 14112 |
| 014328 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:07pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597184.6 | 511859.0 | 95397 | 1.64041666667 | 14328 |
| 012582 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:08pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597182.1 | 511858.6 | 95399 | 1.64041666667 | 12582 |
| 013075 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:09pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597180.1 | 511859.0 | 95401 | 1.64041666667 | 13075 |
| 012899 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:10pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597178.0 | 511858.6 | 95403 | 1.64041666667 | 12899 |
| 012614 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:11pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597175.9 | 511858.3 | 95405 | 1.64041666667 | 12614 |
| 012723 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:12pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597173.4 | 511857.1 | 95407 | 1.64041666667 | 12723 |
| 013440 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:13pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597170.9 | 511856.5 | 95409 | 1.64041666667 | 13440 |
| 012510 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:14pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597167.9 | 511856.2 | 95411 | 1.64041666667 | 12510 |
| 011167 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:15pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597165.6 | 511855.7 | 95413 | 1.64041666667 | 11167 |
| 012002 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:16pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597162.8 | 511855.4 | 95415 | 1.64041666667 | 12002 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012120 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597160.5 | 511854.8 | 95417 | 1.64041666667 | 12120 |
| 011040 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597157.8 | 511854.4 | 95419 | 1.64041666667 | 11040 |
| 009810 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597155.7 | 511853.9 | 95421 | 1.64041666667 | 9810 |
| 010822 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:20pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597153.2 | 511853.6 | 95423 | 1.64041666667 | 10822 |
| 008825 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597151.5 | 511851.6 | 95425 | 1.64041666667 | 8825 |
| 009166 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597148.9 | 511850.2 | 95427 | 1.64041666667 | 9166 |
| 009611 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597146.5 | 511849.3 | 95429 | 1.64041666667 | 9611 |
| 010593 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597143.7 | 511849.0 | 95431 | 1.64041666667 | 10593 |
| 013028 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597141.2 | 511848.6 | 95433 | 1.64041666667 | 13028 |
| 009737 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597138.6 | 511848.3 | 95435 | 1.64041666667 | 9737 |
| 010174 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597136.2 | 511848.5 | 95437 | 1.64041666667 | 10174 |
| 009803 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597133.0 | 511847.9 | 95439 | 1.64041666667 | 9803 |
| 010941 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597130.3 | 511847.5 | 95441 | 1.64041666667 | 10941 |
| 010325 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597127.8 | 511846.3 | 95443 | 1.64041666667 | 10325 |
| 010351 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597125.8 | 511845.7 | 95445 | 1.64041666667 | 10351 |
| 009817 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597124.1 | 511844.0 | 95447 | 1.64041666667 | 9817 |
| 009444 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597122.2 | 511843.1 | 95449 | 1.64041666667 | 9444 |
| 010551 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597120.3 | 511842.0 | 95451 | 1.64041666667 | 10551 |
| 011397 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597118.1 | 511841.5 | 95453 | 1.64041666667 | 11397 |
| 009989 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597115.6 | 511841.0 | 95455 | 1.64041666667 | 9989 |
| 011557 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597113.2 | 511840.4 | 95457 | 1.64041666667 | 11557 |
| 011709 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597110.8 | 511839.6 | 95459 | 1.64041666667 | 11709 |
| 010967 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597108.8 | 511838.6 | 95461 | 1.64041666667 | 10967 |
| 009881 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597106.4 | 511837.8 | 95463 | 1.64041666667 | 9881 |
| 010750 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:41pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597105.0 | 511836.8 | 95465 | 1.64041666667 | 10750 |
| 010007 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597105.9 | 511837.2 | 95467 | 1.64041666667 | 10007 |
| 010421 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597105.9 | 511837.3 | 95469 | 1.64041666667 | 10421 |
| 010015 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597104.0 | 511836.7 | 95471 | 1.64041666667 | 10015 |
| 009254 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597101.9 | 511836.0 | 95473 | 1.64041666667 | 9254 |
| 009873 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597099.5 | 511834.6 | 95475 | 1.64041666667 | 9873 |
| 010898 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597098.0 | 511833.6 | 95477 | 1.64041666667 | 10898 |
| 011634 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597097.9 | 511831.1 | 95479 | 1.64041666667 | 11634 |
| 011158 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597098.4 | 511829.5 | 95481 | 1.64041666667 | 11158 |
| 011639 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597099.7 | 511828.1 | 95483 | 1.64041666667 | 11639 |
| 012570 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597100.1 | 511827.3 | 95485 | 1.64041666667 | 12570 |
| 011182 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597099.9 | 511827.5 | 95487 | 1.64041666667 | 11182 |
| 012005 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597100.7 | 511827.1 | 95489 | 1.64041666667 | 12005 |
| 011761 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597102.6 | 511826.6 | 95491 | 1.64041666667 | 11761 |
| 011370 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597104.7 | 511827.1 | 95493 | 1.64041666667 | 11370 |
| 010102 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597107.3 | 511827.8 | 95495 | 1.64041666667 | 10102 |
| 011435 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597109.1 | 511828.8 | 95497 | 1.64041666667 | 11435 |
| 010359 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597111.2 | 511830.6 | 95499 | 1.64041666667 | 10359 |
| 010149 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:59pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597113.2 | 511831.6 | 95501 | 1.64041666667 | 10149 |
| 012077 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597115.7 | 511832.7 | 95503 | 1.64041666667 | 12077 |
| 012829 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597118.0 | 511833.0 | 95505 | 1.64041666667 | 12829 |
| 011247 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597120.1 | 511834.0 | 95507 | 1.64041666667 | 11247 |
| 010132 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597121.8 | 511834.9 | 95509 | 1.64041666667 | 10132 |
| 011113 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597123.2 | 511835.7 | 95511 | 1.64041666667 | 11113 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011358 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597125.3 | 511835.1 | 95513 | 1.64041666667 | 11358 |
| 010309 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597127.5 | 511834.6 | 95515 | 1.64041666667 | 10309 |
| 009627 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597129.6 | 511834.1 | 95517 | 1.64041666667 | 9627 |
| 009847 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597131.9 | 511834.6 | 95519 | 1.64041666667 | 9847 |
| 009601 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597133.7 | 511835.1 | 95521 | 1.64041666667 | 9601 |
| 010890 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597135.7 | 511835.6 | 95523 | 1.64041666667 | 10890 |
| 009862 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597137.0 | 511837.5 | 95525 | 1.64041666667 | 9862 |
| 009905 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597138.9 | 511839.3 | 95527 | 1.64041666667 | 9905 |
| 011296 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597140.2 | 511841.1 | 95529 | 1.64041666667 | 11296 |
| 010114 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597142.6 | 511842.2 | 95531 | 1.64041666667 | 10114 |
| 011438 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597144.9 | 511842.5 | 95533 | 1.64041666667 | 11438 |
| 010989 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597147.5 | 511842.8 | 95535 | 1.64041666667 | 10989 |
| 009497 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597149.4 | 511843.1 | 95537 | 1.64041666667 | 9497 |
| 009484 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597151.6 | 511843.2 | 95539 | 1.64041666667 | 9484 |
| 009541 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597153.9 | 511843.2 | 95541 | 1.64041666667 | 9541 |
| 010725 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:20pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597155.6 | 511844.1 | 95543 | 1.64041666667 | 10725 |
| 010691 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597156.9 | 511845.0 | 95545 | 1.64041666667 | 10691 |
| 010803 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:22pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597156.9 | 511845.8 | 95547 | 1.64041666667 | 10803 |
| 011190 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:23pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597156.7 | 511845.6 | 95549 | 1.64041666667 | 11190 |
| 011677 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597157.1 | 511845.9 | 95551 | 1.64041666667 | 11677 |
| 011289 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597158.4 | 511846.0 | 95553 | 1.64041666667 | 11289 |
| 012392 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597160.1 | 511846.4 | 95555 | 1.64041666667 | 12392 |
| 012908 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597162.3 | 511846.9 | 95557 | 1.64041666667 | 12908 |
| 011657 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:28pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597164.2 | 511847.7 | 95559 | 1.64041666667 | 11657 |
| 011704 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:29pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597165.5 | 511848.4 | 95561 | 1.64041666667 | 11704 |
| 011686 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:30pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597166.8 | 511849.2 | 95563 | 1.64041666667 | 11686 |
| 011021 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:31pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597168.8 | 511849.4 | 95565 | 1.64041666667 | 11021 |
| 012685 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597171.1 | 511850.0 | 95567 | 1.64041666667 | 12685 |
| 010671 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597173.5 | 511849.6 | 95569 | 1.64041666667 | 10671 |
| 011547 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597175.7 | 511849.8 | 95571 | 1.64041666667 | 11547 |
| 012967 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597177.6 | 511849.6 | 95573 | 1.64041666667 | 12967 |
| 010861 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:36pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597179.2 | 511850.4 | 95575 | 1.64041666667 | 10861 |
| 011415 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:37pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597180.9 | 511850.9 | 95577 | 1.64041666667 | 11415 |
| 013503 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:38pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597182.4 | 511852.1 | 95579 | 1.64041666667 | 13503 |
| 011446 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:39pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597184.2 | 511852.6 | 95581 | 1.64041666667 | 11446 |
| 011591 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:40pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597185.0 | 511852.6 | 95583 | 1.64041666667 | 11591 |
| 010518 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:41pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597183.7 | 511852.3 | 95585 | 1.64041666667 | 10518 |
| 011239 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:42pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597183.3 | 511852.2 | 95587 | 1.64041666667 | 11239 |
| 011239 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:43pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597183.3 | 511852.3 | 95589 | 1.64041666667 | 11239 |
| 010730 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:44pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597183.4 | 511852.3 | 95591 | 1.64041666667 | 10730 |
| 013452 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:45pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597183.3 | 511852.5 | 95593 | 1.64041666667 | 13452 |
| 013593 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:46pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597183.8 | 511852.9 | 95595 | 1.64041666667 | 13593 |
| 011768 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:47pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597185.2 | 511853.1 | 95597 | 1.64041666667 | 11768 |
| 012242 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:48pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597187.2 | 511854.4 | 95599 | 1.64041666667 | 12242 |
| 012390 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:49pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597189.5 | 511855.1 | 95601 | 1.64041666667 | 12390 |
| 012727 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:50pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597191.4 | 511856.0 | 95603 | 1.64041666667 | 12727 |
| 012362 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:51pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597193.6 | 511856.3 | 95605 | 1.64041666667 | 12362 |
| 013170 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:52pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597196.0 | 511857.4 | 95607 | 1.64041666667 | 13170 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012472 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597198.5 | 511858.2 | 95609 | 1.64041666667 | 12472 |
| 011518 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:54pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597200.9 | 511858.6 | 95611 | 1.64041666667 | 11518 |
| 011189 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597202.8 | 511858.7 | 95613 | 1.64041666667 | 11189 |
| 011557 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:56pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597205.0 | 511858.8 | 95615 | 1.64041666667 | 11557 |
| 011859 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:57pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597207.0 | 511858.5 | 95617 | 1.64041666667 | 11859 |
| 011094 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:58pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597209.2 | 511857.5 | 95619 | 1.64041666667 | 11094 |
| 011383 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:59pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597210.7 | 511858.0 | 95621 | 1.64041666667 | 11383 |
| 010406 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:00pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597212.8 | 511858.0 | 95623 | 1.64041666667 | 10406 |
| 011961 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:01pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597214.6 | 511859.1 | 95625 | 1.64041666667 | 11961 |
| 012230 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:02pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597216.8 | 511859.7 | 95627 | 1.64041666667 | 12230 |
| 011187 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:03pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597218.5 | 511861.0 | 95629 | 1.64041666667 | 11187 |
| 011137 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:04pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597220.3 | 511862.5 | 95631 | 1.64041666667 | 11137 |
| 011034 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:05pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597221.0 | 511862.8 | 95633 | 1.64041666667 | 11034 |
| 013168 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:06pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597220.3 | 511862.7 | 95635 | 1.64041666667 | 13168 |
| 013432 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:07pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597219.8 | 511860.6 | 95637 | 1.64041666667 | 13432 |
| 011488 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:08pm | Sensor | 1797-S0055-G-TJV.cor | 6859.5 | 1597219.6 | 511858.7 | 95639 | 1.64041666667 | 11488 |
| 011632 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:09pm | Sensor | 1797-S0055-G-TJV.cor | 6859.6 | 1597219.8 | 511859.4 | 95641 | 1.64041666667 | 11632 |
| 011998 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:10pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597220.8 | 511860.5 | 95643 | 1.64041666667 | 11998 |
| 012989 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:11pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597222.3 | 511861.4 | 95645 | 1.64041666667 | 12989 |
| 011767 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:12pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597224.7 | 511862.4 | 95647 | 1.64041666667 | 11767 |
| 012151 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:13pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597227.2 | 511863.2 | 95649 | 1.64041666667 | 12151 |
| 011347 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:14pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597229.6 | 511863.5 | 95651 | 1.64041666667 | 11347 |
| 010907 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:15pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597231.8 | 511864.0 | 95653 | 1.64041666667 | 10907 |
| 013316 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:16pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597234.1 | 511863.9 | 95655 | 1.64041666667 | 13316 |
| 015869 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:17pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597235.4 | 511864.6 | 95657 | 1.64041666667 | 15869 |
| 014407 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:18pm | Sensor | 1797-S0055-G-TJV.cor | 6858.6 | 1597236.3 | 511864.5 | 95659 | 1.64041666667 | 14407 |
| 013891 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:19pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597234.8 | 511863.9 | 95661 | 1.64041666667 | 13891 |
| 011692 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:20pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597234.5 | 511863.9 | 95663 | 1.64041666667 | 11692 |
| 013183 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:21pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597234.2 | 511864.3 | 95665 | 1.64041666667 | 13183 |
| 012776 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:22pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597233.8 | 511865.6 | 95667 | 1.64041666667 | 12776 |
| 013364 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:23pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597232.0 | 511866.6 | 95669 | 1.64041666667 | 13364 |
| 012581 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:24pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597229.6 | 511867.6 | 95671 | 1.64041666667 | 12581 |
| 012355 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:25pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597227.1 | 511867.7 | 95673 | 1.64041666667 | 12355 |
| 013198 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597224.3 | 511868.0 | 95675 | 1.64041666667 | 13198 |
| 012059 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:27pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597221.6 | 511867.9 | 95677 | 1.64041666667 | 12059 |
| 011925 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:28pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597219.0 | 511867.6 | 95679 | 1.64041666667 | 11925 |
| 014981 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:29pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597216.6 | 511867.3 | 95681 | 1.64041666667 | 14981 |
| 013525 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:30pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597214.1 | 511866.6 | 95683 | 1.64041666667 | 13525 |
| 013131 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:31pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597211.3 | 511866.4 | 95685 | 1.64041666667 | 13131 |
| 012642 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:32pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597208.4 | 511866.2 | 95687 | 1.64041666667 | 12642 |
| 011350 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:33pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597206.1 | 511866.0 | 95689 | 1.64041666667 | 11350 |
| 013937 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:34pm | Sensor | 1797-S0055-G-TJV.cor | 6859.1 | 1597203.7 | 511866.3 | 95691 | 1.64041666667 | 13937 |
| 013234 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597201.5 | 511865.8 | 95693 | 1.64041666667 | 13234 |
| 013598 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597198.7 | 511865.7 | 95695 | 1.64041666667 | 13598 |
| 013989 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.8 | 1597195.9 | 511865.8 | 95697 | 1.64041666667 | 13989 |
| 012887 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:38pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597193.2 | 511865.7 | 95699 | 1.64041666667 | 12887 |
| 014321 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:39pm | Sensor | 1797-S0055-G-TJV.cor | 6859.0 | 1597190.8 | 511866.1 | 95701 | 1.64041666667 | 14321 |
| 013420 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:40pm | Sensor | 1797-S0055-G-TJV.cor | 6858.9 | 1597187.4 | 511866.1 | 95703 | 1.64041666667 | 13420 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013525 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:41pm | Sensor | 1797-S0055-G-TJV.cor | 6859.2 | 1597185.2 | 511866.2 | 95705 | 1.64041666667 | 13525 |
| 012891 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:42pm | Sensor | 1797-S0055-G-TJV.cor | 6859.4 | 1597183.3 | 511867.1 | 95707 | 1.64041666667 | 12891 |
| 011802 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:43pm | Sensor | 1797-S0055-G-TJV.cor | 6859.3 | 1597181.5 | 511867.1 | 95709 | 1.64041666667 | 11802 |
| 013420 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.7 | 1597179.3 | 511867.4 | 95711 | 1.64041666667 | 13420 |
| 014425 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.5 | 1597176.7 | 511867.6 | 95713 | 1.64041666667 | 14425 |
| 013176 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.4 | 1597173.9 | 511866.4 | 95715 | 1.64041666667 | 13176 |
| 011994 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:47pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597171.6 | 511865.5 | 95717 | 1.64041666667 | 11994 |
| 011608 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:48pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597169.0 | 511864.8 | 95719 | 1.64041666667 | 11608 |
| 013972 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:49pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597166.5 | 511864.3 | 95721 | 1.64041666667 | 13972 |
| 011833 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:50pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597163.7 | 511865.1 | 95723 | 1.64041666667 | 11833 |
| 013728 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:51pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597161.7 | 511866.5 | 95725 | 1.64041666667 | 13728 |
| 011712 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:52pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597159.3 | 511867.7 | 95727 | 1.64041666667 | 11712 |
| 012018 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597157.0 | 511869.2 | 95729 | 1.64041666667 | 12018 |
| 011434 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597154.4 | 511870.7 | 95731 | 1.64041666667 | 11434 |
| 013898 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597152.0 | 511871.4 | 95733 | 1.64041666667 | 13898 |
| 012684 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597149.3 | 511872.8 | 95735 | 1.64041666667 | 12684 |
| 012501 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:57pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597146.9 | 511874.3 | 95737 | 1.64041666667 | 12501 |
| 012995 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:58pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597144.5 | 511876.0 | 95739 | 1.64041666667 | 12995 |
| 017498 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:59pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597142.4 | 511877.8 | 95741 | 1.64041666667 | 17498 |
| 016374 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:00pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597139.8 | 511879.1 | 95743 | 1.64041666667 | 16374 |
| 015643 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:01pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597137.7 | 511879.8 | 95745 | 1.64041666667 | 15643 |
| 013601 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:02pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597135.3 | 511880.3 | 95747 | 1.64041666667 | 13601 |
| 013150 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597132.9 | 511880.2 | 95749 | 1.64041666667 | 13150 |
| 011267 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597130.2 | 511881.0 | 95751 | 1.64041666667 | 11267 |
| 009806 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597128.7 | 511882.3 | 95753 | 1.64041666667 | 9806 |
| 011121 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597127.3 | 511883.4 | 95755 | 1.64041666667 | 11121 |
| 009740 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597127.5 | 511883.4 | 95757 | 1.64041666667 | 9740 |
| 009815 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597127.3 | 511883.3 | 95759 | 1.64041666667 | 9815 |
| 010103 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597127.2 | 511883.3 | 95761 | 1.64041666667 | 10103 |
| 010356 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597127.3 | 511883.4 | 95763 | 1.64041666667 | 10356 |
| 009609 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597128.2 | 511883.9 | 95765 | 1.64041666667 | 9609 |
| 010412 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597130.4 | 511884.7 | 95767 | 1.64041666667 | 10412 |
| 010073 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597132.9 | 511885.6 | 95769 | 1.64041666667 | 10073 |
| 009898 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597135.7 | 511886.5 | 95771 | 1.64041666667 | 9898 |
| 009014 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597138.0 | 511886.8 | 95773 | 1.64041666667 | 9014 |
| 011043 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:16pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597140.7 | 511887.5 | 95775 | 1.64041666667 | 11043 |
| 009450 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597143.1 | 511887.7 | 95777 | 1.64041666667 | 9450 |
| 008962 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597145.4 | 511886.7 | 95779 | 1.64041666667 | 8962 |
| 009500 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597147.5 | 511886.3 | 95781 | 1.64041666667 | 9500 |
| 011555 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597150.0 | 511885.0 | 95783 | 1.64041666667 | 11555 |
| 011828 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597152.3 | 511885.1 | 95785 | 1.64041666667 | 11828 |
| 012497 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597155.0 | 511884.9 | 95787 | 1.64041666667 | 12497 |
| 012784 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597157.3 | 511884.0 | 95789 | 1.64041666667 | 12784 |
| 013246 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597159.9 | 511883.9 | 95791 | 1.64041666667 | 13246 |
| 014543 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597161.9 | 511884.8 | 95793 | 1.64041666667 | 14543 |
| 015273 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:26pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597163.8 | 511886.1 | 95795 | 1.64041666667 | 15273 |
| 011888 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597163.7 | 511888.1 | 95797 | 1.64041666667 | 11888 |
| 011072 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597163.9 | 511890.9 | 95799 | 1.64041666667 | 11072 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010868 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597163.7 | 511893.7 | 95801 | 1.64041666667 | 10868 |
| 011777 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597163.2 | 511896.9 | 95803 | 1.64041666667 | 11777 |
| 011134 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597163.2 | 511899.9 | 95805 | 1.64041666667 | 11134 |
| 012893 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:32pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597163.2 | 511902.9 | 95807 | 1.64041666667 | 12893 |
| 011743 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:33pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597162.9 | 511905.5 | 95809 | 1.64041666667 | 11743 |
| 010526 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:34pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597162.6 | 511908.9 | 95811 | 1.64041666667 | 10526 |
| 010731 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:35pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597162.2 | 511911.4 | 95813 | 1.64041666667 | 10731 |
| 010572 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:36pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597160.9 | 511914.8 | 95815 | 1.64041666667 | 10572 |
| 011733 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:37pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597160.0 | 511917.3 | 95817 | 1.64041666667 | 11733 |
| 011543 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597158.3 | 511919.9 | 95819 | 1.64041666667 | 11543 |
| 012005 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597156.0 | 511920.3 | 95821 | 1.64041666667 | 12005 |
| 012781 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597153.1 | 511919.1 | 95823 | 1.64041666667 | 12781 |
| 013455 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597151.2 | 511917.2 | 95825 | 1.64041666667 | 13455 |
| 012543 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:42pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597149.7 | 511914.5 | 95827 | 1.64041666667 | 12543 |
| 011326 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:43pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597148.9 | 511912.0 | 95829 | 1.64041666667 | 11326 |
| 011501 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:44pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597148.1 | 511909.0 | 95831 | 1.64041666667 | 11501 |
| 010285 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:45pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597147.5 | 511906.4 | 95833 | 1.64041666667 | 10285 |
| 009801 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:46pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597146.3 | 511903.0 | 95835 | 1.64041666667 | 9801 |
| 009710 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597145.5 | 511900.6 | 95837 | 1.64041666667 | 9710 |
| 008967 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597144.5 | 511897.7 | 95839 | 1.64041666667 | 8967 |
| 008683 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597143.5 | 511895.5 | 95841 | 1.64041666667 | 8683 |
| 010385 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597142.5 | 511893.6 | 95843 | 1.64041666667 | 10385 |
| 009316 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:51pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597142.3 | 511892.1 | 95845 | 1.64041666667 | 9316 |
| 009109 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:52pm | Sensor | 1797-S0055-G-TJV.cor | 6857.2 | 1597141.4 | 511889.7 | 95847 | 1.64041666667 | 9109 |
| 010197 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:53pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597140.4 | 511887.3 | 95849 | 1.64041666667 | 10197 |
| 010109 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:54pm | Sensor | 1797-S0055-G-TJV.cor | 6857.1 | 1597138.8 | 511885.1 | 95851 | 1.64041666667 | 10109 |
| 010897 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:55pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597137.0 | 511883.7 | 95853 | 1.64041666667 | 10897 |
| 011004 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:56pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597134.7 | 511883.3 | 95855 | 1.64041666667 | 11004 |
| 011001 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:57pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597132.3 | 511884.8 | 95857 | 1.64041666667 | 11001 |
| 010250 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:58pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597130.2 | 511887.0 | 95859 | 1.64041666667 | 10250 |
| 010212 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:59pm | Sensor | 1797-S0055-G-TJV.cor | 6856.9 | 1597127.7 | 511887.9 | 95861 | 1.64041666667 | 10212 |
| 009753 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:00pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597124.3 | 511889.0 | 95863 | 1.64041666667 | 9753 |
| 008318 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:01pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597121.6 | 511889.8 | 95865 | 1.64041666667 | 8318 |
| 009549 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:02pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597118.5 | 511889.6 | 95867 | 1.64041666667 | 9549 |
| 009767 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:03pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597115.6 | 511889.8 | 95869 | 1.64041666667 | 9767 |
| 010271 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:04pm | Sensor | 1797-S0055-G-TJV.cor | 6856.7 | 1597112.5 | 511890.7 | 95871 | 1.64041666667 | 10271 |
| 010668 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:05pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597110.1 | 511891.9 | 95873 | 1.64041666667 | 10668 |
| 009567 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:06pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597108.7 | 511894.4 | 95875 | 1.64041666667 | 9567 |
| 008991 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:07pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597109.5 | 511896.9 | 95877 | 1.64041666667 | 8991 |
| 009988 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:08pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597111.3 | 511899.5 | 95879 | 1.64041666667 | 9988 |
| 009547 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:09pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597113.1 | 511901.2 | 95881 | 1.64041666667 | 9547 |
| 010816 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:10pm | Sensor | 1797-S0055-G-TJV.cor | 6856.5 | 1597116.0 | 511902.1 | 95883 | 1.64041666667 | 10816 |
| 010144 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:11pm | Sensor | 1797-S0055-G-TJV.cor | 6856.4 | 1597118.5 | 511903.0 | 95885 | 1.64041666667 | 10144 |
| 010186 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:12pm | Sensor | 1797-S0055-G-TJV.cor | 6856.6 | 1597121.5 | 511903.9 | 95887 | 1.64041666667 | 10186 |
| 010436 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:13pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597123.5 | 511904.7 | 95889 | 1.64041666667 | 10436 |
| 010379 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:14pm | Sensor | 1797-S0055-G-TJV.cor | 6856.8 | 1597125.5 | 511906.9 | 95891 | 1.64041666667 | 10379 |
| 010065 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.0 | 1597126.8 | 511909.0 | 95893 | 1.64041666667 | 10065 |
| 008486 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.3 | 1597128.0 | 511911.6 | 95895 | 1.64041666667 | 8486 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010371 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597128.5 | 511914.1 | 95897 | 1.64041666667 | 10371 |
| 011472 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.4 | 1597131.0 | 511916.4 | 95899 | 1.64041666667 | 11472 |
| 011808 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597133.1 | 511917.9 | 95901 | 1.64041666667 | 11808 |
| 012192 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597135.2 | 511919.5 | 95903 | 1.64041666667 | 12192 |
| 011268 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:21pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597137.4 | 511920.5 | 95905 | 1.64041666667 | 11268 |
| 012837 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:22pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597139.8 | 511922.2 | 95907 | 1.64041666667 | 12837 |
| 013349 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:23pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597142.5 | 511923.1 | 95909 | 1.64041666667 | 13349 |
| 012067 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:24pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597145.3 | 511924.4 | 95911 | 1.64041666667 | 12067 |
| 011446 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:25pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.9 | 511925.9 | 95913 | 1.64041666667 | 11446 |
| 010931 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:26pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597149.2 | 511927.9 | 95915 | 1.64041666667 | 10931 |
| 010803 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:27pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597150.6 | 511930.2 | 95917 | 1.64041666667 | 10803 |
| 012810 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:28pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597152.0 | 511932.9 | 95919 | 1.64041666667 | 12810 |
| 012142 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:29pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597153.1 | 511935.1 | 95921 | 1.64041666667 | 12142 |
| 011315 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:30pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597154.1 | 511937.8 | 95923 | 1.64041666667 | 11315 |
| 013299 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:31pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597155.8 | 511939.7 | 95925 | 1.64041666667 | 13299 |
| 015414 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:32pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597157.9 | 511941.8 | 95927 | 1.64041666667 | 15414 |
| 015973 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:33pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597159.7 | 511943.5 | 95929 | 1.64041666667 | 15973 |
| 017823 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:34pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597162.3 | 511945.0 | 95931 | 1.64041666667 | 17823 |
| 018555 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:35pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597164.3 | 511946.6 | 95933 | 1.64041666667 | 18555 |
| 018048 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:36pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597166.2 | 511948.8 | 95935 | 1.64041666667 | 18048 |
| 017352 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:37pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597167.7 | 511950.7 | 95937 | 1.64041666667 | 17352 |
| 016818 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:38pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597168.3 | 511953.1 | 95939 | 1.64041666667 | 16818 |
| 016174 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:39pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597168.1 | 511954.5 | 95941 | 1.64041666667 | 16174 |
| 014993 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:40pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597167.1 | 511956.1 | 95943 | 1.64041666667 | 14993 |
| 014068 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:41pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597165.6 | 511956.3 | 95945 | 1.64041666667 | 14068 |
| 015817 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:42pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597163.2 | 511955.7 | 95947 | 1.64041666667 | 15817 |
| 016734 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:43pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597161.1 | 511954.7 | 95949 | 1.64041666667 | 16734 |
| 017473 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:44pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597158.1 | 511954.2 | 95951 | 1.64041666667 | 17473 |
| 016998 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:45pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597155.5 | 511953.7 | 95953 | 1.64041666667 | 16998 |
| 017449 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:46pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597152.7 | 511952.7 | 95955 | 1.64041666667 | 17449 |
| 014922 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:47pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597150.4 | 511952.1 | 95957 | 1.64041666667 | 14922 |
| 012160 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:48pm | Sensor | 1797-S0055-G-TJV.cor | 6857.5 | 1597148.4 | 511950.7 | 95959 | 1.64041666667 | 12160 |
| 013000 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:49pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597148.2 | 511949.0 | 95961 | 1.64041666667 | 13000 |
| 013090 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:50pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597149.7 | 511947.3 | 95963 | 1.64041666667 | 13090 |
| 015272 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:51pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597151.9 | 511947.7 | 95965 | 1.64041666667 | 15272 |
| 016238 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:52pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597154.7 | 511948.2 | 95967 | 1.64041666667 | 16238 |
| 017619 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:53pm | Sensor | 1797-S0055-G-TJV.cor | 6858.3 | 1597157.2 | 511948.1 | 95969 | 1.64041666667 | 17619 |
| 018115 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:54pm | Sensor | 1797-S0055-G-TJV.cor | 6858.2 | 1597160.0 | 511948.4 | 95971 | 1.64041666667 | 18115 |
| 017788 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:55pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597162.7 | 511948.4 | 95973 | 1.64041666667 | 17788 |
| 019447 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:56pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597164.8 | 511947.0 | 95975 | 1.64041666667 | 19447 |
| 018123 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:57pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597165.2 | 511945.0 | 95977 | 1.64041666667 | 18123 |
| 015855 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:58pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597162.5 | 511943.3 | 95979 | 1.64041666667 | 15855 |
| 014883 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:59pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597160.3 | 511942.7 | 95981 | 1.64041666667 | 14883 |
| 015481 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:00pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597157.5 | 511942.0 | 95983 | 1.64041666667 | 15481 |
| 015390 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:01pm | Sensor | 1797-S0055-G-TJV.cor | 6858.1 | 1597155.1 | 511942.0 | 95985 | 1.64041666667 | 15390 |
| 013387 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:02pm | Sensor | 1797-S0055-G-TJV.cor | 6858.0 | 1597152.2 | 511941.6 | 95987 | 1.64041666667 | 13387 |
| 012947 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:03pm | Sensor | 1797-S0055-G-TJV.cor | 6857.9 | 1597150.3 | 511940.4 | 95989 | 1.64041666667 | 12947 |
| 013046 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:04pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597148.4 | 511938.8 | 95991 | 1.64041666667 | 13046 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012141 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:05pm | Sensor | 1797-S0055-G-TJV.cor | 6857.8 | 1597147.4 | 511937.2 | 95993 | 1.64041666667 | 12141 |
| 012305 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:06pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597147.2 | 511937.5 | 95995 | 1.64041666667 | 12305 |
| 011566 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:07pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597147.2 | 511937.4 | 95997 | 1.64041666667 | 11566 |
| 010841 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:08pm | Sensor | 1797-S0055-G-TJV.cor | 6857.7 | 1597147.3 | 511937.4 | 95999 | 1.64041666667 | 10841 |
| 012250 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:09pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597147.0 | 511937.6 | 96001 | 1.64041666667 | 12250 |
| 011192 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:10pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.7 | 511936.9 | 96003 | 1.64041666667 | 11192 |
| 011078 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:11pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.8 | 511937.0 | 96005 | 1.64041666667 | 11078 |
| 011859 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:12pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.9 | 511937.1 | 96007 | 1.64041666667 | 11859 |
| 012085 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:13pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.9 | 511937.2 | 96009 | 1.64041666667 | 12085 |
| 012921 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:14pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.9 | 511937.2 | 96011 | 1.64041666667 | 12921 |
| 011660 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:15pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.8 | 511937.2 | 96013 | 1.64041666667 | 11660 |
| 013235 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:16pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.7 | 511937.3 | 96015 | 1.64041666667 | 13235 |
| 013028 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:17pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.8 | 511937.3 | 96017 | 1.64041666667 | 13028 |
| 012437 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:18pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.7 | 511937.2 | 96019 | 1.64041666667 | 12437 |
| 011959 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:19pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.7 | 511937.3 | 96021 | 1.64041666667 | 11959 |
| 011689 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:20pm | Sensor | 1797-S0055-G-TJV.cor | 6857.6 | 1597146.7 | 511937.4 | 96024 | 1.64041666667 | 11689 |
| 009198 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:36pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596455.0 | 513535.8 | 88054 | 1.64041666667 | 9198 |
| 010191 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:37pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596455.0 | 513535.8 | 88055 | 1.64041666667 | 10191 |
| 010007 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:38pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596455.0 | 513535.7 | 88059 | 1.64041666667 | 10007 |
| 010826 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:39pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596455.3 | 513535.6 | 88061 | 1.64041666667 | 10826 |
| 010252 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:40pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596455.7 | 513535.3 | 88063 | 1.64041666667 | 10252 |
| 010387 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:41pm | Sensor | 1797-S0054-905-G-ACK | 6849.9 | 1596455.8 | 513535.2 | 88065 | 1.64041666667 | 10387 |
| 010635 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:42pm | Sensor | 1797-S0054-905-G-ACK | 6849.9 | 1596455.8 | 513535.1 | 88067 | 1.64041666667 | 10635 |
| 010422 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:43pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596455.8 | 513535.1 | 88069 | 1.64041666667 | 10422 |
| 009575 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:44pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596455.8 | 513535.2 | 88071 | 1.64041666667 | 9575 |
| 009736 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:45pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596455.8 | 513535.2 | 88073 | 1.64041666667 | 9736 |
| 010681 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:46pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.8 | 513535.2 | 88075 | 1.64041666667 | 10681 |
| 010373 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:46pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.8 | 513535.2 | 88076 | 1.64041666667 | 10373 |
| 011400 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:47pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.8 | 513535.1 | 88078 | 1.64041666667 | 11400 |
| 011175 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:48pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.8 | 513535.1 | 88080 | 1.64041666667 | 11175 |
| 011183 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:50pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.7 | 513535.1 | 88083 | 1.64041666667 | 11183 |
| 011255 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:50pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.7 | 513535.1 | 88084 | 1.64041666667 | 11255 |
| 010981 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:52pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.8 | 513535.1 | 88087 | 1.64041666667 | 10981 |
| 010557 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:52pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.8 | 513535.1 | 88088 | 1.64041666667 | 10557 |
| 010505 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:54pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596456.1 | 513535.5 | 88091 | 1.64041666667 | 10505 |
| 010019 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:54pm | Sensor | 1797-S0054-905-G-ACK | 6849.7 | 1596455.9 | 513536.9 | 88092 | 1.64041666667 | 10019 |
| 009356 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:56pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596457.1 | 513537.6 | 88095 | 1.64041666667 | 9356 |
| 009470 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:56pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596456.4 | 513539.0 | 88096 | 1.64041666667 | 9470 |
| 010547 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:58pm | Sensor | 1797-S0054-905-G-ACK | 6849.9 | 1596457.8 | 513539.9 | 88099 | 1.64041666667 | 10547 |
| 009832 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:58pm | Sensor | 1797-S0054-905-G-ACK | 6849.8 | 1596458.9 | 513540.2 | 88100 | 1.64041666667 | 9832 |
| 009618 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:00pm | Sensor | 1797-S0054-905-G-ACK | 6849.9 | 1596461.7 | 513540.0 | 88103 | 1.64041666667 | 9618 |
| 009445 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:00pm | Sensor | 1797-S0054-905-G-ACK | 6849.9 | 1596463.0 | 513539.1 | 88104 | 1.64041666667 | 9445 |
| 010165 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596465.0 | 513539.3 | 88107 | 1.64041666667 | 10165 |
| 010105 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596467.1 | 513539.5 | 88108 | 1.64041666667 | 10105 |
| 009802 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596469.3 | 513539.7 | 88111 | 1.64041666667 | 9802 |
| 009668 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596470.9 | 513540.2 | 88112 | 1.64041666667 | 9668 |
| 009871 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596472.9 | 513539.8 | 88115 | 1.64041666667 | 9871 |
| 009880 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596474.8 | 513539.4 | 88116 | 1.64041666667 | 9880 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010245 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596476.7 | 513540.2 | 88119 | 1.64041666667 | 10245 |
| 010585 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596478.9 | 513541.6 | 88121 | 1.64041666667 | 10585 |
| 011099 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596481.2 | 513542.3 | 88123 | 1.64041666667 | 11099 |
| 010001 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596482.8 | 513543.3 | 88124 | 1.64041666667 | 10001 |
| 009608 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596484.9 | 513544.8 | 88127 | 1.64041666667 | 9608 |
| 010519 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596486.7 | 513544.7 | 88129 | 1.64041666667 | 10519 |
| 010627 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596488.7 | 513545.2 | 88131 | 1.64041666667 | 10627 |
| 009967 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596490.5 | 513546.6 | 88132 | 1.64041666667 | 9967 |
| 010294 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596492.3 | 513547.9 | 88135 | 1.64041666667 | 10294 |
| 009750 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596493.5 | 513548.9 | 88136 | 1.64041666667 | 9750 |
| 009692 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596494.7 | 513551.1 | 88139 | 1.64041666667 | 9692 |
| 009682 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596496.4 | 513552.5 | 88140 | 1.64041666667 | 9682 |
| 010441 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596499.2 | 513553.6 | 88143 | 1.64041666667 | 10441 |
| 010088 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596501.5 | 513554.2 | 88145 | 1.64041666667 | 10088 |
| 011307 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596503.8 | 513555.4 | 88147 | 1.64041666667 | 11307 |
| 011310 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596505.7 | 513556.3 | 88148 | 1.64041666667 | 11310 |
| 011192 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596508.5 | 513557.6 | 88151 | 1.64041666667 | 11192 |
| 010330 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596510.7 | 513558.6 | 88153 | 1.64041666667 | 10330 |
| 010476 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596512.9 | 513560.3 | 88155 | 1.64041666667 | 10476 |
| 011315 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596514.5 | 513561.5 | 88156 | 1.64041666667 | 11315 |
| 010512 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596516.7 | 513562.6 | 88159 | 1.64041666667 | 10512 |
| 010780 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596518.8 | 513563.6 | 88160 | 1.64041666667 | 10780 |
| 010886 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:29pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596520.9 | 513565.0 | 88162 | 1.64041666667 | 10886 |
| 010623 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596523.2 | 513566.6 | 88164 | 1.64041666667 | 10623 |
| 009785 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596525.5 | 513568.0 | 88167 | 1.64041666667 | 9785 |
| 010424 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596527.7 | 513568.9 | 88168 | 1.64041666667 | 10424 |
| 009869 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:33pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596530.3 | 513569.9 | 88170 | 1.64041666667 | 9869 |
| 009736 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596532.3 | 513570.9 | 88172 | 1.64041666667 | 9736 |
| 009819 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596534.7 | 513572.5 | 88175 | 1.64041666667 | 9819 |
| 010413 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596536.5 | 513573.1 | 88176 | 1.64041666667 | 10413 |
| 010710 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596538.3 | 513572.9 | 88179 | 1.64041666667 | 10710 |
| 010539 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596539.6 | 513571.4 | 88180 | 1.64041666667 | 10539 |
| 010601 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596542.2 | 513570.2 | 88183 | 1.64041666667 | 10601 |
| 010680 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596543.8 | 513569.1 | 88185 | 1.64041666667 | 10680 |
| 010717 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596544.9 | 513567.4 | 88187 | 1.64041666667 | 10717 |
| 010641 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596546.4 | 513566.1 | 88189 | 1.64041666667 | 10641 |
| 010905 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596548.2 | 513564.2 | 88191 | 1.64041666667 | 10905 |
| 011099 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596548.6 | 513562.4 | 88193 | 1.64041666667 | 11099 |
| 011606 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596550.2 | 513560.4 | 88195 | 1.64041666667 | 11606 |
| 011058 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596550.9 | 513558.7 | 88197 | 1.64041666667 | 11058 |
| 011613 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596550.9 | 513556.8 | 88198 | 1.64041666667 | 11613 |
| 011542 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596552.0 | 513554.9 | 88200 | 1.64041666667 | 11542 |
| 010692 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596552.1 | 513552.6 | 88203 | 1.64041666667 | 10692 |
| 010049 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596551.6 | 513550.6 | 88204 | 1.64041666667 | 10049 |
| 010175 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596552.3 | 513548.3 | 88207 | 1.64041666667 | 10175 |
| 010373 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596551.8 | 513546.6 | 88208 | 1.64041666667 | 10373 |
| 010620 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596553.1 | 513545.1 | 88211 | 1.64041666667 | 10620 |
| 011358 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596554.2 | 513543.8 | 88212 | 1.64041666667 | 11358 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010222 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:55pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596554.8 | 513542.3 | 88214 | 1.64041666667 | 10222 |
| 010234 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.1 | 513541.1 | 88216 | 1.64041666667 | 10234 |
| 010287 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596556.9 | 513539.2 | 88219 | 1.64041666667 | 10287 |
| 010579 | 0 | GeoXH 6000 | 08/20/2015 | 01:21:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596558.2 | 513538.2 | 88220 | 1.64041666667 | 10579 |
| 010578 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596558.4 | 513537.0 | 88223 | 1.64041666667 | 10578 |
| 012512 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:01pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596559.1 | 513535.9 | 88225 | 1.64041666667 | 12512 |
| 011883 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596558.9 | 513536.1 | 88227 | 1.64041666667 | 11883 |
| 011379 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596558.3 | 513536.3 | 88228 | 1.64041666667 | 11379 |
| 011366 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596556.8 | 513536.6 | 88231 | 1.64041666667 | 11366 |
| 011373 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596555.4 | 513537.3 | 88233 | 1.64041666667 | 11373 |
| 011145 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596554.7 | 513538.3 | 88234 | 1.64041666667 | 11145 |
| 011159 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596553.8 | 513538.2 | 88236 | 1.64041666667 | 11159 |
| 011137 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596552.4 | 513537.8 | 88239 | 1.64041666667 | 11137 |
| 011072 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596552.0 | 513536.8 | 88240 | 1.64041666667 | 11072 |
| 011673 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596550.6 | 513536.1 | 88243 | 1.64041666667 | 11673 |
| 012048 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596549.6 | 513535.4 | 88244 | 1.64041666667 | 12048 |
| 011862 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596548.3 | 513534.9 | 88247 | 1.64041666667 | 11862 |
| 010962 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596547.9 | 513534.8 | 88248 | 1.64041666667 | 10962 |
| 011086 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596548.0 | 513535.1 | 88251 | 1.64041666667 | 11086 |
| 011711 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:15pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596548.0 | 513535.2 | 88253 | 1.64041666667 | 11711 |
| 010907 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596548.1 | 513535.2 | 88255 | 1.64041666667 | 10907 |
| 011355 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596548.0 | 513535.2 | 88256 | 1.64041666667 | 11355 |
| 011329 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:17pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596548.1 | 513535.4 | 88258 | 1.64041666667 | 11329 |
| 011308 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596547.9 | 513535.4 | 88260 | 1.64041666667 | 11308 |
| 011513 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:19pm | Sensor | 1797-S0054-905-G-ACK | 6849.4 | 1596546.5 | 513534.2 | 88262 | 1.64041666667 | 11513 |
| 011516 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:21pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596546.9 | 513534.3 | 88265 | 1.64041666667 | 11516 |
| 010602 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596547.6 | 513534.3 | 88267 | 1.64041666667 | 10602 |
| 010914 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596548.0 | 513534.5 | 88268 | 1.64041666667 | 10914 |
| 010279 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596548.1 | 513534.9 | 88271 | 1.64041666667 | 10279 |
| 011107 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:25pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596548.1 | 513535.0 | 88273 | 1.64041666667 | 11107 |
| 011422 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596548.2 | 513534.6 | 88275 | 1.64041666667 | 11422 |
| 011870 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596546.9 | 513534.2 | 88276 | 1.64041666667 | 11870 |
| 010629 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596547.3 | 513533.9 | 88279 | 1.64041666667 | 10629 |
| 010786 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:29pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596548.4 | 513533.1 | 88281 | 1.64041666667 | 10786 |
| 012112 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596548.2 | 513533.1 | 88283 | 1.64041666667 | 12112 |
| 011800 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:31pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596548.8 | 513533.9 | 88285 | 1.64041666667 | 11800 |
| 011872 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596548.2 | 513535.4 | 88287 | 1.64041666667 | 11872 |
| 011568 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:33pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596548.5 | 513537.1 | 88289 | 1.64041666667 | 11568 |
| 011757 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596548.2 | 513538.6 | 88291 | 1.64041666667 | 11757 |
| 010416 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596548.0 | 513540.5 | 88293 | 1.64041666667 | 10416 |
| 010336 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596548.9 | 513542.4 | 88295 | 1.64041666667 | 10336 |
| 010869 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596548.3 | 513544.0 | 88296 | 1.64041666667 | 10869 |
| 011176 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596549.2 | 513545.6 | 88299 | 1.64041666667 | 11176 |
| 010966 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596549.1 | 513547.1 | 88300 | 1.64041666667 | 10966 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596549.4 | 513549.1 | 88303 | 1.64041666667 | 11928 |
| 011652 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596548.6 | 513550.2 | 88305 | 1.64041666667 | 11652 |
| 010709 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596547.9 | 513551.7 | 88307 | 1.64041666667 | 10709 |
| 010141 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596547.0 | 513552.8 | 88308 | 1.64041666667 | 10141 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010819 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596546.2 | 513553.4 | 88311 | 1.64041666667 | 10819 |
| 010301 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596545.7 | 513554.2 | 88313 | 1.64041666667 | 10301 |
| 010481 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596544.4 | 513555.5 | 88314 | 1.64041666667 | 10481 |
| 010103 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596543.9 | 513557.2 | 88316 | 1.64041666667 | 10103 |
| 010423 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596542.7 | 513559.2 | 88319 | 1.64041666667 | 10423 |
| 010970 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596542.9 | 513560.7 | 88320 | 1.64041666667 | 10970 |
| 011331 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596542.8 | 513562.6 | 88323 | 1.64041666667 | 11331 |
| 011046 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596542.1 | 513564.0 | 88324 | 1.64041666667 | 11046 |
| 011141 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596542.3 | 513566.1 | 88327 | 1.64041666667 | 11141 |
| 011981 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596541.2 | 513567.5 | 88328 | 1.64041666667 | 11981 |
| 011089 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596541.3 | 513569.5 | 88331 | 1.64041666667 | 11089 |
| 011023 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:55pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596540.9 | 513571.1 | 88333 | 1.64041666667 | 11023 |
| 010115 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596541.0 | 513572.8 | 88335 | 1.64041666667 | 10115 |
| 010189 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596542.1 | 513574.2 | 88337 | 1.64041666667 | 10189 |
| 010644 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596542.8 | 513575.9 | 88339 | 1.64041666667 | 10644 |
| 010802 | 0 | GeoXH 6000 | 08/20/2015 | 01:22:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596544.6 | 513577.1 | 88340 | 1.64041666667 | 10802 |
| 010988 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596545.0 | 513579.4 | 88343 | 1.64041666667 | 10988 |
| 010913 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596546.3 | 513580.8 | 88345 | 1.64041666667 | 10913 |
| 011261 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596547.5 | 513582.2 | 88347 | 1.64041666667 | 11261 |
| 011134 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596548.7 | 513584.0 | 88349 | 1.64041666667 | 11134 |
| 012480 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596550.4 | 513585.3 | 88351 | 1.64041666667 | 12480 |
| 011025 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596550.1 | 513587.2 | 88353 | 1.64041666667 | 11025 |
| 011316 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596549.9 | 513589.3 | 88354 | 1.64041666667 | 11316 |
| 011383 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596549.3 | 513591.1 | 88356 | 1.64041666667 | 11383 |
| 010738 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596547.7 | 513592.8 | 88359 | 1.64041666667 | 10738 |
| 010855 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596547.0 | 513594.1 | 88360 | 1.64041666667 | 10855 |
| 011146 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596545.2 | 513594.9 | 88362 | 1.64041666667 | 11146 |
| 010087 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596543.5 | 513596.1 | 88365 | 1.64041666667 | 10087 |
| 010481 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596542.7 | 513596.7 | 88367 | 1.64041666667 | 10481 |
| 010680 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596541.4 | 513597.6 | 88368 | 1.64041666667 | 10680 |
| 010403 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596540.3 | 513599.9 | 88371 | 1.64041666667 | 10403 |
| 011859 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596540.0 | 513601.6 | 88372 | 1.64041666667 | 11859 |
| 011868 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596538.9 | 513603.6 | 88375 | 1.64041666667 | 11868 |
| 011280 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596538.8 | 513605.3 | 88376 | 1.64041666667 | 11280 |
| 010785 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596538.0 | 513607.3 | 88378 | 1.64041666667 | 10785 |
| 011264 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596536.9 | 513608.5 | 88380 | 1.64041666667 | 11264 |
| 011481 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596536.1 | 513610.6 | 88383 | 1.64041666667 | 11481 |
| 011993 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:21pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596534.7 | 513611.7 | 88385 | 1.64041666667 | 11993 |
| 011846 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596533.5 | 513613.3 | 88387 | 1.64041666667 | 11846 |
| 012041 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596531.4 | 513613.8 | 88388 | 1.64041666667 | 12041 |
| 011333 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596528.9 | 513614.0 | 88391 | 1.64041666667 | 11333 |
| 011137 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596527.4 | 513613.5 | 88392 | 1.64041666667 | 11137 |
| 010899 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596525.1 | 513612.7 | 88395 | 1.64041666667 | 10899 |
| 011141 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596523.5 | 513612.2 | 88396 | 1.64041666667 | 11141 |
| 012986 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:27pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596521.6 | 513610.7 | 88398 | 1.64041666667 | 12986 |
| 012435 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:29pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596519.7 | 513609.9 | 88401 | 1.64041666667 | 12435 |
| 011412 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596517.3 | 513608.9 | 88403 | 1.64041666667 | 11412 |
| 010949 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:31pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596515.7 | 513607.0 | 88405 | 1.64041666667 | 10949 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010861 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:32pm | Sensor | 1797-S0054-905-G-ACK | 6849.9 | 1596515.2 | 513604.6 | 88407 | 1.64041666667 | 10861 |
| 011337 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596515.5 | 513602.7 | 88408 | 1.64041666667 | 11337 |
| 010682 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596515.7 | 513600.4 | 88411 | 1.64041666667 | 10682 |
| 010576 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596516.8 | 513598.8 | 88413 | 1.64041666667 | 10576 |
| 010479 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596518.2 | 513597.7 | 88414 | 1.64041666667 | 10479 |
| 010342 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596519.3 | 513596.2 | 88416 | 1.64041666667 | 10342 |
| 010084 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:37pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596521.0 | 513595.5 | 88418 | 1.64041666667 | 10084 |
| 010352 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596522.6 | 513595.2 | 88420 | 1.64041666667 | 10352 |
| 010518 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596523.7 | 513593.6 | 88422 | 1.64041666667 | 10518 |
| 010574 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596524.4 | 513592.2 | 88424 | 1.64041666667 | 10574 |
| 010837 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596525.9 | 513590.5 | 88427 | 1.64041666667 | 10837 |
| 010423 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596526.0 | 513588.9 | 88428 | 1.64041666667 | 10423 |
| 010461 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596526.2 | 513586.9 | 88430 | 1.64041666667 | 10461 |
| 010594 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596527.2 | 513585.2 | 88432 | 1.64041666667 | 10594 |
| 010316 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596528.3 | 513583.1 | 88435 | 1.64041666667 | 10316 |
| 011705 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596528.8 | 513581.1 | 88437 | 1.64041666667 | 11705 |
| 011347 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596529.4 | 513579.7 | 88439 | 1.64041666667 | 11347 |
| 010815 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:49pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596530.5 | 513578.2 | 88441 | 1.64041666667 | 10815 |
| 010163 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596531.1 | 513576.0 | 88443 | 1.64041666667 | 10163 |
| 010427 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596531.5 | 513574.3 | 88444 | 1.64041666667 | 10427 |
| 010147 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596533.0 | 513572.6 | 88447 | 1.64041666667 | 10147 |
| 009938 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596533.8 | 513571.3 | 88448 | 1.64041666667 | 9938 |
| 010022 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596534.0 | 513569.6 | 88450 | 1.64041666667 | 10022 |
| 009912 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596534.9 | 513568.6 | 88452 | 1.64041666667 | 9912 |
| 010248 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596536.0 | 513567.1 | 88455 | 1.64041666667 | 10248 |
| 010039 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596536.1 | 513565.7 | 88456 | 1.64041666667 | 10039 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596537.1 | 513564.7 | 88459 | 1.64041666667 | 11205 |
| 010555 | 0 | GeoXH 6000 | 08/20/2015 | 01:23:58pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596536.6 | 513563.5 | 88460 | 1.64041666667 | 10555 |
| 010092 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596537.1 | 513562.6 | 88463 | 1.64041666667 | 10092 |
| 009997 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596537.0 | 513561.1 | 88465 | 1.64041666667 | 9997 |
| 010183 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596536.7 | 513559.1 | 88467 | 1.64041666667 | 10183 |
| 011053 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596537.1 | 513557.4 | 88469 | 1.64041666667 | 11053 |
| 011572 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596536.4 | 513556.0 | 88471 | 1.64041666667 | 11572 |
| 010732 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596536.3 | 513554.6 | 88473 | 1.64041666667 | 10732 |
| 011181 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596537.3 | 513552.9 | 88475 | 1.64041666667 | 11181 |
| 010602 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596537.9 | 513551.8 | 88476 | 1.64041666667 | 10602 |
| 010418 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596539.0 | 513549.9 | 88479 | 1.64041666667 | 10418 |
| 010293 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596540.0 | 513549.7 | 88480 | 1.64041666667 | 10293 |
| 010635 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596540.2 | 513548.3 | 88483 | 1.64041666667 | 10635 |
| 010819 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:11pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596541.6 | 513547.0 | 88485 | 1.64041666667 | 10819 |
| 011148 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596542.6 | 513545.3 | 88487 | 1.64041666667 | 11148 |
| 011746 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596543.1 | 513544.0 | 88488 | 1.64041666667 | 11746 |
| 011512 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596544.6 | 513543.0 | 88491 | 1.64041666667 | 11512 |
| 011605 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:15pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596544.8 | 513541.7 | 88493 | 1.64041666667 | 11605 |
| 011058 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596545.6 | 513541.5 | 88495 | 1.64041666667 | 11058 |
| 010780 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596546.1 | 513541.2 | 88496 | 1.64041666667 | 10780 |
| 011381 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:17pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596547.5 | 513541.7 | 88498 | 1.64041666667 | 11381 |
| 012154 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596547.5 | 513543.2 | 88500 | 1.64041666667 | 12154 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012011 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596547.7 | 513545.3 | 88503 | 1.64041666667 | 12011 |
| 011774 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596547.9 | 513546.9 | 88504 | 1.64041666667 | 11774 |
| 011430 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596547.6 | 513549.4 | 88507 | 1.64041666667 | 11430 |
| 011507 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:23pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596548.6 | 513551.3 | 88509 | 1.64041666667 | 11507 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596548.6 | 513553.3 | 88511 | 1.64041666667 | 11205 |
| 011103 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596549.3 | 513555.2 | 88512 | 1.64041666667 | 11103 |
| 010325 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596549.8 | 513557.1 | 88515 | 1.64041666667 | 10325 |
| 011058 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596549.8 | 513559.1 | 88516 | 1.64041666667 | 11058 |
| 010615 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:27pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596550.4 | 513560.9 | 88518 | 1.64041666667 | 10615 |
| 010718 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596549.7 | 513562.7 | 88520 | 1.64041666667 | 10718 |
| 010341 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596549.2 | 513565.1 | 88523 | 1.64041666667 | 10341 |
| 010369 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596548.2 | 513566.6 | 88524 | 1.64041666667 | 10369 |
| 010235 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596547.8 | 513568.8 | 88527 | 1.64041666667 | 10235 |
| 010789 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596547.4 | 513570.6 | 88528 | 1.64041666667 | 10789 |
| 010726 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596545.8 | 513572.6 | 88531 | 1.64041666667 | 10726 |
| 010248 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596546.2 | 513574.5 | 88532 | 1.64041666667 | 10248 |
| 010595 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596546.1 | 513576.9 | 88535 | 1.64041666667 | 10595 |
| 010617 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596547.0 | 513578.9 | 88536 | 1.64041666667 | 10617 |
| 011439 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596549.5 | 513579.8 | 88539 | 1.64041666667 | 11439 |
| 011872 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596550.9 | 513581.3 | 88540 | 1.64041666667 | 11872 |
| 010885 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596552.6 | 513583.2 | 88543 | 1.64041666667 | 10885 |
| 010285 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596553.8 | 513584.7 | 88544 | 1.64041666667 | 10285 |
| 010563 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596553.1 | 513586.7 | 88547 | 1.64041666667 | 10563 |
| 010224 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596553.6 | 513588.6 | 88549 | 1.64041666667 | 10224 |
| 010618 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:44pm | Sensor | 1797-S0054-905-G-ACK | 6849.9 | 1596552.7 | 513590.6 | 88551 | 1.64041666667 | 10618 |
| 010458 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596551.3 | 513592.5 | 88553 | 1.64041666667 | 10458 |
| 010135 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596550.7 | 513594.3 | 88555 | 1.64041666667 | 10135 |
| 011026 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596549.7 | 513595.3 | 88556 | 1.64041666667 | 11026 |
| 010492 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596549.4 | 513596.8 | 88559 | 1.64041666667 | 10492 |
| 011099 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596548.6 | 513597.9 | 88560 | 1.64041666667 | 11099 |
| 011486 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596547.3 | 513599.8 | 88562 | 1.64041666667 | 11486 |
| 011268 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596546.4 | 513601.5 | 88564 | 1.64041666667 | 11268 |
| 011243 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596544.2 | 513603.4 | 88567 | 1.64041666667 | 11243 |
| 012039 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596542.9 | 513605.0 | 88568 | 1.64041666667 | 12039 |
| 011039 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596542.2 | 513606.7 | 88570 | 1.64041666667 | 11039 |
| 010620 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596540.3 | 513608.1 | 88572 | 1.64041666667 | 10620 |
| 010706 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596538.8 | 513610.2 | 88575 | 1.64041666667 | 10706 |
| 010717 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596537.6 | 513611.3 | 88577 | 1.64041666667 | 10717 |
| 011016 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596535.7 | 513612.7 | 88579 | 1.64041666667 | 11016 |
| 010974 | 0 | GeoXH 6000 | 08/20/2015 | 01:24:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596536.2 | 513614.3 | 88581 | 1.64041666667 | 10974 |
| 011407 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596535.0 | 513616.0 | 88583 | 1.64041666667 | 11407 |
| 011426 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596533.4 | 513617.3 | 88584 | 1.64041666667 | 11426 |
| 011617 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596532.2 | 513619.1 | 88586 | 1.64041666667 | 11617 |
| 011515 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596530.4 | 513619.5 | 88588 | 1.64041666667 | 11515 |
| 011247 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596528.4 | 513619.5 | 88590 | 1.64041666667 | 11247 |
| 011239 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596526.6 | 513619.0 | 88592 | 1.64041666667 | 11239 |
| 010672 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596524.8 | 513617.5 | 88595 | 1.64041666667 | 10672 |
| 011598 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:07pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596522.9 | 513617.0 | 88597 | 1.64041666667 | 11598 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012119 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596521.3 | 513615.8 | 88599 | 1.64041666667 | 12119 |
| 012652 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596519.9 | 513614.8 | 88600 | 1.64041666667 | 12652 |
| 012974 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596517.5 | 513614.4 | 88603 | 1.64041666667 | 12974 |
| 014580 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596516.4 | 513613.3 | 88604 | 1.64041666667 | 14580 |
| 013511 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596514.5 | 513612.5 | 88607 | 1.64041666667 | 13511 |
| 014725 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:12pm | Sensor | 1797-S0054-905-G-ACK | 6849.9 | 1596514.0 | 513611.2 | 88608 | 1.64041666667 | 14725 |
| 014020 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596512.9 | 513609.6 | 88611 | 1.64041666667 | 14020 |
| 013639 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596512.3 | 513609.1 | 88612 | 1.64041666667 | 13639 |
| 016559 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596510.1 | 513609.4 | 88615 | 1.64041666667 | 16559 |
| 015989 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596509.9 | 513610.5 | 88616 | 1.64041666667 | 15989 |
| 015616 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596508.3 | 513611.5 | 88619 | 1.64041666667 | 15616 |
| 013966 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596508.8 | 513612.8 | 88620 | 1.64041666667 | 13966 |
| 013376 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596508.2 | 513614.5 | 88623 | 1.64041666667 | 13376 |
| 012354 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596507.9 | 513615.8 | 88624 | 1.64041666667 | 12354 |
| 012124 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596507.5 | 513617.6 | 88627 | 1.64041666667 | 12124 |
| 011379 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:23pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596507.0 | 513618.8 | 88629 | 1.64041666667 | 11379 |
| 011133 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596506.6 | 513620.6 | 88631 | 1.64041666667 | 11133 |
| 010875 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596505.8 | 513621.6 | 88633 | 1.64041666667 | 10875 |
| 010834 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596504.9 | 513622.7 | 88635 | 1.64041666667 | 10834 |
| 010662 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596504.1 | 513624.1 | 88636 | 1.64041666667 | 10662 |
| 010362 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:28pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596503.7 | 513625.9 | 88639 | 1.64041666667 | 10362 |
| 009901 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:28pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596502.9 | 513626.1 | 88640 | 1.64041666667 | 9901 |
| 010309 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:30pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596503.0 | 513627.7 | 88643 | 1.64041666667 | 10309 |
| 009894 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:30pm | Sensor | 1797-S0054-905-G-ACK | 6852.4 | 1596502.4 | 513629.1 | 88644 | 1.64041666667 | 9894 |
| 010020 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:32pm | Sensor | 1797-S0054-905-G-ACK | 6852.5 | 1596503.3 | 513630.0 | 88647 | 1.64041666667 | 10020 |
| 010676 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:32pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596503.7 | 513631.5 | 88648 | 1.64041666667 | 10676 |
| 010160 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596505.1 | 513632.9 | 88651 | 1.64041666667 | 10160 |
| 009480 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:34pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596506.3 | 513633.9 | 88652 | 1.64041666667 | 9480 |
| 009495 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596507.3 | 513633.7 | 88655 | 1.64041666667 | 9495 |
| 009593 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:36pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596508.4 | 513632.6 | 88656 | 1.64041666667 | 9593 |
| 010428 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:37pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596509.2 | 513631.3 | 88658 | 1.64041666667 | 10428 |
| 010771 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:38pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596510.5 | 513630.6 | 88660 | 1.64041666667 | 10771 |
| 010184 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:40pm | Sensor | 1797-S0054-905-G-ACK | 6852.4 | 1596510.9 | 513628.4 | 88663 | 1.64041666667 | 10184 |
| 010116 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:40pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596512.0 | 513627.5 | 88664 | 1.64041666667 | 10116 |
| 010355 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596513.3 | 513626.0 | 88667 | 1.64041666667 | 10355 |
| 009979 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596513.6 | 513625.0 | 88668 | 1.64041666667 | 9979 |
| 010983 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596514.8 | 513623.3 | 88671 | 1.64041666667 | 10983 |
| 010670 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596514.9 | 513621.6 | 88673 | 1.64041666667 | 10670 |
| 009812 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596515.6 | 513620.2 | 88674 | 1.64041666667 | 9812 |
| 011332 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596516.7 | 513618.7 | 88676 | 1.64041666667 | 11332 |
| 011991 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596516.7 | 513616.5 | 88679 | 1.64041666667 | 11991 |
| 012003 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596517.5 | 513615.4 | 88680 | 1.64041666667 | 12003 |
| 012159 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:49pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596518.5 | 513614.6 | 88682 | 1.64041666667 | 12159 |
| 011512 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596519.8 | 513614.7 | 88684 | 1.64041666667 | 11512 |
| 011913 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596521.1 | 513616.0 | 88686 | 1.64041666667 | 11913 |
| 012138 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596522.3 | 513617.3 | 88688 | 1.64041666667 | 12138 |
| 012475 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596522.3 | 513619.2 | 88690 | 1.64041666667 | 12475 |
| 012102 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596522.6 | 513620.5 | 88692 | 1.64041666667 | 12102 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011307 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596521.0 | 513621.5 | 88695 | 1.64041666667 | 11307 |
| 011535 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596519.4 | 513622.6 | 88697 | 1.64041666667 | 11535 |
| 011911 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596518.5 | 513623.7 | 88699 | 1.64041666667 | 11911 |
| 011282 | 0 | GeoXH 6000 | 08/20/2015 | 01:25:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596517.5 | 513624.2 | 88701 | 1.64041666667 | 11282 |
| 010741 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596516.4 | 513626.2 | 88703 | 1.64041666667 | 10741 |
| 010879 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596516.2 | 513626.6 | 88704 | 1.64041666667 | 10879 |
| 011310 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596516.1 | 513627.6 | 88707 | 1.64041666667 | 11310 |
| 010539 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596515.4 | 513629.0 | 88708 | 1.64041666667 | 10539 |
| 011320 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596515.5 | 513630.6 | 88710 | 1.64041666667 | 11320 |
| 011092 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596514.3 | 513632.1 | 88712 | 1.64041666667 | 11092 |
| 011279 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596513.0 | 513633.8 | 88715 | 1.64041666667 | 11279 |
| 010245 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596512.8 | 513635.3 | 88716 | 1.64041666667 | 10245 |
| 010570 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596511.0 | 513636.5 | 88719 | 1.64041666667 | 10570 |
| 010147 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596511.2 | 513637.7 | 88720 | 1.64041666667 | 10147 |
| 010414 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596511.5 | 513639.5 | 88723 | 1.64041666667 | 10414 |
| 009885 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596511.7 | 513640.7 | 88724 | 1.64041666667 | 9885 |
| 010375 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596513.0 | 513642.1 | 88727 | 1.64041666667 | 10375 |
| 010361 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596512.8 | 513643.8 | 88728 | 1.64041666667 | 10361 |
| 010538 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596514.1 | 513645.4 | 88731 | 1.64041666667 | 10538 |
| 010840 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596514.2 | 513646.8 | 88732 | 1.64041666667 | 10840 |
| 010590 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596516.1 | 513647.6 | 88735 | 1.64041666667 | 10590 |
| 011394 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596516.9 | 513647.1 | 88736 | 1.64041666667 | 11394 |
| 010924 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596518.6 | 513645.9 | 88739 | 1.64041666667 | 10924 |
| 011410 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596519.1 | 513644.6 | 88740 | 1.64041666667 | 11410 |
| 011323 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596520.8 | 513643.3 | 88743 | 1.64041666667 | 11323 |
| 011626 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596520.6 | 513641.8 | 88744 | 1.64041666667 | 11626 |
| 011430 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596522.4 | 513640.2 | 88747 | 1.64041666667 | 11430 |
| 011409 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596522.7 | 513638.6 | 88748 | 1.64041666667 | 11409 |
| 011480 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596523.4 | 513636.8 | 88751 | 1.64041666667 | 11480 |
| 011340 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596524.8 | 513635.8 | 88752 | 1.64041666667 | 11340 |
| 010983 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596524.9 | 513634.5 | 88755 | 1.64041666667 | 10983 |
| 010551 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596525.9 | 513633.5 | 88756 | 1.64041666667 | 10551 |
| 010247 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596525.2 | 513631.8 | 88759 | 1.64041666667 | 10247 |
| 010811 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596525.6 | 513630.3 | 88760 | 1.64041666667 | 10811 |
| 010536 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596525.0 | 513628.8 | 88762 | 1.64041666667 | 10536 |
| 010584 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596525.3 | 513627.3 | 88764 | 1.64041666667 | 10584 |
| 010198 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596525.6 | 513626.0 | 88767 | 1.64041666667 | 10198 |
| 010139 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596526.0 | 513625.0 | 88768 | 1.64041666667 | 10139 |
| 011599 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596526.9 | 513622.7 | 88771 | 1.64041666667 | 11599 |
| 011399 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596526.8 | 513620.9 | 88772 | 1.64041666667 | 11399 |
| 010972 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596528.5 | 513619.6 | 88775 | 1.64041666667 | 10972 |
| 010799 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596530.1 | 513618.1 | 88776 | 1.64041666667 | 10799 |
| 011062 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596531.8 | 513618.4 | 88779 | 1.64041666667 | 11062 |
| 011832 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596533.4 | 513617.9 | 88780 | 1.64041666667 | 11832 |
| 012063 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596535.2 | 513618.9 | 88783 | 1.64041666667 | 12063 |
| 012035 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596536.9 | 513619.0 | 88784 | 1.64041666667 | 12035 |
| 011397 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596537.5 | 513620.3 | 88787 | 1.64041666667 | 11397 |
| 011113 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596538.8 | 513621.6 | 88788 | 1.64041666667 | 11113 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010878 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596537.8 | 513623.9 | 88791 | 1.64041666667 | 10878 |
| 010739 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596537.0 | 513625.3 | 88792 | 1.64041666667 | 10739 |
| 010961 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596535.6 | 513626.8 | 88794 | 1.64041666667 | 10961 |
| 010230 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:46pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596533.7 | 513627.8 | 88796 | 1.64041666667 | 10230 |
| 009774 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596532.4 | 513629.6 | 88799 | 1.64041666667 | 9774 |
| 010628 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596530.9 | 513629.6 | 88800 | 1.64041666667 | 10628 |
| 010583 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596529.0 | 513630.9 | 88803 | 1.64041666667 | 10583 |
| 010723 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596528.7 | 513632.2 | 88804 | 1.64041666667 | 10723 |
| 010426 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596527.0 | 513633.7 | 88807 | 1.64041666667 | 10426 |
| 010125 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596526.2 | 513635.2 | 88808 | 1.64041666667 | 10125 |
| 011230 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596525.0 | 513635.9 | 88811 | 1.64041666667 | 11230 |
| 010667 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596523.6 | 513637.2 | 88812 | 1.64041666667 | 10667 |
| 010005 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596523.3 | 513639.7 | 88815 | 1.64041666667 | 10005 |
| 010488 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596522.2 | 513641.2 | 88816 | 1.64041666667 | 10488 |
| 010099 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596521.5 | 513643.1 | 88818 | 1.64041666667 | 10099 |
| 010361 | 0 | GeoXH 6000 | 08/20/2015 | 01:26:58pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596521.2 | 513644.3 | 88820 | 1.64041666667 | 10361 |
| 009885 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596520.1 | 513646.7 | 88823 | 1.64041666667 | 9885 |
| 010638 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596520.6 | 513648.2 | 88824 | 1.64041666667 | 10638 |
| 010094 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596520.8 | 513650.7 | 88827 | 1.64041666667 | 10094 |
| 010155 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596521.6 | 513652.2 | 88828 | 1.64041666667 | 10155 |
| 010504 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596522.9 | 513653.1 | 88831 | 1.64041666667 | 10504 |
| 009914 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596524.0 | 513653.2 | 88832 | 1.64041666667 | 9914 |
| 010174 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596525.7 | 513652.3 | 88834 | 1.64041666667 | 10174 |
| 011940 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596526.3 | 513650.8 | 88836 | 1.64041666667 | 11940 |
| 011448 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596527.8 | 513649.4 | 88838 | 1.64041666667 | 11448 |
| 011712 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596528.6 | 513647.9 | 88840 | 1.64041666667 | 11712 |
| 011081 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:09pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596528.8 | 513645.6 | 88842 | 1.64041666667 | 11081 |
| 010785 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:10pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596530.1 | 513644.7 | 88844 | 1.64041666667 | 10785 |
| 011069 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:11pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596531.2 | 513643.0 | 88846 | 1.64041666667 | 11069 |
| 010929 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:12pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596532.5 | 513642.5 | 88848 | 1.64041666667 | 10929 |
| 011495 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:14pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596533.9 | 513640.6 | 88851 | 1.64041666667 | 11495 |
| 010981 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:14pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596535.0 | 513639.5 | 88852 | 1.64041666667 | 10981 |
| 010474 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:16pm | Sensor | 1797-S0054-905-G-ACK | 6852.5 | 1596536.0 | 513637.2 | 88855 | 1.64041666667 | 10474 |
| 010616 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:17pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596536.1 | 513636.2 | 88857 | 1.64041666667 | 10616 |
| 010532 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596537.8 | 513634.3 | 88859 | 1.64041666667 | 10532 |
| 010701 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596538.1 | 513632.5 | 88860 | 1.64041666667 | 10701 |
| 010279 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596539.4 | 513630.7 | 88862 | 1.64041666667 | 10279 |
| 011137 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596539.4 | 513628.6 | 88864 | 1.64041666667 | 11137 |
| 010809 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596541.7 | 513626.6 | 88867 | 1.64041666667 | 10809 |
| 010820 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596542.9 | 513624.5 | 88868 | 1.64041666667 | 10820 |
| 010541 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596542.9 | 513622.4 | 88871 | 1.64041666667 | 10541 |
| 010624 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596543.6 | 513621.1 | 88872 | 1.64041666667 | 10624 |
| 010409 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596544.8 | 513619.4 | 88874 | 1.64041666667 | 10409 |
| 010355 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596545.1 | 513617.8 | 88876 | 1.64041666667 | 10355 |
| 010242 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596546.5 | 513615.9 | 88878 | 1.64041666667 | 10242 |
| 010778 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596546.3 | 513613.9 | 88880 | 1.64041666667 | 10778 |
| 010360 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596546.8 | 513611.8 | 88883 | 1.64041666667 | 10360 |
| 011280 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596547.8 | 513610.0 | 88884 | 1.64041666667 | 11280 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010796 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596548.3 | 513607.7 | 88887 | 1.64041666667 | 10796 |
| 010670 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596549.6 | 513606.7 | 88888 | 1.64041666667 | 10670 |
| 011079 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596549.7 | 513604.3 | 88891 | 1.64041666667 | 11079 |
| 011310 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596550.5 | 513602.5 | 88892 | 1.64041666667 | 11310 |
| 011026 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:36pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596551.1 | 513600.6 | 88895 | 1.64041666667 | 11026 |
| 010927 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:36pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596551.7 | 513600.0 | 88896 | 1.64041666667 | 10927 |
| 010511 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596553.4 | 513599.3 | 88899 | 1.64041666667 | 10511 |
| 010720 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596553.6 | 513598.3 | 88900 | 1.64041666667 | 10720 |
| 010537 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596555.5 | 513596.6 | 88903 | 1.64041666667 | 10537 |
| 010037 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596556.1 | 513594.9 | 88905 | 1.64041666667 | 10037 |
| 010273 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596557.9 | 513593.5 | 88907 | 1.64041666667 | 10273 |
| 010991 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596559.5 | 513592.3 | 88909 | 1.64041666667 | 10991 |
| 011200 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596559.6 | 513590.5 | 88911 | 1.64041666667 | 11200 |
| 010815 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596560.8 | 513588.5 | 88913 | 1.64041666667 | 10815 |
| 010246 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596560.6 | 513586.4 | 88915 | 1.64041666667 | 10246 |
| 010451 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596559.7 | 513584.4 | 88917 | 1.64041666667 | 10451 |
| 009988 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596559.6 | 513582.6 | 88919 | 1.64041666667 | 9988 |
| 011063 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596558.7 | 513581.7 | 88920 | 1.64041666667 | 11063 |
| 010670 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596558.0 | 513579.7 | 88923 | 1.64041666667 | 10670 |
| 010877 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596556.9 | 513578.0 | 88924 | 1.64041666667 | 10877 |
| 011143 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596555.4 | 513576.9 | 88926 | 1.64041666667 | 11143 |
| 010663 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596555.1 | 513575.1 | 88928 | 1.64041666667 | 10663 |
| 011465 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596553.8 | 513573.6 | 88930 | 1.64041666667 | 11465 |
| 011347 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596553.9 | 513572.2 | 88932 | 1.64041666667 | 11347 |
| 011355 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:55pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596554.0 | 513570.5 | 88934 | 1.64041666667 | 11355 |
| 010827 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596555.0 | 513569.5 | 88936 | 1.64041666667 | 10827 |
| 010755 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.5 | 513567.7 | 88938 | 1.64041666667 | 10755 |
| 010257 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596555.8 | 513566.1 | 88940 | 1.64041666667 | 10257 |
| 011274 | 0 | GeoXH 6000 | 08/20/2015 | 01:27:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.5 | 513564.0 | 88942 | 1.64041666667 | 11274 |
| 010909 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596556.1 | 513562.4 | 88944 | 1.64041666667 | 10909 |
| 011064 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596556.4 | 513560.3 | 88947 | 1.64041666667 | 11064 |
| 011676 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.8 | 513558.8 | 88948 | 1.64041666667 | 11676 |
| 012380 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596556.6 | 513557.2 | 88951 | 1.64041666667 | 12380 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.8 | 513556.0 | 88952 | 1.64041666667 | 11928 |
| 011802 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.3 | 513554.5 | 88954 | 1.64041666667 | 11802 |
| 010951 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.7 | 513552.8 | 88956 | 1.64041666667 | 10951 |
| 011440 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:07pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596555.6 | 513551.2 | 88958 | 1.64041666667 | 11440 |
| 011332 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.4 | 513549.6 | 88960 | 1.64041666667 | 11332 |
| 011017 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:09pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596555.8 | 513548.1 | 88962 | 1.64041666667 | 11017 |
| 010637 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596556.5 | 513546.8 | 88964 | 1.64041666667 | 10637 |
| 011038 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596555.3 | 513545.5 | 88967 | 1.64041666667 | 11038 |
| 010131 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596555.8 | 513544.1 | 88968 | 1.64041666667 | 10131 |
| 010724 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:13pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596555.3 | 513542.1 | 88970 | 1.64041666667 | 10724 |
| 010824 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596556.4 | 513541.2 | 88972 | 1.64041666667 | 10824 |
| 010934 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596557.1 | 513539.5 | 88975 | 1.64041666667 | 10934 |
| 011940 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596558.5 | 513539.1 | 88976 | 1.64041666667 | 11940 |
| 010901 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596560.1 | 513538.4 | 88979 | 1.64041666667 | 10901 |
| 011007 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596560.9 | 513537.5 | 88980 | 1.64041666667 | 11007 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010961 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596561.8 | 513536.3 | 88983 | 1.64041666667 | 10961 |
| 010853 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596562.0 | 513534.9 | 88984 | 1.64041666667 | 10853 |
| 011152 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596562.9 | 513533.5 | 88987 | 1.64041666667 | 11152 |
| 010871 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596562.8 | 513531.8 | 88988 | 1.64041666667 | 10871 |
| 010675 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596564.2 | 513531.5 | 88991 | 1.64041666667 | 10675 |
| 010549 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:25pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596565.4 | 513530.4 | 88993 | 1.64041666667 | 10549 |
| 010771 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:25pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596567.1 | 513530.2 | 88994 | 1.64041666667 | 10771 |
| 011144 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596568.9 | 513530.2 | 88996 | 1.64041666667 | 11144 |
| 011248 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:27pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596570.6 | 513530.3 | 88998 | 1.64041666667 | 11248 |
| 010827 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596572.1 | 513531.4 | 89000 | 1.64041666667 | 10827 |
| 010095 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596574.0 | 513531.9 | 89003 | 1.64041666667 | 10095 |
| 010238 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596573.8 | 513533.0 | 89004 | 1.64041666667 | 10238 |
| 010881 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596571.9 | 513534.0 | 89007 | 1.64041666667 | 10881 |
| 010651 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596571.2 | 513535.4 | 89008 | 1.64041666667 | 10651 |
| 010198 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:33pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596569.5 | 513536.4 | 89010 | 1.64041666667 | 10198 |
| 011136 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596567.9 | 513538.0 | 89012 | 1.64041666667 | 11136 |
| 012129 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596567.2 | 513539.6 | 89014 | 1.64041666667 | 12129 |
| 011637 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596565.4 | 513540.7 | 89016 | 1.64041666667 | 11637 |
| 011173 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:37pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596564.5 | 513542.4 | 89018 | 1.64041666667 | 11173 |
| 010590 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596563.0 | 513543.3 | 89020 | 1.64041666667 | 10590 |
| 010862 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596562.4 | 513545.1 | 89022 | 1.64041666667 | 10862 |
| 012252 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596562.4 | 513546.8 | 89024 | 1.64041666667 | 12252 |
| 011797 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596561.8 | 513549.0 | 89026 | 1.64041666667 | 11797 |
| 010940 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596562.4 | 513550.9 | 89028 | 1.64041666667 | 10940 |
| 011809 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596561.6 | 513553.2 | 89031 | 1.64041666667 | 11809 |
| 012012 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596562.1 | 513554.7 | 89032 | 1.64041666667 | 12012 |
| 012029 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596561.6 | 513556.5 | 89034 | 1.64041666667 | 12029 |
| 012106 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596561.4 | 513558.4 | 89036 | 1.64041666667 | 12106 |
| 011392 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596561.7 | 513560.6 | 89038 | 1.64041666667 | 11392 |
| 011043 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596561.3 | 513562.4 | 89040 | 1.64041666667 | 11043 |
| 011116 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:49pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596561.7 | 513564.5 | 89042 | 1.64041666667 | 11116 |
| 011323 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596560.6 | 513566.3 | 89044 | 1.64041666667 | 11323 |
| 010974 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596560.7 | 513568.4 | 89046 | 1.64041666667 | 10974 |
| 010500 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596560.2 | 513570.2 | 89048 | 1.64041666667 | 10500 |
| 011164 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596559.6 | 513572.1 | 89050 | 1.64041666667 | 11164 |
| 010352 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596559.8 | 513573.6 | 89052 | 1.64041666667 | 10352 |
| 011178 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:55pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596560.4 | 513576.0 | 89054 | 1.64041666667 | 11178 |
| 011147 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596562.0 | 513577.2 | 89056 | 1.64041666667 | 11147 |
| 010103 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596562.8 | 513579.5 | 89058 | 1.64041666667 | 10103 |
| 010003 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596564.3 | 513580.7 | 89060 | 1.64041666667 | 10003 |
| 010846 | 0 | GeoXH 6000 | 08/20/2015 | 01:28:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596565.2 | 513582.4 | 89062 | 1.64041666667 | 10846 |
| 010901 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596565.7 | 513584.2 | 89064 | 1.64041666667 | 10901 |
| 010796 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596566.9 | 513585.6 | 89066 | 1.64041666667 | 10796 |
| 010115 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596566.2 | 513587.1 | 89068 | 1.64041666667 | 10115 |
| 010497 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596566.5 | 513588.8 | 89070 | 1.64041666667 | 10497 |
| 010375 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596565.5 | 513590.9 | 89072 | 1.64041666667 | 10375 |
| 010186 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596564.6 | 513593.4 | 89075 | 1.64041666667 | 10186 |
| 010342 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596564.4 | 513595.3 | 89076 | 1.64041666667 | 10342 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009912 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596562.7 | 513597.0 | 89079 | 1.64041666667 | 9912 |
| 009903 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596562.2 | 513599.0 | 89080 | 1.64041666667 | 9903 |
| 010250 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.1 | 1596560.7 | 513600.5 | 89083 | 1.64041666667 | 10250 |
| 010543 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596559.4 | 513601.8 | 89084 | 1.64041666667 | 10543 |
| 010820 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:11pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596558.0 | 513603.8 | 89086 | 1.64041666667 | 10820 |
| 011239 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596556.3 | 513604.7 | 89088 | 1.64041666667 | 11239 |
| 011234 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596555.8 | 513606.1 | 89090 | 1.64041666667 | 11234 |
| 011666 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596554.8 | 513607.3 | 89092 | 1.64041666667 | 11666 |
| 011625 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596554.5 | 513609.4 | 89094 | 1.64041666667 | 11625 |
| 010964 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596554.6 | 513611.3 | 89096 | 1.64041666667 | 10964 |
| 010285 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596552.8 | 513612.6 | 89098 | 1.64041666667 | 10285 |
| 010367 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596552.8 | 513614.5 | 89100 | 1.64041666667 | 10367 |
| 011674 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596551.2 | 513616.0 | 89102 | 1.64041666667 | 11674 |
| 011276 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596551.0 | 513618.0 | 89104 | 1.64041666667 | 11276 |
| 012133 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596549.5 | 513620.0 | 89106 | 1.64041666667 | 12133 |
| 012615 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596548.9 | 513621.6 | 89108 | 1.64041666667 | 12615 |
| 011303 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:23pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596548.1 | 513623.4 | 89110 | 1.64041666667 | 11303 |
| 011000 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596546.7 | 513625.0 | 89112 | 1.64041666667 | 11000 |
| 011715 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:25pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596546.8 | 513626.9 | 89114 | 1.64041666667 | 11715 |
| 011382 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596545.8 | 513628.6 | 89116 | 1.64041666667 | 11382 |
| 012897 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596545.6 | 513630.5 | 89118 | 1.64041666667 | 12897 |
| 012962 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596544.9 | 513632.3 | 89120 | 1.64041666667 | 12962 |
| 011813 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596544.1 | 513634.1 | 89122 | 1.64041666667 | 11813 |
| 011257 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596543.3 | 513635.7 | 89124 | 1.64041666667 | 11257 |
| 010630 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596542.0 | 513636.7 | 89126 | 1.64041666667 | 10630 |
| 011252 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596541.9 | 513638.5 | 89128 | 1.64041666667 | 11252 |
| 011204 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:33pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596540.8 | 513640.1 | 89130 | 1.64041666667 | 11204 |
| 010982 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596540.0 | 513642.0 | 89132 | 1.64041666667 | 10982 |
| 011172 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596539.5 | 513644.2 | 89134 | 1.64041666667 | 11172 |
| 011227 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:36pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596538.4 | 513644.8 | 89136 | 1.64041666667 | 11227 |
| 011452 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:38pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596538.4 | 513646.8 | 89139 | 1.64041666667 | 11452 |
| 011767 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:38pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596536.9 | 513647.6 | 89140 | 1.64041666667 | 11767 |
| 011396 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:39pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596537.3 | 513649.0 | 89142 | 1.64041666667 | 11396 |
| 011045 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:40pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596538.0 | 513650.5 | 89144 | 1.64041666667 | 11045 |
| 010923 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:42pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596539.3 | 513652.7 | 89147 | 1.64041666667 | 10923 |
| 010524 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:42pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596541.0 | 513653.4 | 89148 | 1.64041666667 | 10524 |
| 010607 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:44pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596541.8 | 513655.2 | 89151 | 1.64041666667 | 10607 |
| 010564 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:44pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596543.1 | 513655.4 | 89152 | 1.64041666667 | 10564 |
| 010134 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:45pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596544.7 | 513655.9 | 89154 | 1.64041666667 | 10134 |
| 009398 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:46pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596545.0 | 513655.1 | 89156 | 1.64041666667 | 9398 |
| 009996 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:47pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596545.6 | 513654.0 | 89158 | 1.64041666667 | 9996 |
| 010243 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:48pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596546.1 | 513652.2 | 89160 | 1.64041666667 | 10243 |
| 010704 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:49pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596545.7 | 513650.5 | 89162 | 1.64041666667 | 10704 |
| 010701 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:50pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596546.2 | 513649.0 | 89164 | 1.64041666667 | 10701 |
| 011089 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:51pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596545.7 | 513646.7 | 89166 | 1.64041666667 | 11089 |
| 010505 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:52pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596546.0 | 513646.4 | 89168 | 1.64041666667 | 10505 |
| 010529 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596546.6 | 513644.7 | 89170 | 1.64041666667 | 10529 |
| 011052 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596548.1 | 513643.2 | 89172 | 1.64041666667 | 11052 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010222 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596547.7 | 513640.6 | 89174 | 1.64041666667 | 10222 |
| 010932 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596548.7 | 513639.4 | 89176 | 1.64041666667 | 10932 |
| 010634 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596548.7 | 513637.4 | 89178 | 1.64041666667 | 10634 |
| 010129 | 0 | GeoXH 6000 | 08/20/2015 | 01:29:58pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596548.9 | 513635.5 | 89180 | 1.64041666667 | 10129 |
| 010235 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596550.3 | 513633.6 | 89183 | 1.64041666667 | 10235 |
| 010557 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596550.5 | 513632.0 | 89184 | 1.64041666667 | 10557 |
| 010326 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596552.1 | 513630.4 | 89187 | 1.64041666667 | 10326 |
| 010458 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596552.7 | 513628.6 | 89188 | 1.64041666667 | 10458 |
| 010773 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596554.4 | 513627.2 | 89190 | 1.64041666667 | 10773 |
| 010987 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596554.7 | 513625.4 | 89192 | 1.64041666667 | 10987 |
| 011340 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596555.7 | 513623.9 | 89194 | 1.64041666667 | 11340 |
| 011088 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596556.3 | 513622.1 | 89196 | 1.64041666667 | 11088 |
| 010670 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596557.9 | 513620.9 | 89199 | 1.64041666667 | 10670 |
| 010757 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596558.6 | 513619.1 | 89200 | 1.64041666667 | 10757 |
| 011150 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596558.9 | 513617.4 | 89202 | 1.64041666667 | 11150 |
| 011747 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596559.9 | 513616.2 | 89204 | 1.64041666667 | 11747 |
| 011377 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596560.3 | 513614.5 | 89207 | 1.64041666667 | 11377 |
| 010967 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596561.8 | 513613.3 | 89208 | 1.64041666667 | 10967 |
| 010961 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596562.0 | 513611.2 | 89211 | 1.64041666667 | 10961 |
| 010958 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596563.6 | 513609.8 | 89212 | 1.64041666667 | 10958 |
| 010919 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596564.8 | 513607.1 | 89215 | 1.64041666667 | 10919 |
| 011189 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596565.7 | 513605.3 | 89216 | 1.64041666667 | 11189 |
| 011079 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596567.7 | 513603.7 | 89219 | 1.64041666667 | 11079 |
| 011354 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596567.8 | 513602.3 | 89220 | 1.64041666667 | 11354 |
| 011606 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596569.1 | 513599.8 | 89223 | 1.64041666667 | 11606 |
| 011696 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596569.6 | 513598.1 | 89224 | 1.64041666667 | 11696 |
| 011214 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:21pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596569.9 | 513595.9 | 89226 | 1.64041666667 | 11214 |
| 010523 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596571.0 | 513594.3 | 89228 | 1.64041666667 | 10523 |
| 010329 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:23pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596571.1 | 513592.5 | 89230 | 1.64041666667 | 10329 |
| 010557 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596572.0 | 513590.7 | 89232 | 1.64041666667 | 10557 |
| 011203 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:25pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596572.5 | 513588.9 | 89234 | 1.64041666667 | 11203 |
| 010907 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596573.5 | 513587.5 | 89236 | 1.64041666667 | 10907 |
| 010770 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:27pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596573.7 | 513585.7 | 89238 | 1.64041666667 | 10770 |
| 011495 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596574.0 | 513584.0 | 89240 | 1.64041666667 | 11495 |
| 011259 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:29pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596573.7 | 513581.2 | 89242 | 1.64041666667 | 11259 |
| 010503 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596572.4 | 513580.0 | 89244 | 1.64041666667 | 10503 |
| 01 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596571.1 | 513577.6 | 89247 | 1.64041666667 | 1 |
| 009985 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596569.8 | 513576.8 | 89248 | 1.64041666667 | 9985 |
| 009772 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:33pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596568.5 | 513574.9 | 89250 | 1.64041666667 | 9772 |
| 010536 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596567.4 | 513573.1 | 89252 | 1.64041666667 | 10536 |
| 010809 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596566.1 | 513571.4 | 89255 | 1.64041666667 | 10809 |
| 010670 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596567.2 | 513569.9 | 89256 | 1.64041666667 | 10670 |
| 010644 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596567.6 | 513567.9 | 89259 | 1.64041666667 | 10644 |
| 010982 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596567.4 | 513566.3 | 89260 | 1.64041666667 | 10982 |
| 010925 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596568.2 | 513564.6 | 89262 | 1.64041666667 | 10925 |
| 010600 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596567.6 | 513563.3 | 89264 | 1.64041666667 | 10600 |
| 010642 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596567.9 | 513561.7 | 89266 | 1.64041666667 | 10642 |
| 010554 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596567.2 | 513560.0 | 89268 | 1.64041666667 | 10554 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011621 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596567.1 | 513557.7 | 89270 | 1.64041666667 | 11621 |
| 011697 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596567.1 | 513556.2 | 89272 | 1.64041666667 | 11697 |
| 011507 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596567.3 | 513554.5 | 89274 | 1.64041666667 | 11507 |
| 011685 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596568.2 | 513552.7 | 89276 | 1.64041666667 | 11685 |
| 011185 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596568.2 | 513551.0 | 89278 | 1.64041666667 | 11185 |
| 011419 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596569.6 | 513549.8 | 89280 | 1.64041666667 | 11419 |
| 011359 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:49pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596569.6 | 513548.2 | 89282 | 1.64041666667 | 11359 |
| 012157 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596570.8 | 513546.9 | 89284 | 1.64041666667 | 12157 |
| 011331 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596570.9 | 513544.9 | 89286 | 1.64041666667 | 11331 |
| 012096 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596572.0 | 513543.9 | 89288 | 1.64041666667 | 12096 |
| 011881 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596572.0 | 513542.0 | 89290 | 1.64041666667 | 11881 |
| 010643 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596573.2 | 513541.0 | 89292 | 1.64041666667 | 10643 |
| 010457 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:55pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596573.4 | 513539.3 | 89294 | 1.64041666667 | 10457 |
| 010569 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596574.1 | 513537.9 | 89296 | 1.64041666667 | 10569 |
| 010963 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596574.7 | 513536.4 | 89298 | 1.64041666667 | 10963 |
| 011176 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596574.6 | 513534.7 | 89300 | 1.64041666667 | 11176 |
| 010396 | 0 | GeoXH 6000 | 08/20/2015 | 01:30:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596575.6 | 513533.6 | 89302 | 1.64041666667 | 10396 |
| 010670 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596575.4 | 513532.5 | 89304 | 1.64041666667 | 10670 |
| 010562 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596575.0 | 513533.1 | 89307 | 1.64041666667 | 10562 |
| 010973 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596575.9 | 513533.4 | 89308 | 1.64041666667 | 10973 |
| 010522 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596577.4 | 513534.1 | 89310 | 1.64041666667 | 10522 |
| 010801 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596579.0 | 513533.7 | 89312 | 1.64041666667 | 10801 |
| 011543 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596580.6 | 513534.8 | 89314 | 1.64041666667 | 11543 |
| 010918 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596582.4 | 513534.8 | 89316 | 1.64041666667 | 10918 |
| 011924 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596583.7 | 513536.1 | 89319 | 1.64041666667 | 11924 |
| 011387 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596585.0 | 513536.3 | 89320 | 1.64041666667 | 11387 |
| 011032 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596585.1 | 513537.2 | 89323 | 1.64041666667 | 11032 |
| 010871 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596583.8 | 513537.9 | 89324 | 1.64041666667 | 10871 |
| 010435 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:11pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596582.9 | 513539.9 | 89326 | 1.64041666667 | 10435 |
| 010917 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596581.3 | 513541.3 | 89328 | 1.64041666667 | 10917 |
| 010843 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:13pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596579.3 | 513543.3 | 89330 | 1.64041666667 | 10843 |
| 011694 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596578.9 | 513545.1 | 89332 | 1.64041666667 | 11694 |
| 011768 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:15pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596577.2 | 513546.6 | 89334 | 1.64041666667 | 11768 |
| 012417 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596576.6 | 513548.6 | 89336 | 1.64041666667 | 12417 |
| 011919 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:17pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596575.3 | 513550.3 | 89338 | 1.64041666667 | 11919 |
| 010852 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596574.8 | 513552.1 | 89340 | 1.64041666667 | 10852 |
| 010469 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596574.7 | 513554.7 | 89343 | 1.64041666667 | 10469 |
| 011086 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596574.3 | 513556.4 | 89344 | 1.64041666667 | 11086 |
| 010916 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596575.2 | 513558.3 | 89347 | 1.64041666667 | 10916 |
| 010257 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596574.4 | 513559.7 | 89348 | 1.64041666667 | 10257 |
| 010772 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596574.8 | 513561.7 | 89351 | 1.64041666667 | 10772 |
| 010267 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596573.9 | 513562.9 | 89352 | 1.64041666667 | 10267 |
| 010552 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596574.3 | 513564.7 | 89354 | 1.64041666667 | 10552 |
| 010188 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596573.3 | 513566.1 | 89356 | 1.64041666667 | 10188 |
| 011108 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:27pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596572.8 | 513568.4 | 89358 | 1.64041666667 | 11108 |
| 011206 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596573.9 | 513570.0 | 89360 | 1.64041666667 | 11206 |
| 010503 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596574.6 | 513572.2 | 89362 | 1.64041666667 | 10503 |
| 011353 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596575.9 | 513573.6 | 89364 | 1.64041666667 | 11353 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011223 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596576.4 | 513575.6 | 89366 | 1.64041666667 | 11223 |
| 010498 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596577.0 | 513577.5 | 89368 | 1.64041666667 | 10498 |
| 011403 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596578.4 | 513578.8 | 89370 | 1.64041666667 | 11403 |
| 010606 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596578.5 | 513580.6 | 89372 | 1.64041666667 | 10606 |
| 010668 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596580.2 | 513581.9 | 89374 | 1.64041666667 | 10668 |
| 011243 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596580.1 | 513583.2 | 89376 | 1.64041666667 | 11243 |
| 010367 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:37pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596580.2 | 513585.7 | 89378 | 1.64041666667 | 10367 |
| 010654 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596579.4 | 513587.0 | 89380 | 1.64041666667 | 10654 |
| 010747 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596578.8 | 513589.1 | 89382 | 1.64041666667 | 10747 |
| 010830 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596578.8 | 513590.6 | 89384 | 1.64041666667 | 10830 |
| 011072 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596577.8 | 513592.6 | 89386 | 1.64041666667 | 11072 |
| 011613 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596577.9 | 513594.4 | 89388 | 1.64041666667 | 11613 |
| 011625 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596576.9 | 513596.2 | 89390 | 1.64041666667 | 11625 |
| 011211 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596577.0 | 513598.0 | 89392 | 1.64041666667 | 11211 |
| 010574 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596576.5 | 513600.6 | 89394 | 1.64041666667 | 10574 |
| 011010 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596575.1 | 513602.2 | 89396 | 1.64041666667 | 11010 |
| 010903 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596575.0 | 513604.2 | 89398 | 1.64041666667 | 10903 |
| 010535 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596573.6 | 513604.9 | 89400 | 1.64041666667 | 10535 |
| 011011 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:49pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596573.7 | 513606.6 | 89402 | 1.64041666667 | 11011 |
| 010791 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596573.6 | 513607.2 | 89404 | 1.64041666667 | 10791 |
| 010922 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596572.5 | 513606.1 | 89406 | 1.64041666667 | 10922 |
| 010449 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596572.9 | 513606.4 | 89408 | 1.64041666667 | 10449 |
| 010115 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596573.6 | 513606.4 | 89410 | 1.64041666667 | 10115 |
| 010077 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596572.6 | 513605.9 | 89412 | 1.64041666667 | 10077 |
| 010236 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:55pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596573.7 | 513606.4 | 89414 | 1.64041666667 | 10236 |
| 010857 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596573.4 | 513606.5 | 89416 | 1.64041666667 | 10857 |
| 011192 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596572.8 | 513606.4 | 89418 | 1.64041666667 | 11192 |
| 011201 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596572.0 | 513607.6 | 89420 | 1.64041666667 | 11201 |
| 010755 | 0 | GeoXH 6000 | 08/20/2015 | 01:31:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596570.8 | 513609.0 | 89422 | 1.64041666667 | 10755 |
| 010550 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596569.2 | 513610.7 | 89424 | 1.64041666667 | 10550 |
| 010164 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596569.5 | 513613.0 | 89426 | 1.64041666667 | 10164 |
| 010652 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596568.2 | 513614.1 | 89428 | 1.64041666667 | 10652 |
| 010807 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596567.7 | 513616.1 | 89430 | 1.64041666667 | 10807 |
| 010646 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596566.3 | 513616.7 | 89432 | 1.64041666667 | 10646 |
| 010466 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596566.0 | 513617.8 | 89434 | 1.64041666667 | 10466 |
| 011182 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596564.8 | 513618.5 | 89436 | 1.64041666667 | 11182 |
| 010737 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596564.0 | 513619.8 | 89439 | 1.64041666667 | 10737 |
| 009857 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596563.0 | 513619.7 | 89440 | 1.64041666667 | 9857 |
| 010524 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596561.8 | 513620.0 | 89443 | 1.64041666667 | 10524 |
| 010855 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596561.3 | 513620.7 | 89444 | 1.64041666667 | 10855 |
| 010598 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596559.3 | 513621.4 | 89446 | 1.64041666667 | 10598 |
| 010896 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596558.4 | 513622.7 | 89448 | 1.64041666667 | 10896 |
| 010906 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596555.9 | 513623.1 | 89451 | 1.64041666667 | 10906 |
| 010335 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596554.9 | 513624.4 | 89452 | 1.64041666667 | 10335 |
| 010351 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596552.9 | 513625.4 | 89454 | 1.64041666667 | 10351 |
| 010892 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596552.5 | 513626.9 | 89456 | 1.64041666667 | 10892 |
| 010559 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596551.8 | 513628.7 | 89458 | 1.64041666667 | 10559 |
| 011302 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596550.4 | 513630.1 | 89460 | 1.64041666667 | 11302 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011112 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596550.3 | 513631.8 | 89462 | 1.64041666667 | 11112 |
| 012573 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596549.9 | 513631.5 | 89464 | 1.64041666667 | 12573 |
| 011610 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596550.1 | 513633.2 | 89467 | 1.64041666667 | 11610 |
| 010693 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596550.4 | 513633.9 | 89468 | 1.64041666667 | 10693 |
| 010305 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596551.6 | 513635.4 | 89471 | 1.64041666667 | 10305 |
| 009876 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596553.2 | 513636.4 | 89472 | 1.64041666667 | 9876 |
| 010565 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596553.1 | 513638.0 | 89474 | 1.64041666667 | 10565 |
| 010368 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596552.9 | 513639.6 | 89476 | 1.64041666667 | 10368 |
| 010384 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596551.6 | 513640.6 | 89478 | 1.64041666667 | 10384 |
| 009816 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596550.0 | 513641.5 | 89480 | 1.64041666667 | 9816 |
| 010959 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596548.9 | 513643.4 | 89482 | 1.64041666667 | 10959 |
| 011234 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596548.1 | 513644.5 | 89484 | 1.64041666667 | 11234 |
| 011306 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596547.7 | 513646.2 | 89486 | 1.64041666667 | 11306 |
| 011557 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596548.5 | 513648.1 | 89488 | 1.64041666667 | 11557 |
| 011076 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596548.5 | 513649.9 | 89491 | 1.64041666667 | 11076 |
| 010595 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596549.6 | 513651.5 | 89492 | 1.64041666667 | 10595 |
| 010557 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:35pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596549.0 | 513653.2 | 89494 | 1.64041666667 | 10557 |
| 010723 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:36pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596549.3 | 513654.8 | 89496 | 1.64041666667 | 10723 |
| 010704 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:37pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596548.4 | 513656.1 | 89498 | 1.64041666667 | 10704 |
| 009688 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596548.1 | 513657.3 | 89500 | 1.64041666667 | 9688 |
| 010280 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:39pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596548.0 | 513658.7 | 89502 | 1.64041666667 | 10280 |
| 011235 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596548.4 | 513660.3 | 89504 | 1.64041666667 | 11235 |
| 011779 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596549.0 | 513660.4 | 89506 | 1.64041666667 | 11779 |
| 011336 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596549.5 | 513660.4 | 89508 | 1.64041666667 | 11336 |
| 010876 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596550.3 | 513659.3 | 89510 | 1.64041666667 | 10876 |
| 010933 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:44pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596551.6 | 513659.3 | 89512 | 1.64041666667 | 10933 |
| 011175 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:45pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596553.4 | 513659.4 | 89514 | 1.64041666667 | 11175 |
| 011168 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596555.1 | 513659.6 | 89516 | 1.64041666667 | 11168 |
| 010917 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596557.4 | 513661.0 | 89518 | 1.64041666667 | 10917 |
| 011241 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596557.2 | 513659.8 | 89520 | 1.64041666667 | 11241 |
| 010763 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596557.7 | 513658.0 | 89522 | 1.64041666667 | 10763 |
| 010636 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596558.0 | 513656.6 | 89524 | 1.64041666667 | 10636 |
| 011503 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:51pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596558.1 | 513655.3 | 89526 | 1.64041666667 | 11503 |
| 010700 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596558.8 | 513653.8 | 89528 | 1.64041666667 | 10700 |
| 011403 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596558.4 | 513651.8 | 89530 | 1.64041666667 | 11403 |
| 011522 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596559.8 | 513650.1 | 89532 | 1.64041666667 | 11522 |
| 011236 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596559.8 | 513647.9 | 89534 | 1.64041666667 | 11236 |
| 011000 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596560.3 | 513646.2 | 89536 | 1.64041666667 | 11000 |
| 010440 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596560.7 | 513643.9 | 89538 | 1.64041666667 | 10440 |
| 009750 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:58pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596560.3 | 513642.5 | 89540 | 1.64041666667 | 9750 |
| 009804 | 0 | GeoXH 6000 | 08/20/2015 | 01:32:59pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596560.8 | 513640.5 | 89542 | 1.64041666667 | 9804 |
| 009812 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596560.4 | 513639.0 | 89544 | 1.64041666667 | 9812 |
| 009322 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:01pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596561.8 | 513637.1 | 89546 | 1.64041666667 | 9322 |
| 010298 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596562.2 | 513635.0 | 89548 | 1.64041666667 | 10298 |
| 010878 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596562.2 | 513633.1 | 89550 | 1.64041666667 | 10878 |
| 010641 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596563.6 | 513631.8 | 89552 | 1.64041666667 | 10641 |
| 010733 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596564.2 | 513630.3 | 89554 | 1.64041666667 | 10733 |
| 010605 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596565.2 | 513629.2 | 89556 | 1.64041666667 | 10605 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010645 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596567.1 | 513628.3 | 89558 | 1.64041666667 | 10645 |
| 011223 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596567.6 | 513626.7 | 89560 | 1.64041666667 | 11223 |
| 011090 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596569.3 | 513625.9 | 89562 | 1.64041666667 | 11090 |
| 010933 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596571.0 | 513624.3 | 89564 | 1.64041666667 | 10933 |
| 010687 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596572.0 | 513622.6 | 89567 | 1.64041666667 | 10687 |
| 011209 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596573.5 | 513621.0 | 89568 | 1.64041666667 | 11209 |
| 011487 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:13pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596574.1 | 513619.1 | 89570 | 1.64041666667 | 11487 |
| 011261 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596575.7 | 513618.0 | 89572 | 1.64041666667 | 11261 |
| 011974 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:15pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596576.0 | 513616.0 | 89574 | 1.64041666667 | 11974 |
| 011783 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596576.8 | 513614.3 | 89576 | 1.64041666667 | 11783 |
| 011338 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:17pm | Sensor | 1797-S0054-905-G-ACK | 6850.2 | 1596578.0 | 513612.0 | 89578 | 1.64041666667 | 11338 |
| 010945 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596578.7 | 513610.0 | 89580 | 1.64041666667 | 10945 |
| 011744 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:19pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596580.2 | 513608.2 | 89582 | 1.64041666667 | 11744 |
| 010888 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596580.2 | 513606.9 | 89584 | 1.64041666667 | 10888 |
| 011142 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:21pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596580.5 | 513605.9 | 89586 | 1.64041666667 | 11142 |
| 011420 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596581.3 | 513605.1 | 89588 | 1.64041666667 | 11420 |
| 011066 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:23pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596582.5 | 513603.5 | 89590 | 1.64041666667 | 11066 |
| 011310 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596582.7 | 513601.6 | 89592 | 1.64041666667 | 11310 |
| 011146 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:25pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596584.4 | 513599.8 | 89594 | 1.64041666667 | 11146 |
| 011370 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596584.5 | 513597.9 | 89596 | 1.64041666667 | 11370 |
| 011143 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:27pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596585.2 | 513596.0 | 89598 | 1.64041666667 | 11143 |
| 011323 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596585.8 | 513593.8 | 89600 | 1.64041666667 | 11323 |
| 010479 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:29pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596585.2 | 513591.6 | 89602 | 1.64041666667 | 10479 |
| 010792 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596586.2 | 513589.5 | 89604 | 1.64041666667 | 10792 |
| 010893 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596585.9 | 513587.3 | 89606 | 1.64041666667 | 10893 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596586.2 | 513585.6 | 89608 | 1.64041666667 | 11205 |
| 011485 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:33pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596586.6 | 513583.1 | 89610 | 1.64041666667 | 11485 |
| 011275 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596585.9 | 513581.5 | 89612 | 1.64041666667 | 11275 |
| 011584 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596586.5 | 513579.3 | 89614 | 1.64041666667 | 11584 |
| 012014 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596586.0 | 513577.5 | 89616 | 1.64041666667 | 12014 |
| 011947 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:37pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596584.9 | 513575.7 | 89618 | 1.64041666667 | 11947 |
| 012233 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596584.3 | 513573.7 | 89620 | 1.64041666667 | 12233 |
| 011508 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:39pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596583.0 | 513571.9 | 89622 | 1.64041666667 | 11508 |
| 011356 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596583.1 | 513570.1 | 89624 | 1.64041666667 | 11356 |
| 012012 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596581.9 | 513568.3 | 89626 | 1.64041666667 | 12012 |
| 011767 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596582.0 | 513566.5 | 89628 | 1.64041666667 | 11767 |
| 011779 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596581.8 | 513564.8 | 89630 | 1.64041666667 | 11779 |
| 011080 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596581.4 | 513563.4 | 89632 | 1.64041666667 | 11080 |
| 010957 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596581.1 | 513560.8 | 89634 | 1.64041666667 | 10957 |
| 011128 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596579.8 | 513559.7 | 89636 | 1.64041666667 | 11128 |
| 011142 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596579.8 | 513557.2 | 89638 | 1.64041666667 | 11142 |
| 010512 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596578.8 | 513555.7 | 89640 | 1.64041666667 | 10512 |
| 010278 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:49pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596578.8 | 513554.0 | 89642 | 1.64041666667 | 10278 |
| 010701 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596578.3 | 513553.4 | 89644 | 1.64041666667 | 10701 |
| 011142 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596578.7 | 513553.3 | 89646 | 1.64041666667 | 11142 |
| 011277 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596580.0 | 513552.2 | 89648 | 1.64041666667 | 11277 |
| 010911 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596581.8 | 513551.6 | 89650 | 1.64041666667 | 10911 |
| 010795 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596583.2 | 513550.0 | 89652 | 1.64041666667 | 10795 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010362 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:55pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596583.7 | 513548.2 | 89654 | 1.64041666667 | 10362 |
| 010051 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596585.5 | 513547.1 | 89656 | 1.64041666667 | 10051 |
| 010116 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596586.3 | 513545.0 | 89658 | 1.64041666667 | 10116 |
| 010603 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596587.5 | 513543.7 | 89660 | 1.64041666667 | 10603 |
| 010419 | 0 | GeoXH 6000 | 08/20/2015 | 01:33:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596588.8 | 513542.3 | 89662 | 1.64041666667 | 10419 |
| 010863 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596589.4 | 513540.8 | 89664 | 1.64041666667 | 10863 |
| 011675 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:01pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596590.5 | 513539.9 | 89666 | 1.64041666667 | 11675 |
| 012552 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596591.2 | 513539.3 | 89668 | 1.64041666667 | 12552 |
| 011733 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596590.4 | 513539.3 | 89671 | 1.64041666667 | 11733 |
| 011700 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596590.3 | 513539.3 | 89672 | 1.64041666667 | 11700 |
| 011786 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596590.0 | 513539.3 | 89674 | 1.64041666667 | 11786 |
| 012067 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596591.1 | 513539.5 | 89676 | 1.64041666667 | 12067 |
| 011940 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596592.5 | 513540.9 | 89678 | 1.64041666667 | 11940 |
| 011568 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596594.6 | 513541.8 | 89680 | 1.64041666667 | 11568 |
| 011922 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596596.2 | 513543.9 | 89682 | 1.64041666667 | 11922 |
| 010824 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596597.7 | 513544.5 | 89684 | 1.64041666667 | 10824 |
| 011061 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596597.2 | 513545.0 | 89686 | 1.64041666667 | 11061 |
| 010691 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596597.4 | 513546.5 | 89688 | 1.64041666667 | 10691 |
| 010859 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596596.4 | 513547.9 | 89690 | 1.64041666667 | 10859 |
| 010945 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596596.8 | 513549.0 | 89692 | 1.64041666667 | 10945 |
| 010807 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:15pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596595.6 | 513549.6 | 89694 | 1.64041666667 | 10807 |
| 011006 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596595.5 | 513550.7 | 89696 | 1.64041666667 | 11006 |
| 012048 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:17pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596594.3 | 513551.4 | 89698 | 1.64041666667 | 12048 |
| 012784 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596594.0 | 513552.7 | 89700 | 1.64041666667 | 12784 |
| 012171 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:19pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596592.9 | 513554.1 | 89702 | 1.64041666667 | 12171 |
| 011519 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596592.2 | 513555.5 | 89704 | 1.64041666667 | 11519 |
| 011549 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:21pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596590.3 | 513556.1 | 89706 | 1.64041666667 | 11549 |
| 012061 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596589.3 | 513557.5 | 89708 | 1.64041666667 | 12061 |
| 011419 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596588.4 | 513558.8 | 89710 | 1.64041666667 | 11419 |
| 011013 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596587.9 | 513559.8 | 89712 | 1.64041666667 | 11013 |
| 010927 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596587.1 | 513560.8 | 89714 | 1.64041666667 | 10927 |
| 011786 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596586.8 | 513562.8 | 89716 | 1.64041666667 | 11786 |
| 010965 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596587.7 | 513564.8 | 89718 | 1.64041666667 | 10965 |
| 011268 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596587.8 | 513566.3 | 89720 | 1.64041666667 | 11268 |
| 011700 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596588.8 | 513568.0 | 89722 | 1.64041666667 | 11700 |
| 011524 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596588.7 | 513569.8 | 89724 | 1.64041666667 | 11524 |
| 011327 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596589.6 | 513571.5 | 89726 | 1.64041666667 | 11327 |
| 010999 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596589.1 | 513573.1 | 89728 | 1.64041666667 | 10999 |
| 010934 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596590.3 | 513574.9 | 89730 | 1.64041666667 | 10934 |
| 011423 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596591.4 | 513576.7 | 89732 | 1.64041666667 | 11423 |
| 011180 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596592.2 | 513578.4 | 89734 | 1.64041666667 | 11180 |
| 010631 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596593.4 | 513580.1 | 89736 | 1.64041666667 | 10631 |
| 011230 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:37pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596593.4 | 513582.4 | 89738 | 1.64041666667 | 11230 |
| 010937 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596594.5 | 513584.0 | 89740 | 1.64041666667 | 10937 |
| 011709 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596594.2 | 513586.6 | 89743 | 1.64041666667 | 11709 |
| 010891 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596594.3 | 513588.2 | 89744 | 1.64041666667 | 10891 |
| 010746 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596594.7 | 513590.8 | 89746 | 1.64041666667 | 10746 |
| 011017 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596593.7 | 513592.1 | 89748 | 1.64041666667 | 11017 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010892 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596593.9 | 513593.0 | 89750 | 1.64041666667 | 10892 |
| 011114 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596594.3 | 513593.6 | 89752 | 1.64041666667 | 11114 |
| 011209 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596593.7 | 513593.4 | 89754 | 1.64041666667 | 11209 |
| 010865 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596593.7 | 513593.2 | 89756 | 1.64041666667 | 10865 |
| 010214 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596593.6 | 513593.3 | 89758 | 1.64041666667 | 10214 |
| 010755 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596593.8 | 513593.5 | 89760 | 1.64041666667 | 10755 |
| 011150 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596594.1 | 513594.1 | 89762 | 1.64041666667 | 11150 |
| 011266 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596592.8 | 513594.9 | 89764 | 1.64041666667 | 11266 |
| 010792 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596592.3 | 513596.7 | 89766 | 1.64041666667 | 10792 |
| 010998 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596591.7 | 513598.4 | 89768 | 1.64041666667 | 10998 |
| 011384 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596590.4 | 513600.7 | 89770 | 1.64041666667 | 11384 |
| 012366 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596590.3 | 513602.6 | 89772 | 1.64041666667 | 12366 |
| 011838 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596588.8 | 513604.6 | 89775 | 1.64041666667 | 11838 |
| 012201 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596588.7 | 513606.5 | 89776 | 1.64041666667 | 12201 |
| 011220 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596587.2 | 513608.3 | 89778 | 1.64041666667 | 11220 |
| 011846 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596586.2 | 513610.0 | 89780 | 1.64041666667 | 11846 |
| 011238 | 0 | GeoXH 6000 | 08/20/2015 | 01:34:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596585.8 | 513612.4 | 89782 | 1.64041666667 | 11238 |
| 011804 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596584.4 | 513613.9 | 89784 | 1.64041666667 | 11804 |
| 012032 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596584.1 | 513616.0 | 89786 | 1.64041666667 | 12032 |
| 011965 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596582.8 | 513617.5 | 89788 | 1.64041666667 | 11965 |
| 011328 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596581.4 | 513619.4 | 89790 | 1.64041666667 | 11328 |
| 011592 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596581.0 | 513621.4 | 89792 | 1.64041666667 | 11592 |
| 011245 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596579.6 | 513623.4 | 89794 | 1.64041666667 | 11245 |
| 011410 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596579.3 | 513625.5 | 89796 | 1.64041666667 | 11410 |
| 010791 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:07pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596578.1 | 513627.6 | 89798 | 1.64041666667 | 10791 |
| 011942 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596576.6 | 513629.2 | 89800 | 1.64041666667 | 11942 |
| 011007 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596575.0 | 513631.1 | 89802 | 1.64041666667 | 11007 |
| 010631 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596573.5 | 513631.9 | 89804 | 1.64041666667 | 10631 |
| 010150 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596572.3 | 513633.5 | 89806 | 1.64041666667 | 10150 |
| 010652 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596570.9 | 513634.6 | 89808 | 1.64041666667 | 10652 |
| 011437 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596569.4 | 513635.9 | 89810 | 1.64041666667 | 11437 |
| 010603 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596568.4 | 513637.8 | 89812 | 1.64041666667 | 10603 |
| 010584 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596566.6 | 513639.7 | 89814 | 1.64041666667 | 10584 |
| 011083 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596565.7 | 513641.5 | 89816 | 1.64041666667 | 11083 |
| 011102 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596565.1 | 513643.6 | 89818 | 1.64041666667 | 11102 |
| 010887 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596564.6 | 513645.3 | 89820 | 1.64041666667 | 10887 |
| 011284 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596565.2 | 513647.4 | 89822 | 1.64041666667 | 11284 |
| 011492 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596565.0 | 513649.1 | 89824 | 1.64041666667 | 11492 |
| 011497 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596564.1 | 513650.5 | 89826 | 1.64041666667 | 11497 |
| 011724 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596563.9 | 513652.6 | 89828 | 1.64041666667 | 11724 |
| 011335 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596562.4 | 513653.6 | 89830 | 1.64041666667 | 11335 |
| 010576 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596560.9 | 513655.0 | 89832 | 1.64041666667 | 10576 |
| 011754 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596560.1 | 513657.0 | 89834 | 1.64041666667 | 11754 |
| 011245 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596559.0 | 513658.3 | 89836 | 1.64041666667 | 11245 |
| 011128 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:27pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596558.3 | 513660.9 | 89838 | 1.64041666667 | 11128 |
| 011292 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596556.6 | 513662.5 | 89840 | 1.64041666667 | 11292 |
| 010829 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:29pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596555.3 | 513664.4 | 89842 | 1.64041666667 | 10829 |
| 011169 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596554.3 | 513665.6 | 89844 | 1.64041666667 | 11169 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011720 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:31pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596553.3 | 513667.8 | 89846 | 1.64041666667 | 11720 |
| 012240 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596553.9 | 513669.4 | 89848 | 1.64041666667 | 12240 |
| 011820 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:33pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596553.9 | 513671.9 | 89850 | 1.64041666667 | 11820 |
| 012333 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596555.5 | 513673.1 | 89852 | 1.64041666667 | 12333 |
| 012142 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596556.8 | 513674.7 | 89854 | 1.64041666667 | 12142 |
| 011817 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596558.2 | 513676.2 | 89856 | 1.64041666667 | 11817 |
| 011672 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:37pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596560.2 | 513676.2 | 89858 | 1.64041666667 | 11672 |
| 011756 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596562.1 | 513676.8 | 89860 | 1.64041666667 | 11756 |
| 011712 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596563.7 | 513675.6 | 89862 | 1.64041666667 | 11712 |
| 011403 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596563.6 | 513674.0 | 89864 | 1.64041666667 | 11403 |
| 010757 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596564.7 | 513672.1 | 89866 | 1.64041666667 | 10757 |
| 010933 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596564.5 | 513670.4 | 89868 | 1.64041666667 | 10933 |
| 011655 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596565.1 | 513668.2 | 89870 | 1.64041666667 | 11655 |
| 011071 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596566.2 | 513666.2 | 89872 | 1.64041666667 | 11071 |
| 011567 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596566.4 | 513663.7 | 89874 | 1.64041666667 | 11567 |
| 011036 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596567.5 | 513662.1 | 89876 | 1.64041666667 | 11036 |
| 010513 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596568.3 | 513660.1 | 89878 | 1.64041666667 | 10513 |
| 011366 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596568.8 | 513658.0 | 89880 | 1.64041666667 | 11366 |
| 011171 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:49pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596570.3 | 513656.2 | 89882 | 1.64041666667 | 11171 |
| 011121 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596571.0 | 513653.9 | 89884 | 1.64041666667 | 11121 |
| 010875 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596572.1 | 513651.5 | 89887 | 1.64041666667 | 10875 |
| 011330 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596573.5 | 513649.8 | 89888 | 1.64041666667 | 11330 |
| 010880 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596573.7 | 513647.4 | 89890 | 1.64041666667 | 10880 |
| 010980 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596574.6 | 513646.2 | 89892 | 1.64041666667 | 10980 |
| 010833 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596575.7 | 513643.9 | 89894 | 1.64041666667 | 10833 |
| 010946 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596576.3 | 513642.1 | 89896 | 1.64041666667 | 10946 |
| 010905 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596577.9 | 513640.0 | 89899 | 1.64041666667 | 10905 |
| 010806 | 0 | GeoXH 6000 | 08/20/2015 | 01:35:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596578.9 | 513638.1 | 89900 | 1.64041666667 | 10806 |
| 010608 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596579.3 | 513636.0 | 89903 | 1.64041666667 | 10608 |
| 011044 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596580.5 | 513634.8 | 89904 | 1.64041666667 | 11044 |
| 011657 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596581.8 | 513633.0 | 89906 | 1.64041666667 | 11657 |
| 010997 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596582.6 | 513631.4 | 89908 | 1.64041666667 | 10997 |
| 011496 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596584.6 | 513629.9 | 89910 | 1.64041666667 | 11496 |
| 011341 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596585.0 | 513628.1 | 89912 | 1.64041666667 | 11341 |
| 010902 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596586.8 | 513626.6 | 89914 | 1.64041666667 | 10902 |
| 010610 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596588.4 | 513625.3 | 89916 | 1.64041666667 | 10610 |
| 010745 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:07pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596589.1 | 513623.4 | 89918 | 1.64041666667 | 10745 |
| 010994 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596590.5 | 513621.6 | 89920 | 1.64041666667 | 10994 |
| 011149 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:09pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596591.3 | 513619.5 | 89922 | 1.64041666667 | 11149 |
| 011131 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596591.9 | 513617.3 | 89924 | 1.64041666667 | 11131 |
| 010431 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596593.2 | 513615.6 | 89926 | 1.64041666667 | 10431 |
| 010915 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596593.7 | 513613.7 | 89928 | 1.64041666667 | 10915 |
| 010789 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596594.7 | 513611.2 | 89930 | 1.64041666667 | 10789 |
| 011154 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596595.9 | 513609.2 | 89932 | 1.64041666667 | 11154 |
| 012311 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596596.1 | 513607.1 | 89934 | 1.64041666667 | 12311 |
| 013443 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596596.3 | 513605.4 | 89936 | 1.64041666667 | 13443 |
| 012721 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596597.7 | 513603.3 | 89938 | 1.64041666667 | 12721 |
| 011895 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596598.2 | 513601.2 | 89940 | 1.64041666667 | 11895 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011056 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596598.7 | 513598.6 | 89942 | 1.64041666667 | 11056 |
| 010614 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596599.6 | 513597.1 | 89944 | 1.64041666667 | 10614 |
| 010815 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596599.4 | 513595.0 | 89946 | 1.64041666667 | 10815 |
| 012083 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596600.0 | 513593.1 | 89948 | 1.64041666667 | 12083 |
| 012069 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596599.9 | 513590.7 | 89950 | 1.64041666667 | 12069 |
| 011589 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596599.2 | 513588.7 | 89952 | 1.64041666667 | 11589 |
| 011753 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596599.1 | 513586.6 | 89954 | 1.64041666667 | 11753 |
| 011201 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596598.5 | 513585.0 | 89956 | 1.64041666667 | 11201 |
| 010493 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596599.3 | 513582.9 | 89958 | 1.64041666667 | 10493 |
| 010440 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596599.1 | 513581.0 | 89960 | 1.64041666667 | 10440 |
| 010515 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596598.2 | 513578.6 | 89962 | 1.64041666667 | 10515 |
| 010317 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596598.4 | 513576.8 | 89964 | 1.64041666667 | 10317 |
| 010453 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596597.6 | 513575.5 | 89967 | 1.64041666667 | 10453 |
| 010740 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596598.1 | 513573.6 | 89968 | 1.64041666667 | 10740 |
| 010541 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596598.0 | 513571.2 | 89970 | 1.64041666667 | 10541 |
| 010894 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596597.0 | 513569.7 | 89972 | 1.64041666667 | 10894 |
| 010958 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596596.7 | 513567.5 | 89974 | 1.64041666667 | 10958 |
| 010814 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596596.6 | 513566.2 | 89976 | 1.64041666667 | 10814 |
| 011212 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:37pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596596.4 | 513564.3 | 89978 | 1.64041666667 | 11212 |
| 010702 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596597.4 | 513562.8 | 89980 | 1.64041666667 | 10702 |
| 012440 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596597.3 | 513560.8 | 89982 | 1.64041666667 | 12440 |
| 012532 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596597.9 | 513559.1 | 89984 | 1.64041666667 | 12532 |
| 011572 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596599.2 | 513557.0 | 89986 | 1.64041666667 | 11572 |
| 010469 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596599.7 | 513555.1 | 89988 | 1.64041666667 | 10469 |
| 011319 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596600.6 | 513553.1 | 89990 | 1.64041666667 | 11319 |
| 011422 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596601.7 | 513551.6 | 89992 | 1.64041666667 | 11422 |
| 010887 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596601.9 | 513549.8 | 89994 | 1.64041666667 | 10887 |
| 011621 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596602.9 | 513548.7 | 89996 | 1.64041666667 | 11621 |
| 011374 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:47pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596604.9 | 513549.3 | 89998 | 1.64041666667 | 11374 |
| 011265 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596606.8 | 513550.0 | 90000 | 1.64041666667 | 11265 |
| 011309 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596608.3 | 513551.1 | 90002 | 1.64041666667 | 11309 |
| 011679 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596609.5 | 513552.1 | 90004 | 1.64041666667 | 11679 |
| 011062 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:51pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596610.8 | 513552.7 | 90006 | 1.64041666667 | 11062 |
| 010579 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596610.9 | 513552.9 | 90008 | 1.64041666667 | 10579 |
| 010953 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596609.2 | 513553.8 | 90010 | 1.64041666667 | 10953 |
| 011343 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596609.3 | 513555.2 | 90012 | 1.64041666667 | 11343 |
| 011083 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596608.2 | 513557.5 | 90014 | 1.64041666667 | 11083 |
| 010832 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596607.8 | 513559.7 | 90016 | 1.64041666667 | 10832 |
| 010795 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596607.9 | 513562.3 | 90018 | 1.64041666667 | 10795 |
| 010580 | 0 | GeoXH 6000 | 08/20/2015 | 01:36:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596606.9 | 513564.4 | 90020 | 1.64041666667 | 10580 |
| 010038 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596606.7 | 513566.7 | 90023 | 1.64041666667 | 10038 |
| 010694 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596606.1 | 513568.5 | 90024 | 1.64041666667 | 10694 |
| 010605 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596605.2 | 513571.1 | 90026 | 1.64041666667 | 10605 |
| 011823 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596605.3 | 513572.8 | 90028 | 1.64041666667 | 11823 |
| 010888 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596605.0 | 513575.4 | 90030 | 1.64041666667 | 10888 |
| 010211 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596605.6 | 513576.8 | 90032 | 1.64041666667 | 10211 |
| 010124 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596605.9 | 513578.5 | 90034 | 1.64041666667 | 10124 |
| 009993 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596605.9 | 513580.6 | 90036 | 1.64041666667 | 9993 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010202 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596606.3 | 513582.8 | 90038 | 1.64041666667 | 10202 |
| 010779 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596605.8 | 513585.1 | 90040 | 1.64041666667 | 10779 |
| 011230 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596605.7 | 513587.5 | 90042 | 1.64041666667 | 11230 |
| 011079 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596605.7 | 513589.7 | 90044 | 1.64041666667 | 11079 |
| 011482 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596604.7 | 513592.0 | 90046 | 1.64041666667 | 11482 |
| 011048 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596604.6 | 513594.0 | 90048 | 1.64041666667 | 11048 |
| 010804 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596605.1 | 513597.0 | 90050 | 1.64041666667 | 10804 |
| 010990 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596604.7 | 513599.5 | 90052 | 1.64041666667 | 10990 |
| 010944 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596604.9 | 513601.2 | 90054 | 1.64041666667 | 10944 |
| 011879 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596604.7 | 513603.1 | 90056 | 1.64041666667 | 11879 |
| 011467 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596603.7 | 513605.4 | 90058 | 1.64041666667 | 11467 |
| 011422 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596604.0 | 513607.2 | 90060 | 1.64041666667 | 11422 |
| 011292 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596603.3 | 513609.2 | 90062 | 1.64041666667 | 11292 |
| 010672 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596602.3 | 513611.3 | 90064 | 1.64041666667 | 10672 |
| 011043 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596602.0 | 513613.8 | 90066 | 1.64041666667 | 11043 |
| 011866 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596600.7 | 513615.5 | 90068 | 1.64041666667 | 11866 |
| 011715 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596599.8 | 513617.7 | 90070 | 1.64041666667 | 11715 |
| 011344 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596599.0 | 513619.7 | 90072 | 1.64041666667 | 11344 |
| 010994 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596597.5 | 513621.5 | 90074 | 1.64041666667 | 10994 |
| 011539 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596597.0 | 513623.3 | 90076 | 1.64041666667 | 11539 |
| 010518 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596595.9 | 513625.0 | 90078 | 1.64041666667 | 10518 |
| 010866 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596594.4 | 513626.4 | 90080 | 1.64041666667 | 10866 |
| 010965 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596593.2 | 513628.6 | 90082 | 1.64041666667 | 10965 |
| 011297 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596592.1 | 513630.6 | 90084 | 1.64041666667 | 11297 |
| 010847 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596590.6 | 513632.4 | 90086 | 1.64041666667 | 10847 |
| 010676 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596589.6 | 513633.9 | 90088 | 1.64041666667 | 10676 |
| 010918 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596588.6 | 513636.0 | 90090 | 1.64041666667 | 10918 |
| 010401 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596586.7 | 513637.3 | 90092 | 1.64041666667 | 10401 |
| 010800 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596584.9 | 513639.2 | 90094 | 1.64041666667 | 10800 |
| 010560 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596583.9 | 513640.5 | 90096 | 1.64041666667 | 10560 |
| 011745 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:37pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596582.4 | 513642.4 | 90098 | 1.64041666667 | 11745 |
| 011234 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596581.4 | 513644.8 | 90100 | 1.64041666667 | 11234 |
| 010496 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596579.9 | 513647.2 | 90102 | 1.64041666667 | 10496 |
| 010899 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:40pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596579.2 | 513649.2 | 90104 | 1.64041666667 | 10899 |
| 011073 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:41pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596578.9 | 513651.8 | 90106 | 1.64041666667 | 11073 |
| 010698 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:42pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596578.4 | 513653.8 | 90108 | 1.64041666667 | 10698 |
| 010653 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:43pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596577.4 | 513656.3 | 90110 | 1.64041666667 | 10653 |
| 010995 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:44pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596577.1 | 513658.1 | 90112 | 1.64041666667 | 10995 |
| 010932 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:45pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596576.4 | 513660.5 | 90114 | 1.64041666667 | 10932 |
| 011519 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:46pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596574.9 | 513661.1 | 90116 | 1.64041666667 | 11519 |
| 012427 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:47pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596573.8 | 513662.5 | 90118 | 1.64041666667 | 12427 |
| 012307 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:48pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596572.4 | 513663.6 | 90120 | 1.64041666667 | 12307 |
| 011625 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:49pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596570.9 | 513664.5 | 90122 | 1.64041666667 | 11625 |
| 011579 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:50pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596569.8 | 513665.2 | 90124 | 1.64041666667 | 11579 |
| 011006 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596568.5 | 513666.6 | 90126 | 1.64041666667 | 11006 |
| 011223 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596567.3 | 513667.7 | 90128 | 1.64041666667 | 11223 |
| 012073 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596566.3 | 513669.0 | 90130 | 1.64041666667 | 12073 |
| 012573 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596565.6 | 513670.6 | 90132 | 1.64041666667 | 12573 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012030 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:55pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596564.9 | 513672.8 | 90134 | 1.64041666667 | 12030 |
| 011762 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:56pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596566.4 | 513673.5 | 90136 | 1.64041666667 | 11762 |
| 011221 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:57pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596568.0 | 513675.4 | 90138 | 1.64041666667 | 11221 |
| 012341 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596569.5 | 513676.0 | 90140 | 1.64041666667 | 12341 |
| 011937 | 0 | GeoXH 6000 | 08/20/2015 | 01:37:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596571.1 | 513677.2 | 90142 | 1.64041666667 | 11937 |
| 011447 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596572.6 | 513677.5 | 90144 | 1.64041666667 | 11447 |
| 011231 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596574.8 | 513678.0 | 90146 | 1.64041666667 | 11231 |
| 011230 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:02pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596576.4 | 513678.7 | 90148 | 1.64041666667 | 11230 |
| 011252 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:03pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596577.3 | 513677.7 | 90150 | 1.64041666667 | 11252 |
| 011497 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:04pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596578.3 | 513676.1 | 90152 | 1.64041666667 | 11497 |
| 011927 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:05pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596578.5 | 513674.1 | 90154 | 1.64041666667 | 11927 |
| 010818 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:06pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596578.0 | 513672.2 | 90156 | 1.64041666667 | 10818 |
| 010525 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:07pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596579.6 | 513670.7 | 90158 | 1.64041666667 | 10525 |
| 010615 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:08pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596580.1 | 513668.9 | 90160 | 1.64041666667 | 10615 |
| 010538 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:09pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596581.3 | 513667.3 | 90162 | 1.64041666667 | 10538 |
| 010765 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:10pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596582.0 | 513665.4 | 90164 | 1.64041666667 | 10765 |
| 011073 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:11pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596582.4 | 513663.2 | 90166 | 1.64041666667 | 11073 |
| 011838 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596583.6 | 513661.3 | 90168 | 1.64041666667 | 11838 |
| 011586 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:13pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596583.6 | 513658.8 | 90170 | 1.64041666667 | 11586 |
| 012030 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596584.3 | 513657.0 | 90172 | 1.64041666667 | 12030 |
| 011799 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:15pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596585.3 | 513654.6 | 90174 | 1.64041666667 | 11799 |
| 011294 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596585.6 | 513652.3 | 90176 | 1.64041666667 | 11294 |
| 011138 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596587.1 | 513650.3 | 90178 | 1.64041666667 | 11138 |
| 010742 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596587.6 | 513648.4 | 90180 | 1.64041666667 | 10742 |
| 010677 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596588.2 | 513646.2 | 90182 | 1.64041666667 | 10677 |
| 010228 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596589.3 | 513644.8 | 90184 | 1.64041666667 | 10228 |
| 010021 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596590.0 | 513643.1 | 90186 | 1.64041666667 | 10021 |
| 010841 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596590.4 | 513641.1 | 90188 | 1.64041666667 | 10841 |
| 010898 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596591.7 | 513639.5 | 90190 | 1.64041666667 | 10898 |
| 010803 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:24pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596592.2 | 513638.2 | 90192 | 1.64041666667 | 10803 |
| 010816 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596593.4 | 513636.8 | 90194 | 1.64041666667 | 10816 |
| 010651 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596595.5 | 513635.9 | 90196 | 1.64041666667 | 10651 |
| 010206 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596597.5 | 513634.9 | 90198 | 1.64041666667 | 10206 |
| 010053 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596598.2 | 513633.6 | 90200 | 1.64041666667 | 10053 |
| 010500 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596599.5 | 513632.0 | 90202 | 1.64041666667 | 10500 |
| 010616 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596600.8 | 513630.3 | 90204 | 1.64041666667 | 10616 |
| 010794 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596601.0 | 513627.8 | 90206 | 1.64041666667 | 10794 |
| 011119 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596601.8 | 513626.3 | 90208 | 1.64041666667 | 11119 |
| 011129 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596603.5 | 513624.7 | 90210 | 1.64041666667 | 11129 |
| 010925 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596604.6 | 513622.9 | 90212 | 1.64041666667 | 10925 |
| 011185 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596605.6 | 513621.5 | 90214 | 1.64041666667 | 11185 |
| 011047 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596606.3 | 513620.1 | 90216 | 1.64041666667 | 11047 |
| 010676 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:37pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596606.7 | 513618.4 | 90218 | 1.64041666667 | 10676 |
| 010783 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596607.5 | 513616.5 | 90220 | 1.64041666667 | 10783 |
| 010932 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:39pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596608.8 | 513614.2 | 90222 | 1.64041666667 | 10932 |
| 010634 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596609.4 | 513611.8 | 90224 | 1.64041666667 | 10634 |
| 010842 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:41pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596609.9 | 513610.2 | 90226 | 1.64041666667 | 10842 |
| 010958 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:42pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596610.6 | 513609.0 | 90228 | 1.64041666667 | 10958 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011219 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596611.0 | 513606.8 | 90230 | 1.64041666667 | 11219 |
| 011763 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:44pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596611.5 | 513604.8 | 90232 | 1.64041666667 | 11763 |
| 011507 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:45pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596612.5 | 513602.6 | 90234 | 1.64041666667 | 11507 |
| 011182 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:46pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596612.8 | 513600.5 | 90236 | 1.64041666667 | 11182 |
| 010310 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:47pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596612.8 | 513598.7 | 90238 | 1.64041666667 | 10310 |
| 010149 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596612.9 | 513597.0 | 90240 | 1.64041666667 | 10149 |
| 010644 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:49pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596612.6 | 513595.4 | 90242 | 1.64041666667 | 10644 |
| 011057 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596612.8 | 513593.6 | 90244 | 1.64041666667 | 11057 |
| 011154 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:51pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596612.6 | 513591.2 | 90246 | 1.64041666667 | 11154 |
| 010729 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:52pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596612.9 | 513589.6 | 90248 | 1.64041666667 | 10729 |
| 009950 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:53pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596614.1 | 513588.8 | 90250 | 1.64041666667 | 9950 |
| 011042 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596613.6 | 513587.5 | 90252 | 1.64041666667 | 11042 |
| 010351 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596614.1 | 513584.8 | 90254 | 1.64041666667 | 10351 |
| 010607 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596614.0 | 513582.8 | 90256 | 1.64041666667 | 10607 |
| 010406 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:57pm | Sensor | 1797-S0054-905-G-ACK | 6852.4 | 1596613.5 | 513580.3 | 90258 | 1.64041666667 | 10406 |
| 009956 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:58pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596614.2 | 513578.6 | 90260 | 1.64041666667 | 9956 |
| 011458 | 0 | GeoXH 6000 | 08/20/2015 | 01:38:59pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596614.1 | 513578.3 | 90262 | 1.64041666667 | 11458 |
| 011282 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596614.0 | 513576.8 | 90264 | 1.64041666667 | 11282 |
| 012339 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:01pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596613.8 | 513574.5 | 90266 | 1.64041666667 | 12339 |
| 012415 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596613.9 | 513572.2 | 90268 | 1.64041666667 | 12415 |
| 011371 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596614.1 | 513569.8 | 90270 | 1.64041666667 | 11371 |
| 011001 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596614.0 | 513567.6 | 90272 | 1.64041666667 | 11001 |
| 010463 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596614.7 | 513565.3 | 90274 | 1.64041666667 | 10463 |
| 010190 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596615.0 | 513563.4 | 90276 | 1.64041666667 | 10190 |
| 011072 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596615.2 | 513561.2 | 90278 | 1.64041666667 | 11072 |
| 012040 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596615.9 | 513559.8 | 90280 | 1.64041666667 | 12040 |
| 011445 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596615.6 | 513558.3 | 90282 | 1.64041666667 | 11445 |
| 010810 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596616.8 | 513557.5 | 90284 | 1.64041666667 | 10810 |
| 011541 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596617.6 | 513556.2 | 90286 | 1.64041666667 | 11541 |
| 011299 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596618.6 | 513556.4 | 90288 | 1.64041666667 | 11299 |
| 011133 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596620.4 | 513557.3 | 90290 | 1.64041666667 | 11133 |
| 011355 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:14pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596622.3 | 513557.5 | 90292 | 1.64041666667 | 11355 |
| 010909 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:15pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596623.6 | 513558.5 | 90294 | 1.64041666667 | 10909 |
| 010134 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:16pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596624.9 | 513559.2 | 90296 | 1.64041666667 | 10134 |
| 010567 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:17pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596625.2 | 513559.8 | 90298 | 1.64041666667 | 10567 |
| 010879 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:18pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596624.7 | 513560.7 | 90300 | 1.64041666667 | 10879 |
| 011594 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596623.6 | 513561.8 | 90302 | 1.64041666667 | 11594 |
| 011809 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596622.9 | 513563.6 | 90304 | 1.64041666667 | 11809 |
| 011450 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596622.9 | 513565.7 | 90306 | 1.64041666667 | 11450 |
| 011083 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596622.4 | 513567.8 | 90308 | 1.64041666667 | 11083 |
| 012174 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596621.9 | 513570.3 | 90310 | 1.64041666667 | 12174 |
| 010740 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596622.2 | 513572.5 | 90312 | 1.64041666667 | 10740 |
| 010766 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596621.5 | 513575.1 | 90314 | 1.64041666667 | 10766 |
| 010998 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596620.9 | 513577.2 | 90316 | 1.64041666667 | 10998 |
| 010311 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596620.7 | 513579.8 | 90318 | 1.64041666667 | 10311 |
| 010570 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596620.3 | 513581.8 | 90320 | 1.64041666667 | 10570 |
| 010603 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596619.4 | 513583.7 | 90322 | 1.64041666667 | 10603 |
| 010337 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596619.5 | 513585.4 | 90324 | 1.64041666667 | 10337 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010232 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596619.5 | 513587.9 | 90326 | 1.64041666667 | 10232 |
| 010773 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596618.4 | 513589.5 | 90328 | 1.64041666667 | 10773 |
| 010680 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596617.5 | 513591.6 | 90330 | 1.64041666667 | 10680 |
| 010920 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596617.4 | 513594.0 | 90332 | 1.64041666667 | 10920 |
| 011370 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596618.1 | 513596.4 | 90334 | 1.64041666667 | 11370 |
| 010753 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596618.3 | 513598.8 | 90336 | 1.64041666667 | 10753 |
| 010811 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:37pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596619.0 | 513601.2 | 90338 | 1.64041666667 | 10811 |
| 011143 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:38pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596619.7 | 513603.2 | 90340 | 1.64041666667 | 11143 |
| 010423 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:39pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596618.9 | 513605.4 | 90342 | 1.64041666667 | 10423 |
| 010550 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:40pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596619.2 | 513607.0 | 90344 | 1.64041666667 | 10550 |
| 010262 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596618.7 | 513609.6 | 90347 | 1.64041666667 | 10262 |
| 010842 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596618.1 | 513611.4 | 90348 | 1.64041666667 | 10842 |
| 010906 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596618.0 | 513613.5 | 90350 | 1.64041666667 | 10906 |
| 010065 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:44pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596617.4 | 513615.2 | 90352 | 1.64041666667 | 10065 |
| 010439 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:45pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596615.8 | 513615.8 | 90354 | 1.64041666667 | 10439 |
| 010132 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:46pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596615.4 | 513616.7 | 90356 | 1.64041666667 | 10132 |
| 010034 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:47pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596614.3 | 513617.9 | 90358 | 1.64041666667 | 10034 |
| 010984 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596613.9 | 513619.3 | 90360 | 1.64041666667 | 10984 |
| 011661 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596613.1 | 513620.9 | 90362 | 1.64041666667 | 11661 |
| 012439 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596611.7 | 513622.2 | 90364 | 1.64041666667 | 12439 |
| 011857 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:51pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596611.0 | 513623.5 | 90366 | 1.64041666667 | 11857 |
| 011342 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596610.0 | 513624.7 | 90368 | 1.64041666667 | 11342 |
| 010632 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:53pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596609.5 | 513626.6 | 90370 | 1.64041666667 | 10632 |
| 010353 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:54pm | Sensor | 1797-S0054-905-G-ACK | 6852.5 | 1596608.8 | 513627.7 | 90372 | 1.64041666667 | 10353 |
| 010683 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:55pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596608.7 | 513629.9 | 90374 | 1.64041666667 | 10683 |
| 010389 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596608.1 | 513631.8 | 90376 | 1.64041666667 | 10389 |
| 010479 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596606.6 | 513633.7 | 90378 | 1.64041666667 | 10479 |
| 010679 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:58pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596605.9 | 513635.0 | 90380 | 1.64041666667 | 10679 |
| 010829 | 0 | GeoXH 6000 | 08/20/2015 | 01:39:59pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596605.0 | 513636.9 | 90382 | 1.64041666667 | 10829 |
| 010726 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596603.7 | 513638.2 | 90384 | 1.64041666667 | 10726 |
| 010961 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:01pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596602.7 | 513639.9 | 90386 | 1.64041666667 | 10961 |
| 011063 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596601.8 | 513640.7 | 90388 | 1.64041666667 | 11063 |
| 011233 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596600.1 | 513642.2 | 90390 | 1.64041666667 | 11233 |
| 011403 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596599.2 | 513643.8 | 90392 | 1.64041666667 | 11403 |
| 011439 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596597.3 | 513645.5 | 90394 | 1.64041666667 | 11439 |
| 011827 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596596.1 | 513646.6 | 90396 | 1.64041666667 | 11827 |
| 011670 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596596.3 | 513647.2 | 90398 | 1.64041666667 | 11670 |
| 011079 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596597.9 | 513647.9 | 90400 | 1.64041666667 | 11079 |
| 010860 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596600.0 | 513648.2 | 90402 | 1.64041666667 | 10860 |
| 011426 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596601.4 | 513649.2 | 90404 | 1.64041666667 | 11426 |
| 011264 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596602.1 | 513651.4 | 90406 | 1.64041666667 | 11264 |
| 011211 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596602.1 | 513653.3 | 90408 | 1.64041666667 | 11211 |
| 011369 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596602.4 | 513655.4 | 90410 | 1.64041666667 | 11369 |
| 012072 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596602.2 | 513657.5 | 90412 | 1.64041666667 | 12072 |
| 011575 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596600.8 | 513659.4 | 90414 | 1.64041666667 | 11575 |
| 011303 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596599.0 | 513659.9 | 90416 | 1.64041666667 | 11303 |
| 011068 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:17pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596596.8 | 513660.5 | 90418 | 1.64041666667 | 11068 |
| 012578 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596594.8 | 513660.7 | 90420 | 1.64041666667 | 12578 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012385 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596593.2 | 513659.7 | 90422 | 1.64041666667 | 12385 |
| 011991 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596592.0 | 513658.9 | 90424 | 1.64041666667 | 11991 |
| 012175 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:21pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596591.0 | 513658.2 | 90426 | 1.64041666667 | 12175 |
| 011866 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596590.8 | 513658.1 | 90428 | 1.64041666667 | 11866 |
| 012622 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:23pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596590.9 | 513659.0 | 90430 | 1.64041666667 | 12622 |
| 011187 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596590.1 | 513659.4 | 90432 | 1.64041666667 | 11187 |
| 012030 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:25pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596590.1 | 513660.9 | 90434 | 1.64041666667 | 12030 |
| 011207 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596589.3 | 513662.5 | 90436 | 1.64041666667 | 11207 |
| 011704 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:27pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596589.0 | 513664.6 | 90438 | 1.64041666667 | 11704 |
| 011173 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:28pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596588.8 | 513666.3 | 90440 | 1.64041666667 | 11173 |
| 011287 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:29pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596587.4 | 513668.1 | 90442 | 1.64041666667 | 11287 |
| 010961 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:30pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596587.3 | 513669.8 | 90444 | 1.64041666667 | 10961 |
| 010981 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:31pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596586.1 | 513671.9 | 90446 | 1.64041666667 | 10981 |
| 010856 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596585.2 | 513673.8 | 90448 | 1.64041666667 | 10856 |
| 012152 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:33pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596584.9 | 513676.2 | 90450 | 1.64041666667 | 12152 |
| 010945 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596583.8 | 513678.0 | 90452 | 1.64041666667 | 10945 |
| 010972 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596583.3 | 513680.5 | 90454 | 1.64041666667 | 10972 |
| 011804 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:36pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596584.7 | 513680.8 | 90456 | 1.64041666667 | 11804 |
| 011717 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:37pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596587.2 | 513681.4 | 90458 | 1.64041666667 | 11717 |
| 011518 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:38pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596588.9 | 513681.1 | 90460 | 1.64041666667 | 11518 |
| 011676 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596591.4 | 513680.3 | 90462 | 1.64041666667 | 11676 |
| 011255 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596593.0 | 513681.0 | 90464 | 1.64041666667 | 11255 |
| 010358 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596595.0 | 513680.6 | 90466 | 1.64041666667 | 10358 |
| 010566 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596596.3 | 513680.4 | 90468 | 1.64041666667 | 10566 |
| 011876 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596595.1 | 513679.4 | 90470 | 1.64041666667 | 11876 |
| 012253 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:44pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596598.8 | 513677.7 | 90472 | 1.64041666667 | 12253 |
| 011257 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:45pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596598.4 | 513675.8 | 90474 | 1.64041666667 | 11257 |
| 012264 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:46pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596599.1 | 513674.0 | 90476 | 1.64041666667 | 12264 |
| 011759 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:47pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596599.3 | 513671.8 | 90478 | 1.64041666667 | 11759 |
| 011774 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596599.5 | 513670.1 | 90480 | 1.64041666667 | 11774 |
| 011693 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596600.7 | 513668.0 | 90482 | 1.64041666667 | 11693 |
| 011512 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596600.5 | 513666.5 | 90484 | 1.64041666667 | 11512 |
| 011380 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:51pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596601.6 | 513664.3 | 90486 | 1.64041666667 | 11380 |
| 011824 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596602.1 | 513662.3 | 90488 | 1.64041666667 | 11824 |
| 011316 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596602.5 | 513659.7 | 90490 | 1.64041666667 | 11316 |
| 011352 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596603.5 | 513657.5 | 90492 | 1.64041666667 | 11352 |
| 010946 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596603.7 | 513655.4 | 90494 | 1.64041666667 | 10946 |
| 010904 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596603.9 | 513653.4 | 90496 | 1.64041666667 | 10904 |
| 010641 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596605.1 | 513651.5 | 90498 | 1.64041666667 | 10641 |
| 010208 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:58pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596605.2 | 513649.9 | 90500 | 1.64041666667 | 10208 |
| 009679 | 0 | GeoXH 6000 | 08/20/2015 | 01:40:59pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596605.8 | 513648.1 | 90502 | 1.64041666667 | 9679 |
| 009600 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:00pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596607.2 | 513646.3 | 90504 | 1.64041666667 | 9600 |
| 010125 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:01pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596608.1 | 513644.4 | 90506 | 1.64041666667 | 10125 |
| 010112 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:02pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596609.5 | 513643.4 | 90508 | 1.64041666667 | 10112 |
| 010818 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:03pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596610.6 | 513641.6 | 90510 | 1.64041666667 | 10818 |
| 011343 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:04pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596611.3 | 513639.7 | 90512 | 1.64041666667 | 11343 |
| 011262 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596612.7 | 513637.3 | 90514 | 1.64041666667 | 11262 |
| 011630 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596614.1 | 513635.7 | 90516 | 1.64041666667 | 11630 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010869 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:07pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596614.7 | 513633.4 | 90518 | 1.64041666667 | 10869 |
| 011521 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:08pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596614.8 | 513631.9 | 90520 | 1.64041666667 | 11521 |
| 010988 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596616.1 | 513630.4 | 90522 | 1.64041666667 | 10988 |
| 010651 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596616.9 | 513628.8 | 90524 | 1.64041666667 | 10651 |
| 010086 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596617.8 | 513626.1 | 90526 | 1.64041666667 | 10086 |
| 010871 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:12pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596619.1 | 513624.1 | 90528 | 1.64041666667 | 10871 |
| 010765 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:13pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596620.5 | 513622.3 | 90530 | 1.64041666667 | 10765 |
| 011102 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596620.6 | 513621.1 | 90532 | 1.64041666667 | 11102 |
| 011090 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596621.8 | 513619.2 | 90534 | 1.64041666667 | 11090 |
| 010730 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596622.6 | 513617.1 | 90536 | 1.64041666667 | 10730 |
| 010836 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:17pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596623.1 | 513614.7 | 90538 | 1.64041666667 | 10836 |
| 011300 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:18pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596623.9 | 513612.8 | 90540 | 1.64041666667 | 11300 |
| 011043 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:19pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596624.5 | 513610.5 | 90542 | 1.64041666667 | 11043 |
| 010734 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:20pm | Sensor | 1797-S0054-905-G-ACK | 6852.4 | 1596624.2 | 513608.6 | 90544 | 1.64041666667 | 10734 |
| 011265 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:21pm | Sensor | 1797-S0054-905-G-ACK | 6852.4 | 1596624.6 | 513606.5 | 90546 | 1.64041666667 | 11265 |
| 011182 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:22pm | Sensor | 1797-S0054-905-G-ACK | 6852.5 | 1596624.9 | 513604.6 | 90548 | 1.64041666667 | 11182 |
| 012394 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:23pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596624.5 | 513602.9 | 90550 | 1.64041666667 | 12394 |
| 011787 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:24pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596625.7 | 513601.8 | 90552 | 1.64041666667 | 11787 |
| 012547 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596626.6 | 513599.4 | 90554 | 1.64041666667 | 12547 |
| 011783 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596626.5 | 513597.1 | 90556 | 1.64041666667 | 11783 |
| 010850 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596627.3 | 513594.4 | 90558 | 1.64041666667 | 10850 |
| 010108 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596627.4 | 513592.0 | 90560 | 1.64041666667 | 10108 |
| 010426 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596626.3 | 513589.8 | 90562 | 1.64041666667 | 10426 |
| 010177 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596626.4 | 513588.3 | 90564 | 1.64041666667 | 10177 |
| 010967 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596626.4 | 513586.3 | 90566 | 1.64041666667 | 10967 |
| 011089 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596626.0 | 513584.6 | 90568 | 1.64041666667 | 11089 |
| 011450 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596626.6 | 513582.6 | 90570 | 1.64041666667 | 11450 |
| 011143 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596626.5 | 513580.9 | 90572 | 1.64041666667 | 11143 |
| 011458 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596626.3 | 513578.4 | 90574 | 1.64041666667 | 11458 |
| 011087 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596626.9 | 513576.5 | 90576 | 1.64041666667 | 11087 |
| 011051 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:37pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596627.3 | 513573.9 | 90578 | 1.64041666667 | 11051 |
| 010956 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596627.4 | 513572.0 | 90580 | 1.64041666667 | 10956 |
| 010873 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:39pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596628.1 | 513570.2 | 90582 | 1.64041666667 | 10873 |
| 010376 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:40pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596627.9 | 513568.1 | 90584 | 1.64041666667 | 10376 |
| 010494 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:41pm | Sensor | 1797-S0054-905-G-ACK | 6852.6 | 1596627.7 | 513565.6 | 90586 | 1.64041666667 | 10494 |
| 011437 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:42pm | Sensor | 1797-S0054-905-G-ACK | 6852.6 | 1596627.6 | 513564.6 | 90588 | 1.64041666667 | 11437 |
| 011481 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:43pm | Sensor | 1797-S0054-905-G-ACK | 6852.5 | 1596626.8 | 513562.7 | 90590 | 1.64041666667 | 11481 |
| 011295 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:44pm | Sensor | 1797-S0054-905-G-ACK | 6852.5 | 1596626.8 | 513561.7 | 90592 | 1.64041666667 | 11295 |
| 011266 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:45pm | Sensor | 1797-S0054-905-G-ACK | 6852.5 | 1596626.5 | 513560.0 | 90594 | 1.64041666667 | 11266 |
| 011130 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:46pm | Sensor | 1797-S0054-905-G-ACK | 6852.7 | 1596627.5 | 513559.0 | 90596 | 1.64041666667 | 11130 |
| 010820 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:47pm | Sensor | 1797-S0054-905-G-ACK | 6852.6 | 1596628.9 | 513557.9 | 90598 | 1.64041666667 | 10820 |
| 011021 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:48pm | Sensor | 1797-S0054-905-G-ACK | 6852.7 | 1596630.5 | 513557.1 | 90600 | 1.64041666667 | 11021 |
| 010692 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:49pm | Sensor | 1797-S0054-905-G-ACK | 6852.4 | 1596632.8 | 513556.8 | 90602 | 1.64041666667 | 10692 |
| 010597 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:50pm | Sensor | 1797-S0054-905-G-ACK | 6852.6 | 1596634.4 | 513556.1 | 90604 | 1.64041666667 | 10597 |
| 009883 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:51pm | Sensor | 1797-S0054-905-G-ACK | 6852.8 | 1596635.9 | 513556.0 | 90606 | 1.64041666667 | 9883 |
| 009751 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:52pm | Sensor | 1797-S0054-905-G-ACK | 6852.6 | 1596636.5 | 513555.7 | 90608 | 1.64041666667 | 9751 |
| 009888 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:53pm | Sensor | 1797-S0054-905-G-ACK | 6852.8 | 1596636.5 | 513556.6 | 90610 | 1.64041666667 | 9888 |
| 010056 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:54pm | Sensor | 1797-S0054-905-G-ACK | 6853.2 | 1596636.9 | 513558.6 | 90612 | 1.64041666667 | 10056 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010459 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:55pm | Sensor | 1797-S0054-905-G-ACK | 6852.7 | 1596638.0 | 513559.7 | 90614 | 1.64041666667 | 10459 |
| 010623 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:56pm | Sensor | 1797-S0054-905-G-ACK | 6853.1 | 1596637.8 | 513561.2 | 90616 | 1.64041666667 | 10623 |
| 010873 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:57pm | Sensor | 1797-S0054-905-G-ACK | 6853.4 | 1596638.3 | 513563.0 | 90618 | 1.64041666667 | 10873 |
| 010728 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:58pm | Sensor | 1797-S0054-905-G-ACK | 6853.3 | 1596638.2 | 513565.1 | 90620 | 1.64041666667 | 10728 |
| 011037 | 0 | GeoXH 6000 | 08/20/2015 | 01:41:59pm | Sensor | 1797-S0054-905-G-ACK | 6853.6 | 1596638.0 | 513567.3 | 90622 | 1.64041666667 | 11037 |
| 010731 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:00pm | Sensor | 1797-S0054-905-G-ACK | 6853.5 | 1596638.4 | 513568.6 | 90624 | 1.64041666667 | 10731 |
| 011248 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:01pm | Sensor | 1797-S0054-905-G-ACK | 6852.9 | 1596637.5 | 513570.1 | 90626 | 1.64041666667 | 11248 |
| 010692 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:02pm | Sensor | 1797-S0054-905-G-ACK | 6852.4 | 1596638.3 | 513570.9 | 90628 | 1.64041666667 | 10692 |
| 011864 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:03pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596638.2 | 513572.4 | 90630 | 1.64041666667 | 11864 |
| 010708 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:04pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596637.2 | 513573.7 | 90632 | 1.64041666667 | 10708 |
| 010921 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596637.2 | 513575.4 | 90634 | 1.64041666667 | 10921 |
| 012135 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596636.2 | 513576.7 | 90636 | 1.64041666667 | 12135 |
| 011596 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596635.2 | 513578.6 | 90638 | 1.64041666667 | 11596 |
| 011728 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596635.1 | 513580.6 | 90640 | 1.64041666667 | 11728 |
| 011404 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596634.0 | 513582.8 | 90642 | 1.64041666667 | 11404 |
| 011140 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596634.4 | 513584.6 | 90644 | 1.64041666667 | 11140 |
| 010436 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596633.9 | 513587.0 | 90646 | 1.64041666667 | 10436 |
| 010805 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:12pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596633.8 | 513588.8 | 90648 | 1.64041666667 | 10805 |
| 011050 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596633.5 | 513591.4 | 90650 | 1.64041666667 | 11050 |
| 010678 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:14pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596632.5 | 513593.2 | 90652 | 1.64041666667 | 10678 |
| 011106 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:15pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596632.4 | 513595.9 | 90654 | 1.64041666667 | 11106 |
| 010640 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:16pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596631.4 | 513598.0 | 90656 | 1.64041666667 | 10640 |
| 010961 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:17pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596630.9 | 513600.7 | 90658 | 1.64041666667 | 10961 |
| 010658 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:18pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596631.3 | 513602.8 | 90660 | 1.64041666667 | 10658 |
| 010517 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:19pm | Sensor | 1797-S0054-905-G-ACK | 6850.0 | 1596630.8 | 513605.2 | 90662 | 1.64041666667 | 10517 |
| 011811 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:20pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596630.5 | 513606.7 | 90664 | 1.64041666667 | 11811 |
| 011354 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596630.6 | 513607.5 | 90666 | 1.64041666667 | 11354 |
| 012281 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596630.3 | 513609.0 | 90668 | 1.64041666667 | 12281 |
| 011295 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596630.1 | 513611.9 | 90670 | 1.64041666667 | 11295 |
| 011259 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596630.0 | 513613.9 | 90672 | 1.64041666667 | 11259 |
| 011305 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596629.2 | 513616.7 | 90674 | 1.64041666667 | 11305 |
| 011789 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596629.5 | 513619.3 | 90676 | 1.64041666667 | 11789 |
| 011341 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596629.9 | 513621.0 | 90678 | 1.64041666667 | 11341 |
| 012342 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596628.9 | 513621.1 | 90680 | 1.64041666667 | 12342 |
| 012087 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596628.5 | 513621.2 | 90682 | 1.64041666667 | 12087 |
| 011486 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596628.5 | 513621.2 | 90684 | 1.64041666667 | 11486 |
| 010728 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596628.4 | 513621.2 | 90686 | 1.64041666667 | 10728 |
| 010234 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596628.4 | 513621.2 | 90688 | 1.64041666667 | 10234 |
| 010054 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596628.3 | 513621.2 | 90690 | 1.64041666667 | 10054 |
| 010140 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:34pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596628.3 | 513621.4 | 90692 | 1.64041666667 | 10140 |
| 010939 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596628.4 | 513622.8 | 90694 | 1.64041666667 | 10939 |
| 010630 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596627.0 | 513623.9 | 90696 | 1.64041666667 | 10630 |
| 010644 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:37pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596625.4 | 513625.5 | 90698 | 1.64041666667 | 10644 |
| 010315 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596623.9 | 513627.3 | 90700 | 1.64041666667 | 10315 |
| 010564 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:39pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596622.0 | 513628.4 | 90702 | 1.64041666667 | 10564 |
| 011725 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596620.1 | 513629.7 | 90704 | 1.64041666667 | 11725 |
| 011065 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596618.6 | 513632.0 | 90706 | 1.64041666667 | 11065 |
| 011549 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596618.9 | 513634.3 | 90708 | 1.64041666667 | 11549 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012369 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596618.9 | 513636.9 | 90710 | 1.64041666667 | 12369 |
| 011562 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:44pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596618.0 | 513639.0 | 90712 | 1.64041666667 | 11562 |
| 011169 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:45pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596617.1 | 513641.5 | 90714 | 1.64041666667 | 11169 |
| 010572 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:46pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596616.2 | 513643.2 | 90716 | 1.64041666667 | 10572 |
| 010949 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:47pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596614.7 | 513644.5 | 90718 | 1.64041666667 | 10949 |
| 010314 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:48pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596614.2 | 513646.2 | 90720 | 1.64041666667 | 10314 |
| 010669 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:49pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596613.2 | 513647.9 | 90722 | 1.64041666667 | 10669 |
| 010246 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:50pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596612.3 | 513649.7 | 90724 | 1.64041666667 | 10246 |
| 010653 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:51pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596611.6 | 513652.1 | 90726 | 1.64041666667 | 10653 |
| 010800 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596610.9 | 513654.2 | 90728 | 1.64041666667 | 10800 |
| 010177 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596609.6 | 513656.6 | 90730 | 1.64041666667 | 10177 |
| 010825 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596609.0 | 513658.7 | 90732 | 1.64041666667 | 10825 |
| 011421 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596607.9 | 513660.6 | 90734 | 1.64041666667 | 11421 |
| 012477 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596606.4 | 513661.9 | 90736 | 1.64041666667 | 12477 |
| 012193 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596605.5 | 513663.6 | 90738 | 1.64041666667 | 12193 |
| 011906 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:58pm | Sensor | 1797-S0054-905-G-ACK | 6850.7 | 1596604.9 | 513665.6 | 90740 | 1.64041666667 | 11906 |
| 011640 | 0 | GeoXH 6000 | 08/20/2015 | 01:42:59pm | Sensor | 1797-S0054-905-G-ACK | 6850.4 | 1596604.6 | 513668.2 | 90742 | 1.64041666667 | 11640 |
| 010710 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:00pm | Sensor | 1797-S0054-905-G-ACK | 6850.5 | 1596605.1 | 513670.2 | 90744 | 1.64041666667 | 10710 |
| 011191 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:01pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596604.7 | 513672.4 | 90746 | 1.64041666667 | 11191 |
| 011860 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596604.2 | 513674.6 | 90748 | 1.64041666667 | 11860 |
| 012453 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596604.2 | 513677.1 | 90750 | 1.64041666667 | 12453 |
| 011610 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596604.2 | 513679.2 | 90752 | 1.64041666667 | 11610 |
| 012163 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596605.7 | 513681.2 | 90754 | 1.64041666667 | 12163 |
| 011634 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596607.3 | 513681.4 | 90756 | 1.64041666667 | 11634 |
| 012019 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596609.1 | 513682.4 | 90758 | 1.64041666667 | 12019 |
| 012086 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596610.9 | 513683.3 | 90760 | 1.64041666667 | 12086 |
| 011501 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596612.0 | 513682.2 | 90762 | 1.64041666667 | 11501 |
| 010864 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596612.2 | 513680.4 | 90764 | 1.64041666667 | 10864 |
| 010686 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596612.9 | 513678.0 | 90766 | 1.64041666667 | 10686 |
| 010466 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596612.8 | 513675.9 | 90768 | 1.64041666667 | 10466 |
| 012217 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596613.2 | 513674.3 | 90770 | 1.64041666667 | 12217 |
| 011394 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596613.6 | 513672.4 | 90772 | 1.64041666667 | 11394 |
| 011397 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596613.8 | 513670.2 | 90774 | 1.64041666667 | 11397 |
| 011315 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596615.0 | 513668.8 | 90776 | 1.64041666667 | 11315 |
| 011742 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596615.8 | 513666.7 | 90778 | 1.64041666667 | 11742 |
| 011405 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596615.8 | 513664.9 | 90780 | 1.64041666667 | 11405 |
| 011058 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596615.9 | 513662.4 | 90782 | 1.64041666667 | 11058 |
| 010652 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596615.7 | 513661.1 | 90784 | 1.64041666667 | 10652 |
| 010589 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596615.6 | 513659.0 | 90786 | 1.64041666667 | 10589 |
| 010599 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596616.0 | 513657.5 | 90788 | 1.64041666667 | 10599 |
| 011182 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:23pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596616.6 | 513655.8 | 90790 | 1.64041666667 | 11182 |
| 011524 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:24pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596616.6 | 513653.8 | 90792 | 1.64041666667 | 11524 |
| 011702 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:25pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596617.5 | 513651.7 | 90794 | 1.64041666667 | 11702 |
| 010617 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:26pm | Sensor | 1797-S0054-905-G-ACK | 6852.4 | 1596617.4 | 513650.5 | 90796 | 1.64041666667 | 10617 |
| 011192 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:27pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596617.7 | 513648.6 | 90798 | 1.64041666667 | 11192 |
| 010518 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:28pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596617.8 | 513646.8 | 90800 | 1.64041666667 | 10518 |
| 010401 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:29pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596617.5 | 513644.5 | 90802 | 1.64041666667 | 10401 |
| 010343 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596618.5 | 513642.8 | 90804 | 1.64041666667 | 10343 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009793 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596618.9 | 513641.0 | 90806 | 1.64041666667 | 9793 |
| 009746 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596619.4 | 513639.7 | 90808 | 1.64041666667 | 9746 |
| 010357 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596621.0 | 513638.5 | 90810 | 1.64041666667 | 10357 |
| 011061 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596622.6 | 513638.1 | 90812 | 1.64041666667 | 11061 |
| 011449 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:35pm | Sensor | 1797-S0054-905-G-ACK | 6843.6 | 1596623.6 | 513637.9 | 90814 | 1.64041666667 | 11449 |
| 010407 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:36pm | Sensor | 1797-S0054-905-G-ACK | 6841.8 | 1596625.9 | 513638.2 | 90816 | 1.64041666667 | 10407 |
| 010586 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:37pm | Sensor | 1797-S0054-905-G-ACK | 6841.5 | 1596628.2 | 513637.9 | 90818 | 1.64041666667 | 10586 |
| 010642 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:38pm | Sensor | 1797-S0054-905-G-ACK | 6841.5 | 1596629.8 | 513637.2 | 90820 | 1.64041666667 | 10642 |
| 010839 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:39pm | Sensor | 1797-S0054-905-G-ACK | 6850.3 | 1596632.8 | 513635.6 | 90822 | 1.64041666667 | 10839 |
| 010424 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596633.5 | 513633.0 | 90824 | 1.64041666667 | 10424 |
| 011136 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596632.5 | 513631.0 | 90826 | 1.64041666667 | 11136 |
| 010569 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596631.5 | 513629.3 | 90828 | 1.64041666667 | 10569 |
| 009957 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596632.3 | 513627.7 | 90830 | 1.64041666667 | 9957 |
| 010296 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:44pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596632.4 | 513626.2 | 90832 | 1.64041666667 | 10296 |
| 010006 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:45pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596633.5 | 513625.3 | 90834 | 1.64041666667 | 10006 |
| 010841 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:46pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596633.7 | 513623.4 | 90836 | 1.64041666667 | 10841 |
| 011048 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:47pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596634.2 | 513621.4 | 90838 | 1.64041666667 | 11048 |
| 011359 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:48pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596635.0 | 513619.3 | 90840 | 1.64041666667 | 11359 |
| 011182 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596635.0 | 513617.1 | 90842 | 1.64041666667 | 11182 |
| 010812 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:50pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596634.7 | 513615.1 | 90844 | 1.64041666667 | 10812 |
| 010297 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:51pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596635.5 | 513613.1 | 90846 | 1.64041666667 | 10297 |
| 010667 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596635.4 | 513611.2 | 90848 | 1.64041666667 | 10667 |
| 010567 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596635.8 | 513608.7 | 90850 | 1.64041666667 | 10567 |
| 011156 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596636.6 | 513606.4 | 90852 | 1.64041666667 | 11156 |
| 010678 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596637.1 | 513604.0 | 90854 | 1.64041666667 | 10678 |
| 010408 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596637.4 | 513602.2 | 90856 | 1.64041666667 | 10408 |
| 011814 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596638.2 | 513599.8 | 90858 | 1.64041666667 | 11814 |
| 010845 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:58pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596638.7 | 513597.5 | 90860 | 1.64041666667 | 10845 |
| 010900 | 0 | GeoXH 6000 | 08/20/2015 | 01:43:59pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596638.8 | 513594.9 | 90862 | 1.64041666667 | 10900 |
| 010856 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596639.1 | 513592.4 | 90864 | 1.64041666667 | 10856 |
| 011926 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:01pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596640.0 | 513590.0 | 90866 | 1.64041666667 | 11926 |
| 012018 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596640.8 | 513588.2 | 90868 | 1.64041666667 | 12018 |
| 011695 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596641.2 | 513586.0 | 90870 | 1.64041666667 | 11695 |
| 011881 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596641.7 | 513584.1 | 90872 | 1.64041666667 | 11881 |
| 010395 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596642.5 | 513582.0 | 90874 | 1.64041666667 | 10395 |
| 010310 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:06pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596642.4 | 513580.2 | 90876 | 1.64041666667 | 10310 |
| 009999 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:07pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596642.4 | 513578.0 | 90878 | 1.64041666667 | 9999 |
| 010349 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:08pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596642.7 | 513576.5 | 90880 | 1.64041666667 | 10349 |
| 010644 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:09pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596642.8 | 513574.6 | 90882 | 1.64041666667 | 10644 |
| 010659 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:10pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596643.7 | 513572.8 | 90884 | 1.64041666667 | 10659 |
| 010023 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:11pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596644.8 | 513570.8 | 90886 | 1.64041666667 | 10023 |
| 010993 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:12pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596645.1 | 513569.0 | 90888 | 1.64041666667 | 10993 |
| 012341 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:13pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596646.3 | 513567.8 | 90890 | 1.64041666667 | 12341 |
| 012536 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596647.9 | 513566.8 | 90892 | 1.64041666667 | 12536 |
| 011679 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596649.8 | 513565.7 | 90894 | 1.64041666667 | 11679 |
| 011160 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596651.0 | 513565.8 | 90896 | 1.64041666667 | 11160 |
| 011587 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596652.9 | 513565.9 | 90898 | 1.64041666667 | 11587 |
| 011752 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596653.3 | 513567.0 | 90900 | 1.64041666667 | 11752 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011193 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596654.5 | 513568.4 | 90902 | 1.64041666667 | 11193 |
| 011381 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596654.3 | 513570.1 | 90904 | 1.64041666667 | 11381 |
| 011269 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596654.9 | 513571.3 | 90906 | 1.64041666667 | 11269 |
| 010861 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596654.3 | 513571.3 | 90908 | 1.64041666667 | 10861 |
| 010422 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596654.0 | 513571.2 | 90910 | 1.64041666667 | 10422 |
| 010767 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596654.0 | 513571.3 | 90912 | 1.64041666667 | 10767 |
| 010039 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596655.0 | 513572.3 | 90914 | 1.64041666667 | 10039 |
| 009967 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596654.7 | 513573.8 | 90916 | 1.64041666667 | 9967 |
| 010901 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596654.3 | 513575.8 | 90918 | 1.64041666667 | 10901 |
| 010767 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596654.2 | 513577.8 | 90920 | 1.64041666667 | 10767 |
| 011389 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596652.5 | 513579.1 | 90922 | 1.64041666667 | 11389 |
| 011806 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596651.6 | 513580.6 | 90924 | 1.64041666667 | 11806 |
| 010893 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596650.1 | 513582.3 | 90926 | 1.64041666667 | 10893 |
| 010447 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596648.8 | 513583.7 | 90928 | 1.64041666667 | 10447 |
| 010789 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596648.0 | 513585.8 | 90930 | 1.64041666667 | 10789 |
| 010876 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596646.9 | 513587.3 | 90932 | 1.64041666667 | 10876 |
| 010655 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596645.8 | 513589.5 | 90934 | 1.64041666667 | 10655 |
| 010943 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596645.5 | 513591.2 | 90936 | 1.64041666667 | 10943 |
| 010063 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:37pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596644.6 | 513593.0 | 90938 | 1.64041666667 | 10063 |
| 010805 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596644.9 | 513595.2 | 90940 | 1.64041666667 | 10805 |
| 010518 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:39pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596643.8 | 513597.1 | 90942 | 1.64041666667 | 10518 |
| 010791 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596643.8 | 513598.7 | 90944 | 1.64041666667 | 10791 |
| 010180 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596643.7 | 513600.9 | 90946 | 1.64041666667 | 10180 |
| 010578 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596643.2 | 513602.8 | 90948 | 1.64041666667 | 10578 |
| 011725 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596643.3 | 513604.5 | 90950 | 1.64041666667 | 11725 |
| 011478 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:44pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596643.9 | 513606.1 | 90952 | 1.64041666667 | 11478 |
| 011249 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:45pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596645.6 | 513607.2 | 90954 | 1.64041666667 | 11249 |
| 011007 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:46pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596647.5 | 513606.4 | 90956 | 1.64041666667 | 11007 |
| 011434 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:47pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596649.8 | 513605.4 | 90958 | 1.64041666667 | 11434 |
| 010729 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596651.8 | 513604.5 | 90960 | 1.64041666667 | 10729 |
| 010910 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596654.1 | 513603.4 | 90962 | 1.64041666667 | 10910 |
| 010862 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596656.3 | 513602.7 | 90964 | 1.64041666667 | 10862 |
| 010767 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:51pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596659.2 | 513602.8 | 90966 | 1.64041666667 | 10767 |
| 010744 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:52pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596661.9 | 513603.2 | 90968 | 1.64041666667 | 10744 |
| 010476 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:53pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596664.8 | 513603.3 | 90970 | 1.64041666667 | 10476 |
| 011742 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:54pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596667.2 | 513603.5 | 90972 | 1.64041666667 | 11742 |
| 011007 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596670.3 | 513604.0 | 90974 | 1.64041666667 | 11007 |
| 010984 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596672.8 | 513604.0 | 90976 | 1.64041666667 | 10984 |
| 011646 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596675.5 | 513603.1 | 90978 | 1.64041666667 | 11646 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:58pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596677.7 | 513602.1 | 90980 | 1.64041666667 | 11928 |
| 012754 | 0 | GeoXH 6000 | 08/20/2015 | 01:44:59pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596680.5 | 513601.6 | 90982 | 1.64041666667 | 12754 |
| 011314 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:00pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596682.5 | 513600.5 | 90984 | 1.64041666667 | 11314 |
| 011696 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:01pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596684.8 | 513599.0 | 90986 | 1.64041666667 | 11696 |
| 011462 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:02pm | Sensor | 1797-S0054-905-G-ACK | 6852.2 | 1596686.7 | 513597.9 | 90988 | 1.64041666667 | 11462 |
| 011840 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:03pm | Sensor | 1797-S0054-905-G-ACK | 6852.3 | 1596689.3 | 513596.7 | 90990 | 1.64041666667 | 11840 |
| 012082 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:04pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596691.5 | 513595.4 | 90992 | 1.64041666667 | 12082 |
| 012893 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:05pm | Sensor | 1797-S0054-905-G-ACK | 6852.1 | 1596693.8 | 513593.5 | 90994 | 1.64041666667 | 12893 |
| 012435 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:06pm | Sensor | 1797-S0054-905-G-ACK | 6852.0 | 1596696.0 | 513592.2 | 90996 | 1.64041666667 | 12435 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011764 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596699.0 | 513590.7 | 90998 | 1.64041666667 | 11764 |
| 011530 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596701.0 | 513589.8 | 91000 | 1.64041666667 | 11530 |
| 011870 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596703.3 | 513588.4 | 91002 | 1.64041666667 | 11870 |
| 010810 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596705.5 | 513587.5 | 91004 | 1.64041666667 | 10810 |
| 010700 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596708.0 | 513586.7 | 91006 | 1.64041666667 | 10700 |
| 011029 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596710.2 | 513585.6 | 91008 | 1.64041666667 | 11029 |
| 010178 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596712.3 | 513584.0 | 91010 | 1.64041666667 | 10178 |
| 009933 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596714.3 | 513582.4 | 91012 | 1.64041666667 | 9933 |
| 010417 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596717.0 | 513581.4 | 91014 | 1.64041666667 | 10417 |
| 010007 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596719.1 | 513580.9 | 91016 | 1.64041666667 | 10007 |
| 009746 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.9 | 1596721.8 | 513580.8 | 91018 | 1.64041666667 | 9746 |
| 010050 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596723.9 | 513580.8 | 91020 | 1.64041666667 | 10050 |
| 009673 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596726.7 | 513580.4 | 91022 | 1.64041666667 | 9673 |
| 009978 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596728.8 | 513578.9 | 91024 | 1.64041666667 | 9978 |
| 009768 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:21pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596730.8 | 513576.9 | 91026 | 1.64041666667 | 9768 |
| 010669 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:22pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596733.0 | 513575.6 | 91028 | 1.64041666667 | 10669 |
| 010944 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:23pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596735.5 | 513575.0 | 91030 | 1.64041666667 | 10944 |
| 010551 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:24pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596737.6 | 513574.2 | 91032 | 1.64041666667 | 10551 |
| 010870 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:25pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596740.1 | 513572.9 | 91034 | 1.64041666667 | 10870 |
| 011274 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:26pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596742.6 | 513572.1 | 91036 | 1.64041666667 | 11274 |
| 010556 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596745.6 | 513571.5 | 91038 | 1.64041666667 | 10556 |
| 009515 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596747.6 | 513570.6 | 91040 | 1.64041666667 | 9515 |
| 009717 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:29pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596750.0 | 513569.4 | 91042 | 1.64041666667 | 9717 |
| 009831 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596752.3 | 513568.4 | 91044 | 1.64041666667 | 9831 |
| 009460 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:31pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596754.8 | 513566.6 | 91046 | 1.64041666667 | 9460 |
| 009386 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:32pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596756.3 | 513564.8 | 91048 | 1.64041666667 | 9386 |
| 009480 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:33pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596758.3 | 513562.6 | 91050 | 1.64041666667 | 9480 |
| 010717 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:34pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596760.2 | 513561.2 | 91052 | 1.64041666667 | 10717 |
| 010461 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:35pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596762.7 | 513560.0 | 91054 | 1.64041666667 | 10461 |
| 010781 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596764.5 | 513558.0 | 91056 | 1.64041666667 | 10781 |
| 011772 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:37pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596766.1 | 513555.5 | 91058 | 1.64041666667 | 11772 |
| 011444 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596767.7 | 513553.7 | 91060 | 1.64041666667 | 11444 |
| 011320 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:39pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596770.5 | 513551.9 | 91062 | 1.64041666667 | 11320 |
| 012630 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596772.6 | 513550.2 | 91064 | 1.64041666667 | 12630 |
| 013074 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596774.4 | 513547.5 | 91066 | 1.64041666667 | 13074 |
| 013076 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:42pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596775.8 | 513545.4 | 91068 | 1.64041666667 | 13076 |
| 012403 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:43pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596777.7 | 513542.9 | 91070 | 1.64041666667 | 12403 |
| 012481 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:44pm | Sensor | 1797-S0054-905-G-ACK | 6851.8 | 1596779.5 | 513541.0 | 91072 | 1.64041666667 | 12481 |
| 012173 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:45pm | Sensor | 1797-S0054-905-G-ACK | 6851.7 | 1596781.4 | 513538.8 | 91074 | 1.64041666667 | 12173 |
| 012007 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:46pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596783.1 | 513537.0 | 91076 | 1.64041666667 | 12007 |
| 011614 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:47pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596785.8 | 513535.1 | 91078 | 1.64041666667 | 11614 |
| 012150 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:48pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596788.1 | 513534.1 | 91080 | 1.64041666667 | 12150 |
| 012152 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:49pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596790.6 | 513531.8 | 91082 | 1.64041666667 | 12152 |
| 012895 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:50pm | Sensor | 1797-S0054-905-G-ACK | 6851.2 | 1596792.0 | 513530.0 | 91084 | 1.64041666667 | 12895 |
| 012286 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:51pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596793.5 | 513527.7 | 91086 | 1.64041666667 | 12286 |
| 011681 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:52pm | Sensor | 1797-S0054-905-G-ACK | 6850.6 | 1596795.0 | 513525.4 | 91088 | 1.64041666667 | 11681 |
| 011430 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:53pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596797.1 | 513523.1 | 91090 | 1.64041666667 | 11430 |
| 011042 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:54pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596799.2 | 513521.4 | 91092 | 1.64041666667 | 11042 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011438 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:55pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596801.7 | 513519.3 | 91094 | 1.64041666667 | 11438 |
| 011414 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:56pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596804.2 | 513518.2 | 91096 | 1.64041666667 | 11414 |
| 011348 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:57pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596807.3 | 513517.2 | 91098 | 1.64041666667 | 11348 |
| 010980 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:58pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596809.5 | 513516.5 | 91100 | 1.64041666667 | 10980 |
| 012386 | 0 | GeoXH 6000 | 08/20/2015 | 01:45:59pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596811.8 | 513515.6 | 91102 | 1.64041666667 | 12386 |
| 012787 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:00pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596813.5 | 513516.1 | 91104 | 1.64041666667 | 12787 |
| 012727 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:01pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596815.4 | 513516.6 | 91106 | 1.64041666667 | 12727 |
| 012701 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:02pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596817.2 | 513517.1 | 91108 | 1.64041666667 | 12701 |
| 013497 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:03pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596819.5 | 513518.3 | 91110 | 1.64041666667 | 13497 |
| 013404 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:04pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596820.9 | 513518.3 | 91112 | 1.64041666667 | 13404 |
| 013157 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:05pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596822.9 | 513518.3 | 91114 | 1.64041666667 | 13157 |
| 013056 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:06pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596824.8 | 513518.3 | 91116 | 1.64041666667 | 13056 |
| 012714 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:07pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596826.8 | 513518.1 | 91118 | 1.64041666667 | 12714 |
| 012424 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:08pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596828.6 | 513518.2 | 91120 | 1.64041666667 | 12424 |
| 012658 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:09pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596831.2 | 513518.1 | 91122 | 1.64041666667 | 12658 |
| 013645 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:10pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596833.3 | 513516.8 | 91124 | 1.64041666667 | 13645 |
| 012760 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:11pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596835.6 | 513515.4 | 91126 | 1.64041666667 | 12760 |
| 013402 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:12pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596837.7 | 513514.3 | 91128 | 1.64041666667 | 13402 |
| 013359 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:13pm | Sensor | 1797-S0054-905-G-ACK | 6851.3 | 1596839.5 | 513512.3 | 91130 | 1.64041666667 | 13359 |
| 013327 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:14pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596840.8 | 513510.6 | 91132 | 1.64041666667 | 13327 |
| 013271 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:15pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596842.9 | 513508.5 | 91134 | 1.64041666667 | 13271 |
| 013082 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:16pm | Sensor | 1797-S0054-905-G-ACK | 6851.5 | 1596845.2 | 513507.1 | 91136 | 1.64041666667 | 13082 |
| 012939 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:17pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596847.7 | 513506.4 | 91138 | 1.64041666667 | 12939 |
| 012903 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:18pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596849.7 | 513505.2 | 91140 | 1.64041666667 | 12903 |
| 012793 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:19pm | Sensor | 1797-S0054-905-G-ACK | 6851.4 | 1596852.0 | 513503.8 | 91142 | 1.64041666667 | 12793 |
| 012086 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:20pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596854.1 | 513502.7 | 91144 | 1.64041666667 | 12086 |
| 012318 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:21pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596857.3 | 513501.5 | 91146 | 1.64041666667 | 12318 |
| 011909 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:22pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596859.6 | 513500.4 | 91148 | 1.64041666667 | 11909 |
| 011993 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:23pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596862.1 | 513498.8 | 91150 | 1.64041666667 | 11993 |
| 011299 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:24pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596864.2 | 513497.3 | 91152 | 1.64041666667 | 11299 |
| 011238 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:25pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596866.6 | 513495.5 | 91154 | 1.64041666667 | 11238 |
| 011076 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:26pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596868.5 | 513493.8 | 91156 | 1.64041666667 | 11076 |
| 010895 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:27pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596870.3 | 513491.5 | 91158 | 1.64041666667 | 10895 |
| 011311 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:28pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596871.6 | 513489.9 | 91160 | 1.64041666667 | 11311 |
| 011965 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:29pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596873.9 | 513488.2 | 91162 | 1.64041666667 | 11965 |
| 011935 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:30pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596876.2 | 513487.1 | 91164 | 1.64041666667 | 11935 |
| 011011 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:31pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596879.0 | 513485.5 | 91166 | 1.64041666667 | 11011 |
| 010648 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:32pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596881.2 | 513484.2 | 91168 | 1.64041666667 | 10648 |
| 010647 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:33pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596884.0 | 513482.7 | 91170 | 1.64041666667 | 10647 |
| 010789 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:34pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596886.3 | 513481.9 | 91172 | 1.64041666667 | 10789 |
| 011483 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:35pm | Sensor | 1797-S0054-905-G-ACK | 6850.9 | 1596888.8 | 513480.6 | 91174 | 1.64041666667 | 11483 |
| 010914 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:36pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596890.6 | 513479.3 | 91176 | 1.64041666667 | 10914 |
| 010669 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:37pm | Sensor | 1797-S0054-905-G-ACK | 6850.8 | 1596892.5 | 513478.4 | 91178 | 1.64041666667 | 10669 |
| 010636 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:38pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596893.5 | 513478.2 | 91180 | 1.64041666667 | 10636 |
| 010700 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:39pm | Sensor | 1797-S0054-905-G-ACK | 6851.0 | 1596894.0 | 513477.3 | 91182 | 1.64041666667 | 10700 |
| 010541 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:40pm | Sensor | 1797-S0054-905-G-ACK | 6851.1 | 1596893.9 | 513477.1 | 91184 | 1.64041666667 | 10541 |
| 010092 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:41pm | Sensor | 1797-S0054-905-G-ACK | 6851.6 | 1596893.9 | 513477.0 | 91186 | 1.64041666667 | 10092 |
| 010034 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:42pm | Sensor | 1797-S0054-905-G-ACK | 6837.6 | 1596892.5 | 513472.3 | 91188 | 1.64041666667 | 10034 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009949 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:43pm | Sensor | 1797-S0054-905-G-ACK | 6842.8 | 1596892.8 | 513475.6 | 91190 | 1.64041666667 | 9949 |
| 010861 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:44pm | Sensor | 1797-S0054-905-G-ACK | 6844.7 | 1596892.9 | 513476.5 | 91192 | 1.64041666667 | 10861 |
| 009859 | 0 | GeoXH 6000 | 08/20/2015 | 01:46:45pm | Sensor | 1797-S0054-905-G-ACK | 6844.7 | 1596893.0 | 513476.5 | 91194 | 1.64041666667 | 9859 |
| 011227 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:08pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596896.0 | 513479.2 | 83880 | 1.64041666667 | 11227 |
| 010328 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:09pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596896.1 | 513479.0 | 83882 | 1.64041666667 | 10328 |
| 009687 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596896.2 | 513478.4 | 83885 | 1.64041666667 | 9687 |
| 009739 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:11pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596896.1 | 513478.0 | 83887 | 1.64041666667 | 9739 |
| 010225 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596895.7 | 513478.4 | 83889 | 1.64041666667 | 10225 |
| 009899 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596895.2 | 513478.7 | 83891 | 1.64041666667 | 9899 |
| 010091 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596895.0 | 513478.8 | 83893 | 1.64041666667 | 10091 |
| 009478 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596894.8 | 513478.8 | 83895 | 1.64041666667 | 9478 |
| 009539 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596894.7 | 513478.7 | 83897 | 1.64041666667 | 9539 |
| 009521 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596894.5 | 513478.7 | 83899 | 1.64041666667 | 9521 |
| 010140 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596894.4 | 513478.7 | 83901 | 1.64041666667 | 10140 |
| 010275 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596894.2 | 513478.6 | 83903 | 1.64041666667 | 10275 |
| 009971 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596894.1 | 513478.6 | 83905 | 1.64041666667 | 9971 |
| 009786 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:21pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596893.9 | 513478.5 | 83907 | 1.64041666667 | 9786 |
| 009840 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:22pm | Sensor | 1797-S0053-905-G-ACK | 6845.1 | 1596893.5 | 513480.8 | 83909 | 1.64041666667 | 9840 |
| 009915 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:23pm | Sensor | 1797-S0053-905-G-ACK | 6843.4 | 1596893.2 | 513482.2 | 83911 | 1.64041666667 | 9915 |
| 009612 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:24pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596893.8 | 513478.2 | 83913 | 1.64041666667 | 9612 |
| 009299 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:25pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596894.2 | 513477.9 | 83915 | 1.64041666667 | 9299 |
| 010023 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596894.9 | 513477.8 | 83917 | 1.64041666667 | 10023 |
| 009943 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:27pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596896.0 | 513478.2 | 83919 | 1.64041666667 | 9943 |
| 010100 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:28pm | Sensor | 1797-S0053-905-G-ACK | 6846.6 | 1596896.1 | 513478.6 | 83921 | 1.64041666667 | 10100 |
| 009964 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:29pm | Sensor | 1797-S0053-905-G-ACK | 6846.5 | 1596895.3 | 513479.2 | 83923 | 1.64041666667 | 9964 |
| 010074 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596893.9 | 513479.8 | 83925 | 1.64041666667 | 10074 |
| 010287 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:31pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596893.6 | 513479.3 | 83927 | 1.64041666667 | 10287 |
| 010601 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:32pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596893.4 | 513479.7 | 83929 | 1.64041666667 | 10601 |
| 010320 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:33pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596893.1 | 513480.1 | 83931 | 1.64041666667 | 10320 |
| 010868 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:34pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596893.7 | 513479.6 | 83933 | 1.64041666667 | 10868 |
| 010881 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:35pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596894.9 | 513478.2 | 83935 | 1.64041666667 | 10881 |
| 010836 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:36pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596894.9 | 513478.4 | 83937 | 1.64041666667 | 10836 |
| 010895 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:37pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596894.8 | 513478.2 | 83939 | 1.64041666667 | 10895 |
| 010261 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:38pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596894.3 | 513477.6 | 83941 | 1.64041666667 | 10261 |
| 010684 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:39pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596893.2 | 513477.5 | 83943 | 1.64041666667 | 10684 |
| 010735 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:40pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596891.2 | 513478.3 | 83945 | 1.64041666667 | 10735 |
| 010898 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:41pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596888.4 | 513478.4 | 83947 | 1.64041666667 | 10898 |
| 011373 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:42pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596885.4 | 513477.8 | 83949 | 1.64041666667 | 11373 |
| 012029 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:43pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596882.6 | 513477.1 | 83951 | 1.64041666667 | 12029 |
| 011686 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:44pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596879.5 | 513476.4 | 83953 | 1.64041666667 | 11686 |
| 011666 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:45pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596876.8 | 513475.5 | 83955 | 1.64041666667 | 11666 |
| 010964 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:46pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596873.6 | 513474.0 | 83957 | 1.64041666667 | 10964 |
| 011080 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:47pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596870.4 | 513472.7 | 83959 | 1.64041666667 | 11080 |
| 011610 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:48pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596866.7 | 513471.7 | 83961 | 1.64041666667 | 11610 |
| 011975 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:49pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596863.6 | 513471.1 | 83963 | 1.64041666667 | 11975 |
| 011401 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:50pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596859.4 | 513470.4 | 83965 | 1.64041666667 | 11401 |
| 010920 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:51pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596856.4 | 513469.9 | 83967 | 1.64041666667 | 10920 |
| 011010 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:52pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596852.6 | 513469.2 | 83969 | 1.64041666667 | 11010 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011420 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:53pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596849.3 | 513468.7 | 83971 | 1.64041666667 | 11420 |
| 011066 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:54pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596845.6 | 513468.4 | 83973 | 1.64041666667 | 11066 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:55pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596842.1 | 513468.2 | 83975 | 1.64041666667 | 11205 |
| 011313 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:56pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596838.4 | 513468.1 | 83977 | 1.64041666667 | 11313 |
| 010773 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:57pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596834.9 | 513467.9 | 83979 | 1.64041666667 | 10773 |
| 011497 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:58pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596831.5 | 513467.1 | 83981 | 1.64041666667 | 11497 |
| 010772 | 0 | GeoXH 6000 | 08/20/2015 | 12:45:59pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596828.7 | 513466.2 | 83983 | 1.64041666667 | 10772 |
| 011077 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:00pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596825.6 | 513465.4 | 83985 | 1.64041666667 | 11077 |
| 011263 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:01pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596823.2 | 513464.5 | 83987 | 1.64041666667 | 11263 |
| 010978 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:02pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596820.3 | 513462.5 | 83989 | 1.64041666667 | 10978 |
| 011515 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:03pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596818.1 | 513460.7 | 83991 | 1.64041666667 | 11515 |
| 012484 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:04pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596815.2 | 513458.6 | 83993 | 1.64041666667 | 12484 |
| 012295 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:05pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596812.8 | 513456.8 | 83995 | 1.64041666667 | 12295 |
| 013148 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:06pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596810.2 | 513454.4 | 83997 | 1.64041666667 | 13148 |
| 012511 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:07pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596808.4 | 513452.0 | 83999 | 1.64041666667 | 12511 |
| 012647 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:08pm | Sensor | 1797-S0053-905-G-ACK | 6851.3 | 1596807.2 | 513450.0 | 84001 | 1.64041666667 | 12647 |
| 012101 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:09pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596806.9 | 513449.8 | 84003 | 1.64041666667 | 12101 |
| 013542 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:10pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596807.1 | 513450.8 | 84005 | 1.64041666667 | 13542 |
| 013745 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:11pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.0 | 513451.0 | 84007 | 1.64041666667 | 13745 |
| 013589 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:12pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.0 | 513451.0 | 84009 | 1.64041666667 | 13589 |
| 012833 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:13pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.0 | 513451.0 | 84011 | 1.64041666667 | 12833 |
| 012521 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:14pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.0 | 513451.0 | 84013 | 1.64041666667 | 12521 |
| 012165 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:15pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.0 | 513451.0 | 84015 | 1.64041666667 | 12165 |
| 013646 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:16pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.0 | 513451.0 | 84017 | 1.64041666667 | 13646 |
| 013136 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:17pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.1 | 513451.0 | 84019 | 1.64041666667 | 13136 |
| 013471 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:18pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.1 | 513451.0 | 84021 | 1.64041666667 | 13471 |
| 013645 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:19pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596807.1 | 513451.0 | 84023 | 1.64041666667 | 13645 |
| 013248 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:20pm | Sensor | 1797-S0053-905-G-ACK | 6851.3 | 1596807.4 | 513450.8 | 84025 | 1.64041666667 | 13248 |
| 013189 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:21pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596808.5 | 513450.6 | 84027 | 1.64041666667 | 13189 |
| 012519 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:22pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596810.5 | 513450.7 | 84029 | 1.64041666667 | 12519 |
| 012367 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:23pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596811.7 | 513450.8 | 84031 | 1.64041666667 | 12367 |
| 012986 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:24pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.3 | 513451.0 | 84033 | 1.64041666667 | 12986 |
| 013327 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:25pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.2 | 84035 | 1.64041666667 | 13327 |
| 012491 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:26pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.2 | 84037 | 1.64041666667 | 12491 |
| 012936 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:27pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.2 | 84039 | 1.64041666667 | 12936 |
| 012549 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:28pm | Sensor | 1797-S0053-905-G-ACK | 6851.3 | 1596812.4 | 513451.2 | 84041 | 1.64041666667 | 12549 |
| 013351 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:29pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.2 | 84043 | 1.64041666667 | 13351 |
| 013097 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:30pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.2 | 84045 | 1.64041666667 | 13097 |
| 013292 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:31pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.2 | 84047 | 1.64041666667 | 13292 |
| 013702 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:32pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596812.4 | 513451.2 | 84049 | 1.64041666667 | 13702 |
| 013145 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:33pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596812.5 | 513451.2 | 84051 | 1.64041666667 | 13145 |
| 013334 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:34pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.5 | 513451.2 | 84053 | 1.64041666667 | 13334 |
| 013102 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:35pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.5 | 513451.2 | 84055 | 1.64041666667 | 13102 |
| 012890 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:36pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.2 | 84057 | 1.64041666667 | 12890 |
| 012950 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:37pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.1 | 84059 | 1.64041666667 | 12950 |
| 013045 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:38pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596812.5 | 513451.1 | 84061 | 1.64041666667 | 13045 |
| 012625 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:39pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.5 | 513451.1 | 84063 | 1.64041666667 | 12625 |
| 013169 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:40pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.5 | 513451.1 | 84065 | 1.64041666667 | 13169 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013355 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:41pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.1 | 84067 | 1.64041666667 | 13355 |
| 014239 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:42pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.1 | 84069 | 1.64041666667 | 14239 |
| 013590 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:43pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.1 | 84071 | 1.64041666667 | 13590 |
| 014214 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:44pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.1 | 84073 | 1.64041666667 | 14214 |
| 012923 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:45pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.1 | 84075 | 1.64041666667 | 12923 |
| 012444 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:46pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.5 | 513451.2 | 84077 | 1.64041666667 | 12444 |
| 013007 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:47pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.5 | 513451.2 | 84079 | 1.64041666667 | 13007 |
| 013039 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:48pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.5 | 513451.3 | 84081 | 1.64041666667 | 13039 |
| 012892 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:49pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596812.4 | 513451.2 | 84083 | 1.64041666667 | 12892 |
| 012269 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:50pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596811.9 | 513450.8 | 84085 | 1.64041666667 | 12269 |
| 012481 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:51pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596811.2 | 513450.2 | 84087 | 1.64041666667 | 12481 |
| 012998 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:52pm | Sensor | 1797-S0053-905-G-ACK | 6851.7 | 1596809.5 | 513449.3 | 84089 | 1.64041666667 | 12998 |
| 012824 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:53pm | Sensor | 1797-S0053-905-G-ACK | 6851.7 | 1596807.3 | 513448.5 | 84091 | 1.64041666667 | 12824 |
| 013656 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:54pm | Sensor | 1797-S0053-905-G-ACK | 6851.7 | 1596804.6 | 513447.1 | 84093 | 1.64041666667 | 13656 |
| 014011 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:55pm | Sensor | 1797-S0053-905-G-ACK | 6851.8 | 1596802.7 | 513445.0 | 84095 | 1.64041666667 | 14011 |
| 013476 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:56pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596802.0 | 513442.4 | 84097 | 1.64041666667 | 13476 |
| 013948 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:57pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596802.6 | 513439.4 | 84099 | 1.64041666667 | 13948 |
| 013770 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:58pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596803.9 | 513435.7 | 84101 | 1.64041666667 | 13770 |
| 013716 | 0 | GeoXH 6000 | 08/20/2015 | 12:46:59pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596804.4 | 513432.8 | 84103 | 1.64041666667 | 13716 |
| 014247 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:00pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596804.7 | 513429.3 | 84105 | 1.64041666667 | 14247 |
| 014524 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:01pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596805.1 | 513426.2 | 84107 | 1.64041666667 | 14524 |
| 014815 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:02pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596805.6 | 513423.1 | 84109 | 1.64041666667 | 14815 |
| 014498 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:03pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596805.6 | 513420.9 | 84111 | 1.64041666667 | 14498 |
| 014118 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:04pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596805.1 | 513418.3 | 84113 | 1.64041666667 | 14118 |
| 013873 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:05pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596804.6 | 513416.4 | 84115 | 1.64041666667 | 13873 |
| 013916 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:06pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596803.7 | 513414.7 | 84117 | 1.64041666667 | 13916 |
| 013535 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:07pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596803.5 | 513413.5 | 84119 | 1.64041666667 | 13535 |
| 012938 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:08pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596803.3 | 513412.6 | 84121 | 1.64041666667 | 12938 |
| 012573 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:09pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596802.7 | 513412.6 | 84123 | 1.64041666667 | 12573 |
| 013252 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:10pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596802.4 | 513412.6 | 84125 | 1.64041666667 | 13252 |
| 013334 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:11pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596802.4 | 513412.6 | 84127 | 1.64041666667 | 13334 |
| 012983 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:12pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596802.4 | 513412.6 | 84129 | 1.64041666667 | 12983 |
| 012245 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:13pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596802.4 | 513412.6 | 84131 | 1.64041666667 | 12245 |
| 012888 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:14pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596802.3 | 513412.5 | 84133 | 1.64041666667 | 12888 |
| 013272 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:15pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596802.1 | 513411.7 | 84135 | 1.64041666667 | 13272 |
| 013248 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:16pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596801.1 | 513408.9 | 84137 | 1.64041666667 | 13248 |
| 012784 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:17pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596799.2 | 513406.3 | 84139 | 1.64041666667 | 12784 |
| 013273 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:18pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596797.6 | 513403.5 | 84141 | 1.64041666667 | 13273 |
| 014395 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:19pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596796.3 | 513401.0 | 84143 | 1.64041666667 | 14395 |
| 013537 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:20pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596795.0 | 513397.8 | 84145 | 1.64041666667 | 13537 |
| 013029 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:21pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596793.8 | 513394.9 | 84147 | 1.64041666667 | 13029 |
| 012091 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:22pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596792.0 | 513391.9 | 84149 | 1.64041666667 | 12091 |
| 012344 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:23pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596790.5 | 513389.7 | 84151 | 1.64041666667 | 12344 |
| 012036 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:24pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596788.4 | 513387.0 | 84153 | 1.64041666667 | 12036 |
| 012252 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:25pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596786.9 | 513384.9 | 84155 | 1.64041666667 | 12252 |
| 012119 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:26pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596785.1 | 513381.9 | 84157 | 1.64041666667 | 12119 |
| 012735 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:27pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596783.9 | 513379.2 | 84159 | 1.64041666667 | 12735 |
| 012818 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:28pm | Sensor | 1797-S0053-905-G-ACK | 6852.0 | 1596782.6 | 513376.2 | 84161 | 1.64041666667 | 12818 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012992 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:29pm | Sensor | 1797-S0053-905-G-ACK | 6852.2 | 1596781.4 | 513373.4 | 84163 | 1.64041666667 | 12992 |
| 013368 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:30pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596780.5 | 513369.7 | 84165 | 1.64041666667 | 13368 |
| 013917 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:31pm | Sensor | 1797-S0053-905-G-ACK | 6852.2 | 1596779.9 | 513366.9 | 84167 | 1.64041666667 | 13917 |
| 015343 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:32pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596779.0 | 513363.8 | 84169 | 1.64041666667 | 15343 |
| 016010 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:33pm | Sensor | 1797-S0053-905-G-ACK | 6852.4 | 1596777.5 | 513361.1 | 84171 | 1.64041666667 | 16010 |
| 015673 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:34pm | Sensor | 1797-S0053-905-G-ACK | 6852.4 | 1596775.8 | 513358.8 | 84173 | 1.64041666667 | 15673 |
| 015986 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:35pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596774.3 | 513356.1 | 84175 | 1.64041666667 | 15986 |
| 016230 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:36pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596772.6 | 513353.3 | 84177 | 1.64041666667 | 16230 |
| 015609 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:37pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596771.3 | 513350.9 | 84179 | 1.64041666667 | 15609 |
| 015567 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:38pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596770.1 | 513348.4 | 84181 | 1.64041666667 | 15567 |
| 015746 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:39pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596770.0 | 513345.9 | 84183 | 1.64041666667 | 15746 |
| 015307 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:40pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596770.2 | 513342.6 | 84185 | 1.64041666667 | 15307 |
| 014910 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:41pm | Sensor | 1797-S0053-905-G-ACK | 6852.4 | 1596769.6 | 513340.0 | 84187 | 1.64041666667 | 14910 |
| 014147 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:42pm | Sensor | 1797-S0053-905-G-ACK | 6852.2 | 1596768.2 | 513337.1 | 84189 | 1.64041666667 | 14147 |
| 014302 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:43pm | Sensor | 1797-S0053-905-G-ACK | 6852.3 | 1596767.2 | 513334.4 | 84191 | 1.64041666667 | 14302 |
| 014720 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:44pm | Sensor | 1797-S0053-905-G-ACK | 6852.2 | 1596766.4 | 513331.0 | 84193 | 1.64041666667 | 14720 |
| 014467 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:45pm | Sensor | 1797-S0053-905-G-ACK | 6852.2 | 1596765.4 | 513328.7 | 84195 | 1.64041666667 | 14467 |
| 013935 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:46pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596763.5 | 513325.4 | 84197 | 1.64041666667 | 13935 |
| 013876 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:47pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596761.9 | 513323.2 | 84199 | 1.64041666667 | 13876 |
| 013693 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:48pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596761.0 | 513320.7 | 84201 | 1.64041666667 | 13693 |
| 013357 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:49pm | Sensor | 1797-S0053-905-G-ACK | 6852.2 | 1596761.5 | 513318.4 | 84203 | 1.64041666667 | 13357 |
| 013663 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:50pm | Sensor | 1797-S0053-905-G-ACK | 6852.2 | 1596761.1 | 513315.9 | 84205 | 1.64041666667 | 13663 |
| 013183 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:51pm | Sensor | 1797-S0053-905-G-ACK | 6852.1 | 1596759.7 | 513314.0 | 84207 | 1.64041666667 | 13183 |
| 012995 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:52pm | Sensor | 1797-S0053-905-G-ACK | 6851.9 | 1596758.7 | 513311.8 | 84209 | 1.64041666667 | 12995 |
| 013527 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:53pm | Sensor | 1797-S0053-905-G-ACK | 6851.8 | 1596758.5 | 513309.2 | 84211 | 1.64041666667 | 13527 |
| 013429 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:54pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596758.7 | 513306.6 | 84213 | 1.64041666667 | 13429 |
| 013073 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:55pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596758.8 | 513303.6 | 84215 | 1.64041666667 | 13073 |
| 013706 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:56pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596758.9 | 513300.2 | 84217 | 1.64041666667 | 13706 |
| 013260 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:57pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596758.8 | 513297.5 | 84219 | 1.64041666667 | 13260 |
| 013226 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:58pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596758.5 | 513294.9 | 84221 | 1.64041666667 | 13226 |
| 012344 | 0 | GeoXH 6000 | 08/20/2015 | 12:47:59pm | Sensor | 1797-S0053-905-G-ACK | 6851.3 | 1596757.7 | 513292.2 | 84223 | 1.64041666667 | 12344 |
| 012831 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:00pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596756.3 | 513290.0 | 84225 | 1.64041666667 | 12831 |
| 011882 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:01pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596755.2 | 513287.6 | 84227 | 1.64041666667 | 11882 |
| 011971 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:02pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596753.9 | 513284.4 | 84229 | 1.64041666667 | 11971 |
| 011601 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:03pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596753.7 | 513281.2 | 84231 | 1.64041666667 | 11601 |
| 011528 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:04pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596754.1 | 513278.2 | 84233 | 1.64041666667 | 11528 |
| 011944 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:05pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596754.3 | 513275.3 | 84235 | 1.64041666667 | 11944 |
| 011256 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:06pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596755.2 | 513272.6 | 84237 | 1.64041666667 | 11256 |
| 011184 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:07pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596756.7 | 513270.6 | 84239 | 1.64041666667 | 11184 |
| 011998 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:08pm | Sensor | 1797-S0053-905-G-ACK | 6851.3 | 1596758.9 | 513268.9 | 84241 | 1.64041666667 | 11998 |
| 011294 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:09pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596760.8 | 513267.1 | 84243 | 1.64041666667 | 11294 |
| 011280 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:10pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596762.4 | 513264.6 | 84245 | 1.64041666667 | 11280 |
| 011580 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:11pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596763.3 | 513262.0 | 84247 | 1.64041666667 | 11580 |
| 011757 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:12pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596764.0 | 513259.2 | 84249 | 1.64041666667 | 11757 |
| 011053 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:13pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596764.3 | 513256.4 | 84251 | 1.64041666667 | 11053 |
| 011295 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:14pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596764.5 | 513253.3 | 84253 | 1.64041666667 | 11295 |
| 012023 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:15pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596764.5 | 513250.4 | 84255 | 1.64041666667 | 12023 |
| 010738 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:16pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596764.6 | 513247.2 | 84257 | 1.64041666667 | 10738 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011335 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:17pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596764.7 | 513244.8 | 84259 | 1.64041666667 | 11335 |
| 011513 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:18pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596765.3 | 513241.8 | 84261 | 1.64041666667 | 11513 |
| 011313 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:19pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596765.3 | 513239.2 | 84263 | 1.64041666667 | 11313 |
| 010391 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:20pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596764.6 | 513236.7 | 84265 | 1.64041666667 | 10391 |
| 010037 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:21pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596764.0 | 513234.1 | 84267 | 1.64041666667 | 10037 |
| 009426 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:22pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596763.9 | 513231.3 | 84269 | 1.64041666667 | 9426 |
| 010035 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:23pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596763.3 | 513228.2 | 84271 | 1.64041666667 | 10035 |
| 010002 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:24pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596762.6 | 513224.7 | 84273 | 1.64041666667 | 10002 |
| 010171 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:25pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596762.4 | 513221.8 | 84275 | 1.64041666667 | 10171 |
| 010266 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:26pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596762.6 | 513218.3 | 84277 | 1.64041666667 | 10266 |
| 010342 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:27pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596763.2 | 513215.5 | 84279 | 1.64041666667 | 10342 |
| 011780 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:28pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596764.0 | 513212.3 | 84281 | 1.64041666667 | 11780 |
| 011283 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:29pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596764.0 | 513209.9 | 84283 | 1.64041666667 | 11283 |
| 010577 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:30pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596763.0 | 513207.2 | 84285 | 1.64041666667 | 10577 |
| 010607 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:31pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596762.8 | 513205.1 | 84287 | 1.64041666667 | 10607 |
| 010586 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:32pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596764.5 | 513203.2 | 84289 | 1.64041666667 | 10586 |
| 010567 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:33pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596766.0 | 513201.6 | 84291 | 1.64041666667 | 10567 |
| 010264 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:34pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596768.2 | 513199.8 | 84293 | 1.64041666667 | 10264 |
| 009688 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:35pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596770.4 | 513198.1 | 84295 | 1.64041666667 | 9688 |
| 009552 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:36pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596772.7 | 513196.4 | 84297 | 1.64041666667 | 9552 |
| 010008 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:37pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596774.1 | 513194.3 | 84299 | 1.64041666667 | 10008 |
| 010107 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:38pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596774.9 | 513191.6 | 84301 | 1.64041666667 | 10107 |
| 010192 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:39pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596776.0 | 513188.8 | 84303 | 1.64041666667 | 10192 |
| 010773 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:40pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596777.4 | 513185.9 | 84305 | 1.64041666667 | 10773 |
| 010710 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:41pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596778.9 | 513183.4 | 84307 | 1.64041666667 | 10710 |
| 010989 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:42pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596780.5 | 513180.4 | 84309 | 1.64041666667 | 10989 |
| 012294 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:43pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596781.4 | 513177.9 | 84311 | 1.64041666667 | 12294 |
| 011422 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:44pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596782.0 | 513174.9 | 84313 | 1.64041666667 | 11422 |
| 011105 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:45pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596782.2 | 513172.0 | 84315 | 1.64041666667 | 11105 |
| 011204 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:46pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596782.3 | 513168.7 | 84317 | 1.64041666667 | 11204 |
| 011462 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:47pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596782.3 | 513165.8 | 84319 | 1.64041666667 | 11462 |
| 011315 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:48pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596782.0 | 513162.1 | 84321 | 1.64041666667 | 11315 |
| 011119 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:49pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596781.9 | 513159.5 | 84323 | 1.64041666667 | 11119 |
| 011752 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:50pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596781.9 | 513156.3 | 84325 | 1.64041666667 | 11752 |
| 010758 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:51pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596781.9 | 513153.4 | 84327 | 1.64041666667 | 10758 |
| 010799 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:52pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596782.3 | 513150.3 | 84329 | 1.64041666667 | 10799 |
| 010544 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:53pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596783.2 | 513147.4 | 84331 | 1.64041666667 | 10544 |
| 010281 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:54pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596783.8 | 513144.5 | 84333 | 1.64041666667 | 10281 |
| 010418 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:55pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596783.8 | 513141.5 | 84335 | 1.64041666667 | 10418 |
| 011222 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:56pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596783.9 | 513138.6 | 84337 | 1.64041666667 | 11222 |
| 012132 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:57pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596784.7 | 513136.4 | 84339 | 1.64041666667 | 12132 |
| 012622 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:58pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596786.1 | 513133.6 | 84341 | 1.64041666667 | 12622 |
| 012882 | 0 | GeoXH 6000 | 08/20/2015 | 12:48:59pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596787.0 | 513131.0 | 84343 | 1.64041666667 | 12882 |
| 012353 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:00pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596787.7 | 513128.2 | 84345 | 1.64041666667 | 12353 |
| 011351 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:01pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596789.0 | 513125.4 | 84347 | 1.64041666667 | 11351 |
| 010690 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:02pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596790.4 | 513122.8 | 84349 | 1.64041666667 | 10690 |
| 010873 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:03pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596791.4 | 513120.1 | 84351 | 1.64041666667 | 10873 |
| 010533 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:04pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596791.6 | 513116.9 | 84353 | 1.64041666667 | 10533 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010732 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:05pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596791.3 | 513114.4 | 84355 | 1.64041666667 | 10732 |
| 010432 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:06pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596791.5 | 513111.0 | 84357 | 1.64041666667 | 10432 |
| 011140 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:07pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596792.3 | 513108.4 | 84359 | 1.64041666667 | 11140 |
| 010616 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:08pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596793.3 | 513105.6 | 84361 | 1.64041666667 | 10616 |
| 010179 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:09pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596794.3 | 513103.0 | 84363 | 1.64041666667 | 10179 |
| 010803 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:10pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596795.3 | 513100.4 | 84365 | 1.64041666667 | 10803 |
| 010682 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:11pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596796.1 | 513098.1 | 84367 | 1.64041666667 | 10682 |
| 010568 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:12pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596796.2 | 513095.0 | 84369 | 1.64041666667 | 10568 |
| 011134 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:13pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596795.7 | 513092.7 | 84371 | 1.64041666667 | 11134 |
| 011700 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:14pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596794.9 | 513090.1 | 84373 | 1.64041666667 | 11700 |
| 011306 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:15pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596794.2 | 513087.8 | 84375 | 1.64041666667 | 11306 |
| 012030 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:16pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596792.5 | 513085.2 | 84377 | 1.64041666667 | 12030 |
| 011792 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:17pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596791.7 | 513082.8 | 84379 | 1.64041666667 | 11792 |
| 011935 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:18pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596791.5 | 513080.1 | 84381 | 1.64041666667 | 11935 |
| 012541 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:19pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596791.4 | 513077.5 | 84383 | 1.64041666667 | 12541 |
| 012454 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:20pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596791.0 | 513074.7 | 84385 | 1.64041666667 | 12454 |
| 012480 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:21pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596790.6 | 513072.4 | 84387 | 1.64041666667 | 12480 |
| 012352 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:22pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596790.1 | 513070.0 | 84389 | 1.64041666667 | 12352 |
| 011748 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:23pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596789.1 | 513067.7 | 84391 | 1.64041666667 | 11748 |
| 012188 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:24pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596787.4 | 513065.5 | 84393 | 1.64041666667 | 12188 |
| 012301 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:25pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596785.8 | 513063.6 | 84395 | 1.64041666667 | 12301 |
| 011771 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:26pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596784.0 | 513060.3 | 84397 | 1.64041666667 | 11771 |
| 012089 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:27pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596782.7 | 513057.8 | 84399 | 1.64041666667 | 12089 |
| 011540 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:28pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596781.7 | 513055.1 | 84401 | 1.64041666667 | 11540 |
| 012311 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:29pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596781.2 | 513052.6 | 84403 | 1.64041666667 | 12311 |
| 011522 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:30pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596781.2 | 513049.6 | 84405 | 1.64041666667 | 11522 |
| 011949 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:31pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596780.8 | 513047.1 | 84407 | 1.64041666667 | 11949 |
| 012391 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:32pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596780.2 | 513044.5 | 84409 | 1.64041666667 | 12391 |
| 012323 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:33pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596779.4 | 513041.7 | 84411 | 1.64041666667 | 12323 |
| 011399 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:34pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596778.9 | 513038.9 | 84413 | 1.64041666667 | 11399 |
| 011100 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:35pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596778.7 | 513036.3 | 84415 | 1.64041666667 | 11100 |
| 011246 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:36pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596777.5 | 513033.9 | 84417 | 1.64041666667 | 11246 |
| 011238 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:37pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596776.0 | 513031.8 | 84419 | 1.64041666667 | 11238 |
| 011001 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:38pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596774.2 | 513029.0 | 84421 | 1.64041666667 | 11001 |
| 011363 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:39pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596772.4 | 513026.9 | 84423 | 1.64041666667 | 11363 |
| 011267 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:40pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596769.8 | 513025.0 | 84425 | 1.64041666667 | 11267 |
| 012090 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:41pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596767.4 | 513023.8 | 84427 | 1.64041666667 | 12090 |
| 011713 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:42pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596765.0 | 513022.8 | 84429 | 1.64041666667 | 11713 |
| 011906 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:43pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596762.9 | 513021.9 | 84431 | 1.64041666667 | 11906 |
| 011295 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:44pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596760.3 | 513021.3 | 84433 | 1.64041666667 | 11295 |
| 012128 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:45pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596757.9 | 513021.6 | 84435 | 1.64041666667 | 12128 |
| 010999 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:46pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596755.3 | 513023.0 | 84437 | 1.64041666667 | 10999 |
| 011647 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:47pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596753.7 | 513024.0 | 84439 | 1.64041666667 | 11647 |
| 012154 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:48pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596751.1 | 513025.8 | 84441 | 1.64041666667 | 12154 |
| 011449 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:49pm | Sensor | 1797-S0053-905-G-ACK | 6849.2 | 1596749.4 | 513027.4 | 84443 | 1.64041666667 | 11449 |
| 012320 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:50pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596747.3 | 513029.7 | 84445 | 1.64041666667 | 12320 |
| 012300 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:51pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596745.5 | 513031.1 | 84447 | 1.64041666667 | 12300 |
| 011096 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:52pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596743.1 | 513032.3 | 84449 | 1.64041666667 | 11096 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010561 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:53pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596741.7 | 513033.3 | 84451 | 1.64041666667 | 10561 |
| 010755 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:54pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596740.5 | 513034.0 | 84453 | 1.64041666667 | 10755 |
| 011052 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:55pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596739.9 | 513033.9 | 84455 | 1.64041666667 | 11052 |
| 011009 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:56pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596739.9 | 513033.9 | 84457 | 1.64041666667 | 11009 |
| 010520 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:57pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596740.0 | 513033.9 | 84459 | 1.64041666667 | 10520 |
| 010552 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:58pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596740.7 | 513034.1 | 84461 | 1.64041666667 | 10552 |
| 010961 | 0 | GeoXH 6000 | 08/20/2015 | 12:49:59pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596741.1 | 513034.1 | 84463 | 1.64041666667 | 10961 |
| 011265 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:00pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596739.8 | 513034.0 | 84465 | 1.64041666667 | 11265 |
| 013244 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:01pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596738.5 | 513034.4 | 84467 | 1.64041666667 | 13244 |
| 012437 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:02pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596737.1 | 513033.5 | 84469 | 1.64041666667 | 12437 |
| 012486 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:03pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596736.4 | 513033.0 | 84471 | 1.64041666667 | 12486 |
| 012378 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:04pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596735.1 | 513031.7 | 84473 | 1.64041666667 | 12378 |
| 011620 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:05pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596733.9 | 513030.4 | 84475 | 1.64041666667 | 11620 |
| 011786 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:06pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596731.7 | 513029.7 | 84477 | 1.64041666667 | 11786 |
| 012225 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:07pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596729.5 | 513028.8 | 84479 | 1.64041666667 | 12225 |
| 012449 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:08pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596727.4 | 513027.9 | 84481 | 1.64041666667 | 12449 |
| 012065 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:09pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596725.6 | 513027.6 | 84483 | 1.64041666667 | 12065 |
| 012179 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:10pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596723.4 | 513028.0 | 84485 | 1.64041666667 | 12179 |
| 013705 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:11pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596720.7 | 513028.3 | 84487 | 1.64041666667 | 13705 |
| 013199 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:12pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596717.4 | 513028.2 | 84489 | 1.64041666667 | 13199 |
| 013514 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:13pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596714.6 | 513028.0 | 84491 | 1.64041666667 | 13514 |
| 013549 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:14pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596711.4 | 513027.8 | 84493 | 1.64041666667 | 13549 |
| 013314 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:15pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596708.8 | 513028.0 | 84495 | 1.64041666667 | 13314 |
| 012634 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:16pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596706.0 | 513027.9 | 84497 | 1.64041666667 | 12634 |
| 013069 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596703.2 | 513027.4 | 84499 | 1.64041666667 | 13069 |
| 013298 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596700.1 | 513027.0 | 84501 | 1.64041666667 | 13298 |
| 013533 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596697.8 | 513027.0 | 84503 | 1.64041666667 | 13533 |
| 013620 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596695.0 | 513027.1 | 84505 | 1.64041666667 | 13620 |
| 014058 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596692.4 | 513026.4 | 84507 | 1.64041666667 | 14058 |
| 013113 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596689.9 | 513025.1 | 84509 | 1.64041666667 | 13113 |
| 012933 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596688.1 | 513023.7 | 84511 | 1.64041666667 | 12933 |
| 012180 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596686.2 | 513021.9 | 84513 | 1.64041666667 | 12180 |
| 012371 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596684.9 | 513019.9 | 84515 | 1.64041666667 | 12371 |
| 012209 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596683.2 | 513017.6 | 84517 | 1.64041666667 | 12209 |
| 012065 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596681.9 | 513016.7 | 84519 | 1.64041666667 | 12065 |
| 012561 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596680.6 | 513017.7 | 84521 | 1.64041666667 | 12561 |
| 012165 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596679.1 | 513019.1 | 84523 | 1.64041666667 | 12165 |
| 013563 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596677.6 | 513021.5 | 84525 | 1.64041666667 | 13563 |
| 012347 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596676.7 | 513023.4 | 84527 | 1.64041666667 | 12347 |
| 013357 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596674.8 | 513025.8 | 84529 | 1.64041666667 | 13357 |
| 012966 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596672.9 | 513027.8 | 84531 | 1.64041666667 | 12966 |
| 012746 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596670.9 | 513029.5 | 84533 | 1.64041666667 | 12746 |
| 012247 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596669.0 | 513031.0 | 84535 | 1.64041666667 | 12247 |
| 014449 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596666.7 | 513032.9 | 84537 | 1.64041666667 | 14449 |
| 014345 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596664.5 | 513034.2 | 84539 | 1.64041666667 | 14345 |
| 013956 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596662.1 | 513035.4 | 84541 | 1.64041666667 | 13956 |
| 013835 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596659.8 | 513036.1 | 84543 | 1.64041666667 | 13835 |
| 013572 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596656.8 | 513036.3 | 84545 | 1.64041666667 | 13572 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013199 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596654.2 | 513035.7 | 84547 | 1.64041666667 | 13199 |
| 012622 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596651.2 | 513034.8 | 84549 | 1.64041666667 | 12622 |
| 012425 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596648.6 | 513034.2 | 84551 | 1.64041666667 | 12425 |
| 012299 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596645.3 | 513033.7 | 84553 | 1.64041666667 | 12299 |
| 011973 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596642.6 | 513033.6 | 84555 | 1.64041666667 | 11973 |
| 012712 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596639.5 | 513033.3 | 84557 | 1.64041666667 | 12712 |
| 012430 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596636.7 | 513032.6 | 84559 | 1.64041666667 | 12430 |
| 012474 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596633.7 | 513031.6 | 84561 | 1.64041666667 | 12474 |
| 012596 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596631.2 | 513031.1 | 84563 | 1.64041666667 | 12596 |
| 012969 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596628.3 | 513031.4 | 84565 | 1.64041666667 | 12969 |
| 013483 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596625.4 | 513031.8 | 84567 | 1.64041666667 | 13483 |
| 013404 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596622.5 | 513031.8 | 84569 | 1.64041666667 | 13404 |
| 013862 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596619.4 | 513031.4 | 84571 | 1.64041666667 | 13862 |
| 012987 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596616.7 | 513031.2 | 84573 | 1.64041666667 | 12987 |
| 013530 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596614.2 | 513031.4 | 84575 | 1.64041666667 | 13530 |
| 012508 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596611.6 | 513031.2 | 84577 | 1.64041666667 | 12508 |
| 012563 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596609.8 | 513030.4 | 84579 | 1.64041666667 | 12563 |
| 012542 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596608.3 | 513028.5 | 84581 | 1.64041666667 | 12542 |
| 012259 | 0 | GeoXH 6000 | 08/20/2015 | 12:50:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596607.0 | 513026.6 | 84583 | 1.64041666667 | 12259 |
| 011958 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596605.9 | 513023.9 | 84585 | 1.64041666667 | 11958 |
| 012974 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596605.1 | 513021.7 | 84587 | 1.64041666667 | 12974 |
| 013118 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596603.7 | 513019.2 | 84589 | 1.64041666667 | 13118 |
| 012711 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596602.0 | 513017.2 | 84591 | 1.64041666667 | 12711 |
| 014117 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596600.2 | 513015.3 | 84593 | 1.64041666667 | 14117 |
| 013483 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596598.9 | 513013.1 | 84595 | 1.64041666667 | 13483 |
| 013022 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596597.8 | 513010.1 | 84597 | 1.64041666667 | 13022 |
| 012650 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596596.7 | 513007.7 | 84599 | 1.64041666667 | 12650 |
| 012800 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596595.3 | 513005.4 | 84601 | 1.64041666667 | 12800 |
| 013447 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596594.3 | 513003.6 | 84603 | 1.64041666667 | 13447 |
| 013189 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596594.1 | 513002.3 | 84605 | 1.64041666667 | 13189 |
| 013351 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596594.1 | 513002.1 | 84607 | 1.64041666667 | 13351 |
| 013495 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596594.3 | 513002.3 | 84609 | 1.64041666667 | 13495 |
| 013493 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596594.4 | 513002.4 | 84611 | 1.64041666667 | 13493 |
| 013665 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596594.4 | 513002.4 | 84613 | 1.64041666667 | 13665 |
| 013139 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596594.4 | 513002.4 | 84615 | 1.64041666667 | 13139 |
| 012783 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596594.4 | 513002.4 | 84617 | 1.64041666667 | 12783 |
| 012883 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596594.4 | 513002.4 | 84619 | 1.64041666667 | 12883 |
| 013464 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596594.4 | 513002.4 | 84621 | 1.64041666667 | 13464 |
| 012831 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596594.3 | 513002.5 | 84623 | 1.64041666667 | 12831 |
| 013157 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.7 | 513002.5 | 84625 | 1.64041666667 | 13157 |
| 013528 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.4 | 513002.5 | 84627 | 1.64041666667 | 13528 |
| 013504 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.3 | 513002.5 | 84629 | 1.64041666667 | 13504 |
| 013634 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.3 | 513002.4 | 84631 | 1.64041666667 | 13634 |
| 014164 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.6 | 513001.7 | 84633 | 1.64041666667 | 14164 |
| 014042 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.9 | 513000.2 | 84635 | 1.64041666667 | 14042 |
| 013996 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.0 | 512998.9 | 84637 | 1.64041666667 | 13996 |
| 013955 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596592.7 | 512997.5 | 84639 | 1.64041666667 | 13955 |
| 013999 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596592.2 | 512995.6 | 84641 | 1.64041666667 | 13999 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012877 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596591.8 | 512994.1 | 84643 | 1.64041666667 | 12877 |
| 013198 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596591.8 | 512991.9 | 84645 | 1.64041666667 | 13198 |
| 012561 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596591.1 | 512990.2 | 84647 | 1.64041666667 | 12561 |
| 012023 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596591.0 | 512987.9 | 84649 | 1.64041666667 | 12023 |
| 012313 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596590.1 | 512986.5 | 84651 | 1.64041666667 | 12313 |
| 011913 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596589.7 | 512984.4 | 84653 | 1.64041666667 | 11913 |
| 012633 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596588.8 | 512982.5 | 84655 | 1.64041666667 | 12633 |
| 012626 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596587.1 | 512981.0 | 84657 | 1.64041666667 | 12626 |
| 013185 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:37pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596585.8 | 512979.1 | 84659 | 1.64041666667 | 13185 |
| 013109 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:38pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596584.1 | 512976.8 | 84661 | 1.64041666667 | 13109 |
| 012878 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596583.4 | 512975.1 | 84663 | 1.64041666667 | 12878 |
| 013004 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596584.1 | 512972.5 | 84665 | 1.64041666667 | 13004 |
| 012242 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596584.9 | 512970.5 | 84667 | 1.64041666667 | 12242 |
| 013336 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596586.4 | 512968.8 | 84669 | 1.64041666667 | 13336 |
| 013194 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596588.2 | 512967.7 | 84671 | 1.64041666667 | 13194 |
| 013504 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596589.6 | 512966.0 | 84673 | 1.64041666667 | 13504 |
| 013131 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596591.3 | 512964.9 | 84675 | 1.64041666667 | 13131 |
| 013183 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596592.7 | 512963.0 | 84677 | 1.64041666667 | 13183 |
| 012800 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596593.7 | 512961.4 | 84679 | 1.64041666667 | 12800 |
| 013478 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596595.1 | 512960.1 | 84681 | 1.64041666667 | 13478 |
| 013528 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596595.5 | 512958.6 | 84683 | 1.64041666667 | 13528 |
| 012725 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596596.1 | 512957.1 | 84685 | 1.64041666667 | 12725 |
| 013023 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596595.9 | 512955.5 | 84687 | 1.64041666667 | 13023 |
| 013858 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596595.7 | 512953.5 | 84689 | 1.64041666667 | 13858 |
| 014057 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596595.2 | 512952.0 | 84691 | 1.64041666667 | 14057 |
| 014350 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596593.5 | 512950.8 | 84693 | 1.64041666667 | 14350 |
| 014536 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596592.0 | 512949.1 | 84695 | 1.64041666667 | 14536 |
| 014919 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596589.8 | 512948.4 | 84697 | 1.64041666667 | 14919 |
| 014279 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596588.0 | 512947.1 | 84699 | 1.64041666667 | 14279 |
| 014857 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596585.7 | 512945.9 | 84701 | 1.64041666667 | 14857 |
| 014582 | 0 | GeoXH 6000 | 08/20/2015 | 12:51:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596583.9 | 512945.3 | 84703 | 1.64041666667 | 14582 |
| 014442 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596581.7 | 512943.5 | 84705 | 1.64041666667 | 14442 |
| 014521 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596579.6 | 512942.3 | 84707 | 1.64041666667 | 14521 |
| 014565 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596577.6 | 512940.7 | 84709 | 1.64041666667 | 14565 |
| 014425 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596576.8 | 512938.7 | 84711 | 1.64041666667 | 14425 |
| 014279 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596575.6 | 512936.2 | 84713 | 1.64041666667 | 14279 |
| 013567 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596575.4 | 512934.3 | 84715 | 1.64041666667 | 13567 |
| 014456 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596576.6 | 512932.2 | 84717 | 1.64041666667 | 14456 |
| 014206 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596577.6 | 512930.4 | 84719 | 1.64041666667 | 14206 |
| 013901 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596578.7 | 512928.8 | 84721 | 1.64041666667 | 13901 |
| 013452 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596580.8 | 512927.5 | 84723 | 1.64041666667 | 13452 |
| 013806 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596582.5 | 512926.2 | 84725 | 1.64041666667 | 13806 |
| 015071 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596584.3 | 512925.8 | 84727 | 1.64041666667 | 15071 |
| 015685 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596586.4 | 512925.6 | 84729 | 1.64041666667 | 15685 |
| 014478 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:13pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596588.2 | 512925.2 | 84731 | 1.64041666667 | 14478 |
| 015306 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:14pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596590.5 | 512925.7 | 84733 | 1.64041666667 | 15306 |
| 014632 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:15pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596592.3 | 512926.0 | 84735 | 1.64041666667 | 14632 |
| 014913 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:16pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596594.0 | 512926.4 | 84737 | 1.64041666667 | 14913 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014373 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:17pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596595.7 | 512927.0 | 84739 | 1.64041666667 | 14373 |
| 014295 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:18pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596597.4 | 512926.8 | 84741 | 1.64041666667 | 14295 |
| 014228 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:19pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596598.9 | 512926.7 | 84743 | 1.64041666667 | 14228 |
| 013096 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:20pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596600.4 | 512925.8 | 84745 | 1.64041666667 | 13096 |
| 012796 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:21pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596601.2 | 512925.7 | 84747 | 1.64041666667 | 12796 |
| 013115 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:22pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596601.9 | 512925.6 | 84749 | 1.64041666667 | 13115 |
| 013445 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:23pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596602.8 | 512926.1 | 84751 | 1.64041666667 | 13445 |
| 013787 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:24pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596604.3 | 512926.5 | 84753 | 1.64041666667 | 13787 |
| 014498 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:25pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596605.2 | 512927.0 | 84755 | 1.64041666667 | 14498 |
| 013682 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:26pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596607.1 | 512926.2 | 84757 | 1.64041666667 | 13682 |
| 013374 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:27pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596608.9 | 512925.6 | 84759 | 1.64041666667 | 13374 |
| 014017 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:28pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596610.3 | 512924.4 | 84761 | 1.64041666667 | 14017 |
| 014230 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:29pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596611.9 | 512923.2 | 84763 | 1.64041666667 | 14230 |
| 014402 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:30pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596613.0 | 512921.3 | 84765 | 1.64041666667 | 14402 |
| 014873 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:31pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596614.3 | 512919.9 | 84767 | 1.64041666667 | 14873 |
| 015018 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:32pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596616.2 | 512919.2 | 84769 | 1.64041666667 | 15018 |
| 014748 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:33pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596617.7 | 512918.6 | 84771 | 1.64041666667 | 14748 |
| 015248 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:34pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596619.6 | 512918.2 | 84773 | 1.64041666667 | 15248 |
| 015469 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:35pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596621.0 | 512916.9 | 84775 | 1.64041666667 | 15469 |
| 015646 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:36pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596622.5 | 512915.7 | 84777 | 1.64041666667 | 15646 |
| 014936 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:37pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596624.1 | 512914.5 | 84779 | 1.64041666667 | 14936 |
| 014424 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:38pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596625.3 | 512912.5 | 84781 | 1.64041666667 | 14424 |
| 014143 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:39pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596626.1 | 512910.3 | 84783 | 1.64041666667 | 14143 |
| 013730 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596627.3 | 512908.4 | 84785 | 1.64041666667 | 13730 |
| 013896 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:41pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596628.3 | 512906.2 | 84787 | 1.64041666667 | 13896 |
| 014131 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:42pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596629.7 | 512904.4 | 84789 | 1.64041666667 | 14131 |
| 014504 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:43pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596631.3 | 512902.8 | 84791 | 1.64041666667 | 14504 |
| 013678 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:44pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596632.8 | 512900.6 | 84793 | 1.64041666667 | 13678 |
| 013499 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:45pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596634.1 | 512899.4 | 84795 | 1.64041666667 | 13499 |
| 013585 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:46pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596636.2 | 512899.0 | 84797 | 1.64041666667 | 13585 |
| 014114 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:47pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596638.6 | 512898.1 | 84799 | 1.64041666667 | 14114 |
| 014636 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:48pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596640.3 | 512897.0 | 84801 | 1.64041666667 | 14636 |
| 014645 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:49pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596642.1 | 512895.9 | 84803 | 1.64041666667 | 14645 |
| 014531 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:50pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596643.2 | 512894.8 | 84805 | 1.64041666667 | 14531 |
| 013783 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:51pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596645.1 | 512894.1 | 84807 | 1.64041666667 | 13783 |
| 013505 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:52pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596647.1 | 512892.6 | 84809 | 1.64041666667 | 13505 |
| 013649 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:53pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596648.7 | 512891.8 | 84811 | 1.64041666667 | 13649 |
| 013003 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:54pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596651.0 | 512892.0 | 84813 | 1.64041666667 | 13003 |
| 014086 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:55pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596652.8 | 512891.7 | 84815 | 1.64041666667 | 14086 |
| 014636 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:56pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596655.1 | 512892.0 | 84817 | 1.64041666667 | 14636 |
| 014217 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:57pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596656.9 | 512891.8 | 84819 | 1.64041666667 | 14217 |
| 013887 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:58pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596657.5 | 512891.2 | 84821 | 1.64041666667 | 13887 |
| 013686 | 0 | GeoXH 6000 | 08/20/2015 | 12:52:59pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596657.8 | 512890.8 | 84823 | 1.64041666667 | 13686 |
| 013123 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:00pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596659.0 | 512891.2 | 84825 | 1.64041666667 | 13123 |
| 012939 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596661.0 | 512891.3 | 84827 | 1.64041666667 | 12939 |
| 012521 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596664.0 | 512891.2 | 84829 | 1.64041666667 | 12521 |
| 012428 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596666.6 | 512891.0 | 84831 | 1.64041666667 | 12428 |
| 012510 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596669.5 | 512892.0 | 84833 | 1.64041666667 | 12510 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012384 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596671.7 | 512893.4 | 84835 | 1.64041666667 | 12384 |
| 012194 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596674.4 | 512894.2 | 84837 | 1.64041666667 | 12194 |
| 013354 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596676.8 | 512895.2 | 84839 | 1.64041666667 | 13354 |
| 012926 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596680.0 | 512895.9 | 84841 | 1.64041666667 | 12926 |
| 013406 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596682.8 | 512896.1 | 84843 | 1.64041666667 | 13406 |
| 013646 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596686.0 | 512896.6 | 84845 | 1.64041666667 | 13646 |
| 012933 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596688.7 | 512897.4 | 84847 | 1.64041666667 | 12933 |
| 012772 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596691.7 | 512898.4 | 84849 | 1.64041666667 | 12772 |
| 013004 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596694.2 | 512898.9 | 84851 | 1.64041666667 | 13004 |
| 012820 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596696.9 | 512899.3 | 84853 | 1.64041666667 | 12820 |
| 012825 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596699.2 | 512900.3 | 84855 | 1.64041666667 | 12825 |
| 012644 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:16pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596701.8 | 512901.9 | 84857 | 1.64041666667 | 12644 |
| 012820 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:17pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596704.0 | 512902.9 | 84859 | 1.64041666667 | 12820 |
| 012551 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:18pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596707.3 | 512903.7 | 84861 | 1.64041666667 | 12551 |
| 012700 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:19pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596709.5 | 512904.1 | 84863 | 1.64041666667 | 12700 |
| 013796 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:20pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596711.9 | 512905.1 | 84865 | 1.64041666667 | 13796 |
| 013235 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:21pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596713.9 | 512906.1 | 84867 | 1.64041666667 | 13235 |
| 013452 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:22pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596716.5 | 512907.3 | 84869 | 1.64041666667 | 13452 |
| 013177 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596718.7 | 512908.8 | 84871 | 1.64041666667 | 13177 |
| 012827 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596720.8 | 512910.9 | 84873 | 1.64041666667 | 12827 |
| 012922 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596722.1 | 512913.1 | 84875 | 1.64041666667 | 12922 |
| 012594 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:26pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596723.2 | 512915.5 | 84877 | 1.64041666667 | 12594 |
| 013331 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:27pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596724.1 | 512917.1 | 84879 | 1.64041666667 | 13331 |
| 013874 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:28pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596724.7 | 512919.8 | 84881 | 1.64041666667 | 13874 |
| 013549 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:29pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596726.1 | 512921.9 | 84883 | 1.64041666667 | 13549 |
| 012953 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:30pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596727.8 | 512923.9 | 84885 | 1.64041666667 | 12953 |
| 013091 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:31pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596729.0 | 512925.9 | 84887 | 1.64041666667 | 13091 |
| 012756 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:32pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596731.4 | 512927.4 | 84889 | 1.64041666667 | 12756 |
| 014600 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:33pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596733.5 | 512928.6 | 84891 | 1.64041666667 | 14600 |
| 014040 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:34pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596735.0 | 512930.8 | 84893 | 1.64041666667 | 14040 |
| 013222 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:35pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596735.4 | 512932.8 | 84895 | 1.64041666667 | 13222 |
| 012612 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:36pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596736.2 | 512935.4 | 84897 | 1.64041666667 | 12612 |
| 013087 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:37pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596737.0 | 512937.9 | 84899 | 1.64041666667 | 13087 |
| 013039 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:38pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596737.0 | 512940.0 | 84901 | 1.64041666667 | 13039 |
| 013049 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:39pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596736.1 | 512941.9 | 84903 | 1.64041666667 | 13049 |
| 012792 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:40pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596734.8 | 512944.1 | 84905 | 1.64041666667 | 12792 |
| 013256 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:41pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596733.5 | 512945.6 | 84907 | 1.64041666667 | 13256 |
| 013674 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:42pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596731.1 | 512946.6 | 84909 | 1.64041666667 | 13674 |
| 013129 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:43pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596729.0 | 512947.3 | 84911 | 1.64041666667 | 13129 |
| 013842 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:44pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596726.4 | 512947.4 | 84913 | 1.64041666667 | 13842 |
| 014026 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:45pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596724.1 | 512946.6 | 84915 | 1.64041666667 | 14026 |
| 013927 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596722.0 | 512946.3 | 84917 | 1.64041666667 | 13927 |
| 013661 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596720.4 | 512946.2 | 84919 | 1.64041666667 | 13661 |
| 013399 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596717.2 | 512946.8 | 84921 | 1.64041666667 | 13399 |
| 013529 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596715.2 | 512948.2 | 84923 | 1.64041666667 | 13529 |
| 013830 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596712.2 | 512948.5 | 84925 | 1.64041666667 | 13830 |
| 014349 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596709.9 | 512948.4 | 84927 | 1.64041666667 | 14349 |
| 014896 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596707.3 | 512948.8 | 84929 | 1.64041666667 | 14896 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014161 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596705.0 | 512948.9 | 84931 | 1.64041666667 | 14161 |
| 013508 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596702.5 | 512949.3 | 84933 | 1.64041666667 | 13508 |
| 013568 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596700.6 | 512950.1 | 84935 | 1.64041666667 | 13568 |
| 013429 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596698.3 | 512949.8 | 84937 | 1.64041666667 | 13429 |
| 012856 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596696.4 | 512949.3 | 84939 | 1.64041666667 | 12856 |
| 013081 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596694.7 | 512948.4 | 84941 | 1.64041666667 | 13081 |
| 012233 | 0 | GeoXH 6000 | 08/20/2015 | 12:53:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596693.6 | 512947.2 | 84943 | 1.64041666667 | 12233 |
| 012551 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596691.7 | 512947.3 | 84945 | 1.64041666667 | 12551 |
| 012550 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596690.0 | 512947.5 | 84947 | 1.64041666667 | 12550 |
| 012534 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596688.5 | 512948.2 | 84949 | 1.64041666667 | 12534 |
| 013013 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596687.1 | 512948.6 | 84951 | 1.64041666667 | 13013 |
| 012300 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596685.1 | 512949.7 | 84953 | 1.64041666667 | 12300 |
| 012753 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596683.0 | 512949.6 | 84955 | 1.64041666667 | 12753 |
| 012843 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596680.7 | 512949.9 | 84957 | 1.64041666667 | 12843 |
| 013074 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596678.9 | 512949.4 | 84959 | 1.64041666667 | 13074 |
| 013204 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596676.7 | 512948.8 | 84961 | 1.64041666667 | 13204 |
| 013165 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596674.5 | 512948.5 | 84963 | 1.64041666667 | 13165 |
| 012985 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596672.5 | 512947.4 | 84965 | 1.64041666667 | 12985 |
| 012569 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596670.6 | 512946.8 | 84967 | 1.64041666667 | 12569 |
| 012987 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596668.5 | 512945.8 | 84969 | 1.64041666667 | 12987 |
| 013388 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596666.2 | 512944.9 | 84971 | 1.64041666667 | 13388 |
| 014130 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596664.1 | 512945.0 | 84973 | 1.64041666667 | 14130 |
| 014788 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596662.2 | 512944.8 | 84975 | 1.64041666667 | 14788 |
| 014333 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596660.7 | 512945.7 | 84977 | 1.64041666667 | 14333 |
| 013537 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596659.5 | 512945.9 | 84979 | 1.64041666667 | 13537 |
| 012460 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596658.5 | 512947.7 | 84981 | 1.64041666667 | 12460 |
| 012318 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596657.1 | 512948.2 | 84983 | 1.64041666667 | 12318 |
| 012584 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596655.9 | 512950.6 | 84985 | 1.64041666667 | 12584 |
| 012928 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596654.7 | 512952.3 | 84987 | 1.64041666667 | 12928 |
| 013032 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596654.0 | 512954.7 | 84989 | 1.64041666667 | 13032 |
| 012618 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596653.0 | 512956.5 | 84991 | 1.64041666667 | 12618 |
| 012430 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596651.0 | 512958.2 | 84993 | 1.64041666667 | 12430 |
| 011979 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596649.1 | 512958.9 | 84995 | 1.64041666667 | 11979 |
| 012296 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596647.2 | 512959.1 | 84997 | 1.64041666667 | 12296 |
| 013494 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596646.3 | 512960.2 | 84999 | 1.64041666667 | 13494 |
| 012142 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596645.4 | 512961.6 | 85001 | 1.64041666667 | 12142 |
| 012320 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596644.9 | 512963.6 | 85003 | 1.64041666667 | 12320 |
| 013147 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596645.2 | 512965.4 | 85005 | 1.64041666667 | 13147 |
| 012938 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596645.5 | 512966.6 | 85007 | 1.64041666667 | 12938 |
| 012430 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596646.3 | 512968.4 | 85009 | 1.64041666667 | 12430 |
| 012092 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596647.7 | 512970.1 | 85011 | 1.64041666667 | 12092 |
| 012112 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596647.9 | 512972.3 | 85013 | 1.64041666667 | 12112 |
| 013008 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596647.2 | 512974.2 | 85015 | 1.64041666667 | 13008 |
| 012304 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596645.9 | 512976.5 | 85017 | 1.64041666667 | 12304 |
| 012823 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596644.6 | 512978.6 | 85019 | 1.64041666667 | 12823 |
| 013011 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596642.6 | 512980.4 | 85021 | 1.64041666667 | 13011 |
| 012576 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596641.1 | 512981.8 | 85023 | 1.64041666667 | 12576 |
| 012001 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596640.6 | 512983.3 | 85025 | 1.64041666667 | 12001 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012263 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596640.3 | 512984.7 | 85027 | 1.64041666667 | 12263 |
| 011788 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596641.3 | 512987.2 | 85029 | 1.64041666667 | 11788 |
| 012525 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596642.3 | 512988.8 | 85031 | 1.64041666667 | 12525 |
| 012596 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596642.7 | 512991.5 | 85033 | 1.64041666667 | 12596 |
| 012575 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596643.3 | 512994.0 | 85035 | 1.64041666667 | 12575 |
| 012698 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596644.7 | 512996.4 | 85037 | 1.64041666667 | 12698 |
| 012258 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596645.7 | 512998.4 | 85039 | 1.64041666667 | 12258 |
| 013262 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596646.7 | 513001.5 | 85041 | 1.64041666667 | 13262 |
| 013187 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596648.3 | 513003.4 | 85043 | 1.64041666667 | 13187 |
| 012558 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596650.9 | 513005.1 | 85045 | 1.64041666667 | 12558 |
| 011894 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596653.3 | 513006.7 | 85047 | 1.64041666667 | 11894 |
| 012090 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596655.4 | 513008.4 | 85049 | 1.64041666667 | 12090 |
| 012741 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596657.4 | 513009.8 | 85051 | 1.64041666667 | 12741 |
| 012476 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596659.4 | 513011.5 | 85053 | 1.64041666667 | 12476 |
| 012425 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596660.9 | 513013.3 | 85055 | 1.64041666667 | 12425 |
| 012742 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596662.8 | 513015.8 | 85057 | 1.64041666667 | 12742 |
| 012889 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596664.6 | 513017.6 | 85059 | 1.64041666667 | 12889 |
| 013078 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596666.7 | 513019.8 | 85061 | 1.64041666667 | 13078 |
| 012531 | 0 | GeoXH 6000 | 08/20/2015 | 12:54:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596667.9 | 513021.7 | 85063 | 1.64041666667 | 12531 |
| 012381 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596668.9 | 513024.5 | 85065 | 1.64041666667 | 12381 |
| 013287 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596669.4 | 513027.0 | 85067 | 1.64041666667 | 13287 |
| 012858 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596669.0 | 513029.6 | 85069 | 1.64041666667 | 12858 |
| 012738 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596667.4 | 513031.5 | 85071 | 1.64041666667 | 12738 |
| 012812 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:04pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596664.9 | 513033.5 | 85073 | 1.64041666667 | 12812 |
| 013132 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:05pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596663.0 | 513035.0 | 85075 | 1.64041666667 | 13132 |
| 013762 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:06pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596660.2 | 513036.0 | 85077 | 1.64041666667 | 13762 |
| 013201 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:07pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596657.6 | 513035.7 | 85079 | 1.64041666667 | 13201 |
| 014348 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:08pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596654.4 | 513034.9 | 85081 | 1.64041666667 | 14348 |
| 012938 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:09pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596651.9 | 513034.3 | 85083 | 1.64041666667 | 12938 |
| 012670 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596648.5 | 513033.7 | 85085 | 1.64041666667 | 12670 |
| 012609 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:11pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596645.5 | 513033.4 | 85087 | 1.64041666667 | 12609 |
| 012545 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:12pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596642.6 | 513032.7 | 85089 | 1.64041666667 | 12545 |
| 011916 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596639.6 | 513031.6 | 85091 | 1.64041666667 | 11916 |
| 012658 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596636.9 | 513030.3 | 85093 | 1.64041666667 | 12658 |
| 012775 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596634.1 | 513029.2 | 85095 | 1.64041666667 | 12775 |
| 012653 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596631.1 | 513028.2 | 85097 | 1.64041666667 | 12653 |
| 012375 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:17pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596628.5 | 513027.0 | 85099 | 1.64041666667 | 12375 |
| 011753 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:18pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596626.0 | 513025.2 | 85101 | 1.64041666667 | 11753 |
| 011478 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596624.2 | 513023.5 | 85103 | 1.64041666667 | 11478 |
| 011482 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596622.0 | 513021.8 | 85105 | 1.64041666667 | 11482 |
| 010831 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596619.6 | 513020.7 | 85107 | 1.64041666667 | 10831 |
| 011522 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596616.9 | 513019.4 | 85109 | 1.64041666667 | 11522 |
| 011484 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596615.1 | 513017.8 | 85111 | 1.64041666667 | 11484 |
| 013029 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596613.2 | 513015.8 | 85113 | 1.64041666667 | 13029 |
| 012421 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596611.4 | 513014.1 | 85115 | 1.64041666667 | 12421 |
| 012199 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596609.3 | 513012.5 | 85117 | 1.64041666667 | 12199 |
| 011985 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596607.3 | 513011.5 | 85119 | 1.64041666667 | 11985 |
| 011301 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596605.1 | 513009.6 | 85121 | 1.64041666667 | 11301 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010819 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596603.4 | 513008.0 | 85123 | 1.64041666667 | 10819 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596601.5 | 513006.3 | 85125 | 1.64041666667 | 11928 |
| 012222 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596599.9 | 513004.9 | 85127 | 1.64041666667 | 12222 |
| 012372 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596599.0 | 513002.6 | 85129 | 1.64041666667 | 12372 |
| 011647 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596598.7 | 513000.2 | 85131 | 1.64041666667 | 11647 |
| 011666 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596598.3 | 512997.7 | 85133 | 1.64041666667 | 11666 |
| 011790 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596597.7 | 512995.5 | 85135 | 1.64041666667 | 11790 |
| 012466 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596597.5 | 512993.0 | 85137 | 1.64041666667 | 12466 |
| 013380 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596597.7 | 512991.6 | 85139 | 1.64041666667 | 13380 |
| 013421 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596597.8 | 512989.8 | 85141 | 1.64041666667 | 13421 |
| 014224 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596597.9 | 512987.5 | 85143 | 1.64041666667 | 14224 |
| 013536 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596597.3 | 512985.0 | 85145 | 1.64041666667 | 13536 |
| 013246 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596597.5 | 512983.4 | 85147 | 1.64041666667 | 13246 |
| 012333 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596597.0 | 512981.6 | 85149 | 1.64041666667 | 12333 |
| 012945 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596597.4 | 512979.8 | 85151 | 1.64041666667 | 12945 |
| 013139 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596597.4 | 512977.5 | 85153 | 1.64041666667 | 13139 |
| 012281 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596598.3 | 512976.5 | 85155 | 1.64041666667 | 12281 |
| 012345 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596598.6 | 512974.4 | 85157 | 1.64041666667 | 12345 |
| 012359 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596599.1 | 512973.0 | 85159 | 1.64041666667 | 12359 |
| 012059 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596598.8 | 512970.6 | 85161 | 1.64041666667 | 12059 |
| 012168 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596599.8 | 512969.1 | 85163 | 1.64041666667 | 12168 |
| 012222 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596600.3 | 512967.4 | 85165 | 1.64041666667 | 12222 |
| 012717 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596601.3 | 512966.3 | 85167 | 1.64041666667 | 12717 |
| 013018 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596601.5 | 512965.2 | 85169 | 1.64041666667 | 13018 |
| 012813 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596601.8 | 512963.8 | 85171 | 1.64041666667 | 12813 |
| 012794 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596601.8 | 512961.8 | 85173 | 1.64041666667 | 12794 |
| 012432 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596601.6 | 512960.3 | 85175 | 1.64041666667 | 12432 |
| 013180 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596601.7 | 512958.5 | 85177 | 1.64041666667 | 13180 |
| 013054 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596601.1 | 512957.6 | 85179 | 1.64041666667 | 13054 |
| 012375 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596601.1 | 512957.7 | 85181 | 1.64041666667 | 12375 |
| 012106 | 0 | GeoXH 6000 | 08/20/2015 | 12:55:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596601.0 | 512957.7 | 85183 | 1.64041666667 | 12106 |
| 012952 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596600.9 | 512957.8 | 85185 | 1.64041666667 | 12952 |
| 012385 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596600.9 | 512957.8 | 85187 | 1.64041666667 | 12385 |
| 012322 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596601.0 | 512957.9 | 85189 | 1.64041666667 | 12322 |
| 012653 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596601.0 | 512958.0 | 85191 | 1.64041666667 | 12653 |
| 012577 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596601.0 | 512957.9 | 85193 | 1.64041666667 | 12577 |
| 012820 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596601.1 | 512957.7 | 85195 | 1.64041666667 | 12820 |
| 012296 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596601.6 | 512957.5 | 85197 | 1.64041666667 | 12296 |
| 012451 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596602.0 | 512956.7 | 85199 | 1.64041666667 | 12451 |
| 013139 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596602.3 | 512954.9 | 85201 | 1.64041666667 | 13139 |
| 013375 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596603.6 | 512953.8 | 85203 | 1.64041666667 | 13375 |
| 013928 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596604.5 | 512951.9 | 85205 | 1.64041666667 | 13928 |
| 013407 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596605.7 | 512950.5 | 85207 | 1.64041666667 | 13407 |
| 012994 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596606.3 | 512948.4 | 85209 | 1.64041666667 | 12994 |
| 012461 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596607.1 | 512947.3 | 85211 | 1.64041666667 | 12461 |
| 013767 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596605.1 | 512946.5 | 85213 | 1.64041666667 | 13767 |
| 013954 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596603.7 | 512945.8 | 85215 | 1.64041666667 | 13954 |
| 013601 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596601.8 | 512945.8 | 85217 | 1.64041666667 | 13601 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013170 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596600.6 | 512945.0 | 85219 | 1.64041666667 | 13170 |
| 013476 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596598.8 | 512945.0 | 85221 | 1.64041666667 | 13476 |
| 013272 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596596.7 | 512944.4 | 85223 | 1.64041666667 | 13272 |
| 013788 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596595.3 | 512944.7 | 85225 | 1.64041666667 | 13788 |
| 013341 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596593.6 | 512944.9 | 85227 | 1.64041666667 | 13341 |
| 013931 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596591.3 | 512945.5 | 85229 | 1.64041666667 | 13931 |
| 014863 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596589.4 | 512945.1 | 85231 | 1.64041666667 | 14863 |
| 014353 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596587.3 | 512945.1 | 85233 | 1.64041666667 | 14353 |
| 013736 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596586.1 | 512945.3 | 85235 | 1.64041666667 | 13736 |
| 013479 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596584.3 | 512945.6 | 85237 | 1.64041666667 | 13479 |
| 013079 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596582.4 | 512945.4 | 85239 | 1.64041666667 | 13079 |
| 013064 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596580.0 | 512944.4 | 85241 | 1.64041666667 | 13064 |
| 013386 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596577.6 | 512943.7 | 85243 | 1.64041666667 | 13386 |
| 013155 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596575.7 | 512942.7 | 85245 | 1.64041666667 | 13155 |
| 013204 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596574.8 | 512941.1 | 85247 | 1.64041666667 | 13204 |
| 012895 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596573.8 | 512938.7 | 85249 | 1.64041666667 | 12895 |
| 012953 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596573.4 | 512936.6 | 85251 | 1.64041666667 | 12953 |
| 013691 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596572.7 | 512933.7 | 85253 | 1.64041666667 | 13691 |
| 013919 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596571.5 | 512932.0 | 85255 | 1.64041666667 | 13919 |
| 013942 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596570.0 | 512930.5 | 85257 | 1.64041666667 | 13942 |
| 013519 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596569.3 | 512928.4 | 85259 | 1.64041666667 | 13519 |
| 014205 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596567.8 | 512925.7 | 85261 | 1.64041666667 | 14205 |
| 014815 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596566.0 | 512924.2 | 85263 | 1.64041666667 | 14815 |
| 014386 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:40pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596563.5 | 512923.3 | 85265 | 1.64041666667 | 14386 |
| 013867 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:41pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596561.7 | 512923.5 | 85267 | 1.64041666667 | 13867 |
| 013965 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:42pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596559.6 | 512924.2 | 85269 | 1.64041666667 | 13965 |
| 014260 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:43pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596558.2 | 512924.8 | 85271 | 1.64041666667 | 14260 |
| 014194 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:44pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596557.6 | 512927.2 | 85273 | 1.64041666667 | 14194 |
| 014201 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:45pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596556.5 | 512929.0 | 85275 | 1.64041666667 | 14201 |
| 014528 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:46pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596555.4 | 512931.1 | 85277 | 1.64041666667 | 14528 |
| 014839 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:47pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596554.9 | 512932.4 | 85279 | 1.64041666667 | 14839 |
| 014722 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:48pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596553.2 | 512933.1 | 85281 | 1.64041666667 | 14722 |
| 014866 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:49pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596552.0 | 512934.3 | 85283 | 1.64041666667 | 14866 |
| 014242 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:50pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596550.0 | 512934.8 | 85285 | 1.64041666667 | 14242 |
| 013283 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596548.6 | 512935.9 | 85287 | 1.64041666667 | 13283 |
| 013337 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596547.1 | 512936.6 | 85289 | 1.64041666667 | 13337 |
| 013914 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596545.9 | 512937.4 | 85291 | 1.64041666667 | 13914 |
| 014284 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596544.5 | 512937.8 | 85293 | 1.64041666667 | 14284 |
| 014185 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596543.1 | 512938.3 | 85295 | 1.64041666667 | 14185 |
| 014796 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596541.3 | 512938.7 | 85297 | 1.64041666667 | 14796 |
| 013910 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596539.9 | 512939.7 | 85299 | 1.64041666667 | 13910 |
| 013892 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596538.0 | 512939.8 | 85301 | 1.64041666667 | 13892 |
| 014564 | 0 | GeoXH 6000 | 08/20/2015 | 12:56:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596536.6 | 512940.4 | 85303 | 1.64041666667 | 14564 |
| 013187 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596535.1 | 512940.3 | 85305 | 1.64041666667 | 13187 |
| 013410 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596534.2 | 512940.4 | 85307 | 1.64041666667 | 13410 |
| 012785 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596534.1 | 512939.7 | 85309 | 1.64041666667 | 12785 |
| 013859 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596533.9 | 512938.6 | 85311 | 1.64041666667 | 13859 |
| 013713 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596534.0 | 512937.0 | 85313 | 1.64041666667 | 13713 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013593 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596534.7 | 512935.7 | 85315 | 1.64041666667 | 13593 |
| 013354 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596534.6 | 512933.4 | 85317 | 1.64041666667 | 13354 |
| 013841 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596535.0 | 512930.7 | 85319 | 1.64041666667 | 13841 |
| 013373 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596535.0 | 512928.1 | 85321 | 1.64041666667 | 13373 |
| 013672 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596534.5 | 512926.3 | 85323 | 1.64041666667 | 13672 |
| 014703 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596534.1 | 512924.4 | 85325 | 1.64041666667 | 14703 |
| 013978 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596532.1 | 512923.5 | 85327 | 1.64041666667 | 13978 |
| 013772 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596529.8 | 512922.4 | 85329 | 1.64041666667 | 13772 |
| 013672 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596527.6 | 512921.2 | 85331 | 1.64041666667 | 13672 |
| 014035 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596525.5 | 512920.7 | 85333 | 1.64041666667 | 14035 |
| 015162 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596523.1 | 512920.1 | 85335 | 1.64041666667 | 15162 |
| 016163 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596520.6 | 512919.1 | 85337 | 1.64041666667 | 16163 |
| 015804 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596518.3 | 512919.0 | 85339 | 1.64041666667 | 15804 |
| 016472 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596515.8 | 512919.3 | 85341 | 1.64041666667 | 16472 |
| 016188 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596513.4 | 512918.9 | 85343 | 1.64041666667 | 16188 |
| 015811 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596511.4 | 512919.6 | 85345 | 1.64041666667 | 15811 |
| 015628 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596509.4 | 512920.8 | 85347 | 1.64041666667 | 15628 |
| 015833 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596507.2 | 512921.7 | 85349 | 1.64041666667 | 15833 |
| 015011 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596505.8 | 512923.3 | 85351 | 1.64041666667 | 15011 |
| 013889 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596504.4 | 512925.0 | 85353 | 1.64041666667 | 13889 |
| 014322 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596503.6 | 512927.1 | 85355 | 1.64041666667 | 14322 |
| 013306 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596504.2 | 512928.6 | 85357 | 1.64041666667 | 13306 |
| 013530 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596504.3 | 512930.7 | 85359 | 1.64041666667 | 13530 |
| 013640 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596505.0 | 512933.0 | 85361 | 1.64041666667 | 13640 |
| 014827 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:29pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596505.6 | 512934.1 | 85363 | 1.64041666667 | 14827 |
| 014543 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596504.4 | 512935.3 | 85365 | 1.64041666667 | 14543 |
| 015365 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:31pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596502.9 | 512936.8 | 85367 | 1.64041666667 | 15365 |
| 015318 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:32pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596500.9 | 512937.9 | 85369 | 1.64041666667 | 15318 |
| 014549 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:33pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596499.4 | 512938.9 | 85371 | 1.64041666667 | 14549 |
| 014356 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:34pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596498.2 | 512940.3 | 85373 | 1.64041666667 | 14356 |
| 014982 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596496.8 | 512941.4 | 85375 | 1.64041666667 | 14982 |
| 015575 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596496.2 | 512943.1 | 85377 | 1.64041666667 | 15575 |
| 014716 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:37pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596496.4 | 512945.1 | 85379 | 1.64041666667 | 14716 |
| 014202 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596496.3 | 512947.0 | 85381 | 1.64041666667 | 14202 |
| 015211 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596496.2 | 512948.7 | 85383 | 1.64041666667 | 15211 |
| 015284 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596495.4 | 512950.8 | 85385 | 1.64041666667 | 15284 |
| 014664 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596495.1 | 512953.2 | 85387 | 1.64041666667 | 14664 |
| 013829 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:42pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596494.8 | 512955.0 | 85389 | 1.64041666667 | 13829 |
| 013523 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:43pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596493.1 | 512956.7 | 85391 | 1.64041666667 | 13523 |
| 014859 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596492.0 | 512958.8 | 85393 | 1.64041666667 | 14859 |
| 014531 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596492.4 | 512960.9 | 85395 | 1.64041666667 | 14531 |
| 014353 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:46pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596493.1 | 512963.4 | 85397 | 1.64041666667 | 14353 |
| 014336 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596494.0 | 512964.9 | 85399 | 1.64041666667 | 14336 |
| 014154 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596495.0 | 512966.5 | 85401 | 1.64041666667 | 14154 |
| 014284 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596495.5 | 512967.8 | 85403 | 1.64041666667 | 14284 |
| 014770 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596495.4 | 512968.9 | 85405 | 1.64041666667 | 14770 |
| 014690 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596495.8 | 512970.3 | 85407 | 1.64041666667 | 14690 |
| 013558 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596497.2 | 512971.7 | 85409 | 1.64041666667 | 13558 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013701 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596498.7 | 512973.5 | 85411 | 1.64041666667 | 13701 |
| 014284 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596500.5 | 512974.8 | 85413 | 1.64041666667 | 14284 |
| 013120 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596502.3 | 512975.7 | 85415 | 1.64041666667 | 13120 |
| 013372 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596504.2 | 512976.1 | 85417 | 1.64041666667 | 13372 |
| 012989 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596506.1 | 512976.3 | 85419 | 1.64041666667 | 12989 |
| 012976 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596508.0 | 512976.4 | 85421 | 1.64041666667 | 12976 |
| 012766 | 0 | GeoXH 6000 | 08/20/2015 | 12:57:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596509.9 | 512976.1 | 85423 | 1.64041666667 | 12766 |
| 012318 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596511.7 | 512976.5 | 85425 | 1.64041666667 | 12318 |
| 012892 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:01pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596513.5 | 512977.1 | 85427 | 1.64041666667 | 12892 |
| 011946 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:02pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596515.8 | 512977.9 | 85429 | 1.64041666667 | 11946 |
| 012260 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:03pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596517.4 | 512977.7 | 85431 | 1.64041666667 | 12260 |
| 013035 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:04pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596519.4 | 512978.5 | 85433 | 1.64041666667 | 13035 |
| 012702 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:05pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596521.4 | 512978.7 | 85435 | 1.64041666667 | 12702 |
| 013527 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:06pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596522.9 | 512979.7 | 85437 | 1.64041666667 | 13527 |
| 013954 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:07pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596524.3 | 512980.0 | 85439 | 1.64041666667 | 13954 |
| 013946 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:08pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596525.7 | 512981.0 | 85441 | 1.64041666667 | 13946 |
| 014085 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:09pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596527.6 | 512981.1 | 85443 | 1.64041666667 | 14085 |
| 014703 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:10pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596529.2 | 512981.8 | 85445 | 1.64041666667 | 14703 |
| 013933 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:11pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596531.2 | 512981.3 | 85447 | 1.64041666667 | 13933 |
| 013904 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:12pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596532.8 | 512980.9 | 85449 | 1.64041666667 | 13904 |
| 013251 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:13pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596534.1 | 512980.0 | 85451 | 1.64041666667 | 13251 |
| 013926 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:14pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596535.3 | 512978.9 | 85453 | 1.64041666667 | 13926 |
| 013158 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:15pm | Sensor | 1797-S0053-905-G-ACK | 6846.6 | 1596536.1 | 512977.4 | 85455 | 1.64041666667 | 13158 |
| 012531 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:16pm | Sensor | 1797-S0053-905-G-ACK | 6846.6 | 1596537.5 | 512975.8 | 85457 | 1.64041666667 | 12531 |
| 013259 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:17pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596538.9 | 512974.0 | 85459 | 1.64041666667 | 13259 |
| 013030 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:18pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596539.3 | 512972.3 | 85461 | 1.64041666667 | 13030 |
| 012782 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:19pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596540.1 | 512970.9 | 85463 | 1.64041666667 | 12782 |
| 012777 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:20pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596539.9 | 512969.6 | 85465 | 1.64041666667 | 12777 |
| 013052 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:21pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596540.3 | 512968.1 | 85467 | 1.64041666667 | 13052 |
| 013004 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:22pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596540.3 | 512967.0 | 85469 | 1.64041666667 | 13004 |
| 013862 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596539.5 | 512965.6 | 85471 | 1.64041666667 | 13862 |
| 013550 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:24pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596539.4 | 512964.0 | 85473 | 1.64041666667 | 13550 |
| 013569 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:25pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596538.6 | 512962.9 | 85475 | 1.64041666667 | 13569 |
| 013392 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596539.3 | 512962.9 | 85477 | 1.64041666667 | 13392 |
| 012896 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596540.4 | 512962.8 | 85479 | 1.64041666667 | 12896 |
| 013524 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596540.9 | 512961.7 | 85481 | 1.64041666667 | 13524 |
| 014222 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596541.8 | 512961.3 | 85483 | 1.64041666667 | 14222 |
| 014600 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596542.6 | 512960.3 | 85485 | 1.64041666667 | 14600 |
| 013867 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596542.7 | 512959.1 | 85487 | 1.64041666667 | 13867 |
| 013237 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596543.4 | 512959.4 | 85489 | 1.64041666667 | 13237 |
| 012996 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596544.0 | 512959.6 | 85491 | 1.64041666667 | 12996 |
| 013648 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596544.2 | 512959.8 | 85493 | 1.64041666667 | 13648 |
| 013286 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596544.4 | 512959.8 | 85495 | 1.64041666667 | 13286 |
| 013968 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596544.4 | 512959.5 | 85497 | 1.64041666667 | 13968 |
| 013797 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596543.4 | 512958.8 | 85499 | 1.64041666667 | 13797 |
| 012771 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596543.2 | 512958.1 | 85501 | 1.64041666667 | 12771 |
| 013326 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596543.1 | 512957.9 | 85503 | 1.64041666667 | 13326 |
| 013451 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596543.2 | 512958.2 | 85505 | 1.64041666667 | 13451 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013258 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596543.5 | 512958.2 | 85507 | 1.64041666667 | 13258 |
| 013008 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596543.7 | 512958.2 | 85509 | 1.64041666667 | 13008 |
| 012979 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596545.2 | 512958.7 | 85511 | 1.64041666667 | 12979 |
| 013068 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596547.1 | 512958.8 | 85513 | 1.64041666667 | 13068 |
| 013238 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596548.7 | 512959.5 | 85515 | 1.64041666667 | 13238 |
| 012749 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596550.2 | 512959.2 | 85517 | 1.64041666667 | 12749 |
| 012548 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596550.4 | 512959.6 | 85519 | 1.64041666667 | 12548 |
| 012511 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596551.0 | 512960.5 | 85521 | 1.64041666667 | 12511 |
| 012970 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596552.4 | 512960.8 | 85523 | 1.64041666667 | 12970 |
| 013063 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596553.9 | 512961.4 | 85525 | 1.64041666667 | 13063 |
| 013430 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596556.2 | 512961.1 | 85527 | 1.64041666667 | 13430 |
| 013614 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596558.5 | 512960.6 | 85529 | 1.64041666667 | 13614 |
| 013508 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596560.7 | 512960.4 | 85531 | 1.64041666667 | 13508 |
| 013028 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596562.7 | 512959.7 | 85533 | 1.64041666667 | 13028 |
| 013666 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596564.5 | 512959.5 | 85535 | 1.64041666667 | 13666 |
| 013559 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596566.1 | 512958.3 | 85537 | 1.64041666667 | 13559 |
| 013192 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596566.3 | 512958.5 | 85539 | 1.64041666667 | 13192 |
| 012655 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596566.2 | 512958.5 | 85541 | 1.64041666667 | 12655 |
| 012751 | 0 | GeoXH 6000 | 08/20/2015 | 12:58:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596566.2 | 512958.5 | 85543 | 1.64041666667 | 12751 |
| 013705 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596566.2 | 512958.6 | 85545 | 1.64041666667 | 13705 |
| 014496 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596566.3 | 512958.9 | 85547 | 1.64041666667 | 14496 |
| 013891 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596566.6 | 512958.9 | 85549 | 1.64041666667 | 13891 |
| 013949 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596567.6 | 512957.6 | 85551 | 1.64041666667 | 13949 |
| 014783 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596568.8 | 512956.3 | 85553 | 1.64041666667 | 14783 |
| 014481 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596569.6 | 512954.7 | 85555 | 1.64041666667 | 14481 |
| 014475 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596570.0 | 512953.1 | 85557 | 1.64041666667 | 14475 |
| 013505 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596571.1 | 512951.1 | 85559 | 1.64041666667 | 13505 |
| 012899 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596571.5 | 512948.8 | 85561 | 1.64041666667 | 12899 |
| 014065 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596572.4 | 512947.1 | 85563 | 1.64041666667 | 14065 |
| 014122 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596573.3 | 512945.2 | 85565 | 1.64041666667 | 14122 |
| 013366 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596574.1 | 512943.9 | 85567 | 1.64041666667 | 13366 |
| 014388 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596576.5 | 512943.3 | 85569 | 1.64041666667 | 14388 |
| 014461 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596577.9 | 512943.1 | 85571 | 1.64041666667 | 14461 |
| 014006 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596578.3 | 512943.6 | 85573 | 1.64041666667 | 14006 |
| 014433 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596578.0 | 512943.1 | 85575 | 1.64041666667 | 14433 |
| 014524 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596577.7 | 512941.8 | 85577 | 1.64041666667 | 14524 |
| 014057 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596576.9 | 512939.7 | 85579 | 1.64041666667 | 14057 |
| 014432 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596575.4 | 512937.7 | 85581 | 1.64041666667 | 14432 |
| 013608 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596574.8 | 512935.8 | 85583 | 1.64041666667 | 13608 |
| 014299 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596574.9 | 512933.6 | 85585 | 1.64041666667 | 14299 |
| 014801 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596574.9 | 512931.5 | 85587 | 1.64041666667 | 14801 |
| 014250 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596575.9 | 512929.2 | 85589 | 1.64041666667 | 14250 |
| 014706 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596577.1 | 512927.7 | 85591 | 1.64041666667 | 14706 |
| 013852 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596577.3 | 512925.3 | 85593 | 1.64041666667 | 13852 |
| 014002 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596577.3 | 512923.2 | 85595 | 1.64041666667 | 14002 |
| 013771 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596576.3 | 512922.1 | 85597 | 1.64041666667 | 13771 |
| 013701 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596575.5 | 512921.9 | 85599 | 1.64041666667 | 13701 |
| 014171 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596574.3 | 512921.3 | 85601 | 1.64041666667 | 14171 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013829 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596573.7 | 512921.6 | 85603 | 1.64041666667 | 13829 |
| 013321 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596573.3 | 512922.0 | 85605 | 1.64041666667 | 13321 |
| 013298 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596573.3 | 512922.2 | 85607 | 1.64041666667 | 13298 |
| 013173 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596573.4 | 512922.3 | 85609 | 1.64041666667 | 13173 |
| 012532 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596573.4 | 512922.2 | 85611 | 1.64041666667 | 12532 |
| 014099 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596573.5 | 512921.9 | 85613 | 1.64041666667 | 14099 |
| 014321 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596573.4 | 512921.4 | 85615 | 1.64041666667 | 14321 |
| 013688 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596572.4 | 512920.3 | 85617 | 1.64041666667 | 13688 |
| 014164 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596571.9 | 512918.9 | 85619 | 1.64041666667 | 14164 |
| 014027 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596571.7 | 512917.0 | 85621 | 1.64041666667 | 14027 |
| 013515 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596572.7 | 512915.0 | 85623 | 1.64041666667 | 13515 |
| 013257 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596573.0 | 512913.0 | 85625 | 1.64041666667 | 13257 |
| 013734 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596572.6 | 512911.2 | 85627 | 1.64041666667 | 13734 |
| 013320 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:42pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596571.7 | 512909.7 | 85629 | 1.64041666667 | 13320 |
| 013702 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:43pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596569.8 | 512909.1 | 85631 | 1.64041666667 | 13702 |
| 015042 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:44pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596568.6 | 512907.5 | 85633 | 1.64041666667 | 15042 |
| 013959 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:45pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596567.1 | 512905.9 | 85635 | 1.64041666667 | 13959 |
| 013912 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:46pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596566.2 | 512904.2 | 85637 | 1.64041666667 | 13912 |
| 013413 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:47pm | Sensor | 1797-S0053-905-G-ACK | 6849.2 | 1596565.0 | 512902.7 | 85639 | 1.64041666667 | 13413 |
| 013147 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:48pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596563.1 | 512902.5 | 85641 | 1.64041666667 | 13147 |
| 013162 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:49pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596561.4 | 512901.9 | 85643 | 1.64041666667 | 13162 |
| 013411 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:50pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596559.8 | 512902.2 | 85645 | 1.64041666667 | 13411 |
| 014061 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:51pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596557.9 | 512901.6 | 85647 | 1.64041666667 | 14061 |
| 014164 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:52pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596555.7 | 512901.0 | 85649 | 1.64041666667 | 14164 |
| 014807 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:53pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596554.3 | 512900.0 | 85651 | 1.64041666667 | 14807 |
| 014036 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596552.7 | 512898.5 | 85653 | 1.64041666667 | 14036 |
| 014698 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596550.8 | 512897.3 | 85655 | 1.64041666667 | 14698 |
| 014222 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596549.1 | 512896.2 | 85657 | 1.64041666667 | 14222 |
| 014345 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596546.8 | 512895.8 | 85659 | 1.64041666667 | 14345 |
| 014706 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596544.5 | 512895.5 | 85661 | 1.64041666667 | 14706 |
| 014565 | 0 | GeoXH 6000 | 08/20/2015 | 12:59:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596542.5 | 512895.0 | 85663 | 1.64041666667 | 14565 |
| 013810 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596540.3 | 512894.8 | 85665 | 1.64041666667 | 13810 |
| 013220 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596538.7 | 512893.7 | 85667 | 1.64041666667 | 13220 |
| 013706 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596536.5 | 512892.7 | 85669 | 1.64041666667 | 13706 |
| 014370 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596534.8 | 512891.4 | 85671 | 1.64041666667 | 14370 |
| 014570 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596533.2 | 512889.1 | 85673 | 1.64041666667 | 14570 |
| 013723 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596531.4 | 512887.6 | 85675 | 1.64041666667 | 13723 |
| 014327 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596529.4 | 512886.8 | 85677 | 1.64041666667 | 14327 |
| 015198 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596526.8 | 512886.5 | 85679 | 1.64041666667 | 15198 |
| 014744 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596524.6 | 512886.6 | 85681 | 1.64041666667 | 14744 |
| 014653 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596522.4 | 512887.0 | 85683 | 1.64041666667 | 14653 |
| 014542 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596519.9 | 512887.5 | 85685 | 1.64041666667 | 14542 |
| 015260 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596518.7 | 512888.4 | 85687 | 1.64041666667 | 15260 |
| 014501 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596517.6 | 512888.7 | 85689 | 1.64041666667 | 14501 |
| 014569 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596516.7 | 512889.2 | 85691 | 1.64041666667 | 14569 |
| 014300 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596515.7 | 512889.9 | 85693 | 1.64041666667 | 14300 |
| 014081 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596513.6 | 512889.4 | 85695 | 1.64041666667 | 14081 |
| 014228 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596511.4 | 512889.4 | 85697 | 1.64041666667 | 14228 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014566 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596509.4 | 512889.8 | 85699 | 1.64041666667 | 14566 |
| 014456 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596507.5 | 512890.0 | 85701 | 1.64041666667 | 14456 |
| 013966 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596506.1 | 512891.3 | 85703 | 1.64041666667 | 13966 |
| 014103 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596504.3 | 512892.4 | 85705 | 1.64041666667 | 14103 |
| 013445 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596503.3 | 512893.9 | 85707 | 1.64041666667 | 13445 |
| 013008 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596502.5 | 512895.7 | 85709 | 1.64041666667 | 13008 |
| 013024 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596501.7 | 512897.6 | 85711 | 1.64041666667 | 13024 |
| 013206 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596501.7 | 512899.3 | 85713 | 1.64041666667 | 13206 |
| 013143 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596501.4 | 512901.3 | 85715 | 1.64041666667 | 13143 |
| 013865 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596501.1 | 512903.3 | 85717 | 1.64041666667 | 13865 |
| 013447 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596501.6 | 512904.4 | 85719 | 1.64041666667 | 13447 |
| 014261 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596501.7 | 512905.8 | 85721 | 1.64041666667 | 14261 |
| 014809 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596502.1 | 512907.6 | 85723 | 1.64041666667 | 14809 |
| 014630 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596502.5 | 512909.4 | 85725 | 1.64041666667 | 14630 |
| 014244 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596502.5 | 512911.2 | 85727 | 1.64041666667 | 14244 |
| 014057 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596503.7 | 512912.2 | 85729 | 1.64041666667 | 14057 |
| 013495 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596504.9 | 512913.1 | 85731 | 1.64041666667 | 13495 |
| 013770 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596506.7 | 512913.9 | 85733 | 1.64041666667 | 13770 |
| 014556 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596508.8 | 512914.7 | 85735 | 1.64041666667 | 14556 |
| 014645 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596511.2 | 512914.7 | 85737 | 1.64041666667 | 14645 |
| 014898 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596512.8 | 512914.0 | 85739 | 1.64041666667 | 14898 |
| 014447 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596515.3 | 512914.0 | 85741 | 1.64041666667 | 14447 |
| 014164 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596517.2 | 512913.8 | 85743 | 1.64041666667 | 14164 |
| 014537 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596519.4 | 512913.9 | 85745 | 1.64041666667 | 14537 |
| 014732 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596521.2 | 512914.9 | 85747 | 1.64041666667 | 14732 |
| 014722 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596523.1 | 512915.1 | 85749 | 1.64041666667 | 14722 |
| 014431 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596524.7 | 512916.0 | 85751 | 1.64041666667 | 14431 |
| 015977 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596526.8 | 512915.8 | 85753 | 1.64041666667 | 15977 |
| 015137 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596528.7 | 512915.8 | 85755 | 1.64041666667 | 15137 |
| 015002 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596530.6 | 512915.2 | 85757 | 1.64041666667 | 15002 |
| 014678 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596532.4 | 512913.8 | 85759 | 1.64041666667 | 14678 |
| 014766 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596533.5 | 512912.5 | 85761 | 1.64041666667 | 14766 |
| 014441 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596533.0 | 512910.7 | 85763 | 1.64041666667 | 14441 |
| 014753 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596533.2 | 512908.6 | 85765 | 1.64041666667 | 14753 |
| 014328 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596533.2 | 512906.7 | 85767 | 1.64041666667 | 14328 |
| 014187 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596533.6 | 512904.6 | 85769 | 1.64041666667 | 14187 |
| 014250 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596534.7 | 512902.7 | 85771 | 1.64041666667 | 14250 |
| 013670 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:54pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596536.0 | 512900.9 | 85773 | 1.64041666667 | 13670 |
| 014582 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:55pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596536.9 | 512900.0 | 85775 | 1.64041666667 | 14582 |
| 014615 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596538.2 | 512898.4 | 85777 | 1.64041666667 | 14615 |
| 013718 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596539.4 | 512896.7 | 85779 | 1.64041666667 | 13718 |
| 013349 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596541.5 | 512895.8 | 85781 | 1.64041666667 | 13349 |
| 013486 | 0 | GeoXH 6000 | 08/20/2015 | 01:00:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596544.0 | 512895.8 | 85783 | 1.64041666667 | 13486 |
| 013788 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596546.3 | 512895.9 | 85785 | 1.64041666667 | 13788 |
| 014018 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596548.4 | 512896.6 | 85787 | 1.64041666667 | 14018 |
| 014298 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596550.5 | 512897.7 | 85789 | 1.64041666667 | 14298 |
| 014215 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:03pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596552.0 | 512898.4 | 85791 | 1.64041666667 | 14215 |
| 014468 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:04pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596552.9 | 512899.9 | 85793 | 1.64041666667 | 14468 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015653 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596552.7 | 512902.0 | 85795 | 1.64041666667 | 15653 |
| 015367 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596552.2 | 512904.7 | 85797 | 1.64041666667 | 15367 |
| 014779 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596551.9 | 512907.5 | 85799 | 1.64041666667 | 14779 |
| 014703 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596551.6 | 512910.0 | 85801 | 1.64041666667 | 14703 |
| 013123 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596551.4 | 512912.1 | 85803 | 1.64041666667 | 13123 |
| 012691 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596551.5 | 512914.2 | 85805 | 1.64041666667 | 12691 |
| 013416 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596551.1 | 512916.2 | 85807 | 1.64041666667 | 13416 |
| 014019 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596549.6 | 512917.9 | 85809 | 1.64041666667 | 14019 |
| 014051 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596548.1 | 512919.1 | 85811 | 1.64041666667 | 14051 |
| 014976 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596545.4 | 512918.9 | 85813 | 1.64041666667 | 14976 |
| 013966 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596543.6 | 512918.7 | 85815 | 1.64041666667 | 13966 |
| 014013 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596541.4 | 512918.2 | 85817 | 1.64041666667 | 14013 |
| 013582 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596540.1 | 512917.1 | 85819 | 1.64041666667 | 13582 |
| 014360 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596537.9 | 512916.6 | 85821 | 1.64041666667 | 14360 |
| 013890 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596536.2 | 512916.4 | 85823 | 1.64041666667 | 13890 |
| 014473 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596534.5 | 512918.1 | 85825 | 1.64041666667 | 14473 |
| 014696 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596535.1 | 512919.8 | 85827 | 1.64041666667 | 14696 |
| 014979 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596536.3 | 512921.3 | 85829 | 1.64041666667 | 14979 |
| 014005 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596537.7 | 512923.1 | 85831 | 1.64041666667 | 14005 |
| 013488 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596538.7 | 512924.4 | 85833 | 1.64041666667 | 13488 |
| 013414 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:25pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596538.5 | 512925.9 | 85835 | 1.64041666667 | 13414 |
| 014145 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596538.9 | 512927.4 | 85837 | 1.64041666667 | 14145 |
| 014227 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596538.3 | 512928.9 | 85839 | 1.64041666667 | 14227 |
| 013290 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596537.6 | 512931.2 | 85841 | 1.64041666667 | 13290 |
| 013453 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596537.1 | 512933.0 | 85843 | 1.64041666667 | 13453 |
| 014437 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596536.0 | 512934.4 | 85845 | 1.64041666667 | 14437 |
| 014608 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596535.2 | 512935.6 | 85847 | 1.64041666667 | 14608 |
| 013774 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596534.7 | 512937.1 | 85849 | 1.64041666667 | 13774 |
| 014010 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596534.4 | 512938.3 | 85851 | 1.64041666667 | 14010 |
| 013776 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596535.3 | 512939.2 | 85853 | 1.64041666667 | 13776 |
| 013644 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596536.0 | 512940.0 | 85855 | 1.64041666667 | 13644 |
| 013532 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596537.6 | 512940.2 | 85857 | 1.64041666667 | 13532 |
| 013769 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596538.7 | 512940.2 | 85859 | 1.64041666667 | 13769 |
| 013970 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596540.1 | 512939.2 | 85861 | 1.64041666667 | 13970 |
| 013423 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596541.2 | 512939.2 | 85863 | 1.64041666667 | 13423 |
| 013573 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596543.0 | 512938.4 | 85865 | 1.64041666667 | 13573 |
| 014085 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:41pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596544.8 | 512938.3 | 85867 | 1.64041666667 | 14085 |
| 013742 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:42pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596546.0 | 512937.4 | 85869 | 1.64041666667 | 13742 |
| 013767 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:43pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596547.7 | 512936.8 | 85871 | 1.64041666667 | 13767 |
| 013571 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:44pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596549.5 | 512935.9 | 85873 | 1.64041666667 | 13571 |
| 013049 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:45pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596551.0 | 512936.1 | 85875 | 1.64041666667 | 13049 |
| 013430 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:46pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596552.5 | 512935.4 | 85877 | 1.64041666667 | 13430 |
| 013397 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:47pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596553.8 | 512934.6 | 85879 | 1.64041666667 | 13397 |
| 013633 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:48pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596554.4 | 512933.1 | 85881 | 1.64041666667 | 13633 |
| 013841 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:49pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596555.1 | 512931.8 | 85883 | 1.64041666667 | 13841 |
| 014528 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:50pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596556.1 | 512929.8 | 85885 | 1.64041666667 | 14528 |
| 013804 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:51pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596557.2 | 512928.1 | 85887 | 1.64041666667 | 13804 |
| 013555 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:52pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596558.6 | 512926.3 | 85889 | 1.64041666667 | 13555 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014472 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:53pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596559.4 | 512924.7 | 85891 | 1.64041666667 | 14472 |
| 015303 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:54pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596560.6 | 512924.1 | 85893 | 1.64041666667 | 15303 |
| 015710 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:55pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596562.5 | 512923.8 | 85895 | 1.64041666667 | 15710 |
| 015722 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:56pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596564.5 | 512923.0 | 85897 | 1.64041666667 | 15722 |
| 015053 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596566.5 | 512922.7 | 85899 | 1.64041666667 | 15053 |
| 015360 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596569.0 | 512922.1 | 85901 | 1.64041666667 | 15360 |
| 015660 | 0 | GeoXH 6000 | 08/20/2015 | 01:01:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596570.7 | 512920.9 | 85903 | 1.64041666667 | 15660 |
| 015131 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596573.2 | 512920.6 | 85905 | 1.64041666667 | 15131 |
| 014706 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596575.4 | 512920.0 | 85907 | 1.64041666667 | 14706 |
| 014730 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596577.4 | 512919.2 | 85909 | 1.64041666667 | 14730 |
| 014495 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596580.1 | 512918.9 | 85911 | 1.64041666667 | 14495 |
| 014656 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596582.6 | 512918.3 | 85913 | 1.64041666667 | 14656 |
| 014094 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596584.5 | 512918.2 | 85915 | 1.64041666667 | 14094 |
| 014227 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596586.7 | 512919.2 | 85917 | 1.64041666667 | 14227 |
| 014745 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596588.6 | 512918.8 | 85919 | 1.64041666667 | 14745 |
| 014594 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596590.6 | 512918.6 | 85921 | 1.64041666667 | 14594 |
| 014921 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:09pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596593.1 | 512918.6 | 85923 | 1.64041666667 | 14921 |
| 014821 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:10pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596595.2 | 512918.2 | 85925 | 1.64041666667 | 14821 |
| 014434 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:11pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596597.5 | 512918.7 | 85927 | 1.64041666667 | 14434 |
| 014501 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:12pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596599.8 | 512918.8 | 85929 | 1.64041666667 | 14501 |
| 014404 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:13pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596601.8 | 512918.6 | 85931 | 1.64041666667 | 14404 |
| 014245 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:14pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596604.1 | 512918.0 | 85933 | 1.64041666667 | 14245 |
| 013188 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:15pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596605.8 | 512917.0 | 85935 | 1.64041666667 | 13188 |
| 013980 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:16pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596607.7 | 512916.4 | 85937 | 1.64041666667 | 13980 |
| 013451 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:17pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596609.7 | 512914.9 | 85939 | 1.64041666667 | 13451 |
| 013311 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:18pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596611.3 | 512913.9 | 85941 | 1.64041666667 | 13311 |
| 014815 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:19pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596613.4 | 512913.6 | 85943 | 1.64041666667 | 14815 |
| 014266 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:20pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596615.3 | 512912.6 | 85945 | 1.64041666667 | 14266 |
| 013792 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:21pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596617.6 | 512911.6 | 85947 | 1.64041666667 | 13792 |
| 013293 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:22pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596619.7 | 512910.6 | 85949 | 1.64041666667 | 13293 |
| 013125 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:23pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596620.9 | 512908.7 | 85951 | 1.64041666667 | 13125 |
| 013562 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:24pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596622.5 | 512907.2 | 85953 | 1.64041666667 | 13562 |
| 013089 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:25pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596624.0 | 512905.8 | 85955 | 1.64041666667 | 13089 |
| 012980 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:26pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596625.0 | 512904.3 | 85957 | 1.64041666667 | 12980 |
| 012986 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:27pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596627.0 | 512903.3 | 85959 | 1.64041666667 | 12986 |
| 012667 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:28pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596628.3 | 512901.7 | 85961 | 1.64041666667 | 12667 |
| 012990 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:29pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596629.5 | 512900.6 | 85963 | 1.64041666667 | 12990 |
| 013052 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:30pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596630.7 | 512898.6 | 85965 | 1.64041666667 | 13052 |
| 013244 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:31pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596630.4 | 512896.6 | 85967 | 1.64041666667 | 13244 |
| 013990 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:32pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596630.0 | 512894.9 | 85969 | 1.64041666667 | 13990 |
| 015009 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:33pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596628.4 | 512893.4 | 85971 | 1.64041666667 | 15009 |
| 015417 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596627.1 | 512892.2 | 85973 | 1.64041666667 | 15417 |
| 014222 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596626.2 | 512890.9 | 85975 | 1.64041666667 | 14222 |
| 013737 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596624.8 | 512889.6 | 85977 | 1.64041666667 | 13737 |
| 013622 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596624.6 | 512887.8 | 85979 | 1.64041666667 | 13622 |
| 013250 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596623.9 | 512886.0 | 85981 | 1.64041666667 | 13250 |
| 014053 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596623.5 | 512884.6 | 85983 | 1.64041666667 | 14053 |
| 015090 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596622.5 | 512882.5 | 85985 | 1.64041666667 | 15090 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013805 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596621.1 | 512881.7 | 85987 | 1.64041666667 | 13805 |
| 012963 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596619.8 | 512880.5 | 85989 | 1.64041666667 | 12963 |
| 012676 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596617.9 | 512880.1 | 85991 | 1.64041666667 | 12676 |
| 012538 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596615.9 | 512879.5 | 85993 | 1.64041666667 | 12538 |
| 013270 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596614.1 | 512879.7 | 85995 | 1.64041666667 | 13270 |
| 013704 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596612.2 | 512879.1 | 85997 | 1.64041666667 | 13704 |
| 014706 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:47pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596609.8 | 512878.6 | 85999 | 1.64041666667 | 14706 |
| 013890 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:48pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596607.7 | 512879.2 | 86001 | 1.64041666667 | 13890 |
| 013993 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596605.9 | 512879.6 | 86003 | 1.64041666667 | 13993 |
| 014651 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596604.1 | 512880.6 | 86005 | 1.64041666667 | 14651 |
| 013468 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596602.7 | 512881.5 | 86007 | 1.64041666667 | 13468 |
| 013748 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596600.5 | 512882.1 | 86009 | 1.64041666667 | 13748 |
| 014033 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596599.7 | 512883.6 | 86011 | 1.64041666667 | 14033 |
| 013616 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596598.9 | 512885.7 | 86013 | 1.64041666667 | 13616 |
| 013974 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596599.1 | 512887.1 | 86015 | 1.64041666667 | 13974 |
| 014513 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596598.6 | 512889.3 | 86017 | 1.64041666667 | 14513 |
| 014171 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:57pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596598.5 | 512891.2 | 86019 | 1.64041666667 | 14171 |
| 013273 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:58pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596598.7 | 512893.1 | 86021 | 1.64041666667 | 13273 |
| 014036 | 0 | GeoXH 6000 | 08/20/2015 | 01:02:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596597.6 | 512895.0 | 86023 | 1.64041666667 | 14036 |
| 014143 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596597.3 | 512897.0 | 86025 | 1.64041666667 | 14143 |
| 013783 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596596.9 | 512899.0 | 86027 | 1.64041666667 | 13783 |
| 014150 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596597.7 | 512901.1 | 86029 | 1.64041666667 | 14150 |
| 015114 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596598.8 | 512902.5 | 86031 | 1.64041666667 | 15114 |
| 015439 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:04pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596600.2 | 512904.3 | 86033 | 1.64041666667 | 15439 |
| 015652 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:05pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596601.5 | 512905.3 | 86035 | 1.64041666667 | 15652 |
| 015232 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:06pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596602.6 | 512906.5 | 86037 | 1.64041666667 | 15232 |
| 014823 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596604.3 | 512906.9 | 86039 | 1.64041666667 | 14823 |
| 013857 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:08pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596606.5 | 512906.9 | 86041 | 1.64041666667 | 13857 |
| 013802 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:09pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596608.4 | 512906.3 | 86043 | 1.64041666667 | 13802 |
| 014596 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:10pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596609.6 | 512905.4 | 86045 | 1.64041666667 | 14596 |
| 014810 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:11pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596611.3 | 512905.7 | 86047 | 1.64041666667 | 14810 |
| 015283 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:12pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596613.2 | 512905.8 | 86049 | 1.64041666667 | 15283 |
| 014214 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596615.5 | 512906.2 | 86051 | 1.64041666667 | 14214 |
| 013958 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596617.2 | 512906.6 | 86053 | 1.64041666667 | 13958 |
| 015389 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596618.6 | 512905.8 | 86055 | 1.64041666667 | 15389 |
| 015113 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:16pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596620.3 | 512905.0 | 86057 | 1.64041666667 | 15113 |
| 014614 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:17pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596620.5 | 512904.4 | 86059 | 1.64041666667 | 14614 |
| 013612 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:18pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596619.0 | 512905.1 | 86061 | 1.64041666667 | 13612 |
| 013417 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:19pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596617.4 | 512905.7 | 86063 | 1.64041666667 | 13417 |
| 013989 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:20pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596615.3 | 512906.6 | 86065 | 1.64041666667 | 13989 |
| 013396 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:21pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596613.2 | 512906.9 | 86067 | 1.64041666667 | 13396 |
| 013835 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:22pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596611.1 | 512906.8 | 86069 | 1.64041666667 | 13835 |
| 014330 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:23pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596609.5 | 512907.2 | 86071 | 1.64041666667 | 14330 |
| 014008 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596607.2 | 512906.6 | 86073 | 1.64041666667 | 14008 |
| 013909 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:25pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596605.4 | 512906.0 | 86075 | 1.64041666667 | 13909 |
| 014386 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:26pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596603.0 | 512906.0 | 86077 | 1.64041666667 | 14386 |
| 015187 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:27pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596601.0 | 512905.4 | 86079 | 1.64041666667 | 15187 |
| 014947 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596599.1 | 512905.4 | 86081 | 1.64041666667 | 14947 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014970 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596597.5 | 512905.1 | 86083 | 1.64041666667 | 14970 |
| 014953 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596595.4 | 512905.0 | 86085 | 1.64041666667 | 14953 |
| 014868 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596593.5 | 512905.4 | 86087 | 1.64041666667 | 14868 |
| 015623 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596591.6 | 512905.8 | 86089 | 1.64041666667 | 15623 |
| 014225 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596590.1 | 512906.8 | 86091 | 1.64041666667 | 14225 |
| 013687 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596588.3 | 512907.5 | 86093 | 1.64041666667 | 13687 |
| 014989 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596587.2 | 512908.4 | 86095 | 1.64041666667 | 14989 |
| 014296 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596585.4 | 512909.0 | 86097 | 1.64041666667 | 14296 |
| 014341 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596584.3 | 512909.9 | 86099 | 1.64041666667 | 14341 |
| 014839 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596582.3 | 512910.7 | 86101 | 1.64041666667 | 14839 |
| 015532 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596580.5 | 512911.4 | 86103 | 1.64041666667 | 15532 |
| 015952 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596578.8 | 512911.9 | 86105 | 1.64041666667 | 15952 |
| 014815 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596577.0 | 512911.9 | 86107 | 1.64041666667 | 14815 |
| 014296 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596575.2 | 512913.1 | 86109 | 1.64041666667 | 14296 |
| 013539 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596573.7 | 512914.0 | 86111 | 1.64041666667 | 13539 |
| 013825 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596571.9 | 512915.7 | 86113 | 1.64041666667 | 13825 |
| 014054 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596571.1 | 512917.0 | 86115 | 1.64041666667 | 14054 |
| 013905 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596569.6 | 512917.7 | 86117 | 1.64041666667 | 13905 |
| 013754 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596568.4 | 512918.5 | 86119 | 1.64041666667 | 13754 |
| 013459 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596566.9 | 512918.5 | 86121 | 1.64041666667 | 13459 |
| 014073 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:49pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596565.7 | 512918.8 | 86123 | 1.64041666667 | 14073 |
| 014358 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:50pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596564.6 | 512918.2 | 86125 | 1.64041666667 | 14358 |
| 014069 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:51pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596563.9 | 512918.4 | 86127 | 1.64041666667 | 14069 |
| 014071 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:52pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596565.0 | 512918.2 | 86129 | 1.64041666667 | 14071 |
| 013562 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:53pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596566.5 | 512917.8 | 86131 | 1.64041666667 | 13562 |
| 014836 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596568.3 | 512917.8 | 86133 | 1.64041666667 | 14836 |
| 014833 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596569.5 | 512918.1 | 86135 | 1.64041666667 | 14833 |
| 015273 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596571.3 | 512916.6 | 86137 | 1.64041666667 | 15273 |
| 016106 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596572.2 | 512915.3 | 86139 | 1.64041666667 | 16106 |
| 015502 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596572.0 | 512913.1 | 86141 | 1.64041666667 | 15502 |
| 014450 | 0 | GeoXH 6000 | 08/20/2015 | 01:03:59pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596571.1 | 512911.5 | 86143 | 1.64041666667 | 14450 |
| 014630 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:00pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596570.2 | 512909.8 | 86145 | 1.64041666667 | 14630 |
| 014672 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:01pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596569.0 | 512908.6 | 86147 | 1.64041666667 | 14672 |
| 014508 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:02pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596568.3 | 512906.6 | 86149 | 1.64041666667 | 14508 |
| 014633 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:03pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596567.4 | 512905.3 | 86151 | 1.64041666667 | 14633 |
| 014486 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:04pm | Sensor | 1797-S0053-905-G-ACK | 6849.2 | 1596567.1 | 512904.1 | 86153 | 1.64041666667 | 14486 |
| 013976 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:05pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596566.7 | 512903.2 | 86155 | 1.64041666667 | 13976 |
| 014206 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:06pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.8 | 512902.6 | 86157 | 1.64041666667 | 14206 |
| 014283 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:07pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.3 | 512902.4 | 86159 | 1.64041666667 | 14283 |
| 013929 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:08pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.2 | 512902.3 | 86161 | 1.64041666667 | 13929 |
| 015013 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:09pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.2 | 512902.2 | 86163 | 1.64041666667 | 15013 |
| 014362 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:10pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596566.2 | 512902.2 | 86165 | 1.64041666667 | 14362 |
| 014258 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:11pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.2 | 512902.1 | 86167 | 1.64041666667 | 14258 |
| 013968 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:12pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.2 | 512902.1 | 86169 | 1.64041666667 | 13968 |
| 013654 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:13pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.2 | 512902.1 | 86171 | 1.64041666667 | 13654 |
| 013823 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:14pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.2 | 512902.1 | 86173 | 1.64041666667 | 13823 |
| 013895 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:15pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596566.3 | 512902.0 | 86175 | 1.64041666667 | 13895 |
| 014056 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:16pm | Sensor | 1797-S0053-905-G-ACK | 6849.2 | 1596567.5 | 512901.1 | 86177 | 1.64041666667 | 14056 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014566 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:17pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596568.1 | 512899.9 | 86179 | 1.64041666667 | 14566 |
| 014343 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:18pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596569.8 | 512898.0 | 86181 | 1.64041666667 | 14343 |
| 014008 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:19pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596570.6 | 512896.5 | 86183 | 1.64041666667 | 14008 |
| 014727 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596571.7 | 512895.1 | 86185 | 1.64041666667 | 14727 |
| 014471 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:21pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596573.2 | 512894.5 | 86187 | 1.64041666667 | 14471 |
| 013427 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596574.8 | 512893.4 | 86189 | 1.64041666667 | 13427 |
| 013853 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596577.0 | 512892.8 | 86191 | 1.64041666667 | 13853 |
| 013462 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596579.3 | 512892.6 | 86193 | 1.64041666667 | 13462 |
| 013032 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596581.2 | 512891.6 | 86195 | 1.64041666667 | 13032 |
| 012978 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596583.4 | 512891.5 | 86197 | 1.64041666667 | 12978 |
| 012918 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596585.5 | 512891.5 | 86199 | 1.64041666667 | 12918 |
| 012936 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596587.1 | 512890.8 | 86201 | 1.64041666667 | 12936 |
| 013036 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596589.2 | 512890.8 | 86203 | 1.64041666667 | 13036 |
| 013168 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596590.9 | 512889.5 | 86205 | 1.64041666667 | 13168 |
| 013084 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596592.6 | 512888.5 | 86207 | 1.64041666667 | 13084 |
| 013345 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596594.0 | 512887.2 | 86209 | 1.64041666667 | 13345 |
| 012966 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596594.4 | 512885.7 | 86211 | 1.64041666667 | 12966 |
| 014771 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596594.8 | 512883.4 | 86213 | 1.64041666667 | 14771 |
| 014346 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596594.4 | 512881.4 | 86215 | 1.64041666667 | 14346 |
| 014460 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596594.7 | 512879.6 | 86217 | 1.64041666667 | 14460 |
| 014141 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596593.8 | 512878.2 | 86219 | 1.64041666667 | 14141 |
| 014111 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596593.9 | 512876.0 | 86221 | 1.64041666667 | 14111 |
| 014283 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596594.4 | 512874.4 | 86223 | 1.64041666667 | 14283 |
| 014589 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596595.5 | 512873.2 | 86225 | 1.64041666667 | 14589 |
| 014753 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596597.4 | 512872.7 | 86227 | 1.64041666667 | 14753 |
| 014899 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596598.9 | 512872.0 | 86229 | 1.64041666667 | 14899 |
| 014864 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596600.9 | 512872.5 | 86231 | 1.64041666667 | 14864 |
| 013920 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596602.9 | 512872.3 | 86233 | 1.64041666667 | 13920 |
| 013560 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596604.5 | 512872.8 | 86235 | 1.64041666667 | 13560 |
| 012487 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596606.8 | 512873.3 | 86237 | 1.64041666667 | 12487 |
| 012574 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596608.3 | 512872.9 | 86239 | 1.64041666667 | 12574 |
| 012608 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596610.4 | 512873.3 | 86241 | 1.64041666667 | 12608 |
| 013527 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596611.7 | 512872.4 | 86243 | 1.64041666667 | 13527 |
| 014209 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596613.2 | 512871.7 | 86245 | 1.64041666667 | 14209 |
| 014337 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596614.3 | 512870.6 | 86247 | 1.64041666667 | 14337 |
| 013577 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596616.5 | 512869.8 | 86249 | 1.64041666667 | 13577 |
| 013314 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596618.3 | 512868.8 | 86251 | 1.64041666667 | 13314 |
| 013579 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596620.3 | 512867.8 | 86253 | 1.64041666667 | 13579 |
| 014103 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596622.0 | 512868.0 | 86255 | 1.64041666667 | 14103 |
| 013745 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596624.0 | 512867.8 | 86257 | 1.64041666667 | 13745 |
| 014729 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596626.0 | 512868.8 | 86259 | 1.64041666667 | 14729 |
| 014367 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596627.7 | 512869.5 | 86261 | 1.64041666667 | 14367 |
| 013744 | 0 | GeoXH 6000 | 08/20/2015 | 01:04:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596628.9 | 512870.9 | 86263 | 1.64041666667 | 13744 |
| 014361 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596630.0 | 512872.6 | 86265 | 1.64041666667 | 14361 |
| 015098 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596630.8 | 512873.8 | 86267 | 1.64041666667 | 15098 |
| 014732 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596630.9 | 512875.4 | 86269 | 1.64041666667 | 14732 |
| 014827 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596631.6 | 512876.6 | 86271 | 1.64041666667 | 14827 |
| 015142 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596631.2 | 512878.6 | 86273 | 1.64041666667 | 15142 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014592 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596631.4 | 512880.4 | 86275 | 1.64041666667 | 14592 |
| 013833 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596631.4 | 512882.2 | 86277 | 1.64041666667 | 13833 |
| 013871 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596632.2 | 512883.7 | 86279 | 1.64041666667 | 13871 |
| 013652 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596632.9 | 512885.7 | 86281 | 1.64041666667 | 13652 |
| 014047 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596633.2 | 512887.4 | 86283 | 1.64041666667 | 14047 |
| 014779 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596633.6 | 512889.0 | 86285 | 1.64041666667 | 14779 |
| 014178 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596633.5 | 512890.9 | 86287 | 1.64041666667 | 14178 |
| 013592 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596634.7 | 512892.3 | 86289 | 1.64041666667 | 13592 |
| 013473 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:13pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596636.3 | 512893.1 | 86291 | 1.64041666667 | 13473 |
| 013458 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:14pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596638.4 | 512893.4 | 86293 | 1.64041666667 | 13458 |
| 014320 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:15pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596639.8 | 512892.8 | 86295 | 1.64041666667 | 14320 |
| 014122 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:16pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596641.6 | 512892.4 | 86297 | 1.64041666667 | 14122 |
| 014401 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:17pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596642.2 | 512890.8 | 86299 | 1.64041666667 | 14401 |
| 014100 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:18pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596641.7 | 512888.8 | 86301 | 1.64041666667 | 14100 |
| 014591 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:19pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596641.3 | 512887.0 | 86303 | 1.64041666667 | 14591 |
| 014643 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:20pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596639.7 | 512886.1 | 86305 | 1.64041666667 | 14643 |
| 013899 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596638.5 | 512885.0 | 86307 | 1.64041666667 | 13899 |
| 013360 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596636.5 | 512883.4 | 86309 | 1.64041666667 | 13360 |
| 013515 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596635.0 | 512883.0 | 86311 | 1.64041666667 | 13515 |
| 012244 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596633.9 | 512881.4 | 86313 | 1.64041666667 | 12244 |
| 012685 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596632.4 | 512880.9 | 86315 | 1.64041666667 | 12685 |
| 012318 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596630.9 | 512879.3 | 86317 | 1.64041666667 | 12318 |
| 012644 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596629.1 | 512878.8 | 86319 | 1.64041666667 | 12644 |
| 012887 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596627.4 | 512878.2 | 86321 | 1.64041666667 | 12887 |
| 013519 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596625.8 | 512877.7 | 86323 | 1.64041666667 | 13519 |
| 013979 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596624.0 | 512877.5 | 86325 | 1.64041666667 | 13979 |
| 013713 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596622.3 | 512876.4 | 86327 | 1.64041666667 | 13713 |
| 013548 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596620.6 | 512876.0 | 86329 | 1.64041666667 | 13548 |
| 012833 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596619.4 | 512874.6 | 86331 | 1.64041666667 | 12833 |
| 013976 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596617.8 | 512873.8 | 86333 | 1.64041666667 | 13976 |
| 014701 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596616.3 | 512872.3 | 86335 | 1.64041666667 | 14701 |
| 014689 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596614.8 | 512870.6 | 86337 | 1.64041666667 | 14689 |
| 014473 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596613.3 | 512869.9 | 86339 | 1.64041666667 | 14473 |
| 013436 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596612.1 | 512868.1 | 86341 | 1.64041666667 | 13436 |
| 013242 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596610.5 | 512867.3 | 86343 | 1.64041666667 | 13242 |
| 014191 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596608.9 | 512865.9 | 86345 | 1.64041666667 | 14191 |
| 013930 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596607.8 | 512864.8 | 86347 | 1.64041666667 | 13930 |
| 013595 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596606.0 | 512863.8 | 86349 | 1.64041666667 | 13595 |
| 013190 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596604.8 | 512862.4 | 86351 | 1.64041666667 | 13190 |
| 012879 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596602.8 | 512861.6 | 86353 | 1.64041666667 | 12879 |
| 013567 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596601.3 | 512860.6 | 86355 | 1.64041666667 | 13567 |
| 013781 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596600.0 | 512859.3 | 86357 | 1.64041666667 | 13781 |
| 014164 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596598.8 | 512858.3 | 86359 | 1.64041666667 | 14164 |
| 014155 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596597.2 | 512857.1 | 86361 | 1.64041666667 | 14155 |
| 014389 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596595.6 | 512857.2 | 86363 | 1.64041666667 | 14389 |
| 014334 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596594.2 | 512857.6 | 86365 | 1.64041666667 | 14334 |
| 013845 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596592.3 | 512858.5 | 86367 | 1.64041666667 | 13845 |
| 013923 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596591.0 | 512859.7 | 86369 | 1.64041666667 | 13923 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014034 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596589.5 | 512860.3 | 86371 | 1.64041666667 | 14034 |
| 014209 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596587.8 | 512861.8 | 86373 | 1.64041666667 | 14209 |
| 014697 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596586.8 | 512862.9 | 86375 | 1.64041666667 | 14697 |
| 015985 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596585.3 | 512863.8 | 86377 | 1.64041666667 | 15985 |
| 015104 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596584.5 | 512865.3 | 86379 | 1.64041666667 | 15104 |
| 014653 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596582.6 | 512866.6 | 86381 | 1.64041666667 | 14653 |
| 013425 | 0 | GeoXH 6000 | 08/20/2015 | 01:05:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596581.3 | 512868.0 | 86383 | 1.64041666667 | 13425 |
| 012839 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596579.4 | 512869.2 | 86385 | 1.64041666667 | 12839 |
| 012607 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596577.3 | 512870.2 | 86387 | 1.64041666667 | 12607 |
| 011696 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596575.6 | 512870.7 | 86389 | 1.64041666667 | 11696 |
| 012639 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:03pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596573.8 | 512870.5 | 86391 | 1.64041666667 | 12639 |
| 012712 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:04pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596572.1 | 512870.8 | 86393 | 1.64041666667 | 12712 |
| 013578 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:05pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596570.6 | 512870.0 | 86395 | 1.64041666667 | 13578 |
| 013952 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:06pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596569.2 | 512868.7 | 86397 | 1.64041666667 | 13952 |
| 013961 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:07pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596568.6 | 512867.1 | 86399 | 1.64041666667 | 13961 |
| 012893 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:08pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596568.2 | 512865.0 | 86401 | 1.64041666667 | 12893 |
| 011985 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:09pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596567.1 | 512863.8 | 86403 | 1.64041666667 | 11985 |
| 011361 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596566.6 | 512861.9 | 86405 | 1.64041666667 | 11361 |
| 011948 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596565.2 | 512861.3 | 86407 | 1.64041666667 | 11948 |
| 012383 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596563.7 | 512859.4 | 86409 | 1.64041666667 | 12383 |
| 012545 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596562.8 | 512858.2 | 86411 | 1.64041666667 | 12545 |
| 012937 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596561.7 | 512856.6 | 86413 | 1.64041666667 | 12937 |
| 013262 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596562.5 | 512855.7 | 86415 | 1.64041666667 | 13262 |
| 013182 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596563.2 | 512853.8 | 86417 | 1.64041666667 | 13182 |
| 013677 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596564.2 | 512852.1 | 86419 | 1.64041666667 | 13677 |
| 013048 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596565.0 | 512850.7 | 86421 | 1.64041666667 | 13048 |
| 014097 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596566.4 | 512850.4 | 86423 | 1.64041666667 | 14097 |
| 013344 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596567.8 | 512848.8 | 86425 | 1.64041666667 | 13344 |
| 013709 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596569.6 | 512848.0 | 86427 | 1.64041666667 | 13709 |
| 012856 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596572.1 | 512846.6 | 86429 | 1.64041666667 | 12856 |
| 013014 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596573.5 | 512845.7 | 86431 | 1.64041666667 | 13014 |
| 013207 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596575.9 | 512845.8 | 86433 | 1.64041666667 | 13207 |
| 012424 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596577.6 | 512845.1 | 86435 | 1.64041666667 | 12424 |
| 013716 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596579.3 | 512844.8 | 86437 | 1.64041666667 | 13716 |
| 012695 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596580.8 | 512845.5 | 86439 | 1.64041666667 | 12695 |
| 013238 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596582.8 | 512846.7 | 86441 | 1.64041666667 | 13238 |
| 014286 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596583.9 | 512848.3 | 86443 | 1.64041666667 | 14286 |
| 013811 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596585.6 | 512849.9 | 86445 | 1.64041666667 | 13811 |
| 012996 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596586.7 | 512851.0 | 86447 | 1.64041666667 | 12996 |
| 012905 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596587.3 | 512853.5 | 86449 | 1.64041666667 | 12905 |
| 013206 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596588.1 | 512855.2 | 86451 | 1.64041666667 | 13206 |
| 013166 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596589.3 | 512857.5 | 86453 | 1.64041666667 | 13166 |
| 013421 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596589.7 | 512859.7 | 86455 | 1.64041666667 | 13421 |
| 013429 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596590.4 | 512862.2 | 86457 | 1.64041666667 | 13429 |
| 014034 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596590.7 | 512863.7 | 86459 | 1.64041666667 | 14034 |
| 013984 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596590.7 | 512865.9 | 86461 | 1.64041666667 | 13984 |
| 013641 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596592.1 | 512867.5 | 86463 | 1.64041666667 | 13641 |
| 014235 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596594.0 | 512869.2 | 86465 | 1.64041666667 | 14235 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014450 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596594.8 | 512870.6 | 86467 | 1.64041666667 | 14450 |
| 015005 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596595.3 | 512871.7 | 86469 | 1.64041666667 | 15005 |
| 014718 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596594.0 | 512872.2 | 86471 | 1.64041666667 | 14718 |
| 014579 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596592.3 | 512872.8 | 86473 | 1.64041666667 | 14579 |
| 013735 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596591.0 | 512873.4 | 86475 | 1.64041666667 | 13735 |
| 013163 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596588.8 | 512873.2 | 86477 | 1.64041666667 | 13163 |
| 012939 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596587.3 | 512874.0 | 86479 | 1.64041666667 | 12939 |
| 013286 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596585.1 | 512873.9 | 86481 | 1.64041666667 | 13286 |
| 013616 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596583.5 | 512874.3 | 86483 | 1.64041666667 | 13616 |
| 012384 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596581.3 | 512874.6 | 86485 | 1.64041666667 | 12384 |
| 011713 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596579.5 | 512874.4 | 86487 | 1.64041666667 | 11713 |
| 011628 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596577.9 | 512875.8 | 86489 | 1.64041666667 | 11628 |
| 012301 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596576.5 | 512876.3 | 86491 | 1.64041666667 | 12301 |
| 013436 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596575.4 | 512877.9 | 86493 | 1.64041666667 | 13436 |
| 013783 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596573.8 | 512878.5 | 86495 | 1.64041666667 | 13783 |
| 012613 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596571.9 | 512880.0 | 86497 | 1.64041666667 | 12613 |
| 011782 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596570.2 | 512880.5 | 86499 | 1.64041666667 | 11782 |
| 012125 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596568.4 | 512880.5 | 86501 | 1.64041666667 | 12125 |
| 011283 | 0 | GeoXH 6000 | 08/20/2015 | 01:06:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596567.0 | 512881.7 | 86503 | 1.64041666667 | 11283 |
| 012196 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596565.3 | 512881.9 | 86505 | 1.64041666667 | 12196 |
| 011953 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596564.1 | 512882.0 | 86507 | 1.64041666667 | 11953 |
| 011636 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596562.7 | 512880.6 | 86509 | 1.64041666667 | 11636 |
| 012072 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596561.8 | 512878.9 | 86511 | 1.64041666667 | 12072 |
| 011793 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596560.5 | 512877.8 | 86513 | 1.64041666667 | 11793 |
| 012723 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596559.7 | 512876.3 | 86515 | 1.64041666667 | 12723 |
| 012639 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596557.9 | 512875.1 | 86517 | 1.64041666667 | 12639 |
| 011760 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596557.5 | 512873.6 | 86519 | 1.64041666667 | 11760 |
| 011362 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596557.6 | 512871.6 | 86521 | 1.64041666667 | 11362 |
| 012481 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596557.0 | 512870.4 | 86523 | 1.64041666667 | 12481 |
| 011837 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596556.9 | 512868.4 | 86525 | 1.64041666667 | 11837 |
| 012021 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596556.2 | 512867.3 | 86527 | 1.64041666667 | 12021 |
| 011209 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:12pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596556.5 | 512865.5 | 86529 | 1.64041666667 | 11209 |
| 011930 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596556.1 | 512863.9 | 86531 | 1.64041666667 | 11930 |
| 011698 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596556.4 | 512861.7 | 86533 | 1.64041666667 | 11698 |
| 011605 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:15pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596555.8 | 512860.2 | 86535 | 1.64041666667 | 11605 |
| 011800 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:16pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596554.4 | 512858.4 | 86537 | 1.64041666667 | 11800 |
| 012180 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:17pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596553.7 | 512857.1 | 86539 | 1.64041666667 | 12180 |
| 012251 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:18pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596552.8 | 512855.2 | 86541 | 1.64041666667 | 12251 |
| 014001 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596553.2 | 512853.9 | 86543 | 1.64041666667 | 14001 |
| 013193 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596553.6 | 512851.9 | 86545 | 1.64041666667 | 13193 |
| 013428 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:21pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596555.1 | 512850.8 | 86547 | 1.64041666667 | 13428 |
| 013283 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:22pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596557.0 | 512849.1 | 86549 | 1.64041666667 | 13283 |
| 013749 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:23pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596558.2 | 512848.0 | 86551 | 1.64041666667 | 13749 |
| 013066 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:24pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596560.5 | 512847.9 | 86553 | 1.64041666667 | 13066 |
| 012532 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596561.9 | 512847.4 | 86555 | 1.64041666667 | 12532 |
| 012704 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596563.5 | 512848.2 | 86557 | 1.64041666667 | 12704 |
| 013746 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:27pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596565.2 | 512848.4 | 86559 | 1.64041666667 | 13746 |
| 014430 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:28pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596566.5 | 512847.1 | 86561 | 1.64041666667 | 14430 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013929 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:29pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596567.7 | 512845.8 | 86563 | 1.64041666667 | 13929 |
| 013055 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596568.1 | 512843.7 | 86565 | 1.64041666667 | 13055 |
| 013336 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596569.3 | 512842.4 | 86567 | 1.64041666667 | 13336 |
| 012916 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:32pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596570.3 | 512840.5 | 86569 | 1.64041666667 | 12916 |
| 012950 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:33pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596571.8 | 512839.7 | 86571 | 1.64041666667 | 12950 |
| 012894 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596573.6 | 512838.0 | 86573 | 1.64041666667 | 12894 |
| 012623 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596574.6 | 512836.8 | 86575 | 1.64041666667 | 12623 |
| 011795 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596577.1 | 512836.6 | 86577 | 1.64041666667 | 11795 |
| 011345 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596578.9 | 512837.0 | 86579 | 1.64041666667 | 11345 |
| 011571 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596580.6 | 512837.3 | 86581 | 1.64041666667 | 11571 |
| 012381 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596582.1 | 512838.7 | 86583 | 1.64041666667 | 12381 |
| 012897 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596584.3 | 512839.9 | 86585 | 1.64041666667 | 12897 |
| 014319 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596586.0 | 512840.4 | 86587 | 1.64041666667 | 14319 |
| 014700 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596587.9 | 512842.3 | 86589 | 1.64041666667 | 14700 |
| 012963 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596589.3 | 512843.9 | 86591 | 1.64041666667 | 12963 |
| 012279 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596591.1 | 512845.6 | 86593 | 1.64041666667 | 12279 |
| 013042 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596591.8 | 512847.8 | 86595 | 1.64041666667 | 13042 |
| 012946 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596592.7 | 512850.1 | 86597 | 1.64041666667 | 12946 |
| 013394 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596592.7 | 512851.8 | 86599 | 1.64041666667 | 13394 |
| 013819 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596592.0 | 512854.5 | 86601 | 1.64041666667 | 13819 |
| 014013 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596592.1 | 512856.3 | 86603 | 1.64041666667 | 14013 |
| 014400 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596592.1 | 512859.0 | 86605 | 1.64041666667 | 14400 |
| 014962 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596592.0 | 512861.0 | 86607 | 1.64041666667 | 14962 |
| 014544 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596592.4 | 512863.0 | 86609 | 1.64041666667 | 14544 |
| 014563 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596592.0 | 512864.4 | 86611 | 1.64041666667 | 14563 |
| 014357 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596591.3 | 512866.4 | 86613 | 1.64041666667 | 14357 |
| 014195 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596589.9 | 512867.6 | 86615 | 1.64041666667 | 14195 |
| 013850 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596587.0 | 512869.4 | 86617 | 1.64041666667 | 13850 |
| 013220 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596585.9 | 512870.1 | 86619 | 1.64041666667 | 13220 |
| 012394 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596583.8 | 512870.7 | 86621 | 1.64041666667 | 12394 |
| 012094 | 0 | GeoXH 6000 | 08/20/2015 | 01:07:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596583.0 | 512871.8 | 86623 | 1.64041666667 | 12094 |
| 011453 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:00pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596580.6 | 512872.6 | 86625 | 1.64041666667 | 11453 |
| 011730 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:01pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596579.0 | 512873.9 | 86627 | 1.64041666667 | 11730 |
| 011840 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:02pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596577.5 | 512876.1 | 86629 | 1.64041666667 | 11840 |
| 011797 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:03pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596575.9 | 512877.2 | 86631 | 1.64041666667 | 11797 |
| 012043 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:04pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596574.9 | 512879.0 | 86633 | 1.64041666667 | 12043 |
| 013089 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:05pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596573.6 | 512879.7 | 86635 | 1.64041666667 | 13089 |
| 012583 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596573.6 | 512881.6 | 86637 | 1.64041666667 | 12583 |
| 011795 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:07pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596573.4 | 512883.0 | 86639 | 1.64041666667 | 11795 |
| 012432 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596574.6 | 512884.8 | 86641 | 1.64041666667 | 12432 |
| 012535 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596575.5 | 512886.0 | 86643 | 1.64041666667 | 12535 |
| 012893 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596576.4 | 512887.7 | 86645 | 1.64041666667 | 12893 |
| 013522 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596577.7 | 512888.7 | 86647 | 1.64041666667 | 13522 |
| 013254 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596579.4 | 512889.5 | 86649 | 1.64041666667 | 13254 |
| 012675 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596580.8 | 512889.2 | 86651 | 1.64041666667 | 12675 |
| 012687 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596582.5 | 512888.3 | 86653 | 1.64041666667 | 12687 |
| 012709 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596583.3 | 512886.9 | 86655 | 1.64041666667 | 12709 |
| 012931 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596583.4 | 512885.1 | 86657 | 1.64041666667 | 12931 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012486 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596583.7 | 512883.6 | 86659 | 1.64041666667 | 12486 |
| 013091 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596582.1 | 512883.3 | 86661 | 1.64041666667 | 13091 |
| 012853 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596580.8 | 512882.4 | 86663 | 1.64041666667 | 12853 |
| 013035 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596578.9 | 512882.5 | 86665 | 1.64041666667 | 13035 |
| 012642 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:21pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596577.9 | 512881.7 | 86667 | 1.64041666667 | 12642 |
| 012983 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:22pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596577.0 | 512880.6 | 86669 | 1.64041666667 | 12983 |
| 012868 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:23pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596577.2 | 512879.3 | 86671 | 1.64041666667 | 12868 |
| 012533 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:24pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596578.7 | 512878.5 | 86673 | 1.64041666667 | 12533 |
| 012607 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596579.9 | 512877.4 | 86675 | 1.64041666667 | 12607 |
| 012431 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596581.7 | 512876.8 | 86677 | 1.64041666667 | 12431 |
| 011898 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596582.7 | 512875.6 | 86679 | 1.64041666667 | 11898 |
| 012610 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596584.8 | 512875.8 | 86681 | 1.64041666667 | 12610 |
| 012958 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596586.5 | 512875.6 | 86683 | 1.64041666667 | 12958 |
| 012936 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596588.6 | 512875.8 | 86685 | 1.64041666667 | 12936 |
| 013629 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596590.2 | 512876.5 | 86687 | 1.64041666667 | 13629 |
| 013584 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596591.7 | 512877.1 | 86689 | 1.64041666667 | 13584 |
| 014563 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596592.4 | 512878.7 | 86691 | 1.64041666667 | 14563 |
| 014874 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.7 | 512880.2 | 86693 | 1.64041666667 | 14874 |
| 014629 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596594.1 | 512881.4 | 86695 | 1.64041666667 | 14629 |
| 014589 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.7 | 512882.9 | 86697 | 1.64041666667 | 14589 |
| 014641 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596593.5 | 512884.0 | 86699 | 1.64041666667 | 14641 |
| 014678 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596591.9 | 512884.0 | 86701 | 1.64041666667 | 14678 |
| 014511 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596590.6 | 512884.8 | 86703 | 1.64041666667 | 14511 |
| 013630 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596588.6 | 512885.0 | 86705 | 1.64041666667 | 13630 |
| 013832 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596587.3 | 512886.0 | 86707 | 1.64041666667 | 13832 |
| 013353 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596585.4 | 512886.7 | 86709 | 1.64041666667 | 13353 |
| 013323 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596584.4 | 512888.0 | 86711 | 1.64041666667 | 13323 |
| 013472 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596583.0 | 512889.1 | 86713 | 1.64041666667 | 13472 |
| 013053 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596581.6 | 512889.1 | 86715 | 1.64041666667 | 13053 |
| 012855 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596579.9 | 512890.2 | 86717 | 1.64041666667 | 12855 |
| 012825 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596578.1 | 512890.8 | 86719 | 1.64041666667 | 12825 |
| 012854 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596576.3 | 512892.4 | 86721 | 1.64041666667 | 12854 |
| 012540 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596575.4 | 512893.3 | 86723 | 1.64041666667 | 12540 |
| 013009 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596574.0 | 512894.1 | 86725 | 1.64041666667 | 13009 |
| 014397 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596572.7 | 512894.4 | 86727 | 1.64041666667 | 14397 |
| 014106 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596570.4 | 512894.9 | 86729 | 1.64041666667 | 14106 |
| 014234 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:53pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596569.9 | 512896.0 | 86731 | 1.64041666667 | 14234 |
| 014187 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:54pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596569.2 | 512897.0 | 86733 | 1.64041666667 | 14187 |
| 013830 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:55pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596570.4 | 512897.7 | 86735 | 1.64041666667 | 13830 |
| 013637 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:56pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596571.9 | 512899.1 | 86737 | 1.64041666667 | 13637 |
| 014226 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:57pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596572.6 | 512899.7 | 86739 | 1.64041666667 | 14226 |
| 013679 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:58pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596574.3 | 512899.6 | 86741 | 1.64041666667 | 13679 |
| 014430 | 0 | GeoXH 6000 | 08/20/2015 | 01:08:59pm | Sensor | 1797-S0053-905-G-ACK | 6849.2 | 1596575.1 | 512900.5 | 86743 | 1.64041666667 | 14430 |
| 014229 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:00pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596576.1 | 512900.9 | 86745 | 1.64041666667 | 14229 |
| 013553 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:01pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596577.0 | 512902.1 | 86747 | 1.64041666667 | 13553 |
| 013654 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:02pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596578.3 | 512903.9 | 86749 | 1.64041666667 | 13654 |
| 013770 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596579.5 | 512905.1 | 86751 | 1.64041666667 | 13770 |
| 013745 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596580.5 | 512906.9 | 86753 | 1.64041666667 | 13745 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014519 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596581.9 | 512907.7 | 86755 | 1.64041666667 | 14519 |
| 014670 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596583.4 | 512909.2 | 86757 | 1.64041666667 | 14670 |
| 014724 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596585.2 | 512909.3 | 86759 | 1.64041666667 | 14724 |
| 015182 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596587.1 | 512908.5 | 86761 | 1.64041666667 | 15182 |
| 014600 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596588.4 | 512907.6 | 86763 | 1.64041666667 | 14600 |
| 015210 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596589.0 | 512905.6 | 86765 | 1.64041666667 | 15210 |
| 015043 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596589.6 | 512903.9 | 86767 | 1.64041666667 | 15043 |
| 013651 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596587.7 | 512903.2 | 86769 | 1.64041666667 | 13651 |
| 014556 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596586.7 | 512902.1 | 86771 | 1.64041666667 | 14556 |
| 014225 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596585.4 | 512901.9 | 86773 | 1.64041666667 | 14225 |
| 014189 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596584.6 | 512900.9 | 86775 | 1.64041666667 | 14189 |
| 014071 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596583.0 | 512900.1 | 86777 | 1.64041666667 | 14071 |
| 013397 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596583.3 | 512898.9 | 86779 | 1.64041666667 | 13397 |
| 013806 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596582.6 | 512897.1 | 86781 | 1.64041666667 | 13806 |
| 013083 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596583.4 | 512895.6 | 86783 | 1.64041666667 | 13083 |
| 012579 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596583.1 | 512893.7 | 86785 | 1.64041666667 | 12579 |
| 013548 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596582.9 | 512892.0 | 86787 | 1.64041666667 | 13548 |
| 013028 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596582.9 | 512890.6 | 86789 | 1.64041666667 | 13028 |
| 014191 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596582.0 | 512890.1 | 86791 | 1.64041666667 | 14191 |
| 013510 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596579.8 | 512889.5 | 86793 | 1.64041666667 | 13510 |
| 013351 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596578.1 | 512890.6 | 86795 | 1.64041666667 | 13351 |
| 013173 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596576.1 | 512892.1 | 86797 | 1.64041666667 | 13173 |
| 012899 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596574.4 | 512892.8 | 86799 | 1.64041666667 | 12899 |
| 013586 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596572.4 | 512894.1 | 86801 | 1.64041666667 | 13586 |
| 013424 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596570.9 | 512894.5 | 86803 | 1.64041666667 | 13424 |
| 014069 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:30pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596569.0 | 512895.9 | 86805 | 1.64041666667 | 14069 |
| 014078 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:31pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596567.5 | 512896.4 | 86807 | 1.64041666667 | 14078 |
| 015051 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:32pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596566.6 | 512896.5 | 86809 | 1.64041666667 | 15051 |
| 015539 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:33pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596565.1 | 512895.5 | 86811 | 1.64041666667 | 15539 |
| 015820 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:34pm | Sensor | 1797-S0053-905-G-ACK | 6848.5 | 1596563.9 | 512894.2 | 86813 | 1.64041666667 | 15820 |
| 015079 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:35pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596562.8 | 512893.8 | 86815 | 1.64041666667 | 15079 |
| 014512 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:36pm | Sensor | 1797-S0053-905-G-ACK | 6848.4 | 1596561.1 | 512892.4 | 86817 | 1.64041666667 | 14512 |
| 013878 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:37pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596560.3 | 512891.4 | 86819 | 1.64041666667 | 13878 |
| 013866 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:38pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596559.2 | 512890.7 | 86821 | 1.64041666667 | 13866 |
| 013230 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:39pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596557.8 | 512889.4 | 86823 | 1.64041666667 | 13230 |
| 014371 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596555.9 | 512889.1 | 86825 | 1.64041666667 | 14371 |
| 013341 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596554.6 | 512888.1 | 86827 | 1.64041666667 | 13341 |
| 013564 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596552.2 | 512887.9 | 86829 | 1.64041666667 | 13564 |
| 013352 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596550.4 | 512887.9 | 86831 | 1.64041666667 | 13352 |
| 013878 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596548.0 | 512886.8 | 86833 | 1.64041666667 | 13878 |
| 013484 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596546.0 | 512886.3 | 86835 | 1.64041666667 | 13484 |
| 013419 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596543.6 | 512885.8 | 86837 | 1.64041666667 | 13419 |
| 013128 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596542.1 | 512884.8 | 86839 | 1.64041666667 | 13128 |
| 013594 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:48pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596540.4 | 512884.4 | 86841 | 1.64041666667 | 13594 |
| 012807 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:49pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596539.8 | 512882.8 | 86843 | 1.64041666667 | 12807 |
| 012926 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596538.9 | 512881.3 | 86845 | 1.64041666667 | 12926 |
| 013098 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:51pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596539.3 | 512879.9 | 86847 | 1.64041666667 | 13098 |
| 014710 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:52pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596539.1 | 512878.5 | 86849 | 1.64041666667 | 14710 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013637 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596540.2 | 512877.4 | 86851 | 1.64041666667 | 13637 |
| 013018 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:54pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596540.4 | 512875.4 | 86853 | 1.64041666667 | 13018 |
| 011943 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:55pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596540.5 | 512874.1 | 86855 | 1.64041666667 | 11943 |
| 012200 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:56pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596539.9 | 512872.3 | 86857 | 1.64041666667 | 12200 |
| 012435 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:57pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596538.7 | 512871.2 | 86859 | 1.64041666667 | 12435 |
| 012259 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:58pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596538.0 | 512870.1 | 86861 | 1.64041666667 | 12259 |
| 012213 | 0 | GeoXH 6000 | 08/20/2015 | 01:09:59pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596536.7 | 512869.3 | 86863 | 1.64041666667 | 12213 |
| 012420 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:00pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596535.5 | 512867.7 | 86865 | 1.64041666667 | 12420 |
| 012296 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:01pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596534.6 | 512866.6 | 86867 | 1.64041666667 | 12296 |
| 012301 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596533.8 | 512865.3 | 86869 | 1.64041666667 | 12301 |
| 012687 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596533.9 | 512863.8 | 86871 | 1.64041666667 | 12687 |
| 012094 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:04pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596534.0 | 512862.3 | 86873 | 1.64041666667 | 12094 |
| 012585 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:05pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596535.4 | 512861.4 | 86875 | 1.64041666667 | 12585 |
| 013394 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:06pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596536.3 | 512859.3 | 86877 | 1.64041666667 | 13394 |
| 013084 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:07pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596537.5 | 512858.3 | 86879 | 1.64041666667 | 13084 |
| 012827 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:08pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596537.9 | 512856.8 | 86881 | 1.64041666667 | 12827 |
| 012510 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:09pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596539.2 | 512856.5 | 86883 | 1.64041666667 | 12510 |
| 014079 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596541.0 | 512856.0 | 86885 | 1.64041666667 | 14079 |
| 013717 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:11pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596542.4 | 512856.9 | 86887 | 1.64041666667 | 13717 |
| 013123 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:12pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596543.6 | 512858.1 | 86889 | 1.64041666667 | 13123 |
| 012527 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:13pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596544.5 | 512858.6 | 86891 | 1.64041666667 | 12527 |
| 013406 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:14pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596544.9 | 512860.2 | 86893 | 1.64041666667 | 13406 |
| 012903 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:15pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596546.1 | 512861.5 | 86895 | 1.64041666667 | 12903 |
| 013093 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596547.0 | 512863.7 | 86897 | 1.64041666667 | 13093 |
| 013192 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596547.8 | 512864.6 | 86899 | 1.64041666667 | 13192 |
| 012731 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:18pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596547.9 | 512866.2 | 86901 | 1.64041666667 | 12731 |
| 011916 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596548.1 | 512867.6 | 86903 | 1.64041666667 | 11916 |
| 011870 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596546.8 | 512869.3 | 86905 | 1.64041666667 | 11870 |
| 011897 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596546.5 | 512870.9 | 86907 | 1.64041666667 | 11897 |
| 012167 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596546.2 | 512872.8 | 86909 | 1.64041666667 | 12167 |
| 011869 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596546.9 | 512874.0 | 86911 | 1.64041666667 | 11869 |
| 012113 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596548.2 | 512875.3 | 86913 | 1.64041666667 | 12113 |
| 011711 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596548.9 | 512876.7 | 86915 | 1.64041666667 | 11711 |
| 012317 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596549.9 | 512878.0 | 86917 | 1.64041666667 | 12317 |
| 013708 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596549.9 | 512879.8 | 86919 | 1.64041666667 | 13708 |
| 013073 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596550.9 | 512881.0 | 86921 | 1.64041666667 | 13073 |
| 013623 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596551.9 | 512882.3 | 86923 | 1.64041666667 | 13623 |
| 013791 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596553.0 | 512883.7 | 86925 | 1.64041666667 | 13791 |
| 013825 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596553.7 | 512884.7 | 86927 | 1.64041666667 | 13825 |
| 013919 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:32pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596554.4 | 512886.3 | 86929 | 1.64041666667 | 13919 |
| 014467 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:33pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596555.5 | 512886.8 | 86931 | 1.64041666667 | 14467 |
| 015015 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:34pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596555.4 | 512888.3 | 86933 | 1.64041666667 | 15015 |
| 014296 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:35pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596555.8 | 512889.6 | 86935 | 1.64041666667 | 14296 |
| 014881 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:36pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596554.8 | 512891.8 | 86937 | 1.64041666667 | 14881 |
| 014648 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:37pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596554.6 | 512893.7 | 86939 | 1.64041666667 | 14648 |
| 014509 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:38pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596555.0 | 512895.8 | 86941 | 1.64041666667 | 14509 |
| 014769 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:39pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596555.1 | 512897.8 | 86943 | 1.64041666667 | 14769 |
| 014300 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:40pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596555.5 | 512899.3 | 86945 | 1.64041666667 | 14300 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015026 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:41pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596556.2 | 512900.8 | 86947 | 1.64041666667 | 15026 |
| 015202 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:42pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596556.6 | 512903.1 | 86949 | 1.64041666667 | 15202 |
| 014686 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:43pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596557.1 | 512904.4 | 86951 | 1.64041666667 | 14686 |
| 013983 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:44pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596557.9 | 512906.4 | 86953 | 1.64041666667 | 13983 |
| 014330 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:45pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596557.8 | 512908.5 | 86955 | 1.64041666667 | 14330 |
| 015373 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:46pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596557.5 | 512910.5 | 86957 | 1.64041666667 | 15373 |
| 014692 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596556.8 | 512912.6 | 86959 | 1.64041666667 | 14692 |
| 013912 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596555.5 | 512915.3 | 86961 | 1.64041666667 | 13912 |
| 014418 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596554.5 | 512917.1 | 86963 | 1.64041666667 | 14418 |
| 014417 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596552.4 | 512918.7 | 86965 | 1.64041666667 | 14417 |
| 014530 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596550.8 | 512919.6 | 86967 | 1.64041666667 | 14530 |
| 014990 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596548.5 | 512919.6 | 86969 | 1.64041666667 | 14990 |
| 014724 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596546.7 | 512918.9 | 86971 | 1.64041666667 | 14724 |
| 014200 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596544.9 | 512918.0 | 86973 | 1.64041666667 | 14200 |
| 013470 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596543.1 | 512917.8 | 86975 | 1.64041666667 | 13470 |
| 014259 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596541.0 | 512916.6 | 86977 | 1.64041666667 | 14259 |
| 013923 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596539.1 | 512916.1 | 86979 | 1.64041666667 | 13923 |
| 014132 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:58pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596537.1 | 512914.8 | 86981 | 1.64041666667 | 14132 |
| 013731 | 0 | GeoXH 6000 | 08/20/2015 | 01:10:59pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596535.0 | 512914.2 | 86983 | 1.64041666667 | 13731 |
| 013724 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:00pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596533.0 | 512914.3 | 86985 | 1.64041666667 | 13724 |
| 013367 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596531.3 | 512914.0 | 86987 | 1.64041666667 | 13367 |
| 013721 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596529.4 | 512914.6 | 86989 | 1.64041666667 | 13721 |
| 014408 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596527.3 | 512914.4 | 86991 | 1.64041666667 | 14408 |
| 014322 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596525.7 | 512914.7 | 86993 | 1.64041666667 | 14322 |
| 014528 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596524.5 | 512914.7 | 86995 | 1.64041666667 | 14528 |
| 014149 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596522.7 | 512914.8 | 86997 | 1.64041666667 | 14149 |
| 014011 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596521.3 | 512915.1 | 86999 | 1.64041666667 | 14011 |
| 013491 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596519.4 | 512915.0 | 87001 | 1.64041666667 | 13491 |
| 013761 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596517.7 | 512915.5 | 87003 | 1.64041666667 | 13761 |
| 013238 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596515.4 | 512915.0 | 87005 | 1.64041666667 | 13238 |
| 014669 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596513.6 | 512915.4 | 87007 | 1.64041666667 | 14669 |
| 014693 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596511.5 | 512914.6 | 87009 | 1.64041666667 | 14693 |
| 014385 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596509.9 | 512914.2 | 87011 | 1.64041666667 | 14385 |
| 014594 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596507.9 | 512913.8 | 87013 | 1.64041666667 | 14594 |
| 014786 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596506.6 | 512912.7 | 87015 | 1.64041666667 | 14786 |
| 014407 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596505.1 | 512912.4 | 87017 | 1.64041666667 | 14407 |
| 014029 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596504.7 | 512911.7 | 87019 | 1.64041666667 | 14029 |
| 014544 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596504.1 | 512912.2 | 87021 | 1.64041666667 | 14544 |
| 014458 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596503.4 | 512913.5 | 87023 | 1.64041666667 | 14458 |
| 014793 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596503.6 | 512915.1 | 87025 | 1.64041666667 | 14793 |
| 014718 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596503.1 | 512916.7 | 87027 | 1.64041666667 | 14718 |
| 015059 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596503.7 | 512918.5 | 87029 | 1.64041666667 | 15059 |
| 014208 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596503.1 | 512920.0 | 87031 | 1.64041666667 | 14208 |
| 014584 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596503.6 | 512921.9 | 87033 | 1.64041666667 | 14584 |
| 015239 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596503.2 | 512923.4 | 87035 | 1.64041666667 | 15239 |
| 014452 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596503.3 | 512925.4 | 87037 | 1.64041666667 | 14452 |
| 014414 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596502.7 | 512927.0 | 87039 | 1.64041666667 | 14414 |
| 014700 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596502.8 | 512928.7 | 87041 | 1.64041666667 | 14700 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015296 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596503.3 | 512930.2 | 87043 | 1.64041666667 | 15296 |
| 015279 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596503.7 | 512932.2 | 87045 | 1.64041666667 | 15279 |
| 014512 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:31pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596504.9 | 512933.3 | 87047 | 1.64041666667 | 14512 |
| 014710 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:32pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596506.0 | 512934.8 | 87049 | 1.64041666667 | 14710 |
| 013824 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:33pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596507.5 | 512934.9 | 87051 | 1.64041666667 | 13824 |
| 014474 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:34pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596509.0 | 512935.6 | 87053 | 1.64041666667 | 14474 |
| 014239 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:35pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596510.4 | 512935.8 | 87055 | 1.64041666667 | 14239 |
| 014452 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:36pm | Sensor | 1797-S0053-905-G-ACK | 6848.8 | 1596511.5 | 512936.6 | 87057 | 1.64041666667 | 14452 |
| 013829 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:37pm | Sensor | 1797-S0053-905-G-ACK | 6848.7 | 1596512.9 | 512936.5 | 87059 | 1.64041666667 | 13829 |
| 013884 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:38pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596513.4 | 512937.2 | 87061 | 1.64041666667 | 13884 |
| 014162 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:39pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596514.1 | 512937.6 | 87063 | 1.64041666667 | 14162 |
| 013493 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596515.1 | 512939.2 | 87065 | 1.64041666667 | 13493 |
| 013305 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596516.5 | 512940.1 | 87067 | 1.64041666667 | 13305 |
| 013394 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596517.3 | 512941.0 | 87069 | 1.64041666667 | 13394 |
| 014299 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596517.4 | 512941.1 | 87071 | 1.64041666667 | 14299 |
| 013233 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596518.0 | 512940.8 | 87073 | 1.64041666667 | 13233 |
| 013098 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596518.6 | 512939.5 | 87075 | 1.64041666667 | 13098 |
| 014403 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596518.6 | 512939.7 | 87077 | 1.64041666667 | 14403 |
| 014416 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596518.3 | 512941.0 | 87079 | 1.64041666667 | 14416 |
| 013546 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596518.3 | 512942.1 | 87081 | 1.64041666667 | 13546 |
| 013620 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596518.5 | 512943.1 | 87083 | 1.64041666667 | 13620 |
| 014321 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596516.9 | 512944.5 | 87085 | 1.64041666667 | 14321 |
| 014280 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596517.5 | 512945.6 | 87087 | 1.64041666667 | 14280 |
| 014062 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596517.2 | 512947.9 | 87089 | 1.64041666667 | 14062 |
| 013527 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596516.5 | 512948.6 | 87091 | 1.64041666667 | 13527 |
| 013024 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596515.1 | 512950.0 | 87093 | 1.64041666667 | 13024 |
| 013873 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596513.6 | 512950.5 | 87095 | 1.64041666667 | 13873 |
| 013241 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596511.9 | 512951.8 | 87097 | 1.64041666667 | 13241 |
| 012848 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596509.7 | 512952.8 | 87099 | 1.64041666667 | 12848 |
| 013414 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596507.3 | 512953.5 | 87101 | 1.64041666667 | 13414 |
| 012675 | 0 | GeoXH 6000 | 08/20/2015 | 01:11:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596505.6 | 512954.4 | 87103 | 1.64041666667 | 12675 |
| 013422 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596503.7 | 512955.3 | 87105 | 1.64041666667 | 13422 |
| 012807 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596502.3 | 512956.5 | 87107 | 1.64041666667 | 12807 |
| 012589 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596500.9 | 512957.0 | 87109 | 1.64041666667 | 12589 |
| 014641 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596500.2 | 512958.3 | 87111 | 1.64041666667 | 14641 |
| 014025 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:04pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596498.7 | 512959.6 | 87113 | 1.64041666667 | 14025 |
| 013267 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596497.3 | 512961.5 | 87115 | 1.64041666667 | 13267 |
| 014212 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596496.2 | 512964.0 | 87117 | 1.64041666667 | 14212 |
| 014954 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596495.1 | 512965.5 | 87119 | 1.64041666667 | 14954 |
| 014344 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596495.0 | 512967.5 | 87121 | 1.64041666667 | 14344 |
| 014016 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596494.8 | 512969.2 | 87123 | 1.64041666667 | 14016 |
| 014071 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596495.7 | 512971.1 | 87125 | 1.64041666667 | 14071 |
| 013937 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596497.0 | 512972.1 | 87127 | 1.64041666667 | 13937 |
| 014695 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596498.9 | 512973.6 | 87129 | 1.64041666667 | 14695 |
| 014191 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596500.0 | 512974.1 | 87131 | 1.64041666667 | 14191 |
| 014695 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596500.5 | 512975.3 | 87133 | 1.64041666667 | 14695 |
| 015158 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596502.0 | 512975.4 | 87135 | 1.64041666667 | 15158 |
| 014609 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596503.5 | 512976.1 | 87137 | 1.64041666667 | 14609 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013977 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596504.4 | 512975.3 | 87139 | 1.64041666667 | 13977 |
| 014155 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596504.4 | 512975.0 | 87141 | 1.64041666667 | 14155 |
| 013354 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596504.3 | 512976.0 | 87143 | 1.64041666667 | 13354 |
| 012987 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596504.6 | 512976.9 | 87145 | 1.64041666667 | 12987 |
| 013290 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596505.0 | 512976.8 | 87147 | 1.64041666667 | 13290 |
| 012995 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596507.1 | 512976.8 | 87149 | 1.64041666667 | 12995 |
| 012905 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596509.0 | 512977.1 | 87151 | 1.64041666667 | 12905 |
| 012546 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596511.2 | 512976.4 | 87153 | 1.64041666667 | 12546 |
| 0 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:25pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596513.6 | 512976.8 | 87155 | 1.64041666667 | 0 |
| 013992 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:26pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596515.9 | 512977.1 | 87157 | 1.64041666667 | 13992 |
| 013863 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:27pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596517.5 | 512976.7 | 87159 | 1.64041666667 | 13863 |
| 014045 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:28pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596519.8 | 512977.8 | 87161 | 1.64041666667 | 14045 |
| 013270 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:29pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596521.1 | 512978.4 | 87163 | 1.64041666667 | 13270 |
| 013269 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:30pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596522.2 | 512979.7 | 87165 | 1.64041666667 | 13269 |
| 013396 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596523.8 | 512980.8 | 87167 | 1.64041666667 | 13396 |
| 013228 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:32pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596524.4 | 512982.5 | 87169 | 1.64041666667 | 13228 |
| 013395 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596525.3 | 512983.4 | 87171 | 1.64041666667 | 13395 |
| 013392 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:34pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596525.0 | 512985.2 | 87173 | 1.64041666667 | 13392 |
| 013143 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:35pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596525.8 | 512985.9 | 87175 | 1.64041666667 | 13143 |
| 013393 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:36pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596526.5 | 512986.6 | 87177 | 1.64041666667 | 13393 |
| 013826 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:37pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596527.6 | 512987.4 | 87179 | 1.64041666667 | 13826 |
| 013499 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:38pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596529.1 | 512987.0 | 87181 | 1.64041666667 | 13499 |
| 013908 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:39pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596530.0 | 512985.8 | 87183 | 1.64041666667 | 13908 |
| 012938 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:40pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596531.2 | 512984.4 | 87185 | 1.64041666667 | 12938 |
| 012790 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:41pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596531.9 | 512983.4 | 87187 | 1.64041666667 | 12790 |
| 012482 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:42pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596533.6 | 512982.2 | 87189 | 1.64041666667 | 12482 |
| 012016 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:43pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596534.9 | 512981.3 | 87191 | 1.64041666667 | 12016 |
| 012519 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:44pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596536.6 | 512980.4 | 87193 | 1.64041666667 | 12519 |
| 012674 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:45pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596538.6 | 512979.8 | 87195 | 1.64041666667 | 12674 |
| 012739 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:46pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596541.1 | 512979.8 | 87197 | 1.64041666667 | 12739 |
| 012041 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:47pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596543.1 | 512979.4 | 87199 | 1.64041666667 | 12041 |
| 012293 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:48pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596545.9 | 512980.4 | 87201 | 1.64041666667 | 12293 |
| 012990 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:49pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596547.6 | 512980.4 | 87203 | 1.64041666667 | 12990 |
| 013651 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:50pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596550.0 | 512979.8 | 87205 | 1.64041666667 | 13651 |
| 013341 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:51pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596551.6 | 512979.1 | 87207 | 1.64041666667 | 13341 |
| 013084 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:52pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596552.2 | 512977.1 | 87209 | 1.64041666667 | 13084 |
| 013262 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:53pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596553.4 | 512975.6 | 87211 | 1.64041666667 | 13262 |
| 012920 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596553.1 | 512973.7 | 87213 | 1.64041666667 | 12920 |
| 013867 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596554.3 | 512972.8 | 87215 | 1.64041666667 | 13867 |
| 012698 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596554.1 | 512971.2 | 87217 | 1.64041666667 | 12698 |
| 013015 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596555.0 | 512969.7 | 87219 | 1.64041666667 | 13015 |
| 012623 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596553.4 | 512968.0 | 87221 | 1.64041666667 | 12623 |
| 012898 | 0 | GeoXH 6000 | 08/20/2015 | 01:12:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596553.9 | 512966.2 | 87222 | 1.64041666667 | 12898 |
| 013855 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596552.9 | 512964.3 | 87225 | 1.64041666667 | 13855 |
| 014543 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596553.5 | 512963.3 | 87227 | 1.64041666667 | 14543 |
| 013948 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596554.5 | 512961.3 | 87229 | 1.64041666667 | 13948 |
| 013358 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596556.3 | 512960.5 | 87231 | 1.64041666667 | 13358 |
| 012179 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596558.2 | 512959.1 | 87233 | 1.64041666667 | 12179 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013120 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596560.2 | 512959.2 | 87235 | 1.64041666667 | 13120 |
| 013455 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596561.9 | 512958.7 | 87237 | 1.64041666667 | 13455 |
| 013186 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596563.3 | 512959.0 | 87239 | 1.64041666667 | 13186 |
| 014077 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596565.4 | 512958.8 | 87241 | 1.64041666667 | 14077 |
| 014781 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596566.9 | 512958.4 | 87243 | 1.64041666667 | 14781 |
| 014314 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596568.7 | 512959.2 | 87245 | 1.64041666667 | 14314 |
| 013961 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596570.1 | 512959.9 | 87247 | 1.64041666667 | 13961 |
| 013411 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596570.8 | 512962.0 | 87249 | 1.64041666667 | 13411 |
| 012868 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596571.6 | 512963.7 | 87251 | 1.64041666667 | 12868 |
| 012736 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596572.7 | 512965.9 | 87253 | 1.64041666667 | 12736 |
| 013111 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596572.8 | 512967.8 | 87255 | 1.64041666667 | 13111 |
| 013735 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596573.6 | 512969.7 | 87257 | 1.64041666667 | 13735 |
| 013261 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596573.6 | 512971.1 | 87259 | 1.64041666667 | 13261 |
| 013706 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596573.1 | 512973.4 | 87261 | 1.64041666667 | 13706 |
| 013860 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596572.9 | 512974.7 | 87263 | 1.64041666667 | 13860 |
| 014163 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596571.4 | 512975.4 | 87265 | 1.64041666667 | 14163 |
| 013629 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:21pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596569.7 | 512975.8 | 87267 | 1.64041666667 | 13629 |
| 013636 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:22pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596567.5 | 512975.5 | 87269 | 1.64041666667 | 13636 |
| 013280 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:23pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596566.3 | 512976.1 | 87271 | 1.64041666667 | 13280 |
| 013567 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:24pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596564.5 | 512976.4 | 87273 | 1.64041666667 | 13567 |
| 013309 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:25pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596563.3 | 512976.8 | 87275 | 1.64041666667 | 13309 |
| 012706 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:26pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596561.4 | 512978.0 | 87277 | 1.64041666667 | 12706 |
| 012532 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:27pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596560.8 | 512979.2 | 87279 | 1.64041666667 | 12532 |
| 013214 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:28pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596559.9 | 512981.3 | 87281 | 1.64041666667 | 13214 |
| 013208 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:29pm | Sensor | 1797-S0053-905-G-ACK | 6846.8 | 1596559.9 | 512982.5 | 87283 | 1.64041666667 | 13208 |
| 013782 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:30pm | Sensor | 1797-S0053-905-G-ACK | 6846.9 | 1596560.1 | 512985.1 | 87285 | 1.64041666667 | 13782 |
| 014330 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:31pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596561.0 | 512986.7 | 87287 | 1.64041666667 | 14330 |
| 014878 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596561.5 | 512989.0 | 87289 | 1.64041666667 | 14878 |
| 013701 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.0 | 1596562.3 | 512990.5 | 87291 | 1.64041666667 | 13701 |
| 013002 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596562.3 | 512992.5 | 87293 | 1.64041666667 | 13002 |
| 013306 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596563.5 | 512994.0 | 87295 | 1.64041666667 | 13306 |
| 012877 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596563.7 | 512995.8 | 87297 | 1.64041666667 | 12877 |
| 013266 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596565.4 | 512995.4 | 87298 | 1.64041666667 | 13266 |
| 012817 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596568.0 | 512994.6 | 87301 | 1.64041666667 | 12817 |
| 012624 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596569.9 | 512993.3 | 87303 | 1.64041666667 | 12624 |
| 013821 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596570.4 | 512991.4 | 87305 | 1.64041666667 | 13821 |
| 014052 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596571.9 | 512991.0 | 87306 | 1.64041666667 | 14052 |
| 013626 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596573.2 | 512989.1 | 87309 | 1.64041666667 | 13626 |
| 013820 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596574.9 | 512988.2 | 87311 | 1.64041666667 | 13820 |
| 014181 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596575.4 | 512986.5 | 87313 | 1.64041666667 | 14181 |
| 013032 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596576.2 | 512984.8 | 87315 | 1.64041666667 | 13032 |
| 012813 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596575.7 | 512982.7 | 87317 | 1.64041666667 | 12813 |
| 012795 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596575.4 | 512980.7 | 87319 | 1.64041666667 | 12795 |
| 013722 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596575.5 | 512978.8 | 87321 | 1.64041666667 | 13722 |
| 012758 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:49pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596575.0 | 512977.7 | 87323 | 1.64041666667 | 12758 |
| 012861 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:50pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596575.0 | 512975.5 | 87325 | 1.64041666667 | 12861 |
| 013369 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:51pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596574.4 | 512974.2 | 87327 | 1.64041666667 | 13369 |
| 013408 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596574.9 | 512972.1 | 87329 | 1.64041666667 | 13408 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013189 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:53pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596574.5 | 512970.8 | 87331 | 1.64041666667 | 13189 |
| 013351 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:54pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596575.4 | 512969.4 | 87333 | 1.64041666667 | 13351 |
| 013765 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596576.2 | 512967.8 | 87335 | 1.64041666667 | 13765 |
| 014590 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:56pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596577.5 | 512966.6 | 87337 | 1.64041666667 | 14590 |
| 013674 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:57pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596578.4 | 512965.0 | 87339 | 1.64041666667 | 13674 |
| 012739 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596579.2 | 512963.4 | 87341 | 1.64041666667 | 12739 |
| 013901 | 0 | GeoXH 6000 | 08/20/2015 | 01:13:59pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596580.1 | 512962.6 | 87343 | 1.64041666667 | 13901 |
| 013406 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:00pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596579.6 | 512960.3 | 87345 | 1.64041666667 | 13406 |
| 013113 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:01pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596579.9 | 512958.5 | 87347 | 1.64041666667 | 13113 |
| 013054 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:02pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596579.0 | 512956.8 | 87349 | 1.64041666667 | 13054 |
| 013965 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:03pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596578.6 | 512954.9 | 87351 | 1.64041666667 | 13965 |
| 015018 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:04pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596577.5 | 512953.6 | 87353 | 1.64041666667 | 15018 |
| 014567 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:05pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596576.0 | 512952.6 | 87355 | 1.64041666667 | 14567 |
| 014644 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:06pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596575.1 | 512951.0 | 87357 | 1.64041666667 | 14644 |
| 014897 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:07pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596574.2 | 512950.0 | 87359 | 1.64041666667 | 14897 |
| 014747 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:08pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596575.7 | 512948.5 | 87361 | 1.64041666667 | 14747 |
| 013785 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:09pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596577.6 | 512947.3 | 87363 | 1.64041666667 | 13785 |
| 014654 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:10pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596579.1 | 512947.2 | 87365 | 1.64041666667 | 14654 |
| 014033 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:11pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596579.3 | 512948.8 | 87367 | 1.64041666667 | 14033 |
| 013706 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:12pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596580.5 | 512950.5 | 87369 | 1.64041666667 | 13706 |
| 013874 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:13pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596581.1 | 512952.4 | 87371 | 1.64041666667 | 13874 |
| 014299 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:14pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596580.3 | 512954.8 | 87373 | 1.64041666667 | 14299 |
| 014103 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:15pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596580.8 | 512956.7 | 87375 | 1.64041666667 | 14103 |
| 013430 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:16pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596580.0 | 512958.9 | 87377 | 1.64041666667 | 13430 |
| 013202 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:17pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596580.2 | 512960.9 | 87379 | 1.64041666667 | 13202 |
| 012908 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:18pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596580.1 | 512962.9 | 87381 | 1.64041666667 | 12908 |
| 012436 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:19pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596580.3 | 512964.8 | 87383 | 1.64041666667 | 12436 |
| 013347 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:20pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596580.8 | 512967.6 | 87385 | 1.64041666667 | 13347 |
| 013043 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:21pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596580.4 | 512969.6 | 87387 | 1.64041666667 | 13043 |
| 012211 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:22pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596580.9 | 512972.7 | 87389 | 1.64041666667 | 12211 |
| 012726 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:23pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596581.4 | 512975.1 | 87391 | 1.64041666667 | 12726 |
| 012986 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:24pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596581.2 | 512978.3 | 87393 | 1.64041666667 | 12986 |
| 013657 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:25pm | Sensor | 1797-S0053-905-G-ACK | 6847.3 | 1596581.7 | 512980.6 | 87395 | 1.64041666667 | 13657 |
| 014409 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:26pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596582.3 | 512982.8 | 87397 | 1.64041666667 | 14409 |
| 013640 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:27pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596582.6 | 512985.0 | 87399 | 1.64041666667 | 13640 |
| 014400 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:28pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596583.7 | 512987.1 | 87401 | 1.64041666667 | 14400 |
| 014122 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:29pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596584.5 | 512988.8 | 87403 | 1.64041666667 | 14122 |
| 014266 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596584.8 | 512991.2 | 87405 | 1.64041666667 | 14266 |
| 014437 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:30pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596585.5 | 512992.9 | 87406 | 1.64041666667 | 14437 |
| 013356 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:32pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596587.0 | 512995.2 | 87409 | 1.64041666667 | 13356 |
| 013595 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:33pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596587.6 | 512997.6 | 87411 | 1.64041666667 | 13595 |
| 012747 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:34pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596588.2 | 512999.6 | 87413 | 1.64041666667 | 12747 |
| 013237 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:35pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596589.6 | 513001.3 | 87415 | 1.64041666667 | 13237 |
| 013326 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:36pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596590.5 | 513003.7 | 87417 | 1.64041666667 | 13326 |
| 012873 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:37pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596591.5 | 513006.0 | 87419 | 1.64041666667 | 12873 |
| 012206 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:38pm | Sensor | 1797-S0053-905-G-ACK | 6847.4 | 1596593.1 | 513008.4 | 87421 | 1.64041666667 | 12206 |
| 012018 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.5 | 1596594.2 | 513010.6 | 87423 | 1.64041666667 | 12018 |
| 012280 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:40pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596595.5 | 513013.3 | 87425 | 1.64041666667 | 12280 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012435 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:41pm | Sensor | 1797-S0053-905-G-ACK | 6847.6 | 1596597.1 | 513014.9 | 87427 | 1.64041666667 | 12435 |
| 012852 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:42pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596599.2 | 513016.4 | 87429 | 1.64041666667 | 12852 |
| 013514 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:43pm | Sensor | 1797-S0053-905-G-ACK | 6847.7 | 1596601.1 | 513018.1 | 87431 | 1.64041666667 | 13514 |
| 012619 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:44pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596603.1 | 513020.0 | 87433 | 1.64041666667 | 12619 |
| 012971 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:45pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596605.2 | 513021.6 | 87435 | 1.64041666667 | 12971 |
| 012478 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:46pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596607.2 | 513023.2 | 87437 | 1.64041666667 | 12478 |
| 012456 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:47pm | Sensor | 1797-S0053-905-G-ACK | 6847.8 | 1596608.7 | 513025.3 | 87439 | 1.64041666667 | 12456 |
| 012257 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:48pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596611.1 | 513027.0 | 87441 | 1.64041666667 | 12257 |
| 012752 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:49pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596612.9 | 513028.1 | 87443 | 1.64041666667 | 12752 |
| 012175 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:50pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596614.9 | 513029.9 | 87445 | 1.64041666667 | 12175 |
| 012391 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:51pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596616.7 | 513031.6 | 87447 | 1.64041666667 | 12391 |
| 011942 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:52pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596619.3 | 513033.0 | 87449 | 1.64041666667 | 11942 |
| 011915 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:53pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596621.4 | 513034.1 | 87451 | 1.64041666667 | 11915 |
| 011307 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:54pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596623.1 | 513036.1 | 87453 | 1.64041666667 | 11307 |
| 011782 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:54pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596624.5 | 513037.0 | 87454 | 1.64041666667 | 11782 |
| 012537 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:56pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596626.4 | 513038.5 | 87457 | 1.64041666667 | 12537 |
| 011717 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:57pm | Sensor | 1797-S0053-905-G-ACK | 6848.0 | 1596627.6 | 513040.6 | 87459 | 1.64041666667 | 11717 |
| 011938 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:58pm | Sensor | 1797-S0053-905-G-ACK | 6847.9 | 1596629.0 | 513042.1 | 87461 | 1.64041666667 | 11938 |
| 012243 | 0 | GeoXH 6000 | 08/20/2015 | 01:14:59pm | Sensor | 1797-S0053-905-G-ACK | 6848.2 | 1596630.4 | 513043.6 | 87463 | 1.64041666667 | 12243 |
| 012826 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:00pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596630.8 | 513046.1 | 87465 | 1.64041666667 | 12826 |
| 012630 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:00pm | Sensor | 1797-S0053-905-G-ACK | 6848.1 | 1596631.6 | 513047.9 | 87466 | 1.64041666667 | 12630 |
| 013569 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:02pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596632.7 | 513050.2 | 87469 | 1.64041666667 | 13569 |
| 013475 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:03pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596632.8 | 513052.2 | 87471 | 1.64041666667 | 13475 |
| 013099 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:04pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596633.8 | 513054.3 | 87473 | 1.64041666667 | 13099 |
| 013496 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:04pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596634.2 | 513055.7 | 87474 | 1.64041666667 | 13496 |
| 013194 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:06pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596634.8 | 513058.3 | 87477 | 1.64041666667 | 13194 |
| 011966 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:07pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596635.8 | 513060.1 | 87479 | 1.64041666667 | 11966 |
| 012206 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:08pm | Sensor | 1797-S0053-905-G-ACK | 6848.6 | 1596635.6 | 513062.6 | 87481 | 1.64041666667 | 12206 |
| 013083 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:09pm | Sensor | 1797-S0053-905-G-ACK | 6848.9 | 1596634.9 | 513065.0 | 87483 | 1.64041666667 | 13083 |
| 013929 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:10pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596635.2 | 513067.5 | 87485 | 1.64041666667 | 13929 |
| 013632 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:11pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596635.2 | 513069.7 | 87487 | 1.64041666667 | 13632 |
| 013976 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:12pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596635.6 | 513071.8 | 87489 | 1.64041666667 | 13976 |
| 014064 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:12pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596636.7 | 513073.0 | 87490 | 1.64041666667 | 14064 |
| 014211 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:14pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596637.1 | 513075.4 | 87493 | 1.64041666667 | 14211 |
| 013888 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:15pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596636.9 | 513078.2 | 87495 | 1.64041666667 | 13888 |
| 014104 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:16pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596637.3 | 513080.9 | 87497 | 1.64041666667 | 14104 |
| 013379 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:17pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596637.6 | 513082.8 | 87499 | 1.64041666667 | 13379 |
| 013180 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:18pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596637.4 | 513085.9 | 87501 | 1.64041666667 | 13180 |
| 012544 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:19pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596637.5 | 513088.5 | 87503 | 1.64041666667 | 12544 |
| 013011 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:20pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596638.2 | 513091.5 | 87505 | 1.64041666667 | 13011 |
| 012291 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:20pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596638.8 | 513093.6 | 87506 | 1.64041666667 | 12291 |
| 012673 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:22pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596639.2 | 513096.6 | 87509 | 1.64041666667 | 12673 |
| 012514 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:23pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596639.1 | 513099.2 | 87511 | 1.64041666667 | 12514 |
| 012109 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:24pm | Sensor | 1797-S0053-905-G-ACK | 6849.1 | 1596639.5 | 513101.9 | 87513 | 1.64041666667 | 12109 |
| 011311 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:24pm | Sensor | 1797-S0053-905-G-ACK | 6849.2 | 1596640.1 | 513103.6 | 87514 | 1.64041666667 | 11311 |
| 012227 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:26pm | Sensor | 1797-S0053-905-G-ACK | 6849.0 | 1596640.2 | 513106.5 | 87517 | 1.64041666667 | 12227 |
| 013215 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:27pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596640.4 | 513109.0 | 87519 | 1.64041666667 | 13215 |
| 012863 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:28pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596641.6 | 513111.5 | 87521 | 1.64041666667 | 12863 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012463 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:29pm | Sensor | 1797-S0053-905-G-ACK | 6849.2 | 1596641.9 | 513113.5 | 87523 | 1.64041666667 | 12463 |
| 011975 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:30pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596641.9 | 513116.7 | 87525 | 1.64041666667 | 11975 |
| 012451 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:31pm | Sensor | 1797-S0053-905-G-ACK | 6849.3 | 1596642.2 | 513118.5 | 87527 | 1.64041666667 | 12451 |
| 012741 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:32pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596642.3 | 513120.9 | 87529 | 1.64041666667 | 12741 |
| 012424 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:33pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596642.4 | 513123.6 | 87531 | 1.64041666667 | 12424 |
| 012688 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:34pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596643.2 | 513126.2 | 87533 | 1.64041666667 | 12688 |
| 012237 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:35pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596643.8 | 513128.4 | 87535 | 1.64041666667 | 12237 |
| 012043 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:36pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596643.9 | 513131.4 | 87537 | 1.64041666667 | 12043 |
| 011499 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:37pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596644.3 | 513133.6 | 87539 | 1.64041666667 | 11499 |
| 011036 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:38pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596645.5 | 513136.6 | 87541 | 1.64041666667 | 11036 |
| 010820 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:39pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596646.4 | 513138.8 | 87543 | 1.64041666667 | 10820 |
| 010788 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:40pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596647.0 | 513142.0 | 87545 | 1.64041666667 | 10788 |
| 011281 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:41pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596647.4 | 513144.5 | 87547 | 1.64041666667 | 11281 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:42pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596648.4 | 513147.4 | 87549 | 1.64041666667 | 11205 |
| 011425 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:43pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596649.0 | 513149.3 | 87551 | 1.64041666667 | 11425 |
| 011227 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:44pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596649.6 | 513151.9 | 87553 | 1.64041666667 | 11227 |
| 010845 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:45pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596650.5 | 513154.5 | 87555 | 1.64041666667 | 10845 |
| 010818 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:46pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596652.1 | 513157.2 | 87557 | 1.64041666667 | 10818 |
| 010240 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:47pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596653.5 | 513158.9 | 87559 | 1.64041666667 | 10240 |
| 010005 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:48pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596654.7 | 513161.5 | 87561 | 1.64041666667 | 10005 |
| 011425 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:49pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596655.1 | 513164.0 | 87563 | 1.64041666667 | 11425 |
| 010499 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:50pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596655.5 | 513166.2 | 87565 | 1.64041666667 | 10499 |
| 010271 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:51pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596655.9 | 513168.8 | 87567 | 1.64041666667 | 10271 |
| 009640 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:52pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596655.7 | 513171.4 | 87569 | 1.64041666667 | 9640 |
| 009615 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:53pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596655.4 | 513173.9 | 87571 | 1.64041666667 | 9615 |
| 009765 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:54pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596655.8 | 513176.6 | 87573 | 1.64041666667 | 9765 |
| 010158 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:55pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596655.7 | 513179.3 | 87575 | 1.64041666667 | 10158 |
| 011541 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:56pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596655.1 | 513182.2 | 87577 | 1.64041666667 | 11541 |
| 010947 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:57pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596654.4 | 513184.8 | 87579 | 1.64041666667 | 10947 |
| 010740 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:58pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596653.8 | 513187.5 | 87581 | 1.64041666667 | 10740 |
| 010136 | 0 | GeoXH 6000 | 08/20/2015 | 01:15:59pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596653.2 | 513189.4 | 87583 | 1.64041666667 | 10136 |
| 009984 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:00pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596652.8 | 513192.1 | 87585 | 1.64041666667 | 9984 |
| 010183 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:01pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596653.4 | 513194.1 | 87587 | 1.64041666667 | 10183 |
| 010603 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:02pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596653.9 | 513196.5 | 87589 | 1.64041666667 | 10603 |
| 010944 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:03pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596653.2 | 513198.5 | 87591 | 1.64041666667 | 10944 |
| 011466 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:04pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596653.1 | 513201.1 | 87593 | 1.64041666667 | 11466 |
| 011115 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:05pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596653.4 | 513203.5 | 87595 | 1.64041666667 | 11115 |
| 011172 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:06pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596653.5 | 513205.9 | 87597 | 1.64041666667 | 11172 |
| 010049 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:07pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596653.3 | 513208.2 | 87599 | 1.64041666667 | 10049 |
| 011307 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:08pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596654.0 | 513210.4 | 87601 | 1.64041666667 | 11307 |
| 010718 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:09pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596655.0 | 513212.2 | 87603 | 1.64041666667 | 10718 |
| 009756 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:10pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596655.4 | 513214.2 | 87605 | 1.64041666667 | 9756 |
| 009568 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:11pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596655.3 | 513216.4 | 87607 | 1.64041666667 | 9568 |
| 009732 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:12pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596655.9 | 513218.5 | 87609 | 1.64041666667 | 9732 |
| 010446 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:13pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596656.1 | 513220.0 | 87611 | 1.64041666667 | 10446 |
| 010046 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:14pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596655.6 | 513221.4 | 87613 | 1.64041666667 | 10046 |
| 009956 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:15pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596655.7 | 513221.6 | 87615 | 1.64041666667 | 9956 |
| 010025 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:16pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596655.5 | 513221.6 | 87617 | 1.64041666667 | 10025 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010049 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:17pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596655.4 | 513221.6 | 87619 | 1.64041666667 | 10049 |
| 010475 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:18pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596655.6 | 513221.6 | 87621 | 1.64041666667 | 10475 |
| 010219 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:19pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596656.0 | 513221.7 | 87623 | 1.64041666667 | 10219 |
| 009258 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:20pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596656.6 | 513221.6 | 87625 | 1.64041666667 | 9258 |
| 009445 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:21pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596656.5 | 513222.1 | 87627 | 1.64041666667 | 9445 |
| 009813 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:22pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596656.1 | 513223.8 | 87629 | 1.64041666667 | 9813 |
| 010027 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:23pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596657.1 | 513225.4 | 87631 | 1.64041666667 | 10027 |
| 009720 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:24pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596657.7 | 513227.5 | 87633 | 1.64041666667 | 9720 |
| 009742 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:25pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596658.0 | 513230.1 | 87635 | 1.64041666667 | 9742 |
| 009605 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:26pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596658.6 | 513232.9 | 87637 | 1.64041666667 | 9605 |
| 010165 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:27pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596658.6 | 513235.3 | 87639 | 1.64041666667 | 10165 |
| 010600 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:28pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596657.7 | 513237.9 | 87641 | 1.64041666667 | 10600 |
| 010552 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:29pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596656.9 | 513240.2 | 87643 | 1.64041666667 | 10552 |
| 010751 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:30pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596656.7 | 513243.1 | 87645 | 1.64041666667 | 10751 |
| 011147 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:31pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596656.3 | 513245.0 | 87647 | 1.64041666667 | 11147 |
| 012120 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:32pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596656.2 | 513248.2 | 87649 | 1.64041666667 | 12120 |
| 012615 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:33pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596656.6 | 513250.4 | 87651 | 1.64041666667 | 12615 |
| 012788 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:34pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596657.9 | 513252.9 | 87653 | 1.64041666667 | 12788 |
| 011873 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:35pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596658.7 | 513255.1 | 87655 | 1.64041666667 | 11873 |
| 012101 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:36pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596659.2 | 513257.6 | 87657 | 1.64041666667 | 12101 |
| 012094 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:37pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596659.9 | 513259.8 | 87659 | 1.64041666667 | 12094 |
| 013268 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:38pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596660.8 | 513262.2 | 87661 | 1.64041666667 | 13268 |
| 014123 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:39pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596662.3 | 513264.2 | 87663 | 1.64041666667 | 14123 |
| 013134 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:40pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596662.5 | 513267.4 | 87665 | 1.64041666667 | 13134 |
| 013395 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:41pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596662.4 | 513269.9 | 87667 | 1.64041666667 | 13395 |
| 014067 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:42pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596662.7 | 513272.5 | 87669 | 1.64041666667 | 14067 |
| 014138 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:43pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596663.2 | 513274.3 | 87671 | 1.64041666667 | 14138 |
| 013517 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:44pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596662.6 | 513276.9 | 87673 | 1.64041666667 | 13517 |
| 013536 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:45pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596662.3 | 513278.7 | 87675 | 1.64041666667 | 13536 |
| 013734 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:46pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596661.9 | 513280.9 | 87677 | 1.64041666667 | 13734 |
| 013755 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:46pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596661.5 | 513282.9 | 87678 | 1.64041666667 | 13755 |
| 013969 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:48pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596660.5 | 513285.4 | 87681 | 1.64041666667 | 13969 |
| 013310 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:49pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596660.1 | 513288.1 | 87683 | 1.64041666667 | 13310 |
| 012902 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:50pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596660.1 | 513291.2 | 87685 | 1.64041666667 | 12902 |
| 011855 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:50pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596660.0 | 513293.5 | 87686 | 1.64041666667 | 11855 |
| 011528 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:52pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596659.6 | 513296.6 | 87689 | 1.64041666667 | 11528 |
| 011659 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:52pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596659.8 | 513298.8 | 87690 | 1.64041666667 | 11659 |
| 012078 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:54pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596661.2 | 513301.2 | 87693 | 1.64041666667 | 12078 |
| 011841 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:55pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596662.9 | 513303.5 | 87695 | 1.64041666667 | 11841 |
| 012233 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:56pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596664.1 | 513305.7 | 87697 | 1.64041666667 | 12233 |
| 011996 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:57pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596665.4 | 513307.8 | 87699 | 1.64041666667 | 11996 |
| 011585 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:58pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596667.1 | 513309.9 | 87701 | 1.64041666667 | 11585 |
| 011419 | 0 | GeoXH 6000 | 08/20/2015 | 01:16:59pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596668.4 | 513311.8 | 87703 | 1.64041666667 | 11419 |
| 012585 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:00pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596669.5 | 513314.6 | 87705 | 1.64041666667 | 12585 |
| 012929 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:01pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596670.6 | 513317.0 | 87707 | 1.64041666667 | 12929 |
| 012290 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:02pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596672.6 | 513319.1 | 87709 | 1.64041666667 | 12290 |
| 012388 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:03pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596674.0 | 513320.9 | 87711 | 1.64041666667 | 12388 |
| 012398 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:04pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596674.7 | 513323.3 | 87713 | 1.64041666667 | 12398 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011849 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:04pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596675.1 | 513325.1 | 87714 | 1.64041666667 | 11849 |
| 013355 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:06pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596676.7 | 513328.2 | 87717 | 1.64041666667 | 13355 |
| 012582 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:07pm | Sensor | 1797-S0053-905-G-ACK | 6851.7 | 1596677.6 | 513330.5 | 87719 | 1.64041666667 | 12582 |
| 012267 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:08pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596677.9 | 513332.9 | 87721 | 1.64041666667 | 12267 |
| 012502 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:09pm | Sensor | 1797-S0053-905-G-ACK | 6851.7 | 1596677.9 | 513335.3 | 87723 | 1.64041666667 | 12502 |
| 012890 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:10pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596677.8 | 513338.1 | 87725 | 1.64041666667 | 12890 |
| 013115 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:11pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596677.3 | 513340.1 | 87727 | 1.64041666667 | 13115 |
| 012897 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:12pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596676.1 | 513342.1 | 87729 | 1.64041666667 | 12897 |
| 012467 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:13pm | Sensor | 1797-S0053-905-G-ACK | 6851.7 | 1596675.2 | 513344.1 | 87731 | 1.64041666667 | 12467 |
| 012060 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:14pm | Sensor | 1797-S0053-905-G-ACK | 6851.7 | 1596673.9 | 513346.0 | 87733 | 1.64041666667 | 12060 |
| 012086 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:15pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596672.3 | 513346.9 | 87735 | 1.64041666667 | 12086 |
| 013008 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:16pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596669.7 | 513348.0 | 87737 | 1.64041666667 | 13008 |
| 012544 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:16pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596668.5 | 513348.7 | 87738 | 1.64041666667 | 12544 |
| 013536 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:18pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596665.5 | 513349.8 | 87741 | 1.64041666667 | 13536 |
| 014326 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:19pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596663.5 | 513350.0 | 87743 | 1.64041666667 | 14326 |
| 013293 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:20pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596660.5 | 513351.2 | 87745 | 1.64041666667 | 13293 |
| 013245 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:21pm | Sensor | 1797-S0053-905-G-ACK | 6851.7 | 1596658.4 | 513352.2 | 87747 | 1.64041666667 | 13245 |
| 013465 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:22pm | Sensor | 1797-S0053-905-G-ACK | 6851.6 | 1596656.1 | 513352.5 | 87749 | 1.64041666667 | 13465 |
| 013147 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:23pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596653.8 | 513352.2 | 87751 | 1.64041666667 | 13147 |
| 012930 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:24pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596651.0 | 513352.4 | 87753 | 1.64041666667 | 12930 |
| 013018 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:25pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596649.7 | 513352.7 | 87755 | 1.64041666667 | 13018 |
| 012430 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:26pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596647.4 | 513352.1 | 87757 | 1.64041666667 | 12430 |
| 011889 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:27pm | Sensor | 1797-S0053-905-G-ACK | 6851.3 | 1596645.8 | 513352.4 | 87759 | 1.64041666667 | 11889 |
| 012365 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:28pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596643.1 | 513353.8 | 87761 | 1.64041666667 | 12365 |
| 011238 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:29pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596641.3 | 513354.9 | 87763 | 1.64041666667 | 11238 |
| 010664 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:30pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596638.9 | 513356.3 | 87765 | 1.64041666667 | 10664 |
| 010941 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:31pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596637.5 | 513357.8 | 87767 | 1.64041666667 | 10941 |
| 010571 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:32pm | Sensor | 1797-S0053-905-G-ACK | 6851.5 | 1596635.5 | 513359.9 | 87769 | 1.64041666667 | 10571 |
| 010461 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:33pm | Sensor | 1797-S0053-905-G-ACK | 6851.4 | 1596633.7 | 513361.8 | 87771 | 1.64041666667 | 10461 |
| 010692 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:34pm | Sensor | 1797-S0053-905-G-ACK | 6851.2 | 1596632.5 | 513363.4 | 87773 | 1.64041666667 | 10692 |
| 011182 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:34pm | Sensor | 1797-S0053-905-G-ACK | 6851.3 | 1596630.9 | 513365.2 | 87774 | 1.64041666667 | 11182 |
| 010624 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:36pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596628.5 | 513367.1 | 87777 | 1.64041666667 | 10624 |
| 010671 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:36pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596626.6 | 513368.3 | 87778 | 1.64041666667 | 10671 |
| 010067 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:38pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596624.6 | 513370.4 | 87781 | 1.64041666667 | 10067 |
| 009825 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:39pm | Sensor | 1797-S0053-905-G-ACK | 6851.1 | 1596622.8 | 513372.3 | 87783 | 1.64041666667 | 9825 |
| 009217 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:40pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596620.2 | 513373.5 | 87785 | 1.64041666667 | 9217 |
| 009452 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:41pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596617.4 | 513374.8 | 87787 | 1.64041666667 | 9452 |
| 009321 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:42pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596614.8 | 513376.1 | 87789 | 1.64041666667 | 9321 |
| 009863 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:42pm | Sensor | 1797-S0053-905-G-ACK | 6850.7 | 1596613.1 | 513377.0 | 87790 | 1.64041666667 | 9863 |
| 010520 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:44pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596609.9 | 513378.1 | 87793 | 1.64041666667 | 10520 |
| 010297 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:45pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596607.7 | 513378.4 | 87795 | 1.64041666667 | 10297 |
| 010225 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:46pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596605.0 | 513379.4 | 87797 | 1.64041666667 | 10225 |
| 009539 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:47pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596603.1 | 513380.5 | 87799 | 1.64041666667 | 9539 |
| 009580 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:48pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596600.3 | 513381.6 | 87801 | 1.64041666667 | 9580 |
| 010151 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:49pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596597.7 | 513382.9 | 87803 | 1.64041666667 | 10151 |
| 009182 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:50pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596595.9 | 513384.1 | 87805 | 1.64041666667 | 9182 |
| 008930 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:51pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596594.3 | 513385.4 | 87807 | 1.64041666667 | 8930 |
| 009988 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:52pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596591.7 | 513386.5 | 87809 | 1.64041666667 | 9988 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010666 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:52pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596589.6 | 513386.5 | 87810 | 1.64041666667 | 10666 |
| 010102 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:54pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596586.6 | 513386.5 | 87813 | 1.64041666667 | 10102 |
| 010475 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:55pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596584.2 | 513387.4 | 87815 | 1.64041666667 | 10475 |
| 010407 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:56pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596582.1 | 513388.2 | 87817 | 1.64041666667 | 10407 |
| 009956 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:57pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596580.0 | 513388.9 | 87819 | 1.64041666667 | 9956 |
| 009845 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:58pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596578.6 | 513390.6 | 87821 | 1.64041666667 | 9845 |
| 009520 | 0 | GeoXH 6000 | 08/20/2015 | 01:17:59pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596577.5 | 513392.8 | 87823 | 1.64041666667 | 9520 |
| 009990 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:00pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596576.8 | 513394.5 | 87825 | 1.64041666667 | 9990 |
| 010022 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:01pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596575.4 | 513396.2 | 87827 | 1.64041666667 | 10022 |
| 009987 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:02pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596573.8 | 513397.6 | 87829 | 1.64041666667 | 9987 |
| 010432 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:03pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596571.6 | 513398.8 | 87831 | 1.64041666667 | 10432 |
| 009881 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:04pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596569.3 | 513399.8 | 87833 | 1.64041666667 | 9881 |
| 010088 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:05pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596567.0 | 513400.9 | 87835 | 1.64041666667 | 10088 |
| 009829 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:06pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596565.4 | 513402.6 | 87837 | 1.64041666667 | 9829 |
| 009916 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:06pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596564.0 | 513404.3 | 87838 | 1.64041666667 | 9916 |
| 011023 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:08pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596561.6 | 513406.4 | 87841 | 1.64041666667 | 11023 |
| 010430 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:08pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596559.5 | 513407.3 | 87842 | 1.64041666667 | 10430 |
| 009662 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:10pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596556.0 | 513407.6 | 87845 | 1.64041666667 | 9662 |
| 009852 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:11pm | Sensor | 1797-S0053-905-G-ACK | 6850.5 | 1596553.2 | 513408.1 | 87847 | 1.64041666667 | 9852 |
| 010109 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:12pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596550.9 | 513409.1 | 87849 | 1.64041666667 | 10109 |
| 010666 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:13pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596548.8 | 513409.8 | 87851 | 1.64041666667 | 10666 |
| 010095 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:14pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596545.6 | 513410.5 | 87853 | 1.64041666667 | 10095 |
| 009638 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:15pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596543.2 | 513410.5 | 87855 | 1.64041666667 | 9638 |
| 010236 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:16pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596540.0 | 513411.2 | 87857 | 1.64041666667 | 10236 |
| 010205 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:16pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596537.7 | 513412.2 | 87858 | 1.64041666667 | 10205 |
| 009535 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:18pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596534.8 | 513414.0 | 87861 | 1.64041666667 | 9535 |
| 009826 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:18pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596533.1 | 513415.5 | 87862 | 1.64041666667 | 9826 |
| 009029 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:20pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596530.3 | 513416.7 | 87865 | 1.64041666667 | 9029 |
| 008896 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:20pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596528.0 | 513417.2 | 87866 | 1.64041666667 | 8896 |
| 008499 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:22pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596525.5 | 513418.2 | 87869 | 1.64041666667 | 8499 |
| 009371 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:22pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596523.8 | 513419.1 | 87870 | 1.64041666667 | 9371 |
| 009186 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:24pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596521.3 | 513420.0 | 87873 | 1.64041666667 | 9186 |
| 009037 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:25pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596519.0 | 513421.2 | 87875 | 1.64041666667 | 9037 |
| 008698 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:26pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596517.5 | 513422.2 | 87877 | 1.64041666667 | 8698 |
| 008785 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:27pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596515.3 | 513422.5 | 87879 | 1.64041666667 | 8785 |
| 009809 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:28pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596513.5 | 513421.9 | 87881 | 1.64041666667 | 9809 |
| 010070 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:29pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596511.5 | 513422.0 | 87883 | 1.64041666667 | 10070 |
| 010299 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:30pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596510.0 | 513421.7 | 87885 | 1.64041666667 | 10299 |
| 009761 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:31pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596509.6 | 513422.7 | 87887 | 1.64041666667 | 9761 |
| 009555 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:32pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596509.8 | 513424.7 | 87889 | 1.64041666667 | 9555 |
| 009530 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:32pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596510.3 | 513426.8 | 87890 | 1.64041666667 | 9530 |
| 010033 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:34pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596510.5 | 513429.3 | 87893 | 1.64041666667 | 10033 |
| 010361 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:34pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596510.1 | 513431.1 | 87894 | 1.64041666667 | 10361 |
| 010050 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:36pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596508.5 | 513433.2 | 87897 | 1.64041666667 | 10050 |
| 010183 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:36pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596507.6 | 513434.8 | 87898 | 1.64041666667 | 10183 |
| 011090 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:38pm | Sensor | 1797-S0053-905-G-ACK | 6850.9 | 1596506.5 | 513437.3 | 87901 | 1.64041666667 | 11090 |
| 010528 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:38pm | Sensor | 1797-S0053-905-G-ACK | 6851.0 | 1596505.3 | 513438.8 | 87902 | 1.64041666667 | 10528 |
| 010579 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:40pm | Sensor | 1797-S0053-905-G-ACK | 6850.8 | 1596503.3 | 513441.6 | 87905 | 1.64041666667 | 10579 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010683 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:41pm | Sensor | 1797-S0053-905-G-ACK | 6850.6 | 1596502.5 | 513443.5 | 87907 | 1.64041666667 | 10683 |
| 010592 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:42pm | Sensor | 1797-S0053-905-G-ACK | 6850.4 | 1596500.5 | 513446.2 | 87909 | 1.64041666667 | 10592 |
| 009925 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:43pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596498.8 | 513447.4 | 87911 | 1.64041666667 | 9925 |
| 010030 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:44pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596496.0 | 513448.7 | 87913 | 1.64041666667 | 10030 |
| 009887 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:45pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596494.1 | 513450.0 | 87915 | 1.64041666667 | 9887 |
| 010406 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:46pm | Sensor | 1797-S0053-905-G-ACK | 6850.3 | 1596491.4 | 513451.2 | 87917 | 1.64041666667 | 10406 |
| 010331 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:46pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596489.7 | 513451.4 | 87918 | 1.64041666667 | 10331 |
| 0 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:48pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596486.6 | 513453.1 | 87921 | 1.64041666667 | 0 |
| 010035 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:48pm | Sensor | 1797-S0053-905-G-ACK | 6850.2 | 1596485.5 | 513454.4 | 87922 | 1.64041666667 | 10035 |
| 008997 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:50pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596483.1 | 513456.3 | 87925 | 1.64041666667 | 8997 |
| 009178 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:51pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596481.2 | 513457.7 | 87927 | 1.64041666667 | 9178 |
| 009393 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:52pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596479.3 | 513460.4 | 87929 | 1.64041666667 | 9393 |
| 009363 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:53pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596478.5 | 513462.0 | 87931 | 1.64041666667 | 9363 |
| 010344 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:54pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596476.3 | 513463.7 | 87933 | 1.64041666667 | 10344 |
| 009958 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:55pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596474.5 | 513465.1 | 87935 | 1.64041666667 | 9958 |
| 010207 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:56pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596472.4 | 513466.8 | 87937 | 1.64041666667 | 10207 |
| 010083 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:56pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596471.2 | 513468.1 | 87938 | 1.64041666667 | 10083 |
| 010194 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:58pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596469.7 | 513470.0 | 87941 | 1.64041666667 | 10194 |
| 010572 | 0 | GeoXH 6000 | 08/20/2015 | 01:18:59pm | Sensor | 1797-S0053-905-G-ACK | 6850.0 | 1596468.0 | 513471.7 | 87943 | 1.64041666667 | 10572 |
| 010724 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:00pm | Sensor | 1797-S0053-905-G-ACK | 6850.1 | 1596466.7 | 513473.1 | 87945 | 1.64041666667 | 10724 |
| 009910 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:01pm | Sensor | 1797-S0053-905-G-ACK | 6849.9 | 1596465.7 | 513473.0 | 87947 | 1.64041666667 | 9910 |
| 009999 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:02pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596465.4 | 513474.1 | 87949 | 1.64041666667 | 9999 |
| 010019 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:03pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596464.7 | 513474.3 | 87951 | 1.64041666667 | 10019 |
| 010256 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:04pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596464.7 | 513474.5 | 87953 | 1.64041666667 | 10256 |
| 008889 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:23pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596464.6 | 513477.4 | 87955 | 1.64041666667 | 8889 |
| 009372 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:24pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596464.2 | 513480.2 | 87957 | 1.64041666667 | 9372 |
| 009614 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:25pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596463.6 | 513482.4 | 87959 | 1.64041666667 | 9614 |
| 009645 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:26pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596462.8 | 513484.6 | 87961 | 1.64041666667 | 9645 |
| 008485 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:26pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596461.6 | 513486.8 | 87962 | 1.64041666667 | 8485 |
| 008785 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:28pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596461.0 | 513489.4 | 87965 | 1.64041666667 | 8785 |
| 008782 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:29pm | Sensor | 1797-S0053-905-G-ACK | 6849.4 | 1596460.3 | 513491.6 | 87967 | 1.64041666667 | 8782 |
| 009034 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:30pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596458.6 | 513494.3 | 87969 | 1.64041666667 | 9034 |
| 010752 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:31pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596457.4 | 513495.9 | 87971 | 1.64041666667 | 10752 |
| 010885 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:32pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596457.4 | 513498.6 | 87973 | 1.64041666667 | 10885 |
| 011613 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:33pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596456.7 | 513501.0 | 87975 | 1.64041666667 | 11613 |
| 010410 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:34pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596456.3 | 513503.9 | 87977 | 1.64041666667 | 10410 |
| 010655 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:34pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596456.2 | 513505.7 | 87978 | 1.64041666667 | 10655 |
| 010441 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:36pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596455.5 | 513508.6 | 87981 | 1.64041666667 | 10441 |
| 010485 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:37pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596454.9 | 513510.7 | 87983 | 1.64041666667 | 10485 |
| 010218 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:38pm | Sensor | 1797-S0053-905-G-ACK | 6848.3 | 1596453.9 | 513513.4 | 87985 | 1.64041666667 | 10218 |
| 010120 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:39pm | Sensor | 1797-S0053-905-G-ACK | 6847.2 | 1596454.0 | 513514.1 | 87987 | 1.64041666667 | 10120 |
| 009855 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:40pm | Sensor | 1797-S0053-905-G-ACK | 6846.3 | 1596454.1 | 513514.3 | 87989 | 1.64041666667 | 9855 |
| 009953 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:41pm | Sensor | 1797-S0053-905-G-ACK | 6840.0 | 1596454.5 | 513514.2 | 87991 | 1.64041666667 | 9953 |
| 010248 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:42pm | Sensor | 1797-S0053-905-G-ACK | 6840.2 | 1596454.4 | 513514.3 | 87993 | 1.64041666667 | 10248 |
| 009665 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:43pm | Sensor | 1797-S0053-905-G-ACK | 6840.3 | 1596454.3 | 513514.2 | 87995 | 1.64041666667 | 9665 |
| 009329 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:44pm | Sensor | 1797-S0053-905-G-ACK | 6840.4 | 1596454.3 | 513514.2 | 87997 | 1.64041666667 | 9329 |
| 010340 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:45pm | Sensor | 1797-S0053-905-G-ACK | 6840.4 | 1596454.3 | 513514.1 | 87999 | 1.64041666667 | 10340 |
| 009596 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:46pm | Sensor | 1797-S0053-905-G-ACK | 6840.5 | 1596454.3 | 513514.1 | 88001 | 1.64041666667 | 9596 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010130 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:47pm | Sensor | 1797-S0053-905-G-ACK | 6840.5 | 1596454.2 | 513514.1 | 88003 | 1.64041666667 | 10130 |
| 010453 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:48pm | Sensor | 1797-S0053-905-G-ACK | 6840.6 | 1596454.1 | 513514.1 | 88005 | 1.64041666667 | 10453 |
| 009892 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:48pm | Sensor | 1797-S0053-905-G-ACK | 6841.3 | 1596454.1 | 513514.1 | 88006 | 1.64041666667 | 9892 |
| 010192 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:50pm | Sensor | 1797-S0053-905-G-ACK | 6843.2 | 1596454.1 | 513512.7 | 88009 | 1.64041666667 | 10192 |
| 009700 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:51pm | Sensor | 1797-S0053-905-G-ACK | 6843.3 | 1596453.9 | 513512.5 | 88011 | 1.64041666667 | 9700 |
| 010639 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:52pm | Sensor | 1797-S0053-905-G-ACK | 6843.9 | 1596453.9 | 513514.7 | 88013 | 1.64041666667 | 10639 |
| 011129 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:53pm | Sensor | 1797-S0053-905-G-ACK | 6846.6 | 1596453.9 | 513516.7 | 88015 | 1.64041666667 | 11129 |
| 011062 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:54pm | Sensor | 1797-S0053-905-G-ACK | 6846.7 | 1596453.1 | 513518.0 | 88017 | 1.64041666667 | 11062 |
| 011352 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:55pm | Sensor | 1797-S0053-905-G-ACK | 6847.1 | 1596453.3 | 513518.9 | 88019 | 1.64041666667 | 11352 |
| 010451 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:56pm | Sensor | 1797-S0053-905-G-ACK | 6842.3 | 1596452.2 | 513520.8 | 88021 | 1.64041666667 | 10451 |
| 010123 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:56pm | Sensor | 1797-S0053-905-G-ACK | 6841.6 | 1596452.0 | 513521.2 | 88022 | 1.64041666667 | 10123 |
| 009324 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:58pm | Sensor | 1797-S0053-905-G-ACK | 6843.4 | 1596451.8 | 513520.8 | 88025 | 1.64041666667 | 9324 |
| 008890 | 0 | GeoXH 6000 | 08/20/2015 | 01:19:59pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596451.5 | 513519.9 | 88027 | 1.64041666667 | 8890 |
| 008863 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:00pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596451.9 | 513521.6 | 88029 | 1.64041666667 | 8863 |
| 008720 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:00pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596451.7 | 513523.4 | 88030 | 1.64041666667 | 8720 |
| 009277 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:02pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596450.9 | 513526.3 | 88033 | 1.64041666667 | 9277 |
| 009763 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:02pm | Sensor | 1797-S0053-905-G-ACK | 6849.6 | 1596451.7 | 513527.7 | 88034 | 1.64041666667 | 9763 |
| 010547 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:04pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596453.3 | 513529.3 | 88037 | 1.64041666667 | 10547 |
| 010290 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:04pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596453.6 | 513531.1 | 88038 | 1.64041666667 | 10290 |
| 009688 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:05pm | Sensor | 1797-S0053-905-G-ACK | 6849.5 | 1596454.8 | 513533.3 | 88040 | 1.64041666667 | 9688 |
| 009507 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:06pm | Sensor | 1797-S0053-905-G-ACK | 6849.8 | 1596455.5 | 513534.7 | 88042 | 1.64041666667 | 9507 |
| 009870 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:07pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596455.0 | 513535.7 | 88044 | 1.64041666667 | 9870 |
| 010037 | 0 | GeoXH 6000 | 08/20/2015 | 01:20:08pm | Sensor | 1797-S0053-905-G-ACK | 6849.7 | 1596454.9 | 513535.8 | 88046 | 1.64041666667 | 10037 |
| 015186 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:22am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596764.5 | 512482.9 | 80538 | 1.64041666667 | 15186 |
| 016216 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:22am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596764.5 | 512482.9 | 80539 | 1.64041666667 | 16216 |
| 015334 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:22am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596764.5 | 512482.9 | 80540 | 1.64041666667 | 15334 |
| 015383 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:23am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596764.3 | 512482.8 | 80542 | 1.64041666667 | 15383 |
| 015936 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:24am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596764.1 | 512482.5 | 80544 | 1.64041666667 | 15936 |
| 015174 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596764.1 | 512482.2 | 80546 | 1.64041666667 | 15174 |
| 015673 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:26am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596764.0 | 512482.0 | 80548 | 1.64041666667 | 15673 |
| 015168 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596764.1 | 512481.7 | 80550 | 1.64041666667 | 15168 |
| 015972 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:28am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596764.1 | 512481.6 | 80552 | 1.64041666667 | 15972 |
| 015003 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596764.2 | 512481.5 | 80554 | 1.64041666667 | 15003 |
| 015000 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596764.2 | 512481.4 | 80556 | 1.64041666667 | 15000 |
| 014520 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596764.4 | 512481.3 | 80558 | 1.64041666667 | 14520 |
| 014880 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596765.1 | 512484.0 | 80560 | 1.64041666667 | 14880 |
| 016290 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:33am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596765.1 | 512489.0 | 80563 | 1.64041666667 | 16290 |
| 015652 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:34am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596762.7 | 512483.6 | 80566 | 1.64041666667 | 15652 |
| 015673 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:35am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596763.3 | 512483.5 | 80568 | 1.64041666667 | 15673 |
| 015636 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:36am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596763.3 | 512483.7 | 80570 | 1.64041666667 | 15636 |
| 016534 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:37am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596762.8 | 512484.2 | 80572 | 1.64041666667 | 16534 |
| 015473 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:38am | Sensor | 1797-S0052-G-TJV.cor | 6847.3 | 1596762.4 | 512484.1 | 80575 | 1.64041666667 | 15473 |
| 014398 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:39am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596763.0 | 512483.8 | 80577 | 1.64041666667 | 14398 |
| 016619 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:40am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596763.7 | 512483.5 | 80580 | 1.64041666667 | 16619 |
| 015975 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:41am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596763.5 | 512483.7 | 80583 | 1.64041666667 | 15975 |
| 015003 | 0 | GeoXH 6000 | 08/20/2015 | 10:59:42am | Sensor | 1797-S0052-G-TJV.cor | 6847.5 | 1596762.9 | 512484.1 | 80588 | 1.64041666667 | 15003 |
| 014946 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596762.4 | 512485.3 | 80589 | 1.64041666667 | 14946 |
| 017206 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596762.4 | 512485.3 | 80591 | 1.64041666667 | 17206 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017201 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596762.4 | 512485.4 | 80593 | 1.64041666667 | 17201 |
| 017500 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596762.4 | 512485.4 | 80595 | 1.64041666667 | 17500 |
| 015415 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596762.4 | 512485.4 | 80597 | 1.64041666667 | 15415 |
| 015163 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596762.4 | 512485.3 | 80599 | 1.64041666667 | 15163 |
| 014651 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596762.4 | 512485.4 | 80601 | 1.64041666667 | 14651 |
| 014012 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596762.4 | 512485.3 | 80603 | 1.64041666667 | 14012 |
| 014093 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596762.2 | 512484.9 | 80605 | 1.64041666667 | 14093 |
| 015493 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596761.9 | 512483.8 | 80607 | 1.64041666667 | 15493 |
| 015933 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596761.8 | 512483.3 | 80609 | 1.64041666667 | 15933 |
| 016493 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:48am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596761.9 | 512483.3 | 80611 | 1.64041666667 | 16493 |
| 016213 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596762.3 | 512483.8 | 80613 | 1.64041666667 | 16213 |
| 014946 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596762.5 | 512484.1 | 80615 | 1.64041666667 | 14946 |
| 013808 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596762.7 | 512484.7 | 80617 | 1.64041666667 | 13808 |
| 015152 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596762.8 | 512484.6 | 80619 | 1.64041666667 | 15152 |
| 016238 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596762.6 | 512484.6 | 80621 | 1.64041666667 | 16238 |
| 016869 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596762.3 | 512484.4 | 80623 | 1.64041666667 | 16869 |
| 016487 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596761.2 | 512483.7 | 80625 | 1.64041666667 | 16487 |
| 016001 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:56am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596761.2 | 512483.5 | 80627 | 1.64041666667 | 16001 |
| 015430 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596761.1 | 512483.6 | 80629 | 1.64041666667 | 15430 |
| 014717 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596761.5 | 512484.1 | 80631 | 1.64041666667 | 14717 |
| 017299 | 0 | GeoXH 6000 | 08/20/2015 | 11:01:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596760.9 | 512483.3 | 80633 | 1.64041666667 | 17299 |
| 016234 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596759.4 | 512482.5 | 80635 | 1.64041666667 | 16234 |
| 015218 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596757.6 | 512481.0 | 80637 | 1.64041666667 | 15218 |
| 014364 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:02am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596755.9 | 512479.6 | 80639 | 1.64041666667 | 14364 |
| 013971 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:03am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596753.5 | 512477.7 | 80641 | 1.64041666667 | 13971 |
| 013752 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:04am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596751.8 | 512476.2 | 80643 | 1.64041666667 | 13752 |
| 014538 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:05am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596749.1 | 512474.1 | 80645 | 1.64041666667 | 14538 |
| 015454 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:06am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596747.2 | 512472.2 | 80647 | 1.64041666667 | 15454 |
| 014723 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:07am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596744.7 | 512469.8 | 80649 | 1.64041666667 | 14723 |
| 015231 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596742.3 | 512468.0 | 80651 | 1.64041666667 | 15231 |
| 015057 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596739.7 | 512465.9 | 80653 | 1.64041666667 | 15057 |
| 016814 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596737.2 | 512464.1 | 80655 | 1.64041666667 | 16814 |
| 015483 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596734.0 | 512463.0 | 80657 | 1.64041666667 | 15483 |
| 015000 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:12am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596731.5 | 512462.5 | 80659 | 1.64041666667 | 15000 |
| 016320 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:13am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596729.4 | 512462.0 | 80661 | 1.64041666667 | 16320 |
| 014250 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:14am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596727.8 | 512461.5 | 80663 | 1.64041666667 | 14250 |
| 014092 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:15am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596725.5 | 512460.4 | 80665 | 1.64041666667 | 14092 |
| 015253 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:16am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596723.8 | 512459.7 | 80667 | 1.64041666667 | 15253 |
| 015213 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:17am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596722.2 | 512458.7 | 80669 | 1.64041666667 | 15213 |
| 017333 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:18am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596720.3 | 512457.7 | 80671 | 1.64041666667 | 17333 |
| 015523 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596718.4 | 512456.0 | 80673 | 1.64041666667 | 15523 |
| 015431 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:20am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596716.0 | 512454.2 | 80675 | 1.64041666667 | 15431 |
| 014267 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:21am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596713.7 | 512452.6 | 80677 | 1.64041666667 | 14267 |
| 016196 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:22am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596712.1 | 512450.7 | 80679 | 1.64041666667 | 16196 |
| 016049 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:23am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596709.8 | 512448.5 | 80681 | 1.64041666667 | 16049 |
| 015472 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:24am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596708.0 | 512446.5 | 80683 | 1.64041666667 | 15472 |
| 013348 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596706.3 | 512444.2 | 80685 | 1.64041666667 | 13348 |
| 015487 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596704.2 | 512442.3 | 80687 | 1.64041666667 | 15487 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015091 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:27am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596701.8 | 512440.2 | 80689 | 1.64041666667 | 15091 |
| 016102 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:28am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596699.9 | 512438.6 | 80691 | 1.64041666667 | 16102 |
| 013025 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:29am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596697.5 | 512437.5 | 80693 | 1.64041666667 | 13025 |
| 013816 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:30am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596695.9 | 512436.3 | 80695 | 1.64041666667 | 13816 |
| 014764 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:31am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596693.2 | 512434.7 | 80697 | 1.64041666667 | 14764 |
| 015241 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:32am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596690.5 | 512433.3 | 80699 | 1.64041666667 | 15241 |
| 013680 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:33am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596688.6 | 512431.7 | 80701 | 1.64041666667 | 13680 |
| 015210 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:34am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596686.7 | 512430.2 | 80703 | 1.64041666667 | 15210 |
| 014152 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:35am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596684.4 | 512428.4 | 80705 | 1.64041666667 | 14152 |
| 016768 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:36am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596682.5 | 512426.4 | 80707 | 1.64041666667 | 16768 |
| 015622 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596680.7 | 512424.4 | 80709 | 1.64041666667 | 15622 |
| 016325 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:38am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596678.8 | 512422.7 | 80711 | 1.64041666667 | 16325 |
| 015091 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596676.5 | 512420.7 | 80713 | 1.64041666667 | 15091 |
| 016642 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596674.0 | 512419.4 | 80715 | 1.64041666667 | 16642 |
| 015740 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596671.5 | 512417.9 | 80717 | 1.64041666667 | 15740 |
| 016865 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596669.4 | 512416.1 | 80719 | 1.64041666667 | 16865 |
| 015166 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596666.7 | 512414.4 | 80721 | 1.64041666667 | 15166 |
| 015641 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596664.2 | 512413.2 | 80723 | 1.64041666667 | 15641 |
| 016720 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596661.8 | 512411.7 | 80725 | 1.64041666667 | 16720 |
| 015670 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596659.2 | 512410.3 | 80727 | 1.64041666667 | 15670 |
| 015197 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596656.6 | 512408.9 | 80729 | 1.64041666667 | 15197 |
| 015019 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596654.1 | 512407.3 | 80731 | 1.64041666667 | 15019 |
| 013984 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596652.0 | 512405.4 | 80733 | 1.64041666667 | 13984 |
| 015016 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:50am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596649.9 | 512403.3 | 80735 | 1.64041666667 | 15016 |
| 015004 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596648.2 | 512400.9 | 80737 | 1.64041666667 | 15004 |
| 015061 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596646.8 | 512398.4 | 80739 | 1.64041666667 | 15061 |
| 015435 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596644.5 | 512395.5 | 80741 | 1.64041666667 | 15435 |
| 015408 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596642.7 | 512393.4 | 80743 | 1.64041666667 | 15408 |
| 015702 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596640.6 | 512390.8 | 80745 | 1.64041666667 | 15702 |
| 014755 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596638.6 | 512388.7 | 80747 | 1.64041666667 | 14755 |
| 014759 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596636.6 | 512386.8 | 80749 | 1.64041666667 | 14759 |
| 013739 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596634.5 | 512385.1 | 80751 | 1.64041666667 | 13739 |
| 014565 | 0 | GeoXH 6000 | 08/20/2015 | 11:02:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596632.0 | 512383.9 | 80753 | 1.64041666667 | 14565 |
| 014651 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596629.9 | 512383.1 | 80755 | 1.64041666667 | 14651 |
| 015302 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596627.5 | 512381.7 | 80757 | 1.64041666667 | 15302 |
| 015495 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596625.1 | 512380.4 | 80759 | 1.64041666667 | 15495 |
| 014643 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596623.2 | 512378.4 | 80761 | 1.64041666667 | 14643 |
| 014161 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596621.9 | 512376.4 | 80763 | 1.64041666667 | 14161 |
| 015420 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596620.1 | 512374.7 | 80765 | 1.64041666667 | 15420 |
| 016215 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596618.6 | 512372.8 | 80767 | 1.64041666667 | 16215 |
| 014403 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596616.9 | 512371.0 | 80769 | 1.64041666667 | 14403 |
| 014131 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596615.9 | 512368.5 | 80771 | 1.64041666667 | 14131 |
| 016012 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596615.6 | 512366.0 | 80773 | 1.64041666667 | 16012 |
| 014683 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596615.2 | 512363.3 | 80775 | 1.64041666667 | 14683 |
| 015191 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596615.1 | 512360.3 | 80777 | 1.64041666667 | 15191 |
| 015827 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596614.8 | 512358.0 | 80779 | 1.64041666667 | 15827 |
| 014996 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596614.3 | 512355.0 | 80781 | 1.64041666667 | 14996 |
| 015029 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596614.0 | 512352.9 | 80783 | 1.64041666667 | 15029 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015397 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596613.0 | 512350.2 | 80785 | 1.64041666667 | 15397 |
| 015549 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596612.0 | 512348.8 | 80787 | 1.64041666667 | 15549 |
| 015257 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:17am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596611.7 | 512348.4 | 80789 | 1.64041666667 | 15257 |
| 014944 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596612.0 | 512348.5 | 80791 | 1.64041666667 | 14944 |
| 015256 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596612.2 | 512348.7 | 80793 | 1.64041666667 | 15256 |
| 015634 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596612.7 | 512349.2 | 80795 | 1.64041666667 | 15634 |
| 015638 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596613.1 | 512349.5 | 80797 | 1.64041666667 | 15638 |
| 016119 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596613.1 | 512349.5 | 80799 | 1.64041666667 | 16119 |
| 014380 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596613.2 | 512349.5 | 80801 | 1.64041666667 | 14380 |
| 013645 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596613.0 | 512349.0 | 80803 | 1.64041666667 | 13645 |
| 013641 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596612.1 | 512347.2 | 80805 | 1.64041666667 | 13641 |
| 014690 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596611.2 | 512345.1 | 80807 | 1.64041666667 | 14690 |
| 015432 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596609.4 | 512343.7 | 80809 | 1.64041666667 | 15432 |
| 014298 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596608.1 | 512342.3 | 80811 | 1.64041666667 | 14298 |
| 014194 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.9 | 80813 | 1.64041666667 | 14194 |
| 014768 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.9 | 80815 | 1.64041666667 | 14768 |
| 013652 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.9 | 80817 | 1.64041666667 | 13652 |
| 014183 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.9 | 80819 | 1.64041666667 | 14183 |
| 012215 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.8 | 80821 | 1.64041666667 | 12215 |
| 013374 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.1 | 512341.8 | 80823 | 1.64041666667 | 13374 |
| 013843 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.1 | 512341.8 | 80825 | 1.64041666667 | 13843 |
| 014681 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.9 | 80827 | 1.64041666667 | 14681 |
| 013780 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.1 | 512341.9 | 80829 | 1.64041666667 | 13780 |
| 014665 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.8 | 80831 | 1.64041666667 | 14665 |
| 015156 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.8 | 80833 | 1.64041666667 | 15156 |
| 014289 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.0 | 512341.8 | 80835 | 1.64041666667 | 14289 |
| 013142 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596607.0 | 512341.8 | 80837 | 1.64041666667 | 13142 |
| 012975 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596607.0 | 512341.8 | 80839 | 1.64041666667 | 12975 |
| 013503 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596607.0 | 512341.8 | 80841 | 1.64041666667 | 13503 |
| 013786 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596606.9 | 512341.8 | 80843 | 1.64041666667 | 13786 |
| 014246 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596607.0 | 512341.7 | 80845 | 1.64041666667 | 14246 |
| 013551 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596606.9 | 512341.7 | 80847 | 1.64041666667 | 13551 |
| 015148 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596606.7 | 512341.4 | 80849 | 1.64041666667 | 15148 |
| 014407 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596606.8 | 512341.2 | 80851 | 1.64041666667 | 14407 |
| 015631 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596607.1 | 512341.2 | 80853 | 1.64041666667 | 15631 |
| 014047 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:50am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596606.9 | 512340.3 | 80855 | 1.64041666667 | 14047 |
| 014012 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596605.6 | 512338.0 | 80857 | 1.64041666667 | 14012 |
| 013463 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596604.4 | 512336.2 | 80859 | 1.64041666667 | 13463 |
| 013115 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.8 | 512333.7 | 80861 | 1.64041666667 | 13115 |
| 013899 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.4 | 512332.2 | 80863 | 1.64041666667 | 13899 |
| 013074 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596600.7 | 512330.6 | 80865 | 1.64041666667 | 13074 |
| 012688 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596600.3 | 512330.3 | 80867 | 1.64041666667 | 12688 |
| 014602 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596601.0 | 512329.0 | 80869 | 1.64041666667 | 14602 |
| 014720 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596601.9 | 512326.9 | 80871 | 1.64041666667 | 14720 |
| 014120 | 0 | GeoXH 6000 | 08/20/2015 | 11:03:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.9 | 512325.1 | 80873 | 1.64041666667 | 14120 |
| 013640 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596603.3 | 512323.4 | 80875 | 1.64041666667 | 13640 |
| 013640 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596603.6 | 512322.8 | 80877 | 1.64041666667 | 13640 |
| 012500 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596603.4 | 512322.8 | 80879 | 1.64041666667 | 12500 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014795 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596603.3 | 512322.9 | 80881 | 1.64041666667 | 14795 |
| 012878 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596603.3 | 512323.0 | 80883 | 1.64041666667 | 12878 |
| 012879 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596603.4 | 512322.9 | 80885 | 1.64041666667 | 12879 |
| 014830 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596603.8 | 512322.8 | 80887 | 1.64041666667 | 14830 |
| 014417 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596603.8 | 512322.3 | 80889 | 1.64041666667 | 14417 |
| 013534 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596603.0 | 512321.4 | 80891 | 1.64041666667 | 13534 |
| 013043 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596603.1 | 512320.4 | 80893 | 1.64041666667 | 13043 |
| 013761 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.6 | 512320.0 | 80895 | 1.64041666667 | 13761 |
| 013370 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596602.7 | 512319.7 | 80897 | 1.64041666667 | 13370 |
| 013602 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.8 | 512319.6 | 80899 | 1.64041666667 | 13602 |
| 014350 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596603.1 | 512318.9 | 80901 | 1.64041666667 | 14350 |
| 013637 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596602.2 | 512317.0 | 80903 | 1.64041666667 | 13637 |
| 012649 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596602.0 | 512314.9 | 80905 | 1.64041666667 | 12649 |
| 013032 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596601.8 | 512313.9 | 80907 | 1.64041666667 | 13032 |
| 013698 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596602.0 | 512313.8 | 80909 | 1.64041666667 | 13698 |
| 014074 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596602.0 | 512313.8 | 80911 | 1.64041666667 | 14074 |
| 015698 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596601.9 | 512313.7 | 80913 | 1.64041666667 | 15698 |
| 013794 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.2 | 512313.5 | 80915 | 1.64041666667 | 13794 |
| 014008 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.5 | 512313.4 | 80917 | 1.64041666667 | 14008 |
| 013582 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.3 | 512313.6 | 80919 | 1.64041666667 | 13582 |
| 013985 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.2 | 512313.6 | 80921 | 1.64041666667 | 13985 |
| 013486 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596602.2 | 512313.7 | 80923 | 1.64041666667 | 13486 |
| 013571 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.7 | 512313.6 | 80925 | 1.64041666667 | 13571 |
| 013293 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596600.8 | 512313.5 | 80927 | 1.64041666667 | 13293 |
| 012743 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596600.9 | 512314.1 | 80929 | 1.64041666667 | 12743 |
| 013325 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596600.8 | 512314.1 | 80931 | 1.64041666667 | 13325 |
| 014881 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596600.7 | 512315.5 | 80933 | 1.64041666667 | 14881 |
| 014370 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.5 | 512316.4 | 80935 | 1.64041666667 | 14370 |
| 014242 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.4 | 512316.7 | 80937 | 1.64041666667 | 14242 |
| 015680 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.4 | 512316.7 | 80939 | 1.64041666667 | 15680 |
| 014000 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.4 | 512316.7 | 80941 | 1.64041666667 | 14000 |
| 013520 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.4 | 512316.7 | 80943 | 1.64041666667 | 13520 |
| 013220 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.3 | 512316.7 | 80945 | 1.64041666667 | 13220 |
| 013505 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.3 | 512316.8 | 80947 | 1.64041666667 | 13505 |
| 013276 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.4 | 512316.7 | 80949 | 1.64041666667 | 13276 |
| 014269 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.4 | 512316.7 | 80951 | 1.64041666667 | 14269 |
| 012417 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.3 | 512316.8 | 80953 | 1.64041666667 | 12417 |
| 013634 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.5 | 512316.8 | 80955 | 1.64041666667 | 13634 |
| 013608 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596601.6 | 512317.0 | 80957 | 1.64041666667 | 13608 |
| 014322 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596601.6 | 512317.6 | 80959 | 1.64041666667 | 14322 |
| 013660 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596600.7 | 512318.3 | 80961 | 1.64041666667 | 13660 |
| 014785 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596599.4 | 512318.2 | 80963 | 1.64041666667 | 14785 |
| 013776 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596597.6 | 512317.5 | 80965 | 1.64041666667 | 13776 |
| 012384 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596595.7 | 512316.2 | 80967 | 1.64041666667 | 12384 |
| 013026 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596594.4 | 512315.1 | 80969 | 1.64041666667 | 13026 |
| 014236 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596593.0 | 512314.3 | 80971 | 1.64041666667 | 14236 |
| 012619 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596591.2 | 512312.9 | 80973 | 1.64041666667 | 12619 |
| 012784 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:50am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596589.9 | 512312.0 | 80975 | 1.64041666667 | 12784 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014506 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596588.2 | 512310.4 | 80977 | 1.64041666667 | 14506 |
| 013916 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596587.1 | 512309.2 | 80979 | 1.64041666667 | 13916 |
| 013949 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596585.2 | 512308.0 | 80981 | 1.64041666667 | 13949 |
| 014287 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596583.8 | 512307.2 | 80983 | 1.64041666667 | 14287 |
| 014701 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596581.8 | 512305.8 | 80985 | 1.64041666667 | 14701 |
| 014355 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596580.4 | 512304.6 | 80987 | 1.64041666667 | 14355 |
| 015468 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.3 | 512303.0 | 80989 | 1.64041666667 | 15468 |
| 012837 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596577.0 | 512301.7 | 80991 | 1.64041666667 | 12837 |
| 013859 | 0 | GeoXH 6000 | 08/20/2015 | 11:04:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596574.7 | 512299.8 | 80993 | 1.64041666667 | 13859 |
| 012975 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596572.8 | 512298.5 | 80995 | 1.64041666667 | 12975 |
| 015393 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596570.9 | 512296.8 | 80997 | 1.64041666667 | 15393 |
| 015248 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596569.4 | 512296.0 | 80999 | 1.64041666667 | 15248 |
| 014462 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596567.2 | 512294.5 | 81001 | 1.64041666667 | 14462 |
| 015615 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596565.1 | 512294.0 | 81003 | 1.64041666667 | 15615 |
| 016143 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596562.9 | 512292.8 | 81005 | 1.64041666667 | 16143 |
| 015706 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596561.7 | 512293.0 | 81007 | 1.64041666667 | 15706 |
| 015776 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596561.6 | 512292.7 | 81009 | 1.64041666667 | 15776 |
| 014774 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596561.6 | 512292.6 | 81011 | 1.64041666667 | 14774 |
| 014553 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596561.3 | 512292.6 | 81013 | 1.64041666667 | 14553 |
| 015458 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596560.2 | 512292.8 | 81015 | 1.64041666667 | 15458 |
| 014814 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596558.0 | 512292.6 | 81017 | 1.64041666667 | 14814 |
| 015823 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596555.9 | 512292.4 | 81019 | 1.64041666667 | 15823 |
| 017606 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:13am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596553.2 | 512291.2 | 81021 | 1.64041666667 | 17606 |
| 016371 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:14am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596551.1 | 512290.8 | 81023 | 1.64041666667 | 16371 |
| 016182 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:15am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596548.6 | 512290.2 | 81025 | 1.64041666667 | 16182 |
| 014455 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:16am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596546.5 | 512290.1 | 81027 | 1.64041666667 | 14455 |
| 013694 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596544.4 | 512289.3 | 81029 | 1.64041666667 | 13694 |
| 013623 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596542.2 | 512288.6 | 81031 | 1.64041666667 | 13623 |
| 012735 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596539.8 | 512287.6 | 81033 | 1.64041666667 | 12735 |
| 013323 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:20am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596537.5 | 512286.8 | 81035 | 1.64041666667 | 13323 |
| 013621 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:21am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596534.9 | 512286.3 | 81037 | 1.64041666667 | 13621 |
| 012825 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:22am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596532.7 | 512285.4 | 81039 | 1.64041666667 | 12825 |
| 015536 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:23am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596530.0 | 512285.2 | 81041 | 1.64041666667 | 15536 |
| 014504 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:24am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596528.2 | 512284.9 | 81043 | 1.64041666667 | 14504 |
| 014576 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596526.1 | 512285.1 | 81045 | 1.64041666667 | 14576 |
| 014654 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:26am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596524.5 | 512284.9 | 81047 | 1.64041666667 | 14654 |
| 014373 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596522.7 | 512284.1 | 81049 | 1.64041666667 | 14373 |
| 012863 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:28am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596520.6 | 512283.8 | 81051 | 1.64041666667 | 12863 |
| 013175 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596519.0 | 512282.9 | 81053 | 1.64041666667 | 13175 |
| 014334 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:30am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596518.0 | 512283.5 | 81055 | 1.64041666667 | 14334 |
| 015043 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:31am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596518.2 | 512283.2 | 81057 | 1.64041666667 | 15043 |
| 014711 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:32am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596517.7 | 512282.9 | 81059 | 1.64041666667 | 14711 |
| 013667 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596515.0 | 512282.6 | 81061 | 1.64041666667 | 13667 |
| 012956 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596513.4 | 512281.9 | 81063 | 1.64041666667 | 12956 |
| 012509 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596511.5 | 512282.1 | 81065 | 1.64041666667 | 12509 |
| 012607 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596511.4 | 512281.6 | 81067 | 1.64041666667 | 12607 |
| 012541 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596511.2 | 512281.3 | 81069 | 1.64041666667 | 12541 |
| 013785 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596510.4 | 512281.2 | 81071 | 1.64041666667 | 13785 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013766 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596509.9 | 512281.1 | 81073 | 1.64041666667 | 13766 |
| 013221 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596510.0 | 512280.5 | 81075 | 1.64041666667 | 13221 |
| 012125 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:41am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596509.9 | 512279.6 | 81077 | 1.64041666667 | 12125 |
| 011701 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:42am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596508.6 | 512279.8 | 81079 | 1.64041666667 | 11701 |
| 013335 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596507.6 | 512279.2 | 81081 | 1.64041666667 | 13335 |
| 013893 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596506.6 | 512278.2 | 81083 | 1.64041666667 | 13893 |
| 014123 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596504.6 | 512277.2 | 81085 | 1.64041666667 | 14123 |
| 013011 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596504.8 | 512275.8 | 81087 | 1.64041666667 | 13011 |
| 012582 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596504.4 | 512275.4 | 81089 | 1.64041666667 | 12582 |
| 013555 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596503.4 | 512274.9 | 81091 | 1.64041666667 | 13555 |
| 013499 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596502.6 | 512273.3 | 81093 | 1.64041666667 | 13499 |
| 014204 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:50am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596500.6 | 512272.2 | 81095 | 1.64041666667 | 14204 |
| 013811 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:51am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596499.5 | 512270.6 | 81097 | 1.64041666667 | 13811 |
| 012722 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:52am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596497.4 | 512269.6 | 81099 | 1.64041666667 | 12722 |
| 011970 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:53am | Sensor | 1797-S0052-G-TJV.cor | 6847.5 | 1596496.0 | 512267.6 | 81101 | 1.64041666667 | 11970 |
| 012682 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:54am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596495.0 | 512266.7 | 81103 | 1.64041666667 | 12682 |
| 012980 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:55am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596494.7 | 512266.2 | 81105 | 1.64041666667 | 12980 |
| 013655 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:56am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596494.7 | 512266.3 | 81107 | 1.64041666667 | 13655 |
| 016733 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:57am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596494.7 | 512266.3 | 81109 | 1.64041666667 | 16733 |
| 013183 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:58am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596494.8 | 512266.4 | 81111 | 1.64041666667 | 13183 |
| 012146 | 0 | GeoXH 6000 | 08/20/2015 | 11:05:59am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596494.9 | 512266.4 | 81113 | 1.64041666667 | 12146 |
| 012096 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:00am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596495.1 | 512266.3 | 81115 | 1.64041666667 | 12096 |
| 011874 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:01am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596495.1 | 512266.3 | 81117 | 1.64041666667 | 11874 |
| 011368 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:02am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596495.7 | 512265.7 | 81119 | 1.64041666667 | 11368 |
| 012142 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:03am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596497.0 | 512263.4 | 81121 | 1.64041666667 | 12142 |
| 013115 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:04am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596498.3 | 512262.8 | 81123 | 1.64041666667 | 13115 |
| 012458 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:05am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596498.6 | 512262.6 | 81125 | 1.64041666667 | 12458 |
| 013314 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:06am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596498.9 | 512262.6 | 81127 | 1.64041666667 | 13314 |
| 012208 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:07am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596498.9 | 512262.3 | 81129 | 1.64041666667 | 12208 |
| 014152 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:08am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596500.0 | 512260.3 | 81131 | 1.64041666667 | 14152 |
| 014038 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:09am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596501.4 | 512258.9 | 81133 | 1.64041666667 | 14038 |
| 014219 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:10am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596501.6 | 512258.4 | 81135 | 1.64041666667 | 14219 |
| 013395 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:11am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596501.7 | 512258.4 | 81137 | 1.64041666667 | 13395 |
| 012258 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:12am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596501.6 | 512258.4 | 81139 | 1.64041666667 | 12258 |
| 011794 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:13am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596501.5 | 512258.3 | 81141 | 1.64041666667 | 11794 |
| 012608 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:14am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596501.5 | 512258.5 | 81143 | 1.64041666667 | 12608 |
| 013502 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:15am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596501.4 | 512258.5 | 81145 | 1.64041666667 | 13502 |
| 013905 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:16am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596501.5 | 512258.4 | 81147 | 1.64041666667 | 13905 |
| 013736 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:17am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596501.5 | 512258.1 | 81149 | 1.64041666667 | 13736 |
| 012194 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:18am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596501.6 | 512257.8 | 81151 | 1.64041666667 | 12194 |
| 013128 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:19am | Sensor | 1797-S0052-G-TJV.cor | 6847.1 | 1596502.6 | 512256.6 | 81153 | 1.64041666667 | 13128 |
| 013482 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:20am | Sensor | 1797-S0052-G-TJV.cor | 6847.1 | 1596502.5 | 512256.9 | 81155 | 1.64041666667 | 13482 |
| 012820 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:21am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596501.4 | 512258.4 | 81157 | 1.64041666667 | 12820 |
| 013135 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:22am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596501.5 | 512258.7 | 81159 | 1.64041666667 | 13135 |
| 014323 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:23am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596501.9 | 512258.8 | 81161 | 1.64041666667 | 14323 |
| 012431 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:24am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596503.5 | 512259.0 | 81163 | 1.64041666667 | 12431 |
| 013667 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:25am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596505.7 | 512260.3 | 81165 | 1.64041666667 | 13667 |
| 012596 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:26am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596507.7 | 512260.6 | 81167 | 1.64041666667 | 12596 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012809 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596508.2 | 512260.8 | 81169 | 1.64041666667 | 12809 |
| 013222 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:28am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596508.6 | 512260.9 | 81171 | 1.64041666667 | 13222 |
| 012245 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596507.4 | 512260.2 | 81173 | 1.64041666667 | 12245 |
| 013171 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:30am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596506.5 | 512260.7 | 81175 | 1.64041666667 | 13171 |
| 012742 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:31am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596503.9 | 512261.8 | 81177 | 1.64041666667 | 12742 |
| 013115 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:32am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596501.8 | 512262.4 | 81179 | 1.64041666667 | 13115 |
| 013779 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:33am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596500.0 | 512262.4 | 81181 | 1.64041666667 | 13779 |
| 012384 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:34am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596498.5 | 512262.4 | 81183 | 1.64041666667 | 12384 |
| 012216 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:35am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596496.8 | 512262.3 | 81185 | 1.64041666667 | 12216 |
| 011994 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:36am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596496.7 | 512261.5 | 81187 | 1.64041666667 | 11994 |
| 012688 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:37am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596496.8 | 512261.7 | 81189 | 1.64041666667 | 12688 |
| 012292 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:38am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596497.4 | 512262.1 | 81191 | 1.64041666667 | 12292 |
| 012133 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:39am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596499.2 | 512261.9 | 81193 | 1.64041666667 | 12133 |
| 013113 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:40am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596500.6 | 512263.1 | 81195 | 1.64041666667 | 13113 |
| 013478 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:41am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596503.0 | 512263.8 | 81197 | 1.64041666667 | 13478 |
| 013659 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:42am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596503.9 | 512264.7 | 81199 | 1.64041666667 | 13659 |
| 012955 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596505.7 | 512265.7 | 81201 | 1.64041666667 | 12955 |
| 013168 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596507.3 | 512267.2 | 81203 | 1.64041666667 | 13168 |
| 013192 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:45am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596509.4 | 512267.8 | 81205 | 1.64041666667 | 13192 |
| 012448 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596510.0 | 512267.8 | 81207 | 1.64041666667 | 12448 |
| 012532 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596509.7 | 512268.0 | 81209 | 1.64041666667 | 12532 |
| 013963 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596509.6 | 512268.2 | 81211 | 1.64041666667 | 13963 |
| 012910 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596511.4 | 512268.3 | 81213 | 1.64041666667 | 12910 |
| 012437 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.6 | 512269.3 | 81215 | 1.64041666667 | 12437 |
| 012229 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:51am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596514.6 | 512270.6 | 81217 | 1.64041666667 | 12229 |
| 013497 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:52am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596517.1 | 512272.0 | 81219 | 1.64041666667 | 13497 |
| 012434 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596519.9 | 512272.8 | 81221 | 1.64041666667 | 12434 |
| 013278 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:54am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596522.3 | 512273.8 | 81223 | 1.64041666667 | 13278 |
| 014359 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596524.7 | 512273.7 | 81225 | 1.64041666667 | 14359 |
| 011959 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:56am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596526.4 | 512274.8 | 81227 | 1.64041666667 | 11959 |
| 011780 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596528.6 | 512275.4 | 81229 | 1.64041666667 | 11780 |
| 012785 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:58am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596529.6 | 512276.8 | 81231 | 1.64041666667 | 12785 |
| 014326 | 0 | GeoXH 6000 | 08/20/2015 | 11:06:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596531.2 | 512277.5 | 81233 | 1.64041666667 | 14326 |
| 013811 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:00am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596531.6 | 512278.7 | 81235 | 1.64041666667 | 13811 |
| 014403 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596532.5 | 512280.5 | 81237 | 1.64041666667 | 14403 |
| 013470 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:02am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596534.3 | 512281.6 | 81239 | 1.64041666667 | 13470 |
| 013507 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596536.6 | 512282.6 | 81241 | 1.64041666667 | 13507 |
| 013533 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596539.4 | 512283.7 | 81243 | 1.64041666667 | 13533 |
| 014861 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596540.1 | 512284.1 | 81245 | 1.64041666667 | 14861 |
| 014665 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596540.4 | 512284.4 | 81246 | 1.64041666667 | 14665 |
| 015096 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596542.2 | 512284.8 | 81249 | 1.64041666667 | 15096 |
| 012744 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596544.1 | 512285.3 | 81251 | 1.64041666667 | 12744 |
| 014586 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596546.0 | 512285.7 | 81253 | 1.64041666667 | 14586 |
| 013156 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:10am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596549.1 | 512286.9 | 81255 | 1.64041666667 | 13156 |
| 015439 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596551.9 | 512287.5 | 81257 | 1.64041666667 | 15439 |
| 014299 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596554.0 | 512288.8 | 81259 | 1.64041666667 | 14299 |
| 014765 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596557.1 | 512289.8 | 81261 | 1.64041666667 | 14765 |
| 015121 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596559.1 | 512291.0 | 81263 | 1.64041666667 | 15121 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015030 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596562.1 | 512292.1 | 81265 | 1.64041666667 | 15030 |
| 013477 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596564.2 | 512293.3 | 81267 | 1.64041666667 | 13477 |
| 013449 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596566.9 | 512295.2 | 81269 | 1.64041666667 | 13449 |
| 012302 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596569.1 | 512296.2 | 81271 | 1.64041666667 | 12302 |
| 013935 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596571.7 | 512297.6 | 81273 | 1.64041666667 | 13935 |
| 013923 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596573.9 | 512297.9 | 81275 | 1.64041666667 | 13923 |
| 014641 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596576.3 | 512298.9 | 81277 | 1.64041666667 | 14641 |
| 014160 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596578.6 | 512299.4 | 81279 | 1.64041666667 | 14160 |
| 013380 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596581.3 | 512300.5 | 81281 | 1.64041666667 | 13380 |
| 014835 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596583.6 | 512300.9 | 81283 | 1.64041666667 | 14835 |
| 013728 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596585.9 | 512302.0 | 81285 | 1.64041666667 | 13728 |
| 013692 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596588.4 | 512302.6 | 81287 | 1.64041666667 | 13692 |
| 014583 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596590.6 | 512303.9 | 81289 | 1.64041666667 | 14583 |
| 013425 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596592.8 | 512305.4 | 81291 | 1.64041666667 | 13425 |
| 014396 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596595.1 | 512306.7 | 81293 | 1.64041666667 | 14396 |
| 013619 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596597.2 | 512308.2 | 81295 | 1.64041666667 | 13619 |
| 015015 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596599.7 | 512309.3 | 81297 | 1.64041666667 | 15015 |
| 013027 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596600.6 | 512310.3 | 81299 | 1.64041666667 | 13027 |
| 012698 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596601.1 | 512310.5 | 81301 | 1.64041666667 | 12698 |
| 014664 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.0 | 512310.8 | 81303 | 1.64041666667 | 14664 |
| 013566 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.6 | 512311.3 | 81305 | 1.64041666667 | 13566 |
| 012931 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596602.9 | 512312.0 | 81307 | 1.64041666667 | 12931 |
| 013882 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.5 | 512312.1 | 81309 | 1.64041666667 | 13882 |
| 013700 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596601.9 | 512311.7 | 81311 | 1.64041666667 | 13700 |
| 013985 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596603.7 | 512310.3 | 81313 | 1.64041666667 | 13985 |
| 013426 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596605.2 | 512309.0 | 81315 | 1.64041666667 | 13426 |
| 014096 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596605.8 | 512307.8 | 81317 | 1.64041666667 | 14096 |
| 013124 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:42am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596606.2 | 512307.4 | 81319 | 1.64041666667 | 13124 |
| 014321 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:43am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596608.3 | 512306.3 | 81321 | 1.64041666667 | 14321 |
| 013030 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:44am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596609.4 | 512304.5 | 81323 | 1.64041666667 | 13030 |
| 012797 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596611.0 | 512303.2 | 81325 | 1.64041666667 | 12797 |
| 013579 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596612.6 | 512302.2 | 81327 | 1.64041666667 | 13579 |
| 012874 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596612.8 | 512302.0 | 81329 | 1.64041666667 | 12874 |
| 012908 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596612.4 | 512302.1 | 81331 | 1.64041666667 | 12908 |
| 012197 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:49am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596610.0 | 512302.7 | 81333 | 1.64041666667 | 12197 |
| 013039 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:50am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596609.7 | 512303.8 | 81335 | 1.64041666667 | 13039 |
| 014059 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:51am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596609.2 | 512306.1 | 81337 | 1.64041666667 | 14059 |
| 014915 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:52am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596608.8 | 512307.8 | 81339 | 1.64041666667 | 14915 |
| 014768 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:53am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596606.9 | 512308.1 | 81341 | 1.64041666667 | 14768 |
| 014372 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:54am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596604.8 | 512307.6 | 81343 | 1.64041666667 | 14372 |
| 013403 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:55am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596602.0 | 512306.8 | 81345 | 1.64041666667 | 13403 |
| 013100 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596600.1 | 512305.5 | 81347 | 1.64041666667 | 13100 |
| 013865 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596597.0 | 512304.6 | 81349 | 1.64041666667 | 13865 |
| 013726 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596595.2 | 512303.6 | 81351 | 1.64041666667 | 13726 |
| 013031 | 0 | GeoXH 6000 | 08/20/2015 | 11:07:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596592.2 | 512302.6 | 81353 | 1.64041666667 | 13031 |
| 014838 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596590.2 | 512301.5 | 81355 | 1.64041666667 | 14838 |
| 015199 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596587.0 | 512300.0 | 81357 | 1.64041666667 | 15199 |
| 014269 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596584.6 | 512298.9 | 81359 | 1.64041666667 | 14269 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013347 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596581.6 | 512297.1 | 81361 | 1.64041666667 | 13347 |
| 015577 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596579.3 | 512295.9 | 81363 | 1.64041666667 | 15577 |
| 013794 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596576.8 | 512294.1 | 81365 | 1.64041666667 | 13794 |
| 015688 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596574.2 | 512293.3 | 81367 | 1.64041666667 | 15688 |
| 017422 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596571.9 | 512291.8 | 81369 | 1.64041666667 | 17422 |
| 016505 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596569.3 | 512291.0 | 81371 | 1.64041666667 | 16505 |
| 016966 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596566.9 | 512289.4 | 81373 | 1.64041666667 | 16966 |
| 015971 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596564.1 | 512288.0 | 81375 | 1.64041666667 | 15971 |
| 014883 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596561.5 | 512286.5 | 81377 | 1.64041666667 | 14883 |
| 014340 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596559.2 | 512285.0 | 81379 | 1.64041666667 | 14340 |
| 015405 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596556.8 | 512283.9 | 81381 | 1.64041666667 | 15405 |
| 014861 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596554.6 | 512282.5 | 81383 | 1.64041666667 | 14861 |
| 013825 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596552.3 | 512282.2 | 81385 | 1.64041666667 | 13825 |
| 014376 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596550.1 | 512281.2 | 81387 | 1.64041666667 | 14376 |
| 014454 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596547.6 | 512280.8 | 81389 | 1.64041666667 | 14454 |
| 014863 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596546.3 | 512280.0 | 81391 | 1.64041666667 | 14863 |
| 013136 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596544.8 | 512280.3 | 81393 | 1.64041666667 | 13136 |
| 013844 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596544.8 | 512279.6 | 81395 | 1.64041666667 | 13844 |
| 013571 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596544.6 | 512278.7 | 81397 | 1.64041666667 | 13571 |
| 013832 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596544.3 | 512278.8 | 81399 | 1.64041666667 | 13832 |
| 013268 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:23am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596544.2 | 512278.5 | 81401 | 1.64041666667 | 13268 |
| 013097 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:24am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596543.6 | 512278.2 | 81403 | 1.64041666667 | 13097 |
| 015364 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596543.0 | 512276.6 | 81405 | 1.64041666667 | 15364 |
| 014641 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:26am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596543.0 | 512274.4 | 81407 | 1.64041666667 | 14641 |
| 014250 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596540.6 | 512272.7 | 81409 | 1.64041666667 | 14250 |
| 012832 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:28am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596538.5 | 512271.5 | 81411 | 1.64041666667 | 12832 |
| 012568 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596536.2 | 512271.7 | 81413 | 1.64041666667 | 12568 |
| 012052 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:30am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596534.4 | 512271.5 | 81415 | 1.64041666667 | 12052 |
| 011713 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:31am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596531.9 | 512272.1 | 81417 | 1.64041666667 | 11713 |
| 012198 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:32am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596530.1 | 512271.4 | 81419 | 1.64041666667 | 12198 |
| 012559 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:33am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596527.7 | 512271.6 | 81421 | 1.64041666667 | 12559 |
| 013519 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:34am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596526.0 | 512270.4 | 81423 | 1.64041666667 | 13519 |
| 012380 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:35am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596523.4 | 512269.9 | 81425 | 1.64041666667 | 12380 |
| 012575 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:36am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596521.8 | 512268.9 | 81427 | 1.64041666667 | 12575 |
| 011393 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:37am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596520.3 | 512268.2 | 81429 | 1.64041666667 | 11393 |
| 013138 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:38am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596518.9 | 512266.8 | 81431 | 1.64041666667 | 13138 |
| 012464 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:39am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596517.5 | 512266.4 | 81433 | 1.64041666667 | 12464 |
| 012386 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:40am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596517.5 | 512265.2 | 81435 | 1.64041666667 | 12386 |
| 012156 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:41am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596517.8 | 512265.3 | 81437 | 1.64041666667 | 12156 |
| 012159 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:42am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596518.0 | 512264.8 | 81439 | 1.64041666667 | 12159 |
| 012519 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596517.0 | 512264.8 | 81441 | 1.64041666667 | 12519 |
| 012970 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596515.8 | 512264.2 | 81443 | 1.64041666667 | 12970 |
| 013082 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596515.3 | 512263.0 | 81445 | 1.64041666667 | 13082 |
| 011850 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596513.5 | 512261.6 | 81447 | 1.64041666667 | 11850 |
| 012202 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.2 | 512261.2 | 81449 | 1.64041666667 | 12202 |
| 012530 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.5 | 512261.2 | 81451 | 1.64041666667 | 12530 |
| 012792 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.7 | 512260.9 | 81453 | 1.64041666667 | 12792 |
| 012858 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596513.1 | 512258.3 | 81455 | 1.64041666667 | 12858 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012214 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:51am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596514.5 | 512256.3 | 81457 | 1.64041666667 | 12214 |
| 014183 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:52am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596516.5 | 512254.8 | 81459 | 1.64041666667 | 14183 |
| 014376 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596518.0 | 512253.2 | 81461 | 1.64041666667 | 14376 |
| 013584 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:54am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596519.5 | 512253.3 | 81463 | 1.64041666667 | 13584 |
| 012846 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596520.1 | 512253.0 | 81465 | 1.64041666667 | 12846 |
| 012811 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:56am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596520.0 | 512252.9 | 81467 | 1.64041666667 | 12811 |
| 013102 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596519.4 | 512252.6 | 81469 | 1.64041666667 | 13102 |
| 011405 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:58am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596518.6 | 512253.3 | 81471 | 1.64041666667 | 11405 |
| 012601 | 0 | GeoXH 6000 | 08/20/2015 | 11:08:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596516.4 | 512254.8 | 81473 | 1.64041666667 | 12601 |
| 013350 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:00am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596513.7 | 512255.8 | 81475 | 1.64041666667 | 13350 |
| 012097 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.3 | 512256.0 | 81477 | 1.64041666667 | 12097 |
| 012714 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:02am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.3 | 512255.9 | 81479 | 1.64041666667 | 12714 |
| 014548 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.4 | 512255.8 | 81481 | 1.64041666667 | 14548 |
| 014917 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:04am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.5 | 512255.6 | 81483 | 1.64041666667 | 14917 |
| 013809 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:05am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.5 | 512255.6 | 81485 | 1.64041666667 | 13809 |
| 013262 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:06am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596512.6 | 512255.5 | 81487 | 1.64041666667 | 13262 |
| 013185 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:07am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596512.5 | 512255.5 | 81489 | 1.64041666667 | 13185 |
| 012866 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:08am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596512.3 | 512255.5 | 81491 | 1.64041666667 | 12866 |
| 012366 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596510.7 | 512256.5 | 81493 | 1.64041666667 | 12366 |
| 013711 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:10am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596508.2 | 512256.7 | 81495 | 1.64041666667 | 13711 |
| 013627 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:11am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596505.6 | 512257.0 | 81497 | 1.64041666667 | 13627 |
| 012407 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:12am | Sensor | 1797-S0052-G-TJV.cor | 6847.5 | 1596503.0 | 512256.5 | 81499 | 1.64041666667 | 12407 |
| 011591 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:13am | Sensor | 1797-S0052-G-TJV.cor | 6847.5 | 1596502.7 | 512256.2 | 81501 | 1.64041666667 | 11591 |
| 012348 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:14am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596504.2 | 512255.5 | 81503 | 1.64041666667 | 12348 |
| 012957 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:15am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596505.4 | 512253.4 | 81505 | 1.64041666667 | 12957 |
| 012689 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:16am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596505.8 | 512253.2 | 81507 | 1.64041666667 | 12689 |
| 012442 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:17am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596506.3 | 512252.1 | 81509 | 1.64041666667 | 12442 |
| 013580 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:18am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596507.0 | 512249.8 | 81511 | 1.64041666667 | 13580 |
| 012455 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:19am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596508.9 | 512247.9 | 81513 | 1.64041666667 | 12455 |
| 013613 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:20am | Sensor | 1797-S0052-G-TJV.cor | 6847.4 | 1596509.5 | 512247.7 | 81515 | 1.64041666667 | 13613 |
| 011893 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:21am | Sensor | 1797-S0052-G-TJV.cor | 6847.5 | 1596509.3 | 512247.8 | 81517 | 1.64041666667 | 11893 |
| 011943 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:21am | Sensor | 1797-S0052-G-TJV.cor | 6847.2 | 1596509.7 | 512247.9 | 81518 | 1.64041666667 | 11943 |
| 011835 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:23am | Sensor | 1797-S0052-G-TJV.cor | 6847.3 | 1596509.7 | 512247.9 | 81521 | 1.64041666667 | 11835 |
| 013008 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:24am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596508.9 | 512248.1 | 81523 | 1.64041666667 | 13008 |
| 011922 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596507.6 | 512248.4 | 81525 | 1.64041666667 | 11922 |
| 014050 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:26am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596507.4 | 512248.2 | 81527 | 1.64041666667 | 14050 |
| 011882 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596507.3 | 512248.1 | 81529 | 1.64041666667 | 11882 |
| 012150 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:28am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596507.3 | 512248.2 | 81531 | 1.64041666667 | 12150 |
| 011467 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:29am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596507.3 | 512248.2 | 81533 | 1.64041666667 | 11467 |
| 011327 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:30am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596507.2 | 512248.3 | 81535 | 1.64041666667 | 11327 |
| 012071 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:31am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596507.3 | 512249.5 | 81537 | 1.64041666667 | 12071 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:32am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596507.0 | 512251.2 | 81539 | 1.64041666667 | 11928 |
| 012672 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:33am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596508.3 | 512252.9 | 81541 | 1.64041666667 | 12672 |
| 012588 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:34am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596508.8 | 512253.8 | 81543 | 1.64041666667 | 12588 |
| 012297 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:35am | Sensor | 1797-S0052-G-TJV.cor | 6847.3 | 1596509.2 | 512253.9 | 81545 | 1.64041666667 | 12297 |
| 013034 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:36am | Sensor | 1797-S0052-G-TJV.cor | 6846.8 | 1596509.0 | 512254.6 | 81547 | 1.64041666667 | 13034 |
| 011838 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:37am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596507.9 | 512253.6 | 81549 | 1.64041666667 | 11838 |
| 014329 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:38am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596507.9 | 512253.8 | 81551 | 1.64041666667 | 14329 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013812 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:39am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596508.3 | 512254.0 | 81553 | 1.64041666667 | 13812 |
| 012723 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:40am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596510.5 | 512254.7 | 81555 | 1.64041666667 | 12723 |
| 013410 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:41am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596512.2 | 512256.1 | 81557 | 1.64041666667 | 13410 |
| 012892 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:42am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596514.3 | 512255.5 | 81559 | 1.64041666667 | 12892 |
| 012043 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596514.7 | 512255.7 | 81561 | 1.64041666667 | 12043 |
| 012641 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596515.8 | 512256.7 | 81563 | 1.64041666667 | 12641 |
| 014470 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596516.1 | 512256.3 | 81565 | 1.64041666667 | 14470 |
| 014147 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:45am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596517.7 | 512258.0 | 81566 | 1.64041666667 | 14147 |
| 013826 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596518.7 | 512258.8 | 81569 | 1.64041666667 | 13826 |
| 012366 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596520.1 | 512259.1 | 81571 | 1.64041666667 | 12366 |
| 014581 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596521.4 | 512260.3 | 81573 | 1.64041666667 | 14581 |
| 013815 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596523.0 | 512261.0 | 81575 | 1.64041666667 | 13815 |
| 013563 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:51am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596525.5 | 512262.8 | 81577 | 1.64041666667 | 13563 |
| 012391 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:52am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596527.6 | 512263.9 | 81579 | 1.64041666667 | 12391 |
| 012067 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596530.0 | 512265.2 | 81581 | 1.64041666667 | 12067 |
| 012497 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:54am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596532.4 | 512265.2 | 81583 | 1.64041666667 | 12497 |
| 011164 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596534.5 | 512266.6 | 81585 | 1.64041666667 | 11164 |
| 012811 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596536.5 | 512267.3 | 81586 | 1.64041666667 | 12811 |
| 012112 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:57am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596538.2 | 512269.2 | 81589 | 1.64041666667 | 12112 |
| 011548 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:57am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596539.9 | 512270.6 | 81590 | 1.64041666667 | 11548 |
| 012757 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:59am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596542.5 | 512271.7 | 81593 | 1.64041666667 | 12757 |
| 013239 | 0 | GeoXH 6000 | 08/20/2015 | 11:09:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596544.2 | 512272.5 | 81594 | 1.64041666667 | 13239 |
| 010869 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596546.4 | 512272.3 | 81597 | 1.64041666667 | 10869 |
| 011807 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596547.4 | 512273.6 | 81598 | 1.64041666667 | 11807 |
| 012941 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596549.0 | 512273.5 | 81601 | 1.64041666667 | 12941 |
| 013045 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596550.8 | 512275.0 | 81602 | 1.64041666667 | 13045 |
| 013671 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:05am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596552.8 | 512276.1 | 81605 | 1.64041666667 | 13671 |
| 012777 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:05am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596554.5 | 512277.0 | 81606 | 1.64041666667 | 12777 |
| 013394 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:07am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596557.1 | 512277.9 | 81609 | 1.64041666667 | 13394 |
| 015018 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:08am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596559.7 | 512278.8 | 81611 | 1.64041666667 | 15018 |
| 015034 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596561.9 | 512279.8 | 81613 | 1.64041666667 | 15034 |
| 015428 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596564.3 | 512281.4 | 81614 | 1.64041666667 | 15428 |
| 016307 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:11am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596567.3 | 512282.1 | 81617 | 1.64041666667 | 16307 |
| 016976 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596569.1 | 512283.3 | 81618 | 1.64041666667 | 16976 |
| 017624 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596572.1 | 512284.2 | 81621 | 1.64041666667 | 17624 |
| 015566 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596573.9 | 512285.4 | 81622 | 1.64041666667 | 15566 |
| 015471 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.2 | 512286.3 | 81625 | 1.64041666667 | 15471 |
| 015177 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596579.3 | 512287.6 | 81626 | 1.64041666667 | 15177 |
| 015404 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596582.0 | 512288.9 | 81629 | 1.64041666667 | 15404 |
| 014951 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596584.6 | 512290.0 | 81631 | 1.64041666667 | 14951 |
| 018077 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596586.9 | 512291.3 | 81633 | 1.64041666667 | 18077 |
| 015259 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596589.5 | 512292.0 | 81634 | 1.64041666667 | 15259 |
| 014974 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596591.8 | 512293.4 | 81637 | 1.64041666667 | 14974 |
| 013733 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596594.1 | 512294.4 | 81639 | 1.64041666667 | 13733 |
| 015403 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596596.1 | 512295.9 | 81641 | 1.64041666667 | 15403 |
| 014891 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596598.8 | 512296.4 | 81643 | 1.64041666667 | 14891 |
| 013412 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596601.4 | 512297.6 | 81645 | 1.64041666667 | 13412 |
| 014003 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596603.8 | 512298.4 | 81646 | 1.64041666667 | 14003 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014960 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596606.8 | 512299.8 | 81649 | 1.64041666667 | 14960 |
| 015710 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596608.4 | 512301.1 | 81650 | 1.64041666667 | 15710 |
| 014547 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596611.1 | 512301.7 | 81653 | 1.64041666667 | 14547 |
| 013393 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596612.4 | 512301.9 | 81654 | 1.64041666667 | 13393 |
| 013884 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596611.6 | 512302.6 | 81657 | 1.64041666667 | 13884 |
| 014541 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596612.4 | 512301.1 | 81659 | 1.64041666667 | 14541 |
| 014705 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596614.2 | 512299.0 | 81661 | 1.64041666667 | 14705 |
| 014956 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596613.8 | 512297.1 | 81662 | 1.64041666667 | 14956 |
| 013999 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596613.8 | 512296.4 | 81665 | 1.64041666667 | 13999 |
| 015799 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596613.5 | 512296.8 | 81666 | 1.64041666667 | 15799 |
| 015890 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596613.8 | 512296.3 | 81669 | 1.64041666667 | 15890 |
| 013842 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596614.9 | 512295.5 | 81671 | 1.64041666667 | 13842 |
| 014620 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596616.4 | 512292.4 | 81673 | 1.64041666667 | 14620 |
| 014365 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.8 | 512290.9 | 81675 | 1.64041666667 | 14365 |
| 015801 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596618.9 | 512289.9 | 81676 | 1.64041666667 | 15801 |
| 015140 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:41am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596617.8 | 512291.1 | 81678 | 1.64041666667 | 15140 |
| 014885 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.5 | 512291.3 | 81681 | 1.64041666667 | 14885 |
| 013682 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.3 | 512291.3 | 81682 | 1.64041666667 | 13682 |
| 014760 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.2 | 512291.4 | 81685 | 1.64041666667 | 14760 |
| 016170 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.2 | 512291.5 | 81687 | 1.64041666667 | 16170 |
| 015922 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.2 | 512291.5 | 81689 | 1.64041666667 | 15922 |
| 015140 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596616.8 | 512291.3 | 81690 | 1.64041666667 | 15140 |
| 015455 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.1 | 512291.5 | 81693 | 1.64041666667 | 15455 |
| 015653 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.0 | 512291.5 | 81694 | 1.64041666667 | 15653 |
| 014293 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.1 | 512291.5 | 81697 | 1.64041666667 | 14293 |
| 015093 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.1 | 512291.5 | 81698 | 1.64041666667 | 15093 |
| 013043 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.0 | 512291.5 | 81701 | 1.64041666667 | 13043 |
| 014060 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.0 | 512291.4 | 81702 | 1.64041666667 | 14060 |
| 015035 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.0 | 512291.5 | 81705 | 1.64041666667 | 15035 |
| 015938 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.0 | 512291.5 | 81706 | 1.64041666667 | 15938 |
| 014334 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.0 | 512291.5 | 81708 | 1.64041666667 | 14334 |
| 014143 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.0 | 512291.4 | 81711 | 1.64041666667 | 14143 |
| 013346 | 0 | GeoXH 6000 | 08/20/2015 | 11:10:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.0 | 512291.4 | 81713 | 1.64041666667 | 13346 |
| 015486 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.0 | 512291.5 | 81715 | 1.64041666667 | 15486 |
| 015751 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.5 | 81717 | 1.64041666667 | 15751 |
| 014077 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.5 | 81718 | 1.64041666667 | 14077 |
| 013899 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.0 | 512291.4 | 81721 | 1.64041666667 | 13899 |
| 013975 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.0 | 512291.4 | 81722 | 1.64041666667 | 13975 |
| 014503 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.4 | 81725 | 1.64041666667 | 14503 |
| 014006 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.4 | 81726 | 1.64041666667 | 14006 |
| 015231 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.0 | 512291.4 | 81729 | 1.64041666667 | 15231 |
| 013407 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596617.0 | 512291.4 | 81730 | 1.64041666667 | 13407 |
| 014752 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596617.1 | 512291.4 | 81733 | 1.64041666667 | 14752 |
| 013618 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.4 | 81735 | 1.64041666667 | 13618 |
| 013544 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.4 | 81737 | 1.64041666667 | 13544 |
| 016196 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.2 | 512291.4 | 81738 | 1.64041666667 | 16196 |
| 016439 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.2 | 512291.4 | 81741 | 1.64041666667 | 16439 |
| 015449 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.4 | 81742 | 1.64041666667 | 15449 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015472 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.2 | 512291.4 | 81745 | 1.64041666667 | 15472 |
| 013978 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596617.2 | 512291.4 | 81747 | 1.64041666667 | 13978 |
| 013964 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.4 | 81749 | 1.64041666667 | 13964 |
| 014531 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.4 | 81751 | 1.64041666667 | 14531 |
| 014972 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.1 | 512291.4 | 81753 | 1.64041666667 | 14972 |
| 015593 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.2 | 512291.4 | 81754 | 1.64041666667 | 15593 |
| 015598 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.2 | 512291.4 | 81757 | 1.64041666667 | 15598 |
| 014909 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596617.2 | 512291.3 | 81759 | 1.64041666667 | 14909 |
| 013447 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596618.2 | 512290.9 | 81761 | 1.64041666667 | 13447 |
| 014011 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596618.1 | 512292.0 | 81762 | 1.64041666667 | 14011 |
| 015772 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596617.4 | 512294.9 | 81765 | 1.64041666667 | 15772 |
| 015643 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596615.6 | 512296.0 | 81766 | 1.64041666667 | 15643 |
| 014861 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596613.1 | 512296.1 | 81769 | 1.64041666667 | 14861 |
| 014665 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596610.6 | 512295.3 | 81771 | 1.64041666667 | 14665 |
| 016866 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596608.3 | 512293.5 | 81773 | 1.64041666667 | 16866 |
| 016156 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596606.0 | 512292.7 | 81774 | 1.64041666667 | 16156 |
| 016249 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596603.4 | 512291.3 | 81777 | 1.64041666667 | 16249 |
| 016062 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596601.3 | 512290.5 | 81778 | 1.64041666667 | 16062 |
| 015685 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596599.4 | 512289.0 | 81781 | 1.64041666667 | 15685 |
| 015411 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596597.2 | 512288.6 | 81782 | 1.64041666667 | 15411 |
| 017352 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596595.0 | 512287.0 | 81785 | 1.64041666667 | 17352 |
| 015378 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596592.8 | 512286.4 | 81786 | 1.64041666667 | 15378 |
| 015184 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596590.2 | 512284.6 | 81789 | 1.64041666667 | 15184 |
| 016336 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596587.8 | 512283.8 | 81790 | 1.64041666667 | 16336 |
| 016024 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596585.5 | 512282.1 | 81793 | 1.64041666667 | 16024 |
| 015106 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596583.3 | 512281.3 | 81794 | 1.64041666667 | 15106 |
| 015326 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596580.8 | 512279.9 | 81797 | 1.64041666667 | 15326 |
| 014391 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596578.6 | 512279.2 | 81798 | 1.64041666667 | 14391 |
| 014668 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596575.7 | 512278.1 | 81801 | 1.64041666667 | 14668 |
| 014197 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596573.5 | 512277.1 | 81802 | 1.64041666667 | 14197 |
| 012339 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596570.7 | 512275.9 | 81805 | 1.64041666667 | 12339 |
| 012984 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596569.0 | 512274.4 | 81806 | 1.64041666667 | 12984 |
| 014286 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596566.8 | 512273.5 | 81809 | 1.64041666667 | 14286 |
| 013201 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596566.6 | 512273.0 | 81810 | 1.64041666667 | 13201 |
| 012030 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596564.4 | 512272.7 | 81813 | 1.64041666667 | 12030 |
| 012337 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596564.0 | 512272.5 | 81814 | 1.64041666667 | 12337 |
| 013524 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596562.9 | 512270.7 | 81816 | 1.64041666667 | 13524 |
| 011601 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:51am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596561.3 | 512269.3 | 81818 | 1.64041666667 | 11601 |
| 012410 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596559.3 | 512267.3 | 81821 | 1.64041666667 | 12410 |
| 013242 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596557.1 | 512266.8 | 81822 | 1.64041666667 | 13242 |
| 013060 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596554.4 | 512264.9 | 81825 | 1.64041666667 | 13060 |
| 012745 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596552.3 | 512264.2 | 81826 | 1.64041666667 | 12745 |
| 012456 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596549.8 | 512263.1 | 81829 | 1.64041666667 | 12456 |
| 011154 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596547.6 | 512262.7 | 81830 | 1.64041666667 | 11154 |
| 012298 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596544.8 | 512262.1 | 81833 | 1.64041666667 | 12298 |
| 012944 | 0 | GeoXH 6000 | 08/20/2015 | 11:11:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596543.2 | 512261.0 | 81834 | 1.64041666667 | 12944 |
| 012566 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596540.9 | 512259.2 | 81837 | 1.64041666667 | 12566 |
| 012141 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596539.5 | 512258.0 | 81838 | 1.64041666667 | 12141 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014135 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596537.0 | 512257.5 | 81841 | 1.64041666667 | 14135 |
| 014147 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:04am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596536.1 | 512256.5 | 81843 | 1.64041666667 | 14147 |
| 012493 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:05am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596534.1 | 512256.5 | 81845 | 1.64041666667 | 12493 |
| 012843 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:05am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596532.5 | 512255.1 | 81846 | 1.64041666667 | 12843 |
| 013320 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:07am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596531.2 | 512254.5 | 81849 | 1.64041666667 | 13320 |
| 012960 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:07am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596529.4 | 512254.0 | 81850 | 1.64041666667 | 12960 |
| 013200 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596528.7 | 512252.8 | 81853 | 1.64041666667 | 13200 |
| 014100 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596526.9 | 512252.0 | 81854 | 1.64041666667 | 14100 |
| 012225 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:11am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596525.7 | 512251.1 | 81857 | 1.64041666667 | 12225 |
| 012056 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:11am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596525.3 | 512251.2 | 81858 | 1.64041666667 | 12056 |
| 012734 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:12am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596525.4 | 512251.6 | 81860 | 1.64041666667 | 12734 |
| 013173 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:13am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596525.4 | 512251.8 | 81862 | 1.64041666667 | 13173 |
| 012803 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:14am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596525.2 | 512251.3 | 81864 | 1.64041666667 | 12803 |
| 013070 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:15am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596525.0 | 512250.2 | 81866 | 1.64041666667 | 13070 |
| 013737 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:17am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596525.9 | 512247.2 | 81869 | 1.64041666667 | 13737 |
| 014354 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:17am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596526.9 | 512245.4 | 81870 | 1.64041666667 | 14354 |
| 014388 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:19am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596528.5 | 512242.7 | 81873 | 1.64041666667 | 14388 |
| 013647 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:19am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596529.8 | 512241.6 | 81874 | 1.64041666667 | 13647 |
| 014271 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:21am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596530.3 | 512241.4 | 81877 | 1.64041666667 | 14271 |
| 013288 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:22am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596530.0 | 512242.5 | 81879 | 1.64041666667 | 13288 |
| 014662 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:23am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596528.2 | 512243.6 | 81881 | 1.64041666667 | 14662 |
| 013565 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:23am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596526.8 | 512245.6 | 81882 | 1.64041666667 | 13565 |
| 012781 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596524.5 | 512247.5 | 81885 | 1.64041666667 | 12781 |
| 014085 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596523.2 | 512249.2 | 81886 | 1.64041666667 | 14085 |
| 013121 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:27am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596521.7 | 512250.7 | 81889 | 1.64041666667 | 13121 |
| 013360 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:27am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596520.0 | 512252.1 | 81890 | 1.64041666667 | 13360 |
| 013150 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596517.1 | 512252.7 | 81893 | 1.64041666667 | 13150 |
| 012947 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:30am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596515.4 | 512251.4 | 81895 | 1.64041666667 | 12947 |
| 012506 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:31am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596512.9 | 512249.7 | 81897 | 1.64041666667 | 12506 |
| 012636 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:31am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596511.5 | 512248.1 | 81898 | 1.64041666667 | 12636 |
| 012339 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:32am | Sensor | 1797-S0052-G-TJV.cor | 6847.5 | 1596510.5 | 512246.8 | 81900 | 1.64041666667 | 12339 |
| 011934 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:33am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596511.6 | 512246.9 | 81902 | 1.64041666667 | 11934 |
| 013903 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:34am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596512.5 | 512245.4 | 81904 | 1.64041666667 | 13903 |
| 013436 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:35am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596513.2 | 512243.1 | 81906 | 1.64041666667 | 13436 |
| 013619 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:37am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596513.3 | 512241.2 | 81909 | 1.64041666667 | 13619 |
| 013544 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:37am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596513.3 | 512241.3 | 81910 | 1.64041666667 | 13544 |
| 012506 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:39am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596513.8 | 512241.3 | 81913 | 1.64041666667 | 12506 |
| 012396 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:39am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596513.8 | 512241.0 | 81914 | 1.64041666667 | 12396 |
| 013479 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:41am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596513.3 | 512238.9 | 81917 | 1.64041666667 | 13479 |
| 013569 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:41am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596514.2 | 512237.0 | 81918 | 1.64041666667 | 13569 |
| 013502 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596514.6 | 512235.3 | 81921 | 1.64041666667 | 13502 |
| 013575 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596514.5 | 512235.5 | 81923 | 1.64041666667 | 13575 |
| 014973 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596514.0 | 512235.5 | 81925 | 1.64041666667 | 14973 |
| 013013 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596513.5 | 512235.4 | 81926 | 1.64041666667 | 13013 |
| 012913 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:46am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596513.6 | 512237.8 | 81928 | 1.64041666667 | 12913 |
| 013368 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:47am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596513.2 | 512240.2 | 81930 | 1.64041666667 | 13368 |
| 012492 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:49am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596514.3 | 512242.0 | 81933 | 1.64041666667 | 12492 |
| 013563 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:49am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596515.9 | 512243.4 | 81934 | 1.64041666667 | 13563 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012090 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:50am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596518.7 | 512244.5 | 81936 | 1.64041666667 | 12090 |
| 013222 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:51am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596521.0 | 512244.0 | 81938 | 1.64041666667 | 13222 |
| 014435 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596523.5 | 512244.7 | 81941 | 1.64041666667 | 14435 |
| 014799 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596525.9 | 512244.7 | 81942 | 1.64041666667 | 14799 |
| 014319 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:54am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596528.1 | 512245.7 | 81944 | 1.64041666667 | 14319 |
| 016000 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596530.6 | 512246.2 | 81946 | 1.64041666667 | 16000 |
| 014200 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:56am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596532.0 | 512247.1 | 81948 | 1.64041666667 | 14200 |
| 011860 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596534.1 | 512247.8 | 81950 | 1.64041666667 | 11860 |
| 013135 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596536.1 | 512249.1 | 81953 | 1.64041666667 | 13135 |
| 014503 | 0 | GeoXH 6000 | 08/20/2015 | 11:12:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596538.4 | 512249.4 | 81954 | 1.64041666667 | 14503 |
| 013076 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:00am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596540.7 | 512251.0 | 81956 | 1.64041666667 | 13076 |
| 014939 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596543.4 | 512251.9 | 81958 | 1.64041666667 | 14939 |
| 014084 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:02am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596544.8 | 512253.3 | 81960 | 1.64041666667 | 14084 |
| 014201 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596547.3 | 512253.9 | 81962 | 1.64041666667 | 14201 |
| 012970 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:04am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596549.8 | 512255.4 | 81964 | 1.64041666667 | 12970 |
| 014462 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:05am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596551.7 | 512257.0 | 81966 | 1.64041666667 | 14462 |
| 013575 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:06am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596554.1 | 512258.5 | 81968 | 1.64041666667 | 13575 |
| 012243 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:07am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596556.3 | 512259.9 | 81970 | 1.64041666667 | 12243 |
| 011221 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596558.5 | 512260.6 | 81973 | 1.64041666667 | 11221 |
| 012405 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596560.4 | 512261.4 | 81974 | 1.64041666667 | 12405 |
| 013091 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:10am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596561.7 | 512262.1 | 81976 | 1.64041666667 | 13091 |
| 013503 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:12am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596564.6 | 512263.4 | 81979 | 1.64041666667 | 13503 |
| 013635 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:13am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596566.4 | 512264.1 | 81981 | 1.64041666667 | 13635 |
| 013848 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:13am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596568.3 | 512263.8 | 81982 | 1.64041666667 | 13848 |
| 014772 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:14am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596571.4 | 512265.0 | 81984 | 1.64041666667 | 14772 |
| 013473 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:15am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596574.4 | 512264.9 | 81986 | 1.64041666667 | 13473 |
| 014078 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:17am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596576.1 | 512266.4 | 81989 | 1.64041666667 | 14078 |
| 013029 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596578.3 | 512266.9 | 81990 | 1.64041666667 | 13029 |
| 013187 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596580.2 | 512268.1 | 81992 | 1.64041666667 | 13187 |
| 014126 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596582.4 | 512269.5 | 81994 | 1.64041666667 | 14126 |
| 017151 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596584.6 | 512271.1 | 81996 | 1.64041666667 | 17151 |
| 014128 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596586.9 | 512271.9 | 81998 | 1.64041666667 | 14128 |
| 015172 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596589.3 | 512273.2 | 82000 | 1.64041666667 | 15172 |
| 013603 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596591.4 | 512274.7 | 82002 | 1.64041666667 | 13603 |
| 013900 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596594.3 | 512275.8 | 82004 | 1.64041666667 | 13900 |
| 013585 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596596.3 | 512277.1 | 82006 | 1.64041666667 | 13585 |
| 014856 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596598.8 | 512278.2 | 82008 | 1.64041666667 | 14856 |
| 015654 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596600.4 | 512279.9 | 82010 | 1.64041666667 | 15654 |
| 015193 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596603.1 | 512280.8 | 82012 | 1.64041666667 | 15193 |
| 015198 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596605.0 | 512282.0 | 82014 | 1.64041666667 | 15198 |
| 014029 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596607.7 | 512282.5 | 82016 | 1.64041666667 | 14029 |
| 015207 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596609.4 | 512283.5 | 82018 | 1.64041666667 | 15207 |
| 014932 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596612.0 | 512283.9 | 82020 | 1.64041666667 | 14932 |
| 015553 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596613.5 | 512285.0 | 82022 | 1.64041666667 | 15553 |
| 015438 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596615.8 | 512286.1 | 82024 | 1.64041666667 | 15438 |
| 015349 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596616.9 | 512287.9 | 82026 | 1.64041666667 | 15349 |
| 013887 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596618.1 | 512289.3 | 82028 | 1.64041666667 | 13887 |
| 013522 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:37am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596617.0 | 512289.2 | 82030 | 1.64041666667 | 13522 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013340 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:38am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596616.6 | 512288.5 | 82032 | 1.64041666667 | 13340 |
| 015095 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:39am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596616.6 | 512288.4 | 82034 | 1.64041666667 | 15095 |
| 013403 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596618.1 | 512285.8 | 82037 | 1.64041666667 | 13403 |
| 015411 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596618.9 | 512283.7 | 82038 | 1.64041666667 | 15411 |
| 015612 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596620.0 | 512283.5 | 82040 | 1.64041666667 | 15612 |
| 015423 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596620.3 | 512283.1 | 82042 | 1.64041666667 | 15423 |
| 015915 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596620.6 | 512281.9 | 82044 | 1.64041666667 | 15915 |
| 014448 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596622.2 | 512279.8 | 82046 | 1.64041666667 | 14448 |
| 015132 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596624.0 | 512277.5 | 82049 | 1.64041666667 | 15132 |
| 014643 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596625.3 | 512275.8 | 82050 | 1.64041666667 | 14643 |
| 015870 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596625.3 | 512275.6 | 82053 | 1.64041666667 | 15870 |
| 015397 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596623.9 | 512276.9 | 82054 | 1.64041666667 | 15397 |
| 016269 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596623.8 | 512278.5 | 82057 | 1.64041666667 | 16269 |
| 016337 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596623.6 | 512279.0 | 82058 | 1.64041666667 | 16337 |
| 016714 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596622.6 | 512280.0 | 82060 | 1.64041666667 | 16714 |
| 014978 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596620.8 | 512281.7 | 82062 | 1.64041666667 | 14978 |
| 013554 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596618.1 | 512281.3 | 82064 | 1.64041666667 | 13554 |
| 014368 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596615.3 | 512281.2 | 82066 | 1.64041666667 | 14368 |
| 015832 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596612.8 | 512280.3 | 82068 | 1.64041666667 | 15832 |
| 014638 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596610.2 | 512279.7 | 82070 | 1.64041666667 | 14638 |
| 013529 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596607.7 | 512278.5 | 82072 | 1.64041666667 | 13529 |
| 015802 | 0 | GeoXH 6000 | 08/20/2015 | 11:13:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596605.2 | 512277.2 | 82074 | 1.64041666667 | 15802 |
| 015770 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596602.2 | 512275.8 | 82076 | 1.64041666667 | 15770 |
| 015132 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596600.0 | 512274.5 | 82078 | 1.64041666667 | 15132 |
| 01521 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596596.9 | 512274.2 | 82081 | 1.64041666667 | 1521 |
| 013673 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596595.2 | 512273.4 | 82082 | 1.64041666667 | 13673 |
| 013888 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596592.1 | 512273.1 | 82084 | 1.64041666667 | 13888 |
| 012562 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596589.9 | 512271.6 | 82086 | 1.64041666667 | 12562 |
| 013370 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596587.2 | 512270.7 | 82089 | 1.64041666667 | 13370 |
| 012432 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596585.2 | 512269.4 | 82090 | 1.64041666667 | 12432 |
| 012648 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596582.4 | 512268.7 | 82093 | 1.64041666667 | 12648 |
| 013302 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596580.3 | 512267.9 | 82094 | 1.64041666667 | 13302 |
| 012775 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596578.0 | 512267.1 | 82096 | 1.64041666667 | 12775 |
| 013664 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:11am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596576.1 | 512265.3 | 82098 | 1.64041666667 | 13664 |
| 013676 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:12am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596574.6 | 512263.6 | 82100 | 1.64041666667 | 13676 |
| 012809 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:13am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596572.8 | 512262.1 | 82102 | 1.64041666667 | 12809 |
| 013912 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:15am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596571.3 | 512260.1 | 82105 | 1.64041666667 | 13912 |
| 012688 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:15am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596570.7 | 512259.0 | 82106 | 1.64041666667 | 12688 |
| 013732 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:17am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596568.0 | 512258.7 | 82109 | 1.64041666667 | 13732 |
| 012326 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:17am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596566.5 | 512258.1 | 82110 | 1.64041666667 | 12326 |
| 012460 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:18am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596564.3 | 512259.4 | 82112 | 1.64041666667 | 12460 |
| 013105 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:19am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596562.7 | 512259.5 | 82114 | 1.64041666667 | 13105 |
| 012516 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:20am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596560.4 | 512259.1 | 82116 | 1.64041666667 | 12516 |
| 013269 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:21am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596559.5 | 512257.6 | 82118 | 1.64041666667 | 13269 |
| 013157 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:22am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596557.1 | 512256.6 | 82120 | 1.64041666667 | 13157 |
| 014179 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596555.6 | 512255.0 | 82122 | 1.64041666667 | 14179 |
| 013384 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596553.0 | 512253.5 | 82125 | 1.64041666667 | 13384 |
| 012316 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596551.8 | 512251.6 | 82126 | 1.64041666667 | 12316 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012139 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:26am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596549.3 | 512250.4 | 82128 | 1.64041666667 | 12139 |
| 011824 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596548.0 | 512248.8 | 82130 | 1.64041666667 | 11824 |
| 012406 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596544.8 | 512246.9 | 82133 | 1.64041666667 | 12406 |
| 012251 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596543.4 | 512245.4 | 82134 | 1.64041666667 | 12251 |
| 011883 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:30am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596540.6 | 512245.8 | 82136 | 1.64041666667 | 11883 |
| 012150 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:31am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596539.0 | 512244.4 | 82138 | 1.64041666667 | 12150 |
| 012847 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:33am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596536.4 | 512243.1 | 82141 | 1.64041666667 | 12847 |
| 013172 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:33am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596535.7 | 512241.9 | 82142 | 1.64041666667 | 13172 |
| 013343 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:35am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596534.6 | 512240.5 | 82145 | 1.64041666667 | 13343 |
| 013355 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:35am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596532.8 | 512240.3 | 82146 | 1.64041666667 | 13355 |
| 013689 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:36am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596531.6 | 512239.7 | 82148 | 1.64041666667 | 13689 |
| 012662 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:37am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596531.1 | 512239.9 | 82150 | 1.64041666667 | 12662 |
| 011745 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:39am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596531.0 | 512240.0 | 82153 | 1.64041666667 | 11745 |
| 013586 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:39am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596531.1 | 512239.5 | 82154 | 1.64041666667 | 13586 |
| 012996 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:41am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596533.2 | 512236.4 | 82157 | 1.64041666667 | 12996 |
| 012369 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:41am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596535.1 | 512234.6 | 82158 | 1.64041666667 | 12369 |
| 013112 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:42am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596536.3 | 512232.0 | 82160 | 1.64041666667 | 13112 |
| 014018 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596536.0 | 512231.8 | 82162 | 1.64041666667 | 14018 |
| 012324 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596536.0 | 512231.7 | 82164 | 1.64041666667 | 12324 |
| 013161 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596535.7 | 512232.3 | 82166 | 1.64041666667 | 13161 |
| 012410 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596534.7 | 512234.9 | 82168 | 1.64041666667 | 12410 |
| 014472 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596532.9 | 512237.0 | 82170 | 1.64041666667 | 14472 |
| 013068 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596530.9 | 512239.7 | 82172 | 1.64041666667 | 13068 |
| 015417 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596529.2 | 512241.9 | 82174 | 1.64041666667 | 15417 |
| 013034 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:50am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596526.6 | 512243.0 | 82176 | 1.64041666667 | 13034 |
| 013158 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:51am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596523.9 | 512243.1 | 82178 | 1.64041666667 | 13158 |
| 014359 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:52am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596522.0 | 512241.3 | 82180 | 1.64041666667 | 14359 |
| 011689 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:53am | Sensor | 1797-S0052-G-TJV.cor | 6847.8 | 1596520.0 | 512239.7 | 82182 | 1.64041666667 | 11689 |
| 012312 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:55am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596520.2 | 512237.4 | 82185 | 1.64041666667 | 12312 |
| 012618 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596518.7 | 512235.8 | 82186 | 1.64041666667 | 12618 |
| 011794 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:56am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596517.0 | 512234.4 | 82188 | 1.64041666667 | 11794 |
| 011768 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596515.9 | 512233.3 | 82190 | 1.64041666667 | 11768 |
| 012302 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:58am | Sensor | 1797-S0052-G-TJV.cor | 6848.0 | 1596517.6 | 512231.1 | 82192 | 1.64041666667 | 12302 |
| 012765 | 0 | GeoXH 6000 | 08/20/2015 | 11:14:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596519.2 | 512229.3 | 82194 | 1.64041666667 | 12765 |
| 013511 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:00am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596519.0 | 512229.0 | 82196 | 1.64041666667 | 13511 |
| 011328 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.2 | 1596519.4 | 512228.6 | 82198 | 1.64041666667 | 11328 |
| 013032 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:02am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596521.8 | 512227.0 | 82200 | 1.64041666667 | 13032 |
| 013098 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596523.4 | 512224.6 | 82202 | 1.64041666667 | 13098 |
| 013924 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:04am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596525.0 | 512223.3 | 82204 | 1.64041666667 | 13924 |
| 013621 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:05am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596525.6 | 512222.5 | 82206 | 1.64041666667 | 13621 |
| 010935 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:06am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596525.3 | 512221.9 | 82208 | 1.64041666667 | 10935 |
| 013833 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:07am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596525.2 | 512221.8 | 82210 | 1.64041666667 | 13833 |
| 012968 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:08am | Sensor | 1797-S0052-G-TJV.cor | 6847.7 | 1596525.2 | 512221.9 | 82212 | 1.64041666667 | 12968 |
| 012752 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:09am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596525.5 | 512222.0 | 82214 | 1.64041666667 | 12752 |
| 011828 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:11am | Sensor | 1797-S0052-G-TJV.cor | 6847.4 | 1596525.6 | 512222.0 | 82217 | 1.64041666667 | 11828 |
| 013997 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:11am | Sensor | 1797-S0052-G-TJV.cor | 6847.3 | 1596525.7 | 512222.0 | 82218 | 1.64041666667 | 13997 |
| 011539 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:13am | Sensor | 1797-S0052-G-TJV.cor | 6847.2 | 1596525.8 | 512222.0 | 82221 | 1.64041666667 | 11539 |
| 014014 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:13am | Sensor | 1797-S0052-G-TJV.cor | 6847.1 | 1596526.3 | 512222.5 | 82222 | 1.64041666667 | 14014 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014603 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:15am | Sensor | 1797-S0052-G-TJV.cor | 6848.1 | 1596525.6 | 512222.8 | 82225 | 1.64041666667 | 14603 |
| 014061 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:15am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596524.0 | 512223.2 | 82226 | 1.64041666667 | 14061 |
| 013865 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:16am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596523.4 | 512224.6 | 82228 | 1.64041666667 | 13865 |
| 013996 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:17am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596522.4 | 512226.0 | 82230 | 1.64041666667 | 13996 |
| 012799 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:18am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596521.6 | 512227.6 | 82232 | 1.64041666667 | 12799 |
| 013879 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:19am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596522.4 | 512228.1 | 82234 | 1.64041666667 | 13879 |
| 014600 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:21am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596524.0 | 512229.4 | 82237 | 1.64041666667 | 14600 |
| 012380 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:21am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596525.6 | 512230.3 | 82238 | 1.64041666667 | 12380 |
| 012575 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:23am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596527.2 | 512232.2 | 82241 | 1.64041666667 | 12575 |
| 013313 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:23am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596529.3 | 512233.6 | 82242 | 1.64041666667 | 13313 |
| 012898 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:24am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596530.8 | 512235.5 | 82244 | 1.64041666667 | 12898 |
| 015644 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596532.8 | 512235.0 | 82246 | 1.64041666667 | 15644 |
| 012611 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596534.0 | 512235.4 | 82249 | 1.64041666667 | 12611 |
| 014522 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596535.6 | 512236.6 | 82250 | 1.64041666667 | 14522 |
| 014220 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596536.8 | 512236.9 | 82253 | 1.64041666667 | 14220 |
| 013995 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596538.5 | 512238.1 | 82254 | 1.64041666667 | 13995 |
| 013488 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:30am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596539.8 | 512238.8 | 82256 | 1.64041666667 | 13488 |
| 012402 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:31am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596540.5 | 512240.2 | 82258 | 1.64041666667 | 12402 |
| 011620 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:32am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596542.6 | 512241.1 | 82260 | 1.64041666667 | 11620 |
| 013405 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:33am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596543.6 | 512242.0 | 82262 | 1.64041666667 | 13405 |
| 013851 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:35am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596545.0 | 512243.2 | 82265 | 1.64041666667 | 13851 |
| 012612 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:35am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596546.4 | 512244.4 | 82266 | 1.64041666667 | 12612 |
| 012333 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:36am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596548.7 | 512244.2 | 82268 | 1.64041666667 | 12333 |
| 014453 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:37am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596549.8 | 512244.5 | 82270 | 1.64041666667 | 14453 |
| 014353 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:38am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596552.1 | 512243.7 | 82272 | 1.64041666667 | 14353 |
| 013008 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:39am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596553.2 | 512244.8 | 82274 | 1.64041666667 | 13008 |
| 011742 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:40am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596555.8 | 512245.3 | 82276 | 1.64041666667 | 11742 |
| 012295 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:41am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596557.3 | 512246.1 | 82278 | 1.64041666667 | 12295 |
| 012314 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596560.2 | 512246.6 | 82281 | 1.64041666667 | 12314 |
| 012108 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596562.0 | 512247.7 | 82282 | 1.64041666667 | 12108 |
| 013587 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596564.8 | 512248.2 | 82284 | 1.64041666667 | 13587 |
| 013296 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596567.3 | 512248.1 | 82286 | 1.64041666667 | 13296 |
| 013674 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596569.2 | 512248.8 | 82289 | 1.64041666667 | 13674 |
| 013828 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596570.8 | 512250.0 | 82290 | 1.64041666667 | 13828 |
| 013597 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596572.1 | 512252.3 | 82292 | 1.64041666667 | 13597 |
| 013239 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596574.3 | 512253.2 | 82294 | 1.64041666667 | 13239 |
| 013359 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596576.6 | 512255.2 | 82296 | 1.64041666667 | 13359 |
| 013810 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:51am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596579.2 | 512255.4 | 82298 | 1.64041666667 | 13810 |
| 013562 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:52am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596581.8 | 512256.1 | 82300 | 1.64041666667 | 13562 |
| 013440 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596584.0 | 512255.8 | 82302 | 1.64041666667 | 13440 |
| 014130 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596586.4 | 512257.0 | 82305 | 1.64041666667 | 14130 |
| 014302 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596588.3 | 512258.4 | 82306 | 1.64041666667 | 14302 |
| 016205 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:56am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596590.9 | 512259.6 | 82308 | 1.64041666667 | 16205 |
| 013591 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596592.5 | 512260.9 | 82310 | 1.64041666667 | 13591 |
| 012457 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:58am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596595.2 | 512261.1 | 82312 | 1.64041666667 | 12457 |
| 012564 | 0 | GeoXH 6000 | 08/20/2015 | 11:15:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596597.0 | 512262.0 | 82314 | 1.64041666667 | 12564 |
| 014241 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596599.8 | 512263.0 | 82316 | 1.64041666667 | 14241 |
| 013250 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596601.1 | 512264.7 | 82318 | 1.64041666667 | 13250 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013092 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596603.6 | 512265.7 | 82320 | 1.64041666667 | 13092 |
| 013143 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596605.5 | 512266.8 | 82322 | 1.64041666667 | 13143 |
| 013245 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596608.3 | 512267.8 | 82324 | 1.64041666667 | 13245 |
| 014542 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596610.0 | 512268.8 | 82326 | 1.64041666667 | 14542 |
| 014358 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596612.6 | 512270.0 | 82328 | 1.64041666667 | 14358 |
| 015169 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596615.2 | 512271.0 | 82330 | 1.64041666667 | 15169 |
| 015342 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596617.8 | 512272.5 | 82332 | 1.64041666667 | 15342 |
| 016495 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596620.2 | 512273.2 | 82334 | 1.64041666667 | 16495 |
| 015014 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596622.4 | 512274.9 | 82336 | 1.64041666667 | 15014 |
| 013773 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596625.1 | 512275.0 | 82338 | 1.64041666667 | 13773 |
| 014183 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596626.2 | 512274.0 | 82340 | 1.64041666667 | 14183 |
| 014795 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596627.5 | 512271.5 | 82342 | 1.64041666667 | 14795 |
| 014739 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596628.2 | 512270.2 | 82344 | 1.64041666667 | 14739 |
| 016344 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596628.2 | 512270.4 | 82346 | 1.64041666667 | 16344 |
| 014556 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596629.6 | 512268.0 | 82348 | 1.64041666667 | 14556 |
| 013239 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596630.3 | 512265.3 | 82350 | 1.64041666667 | 13239 |
| 012849 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596631.7 | 512262.6 | 82352 | 1.64041666667 | 12849 |
| 013382 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596632.0 | 512262.3 | 82354 | 1.64041666667 | 13382 |
| 014325 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596632.1 | 512262.3 | 82356 | 1.64041666667 | 14325 |
| 014921 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596631.9 | 512262.6 | 82358 | 1.64041666667 | 14921 |
| 014440 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596630.8 | 512263.3 | 82360 | 1.64041666667 | 14440 |
| 013480 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596630.6 | 512263.8 | 82362 | 1.64041666667 | 13480 |
| 012430 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596631.7 | 512265.4 | 82364 | 1.64041666667 | 12430 |
| 014987 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596631.0 | 512267.0 | 82366 | 1.64041666667 | 14987 |
| 013856 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596630.2 | 512269.3 | 82368 | 1.64041666667 | 13856 |
| 015464 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596628.9 | 512270.7 | 82370 | 1.64041666667 | 15464 |
| 014156 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596627.6 | 512270.7 | 82372 | 1.64041666667 | 14156 |
| 013229 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596626.0 | 512270.0 | 82374 | 1.64041666667 | 13229 |
| 012787 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596623.1 | 512268.7 | 82376 | 1.64041666667 | 12787 |
| 013666 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596621.0 | 512268.7 | 82378 | 1.64041666667 | 13666 |
| 013526 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596618.9 | 512268.4 | 82380 | 1.64041666667 | 13526 |
| 013581 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596616.4 | 512268.3 | 82382 | 1.64041666667 | 13581 |
| 014495 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596614.1 | 512267.0 | 82384 | 1.64041666667 | 14495 |
| 013613 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596611.7 | 512266.7 | 82386 | 1.64041666667 | 13613 |
| 013153 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596609.8 | 512265.3 | 82388 | 1.64041666667 | 13153 |
| 013368 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596607.6 | 512264.5 | 82390 | 1.64041666667 | 13368 |
| 015492 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596605.5 | 512262.8 | 82392 | 1.64041666667 | 15492 |
| 013833 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596603.2 | 512262.5 | 82394 | 1.64041666667 | 13833 |
| 012578 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596600.8 | 512261.3 | 82396 | 1.64041666667 | 12578 |
| 012354 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596598.3 | 512261.1 | 82398 | 1.64041666667 | 12354 |
| 012118 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:42am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596595.6 | 512260.2 | 82400 | 1.64041666667 | 12118 |
| 013889 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596593.8 | 512259.7 | 82402 | 1.64041666667 | 13889 |
| 013342 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596591.7 | 512258.1 | 82404 | 1.64041666667 | 13342 |
| 013535 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596589.9 | 512256.6 | 82406 | 1.64041666667 | 13535 |
| 011543 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596587.8 | 512255.1 | 82408 | 1.64041666667 | 11543 |
| 012966 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596585.8 | 512253.9 | 82410 | 1.64041666667 | 12966 |
| 013111 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596583.4 | 512253.4 | 82412 | 1.64041666667 | 13111 |
| 012667 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596581.3 | 512252.1 | 82414 | 1.64041666667 | 12667 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013517 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596578.7 | 512250.9 | 82416 | 1.64041666667 | 13517 |
| 013399 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:51am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596577.4 | 512248.7 | 82418 | 1.64041666667 | 13399 |
| 012559 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:52am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596574.9 | 512247.4 | 82420 | 1.64041666667 | 12559 |
| 012740 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596573.3 | 512246.1 | 82422 | 1.64041666667 | 12740 |
| 012515 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:54am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596570.9 | 512245.5 | 82424 | 1.64041666667 | 12515 |
| 011738 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:55am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596569.1 | 512244.4 | 82426 | 1.64041666667 | 11738 |
| 014544 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596567.5 | 512243.7 | 82428 | 1.64041666667 | 14544 |
| 013716 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:57am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596567.2 | 512242.0 | 82430 | 1.64041666667 | 13716 |
| 013029 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596565.7 | 512239.8 | 82432 | 1.64041666667 | 13029 |
| 013187 | 0 | GeoXH 6000 | 08/20/2015 | 11:16:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596564.8 | 512237.6 | 82434 | 1.64041666667 | 13187 |
| 012986 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:00am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596562.9 | 512235.5 | 82436 | 1.64041666667 | 12986 |
| 012816 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596560.3 | 512234.2 | 82438 | 1.64041666667 | 12816 |
| 012054 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:02am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596558.6 | 512232.8 | 82440 | 1.64041666667 | 12054 |
| 012223 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596556.8 | 512232.9 | 82442 | 1.64041666667 | 12223 |
| 015416 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:04am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596554.1 | 512233.1 | 82444 | 1.64041666667 | 15416 |
| 014054 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:05am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596551.7 | 512234.2 | 82446 | 1.64041666667 | 14054 |
| 012303 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:06am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596548.8 | 512234.2 | 82448 | 1.64041666667 | 12303 |
| 014295 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:07am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596546.6 | 512234.5 | 82450 | 1.64041666667 | 14295 |
| 014523 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:08am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596544.2 | 512233.7 | 82452 | 1.64041666667 | 14523 |
| 013921 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596542.3 | 512234.2 | 82454 | 1.64041666667 | 13921 |
| 013920 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:10am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596540.3 | 512233.3 | 82456 | 1.64041666667 | 13920 |
| 013770 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:11am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596538.7 | 512233.3 | 82458 | 1.64041666667 | 13770 |
| 014902 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:12am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596537.5 | 512233.0 | 82460 | 1.64041666667 | 14902 |
| 013775 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:13am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596537.3 | 512232.2 | 82462 | 1.64041666667 | 13775 |
| 013524 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:14am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596537.3 | 512232.2 | 82464 | 1.64041666667 | 13524 |
| 013341 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:15am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596537.3 | 512232.1 | 82466 | 1.64041666667 | 13341 |
| 013595 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:16am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596537.3 | 512232.0 | 82468 | 1.64041666667 | 13595 |
| 013778 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:17am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596536.5 | 512231.2 | 82470 | 1.64041666667 | 13778 |
| 012384 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:18am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596535.0 | 512229.7 | 82472 | 1.64041666667 | 12384 |
| 014706 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:19am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596533.5 | 512227.8 | 82474 | 1.64041666667 | 14706 |
| 013456 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:20am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596531.2 | 512225.6 | 82476 | 1.64041666667 | 13456 |
| 013654 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:21am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596529.0 | 512224.7 | 82478 | 1.64041666667 | 13654 |
| 012533 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:22am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596527.3 | 512223.4 | 82480 | 1.64041666667 | 12533 |
| 013783 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:23am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596526.1 | 512222.4 | 82482 | 1.64041666667 | 13783 |
| 014696 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:24am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596526.6 | 512222.7 | 82484 | 1.64041666667 | 14696 |
| 013034 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:25am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596528.3 | 512221.0 | 82486 | 1.64041666667 | 13034 |
| 012588 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:26am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596529.3 | 512218.9 | 82488 | 1.64041666667 | 12588 |
| 013887 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:27am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596529.7 | 512218.6 | 82490 | 1.64041666667 | 13887 |
| 013701 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:28am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596530.2 | 512218.7 | 82492 | 1.64041666667 | 13701 |
| 013415 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:29am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596530.6 | 512217.8 | 82494 | 1.64041666667 | 13415 |
| 014183 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:30am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596532.3 | 512215.3 | 82496 | 1.64041666667 | 14183 |
| 014346 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:31am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596533.8 | 512213.4 | 82498 | 1.64041666667 | 14346 |
| 012466 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:32am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596535.0 | 512212.6 | 82500 | 1.64041666667 | 12466 |
| 013856 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:33am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596534.7 | 512212.3 | 82502 | 1.64041666667 | 13856 |
| 014294 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:34am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596535.1 | 512212.1 | 82504 | 1.64041666667 | 14294 |
| 014373 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:35am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596535.9 | 512211.1 | 82506 | 1.64041666667 | 14373 |
| 014243 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:36am | Sensor | 1797-S0052-G-TJV.cor | 6847.6 | 1596536.2 | 512210.7 | 82508 | 1.64041666667 | 14243 |
| 013880 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:37am | Sensor | 1797-S0052-G-TJV.cor | 6847.5 | 1596536.2 | 512210.7 | 82510 | 1.64041666667 | 13880 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014390 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:38am | Sensor | 1797-S0052-G-TJV.cor | 6847.4 | 1596536.3 | 512210.6 | 82512 | 1.64041666667 | 14390 |
| 015087 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:39am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596535.5 | 512211.5 | 82514 | 1.64041666667 | 15087 |
| 013702 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:40am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596533.7 | 512212.3 | 82516 | 1.64041666667 | 13702 |
| 013505 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:41am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596533.2 | 512213.2 | 82518 | 1.64041666667 | 13505 |
| 012496 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:42am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596532.6 | 512215.1 | 82520 | 1.64041666667 | 12496 |
| 011884 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596532.1 | 512216.9 | 82522 | 1.64041666667 | 11884 |
| 011551 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:44am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596530.9 | 512218.5 | 82524 | 1.64041666667 | 11551 |
| 015337 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596530.7 | 512218.5 | 82526 | 1.64041666667 | 15337 |
| 013164 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596530.6 | 512218.8 | 82528 | 1.64041666667 | 13164 |
| 014001 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596531.2 | 512218.8 | 82530 | 1.64041666667 | 14001 |
| 013490 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596533.4 | 512219.8 | 82532 | 1.64041666667 | 13490 |
| 012492 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596535.7 | 512220.8 | 82534 | 1.64041666667 | 12492 |
| 013203 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596538.3 | 512222.2 | 82536 | 1.64041666667 | 13203 |
| 012240 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:51am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596540.8 | 512222.6 | 82538 | 1.64041666667 | 12240 |
| 013890 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:52am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596543.3 | 512223.9 | 82540 | 1.64041666667 | 13890 |
| 013582 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:53am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596545.8 | 512224.5 | 82542 | 1.64041666667 | 13582 |
| 012995 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:54am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596547.8 | 512226.0 | 82544 | 1.64041666667 | 12995 |
| 013479 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596549.8 | 512226.9 | 82546 | 1.64041666667 | 13479 |
| 014229 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596551.5 | 512228.6 | 82548 | 1.64041666667 | 14229 |
| 013337 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596553.7 | 512229.4 | 82550 | 1.64041666667 | 13337 |
| 014014 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:58am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596555.9 | 512230.6 | 82552 | 1.64041666667 | 14014 |
| 011693 | 0 | GeoXH 6000 | 08/20/2015 | 11:17:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596558.0 | 512232.0 | 82554 | 1.64041666667 | 11693 |
| 012793 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:00am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596560.0 | 512233.3 | 82556 | 1.64041666667 | 12793 |
| 012288 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:01am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596562.1 | 512235.0 | 82558 | 1.64041666667 | 12288 |
| 011802 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:02am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596564.5 | 512236.4 | 82560 | 1.64041666667 | 11802 |
| 011650 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:03am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596565.7 | 512238.4 | 82562 | 1.64041666667 | 11650 |
| 012362 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:04am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596567.8 | 512240.3 | 82564 | 1.64041666667 | 12362 |
| 012180 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:05am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596569.2 | 512242.5 | 82566 | 1.64041666667 | 12180 |
| 013065 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:06am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596571.5 | 512244.2 | 82568 | 1.64041666667 | 13065 |
| 013916 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:07am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596573.4 | 512245.6 | 82570 | 1.64041666667 | 13916 |
| 013229 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:08am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596576.4 | 512245.8 | 82572 | 1.64041666667 | 13229 |
| 012097 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:09am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596578.9 | 512246.1 | 82574 | 1.64041666667 | 12097 |
| 013044 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596581.1 | 512247.0 | 82576 | 1.64041666667 | 13044 |
| 013401 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596583.7 | 512247.0 | 82578 | 1.64041666667 | 13401 |
| 016910 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596586.3 | 512247.5 | 82580 | 1.64041666667 | 16910 |
| 012837 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596589.0 | 512247.1 | 82582 | 1.64041666667 | 12837 |
| 013619 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596591.2 | 512247.7 | 82584 | 1.64041666667 | 13619 |
| 014955 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596593.6 | 512247.6 | 82586 | 1.64041666667 | 14955 |
| 014238 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596595.5 | 512248.8 | 82588 | 1.64041666667 | 14238 |
| 013639 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596597.6 | 512249.6 | 82590 | 1.64041666667 | 13639 |
| 013489 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596599.6 | 512250.7 | 82592 | 1.64041666667 | 13489 |
| 013782 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596602.0 | 512251.1 | 82594 | 1.64041666667 | 13782 |
| 013225 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596603.4 | 512252.4 | 82596 | 1.64041666667 | 13225 |
| 013056 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596605.9 | 512252.2 | 82598 | 1.64041666667 | 13056 |
| 012684 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596608.1 | 512253.7 | 82600 | 1.64041666667 | 12684 |
| 013062 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596610.6 | 512253.5 | 82602 | 1.64041666667 | 13062 |
| 013377 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596612.1 | 512255.0 | 82604 | 1.64041666667 | 13377 |
| 013004 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596614.3 | 512255.5 | 82606 | 1.64041666667 | 13004 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013361 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596616.4 | 512257.3 | 82608 | 1.64041666667 | 13361 |
| 012520 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596618.6 | 512258.6 | 82610 | 1.64041666667 | 12520 |
| 013690 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596621.4 | 512259.9 | 82612 | 1.64041666667 | 13690 |
| 014102 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596623.4 | 512260.5 | 82614 | 1.64041666667 | 14102 |
| 013125 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596626.4 | 512261.0 | 82616 | 1.64041666667 | 13125 |
| 011951 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596628.2 | 512261.8 | 82618 | 1.64041666667 | 11951 |
| 013818 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596631.4 | 512261.8 | 82620 | 1.64041666667 | 13818 |
| 013894 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596630.6 | 512262.6 | 82622 | 1.64041666667 | 13894 |
| 014393 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596630.3 | 512261.5 | 82624 | 1.64041666667 | 14393 |
| 012598 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596632.0 | 512259.8 | 82626 | 1.64041666667 | 12598 |
| 013679 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:36am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596633.1 | 512256.8 | 82628 | 1.64041666667 | 13679 |
| 013530 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:37am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596633.3 | 512256.6 | 82630 | 1.64041666667 | 13530 |
| 013792 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:38am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596633.1 | 512256.6 | 82632 | 1.64041666667 | 13792 |
| 013408 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596634.5 | 512256.0 | 82634 | 1.64041666667 | 13408 |
| 013372 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596637.2 | 512253.2 | 82636 | 1.64041666667 | 13372 |
| 012463 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:41am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596639.1 | 512251.9 | 82638 | 1.64041666667 | 12463 |
| 012775 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596641.4 | 512250.3 | 82640 | 1.64041666667 | 12775 |
| 013784 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596641.5 | 512250.2 | 82642 | 1.64041666667 | 13784 |
| 012896 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596641.5 | 512250.2 | 82644 | 1.64041666667 | 12896 |
| 012374 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596640.8 | 512250.7 | 82646 | 1.64041666667 | 12374 |
| 013563 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596641.6 | 512250.1 | 82648 | 1.64041666667 | 13563 |
| 013260 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596641.7 | 512250.2 | 82650 | 1.64041666667 | 13260 |
| 012525 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596641.6 | 512250.4 | 82652 | 1.64041666667 | 12525 |
| 011621 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596639.3 | 512251.4 | 82654 | 1.64041666667 | 11621 |
| 013945 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:50am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596637.7 | 512253.7 | 82656 | 1.64041666667 | 13945 |
| 012306 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:51am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596635.9 | 512255.2 | 82658 | 1.64041666667 | 12306 |
| 012766 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:52am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596633.6 | 512255.7 | 82660 | 1.64041666667 | 12766 |
| 013451 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596631.1 | 512255.4 | 82662 | 1.64041666667 | 13451 |
| 013263 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596629.1 | 512253.4 | 82664 | 1.64041666667 | 13263 |
| 014715 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596627.0 | 512252.3 | 82666 | 1.64041666667 | 14715 |
| 012588 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596625.2 | 512250.6 | 82668 | 1.64041666667 | 12588 |
| 012387 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596623.3 | 512249.2 | 82670 | 1.64041666667 | 12387 |
| 012967 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596622.5 | 512248.3 | 82672 | 1.64041666667 | 12967 |
| 013471 | 0 | GeoXH 6000 | 08/20/2015 | 11:18:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596621.0 | 512247.3 | 82674 | 1.64041666667 | 13471 |
| 012877 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596618.7 | 512246.6 | 82676 | 1.64041666667 | 12877 |
| 012969 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596616.6 | 512245.9 | 82678 | 1.64041666667 | 12969 |
| 012212 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596614.7 | 512245.0 | 82680 | 1.64041666667 | 12212 |
| 014093 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596612.5 | 512243.6 | 82682 | 1.64041666667 | 14093 |
| 016123 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596609.7 | 512243.1 | 82684 | 1.64041666667 | 16123 |
| 012941 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596608.0 | 512242.2 | 82686 | 1.64041666667 | 12941 |
| 014545 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596605.4 | 512241.4 | 82688 | 1.64041666667 | 14545 |
| 015666 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596603.2 | 512240.1 | 82690 | 1.64041666667 | 15666 |
| 014626 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596600.3 | 512239.6 | 82692 | 1.64041666667 | 14626 |
| 011876 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596598.5 | 512238.6 | 82694 | 1.64041666667 | 11876 |
| 013949 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596595.4 | 512237.9 | 82696 | 1.64041666667 | 13949 |
| 011677 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596593.8 | 512236.7 | 82698 | 1.64041666667 | 11677 |
| 014319 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596591.1 | 512235.6 | 82700 | 1.64041666667 | 14319 |
| 013209 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:13am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596589.4 | 512234.4 | 82702 | 1.64041666667 | 13209 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013382 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:14am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596586.8 | 512233.6 | 82704 | 1.64041666667 | 13382 |
| 014145 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:15am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596584.5 | 512232.3 | 82706 | 1.64041666667 | 14145 |
| 013016 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596582.1 | 512232.1 | 82708 | 1.64041666667 | 13016 |
| 013034 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596580.6 | 512231.3 | 82710 | 1.64041666667 | 13034 |
| 014748 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596578.3 | 512231.5 | 82712 | 1.64041666667 | 14748 |
| 013557 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596576.8 | 512229.9 | 82714 | 1.64041666667 | 13557 |
| 012509 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596573.6 | 512229.3 | 82716 | 1.64041666667 | 12509 |
| 013717 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596572.0 | 512228.3 | 82718 | 1.64041666667 | 13717 |
| 014439 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596569.2 | 512227.7 | 82720 | 1.64041666667 | 14439 |
| 013119 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596566.6 | 512226.9 | 82722 | 1.64041666667 | 13119 |
| 014020 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596563.7 | 512225.1 | 82724 | 1.64041666667 | 14020 |
| 014845 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596561.1 | 512224.0 | 82726 | 1.64041666667 | 14845 |
| 014061 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596559.2 | 512222.2 | 82728 | 1.64041666667 | 14061 |
| 013085 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596556.7 | 512221.3 | 82730 | 1.64041666667 | 13085 |
| 012871 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596554.8 | 512219.7 | 82732 | 1.64041666667 | 12871 |
| 012667 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596552.2 | 512219.0 | 82734 | 1.64041666667 | 12667 |
| 013787 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596549.7 | 512217.8 | 82736 | 1.64041666667 | 13787 |
| 013916 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:31am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596546.9 | 512217.0 | 82738 | 1.64041666667 | 13916 |
| 013169 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:32am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596543.8 | 512215.9 | 82740 | 1.64041666667 | 13169 |
| 014062 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:33am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596541.4 | 512214.6 | 82742 | 1.64041666667 | 14062 |
| 014045 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596538.7 | 512213.7 | 82744 | 1.64041666667 | 14045 |
| 012871 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:35am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596537.3 | 512212.2 | 82746 | 1.64041666667 | 12871 |
| 013597 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:36am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596536.2 | 512211.2 | 82748 | 1.64041666667 | 13597 |
| 013299 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596537.4 | 512210.0 | 82750 | 1.64041666667 | 13299 |
| 012925 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596538.5 | 512207.1 | 82752 | 1.64041666667 | 12925 |
| 014301 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596539.1 | 512206.1 | 82754 | 1.64041666667 | 14301 |
| 013895 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596539.1 | 512205.8 | 82756 | 1.64041666667 | 13895 |
| 014063 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596539.1 | 512205.4 | 82758 | 1.64041666667 | 14063 |
| 013206 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596539.2 | 512205.2 | 82760 | 1.64041666667 | 13206 |
| 015811 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596540.8 | 512203.5 | 82762 | 1.64041666667 | 15811 |
| 014122 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596542.8 | 512201.1 | 82764 | 1.64041666667 | 14122 |
| 013790 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:45am | Sensor | 1797-S0052-G-TJV.cor | 6848.6 | 1596544.7 | 512199.0 | 82766 | 1.64041666667 | 13790 |
| 015417 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:46am | Sensor | 1797-S0052-G-TJV.cor | 6848.4 | 1596545.2 | 512198.7 | 82768 | 1.64041666667 | 15417 |
| 013814 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:47am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596545.1 | 512198.7 | 82770 | 1.64041666667 | 13814 |
| 015123 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:48am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596545.2 | 512198.7 | 82772 | 1.64041666667 | 15123 |
| 014520 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:49am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596544.8 | 512198.8 | 82774 | 1.64041666667 | 14520 |
| 013980 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:50am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596542.7 | 512199.5 | 82776 | 1.64041666667 | 13980 |
| 014895 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596542.5 | 512201.0 | 82778 | 1.64041666667 | 14895 |
| 013533 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596541.4 | 512202.7 | 82780 | 1.64041666667 | 13533 |
| 014213 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596540.4 | 512204.8 | 82782 | 1.64041666667 | 14213 |
| 013513 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596539.5 | 512206.0 | 82784 | 1.64041666667 | 13513 |
| 014178 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596539.2 | 512206.2 | 82786 | 1.64041666667 | 14178 |
| 014194 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596539.2 | 512206.2 | 82788 | 1.64041666667 | 14194 |
| 012938 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596540.1 | 512206.4 | 82790 | 1.64041666667 | 12938 |
| 013344 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:58am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596541.6 | 512207.1 | 82792 | 1.64041666667 | 13344 |
| 014046 | 0 | GeoXH 6000 | 08/20/2015 | 11:19:59am | Sensor | 1797-S0052-G-TJV.cor | 6848.9 | 1596543.6 | 512208.3 | 82794 | 1.64041666667 | 14046 |
| 014011 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596546.0 | 512210.1 | 82796 | 1.64041666667 | 14011 |
| 014272 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596548.5 | 512211.1 | 82798 | 1.64041666667 | 14272 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012118 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596550.8 | 512212.5 | 82800 | 1.64041666667 | 12118 |
| 012899 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596553.4 | 512213.3 | 82802 | 1.64041666667 | 12899 |
| 013485 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596556.0 | 512214.5 | 82804 | 1.64041666667 | 13485 |
| 014951 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596558.4 | 512215.6 | 82806 | 1.64041666667 | 14951 |
| 012587 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596560.9 | 512216.8 | 82808 | 1.64041666667 | 12587 |
| 013946 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596563.2 | 512217.9 | 82810 | 1.64041666667 | 13946 |
| 013326 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596565.7 | 512218.5 | 82812 | 1.64041666667 | 13326 |
| 012361 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596567.4 | 512219.2 | 82814 | 1.64041666667 | 12361 |
| 012780 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596570.3 | 512219.9 | 82816 | 1.64041666667 | 12780 |
| 014445 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596573.0 | 512220.9 | 82818 | 1.64041666667 | 14445 |
| 013841 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596575.6 | 512220.6 | 82820 | 1.64041666667 | 13841 |
| 014890 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596577.0 | 512221.8 | 82822 | 1.64041666667 | 14890 |
| 013952 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596579.4 | 512223.2 | 82824 | 1.64041666667 | 13952 |
| 015668 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596581.8 | 512224.3 | 82826 | 1.64041666667 | 15668 |
| 016427 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596584.2 | 512224.8 | 82828 | 1.64041666667 | 16427 |
| 014276 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596586.9 | 512225.2 | 82830 | 1.64041666667 | 14276 |
| 012119 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596589.4 | 512226.3 | 82832 | 1.64041666667 | 12119 |
| 013050 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596591.7 | 512226.9 | 82834 | 1.64041666667 | 13050 |
| 013822 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596593.3 | 512228.5 | 82836 | 1.64041666667 | 13822 |
| 012275 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596595.3 | 512230.0 | 82838 | 1.64041666667 | 12275 |
| 011618 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596596.5 | 512231.5 | 82840 | 1.64041666667 | 11618 |
| 012354 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596598.5 | 512230.9 | 82842 | 1.64041666667 | 12354 |
| 013408 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596601.1 | 512231.4 | 82844 | 1.64041666667 | 13408 |
| 012802 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596603.7 | 512232.1 | 82846 | 1.64041666667 | 12802 |
| 014120 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596606.4 | 512233.4 | 82848 | 1.64041666667 | 14120 |
| 012770 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596608.8 | 512235.0 | 82850 | 1.64041666667 | 12770 |
| 014412 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596611.6 | 512236.3 | 82852 | 1.64041666667 | 14412 |
| 014493 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596613.6 | 512237.7 | 82854 | 1.64041666667 | 14493 |
| 012863 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:30am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596616.4 | 512238.3 | 82856 | 1.64041666667 | 12863 |
| 013025 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596618.3 | 512239.6 | 82858 | 1.64041666667 | 13025 |
| 012886 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:32am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596621.0 | 512240.9 | 82860 | 1.64041666667 | 12886 |
| 013391 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:33am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596623.1 | 512242.5 | 82862 | 1.64041666667 | 13391 |
| 013758 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:34am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596625.6 | 512244.0 | 82864 | 1.64041666667 | 13758 |
| 013459 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596627.6 | 512245.3 | 82866 | 1.64041666667 | 13459 |
| 013144 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:36am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596630.1 | 512247.2 | 82868 | 1.64041666667 | 13144 |
| 013126 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:37am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596632.4 | 512248.2 | 82870 | 1.64041666667 | 13126 |
| 012821 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:38am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596634.9 | 512249.5 | 82872 | 1.64041666667 | 12821 |
| 013195 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:39am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596637.3 | 512249.8 | 82874 | 1.64041666667 | 13195 |
| 012449 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596640.4 | 512249.9 | 82876 | 1.64041666667 | 12449 |
| 011632 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:41am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596639.8 | 512250.0 | 82878 | 1.64041666667 | 11632 |
| 012058 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:42am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596641.1 | 512248.3 | 82880 | 1.64041666667 | 12058 |
| 012134 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:43am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596641.7 | 512246.2 | 82882 | 1.64041666667 | 12134 |
| 012453 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:44am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596641.8 | 512245.0 | 82884 | 1.64041666667 | 12453 |
| 014333 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:45am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596641.8 | 512244.9 | 82886 | 1.64041666667 | 14333 |
| 014293 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:46am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596643.3 | 512243.3 | 82888 | 1.64041666667 | 14293 |
| 015183 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:47am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596644.5 | 512241.1 | 82890 | 1.64041666667 | 15183 |
| 014205 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:48am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596646.6 | 512239.3 | 82892 | 1.64041666667 | 14205 |
| 014171 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:49am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596647.4 | 512238.9 | 82894 | 1.64041666667 | 14171 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012723 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:50am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596647.0 | 512239.7 | 82896 | 1.64041666667 | 12723 |
| 014640 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:51am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596646.2 | 512240.4 | 82898 | 1.64041666667 | 14640 |
| 016500 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:52am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596644.5 | 512242.1 | 82900 | 1.64041666667 | 16500 |
| 014325 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:53am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596642.5 | 512243.0 | 82902 | 1.64041666667 | 14325 |
| 014081 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:54am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596639.3 | 512243.6 | 82904 | 1.64041666667 | 14081 |
| 014350 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:55am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596636.7 | 512242.4 | 82906 | 1.64041666667 | 14350 |
| 012917 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:56am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596634.0 | 512241.2 | 82908 | 1.64041666667 | 12917 |
| 012799 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596632.0 | 512240.0 | 82910 | 1.64041666667 | 12799 |
| 013669 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:58am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596629.5 | 512238.2 | 82912 | 1.64041666667 | 13669 |
| 012957 | 0 | GeoXH 6000 | 08/20/2015 | 11:20:59am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596626.9 | 512237.5 | 82914 | 1.64041666667 | 12957 |
| 014339 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:00am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596624.3 | 512236.5 | 82916 | 1.64041666667 | 14339 |
| 013875 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:01am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596621.4 | 512236.3 | 82918 | 1.64041666667 | 13875 |
| 013998 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:02am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596618.6 | 512235.4 | 82920 | 1.64041666667 | 13998 |
| 013429 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:03am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596616.4 | 512235.5 | 82922 | 1.64041666667 | 13429 |
| 014067 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596613.7 | 512234.5 | 82924 | 1.64041666667 | 14067 |
| 014677 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596611.2 | 512233.0 | 82926 | 1.64041666667 | 14677 |
| 012789 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596608.2 | 512231.8 | 82928 | 1.64041666667 | 12789 |
| 012437 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596606.1 | 512230.3 | 82930 | 1.64041666667 | 12437 |
| 013279 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596603.7 | 512229.7 | 82932 | 1.64041666667 | 13279 |
| 013459 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596601.5 | 512228.4 | 82934 | 1.64041666667 | 13459 |
| 013835 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596598.7 | 512227.3 | 82936 | 1.64041666667 | 13835 |
| 012998 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596596.2 | 512226.0 | 82938 | 1.64041666667 | 12998 |
| 012699 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596593.8 | 512224.5 | 82940 | 1.64041666667 | 12699 |
| 014035 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596591.8 | 512223.6 | 82942 | 1.64041666667 | 14035 |
| 014428 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596589.1 | 512222.2 | 82944 | 1.64041666667 | 14428 |
| 012907 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596586.8 | 512221.1 | 82946 | 1.64041666667 | 12907 |
| 013486 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596584.8 | 512219.4 | 82948 | 1.64041666667 | 13486 |
| 012581 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:17am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596582.8 | 512218.8 | 82950 | 1.64041666667 | 12581 |
| 013615 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596581.1 | 512217.4 | 82952 | 1.64041666667 | 13615 |
| 012614 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.7 | 512216.6 | 82954 | 1.64041666667 | 12614 |
| 013233 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596576.7 | 512215.3 | 82956 | 1.64041666667 | 13233 |
| 013058 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596574.6 | 512214.2 | 82958 | 1.64041666667 | 13058 |
| 013944 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596572.0 | 512212.7 | 82960 | 1.64041666667 | 13944 |
| 014136 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596569.6 | 512212.1 | 82962 | 1.64041666667 | 14136 |
| 013344 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596566.7 | 512211.4 | 82964 | 1.64041666667 | 13344 |
| 014436 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596564.1 | 512210.4 | 82966 | 1.64041666667 | 14436 |
| 014169 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596561.1 | 512209.3 | 82968 | 1.64041666667 | 14169 |
| 014432 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596558.9 | 512207.7 | 82970 | 1.64041666667 | 14432 |
| 013718 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596556.2 | 512206.5 | 82972 | 1.64041666667 | 13718 |
| 012369 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596553.5 | 512205.3 | 82974 | 1.64041666667 | 12369 |
| 013202 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596550.6 | 512203.6 | 82976 | 1.64041666667 | 13202 |
| 013200 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596548.3 | 512202.1 | 82978 | 1.64041666667 | 13200 |
| 014010 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596546.9 | 512200.0 | 82980 | 1.64041666667 | 14010 |
| 015112 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.0 | 1596545.1 | 512198.3 | 82982 | 1.64041666667 | 15112 |
| 014098 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596545.4 | 512198.2 | 82984 | 1.64041666667 | 14098 |
| 013724 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596547.1 | 512197.0 | 82986 | 1.64041666667 | 13724 |
| 015101 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596549.1 | 512195.4 | 82988 | 1.64041666667 | 15101 |
| 013615 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596550.4 | 512194.7 | 82990 | 1.64041666667 | 13615 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015433 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596550.2 | 512194.8 | 82992 | 1.64041666667 | 15433 |
| 015438 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596550.8 | 512194.0 | 82994 | 1.64041666667 | 15438 |
| 012649 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596553.1 | 512191.8 | 82996 | 1.64041666667 | 12649 |
| 012942 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596555.2 | 512189.5 | 82998 | 1.64041666667 | 12942 |
| 013855 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:42am | Sensor | 1797-S0052-G-TJV.cor | 6848.7 | 1596556.4 | 512188.4 | 83000 | 1.64041666667 | 13855 |
| 013844 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:43am | Sensor | 1797-S0052-G-TJV.cor | 6848.8 | 1596556.4 | 512188.4 | 83002 | 1.64041666667 | 13844 |
| 013931 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596555.4 | 512189.7 | 83004 | 1.64041666667 | 13931 |
| 014072 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596555.1 | 512190.1 | 83006 | 1.64041666667 | 14072 |
| 014558 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596555.0 | 512190.2 | 83008 | 1.64041666667 | 14558 |
| 014019 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596555.0 | 512190.1 | 83010 | 1.64041666667 | 14019 |
| 014035 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512190.0 | 83012 | 1.64041666667 | 14035 |
| 013978 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512190.1 | 83014 | 1.64041666667 | 13978 |
| 013784 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:50am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512190.1 | 83016 | 1.64041666667 | 13784 |
| 014756 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512190.1 | 83018 | 1.64041666667 | 14756 |
| 014459 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596554.9 | 512190.1 | 83020 | 1.64041666667 | 14459 |
| 013874 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512189.9 | 83022 | 1.64041666667 | 13874 |
| 014268 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.1 | 512189.8 | 83024 | 1.64041666667 | 14268 |
| 013527 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.1 | 512189.8 | 83026 | 1.64041666667 | 13527 |
| 013281 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.2 | 512189.8 | 83028 | 1.64041666667 | 13281 |
| 014270 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.1 | 512189.9 | 83030 | 1.64041666667 | 14270 |
| 013707 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.1 | 512189.9 | 83032 | 1.64041666667 | 13707 |
| 013237 | 0 | GeoXH 6000 | 08/20/2015 | 11:21:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512189.9 | 83034 | 1.64041666667 | 13237 |
| 012909 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512190.0 | 83036 | 1.64041666667 | 12909 |
| 014837 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512190.0 | 83038 | 1.64041666667 | 14837 |
| 015139 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512190.1 | 83040 | 1.64041666667 | 15139 |
| 013564 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.0 | 512190.2 | 83042 | 1.64041666667 | 13564 |
| 012751 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.1 | 512190.2 | 83044 | 1.64041666667 | 12751 |
| 012697 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596555.2 | 512189.5 | 83046 | 1.64041666667 | 12697 |
| 012984 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596554.6 | 512189.4 | 83048 | 1.64041666667 | 12984 |
| 013326 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596554.6 | 512189.8 | 83050 | 1.64041666667 | 13326 |
| 014191 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596554.1 | 512191.3 | 83052 | 1.64041666667 | 14191 |
| 013897 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596553.0 | 512192.4 | 83054 | 1.64041666667 | 13897 |
| 014154 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596552.2 | 512194.0 | 83056 | 1.64041666667 | 14154 |
| 014068 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596551.7 | 512194.4 | 83058 | 1.64041666667 | 14068 |
| 014647 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596550.2 | 512194.5 | 83060 | 1.64041666667 | 14647 |
| 013831 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596548.3 | 512194.2 | 83062 | 1.64041666667 | 13831 |
| 013117 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596546.3 | 512192.8 | 83064 | 1.64041666667 | 13117 |
| 014358 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596545.7 | 512191.2 | 83066 | 1.64041666667 | 14358 |
| 012400 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596546.1 | 512189.8 | 83068 | 1.64041666667 | 12400 |
| 012700 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596546.8 | 512190.9 | 83070 | 1.64041666667 | 12700 |
| 014575 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596548.9 | 512192.8 | 83072 | 1.64041666667 | 14575 |
| 012973 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596551.0 | 512194.3 | 83074 | 1.64041666667 | 12973 |
| 012033 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596553.9 | 512196.1 | 83076 | 1.64041666667 | 12033 |
| 013628 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596556.6 | 512197.0 | 83078 | 1.64041666667 | 13628 |
| 012737 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596559.5 | 512198.4 | 83080 | 1.64041666667 | 12737 |
| 014314 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596562.3 | 512198.9 | 83082 | 1.64041666667 | 14314 |
| 014018 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596565.4 | 512199.8 | 83084 | 1.64041666667 | 14018 |
| 013764 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596568.2 | 512201.0 | 83086 | 1.64041666667 | 13764 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013341 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596571.8 | 512202.1 | 83088 | 1.64041666667 | 13341 |
| 014555 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596574.1 | 512203.5 | 83090 | 1.64041666667 | 14555 |
| 012848 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596577.2 | 512204.8 | 83092 | 1.64041666667 | 12848 |
| 014282 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596579.5 | 512206.1 | 83094 | 1.64041666667 | 14282 |
| 012840 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596582.8 | 512207.8 | 83096 | 1.64041666667 | 12840 |
| 015270 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596585.4 | 512208.8 | 83098 | 1.64041666667 | 15270 |
| 013927 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596588.3 | 512210.4 | 83100 | 1.64041666667 | 13927 |
| 014372 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596591.2 | 512211.3 | 83102 | 1.64041666667 | 14372 |
| 012653 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596594.3 | 512212.6 | 83104 | 1.64041666667 | 12653 |
| 014653 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596597.1 | 512214.2 | 83106 | 1.64041666667 | 14653 |
| 014433 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596600.3 | 512215.4 | 83108 | 1.64041666667 | 14433 |
| 013298 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596602.6 | 512216.8 | 83110 | 1.64041666667 | 13298 |
| 013944 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:38am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596605.5 | 512218.3 | 83112 | 1.64041666667 | 13944 |
| 014976 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:39am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596608.2 | 512219.9 | 83114 | 1.64041666667 | 14976 |
| 016224 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:40am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596611.2 | 512221.6 | 83116 | 1.64041666667 | 16224 |
| 013746 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:41am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596613.9 | 512222.4 | 83118 | 1.64041666667 | 13746 |
| 015316 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:42am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596616.8 | 512223.7 | 83120 | 1.64041666667 | 15316 |
| 013909 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:43am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596619.9 | 512224.7 | 83122 | 1.64041666667 | 13909 |
| 013077 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:44am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596623.2 | 512225.5 | 83124 | 1.64041666667 | 13077 |
| 012389 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:45am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596625.8 | 512226.6 | 83126 | 1.64041666667 | 12389 |
| 013897 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:46am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596629.0 | 512227.9 | 83128 | 1.64041666667 | 13897 |
| 012954 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:47am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596631.2 | 512229.8 | 83130 | 1.64041666667 | 12954 |
| 010978 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:48am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596634.3 | 512231.3 | 83132 | 1.64041666667 | 10978 |
| 011684 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:49am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596637.4 | 512232.0 | 83134 | 1.64041666667 | 11684 |
| 012611 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:50am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596640.1 | 512233.9 | 83136 | 1.64041666667 | 12611 |
| 012842 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:51am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596642.2 | 512234.7 | 83138 | 1.64041666667 | 12842 |
| 013650 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:52am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596644.6 | 512235.9 | 83140 | 1.64041666667 | 13650 |
| 013012 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:53am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596645.9 | 512237.1 | 83142 | 1.64041666667 | 13012 |
| 012523 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:54am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596646.8 | 512236.7 | 83144 | 1.64041666667 | 12523 |
| 012341 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:55am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596648.9 | 512235.3 | 83146 | 1.64041666667 | 12341 |
| 012205 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:56am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596651.1 | 512232.7 | 83148 | 1.64041666667 | 12205 |
| 013101 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:57am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596651.6 | 512231.1 | 83150 | 1.64041666667 | 13101 |
| 012665 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:58am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596651.2 | 512230.5 | 83152 | 1.64041666667 | 12665 |
| 013156 | 0 | GeoXH 6000 | 08/20/2015 | 11:22:59am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596652.3 | 512229.1 | 83154 | 1.64041666667 | 13156 |
| 012739 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:00am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596653.2 | 512226.4 | 83156 | 1.64041666667 | 12739 |
| 013324 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:01am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596654.5 | 512225.6 | 83158 | 1.64041666667 | 13324 |
| 012571 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:02am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596654.2 | 512226.4 | 83160 | 1.64041666667 | 12571 |
| 012862 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:03am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596652.9 | 512227.8 | 83162 | 1.64041666667 | 12862 |
| 012605 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:04am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596651.2 | 512229.6 | 83164 | 1.64041666667 | 12605 |
| 012721 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:05am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596649.0 | 512230.4 | 83166 | 1.64041666667 | 12721 |
| 011490 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:06am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596646.2 | 512230.0 | 83168 | 1.64041666667 | 11490 |
| 011752 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:07am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596643.1 | 512229.0 | 83170 | 1.64041666667 | 11752 |
| 011578 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:08am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596640.7 | 512227.6 | 83172 | 1.64041666667 | 11578 |
| 012044 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:09am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596638.2 | 512226.8 | 83174 | 1.64041666667 | 12044 |
| 012011 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:10am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596635.2 | 512225.3 | 83176 | 1.64041666667 | 12011 |
| 015542 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:11am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596633.0 | 512224.4 | 83178 | 1.64041666667 | 15542 |
| 012975 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:12am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596630.6 | 512223.0 | 83180 | 1.64041666667 | 12975 |
| 013623 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:13am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596628.7 | 512221.8 | 83182 | 1.64041666667 | 13623 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013666 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:14am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596625.4 | 512220.9 | 83184 | 1.64041666667 | 13666 |
| 013256 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:15am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596623.2 | 512219.4 | 83186 | 1.64041666667 | 13256 |
| 011864 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:16am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596620.5 | 512217.9 | 83188 | 1.64041666667 | 11864 |
| 012866 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:17am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596618.2 | 512216.5 | 83190 | 1.64041666667 | 12866 |
| 013626 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:18am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596615.2 | 512216.1 | 83192 | 1.64041666667 | 13626 |
| 013306 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:19am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596612.6 | 512216.1 | 83194 | 1.64041666667 | 13306 |
| 013316 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596609.6 | 512215.1 | 83196 | 1.64041666667 | 13316 |
| 014459 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:21am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596607.1 | 512214.4 | 83198 | 1.64041666667 | 14459 |
| 012165 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:22am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596604.4 | 512213.0 | 83200 | 1.64041666667 | 12165 |
| 012971 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596602.1 | 512212.0 | 83202 | 1.64041666667 | 12971 |
| 011912 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596599.4 | 512210.7 | 83204 | 1.64041666667 | 11912 |
| 012938 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596596.7 | 512209.7 | 83206 | 1.64041666667 | 12938 |
| 013614 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596593.8 | 512208.3 | 83208 | 1.64041666667 | 13614 |
| 012613 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596591.4 | 512206.2 | 83210 | 1.64041666667 | 12613 |
| 012753 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596588.7 | 512204.3 | 83212 | 1.64041666667 | 12753 |
| 012878 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596586.6 | 512202.5 | 83214 | 1.64041666667 | 12878 |
| 012009 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596583.7 | 512201.3 | 83216 | 1.64041666667 | 12009 |
| 013892 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596581.5 | 512200.0 | 83218 | 1.64041666667 | 13892 |
| 014063 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596578.7 | 512198.8 | 83220 | 1.64041666667 | 14063 |
| 011495 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596575.8 | 512197.9 | 83222 | 1.64041666667 | 11495 |
| 013554 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596572.4 | 512196.7 | 83224 | 1.64041666667 | 13554 |
| 015088 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596569.6 | 512196.3 | 83226 | 1.64041666667 | 15088 |
| 013192 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596567.0 | 512195.1 | 83228 | 1.64041666667 | 13192 |
| 012748 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596564.7 | 512193.8 | 83230 | 1.64041666667 | 12748 |
| 014167 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596561.9 | 512192.0 | 83232 | 1.64041666667 | 14167 |
| 012811 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596559.7 | 512190.4 | 83234 | 1.64041666667 | 12811 |
| 014242 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596556.3 | 512188.8 | 83236 | 1.64041666667 | 14242 |
| 014750 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596555.9 | 512188.5 | 83238 | 1.64041666667 | 14750 |
| 014007 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596555.4 | 512188.4 | 83240 | 1.64041666667 | 14007 |
| 013522 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596554.3 | 512187.5 | 83242 | 1.64041666667 | 13522 |
| 013610 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596551.8 | 512186.2 | 83244 | 1.64041666667 | 13610 |
| 013212 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596549.1 | 512184.9 | 83246 | 1.64041666667 | 13212 |
| 013983 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596546.5 | 512182.8 | 83248 | 1.64041666667 | 13983 |
| 013395 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596544.3 | 512181.6 | 83250 | 1.64041666667 | 13395 |
| 013038 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596543.0 | 512179.9 | 83252 | 1.64041666667 | 13038 |
| 013219 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596543.8 | 512178.6 | 83254 | 1.64041666667 | 13219 |
| 013475 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:50am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596546.1 | 512178.8 | 83256 | 1.64041666667 | 13475 |
| 013808 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596548.3 | 512179.9 | 83258 | 1.64041666667 | 13808 |
| 014072 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596550.6 | 512181.2 | 83260 | 1.64041666667 | 14072 |
| 012668 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596552.3 | 512182.9 | 83262 | 1.64041666667 | 12668 |
| 012077 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596554.9 | 512184.2 | 83264 | 1.64041666667 | 12077 |
| 012739 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596555.8 | 512186.1 | 83266 | 1.64041666667 | 12739 |
| 015874 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596557.6 | 512185.9 | 83268 | 1.64041666667 | 15874 |
| 014258 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596559.6 | 512185.2 | 83270 | 1.64041666667 | 14258 |
| 012684 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596560.8 | 512185.0 | 83272 | 1.64041666667 | 12684 |
| 014631 | 0 | GeoXH 6000 | 08/20/2015 | 11:23:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596560.8 | 512184.7 | 83274 | 1.64041666667 | 14631 |
| 013077 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596561.8 | 512182.3 | 83276 | 1.64041666667 | 13077 |
| 014309 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596563.4 | 512180.5 | 83278 | 1.64041666667 | 14309 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014467 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596565.2 | 512178.1 | 83280 | 1.64041666667 | 14467 |
| 013966 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596565.0 | 512178.1 | 83282 | 1.64041666667 | 13966 |
| 012251 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596564.3 | 512178.8 | 83284 | 1.64041666667 | 12251 |
| 013443 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596563.9 | 512179.1 | 83286 | 1.64041666667 | 13443 |
| 014460 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596563.7 | 512179.2 | 83288 | 1.64041666667 | 14460 |
| 014265 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596563.7 | 512179.2 | 83290 | 1.64041666667 | 14265 |
| 013526 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596563.7 | 512179.1 | 83292 | 1.64041666667 | 13526 |
| 014211 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596564.3 | 512178.8 | 83294 | 1.64041666667 | 14211 |
| 013093 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596563.6 | 512178.5 | 83296 | 1.64041666667 | 13093 |
| 015993 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596563.5 | 512179.1 | 83298 | 1.64041666667 | 15993 |
| 013838 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596563.0 | 512179.7 | 83300 | 1.64041666667 | 13838 |
| 013749 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596561.4 | 512178.8 | 83302 | 1.64041666667 | 13749 |
| 012917 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596559.4 | 512177.1 | 83304 | 1.64041666667 | 12917 |
| 013669 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596557.3 | 512176.2 | 83306 | 1.64041666667 | 13669 |
| 013017 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596555.1 | 512176.3 | 83308 | 1.64041666667 | 13017 |
| 013154 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596554.7 | 512178.2 | 83310 | 1.64041666667 | 13154 |
| 012918 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596556.1 | 512180.3 | 83312 | 1.64041666667 | 12918 |
| 013669 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596557.3 | 512181.9 | 83314 | 1.64041666667 | 13669 |
| 012897 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596559.9 | 512183.4 | 83316 | 1.64041666667 | 12897 |
| 012134 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596562.4 | 512184.8 | 83318 | 1.64041666667 | 12134 |
| 013713 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596565.6 | 512186.8 | 83320 | 1.64041666667 | 13713 |
| 014978 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596568.5 | 512187.9 | 83322 | 1.64041666667 | 14978 |
| 013374 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596571.1 | 512189.7 | 83324 | 1.64041666667 | 13374 |
| 013063 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596574.0 | 512191.2 | 83326 | 1.64041666667 | 13063 |
| 015116 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596577.1 | 512192.5 | 83328 | 1.64041666667 | 15116 |
| 013889 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596580.0 | 512194.1 | 83330 | 1.64041666667 | 13889 |
| 012082 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596583.0 | 512195.1 | 83332 | 1.64041666667 | 12082 |
| 013580 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596585.8 | 512196.4 | 83334 | 1.64041666667 | 13580 |
| 013055 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596588.8 | 512197.8 | 83336 | 1.64041666667 | 13055 |
| 012563 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596591.9 | 512199.1 | 83338 | 1.64041666667 | 12563 |
| 012351 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596594.6 | 512201.2 | 83340 | 1.64041666667 | 12351 |
| 012267 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:33am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596597.0 | 512202.4 | 83342 | 1.64041666667 | 12267 |
| 012847 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596600.3 | 512204.3 | 83344 | 1.64041666667 | 12847 |
| 012151 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:35am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596602.4 | 512205.9 | 83346 | 1.64041666667 | 12151 |
| 011557 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:36am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596605.5 | 512207.3 | 83348 | 1.64041666667 | 11557 |
| 013629 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:37am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596607.8 | 512208.5 | 83350 | 1.64041666667 | 13629 |
| 012317 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:38am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596611.1 | 512209.6 | 83352 | 1.64041666667 | 12317 |
| 012919 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:39am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596614.1 | 512209.9 | 83354 | 1.64041666667 | 12919 |
| 012679 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:40am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596617.3 | 512210.9 | 83356 | 1.64041666667 | 12679 |
| 012890 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:41am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596619.8 | 512211.3 | 83358 | 1.64041666667 | 12890 |
| 013782 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:42am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596622.7 | 512212.0 | 83360 | 1.64041666667 | 13782 |
| 014215 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:43am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596625.8 | 512212.9 | 83362 | 1.64041666667 | 14215 |
| 013154 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:44am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596629.2 | 512213.6 | 83364 | 1.64041666667 | 13154 |
| 012468 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:45am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596631.3 | 512215.0 | 83366 | 1.64041666667 | 12468 |
| 013467 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:46am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596634.1 | 512216.7 | 83368 | 1.64041666667 | 13467 |
| 012306 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:47am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596636.9 | 512218.0 | 83370 | 1.64041666667 | 12306 |
| 012526 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:48am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596639.9 | 512219.8 | 83372 | 1.64041666667 | 12526 |
| 012761 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:49am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596642.3 | 512220.3 | 83374 | 1.64041666667 | 12761 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011830 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:50am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596645.4 | 512220.9 | 83376 | 1.64041666667 | 11830 |
| 012707 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:51am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596648.0 | 512221.2 | 83378 | 1.64041666667 | 12707 |
| 012206 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:52am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596651.0 | 512221.9 | 83380 | 1.64041666667 | 12206 |
| 012381 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:53am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596653.1 | 512222.7 | 83382 | 1.64041666667 | 12381 |
| 013535 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:54am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596652.3 | 512222.9 | 83384 | 1.64041666667 | 13535 |
| 012443 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:55am | Sensor | 1797-S0052-G-TJV.cor | 6850.8 | 1596652.6 | 512221.0 | 83386 | 1.64041666667 | 12443 |
| 012441 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:56am | Sensor | 1797-S0052-G-TJV.cor | 6850.8 | 1596654.7 | 512218.7 | 83388 | 1.64041666667 | 12441 |
| 013190 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:57am | Sensor | 1797-S0052-G-TJV.cor | 6850.8 | 1596655.7 | 512217.8 | 83390 | 1.64041666667 | 13190 |
| 010887 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:58am | Sensor | 1797-S0052-G-TJV.cor | 6850.8 | 1596656.0 | 512215.6 | 83392 | 1.64041666667 | 10887 |
| 013342 | 0 | GeoXH 6000 | 08/20/2015 | 11:24:59am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596657.3 | 512214.0 | 83394 | 1.64041666667 | 13342 |
| 013355 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:00am | Sensor | 1797-S0052-G-TJV.cor | 6851.0 | 1596658.4 | 512212.2 | 83396 | 1.64041666667 | 13355 |
| 013178 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:01am | Sensor | 1797-S0052-G-TJV.cor | 6851.1 | 1596658.7 | 512212.1 | 83398 | 1.64041666667 | 13178 |
| 012834 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:02am | Sensor | 1797-S0052-G-TJV.cor | 6851.1 | 1596658.9 | 512212.3 | 83400 | 1.64041666667 | 12834 |
| 013378 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:03am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596659.4 | 512210.3 | 83402 | 1.64041666667 | 13378 |
| 014384 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:04am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596659.6 | 512209.4 | 83404 | 1.64041666667 | 14384 |
| 013646 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:05am | Sensor | 1797-S0052-G-TJV.cor | 6851.0 | 1596658.2 | 512210.7 | 83406 | 1.64041666667 | 13646 |
| 013461 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:06am | Sensor | 1797-S0052-G-TJV.cor | 6851.1 | 1596658.0 | 512212.7 | 83408 | 1.64041666667 | 13461 |
| 013205 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:07am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596656.8 | 512214.6 | 83410 | 1.64041666667 | 13205 |
| 013531 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:08am | Sensor | 1797-S0052-G-TJV.cor | 6850.8 | 1596654.7 | 512216.0 | 83412 | 1.64041666667 | 13531 |
| 013132 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:09am | Sensor | 1797-S0052-G-TJV.cor | 6850.8 | 1596652.3 | 512216.1 | 83414 | 1.64041666667 | 13132 |
| 014053 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:10am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596649.1 | 512215.1 | 83416 | 1.64041666667 | 14053 |
| 015153 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:11am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596646.8 | 512213.6 | 83418 | 1.64041666667 | 15153 |
| 013778 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:12am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596643.6 | 512212.0 | 83420 | 1.64041666667 | 13778 |
| 013614 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:13am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596641.2 | 512210.3 | 83422 | 1.64041666667 | 13614 |
| 012133 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:14am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596638.1 | 512208.9 | 83424 | 1.64041666667 | 12133 |
| 013113 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:15am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596635.6 | 512207.8 | 83426 | 1.64041666667 | 13113 |
| 013838 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:16am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596632.5 | 512206.3 | 83428 | 1.64041666667 | 13838 |
| 014439 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:17am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596630.0 | 512205.6 | 83430 | 1.64041666667 | 14439 |
| 013870 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:18am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596627.3 | 512204.1 | 83432 | 1.64041666667 | 13870 |
| 014747 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:19am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596625.1 | 512203.0 | 83434 | 1.64041666667 | 14747 |
| 012656 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:20am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596622.3 | 512201.2 | 83436 | 1.64041666667 | 12656 |
| 013124 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:21am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596619.8 | 512199.7 | 83438 | 1.64041666667 | 13124 |
| 013001 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:22am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596616.4 | 512198.7 | 83440 | 1.64041666667 | 13001 |
| 011920 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:23am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596614.0 | 512197.7 | 83442 | 1.64041666667 | 11920 |
| 014620 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:24am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596611.0 | 512196.6 | 83444 | 1.64041666667 | 14620 |
| 013075 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:25am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596608.3 | 512195.3 | 83446 | 1.64041666667 | 13075 |
| 011938 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596605.0 | 512193.7 | 83448 | 1.64041666667 | 11938 |
| 012704 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596601.8 | 512193.1 | 83450 | 1.64041666667 | 12704 |
| 012416 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596598.9 | 512192.0 | 83452 | 1.64041666667 | 12416 |
| 013814 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596595.8 | 512191.2 | 83454 | 1.64041666667 | 13814 |
| 014133 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596592.6 | 512190.5 | 83456 | 1.64041666667 | 14133 |
| 012893 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596590.1 | 512189.5 | 83458 | 1.64041666667 | 12893 |
| 013633 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596587.1 | 512188.4 | 83460 | 1.64041666667 | 13633 |
| 014178 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596584.6 | 512187.1 | 83462 | 1.64041666667 | 14178 |
| 015184 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596581.6 | 512185.7 | 83464 | 1.64041666667 | 15184 |
| 013666 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.7 | 512184.6 | 83466 | 1.64041666667 | 13666 |
| 014426 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596575.6 | 512183.0 | 83468 | 1.64041666667 | 14426 |
| 014736 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596573.0 | 512182.0 | 83470 | 1.64041666667 | 14736 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013854 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596570.0 | 512180.3 | 83472 | 1.64041666667 | 13854 |
| 013963 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596567.9 | 512178.9 | 83474 | 1.64041666667 | 13963 |
| 015521 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596565.5 | 512177.8 | 83476 | 1.64041666667 | 15521 |
| 014620 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596564.7 | 512177.4 | 83478 | 1.64041666667 | 14620 |
| 014245 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596564.4 | 512177.2 | 83480 | 1.64041666667 | 14245 |
| 014721 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596562.7 | 512176.5 | 83482 | 1.64041666667 | 14721 |
| 012140 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596560.3 | 512175.1 | 83484 | 1.64041666667 | 12140 |
| 014375 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596558.2 | 512173.3 | 83486 | 1.64041666667 | 14375 |
| 013133 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596558.4 | 512171.1 | 83488 | 1.64041666667 | 13133 |
| 012943 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596559.8 | 512169.2 | 83490 | 1.64041666667 | 12943 |
| 013916 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596562.6 | 512168.3 | 83492 | 1.64041666667 | 13916 |
| 014129 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596564.8 | 512168.7 | 83494 | 1.64041666667 | 14129 |
| 014062 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:50am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596567.8 | 512169.2 | 83496 | 1.64041666667 | 14062 |
| 013295 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596569.5 | 512170.4 | 83498 | 1.64041666667 | 13295 |
| 015863 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596571.1 | 512171.1 | 83500 | 1.64041666667 | 15863 |
| 014136 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596571.0 | 512171.2 | 83502 | 1.64041666667 | 14136 |
| 013794 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596570.7 | 512171.3 | 83504 | 1.64041666667 | 13794 |
| 014368 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596570.6 | 512171.3 | 83506 | 1.64041666667 | 14368 |
| 014362 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596570.6 | 512171.4 | 83508 | 1.64041666667 | 14362 |
| 014630 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596570.6 | 512171.5 | 83510 | 1.64041666667 | 14630 |
| 014697 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596571.0 | 512171.7 | 83512 | 1.64041666667 | 14697 |
| 013874 | 0 | GeoXH 6000 | 08/20/2015 | 11:25:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596573.0 | 512172.2 | 83514 | 1.64041666667 | 13874 |
| 013698 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596575.7 | 512173.4 | 83516 | 1.64041666667 | 13698 |
| 012874 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596578.4 | 512174.8 | 83518 | 1.64041666667 | 12874 |
| 013418 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596581.7 | 512176.0 | 83520 | 1.64041666667 | 13418 |
| 013644 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596584.0 | 512177.3 | 83522 | 1.64041666667 | 13644 |
| 014211 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596587.1 | 512178.8 | 83524 | 1.64041666667 | 14211 |
| 013812 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596589.6 | 512180.4 | 83526 | 1.64041666667 | 13812 |
| 014343 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596592.3 | 512182.5 | 83528 | 1.64041666667 | 14343 |
| 013935 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:07am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596594.8 | 512183.2 | 83530 | 1.64041666667 | 13935 |
| 014793 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:08am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596597.4 | 512184.6 | 83532 | 1.64041666667 | 14793 |
| 013658 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:09am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596599.3 | 512185.5 | 83534 | 1.64041666667 | 13658 |
| 013884 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:10am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596602.1 | 512187.1 | 83536 | 1.64041666667 | 13884 |
| 014511 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:11am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596604.4 | 512188.3 | 83538 | 1.64041666667 | 14511 |
| 013197 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:12am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596607.4 | 512189.2 | 83540 | 1.64041666667 | 13197 |
| 012209 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:13am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596609.3 | 512190.5 | 83542 | 1.64041666667 | 12209 |
| 013972 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:14am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596612.1 | 512192.1 | 83544 | 1.64041666667 | 13972 |
| 014383 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:15am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596614.5 | 512193.1 | 83546 | 1.64041666667 | 14383 |
| 013675 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:16am | Sensor | 1797-S0052-G-TJV.cor | 6850.4 | 1596617.6 | 512194.6 | 83548 | 1.64041666667 | 13675 |
| 011459 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:17am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596620.3 | 512195.4 | 83550 | 1.64041666667 | 11459 |
| 013154 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:18am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596623.4 | 512196.5 | 83552 | 1.64041666667 | 13154 |
| 015588 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:19am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596626.0 | 512197.2 | 83554 | 1.64041666667 | 15588 |
| 014457 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:20am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596629.1 | 512198.0 | 83556 | 1.64041666667 | 14457 |
| 014444 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:21am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596631.9 | 512199.1 | 83558 | 1.64041666667 | 14444 |
| 013901 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:22am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596635.3 | 512200.0 | 83560 | 1.64041666667 | 13901 |
| 013015 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:23am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596637.8 | 512201.4 | 83562 | 1.64041666667 | 13015 |
| 013183 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:24am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596640.4 | 512202.9 | 83564 | 1.64041666667 | 13183 |
| 013736 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:25am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596643.1 | 512204.3 | 83566 | 1.64041666667 | 13736 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014084 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:26am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596646.0 | 512205.7 | 83568 | 1.64041666667 | 14084 |
| 013361 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:27am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596648.8 | 512206.7 | 83570 | 1.64041666667 | 13361 |
| 012790 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:28am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596651.9 | 512208.2 | 83572 | 1.64041666667 | 12790 |
| 013457 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:29am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596654.3 | 512208.7 | 83574 | 1.64041666667 | 13457 |
| 014794 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:30am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596656.6 | 512209.7 | 83576 | 1.64041666667 | 14794 |
| 013478 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:31am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596658.4 | 512210.3 | 83578 | 1.64041666667 | 13478 |
| 013719 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:32am | Sensor | 1797-S0052-G-TJV.cor | 6850.8 | 1596657.5 | 512210.4 | 83580 | 1.64041666667 | 13719 |
| 014590 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:33am | Sensor | 1797-S0052-G-TJV.cor | 6851.0 | 1596657.7 | 512210.0 | 83582 | 1.64041666667 | 14590 |
| 014657 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:34am | Sensor | 1797-S0052-G-TJV.cor | 6851.0 | 1596657.5 | 512209.9 | 83584 | 1.64041666667 | 14657 |
| 012184 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:35am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596657.1 | 512210.5 | 83586 | 1.64041666667 | 12184 |
| 011026 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:36am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596656.6 | 512211.0 | 83588 | 1.64041666667 | 11026 |
| 016406 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:37am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596656.5 | 512211.0 | 83590 | 1.64041666667 | 16406 |
| 014541 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:38am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596656.5 | 512210.9 | 83592 | 1.64041666667 | 14541 |
| 014675 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:39am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596656.3 | 512210.9 | 83594 | 1.64041666667 | 14675 |
| 012968 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:40am | Sensor | 1797-S0052-G-TJV.cor | 6850.9 | 1596655.4 | 512212.2 | 83596 | 1.64041666667 | 12968 |
| 014582 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:41am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596653.6 | 512213.8 | 83598 | 1.64041666667 | 14582 |
| 012375 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:42am | Sensor | 1797-S0052-G-TJV.cor | 6850.7 | 1596650.6 | 512215.9 | 83600 | 1.64041666667 | 12375 |
| 012123 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:43am | Sensor | 1797-S0052-G-TJV.cor | 6850.8 | 1596648.3 | 512217.6 | 83602 | 1.64041666667 | 12123 |
| 013831 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:44am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596645.3 | 512219.8 | 83604 | 1.64041666667 | 13831 |
| 012127 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:45am | Sensor | 1797-S0052-G-TJV.cor | 6850.6 | 1596642.8 | 512221.8 | 83606 | 1.64041666667 | 12127 |
| 012002 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:46am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596640.2 | 512224.1 | 83608 | 1.64041666667 | 12002 |
| 012450 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:47am | Sensor | 1797-S0052-G-TJV.cor | 6850.5 | 1596638.1 | 512226.5 | 83610 | 1.64041666667 | 12450 |
| 012232 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:48am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596635.8 | 512229.0 | 83612 | 1.64041666667 | 12232 |
| 012268 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:49am | Sensor | 1797-S0052-G-TJV.cor | 6850.3 | 1596633.6 | 512231.7 | 83614 | 1.64041666667 | 12268 |
| 010957 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:50am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596631.6 | 512234.3 | 83616 | 1.64041666667 | 10957 |
| 011049 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:51am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596629.4 | 512236.6 | 83618 | 1.64041666667 | 11049 |
| 013532 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:52am | Sensor | 1797-S0052-G-TJV.cor | 6850.2 | 1596627.2 | 512237.5 | 83620 | 1.64041666667 | 13532 |
| 013403 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:53am | Sensor | 1797-S0052-G-TJV.cor | 6850.0 | 1596624.5 | 512238.2 | 83622 | 1.64041666667 | 13403 |
| 013340 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:54am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596621.5 | 512238.9 | 83624 | 1.64041666667 | 13340 |
| 013505 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:55am | Sensor | 1797-S0052-G-TJV.cor | 6850.1 | 1596618.9 | 512239.1 | 83626 | 1.64041666667 | 13505 |
| 013246 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.7 | 1596615.3 | 512239.6 | 83628 | 1.64041666667 | 13246 |
| 014201 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596612.3 | 512240.6 | 83630 | 1.64041666667 | 14201 |
| 014500 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.9 | 1596609.7 | 512240.7 | 83632 | 1.64041666667 | 14500 |
| 014185 | 0 | GeoXH 6000 | 08/20/2015 | 11:26:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.8 | 1596607.1 | 512240.9 | 83634 | 1.64041666667 | 14185 |
| 014286 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596603.9 | 512241.9 | 83636 | 1.64041666667 | 14286 |
| 012631 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596600.8 | 512242.8 | 83638 | 1.64041666667 | 12631 |
| 012037 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.6 | 1596598.1 | 512244.1 | 83640 | 1.64041666667 | 12037 |
| 014229 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596595.4 | 512245.5 | 83642 | 1.64041666667 | 14229 |
| 013067 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596592.1 | 512246.9 | 83644 | 1.64041666667 | 13067 |
| 013886 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596589.7 | 512248.2 | 83646 | 1.64041666667 | 13886 |
| 013131 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596587.3 | 512249.4 | 83648 | 1.64041666667 | 13131 |
| 013483 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596585.4 | 512249.2 | 83650 | 1.64041666667 | 13483 |
| 014050 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596583.4 | 512249.3 | 83652 | 1.64041666667 | 14050 |
| 013712 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596582.9 | 512249.2 | 83654 | 1.64041666667 | 13712 |
| 013718 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596582.6 | 512249.2 | 83656 | 1.64041666667 | 13718 |
| 014169 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596582.5 | 512249.4 | 83658 | 1.64041666667 | 14169 |
| 013712 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596582.3 | 512249.2 | 83660 | 1.64041666667 | 13712 |
| 012308 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596582.0 | 512248.0 | 83662 | 1.64041666667 | 12308 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013127 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596581.1 | 512246.5 | 83664 | 1.64041666667 | 13127 |
| 012011 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596580.9 | 512246.2 | 83666 | 1.64041666667 | 12011 |
| 013413 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596580.7 | 512246.1 | 83668 | 1.64041666667 | 13413 |
| 013883 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596580.8 | 512244.6 | 83670 | 1.64041666667 | 13883 |
| 013730 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596580.3 | 512242.6 | 83672 | 1.64041666667 | 13730 |
| 012582 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596580.1 | 512242.1 | 83674 | 1.64041666667 | 12582 |
| 012025 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596580.1 | 512242.0 | 83676 | 1.64041666667 | 12025 |
| 012696 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596580.0 | 512241.9 | 83678 | 1.64041666667 | 12696 |
| 011634 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596579.3 | 512240.6 | 83680 | 1.64041666667 | 11634 |
| 011698 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596578.6 | 512239.8 | 83682 | 1.64041666667 | 11698 |
| 013094 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596578.3 | 512239.5 | 83684 | 1.64041666667 | 13094 |
| 013173 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596578.2 | 512239.3 | 83686 | 1.64041666667 | 13173 |
| 013193 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596578.2 | 512239.3 | 83688 | 1.64041666667 | 13193 |
| 013528 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.3 | 83690 | 1.64041666667 | 13528 |
| 012922 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596577.9 | 512239.2 | 83692 | 1.64041666667 | 12922 |
| 012620 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596577.7 | 512239.3 | 83694 | 1.64041666667 | 12620 |
| 011555 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596577.8 | 512239.3 | 83696 | 1.64041666667 | 11555 |
| 011918 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596577.9 | 512239.4 | 83698 | 1.64041666667 | 11918 |
| 012309 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596577.9 | 512239.2 | 83700 | 1.64041666667 | 12309 |
| 012347 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.3 | 83702 | 1.64041666667 | 12347 |
| 011936 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.1 | 512239.3 | 83704 | 1.64041666667 | 11936 |
| 013694 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.3 | 512239.4 | 83706 | 1.64041666667 | 13694 |
| 014343 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.3 | 512239.1 | 83708 | 1.64041666667 | 14343 |
| 013845 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.0 | 512239.2 | 83710 | 1.64041666667 | 13845 |
| 012791 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.0 | 512239.3 | 83712 | 1.64041666667 | 12791 |
| 013038 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.3 | 512239.2 | 83714 | 1.64041666667 | 13038 |
| 012229 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.4 | 512239.1 | 83716 | 1.64041666667 | 12229 |
| 011454 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.4 | 512239.1 | 83718 | 1.64041666667 | 11454 |
| 011932 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.4 | 512239.2 | 83720 | 1.64041666667 | 11932 |
| 013243 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.4 | 512239.2 | 83722 | 1.64041666667 | 13243 |
| 011710 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.4 | 512239.2 | 83724 | 1.64041666667 | 11710 |
| 012227 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.4 | 512239.1 | 83726 | 1.64041666667 | 12227 |
| 012836 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.1 | 83728 | 1.64041666667 | 12836 |
| 012329 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.1 | 83730 | 1.64041666667 | 12329 |
| 014452 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.1 | 83732 | 1.64041666667 | 14452 |
| 012883 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.1 | 512238.9 | 83734 | 1.64041666667 | 12883 |
| 013330 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:50am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596577.9 | 512238.9 | 83736 | 1.64041666667 | 13330 |
| 012842 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:51am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.8 | 83738 | 1.64041666667 | 12842 |
| 011970 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:52am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.7 | 83740 | 1.64041666667 | 11970 |
| 013282 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.7 | 83742 | 1.64041666667 | 13282 |
| 012470 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.7 | 83744 | 1.64041666667 | 12470 |
| 013287 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.7 | 83746 | 1.64041666667 | 13287 |
| 012502 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.7 | 83748 | 1.64041666667 | 12502 |
| 012485 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.7 | 83750 | 1.64041666667 | 12485 |
| 013381 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.7 | 512238.6 | 83752 | 1.64041666667 | 13381 |
| 012705 | 0 | GeoXH 6000 | 08/20/2015 | 11:27:59am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.7 | 512238.7 | 83754 | 1.64041666667 | 12705 |
| 013496 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:00am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.7 | 512238.7 | 83756 | 1.64041666667 | 13496 |
| 013424 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:01am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596577.7 | 512238.7 | 83758 | 1.64041666667 | 13424 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013586 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:02am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596577.7 | 512238.8 | 83760 | 1.64041666667 | 13586 |
| 015276 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:03am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.7 | 512238.8 | 83762 | 1.64041666667 | 15276 |
| 014379 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:04am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596577.7 | 512238.8 | 83764 | 1.64041666667 | 14379 |
| 011934 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:05am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596577.7 | 512238.8 | 83766 | 1.64041666667 | 11934 |
| 012673 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:06am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596577.6 | 512238.8 | 83768 | 1.64041666667 | 12673 |
| 013308 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:07am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.7 | 83770 | 1.64041666667 | 13308 |
| 014097 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:08am | Sensor | 1797-S0052-G-TJV.cor | 6849.2 | 1596577.6 | 512238.7 | 83772 | 1.64041666667 | 14097 |
| 012374 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:09am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596577.7 | 512238.8 | 83774 | 1.64041666667 | 12374 |
| 012633 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:10am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596578.2 | 512239.3 | 83776 | 1.64041666667 | 12633 |
| 013208 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:11am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.7 | 83778 | 1.64041666667 | 13208 |
| 014912 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:12am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.7 | 83780 | 1.64041666667 | 14912 |
| 012998 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:13am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.7 | 83782 | 1.64041666667 | 12998 |
| 012699 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:14am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83784 | 1.64041666667 | 12699 |
| 013675 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:15am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83786 | 1.64041666667 | 13675 |
| 013468 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:16am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83788 | 1.64041666667 | 13468 |
| 012997 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:17am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83790 | 1.64041666667 | 12997 |
| 012939 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:18am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83792 | 1.64041666667 | 12939 |
| 014334 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:19am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83794 | 1.64041666667 | 14334 |
| 014233 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:20am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.7 | 83796 | 1.64041666667 | 14233 |
| 013008 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:21am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.1 | 512239.7 | 83798 | 1.64041666667 | 13008 |
| 012432 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:22am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.0 | 512239.7 | 83800 | 1.64041666667 | 12432 |
| 013218 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:23am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83802 | 1.64041666667 | 13218 |
| 012034 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:24am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596577.9 | 512239.6 | 83804 | 1.64041666667 | 12034 |
| 012098 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:25am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83806 | 1.64041666667 | 12098 |
| 012594 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:26am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.6 | 83808 | 1.64041666667 | 12594 |
| 013828 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:27am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.5 | 83810 | 1.64041666667 | 13828 |
| 013417 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:28am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.1 | 512239.1 | 83812 | 1.64041666667 | 13417 |
| 013914 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:29am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.0 | 83814 | 1.64041666667 | 13914 |
| 013378 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:30am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596577.7 | 512239.0 | 83816 | 1.64041666667 | 13378 |
| 012914 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:31am | Sensor | 1797-S0052-G-TJV.cor | 6849.3 | 1596578.1 | 512239.3 | 83818 | 1.64041666667 | 12914 |
| 012438 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:32am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.4 | 512239.5 | 83820 | 1.64041666667 | 12438 |
| 013539 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:33am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.4 | 512239.4 | 83822 | 1.64041666667 | 13539 |
| 012792 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:34am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.4 | 512239.4 | 83824 | 1.64041666667 | 12792 |
| 012138 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:35am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.4 | 512239.5 | 83826 | 1.64041666667 | 12138 |
| 013804 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:36am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.4 | 512239.5 | 83828 | 1.64041666667 | 13804 |
| 014881 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:37am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.5 | 83830 | 1.64041666667 | 14881 |
| 014310 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:38am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.1 | 512239.5 | 83832 | 1.64041666667 | 14310 |
| 015037 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:39am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.1 | 512239.5 | 83834 | 1.64041666667 | 15037 |
| 012789 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:40am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.5 | 83836 | 1.64041666667 | 12789 |
| 012227 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:41am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.0 | 512239.5 | 83838 | 1.64041666667 | 12227 |
| 012026 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:42am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.0 | 512239.5 | 83840 | 1.64041666667 | 12026 |
| 012036 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:43am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.0 | 512239.5 | 83842 | 1.64041666667 | 12036 |
| 012429 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:44am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.1 | 512239.4 | 83844 | 1.64041666667 | 12429 |
| 013007 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:45am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.1 | 512239.4 | 83846 | 1.64041666667 | 13007 |
| 013361 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:46am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.1 | 512239.4 | 83848 | 1.64041666667 | 13361 |
| 012520 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:47am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.1 | 512239.4 | 83850 | 1.64041666667 | 12520 |
| 012850 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:48am | Sensor | 1797-S0052-G-TJV.cor | 6849.5 | 1596578.1 | 512239.4 | 83852 | 1.64041666667 | 12850 |
| 013112 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:49am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.1 | 512238.9 | 83854 | 1.64041666667 | 13112 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013028 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:50am | Sensor | 1797-S0052-G-TJV.cor | 6848.3 | 1596577.9 | 512237.7 | 83856 | 1.64041666667 | 13028 |
| 012197 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:51am | Sensor | 1797-S0052-G-TJV.cor | 6847.9 | 1596577.7 | 512237.3 | 83858 | 1.64041666667 | 12197 |
| 012259 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:52am | Sensor | 1797-S0052-G-TJV.cor | 6848.5 | 1596577.7 | 512237.7 | 83860 | 1.64041666667 | 12259 |
| 011404 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:53am | Sensor | 1797-S0052-G-TJV.cor | 6849.1 | 1596578.1 | 512238.8 | 83862 | 1.64041666667 | 11404 |
| 012421 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:54am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.3 | 512239.4 | 83864 | 1.64041666667 | 12421 |
| 012735 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:55am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.4 | 83866 | 1.64041666667 | 12735 |
| 013593 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:56am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.4 | 83868 | 1.64041666667 | 13593 |
| 014078 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:57am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.2 | 512239.5 | 83870 | 1.64041666667 | 14078 |
| 012789 | 0 | GeoXH 6000 | 08/20/2015 | 11:28:58am | Sensor | 1797-S0052-G-TJV.cor | 6849.4 | 1596578.1 | 512239.5 | 83872 | 1.64041666667 | 12789 |
| 014611 | 0 | GeoXH 6000 | 08/19/2015 | 04:41:55pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.2 | 512583.1 | 77361 | 1.64041666667 | 14611 |
| 015352 | 0 | GeoXH 6000 | 08/19/2015 | 04:41:56pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.2 | 512583.0 | 77364 | 1.64041666667 | 15352 |
| 014428 | 0 | GeoXH 6000 | 08/19/2015 | 04:41:57pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.2 | 512583.0 | 77366 | 1.64041666667 | 14428 |
| 015517 | 0 | GeoXH 6000 | 08/19/2015 | 04:41:58pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.2 | 512583.0 | 77368 | 1.64041666667 | 15517 |
| 016269 | 0 | GeoXH 6000 | 08/19/2015 | 04:41:59pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.2 | 512583.1 | 77370 | 1.64041666667 | 16269 |
| 014987 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:00pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.5 | 512583.1 | 77372 | 1.64041666667 | 14987 |
| 016226 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:01pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.5 | 512583.1 | 77374 | 1.64041666667 | 16226 |
| 014526 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:02pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.5 | 512583.1 | 77376 | 1.64041666667 | 14526 |
| 014671 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:03pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.6 | 512583.1 | 77378 | 1.64041666667 | 14671 |
| 013837 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:04pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.5 | 512583.1 | 77380 | 1.64041666667 | 13837 |
| 015339 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:05pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.5 | 512583.1 | 77382 | 1.64041666667 | 15339 |
| 014455 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:06pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595983.4 | 512583.1 | 77384 | 1.64041666667 | 14455 |
| 013963 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:07pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.1 | 512583.2 | 77386 | 1.64041666667 | 13963 |
| 014051 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:08pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.1 | 512583.2 | 77388 | 1.64041666667 | 14051 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:09pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.2 | 512583.2 | 77390 | 1.64041666667 | 14132 |
| 014813 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:10pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.2 | 512583.2 | 77392 | 1.64041666667 | 14813 |
| 014023 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:11pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.3 | 512583.2 | 77394 | 1.64041666667 | 14023 |
| 014096 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:12pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.4 | 512583.2 | 77396 | 1.64041666667 | 14096 |
| 014504 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:13pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.7 | 512583.2 | 77398 | 1.64041666667 | 14504 |
| 015866 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:14pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.2 | 512583.5 | 77400 | 1.64041666667 | 15866 |
| 013926 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:15pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595982.9 | 512583.6 | 77402 | 1.64041666667 | 13926 |
| 014251 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:16pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595982.8 | 512583.7 | 77404 | 1.64041666667 | 14251 |
| 013552 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:17pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595982.8 | 512583.9 | 77406 | 1.64041666667 | 13552 |
| 013438 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:18pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595983.0 | 512584.3 | 77408 | 1.64041666667 | 13438 |
| 013799 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:19pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1595984.3 | 512586.2 | 77410 | 1.64041666667 | 13799 |
| 016050 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:20pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595985.2 | 512588.7 | 77412 | 1.64041666667 | 16050 |
| 016492 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:21pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595986.2 | 512591.8 | 77414 | 1.64041666667 | 16492 |
| 013633 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:22pm | Sensor | 1797-S0051=G-TJV.cor | 6840.7 | 1595987.2 | 512594.1 | 77416 | 1.64041666667 | 13633 |
| 014028 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:23pm | Sensor | 1797-S0051=G-TJV.cor | 6840.7 | 1595988.1 | 512597.3 | 77418 | 1.64041666667 | 14028 |
| 013587 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:24pm | Sensor | 1797-S0051=G-TJV.cor | 6840.7 | 1595988.7 | 512600.2 | 77420 | 1.64041666667 | 13587 |
| 013146 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:25pm | Sensor | 1797-S0051=G-TJV.cor | 6840.8 | 1595989.5 | 512603.7 | 77422 | 1.64041666667 | 13146 |
| 012886 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:26pm | Sensor | 1797-S0051=G-TJV.cor | 6840.7 | 1595989.7 | 512607.4 | 77424 | 1.64041666667 | 12886 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:27pm | Sensor | 1797-S0051=G-TJV.cor | 6840.9 | 1595989.5 | 512611.1 | 77426 | 1.64041666667 | 12401 |
| 013870 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:28pm | Sensor | 1797-S0051=G-TJV.cor | 6840.9 | 1595989.6 | 512614.2 | 77428 | 1.64041666667 | 13870 |
| 014267 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:29pm | Sensor | 1797-S0051=G-TJV.cor | 6841.2 | 1595989.9 | 512618.1 | 77430 | 1.64041666667 | 14267 |
| 013676 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:30pm | Sensor | 1797-S0051=G-TJV.cor | 6841.1 | 1595990.1 | 512621.6 | 77432 | 1.64041666667 | 13676 |
| 014519 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:31pm | Sensor | 1797-S0051=G-TJV.cor | 6841.2 | 1595990.2 | 512625.3 | 77434 | 1.64041666667 | 14519 |
| 014520 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:32pm | Sensor | 1797-S0051=G-TJV.cor | 6841.2 | 1595990.9 | 512628.2 | 77436 | 1.64041666667 | 14520 |
| 014730 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:33pm | Sensor | 1797-S0051=G-TJV.cor | 6841.4 | 1595991.9 | 512631.7 | 77438 | 1.64041666667 | 14730 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013342 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:34pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595992.9 | 512634.5 | 77440 | 1.64041666667 | 13342 |
| 013355 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:35pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595994.5 | 512638.2 | 77442 | 1.64041666667 | 13355 |
| 014678 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:36pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595995.9 | 512640.9 | 77444 | 1.64041666667 | 14678 |
| 015519 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:37pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595997.5 | 512644.6 | 77446 | 1.64041666667 | 15519 |
| 013780 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:38pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595998.2 | 512647.9 | 77448 | 1.64041666667 | 13780 |
| 013285 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:39pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595998.1 | 512651.7 | 77450 | 1.64041666667 | 13285 |
| 012351 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:40pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595997.9 | 512654.6 | 77452 | 1.64041666667 | 12351 |
| 014727 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:41pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595998.1 | 512658.6 | 77454 | 1.64041666667 | 14727 |
| 012952 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:42pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595998.9 | 512661.7 | 77456 | 1.64041666667 | 12952 |
| 013498 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:43pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1596000.6 | 512665.9 | 77458 | 1.64041666667 | 13498 |
| 013604 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:44pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1596002.1 | 512668.5 | 77460 | 1.64041666667 | 13604 |
| 012731 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:45pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1596004.1 | 512671.8 | 77462 | 1.64041666667 | 12731 |
| 012305 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:46pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1596005.8 | 512674.6 | 77464 | 1.64041666667 | 12305 |
| 014663 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:47pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1596007.8 | 512677.7 | 77466 | 1.64041666667 | 14663 |
| 013415 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:48pm | Sensor | 1797-S0051=G-TJV.cor | 6842.3 | 1596008.9 | 512680.6 | 77468 | 1.64041666667 | 13415 |
| 014544 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:49pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1596009.9 | 512684.1 | 77470 | 1.64041666667 | 14544 |
| 012696 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:50pm | Sensor | 1797-S0051=G-TJV.cor | 6842.3 | 1596010.6 | 512687.3 | 77472 | 1.64041666667 | 12696 |
| 010974 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:51pm | Sensor | 1797-S0051=G-TJV.cor | 6842.3 | 1596011.4 | 512691.0 | 77474 | 1.64041666667 | 10974 |
| 011593 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:52pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1596012.1 | 512694.8 | 77476 | 1.64041666667 | 11593 |
| 010968 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:53pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1596012.8 | 512698.6 | 77478 | 1.64041666667 | 10968 |
| 011382 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:54pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1596013.5 | 512702.6 | 77480 | 1.64041666667 | 11382 |
| 012715 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:55pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1596014.5 | 512706.8 | 77482 | 1.64041666667 | 12715 |
| 013169 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:56pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1596015.6 | 512709.8 | 77484 | 1.64041666667 | 13169 |
| 012862 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:57pm | Sensor | 1797-S0051=G-TJV.cor | 6840.9 | 1596017.0 | 512713.4 | 77486 | 1.64041666667 | 12862 |
| 012725 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:58pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1596018.5 | 512716.5 | 77488 | 1.64041666667 | 12725 |
| 011941 | 0 | GeoXH 6000 | 08/19/2015 | 04:42:59pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1596020.4 | 512720.2 | 77490 | 1.64041666667 | 11941 |
| 010695 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:00pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1596021.9 | 512723.6 | 77492 | 1.64041666667 | 10695 |
| 013803 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:01pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1596023.4 | 512727.6 | 77494 | 1.64041666667 | 13803 |
| 013351 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:02pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1596024.3 | 512731.0 | 77496 | 1.64041666667 | 13351 |
| 012547 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:03pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1596025.0 | 512735.0 | 77498 | 1.64041666667 | 12547 |
| 013187 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:04pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1596025.6 | 512738.6 | 77500 | 1.64041666667 | 13187 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:05pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1596026.7 | 512742.2 | 77502 | 1.64041666667 | 12056 |
| 013214 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:06pm | Sensor | 1797-S0051=G-TJV.cor | 6839.7 | 1596028.2 | 512746.0 | 77504 | 1.64041666667 | 13214 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:07pm | Sensor | 1797-S0051=G-TJV.cor | 6839.6 | 1596029.3 | 512750.1 | 77506 | 1.64041666667 | 13593 |
| 013718 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:08pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1596030.0 | 512753.3 | 77508 | 1.64041666667 | 13718 |
| 013989 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:09pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1596030.9 | 512757.2 | 77510 | 1.64041666667 | 13989 |
| 014747 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:10pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1596032.0 | 512760.9 | 77512 | 1.64041666667 | 14747 |
| 013916 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:11pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1596032.7 | 512765.0 | 77514 | 1.64041666667 | 13916 |
| 014009 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:12pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1596033.0 | 512768.4 | 77516 | 1.64041666667 | 14009 |
| 013552 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:13pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1596033.4 | 512772.7 | 77518 | 1.64041666667 | 13552 |
| 012838 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:14pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1596034.4 | 512776.2 | 77520 | 1.64041666667 | 12838 |
| 013529 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:15pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1596036.0 | 512780.4 | 77522 | 1.64041666667 | 13529 |
| 013882 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:16pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1596036.9 | 512783.5 | 77524 | 1.64041666667 | 13882 |
| 012920 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:17pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1596037.9 | 512787.1 | 77526 | 1.64041666667 | 12920 |
| 013190 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:18pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1596038.7 | 512790.3 | 77528 | 1.64041666667 | 13190 |
| 012777 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:19pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1596038.7 | 512794.6 | 77530 | 1.64041666667 | 12777 |
| 011924 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:20pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1596038.4 | 512798.2 | 77532 | 1.64041666667 | 11924 |
| 011981 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:21pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1596037.7 | 512802.7 | 77534 | 1.64041666667 | 11981 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013405 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:22pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1596037.1 | 512806.4 | 77536 | 1.64041666667 | 13405 |
| 012231 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:23pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1596036.2 | 512810.9 | 77538 | 1.64041666667 | 12231 |
| 012717 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:24pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1596035.5 | 512814.6 | 77540 | 1.64041666667 | 12717 |
| 011969 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:25pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1596034.9 | 512819.1 | 77542 | 1.64041666667 | 11969 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:26pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1596034.4 | 512822.5 | 77544 | 1.64041666667 | 12652 |
| 013033 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:27pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1596033.6 | 512826.7 | 77546 | 1.64041666667 | 13033 |
| 012138 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:28pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1596032.8 | 512830.4 | 77548 | 1.64041666667 | 12138 |
| 011914 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:29pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1596032.2 | 512834.9 | 77550 | 1.64041666667 | 11914 |
| 012218 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:30pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1596031.9 | 512838.7 | 77552 | 1.64041666667 | 12218 |
| 013164 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:31pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1596031.3 | 512843.2 | 77554 | 1.64041666667 | 13164 |
| 011481 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:32pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1596030.5 | 512846.7 | 77556 | 1.64041666667 | 11481 |
| 012890 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:33pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1596029.2 | 512851.1 | 77558 | 1.64041666667 | 12890 |
| 014112 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:34pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1596027.8 | 512854.5 | 77560 | 1.64041666667 | 14112 |
| 012348 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:35pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1596025.4 | 512858.8 | 77562 | 1.64041666667 | 12348 |
| 013047 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:36pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1596023.9 | 512861.7 | 77564 | 1.64041666667 | 13047 |
| 012651 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:37pm | Sensor | 1797-S0051=G-TJV.cor | 6841.1 | 1596022.9 | 512865.6 | 77566 | 1.64041666667 | 12651 |
| 011863 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:38pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1596022.4 | 512867.6 | 77568 | 1.64041666667 | 11863 |
| 012145 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:39pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1596022.1 | 512869.8 | 77570 | 1.64041666667 | 12145 |
| 011976 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:40pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1596021.6 | 512871.8 | 77572 | 1.64041666667 | 11976 |
| 012684 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:41pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1596021.5 | 512874.6 | 77574 | 1.64041666667 | 12684 |
| 013101 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596021.9 | 512877.1 | 77576 | 1.64041666667 | 13101 |
| 013535 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:43pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596021.2 | 512880.6 | 77578 | 1.64041666667 | 13535 |
| 014123 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:44pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596019.9 | 512883.7 | 77580 | 1.64041666667 | 14123 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:45pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596019.1 | 512887.2 | 77582 | 1.64041666667 | 12021 |
| 013295 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:46pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596019.0 | 512890.6 | 77584 | 1.64041666667 | 13295 |
| 012713 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:47pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596019.4 | 512894.1 | 77586 | 1.64041666667 | 12713 |
| 012838 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1596019.8 | 512897.6 | 77588 | 1.64041666667 | 12838 |
| 014819 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596020.1 | 512901.2 | 77590 | 1.64041666667 | 14819 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1596019.5 | 512904.3 | 77592 | 1.64041666667 | 12975 |
| 012993 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1596017.3 | 512908.0 | 77594 | 1.64041666667 | 12993 |
| 012398 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1596015.2 | 512910.4 | 77596 | 1.64041666667 | 12398 |
| 012399 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1596012.1 | 512913.7 | 77598 | 1.64041666667 | 12399 |
| 013090 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1596009.2 | 512916.3 | 77600 | 1.64041666667 | 13090 |
| 013622 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1596007.1 | 512918.9 | 77602 | 1.64041666667 | 13622 |
| 013155 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:56pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1596005.7 | 512921.8 | 77604 | 1.64041666667 | 13155 |
| 012468 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:57pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1596003.9 | 512926.0 | 77606 | 1.64041666667 | 12468 |
| 012057 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:58pm | Sensor | 1797-S0051=G-TJV.cor | 6842.3 | 1596002.1 | 512929.3 | 77608 | 1.64041666667 | 12057 |
| 012404 | 0 | GeoXH 6000 | 08/19/2015 | 04:43:59pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1596000.4 | 512932.8 | 77610 | 1.64041666667 | 12404 |
| 011351 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:00pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595999.1 | 512936.3 | 77612 | 1.64041666667 | 11351 |
| 011837 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:01pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595998.4 | 512940.2 | 77614 | 1.64041666667 | 11837 |
| 010489 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:02pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595997.6 | 512943.5 | 77616 | 1.64041666667 | 10489 |
| 012462 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:03pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595996.6 | 512947.6 | 77618 | 1.64041666667 | 12462 |
| 010195 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:04pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595995.6 | 512951.0 | 77620 | 1.64041666667 | 10195 |
| 010949 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:05pm | Sensor | 1797-S0051=G-TJV.cor | 6841.4 | 1595994.4 | 512955.4 | 77622 | 1.64041666667 | 10949 |
| 010147 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:06pm | Sensor | 1797-S0051=G-TJV.cor | 6841.4 | 1595992.9 | 512958.7 | 77624 | 1.64041666667 | 10147 |
| 009106 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:07pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595990.2 | 512962.1 | 77626 | 1.64041666667 | 9106 |
| 010946 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:08pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595987.9 | 512964.9 | 77628 | 1.64041666667 | 10946 |
| 008676 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:09pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595985.5 | 512968.5 | 77630 | 1.64041666667 | 8676 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009399 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:10pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595984.1 | 512971.4 | 77632 | 1.64041666667 | 9399 |
| 011139 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:11pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595982.3 | 512975.4 | 77634 | 1.64041666667 | 11139 |
| 009805 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:12pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595980.4 | 512979.2 | 77636 | 1.64041666667 | 9805 |
| 009681 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:13pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595978.7 | 512982.7 | 77638 | 1.64041666667 | 9681 |
| 008870 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:14pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595977.3 | 512985.8 | 77640 | 1.64041666667 | 8870 |
| 009507 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:15pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595975.5 | 512989.8 | 77642 | 1.64041666667 | 9507 |
| 010237 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:16pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595974.7 | 512993.1 | 77644 | 1.64041666667 | 10237 |
| 008709 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595973.2 | 512997.1 | 77646 | 1.64041666667 | 8709 |
| 012947 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595971.6 | 512999.9 | 77648 | 1.64041666667 | 12947 |
| 010646 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595969.9 | 513003.5 | 77650 | 1.64041666667 | 10646 |
| 010701 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:20pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595968.8 | 513006.7 | 77652 | 1.64041666667 | 10701 |
| 010865 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:21pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595967.0 | 513011.0 | 77654 | 1.64041666667 | 10865 |
| 011116 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595965.6 | 513014.4 | 77656 | 1.64041666667 | 11116 |
| 011689 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595964.5 | 513017.8 | 77658 | 1.64041666667 | 11689 |
| 010272 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595964.1 | 513020.9 | 77660 | 1.64041666667 | 10272 |
| 011268 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595963.5 | 513025.2 | 77662 | 1.64041666667 | 11268 |
| 010437 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595962.5 | 513029.3 | 77664 | 1.64041666667 | 10437 |
| 013499 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595961.4 | 513033.5 | 77666 | 1.64041666667 | 13499 |
| 012735 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595960.7 | 513037.3 | 77668 | 1.64041666667 | 12735 |
| 012693 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:29pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595960.2 | 513040.9 | 77670 | 1.64041666667 | 12693 |
| 011693 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:30pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595959.2 | 513044.5 | 77672 | 1.64041666667 | 11693 |
| 010543 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:31pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595958.1 | 513048.4 | 77674 | 1.64041666667 | 10543 |
| 011336 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:32pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595957.5 | 513052.0 | 77676 | 1.64041666667 | 11336 |
| 011444 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:33pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595957.4 | 513056.0 | 77678 | 1.64041666667 | 11444 |
| 013282 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:34pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595957.8 | 513059.5 | 77680 | 1.64041666667 | 13282 |
| 012010 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:35pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595957.6 | 513063.6 | 77682 | 1.64041666667 | 12010 |
| 011522 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:36pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595956.8 | 513067.0 | 77684 | 1.64041666667 | 11522 |
| 010230 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:37pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595955.7 | 513071.2 | 77686 | 1.64041666667 | 10230 |
| 010987 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:38pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595954.7 | 513074.8 | 77688 | 1.64041666667 | 10987 |
| 011687 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:39pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595953.7 | 513079.0 | 77690 | 1.64041666667 | 11687 |
| 012311 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:40pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595952.8 | 513082.9 | 77692 | 1.64041666667 | 12311 |
| 011508 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:41pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595951.8 | 513087.0 | 77694 | 1.64041666667 | 11508 |
| 011937 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595951.5 | 513090.3 | 77696 | 1.64041666667 | 11937 |
| 010904 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:43pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595951.4 | 513094.1 | 77698 | 1.64041666667 | 10904 |
| 010586 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:44pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595951.0 | 513097.4 | 77700 | 1.64041666667 | 10586 |
| 011076 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:45pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595950.5 | 513101.6 | 77702 | 1.64041666667 | 11076 |
| 011859 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:46pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595950.4 | 513105.1 | 77704 | 1.64041666667 | 11859 |
| 011274 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:47pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595950.5 | 513109.1 | 77706 | 1.64041666667 | 11274 |
| 010288 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595950.7 | 513112.6 | 77708 | 1.64041666667 | 10288 |
| 010282 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595951.0 | 513116.8 | 77710 | 1.64041666667 | 10282 |
| 013520 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595951.1 | 513120.5 | 77712 | 1.64041666667 | 13520 |
| 011990 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595951.1 | 513124.2 | 77714 | 1.64041666667 | 11990 |
| 012177 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595951.2 | 513128.2 | 77716 | 1.64041666667 | 12177 |
| 012344 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595951.7 | 513132.1 | 77718 | 1.64041666667 | 12344 |
| 013376 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595952.0 | 513135.3 | 77720 | 1.64041666667 | 13376 |
| 013064 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595952.2 | 513139.2 | 77722 | 1.64041666667 | 13064 |
| 011426 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595952.4 | 513142.5 | 77724 | 1.64041666667 | 11426 |
| 011256 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595952.6 | 513146.9 | 77726 | 1.64041666667 | 11256 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010164 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595952.7 | 513150.4 | 77728 | 1.64041666667 | 10164 |
| 010791 | 0 | GeoXH 6000 | 08/19/2015 | 04:44:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595952.6 | 513154.6 | 77730 | 1.64041666667 | 10791 |
| 011187 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595952.3 | 513158.4 | 77732 | 1.64041666667 | 11187 |
| 010447 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595952.3 | 513162.4 | 77734 | 1.64041666667 | 10447 |
| 010291 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595952.7 | 513166.1 | 77736 | 1.64041666667 | 10291 |
| 011752 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.0 | 513170.1 | 77738 | 1.64041666667 | 11752 |
| 013168 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595952.8 | 513173.6 | 77740 | 1.64041666667 | 13168 |
| 011002 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.4 | 513177.2 | 77742 | 1.64041666667 | 11002 |
| 011600 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595952.6 | 513180.6 | 77744 | 1.64041666667 | 11600 |
| 009920 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595953.3 | 513184.2 | 77746 | 1.64041666667 | 9920 |
| 010850 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595953.0 | 513185.1 | 77748 | 1.64041666667 | 10850 |
| 012252 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.8 | 513184.8 | 77750 | 1.64041666667 | 12252 |
| 011343 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595952.8 | 513184.7 | 77752 | 1.64041666667 | 11343 |
| 011205 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595952.8 | 513184.7 | 77754 | 1.64041666667 | 11205 |
| 010871 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.3 | 513184.9 | 77756 | 1.64041666667 | 10871 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.4 | 513184.6 | 77758 | 1.64041666667 | 12918 |
| 011809 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.4 | 513184.3 | 77760 | 1.64041666667 | 11809 |
| 011802 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.5 | 513184.2 | 77762 | 1.64041666667 | 11802 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.4 | 513184.2 | 77764 | 1.64041666667 | 12760 |
| 011800 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.3 | 513184.2 | 77766 | 1.64041666667 | 11800 |
| 010060 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.2 | 513184.2 | 77768 | 1.64041666667 | 10060 |
| 010915 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595953.7 | 513184.3 | 77770 | 1.64041666667 | 10915 |
| 010588 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:20pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595953.1 | 513184.3 | 77772 | 1.64041666667 | 10588 |
| 011257 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:21pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.7 | 513184.5 | 77774 | 1.64041666667 | 11257 |
| 010434 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.7 | 513184.5 | 77776 | 1.64041666667 | 10434 |
| 011368 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.8 | 513184.5 | 77778 | 1.64041666667 | 11368 |
| 012712 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.7 | 513184.5 | 77780 | 1.64041666667 | 12712 |
| 010978 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.7 | 513184.4 | 77782 | 1.64041666667 | 10978 |
| 010964 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.7 | 513184.4 | 77784 | 1.64041666667 | 10964 |
| 011201 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.7 | 513184.4 | 77786 | 1.64041666667 | 11201 |
| 010120 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.7 | 513184.4 | 77788 | 1.64041666667 | 10120 |
| 011020 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:29pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.8 | 513184.4 | 77790 | 1.64041666667 | 11020 |
| 010975 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:30pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.8 | 513184.4 | 77792 | 1.64041666667 | 10975 |
| 011983 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:31pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.8 | 513184.3 | 77794 | 1.64041666667 | 11983 |
| 011366 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:32pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.7 | 513184.4 | 77796 | 1.64041666667 | 11366 |
| 011001 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:33pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.6 | 513184.8 | 77798 | 1.64041666667 | 11001 |
| 009140 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:34pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595953.1 | 513185.5 | 77800 | 1.64041666667 | 9140 |
| 011435 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:35pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595953.0 | 513186.3 | 77802 | 1.64041666667 | 11435 |
| 011228 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:36pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.9 | 513186.5 | 77804 | 1.64041666667 | 11228 |
| 011087 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:37pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595953.4 | 513186.2 | 77806 | 1.64041666667 | 11087 |
| 011141 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:38pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595953.8 | 513186.0 | 77808 | 1.64041666667 | 11141 |
| 011035 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:39pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595953.4 | 513185.7 | 77810 | 1.64041666667 | 11035 |
| 011549 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:40pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595953.1 | 513185.6 | 77812 | 1.64041666667 | 11549 |
| 014047 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:41pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595953.3 | 513185.6 | 77814 | 1.64041666667 | 14047 |
| 011731 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:42pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595953.1 | 513185.6 | 77816 | 1.64041666667 | 11731 |
| 011362 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:43pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595952.8 | 513185.7 | 77818 | 1.64041666667 | 11362 |
| 011330 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:44pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.7 | 513185.8 | 77820 | 1.64041666667 | 11330 |
| 012222 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:45pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595952.8 | 513185.7 | 77822 | 1.64041666667 | 12222 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011905 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:46pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595952.9 | 513185.7 | 77824 | 1.64041666667 | 11905 |
| 012126 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:47pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595952.9 | 513185.6 | 77826 | 1.64041666667 | 12126 |
| 011401 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:48pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.9 | 513185.6 | 77828 | 1.64041666667 | 11401 |
| 010200 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:49pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.8 | 513185.6 | 77830 | 1.64041666667 | 10200 |
| 010950 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:50pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.8 | 513185.8 | 77832 | 1.64041666667 | 10950 |
| 011857 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:51pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.6 | 513186.0 | 77834 | 1.64041666667 | 11857 |
| 011244 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:52pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.3 | 513186.1 | 77836 | 1.64041666667 | 11244 |
| 011571 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:53pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.7 | 513186.0 | 77838 | 1.64041666667 | 11571 |
| 010692 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:54pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.8 | 513185.9 | 77840 | 1.64041666667 | 10692 |
| 011223 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:55pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.9 | 513185.9 | 77842 | 1.64041666667 | 11223 |
| 011805 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:56pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.9 | 513185.9 | 77844 | 1.64041666667 | 11805 |
| 010841 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:57pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.9 | 513185.8 | 77846 | 1.64041666667 | 10841 |
| 011680 | 0 | GeoXH 6000 | 08/19/2015 | 04:45:58pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595952.9 | 513185.8 | 77848 | 1.64041666667 | 11680 |
| 011396 | 0 | GeoXH 6000 | 08/19/2015 | 04:53:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595940.5 | 513216.8 | 77849 | 1.64041666667 | 11396 |
| 011039 | 0 | GeoXH 6000 | 08/19/2015 | 04:53:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595940.5 | 513216.9 | 77851 | 1.64041666667 | 11039 |
| 011820 | 0 | GeoXH 6000 | 08/19/2015 | 04:53:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595940.6 | 513217.7 | 77853 | 1.64041666667 | 11820 |
| 011145 | 0 | GeoXH 6000 | 08/19/2015 | 04:53:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595940.8 | 513217.6 | 77855 | 1.64041666667 | 11145 |
| 012386 | 0 | GeoXH 6000 | 08/19/2015 | 04:53:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595940.1 | 513216.5 | 77857 | 1.64041666667 | 12386 |
| 011256 | 0 | GeoXH 6000 | 08/19/2015 | 04:53:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595939.9 | 513215.0 | 77859 | 1.64041666667 | 11256 |
| 011994 | 0 | GeoXH 6000 | 08/19/2015 | 04:53:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595940.3 | 513212.5 | 77861 | 1.64041666667 | 11994 |
| 010588 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595941.4 | 513210.9 | 77863 | 1.64041666667 | 10588 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595944.0 | 513210.2 | 77865 | 1.64041666667 | 12247 |
| 011611 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595946.8 | 513210.3 | 77867 | 1.64041666667 | 11611 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595950.1 | 513211.2 | 77869 | 1.64041666667 | 12652 |
| 012283 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595952.8 | 513212.1 | 77871 | 1.64041666667 | 12283 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595955.8 | 513213.3 | 77873 | 1.64041666667 | 12461 |
| 010675 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595959.0 | 513214.9 | 77875 | 1.64041666667 | 10675 |
| 010438 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595962.4 | 513216.1 | 77877 | 1.64041666667 | 10438 |
| 010769 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595965.2 | 513217.6 | 77879 | 1.64041666667 | 10769 |
| 011482 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595968.0 | 513219.2 | 77881 | 1.64041666667 | 11482 |
| 009800 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595971.2 | 513220.3 | 77883 | 1.64041666667 | 9800 |
| 010430 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595974.0 | 513221.5 | 77885 | 1.64041666667 | 10430 |
| 010887 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595976.6 | 513222.8 | 77887 | 1.64041666667 | 10887 |
| 011992 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595979.8 | 513224.4 | 77889 | 1.64041666667 | 11992 |
| 011308 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595982.4 | 513226.0 | 77891 | 1.64041666667 | 11308 |
| 012517 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595985.5 | 513227.3 | 77893 | 1.64041666667 | 12517 |
| 011559 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595988.3 | 513228.2 | 77895 | 1.64041666667 | 11559 |
| 011139 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595991.3 | 513229.4 | 77897 | 1.64041666667 | 11139 |
| 011455 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595993.9 | 513230.4 | 77899 | 1.64041666667 | 11455 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595996.9 | 513232.1 | 77901 | 1.64041666667 | 12133 |
| 013083 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595999.2 | 513233.6 | 77903 | 1.64041666667 | 13083 |
| 011430 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:21pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596002.1 | 513235.4 | 77905 | 1.64041666667 | 11430 |
| 011917 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596004.7 | 513237.1 | 77907 | 1.64041666667 | 11917 |
| 010989 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:23pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596007.9 | 513238.7 | 77909 | 1.64041666667 | 10989 |
| 009887 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596010.3 | 513240.3 | 77911 | 1.64041666667 | 9887 |
| 011171 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596013.2 | 513242.3 | 77913 | 1.64041666667 | 11171 |
| 010803 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596016.0 | 513243.6 | 77915 | 1.64041666667 | 10803 |
| 010860 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596019.1 | 513245.2 | 77917 | 1.64041666667 | 10860 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011295 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:28pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596021.5 | 513246.4 | 77919 | 1.64041666667 | 11295 |
| 012423 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:29pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596025.3 | 513247.8 | 77921 | 1.64041666667 | 12423 |
| 011866 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:30pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596028.1 | 513249.4 | 77923 | 1.64041666667 | 11866 |
| 011726 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:31pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596031.0 | 513250.9 | 77925 | 1.64041666667 | 11726 |
| 011781 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:32pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596033.9 | 513252.5 | 77927 | 1.64041666667 | 11781 |
| 013055 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:33pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596037.3 | 513254.4 | 77929 | 1.64041666667 | 13055 |
| 010913 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:34pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596039.9 | 513255.3 | 77931 | 1.64041666667 | 10913 |
| 010768 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:35pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596042.9 | 513256.1 | 77933 | 1.64041666667 | 10768 |
| 010852 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:36pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596045.9 | 513257.0 | 77935 | 1.64041666667 | 10852 |
| 010783 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:37pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596049.4 | 513258.2 | 77937 | 1.64041666667 | 10783 |
| 010705 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:38pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596051.9 | 513259.6 | 77939 | 1.64041666667 | 10705 |
| 011676 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:39pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596055.0 | 513261.3 | 77941 | 1.64041666667 | 11676 |
| 011409 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:40pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596057.5 | 513262.7 | 77943 | 1.64041666667 | 11409 |
| 010772 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:41pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596060.2 | 513264.9 | 77945 | 1.64041666667 | 10772 |
| 011693 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:42pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596062.5 | 513266.7 | 77947 | 1.64041666667 | 11693 |
| 011353 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:43pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596065.0 | 513267.9 | 77949 | 1.64041666667 | 11353 |
| 012216 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:44pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596067.5 | 513268.6 | 77951 | 1.64041666667 | 12216 |
| 011262 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:45pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596070.4 | 513268.9 | 77953 | 1.64041666667 | 11262 |
| 011935 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:46pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596073.3 | 513268.7 | 77955 | 1.64041666667 | 11935 |
| 012644 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:47pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596074.6 | 513266.8 | 77957 | 1.64041666667 | 12644 |
| 011231 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:48pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596073.8 | 513264.5 | 77959 | 1.64041666667 | 11231 |
| 014117 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:49pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596071.9 | 513261.6 | 77961 | 1.64041666667 | 14117 |
| 011029 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:50pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596069.6 | 513259.5 | 77963 | 1.64041666667 | 11029 |
| 011157 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:51pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596066.8 | 513257.7 | 77965 | 1.64041666667 | 11157 |
| 011789 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:52pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596064.0 | 513255.9 | 77967 | 1.64041666667 | 11789 |
| 011857 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:53pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596060.7 | 513254.4 | 77969 | 1.64041666667 | 11857 |
| 010464 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:54pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596058.1 | 513253.1 | 77971 | 1.64041666667 | 10464 |
| 010476 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:55pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596054.9 | 513251.5 | 77973 | 1.64041666667 | 10476 |
| 009669 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:56pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596051.6 | 513250.3 | 77975 | 1.64041666667 | 9669 |
| 010157 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:57pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596048.5 | 513248.9 | 77977 | 1.64041666667 | 10157 |
| 011389 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:58pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596045.8 | 513247.4 | 77979 | 1.64041666667 | 11389 |
| 011367 | 0 | GeoXH 6000 | 08/19/2015 | 04:54:59pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596042.2 | 513245.6 | 77981 | 1.64041666667 | 11367 |
| 010462 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:00pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596039.7 | 513244.0 | 77983 | 1.64041666667 | 10462 |
| 012665 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:01pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596036.4 | 513242.4 | 77985 | 1.64041666667 | 12665 |
| 011372 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:02pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596033.5 | 513241.6 | 77987 | 1.64041666667 | 11372 |
| 010376 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:03pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596029.8 | 513240.3 | 77989 | 1.64041666667 | 10376 |
| 010064 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:04pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596026.9 | 513239.3 | 77991 | 1.64041666667 | 10064 |
| 010916 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:05pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596023.0 | 513238.2 | 77993 | 1.64041666667 | 10916 |
| 011039 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:06pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596020.2 | 513236.9 | 77995 | 1.64041666667 | 11039 |
| 010859 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596017.1 | 513235.6 | 77997 | 1.64041666667 | 10859 |
| 011115 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:08pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596014.3 | 513235.0 | 77999 | 1.64041666667 | 11115 |
| 011598 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:09pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596011.1 | 513233.8 | 78001 | 1.64041666667 | 11598 |
| 010159 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:10pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596008.8 | 513232.9 | 78003 | 1.64041666667 | 10159 |
| 010999 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:11pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596005.3 | 513231.6 | 78005 | 1.64041666667 | 10999 |
| 013160 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596002.7 | 513230.3 | 78007 | 1.64041666667 | 13160 |
| 011540 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595999.3 | 513228.7 | 78009 | 1.64041666667 | 11540 |
| 012335 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595996.4 | 513227.5 | 78011 | 1.64041666667 | 12335 |
| 012173 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595993.2 | 513225.9 | 78013 | 1.64041666667 | 12173 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011563 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595990.7 | 513224.9 | 78015 | 1.64041666667 | 11563 |
| 011381 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595987.3 | 513223.7 | 78017 | 1.64041666667 | 11381 |
| 012055 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595984.2 | 513222.1 | 78019 | 1.64041666667 | 12055 |
| 010483 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595980.9 | 513220.7 | 78021 | 1.64041666667 | 10483 |
| 011411 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:20pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595978.2 | 513219.8 | 78023 | 1.64041666667 | 11411 |
| 011672 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:21pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595974.6 | 513218.3 | 78025 | 1.64041666667 | 11672 |
| 011618 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595971.7 | 513217.3 | 78027 | 1.64041666667 | 11618 |
| 011064 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595968.2 | 513216.1 | 78029 | 1.64041666667 | 11064 |
| 010032 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595965.3 | 513214.9 | 78031 | 1.64041666667 | 10032 |
| 009999 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595961.9 | 513214.0 | 78033 | 1.64041666667 | 9999 |
| 011919 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595958.6 | 513213.3 | 78035 | 1.64041666667 | 11919 |
| 012160 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595955.3 | 513212.2 | 78037 | 1.64041666667 | 12160 |
| 011740 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595952.2 | 513211.3 | 78039 | 1.64041666667 | 11740 |
| 013525 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:29pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595948.7 | 513210.3 | 78041 | 1.64041666667 | 13525 |
| 012411 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:30pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595946.0 | 513208.5 | 78043 | 1.64041666667 | 12411 |
| 012102 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:31pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595943.9 | 513205.9 | 78045 | 1.64041666667 | 12102 |
| 012655 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:32pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595943.7 | 513203.4 | 78047 | 1.64041666667 | 12655 |
| 011264 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:33pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595945.4 | 513201.1 | 78049 | 1.64041666667 | 11264 |
| 011756 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:34pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595947.9 | 513200.2 | 78051 | 1.64041666667 | 11756 |
| 011129 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:35pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595951.3 | 513200.1 | 78053 | 1.64041666667 | 11129 |
| 013792 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:36pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595954.4 | 513200.7 | 78055 | 1.64041666667 | 13792 |
| 012478 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:37pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595957.7 | 513201.5 | 78057 | 1.64041666667 | 12478 |
| 012809 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:38pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595960.5 | 513202.2 | 78059 | 1.64041666667 | 12809 |
| 011212 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:39pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595964.1 | 513203.8 | 78061 | 1.64041666667 | 11212 |
| 011113 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:40pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595966.7 | 513204.9 | 78063 | 1.64041666667 | 11113 |
| 012108 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:41pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595970.1 | 513206.2 | 78065 | 1.64041666667 | 12108 |
| 011067 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595973.3 | 513207.7 | 78067 | 1.64041666667 | 11067 |
| 011346 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:43pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595976.5 | 513208.8 | 78069 | 1.64041666667 | 11346 |
| 010966 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:44pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595979.8 | 513209.9 | 78071 | 1.64041666667 | 10966 |
| 010121 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:45pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595982.9 | 513211.2 | 78073 | 1.64041666667 | 10121 |
| 011350 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:46pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595985.7 | 513212.1 | 78075 | 1.64041666667 | 11350 |
| 011417 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:47pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595989.1 | 513213.3 | 78077 | 1.64041666667 | 11417 |
| 011374 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595991.9 | 513214.7 | 78079 | 1.64041666667 | 11374 |
| 011333 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595995.0 | 513216.1 | 78081 | 1.64041666667 | 11333 |
| 010153 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595997.5 | 513217.4 | 78083 | 1.64041666667 | 10153 |
| 010218 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1596000.9 | 513219.4 | 78085 | 1.64041666667 | 10218 |
| 012274 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596003.4 | 513220.7 | 78087 | 1.64041666667 | 12274 |
| 012218 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596006.7 | 513222.5 | 78089 | 1.64041666667 | 12218 |
| 010494 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596009.3 | 513224.3 | 78091 | 1.64041666667 | 10494 |
| 012523 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:55pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596012.4 | 513226.3 | 78093 | 1.64041666667 | 12523 |
| 011081 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:56pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596015.0 | 513228.1 | 78095 | 1.64041666667 | 11081 |
| 010840 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596017.7 | 513230.3 | 78097 | 1.64041666667 | 10840 |
| 010480 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:58pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596020.3 | 513232.2 | 78099 | 1.64041666667 | 10480 |
| 012580 | 0 | GeoXH 6000 | 08/19/2015 | 04:55:59pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596023.5 | 513234.1 | 78101 | 1.64041666667 | 12580 |
| 011365 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:00pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596026.2 | 513236.2 | 78103 | 1.64041666667 | 11365 |
| 012651 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:01pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596029.1 | 513237.5 | 78105 | 1.64041666667 | 12651 |
| 012792 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:02pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596032.0 | 513238.9 | 78107 | 1.64041666667 | 12792 |
| 012588 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:03pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596035.2 | 513240.8 | 78109 | 1.64041666667 | 12588 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009987 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:04pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596037.7 | 513241.9 | 78111 | 1.64041666667 | 9987 |
| 009846 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:05pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596041.2 | 513243.4 | 78113 | 1.64041666667 | 9846 |
| 009241 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:06pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596043.8 | 513245.2 | 78115 | 1.64041666667 | 9241 |
| 009870 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:07pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596046.7 | 513246.7 | 78117 | 1.64041666667 | 9870 |
| 009435 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:08pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596049.5 | 513247.9 | 78119 | 1.64041666667 | 9435 |
| 010659 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:09pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596052.9 | 513249.6 | 78121 | 1.64041666667 | 10659 |
| 009685 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:10pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596055.5 | 513250.6 | 78123 | 1.64041666667 | 9685 |
| 010701 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:11pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596058.7 | 513251.6 | 78125 | 1.64041666667 | 10701 |
| 009035 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:12pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596061.9 | 513253.0 | 78127 | 1.64041666667 | 9035 |
| 012788 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:13pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596065.0 | 513254.3 | 78129 | 1.64041666667 | 12788 |
| 011477 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:14pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596067.4 | 513255.7 | 78131 | 1.64041666667 | 11477 |
| 011599 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:15pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596070.7 | 513258.2 | 78133 | 1.64041666667 | 11599 |
| 012259 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:16pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596073.2 | 513259.7 | 78135 | 1.64041666667 | 12259 |
| 011345 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596076.3 | 513261.3 | 78137 | 1.64041666667 | 11345 |
| 013516 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:18pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596078.8 | 513262.6 | 78139 | 1.64041666667 | 13516 |
| 013099 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:19pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596081.8 | 513263.9 | 78141 | 1.64041666667 | 13099 |
| 011944 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596084.1 | 513265.2 | 78143 | 1.64041666667 | 11944 |
| 010936 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:21pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596086.0 | 513264.7 | 78145 | 1.64041666667 | 10936 |
| 012364 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:22pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596086.6 | 513262.8 | 78147 | 1.64041666667 | 12364 |
| 016561 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:23pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596085.6 | 513260.7 | 78149 | 1.64041666667 | 16561 |
| 017190 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:24pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596083.9 | 513259.3 | 78151 | 1.64041666667 | 17190 |
| 013687 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:25pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596081.7 | 513257.7 | 78153 | 1.64041666667 | 13687 |
| 012482 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:26pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596079.7 | 513255.7 | 78155 | 1.64041666667 | 12482 |
| 012750 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:27pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596077.0 | 513253.7 | 78157 | 1.64041666667 | 12750 |
| 013927 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:28pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596074.9 | 513251.9 | 78159 | 1.64041666667 | 13927 |
| 012422 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:29pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596072.4 | 513249.5 | 78161 | 1.64041666667 | 12422 |
| 010635 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:30pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596069.4 | 513248.1 | 78163 | 1.64041666667 | 10635 |
| 011208 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:31pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596066.4 | 513246.9 | 78165 | 1.64041666667 | 11208 |
| 010812 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:32pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596063.4 | 513245.8 | 78167 | 1.64041666667 | 10812 |
| 010143 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:33pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596059.8 | 513244.9 | 78169 | 1.64041666667 | 10143 |
| 010995 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:34pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596057.2 | 513244.0 | 78171 | 1.64041666667 | 10995 |
| 011478 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:35pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596054.3 | 513242.6 | 78173 | 1.64041666667 | 11478 |
| 011059 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:36pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596051.4 | 513241.5 | 78175 | 1.64041666667 | 11059 |
| 010385 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:37pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596048.0 | 513240.2 | 78177 | 1.64041666667 | 10385 |
| 010352 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:38pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596045.3 | 513239.4 | 78179 | 1.64041666667 | 10352 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:39pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596041.5 | 513238.5 | 78181 | 1.64041666667 | 11959 |
| 010939 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:40pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596038.9 | 513237.5 | 78183 | 1.64041666667 | 10939 |
| 010865 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:41pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596035.8 | 513236.0 | 78185 | 1.64041666667 | 10865 |
| 011146 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596032.8 | 513234.8 | 78187 | 1.64041666667 | 11146 |
| 010706 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:43pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596029.4 | 513233.5 | 78189 | 1.64041666667 | 10706 |
| 009846 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:44pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596026.6 | 513232.6 | 78191 | 1.64041666667 | 9846 |
| 013411 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:45pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596022.9 | 513231.4 | 78193 | 1.64041666667 | 13411 |
| 011182 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:46pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596020.1 | 513230.3 | 78195 | 1.64041666667 | 11182 |
| 011885 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:47pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596016.8 | 513229.3 | 78197 | 1.64041666667 | 11885 |
| 011671 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596014.0 | 513228.1 | 78199 | 1.64041666667 | 11671 |
| 012007 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596011.0 | 513226.4 | 78201 | 1.64041666667 | 12007 |
| 010172 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596008.3 | 513225.5 | 78203 | 1.64041666667 | 10172 |
| 011483 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596004.6 | 513224.4 | 78205 | 1.64041666667 | 11483 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010490 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596001.5 | 513223.2 | 78207 | 1.64041666667 | 10490 |
| 010602 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595997.8 | 513222.3 | 78209 | 1.64041666667 | 10602 |
| 011800 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595994.4 | 513221.7 | 78211 | 1.64041666667 | 11800 |
| 012190 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595990.7 | 513220.8 | 78213 | 1.64041666667 | 12190 |
| 012767 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595987.7 | 513220.0 | 78215 | 1.64041666667 | 12767 |
| 012491 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595984.1 | 513219.0 | 78217 | 1.64041666667 | 12491 |
| 011193 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595981.1 | 513217.7 | 78219 | 1.64041666667 | 11193 |
| 011318 | 0 | GeoXH 6000 | 08/19/2015 | 04:56:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595977.7 | 513216.2 | 78221 | 1.64041666667 | 11318 |
| 010839 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595974.6 | 513215.2 | 78223 | 1.64041666667 | 10839 |
| 010570 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595971.1 | 513213.9 | 78225 | 1.64041666667 | 10570 |
| 011282 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595968.0 | 513213.1 | 78227 | 1.64041666667 | 11282 |
| 009960 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595964.4 | 513212.5 | 78229 | 1.64041666667 | 9960 |
| 011190 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595961.2 | 513211.7 | 78231 | 1.64041666667 | 11190 |
| 014077 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595958.0 | 513210.7 | 78233 | 1.64041666667 | 14077 |
| 013149 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595955.1 | 513209.8 | 78235 | 1.64041666667 | 13149 |
| 011447 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595951.9 | 513208.1 | 78237 | 1.64041666667 | 11447 |
| 012491 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595949.9 | 513206.8 | 78239 | 1.64041666667 | 12491 |
| 012663 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595947.7 | 513204.6 | 78241 | 1.64041666667 | 12663 |
| 012285 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595947.5 | 513202.3 | 78243 | 1.64041666667 | 12285 |
| 012641 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595948.9 | 513200.0 | 78245 | 1.64041666667 | 12641 |
| 010540 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595951.2 | 513199.2 | 78247 | 1.64041666667 | 10540 |
| 011725 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595954.2 | 513199.5 | 78249 | 1.64041666667 | 11725 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595957.1 | 513200.0 | 78251 | 1.64041666667 | 11241 |
| 010580 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595960.7 | 513200.5 | 78253 | 1.64041666667 | 10580 |
| 010655 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595963.5 | 513201.2 | 78255 | 1.64041666667 | 10655 |
| 010463 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595966.4 | 513202.3 | 78257 | 1.64041666667 | 10463 |
| 010596 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595969.2 | 513203.7 | 78259 | 1.64041666667 | 10596 |
| 011139 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595972.4 | 513205.4 | 78261 | 1.64041666667 | 11139 |
| 009084 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:20pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595975.1 | 513206.1 | 78263 | 1.64041666667 | 9084 |
| 009291 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:21pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595978.0 | 513206.9 | 78265 | 1.64041666667 | 9291 |
| 010632 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595980.7 | 513208.1 | 78267 | 1.64041666667 | 10632 |
| 012018 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595984.0 | 513209.5 | 78269 | 1.64041666667 | 12018 |
| 012754 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595986.5 | 513210.9 | 78271 | 1.64041666667 | 12754 |
| 012038 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595989.3 | 513212.7 | 78273 | 1.64041666667 | 12038 |
| 011259 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595992.3 | 513214.2 | 78275 | 1.64041666667 | 11259 |
| 011485 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595995.2 | 513215.8 | 78277 | 1.64041666667 | 11485 |
| 011751 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595997.6 | 513217.0 | 78279 | 1.64041666667 | 11751 |
| 011637 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:29pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596000.7 | 513218.3 | 78281 | 1.64041666667 | 11637 |
| 012629 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:30pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596003.3 | 513219.8 | 78283 | 1.64041666667 | 12629 |
| 012037 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:31pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596006.2 | 513221.4 | 78285 | 1.64041666667 | 12037 |
| 013179 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:32pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596008.4 | 513222.6 | 78287 | 1.64041666667 | 13179 |
| 010644 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:33pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596011.5 | 513223.9 | 78289 | 1.64041666667 | 10644 |
| 010281 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:34pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596014.0 | 513224.9 | 78291 | 1.64041666667 | 10281 |
| 010190 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:35pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596017.1 | 513226.4 | 78293 | 1.64041666667 | 10190 |
| 010947 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:36pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596019.5 | 513227.4 | 78295 | 1.64041666667 | 10947 |
| 010327 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:37pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596022.7 | 513228.6 | 78297 | 1.64041666667 | 10327 |
| 010921 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:38pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596025.2 | 513229.8 | 78299 | 1.64041666667 | 10921 |
| 011400 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:39pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596028.3 | 513231.1 | 78301 | 1.64041666667 | 11400 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010920 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:40pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596030.7 | 513232.4 | 78303 | 1.64041666667 | 10920 |
| 012300 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:41pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596033.5 | 513233.9 | 78305 | 1.64041666667 | 12300 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:42pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596036.1 | 513235.0 | 78307 | 1.64041666667 | 14355 |
| 011208 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:43pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596039.1 | 513236.5 | 78309 | 1.64041666667 | 11208 |
| 010902 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:44pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596041.5 | 513237.3 | 78311 | 1.64041666667 | 10902 |
| 010405 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:45pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596044.6 | 513238.1 | 78313 | 1.64041666667 | 10405 |
| 009981 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:46pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596047.3 | 513239.5 | 78315 | 1.64041666667 | 9981 |
| 010805 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:47pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596050.2 | 513240.9 | 78317 | 1.64041666667 | 10805 |
| 010441 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:48pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596052.8 | 513242.4 | 78319 | 1.64041666667 | 10441 |
| 011430 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:49pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596055.7 | 513244.0 | 78321 | 1.64041666667 | 11430 |
| 011767 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:50pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596058.2 | 513245.3 | 78323 | 1.64041666667 | 11767 |
| 011402 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:51pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596061.0 | 513247.1 | 78325 | 1.64041666667 | 11402 |
| 013770 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:52pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596063.1 | 513248.4 | 78327 | 1.64041666667 | 13770 |
| 011722 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:53pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596066.0 | 513250.1 | 78329 | 1.64041666667 | 11722 |
| 012440 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:54pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596068.2 | 513251.9 | 78331 | 1.64041666667 | 12440 |
| 011300 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:55pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596070.7 | 513253.5 | 78333 | 1.64041666667 | 11300 |
| 012875 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:56pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596073.1 | 513254.4 | 78335 | 1.64041666667 | 12875 |
| 011258 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:57pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596075.8 | 513255.3 | 78337 | 1.64041666667 | 11258 |
| 011544 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:58pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596078.5 | 513256.1 | 78339 | 1.64041666667 | 11544 |
| 016776 | 0 | GeoXH 6000 | 08/19/2015 | 04:57:59pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596081.2 | 513257.6 | 78341 | 1.64041666667 | 16776 |
| 018684 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:00pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596083.0 | 513258.9 | 78343 | 1.64041666667 | 18684 |
| 016431 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:01pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596085.1 | 513260.1 | 78345 | 1.64041666667 | 16431 |
| 014247 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:02pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596087.0 | 513260.6 | 78347 | 1.64041666667 | 14247 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:03pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596089.4 | 513260.9 | 78349 | 1.64041666667 | 14602 |
| 015230 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:04pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596091.0 | 513261.3 | 78351 | 1.64041666667 | 15230 |
| 013317 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:05pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596091.0 | 513261.7 | 78353 | 1.64041666667 | 13317 |
| 012959 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:06pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596089.2 | 513262.0 | 78355 | 1.64041666667 | 12959 |
| 015180 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:07pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596086.2 | 513262.1 | 78357 | 1.64041666667 | 15180 |
| 018945 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:08pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596083.5 | 513262.0 | 78359 | 1.64041666667 | 18945 |
| 014876 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:09pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596080.2 | 513262.2 | 78361 | 1.64041666667 | 14876 |
| 012749 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:10pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596077.0 | 513262.9 | 78363 | 1.64041666667 | 12749 |
| 011077 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:11pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596074.0 | 513263.5 | 78365 | 1.64041666667 | 11077 |
| 011979 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:12pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596071.3 | 513263.9 | 78367 | 1.64041666667 | 11979 |
| 010824 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:13pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596068.4 | 513265.0 | 78369 | 1.64041666667 | 10824 |
| 010866 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:14pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596066.5 | 513265.7 | 78371 | 1.64041666667 | 10866 |
| 010756 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:15pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596065.8 | 513265.6 | 78373 | 1.64041666667 | 10756 |
| 010159 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:16pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596066.4 | 513266.3 | 78375 | 1.64041666667 | 10159 |
| 011929 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596065.8 | 513268.4 | 78377 | 1.64041666667 | 11929 |
| 012762 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:18pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596065.1 | 513270.7 | 78379 | 1.64041666667 | 12762 |
| 012550 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:19pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596064.7 | 513272.6 | 78381 | 1.64041666667 | 12550 |
| 012737 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596064.5 | 513273.0 | 78383 | 1.64041666667 | 12737 |
| 011914 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:21pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596064.1 | 513274.2 | 78385 | 1.64041666667 | 11914 |
| 014408 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:22pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596063.6 | 513276.1 | 78387 | 1.64041666667 | 14408 |
| 018122 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:23pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596062.9 | 513279.6 | 78389 | 1.64041666667 | 18122 |
| 019170 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596062.3 | 513281.7 | 78391 | 1.64041666667 | 19170 |
| 018562 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1596061.9 | 513282.5 | 78393 | 1.64041666667 | 18562 |
| 019310 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:26pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1596061.9 | 513282.7 | 78395 | 1.64041666667 | 19310 |
| 016587 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1596061.8 | 513282.7 | 78397 | 1.64041666667 | 16587 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017527 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596062.3 | 513282.2 | 78399 | 1.64041666667 | 17527 |
| 018481 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:29pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596063.6 | 513281.1 | 78401 | 1.64041666667 | 18481 |
| 014850 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:30pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596064.1 | 513279.6 | 78403 | 1.64041666667 | 14850 |
| 012532 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:31pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596064.0 | 513277.8 | 78405 | 1.64041666667 | 12532 |
| 011833 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:32pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596064.5 | 513276.3 | 78407 | 1.64041666667 | 11833 |
| 012258 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:33pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596064.8 | 513274.5 | 78409 | 1.64041666667 | 12258 |
| 012964 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:34pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596063.7 | 513273.7 | 78411 | 1.64041666667 | 12964 |
| 012841 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:35pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596061.1 | 513272.6 | 78413 | 1.64041666667 | 12841 |
| 013770 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:36pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596058.8 | 513271.6 | 78415 | 1.64041666667 | 13770 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:37pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596055.7 | 513270.3 | 78417 | 1.64041666667 | 14602 |
| 014540 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:38pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596053.0 | 513268.7 | 78419 | 1.64041666667 | 14540 |
| 013535 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:39pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596050.3 | 513267.6 | 78421 | 1.64041666667 | 13535 |
| 013193 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:40pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596048.2 | 513266.5 | 78423 | 1.64041666667 | 13193 |
| 012028 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:41pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596045.4 | 513264.9 | 78425 | 1.64041666667 | 12028 |
| 015247 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596042.8 | 513263.6 | 78427 | 1.64041666667 | 15247 |
| 012631 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:43pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596040.0 | 513262.0 | 78429 | 1.64041666667 | 12631 |
| 013927 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:44pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596037.9 | 513261.0 | 78431 | 1.64041666667 | 13927 |
| 013052 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:45pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596035.2 | 513260.1 | 78433 | 1.64041666667 | 13052 |
| 013463 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:46pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596032.4 | 513258.9 | 78435 | 1.64041666667 | 13463 |
| 012185 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:47pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596029.4 | 513258.2 | 78437 | 1.64041666667 | 12185 |
| 014146 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596026.6 | 513257.3 | 78439 | 1.64041666667 | 14146 |
| 013256 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:49pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596023.6 | 513256.7 | 78441 | 1.64041666667 | 13256 |
| 013304 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596020.9 | 513256.2 | 78443 | 1.64041666667 | 13304 |
| 012746 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596017.7 | 513254.3 | 78445 | 1.64041666667 | 12746 |
| 012906 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596015.1 | 513252.8 | 78447 | 1.64041666667 | 12906 |
| 011086 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596012.2 | 513251.5 | 78449 | 1.64041666667 | 11086 |
| 012731 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596009.4 | 513250.4 | 78451 | 1.64041666667 | 12731 |
| 011253 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1596005.7 | 513249.5 | 78453 | 1.64041666667 | 11253 |
| 013043 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1596002.8 | 513248.3 | 78455 | 1.64041666667 | 13043 |
| 012350 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595999.9 | 513247.6 | 78457 | 1.64041666667 | 12350 |
| 010767 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595997.5 | 513247.1 | 78459 | 1.64041666667 | 10767 |
| 010702 | 0 | GeoXH 6000 | 08/19/2015 | 04:58:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595994.3 | 513245.5 | 78461 | 1.64041666667 | 10702 |
| 011765 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595991.5 | 513244.3 | 78463 | 1.64041666667 | 11765 |
| 009661 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595988.8 | 513243.1 | 78465 | 1.64041666667 | 9661 |
| 010815 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595986.1 | 513241.8 | 78467 | 1.64041666667 | 10815 |
| 010923 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595982.8 | 513240.6 | 78469 | 1.64041666667 | 10923 |
| 010801 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595980.3 | 513239.3 | 78471 | 1.64041666667 | 10801 |
| 010920 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595977.4 | 513237.9 | 78473 | 1.64041666667 | 10920 |
| 011910 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595974.6 | 513236.9 | 78475 | 1.64041666667 | 11910 |
| 013717 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595971.5 | 513235.5 | 78477 | 1.64041666667 | 13717 |
| 012129 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595969.0 | 513234.5 | 78479 | 1.64041666667 | 12129 |
| 013202 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595966.3 | 513233.1 | 78481 | 1.64041666667 | 13202 |
| 011941 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595963.6 | 513231.7 | 78483 | 1.64041666667 | 11941 |
| 012232 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595960.2 | 513230.5 | 78485 | 1.64041666667 | 12232 |
| 013438 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595957.5 | 513228.9 | 78487 | 1.64041666667 | 13438 |
| 011249 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595954.8 | 513227.1 | 78489 | 1.64041666667 | 11249 |
| 011722 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595952.3 | 513225.5 | 78491 | 1.64041666667 | 11722 |
| 011840 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595949.5 | 513223.2 | 78493 | 1.64041666667 | 11840 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011240 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595947.2 | 513221.9 | 78495 | 1.64041666667 | 11240 |
| 011390 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595944.5 | 513220.3 | 78497 | 1.64041666667 | 11390 |
| 013767 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595942.3 | 513219.3 | 78499 | 1.64041666667 | 13767 |
| 012832 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595940.4 | 513218.7 | 78501 | 1.64041666667 | 12832 |
| 012568 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:20pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595940.1 | 513218.6 | 78503 | 1.64041666667 | 12568 |
| 011122 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:21pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595940.4 | 513218.6 | 78505 | 1.64041666667 | 11122 |
| 011390 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595941.1 | 513218.7 | 78507 | 1.64041666667 | 11390 |
| 010767 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595940.7 | 513220.2 | 78509 | 1.64041666667 | 10767 |
| 011092 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595939.9 | 513222.9 | 78511 | 1.64041666667 | 11092 |
| 013243 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595939.1 | 513225.6 | 78513 | 1.64041666667 | 13243 |
| 011710 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595938.2 | 513226.7 | 78515 | 1.64041666667 | 11710 |
| 011117 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595937.9 | 513226.9 | 78517 | 1.64041666667 | 11117 |
| 011659 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595938.0 | 513226.9 | 78519 | 1.64041666667 | 11659 |
| 011824 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:29pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595938.2 | 513228.2 | 78521 | 1.64041666667 | 11824 |
| 010726 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:30pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595938.1 | 513230.7 | 78523 | 1.64041666667 | 10726 |
| 010541 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:31pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595937.3 | 513234.0 | 78525 | 1.64041666667 | 10541 |
| 010225 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:32pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595936.6 | 513236.2 | 78527 | 1.64041666667 | 10225 |
| 010326 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:33pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1595936.3 | 513237.9 | 78529 | 1.64041666667 | 10326 |
| 009901 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:34pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595936.5 | 513237.5 | 78531 | 1.64041666667 | 9901 |
| 011085 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:35pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595936.6 | 513235.5 | 78533 | 1.64041666667 | 11085 |
| 011711 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:36pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595936.3 | 513233.7 | 78535 | 1.64041666667 | 11711 |
| 010008 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:37pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595936.2 | 513231.1 | 78537 | 1.64041666667 | 10008 |
| 010212 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:38pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595936.6 | 513229.3 | 78539 | 1.64041666667 | 10212 |
| 011163 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:39pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595938.6 | 513227.8 | 78541 | 1.64041666667 | 11163 |
| 012030 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:40pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595940.5 | 513227.1 | 78543 | 1.64041666667 | 12030 |
| 011047 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:41pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595943.0 | 513227.7 | 78545 | 1.64041666667 | 11047 |
| 012842 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595945.4 | 513228.7 | 78547 | 1.64041666667 | 12842 |
| 014040 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:43pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595948.4 | 513229.8 | 78549 | 1.64041666667 | 14040 |
| 011310 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:44pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595951.0 | 513231.1 | 78551 | 1.64041666667 | 11310 |
| 010867 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:45pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595954.1 | 513232.3 | 78553 | 1.64041666667 | 10867 |
| 012887 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:46pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595956.7 | 513233.4 | 78555 | 1.64041666667 | 12887 |
| 012101 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:47pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595959.6 | 513234.8 | 78557 | 1.64041666667 | 12101 |
| 012385 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595962.1 | 513236.0 | 78559 | 1.64041666667 | 12385 |
| 010896 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595964.8 | 513237.5 | 78561 | 1.64041666667 | 10896 |
| 011214 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595967.1 | 513238.5 | 78563 | 1.64041666667 | 11214 |
| 011293 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595969.9 | 513239.4 | 78565 | 1.64041666667 | 11293 |
| 012393 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595972.2 | 513240.3 | 78567 | 1.64041666667 | 12393 |
| 012308 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595975.4 | 513241.1 | 78569 | 1.64041666667 | 12308 |
| 011267 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595978.2 | 513242.2 | 78571 | 1.64041666667 | 11267 |
| 011546 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595981.1 | 513243.2 | 78573 | 1.64041666667 | 11546 |
| 011316 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595983.5 | 513244.0 | 78575 | 1.64041666667 | 11316 |
| 011229 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595986.4 | 513245.0 | 78577 | 1.64041666667 | 11229 |
| 011417 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595988.7 | 513245.9 | 78579 | 1.64041666667 | 11417 |
| 010534 | 0 | GeoXH 6000 | 08/19/2015 | 04:59:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595991.2 | 513247.5 | 78581 | 1.64041666667 | 10534 |
| 011213 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595993.4 | 513248.5 | 78583 | 1.64041666667 | 11213 |
| 011323 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595996.4 | 513249.7 | 78585 | 1.64041666667 | 11323 |
| 012221 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595998.8 | 513251.1 | 78587 | 1.64041666667 | 12221 |
| 011515 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1596001.9 | 513252.5 | 78589 | 1.64041666667 | 11515 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009868 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596004.3 | 513253.8 | 78591 | 1.64041666667 | 9868 |
| 010267 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596006.9 | 513255.3 | 78593 | 1.64041666667 | 10267 |
| 012166 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596009.3 | 513256.6 | 78595 | 1.64041666667 | 12166 |
| 012071 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596011.9 | 513258.7 | 78597 | 1.64041666667 | 12071 |
| 011628 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596014.1 | 513259.9 | 78599 | 1.64041666667 | 11628 |
| 012087 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596016.8 | 513260.9 | 78601 | 1.64041666667 | 12087 |
| 012831 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596019.2 | 513261.7 | 78603 | 1.64041666667 | 12831 |
| 014038 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596022.1 | 513262.4 | 78605 | 1.64041666667 | 14038 |
| 013139 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596024.8 | 513263.6 | 78607 | 1.64041666667 | 13139 |
| 015525 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596027.8 | 513264.6 | 78609 | 1.64041666667 | 15525 |
| 014531 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596030.4 | 513265.5 | 78611 | 1.64041666667 | 14531 |
| 012452 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:15pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596032.8 | 513266.2 | 78613 | 1.64041666667 | 12452 |
| 012323 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:16pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596034.9 | 513267.0 | 78615 | 1.64041666667 | 12323 |
| 012980 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596037.2 | 513268.8 | 78617 | 1.64041666667 | 12980 |
| 013595 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:18pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596039.4 | 513270.1 | 78619 | 1.64041666667 | 13595 |
| 013808 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:19pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596042.0 | 513271.9 | 78621 | 1.64041666667 | 13808 |
| 014492 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596043.9 | 513273.4 | 78623 | 1.64041666667 | 14492 |
| 016583 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:21pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596046.2 | 513275.0 | 78625 | 1.64041666667 | 16583 |
| 015395 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:22pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596048.1 | 513276.4 | 78627 | 1.64041666667 | 15395 |
| 020139 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596050.9 | 513277.6 | 78629 | 1.64041666667 | 20139 |
| 021054 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596053.2 | 513278.6 | 78631 | 1.64041666667 | 21054 |
| 018883 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:25pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596056.3 | 513279.6 | 78633 | 1.64041666667 | 18883 |
| 018071 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:26pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596058.3 | 513280.4 | 78635 | 1.64041666667 | 18071 |
| 017657 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:27pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596060.5 | 513281.1 | 78637 | 1.64041666667 | 17657 |
| 016294 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:28pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596061.8 | 513280.8 | 78639 | 1.64041666667 | 16294 |
| 016133 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:29pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596061.9 | 513280.2 | 78641 | 1.64041666667 | 16133 |
| 018133 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:30pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596061.8 | 513280.1 | 78643 | 1.64041666667 | 18133 |
| 017463 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:31pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596062.0 | 513280.2 | 78645 | 1.64041666667 | 17463 |
| 015885 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:32pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596062.3 | 513280.6 | 78647 | 1.64041666667 | 15885 |
| 015941 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:33pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596062.2 | 513280.8 | 78649 | 1.64041666667 | 15941 |
| 016885 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:34pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596061.3 | 513280.4 | 78651 | 1.64041666667 | 16885 |
| 018741 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:35pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596059.8 | 513279.7 | 78653 | 1.64041666667 | 18741 |
| 020435 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:36pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596058.4 | 513278.9 | 78655 | 1.64041666667 | 20435 |
| 018728 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:37pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596056.8 | 513278.8 | 78657 | 1.64041666667 | 18728 |
| 021062 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:38pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596055.4 | 513279.1 | 78659 | 1.64041666667 | 21062 |
| 024225 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:39pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1596053.9 | 513279.9 | 78661 | 1.64041666667 | 24225 |
| 022826 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:40pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1596054.0 | 513279.6 | 78663 | 1.64041666667 | 22826 |
| 023256 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:41pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1596054.5 | 513278.5 | 78665 | 1.64041666667 | 23256 |
| 024174 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:42pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1596054.4 | 513278.1 | 78667 | 1.64041666667 | 24174 |
| 024523 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:43pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1596054.1 | 513278.5 | 78669 | 1.64041666667 | 24523 |
| 024131 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:44pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1596055.1 | 513278.4 | 78671 | 1.64041666667 | 24131 |
| 022922 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:45pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596057.0 | 513278.1 | 78673 | 1.64041666667 | 22922 |
| 020790 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:46pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596057.9 | 513278.4 | 78675 | 1.64041666667 | 20790 |
| 021157 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:47pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596058.3 | 513279.5 | 78677 | 1.64041666667 | 21157 |
| 018849 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:48pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596058.5 | 513279.7 | 78679 | 1.64041666667 | 18849 |
| 018662 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:49pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596058.5 | 513279.8 | 78681 | 1.64041666667 | 18662 |
| 019005 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:50pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596058.6 | 513279.8 | 78683 | 1.64041666667 | 19005 |
| 018851 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:51pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596058.9 | 513279.6 | 78685 | 1.64041666667 | 18851 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017793 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:52pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596059.3 | 513279.9 | 78687 | 1.64041666667 | 17793 |
| 017138 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:53pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596060.9 | 513281.3 | 78689 | 1.64041666667 | 17138 |
| 017934 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596062.1 | 513282.1 | 78691 | 1.64041666667 | 17934 |
| 018853 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:55pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596061.5 | 513282.0 | 78693 | 1.64041666667 | 18853 |
| 019443 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:56pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596061.5 | 513282.4 | 78695 | 1.64041666667 | 19443 |
| 016560 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:57pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596062.0 | 513285.1 | 78697 | 1.64041666667 | 16560 |
| 015540 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:58pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596062.4 | 513287.6 | 78699 | 1.64041666667 | 15540 |
| 012675 | 0 | GeoXH 6000 | 08/19/2015 | 05:00:59pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596062.2 | 513288.4 | 78701 | 1.64041666667 | 12675 |
| 011448 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:00pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596061.7 | 513289.5 | 78703 | 1.64041666667 | 11448 |
| 012762 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:01pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596061.0 | 513292.1 | 78705 | 1.64041666667 | 12762 |
| 012400 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:02pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596060.4 | 513294.6 | 78707 | 1.64041666667 | 12400 |
| 012310 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:03pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596060.1 | 513296.6 | 78709 | 1.64041666667 | 12310 |
| 010067 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:04pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596059.7 | 513297.1 | 78711 | 1.64041666667 | 10067 |
| 011876 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:05pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596059.6 | 513297.1 | 78713 | 1.64041666667 | 11876 |
| 011759 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:06pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596059.7 | 513297.1 | 78715 | 1.64041666667 | 11759 |
| 011580 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:07pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596059.9 | 513296.6 | 78717 | 1.64041666667 | 11580 |
| 013155 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:08pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596060.0 | 513295.9 | 78719 | 1.64041666667 | 13155 |
| 010668 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:09pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596059.8 | 513296.4 | 78721 | 1.64041666667 | 10668 |
| 011457 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596059.5 | 513297.2 | 78723 | 1.64041666667 | 11457 |
| 011054 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1596059.3 | 513297.6 | 78725 | 1.64041666667 | 11054 |
| 011403 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:12pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596059.9 | 513296.8 | 78727 | 1.64041666667 | 11403 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:13pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596061.1 | 513295.3 | 78729 | 1.64041666667 | 12840 |
| 014430 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:14pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596061.1 | 513294.1 | 78731 | 1.64041666667 | 14430 |
| 016477 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:15pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596060.4 | 513291.9 | 78733 | 1.64041666667 | 16477 |
| 014349 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:16pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596060.2 | 513290.2 | 78735 | 1.64041666667 | 14349 |
| 013547 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596059.3 | 513289.0 | 78737 | 1.64041666667 | 13547 |
| 011696 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:18pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596057.5 | 513288.5 | 78739 | 1.64041666667 | 11696 |
| 013514 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:19pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596054.6 | 513287.4 | 78741 | 1.64041666667 | 13514 |
| 013428 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596051.4 | 513286.6 | 78743 | 1.64041666667 | 13428 |
| 012357 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:21pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596048.6 | 513285.6 | 78745 | 1.64041666667 | 12357 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:22pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596046.3 | 513284.4 | 78747 | 1.64041666667 | 12539 |
| 011205 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:23pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596043.3 | 513283.6 | 78749 | 1.64041666667 | 11205 |
| 012791 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:24pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596040.6 | 513282.8 | 78751 | 1.64041666667 | 12791 |
| 011357 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:25pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596037.6 | 513282.3 | 78753 | 1.64041666667 | 11357 |
| 012679 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:26pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596035.1 | 513281.7 | 78755 | 1.64041666667 | 12679 |
| 012829 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:27pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596032.4 | 513280.5 | 78757 | 1.64041666667 | 12829 |
| 014037 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:28pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596029.9 | 513279.5 | 78759 | 1.64041666667 | 14037 |
| 012149 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:29pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596027.1 | 513278.2 | 78761 | 1.64041666667 | 12149 |
| 011587 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:30pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596024.2 | 513277.2 | 78763 | 1.64041666667 | 11587 |
| 013966 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:31pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596021.3 | 513276.0 | 78765 | 1.64041666667 | 13966 |
| 011741 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:32pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596018.9 | 513274.7 | 78767 | 1.64041666667 | 11741 |
| 012985 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:33pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596016.3 | 513273.7 | 78769 | 1.64041666667 | 12985 |
| 011736 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:34pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596013.9 | 513272.9 | 78771 | 1.64041666667 | 11736 |
| 012144 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:35pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596010.7 | 513272.3 | 78773 | 1.64041666667 | 12144 |
| 013926 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:36pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1596008.2 | 513271.5 | 78775 | 1.64041666667 | 13926 |
| 010861 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:37pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596005.2 | 513270.2 | 78777 | 1.64041666667 | 10861 |
| 010875 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:38pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596002.7 | 513269.0 | 78779 | 1.64041666667 | 10875 |
| 011598 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:39pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595999.9 | 513267.3 | 78781 | 1.64041666667 | 11598 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011149 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:40pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595997.3 | 513266.4 | 78783 | 1.64041666667 | 11149 |
| 011607 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:41pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595994.5 | 513264.5 | 78785 | 1.64041666667 | 11607 |
| 009982 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595992.5 | 513262.8 | 78787 | 1.64041666667 | 9982 |
| 012365 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:43pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595990.6 | 513261.3 | 78789 | 1.64041666667 | 12365 |
| 011941 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:44pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595990.0 | 513260.6 | 78791 | 1.64041666667 | 11941 |
| 011205 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:45pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595989.5 | 513260.6 | 78793 | 1.64041666667 | 11205 |
| 012161 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:46pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595988.4 | 513260.7 | 78795 | 1.64041666667 | 12161 |
| 012580 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:47pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595986.0 | 513260.6 | 78797 | 1.64041666667 | 12580 |
| 011515 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595983.7 | 513259.7 | 78799 | 1.64041666667 | 11515 |
| 010798 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595981.2 | 513257.8 | 78801 | 1.64041666667 | 10798 |
| 011489 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595979.0 | 513256.7 | 78803 | 1.64041666667 | 11489 |
| 011692 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595975.9 | 513255.2 | 78805 | 1.64041666667 | 11692 |
| 011173 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595973.0 | 513254.4 | 78807 | 1.64041666667 | 11173 |
| 011133 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595969.6 | 513253.2 | 78809 | 1.64041666667 | 11133 |
| 011513 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595967.3 | 513252.1 | 78811 | 1.64041666667 | 11513 |
| 011128 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595964.4 | 513251.2 | 78813 | 1.64041666667 | 11128 |
| 010432 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595961.9 | 513250.2 | 78815 | 1.64041666667 | 10432 |
| 009658 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595958.5 | 513249.4 | 78817 | 1.64041666667 | 9658 |
| 012194 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595956.3 | 513248.6 | 78819 | 1.64041666667 | 12194 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 05:01:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595953.8 | 513247.0 | 78821 | 1.64041666667 | 12078 |
| 012109 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595951.8 | 513245.9 | 78823 | 1.64041666667 | 12109 |
| 012747 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595949.4 | 513244.2 | 78825 | 1.64041666667 | 12747 |
| 012157 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595947.4 | 513243.0 | 78827 | 1.64041666667 | 12157 |
| 012519 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595944.9 | 513241.5 | 78829 | 1.64041666667 | 12519 |
| 011559 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595942.6 | 513240.3 | 78831 | 1.64041666667 | 11559 |
| 011680 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595940.3 | 513238.9 | 78833 | 1.64041666667 | 11680 |
| 011320 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595938.6 | 513237.8 | 78835 | 1.64041666667 | 11320 |
| 011890 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:07pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595937.0 | 513237.6 | 78837 | 1.64041666667 | 11890 |
| 011702 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:08pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595936.9 | 513237.5 | 78839 | 1.64041666667 | 11702 |
| 012705 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:09pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595937.5 | 513237.1 | 78841 | 1.64041666667 | 12705 |
| 010256 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595938.1 | 513237.4 | 78843 | 1.64041666667 | 10256 |
| 010124 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595937.2 | 513237.5 | 78845 | 1.64041666667 | 10124 |
| 011741 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595936.6 | 513238.9 | 78847 | 1.64041666667 | 11741 |
| 011815 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595935.5 | 513241.9 | 78849 | 1.64041666667 | 11815 |
| 010393 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595934.8 | 513243.2 | 78851 | 1.64041666667 | 10393 |
| 010188 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595934.8 | 513243.7 | 78853 | 1.64041666667 | 10188 |
| 010497 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595934.7 | 513244.2 | 78855 | 1.64041666667 | 10497 |
| 011594 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595934.3 | 513246.0 | 78857 | 1.64041666667 | 11594 |
| 009768 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:18pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595933.3 | 513248.4 | 78859 | 1.64041666667 | 9768 |
| 010602 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:19pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595932.3 | 513251.4 | 78861 | 1.64041666667 | 10602 |
| 010600 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:20pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595931.6 | 513252.9 | 78863 | 1.64041666667 | 10600 |
| 011590 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:21pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595931.6 | 513253.2 | 78865 | 1.64041666667 | 11590 |
| 011537 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:22pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595931.9 | 513252.6 | 78867 | 1.64041666667 | 11537 |
| 011314 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:23pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595932.6 | 513251.3 | 78869 | 1.64041666667 | 11314 |
| 011378 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:24pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595932.7 | 513250.0 | 78871 | 1.64041666667 | 11378 |
| 011244 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595933.0 | 513248.5 | 78873 | 1.64041666667 | 11244 |
| 009441 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595934.0 | 513247.1 | 78875 | 1.64041666667 | 9441 |
| 010760 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595935.0 | 513245.4 | 78877 | 1.64041666667 | 10760 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011480 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595935.8 | 513244.6 | 78879 | 1.64041666667 | 11480 |
| 011780 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:29pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595937.3 | 513245.1 | 78881 | 1.64041666667 | 11780 |
| 011015 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:30pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595939.7 | 513245.8 | 78883 | 1.64041666667 | 11015 |
| 010793 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:31pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595942.3 | 513246.9 | 78885 | 1.64041666667 | 10793 |
| 010228 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:32pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595944.8 | 513247.8 | 78887 | 1.64041666667 | 10228 |
| 012577 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:33pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595947.5 | 513248.4 | 78889 | 1.64041666667 | 12577 |
| 011964 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:34pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595949.8 | 513249.6 | 78891 | 1.64041666667 | 11964 |
| 010671 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:35pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595953.1 | 513251.2 | 78893 | 1.64041666667 | 10671 |
| 010767 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:36pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595955.3 | 513252.4 | 78895 | 1.64041666667 | 10767 |
| 010672 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:37pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595958.0 | 513253.8 | 78897 | 1.64041666667 | 10672 |
| 011308 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:38pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595960.7 | 513254.8 | 78899 | 1.64041666667 | 11308 |
| 011647 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:39pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595963.5 | 513256.1 | 78901 | 1.64041666667 | 11647 |
| 012421 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:40pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595966.2 | 513257.0 | 78903 | 1.64041666667 | 12421 |
| 010875 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:41pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595969.5 | 513258.3 | 78905 | 1.64041666667 | 10875 |
| 011298 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595972.0 | 513259.2 | 78907 | 1.64041666667 | 11298 |
| 011344 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:43pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595975.3 | 513260.1 | 78909 | 1.64041666667 | 11344 |
| 009976 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:44pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595977.9 | 513261.2 | 78911 | 1.64041666667 | 9976 |
| 011344 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:45pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595980.7 | 513262.5 | 78913 | 1.64041666667 | 11344 |
| 011086 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:46pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595983.1 | 513264.0 | 78915 | 1.64041666667 | 11086 |
| 011141 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:47pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595985.6 | 513265.7 | 78917 | 1.64041666667 | 11141 |
| 010615 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595988.1 | 513266.8 | 78919 | 1.64041666667 | 10615 |
| 009704 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595990.9 | 513268.6 | 78921 | 1.64041666667 | 9704 |
| 010916 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595994.0 | 513270.1 | 78923 | 1.64041666667 | 10916 |
| 010199 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595997.0 | 513271.5 | 78925 | 1.64041666667 | 10199 |
| 012599 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595999.3 | 513272.4 | 78927 | 1.64041666667 | 12599 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596002.1 | 513273.3 | 78929 | 1.64041666667 | 12420 |
| 012435 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1596004.4 | 513274.9 | 78931 | 1.64041666667 | 12435 |
| 013278 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596007.1 | 513276.6 | 78933 | 1.64041666667 | 13278 |
| 013609 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596009.6 | 513277.9 | 78935 | 1.64041666667 | 13609 |
| 011292 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596012.0 | 513279.3 | 78937 | 1.64041666667 | 11292 |
| 011343 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596014.8 | 513280.6 | 78939 | 1.64041666667 | 11343 |
| 011415 | 0 | GeoXH 6000 | 08/19/2015 | 05:02:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596017.4 | 513282.4 | 78941 | 1.64041666667 | 11415 |
| 011223 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:00pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596019.9 | 513283.9 | 78943 | 1.64041666667 | 11223 |
| 010246 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:01pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596022.7 | 513285.0 | 78945 | 1.64041666667 | 10246 |
| 010181 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:02pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596025.1 | 513285.9 | 78947 | 1.64041666667 | 10181 |
| 010765 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:03pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596028.2 | 513286.5 | 78949 | 1.64041666667 | 10765 |
| 009591 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:04pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596031.3 | 513287.2 | 78951 | 1.64041666667 | 9591 |
| 013317 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:05pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596034.2 | 513287.5 | 78953 | 1.64041666667 | 13317 |
| 014039 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:06pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596036.7 | 513287.8 | 78955 | 1.64041666667 | 14039 |
| 012630 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:07pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596039.3 | 513288.9 | 78957 | 1.64041666667 | 12630 |
| 011407 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:08pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596041.9 | 513290.2 | 78959 | 1.64041666667 | 11407 |
| 012511 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:09pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596044.6 | 513291.8 | 78961 | 1.64041666667 | 12511 |
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:10pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596047.5 | 513292.9 | 78963 | 1.64041666667 | 12937 |
| 011724 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:11pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596050.2 | 513293.7 | 78965 | 1.64041666667 | 11724 |
| 011511 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:12pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596052.7 | 513295.0 | 78967 | 1.64041666667 | 11511 |
| 011427 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:13pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596055.3 | 513296.0 | 78969 | 1.64041666667 | 11427 |
| 011437 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:14pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596057.3 | 513297.1 | 78971 | 1.64041666667 | 11437 |
| 010839 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:15pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596059.3 | 513297.9 | 78973 | 1.64041666667 | 10839 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010359 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:16pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596060.6 | 513298.0 | 78975 | 1.64041666667 | 10359 |
| 009850 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596059.9 | 513297.8 | 78977 | 1.64041666667 | 9850 |
| 011222 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:18pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596059.0 | 513297.9 | 78979 | 1.64041666667 | 11222 |
| 011235 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:19pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596058.4 | 513299.3 | 78981 | 1.64041666667 | 11235 |
| 011328 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596056.7 | 513301.8 | 78983 | 1.64041666667 | 11328 |
| 011652 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:21pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596056.1 | 513303.5 | 78985 | 1.64041666667 | 11652 |
| 011133 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:22pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596056.2 | 513303.7 | 78987 | 1.64041666667 | 11133 |
| 010793 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:23pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596055.5 | 513304.5 | 78989 | 1.64041666667 | 10793 |
| 012778 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:24pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596054.0 | 513306.5 | 78991 | 1.64041666667 | 12778 |
| 010964 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:25pm | Sensor | 1797-S0051=G-TJV.cor | 6845.0 | 1596052.8 | 513308.9 | 78993 | 1.64041666667 | 10964 |
| 011261 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:26pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596051.6 | 513310.6 | 78995 | 1.64041666667 | 11261 |
| 010885 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:27pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596051.1 | 513311.7 | 78997 | 1.64041666667 | 10885 |
| 011211 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:28pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596051.7 | 513311.5 | 78999 | 1.64041666667 | 11211 |
| 010602 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:29pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596053.2 | 513310.6 | 79001 | 1.64041666667 | 10602 |
| 011230 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:30pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596053.3 | 513309.5 | 79003 | 1.64041666667 | 11230 |
| 009887 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:31pm | Sensor | 1797-S0051=G-TJV.cor | 6845.0 | 1596054.2 | 513307.3 | 79005 | 1.64041666667 | 9887 |
| 009851 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:32pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596054.9 | 513305.4 | 79007 | 1.64041666667 | 9851 |
| 010473 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:33pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596054.7 | 513303.8 | 79009 | 1.64041666667 | 10473 |
| 010118 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:34pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596052.3 | 513302.7 | 79011 | 1.64041666667 | 10118 |
| 010599 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:35pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596049.3 | 513301.1 | 79013 | 1.64041666667 | 10599 |
| 011380 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:36pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596046.9 | 513300.1 | 79015 | 1.64041666667 | 11380 |
| 013255 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:37pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596044.2 | 513299.1 | 79017 | 1.64041666667 | 13255 |
| 011533 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:38pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596042.2 | 513298.2 | 79019 | 1.64041666667 | 11533 |
| 010683 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:39pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596039.4 | 513297.6 | 79021 | 1.64041666667 | 10683 |
| 011760 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:40pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596036.8 | 513296.9 | 79023 | 1.64041666667 | 11760 |
| 009840 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:41pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596033.6 | 513296.4 | 79025 | 1.64041666667 | 9840 |
| 013620 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:42pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596031.1 | 513296.0 | 79027 | 1.64041666667 | 13620 |
| 013635 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:43pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596028.4 | 513295.5 | 79029 | 1.64041666667 | 13635 |
| 016098 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:44pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596025.7 | 513295.4 | 79031 | 1.64041666667 | 16098 |
| 012934 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:45pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596023.4 | 513294.5 | 79033 | 1.64041666667 | 12934 |
| 012533 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:46pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596020.8 | 513293.3 | 79035 | 1.64041666667 | 12533 |
| 011293 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:47pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596018.4 | 513292.1 | 79037 | 1.64041666667 | 11293 |
| 010893 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:48pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596016.2 | 513290.7 | 79039 | 1.64041666667 | 10893 |
| 009803 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:49pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596013.8 | 513289.4 | 79041 | 1.64041666667 | 9803 |
| 010430 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596011.6 | 513287.8 | 79043 | 1.64041666667 | 10430 |
| 014457 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596009.1 | 513286.5 | 79045 | 1.64041666667 | 14457 |
| 013484 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1596006.6 | 513285.3 | 79047 | 1.64041666667 | 13484 |
| 014201 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596004.0 | 513284.2 | 79049 | 1.64041666667 | 14201 |
| 015580 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596001.6 | 513283.6 | 79051 | 1.64041666667 | 15580 |
| 015415 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595999.4 | 513282.6 | 79053 | 1.64041666667 | 15415 |
| 014983 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595997.1 | 513282.0 | 79055 | 1.64041666667 | 14983 |
| 014606 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595995.0 | 513281.2 | 79057 | 1.64041666667 | 14606 |
| 015411 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595992.8 | 513281.0 | 79059 | 1.64041666667 | 15411 |
| 011952 | 0 | GeoXH 6000 | 08/19/2015 | 05:03:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595990.2 | 513280.3 | 79061 | 1.64041666667 | 11952 |
| 011958 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595987.4 | 513278.9 | 79063 | 1.64041666667 | 11958 |
| 011629 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595984.7 | 513277.3 | 79065 | 1.64041666667 | 11629 |
| 011187 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595982.5 | 513275.9 | 79067 | 1.64041666667 | 11187 |
| 013177 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595979.7 | 513274.5 | 79069 | 1.64041666667 | 13177 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012624 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595977.3 | 513273.1 | 79071 | 1.64041666667 | 12624 |
| 010716 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595974.2 | 513271.7 | 79073 | 1.64041666667 | 10716 |
| 011379 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595971.7 | 513270.6 | 79075 | 1.64041666667 | 11379 |
| 010914 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595968.9 | 513269.5 | 79077 | 1.64041666667 | 10914 |
| 010528 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595966.4 | 513268.9 | 79079 | 1.64041666667 | 10528 |
| 010102 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595963.2 | 513267.9 | 79081 | 1.64041666667 | 10102 |
| 010295 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595960.6 | 513267.5 | 79083 | 1.64041666667 | 10295 |
| 012773 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595957.2 | 513267.1 | 79085 | 1.64041666667 | 12773 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595954.7 | 513266.1 | 79087 | 1.64041666667 | 12163 |
| 012101 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595952.0 | 513265.4 | 79089 | 1.64041666667 | 12101 |
| 012595 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595949.3 | 513264.1 | 79091 | 1.64041666667 | 12595 |
| 010918 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:15pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595946.5 | 513262.5 | 79093 | 1.64041666667 | 10918 |
| 010139 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595944.2 | 513260.8 | 79095 | 1.64041666667 | 10139 |
| 011385 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:17pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595942.1 | 513258.9 | 79097 | 1.64041666667 | 11385 |
| 011096 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:18pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595940.0 | 513257.6 | 79099 | 1.64041666667 | 11096 |
| 009134 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:19pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595937.6 | 513255.8 | 79101 | 1.64041666667 | 9134 |
| 010563 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:20pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595935.7 | 513254.4 | 79103 | 1.64041666667 | 10563 |
| 011310 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:21pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595933.4 | 513253.3 | 79105 | 1.64041666667 | 11310 |
| 012307 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:22pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595932.5 | 513252.6 | 79107 | 1.64041666667 | 12307 |
| 010637 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:23pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595932.9 | 513252.9 | 79109 | 1.64041666667 | 10637 |
| 011629 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:24pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595932.6 | 513254.4 | 79111 | 1.64041666667 | 11629 |
| 011427 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:25pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595931.6 | 513257.4 | 79113 | 1.64041666667 | 11427 |
| 011137 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:26pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595931.5 | 513259.2 | 79115 | 1.64041666667 | 11137 |
| 012564 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:27pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595930.9 | 513260.5 | 79117 | 1.64041666667 | 12564 |
| 012801 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:28pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595930.0 | 513262.7 | 79119 | 1.64041666667 | 12801 |
| 012470 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:29pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595929.4 | 513265.3 | 79121 | 1.64041666667 | 12470 |
| 011277 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:30pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595929.1 | 513266.9 | 79123 | 1.64041666667 | 11277 |
| 011909 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:31pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595929.1 | 513267.1 | 79125 | 1.64041666667 | 11909 |
| 010897 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:32pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595928.9 | 513266.1 | 79127 | 1.64041666667 | 10897 |
| 011094 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:33pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595928.1 | 513264.0 | 79129 | 1.64041666667 | 11094 |
| 010633 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:34pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595928.4 | 513262.7 | 79131 | 1.64041666667 | 10633 |
| 012198 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:35pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595929.5 | 513261.5 | 79133 | 1.64041666667 | 12198 |
| 011719 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:36pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595930.0 | 513260.3 | 79135 | 1.64041666667 | 11719 |
| 010339 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:37pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595930.5 | 513259.4 | 79137 | 1.64041666667 | 10339 |
| 011045 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:38pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595930.1 | 513259.0 | 79139 | 1.64041666667 | 11045 |
| 011491 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:39pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595930.0 | 513258.9 | 79141 | 1.64041666667 | 11491 |
| 012112 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:40pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595929.9 | 513258.9 | 79143 | 1.64041666667 | 12112 |
| 010528 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:41pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595930.4 | 513259.1 | 79145 | 1.64041666667 | 10528 |
| 010582 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:42pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595932.0 | 513259.6 | 79147 | 1.64041666667 | 10582 |
| 010925 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:43pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595934.2 | 513260.4 | 79149 | 1.64041666667 | 10925 |
| 009841 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:44pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595936.2 | 513261.0 | 79151 | 1.64041666667 | 9841 |
| 011430 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:45pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595938.5 | 513262.4 | 79153 | 1.64041666667 | 11430 |
| 012367 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:46pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595940.9 | 513263.6 | 79155 | 1.64041666667 | 12367 |
| 011222 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:47pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595944.0 | 513265.0 | 79157 | 1.64041666667 | 11222 |
| 010965 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595946.5 | 513266.3 | 79159 | 1.64041666667 | 10965 |
| 010001 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595948.9 | 513267.5 | 79161 | 1.64041666667 | 10001 |
| 012340 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:50pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595951.0 | 513268.8 | 79163 | 1.64041666667 | 12340 |
| 011875 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:51pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595954.0 | 513270.1 | 79165 | 1.64041666667 | 11875 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011428 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595956.5 | 513271.4 | 79167 | 1.64041666667 | 11428 |
| 011437 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:53pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595959.2 | 513272.9 | 79169 | 1.64041666667 | 11437 |
| 012339 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:54pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595961.5 | 513273.9 | 79171 | 1.64041666667 | 12339 |
| 010704 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:55pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595964.5 | 513275.9 | 79173 | 1.64041666667 | 10704 |
| 011556 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595967.0 | 513277.1 | 79175 | 1.64041666667 | 11556 |
| 011499 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595969.9 | 513278.7 | 79177 | 1.64041666667 | 11499 |
| 011454 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595972.4 | 513280.2 | 79179 | 1.64041666667 | 11454 |
| 011563 | 0 | GeoXH 6000 | 08/19/2015 | 05:04:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595975.3 | 513281.4 | 79181 | 1.64041666667 | 11563 |
| 011591 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595977.8 | 513283.2 | 79183 | 1.64041666667 | 11591 |
| 011537 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595980.9 | 513285.2 | 79185 | 1.64041666667 | 11537 |
| 011708 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595983.1 | 513286.5 | 79187 | 1.64041666667 | 11708 |
| 012698 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595985.7 | 513288.5 | 79189 | 1.64041666667 | 12698 |
| 011514 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595988.3 | 513290.1 | 79191 | 1.64041666667 | 11514 |
| 011878 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595990.5 | 513291.6 | 79193 | 1.64041666667 | 11878 |
| 012449 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595992.8 | 513292.9 | 79195 | 1.64041666667 | 12449 |
| 011632 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595995.7 | 513293.6 | 79197 | 1.64041666667 | 11632 |
| 010858 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595998.2 | 513294.7 | 79199 | 1.64041666667 | 10858 |
| 012014 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1596001.1 | 513295.2 | 79201 | 1.64041666667 | 12014 |
| 011343 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1596004.1 | 513295.7 | 79203 | 1.64041666667 | 11343 |
| 010785 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:11pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596006.5 | 513296.7 | 79205 | 1.64041666667 | 10785 |
| 012416 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:12pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596009.4 | 513297.7 | 79207 | 1.64041666667 | 12416 |
| 010574 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:13pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596012.3 | 513298.7 | 79209 | 1.64041666667 | 10574 |
| 012573 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:14pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596015.3 | 513299.7 | 79211 | 1.64041666667 | 12573 |
| 012053 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:15pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596018.2 | 513300.8 | 79213 | 1.64041666667 | 12053 |
| 012493 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:16pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596020.9 | 513302.2 | 79215 | 1.64041666667 | 12493 |
| 010893 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596024.5 | 513303.4 | 79217 | 1.64041666667 | 10893 |
| 011423 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:18pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596027.3 | 513304.5 | 79219 | 1.64041666667 | 11423 |
| 011315 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:19pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596030.0 | 513305.6 | 79221 | 1.64041666667 | 11315 |
| 010929 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596032.4 | 513306.3 | 79223 | 1.64041666667 | 10929 |
| 011042 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:21pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596035.5 | 513307.2 | 79225 | 1.64041666667 | 11042 |
| 010470 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:22pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596038.4 | 513307.7 | 79227 | 1.64041666667 | 10470 |
| 009967 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:23pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596041.3 | 513308.3 | 79229 | 1.64041666667 | 9967 |
| 009842 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:24pm | Sensor | 1797-S0051=G-TJV.cor | 6845.0 | 1596043.4 | 513309.1 | 79231 | 1.64041666667 | 9842 |
| 009870 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:25pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596045.8 | 513310.0 | 79233 | 1.64041666667 | 9870 |
| 011227 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:26pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596047.9 | 513311.2 | 79235 | 1.64041666667 | 11227 |
| 009917 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:27pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596049.9 | 513311.8 | 79237 | 1.64041666667 | 9917 |
| 011599 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:28pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596051.6 | 513312.2 | 79239 | 1.64041666667 | 11599 |
| 010759 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:29pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596051.1 | 513312.0 | 79241 | 1.64041666667 | 10759 |
| 011180 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:30pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596050.2 | 513312.8 | 79243 | 1.64041666667 | 11180 |
| 009905 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:31pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596048.9 | 513315.7 | 79245 | 1.64041666667 | 9905 |
| 011536 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:32pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596047.8 | 513317.3 | 79247 | 1.64041666667 | 11536 |
| 010984 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:33pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596048.3 | 513318.0 | 79249 | 1.64041666667 | 10984 |
| 011626 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:34pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596048.3 | 513318.1 | 79251 | 1.64041666667 | 11626 |
| 009536 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:35pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596048.3 | 513318.0 | 79253 | 1.64041666667 | 9536 |
| 011474 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:36pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596048.3 | 513318.1 | 79255 | 1.64041666667 | 11474 |
| 011058 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:37pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596048.0 | 513319.0 | 79257 | 1.64041666667 | 11058 |
| 009694 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:38pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596047.1 | 513321.3 | 79259 | 1.64041666667 | 9694 |
| 010763 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:39pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596046.5 | 513323.9 | 79261 | 1.64041666667 | 10763 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013011 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:40pm | Sensor | 1797-S0051=G-TJV.cor | 6845.0 | 1596045.8 | 513325.7 | 79263 | 1.64041666667 | 13011 |
| 010122 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:41pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596045.3 | 513326.6 | 79265 | 1.64041666667 | 10122 |
| 010360 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:42pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596045.1 | 513326.9 | 79267 | 1.64041666667 | 10360 |
| 010750 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:43pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596045.4 | 513326.6 | 79269 | 1.64041666667 | 10750 |
| 009437 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:44pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596046.5 | 513325.7 | 79271 | 1.64041666667 | 9437 |
| 011449 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:45pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596047.4 | 513324.5 | 79273 | 1.64041666667 | 11449 |
| 010122 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:46pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596047.0 | 513322.6 | 79275 | 1.64041666667 | 10122 |
| 010720 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:47pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596047.3 | 513320.2 | 79277 | 1.64041666667 | 10720 |
| 012370 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:48pm | Sensor | 1797-S0051=G-TJV.cor | 6845.0 | 1596046.7 | 513318.3 | 79279 | 1.64041666667 | 12370 |
| 010892 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:49pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596045.0 | 513316.6 | 79281 | 1.64041666667 | 10892 |
| 010703 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:50pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596043.0 | 513314.9 | 79283 | 1.64041666667 | 10703 |
| 010715 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:51pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596040.5 | 513313.1 | 79285 | 1.64041666667 | 10715 |
| 010689 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:52pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596038.1 | 513311.6 | 79287 | 1.64041666667 | 10689 |
| 010502 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:53pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596035.2 | 513310.6 | 79289 | 1.64041666667 | 10502 |
| 010665 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:54pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596032.5 | 513309.7 | 79291 | 1.64041666667 | 10665 |
| 009206 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:55pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596029.3 | 513308.5 | 79293 | 1.64041666667 | 9206 |
| 011451 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:56pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596026.8 | 513307.5 | 79295 | 1.64041666667 | 11451 |
| 011443 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:57pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596024.2 | 513306.0 | 79297 | 1.64041666667 | 11443 |
| 009940 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:58pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596021.8 | 513305.3 | 79299 | 1.64041666667 | 9940 |
| 012955 | 0 | GeoXH 6000 | 08/19/2015 | 05:05:59pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596018.9 | 513304.2 | 79301 | 1.64041666667 | 12955 |
| 011458 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:00pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596016.5 | 513303.4 | 79303 | 1.64041666667 | 11458 |
| 011414 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:01pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596014.6 | 513303.2 | 79305 | 1.64041666667 | 11414 |
| 009453 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:02pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596014.3 | 513302.8 | 79307 | 1.64041666667 | 9453 |
| 009443 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:03pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596013.0 | 513302.5 | 79309 | 1.64041666667 | 9443 |
| 011270 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:04pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596011.2 | 513301.8 | 79311 | 1.64041666667 | 11270 |
| 010257 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:05pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1596007.9 | 513300.7 | 79313 | 1.64041666667 | 10257 |
| 010334 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:06pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1596005.2 | 513299.3 | 79315 | 1.64041666667 | 10334 |
| 010773 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:07pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1596002.2 | 513298.3 | 79317 | 1.64041666667 | 10773 |
| 011513 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595999.2 | 513297.4 | 79319 | 1.64041666667 | 11513 |
| 012658 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595996.6 | 513296.3 | 79321 | 1.64041666667 | 12658 |
| 011864 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595993.9 | 513295.6 | 79323 | 1.64041666667 | 11864 |
| 012416 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595990.8 | 513294.0 | 79325 | 1.64041666667 | 12416 |
| 012404 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595987.7 | 513292.7 | 79327 | 1.64041666667 | 12404 |
| 011801 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595984.6 | 513292.0 | 79329 | 1.64041666667 | 11801 |
| 012190 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595982.0 | 513290.8 | 79331 | 1.64041666667 | 12190 |
| 011717 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595978.5 | 513289.3 | 79333 | 1.64041666667 | 11717 |
| 011389 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595975.8 | 513287.8 | 79335 | 1.64041666667 | 11389 |
| 012177 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595973.1 | 513286.5 | 79337 | 1.64041666667 | 12177 |
| 010574 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595970.8 | 513285.8 | 79339 | 1.64041666667 | 10574 |
| 013953 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595967.9 | 513284.1 | 79341 | 1.64041666667 | 13953 |
| 012728 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:20pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595965.3 | 513282.9 | 79343 | 1.64041666667 | 12728 |
| 011402 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:21pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595962.1 | 513281.5 | 79345 | 1.64041666667 | 11402 |
| 011940 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595959.9 | 513280.2 | 79347 | 1.64041666667 | 11940 |
| 011805 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595956.9 | 513279.3 | 79349 | 1.64041666667 | 11805 |
| 012281 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595954.2 | 513277.7 | 79351 | 1.64041666667 | 12281 |
| 012460 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:25pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595951.5 | 513276.3 | 79353 | 1.64041666667 | 12460 |
| 011215 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595949.1 | 513275.2 | 79355 | 1.64041666667 | 11215 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595946.5 | 513273.8 | 79357 | 1.64041666667 | 12133 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012003 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595944.0 | 513273.0 | 79359 | 1.64041666667 | 12003 |
| 011490 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:29pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595941.2 | 513271.5 | 79361 | 1.64041666667 | 11490 |
| 011902 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:30pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595938.3 | 513270.3 | 79363 | 1.64041666667 | 11902 |
| 010655 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:31pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595935.5 | 513269.2 | 79365 | 1.64041666667 | 10655 |
| 012474 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:32pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595933.8 | 513267.9 | 79367 | 1.64041666667 | 12474 |
| 011638 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:33pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595931.4 | 513267.2 | 79369 | 1.64041666667 | 11638 |
| 011639 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:34pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595929.9 | 513266.6 | 79371 | 1.64041666667 | 11639 |
| 010920 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:35pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595929.3 | 513266.5 | 79373 | 1.64041666667 | 10920 |
| 011400 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:36pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595930.0 | 513266.4 | 79375 | 1.64041666667 | 11400 |
| 010500 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:37pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595929.7 | 513269.0 | 79377 | 1.64041666667 | 10500 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:38pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595929.1 | 513271.5 | 79379 | 1.64041666667 | 12405 |
| 009881 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:39pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595928.8 | 513274.2 | 79381 | 1.64041666667 | 9881 |
| 011800 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:40pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595928.6 | 513275.8 | 79383 | 1.64041666667 | 11800 |
| 011320 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:41pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595927.8 | 513277.4 | 79385 | 1.64041666667 | 11320 |
| 012400 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:42pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595927.3 | 513279.8 | 79387 | 1.64041666667 | 12400 |
| 013780 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:43pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595926.1 | 513282.7 | 79389 | 1.64041666667 | 13780 |
| 013345 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:44pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1595925.6 | 513284.0 | 79391 | 1.64041666667 | 13345 |
| 012516 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:45pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595926.2 | 513283.0 | 79393 | 1.64041666667 | 12516 |
| 011949 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:46pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595926.6 | 513281.4 | 79395 | 1.64041666667 | 11949 |
| 010787 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:47pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595926.3 | 513279.3 | 79397 | 1.64041666667 | 10787 |
| 011876 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:48pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595927.1 | 513278.1 | 79399 | 1.64041666667 | 11876 |
| 011639 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:49pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595928.3 | 513276.5 | 79401 | 1.64041666667 | 11639 |
| 012270 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:50pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595930.3 | 513275.7 | 79403 | 1.64041666667 | 12270 |
| 011587 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:51pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595933.0 | 513275.9 | 79405 | 1.64041666667 | 11587 |
| 011566 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:52pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595935.4 | 513276.3 | 79407 | 1.64041666667 | 11566 |
| 010931 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:53pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595937.7 | 513277.9 | 79409 | 1.64041666667 | 10931 |
| 010593 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:54pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595940.1 | 513279.1 | 79411 | 1.64041666667 | 10593 |
| 012578 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:55pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595942.7 | 513280.6 | 79413 | 1.64041666667 | 12578 |
| 011004 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:56pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595945.3 | 513281.6 | 79415 | 1.64041666667 | 11004 |
| 011061 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:57pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595948.4 | 513282.5 | 79417 | 1.64041666667 | 11061 |
| 011165 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:58pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595950.7 | 513283.5 | 79419 | 1.64041666667 | 11165 |
| 011821 | 0 | GeoXH 6000 | 08/19/2015 | 05:06:59pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595953.5 | 513284.2 | 79421 | 1.64041666667 | 11821 |
| 011535 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:00pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595955.7 | 513285.0 | 79423 | 1.64041666667 | 11535 |
| 011883 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595958.7 | 513285.8 | 79425 | 1.64041666667 | 11883 |
| 011851 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595961.4 | 513286.5 | 79427 | 1.64041666667 | 11851 |
| 010882 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595964.1 | 513287.2 | 79429 | 1.64041666667 | 10882 |
| 011360 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595966.3 | 513287.8 | 79431 | 1.64041666667 | 11360 |
| 011870 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595968.9 | 513289.0 | 79433 | 1.64041666667 | 11870 |
| 012387 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595971.2 | 513290.0 | 79435 | 1.64041666667 | 12387 |
| 011617 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595973.3 | 513291.7 | 79437 | 1.64041666667 | 11617 |
| 011904 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595975.4 | 513293.0 | 79439 | 1.64041666667 | 11904 |
| 011946 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595978.5 | 513294.6 | 79441 | 1.64041666667 | 11946 |
| 011206 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595980.6 | 513295.5 | 79443 | 1.64041666667 | 11206 |
| 010631 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:11pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595983.5 | 513296.6 | 79445 | 1.64041666667 | 10631 |
| 010248 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:12pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595985.7 | 513297.8 | 79447 | 1.64041666667 | 10248 |
| 010092 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595988.6 | 513299.0 | 79449 | 1.64041666667 | 10092 |
| 011346 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595990.9 | 513300.1 | 79451 | 1.64041666667 | 11346 |
| 010478 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:15pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595993.8 | 513301.2 | 79453 | 1.64041666667 | 10478 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010149 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:16pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1595996.0 | 513302.0 | 79455 | 1.64041666667 | 10149 |
| 011267 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1595998.6 | 513303.3 | 79457 | 1.64041666667 | 11267 |
| 010106 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:18pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596001.1 | 513304.5 | 79459 | 1.64041666667 | 10106 |
| 010536 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:19pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596003.8 | 513306.7 | 79461 | 1.64041666667 | 10536 |
| 010674 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596006.2 | 513308.3 | 79463 | 1.64041666667 | 10674 |
| 011938 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:21pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596009.1 | 513309.6 | 79465 | 1.64041666667 | 11938 |
| 011204 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:22pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596011.4 | 513310.7 | 79467 | 1.64041666667 | 11204 |
| 012671 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:23pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596014.5 | 513311.7 | 79469 | 1.64041666667 | 12671 |
| 011897 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:24pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596017.1 | 513313.0 | 79471 | 1.64041666667 | 11897 |
| 011254 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:25pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596019.8 | 513314.4 | 79473 | 1.64041666667 | 11254 |
| 011123 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:26pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596022.3 | 513315.5 | 79475 | 1.64041666667 | 11123 |
| 010911 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:27pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596024.9 | 513316.9 | 79477 | 1.64041666667 | 10911 |
| 011997 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:28pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596027.4 | 513317.6 | 79479 | 1.64041666667 | 11997 |
| 011429 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:29pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596030.3 | 513318.7 | 79481 | 1.64041666667 | 11429 |
| 011677 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:30pm | Sensor | 1797-S0051=G-TJV.cor | 6845.0 | 1596032.7 | 513319.8 | 79483 | 1.64041666667 | 11677 |
| 011859 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:31pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596035.3 | 513321.1 | 79485 | 1.64041666667 | 11859 |
| 011574 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:32pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596037.2 | 513322.5 | 79487 | 1.64041666667 | 11574 |
| 010573 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:33pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596039.6 | 513323.7 | 79489 | 1.64041666667 | 10573 |
| 010983 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:34pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596041.5 | 513325.1 | 79491 | 1.64041666667 | 10983 |
| 010635 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:35pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596043.7 | 513326.1 | 79493 | 1.64041666667 | 10635 |
| 011028 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:36pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596045.5 | 513326.6 | 79495 | 1.64041666667 | 11028 |
| 011547 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:37pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596046.0 | 513327.1 | 79497 | 1.64041666667 | 11547 |
| 009637 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:38pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596044.9 | 513328.0 | 79499 | 1.64041666667 | 9637 |
| 008859 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:39pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596043.9 | 513330.8 | 79501 | 1.64041666667 | 8859 |
| 010764 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:40pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596043.3 | 513332.0 | 79503 | 1.64041666667 | 10764 |
| 011331 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:41pm | Sensor | 1797-S0051=G-TJV.cor | 6845.5 | 1596043.1 | 513332.6 | 79505 | 1.64041666667 | 11331 |
| 011862 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:42pm | Sensor | 1797-S0051=G-TJV.cor | 6845.5 | 1596042.3 | 513333.5 | 79507 | 1.64041666667 | 11862 |
| 010345 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:43pm | Sensor | 1797-S0051=G-TJV.cor | 6845.5 | 1596040.8 | 513336.5 | 79509 | 1.64041666667 | 10345 |
| 011466 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:44pm | Sensor | 1797-S0051=G-TJV.cor | 6845.4 | 1596039.5 | 513338.8 | 79511 | 1.64041666667 | 11466 |
| 011116 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:45pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596039.0 | 513341.5 | 79513 | 1.64041666667 | 11116 |
| 010039 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:46pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596038.9 | 513341.6 | 79515 | 1.64041666667 | 10039 |
| 010819 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:47pm | Sensor | 1797-S0051=G-TJV.cor | 6845.6 | 1596040.0 | 513340.8 | 79517 | 1.64041666667 | 10819 |
| 011495 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:48pm | Sensor | 1797-S0051=G-TJV.cor | 6845.6 | 1596040.8 | 513339.9 | 79519 | 1.64041666667 | 11495 |
| 010643 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:49pm | Sensor | 1797-S0051=G-TJV.cor | 6845.6 | 1596040.5 | 513337.9 | 79521 | 1.64041666667 | 10643 |
| 010761 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:50pm | Sensor | 1797-S0051=G-TJV.cor | 6845.5 | 1596041.4 | 513335.8 | 79523 | 1.64041666667 | 10761 |
| 010910 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:51pm | Sensor | 1797-S0051=G-TJV.cor | 6845.4 | 1596041.2 | 513333.0 | 79525 | 1.64041666667 | 10910 |
| 010827 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:52pm | Sensor | 1797-S0051=G-TJV.cor | 6845.4 | 1596039.7 | 513331.2 | 79527 | 1.64041666667 | 10827 |
| 010597 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:53pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596037.2 | 513329.1 | 79529 | 1.64041666667 | 10597 |
| 010629 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:54pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596034.8 | 513327.9 | 79531 | 1.64041666667 | 10629 |
| 010637 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:55pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596032.0 | 513326.5 | 79533 | 1.64041666667 | 10637 |
| 011989 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:56pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596029.4 | 513325.4 | 79535 | 1.64041666667 | 11989 |
| 011037 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:57pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596026.5 | 513324.3 | 79537 | 1.64041666667 | 11037 |
| 013109 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:58pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596024.2 | 513323.2 | 79539 | 1.64041666667 | 13109 |
| 011257 | 0 | GeoXH 6000 | 08/19/2015 | 05:07:59pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596021.2 | 513322.1 | 79541 | 1.64041666667 | 11257 |
| 012504 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:00pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596018.7 | 513320.6 | 79543 | 1.64041666667 | 12504 |
| 010806 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:01pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596015.8 | 513318.8 | 79545 | 1.64041666667 | 10806 |
| 011491 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:02pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596013.5 | 513317.9 | 79547 | 1.64041666667 | 11491 |
| 011572 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:03pm | Sensor | 1797-S0051=G-TJV.cor | 6844.6 | 1596011.0 | 513316.5 | 79549 | 1.64041666667 | 11572 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013123 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:04pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596008.5 | 513315.7 | 79551 | 1.64041666667 | 13123 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:05pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596005.5 | 513314.3 | 79553 | 1.64041666667 | 12461 |
| 012385 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:06pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596002.7 | 513313.3 | 79555 | 1.64041666667 | 12385 |
| 010686 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:07pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1595999.7 | 513312.5 | 79557 | 1.64041666667 | 10686 |
| 011791 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:08pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1595997.2 | 513311.1 | 79559 | 1.64041666667 | 11791 |
| 011827 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:09pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1595994.1 | 513309.9 | 79561 | 1.64041666667 | 11827 |
| 011507 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595991.2 | 513308.7 | 79563 | 1.64041666667 | 11507 |
| 009926 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:11pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595988.4 | 513307.5 | 79565 | 1.64041666667 | 9926 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:12pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1595985.6 | 513306.6 | 79567 | 1.64041666667 | 11241 |
| 010340 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:13pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595983.0 | 513305.3 | 79569 | 1.64041666667 | 10340 |
| 011765 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:14pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595980.2 | 513304.8 | 79571 | 1.64041666667 | 11765 |
| 011731 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595976.9 | 513304.1 | 79573 | 1.64041666667 | 11731 |
| 011032 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595974.2 | 513303.3 | 79575 | 1.64041666667 | 11032 |
| 011908 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595971.3 | 513302.6 | 79577 | 1.64041666667 | 11908 |
| 011707 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595969.0 | 513301.6 | 79579 | 1.64041666667 | 11707 |
| 010756 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595965.8 | 513300.5 | 79581 | 1.64041666667 | 10756 |
| 011329 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:20pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595963.4 | 513299.4 | 79583 | 1.64041666667 | 11329 |
| 009972 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:21pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595960.5 | 513297.8 | 79585 | 1.64041666667 | 9972 |
| 010833 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595958.2 | 513296.9 | 79587 | 1.64041666667 | 10833 |
| 011318 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595955.1 | 513295.1 | 79589 | 1.64041666667 | 11318 |
| 011739 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595952.4 | 513293.8 | 79591 | 1.64041666667 | 11739 |
| 011515 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595949.9 | 513292.9 | 79593 | 1.64041666667 | 11515 |
| 013468 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:26pm | Sensor | 1797-S0051=G-TJV.cor | 6843.1 | 1595947.4 | 513291.7 | 79595 | 1.64041666667 | 13468 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:27pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595944.6 | 513291.2 | 79597 | 1.64041666667 | 13297 |
| 012204 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:28pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595942.3 | 513290.4 | 79599 | 1.64041666667 | 12204 |
| 012141 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:29pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595939.6 | 513289.6 | 79601 | 1.64041666667 | 12141 |
| 011825 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:30pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595936.6 | 513288.5 | 79603 | 1.64041666667 | 11825 |
| 011236 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:31pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595934.1 | 513287.2 | 79605 | 1.64041666667 | 11236 |
| 011719 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:32pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595931.6 | 513286.7 | 79607 | 1.64041666667 | 11719 |
| 011269 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:33pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595929.4 | 513285.5 | 79609 | 1.64041666667 | 11269 |
| 012327 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:34pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595928.1 | 513284.7 | 79611 | 1.64041666667 | 12327 |
| 011932 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:35pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595927.8 | 513284.5 | 79613 | 1.64041666667 | 11932 |
| 012103 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:36pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595927.2 | 513284.4 | 79615 | 1.64041666667 | 12103 |
| 011575 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:37pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595926.2 | 513284.4 | 79617 | 1.64041666667 | 11575 |
| 011594 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:38pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595926.0 | 513284.3 | 79619 | 1.64041666667 | 11594 |
| 012108 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:39pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595925.1 | 513284.3 | 79621 | 1.64041666667 | 12108 |
| 012867 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:40pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595923.3 | 513284.9 | 79623 | 1.64041666667 | 12867 |
| 011106 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:41pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595921.4 | 513286.2 | 79625 | 1.64041666667 | 11106 |
| 011626 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:42pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595919.9 | 513287.9 | 79627 | 1.64041666667 | 11626 |
| 011756 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:43pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595918.8 | 513289.3 | 79629 | 1.64041666667 | 11756 |
| 012029 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:44pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595918.9 | 513290.3 | 79631 | 1.64041666667 | 12029 |
| 013417 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:45pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595918.6 | 513291.1 | 79633 | 1.64041666667 | 13417 |
| 011694 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:46pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595918.9 | 513293.2 | 79635 | 1.64041666667 | 11694 |
| 011173 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:47pm | Sensor | 1797-S0051=G-TJV.cor | 6842.3 | 1595918.4 | 513296.4 | 79637 | 1.64041666667 | 11173 |
| 011373 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:48pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595918.0 | 513298.8 | 79639 | 1.64041666667 | 11373 |
| 011873 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:49pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595918.5 | 513298.2 | 79641 | 1.64041666667 | 11873 |
| 010438 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:50pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595918.9 | 513296.5 | 79643 | 1.64041666667 | 10438 |
| 011489 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:51pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595918.1 | 513294.9 | 79645 | 1.64041666667 | 11489 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011092 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:52pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595919.1 | 513293.1 | 79647 | 1.64041666667 | 11092 |
| 009763 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:53pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595921.1 | 513292.9 | 79649 | 1.64041666667 | 9763 |
| 010210 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:54pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595923.6 | 513293.5 | 79651 | 1.64041666667 | 10210 |
| 010472 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:55pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595926.3 | 513294.4 | 79653 | 1.64041666667 | 10472 |
| 011378 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:56pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595929.1 | 513294.8 | 79655 | 1.64041666667 | 11378 |
| 011964 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:57pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595932.5 | 513295.4 | 79657 | 1.64041666667 | 11964 |
| 012051 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:58pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595935.2 | 513296.5 | 79659 | 1.64041666667 | 12051 |
| 010572 | 0 | GeoXH 6000 | 08/19/2015 | 05:08:59pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595938.1 | 513297.5 | 79661 | 1.64041666667 | 10572 |
| 011253 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:00pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595940.8 | 513298.8 | 79663 | 1.64041666667 | 11253 |
| 011873 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:01pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595943.2 | 513299.8 | 79665 | 1.64041666667 | 11873 |
| 012388 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:02pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595945.3 | 513300.5 | 79667 | 1.64041666667 | 12388 |
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:03pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595947.4 | 513301.6 | 79669 | 1.64041666667 | 12937 |
| 013584 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:04pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595949.8 | 513302.3 | 79671 | 1.64041666667 | 13584 |
| 011196 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:05pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595952.7 | 513303.3 | 79673 | 1.64041666667 | 11196 |
| 010839 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595955.1 | 513304.2 | 79675 | 1.64041666667 | 10839 |
| 010299 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595958.0 | 513305.3 | 79677 | 1.64041666667 | 10299 |
| 010645 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:08pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595960.3 | 513306.4 | 79679 | 1.64041666667 | 10645 |
| 010941 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595963.3 | 513307.1 | 79681 | 1.64041666667 | 10941 |
| 010985 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595965.5 | 513308.1 | 79683 | 1.64041666667 | 10985 |
| 010186 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595968.7 | 513309.4 | 79685 | 1.64041666667 | 10186 |
| 009386 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595971.1 | 513310.3 | 79687 | 1.64041666667 | 9386 |
| 010326 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:13pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595973.7 | 513311.5 | 79689 | 1.64041666667 | 10326 |
| 009691 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:14pm | Sensor | 1797-S0051=G-TJV.cor | 6844.1 | 1595976.0 | 513312.4 | 79691 | 1.64041666667 | 9691 |
| 011362 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595978.5 | 513313.8 | 79693 | 1.64041666667 | 11362 |
| 010220 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595981.4 | 513315.0 | 79695 | 1.64041666667 | 10220 |
| 010745 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:17pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1595984.1 | 513316.0 | 79697 | 1.64041666667 | 10745 |
| 010726 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:18pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1595986.6 | 513317.1 | 79699 | 1.64041666667 | 10726 |
| 011051 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:19pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1595989.1 | 513317.8 | 79701 | 1.64041666667 | 11051 |
| 011043 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:20pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1595991.9 | 513319.1 | 79703 | 1.64041666667 | 11043 |
| 011580 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:21pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1595994.8 | 513320.0 | 79705 | 1.64041666667 | 11580 |
| 010725 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:22pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1595997.6 | 513320.4 | 79707 | 1.64041666667 | 10725 |
| 011231 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:23pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596000.0 | 513321.4 | 79709 | 1.64041666667 | 11231 |
| 010608 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:24pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596002.9 | 513322.0 | 79711 | 1.64041666667 | 10608 |
| 012042 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:25pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596005.4 | 513323.2 | 79713 | 1.64041666667 | 12042 |
| 014980 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:26pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596007.7 | 513324.5 | 79715 | 1.64041666667 | 14980 |
| 014635 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:27pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596010.2 | 513325.7 | 79717 | 1.64041666667 | 14635 |
| 014158 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:28pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596012.1 | 513327.0 | 79719 | 1.64041666667 | 14158 |
| 014549 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:29pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596014.8 | 513328.1 | 79721 | 1.64041666667 | 14549 |
| 012577 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:30pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596017.1 | 513329.2 | 79723 | 1.64041666667 | 12577 |
| 014634 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:31pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596020.1 | 513330.3 | 79725 | 1.64041666667 | 14634 |
| 011578 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:32pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596022.5 | 513331.4 | 79727 | 1.64041666667 | 11578 |
| 012224 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:33pm | Sensor | 1797-S0051=G-TJV.cor | 6845.0 | 1596024.6 | 513333.3 | 79729 | 1.64041666667 | 12224 |
| 011606 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:34pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596026.7 | 513334.3 | 79731 | 1.64041666667 | 11606 |
| 010041 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:35pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596029.3 | 513336.0 | 79733 | 1.64041666667 | 10041 |
| 011030 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:36pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596031.6 | 513337.4 | 79735 | 1.64041666667 | 11030 |
| 011547 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:37pm | Sensor | 1797-S0051=G-TJV.cor | 6845.4 | 1596033.9 | 513338.8 | 79737 | 1.64041666667 | 11547 |
| 011677 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:38pm | Sensor | 1797-S0051=G-TJV.cor | 6845.6 | 1596035.8 | 513340.1 | 79739 | 1.64041666667 | 11677 |
| 010959 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:39pm | Sensor | 1797-S0051=G-TJV.cor | 6845.5 | 1596038.0 | 513340.9 | 79741 | 1.64041666667 | 10959 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010449 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:40pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596039.5 | 513341.9 | 79743 | 1.64041666667 | 10449 |
| 010772 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:41pm | Sensor | 1797-S0051=G-TJV.cor | 6845.6 | 1596038.8 | 513342.1 | 79745 | 1.64041666667 | 10772 |
| 009773 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:42pm | Sensor | 1797-S0051=G-TJV.cor | 6845.5 | 1596037.4 | 513344.0 | 79747 | 1.64041666667 | 9773 |
| 010843 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:43pm | Sensor | 1797-S0051=G-TJV.cor | 6845.4 | 1596036.2 | 513346.1 | 79749 | 1.64041666667 | 10843 |
| 011081 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:44pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596034.2 | 513346.5 | 79751 | 1.64041666667 | 11081 |
| 010900 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:45pm | Sensor | 1797-S0051=G-TJV.cor | 6845.3 | 1596031.7 | 513346.4 | 79753 | 1.64041666667 | 10900 |
| 011905 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:46pm | Sensor | 1797-S0051=G-TJV.cor | 6845.2 | 1596029.0 | 513346.1 | 79755 | 1.64041666667 | 11905 |
| 011796 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:47pm | Sensor | 1797-S0051=G-TJV.cor | 6845.1 | 1596026.4 | 513345.1 | 79757 | 1.64041666667 | 11796 |
| 010599 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:48pm | Sensor | 1797-S0051=G-TJV.cor | 6845.0 | 1596023.9 | 513344.3 | 79759 | 1.64041666667 | 10599 |
| 011649 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:49pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596020.9 | 513342.8 | 79761 | 1.64041666667 | 11649 |
| 011582 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:50pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596018.6 | 513341.4 | 79763 | 1.64041666667 | 11582 |
| 011925 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:51pm | Sensor | 1797-S0051=G-TJV.cor | 6844.9 | 1596015.9 | 513340.1 | 79765 | 1.64041666667 | 11925 |
| 015431 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:52pm | Sensor | 1797-S0051=G-TJV.cor | 6844.8 | 1596013.8 | 513338.8 | 79767 | 1.64041666667 | 15431 |
| 018468 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:53pm | Sensor | 1797-S0051=G-TJV.cor | 6844.7 | 1596011.4 | 513338.0 | 79769 | 1.64041666667 | 18468 |
| 018147 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:54pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596009.2 | 513337.2 | 79771 | 1.64041666667 | 18147 |
| 012246 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:55pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1596006.9 | 513336.3 | 79773 | 1.64041666667 | 12246 |
| 011191 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:56pm | Sensor | 1797-S0051=G-TJV.cor | 6844.5 | 1596004.5 | 513335.5 | 79775 | 1.64041666667 | 11191 |
| 011047 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:57pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1596002.2 | 513334.0 | 79777 | 1.64041666667 | 11047 |
| 011432 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:58pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1595999.8 | 513333.0 | 79779 | 1.64041666667 | 11432 |
| 010418 | 0 | GeoXH 6000 | 08/19/2015 | 05:09:59pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1595997.5 | 513331.1 | 79781 | 1.64041666667 | 10418 |
| 011214 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:00pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595995.7 | 513329.9 | 79783 | 1.64041666667 | 11214 |
| 013093 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:01pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595993.0 | 513328.3 | 79785 | 1.64041666667 | 13093 |
| 011403 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:02pm | Sensor | 1797-S0051=G-TJV.cor | 6844.3 | 1595991.1 | 513326.8 | 79787 | 1.64041666667 | 11403 |
| 012360 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:03pm | Sensor | 1797-S0051=G-TJV.cor | 6844.4 | 1595989.0 | 513325.7 | 79789 | 1.64041666667 | 12360 |
| 011850 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:04pm | Sensor | 1797-S0051=G-TJV.cor | 6844.2 | 1595986.9 | 513324.3 | 79791 | 1.64041666667 | 11850 |
| 012322 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:05pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595983.8 | 513323.7 | 79793 | 1.64041666667 | 12322 |
| 012350 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:06pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595981.2 | 513323.1 | 79795 | 1.64041666667 | 12350 |
| 011427 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:07pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595978.6 | 513322.6 | 79797 | 1.64041666667 | 11427 |
| 010537 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:08pm | Sensor | 1797-S0051=G-TJV.cor | 6844.0 | 1595976.2 | 513322.2 | 79799 | 1.64041666667 | 10537 |
| 010854 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:09pm | Sensor | 1797-S0051=G-TJV.cor | 6843.9 | 1595973.7 | 513320.9 | 79801 | 1.64041666667 | 10854 |
| 009313 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:10pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595971.6 | 513320.0 | 79803 | 1.64041666667 | 9313 |
| 012288 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:11pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595969.0 | 513318.1 | 79805 | 1.64041666667 | 12288 |
| 011202 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:12pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595966.7 | 513316.5 | 79807 | 1.64041666667 | 11202 |
| 010060 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:13pm | Sensor | 1797-S0051=G-TJV.cor | 6843.8 | 1595964.2 | 513315.9 | 79809 | 1.64041666667 | 10060 |
| 009235 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:14pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595961.5 | 513315.2 | 79811 | 1.64041666667 | 9235 |
| 009658 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:15pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595958.9 | 513315.1 | 79813 | 1.64041666667 | 9658 |
| 010994 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:16pm | Sensor | 1797-S0051=G-TJV.cor | 6843.5 | 1595956.5 | 513314.5 | 79815 | 1.64041666667 | 10994 |
| 013068 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:17pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595953.7 | 513313.9 | 79817 | 1.64041666667 | 13068 |
| 011217 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:18pm | Sensor | 1797-S0051=G-TJV.cor | 6843.7 | 1595951.0 | 513313.3 | 79819 | 1.64041666667 | 11217 |
| 011594 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:19pm | Sensor | 1797-S0051=G-TJV.cor | 6843.6 | 1595948.9 | 513312.2 | 79821 | 1.64041666667 | 11594 |
| 012858 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:20pm | Sensor | 1797-S0051=G-TJV.cor | 6843.4 | 1595946.6 | 513311.2 | 79823 | 1.64041666667 | 12858 |
| 011074 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:21pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595944.0 | 513309.4 | 79825 | 1.64041666667 | 11074 |
| 011168 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:22pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595941.7 | 513308.1 | 79827 | 1.64041666667 | 11168 |
| 011402 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:23pm | Sensor | 1797-S0051=G-TJV.cor | 6843.3 | 1595938.9 | 513307.0 | 79829 | 1.64041666667 | 11402 |
| 012600 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:24pm | Sensor | 1797-S0051=G-TJV.cor | 6843.2 | 1595936.5 | 513305.7 | 79831 | 1.64041666667 | 12600 |
| 013200 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:25pm | Sensor | 1797-S0051=G-TJV.cor | 6843.0 | 1595933.4 | 513304.6 | 79833 | 1.64041666667 | 13200 |
| 011250 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:26pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595930.9 | 513303.3 | 79835 | 1.64041666667 | 11250 |
| 010222 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:27pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595928.2 | 513301.9 | 79837 | 1.64041666667 | 10222 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010325 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:28pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595925.9 | 513301.2 | 79839 | 1.64041666667 | 10325 |
| 010681 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:29pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595923.5 | 513299.8 | 79841 | 1.64041666667 | 10681 |
| 011610 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:30pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595921.5 | 513299.2 | 79843 | 1.64041666667 | 11610 |
| 012142 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:31pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595919.4 | 513299.1 | 79845 | 1.64041666667 | 12142 |
| 010535 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:32pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595918.5 | 513299.4 | 79847 | 1.64041666667 | 10535 |
| 010554 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:33pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595919.8 | 513299.3 | 79849 | 1.64041666667 | 10554 |
| 011038 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:34pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.4 | 513299.4 | 79851 | 1.64041666667 | 11038 |
| 011879 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:35pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513299.3 | 79853 | 1.64041666667 | 11879 |
| 011400 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:36pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513299.3 | 79855 | 1.64041666667 | 11400 |
| 011130 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:37pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.2 | 513299.3 | 79857 | 1.64041666667 | 11130 |
| 011152 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:38pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595919.7 | 513299.3 | 79859 | 1.64041666667 | 11152 |
| 012238 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:39pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595919.5 | 513299.2 | 79861 | 1.64041666667 | 12238 |
| 011399 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:40pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595919.8 | 513299.4 | 79863 | 1.64041666667 | 11399 |
| 011280 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:41pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.3 | 513299.4 | 79865 | 1.64041666667 | 11280 |
| 011100 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:42pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.3 | 513299.3 | 79867 | 1.64041666667 | 11100 |
| 009615 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:43pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.4 | 513299.4 | 79869 | 1.64041666667 | 9615 |
| 010203 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:44pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513299.3 | 79871 | 1.64041666667 | 10203 |
| 010920 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:45pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.3 | 513299.0 | 79873 | 1.64041666667 | 10920 |
| 011190 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:46pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.1 | 513298.3 | 79875 | 1.64041666667 | 11190 |
| 010867 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:47pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.1 | 513298.2 | 79877 | 1.64041666667 | 10867 |
| 011177 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:48pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.1 | 513298.2 | 79879 | 1.64041666667 | 11177 |
| 011074 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:49pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.1 | 513298.4 | 79881 | 1.64041666667 | 11074 |
| 009698 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:50pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.0 | 513298.5 | 79883 | 1.64041666667 | 9698 |
| 011694 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:51pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.1 | 513298.4 | 79885 | 1.64041666667 | 11694 |
| 011113 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:52pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.1 | 513298.3 | 79887 | 1.64041666667 | 11113 |
| 010338 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:53pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.1 | 513298.3 | 79889 | 1.64041666667 | 10338 |
| 014704 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:54pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.1 | 513298.3 | 79891 | 1.64041666667 | 14704 |
| 012136 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:55pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.1 | 513298.2 | 79893 | 1.64041666667 | 12136 |
| 011824 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:56pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.2 | 513298.3 | 79895 | 1.64041666667 | 11824 |
| 012286 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:57pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.3 | 513298.6 | 79897 | 1.64041666667 | 12286 |
| 010991 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:58pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.5 | 513298.5 | 79899 | 1.64041666667 | 10991 |
| 011988 | 0 | GeoXH 6000 | 08/19/2015 | 05:10:59pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.4 | 513298.4 | 79901 | 1.64041666667 | 11988 |
| 012687 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:00pm | Sensor | 1797-S0051=G-TJV.cor | 6842.9 | 1595920.4 | 513298.4 | 79903 | 1.64041666667 | 12687 |
| 011541 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:01pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.4 | 79905 | 1.64041666667 | 11541 |
| 011735 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:02pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.4 | 79907 | 1.64041666667 | 11735 |
| 011243 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:03pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.4 | 79909 | 1.64041666667 | 11243 |
| 011901 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:04pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.4 | 513298.4 | 79911 | 1.64041666667 | 11901 |
| 010025 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:05pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.4 | 79913 | 1.64041666667 | 10025 |
| 012256 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:06pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.4 | 79915 | 1.64041666667 | 12256 |
| 010324 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:07pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.3 | 79917 | 1.64041666667 | 10324 |
| 012871 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:08pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.3 | 79919 | 1.64041666667 | 12871 |
| 010597 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:09pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.5 | 513298.3 | 79921 | 1.64041666667 | 10597 |
| 010029 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:10pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.5 | 513298.4 | 79923 | 1.64041666667 | 10029 |
| 010277 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:11pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.4 | 79925 | 1.64041666667 | 10277 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:12pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.5 | 513298.5 | 79927 | 1.64041666667 | 11959 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:13pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.4 | 513298.5 | 79929 | 1.64041666667 | 11959 |
| 011750 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:14pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.4 | 513298.4 | 79931 | 1.64041666667 | 11750 |
| 010887 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:15pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.3 | 513298.2 | 79933 | 1.64041666667 | 10887 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010882 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:16pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.2 | 513298.3 | 79935 | 1.64041666667 | 10882 |
| 010610 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:17pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.2 | 513298.2 | 79937 | 1.64041666667 | 10610 |
| 010045 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:18pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.2 | 513298.2 | 79939 | 1.64041666667 | 10045 |
| 011845 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:19pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.2 | 513298.2 | 79941 | 1.64041666667 | 11845 |
| 012531 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:20pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.2 | 513298.2 | 79943 | 1.64041666667 | 12531 |
| 011412 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:21pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.2 | 513298.2 | 79945 | 1.64041666667 | 11412 |
| 011613 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:22pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.2 | 513298.2 | 79947 | 1.64041666667 | 11613 |
| 011513 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:23pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.2 | 513298.2 | 79949 | 1.64041666667 | 11513 |
| 010768 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:24pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.1 | 513298.2 | 79951 | 1.64041666667 | 10768 |
| 010792 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:25pm | Sensor | 1797-S0051=G-TJV.cor | 6842.7 | 1595920.2 | 513298.3 | 79953 | 1.64041666667 | 10792 |
| 010648 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:26pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.3 | 513298.8 | 79955 | 1.64041666667 | 10648 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:27pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.3 | 513299.1 | 79957 | 1.64041666667 | 11962 |
| 011450 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:28pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595920.1 | 513299.1 | 79959 | 1.64041666667 | 11450 |
| 012612 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:29pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595919.4 | 513299.0 | 79961 | 1.64041666667 | 12612 |
| 014013 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:30pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595917.3 | 513298.2 | 79963 | 1.64041666667 | 14013 |
| 012023 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:31pm | Sensor | 1797-S0051=G-TJV.cor | 6842.6 | 1595914.5 | 513296.8 | 79965 | 1.64041666667 | 12023 |
| 012125 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:32pm | Sensor | 1797-S0051=G-TJV.cor | 6842.8 | 1595912.0 | 513296.0 | 79967 | 1.64041666667 | 12125 |
| 011791 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:33pm | Sensor | 1797-S0051=G-TJV.cor | 6842.5 | 1595909.0 | 513295.1 | 79969 | 1.64041666667 | 11791 |
| 011737 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:34pm | Sensor | 1797-S0051=G-TJV.cor | 6842.3 | 1595906.4 | 513294.5 | 79971 | 1.64041666667 | 11737 |
| 010944 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:35pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595903.7 | 513293.2 | 79973 | 1.64041666667 | 10944 |
| 011796 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:36pm | Sensor | 1797-S0051=G-TJV.cor | 6842.3 | 1595902.2 | 513290.9 | 79975 | 1.64041666667 | 11796 |
| 010929 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:37pm | Sensor | 1797-S0051=G-TJV.cor | 6842.3 | 1595900.6 | 513288.4 | 79977 | 1.64041666667 | 10929 |
| 012512 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:38pm | Sensor | 1797-S0051=G-TJV.cor | 6842.4 | 1595899.1 | 513285.9 | 79979 | 1.64041666667 | 12512 |
| 011978 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:39pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595897.4 | 513282.5 | 79981 | 1.64041666667 | 11978 |
| 012174 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:40pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595895.7 | 513279.6 | 79983 | 1.64041666667 | 12174 |
| 012253 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:41pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595893.6 | 513276.8 | 79985 | 1.64041666667 | 12253 |
| 012753 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:42pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595891.5 | 513273.9 | 79987 | 1.64041666667 | 12753 |
| 011828 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:43pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1595889.5 | 513271.3 | 79989 | 1.64041666667 | 11828 |
| 011477 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:44pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1595887.5 | 513268.8 | 79991 | 1.64041666667 | 11477 |
| 012469 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:45pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595885.3 | 513266.5 | 79993 | 1.64041666667 | 12469 |
| 010047 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:46pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595883.4 | 513264.4 | 79995 | 1.64041666667 | 10047 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:47pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595881.3 | 513261.6 | 79997 | 1.64041666667 | 12652 |
| 010963 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:48pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1595879.5 | 513258.7 | 79999 | 1.64041666667 | 10963 |
| 012850 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:49pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595877.9 | 513255.7 | 80001 | 1.64041666667 | 12850 |
| 011582 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:50pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595876.6 | 513252.9 | 80003 | 1.64041666667 | 11582 |
| 014295 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:51pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595874.8 | 513249.5 | 80005 | 1.64041666667 | 14295 |
| 011373 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:52pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595873.2 | 513246.4 | 80007 | 1.64041666667 | 11373 |
| 010733 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:53pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595872.0 | 513243.3 | 80009 | 1.64041666667 | 10733 |
| 012373 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:54pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595871.4 | 513240.0 | 80011 | 1.64041666667 | 12373 |
| 011343 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:55pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595870.0 | 513236.6 | 80013 | 1.64041666667 | 11343 |
| 011685 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:56pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595868.6 | 513234.0 | 80015 | 1.64041666667 | 11685 |
| 011681 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:57pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595867.0 | 513230.9 | 80017 | 1.64041666667 | 11681 |
| 011770 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:58pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595865.6 | 513227.8 | 80019 | 1.64041666667 | 11770 |
| 012092 | 0 | GeoXH 6000 | 08/19/2015 | 05:11:59pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595864.3 | 513224.8 | 80021 | 1.64041666667 | 12092 |
| 012023 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:00pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595862.8 | 513221.6 | 80023 | 1.64041666667 | 12023 |
| 010595 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:01pm | Sensor | 1797-S0051=G-TJV.cor | 6841.3 | 1595860.8 | 513217.9 | 80025 | 1.64041666667 | 10595 |
| 011589 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:02pm | Sensor | 1797-S0051=G-TJV.cor | 6840.9 | 1595859.0 | 513214.5 | 80027 | 1.64041666667 | 11589 |
| 011327 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:03pm | Sensor | 1797-S0051=G-TJV.cor | 6840.8 | 1595857.0 | 513210.8 | 80029 | 1.64041666667 | 11327 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010421 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:04pm | Sensor | 1797-S0051=G-TJV.cor | 6840.7 | 1595855.5 | 513208.0 | 80031 | 1.64041666667 | 10421 |
| 013135 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:05pm | Sensor | 1797-S0051=G-TJV.cor | 6840.7 | 1595853.6 | 513204.7 | 80033 | 1.64041666667 | 13135 |
| 012704 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:06pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595852.2 | 513201.4 | 80035 | 1.64041666667 | 12704 |
| 011336 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:07pm | Sensor | 1797-S0051=G-TJV.cor | 6840.7 | 1595850.9 | 513197.9 | 80037 | 1.64041666667 | 11336 |
| 010574 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:08pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595849.4 | 513194.8 | 80039 | 1.64041666667 | 10574 |
| 010923 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:09pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595847.0 | 513191.3 | 80041 | 1.64041666667 | 10923 |
| 010920 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:10pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595845.5 | 513188.4 | 80043 | 1.64041666667 | 10920 |
| 010980 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:11pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595844.4 | 513184.6 | 80045 | 1.64041666667 | 10980 |
| 010470 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:12pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595843.8 | 513181.7 | 80047 | 1.64041666667 | 10470 |
| 011628 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:13pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595842.7 | 513178.4 | 80049 | 1.64041666667 | 11628 |
| 011007 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:14pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595842.0 | 513175.4 | 80051 | 1.64041666667 | 11007 |
| 011212 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:15pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595840.6 | 513171.6 | 80053 | 1.64041666667 | 11212 |
| 011773 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:16pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595838.9 | 513168.7 | 80055 | 1.64041666667 | 11773 |
| 009363 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:17pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595836.8 | 513165.7 | 80057 | 1.64041666667 | 9363 |
| 010020 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:18pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595835.0 | 513162.6 | 80059 | 1.64041666667 | 10020 |
| 010485 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:19pm | Sensor | 1797-S0051=G-TJV.cor | 6840.6 | 1595832.9 | 513160.0 | 80061 | 1.64041666667 | 10485 |
| 010361 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:20pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1595830.7 | 513157.6 | 80063 | 1.64041666667 | 10361 |
| 009550 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:21pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595828.5 | 513154.6 | 80065 | 1.64041666667 | 9550 |
| 010217 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:22pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595826.8 | 513151.3 | 80067 | 1.64041666667 | 10217 |
| 011674 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:23pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595825.1 | 513148.3 | 80069 | 1.64041666667 | 11674 |
| 011678 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:24pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595822.8 | 513145.4 | 80071 | 1.64041666667 | 11678 |
| 011019 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:25pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1595820.3 | 513142.7 | 80073 | 1.64041666667 | 11019 |
| 010795 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:26pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595817.7 | 513140.2 | 80075 | 1.64041666667 | 10795 |
| 010078 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:27pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1595815.6 | 513137.6 | 80077 | 1.64041666667 | 10078 |
| 010229 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:28pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595813.7 | 513135.0 | 80079 | 1.64041666667 | 10229 |
| 010837 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:29pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595811.3 | 513131.5 | 80081 | 1.64041666667 | 10837 |
| 010329 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:30pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595809.0 | 513128.7 | 80083 | 1.64041666667 | 10329 |
| 011132 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:31pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1595806.3 | 513125.5 | 80085 | 1.64041666667 | 11132 |
| 010733 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:32pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595803.6 | 513122.6 | 80087 | 1.64041666667 | 10733 |
| 011113 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:33pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1595801.2 | 513119.9 | 80089 | 1.64041666667 | 11113 |
| 009498 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:34pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595799.0 | 513116.9 | 80091 | 1.64041666667 | 9498 |
| 010114 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:35pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595796.8 | 513113.7 | 80093 | 1.64041666667 | 10114 |
| 010268 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:36pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1595794.7 | 513110.8 | 80095 | 1.64041666667 | 10268 |
| 010907 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:37pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1595793.0 | 513107.2 | 80097 | 1.64041666667 | 10907 |
| 009566 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:38pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1595792.9 | 513104.2 | 80099 | 1.64041666667 | 9566 |
| 010821 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:39pm | Sensor | 1797-S0051=G-TJV.cor | 6840.0 | 1595793.8 | 513100.4 | 80101 | 1.64041666667 | 10821 |
| 011195 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:40pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1595793.9 | 513097.3 | 80103 | 1.64041666667 | 11195 |
| 012488 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:41pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1595793.6 | 513093.5 | 80105 | 1.64041666667 | 12488 |
| 011612 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:42pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595793.1 | 513089.8 | 80107 | 1.64041666667 | 11612 |
| 010403 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:43pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595792.1 | 513086.9 | 80109 | 1.64041666667 | 10403 |
| 009860 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:44pm | Sensor | 1797-S0051=G-TJV.cor | 6840.4 | 1595790.1 | 513083.9 | 80111 | 1.64041666667 | 9860 |
| 012965 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:45pm | Sensor | 1797-S0051=G-TJV.cor | 6840.9 | 1595788.5 | 513081.4 | 80113 | 1.64041666667 | 12965 |
| 010591 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:46pm | Sensor | 1797-S0051=G-TJV.cor | 6841.2 | 1595787.2 | 513078.9 | 80115 | 1.64041666667 | 10591 |
| 011167 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:47pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595785.4 | 513076.3 | 80117 | 1.64041666667 | 11167 |
| 010142 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:48pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595783.5 | 513073.9 | 80119 | 1.64041666667 | 10142 |
| 010245 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:49pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595781.2 | 513071.1 | 80121 | 1.64041666667 | 10245 |
| 010751 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:50pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595779.4 | 513068.6 | 80123 | 1.64041666667 | 10751 |
| 009948 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:51pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595777.4 | 513065.9 | 80125 | 1.64041666667 | 9948 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010887 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:52pm | Sensor | 1797-S0051=G-TJV.cor | 6842.2 | 1595775.7 | 513063.4 | 80127 | 1.64041666667 | 10887 |
| 009021 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:53pm | Sensor | 1797-S0051=G-TJV.cor | 6842.1 | 1595774.1 | 513060.9 | 80129 | 1.64041666667 | 9021 |
| 009095 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:54pm | Sensor | 1797-S0051=G-TJV.cor | 6842.0 | 1595772.0 | 513058.1 | 80131 | 1.64041666667 | 9095 |
| 009683 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:55pm | Sensor | 1797-S0051=G-TJV.cor | 6841.9 | 1595769.5 | 513056.0 | 80133 | 1.64041666667 | 9683 |
| 010941 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:56pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595767.1 | 513054.2 | 80135 | 1.64041666667 | 10941 |
| 011315 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:57pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595764.3 | 513051.8 | 80137 | 1.64041666667 | 11315 |
| 010598 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:58pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595761.8 | 513049.5 | 80139 | 1.64041666667 | 10598 |
| 009489 | 0 | GeoXH 6000 | 08/19/2015 | 05:12:59pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595759.2 | 513047.8 | 80141 | 1.64041666667 | 9489 |
| 010202 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:00pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595756.0 | 513046.0 | 80143 | 1.64041666667 | 10202 |
| 009900 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:01pm | Sensor | 1797-S0051=G-TJV.cor | 6841.8 | 1595753.2 | 513044.1 | 80145 | 1.64041666667 | 9900 |
| 010905 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:02pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595750.8 | 513041.5 | 80147 | 1.64041666667 | 10905 |
| 010736 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:03pm | Sensor | 1797-S0051=G-TJV.cor | 6841.7 | 1595749.1 | 513038.4 | 80149 | 1.64041666667 | 10736 |
| 009254 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:04pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595747.6 | 513036.0 | 80151 | 1.64041666667 | 9254 |
| 009063 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:05pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595744.9 | 513033.0 | 80153 | 1.64041666667 | 9063 |
| 010455 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:06pm | Sensor | 1797-S0051=G-TJV.cor | 6841.2 | 1595742.2 | 513030.5 | 80155 | 1.64041666667 | 10455 |
| 010803 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:07pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595739.3 | 513027.9 | 80157 | 1.64041666667 | 10803 |
| 010501 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:08pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595737.0 | 513025.7 | 80159 | 1.64041666667 | 10501 |
| 011115 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:09pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595734.5 | 513023.2 | 80161 | 1.64041666667 | 11115 |
| 010938 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:10pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595732.4 | 513021.1 | 80163 | 1.64041666667 | 10938 |
| 012784 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:11pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595729.2 | 513018.4 | 80165 | 1.64041666667 | 12784 |
| 012316 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:12pm | Sensor | 1797-S0051=G-TJV.cor | 6841.4 | 1595726.7 | 513016.3 | 80167 | 1.64041666667 | 12316 |
| 012589 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:13pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595723.9 | 513013.6 | 80169 | 1.64041666667 | 12589 |
| 015057 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:14pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595721.9 | 513011.4 | 80171 | 1.64041666667 | 15057 |
| 011774 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:15pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595719.0 | 513008.3 | 80173 | 1.64041666667 | 11774 |
| 010953 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:16pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595716.6 | 513006.4 | 80175 | 1.64041666667 | 10953 |
| 012038 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:17pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595713.7 | 513004.8 | 80177 | 1.64041666667 | 12038 |
| 013149 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:18pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595710.9 | 513003.5 | 80179 | 1.64041666667 | 13149 |
| 013637 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:19pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595708.2 | 513001.4 | 80181 | 1.64041666667 | 13637 |
| 012199 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:20pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595705.8 | 512999.3 | 80183 | 1.64041666667 | 12199 |
| 013969 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:21pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595703.2 | 512997.5 | 80185 | 1.64041666667 | 13969 |
| 011442 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:22pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595701.3 | 512995.5 | 80187 | 1.64041666667 | 11442 |
| 011800 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:23pm | Sensor | 1797-S0051=G-TJV.cor | 6841.6 | 1595698.9 | 512993.5 | 80189 | 1.64041666667 | 11800 |
| 013510 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:24pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595696.5 | 512991.9 | 80191 | 1.64041666667 | 13510 |
| 011447 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:25pm | Sensor | 1797-S0051=G-TJV.cor | 6841.3 | 1595694.3 | 512990.1 | 80193 | 1.64041666667 | 11447 |
| 011351 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:26pm | Sensor | 1797-S0051=G-TJV.cor | 6841.4 | 1595692.1 | 512988.4 | 80195 | 1.64041666667 | 11351 |
| 012408 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:27pm | Sensor | 1797-S0051=G-TJV.cor | 6841.5 | 1595689.3 | 512986.5 | 80197 | 1.64041666667 | 12408 |
| 011442 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:28pm | Sensor | 1797-S0051=G-TJV.cor | 6841.3 | 1595687.5 | 512984.5 | 80199 | 1.64041666667 | 11442 |
| 009910 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:29pm | Sensor | 1797-S0051=G-TJV.cor | 6841.1 | 1595684.9 | 512982.2 | 80201 | 1.64041666667 | 9910 |
| 009827 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:30pm | Sensor | 1797-S0051=G-TJV.cor | 6841.1 | 1595682.4 | 512980.3 | 80203 | 1.64041666667 | 9827 |
| 008846 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:31pm | Sensor | 1797-S0051=G-TJV.cor | 6840.9 | 1595680.3 | 512978.3 | 80205 | 1.64041666667 | 8846 |
| 011031 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:32pm | Sensor | 1797-S0051=G-TJV.cor | 6840.8 | 1595678.5 | 512976.6 | 80207 | 1.64041666667 | 11031 |
| 009538 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:33pm | Sensor | 1797-S0051=G-TJV.cor | 6840.8 | 1595676.0 | 512974.4 | 80209 | 1.64041666667 | 9538 |
| 010184 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:34pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595674.4 | 512972.7 | 80211 | 1.64041666667 | 10184 |
| 010736 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:35pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595671.8 | 512970.8 | 80213 | 1.64041666667 | 10736 |
| 012464 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:36pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595669.6 | 512969.8 | 80215 | 1.64041666667 | 12464 |
| 011156 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:37pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595667.8 | 512968.1 | 80217 | 1.64041666667 | 11156 |
| 011309 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:38pm | Sensor | 1797-S0051=G-TJV.cor | 6840.5 | 1595665.7 | 512966.6 | 80219 | 1.64041666667 | 11309 |
| 010477 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:39pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1595663.7 | 512964.3 | 80221 | 1.64041666667 | 10477 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011379 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:40pm | Sensor | 1797-S0051=G-TJV.cor | 6840.3 | 1595662.2 | 512962.1 | 80223 | 1.64041666667 | 11379 |
| 011784 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:41pm | Sensor | 1797-S0051=G-TJV.cor | 6840.2 | 1595659.7 | 512960.3 | 80225 | 1.64041666667 | 11784 |
| 013026 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:42pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1595657.5 | 512958.8 | 80227 | 1.64041666667 | 13026 |
| 013366 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:43pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1595655.1 | 512956.9 | 80229 | 1.64041666667 | 13366 |
| 012281 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:44pm | Sensor | 1797-S0051=G-TJV.cor | 6840.1 | 1595653.5 | 512956.2 | 80231 | 1.64041666667 | 12281 |
| 011290 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:45pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1595652.0 | 512955.5 | 80233 | 1.64041666667 | 11290 |
| 010502 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:46pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1595651.7 | 512955.6 | 80235 | 1.64041666667 | 10502 |
| 010965 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:47pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1595652.5 | 512955.6 | 80237 | 1.64041666667 | 10965 |
| 010451 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:48pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1595652.7 | 512955.9 | 80239 | 1.64041666667 | 10451 |
| 009693 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:49pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1595652.6 | 512955.9 | 80241 | 1.64041666667 | 9693 |
| 009743 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:50pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1595652.7 | 512955.9 | 80243 | 1.64041666667 | 9743 |
| 009785 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:51pm | Sensor | 1797-S0051=G-TJV.cor | 6839.9 | 1595652.8 | 512955.9 | 80245 | 1.64041666667 | 9785 |
| 009736 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:52pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1595652.8 | 512955.9 | 80247 | 1.64041666667 | 9736 |
| 010204 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:53pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1595652.0 | 512955.9 | 80249 | 1.64041666667 | 10204 |
| 009781 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:54pm | Sensor | 1797-S0051=G-TJV.cor | 6839.8 | 1595650.8 | 512955.8 | 80251 | 1.64041666667 | 9781 |
| 011505 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:55pm | Sensor | 1797-S0051=G-TJV.cor | 6839.7 | 1595649.0 | 512955.5 | 80253 | 1.64041666667 | 11505 |
| 010436 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:56pm | Sensor | 1797-S0051=G-TJV.cor | 6839.6 | 1595647.2 | 512955.8 | 80255 | 1.64041666667 | 10436 |
| 009329 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:57pm | Sensor | 1797-S0051=G-TJV.cor | 6839.5 | 1595644.4 | 512955.9 | 80257 | 1.64041666667 | 9329 |
| 011152 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:58pm | Sensor | 1797-S0051=G-TJV.cor | 6839.7 | 1595642.4 | 512955.5 | 80259 | 1.64041666667 | 11152 |
| 010768 | 0 | GeoXH 6000 | 08/19/2015 | 05:13:59pm | Sensor | 1797-S0051=G-TJV.cor | 6839.6 | 1595639.2 | 512955.2 | 80261 | 1.64041666667 | 10768 |
| 009772 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:00pm | Sensor | 1797-S0051=G-TJV.cor | 6839.4 | 1595636.5 | 512954.1 | 80263 | 1.64041666667 | 9772 |
| 010693 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:01pm | Sensor | 1797-S0051=G-TJV.cor | 6839.4 | 1595634.2 | 512952.8 | 80265 | 1.64041666667 | 10693 |
| 010653 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:02pm | Sensor | 1797-S0051=G-TJV.cor | 6839.3 | 1595631.7 | 512951.2 | 80267 | 1.64041666667 | 10653 |
| 010283 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:03pm | Sensor | 1797-S0051=G-TJV.cor | 6839.0 | 1595629.7 | 512949.1 | 80269 | 1.64041666667 | 10283 |
| 009530 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:04pm | Sensor | 1797-S0051=G-TJV.cor | 6839.0 | 1595628.0 | 512946.9 | 80271 | 1.64041666667 | 9530 |
| 010032 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:05pm | Sensor | 1797-S0051=G-TJV.cor | 6838.9 | 1595625.7 | 512944.4 | 80273 | 1.64041666667 | 10032 |
| 009828 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:06pm | Sensor | 1797-S0051=G-TJV.cor | 6838.8 | 1595624.4 | 512942.3 | 80275 | 1.64041666667 | 9828 |
| 009177 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:07pm | Sensor | 1797-S0051=G-TJV.cor | 6838.7 | 1595622.3 | 512939.7 | 80277 | 1.64041666667 | 9177 |
| 011744 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:08pm | Sensor | 1797-S0051=G-TJV.cor | 6838.7 | 1595620.4 | 512937.7 | 80279 | 1.64041666667 | 11744 |
| 010286 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:09pm | Sensor | 1797-S0051=G-TJV.cor | 6838.5 | 1595618.3 | 512935.0 | 80281 | 1.64041666667 | 10286 |
| 010641 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:10pm | Sensor | 1797-S0051=G-TJV.cor | 6838.5 | 1595616.3 | 512933.3 | 80283 | 1.64041666667 | 10641 |
| 009890 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:11pm | Sensor | 1797-S0051=G-TJV.cor | 6838.6 | 1595614.0 | 512931.1 | 80285 | 1.64041666667 | 9890 |
| 009762 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:12pm | Sensor | 1797-S0051=G-TJV.cor | 6838.4 | 1595612.7 | 512928.7 | 80287 | 1.64041666667 | 9762 |
| 011200 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:13pm | Sensor | 1797-S0051=G-TJV.cor | 6838.5 | 1595611.2 | 512925.6 | 80289 | 1.64041666667 | 11200 |
| 012220 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:14pm | Sensor | 1797-S0051=G-TJV.cor | 6838.4 | 1595609.7 | 512923.1 | 80291 | 1.64041666667 | 12220 |
| 011425 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:15pm | Sensor | 1797-S0051=G-TJV.cor | 6838.3 | 1595608.1 | 512920.2 | 80293 | 1.64041666667 | 11425 |
| 011406 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:16pm | Sensor | 1797-S0051=G-TJV.cor | 6838.3 | 1595606.6 | 512918.5 | 80295 | 1.64041666667 | 11406 |
| 011791 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:17pm | Sensor | 1797-S0051=G-TJV.cor | 6838.3 | 1595604.0 | 512917.1 | 80297 | 1.64041666667 | 11791 |
| 011827 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:18pm | Sensor | 1797-S0051=G-TJV.cor | 6838.2 | 1595602.2 | 512916.0 | 80299 | 1.64041666667 | 11827 |
| 012347 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:19pm | Sensor | 1797-S0051=G-TJV.cor | 6838.0 | 1595599.5 | 512914.5 | 80301 | 1.64041666667 | 12347 |
| 010886 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:20pm | Sensor | 1797-S0051=G-TJV.cor | 6838.0 | 1595597.4 | 512913.3 | 80303 | 1.64041666667 | 10886 |
| 010161 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:21pm | Sensor | 1797-S0051=G-TJV.cor | 6837.8 | 1595595.2 | 512910.9 | 80305 | 1.64041666667 | 10161 |
| 010850 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:22pm | Sensor | 1797-S0051=G-TJV.cor | 6837.8 | 1595593.5 | 512908.9 | 80307 | 1.64041666667 | 10850 |
| 010212 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:23pm | Sensor | 1797-S0051=G-TJV.cor | 6837.8 | 1595591.4 | 512906.1 | 80309 | 1.64041666667 | 10212 |
| 011313 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:24pm | Sensor | 1797-S0051=G-TJV.cor | 6837.6 | 1595589.7 | 512903.4 | 80311 | 1.64041666667 | 11313 |
| 011438 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:25pm | Sensor | 1797-S0051=G-TJV.cor | 6837.6 | 1595587.5 | 512901.6 | 80313 | 1.64041666667 | 11438 |
| 010839 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:26pm | Sensor | 1797-S0051=G-TJV.cor | 6837.5 | 1595585.0 | 512900.7 | 80315 | 1.64041666667 | 10839 |
| 010720 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:27pm | Sensor | 1797-S0051=G-TJV.cor | 6837.3 | 1595582.1 | 512899.2 | 80317 | 1.64041666667 | 10720 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011260 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:28pm | Sensor | 1797-S0051=G-TJV.cor | 6837.4 | 1595580.3 | 512897.7 | 80319 | 1.64041666667 | 11260 |
| 008905 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:29pm | Sensor | 1797-S0051=G-TJV.cor | 6837.4 | 1595578.1 | 512895.1 | 80321 | 1.64041666667 | 8905 |
| 010836 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:30pm | Sensor | 1797-S0051=G-TJV.cor | 6837.3 | 1595576.9 | 512892.8 | 80323 | 1.64041666667 | 10836 |
| 009849 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:31pm | Sensor | 1797-S0051=G-TJV.cor | 6837.4 | 1595575.4 | 512890.8 | 80325 | 1.64041666667 | 9849 |
| 010142 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:32pm | Sensor | 1797-S0051=G-TJV.cor | 6837.3 | 1595573.0 | 512889.3 | 80327 | 1.64041666667 | 10142 |
| 010725 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:33pm | Sensor | 1797-S0051=G-TJV.cor | 6836.9 | 1595571.0 | 512887.3 | 80329 | 1.64041666667 | 10725 |
| 011321 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:34pm | Sensor | 1797-S0051=G-TJV.cor | 6836.9 | 1595569.5 | 512884.8 | 80331 | 1.64041666667 | 11321 |
| 011230 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:35pm | Sensor | 1797-S0051=G-TJV.cor | 6836.7 | 1595566.6 | 512883.0 | 80333 | 1.64041666667 | 11230 |
| 010517 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:36pm | Sensor | 1797-S0051=G-TJV.cor | 6836.7 | 1595564.0 | 512882.5 | 80335 | 1.64041666667 | 10517 |
| 011119 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:37pm | Sensor | 1797-S0051=G-TJV.cor | 6836.7 | 1595561.4 | 512882.1 | 80337 | 1.64041666667 | 11119 |
| 009499 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:38pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595559.0 | 512881.6 | 80339 | 1.64041666667 | 9499 |
| 009185 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:39pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595555.9 | 512879.8 | 80341 | 1.64041666667 | 9185 |
| 009706 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:40pm | Sensor | 1797-S0051=G-TJV.cor | 6836.5 | 1595553.9 | 512878.1 | 80343 | 1.64041666667 | 9706 |
| 011006 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:41pm | Sensor | 1797-S0051=G-TJV.cor | 6836.4 | 1595551.1 | 512877.2 | 80345 | 1.64041666667 | 11006 |
| 011181 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:42pm | Sensor | 1797-S0051=G-TJV.cor | 6836.3 | 1595548.6 | 512876.0 | 80347 | 1.64041666667 | 11181 |
| 011045 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:43pm | Sensor | 1797-S0051=G-TJV.cor | 6836.3 | 1595546.2 | 512874.5 | 80349 | 1.64041666667 | 11045 |
| 009901 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:44pm | Sensor | 1797-S0051=G-TJV.cor | 6836.4 | 1595544.2 | 512873.7 | 80351 | 1.64041666667 | 9901 |
| 010425 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:45pm | Sensor | 1797-S0051=G-TJV.cor | 6836.5 | 1595542.0 | 512872.2 | 80353 | 1.64041666667 | 10425 |
| 009592 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:46pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595540.7 | 512870.9 | 80355 | 1.64041666667 | 9592 |
| 009749 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:47pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595539.4 | 512868.0 | 80357 | 1.64041666667 | 9749 |
| 009637 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:48pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595538.7 | 512865.7 | 80359 | 1.64041666667 | 9637 |
| 008889 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:49pm | Sensor | 1797-S0051=G-TJV.cor | 6836.4 | 1595537.0 | 512862.6 | 80361 | 1.64041666667 | 8889 |
| 009092 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:50pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595535.6 | 512860.3 | 80363 | 1.64041666667 | 9092 |
| 010253 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:51pm | Sensor | 1797-S0051=G-TJV.cor | 6836.8 | 1595534.9 | 512857.8 | 80365 | 1.64041666667 | 10253 |
| 011653 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:52pm | Sensor | 1797-S0051=G-TJV.cor | 6836.7 | 1595533.9 | 512855.7 | 80367 | 1.64041666667 | 11653 |
| 010263 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:53pm | Sensor | 1797-S0051=G-TJV.cor | 6836.8 | 1595533.6 | 512854.5 | 80369 | 1.64041666667 | 10263 |
| 008925 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:54pm | Sensor | 1797-S0051=G-TJV.cor | 6836.8 | 1595533.6 | 512854.4 | 80371 | 1.64041666667 | 8925 |
| 009731 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:55pm | Sensor | 1797-S0051=G-TJV.cor | 6836.7 | 1595533.8 | 512854.3 | 80373 | 1.64041666667 | 9731 |
| 010863 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:56pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595533.9 | 512854.5 | 80375 | 1.64041666667 | 10863 |
| 009495 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:57pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595533.9 | 512854.5 | 80377 | 1.64041666667 | 9495 |
| 010653 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:58pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595533.6 | 512854.4 | 80379 | 1.64041666667 | 10653 |
| 009353 | 0 | GeoXH 6000 | 08/19/2015 | 05:14:59pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595533.7 | 512854.4 | 80381 | 1.64041666667 | 9353 |
| 009958 | 0 | GeoXH 6000 | 08/19/2015 | 05:15:00pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595533.7 | 512854.4 | 80383 | 1.64041666667 | 9958 |
| 009989 | 0 | GeoXH 6000 | 08/19/2015 | 05:15:01pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595533.8 | 512854.3 | 80385 | 1.64041666667 | 9989 |
| 007927 | 0 | GeoXH 6000 | 08/19/2015 | 05:15:02pm | Sensor | 1797-S0051=G-TJV.cor | 6836.6 | 1595533.9 | 512854.3 | 80388 | 1.64041666667 | 7927 |
| 013373 | 0 | GeoXH 6000 | 08/19/2015 | 04:18:56pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595932.6 | 512522.6 | 74901 | 1.64041666667 | 13373 |
| 012913 | 0 | GeoXH 6000 | 08/19/2015 | 04:18:57pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595933.1 | 512523.9 | 74904 | 1.64041666667 | 12913 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 04:18:58pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595933.0 | 512523.9 | 74906 | 1.64041666667 | 12918 |
| 012559 | 0 | GeoXH 6000 | 08/19/2015 | 04:18:59pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595933.1 | 512523.9 | 74908 | 1.64041666667 | 12559 |
| 012949 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:00pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595933.0 | 512523.8 | 74910 | 1.64041666667 | 12949 |
| 012717 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:01pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595933.0 | 512523.9 | 74912 | 1.64041666667 | 12717 |
| 012839 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:02pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.9 | 512524.1 | 74914 | 1.64041666667 | 12839 |
| 013500 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:03pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.8 | 512524.3 | 74916 | 1.64041666667 | 13500 |
| 013185 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:04pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.9 | 512524.3 | 74918 | 1.64041666667 | 13185 |
| 014246 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:05pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.8 | 512524.3 | 74920 | 1.64041666667 | 14246 |
| 013941 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:06pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.8 | 512524.3 | 74922 | 1.64041666667 | 13941 |
| 014075 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:07pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.8 | 512524.2 | 74924 | 1.64041666667 | 14075 |
| 011558 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:08pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.8 | 512524.0 | 74926 | 1.64041666667 | 11558 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013149 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:09pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.9 | 512524.0 | 74928 | 1.64041666667 | 13149 |
| 013427 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:10pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.8 | 512524.3 | 74930 | 1.64041666667 | 13427 |
| 013076 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:11pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.7 | 512524.6 | 74932 | 1.64041666667 | 13076 |
| 012149 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:12pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.6 | 512524.7 | 74934 | 1.64041666667 | 12149 |
| 014137 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:13pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.6 | 512524.6 | 74936 | 1.64041666667 | 14137 |
| 014034 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:14pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.5 | 512524.6 | 74938 | 1.64041666667 | 14034 |
| 012568 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:15pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.4 | 512524.7 | 74940 | 1.64041666667 | 12568 |
| 013912 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:16pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.5 | 512524.6 | 74942 | 1.64041666667 | 13912 |
| 012268 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:17pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.7 | 512524.4 | 74944 | 1.64041666667 | 12268 |
| 012037 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:18pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.7 | 512524.4 | 74946 | 1.64041666667 | 12037 |
| 012069 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:19pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.7 | 512524.4 | 74948 | 1.64041666667 | 12069 |
| 013367 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:20pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.8 | 512524.4 | 74950 | 1.64041666667 | 13367 |
| 012821 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:21pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.7 | 512524.1 | 74952 | 1.64041666667 | 12821 |
| 012295 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:22pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595932.2 | 512523.7 | 74954 | 1.64041666667 | 12295 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:23pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595932.5 | 512523.2 | 74956 | 1.64041666667 | 13424 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:24pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595934.3 | 512521.7 | 74958 | 1.64041666667 | 12536 |
| 014144 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:25pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595936.0 | 512520.5 | 74960 | 1.64041666667 | 14144 |
| 014126 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:26pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595938.2 | 512520.9 | 74962 | 1.64041666667 | 14126 |
| 013641 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:27pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595940.7 | 512521.5 | 74964 | 1.64041666667 | 13641 |
| 013850 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:28pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595943.4 | 512523.1 | 74966 | 1.64041666667 | 13850 |
| 013782 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:29pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595945.8 | 512524.4 | 74968 | 1.64041666667 | 13782 |
| 014455 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:30pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595948.9 | 512526.0 | 74970 | 1.64041666667 | 14455 |
| 012704 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:31pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595951.3 | 512527.7 | 74972 | 1.64041666667 | 12704 |
| 012776 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:32pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595954.5 | 512529.1 | 74974 | 1.64041666667 | 12776 |
| 013994 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:33pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595957.5 | 512530.7 | 74976 | 1.64041666667 | 13994 |
| 014808 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:34pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595960.3 | 512532.1 | 74978 | 1.64041666667 | 14808 |
| 013272 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:35pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595963.0 | 512533.2 | 74980 | 1.64041666667 | 13272 |
| 014598 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:36pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595966.1 | 512535.0 | 74982 | 1.64041666667 | 14598 |
| 015199 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:37pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595968.5 | 512536.7 | 74984 | 1.64041666667 | 15199 |
| 013669 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:38pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595971.6 | 512538.3 | 74986 | 1.64041666667 | 13669 |
| 013797 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:39pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595974.3 | 512540.1 | 74988 | 1.64041666667 | 13797 |
| 015479 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:40pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595977.1 | 512542.1 | 74990 | 1.64041666667 | 15479 |
| 014130 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:41pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595979.5 | 512543.5 | 74992 | 1.64041666667 | 14130 |
| 014542 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:42pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595982.4 | 512545.5 | 74994 | 1.64041666667 | 14542 |
| 013985 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:43pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595984.9 | 512546.7 | 74996 | 1.64041666667 | 13985 |
| 013846 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:44pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595987.8 | 512547.9 | 74998 | 1.64041666667 | 13846 |
| 015611 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:45pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595990.4 | 512549.6 | 75000 | 1.64041666667 | 15611 |
| 014253 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:46pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595993.7 | 512551.4 | 75002 | 1.64041666667 | 14253 |
| 014003 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:47pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595996.2 | 512552.6 | 75004 | 1.64041666667 | 14003 |
| 014840 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:48pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595998.8 | 512554.7 | 75006 | 1.64041666667 | 14840 |
| 014360 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:49pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1596001.2 | 512556.6 | 75008 | 1.64041666667 | 14360 |
| 014300 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596004.0 | 512558.9 | 75010 | 1.64041666667 | 14300 |
| 014015 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:51pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596006.1 | 512560.6 | 75012 | 1.64041666667 | 14015 |
| 013973 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596009.2 | 512562.4 | 75014 | 1.64041666667 | 13973 |
| 014773 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:53pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596011.8 | 512563.9 | 75016 | 1.64041666667 | 14773 |
| 014073 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:54pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596014.6 | 512565.7 | 75018 | 1.64041666667 | 14073 |
| 013808 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:55pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596016.9 | 512567.4 | 75020 | 1.64041666667 | 13808 |
| 015752 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:56pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596019.2 | 512569.5 | 75022 | 1.64041666667 | 15752 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014048 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:57pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596020.8 | 512570.8 | 75024 | 1.64041666667 | 14048 |
| 013592 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596022.3 | 512571.7 | 75026 | 1.64041666667 | 13592 |
| 015818 | 0 | GeoXH 6000 | 08/19/2015 | 04:19:59pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596022.3 | 512571.6 | 75028 | 1.64041666667 | 15818 |
| 017214 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:00pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596021.2 | 512571.8 | 75030 | 1.64041666667 | 17214 |
| 014203 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:01pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596019.9 | 512573.0 | 75032 | 1.64041666667 | 14203 |
| 013781 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:02pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596018.9 | 512574.0 | 75034 | 1.64041666667 | 13781 |
| 014335 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:03pm | Sensor | 1797-S0050-G-TJV.cor | 6841.5 | 1596018.5 | 512574.6 | 75036 | 1.64041666667 | 14335 |
| 018043 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:04pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596017.9 | 512576.7 | 75038 | 1.64041666667 | 18043 |
| 016391 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:05pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596017.0 | 512579.6 | 75040 | 1.64041666667 | 16391 |
| 015857 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596016.8 | 512582.0 | 75042 | 1.64041666667 | 15857 |
| 015394 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:07pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596017.3 | 512581.6 | 75044 | 1.64041666667 | 15394 |
| 014678 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:08pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596017.9 | 512579.9 | 75046 | 1.64041666667 | 14678 |
| 014619 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:09pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596017.6 | 512577.5 | 75048 | 1.64041666667 | 14619 |
| 015925 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:10pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596017.4 | 512575.3 | 75050 | 1.64041666667 | 15925 |
| 014241 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:11pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596015.3 | 512572.8 | 75052 | 1.64041666667 | 14241 |
| 014840 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596012.8 | 512570.2 | 75054 | 1.64041666667 | 14840 |
| 015170 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:13pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596010.7 | 512568.6 | 75056 | 1.64041666667 | 15170 |
| 013392 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596007.8 | 512567.3 | 75058 | 1.64041666667 | 13392 |
| 014148 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:15pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596005.0 | 512565.9 | 75060 | 1.64041666667 | 14148 |
| 014427 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596001.5 | 512564.5 | 75062 | 1.64041666667 | 14427 |
| 014586 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595998.8 | 512563.5 | 75064 | 1.64041666667 | 14586 |
| 013126 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595995.7 | 512561.6 | 75066 | 1.64041666667 | 13126 |
| 013901 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:19pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595993.0 | 512560.2 | 75068 | 1.64041666667 | 13901 |
| 014425 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595989.8 | 512558.6 | 75070 | 1.64041666667 | 14425 |
| 015066 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:21pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595987.5 | 512557.5 | 75072 | 1.64041666667 | 15066 |
| 013186 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595984.3 | 512556.2 | 75074 | 1.64041666667 | 13186 |
| 014996 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:23pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595982.0 | 512554.4 | 75076 | 1.64041666667 | 14996 |
| 016319 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:24pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595979.6 | 512552.4 | 75078 | 1.64041666667 | 16319 |
| 013530 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:25pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595977.3 | 512551.0 | 75080 | 1.64041666667 | 13530 |
| 014632 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:26pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595974.5 | 512549.1 | 75082 | 1.64041666667 | 14632 |
| 015028 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:27pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595971.7 | 512547.8 | 75084 | 1.64041666667 | 15028 |
| 013507 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:28pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595968.7 | 512546.4 | 75086 | 1.64041666667 | 13507 |
| 014026 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:29pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595966.3 | 512544.4 | 75088 | 1.64041666667 | 14026 |
| 015206 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:30pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595963.2 | 512542.6 | 75090 | 1.64041666667 | 15206 |
| 013461 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:31pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595960.6 | 512541.3 | 75092 | 1.64041666667 | 13461 |
| 015065 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:32pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595957.5 | 512539.6 | 75094 | 1.64041666667 | 15065 |
| 014896 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:33pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595954.4 | 512538.3 | 75096 | 1.64041666667 | 14896 |
| 016504 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:34pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595951.3 | 512536.6 | 75098 | 1.64041666667 | 16504 |
| 014746 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:35pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595948.7 | 512534.9 | 75100 | 1.64041666667 | 14746 |
| 013646 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:36pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595945.4 | 512533.3 | 75102 | 1.64041666667 | 13646 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:37pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595942.5 | 512531.6 | 75104 | 1.64041666667 | 12021 |
| 012785 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:38pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595939.7 | 512529.9 | 75106 | 1.64041666667 | 12785 |
| 012976 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:39pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595937.1 | 512528.6 | 75108 | 1.64041666667 | 12976 |
| 013384 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:40pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595934.6 | 512526.8 | 75110 | 1.64041666667 | 13384 |
| 013096 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:41pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595933.1 | 512525.8 | 75112 | 1.64041666667 | 13096 |
| 013294 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595931.5 | 512525.7 | 75114 | 1.64041666667 | 13294 |
| 014183 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:43pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595931.3 | 512525.8 | 75116 | 1.64041666667 | 14183 |
| 012966 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595931.1 | 512526.8 | 75118 | 1.64041666667 | 12966 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013261 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:45pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595929.7 | 512529.2 | 75120 | 1.64041666667 | 13261 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595929.3 | 512530.9 | 75122 | 1.64041666667 | 14355 |
| 013878 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:47pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595928.8 | 512531.8 | 75124 | 1.64041666667 | 13878 |
| 014839 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:48pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595927.3 | 512534.6 | 75126 | 1.64041666667 | 14839 |
| 012830 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:49pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595926.2 | 512537.0 | 75128 | 1.64041666667 | 12830 |
| 013407 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:50pm | Sensor | 1797-S0050-G-TJV.cor | 6837.5 | 1595925.7 | 512538.8 | 75130 | 1.64041666667 | 13407 |
| 014482 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:51pm | Sensor | 1797-S0050-G-TJV.cor | 6837.3 | 1595925.6 | 512539.0 | 75132 | 1.64041666667 | 14482 |
| 012500 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:52pm | Sensor | 1797-S0050-G-TJV.cor | 6837.1 | 1595925.5 | 512539.2 | 75134 | 1.64041666667 | 12500 |
| 011855 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:53pm | Sensor | 1797-S0050-G-TJV.cor | 6837.1 | 1595925.5 | 512539.3 | 75136 | 1.64041666667 | 11855 |
| 012383 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:54pm | Sensor | 1797-S0050-G-TJV.cor | 6837.5 | 1595925.7 | 512538.9 | 75138 | 1.64041666667 | 12383 |
| 011616 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:55pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595926.4 | 512537.9 | 75140 | 1.64041666667 | 11616 |
| 013254 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:56pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595927.0 | 512536.5 | 75142 | 1.64041666667 | 13254 |
| 014233 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:57pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595927.0 | 512534.9 | 75144 | 1.64041666667 | 14233 |
| 013758 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:58pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595928.5 | 512532.9 | 75146 | 1.64041666667 | 13758 |
| 014209 | 0 | GeoXH 6000 | 08/19/2015 | 04:20:59pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595930.6 | 512532.7 | 75148 | 1.64041666667 | 14209 |
| 014712 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:00pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595933.3 | 512533.4 | 75150 | 1.64041666667 | 14712 |
| 014358 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:01pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595935.9 | 512534.3 | 75152 | 1.64041666667 | 14358 |
| 013519 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:02pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595938.6 | 512536.5 | 75154 | 1.64041666667 | 13519 |
| 013369 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:03pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595941.1 | 512538.3 | 75156 | 1.64041666667 | 13369 |
| 014412 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:04pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595944.2 | 512539.8 | 75158 | 1.64041666667 | 14412 |
| 016143 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:05pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595946.8 | 512541.2 | 75160 | 1.64041666667 | 16143 |
| 016935 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595950.5 | 512542.6 | 75162 | 1.64041666667 | 16935 |
| 016203 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:07pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595953.1 | 512543.8 | 75164 | 1.64041666667 | 16203 |
| 013081 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595955.5 | 512545.5 | 75166 | 1.64041666667 | 13081 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:09pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595957.8 | 512546.9 | 75168 | 1.64041666667 | 12960 |
| 012900 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:10pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595960.5 | 512548.5 | 75170 | 1.64041666667 | 12900 |
| 012855 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:11pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595963.1 | 512550.2 | 75172 | 1.64041666667 | 12855 |
| 015213 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:12pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595966.0 | 512552.1 | 75174 | 1.64041666667 | 15213 |
| 015113 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:13pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595968.1 | 512553.7 | 75176 | 1.64041666667 | 15113 |
| 014638 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595971.7 | 512555.6 | 75178 | 1.64041666667 | 14638 |
| 015599 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:15pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595974.2 | 512557.4 | 75180 | 1.64041666667 | 15599 |
| 014400 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595976.7 | 512559.3 | 75182 | 1.64041666667 | 14400 |
| 014940 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595979.4 | 512560.7 | 75184 | 1.64041666667 | 14940 |
| 014475 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595982.7 | 512562.9 | 75186 | 1.64041666667 | 14475 |
| 014208 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:19pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595984.9 | 512564.4 | 75188 | 1.64041666667 | 14208 |
| 014562 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595987.8 | 512565.9 | 75190 | 1.64041666667 | 14562 |
| 014890 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:21pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595990.6 | 512567.9 | 75192 | 1.64041666667 | 14890 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595993.6 | 512569.7 | 75194 | 1.64041666667 | 14132 |
| 015083 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:23pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1595995.9 | 512570.6 | 75196 | 1.64041666667 | 15083 |
| 016070 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:24pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595998.4 | 512572.3 | 75198 | 1.64041666667 | 16070 |
| 014877 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:25pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596001.0 | 512573.3 | 75200 | 1.64041666667 | 14877 |
| 015239 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:26pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596003.7 | 512574.8 | 75202 | 1.64041666667 | 15239 |
| 015060 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:27pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596006.0 | 512576.1 | 75204 | 1.64041666667 | 15060 |
| 015735 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:28pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596008.6 | 512577.9 | 75206 | 1.64041666667 | 15735 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:29pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596010.8 | 512579.9 | 75208 | 1.64041666667 | 14463 |
| 013995 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:30pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596013.4 | 512581.3 | 75210 | 1.64041666667 | 13995 |
| 014928 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:31pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596015.4 | 512582.4 | 75212 | 1.64041666667 | 14928 |
| 013902 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:32pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596017.4 | 512583.1 | 75214 | 1.64041666667 | 13902 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015685 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:33pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596016.7 | 512584.7 | 75216 | 1.64041666667 | 15685 |
| 014991 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:34pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596016.8 | 512587.1 | 75218 | 1.64041666667 | 14991 |
| 015357 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:35pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596016.6 | 512588.3 | 75220 | 1.64041666667 | 15357 |
| 014369 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:36pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596016.0 | 512590.9 | 75222 | 1.64041666667 | 14369 |
| 014962 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:37pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596016.0 | 512593.8 | 75224 | 1.64041666667 | 14962 |
| 015560 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:38pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596016.0 | 512594.1 | 75226 | 1.64041666667 | 15560 |
| 016010 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:39pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596016.5 | 512593.2 | 75228 | 1.64041666667 | 16010 |
| 015252 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:40pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596017.2 | 512591.6 | 75230 | 1.64041666667 | 15252 |
| 015153 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:41pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596017.4 | 512589.2 | 75232 | 1.64041666667 | 15153 |
| 015368 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:42pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596019.1 | 512586.8 | 75234 | 1.64041666667 | 15368 |
| 014732 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:43pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596020.2 | 512586.0 | 75236 | 1.64041666667 | 14732 |
| 015023 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:44pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596019.1 | 512586.8 | 75238 | 1.64041666667 | 15023 |
| 013775 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:45pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596017.3 | 512586.8 | 75240 | 1.64041666667 | 13775 |
| 014124 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:46pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596014.9 | 512586.5 | 75242 | 1.64041666667 | 14124 |
| 015321 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:47pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596012.4 | 512585.5 | 75244 | 1.64041666667 | 15321 |
| 015980 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:48pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596009.9 | 512583.9 | 75246 | 1.64041666667 | 15980 |
| 015875 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:49pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596007.2 | 512582.5 | 75248 | 1.64041666667 | 15875 |
| 016658 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596004.4 | 512580.9 | 75250 | 1.64041666667 | 16658 |
| 015024 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:51pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596001.8 | 512579.4 | 75252 | 1.64041666667 | 15024 |
| 014676 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595999.1 | 512578.3 | 75254 | 1.64041666667 | 14676 |
| 016149 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:53pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595997.2 | 512577.0 | 75256 | 1.64041666667 | 16149 |
| 015437 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:54pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595994.3 | 512575.4 | 75258 | 1.64041666667 | 15437 |
| 015469 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:55pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595991.9 | 512573.9 | 75260 | 1.64041666667 | 15469 |
| 013137 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:56pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595989.1 | 512572.2 | 75262 | 1.64041666667 | 13137 |
| 014204 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:57pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595986.6 | 512571.3 | 75264 | 1.64041666667 | 14204 |
| 013571 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595984.3 | 512569.6 | 75266 | 1.64041666667 | 13571 |
| 014972 | 0 | GeoXH 6000 | 08/19/2015 | 04:21:59pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595981.5 | 512568.0 | 75268 | 1.64041666667 | 14972 |
| 016583 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:00pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595978.3 | 512566.3 | 75270 | 1.64041666667 | 16583 |
| 014525 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:01pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595975.9 | 512564.9 | 75272 | 1.64041666667 | 14525 |
| 012571 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:02pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595972.8 | 512563.6 | 75274 | 1.64041666667 | 12571 |
| 013702 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:03pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595970.3 | 512562.1 | 75276 | 1.64041666667 | 13702 |
| 013505 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:04pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595967.1 | 512560.6 | 75278 | 1.64041666667 | 13505 |
| 012436 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:05pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595964.4 | 512559.7 | 75280 | 1.64041666667 | 12436 |
| 014509 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595961.7 | 512558.0 | 75282 | 1.64041666667 | 14509 |
| 015537 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:07pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595958.9 | 512556.1 | 75284 | 1.64041666667 | 15537 |
| 014924 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595955.9 | 512554.5 | 75286 | 1.64041666667 | 14924 |
| 014741 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:09pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595953.2 | 512552.6 | 75288 | 1.64041666667 | 14741 |
| 016345 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:10pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595950.4 | 512551.0 | 75290 | 1.64041666667 | 16345 |
| 016626 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:11pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595947.6 | 512549.8 | 75292 | 1.64041666667 | 16626 |
| 017686 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:12pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595944.9 | 512548.1 | 75294 | 1.64041666667 | 17686 |
| 016151 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:13pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595942.5 | 512547.1 | 75296 | 1.64041666667 | 16151 |
| 013128 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:14pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595939.1 | 512545.8 | 75298 | 1.64041666667 | 13128 |
| 012492 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:15pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595936.6 | 512544.4 | 75300 | 1.64041666667 | 12492 |
| 013383 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:16pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595933.7 | 512542.8 | 75302 | 1.64041666667 | 13383 |
| 013665 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:17pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595931.4 | 512540.9 | 75304 | 1.64041666667 | 13665 |
| 014516 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:18pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595928.4 | 512539.3 | 75306 | 1.64041666667 | 14516 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:19pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595926.1 | 512538.8 | 75308 | 1.64041666667 | 12539 |
| 012315 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:20pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595926.4 | 512538.9 | 75310 | 1.64041666667 | 12315 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014148 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:21pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595926.6 | 512539.4 | 75312 | 1.64041666667 | 14148 |
| 013017 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:22pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595925.5 | 512542.1 | 75314 | 1.64041666667 | 13017 |
| 013544 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:23pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595925.3 | 512543.8 | 75316 | 1.64041666667 | 13544 |
| 013496 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:24pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595924.9 | 512544.8 | 75318 | 1.64041666667 | 13496 |
| 014954 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:25pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595923.7 | 512546.9 | 75320 | 1.64041666667 | 14954 |
| 013698 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:26pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595922.7 | 512549.0 | 75322 | 1.64041666667 | 13698 |
| 014314 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:27pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595922.0 | 512549.2 | 75324 | 1.64041666667 | 14314 |
| 012578 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:28pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595921.9 | 512550.1 | 75326 | 1.64041666667 | 12578 |
| 014274 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:29pm | Sensor | 1797-S0050-G-TJV.cor | 6837.2 | 1595922.2 | 512552.0 | 75328 | 1.64041666667 | 14274 |
| 013798 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:30pm | Sensor | 1797-S0050-G-TJV.cor | 6836.9 | 1595922.2 | 512552.3 | 75330 | 1.64041666667 | 13798 |
| 013589 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:31pm | Sensor | 1797-S0050-G-TJV.cor | 6836.8 | 1595922.1 | 512552.4 | 75332 | 1.64041666667 | 13589 |
| 013537 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:32pm | Sensor | 1797-S0050-G-TJV.cor | 6836.8 | 1595922.1 | 512552.4 | 75334 | 1.64041666667 | 13537 |
| 013464 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:33pm | Sensor | 1797-S0050-G-TJV.cor | 6837.1 | 1595922.1 | 512552.2 | 75336 | 1.64041666667 | 13464 |
| 014376 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:34pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595921.8 | 512550.9 | 75338 | 1.64041666667 | 14376 |
| 012054 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:35pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595921.0 | 512548.9 | 75340 | 1.64041666667 | 12054 |
| 013363 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:36pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595921.9 | 512546.9 | 75342 | 1.64041666667 | 13363 |
| 013241 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:37pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595923.8 | 512545.9 | 75344 | 1.64041666667 | 13241 |
| 012850 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:38pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595926.4 | 512546.2 | 75346 | 1.64041666667 | 12850 |
| 013772 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:39pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595929.3 | 512547.0 | 75348 | 1.64041666667 | 13772 |
| 013823 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:40pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595931.7 | 512548.0 | 75350 | 1.64041666667 | 13823 |
| 013565 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:41pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595933.9 | 512549.8 | 75352 | 1.64041666667 | 13565 |
| 014971 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595936.8 | 512551.8 | 75354 | 1.64041666667 | 14971 |
| 015892 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:43pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595939.5 | 512553.7 | 75356 | 1.64041666667 | 15892 |
| 016813 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595942.2 | 512555.7 | 75358 | 1.64041666667 | 16813 |
| 014283 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:45pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595944.8 | 512557.3 | 75360 | 1.64041666667 | 14283 |
| 014430 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595947.3 | 512559.1 | 75362 | 1.64041666667 | 14430 |
| 012877 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:47pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595950.2 | 512560.6 | 75364 | 1.64041666667 | 12877 |
| 012849 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:48pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595953.3 | 512562.0 | 75366 | 1.64041666667 | 12849 |
| 014372 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:49pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595956.0 | 512563.8 | 75368 | 1.64041666667 | 14372 |
| 013013 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:50pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595959.2 | 512565.5 | 75370 | 1.64041666667 | 13013 |
| 013453 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:51pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595961.8 | 512567.2 | 75372 | 1.64041666667 | 13453 |
| 013983 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:52pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595964.4 | 512569.2 | 75374 | 1.64041666667 | 13983 |
| 012795 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:53pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595966.9 | 512570.5 | 75376 | 1.64041666667 | 12795 |
| 013788 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:54pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595970.1 | 512572.3 | 75378 | 1.64041666667 | 13788 |
| 015357 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:55pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595972.5 | 512573.8 | 75380 | 1.64041666667 | 15357 |
| 016379 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:56pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595975.6 | 512575.5 | 75382 | 1.64041666667 | 16379 |
| 015315 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:57pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595978.2 | 512576.9 | 75384 | 1.64041666667 | 15315 |
| 014838 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:58pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595981.5 | 512578.6 | 75386 | 1.64041666667 | 14838 |
| 016039 | 0 | GeoXH 6000 | 08/19/2015 | 04:22:59pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595984.0 | 512579.6 | 75388 | 1.64041666667 | 16039 |
| 014059 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595986.5 | 512581.2 | 75390 | 1.64041666667 | 14059 |
| 016565 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:01pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595989.5 | 512582.8 | 75392 | 1.64041666667 | 16565 |
| 013861 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595992.7 | 512584.2 | 75394 | 1.64041666667 | 13861 |
| 015255 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:03pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595995.0 | 512585.2 | 75396 | 1.64041666667 | 15255 |
| 014673 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595997.9 | 512586.1 | 75398 | 1.64041666667 | 14673 |
| 016388 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:05pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596000.8 | 512587.7 | 75400 | 1.64041666667 | 16388 |
| 016277 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596003.7 | 512589.2 | 75402 | 1.64041666667 | 16277 |
| 013969 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:07pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596006.4 | 512590.3 | 75404 | 1.64041666667 | 13969 |
| 014652 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596009.4 | 512591.8 | 75406 | 1.64041666667 | 14652 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014313 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:09pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596012.3 | 512592.9 | 75408 | 1.64041666667 | 14313 |
| 014948 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596014.6 | 512594.0 | 75410 | 1.64041666667 | 14948 |
| 016534 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:11pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596016.5 | 512595.6 | 75412 | 1.64041666667 | 16534 |
| 015011 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596019.6 | 512596.3 | 75414 | 1.64041666667 | 15011 |
| 014163 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:13pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596021.7 | 512596.8 | 75416 | 1.64041666667 | 14163 |
| 015810 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:14pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596021.2 | 512596.2 | 75418 | 1.64041666667 | 15810 |
| 016432 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:15pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596019.6 | 512596.0 | 75420 | 1.64041666667 | 16432 |
| 016648 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596017.8 | 512594.7 | 75422 | 1.64041666667 | 16648 |
| 014242 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596017.0 | 512594.5 | 75424 | 1.64041666667 | 14242 |
| 014900 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:18pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596017.0 | 512595.5 | 75426 | 1.64041666667 | 14900 |
| 015365 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:19pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596016.6 | 512597.9 | 75428 | 1.64041666667 | 15365 |
| 015511 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:20pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596017.6 | 512599.8 | 75430 | 1.64041666667 | 15511 |
| 014857 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:21pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596017.4 | 512600.6 | 75432 | 1.64041666667 | 14857 |
| 018954 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596017.6 | 512602.4 | 75434 | 1.64041666667 | 18954 |
| 016678 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:23pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596018.6 | 512605.1 | 75436 | 1.64041666667 | 16678 |
| 017069 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:24pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596020.0 | 512607.2 | 75438 | 1.64041666667 | 17069 |
| 016087 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:25pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596019.9 | 512606.5 | 75440 | 1.64041666667 | 16087 |
| 014791 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:26pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596019.5 | 512604.2 | 75442 | 1.64041666667 | 14791 |
| 015187 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:27pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596017.9 | 512602.2 | 75444 | 1.64041666667 | 15187 |
| 015197 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:28pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596016.3 | 512600.3 | 75446 | 1.64041666667 | 15197 |
| 014689 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:29pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596014.5 | 512598.2 | 75448 | 1.64041666667 | 14689 |
| 014412 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:30pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596012.0 | 512596.4 | 75450 | 1.64041666667 | 14412 |
| 013983 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:31pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596009.4 | 512594.7 | 75452 | 1.64041666667 | 13983 |
| 013875 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:32pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596006.4 | 512593.6 | 75454 | 1.64041666667 | 13875 |
| 014358 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:33pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596003.3 | 512592.8 | 75456 | 1.64041666667 | 14358 |
| 013219 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:34pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596000.3 | 512591.3 | 75458 | 1.64041666667 | 13219 |
| 014915 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:35pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595997.6 | 512590.1 | 75460 | 1.64041666667 | 14915 |
| 014468 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:36pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595995.1 | 512588.3 | 75462 | 1.64041666667 | 14468 |
| 013727 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:37pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595992.4 | 512586.5 | 75464 | 1.64041666667 | 13727 |
| 015521 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:38pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595989.8 | 512585.6 | 75466 | 1.64041666667 | 15521 |
| 013000 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:39pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595987.0 | 512584.1 | 75468 | 1.64041666667 | 13000 |
| 014950 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:40pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595983.8 | 512582.7 | 75470 | 1.64041666667 | 14950 |
| 013277 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:41pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595980.8 | 512581.5 | 75472 | 1.64041666667 | 13277 |
| 013159 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:42pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595977.8 | 512580.1 | 75474 | 1.64041666667 | 13159 |
| 015199 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:43pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595975.4 | 512579.1 | 75476 | 1.64041666667 | 15199 |
| 016700 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:44pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595972.8 | 512577.3 | 75478 | 1.64041666667 | 16700 |
| 014765 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:45pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595970.6 | 512575.8 | 75480 | 1.64041666667 | 14765 |
| 015481 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:46pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595967.7 | 512574.9 | 75482 | 1.64041666667 | 15481 |
| 014700 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:47pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595965.3 | 512573.5 | 75484 | 1.64041666667 | 14700 |
| 015315 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:48pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595962.6 | 512572.4 | 75486 | 1.64041666667 | 15315 |
| 015918 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:49pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595959.9 | 512571.0 | 75488 | 1.64041666667 | 15918 |
| 014299 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:50pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595957.1 | 512569.3 | 75490 | 1.64041666667 | 14299 |
| 015815 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:51pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595954.6 | 512568.3 | 75492 | 1.64041666667 | 15815 |
| 014513 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:52pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595952.1 | 512566.6 | 75494 | 1.64041666667 | 14513 |
| 015718 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:53pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595949.2 | 512565.2 | 75496 | 1.64041666667 | 15718 |
| 014369 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:54pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595945.9 | 512563.8 | 75498 | 1.64041666667 | 14369 |
| 013882 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:55pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595943.5 | 512562.4 | 75500 | 1.64041666667 | 13882 |
| 014480 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:56pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595940.7 | 512561.2 | 75502 | 1.64041666667 | 14480 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013790 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:57pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595938.0 | 512559.8 | 75504 | 1.64041666667 | 13790 |
| 013017 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:58pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595934.8 | 512558.4 | 75506 | 1.64041666667 | 13017 |
| 014264 | 0 | GeoXH 6000 | 08/19/2015 | 04:23:59pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595932.4 | 512557.6 | 75508 | 1.64041666667 | 14264 |
| 013946 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:00pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595929.5 | 512555.9 | 75510 | 1.64041666667 | 13946 |
| 012396 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:01pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595926.9 | 512554.0 | 75512 | 1.64041666667 | 12396 |
| 013209 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:02pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595924.3 | 512552.4 | 75514 | 1.64041666667 | 13209 |
| 013742 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:03pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595923.4 | 512551.2 | 75516 | 1.64041666667 | 13742 |
| 012315 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:04pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595923.4 | 512551.1 | 75518 | 1.64041666667 | 12315 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:05pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595923.5 | 512551.0 | 75520 | 1.64041666667 | 14538 |
| 012574 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:06pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595923.3 | 512551.1 | 75522 | 1.64041666667 | 12574 |
| 014123 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:07pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595922.6 | 512551.6 | 75524 | 1.64041666667 | 14123 |
| 014751 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:08pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595922.4 | 512551.7 | 75526 | 1.64041666667 | 14751 |
| 013167 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:09pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595923.0 | 512551.6 | 75528 | 1.64041666667 | 13167 |
| 011632 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:10pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595923.0 | 512553.2 | 75530 | 1.64041666667 | 11632 |
| 012328 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:11pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595922.3 | 512555.4 | 75532 | 1.64041666667 | 12328 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:12pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595922.7 | 512557.6 | 75534 | 1.64041666667 | 12742 |
| 013445 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:13pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595922.5 | 512558.2 | 75536 | 1.64041666667 | 13445 |
| 014071 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:14pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595921.9 | 512560.0 | 75538 | 1.64041666667 | 14071 |
| 012757 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:15pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595921.5 | 512562.7 | 75540 | 1.64041666667 | 12757 |
| 014649 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:16pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595921.1 | 512565.0 | 75542 | 1.64041666667 | 14649 |
| 013502 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:17pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595921.0 | 512565.8 | 75544 | 1.64041666667 | 13502 |
| 015705 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:18pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595921.1 | 512566.0 | 75546 | 1.64041666667 | 15705 |
| 013616 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:19pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595921.1 | 512565.5 | 75548 | 1.64041666667 | 13616 |
| 013064 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:20pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595921.0 | 512563.0 | 75550 | 1.64041666667 | 13064 |
| 014516 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:21pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595920.1 | 512561.5 | 75552 | 1.64041666667 | 14516 |
| 012029 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:22pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595920.8 | 512559.4 | 75554 | 1.64041666667 | 12029 |
| 013237 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:23pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595922.2 | 512558.7 | 75556 | 1.64041666667 | 13237 |
| 013929 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:24pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595925.2 | 512559.3 | 75558 | 1.64041666667 | 13929 |
| 012872 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:25pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595927.6 | 512561.0 | 75560 | 1.64041666667 | 12872 |
| 014048 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:26pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595930.3 | 512562.7 | 75562 | 1.64041666667 | 14048 |
| 013472 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:27pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595932.8 | 512564.0 | 75564 | 1.64041666667 | 13472 |
| 013838 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:28pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595935.9 | 512565.7 | 75566 | 1.64041666667 | 13838 |
| 014439 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:29pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595938.8 | 512566.7 | 75568 | 1.64041666667 | 14439 |
| 013630 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:30pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595942.2 | 512567.8 | 75570 | 1.64041666667 | 13630 |
| 014897 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:31pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595944.9 | 512569.2 | 75572 | 1.64041666667 | 14897 |
| 013864 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:32pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595947.8 | 512570.3 | 75574 | 1.64041666667 | 13864 |
| 015466 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:33pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595950.7 | 512571.7 | 75576 | 1.64041666667 | 15466 |
| 015086 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:34pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595953.7 | 512573.4 | 75578 | 1.64041666667 | 15086 |
| 014751 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:35pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595956.2 | 512574.2 | 75580 | 1.64041666667 | 14751 |
| 013978 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:36pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595959.4 | 512576.0 | 75582 | 1.64041666667 | 13978 |
| 016304 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:37pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595962.4 | 512577.7 | 75584 | 1.64041666667 | 16304 |
| 014456 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:38pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595965.4 | 512578.9 | 75586 | 1.64041666667 | 14456 |
| 014684 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:39pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595968.1 | 512580.8 | 75588 | 1.64041666667 | 14684 |
| 015701 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:40pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595970.9 | 512582.8 | 75590 | 1.64041666667 | 15701 |
| 014995 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:41pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595973.6 | 512584.2 | 75592 | 1.64041666667 | 14995 |
| 014278 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:42pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595976.5 | 512586.0 | 75594 | 1.64041666667 | 14278 |
| 013319 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:43pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595979.3 | 512587.4 | 75596 | 1.64041666667 | 13319 |
| 012990 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:44pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595982.3 | 512588.5 | 75598 | 1.64041666667 | 12990 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014317 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:45pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.9 | 512590.3 | 75600 | 1.64041666667 | 14317 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:46pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595987.9 | 512591.9 | 75602 | 1.64041666667 | 14049 |
| 012932 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:47pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595990.6 | 512593.4 | 75604 | 1.64041666667 | 12932 |
| 013793 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:48pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595993.1 | 512595.1 | 75606 | 1.64041666667 | 13793 |
| 015058 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:49pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595996.1 | 512596.3 | 75608 | 1.64041666667 | 15058 |
| 015284 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595999.2 | 512597.9 | 75610 | 1.64041666667 | 15284 |
| 014501 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:51pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596001.6 | 512599.3 | 75612 | 1.64041666667 | 14501 |
| 013495 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596004.8 | 512600.4 | 75614 | 1.64041666667 | 13495 |
| 014263 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:53pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596007.7 | 512601.8 | 75616 | 1.64041666667 | 14263 |
| 013976 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:54pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596010.3 | 512603.3 | 75618 | 1.64041666667 | 13976 |
| 013708 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:55pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596012.4 | 512604.0 | 75620 | 1.64041666667 | 13708 |
| 015873 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:56pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596015.4 | 512605.5 | 75622 | 1.64041666667 | 15873 |
| 015518 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:57pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596018.3 | 512606.8 | 75624 | 1.64041666667 | 15518 |
| 015549 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596020.4 | 512607.7 | 75626 | 1.64041666667 | 15549 |
| 014687 | 0 | GeoXH 6000 | 08/19/2015 | 04:24:59pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596019.7 | 512607.9 | 75628 | 1.64041666667 | 14687 |
| 013781 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596018.9 | 512610.1 | 75630 | 1.64041666667 | 13781 |
| 014365 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:01pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596018.6 | 512611.5 | 75632 | 1.64041666667 | 14365 |
| 016671 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596018.6 | 512612.4 | 75634 | 1.64041666667 | 16671 |
| 014967 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:03pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596019.1 | 512614.3 | 75636 | 1.64041666667 | 14967 |
| 014122 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1596019.2 | 512617.8 | 75638 | 1.64041666667 | 14122 |
| 014930 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:05pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1596019.3 | 512619.0 | 75640 | 1.64041666667 | 14930 |
| 014292 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596019.4 | 512616.4 | 75642 | 1.64041666667 | 14292 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:07pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596018.4 | 512614.4 | 75644 | 1.64041666667 | 13593 |
| 014528 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596017.4 | 512612.1 | 75646 | 1.64041666667 | 14528 |
| 016352 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:09pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596015.2 | 512610.1 | 75648 | 1.64041666667 | 16352 |
| 013448 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596012.4 | 512608.9 | 75650 | 1.64041666667 | 13448 |
| 013712 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:11pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596010.0 | 512607.4 | 75652 | 1.64041666667 | 13712 |
| 014168 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596006.9 | 512605.7 | 75654 | 1.64041666667 | 14168 |
| 015572 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:13pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596004.2 | 512605.0 | 75656 | 1.64041666667 | 15572 |
| 014273 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596001.2 | 512603.5 | 75658 | 1.64041666667 | 14273 |
| 013438 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:15pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595998.8 | 512602.7 | 75660 | 1.64041666667 | 13438 |
| 012839 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595995.5 | 512601.2 | 75662 | 1.64041666667 | 12839 |
| 014310 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595993.1 | 512599.9 | 75664 | 1.64041666667 | 14310 |
| 012757 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595989.8 | 512598.8 | 75666 | 1.64041666667 | 12757 |
| 014889 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:19pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595987.5 | 512597.1 | 75668 | 1.64041666667 | 14889 |
| 014792 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:20pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.7 | 512595.1 | 75670 | 1.64041666667 | 14792 |
| 014438 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:21pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595981.8 | 512593.6 | 75672 | 1.64041666667 | 14438 |
| 014979 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:22pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595979.3 | 512592.4 | 75674 | 1.64041666667 | 14979 |
| 016285 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:23pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595976.6 | 512591.8 | 75676 | 1.64041666667 | 16285 |
| 016671 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:24pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595973.5 | 512590.8 | 75678 | 1.64041666667 | 16671 |
| 013797 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:25pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595971.2 | 512590.0 | 75680 | 1.64041666667 | 13797 |
| 014009 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:26pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595968.0 | 512589.4 | 75682 | 1.64041666667 | 14009 |
| 014512 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:27pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595965.4 | 512588.3 | 75684 | 1.64041666667 | 14512 |
| 015628 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:28pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595962.4 | 512587.1 | 75686 | 1.64041666667 | 15628 |
| 013687 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:29pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595959.6 | 512585.8 | 75688 | 1.64041666667 | 13687 |
| 014941 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:30pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595957.0 | 512584.0 | 75690 | 1.64041666667 | 14941 |
| 013215 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:31pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595954.6 | 512583.0 | 75692 | 1.64041666667 | 13215 |
| 013653 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:32pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595951.5 | 512581.3 | 75694 | 1.64041666667 | 13653 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013013 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:33pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595949.0 | 512579.6 | 75696 | 1.64041666667 | 13013 |
| 014713 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:34pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595946.0 | 512578.6 | 75698 | 1.64041666667 | 14713 |
| 013938 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:35pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595943.3 | 512577.2 | 75700 | 1.64041666667 | 13938 |
| 014824 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:36pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595940.4 | 512575.5 | 75702 | 1.64041666667 | 14824 |
| 013546 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:37pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595937.6 | 512574.7 | 75704 | 1.64041666667 | 13546 |
| 014216 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:38pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595934.9 | 512573.2 | 75706 | 1.64041666667 | 14216 |
| 014264 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:39pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595932.3 | 512572.1 | 75708 | 1.64041666667 | 14264 |
| 014696 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:40pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595929.2 | 512570.1 | 75710 | 1.64041666667 | 14696 |
| 014294 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:41pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595926.8 | 512568.5 | 75712 | 1.64041666667 | 14294 |
| 013353 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595924.1 | 512567.3 | 75714 | 1.64041666667 | 13353 |
| 013058 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:43pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595922.8 | 512566.3 | 75716 | 1.64041666667 | 13058 |
| 012744 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595922.1 | 512566.0 | 75718 | 1.64041666667 | 12744 |
| 012696 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:45pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595923.1 | 512566.1 | 75720 | 1.64041666667 | 12696 |
| 012984 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595922.0 | 512568.1 | 75722 | 1.64041666667 | 12984 |
| 012696 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:47pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595920.3 | 512570.6 | 75724 | 1.64041666667 | 12696 |
| 013824 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:48pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595919.4 | 512571.8 | 75726 | 1.64041666667 | 13824 |
| 014076 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:49pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595919.1 | 512572.6 | 75728 | 1.64041666667 | 14076 |
| 014109 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:50pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595918.9 | 512575.2 | 75730 | 1.64041666667 | 14109 |
| 014597 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:51pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595917.6 | 512577.2 | 75732 | 1.64041666667 | 14597 |
| 013939 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:52pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595916.1 | 512579.0 | 75734 | 1.64041666667 | 13939 |
| 014764 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:53pm | Sensor | 1797-S0050-G-TJV.cor | 6837.5 | 1595915.9 | 512579.1 | 75736 | 1.64041666667 | 14764 |
| 014911 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:54pm | Sensor | 1797-S0050-G-TJV.cor | 6837.3 | 1595915.8 | 512579.3 | 75738 | 1.64041666667 | 14911 |
| 013687 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:55pm | Sensor | 1797-S0050-G-TJV.cor | 6837.4 | 1595915.9 | 512579.2 | 75740 | 1.64041666667 | 13687 |
| 014252 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:56pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595917.3 | 512577.8 | 75742 | 1.64041666667 | 14252 |
| 013223 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:57pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595917.0 | 512577.2 | 75744 | 1.64041666667 | 13223 |
| 015185 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:58pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595917.8 | 512574.8 | 75746 | 1.64041666667 | 15185 |
| 013426 | 0 | GeoXH 6000 | 08/19/2015 | 04:25:59pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595918.9 | 512572.7 | 75748 | 1.64041666667 | 13426 |
| 014516 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:00pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595920.5 | 512572.6 | 75750 | 1.64041666667 | 14516 |
| 013319 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:01pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595923.1 | 512573.2 | 75752 | 1.64041666667 | 13319 |
| 014670 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:02pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595926.5 | 512574.5 | 75754 | 1.64041666667 | 14670 |
| 013177 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:03pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595928.9 | 512575.7 | 75756 | 1.64041666667 | 13177 |
| 013044 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:04pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595932.2 | 512577.0 | 75758 | 1.64041666667 | 13044 |
| 014211 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:05pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595935.3 | 512578.8 | 75760 | 1.64041666667 | 14211 |
| 013602 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:06pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595938.3 | 512580.5 | 75762 | 1.64041666667 | 13602 |
| 013930 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:07pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595940.9 | 512581.3 | 75764 | 1.64041666667 | 13930 |
| 016052 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:08pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595944.3 | 512582.8 | 75766 | 1.64041666667 | 16052 |
| 013583 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:09pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595947.4 | 512584.0 | 75768 | 1.64041666667 | 13583 |
| 014525 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:10pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595950.1 | 512584.8 | 75770 | 1.64041666667 | 14525 |
| 013111 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:11pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595952.4 | 512586.2 | 75772 | 1.64041666667 | 13111 |
| 013987 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:12pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595955.5 | 512588.3 | 75774 | 1.64041666667 | 13987 |
| 014327 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:13pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595958.3 | 512589.5 | 75776 | 1.64041666667 | 14327 |
| 015761 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595961.3 | 512591.1 | 75778 | 1.64041666667 | 15761 |
| 012370 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:15pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595965.0 | 512592.6 | 75780 | 1.64041666667 | 12370 |
| 014042 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:16pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595968.3 | 512593.9 | 75782 | 1.64041666667 | 14042 |
| 013590 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:17pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595970.6 | 512595.2 | 75784 | 1.64041666667 | 13590 |
| 013207 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:18pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595973.8 | 512596.5 | 75786 | 1.64041666667 | 13207 |
| 014792 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:19pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595976.7 | 512597.9 | 75788 | 1.64041666667 | 14792 |
| 015638 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595979.4 | 512599.4 | 75790 | 1.64041666667 | 15638 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013449 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:21pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595981.9 | 512600.2 | 75792 | 1.64041666667 | 13449 |
| 014792 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595985.3 | 512601.9 | 75794 | 1.64041666667 | 14792 |
| 013568 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:23pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595988.3 | 512603.6 | 75796 | 1.64041666667 | 13568 |
| 014312 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:24pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595991.6 | 512604.9 | 75798 | 1.64041666667 | 14312 |
| 017168 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:25pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595994.0 | 512606.6 | 75800 | 1.64041666667 | 17168 |
| 014972 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:26pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595997.3 | 512608.4 | 75802 | 1.64041666667 | 14972 |
| 013583 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:27pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1595999.9 | 512609.2 | 75804 | 1.64041666667 | 13583 |
| 015845 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:28pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596003.2 | 512611.1 | 75806 | 1.64041666667 | 15845 |
| 015151 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:29pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596006.2 | 512612.6 | 75808 | 1.64041666667 | 15151 |
| 014197 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:30pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596009.5 | 512613.9 | 75810 | 1.64041666667 | 14197 |
| 013479 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:31pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596012.1 | 512615.6 | 75812 | 1.64041666667 | 13479 |
| 013210 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:32pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596015.3 | 512617.4 | 75814 | 1.64041666667 | 13210 |
| 016622 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:33pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596017.5 | 512618.5 | 75816 | 1.64041666667 | 16622 |
| 013275 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:34pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596019.9 | 512620.5 | 75818 | 1.64041666667 | 13275 |
| 014298 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:35pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596022.6 | 512621.5 | 75820 | 1.64041666667 | 14298 |
| 015424 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:36pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596026.1 | 512623.5 | 75822 | 1.64041666667 | 15424 |
| 013996 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:37pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596028.3 | 512625.3 | 75824 | 1.64041666667 | 13996 |
| 012889 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:38pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596031.2 | 512626.9 | 75826 | 1.64041666667 | 12889 |
| 013332 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:39pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596033.7 | 512628.3 | 75828 | 1.64041666667 | 13332 |
| 013443 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:40pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596036.6 | 512630.0 | 75830 | 1.64041666667 | 13443 |
| 013230 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:41pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596038.6 | 512630.9 | 75832 | 1.64041666667 | 13230 |
| 014797 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:42pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596041.1 | 512632.5 | 75834 | 1.64041666667 | 14797 |
| 012999 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:43pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596043.5 | 512633.2 | 75836 | 1.64041666667 | 12999 |
| 012790 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:44pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596045.5 | 512634.6 | 75838 | 1.64041666667 | 12790 |
| 012497 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:45pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596045.9 | 512634.8 | 75840 | 1.64041666667 | 12497 |
| 012484 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:46pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596045.9 | 512634.8 | 75842 | 1.64041666667 | 12484 |
| 012451 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:47pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596046.7 | 512635.1 | 75844 | 1.64041666667 | 12451 |
| 014572 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:48pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596047.1 | 512635.9 | 75846 | 1.64041666667 | 14572 |
| 013213 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:49pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596047.2 | 512635.1 | 75848 | 1.64041666667 | 13213 |
| 013323 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:50pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596048.2 | 512632.2 | 75850 | 1.64041666667 | 13323 |
| 014670 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:51pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596048.8 | 512628.9 | 75852 | 1.64041666667 | 14670 |
| 016207 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:52pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596050.2 | 512626.0 | 75854 | 1.64041666667 | 16207 |
| 015572 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:53pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596050.9 | 512623.0 | 75856 | 1.64041666667 | 15572 |
| 015473 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:54pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596052.1 | 512619.0 | 75858 | 1.64041666667 | 15473 |
| 014338 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:55pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596053.1 | 512616.1 | 75860 | 1.64041666667 | 14338 |
| 014354 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:56pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596053.8 | 512611.9 | 75862 | 1.64041666667 | 14354 |
| 015108 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:57pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596054.6 | 512608.4 | 75864 | 1.64041666667 | 15108 |
| 012987 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:58pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596055.0 | 512605.3 | 75866 | 1.64041666667 | 12987 |
| 014466 | 0 | GeoXH 6000 | 08/19/2015 | 04:26:59pm | Sensor | 1797-S0050-G-TJV.cor | 6841.5 | 1596055.0 | 512602.5 | 75868 | 1.64041666667 | 14466 |
| 014656 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:00pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596055.6 | 512599.2 | 75870 | 1.64041666667 | 14656 |
| 014734 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:01pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596055.8 | 512596.3 | 75872 | 1.64041666667 | 14734 |
| 014333 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:02pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596055.3 | 512592.8 | 75874 | 1.64041666667 | 14333 |
| 015583 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:03pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596055.2 | 512589.9 | 75876 | 1.64041666667 | 15583 |
| 015476 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596054.8 | 512585.9 | 75878 | 1.64041666667 | 15476 |
| 016259 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:05pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596053.8 | 512583.0 | 75880 | 1.64041666667 | 16259 |
| 014444 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596053.1 | 512580.1 | 75882 | 1.64041666667 | 14444 |
| 014861 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:07pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596051.8 | 512577.7 | 75884 | 1.64041666667 | 14861 |
| 015145 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596050.1 | 512574.1 | 75886 | 1.64041666667 | 15145 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015606 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:09pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596049.0 | 512571.4 | 75888 | 1.64041666667 | 15606 |
| 015211 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596047.1 | 512568.8 | 75890 | 1.64041666667 | 15211 |
| 014392 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:11pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596046.1 | 512565.8 | 75892 | 1.64041666667 | 14392 |
| 014398 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596045.2 | 512562.8 | 75894 | 1.64041666667 | 14398 |
| 014579 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:13pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596043.7 | 512560.6 | 75896 | 1.64041666667 | 14579 |
| 014655 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596041.6 | 512558.0 | 75898 | 1.64041666667 | 14655 |
| 016773 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:15pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596039.3 | 512557.5 | 75900 | 1.64041666667 | 16773 |
| 015233 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596037.9 | 512559.7 | 75902 | 1.64041666667 | 15233 |
| 014668 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596037.8 | 512561.9 | 75904 | 1.64041666667 | 14668 |
| 015157 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596039.2 | 512565.2 | 75906 | 1.64041666667 | 15157 |
| 015669 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:19pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596040.5 | 512568.0 | 75908 | 1.64041666667 | 15669 |
| 015527 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596041.7 | 512570.7 | 75910 | 1.64041666667 | 15527 |
| 016061 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:21pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596043.6 | 512572.8 | 75912 | 1.64041666667 | 16061 |
| 015685 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596045.6 | 512575.7 | 75914 | 1.64041666667 | 15685 |
| 015291 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:23pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596047.0 | 512577.9 | 75916 | 1.64041666667 | 15291 |
| 015492 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:24pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596049.1 | 512580.5 | 75918 | 1.64041666667 | 15492 |
| 015033 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:25pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596050.0 | 512583.3 | 75920 | 1.64041666667 | 15033 |
| 015158 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:26pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596050.7 | 512586.8 | 75922 | 1.64041666667 | 15158 |
| 016389 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:27pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596051.6 | 512589.0 | 75924 | 1.64041666667 | 16389 |
| 014927 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:28pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596051.9 | 512591.9 | 75926 | 1.64041666667 | 14927 |
| 013241 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:29pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596051.8 | 512595.0 | 75928 | 1.64041666667 | 13241 |
| 015340 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:30pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596051.0 | 512597.9 | 75930 | 1.64041666667 | 15340 |
| 015595 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:31pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596049.3 | 512600.5 | 75932 | 1.64041666667 | 15595 |
| 013648 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:32pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596048.2 | 512603.7 | 75934 | 1.64041666667 | 13648 |
| 012952 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:33pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596047.0 | 512606.8 | 75936 | 1.64041666667 | 12952 |
| 014458 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:34pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596045.6 | 512609.8 | 75938 | 1.64041666667 | 14458 |
| 014744 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:35pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596044.8 | 512612.5 | 75940 | 1.64041666667 | 14744 |
| 014246 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:36pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596043.2 | 512615.4 | 75942 | 1.64041666667 | 14246 |
| 014391 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:37pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596041.5 | 512618.1 | 75944 | 1.64041666667 | 14391 |
| 014127 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:38pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596040.3 | 512620.4 | 75946 | 1.64041666667 | 14127 |
| 013582 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:39pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596038.4 | 512621.0 | 75948 | 1.64041666667 | 13582 |
| 014855 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:40pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596036.6 | 512620.1 | 75950 | 1.64041666667 | 14855 |
| 015053 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:41pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596035.7 | 512617.8 | 75952 | 1.64041666667 | 15053 |
| 013483 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:42pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596035.8 | 512614.4 | 75954 | 1.64041666667 | 13483 |
| 014411 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:43pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596036.5 | 512611.6 | 75956 | 1.64041666667 | 14411 |
| 015152 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:44pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596036.5 | 512608.5 | 75958 | 1.64041666667 | 15152 |
| 014258 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:45pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596036.5 | 512606.0 | 75960 | 1.64041666667 | 14258 |
| 015354 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:46pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596036.2 | 512602.2 | 75962 | 1.64041666667 | 15354 |
| 015958 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:47pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596036.1 | 512599.1 | 75964 | 1.64041666667 | 15958 |
| 016169 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:48pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596036.2 | 512595.9 | 75966 | 1.64041666667 | 16169 |
| 014902 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:48pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596035.7 | 512593.5 | 75967 | 1.64041666667 | 14902 |
| 016745 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596036.5 | 512589.7 | 75970 | 1.64041666667 | 16745 |
| 014206 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:51pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596037.5 | 512586.9 | 75972 | 1.64041666667 | 14206 |
| 014321 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:52pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596037.4 | 512583.8 | 75974 | 1.64041666667 | 14321 |
| 015040 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:53pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596038.1 | 512581.1 | 75976 | 1.64041666667 | 15040 |
| 015010 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:54pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596039.0 | 512577.4 | 75978 | 1.64041666667 | 15010 |
| 015932 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:55pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596039.2 | 512574.7 | 75980 | 1.64041666667 | 15932 |
| 013763 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:56pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596038.7 | 512571.3 | 75982 | 1.64041666667 | 13763 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014900 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:57pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596036.9 | 512569.9 | 75984 | 1.64041666667 | 14900 |
| 015155 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596033.4 | 512569.1 | 75986 | 1.64041666667 | 15155 |
| 016748 | 0 | GeoXH 6000 | 08/19/2015 | 04:27:59pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596030.5 | 512568.7 | 75988 | 1.64041666667 | 16748 |
| 014057 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596027.0 | 512569.0 | 75990 | 1.64041666667 | 14057 |
| 013864 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:01pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596024.4 | 512569.0 | 75992 | 1.64041666667 | 13864 |
| 014296 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596021.0 | 512570.0 | 75994 | 1.64041666667 | 14296 |
| 015514 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:03pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596019.1 | 512572.0 | 75996 | 1.64041666667 | 15514 |
| 016028 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596017.2 | 512574.6 | 75998 | 1.64041666667 | 16028 |
| 016427 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:05pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596016.7 | 512576.9 | 76000 | 1.64041666667 | 16427 |
| 015386 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596016.9 | 512580.6 | 76002 | 1.64041666667 | 15386 |
| 016206 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:07pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596016.9 | 512583.5 | 76004 | 1.64041666667 | 16206 |
| 017821 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596016.8 | 512587.0 | 76006 | 1.64041666667 | 17821 |
| 015855 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:09pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596017.1 | 512590.4 | 76008 | 1.64041666667 | 15855 |
| 016113 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596017.5 | 512593.7 | 76010 | 1.64041666667 | 16113 |
| 015008 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:11pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596018.1 | 512596.6 | 76012 | 1.64041666667 | 15008 |
| 014222 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596019.1 | 512599.9 | 76014 | 1.64041666667 | 14222 |
| 015675 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:13pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596019.3 | 512602.4 | 76016 | 1.64041666667 | 15675 |
| 015138 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596018.6 | 512605.7 | 76018 | 1.64041666667 | 15138 |
| 014524 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:15pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596018.0 | 512608.9 | 76020 | 1.64041666667 | 14524 |
| 013891 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596018.0 | 512612.6 | 76022 | 1.64041666667 | 13891 |
| 014842 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596018.3 | 512616.0 | 76024 | 1.64041666667 | 14842 |
| 013670 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596019.0 | 512618.4 | 76026 | 1.64041666667 | 13670 |
| 014247 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:19pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1596019.4 | 512619.6 | 76028 | 1.64041666667 | 14247 |
| 013282 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596019.2 | 512621.1 | 76030 | 1.64041666667 | 13282 |
| 014150 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:21pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596019.6 | 512623.3 | 76032 | 1.64041666667 | 14150 |
| 011157 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596019.5 | 512625.0 | 76034 | 1.64041666667 | 11157 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:23pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596019.6 | 512625.6 | 76036 | 1.64041666667 | 12539 |
| 013215 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:24pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596020.2 | 512627.3 | 76038 | 1.64041666667 | 13215 |
| 014043 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:25pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596020.5 | 512629.4 | 76040 | 1.64041666667 | 14043 |
| 011850 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:26pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596020.7 | 512631.3 | 76042 | 1.64041666667 | 11850 |
| 011452 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:27pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596021.0 | 512631.2 | 76044 | 1.64041666667 | 11452 |
| 012703 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:28pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596023.5 | 512630.1 | 76046 | 1.64041666667 | 12703 |
| 013436 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:29pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596027.2 | 512629.6 | 76048 | 1.64041666667 | 13436 |
| 012269 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:30pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596031.2 | 512629.6 | 76050 | 1.64041666667 | 12269 |
| 012457 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:31pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596034.5 | 512629.2 | 76052 | 1.64041666667 | 12457 |
| 013224 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:32pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596038.2 | 512628.8 | 76054 | 1.64041666667 | 13224 |
| 013626 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:33pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596041.8 | 512628.5 | 76056 | 1.64041666667 | 13626 |
| 014206 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:34pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596044.9 | 512628.0 | 76058 | 1.64041666667 | 14206 |
| 012971 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:35pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596048.2 | 512627.3 | 76060 | 1.64041666667 | 12971 |
| 013443 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:36pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596051.6 | 512626.7 | 76062 | 1.64041666667 | 13443 |
| 013590 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:37pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596054.9 | 512626.1 | 76064 | 1.64041666667 | 13590 |
| 015277 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:38pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596058.2 | 512625.7 | 76066 | 1.64041666667 | 15277 |
| 013539 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:39pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596060.2 | 512625.7 | 76068 | 1.64041666667 | 13539 |
| 013195 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:40pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1596060.6 | 512625.7 | 76070 | 1.64041666667 | 13195 |
| 013258 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:41pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1596060.6 | 512625.8 | 76072 | 1.64041666667 | 13258 |
| 014474 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:42pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596059.6 | 512625.2 | 76074 | 1.64041666667 | 14474 |
| 014358 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:43pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596058.0 | 512624.2 | 76076 | 1.64041666667 | 14358 |
| 015199 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:44pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596055.4 | 512624.9 | 76078 | 1.64041666667 | 15199 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013729 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:45pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596053.6 | 512624.6 | 76080 | 1.64041666667 | 13729 |
| 013722 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:46pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596051.9 | 512623.0 | 76082 | 1.64041666667 | 13722 |
| 014380 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:47pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596048.9 | 512621.9 | 76084 | 1.64041666667 | 14380 |
| 014305 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:48pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596045.9 | 512621.5 | 76086 | 1.64041666667 | 14305 |
| 013176 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:49pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596042.6 | 512621.1 | 76088 | 1.64041666667 | 13176 |
| 014694 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596039.1 | 512621.3 | 76090 | 1.64041666667 | 14694 |
| 013783 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:51pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596035.9 | 512621.7 | 76092 | 1.64041666667 | 13783 |
| 013286 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596032.3 | 512621.5 | 76094 | 1.64041666667 | 13286 |
| 016071 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:53pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596029.2 | 512621.6 | 76096 | 1.64041666667 | 16071 |
| 015987 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:54pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596025.6 | 512621.6 | 76098 | 1.64041666667 | 15987 |
| 014107 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:55pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596023.2 | 512621.2 | 76100 | 1.64041666667 | 14107 |
| 013696 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:56pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596020.5 | 512620.6 | 76102 | 1.64041666667 | 13696 |
| 013624 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:57pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596019.1 | 512619.4 | 76104 | 1.64041666667 | 13624 |
| 014056 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596017.3 | 512618.6 | 76106 | 1.64041666667 | 14056 |
| 012904 | 0 | GeoXH 6000 | 08/19/2015 | 04:28:59pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596016.5 | 512618.6 | 76108 | 1.64041666667 | 12904 |
| 013726 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596016.0 | 512619.9 | 76110 | 1.64041666667 | 13726 |
| 015101 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:01pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596016.1 | 512621.6 | 76112 | 1.64041666667 | 15101 |
| 012625 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596015.0 | 512623.0 | 76114 | 1.64041666667 | 12625 |
| 012306 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:03pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596013.2 | 512623.8 | 76116 | 1.64041666667 | 12306 |
| 012736 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596010.1 | 512623.3 | 76118 | 1.64041666667 | 12736 |
| 013174 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:05pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596007.3 | 512622.3 | 76120 | 1.64041666667 | 13174 |
| 012923 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596005.2 | 512621.5 | 76122 | 1.64041666667 | 12923 |
| 011661 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:07pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596005.1 | 512621.1 | 76124 | 1.64041666667 | 11661 |
| 013505 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596004.7 | 512620.6 | 76126 | 1.64041666667 | 13505 |
| 015166 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:09pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596003.6 | 512619.8 | 76128 | 1.64041666667 | 15166 |
| 013661 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596000.6 | 512618.5 | 76130 | 1.64041666667 | 13661 |
| 013255 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:11pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595998.9 | 512617.5 | 76132 | 1.64041666667 | 13255 |
| 013814 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595995.7 | 512616.6 | 76134 | 1.64041666667 | 13814 |
| 016623 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:13pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595992.6 | 512615.2 | 76136 | 1.64041666667 | 16623 |
| 014865 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595989.3 | 512613.9 | 76138 | 1.64041666667 | 14865 |
| 014152 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:15pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595987.0 | 512613.3 | 76140 | 1.64041666667 | 14152 |
| 014984 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595984.1 | 512611.5 | 76142 | 1.64041666667 | 14984 |
| 015416 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595981.2 | 512610.0 | 76144 | 1.64041666667 | 15416 |
| 015734 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595977.8 | 512608.7 | 76146 | 1.64041666667 | 15734 |
| 016473 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:19pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595975.3 | 512607.3 | 76148 | 1.64041666667 | 16473 |
| 014678 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:20pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595972.4 | 512606.1 | 76150 | 1.64041666667 | 14678 |
| 015279 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:21pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595969.5 | 512604.6 | 76152 | 1.64041666667 | 15279 |
| 015430 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:22pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595967.0 | 512603.0 | 76154 | 1.64041666667 | 15430 |
| 015407 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:23pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595964.2 | 512602.1 | 76156 | 1.64041666667 | 15407 |
| 014951 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:24pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595961.4 | 512600.7 | 76158 | 1.64041666667 | 14951 |
| 014358 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:25pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595958.4 | 512599.1 | 76160 | 1.64041666667 | 14358 |
| 014659 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:26pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595955.6 | 512598.1 | 76162 | 1.64041666667 | 14659 |
| 015214 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:27pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595953.2 | 512596.6 | 76164 | 1.64041666667 | 15214 |
| 014573 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:28pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595949.7 | 512594.6 | 76166 | 1.64041666667 | 14573 |
| 012943 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:29pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595947.2 | 512593.6 | 76168 | 1.64041666667 | 12943 |
| 014156 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:30pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595944.0 | 512591.7 | 76170 | 1.64041666667 | 14156 |
| 014939 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:31pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595941.5 | 512590.3 | 76172 | 1.64041666667 | 14939 |
| 014204 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:32pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595938.3 | 512589.0 | 76174 | 1.64041666667 | 14204 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012551 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:33pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595935.9 | 512587.6 | 76176 | 1.64041666667 | 12551 |
| 014237 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:34pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595932.5 | 512586.7 | 76178 | 1.64041666667 | 14237 |
| 014839 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:35pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595929.7 | 512586.0 | 76180 | 1.64041666667 | 14839 |
| 015949 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:36pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595927.1 | 512584.9 | 76182 | 1.64041666667 | 15949 |
| 014217 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:37pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595924.4 | 512584.1 | 76184 | 1.64041666667 | 14217 |
| 014534 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:38pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595921.8 | 512582.6 | 76186 | 1.64041666667 | 14534 |
| 014523 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:39pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595919.3 | 512581.1 | 76188 | 1.64041666667 | 14523 |
| 014160 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:40pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595916.5 | 512580.0 | 76190 | 1.64041666667 | 14160 |
| 014970 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:41pm | Sensor | 1797-S0050-G-TJV.cor | 6837.6 | 1595915.8 | 512579.5 | 76192 | 1.64041666667 | 14970 |
| 013432 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595917.0 | 512579.7 | 76194 | 1.64041666667 | 13432 |
| 014878 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:43pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595916.1 | 512581.2 | 76196 | 1.64041666667 | 14878 |
| 014729 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595914.3 | 512583.2 | 76198 | 1.64041666667 | 14729 |
| 014482 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:45pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595913.8 | 512584.7 | 76200 | 1.64041666667 | 14482 |
| 015080 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595913.2 | 512585.7 | 76202 | 1.64041666667 | 15080 |
| 014540 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:47pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595911.5 | 512587.7 | 76204 | 1.64041666667 | 14540 |
| 013535 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:48pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595910.0 | 512589.9 | 76206 | 1.64041666667 | 13535 |
| 015383 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:49pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595909.3 | 512591.6 | 76208 | 1.64041666667 | 15383 |
| 014706 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:50pm | Sensor | 1797-S0050-G-TJV.cor | 6837.5 | 1595909.2 | 512591.9 | 76210 | 1.64041666667 | 14706 |
| 015046 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:51pm | Sensor | 1797-S0050-G-TJV.cor | 6837.4 | 1595909.2 | 512592.0 | 76212 | 1.64041666667 | 15046 |
| 014141 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:52pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595909.4 | 512591.4 | 76214 | 1.64041666667 | 14141 |
| 014515 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:53pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595908.8 | 512589.6 | 76216 | 1.64041666667 | 14515 |
| 014939 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:54pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595909.0 | 512588.0 | 76218 | 1.64041666667 | 14939 |
| 014174 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:55pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595910.7 | 512587.2 | 76220 | 1.64041666667 | 14174 |
| 014673 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:56pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595912.7 | 512586.5 | 76222 | 1.64041666667 | 14673 |
| 015098 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:57pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595914.8 | 512586.7 | 76224 | 1.64041666667 | 15098 |
| 014184 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:58pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595917.6 | 512587.5 | 76226 | 1.64041666667 | 14184 |
| 015186 | 0 | GeoXH 6000 | 08/19/2015 | 04:29:59pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595920.1 | 512588.2 | 76228 | 1.64041666667 | 15186 |
| 014326 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:00pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595922.5 | 512589.8 | 76230 | 1.64041666667 | 14326 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:01pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595924.8 | 512590.7 | 76232 | 1.64041666667 | 13811 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:02pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595927.1 | 512592.1 | 76234 | 1.64041666667 | 13593 |
| 015488 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:03pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595930.2 | 512593.6 | 76236 | 1.64041666667 | 15488 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:04pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595933.2 | 512595.0 | 76238 | 1.64041666667 | 14132 |
| 014813 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:05pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595935.3 | 512596.4 | 76240 | 1.64041666667 | 14813 |
| 014923 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595937.9 | 512597.6 | 76242 | 1.64041666667 | 14923 |
| 014141 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:07pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595940.3 | 512599.3 | 76244 | 1.64041666667 | 14141 |
| 014905 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595942.8 | 512600.8 | 76246 | 1.64041666667 | 14905 |
| 014226 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:09pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595945.8 | 512602.2 | 76248 | 1.64041666667 | 14226 |
| 013786 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:10pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595948.1 | 512604.0 | 76250 | 1.64041666667 | 13786 |
| 014276 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:11pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595950.1 | 512604.9 | 76252 | 1.64041666667 | 14276 |
| 015389 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:12pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595952.6 | 512606.5 | 76254 | 1.64041666667 | 15389 |
| 014797 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:13pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595955.0 | 512607.7 | 76256 | 1.64041666667 | 14797 |
| 014289 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595956.8 | 512609.1 | 76258 | 1.64041666667 | 14289 |
| 015062 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:15pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595957.0 | 512609.5 | 76260 | 1.64041666667 | 15062 |
| 014235 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:16pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595956.9 | 512609.6 | 76262 | 1.64041666667 | 14235 |
| 015318 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:17pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595957.0 | 512609.7 | 76264 | 1.64041666667 | 15318 |
| 015049 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:18pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595958.1 | 512610.1 | 76266 | 1.64041666667 | 15049 |
| 013242 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:19pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595960.2 | 512611.2 | 76268 | 1.64041666667 | 13242 |
| 014560 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:20pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595962.8 | 512613.1 | 76270 | 1.64041666667 | 14560 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013810 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:21pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595964.4 | 512614.6 | 76272 | 1.64041666667 | 13810 |
| 013622 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595966.9 | 512616.1 | 76274 | 1.64041666667 | 13622 |
| 014715 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:23pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595968.7 | 512618.1 | 76276 | 1.64041666667 | 14715 |
| 013668 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:24pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595970.9 | 512619.5 | 76278 | 1.64041666667 | 13668 |
| 014967 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:25pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595972.4 | 512620.9 | 76280 | 1.64041666667 | 14967 |
| 014812 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:26pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595973.7 | 512621.8 | 76282 | 1.64041666667 | 14812 |
| 014503 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:27pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595974.0 | 512622.0 | 76284 | 1.64041666667 | 14503 |
| 013945 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:28pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595973.8 | 512622.0 | 76286 | 1.64041666667 | 13945 |
| 016116 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:29pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595973.6 | 512621.8 | 76288 | 1.64041666667 | 16116 |
| 015039 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:30pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595973.9 | 512622.5 | 76290 | 1.64041666667 | 15039 |
| 014409 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:31pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595974.4 | 512622.5 | 76292 | 1.64041666667 | 14409 |
| 015362 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:32pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595976.8 | 512622.1 | 76294 | 1.64041666667 | 15362 |
| 013830 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:33pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595979.1 | 512622.9 | 76296 | 1.64041666667 | 13830 |
| 012817 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:34pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595982.0 | 512623.6 | 76298 | 1.64041666667 | 12817 |
| 014514 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:35pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595984.5 | 512624.5 | 76300 | 1.64041666667 | 14514 |
| 012838 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:36pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595987.6 | 512625.8 | 76302 | 1.64041666667 | 12838 |
| 014159 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:37pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595990.3 | 512626.7 | 76304 | 1.64041666667 | 14159 |
| 014310 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:38pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1595992.3 | 512627.8 | 76306 | 1.64041666667 | 14310 |
| 013867 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:39pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595994.7 | 512628.1 | 76308 | 1.64041666667 | 13867 |
| 014416 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:40pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595997.0 | 512629.6 | 76310 | 1.64041666667 | 14416 |
| 013684 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:41pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595999.6 | 512630.5 | 76312 | 1.64041666667 | 13684 |
| 015781 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:42pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596002.2 | 512631.9 | 76314 | 1.64041666667 | 15781 |
| 015795 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:43pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596004.6 | 512633.4 | 76316 | 1.64041666667 | 15795 |
| 015648 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:44pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596007.6 | 512634.8 | 76318 | 1.64041666667 | 15648 |
| 015672 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:45pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596009.2 | 512636.6 | 76320 | 1.64041666667 | 15672 |
| 014808 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:46pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596012.0 | 512637.5 | 76322 | 1.64041666667 | 14808 |
| 012852 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:47pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596013.9 | 512638.9 | 76324 | 1.64041666667 | 12852 |
| 012303 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:48pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596015.9 | 512640.4 | 76326 | 1.64041666667 | 12303 |
| 012525 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:49pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596017.9 | 512642.4 | 76328 | 1.64041666667 | 12525 |
| 012491 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596020.4 | 512644.0 | 76330 | 1.64041666667 | 12491 |
| 012573 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:50pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596022.4 | 512644.5 | 76331 | 1.64041666667 | 12573 |
| 011993 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:52pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596024.4 | 512646.0 | 76334 | 1.64041666667 | 11993 |
| 011758 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:52pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596026.4 | 512647.0 | 76335 | 1.64041666667 | 11758 |
| 011789 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:54pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596025.8 | 512648.9 | 76338 | 1.64041666667 | 11789 |
| 011677 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:55pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596025.3 | 512648.7 | 76340 | 1.64041666667 | 11677 |
| 012039 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:56pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596025.6 | 512649.2 | 76342 | 1.64041666667 | 12039 |
| 013179 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:57pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596025.9 | 512649.1 | 76344 | 1.64041666667 | 13179 |
| 012415 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596025.7 | 512649.0 | 76346 | 1.64041666667 | 12415 |
| 012283 | 0 | GeoXH 6000 | 08/19/2015 | 04:30:59pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596026.2 | 512648.2 | 76348 | 1.64041666667 | 12283 |
| 013181 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596027.9 | 512645.5 | 76350 | 1.64041666667 | 13181 |
| 013495 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:00pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596030.0 | 512643.6 | 76351 | 1.64041666667 | 13495 |
| 013933 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:02pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596033.9 | 512642.1 | 76354 | 1.64041666667 | 13933 |
| 013173 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:02pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596036.8 | 512640.8 | 76355 | 1.64041666667 | 13173 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:04pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596040.7 | 512638.9 | 76358 | 1.64041666667 | 12743 |
| 012965 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:05pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596044.4 | 512636.8 | 76360 | 1.64041666667 | 12965 |
| 012751 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596047.6 | 512634.4 | 76362 | 1.64041666667 | 12751 |
| 015277 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:07pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596050.1 | 512632.5 | 76364 | 1.64041666667 | 15277 |
| 014739 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:08pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596053.4 | 512629.8 | 76366 | 1.64041666667 | 14739 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013525 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:09pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596055.7 | 512627.8 | 76368 | 1.64041666667 | 13525 |
| 013221 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:10pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596057.9 | 512626.3 | 76370 | 1.64041666667 | 13221 |
| 013145 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:11pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596059.1 | 512625.6 | 76372 | 1.64041666667 | 13145 |
| 014566 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:12pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596056.6 | 512626.1 | 76374 | 1.64041666667 | 14566 |
| 013871 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:13pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596055.5 | 512628.4 | 76376 | 1.64041666667 | 13871 |
| 012948 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:14pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596053.8 | 512631.0 | 76378 | 1.64041666667 | 12948 |
| 012597 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:15pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596050.6 | 512633.2 | 76380 | 1.64041666667 | 12597 |
| 012779 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:16pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596047.7 | 512635.6 | 76382 | 1.64041666667 | 12779 |
| 013395 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:17pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596045.2 | 512638.3 | 76384 | 1.64041666667 | 13395 |
| 014148 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:18pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596042.7 | 512640.6 | 76386 | 1.64041666667 | 14148 |
| 013887 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:19pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596040.4 | 512642.7 | 76388 | 1.64041666667 | 13887 |
| 012681 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:20pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596038.2 | 512644.9 | 76390 | 1.64041666667 | 12681 |
| 013100 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:20pm | Sensor | 1797-S0050-G-TJV.cor | 6841.5 | 1596036.8 | 512647.0 | 76391 | 1.64041666667 | 13100 |
| 012095 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:22pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596034.6 | 512650.2 | 76394 | 1.64041666667 | 12095 |
| 012473 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:23pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596033.0 | 512651.7 | 76396 | 1.64041666667 | 12473 |
| 012778 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:24pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596031.0 | 512653.4 | 76398 | 1.64041666667 | 12778 |
| 012704 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:24pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596028.9 | 512653.7 | 76399 | 1.64041666667 | 12704 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:26pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596026.6 | 512652.9 | 76402 | 1.64041666667 | 12626 |
| 013626 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:27pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596024.8 | 512652.3 | 76404 | 1.64041666667 | 13626 |
| 013846 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:28pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596024.9 | 512650.6 | 76406 | 1.64041666667 | 13846 |
| 012491 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:29pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596024.5 | 512650.6 | 76408 | 1.64041666667 | 12491 |
| 013233 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:30pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596024.3 | 512650.9 | 76410 | 1.64041666667 | 13233 |
| 011948 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:31pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596024.8 | 512650.3 | 76412 | 1.64041666667 | 11948 |
| 012647 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:32pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596024.8 | 512650.3 | 76414 | 1.64041666667 | 12647 |
| 011861 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:32pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596024.8 | 512650.2 | 76415 | 1.64041666667 | 11861 |
| 013435 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:34pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596024.3 | 512650.3 | 76418 | 1.64041666667 | 13435 |
| 011819 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:35pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596023.6 | 512651.2 | 76420 | 1.64041666667 | 11819 |
| 012464 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:36pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596021.8 | 512651.4 | 76422 | 1.64041666667 | 12464 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:36pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596021.5 | 512651.7 | 76423 | 1.64041666667 | 12056 |
| 013064 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:38pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596021.4 | 512653.0 | 76426 | 1.64041666667 | 13064 |
| 012266 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:39pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596020.0 | 512654.9 | 76428 | 1.64041666667 | 12266 |
| 011826 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:40pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596018.2 | 512658.2 | 76430 | 1.64041666667 | 11826 |
| 013306 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:40pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596017.7 | 512658.9 | 76431 | 1.64041666667 | 13306 |
| 013556 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:42pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1596017.7 | 512659.4 | 76434 | 1.64041666667 | 13556 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:42pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1596017.6 | 512659.6 | 76435 | 1.64041666667 | 12539 |
| 012075 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:44pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596018.8 | 512658.7 | 76438 | 1.64041666667 | 12075 |
| 011868 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:44pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596020.5 | 512658.2 | 76439 | 1.64041666667 | 11868 |
| 011937 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:46pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596020.4 | 512655.9 | 76442 | 1.64041666667 | 11937 |
| 013514 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:47pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596020.3 | 512653.3 | 76444 | 1.64041666667 | 13514 |
| 013218 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:48pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596018.3 | 512650.8 | 76446 | 1.64041666667 | 13218 |
| 013114 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:49pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596016.5 | 512649.6 | 76448 | 1.64041666667 | 13114 |
| 012668 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596014.0 | 512647.9 | 76450 | 1.64041666667 | 12668 |
| 011267 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:51pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596011.3 | 512646.8 | 76452 | 1.64041666667 | 11267 |
| 012146 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596008.6 | 512645.7 | 76454 | 1.64041666667 | 12146 |
| 013716 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596006.7 | 512644.5 | 76455 | 1.64041666667 | 13716 |
| 013899 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:54pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596003.7 | 512643.9 | 76458 | 1.64041666667 | 13899 |
| 012684 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:54pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596001.6 | 512642.7 | 76459 | 1.64041666667 | 12684 |
| 013491 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:56pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1595998.7 | 512641.3 | 76462 | 1.64041666667 | 13491 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013962 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:57pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1595996.8 | 512639.2 | 76464 | 1.64041666667 | 13962 |
| 012340 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1595994.3 | 512637.0 | 76466 | 1.64041666667 | 12340 |
| 011905 | 0 | GeoXH 6000 | 08/19/2015 | 04:31:59pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595991.9 | 512635.7 | 76468 | 1.64041666667 | 11905 |
| 012636 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1595989.5 | 512633.6 | 76470 | 1.64041666667 | 12636 |
| 012429 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1595987.4 | 512632.6 | 76471 | 1.64041666667 | 12429 |
| 013487 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595984.7 | 512630.9 | 76474 | 1.64041666667 | 13487 |
| 014171 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595982.2 | 512629.8 | 76475 | 1.64041666667 | 14171 |
| 014703 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595978.7 | 512628.8 | 76478 | 1.64041666667 | 14703 |
| 015315 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595976.8 | 512627.8 | 76479 | 1.64041666667 | 15315 |
| 015018 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595973.5 | 512626.9 | 76482 | 1.64041666667 | 15018 |
| 016174 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1595971.5 | 512625.7 | 76483 | 1.64041666667 | 16174 |
| 016643 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595968.2 | 512624.0 | 76486 | 1.64041666667 | 16643 |
| 015831 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595965.7 | 512622.7 | 76487 | 1.64041666667 | 15831 |
| 015897 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595962.6 | 512620.9 | 76490 | 1.64041666667 | 15897 |
| 016154 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:11pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595960.3 | 512620.1 | 76492 | 1.64041666667 | 16154 |
| 016698 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1595957.8 | 512618.7 | 76494 | 1.64041666667 | 16698 |
| 015244 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:13pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595955.2 | 512617.2 | 76496 | 1.64041666667 | 15244 |
| 015061 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595952.5 | 512615.7 | 76498 | 1.64041666667 | 15061 |
| 014595 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595950.3 | 512613.9 | 76499 | 1.64041666667 | 14595 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:16pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595947.4 | 512612.7 | 76502 | 1.64041666667 | 14538 |
| 015124 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:17pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595944.7 | 512610.9 | 76504 | 1.64041666667 | 15124 |
| 013741 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:18pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595942.0 | 512608.9 | 76506 | 1.64041666667 | 13741 |
| 014325 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:19pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595939.3 | 512608.0 | 76508 | 1.64041666667 | 14325 |
| 014291 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:20pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595936.8 | 512606.2 | 76510 | 1.64041666667 | 14291 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:20pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595934.2 | 512604.5 | 76511 | 1.64041666667 | 13593 |
| 014648 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:22pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595931.0 | 512602.7 | 76514 | 1.64041666667 | 14648 |
| 015062 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:22pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595929.1 | 512600.8 | 76515 | 1.64041666667 | 15062 |
| 013905 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:23pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595926.5 | 512599.5 | 76517 | 1.64041666667 | 13905 |
| 013406 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:24pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595923.3 | 512598.6 | 76519 | 1.64041666667 | 13406 |
| 014121 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:26pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595919.7 | 512597.0 | 76522 | 1.64041666667 | 14121 |
| 014330 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:27pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595916.9 | 512595.8 | 76524 | 1.64041666667 | 14330 |
| 012552 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:28pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595914.5 | 512593.7 | 76526 | 1.64041666667 | 12552 |
| 014148 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:28pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595912.6 | 512592.0 | 76527 | 1.64041666667 | 14148 |
| 014067 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:30pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595910.5 | 512591.1 | 76530 | 1.64041666667 | 14067 |
| 015036 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:30pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595910.3 | 512590.5 | 76531 | 1.64041666667 | 15036 |
| 016029 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:32pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595910.3 | 512590.4 | 76534 | 1.64041666667 | 16029 |
| 013487 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:32pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595910.3 | 512590.4 | 76535 | 1.64041666667 | 13487 |
| 011951 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:34pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595909.9 | 512590.5 | 76538 | 1.64041666667 | 11951 |
| 013938 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:35pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595909.5 | 512591.4 | 76540 | 1.64041666667 | 13938 |
| 013654 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:35pm | Sensor | 1797-S0050-G-TJV.cor | 6837.7 | 1595909.0 | 512591.7 | 76541 | 1.64041666667 | 13654 |
| 013433 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:37pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595909.7 | 512591.2 | 76544 | 1.64041666667 | 13433 |
| 013738 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:38pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595908.6 | 512592.6 | 76546 | 1.64041666667 | 13738 |
| 014774 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:38pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595907.7 | 512594.4 | 76547 | 1.64041666667 | 14774 |
| 013503 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:40pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595906.6 | 512595.9 | 76550 | 1.64041666667 | 13503 |
| 014265 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:40pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595906.8 | 512595.9 | 76551 | 1.64041666667 | 14265 |
| 013316 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595907.3 | 512596.1 | 76554 | 1.64041666667 | 13316 |
| 014159 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595907.4 | 512596.4 | 76555 | 1.64041666667 | 14159 |
| 012570 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595907.8 | 512595.8 | 76558 | 1.64041666667 | 12570 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014932 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595907.3 | 512596.2 | 76559 | 1.64041666667 | 14932 |
| 013903 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595906.6 | 512597.2 | 76562 | 1.64041666667 | 13903 |
| 013855 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595905.5 | 512597.4 | 76563 | 1.64041666667 | 13855 |
| 016184 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:48pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595905.4 | 512597.4 | 76566 | 1.64041666667 | 16184 |
| 014366 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:49pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595905.5 | 512597.6 | 76568 | 1.64041666667 | 14366 |
| 015021 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:50pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595906.8 | 512597.7 | 76570 | 1.64041666667 | 15021 |
| 015815 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:50pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595907.9 | 512598.8 | 76571 | 1.64041666667 | 15815 |
| 015023 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:52pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595910.4 | 512599.9 | 76574 | 1.64041666667 | 15023 |
| 013416 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:52pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595912.2 | 512601.8 | 76575 | 1.64041666667 | 13416 |
| 014544 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:53pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595914.8 | 512602.8 | 76577 | 1.64041666667 | 14544 |
| 014046 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:54pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595917.1 | 512604.3 | 76579 | 1.64041666667 | 14046 |
| 013471 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:55pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595920.0 | 512606.2 | 76581 | 1.64041666667 | 13471 |
| 014227 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:57pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595923.1 | 512607.8 | 76584 | 1.64041666667 | 14227 |
| 015287 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:58pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595925.5 | 512609.6 | 76586 | 1.64041666667 | 15287 |
| 012941 | 0 | GeoXH 6000 | 08/19/2015 | 04:32:58pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595928.0 | 512610.5 | 76587 | 1.64041666667 | 12941 |
| 014095 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:00pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595931.2 | 512612.5 | 76590 | 1.64041666667 | 14095 |
| 013574 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:00pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595933.6 | 512614.4 | 76591 | 1.64041666667 | 13574 |
| 014013 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:02pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595936.7 | 512615.8 | 76594 | 1.64041666667 | 14013 |
| 015743 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:02pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595938.3 | 512617.2 | 76595 | 1.64041666667 | 15743 |
| 013505 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:04pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595940.8 | 512617.8 | 76598 | 1.64041666667 | 13505 |
| 013606 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:04pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595942.1 | 512619.1 | 76599 | 1.64041666667 | 13606 |
| 016271 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595944.6 | 512620.9 | 76602 | 1.64041666667 | 16271 |
| 015438 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595946.6 | 512622.7 | 76603 | 1.64041666667 | 15438 |
| 014299 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595949.5 | 512624.4 | 76606 | 1.64041666667 | 14299 |
| 013894 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1595951.9 | 512625.4 | 76607 | 1.64041666667 | 13894 |
| 015473 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595954.0 | 512627.8 | 76610 | 1.64041666667 | 15473 |
| 014728 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595955.9 | 512629.2 | 76611 | 1.64041666667 | 14728 |
| 013372 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595958.4 | 512631.9 | 76614 | 1.64041666667 | 13372 |
| 014473 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595960.6 | 512633.7 | 76615 | 1.64041666667 | 14473 |
| 016788 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595964.0 | 512635.0 | 76618 | 1.64041666667 | 16788 |
| 015087 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595966.1 | 512636.5 | 76619 | 1.64041666667 | 15087 |
| 014451 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595969.3 | 512637.7 | 76622 | 1.64041666667 | 14451 |
| 013303 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595972.0 | 512638.3 | 76623 | 1.64041666667 | 13303 |
| 013945 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595974.9 | 512639.7 | 76626 | 1.64041666667 | 13945 |
| 014946 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1595977.1 | 512640.8 | 76627 | 1.64041666667 | 14946 |
| 015316 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1595980.1 | 512643.1 | 76630 | 1.64041666667 | 15316 |
| 014299 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1595982.4 | 512644.9 | 76631 | 1.64041666667 | 14299 |
| 012484 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:22pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1595985.6 | 512646.5 | 76634 | 1.64041666667 | 12484 |
| 012271 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:22pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1595987.4 | 512648.1 | 76635 | 1.64041666667 | 12271 |
| 013537 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:24pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1595990.9 | 512649.8 | 76638 | 1.64041666667 | 13537 |
| 012264 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:24pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1595993.4 | 512650.9 | 76639 | 1.64041666667 | 12264 |
| 013356 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:26pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1595996.9 | 512652.2 | 76642 | 1.64041666667 | 13356 |
| 012729 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:26pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1595999.4 | 512652.9 | 76643 | 1.64041666667 | 12729 |
| 014582 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:28pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596002.4 | 512654.4 | 76646 | 1.64041666667 | 14582 |
| 013575 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:28pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596005.5 | 512655.0 | 76647 | 1.64041666667 | 13575 |
| 014523 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:30pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596009.2 | 512655.7 | 76650 | 1.64041666667 | 14523 |
| 012331 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:30pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596011.9 | 512657.0 | 76651 | 1.64041666667 | 12331 |
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:32pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596014.5 | 512658.6 | 76654 | 1.64041666667 | 12562 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013340 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:32pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596017.7 | 512659.2 | 76655 | 1.64041666667 | 13340 |
| 012545 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:33pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596016.6 | 512659.7 | 76657 | 1.64041666667 | 12545 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:34pm | Sensor | 1797-S0050-G-TJV.cor | 6841.4 | 1596018.1 | 512658.7 | 76659 | 1.64041666667 | 12106 |
| 012566 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:35pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596020.1 | 512658.3 | 76661 | 1.64041666667 | 12566 |
| 012051 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:36pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596022.7 | 512656.7 | 76663 | 1.64041666667 | 12051 |
| 012703 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:38pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596026.8 | 512654.8 | 76666 | 1.64041666667 | 12703 |
| 012025 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:38pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596029.3 | 512653.5 | 76667 | 1.64041666667 | 12025 |
| 013206 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:40pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596033.0 | 512650.8 | 76670 | 1.64041666667 | 13206 |
| 012361 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:40pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596035.3 | 512648.8 | 76671 | 1.64041666667 | 12361 |
| 012360 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:42pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596038.1 | 512645.9 | 76674 | 1.64041666667 | 12360 |
| 013830 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:42pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596040.0 | 512643.8 | 76675 | 1.64041666667 | 13830 |
| 013417 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:44pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596042.5 | 512640.9 | 76678 | 1.64041666667 | 13417 |
| 012144 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:45pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596045.3 | 512638.2 | 76680 | 1.64041666667 | 12144 |
| 011766 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:45pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596047.6 | 512635.8 | 76681 | 1.64041666667 | 11766 |
| 012031 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:46pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596049.5 | 512633.0 | 76683 | 1.64041666667 | 12031 |
| 015067 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:47pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596051.3 | 512629.1 | 76685 | 1.64041666667 | 15067 |
| 014387 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:48pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596052.7 | 512626.0 | 76687 | 1.64041666667 | 14387 |
| 015236 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:49pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596054.4 | 512622.7 | 76689 | 1.64041666667 | 15236 |
| 014489 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:50pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596056.1 | 512619.5 | 76691 | 1.64041666667 | 14489 |
| 014662 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596057.9 | 512615.2 | 76694 | 1.64041666667 | 14662 |
| 013325 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:52pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596058.4 | 512612.3 | 76695 | 1.64041666667 | 13325 |
| 014041 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:53pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596059.2 | 512608.6 | 76697 | 1.64041666667 | 14041 |
| 013920 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:54pm | Sensor | 1797-S0050-G-TJV.cor | 6841.2 | 1596059.9 | 512605.5 | 76699 | 1.64041666667 | 13920 |
| 013890 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:55pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596060.3 | 512601.7 | 76701 | 1.64041666667 | 13890 |
| 013042 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:56pm | Sensor | 1797-S0050-G-TJV.cor | 6841.6 | 1596061.1 | 512598.6 | 76703 | 1.64041666667 | 13042 |
| 014510 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:57pm | Sensor | 1797-S0050-G-TJV.cor | 6841.6 | 1596062.2 | 512595.8 | 76705 | 1.64041666667 | 14510 |
| 015507 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:58pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596062.9 | 512593.1 | 76707 | 1.64041666667 | 15507 |
| 017587 | 0 | GeoXH 6000 | 08/19/2015 | 04:33:59pm | Sensor | 1797-S0050-G-TJV.cor | 6841.3 | 1596064.2 | 512590.0 | 76709 | 1.64041666667 | 17587 |
| 015556 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:00pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596065.6 | 512587.7 | 76711 | 1.64041666667 | 15556 |
| 014239 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596067.4 | 512584.6 | 76714 | 1.64041666667 | 14239 |
| 014689 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:02pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596067.5 | 512582.5 | 76715 | 1.64041666667 | 14689 |
| 015282 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:03pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596066.8 | 512579.6 | 76717 | 1.64041666667 | 15282 |
| 016150 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596065.2 | 512577.5 | 76719 | 1.64041666667 | 16150 |
| 015647 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596062.4 | 512575.8 | 76722 | 1.64041666667 | 15647 |
| 015971 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596060.3 | 512573.9 | 76723 | 1.64041666667 | 15971 |
| 015153 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:07pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596057.4 | 512572.3 | 76725 | 1.64041666667 | 15153 |
| 015278 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596055.3 | 512570.8 | 76727 | 1.64041666667 | 15278 |
| 013989 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:09pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596052.7 | 512568.6 | 76729 | 1.64041666667 | 13989 |
| 014687 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596049.8 | 512567.6 | 76731 | 1.64041666667 | 14687 |
| 015311 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:11pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596047.4 | 512565.6 | 76733 | 1.64041666667 | 15311 |
| 014118 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596045.0 | 512564.2 | 76735 | 1.64041666667 | 14118 |
| 013609 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596041.7 | 512562.7 | 76738 | 1.64041666667 | 13609 |
| 014262 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596039.8 | 512560.9 | 76739 | 1.64041666667 | 14262 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596036.9 | 512559.2 | 76742 | 1.64041666667 | 12475 |
| 014189 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596035.2 | 512557.8 | 76743 | 1.64041666667 | 14189 |
| 013627 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596032.1 | 512556.0 | 76746 | 1.64041666667 | 13627 |
| 014686 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.2 | 1596029.5 | 512554.6 | 76747 | 1.64041666667 | 14686 |
| 013511 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596026.7 | 512552.7 | 76750 | 1.64041666667 | 13511 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014448 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596024.3 | 512552.3 | 76751 | 1.64041666667 | 14448 |
| 015552 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1596021.3 | 512550.8 | 76754 | 1.64041666667 | 15552 |
| 014508 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:22pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1596018.9 | 512549.6 | 76755 | 1.64041666667 | 14508 |
| 014487 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:24pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1596015.9 | 512548.5 | 76758 | 1.64041666667 | 14487 |
| 017181 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:24pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1596013.5 | 512547.1 | 76759 | 1.64041666667 | 17181 |
| 014195 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:25pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1596010.4 | 512546.1 | 76761 | 1.64041666667 | 14195 |
| 015488 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:26pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1596008.0 | 512544.7 | 76763 | 1.64041666667 | 15488 |
| 013712 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:28pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1596004.7 | 512543.3 | 76766 | 1.64041666667 | 13712 |
| 014138 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:28pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1596002.0 | 512542.5 | 76767 | 1.64041666667 | 14138 |
| 013854 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:30pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595998.7 | 512540.7 | 76770 | 1.64041666667 | 13854 |
| 014923 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:30pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595996.1 | 512540.2 | 76771 | 1.64041666667 | 14923 |
| 013271 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:32pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595993.7 | 512538.3 | 76774 | 1.64041666667 | 13271 |
| 013535 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:32pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595991.2 | 512536.6 | 76775 | 1.64041666667 | 13535 |
| 013121 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:34pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595988.0 | 512535.6 | 76778 | 1.64041666667 | 13121 |
| 013060 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:34pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595985.7 | 512534.1 | 76779 | 1.64041666667 | 13060 |
| 014035 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:35pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595982.7 | 512533.3 | 76781 | 1.64041666667 | 14035 |
| 015088 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:36pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595980.0 | 512532.1 | 76783 | 1.64041666667 | 15088 |
| 014302 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:37pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595977.0 | 512530.4 | 76785 | 1.64041666667 | 14302 |
| 014255 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:38pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595974.2 | 512529.5 | 76787 | 1.64041666667 | 14255 |
| 012983 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:40pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595971.2 | 512527.8 | 76790 | 1.64041666667 | 12983 |
| 012126 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:40pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595969.0 | 512526.8 | 76791 | 1.64041666667 | 12126 |
| 012301 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595965.8 | 512525.6 | 76794 | 1.64041666667 | 12301 |
| 012105 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595963.5 | 512524.0 | 76795 | 1.64041666667 | 12105 |
| 013196 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595960.5 | 512523.6 | 76798 | 1.64041666667 | 13196 |
| 012209 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595957.9 | 512522.6 | 76799 | 1.64041666667 | 12209 |
| 012832 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595954.7 | 512521.2 | 76802 | 1.64041666667 | 12832 |
| 013978 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595952.0 | 512520.8 | 76803 | 1.64041666667 | 13978 |
| 013334 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:48pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595949.8 | 512519.1 | 76806 | 1.64041666667 | 13334 |
| 013353 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:48pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595947.4 | 512517.5 | 76807 | 1.64041666667 | 13353 |
| 013028 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:50pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595945.1 | 512515.5 | 76810 | 1.64041666667 | 13028 |
| 014417 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:51pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595945.4 | 512512.6 | 76812 | 1.64041666667 | 14417 |
| 013534 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:52pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595946.9 | 512509.8 | 76814 | 1.64041666667 | 13534 |
| 015023 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:52pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595949.4 | 512509.3 | 76815 | 1.64041666667 | 15023 |
| 014466 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:53pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595952.5 | 512510.0 | 76817 | 1.64041666667 | 14466 |
| 014326 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:54pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595955.5 | 512510.2 | 76819 | 1.64041666667 | 14326 |
| 013481 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:56pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595958.7 | 512511.5 | 76822 | 1.64041666667 | 13481 |
| 011860 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:56pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595960.7 | 512513.0 | 76823 | 1.64041666667 | 11860 |
| 011695 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:58pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595963.4 | 512514.0 | 76826 | 1.64041666667 | 11695 |
| 012433 | 0 | GeoXH 6000 | 08/19/2015 | 04:34:58pm | Sensor | 1797-S0050-G-TJV.cor | 6838.8 | 1595964.9 | 512515.3 | 76827 | 1.64041666667 | 12433 |
| 011988 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:00pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595967.1 | 512516.1 | 76830 | 1.64041666667 | 11988 |
| 012087 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:00pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595967.0 | 512516.4 | 76831 | 1.64041666667 | 12087 |
| 014031 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:01pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595966.9 | 512516.5 | 76833 | 1.64041666667 | 14031 |
| 013348 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:03pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595966.9 | 512516.7 | 76836 | 1.64041666667 | 13348 |
| 013567 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:04pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595969.2 | 512517.1 | 76838 | 1.64041666667 | 13567 |
| 012991 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:04pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595971.0 | 512518.1 | 76839 | 1.64041666667 | 12991 |
| 013357 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595974.2 | 512519.1 | 76842 | 1.64041666667 | 13357 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595976.9 | 512519.9 | 76843 | 1.64041666667 | 14049 |
| 012662 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595980.2 | 512521.3 | 76846 | 1.64041666667 | 12662 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013755 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595982.5 | 512522.2 | 76847 | 1.64041666667 | 13755 |
| 012198 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:10pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595985.5 | 512524.4 | 76850 | 1.64041666667 | 12198 |
| 013789 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:10pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595988.2 | 512525.8 | 76851 | 1.64041666667 | 13789 |
| 015087 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:12pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595991.3 | 512526.9 | 76854 | 1.64041666667 | 15087 |
| 013702 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:12pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595993.6 | 512528.3 | 76855 | 1.64041666667 | 13702 |
| 015365 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.9 | 1595997.0 | 512529.3 | 76858 | 1.64041666667 | 15365 |
| 015901 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1596000.1 | 512530.5 | 76859 | 1.64041666667 | 15901 |
| 014295 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:15pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1596002.9 | 512532.2 | 76861 | 1.64041666667 | 14295 |
| 014433 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1596005.4 | 512533.1 | 76863 | 1.64041666667 | 14433 |
| 015308 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1596008.3 | 512534.8 | 76865 | 1.64041666667 | 15308 |
| 014897 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1596011.3 | 512536.1 | 76867 | 1.64041666667 | 14897 |
| 015424 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596014.5 | 512536.9 | 76870 | 1.64041666667 | 15424 |
| 014746 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596016.8 | 512538.1 | 76871 | 1.64041666667 | 14746 |
| 014216 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:21pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596020.0 | 512539.3 | 76873 | 1.64041666667 | 14216 |
| 014834 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:22pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1596023.0 | 512540.6 | 76875 | 1.64041666667 | 14834 |
| 014358 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:23pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596025.3 | 512542.2 | 76877 | 1.64041666667 | 14358 |
| 013699 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:24pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596028.2 | 512543.4 | 76879 | 1.64041666667 | 13699 |
| 014944 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:25pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596031.3 | 512545.2 | 76881 | 1.64041666667 | 14944 |
| 014386 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:26pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596034.0 | 512546.8 | 76883 | 1.64041666667 | 14386 |
| 015026 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:28pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596037.3 | 512548.0 | 76886 | 1.64041666667 | 15026 |
| 014406 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:28pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596039.2 | 512549.6 | 76887 | 1.64041666667 | 14406 |
| 015811 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:29pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596041.8 | 512552.2 | 76889 | 1.64041666667 | 15811 |
| 015952 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:30pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596044.2 | 512553.7 | 76891 | 1.64041666667 | 15952 |
| 013948 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:31pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596046.3 | 512555.6 | 76893 | 1.64041666667 | 13948 |
| 014707 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:32pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596048.8 | 512556.6 | 76895 | 1.64041666667 | 14707 |
| 013786 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:34pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596051.7 | 512558.5 | 76898 | 1.64041666667 | 13786 |
| 015296 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:34pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596054.1 | 512560.0 | 76899 | 1.64041666667 | 15296 |
| 015224 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:36pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596057.2 | 512560.9 | 76902 | 1.64041666667 | 15224 |
| 018356 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:36pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596059.5 | 512561.7 | 76903 | 1.64041666667 | 18356 |
| 015359 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:38pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596063.3 | 512562.5 | 76906 | 1.64041666667 | 15359 |
| 014579 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:38pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596065.6 | 512562.7 | 76907 | 1.64041666667 | 14579 |
| 015915 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:39pm | Sensor | 1797-S0050-G-TJV.cor | 6841.0 | 1596067.8 | 512561.6 | 76909 | 1.64041666667 | 15915 |
| 014388 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:40pm | Sensor | 1797-S0050-G-TJV.cor | 6841.1 | 1596068.9 | 512559.1 | 76911 | 1.64041666667 | 14388 |
| 014877 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:41pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596069.3 | 512556.1 | 76913 | 1.64041666667 | 14877 |
| 017279 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:42pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596067.4 | 512553.9 | 76915 | 1.64041666667 | 17279 |
| 014160 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:43pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596064.8 | 512552.1 | 76917 | 1.64041666667 | 14160 |
| 014490 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:44pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596062.6 | 512550.2 | 76919 | 1.64041666667 | 14490 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:45pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596059.5 | 512549.1 | 76921 | 1.64041666667 | 14602 |
| 015770 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:46pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596056.3 | 512548.3 | 76923 | 1.64041666667 | 15770 |
| 014 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:48pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596053.2 | 512546.9 | 76926 | 1.64041666667 | 14 |
| 014598 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:48pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596050.6 | 512546.3 | 76927 | 1.64041666667 | 14598 |
| 015 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596047.5 | 512545.1 | 76930 | 1.64041666667 | 15 |
| 015769 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:50pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596045.2 | 512544.2 | 76931 | 1.64041666667 | 15769 |
| 015132 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:51pm | Sensor | 1797-S0050-G-TJV.cor | 6840.9 | 1596042.0 | 512543.7 | 76933 | 1.64041666667 | 15132 |
| 014523 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596039.9 | 512542.4 | 76935 | 1.64041666667 | 14523 |
| 015180 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:54pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596036.6 | 512541.4 | 76938 | 1.64041666667 | 15180 |
| 014985 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:54pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596034.6 | 512540.3 | 76939 | 1.64041666667 | 14985 |
| 016076 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:56pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596031.7 | 512538.0 | 76942 | 1.64041666667 | 16076 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015239 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:56pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596029.8 | 512537.1 | 76943 | 1.64041666667 | 15239 |
| 013860 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.8 | 1596027.2 | 512535.0 | 76946 | 1.64041666667 | 13860 |
| 014655 | 0 | GeoXH 6000 | 08/19/2015 | 04:35:59pm | Sensor | 1797-S0050-G-TJV.cor | 6840.7 | 1596024.4 | 512534.1 | 76948 | 1.64041666667 | 14655 |
| 013923 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596021.6 | 512532.8 | 76950 | 1.64041666667 | 13923 |
| 014370 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596019.1 | 512531.8 | 76951 | 1.64041666667 | 14370 |
| 014842 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.6 | 1596016.0 | 512531.6 | 76954 | 1.64041666667 | 14842 |
| 013250 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1596013.7 | 512530.4 | 76955 | 1.64041666667 | 13250 |
| 014712 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.3 | 1596010.4 | 512529.8 | 76958 | 1.64041666667 | 14712 |
| 015798 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1596007.7 | 512529.3 | 76959 | 1.64041666667 | 15798 |
| 014359 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:05pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1596004.6 | 512528.8 | 76961 | 1.64041666667 | 14359 |
| 013909 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1596002.1 | 512529.6 | 76963 | 1.64041666667 | 13909 |
| 014997 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.0 | 1596000.0 | 512527.8 | 76966 | 1.64041666667 | 14997 |
| 013859 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595997.9 | 512525.7 | 76967 | 1.64041666667 | 13859 |
| 012435 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:09pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595995.0 | 512524.1 | 76969 | 1.64041666667 | 12435 |
| 013248 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:10pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595993.1 | 512522.2 | 76971 | 1.64041666667 | 13248 |
| 013512 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:11pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595990.6 | 512520.7 | 76973 | 1.64041666667 | 13512 |
| 012978 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:12pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595988.6 | 512519.0 | 76975 | 1.64041666667 | 12978 |
| 013324 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:13pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595985.7 | 512517.1 | 76977 | 1.64041666667 | 13324 |
| 013411 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595982.7 | 512516.2 | 76979 | 1.64041666667 | 13411 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:15pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595979.7 | 512514.6 | 76981 | 1.64041666667 | 12742 |
| 012035 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:16pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595977.2 | 512513.7 | 76983 | 1.64041666667 | 12035 |
| 013389 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:17pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595974.1 | 512511.9 | 76985 | 1.64041666667 | 13389 |
| 011897 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:18pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595972.2 | 512510.3 | 76987 | 1.64041666667 | 11897 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:19pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595969.8 | 512509.0 | 76989 | 1.64041666667 | 12454 |
| 012773 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:20pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595967.9 | 512507.8 | 76991 | 1.64041666667 | 12773 |
| 012403 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:21pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595964.8 | 512507.6 | 76993 | 1.64041666667 | 12403 |
| 013331 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:22pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595962.1 | 512508.2 | 76995 | 1.64041666667 | 13331 |
| 012332 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:23pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595959.2 | 512508.8 | 76997 | 1.64041666667 | 12332 |
| 013133 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:24pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595956.8 | 512509.3 | 76999 | 1.64041666667 | 13133 |
| 013693 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:25pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595954.1 | 512510.7 | 77001 | 1.64041666667 | 13693 |
| 014073 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:26pm | Sensor | 1797-S0050-G-TJV.cor | 6838.3 | 1595951.5 | 512512.1 | 77003 | 1.64041666667 | 14073 |
| 013358 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:28pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595949.7 | 512513.3 | 77006 | 1.64041666667 | 13358 |
| 013059 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:28pm | Sensor | 1797-S0050-G-TJV.cor | 6837.7 | 1595949.5 | 512515.8 | 77007 | 1.64041666667 | 13059 |
| 014665 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:30pm | Sensor | 1797-S0050-G-TJV.cor | 6837.3 | 1595949.6 | 512516.7 | 77010 | 1.64041666667 | 14665 |
| 012966 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:30pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595949.0 | 512515.7 | 77011 | 1.64041666667 | 12966 |
| 012871 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:31pm | Sensor | 1797-S0050-G-TJV.cor | 6838.0 | 1595947.0 | 512516.8 | 77013 | 1.64041666667 | 12871 |
| 014947 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:32pm | Sensor | 1797-S0050-G-TJV.cor | 6836.9 | 1595945.7 | 512517.9 | 77015 | 1.64041666667 | 14947 |
| 014417 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:33pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595945.7 | 512517.3 | 77017 | 1.64041666667 | 14417 |
| 014644 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:34pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595945.8 | 512516.4 | 77019 | 1.64041666667 | 14644 |
| 014671 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:35pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595945.7 | 512516.0 | 77021 | 1.64041666667 | 14671 |
| 012637 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:36pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595945.7 | 512515.9 | 77023 | 1.64041666667 | 12637 |
| 012879 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:37pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595945.4 | 512516.0 | 77025 | 1.64041666667 | 12879 |
| 013030 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:38pm | Sensor | 1797-S0050-G-TJV.cor | 6837.8 | 1595945.4 | 512516.6 | 77027 | 1.64041666667 | 13030 |
| 012227 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:39pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595945.7 | 512518.6 | 77029 | 1.64041666667 | 12227 |
| 012746 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:40pm | Sensor | 1797-S0050-G-TJV.cor | 6837.9 | 1595945.4 | 512521.2 | 77031 | 1.64041666667 | 12746 |
| 013326 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:41pm | Sensor | 1797-S0050-G-TJV.cor | 6838.1 | 1595945.1 | 512524.3 | 77033 | 1.64041666667 | 13326 |
| 012961 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595945.5 | 512526.9 | 77035 | 1.64041666667 | 12961 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:43pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595945.9 | 512530.3 | 77037 | 1.64041666667 | 12180 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013185 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:44pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595946.9 | 512533.2 | 77039 | 1.64041666667 | 13185 |
| 015146 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:45pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595948.8 | 512536.3 | 77041 | 1.64041666667 | 15146 |
| 015486 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:46pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595950.4 | 512539.3 | 77043 | 1.64041666667 | 15486 |
| 015751 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:47pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595951.9 | 512542.4 | 77045 | 1.64041666667 | 15751 |
| 015097 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:48pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595953.6 | 512545.3 | 77047 | 1.64041666667 | 15097 |
| 013884 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:50pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595955.3 | 512548.6 | 77050 | 1.64041666667 | 13884 |
| 013461 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:50pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595956.6 | 512550.9 | 77051 | 1.64041666667 | 13461 |
| 014645 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:51pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595959.0 | 512554.0 | 77053 | 1.64041666667 | 14645 |
| 014191 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:52pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595961.0 | 512556.3 | 77055 | 1.64041666667 | 14191 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:53pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595962.6 | 512559.3 | 77057 | 1.64041666667 | 13297 |
| 014574 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:54pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595964.0 | 512561.9 | 77059 | 1.64041666667 | 14574 |
| 014923 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:55pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595966.0 | 512565.1 | 77061 | 1.64041666667 | 14923 |
| 014621 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:56pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595967.9 | 512568.1 | 77063 | 1.64041666667 | 14621 |
| 014995 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:58pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595970.3 | 512571.0 | 77066 | 1.64041666667 | 14995 |
| 013678 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:58pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595972.5 | 512573.2 | 77067 | 1.64041666667 | 13678 |
| 014759 | 0 | GeoXH 6000 | 08/19/2015 | 04:36:59pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595975.1 | 512575.4 | 77069 | 1.64041666667 | 14759 |
| 015450 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:00pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595976.7 | 512576.9 | 77071 | 1.64041666667 | 15450 |
| 014902 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:01pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595977.8 | 512577.8 | 77073 | 1.64041666667 | 14902 |
| 014135 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:02pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595977.8 | 512577.7 | 77075 | 1.64041666667 | 14135 |
| 013943 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:03pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595977.8 | 512577.8 | 77077 | 1.64041666667 | 13943 |
| 014916 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:04pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595978.2 | 512578.3 | 77079 | 1.64041666667 | 14916 |
| 013899 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:05pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595980.4 | 512579.5 | 77081 | 1.64041666667 | 13899 |
| 013224 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595981.2 | 512580.0 | 77083 | 1.64041666667 | 13224 |
| 014646 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:07pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595981.1 | 512580.1 | 77085 | 1.64041666667 | 14646 |
| 014041 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595982.1 | 512580.2 | 77087 | 1.64041666667 | 14041 |
| 014370 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:09pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595983.8 | 512581.0 | 77089 | 1.64041666667 | 14370 |
| 015052 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:10pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.2 | 512581.2 | 77091 | 1.64041666667 | 15052 |
| 016153 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:11pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.2 | 512581.3 | 77093 | 1.64041666667 | 16153 |
| 013998 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:12pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.6 | 512581.1 | 77095 | 1.64041666667 | 13998 |
| 013729 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:13pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.5 | 512580.3 | 77097 | 1.64041666667 | 13729 |
| 013932 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.2 | 512580.1 | 77099 | 1.64041666667 | 13932 |
| 014043 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:15pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.1 | 512579.9 | 77101 | 1.64041666667 | 14043 |
| 014550 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:16pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.1 | 512579.9 | 77103 | 1.64041666667 | 14550 |
| 014647 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:18pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.0 | 512579.9 | 77106 | 1.64041666667 | 14647 |
| 014642 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:18pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.0 | 512580.0 | 77107 | 1.64041666667 | 14642 |
| 013560 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:19pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595983.9 | 512579.9 | 77109 | 1.64041666667 | 13560 |
| 012390 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:20pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595983.9 | 512579.9 | 77111 | 1.64041666667 | 12390 |
| 013237 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:21pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.3 | 512580.9 | 77113 | 1.64041666667 | 13237 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:22pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.4 | 512580.6 | 77115 | 1.64041666667 | 14049 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:23pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.5 | 512580.3 | 77117 | 1.64041666667 | 14132 |
| 013883 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:24pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.2 | 77119 | 1.64041666667 | 13883 |
| 014240 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:25pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77121 | 1.64041666667 | 14240 |
| 013040 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:26pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77123 | 1.64041666667 | 13040 |
| 014300 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:27pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.5 | 512580.1 | 77125 | 1.64041666667 | 14300 |
| 013655 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:28pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77127 | 1.64041666667 | 13655 |
| 014033 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:29pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.2 | 77129 | 1.64041666667 | 14033 |
| 014038 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:30pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.2 | 77131 | 1.64041666667 | 14038 |
| 014939 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:31pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.4 | 512580.1 | 77133 | 1.64041666667 | 14939 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012885 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:32pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.2 | 77135 | 1.64041666667 | 12885 |
| 015071 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:33pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77137 | 1.64041666667 | 15071 |
| 014387 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:34pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77139 | 1.64041666667 | 14387 |
| 017456 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:35pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.5 | 512580.2 | 77141 | 1.64041666667 | 17456 |
| 017008 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:36pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.2 | 77143 | 1.64041666667 | 17008 |
| 014741 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:37pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77145 | 1.64041666667 | 14741 |
| 014275 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:38pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77147 | 1.64041666667 | 14275 |
| 013558 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:39pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.5 | 512580.2 | 77149 | 1.64041666667 | 13558 |
| 014699 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:40pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.5 | 512580.1 | 77151 | 1.64041666667 | 14699 |
| 013605 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:41pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77153 | 1.64041666667 | 13605 |
| 014122 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:42pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.0 | 77155 | 1.64041666667 | 14122 |
| 013765 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:43pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.1 | 77157 | 1.64041666667 | 13765 |
| 013491 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:44pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.2 | 77159 | 1.64041666667 | 13491 |
| 011622 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:45pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512580.3 | 77161 | 1.64041666667 | 11622 |
| 013825 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:46pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.4 | 512580.1 | 77163 | 1.64041666667 | 13825 |
| 013356 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:48pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.1 | 77166 | 1.64041666667 | 13356 |
| 013809 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:48pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.3 | 512580.0 | 77167 | 1.64041666667 | 13809 |
| 013142 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:49pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.0 | 77169 | 1.64041666667 | 13142 |
| 013395 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:50pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512579.9 | 77171 | 1.64041666667 | 13395 |
| 014298 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:51pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.2 | 512579.9 | 77173 | 1.64041666667 | 14298 |
| 013294 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:52pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512579.8 | 77175 | 1.64041666667 | 13294 |
| 013523 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:53pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512579.9 | 77177 | 1.64041666667 | 13523 |
| 013281 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:54pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.0 | 77179 | 1.64041666667 | 13281 |
| 014540 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:55pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512579.9 | 77181 | 1.64041666667 | 14540 |
| 014885 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:56pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.2 | 512579.9 | 77183 | 1.64041666667 | 14885 |
| 014371 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:57pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512579.8 | 77185 | 1.64041666667 | 14371 |
| 016072 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:58pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.2 | 512579.9 | 77187 | 1.64041666667 | 16072 |
| 014728 | 0 | GeoXH 6000 | 08/19/2015 | 04:37:59pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.2 | 512579.9 | 77189 | 1.64041666667 | 14728 |
| 014572 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:00pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.8 | 77191 | 1.64041666667 | 14572 |
| 013933 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:01pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77193 | 1.64041666667 | 13933 |
| 014223 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:02pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77195 | 1.64041666667 | 14223 |
| 014445 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:03pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77197 | 1.64041666667 | 14445 |
| 015581 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:04pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77199 | 1.64041666667 | 15581 |
| 015055 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:05pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.1 | 512579.9 | 77201 | 1.64041666667 | 15055 |
| 014714 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:06pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77203 | 1.64041666667 | 14714 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:07pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77205 | 1.64041666667 | 14538 |
| 014944 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:08pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77207 | 1.64041666667 | 14944 |
| 013036 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:09pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77209 | 1.64041666667 | 13036 |
| 013939 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:10pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.2 | 512579.9 | 77211 | 1.64041666667 | 13939 |
| 016174 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:11pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.3 | 512580.0 | 77213 | 1.64041666667 | 16174 |
| 014183 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:12pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.0 | 77215 | 1.64041666667 | 14183 |
| 013926 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:13pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.2 | 512580.0 | 77217 | 1.64041666667 | 13926 |
| 014731 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:14pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.0 | 77219 | 1.64041666667 | 14731 |
| 013432 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:15pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.1 | 77221 | 1.64041666667 | 13432 |
| 012778 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:16pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.0 | 77223 | 1.64041666667 | 12778 |
| 014654 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:17pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.4 | 512579.9 | 77225 | 1.64041666667 | 14654 |
| 014763 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:18pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.0 | 77227 | 1.64041666667 | 14763 |
| 013170 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:19pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.1 | 77229 | 1.64041666667 | 13170 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013222 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:20pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.1 | 77231 | 1.64041666667 | 13222 |
| 016925 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:21pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.3 | 512580.0 | 77233 | 1.64041666667 | 16925 |
| 014131 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:22pm | Sensor | 1797-S0050-G-TJV.cor | 6839.6 | 1595984.3 | 512580.0 | 77235 | 1.64041666667 | 14131 |
| 013552 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:23pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.3 | 512580.1 | 77237 | 1.64041666667 | 13552 |
| 015658 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:24pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595984.2 | 512580.2 | 77239 | 1.64041666667 | 15658 |
| 014084 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:25pm | Sensor | 1797-S0050-G-TJV.cor | 6839.5 | 1595984.5 | 512581.2 | 77241 | 1.64041666667 | 14084 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:26pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595984.7 | 512581.2 | 77243 | 1.64041666667 | 12461 |
| 013435 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:27pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595984.6 | 512581.3 | 77245 | 1.64041666667 | 13435 |
| 014338 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:28pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595984.5 | 512581.3 | 77247 | 1.64041666667 | 14338 |
| 013154 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:29pm | Sensor | 1797-S0050-G-TJV.cor | 6839.4 | 1595984.5 | 512581.3 | 77249 | 1.64041666667 | 13154 |
| 015078 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:30pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595985.2 | 512581.8 | 77251 | 1.64041666667 | 15078 |
| 015409 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:31pm | Sensor | 1797-S0050-G-TJV.cor | 6838.2 | 1595985.3 | 512582.0 | 77253 | 1.64041666667 | 15409 |
| 014592 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:32pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595985.1 | 512581.9 | 77255 | 1.64041666667 | 14592 |
| 014658 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:33pm | Sensor | 1797-S0050-G-TJV.cor | 6839.7 | 1595985.1 | 512582.0 | 77257 | 1.64041666667 | 14658 |
| 012124 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:34pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595984.9 | 512581.5 | 77259 | 1.64041666667 | 12124 |
| 013681 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:35pm | Sensor | 1797-S0050-G-TJV.cor | 6839.8 | 1595984.1 | 512581.6 | 77261 | 1.64041666667 | 13681 |
| 014070 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:36pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595983.6 | 512582.0 | 77263 | 1.64041666667 | 14070 |
| 014647 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:37pm | Sensor | 1797-S0050-G-TJV.cor | 6839.1 | 1595982.2 | 512582.1 | 77265 | 1.64041666667 | 14647 |
| 015752 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:38pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595982.9 | 512582.1 | 77267 | 1.64041666667 | 15752 |
| 015488 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:39pm | Sensor | 1797-S0050-G-TJV.cor | 6838.7 | 1595983.0 | 512581.9 | 77269 | 1.64041666667 | 15488 |
| 013982 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:40pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595982.9 | 512582.0 | 77271 | 1.64041666667 | 13982 |
| 012735 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:41pm | Sensor | 1797-S0050-G-TJV.cor | 6838.5 | 1595983.0 | 512582.1 | 77273 | 1.64041666667 | 12735 |
| 013683 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:42pm | Sensor | 1797-S0050-G-TJV.cor | 6838.4 | 1595983.1 | 512582.2 | 77275 | 1.64041666667 | 13683 |
| 013711 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:43pm | Sensor | 1797-S0050-G-TJV.cor | 6838.6 | 1595983.1 | 512582.1 | 77277 | 1.64041666667 | 13711 |
| 014527 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:44pm | Sensor | 1797-S0050-G-TJV.cor | 6839.0 | 1595983.2 | 512581.9 | 77279 | 1.64041666667 | 14527 |
| 013532 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:45pm | Sensor | 1797-S0050-G-TJV.cor | 6839.2 | 1595983.3 | 512581.7 | 77281 | 1.64041666667 | 13532 |
| 014243 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:46pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595983.4 | 512581.7 | 77283 | 1.64041666667 | 14243 |
| 013460 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:47pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595983.3 | 512581.7 | 77285 | 1.64041666667 | 13460 |
| 014705 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:48pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595983.4 | 512581.7 | 77287 | 1.64041666667 | 14705 |
| 012766 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:49pm | Sensor | 1797-S0050-G-TJV.cor | 6839.3 | 1595983.5 | 512581.7 | 77289 | 1.64041666667 | 12766 |
| 016811 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:50pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595983.5 | 512581.9 | 77291 | 1.64041666667 | 16811 |
| 015723 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:51pm | Sensor | 1797-S0050-G-TJV.cor | 6838.9 | 1595983.3 | 512582.0 | 77293 | 1.64041666667 | 15723 |
| 014160 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:52pm | Sensor | 1797-S0050-G-TJV.cor | 6840.1 | 1595984.1 | 512581.0 | 77295 | 1.64041666667 | 14160 |
| 013290 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:53pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.6 | 512580.4 | 77297 | 1.64041666667 | 13290 |
| 014692 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:54pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595984.8 | 512580.7 | 77299 | 1.64041666667 | 14692 |
| 015493 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:55pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595984.9 | 512580.4 | 77301 | 1.64041666667 | 15493 |
| 014763 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:56pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.8 | 512580.5 | 77303 | 1.64041666667 | 14763 |
| 013770 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:57pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.4 | 77305 | 1.64041666667 | 13770 |
| 014992 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:58pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.3 | 77307 | 1.64041666667 | 14992 |
| 014488 | 0 | GeoXH 6000 | 08/19/2015 | 04:38:59pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.5 | 77309 | 1.64041666667 | 14488 |
| 014302 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:00pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.8 | 512580.3 | 77311 | 1.64041666667 | 14302 |
| 013505 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:01pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.8 | 512580.3 | 77313 | 1.64041666667 | 13505 |
| 014146 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:02pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.8 | 512580.4 | 77315 | 1.64041666667 | 14146 |
| 014006 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:03pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.4 | 77317 | 1.64041666667 | 14006 |
| 014301 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:04pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.8 | 512580.4 | 77319 | 1.64041666667 | 14301 |
| 013115 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:05pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595984.7 | 512580.5 | 77321 | 1.64041666667 | 13115 |
| 015128 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:06pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.6 | 512580.8 | 77323 | 1.64041666667 | 15128 |
| 013832 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:07pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.5 | 512580.6 | 77325 | 1.64041666667 | 13832 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014918 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:08pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.5 | 512580.6 | 77327 | 1.64041666667 | 14918 |
| 014439 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:09pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.5 | 512580.5 | 77329 | 1.64041666667 | 14439 |
| 014410 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:10pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.5 | 512580.5 | 77331 | 1.64041666667 | 14410 |
| 014702 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:11pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595984.5 | 512580.7 | 77333 | 1.64041666667 | 14702 |
| 014235 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:12pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595984.5 | 512580.7 | 77335 | 1.64041666667 | 14235 |
| 013788 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:13pm | Sensor | 1797-S0050-G-TJV.cor | 6840.5 | 1595984.6 | 512580.8 | 77337 | 1.64041666667 | 13788 |
| 012897 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:14pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.8 | 512580.5 | 77339 | 1.64041666667 | 12897 |
| 014444 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:15pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.7 | 512580.5 | 77341 | 1.64041666667 | 14444 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:16pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.7 | 512580.5 | 77343 | 1.64041666667 | 13931 |
| 013652 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:17pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.4 | 77345 | 1.64041666667 | 13652 |
| 013943 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:18pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.5 | 77347 | 1.64041666667 | 13943 |
| 013895 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:19pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.5 | 77349 | 1.64041666667 | 13895 |
| 013734 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:20pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.4 | 77351 | 1.64041666667 | 13734 |
| 015373 | 0 | GeoXH 6000 | 08/19/2015 | 04:39:21pm | Sensor | 1797-S0050-G-TJV.cor | 6840.4 | 1595984.9 | 512580.4 | 77353 | 1.64041666667 | 15373 |
| 011691 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:03pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.5 | 511931.0 | 71150 | 1.64041666667 | 11691 |
| 012193 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:04pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.0 | 71153 | 1.64041666667 | 12193 |
| 012558 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:05pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.0 | 71155 | 1.64041666667 | 12558 |
| 012229 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:06pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.5 | 511931.0 | 71157 | 1.64041666667 | 12229 |
| 014307 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:07pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.0 | 71159 | 1.64041666667 | 14307 |
| 013267 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:08pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.0 | 71161 | 1.64041666667 | 13267 |
| 012886 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:09pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.0 | 71163 | 1.64041666667 | 12886 |
| 012821 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:10pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.0 | 71165 | 1.64041666667 | 12821 |
| 012775 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:11pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.0 | 71167 | 1.64041666667 | 12775 |
| 011984 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:12pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.0 | 71169 | 1.64041666667 | 11984 |
| 011156 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:13pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.0 | 71171 | 1.64041666667 | 11156 |
| 010739 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:14pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.0 | 71173 | 1.64041666667 | 10739 |
| 012134 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:15pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.0 | 71175 | 1.64041666667 | 12134 |
| 013203 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:16pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.2 | 71177 | 1.64041666667 | 13203 |
| 014520 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:17pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.3 | 511931.5 | 71179 | 1.64041666667 | 14520 |
| 015180 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:18pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.4 | 71181 | 1.64041666667 | 15180 |
| 014985 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:19pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.4 | 71183 | 1.64041666667 | 14985 |
| 013346 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:20pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.4 | 511931.3 | 71185 | 1.64041666667 | 13346 |
| 012846 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:21pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.5 | 511931.2 | 71187 | 1.64041666667 | 12846 |
| 013501 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:22pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.6 | 511931.0 | 71189 | 1.64041666667 | 13501 |
| 013215 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:23pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.5 | 511931.0 | 71191 | 1.64041666667 | 13215 |
| 011703 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:24pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.5 | 511931.0 | 71193 | 1.64041666667 | 11703 |
| 011956 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:25pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.5 | 511931.0 | 71195 | 1.64041666667 | 11956 |
| 011839 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:26pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.5 | 511931.0 | 71197 | 1.64041666667 | 11839 |
| 011419 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:27pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.6 | 511931.0 | 71199 | 1.64041666667 | 11419 |
| 011555 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:28pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.6 | 511931.0 | 71201 | 1.64041666667 | 11555 |
| 011708 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:29pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.7 | 511931.1 | 71203 | 1.64041666667 | 11708 |
| 012377 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:30pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.7 | 511931.0 | 71205 | 1.64041666667 | 12377 |
| 011734 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:31pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.8 | 511930.9 | 71207 | 1.64041666667 | 11734 |
| 011063 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:32pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.8 | 511930.9 | 71209 | 1.64041666667 | 11063 |
| 011466 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:33pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.7 | 511931.0 | 71211 | 1.64041666667 | 11466 |
| 011506 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:34pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.7 | 511930.9 | 71213 | 1.64041666667 | 11506 |
| 012506 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:35pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.8 | 511931.0 | 71215 | 1.64041666667 | 12506 |
| 011766 | 0 | GeoXH 6000 | 08/19/2015 | 03:34:36pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.7 | 511931.0 | 71217 | 1.64041666667 | 11766 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011278 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:25pm | Sensor | 1797-S0049-G-TJV.cor | 6834.7 | 1595879.3 | 511931.1 | 71315 | 1.64041666667 | 11278 |
| 009869 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:26pm | Sensor | 1797-S0049-G-TJV.cor | 6834.7 | 1595879.3 | 511931.1 | 71317 | 1.64041666667 | 9869 |
| 012517 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:27pm | Sensor | 1797-S0049-G-TJV.cor | 6834.7 | 1595879.3 | 511931.2 | 71319 | 1.64041666667 | 12517 |
| 011409 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:28pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.3 | 511931.1 | 71321 | 1.64041666667 | 11409 |
| 013442 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:29pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.3 | 511931.1 | 71323 | 1.64041666667 | 13442 |
| 011790 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:30pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.3 | 511931.1 | 71325 | 1.64041666667 | 11790 |
| 014077 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:31pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.3 | 511931.2 | 71327 | 1.64041666667 | 14077 |
| 012729 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:32pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.1 | 71329 | 1.64041666667 | 12729 |
| 013562 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:33pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.1 | 71331 | 1.64041666667 | 13562 |
| 012270 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:34pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.1 | 71333 | 1.64041666667 | 12270 |
| 014257 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:35pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.1 | 71335 | 1.64041666667 | 14257 |
| 013614 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:36pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.1 | 71337 | 1.64041666667 | 13614 |
| 012763 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:37pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.1 | 71339 | 1.64041666667 | 12763 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:38pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.0 | 71341 | 1.64041666667 | 12461 |
| 012145 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:39pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.0 | 71343 | 1.64041666667 | 12145 |
| 012456 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:40pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511930.9 | 71345 | 1.64041666667 | 12456 |
| 012444 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:41pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511930.9 | 71347 | 1.64041666667 | 12444 |
| 012501 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:42pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.0 | 71349 | 1.64041666667 | 12501 |
| 010355 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:43pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.0 | 71351 | 1.64041666667 | 10355 |
| 012338 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:44pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.0 | 71353 | 1.64041666667 | 12338 |
| 012654 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:45pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.1 | 71355 | 1.64041666667 | 12654 |
| 012763 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:46pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.1 | 71357 | 1.64041666667 | 12763 |
| 013361 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:47pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.1 | 71359 | 1.64041666667 | 13361 |
| 012100 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:48pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.1 | 71361 | 1.64041666667 | 12100 |
| 012565 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:49pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511931.2 | 71363 | 1.64041666667 | 12565 |
| 011931 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:50pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.3 | 71365 | 1.64041666667 | 11931 |
| 013152 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:51pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.3 | 71367 | 1.64041666667 | 13152 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:52pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.3 | 71369 | 1.64041666667 | 12918 |
| 012139 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:53pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.2 | 71371 | 1.64041666667 | 12139 |
| 012394 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:54pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.2 | 71373 | 1.64041666667 | 12394 |
| 013058 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:55pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.2 | 71375 | 1.64041666667 | 13058 |
| 013164 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:56pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.2 | 71377 | 1.64041666667 | 13164 |
| 011991 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:57pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.2 | 71379 | 1.64041666667 | 11991 |
| 011427 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:58pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.4 | 511931.2 | 71381 | 1.64041666667 | 11427 |
| 011377 | 0 | GeoXH 6000 | 08/19/2015 | 03:35:59pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.2 | 71383 | 1.64041666667 | 11377 |
| 012804 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:00pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.4 | 511931.1 | 71385 | 1.64041666667 | 12804 |
| 012951 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:01pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.5 | 511931.1 | 71387 | 1.64041666667 | 12951 |
| 012627 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:02pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.5 | 511931.1 | 71389 | 1.64041666667 | 12627 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:03pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.5 | 511931.0 | 71391 | 1.64041666667 | 12247 |
| 011971 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:04pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.5 | 511931.0 | 71393 | 1.64041666667 | 11971 |
| 013402 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:05pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.5 | 511931.0 | 71395 | 1.64041666667 | 13402 |
| 013100 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:06pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.5 | 511930.9 | 71397 | 1.64041666667 | 13100 |
| 014195 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:07pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.6 | 511930.8 | 71399 | 1.64041666667 | 14195 |
| 013478 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:08pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.6 | 511930.8 | 71401 | 1.64041666667 | 13478 |
| 011589 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:09pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.6 | 511930.8 | 71403 | 1.64041666667 | 11589 |
| 012497 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:10pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.6 | 511930.8 | 71405 | 1.64041666667 | 12497 |
| 012004 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:11pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.6 | 511930.7 | 71407 | 1.64041666667 | 12004 |
| 012061 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:12pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.6 | 511930.8 | 71409 | 1.64041666667 | 12061 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011955 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:13pm | Sensor | 1797-S0049-G-TJV.cor | 6835.1 | 1595879.5 | 511931.0 | 71411 | 1.64041666667 | 11955 |
| 011437 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:14pm | Sensor | 1797-S0049-G-TJV.cor | 6835.3 | 1595879.5 | 511931.0 | 71413 | 1.64041666667 | 11437 |
| 013339 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:15pm | Sensor | 1797-S0049-G-TJV.cor | 6835.2 | 1595879.4 | 511930.9 | 71415 | 1.64041666667 | 13339 |
| 013565 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:16pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1595879.7 | 511931.1 | 71417 | 1.64041666667 | 13565 |
| 012541 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:17pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595879.8 | 511930.8 | 71419 | 1.64041666667 | 12541 |
| 011655 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:18pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.8 | 511930.8 | 71421 | 1.64041666667 | 11655 |
| 012693 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:19pm | Sensor | 1797-S0049-G-TJV.cor | 6834.8 | 1595879.8 | 511930.8 | 71423 | 1.64041666667 | 12693 |
| 012983 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:20pm | Sensor | 1797-S0049-G-TJV.cor | 6834.7 | 1595879.6 | 511930.9 | 71425 | 1.64041666667 | 12983 |
| 014826 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:21pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595878.9 | 511931.9 | 71427 | 1.64041666667 | 14826 |
| 014116 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:22pm | Sensor | 1797-S0049-G-TJV.cor | 6834.9 | 1595878.8 | 511932.1 | 71429 | 1.64041666667 | 14116 |
| 012979 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:23pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1595879.3 | 511932.1 | 71431 | 1.64041666667 | 12979 |
| 011074 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:24pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.4 | 511932.8 | 71433 | 1.64041666667 | 11074 |
| 013148 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595879.3 | 511934.2 | 71435 | 1.64041666667 | 13148 |
| 012257 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:26pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.3 | 511934.3 | 71437 | 1.64041666667 | 12257 |
| 011764 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.5 | 511934.0 | 71439 | 1.64041666667 | 11764 |
| 011641 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.5 | 511933.8 | 71441 | 1.64041666667 | 11641 |
| 012030 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.5 | 511934.0 | 71443 | 1.64041666667 | 12030 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.0 | 511933.7 | 71445 | 1.64041666667 | 12247 |
| 013322 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.1 | 511933.7 | 71447 | 1.64041666667 | 13322 |
| 013410 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.2 | 511933.6 | 71449 | 1.64041666667 | 13410 |
| 011512 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595879.4 | 511933.7 | 71451 | 1.64041666667 | 11512 |
| 013108 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595880.3 | 511933.6 | 71453 | 1.64041666667 | 13108 |
| 012337 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595882.5 | 511933.2 | 71455 | 1.64041666667 | 12337 |
| 013134 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595884.6 | 511933.5 | 71457 | 1.64041666667 | 13134 |
| 011713 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595887.0 | 511933.8 | 71459 | 1.64041666667 | 11713 |
| 012108 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595889.1 | 511934.7 | 71461 | 1.64041666667 | 12108 |
| 012537 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595891.7 | 511935.5 | 71463 | 1.64041666667 | 12537 |
| 012494 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595894.1 | 511936.2 | 71465 | 1.64041666667 | 12494 |
| 010953 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595896.7 | 511937.2 | 71467 | 1.64041666667 | 10953 |
| 011828 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595899.6 | 511937.7 | 71469 | 1.64041666667 | 11828 |
| 013067 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595902.2 | 511937.9 | 71471 | 1.64041666667 | 13067 |
| 011696 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595904.4 | 511938.1 | 71473 | 1.64041666667 | 11696 |
| 011534 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595907.1 | 511937.9 | 71475 | 1.64041666667 | 11534 |
| 012693 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595908.8 | 511937.7 | 71477 | 1.64041666667 | 12693 |
| 015263 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595910.5 | 511936.8 | 71479 | 1.64041666667 | 15263 |
| 012545 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595911.7 | 511936.3 | 71481 | 1.64041666667 | 12545 |
| 012706 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595913.2 | 511934.3 | 71483 | 1.64041666667 | 12706 |
| 012566 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595915.1 | 511933.1 | 71485 | 1.64041666667 | 12566 |
| 013971 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595915.8 | 511932.5 | 71487 | 1.64041666667 | 13971 |
| 013993 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595915.8 | 511932.5 | 71489 | 1.64041666667 | 13993 |
| 012798 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511932.6 | 71491 | 1.64041666667 | 12798 |
| 013129 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511932.7 | 71493 | 1.64041666667 | 13129 |
| 014262 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511933.1 | 71495 | 1.64041666667 | 14262 |
| 013045 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511932.5 | 71497 | 1.64041666667 | 13045 |
| 012831 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.4 | 511932.1 | 71499 | 1.64041666667 | 12831 |
| 012057 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:58pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595915.5 | 511932.3 | 71501 | 1.64041666667 | 12057 |
| 011954 | 0 | GeoXH 6000 | 08/19/2015 | 03:36:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.5 | 511932.0 | 71503 | 1.64041666667 | 11954 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.5 | 511931.8 | 71505 | 1.64041666667 | 12078 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595915.8 | 511930.1 | 71507 | 1.64041666667 | 12019 |
| 013474 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595915.5 | 511928.4 | 71509 | 1.64041666667 | 13474 |
| 013148 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.7 | 511927.4 | 71511 | 1.64041666667 | 13148 |
| 013247 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:04pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71513 | 1.64041666667 | 13247 |
| 012971 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.0 | 511927.8 | 71515 | 1.64041666667 | 12971 |
| 012633 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.0 | 511927.8 | 71517 | 1.64041666667 | 12633 |
| 013448 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.0 | 511927.9 | 71519 | 1.64041666667 | 13448 |
| 011072 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.9 | 71521 | 1.64041666667 | 11072 |
| 012488 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.1 | 511927.8 | 71523 | 1.64041666667 | 12488 |
| 012752 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.9 | 71525 | 1.64041666667 | 12752 |
| 014648 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.9 | 71527 | 1.64041666667 | 14648 |
| 012422 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:12pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.9 | 71529 | 1.64041666667 | 12422 |
| 012855 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.9 | 71531 | 1.64041666667 | 12855 |
| 013207 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:14pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.9 | 71533 | 1.64041666667 | 13207 |
| 013546 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.9 | 71535 | 1.64041666667 | 13546 |
| 013616 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:16pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.9 | 71537 | 1.64041666667 | 13616 |
| 012854 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.9 | 71539 | 1.64041666667 | 12854 |
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:18pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.9 | 71541 | 1.64041666667 | 12183 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.9 | 71543 | 1.64041666667 | 12255 |
| 012753 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:20pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.8 | 71545 | 1.64041666667 | 12753 |
| 013778 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.0 | 511927.8 | 71547 | 1.64041666667 | 13778 |
| 012294 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.9 | 71549 | 1.64041666667 | 12294 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.9 | 71551 | 1.64041666667 | 12163 |
| 013301 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.8 | 71553 | 1.64041666667 | 13301 |
| 010945 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595915.9 | 511927.8 | 71555 | 1.64041666667 | 10945 |
| 011412 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595915.9 | 511927.8 | 71557 | 1.64041666667 | 11412 |
| 012526 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.8 | 71559 | 1.64041666667 | 12526 |
| 012221 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.8 | 71561 | 1.64041666667 | 12221 |
| 011335 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.8 | 71563 | 1.64041666667 | 11335 |
| 011024 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.8 | 71565 | 1.64041666667 | 11024 |
| 012476 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.9 | 71567 | 1.64041666667 | 12476 |
| 013109 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.9 | 71569 | 1.64041666667 | 13109 |
| 012397 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.9 | 71571 | 1.64041666667 | 12397 |
| 011949 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.7 | 511927.8 | 71573 | 1.64041666667 | 11949 |
| 012197 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.8 | 71575 | 1.64041666667 | 12197 |
| 011779 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.8 | 71577 | 1.64041666667 | 11779 |
| 012724 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.8 | 71579 | 1.64041666667 | 12724 |
| 013111 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595915.8 | 511927.8 | 71581 | 1.64041666667 | 13111 |
| 012667 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.8 | 71583 | 1.64041666667 | 12667 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.8 | 71585 | 1.64041666667 | 12917 |
| 010969 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.8 | 71587 | 1.64041666667 | 10969 |
| 012372 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.8 | 71589 | 1.64041666667 | 12372 |
| 012813 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.8 | 71591 | 1.64041666667 | 12813 |
| 011873 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.8 | 511927.9 | 71593 | 1.64041666667 | 11873 |
| 012268 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595915.9 | 511927.8 | 71595 | 1.64041666667 | 12268 |
| 010927 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.2 | 511927.6 | 71597 | 1.64041666667 | 10927 |
| 012271 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.0 | 511927.4 | 71599 | 1.64041666667 | 12271 |
| 013957 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.8 | 71601 | 1.64041666667 | 13957 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011589 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.3 | 511927.9 | 71603 | 1.64041666667 | 11589 |
| 012317 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.3 | 511927.9 | 71605 | 1.64041666667 | 12317 |
| 012499 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.3 | 511927.9 | 71607 | 1.64041666667 | 12499 |
| 012214 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.3 | 511927.9 | 71609 | 1.64041666667 | 12214 |
| 011573 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.3 | 511928.0 | 71611 | 1.64041666667 | 11573 |
| 012643 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.3 | 511928.0 | 71613 | 1.64041666667 | 12643 |
| 011741 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.0 | 511927.5 | 71615 | 1.64041666667 | 11741 |
| 013375 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.0 | 511927.2 | 71617 | 1.64041666667 | 13375 |
| 011863 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.0 | 511927.5 | 71619 | 1.64041666667 | 11863 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:58pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.6 | 71621 | 1.64041666667 | 12536 |
| 010664 | 0 | GeoXH 6000 | 08/19/2015 | 03:37:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71623 | 1.64041666667 | 10664 |
| 011096 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71625 | 1.64041666667 | 11096 |
| 011024 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71627 | 1.64041666667 | 11024 |
| 012896 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.8 | 71629 | 1.64041666667 | 12896 |
| 012074 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71631 | 1.64041666667 | 12074 |
| 011928 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:04pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.8 | 71633 | 1.64041666667 | 11928 |
| 012702 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71635 | 1.64041666667 | 12702 |
| 013375 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.7 | 71637 | 1.64041666667 | 13375 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.7 | 71639 | 1.64041666667 | 13424 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71641 | 1.64041666667 | 12536 |
| 012464 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71643 | 1.64041666667 | 12464 |
| 012956 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71645 | 1.64041666667 | 12956 |
| 012509 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.2 | 511927.7 | 71647 | 1.64041666667 | 12509 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:12pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71649 | 1.64041666667 | 13297 |
| 013074 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71651 | 1.64041666667 | 13074 |
| 012208 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:14pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.2 | 511927.7 | 71653 | 1.64041666667 | 12208 |
| 011272 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71655 | 1.64041666667 | 11272 |
| 010438 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:16pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595916.1 | 511927.8 | 71657 | 1.64041666667 | 10438 |
| 011819 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.9 | 71659 | 1.64041666667 | 11819 |
| 010965 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:18pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.9 | 71661 | 1.64041666667 | 10965 |
| 011381 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.2 | 511927.9 | 71663 | 1.64041666667 | 11381 |
| 013255 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:20pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.2 | 511927.9 | 71665 | 1.64041666667 | 13255 |
| 013993 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.2 | 511927.9 | 71667 | 1.64041666667 | 13993 |
| 013008 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71669 | 1.64041666667 | 13008 |
| 012942 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.2 | 511927.7 | 71671 | 1.64041666667 | 12942 |
| 012385 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.2 | 511927.8 | 71673 | 1.64041666667 | 12385 |
| 011916 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.2 | 511927.8 | 71675 | 1.64041666667 | 11916 |
| 013749 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.9 | 71677 | 1.64041666667 | 13749 |
| 012557 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71679 | 1.64041666667 | 12557 |
| 011498 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71681 | 1.64041666667 | 11498 |
| 013062 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71683 | 1.64041666667 | 13062 |
| 012655 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.8 | 71685 | 1.64041666667 | 12655 |
| 014984 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.7 | 71687 | 1.64041666667 | 14984 |
| 013736 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71689 | 1.64041666667 | 13736 |
| 012104 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71691 | 1.64041666667 | 12104 |
| 012686 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.8 | 71693 | 1.64041666667 | 12686 |
| 012831 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.8 | 71695 | 1.64041666667 | 12831 |
| 012207 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595916.1 | 511927.7 | 71697 | 1.64041666667 | 12207 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011032 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.7 | 71699 | 1.64041666667 | 11032 |
| 011728 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71701 | 1.64041666667 | 11728 |
| 011482 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71703 | 1.64041666667 | 11482 |
| 011900 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71705 | 1.64041666667 | 11900 |
| 013175 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.9 | 71707 | 1.64041666667 | 13175 |
| 011273 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.9 | 71709 | 1.64041666667 | 11273 |
| 012748 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.1 | 511927.8 | 71711 | 1.64041666667 | 12748 |
| 012877 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.0 | 511927.8 | 71713 | 1.64041666667 | 12877 |
| 012099 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.0 | 511927.8 | 71715 | 1.64041666667 | 12099 |
| 012234 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.0 | 511927.9 | 71717 | 1.64041666667 | 12234 |
| 011368 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595915.9 | 511927.9 | 71719 | 1.64041666667 | 11368 |
| 012202 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:48pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595915.9 | 511927.8 | 71721 | 1.64041666667 | 12202 |
| 012680 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595915.9 | 511927.8 | 71723 | 1.64041666667 | 12680 |
| 014270 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.0 | 511927.8 | 71725 | 1.64041666667 | 14270 |
| 012747 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.0 | 511927.8 | 71727 | 1.64041666667 | 12747 |
| 010957 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:52pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.0 | 511927.8 | 71729 | 1.64041666667 | 10957 |
| 012069 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.0 | 511927.8 | 71731 | 1.64041666667 | 12069 |
| 013337 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:54pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.1 | 511927.9 | 71733 | 1.64041666667 | 13337 |
| 012544 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.2 | 511927.9 | 71735 | 1.64041666667 | 12544 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:56pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.2 | 511928.0 | 71737 | 1.64041666667 | 12106 |
| 012896 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.3 | 511928.0 | 71739 | 1.64041666667 | 12896 |
| 011984 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595916.4 | 511927.2 | 71741 | 1.64041666667 | 11984 |
| 011966 | 0 | GeoXH 6000 | 08/19/2015 | 03:38:59pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595916.9 | 511924.9 | 71743 | 1.64041666667 | 11966 |
| 013221 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:00pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1595917.2 | 511924.4 | 71745 | 1.64041666667 | 13221 |
| 012845 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595915.8 | 511925.6 | 71747 | 1.64041666667 | 12845 |
| 011191 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595914.8 | 511926.3 | 71749 | 1.64041666667 | 11191 |
| 012307 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595915.3 | 511927.2 | 71751 | 1.64041666667 | 12307 |
| 011717 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:04pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595915.1 | 511929.0 | 71753 | 1.64041666667 | 11717 |
| 011719 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595915.1 | 511930.5 | 71755 | 1.64041666667 | 11719 |
| 013009 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595914.5 | 511931.4 | 71757 | 1.64041666667 | 13009 |
| 011112 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595914.5 | 511931.4 | 71759 | 1.64041666667 | 11112 |
| 012828 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595914.5 | 511931.5 | 71761 | 1.64041666667 | 12828 |
| 013737 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595914.8 | 511931.5 | 71763 | 1.64041666667 | 13737 |
| 013124 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595914.7 | 511931.4 | 71765 | 1.64041666667 | 13124 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595914.7 | 511931.6 | 71767 | 1.64041666667 | 12521 |
| 013510 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595915.7 | 511932.0 | 71769 | 1.64041666667 | 13510 |
| 013817 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595918.4 | 511933.2 | 71771 | 1.64041666667 | 13817 |
| 010954 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595920.6 | 511933.7 | 71773 | 1.64041666667 | 10954 |
| 011828 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595923.0 | 511934.5 | 71775 | 1.64041666667 | 11828 |
| 011897 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595925.3 | 511934.5 | 71777 | 1.64041666667 | 11897 |
| 012724 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595927.3 | 511935.7 | 71779 | 1.64041666667 | 12724 |
| 012391 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595929.4 | 511936.7 | 71781 | 1.64041666667 | 12391 |
| 012577 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595931.1 | 511938.0 | 71783 | 1.64041666667 | 12577 |
| 012174 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595933.2 | 511938.5 | 71785 | 1.64041666667 | 12174 |
| 012493 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595935.3 | 511939.8 | 71787 | 1.64041666667 | 12493 |
| 012783 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:22pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595937.1 | 511941.1 | 71789 | 1.64041666667 | 12783 |
| 014055 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:23pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595939.2 | 511941.9 | 71791 | 1.64041666667 | 14055 |
| 011673 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:24pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595941.9 | 511943.2 | 71793 | 1.64041666667 | 11673 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012998 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595944.3 | 511943.8 | 71795 | 1.64041666667 | 12998 |
| 014949 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:26pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595946.3 | 511945.0 | 71797 | 1.64041666667 | 14949 |
| 013187 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595947.9 | 511945.6 | 71799 | 1.64041666667 | 13187 |
| 014276 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595948.8 | 511946.6 | 71801 | 1.64041666667 | 14276 |
| 014159 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595951.1 | 511947.2 | 71803 | 1.64041666667 | 14159 |
| 013110 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595953.0 | 511948.0 | 71805 | 1.64041666667 | 13110 |
| 017467 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595955.4 | 511948.5 | 71807 | 1.64041666667 | 17467 |
| 014356 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.9 | 511949.3 | 71809 | 1.64041666667 | 14356 |
| 016009 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.1 | 511949.1 | 71811 | 1.64041666667 | 16009 |
| 016332 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.2 | 511949.1 | 71813 | 1.64041666667 | 16332 |
| 020283 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595956.2 | 511947.4 | 71815 | 1.64041666667 | 20283 |
| 019890 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595956.9 | 511946.9 | 71817 | 1.64041666667 | 19890 |
| 023332 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595958.0 | 511945.4 | 71819 | 1.64041666667 | 23332 |
| 023383 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595958.5 | 511943.7 | 71821 | 1.64041666667 | 23383 |
| 021956 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595958.6 | 511941.7 | 71823 | 1.64041666667 | 21956 |
| 023039 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.7 | 511940.8 | 71825 | 1.64041666667 | 23039 |
| 022439 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.3 | 511941.1 | 71827 | 1.64041666667 | 22439 |
| 024180 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.6 | 511942.1 | 71829 | 1.64041666667 | 24180 |
| 024975 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.8 | 511942.1 | 71831 | 1.64041666667 | 24975 |
| 023133 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.7 | 511942.1 | 71833 | 1.64041666667 | 23133 |
| 020723 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.6 | 511942.2 | 71835 | 1.64041666667 | 20723 |
| 024110 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.6 | 511942.2 | 71837 | 1.64041666667 | 24110 |
| 025287 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.6 | 511942.4 | 71839 | 1.64041666667 | 25287 |
| 024112 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:48pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595956.5 | 511943.6 | 71841 | 1.64041666667 | 24112 |
| 021178 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595956.0 | 511945.6 | 71843 | 1.64041666667 | 21178 |
| 016394 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.5 | 511948.1 | 71845 | 1.64041666667 | 16394 |
| 015708 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.1 | 511949.8 | 71847 | 1.64041666667 | 15708 |
| 015447 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:52pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595959.2 | 511950.9 | 71849 | 1.64041666667 | 15447 |
| 016161 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595960.9 | 511952.5 | 71851 | 1.64041666667 | 16161 |
| 016070 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:54pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595962.8 | 511953.7 | 71853 | 1.64041666667 | 16070 |
| 015837 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595964.5 | 511955.0 | 71855 | 1.64041666667 | 15837 |
| 013499 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:56pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595966.8 | 511955.9 | 71857 | 1.64041666667 | 13499 |
| 014325 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595969.0 | 511957.0 | 71859 | 1.64041666667 | 14325 |
| 015191 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595971.3 | 511958.0 | 71861 | 1.64041666667 | 15191 |
| 013877 | 0 | GeoXH 6000 | 08/19/2015 | 03:39:59pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595973.9 | 511959.0 | 71863 | 1.64041666667 | 13877 |
| 014149 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:00pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595975.7 | 511960.2 | 71865 | 1.64041666667 | 14149 |
| 016137 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595977.5 | 511961.3 | 71867 | 1.64041666667 | 16137 |
| 016784 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:02pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595979.7 | 511961.8 | 71869 | 1.64041666667 | 16784 |
| 017486 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595981.8 | 511963.1 | 71871 | 1.64041666667 | 17486 |
| 016701 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:04pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595983.7 | 511964.4 | 71873 | 1.64041666667 | 16701 |
| 016775 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:05pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595985.5 | 511965.7 | 71875 | 1.64041666667 | 16775 |
| 015593 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595987.7 | 511966.8 | 71877 | 1.64041666667 | 15593 |
| 014848 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595989.6 | 511967.2 | 71879 | 1.64041666667 | 14848 |
| 014662 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:08pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595992.0 | 511968.0 | 71881 | 1.64041666667 | 14662 |
| 015215 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595994.3 | 511969.2 | 71883 | 1.64041666667 | 15215 |
| 016553 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595995.8 | 511970.0 | 71885 | 1.64041666667 | 16553 |
| 020308 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595998.3 | 511971.2 | 71887 | 1.64041666667 | 20308 |
| 026527 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595999.8 | 511972.3 | 71889 | 1.64041666667 | 26527 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 023911 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1596001.2 | 511972.2 | 71891 | 1.64041666667 | 23911 |
| 023317 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1596002.6 | 511972.2 | 71893 | 1.64041666667 | 23317 |
| 023889 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1596002.9 | 511971.9 | 71895 | 1.64041666667 | 23889 |
| 022772 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1596002.0 | 511971.6 | 71897 | 1.64041666667 | 22772 |
| 021113 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1596000.6 | 511972.1 | 71899 | 1.64041666667 | 21113 |
| 022138 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.7 | 511973.1 | 71901 | 1.64041666667 | 22138 |
| 022514 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595999.5 | 511973.4 | 71903 | 1.64041666667 | 22514 |
| 025488 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.6 | 511973.8 | 71905 | 1.64041666667 | 25488 |
| 023262 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.7 | 511973.8 | 71907 | 1.64041666667 | 23262 |
| 023695 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:22pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.7 | 511973.7 | 71909 | 1.64041666667 | 23695 |
| 023564 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:23pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.7 | 511973.7 | 71911 | 1.64041666667 | 23564 |
| 022601 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:24pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.6 | 511973.8 | 71913 | 1.64041666667 | 22601 |
| 021730 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.7 | 511973.8 | 71915 | 1.64041666667 | 21730 |
| 022082 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:26pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.7 | 511973.8 | 71917 | 1.64041666667 | 22082 |
| 023160 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595999.7 | 511973.7 | 71919 | 1.64041666667 | 23160 |
| 025110 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595999.9 | 511973.2 | 71921 | 1.64041666667 | 25110 |
| 024517 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1595999.8 | 511971.8 | 71923 | 1.64041666667 | 24517 |
| 025599 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1595999.7 | 511971.5 | 71925 | 1.64041666667 | 25599 |
| 026200 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:31pm | Sensor | 1797-S0049-G-TJV.cor | 6835.8 | 1595999.8 | 511971.0 | 71927 | 1.64041666667 | 26200 |
| 029410 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1595999.7 | 511971.7 | 71929 | 1.64041666667 | 29410 |
| 024992 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595999.4 | 511973.3 | 71931 | 1.64041666667 | 24992 |
| 024728 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595999.8 | 511973.1 | 71933 | 1.64041666667 | 24728 |
| 026552 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1596001.0 | 511972.0 | 71935 | 1.64041666667 | 26552 |
| 023168 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1596001.4 | 511972.4 | 71937 | 1.64041666667 | 23168 |
| 023552 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1596003.4 | 511972.1 | 71939 | 1.64041666667 | 23552 |
| 019358 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1596005.0 | 511972.6 | 71941 | 1.64041666667 | 19358 |
| 014559 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1596007.4 | 511973.6 | 71943 | 1.64041666667 | 14559 |
| 014080 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1596009.3 | 511974.5 | 71945 | 1.64041666667 | 14080 |
| 014200 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1596011.5 | 511976.0 | 71947 | 1.64041666667 | 14200 |
| 015190 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:42pm | Sensor | 1797-S0049-G-TJV.cor | 6835.8 | 1596013.4 | 511976.9 | 71949 | 1.64041666667 | 15190 |
| 014687 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:43pm | Sensor | 1797-S0049-G-TJV.cor | 6835.7 | 1596015.9 | 511978.5 | 71951 | 1.64041666667 | 14687 |
| 013661 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:44pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596017.8 | 511979.5 | 71953 | 1.64041666667 | 13661 |
| 013465 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:45pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596019.7 | 511981.9 | 71955 | 1.64041666667 | 13465 |
| 013236 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:46pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596021.8 | 511983.0 | 71957 | 1.64041666667 | 13236 |
| 013899 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:47pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.5 | 511984.6 | 71959 | 1.64041666667 | 13899 |
| 012984 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:48pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.6 | 511984.5 | 71961 | 1.64041666667 | 12984 |
| 012366 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:49pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.6 | 511984.5 | 71963 | 1.64041666667 | 12366 |
| 012451 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:50pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.5 | 511984.5 | 71965 | 1.64041666667 | 12451 |
| 014302 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:51pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.4 | 511984.4 | 71967 | 1.64041666667 | 14302 |
| 012095 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:52pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.4 | 511984.5 | 71969 | 1.64041666667 | 12095 |
| 012684 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:53pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.4 | 511984.5 | 71971 | 1.64041666667 | 12684 |
| 013881 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:54pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.5 | 511984.5 | 71973 | 1.64041666667 | 13881 |
| 012680 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:55pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.4 | 511984.5 | 71975 | 1.64041666667 | 12680 |
| 013370 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:56pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.4 | 511984.5 | 71977 | 1.64041666667 | 13370 |
| 013932 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:57pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.5 | 511984.5 | 71979 | 1.64041666667 | 13932 |
| 014883 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:58pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.5 | 511984.4 | 71981 | 1.64041666667 | 14883 |
| 013560 | 0 | GeoXH 6000 | 08/19/2015 | 03:40:59pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.5 | 511984.5 | 71983 | 1.64041666667 | 13560 |
| 013080 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:00pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.4 | 511984.5 | 71985 | 1.64041666667 | 13080 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014910 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:01pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.4 | 511984.6 | 71987 | 1.64041666667 | 14910 |
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:02pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.4 | 511984.5 | 71989 | 1.64041666667 | 12937 |
| 013254 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:03pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596022.5 | 511984.4 | 71991 | 1.64041666667 | 13254 |
| 012793 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:04pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.6 | 511984.4 | 71993 | 1.64041666667 | 12793 |
| 012588 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:05pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.6 | 511984.5 | 71995 | 1.64041666667 | 12588 |
| 012327 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:06pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.7 | 511984.5 | 71997 | 1.64041666667 | 12327 |
| 012171 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:07pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596023.1 | 511984.5 | 71999 | 1.64041666667 | 12171 |
| 015493 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:08pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596023.5 | 511984.1 | 72001 | 1.64041666667 | 15493 |
| 013533 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:09pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596023.7 | 511984.3 | 72003 | 1.64041666667 | 13533 |
| 015143 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:10pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596023.4 | 511984.4 | 72005 | 1.64041666667 | 15143 |
| 015965 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:11pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72007 | 1.64041666667 | 15965 |
| 013261 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:12pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72009 | 1.64041666667 | 13261 |
| 012435 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:13pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.8 | 511984.5 | 72011 | 1.64041666667 | 12435 |
| 014328 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:14pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.8 | 511984.6 | 72013 | 1.64041666667 | 14328 |
| 013392 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:15pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.8 | 511984.5 | 72015 | 1.64041666667 | 13392 |
| 013488 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:16pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.8 | 511984.6 | 72017 | 1.64041666667 | 13488 |
| 013272 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:17pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.8 | 511984.5 | 72019 | 1.64041666667 | 13272 |
| 012978 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:18pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.8 | 511984.6 | 72021 | 1.64041666667 | 12978 |
| 012154 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:19pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.8 | 511984.6 | 72023 | 1.64041666667 | 12154 |
| 012218 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:20pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.8 | 511984.6 | 72025 | 1.64041666667 | 12218 |
| 015324 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:21pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.8 | 511984.6 | 72027 | 1.64041666667 | 15324 |
| 013611 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:22pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.8 | 511984.6 | 72029 | 1.64041666667 | 13611 |
| 014262 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:23pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72031 | 1.64041666667 | 14262 |
| 013585 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:24pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72033 | 1.64041666667 | 13585 |
| 013416 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:25pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72035 | 1.64041666667 | 13416 |
| 013044 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:26pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72037 | 1.64041666667 | 13044 |
| 012081 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:27pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.7 | 511984.6 | 72039 | 1.64041666667 | 12081 |
| 012560 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:28pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72041 | 1.64041666667 | 12560 |
| 013310 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:29pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72043 | 1.64041666667 | 13310 |
| 014397 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:30pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72045 | 1.64041666667 | 14397 |
| 014639 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:31pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72047 | 1.64041666667 | 14639 |
| 013830 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:32pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.6 | 511984.6 | 72049 | 1.64041666667 | 13830 |
| 015157 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:33pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.6 | 511984.6 | 72051 | 1.64041666667 | 15157 |
| 014589 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:34pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72053 | 1.64041666667 | 14589 |
| 013757 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:35pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.6 | 511984.6 | 72055 | 1.64041666667 | 13757 |
| 013039 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:36pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72057 | 1.64041666667 | 13039 |
| 012709 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:37pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72059 | 1.64041666667 | 12709 |
| 012747 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:38pm | Sensor | 1797-S0049-G-TJV.cor | 6835.7 | 1596022.7 | 511984.6 | 72061 | 1.64041666667 | 12747 |
| 012427 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:39pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72063 | 1.64041666667 | 12427 |
| 013246 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:40pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72065 | 1.64041666667 | 13246 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:41pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72067 | 1.64041666667 | 13931 |
| 012753 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:42pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72069 | 1.64041666667 | 12753 |
| 014048 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:43pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.6 | 72071 | 1.64041666667 | 14048 |
| 013712 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:44pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.6 | 511984.5 | 72073 | 1.64041666667 | 13712 |
| 013538 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:45pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.6 | 511984.5 | 72075 | 1.64041666667 | 13538 |
| 013284 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:46pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.6 | 511984.6 | 72077 | 1.64041666667 | 13284 |
| 013071 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:47pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.6 | 511984.5 | 72079 | 1.64041666667 | 13071 |
| 013587 | 0 | GeoXH 6000 | 08/19/2015 | 03:41:48pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596022.7 | 511984.5 | 72081 | 1.64041666667 | 13587 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014269 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:37pm | Sensor | 1797-S0049-G-TJV.cor | 6835.3 | 1596024.1 | 511984.0 | 72179 | 1.64041666667 | 14269 |
| 014037 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:38pm | Sensor | 1797-S0049-G-TJV.cor | 6835.1 | 1596024.1 | 511984.3 | 72181 | 1.64041666667 | 14037 |
| 012059 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:39pm | Sensor | 1797-S0049-G-TJV.cor | 6833.7 | 1596025.1 | 511984.4 | 72183 | 1.64041666667 | 12059 |
| 012525 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:40pm | Sensor | 1797-S0049-G-TJV.cor | 6833.5 | 1596025.3 | 511984.5 | 72185 | 1.64041666667 | 12525 |
| 012641 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:41pm | Sensor | 1797-S0049-G-TJV.cor | 6833.7 | 1596025.1 | 511984.7 | 72187 | 1.64041666667 | 12641 |
| 012070 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:42pm | Sensor | 1797-S0049-G-TJV.cor | 6833.7 | 1596025.2 | 511984.5 | 72189 | 1.64041666667 | 12070 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:43pm | Sensor | 1797-S0049-G-TJV.cor | 6833.8 | 1596025.1 | 511984.7 | 72191 | 1.64041666667 | 12917 |
| 011719 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:44pm | Sensor | 1797-S0049-G-TJV.cor | 6834.4 | 1596024.8 | 511984.4 | 72193 | 1.64041666667 | 11719 |
| 012319 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:45pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596023.3 | 511984.4 | 72195 | 1.64041666667 | 12319 |
| 013820 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:46pm | Sensor | 1797-S0049-G-TJV.cor | 6835.3 | 1596022.6 | 511984.7 | 72197 | 1.64041666667 | 13820 |
| 013565 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:47pm | Sensor | 1797-S0049-G-TJV.cor | 6835.3 | 1596022.7 | 511984.4 | 72199 | 1.64041666667 | 13565 |
| 012931 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:48pm | Sensor | 1797-S0049-G-TJV.cor | 6835.3 | 1596023.0 | 511984.5 | 72201 | 1.64041666667 | 12931 |
| 011992 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:49pm | Sensor | 1797-S0049-G-TJV.cor | 6835.3 | 1596023.5 | 511984.7 | 72203 | 1.64041666667 | 11992 |
| 014488 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:50pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596023.4 | 511983.8 | 72205 | 1.64041666667 | 14488 |
| 015082 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:51pm | Sensor | 1797-S0049-G-TJV.cor | 6835.3 | 1596024.6 | 511982.0 | 72207 | 1.64041666667 | 15082 |
| 013940 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:52pm | Sensor | 1797-S0049-G-TJV.cor | 6835.2 | 1596024.8 | 511981.3 | 72209 | 1.64041666667 | 13940 |
| 013535 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:53pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596024.9 | 511980.9 | 72211 | 1.64041666667 | 13535 |
| 014843 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:54pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596024.7 | 511979.6 | 72213 | 1.64041666667 | 14843 |
| 014091 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:55pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596025.1 | 511977.5 | 72215 | 1.64041666667 | 14091 |
| 013782 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:56pm | Sensor | 1797-S0049-G-TJV.cor | 6835.8 | 1596025.6 | 511975.6 | 72217 | 1.64041666667 | 13782 |
| 012955 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1596026.2 | 511974.6 | 72219 | 1.64041666667 | 12955 |
| 013889 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:58pm | Sensor | 1797-S0049-G-TJV.cor | 6835.9 | 1596026.1 | 511974.4 | 72221 | 1.64041666667 | 13889 |
| 015262 | 0 | GeoXH 6000 | 08/19/2015 | 03:42:59pm | Sensor | 1797-S0049-G-TJV.cor | 6835.2 | 1596026.5 | 511973.1 | 72223 | 1.64041666667 | 15262 |
| 015635 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:00pm | Sensor | 1797-S0049-G-TJV.cor | 6835.1 | 1596026.7 | 511973.0 | 72225 | 1.64041666667 | 15635 |
| 016268 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:01pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1596026.7 | 511972.9 | 72227 | 1.64041666667 | 16268 |
| 015827 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:02pm | Sensor | 1797-S0049-G-TJV.cor | 6835.0 | 1596026.8 | 511972.9 | 72229 | 1.64041666667 | 15827 |
| 015356 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:03pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1596026.8 | 511973.2 | 72231 | 1.64041666667 | 15356 |
| 014309 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:04pm | Sensor | 1797-S0049-G-TJV.cor | 6835.9 | 1596026.7 | 511973.8 | 72233 | 1.64041666667 | 14309 |
| 013867 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:05pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1596026.4 | 511974.9 | 72235 | 1.64041666667 | 13867 |
| 014296 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1596025.9 | 511974.4 | 72237 | 1.64041666667 | 14296 |
| 014104 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:07pm | Sensor | 1797-S0049-G-TJV.cor | 6835.9 | 1596025.4 | 511976.0 | 72239 | 1.64041666667 | 14104 |
| 015076 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:08pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596025.2 | 511977.9 | 72241 | 1.64041666667 | 15076 |
| 014209 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:09pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596025.4 | 511980.5 | 72243 | 1.64041666667 | 14209 |
| 013812 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:10pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596024.8 | 511981.6 | 72245 | 1.64041666667 | 13812 |
| 012783 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:11pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596023.3 | 511982.0 | 72247 | 1.64041666667 | 12783 |
| 013935 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:12pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596022.0 | 511981.3 | 72249 | 1.64041666667 | 13935 |
| 014823 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:13pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596019.0 | 511980.2 | 72251 | 1.64041666667 | 14823 |
| 013996 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:14pm | Sensor | 1797-S0049-G-TJV.cor | 6835.5 | 1596016.8 | 511979.0 | 72253 | 1.64041666667 | 13996 |
| 015109 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:15pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1596014.7 | 511977.6 | 72255 | 1.64041666667 | 15109 |
| 012777 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:16pm | Sensor | 1797-S0049-G-TJV.cor | 6835.7 | 1596013.9 | 511976.7 | 72257 | 1.64041666667 | 12777 |
| 013514 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:17pm | Sensor | 1797-S0049-G-TJV.cor | 6835.9 | 1596013.8 | 511976.0 | 72259 | 1.64041666667 | 13514 |
| 012498 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1596012.2 | 511975.5 | 72261 | 1.64041666667 | 12498 |
| 013564 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1596009.7 | 511974.1 | 72263 | 1.64041666667 | 13564 |
| 016261 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1596007.3 | 511973.0 | 72265 | 1.64041666667 | 16261 |
| 018765 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1596005.3 | 511971.4 | 72267 | 1.64041666667 | 18765 |
| 022721 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:22pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1596002.8 | 511970.8 | 72269 | 1.64041666667 | 22721 |
| 022060 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:23pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596001.1 | 511969.4 | 72271 | 1.64041666667 | 22060 |
| 018565 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:24pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595999.1 | 511968.2 | 72273 | 1.64041666667 | 18565 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017691 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595997.5 | 511966.6 | 72275 | 1.64041666667 | 17691 |
| 016842 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:26pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595994.8 | 511965.3 | 72277 | 1.64041666667 | 16842 |
| 017020 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595992.0 | 511964.5 | 72279 | 1.64041666667 | 17020 |
| 017725 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595989.3 | 511963.1 | 72281 | 1.64041666667 | 17725 |
| 018651 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595986.8 | 511962.4 | 72283 | 1.64041666667 | 18651 |
| 019572 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595985.3 | 511961.2 | 72285 | 1.64041666667 | 19572 |
| 016833 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595982.8 | 511960.6 | 72287 | 1.64041666667 | 16833 |
| 015518 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595980.8 | 511959.1 | 72289 | 1.64041666667 | 15518 |
| 015099 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595978.3 | 511958.3 | 72291 | 1.64041666667 | 15099 |
| 015955 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595977.1 | 511956.4 | 72293 | 1.64041666667 | 15955 |
| 015868 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595975.4 | 511955.5 | 72295 | 1.64041666667 | 15868 |
| 015367 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595973.6 | 511953.7 | 72297 | 1.64041666667 | 15367 |
| 018361 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595971.5 | 511952.8 | 72299 | 1.64041666667 | 18361 |
| 017490 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595970.3 | 511951.9 | 72301 | 1.64041666667 | 17490 |
| 019282 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595968.7 | 511950.5 | 72303 | 1.64041666667 | 19282 |
| 019130 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595967.0 | 511948.7 | 72305 | 1.64041666667 | 19130 |
| 021402 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595965.6 | 511947.5 | 72307 | 1.64041666667 | 21402 |
| 019390 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595963.8 | 511946.1 | 72309 | 1.64041666667 | 19390 |
| 019787 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595961.7 | 511945.3 | 72311 | 1.64041666667 | 19787 |
| 021356 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595959.5 | 511944.7 | 72313 | 1.64041666667 | 21356 |
| 024209 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595958.2 | 511944.9 | 72315 | 1.64041666667 | 24209 |
| 021142 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.4 | 72316 | 1.64041666667 | 21142 |
| 022085 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.4 | 72319 | 1.64041666667 | 22085 |
| 019501 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.3 | 72320 | 1.64041666667 | 19501 |
| 018585 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.4 | 72323 | 1.64041666667 | 18585 |
| 019166 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.4 | 72325 | 1.64041666667 | 19166 |
| 019491 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.5 | 511944.4 | 72327 | 1.64041666667 | 19491 |
| 019303 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:52pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.6 | 511944.3 | 72329 | 1.64041666667 | 19303 |
| 021475 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.7 | 511944.3 | 72331 | 1.64041666667 | 21475 |
| 021209 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:54pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.6 | 511944.3 | 72333 | 1.64041666667 | 21209 |
| 022642 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.3 | 511944.2 | 72335 | 1.64041666667 | 22642 |
| 024890 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:56pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.2 | 511944.5 | 72337 | 1.64041666667 | 24890 |
| 026262 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.2 | 511944.4 | 72339 | 1.64041666667 | 26262 |
| 024715 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.3 | 511944.6 | 72341 | 1.64041666667 | 24715 |
| 026819 | 0 | GeoXH 6000 | 08/19/2015 | 03:43:59pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.3 | 511944.6 | 72343 | 1.64041666667 | 26819 |
| 026324 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:00pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.6 | 72345 | 1.64041666667 | 26324 |
| 025691 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.6 | 72347 | 1.64041666667 | 25691 |
| 024122 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:02pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.5 | 72349 | 1.64041666667 | 24122 |
| 027210 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.3 | 511944.4 | 72351 | 1.64041666667 | 27210 |
| 026572 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:04pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.3 | 511944.3 | 72353 | 1.64041666667 | 26572 |
| 027013 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:05pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.4 | 72355 | 1.64041666667 | 27013 |
| 025563 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.4 | 72357 | 1.64041666667 | 25563 |
| 026670 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.4 | 72359 | 1.64041666667 | 26670 |
| 025087 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:08pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.3 | 72361 | 1.64041666667 | 25087 |
| 026312 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.3 | 72363 | 1.64041666667 | 26312 |
| 026198 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:10pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.4 | 72365 | 1.64041666667 | 26198 |
| 026049 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.3 | 72367 | 1.64041666667 | 26049 |
| 027872 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.6 | 511944.3 | 72369 | 1.64041666667 | 27872 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 025748 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.6 | 511944.3 | 72371 | 1.64041666667 | 25748 |
| 025337 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.6 | 511944.3 | 72373 | 1.64041666667 | 25337 |
| 024184 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595957.6 | 511944.3 | 72375 | 1.64041666667 | 24184 |
| 027346 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.6 | 511944.4 | 72377 | 1.64041666667 | 27346 |
| 026906 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.6 | 511944.4 | 72379 | 1.64041666667 | 26906 |
| 025356 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.5 | 511944.4 | 72381 | 1.64041666667 | 25356 |
| 025809 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.5 | 511944.3 | 72383 | 1.64041666667 | 25809 |
| 028892 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.4 | 511944.2 | 72385 | 1.64041666667 | 28892 |
| 027563 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.4 | 511944.2 | 72387 | 1.64041666667 | 27563 |
| 026390 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:22pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72389 | 1.64041666667 | 26390 |
| 027087 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:23pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72391 | 1.64041666667 | 27087 |
| 028402 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:24pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72393 | 1.64041666667 | 28402 |
| 027560 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72395 | 1.64041666667 | 27560 |
| 026180 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72396 | 1.64041666667 | 26180 |
| 025475 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72399 | 1.64041666667 | 25475 |
| 026528 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72401 | 1.64041666667 | 26528 |
| 025562 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72403 | 1.64041666667 | 25562 |
| 024870 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.2 | 72405 | 1.64041666667 | 24870 |
| 025627 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.5 | 511944.2 | 72407 | 1.64041666667 | 25627 |
| 028187 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72409 | 1.64041666667 | 28187 |
| 027746 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72411 | 1.64041666667 | 27746 |
| 026376 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72413 | 1.64041666667 | 26376 |
| 027654 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72415 | 1.64041666667 | 27654 |
| 025903 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72416 | 1.64041666667 | 25903 |
| 025376 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.4 | 511944.2 | 72419 | 1.64041666667 | 25376 |
| 026354 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.3 | 511944.3 | 72421 | 1.64041666667 | 26354 |
| 027588 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595956.8 | 511944.4 | 72423 | 1.64041666667 | 27588 |
| 027927 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:39pm | Sensor | 1797-S0049-G-TJV.cor | 6835.7 | 1595956.0 | 511943.9 | 72424 | 1.64041666667 | 27927 |
| 026151 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:41pm | Sensor | 1797-S0049-G-TJV.cor | 6835.1 | 1595955.5 | 511943.2 | 72427 | 1.64041666667 | 26151 |
| 026848 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1595955.2 | 511942.3 | 72429 | 1.64041666667 | 26848 |
| 026092 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595954.6 | 511942.3 | 72431 | 1.64041666667 | 26092 |
| 025753 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595954.4 | 511942.4 | 72433 | 1.64041666667 | 25753 |
| 026898 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595954.8 | 511943.3 | 72435 | 1.64041666667 | 26898 |
| 027904 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1595955.6 | 511944.1 | 72437 | 1.64041666667 | 27904 |
| 025156 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1595954.9 | 511943.0 | 72439 | 1.64041666667 | 25156 |
| 024079 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595954.9 | 511942.9 | 72441 | 1.64041666667 | 24079 |
| 025009 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:49pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1595955.8 | 511944.0 | 72443 | 1.64041666667 | 25009 |
| 024192 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595956.2 | 511944.2 | 72445 | 1.64041666667 | 24192 |
| 025968 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595956.9 | 511944.2 | 72447 | 1.64041666667 | 25968 |
| 021282 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:52pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595956.9 | 511944.6 | 72449 | 1.64041666667 | 21282 |
| 019390 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595954.7 | 511944.0 | 72451 | 1.64041666667 | 19390 |
| 015797 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:54pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595952.6 | 511943.6 | 72453 | 1.64041666667 | 15797 |
| 014209 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595950.4 | 511942.6 | 72455 | 1.64041666667 | 14209 |
| 013422 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595948.5 | 511941.9 | 72457 | 1.64041666667 | 13422 |
| 014155 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595945.9 | 511940.1 | 72459 | 1.64041666667 | 14155 |
| 013229 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595943.1 | 511938.8 | 72461 | 1.64041666667 | 13229 |
| 014137 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595939.8 | 511937.9 | 72463 | 1.64041666667 | 14137 |
| 014214 | 0 | GeoXH 6000 | 08/19/2015 | 03:44:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595938.2 | 511936.1 | 72464 | 1.64041666667 | 14214 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013423 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595935.4 | 511934.6 | 72467 | 1.64041666667 | 13423 |
| 013946 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595933.6 | 511932.9 | 72468 | 1.64041666667 | 13946 |
| 011916 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595931.4 | 511931.0 | 72471 | 1.64041666667 | 11916 |
| 012489 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595929.4 | 511929.5 | 72472 | 1.64041666667 | 12489 |
| 012392 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595926.2 | 511926.4 | 72475 | 1.64041666667 | 12392 |
| 012458 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595923.8 | 511925.5 | 72477 | 1.64041666667 | 12458 |
| 013464 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595920.8 | 511924.5 | 72479 | 1.64041666667 | 13464 |
| 013086 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595919.0 | 511924.4 | 72481 | 1.64041666667 | 13086 |
| 011611 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595916.8 | 511923.8 | 72483 | 1.64041666667 | 11611 |
| 014122 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595917.3 | 511924.8 | 72485 | 1.64041666667 | 14122 |
| 012320 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595918.3 | 511923.0 | 72487 | 1.64041666667 | 12320 |
| 013490 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1595918.9 | 511920.6 | 72488 | 1.64041666667 | 13490 |
| 011922 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1595920.4 | 511919.1 | 72491 | 1.64041666667 | 11922 |
| 013930 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:13pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1595920.6 | 511918.7 | 72492 | 1.64041666667 | 13930 |
| 014312 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:15pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1595921.4 | 511916.4 | 72495 | 1.64041666667 | 14312 |
| 013598 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:16pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1595922.6 | 511914.6 | 72497 | 1.64041666667 | 13598 |
| 014169 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595923.7 | 511911.4 | 72499 | 1.64041666667 | 14169 |
| 014102 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:18pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595924.7 | 511909.0 | 72501 | 1.64041666667 | 14102 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595925.3 | 511908.2 | 72503 | 1.64041666667 | 12405 |
| 013301 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595925.4 | 511908.0 | 72505 | 1.64041666667 | 13301 |
| 011875 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1595923.1 | 511909.8 | 72507 | 1.64041666667 | 11875 |
| 011729 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1595923.3 | 511910.9 | 72508 | 1.64041666667 | 11729 |
| 012532 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1595921.6 | 511913.5 | 72511 | 1.64041666667 | 12532 |
| 013423 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:23pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1595921.0 | 511915.5 | 72512 | 1.64041666667 | 13423 |
| 012955 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:25pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1595921.2 | 511917.1 | 72515 | 1.64041666667 | 12955 |
| 012509 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:25pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1595921.3 | 511917.9 | 72516 | 1.64041666667 | 12509 |
| 012847 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1595923.3 | 511919.6 | 72519 | 1.64041666667 | 12847 |
| 013321 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595924.6 | 511921.6 | 72521 | 1.64041666667 | 13321 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595927.4 | 511923.6 | 72523 | 1.64041666667 | 12840 |
| 011880 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595929.6 | 511925.5 | 72525 | 1.64041666667 | 11880 |
| 012240 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595932.4 | 511927.4 | 72527 | 1.64041666667 | 12240 |
| 014010 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595934.9 | 511927.9 | 72528 | 1.64041666667 | 14010 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1595937.4 | 511929.2 | 72531 | 1.64041666667 | 12652 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:33pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1595939.4 | 511929.3 | 72532 | 1.64041666667 | 11953 |
| 013608 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595942.4 | 511930.5 | 72535 | 1.64041666667 | 13608 |
| 013344 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595944.9 | 511931.2 | 72536 | 1.64041666667 | 13344 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595947.5 | 511932.4 | 72539 | 1.64041666667 | 14538 |
| 016894 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595949.8 | 511933.4 | 72541 | 1.64041666667 | 16894 |
| 016043 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595953.2 | 511934.2 | 72543 | 1.64041666667 | 16043 |
| 017631 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595955.3 | 511935.9 | 72544 | 1.64041666667 | 17631 |
| 017187 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595958.4 | 511937.5 | 72547 | 1.64041666667 | 17187 |
| 020077 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595960.2 | 511939.4 | 72548 | 1.64041666667 | 20077 |
| 020199 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595963.7 | 511941.6 | 72551 | 1.64041666667 | 20199 |
| 023229 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595966.6 | 511942.3 | 72553 | 1.64041666667 | 23229 |
| 020777 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595969.8 | 511943.5 | 72555 | 1.64041666667 | 20777 |
| 022954 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595972.2 | 511943.7 | 72557 | 1.64041666667 | 22954 |
| 021638 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595975.1 | 511945.1 | 72559 | 1.64041666667 | 21638 |
| 023679 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:48pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595977.3 | 511945.8 | 72561 | 1.64041666667 | 23679 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 022090 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595979.6 | 511946.7 | 72563 | 1.64041666667 | 22090 |
| 020582 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595982.1 | 511947.6 | 72565 | 1.64041666667 | 20582 |
| 020385 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595984.5 | 511948.9 | 72567 | 1.64041666667 | 20385 |
| 023126 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595986.7 | 511950.7 | 72568 | 1.64041666667 | 23126 |
| 024201 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595989.5 | 511952.2 | 72571 | 1.64041666667 | 24201 |
| 021530 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595991.3 | 511953.5 | 72572 | 1.64041666667 | 21530 |
| 020712 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595993.7 | 511954.3 | 72575 | 1.64041666667 | 20712 |
| 016518 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595995.4 | 511955.9 | 72576 | 1.64041666667 | 16518 |
| 014779 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595998.6 | 511957.3 | 72579 | 1.64041666667 | 14779 |
| 015664 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596000.8 | 511958.4 | 72580 | 1.64041666667 | 15664 |
| 015886 | 0 | GeoXH 6000 | 08/19/2015 | 03:45:59pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1596004.6 | 511960.5 | 72583 | 1.64041666667 | 15886 |
| 014231 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596007.4 | 511962.0 | 72585 | 1.64041666667 | 14231 |
| 012738 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596009.5 | 511963.7 | 72587 | 1.64041666667 | 12738 |
| 014974 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596011.4 | 511964.5 | 72588 | 1.64041666667 | 14974 |
| 014333 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596011.3 | 511965.2 | 72591 | 1.64041666667 | 14333 |
| 013633 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596011.7 | 511965.4 | 72592 | 1.64041666667 | 13633 |
| 013638 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596013.6 | 511967.0 | 72595 | 1.64041666667 | 13638 |
| 015049 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596015.3 | 511968.4 | 72597 | 1.64041666667 | 15049 |
| 014082 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1596017.9 | 511970.5 | 72599 | 1.64041666667 | 14082 |
| 013570 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1596020.0 | 511971.7 | 72600 | 1.64041666667 | 13570 |
| 013832 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1596023.5 | 511973.1 | 72603 | 1.64041666667 | 13832 |
| 014048 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1596025.1 | 511974.2 | 72604 | 1.64041666667 | 14048 |
| 014522 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1596027.6 | 511974.0 | 72607 | 1.64041666667 | 14522 |
| 014640 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1596027.8 | 511974.3 | 72609 | 1.64041666667 | 14640 |
| 014430 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1596029.3 | 511972.6 | 72611 | 1.64041666667 | 14430 |
| 013717 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1596030.4 | 511970.5 | 72612 | 1.64041666667 | 13717 |
| 014259 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596030.8 | 511969.7 | 72615 | 1.64041666667 | 14259 |
| 014605 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596031.0 | 511969.6 | 72616 | 1.64041666667 | 14605 |
| 013941 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596030.7 | 511967.6 | 72619 | 1.64041666667 | 13941 |
| 015845 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596031.5 | 511965.7 | 72620 | 1.64041666667 | 15845 |
| 013801 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596031.6 | 511963.1 | 72623 | 1.64041666667 | 13801 |
| 013260 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596033.1 | 511961.6 | 72624 | 1.64041666667 | 13260 |
| 014265 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596034.7 | 511961.0 | 72627 | 1.64041666667 | 14265 |
| 015386 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596033.3 | 511960.9 | 72629 | 1.64041666667 | 15386 |
| 014196 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596032.0 | 511961.3 | 72631 | 1.64041666667 | 14196 |
| 014889 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596030.7 | 511962.9 | 72632 | 1.64041666667 | 14889 |
| 013862 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596029.7 | 511965.9 | 72635 | 1.64041666667 | 13862 |
| 013815 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596028.4 | 511967.0 | 72637 | 1.64041666667 | 13815 |
| 013653 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596025.4 | 511967.0 | 72639 | 1.64041666667 | 13653 |
| 014933 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596021.8 | 511966.6 | 72641 | 1.64041666667 | 14933 |
| 014023 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1596019.6 | 511965.2 | 72643 | 1.64041666667 | 14023 |
| 014726 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596017.1 | 511964.6 | 72644 | 1.64041666667 | 14726 |
| 013551 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596014.4 | 511962.4 | 72647 | 1.64041666667 | 13551 |
| 013947 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596012.3 | 511961.1 | 72649 | 1.64041666667 | 13947 |
| 012997 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596009.6 | 511959.2 | 72651 | 1.64041666667 | 12997 |
| 013749 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1596007.4 | 511957.4 | 72652 | 1.64041666667 | 13749 |
| 013967 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1596004.4 | 511955.7 | 72655 | 1.64041666667 | 13967 |
| 014681 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596002.8 | 511954.1 | 72656 | 1.64041666667 | 14681 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019030 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596000.0 | 511952.5 | 72659 | 1.64041666667 | 19030 |
| 020597 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595998.5 | 511951.0 | 72660 | 1.64041666667 | 20597 |
| 020989 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595995.5 | 511949.0 | 72663 | 1.64041666667 | 20989 |
| 021807 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595993.2 | 511947.0 | 72665 | 1.64041666667 | 21807 |
| 021502 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595990.8 | 511944.5 | 72667 | 1.64041666667 | 21502 |
| 0213 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595988.6 | 511942.9 | 72669 | 1.64041666667 | 213 |
| 020978 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595986.3 | 511941.4 | 72671 | 1.64041666667 | 20978 |
| 022344 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595983.9 | 511941.1 | 72673 | 1.64041666667 | 22344 |
| 020556 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595980.9 | 511940.1 | 72675 | 1.64041666667 | 20556 |
| 019749 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595978.6 | 511939.2 | 72676 | 1.64041666667 | 19749 |
| 019667 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595975.7 | 511938.0 | 72679 | 1.64041666667 | 19667 |
| 019376 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595973.5 | 511936.1 | 72680 | 1.64041666667 | 19376 |
| 020204 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595971.0 | 511934.6 | 72683 | 1.64041666667 | 20204 |
| 020651 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595969.3 | 511932.8 | 72685 | 1.64041666667 | 20651 |
| 021662 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595967.1 | 511931.8 | 72686 | 1.64041666667 | 21662 |
| 022665 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595964.7 | 511930.4 | 72688 | 1.64041666667 | 22665 |
| 022976 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:52pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595962.2 | 511929.8 | 72690 | 1.64041666667 | 22976 |
| 022214 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595959.9 | 511929.0 | 72692 | 1.64041666667 | 22214 |
| 019653 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.7 | 511927.0 | 72695 | 1.64041666667 | 19653 |
| 022523 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595954.4 | 511926.0 | 72696 | 1.64041666667 | 22523 |
| 023510 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595951.8 | 511923.8 | 72699 | 1.64041666667 | 23510 |
| 018837 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595949.5 | 511922.9 | 72700 | 1.64041666667 | 18837 |
| 013949 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595947.3 | 511921.0 | 72703 | 1.64041666667 | 13949 |
| 014047 | 0 | GeoXH 6000 | 08/19/2015 | 03:46:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595945.6 | 511920.3 | 72704 | 1.64041666667 | 14047 |
| 014341 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595943.8 | 511918.6 | 72707 | 1.64041666667 | 14341 |
| 013125 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595942.3 | 511916.9 | 72708 | 1.64041666667 | 13125 |
| 013631 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595939.7 | 511915.4 | 72710 | 1.64041666667 | 13631 |
| 012318 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595938.7 | 511913.8 | 72712 | 1.64041666667 | 12318 |
| 012229 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595936.1 | 511911.5 | 72715 | 1.64041666667 | 12229 |
| 012447 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595934.5 | 511909.8 | 72716 | 1.64041666667 | 12447 |
| 013492 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595931.6 | 511908.7 | 72719 | 1.64041666667 | 13492 |
| 012973 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595928.7 | 511907.5 | 72720 | 1.64041666667 | 12973 |
| 013773 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595927.2 | 511906.4 | 72723 | 1.64041666667 | 13773 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595925.3 | 511906.5 | 72724 | 1.64041666667 | 12803 |
| 013310 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595926.6 | 511906.3 | 72727 | 1.64041666667 | 13310 |
| 014187 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:12pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595927.4 | 511904.6 | 72729 | 1.64041666667 | 14187 |
| 013117 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595928.8 | 511902.6 | 72731 | 1.64041666667 | 13117 |
| 012459 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595929.1 | 511902.0 | 72732 | 1.64041666667 | 12459 |
| 011424 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1595929.2 | 511900.8 | 72735 | 1.64041666667 | 11424 |
| 013686 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595930.3 | 511898.8 | 72736 | 1.64041666667 | 13686 |
| 012271 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595930.8 | 511894.7 | 72739 | 1.64041666667 | 12271 |
| 013507 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595930.8 | 511894.3 | 72740 | 1.64041666667 | 13507 |
| 011717 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595930.1 | 511895.2 | 72743 | 1.64041666667 | 11717 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595929.4 | 511896.1 | 72744 | 1.64041666667 | 11959 |
| 013999 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595930.0 | 511898.5 | 72747 | 1.64041666667 | 13999 |
| 013370 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595929.8 | 511899.9 | 72748 | 1.64041666667 | 13370 |
| 014052 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595931.1 | 511902.8 | 72751 | 1.64041666667 | 14052 |
| 012993 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595933.4 | 511904.5 | 72753 | 1.64041666667 | 12993 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012938 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595935.8 | 511906.9 | 72755 | 1.64041666667 | 12938 |
| 012894 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595937.7 | 511907.6 | 72756 | 1.64041666667 | 12894 |
| 013753 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595940.6 | 511908.8 | 72759 | 1.64041666667 | 13753 |
| 013098 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595943.0 | 511908.9 | 72761 | 1.64041666667 | 13098 |
| 013474 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595946.0 | 511908.9 | 72763 | 1.64041666667 | 13474 |
| 013658 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595948.2 | 511909.5 | 72765 | 1.64041666667 | 13658 |
| 013494 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595950.2 | 511910.5 | 72766 | 1.64041666667 | 13494 |
| 017803 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595951.9 | 511912.7 | 72768 | 1.64041666667 | 17803 |
| 019511 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595954.0 | 511914.1 | 72770 | 1.64041666667 | 19511 |
| 019007 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595955.1 | 511916.0 | 72772 | 1.64041666667 | 19007 |
| 018971 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595957.2 | 511917.6 | 72774 | 1.64041666667 | 18971 |
| 020826 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595958.4 | 511920.0 | 72776 | 1.64041666667 | 20826 |
| 019658 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595960.8 | 511921.8 | 72779 | 1.64041666667 | 19658 |
| 018234 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595962.6 | 511922.6 | 72780 | 1.64041666667 | 18234 |
| 016108 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595965.3 | 511923.8 | 72782 | 1.64041666667 | 16108 |
| 018157 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595967.8 | 511924.4 | 72784 | 1.64041666667 | 18157 |
| 020469 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595969.8 | 511926.2 | 72786 | 1.64041666667 | 20469 |
| 020897 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595972.1 | 511927.1 | 72788 | 1.64041666667 | 20897 |
| 018274 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595974.3 | 511928.9 | 72790 | 1.64041666667 | 18274 |
| 016388 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595977.0 | 511929.6 | 72792 | 1.64041666667 | 16388 |
| 017867 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595979.1 | 511930.8 | 72794 | 1.64041666667 | 17867 |
| 016526 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595982.0 | 511931.0 | 72796 | 1.64041666667 | 16526 |
| 016881 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595984.9 | 511931.8 | 72798 | 1.64041666667 | 16881 |
| 016340 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595987.7 | 511933.2 | 72800 | 1.64041666667 | 16340 |
| 016505 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595990.4 | 511934.5 | 72803 | 1.64041666667 | 16505 |
| 017956 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595992.6 | 511936.1 | 72804 | 1.64041666667 | 17956 |
| 017239 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595995.4 | 511936.8 | 72806 | 1.64041666667 | 17239 |
| 018919 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595997.7 | 511938.2 | 72808 | 1.64041666667 | 18919 |
| 021980 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1596000.7 | 511940.5 | 72811 | 1.64041666667 | 21980 |
| 019475 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596003.0 | 511941.5 | 72812 | 1.64041666667 | 19475 |
| 016718 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596006.0 | 511943.4 | 72815 | 1.64041666667 | 16718 |
| 015849 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596008.0 | 511944.3 | 72816 | 1.64041666667 | 15849 |
| 017102 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596010.9 | 511946.2 | 72819 | 1.64041666667 | 17102 |
| 016215 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596013.0 | 511946.9 | 72820 | 1.64041666667 | 16215 |
| 015333 | 0 | GeoXH 6000 | 08/19/2015 | 03:47:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596016.0 | 511948.5 | 72823 | 1.64041666667 | 15333 |
| 014753 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596018.4 | 511950.6 | 72825 | 1.64041666667 | 14753 |
| 014338 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596020.8 | 511951.5 | 72827 | 1.64041666667 | 14338 |
| 014594 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596022.8 | 511953.1 | 72828 | 1.64041666667 | 14594 |
| 014118 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596025.5 | 511954.2 | 72830 | 1.64041666667 | 14118 |
| 014659 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596027.9 | 511955.8 | 72832 | 1.64041666667 | 14659 |
| 013444 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596030.8 | 511957.2 | 72835 | 1.64041666667 | 13444 |
| 013711 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596033.3 | 511958.3 | 72836 | 1.64041666667 | 13711 |
| 014767 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596035.0 | 511960.8 | 72839 | 1.64041666667 | 14767 |
| 014792 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596034.1 | 511960.5 | 72840 | 1.64041666667 | 14792 |
| 015188 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596033.5 | 511960.4 | 72843 | 1.64041666667 | 15188 |
| 016307 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596033.2 | 511959.0 | 72844 | 1.64041666667 | 16307 |
| 015296 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596033.7 | 511956.5 | 72846 | 1.64041666667 | 15296 |
| 013364 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596033.8 | 511954.3 | 72848 | 1.64041666667 | 13364 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016751 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:12pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596034.2 | 511953.5 | 72850 | 1.64041666667 | 16751 |
| 015137 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596033.9 | 511953.6 | 72852 | 1.64041666667 | 15137 |
| 013534 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596035.0 | 511953.2 | 72855 | 1.64041666667 | 13534 |
| 013913 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596036.0 | 511951.0 | 72856 | 1.64041666667 | 13913 |
| 013558 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596038.4 | 511948.5 | 72859 | 1.64041666667 | 13558 |
| 014669 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596039.9 | 511946.1 | 72860 | 1.64041666667 | 14669 |
| 014107 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:18pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596040.3 | 511945.7 | 72862 | 1.64041666667 | 14107 |
| 014416 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596040.4 | 511945.6 | 72864 | 1.64041666667 | 14416 |
| 015274 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596040.4 | 511945.5 | 72867 | 1.64041666667 | 15274 |
| 016388 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596039.1 | 511946.6 | 72869 | 1.64041666667 | 16388 |
| 013247 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596039.5 | 511946.4 | 72870 | 1.64041666667 | 13247 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:23pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1596040.7 | 511945.5 | 72872 | 1.64041666667 | 13931 |
| 015393 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1596040.8 | 511945.3 | 72875 | 1.64041666667 | 15393 |
| 015218 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1596040.7 | 511945.3 | 72876 | 1.64041666667 | 15218 |
| 014934 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596038.0 | 511946.6 | 72879 | 1.64041666667 | 14934 |
| 015193 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596037.8 | 511947.7 | 72880 | 1.64041666667 | 15193 |
| 014058 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596036.3 | 511949.4 | 72883 | 1.64041666667 | 14058 |
| 013234 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596035.5 | 511950.6 | 72884 | 1.64041666667 | 13234 |
| 013838 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596034.2 | 511951.3 | 72887 | 1.64041666667 | 13838 |
| 012279 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596033.9 | 511952.4 | 72888 | 1.64041666667 | 12279 |
| 014230 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596032.7 | 511951.4 | 72891 | 1.64041666667 | 14230 |
| 013607 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596030.9 | 511950.9 | 72892 | 1.64041666667 | 13607 |
| 013691 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596028.6 | 511949.3 | 72895 | 1.64041666667 | 13691 |
| 014433 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596026.4 | 511948.5 | 72896 | 1.64041666667 | 14433 |
| 015308 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596023.9 | 511946.5 | 72898 | 1.64041666667 | 15308 |
| 014477 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596021.5 | 511945.1 | 72900 | 1.64041666667 | 14477 |
| 014839 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596018.2 | 511942.9 | 72903 | 1.64041666667 | 14839 |
| 013729 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596016.0 | 511941.5 | 72904 | 1.64041666667 | 13729 |
| 012912 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596013.2 | 511940.5 | 72906 | 1.64041666667 | 12912 |
| 016068 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596011.0 | 511938.9 | 72908 | 1.64041666667 | 16068 |
| 016827 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596008.0 | 511938.0 | 72910 | 1.64041666667 | 16827 |
| 019986 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596005.6 | 511937.0 | 72912 | 1.64041666667 | 19986 |
| 020656 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596002.5 | 511935.3 | 72914 | 1.64041666667 | 20656 |
| 020494 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596000.0 | 511934.3 | 72916 | 1.64041666667 | 20494 |
| 018293 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595997.8 | 511932.2 | 72918 | 1.64041666667 | 18293 |
| 017293 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595995.3 | 511931.1 | 72920 | 1.64041666667 | 17293 |
| 019053 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595992.7 | 511929.5 | 72922 | 1.64041666667 | 19053 |
| 017513 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595990.3 | 511928.2 | 72924 | 1.64041666667 | 17513 |
| 017278 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595987.5 | 511926.9 | 72926 | 1.64041666667 | 17278 |
| 017099 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595984.8 | 511924.9 | 72928 | 1.64041666667 | 17099 |
| 016725 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595982.2 | 511923.8 | 72930 | 1.64041666667 | 16725 |
| 017051 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595980.8 | 511922.0 | 72932 | 1.64041666667 | 17051 |
| 018602 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595978.5 | 511920.1 | 72935 | 1.64041666667 | 18602 |
| 018300 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595976.9 | 511918.5 | 72936 | 1.64041666667 | 18300 |
| 017265 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:56pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595973.9 | 511917.6 | 72938 | 1.64041666667 | 17265 |
| 017186 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595971.4 | 511916.7 | 72940 | 1.64041666667 | 17186 |
| 014586 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:58pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595968.6 | 511915.0 | 72942 | 1.64041666667 | 14586 |
| 015586 | 0 | GeoXH 6000 | 08/19/2015 | 03:48:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595966.2 | 511914.0 | 72944 | 1.64041666667 | 15586 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017486 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595963.6 | 511912.2 | 72946 | 1.64041666667 | 17486 |
| 016971 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595960.9 | 511911.4 | 72948 | 1.64041666667 | 16971 |
| 017203 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:02pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595958.1 | 511910.1 | 72950 | 1.64041666667 | 17203 |
| 018280 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595955.1 | 511908.1 | 72952 | 1.64041666667 | 18280 |
| 014830 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595952.0 | 511906.9 | 72955 | 1.64041666667 | 14830 |
| 013637 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595950.4 | 511905.8 | 72956 | 1.64041666667 | 13637 |
| 012949 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595947.8 | 511905.1 | 72959 | 1.64041666667 | 12949 |
| 012387 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595945.7 | 511903.9 | 72960 | 1.64041666667 | 12387 |
| 012397 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595942.7 | 511902.4 | 72963 | 1.64041666667 | 12397 |
| 012309 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595940.5 | 511901.0 | 72964 | 1.64041666667 | 12309 |
| 013037 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595938.3 | 511899.1 | 72966 | 1.64041666667 | 13037 |
| 011089 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595935.8 | 511897.8 | 72968 | 1.64041666667 | 11089 |
| 011682 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:12pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595933.4 | 511895.8 | 72970 | 1.64041666667 | 11682 |
| 013120 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595930.5 | 511894.2 | 72972 | 1.64041666667 | 13120 |
| 012940 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:14pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595930.4 | 511894.2 | 72974 | 1.64041666667 | 12940 |
| 012925 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595931.7 | 511892.4 | 72976 | 1.64041666667 | 12925 |
| 013011 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595931.8 | 511889.9 | 72978 | 1.64041666667 | 13011 |
| 013812 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595932.0 | 511888.8 | 72980 | 1.64041666667 | 13812 |
| 013503 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:18pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595932.7 | 511888.8 | 72982 | 1.64041666667 | 13503 |
| 012075 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595933.5 | 511886.2 | 72984 | 1.64041666667 | 12075 |
| 011928 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595934.9 | 511882.4 | 72987 | 1.64041666667 | 11928 |
| 011832 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595935.4 | 511880.2 | 72988 | 1.64041666667 | 11832 |
| 012318 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595934.9 | 511880.7 | 72991 | 1.64041666667 | 12318 |
| 013849 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595933.5 | 511881.8 | 72992 | 1.64041666667 | 13849 |
| 012792 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595933.4 | 511883.9 | 72994 | 1.64041666667 | 12792 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595933.0 | 511886.3 | 72996 | 1.64041666667 | 12378 |
| 012004 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595933.7 | 511889.0 | 72999 | 1.64041666667 | 12004 |
| 014191 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595934.8 | 511889.9 | 73000 | 1.64041666667 | 14191 |
| 015127 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595937.8 | 511892.2 | 73003 | 1.64041666667 | 15127 |
| 013892 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595940.2 | 511893.0 | 73005 | 1.64041666667 | 13892 |
| 013493 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595942.4 | 511894.4 | 73007 | 1.64041666667 | 13493 |
| 012793 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:32pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1595945.1 | 511894.8 | 73009 | 1.64041666667 | 12793 |
| 015348 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:33pm | Sensor | 1797-S0049-G-TJV.cor | 6838.4 | 1595946.8 | 511896.1 | 73011 | 1.64041666667 | 15348 |
| 013017 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:33pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1595949.0 | 511896.1 | 73012 | 1.64041666667 | 13017 |
| 013814 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595950.8 | 511897.4 | 73015 | 1.64041666667 | 13814 |
| 014733 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595953.2 | 511898.1 | 73016 | 1.64041666667 | 14733 |
| 012773 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595955.7 | 511899.4 | 73019 | 1.64041666667 | 12773 |
| 013873 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595958.1 | 511900.9 | 73020 | 1.64041666667 | 13873 |
| 016968 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595961.4 | 511901.6 | 73023 | 1.64041666667 | 16968 |
| 016212 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595963.3 | 511903.3 | 73024 | 1.64041666667 | 16212 |
| 014043 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595965.7 | 511904.2 | 73026 | 1.64041666667 | 14043 |
| 016050 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595967.6 | 511905.5 | 73028 | 1.64041666667 | 16050 |
| 017662 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595970.8 | 511906.9 | 73031 | 1.64041666667 | 17662 |
| 019025 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595972.4 | 511907.9 | 73032 | 1.64041666667 | 19025 |
| 017656 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595975.6 | 511910.0 | 73035 | 1.64041666667 | 17656 |
| 018184 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595978.0 | 511911.0 | 73036 | 1.64041666667 | 18184 |
| 017206 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595980.4 | 511912.8 | 73038 | 1.64041666667 | 17206 |
| 017291 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595982.7 | 511914.0 | 73040 | 1.64041666667 | 17291 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016983 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595985.3 | 511915.9 | 73042 | 1.64041666667 | 16983 |
| 018255 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595987.8 | 511917.9 | 73044 | 1.64041666667 | 18255 |
| 017433 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595990.9 | 511919.0 | 73046 | 1.64041666667 | 17433 |
| 016238 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595993.2 | 511920.6 | 73048 | 1.64041666667 | 16238 |
| 016029 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595996.4 | 511921.5 | 73050 | 1.64041666667 | 16029 |
| 018287 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595998.8 | 511922.9 | 73052 | 1.64041666667 | 18287 |
| 017621 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596001.9 | 511925.0 | 73054 | 1.64041666667 | 17621 |
| 016645 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596004.4 | 511925.9 | 73056 | 1.64041666667 | 16645 |
| 018651 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596007.0 | 511927.8 | 73058 | 1.64041666667 | 18651 |
| 016152 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596009.5 | 511928.7 | 73060 | 1.64041666667 | 16152 |
| 014508 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:58pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596012.6 | 511930.3 | 73062 | 1.64041666667 | 14508 |
| 014907 | 0 | GeoXH 6000 | 08/19/2015 | 03:49:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596015.2 | 511932.1 | 73064 | 1.64041666667 | 14907 |
| 014526 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596018.1 | 511933.4 | 73066 | 1.64041666667 | 14526 |
| 013441 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596020.3 | 511935.1 | 73068 | 1.64041666667 | 13441 |
| 014070 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596023.3 | 511936.6 | 73071 | 1.64041666667 | 14070 |
| 014797 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596026.3 | 511937.8 | 73072 | 1.64041666667 | 14797 |
| 014439 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:04pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596028.5 | 511939.5 | 73074 | 1.64041666667 | 14439 |
| 014680 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596030.7 | 511940.6 | 73076 | 1.64041666667 | 14680 |
| 016060 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596033.2 | 511942.8 | 73078 | 1.64041666667 | 16060 |
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596035.5 | 511944.5 | 73080 | 1.64041666667 | 13795 |
| 015358 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596038.4 | 511945.0 | 73082 | 1.64041666667 | 15358 |
| 015509 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596039.6 | 511944.7 | 73084 | 1.64041666667 | 15509 |
| 015157 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596039.2 | 511945.0 | 73086 | 1.64041666667 | 15157 |
| 016029 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596040.4 | 511943.3 | 73088 | 1.64041666667 | 16029 |
| 014957 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:12pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596041.8 | 511940.0 | 73090 | 1.64041666667 | 14957 |
| 015679 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596042.7 | 511939.1 | 73092 | 1.64041666667 | 15679 |
| 014989 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:14pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596042.8 | 511938.8 | 73094 | 1.64041666667 | 14989 |
| 014397 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596043.4 | 511936.0 | 73096 | 1.64041666667 | 14397 |
| 013319 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:16pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596044.6 | 511932.0 | 73098 | 1.64041666667 | 13319 |
| 014310 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596045.8 | 511930.7 | 73100 | 1.64041666667 | 14310 |
| 016507 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596046.1 | 511930.2 | 73102 | 1.64041666667 | 16507 |
| 015976 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596046.2 | 511930.2 | 73104 | 1.64041666667 | 15976 |
| 014584 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596046.3 | 511930.2 | 73106 | 1.64041666667 | 14584 |
| 015556 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:21pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596045.0 | 511931.5 | 73108 | 1.64041666667 | 15556 |
| 014359 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:22pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596044.4 | 511932.0 | 73110 | 1.64041666667 | 14359 |
| 014629 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:23pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596044.2 | 511932.0 | 73112 | 1.64041666667 | 14629 |
| 015867 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:24pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596045.0 | 511931.6 | 73114 | 1.64041666667 | 15867 |
| 013327 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:25pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596044.7 | 511933.0 | 73116 | 1.64041666667 | 13327 |
| 013921 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596044.2 | 511935.8 | 73118 | 1.64041666667 | 13921 |
| 015150 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596042.8 | 511937.7 | 73120 | 1.64041666667 | 15150 |
| 014797 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596041.4 | 511939.0 | 73122 | 1.64041666667 | 14797 |
| 014919 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596039.0 | 511939.2 | 73124 | 1.64041666667 | 14919 |
| 015400 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596036.0 | 511938.1 | 73126 | 1.64041666667 | 15400 |
| 013930 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596033.2 | 511937.5 | 73128 | 1.64041666667 | 13930 |
| 014432 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596029.9 | 511935.9 | 73131 | 1.64041666667 | 14432 |
| 014558 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596027.1 | 511933.8 | 73132 | 1.64041666667 | 14558 |
| 014499 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596023.9 | 511932.9 | 73135 | 1.64041666667 | 14499 |
| 014095 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596022.0 | 511931.5 | 73136 | 1.64041666667 | 14095 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014023 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596019.1 | 511930.6 | 73138 | 1.64041666667 | 14023 |
| 015626 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596017.0 | 511929.4 | 73140 | 1.64041666667 | 15626 |
| 014826 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596014.2 | 511927.0 | 73142 | 1.64041666667 | 14826 |
| 014476 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596012.0 | 511925.7 | 73144 | 1.64041666667 | 14476 |
| 017749 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596009.5 | 511923.5 | 73146 | 1.64041666667 | 17749 |
| 017814 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596007.1 | 511922.5 | 73148 | 1.64041666667 | 17814 |
| 017062 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596004.8 | 511920.7 | 73150 | 1.64041666667 | 17062 |
| 015185 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596002.2 | 511919.6 | 73152 | 1.64041666667 | 15185 |
| 015736 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595998.6 | 511918.7 | 73154 | 1.64041666667 | 15736 |
| 017674 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595996.5 | 511917.2 | 73156 | 1.64041666667 | 17674 |
| 018968 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595993.8 | 511915.8 | 73158 | 1.64041666667 | 18968 |
| 017582 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595991.8 | 511914.2 | 73160 | 1.64041666667 | 17582 |
| 018615 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595989.1 | 511912.3 | 73162 | 1.64041666667 | 18615 |
| 018423 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595986.8 | 511910.6 | 73164 | 1.64041666667 | 18423 |
| 018406 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595984.5 | 511908.5 | 73166 | 1.64041666667 | 18406 |
| 016961 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595982.1 | 511907.1 | 73168 | 1.64041666667 | 16961 |
| 019060 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:52pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595979.9 | 511905.1 | 73170 | 1.64041666667 | 19060 |
| 021445 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595977.7 | 511903.3 | 73172 | 1.64041666667 | 21445 |
| 024951 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:54pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595975.0 | 511901.4 | 73174 | 1.64041666667 | 24951 |
| 024387 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595973.0 | 511899.7 | 73176 | 1.64041666667 | 24387 |
| 021727 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:56pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595970.2 | 511898.8 | 73178 | 1.64041666667 | 21727 |
| 017371 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595968.1 | 511897.7 | 73180 | 1.64041666667 | 17371 |
| 014542 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595964.7 | 511896.5 | 73182 | 1.64041666667 | 14542 |
| 012695 | 0 | GeoXH 6000 | 08/19/2015 | 03:50:59pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595962.7 | 511895.3 | 73184 | 1.64041666667 | 12695 |
| 014184 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:00pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595959.5 | 511892.8 | 73186 | 1.64041666667 | 14184 |
| 014436 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595957.2 | 511891.8 | 73188 | 1.64041666667 | 14436 |
| 014169 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:02pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595954.9 | 511889.8 | 73190 | 1.64041666667 | 14169 |
| 013442 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595952.7 | 511888.5 | 73192 | 1.64041666667 | 13442 |
| 012540 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:04pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595950.2 | 511887.2 | 73194 | 1.64041666667 | 12540 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1595949.0 | 511885.9 | 73196 | 1.64041666667 | 12975 |
| 012753 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595946.9 | 511885.0 | 73198 | 1.64041666667 | 12753 |
| 012788 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595944.9 | 511883.9 | 73200 | 1.64041666667 | 12788 |
| 012647 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595941.6 | 511883.4 | 73203 | 1.64041666667 | 12647 |
| 013061 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595939.2 | 511882.6 | 73204 | 1.64041666667 | 13061 |
| 012505 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595936.8 | 511881.3 | 73206 | 1.64041666667 | 12505 |
| 013146 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595935.0 | 511879.6 | 73208 | 1.64041666667 | 13146 |
| 011746 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595934.0 | 511878.8 | 73210 | 1.64041666667 | 11746 |
| 013136 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595934.7 | 511879.6 | 73212 | 1.64041666667 | 13136 |
| 011924 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:14pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595936.1 | 511877.6 | 73214 | 1.64041666667 | 11924 |
| 013091 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595935.9 | 511874.8 | 73216 | 1.64041666667 | 13091 |
| 013142 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:16pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595936.4 | 511874.6 | 73218 | 1.64041666667 | 13142 |
| 013095 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595936.9 | 511874.2 | 73220 | 1.64041666667 | 13095 |
| 013263 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595936.9 | 511872.0 | 73222 | 1.64041666667 | 13263 |
| 013726 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595938.3 | 511869.6 | 73224 | 1.64041666667 | 13726 |
| 014711 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595939.5 | 511866.4 | 73226 | 1.64041666667 | 14711 |
| 012978 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595939.6 | 511865.8 | 73228 | 1.64041666667 | 12978 |
| 014044 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595937.5 | 511866.8 | 73230 | 1.64041666667 | 14044 |
| 014161 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595938.2 | 511867.5 | 73232 | 1.64041666667 | 14161 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012990 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595937.2 | 511868.6 | 73234 | 1.64041666667 | 12990 |
| 013567 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595936.1 | 511870.4 | 73236 | 1.64041666667 | 13567 |
| 013172 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595935.9 | 511872.2 | 73238 | 1.64041666667 | 13172 |
| 012953 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595936.8 | 511873.8 | 73240 | 1.64041666667 | 12953 |
| 011848 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595939.4 | 511875.1 | 73242 | 1.64041666667 | 11848 |
| 012682 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595941.4 | 511877.0 | 73244 | 1.64041666667 | 12682 |
| 013250 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595944.2 | 511879.0 | 73246 | 1.64041666667 | 13250 |
| 014442 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595946.8 | 511880.3 | 73248 | 1.64041666667 | 14442 |
| 013000 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595949.2 | 511881.6 | 73250 | 1.64041666667 | 13000 |
| 013630 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595951.7 | 511881.6 | 73252 | 1.64041666667 | 13630 |
| 014207 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595954.1 | 511883.0 | 73254 | 1.64041666667 | 14207 |
| 015011 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595956.6 | 511884.5 | 73256 | 1.64041666667 | 15011 |
| 013113 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595960.0 | 511885.7 | 73258 | 1.64041666667 | 13113 |
| 013448 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595962.1 | 511887.1 | 73260 | 1.64041666667 | 13448 |
| 012872 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595964.6 | 511888.2 | 73262 | 1.64041666667 | 12872 |
| 014498 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595966.7 | 511890.1 | 73264 | 1.64041666667 | 14498 |
| 014904 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595969.2 | 511892.0 | 73266 | 1.64041666667 | 14904 |
| 019956 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595971.8 | 511893.4 | 73268 | 1.64041666667 | 19956 |
| 023259 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595973.9 | 511895.2 | 73270 | 1.64041666667 | 23259 |
| 025674 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595975.9 | 511895.7 | 73272 | 1.64041666667 | 25674 |
| 025138 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595977.7 | 511897.3 | 73274 | 1.64041666667 | 25138 |
| 023624 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595980.2 | 511898.4 | 73276 | 1.64041666667 | 23624 |
| 021026 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595981.8 | 511900.4 | 73278 | 1.64041666667 | 21026 |
| 018906 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595983.9 | 511901.1 | 73280 | 1.64041666667 | 18906 |
| 017836 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:48pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595986.8 | 511902.3 | 73282 | 1.64041666667 | 17836 |
| 019609 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595989.5 | 511903.8 | 73284 | 1.64041666667 | 19609 |
| 017802 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595992.5 | 511904.9 | 73287 | 1.64041666667 | 17802 |
| 018490 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595994.7 | 511906.4 | 73288 | 1.64041666667 | 18490 |
| 017552 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595997.5 | 511907.1 | 73290 | 1.64041666667 | 17552 |
| 019328 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595999.8 | 511908.7 | 73292 | 1.64041666667 | 19328 |
| 021512 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596002.8 | 511910.9 | 73294 | 1.64041666667 | 21512 |
| 019448 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596005.5 | 511911.5 | 73296 | 1.64041666667 | 19448 |
| 018632 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596008.1 | 511912.7 | 73298 | 1.64041666667 | 18632 |
| 018998 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596011.1 | 511913.5 | 73300 | 1.64041666667 | 18998 |
| 015399 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1596013.9 | 511915.3 | 73302 | 1.64041666667 | 15399 |
| 014380 | 0 | GeoXH 6000 | 08/19/2015 | 03:51:59pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1596017.0 | 511917.4 | 73304 | 1.64041666667 | 14380 |
| 013675 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596019.7 | 511918.6 | 73306 | 1.64041666667 | 13675 |
| 014877 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596022.0 | 511920.3 | 73308 | 1.64041666667 | 14877 |
| 014609 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596024.7 | 511921.7 | 73310 | 1.64041666667 | 14609 |
| 014782 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596027.6 | 511923.1 | 73312 | 1.64041666667 | 14782 |
| 015005 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:04pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596030.2 | 511925.1 | 73314 | 1.64041666667 | 15005 |
| 015271 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596033.0 | 511926.1 | 73316 | 1.64041666667 | 15271 |
| 015697 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596035.9 | 511928.1 | 73318 | 1.64041666667 | 15697 |
| 014484 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596038.9 | 511929.7 | 73320 | 1.64041666667 | 14484 |
| 016701 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596041.7 | 511930.3 | 73322 | 1.64041666667 | 16701 |
| 015215 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596044.5 | 511930.7 | 73324 | 1.64041666667 | 15215 |
| 016193 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596044.7 | 511930.2 | 73326 | 1.64041666667 | 16193 |
| 015628 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:11pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596045.9 | 511928.7 | 73328 | 1.64041666667 | 15628 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015847 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:12pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596047.1 | 511926.0 | 73330 | 1.64041666667 | 15847 |
| 015781 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:13pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596047.5 | 511925.2 | 73332 | 1.64041666667 | 15781 |
| 015375 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:14pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596047.7 | 511924.9 | 73334 | 1.64041666667 | 15375 |
| 014973 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:15pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596048.4 | 511922.7 | 73336 | 1.64041666667 | 14973 |
| 014033 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:16pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596049.9 | 511919.6 | 73338 | 1.64041666667 | 14033 |
| 013018 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596050.7 | 511917.7 | 73340 | 1.64041666667 | 13018 |
| 013814 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:18pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1596051.3 | 511916.9 | 73342 | 1.64041666667 | 13814 |
| 013353 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1596051.4 | 511916.7 | 73344 | 1.64041666667 | 13353 |
| 013058 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1596051.5 | 511916.6 | 73346 | 1.64041666667 | 13058 |
| 014004 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1596051.5 | 511916.5 | 73348 | 1.64041666667 | 14004 |
| 014571 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:23pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596050.7 | 511918.2 | 73351 | 1.64041666667 | 14571 |
| 014592 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:23pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596050.2 | 511918.8 | 73352 | 1.64041666667 | 14592 |
| 015978 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:24pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596049.9 | 511919.2 | 73354 | 1.64041666667 | 15978 |
| 013114 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:25pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596050.1 | 511918.4 | 73356 | 1.64041666667 | 13114 |
| 013898 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:26pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596050.6 | 511919.2 | 73358 | 1.64041666667 | 13898 |
| 016614 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:27pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596050.4 | 511921.2 | 73360 | 1.64041666667 | 16614 |
| 015853 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:28pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596050.0 | 511923.7 | 73362 | 1.64041666667 | 15853 |
| 016323 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:29pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596048.4 | 511925.3 | 73364 | 1.64041666667 | 16323 |
| 015270 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:30pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596046.2 | 511925.3 | 73366 | 1.64041666667 | 15270 |
| 014857 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596043.5 | 511924.9 | 73368 | 1.64041666667 | 14857 |
| 014244 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596039.7 | 511923.4 | 73370 | 1.64041666667 | 14244 |
| 015261 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596037.4 | 511921.7 | 73372 | 1.64041666667 | 15261 |
| 015215 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596034.1 | 511920.1 | 73374 | 1.64041666667 | 15215 |
| 015323 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596031.5 | 511918.3 | 73376 | 1.64041666667 | 15323 |
| 013731 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596028.4 | 511915.8 | 73378 | 1.64041666667 | 13731 |
| 013722 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596026.0 | 511914.7 | 73380 | 1.64041666667 | 13722 |
| 013360 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596023.4 | 511912.7 | 73382 | 1.64041666667 | 13360 |
| 015220 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596020.9 | 511911.5 | 73384 | 1.64041666667 | 15220 |
| 016165 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596017.9 | 511909.7 | 73386 | 1.64041666667 | 16165 |
| 014271 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596015.7 | 511907.7 | 73388 | 1.64041666667 | 14271 |
| 014697 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596013.0 | 511906.1 | 73390 | 1.64041666667 | 14697 |
| 015284 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596011.3 | 511904.4 | 73392 | 1.64041666667 | 15284 |
| 015101 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596008.4 | 511902.8 | 73394 | 1.64041666667 | 15101 |
| 015685 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596006.3 | 511901.7 | 73396 | 1.64041666667 | 15685 |
| 016821 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596002.9 | 511900.1 | 73398 | 1.64041666667 | 16821 |
| 017015 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596000.1 | 511899.9 | 73400 | 1.64041666667 | 17015 |
| 018893 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595997.4 | 511898.8 | 73402 | 1.64041666667 | 18893 |
| 020473 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595995.2 | 511897.9 | 73404 | 1.64041666667 | 20473 |
| 020628 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595992.5 | 511895.9 | 73406 | 1.64041666667 | 20628 |
| 021657 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595990.3 | 511894.4 | 73408 | 1.64041666667 | 21657 |
| 019454 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595987.2 | 511893.2 | 73410 | 1.64041666667 | 19454 |
| 018243 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595985.4 | 511891.0 | 73412 | 1.64041666667 | 18243 |
| 017700 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595982.9 | 511889.4 | 73414 | 1.64041666667 | 17700 |
| 018615 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595981.0 | 511887.8 | 73416 | 1.64041666667 | 18615 |
| 015933 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:56pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595978.0 | 511885.7 | 73418 | 1.64041666667 | 15933 |
| 014423 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595975.5 | 511884.4 | 73420 | 1.64041666667 | 14423 |
| 015396 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:58pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595972.7 | 511882.2 | 73422 | 1.64041666667 | 15396 |
| 015939 | 0 | GeoXH 6000 | 08/19/2015 | 03:52:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595970.4 | 511881.4 | 73424 | 1.64041666667 | 15939 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014604 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595967.5 | 511879.7 | 73426 | 1.64041666667 | 14604 |
| 013071 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595964.8 | 511877.8 | 73428 | 1.64041666667 | 13071 |
| 012267 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:02pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595961.6 | 511876.6 | 73430 | 1.64041666667 | 12267 |
| 013897 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595959.2 | 511875.0 | 73432 | 1.64041666667 | 13897 |
| 017274 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:04pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595956.6 | 511873.9 | 73434 | 1.64041666667 | 17274 |
| 015808 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:05pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595954.1 | 511872.0 | 73436 | 1.64041666667 | 15808 |
| 015562 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595951.1 | 511869.8 | 73438 | 1.64041666667 | 15562 |
| 016460 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595948.7 | 511869.2 | 73440 | 1.64041666667 | 16460 |
| 016385 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595946.2 | 511868.0 | 73442 | 1.64041666667 | 16385 |
| 015496 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595943.4 | 511867.4 | 73444 | 1.64041666667 | 15496 |
| 014704 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595940.1 | 511866.0 | 73446 | 1.64041666667 | 14704 |
| 014926 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595939.3 | 511865.6 | 73448 | 1.64041666667 | 14926 |
| 014231 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:12pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595939.9 | 511863.5 | 73450 | 1.64041666667 | 14231 |
| 016338 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595939.4 | 511861.0 | 73452 | 1.64041666667 | 16338 |
| 013594 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:14pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595939.5 | 511859.6 | 73454 | 1.64041666667 | 13594 |
| 014018 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595940.3 | 511859.6 | 73456 | 1.64041666667 | 14018 |
| 013614 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:16pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595940.7 | 511856.6 | 73458 | 1.64041666667 | 13614 |
| 013453 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595941.6 | 511854.7 | 73460 | 1.64041666667 | 13453 |
| 015843 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595942.3 | 511852.2 | 73462 | 1.64041666667 | 15843 |
| 013740 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595941.2 | 511852.7 | 73464 | 1.64041666667 | 13740 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595939.9 | 511854.0 | 73466 | 1.64041666667 | 14355 |
| 012228 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595939.0 | 511856.3 | 73468 | 1.64041666667 | 12228 |
| 011967 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595939.5 | 511859.1 | 73470 | 1.64041666667 | 11967 |
| 012763 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595941.2 | 511860.7 | 73472 | 1.64041666667 | 12763 |
| 015980 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595943.6 | 511862.5 | 73474 | 1.64041666667 | 15980 |
| 014255 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595946.4 | 511864.1 | 73476 | 1.64041666667 | 14255 |
| 014033 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595949.4 | 511865.9 | 73478 | 1.64041666667 | 14033 |
| 014218 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595951.5 | 511867.8 | 73480 | 1.64041666667 | 14218 |
| 014954 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595954.2 | 511868.6 | 73482 | 1.64041666667 | 14954 |
| 013428 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595956.7 | 511870.1 | 73484 | 1.64041666667 | 13428 |
| 014697 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595960.0 | 511871.3 | 73486 | 1.64041666667 | 14697 |
| 013724 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595963.0 | 511872.5 | 73488 | 1.64041666667 | 13724 |
| 014081 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595965.7 | 511874.4 | 73490 | 1.64041666667 | 14081 |
| 013900 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595968.2 | 511875.3 | 73492 | 1.64041666667 | 13900 |
| 014395 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595971.4 | 511876.8 | 73494 | 1.64041666667 | 14395 |
| 015568 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595974.3 | 511878.0 | 73496 | 1.64041666667 | 15568 |
| 015382 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595977.4 | 511878.8 | 73498 | 1.64041666667 | 15382 |
| 014495 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595979.8 | 511880.4 | 73500 | 1.64041666667 | 14495 |
| 015323 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595983.0 | 511882.0 | 73502 | 1.64041666667 | 15323 |
| 014661 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595985.5 | 511883.5 | 73504 | 1.64041666667 | 14661 |
| 014765 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595988.2 | 511885.3 | 73506 | 1.64041666667 | 14765 |
| 014491 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595991.2 | 511886.1 | 73508 | 1.64041666667 | 14491 |
| 014092 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595993.9 | 511887.6 | 73510 | 1.64041666667 | 14092 |
| 014083 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595996.4 | 511888.8 | 73512 | 1.64041666667 | 14083 |
| 015701 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596000.1 | 511890.2 | 73514 | 1.64041666667 | 15701 |
| 013855 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596002.0 | 511891.7 | 73516 | 1.64041666667 | 13855 |
| 014383 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596004.9 | 511893.1 | 73518 | 1.64041666667 | 14383 |
| 014906 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596007.5 | 511894.7 | 73520 | 1.64041666667 | 14906 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014886 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596010.4 | 511896.5 | 73522 | 1.64041666667 | 14886 |
| 014583 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596013.2 | 511897.8 | 73524 | 1.64041666667 | 14583 |
| 014392 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596015.9 | 511899.7 | 73526 | 1.64041666667 | 14392 |
| 013438 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596018.4 | 511901.0 | 73528 | 1.64041666667 | 13438 |
| 013379 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596021.5 | 511902.9 | 73530 | 1.64041666667 | 13379 |
| 014205 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:53pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596023.7 | 511904.6 | 73532 | 1.64041666667 | 14205 |
| 015791 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:54pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596026.5 | 511905.4 | 73534 | 1.64041666667 | 15791 |
| 014297 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:55pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596028.8 | 511906.9 | 73536 | 1.64041666667 | 14297 |
| 014434 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:57pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596031.8 | 511908.3 | 73539 | 1.64041666667 | 14434 |
| 016058 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:57pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596034.3 | 511909.1 | 73540 | 1.64041666667 | 16058 |
| 014964 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:58pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596036.9 | 511910.6 | 73542 | 1.64041666667 | 14964 |
| 013701 | 0 | GeoXH 6000 | 08/19/2015 | 03:53:59pm | Sensor | 1797-S0049-G-TJV.cor | 6838.4 | 1596039.6 | 511911.7 | 73544 | 1.64041666667 | 13701 |
| 013715 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:00pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596042.2 | 511913.3 | 73546 | 1.64041666667 | 13715 |
| 013178 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:01pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596044.4 | 511914.4 | 73548 | 1.64041666667 | 13178 |
| 012864 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:02pm | Sensor | 1797-S0049-G-TJV.cor | 6838.4 | 1596047.6 | 511915.8 | 73550 | 1.64041666667 | 12864 |
| 015726 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596049.8 | 511917.1 | 73552 | 1.64041666667 | 15726 |
| 014881 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:04pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596050.4 | 511916.6 | 73554 | 1.64041666667 | 14881 |
| 016290 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:05pm | Sensor | 1797-S0049-G-TJV.cor | 6838.4 | 1596051.6 | 511914.6 | 73556 | 1.64041666667 | 16290 |
| 017002 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:06pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596053.0 | 511913.3 | 73558 | 1.64041666667 | 17002 |
| 014570 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:07pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596053.2 | 511913.3 | 73560 | 1.64041666667 | 14570 |
| 015132 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:08pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596053.4 | 511911.1 | 73562 | 1.64041666667 | 15132 |
| 014013 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:09pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596054.4 | 511908.1 | 73564 | 1.64041666667 | 14013 |
| 014513 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:10pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596055.8 | 511906.0 | 73566 | 1.64041666667 | 14513 |
| 014938 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596056.0 | 511905.6 | 73568 | 1.64041666667 | 14938 |
| 014744 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:12pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596050.9 | 511905.6 | 73570 | 1.64041666667 | 14744 |
| 015686 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:13pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596055.6 | 511907.3 | 73572 | 1.64041666667 | 15686 |
| 015321 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:14pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596055.1 | 511908.9 | 73574 | 1.64041666667 | 15321 |
| 015470 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:15pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596053.9 | 511909.7 | 73576 | 1.64041666667 | 15470 |
| 014337 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:16pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596053.6 | 511911.3 | 73578 | 1.64041666667 | 14337 |
| 013634 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:17pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596053.8 | 511911.7 | 73580 | 1.64041666667 | 13634 |
| 015348 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:18pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596053.9 | 511911.7 | 73582 | 1.64041666667 | 15348 |
| 014607 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:19pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596052.5 | 511912.1 | 73584 | 1.64041666667 | 14607 |
| 014631 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:20pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596050.5 | 511911.1 | 73586 | 1.64041666667 | 14631 |
| 014878 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:21pm | Sensor | 1797-S0049-G-TJV.cor | 6838.4 | 1596047.9 | 511910.2 | 73588 | 1.64041666667 | 14878 |
| 013829 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:22pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596045.1 | 511909.0 | 73590 | 1.64041666667 | 13829 |
| 012727 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:23pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596042.4 | 511907.7 | 73592 | 1.64041666667 | 12727 |
| 014761 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:24pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596038.7 | 511906.7 | 73594 | 1.64041666667 | 14761 |
| 014760 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:25pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596036.7 | 511905.2 | 73596 | 1.64041666667 | 14760 |
| 013830 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:26pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596033.8 | 511903.5 | 73598 | 1.64041666667 | 13830 |
| 013447 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:27pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596031.4 | 511902.0 | 73600 | 1.64041666667 | 13447 |
| 014012 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:28pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596028.4 | 511900.0 | 73602 | 1.64041666667 | 14012 |
| 014153 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:29pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596025.6 | 511898.8 | 73604 | 1.64041666667 | 14153 |
| 014398 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:30pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596023.0 | 511897.0 | 73606 | 1.64041666667 | 14398 |
| 013679 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596020.0 | 511894.9 | 73608 | 1.64041666667 | 13679 |
| 014550 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:32pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596017.0 | 511893.7 | 73610 | 1.64041666667 | 14550 |
| 015127 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:33pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596014.6 | 511892.0 | 73612 | 1.64041666667 | 15127 |
| 016861 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596011.7 | 511890.7 | 73614 | 1.64041666667 | 16861 |
| 016575 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596009.1 | 511889.4 | 73616 | 1.64041666667 | 16575 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015363 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596006.2 | 511887.5 | 73618 | 1.64041666667 | 15363 |
| 013651 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596003.5 | 511886.5 | 73620 | 1.64041666667 | 13651 |
| 014482 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596000.3 | 511885.2 | 73622 | 1.64041666667 | 14482 |
| 015680 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595997.6 | 511884.3 | 73624 | 1.64041666667 | 15680 |
| 013820 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595994.0 | 511883.2 | 73626 | 1.64041666667 | 13820 |
| 015125 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595992.1 | 511881.4 | 73628 | 1.64041666667 | 15125 |
| 014551 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595989.9 | 511879.8 | 73630 | 1.64041666667 | 14551 |
| 014077 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595987.6 | 511878.0 | 73632 | 1.64041666667 | 14077 |
| 014139 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595984.9 | 511876.3 | 73634 | 1.64041666667 | 14139 |
| 015325 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595982.0 | 511875.2 | 73636 | 1.64041666667 | 15325 |
| 013521 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595979.3 | 511873.9 | 73638 | 1.64041666667 | 13521 |
| 014540 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595976.3 | 511873.2 | 73640 | 1.64041666667 | 14540 |
| 014015 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595973.6 | 511872.2 | 73642 | 1.64041666667 | 14015 |
| 013103 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595970.9 | 511871.2 | 73644 | 1.64041666667 | 13103 |
| 013116 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595967.8 | 511870.5 | 73646 | 1.64041666667 | 13116 |
| 014799 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595966.0 | 511868.6 | 73648 | 1.64041666667 | 14799 |
| 014259 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595963.5 | 511867.0 | 73650 | 1.64041666667 | 14259 |
| 012715 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595961.4 | 511865.3 | 73652 | 1.64041666667 | 12715 |
| 014038 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595958.7 | 511862.8 | 73654 | 1.64041666667 | 14038 |
| 015239 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595956.5 | 511861.6 | 73656 | 1.64041666667 | 15239 |
| 015000 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595953.9 | 511859.4 | 73658 | 1.64041666667 | 15000 |
| 015570 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595951.4 | 511858.3 | 73660 | 1.64041666667 | 15570 |
| 014482 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:58pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595948.6 | 511856.8 | 73662 | 1.64041666667 | 14482 |
| 013490 | 0 | GeoXH 6000 | 08/19/2015 | 03:54:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595946.4 | 511854.9 | 73664 | 1.64041666667 | 13490 |
| 014352 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595944.1 | 511853.3 | 73666 | 1.64041666667 | 14352 |
| 013998 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595942.4 | 511851.9 | 73668 | 1.64041666667 | 13998 |
| 014539 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595942.4 | 511851.9 | 73670 | 1.64041666667 | 14539 |
| 012784 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595943.3 | 511851.1 | 73672 | 1.64041666667 | 12784 |
| 013846 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:04pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595943.8 | 511848.4 | 73674 | 1.64041666667 | 13846 |
| 014591 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595944.6 | 511847.2 | 73676 | 1.64041666667 | 14591 |
| 013128 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595945.3 | 511846.3 | 73678 | 1.64041666667 | 13128 |
| 014562 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595945.1 | 511845.9 | 73680 | 1.64041666667 | 14562 |
| 014290 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595946.3 | 511843.7 | 73682 | 1.64041666667 | 14290 |
| 014192 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595947.1 | 511840.8 | 73684 | 1.64041666667 | 14192 |
| 013538 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:10pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595948.1 | 511839.2 | 73686 | 1.64041666667 | 13538 |
| 014694 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595948.4 | 511838.7 | 73688 | 1.64041666667 | 14694 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595948.7 | 511838.4 | 73690 | 1.64041666667 | 11953 |
| 011917 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595948.8 | 511838.2 | 73692 | 1.64041666667 | 11917 |
| 013414 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595948.6 | 511838.2 | 73694 | 1.64041666667 | 13414 |
| 014213 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:15pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595948.0 | 511838.8 | 73696 | 1.64041666667 | 14213 |
| 014263 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:16pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595947.6 | 511839.0 | 73698 | 1.64041666667 | 14263 |
| 013526 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1595948.3 | 511837.8 | 73700 | 1.64041666667 | 13526 |
| 015441 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:18pm | Sensor | 1797-S0049-G-TJV.cor | 6835.9 | 1595948.8 | 511837.9 | 73702 | 1.64041666667 | 15441 |
| 014270 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:19pm | Sensor | 1797-S0049-G-TJV.cor | 6835.8 | 1595949.0 | 511838.0 | 73704 | 1.64041666667 | 14270 |
| 013437 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:20pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595947.9 | 511838.2 | 73706 | 1.64041666667 | 13437 |
| 014219 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595946.1 | 511838.9 | 73708 | 1.64041666667 | 14219 |
| 013365 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595945.9 | 511840.9 | 73710 | 1.64041666667 | 13365 |
| 014171 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595945.3 | 511842.7 | 73712 | 1.64041666667 | 14171 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014312 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595945.6 | 511845.4 | 73714 | 1.64041666667 | 14312 |
| 013718 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595947.0 | 511847.0 | 73716 | 1.64041666667 | 13718 |
| 012279 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595949.5 | 511849.1 | 73718 | 1.64041666667 | 12279 |
| 014110 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595951.9 | 511849.8 | 73720 | 1.64041666667 | 14110 |
| 014537 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595954.3 | 511851.2 | 73722 | 1.64041666667 | 14537 |
| 013954 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595956.7 | 511851.8 | 73724 | 1.64041666667 | 13954 |
| 015158 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595959.0 | 511853.2 | 73726 | 1.64041666667 | 15158 |
| 013869 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595961.3 | 511853.9 | 73728 | 1.64041666667 | 13869 |
| 013817 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595963.7 | 511855.1 | 73730 | 1.64041666667 | 13817 |
| 012904 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595966.0 | 511855.8 | 73732 | 1.64041666667 | 12904 |
| 012616 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595968.4 | 511856.7 | 73734 | 1.64041666667 | 12616 |
| 012484 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595970.4 | 511858.4 | 73736 | 1.64041666667 | 12484 |
| 015391 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595973.2 | 511859.1 | 73738 | 1.64041666667 | 15391 |
| 014827 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595974.7 | 511860.7 | 73740 | 1.64041666667 | 14827 |
| 014117 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595977.0 | 511862.2 | 73742 | 1.64041666667 | 14117 |
| 014449 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595978.5 | 511863.9 | 73744 | 1.64041666667 | 14449 |
| 014922 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595981.0 | 511865.5 | 73746 | 1.64041666667 | 14922 |
| 012460 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595983.3 | 511866.8 | 73748 | 1.64041666667 | 12460 |
| 013225 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595985.9 | 511868.4 | 73750 | 1.64041666667 | 13225 |
| 014106 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595988.6 | 511869.1 | 73752 | 1.64041666667 | 14106 |
| 015226 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595990.8 | 511870.4 | 73754 | 1.64041666667 | 15226 |
| 014606 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595993.0 | 511871.2 | 73756 | 1.64041666667 | 14606 |
| 014271 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595995.8 | 511872.8 | 73758 | 1.64041666667 | 14271 |
| 013018 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595998.2 | 511874.8 | 73760 | 1.64041666667 | 13018 |
| 014594 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596001.2 | 511876.3 | 73762 | 1.64041666667 | 14594 |
| 015018 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596003.4 | 511878.1 | 73764 | 1.64041666667 | 15018 |
| 015304 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596006.0 | 511880.0 | 73766 | 1.64041666667 | 15304 |
| 014776 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596008.0 | 511881.8 | 73768 | 1.64041666667 | 14776 |
| 017044 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596011.0 | 511884.1 | 73770 | 1.64041666667 | 17044 |
| 015301 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:53pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596013.4 | 511885.0 | 73772 | 1.64041666667 | 15301 |
| 015045 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:54pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596016.0 | 511886.6 | 73774 | 1.64041666667 | 15045 |
| 015491 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:55pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596018.7 | 511887.5 | 73776 | 1.64041666667 | 15491 |
| 015483 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:56pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596021.8 | 511889.2 | 73778 | 1.64041666667 | 15483 |
| 015120 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:57pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596024.4 | 511890.7 | 73780 | 1.64041666667 | 15120 |
| 015180 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:58pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596027.1 | 511891.9 | 73782 | 1.64041666667 | 15180 |
| 013665 | 0 | GeoXH 6000 | 08/19/2015 | 03:55:59pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596029.1 | 511893.5 | 73784 | 1.64041666667 | 13665 |
| 016466 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:00pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596032.2 | 511894.6 | 73786 | 1.64041666667 | 16466 |
| 015066 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:01pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596034.6 | 511895.5 | 73788 | 1.64041666667 | 15066 |
| 014596 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:02pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596037.6 | 511897.2 | 73790 | 1.64041666667 | 14596 |
| 013549 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:03pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596040.2 | 511898.4 | 73792 | 1.64041666667 | 13549 |
| 016167 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:04pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596042.9 | 511900.3 | 73794 | 1.64041666667 | 16167 |
| 015202 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:05pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596045.2 | 511901.4 | 73796 | 1.64041666667 | 15202 |
| 014690 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:06pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596048.4 | 511903.1 | 73798 | 1.64041666667 | 14690 |
| 014172 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:07pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596050.7 | 511904.6 | 73800 | 1.64041666667 | 14172 |
| 014073 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:08pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596053.6 | 511905.7 | 73802 | 1.64041666667 | 14073 |
| 015578 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:09pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596055.2 | 511906.0 | 73804 | 1.64041666667 | 15578 |
| 012834 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:10pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596054.8 | 511906.4 | 73806 | 1.64041666667 | 12834 |
| 013618 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:11pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596055.4 | 511906.0 | 73808 | 1.64041666667 | 13618 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014354 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:12pm | Sensor | 1797-S0049-G-TJV.cor | 6839.0 | 1596056.8 | 511903.8 | 73810 | 1.64041666667 | 14354 |
| 014568 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:13pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596058.1 | 511902.2 | 73812 | 1.64041666667 | 14568 |
| 015762 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:14pm | Sensor | 1797-S0049-G-TJV.cor | 6839.1 | 1596059.0 | 511901.4 | 73814 | 1.64041666667 | 15762 |
| 015250 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:15pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596060.0 | 511899.0 | 73816 | 1.64041666667 | 15250 |
| 015842 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:16pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596061.9 | 511896.3 | 73818 | 1.64041666667 | 15842 |
| 017160 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:17pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596063.2 | 511894.5 | 73820 | 1.64041666667 | 17160 |
| 016140 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:18pm | Sensor | 1797-S0049-G-TJV.cor | 6839.0 | 1596063.6 | 511893.7 | 73822 | 1.64041666667 | 16140 |
| 015315 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:19pm | Sensor | 1797-S0049-G-TJV.cor | 6839.8 | 1596062.9 | 511893.4 | 73824 | 1.64041666667 | 15315 |
| 015648 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:20pm | Sensor | 1797-S0049-G-TJV.cor | 6840.8 | 1596061.6 | 511894.9 | 73826 | 1.64041666667 | 15648 |
| 014862 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:21pm | Sensor | 1797-S0049-G-TJV.cor | 6839.7 | 1596061.9 | 511895.8 | 73828 | 1.64041666667 | 14862 |
| 015415 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:22pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596062.2 | 511895.8 | 73830 | 1.64041666667 | 15415 |
| 015854 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:23pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596063.2 | 511896.3 | 73832 | 1.64041666667 | 15854 |
| 014973 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:24pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596062.2 | 511897.5 | 73834 | 1.64041666667 | 14973 |
| 015353 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:25pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596060.6 | 511897.9 | 73836 | 1.64041666667 | 15353 |
| 015028 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:26pm | Sensor | 1797-S0049-G-TJV.cor | 6839.1 | 1596058.7 | 511899.7 | 73838 | 1.64041666667 | 15028 |
| 013417 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:27pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596056.8 | 511899.7 | 73840 | 1.64041666667 | 13417 |
| 014694 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:28pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596053.6 | 511898.3 | 73842 | 1.64041666667 | 14694 |
| 016303 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:29pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596051.1 | 511897.7 | 73844 | 1.64041666667 | 16303 |
| 017036 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:30pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596048.5 | 511896.0 | 73846 | 1.64041666667 | 17036 |
| 015899 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:31pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596046.1 | 511894.9 | 73848 | 1.64041666667 | 15899 |
| 015914 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:32pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596043.3 | 511892.8 | 73850 | 1.64041666667 | 15914 |
| 016008 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:33pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596041.0 | 511890.7 | 73852 | 1.64041666667 | 16008 |
| 015822 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:34pm | Sensor | 1797-S0049-G-TJV.cor | 6838.4 | 1596038.0 | 511889.2 | 73854 | 1.64041666667 | 15822 |
| 014485 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:35pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596036.0 | 511887.4 | 73856 | 1.64041666667 | 14485 |
| 015171 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:36pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596032.9 | 511885.8 | 73858 | 1.64041666667 | 15171 |
| 014862 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:37pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596030.7 | 511884.3 | 73860 | 1.64041666667 | 14862 |
| 016885 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:38pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596027.7 | 511881.7 | 73862 | 1.64041666667 | 16885 |
| 016041 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:39pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596025.5 | 511880.6 | 73864 | 1.64041666667 | 16041 |
| 014600 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:40pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596022.7 | 511878.8 | 73866 | 1.64041666667 | 14600 |
| 014630 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:41pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596020.5 | 511878.2 | 73868 | 1.64041666667 | 14630 |
| 014217 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596017.3 | 511877.4 | 73870 | 1.64041666667 | 14217 |
| 013724 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596014.9 | 511876.2 | 73872 | 1.64041666667 | 13724 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596011.9 | 511875.0 | 73874 | 1.64041666667 | 13811 |
| 014792 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596009.7 | 511873.2 | 73876 | 1.64041666667 | 14792 |
| 015188 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596006.9 | 511871.7 | 73878 | 1.64041666667 | 15188 |
| 014927 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596004.2 | 511870.5 | 73880 | 1.64041666667 | 14927 |
| 016121 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596001.4 | 511868.8 | 73882 | 1.64041666667 | 16121 |
| 017800 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595998.6 | 511868.0 | 73884 | 1.64041666667 | 17800 |
| 015850 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595995.3 | 511866.8 | 73886 | 1.64041666667 | 15850 |
| 014522 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595992.7 | 511865.6 | 73888 | 1.64041666667 | 14522 |
| 016560 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595989.2 | 511863.9 | 73890 | 1.64041666667 | 16560 |
| 012660 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595987.0 | 511862.0 | 73892 | 1.64041666667 | 12660 |
| 013485 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595984.2 | 511860.0 | 73894 | 1.64041666667 | 13485 |
| 013031 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595981.4 | 511858.2 | 73896 | 1.64041666667 | 13031 |
| 013098 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595979.0 | 511856.1 | 73898 | 1.64041666667 | 13098 |
| 013174 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595976.7 | 511854.7 | 73900 | 1.64041666667 | 13174 |
| 014483 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:58pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595974.2 | 511852.6 | 73902 | 1.64041666667 | 14483 |
| 014181 | 0 | GeoXH 6000 | 08/19/2015 | 03:56:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595971.9 | 511850.4 | 73904 | 1.64041666667 | 14181 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014225 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595969.1 | 511848.6 | 73906 | 1.64041666667 | 14225 |
| 015136 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595967.1 | 511847.0 | 73908 | 1.64041666667 | 15136 |
| 014794 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595964.6 | 511845.0 | 73910 | 1.64041666667 | 14794 |
| 015158 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595961.5 | 511843.4 | 73912 | 1.64041666667 | 15158 |
| 016509 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:04pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595958.8 | 511842.1 | 73914 | 1.64041666667 | 16509 |
| 014447 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595955.8 | 511841.7 | 73916 | 1.64041666667 | 14447 |
| 015341 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:06pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595952.8 | 511840.5 | 73918 | 1.64041666667 | 15341 |
| 014275 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:07pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595951.2 | 511839.3 | 73920 | 1.64041666667 | 14275 |
| 012569 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:08pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595948.4 | 511837.9 | 73922 | 1.64041666667 | 12569 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:09pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595948.6 | 511838.3 | 73924 | 1.64041666667 | 14602 |
| 014330 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595950.2 | 511837.0 | 73926 | 1.64041666667 | 14330 |
| 013452 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595951.0 | 511834.7 | 73928 | 1.64041666667 | 13452 |
| 014013 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:12pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595951.5 | 511833.3 | 73930 | 1.64041666667 | 14013 |
| 013913 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:13pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595951.9 | 511833.1 | 73932 | 1.64041666667 | 13913 |
| 013978 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595953.0 | 511831.7 | 73934 | 1.64041666667 | 13978 |
| 013994 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595954.8 | 511829.9 | 73936 | 1.64041666667 | 13994 |
| 013278 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595956.8 | 511827.6 | 73938 | 1.64041666667 | 13278 |
| 013549 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:17pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595957.2 | 511826.8 | 73940 | 1.64041666667 | 13549 |
| 014757 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:18pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595955.5 | 511827.7 | 73942 | 1.64041666667 | 14757 |
| 014039 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595954.5 | 511829.0 | 73944 | 1.64041666667 | 14039 |
| 012390 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:20pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595953.4 | 511831.1 | 73946 | 1.64041666667 | 12390 |
| 012517 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595954.2 | 511834.0 | 73948 | 1.64041666667 | 12517 |
| 014079 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595956.3 | 511836.4 | 73950 | 1.64041666667 | 14079 |
| 014289 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595958.1 | 511838.6 | 73952 | 1.64041666667 | 14289 |
| 014462 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595960.9 | 511840.6 | 73954 | 1.64041666667 | 14462 |
| 012705 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595962.9 | 511842.2 | 73956 | 1.64041666667 | 12705 |
| 013856 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595965.9 | 511844.6 | 73958 | 1.64041666667 | 13856 |
| 014984 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595968.3 | 511846.1 | 73960 | 1.64041666667 | 14984 |
| 013706 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595970.2 | 511848.0 | 73962 | 1.64041666667 | 13706 |
| 012576 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595972.8 | 511849.5 | 73964 | 1.64041666667 | 12576 |
| 012594 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595975.9 | 511851.0 | 73966 | 1.64041666667 | 12594 |
| 014968 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595978.1 | 511852.6 | 73968 | 1.64041666667 | 14968 |
| 014422 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595980.7 | 511854.1 | 73970 | 1.64041666667 | 14422 |
| 012995 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595983.0 | 511855.8 | 73972 | 1.64041666667 | 12995 |
| 012488 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595985.9 | 511857.7 | 73974 | 1.64041666667 | 12488 |
| 013682 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595988.7 | 511858.3 | 73976 | 1.64041666667 | 13682 |
| 014400 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595991.5 | 511859.4 | 73978 | 1.64041666667 | 14400 |
| 014340 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595994.1 | 511860.2 | 73980 | 1.64041666667 | 14340 |
| 013905 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595996.1 | 511862.1 | 73982 | 1.64041666667 | 13905 |
| 014846 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595998.2 | 511864.0 | 73984 | 1.64041666667 | 14846 |
| 016161 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596001.0 | 511865.6 | 73986 | 1.64041666667 | 16161 |
| 015470 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596003.4 | 511867.2 | 73988 | 1.64041666667 | 15470 |
| 015237 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596006.3 | 511868.4 | 73990 | 1.64041666667 | 15237 |
| 013979 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596008.6 | 511869.7 | 73992 | 1.64041666667 | 13979 |
| 015135 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596011.4 | 511871.2 | 73994 | 1.64041666667 | 15135 |
| 014283 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:45pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596014.3 | 511872.4 | 73996 | 1.64041666667 | 14283 |
| 014340 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:46pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596016.7 | 511874.0 | 73998 | 1.64041666667 | 14340 |
| 013665 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:47pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596019.4 | 511875.3 | 74000 | 1.64041666667 | 13665 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014936 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:48pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596022.2 | 511877.1 | 74002 | 1.64041666667 | 14936 |
| 013484 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:49pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596025.0 | 511879.0 | 74004 | 1.64041666667 | 13484 |
| 014321 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:50pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596028.0 | 511880.1 | 74006 | 1.64041666667 | 14321 |
| 014530 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:51pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596030.3 | 511881.6 | 74008 | 1.64041666667 | 14530 |
| 014762 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:52pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596033.3 | 511882.9 | 74010 | 1.64041666667 | 14762 |
| 014910 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:53pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596036.1 | 511884.0 | 74012 | 1.64041666667 | 14910 |
| 017407 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:54pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596039.0 | 511885.7 | 74014 | 1.64041666667 | 17407 |
| 014672 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:55pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596041.6 | 511886.3 | 74016 | 1.64041666667 | 14672 |
| 014708 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:56pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596044.6 | 511887.4 | 74018 | 1.64041666667 | 14708 |
| 014717 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:57pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596047.3 | 511889.0 | 74020 | 1.64041666667 | 14717 |
| 016579 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:58pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596050.6 | 511890.1 | 74022 | 1.64041666667 | 16579 |
| 015724 | 0 | GeoXH 6000 | 08/19/2015 | 03:57:59pm | Sensor | 1797-S0049-G-TJV.cor | 6839.0 | 1596052.6 | 511891.2 | 74024 | 1.64041666667 | 15724 |
| 014311 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:00pm | Sensor | 1797-S0049-G-TJV.cor | 6839.0 | 1596055.6 | 511892.1 | 74026 | 1.64041666667 | 14311 |
| 015547 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:01pm | Sensor | 1797-S0049-G-TJV.cor | 6839.1 | 1596058.9 | 511892.9 | 74028 | 1.64041666667 | 15547 |
| 015407 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:02pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596062.0 | 511893.9 | 74030 | 1.64041666667 | 15407 |
| 015251 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:03pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596062.6 | 511894.1 | 74032 | 1.64041666667 | 15251 |
| 015093 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:04pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596062.5 | 511893.3 | 74034 | 1.64041666667 | 15093 |
| 015263 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:05pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596063.1 | 511891.1 | 74036 | 1.64041666667 | 15263 |
| 015815 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:06pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596063.4 | 511888.8 | 74038 | 1.64041666667 | 15815 |
| 017034 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:07pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596064.1 | 511887.5 | 74040 | 1.64041666667 | 17034 |
| 016528 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:08pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596064.9 | 511884.0 | 74042 | 1.64041666667 | 16528 |
| 014422 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:09pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596065.7 | 511882.6 | 74044 | 1.64041666667 | 14422 |
| 014735 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:10pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596065.9 | 511883.1 | 74046 | 1.64041666667 | 14735 |
| 014603 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:11pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.6 | 511883.4 | 74048 | 1.64041666667 | 14603 |
| 014751 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:12pm | Sensor | 1797-S0049-G-TJV.cor | 6839.5 | 1596065.5 | 511883.6 | 74050 | 1.64041666667 | 14751 |
| 013287 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:13pm | Sensor | 1797-S0049-G-TJV.cor | 6839.5 | 1596065.2 | 511883.5 | 74052 | 1.64041666667 | 13287 |
| 013972 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:14pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511884.0 | 74054 | 1.64041666667 | 13972 |
| 013813 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:15pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.9 | 511884.2 | 74056 | 1.64041666667 | 13813 |
| 015063 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:16pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.4 | 511885.4 | 74058 | 1.64041666667 | 15063 |
| 015285 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:17pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596063.9 | 511887.2 | 74060 | 1.64041666667 | 15285 |
| 015821 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:18pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596061.0 | 511887.9 | 74062 | 1.64041666667 | 15821 |
| 015595 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:19pm | Sensor | 1797-S0049-G-TJV.cor | 6839.1 | 1596058.6 | 511887.1 | 74064 | 1.64041666667 | 15595 |
| 014519 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:20pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596055.2 | 511886.3 | 74066 | 1.64041666667 | 14519 |
| 015149 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:21pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596052.5 | 511885.7 | 74068 | 1.64041666667 | 15149 |
| 014137 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:22pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596049.6 | 511884.7 | 74070 | 1.64041666667 | 14137 |
| 015984 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:23pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596046.7 | 511884.1 | 74072 | 1.64041666667 | 15984 |
| 014076 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:24pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596044.1 | 511882.4 | 74074 | 1.64041666667 | 14076 |
| 014229 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:25pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596041.6 | 511881.2 | 74076 | 1.64041666667 | 14229 |
| 015557 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:26pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596039.1 | 511879.3 | 74078 | 1.64041666667 | 15557 |
| 014269 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:27pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596036.9 | 511878.5 | 74080 | 1.64041666667 | 14269 |
| 016497 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:28pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596033.8 | 511877.2 | 74082 | 1.64041666667 | 16497 |
| 015704 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:29pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596031.5 | 511875.5 | 74084 | 1.64041666667 | 15704 |
| 014876 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:30pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596028.6 | 511874.1 | 74086 | 1.64041666667 | 14876 |
| 013979 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:31pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596026.6 | 511872.3 | 74088 | 1.64041666667 | 13979 |
| 014414 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:32pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596024.2 | 511870.6 | 74090 | 1.64041666667 | 14414 |
| 013563 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:33pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596021.7 | 511868.8 | 74092 | 1.64041666667 | 13563 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:34pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596019.1 | 511866.8 | 74094 | 1.64041666667 | 12960 |
| 013290 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:35pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596016.8 | 511865.7 | 74096 | 1.64041666667 | 13290 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014932 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:36pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596014.2 | 511863.9 | 74098 | 1.64041666667 | 14932 |
| 015313 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596011.9 | 511862.4 | 74100 | 1.64041666667 | 15313 |
| 014988 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596009.2 | 511860.5 | 74102 | 1.64041666667 | 14988 |
| 015567 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596007.2 | 511858.3 | 74104 | 1.64041666667 | 15567 |
| 015051 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596004.4 | 511856.4 | 74106 | 1.64041666667 | 15051 |
| 014773 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596002.4 | 511854.7 | 74108 | 1.64041666667 | 14773 |
| 013563 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595999.5 | 511853.1 | 74110 | 1.64041666667 | 13563 |
| 013050 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595996.9 | 511851.6 | 74112 | 1.64041666667 | 13050 |
| 013462 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595994.3 | 511849.2 | 74114 | 1.64041666667 | 13462 |
| 014735 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595992.3 | 511847.7 | 74116 | 1.64041666667 | 14735 |
| 014544 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:46pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595990.3 | 511845.8 | 74118 | 1.64041666667 | 14544 |
| 013716 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:47pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595988.1 | 511844.8 | 74120 | 1.64041666667 | 13716 |
| 015249 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595985.2 | 511843.7 | 74122 | 1.64041666667 | 15249 |
| 012662 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595982.8 | 511842.3 | 74124 | 1.64041666667 | 12662 |
| 014085 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595979.6 | 511841.3 | 74126 | 1.64041666667 | 14085 |
| 012881 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595977.8 | 511839.9 | 74128 | 1.64041666667 | 12881 |
| 012220 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595975.4 | 511838.7 | 74130 | 1.64041666667 | 12220 |
| 013105 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595974.4 | 511837.2 | 74132 | 1.64041666667 | 13105 |
| 013476 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595972.3 | 511835.2 | 74134 | 1.64041666667 | 13476 |
| 012399 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1595971.5 | 511833.1 | 74136 | 1.64041666667 | 12399 |
| 012219 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1595969.9 | 511831.4 | 74138 | 1.64041666667 | 12219 |
| 010915 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:57pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595967.7 | 511831.1 | 74140 | 1.64041666667 | 10915 |
| 012868 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:58pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595965.0 | 511830.1 | 74142 | 1.64041666667 | 12868 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 03:58:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595962.0 | 511829.2 | 74144 | 1.64041666667 | 13297 |
| 014184 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595960.0 | 511827.6 | 74146 | 1.64041666667 | 14184 |
| 013056 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595957.7 | 511826.6 | 74148 | 1.64041666667 | 13056 |
| 014184 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595957.1 | 511826.4 | 74150 | 1.64041666667 | 14184 |
| 013056 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595958.1 | 511824.8 | 74152 | 1.64041666667 | 13056 |
| 012924 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:04pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595958.4 | 511822.2 | 74154 | 1.64041666667 | 12924 |
| 013881 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:05pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595958.8 | 511820.9 | 74156 | 1.64041666667 | 13881 |
| 013130 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595959.7 | 511817.9 | 74158 | 1.64041666667 | 13130 |
| 014532 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595960.6 | 511815.7 | 74160 | 1.64041666667 | 14532 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:08pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1595960.8 | 511814.8 | 74162 | 1.64041666667 | 14463 |
| 015195 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:09pm | Sensor | 1797-S0049-G-TJV.cor | 6835.9 | 1595960.9 | 511814.7 | 74164 | 1.64041666667 | 15195 |
| 014088 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:10pm | Sensor | 1797-S0049-G-TJV.cor | 6835.8 | 1595961.0 | 511814.5 | 74166 | 1.64041666667 | 14088 |
| 015432 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595959.8 | 511815.8 | 74168 | 1.64041666667 | 15432 |
| 012708 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595959.2 | 511817.2 | 74170 | 1.64041666667 | 12708 |
| 013467 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595958.7 | 511818.9 | 74172 | 1.64041666667 | 13467 |
| 012036 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595959.9 | 511820.2 | 74174 | 1.64041666667 | 12036 |
| 012849 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595961.3 | 511821.8 | 74176 | 1.64041666667 | 12849 |
| 014492 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595963.7 | 511823.7 | 74178 | 1.64041666667 | 14492 |
| 013343 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595965.9 | 511824.9 | 74180 | 1.64041666667 | 13343 |
| 015185 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595968.4 | 511826.4 | 74182 | 1.64041666667 | 15185 |
| 014656 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595970.4 | 511827.2 | 74184 | 1.64041666667 | 14656 |
| 013294 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:20pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595971.8 | 511828.6 | 74186 | 1.64041666667 | 13294 |
| 014993 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1595971.9 | 511828.3 | 74188 | 1.64041666667 | 14993 |
| 014458 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1595972.2 | 511826.6 | 74190 | 1.64041666667 | 14458 |
| 014984 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595973.2 | 511825.0 | 74192 | 1.64041666667 | 14984 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014396 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595975.8 | 511823.8 | 74194 | 1.64041666667 | 14396 |
| 013589 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595978.0 | 511823.4 | 74196 | 1.64041666667 | 13589 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:26pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595980.0 | 511824.6 | 74198 | 1.64041666667 | 12787 |
| 013126 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595981.7 | 511826.0 | 74200 | 1.64041666667 | 13126 |
| 013751 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595983.0 | 511828.2 | 74202 | 1.64041666667 | 13751 |
| 014088 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595984.7 | 511829.8 | 74204 | 1.64041666667 | 14088 |
| 013782 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595986.4 | 511832.6 | 74206 | 1.64041666667 | 13782 |
| 013015 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595988.2 | 511834.2 | 74208 | 1.64041666667 | 13015 |
| 013934 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595989.8 | 511836.4 | 74210 | 1.64041666667 | 13934 |
| 013563 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:33pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595992.0 | 511837.9 | 74212 | 1.64041666667 | 13563 |
| 013320 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:34pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595994.7 | 511840.0 | 74214 | 1.64041666667 | 13320 |
| 015030 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:35pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595996.5 | 511841.8 | 74216 | 1.64041666667 | 15030 |
| 014857 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:36pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595999.1 | 511843.6 | 74218 | 1.64041666667 | 14857 |
| 013854 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:37pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596001.6 | 511845.1 | 74220 | 1.64041666667 | 13854 |
| 013513 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:38pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596004.7 | 511847.2 | 74222 | 1.64041666667 | 13513 |
| 015048 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596007.2 | 511848.2 | 74224 | 1.64041666667 | 15048 |
| 015222 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.6 | 1596009.9 | 511849.8 | 74226 | 1.64041666667 | 15222 |
| 013615 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596012.5 | 511850.9 | 74228 | 1.64041666667 | 13615 |
| 014174 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:42pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596015.0 | 511852.5 | 74230 | 1.64041666667 | 14174 |
| 015663 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596017.3 | 511854.3 | 74232 | 1.64041666667 | 15663 |
| 014775 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596020.2 | 511856.0 | 74234 | 1.64041666667 | 14775 |
| 014943 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:45pm | Sensor | 1797-S0049-G-TJV.cor | 6838.0 | 1596022.2 | 511857.6 | 74236 | 1.64041666667 | 14943 |
| 014326 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:46pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596025.2 | 511859.0 | 74238 | 1.64041666667 | 14326 |
| 015371 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:47pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596027.6 | 511860.4 | 74240 | 1.64041666667 | 15371 |
| 015303 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:48pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596030.2 | 511862.0 | 74242 | 1.64041666667 | 15303 |
| 014895 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:49pm | Sensor | 1797-S0049-G-TJV.cor | 6838.4 | 1596032.9 | 511863.3 | 74244 | 1.64041666667 | 14895 |
| 014793 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:50pm | Sensor | 1797-S0049-G-TJV.cor | 6838.4 | 1596035.6 | 511865.2 | 74246 | 1.64041666667 | 14793 |
| 015128 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:51pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596038.1 | 511867.1 | 74248 | 1.64041666667 | 15128 |
| 015662 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:52pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596040.9 | 511868.8 | 74250 | 1.64041666667 | 15662 |
| 014175 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:53pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596043.2 | 511870.5 | 74252 | 1.64041666667 | 14175 |
| 014553 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:54pm | Sensor | 1797-S0049-G-TJV.cor | 6838.7 | 1596046.4 | 511872.4 | 74254 | 1.64041666667 | 14553 |
| 014528 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:55pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596049.1 | 511873.8 | 74256 | 1.64041666667 | 14528 |
| 013322 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:56pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596051.8 | 511875.6 | 74258 | 1.64041666667 | 13322 |
| 014220 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:57pm | Sensor | 1797-S0049-G-TJV.cor | 6839.0 | 1596054.3 | 511876.4 | 74260 | 1.64041666667 | 14220 |
| 014925 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:58pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596057.3 | 511877.9 | 74262 | 1.64041666667 | 14925 |
| 014291 | 0 | GeoXH 6000 | 08/19/2015 | 03:59:59pm | Sensor | 1797-S0049-G-TJV.cor | 6839.1 | 1596059.7 | 511879.4 | 74264 | 1.64041666667 | 14291 |
| 013533 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:00pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596062.5 | 511880.6 | 74266 | 1.64041666667 | 13533 |
| 015023 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:01pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596064.6 | 511881.9 | 74268 | 1.64041666667 | 15023 |
| 014255 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:02pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596065.9 | 511882.3 | 74270 | 1.64041666667 | 14255 |
| 015228 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:03pm | Sensor | 1797-S0049-G-TJV.cor | 6839.1 | 1596065.1 | 511882.4 | 74272 | 1.64041666667 | 15228 |
| 015343 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:04pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.8 | 511882.2 | 74274 | 1.64041666667 | 15343 |
| 015356 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:05pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511881.9 | 74276 | 1.64041666667 | 15356 |
| 012899 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:06pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511881.6 | 74278 | 1.64041666667 | 12899 |
| 012884 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:07pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.0 | 511881.6 | 74280 | 1.64041666667 | 12884 |
| 015251 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:08pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.1 | 511881.9 | 74282 | 1.64041666667 | 15251 |
| 015692 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:09pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.1 | 511882.1 | 74284 | 1.64041666667 | 15692 |
| 013823 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:10pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.0 | 511882.2 | 74286 | 1.64041666667 | 13823 |
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:11pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511882.2 | 74288 | 1.64041666667 | 13451 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014821 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:12pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.1 | 511882.2 | 74290 | 1.64041666667 | 14821 |
| 014955 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:13pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511882.3 | 74292 | 1.64041666667 | 14955 |
| 013758 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:14pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511882.3 | 74294 | 1.64041666667 | 13758 |
| 013909 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:15pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511882.3 | 74296 | 1.64041666667 | 13909 |
| 014517 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:16pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511882.2 | 74298 | 1.64041666667 | 14517 |
| 014189 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:17pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511882.3 | 74300 | 1.64041666667 | 14189 |
| 014287 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:18pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511882.4 | 74302 | 1.64041666667 | 14287 |
| 014341 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:19pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596065.0 | 511882.4 | 74304 | 1.64041666667 | 14341 |
| 014025 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:20pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.4 | 74306 | 1.64041666667 | 14025 |
| 014306 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:21pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74308 | 1.64041666667 | 14306 |
| 014646 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:22pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.3 | 74310 | 1.64041666667 | 14646 |
| 013471 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:23pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.3 | 74312 | 1.64041666667 | 13471 |
| 013447 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:24pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.3 | 74314 | 1.64041666667 | 13447 |
| 014522 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:25pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.3 | 74316 | 1.64041666667 | 14522 |
| 014790 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:26pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.3 | 74318 | 1.64041666667 | 14790 |
| 016087 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:27pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.4 | 74320 | 1.64041666667 | 16087 |
| 013802 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:28pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.0 | 511882.6 | 74322 | 1.64041666667 | 13802 |
| 014040 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:29pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.0 | 511882.7 | 74324 | 1.64041666667 | 14040 |
| 014340 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:30pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.1 | 511882.8 | 74326 | 1.64041666667 | 14340 |
| 014835 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:31pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.0 | 511882.7 | 74328 | 1.64041666667 | 14835 |
| 014238 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:32pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.6 | 74330 | 1.64041666667 | 14238 |
| 014539 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:33pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.8 | 511882.5 | 74332 | 1.64041666667 | 14539 |
| 017045 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:34pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.4 | 74334 | 1.64041666667 | 17045 |
| 014011 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:35pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74336 | 1.64041666667 | 14011 |
| 016462 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:36pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74338 | 1.64041666667 | 16462 |
| 014765 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:37pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74340 | 1.64041666667 | 14765 |
| 013201 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:38pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74342 | 1.64041666667 | 13201 |
| 014070 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:39pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74344 | 1.64041666667 | 14070 |
| 014347 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:40pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74346 | 1.64041666667 | 14347 |
| 013877 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:41pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.4 | 74348 | 1.64041666667 | 13877 |
| 015049 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:42pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.5 | 74350 | 1.64041666667 | 15049 |
| 013122 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:43pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.4 | 74352 | 1.64041666667 | 13122 |
| 016390 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:44pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.4 | 74354 | 1.64041666667 | 16390 |
| 015767 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:45pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74356 | 1.64041666667 | 15767 |
| 014831 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:46pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.3 | 74358 | 1.64041666667 | 14831 |
| 014358 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:47pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.2 | 74360 | 1.64041666667 | 14358 |
| 016369 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:48pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.2 | 74362 | 1.64041666667 | 16369 |
| 014472 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:49pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.2 | 74364 | 1.64041666667 | 14472 |
| 014568 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:50pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.9 | 511882.2 | 74366 | 1.64041666667 | 14568 |
| 015162 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:51pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596064.8 | 511882.2 | 74368 | 1.64041666667 | 15162 |
| 013930 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:52pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.2 | 74370 | 1.64041666667 | 13930 |
| 015062 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:53pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.1 | 74372 | 1.64041666667 | 15062 |
| 015765 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:54pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.9 | 511882.0 | 74374 | 1.64041666667 | 15765 |
| 016151 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:55pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.8 | 511882.0 | 74376 | 1.64041666667 | 16151 |
| 015018 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:56pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.8 | 511881.8 | 74378 | 1.64041666667 | 15018 |
| 014344 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:57pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.3 | 511881.3 | 74380 | 1.64041666667 | 14344 |
| 014416 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:58pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596066.1 | 511880.4 | 74382 | 1.64041666667 | 14416 |
| 014164 | 0 | GeoXH 6000 | 08/19/2015 | 04:00:59pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596066.4 | 511878.8 | 74384 | 1.64041666667 | 14164 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013381 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:00pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596066.6 | 511876.5 | 74386 | 1.64041666667 | 13381 |
| 013305 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:01pm | Sensor | 1797-S0049-G-TJV.cor | 6839.4 | 1596066.1 | 511875.7 | 74388 | 1.64041666667 | 13305 |
| 014876 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:02pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596065.9 | 511875.0 | 74390 | 1.64041666667 | 14876 |
| 013079 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:03pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596064.7 | 511874.4 | 74392 | 1.64041666667 | 13079 |
| 014880 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:04pm | Sensor | 1797-S0049-G-TJV.cor | 6839.3 | 1596063.1 | 511873.2 | 74394 | 1.64041666667 | 14880 |
| 015510 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:05pm | Sensor | 1797-S0049-G-TJV.cor | 6839.2 | 1596061.3 | 511872.2 | 74396 | 1.64041666667 | 15510 |
| 015667 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:06pm | Sensor | 1797-S0049-G-TJV.cor | 6839.1 | 1596058.8 | 511870.5 | 74398 | 1.64041666667 | 15667 |
| 014206 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:07pm | Sensor | 1797-S0049-G-TJV.cor | 6838.9 | 1596056.6 | 511869.1 | 74400 | 1.64041666667 | 14206 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:08pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596053.5 | 511867.9 | 74402 | 1.64041666667 | 13931 |
| 014913 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:09pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596051.2 | 511866.4 | 74404 | 1.64041666667 | 14913 |
| 013418 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:10pm | Sensor | 1797-S0049-G-TJV.cor | 6838.8 | 1596048.4 | 511865.3 | 74406 | 1.64041666667 | 13418 |
| 014304 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:11pm | Sensor | 1797-S0049-G-TJV.cor | 6838.6 | 1596046.0 | 511864.3 | 74408 | 1.64041666667 | 14304 |
| 013026 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:12pm | Sensor | 1797-S0049-G-TJV.cor | 6838.5 | 1596043.1 | 511863.1 | 74410 | 1.64041666667 | 13026 |
| 013786 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:13pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596040.7 | 511861.9 | 74412 | 1.64041666667 | 13786 |
| 012986 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:14pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596037.9 | 511860.1 | 74414 | 1.64041666667 | 12986 |
| 014226 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:15pm | Sensor | 1797-S0049-G-TJV.cor | 6838.3 | 1596035.3 | 511859.0 | 74416 | 1.64041666667 | 14226 |
| 014386 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:16pm | Sensor | 1797-S0049-G-TJV.cor | 6838.2 | 1596032.7 | 511857.4 | 74418 | 1.64041666667 | 14386 |
| 013946 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:17pm | Sensor | 1797-S0049-G-TJV.cor | 6838.1 | 1596030.4 | 511856.3 | 74420 | 1.64041666667 | 13946 |
| 014616 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:18pm | Sensor | 1797-S0049-G-TJV.cor | 6837.9 | 1596027.3 | 511854.6 | 74422 | 1.64041666667 | 14616 |
| 014874 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:19pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596025.0 | 511852.8 | 74424 | 1.64041666667 | 14874 |
| 013738 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:20pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596022.0 | 511851.5 | 74426 | 1.64041666667 | 13738 |
| 014744 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596019.7 | 511850.0 | 74428 | 1.64041666667 | 14744 |
| 013856 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.8 | 1596017.4 | 511848.5 | 74430 | 1.64041666667 | 13856 |
| 017144 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.7 | 1596015.1 | 511846.9 | 74432 | 1.64041666667 | 17144 |
| 015266 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596012.4 | 511845.1 | 74434 | 1.64041666667 | 15266 |
| 015066 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596009.6 | 511843.9 | 74436 | 1.64041666667 | 15066 |
| 014356 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.5 | 1596007.0 | 511842.3 | 74438 | 1.64041666667 | 14356 |
| 014449 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.4 | 1596004.7 | 511841.2 | 74440 | 1.64041666667 | 14449 |
| 014472 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:28pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1596002.0 | 511839.7 | 74442 | 1.64041666667 | 14472 |
| 014988 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595999.7 | 511837.9 | 74444 | 1.64041666667 | 14988 |
| 014787 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.3 | 1595996.8 | 511836.1 | 74446 | 1.64041666667 | 14787 |
| 015066 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:31pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595994.9 | 511834.4 | 74448 | 1.64041666667 | 15066 |
| 014446 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:32pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595992.3 | 511832.4 | 74450 | 1.64041666667 | 14446 |
| 015071 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595990.0 | 511830.7 | 74452 | 1.64041666667 | 15071 |
| 014118 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595987.6 | 511828.0 | 74454 | 1.64041666667 | 14118 |
| 014389 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595985.4 | 511826.1 | 74456 | 1.64041666667 | 14389 |
| 014487 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595983.1 | 511824.2 | 74458 | 1.64041666667 | 14487 |
| 013342 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595980.7 | 511822.8 | 74460 | 1.64041666667 | 13342 |
| 014615 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595977.9 | 511821.3 | 74462 | 1.64041666667 | 14615 |
| 014153 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:39pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595975.7 | 511819.5 | 74464 | 1.64041666667 | 14153 |
| 013288 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:40pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595972.9 | 511818.5 | 74466 | 1.64041666667 | 13288 |
| 013642 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:41pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595970.1 | 511817.8 | 74468 | 1.64041666667 | 13642 |
| 013970 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595967.8 | 511817.1 | 74470 | 1.64041666667 | 13970 |
| 013602 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595965.5 | 511816.3 | 74472 | 1.64041666667 | 13602 |
| 013270 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595962.5 | 511815.0 | 74474 | 1.64041666667 | 13270 |
| 013307 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595960.4 | 511815.1 | 74476 | 1.64041666667 | 13307 |
| 014096 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595959.3 | 511815.8 | 74478 | 1.64041666667 | 14096 |
| 013304 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595959.0 | 511817.5 | 74480 | 1.64041666667 | 13304 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014636 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:48pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595958.6 | 511820.3 | 74482 | 1.64041666667 | 14636 |
| 014579 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595957.9 | 511822.9 | 74484 | 1.64041666667 | 14579 |
| 013934 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595957.1 | 511825.7 | 74486 | 1.64041666667 | 13934 |
| 013743 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595956.6 | 511827.5 | 74488 | 1.64041666667 | 13743 |
| 013725 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595956.4 | 511830.0 | 74490 | 1.64041666667 | 13725 |
| 013661 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595956.8 | 511832.4 | 74492 | 1.64041666667 | 13661 |
| 013765 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595957.0 | 511835.9 | 74494 | 1.64041666667 | 13765 |
| 014121 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595957.8 | 511838.7 | 74496 | 1.64041666667 | 14121 |
| 012380 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595958.7 | 511841.5 | 74498 | 1.64041666667 | 12380 |
| 014285 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595959.3 | 511844.7 | 74500 | 1.64041666667 | 14285 |
| 014131 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595959.2 | 511847.7 | 74502 | 1.64041666667 | 14131 |
| 013492 | 0 | GeoXH 6000 | 08/19/2015 | 04:01:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595959.0 | 511850.6 | 74504 | 1.64041666667 | 13492 |
| 016873 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595958.7 | 511854.2 | 74506 | 1.64041666667 | 16873 |
| 016518 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595958.4 | 511857.3 | 74508 | 1.64041666667 | 16518 |
| 016699 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:02pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595958.5 | 511860.9 | 74510 | 1.64041666667 | 16699 |
| 014674 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595958.6 | 511864.3 | 74512 | 1.64041666667 | 14674 |
| 013628 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:04pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595958.3 | 511868.3 | 74514 | 1.64041666667 | 13628 |
| 013907 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:05pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595957.8 | 511871.3 | 74516 | 1.64041666667 | 13907 |
| 016016 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595957.6 | 511875.3 | 74518 | 1.64041666667 | 16016 |
| 013094 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595957.7 | 511878.4 | 74520 | 1.64041666667 | 13094 |
| 012603 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:08pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595957.6 | 511882.0 | 74522 | 1.64041666667 | 12603 |
| 014460 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595957.7 | 511885.2 | 74524 | 1.64041666667 | 14460 |
| 013755 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:10pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595957.9 | 511888.6 | 74526 | 1.64041666667 | 13755 |
| 012978 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:11pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595957.5 | 511891.5 | 74528 | 1.64041666667 | 12978 |
| 014224 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595956.9 | 511895.3 | 74530 | 1.64041666667 | 14224 |
| 013366 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595957.4 | 511898.2 | 74532 | 1.64041666667 | 13366 |
| 016271 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595959.5 | 511901.0 | 74534 | 1.64041666667 | 16271 |
| 017958 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595962.2 | 511902.5 | 74536 | 1.64041666667 | 17958 |
| 015589 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595965.8 | 511903.4 | 74538 | 1.64041666667 | 15589 |
| 016377 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595969.0 | 511904.1 | 74540 | 1.64041666667 | 16377 |
| 018794 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595972.9 | 511905.3 | 74542 | 1.64041666667 | 18794 |
| 019728 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595975.6 | 511906.1 | 74544 | 1.64041666667 | 19728 |
| 018312 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595979.3 | 511907.9 | 74546 | 1.64041666667 | 18312 |
| 020328 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:21pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595981.2 | 511910.2 | 74548 | 1.64041666667 | 20328 |
| 018042 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595983.0 | 511913.4 | 74550 | 1.64041666667 | 18042 |
| 016690 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:23pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595984.8 | 511916.3 | 74552 | 1.64041666667 | 16690 |
| 015332 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:24pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595985.8 | 511919.8 | 74554 | 1.64041666667 | 15332 |
| 017603 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:25pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595985.3 | 511922.3 | 74556 | 1.64041666667 | 17603 |
| 013970 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:26pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595983.2 | 511924.6 | 74558 | 1.64041666667 | 13970 |
| 015162 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:27pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595980.5 | 511925.8 | 74560 | 1.64041666667 | 15162 |
| 017230 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595976.7 | 511927.1 | 74562 | 1.64041666667 | 17230 |
| 019547 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:29pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595974.0 | 511929.1 | 74564 | 1.64041666667 | 19547 |
| 019466 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:30pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595971.2 | 511931.5 | 74566 | 1.64041666667 | 19466 |
| 020046 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595968.4 | 511934.0 | 74568 | 1.64041666667 | 20046 |
| 019291 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595965.4 | 511936.3 | 74570 | 1.64041666667 | 19291 |
| 018532 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595962.5 | 511938.6 | 74572 | 1.64041666667 | 18532 |
| 019513 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595959.8 | 511940.9 | 74574 | 1.64041666667 | 19513 |
| 021018 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595957.3 | 511942.7 | 74576 | 1.64041666667 | 21018 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 021844 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595956.1 | 511943.6 | 74578 | 1.64041666667 | 21844 |
| 023371 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595957.2 | 511944.1 | 74580 | 1.64041666667 | 23371 |
| 025672 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595959.7 | 511943.7 | 74582 | 1.64041666667 | 25672 |
| 025288 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595962.5 | 511943.1 | 74584 | 1.64041666667 | 25288 |
| 023092 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595966.0 | 511942.8 | 74586 | 1.64041666667 | 23092 |
| 021313 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595968.9 | 511942.2 | 74588 | 1.64041666667 | 21313 |
| 021918 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595972.2 | 511941.8 | 74590 | 1.64041666667 | 21918 |
| 023419 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595975.1 | 511941.9 | 74592 | 1.64041666667 | 23419 |
| 021334 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595978.0 | 511941.4 | 74594 | 1.64041666667 | 21334 |
| 020723 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595980.6 | 511941.1 | 74596 | 1.64041666667 | 20723 |
| 023181 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595983.9 | 511940.8 | 74598 | 1.64041666667 | 23181 |
| 024245 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595986.4 | 511939.8 | 74600 | 1.64041666667 | 24245 |
| 021511 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:48pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595988.7 | 511937.2 | 74602 | 1.64041666667 | 21511 |
| 019687 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:49pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595989.9 | 511934.8 | 74604 | 1.64041666667 | 19687 |
| 019532 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:50pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595990.8 | 511932.3 | 74606 | 1.64041666667 | 19532 |
| 017603 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:51pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595992.1 | 511931.0 | 74608 | 1.64041666667 | 17603 |
| 019940 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:52pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595993.5 | 511931.5 | 74610 | 1.64041666667 | 19940 |
| 018635 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:53pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595994.2 | 511933.5 | 74612 | 1.64041666667 | 18635 |
| 017798 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:54pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595994.1 | 511936.1 | 74614 | 1.64041666667 | 17798 |
| 019749 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:55pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595993.3 | 511938.2 | 74616 | 1.64041666667 | 19749 |
| 019637 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:56pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595991.4 | 511940.2 | 74618 | 1.64041666667 | 19637 |
| 022669 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595989.3 | 511940.7 | 74620 | 1.64041666667 | 22669 |
| 021657 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595986.6 | 511940.0 | 74622 | 1.64041666667 | 21657 |
| 021328 | 0 | GeoXH 6000 | 08/19/2015 | 04:02:59pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595984.5 | 511938.1 | 74624 | 1.64041666667 | 21328 |
| 017906 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:00pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595983.5 | 511935.4 | 74626 | 1.64041666667 | 17906 |
| 016206 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595982.6 | 511932.9 | 74628 | 1.64041666667 | 16206 |
| 018391 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:02pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595981.2 | 511931.2 | 74630 | 1.64041666667 | 18391 |
| 018127 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:03pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595980.5 | 511929.1 | 74632 | 1.64041666667 | 18127 |
| 017252 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:04pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595980.2 | 511926.1 | 74634 | 1.64041666667 | 17252 |
| 016373 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:05pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595979.7 | 511923.1 | 74636 | 1.64041666667 | 16373 |
| 017293 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595979.2 | 511919.6 | 74638 | 1.64041666667 | 17293 |
| 017163 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595979.0 | 511916.4 | 74640 | 1.64041666667 | 17163 |
| 016890 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:08pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595978.6 | 511912.5 | 74642 | 1.64041666667 | 16890 |
| 016492 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595978.5 | 511909.9 | 74644 | 1.64041666667 | 16492 |
| 018763 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:10pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595978.4 | 511907.4 | 74646 | 1.64041666667 | 18763 |
| 019481 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595978.3 | 511907.2 | 74648 | 1.64041666667 | 19481 |
| 018190 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595977.6 | 511908.6 | 74650 | 1.64041666667 | 18190 |
| 017627 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595977.6 | 511910.5 | 74652 | 1.64041666667 | 17627 |
| 017696 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595978.3 | 511913.7 | 74654 | 1.64041666667 | 17696 |
| 018644 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595978.8 | 511916.9 | 74656 | 1.64041666667 | 18644 |
| 018941 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595979.5 | 511920.2 | 74658 | 1.64041666667 | 18941 |
| 016705 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595980.6 | 511923.1 | 74660 | 1.64041666667 | 16705 |
| 015456 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595982.6 | 511925.9 | 74662 | 1.64041666667 | 15456 |
| 015894 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595985.0 | 511927.9 | 74664 | 1.64041666667 | 15894 |
| 018613 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:20pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595987.7 | 511930.1 | 74666 | 1.64041666667 | 18613 |
| 018183 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595988.9 | 511932.9 | 74668 | 1.64041666667 | 18183 |
| 017655 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:22pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595988.4 | 511936.0 | 74670 | 1.64041666667 | 17655 |
| 019623 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:23pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595987.2 | 511938.5 | 74672 | 1.64041666667 | 19623 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019306 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:24pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595985.2 | 511940.1 | 74674 | 1.64041666667 | 19306 |
| 021056 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595983.5 | 511940.3 | 74676 | 1.64041666667 | 21056 |
| 022334 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:26pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595983.7 | 511940.5 | 74678 | 1.64041666667 | 22334 |
| 022567 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.2 | 1595984.2 | 511940.8 | 74680 | 1.64041666667 | 22567 |
| 022800 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:28pm | Sensor | 1797-S0049-G-TJV.cor | 6835.6 | 1595984.8 | 511941.0 | 74682 | 1.64041666667 | 22800 |
| 023490 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:29pm | Sensor | 1797-S0049-G-TJV.cor | 6835.2 | 1595985.1 | 511941.0 | 74684 | 1.64041666667 | 23490 |
| 023272 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:30pm | Sensor | 1797-S0049-G-TJV.cor | 6835.4 | 1595984.9 | 511941.0 | 74686 | 1.64041666667 | 23272 |
| 020878 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:31pm | Sensor | 1797-S0049-G-TJV.cor | 6835.9 | 1595984.2 | 511941.0 | 74688 | 1.64041666667 | 20878 |
| 024119 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595983.4 | 511940.7 | 74690 | 1.64041666667 | 24119 |
| 022050 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595982.8 | 511940.4 | 74692 | 1.64041666667 | 22050 |
| 021412 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595983.4 | 511941.8 | 74694 | 1.64041666667 | 21412 |
| 023953 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595984.6 | 511943.2 | 74696 | 1.64041666667 | 23953 |
| 020508 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595987.0 | 511944.9 | 74698 | 1.64041666667 | 20508 |
| 022587 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595989.1 | 511946.2 | 74700 | 1.64041666667 | 22587 |
| 020976 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595991.1 | 511948.4 | 74702 | 1.64041666667 | 20976 |
| 021504 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595992.7 | 511950.9 | 74704 | 1.64041666667 | 21504 |
| 021456 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:40pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595994.3 | 511954.2 | 74706 | 1.64041666667 | 21456 |
| 019224 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595995.1 | 511957.1 | 74708 | 1.64041666667 | 19224 |
| 017616 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595996.1 | 511960.4 | 74710 | 1.64041666667 | 17616 |
| 017784 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:43pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595997.2 | 511963.2 | 74712 | 1.64041666667 | 17784 |
| 016776 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:44pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595998.3 | 511966.5 | 74714 | 1.64041666667 | 16776 |
| 015384 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:45pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595998.2 | 511968.9 | 74716 | 1.64041666667 | 15384 |
| 017136 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595998.1 | 511971.0 | 74718 | 1.64041666667 | 17136 |
| 017934 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595997.4 | 511972.6 | 74720 | 1.64041666667 | 17934 |
| 018373 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:48pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595995.9 | 511973.5 | 74722 | 1.64041666667 | 18373 |
| 019353 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595994.4 | 511973.5 | 74724 | 1.64041666667 | 19353 |
| 020978 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595992.3 | 511973.0 | 74726 | 1.64041666667 | 20978 |
| 020814 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595992.0 | 511973.6 | 74728 | 1.64041666667 | 20814 |
| 019753 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:52pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595993.9 | 511973.5 | 74730 | 1.64041666667 | 19753 |
| 018888 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595996.4 | 511973.0 | 74732 | 1.64041666667 | 18888 |
| 021222 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:54pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595998.9 | 511971.9 | 74734 | 1.64041666667 | 21222 |
| 022945 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1596000.3 | 511972.2 | 74736 | 1.64041666667 | 22945 |
| 024216 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:56pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1596000.8 | 511972.6 | 74738 | 1.64041666667 | 24216 |
| 024594 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1596000.9 | 511972.7 | 74740 | 1.64041666667 | 24594 |
| 024298 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1596000.5 | 511971.3 | 74742 | 1.64041666667 | 24298 |
| 022394 | 0 | GeoXH 6000 | 08/19/2015 | 04:03:59pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1596000.8 | 511969.5 | 74744 | 1.64041666667 | 22394 |
| 019698 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:00pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1596000.5 | 511967.2 | 74746 | 1.64041666667 | 19698 |
| 020944 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:01pm | Sensor | 1797-S0049-G-TJV.cor | 6837.2 | 1595999.5 | 511964.6 | 74748 | 1.64041666667 | 20944 |
| 018766 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:02pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595997.7 | 511961.5 | 74750 | 1.64041666667 | 18766 |
| 018461 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595995.7 | 511958.6 | 74752 | 1.64041666667 | 18461 |
| 017995 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:04pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595993.6 | 511954.9 | 74754 | 1.64041666667 | 17995 |
| 023009 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:05pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595991.7 | 511952.4 | 74756 | 1.64041666667 | 23009 |
| 023002 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595988.4 | 511950.1 | 74758 | 1.64041666667 | 23002 |
| 023150 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595985.1 | 511948.8 | 74760 | 1.64041666667 | 23150 |
| 022437 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:08pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595981.3 | 511947.4 | 74762 | 1.64041666667 | 22437 |
| 023189 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595977.7 | 511946.2 | 74764 | 1.64041666667 | 23189 |
| 020647 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:10pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595973.8 | 511945.0 | 74766 | 1.64041666667 | 20647 |
| 021391 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595970.5 | 511944.3 | 74768 | 1.64041666667 | 21391 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 022207 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595966.2 | 511943.7 | 74770 | 1.64041666667 | 22207 |
| 020762 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595962.6 | 511943.3 | 74772 | 1.64041666667 | 20762 |
| 021360 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:14pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595958.6 | 511943.2 | 74774 | 1.64041666667 | 21360 |
| 020670 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:15pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595955.7 | 511943.4 | 74776 | 1.64041666667 | 20670 |
| 016987 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:16pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595954.4 | 511943.8 | 74778 | 1.64041666667 | 16987 |
| 018527 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:17pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595954.2 | 511943.6 | 74780 | 1.64041666667 | 18527 |
| 015521 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:18pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595952.0 | 511943.4 | 74782 | 1.64041666667 | 15521 |
| 016120 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:19pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595949.1 | 511942.9 | 74784 | 1.64041666667 | 16120 |
| 014350 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:20pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595945.7 | 511941.8 | 74786 | 1.64041666667 | 14350 |
| 013067 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:21pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595942.3 | 511940.8 | 74788 | 1.64041666667 | 13067 |
| 011366 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:22pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595939.2 | 511940.6 | 74790 | 1.64041666667 | 11366 |
| 012411 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:23pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595936.2 | 511941.6 | 74792 | 1.64041666667 | 12411 |
| 011533 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:24pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595932.7 | 511943.3 | 74794 | 1.64041666667 | 11533 |
| 012723 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:25pm | Sensor | 1797-S0049-G-TJV.cor | 6836.7 | 1595930.0 | 511945.0 | 74796 | 1.64041666667 | 12723 |
| 011760 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:26pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595926.7 | 511946.9 | 74798 | 1.64041666667 | 11760 |
| 011130 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:27pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595923.7 | 511948.0 | 74800 | 1.64041666667 | 11130 |
| 013192 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:28pm | Sensor | 1797-S0049-G-TJV.cor | 6836.8 | 1595919.9 | 511948.8 | 74802 | 1.64041666667 | 13192 |
| 012448 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:29pm | Sensor | 1797-S0049-G-TJV.cor | 6837.0 | 1595916.8 | 511949.6 | 74804 | 1.64041666667 | 12448 |
| 013912 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:30pm | Sensor | 1797-S0049-G-TJV.cor | 6837.1 | 1595913.4 | 511950.9 | 74806 | 1.64041666667 | 13912 |
| 011878 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:31pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595910.3 | 511952.1 | 74808 | 1.64041666667 | 11878 |
| 012389 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:32pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595906.8 | 511953.2 | 74810 | 1.64041666667 | 12389 |
| 011407 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:33pm | Sensor | 1797-S0049-G-TJV.cor | 6836.9 | 1595903.6 | 511953.8 | 74812 | 1.64041666667 | 11407 |
| 012721 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:34pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595900.1 | 511953.7 | 74814 | 1.64041666667 | 12721 |
| 011700 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:35pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595896.6 | 511952.8 | 74816 | 1.64041666667 | 11700 |
| 012825 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:36pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595893.4 | 511951.3 | 74818 | 1.64041666667 | 12825 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:37pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595891.2 | 511950.1 | 74820 | 1.64041666667 | 12536 |
| 013154 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:38pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1595888.7 | 511947.3 | 74822 | 1.64041666667 | 13154 |
| 011598 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:39pm | Sensor | 1797-S0049-G-TJV.cor | 6836.0 | 1595887.5 | 511944.4 | 74824 | 1.64041666667 | 11598 |
| 013189 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:40pm | Sensor | 1797-S0049-G-TJV.cor | 6835.9 | 1595886.0 | 511941.5 | 74826 | 1.64041666667 | 13189 |
| 012057 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:41pm | Sensor | 1797-S0049-G-TJV.cor | 6836.1 | 1595884.2 | 511938.9 | 74828 | 1.64041666667 | 12057 |
| 011774 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:42pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595882.6 | 511936.4 | 74830 | 1.64041666667 | 11774 |
| 011793 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:43pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595881.4 | 511934.4 | 74832 | 1.64041666667 | 11793 |
| 012758 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:44pm | Sensor | 1797-S0049-G-TJV.cor | 6836.6 | 1595879.5 | 511932.4 | 74834 | 1.64041666667 | 12758 |
| 013359 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:45pm | Sensor | 1797-S0049-G-TJV.cor | 6836.5 | 1595878.4 | 511932.6 | 74836 | 1.64041666667 | 13359 |
| 012490 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:46pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.4 | 511933.5 | 74838 | 1.64041666667 | 12490 |
| 012302 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:47pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.2 | 511933.8 | 74840 | 1.64041666667 | 12302 |
| 012795 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:48pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.2 | 511933.7 | 74842 | 1.64041666667 | 12795 |
| 013248 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:49pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.1 | 511933.6 | 74844 | 1.64041666667 | 13248 |
| 013062 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:50pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.0 | 511933.5 | 74846 | 1.64041666667 | 13062 |
| 012295 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:51pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595876.9 | 511933.5 | 74848 | 1.64041666667 | 12295 |
| 011534 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:52pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.1 | 511933.3 | 74850 | 1.64041666667 | 11534 |
| 012573 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:53pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.2 | 511933.4 | 74852 | 1.64041666667 | 12573 |
| 012173 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:54pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.0 | 511933.4 | 74854 | 1.64041666667 | 12173 |
| 011263 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:55pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.0 | 511933.3 | 74856 | 1.64041666667 | 11263 |
| 012566 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:56pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.3 | 511933.1 | 74858 | 1.64041666667 | 12566 |
| 012891 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:57pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.4 | 511933.2 | 74860 | 1.64041666667 | 12891 |
| 012222 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:58pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.5 | 511933.2 | 74862 | 1.64041666667 | 12222 |
| 011545 | 0 | GeoXH 6000 | 08/19/2015 | 04:04:59pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.5 | 511933.2 | 74864 | 1.64041666667 | 11545 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012066 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:00pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595877.4 | 511933.1 | 74866 | 1.64041666667 | 12066 |
| 011596 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:01pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.4 | 511933.1 | 74868 | 1.64041666667 | 11596 |
| 013249 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:02pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.4 | 511933.1 | 74870 | 1.64041666667 | 13249 |
| 012552 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:03pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.4 | 511933.2 | 74872 | 1.64041666667 | 12552 |
| 011658 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:04pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.3 | 511933.2 | 74874 | 1.64041666667 | 11658 |
| 011944 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:05pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.3 | 511933.2 | 74876 | 1.64041666667 | 11944 |
| 012466 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:06pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.2 | 511933.3 | 74878 | 1.64041666667 | 12466 |
| 012356 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:07pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.1 | 511933.3 | 74880 | 1.64041666667 | 12356 |
| 012719 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:08pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595877.0 | 511933.2 | 74882 | 1.64041666667 | 12719 |
| 013380 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:09pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595877.0 | 511933.2 | 74884 | 1.64041666667 | 13380 |
| 011355 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:10pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595877.0 | 511933.2 | 74886 | 1.64041666667 | 11355 |
| 011868 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:11pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595876.9 | 511933.3 | 74888 | 1.64041666667 | 11868 |
| 012567 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:12pm | Sensor | 1797-S0049-G-TJV.cor | 6836.4 | 1595876.9 | 511933.3 | 74890 | 1.64041666667 | 12567 |
| 012501 | 0 | GeoXH 6000 | 08/19/2015 | 04:05:13pm | Sensor | 1797-S0049-G-TJV.cor | 6836.3 | 1595876.9 | 511933.3 | 74892 | 1.64041666667 | 12501 |
| 008513 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:29pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595468.1 | 512893.9 | 69473 | 1.64041666667 | 8513 |
| 010408 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:29pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595468.1 | 512893.9 | 69474 | 1.64041666667 | 10408 |
| 010552 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:31pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512894.0 | 69478 | 1.64041666667 | 10552 |
| 009808 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:32pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595468.1 | 512894.0 | 69480 | 1.64041666667 | 9808 |
| 010342 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:33pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512893.9 | 69482 | 1.64041666667 | 10342 |
| 009995 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:34pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512893.9 | 69484 | 1.64041666667 | 9995 |
| 010028 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:35pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512893.8 | 69486 | 1.64041666667 | 10028 |
| 008717 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:36pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512893.9 | 69488 | 1.64041666667 | 8717 |
| 007969 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:37pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512893.9 | 69490 | 1.64041666667 | 7969 |
| 009432 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:38pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512894.0 | 69492 | 1.64041666667 | 9432 |
| 009378 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:39pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512894.0 | 69494 | 1.64041666667 | 9378 |
| 009544 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:40pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512894.0 | 69496 | 1.64041666667 | 9544 |
| 009226 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:41pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512894.0 | 69498 | 1.64041666667 | 9226 |
| 009866 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:42pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.1 | 512894.0 | 69500 | 1.64041666667 | 9866 |
| 009396 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:43pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.3 | 512894.0 | 69502 | 1.64041666667 | 9396 |
| 009249 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:43pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595468.7 | 512894.4 | 69503 | 1.64041666667 | 9249 |
| 009122 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:45pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595468.8 | 512894.5 | 69506 | 1.64041666667 | 9122 |
| 011070 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:46pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595468.9 | 512894.4 | 69508 | 1.64041666667 | 11070 |
| 010657 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:47pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595468.9 | 512894.5 | 69510 | 1.64041666667 | 10657 |
| 011064 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:48pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595468.7 | 512894.6 | 69512 | 1.64041666667 | 11064 |
| 009096 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:49pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595467.5 | 512895.0 | 69514 | 1.64041666667 | 9096 |
| 009414 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:50pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595467.0 | 512895.7 | 69516 | 1.64041666667 | 9414 |
| 011113 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:51pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595467.0 | 512895.5 | 69518 | 1.64041666667 | 11113 |
| 010698 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:52pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595468.0 | 512894.7 | 69520 | 1.64041666667 | 10698 |
| 010894 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:53pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.7 | 512894.9 | 69522 | 1.64041666667 | 10894 |
| 009533 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:54pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.6 | 512895.0 | 69524 | 1.64041666667 | 9533 |
| 010303 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:55pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595468.7 | 512895.2 | 69526 | 1.64041666667 | 10303 |
| 009206 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:56pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595468.7 | 512895.5 | 69528 | 1.64041666667 | 9206 |
| 009021 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:57pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595468.5 | 512895.0 | 69530 | 1.64041666667 | 9021 |
| 010115 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:58pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.6 | 512893.0 | 69532 | 1.64041666667 | 10115 |
| 009998 | 0 | GeoXH 6000 | 08/19/2015 | 05:17:59pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595469.4 | 512890.7 | 69534 | 1.64041666667 | 9998 |
| 010689 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:00pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595470.4 | 512890.0 | 69536 | 1.64041666667 | 10689 |
| 010682 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:01pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595470.0 | 512890.6 | 69538 | 1.64041666667 | 10682 |
| 009540 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:01pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595468.5 | 512890.8 | 69539 | 1.64041666667 | 9540 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009345 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:03pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595468.1 | 512893.4 | 69542 | 1.64041666667 | 9345 |
| 010286 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:04pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595467.1 | 512895.5 | 69544 | 1.64041666667 | 10286 |
| 010011 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:05pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595466.5 | 512898.6 | 69546 | 1.64041666667 | 10011 |
| 011503 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:05pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595466.1 | 512899.9 | 69547 | 1.64041666667 | 11503 |
| 010915 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:07pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595465.9 | 512900.4 | 69550 | 1.64041666667 | 10915 |
| 011249 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:07pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595466.0 | 512900.2 | 69551 | 1.64041666667 | 11249 |
| 010642 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:09pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595466.0 | 512900.1 | 69554 | 1.64041666667 | 10642 |
| 011900 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:09pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595466.0 | 512900.1 | 69555 | 1.64041666667 | 11900 |
| 009365 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:11pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595465.9 | 512900.1 | 69558 | 1.64041666667 | 9365 |
| 011641 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:12pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595465.9 | 512900.1 | 69560 | 1.64041666667 | 11641 |
| 010650 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:13pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595465.9 | 512900.3 | 69562 | 1.64041666667 | 10650 |
| 011422 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:13pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595465.7 | 512902.6 | 69563 | 1.64041666667 | 11422 |
| 010655 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:15pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595465.4 | 512903.6 | 69566 | 1.64041666667 | 10655 |
| 010374 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:16pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595465.3 | 512903.7 | 69568 | 1.64041666667 | 10374 |
| 010093 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:17pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595465.3 | 512903.8 | 69570 | 1.64041666667 | 10093 |
| 010413 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:18pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595465.5 | 512903.8 | 69572 | 1.64041666667 | 10413 |
| 010043 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595465.3 | 512903.4 | 69574 | 1.64041666667 | 10043 |
| 011360 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:20pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595464.7 | 512901.1 | 69576 | 1.64041666667 | 11360 |
| 009950 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595463.0 | 512900.4 | 69578 | 1.64041666667 | 9950 |
| 009897 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:22pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595462.9 | 512900.2 | 69580 | 1.64041666667 | 9897 |
| 011474 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595463.3 | 512899.9 | 69582 | 1.64041666667 | 11474 |
| 010428 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595463.3 | 512898.6 | 69584 | 1.64041666667 | 10428 |
| 010227 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:25pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595462.8 | 512898.4 | 69586 | 1.64041666667 | 10227 |
| 010746 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:26pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595462.7 | 512898.2 | 69588 | 1.64041666667 | 10746 |
| 010276 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:27pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595462.9 | 512898.4 | 69590 | 1.64041666667 | 10276 |
| 008539 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:28pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595462.9 | 512898.4 | 69592 | 1.64041666667 | 8539 |
| 009724 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:29pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595463.2 | 512898.2 | 69594 | 1.64041666667 | 9724 |
| 008491 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:30pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595463.8 | 512899.0 | 69596 | 1.64041666667 | 8491 |
| 009592 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:31pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595465.1 | 512899.9 | 69598 | 1.64041666667 | 9592 |
| 011068 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:32pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595464.8 | 512897.6 | 69600 | 1.64041666667 | 11068 |
| 011317 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:33pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595464.0 | 512895.8 | 69602 | 1.64041666667 | 11317 |
| 010659 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:34pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595462.3 | 512894.7 | 69604 | 1.64041666667 | 10659 |
| 010944 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:35pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595459.7 | 512895.0 | 69606 | 1.64041666667 | 10944 |
| 011586 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:36pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595457.6 | 512894.7 | 69608 | 1.64041666667 | 11586 |
| 010966 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:37pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595454.6 | 512895.9 | 69610 | 1.64041666667 | 10966 |
| 011381 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:38pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595452.3 | 512896.5 | 69612 | 1.64041666667 | 11381 |
| 011725 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:39pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595450.7 | 512898.0 | 69614 | 1.64041666667 | 11725 |
| 011151 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:40pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595450.7 | 512897.6 | 69616 | 1.64041666667 | 11151 |
| 011097 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:41pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595448.8 | 512896.6 | 69618 | 1.64041666667 | 11097 |
| 010154 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:42pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595448.2 | 512894.7 | 69620 | 1.64041666667 | 10154 |
| 010308 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:43pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595446.2 | 512893.9 | 69622 | 1.64041666667 | 10308 |
| 011697 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:43pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595446.1 | 512892.6 | 69623 | 1.64041666667 | 11697 |
| 011594 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:45pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595444.2 | 512892.2 | 69626 | 1.64041666667 | 11594 |
| 009858 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:46pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595443.3 | 512891.7 | 69628 | 1.64041666667 | 9858 |
| 010534 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:47pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595442.4 | 512891.6 | 69630 | 1.64041666667 | 10534 |
| 009923 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:48pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595441.6 | 512891.9 | 69632 | 1.64041666667 | 9923 |
| 011841 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:49pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595441.2 | 512891.8 | 69634 | 1.64041666667 | 11841 |
| 011840 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:50pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595440.2 | 512892.6 | 69636 | 1.64041666667 | 11840 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010280 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:51pm | Sensor | 1797-S0048-G-TJV.cor | 6837.2 | 1595439.1 | 512893.2 | 69638 | 1.64041666667 | 10280 |
| 010730 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:52pm | Sensor | 1797-S0048-G-TJV.cor | 6837.1 | 1595437.8 | 512894.2 | 69640 | 1.64041666667 | 10730 |
| 011502 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:53pm | Sensor | 1797-S0048-G-TJV.cor | 6837.0 | 1595436.0 | 512895.0 | 69642 | 1.64041666667 | 11502 |
| 012715 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:54pm | Sensor | 1797-S0048-G-TJV.cor | 6837.0 | 1595434.4 | 512896.1 | 69644 | 1.64041666667 | 12715 |
| 011969 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:55pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595432.6 | 512896.8 | 69646 | 1.64041666667 | 11969 |
| 011392 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:56pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595431.4 | 512897.8 | 69648 | 1.64041666667 | 11392 |
| 012688 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:57pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595429.9 | 512898.4 | 69650 | 1.64041666667 | 12688 |
| 011662 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:58pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595428.2 | 512899.6 | 69652 | 1.64041666667 | 11662 |
| 011315 | 0 | GeoXH 6000 | 08/19/2015 | 05:18:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595427.5 | 512900.1 | 69654 | 1.64041666667 | 11315 |
| 011108 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:00pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595426.7 | 512899.1 | 69656 | 1.64041666667 | 11108 |
| 012167 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:01pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595424.8 | 512897.7 | 69658 | 1.64041666667 | 12167 |
| 012101 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:01pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595423.7 | 512896.5 | 69659 | 1.64041666667 | 12101 |
| 011755 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:03pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595421.5 | 512894.6 | 69662 | 1.64041666667 | 11755 |
| 012269 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:04pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595420.4 | 512893.2 | 69664 | 1.64041666667 | 12269 |
| 012007 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:05pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595418.7 | 512891.2 | 69666 | 1.64041666667 | 12007 |
| 011791 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:05pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595418.3 | 512889.7 | 69667 | 1.64041666667 | 11791 |
| 011587 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:07pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595416.7 | 512887.5 | 69670 | 1.64041666667 | 11587 |
| 012557 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:08pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595415.1 | 512886.2 | 69672 | 1.64041666667 | 12557 |
| 013249 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:09pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595413.3 | 512884.3 | 69674 | 1.64041666667 | 13249 |
| 013272 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:10pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595411.3 | 512883.1 | 69676 | 1.64041666667 | 13272 |
| 013278 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:11pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595409.5 | 512881.4 | 69678 | 1.64041666667 | 13278 |
| 013279 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:12pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595407.5 | 512880.4 | 69680 | 1.64041666667 | 13279 |
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:13pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595405.7 | 512878.4 | 69682 | 1.64041666667 | 12019 |
| 012665 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:14pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595403.4 | 512877.5 | 69684 | 1.64041666667 | 12665 |
| 011476 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:15pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595401.9 | 512875.7 | 69686 | 1.64041666667 | 11476 |
| 012739 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:16pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595400.3 | 512874.0 | 69688 | 1.64041666667 | 12739 |
| 011974 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:17pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595398.4 | 512871.8 | 69690 | 1.64041666667 | 11974 |
| 012203 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:18pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595397.5 | 512869.9 | 69692 | 1.64041666667 | 12203 |
| 011631 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:19pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595395.9 | 512868.0 | 69694 | 1.64041666667 | 11631 |
| 013347 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595395.1 | 512865.8 | 69696 | 1.64041666667 | 13347 |
| 012457 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595393.1 | 512864.4 | 69698 | 1.64041666667 | 12457 |
| 011814 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595391.9 | 512862.9 | 69699 | 1.64041666667 | 11814 |
| 010513 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595390.0 | 512861.7 | 69702 | 1.64041666667 | 10513 |
| 011238 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595388.9 | 512860.5 | 69703 | 1.64041666667 | 11238 |
| 010519 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595386.0 | 512859.7 | 69706 | 1.64041666667 | 10519 |
| 011509 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:26pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595383.6 | 512858.9 | 69708 | 1.64041666667 | 11509 |
| 011457 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:27pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595380.9 | 512857.6 | 69710 | 1.64041666667 | 11457 |
| 011504 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:27pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595378.8 | 512857.1 | 69711 | 1.64041666667 | 11504 |
| 013646 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:29pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595376.9 | 512855.3 | 69714 | 1.64041666667 | 13646 |
| 012981 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:30pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595374.5 | 512854.3 | 69716 | 1.64041666667 | 12981 |
| 011495 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:31pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595372.7 | 512852.5 | 69718 | 1.64041666667 | 11495 |
| 010913 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:31pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595371.1 | 512851.4 | 69719 | 1.64041666667 | 10913 |
| 010498 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:33pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595370.5 | 512849.8 | 69722 | 1.64041666667 | 10498 |
| 011264 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:33pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595369.0 | 512848.8 | 69723 | 1.64041666667 | 11264 |
| 011276 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:35pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595368.3 | 512847.6 | 69726 | 1.64041666667 | 11276 |
| 011159 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:36pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595368.3 | 512847.5 | 69728 | 1.64041666667 | 11159 |
| 012509 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:37pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595368.4 | 512847.5 | 69730 | 1.64041666667 | 12509 |
| 011257 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:37pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595368.3 | 512847.6 | 69731 | 1.64041666667 | 11257 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013404 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:39pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595367.6 | 512847.6 | 69734 | 1.64041666667 | 13404 |
| 012291 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:40pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595367.7 | 512847.6 | 69736 | 1.64041666667 | 12291 |
| 012012 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:41pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595367.7 | 512846.7 | 69738 | 1.64041666667 | 12012 |
| 011103 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:42pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595367.7 | 512846.7 | 69740 | 1.64041666667 | 11103 |
| 011475 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:43pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595367.9 | 512846.6 | 69742 | 1.64041666667 | 11475 |
| 012318 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:44pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595367.6 | 512846.8 | 69744 | 1.64041666667 | 12318 |
| 011509 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595367.5 | 512846.9 | 69746 | 1.64041666667 | 11509 |
| 010857 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595367.5 | 512847.5 | 69747 | 1.64041666667 | 10857 |
| 011624 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:46pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595365.3 | 512848.6 | 69749 | 1.64041666667 | 11624 |
| 011936 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:48pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595362.9 | 512850.5 | 69752 | 1.64041666667 | 11936 |
| 012614 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:48pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595360.6 | 512851.5 | 69753 | 1.64041666667 | 12614 |
| 014313 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:49pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595361.4 | 512852.4 | 69755 | 1.64041666667 | 14313 |
| 012998 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:51pm | Sensor | 1797-S0048-G-TJV.cor | 6834.0 | 1595361.1 | 512853.3 | 69758 | 1.64041666667 | 12998 |
| 014109 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:51pm | Sensor | 1797-S0048-G-TJV.cor | 6834.0 | 1595361.6 | 512854.5 | 69759 | 1.64041666667 | 14109 |
| 013547 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:53pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595362.0 | 512856.3 | 69762 | 1.64041666667 | 13547 |
| 013256 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:54pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595361.9 | 512856.0 | 69764 | 1.64041666667 | 13256 |
| 013064 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:55pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595361.6 | 512856.2 | 69766 | 1.64041666667 | 13064 |
| 013886 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:56pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595362.2 | 512858.2 | 69768 | 1.64041666667 | 13886 |
| 012561 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:57pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595362.8 | 512861.1 | 69770 | 1.64041666667 | 12561 |
| 013010 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:58pm | Sensor | 1797-S0048-G-TJV.cor | 6833.9 | 1595364.2 | 512864.1 | 69772 | 1.64041666667 | 13010 |
| 012612 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:59pm | Sensor | 1797-S0048-G-TJV.cor | 6833.3 | 1595364.4 | 512865.0 | 69774 | 1.64041666667 | 12612 |
| 011643 | 0 | GeoXH 6000 | 08/19/2015 | 05:19:59pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595364.2 | 512863.4 | 69775 | 1.64041666667 | 11643 |
| 012630 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595364.0 | 512861.6 | 69778 | 1.64041666667 | 12630 |
| 010867 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:02pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595363.4 | 512859.3 | 69780 | 1.64041666667 | 10867 |
| 013097 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:03pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595363.3 | 512856.6 | 69782 | 1.64041666667 | 13097 |
| 013714 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:04pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595364.2 | 512855.1 | 69784 | 1.64041666667 | 13714 |
| 013298 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:05pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595366.2 | 512853.0 | 69786 | 1.64041666667 | 13298 |
| 013254 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:06pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595368.3 | 512853.5 | 69788 | 1.64041666667 | 13254 |
| 010903 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:07pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595371.5 | 512855.1 | 69790 | 1.64041666667 | 10903 |
| 010736 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:08pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595374.3 | 512856.1 | 69792 | 1.64041666667 | 10736 |
| 011864 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:09pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595377.0 | 512858.4 | 69794 | 1.64041666667 | 11864 |
| 011 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:10pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595379.8 | 512860.0 | 69796 | 1.64041666667 | 11 |
| 011024 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:11pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595382.9 | 512861.7 | 69798 | 1.64041666667 | 11024 |
| 012146 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:11pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595385.0 | 512862.9 | 69799 | 1.64041666667 | 12146 |
| 011886 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:13pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595388.9 | 512864.2 | 69802 | 1.64041666667 | 11886 |
| 012961 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:14pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595391.4 | 512865.5 | 69804 | 1.64041666667 | 12961 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:15pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595394.7 | 512867.2 | 69806 | 1.64041666667 | 12180 |
| 011025 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:16pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595396.5 | 512867.6 | 69808 | 1.64041666667 | 11025 |
| 011516 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:17pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595399.0 | 512868.8 | 69810 | 1.64041666667 | 11516 |
| 010019 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:17pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595401.8 | 512870.1 | 69811 | 1.64041666667 | 10019 |
| 013785 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:19pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595405.3 | 512871.0 | 69814 | 1.64041666667 | 13785 |
| 012476 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:20pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595407.2 | 512872.3 | 69816 | 1.64041666667 | 12476 |
| 012299 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:21pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595410.9 | 512873.9 | 69818 | 1.64041666667 | 12299 |
| 012824 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:21pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595412.9 | 512874.8 | 69819 | 1.64041666667 | 12824 |
| 011456 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595415.8 | 512876.6 | 69822 | 1.64041666667 | 11456 |
| 011204 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595418.3 | 512877.9 | 69823 | 1.64041666667 | 11204 |
| 011201 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595421.4 | 512879.9 | 69826 | 1.64041666667 | 11201 |
| 013540 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:26pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595423.8 | 512881.0 | 69828 | 1.64041666667 | 13540 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011995 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:26pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595426.4 | 512881.4 | 69829 | 1.64041666667 | 11995 |
| 011968 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:27pm | Sensor | 1797-S0048-G-TJV.cor | 6836.9 | 1595428.8 | 512882.4 | 69831 | 1.64041666667 | 11968 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:29pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595432.0 | 512883.4 | 69834 | 1.64041666667 | 11962 |
| 011990 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:29pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595434.9 | 512883.9 | 69835 | 1.64041666667 | 11990 |
| 011097 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:31pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595438.1 | 512885.7 | 69838 | 1.64041666667 | 11097 |
| 010874 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:31pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595440.8 | 512886.5 | 69839 | 1.64041666667 | 10874 |
| 011388 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:33pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595444.6 | 512888.2 | 69842 | 1.64041666667 | 11388 |
| 011097 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:33pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595446.5 | 512889.6 | 69843 | 1.64041666667 | 11097 |
| 010394 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:35pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595449.6 | 512891.3 | 69846 | 1.64041666667 | 10394 |
| 010578 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:35pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595451.9 | 512893.1 | 69847 | 1.64041666667 | 10578 |
| 010834 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:37pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595455.1 | 512895.7 | 69850 | 1.64041666667 | 10834 |
| 010148 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:37pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595457.4 | 512896.7 | 69851 | 1.64041666667 | 10148 |
| 010397 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:39pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595460.7 | 512898.1 | 69854 | 1.64041666667 | 10397 |
| 010609 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:39pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595463.7 | 512898.8 | 69855 | 1.64041666667 | 10609 |
| 010332 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:41pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595466.7 | 512899.8 | 69858 | 1.64041666667 | 10332 |
| 010053 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:41pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595469.0 | 512900.6 | 69859 | 1.64041666667 | 10053 |
| 010553 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:43pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595470.4 | 512900.1 | 69862 | 1.64041666667 | 10553 |
| 011218 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:44pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595470.2 | 512899.5 | 69864 | 1.64041666667 | 11218 |
| 009584 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:45pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595470.1 | 512899.7 | 69866 | 1.64041666667 | 9584 |
| 010346 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:45pm | Sensor | 1797-S0048-G-TJV.cor | 6836.9 | 1595470.0 | 512900.3 | 69867 | 1.64041666667 | 10346 |
| 010266 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:47pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595467.8 | 512899.6 | 69870 | 1.64041666667 | 10266 |
| 009166 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:47pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595466.0 | 512899.0 | 69871 | 1.64041666667 | 9166 |
| 010871 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:49pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595464.0 | 512899.5 | 69874 | 1.64041666667 | 10871 |
| 012438 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:49pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595462.5 | 512899.6 | 69875 | 1.64041666667 | 12438 |
| 011599 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:51pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595463.3 | 512899.0 | 69878 | 1.64041666667 | 11599 |
| 010189 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:51pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595463.2 | 512900.4 | 69879 | 1.64041666667 | 10189 |
| 011637 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:53pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595462.3 | 512904.2 | 69882 | 1.64041666667 | 11637 |
| 010439 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:53pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595462.6 | 512906.7 | 69883 | 1.64041666667 | 10439 |
| 010680 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:55pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595462.8 | 512907.6 | 69886 | 1.64041666667 | 10680 |
| 010620 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:55pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595461.8 | 512909.4 | 69887 | 1.64041666667 | 10620 |
| 010305 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:56pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595461.7 | 512912.5 | 69889 | 1.64041666667 | 10305 |
| 009476 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:57pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595459.4 | 512913.7 | 69891 | 1.64041666667 | 9476 |
| 010349 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:58pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595459.1 | 512914.6 | 69893 | 1.64041666667 | 10349 |
| 012427 | 0 | GeoXH 6000 | 08/19/2015 | 05:20:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595457.6 | 512914.1 | 69895 | 1.64041666667 | 12427 |
| 010276 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595457.3 | 512913.9 | 69898 | 1.64041666667 | 10276 |
| 011029 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595457.5 | 512914.0 | 69899 | 1.64041666667 | 11029 |
| 010497 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:02pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595458.0 | 512914.3 | 69901 | 1.64041666667 | 10497 |
| 009674 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:03pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595459.0 | 512914.8 | 69903 | 1.64041666667 | 9674 |
| 011988 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:04pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595460.3 | 512914.1 | 69905 | 1.64041666667 | 11988 |
| 011277 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:05pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595459.9 | 512912.0 | 69907 | 1.64041666667 | 11277 |
| 011279 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:06pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595459.7 | 512909.3 | 69909 | 1.64041666667 | 11279 |
| 009990 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:07pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595458.3 | 512907.1 | 69911 | 1.64041666667 | 9990 |
| 011917 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:09pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595455.2 | 512905.8 | 69914 | 1.64041666667 | 11917 |
| 010869 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:09pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595452.9 | 512904.5 | 69915 | 1.64041666667 | 10869 |
| 011117 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:11pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595448.9 | 512903.6 | 69918 | 1.64041666667 | 11117 |
| 010969 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:11pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595445.7 | 512903.1 | 69919 | 1.64041666667 | 10969 |
| 011022 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:13pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595443.0 | 512902.2 | 69922 | 1.64041666667 | 11022 |
| 011395 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:13pm | Sensor | 1797-S0048-G-TJV.cor | 6836.9 | 1595441.1 | 512902.4 | 69923 | 1.64041666667 | 11395 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010409 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:14pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595438.5 | 512901.3 | 69925 | 1.64041666667 | 10409 |
| 011782 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:15pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595435.3 | 512899.6 | 69927 | 1.64041666667 | 11782 |
| 012005 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:17pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595432.1 | 512899.1 | 69930 | 1.64041666667 | 12005 |
| 011581 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:17pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595430.2 | 512897.8 | 69931 | 1.64041666667 | 11581 |
| 011235 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595427.2 | 512896.3 | 69934 | 1.64041666667 | 11235 |
| 011058 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595424.1 | 512895.4 | 69935 | 1.64041666667 | 11058 |
| 011224 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595421.2 | 512893.6 | 69938 | 1.64041666667 | 11224 |
| 011566 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595418.9 | 512892.8 | 69939 | 1.64041666667 | 11566 |
| 013121 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595416.5 | 512891.2 | 69942 | 1.64041666667 | 13121 |
| 013120 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:23pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595413.7 | 512889.7 | 69943 | 1.64041666667 | 13120 |
| 011500 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595410.9 | 512889.6 | 69945 | 1.64041666667 | 11500 |
| 011185 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595408.3 | 512888.5 | 69947 | 1.64041666667 | 11185 |
| 011706 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:26pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595405.3 | 512888.3 | 69949 | 1.64041666667 | 11706 |
| 011086 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:27pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595402.8 | 512887.4 | 69951 | 1.64041666667 | 11086 |
| 013331 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595399.7 | 512885.2 | 69954 | 1.64041666667 | 13331 |
| 014673 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595397.0 | 512884.2 | 69955 | 1.64041666667 | 14673 |
| 013148 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:31pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595394.0 | 512882.3 | 69958 | 1.64041666667 | 13148 |
| 009917 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:31pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595391.1 | 512881.1 | 69959 | 1.64041666667 | 9917 |
| 010549 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:33pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595388.0 | 512879.6 | 69962 | 1.64041666667 | 10549 |
| 011127 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:33pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595386.0 | 512877.8 | 69963 | 1.64041666667 | 11127 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:35pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595382.9 | 512876.1 | 69966 | 1.64041666667 | 11962 |
| 012020 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:35pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595380.7 | 512874.4 | 69967 | 1.64041666667 | 12020 |
| 012425 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:37pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595377.1 | 512872.0 | 69970 | 1.64041666667 | 12425 |
| 014866 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:38pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595374.4 | 512871.1 | 69972 | 1.64041666667 | 14866 |
| 010256 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:39pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595371.7 | 512869.4 | 69974 | 1.64041666667 | 10256 |
| 010934 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:39pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595369.3 | 512868.5 | 69975 | 1.64041666667 | 10934 |
| 012993 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:40pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595366.8 | 512867.4 | 69977 | 1.64041666667 | 12993 |
| 013118 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:41pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595365.0 | 512865.5 | 69979 | 1.64041666667 | 13118 |
| 012309 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:42pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595365.2 | 512866.8 | 69981 | 1.64041666667 | 12309 |
| 011147 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:43pm | Sensor | 1797-S0048-G-TJV.cor | 6833.8 | 1595364.8 | 512869.7 | 69983 | 1.64041666667 | 11147 |
| 011096 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:44pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595364.7 | 512872.7 | 69985 | 1.64041666667 | 11096 |
| 011474 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595364.3 | 512873.5 | 69987 | 1.64041666667 | 11474 |
| 011748 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:46pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595362.9 | 512875.8 | 69989 | 1.64041666667 | 11748 |
| 011487 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:47pm | Sensor | 1797-S0048-G-TJV.cor | 6834.0 | 1595362.1 | 512879.0 | 69991 | 1.64041666667 | 11487 |
| 011931 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:49pm | Sensor | 1797-S0048-G-TJV.cor | 6833.4 | 1595361.0 | 512882.4 | 69994 | 1.64041666667 | 11931 |
| 013093 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:49pm | Sensor | 1797-S0048-G-TJV.cor | 6833.8 | 1595361.0 | 512882.7 | 69995 | 1.64041666667 | 13093 |
| 013023 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:50pm | Sensor | 1797-S0048-G-TJV.cor | 6833.7 | 1595361.2 | 512883.5 | 69997 | 1.64041666667 | 13023 |
| 010845 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:51pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595360.7 | 512882.0 | 69999 | 1.64041666667 | 10845 |
| 011411 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:52pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595362.1 | 512880.2 | 70001 | 1.64041666667 | 11411 |
| 012033 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:53pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595363.8 | 512877.5 | 70003 | 1.64041666667 | 12033 |
| 011408 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:55pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595366.5 | 512876.6 | 70006 | 1.64041666667 | 11408 |
| 010832 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:55pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595370.1 | 512877.1 | 70007 | 1.64041666667 | 10832 |
| 011198 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:56pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595373.2 | 512877.1 | 70009 | 1.64041666667 | 11198 |
| 014229 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:57pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595375.5 | 512878.3 | 70011 | 1.64041666667 | 14229 |
| 011597 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:59pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595378.6 | 512879.3 | 70014 | 1.64041666667 | 11597 |
| 012349 | 0 | GeoXH 6000 | 08/19/2015 | 05:21:59pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595380.7 | 512880.5 | 70015 | 1.64041666667 | 12349 |
| 011577 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595383.9 | 512882.5 | 70018 | 1.64041666667 | 11577 |
| 011384 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595386.2 | 512883.5 | 70019 | 1.64041666667 | 11384 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011216 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:03pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595388.9 | 512885.8 | 70022 | 1.64041666667 | 11216 |
| 010904 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:03pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595391.1 | 512887.7 | 70023 | 1.64041666667 | 10904 |
| 012086 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:05pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595394.3 | 512889.0 | 70026 | 1.64041666667 | 12086 |
| 012111 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:05pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595396.2 | 512890.2 | 70027 | 1.64041666667 | 12111 |
| 011667 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:07pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595399.2 | 512891.4 | 70030 | 1.64041666667 | 11667 |
| 010867 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:07pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595401.7 | 512892.2 | 70031 | 1.64041666667 | 10867 |
| 012916 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:09pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595404.7 | 512893.8 | 70034 | 1.64041666667 | 12916 |
| 010609 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:10pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595406.6 | 512894.7 | 70036 | 1.64041666667 | 10609 |
| 010692 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:11pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595408.7 | 512896.3 | 70038 | 1.64041666667 | 10692 |
| 010593 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:11pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595411.4 | 512898.2 | 70039 | 1.64041666667 | 10593 |
| 010868 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:13pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595414.7 | 512899.3 | 70042 | 1.64041666667 | 10868 |
| 012827 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:13pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595416.7 | 512900.3 | 70043 | 1.64041666667 | 12827 |
| 011306 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:15pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595420.1 | 512900.0 | 70046 | 1.64041666667 | 11306 |
| 009876 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:15pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595423.0 | 512900.1 | 70047 | 1.64041666667 | 9876 |
| 011349 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:17pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595426.1 | 512901.2 | 70050 | 1.64041666667 | 11349 |
| 012317 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:18pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595429.1 | 512901.9 | 70052 | 1.64041666667 | 12317 |
| 012259 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595431.6 | 512903.9 | 70054 | 1.64041666667 | 12259 |
| 011884 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595433.9 | 512906.2 | 70056 | 1.64041666667 | 11884 |
| 012151 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:20pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595436.6 | 512907.7 | 70057 | 1.64041666667 | 12151 |
| 011647 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595438.9 | 512909.1 | 70059 | 1.64041666667 | 11647 |
| 012902 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595442.5 | 512909.7 | 70062 | 1.64041666667 | 12902 |
| 010425 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595445.3 | 512910.0 | 70063 | 1.64041666667 | 10425 |
| 012146 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595448.0 | 512911.7 | 70065 | 1.64041666667 | 12146 |
| 010506 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595450.4 | 512911.9 | 70067 | 1.64041666667 | 10506 |
| 009616 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:27pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595452.6 | 512913.3 | 70070 | 1.64041666667 | 9616 |
| 009844 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:27pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595455.4 | 512914.1 | 70071 | 1.64041666667 | 9844 |
| 011071 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:28pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595455.2 | 512913.8 | 70073 | 1.64041666667 | 11071 |
| 012067 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595453.6 | 512915.7 | 70075 | 1.64041666667 | 12067 |
| 010037 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:31pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595453.2 | 512918.6 | 70078 | 1.64041666667 | 10037 |
| 011599 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:31pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595453.0 | 512919.5 | 70079 | 1.64041666667 | 11599 |
| 010849 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:33pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595452.0 | 512920.1 | 70082 | 1.64041666667 | 10849 |
| 012432 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:33pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595451.4 | 512922.5 | 70083 | 1.64041666667 | 12432 |
| 011388 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:35pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595449.9 | 512924.1 | 70086 | 1.64041666667 | 11388 |
| 011757 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:35pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595448.8 | 512924.9 | 70087 | 1.64041666667 | 11757 |
| 011279 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:36pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595448.5 | 512925.0 | 70089 | 1.64041666667 | 11279 |
| 012240 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:37pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595448.5 | 512924.9 | 70091 | 1.64041666667 | 12240 |
| 011160 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:39pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595448.6 | 512925.2 | 70094 | 1.64041666667 | 11160 |
| 011580 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:39pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595449.3 | 512925.2 | 70095 | 1.64041666667 | 11580 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:40pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595451.4 | 512925.6 | 70097 | 1.64041666667 | 12045 |
| 012311 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:41pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595450.9 | 512923.5 | 70099 | 1.64041666667 | 12311 |
| 011117 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:42pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595452.4 | 512921.6 | 70101 | 1.64041666667 | 11117 |
| 011149 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:43pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595451.6 | 512920.3 | 70103 | 1.64041666667 | 11149 |
| 011367 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:45pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595449.1 | 512917.8 | 70106 | 1.64041666667 | 11367 |
| 011152 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:45pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595446.6 | 512917.3 | 70107 | 1.64041666667 | 11152 |
| 010768 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:47pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595443.6 | 512915.8 | 70110 | 1.64041666667 | 10768 |
| 011422 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:47pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595440.9 | 512914.3 | 70111 | 1.64041666667 | 11422 |
| 010835 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:49pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595438.1 | 512913.1 | 70114 | 1.64041666667 | 10835 |
| 010868 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:49pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595435.6 | 512911.7 | 70115 | 1.64041666667 | 10868 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011147 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:50pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595432.7 | 512911.9 | 70117 | 1.64041666667 | 11147 |
| 010706 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:51pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595429.5 | 512911.4 | 70119 | 1.64041666667 | 10706 |
| 010866 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:52pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595426.8 | 512910.0 | 70121 | 1.64041666667 | 10866 |
| 011956 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:53pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595424.9 | 512908.8 | 70123 | 1.64041666667 | 11956 |
| 010789 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:54pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595423.6 | 512906.4 | 70125 | 1.64041666667 | 10789 |
| 011607 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:55pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595421.4 | 512905.5 | 70127 | 1.64041666667 | 11607 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:56pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595418.3 | 512904.2 | 70129 | 1.64041666667 | 12442 |
| 011090 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:57pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595415.4 | 512903.7 | 70131 | 1.64041666667 | 11090 |
| 013062 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:58pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595411.9 | 512902.7 | 70133 | 1.64041666667 | 13062 |
| 012805 | 0 | GeoXH 6000 | 08/19/2015 | 05:22:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595408.9 | 512901.2 | 70135 | 1.64041666667 | 12805 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:00pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595405.6 | 512900.2 | 70137 | 1.64041666667 | 12021 |
| 010325 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595403.1 | 512898.6 | 70139 | 1.64041666667 | 10325 |
| 012271 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:03pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595400.0 | 512896.2 | 70142 | 1.64041666667 | 12271 |
| 013057 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:03pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595397.6 | 512895.3 | 70143 | 1.64041666667 | 13057 |
| 011694 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:04pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595395.2 | 512893.6 | 70145 | 1.64041666667 | 11694 |
| 011053 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:05pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595391.8 | 512892.9 | 70147 | 1.64041666667 | 11053 |
| 010503 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:06pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595388.6 | 512892.8 | 70149 | 1.64041666667 | 10503 |
| 010635 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:07pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595386.0 | 512891.6 | 70151 | 1.64041666667 | 10635 |
| 009708 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:08pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595382.8 | 512890.8 | 70153 | 1.64041666667 | 9708 |
| 010587 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:09pm | Sensor | 1797-S0048-G-TJV.cor | 6834.0 | 1595379.3 | 512889.8 | 70155 | 1.64041666667 | 10587 |
| 009757 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:10pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595376.9 | 512888.1 | 70157 | 1.64041666667 | 9757 |
| 011649 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:11pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595374.4 | 512887.2 | 70159 | 1.64041666667 | 11649 |
| 012842 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:12pm | Sensor | 1797-S0048-G-TJV.cor | 6834.0 | 1595370.6 | 512885.5 | 70161 | 1.64041666667 | 12842 |
| 011401 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:13pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595368.3 | 512884.3 | 70163 | 1.64041666667 | 11401 |
| 012135 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:14pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595365.9 | 512883.7 | 70165 | 1.64041666667 | 12135 |
| 013203 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:15pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595363.2 | 512883.3 | 70167 | 1.64041666667 | 13203 |
| 012601 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:16pm | Sensor | 1797-S0048-G-TJV.cor | 6833.6 | 1595360.4 | 512883.3 | 70169 | 1.64041666667 | 12601 |
| 014010 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:17pm | Sensor | 1797-S0048-G-TJV.cor | 6833.9 | 1595360.4 | 512884.0 | 70171 | 1.64041666667 | 14010 |
| 011722 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:18pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595359.1 | 512886.7 | 70173 | 1.64041666667 | 11722 |
| 011300 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:19pm | Sensor | 1797-S0048-G-TJV.cor | 6834.0 | 1595358.8 | 512889.6 | 70175 | 1.64041666667 | 11300 |
| 011345 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:20pm | Sensor | 1797-S0048-G-TJV.cor | 6834.0 | 1595358.6 | 512890.6 | 70177 | 1.64041666667 | 11345 |
| 011236 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:21pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595357.6 | 512892.6 | 70179 | 1.64041666667 | 11236 |
| 010939 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:22pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595356.4 | 512895.8 | 70181 | 1.64041666667 | 10939 |
| 012364 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:23pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595355.2 | 512897.4 | 70183 | 1.64041666667 | 12364 |
| 013351 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:24pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595355.2 | 512897.6 | 70185 | 1.64041666667 | 13351 |
| 010927 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:25pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595355.7 | 512896.7 | 70187 | 1.64041666667 | 10927 |
| 011132 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:26pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595356.2 | 512895.3 | 70189 | 1.64041666667 | 11132 |
| 013493 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:27pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595357.3 | 512894.7 | 70191 | 1.64041666667 | 13493 |
| 012763 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:28pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595358.0 | 512893.0 | 70193 | 1.64041666667 | 12763 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:29pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595358.6 | 512891.4 | 70195 | 1.64041666667 | 12431 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:30pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595360.3 | 512889.6 | 70197 | 1.64041666667 | 12917 |
| 010549 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:31pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595362.1 | 512890.5 | 70199 | 1.64041666667 | 10549 |
| 010557 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:32pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595365.4 | 512891.7 | 70201 | 1.64041666667 | 10557 |
| 011159 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:33pm | Sensor | 1797-S0048-G-TJV.cor | 6834.0 | 1595368.6 | 512893.0 | 70203 | 1.64041666667 | 11159 |
| 012450 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:34pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595371.1 | 512894.7 | 70205 | 1.64041666667 | 12450 |
| 012382 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:35pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595373.8 | 512896.1 | 70207 | 1.64041666667 | 12382 |
| 011555 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:36pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595376.0 | 512898.2 | 70209 | 1.64041666667 | 11555 |
| 012308 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:37pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595378.6 | 512900.4 | 70211 | 1.64041666667 | 12308 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011357 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:38pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595381.7 | 512901.6 | 70213 | 1.64041666667 | 11357 |
| 012349 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:39pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595383.8 | 512903.3 | 70215 | 1.64041666667 | 12349 |
| 012477 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:40pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595386.8 | 512904.7 | 70217 | 1.64041666667 | 12477 |
| 010649 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:41pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595388.8 | 512906.3 | 70219 | 1.64041666667 | 10649 |
| 010792 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:42pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595391.2 | 512908.7 | 70221 | 1.64041666667 | 10792 |
| 010918 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:43pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595393.3 | 512909.9 | 70223 | 1.64041666667 | 10918 |
| 011639 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:44pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595395.8 | 512911.8 | 70225 | 1.64041666667 | 11639 |
| 010890 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595398.8 | 512913.3 | 70227 | 1.64041666667 | 10890 |
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:46pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595401.9 | 512913.9 | 70229 | 1.64041666667 | 12562 |
| 012560 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:47pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595403.8 | 512915.3 | 70231 | 1.64041666667 | 12560 |
| 011930 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:48pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595406.6 | 512916.6 | 70233 | 1.64041666667 | 11930 |
| 010992 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:49pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595409.5 | 512917.8 | 70235 | 1.64041666667 | 10992 |
| 011208 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:50pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595412.3 | 512919.6 | 70237 | 1.64041666667 | 11208 |
| 010842 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:51pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595414.4 | 512920.0 | 70239 | 1.64041666667 | 10842 |
| 011980 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:52pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595416.1 | 512921.6 | 70241 | 1.64041666667 | 11980 |
| 010975 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:53pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595418.5 | 512922.3 | 70243 | 1.64041666667 | 10975 |
| 011473 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:54pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595421.2 | 512923.5 | 70245 | 1.64041666667 | 11473 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:55pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595422.8 | 512924.3 | 70247 | 1.64041666667 | 12078 |
| 012109 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:56pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595424.9 | 512924.1 | 70249 | 1.64041666667 | 12109 |
| 011637 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:57pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595427.4 | 512924.4 | 70251 | 1.64041666667 | 11637 |
| 011969 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:58pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595430.3 | 512924.0 | 70253 | 1.64041666667 | 11969 |
| 012202 | 0 | GeoXH 6000 | 08/19/2015 | 05:23:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595432.4 | 512925.0 | 70255 | 1.64041666667 | 12202 |
| 014420 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:00pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595435.8 | 512925.5 | 70257 | 1.64041666667 | 14420 |
| 011735 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:01pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595438.3 | 512926.1 | 70259 | 1.64041666667 | 11735 |
| 013793 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:02pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595441.0 | 512925.5 | 70261 | 1.64041666667 | 13793 |
| 012478 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:03pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595442.8 | 512926.4 | 70263 | 1.64041666667 | 12478 |
| 011849 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:04pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595446.2 | 512927.1 | 70265 | 1.64041666667 | 11849 |
| 010342 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:05pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595447.8 | 512928.2 | 70267 | 1.64041666667 | 10342 |
| 011345 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:06pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595450.8 | 512928.3 | 70269 | 1.64041666667 | 11345 |
| 010516 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:07pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595452.5 | 512929.8 | 70271 | 1.64041666667 | 10516 |
| 013609 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:08pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595455.0 | 512931.3 | 70273 | 1.64041666667 | 13609 |
| 011532 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:09pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595454.9 | 512933.8 | 70275 | 1.64041666667 | 11532 |
| 013743 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:10pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595455.6 | 512936.8 | 70277 | 1.64041666667 | 13743 |
| 013155 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:11pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595454.7 | 512938.2 | 70279 | 1.64041666667 | 13155 |
| 012318 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:12pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595454.5 | 512938.6 | 70281 | 1.64041666667 | 12318 |
| 012889 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:13pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595455.0 | 512939.0 | 70283 | 1.64041666667 | 12889 |
| 013272 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:14pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595455.5 | 512940.6 | 70285 | 1.64041666667 | 13272 |
| 013428 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:15pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595455.6 | 512943.5 | 70287 | 1.64041666667 | 13428 |
| 013317 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:16pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595455.3 | 512945.8 | 70289 | 1.64041666667 | 13317 |
| 011939 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:17pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595455.0 | 512948.4 | 70291 | 1.64041666667 | 11939 |
| 010875 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:19pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595454.0 | 512950.4 | 70294 | 1.64041666667 | 10875 |
| 013308 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595454.3 | 512950.1 | 70295 | 1.64041666667 | 13308 |
| 011337 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:20pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595455.9 | 512947.9 | 70297 | 1.64041666667 | 11337 |
| 011024 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:21pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595455.7 | 512946.0 | 70299 | 1.64041666667 | 11024 |
| 011036 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:22pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595456.0 | 512943.9 | 70301 | 1.64041666667 | 11036 |
| 012749 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:23pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595455.5 | 512941.7 | 70303 | 1.64041666667 | 12749 |
| 012277 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:24pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595454.1 | 512939.4 | 70305 | 1.64041666667 | 12277 |
| 013839 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:25pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595451.8 | 512937.8 | 70307 | 1.64041666667 | 13839 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016149 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:26pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595448.9 | 512937.6 | 70309 | 1.64041666667 | 16149 |
| 016067 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:27pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595446.6 | 512936.8 | 70311 | 1.64041666667 | 16067 |
| 015416 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595443.9 | 512936.0 | 70314 | 1.64041666667 | 15416 |
| 016244 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595442.0 | 512935.2 | 70315 | 1.64041666667 | 16244 |
| 013421 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:30pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595439.3 | 512933.4 | 70317 | 1.64041666667 | 13421 |
| 012685 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:31pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595437.0 | 512933.2 | 70319 | 1.64041666667 | 12685 |
| 011721 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:33pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595435.0 | 512931.6 | 70322 | 1.64041666667 | 11721 |
| 012140 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:33pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595432.9 | 512930.9 | 70323 | 1.64041666667 | 12140 |
| 011885 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:34pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595430.3 | 512929.0 | 70325 | 1.64041666667 | 11885 |
| 012811 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:35pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595427.7 | 512927.2 | 70327 | 1.64041666667 | 12811 |
| 012082 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:37pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595424.7 | 512926.4 | 70330 | 1.64041666667 | 12082 |
| 012800 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:37pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595422.5 | 512924.9 | 70331 | 1.64041666667 | 12800 |
| 012380 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:39pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595419.5 | 512923.9 | 70334 | 1.64041666667 | 12380 |
| 011105 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:39pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595417.1 | 512922.9 | 70335 | 1.64041666667 | 11105 |
| 012226 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:40pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595413.6 | 512921.6 | 70337 | 1.64041666667 | 12226 |
| 012656 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:41pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595410.8 | 512921.3 | 70339 | 1.64041666667 | 12656 |
| 011144 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:43pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595407.9 | 512919.8 | 70342 | 1.64041666667 | 11144 |
| 012446 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:43pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595405.3 | 512918.8 | 70343 | 1.64041666667 | 12446 |
| 011061 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:44pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595402.4 | 512917.9 | 70345 | 1.64041666667 | 11061 |
| 011285 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595399.6 | 512917.0 | 70347 | 1.64041666667 | 11285 |
| 010891 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:46pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595396.3 | 512916.4 | 70349 | 1.64041666667 | 10891 |
| 011902 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:47pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595393.8 | 512915.3 | 70351 | 1.64041666667 | 11902 |
| 012005 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:48pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595390.6 | 512913.5 | 70353 | 1.64041666667 | 12005 |
| 010081 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:49pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595388.1 | 512912.4 | 70355 | 1.64041666667 | 10081 |
| 011670 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:50pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595385.5 | 512910.6 | 70357 | 1.64041666667 | 11670 |
| 012397 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:51pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595382.8 | 512909.4 | 70359 | 1.64041666667 | 12397 |
| 011229 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:52pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595379.6 | 512908.3 | 70361 | 1.64041666667 | 11229 |
| 012437 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:53pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595377.6 | 512907.2 | 70363 | 1.64041666667 | 12437 |
| 013549 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:54pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595374.6 | 512906.4 | 70365 | 1.64041666667 | 13549 |
| 012687 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:55pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595372.5 | 512905.3 | 70367 | 1.64041666667 | 12687 |
| 012952 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:56pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595370.1 | 512904.5 | 70369 | 1.64041666667 | 12952 |
| 012838 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:57pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595367.9 | 512903.3 | 70371 | 1.64041666667 | 12838 |
| 012869 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:58pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595365.3 | 512901.3 | 70373 | 1.64041666667 | 12869 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 05:24:59pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595362.6 | 512900.5 | 70375 | 1.64041666667 | 12247 |
| 011251 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595359.9 | 512899.1 | 70378 | 1.64041666667 | 11251 |
| 011242 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595357.9 | 512899.4 | 70379 | 1.64041666667 | 11242 |
| 012200 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:02pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595355.0 | 512898.7 | 70381 | 1.64041666667 | 12200 |
| 011630 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:03pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595355.9 | 512899.0 | 70383 | 1.64041666667 | 11630 |
| 012567 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:04pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595354.1 | 512900.1 | 70385 | 1.64041666667 | 12567 |
| 013102 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:05pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595352.4 | 512899.2 | 70387 | 1.64041666667 | 13102 |
| 011135 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:06pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595349.7 | 512901.0 | 70389 | 1.64041666667 | 11135 |
| 011723 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:07pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595348.0 | 512901.7 | 70391 | 1.64041666667 | 11723 |
| 011091 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:08pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595347.3 | 512902.1 | 70393 | 1.64041666667 | 11091 |
| 011592 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:09pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595347.1 | 512904.3 | 70395 | 1.64041666667 | 11592 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:10pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595346.1 | 512906.8 | 70397 | 1.64041666667 | 12678 |
| 012919 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:11pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595346.1 | 512909.8 | 70399 | 1.64041666667 | 12919 |
| 010819 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:12pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595345.1 | 512913.9 | 70401 | 1.64041666667 | 10819 |
| 012515 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:13pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595344.8 | 512914.5 | 70403 | 1.64041666667 | 12515 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014168 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:15pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595344.6 | 512914.8 | 70406 | 1.64041666667 | 14168 |
| 013862 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:15pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595346.1 | 512912.7 | 70407 | 1.64041666667 | 13862 |
| 013545 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:16pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595345.3 | 512911.4 | 70409 | 1.64041666667 | 13545 |
| 013826 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:17pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595346.0 | 512909.7 | 70411 | 1.64041666667 | 13826 |
| 013926 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:18pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595346.9 | 512907.0 | 70413 | 1.64041666667 | 13926 |
| 013561 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595349.0 | 512906.1 | 70415 | 1.64041666667 | 13561 |
| 012990 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595352.1 | 512905.7 | 70417 | 1.64041666667 | 12990 |
| 012757 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595353.8 | 512906.1 | 70419 | 1.64041666667 | 12757 |
| 012759 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:22pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595355.7 | 512907.5 | 70421 | 1.64041666667 | 12759 |
| 013840 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:23pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595357.7 | 512907.2 | 70423 | 1.64041666667 | 13840 |
| 013180 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595359.6 | 512907.5 | 70425 | 1.64041666667 | 13180 |
| 012205 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:25pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595362.2 | 512907.1 | 70427 | 1.64041666667 | 12205 |
| 012771 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:26pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595365.9 | 512907.2 | 70429 | 1.64041666667 | 12771 |
| 011832 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:27pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595367.8 | 512908.3 | 70431 | 1.64041666667 | 11832 |
| 012888 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:28pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595370.2 | 512909.7 | 70433 | 1.64041666667 | 12888 |
| 011082 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:29pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595370.5 | 512910.6 | 70435 | 1.64041666667 | 11082 |
| 011260 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:30pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595370.5 | 512910.8 | 70437 | 1.64041666667 | 11260 |
| 012025 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:31pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595370.7 | 512910.9 | 70439 | 1.64041666667 | 12025 |
| 011646 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:32pm | Sensor | 1797-S0048-G-TJV.cor | 6834.2 | 1595371.5 | 512911.2 | 70441 | 1.64041666667 | 11646 |
| 012601 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:33pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595373.6 | 512911.4 | 70443 | 1.64041666667 | 12601 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:34pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595376.5 | 512911.6 | 70445 | 1.64041666667 | 12960 |
| 012540 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:35pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595378.2 | 512912.4 | 70447 | 1.64041666667 | 12540 |
| 012465 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:36pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595381.2 | 512912.2 | 70449 | 1.64041666667 | 12465 |
| 011276 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:37pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595383.1 | 512913.3 | 70451 | 1.64041666667 | 11276 |
| 012839 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:38pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595386.1 | 512914.2 | 70453 | 1.64041666667 | 12839 |
| 011970 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:39pm | Sensor | 1797-S0048-G-TJV.cor | 6834.3 | 1595388.8 | 512915.7 | 70455 | 1.64041666667 | 11970 |
| 011902 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:40pm | Sensor | 1797-S0048-G-TJV.cor | 6834.4 | 1595391.6 | 512917.6 | 70457 | 1.64041666667 | 11902 |
| 011195 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:41pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595393.8 | 512918.2 | 70459 | 1.64041666667 | 11195 |
| 012068 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:42pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595395.9 | 512919.3 | 70461 | 1.64041666667 | 12068 |
| 012347 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:43pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595398.2 | 512919.6 | 70463 | 1.64041666667 | 12347 |
| 011936 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595399.9 | 512921.5 | 70466 | 1.64041666667 | 11936 |
| 010604 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595401.4 | 512923.3 | 70467 | 1.64041666667 | 10604 |
| 010301 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:46pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595403.7 | 512925.1 | 70469 | 1.64041666667 | 10301 |
| 010310 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:47pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595405.7 | 512927.1 | 70471 | 1.64041666667 | 10310 |
| 010783 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:48pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595407.5 | 512928.1 | 70473 | 1.64041666667 | 10783 |
| 011516 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:49pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595407.2 | 512928.2 | 70475 | 1.64041666667 | 11516 |
| 013709 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:50pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595407.0 | 512928.1 | 70477 | 1.64041666667 | 13709 |
| 011197 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:51pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595406.6 | 512928.3 | 70479 | 1.64041666667 | 11197 |
| 011409 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:52pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595405.8 | 512927.1 | 70481 | 1.64041666667 | 11409 |
| 011762 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:53pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595404.0 | 512925.7 | 70483 | 1.64041666667 | 11762 |
| 011220 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:55pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595402.3 | 512924.0 | 70486 | 1.64041666667 | 11220 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:55pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595400.5 | 512922.9 | 70487 | 1.64041666667 | 12255 |
| 010893 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:57pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595398.7 | 512920.7 | 70490 | 1.64041666667 | 10893 |
| 012773 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:57pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595396.8 | 512918.8 | 70491 | 1.64041666667 | 12773 |
| 011083 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:58pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595395.1 | 512917.2 | 70493 | 1.64041666667 | 11083 |
| 011531 | 0 | GeoXH 6000 | 08/19/2015 | 05:25:59pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595395.3 | 512916.7 | 70495 | 1.64041666667 | 11531 |
| 010472 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:00pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595395.6 | 512916.7 | 70497 | 1.64041666667 | 10472 |
| 012038 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:01pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595395.4 | 512916.7 | 70499 | 1.64041666667 | 12038 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011739 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:03pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595395.5 | 512916.7 | 70502 | 1.64041666667 | 11739 |
| 009835 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:03pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595395.4 | 512916.7 | 70503 | 1.64041666667 | 9835 |
| 010708 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:04pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595395.5 | 512916.7 | 70505 | 1.64041666667 | 10708 |
| 010927 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:05pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595395.4 | 512916.6 | 70507 | 1.64041666667 | 10927 |
| 011881 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:06pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595395.2 | 512916.6 | 70509 | 1.64041666667 | 11881 |
| 011070 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:07pm | Sensor | 1797-S0048-G-TJV.cor | 6834.1 | 1595393.8 | 512917.2 | 70511 | 1.64041666667 | 11070 |
| 011197 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:08pm | Sensor | 1797-S0048-G-TJV.cor | 6833.1 | 1595392.8 | 512917.3 | 70513 | 1.64041666667 | 11197 |
| 012279 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:09pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595394.3 | 512916.9 | 70515 | 1.64041666667 | 12279 |
| 010300 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:10pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595395.6 | 512916.3 | 70517 | 1.64041666667 | 10300 |
| 011185 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:11pm | Sensor | 1797-S0048-G-TJV.cor | 6834.5 | 1595396.6 | 512916.8 | 70519 | 1.64041666667 | 11185 |
| 012036 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:12pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595398.2 | 512918.8 | 70521 | 1.64041666667 | 12036 |
| 013089 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:13pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595398.4 | 512921.0 | 70523 | 1.64041666667 | 13089 |
| 012332 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:14pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595400.4 | 512923.1 | 70525 | 1.64041666667 | 12332 |
| 011453 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:15pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595402.1 | 512925.4 | 70527 | 1.64041666667 | 11453 |
| 013423 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:16pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595404.5 | 512927.8 | 70529 | 1.64041666667 | 13423 |
| 012236 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:17pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595406.8 | 512928.9 | 70531 | 1.64041666667 | 12236 |
| 011519 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:18pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595409.1 | 512930.6 | 70533 | 1.64041666667 | 11519 |
| 010469 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595411.5 | 512930.9 | 70535 | 1.64041666667 | 10469 |
| 011317 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595414.0 | 512932.0 | 70537 | 1.64041666667 | 11317 |
| 011319 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595416.4 | 512933.7 | 70539 | 1.64041666667 | 11319 |
| 011079 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:22pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595419.6 | 512934.9 | 70541 | 1.64041666667 | 11079 |
| 011080 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595421.9 | 512936.3 | 70543 | 1.64041666667 | 11080 |
| 011170 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595425.3 | 512936.9 | 70545 | 1.64041666667 | 11170 |
| 011342 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595428.1 | 512937.7 | 70547 | 1.64041666667 | 11342 |
| 011565 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:26pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595430.9 | 512939.5 | 70549 | 1.64041666667 | 11565 |
| 013781 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:27pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595433.5 | 512940.4 | 70551 | 1.64041666667 | 13781 |
| 013315 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:28pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595436.5 | 512941.8 | 70553 | 1.64041666667 | 13315 |
| 015479 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595438.9 | 512943.2 | 70555 | 1.64041666667 | 15479 |
| 013259 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:30pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595442.2 | 512944.0 | 70557 | 1.64041666667 | 13259 |
| 012465 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:31pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595444.8 | 512945.2 | 70559 | 1.64041666667 | 12465 |
| 012746 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:32pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595447.9 | 512946.5 | 70561 | 1.64041666667 | 12746 |
| 011676 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:33pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595450.5 | 512947.7 | 70563 | 1.64041666667 | 11676 |
| 011259 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:34pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595452.3 | 512949.5 | 70565 | 1.64041666667 | 11259 |
| 012924 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:35pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595454.7 | 512950.5 | 70567 | 1.64041666667 | 12924 |
| 012651 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:36pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595454.5 | 512951.1 | 70569 | 1.64041666667 | 12651 |
| 014532 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:37pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595453.8 | 512953.2 | 70571 | 1.64041666667 | 14532 |
| 011883 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:38pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595453.5 | 512956.0 | 70573 | 1.64041666667 | 11883 |
| 012660 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:39pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595452.8 | 512956.9 | 70575 | 1.64041666667 | 12660 |
| 011655 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:40pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595452.3 | 512957.0 | 70577 | 1.64041666667 | 11655 |
| 012067 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:41pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595452.6 | 512957.1 | 70579 | 1.64041666667 | 12067 |
| 013268 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:42pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595453.6 | 512959.3 | 70581 | 1.64041666667 | 13268 |
| 011297 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:43pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595452.9 | 512961.6 | 70583 | 1.64041666667 | 11297 |
| 011524 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:44pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595451.8 | 512965.2 | 70585 | 1.64041666667 | 11524 |
| 011401 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595451.5 | 512966.1 | 70587 | 1.64041666667 | 11401 |
| 011820 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:46pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595451.6 | 512965.9 | 70589 | 1.64041666667 | 11820 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:47pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595453.6 | 512964.2 | 70591 | 1.64041666667 | 12405 |
| 011411 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:48pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595452.9 | 512962.2 | 70593 | 1.64041666667 | 11411 |
| 013143 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:49pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595452.2 | 512959.9 | 70595 | 1.64041666667 | 13143 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012225 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:50pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595449.4 | 512957.9 | 70597 | 1.64041666667 | 12225 |
| 012656 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:51pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595446.6 | 512956.9 | 70599 | 1.64041666667 | 12656 |
| 012884 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:52pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595444.1 | 512955.3 | 70601 | 1.64041666667 | 12884 |
| 014801 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:53pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595441.2 | 512954.8 | 70603 | 1.64041666667 | 14801 |
| 014230 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:54pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595438.4 | 512954.0 | 70605 | 1.64041666667 | 14230 |
| 013877 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:55pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595435.8 | 512952.7 | 70607 | 1.64041666667 | 13877 |
| 012379 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:56pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595432.6 | 512951.7 | 70609 | 1.64041666667 | 12379 |
| 013114 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:57pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595430.5 | 512950.0 | 70611 | 1.64041666667 | 13114 |
| 013598 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:58pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595427.6 | 512949.4 | 70613 | 1.64041666667 | 13598 |
| 013989 | 0 | GeoXH 6000 | 08/19/2015 | 05:26:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595425.1 | 512948.3 | 70615 | 1.64041666667 | 13989 |
| 013937 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:00pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595422.2 | 512948.0 | 70617 | 1.64041666667 | 13937 |
| 012814 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:01pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595420.0 | 512947.5 | 70619 | 1.64041666667 | 12814 |
| 013223 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:02pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595416.5 | 512945.9 | 70621 | 1.64041666667 | 13223 |
| 013056 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:03pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595414.4 | 512945.4 | 70623 | 1.64041666667 | 13056 |
| 011454 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:04pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595412.4 | 512944.0 | 70625 | 1.64041666667 | 11454 |
| 012313 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:05pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595410.1 | 512943.6 | 70627 | 1.64041666667 | 12313 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:06pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595407.7 | 512942.3 | 70629 | 1.64041666667 | 12768 |
| 011562 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:07pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595405.0 | 512942.3 | 70631 | 1.64041666667 | 11562 |
| 011440 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:08pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595401.8 | 512941.7 | 70633 | 1.64041666667 | 11440 |
| 012160 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:09pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595399.0 | 512941.6 | 70635 | 1.64041666667 | 12160 |
| 012010 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:10pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595395.5 | 512942.1 | 70637 | 1.64041666667 | 12010 |
| 010982 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:11pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595393.0 | 512941.2 | 70639 | 1.64041666667 | 10982 |
| 012615 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:12pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595389.4 | 512939.9 | 70641 | 1.64041666667 | 12615 |
| 013143 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:13pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595386.9 | 512938.8 | 70643 | 1.64041666667 | 13143 |
| 012916 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:14pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595384.3 | 512936.6 | 70645 | 1.64041666667 | 12916 |
| 012769 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:15pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595382.0 | 512935.2 | 70647 | 1.64041666667 | 12769 |
| 011982 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:16pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595379.2 | 512933.3 | 70649 | 1.64041666667 | 11982 |
| 011995 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:17pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595376.5 | 512931.3 | 70651 | 1.64041666667 | 11995 |
| 011309 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:18pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595373.7 | 512929.6 | 70653 | 1.64041666667 | 11309 |
| 011827 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:19pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595371.8 | 512927.9 | 70655 | 1.64041666667 | 11827 |
| 013336 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595369.1 | 512926.8 | 70657 | 1.64041666667 | 13336 |
| 012064 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595366.7 | 512925.8 | 70659 | 1.64041666667 | 12064 |
| 012466 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:22pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595364.1 | 512924.5 | 70661 | 1.64041666667 | 12466 |
| 012026 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595361.1 | 512923.7 | 70663 | 1.64041666667 | 12026 |
| 012216 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595358.7 | 512921.8 | 70665 | 1.64041666667 | 12216 |
| 011814 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595356.2 | 512920.5 | 70667 | 1.64041666667 | 11814 |
| 012733 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:26pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595353.2 | 512919.1 | 70669 | 1.64041666667 | 12733 |
| 011823 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:27pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595350.9 | 512917.7 | 70671 | 1.64041666667 | 11823 |
| 012345 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:28pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595348.0 | 512916.7 | 70673 | 1.64041666667 | 12345 |
| 010346 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595346.8 | 512915.3 | 70675 | 1.64041666667 | 10346 |
| 011286 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:30pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595345.2 | 512914.3 | 70677 | 1.64041666667 | 11286 |
| 012151 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:31pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595345.2 | 512913.5 | 70679 | 1.64041666667 | 12151 |
| 012337 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:32pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595344.9 | 512915.0 | 70681 | 1.64041666667 | 12337 |
| 013014 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:33pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595343.7 | 512916.4 | 70683 | 1.64041666667 | 13014 |
| 012433 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:34pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595343.3 | 512918.6 | 70685 | 1.64041666667 | 12433 |
| 012618 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:35pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595343.0 | 512920.6 | 70687 | 1.64041666667 | 12618 |
| 013564 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:36pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595342.9 | 512922.7 | 70689 | 1.64041666667 | 13564 |
| 011761 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:37pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595342.2 | 512923.8 | 70691 | 1.64041666667 | 11761 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011100 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:38pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595341.6 | 512926.4 | 70693 | 1.64041666667 | 11100 |
| 011985 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:39pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595340.5 | 512929.0 | 70695 | 1.64041666667 | 11985 |
| 012386 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:40pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595339.6 | 512931.1 | 70697 | 1.64041666667 | 12386 |
| 014946 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:41pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595340.5 | 512930.0 | 70699 | 1.64041666667 | 14946 |
| 014056 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:42pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595339.7 | 512927.8 | 70701 | 1.64041666667 | 14056 |
| 011254 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:43pm | Sensor | 1797-S0048-G-TJV.cor | 6834.8 | 1595340.3 | 512925.9 | 70703 | 1.64041666667 | 11254 |
| 011873 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:44pm | Sensor | 1797-S0048-G-TJV.cor | 6834.7 | 1595341.9 | 512924.3 | 70705 | 1.64041666667 | 11873 |
| 011638 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:45pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595344.2 | 512923.7 | 70707 | 1.64041666667 | 11638 |
| 011849 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:46pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595346.6 | 512924.4 | 70709 | 1.64041666667 | 11849 |
| 012202 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:47pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595349.1 | 512925.1 | 70711 | 1.64041666667 | 12202 |
| 011960 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:48pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595351.5 | 512926.0 | 70713 | 1.64041666667 | 11960 |
| 013400 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:49pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595354.2 | 512926.9 | 70715 | 1.64041666667 | 13400 |
| 013250 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:50pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595357.2 | 512927.4 | 70717 | 1.64041666667 | 13250 |
| 011982 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:51pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595359.0 | 512928.4 | 70719 | 1.64041666667 | 11982 |
| 012835 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:52pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595361.7 | 512928.9 | 70721 | 1.64041666667 | 12835 |
| 013619 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:53pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595364.3 | 512930.0 | 70723 | 1.64041666667 | 13619 |
| 012614 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:54pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595367.7 | 512931.5 | 70725 | 1.64041666667 | 12614 |
| 012843 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:55pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595370.8 | 512932.0 | 70727 | 1.64041666667 | 12843 |
| 012150 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:56pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595373.2 | 512933.2 | 70729 | 1.64041666667 | 12150 |
| 012607 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:57pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595376.2 | 512933.8 | 70731 | 1.64041666667 | 12607 |
| 012182 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:58pm | Sensor | 1797-S0048-G-TJV.cor | 6834.9 | 1595379.3 | 512934.9 | 70733 | 1.64041666667 | 12182 |
| 011895 | 0 | GeoXH 6000 | 08/19/2015 | 05:27:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595381.9 | 512936.4 | 70735 | 1.64041666667 | 11895 |
| 013083 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:00pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595385.0 | 512937.5 | 70737 | 1.64041666667 | 13083 |
| 011521 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:01pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595386.8 | 512939.2 | 70739 | 1.64041666667 | 11521 |
| 012780 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:02pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595388.9 | 512940.9 | 70741 | 1.64041666667 | 12780 |
| 012225 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:03pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595391.6 | 512942.6 | 70743 | 1.64041666667 | 12225 |
| 012926 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:04pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595394.2 | 512944.8 | 70745 | 1.64041666667 | 12926 |
| 012501 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:05pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595396.3 | 512945.7 | 70747 | 1.64041666667 | 12501 |
| 011675 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:06pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595398.8 | 512947.2 | 70749 | 1.64041666667 | 11675 |
| 012248 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:07pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595401.2 | 512948.4 | 70751 | 1.64041666667 | 12248 |
| 011252 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:08pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595403.9 | 512949.4 | 70753 | 1.64041666667 | 11252 |
| 013373 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:09pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595406.2 | 512950.3 | 70755 | 1.64041666667 | 13373 |
| 012793 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:10pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595408.9 | 512950.7 | 70757 | 1.64041666667 | 12793 |
| 012648 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:11pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595411.8 | 512950.9 | 70759 | 1.64041666667 | 12648 |
| 011832 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:12pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595414.7 | 512950.3 | 70761 | 1.64041666667 | 11832 |
| 013098 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:13pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595415.9 | 512951.2 | 70763 | 1.64041666667 | 13098 |
| 012694 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:14pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595418.4 | 512952.1 | 70765 | 1.64041666667 | 12694 |
| 012833 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:15pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595420.1 | 512953.6 | 70767 | 1.64041666667 | 12833 |
| 013678 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:16pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595422.5 | 512954.7 | 70769 | 1.64041666667 | 13678 |
| 013379 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:17pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595424.3 | 512956.0 | 70771 | 1.64041666667 | 13379 |
| 013545 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:18pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595427.3 | 512956.9 | 70773 | 1.64041666667 | 13545 |
| 011726 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595429.5 | 512957.7 | 70775 | 1.64041666667 | 11726 |
| 011571 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595432.7 | 512958.5 | 70777 | 1.64041666667 | 11571 |
| 013242 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595435.3 | 512959.2 | 70779 | 1.64041666667 | 13242 |
| 011230 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:22pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595438.6 | 512960.9 | 70781 | 1.64041666667 | 11230 |
| 011387 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595441.6 | 512961.6 | 70783 | 1.64041666667 | 11387 |
| 011576 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595444.7 | 512962.9 | 70785 | 1.64041666667 | 11576 |
| 011834 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595447.4 | 512964.3 | 70787 | 1.64041666667 | 11834 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011298 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:26pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595451.0 | 512966.0 | 70789 | 1.64041666667 | 11298 |
| 010834 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:27pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595451.0 | 512966.6 | 70791 | 1.64041666667 | 10834 |
| 010808 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:28pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595449.1 | 512967.7 | 70793 | 1.64041666667 | 10808 |
| 012332 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:29pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595447.7 | 512969.8 | 70795 | 1.64041666667 | 12332 |
| 010103 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:30pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595447.9 | 512972.2 | 70797 | 1.64041666667 | 10103 |
| 010415 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:31pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595447.4 | 512973.3 | 70799 | 1.64041666667 | 10415 |
| 011064 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:32pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595446.3 | 512976.1 | 70801 | 1.64041666667 | 11064 |
| 011766 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:33pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595445.5 | 512978.1 | 70803 | 1.64041666667 | 11766 |
| 011221 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:34pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595444.6 | 512981.6 | 70805 | 1.64041666667 | 11221 |
| 012195 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:35pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595445.0 | 512980.5 | 70807 | 1.64041666667 | 12195 |
| 011928 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:36pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595445.8 | 512979.8 | 70809 | 1.64041666667 | 11928 |
| 012372 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:37pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595446.0 | 512980.0 | 70811 | 1.64041666667 | 12372 |
| 013023 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:38pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595446.0 | 512979.7 | 70813 | 1.64041666667 | 13023 |
| 012225 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:39pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595445.8 | 512977.7 | 70815 | 1.64041666667 | 12225 |
| 012596 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:40pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595446.9 | 512974.7 | 70817 | 1.64041666667 | 12596 |
| 010259 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:41pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595445.7 | 512972.7 | 70819 | 1.64041666667 | 10259 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:42pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595444.0 | 512970.6 | 70821 | 1.64041666667 | 12405 |
| 011441 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:43pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595442.1 | 512968.5 | 70823 | 1.64041666667 | 11441 |
| 011770 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:44pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595439.2 | 512967.3 | 70825 | 1.64041666667 | 11770 |
| 010742 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:45pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595436.9 | 512965.9 | 70827 | 1.64041666667 | 10742 |
| 012615 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:46pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595433.7 | 512965.0 | 70829 | 1.64041666667 | 12615 |
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:47pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595431.0 | 512964.0 | 70831 | 1.64041666667 | 12183 |
| 012286 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:48pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595427.9 | 512962.3 | 70833 | 1.64041666667 | 12286 |
| 013091 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:49pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595425.2 | 512962.3 | 70835 | 1.64041666667 | 13091 |
| 012543 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:50pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595422.3 | 512962.4 | 70837 | 1.64041666667 | 12543 |
| 012195 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:51pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595419.8 | 512962.7 | 70839 | 1.64041666667 | 12195 |
| 011778 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:52pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595416.4 | 512962.7 | 70841 | 1.64041666667 | 11778 |
| 011974 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:53pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595414.2 | 512962.0 | 70843 | 1.64041666667 | 11974 |
| 014303 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:54pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595411.8 | 512961.3 | 70845 | 1.64041666667 | 14303 |
| 013626 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:55pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595409.7 | 512959.8 | 70847 | 1.64041666667 | 13626 |
| 013666 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:56pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595406.9 | 512958.5 | 70849 | 1.64041666667 | 13666 |
| 013706 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:57pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595404.5 | 512956.8 | 70851 | 1.64041666667 | 13706 |
| 013956 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:58pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595401.5 | 512955.4 | 70853 | 1.64041666667 | 13956 |
| 012429 | 0 | GeoXH 6000 | 08/19/2015 | 05:28:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595398.7 | 512954.1 | 70855 | 1.64041666667 | 12429 |
| 012617 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:00pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595395.5 | 512952.3 | 70857 | 1.64041666667 | 12617 |
| 012064 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:01pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595392.8 | 512951.4 | 70859 | 1.64041666667 | 12064 |
| 012646 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:02pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595390.0 | 512949.7 | 70861 | 1.64041666667 | 12646 |
| 012311 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:03pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595387.5 | 512948.5 | 70863 | 1.64041666667 | 12311 |
| 013758 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:04pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595384.4 | 512946.8 | 70865 | 1.64041666667 | 13758 |
| 014019 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:05pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595382.1 | 512945.5 | 70867 | 1.64041666667 | 14019 |
| 012402 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:06pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595379.0 | 512944.8 | 70869 | 1.64041666667 | 12402 |
| 011860 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:07pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595377.3 | 512943.4 | 70871 | 1.64041666667 | 11860 |
| 011305 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:08pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595374.4 | 512942.2 | 70873 | 1.64041666667 | 11305 |
| 011796 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:09pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595372.0 | 512940.8 | 70875 | 1.64041666667 | 11796 |
| 011799 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:10pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595368.6 | 512939.0 | 70877 | 1.64041666667 | 11799 |
| 011499 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:11pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595365.5 | 512939.0 | 70879 | 1.64041666667 | 11499 |
| 014545 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:12pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595363.2 | 512938.4 | 70881 | 1.64041666667 | 14545 |
| 014856 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:13pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595360.9 | 512939.1 | 70883 | 1.64041666667 | 14856 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013284 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:14pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595358.3 | 512938.6 | 70885 | 1.64041666667 | 13284 |
| 013581 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:15pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595355.3 | 512937.4 | 70887 | 1.64041666667 | 13581 |
| 013805 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:16pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595352.7 | 512936.4 | 70889 | 1.64041666667 | 13805 |
| 014401 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:17pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595350.6 | 512934.7 | 70891 | 1.64041666667 | 14401 |
| 012300 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:18pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595347.7 | 512933.6 | 70893 | 1.64041666667 | 12300 |
| 011925 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595344.8 | 512932.5 | 70895 | 1.64041666667 | 11925 |
| 012161 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595340.6 | 512932.1 | 70897 | 1.64041666667 | 12161 |
| 013450 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595339.0 | 512932.8 | 70899 | 1.64041666667 | 13450 |
| 012782 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:22pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595338.1 | 512934.4 | 70901 | 1.64041666667 | 12782 |
| 011385 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595337.9 | 512937.4 | 70903 | 1.64041666667 | 11385 |
| 010556 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595338.7 | 512939.8 | 70905 | 1.64041666667 | 10556 |
| 012179 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595338.0 | 512941.2 | 70907 | 1.64041666667 | 12179 |
| 011715 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:26pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595337.2 | 512943.6 | 70909 | 1.64041666667 | 11715 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:27pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595335.4 | 512946.0 | 70911 | 1.64041666667 | 12678 |
| 012649 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:28pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595333.7 | 512949.8 | 70913 | 1.64041666667 | 12649 |
| 012522 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595334.5 | 512948.6 | 70915 | 1.64041666667 | 12522 |
| 013060 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:30pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595334.2 | 512947.0 | 70917 | 1.64041666667 | 13060 |
| 014365 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:31pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595335.2 | 512945.0 | 70919 | 1.64041666667 | 14365 |
| 013311 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:32pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595336.9 | 512942.8 | 70921 | 1.64041666667 | 13311 |
| 012297 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:33pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595339.4 | 512941.8 | 70923 | 1.64041666667 | 12297 |
| 014174 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:34pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595342.8 | 512942.1 | 70925 | 1.64041666667 | 14174 |
| 012783 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:35pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595345.5 | 512942.2 | 70927 | 1.64041666667 | 12783 |
| 012765 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:36pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595347.8 | 512944.0 | 70929 | 1.64041666667 | 12765 |
| 011471 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:37pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595350.3 | 512945.9 | 70931 | 1.64041666667 | 11471 |
| 011718 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:38pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595353.6 | 512947.2 | 70933 | 1.64041666667 | 11718 |
| 010669 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:39pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595356.0 | 512948.7 | 70935 | 1.64041666667 | 10669 |
| 011427 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:40pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595359.0 | 512949.8 | 70937 | 1.64041666667 | 11427 |
| 011497 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:41pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595361.8 | 512950.4 | 70939 | 1.64041666667 | 11497 |
| 011244 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:42pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595364.8 | 512951.8 | 70941 | 1.64041666667 | 11244 |
| 011511 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:43pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595367.6 | 512952.7 | 70943 | 1.64041666667 | 11511 |
| 013587 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:44pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595370.3 | 512954.3 | 70945 | 1.64041666667 | 13587 |
| 012337 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:45pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595372.9 | 512954.9 | 70947 | 1.64041666667 | 12337 |
| 011934 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:46pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595376.4 | 512955.4 | 70949 | 1.64041666667 | 11934 |
| 013093 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:47pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595378.9 | 512956.6 | 70951 | 1.64041666667 | 13093 |
| 011973 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:48pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595381.9 | 512957.4 | 70953 | 1.64041666667 | 11973 |
| 014393 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:49pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595384.1 | 512959.0 | 70955 | 1.64041666667 | 14393 |
| 011878 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:50pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595386.6 | 512961.0 | 70957 | 1.64041666667 | 11878 |
| 012179 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:51pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595389.2 | 512962.7 | 70959 | 1.64041666667 | 12179 |
| 012675 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:52pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595391.5 | 512964.8 | 70961 | 1.64041666667 | 12675 |
| 011988 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:53pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595394.1 | 512966.2 | 70963 | 1.64041666667 | 11988 |
| 012807 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:54pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595397.3 | 512967.4 | 70965 | 1.64041666667 | 12807 |
| 013221 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:55pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595399.7 | 512968.6 | 70967 | 1.64041666667 | 13221 |
| 012575 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:56pm | Sensor | 1797-S0048-G-TJV.cor | 6835.7 | 1595402.6 | 512968.9 | 70969 | 1.64041666667 | 12575 |
| 013463 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:57pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595404.9 | 512969.8 | 70971 | 1.64041666667 | 13463 |
| 012996 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:58pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595408.1 | 512971.2 | 70973 | 1.64041666667 | 12996 |
| 012699 | 0 | GeoXH 6000 | 08/19/2015 | 05:29:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595410.7 | 512972.0 | 70975 | 1.64041666667 | 12699 |
| 011964 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:00pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595412.8 | 512972.8 | 70977 | 1.64041666667 | 11964 |
| 012081 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:01pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595414.8 | 512973.2 | 70979 | 1.64041666667 | 12081 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011120 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:02pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595416.8 | 512974.3 | 70981 | 1.64041666667 | 11120 |
| 012680 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:03pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595419.4 | 512974.8 | 70983 | 1.64041666667 | 12680 |
| 012590 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:04pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595421.2 | 512975.7 | 70985 | 1.64041666667 | 12590 |
| 011787 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:05pm | Sensor | 1797-S0048-G-TJV.cor | 6837.0 | 1595423.2 | 512976.5 | 70987 | 1.64041666667 | 11787 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:06pm | Sensor | 1797-S0048-G-TJV.cor | 6837.1 | 1595425.4 | 512977.4 | 70989 | 1.64041666667 | 12787 |
| 011926 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:07pm | Sensor | 1797-S0048-G-TJV.cor | 6837.0 | 1595427.5 | 512978.2 | 70991 | 1.64041666667 | 11926 |
| 012881 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:08pm | Sensor | 1797-S0048-G-TJV.cor | 6837.1 | 1595430.7 | 512978.6 | 70993 | 1.64041666667 | 12881 |
| 013540 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:09pm | Sensor | 1797-S0048-G-TJV.cor | 6837.0 | 1595433.0 | 512979.2 | 70995 | 1.64041666667 | 13540 |
| 011245 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:10pm | Sensor | 1797-S0048-G-TJV.cor | 6837.0 | 1595436.1 | 512979.8 | 70997 | 1.64041666667 | 11245 |
| 013521 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:11pm | Sensor | 1797-S0048-G-TJV.cor | 6836.9 | 1595438.3 | 512980.7 | 70999 | 1.64041666667 | 13521 |
| 012770 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:12pm | Sensor | 1797-S0048-G-TJV.cor | 6836.8 | 1595441.4 | 512982.0 | 71001 | 1.64041666667 | 12770 |
| 011712 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:13pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595444.4 | 512982.7 | 71003 | 1.64041666667 | 11712 |
| 012198 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:14pm | Sensor | 1797-S0048-G-TJV.cor | 6836.7 | 1595443.6 | 512982.6 | 71005 | 1.64041666667 | 12198 |
| 011689 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:15pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595442.9 | 512984.1 | 71007 | 1.64041666667 | 11689 |
| 011292 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:16pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595440.7 | 512986.1 | 71009 | 1.64041666667 | 11292 |
| 011943 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:17pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595439.2 | 512988.0 | 71011 | 1.64041666667 | 11943 |
| 010755 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:18pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595436.2 | 512988.5 | 71013 | 1.64041666667 | 10755 |
| 011598 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:19pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595434.0 | 512988.6 | 71015 | 1.64041666667 | 11598 |
| 013489 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595431.2 | 512988.7 | 71017 | 1.64041666667 | 13489 |
| 012252 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:21pm | Sensor | 1797-S0048-G-TJV.cor | 6836.1 | 1595428.5 | 512988.4 | 71019 | 1.64041666667 | 12252 |
| 013053 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:22pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595425.7 | 512989.4 | 71021 | 1.64041666667 | 13053 |
| 011633 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595423.0 | 512990.7 | 71023 | 1.64041666667 | 11633 |
| 013828 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:24pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595419.7 | 512992.5 | 71025 | 1.64041666667 | 13828 |
| 012967 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:25pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595417.5 | 512994.9 | 71027 | 1.64041666667 | 12967 |
| 014191 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:26pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595415.2 | 512997.6 | 71029 | 1.64041666667 | 14191 |
| 015517 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:27pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595414.0 | 512999.8 | 71031 | 1.64041666667 | 15517 |
| 017109 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:28pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595413.7 | 513002.9 | 71033 | 1.64041666667 | 17109 |
| 014717 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:29pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595414.0 | 513005.1 | 71035 | 1.64041666667 | 14717 |
| 015199 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:30pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595414.9 | 513007.9 | 71037 | 1.64041666667 | 15199 |
| 014479 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:31pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595415.0 | 513007.5 | 71039 | 1.64041666667 | 14479 |
| 015860 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:32pm | Sensor | 1797-S0048-G-TJV.cor | 6835.5 | 1595415.2 | 513004.8 | 71041 | 1.64041666667 | 15860 |
| 014585 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:33pm | Sensor | 1797-S0048-G-TJV.cor | 6835.4 | 1595414.8 | 513002.1 | 71043 | 1.64041666667 | 14585 |
| 015316 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:34pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595415.1 | 512998.4 | 71045 | 1.64041666667 | 15316 |
| 012859 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:35pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595416.7 | 512996.3 | 71047 | 1.64041666667 | 12859 |
| 012184 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:36pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595419.5 | 512993.7 | 71049 | 1.64041666667 | 12184 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:37pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595421.3 | 512991.2 | 71051 | 1.64041666667 | 12106 |
| 011936 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:38pm | Sensor | 1797-S0048-G-TJV.cor | 6835.8 | 1595423.2 | 512988.8 | 71053 | 1.64041666667 | 11936 |
| 010784 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:39pm | Sensor | 1797-S0048-G-TJV.cor | 6836.0 | 1595423.6 | 512986.4 | 71055 | 1.64041666667 | 10784 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:40pm | Sensor | 1797-S0048-G-TJV.cor | 6836.2 | 1595422.9 | 512984.4 | 71057 | 1.64041666667 | 12056 |
| 011504 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:41pm | Sensor | 1797-S0048-G-TJV.cor | 6836.3 | 1595422.2 | 512982.2 | 71059 | 1.64041666667 | 11504 |
| 012026 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:42pm | Sensor | 1797-S0048-G-TJV.cor | 6836.5 | 1595420.3 | 512980.8 | 71061 | 1.64041666667 | 12026 |
| 012726 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:43pm | Sensor | 1797-S0048-G-TJV.cor | 6836.6 | 1595418.4 | 512979.2 | 71063 | 1.64041666667 | 12726 |
| 011731 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:44pm | Sensor | 1797-S0048-G-TJV.cor | 6836.4 | 1595415.7 | 512977.7 | 71065 | 1.64041666667 | 11731 |
| 010882 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:45pm | Sensor | 1797-S0048-G-TJV.cor | 6835.9 | 1595412.9 | 512976.6 | 71067 | 1.64041666667 | 10882 |
| 012770 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:46pm | Sensor | 1797-S0048-G-TJV.cor | 6835.6 | 1595409.6 | 512975.4 | 71069 | 1.64041666667 | 12770 |
| 013362 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:47pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595406.6 | 512975.1 | 71071 | 1.64041666667 | 13362 |
| 011440 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:48pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595402.8 | 512974.9 | 71073 | 1.64041666667 | 11440 |
| 011830 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:49pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595399.9 | 512973.9 | 71075 | 1.64041666667 | 11830 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012227 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:50pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595397.0 | 512973.3 | 71077 | 1.64041666667 | 12227 |
| 012746 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:51pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595394.2 | 512972.2 | 71079 | 1.64041666667 | 12746 |
| 011316 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:52pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595391.1 | 512970.4 | 71081 | 1.64041666667 | 11316 |
| 012219 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:53pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595388.6 | 512969.6 | 71083 | 1.64041666667 | 12219 |
| 013014 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:54pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595385.5 | 512968.0 | 71085 | 1.64041666667 | 13014 |
| 012073 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:55pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595383.2 | 512966.8 | 71087 | 1.64041666667 | 12073 |
| 012468 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:56pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595380.2 | 512965.6 | 71089 | 1.64041666667 | 12468 |
| 012567 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:57pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595377.6 | 512963.9 | 71091 | 1.64041666667 | 12567 |
| 011631 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:58pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595374.4 | 512962.0 | 71093 | 1.64041666667 | 11631 |
| 011668 | 0 | GeoXH 6000 | 08/19/2015 | 05:30:59pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595372.1 | 512961.2 | 71095 | 1.64041666667 | 11668 |
| 012337 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:00pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595369.2 | 512959.6 | 71097 | 1.64041666667 | 12337 |
| 013014 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:01pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595366.8 | 512958.3 | 71099 | 1.64041666667 | 13014 |
| 013393 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:02pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595363.4 | 512957.2 | 71101 | 1.64041666667 | 13393 |
| 012738 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:03pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595360.6 | 512955.9 | 71103 | 1.64041666667 | 12738 |
| 013684 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:04pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595357.5 | 512955.3 | 71105 | 1.64041666667 | 13684 |
| 012691 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:05pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595354.7 | 512954.7 | 71107 | 1.64041666667 | 12691 |
| 012532 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:06pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595351.2 | 512953.4 | 71109 | 1.64041666667 | 12532 |
| 012493 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:07pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595348.2 | 512953.0 | 71111 | 1.64041666667 | 12493 |
| 012543 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:08pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595344.9 | 512952.1 | 71113 | 1.64041666667 | 12543 |
| 012765 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:09pm | Sensor | 1797-S0048-G-TJV.cor | 6835.0 | 1595342.0 | 512951.4 | 71115 | 1.64041666667 | 12765 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:10pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595338.9 | 512951.4 | 71117 | 1.64041666667 | 12461 |
| 012175 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:11pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595337.1 | 512950.8 | 71119 | 1.64041666667 | 12175 |
| 012704 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:12pm | Sensor | 1797-S0048-G-TJV.cor | 6834.6 | 1595334.9 | 512949.7 | 71121 | 1.64041666667 | 12704 |
| 012236 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:13pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595335.7 | 512950.6 | 71123 | 1.64041666667 | 12236 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:14pm | Sensor | 1797-S0048-G-TJV.cor | 6835.3 | 1595336.3 | 512951.2 | 71125 | 1.64041666667 | 12539 |
| 012164 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:15pm | Sensor | 1797-S0048-G-TJV.cor | 6835.2 | 1595336.4 | 512951.2 | 71127 | 1.64041666667 | 12164 |
| 012941 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:16pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595336.4 | 512951.2 | 71129 | 1.64041666667 | 12941 |
| 012715 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:17pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595336.3 | 512951.3 | 71131 | 1.64041666667 | 12715 |
| 012928 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:18pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595336.2 | 512951.4 | 71133 | 1.64041666667 | 12928 |
| 011662 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:19pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595336.2 | 512951.3 | 71135 | 1.64041666667 | 11662 |
| 012335 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:20pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595336.4 | 512951.3 | 71137 | 1.64041666667 | 12335 |
| 013493 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:21pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595336.4 | 512951.4 | 71139 | 1.64041666667 | 13493 |
| 012613 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:22pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595336.4 | 512951.5 | 71141 | 1.64041666667 | 12613 |
| 010443 | 0 | GeoXH 6000 | 08/19/2015 | 05:31:23pm | Sensor | 1797-S0048-G-TJV.cor | 6835.1 | 1595336.4 | 512951.5 | 71144 | 1.64041666667 | 10443 |
| 014834 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:45pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595512.1 | 511679.9 | 65603 | 1.64041666667 | 14834 |
| 014816 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:46pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595512.0 | 511679.9 | 65606 | 1.64041666667 | 14816 |
| 015189 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:47pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.7 | 511680.1 | 65608 | 1.64041666667 | 15189 |
| 015039 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:48pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.1 | 65610 | 1.64041666667 | 15039 |
| 015382 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:48pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595511.6 | 511680.2 | 65611 | 1.64041666667 | 15382 |
| 014704 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:50pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.2 | 65614 | 1.64041666667 | 14704 |
| 014616 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:50pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.6 | 511680.2 | 65615 | 1.64041666667 | 14616 |
| 014874 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:52pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.2 | 65618 | 1.64041666667 | 14874 |
| 015041 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:52pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.2 | 65619 | 1.64041666667 | 15041 |
| 015286 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:54pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.2 | 65622 | 1.64041666667 | 15286 |
| 015408 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:55pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.2 | 65624 | 1.64041666667 | 15408 |
| 014974 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:55pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.2 | 65625 | 1.64041666667 | 14974 |
| 015090 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:56pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.2 | 65627 | 1.64041666667 | 15090 |
| 01 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:58pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.5 | 511680.0 | 65630 | 1.64041666667 | 1 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014658 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:58pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595512.2 | 511679.8 | 65631 | 1.64041666667 | 14658 |
| 014275 | 0 | GeoXH 6000 | 08/19/2015 | 12:23:59pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595512.4 | 511680.0 | 65633 | 1.64041666667 | 14275 |
| 014359 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:00pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595511.5 | 511679.9 | 65635 | 1.64041666667 | 14359 |
| 013860 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:02pm | Sensor | 1797-S0046-905-G-ACK | 6830.8 | 1595513.3 | 511680.0 | 65638 | 1.64041666667 | 13860 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:02pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595513.7 | 511680.1 | 65639 | 1.64041666667 | 14463 |
| 014683 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:04pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595514.6 | 511680.1 | 65642 | 1.64041666667 | 14683 |
| 015219 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:05pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595512.0 | 511679.3 | 65644 | 1.64041666667 | 15219 |
| 015266 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:06pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595511.6 | 511678.5 | 65646 | 1.64041666667 | 15266 |
| 015719 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:07pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595511.4 | 511678.6 | 65648 | 1.64041666667 | 15719 |
| 015217 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:08pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.7 | 511678.3 | 65650 | 1.64041666667 | 15217 |
| 014582 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:09pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595511.9 | 511678.3 | 65652 | 1.64041666667 | 14582 |
| 015057 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:10pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595512.8 | 511679.1 | 65654 | 1.64041666667 | 15057 |
| 014574 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:10pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595514.0 | 511678.1 | 65655 | 1.64041666667 | 14574 |
| 014813 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:12pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595515.8 | 511676.7 | 65659 | 1.64041666667 | 14813 |
| 015307 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:12pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595516.8 | 511674.7 | 65660 | 1.64041666667 | 15307 |
| 015465 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:14pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595517.4 | 511671.9 | 65663 | 1.64041666667 | 15465 |
| 015149 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:15pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595518.4 | 511669.9 | 65665 | 1.64041666667 | 15149 |
| 014664 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:16pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595518.7 | 511667.4 | 65667 | 1.64041666667 | 14664 |
| 015253 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:16pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595519.0 | 511665.2 | 65668 | 1.64041666667 | 15253 |
| 015390 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:18pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595519.8 | 511662.0 | 65671 | 1.64041666667 | 15390 |
| 014889 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:18pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595520.1 | 511659.8 | 65672 | 1.64041666667 | 14889 |
| 015335 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:19pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595520.1 | 511658.4 | 65674 | 1.64041666667 | 15335 |
| 015233 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:20pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595519.9 | 511658.2 | 65676 | 1.64041666667 | 15233 |
| 014336 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:22pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595519.7 | 511657.8 | 65679 | 1.64041666667 | 14336 |
| 014656 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:22pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595519.6 | 511658.3 | 65680 | 1.64041666667 | 14656 |
| 015497 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:24pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595519.7 | 511658.5 | 65683 | 1.64041666667 | 15497 |
| 015159 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:24pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595519.7 | 511658.6 | 65684 | 1.64041666667 | 15159 |
| 014415 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:26pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595519.9 | 511658.3 | 65687 | 1.64041666667 | 14415 |
| 014093 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:26pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595520.4 | 511657.4 | 65688 | 1.64041666667 | 14093 |
| 014167 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:28pm | Sensor | 1797-S0046-905-G-ACK | 6829.5 | 1595521.7 | 511655.6 | 65691 | 1.64041666667 | 14167 |
| 013759 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:28pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595522.5 | 511653.8 | 65692 | 1.64041666667 | 13759 |
| 013484 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:30pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595522.6 | 511651.1 | 65695 | 1.64041666667 | 13484 |
| 013172 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:31pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595522.7 | 511648.6 | 65697 | 1.64041666667 | 13172 |
| 012494 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:32pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595521.3 | 511646.1 | 65699 | 1.64041666667 | 12494 |
| 013290 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:33pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595519.7 | 511644.3 | 65701 | 1.64041666667 | 13290 |
| 013213 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:34pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595519.0 | 511642.7 | 65703 | 1.64041666667 | 13213 |
| 013575 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:34pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595517.2 | 511641.6 | 65704 | 1.64041666667 | 13575 |
| 013726 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:36pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595515.5 | 511639.6 | 65707 | 1.64041666667 | 13726 |
| 013106 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:36pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595514.2 | 511638.6 | 65708 | 1.64041666667 | 13106 |
| 012599 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:38pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595511.9 | 511636.8 | 65711 | 1.64041666667 | 12599 |
| 012757 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:38pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595510.7 | 511634.8 | 65712 | 1.64041666667 | 12757 |
| 012643 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:40pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595509.4 | 511632.7 | 65715 | 1.64041666667 | 12643 |
| 012819 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:40pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595508.5 | 511631.6 | 65716 | 1.64041666667 | 12819 |
| 013346 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:42pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595507.7 | 511629.3 | 65719 | 1.64041666667 | 13346 |
| 013619 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:43pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595506.7 | 511628.0 | 65721 | 1.64041666667 | 13619 |
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:44pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595506.8 | 511628.9 | 65723 | 1.64041666667 | 12183 |
| 013588 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:45pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595508.2 | 511630.2 | 65725 | 1.64041666667 | 13588 |
| 013800 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:46pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595509.1 | 511633.1 | 65727 | 1.64041666667 | 13800 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014603 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:47pm | Sensor | 1797-S0046-905-G-ACK | 6830.9 | 1595512.0 | 511636.1 | 65729 | 1.64041666667 | 14603 |
| 013906 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:48pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595511.5 | 511638.8 | 65731 | 1.64041666667 | 13906 |
| 014310 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:49pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595512.8 | 511641.2 | 65733 | 1.64041666667 | 14310 |
| 012796 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:50pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595513.8 | 511644.2 | 65735 | 1.64041666667 | 12796 |
| 012935 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:50pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595514.1 | 511646.8 | 65736 | 1.64041666667 | 12935 |
| 014048 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:52pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595514.6 | 511650.5 | 65739 | 1.64041666667 | 14048 |
| 013205 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:52pm | Sensor | 1797-S0046-905-G-ACK | 6829.5 | 1595515.3 | 511653.3 | 65740 | 1.64041666667 | 13205 |
| 013082 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:54pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595515.9 | 511657.0 | 65743 | 1.64041666667 | 13082 |
| 014514 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:55pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595515.8 | 511660.5 | 65745 | 1.64041666667 | 14514 |
| 015304 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:56pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595514.7 | 511663.8 | 65747 | 1.64041666667 | 15304 |
| 015771 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:57pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595513.8 | 511666.8 | 65749 | 1.64041666667 | 15771 |
| 014383 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:58pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595513.0 | 511670.5 | 65751 | 1.64041666667 | 14383 |
| 014945 | 0 | GeoXH 6000 | 08/19/2015 | 12:24:58pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595512.8 | 511673.1 | 65752 | 1.64041666667 | 14945 |
| 015037 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:00pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595511.9 | 511677.3 | 65755 | 1.64041666667 | 15037 |
| 014286 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:01pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595511.3 | 511680.3 | 65757 | 1.64041666667 | 14286 |
| 014231 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:02pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595510.5 | 511683.9 | 65759 | 1.64041666667 | 14231 |
| 014935 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:03pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595510.3 | 511687.1 | 65761 | 1.64041666667 | 14935 |
| 014700 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:04pm | Sensor | 1797-S0046-905-G-ACK | 6830.8 | 1595510.9 | 511690.2 | 65763 | 1.64041666667 | 14700 |
| 014554 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:05pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595510.5 | 511693.3 | 65765 | 1.64041666667 | 14554 |
| 013789 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:06pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595509.7 | 511697.0 | 65767 | 1.64041666667 | 13789 |
| 013239 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:06pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595509.2 | 511699.8 | 65768 | 1.64041666667 | 13239 |
| 013702 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:08pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595509.2 | 511703.8 | 65771 | 1.64041666667 | 13702 |
| 014824 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:08pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595509.1 | 511706.5 | 65772 | 1.64041666667 | 14824 |
| 014271 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:09pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595509.1 | 511710.0 | 65774 | 1.64041666667 | 14271 |
| 014732 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:10pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595508.0 | 511712.8 | 65776 | 1.64041666667 | 14732 |
| 015682 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:12pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595505.9 | 511716.2 | 65779 | 1.64041666667 | 15682 |
| 014971 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:12pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595506.2 | 511718.8 | 65780 | 1.64041666667 | 14971 |
| 015021 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:14pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595505.5 | 511721.6 | 65783 | 1.64041666667 | 15021 |
| 015364 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:14pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595505.1 | 511724.1 | 65784 | 1.64041666667 | 15364 |
| 015130 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:16pm | Sensor | 1797-S0046-905-G-ACK | 6831.2 | 1595505.1 | 511727.9 | 65787 | 1.64041666667 | 15130 |
| 014330 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:16pm | Sensor | 1797-S0046-905-G-ACK | 6832.3 | 1595504.7 | 511729.5 | 65788 | 1.64041666667 | 14330 |
| 013963 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:18pm | Sensor | 1797-S0046-905-G-ACK | 6831.4 | 1595502.8 | 511732.2 | 65791 | 1.64041666667 | 13963 |
| 013562 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:19pm | Sensor | 1797-S0046-905-G-ACK | 6831.4 | 1595502.4 | 511734.6 | 65793 | 1.64041666667 | 13562 |
| 012818 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:20pm | Sensor | 1797-S0046-905-G-ACK | 6831.3 | 1595500.9 | 511737.9 | 65795 | 1.64041666667 | 12818 |
| 012603 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:20pm | Sensor | 1797-S0046-905-G-ACK | 6830.7 | 1595500.0 | 511740.2 | 65796 | 1.64041666667 | 12603 |
| 013119 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:22pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595498.2 | 511743.5 | 65799 | 1.64041666667 | 13119 |
| 013972 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:22pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595497.6 | 511746.2 | 65800 | 1.64041666667 | 13972 |
| 014346 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:24pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595496.8 | 511750.1 | 65803 | 1.64041666667 | 14346 |
| 014302 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:25pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595496.8 | 511753.1 | 65805 | 1.64041666667 | 14302 |
| 014292 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:26pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595497.1 | 511756.5 | 65807 | 1.64041666667 | 14292 |
| 014212 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:26pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595497.2 | 511759.1 | 65808 | 1.64041666667 | 14212 |
| 014174 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:28pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595496.6 | 511762.9 | 65811 | 1.64041666667 | 14174 |
| 014760 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:29pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595495.2 | 511765.7 | 65813 | 1.64041666667 | 14760 |
| 014385 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:30pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595495.5 | 511769.4 | 65815 | 1.64041666667 | 14385 |
| 013776 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:31pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595495.8 | 511772.4 | 65817 | 1.64041666667 | 13776 |
| 014117 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:32pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595496.1 | 511776.3 | 65819 | 1.64041666667 | 14117 |
| 014060 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:33pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595496.1 | 511779.6 | 65821 | 1.64041666667 | 14060 |
| 014434 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:34pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595496.2 | 511783.0 | 65823 | 1.64041666667 | 14434 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013946 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:34pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595496.7 | 511785.7 | 65824 | 1.64041666667 | 13946 |
| 014445 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:36pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595497.1 | 511789.2 | 65827 | 1.64041666667 | 14445 |
| 015273 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:36pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595497.4 | 511792.0 | 65828 | 1.64041666667 | 15273 |
| 015273 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:38pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595497.5 | 511796.3 | 65831 | 1.64041666667 | 15273 |
| 015446 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:38pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595497.5 | 511799.1 | 65832 | 1.64041666667 | 15446 |
| 015236 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:40pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595497.6 | 511803.0 | 65835 | 1.64041666667 | 15236 |
| 014652 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:40pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595497.8 | 511806.4 | 65836 | 1.64041666667 | 14652 |
| 014579 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:42pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595497.8 | 511810.0 | 65839 | 1.64041666667 | 14579 |
| 014351 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:42pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595498.0 | 511813.1 | 65840 | 1.64041666667 | 14351 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:44pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595499.0 | 511817.1 | 65843 | 1.64041666667 | 14132 |
| 014819 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:44pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595499.7 | 511820.2 | 65844 | 1.64041666667 | 14819 |
| 014591 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:46pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595499.6 | 511823.7 | 65847 | 1.64041666667 | 14591 |
| 014995 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:46pm | Sensor | 1797-S0046-905-G-ACK | 6830.7 | 1595499.6 | 511826.2 | 65848 | 1.64041666667 | 14995 |
| 015664 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:48pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595499.7 | 511829.9 | 65851 | 1.64041666667 | 15664 |
| 017504 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:48pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595500.1 | 511833.3 | 65852 | 1.64041666667 | 17504 |
| 016941 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:50pm | Sensor | 1797-S0046-905-G-ACK | 6830.9 | 1595501.0 | 511837.6 | 65855 | 1.64041666667 | 16941 |
| 017329 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:51pm | Sensor | 1797-S0046-905-G-ACK | 6830.8 | 1595501.7 | 511840.1 | 65857 | 1.64041666667 | 17329 |
| 017727 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:52pm | Sensor | 1797-S0046-905-G-ACK | 6830.7 | 1595502.1 | 511842.2 | 65859 | 1.64041666667 | 17727 |
| 018529 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:53pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595502.6 | 511843.8 | 65861 | 1.64041666667 | 18529 |
| 018185 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:54pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595503.2 | 511844.2 | 65863 | 1.64041666667 | 18185 |
| 017586 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:54pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595502.9 | 511843.3 | 65864 | 1.64041666667 | 17586 |
| 017362 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:56pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595503.0 | 511842.8 | 65867 | 1.64041666667 | 17362 |
| 017356 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:57pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595502.6 | 511842.5 | 65869 | 1.64041666667 | 17356 |
| 017068 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:58pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595502.0 | 511842.3 | 65871 | 1.64041666667 | 17068 |
| 016538 | 0 | GeoXH 6000 | 08/19/2015 | 12:25:59pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595502.3 | 511842.3 | 65873 | 1.64041666667 | 16538 |
| 015632 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:00pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595502.5 | 511843.1 | 65875 | 1.64041666667 | 15632 |
| 016451 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:01pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595502.5 | 511844.5 | 65877 | 1.64041666667 | 16451 |
| 018576 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:02pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595503.0 | 511846.2 | 65880 | 1.64041666667 | 18576 |
| 019816 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:02pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595502.3 | 511846.6 | 65881 | 1.64041666667 | 19816 |
| 020536 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:04pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595502.2 | 511844.6 | 65884 | 1.64041666667 | 20536 |
| 020507 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:05pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595502.2 | 511844.8 | 65887 | 1.64041666667 | 20507 |
| 020010 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:06pm | Sensor | 1797-S0046-905-G-ACK | 6829.4 | 1595502.1 | 511844.8 | 65889 | 1.64041666667 | 20010 |
| 019468 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:06pm | Sensor | 1797-S0046-905-G-ACK | 6829.4 | 1595502.2 | 511844.6 | 65890 | 1.64041666667 | 19468 |
| 019898 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:07pm | Sensor | 1797-S0046-905-G-ACK | 6829.5 | 1595502.5 | 511844.5 | 65892 | 1.64041666667 | 19898 |
| 020418 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:08pm | Sensor | 1797-S0046-905-G-ACK | 6829.5 | 1595502.5 | 511844.5 | 65894 | 1.64041666667 | 20418 |
| 021460 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:10pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595500.7 | 511844.2 | 65897 | 1.64041666667 | 21460 |
| 021131 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:11pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595500.9 | 511843.3 | 65899 | 1.64041666667 | 21131 |
| 020339 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:12pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595500.6 | 511842.8 | 65901 | 1.64041666667 | 20339 |
| 018625 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:12pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595500.3 | 511842.5 | 65902 | 1.64041666667 | 18625 |
| 017542 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:14pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595499.5 | 511842.9 | 65905 | 1.64041666667 | 17542 |
| 017209 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:15pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595498.6 | 511842.9 | 65907 | 1.64041666667 | 17209 |
| 015808 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:16pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595498.0 | 511842.7 | 65909 | 1.64041666667 | 15808 |
| 015994 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:16pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595497.7 | 511842.9 | 65910 | 1.64041666667 | 15994 |
| 015964 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:17pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595498.1 | 511842.5 | 65912 | 1.64041666667 | 15964 |
| 015722 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:18pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595499.3 | 511840.9 | 65914 | 1.64041666667 | 15722 |
| 016171 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:19pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595499.6 | 511838.0 | 65916 | 1.64041666667 | 16171 |
| 017009 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:20pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595499.8 | 511835.3 | 65918 | 1.64041666667 | 17009 |
| 016332 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:22pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595500.5 | 511831.6 | 65921 | 1.64041666667 | 16332 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016117 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:22pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595501.5 | 511828.9 | 65922 | 1.64041666667 | 16117 |
| 016048 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:24pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595502.9 | 511825.2 | 65925 | 1.64041666667 | 16048 |
| 015634 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:24pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595503.7 | 511822.8 | 65926 | 1.64041666667 | 15634 |
| 014382 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:26pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595505.4 | 511819.3 | 65929 | 1.64041666667 | 14382 |
| 014659 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:26pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595507.1 | 511817.0 | 65930 | 1.64041666667 | 14659 |
| 014793 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:28pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595509.5 | 511814.2 | 65933 | 1.64041666667 | 14793 |
| 014336 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:28pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595511.0 | 511811.8 | 65934 | 1.64041666667 | 14336 |
| 015249 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:30pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595512.9 | 511808.4 | 65937 | 1.64041666667 | 15249 |
| 014577 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:31pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595514.2 | 511805.9 | 65939 | 1.64041666667 | 14577 |
| 014545 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:32pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595516.3 | 511802.8 | 65941 | 1.64041666667 | 14545 |
| 014226 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:33pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595518.0 | 511800.2 | 65943 | 1.64041666667 | 14226 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:34pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595520.1 | 511797.1 | 65945 | 1.64041666667 | 14737 |
| 014844 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:35pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595521.8 | 511794.1 | 65947 | 1.64041666667 | 14844 |
| 014740 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:36pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595523.5 | 511791.3 | 65949 | 1.64041666667 | 14740 |
| 014411 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:36pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595524.8 | 511789.0 | 65950 | 1.64041666667 | 14411 |
| 014751 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:38pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595527.3 | 511785.5 | 65953 | 1.64041666667 | 14751 |
| 014537 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:38pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595528.4 | 511783.6 | 65954 | 1.64041666667 | 14537 |
| 013727 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:40pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595529.9 | 511780.4 | 65957 | 1.64041666667 | 13727 |
| 013444 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:40pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595531.0 | 511777.9 | 65958 | 1.64041666667 | 13444 |
| 014012 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:42pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595532.7 | 511774.9 | 65961 | 1.64041666667 | 14012 |
| 013177 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:42pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595534.1 | 511772.8 | 65962 | 1.64041666667 | 13177 |
| 013524 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:44pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595536.5 | 511769.9 | 65965 | 1.64041666667 | 13524 |
| 014365 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:44pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595538.3 | 511767.9 | 65966 | 1.64041666667 | 14365 |
| 014418 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:46pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595540.1 | 511765.2 | 65969 | 1.64041666667 | 14418 |
| 014912 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:46pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595541.5 | 511762.9 | 65970 | 1.64041666667 | 14912 |
| 014358 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:48pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595543.4 | 511759.5 | 65973 | 1.64041666667 | 14358 |
| 015846 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:48pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595545.2 | 511757.1 | 65974 | 1.64041666667 | 15846 |
| 015873 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:50pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595547.7 | 511753.8 | 65977 | 1.64041666667 | 15873 |
| 014666 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:50pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595549.7 | 511751.6 | 65978 | 1.64041666667 | 14666 |
| 014242 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:52pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595551.9 | 511748.8 | 65981 | 1.64041666667 | 14242 |
| 014978 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:52pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595553.5 | 511746.6 | 65982 | 1.64041666667 | 14978 |
| 014448 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:54pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595555.5 | 511743.6 | 65985 | 1.64041666667 | 14448 |
| 013977 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:54pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595557.4 | 511741.6 | 65986 | 1.64041666667 | 13977 |
| 014222 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:55pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595559.9 | 511739.9 | 65988 | 1.64041666667 | 14222 |
| 014337 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:56pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595562.5 | 511738.8 | 65990 | 1.64041666667 | 14337 |
| 015204 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:58pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595565.7 | 511736.8 | 65993 | 1.64041666667 | 15204 |
| 014425 | 0 | GeoXH 6000 | 08/19/2015 | 12:26:59pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595567.8 | 511734.7 | 65995 | 1.64041666667 | 14425 |
| 014594 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:00pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595569.4 | 511731.9 | 65997 | 1.64041666667 | 14594 |
| 014014 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:01pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595570.4 | 511729.5 | 65999 | 1.64041666667 | 14014 |
| 014880 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:02pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595571.6 | 511726.5 | 66001 | 1.64041666667 | 14880 |
| 014895 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:02pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595572.4 | 511723.8 | 66002 | 1.64041666667 | 14895 |
| 014513 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:04pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595573.4 | 511720.5 | 66005 | 1.64041666667 | 14513 |
| 014441 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:05pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595574.4 | 511717.7 | 66007 | 1.64041666667 | 14441 |
| 013575 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:06pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595575.5 | 511714.6 | 66009 | 1.64041666667 | 13575 |
| 013576 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:06pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595576.5 | 511711.9 | 66010 | 1.64041666667 | 13576 |
| 014146 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:07pm | Sensor | 1797-S0046-905-G-ACK | 6830.7 | 1595577.8 | 511709.0 | 66012 | 1.64041666667 | 14146 |
| 014580 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:08pm | Sensor | 1797-S0046-905-G-ACK | 6830.7 | 1595578.7 | 511705.9 | 66014 | 1.64041666667 | 14580 |
| 014246 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:10pm | Sensor | 1797-S0046-905-G-ACK | 6830.7 | 1595579.5 | 511702.3 | 66017 | 1.64041666667 | 14246 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013961 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:11pm | Sensor | 1797-S0046-905-G-ACK | 6830.7 | 1595580.0 | 511699.8 | 66019 | 1.64041666667 | 13961 |
| 013298 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:12pm | Sensor | 1797-S0046-905-G-ACK | 6830.7 | 1595580.4 | 511696.1 | 66021 | 1.64041666667 | 13298 |
| 014080 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:13pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595580.7 | 511693.3 | 66023 | 1.64041666667 | 14080 |
| 013867 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:14pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595580.8 | 511689.6 | 66025 | 1.64041666667 | 13867 |
| 014820 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:14pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595580.7 | 511686.8 | 66026 | 1.64041666667 | 14820 |
| 015056 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:15pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595580.6 | 511683.8 | 66028 | 1.64041666667 | 15056 |
| 014551 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:16pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595580.6 | 511681.0 | 66030 | 1.64041666667 | 14551 |
| 014313 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:18pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595580.4 | 511677.7 | 66033 | 1.64041666667 | 14313 |
| 013578 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:18pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595580.6 | 511675.0 | 66034 | 1.64041666667 | 13578 |
| 013780 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:20pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595582.8 | 511673.2 | 66037 | 1.64041666667 | 13780 |
| 013788 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:20pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595584.2 | 511670.9 | 66038 | 1.64041666667 | 13788 |
| 013658 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:22pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595584.7 | 511666.9 | 66041 | 1.64041666667 | 13658 |
| 013923 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:22pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595586.3 | 511664.6 | 66042 | 1.64041666667 | 13923 |
| 013411 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:24pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595588.7 | 511662.1 | 66045 | 1.64041666667 | 13411 |
| 013844 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:24pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595590.9 | 511660.2 | 66046 | 1.64041666667 | 13844 |
| 013352 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:26pm | Sensor | 1797-S0046-905-G-ACK | 6830.5 | 1595593.5 | 511658.0 | 66049 | 1.64041666667 | 13352 |
| 013660 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:26pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595595.4 | 511656.3 | 66050 | 1.64041666667 | 13660 |
| 013354 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:27pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595597.7 | 511653.7 | 66052 | 1.64041666667 | 13354 |
| 012806 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:28pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595599.3 | 511651.2 | 66054 | 1.64041666667 | 12806 |
| 013203 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:29pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595601.3 | 511648.5 | 66056 | 1.64041666667 | 13203 |
| 012984 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:30pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595602.6 | 511646.2 | 66058 | 1.64041666667 | 12984 |
| 012216 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:32pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595604.6 | 511643.7 | 66061 | 1.64041666667 | 12216 |
| 012879 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:32pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595606.4 | 511641.7 | 66062 | 1.64041666667 | 12879 |
| 012629 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:34pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595608.8 | 511639.2 | 66065 | 1.64041666667 | 12629 |
| 012781 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:34pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595611.2 | 511638.3 | 66066 | 1.64041666667 | 12781 |
| 012267 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:36pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595614.7 | 511637.4 | 66069 | 1.64041666667 | 12267 |
| 012885 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:36pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595617.2 | 511636.7 | 66070 | 1.64041666667 | 12885 |
| 012880 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:38pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595620.3 | 511636.8 | 66073 | 1.64041666667 | 12880 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:38pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595622.8 | 511637.3 | 66074 | 1.64041666667 | 12652 |
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:40pm | Sensor | 1797-S0046-905-G-ACK | 6830.3 | 1595625.8 | 511638.3 | 66077 | 1.64041666667 | 12937 |
| 013329 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:41pm | Sensor | 1797-S0046-905-G-ACK | 6830.1 | 1595628.2 | 511638.8 | 66079 | 1.64041666667 | 13329 |
| 012875 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:42pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595631.2 | 511638.9 | 66081 | 1.64041666667 | 12875 |
| 012612 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:43pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595632.5 | 511637.9 | 66083 | 1.64041666667 | 12612 |
| 013087 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:44pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595634.0 | 511636.1 | 66085 | 1.64041666667 | 13087 |
| 012836 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:45pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595633.9 | 511634.0 | 66087 | 1.64041666667 | 12836 |
| 013010 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:46pm | Sensor | 1797-S0046-905-G-ACK | 6830.6 | 1595633.5 | 511632.0 | 66089 | 1.64041666667 | 13010 |
| 013746 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:46pm | Sensor | 1797-S0046-905-G-ACK | 6830.4 | 1595633.8 | 511630.4 | 66090 | 1.64041666667 | 13746 |
| 013199 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:48pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595634.8 | 511627.5 | 66093 | 1.64041666667 | 13199 |
| 012270 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:48pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595635.8 | 511625.3 | 66094 | 1.64041666667 | 12270 |
| 012256 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:50pm | Sensor | 1797-S0046-905-G-ACK | 6829.5 | 1595636.5 | 511622.3 | 66097 | 1.64041666667 | 12256 |
| 012856 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:51pm | Sensor | 1797-S0046-905-G-ACK | 6829.4 | 1595637.1 | 511619.9 | 66099 | 1.64041666667 | 12856 |
| 013577 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:52pm | Sensor | 1797-S0046-905-G-ACK | 6829.0 | 1595637.7 | 511617.2 | 66101 | 1.64041666667 | 13577 |
| 012512 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:53pm | Sensor | 1797-S0046-905-G-ACK | 6828.9 | 1595638.1 | 511615.2 | 66103 | 1.64041666667 | 12512 |
| 012745 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:54pm | Sensor | 1797-S0046-905-G-ACK | 6828.5 | 1595638.3 | 511612.1 | 66105 | 1.64041666667 | 12745 |
| 012659 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:55pm | Sensor | 1797-S0046-905-G-ACK | 6828.5 | 1595638.7 | 511610.0 | 66107 | 1.64041666667 | 12659 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:56pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595639.6 | 511608.4 | 66109 | 1.64041666667 | 12461 |
| 011944 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:56pm | Sensor | 1797-S0046-905-G-ACK | 6828.4 | 1595638.8 | 511605.0 | 66110 | 1.64041666667 | 11944 |
| 012718 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:58pm | Sensor | 1797-S0046-905-G-ACK | 6828.4 | 1595640.7 | 511602.6 | 66113 | 1.64041666667 | 12718 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012816 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:58pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595641.7 | 511600.5 | 66114 | 1.64041666667 | 12816 |
| 012429 | 0 | GeoXH 6000 | 08/19/2015 | 12:27:59pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595643.1 | 511598.5 | 66116 | 1.64041666667 | 12429 |
| 012526 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:00pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595644.4 | 511596.5 | 66118 | 1.64041666667 | 12526 |
| 012491 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:02pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595645.5 | 511594.0 | 66121 | 1.64041666667 | 12491 |
| 012118 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:02pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595647.5 | 511592.5 | 66122 | 1.64041666667 | 12118 |
| 011992 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:04pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595650.2 | 511590.5 | 66125 | 1.64041666667 | 11992 |
| 012018 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:04pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595650.8 | 511588.5 | 66126 | 1.64041666667 | 12018 |
| 011860 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:06pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595652.3 | 511585.6 | 66129 | 1.64041666667 | 11860 |
| 011703 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:06pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595653.8 | 511584.1 | 66130 | 1.64041666667 | 11703 |
| 011961 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:08pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595655.8 | 511581.5 | 66133 | 1.64041666667 | 11961 |
| 011528 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:09pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595656.8 | 511580.1 | 66135 | 1.64041666667 | 11528 |
| 012582 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:10pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595658.5 | 511578.1 | 66137 | 1.64041666667 | 12582 |
| 012132 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:10pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595658.8 | 511576.4 | 66138 | 1.64041666667 | 12132 |
| 011362 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:12pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.6 | 511575.7 | 66141 | 1.64041666667 | 11362 |
| 011573 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:12pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595658.6 | 511575.6 | 66142 | 1.64041666667 | 11573 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:14pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.6 | 511575.7 | 66145 | 1.64041666667 | 12045 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:14pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.7 | 511575.7 | 66146 | 1.64041666667 | 12475 |
| 011532 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:16pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.7 | 511575.9 | 66149 | 1.64041666667 | 11532 |
| 011692 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:16pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.8 | 511575.9 | 66150 | 1.64041666667 | 11692 |
| 011211 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:18pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595659.0 | 511575.9 | 66153 | 1.64041666667 | 11211 |
| 011376 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:18pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.9 | 511575.8 | 66154 | 1.64041666667 | 11376 |
| 011476 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:20pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.7 | 511575.9 | 66157 | 1.64041666667 | 11476 |
| 011735 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:21pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.1 | 511576.0 | 66159 | 1.64041666667 | 11735 |
| 012008 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:22pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595657.9 | 511576.0 | 66161 | 1.64041666667 | 12008 |
| 012845 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:22pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595657.9 | 511575.9 | 66162 | 1.64041666667 | 12845 |
| 013150 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:24pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595657.8 | 511575.8 | 66165 | 1.64041666667 | 13150 |
| 012752 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:24pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595658.5 | 511575.0 | 66166 | 1.64041666667 | 12752 |
| 011703 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:25pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595658.9 | 511573.0 | 66168 | 1.64041666667 | 11703 |
| 011848 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:26pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595659.5 | 511570.6 | 66170 | 1.64041666667 | 11848 |
| 011194 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:28pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595661.3 | 511567.6 | 66173 | 1.64041666667 | 11194 |
| 011209 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:28pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595661.8 | 511565.1 | 66174 | 1.64041666667 | 11209 |
| 010175 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:29pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595661.6 | 511562.7 | 66176 | 1.64041666667 | 10175 |
| 010268 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:30pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595662.3 | 511560.8 | 66178 | 1.64041666667 | 10268 |
| 010283 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:31pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595662.1 | 511558.3 | 66180 | 1.64041666667 | 10283 |
| 009939 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:32pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595661.0 | 511556.3 | 66182 | 1.64041666667 | 9939 |
| 010458 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:34pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595659.7 | 511554.2 | 66185 | 1.64041666667 | 10458 |
| 009805 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:34pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595659.4 | 511552.2 | 66186 | 1.64041666667 | 9805 |
| 010285 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:36pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595658.3 | 511550.5 | 66189 | 1.64041666667 | 10285 |
| 009753 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:37pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595658.2 | 511548.7 | 66191 | 1.64041666667 | 9753 |
| 009446 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:38pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595658.5 | 511547.2 | 66193 | 1.64041666667 | 9446 |
| 009731 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:39pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595658.2 | 511545.3 | 66195 | 1.64041666667 | 9731 |
| 010176 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:40pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595657.3 | 511543.3 | 66197 | 1.64041666667 | 10176 |
| 010929 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:40pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595656.6 | 511542.2 | 66198 | 1.64041666667 | 10929 |
| 010992 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595656.1 | 511540.0 | 66201 | 1.64041666667 | 10992 |
| 011238 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595654.9 | 511539.2 | 66202 | 1.64041666667 | 11238 |
| 011406 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:44pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595653.4 | 511537.4 | 66205 | 1.64041666667 | 11406 |
| 011216 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:44pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595652.4 | 511535.5 | 66206 | 1.64041666667 | 11216 |
| 011176 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:46pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595650.4 | 511533.8 | 66209 | 1.64041666667 | 11176 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010854 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:47pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595649.4 | 511532.3 | 66211 | 1.64041666667 | 10854 |
| 010470 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:48pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595648.1 | 511529.9 | 66213 | 1.64041666667 | 10470 |
| 010487 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:49pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595646.6 | 511528.9 | 66215 | 1.64041666667 | 10487 |
| 010631 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:50pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595645.3 | 511526.7 | 66217 | 1.64041666667 | 10631 |
| 011335 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:50pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595644.5 | 511525.5 | 66218 | 1.64041666667 | 11335 |
| 010381 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:52pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595642.7 | 511524.3 | 66221 | 1.64041666667 | 10381 |
| 010856 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:52pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595641.6 | 511522.3 | 66222 | 1.64041666667 | 10856 |
| 010697 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595639.8 | 511521.4 | 66225 | 1.64041666667 | 10697 |
| 010997 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595638.4 | 511521.0 | 66226 | 1.64041666667 | 10997 |
| 011788 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595636.9 | 511520.9 | 66229 | 1.64041666667 | 11788 |
| 011506 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595635.1 | 511520.3 | 66230 | 1.64041666667 | 11506 |
| 011654 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595632.7 | 511520.5 | 66233 | 1.64041666667 | 11654 |
| 011925 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595631.4 | 511519.9 | 66234 | 1.64041666667 | 11925 |
| 012100 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:00pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595629.4 | 511518.4 | 66237 | 1.64041666667 | 12100 |
| 011565 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:01pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595627.7 | 511517.7 | 66239 | 1.64041666667 | 11565 |
| 011430 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:02pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595626.0 | 511516.4 | 66241 | 1.64041666667 | 11430 |
| 012279 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:02pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595624.4 | 511516.2 | 66242 | 1.64041666667 | 12279 |
| 011797 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:04pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595622.8 | 511514.8 | 66245 | 1.64041666667 | 11797 |
| 011856 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:04pm | Sensor | 1797-S0046-905-G-ACK | 6824.6 | 1595622.7 | 511514.5 | 66246 | 1.64041666667 | 11856 |
| 011956 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:06pm | Sensor | 1797-S0046-905-G-ACK | 6824.5 | 1595620.6 | 511513.3 | 66249 | 1.64041666667 | 11956 |
| 011818 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:06pm | Sensor | 1797-S0046-905-G-ACK | 6824.5 | 1595620.2 | 511512.6 | 66250 | 1.64041666667 | 11818 |
| 011680 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:08pm | Sensor | 1797-S0046-905-G-ACK | 6824.5 | 1595620.8 | 511510.6 | 66253 | 1.64041666667 | 11680 |
| 011467 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:08pm | Sensor | 1797-S0046-905-G-ACK | 6824.4 | 1595620.7 | 511508.5 | 66254 | 1.64041666667 | 11467 |
| 011580 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:10pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595618.8 | 511505.0 | 66257 | 1.64041666667 | 11580 |
| 012281 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:10pm | Sensor | 1797-S0046-905-G-ACK | 6824.6 | 1595619.5 | 511504.0 | 66258 | 1.64041666667 | 12281 |
| 012540 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:12pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595618.4 | 511501.5 | 66261 | 1.64041666667 | 12540 |
| 011246 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:12pm | Sensor | 1797-S0046-905-G-ACK | 6824.0 | 1595617.3 | 511500.0 | 66262 | 1.64041666667 | 11246 |
| 011013 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:13pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595615.3 | 511498.3 | 66264 | 1.64041666667 | 11013 |
| 011557 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:14pm | Sensor | 1797-S0046-905-G-ACK | 6824.1 | 1595612.7 | 511498.3 | 66266 | 1.64041666667 | 11557 |
| 011743 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:16pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595609.7 | 511496.4 | 66269 | 1.64041666667 | 11743 |
| 011548 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:17pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595608.4 | 511495.2 | 66271 | 1.64041666667 | 11548 |
| 010951 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:18pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595607.3 | 511492.8 | 66273 | 1.64041666667 | 10951 |
| 011687 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:19pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595604.9 | 511491.9 | 66275 | 1.64041666667 | 11687 |
| 011524 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:20pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595603.0 | 511490.5 | 66277 | 1.64041666667 | 11524 |
| 011079 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:21pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595602.8 | 511488.7 | 66279 | 1.64041666667 | 11079 |
| 011715 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:22pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595600.4 | 511487.5 | 66281 | 1.64041666667 | 11715 |
| 011239 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:23pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595598.4 | 511487.1 | 66283 | 1.64041666667 | 11239 |
| 010904 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:24pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595596.4 | 511485.7 | 66285 | 1.64041666667 | 10904 |
| 010769 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:25pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595594.6 | 511485.6 | 66287 | 1.64041666667 | 10769 |
| 011345 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:26pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595592.4 | 511485.7 | 66289 | 1.64041666667 | 11345 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:26pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595590.6 | 511485.7 | 66290 | 1.64041666667 | 11241 |
| 011543 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:28pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595588.3 | 511486.4 | 66293 | 1.64041666667 | 11543 |
| 010970 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:28pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595586.8 | 511486.2 | 66294 | 1.64041666667 | 10970 |
| 011608 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:30pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595584.7 | 511487.4 | 66297 | 1.64041666667 | 11608 |
| 011764 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:31pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595584.5 | 511489.3 | 66299 | 1.64041666667 | 11764 |
| 011920 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:32pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595584.2 | 511491.9 | 66301 | 1.64041666667 | 11920 |
| 011925 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:33pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595584.2 | 511494.0 | 66303 | 1.64041666667 | 11925 |
| 011823 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:34pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595585.2 | 511496.1 | 66305 | 1.64041666667 | 11823 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011892 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:35pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595585.2 | 511497.6 | 66307 | 1.64041666667 | 11892 |
| 012194 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:36pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595586.1 | 511499.2 | 66309 | 1.64041666667 | 12194 |
| 012094 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:36pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595586.2 | 511500.7 | 66310 | 1.64041666667 | 12094 |
| 011723 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:38pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595585.4 | 511501.8 | 66313 | 1.64041666667 | 11723 |
| 011312 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:38pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595584.0 | 511502.5 | 66314 | 1.64041666667 | 11312 |
| 011940 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:40pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595582.5 | 511501.5 | 66317 | 1.64041666667 | 11940 |
| 011711 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:41pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595580.9 | 511501.0 | 66319 | 1.64041666667 | 11711 |
| 011320 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:42pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595580.8 | 511498.7 | 66321 | 1.64041666667 | 11320 |
| 011580 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:43pm | Sensor | 1797-S0046-905-G-ACK | 6823.4 | 1595581.5 | 511497.5 | 66323 | 1.64041666667 | 11580 |
| 012041 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:44pm | Sensor | 1797-S0046-905-G-ACK | 6823.3 | 1595580.0 | 511495.1 | 66325 | 1.64041666667 | 12041 |
| 012098 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:45pm | Sensor | 1797-S0046-905-G-ACK | 6823.5 | 1595578.9 | 511493.4 | 66327 | 1.64041666667 | 12098 |
| 011725 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:46pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595575.1 | 511491.8 | 66329 | 1.64041666667 | 11725 |
| 012063 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:46pm | Sensor | 1797-S0046-905-G-ACK | 6824.6 | 1595573.6 | 511490.4 | 66330 | 1.64041666667 | 12063 |
| 011683 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:47pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595571.5 | 511490.5 | 66332 | 1.64041666667 | 11683 |
| 012114 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:48pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595569.5 | 511491.0 | 66334 | 1.64041666667 | 12114 |
| 012086 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:50pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595566.9 | 511491.2 | 66337 | 1.64041666667 | 12086 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:50pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595565.6 | 511492.0 | 66338 | 1.64041666667 | 12056 |
| 012571 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:52pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595563.8 | 511491.3 | 66341 | 1.64041666667 | 12571 |
| 013049 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:53pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595561.8 | 511492.4 | 66343 | 1.64041666667 | 13049 |
| 012305 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:54pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595560.4 | 511494.6 | 66345 | 1.64041666667 | 12305 |
| 012096 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:54pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595559.3 | 511495.7 | 66346 | 1.64041666667 | 12096 |
| 011746 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:56pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595558.0 | 511498.0 | 66349 | 1.64041666667 | 11746 |
| 012360 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:56pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595556.5 | 511498.5 | 66350 | 1.64041666667 | 12360 |
| 012262 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:57pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595555.0 | 511499.4 | 66352 | 1.64041666667 | 12262 |
| 012530 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:58pm | Sensor | 1797-S0046-905-G-ACK | 6824.5 | 1595553.3 | 511500.2 | 66354 | 1.64041666667 | 12530 |
| 012455 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:59pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595550.9 | 511499.2 | 66356 | 1.64041666667 | 12455 |
| 012541 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:00pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595548.9 | 511500.2 | 66358 | 1.64041666667 | 12541 |
| 012207 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:01pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595546.6 | 511499.8 | 66360 | 1.64041666667 | 12207 |
| 011261 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:02pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595544.8 | 511500.6 | 66362 | 1.64041666667 | 11261 |
| 012004 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595542.6 | 511502.0 | 66365 | 1.64041666667 | 12004 |
| 011732 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595541.0 | 511502.9 | 66366 | 1.64041666667 | 11732 |
| 013027 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:06pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595540.6 | 511504.8 | 66369 | 1.64041666667 | 13027 |
| 013050 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:06pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595541.2 | 511507.1 | 66370 | 1.64041666667 | 13050 |
| 011930 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:07pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595540.8 | 511509.5 | 66372 | 1.64041666667 | 11930 |
| 012673 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:08pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595540.8 | 511511.7 | 66374 | 1.64041666667 | 12673 |
| 012033 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:10pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595538.6 | 511513.7 | 66377 | 1.64041666667 | 12033 |
| 011996 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:11pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595539.0 | 511515.2 | 66379 | 1.64041666667 | 11996 |
| 012935 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:12pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595539.4 | 511517.1 | 66381 | 1.64041666667 | 12935 |
| 012451 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:12pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595540.2 | 511519.6 | 66382 | 1.64041666667 | 12451 |
| 012441 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:14pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595541.3 | 511521.0 | 66385 | 1.64041666667 | 12441 |
| 011685 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:14pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595543.5 | 511524.4 | 66386 | 1.64041666667 | 11685 |
| 011403 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595543.6 | 511525.0 | 66389 | 1.64041666667 | 11403 |
| 012249 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595543.8 | 511527.0 | 66390 | 1.64041666667 | 12249 |
| 012402 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:17pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595544.6 | 511528.9 | 66392 | 1.64041666667 | 12402 |
| 012549 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:18pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595544.9 | 511531.4 | 66394 | 1.64041666667 | 12549 |
| 011641 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:20pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595545.1 | 511534.3 | 66397 | 1.64041666667 | 11641 |
| 011700 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:20pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595545.4 | 511536.2 | 66398 | 1.64041666667 | 11700 |
| 011621 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:22pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595544.0 | 511537.6 | 66401 | 1.64041666667 | 11621 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:22pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595543.5 | 511539.4 | 66402 | 1.64041666667 | 12019 |
| 012191 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:24pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595543.7 | 511542.0 | 66405 | 1.64041666667 | 12191 |
| 012220 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:24pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595543.9 | 511543.4 | 66406 | 1.64041666667 | 12220 |
| 011958 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:25pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595543.9 | 511545.5 | 66408 | 1.64041666667 | 11958 |
| 012531 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595544.6 | 511547.1 | 66410 | 1.64041666667 | 12531 |
| 012126 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:27pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595545.9 | 511550.1 | 66412 | 1.64041666667 | 12126 |
| 012093 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:28pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595545.6 | 511551.5 | 66414 | 1.64041666667 | 12093 |
| 011632 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:30pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595546.1 | 511554.3 | 66417 | 1.64041666667 | 11632 |
| 011433 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:30pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595546.9 | 511556.0 | 66418 | 1.64041666667 | 11433 |
| 010766 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:32pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595546.2 | 511557.6 | 66421 | 1.64041666667 | 10766 |
| 010856 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:32pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595545.4 | 511559.5 | 66422 | 1.64041666667 | 10856 |
| 011304 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:34pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595545.7 | 511561.8 | 66425 | 1.64041666667 | 11304 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:34pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595545.0 | 511563.8 | 66426 | 1.64041666667 | 11953 |
| 012581 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:36pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595545.4 | 511565.6 | 66429 | 1.64041666667 | 12581 |
| 012822 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:36pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595544.4 | 511567.0 | 66430 | 1.64041666667 | 12822 |
| 012042 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:37pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595544.5 | 511568.6 | 66432 | 1.64041666667 | 12042 |
| 012211 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:38pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595544.4 | 511570.0 | 66434 | 1.64041666667 | 12211 |
| 012606 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:40pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595544.3 | 511572.9 | 66437 | 1.64041666667 | 12606 |
| 012731 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:41pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595544.9 | 511574.1 | 66439 | 1.64041666667 | 12731 |
| 011968 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595544.9 | 511576.7 | 66441 | 1.64041666667 | 11968 |
| 012672 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:43pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595546.0 | 511577.9 | 66443 | 1.64041666667 | 12672 |
| 012333 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:44pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595546.7 | 511580.2 | 66445 | 1.64041666667 | 12333 |
| 012202 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:44pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595547.6 | 511582.0 | 66446 | 1.64041666667 | 12202 |
| 011761 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:46pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595546.8 | 511582.9 | 66449 | 1.64041666667 | 11761 |
| 011070 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:47pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595548.2 | 511584.5 | 66451 | 1.64041666667 | 11070 |
| 011439 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:48pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595551.1 | 511585.2 | 66453 | 1.64041666667 | 11439 |
| 011355 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:48pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595552.3 | 511586.9 | 66454 | 1.64041666667 | 11355 |
| 011262 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:50pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595554.1 | 511588.1 | 66457 | 1.64041666667 | 11262 |
| 011292 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:50pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595553.9 | 511588.4 | 66458 | 1.64041666667 | 11292 |
| 011842 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:52pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595555.0 | 511589.8 | 66461 | 1.64041666667 | 11842 |
| 011228 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:52pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595557.6 | 511591.5 | 66462 | 1.64041666667 | 11228 |
| 011221 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:53pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595559.4 | 511591.4 | 66464 | 1.64041666667 | 11221 |
| 010991 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595560.6 | 511592.3 | 66466 | 1.64041666667 | 10991 |
| 011253 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595562.3 | 511593.9 | 66469 | 1.64041666667 | 11253 |
| 012060 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595562.0 | 511596.0 | 66470 | 1.64041666667 | 12060 |
| 012018 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595564.2 | 511597.3 | 66473 | 1.64041666667 | 12018 |
| 012910 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595565.2 | 511598.3 | 66474 | 1.64041666667 | 12910 |
| 013044 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:00pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595567.6 | 511597.8 | 66477 | 1.64041666667 | 13044 |
| 012610 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:00pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595569.2 | 511596.9 | 66478 | 1.64041666667 | 12610 |
| 012755 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:02pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595571.6 | 511596.9 | 66481 | 1.64041666667 | 12755 |
| 012275 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:03pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595573.2 | 511597.1 | 66483 | 1.64041666667 | 12275 |
| 011217 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595576.1 | 511598.7 | 66485 | 1.64041666667 | 11217 |
| 012977 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:04pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595578.8 | 511599.1 | 66486 | 1.64041666667 | 12977 |
| 012872 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:06pm | Sensor | 1797-S0046-905-G-ACK | 6824.6 | 1595580.6 | 511599.0 | 66489 | 1.64041666667 | 12872 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:07pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595582.4 | 511599.9 | 66491 | 1.64041666667 | 12760 |
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:08pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595583.6 | 511600.8 | 66493 | 1.64041666667 | 12562 |
| 012204 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:08pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595585.5 | 511601.4 | 66494 | 1.64041666667 | 12204 |
| 011897 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:09pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595585.8 | 511601.1 | 66496 | 1.64041666667 | 11897 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012287 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:10pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595588.6 | 511601.3 | 66498 | 1.64041666667 | 12287 |
| 012259 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:11pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595590.5 | 511601.3 | 66500 | 1.64041666667 | 12259 |
| 011883 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:12pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595592.0 | 511602.6 | 66502 | 1.64041666667 | 11883 |
| 011349 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:13pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595594.7 | 511602.9 | 66504 | 1.64041666667 | 11349 |
| 012616 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:14pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595596.8 | 511604.2 | 66506 | 1.64041666667 | 12616 |
| 012654 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595596.2 | 511602.6 | 66509 | 1.64041666667 | 12654 |
| 012233 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595596.9 | 511603.0 | 66510 | 1.64041666667 | 12233 |
| 012888 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:18pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595597.1 | 511603.1 | 66513 | 1.64041666667 | 12888 |
| 012439 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:19pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595596.9 | 511603.0 | 66515 | 1.64041666667 | 12439 |
| 011977 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:20pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595598.9 | 511602.7 | 66517 | 1.64041666667 | 11977 |
| 011724 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:20pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595600.8 | 511601.3 | 66518 | 1.64041666667 | 11724 |
| 011395 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:21pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595600.3 | 511600.4 | 66520 | 1.64041666667 | 11395 |
| 011652 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:22pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595600.2 | 511600.9 | 66522 | 1.64041666667 | 11652 |
| 012157 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:24pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595600.2 | 511600.8 | 66525 | 1.64041666667 | 12157 |
| 012635 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:24pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595600.0 | 511600.7 | 66526 | 1.64041666667 | 12635 |
| 012732 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:26pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595600.0 | 511600.7 | 66529 | 1.64041666667 | 12732 |
| 011849 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:26pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595600.1 | 511600.8 | 66530 | 1.64041666667 | 11849 |
| 012575 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:28pm | Sensor | 1797-S0046-905-G-ACK | 6822.9 | 1595600.8 | 511601.1 | 66533 | 1.64041666667 | 12575 |
| 012113 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:28pm | Sensor | 1797-S0046-905-G-ACK | 6823.0 | 1595600.7 | 511601.1 | 66534 | 1.64041666667 | 12113 |
| 011643 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:30pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595599.9 | 511600.9 | 66537 | 1.64041666667 | 11643 |
| 011904 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:31pm | Sensor | 1797-S0046-905-G-ACK | 6822.9 | 1595600.7 | 511601.4 | 66539 | 1.64041666667 | 11904 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:32pm | Sensor | 1797-S0046-905-G-ACK | 6822.8 | 1595600.8 | 511601.2 | 66541 | 1.64041666667 | 12539 |
| 012220 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:32pm | Sensor | 1797-S0046-905-G-ACK | 6823.0 | 1595600.2 | 511600.8 | 66542 | 1.64041666667 | 12220 |
| 012064 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:34pm | Sensor | 1797-S0046-905-G-ACK | 6822.9 | 1595599.5 | 511600.5 | 66545 | 1.64041666667 | 12064 |
| 012253 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:34pm | Sensor | 1797-S0046-905-G-ACK | 6822.9 | 1595599.6 | 511600.5 | 66546 | 1.64041666667 | 12253 |
| 012667 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:35pm | Sensor | 1797-S0046-905-G-ACK | 6824.4 | 1595599.6 | 511600.8 | 66548 | 1.64041666667 | 12667 |
| 012915 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:36pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595599.2 | 511602.5 | 66550 | 1.64041666667 | 12915 |
| 013520 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:37pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595600.1 | 511601.8 | 66552 | 1.64041666667 | 13520 |
| 013125 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:38pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595602.3 | 511601.3 | 66554 | 1.64041666667 | 13125 |
| 012662 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:39pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595604.2 | 511600.4 | 66556 | 1.64041666667 | 12662 |
| 012215 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:40pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595606.2 | 511601.0 | 66558 | 1.64041666667 | 12215 |
| 012526 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:42pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595607.5 | 511600.8 | 66561 | 1.64041666667 | 12526 |
| 011778 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:42pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595609.6 | 511600.6 | 66562 | 1.64041666667 | 11778 |
| 011305 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:43pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595611.5 | 511601.5 | 66564 | 1.64041666667 | 11305 |
| 012284 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:44pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595613.0 | 511602.4 | 66566 | 1.64041666667 | 12284 |
| 011807 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:45pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595613.5 | 511604.9 | 66568 | 1.64041666667 | 11807 |
| 011681 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:46pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595614.8 | 511606.8 | 66570 | 1.64041666667 | 11681 |
| 012060 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:47pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595616.3 | 511608.8 | 66572 | 1.64041666667 | 12060 |
| 011779 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:48pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595617.4 | 511610.8 | 66574 | 1.64041666667 | 11779 |
| 011643 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:49pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595619.5 | 511612.2 | 66576 | 1.64041666667 | 11643 |
| 011844 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:50pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595620.5 | 511614.3 | 66578 | 1.64041666667 | 11844 |
| 012730 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:52pm | Sensor | 1797-S0046-905-G-ACK | 6828.4 | 1595621.9 | 511616.1 | 66581 | 1.64041666667 | 12730 |
| 012425 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:52pm | Sensor | 1797-S0046-905-G-ACK | 6828.7 | 1595623.1 | 511617.8 | 66582 | 1.64041666667 | 12425 |
| 013259 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:54pm | Sensor | 1797-S0046-905-G-ACK | 6829.2 | 1595623.9 | 511620.2 | 66585 | 1.64041666667 | 13259 |
| 013571 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:54pm | Sensor | 1797-S0046-905-G-ACK | 6829.3 | 1595625.4 | 511621.0 | 66586 | 1.64041666667 | 13571 |
| 013881 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:55pm | Sensor | 1797-S0046-905-G-ACK | 6829.2 | 1595627.3 | 511622.6 | 66588 | 1.64041666667 | 13881 |
| 013523 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:56pm | Sensor | 1797-S0046-905-G-ACK | 6829.4 | 1595629.2 | 511623.3 | 66590 | 1.64041666667 | 13523 |
| 012751 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:57pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595629.6 | 511623.6 | 66592 | 1.64041666667 | 12751 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012940 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:58pm | Sensor | 1797-S0046-905-G-ACK | 6829.3 | 1595627.8 | 511622.4 | 66594 | 1.64041666667 | 12940 |
| 012176 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:59pm | Sensor | 1797-S0046-905-G-ACK | 6829.2 | 1595625.6 | 511621.9 | 66596 | 1.64041666667 | 12176 |
| 012219 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:00pm | Sensor | 1797-S0046-905-G-ACK | 6829.2 | 1595623.6 | 511622.7 | 66598 | 1.64041666667 | 12219 |
| 012903 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:02pm | Sensor | 1797-S0046-905-G-ACK | 6829.2 | 1595620.9 | 511622.7 | 66601 | 1.64041666667 | 12903 |
| 011615 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:02pm | Sensor | 1797-S0046-905-G-ACK | 6829.3 | 1595619.1 | 511623.7 | 66602 | 1.64041666667 | 11615 |
| 012271 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:03pm | Sensor | 1797-S0046-905-G-ACK | 6829.1 | 1595616.8 | 511623.7 | 66604 | 1.64041666667 | 12271 |
| 011755 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:04pm | Sensor | 1797-S0046-905-G-ACK | 6829.2 | 1595614.3 | 511624.6 | 66606 | 1.64041666667 | 11755 |
| 013789 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:06pm | Sensor | 1797-S0046-905-G-ACK | 6829.4 | 1595612.5 | 511625.8 | 66609 | 1.64041666667 | 13789 |
| 013471 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:06pm | Sensor | 1797-S0046-905-G-ACK | 6829.2 | 1595611.4 | 511624.5 | 66610 | 1.64041666667 | 13471 |
| 013742 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:08pm | Sensor | 1797-S0046-905-G-ACK | 6828.9 | 1595609.6 | 511623.1 | 66613 | 1.64041666667 | 13742 |
| 014142 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:08pm | Sensor | 1797-S0046-905-G-ACK | 6829.0 | 1595607.6 | 511622.8 | 66614 | 1.64041666667 | 14142 |
| 013670 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:09pm | Sensor | 1797-S0046-905-G-ACK | 6828.7 | 1595606.4 | 511621.2 | 66616 | 1.64041666667 | 13670 |
| 013224 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:10pm | Sensor | 1797-S0046-905-G-ACK | 6828.5 | 1595604.3 | 511620.3 | 66618 | 1.64041666667 | 13224 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:11pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595602.3 | 511619.5 | 66620 | 1.64041666667 | 13424 |
| 013206 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:12pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595601.0 | 511618.4 | 66622 | 1.64041666667 | 13206 |
| 013053 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:13pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595599.1 | 511617.6 | 66624 | 1.64041666667 | 13053 |
| 013575 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:14pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595598.0 | 511616.1 | 66626 | 1.64041666667 | 13575 |
| 012698 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:16pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595595.5 | 511615.8 | 66629 | 1.64041666667 | 12698 |
| 012925 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:16pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595594.0 | 511614.7 | 66630 | 1.64041666667 | 12925 |
| 012055 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:18pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595592.0 | 511614.7 | 66633 | 1.64041666667 | 12055 |
| 013006 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:18pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595592.0 | 511613.9 | 66634 | 1.64041666667 | 13006 |
| 012776 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:19pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595590.3 | 511613.5 | 66636 | 1.64041666667 | 12776 |
| 012166 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:20pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595589.5 | 511612.1 | 66638 | 1.64041666667 | 12166 |
| 012206 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:21pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595588.6 | 511611.8 | 66640 | 1.64041666667 | 12206 |
| 012288 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:22pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595587.3 | 511610.7 | 66642 | 1.64041666667 | 12288 |
| 012739 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:23pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595584.3 | 511610.1 | 66644 | 1.64041666667 | 12739 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:24pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595583.0 | 511608.9 | 66646 | 1.64041666667 | 12521 |
| 012360 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:25pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595580.7 | 511608.5 | 66648 | 1.64041666667 | 12360 |
| 012517 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595579.4 | 511606.9 | 66650 | 1.64041666667 | 12517 |
| 011893 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:27pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595577.3 | 511606.4 | 66652 | 1.64041666667 | 11893 |
| 012217 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:28pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595576.4 | 511605.1 | 66654 | 1.64041666667 | 12217 |
| 011567 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:29pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595574.6 | 511604.9 | 66656 | 1.64041666667 | 11567 |
| 011119 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:30pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595574.3 | 511604.0 | 66658 | 1.64041666667 | 11119 |
| 010387 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:32pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595572.9 | 511603.7 | 66661 | 1.64041666667 | 10387 |
| 011422 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:32pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595571.7 | 511603.3 | 66662 | 1.64041666667 | 11422 |
| 011765 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:34pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595569.9 | 511603.5 | 66665 | 1.64041666667 | 11765 |
| 011928 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:34pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595569.0 | 511603.5 | 66666 | 1.64041666667 | 11928 |
| 011967 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:35pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595566.9 | 511604.1 | 66668 | 1.64041666667 | 11967 |
| 011883 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:36pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595564.6 | 511604.5 | 66670 | 1.64041666667 | 11883 |
| 011484 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:37pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595563.5 | 511605.9 | 66672 | 1.64041666667 | 11484 |
| 011672 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:38pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595561.9 | 511606.4 | 66674 | 1.64041666667 | 11672 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:39pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595559.8 | 511607.4 | 66676 | 1.64041666667 | 12078 |
| 011526 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:40pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595559.2 | 511606.9 | 66678 | 1.64041666667 | 11526 |
| 011883 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:41pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595558.4 | 511606.8 | 66680 | 1.64041666667 | 11883 |
| 011364 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595558.8 | 511605.7 | 66682 | 1.64041666667 | 11364 |
| 011147 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:43pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595557.9 | 511604.3 | 66684 | 1.64041666667 | 11147 |
| 011460 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:44pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595557.9 | 511602.9 | 66686 | 1.64041666667 | 11460 |
| 012334 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:46pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595555.8 | 511600.9 | 66689 | 1.64041666667 | 12334 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012352 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:46pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595554.3 | 511600.5 | 66690 | 1.64041666667 | 12352 |
| 012701 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:47pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595554.2 | 511598.6 | 66692 | 1.64041666667 | 12701 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:48pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595553.6 | 511597.4 | 66694 | 1.64041666667 | 12056 |
| 011544 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:50pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595553.3 | 511595.2 | 66697 | 1.64041666667 | 11544 |
| 011548 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:50pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595551.5 | 511594.5 | 66698 | 1.64041666667 | 11548 |
| 011386 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:51pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595548.1 | 511593.8 | 66700 | 1.64041666667 | 11386 |
| 011714 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:52pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595546.6 | 511593.3 | 66702 | 1.64041666667 | 11714 |
| 011944 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:53pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595544.8 | 511592.6 | 66704 | 1.64041666667 | 11944 |
| 011391 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:54pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595544.5 | 511591.2 | 66706 | 1.64041666667 | 11391 |
| 012302 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:56pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595543.3 | 511590.3 | 66709 | 1.64041666667 | 12302 |
| 012132 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:56pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595543.5 | 511590.9 | 66710 | 1.64041666667 | 12132 |
| 012209 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:57pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595543.8 | 511591.6 | 66712 | 1.64041666667 | 12209 |
| 012200 | 0 | GeoXH 6000 | 08/19/2015 | 12:32:58pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595544.1 | 511590.7 | 66714 | 1.64041666667 | 12200 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:00pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595544.9 | 511591.9 | 66717 | 1.64041666667 | 11962 |
| 011664 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:00pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595545.6 | 511591.9 | 66718 | 1.64041666667 | 11664 |
| 012013 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:02pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595546.2 | 511593.2 | 66721 | 1.64041666667 | 12013 |
| 011730 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:02pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595548.3 | 511592.8 | 66722 | 1.64041666667 | 11730 |
| 012103 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595550.7 | 511592.7 | 66725 | 1.64041666667 | 12103 |
| 011330 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595552.0 | 511591.5 | 66726 | 1.64041666667 | 11330 |
| 011383 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:05pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595555.6 | 511591.7 | 66728 | 1.64041666667 | 11383 |
| 010858 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:06pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595557.6 | 511590.7 | 66730 | 1.64041666667 | 10858 |
| 012002 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:07pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595559.7 | 511591.5 | 66732 | 1.64041666667 | 12002 |
| 012054 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:08pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595561.7 | 511591.3 | 66734 | 1.64041666667 | 12054 |
| 012675 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:09pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595562.7 | 511590.9 | 66736 | 1.64041666667 | 12675 |
| 012597 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:10pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595564.4 | 511590.7 | 66738 | 1.64041666667 | 12597 |
| 013071 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:11pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595566.7 | 511589.5 | 66740 | 1.64041666667 | 13071 |
| 012812 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:12pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595568.8 | 511589.3 | 66742 | 1.64041666667 | 12812 |
| 013357 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:13pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595571.0 | 511588.3 | 66744 | 1.64041666667 | 13357 |
| 012815 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:14pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595574.0 | 511589.2 | 66746 | 1.64041666667 | 12815 |
| 012939 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595575.8 | 511588.5 | 66749 | 1.64041666667 | 12939 |
| 012175 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595577.5 | 511589.5 | 66750 | 1.64041666667 | 12175 |
| 012121 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:17pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595579.4 | 511589.1 | 66752 | 1.64041666667 | 12121 |
| 011565 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:18pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595581.2 | 511590.1 | 66754 | 1.64041666667 | 11565 |
| 014200 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:20pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595582.9 | 511589.6 | 66757 | 1.64041666667 | 14200 |
| 013470 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:20pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595584.0 | 511590.2 | 66758 | 1.64041666667 | 13470 |
| 012947 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:22pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595586.1 | 511589.5 | 66761 | 1.64041666667 | 12947 |
| 012412 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:22pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595587.8 | 511590.3 | 66762 | 1.64041666667 | 12412 |
| 012164 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:24pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595590.1 | 511589.5 | 66765 | 1.64041666667 | 12164 |
| 012445 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:24pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595591.7 | 511589.6 | 66766 | 1.64041666667 | 12445 |
| 012393 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595594.1 | 511589.1 | 66769 | 1.64041666667 | 12393 |
| 012446 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595595.8 | 511589.6 | 66770 | 1.64041666667 | 12446 |
| 011876 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:28pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595598.2 | 511589.4 | 66773 | 1.64041666667 | 11876 |
| 011787 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:28pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595600.0 | 511589.3 | 66774 | 1.64041666667 | 11787 |
| 011400 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:30pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595602.7 | 511588.9 | 66777 | 1.64041666667 | 11400 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:30pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595604.2 | 511588.0 | 66778 | 1.64041666667 | 12180 |
| 012558 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:32pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595606.6 | 511588.5 | 66781 | 1.64041666667 | 12558 |
| 012487 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:32pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595608.4 | 511588.6 | 66782 | 1.64041666667 | 12487 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:33pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595610.7 | 511588.9 | 66784 | 1.64041666667 | 12378 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012123 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:34pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595612.4 | 511589.9 | 66786 | 1.64041666667 | 12123 |
| 012129 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:35pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595614.7 | 511590.3 | 66788 | 1.64041666667 | 12129 |
| 011847 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:36pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595616.2 | 511591.6 | 66790 | 1.64041666667 | 11847 |
| 011674 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:37pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595618.6 | 511592.4 | 66792 | 1.64041666667 | 11674 |
| 011524 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:38pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595619.8 | 511593.6 | 66794 | 1.64041666667 | 11524 |
| 013045 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:39pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595621.7 | 511594.8 | 66796 | 1.64041666667 | 13045 |
| 012550 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:40pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595623.6 | 511595.7 | 66798 | 1.64041666667 | 12550 |
| 012084 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:41pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595625.3 | 511597.1 | 66800 | 1.64041666667 | 12084 |
| 012130 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:42pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595626.9 | 511598.0 | 66802 | 1.64041666667 | 12130 |
| 012755 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:43pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595628.4 | 511600.0 | 66804 | 1.64041666667 | 12755 |
| 011495 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:44pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595630.2 | 511600.9 | 66806 | 1.64041666667 | 11495 |
| 011618 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:45pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595631.2 | 511602.8 | 66808 | 1.64041666667 | 11618 |
| 011650 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:46pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595632.8 | 511603.3 | 66810 | 1.64041666667 | 11650 |
| 011848 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:48pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595633.9 | 511602.0 | 66813 | 1.64041666667 | 11848 |
| 011907 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:48pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595634.7 | 511600.7 | 66814 | 1.64041666667 | 11907 |
| 013462 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:49pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595634.5 | 511599.0 | 66816 | 1.64041666667 | 13462 |
| 013190 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:50pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595635.8 | 511598.1 | 66818 | 1.64041666667 | 13190 |
| 012842 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:52pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595636.9 | 511596.1 | 66821 | 1.64041666667 | 12842 |
| 012578 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:52pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595638.2 | 511595.2 | 66822 | 1.64041666667 | 12578 |
| 012595 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:53pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595639.4 | 511593.1 | 66824 | 1.64041666667 | 12595 |
| 012642 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:54pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595640.2 | 511591.6 | 66826 | 1.64041666667 | 12642 |
| 012586 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:56pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595640.3 | 511589.2 | 66829 | 1.64041666667 | 12586 |
| 012075 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:56pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595639.1 | 511588.6 | 66830 | 1.64041666667 | 12075 |
| 011989 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:57pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595638.0 | 511586.9 | 66832 | 1.64041666667 | 11989 |
| 011889 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:58pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595635.9 | 511586.4 | 66834 | 1.64041666667 | 11889 |
| 011885 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:59pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595634.2 | 511585.3 | 66836 | 1.64041666667 | 11885 |
| 011260 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:00pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595632.3 | 511585.0 | 66838 | 1.64041666667 | 11260 |
| 011501 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:01pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595629.8 | 511586.0 | 66840 | 1.64041666667 | 11501 |
| 011659 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:02pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595628.3 | 511585.4 | 66842 | 1.64041666667 | 11659 |
| 011741 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:03pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595626.8 | 511584.6 | 66844 | 1.64041666667 | 11741 |
| 011674 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:04pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595625.3 | 511583.5 | 66846 | 1.64041666667 | 11674 |
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:05pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595623.6 | 511581.7 | 66848 | 1.64041666667 | 12019 |
| 013226 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:06pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595621.8 | 511581.8 | 66850 | 1.64041666667 | 13226 |
| 013484 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:08pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595620.0 | 511580.5 | 66853 | 1.64041666667 | 13484 |
| 012797 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:08pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595618.4 | 511579.6 | 66854 | 1.64041666667 | 12797 |
| 012891 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:09pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595616.3 | 511579.7 | 66856 | 1.64041666667 | 12891 |
| 012763 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:10pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595615.0 | 511578.2 | 66858 | 1.64041666667 | 12763 |
| 011417 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:11pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595613.1 | 511577.8 | 66860 | 1.64041666667 | 11417 |
| 012294 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:12pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595611.6 | 511576.8 | 66862 | 1.64041666667 | 12294 |
| 012878 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:14pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595608.8 | 511576.2 | 66865 | 1.64041666667 | 12878 |
| 013259 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:14pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595607.2 | 511576.7 | 66866 | 1.64041666667 | 13259 |
| 013158 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:16pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595604.9 | 511576.2 | 66869 | 1.64041666667 | 13158 |
| 012981 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595603.6 | 511577.3 | 66870 | 1.64041666667 | 12981 |
| 012267 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:18pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595601.1 | 511577.2 | 66873 | 1.64041666667 | 12267 |
| 013290 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:18pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595599.1 | 511577.0 | 66874 | 1.64041666667 | 13290 |
| 012485 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:19pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595596.8 | 511577.6 | 66876 | 1.64041666667 | 12485 |
| 012491 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:20pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595595.2 | 511576.6 | 66878 | 1.64041666667 | 12491 |
| 011998 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:22pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595593.2 | 511576.7 | 66881 | 1.64041666667 | 11998 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012081 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:22pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595591.6 | 511576.2 | 66882 | 1.64041666667 | 12081 |
| 012631 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:23pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595591.1 | 511577.1 | 66884 | 1.64041666667 | 12631 |
| 012115 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:24pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595589.5 | 511577.5 | 66886 | 1.64041666667 | 12115 |
| 012297 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595587.6 | 511578.7 | 66889 | 1.64041666667 | 12297 |
| 011267 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595585.9 | 511578.7 | 66890 | 1.64041666667 | 11267 |
| 011490 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:27pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595584.5 | 511580.2 | 66892 | 1.64041666667 | 11490 |
| 011488 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:28pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595583.0 | 511579.9 | 66894 | 1.64041666667 | 11488 |
| 011434 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:29pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595581.2 | 511580.6 | 66896 | 1.64041666667 | 11434 |
| 011344 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:30pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595580.3 | 511579.5 | 66898 | 1.64041666667 | 11344 |
| 011706 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:31pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595578.5 | 511578.3 | 66900 | 1.64041666667 | 11706 |
| 011955 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:32pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595577.3 | 511577.1 | 66902 | 1.64041666667 | 11955 |
| 011787 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:33pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595575.1 | 511576.9 | 66904 | 1.64041666667 | 11787 |
| 012510 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:34pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595573.6 | 511577.0 | 66906 | 1.64041666667 | 12510 |
| 012204 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:35pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595572.3 | 511576.0 | 66908 | 1.64041666667 | 12204 |
| 012512 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:36pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595571.1 | 511574.5 | 66910 | 1.64041666667 | 12512 |
| 012528 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:37pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595570.9 | 511572.3 | 66912 | 1.64041666667 | 12528 |
| 012379 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:38pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595570.5 | 511570.6 | 66914 | 1.64041666667 | 12379 |
| 011891 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:39pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595570.6 | 511568.1 | 66916 | 1.64041666667 | 11891 |
| 011511 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:40pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595569.2 | 511567.5 | 66918 | 1.64041666667 | 11511 |
| 011035 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595567.7 | 511566.2 | 66921 | 1.64041666667 | 11035 |
| 010602 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595565.9 | 511566.8 | 66922 | 1.64041666667 | 10602 |
| 010613 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:44pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595563.6 | 511565.9 | 66925 | 1.64041666667 | 10613 |
| 010582 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:44pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595561.9 | 511566.3 | 66926 | 1.64041666667 | 10582 |
| 011405 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:45pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595560.0 | 511565.9 | 66928 | 1.64041666667 | 11405 |
| 011403 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:46pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595558.3 | 511565.9 | 66930 | 1.64041666667 | 11403 |
| 011431 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:48pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595556.8 | 511564.3 | 66933 | 1.64041666667 | 11431 |
| 011852 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:48pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595555.0 | 511563.6 | 66934 | 1.64041666667 | 11852 |
| 011909 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:49pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595554.0 | 511561.5 | 66936 | 1.64041666667 | 11909 |
| 011784 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:50pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595552.8 | 511561.5 | 66938 | 1.64041666667 | 11784 |
| 011586 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:51pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595551.6 | 511560.2 | 66940 | 1.64041666667 | 11586 |
| 011594 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:52pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595549.7 | 511560.0 | 66942 | 1.64041666667 | 11594 |
| 011644 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595547.8 | 511558.9 | 66945 | 1.64041666667 | 11644 |
| 011912 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595547.1 | 511557.8 | 66946 | 1.64041666667 | 11912 |
| 011223 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:55pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595546.2 | 511555.8 | 66948 | 1.64041666667 | 11223 |
| 011773 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595546.4 | 511553.8 | 66950 | 1.64041666667 | 11773 |
| 011955 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595545.7 | 511551.6 | 66953 | 1.64041666667 | 11955 |
| 011659 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595545.2 | 511549.3 | 66954 | 1.64041666667 | 11659 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:00pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595544.7 | 511547.6 | 66957 | 1.64041666667 | 12521 |
| 012503 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:00pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595544.1 | 511546.3 | 66958 | 1.64041666667 | 12503 |
| 011945 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:01pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595544.8 | 511544.5 | 66960 | 1.64041666667 | 11945 |
| 011609 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:02pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595545.2 | 511543.1 | 66962 | 1.64041666667 | 11609 |
| 011510 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:03pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595545.2 | 511540.9 | 66964 | 1.64041666667 | 11510 |
| 012077 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595544.9 | 511538.9 | 66966 | 1.64041666667 | 12077 |
| 011173 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:05pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595545.1 | 511536.8 | 66968 | 1.64041666667 | 11173 |
| 011070 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:06pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595545.1 | 511534.7 | 66970 | 1.64041666667 | 11070 |
| 011139 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:08pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595544.6 | 511532.2 | 66973 | 1.64041666667 | 11139 |
| 012318 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:08pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595544.1 | 511529.7 | 66974 | 1.64041666667 | 12318 |
| 011901 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:09pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595544.0 | 511527.3 | 66976 | 1.64041666667 | 11901 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011172 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:10pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595543.4 | 511525.6 | 66978 | 1.64041666667 | 11172 |
| 011714 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:11pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595542.4 | 511523.1 | 66980 | 1.64041666667 | 11714 |
| 011809 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:12pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595541.4 | 511521.2 | 66982 | 1.64041666667 | 11809 |
| 012080 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:13pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595540.1 | 511519.0 | 66984 | 1.64041666667 | 12080 |
| 012067 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:14pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595538.9 | 511517.5 | 66986 | 1.64041666667 | 12067 |
| 011730 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:16pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595538.5 | 511514.9 | 66989 | 1.64041666667 | 11730 |
| 011188 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:16pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595538.1 | 511512.8 | 66990 | 1.64041666667 | 11188 |
| 012391 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:18pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595537.7 | 511510.1 | 66993 | 1.64041666667 | 12391 |
| 012722 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:18pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595538.3 | 511508.4 | 66994 | 1.64041666667 | 12722 |
| 011446 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:19pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595539.0 | 511506.7 | 66996 | 1.64041666667 | 11446 |
| 011546 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:20pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595538.7 | 511505.7 | 66998 | 1.64041666667 | 11546 |
| 011864 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:21pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595538.7 | 511503.9 | 67000 | 1.64041666667 | 11864 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:22pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595538.8 | 511502.0 | 67002 | 1.64041666667 | 12021 |
| 011772 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:23pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595539.3 | 511500.4 | 67004 | 1.64041666667 | 11772 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:24pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595539.5 | 511498.4 | 67006 | 1.64041666667 | 11241 |
| 011746 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595540.0 | 511495.5 | 67009 | 1.64041666667 | 11746 |
| 011887 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:26pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595540.0 | 511492.6 | 67010 | 1.64041666667 | 11887 |
| 011719 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:28pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595539.4 | 511490.7 | 67013 | 1.64041666667 | 11719 |
| 011414 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:28pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595539.1 | 511489.8 | 67014 | 1.64041666667 | 11414 |
| 011835 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:29pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595539.4 | 511487.4 | 67016 | 1.64041666667 | 11835 |
| 011652 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:30pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595539.0 | 511484.9 | 67018 | 1.64041666667 | 11652 |
| 011797 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:31pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595539.3 | 511482.0 | 67020 | 1.64041666667 | 11797 |
| 011848 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:32pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595542.3 | 511481.5 | 67022 | 1.64041666667 | 11848 |
| 012649 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:33pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595544.8 | 511478.9 | 67024 | 1.64041666667 | 12649 |
| 012433 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:34pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595546.6 | 511477.7 | 67026 | 1.64041666667 | 12433 |
| 013293 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:35pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595549.1 | 511476.6 | 67028 | 1.64041666667 | 13293 |
| 012870 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:36pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595551.5 | 511476.6 | 67030 | 1.64041666667 | 12870 |
| 012452 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:37pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595554.2 | 511476.4 | 67032 | 1.64041666667 | 12452 |
| 011961 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:38pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595556.3 | 511476.2 | 67034 | 1.64041666667 | 11961 |
| 011483 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:39pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595559.2 | 511476.1 | 67036 | 1.64041666667 | 11483 |
| 011424 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:40pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595562.0 | 511476.0 | 67038 | 1.64041666667 | 11424 |
| 011961 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595565.1 | 511475.3 | 67041 | 1.64041666667 | 11961 |
| 012278 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595567.3 | 511474.9 | 67042 | 1.64041666667 | 12278 |
| 011819 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:43pm | Sensor | 1797-S0046-905-G-ACK | 6824.0 | 1595570.4 | 511475.4 | 67044 | 1.64041666667 | 11819 |
| 012505 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:44pm | Sensor | 1797-S0046-905-G-ACK | 6823.2 | 1595572.2 | 511474.9 | 67046 | 1.64041666667 | 12505 |
| 011857 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:46pm | Sensor | 1797-S0046-905-G-ACK | 6823.5 | 1595570.5 | 511475.8 | 67049 | 1.64041666667 | 11857 |
| 011387 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:46pm | Sensor | 1797-S0046-905-G-ACK | 6823.5 | 1595570.5 | 511475.8 | 67050 | 1.64041666667 | 11387 |
| 011310 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:48pm | Sensor | 1797-S0046-905-G-ACK | 6823.5 | 1595570.6 | 511475.9 | 67053 | 1.64041666667 | 11310 |
| 011507 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:48pm | Sensor | 1797-S0046-905-G-ACK | 6824.5 | 1595572.4 | 511476.3 | 67054 | 1.64041666667 | 11507 |
| 011925 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:50pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595572.4 | 511476.3 | 67057 | 1.64041666667 | 11925 |
| 011110 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:50pm | Sensor | 1797-S0046-905-G-ACK | 6823.7 | 1595571.0 | 511476.0 | 67058 | 1.64041666667 | 11110 |
| 011154 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:51pm | Sensor | 1797-S0046-905-G-ACK | 6824.1 | 1595570.6 | 511476.3 | 67060 | 1.64041666667 | 11154 |
| 011937 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:52pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595569.5 | 511476.8 | 67062 | 1.64041666667 | 11937 |
| 011589 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:53pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595569.5 | 511476.5 | 67064 | 1.64041666667 | 11589 |
| 012054 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595571.6 | 511476.6 | 67066 | 1.64041666667 | 12054 |
| 011512 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:55pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595574.7 | 511476.3 | 67068 | 1.64041666667 | 11512 |
| 011763 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595576.9 | 511476.2 | 67070 | 1.64041666667 | 11763 |
| 011582 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:57pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595579.7 | 511476.7 | 67072 | 1.64041666667 | 11582 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011607 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595582.4 | 511476.9 | 67074 | 1.64041666667 | 11607 |
| 012049 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:00pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595585.2 | 511476.6 | 67077 | 1.64041666667 | 12049 |
| 011862 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:00pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595587.3 | 511476.5 | 67078 | 1.64041666667 | 11862 |
| 012380 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:01pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595589.8 | 511475.7 | 67080 | 1.64041666667 | 12380 |
| 011996 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:02pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595592.8 | 511477.0 | 67082 | 1.64041666667 | 11996 |
| 012095 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:03pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595595.4 | 511476.5 | 67084 | 1.64041666667 | 12095 |
| 011836 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:04pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595597.8 | 511476.5 | 67086 | 1.64041666667 | 11836 |
| 011810 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:05pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595600.8 | 511477.0 | 67088 | 1.64041666667 | 11810 |
| 010970 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:06pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595603.0 | 511477.1 | 67090 | 1.64041666667 | 10970 |
| 010956 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:07pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595605.8 | 511477.6 | 67092 | 1.64041666667 | 10956 |
| 011180 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:08pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595608.0 | 511478.6 | 67094 | 1.64041666667 | 11180 |
| 011328 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:09pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595610.6 | 511479.2 | 67096 | 1.64041666667 | 11328 |
| 011922 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:10pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595612.6 | 511479.8 | 67098 | 1.64041666667 | 11922 |
| 011949 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:12pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595614.9 | 511481.6 | 67101 | 1.64041666667 | 11949 |
| 011618 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:12pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595617.6 | 511482.1 | 67102 | 1.64041666667 | 11618 |
| 011718 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:14pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595620.5 | 511481.4 | 67105 | 1.64041666667 | 11718 |
| 011488 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:14pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595622.2 | 511481.5 | 67106 | 1.64041666667 | 11488 |
| 011293 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:16pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595624.9 | 511481.5 | 67109 | 1.64041666667 | 11293 |
| 011684 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595627.0 | 511480.7 | 67110 | 1.64041666667 | 11684 |
| 011665 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:18pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595629.2 | 511482.6 | 67113 | 1.64041666667 | 11665 |
| 011616 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:18pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595630.9 | 511483.4 | 67114 | 1.64041666667 | 11616 |
| 011146 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:20pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595633.0 | 511484.6 | 67117 | 1.64041666667 | 11146 |
| 010680 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:20pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595633.5 | 511486.5 | 67118 | 1.64041666667 | 10680 |
| 011445 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:22pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595634.7 | 511489.0 | 67121 | 1.64041666667 | 11445 |
| 011110 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:22pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595635.9 | 511490.4 | 67122 | 1.64041666667 | 11110 |
| 011672 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:24pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595636.7 | 511493.2 | 67125 | 1.64041666667 | 11672 |
| 012138 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:24pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595637.4 | 511494.7 | 67126 | 1.64041666667 | 12138 |
| 012040 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:25pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595638.4 | 511497.2 | 67128 | 1.64041666667 | 12040 |
| 013057 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595637.9 | 511499.1 | 67130 | 1.64041666667 | 13057 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:27pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595638.9 | 511501.4 | 67132 | 1.64041666667 | 12760 |
| 012577 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:28pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595639.3 | 511503.4 | 67134 | 1.64041666667 | 12577 |
| 012467 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:29pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595640.4 | 511507.3 | 67136 | 1.64041666667 | 12467 |
| 011017 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:30pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595641.3 | 511508.9 | 67138 | 1.64041666667 | 11017 |
| 011777 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:31pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595641.6 | 511511.5 | 67140 | 1.64041666667 | 11777 |
| 010690 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:32pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595642.3 | 511513.8 | 67142 | 1.64041666667 | 10690 |
| 011285 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:34pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595644.0 | 511515.9 | 67145 | 1.64041666667 | 11285 |
| 010930 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:34pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595644.1 | 511516.7 | 67146 | 1.64041666667 | 10930 |
| 010648 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:35pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595646.4 | 511518.2 | 67148 | 1.64041666667 | 10648 |
| 010714 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:36pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595647.4 | 511518.2 | 67150 | 1.64041666667 | 10714 |
| 011262 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:37pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595648.9 | 511519.8 | 67152 | 1.64041666667 | 11262 |
| 011517 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:38pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595649.8 | 511521.1 | 67154 | 1.64041666667 | 11517 |
| 011578 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:40pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595651.6 | 511524.9 | 67157 | 1.64041666667 | 11578 |
| 011050 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:40pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595652.7 | 511526.1 | 67158 | 1.64041666667 | 11050 |
| 010805 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:41pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595654.1 | 511527.9 | 67160 | 1.64041666667 | 10805 |
| 010818 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595654.5 | 511528.5 | 67162 | 1.64041666667 | 10818 |
| 011193 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:43pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595657.2 | 511531.1 | 67164 | 1.64041666667 | 11193 |
| 012311 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:44pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595659.7 | 511532.2 | 67166 | 1.64041666667 | 12311 |
| 011867 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:45pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595661.0 | 511533.6 | 67168 | 1.64041666667 | 11867 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011895 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:46pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595662.8 | 511534.8 | 67170 | 1.64041666667 | 11895 |
| 011798 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:48pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595663.4 | 511535.6 | 67173 | 1.64041666667 | 11798 |
| 012081 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:48pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595664.8 | 511538.9 | 67174 | 1.64041666667 | 12081 |
| 012503 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:49pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595666.4 | 511540.7 | 67176 | 1.64041666667 | 12503 |
| 012575 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:50pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595666.9 | 511542.9 | 67178 | 1.64041666667 | 12575 |
| 011641 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:51pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595668.3 | 511545.5 | 67180 | 1.64041666667 | 11641 |
| 011565 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:52pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595669.0 | 511545.9 | 67182 | 1.64041666667 | 11565 |
| 012220 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:54pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595669.9 | 511548.0 | 67185 | 1.64041666667 | 12220 |
| 011794 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595671.8 | 511551.0 | 67186 | 1.64041666667 | 11794 |
| 012341 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595673.5 | 511553.0 | 67189 | 1.64041666667 | 12341 |
| 012102 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595673.4 | 511555.1 | 67190 | 1.64041666667 | 12102 |
| 011870 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595673.3 | 511557.7 | 67193 | 1.64041666667 | 11870 |
| 012384 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:58pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595673.3 | 511558.1 | 67194 | 1.64041666667 | 12384 |
| 012996 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:59pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595675.3 | 511562.4 | 67196 | 1.64041666667 | 12996 |
| 012522 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:00pm | Sensor | 1797-S0046-905-G-ACK | 6823.9 | 1595675.3 | 511563.0 | 67198 | 1.64041666667 | 12522 |
| 012549 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:01pm | Sensor | 1797-S0046-905-G-ACK | 6824.1 | 1595675.8 | 511563.0 | 67200 | 1.64041666667 | 12549 |
| 012338 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:02pm | Sensor | 1797-S0046-905-G-ACK | 6824.1 | 1595675.8 | 511563.1 | 67202 | 1.64041666667 | 12338 |
| 012115 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:03pm | Sensor | 1797-S0046-905-G-ACK | 6824.1 | 1595675.8 | 511563.1 | 67204 | 1.64041666667 | 12115 |
| 011502 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:04pm | Sensor | 1797-S0046-905-G-ACK | 6824.0 | 1595675.7 | 511563.1 | 67206 | 1.64041666667 | 11502 |
| 011540 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:05pm | Sensor | 1797-S0046-905-G-ACK | 6836.2 | 1595671.4 | 511563.8 | 67208 | 1.64041666667 | 11540 |
| 011928 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:06pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595674.8 | 511563.2 | 67210 | 1.64041666667 | 11928 |
| 011330 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:08pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595674.4 | 511561.8 | 67213 | 1.64041666667 | 11330 |
| 011435 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:08pm | Sensor | 1797-S0046-905-G-ACK | 6828.7 | 1595675.0 | 511562.0 | 67214 | 1.64041666667 | 11435 |
| 011615 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:10pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595675.1 | 511565.0 | 67217 | 1.64041666667 | 11615 |
| 011745 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:10pm | Sensor | 1797-S0046-905-G-ACK | 6829.4 | 1595674.7 | 511566.1 | 67218 | 1.64041666667 | 11745 |
| 012014 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:11pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595675.3 | 511568.6 | 67220 | 1.64041666667 | 12014 |
| 011235 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:12pm | Sensor | 1797-S0046-905-G-ACK | 6828.5 | 1595674.9 | 511570.8 | 67222 | 1.64041666667 | 11235 |
| 011180 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:13pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595675.0 | 511571.4 | 67224 | 1.64041666667 | 11180 |
| 011538 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:14pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595674.2 | 511572.9 | 67226 | 1.64041666667 | 11538 |
| 011253 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:15pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595672.1 | 511574.6 | 67228 | 1.64041666667 | 11253 |
| 011812 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:16pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595670.6 | 511576.2 | 67230 | 1.64041666667 | 11812 |
| 011392 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:17pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595669.3 | 511578.2 | 67232 | 1.64041666667 | 11392 |
| 012453 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:18pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595667.4 | 511578.6 | 67234 | 1.64041666667 | 12453 |
| 012067 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:19pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595665.6 | 511580.0 | 67236 | 1.64041666667 | 12067 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:20pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595663.6 | 511580.9 | 67238 | 1.64041666667 | 12045 |
| 012085 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:21pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595661.1 | 511581.4 | 67240 | 1.64041666667 | 12085 |
| 011643 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:22pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595659.6 | 511582.3 | 67242 | 1.64041666667 | 11643 |
| 012234 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:23pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595657.3 | 511582.6 | 67244 | 1.64041666667 | 12234 |
| 012146 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:24pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595655.9 | 511584.1 | 67246 | 1.64041666667 | 12146 |
| 011872 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:26pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595655.9 | 511586.6 | 67249 | 1.64041666667 | 11872 |
| 012700 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:26pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595654.6 | 511588.4 | 67250 | 1.64041666667 | 12700 |
| 012086 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:27pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595654.5 | 511590.8 | 67252 | 1.64041666667 | 12086 |
| 012671 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:28pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595654.9 | 511592.7 | 67254 | 1.64041666667 | 12671 |
| 013135 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:29pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595654.0 | 511594.9 | 67256 | 1.64041666667 | 13135 |
| 012376 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:30pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595654.1 | 511596.8 | 67258 | 1.64041666667 | 12376 |
| 012084 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:32pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595652.6 | 511598.3 | 67261 | 1.64041666667 | 12084 |
| 012317 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:32pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595651.5 | 511599.7 | 67262 | 1.64041666667 | 12317 |
| 012216 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:33pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595650.1 | 511602.0 | 67264 | 1.64041666667 | 12216 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012429 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:34pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595648.6 | 511603.3 | 67266 | 1.64041666667 | 12429 |
| 012638 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:35pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595647.1 | 511605.3 | 67268 | 1.64041666667 | 12638 |
| 012922 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:36pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595645.6 | 511606.5 | 67270 | 1.64041666667 | 12922 |
| 012128 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:37pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595643.5 | 511608.2 | 67272 | 1.64041666667 | 12128 |
| 012432 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:38pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595642.7 | 511610.2 | 67274 | 1.64041666667 | 12432 |
| 012925 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:39pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595641.2 | 511611.4 | 67276 | 1.64041666667 | 12925 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:40pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595639.6 | 511612.0 | 67278 | 1.64041666667 | 12760 |
| 012067 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:41pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595637.4 | 511612.8 | 67280 | 1.64041666667 | 12067 |
| 011588 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:42pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595634.7 | 511611.0 | 67282 | 1.64041666667 | 11588 |
| 011940 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:43pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595633.0 | 511611.7 | 67284 | 1.64041666667 | 11940 |
| 011944 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:44pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595632.8 | 511609.8 | 67286 | 1.64041666667 | 11944 |
| 011646 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:46pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595632.8 | 511606.2 | 67289 | 1.64041666667 | 11646 |
| 012656 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:46pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595631.7 | 511604.2 | 67290 | 1.64041666667 | 12656 |
| 011986 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:48pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595631.7 | 511601.4 | 67293 | 1.64041666667 | 11986 |
| 012097 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:48pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595631.0 | 511600.0 | 67294 | 1.64041666667 | 12097 |
| 011732 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:50pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595632.2 | 511598.2 | 67297 | 1.64041666667 | 11732 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:50pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595632.0 | 511596.4 | 67298 | 1.64041666667 | 12247 |
| 013248 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:51pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595632.7 | 511593.8 | 67300 | 1.64041666667 | 13248 |
| 013047 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:52pm | Sensor | 1797-S0046-905-G-ACK | 6827.6 | 1595632.7 | 511592.3 | 67302 | 1.64041666667 | 13047 |
| 013174 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:53pm | Sensor | 1797-S0046-905-G-ACK | 6827.4 | 1595632.7 | 511590.9 | 67304 | 1.64041666667 | 13174 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595631.5 | 511590.4 | 67306 | 1.64041666667 | 13297 |
| 013712 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:55pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595629.9 | 511589.0 | 67308 | 1.64041666667 | 13712 |
| 013241 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:56pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595630.2 | 511586.4 | 67310 | 1.64041666667 | 13241 |
| 012330 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:57pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595628.6 | 511584.5 | 67312 | 1.64041666667 | 12330 |
| 012508 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:58pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595627.3 | 511582.8 | 67314 | 1.64041666667 | 12508 |
| 011881 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:59pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595625.8 | 511581.0 | 67316 | 1.64041666667 | 11881 |
| 011760 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:00pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595624.1 | 511579.8 | 67318 | 1.64041666667 | 11760 |
| 011790 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:02pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595623.7 | 511577.4 | 67321 | 1.64041666667 | 11790 |
| 012062 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:02pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595622.5 | 511576.5 | 67322 | 1.64041666667 | 12062 |
| 012320 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595622.7 | 511574.7 | 67325 | 1.64041666667 | 12320 |
| 012802 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595623.2 | 511572.8 | 67326 | 1.64041666667 | 12802 |
| 012968 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:05pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595623.2 | 511570.7 | 67328 | 1.64041666667 | 12968 |
| 013055 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:06pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595624.6 | 511570.1 | 67330 | 1.64041666667 | 13055 |
| 013515 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:07pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595626.4 | 511568.9 | 67332 | 1.64041666667 | 13515 |
| 012530 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:08pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595628.0 | 511568.5 | 67334 | 1.64041666667 | 12530 |
| 011863 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:09pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595630.1 | 511567.6 | 67336 | 1.64041666667 | 11863 |
| 011810 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:10pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595631.8 | 511568.5 | 67338 | 1.64041666667 | 11810 |
| 012043 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:11pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595633.7 | 511568.7 | 67340 | 1.64041666667 | 12043 |
| 012174 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:12pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595635.0 | 511569.7 | 67342 | 1.64041666667 | 12174 |
| 012923 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:13pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595636.9 | 511570.8 | 67344 | 1.64041666667 | 12923 |
| 013239 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:14pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595638.3 | 511571.2 | 67346 | 1.64041666667 | 13239 |
| 013177 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:15pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595639.5 | 511573.4 | 67348 | 1.64041666667 | 13177 |
| 012969 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:16pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595641.3 | 511573.8 | 67350 | 1.64041666667 | 12969 |
| 012425 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:17pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595643.7 | 511574.2 | 67352 | 1.64041666667 | 12425 |
| 012854 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:18pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595645.8 | 511574.8 | 67354 | 1.64041666667 | 12854 |
| 012518 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:19pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595646.7 | 511577.1 | 67356 | 1.64041666667 | 12518 |
| 012381 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:20pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595647.8 | 511578.9 | 67358 | 1.64041666667 | 12381 |
| 012529 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:21pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595649.6 | 511579.1 | 67360 | 1.64041666667 | 12529 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012732 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:22pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595650.2 | 511580.6 | 67362 | 1.64041666667 | 12732 |
| 012899 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:23pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595650.9 | 511582.0 | 67364 | 1.64041666667 | 12899 |
| 011988 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:24pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595651.7 | 511582.1 | 67366 | 1.64041666667 | 11988 |
| 012646 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:25pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595650.4 | 511582.9 | 67368 | 1.64041666667 | 12646 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:26pm | Sensor | 1797-S0046-905-G-ACK | 6827.2 | 1595648.9 | 511583.8 | 67370 | 1.64041666667 | 12768 |
| 012499 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:27pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595647.0 | 511583.9 | 67372 | 1.64041666667 | 12499 |
| 012048 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:28pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595645.7 | 511584.9 | 67374 | 1.64041666667 | 12048 |
| 012679 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:29pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595644.1 | 511584.4 | 67376 | 1.64041666667 | 12679 |
| 012150 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:30pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595641.5 | 511585.3 | 67378 | 1.64041666667 | 12150 |
| 011986 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:31pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595639.6 | 511584.7 | 67380 | 1.64041666667 | 11986 |
| 011205 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:32pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595638.3 | 511583.6 | 67382 | 1.64041666667 | 11205 |
| 011612 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:33pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595636.6 | 511582.4 | 67384 | 1.64041666667 | 11612 |
| 012082 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:34pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595635.7 | 511580.8 | 67386 | 1.64041666667 | 12082 |
| 012256 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:36pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595634.0 | 511579.4 | 67389 | 1.64041666667 | 12256 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:36pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595634.0 | 511578.0 | 67390 | 1.64041666667 | 12106 |
| 013057 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:38pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595633.3 | 511576.0 | 67393 | 1.64041666667 | 13057 |
| 012977 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:38pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595634.3 | 511575.5 | 67394 | 1.64041666667 | 12977 |
| 012692 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:40pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595637.1 | 511573.0 | 67397 | 1.64041666667 | 12692 |
| 013282 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:40pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595638.0 | 511574.8 | 67398 | 1.64041666667 | 13282 |
| 012578 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:42pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595641.3 | 511572.5 | 67401 | 1.64041666667 | 12578 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:42pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595641.5 | 511572.4 | 67402 | 1.64041666667 | 12078 |
| 012478 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:43pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595643.2 | 511570.4 | 67404 | 1.64041666667 | 12478 |
| 012509 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:44pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595642.4 | 511568.8 | 67406 | 1.64041666667 | 12509 |
| 012646 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:45pm | Sensor | 1797-S0046-905-G-ACK | 6830.0 | 1595642.7 | 511566.0 | 67408 | 1.64041666667 | 12646 |
| 012618 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:46pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595642.7 | 511564.5 | 67410 | 1.64041666667 | 12618 |
| 012205 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:47pm | Sensor | 1797-S0046-905-G-ACK | 6828.4 | 1595642.1 | 511562.0 | 67412 | 1.64041666667 | 12205 |
| 011545 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:48pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595640.4 | 511560.5 | 67414 | 1.64041666667 | 11545 |
| 012082 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:49pm | Sensor | 1797-S0046-905-G-ACK | 6824.6 | 1595638.7 | 511559.5 | 67416 | 1.64041666667 | 12082 |
| 012143 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:50pm | Sensor | 1797-S0046-905-G-ACK | 6824.4 | 1595637.3 | 511558.5 | 67418 | 1.64041666667 | 12143 |
| 011540 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:51pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595636.3 | 511555.9 | 67420 | 1.64041666667 | 11540 |
| 011006 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:52pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595634.7 | 511555.1 | 67422 | 1.64041666667 | 11006 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:53pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595632.8 | 511553.4 | 67424 | 1.64041666667 | 12078 |
| 012419 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:54pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595631.0 | 511552.6 | 67426 | 1.64041666667 | 12419 |
| 012228 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595629.1 | 511551.2 | 67429 | 1.64041666667 | 12228 |
| 012706 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595627.3 | 511550.5 | 67430 | 1.64041666667 | 12706 |
| 012839 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:57pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595625.2 | 511550.4 | 67432 | 1.64041666667 | 12839 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595624.3 | 511549.0 | 67434 | 1.64041666667 | 11962 |
| 012023 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:59pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595622.8 | 511548.8 | 67436 | 1.64041666667 | 12023 |
| 011683 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:00pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595622.7 | 511548.4 | 67438 | 1.64041666667 | 11683 |
| 011469 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:01pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595622.6 | 511548.4 | 67440 | 1.64041666667 | 11469 |
| 012076 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:02pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595622.1 | 511548.2 | 67442 | 1.64041666667 | 12076 |
| 011578 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:03pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595620.2 | 511548.2 | 67444 | 1.64041666667 | 11578 |
| 011402 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:04pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595618.4 | 511548.5 | 67446 | 1.64041666667 | 11402 |
| 011814 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:05pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595616.7 | 511548.1 | 67448 | 1.64041666667 | 11814 |
| 011250 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:06pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595615.1 | 511547.3 | 67450 | 1.64041666667 | 11250 |
| 011405 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:07pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595614.3 | 511545.4 | 67452 | 1.64041666667 | 11405 |
| 011868 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:08pm | Sensor | 1797-S0046-905-G-ACK | 6825.9 | 1595612.9 | 511544.4 | 67454 | 1.64041666667 | 11868 |
| 011671 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:10pm | Sensor | 1797-S0046-905-G-ACK | 6823.3 | 1595613.5 | 511544.2 | 67457 | 1.64041666667 | 11671 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011132 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:10pm | Sensor | 1797-S0046-905-G-ACK | 6823.2 | 1595612.7 | 511542.9 | 67458 | 1.64041666667 | 11132 |
| 011189 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:11pm | Sensor | 1797-S0046-905-G-ACK | 6822.9 | 1595612.3 | 511540.9 | 67460 | 1.64041666667 | 11189 |
| 011881 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:12pm | Sensor | 1797-S0046-905-G-ACK | 6822.9 | 1595612.7 | 511539.8 | 67462 | 1.64041666667 | 11881 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:13pm | Sensor | 1797-S0046-905-G-ACK | 6822.9 | 1595614.0 | 511538.2 | 67464 | 1.64041666667 | 12405 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:14pm | Sensor | 1797-S0046-905-G-ACK | 6822.8 | 1595615.8 | 511537.1 | 67466 | 1.64041666667 | 12678 |
| 012756 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:15pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595616.1 | 511533.6 | 67468 | 1.64041666667 | 12756 |
| 011930 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:16pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595616.9 | 511532.5 | 67470 | 1.64041666667 | 11930 |
| 011323 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:17pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595617.5 | 511531.0 | 67472 | 1.64041666667 | 11323 |
| 011109 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:18pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595618.5 | 511530.2 | 67474 | 1.64041666667 | 11109 |
| 010569 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:19pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595619.8 | 511528.6 | 67476 | 1.64041666667 | 10569 |
| 011225 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:20pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595620.1 | 511527.5 | 67478 | 1.64041666667 | 11225 |
| 010739 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:21pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595621.5 | 511526.8 | 67480 | 1.64041666667 | 10739 |
| 011815 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:22pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595622.3 | 511527.2 | 67482 | 1.64041666667 | 11815 |
| 011041 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:23pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595623.8 | 511528.0 | 67484 | 1.64041666667 | 11041 |
| 011303 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:24pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595624.6 | 511528.7 | 67486 | 1.64041666667 | 11303 |
| 011870 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:25pm | Sensor | 1797-S0046-905-G-ACK | 6822.8 | 1595627.4 | 511530.5 | 67488 | 1.64041666667 | 11870 |
| 011282 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:26pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595627.2 | 511530.4 | 67490 | 1.64041666667 | 11282 |
| 011761 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:27pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595628.6 | 511530.4 | 67492 | 1.64041666667 | 11761 |
| 011183 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:28pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595630.4 | 511530.3 | 67494 | 1.64041666667 | 11183 |
| 011293 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:29pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595631.2 | 511531.2 | 67496 | 1.64041666667 | 11293 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:30pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595631.8 | 511532.0 | 67498 | 1.64041666667 | 12442 |
| 011588 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:31pm | Sensor | 1797-S0046-905-G-ACK | 6823.6 | 1595632.1 | 511536.0 | 67500 | 1.64041666667 | 11588 |
| 011536 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:32pm | Sensor | 1797-S0046-905-G-ACK | 6822.8 | 1595633.2 | 511538.2 | 67502 | 1.64041666667 | 11536 |
| 011641 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:33pm | Sensor | 1797-S0046-905-G-ACK | 6823.9 | 1595634.5 | 511538.6 | 67504 | 1.64041666667 | 11641 |
| 011445 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:34pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595635.2 | 511538.6 | 67506 | 1.64041666667 | 11445 |
| 010811 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:35pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595637.3 | 511539.1 | 67508 | 1.64041666667 | 10811 |
| 011376 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:36pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595638.3 | 511540.5 | 67510 | 1.64041666667 | 11376 |
| 011289 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:37pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595640.2 | 511541.4 | 67512 | 1.64041666667 | 11289 |
| 011210 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:38pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595641.5 | 511542.8 | 67514 | 1.64041666667 | 11210 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:39pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595642.6 | 511544.9 | 67516 | 1.64041666667 | 12133 |
| 013102 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:40pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595643.7 | 511546.2 | 67518 | 1.64041666667 | 13102 |
| 012297 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:41pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595644.4 | 511547.9 | 67520 | 1.64041666667 | 12297 |
| 012362 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:42pm | Sensor | 1797-S0046-905-G-ACK | 6823.9 | 1595646.6 | 511550.0 | 67522 | 1.64041666667 | 12362 |
| 012091 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:43pm | Sensor | 1797-S0046-905-G-ACK | 6823.4 | 1595647.1 | 511552.6 | 67524 | 1.64041666667 | 12091 |
| 011798 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:44pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595646.2 | 511552.9 | 67526 | 1.64041666667 | 11798 |
| 011660 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:45pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595646.4 | 511554.5 | 67528 | 1.64041666667 | 11660 |
| 011268 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:46pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595646.2 | 511556.1 | 67530 | 1.64041666667 | 11268 |
| 011138 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:47pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595646.2 | 511558.1 | 67532 | 1.64041666667 | 11138 |
| 012310 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:48pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595645.5 | 511559.5 | 67534 | 1.64041666667 | 12310 |
| 012257 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:49pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595644.3 | 511560.9 | 67536 | 1.64041666667 | 12257 |
| 012032 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:50pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595642.9 | 511561.5 | 67538 | 1.64041666667 | 12032 |
| 011545 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:51pm | Sensor | 1797-S0046-905-G-ACK | 6826.8 | 1595641.6 | 511562.7 | 67540 | 1.64041666667 | 11545 |
| 012052 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:52pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595640.1 | 511562.8 | 67542 | 1.64041666667 | 12052 |
| 012164 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:53pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595638.4 | 511563.8 | 67544 | 1.64041666667 | 12164 |
| 011889 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:54pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595636.7 | 511564.4 | 67546 | 1.64041666667 | 11889 |
| 012605 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:56pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595634.5 | 511564.7 | 67549 | 1.64041666667 | 12605 |
| 012235 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:56pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595633.2 | 511565.7 | 67550 | 1.64041666667 | 12235 |
| 011922 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:58pm | Sensor | 1797-S0046-905-G-ACK | 6827.0 | 1595631.6 | 511565.5 | 67553 | 1.64041666667 | 11922 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011918 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:58pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595630.0 | 511566.4 | 67554 | 1.64041666667 | 11918 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:59pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595628.0 | 511565.8 | 67556 | 1.64041666667 | 12539 |
| 013233 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:00pm | Sensor | 1797-S0046-905-G-ACK | 6826.9 | 1595626.4 | 511566.3 | 67558 | 1.64041666667 | 13233 |
| 012963 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:01pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595624.2 | 511566.3 | 67560 | 1.64041666667 | 12963 |
| 012753 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:02pm | Sensor | 1797-S0046-905-G-ACK | 6826.6 | 1595621.8 | 511566.1 | 67562 | 1.64041666667 | 12753 |
| 011760 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:03pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595619.6 | 511567.1 | 67564 | 1.64041666667 | 11760 |
| 012315 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:04pm | Sensor | 1797-S0046-905-G-ACK | 6826.5 | 1595617.6 | 511567.1 | 67566 | 1.64041666667 | 12315 |
| 011644 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:05pm | Sensor | 1797-S0046-905-G-ACK | 6826.7 | 1595615.2 | 511566.0 | 67568 | 1.64041666667 | 11644 |
| 011035 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:06pm | Sensor | 1797-S0046-905-G-ACK | 6823.2 | 1595614.8 | 511567.1 | 67570 | 1.64041666667 | 11035 |
| 011059 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:07pm | Sensor | 1797-S0046-905-G-ACK | 6822.3 | 1595613.8 | 511565.5 | 67572 | 1.64041666667 | 11059 |
| 011006 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:08pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595612.1 | 511563.2 | 67574 | 1.64041666667 | 11006 |
| 011973 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:09pm | Sensor | 1797-S0046-905-G-ACK | 6822.2 | 1595610.0 | 511562.8 | 67576 | 1.64041666667 | 11973 |
| 011122 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:10pm | Sensor | 1797-S0046-905-G-ACK | 6822.0 | 1595609.2 | 511561.4 | 67578 | 1.64041666667 | 11122 |
| 011986 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:11pm | Sensor | 1797-S0046-905-G-ACK | 6822.0 | 1595607.3 | 511560.7 | 67580 | 1.64041666667 | 11986 |
| 011205 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:12pm | Sensor | 1797-S0046-905-G-ACK | 6821.9 | 1595606.5 | 511559.4 | 67582 | 1.64041666667 | 11205 |
| 010930 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:13pm | Sensor | 1797-S0046-905-G-ACK | 6821.6 | 1595605.2 | 511558.7 | 67584 | 1.64041666667 | 10930 |
| 010970 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:14pm | Sensor | 1797-S0046-905-G-ACK | 6821.7 | 1595604.6 | 511558.1 | 67586 | 1.64041666667 | 10970 |
| 011443 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:15pm | Sensor | 1797-S0046-905-G-ACK | 6821.7 | 1595603.3 | 511558.8 | 67588 | 1.64041666667 | 11443 |
| 011462 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:16pm | Sensor | 1797-S0046-905-G-ACK | 6821.6 | 1595601.5 | 511559.8 | 67590 | 1.64041666667 | 11462 |
| 011105 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:17pm | Sensor | 1797-S0046-905-G-ACK | 6821.5 | 1595599.6 | 511559.8 | 67592 | 1.64041666667 | 11105 |
| 011091 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:18pm | Sensor | 1797-S0046-905-G-ACK | 6821.6 | 1595597.7 | 511560.0 | 67594 | 1.64041666667 | 11091 |
| 011361 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:19pm | Sensor | 1797-S0046-905-G-ACK | 6821.4 | 1595596.2 | 511559.0 | 67596 | 1.64041666667 | 11361 |
| 011138 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:20pm | Sensor | 1797-S0046-905-G-ACK | 6821.4 | 1595595.0 | 511559.8 | 67598 | 1.64041666667 | 11138 |
| 011988 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:22pm | Sensor | 1797-S0046-905-G-ACK | 6821.4 | 1595594.7 | 511559.0 | 67601 | 1.64041666667 | 11988 |
| 011933 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:22pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595592.7 | 511556.5 | 67602 | 1.64041666667 | 11933 |
| 011842 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:23pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595591.1 | 511555.2 | 67604 | 1.64041666667 | 11842 |
| 012323 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:24pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595591.2 | 511554.6 | 67606 | 1.64041666667 | 12323 |
| 011754 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595590.5 | 511552.0 | 67609 | 1.64041666667 | 11754 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:26pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595591.4 | 511551.2 | 67610 | 1.64041666667 | 11959 |
| 011572 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:27pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595592.0 | 511549.7 | 67612 | 1.64041666667 | 11572 |
| 011384 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:28pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595593.2 | 511548.4 | 67614 | 1.64041666667 | 11384 |
| 011976 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:30pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595592.3 | 511546.9 | 67617 | 1.64041666667 | 11976 |
| 011401 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:30pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595592.2 | 511545.9 | 67618 | 1.64041666667 | 11401 |
| 011333 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:32pm | Sensor | 1797-S0046-905-G-ACK | 6825.8 | 1595591.0 | 511544.5 | 67621 | 1.64041666667 | 11333 |
| 010710 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:32pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595592.0 | 511543.0 | 67622 | 1.64041666667 | 10710 |
| 010742 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:34pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595591.3 | 511540.5 | 67625 | 1.64041666667 | 10742 |
| 010894 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:35pm | Sensor | 1797-S0046-905-G-ACK | 6825.6 | 1595590.6 | 511539.6 | 67627 | 1.64041666667 | 10894 |
| 011273 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:35pm | Sensor | 1797-S0046-905-G-ACK | 6825.5 | 1595590.0 | 511538.8 | 67628 | 1.64041666667 | 11273 |
| 011771 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:36pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595588.4 | 511538.2 | 67630 | 1.64041666667 | 11771 |
| 012306 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:37pm | Sensor | 1797-S0046-905-G-ACK | 6825.2 | 1595586.6 | 511537.1 | 67632 | 1.64041666667 | 12306 |
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:38pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595585.1 | 511538.2 | 67634 | 1.64041666667 | 12562 |
| 012053 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:39pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595583.2 | 511537.9 | 67636 | 1.64041666667 | 12053 |
| 012300 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:40pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595582.1 | 511538.8 | 67638 | 1.64041666667 | 12300 |
| 012318 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:41pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595579.9 | 511538.2 | 67640 | 1.64041666667 | 12318 |
| 012007 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:42pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595577.8 | 511537.9 | 67642 | 1.64041666667 | 12007 |
| 011831 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:43pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595576.1 | 511537.2 | 67644 | 1.64041666667 | 11831 |
| 013120 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:44pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595574.5 | 511537.1 | 67646 | 1.64041666667 | 13120 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:45pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595574.3 | 511538.0 | 67648 | 1.64041666667 | 12442 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011896 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:46pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595574.0 | 511537.3 | 67650 | 1.64041666667 | 11896 |
| 011206 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:47pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595572.4 | 511537.2 | 67652 | 1.64041666667 | 11206 |
| 011103 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:48pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595571.4 | 511535.8 | 67654 | 1.64041666667 | 11103 |
| 011968 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:49pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595569.9 | 511535.8 | 67656 | 1.64041666667 | 11968 |
| 011134 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:50pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595568.3 | 511535.3 | 67658 | 1.64041666667 | 11134 |
| 011678 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:51pm | Sensor | 1797-S0046-905-G-ACK | 6825.0 | 1595566.3 | 511535.8 | 67660 | 1.64041666667 | 11678 |
| 011916 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:52pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595565.5 | 511537.7 | 67662 | 1.64041666667 | 11916 |
| 012110 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:53pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595565.7 | 511540.0 | 67664 | 1.64041666667 | 12110 |
| 012662 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:54pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595566.5 | 511541.7 | 67666 | 1.64041666667 | 12662 |
| 012470 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:55pm | Sensor | 1797-S0046-905-G-ACK | 6824.0 | 1595566.4 | 511544.3 | 67668 | 1.64041666667 | 12470 |
| 012699 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:56pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595567.2 | 511546.1 | 67670 | 1.64041666667 | 12699 |
| 012356 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:57pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595569.1 | 511546.9 | 67672 | 1.64041666667 | 12356 |
| 011742 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:58pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595570.1 | 511547.9 | 67674 | 1.64041666667 | 11742 |
| 011585 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:59pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595571.1 | 511548.3 | 67676 | 1.64041666667 | 11585 |
| 011631 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:00pm | Sensor | 1797-S0046-905-G-ACK | 6824.5 | 1595570.4 | 511547.9 | 67678 | 1.64041666667 | 11631 |
| 011433 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:01pm | Sensor | 1797-S0046-905-G-ACK | 6824.4 | 1595569.1 | 511547.2 | 67680 | 1.64041666667 | 11433 |
| 010826 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:02pm | Sensor | 1797-S0046-905-G-ACK | 6824.6 | 1595567.3 | 511546.3 | 67682 | 1.64041666667 | 10826 |
| 011692 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:03pm | Sensor | 1797-S0046-905-G-ACK | 6824.8 | 1595567.0 | 511544.5 | 67684 | 1.64041666667 | 11692 |
| 011437 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:04pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595566.4 | 511543.1 | 67686 | 1.64041666667 | 11437 |
| 012328 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:05pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595566.1 | 511541.1 | 67688 | 1.64041666667 | 12328 |
| 011667 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:06pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595564.5 | 511540.0 | 67690 | 1.64041666667 | 11667 |
| 011595 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:08pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595563.1 | 511538.2 | 67693 | 1.64041666667 | 11595 |
| 011112 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:08pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595561.8 | 511536.2 | 67694 | 1.64041666667 | 11112 |
| 011628 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:09pm | Sensor | 1797-S0046-905-G-ACK | 6824.4 | 1595559.7 | 511534.7 | 67696 | 1.64041666667 | 11628 |
| 010980 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:10pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595558.6 | 511533.5 | 67698 | 1.64041666667 | 10980 |
| 011599 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:11pm | Sensor | 1797-S0046-905-G-ACK | 6824.4 | 1595556.7 | 511533.0 | 67700 | 1.64041666667 | 11599 |
| 011054 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:12pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595554.8 | 511532.9 | 67702 | 1.64041666667 | 11054 |
| 010800 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:13pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595553.3 | 511534.2 | 67704 | 1.64041666667 | 10800 |
| 011662 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:14pm | Sensor | 1797-S0046-905-G-ACK | 6824.2 | 1595552.0 | 511535.0 | 67706 | 1.64041666667 | 11662 |
| 011090 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:16pm | Sensor | 1797-S0046-905-G-ACK | 6824.7 | 1595549.6 | 511536.9 | 67709 | 1.64041666667 | 11090 |
| 011600 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:16pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595548.1 | 511538.1 | 67710 | 1.64041666667 | 11600 |
| 011618 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:17pm | Sensor | 1797-S0046-905-G-ACK | 6825.1 | 1595545.8 | 511538.8 | 67712 | 1.64041666667 | 11618 |
| 011845 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:18pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595544.1 | 511540.4 | 67714 | 1.64041666667 | 11845 |
| 013045 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:19pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595543.6 | 511542.2 | 67716 | 1.64041666667 | 13045 |
| 012250 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:20pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595543.6 | 511544.4 | 67718 | 1.64041666667 | 12250 |
| 011533 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:21pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595544.4 | 511547.1 | 67720 | 1.64041666667 | 11533 |
| 011685 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:22pm | Sensor | 1797-S0046-905-G-ACK | 6822.4 | 1595546.6 | 511551.2 | 67722 | 1.64041666667 | 11685 |
| 011260 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:23pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595545.1 | 511552.5 | 67724 | 1.64041666667 | 11260 |
| 011298 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:24pm | Sensor | 1797-S0046-905-G-ACK | 6822.5 | 1595546.8 | 511556.8 | 67726 | 1.64041666667 | 11298 |
| 012430 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:26pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595546.0 | 511558.4 | 67729 | 1.64041666667 | 12430 |
| 012024 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:26pm | Sensor | 1797-S0046-905-G-ACK | 6826.2 | 1595545.3 | 511560.2 | 67730 | 1.64041666667 | 12024 |
| 011534 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:27pm | Sensor | 1797-S0046-905-G-ACK | 6826.4 | 1595543.4 | 511561.7 | 67732 | 1.64041666667 | 11534 |
| 011895 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:28pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595542.7 | 511564.0 | 67734 | 1.64041666667 | 11895 |
| 012293 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:30pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595542.1 | 511566.9 | 67737 | 1.64041666667 | 12293 |
| 012097 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:30pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595542.2 | 511569.2 | 67738 | 1.64041666667 | 12097 |
| 012730 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:31pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595542.6 | 511572.2 | 67740 | 1.64041666667 | 12730 |
| 012365 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:32pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595542.7 | 511574.8 | 67742 | 1.64041666667 | 12365 |
| 012333 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:33pm | Sensor | 1797-S0046-905-G-ACK | 6827.7 | 1595542.8 | 511577.9 | 67744 | 1.64041666667 | 12333 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012120 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:34pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595542.1 | 511579.8 | 67746 | 1.64041666667 | 12120 |
| 013410 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:36pm | Sensor | 1797-S0046-905-G-ACK | 6827.9 | 1595541.3 | 511582.2 | 67749 | 1.64041666667 | 13410 |
| 012613 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:36pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595541.0 | 511584.2 | 67750 | 1.64041666667 | 12613 |
| 012810 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:37pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595540.0 | 511586.7 | 67752 | 1.64041666667 | 12810 |
| 012635 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:38pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595539.6 | 511588.9 | 67754 | 1.64041666667 | 12635 |
| 013669 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:39pm | Sensor | 1797-S0046-905-G-ACK | 6828.4 | 1595539.5 | 511591.1 | 67756 | 1.64041666667 | 13669 |
| 013861 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:40pm | Sensor | 1797-S0046-905-G-ACK | 6828.2 | 1595538.9 | 511592.9 | 67758 | 1.64041666667 | 13861 |
| 012574 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:41pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595537.8 | 511595.0 | 67760 | 1.64041666667 | 12574 |
| 012413 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:42pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595537.8 | 511597.3 | 67762 | 1.64041666667 | 12413 |
| 012142 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:43pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595537.7 | 511599.9 | 67764 | 1.64041666667 | 12142 |
| 013572 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:44pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595537.1 | 511602.7 | 67766 | 1.64041666667 | 13572 |
| 013357 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:45pm | Sensor | 1797-S0046-905-G-ACK | 6828.5 | 1595536.6 | 511606.0 | 67768 | 1.64041666667 | 13357 |
| 012621 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:46pm | Sensor | 1797-S0046-905-G-ACK | 6828.9 | 1595536.5 | 511608.1 | 67770 | 1.64041666667 | 12621 |
| 012709 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:47pm | Sensor | 1797-S0046-905-G-ACK | 6828.9 | 1595535.9 | 511611.0 | 67772 | 1.64041666667 | 12709 |
| 012376 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:48pm | Sensor | 1797-S0046-905-G-ACK | 6828.9 | 1595535.4 | 511613.4 | 67774 | 1.64041666667 | 12376 |
| 012376 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:49pm | Sensor | 1797-S0046-905-G-ACK | 6828.8 | 1595534.9 | 511616.7 | 67776 | 1.64041666667 | 12376 |
| 013472 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:50pm | Sensor | 1797-S0046-905-G-ACK | 6828.9 | 1595534.4 | 511618.9 | 67778 | 1.64041666667 | 13472 |
| 013510 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:51pm | Sensor | 1797-S0046-905-G-ACK | 6828.7 | 1595533.6 | 511622.0 | 67780 | 1.64041666667 | 13510 |
| 013442 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:52pm | Sensor | 1797-S0046-905-G-ACK | 6828.9 | 1595532.4 | 511624.3 | 67782 | 1.64041666667 | 13442 |
| 013261 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:53pm | Sensor | 1797-S0046-905-G-ACK | 6829.2 | 1595531.2 | 511627.1 | 67784 | 1.64041666667 | 13261 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:54pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595530.6 | 511629.2 | 67786 | 1.64041666667 | 13811 |
| 012936 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:55pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595529.1 | 511631.9 | 67788 | 1.64041666667 | 12936 |
| 013254 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:56pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595528.8 | 511633.9 | 67790 | 1.64041666667 | 13254 |
| 012480 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:57pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595529.2 | 511636.6 | 67792 | 1.64041666667 | 12480 |
| 012952 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:58pm | Sensor | 1797-S0046-905-G-ACK | 6829.7 | 1595529.1 | 511638.9 | 67794 | 1.64041666667 | 12952 |
| 013391 | 0 | GeoXH 6000 | 08/19/2015 | 12:41:59pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595528.6 | 511641.4 | 67796 | 1.64041666667 | 13391 |
| 013195 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:00pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595528.2 | 511643.8 | 67798 | 1.64041666667 | 13195 |
| 013264 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:01pm | Sensor | 1797-S0046-905-G-ACK | 6829.4 | 1595527.2 | 511646.8 | 67800 | 1.64041666667 | 13264 |
| 013319 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:02pm | Sensor | 1797-S0046-905-G-ACK | 6829.5 | 1595526.3 | 511649.2 | 67802 | 1.64041666667 | 13319 |
| 013357 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:03pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595525.3 | 511651.9 | 67804 | 1.64041666667 | 13357 |
| 013993 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:04pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595524.4 | 511654.0 | 67806 | 1.64041666667 | 13993 |
| 014291 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:05pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595522.7 | 511656.6 | 67808 | 1.64041666667 | 14291 |
| 013341 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:06pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595521.0 | 511658.9 | 67810 | 1.64041666667 | 13341 |
| 014119 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:07pm | Sensor | 1797-S0046-905-G-ACK | 6829.6 | 1595519.5 | 511661.4 | 67812 | 1.64041666667 | 14119 |
| 014129 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:08pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595518.3 | 511663.8 | 67814 | 1.64041666667 | 14129 |
| 014368 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:09pm | Sensor | 1797-S0046-905-G-ACK | 6829.8 | 1595517.0 | 511666.4 | 67816 | 1.64041666667 | 14368 |
| 014074 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:10pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595516.2 | 511668.9 | 67818 | 1.64041666667 | 14074 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:11pm | Sensor | 1797-S0046-905-G-ACK | 6829.0 | 1595516.5 | 511671.3 | 67820 | 1.64041666667 | 13931 |
| 014031 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:12pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595515.4 | 511674.0 | 67822 | 1.64041666667 | 14031 |
| 014148 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:13pm | Sensor | 1797-S0046-905-G-ACK | 6830.2 | 1595514.2 | 511676.8 | 67824 | 1.64041666667 | 14148 |
| 013958 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:14pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595514.5 | 511679.1 | 67826 | 1.64041666667 | 13958 |
| 013071 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:15pm | Sensor | 1797-S0046-905-G-ACK | 6829.9 | 1595514.8 | 511681.9 | 67828 | 1.64041666667 | 13071 |
| 013360 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:16pm | Sensor | 1797-S0046-905-G-ACK | 6822.8 | 1595517.8 | 511684.0 | 67830 | 1.64041666667 | 13360 |
| 014977 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:17pm | Sensor | 1797-S0046-905-G-ACK | 6823.7 | 1595517.0 | 511689.7 | 67832 | 1.64041666667 | 14977 |
| 015077 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:18pm | Sensor | 1797-S0046-905-G-ACK | 6823.9 | 1595516.8 | 511692.2 | 67834 | 1.64041666667 | 15077 |
| 015156 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:19pm | Sensor | 1797-S0046-905-G-ACK | 6824.9 | 1595515.9 | 511692.5 | 67836 | 1.64041666667 | 15156 |
| 014757 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:20pm | Sensor | 1797-S0046-905-G-ACK | 6828.6 | 1595513.2 | 511695.3 | 67838 | 1.64041666667 | 14757 |
| 013206 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:21pm | Sensor | 1797-S0046-905-G-ACK | 6828.3 | 1595512.6 | 511698.2 | 67840 | 1.64041666667 | 13206 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013751 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:22pm | Sensor | 1797-S0046-905-G-ACK | 6827.1 | 1595512.8 | 511700.7 | 67842 | 1.64041666667 | 13751 |
| 013840 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:23pm | Sensor | 1797-S0046-905-G-ACK | 6828.7 | 1595511.1 | 511703.9 | 67844 | 1.64041666667 | 13840 |
| 014407 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:24pm | Sensor | 1797-S0046-905-G-ACK | 6828.1 | 1595510.3 | 511706.1 | 67846 | 1.64041666667 | 14407 |
| 014276 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:25pm | Sensor | 1797-S0046-905-G-ACK | 6827.8 | 1595509.8 | 511708.7 | 67848 | 1.64041666667 | 14276 |
| 015523 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:26pm | Sensor | 1797-S0046-905-G-ACK | 6827.5 | 1595510.2 | 511711.0 | 67850 | 1.64041666667 | 15523 |
| 016186 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:27pm | Sensor | 1797-S0046-905-G-ACK | 6827.3 | 1595510.1 | 511713.8 | 67852 | 1.64041666667 | 16186 |
| 015090 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:28pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595510.3 | 511716.2 | 67854 | 1.64041666667 | 15090 |
| 014990 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:29pm | Sensor | 1797-S0046-905-G-ACK | 6823.6 | 1595511.0 | 511721.3 | 67856 | 1.64041666667 | 14990 |
| 014312 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:30pm | Sensor | 1797-S0046-905-G-ACK | 6828.0 | 1595508.3 | 511721.8 | 67858 | 1.64041666667 | 14312 |
| 014095 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:31pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595508.7 | 511726.1 | 67860 | 1.64041666667 | 14095 |
| 013643 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:32pm | Sensor | 1797-S0046-905-G-ACK | 6824.4 | 1595508.8 | 511725.3 | 67862 | 1.64041666667 | 13643 |
| 014147 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:33pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595508.3 | 511727.4 | 67864 | 1.64041666667 | 14147 |
| 013672 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:34pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595507.9 | 511730.1 | 67866 | 1.64041666667 | 13672 |
| 014036 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:35pm | Sensor | 1797-S0046-905-G-ACK | 6824.6 | 1595507.5 | 511732.9 | 67868 | 1.64041666667 | 14036 |
| 013647 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:36pm | Sensor | 1797-S0046-905-G-ACK | 6823.7 | 1595507.7 | 511735.5 | 67870 | 1.64041666667 | 13647 |
| 012596 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:37pm | Sensor | 1797-S0046-905-G-ACK | 6824.5 | 1595507.2 | 511738.9 | 67872 | 1.64041666667 | 12596 |
| 012845 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:38pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595506.4 | 511741.5 | 67874 | 1.64041666667 | 12845 |
| 013443 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:39pm | Sensor | 1797-S0046-905-G-ACK | 6824.0 | 1595505.0 | 511744.6 | 67876 | 1.64041666667 | 13443 |
| 013839 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:40pm | Sensor | 1797-S0046-905-G-ACK | 6823.0 | 1595504.4 | 511747.7 | 67878 | 1.64041666667 | 13839 |
| 015322 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:41pm | Sensor | 1797-S0046-905-G-ACK | 6824.3 | 1595503.2 | 511750.9 | 67880 | 1.64041666667 | 15322 |
| 014513 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:42pm | Sensor | 1797-S0046-905-G-ACK | 6823.7 | 1595503.1 | 511755.7 | 67882 | 1.64041666667 | 14513 |
| 014088 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:43pm | Sensor | 1797-S0046-905-G-ACK | 6823.3 | 1595502.7 | 511759.2 | 67884 | 1.64041666667 | 14088 |
| 014255 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:44pm | Sensor | 1797-S0046-905-G-ACK | 6823.4 | 1595502.2 | 511761.8 | 67886 | 1.64041666667 | 14255 |
| 014956 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:45pm | Sensor | 1797-S0046-905-G-ACK | 6823.4 | 1595502.6 | 511762.4 | 67888 | 1.64041666667 | 14956 |
| 014765 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:46pm | Sensor | 1797-S0046-905-G-ACK | 6823.5 | 1595502.8 | 511764.9 | 67890 | 1.64041666667 | 14765 |
| 013990 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:47pm | Sensor | 1797-S0046-905-G-ACK | 6822.2 | 1595502.8 | 511767.8 | 67892 | 1.64041666667 | 13990 |
| 014192 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:48pm | Sensor | 1797-S0046-905-G-ACK | 6822.0 | 1595502.8 | 511770.1 | 67894 | 1.64041666667 | 14192 |
| 014808 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:49pm | Sensor | 1797-S0046-905-G-ACK | 6822.2 | 1595503.2 | 511773.1 | 67896 | 1.64041666667 | 14808 |
| 015169 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:50pm | Sensor | 1797-S0046-905-G-ACK | 6822.1 | 1595503.4 | 511775.4 | 67898 | 1.64041666667 | 15169 |
| 014585 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:51pm | Sensor | 1797-S0046-905-G-ACK | 6822.2 | 1595502.8 | 511778.6 | 67900 | 1.64041666667 | 14585 |
| 014264 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:52pm | Sensor | 1797-S0046-905-G-ACK | 6821.6 | 1595503.1 | 511781.4 | 67902 | 1.64041666667 | 14264 |
| 014016 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:53pm | Sensor | 1797-S0046-905-G-ACK | 6823.6 | 1595502.6 | 511784.5 | 67904 | 1.64041666667 | 14016 |
| 013629 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:54pm | Sensor | 1797-S0046-905-G-ACK | 6822.7 | 1595502.8 | 511787.0 | 67906 | 1.64041666667 | 13629 |
| 014738 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:55pm | Sensor | 1797-S0046-905-G-ACK | 6822.4 | 1595502.4 | 511790.1 | 67908 | 1.64041666667 | 14738 |
| 014695 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:56pm | Sensor | 1797-S0046-905-G-ACK | 6824.1 | 1595501.3 | 511793.0 | 67910 | 1.64041666667 | 14695 |
| 014221 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:57pm | Sensor | 1797-S0046-905-G-ACK | 6824.5 | 1595501.0 | 511796.5 | 67912 | 1.64041666667 | 14221 |
| 014606 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:58pm | Sensor | 1797-S0046-905-G-ACK | 6825.4 | 1595500.1 | 511799.5 | 67914 | 1.64041666667 | 14606 |
| 014471 | 0 | GeoXH 6000 | 08/19/2015 | 12:42:59pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595499.1 | 511802.8 | 67916 | 1.64041666667 | 14471 |
| 014800 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:00pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595498.8 | 511805.4 | 67918 | 1.64041666667 | 14800 |
| 015607 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:01pm | Sensor | 1797-S0046-905-G-ACK | 6826.0 | 1595499.0 | 511808.8 | 67920 | 1.64041666667 | 15607 |
| 015514 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:02pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595499.7 | 511811.5 | 67922 | 1.64041666667 | 15514 |
| 015904 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:03pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595499.6 | 511814.8 | 67924 | 1.64041666667 | 15904 |
| 015636 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:04pm | Sensor | 1797-S0046-905-G-ACK | 6823.9 | 1595499.9 | 511819.6 | 67926 | 1.64041666667 | 15636 |
| 015118 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:05pm | Sensor | 1797-S0046-905-G-ACK | 6823.6 | 1595500.1 | 511823.4 | 67928 | 1.64041666667 | 15118 |
| 014773 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:06pm | Sensor | 1797-S0046-905-G-ACK | 6823.9 | 1595500.5 | 511825.2 | 67930 | 1.64041666667 | 14773 |
| 015450 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:07pm | Sensor | 1797-S0046-905-G-ACK | 6825.3 | 1595500.1 | 511826.1 | 67932 | 1.64041666667 | 15450 |
| 016168 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:08pm | Sensor | 1797-S0046-905-G-ACK | 6826.1 | 1595499.7 | 511829.3 | 67934 | 1.64041666667 | 16168 |
| 016924 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:09pm | Sensor | 1797-S0046-905-G-ACK | 6829.0 | 1595498.7 | 511832.5 | 67936 | 1.64041666667 | 16924 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017207 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:10pm | Sensor | 1797-S0046-905-G-ACK | 6826.3 | 1595500.9 | 511835.1 | 67938 | 1.64041666667 | 17207 |
| 016369 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:11pm | Sensor | 1797-S0046-905-G-ACK | 6825.7 | 1595501.2 | 511837.7 | 67940 | 1.64041666667 | 16369 |
| 016805 | 0 | GeoXH 6000 | 08/19/2015 | 12:43:12pm | Sensor | 1797-S0046-905-G-ACK | 6824.0 | 1595501.9 | 511839.7 | 67942 | 1.64041666667 | 16805 |
| 007196 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.6 | 510305.2 | 62132 | 1.64041666667 | 7196 |
| 007439 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62135 | 1.64041666667 | 7439 |
| 007500 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.6 | 510305.3 | 62137 | 1.64041666667 | 7500 |
| 007515 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.6 | 510305.2 | 62139 | 1.64041666667 | 7515 |
| 007488 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.6 | 510305.2 | 62141 | 1.64041666667 | 7488 |
| 010302 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.6 | 510305.2 | 62143 | 1.64041666667 | 10302 |
| 007645 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62145 | 1.64041666667 | 7645 |
| 009231 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.3 | 62147 | 1.64041666667 | 9231 |
| 008097 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.6 | 510305.2 | 62149 | 1.64041666667 | 8097 |
| 008324 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62151 | 1.64041666667 | 8324 |
| 007301 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62153 | 1.64041666667 | 7301 |
| 007525 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62155 | 1.64041666667 | 7525 |
| 007551 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62157 | 1.64041666667 | 7551 |
| 007977 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62159 | 1.64041666667 | 7977 |
| 008144 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62161 | 1.64041666667 | 8144 |
| 008216 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.1 | 62163 | 1.64041666667 | 8216 |
| 008714 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62165 | 1.64041666667 | 8714 |
| 007728 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.6 | 510305.2 | 62167 | 1.64041666667 | 7728 |
| 007272 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.7 | 510305.1 | 62169 | 1.64041666667 | 7272 |
| 008058 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.7 | 510305.1 | 62171 | 1.64041666667 | 8058 |
| 007504 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.8 | 510305.1 | 62173 | 1.64041666667 | 7504 |
| 009946 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.6 | 510305.1 | 62175 | 1.64041666667 | 9946 |
| 009236 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595511.9 | 510305.1 | 62177 | 1.64041666667 | 9236 |
| 009119 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.9 | 510305.1 | 62179 | 1.64041666667 | 9119 |
| 008670 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.9 | 510305.0 | 62181 | 1.64041666667 | 8670 |
| 007567 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.9 | 510305.0 | 62183 | 1.64041666667 | 7567 |
| 007711 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595512.1 | 510305.0 | 62185 | 1.64041666667 | 7711 |
| 008527 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.2 | 510305.0 | 62187 | 1.64041666667 | 8527 |
| 008162 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.3 | 510305.2 | 62189 | 1.64041666667 | 8162 |
| 008130 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595512.4 | 510305.3 | 62191 | 1.64041666667 | 8130 |
| 008452 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595512.3 | 510305.3 | 62193 | 1.64041666667 | 8452 |
| 008683 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62195 | 1.64041666667 | 8683 |
| 009131 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62197 | 1.64041666667 | 9131 |
| 009482 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.2 | 510305.2 | 62199 | 1.64041666667 | 9482 |
| 008970 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.2 | 510305.1 | 62201 | 1.64041666667 | 8970 |
| 007012 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62203 | 1.64041666667 | 7012 |
| 006823 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.4 | 62205 | 1.64041666667 | 6823 |
| 006956 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.5 | 62207 | 1.64041666667 | 6956 |
| 008189 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.2 | 510305.5 | 62209 | 1.64041666667 | 8189 |
| 007447 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.4 | 62211 | 1.64041666667 | 7447 |
| 007681 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.9 | 510305.4 | 62213 | 1.64041666667 | 7681 |
| 007410 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.9 | 510305.4 | 62215 | 1.64041666667 | 7410 |
| 007402 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.0 | 510305.3 | 62217 | 1.64041666667 | 7402 |
| 007070 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.3 | 62219 | 1.64041666667 | 7070 |
| 009087 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.3 | 62221 | 1.64041666667 | 9087 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 007072 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.3 | 62223 | 1.64041666667 | 7072 |
| 006868 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.2 | 62225 | 1.64041666667 | 6868 |
| 006397 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.2 | 62227 | 1.64041666667 | 6397 |
| 008979 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.2 | 62229 | 1.64041666667 | 8979 |
| 008784 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62231 | 1.64041666667 | 8784 |
| 008616 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62233 | 1.64041666667 | 8616 |
| 008724 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62235 | 1.64041666667 | 8724 |
| 007401 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62237 | 1.64041666667 | 7401 |
| 007070 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62239 | 1.64041666667 | 7070 |
| 008967 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.2 | 62241 | 1.64041666667 | 8967 |
| 008572 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.2 | 62243 | 1.64041666667 | 8572 |
| 007633 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62245 | 1.64041666667 | 7633 |
| 007338 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.2 | 62247 | 1.64041666667 | 7338 |
| 007504 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.3 | 62249 | 1.64041666667 | 7504 |
| 008776 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.2 | 62251 | 1.64041666667 | 8776 |
| 009124 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.2 | 62253 | 1.64041666667 | 9124 |
| 008491 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.0 | 510305.2 | 62255 | 1.64041666667 | 8491 |
| 007822 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.1 | 510305.1 | 62257 | 1.64041666667 | 7822 |
| 008645 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.1 | 510305.1 | 62259 | 1.64041666667 | 8645 |
| 007021 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.1 | 510305.2 | 62261 | 1.64041666667 | 7021 |
| 007410 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.1 | 510305.2 | 62263 | 1.64041666667 | 7410 |
| 006731 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.1 | 510305.2 | 62265 | 1.64041666667 | 6731 |
| 007083 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.2 | 510305.1 | 62267 | 1.64041666667 | 7083 |
| 006600 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.2 | 510305.1 | 62269 | 1.64041666667 | 6600 |
| 008130 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.2 | 510305.1 | 62271 | 1.64041666667 | 8130 |
| 010132 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.2 | 510305.1 | 62273 | 1.64041666667 | 10132 |
| 008443 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595512.1 | 510305.1 | 62275 | 1.64041666667 | 8443 |
| 007811 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.8 | 510305.1 | 62277 | 1.64041666667 | 7811 |
| 008012 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595511.3 | 510305.0 | 62279 | 1.64041666667 | 8012 |
| 008453 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595511.5 | 510305.1 | 62281 | 1.64041666667 | 8453 |
| 007723 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.4 | 510306.0 | 62283 | 1.64041666667 | 7723 |
| 009521 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.5 | 510307.6 | 62285 | 1.64041666667 | 9521 |
| 009820 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595512.6 | 510308.6 | 62287 | 1.64041666667 | 9820 |
| 011725 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595513.0 | 510308.8 | 62289 | 1.64041666667 | 11725 |
| 012321 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595513.8 | 510308.8 | 62291 | 1.64041666667 | 12321 |
| 012050 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595513.9 | 510308.3 | 62293 | 1.64041666667 | 12050 |
| 010692 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595513.9 | 510307.6 | 62295 | 1.64041666667 | 10692 |
| 011133 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595513.6 | 510308.3 | 62297 | 1.64041666667 | 11133 |
| 010553 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595512.3 | 510309.6 | 62299 | 1.64041666667 | 10553 |
| 012058 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595510.6 | 510312.0 | 62301 | 1.64041666667 | 12058 |
| 011984 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595509.4 | 510314.1 | 62303 | 1.64041666667 | 11984 |
| 014156 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595507.4 | 510314.7 | 62305 | 1.64041666667 | 14156 |
| 013259 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:56am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595507.7 | 510313.3 | 62307 | 1.64041666667 | 13259 |
| 012254 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:57am | Sensor | 1797-S0045-G-TJV.cor | 6825.5 | 1595507.5 | 510314.0 | 62309 | 1.64041666667 | 12254 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:58am | Sensor | 1797-S0045-G-TJV.cor | 6825.0 | 1595506.9 | 510314.8 | 62311 | 1.64041666667 | 14463 |
| 013785 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:59am | Sensor | 1797-S0045-G-TJV.cor | 6825.7 | 1595507.2 | 510315.0 | 62313 | 1.64041666667 | 13785 |
| 013346 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:00am | Sensor | 1797-S0045-G-TJV.cor | 6826.1 | 1595507.3 | 510315.1 | 62315 | 1.64041666667 | 13346 |
| 012696 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:01am | Sensor | 1797-S0045-G-TJV.cor | 6826.1 | 1595507.6 | 510315.3 | 62317 | 1.64041666667 | 12696 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011994 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:02am | Sensor | 1797-S0045-G-TJV.cor | 6826.2 | 1595507.6 | 510315.4 | 62319 | 1.64041666667 | 11994 |
| 012028 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:03am | Sensor | 1797-S0045-G-TJV.cor | 6826.6 | 1595507.0 | 510315.2 | 62321 | 1.64041666667 | 12028 |
| 012187 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:04am | Sensor | 1797-S0045-G-TJV.cor | 6825.9 | 1595507.6 | 510314.2 | 62323 | 1.64041666667 | 12187 |
| 012166 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:05am | Sensor | 1797-S0045-G-TJV.cor | 6826.1 | 1595507.0 | 510315.2 | 62325 | 1.64041666667 | 12166 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:06am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595507.5 | 510316.0 | 62327 | 1.64041666667 | 12521 |
| 011890 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595509.6 | 510317.0 | 62329 | 1.64041666667 | 11890 |
| 014582 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595511.8 | 510317.7 | 62331 | 1.64041666667 | 14582 |
| 011955 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595513.5 | 510318.5 | 62333 | 1.64041666667 | 11955 |
| 012528 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595513.9 | 510318.5 | 62335 | 1.64041666667 | 12528 |
| 013662 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.0 | 510318.2 | 62337 | 1.64041666667 | 13662 |
| 013165 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595513.9 | 510318.2 | 62339 | 1.64041666667 | 13165 |
| 012891 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595513.9 | 510318.2 | 62341 | 1.64041666667 | 12891 |
| 013332 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595513.8 | 510318.2 | 62343 | 1.64041666667 | 13332 |
| 013353 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595513.7 | 510318.3 | 62345 | 1.64041666667 | 13353 |
| 013838 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595513.8 | 510318.6 | 62347 | 1.64041666667 | 13838 |
| 012609 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595513.8 | 510318.5 | 62349 | 1.64041666667 | 12609 |
| 012122 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595513.7 | 510318.5 | 62351 | 1.64041666667 | 12122 |
| 012210 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595513.7 | 510318.5 | 62353 | 1.64041666667 | 12210 |
| 012472 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595513.9 | 510318.4 | 62355 | 1.64041666667 | 12472 |
| 013918 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.5 | 510317.8 | 62357 | 1.64041666667 | 13918 |
| 013889 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.6 | 510317.4 | 62359 | 1.64041666667 | 13889 |
| 011812 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.5 | 510317.6 | 62361 | 1.64041666667 | 11812 |
| 013873 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.5 | 510317.8 | 62363 | 1.64041666667 | 13873 |
| 013608 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595514.6 | 510318.0 | 62365 | 1.64041666667 | 13608 |
| 012522 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595514.6 | 510318.1 | 62367 | 1.64041666667 | 12522 |
| 013720 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595514.5 | 510318.1 | 62369 | 1.64041666667 | 13720 |
| 013120 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595514.5 | 510318.1 | 62371 | 1.64041666667 | 13120 |
| 014230 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595514.4 | 510318.0 | 62373 | 1.64041666667 | 14230 |
| 012587 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.0 | 62375 | 1.64041666667 | 12587 |
| 013316 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.0 | 62377 | 1.64041666667 | 13316 |
| 012419 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.0 | 62379 | 1.64041666667 | 12419 |
| 013125 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.1 | 62381 | 1.64041666667 | 13125 |
| 013091 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.1 | 62383 | 1.64041666667 | 13091 |
| 013022 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.1 | 62385 | 1.64041666667 | 13022 |
| 012195 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.1 | 62387 | 1.64041666667 | 12195 |
| 012738 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.1 | 62389 | 1.64041666667 | 12738 |
| 013594 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595514.4 | 510318.2 | 62391 | 1.64041666667 | 13594 |
| 013748 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595515.0 | 510318.1 | 62393 | 1.64041666667 | 13748 |
| 011987 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595516.9 | 510317.9 | 62395 | 1.64041666667 | 11987 |
| 011846 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595520.1 | 510318.3 | 62397 | 1.64041666667 | 11846 |
| 012861 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595522.7 | 510320.0 | 62399 | 1.64041666667 | 12861 |
| 013475 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:43am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595525.8 | 510322.9 | 62401 | 1.64041666667 | 13475 |
| 014018 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:44am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595528.2 | 510325.9 | 62403 | 1.64041666667 | 14018 |
| 014004 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:45am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595530.4 | 510329.1 | 62405 | 1.64041666667 | 14004 |
| 012921 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595532.2 | 510331.8 | 62407 | 1.64041666667 | 12921 |
| 013580 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595533.1 | 510335.2 | 62409 | 1.64041666667 | 13580 |
| 014735 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595532.7 | 510338.0 | 62411 | 1.64041666667 | 14735 |
| 014033 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595533.0 | 510341.5 | 62413 | 1.64041666667 | 14033 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013828 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595534.0 | 510344.8 | 62415 | 1.64041666667 | 13828 |
| 012097 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595535.0 | 510348.4 | 62417 | 1.64041666667 | 12097 |
| 014028 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595536.2 | 510351.5 | 62419 | 1.64041666667 | 14028 |
| 013438 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595538.3 | 510355.3 | 62421 | 1.64041666667 | 13438 |
| 014339 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595539.7 | 510358.2 | 62423 | 1.64041666667 | 14339 |
| 014325 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595540.8 | 510361.6 | 62425 | 1.64041666667 | 14325 |
| 013331 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595541.2 | 510364.7 | 62427 | 1.64041666667 | 13331 |
| 015422 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595541.2 | 510367.6 | 62429 | 1.64041666667 | 15422 |
| 012315 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595540.8 | 510369.0 | 62431 | 1.64041666667 | 12315 |
| 013998 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595540.4 | 510369.4 | 62433 | 1.64041666667 | 13998 |
| 013969 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595540.4 | 510369.5 | 62435 | 1.64041666667 | 13969 |
| 013752 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595540.6 | 510369.7 | 62437 | 1.64041666667 | 13752 |
| 012828 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595540.6 | 510369.7 | 62439 | 1.64041666667 | 12828 |
| 012057 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595540.9 | 510369.2 | 62441 | 1.64041666667 | 12057 |
| 011894 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595541.0 | 510369.1 | 62443 | 1.64041666667 | 11894 |
| 012963 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595541.0 | 510369.2 | 62445 | 1.64041666667 | 12963 |
| 013080 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595541.8 | 510369.1 | 62447 | 1.64041666667 | 13080 |
| 012540 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595543.6 | 510367.5 | 62449 | 1.64041666667 | 12540 |
| 013725 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595545.0 | 510365.9 | 62451 | 1.64041666667 | 13725 |
| 013271 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595546.0 | 510365.1 | 62453 | 1.64041666667 | 13271 |
| 013938 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:10am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595546.7 | 510364.6 | 62455 | 1.64041666667 | 13938 |
| 012574 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:11am | Sensor | 1797-S0045-G-TJV.cor | 6827.0 | 1595547.0 | 510364.4 | 62457 | 1.64041666667 | 12574 |
| 012713 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:12am | Sensor | 1797-S0045-G-TJV.cor | 6827.0 | 1595547.1 | 510364.4 | 62459 | 1.64041666667 | 12713 |
| 014188 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:13am | Sensor | 1797-S0045-G-TJV.cor | 6826.9 | 1595547.2 | 510364.3 | 62461 | 1.64041666667 | 14188 |
| 012847 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:14am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595546.2 | 510364.7 | 62463 | 1.64041666667 | 12847 |
| 013141 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595544.4 | 510365.1 | 62465 | 1.64041666667 | 13141 |
| 013995 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595544.0 | 510365.9 | 62467 | 1.64041666667 | 13995 |
| 013098 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595542.7 | 510368.0 | 62469 | 1.64041666667 | 13098 |
| 012784 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595542.2 | 510370.0 | 62471 | 1.64041666667 | 12784 |
| 012766 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595543.0 | 510371.7 | 62473 | 1.64041666667 | 12766 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595544.2 | 510372.7 | 62475 | 1.64041666667 | 12461 |
| 012115 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595546.2 | 510372.0 | 62477 | 1.64041666667 | 12115 |
| 012239 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595548.1 | 510371.4 | 62479 | 1.64041666667 | 12239 |
| 012269 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595549.8 | 510371.1 | 62481 | 1.64041666667 | 12269 |
| 014047 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595550.3 | 510371.2 | 62483 | 1.64041666667 | 14047 |
| 013411 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595550.7 | 510370.8 | 62485 | 1.64041666667 | 13411 |
| 014242 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595552.0 | 510370.8 | 62487 | 1.64041666667 | 14242 |
| 013670 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595554.5 | 510370.8 | 62489 | 1.64041666667 | 13670 |
| 013977 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:28am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595556.8 | 510370.7 | 62491 | 1.64041666667 | 13977 |
| 012974 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:29am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595559.6 | 510371.8 | 62493 | 1.64041666667 | 12974 |
| 016383 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:30am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595560.7 | 510372.0 | 62495 | 1.64041666667 | 16383 |
| 012885 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:31am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595561.0 | 510372.0 | 62497 | 1.64041666667 | 12885 |
| 012671 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:32am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595560.9 | 510372.1 | 62499 | 1.64041666667 | 12671 |
| 014028 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:33am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595560.9 | 510372.0 | 62501 | 1.64041666667 | 14028 |
| 013197 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:34am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595560.8 | 510372.0 | 62503 | 1.64041666667 | 13197 |
| 012839 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:35am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595560.8 | 510372.0 | 62505 | 1.64041666667 | 12839 |
| 013290 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:36am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595560.8 | 510372.1 | 62507 | 1.64041666667 | 13290 |
| 013042 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:37am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595560.8 | 510372.1 | 62509 | 1.64041666667 | 13042 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013335 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:26am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.7 | 510372.2 | 62607 | 1.64041666667 | 13335 |
| 013263 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:27am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.7 | 510372.2 | 62609 | 1.64041666667 | 13263 |
| 011656 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:28am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.6 | 510372.2 | 62611 | 1.64041666667 | 11656 |
| 013504 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:29am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.6 | 510372.2 | 62613 | 1.64041666667 | 13504 |
| 012676 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:30am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.6 | 510372.2 | 62615 | 1.64041666667 | 12676 |
| 012979 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:31am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.6 | 510372.2 | 62617 | 1.64041666667 | 12979 |
| 011104 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:32am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.6 | 510372.1 | 62619 | 1.64041666667 | 11104 |
| 014656 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:33am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595560.6 | 510372.1 | 62621 | 1.64041666667 | 14656 |
| 013834 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:34am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595560.6 | 510372.1 | 62623 | 1.64041666667 | 13834 |
| 012788 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:35am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.6 | 510372.2 | 62625 | 1.64041666667 | 12788 |
| 013337 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:36am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595560.8 | 510372.1 | 62627 | 1.64041666667 | 13337 |
| 013204 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:37am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595561.6 | 510371.8 | 62629 | 1.64041666667 | 13204 |
| 014041 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:38am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595562.1 | 510371.9 | 62631 | 1.64041666667 | 14041 |
| 013860 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:39am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595562.9 | 510372.8 | 62633 | 1.64041666667 | 13860 |
| 013965 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:40am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595564.5 | 510374.2 | 62635 | 1.64041666667 | 13965 |
| 013571 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:41am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595566.0 | 510375.4 | 62637 | 1.64041666667 | 13571 |
| 013983 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:42am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595567.6 | 510376.4 | 62639 | 1.64041666667 | 13983 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:43am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595568.9 | 510377.4 | 62641 | 1.64041666667 | 12975 |
| 014493 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:44am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595569.2 | 510377.3 | 62643 | 1.64041666667 | 14493 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:45am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595569.4 | 510377.1 | 62645 | 1.64041666667 | 12803 |
| 014001 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:46am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595569.9 | 510377.8 | 62647 | 1.64041666667 | 14001 |
| 012710 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:47am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595571.4 | 510379.2 | 62649 | 1.64041666667 | 12710 |
| 013017 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:48am | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595572.6 | 510381.0 | 62651 | 1.64041666667 | 13017 |
| 013814 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:49am | Sensor | 1797-S0045-G-TJV.cor | 6827.0 | 1595574.0 | 510383.4 | 62653 | 1.64041666667 | 13814 |
| 012273 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:50am | Sensor | 1797-S0045-G-TJV.cor | 6827.1 | 1595575.3 | 510384.8 | 62655 | 1.64041666667 | 12273 |
| 014078 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:51am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595577.1 | 510386.3 | 62657 | 1.64041666667 | 14078 |
| 012999 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:52am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595578.5 | 510386.8 | 62659 | 1.64041666667 | 12999 |
| 013630 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:53am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595580.0 | 510388.1 | 62661 | 1.64041666667 | 13630 |
| 013157 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:54am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595581.9 | 510388.9 | 62663 | 1.64041666667 | 13157 |
| 012829 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:55am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595584.4 | 510390.0 | 62665 | 1.64041666667 | 12829 |
| 012117 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:56am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595586.6 | 510390.5 | 62667 | 1.64041666667 | 12117 |
| 013769 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:57am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595588.4 | 510391.1 | 62669 | 1.64041666667 | 13769 |
| 012952 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:58am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595590.4 | 510391.5 | 62671 | 1.64041666667 | 12952 |
| 014098 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:59am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595592.9 | 510392.4 | 62673 | 1.64041666667 | 14098 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:00am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595595.4 | 510393.5 | 62675 | 1.64041666667 | 13424 |
| 012176 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:01am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595597.6 | 510394.7 | 62677 | 1.64041666667 | 12176 |
| 013694 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:02am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595600.0 | 510395.9 | 62679 | 1.64041666667 | 13694 |
| 014613 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:03am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595602.2 | 510396.9 | 62681 | 1.64041666667 | 14613 |
| 014963 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:04am | Sensor | 1797-S0045-G-TJV.cor | 6827.1 | 1595604.7 | 510398.1 | 62683 | 1.64041666667 | 14963 |
| 012410 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:05am | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595607.2 | 510398.8 | 62685 | 1.64041666667 | 12410 |
| 014262 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:06am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595609.3 | 510399.4 | 62687 | 1.64041666667 | 14262 |
| 014785 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:07am | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595611.9 | 510399.7 | 62689 | 1.64041666667 | 14785 |
| 013956 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:08am | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595613.9 | 510400.6 | 62691 | 1.64041666667 | 13956 |
| 012759 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:09am | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595616.5 | 510401.0 | 62693 | 1.64041666667 | 12759 |
| 012909 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:10am | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595618.3 | 510401.3 | 62695 | 1.64041666667 | 12909 |
| 013457 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:11am | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595620.4 | 510401.9 | 62697 | 1.64041666667 | 13457 |
| 012694 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:12am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595622.1 | 510402.8 | 62699 | 1.64041666667 | 12694 |
| 013583 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:13am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595623.9 | 510404.1 | 62701 | 1.64041666667 | 13583 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012396 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:14am | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595625.2 | 510405.6 | 62703 | 1.64041666667 | 12396 |
| 011199 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:15am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595626.4 | 510406.8 | 62705 | 1.64041666667 | 11199 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:16am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595628.0 | 510408.0 | 62707 | 1.64041666667 | 14049 |
| 013712 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:17am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595629.9 | 510409.2 | 62709 | 1.64041666667 | 13712 |
| 014528 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:18am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595632.0 | 510409.6 | 62711 | 1.64041666667 | 14528 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:19am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595633.7 | 510410.4 | 62713 | 1.64041666667 | 14132 |
| 012023 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:20am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595634.0 | 510410.9 | 62715 | 1.64041666667 | 12023 |
| 012965 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:21am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595634.4 | 510410.8 | 62717 | 1.64041666667 | 12965 |
| 011763 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:22am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595635.7 | 510411.6 | 62719 | 1.64041666667 | 11763 |
| 012555 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:23am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595637.2 | 510412.5 | 62721 | 1.64041666667 | 12555 |
| 013128 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:24am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595637.6 | 510413.0 | 62723 | 1.64041666667 | 13128 |
| 013002 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:25am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595637.7 | 510413.3 | 62725 | 1.64041666667 | 13002 |
| 013840 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:26am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595637.7 | 510413.2 | 62727 | 1.64041666667 | 13840 |
| 014380 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:27am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595638.7 | 510411.6 | 62729 | 1.64041666667 | 14380 |
| 014545 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:28am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595640.3 | 510410.4 | 62731 | 1.64041666667 | 14545 |
| 014586 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:29am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595641.0 | 510410.1 | 62733 | 1.64041666667 | 14586 |
| 013696 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:30am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595641.2 | 510409.4 | 62735 | 1.64041666667 | 13696 |
| 013264 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:31am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595642.6 | 510407.3 | 62737 | 1.64041666667 | 13264 |
| 013276 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:32am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.4 | 510405.9 | 62739 | 1.64041666667 | 13276 |
| 014059 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:33am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.6 | 510405.5 | 62741 | 1.64041666667 | 14059 |
| 011884 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:34am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.7 | 510405.5 | 62743 | 1.64041666667 | 11884 |
| 012391 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:35am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.6 | 510405.5 | 62745 | 1.64041666667 | 12391 |
| 013537 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:36am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.5 | 510405.5 | 62747 | 1.64041666667 | 13537 |
| 013044 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:37am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.6 | 510405.4 | 62749 | 1.64041666667 | 13044 |
| 014511 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:38am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.7 | 510405.5 | 62751 | 1.64041666667 | 14511 |
| 013947 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:39am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.7 | 510405.5 | 62753 | 1.64041666667 | 13947 |
| 013387 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:40am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.5 | 510405.4 | 62755 | 1.64041666667 | 13387 |
| 012946 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:41am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595643.5 | 510405.2 | 62757 | 1.64041666667 | 12946 |
| 013166 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:42am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595644.8 | 510405.1 | 62759 | 1.64041666667 | 13166 |
| 013551 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:43am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595646.1 | 510405.0 | 62761 | 1.64041666667 | 13551 |
| 013528 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:44am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595645.6 | 510405.2 | 62763 | 1.64041666667 | 13528 |
| 013702 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:45am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595645.1 | 510404.8 | 62765 | 1.64041666667 | 13702 |
| 013595 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:46am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595645.1 | 510404.5 | 62767 | 1.64041666667 | 13595 |
| 012158 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:47am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595644.7 | 510404.8 | 62769 | 1.64041666667 | 12158 |
| 011839 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:48am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.9 | 510405.3 | 62771 | 1.64041666667 | 11839 |
| 012655 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:49am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.3 | 510407.0 | 62773 | 1.64041666667 | 12655 |
| 013363 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:50am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595643.7 | 510408.0 | 62775 | 1.64041666667 | 13363 |
| 012011 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:51am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595644.0 | 510408.3 | 62777 | 1.64041666667 | 12011 |
| 012722 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:52am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.6 | 510408.3 | 62779 | 1.64041666667 | 12722 |
| 012300 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:53am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.6 | 510408.4 | 62781 | 1.64041666667 | 12300 |
| 012285 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:54am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595643.8 | 510408.4 | 62783 | 1.64041666667 | 12285 |
| 011861 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:55am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595643.8 | 510408.1 | 62785 | 1.64041666667 | 11861 |
| 012175 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:56am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595643.0 | 510408.1 | 62787 | 1.64041666667 | 12175 |
| 014504 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:57am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595641.5 | 510408.0 | 62789 | 1.64041666667 | 14504 |
| 013466 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:58am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595639.5 | 510407.5 | 62791 | 1.64041666667 | 13466 |
| 013266 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:59am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595637.3 | 510406.0 | 62793 | 1.64041666667 | 13266 |
| 012466 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:00am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595635.4 | 510405.3 | 62795 | 1.64041666667 | 12466 |
| 012986 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:01am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595633.4 | 510404.8 | 62797 | 1.64041666667 | 12986 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012456 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:02am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595631.4 | 510404.3 | 62799 | 1.64041666667 | 12456 |
| 013344 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:03am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595629.1 | 510403.3 | 62801 | 1.64041666667 | 13344 |
| 015096 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:04am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595627.2 | 510402.3 | 62803 | 1.64041666667 | 15096 |
| 015024 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:05am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595624.5 | 510401.3 | 62805 | 1.64041666667 | 15024 |
| 013266 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:06am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595622.7 | 510401.2 | 62807 | 1.64041666667 | 13266 |
| 013516 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:07am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595620.2 | 510400.9 | 62809 | 1.64041666667 | 13516 |
| 015079 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:08am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595618.2 | 510400.6 | 62811 | 1.64041666667 | 15079 |
| 013729 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:09am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595616.2 | 510399.8 | 62813 | 1.64041666667 | 13729 |
| 014292 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:10am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595614.4 | 510398.3 | 62815 | 1.64041666667 | 14292 |
| 013293 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:11am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595611.9 | 510396.7 | 62817 | 1.64041666667 | 13293 |
| 014123 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:12am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.7 | 510395.1 | 62819 | 1.64041666667 | 14123 |
| 013010 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:13am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595607.3 | 510393.9 | 62821 | 1.64041666667 | 13010 |
| 015132 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:14am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595605.1 | 510392.6 | 62823 | 1.64041666667 | 15132 |
| 013983 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:15am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595602.9 | 510391.2 | 62825 | 1.64041666667 | 13983 |
| 013935 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:16am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595600.9 | 510390.2 | 62827 | 1.64041666667 | 13935 |
| 013833 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:17am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595598.5 | 510388.6 | 62829 | 1.64041666667 | 13833 |
| 013838 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:18am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595596.5 | 510387.1 | 62831 | 1.64041666667 | 13838 |
| 013569 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:19am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595593.8 | 510385.1 | 62833 | 1.64041666667 | 13569 |
| 012422 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:20am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595591.3 | 510384.3 | 62835 | 1.64041666667 | 12422 |
| 013635 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:21am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595588.8 | 510383.3 | 62837 | 1.64041666667 | 13635 |
| 013548 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:22am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595586.4 | 510382.4 | 62839 | 1.64041666667 | 13548 |
| 013677 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:23am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595584.0 | 510381.3 | 62841 | 1.64041666667 | 13677 |
| 012629 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:24am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595581.6 | 510380.6 | 62843 | 1.64041666667 | 12629 |
| 013057 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:25am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595579.1 | 510379.7 | 62845 | 1.64041666667 | 13057 |
| 013524 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:26am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595576.7 | 510379.2 | 62847 | 1.64041666667 | 13524 |
| 013311 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:27am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595573.8 | 510378.2 | 62849 | 1.64041666667 | 13311 |
| 012237 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:28am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595571.6 | 510377.0 | 62851 | 1.64041666667 | 12237 |
| 012179 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:29am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595569.3 | 510375.9 | 62853 | 1.64041666667 | 12179 |
| 014385 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:30am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595567.4 | 510375.0 | 62855 | 1.64041666667 | 14385 |
| 013136 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:31am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595564.6 | 510374.1 | 62857 | 1.64041666667 | 13136 |
| 012854 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:32am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595562.6 | 510372.8 | 62859 | 1.64041666667 | 12854 |
| 013473 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:33am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595559.9 | 510371.1 | 62861 | 1.64041666667 | 13473 |
| 013628 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595558.2 | 510369.7 | 62863 | 1.64041666667 | 13628 |
| 014567 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595555.8 | 510368.2 | 62865 | 1.64041666667 | 14567 |
| 012911 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595553.4 | 510366.7 | 62867 | 1.64041666667 | 12911 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595550.8 | 510366.0 | 62869 | 1.64041666667 | 12378 |
| 013354 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595549.4 | 510365.7 | 62871 | 1.64041666667 | 13354 |
| 012848 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595548.9 | 510366.0 | 62873 | 1.64041666667 | 12848 |
| 011522 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595548.8 | 510366.4 | 62875 | 1.64041666667 | 11522 |
| 013260 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595548.7 | 510366.4 | 62877 | 1.64041666667 | 13260 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595548.6 | 510366.2 | 62879 | 1.64041666667 | 12975 |
| 012243 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595547.8 | 510365.2 | 62881 | 1.64041666667 | 12243 |
| 012781 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595546.9 | 510363.4 | 62883 | 1.64041666667 | 12781 |
| 013095 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595545.3 | 510361.1 | 62885 | 1.64041666667 | 13095 |
| 013023 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595543.9 | 510359.3 | 62887 | 1.64041666667 | 13023 |
| 013726 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595542.2 | 510357.2 | 62889 | 1.64041666667 | 13726 |
| 013721 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595540.9 | 510355.4 | 62891 | 1.64041666667 | 13721 |
| 014230 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595539.8 | 510353.8 | 62893 | 1.64041666667 | 14230 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013457 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:50am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595538.3 | 510352.1 | 62895 | 1.64041666667 | 13457 |
| 013924 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:51am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595537.5 | 510350.2 | 62897 | 1.64041666667 | 13924 |
| 014701 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595537.1 | 510348.6 | 62899 | 1.64041666667 | 14701 |
| 013035 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595536.8 | 510348.3 | 62901 | 1.64041666667 | 13035 |
| 011988 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595536.3 | 510348.3 | 62903 | 1.64041666667 | 11988 |
| 011847 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595536.2 | 510348.3 | 62905 | 1.64041666667 | 11847 |
| 012523 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595536.6 | 510348.4 | 62907 | 1.64041666667 | 12523 |
| 013025 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595537.9 | 510347.2 | 62909 | 1.64041666667 | 13025 |
| 013096 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595539.5 | 510346.0 | 62911 | 1.64041666667 | 13096 |
| 014674 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595540.9 | 510345.3 | 62913 | 1.64041666667 | 14674 |
| 014498 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595541.6 | 510344.0 | 62915 | 1.64041666667 | 14498 |
| 011784 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595543.0 | 510342.6 | 62917 | 1.64041666667 | 11784 |
| 012006 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595543.5 | 510342.2 | 62919 | 1.64041666667 | 12006 |
| 011971 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:03am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595544.4 | 510341.4 | 62921 | 1.64041666667 | 11971 |
| 013372 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:04am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595545.2 | 510341.0 | 62923 | 1.64041666667 | 13372 |
| 013063 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:05am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595545.4 | 510340.9 | 62925 | 1.64041666667 | 13063 |
| 013676 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:06am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595545.5 | 510340.8 | 62927 | 1.64041666667 | 13676 |
| 012209 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:07am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595545.4 | 510340.8 | 62929 | 1.64041666667 | 12209 |
| 013162 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595544.5 | 510340.7 | 62931 | 1.64041666667 | 13162 |
| 014570 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595543.7 | 510341.3 | 62933 | 1.64041666667 | 14570 |
| 014112 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595543.1 | 510343.2 | 62935 | 1.64041666667 | 14112 |
| 012318 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595543.0 | 510346.6 | 62937 | 1.64041666667 | 12318 |
| 013159 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595543.3 | 510350.2 | 62939 | 1.64041666667 | 13159 |
| 012679 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595544.0 | 510353.6 | 62941 | 1.64041666667 | 12679 |
| 015890 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595544.6 | 510356.6 | 62943 | 1.64041666667 | 15890 |
| 015342 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595545.3 | 510360.7 | 62945 | 1.64041666667 | 15342 |
| 012835 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595545.5 | 510363.2 | 62947 | 1.64041666667 | 12835 |
| 014819 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595545.5 | 510362.5 | 62949 | 1.64041666667 | 14819 |
| 012164 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595544.5 | 510361.0 | 62951 | 1.64041666667 | 12164 |
| 013781 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595542.3 | 510359.0 | 62953 | 1.64041666667 | 13781 |
| 013525 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595540.5 | 510356.4 | 62955 | 1.64041666667 | 13525 |
| 015531 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595539.1 | 510352.8 | 62957 | 1.64041666667 | 15531 |
| 014082 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595538.5 | 510349.8 | 62959 | 1.64041666667 | 14082 |
| 014560 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595538.8 | 510346.7 | 62961 | 1.64041666667 | 14560 |
| 014260 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595539.3 | 510345.5 | 62963 | 1.64041666667 | 14260 |
| 012835 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595539.8 | 510345.1 | 62965 | 1.64041666667 | 12835 |
| 012358 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595540.8 | 510344.6 | 62967 | 1.64041666667 | 12358 |
| 012029 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:27am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595542.7 | 510344.4 | 62969 | 1.64041666667 | 12029 |
| 013237 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:28am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595545.0 | 510345.7 | 62971 | 1.64041666667 | 13237 |
| 012849 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595547.9 | 510347.2 | 62973 | 1.64041666667 | 12849 |
| 012692 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595549.8 | 510348.6 | 62975 | 1.64041666667 | 12692 |
| 014243 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595552.3 | 510350.5 | 62977 | 1.64041666667 | 14243 |
| 012500 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595554.9 | 510352.0 | 62979 | 1.64041666667 | 12500 |
| 014585 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595557.8 | 510354.0 | 62981 | 1.64041666667 | 14585 |
| 012256 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595560.0 | 510355.5 | 62983 | 1.64041666667 | 12256 |
| 012904 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595562.0 | 510357.4 | 62985 | 1.64041666667 | 12904 |
| 012856 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595564.5 | 510358.8 | 62987 | 1.64041666667 | 12856 |
| 013624 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595566.7 | 510360.8 | 62989 | 1.64041666667 | 13624 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013216 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:38am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595568.4 | 510362.1 | 62991 | 1.64041666667 | 13216 |
| 013744 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:39am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595570.4 | 510363.6 | 62993 | 1.64041666667 | 13744 |
| 013246 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:40am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595571.5 | 510364.5 | 62995 | 1.64041666667 | 13246 |
| 014441 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595573.5 | 510365.8 | 62997 | 1.64041666667 | 14441 |
| 013810 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595574.9 | 510367.2 | 62999 | 1.64041666667 | 13810 |
| 012032 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595576.0 | 510367.9 | 63001 | 1.64041666667 | 12032 |
| 012008 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595577.4 | 510369.4 | 63003 | 1.64041666667 | 12008 |
| 012692 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595579.3 | 510370.6 | 63005 | 1.64041666667 | 12692 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595580.7 | 510371.5 | 63007 | 1.64041666667 | 12743 |
| 012935 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595582.7 | 510372.7 | 63009 | 1.64041666667 | 12935 |
| 012924 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.1 | 510374.0 | 63011 | 1.64041666667 | 12924 |
| 012831 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595586.4 | 510375.3 | 63013 | 1.64041666667 | 12831 |
| 014007 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595588.3 | 510376.6 | 63015 | 1.64041666667 | 14007 |
| 013792 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595590.5 | 510377.5 | 63017 | 1.64041666667 | 13792 |
| 012718 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595592.3 | 510378.3 | 63019 | 1.64041666667 | 12718 |
| 014249 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595594.8 | 510379.7 | 63021 | 1.64041666667 | 14249 |
| 013702 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:54am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595596.7 | 510381.2 | 63023 | 1.64041666667 | 13702 |
| 013535 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:55am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595599.0 | 510383.3 | 63025 | 1.64041666667 | 13535 |
| 012683 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:56am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595601.3 | 510384.7 | 63027 | 1.64041666667 | 12683 |
| 013731 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:57am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595604.2 | 510386.1 | 63029 | 1.64041666667 | 13731 |
| 013302 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:58am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595606.6 | 510386.9 | 63031 | 1.64041666667 | 13302 |
| 014305 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:59am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595609.2 | 510387.9 | 63033 | 1.64041666667 | 14305 |
| 016356 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:00am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595611.5 | 510388.6 | 63035 | 1.64041666667 | 16356 |
| 014229 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:01am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595613.9 | 510389.3 | 63037 | 1.64041666667 | 14229 |
| 014687 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:02am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595616.1 | 510390.2 | 63039 | 1.64041666667 | 14687 |
| 013961 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:03am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595618.1 | 510391.6 | 63041 | 1.64041666667 | 13961 |
| 012970 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:04am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595620.1 | 510392.5 | 63043 | 1.64041666667 | 12970 |
| 012062 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:05am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595621.6 | 510394.0 | 63045 | 1.64041666667 | 12062 |
| 012795 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:06am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595623.3 | 510395.3 | 63047 | 1.64041666667 | 12795 |
| 012948 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:07am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595625.0 | 510396.6 | 63049 | 1.64041666667 | 12948 |
| 015207 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:08am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595626.8 | 510397.0 | 63051 | 1.64041666667 | 15207 |
| 014152 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:09am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595627.8 | 510397.5 | 63053 | 1.64041666667 | 14152 |
| 013708 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:10am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595627.9 | 510398.1 | 63055 | 1.64041666667 | 13708 |
| 014047 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:11am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595628.8 | 510397.3 | 63057 | 1.64041666667 | 14047 |
| 014071 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:12am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595629.8 | 510397.1 | 63059 | 1.64041666667 | 14071 |
| 013477 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:13am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595630.1 | 510397.4 | 63061 | 1.64041666667 | 13477 |
| 013359 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:14am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595630.1 | 510397.5 | 63063 | 1.64041666667 | 13359 |
| 012490 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:15am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595630.2 | 510397.6 | 63065 | 1.64041666667 | 12490 |
| 014492 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:16am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595630.7 | 510397.6 | 63067 | 1.64041666667 | 14492 |
| 013913 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:17am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595631.8 | 510397.8 | 63069 | 1.64041666667 | 13913 |
| 013948 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:18am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595632.8 | 510397.9 | 63071 | 1.64041666667 | 13948 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:19am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595634.6 | 510397.9 | 63073 | 1.64041666667 | 13297 |
| 013944 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:20am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595636.6 | 510398.7 | 63075 | 1.64041666667 | 13944 |
| 012906 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:21am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595639.1 | 510399.1 | 63077 | 1.64041666667 | 12906 |
| 013666 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:22am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595640.6 | 510399.5 | 63079 | 1.64041666667 | 13666 |
| 013406 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:23am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595642.1 | 510400.4 | 63081 | 1.64041666667 | 13406 |
| 014121 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:24am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595643.8 | 510401.3 | 63083 | 1.64041666667 | 14121 |
| 013400 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:25am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595645.7 | 510402.4 | 63085 | 1.64041666667 | 13400 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013760 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:26am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595646.4 | 510403.2 | 63087 | 1.64041666667 | 13760 |
| 012260 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:27am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595646.5 | 510403.9 | 63089 | 1.64041666667 | 12260 |
| 012605 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:28am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595646.3 | 510403.8 | 63091 | 1.64041666667 | 12605 |
| 012271 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:29am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595646.6 | 510402.8 | 63093 | 1.64041666667 | 12271 |
| 012667 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:30am | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595646.8 | 510402.3 | 63095 | 1.64041666667 | 12667 |
| 012377 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:31am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595646.3 | 510402.9 | 63097 | 1.64041666667 | 12377 |
| 012814 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:32am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595646.1 | 510403.2 | 63099 | 1.64041666667 | 12814 |
| 013313 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:33am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595646.1 | 510403.3 | 63101 | 1.64041666667 | 13313 |
| 013858 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:34am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595646.3 | 510403.3 | 63103 | 1.64041666667 | 13858 |
| 012494 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:35am | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595646.9 | 510402.7 | 63105 | 1.64041666667 | 12494 |
| 012633 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:36am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595648.1 | 510401.5 | 63107 | 1.64041666667 | 12633 |
| 014588 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:37am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595649.9 | 510399.1 | 63109 | 1.64041666667 | 14588 |
| 013217 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:38am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595650.8 | 510398.7 | 63111 | 1.64041666667 | 13217 |
| 014584 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:39am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595651.3 | 510399.0 | 63113 | 1.64041666667 | 14584 |
| 012436 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:40am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595651.4 | 510399.0 | 63115 | 1.64041666667 | 12436 |
| 013669 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:41am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595651.2 | 510399.0 | 63117 | 1.64041666667 | 13669 |
| 013677 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:42am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595651.1 | 510398.9 | 63119 | 1.64041666667 | 13677 |
| 014099 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:43am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595651.1 | 510398.7 | 63121 | 1.64041666667 | 14099 |
| 012165 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:44am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595650.9 | 510398.5 | 63123 | 1.64041666667 | 12165 |
| 013361 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:45am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595651.8 | 510397.3 | 63125 | 1.64041666667 | 13361 |
| 012970 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:46am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595653.1 | 510395.3 | 63127 | 1.64041666667 | 12970 |
| 012242 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:47am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595654.1 | 510393.9 | 63129 | 1.64041666667 | 12242 |
| 013680 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:48am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595655.0 | 510393.5 | 63131 | 1.64041666667 | 13680 |
| 013260 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595655.3 | 510393.3 | 63133 | 1.64041666667 | 13260 |
| 012195 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595655.1 | 510392.9 | 63135 | 1.64041666667 | 12195 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595654.5 | 510392.8 | 63137 | 1.64041666667 | 12768 |
| 013404 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595653.7 | 510394.3 | 63139 | 1.64041666667 | 13404 |
| 011800 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:53am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595652.3 | 510396.2 | 63141 | 1.64041666667 | 11800 |
| 013600 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:54am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595651.3 | 510397.1 | 63143 | 1.64041666667 | 13600 |
| 013870 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:55am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595649.9 | 510396.9 | 63145 | 1.64041666667 | 13870 |
| 012527 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:56am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595648.0 | 510395.7 | 63147 | 1.64041666667 | 12527 |
| 015191 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:57am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595645.5 | 510394.7 | 63149 | 1.64041666667 | 15191 |
| 015378 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:58am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595643.7 | 510393.8 | 63151 | 1.64041666667 | 15378 |
| 013204 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:59am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595641.5 | 510393.2 | 63153 | 1.64041666667 | 13204 |
| 012151 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:00am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595640.0 | 510392.4 | 63155 | 1.64041666667 | 12151 |
| 012877 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:01am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595638.2 | 510391.3 | 63157 | 1.64041666667 | 12877 |
| 013509 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:02am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595636.8 | 510390.2 | 63159 | 1.64041666667 | 13509 |
| 012827 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:03am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595635.5 | 510389.4 | 63161 | 1.64041666667 | 12827 |
| 011996 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:04am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595634.0 | 510389.3 | 63163 | 1.64041666667 | 11996 |
| 013709 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:05am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595632.7 | 510388.1 | 63165 | 1.64041666667 | 13709 |
| 012007 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:06am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595632.7 | 510387.8 | 63167 | 1.64041666667 | 12007 |
| 013741 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:07am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595632.9 | 510387.7 | 63169 | 1.64041666667 | 13741 |
| 014235 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:08am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595631.3 | 510387.4 | 63171 | 1.64041666667 | 14235 |
| 012828 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:09am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595630.2 | 510387.5 | 63173 | 1.64041666667 | 12828 |
| 013377 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:10am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595629.4 | 510386.4 | 63175 | 1.64041666667 | 13377 |
| 011684 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:11am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595628.3 | 510385.2 | 63177 | 1.64041666667 | 11684 |
| 012671 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:12am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595626.4 | 510384.8 | 63179 | 1.64041666667 | 12671 |
| 012407 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:13am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595624.0 | 510383.9 | 63181 | 1.64041666667 | 12407 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595621.9 | 510383.4 | 63183 | 1.64041666667 | 13451 |
| 014673 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:15am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595619.2 | 510382.8 | 63185 | 1.64041666667 | 14673 |
| 012968 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:16am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595617.0 | 510381.4 | 63187 | 1.64041666667 | 12968 |
| 012512 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595614.2 | 510379.5 | 63189 | 1.64041666667 | 12512 |
| 013388 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595611.9 | 510378.0 | 63191 | 1.64041666667 | 13388 |
| 012227 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595609.4 | 510376.5 | 63193 | 1.64041666667 | 12227 |
| 012416 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595607.1 | 510374.9 | 63195 | 1.64041666667 | 12416 |
| 012764 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595604.6 | 510372.6 | 63197 | 1.64041666667 | 12764 |
| 013421 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595602.0 | 510370.7 | 63199 | 1.64041666667 | 13421 |
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595599.8 | 510368.3 | 63201 | 1.64041666667 | 13795 |
| 012898 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595598.0 | 510366.2 | 63203 | 1.64041666667 | 12898 |
| 012734 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595596.2 | 510364.0 | 63205 | 1.64041666667 | 12734 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595594.3 | 510361.7 | 63207 | 1.64041666667 | 13593 |
| 015038 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595590.8 | 510359.9 | 63209 | 1.64041666667 | 15038 |
| 015009 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:28am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595588.8 | 510358.9 | 63211 | 1.64041666667 | 15009 |
| 013202 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:29am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595585.8 | 510357.9 | 63213 | 1.64041666667 | 13202 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595583.8 | 510356.8 | 63215 | 1.64041666667 | 12420 |
| 012525 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595580.7 | 510355.2 | 63217 | 1.64041666667 | 12525 |
| 014261 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595577.8 | 510354.0 | 63219 | 1.64041666667 | 14261 |
| 012595 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595574.7 | 510352.8 | 63221 | 1.64041666667 | 12595 |
| 011309 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595571.7 | 510351.9 | 63223 | 1.64041666667 | 11309 |
| 011707 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595568.6 | 510350.6 | 63225 | 1.64041666667 | 11707 |
| 011986 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595566.2 | 510349.7 | 63227 | 1.64041666667 | 11986 |
| 012386 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595563.4 | 510348.4 | 63229 | 1.64041666667 | 12386 |
| 012756 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595561.0 | 510347.0 | 63231 | 1.64041666667 | 12756 |
| 012609 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595557.7 | 510345.5 | 63233 | 1.64041666667 | 12609 |
| 011852 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595554.8 | 510344.0 | 63235 | 1.64041666667 | 11852 |
| 011903 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595552.1 | 510343.1 | 63237 | 1.64041666667 | 11903 |
| 013505 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595549.7 | 510342.1 | 63239 | 1.64041666667 | 13505 |
| 013276 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595546.7 | 510340.7 | 63241 | 1.64041666667 | 13276 |
| 013669 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595546.1 | 510340.9 | 63243 | 1.64041666667 | 13669 |
| 012957 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595546.5 | 510342.1 | 63245 | 1.64041666667 | 12957 |
| 012599 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595547.3 | 510342.1 | 63247 | 1.64041666667 | 12599 |
| 011250 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595549.7 | 510340.9 | 63249 | 1.64041666667 | 11250 |
| 012472 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595551.4 | 510340.3 | 63251 | 1.64041666667 | 12472 |
| 012898 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595552.0 | 510340.1 | 63253 | 1.64041666667 | 12898 |
| 014504 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595553.0 | 510339.0 | 63255 | 1.64041666667 | 14504 |
| 013016 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595555.4 | 510337.4 | 63257 | 1.64041666667 | 13016 |
| 012614 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595557.7 | 510336.1 | 63259 | 1.64041666667 | 12614 |
| 013713 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595558.8 | 510335.3 | 63261 | 1.64041666667 | 13713 |
| 011768 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595558.4 | 510335.4 | 63263 | 1.64041666667 | 11768 |
| 011432 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595557.0 | 510335.7 | 63265 | 1.64041666667 | 11432 |
| 012976 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595556.6 | 510335.6 | 63267 | 1.64041666667 | 12976 |
| 012587 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595555.9 | 510336.3 | 63269 | 1.64041666667 | 12587 |
| 011846 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595553.8 | 510337.7 | 63271 | 1.64041666667 | 11846 |
| 012801 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595552.4 | 510338.7 | 63273 | 1.64041666667 | 12801 |
| 011930 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595551.5 | 510339.6 | 63275 | 1.64041666667 | 11930 |
| 013332 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595552.0 | 510340.4 | 63277 | 1.64041666667 | 13332 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012543 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595553.8 | 510341.7 | 63279 | 1.64041666667 | 12543 |
| 013425 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595556.6 | 510343.5 | 63281 | 1.64041666667 | 13425 |
| 013646 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595558.8 | 510344.9 | 63283 | 1.64041666667 | 13646 |
| 013941 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595561.3 | 510346.5 | 63285 | 1.64041666667 | 13941 |
| 013325 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595563.6 | 510347.9 | 63287 | 1.64041666667 | 13325 |
| 012331 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595566.5 | 510349.6 | 63289 | 1.64041666667 | 12331 |
| 012412 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595569.2 | 510350.8 | 63291 | 1.64041666667 | 12412 |
| 013663 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595572.0 | 510352.0 | 63293 | 1.64041666667 | 13663 |
| 014126 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595574.2 | 510352.7 | 63295 | 1.64041666667 | 14126 |
| 011991 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595576.9 | 510354.1 | 63297 | 1.64041666667 | 11991 |
| 012057 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595579.1 | 510355.1 | 63299 | 1.64041666667 | 12057 |
| 012314 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595581.7 | 510356.0 | 63301 | 1.64041666667 | 12314 |
| 012408 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595583.9 | 510357.1 | 63303 | 1.64041666667 | 12408 |
| 015222 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:15am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595586.8 | 510358.3 | 63305 | 1.64041666667 | 15222 |
| 014605 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:16am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595589.2 | 510359.3 | 63307 | 1.64041666667 | 14605 |
| 011601 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:17am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595592.1 | 510360.4 | 63309 | 1.64041666667 | 11601 |
| 013040 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:18am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595594.1 | 510361.4 | 63311 | 1.64041666667 | 13040 |
| 014510 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595596.2 | 510362.9 | 63313 | 1.64041666667 | 14510 |
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595597.2 | 510363.7 | 63315 | 1.64041666667 | 13795 |
| 013994 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595597.2 | 510363.9 | 63317 | 1.64041666667 | 13994 |
| 013188 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595597.2 | 510363.9 | 63319 | 1.64041666667 | 13188 |
| 013497 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595597.0 | 510364.2 | 63321 | 1.64041666667 | 13497 |
| 012944 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595596.9 | 510364.3 | 63323 | 1.64041666667 | 12944 |
| 013856 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595597.4 | 510364.5 | 63325 | 1.64041666667 | 13856 |
| 012194 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595598.9 | 510365.4 | 63327 | 1.64041666667 | 12194 |
| 013518 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595601.2 | 510366.9 | 63329 | 1.64041666667 | 13518 |
| 014509 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595602.8 | 510368.3 | 63331 | 1.64041666667 | 14509 |
| 013677 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595605.6 | 510369.7 | 63333 | 1.64041666667 | 13677 |
| 013199 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595607.6 | 510371.2 | 63335 | 1.64041666667 | 13199 |
| 013590 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595610.1 | 510372.6 | 63337 | 1.64041666667 | 13590 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595612.4 | 510373.4 | 63339 | 1.64041666667 | 13297 |
| 011934 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595615.7 | 510374.4 | 63341 | 1.64041666667 | 11934 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595618.3 | 510375.3 | 63343 | 1.64041666667 | 11953 |
| 014118 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595621.3 | 510376.9 | 63345 | 1.64041666667 | 14118 |
| 013369 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595623.8 | 510377.8 | 63347 | 1.64041666667 | 13369 |
| 013272 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595626.5 | 510378.6 | 63349 | 1.64041666667 | 13272 |
| 013008 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595628.8 | 510379.4 | 63351 | 1.64041666667 | 13008 |
| 012852 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595630.9 | 510380.8 | 63353 | 1.64041666667 | 12852 |
| 014043 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595632.8 | 510382.3 | 63355 | 1.64041666667 | 14043 |
| 012720 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595634.9 | 510384.4 | 63357 | 1.64041666667 | 12720 |
| 013830 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595637.2 | 510385.5 | 63359 | 1.64041666667 | 13830 |
| 013057 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595640.5 | 510386.4 | 63361 | 1.64041666667 | 13057 |
| 012114 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595642.8 | 510387.6 | 63363 | 1.64041666667 | 12114 |
| 014488 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595645.6 | 510389.2 | 63365 | 1.64041666667 | 14488 |
| 014062 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595647.8 | 510390.4 | 63367 | 1.64041666667 | 14062 |
| 012815 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595650.5 | 510391.7 | 63369 | 1.64041666667 | 12815 |
| 013733 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595652.7 | 510392.2 | 63371 | 1.64041666667 | 13733 |
| 013183 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595654.8 | 510391.9 | 63373 | 1.64041666667 | 13183 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013286 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595655.5 | 510392.1 | 63375 | 1.64041666667 | 13286 |
| 013581 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595655.8 | 510393.0 | 63377 | 1.64041666667 | 13581 |
| 012515 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595655.5 | 510393.1 | 63379 | 1.64041666667 | 12515 |
| 013238 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595655.6 | 510392.5 | 63381 | 1.64041666667 | 13238 |
| 013389 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595656.0 | 510391.9 | 63383 | 1.64041666667 | 13389 |
| 013907 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595657.3 | 510390.2 | 63385 | 1.64041666667 | 13907 |
| 013076 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595658.7 | 510388.4 | 63387 | 1.64041666667 | 13076 |
| 012899 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595659.5 | 510387.1 | 63389 | 1.64041666667 | 12899 |
| 012105 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.4 | 510386.2 | 63391 | 1.64041666667 | 12105 |
| 012896 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595662.3 | 510385.0 | 63393 | 1.64041666667 | 12896 |
| 013874 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595663.4 | 510384.6 | 63395 | 1.64041666667 | 13874 |
| 012198 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595663.5 | 510384.6 | 63397 | 1.64041666667 | 12198 |
| 012889 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595663.0 | 510384.1 | 63399 | 1.64041666667 | 12889 |
| 013692 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595663.9 | 510383.2 | 63401 | 1.64041666667 | 13692 |
| 014343 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:04am | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595664.9 | 510382.9 | 63403 | 1.64041666667 | 14343 |
| 012285 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:05am | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595665.2 | 510382.9 | 63405 | 1.64041666667 | 12285 |
| 014591 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595664.2 | 510383.4 | 63407 | 1.64041666667 | 14591 |
| 014598 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595663.8 | 510383.5 | 63409 | 1.64041666667 | 14598 |
| 015139 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595663.4 | 510383.7 | 63411 | 1.64041666667 | 15139 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595661.6 | 510384.8 | 63413 | 1.64041666667 | 12454 |
| 014243 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.9 | 510384.9 | 63415 | 1.64041666667 | 14243 |
| 013881 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.8 | 510384.9 | 63417 | 1.64041666667 | 13881 |
| 013100 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.6 | 510384.9 | 63419 | 1.64041666667 | 13100 |
| 013565 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.4 | 510384.8 | 63421 | 1.64041666667 | 13565 |
| 013471 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.3 | 510384.8 | 63423 | 1.64041666667 | 13471 |
| 013807 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.3 | 510384.8 | 63425 | 1.64041666667 | 13807 |
| 013172 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.4 | 510384.9 | 63427 | 1.64041666667 | 13172 |
| 013133 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.4 | 510384.8 | 63429 | 1.64041666667 | 13133 |
| 012373 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.5 | 510384.8 | 63431 | 1.64041666667 | 12373 |
| 012153 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.5 | 510384.9 | 63433 | 1.64041666667 | 12153 |
| 012938 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.9 | 63435 | 1.64041666667 | 12938 |
| 012354 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.3 | 510384.8 | 63437 | 1.64041666667 | 12354 |
| 014758 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.3 | 510384.8 | 63439 | 1.64041666667 | 14758 |
| 012809 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.4 | 510384.9 | 63441 | 1.64041666667 | 12809 |
| 014002 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.5 | 510384.9 | 63443 | 1.64041666667 | 14002 |
| 014090 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.6 | 510384.9 | 63445 | 1.64041666667 | 14090 |
| 013182 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.6 | 510384.9 | 63447 | 1.64041666667 | 13182 |
| 012685 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.9 | 63449 | 1.64041666667 | 12685 |
| 012351 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.5 | 510384.9 | 63451 | 1.64041666667 | 12351 |
| 013377 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.6 | 510384.9 | 63453 | 1.64041666667 | 13377 |
| 012434 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.6 | 510384.9 | 63455 | 1.64041666667 | 12434 |
| 013488 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63457 | 1.64041666667 | 13488 |
| 012462 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63459 | 1.64041666667 | 12462 |
| 011695 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.4 | 510384.7 | 63461 | 1.64041666667 | 11695 |
| 012434 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.3 | 510384.7 | 63463 | 1.64041666667 | 12434 |
| 013068 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63465 | 1.64041666667 | 13068 |
| 012237 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.6 | 510384.8 | 63467 | 1.64041666667 | 12237 |
| 013349 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.5 | 510384.8 | 63469 | 1.64041666667 | 13349 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.5 | 510384.8 | 63471 | 1.64041666667 | 12937 |
| 013494 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63473 | 1.64041666667 | 13494 |
| 013063 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.9 | 63475 | 1.64041666667 | 13063 |
| 013676 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63477 | 1.64041666667 | 13676 |
| 013079 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63479 | 1.64041666667 | 13079 |
| 012509 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63481 | 1.64041666667 | 12509 |
| 014197 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63483 | 1.64041666667 | 14197 |
| 012849 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63485 | 1.64041666667 | 12849 |
| 011072 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63487 | 1.64041666667 | 11072 |
| 012008 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63489 | 1.64041666667 | 12008 |
| 011102 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63491 | 1.64041666667 | 11102 |
| 012645 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63493 | 1.64041666667 | 12645 |
| 014441 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63495 | 1.64041666667 | 14441 |
| 013420 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.5 | 510384.8 | 63497 | 1.64041666667 | 13420 |
| 012325 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.5 | 510384.9 | 63499 | 1.64041666667 | 12325 |
| 012441 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.4 | 510385.9 | 63501 | 1.64041666667 | 12441 |
| 013190 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.3 | 510386.6 | 63503 | 1.64041666667 | 13190 |
| 011667 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.3 | 510386.7 | 63505 | 1.64041666667 | 11667 |
| 012877 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.2 | 510386.7 | 63507 | 1.64041666667 | 12877 |
| 013269 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.2 | 510386.7 | 63509 | 1.64041666667 | 13269 |
| 012617 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.7 | 63511 | 1.64041666667 | 12617 |
| 013444 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.7 | 63513 | 1.64041666667 | 13444 |
| 012511 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.7 | 63515 | 1.64041666667 | 12511 |
| 012817 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.7 | 63517 | 1.64041666667 | 12817 |
| 011724 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.7 | 63519 | 1.64041666667 | 11724 |
| 013881 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.0 | 510386.7 | 63521 | 1.64041666667 | 13881 |
| 012440 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.0 | 510386.7 | 63523 | 1.64041666667 | 12440 |
| 013910 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.8 | 63525 | 1.64041666667 | 13910 |
| 013257 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.8 | 63527 | 1.64041666667 | 13257 |
| 012854 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.8 | 63529 | 1.64041666667 | 12854 |
| 012933 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.8 | 63531 | 1.64041666667 | 12933 |
| 012953 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.8 | 63533 | 1.64041666667 | 12953 |
| 012328 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.8 | 63535 | 1.64041666667 | 12328 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.1 | 510386.8 | 63537 | 1.64041666667 | 11962 |
| 011090 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.1 | 510386.8 | 63539 | 1.64041666667 | 11090 |
| 013692 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.2 | 510386.8 | 63541 | 1.64041666667 | 13692 |
| 011043 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.4 | 510386.8 | 63543 | 1.64041666667 | 11043 |
| 014100 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595661.0 | 510386.7 | 63545 | 1.64041666667 | 14100 |
| 013305 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:16am | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595661.6 | 510386.8 | 63547 | 1.64041666667 | 13305 |
| 013286 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595661.5 | 510386.7 | 63549 | 1.64041666667 | 13286 |
| 012801 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.8 | 510386.2 | 63551 | 1.64041666667 | 12801 |
| 013730 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.5 | 510385.6 | 63553 | 1.64041666667 | 13730 |
| 014592 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595660.8 | 510385.4 | 63555 | 1.64041666667 | 14592 |
| 013458 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595660.9 | 510385.4 | 63557 | 1.64041666667 | 13458 |
| 011764 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595661.0 | 510386.0 | 63559 | 1.64041666667 | 11764 |
| 011911 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595660.7 | 510386.6 | 63561 | 1.64041666667 | 11911 |
| 013417 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595659.6 | 510385.9 | 63563 | 1.64041666667 | 13417 |
| 013794 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595657.9 | 510383.9 | 63565 | 1.64041666667 | 13794 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011698 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595656.1 | 510382.0 | 63567 | 1.64041666667 | 11698 |
| 014504 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595654.5 | 510380.3 | 63569 | 1.64041666667 | 14504 |
| 013196 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595653.0 | 510379.1 | 63571 | 1.64041666667 | 13196 |
| 013289 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595651.2 | 510377.5 | 63573 | 1.64041666667 | 13289 |
| 013732 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595649.3 | 510375.9 | 63575 | 1.64041666667 | 13732 |
| 013003 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:31am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595647.7 | 510374.4 | 63577 | 1.64041666667 | 13003 |
| 012730 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595646.0 | 510373.3 | 63579 | 1.64041666667 | 12730 |
| 013652 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595644.5 | 510371.8 | 63581 | 1.64041666667 | 13652 |
| 012833 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595643.1 | 510370.4 | 63583 | 1.64041666667 | 12833 |
| 013738 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595641.4 | 510368.4 | 63585 | 1.64041666667 | 13738 |
| 011924 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595639.8 | 510366.6 | 63587 | 1.64041666667 | 11924 |
| 013571 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595637.8 | 510364.9 | 63589 | 1.64041666667 | 13571 |
| 013142 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595636.0 | 510363.4 | 63591 | 1.64041666667 | 13142 |
| 014745 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595633.5 | 510362.0 | 63593 | 1.64041666667 | 14745 |
| 014396 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595630.9 | 510361.4 | 63595 | 1.64041666667 | 14396 |
| 014399 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595627.4 | 510360.9 | 63597 | 1.64041666667 | 14399 |
| 012480 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595624.6 | 510360.1 | 63599 | 1.64041666667 | 12480 |
| 012000 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595621.3 | 510359.1 | 63601 | 1.64041666667 | 12000 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595619.0 | 510358.2 | 63603 | 1.64041666667 | 12420 |
| 013065 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595616.2 | 510356.9 | 63605 | 1.64041666667 | 13065 |
| 012896 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595613.6 | 510355.8 | 63607 | 1.64041666667 | 12896 |
| 013034 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:47am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595610.2 | 510354.0 | 63609 | 1.64041666667 | 13034 |
| 012828 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:48am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595607.5 | 510353.6 | 63611 | 1.64041666667 | 12828 |
| 012057 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:49am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595604.6 | 510353.5 | 63613 | 1.64041666667 | 12057 |
| 012284 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:50am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595602.1 | 510353.3 | 63615 | 1.64041666667 | 12284 |
| 013541 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:51am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595599.0 | 510353.1 | 63617 | 1.64041666667 | 13541 |
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:52am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595596.8 | 510352.8 | 63619 | 1.64041666667 | 13795 |
| 013798 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595594.6 | 510352.3 | 63621 | 1.64041666667 | 13798 |
| 013859 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595592.5 | 510351.1 | 63623 | 1.64041666667 | 13859 |
| 013155 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595589.1 | 510348.8 | 63625 | 1.64041666667 | 13155 |
| 012438 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595586.6 | 510347.2 | 63627 | 1.64041666667 | 12438 |
| 011449 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595583.4 | 510345.4 | 63629 | 1.64041666667 | 11449 |
| 012972 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595580.8 | 510344.2 | 63631 | 1.64041666667 | 12972 |
| 015543 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595577.4 | 510342.3 | 63633 | 1.64041666667 | 15543 |
| 011985 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595574.9 | 510341.5 | 63635 | 1.64041666667 | 11985 |
| 011546 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595571.8 | 510340.4 | 63637 | 1.64041666667 | 11546 |
| 012546 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595569.2 | 510339.5 | 63639 | 1.64041666667 | 12546 |
| 014746 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595566.0 | 510338.6 | 63641 | 1.64041666667 | 14746 |
| 010676 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595563.3 | 510337.2 | 63643 | 1.64041666667 | 10676 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595560.9 | 510335.8 | 63645 | 1.64041666667 | 12539 |
| 012795 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595560.0 | 510335.6 | 63647 | 1.64041666667 | 12795 |
| 013578 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595560.3 | 510335.9 | 63649 | 1.64041666667 | 13578 |
| 013234 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595560.5 | 510336.0 | 63651 | 1.64041666667 | 13234 |
| 011678 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595560.5 | 510336.1 | 63653 | 1.64041666667 | 11678 |
| 011289 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595560.5 | 510336.1 | 63655 | 1.64041666667 | 11289 |
| 011312 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595560.5 | 510336.1 | 63657 | 1.64041666667 | 11312 |
| 011348 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595560.4 | 510336.1 | 63659 | 1.64041666667 | 11348 |
| 013427 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595560.5 | 510336.1 | 63661 | 1.64041666667 | 13427 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014726 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595560.5 | 510335.9 | 63663 | 1.64041666667 | 14726 |
| 012591 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595559.7 | 510334.9 | 63665 | 1.64041666667 | 12591 |
| 012718 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595559.3 | 510334.7 | 63667 | 1.64041666667 | 12718 |
| 014309 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595559.3 | 510334.2 | 63669 | 1.64041666667 | 14309 |
| 013357 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595558.8 | 510332.6 | 63671 | 1.64041666667 | 13357 |
| 013659 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:19am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595559.2 | 510330.6 | 63673 | 1.64041666667 | 13659 |
| 013794 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:20am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595560.1 | 510329.9 | 63675 | 1.64041666667 | 13794 |
| 012628 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:21am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595560.4 | 510329.6 | 63677 | 1.64041666667 | 12628 |
| 012307 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:22am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595561.1 | 510328.6 | 63679 | 1.64041666667 | 12307 |
| 014926 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595563.4 | 510326.8 | 63681 | 1.64041666667 | 14926 |
| 011921 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595565.3 | 510326.1 | 63683 | 1.64041666667 | 11921 |
| 011980 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595565.9 | 510326.2 | 63685 | 1.64041666667 | 11980 |
| 013345 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595565.7 | 510326.1 | 63687 | 1.64041666667 | 13345 |
| 012696 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:27am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595564.4 | 510325.7 | 63689 | 1.64041666667 | 12696 |
| 013704 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:28am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595562.9 | 510326.0 | 63691 | 1.64041666667 | 13704 |
| 013326 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:29am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595561.2 | 510327.1 | 63693 | 1.64041666667 | 13326 |
| 011941 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:30am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595560.3 | 510327.6 | 63695 | 1.64041666667 | 11941 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:31am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595560.2 | 510327.8 | 63697 | 1.64041666667 | 12975 |
| 012993 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:32am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595560.7 | 510328.0 | 63699 | 1.64041666667 | 12993 |
| 011468 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:33am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595561.6 | 510328.7 | 63701 | 1.64041666667 | 11468 |
| 012377 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595562.7 | 510329.8 | 63703 | 1.64041666667 | 12377 |
| 012484 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595564.6 | 510331.5 | 63705 | 1.64041666667 | 12484 |
| 012811 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595566.5 | 510333.1 | 63707 | 1.64041666667 | 12811 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595568.7 | 510334.9 | 63709 | 1.64041666667 | 12742 |
| 013085 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595570.8 | 510336.5 | 63711 | 1.64041666667 | 13085 |
| 013321 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595573.2 | 510338.5 | 63713 | 1.64041666667 | 13321 |
| 014100 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595575.3 | 510340.0 | 63715 | 1.64041666667 | 14100 |
| 012645 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595578.2 | 510341.2 | 63717 | 1.64041666667 | 12645 |
| 011801 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595580.5 | 510342.5 | 63719 | 1.64041666667 | 11801 |
| 011350 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595583.3 | 510343.4 | 63721 | 1.64041666667 | 11350 |
| 011297 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595585.4 | 510343.9 | 63723 | 1.64041666667 | 11297 |
| 012664 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595588.0 | 510344.3 | 63725 | 1.64041666667 | 12664 |
| 012016 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595590.1 | 510345.2 | 63727 | 1.64041666667 | 12016 |
| 012154 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595592.6 | 510346.7 | 63729 | 1.64041666667 | 12154 |
| 013628 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595594.4 | 510348.1 | 63731 | 1.64041666667 | 13628 |
| 013247 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595596.2 | 510350.1 | 63733 | 1.64041666667 | 13247 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595598.5 | 510351.8 | 63735 | 1.64041666667 | 12401 |
| 011680 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595600.8 | 510353.0 | 63737 | 1.64041666667 | 11680 |
| 011950 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595603.0 | 510353.8 | 63739 | 1.64041666667 | 11950 |
| 011507 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595606.1 | 510354.8 | 63741 | 1.64041666667 | 11507 |
| 013406 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595609.1 | 510355.4 | 63743 | 1.64041666667 | 13406 |
| 013131 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595611.4 | 510357.1 | 63745 | 1.64041666667 | 13131 |
| 013543 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595613.2 | 510358.8 | 63747 | 1.64041666667 | 13543 |
| 012955 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595616.3 | 510360.7 | 63749 | 1.64041666667 | 12955 |
| 013649 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595619.0 | 510361.9 | 63751 | 1.64041666667 | 13649 |
| 013162 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595622.4 | 510363.1 | 63753 | 1.64041666667 | 13162 |
| 012620 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595625.0 | 510364.4 | 63755 | 1.64041666667 | 12620 |
| 011915 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595627.7 | 510366.1 | 63757 | 1.64041666667 | 11915 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012278 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595630.0 | 510367.4 | 63759 | 1.64041666667 | 12278 |
| 012759 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595633.0 | 510369.3 | 63761 | 1.64041666667 | 12759 |
| 013060 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595635.4 | 510370.4 | 63763 | 1.64041666667 | 13060 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595637.9 | 510371.6 | 63765 | 1.64041666667 | 12475 |
| 012178 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595639.8 | 510372.6 | 63767 | 1.64041666667 | 12178 |
| 012914 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595642.7 | 510373.9 | 63769 | 1.64041666667 | 12914 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595645.2 | 510374.9 | 63771 | 1.64041666667 | 12678 |
| 013219 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595647.4 | 510376.3 | 63773 | 1.64041666667 | 13219 |
| 012514 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595649.3 | 510377.9 | 63775 | 1.64041666667 | 12514 |
| 012038 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595652.0 | 510380.0 | 63777 | 1.64041666667 | 12038 |
| 013119 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595654.2 | 510380.9 | 63779 | 1.64041666667 | 13119 |
| 012670 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595657.4 | 510381.3 | 63781 | 1.64041666667 | 12670 |
| 011957 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595659.7 | 510382.2 | 63783 | 1.64041666667 | 11957 |
| 012859 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595663.1 | 510383.0 | 63785 | 1.64041666667 | 12859 |
| 013234 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595664.8 | 510383.1 | 63787 | 1.64041666667 | 13234 |
| 014408 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595665.4 | 510383.2 | 63789 | 1.64041666667 | 14408 |
| 013742 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595666.7 | 510381.8 | 63791 | 1.64041666667 | 13742 |
| 014745 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595668.2 | 510379.2 | 63793 | 1.64041666667 | 14745 |
| 013736 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595668.7 | 510377.9 | 63795 | 1.64041666667 | 13736 |
| 014804 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595669.1 | 510376.1 | 63797 | 1.64041666667 | 14804 |
| 013661 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595670.1 | 510373.7 | 63799 | 1.64041666667 | 13661 |
| 014185 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595670.7 | 510371.9 | 63801 | 1.64041666667 | 14185 |
| 014886 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595670.6 | 510372.6 | 63803 | 1.64041666667 | 14886 |
| 014551 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595670.4 | 510374.1 | 63805 | 1.64041666667 | 14551 |
| 014077 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595670.8 | 510374.6 | 63807 | 1.64041666667 | 14077 |
| 014499 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595670.5 | 510375.7 | 63809 | 1.64041666667 | 14499 |
| 013555 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595669.0 | 510376.3 | 63811 | 1.64041666667 | 13555 |
| 012538 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595666.5 | 510375.7 | 63813 | 1.64041666667 | 12538 |
| 013364 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595664.3 | 510374.7 | 63815 | 1.64041666667 | 13364 |
| 014831 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595661.7 | 510372.7 | 63817 | 1.64041666667 | 14831 |
| 013667 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595659.1 | 510371.1 | 63819 | 1.64041666667 | 13667 |
| 012386 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595656.6 | 510369.5 | 63821 | 1.64041666667 | 12386 |
| 012876 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595654.6 | 510368.1 | 63823 | 1.64041666667 | 12876 |
| 012279 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595651.9 | 510366.6 | 63825 | 1.64041666667 | 12279 |
| 012759 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595649.5 | 510365.7 | 63827 | 1.64041666667 | 12759 |
| 013420 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595646.3 | 510365.0 | 63829 | 1.64041666667 | 13420 |
| 013945 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595643.6 | 510363.6 | 63831 | 1.64041666667 | 13945 |
| 014466 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595640.4 | 510362.1 | 63833 | 1.64041666667 | 14466 |
| 013516 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595638.4 | 510360.9 | 63835 | 1.64041666667 | 13516 |
| 013519 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595636.4 | 510358.8 | 63837 | 1.64041666667 | 13519 |
| 013429 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595634.4 | 510357.3 | 63839 | 1.64041666667 | 13429 |
| 013767 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595631.6 | 510355.6 | 63841 | 1.64041666667 | 13767 |
| 013192 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595628.7 | 510354.7 | 63843 | 1.64041666667 | 13192 |
| 012718 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595625.3 | 510354.1 | 63845 | 1.64041666667 | 12718 |
| 011909 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595623.0 | 510352.9 | 63847 | 1.64041666667 | 11909 |
| 011527 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595620.2 | 510351.1 | 63849 | 1.64041666667 | 11527 |
| 013081 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595617.7 | 510348.9 | 63851 | 1.64041666667 | 13081 |
| 013530 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595615.0 | 510346.7 | 63853 | 1.64041666667 | 13530 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595612.7 | 510344.8 | 63855 | 1.64041666667 | 12562 |
| 012080 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595610.2 | 510342.6 | 63857 | 1.64041666667 | 12080 |
| 011990 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595607.3 | 510340.8 | 63859 | 1.64041666667 | 11990 |
| 011337 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595604.4 | 510339.3 | 63861 | 1.64041666667 | 11337 |
| 014984 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595601.9 | 510338.4 | 63863 | 1.64041666667 | 14984 |
| 014336 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595598.7 | 510337.8 | 63865 | 1.64041666667 | 14336 |
| 013334 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595595.8 | 510336.8 | 63867 | 1.64041666667 | 13334 |
| 014103 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595592.3 | 510335.4 | 63869 | 1.64041666667 | 14103 |
| 013905 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595589.9 | 510334.2 | 63871 | 1.64041666667 | 13905 |
| 012716 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595587.0 | 510332.1 | 63873 | 1.64041666667 | 12716 |
| 012629 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595584.2 | 510330.5 | 63875 | 1.64041666667 | 12629 |
| 011917 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595581.2 | 510328.8 | 63877 | 1.64041666667 | 11917 |
| 012759 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595578.4 | 510327.9 | 63879 | 1.64041666667 | 12759 |
| 012759 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595575.0 | 510327.6 | 63881 | 1.64041666667 | 12759 |
| 014410 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595571.9 | 510326.8 | 63883 | 1.64041666667 | 14410 |
| 013772 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595568.9 | 510325.9 | 63885 | 1.64041666667 | 13772 |
| 012443 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595567.2 | 510325.3 | 63887 | 1.64041666667 | 12443 |
| 012230 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595567.8 | 510325.0 | 63889 | 1.64041666667 | 12230 |
| 012717 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595569.3 | 510323.9 | 63891 | 1.64041666667 | 12717 |
| 011249 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595571.0 | 510322.7 | 63893 | 1.64041666667 | 11249 |
| 012172 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595572.0 | 510323.3 | 63895 | 1.64041666667 | 12172 |
| 012223 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595572.2 | 510323.5 | 63897 | 1.64041666667 | 12223 |
| 013075 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595572.9 | 510322.3 | 63899 | 1.64041666667 | 13075 |
| 013949 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595574.9 | 510320.6 | 63901 | 1.64041666667 | 13949 |
| 013357 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595577.1 | 510319.6 | 63903 | 1.64041666667 | 13357 |
| 013359 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595578.3 | 510319.1 | 63905 | 1.64041666667 | 13359 |
| 014919 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595578.4 | 510319.1 | 63907 | 1.64041666667 | 14919 |
| 013510 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595578.4 | 510319.1 | 63909 | 1.64041666667 | 13510 |
| 013097 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595578.2 | 510319.2 | 63911 | 1.64041666667 | 13097 |
| 013384 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595578.4 | 510319.2 | 63913 | 1.64041666667 | 13384 |
| 013066 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:20am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595578.9 | 510319.2 | 63915 | 1.64041666667 | 13066 |
| 012266 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:21am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595578.9 | 510319.1 | 63917 | 1.64041666667 | 12266 |
| 013566 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:22am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595578.9 | 510319.1 | 63919 | 1.64041666667 | 13566 |
| 012901 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595578.0 | 510319.0 | 63921 | 1.64041666667 | 12901 |
| 013635 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595576.5 | 510318.6 | 63923 | 1.64041666667 | 13635 |
| 013698 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595575.2 | 510319.3 | 63925 | 1.64041666667 | 13698 |
| 014974 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595574.0 | 510320.9 | 63927 | 1.64041666667 | 14974 |
| 013433 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595573.7 | 510322.0 | 63929 | 1.64041666667 | 13433 |
| 013558 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595575.1 | 510323.4 | 63931 | 1.64041666667 | 13558 |
| 012689 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595577.1 | 510325.7 | 63933 | 1.64041666667 | 12689 |
| 012292 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595579.6 | 510327.5 | 63935 | 1.64041666667 | 12292 |
| 011713 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595582.6 | 510329.1 | 63937 | 1.64041666667 | 11713 |
| 011328 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595585.3 | 510330.0 | 63939 | 1.64041666667 | 11328 |
| 011442 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595588.5 | 510331.3 | 63941 | 1.64041666667 | 11442 |
| 012880 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595590.9 | 510332.5 | 63943 | 1.64041666667 | 12880 |
| 013120 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595594.2 | 510333.8 | 63945 | 1.64041666667 | 13120 |
| 013540 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595596.7 | 510335.3 | 63947 | 1.64041666667 | 13540 |
| 012175 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595599.9 | 510337.1 | 63949 | 1.64041666667 | 12175 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012853 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595602.1 | 510338.4 | 63951 | 1.64041666667 | 12853 |
| 013563 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595604.7 | 510339.9 | 63953 | 1.64041666667 | 13563 |
| 012060 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595607.3 | 510340.9 | 63955 | 1.64041666667 | 12060 |
| 013815 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595610.1 | 510342.8 | 63957 | 1.64041666667 | 13815 |
| 012843 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595612.1 | 510344.5 | 63959 | 1.64041666667 | 12843 |
| 013231 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595615.0 | 510345.9 | 63961 | 1.64041666667 | 13231 |
| 012727 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595617.9 | 510346.9 | 63963 | 1.64041666667 | 12727 |
| 012182 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595621.4 | 510347.4 | 63965 | 1.64041666667 | 12182 |
| 012345 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595623.9 | 510347.7 | 63967 | 1.64041666667 | 12345 |
| 013316 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595626.4 | 510349.0 | 63969 | 1.64041666667 | 13316 |
| 012119 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595628.8 | 510350.6 | 63971 | 1.64041666667 | 12119 |
| 012660 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595631.6 | 510353.0 | 63973 | 1.64041666667 | 12660 |
| 012915 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595634.3 | 510354.2 | 63975 | 1.64041666667 | 12915 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595637.8 | 510354.8 | 63977 | 1.64041666667 | 12378 |
| 012034 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595640.5 | 510355.3 | 63979 | 1.64041666667 | 12034 |
| 011918 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595644.2 | 510356.1 | 63981 | 1.64041666667 | 11918 |
| 013089 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595647.0 | 510357.3 | 63983 | 1.64041666667 | 13089 |
| 012662 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595649.6 | 510358.8 | 63985 | 1.64041666667 | 12662 |
| 012345 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595652.1 | 510360.1 | 63987 | 1.64041666667 | 12345 |
| 015236 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595654.4 | 510361.9 | 63989 | 1.64041666667 | 15236 |
| 015209 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595656.6 | 510363.7 | 63991 | 1.64041666667 | 15209 |
| 014332 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595658.9 | 510365.8 | 63993 | 1.64041666667 | 14332 |
| 013693 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595660.7 | 510367.6 | 63995 | 1.64041666667 | 13693 |
| 013173 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595664.1 | 510369.3 | 63997 | 1.64041666667 | 13173 |
| 013763 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:02am | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595666.6 | 510370.6 | 63999 | 1.64041666667 | 13763 |
| 013010 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595669.2 | 510371.5 | 64001 | 1.64041666667 | 13010 |
| 012672 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:04am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595670.9 | 510371.4 | 64003 | 1.64041666667 | 12672 |
| 015048 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:05am | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595671.0 | 510371.6 | 64005 | 1.64041666667 | 15048 |
| 013392 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595671.1 | 510371.0 | 64007 | 1.64041666667 | 13392 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595672.5 | 510368.1 | 64009 | 1.64041666667 | 14538 |
| 012634 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595673.2 | 510366.5 | 64011 | 1.64041666667 | 12634 |
| 013808 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595674.0 | 510365.1 | 64013 | 1.64041666667 | 13808 |
| 014672 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595675.2 | 510363.7 | 64015 | 1.64041666667 | 14672 |
| 013718 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595676.5 | 510361.0 | 64017 | 1.64041666667 | 13718 |
| 014469 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595677.0 | 510359.5 | 64019 | 1.64041666667 | 14469 |
| 013157 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595676.4 | 510359.9 | 64021 | 1.64041666667 | 13157 |
| 014359 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595675.8 | 510361.6 | 64023 | 1.64041666667 | 14359 |
| 013309 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595675.4 | 510363.6 | 64025 | 1.64041666667 | 13309 |
| 013857 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595674.0 | 510364.9 | 64027 | 1.64041666667 | 13857 |
| 013214 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595671.1 | 510365.7 | 64029 | 1.64041666667 | 13214 |
| 014973 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595668.4 | 510365.5 | 64031 | 1.64041666667 | 14973 |
| 013073 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595665.8 | 510364.4 | 64033 | 1.64041666667 | 13073 |
| 013168 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595663.0 | 510362.9 | 64035 | 1.64041666667 | 13168 |
| 013222 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595660.7 | 510360.7 | 64037 | 1.64041666667 | 13222 |
| 012551 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595658.1 | 510358.9 | 64039 | 1.64041666667 | 12551 |
| 013718 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595655.2 | 510357.7 | 64041 | 1.64041666667 | 13718 |
| 012999 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595652.2 | 510356.3 | 64043 | 1.64041666667 | 12999 |
| 011620 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595648.8 | 510355.2 | 64045 | 1.64041666667 | 11620 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595646.2 | 510354.2 | 64047 | 1.64041666667 | 13795 |
| 013168 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595643.1 | 510352.4 | 64049 | 1.64041666667 | 13168 |
| 014122 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595640.4 | 510351.4 | 64051 | 1.64041666667 | 14122 |
| 012530 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595637.3 | 510350.1 | 64053 | 1.64041666667 | 12530 |
| 013272 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595635.1 | 510348.7 | 64055 | 1.64041666667 | 13272 |
| 012498 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595632.0 | 510346.9 | 64057 | 1.64041666667 | 12498 |
| 012364 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595629.4 | 510345.0 | 64059 | 1.64041666667 | 12364 |
| 013171 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595626.7 | 510343.4 | 64061 | 1.64041666667 | 13171 |
| 014062 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595624.2 | 510342.6 | 64063 | 1.64041666667 | 14062 |
| 014345 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595622.0 | 510341.0 | 64065 | 1.64041666667 | 14345 |
| 013216 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595619.7 | 510339.1 | 64067 | 1.64041666667 | 13216 |
| 012694 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595616.9 | 510337.2 | 64069 | 1.64041666667 | 12694 |
| 015383 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595614.8 | 510335.6 | 64071 | 1.64041666667 | 15383 |
| 012696 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595611.7 | 510334.1 | 64073 | 1.64041666667 | 12696 |
| 011574 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595608.7 | 510332.5 | 64075 | 1.64041666667 | 11574 |
| 010933 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595605.6 | 510331.3 | 64077 | 1.64041666667 | 10933 |
| 011013 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595602.8 | 510330.4 | 64079 | 1.64041666667 | 11013 |
| 010703 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595599.5 | 510328.5 | 64081 | 1.64041666667 | 10703 |
| 010235 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595596.9 | 510326.8 | 64083 | 1.64041666667 | 10235 |
| 009489 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595594.4 | 510324.8 | 64085 | 1.64041666667 | 9489 |
| 009962 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595592.1 | 510323.0 | 64087 | 1.64041666667 | 9962 |
| 011820 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595588.8 | 510321.9 | 64089 | 1.64041666667 | 11820 |
| 014625 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595586.0 | 510321.1 | 64091 | 1.64041666667 | 14625 |
| 013466 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595583.2 | 510320.3 | 64093 | 1.64041666667 | 13466 |
| 013146 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595580.8 | 510319.4 | 64095 | 1.64041666667 | 13146 |
| 012346 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595579.2 | 510318.0 | 64097 | 1.64041666667 | 12346 |
| 013256 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595579.3 | 510318.6 | 64099 | 1.64041666667 | 13256 |
| 011774 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595579.8 | 510319.8 | 64101 | 1.64041666667 | 11774 |
| 012213 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595581.1 | 510319.4 | 64103 | 1.64041666667 | 12213 |
| 012113 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595583.6 | 510317.8 | 64105 | 1.64041666667 | 12113 |
| 012778 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595585.1 | 510316.0 | 64107 | 1.64041666667 | 12778 |
| 012224 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595586.6 | 510314.9 | 64109 | 1.64041666667 | 12224 |
| 012206 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595588.5 | 510314.2 | 64111 | 1.64041666667 | 12206 |
| 012681 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595590.9 | 510313.2 | 64113 | 1.64041666667 | 12681 |
| 012710 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595592.0 | 510313.1 | 64115 | 1.64041666667 | 12710 |
| 012207 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595591.8 | 510313.3 | 64117 | 1.64041666667 | 12207 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595591.2 | 510313.7 | 64119 | 1.64041666667 | 11962 |
| 012440 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595591.0 | 510313.8 | 64121 | 1.64041666667 | 12440 |
| 011540 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595590.8 | 510313.7 | 64123 | 1.64041666667 | 11540 |
| 011135 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595590.8 | 510313.5 | 64125 | 1.64041666667 | 11135 |
| 011813 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595590.8 | 510313.6 | 64127 | 1.64041666667 | 11813 |
| 012103 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595590.9 | 510313.2 | 64129 | 1.64041666667 | 12103 |
| 011066 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595590.7 | 510312.8 | 64131 | 1.64041666667 | 11066 |
| 011856 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595589.6 | 510313.6 | 64133 | 1.64041666667 | 11856 |
| 012564 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595588.1 | 510313.8 | 64135 | 1.64041666667 | 12564 |
| 012981 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595586.1 | 510312.6 | 64137 | 1.64041666667 | 12981 |
| 012875 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595584.7 | 510311.0 | 64139 | 1.64041666667 | 12875 |
| 012968 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595582.9 | 510308.7 | 64141 | 1.64041666667 | 12968 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012722 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595581.5 | 510306.8 | 64143 | 1.64041666667 | 12722 |
| 014550 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595580.0 | 510304.7 | 64145 | 1.64041666667 | 14550 |
| 013687 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595578.5 | 510303.4 | 64147 | 1.64041666667 | 13687 |
| 012422 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595577.1 | 510302.1 | 64149 | 1.64041666667 | 12422 |
| 012915 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595576.5 | 510301.4 | 64151 | 1.64041666667 | 12915 |
| 011268 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595576.1 | 510299.7 | 64153 | 1.64041666667 | 11268 |
| 011067 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595574.4 | 510297.7 | 64155 | 1.64041666667 | 11067 |
| 012127 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595572.5 | 510295.7 | 64157 | 1.64041666667 | 12127 |
| 012931 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595571.0 | 510294.0 | 64159 | 1.64041666667 | 12931 |
| 012922 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595569.2 | 510292.5 | 64161 | 1.64041666667 | 12922 |
| 013610 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595567.1 | 510291.2 | 64163 | 1.64041666667 | 13610 |
| 014022 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595565.2 | 510290.1 | 64165 | 1.64041666667 | 14022 |
| 013825 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595564.2 | 510288.5 | 64167 | 1.64041666667 | 13825 |
| 015366 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595563.4 | 510286.7 | 64169 | 1.64041666667 | 15366 |
| 013531 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595563.0 | 510285.7 | 64171 | 1.64041666667 | 13531 |
| 011242 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595563.4 | 510286.4 | 64173 | 1.64041666667 | 11242 |
| 012200 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595564.8 | 510287.6 | 64175 | 1.64041666667 | 12200 |
| 012140 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595566.6 | 510289.7 | 64177 | 1.64041666667 | 12140 |
| 011735 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595568.6 | 510291.7 | 64179 | 1.64041666667 | 11735 |
| 012203 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595570.6 | 510293.5 | 64181 | 1.64041666667 | 12203 |
| 012381 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595572.0 | 510295.6 | 64183 | 1.64041666667 | 12381 |
| 012995 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595573.8 | 510297.7 | 64185 | 1.64041666667 | 12995 |
| 013478 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595575.3 | 510300.1 | 64187 | 1.64041666667 | 13478 |
| 012369 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595576.8 | 510302.4 | 64189 | 1.64041666667 | 12369 |
| 013922 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595579.0 | 510304.8 | 64191 | 1.64041666667 | 13922 |
| 012150 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595581.0 | 510307.4 | 64193 | 1.64041666667 | 12150 |
| 010777 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595582.6 | 510309.9 | 64195 | 1.64041666667 | 10777 |
| 011724 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595584.7 | 510312.3 | 64197 | 1.64041666667 | 11724 |
| 012141 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595587.0 | 510314.3 | 64199 | 1.64041666667 | 12141 |
| 011975 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595589.9 | 510316.0 | 64201 | 1.64041666667 | 11975 |
| 012953 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595592.8 | 510317.3 | 64203 | 1.64041666667 | 12953 |
| 011158 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595596.4 | 510319.1 | 64205 | 1.64041666667 | 11158 |
| 012329 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595598.8 | 510320.4 | 64207 | 1.64041666667 | 12329 |
| 012952 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595601.9 | 510321.8 | 64209 | 1.64041666667 | 12952 |
| 010498 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595604.6 | 510323.5 | 64211 | 1.64041666667 | 10498 |
| 010484 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595607.8 | 510324.9 | 64213 | 1.64041666667 | 10484 |
| 010991 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595610.4 | 510325.7 | 64215 | 1.64041666667 | 10991 |
| 011297 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595613.3 | 510326.9 | 64217 | 1.64041666667 | 11297 |
| 011794 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595616.1 | 510327.5 | 64219 | 1.64041666667 | 11794 |
| 011678 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595619.0 | 510328.8 | 64221 | 1.64041666667 | 11678 |
| 012609 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595621.0 | 510330.3 | 64223 | 1.64041666667 | 12609 |
| 011882 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595623.3 | 510332.2 | 64225 | 1.64041666667 | 11882 |
| 012150 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595625.1 | 510333.8 | 64227 | 1.64041666667 | 12150 |
| 011857 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595628.0 | 510335.4 | 64229 | 1.64041666667 | 11857 |
| 011604 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595630.6 | 510337.1 | 64231 | 1.64041666667 | 11604 |
| 012261 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595633.7 | 510338.5 | 64233 | 1.64041666667 | 12261 |
| 011435 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595636.4 | 510339.4 | 64235 | 1.64041666667 | 11435 |
| 012578 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595639.4 | 510340.5 | 64237 | 1.64041666667 | 12578 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013614 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595642.0 | 510341.2 | 64239 | 1.64041666667 | 13614 |
| 013093 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595645.4 | 510342.3 | 64241 | 1.64041666667 | 13093 |
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595647.8 | 510343.1 | 64243 | 1.64041666667 | 12183 |
| 012915 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595650.6 | 510344.4 | 64245 | 1.64041666667 | 12915 |
| 012888 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595652.5 | 510346.2 | 64247 | 1.64041666667 | 12888 |
| 014142 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595655.4 | 510348.4 | 64249 | 1.64041666667 | 14142 |
| 012985 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595657.8 | 510349.9 | 64251 | 1.64041666667 | 12985 |
| 013116 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595660.5 | 510351.6 | 64253 | 1.64041666667 | 13116 |
| 012729 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595662.8 | 510352.6 | 64255 | 1.64041666667 | 12729 |
| 014102 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595666.2 | 510354.2 | 64257 | 1.64041666667 | 14102 |
| 014025 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595668.8 | 510355.3 | 64259 | 1.64041666667 | 14025 |
| 013616 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595671.7 | 510356.3 | 64261 | 1.64041666667 | 13616 |
| 012764 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595674.0 | 510357.6 | 64263 | 1.64041666667 | 12764 |
| 014201 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595675.3 | 510358.5 | 64265 | 1.64041666667 | 14201 |
| 012850 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595675.1 | 510358.6 | 64267 | 1.64041666667 | 12850 |
| 012752 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595675.0 | 510358.6 | 64269 | 1.64041666667 | 12752 |
| 013328 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595675.3 | 510358.7 | 64271 | 1.64041666667 | 13328 |
| 013502 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595675.8 | 510358.5 | 64273 | 1.64041666667 | 13502 |
| 013185 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595675.7 | 510358.1 | 64275 | 1.64041666667 | 13185 |
| 015056 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595676.9 | 510356.7 | 64277 | 1.64041666667 | 15056 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595678.4 | 510355.2 | 64279 | 1.64041666667 | 13424 |
| 013016 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:23am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595679.3 | 510353.5 | 64281 | 1.64041666667 | 13016 |
| 013034 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595680.3 | 510351.4 | 64283 | 1.64041666667 | 13034 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595681.3 | 510350.2 | 64285 | 1.64041666667 | 12678 |
| 012819 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595681.1 | 510350.8 | 64287 | 1.64041666667 | 12819 |
| 012477 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595680.9 | 510352.6 | 64289 | 1.64041666667 | 12477 |
| 013049 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595680.5 | 510353.5 | 64291 | 1.64041666667 | 13049 |
| 013192 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:29am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595678.5 | 510354.1 | 64293 | 1.64041666667 | 13192 |
| 012358 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595676.2 | 510353.7 | 64295 | 1.64041666667 | 12358 |
| 012689 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:31am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595673.0 | 510352.6 | 64297 | 1.64041666667 | 12689 |
| 012592 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:32am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595670.6 | 510351.5 | 64299 | 1.64041666667 | 12592 |
| 013468 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595667.8 | 510350.0 | 64301 | 1.64041666667 | 13468 |
| 012997 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595664.9 | 510348.9 | 64303 | 1.64041666667 | 12997 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595661.7 | 510347.0 | 64305 | 1.64041666667 | 14049 |
| 012782 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595659.0 | 510345.4 | 64307 | 1.64041666667 | 12782 |
| 011655 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595655.8 | 510343.7 | 64309 | 1.64041666667 | 11655 |
| 014433 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595653.3 | 510341.9 | 64311 | 1.64041666667 | 14433 |
| 013208 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595649.8 | 510340.1 | 64313 | 1.64041666667 | 13208 |
| 013022 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595647.2 | 510338.6 | 64315 | 1.64041666667 | 13022 |
| 011115 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595643.6 | 510336.4 | 64317 | 1.64041666667 | 11115 |
| 011778 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595640.7 | 510335.1 | 64319 | 1.64041666667 | 11778 |
| 013984 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595637.8 | 510333.8 | 64321 | 1.64041666667 | 13984 |
| 015376 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595635.0 | 510331.9 | 64323 | 1.64041666667 | 15376 |
| 014014 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595632.1 | 510330.0 | 64325 | 1.64041666667 | 14014 |
| 012023 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595629.4 | 510328.4 | 64327 | 1.64041666667 | 12023 |
| 012066 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595626.0 | 510327.0 | 64329 | 1.64041666667 | 12066 |
| 011566 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595622.9 | 510326.1 | 64331 | 1.64041666667 | 11566 |
| 011501 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595619.3 | 510324.7 | 64333 | 1.64041666667 | 11501 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011785 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595616.7 | 510323.3 | 64335 | 1.64041666667 | 11785 |
| 011046 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595613.4 | 510321.8 | 64337 | 1.64041666667 | 11046 |
| 011221 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595610.3 | 510320.3 | 64339 | 1.64041666667 | 11221 |
| 011745 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595607.4 | 510318.6 | 64341 | 1.64041666667 | 11745 |
| 011066 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595604.6 | 510317.1 | 64343 | 1.64041666667 | 11066 |
| 012426 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595601.0 | 510315.3 | 64345 | 1.64041666667 | 12426 |
| 010576 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595598.3 | 510314.3 | 64347 | 1.64041666667 | 10576 |
| 011464 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595595.0 | 510313.5 | 64349 | 1.64041666667 | 11464 |
| 013666 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595593.2 | 510312.7 | 64351 | 1.64041666667 | 13666 |
| 012806 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595592.7 | 510312.3 | 64353 | 1.64041666667 | 12806 |
| 012771 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595592.2 | 510311.6 | 64355 | 1.64041666667 | 12771 |
| 010483 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595589.6 | 510310.2 | 64357 | 1.64041666667 | 10483 |
| 011140 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595587.1 | 510309.0 | 64359 | 1.64041666667 | 11140 |
| 011035 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595584.5 | 510307.0 | 64361 | 1.64041666667 | 11035 |
| 010378 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595581.5 | 510305.5 | 64363 | 1.64041666667 | 10378 |
| 013334 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595578.8 | 510303.9 | 64365 | 1.64041666667 | 13334 |
| 012063 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595577.2 | 510302.2 | 64367 | 1.64041666667 | 12063 |
| 012855 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595575.3 | 510300.3 | 64369 | 1.64041666667 | 12855 |
| 011613 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595573.3 | 510298.7 | 64371 | 1.64041666667 | 11613 |
| 011993 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595570.9 | 510298.1 | 64373 | 1.64041666667 | 11993 |
| 011998 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595569.2 | 510297.7 | 64375 | 1.64041666667 | 11998 |
| 011969 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595568.5 | 510297.6 | 64377 | 1.64041666667 | 11969 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595568.8 | 510297.6 | 64379 | 1.64041666667 | 12442 |
| 013760 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595569.6 | 510296.3 | 64381 | 1.64041666667 | 13760 |
| 013580 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:14am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595571.3 | 510294.8 | 64383 | 1.64041666667 | 13580 |
| 011555 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:15am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595572.5 | 510294.6 | 64385 | 1.64041666667 | 11555 |
| 010898 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595572.5 | 510293.4 | 64387 | 1.64041666667 | 10898 |
| 011664 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595573.7 | 510291.0 | 64389 | 1.64041666667 | 11664 |
| 011886 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595575.0 | 510289.7 | 64391 | 1.64041666667 | 11886 |
| 011371 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595574.7 | 510290.0 | 64393 | 1.64041666667 | 11371 |
| 010462 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595574.3 | 510290.3 | 64395 | 1.64041666667 | 10462 |
| 011885 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595573.9 | 510290.3 | 64397 | 1.64041666667 | 11885 |
| 011731 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595573.7 | 510290.2 | 64399 | 1.64041666667 | 11731 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595573.5 | 510290.0 | 64401 | 1.64041666667 | 11962 |
| 012080 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595573.2 | 510290.8 | 64403 | 1.64041666667 | 12080 |
| 012650 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595572.6 | 510292.6 | 64405 | 1.64041666667 | 12650 |
| 012342 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595572.3 | 510293.8 | 64407 | 1.64041666667 | 12342 |
| 011425 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595572.9 | 510294.5 | 64409 | 1.64041666667 | 11425 |
| 012066 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595572.6 | 510294.8 | 64411 | 1.64041666667 | 12066 |
| 013516 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:29am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595572.5 | 510294.8 | 64413 | 1.64041666667 | 13516 |
| 011899 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:30am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595572.6 | 510294.8 | 64415 | 1.64041666667 | 11899 |
| 011614 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:31am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595573.1 | 510294.6 | 64417 | 1.64041666667 | 11614 |
| 010733 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:32am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595573.9 | 510294.8 | 64419 | 1.64041666667 | 10733 |
| 012433 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:33am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595575.3 | 510295.4 | 64421 | 1.64041666667 | 12433 |
| 012228 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:34am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595576.8 | 510295.9 | 64423 | 1.64041666667 | 12228 |
| 013047 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:35am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595578.7 | 510297.2 | 64425 | 1.64041666667 | 13047 |
| 012441 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:36am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595581.3 | 510298.4 | 64427 | 1.64041666667 | 12441 |
| 012320 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:37am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595583.9 | 510300.0 | 64429 | 1.64041666667 | 12320 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011540 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:38am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595586.3 | 510301.4 | 64431 | 1.64041666667 | 11540 |
| 010745 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:39am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595588.9 | 510302.7 | 64433 | 1.64041666667 | 10745 |
| 011326 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:40am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595591.3 | 510304.0 | 64435 | 1.64041666667 | 11326 |
| 011411 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595594.0 | 510305.0 | 64437 | 1.64041666667 | 11411 |
| 010503 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595596.5 | 510306.2 | 64439 | 1.64041666667 | 10503 |
| 011145 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595599.2 | 510307.0 | 64441 | 1.64041666667 | 11145 |
| 012686 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595602.0 | 510308.2 | 64443 | 1.64041666667 | 12686 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595604.5 | 510309.7 | 64445 | 1.64041666667 | 11241 |
| 010940 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595607.2 | 510310.9 | 64447 | 1.64041666667 | 10940 |
| 010145 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595609.9 | 510312.6 | 64449 | 1.64041666667 | 10145 |
| 011536 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595612.4 | 510314.1 | 64451 | 1.64041666667 | 11536 |
| 010684 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595615.0 | 510316.2 | 64453 | 1.64041666667 | 10684 |
| 012931 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595617.0 | 510317.7 | 64455 | 1.64041666667 | 12931 |
| 011392 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:51am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595619.9 | 510318.7 | 64457 | 1.64041666667 | 11392 |
| 010918 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595622.3 | 510320.0 | 64459 | 1.64041666667 | 10918 |
| 010709 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595625.1 | 510321.2 | 64461 | 1.64041666667 | 10709 |
| 012427 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595627.9 | 510322.6 | 64463 | 1.64041666667 | 12427 |
| 011986 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595631.2 | 510324.3 | 64465 | 1.64041666667 | 11986 |
| 011876 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:56am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595633.6 | 510325.2 | 64467 | 1.64041666667 | 11876 |
| 013139 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:57am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595636.3 | 510326.6 | 64469 | 1.64041666667 | 13139 |
| 013005 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595638.7 | 510327.7 | 64471 | 1.64041666667 | 13005 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595641.6 | 510329.8 | 64473 | 1.64041666667 | 12401 |
| 011680 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:00am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595644.2 | 510331.4 | 64475 | 1.64041666667 | 11680 |
| 010270 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:01am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595646.8 | 510332.8 | 64477 | 1.64041666667 | 10270 |
| 012137 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595649.2 | 510334.7 | 64479 | 1.64041666667 | 12137 |
| 014314 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595652.1 | 510336.4 | 64481 | 1.64041666667 | 14314 |
| 014858 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:04am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595655.3 | 510337.9 | 64483 | 1.64041666667 | 14858 |
| 013494 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:05am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595657.6 | 510339.0 | 64485 | 1.64041666667 | 13494 |
| 012703 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:06am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595660.1 | 510339.6 | 64487 | 1.64041666667 | 12703 |
| 011936 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:07am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595662.7 | 510340.6 | 64489 | 1.64041666667 | 11936 |
| 012854 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:08am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595665.7 | 510341.4 | 64491 | 1.64041666667 | 12854 |
| 012753 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:09am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595668.7 | 510343.0 | 64493 | 1.64041666667 | 12753 |
| 013718 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:10am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595671.0 | 510344.4 | 64495 | 1.64041666667 | 13718 |
| 012939 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:11am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595673.3 | 510345.8 | 64497 | 1.64041666667 | 12939 |
| 013465 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:12am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595675.4 | 510347.6 | 64499 | 1.64041666667 | 13465 |
| 014736 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:13am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595678.1 | 510349.0 | 64501 | 1.64041666667 | 14736 |
| 012894 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:14am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595680.4 | 510349.6 | 64503 | 1.64041666667 | 12894 |
| 013183 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:15am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595682.3 | 510349.2 | 64505 | 1.64041666667 | 13183 |
| 013196 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:16am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595683.4 | 510348.1 | 64507 | 1.64041666667 | 13196 |
| 013979 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:17am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595684.5 | 510346.0 | 64509 | 1.64041666667 | 13979 |
| 013904 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:18am | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595685.1 | 510344.7 | 64511 | 1.64041666667 | 13904 |
| 012416 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:19am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595686.7 | 510342.3 | 64513 | 1.64041666667 | 12416 |
| 013064 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:20am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595687.6 | 510340.4 | 64515 | 1.64041666667 | 13064 |
| 014246 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:21am | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595686.9 | 510341.3 | 64517 | 1.64041666667 | 14246 |
| 014121 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:22am | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595686.5 | 510342.5 | 64519 | 1.64041666667 | 14121 |
| 012140 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:23am | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595685.5 | 510343.6 | 64521 | 1.64041666667 | 12140 |
| 013745 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:24am | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595684.2 | 510343.9 | 64523 | 1.64041666667 | 13745 |
| 013516 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:25am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595682.5 | 510343.4 | 64525 | 1.64041666667 | 13516 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013759 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:26am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595680.2 | 510342.4 | 64527 | 1.64041666667 | 13759 |
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:27am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595677.9 | 510341.4 | 64529 | 1.64041666667 | 12019 |
| 012005 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:28am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595675.5 | 510340.1 | 64531 | 1.64041666667 | 12005 |
| 014131 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:29am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595673.1 | 510339.0 | 64533 | 1.64041666667 | 14131 |
| 013732 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:30am | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595671.5 | 510337.8 | 64535 | 1.64041666667 | 13732 |
| 013303 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:31am | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595669.0 | 510336.6 | 64537 | 1.64041666667 | 13303 |
| 014126 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:32am | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595666.9 | 510335.3 | 64539 | 1.64041666667 | 14126 |
| 011751 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:33am | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595664.4 | 510334.1 | 64541 | 1.64041666667 | 11751 |
| 012537 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:34am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595662.1 | 510332.7 | 64543 | 1.64041666667 | 12537 |
| 012944 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:35am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595659.2 | 510331.0 | 64545 | 1.64041666667 | 12944 |
| 014006 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:36am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595656.7 | 510330.0 | 64547 | 1.64041666667 | 14006 |
| 012351 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:37am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595654.4 | 510328.9 | 64549 | 1.64041666667 | 12351 |
| 012477 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:38am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595652.1 | 510328.0 | 64551 | 1.64041666667 | 12477 |
| 013109 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:39am | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595649.7 | 510326.7 | 64553 | 1.64041666667 | 13109 |
| 013357 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:40am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595647.6 | 510325.8 | 64555 | 1.64041666667 | 13357 |
| 013419 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:41am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595645.2 | 510324.2 | 64557 | 1.64041666667 | 13419 |
| 012594 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:42am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595642.7 | 510322.8 | 64559 | 1.64041666667 | 12594 |
| 012418 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595639.7 | 510321.1 | 64561 | 1.64041666667 | 12418 |
| 011714 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595637.5 | 510319.8 | 64563 | 1.64041666667 | 11714 |
| 010608 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595634.3 | 510318.3 | 64565 | 1.64041666667 | 10608 |
| 009102 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595631.4 | 510316.4 | 64567 | 1.64041666667 | 9102 |
| 010975 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:47am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595628.2 | 510314.6 | 64569 | 1.64041666667 | 10975 |
| 011924 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:48am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595625.7 | 510313.3 | 64571 | 1.64041666667 | 11924 |
| 011651 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595622.9 | 510311.2 | 64573 | 1.64041666667 | 11651 |
| 011042 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595620.1 | 510309.6 | 64575 | 1.64041666667 | 11042 |
| 011400 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:51am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595616.8 | 510307.7 | 64577 | 1.64041666667 | 11400 |
| 011790 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:52am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595613.9 | 510306.1 | 64579 | 1.64041666667 | 11790 |
| 012007 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595610.4 | 510304.7 | 64581 | 1.64041666667 | 12007 |
| 011492 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:54am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595607.8 | 510303.4 | 64583 | 1.64041666667 | 11492 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:55am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595605.1 | 510302.7 | 64585 | 1.64041666667 | 12743 |
| 012605 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:56am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595602.3 | 510302.0 | 64587 | 1.64041666667 | 12605 |
| 013411 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:57am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595599.5 | 510300.2 | 64589 | 1.64041666667 | 13411 |
| 014152 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:58am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595597.2 | 510298.4 | 64591 | 1.64041666667 | 14152 |
| 013948 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:59am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595594.3 | 510296.4 | 64593 | 1.64041666667 | 13948 |
| 011947 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:00am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595591.8 | 510294.8 | 64595 | 1.64041666667 | 11947 |
| 011536 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:01am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595589.0 | 510293.8 | 64597 | 1.64041666667 | 11536 |
| 011134 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:02am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595586.4 | 510292.8 | 64599 | 1.64041666667 | 11134 |
| 011513 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:03am | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595583.1 | 510291.9 | 64601 | 1.64041666667 | 11513 |
| 012058 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:04am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595580.4 | 510290.9 | 64603 | 1.64041666667 | 12058 |
| 012734 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:05am | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595577.8 | 510289.5 | 64605 | 1.64041666667 | 12734 |
| 012903 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:06am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595575.6 | 510288.5 | 64607 | 1.64041666667 | 12903 |
| 013305 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:07am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595575.8 | 510289.1 | 64609 | 1.64041666667 | 13305 |
| 013316 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:08am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595576.3 | 510290.5 | 64611 | 1.64041666667 | 13316 |
| 011699 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:09am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595575.9 | 510290.4 | 64613 | 1.64041666667 | 11699 |
| 012555 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:10am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595576.1 | 510290.2 | 64615 | 1.64041666667 | 12555 |
| 012108 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:11am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595576.6 | 510289.0 | 64617 | 1.64041666667 | 12108 |
| 012207 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:12am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595577.5 | 510287.0 | 64619 | 1.64041666667 | 12207 |
| 012261 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:13am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595577.8 | 510285.7 | 64621 | 1.64041666667 | 12261 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012365 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:14am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595578.4 | 510285.6 | 64623 | 1.64041666667 | 12365 |
| 011131 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:15am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595580.3 | 510283.6 | 64625 | 1.64041666667 | 11131 |
| 011842 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:16am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595581.9 | 510282.3 | 64627 | 1.64041666667 | 11842 |
| 013520 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:17am | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595583.8 | 510279.8 | 64629 | 1.64041666667 | 13520 |
| 011450 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:18am | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595583.8 | 510279.5 | 64631 | 1.64041666667 | 11450 |
| 012012 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:19am | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595583.6 | 510279.9 | 64633 | 1.64041666667 | 12012 |
| 012333 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:20am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.0 | 510280.0 | 64635 | 1.64041666667 | 12333 |
| 011633 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:21am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.0 | 510279.9 | 64637 | 1.64041666667 | 11633 |
| 013108 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:22am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.1 | 510279.8 | 64639 | 1.64041666667 | 13108 |
| 012037 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:23am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.1 | 510279.9 | 64641 | 1.64041666667 | 12037 |
| 011859 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:24am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.1 | 510279.8 | 64643 | 1.64041666667 | 11859 |
| 011694 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:25am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.1 | 510279.8 | 64645 | 1.64041666667 | 11694 |
| 011623 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:26am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.2 | 510279.8 | 64647 | 1.64041666667 | 11623 |
| 011546 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:27am | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595584.2 | 510279.8 | 64649 | 1.64041666667 | 11546 |
| 012756 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:28am | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595583.7 | 510280.2 | 64651 | 1.64041666667 | 12756 |
| 013149 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:29am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595582.1 | 510280.8 | 64653 | 1.64041666667 | 13149 |
| 012197 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:30am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595580.7 | 510281.1 | 64655 | 1.64041666667 | 12197 |
| 011119 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:31am | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595580.0 | 510282.9 | 64657 | 1.64041666667 | 11119 |
| 010729 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:32am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595579.2 | 510284.8 | 64659 | 1.64041666667 | 10729 |
| 012132 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:33am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595579.4 | 510286.2 | 64661 | 1.64041666667 | 12132 |
| 012303 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:34am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595579.6 | 510286.4 | 64663 | 1.64041666667 | 12303 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:35am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595579.1 | 510286.6 | 64665 | 1.64041666667 | 12045 |
| 012371 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:36am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595579.0 | 510286.7 | 64667 | 1.64041666667 | 12371 |
| 012303 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:37am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595579.1 | 510286.8 | 64669 | 1.64041666667 | 12303 |
| 012585 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:38am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595580.2 | 510287.1 | 64671 | 1.64041666667 | 12585 |
| 011336 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:39am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595582.5 | 510288.0 | 64673 | 1.64041666667 | 11336 |
| 011114 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:40am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595584.4 | 510289.1 | 64675 | 1.64041666667 | 11114 |
| 011658 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:41am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595587.3 | 510290.3 | 64677 | 1.64041666667 | 11658 |
| 010144 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:42am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595590.0 | 510291.3 | 64679 | 1.64041666667 | 10144 |
| 012226 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:43am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595592.9 | 510292.7 | 64681 | 1.64041666667 | 12226 |
| 012266 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:44am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595595.3 | 510293.8 | 64683 | 1.64041666667 | 12266 |
| 012666 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:45am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595598.3 | 510295.7 | 64685 | 1.64041666667 | 12666 |
| 012436 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:46am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595601.6 | 510296.9 | 64687 | 1.64041666667 | 12436 |
| 011659 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:47am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595604.4 | 510297.7 | 64689 | 1.64041666667 | 11659 |
| 012574 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:48am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595607.1 | 510298.8 | 64691 | 1.64041666667 | 12574 |
| 011453 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:49am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595610.0 | 510300.0 | 64693 | 1.64041666667 | 11453 |
| 010646 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:50am | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595612.8 | 510302.1 | 64695 | 1.64041666667 | 10646 |
| 010016 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:51am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595615.2 | 510304.3 | 64697 | 1.64041666667 | 10016 |
| 010544 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:52am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595617.6 | 510305.5 | 64699 | 1.64041666667 | 10544 |
| 011186 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:53am | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595620.6 | 510307.3 | 64701 | 1.64041666667 | 11186 |
| 009636 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:54am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595623.4 | 510309.1 | 64703 | 1.64041666667 | 9636 |
| 011829 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:55am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595626.1 | 510310.5 | 64705 | 1.64041666667 | 11829 |
| 010817 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:56am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595628.4 | 510312.1 | 64707 | 1.64041666667 | 10817 |
| 011884 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:57am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595631.8 | 510313.6 | 64709 | 1.64041666667 | 11884 |
| 012721 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:58am | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595634.2 | 510314.8 | 64711 | 1.64041666667 | 12721 |
| 011850 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:59am | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595637.3 | 510316.5 | 64713 | 1.64041666667 | 11850 |
| 010522 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:00pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595639.8 | 510317.6 | 64715 | 1.64041666667 | 10522 |
| 010550 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:01pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595642.8 | 510319.6 | 64717 | 1.64041666667 | 10550 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012897 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:02pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595645.2 | 510321.1 | 64719 | 1.64041666667 | 12897 |
| 012764 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:03pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595648.3 | 510322.6 | 64721 | 1.64041666667 | 12764 |
| 012581 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:04pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595650.7 | 510324.0 | 64723 | 1.64041666667 | 12581 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:05pm | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595654.1 | 510325.3 | 64725 | 1.64041666667 | 12475 |
| 013228 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:06pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595657.0 | 510326.5 | 64727 | 1.64041666667 | 13228 |
| 012877 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:07pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595659.9 | 510327.8 | 64729 | 1.64041666667 | 12877 |
| 014079 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:08pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595662.8 | 510328.5 | 64731 | 1.64041666667 | 14079 |
| 013719 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:09pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595665.8 | 510329.5 | 64733 | 1.64041666667 | 13719 |
| 014140 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:10pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595668.8 | 510330.7 | 64735 | 1.64041666667 | 14140 |
| 013705 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:11pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595671.9 | 510331.8 | 64737 | 1.64041666667 | 13705 |
| 012876 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:12pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595674.6 | 510332.8 | 64739 | 1.64041666667 | 12876 |
| 013599 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:13pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595677.3 | 510333.6 | 64741 | 1.64041666667 | 13599 |
| 013059 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:14pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595679.8 | 510335.2 | 64743 | 1.64041666667 | 13059 |
| 013675 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:15pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595682.5 | 510337.2 | 64745 | 1.64041666667 | 13675 |
| 014158 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:16pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595684.7 | 510338.6 | 64747 | 1.64041666667 | 14158 |
| 014849 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:17pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595686.5 | 510339.9 | 64749 | 1.64041666667 | 14849 |
| 014182 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:18pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595687.2 | 510339.8 | 64751 | 1.64041666667 | 14182 |
| 012815 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:19pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595687.6 | 510339.4 | 64753 | 1.64041666667 | 12815 |
| 013673 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:20pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595689.7 | 510338.0 | 64755 | 1.64041666667 | 13673 |
| 012868 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:21pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595691.7 | 510337.0 | 64757 | 1.64041666667 | 12868 |
| 012637 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:22pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595692.6 | 510336.0 | 64759 | 1.64041666667 | 12637 |
| 013599 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:23pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595694.8 | 510333.8 | 64761 | 1.64041666667 | 13599 |
| 013389 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:24pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595696.4 | 510332.2 | 64763 | 1.64041666667 | 13389 |
| 014177 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:25pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595696.2 | 510332.6 | 64765 | 1.64041666667 | 14177 |
| 013024 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:26pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595695.7 | 510334.0 | 64767 | 1.64041666667 | 13024 |
| 012436 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:27pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595695.2 | 510334.9 | 64769 | 1.64041666667 | 12436 |
| 014749 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:28pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595693.4 | 510335.3 | 64771 | 1.64041666667 | 14749 |
| 014307 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:29pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595691.3 | 510335.6 | 64773 | 1.64041666667 | 14307 |
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:30pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595689.3 | 510335.1 | 64775 | 1.64041666667 | 12937 |
| 013254 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:31pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595686.5 | 510334.0 | 64777 | 1.64041666667 | 13254 |
| 013423 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:32pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595684.0 | 510332.7 | 64779 | 1.64041666667 | 13423 |
| 012146 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:33pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595680.9 | 510331.2 | 64781 | 1.64041666667 | 12146 |
| 013206 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:34pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595678.3 | 510330.8 | 64783 | 1.64041666667 | 13206 |
| 012241 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:35pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595675.3 | 510329.5 | 64785 | 1.64041666667 | 12241 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:36pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595672.5 | 510328.4 | 64787 | 1.64041666667 | 12420 |
| 012585 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:37pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595669.5 | 510326.8 | 64789 | 1.64041666667 | 12585 |
| 013646 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:38pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595667.4 | 510325.3 | 64791 | 1.64041666667 | 13646 |
| 014061 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:39pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595664.4 | 510323.7 | 64793 | 1.64041666667 | 14061 |
| 015215 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:40pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595662.0 | 510321.9 | 64795 | 1.64041666667 | 15215 |
| 014183 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:41pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595659.0 | 510319.9 | 64797 | 1.64041666667 | 14183 |
| 012426 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:42pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595656.0 | 510318.7 | 64799 | 1.64041666667 | 12426 |
| 011416 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:43pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595653.3 | 510316.7 | 64801 | 1.64041666667 | 11416 |
| 012368 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:44pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595650.3 | 510314.9 | 64803 | 1.64041666667 | 12368 |
| 013936 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:45pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595647.2 | 510313.6 | 64805 | 1.64041666667 | 13936 |
| 014044 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:46pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595644.6 | 510312.3 | 64807 | 1.64041666667 | 14044 |
| 012031 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:47pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595641.3 | 510311.1 | 64809 | 1.64041666667 | 12031 |
| 010327 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:48pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595638.4 | 510309.7 | 64811 | 1.64041666667 | 10327 |
| 011372 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:49pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595635.4 | 510308.2 | 64813 | 1.64041666667 | 11372 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010913 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:50pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595633.0 | 510307.2 | 64815 | 1.64041666667 | 10913 |
| 011188 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:51pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595629.9 | 510304.9 | 64817 | 1.64041666667 | 11188 |
| 009967 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:52pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595627.4 | 510303.3 | 64819 | 1.64041666667 | 9967 |
| 009391 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:53pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595624.5 | 510301.3 | 64821 | 1.64041666667 | 9391 |
| 010777 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:54pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595622.6 | 510299.3 | 64823 | 1.64041666667 | 10777 |
| 010944 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:55pm | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595619.3 | 510297.2 | 64825 | 1.64041666667 | 10944 |
| 008586 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:56pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595616.7 | 510296.1 | 64827 | 1.64041666667 | 8586 |
| 010696 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:57pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595613.8 | 510294.8 | 64829 | 1.64041666667 | 10696 |
| 011194 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:58pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595611.3 | 510293.8 | 64831 | 1.64041666667 | 11194 |
| 010928 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:59pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595608.5 | 510291.2 | 64833 | 1.64041666667 | 10928 |
| 011492 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:00pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595606.3 | 510289.3 | 64835 | 1.64041666667 | 11492 |
| 011003 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:01pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595603.2 | 510288.1 | 64837 | 1.64041666667 | 11003 |
| 010970 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:02pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595600.6 | 510286.6 | 64839 | 1.64041666667 | 10970 |
| 010632 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:03pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595597.3 | 510284.9 | 64841 | 1.64041666667 | 10632 |
| 010218 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:04pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595594.6 | 510284.3 | 64843 | 1.64041666667 | 10218 |
| 009094 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:05pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595591.4 | 510282.8 | 64845 | 1.64041666667 | 9094 |
| 012083 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:06pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595588.6 | 510281.5 | 64847 | 1.64041666667 | 12083 |
| 011541 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:07pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595585.6 | 510280.3 | 64849 | 1.64041666667 | 11541 |
| 011465 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:08pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595584.7 | 510279.5 | 64851 | 1.64041666667 | 11465 |
| 011566 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:09pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595584.5 | 510279.5 | 64853 | 1.64041666667 | 11566 |
| 012311 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:10pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595583.0 | 510278.9 | 64855 | 1.64041666667 | 12311 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:11pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595581.7 | 510277.2 | 64857 | 1.64041666667 | 12378 |
| 012334 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:12pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595581.9 | 510275.3 | 64859 | 1.64041666667 | 12334 |
| 013073 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:13pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595583.2 | 510273.7 | 64861 | 1.64041666667 | 13073 |
| 011248 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:14pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595584.0 | 510272.6 | 64863 | 1.64041666667 | 11248 |
| 011782 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:15pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595585.2 | 510270.5 | 64865 | 1.64041666667 | 11782 |
| 010805 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:16pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595586.5 | 510269.4 | 64867 | 1.64041666667 | 10805 |
| 010891 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:17pm | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595587.2 | 510269.6 | 64869 | 1.64041666667 | 10891 |
| 010552 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:18pm | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595587.5 | 510269.8 | 64871 | 1.64041666667 | 10552 |
| 009958 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:19pm | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595587.7 | 510269.8 | 64873 | 1.64041666667 | 9958 |
| 010769 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:20pm | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595587.9 | 510269.8 | 64875 | 1.64041666667 | 10769 |
| 010312 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:21pm | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595587.8 | 510269.6 | 64877 | 1.64041666667 | 10312 |
| 010856 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:22pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595587.1 | 510269.3 | 64879 | 1.64041666667 | 10856 |
| 011287 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:23pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595585.8 | 510268.5 | 64881 | 1.64041666667 | 11287 |
| 010921 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:24pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595585.0 | 510269.3 | 64883 | 1.64041666667 | 10921 |
| 012210 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:25pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595583.9 | 510271.8 | 64885 | 1.64041666667 | 12210 |
| 010762 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:26pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595584.0 | 510274.0 | 64887 | 1.64041666667 | 10762 |
| 011780 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:27pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595586.5 | 510276.2 | 64889 | 1.64041666667 | 11780 |
| 011255 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:28pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595588.8 | 510277.2 | 64891 | 1.64041666667 | 11255 |
| 012203 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:29pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595591.2 | 510278.5 | 64893 | 1.64041666667 | 12203 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:30pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595594.0 | 510279.7 | 64895 | 1.64041666667 | 11241 |
| 011120 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:31pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595596.9 | 510281.3 | 64897 | 1.64041666667 | 11120 |
| 013370 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:32pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595598.4 | 510282.3 | 64899 | 1.64041666667 | 13370 |
| 011682 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:33pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595599.0 | 510282.2 | 64901 | 1.64041666667 | 11682 |
| 010720 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:34pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595598.8 | 510282.2 | 64903 | 1.64041666667 | 10720 |
| 013150 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:35pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595598.7 | 510282.2 | 64905 | 1.64041666667 | 13150 |
| 010517 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:36pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595598.7 | 510282.3 | 64907 | 1.64041666667 | 10517 |
| 010459 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:37pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595598.8 | 510282.5 | 64909 | 1.64041666667 | 10459 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009874 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:38pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595600.1 | 510283.0 | 64911 | 1.64041666667 | 9874 |
| 010508 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:39pm | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595602.8 | 510284.3 | 64913 | 1.64041666667 | 10508 |
| 011837 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:40pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595605.4 | 510286.1 | 64915 | 1.64041666667 | 11837 |
| 011269 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:41pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595608.0 | 510288.1 | 64917 | 1.64041666667 | 11269 |
| 010527 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:42pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595610.8 | 510289.4 | 64919 | 1.64041666667 | 10527 |
| 010012 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:43pm | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595614.4 | 510290.8 | 64921 | 1.64041666667 | 10012 |
| 009583 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:44pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595616.7 | 510292.3 | 64923 | 1.64041666667 | 9583 |
| 010075 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:45pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595619.6 | 510293.8 | 64925 | 1.64041666667 | 10075 |
| 009539 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:46pm | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595622.9 | 510295.2 | 64927 | 1.64041666667 | 9539 |
| 009374 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:47pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595626.2 | 510296.5 | 64929 | 1.64041666667 | 9374 |
| 010953 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:48pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595629.1 | 510297.3 | 64931 | 1.64041666667 | 10953 |
| 009908 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:49pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595632.4 | 510298.9 | 64933 | 1.64041666667 | 9908 |
| 009707 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:50pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595635.5 | 510300.0 | 64935 | 1.64041666667 | 9707 |
| 009566 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:51pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595638.8 | 510300.6 | 64937 | 1.64041666667 | 9566 |
| 010401 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:52pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595641.8 | 510301.3 | 64939 | 1.64041666667 | 10401 |
| 011180 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:53pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595645.3 | 510302.6 | 64941 | 1.64041666667 | 11180 |
| 011585 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:54pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595648.1 | 510304.4 | 64943 | 1.64041666667 | 11585 |
| 011716 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:55pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595651.3 | 510306.4 | 64945 | 1.64041666667 | 11716 |
| 012559 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:56pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595653.9 | 510307.6 | 64947 | 1.64041666667 | 12559 |
| 011689 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:57pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595656.5 | 510309.8 | 64949 | 1.64041666667 | 11689 |
| 011562 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:58pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595659.4 | 510312.0 | 64951 | 1.64041666667 | 11562 |
| 014080 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:59pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595662.2 | 510313.7 | 64953 | 1.64041666667 | 14080 |
| 012730 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:00pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595664.3 | 510315.4 | 64955 | 1.64041666667 | 12730 |
| 014012 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:01pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595667.2 | 510317.1 | 64957 | 1.64041666667 | 14012 |
| 013433 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:02pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595670.3 | 510319.0 | 64959 | 1.64041666667 | 13433 |
| 014638 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:03pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595672.9 | 510320.5 | 64961 | 1.64041666667 | 14638 |
| 013769 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:04pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595675.4 | 510321.6 | 64963 | 1.64041666667 | 13769 |
| 013792 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:05pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595678.5 | 510323.6 | 64965 | 1.64041666667 | 13792 |
| 012358 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:06pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595681.1 | 510325.2 | 64967 | 1.64041666667 | 12358 |
| 012779 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:07pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595684.1 | 510327.1 | 64969 | 1.64041666667 | 12779 |
| 012735 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:08pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595686.4 | 510328.9 | 64971 | 1.64041666667 | 12735 |
| 013323 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:09pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595689.3 | 510330.5 | 64973 | 1.64041666667 | 13323 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:10pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595691.7 | 510332.1 | 64975 | 1.64041666667 | 12840 |
| 015060 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:11pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595694.2 | 510332.8 | 64977 | 1.64041666667 | 15060 |
| 012795 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:12pm | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595696.2 | 510332.1 | 64979 | 1.64041666667 | 12795 |
| 013818 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:13pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595695.9 | 510331.9 | 64981 | 1.64041666667 | 13818 |
| 013294 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:14pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595697.7 | 510330.0 | 64983 | 1.64041666667 | 13294 |
| 011393 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:15pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595699.7 | 510328.5 | 64985 | 1.64041666667 | 11393 |
| 013528 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:16pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595700.6 | 510327.5 | 64987 | 1.64041666667 | 13528 |
| 013972 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:17pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595702.4 | 510325.1 | 64989 | 1.64041666667 | 13972 |
| 012643 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:18pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595703.9 | 510323.5 | 64991 | 1.64041666667 | 12643 |
| 012430 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:19pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595703.5 | 510323.8 | 64993 | 1.64041666667 | 12430 |
| 015437 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:20pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595702.7 | 510324.9 | 64995 | 1.64041666667 | 15437 |
| 014779 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:21pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595701.6 | 510326.7 | 64997 | 1.64041666667 | 14779 |
| 015934 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:22pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595699.6 | 510327.2 | 64999 | 1.64041666667 | 15934 |
| 014093 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:23pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595697.5 | 510325.8 | 65001 | 1.64041666667 | 14093 |
| 013573 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:24pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595695.1 | 510323.8 | 65003 | 1.64041666667 | 13573 |
| 012483 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:25pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595692.7 | 510321.5 | 65005 | 1.64041666667 | 12483 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013470 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:26pm | Sensor | 1797-S0045-G-TJV.cor | 6830.2 | 1595691.0 | 510319.7 | 65007 | 1.64041666667 | 13470 |
| 012097 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:27pm | Sensor | 1797-S0045-G-TJV.cor | 6830.2 | 1595688.2 | 510318.3 | 65009 | 1.64041666667 | 12097 |
| 012744 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:28pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595685.3 | 510316.7 | 65011 | 1.64041666667 | 12744 |
| 013236 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:29pm | Sensor | 1797-S0045-G-TJV.cor | 6830.2 | 1595682.3 | 510315.4 | 65013 | 1.64041666667 | 13236 |
| 012609 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:30pm | Sensor | 1797-S0045-G-TJV.cor | 6830.3 | 1595679.8 | 510314.5 | 65015 | 1.64041666667 | 12609 |
| 014012 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:31pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595676.6 | 510312.5 | 65017 | 1.64041666667 | 14012 |
| 012293 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:32pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595673.7 | 510311.1 | 65019 | 1.64041666667 | 12293 |
| 012673 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:33pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595670.4 | 510309.4 | 65021 | 1.64041666667 | 12673 |
| 011328 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:34pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595667.7 | 510307.8 | 65023 | 1.64041666667 | 11328 |
| 010902 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:35pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595664.3 | 510306.4 | 65025 | 1.64041666667 | 10902 |
| 011185 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:36pm | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595660.8 | 510304.8 | 65027 | 1.64041666667 | 11185 |
| 013476 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:37pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595658.2 | 510303.2 | 65029 | 1.64041666667 | 13476 |
| 012849 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:38pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595655.2 | 510301.8 | 65031 | 1.64041666667 | 12849 |
| 012122 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:39pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595652.2 | 510300.0 | 65033 | 1.64041666667 | 12122 |
| 010860 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:40pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595649.6 | 510298.3 | 65035 | 1.64041666667 | 10860 |
| 011115 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:41pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595646.9 | 510297.2 | 65037 | 1.64041666667 | 11115 |
| 010968 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:42pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595643.8 | 510295.5 | 65039 | 1.64041666667 | 10968 |
| 009972 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:43pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595640.8 | 510293.8 | 65041 | 1.64041666667 | 9972 |
| 009063 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:44pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595638.2 | 510292.4 | 65043 | 1.64041666667 | 9063 |
| 009345 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:45pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595635.7 | 510290.4 | 65045 | 1.64041666667 | 9345 |
| 009386 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:46pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595632.8 | 510288.7 | 65047 | 1.64041666667 | 9386 |
| 008556 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:47pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595629.7 | 510286.8 | 65049 | 1.64041666667 | 8556 |
| 009879 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:48pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595627.0 | 510285.2 | 65051 | 1.64041666667 | 9879 |
| 010479 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:49pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595623.8 | 510284.4 | 65053 | 1.64041666667 | 10479 |
| 010150 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:50pm | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595620.5 | 510283.1 | 65055 | 1.64041666667 | 10150 |
| 010547 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:51pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595618.2 | 510281.6 | 65057 | 1.64041666667 | 10547 |
| 009176 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:52pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595615.6 | 510280.5 | 65059 | 1.64041666667 | 9176 |
| 010184 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:53pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595612.4 | 510278.7 | 65061 | 1.64041666667 | 10184 |
| 011786 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:54pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595609.3 | 510277.8 | 65063 | 1.64041666667 | 11786 |
| 011016 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:55pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595605.7 | 510276.9 | 65065 | 1.64041666667 | 11016 |
| 012174 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:56pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595603.1 | 510276.1 | 65067 | 1.64041666667 | 12174 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:57pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595599.7 | 510275.4 | 65069 | 1.64041666667 | 12133 |
| 012813 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:58pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595597.1 | 510274.3 | 65071 | 1.64041666667 | 12813 |
| 011033 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:59pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595594.1 | 510272.7 | 65073 | 1.64041666667 | 11033 |
| 010438 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:00pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595591.6 | 510271.3 | 65075 | 1.64041666667 | 10438 |
| 011729 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:01pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595589.2 | 510269.3 | 65077 | 1.64041666667 | 11729 |
| 009652 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:02pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595588.0 | 510268.2 | 65079 | 1.64041666667 | 9652 |
| 010663 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:03pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595589.5 | 510267.8 | 65081 | 1.64041666667 | 10663 |
| 011665 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:04pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595591.1 | 510265.7 | 65083 | 1.64041666667 | 11665 |
| 012996 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:05pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595592.8 | 510262.8 | 65085 | 1.64041666667 | 12996 |
| 010179 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:06pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595594.0 | 510260.5 | 65087 | 1.64041666667 | 10179 |
| 010254 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:07pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595595.6 | 510259.0 | 65089 | 1.64041666667 | 10254 |
| 009883 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:08pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595594.7 | 510259.3 | 65091 | 1.64041666667 | 9883 |
| 011351 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:09pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595593.5 | 510261.0 | 65093 | 1.64041666667 | 11351 |
| 010697 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:10pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595593.4 | 510263.5 | 65095 | 1.64041666667 | 10697 |
| 010984 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:11pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595594.9 | 510265.5 | 65097 | 1.64041666667 | 10984 |
| 010636 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:12pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595596.1 | 510267.7 | 65099 | 1.64041666667 | 10636 |
| 011029 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:13pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595598.3 | 510269.0 | 65101 | 1.64041666667 | 11029 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011937 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:14pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595600.2 | 510270.5 | 65103 | 1.64041666667 | 11937 |
| 011234 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:15pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595603.5 | 510272.1 | 65105 | 1.64041666667 | 11234 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:16pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595606.1 | 510273.7 | 65107 | 1.64041666667 | 12078 |
| 011029 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:17pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595608.7 | 510275.9 | 65109 | 1.64041666667 | 11029 |
| 010857 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:18pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595611.1 | 510277.0 | 65111 | 1.64041666667 | 10857 |
| 012014 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:19pm | Sensor | 1797-S0045-G-TJV.cor | 6828.7 | 1595614.0 | 510278.7 | 65113 | 1.64041666667 | 12014 |
| 010473 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:20pm | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595616.4 | 510280.0 | 65115 | 1.64041666667 | 10473 |
| 011198 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:21pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595619.1 | 510281.3 | 65117 | 1.64041666667 | 11198 |
| 011799 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:22pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595621.6 | 510283.0 | 65119 | 1.64041666667 | 11799 |
| 010300 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:23pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595624.5 | 510284.5 | 65121 | 1.64041666667 | 10300 |
| 009865 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:24pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595627.4 | 510286.5 | 65123 | 1.64041666667 | 9865 |
| 009306 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:25pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595630.0 | 510288.2 | 65125 | 1.64041666667 | 9306 |
| 008686 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:26pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595632.3 | 510289.3 | 65127 | 1.64041666667 | 8686 |
| 010541 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:27pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595634.8 | 510291.0 | 65129 | 1.64041666667 | 10541 |
| 010525 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:28pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595637.7 | 510293.0 | 65131 | 1.64041666667 | 10525 |
| 010551 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:29pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595640.2 | 510294.7 | 65133 | 1.64041666667 | 10551 |
| 010527 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:30pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595642.3 | 510296.5 | 65135 | 1.64041666667 | 10527 |
| 011452 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:31pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595645.1 | 510297.9 | 65137 | 1.64041666667 | 11452 |
| 010033 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:32pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595648.1 | 510299.7 | 65139 | 1.64041666667 | 10033 |
| 009618 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:33pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595650.7 | 510301.2 | 65141 | 1.64041666667 | 9618 |
| 010474 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:34pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595653.5 | 510302.2 | 65143 | 1.64041666667 | 10474 |
| 013688 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:35pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595656.8 | 510303.8 | 65145 | 1.64041666667 | 13688 |
| 011282 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:36pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595659.4 | 510305.2 | 65147 | 1.64041666667 | 11282 |
| 012810 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:37pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595662.3 | 510306.3 | 65149 | 1.64041666667 | 12810 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:38pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595664.7 | 510307.8 | 65151 | 1.64041666667 | 12442 |
| 013580 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:39pm | Sensor | 1797-S0045-G-TJV.cor | 6829.7 | 1595668.0 | 510309.0 | 65153 | 1.64041666667 | 13580 |
| 013895 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:40pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595671.0 | 510310.1 | 65155 | 1.64041666667 | 13895 |
| 013463 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:41pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595673.4 | 510311.6 | 65157 | 1.64041666667 | 13463 |
| 012996 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:42pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595675.9 | 510312.8 | 65159 | 1.64041666667 | 12996 |
| 013869 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:43pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595678.9 | 510314.7 | 65161 | 1.64041666667 | 13869 |
| 012077 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:44pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595681.7 | 510315.9 | 65163 | 1.64041666667 | 12077 |
| 011629 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:45pm | Sensor | 1797-S0045-G-TJV.cor | 6830.2 | 1595684.7 | 510316.7 | 65165 | 1.64041666667 | 11629 |
| 012897 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:46pm | Sensor | 1797-S0045-G-TJV.cor | 6830.2 | 1595687.3 | 510318.0 | 65167 | 1.64041666667 | 12897 |
| 013874 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:47pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595690.4 | 510318.9 | 65169 | 1.64041666667 | 13874 |
| 013668 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:48pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595693.9 | 510319.6 | 65171 | 1.64041666667 | 13668 |
| 011997 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:49pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595696.6 | 510320.4 | 65173 | 1.64041666667 | 11997 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:50pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595699.7 | 510321.3 | 65175 | 1.64041666667 | 12539 |
| 013245 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:51pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595702.6 | 510322.4 | 65177 | 1.64041666667 | 13245 |
| 013091 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:52pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595703.2 | 510323.0 | 65179 | 1.64041666667 | 13091 |
| 013112 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:53pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595701.8 | 510322.8 | 65181 | 1.64041666667 | 13112 |
| 012098 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:54pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595701.7 | 510323.0 | 65183 | 1.64041666667 | 12098 |
| 012624 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:55pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595701.6 | 510322.9 | 65185 | 1.64041666667 | 12624 |
| 012396 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:56pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595701.6 | 510322.9 | 65187 | 1.64041666667 | 12396 |
| 013329 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:57pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595701.6 | 510322.9 | 65189 | 1.64041666667 | 13329 |
| 012722 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:58pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595701.6 | 510322.9 | 65191 | 1.64041666667 | 12722 |
| 011670 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:59pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595701.7 | 510323.0 | 65193 | 1.64041666667 | 11670 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:00pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595702.4 | 510323.1 | 65195 | 1.64041666667 | 12975 |
| 013832 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:01pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595702.4 | 510323.1 | 65197 | 1.64041666667 | 13832 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014288 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:02pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595702.2 | 510323.1 | 65199 | 1.64041666667 | 14288 |
| 013682 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:03pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595702.5 | 510323.0 | 65201 | 1.64041666667 | 13682 |
| 012690 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:04pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595702.9 | 510323.3 | 65203 | 1.64041666667 | 12690 |
| 013852 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:05pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595702.9 | 510323.7 | 65205 | 1.64041666667 | 13852 |
| 013513 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:06pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595703.0 | 510323.7 | 65207 | 1.64041666667 | 13513 |
| 013308 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:07pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595703.4 | 510323.8 | 65209 | 1.64041666667 | 13308 |
| 013617 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:08pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595704.0 | 510322.9 | 65211 | 1.64041666667 | 13617 |
| 013334 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:09pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595705.2 | 510320.4 | 65213 | 1.64041666667 | 13334 |
| 013533 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:10pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595705.2 | 510317.5 | 65215 | 1.64041666667 | 13533 |
| 013133 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:11pm | Sensor | 1797-S0045-G-TJV.cor | 6830.2 | 1595703.5 | 510314.8 | 65217 | 1.64041666667 | 13133 |
| 014593 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:12pm | Sensor | 1797-S0045-G-TJV.cor | 6830.4 | 1595700.9 | 510313.0 | 65219 | 1.64041666667 | 14593 |
| 013008 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:13pm | Sensor | 1797-S0045-G-TJV.cor | 6830.2 | 1595698.7 | 510311.0 | 65221 | 1.64041666667 | 13008 |
| 014772 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:14pm | Sensor | 1797-S0045-G-TJV.cor | 6830.3 | 1595696.1 | 510308.9 | 65223 | 1.64041666667 | 14772 |
| 013653 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:15pm | Sensor | 1797-S0045-G-TJV.cor | 6830.5 | 1595693.5 | 510307.4 | 65225 | 1.64041666667 | 13653 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:16pm | Sensor | 1797-S0045-G-TJV.cor | 6830.5 | 1595691.3 | 510305.7 | 65227 | 1.64041666667 | 12803 |
| 013460 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:17pm | Sensor | 1797-S0045-G-TJV.cor | 6830.5 | 1595688.3 | 510304.4 | 65229 | 1.64041666667 | 13460 |
| 011165 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:18pm | Sensor | 1797-S0045-G-TJV.cor | 6830.3 | 1595685.6 | 510303.0 | 65231 | 1.64041666667 | 11165 |
| 012151 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:19pm | Sensor | 1797-S0045-G-TJV.cor | 6830.1 | 1595682.8 | 510301.4 | 65233 | 1.64041666667 | 12151 |
| 011287 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:20pm | Sensor | 1797-S0045-G-TJV.cor | 6830.2 | 1595680.1 | 510300.3 | 65235 | 1.64041666667 | 11287 |
| 012752 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:21pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595677.2 | 510298.4 | 65237 | 1.64041666667 | 12752 |
| 012518 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:22pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595674.4 | 510297.0 | 65239 | 1.64041666667 | 12518 |
| 012519 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:23pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595671.5 | 510295.6 | 65241 | 1.64041666667 | 12519 |
| 012190 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:24pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595669.6 | 510294.3 | 65243 | 1.64041666667 | 12190 |
| 011027 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:25pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595666.7 | 510292.8 | 65245 | 1.64041666667 | 11027 |
| 012566 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:26pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595664.5 | 510291.0 | 65247 | 1.64041666667 | 12566 |
| 013911 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:27pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595661.8 | 510288.9 | 65249 | 1.64041666667 | 13911 |
| 013918 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:28pm | Sensor | 1797-S0045-G-TJV.cor | 6830.0 | 1595659.5 | 510287.7 | 65251 | 1.64041666667 | 13918 |
| 012329 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:29pm | Sensor | 1797-S0045-G-TJV.cor | 6829.9 | 1595657.0 | 510285.8 | 65253 | 1.64041666667 | 12329 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:30pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595654.2 | 510283.9 | 65255 | 1.64041666667 | 11962 |
| 013940 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:31pm | Sensor | 1797-S0045-G-TJV.cor | 6829.8 | 1595651.4 | 510282.1 | 65257 | 1.64041666667 | 13940 |
| 012605 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:32pm | Sensor | 1797-S0045-G-TJV.cor | 6829.6 | 1595649.0 | 510280.8 | 65259 | 1.64041666667 | 12605 |
| 012601 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:33pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595645.8 | 510279.7 | 65261 | 1.64041666667 | 12601 |
| 014040 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:34pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595643.1 | 510278.1 | 65263 | 1.64041666667 | 14040 |
| 013440 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:35pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595640.1 | 510276.5 | 65265 | 1.64041666667 | 13440 |
| 013380 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:36pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595636.9 | 510275.6 | 65267 | 1.64041666667 | 13380 |
| 011175 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:37pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595633.4 | 510274.7 | 65269 | 1.64041666667 | 11175 |
| 010533 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:38pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595630.7 | 510274.3 | 65271 | 1.64041666667 | 10533 |
| 012863 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:39pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595627.3 | 510273.7 | 65273 | 1.64041666667 | 12863 |
| 011916 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:40pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595624.7 | 510271.8 | 65275 | 1.64041666667 | 11916 |
| 012339 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:41pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595621.7 | 510269.9 | 65277 | 1.64041666667 | 12339 |
| 011874 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:42pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595619.2 | 510268.7 | 65279 | 1.64041666667 | 11874 |
| 011068 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:43pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595616.6 | 510267.3 | 65281 | 1.64041666667 | 11068 |
| 011377 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:44pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595613.6 | 510266.4 | 65283 | 1.64041666667 | 11377 |
| 013014 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:45pm | Sensor | 1797-S0045-G-TJV.cor | 6828.9 | 1595610.6 | 510264.9 | 65285 | 1.64041666667 | 13014 |
| 012763 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:46pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595607.9 | 510263.2 | 65287 | 1.64041666667 | 12763 |
| 011501 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:47pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595605.0 | 510261.7 | 65289 | 1.64041666667 | 11501 |
| 012145 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:48pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595602.1 | 510260.0 | 65291 | 1.64041666667 | 12145 |
| 011196 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:49pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595598.8 | 510258.9 | 65293 | 1.64041666667 | 11196 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010119 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:50pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595596.1 | 510258.3 | 65295 | 1.64041666667 | 10119 |
| 011019 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:51pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595596.4 | 510259.0 | 65297 | 1.64041666667 | 11019 |
| 011875 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:52pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595595.3 | 510258.6 | 65299 | 1.64041666667 | 11875 |
| 011608 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:53pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595594.5 | 510257.6 | 65301 | 1.64041666667 | 11608 |
| 010312 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:54pm | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595594.0 | 510258.0 | 65303 | 1.64041666667 | 10312 |
| 011128 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:55pm | Sensor | 1797-S0045-G-TJV.cor | 6829.5 | 1595592.1 | 510260.1 | 65305 | 1.64041666667 | 11128 |
| 009592 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:56pm | Sensor | 1797-S0045-G-TJV.cor | 6829.4 | 1595589.7 | 510262.0 | 65307 | 1.64041666667 | 9592 |
| 012118 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:57pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595587.2 | 510265.0 | 65309 | 1.64041666667 | 12118 |
| 009899 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:58pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595584.7 | 510267.6 | 65311 | 1.64041666667 | 9899 |
| 009075 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:59pm | Sensor | 1797-S0045-G-TJV.cor | 6829.3 | 1595582.0 | 510269.9 | 65313 | 1.64041666667 | 9075 |
| 010177 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:00pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595579.3 | 510271.7 | 65315 | 1.64041666667 | 10177 |
| 013407 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:01pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595575.7 | 510274.2 | 65317 | 1.64041666667 | 13407 |
| 013641 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:02pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595572.6 | 510276.5 | 65319 | 1.64041666667 | 13641 |
| 012770 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:03pm | Sensor | 1797-S0045-G-TJV.cor | 6829.2 | 1595569.7 | 510279.0 | 65321 | 1.64041666667 | 12770 |
| 012492 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:04pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595567.3 | 510281.5 | 65323 | 1.64041666667 | 12492 |
| 013413 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:05pm | Sensor | 1797-S0045-G-TJV.cor | 6829.1 | 1595564.7 | 510284.5 | 65325 | 1.64041666667 | 13413 |
| 010403 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:06pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595562.1 | 510286.8 | 65327 | 1.64041666667 | 10403 |
| 011600 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:07pm | Sensor | 1797-S0045-G-TJV.cor | 6829.0 | 1595558.6 | 510288.5 | 65329 | 1.64041666667 | 11600 |
| 010640 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:08pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595555.3 | 510290.5 | 65331 | 1.64041666667 | 10640 |
| 011570 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:09pm | Sensor | 1797-S0045-G-TJV.cor | 6828.8 | 1595552.0 | 510292.7 | 65333 | 1.64041666667 | 11570 |
| 011322 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:10pm | Sensor | 1797-S0045-G-TJV.cor | 6828.6 | 1595549.1 | 510294.9 | 65335 | 1.64041666667 | 11322 |
| 012190 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:11pm | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595546.1 | 510297.7 | 65337 | 1.64041666667 | 12190 |
| 013217 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:12pm | Sensor | 1797-S0045-G-TJV.cor | 6828.5 | 1595543.3 | 510300.8 | 65339 | 1.64041666667 | 13217 |
| 012994 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:13pm | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595540.9 | 510304.3 | 65341 | 1.64041666667 | 12994 |
| 011588 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:14pm | Sensor | 1797-S0045-G-TJV.cor | 6828.4 | 1595539.5 | 510307.6 | 65343 | 1.64041666667 | 11588 |
| 012467 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:15pm | Sensor | 1797-S0045-G-TJV.cor | 6828.3 | 1595539.9 | 510311.6 | 65345 | 1.64041666667 | 12467 |
| 012716 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:16pm | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595541.4 | 510315.0 | 65347 | 1.64041666667 | 12716 |
| 012389 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:17pm | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595543.0 | 510319.1 | 65349 | 1.64041666667 | 12389 |
| 012307 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:18pm | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595544.4 | 510322.5 | 65351 | 1.64041666667 | 12307 |
| 011896 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:19pm | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595545.3 | 510325.4 | 65353 | 1.64041666667 | 11896 |
| 013234 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:20pm | Sensor | 1797-S0045-G-TJV.cor | 6828.1 | 1595546.6 | 510328.3 | 65355 | 1.64041666667 | 13234 |
| 013268 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:21pm | Sensor | 1797-S0045-G-TJV.cor | 6828.2 | 1595548.4 | 510331.8 | 65357 | 1.64041666667 | 13268 |
| 012287 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:22pm | Sensor | 1797-S0045-G-TJV.cor | 6828.0 | 1595550.0 | 510334.9 | 65359 | 1.64041666667 | 12287 |
| 013721 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:23pm | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595552.2 | 510338.4 | 65361 | 1.64041666667 | 13721 |
| 013390 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:24pm | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595555.0 | 510341.3 | 65363 | 1.64041666667 | 13390 |
| 013877 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:25pm | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595557.9 | 510344.0 | 65365 | 1.64041666667 | 13877 |
| 013309 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:26pm | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595560.1 | 510346.8 | 65367 | 1.64041666667 | 13309 |
| 012147 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:27pm | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595561.7 | 510349.7 | 65369 | 1.64041666667 | 12147 |
| 012547 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:28pm | Sensor | 1797-S0045-G-TJV.cor | 6827.9 | 1595563.1 | 510352.4 | 65371 | 1.64041666667 | 12547 |
| 012406 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:29pm | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595563.9 | 510355.2 | 65373 | 1.64041666667 | 12406 |
| 013901 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:30pm | Sensor | 1797-S0045-G-TJV.cor | 6827.8 | 1595564.3 | 510358.0 | 65375 | 1.64041666667 | 13901 |
| 012385 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:31pm | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595565.2 | 510361.3 | 65377 | 1.64041666667 | 12385 |
| 012876 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:32pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595566.5 | 510364.9 | 65379 | 1.64041666667 | 12876 |
| 014409 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:33pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595567.9 | 510368.6 | 65381 | 1.64041666667 | 14409 |
| 013622 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:34pm | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595569.4 | 510371.7 | 65383 | 1.64041666667 | 13622 |
| 013875 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:35pm | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595570.7 | 510374.3 | 65385 | 1.64041666667 | 13875 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:36pm | Sensor | 1797-S0045-G-TJV.cor | 6827.0 | 1595572.1 | 510376.9 | 65387 | 1.64041666667 | 12768 |
| 012462 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:37pm | Sensor | 1797-S0045-G-TJV.cor | 6827.1 | 1595573.3 | 510379.7 | 65389 | 1.64041666667 | 12462 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012775 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:38pm | Sensor | 1797-S0045-G-TJV.cor | 6827.0 | 1595574.7 | 510381.7 | 65391 | 1.64041666667 | 12775 |
| 012944 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:39pm | Sensor | 1797-S0045-G-TJV.cor | 6826.9 | 1595576.9 | 510383.4 | 65393 | 1.64041666667 | 12944 |
| 011906 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:40pm | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595579.1 | 510383.5 | 65395 | 1.64041666667 | 11906 |
| 012636 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:41pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595582.2 | 510382.0 | 65397 | 1.64041666667 | 12636 |
| 012609 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:42pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595585.1 | 510381.7 | 65399 | 1.64041666667 | 12609 |
| 013652 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:43pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595588.7 | 510381.8 | 65401 | 1.64041666667 | 13652 |
| 011303 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:44pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595591.3 | 510382.3 | 65403 | 1.64041666667 | 11303 |
| 013175 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:45pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595594.6 | 510383.2 | 65405 | 1.64041666667 | 13175 |
| 013584 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:46pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595597.5 | 510383.1 | 65407 | 1.64041666667 | 13584 |
| 014346 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:47pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595600.5 | 510383.3 | 65409 | 1.64041666667 | 14346 |
| 013966 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:48pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595603.4 | 510383.4 | 65411 | 1.64041666667 | 13966 |
| 013871 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:49pm | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595606.1 | 510383.1 | 65413 | 1.64041666667 | 13871 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:50pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595608.5 | 510382.6 | 65415 | 1.64041666667 | 12918 |
| 012799 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:51pm | Sensor | 1797-S0045-G-TJV.cor | 6827.1 | 1595610.6 | 510381.0 | 65417 | 1.64041666667 | 12799 |
| 014989 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:52pm | Sensor | 1797-S0045-G-TJV.cor | 6826.8 | 1595610.9 | 510380.8 | 65419 | 1.64041666667 | 14989 |
| 014907 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:53pm | Sensor | 1797-S0045-G-TJV.cor | 6826.2 | 1595611.1 | 510380.4 | 65421 | 1.64041666667 | 14907 |
| 014047 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:54pm | Sensor | 1797-S0045-G-TJV.cor | 6826.1 | 1595611.2 | 510380.3 | 65423 | 1.64041666667 | 14047 |
| 013981 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:55pm | Sensor | 1797-S0045-G-TJV.cor | 6827.0 | 1595610.4 | 510380.7 | 65425 | 1.64041666667 | 13981 |
| 014055 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:56pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595608.7 | 510381.2 | 65427 | 1.64041666667 | 14055 |
| 012123 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:57pm | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595609.2 | 510381.0 | 65429 | 1.64041666667 | 12123 |
| 013771 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:58pm | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595608.9 | 510380.9 | 65431 | 1.64041666667 | 13771 |
| 014782 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:59pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.4 | 510381.3 | 65433 | 1.64041666667 | 14782 |
| 014765 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:00pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.4 | 510381.0 | 65435 | 1.64041666667 | 14765 |
| 013771 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:01pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.4 | 510381.0 | 65437 | 1.64041666667 | 13771 |
| 011992 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:02pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.5 | 510381.0 | 65439 | 1.64041666667 | 11992 |
| 013678 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:03pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.4 | 510381.1 | 65441 | 1.64041666667 | 13678 |
| 013379 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:04pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.6 | 510381.1 | 65443 | 1.64041666667 | 13379 |
| 012285 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:05pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.6 | 510381.2 | 65445 | 1.64041666667 | 12285 |
| 013151 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:06pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.5 | 510381.5 | 65447 | 1.64041666667 | 13151 |
| 012407 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:07pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.5 | 510381.6 | 65449 | 1.64041666667 | 12407 |
| 013151 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:08pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.4 | 510381.5 | 65451 | 1.64041666667 | 13151 |
| 013008 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:09pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.1 | 510381.1 | 65453 | 1.64041666667 | 13008 |
| 013002 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:10pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.0 | 510381.0 | 65455 | 1.64041666667 | 13002 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:11pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.0 | 510381.0 | 65457 | 1.64041666667 | 12760 |
| 012970 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:12pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595609.1 | 510381.0 | 65459 | 1.64041666667 | 12970 |
| 014522 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:13pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.3 | 510381.4 | 65461 | 1.64041666667 | 14522 |
| 013410 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:14pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.4 | 510381.7 | 65463 | 1.64041666667 | 13410 |
| 013912 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:15pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.2 | 510381.5 | 65465 | 1.64041666667 | 13912 |
| 012358 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:16pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.2 | 510381.4 | 65467 | 1.64041666667 | 12358 |
| 012299 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:17pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.3 | 510381.4 | 65469 | 1.64041666667 | 12299 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:18pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.3 | 510381.4 | 65471 | 1.64041666667 | 12255 |
| 012393 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:19pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.3 | 510381.5 | 65473 | 1.64041666667 | 12393 |
| 011948 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:20pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.4 | 510381.6 | 65475 | 1.64041666667 | 11948 |
| 013277 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:21pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.5 | 510381.9 | 65477 | 1.64041666667 | 13277 |
| 014149 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:22pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.4 | 510381.8 | 65479 | 1.64041666667 | 14149 |
| 015447 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:23pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595609.4 | 510381.8 | 65481 | 1.64041666667 | 15447 |
| 013732 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:24pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595608.9 | 510382.0 | 65483 | 1.64041666667 | 13732 |
| 012553 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:25pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595608.2 | 510383.2 | 65485 | 1.64041666667 | 12553 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014628 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:26pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595608.2 | 510384.1 | 65487 | 1.64041666667 | 14628 |
| 014757 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:27pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595608.3 | 510384.3 | 65489 | 1.64041666667 | 14757 |
| 013649 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:28pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595608.4 | 510384.4 | 65491 | 1.64041666667 | 13649 |
| 014032 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:29pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595608.4 | 510384.4 | 65493 | 1.64041666667 | 14032 |
| 013136 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:30pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595608.2 | 510384.3 | 65495 | 1.64041666667 | 13136 |
| 013102 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:31pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595607.6 | 510383.8 | 65497 | 1.64041666667 | 13102 |
| 012305 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:32pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595607.8 | 510383.6 | 65499 | 1.64041666667 | 12305 |
| 012736 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:33pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595608.6 | 510384.3 | 65501 | 1.64041666667 | 12736 |
| 011644 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:34pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.6 | 510384.7 | 65503 | 1.64041666667 | 11644 |
| 012361 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:35pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595608.0 | 510386.2 | 65505 | 1.64041666667 | 12361 |
| 012360 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:36pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595606.2 | 510388.5 | 65507 | 1.64041666667 | 12360 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:37pm | Sensor | 1797-S0045-G-TJV.cor | 6827.1 | 1595604.0 | 510390.7 | 65509 | 1.64041666667 | 12960 |
| 015870 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:38pm | Sensor | 1797-S0045-G-TJV.cor | 6827.0 | 1595601.9 | 510393.1 | 65511 | 1.64041666667 | 15870 |
| 014617 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:39pm | Sensor | 1797-S0045-G-TJV.cor | 6827.0 | 1595599.9 | 510395.4 | 65513 | 1.64041666667 | 14617 |
| 012174 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:40pm | Sensor | 1797-S0045-G-TJV.cor | 6826.9 | 1595598.4 | 510396.7 | 65515 | 1.64041666667 | 12174 |
| 012253 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:41pm | Sensor | 1797-S0045-G-TJV.cor | 6826.9 | 1595597.6 | 510396.4 | 65517 | 1.64041666667 | 12253 |
| 012667 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:42pm | Sensor | 1797-S0045-G-TJV.cor | 6826.9 | 1595597.0 | 510394.2 | 65519 | 1.64041666667 | 12667 |
| 013793 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:43pm | Sensor | 1797-S0045-G-TJV.cor | 6827.1 | 1595596.0 | 510391.1 | 65521 | 1.64041666667 | 13793 |
| 015058 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:44pm | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595594.8 | 510388.6 | 65523 | 1.64041666667 | 15058 |
| 012674 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:45pm | Sensor | 1797-S0045-G-TJV.cor | 6827.1 | 1595594.2 | 510385.7 | 65525 | 1.64041666667 | 12674 |
| 012498 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:46pm | Sensor | 1797-S0045-G-TJV.cor | 6827.2 | 1595594.6 | 510384.3 | 65527 | 1.64041666667 | 12498 |
| 011584 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:47pm | Sensor | 1797-S0045-G-TJV.cor | 6827.3 | 1595596.7 | 510383.6 | 65529 | 1.64041666667 | 11584 |
| 013906 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:48pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595598.8 | 510384.0 | 65531 | 1.64041666667 | 13906 |
| 013616 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:49pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595602.2 | 510384.0 | 65533 | 1.64041666667 | 13616 |
| 013994 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:50pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595605.4 | 510383.7 | 65535 | 1.64041666667 | 13994 |
| 013158 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:51pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595608.1 | 510382.7 | 65537 | 1.64041666667 | 13158 |
| 013849 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:52pm | Sensor | 1797-S0045-G-TJV.cor | 6827.4 | 1595609.0 | 510381.3 | 65539 | 1.64041666667 | 13849 |
| 013872 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:53pm | Sensor | 1797-S0045-G-TJV.cor | 6827.5 | 1595607.3 | 510379.3 | 65541 | 1.64041666667 | 13872 |
| 014208 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:54pm | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595605.7 | 510378.0 | 65543 | 1.64041666667 | 14208 |
| 012882 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:55pm | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595604.4 | 510377.3 | 65545 | 1.64041666667 | 12882 |
| 012130 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:56pm | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595604.4 | 510377.2 | 65547 | 1.64041666667 | 12130 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:57pm | Sensor | 1797-S0045-G-TJV.cor | 6827.6 | 1595604.6 | 510377.4 | 65549 | 1.64041666667 | 14132 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:58pm | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595604.7 | 510377.3 | 65551 | 1.64041666667 | 12743 |
| 013835 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:59pm | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595604.6 | 510377.3 | 65553 | 1.64041666667 | 13835 |
| 012489 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:00pm | Sensor | 1797-S0045-G-TJV.cor | 6827.7 | 1595604.5 | 510377.4 | 65598 | 1.64041666667 | 12489 |
| 012187 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:57pm | Sensor | 1797-S0044-G-636-DTE | 6842.1 | 1595027.0 | 513150.3 | 60989 | 1.64041666667 | 12187 |
| 012210 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:58pm | Sensor | 1797-S0044-G-636-DTE | 6842.7 | 1595026.7 | 513150.2 | 60990 | 1.64041666667 | 12210 |
| 011975 | 0 | GeoXH 6000 | 08/19/2015 | 12:28:59pm | Sensor | 1797-S0044-G-636-DTE | 6843.6 | 1595026.3 | 513150.1 | 60991 | 1.64041666667 | 11975 |
| 011946 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:41pm | Sensor | 1797-S0044-G-636-DTE | 6875.0 | 1595012.2 | 513145.1 | 60992 | 1.64041666667 | 11946 |
| 011610 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:42pm | Sensor | 1797-S0044-G-636-DTE | 6875.6 | 1595011.9 | 513145.0 | 60993 | 1.64041666667 | 11610 |
| 011525 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:43pm | Sensor | 1797-S0044-G-636-DTE | 6876.4 | 1595011.6 | 513144.9 | 60994 | 1.64041666667 | 11525 |
| 011545 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:44pm | Sensor | 1797-S0044-G-636-DTE | 6877.1 | 1595011.2 | 513144.8 | 60995 | 1.64041666667 | 11545 |
| 011999 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:45pm | Sensor | 1797-S0044-G-636-DTE | 6878.1 | 1595010.8 | 513144.7 | 60996 | 1.64041666667 | 11999 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:46pm | Sensor | 1797-S0044-G-636-DTE | 6878.8 | 1595010.5 | 513144.5 | 60997 | 1.64041666667 | 11962 |
| 011233 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:48pm | Sensor | 1797-S0044-G-636-DTE | 6880.2 | 1595009.9 | 513144.3 | 60998 | 1.64041666667 | 11233 |
| 011231 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:49pm | Sensor | 1797-S0044-G-636-DTE | 6881.0 | 1595009.5 | 513144.2 | 60999 | 1.64041666667 | 11231 |
| 011822 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:50pm | Sensor | 1797-S0044-G-636-DTE | 6881.7 | 1595009.2 | 513144.1 | 61000 | 1.64041666667 | 11822 |
| 012147 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:51pm | Sensor | 1797-S0044-G-636-DTE | 6882.6 | 1595008.8 | 513143.9 | 61001 | 1.64041666667 | 12147 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012383 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:52pm | Sensor | 1797-S0044-G-636-DTE | 6860.6 | 1595019.6 | 513147.1 | 61003 | 1.64041666667 | 12383 |
| 011623 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:53pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595033.9 | 513151.3 | 61005 | 1.64041666667 | 11623 |
| 011735 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:54pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595033.9 | 513151.2 | 61007 | 1.64041666667 | 11735 |
| 011941 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:55pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595033.9 | 513151.3 | 61009 | 1.64041666667 | 11941 |
| 011966 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:56pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595033.9 | 513151.3 | 61011 | 1.64041666667 | 11966 |
| 012161 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:57pm | Sensor | 1797-S0044-G-636-DTE | 6830.5 | 1595033.2 | 513151.7 | 61013 | 1.64041666667 | 12161 |
| 011693 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:58pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.4 | 513152.2 | 61015 | 1.64041666667 | 11693 |
| 012112 | 0 | GeoXH 6000 | 08/19/2015 | 12:29:59pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.4 | 513152.1 | 61017 | 1.64041666667 | 12112 |
| 011996 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:00pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.4 | 513152.0 | 61019 | 1.64041666667 | 11996 |
| 011517 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:01pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.4 | 513152.0 | 61021 | 1.64041666667 | 11517 |
| 011608 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:02pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.4 | 513152.0 | 61023 | 1.64041666667 | 11608 |
| 011883 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:03pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.4 | 513152.0 | 61025 | 1.64041666667 | 11883 |
| 011597 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:04pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61027 | 1.64041666667 | 11597 |
| 011720 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:05pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61029 | 1.64041666667 | 11720 |
| 011175 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:06pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61031 | 1.64041666667 | 11175 |
| 010568 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:07pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61033 | 1.64041666667 | 10568 |
| 011689 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:08pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61035 | 1.64041666667 | 11689 |
| 012065 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:09pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.1 | 61037 | 1.64041666667 | 12065 |
| 012169 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:10pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.1 | 61039 | 1.64041666667 | 12169 |
| 012302 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:11pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61041 | 1.64041666667 | 12302 |
| 011974 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:12pm | Sensor | 1797-S0044-G-636-DTE | 6829.9 | 1595032.3 | 513152.0 | 61043 | 1.64041666667 | 11974 |
| 011160 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:13pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61045 | 1.64041666667 | 11160 |
| 012263 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:14pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61047 | 1.64041666667 | 12263 |
| 011375 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:15pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61049 | 1.64041666667 | 11375 |
| 011993 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:16pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595032.3 | 513152.0 | 61051 | 1.64041666667 | 11993 |
| 011058 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:17pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595032.3 | 513152.0 | 61053 | 1.64041666667 | 11058 |
| 010690 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:18pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61055 | 1.64041666667 | 10690 |
| 011736 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:19pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61057 | 1.64041666667 | 11736 |
| 011379 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:20pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.0 | 61059 | 1.64041666667 | 11379 |
| 011650 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:21pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.1 | 61061 | 1.64041666667 | 11650 |
| 011466 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:22pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.1 | 61063 | 1.64041666667 | 11466 |
| 011834 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:23pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.1 | 61065 | 1.64041666667 | 11834 |
| 011554 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:24pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.3 | 513152.1 | 61067 | 1.64041666667 | 11554 |
| 010384 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:25pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595032.2 | 513152.0 | 61069 | 1.64041666667 | 10384 |
| 011661 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:26pm | Sensor | 1797-S0044-G-636-DTE | 6829.9 | 1595031.9 | 513152.0 | 61071 | 1.64041666667 | 11661 |
| 012034 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:27pm | Sensor | 1797-S0044-G-636-DTE | 6829.9 | 1595031.6 | 513152.1 | 61073 | 1.64041666667 | 12034 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:28pm | Sensor | 1797-S0044-G-636-DTE | 6829.9 | 1595031.8 | 513152.1 | 61075 | 1.64041666667 | 12536 |
| 012062 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:29pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.2 | 61077 | 1.64041666667 | 12062 |
| 011727 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:30pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.2 | 61079 | 1.64041666667 | 11727 |
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:31pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.3 | 61081 | 1.64041666667 | 12019 |
| 012813 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:32pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.3 | 61083 | 1.64041666667 | 12813 |
| 012772 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:33pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.3 | 61085 | 1.64041666667 | 12772 |
| 011954 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:34pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.3 | 61087 | 1.64041666667 | 11954 |
| 012649 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:35pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.3 | 61089 | 1.64041666667 | 12649 |
| 012387 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:36pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.3 | 61091 | 1.64041666667 | 12387 |
| 012015 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:37pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.3 | 61093 | 1.64041666667 | 12015 |
| 012511 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:38pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.3 | 61095 | 1.64041666667 | 12511 |
| 012902 | 0 | GeoXH 6000 | 08/19/2015 | 12:30:39pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.3 | 61097 | 1.64041666667 | 12902 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010875 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:28pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.4 | 61195 | 1.64041666667 | 10875 |
| 010512 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:29pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.5 | 61197 | 1.64041666667 | 10512 |
| 011253 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:30pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.4 | 61199 | 1.64041666667 | 11253 |
| 011452 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:31pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.4 | 61201 | 1.64041666667 | 11452 |
| 012457 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:32pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.5 | 61203 | 1.64041666667 | 12457 |
| 012024 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:33pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.7 | 513152.4 | 61205 | 1.64041666667 | 12024 |
| 012284 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:34pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.4 | 61207 | 1.64041666667 | 12284 |
| 011574 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:35pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.8 | 513152.5 | 61209 | 1.64041666667 | 11574 |
| 011123 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:36pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.8 | 513152.5 | 61211 | 1.64041666667 | 11123 |
| 011964 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:37pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.8 | 513152.5 | 61213 | 1.64041666667 | 11964 |
| 011950 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:38pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.5 | 61215 | 1.64041666667 | 11950 |
| 011716 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:39pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.6 | 61217 | 1.64041666667 | 11716 |
| 011923 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:40pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.5 | 61219 | 1.64041666667 | 11923 |
| 012039 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:41pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.5 | 61221 | 1.64041666667 | 12039 |
| 011024 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:42pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.4 | 61223 | 1.64041666667 | 11024 |
| 011061 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:43pm | Sensor | 1797-S0044-G-636-DTE | 6829.9 | 1595031.6 | 513152.4 | 61225 | 1.64041666667 | 11061 |
| 010857 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:44pm | Sensor | 1797-S0044-G-636-DTE | 6829.9 | 1595031.6 | 513152.4 | 61227 | 1.64041666667 | 10857 |
| 010802 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:45pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.6 | 513152.4 | 61229 | 1.64041666667 | 10802 |
| 010996 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:46pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.6 | 513152.4 | 61231 | 1.64041666667 | 10996 |
| 011292 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:47pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.4 | 61233 | 1.64041666667 | 11292 |
| 011422 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:48pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.5 | 61235 | 1.64041666667 | 11422 |
| 011555 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:49pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.7 | 513152.5 | 61237 | 1.64041666667 | 11555 |
| 011847 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:50pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.5 | 61239 | 1.64041666667 | 11847 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:51pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.5 | 61241 | 1.64041666667 | 11959 |
| 011699 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:52pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.5 | 61243 | 1.64041666667 | 11699 |
| 011133 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:53pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.5 | 61245 | 1.64041666667 | 11133 |
| 011170 | 0 | GeoXH 6000 | 08/19/2015 | 12:31:54pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.8 | 513152.5 | 61247 | 1.64041666667 | 11170 |
| 011278 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:00pm | Sensor | 1797-S0044-G-636-DTE | 6829.6 | 1595031.7 | 513152.4 | 61249 | 1.64041666667 | 11278 |
| 010732 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:01pm | Sensor | 1797-S0044-G-636-DTE | 6829.6 | 1595031.7 | 513152.4 | 61251 | 1.64041666667 | 10732 |
| 011061 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:02pm | Sensor | 1797-S0044-G-636-DTE | 6829.6 | 1595031.7 | 513152.4 | 61253 | 1.64041666667 | 11061 |
| 011262 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:03pm | Sensor | 1797-S0044-G-636-DTE | 6829.6 | 1595031.7 | 513152.5 | 61255 | 1.64041666667 | 11262 |
| 011240 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:04pm | Sensor | 1797-S0044-G-636-DTE | 6829.6 | 1595031.7 | 513152.5 | 61257 | 1.64041666667 | 11240 |
| 011025 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:05pm | Sensor | 1797-S0044-G-636-DTE | 6829.6 | 1595031.7 | 513152.5 | 61259 | 1.64041666667 | 11025 |
| 011339 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:06pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.7 | 513152.6 | 61261 | 1.64041666667 | 11339 |
| 011905 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:07pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.7 | 513152.6 | 61263 | 1.64041666667 | 11905 |
| 011639 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:08pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.7 | 513152.6 | 61265 | 1.64041666667 | 11639 |
| 011692 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:09pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.7 | 513152.5 | 61267 | 1.64041666667 | 11692 |
| 011534 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:10pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.7 | 513152.5 | 61269 | 1.64041666667 | 11534 |
| 011543 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:11pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.7 | 513152.5 | 61271 | 1.64041666667 | 11543 |
| 011038 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:12pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.6 | 513152.5 | 61273 | 1.64041666667 | 11038 |
| 010536 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:13pm | Sensor | 1797-S0044-G-636-DTE | 6829.8 | 1595031.6 | 513152.4 | 61275 | 1.64041666667 | 10536 |
| 010531 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:14pm | Sensor | 1797-S0044-G-636-DTE | 6829.7 | 1595031.9 | 513152.4 | 61277 | 1.64041666667 | 10531 |
| 010634 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:15pm | Sensor | 1797-S0044-G-636-DTE | 6829.6 | 1595032.3 | 513152.5 | 61279 | 1.64041666667 | 10634 |
| 011186 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:16pm | Sensor | 1797-S0044-G-636-DTE | 6830.1 | 1595032.4 | 513151.8 | 61281 | 1.64041666667 | 11186 |
| 011205 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:17pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595032.7 | 513152.0 | 61283 | 1.64041666667 | 11205 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:18pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595032.7 | 513153.2 | 61285 | 1.64041666667 | 12475 |
| 013002 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:19pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595032.7 | 513153.4 | 61287 | 1.64041666667 | 13002 |
| 011941 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:20pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595032.3 | 513153.0 | 61289 | 1.64041666667 | 11941 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011817 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:21pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595031.2 | 513151.9 | 61291 | 1.64041666667 | 11817 |
| 011904 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:22pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595029.0 | 513150.1 | 61293 | 1.64041666667 | 11904 |
| 010799 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:23pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595025.5 | 513148.2 | 61295 | 1.64041666667 | 10799 |
| 010927 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:24pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595022.3 | 513146.2 | 61297 | 1.64041666667 | 10927 |
| 011306 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:25pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595019.2 | 513143.4 | 61299 | 1.64041666667 | 11306 |
| 011730 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:26pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595016.4 | 513140.6 | 61301 | 1.64041666667 | 11730 |
| 011593 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:27pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595013.0 | 513138.3 | 61303 | 1.64041666667 | 11593 |
| 011688 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:28pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595010.2 | 513137.0 | 61305 | 1.64041666667 | 11688 |
| 012034 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:29pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595007.3 | 513135.1 | 61307 | 1.64041666667 | 12034 |
| 011644 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:30pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595006.1 | 513132.5 | 61309 | 1.64041666667 | 11644 |
| 012025 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:31pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595006.2 | 513128.1 | 61311 | 1.64041666667 | 12025 |
| 011571 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:32pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595007.3 | 513124.9 | 61313 | 1.64041666667 | 11571 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:33pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595009.2 | 513121.4 | 61315 | 1.64041666667 | 11241 |
| 012165 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:34pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595010.9 | 513118.3 | 61317 | 1.64041666667 | 12165 |
| 012363 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:35pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595012.8 | 513115.0 | 61319 | 1.64041666667 | 12363 |
| 012354 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:36pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595014.6 | 513112.0 | 61321 | 1.64041666667 | 12354 |
| 011824 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:37pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595016.7 | 513109.1 | 61323 | 1.64041666667 | 11824 |
| 012613 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:38pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595018.8 | 513106.1 | 61325 | 1.64041666667 | 12613 |
| 012225 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:39pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595020.3 | 513102.9 | 61327 | 1.64041666667 | 12225 |
| 012231 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:40pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595021.6 | 513099.9 | 61329 | 1.64041666667 | 12231 |
| 011680 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:41pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595023.5 | 513097.1 | 61331 | 1.64041666667 | 11680 |
| 012052 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:42pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595024.7 | 513094.1 | 61333 | 1.64041666667 | 12052 |
| 011812 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:43pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595025.3 | 513090.9 | 61335 | 1.64041666667 | 11812 |
| 012487 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:44pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595026.2 | 513087.7 | 61337 | 1.64041666667 | 12487 |
| 013196 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:45pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595027.5 | 513084.4 | 61339 | 1.64041666667 | 13196 |
| 013115 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:46pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595028.9 | 513081.1 | 61341 | 1.64041666667 | 13115 |
| 012424 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:47pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595030.6 | 513078.1 | 61343 | 1.64041666667 | 12424 |
| 012096 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:48pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595032.7 | 513075.4 | 61345 | 1.64041666667 | 12096 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:49pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595034.3 | 513072.9 | 61347 | 1.64041666667 | 12106 |
| 012525 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:50pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595035.1 | 513069.9 | 61349 | 1.64041666667 | 12525 |
| 012633 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:51pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595035.1 | 513066.6 | 61351 | 1.64041666667 | 12633 |
| 013128 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:52pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595035.1 | 513062.9 | 61353 | 1.64041666667 | 13128 |
| 012904 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:53pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595035.7 | 513059.4 | 61355 | 1.64041666667 | 12904 |
| 012779 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:54pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595036.9 | 513056.1 | 61357 | 1.64041666667 | 12779 |
| 012978 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:55pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595038.3 | 513053.1 | 61359 | 1.64041666667 | 12978 |
| 013300 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:56pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595040.0 | 513050.3 | 61361 | 1.64041666667 | 13300 |
| 013038 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:57pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595041.6 | 513047.9 | 61363 | 1.64041666667 | 13038 |
| 012667 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:58pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595043.0 | 513045.7 | 61365 | 1.64041666667 | 12667 |
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 12:33:59pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595045.1 | 513044.0 | 61367 | 1.64041666667 | 12562 |
| 012121 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:00pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595047.4 | 513042.7 | 61369 | 1.64041666667 | 12121 |
| 013140 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:01pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595049.9 | 513042.1 | 61371 | 1.64041666667 | 13140 |
| 013354 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:02pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595052.6 | 513042.6 | 61373 | 1.64041666667 | 13354 |
| 013181 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:03pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595054.6 | 513043.1 | 61375 | 1.64041666667 | 13181 |
| 012529 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:04pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595055.3 | 513043.1 | 61377 | 1.64041666667 | 12529 |
| 014165 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:05pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595056.8 | 513043.6 | 61379 | 1.64041666667 | 14165 |
| 014718 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:06pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595059.6 | 513044.1 | 61381 | 1.64041666667 | 14718 |
| 014174 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:07pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595063.4 | 513045.3 | 61383 | 1.64041666667 | 14174 |
| 014295 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:08pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595066.9 | 513047.1 | 61385 | 1.64041666667 | 14295 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014498 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:09pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595071.2 | 513049.3 | 61387 | 1.64041666667 | 14498 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:10pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595074.8 | 513051.0 | 61389 | 1.64041666667 | 13593 |
| 013871 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:11pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595078.6 | 513053.0 | 61391 | 1.64041666667 | 13871 |
| 013412 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:12pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595081.8 | 513054.7 | 61393 | 1.64041666667 | 13412 |
| 013604 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:13pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595085.8 | 513056.6 | 61395 | 1.64041666667 | 13604 |
| 013540 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:14pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595089.2 | 513058.0 | 61397 | 1.64041666667 | 13540 |
| 013563 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:15pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595093.3 | 513059.3 | 61399 | 1.64041666667 | 13563 |
| 013674 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:16pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595096.9 | 513060.3 | 61401 | 1.64041666667 | 13674 |
| 013549 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:17pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595100.4 | 513062.5 | 61403 | 1.64041666667 | 13549 |
| 013374 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:18pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595103.0 | 513064.8 | 61405 | 1.64041666667 | 13374 |
| 013477 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:19pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595106.3 | 513067.3 | 61407 | 1.64041666667 | 13477 |
| 013438 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:20pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595109.7 | 513069.0 | 61409 | 1.64041666667 | 13438 |
| 013582 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:21pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595113.3 | 513070.7 | 61411 | 1.64041666667 | 13582 |
| 013159 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:22pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595115.9 | 513072.2 | 61413 | 1.64041666667 | 13159 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:23pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595119.0 | 513074.0 | 61415 | 1.64041666667 | 12742 |
| 012455 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:24pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595122.1 | 513075.6 | 61417 | 1.64041666667 | 12455 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:25pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595125.9 | 513077.7 | 61419 | 1.64041666667 | 12743 |
| 013040 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:26pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595129.0 | 513079.5 | 61421 | 1.64041666667 | 13040 |
| 012795 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:27pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595132.7 | 513081.2 | 61423 | 1.64041666667 | 12795 |
| 012709 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:28pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595136.0 | 513082.4 | 61425 | 1.64041666667 | 12709 |
| 012114 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:29pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595140.0 | 513083.6 | 61427 | 1.64041666667 | 12114 |
| 012334 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:30pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595142.9 | 513084.5 | 61429 | 1.64041666667 | 12334 |
| 012368 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:31pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595146.4 | 513086.5 | 61431 | 1.64041666667 | 12368 |
| 011682 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:32pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595148.2 | 513089.0 | 61433 | 1.64041666667 | 11682 |
| 012503 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:33pm | Sensor | 1797-S0044-G-636-DTE | 6833.6 | 1595148.0 | 513093.0 | 61435 | 1.64041666667 | 12503 |
| 011983 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:34pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595146.3 | 513096.5 | 61437 | 1.64041666667 | 11983 |
| 012605 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:35pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595144.5 | 513100.5 | 61439 | 1.64041666667 | 12605 |
| 011590 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:36pm | Sensor | 1797-S0044-G-636-DTE | 6833.5 | 1595143.2 | 513104.6 | 61441 | 1.64041666667 | 11590 |
| 012242 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:37pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595142.2 | 513108.8 | 61443 | 1.64041666667 | 12242 |
| 012848 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:38pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595140.7 | 513112.9 | 61445 | 1.64041666667 | 12848 |
| 012199 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:39pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595138.7 | 513116.4 | 61447 | 1.64041666667 | 12199 |
| 012697 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:40pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595136.4 | 513119.7 | 61449 | 1.64041666667 | 12697 |
| 011297 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:41pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595134.0 | 513123.8 | 61451 | 1.64041666667 | 11297 |
| 011619 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:42pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595132.4 | 513127.2 | 61453 | 1.64041666667 | 11619 |
| 012963 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:43pm | Sensor | 1797-S0044-G-636-DTE | 6833.5 | 1595131.0 | 513131.2 | 61455 | 1.64041666667 | 12963 |
| 012002 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:44pm | Sensor | 1797-S0044-G-636-DTE | 6833.5 | 1595129.7 | 513134.5 | 61457 | 1.64041666667 | 12002 |
| 012346 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:45pm | Sensor | 1797-S0044-G-636-DTE | 6833.6 | 1595128.5 | 513138.5 | 61459 | 1.64041666667 | 12346 |
| 011909 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:46pm | Sensor | 1797-S0044-G-636-DTE | 6833.6 | 1595127.9 | 513142.3 | 61461 | 1.64041666667 | 11909 |
| 011349 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:47pm | Sensor | 1797-S0044-G-636-DTE | 6833.5 | 1595126.1 | 513145.7 | 61463 | 1.64041666667 | 11349 |
| 011236 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:48pm | Sensor | 1797-S0044-G-636-DTE | 6833.6 | 1595124.3 | 513148.8 | 61465 | 1.64041666667 | 11236 |
| 012463 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:49pm | Sensor | 1797-S0044-G-636-DTE | 6833.5 | 1595122.0 | 513152.6 | 61467 | 1.64041666667 | 12463 |
| 011825 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:50pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595120.3 | 513155.9 | 61469 | 1.64041666667 | 11825 |
| 011369 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:51pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595117.6 | 513159.6 | 61471 | 1.64041666667 | 11369 |
| 012312 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:52pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595114.8 | 513162.4 | 61473 | 1.64041666667 | 12312 |
| 011448 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:53pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595112.4 | 513165.9 | 61475 | 1.64041666667 | 11448 |
| 012529 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:54pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595110.4 | 513168.7 | 61477 | 1.64041666667 | 12529 |
| 012050 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:55pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595108.0 | 513172.3 | 61479 | 1.64041666667 | 12050 |
| 012328 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:56pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595106.3 | 513175.3 | 61481 | 1.64041666667 | 12328 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011652 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:57pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595104.3 | 513178.4 | 61483 | 1.64041666667 | 11652 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:58pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595102.3 | 513180.3 | 61485 | 1.64041666667 | 11962 |
| 011971 | 0 | GeoXH 6000 | 08/19/2015 | 12:34:59pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595099.6 | 513181.4 | 61487 | 1.64041666667 | 11971 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:00pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595097.2 | 513181.1 | 61489 | 1.64041666667 | 11953 |
| 011283 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:01pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595095.4 | 513178.4 | 61491 | 1.64041666667 | 11283 |
| 011522 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:02pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595095.7 | 513175.0 | 61493 | 1.64041666667 | 11522 |
| 011873 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:03pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595097.1 | 513170.7 | 61495 | 1.64041666667 | 11873 |
| 011666 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:04pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595098.4 | 513166.9 | 61497 | 1.64041666667 | 11666 |
| 011940 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:05pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595100.2 | 513163.3 | 61499 | 1.64041666667 | 11940 |
| 011606 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:06pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595102.6 | 513160.0 | 61501 | 1.64041666667 | 11606 |
| 012048 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:07pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595105.7 | 513156.4 | 61503 | 1.64041666667 | 12048 |
| 011884 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:08pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595108.0 | 513153.6 | 61505 | 1.64041666667 | 11884 |
| 011440 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:09pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595110.8 | 513149.6 | 61507 | 1.64041666667 | 11440 |
| 011452 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:10pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595112.5 | 513146.0 | 61509 | 1.64041666667 | 11452 |
| 012037 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:11pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595114.1 | 513142.2 | 61511 | 1.64041666667 | 12037 |
| 012748 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:12pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595115.8 | 513138.5 | 61513 | 1.64041666667 | 12748 |
| 012698 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:13pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595117.6 | 513134.7 | 61515 | 1.64041666667 | 12698 |
| 012738 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:14pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595119.1 | 513131.4 | 61517 | 1.64041666667 | 12738 |
| 013022 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:15pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595121.0 | 513127.7 | 61519 | 1.64041666667 | 13022 |
| 012717 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:16pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595122.4 | 513124.5 | 61521 | 1.64041666667 | 12717 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:17pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595124.1 | 513121.0 | 61523 | 1.64041666667 | 12133 |
| 011550 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:18pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595126.0 | 513118.3 | 61525 | 1.64041666667 | 11550 |
| 011162 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:19pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595128.8 | 513115.2 | 61527 | 1.64041666667 | 11162 |
| 010906 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:20pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595130.8 | 513112.7 | 61529 | 1.64041666667 | 10906 |
| 010769 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:21pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595132.9 | 513109.3 | 61531 | 1.64041666667 | 10769 |
| 011900 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:22pm | Sensor | 1797-S0044-G-636-DTE | 6833.5 | 1595134.7 | 513106.2 | 61533 | 1.64041666667 | 11900 |
| 012393 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:23pm | Sensor | 1797-S0044-G-636-DTE | 6833.7 | 1595136.6 | 513103.0 | 61535 | 1.64041666667 | 12393 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:24pm | Sensor | 1797-S0044-G-636-DTE | 6833.5 | 1595139.1 | 513099.6 | 61537 | 1.64041666667 | 12431 |
| 012617 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:25pm | Sensor | 1797-S0044-G-636-DTE | 6833.7 | 1595142.2 | 513095.3 | 61539 | 1.64041666667 | 12617 |
| 012647 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:26pm | Sensor | 1797-S0044-G-636-DTE | 6833.8 | 1595144.2 | 513091.2 | 61541 | 1.64041666667 | 12647 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:27pm | Sensor | 1797-S0044-G-636-DTE | 6833.7 | 1595144.8 | 513087.4 | 61543 | 1.64041666667 | 12431 |
| 011988 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:28pm | Sensor | 1797-S0044-G-636-DTE | 6833.6 | 1595143.9 | 513084.4 | 61545 | 1.64041666667 | 11988 |
| 012765 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:29pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595140.4 | 513082.6 | 61547 | 1.64041666667 | 12765 |
| 013060 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:30pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595137.2 | 513083.5 | 61549 | 1.64041666667 | 13060 |
| 013646 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:31pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595134.5 | 513087.0 | 61551 | 1.64041666667 | 13646 |
| 013736 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:32pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595132.7 | 513090.7 | 61553 | 1.64041666667 | 13736 |
| 013066 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:33pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595130.4 | 513095.5 | 61555 | 1.64041666667 | 13066 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:34pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595128.7 | 513099.2 | 61557 | 1.64041666667 | 12420 |
| 012108 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:35pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595126.5 | 513103.1 | 61559 | 1.64041666667 | 12108 |
| 012323 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:36pm | Sensor | 1797-S0044-G-636-DTE | 6833.3 | 1595124.4 | 513106.4 | 61561 | 1.64041666667 | 12323 |
| 012572 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:37pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595122.6 | 513110.2 | 61563 | 1.64041666667 | 12572 |
| 012584 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:38pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595121.1 | 513113.8 | 61565 | 1.64041666667 | 12584 |
| 011976 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:39pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595119.1 | 513118.0 | 61567 | 1.64041666667 | 11976 |
| 012451 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:40pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595117.0 | 513121.8 | 61569 | 1.64041666667 | 12451 |
| 012681 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:41pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595114.9 | 513125.3 | 61571 | 1.64041666667 | 12681 |
| 012315 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:42pm | Sensor | 1797-S0044-G-636-DTE | 6833.2 | 1595112.9 | 513129.1 | 61573 | 1.64041666667 | 12315 |
| 011945 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:43pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595111.1 | 513132.6 | 61575 | 1.64041666667 | 11945 |
| 012134 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:44pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595109.2 | 513136.5 | 61577 | 1.64041666667 | 12134 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012503 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:45pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595107.5 | 513140.0 | 61579 | 1.64041666667 | 12503 |
| 012170 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:46pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595105.9 | 513143.6 | 61581 | 1.64041666667 | 12170 |
| 012110 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:47pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595104.1 | 513147.8 | 61583 | 1.64041666667 | 12110 |
| 012512 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:48pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595102.6 | 513151.3 | 61585 | 1.64041666667 | 12512 |
| 012580 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:49pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595100.8 | 513154.9 | 61587 | 1.64041666667 | 12580 |
| 012416 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:50pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595099.4 | 513158.7 | 61589 | 1.64041666667 | 12416 |
| 012631 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:51pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595098.3 | 513163.1 | 61591 | 1.64041666667 | 12631 |
| 011980 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:52pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595096.8 | 513166.7 | 61593 | 1.64041666667 | 11980 |
| 011748 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:53pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595094.9 | 513170.3 | 61595 | 1.64041666667 | 11748 |
| 011633 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:54pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595093.2 | 513173.6 | 61597 | 1.64041666667 | 11633 |
| 011666 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:55pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595091.7 | 513176.8 | 61599 | 1.64041666667 | 11666 |
| 011629 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:56pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595089.4 | 513179.1 | 61601 | 1.64041666667 | 11629 |
| 011873 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:57pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595086.5 | 513179.9 | 61603 | 1.64041666667 | 11873 |
| 013159 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:58pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595084.1 | 513178.9 | 61605 | 1.64041666667 | 13159 |
| 012397 | 0 | GeoXH 6000 | 08/19/2015 | 12:35:59pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595083.3 | 513176.0 | 61607 | 1.64041666667 | 12397 |
| 011593 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:00pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595084.3 | 513172.2 | 61609 | 1.64041666667 | 11593 |
| 012011 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:01pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595086.0 | 513168.9 | 61611 | 1.64041666667 | 12011 |
| 011648 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:02pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595087.7 | 513165.5 | 61613 | 1.64041666667 | 11648 |
| 011934 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:03pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595089.8 | 513161.9 | 61615 | 1.64041666667 | 11934 |
| 011437 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:04pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595092.3 | 513157.8 | 61617 | 1.64041666667 | 11437 |
| 011533 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:05pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595094.5 | 513154.4 | 61619 | 1.64041666667 | 11533 |
| 011355 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:06pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595096.4 | 513151.3 | 61621 | 1.64041666667 | 11355 |
| 010767 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:07pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595098.4 | 513147.8 | 61623 | 1.64041666667 | 10767 |
| 011861 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:08pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595100.5 | 513144.4 | 61625 | 1.64041666667 | 11861 |
| 012417 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:09pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595102.8 | 513141.3 | 61627 | 1.64041666667 | 12417 |
| 011987 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:10pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595104.9 | 513138.2 | 61629 | 1.64041666667 | 11987 |
| 011850 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:11pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595106.7 | 513134.7 | 61631 | 1.64041666667 | 11850 |
| 011788 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:12pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595108.2 | 513130.8 | 61633 | 1.64041666667 | 11788 |
| 012061 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:13pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595109.7 | 513126.7 | 61635 | 1.64041666667 | 12061 |
| 011839 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:14pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595111.1 | 513122.9 | 61637 | 1.64041666667 | 11839 |
| 011924 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:15pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595112.6 | 513119.2 | 61639 | 1.64041666667 | 11924 |
| 011830 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:16pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595114.7 | 513115.2 | 61641 | 1.64041666667 | 11830 |
| 011529 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:17pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595116.6 | 513111.5 | 61643 | 1.64041666667 | 11529 |
| 011990 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:18pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595118.4 | 513107.6 | 61645 | 1.64041666667 | 11990 |
| 011837 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:19pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595120.0 | 513103.6 | 61647 | 1.64041666667 | 11837 |
| 011796 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:20pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595121.8 | 513099.6 | 61649 | 1.64041666667 | 11796 |
| 011840 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:21pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595124.1 | 513095.3 | 61651 | 1.64041666667 | 11840 |
| 011595 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:22pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595126.0 | 513091.6 | 61653 | 1.64041666667 | 11595 |
| 012057 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:23pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595128.1 | 513087.4 | 61655 | 1.64041666667 | 12057 |
| 012512 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:24pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595129.5 | 513083.9 | 61657 | 1.64041666667 | 12512 |
| 013030 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:25pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595130.8 | 513080.4 | 61659 | 1.64041666667 | 13030 |
| 012774 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:26pm | Sensor | 1797-S0044-G-636-DTE | 6833.1 | 1595131.2 | 513077.7 | 61661 | 1.64041666667 | 12774 |
| 013110 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:27pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595129.0 | 513075.3 | 61663 | 1.64041666667 | 13110 |
| 014237 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:28pm | Sensor | 1797-S0044-G-636-DTE | 6833.0 | 1595125.4 | 513074.2 | 61665 | 1.64041666667 | 14237 |
| 013131 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:29pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595121.9 | 513075.3 | 61667 | 1.64041666667 | 13131 |
| 012823 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:30pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595119.3 | 513078.7 | 61669 | 1.64041666667 | 12823 |
| 014195 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:31pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595117.5 | 513082.2 | 61671 | 1.64041666667 | 14195 |
| 013812 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:32pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595115.5 | 513086.2 | 61673 | 1.64041666667 | 13812 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013747 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:33pm | Sensor | 1797-S0044-G-636-DTE | 6832.6 | 1595113.3 | 513089.7 | 61675 | 1.64041666667 | 13747 |
| 014295 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:34pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595110.7 | 513093.4 | 61677 | 1.64041666667 | 14295 |
| 014131 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:35pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595108.2 | 513096.9 | 61679 | 1.64041666667 | 14131 |
| 014083 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:36pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595106.2 | 513100.6 | 61681 | 1.64041666667 | 14083 |
| 014582 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:37pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595104.8 | 513104.6 | 61683 | 1.64041666667 | 14582 |
| 013640 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:38pm | Sensor | 1797-S0044-G-636-DTE | 6832.6 | 1595103.7 | 513108.2 | 61685 | 1.64041666667 | 13640 |
| 013095 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:39pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595102.2 | 513111.9 | 61687 | 1.64041666667 | 13095 |
| 013620 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:40pm | Sensor | 1797-S0044-G-636-DTE | 6832.6 | 1595100.3 | 513116.1 | 61689 | 1.64041666667 | 13620 |
| 013144 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:41pm | Sensor | 1797-S0044-G-636-DTE | 6832.6 | 1595098.4 | 513120.2 | 61691 | 1.64041666667 | 13144 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:42pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595096.6 | 513124.3 | 61693 | 1.64041666667 | 12133 |
| 012030 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:43pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595094.4 | 513128.8 | 61695 | 1.64041666667 | 12030 |
| 011852 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:44pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595092.2 | 513133.2 | 61697 | 1.64041666667 | 11852 |
| 012929 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:45pm | Sensor | 1797-S0044-G-636-DTE | 6833.5 | 1595091.1 | 513136.9 | 61699 | 1.64041666667 | 12929 |
| 013632 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:46pm | Sensor | 1797-S0044-G-636-DTE | 6833.4 | 1595089.9 | 513140.6 | 61701 | 1.64041666667 | 13632 |
| 012716 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:47pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595087.8 | 513145.5 | 61703 | 1.64041666667 | 12716 |
| 012867 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:48pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595085.8 | 513149.7 | 61705 | 1.64041666667 | 12867 |
| 013718 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:49pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595083.4 | 513153.7 | 61707 | 1.64041666667 | 13718 |
| 013071 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:50pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595081.8 | 513157.0 | 61709 | 1.64041666667 | 13071 |
| 012625 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:51pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595080.4 | 513161.1 | 61711 | 1.64041666667 | 12625 |
| 012254 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:52pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595079.3 | 513164.7 | 61713 | 1.64041666667 | 12254 |
| 011168 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:53pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595077.2 | 513168.3 | 61715 | 1.64041666667 | 11168 |
| 011614 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:54pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595074.4 | 513169.9 | 61717 | 1.64041666667 | 11614 |
| 011573 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:55pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595070.9 | 513169.4 | 61719 | 1.64041666667 | 11573 |
| 011932 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:56pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595067.7 | 513167.9 | 61721 | 1.64041666667 | 11932 |
| 011857 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:57pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595065.8 | 513165.7 | 61723 | 1.64041666667 | 11857 |
| 011942 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:58pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595065.7 | 513161.9 | 61725 | 1.64041666667 | 11942 |
| 011465 | 0 | GeoXH 6000 | 08/19/2015 | 12:36:59pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595067.3 | 513158.0 | 61727 | 1.64041666667 | 11465 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:00pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595069.5 | 513154.0 | 61729 | 1.64041666667 | 11241 |
| 010643 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:01pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595072.0 | 513149.9 | 61731 | 1.64041666667 | 10643 |
| 011027 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:02pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595074.4 | 513146.1 | 61733 | 1.64041666667 | 11027 |
| 011070 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:03pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595077.2 | 513142.1 | 61735 | 1.64041666667 | 11070 |
| 011282 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:04pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595079.5 | 513138.9 | 61737 | 1.64041666667 | 11282 |
| 012076 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:05pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595082.0 | 513135.2 | 61739 | 1.64041666667 | 12076 |
| 011772 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:06pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595084.4 | 513131.5 | 61741 | 1.64041666667 | 11772 |
| 011579 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:07pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595086.6 | 513127.8 | 61743 | 1.64041666667 | 11579 |
| 011553 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:08pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595088.8 | 513124.4 | 61745 | 1.64041666667 | 11553 |
| 011583 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:09pm | Sensor | 1797-S0044-G-636-DTE | 6832.7 | 1595091.1 | 513121.1 | 61747 | 1.64041666667 | 11583 |
| 011556 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:10pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595093.4 | 513117.7 | 61749 | 1.64041666667 | 11556 |
| 011660 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:11pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595095.9 | 513113.7 | 61751 | 1.64041666667 | 11660 |
| 012866 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:12pm | Sensor | 1797-S0044-G-636-DTE | 6832.6 | 1595097.8 | 513109.9 | 61753 | 1.64041666667 | 12866 |
| 012825 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:13pm | Sensor | 1797-S0044-G-636-DTE | 6832.6 | 1595099.7 | 513105.5 | 61755 | 1.64041666667 | 12825 |
| 012618 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:14pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595101.4 | 513101.0 | 61757 | 1.64041666667 | 12618 |
| 012502 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:15pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595103.0 | 513096.9 | 61759 | 1.64041666667 | 12502 |
| 012605 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:16pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595104.5 | 513092.6 | 61761 | 1.64041666667 | 12605 |
| 012363 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:17pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595106.2 | 513088.4 | 61763 | 1.64041666667 | 12363 |
| 013014 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:18pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595108.1 | 513084.2 | 61765 | 1.64041666667 | 13014 |
| 013522 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:19pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595109.9 | 513080.4 | 61767 | 1.64041666667 | 13522 |
| 013261 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:20pm | Sensor | 1797-S0044-G-636-DTE | 6832.4 | 1595111.6 | 513076.6 | 61769 | 1.64041666667 | 13261 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013354 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:21pm | Sensor | 1797-S0044-G-636-DTE | 6832.6 | 1595113.2 | 513072.9 | 61771 | 1.64041666667 | 13354 |
| 013444 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:22pm | Sensor | 1797-S0044-G-636-DTE | 6832.9 | 1595113.8 | 513070.2 | 61773 | 1.64041666667 | 13444 |
| 013412 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:23pm | Sensor | 1797-S0044-G-636-DTE | 6832.8 | 1595113.1 | 513067.5 | 61775 | 1.64041666667 | 13412 |
| 013567 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:24pm | Sensor | 1797-S0044-G-636-DTE | 6832.5 | 1595109.9 | 513064.9 | 61777 | 1.64041666667 | 13567 |
| 013796 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:25pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595105.5 | 513064.8 | 61779 | 1.64041666667 | 13796 |
| 013550 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:26pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595102.4 | 513067.3 | 61781 | 1.64041666667 | 13550 |
| 014402 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:27pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595100.6 | 513071.2 | 61783 | 1.64041666667 | 14402 |
| 014648 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:28pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595098.9 | 513075.2 | 61785 | 1.64041666667 | 14648 |
| 013887 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:29pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595097.1 | 513078.6 | 61787 | 1.64041666667 | 13887 |
| 013496 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:30pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595095.1 | 513082.5 | 61789 | 1.64041666667 | 13496 |
| 012804 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:31pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595093.0 | 513086.3 | 61791 | 1.64041666667 | 12804 |
| 012010 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:32pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595090.9 | 513090.3 | 61793 | 1.64041666667 | 12010 |
| 012418 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:33pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595089.2 | 513094.4 | 61795 | 1.64041666667 | 12418 |
| 013142 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:34pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595087.8 | 513098.0 | 61797 | 1.64041666667 | 13142 |
| 012432 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:35pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595086.1 | 513101.9 | 61799 | 1.64041666667 | 12432 |
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:36pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595084.2 | 513105.8 | 61801 | 1.64041666667 | 12183 |
| 012095 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:37pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595082.3 | 513109.4 | 61803 | 1.64041666667 | 12095 |
| 011768 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:38pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595080.4 | 513113.3 | 61805 | 1.64041666667 | 11768 |
| 011502 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:39pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595078.6 | 513117.4 | 61807 | 1.64041666667 | 11502 |
| 011442 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:40pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595077.2 | 513121.4 | 61809 | 1.64041666667 | 11442 |
| 010906 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:41pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595076.2 | 513125.7 | 61811 | 1.64041666667 | 10906 |
| 011145 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:42pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595075.2 | 513129.7 | 61813 | 1.64041666667 | 11145 |
| 012351 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:43pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595074.0 | 513133.6 | 61815 | 1.64041666667 | 12351 |
| 011717 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:44pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595072.4 | 513137.2 | 61817 | 1.64041666667 | 11717 |
| 012463 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:45pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595070.6 | 513141.1 | 61819 | 1.64041666667 | 12463 |
| 012148 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:46pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595068.9 | 513145.3 | 61821 | 1.64041666667 | 12148 |
| 011866 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:47pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595067.4 | 513148.5 | 61823 | 1.64041666667 | 11866 |
| 011804 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:48pm | Sensor | 1797-S0044-G-636-DTE | 6832.3 | 1595065.4 | 513151.6 | 61825 | 1.64041666667 | 11804 |
| 011830 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:49pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595062.6 | 513155.7 | 61827 | 1.64041666667 | 11830 |
| 012077 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:50pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595059.6 | 513158.9 | 61829 | 1.64041666667 | 12077 |
| 012298 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:51pm | Sensor | 1797-S0044-G-636-DTE | 6832.2 | 1595056.0 | 513160.7 | 61831 | 1.64041666667 | 12298 |
| 013780 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:52pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595051.9 | 513160.6 | 61833 | 1.64041666667 | 13780 |
| 012603 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:53pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595048.5 | 513158.3 | 61835 | 1.64041666667 | 12603 |
| 012624 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:54pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595046.8 | 513155.0 | 61837 | 1.64041666667 | 12624 |
| 012329 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:55pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595047.2 | 513151.1 | 61839 | 1.64041666667 | 12329 |
| 012125 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:56pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595049.3 | 513147.9 | 61841 | 1.64041666667 | 12125 |
| 013517 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:57pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595052.2 | 513144.8 | 61843 | 1.64041666667 | 13517 |
| 014151 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:58pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595054.8 | 513142.0 | 61845 | 1.64041666667 | 14151 |
| 013067 | 0 | GeoXH 6000 | 08/19/2015 | 12:37:59pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595057.1 | 513138.9 | 61847 | 1.64041666667 | 13067 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:00pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595059.5 | 513135.4 | 61849 | 1.64041666667 | 12405 |
| 012858 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:01pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595062.1 | 513132.1 | 61851 | 1.64041666667 | 12858 |
| 012613 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:02pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595064.4 | 513129.4 | 61853 | 1.64041666667 | 12613 |
| 012812 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:03pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595066.9 | 513126.3 | 61855 | 1.64041666667 | 12812 |
| 012854 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:04pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595069.3 | 513123.5 | 61857 | 1.64041666667 | 12854 |
| 012728 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:05pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595072.0 | 513119.9 | 61859 | 1.64041666667 | 12728 |
| 011877 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:06pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595074.0 | 513116.8 | 61861 | 1.64041666667 | 11877 |
| 011893 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:07pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595075.9 | 513113.7 | 61863 | 1.64041666667 | 11893 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:08pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595077.9 | 513109.9 | 61865 | 1.64041666667 | 12247 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011441 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:09pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595079.6 | 513105.9 | 61867 | 1.64041666667 | 11441 |
| 011536 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:10pm | Sensor | 1797-S0044-G-636-DTE | 6832.0 | 1595081.3 | 513101.8 | 61869 | 1.64041666667 | 11536 |
| 011664 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:11pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595083.1 | 513098.2 | 61871 | 1.64041666667 | 11664 |
| 012973 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:12pm | Sensor | 1797-S0044-G-636-DTE | 6832.1 | 1595085.2 | 513094.6 | 61873 | 1.64041666667 | 12973 |
| 013312 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:13pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595087.3 | 513091.0 | 61875 | 1.64041666667 | 13312 |
| 013166 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:14pm | Sensor | 1797-S0044-G-636-DTE | 6831.9 | 1595089.0 | 513087.4 | 61877 | 1.64041666667 | 13166 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:15pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595090.3 | 513083.4 | 61879 | 1.64041666667 | 12401 |
| 012390 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:16pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595091.1 | 513079.5 | 61881 | 1.64041666667 | 12390 |
| 013659 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:17pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595092.2 | 513075.6 | 61883 | 1.64041666667 | 13659 |
| 013436 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:18pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595093.3 | 513072.5 | 61885 | 1.64041666667 | 13436 |
| 013805 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:19pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595094.9 | 513069.0 | 61887 | 1.64041666667 | 13805 |
| 013630 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:20pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595095.7 | 513066.2 | 61889 | 1.64041666667 | 13630 |
| 013884 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:21pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595095.8 | 513062.6 | 61891 | 1.64041666667 | 13884 |
| 013360 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:22pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595094.6 | 513059.8 | 61893 | 1.64041666667 | 13360 |
| 014010 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:23pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595091.7 | 513057.5 | 61895 | 1.64041666667 | 14010 |
| 013603 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:24pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595088.3 | 513056.3 | 61897 | 1.64041666667 | 13603 |
| 013381 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:25pm | Sensor | 1797-S0044-G-636-DTE | 6831.0 | 1595085.1 | 513057.6 | 61899 | 1.64041666667 | 13381 |
| 013452 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:26pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595082.8 | 513060.6 | 61901 | 1.64041666667 | 13452 |
| 013027 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:27pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595080.3 | 513064.2 | 61903 | 1.64041666667 | 13027 |
| 013530 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:28pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595078.3 | 513067.0 | 61905 | 1.64041666667 | 13530 |
| 013438 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:29pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595075.8 | 513071.0 | 61907 | 1.64041666667 | 13438 |
| 014316 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:30pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595073.6 | 513074.5 | 61909 | 1.64041666667 | 14316 |
| 013738 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:31pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595071.1 | 513077.7 | 61911 | 1.64041666667 | 13738 |
| 012872 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:32pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595068.2 | 513081.1 | 61913 | 1.64041666667 | 12872 |
| 013368 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:33pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595065.5 | 513084.8 | 61915 | 1.64041666667 | 13368 |
| 013489 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:34pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595063.5 | 513087.9 | 61917 | 1.64041666667 | 13489 |
| 013183 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:35pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595060.8 | 513091.8 | 61919 | 1.64041666667 | 13183 |
| 013115 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:36pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595058.5 | 513094.9 | 61921 | 1.64041666667 | 13115 |
| 012739 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:37pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595056.1 | 513098.8 | 61923 | 1.64041666667 | 12739 |
| 012311 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:38pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595054.0 | 513102.8 | 61925 | 1.64041666667 | 12311 |
| 012100 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:39pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595052.1 | 513106.6 | 61927 | 1.64041666667 | 12100 |
| 011373 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:40pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595050.6 | 513110.4 | 61929 | 1.64041666667 | 11373 |
| 011782 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:41pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595049.1 | 513115.0 | 61931 | 1.64041666667 | 11782 |
| 012260 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:42pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595047.7 | 513119.0 | 61933 | 1.64041666667 | 12260 |
| 011771 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:43pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595046.4 | 513123.0 | 61935 | 1.64041666667 | 11771 |
| 011406 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:44pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595045.3 | 513126.9 | 61937 | 1.64041666667 | 11406 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:45pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595044.1 | 513130.8 | 61939 | 1.64041666667 | 12768 |
| 011712 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:46pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595041.9 | 513135.0 | 61941 | 1.64041666667 | 11712 |
| 012393 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:47pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595039.8 | 513138.1 | 61943 | 1.64041666667 | 12393 |
| 012101 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:48pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595037.7 | 513141.5 | 61945 | 1.64041666667 | 12101 |
| 011554 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:49pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595035.8 | 513145.1 | 61947 | 1.64041666667 | 11554 |
| 011074 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:50pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595034.0 | 513148.0 | 61949 | 1.64041666667 | 11074 |
| 011794 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:51pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595030.9 | 513151.2 | 61951 | 1.64041666667 | 11794 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:52pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595027.3 | 513151.9 | 61953 | 1.64041666667 | 12401 |
| 012346 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:53pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595024.4 | 513150.7 | 61955 | 1.64041666667 | 12346 |
| 011989 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:54pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595022.5 | 513147.6 | 61957 | 1.64041666667 | 11989 |
| 011632 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:55pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595022.6 | 513143.9 | 61959 | 1.64041666667 | 11632 |
| 011418 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:56pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595024.0 | 513140.0 | 61961 | 1.64041666667 | 11418 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011530 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:57pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595025.4 | 513136.0 | 61963 | 1.64041666667 | 11530 |
| 013153 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:58pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595026.9 | 513131.8 | 61965 | 1.64041666667 | 13153 |
| 012663 | 0 | GeoXH 6000 | 08/19/2015 | 12:38:59pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595028.8 | 513127.6 | 61967 | 1.64041666667 | 12663 |
| 013100 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:00pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595031.0 | 513123.3 | 61969 | 1.64041666667 | 13100 |
| 012386 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:01pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595033.4 | 513119.3 | 61971 | 1.64041666667 | 12386 |
| 012270 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:02pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595035.9 | 513115.4 | 61973 | 1.64041666667 | 12270 |
| 012384 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:03pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595038.2 | 513111.8 | 61975 | 1.64041666667 | 12384 |
| 011458 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:04pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595040.1 | 513108.2 | 61977 | 1.64041666667 | 11458 |
| 011943 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:05pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595042.0 | 513104.9 | 61979 | 1.64041666667 | 11943 |
| 011750 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:06pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595044.1 | 513101.8 | 61981 | 1.64041666667 | 11750 |
| 011312 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:07pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595046.4 | 513098.3 | 61983 | 1.64041666667 | 11312 |
| 011823 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:08pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595048.4 | 513095.1 | 61985 | 1.64041666667 | 11823 |
| 012290 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:09pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595050.5 | 513090.8 | 61987 | 1.64041666667 | 12290 |
| 012673 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:10pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595052.2 | 513087.7 | 61989 | 1.64041666667 | 12673 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:11pm | Sensor | 1797-S0044-G-636-DTE | 6831.0 | 1595054.4 | 513084.1 | 61991 | 1.64041666667 | 12678 |
| 012269 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:12pm | Sensor | 1797-S0044-G-636-DTE | 6831.0 | 1595056.1 | 513081.0 | 61993 | 1.64041666667 | 12269 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:13pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595058.0 | 513076.1 | 61995 | 1.64041666667 | 12106 |
| 011955 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:14pm | Sensor | 1797-S0044-G-636-DTE | 6830.8 | 1595059.5 | 513072.5 | 61997 | 1.64041666667 | 11955 |
| 012072 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:15pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595061.6 | 513068.9 | 61999 | 1.64041666667 | 12072 |
| 011950 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:16pm | Sensor | 1797-S0044-G-636-DTE | 6830.7 | 1595063.2 | 513065.8 | 62001 | 1.64041666667 | 11950 |
| 012744 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:17pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595064.5 | 513061.9 | 62003 | 1.64041666667 | 12744 |
| 013356 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:18pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595064.9 | 513058.8 | 62005 | 1.64041666667 | 13356 |
| 013640 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:19pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595066.1 | 513054.9 | 62007 | 1.64041666667 | 13640 |
| 013620 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:20pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595067.1 | 513052.3 | 62009 | 1.64041666667 | 13620 |
| 013368 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:21pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595066.4 | 513048.8 | 62011 | 1.64041666667 | 13368 |
| 013572 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:22pm | Sensor | 1797-S0044-G-636-DTE | 6830.8 | 1595063.7 | 513047.6 | 62013 | 1.64041666667 | 13572 |
| 013567 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:23pm | Sensor | 1797-S0044-G-636-DTE | 6830.8 | 1595060.6 | 513048.6 | 62015 | 1.64041666667 | 13567 |
| 012911 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:24pm | Sensor | 1797-S0044-G-636-DTE | 6830.7 | 1595058.4 | 513050.9 | 62017 | 1.64041666667 | 12911 |
| 013682 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:25pm | Sensor | 1797-S0044-G-636-DTE | 6830.7 | 1595055.8 | 513055.0 | 62019 | 1.64041666667 | 13682 |
| 013336 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:26pm | Sensor | 1797-S0044-G-636-DTE | 6830.6 | 1595054.5 | 513058.4 | 62021 | 1.64041666667 | 13336 |
| 012864 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:27pm | Sensor | 1797-S0044-G-636-DTE | 6830.8 | 1595053.9 | 513063.1 | 62023 | 1.64041666667 | 12864 |
| 013318 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:28pm | Sensor | 1797-S0044-G-636-DTE | 6830.7 | 1595053.4 | 513065.6 | 62025 | 1.64041666667 | 13318 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:29pm | Sensor | 1797-S0044-G-636-DTE | 6830.7 | 1595051.3 | 513069.9 | 62027 | 1.64041666667 | 13424 |
| 013513 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:30pm | Sensor | 1797-S0044-G-636-DTE | 6831.0 | 1595049.5 | 513073.1 | 62029 | 1.64041666667 | 13513 |
| 013728 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:31pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595048.2 | 513077.0 | 62031 | 1.64041666667 | 13728 |
| 013542 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:32pm | Sensor | 1797-S0044-G-636-DTE | 6830.8 | 1595047.3 | 513080.2 | 62033 | 1.64041666667 | 13542 |
| 012785 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:33pm | Sensor | 1797-S0044-G-636-DTE | 6830.8 | 1595045.0 | 513084.2 | 62035 | 1.64041666667 | 12785 |
| 012186 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:34pm | Sensor | 1797-S0044-G-636-DTE | 6830.6 | 1595042.7 | 513087.4 | 62037 | 1.64041666667 | 12186 |
| 012375 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:35pm | Sensor | 1797-S0044-G-636-DTE | 6830.7 | 1595039.4 | 513091.4 | 62039 | 1.64041666667 | 12375 |
| 012136 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:36pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595037.1 | 513094.3 | 62041 | 1.64041666667 | 12136 |
| 012339 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:37pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595034.7 | 513098.7 | 62043 | 1.64041666667 | 12339 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:38pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595033.1 | 513101.9 | 62045 | 1.64041666667 | 12475 |
| 012125 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:39pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595030.5 | 513105.7 | 62047 | 1.64041666667 | 12125 |
| 011748 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:40pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595028.1 | 513108.9 | 62049 | 1.64041666667 | 11748 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:41pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595024.9 | 513113.4 | 62051 | 1.64041666667 | 12420 |
| 012851 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:42pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595022.9 | 513116.7 | 62053 | 1.64041666667 | 12851 |
| 011931 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:43pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595020.4 | 513121.1 | 62055 | 1.64041666667 | 11931 |
| 010971 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:44pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595018.6 | 513124.4 | 62057 | 1.64041666667 | 10971 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010784 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:45pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595016.5 | 513128.2 | 62059 | 1.64041666667 | 10784 |
| 011248 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:46pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595014.4 | 513131.1 | 62061 | 1.64041666667 | 11248 |
| 011974 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:47pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595011.5 | 513133.9 | 62063 | 1.64041666667 | 11974 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:48pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595009.2 | 513135.4 | 62065 | 1.64041666667 | 12045 |
| 012048 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:49pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595006.8 | 513135.0 | 62067 | 1.64041666667 | 12048 |
| 011929 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:50pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595006.1 | 513132.8 | 62069 | 1.64041666667 | 11929 |
| 012200 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:51pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595007.4 | 513128.6 | 62071 | 1.64041666667 | 12200 |
| 012157 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:52pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595008.8 | 513125.3 | 62073 | 1.64041666667 | 12157 |
| 011931 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:53pm | Sensor | 1797-S0044-G-636-DTE | 6831.6 | 1595010.9 | 513121.4 | 62075 | 1.64041666667 | 11931 |
| 011264 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:54pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595012.6 | 513118.5 | 62077 | 1.64041666667 | 11264 |
| 011091 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:55pm | Sensor | 1797-S0044-G-636-DTE | 6831.7 | 1595014.6 | 513114.6 | 62079 | 1.64041666667 | 11091 |
| 011533 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:56pm | Sensor | 1797-S0044-G-636-DTE | 6831.8 | 1595016.2 | 513111.3 | 62081 | 1.64041666667 | 11533 |
| 011767 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:57pm | Sensor | 1797-S0044-G-636-DTE | 6831.5 | 1595018.4 | 513107.9 | 62083 | 1.64041666667 | 11767 |
| 011299 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:58pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595020.6 | 513104.6 | 62085 | 1.64041666667 | 11299 |
| 010916 | 0 | GeoXH 6000 | 08/19/2015 | 12:39:59pm | Sensor | 1797-S0044-G-636-DTE | 6831.4 | 1595022.7 | 513100.7 | 62087 | 1.64041666667 | 10916 |
| 011187 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:00pm | Sensor | 1797-S0044-G-636-DTE | 6831.2 | 1595024.2 | 513097.5 | 62089 | 1.64041666667 | 11187 |
| 011852 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:01pm | Sensor | 1797-S0044-G-636-DTE | 6831.3 | 1595026.0 | 513093.5 | 62091 | 1.64041666667 | 11852 |
| 011467 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:02pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595027.4 | 513090.5 | 62093 | 1.64041666667 | 11467 |
| 011790 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:03pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595029.1 | 513087.0 | 62095 | 1.64041666667 | 11790 |
| 013082 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:04pm | Sensor | 1797-S0044-G-636-DTE | 6830.7 | 1595030.8 | 513083.2 | 62097 | 1.64041666667 | 13082 |
| 012691 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:05pm | Sensor | 1797-S0044-G-636-DTE | 6830.8 | 1595032.6 | 513079.3 | 62099 | 1.64041666667 | 12691 |
| 013221 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:06pm | Sensor | 1797-S0044-G-636-DTE | 6831.0 | 1595034.2 | 513076.3 | 62101 | 1.64041666667 | 13221 |
| 012469 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:07pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595036.6 | 513072.9 | 62103 | 1.64041666667 | 12469 |
| 012789 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:08pm | Sensor | 1797-S0044-G-636-DTE | 6830.7 | 1595038.6 | 513069.5 | 62105 | 1.64041666667 | 12789 |
| 012728 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:09pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595040.7 | 513066.2 | 62107 | 1.64041666667 | 12728 |
| 013400 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:10pm | Sensor | 1797-S0044-G-636-DTE | 6831.0 | 1595042.4 | 513063.4 | 62109 | 1.64041666667 | 13400 |
| 013912 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:11pm | Sensor | 1797-S0044-G-636-DTE | 6831.0 | 1595043.0 | 513060.1 | 62111 | 1.64041666667 | 13912 |
| 013323 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:12pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595044.7 | 513056.9 | 62113 | 1.64041666667 | 13323 |
| 013704 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:13pm | Sensor | 1797-S0044-G-636-DTE | 6831.0 | 1595046.2 | 513053.0 | 62115 | 1.64041666667 | 13704 |
| 013873 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:14pm | Sensor | 1797-S0044-G-636-DTE | 6831.1 | 1595047.0 | 513050.2 | 62117 | 1.64041666667 | 13873 |
| 013278 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:15pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595047.9 | 513046.9 | 62119 | 1.64041666667 | 13278 |
| 013732 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:16pm | Sensor | 1797-S0044-G-636-DTE | 6830.8 | 1595048.0 | 513044.3 | 62121 | 1.64041666667 | 13732 |
| 014046 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:17pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595047.8 | 513042.4 | 62123 | 1.64041666667 | 14046 |
| 014651 | 0 | GeoXH 6000 | 08/19/2015 | 12:40:18pm | Sensor | 1797-S0044-G-636-DTE | 6830.9 | 1595048.3 | 513042.2 | 62126 | 1.64041666667 | 14651 |
| 014448 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:28am | Sensor | 1797-S0043-G-636-DTE | 6831.3 | 1595099.1 | 512571.6 | 59920 | 1.64041666667 | 14448 |
| 014862 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:29am | Sensor | 1797-S0043-G-636-DTE | 6831.3 | 1595099.1 | 512572.4 | 59922 | 1.64041666667 | 14862 |
| 014517 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:30am | Sensor | 1797-S0043-G-636-DTE | 6831.3 | 1595099.1 | 512572.4 | 59924 | 1.64041666667 | 14517 |
| 014256 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:31am | Sensor | 1797-S0043-G-636-DTE | 6831.3 | 1595099.1 | 512572.4 | 59926 | 1.64041666667 | 14256 |
| 014724 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:32am | Sensor | 1797-S0043-G-636-DTE | 6831.4 | 1595099.1 | 512572.5 | 59928 | 1.64041666667 | 14724 |
| 015107 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:33am | Sensor | 1797-S0043-G-636-DTE | 6831.3 | 1595099.1 | 512572.4 | 59930 | 1.64041666667 | 15107 |
| 014430 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:34am | Sensor | 1797-S0043-G-636-DTE | 6831.3 | 1595099.1 | 512572.4 | 59932 | 1.64041666667 | 14430 |
| 011478 | 0 | GeoXH 6000 | 08/19/2015 | 11:17:52am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.5 | 58691 | 1.64041666667 | 11478 |
| 011137 | 0 | GeoXH 6000 | 08/19/2015 | 11:17:53am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.0 | 510985.5 | 58694 | 1.64041666667 | 11137 |
| 011477 | 0 | GeoXH 6000 | 08/19/2015 | 11:17:54am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.0 | 510985.6 | 58696 | 1.64041666667 | 11477 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 11:17:55am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58698 | 1.64041666667 | 12021 |
| 011314 | 0 | GeoXH 6000 | 08/19/2015 | 11:17:56am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58700 | 1.64041666667 | 11314 |
| 010804 | 0 | GeoXH 6000 | 08/19/2015 | 11:17:57am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.0 | 510985.6 | 58702 | 1.64041666667 | 10804 |
| 011455 | 0 | GeoXH 6000 | 08/19/2015 | 11:17:58am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.0 | 510985.6 | 58704 | 1.64041666667 | 11455 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011063 | 0 | GeoXH 6000 | 08/19/2015 | 11:17:59am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.0 | 510985.6 | 58706 | 1.64041666667 | 11063 |
| 010820 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:00am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.1 | 510985.6 | 58708 | 1.64041666667 | 10820 |
| 010166 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:01am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.1 | 510985.6 | 58710 | 1.64041666667 | 10166 |
| 010556 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:02am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.0 | 510985.6 | 58712 | 1.64041666667 | 10556 |
| 011405 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:03am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.1 | 510985.6 | 58714 | 1.64041666667 | 11405 |
| 011125 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:04am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58716 | 1.64041666667 | 11125 |
| 011530 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:05am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58718 | 1.64041666667 | 11530 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:06am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.1 | 510985.6 | 58720 | 1.64041666667 | 11241 |
| 010920 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:07am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.1 | 510985.6 | 58722 | 1.64041666667 | 10920 |
| 011640 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:08am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.1 | 510985.6 | 58724 | 1.64041666667 | 11640 |
| 010995 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:09am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.1 | 510985.6 | 58726 | 1.64041666667 | 10995 |
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:10am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.1 | 510985.6 | 58728 | 1.64041666667 | 12019 |
| 011771 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:11am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595095.0 | 510985.6 | 58730 | 1.64041666667 | 11771 |
| 011653 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:12am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.0 | 510985.6 | 58732 | 1.64041666667 | 11653 |
| 011970 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:13am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58734 | 1.64041666667 | 11970 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:14am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58736 | 1.64041666667 | 11953 |
| 010916 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:15am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58738 | 1.64041666667 | 10916 |
| 011315 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:16am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58740 | 1.64041666667 | 11315 |
| 012094 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:17am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58742 | 1.64041666667 | 12094 |
| 012000 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:18am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.2 | 510985.6 | 58744 | 1.64041666667 | 12000 |
| 011933 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:19am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.2 | 510985.7 | 58746 | 1.64041666667 | 11933 |
| 010972 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:20am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.2 | 510985.6 | 58748 | 1.64041666667 | 10972 |
| 010582 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:21am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58750 | 1.64041666667 | 10582 |
| 011389 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:22am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.6 | 58752 | 1.64041666667 | 11389 |
| 011199 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:23am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.6 | 58754 | 1.64041666667 | 11199 |
| 011932 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:24am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.7 | 58756 | 1.64041666667 | 11932 |
| 012044 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:25am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.7 | 58758 | 1.64041666667 | 12044 |
| 011305 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:26am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.2 | 510985.7 | 58760 | 1.64041666667 | 11305 |
| 012411 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:27am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.7 | 58762 | 1.64041666667 | 12411 |
| 011496 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:28am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595095.1 | 510985.7 | 58764 | 1.64041666667 | 11496 |
| 010824 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:29am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.6 | 58766 | 1.64041666667 | 10824 |
| 010333 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:30am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.6 | 58768 | 1.64041666667 | 10333 |
| 010732 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:31am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.7 | 58770 | 1.64041666667 | 10732 |
| 010919 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:32am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.7 | 58772 | 1.64041666667 | 10919 |
| 010545 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:33am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.2 | 510985.7 | 58774 | 1.64041666667 | 10545 |
| 011189 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:34am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.7 | 58776 | 1.64041666667 | 11189 |
| 011423 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:35am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58778 | 1.64041666667 | 11423 |
| 011083 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:36am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.1 | 510985.7 | 58780 | 1.64041666667 | 11083 |
| 011184 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:37am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.0 | 510985.7 | 58782 | 1.64041666667 | 11184 |
| 010986 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:38am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.0 | 510985.7 | 58784 | 1.64041666667 | 10986 |
| 011092 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:39am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58786 | 1.64041666667 | 11092 |
| 012104 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:40am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58788 | 1.64041666667 | 12104 |
| 011503 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:41am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.9 | 510985.7 | 58790 | 1.64041666667 | 11503 |
| 010963 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:42am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.9 | 510985.7 | 58792 | 1.64041666667 | 10963 |
| 010937 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:43am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.9 | 510985.7 | 58794 | 1.64041666667 | 10937 |
| 010689 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:44am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58796 | 1.64041666667 | 10689 |
| 011255 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:45am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58798 | 1.64041666667 | 11255 |
| 011483 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:46am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58800 | 1.64041666667 | 11483 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010697 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:47am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58802 | 1.64041666667 | 10697 |
| 010742 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:48am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58804 | 1.64041666667 | 10742 |
| 009935 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:49am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.9 | 510985.7 | 58806 | 1.64041666667 | 9935 |
| 010658 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:50am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.9 | 510985.7 | 58808 | 1.64041666667 | 10658 |
| 012108 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:51am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58810 | 1.64041666667 | 12108 |
| 011730 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:52am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.0 | 510985.7 | 58812 | 1.64041666667 | 11730 |
| 011166 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:53am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.9 | 510985.7 | 58814 | 1.64041666667 | 11166 |
| 011171 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:54am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.0 | 510985.7 | 58816 | 1.64041666667 | 11171 |
| 011413 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:55am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.0 | 510985.7 | 58818 | 1.64041666667 | 11413 |
| 011310 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:56am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.0 | 510985.7 | 58820 | 1.64041666667 | 11310 |
| 012107 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:57am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.9 | 510985.7 | 58822 | 1.64041666667 | 12107 |
| 011100 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:58am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595094.9 | 510985.6 | 58824 | 1.64041666667 | 11100 |
| 010848 | 0 | GeoXH 6000 | 08/19/2015 | 11:18:59am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.9 | 510985.6 | 58826 | 1.64041666667 | 10848 |
| 011075 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:00am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.8 | 510985.7 | 58828 | 1.64041666667 | 11075 |
| 011352 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:01am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595094.8 | 510985.6 | 58830 | 1.64041666667 | 11352 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:02am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595094.8 | 510985.6 | 58832 | 1.64041666667 | 12078 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:03am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595094.8 | 510985.6 | 58834 | 1.64041666667 | 12021 |
| 011217 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:04am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.8 | 510985.6 | 58836 | 1.64041666667 | 11217 |
| 011237 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:05am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.8 | 510985.6 | 58838 | 1.64041666667 | 11237 |
| 011001 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:06am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.8 | 510985.6 | 58840 | 1.64041666667 | 11001 |
| 010425 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:07am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595094.8 | 510985.7 | 58842 | 1.64041666667 | 10425 |
| 010859 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:08am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.3 | 510986.1 | 58844 | 1.64041666667 | 10859 |
| 011216 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:09am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595096.1 | 510986.8 | 58846 | 1.64041666667 | 11216 |
| 011536 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:10am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.7 | 510986.7 | 58848 | 1.64041666667 | 11536 |
| 010884 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:11am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.5 | 510986.7 | 58850 | 1.64041666667 | 10884 |
| 011042 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:12am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.5 | 510986.8 | 58852 | 1.64041666667 | 11042 |
| 011041 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:13am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.5 | 510986.8 | 58854 | 1.64041666667 | 11041 |
| 011175 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:14am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.5 | 510986.8 | 58856 | 1.64041666667 | 11175 |
| 011378 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:15am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595095.5 | 510986.7 | 58858 | 1.64041666667 | 11378 |
| 011043 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:16am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595095.6 | 510986.7 | 58860 | 1.64041666667 | 11043 |
| 010839 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:17am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595096.7 | 510986.8 | 58862 | 1.64041666667 | 10839 |
| 010454 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:18am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.6 | 510986.1 | 58864 | 1.64041666667 | 10454 |
| 010905 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:19am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.7 | 510983.5 | 58866 | 1.64041666667 | 10905 |
| 010619 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:20am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510981.7 | 58868 | 1.64041666667 | 10619 |
| 010271 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:21am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.9 | 510980.9 | 58870 | 1.64041666667 | 10271 |
| 009940 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:22am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595098.0 | 510980.9 | 58872 | 1.64041666667 | 9940 |
| 009633 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:23am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595098.0 | 510980.9 | 58874 | 1.64041666667 | 9633 |
| 009221 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:24am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510980.9 | 58876 | 1.64041666667 | 9221 |
| 008869 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:25am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510980.9 | 58878 | 1.64041666667 | 8869 |
| 008446 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:26am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510980.9 | 58880 | 1.64041666667 | 8446 |
| 008861 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:27am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595098.0 | 510981.0 | 58882 | 1.64041666667 | 8861 |
| 009371 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:28am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595098.0 | 510981.0 | 58884 | 1.64041666667 | 9371 |
| 009606 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:29am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510981.0 | 58886 | 1.64041666667 | 9606 |
| 009288 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:30am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510980.9 | 58888 | 1.64041666667 | 9288 |
| 009882 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:31am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510980.9 | 58890 | 1.64041666667 | 9882 |
| 009563 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:32am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510980.8 | 58892 | 1.64041666667 | 9563 |
| 009609 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:33am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595098.0 | 510980.8 | 58894 | 1.64041666667 | 9609 |
| 009103 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:34am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.9 | 510980.8 | 58896 | 1.64041666667 | 9103 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009230 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:35am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.9 | 510980.8 | 58898 | 1.64041666667 | 9230 |
| 009107 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:36am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595098.0 | 510980.8 | 58900 | 1.64041666667 | 9107 |
| 008535 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:37am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.9 | 510980.8 | 58902 | 1.64041666667 | 8535 |
| 009046 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:38am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.8 | 510980.9 | 58904 | 1.64041666667 | 9046 |
| 009161 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:39am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595098.0 | 510980.9 | 58906 | 1.64041666667 | 9161 |
| 009480 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:40am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595098.0 | 510980.9 | 58908 | 1.64041666667 | 9480 |
| 008940 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:41am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510981.0 | 58910 | 1.64041666667 | 8940 |
| 009581 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:42am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.9 | 510981.0 | 58912 | 1.64041666667 | 9581 |
| 008757 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:43am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.9 | 510980.9 | 58914 | 1.64041666667 | 8757 |
| 008413 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:44am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.9 | 510980.7 | 58916 | 1.64041666667 | 8413 |
| 008902 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:45am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.8 | 510980.6 | 58918 | 1.64041666667 | 8902 |
| 008787 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:46am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.8 | 510980.6 | 58920 | 1.64041666667 | 8787 |
| 008753 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:47am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.9 | 510980.7 | 58922 | 1.64041666667 | 8753 |
| 009071 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:48am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.9 | 510980.7 | 58924 | 1.64041666667 | 9071 |
| 008807 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:49am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.9 | 510980.7 | 58926 | 1.64041666667 | 8807 |
| 008255 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:50am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.9 | 510980.7 | 58928 | 1.64041666667 | 8255 |
| 008676 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:51am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595098.0 | 510981.0 | 58930 | 1.64041666667 | 8676 |
| 009575 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:52am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595098.0 | 510981.0 | 58932 | 1.64041666667 | 9575 |
| 009586 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:53am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595098.1 | 510980.9 | 58934 | 1.64041666667 | 9586 |
| 009457 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:54am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595098.0 | 510980.8 | 58936 | 1.64041666667 | 9457 |
| 009737 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:55am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.6 | 510980.6 | 58938 | 1.64041666667 | 9737 |
| 009872 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:56am | Sensor | 1797-S0042-G-636-DTE | 6825.2 | 1595097.2 | 510980.3 | 58940 | 1.64041666667 | 9872 |
| 009873 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:57am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.6 | 510980.6 | 58942 | 1.64041666667 | 9873 |
| 009611 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:58am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.6 | 510980.4 | 58944 | 1.64041666667 | 9611 |
| 010116 | 0 | GeoXH 6000 | 08/19/2015 | 11:19:59am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.6 | 510980.4 | 58946 | 1.64041666667 | 10116 |
| 010047 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:00am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.5 | 510980.7 | 58948 | 1.64041666667 | 10047 |
| 010294 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:01am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.4 | 510981.1 | 58950 | 1.64041666667 | 10294 |
| 009675 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:02am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.3 | 510981.2 | 58952 | 1.64041666667 | 9675 |
| 009957 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:03am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.0 | 510981.0 | 58954 | 1.64041666667 | 9957 |
| 010071 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:04am | Sensor | 1797-S0042-G-636-DTE | 6825.3 | 1595096.8 | 510980.6 | 58956 | 1.64041666667 | 10071 |
| 010540 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:05am | Sensor | 1797-S0042-G-636-DTE | 6825.3 | 1595097.0 | 510980.6 | 58958 | 1.64041666667 | 10540 |
| 010248 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:06am | Sensor | 1797-S0042-G-636-DTE | 6825.3 | 1595097.2 | 510980.6 | 58960 | 1.64041666667 | 10248 |
| 010902 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:07am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.2 | 510980.6 | 58962 | 1.64041666667 | 10902 |
| 011157 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:08am | Sensor | 1797-S0042-G-636-DTE | 6825.3 | 1595097.1 | 510980.7 | 58964 | 1.64041666667 | 11157 |
| 010821 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:09am | Sensor | 1797-S0042-G-636-DTE | 6825.3 | 1595097.0 | 510980.6 | 58966 | 1.64041666667 | 10821 |
| 010069 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:10am | Sensor | 1797-S0042-G-636-DTE | 6825.3 | 1595096.9 | 510980.5 | 58968 | 1.64041666667 | 10069 |
| 009864 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:11am | Sensor | 1797-S0042-G-636-DTE | 6825.2 | 1595096.8 | 510980.5 | 58970 | 1.64041666667 | 9864 |
| 009426 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:12am | Sensor | 1797-S0042-G-636-DTE | 6825.2 | 1595097.0 | 510980.4 | 58972 | 1.64041666667 | 9426 |
| 009449 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:13am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595097.0 | 510980.2 | 58974 | 1.64041666667 | 9449 |
| 009890 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:14am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.1 | 58976 | 1.64041666667 | 9890 |
| 009830 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:15am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.7 | 510980.0 | 58978 | 1.64041666667 | 9830 |
| 010315 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:16am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.7 | 510980.0 | 58980 | 1.64041666667 | 10315 |
| 011217 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:17am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.7 | 510980.0 | 58982 | 1.64041666667 | 11217 |
| 011207 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:18am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510980.0 | 58984 | 1.64041666667 | 11207 |
| 011284 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:19am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.9 | 510980.0 | 58986 | 1.64041666667 | 11284 |
| 011192 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:20am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.9 | 510980.1 | 58988 | 1.64041666667 | 11192 |
| 010330 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:21am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510980.0 | 58990 | 1.64041666667 | 10330 |
| 010731 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:22am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.0 | 58992 | 1.64041666667 | 10731 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009838 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:23am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.0 | 58994 | 1.64041666667 | 9838 |
| 010311 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:24am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510980.0 | 58996 | 1.64041666667 | 10311 |
| 010390 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:25am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.0 | 58998 | 1.64041666667 | 10390 |
| 009654 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:26am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510979.9 | 59000 | 1.64041666667 | 9654 |
| 009593 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:27am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510979.9 | 59002 | 1.64041666667 | 9593 |
| 009746 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:28am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510979.9 | 59004 | 1.64041666667 | 9746 |
| 009937 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:29am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510979.9 | 59006 | 1.64041666667 | 9937 |
| 010089 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:30am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510979.9 | 59008 | 1.64041666667 | 10089 |
| 010760 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:31am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510980.0 | 59010 | 1.64041666667 | 10760 |
| 010755 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:32am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.8 | 510980.0 | 59012 | 1.64041666667 | 10755 |
| 010384 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:33am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.0 | 59014 | 1.64041666667 | 10384 |
| 010866 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:34am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.0 | 59016 | 1.64041666667 | 10866 |
| 010252 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:35am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.0 | 59018 | 1.64041666667 | 10252 |
| 010192 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:36am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.0 | 59020 | 1.64041666667 | 10192 |
| 010150 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:37am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.7 | 510980.0 | 59022 | 1.64041666667 | 10150 |
| 009977 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:38am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.7 | 510980.0 | 59024 | 1.64041666667 | 9977 |
| 009609 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:39am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.0 | 59026 | 1.64041666667 | 9609 |
| 009770 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:40am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.7 | 510980.0 | 59028 | 1.64041666667 | 9770 |
| 010318 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:41am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.7 | 510980.0 | 59030 | 1.64041666667 | 10318 |
| 010206 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:42am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.7 | 510980.0 | 59032 | 1.64041666667 | 10206 |
| 009843 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:43am | Sensor | 1797-S0042-G-636-DTE | 6825.0 | 1595096.7 | 510980.0 | 59034 | 1.64041666667 | 9843 |
| 009647 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:44am | Sensor | 1797-S0042-G-636-DTE | 6825.1 | 1595096.8 | 510980.3 | 59036 | 1.64041666667 | 9647 |
| 009934 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:45am | Sensor | 1797-S0042-G-636-DTE | 6825.3 | 1595097.3 | 510980.9 | 59038 | 1.64041666667 | 9934 |
| 010335 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:46am | Sensor | 1797-S0042-G-636-DTE | 6825.3 | 1595097.5 | 510981.1 | 59040 | 1.64041666667 | 10335 |
| 010651 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:47am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.6 | 510981.4 | 59042 | 1.64041666667 | 10651 |
| 010491 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:48am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.3 | 510981.4 | 59044 | 1.64041666667 | 10491 |
| 010499 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:49am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.2 | 510981.3 | 59046 | 1.64041666667 | 10499 |
| 010023 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:50am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.4 | 510981.1 | 59048 | 1.64041666667 | 10023 |
| 010123 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:51am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.4 | 510981.0 | 59050 | 1.64041666667 | 10123 |
| 009586 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:52am | Sensor | 1797-S0042-G-636-DTE | 6825.4 | 1595097.4 | 510981.0 | 59052 | 1.64041666667 | 9586 |
| 009832 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:53am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595097.3 | 510981.1 | 59054 | 1.64041666667 | 9832 |
| 009273 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:54am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.1 | 510981.2 | 59056 | 1.64041666667 | 9273 |
| 010473 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:55am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.1 | 510981.2 | 59058 | 1.64041666667 | 10473 |
| 010811 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:56am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.1 | 510981.2 | 59060 | 1.64041666667 | 10811 |
| 010664 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:57am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.1 | 510981.1 | 59062 | 1.64041666667 | 10664 |
| 010791 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:58am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.0 | 510981.1 | 59064 | 1.64041666667 | 10791 |
| 011035 | 0 | GeoXH 6000 | 08/19/2015 | 11:20:59am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595096.7 | 510981.0 | 59066 | 1.64041666667 | 11035 |
| 010962 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:00am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595096.7 | 510981.1 | 59068 | 1.64041666667 | 10962 |
| 011371 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:01am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595096.8 | 510981.1 | 59070 | 1.64041666667 | 11371 |
| 011301 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:02am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595096.8 | 510981.1 | 59072 | 1.64041666667 | 11301 |
| 010774 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:03am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595096.9 | 510981.1 | 59074 | 1.64041666667 | 10774 |
| 010605 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:04am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.2 | 510981.1 | 59076 | 1.64041666667 | 10605 |
| 011028 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:05am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.4 | 510981.0 | 59078 | 1.64041666667 | 11028 |
| 010913 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:06am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.4 | 510981.0 | 59080 | 1.64041666667 | 10913 |
| 010781 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:07am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.4 | 510980.9 | 59082 | 1.64041666667 | 10781 |
| 009807 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:08am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.4 | 510980.8 | 59084 | 1.64041666667 | 9807 |
| 009933 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:09am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.4 | 510980.8 | 59086 | 1.64041666667 | 9933 |
| 009727 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:10am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.4 | 510980.8 | 59088 | 1.64041666667 | 9727 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 009806 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:11am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.3 | 510980.9 | 59090 | 1.64041666667 | 9806 |
| 010466 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:12am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.2 | 510981.0 | 59092 | 1.64041666667 | 10466 |
| 009907 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:13am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.3 | 510981.2 | 59094 | 1.64041666667 | 9907 |
| 009967 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:14am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.4 | 510981.2 | 59096 | 1.64041666667 | 9967 |
| 009956 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:15am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.4 | 510981.1 | 59098 | 1.64041666667 | 9956 |
| 010295 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:16am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.5 | 510981.1 | 59100 | 1.64041666667 | 10295 |
| 009954 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:17am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.5 | 510981.1 | 59102 | 1.64041666667 | 9954 |
| 010189 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:18am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.6 | 510981.1 | 59104 | 1.64041666667 | 10189 |
| 010043 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:19am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.6 | 510981.1 | 59106 | 1.64041666667 | 10043 |
| 010689 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:20am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595097.6 | 510981.2 | 59108 | 1.64041666667 | 10689 |
| 010513 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:21am | Sensor | 1797-S0042-G-636-DTE | 6825.8 | 1595097.6 | 510981.1 | 59110 | 1.64041666667 | 10513 |
| 011036 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:22am | Sensor | 1797-S0042-G-636-DTE | 6825.8 | 1595097.5 | 510981.1 | 59112 | 1.64041666667 | 11036 |
| 010917 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:23am | Sensor | 1797-S0042-G-636-DTE | 6825.8 | 1595097.2 | 510980.9 | 59114 | 1.64041666667 | 10917 |
| 010341 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:24am | Sensor | 1797-S0042-G-636-DTE | 6825.8 | 1595097.0 | 510981.1 | 59116 | 1.64041666667 | 10341 |
| 010564 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:25am | Sensor | 1797-S0042-G-636-DTE | 6824.2 | 1595097.1 | 510980.7 | 59118 | 1.64041666667 | 10564 |
| 010382 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:26am | Sensor | 1797-S0042-G-636-DTE | 6822.2 | 1595097.7 | 510980.4 | 59120 | 1.64041666667 | 10382 |
| 011022 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:27am | Sensor | 1797-S0042-G-636-DTE | 6826.2 | 1595097.8 | 510984.1 | 59122 | 1.64041666667 | 11022 |
| 010332 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:28am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.6 | 510985.2 | 59124 | 1.64041666667 | 10332 |
| 010694 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:29am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595097.2 | 510986.1 | 59126 | 1.64041666667 | 10694 |
| 011078 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:30am | Sensor | 1797-S0042-G-636-DTE | 6825.7 | 1595094.8 | 510987.8 | 59128 | 1.64041666667 | 11078 |
| 012051 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:31am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595091.9 | 510988.5 | 59130 | 1.64041666667 | 12051 |
| 011924 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:32am | Sensor | 1797-S0042-G-636-DTE | 6824.9 | 1595090.4 | 510988.4 | 59132 | 1.64041666667 | 11924 |
| 012377 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:33am | Sensor | 1797-S0042-G-636-DTE | 6820.0 | 1595090.6 | 510987.2 | 59134 | 1.64041666667 | 12377 |
| 012002 | 0 | GeoXH 6000 | 08/19/2015 | 11:21:34am | Sensor | 1797-S0042-G-636-DTE | 6813.8 | 1595091.9 | 510986.0 | 59142 | 1.64041666667 | 12002 |
| 040226 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:56am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511195.1 | 59144 | 1.64041666667 | 40226 |
| 039945 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:57am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511195.1 | 59146 | 1.64041666667 | 39945 |
| 040488 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:58am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511195.1 | 59148 | 1.64041666667 | 40488 |
| 041985 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:59am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511195.0 | 59150 | 1.64041666667 | 41985 |
| 041009 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:00am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511195.0 | 59151 | 1.64041666667 | 41009 |
| 041480 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:01am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511195.0 | 59152 | 1.64041666667 | 41480 |
| 042000 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:02am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511194.9 | 59153 | 1.64041666667 | 42000 |
| 040530 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:03am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511194.9 | 59154 | 1.64041666667 | 40530 |
| 040243 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:04am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.9 | 59155 | 1.64041666667 | 40243 |
| 039586 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:05am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511195.0 | 59156 | 1.64041666667 | 39586 |
| 040117 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:06am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511195.0 | 59157 | 1.64041666667 | 40117 |
| 040783 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:07am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511195.0 | 59158 | 1.64041666667 | 40783 |
| 040888 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:08am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511195.0 | 59159 | 1.64041666667 | 40888 |
| 041509 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:09am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511195.0 | 59160 | 1.64041666667 | 41509 |
| 040726 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:10am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.4 | 511194.9 | 59161 | 1.64041666667 | 40726 |
| 039753 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:11am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.5 | 511194.9 | 59162 | 1.64041666667 | 39753 |
| 039858 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:12am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.9 | 59163 | 1.64041666667 | 39858 |
| 040990 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:13am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.5 | 511194.9 | 59164 | 1.64041666667 | 40990 |
| 041597 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:14am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511194.9 | 59165 | 1.64041666667 | 41597 |
| 041593 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:15am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511194.9 | 59166 | 1.64041666667 | 41593 |
| 041808 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:16am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511194.9 | 59167 | 1.64041666667 | 41808 |
| 041240 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:17am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511194.9 | 59168 | 1.64041666667 | 41240 |
| 041415 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:18am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.6 | 511194.9 | 59169 | 1.64041666667 | 41415 |
| 041408 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:19am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.5 | 511194.9 | 59170 | 1.64041666667 | 41408 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 041892 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:20am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.5 | 511194.9 | 59171 | 1.64041666667 | 41892 |
| 041804 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:21am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.5 | 511194.9 | 59172 | 1.64041666667 | 41804 |
| 041530 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:22am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.5 | 511194.8 | 59173 | 1.64041666667 | 41530 |
| 040610 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:23am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.5 | 511194.8 | 59174 | 1.64041666667 | 40610 |
| 040588 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:24am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.5 | 511194.8 | 59175 | 1.64041666667 | 40588 |
| 041213 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:25am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.5 | 511194.8 | 59176 | 1.64041666667 | 41213 |
| 041890 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:26am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.8 | 59177 | 1.64041666667 | 41890 |
| 042021 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:27am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.8 | 59178 | 1.64041666667 | 42021 |
| 043429 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:28am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.8 | 59179 | 1.64041666667 | 43429 |
| 042331 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:29am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.8 | 59180 | 1.64041666667 | 42331 |
| 042854 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:30am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.8 | 59181 | 1.64041666667 | 42854 |
| 043275 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:31am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.8 | 59182 | 1.64041666667 | 43275 |
| 043039 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:32am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.8 | 59183 | 1.64041666667 | 43039 |
| 041250 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:33am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.8 | 59184 | 1.64041666667 | 41250 |
| 039140 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:34am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.8 | 59185 | 1.64041666667 | 39140 |
| 041134 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:35am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.8 | 59186 | 1.64041666667 | 41134 |
| 040905 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:36am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.9 | 59187 | 1.64041666667 | 40905 |
| 041639 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:37am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.9 | 59188 | 1.64041666667 | 41639 |
| 041549 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:38am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511195.0 | 59189 | 1.64041666667 | 41549 |
| 041131 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:39am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511195.0 | 59190 | 1.64041666667 | 41131 |
| 040709 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:40am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.9 | 59191 | 1.64041666667 | 40709 |
| 041513 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:41am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.6 | 511194.9 | 59192 | 1.64041666667 | 41513 |
| 040624 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:42am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.8 | 59193 | 1.64041666667 | 40624 |
| 040918 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:43am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.8 | 511194.8 | 59194 | 1.64041666667 | 40918 |
| 041841 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:44am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.8 | 511194.9 | 59195 | 1.64041666667 | 41841 |
| 042450 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:45am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.8 | 511194.9 | 59196 | 1.64041666667 | 42450 |
| 040919 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:47am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.8 | 511194.8 | 59197 | 1.64041666667 | 40919 |
| 042127 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:48am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.8 | 511194.8 | 59199 | 1.64041666667 | 42127 |
| 042626 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:49am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.9 | 59201 | 1.64041666667 | 42626 |
| 042007 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:50am | Sensor | 1797-S0042-G-636-DTE | 6825.6 | 1595182.7 | 511194.9 | 59203 | 1.64041666667 | 42007 |
| 040279 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:51am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.7 | 511194.9 | 59205 | 1.64041666667 | 40279 |
| 041864 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:52am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.7 | 511194.9 | 59207 | 1.64041666667 | 41864 |
| 042381 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:53am | Sensor | 1797-S0042-G-636-DTE | 6825.5 | 1595182.7 | 511195.2 | 59209 | 1.64041666667 | 42381 |
| 015075 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:38am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.7 | 511888.3 | 59210 | 1.64041666667 | 15075 |
| 014675 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:39am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.7 | 511888.5 | 59212 | 1.64041666667 | 14675 |
| 015439 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:40am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.7 | 511888.5 | 59214 | 1.64041666667 | 15439 |
| 014992 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:41am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.7 | 511888.5 | 59216 | 1.64041666667 | 14992 |
| 014838 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:42am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.6 | 511888.5 | 59218 | 1.64041666667 | 14838 |
| 014451 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:43am | Sensor | 1797-S0042-G-636-DTE | 6830.0 | 1595090.5 | 511888.5 | 59220 | 1.64041666667 | 14451 |
| 014466 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:44am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.9 | 511888.4 | 59222 | 1.64041666667 | 14466 |
| 014842 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:45am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.8 | 511888.6 | 59224 | 1.64041666667 | 14842 |
| 014033 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:46am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.8 | 511888.5 | 59226 | 1.64041666667 | 14033 |
| 014486 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:47am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595090.6 | 511888.6 | 59228 | 1.64041666667 | 14486 |
| 014291 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:48am | Sensor | 1797-S0042-G-636-DTE | 6830.0 | 1595089.7 | 511889.4 | 59230 | 1.64041666667 | 14291 |
| 014443 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:49am | Sensor | 1797-S0042-G-636-DTE | 6830.0 | 1595087.3 | 511891.0 | 59232 | 1.64041666667 | 14443 |
| 013892 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:50am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595083.8 | 511893.0 | 59234 | 1.64041666667 | 13892 |
| 013589 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:51am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595081.2 | 511895.2 | 59236 | 1.64041666667 | 13589 |
| 014881 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:52am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595078.2 | 511898.5 | 59238 | 1.64041666667 | 14881 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014385 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:53am | Sensor | 1797-S0042-G-636-DTE | 6830.1 | 1595076.0 | 511901.4 | 59240 | 1.64041666667 | 14385 |
| 014474 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:54am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595073.7 | 511904.6 | 59242 | 1.64041666667 | 14474 |
| 014862 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:55am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595073.0 | 511907.4 | 59244 | 1.64041666667 | 14862 |
| 014427 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:56am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595072.0 | 511909.6 | 59246 | 1.64041666667 | 14427 |
| 014895 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:57am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595071.8 | 511910.1 | 59248 | 1.64041666667 | 14895 |
| 013696 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:58am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595072.0 | 511910.1 | 59250 | 1.64041666667 | 13696 |
| 012916 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:59am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595071.9 | 511910.2 | 59252 | 1.64041666667 | 12916 |
| 013948 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:00am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595072.0 | 511910.1 | 59254 | 1.64041666667 | 13948 |
| 013898 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:01am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595072.0 | 511910.1 | 59256 | 1.64041666667 | 13898 |
| 014245 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:02am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595072.1 | 511910.1 | 59258 | 1.64041666667 | 14245 |
| 013855 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:03am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595072.0 | 511910.0 | 59260 | 1.64041666667 | 13855 |
| 014018 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:04am | Sensor | 1797-S0042-G-636-DTE | 6830.2 | 1595071.9 | 511910.0 | 59262 | 1.64041666667 | 14018 |
| 013968 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:05am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595071.9 | 511910.0 | 59264 | 1.64041666667 | 13968 |
| 013534 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:06am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595071.2 | 511910.2 | 59266 | 1.64041666667 | 13534 |
| 013275 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:07am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595068.8 | 511911.3 | 59268 | 1.64041666667 | 13275 |
| 013835 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:08am | Sensor | 1797-S0042-G-636-DTE | 6830.5 | 1595066.0 | 511913.7 | 59270 | 1.64041666667 | 13835 |
| 013707 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:09am | Sensor | 1797-S0042-G-636-DTE | 6830.4 | 1595064.4 | 511916.2 | 59272 | 1.64041666667 | 13707 |
| 013747 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:10am | Sensor | 1797-S0042-G-636-DTE | 6830.5 | 1595062.3 | 511919.8 | 59274 | 1.64041666667 | 13747 |
| 013665 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:11am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595059.9 | 511922.9 | 59276 | 1.64041666667 | 13665 |
| 013507 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:12am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595057.8 | 511926.3 | 59278 | 1.64041666667 | 13507 |
| 013845 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:13am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595056.8 | 511929.7 | 59280 | 1.64041666667 | 13845 |
| 014013 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:14am | Sensor | 1797-S0042-G-636-DTE | 6830.4 | 1595057.8 | 511932.8 | 59282 | 1.64041666667 | 14013 |
| 013897 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:15am | Sensor | 1797-S0042-G-636-DTE | 6830.6 | 1595058.7 | 511934.6 | 59284 | 1.64041666667 | 13897 |
| 015497 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:16am | Sensor | 1797-S0042-G-636-DTE | 6830.4 | 1595061.0 | 511936.9 | 59286 | 1.64041666667 | 15497 |
| 015204 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:17am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595064.3 | 511938.9 | 59288 | 1.64041666667 | 15204 |
| 014597 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:18am | Sensor | 1797-S0042-G-636-DTE | 6830.4 | 1595068.7 | 511940.8 | 59290 | 1.64041666667 | 14597 |
| 014196 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:19am | Sensor | 1797-S0042-G-636-DTE | 6830.8 | 1595071.6 | 511941.7 | 59292 | 1.64041666667 | 14196 |
| 015005 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:20am | Sensor | 1797-S0042-G-636-DTE | 6830.6 | 1595075.7 | 511942.7 | 59294 | 1.64041666667 | 15005 |
| 014395 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:21am | Sensor | 1797-S0042-G-636-DTE | 6830.4 | 1595079.3 | 511943.9 | 59296 | 1.64041666667 | 14395 |
| 014442 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:22am | Sensor | 1797-S0042-G-636-DTE | 6830.5 | 1595083.7 | 511946.0 | 59298 | 1.64041666667 | 14442 |
| 015443 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:23am | Sensor | 1797-S0042-G-636-DTE | 6830.8 | 1595087.1 | 511948.0 | 59300 | 1.64041666667 | 15443 |
| 015782 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:24am | Sensor | 1797-S0042-G-636-DTE | 6830.8 | 1595091.1 | 511949.8 | 59302 | 1.64041666667 | 15782 |
| 016820 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:25am | Sensor | 1797-S0042-G-636-DTE | 6830.9 | 1595094.2 | 511951.0 | 59304 | 1.64041666667 | 16820 |
| 017733 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:26am | Sensor | 1797-S0042-G-636-DTE | 6830.9 | 1595097.2 | 511951.7 | 59306 | 1.64041666667 | 17733 |
| 017137 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:27am | Sensor | 1797-S0042-G-636-DTE | 6831.0 | 1595099.0 | 511951.7 | 59308 | 1.64041666667 | 17137 |
| 016442 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:28am | Sensor | 1797-S0042-G-636-DTE | 6831.0 | 1595100.5 | 511950.6 | 59310 | 1.64041666667 | 16442 |
| 017334 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:29am | Sensor | 1797-S0042-G-636-DTE | 6830.8 | 1595103.1 | 511948.3 | 59312 | 1.64041666667 | 17334 |
| 016605 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:30am | Sensor | 1797-S0042-G-636-DTE | 6830.7 | 1595105.9 | 511944.6 | 59314 | 1.64041666667 | 16605 |
| 016375 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:31am | Sensor | 1797-S0042-G-636-DTE | 6830.6 | 1595107.0 | 511940.8 | 59316 | 1.64041666667 | 16375 |
| 016291 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:32am | Sensor | 1797-S0042-G-636-DTE | 6830.6 | 1595107.8 | 511936.8 | 59318 | 1.64041666667 | 16291 |
| 016371 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:33am | Sensor | 1797-S0042-G-636-DTE | 6830.6 | 1595108.6 | 511933.0 | 59320 | 1.64041666667 | 16371 |
| 015846 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:34am | Sensor | 1797-S0042-G-636-DTE | 6830.4 | 1595109.0 | 511928.7 | 59322 | 1.64041666667 | 15846 |
| 016841 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:35am | Sensor | 1797-S0042-G-636-DTE | 6830.5 | 1595109.4 | 511925.2 | 59324 | 1.64041666667 | 16841 |
| 015765 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:36am | Sensor | 1797-S0042-G-636-DTE | 6830.3 | 1595111.2 | 511921.1 | 59326 | 1.64041666667 | 15765 |
| 016135 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:37am | Sensor | 1797-S0042-G-636-DTE | 6830.6 | 1595113.0 | 511918.2 | 59328 | 1.64041666667 | 16135 |
| 017041 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:38am | Sensor | 1797-S0042-G-636-DTE | 6830.6 | 1595115.3 | 511914.2 | 59330 | 1.64041666667 | 17041 |
| 016733 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:39am | Sensor | 1797-S0042-G-636-DTE | 6830.6 | 1595117.5 | 511910.9 | 59332 | 1.64041666667 | 16733 |
| 018180 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:40am | Sensor | 1797-S0042-G-636-DTE | 6830.7 | 1595119.4 | 511907.3 | 59334 | 1.64041666667 | 18180 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017951 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:41am | Sensor | 1797-S0042-G-636-DTE | 6830.7 | 1595120.5 | 511904.3 | 59336 | 1.64041666667 | 17951 |
| 017207 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:42am | Sensor | 1797-S0042-G-636-DTE | 6830.8 | 1595121.9 | 511900.2 | 59338 | 1.64041666667 | 17207 |
| 016976 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:43am | Sensor | 1797-S0042-G-636-DTE | 6830.7 | 1595123.4 | 511896.7 | 59340 | 1.64041666667 | 16976 |
| 015992 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:44am | Sensor | 1797-S0042-G-636-DTE | 6830.8 | 1595125.6 | 511892.9 | 59342 | 1.64041666667 | 15992 |
| 015618 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:45am | Sensor | 1797-S0042-G-636-DTE | 6830.8 | 1595127.5 | 511889.4 | 59344 | 1.64041666667 | 15618 |
| 014687 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:46am | Sensor | 1797-S0042-G-636-DTE | 6830.8 | 1595129.1 | 511885.5 | 59346 | 1.64041666667 | 14687 |
| 014711 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:47am | Sensor | 1797-S0042-G-636-DTE | 6830.9 | 1595130.4 | 511882.0 | 59348 | 1.64041666667 | 14711 |
| 011294 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:56am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56477 | 1.64041666667 | 11294 |
| 010597 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:57am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56478 | 1.64041666667 | 10597 |
| 010731 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:58am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56481 | 1.64041666667 | 10731 |
| 010829 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:59am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56483 | 1.64041666667 | 10829 |
| 010291 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:00am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56485 | 1.64041666667 | 10291 |
| 010641 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:01am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56487 | 1.64041666667 | 10641 |
| 009713 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:02am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.6 | 510881.2 | 56489 | 1.64041666667 | 9713 |
| 009866 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:03am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.6 | 510881.2 | 56491 | 1.64041666667 | 9866 |
| 010072 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:04am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.6 | 510881.2 | 56493 | 1.64041666667 | 10072 |
| 010353 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:05am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56495 | 1.64041666667 | 10353 |
| 010886 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:06am | Sensor | 1797-S0041-G-636-DTE | 6818.1 | 1594828.7 | 510881.2 | 56497 | 1.64041666667 | 10886 |
| 011014 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:07am | Sensor | 1797-S0041-G-636-DTE | 6818.1 | 1594828.7 | 510881.2 | 56499 | 1.64041666667 | 11014 |
| 011528 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:08am | Sensor | 1797-S0041-G-636-DTE | 6818.1 | 1594828.7 | 510881.2 | 56501 | 1.64041666667 | 11528 |
| 011307 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:09am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56503 | 1.64041666667 | 11307 |
| 010867 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:10am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56505 | 1.64041666667 | 10867 |
| 010410 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:11am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56507 | 1.64041666667 | 10410 |
| 010416 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:12am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56509 | 1.64041666667 | 10416 |
| 010651 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:13am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56511 | 1.64041666667 | 10651 |
| 010109 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:14am | Sensor | 1797-S0041-G-636-DTE | 6818.1 | 1594828.7 | 510881.2 | 56513 | 1.64041666667 | 10109 |
| 010148 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:15am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56515 | 1.64041666667 | 10148 |
| 010343 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:16am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56517 | 1.64041666667 | 10343 |
| 010303 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:17am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56519 | 1.64041666667 | 10303 |
| 010280 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:18am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.7 | 510881.2 | 56521 | 1.64041666667 | 10280 |
| 010410 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:19am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.8 | 510881.2 | 56523 | 1.64041666667 | 10410 |
| 010040 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:20am | Sensor | 1797-S0041-G-636-DTE | 6818.0 | 1594828.8 | 510881.2 | 56525 | 1.64041666667 | 10040 |
| 010485 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:21am | Sensor | 1797-S0041-G-636-DTE | 6818.1 | 1594828.8 | 510881.2 | 56527 | 1.64041666667 | 10485 |
| 012671 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:25am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595054.2 | 511261.9 | 56529 | 1.64041666667 | 12671 |
| 012144 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:26am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595054.4 | 511262.2 | 56531 | 1.64041666667 | 12144 |
| 012471 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:27am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595054.5 | 511262.1 | 56533 | 1.64041666667 | 12471 |
| 012572 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:28am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595054.6 | 511262.0 | 56535 | 1.64041666667 | 12572 |
| 013132 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:29am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595054.5 | 511261.9 | 56537 | 1.64041666667 | 13132 |
| 013612 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:30am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595054.0 | 511261.5 | 56539 | 1.64041666667 | 13612 |
| 013731 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:31am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595052.2 | 511260.9 | 56541 | 1.64041666667 | 13731 |
| 012764 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:32am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595048.9 | 511260.7 | 56543 | 1.64041666667 | 12764 |
| 012692 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:33am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595046.2 | 511260.7 | 56545 | 1.64041666667 | 12692 |
| 013214 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:34am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595042.8 | 511260.2 | 56547 | 1.64041666667 | 13214 |
| 013305 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:35am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595040.0 | 511259.7 | 56549 | 1.64041666667 | 13305 |
| 013702 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:36am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595036.5 | 511258.8 | 56551 | 1.64041666667 | 13702 |
| 014292 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:37am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595033.6 | 511258.2 | 56553 | 1.64041666667 | 14292 |
| 013537 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:38am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595029.9 | 511257.5 | 56555 | 1.64041666667 | 13537 |
| 012452 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:39am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595026.9 | 511256.9 | 56557 | 1.64041666667 | 12452 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012239 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:40am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595023.6 | 511256.6 | 56559 | 1.64041666667 | 12239 |
| 012097 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:41am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595022.3 | 511256.7 | 56561 | 1.64041666667 | 12097 |
| 012707 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:42am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595021.8 | 511256.7 | 56563 | 1.64041666667 | 12707 |
| 012660 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:43am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595021.8 | 511256.3 | 56565 | 1.64041666667 | 12660 |
| 012603 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:44am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595021.8 | 511256.1 | 56567 | 1.64041666667 | 12603 |
| 013224 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:45am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595020.3 | 511256.6 | 56569 | 1.64041666667 | 13224 |
| 012074 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:46am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595016.8 | 511256.7 | 56571 | 1.64041666667 | 12074 |
| 012289 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:47am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595013.9 | 511256.1 | 56573 | 1.64041666667 | 12289 |
| 012597 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:48am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595010.7 | 511255.0 | 56575 | 1.64041666667 | 12597 |
| 012073 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:49am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595009.4 | 511253.4 | 56577 | 1.64041666667 | 12073 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:50am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595008.9 | 511252.4 | 56579 | 1.64041666667 | 12521 |
| 011880 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:51am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595008.7 | 511252.4 | 56581 | 1.64041666667 | 11880 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:52am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595008.7 | 511252.5 | 56583 | 1.64041666667 | 12960 |
| 012277 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:53am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595008.7 | 511252.5 | 56585 | 1.64041666667 | 12277 |
| 013408 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:54am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595008.8 | 511251.9 | 56587 | 1.64041666667 | 13408 |
| 013797 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:55am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595009.4 | 511251.3 | 56589 | 1.64041666667 | 13797 |
| 014001 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:56am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595011.8 | 511249.8 | 56591 | 1.64041666667 | 14001 |
| 012585 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:57am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595014.2 | 511247.4 | 56593 | 1.64041666667 | 12585 |
| 012292 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:58am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595015.0 | 511244.1 | 56595 | 1.64041666667 | 12292 |
| 012441 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:59am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595014.3 | 511241.0 | 56597 | 1.64041666667 | 12441 |
| 012548 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:00am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595013.9 | 511238.4 | 56599 | 1.64041666667 | 12548 |
| 012173 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:01am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595013.7 | 511236.7 | 56601 | 1.64041666667 | 12173 |
| 011670 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:02am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595012.4 | 511234.7 | 56603 | 1.64041666667 | 11670 |
| 011537 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:03am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595010.9 | 511232.8 | 56605 | 1.64041666667 | 11537 |
| 011282 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:04am | Sensor | 1797-S0041-G-636-DTE | 6823.1 | 1595008.0 | 511231.4 | 56607 | 1.64041666667 | 11282 |
| 012931 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:05am | Sensor | 1797-S0041-G-636-DTE | 6822.7 | 1595004.9 | 511230.8 | 56609 | 1.64041666667 | 12931 |
| 012096 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:06am | Sensor | 1797-S0041-G-636-DTE | 6822.5 | 1595002.6 | 511228.7 | 56611 | 1.64041666667 | 12096 |
| 011559 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:07am | Sensor | 1797-S0041-G-636-DTE | 6822.9 | 1595001.8 | 511226.3 | 56613 | 1.64041666667 | 11559 |
| 011932 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:08am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595001.3 | 511224.5 | 56615 | 1.64041666667 | 11932 |
| 011429 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:09am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595001.7 | 511222.9 | 56617 | 1.64041666667 | 11429 |
| 011334 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:10am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595003.3 | 511219.9 | 56619 | 1.64041666667 | 11334 |
| 011820 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:11am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595004.1 | 511217.7 | 56621 | 1.64041666667 | 11820 |
| 011966 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:12am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595004.0 | 511217.1 | 56623 | 1.64041666667 | 11966 |
| 012468 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:13am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595004.2 | 511217.2 | 56625 | 1.64041666667 | 12468 |
| 011723 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:14am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595004.1 | 511217.0 | 56627 | 1.64041666667 | 11723 |
| 011994 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:15am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595004.1 | 511215.8 | 56629 | 1.64041666667 | 11994 |
| 011644 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:16am | Sensor | 1797-S0041-G-636-DTE | 6823.0 | 1595003.9 | 511213.1 | 56631 | 1.64041666667 | 11644 |
| 011897 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:17am | Sensor | 1797-S0041-G-636-DTE | 6823.0 | 1595003.4 | 511210.1 | 56633 | 1.64041666667 | 11897 |
| 011710 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:18am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595003.0 | 511206.2 | 56635 | 1.64041666667 | 11710 |
| 011761 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:19am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.9 | 511203.7 | 56637 | 1.64041666667 | 11761 |
| 011753 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:20am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.6 | 511201.1 | 56639 | 1.64041666667 | 11753 |
| 012438 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:21am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.6 | 511198.4 | 56641 | 1.64041666667 | 12438 |
| 012817 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:22am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.9 | 511196.5 | 56643 | 1.64041666667 | 12817 |
| 012572 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:23am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595003.0 | 511196.2 | 56645 | 1.64041666667 | 12572 |
| 012801 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:24am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.5 | 511196.4 | 56647 | 1.64041666667 | 12801 |
| 012646 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:25am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.4 | 511196.4 | 56649 | 1.64041666667 | 12646 |
| 012086 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:26am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.4 | 511196.4 | 56651 | 1.64041666667 | 12086 |
| 012363 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:27am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.5 | 511196.4 | 56653 | 1.64041666667 | 12363 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011829 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:28am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.6 | 511196.4 | 56655 | 1.64041666667 | 11829 |
| 011994 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:29am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.6 | 511196.4 | 56657 | 1.64041666667 | 11994 |
| 011824 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:30am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.5 | 511196.4 | 56659 | 1.64041666667 | 11824 |
| 012036 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:31am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.4 | 511196.4 | 56661 | 1.64041666667 | 12036 |
| 012237 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:32am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.2 | 511196.4 | 56663 | 1.64041666667 | 12237 |
| 012381 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:33am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.2 | 511196.5 | 56665 | 1.64041666667 | 12381 |
| 011899 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:34am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595002.5 | 511196.4 | 56667 | 1.64041666667 | 11899 |
| 012333 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:35am | Sensor | 1797-S0041-G-636-DTE | 6823.2 | 1595002.7 | 511196.3 | 56669 | 1.64041666667 | 12333 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:36am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.8 | 511196.4 | 56671 | 1.64041666667 | 12742 |
| 012042 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:37am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.7 | 511196.3 | 56673 | 1.64041666667 | 12042 |
| 012444 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:38am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.8 | 511196.2 | 56675 | 1.64041666667 | 12444 |
| 012489 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:39am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595003.0 | 511196.1 | 56677 | 1.64041666667 | 12489 |
| 012058 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:40am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595003.0 | 511195.2 | 56679 | 1.64041666667 | 12058 |
| 012227 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:41am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595003.5 | 511194.1 | 56681 | 1.64041666667 | 12227 |
| 013170 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:42am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595005.8 | 511193.3 | 56683 | 1.64041666667 | 13170 |
| 012921 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:43am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595008.6 | 511193.0 | 56685 | 1.64041666667 | 12921 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:44am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595012.5 | 511192.8 | 56687 | 1.64041666667 | 12045 |
| 012453 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:45am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595016.4 | 511192.1 | 56689 | 1.64041666667 | 12453 |
| 012337 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:46am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595020.2 | 511191.8 | 56691 | 1.64041666667 | 12337 |
| 012527 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:47am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595022.7 | 511191.0 | 56693 | 1.64041666667 | 12527 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:48am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595026.3 | 511189.4 | 56695 | 1.64041666667 | 12626 |
| 012307 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:49am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595028.8 | 511189.0 | 56697 | 1.64041666667 | 12307 |
| 013042 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:50am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595030.6 | 511188.5 | 56699 | 1.64041666667 | 13042 |
| 012984 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:51am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595031.0 | 511188.0 | 56701 | 1.64041666667 | 12984 |
| 013108 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:52am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595031.2 | 511188.1 | 56703 | 1.64041666667 | 13108 |
| 013561 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:53am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595031.1 | 511188.4 | 56705 | 1.64041666667 | 13561 |
| 013058 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:54am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.1 | 511188.3 | 56707 | 1.64041666667 | 13058 |
| 013180 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:55am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595033.5 | 511187.8 | 56709 | 1.64041666667 | 13180 |
| 013443 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:56am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595035.9 | 511187.0 | 56711 | 1.64041666667 | 13443 |
| 012939 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:57am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595038.4 | 511186.8 | 56713 | 1.64041666667 | 12939 |
| 012843 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:58am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595041.9 | 511187.1 | 56715 | 1.64041666667 | 12843 |
| 013179 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:59am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595045.0 | 511187.2 | 56717 | 1.64041666667 | 13179 |
| 013256 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:00am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595048.8 | 511187.5 | 56719 | 1.64041666667 | 13256 |
| 013231 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:01am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595051.8 | 511188.5 | 56721 | 1.64041666667 | 13231 |
| 011672 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:02am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595055.3 | 511190.0 | 56723 | 1.64041666667 | 11672 |
| 012693 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:03am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595059.0 | 511190.7 | 56725 | 1.64041666667 | 12693 |
| 013230 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:04am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595062.9 | 511191.4 | 56727 | 1.64041666667 | 13230 |
| 013622 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:05am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595066.5 | 511192.9 | 56729 | 1.64041666667 | 13622 |
| 014502 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:06am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595070.2 | 511195.1 | 56731 | 1.64041666667 | 14502 |
| 014645 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:07am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595073.4 | 511196.7 | 56733 | 1.64041666667 | 14645 |
| 013690 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:08am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595077.3 | 511198.2 | 56735 | 1.64041666667 | 13690 |
| 013130 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:09am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595081.2 | 511199.6 | 56737 | 1.64041666667 | 13130 |
| 013326 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:10am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595085.1 | 511201.2 | 56739 | 1.64041666667 | 13326 |
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:11am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595088.4 | 511203.0 | 56741 | 1.64041666667 | 13451 |
| 013708 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:12am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595091.9 | 511205.1 | 56743 | 1.64041666667 | 13708 |
| 013501 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:13am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595095.1 | 511206.6 | 56745 | 1.64041666667 | 13501 |
| 013114 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:14am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595099.0 | 511208.1 | 56747 | 1.64041666667 | 13114 |
| 012371 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:15am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595101.7 | 511209.2 | 56749 | 1.64041666667 | 12371 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012344 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:16am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595105.1 | 511211.4 | 56751 | 1.64041666667 | 12344 |
| 012948 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:17am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595107.9 | 511213.4 | 56753 | 1.64041666667 | 12948 |
| 012891 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:18am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595111.2 | 511215.6 | 56755 | 1.64041666667 | 12891 |
| 012944 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:19am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595113.2 | 511217.0 | 56757 | 1.64041666667 | 12944 |
| 013296 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:20am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595115.5 | 511218.4 | 56759 | 1.64041666667 | 13296 |
| 012774 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:21am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595117.5 | 511219.6 | 56761 | 1.64041666667 | 12774 |
| 012300 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:22am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595120.5 | 511222.0 | 56763 | 1.64041666667 | 12300 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:23am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595123.4 | 511223.4 | 56765 | 1.64041666667 | 12431 |
| 013877 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:24am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595126.9 | 511225.0 | 56767 | 1.64041666667 | 13877 |
| 013993 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:25am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595129.8 | 511226.9 | 56769 | 1.64041666667 | 13993 |
| 013106 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:26am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595132.7 | 511229.0 | 56771 | 1.64041666667 | 13106 |
| 013575 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:27am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595135.0 | 511229.8 | 56773 | 1.64041666667 | 13575 |
| 013013 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:28am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595136.9 | 511230.9 | 56775 | 1.64041666667 | 13013 |
| 013252 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:29am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595137.6 | 511232.3 | 56777 | 1.64041666667 | 13252 |
| 013507 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:30am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595137.5 | 511234.8 | 56779 | 1.64041666667 | 13507 |
| 012862 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:31am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595136.3 | 511237.3 | 56781 | 1.64041666667 | 12862 |
| 013707 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:32am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595134.6 | 511240.7 | 56783 | 1.64041666667 | 13707 |
| 013628 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:33am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595134.1 | 511243.4 | 56785 | 1.64041666667 | 13628 |
| 013853 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:34am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595134.5 | 511247.0 | 56787 | 1.64041666667 | 13853 |
| 012997 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:35am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595134.4 | 511250.5 | 56789 | 1.64041666667 | 12997 |
| 013251 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:36am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595133.8 | 511255.1 | 56791 | 1.64041666667 | 13251 |
| 012793 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:37am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595133.4 | 511258.8 | 56793 | 1.64041666667 | 12793 |
| 012551 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:38am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595132.2 | 511262.9 | 56795 | 1.64041666667 | 12551 |
| 012422 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:39am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595130.9 | 511265.9 | 56797 | 1.64041666667 | 12422 |
| 011780 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:40am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595129.2 | 511269.7 | 56799 | 1.64041666667 | 11780 |
| 012513 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:41am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595127.9 | 511272.5 | 56801 | 1.64041666667 | 12513 |
| 012356 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:42am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595125.7 | 511275.1 | 56803 | 1.64041666667 | 12356 |
| 012485 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:43am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595123.7 | 511277.7 | 56805 | 1.64041666667 | 12485 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:44am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595122.9 | 511281.0 | 56807 | 1.64041666667 | 12475 |
| 012335 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:45am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595122.8 | 511284.2 | 56809 | 1.64041666667 | 12335 |
| 012173 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:46am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595123.1 | 511288.1 | 56811 | 1.64041666667 | 12173 |
| 011902 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:47am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595123.6 | 511291.1 | 56813 | 1.64041666667 | 11902 |
| 012387 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:48am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595123.8 | 511295.0 | 56815 | 1.64041666667 | 12387 |
| 012683 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:49am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595122.7 | 511298.4 | 56817 | 1.64041666667 | 12683 |
| 012984 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:50am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595120.5 | 511302.1 | 56819 | 1.64041666667 | 12984 |
| 012636 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:51am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595118.2 | 511305.0 | 56821 | 1.64041666667 | 12636 |
| 011487 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:52am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595116.0 | 511308.1 | 56823 | 1.64041666667 | 11487 |
| 011861 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:53am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595114.7 | 511310.9 | 56825 | 1.64041666667 | 11861 |
| 012027 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:54am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595113.1 | 511313.7 | 56827 | 1.64041666667 | 12027 |
| 011962 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:55am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595110.9 | 511316.0 | 56829 | 1.64041666667 | 11962 |
| 012361 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:56am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595108.0 | 511317.8 | 56831 | 1.64041666667 | 12361 |
| 012660 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:57am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595104.9 | 511319.3 | 56833 | 1.64041666667 | 12660 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:58am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595102.5 | 511322.1 | 56835 | 1.64041666667 | 12521 |
| 012811 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:59am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595102.1 | 511324.5 | 56837 | 1.64041666667 | 12811 |
| 013161 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:00am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595101.9 | 511326.8 | 56839 | 1.64041666667 | 13161 |
| 013170 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:01am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595101.2 | 511328.9 | 56841 | 1.64041666667 | 13170 |
| 013093 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:02am | Sensor | 1797-S0041-G-636-DTE | 6825.7 | 1595100.7 | 511330.9 | 56843 | 1.64041666667 | 13093 |
| 013522 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:03am | Sensor | 1797-S0041-G-636-DTE | 6825.8 | 1595100.8 | 511331.8 | 56845 | 1.64041666667 | 13522 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013171 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:04am | Sensor | 1797-S0041-G-636-DTE | 6825.8 | 1595100.8 | 511331.8 | 56847 | 1.64041666667 | 13171 |
| 013491 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:05am | Sensor | 1797-S0041-G-636-DTE | 6825.8 | 1595100.9 | 511331.5 | 56849 | 1.64041666667 | 13491 |
| 013176 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:06am | Sensor | 1797-S0041-G-636-DTE | 6825.7 | 1595100.9 | 511331.2 | 56851 | 1.64041666667 | 13176 |
| 013074 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:07am | Sensor | 1797-S0041-G-636-DTE | 6825.7 | 1595100.9 | 511331.1 | 56853 | 1.64041666667 | 13074 |
| 012911 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:08am | Sensor | 1797-S0041-G-636-DTE | 6825.7 | 1595100.1 | 511331.7 | 56855 | 1.64041666667 | 12911 |
| 012813 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:09am | Sensor | 1797-S0041-G-636-DTE | 6825.7 | 1595098.2 | 511331.7 | 56857 | 1.64041666667 | 12813 |
| 012592 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:10am | Sensor | 1797-S0041-G-636-DTE | 6825.7 | 1595095.0 | 511330.5 | 56859 | 1.64041666667 | 12592 |
| 013060 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:11am | Sensor | 1797-S0041-G-636-DTE | 6825.7 | 1595092.8 | 511329.6 | 56861 | 1.64041666667 | 13060 |
| 012881 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:12am | Sensor | 1797-S0041-G-636-DTE | 6825.6 | 1595091.6 | 511328.5 | 56863 | 1.64041666667 | 12881 |
| 013065 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:13am | Sensor | 1797-S0041-G-636-DTE | 6825.6 | 1595090.9 | 511327.8 | 56865 | 1.64041666667 | 13065 |
| 013522 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:14am | Sensor | 1797-S0041-G-636-DTE | 6825.6 | 1595088.8 | 511326.8 | 56867 | 1.64041666667 | 13522 |
| 012863 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:15am | Sensor | 1797-S0041-G-636-DTE | 6825.7 | 1595086.2 | 511325.6 | 56869 | 1.64041666667 | 12863 |
| 013700 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:16am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595083.0 | 511323.6 | 56871 | 1.64041666667 | 13700 |
| 014704 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:17am | Sensor | 1797-S0041-G-636-DTE | 6825.6 | 1595080.5 | 511321.6 | 56873 | 1.64041666667 | 14704 |
| 014301 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:18am | Sensor | 1797-S0041-G-636-DTE | 6825.6 | 1595077.6 | 511319.0 | 56875 | 1.64041666667 | 14301 |
| 014269 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:19am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595074.8 | 511316.3 | 56877 | 1.64041666667 | 14269 |
| 013509 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:20am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595071.6 | 511313.5 | 56879 | 1.64041666667 | 13509 |
| 013771 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:21am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595068.9 | 511311.4 | 56881 | 1.64041666667 | 13771 |
| 013446 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:22am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595065.3 | 511309.4 | 56883 | 1.64041666667 | 13446 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:23am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595062.3 | 511307.8 | 56885 | 1.64041666667 | 13931 |
| 013851 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:24am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595058.1 | 511306.2 | 56887 | 1.64041666667 | 13851 |
| 013588 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:25am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595054.6 | 511305.4 | 56889 | 1.64041666667 | 13588 |
| 014416 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:26am | Sensor | 1797-S0041-G-636-DTE | 6825.6 | 1595050.4 | 511305.0 | 56891 | 1.64041666667 | 14416 |
| 014694 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:27am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595046.8 | 511304.4 | 56893 | 1.64041666667 | 14694 |
| 013800 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:28am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595043.1 | 511302.9 | 56895 | 1.64041666667 | 13800 |
| 014205 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:29am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595040.3 | 511301.6 | 56897 | 1.64041666667 | 14205 |
| 013263 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:30am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595036.5 | 511300.5 | 56899 | 1.64041666667 | 13263 |
| 013423 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:31am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595033.3 | 511299.4 | 56901 | 1.64041666667 | 13423 |
| 013475 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:32am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595030.0 | 511297.2 | 56903 | 1.64041666667 | 13475 |
| 013167 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:33am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595027.9 | 511294.8 | 56905 | 1.64041666667 | 13167 |
| 013106 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:34am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595025.2 | 511292.4 | 56907 | 1.64041666667 | 13106 |
| 012390 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:35am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595021.6 | 511290.8 | 56909 | 1.64041666667 | 12390 |
| 012541 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:36am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595017.8 | 511290.0 | 56911 | 1.64041666667 | 12541 |
| 012237 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:37am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595013.9 | 511289.3 | 56913 | 1.64041666667 | 12237 |
| 012036 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:38am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595010.0 | 511288.7 | 56915 | 1.64041666667 | 12036 |
| 011390 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:39am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595006.8 | 511288.2 | 56917 | 1.64041666667 | 11390 |
| 012272 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:40am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595004.5 | 511287.6 | 56919 | 1.64041666667 | 12272 |
| 012303 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:41am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595003.8 | 511286.8 | 56921 | 1.64041666667 | 12303 |
| 011098 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:42am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595003.0 | 511285.6 | 56923 | 1.64041666667 | 11098 |
| 010892 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:43am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595002.2 | 511284.5 | 56925 | 1.64041666667 | 10892 |
| 011009 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:44am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595001.5 | 511283.0 | 56927 | 1.64041666667 | 11009 |
| 011180 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:45am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595001.5 | 511282.1 | 56929 | 1.64041666667 | 11180 |
| 011358 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:46am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595002.9 | 511280.3 | 56931 | 1.64041666667 | 11358 |
| 011377 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:47am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595003.9 | 511277.5 | 56933 | 1.64041666667 | 11377 |
| 012107 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:48am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595004.6 | 511274.1 | 56935 | 1.64041666667 | 12107 |
| 011587 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:49am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595004.9 | 511272.8 | 56937 | 1.64041666667 | 11587 |
| 011888 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:50am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595004.9 | 511273.8 | 56939 | 1.64041666667 | 11888 |
| 011689 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:51am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595004.8 | 511274.6 | 56941 | 1.64041666667 | 11689 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011143 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:52am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595004.6 | 511274.2 | 56943 | 1.64041666667 | 11143 |
| 011232 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:53am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595004.6 | 511273.6 | 56945 | 1.64041666667 | 11232 |
| 011208 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:54am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595004.9 | 511274.0 | 56947 | 1.64041666667 | 11208 |
| 011292 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:55am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595005.3 | 511274.3 | 56949 | 1.64041666667 | 11292 |
| 011632 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:56am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595005.3 | 511273.5 | 56951 | 1.64041666667 | 11632 |
| 011575 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:57am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595005.8 | 511271.8 | 56953 | 1.64041666667 | 11575 |
| 011281 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:58am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595006.9 | 511269.2 | 56955 | 1.64041666667 | 11281 |
| 012383 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:59am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595007.7 | 511265.8 | 56957 | 1.64041666667 | 12383 |
| 012613 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:00am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595008.6 | 511262.4 | 56959 | 1.64041666667 | 12613 |
| 013005 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:01am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595009.5 | 511259.1 | 56961 | 1.64041666667 | 13005 |
| 012835 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:02am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595010.4 | 511256.3 | 56963 | 1.64041666667 | 12835 |
| 011937 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:03am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595011.9 | 511253.9 | 56965 | 1.64041666667 | 11937 |
| 012122 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:04am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595013.9 | 511250.4 | 56967 | 1.64041666667 | 12122 |
| 012458 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:05am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595015.1 | 511246.5 | 56969 | 1.64041666667 | 12458 |
| 011965 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:06am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595015.8 | 511242.9 | 56971 | 1.64041666667 | 11965 |
| 011448 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:07am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595016.5 | 511240.2 | 56973 | 1.64041666667 | 11448 |
| 011412 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:08am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595018.0 | 511237.9 | 56975 | 1.64041666667 | 11412 |
| 012336 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:09am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595019.7 | 511236.2 | 56977 | 1.64041666667 | 12336 |
| 012317 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:10am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595022.8 | 511233.5 | 56979 | 1.64041666667 | 12317 |
| 012207 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:11am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595025.5 | 511230.6 | 56981 | 1.64041666667 | 12207 |
| 011986 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:12am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595027.8 | 511227.0 | 56983 | 1.64041666667 | 11986 |
| 012135 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:13am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595029.1 | 511224.0 | 56985 | 1.64041666667 | 12135 |
| 012015 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:14am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595031.4 | 511219.7 | 56987 | 1.64041666667 | 12015 |
| 012421 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:15am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595034.9 | 511215.9 | 56989 | 1.64041666667 | 12421 |
| 013692 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:16am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595039.7 | 511213.2 | 56991 | 1.64041666667 | 13692 |
| 013799 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:17am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595043.2 | 511212.4 | 56993 | 1.64041666667 | 13799 |
| 013139 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:18am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595044.3 | 511212.9 | 56995 | 1.64041666667 | 13139 |
| 013158 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:19am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595043.5 | 511214.0 | 56997 | 1.64041666667 | 13158 |
| 013109 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:20am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595043.0 | 511216.3 | 56999 | 1.64041666667 | 13109 |
| 012991 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:21am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595043.1 | 511218.4 | 57001 | 1.64041666667 | 12991 |
| 014005 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:22am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.1 | 511220.0 | 57003 | 1.64041666667 | 14005 |
| 013653 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:23am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.8 | 511220.5 | 57005 | 1.64041666667 | 13653 |
| 013237 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:24am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.8 | 511220.6 | 57007 | 1.64041666667 | 13237 |
| 013738 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:25am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.7 | 511220.6 | 57009 | 1.64041666667 | 13738 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:26am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.7 | 511220.4 | 57011 | 1.64041666667 | 14538 |
| 013892 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:27am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595044.7 | 511220.2 | 57013 | 1.64041666667 | 13892 |
| 013199 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:28am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.8 | 511220.1 | 57015 | 1.64041666667 | 13199 |
| 013612 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:29am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.8 | 511220.1 | 57017 | 1.64041666667 | 13612 |
| 013304 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:30am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.5 | 511219.9 | 57019 | 1.64041666667 | 13304 |
| 013521 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:31am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.3 | 511220.0 | 57021 | 1.64041666667 | 13521 |
| 013515 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:32am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595044.5 | 511220.5 | 57023 | 1.64041666667 | 13515 |
| 013047 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:33am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.6 | 511220.6 | 57025 | 1.64041666667 | 13047 |
| 012986 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:34am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.4 | 57027 | 1.64041666667 | 12986 |
| 012622 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:35am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.3 | 57029 | 1.64041666667 | 12622 |
| 012590 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:36am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.6 | 57031 | 1.64041666667 | 12590 |
| 011904 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:37am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.6 | 57033 | 1.64041666667 | 11904 |
| 012321 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:38am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.6 | 57035 | 1.64041666667 | 12321 |
| 012788 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:39am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.6 | 57037 | 1.64041666667 | 12788 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013350 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:40am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.8 | 511220.5 | 57039 | 1.64041666667 | 13350 |
| 013030 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:41am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.8 | 511220.6 | 57041 | 1.64041666667 | 13030 |
| 013599 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:42am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.6 | 511220.8 | 57043 | 1.64041666667 | 13599 |
| 014017 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:43am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.6 | 511220.6 | 57045 | 1.64041666667 | 14017 |
| 013637 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:44am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.6 | 511220.6 | 57047 | 1.64041666667 | 13637 |
| 013446 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:45am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.6 | 511220.8 | 57049 | 1.64041666667 | 13446 |
| 013218 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:46am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.6 | 511220.8 | 57051 | 1.64041666667 | 13218 |
| 013533 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:47am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.6 | 511220.9 | 57053 | 1.64041666667 | 13533 |
| 014054 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:48am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.8 | 57055 | 1.64041666667 | 14054 |
| 014310 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:49am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.7 | 57057 | 1.64041666667 | 14310 |
| 013037 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:50am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.7 | 57059 | 1.64041666667 | 13037 |
| 012681 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:51am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.8 | 511220.6 | 57061 | 1.64041666667 | 12681 |
| 012690 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:52am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.7 | 511220.5 | 57063 | 1.64041666667 | 12690 |
| 012538 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:53am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595044.6 | 511220.4 | 57065 | 1.64041666667 | 12538 |
| 013083 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:54am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.6 | 57067 | 1.64041666667 | 13083 |
| 013014 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:55am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.7 | 511220.7 | 57069 | 1.64041666667 | 13014 |
| 012600 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:56am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.8 | 511220.7 | 57071 | 1.64041666667 | 12600 |
| 012157 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:57am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.8 | 511220.6 | 57073 | 1.64041666667 | 12157 |
| 012238 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:58am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.8 | 511220.6 | 57075 | 1.64041666667 | 12238 |
| 012479 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:59am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.7 | 511220.5 | 57077 | 1.64041666667 | 12479 |
| 012149 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:00am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595044.8 | 511220.5 | 57079 | 1.64041666667 | 12149 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:01am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595044.8 | 511220.5 | 57081 | 1.64041666667 | 12652 |
| 012425 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:02am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595044.8 | 511220.4 | 57083 | 1.64041666667 | 12425 |
| 012959 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:03am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595044.6 | 511220.4 | 57085 | 1.64041666667 | 12959 |
| 013282 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:04am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.5 | 511220.4 | 57087 | 1.64041666667 | 13282 |
| 012781 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:05am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.7 | 511220.4 | 57089 | 1.64041666667 | 12781 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:06am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.7 | 511220.4 | 57091 | 1.64041666667 | 12431 |
| 012828 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:07am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.7 | 511220.4 | 57093 | 1.64041666667 | 12828 |
| 013350 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:08am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.6 | 511220.3 | 57095 | 1.64041666667 | 13350 |
| 013742 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:09am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.3 | 511220.1 | 57097 | 1.64041666667 | 13742 |
| 013182 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:10am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.0 | 511220.1 | 57099 | 1.64041666667 | 13182 |
| 013452 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:11am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.2 | 511220.2 | 57101 | 1.64041666667 | 13452 |
| 013409 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:12am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.4 | 511220.3 | 57103 | 1.64041666667 | 13409 |
| 012920 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:13am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.5 | 511220.3 | 57105 | 1.64041666667 | 12920 |
| 013500 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:14am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.6 | 511220.4 | 57107 | 1.64041666667 | 13500 |
| 014201 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:15am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.6 | 511220.3 | 57109 | 1.64041666667 | 14201 |
| 013493 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:16am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595044.8 | 511219.0 | 57111 | 1.64041666667 | 13493 |
| 013005 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:17am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595045.6 | 511216.9 | 57113 | 1.64041666667 | 13005 |
| 013083 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:18am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595047.3 | 511214.7 | 57115 | 1.64041666667 | 13083 |
| 012864 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:19am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595048.5 | 511212.4 | 57117 | 1.64041666667 | 12864 |
| 013948 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:20am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595049.5 | 511209.9 | 57119 | 1.64041666667 | 13948 |
| 014033 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:21am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.4 | 511207.7 | 57121 | 1.64041666667 | 14033 |
| 012933 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:22am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.3 | 511205.1 | 57123 | 1.64041666667 | 12933 |
| 013897 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:23am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.3 | 511202.7 | 57125 | 1.64041666667 | 13897 |
| 012640 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:24am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.0 | 511200.4 | 57127 | 1.64041666667 | 12640 |
| 012225 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:25am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595049.7 | 511199.7 | 57129 | 1.64041666667 | 12225 |
| 012381 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:26am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.0 | 511199.5 | 57131 | 1.64041666667 | 12381 |
| 012334 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:27am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.5 | 511199.5 | 57133 | 1.64041666667 | 12334 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012923 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:28am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.7 | 511199.4 | 57135 | 1.64041666667 | 12923 |
| 012684 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:29am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.7 | 511199.4 | 57137 | 1.64041666667 | 12684 |
| 013150 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:30am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.7 | 511199.4 | 57139 | 1.64041666667 | 13150 |
| 013014 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:31am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.7 | 511199.4 | 57141 | 1.64041666667 | 13014 |
| 014078 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:32am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.7 | 511199.4 | 57143 | 1.64041666667 | 14078 |
| 014136 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:33am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.7 | 511199.5 | 57145 | 1.64041666667 | 14136 |
| 013764 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:34am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.8 | 511199.3 | 57147 | 1.64041666667 | 13764 |
| 014072 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:35am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.6 | 511199.4 | 57149 | 1.64041666667 | 14072 |
| 013848 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:36am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.5 | 511199.6 | 57151 | 1.64041666667 | 13848 |
| 013782 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:37am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.5 | 511199.6 | 57153 | 1.64041666667 | 13782 |
| 013924 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:38am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595050.5 | 511199.5 | 57155 | 1.64041666667 | 13924 |
| 013187 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:39am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595050.6 | 511199.5 | 57157 | 1.64041666667 | 13187 |
| 013733 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:40am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595050.7 | 511199.5 | 57159 | 1.64041666667 | 13733 |
| 013582 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:41am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595050.4 | 511199.3 | 57161 | 1.64041666667 | 13582 |
| 014277 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:42am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595049.7 | 511198.5 | 57163 | 1.64041666667 | 14277 |
| 013963 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:43am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595049.0 | 511197.4 | 57165 | 1.64041666667 | 13963 |
| 014709 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:44am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595048.5 | 511196.9 | 57167 | 1.64041666667 | 14709 |
| 014281 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:45am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595047.5 | 511198.3 | 57169 | 1.64041666667 | 14281 |
| 014168 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:46am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595046.0 | 511201.4 | 57171 | 1.64041666667 | 14168 |
| 012852 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:47am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595045.9 | 511204.4 | 57173 | 1.64041666667 | 12852 |
| 012989 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:48am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595046.4 | 511208.0 | 57175 | 1.64041666667 | 12989 |
| 014311 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:49am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595047.0 | 511211.2 | 57177 | 1.64041666667 | 14311 |
| 013247 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:50am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595048.3 | 511214.8 | 57179 | 1.64041666667 | 13247 |
| 014269 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:51am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595048.2 | 511217.3 | 57181 | 1.64041666667 | 14269 |
| 013891 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:52am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595046.7 | 511219.5 | 57183 | 1.64041666667 | 13891 |
| 013934 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:53am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595044.8 | 511220.5 | 57185 | 1.64041666667 | 13934 |
| 013740 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:54am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595041.9 | 511220.7 | 57187 | 1.64041666667 | 13740 |
| 012963 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:55am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595040.4 | 511220.8 | 57189 | 1.64041666667 | 12963 |
| 012932 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:56am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595039.7 | 511220.6 | 57191 | 1.64041666667 | 12932 |
| 013462 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:57am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595039.8 | 511220.7 | 57193 | 1.64041666667 | 13462 |
| 012102 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:58am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595039.8 | 511220.8 | 57195 | 1.64041666667 | 12102 |
| 012335 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:59am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595039.6 | 511220.9 | 57197 | 1.64041666667 | 12335 |
| 013440 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:00am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595038.4 | 511221.5 | 57199 | 1.64041666667 | 13440 |
| 013485 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:01am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595037.4 | 511222.5 | 57201 | 1.64041666667 | 13485 |
| 012835 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:02am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595036.8 | 511224.0 | 57203 | 1.64041666667 | 12835 |
| 012792 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:03am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595035.9 | 511224.5 | 57205 | 1.64041666667 | 12792 |
| 013150 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:04am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.8 | 511225.2 | 57207 | 1.64041666667 | 13150 |
| 012512 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:05am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.7 | 511225.1 | 57209 | 1.64041666667 | 12512 |
| 012370 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:06am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.7 | 511225.0 | 57211 | 1.64041666667 | 12370 |
| 012456 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:07am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.8 | 511225.0 | 57213 | 1.64041666667 | 12456 |
| 012601 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:08am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.8 | 511225.1 | 57215 | 1.64041666667 | 12601 |
| 012893 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:09am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.8 | 511225.1 | 57217 | 1.64041666667 | 12893 |
| 012322 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:10am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.8 | 511225.0 | 57219 | 1.64041666667 | 12322 |
| 012189 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:11am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.8 | 511225.0 | 57221 | 1.64041666667 | 12189 |
| 011686 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:12am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.7 | 511224.8 | 57223 | 1.64041666667 | 11686 |
| 011778 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:13am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595035.7 | 511224.8 | 57225 | 1.64041666667 | 11778 |
| 012723 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:14am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.8 | 511224.8 | 57227 | 1.64041666667 | 12723 |
| 013254 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:15am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.8 | 511224.5 | 57229 | 1.64041666667 | 13254 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013492 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:16am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595035.6 | 511224.7 | 57231 | 1.64041666667 | 13492 |
| 012659 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:17am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595034.9 | 511225.8 | 57233 | 1.64041666667 | 12659 |
| 011891 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:18am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595034.0 | 511228.1 | 57235 | 1.64041666667 | 11891 |
| 011556 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:19am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595033.5 | 511229.6 | 57237 | 1.64041666667 | 11556 |
| 012642 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:20am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595032.7 | 511229.7 | 57239 | 1.64041666667 | 12642 |
| 013201 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:21am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595032.6 | 511229.8 | 57241 | 1.64041666667 | 13201 |
| 013058 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:22am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.6 | 511229.9 | 57243 | 1.64041666667 | 13058 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:23am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.7 | 511230.1 | 57245 | 1.64041666667 | 12678 |
| 012073 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:24am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.9 | 511230.3 | 57247 | 1.64041666667 | 12073 |
| 012566 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:25am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.9 | 511230.2 | 57249 | 1.64041666667 | 12566 |
| 012663 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:26am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.8 | 511230.2 | 57251 | 1.64041666667 | 12663 |
| 013205 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:27am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.9 | 511230.1 | 57253 | 1.64041666667 | 13205 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:28am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.8 | 511230.1 | 57255 | 1.64041666667 | 12626 |
| 012277 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:29am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.9 | 511230.2 | 57257 | 1.64041666667 | 12277 |
| 013146 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:30am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595033.0 | 511230.3 | 57259 | 1.64041666667 | 13146 |
| 013904 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:31am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595033.0 | 511230.2 | 57261 | 1.64041666667 | 13904 |
| 013926 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:32am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595032.9 | 511230.2 | 57263 | 1.64041666667 | 13926 |
| 014456 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:33am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.9 | 511230.2 | 57265 | 1.64041666667 | 14456 |
| 013854 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:34am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.8 | 511230.1 | 57267 | 1.64041666667 | 13854 |
| 013560 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:35am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.8 | 511230.1 | 57269 | 1.64041666667 | 13560 |
| 012990 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:36am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.8 | 511230.2 | 57271 | 1.64041666667 | 12990 |
| 012174 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:37am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.7 | 511230.2 | 57273 | 1.64041666667 | 12174 |
| 012218 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:38am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595032.7 | 511230.2 | 57275 | 1.64041666667 | 12218 |
| 012182 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:39am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595032.6 | 511230.2 | 57277 | 1.64041666667 | 12182 |
| 011855 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:40am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595032.6 | 511230.1 | 57279 | 1.64041666667 | 11855 |
| 012946 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:41am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.7 | 511230.0 | 57281 | 1.64041666667 | 12946 |
| 012224 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:42am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595032.6 | 511230.3 | 57283 | 1.64041666667 | 12224 |
| 011849 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:43am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595032.1 | 511232.0 | 57285 | 1.64041666667 | 11849 |
| 012110 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:44am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595030.5 | 511235.1 | 57287 | 1.64041666667 | 12110 |
| 012856 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:45am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595028.8 | 511237.3 | 57289 | 1.64041666667 | 12856 |
| 012549 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:46am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595025.9 | 511238.9 | 57291 | 1.64041666667 | 12549 |
| 012339 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:47am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595024.3 | 511239.8 | 57293 | 1.64041666667 | 12339 |
| 012550 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:48am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595023.9 | 511240.2 | 57295 | 1.64041666667 | 12550 |
| 011679 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:49am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595023.9 | 511240.2 | 57297 | 1.64041666667 | 11679 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:50am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595023.9 | 511240.1 | 57299 | 1.64041666667 | 12255 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:51am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595023.9 | 511240.1 | 57301 | 1.64041666667 | 12743 |
| 012598 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:52am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595024.0 | 511240.0 | 57303 | 1.64041666667 | 12598 |
| 012914 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:53am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595024.0 | 511239.9 | 57305 | 1.64041666667 | 12914 |
| 013069 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:54am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595024.0 | 511239.8 | 57307 | 1.64041666667 | 13069 |
| 012886 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:55am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595024.0 | 511239.8 | 57309 | 1.64041666667 | 12886 |
| 013713 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:56am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595024.0 | 511239.5 | 57311 | 1.64041666667 | 13713 |
| 013518 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:57am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595023.8 | 511239.0 | 57313 | 1.64041666667 | 13518 |
| 012344 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:58am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595023.4 | 511238.5 | 57315 | 1.64041666667 | 12344 |
| 012141 | 0 | GeoXH 6000 | 08/19/2015 | 10:44:59am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595023.5 | 511238.4 | 57317 | 1.64041666667 | 12141 |
| 012071 | 0 | GeoXH 6000 | 08/19/2015 | 10:45:00am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595023.5 | 511238.4 | 57319 | 1.64041666667 | 12071 |
| 012354 | 0 | GeoXH 6000 | 08/19/2015 | 10:45:01am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595023.6 | 511238.4 | 57321 | 1.64041666667 | 12354 |
| 013124 | 0 | GeoXH 6000 | 08/19/2015 | 10:45:02am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595023.6 | 511238.4 | 57323 | 1.64041666667 | 13124 |
| 011335 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:57am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.6 | 511271.9 | 57325 | 1.64041666667 | 11335 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011168 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:58am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.6 | 511272.0 | 57327 | 1.64041666667 | 11168 |
| 012192 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:59am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.6 | 511272.0 | 57329 | 1.64041666667 | 12192 |
| 011635 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:00am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.5 | 511272.0 | 57331 | 1.64041666667 | 11635 |
| 010797 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:01am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.5 | 511272.0 | 57333 | 1.64041666667 | 10797 |
| 011136 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:02am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.6 | 511272.0 | 57335 | 1.64041666667 | 11136 |
| 010584 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:03am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.5 | 511271.9 | 57337 | 1.64041666667 | 10584 |
| 010671 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:04am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.4 | 511271.9 | 57339 | 1.64041666667 | 10671 |
| 010720 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:05am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.5 | 511271.9 | 57341 | 1.64041666667 | 10720 |
| 010807 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:06am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.4 | 511271.9 | 57343 | 1.64041666667 | 10807 |
| 010324 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:07am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.5 | 511272.0 | 57345 | 1.64041666667 | 10324 |
| 010599 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:08am | Sensor | 1797-S0041-G-636-DTE | 6823.3 | 1595002.6 | 511272.1 | 57347 | 1.64041666667 | 10599 |
| 010575 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:08am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.8 | 511272.0 | 57348 | 1.64041666667 | 10575 |
| 011685 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:10am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595002.9 | 511271.8 | 57351 | 1.64041666667 | 11685 |
| 011223 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:11am | Sensor | 1797-S0041-G-636-DTE | 6823.4 | 1595003.2 | 511271.6 | 57353 | 1.64041666667 | 11223 |
| 010835 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:12am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595004.3 | 511269.7 | 57355 | 1.64041666667 | 10835 |
| 011105 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:13am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595006.5 | 511268.6 | 57357 | 1.64041666667 | 11105 |
| 011594 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:14am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595009.5 | 511267.5 | 57359 | 1.64041666667 | 11594 |
| 013084 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:15am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595012.3 | 511266.1 | 57361 | 1.64041666667 | 13084 |
| 012992 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:16am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595015.6 | 511266.3 | 57363 | 1.64041666667 | 12992 |
| 013570 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:17am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595018.3 | 511265.6 | 57365 | 1.64041666667 | 13570 |
| 012801 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:18am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595021.5 | 511263.5 | 57367 | 1.64041666667 | 12801 |
| 012345 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:18am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595023.9 | 511262.4 | 57368 | 1.64041666667 | 12345 |
| 012142 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:20am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595024.7 | 511259.9 | 57371 | 1.64041666667 | 12142 |
| 012124 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:21am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595025.3 | 511257.5 | 57373 | 1.64041666667 | 12124 |
| 011897 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:22am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595025.7 | 511255.0 | 57375 | 1.64041666667 | 11897 |
| 012062 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:22am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595025.0 | 511253.5 | 57376 | 1.64041666667 | 12062 |
| 012447 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:24am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595026.4 | 511251.5 | 57379 | 1.64041666667 | 12447 |
| 012154 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:25am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595027.1 | 511249.6 | 57381 | 1.64041666667 | 12154 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:26am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595027.8 | 511246.8 | 57383 | 1.64041666667 | 12626 |
| 012547 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:27am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595027.4 | 511245.1 | 57385 | 1.64041666667 | 12547 |
| 012188 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:28am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595028.4 | 511243.8 | 57387 | 1.64041666667 | 12188 |
| 012878 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:29am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595028.8 | 511242.4 | 57389 | 1.64041666667 | 12878 |
| 012741 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:30am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595030.1 | 511240.6 | 57391 | 1.64041666667 | 12741 |
| 013024 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:30am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595030.4 | 511239.0 | 57392 | 1.64041666667 | 13024 |
| 012711 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:32am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595031.6 | 511236.5 | 57395 | 1.64041666667 | 12711 |
| 012295 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:33am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595031.8 | 511234.8 | 57397 | 1.64041666667 | 12295 |
| 012241 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:34am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595033.3 | 511233.6 | 57399 | 1.64041666667 | 12241 |
| 011708 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:35am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595033.2 | 511233.7 | 57401 | 1.64041666667 | 11708 |
| 010605 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:36am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595033.1 | 511233.9 | 57403 | 1.64041666667 | 10605 |
| 010720 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:37am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595033.1 | 511233.9 | 57405 | 1.64041666667 | 10720 |
| 011152 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:38am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595033.1 | 511233.9 | 57407 | 1.64041666667 | 11152 |
| 012296 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:38am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595033.1 | 511233.9 | 57408 | 1.64041666667 | 12296 |
| 012789 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:40am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595033.2 | 511233.8 | 57411 | 1.64041666667 | 12789 |
| 012113 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:40am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595033.3 | 511233.7 | 57412 | 1.64041666667 | 12113 |
| 012499 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:42am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595033.2 | 511232.3 | 57415 | 1.64041666667 | 12499 |
| 012288 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:43am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595033.6 | 511229.9 | 57417 | 1.64041666667 | 12288 |
| 012319 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:44am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595035.2 | 511226.2 | 57419 | 1.64041666667 | 12319 |
| 011977 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:44am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595036.4 | 511224.7 | 57420 | 1.64041666667 | 11977 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011972 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:46am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595037.7 | 511222.5 | 57423 | 1.64041666667 | 11972 |
| 011834 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:46am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595038.1 | 511222.2 | 57424 | 1.64041666667 | 11834 |
| 012259 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:48am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595038.1 | 511222.3 | 57427 | 1.64041666667 | 12259 |
| 011861 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:49am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595038.0 | 511222.3 | 57429 | 1.64041666667 | 11861 |
| 011914 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:50am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595037.9 | 511222.0 | 57431 | 1.64041666667 | 11914 |
| 011546 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:51am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595037.7 | 511221.4 | 57433 | 1.64041666667 | 11546 |
| 011850 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:52am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595037.7 | 511220.9 | 57435 | 1.64041666667 | 11850 |
| 012455 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:53am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595038.3 | 511220.6 | 57437 | 1.64041666667 | 12455 |
| 012443 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:54am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595038.2 | 511218.3 | 57439 | 1.64041666667 | 12443 |
| 012849 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:55am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595038.3 | 511215.7 | 57441 | 1.64041666667 | 12849 |
| 012740 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:56am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595039.1 | 511213.0 | 57443 | 1.64041666667 | 12740 |
| 013556 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:56am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595040.0 | 511210.5 | 57444 | 1.64041666667 | 13556 |
| 014420 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:58am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595041.9 | 511207.1 | 57447 | 1.64041666667 | 14420 |
| 014021 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:59am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595043.5 | 511204.2 | 57449 | 1.64041666667 | 14021 |
| 013677 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:00am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595044.8 | 511201.4 | 57451 | 1.64041666667 | 13677 |
| 013941 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:01am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595047.1 | 511199.4 | 57453 | 1.64041666667 | 13941 |
| 014111 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:02am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595048.5 | 511197.2 | 57455 | 1.64041666667 | 14111 |
| 014215 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:03am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595049.7 | 511195.6 | 57457 | 1.64041666667 | 14215 |
| 014011 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:04am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595051.6 | 511193.7 | 57459 | 1.64041666667 | 14011 |
| 014113 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:04am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595052.5 | 511192.7 | 57460 | 1.64041666667 | 14113 |
| 013714 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:06am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595053.2 | 511193.2 | 57463 | 1.64041666667 | 13714 |
| 013474 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:06am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595053.7 | 511194.9 | 57464 | 1.64041666667 | 13474 |
| 012769 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:08am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595052.6 | 511198.2 | 57467 | 1.64041666667 | 12769 |
| 012102 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:08am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595051.7 | 511200.8 | 57468 | 1.64041666667 | 12102 |
| 011465 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:10am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595050.4 | 511204.5 | 57471 | 1.64041666667 | 11465 |
| 011886 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:10am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595049.4 | 511207.3 | 57472 | 1.64041666667 | 11886 |
| 011966 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:12am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595047.6 | 511210.9 | 57475 | 1.64041666667 | 11966 |
| 012303 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:13am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595047.1 | 511213.9 | 57477 | 1.64041666667 | 12303 |
| 012470 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:14am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595044.7 | 511217.4 | 57479 | 1.64041666667 | 12470 |
| 012654 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:15am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595043.0 | 511219.9 | 57481 | 1.64041666667 | 12654 |
| 012555 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:16am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595041.9 | 511223.8 | 57483 | 1.64041666667 | 12555 |
| 013422 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:17am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595040.4 | 511226.6 | 57485 | 1.64041666667 | 13422 |
| 013010 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:18am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595039.3 | 511229.5 | 57487 | 1.64041666667 | 13010 |
| 013243 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:19am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595039.1 | 511232.7 | 57489 | 1.64041666667 | 13243 |
| 012692 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:20am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595037.5 | 511235.7 | 57491 | 1.64041666667 | 12692 |
| 013019 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:20am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595037.5 | 511238.3 | 57492 | 1.64041666667 | 13019 |
| 0135 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:22am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595036.1 | 511241.6 | 57495 | 1.64041666667 | 135 |
| 012962 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:22am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595034.3 | 511242.8 | 57496 | 1.64041666667 | 12962 |
| 012983 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:24am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595032.6 | 511245.4 | 57499 | 1.64041666667 | 12983 |
| 012485 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:25am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595030.6 | 511246.6 | 57501 | 1.64041666667 | 12485 |
| 012446 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:26am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595029.2 | 511249.4 | 57503 | 1.64041666667 | 12446 |
| 012468 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:27am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595027.8 | 511251.1 | 57505 | 1.64041666667 | 12468 |
| 011918 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:28am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595026.5 | 511253.9 | 57507 | 1.64041666667 | 11918 |
| 011976 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:28am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595025.9 | 511256.5 | 57508 | 1.64041666667 | 11976 |
| 012159 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:30am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595024.4 | 511259.0 | 57511 | 1.64041666667 | 12159 |
| 012359 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:30am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595024.6 | 511260.8 | 57512 | 1.64041666667 | 12359 |
| 012660 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:32am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595023.0 | 511262.0 | 57515 | 1.64041666667 | 12660 |
| 012776 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:32am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595022.1 | 511263.8 | 57516 | 1.64041666667 | 12776 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012916 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:33am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595019.3 | 511264.8 | 57518 | 1.64041666667 | 12916 |
| 013595 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:34am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595018.2 | 511267.1 | 57520 | 1.64041666667 | 13595 |
| 014037 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:36am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595017.3 | 511270.8 | 57523 | 1.64041666667 | 14037 |
| 013483 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:36am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595015.9 | 511272.3 | 57524 | 1.64041666667 | 13483 |
| 012714 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:37am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595014.9 | 511275.1 | 57526 | 1.64041666667 | 12714 |
| 011944 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:38am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595012.5 | 511277.3 | 57528 | 1.64041666667 | 11944 |
| 011391 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:40am | Sensor | 1797-S0041-G-636-DTE | 6823.5 | 1595010.9 | 511280.9 | 57531 | 1.64041666667 | 11391 |
| 010877 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:40am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595011.0 | 511283.4 | 57532 | 1.64041666667 | 10877 |
| 010768 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:42am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595010.3 | 511285.6 | 57535 | 1.64041666667 | 10768 |
| 011082 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:42am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595011.4 | 511287.5 | 57536 | 1.64041666667 | 11082 |
| 011131 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:44am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595014.4 | 511287.7 | 57539 | 1.64041666667 | 11131 |
| 011301 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:44am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595016.3 | 511289.0 | 57540 | 1.64041666667 | 11301 |
| 012364 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:45am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595017.1 | 511289.0 | 57542 | 1.64041666667 | 12364 |
| 011852 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:46am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595017.4 | 511287.1 | 57544 | 1.64041666667 | 11852 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:48am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595019.2 | 511285.1 | 57547 | 1.64041666667 | 12442 |
| 013253 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:48am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595020.2 | 511282.2 | 57548 | 1.64041666667 | 13253 |
| 013177 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:50am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595022.0 | 511279.0 | 57551 | 1.64041666667 | 13177 |
| 013945 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:50am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595023.8 | 511277.1 | 57552 | 1.64041666667 | 13945 |
| 013694 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:52am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595024.7 | 511273.7 | 57555 | 1.64041666667 | 13694 |
| 013567 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:53am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595026.5 | 511271.4 | 57557 | 1.64041666667 | 13567 |
| 013331 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:54am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595027.6 | 511268.5 | 57559 | 1.64041666667 | 13331 |
| 013124 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:55am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595028.6 | 511265.8 | 57561 | 1.64041666667 | 13124 |
| 013337 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:56am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595030.6 | 511263.4 | 57563 | 1.64041666667 | 13337 |
| 013104 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:56am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595030.3 | 511260.9 | 57564 | 1.64041666667 | 13104 |
| 013086 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:58am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595032.0 | 511258.1 | 57567 | 1.64041666667 | 13086 |
| 013908 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:58am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595032.6 | 511256.4 | 57568 | 1.64041666667 | 13908 |
| 013598 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:59am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595034.4 | 511255.2 | 57570 | 1.64041666667 | 13598 |
| 013386 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:00am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595035.7 | 511252.4 | 57572 | 1.64041666667 | 13386 |
| 013440 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:02am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595036.0 | 511248.8 | 57575 | 1.64041666667 | 13440 |
| 013732 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:02am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595036.8 | 511246.7 | 57576 | 1.64041666667 | 13732 |
| 013702 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:04am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595037.3 | 511243.8 | 57579 | 1.64041666667 | 13702 |
| 013467 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:04am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595038.3 | 511242.3 | 57580 | 1.64041666667 | 13467 |
| 013687 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:06am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595038.7 | 511238.6 | 57583 | 1.64041666667 | 13687 |
| 013684 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:07am | Sensor | 1797-S0041-G-636-DTE | 6823.6 | 1595039.8 | 511236.3 | 57585 | 1.64041666667 | 13684 |
| 013547 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:08am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595041.1 | 511233.5 | 57587 | 1.64041666667 | 13547 |
| 013700 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:08am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595041.2 | 511230.9 | 57588 | 1.64041666667 | 13700 |
| 013432 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:10am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595043.2 | 511228.4 | 57591 | 1.64041666667 | 13432 |
| 013488 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:10am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595043.9 | 511225.7 | 57592 | 1.64041666667 | 13488 |
| 013391 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:12am | Sensor | 1797-S0041-G-636-DTE | 6823.8 | 1595045.8 | 511223.0 | 57595 | 1.64041666667 | 13391 |
| 013420 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:12am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595046.8 | 511220.3 | 57596 | 1.64041666667 | 13420 |
| 013789 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:14am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595047.9 | 511217.1 | 57599 | 1.64041666667 | 13789 |
| 013636 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:14am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595049.2 | 511214.9 | 57600 | 1.64041666667 | 13636 |
| 013400 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:16am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595049.7 | 511211.9 | 57603 | 1.64041666667 | 13400 |
| 012847 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:16am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595051.6 | 511210.2 | 57604 | 1.64041666667 | 12847 |
| 012881 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:18am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595051.4 | 511207.2 | 57607 | 1.64041666667 | 12881 |
| 012406 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:19am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595052.1 | 511205.4 | 57609 | 1.64041666667 | 12406 |
| 012528 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:20am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595051.5 | 511203.0 | 57611 | 1.64041666667 | 12528 |
| 012769 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:20am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595051.6 | 511201.2 | 57612 | 1.64041666667 | 12769 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012988 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:22am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595052.7 | 511198.5 | 57615 | 1.64041666667 | 12988 |
| 012368 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:22am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595053.3 | 511196.3 | 57616 | 1.64041666667 | 12368 |
| 012244 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:24am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595055.6 | 511194.0 | 57619 | 1.64041666667 | 12244 |
| 013300 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:24am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595056.1 | 511192.0 | 57620 | 1.64041666667 | 13300 |
| 013211 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:26am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595057.8 | 511191.8 | 57623 | 1.64041666667 | 13211 |
| 013619 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:26am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595059.4 | 511191.6 | 57624 | 1.64041666667 | 13619 |
| 013330 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:27am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595060.5 | 511192.4 | 57626 | 1.64041666667 | 13330 |
| 013393 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:28am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595060.4 | 511192.1 | 57628 | 1.64041666667 | 13393 |
| 012971 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:30am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595060.2 | 511191.9 | 57631 | 1.64041666667 | 12971 |
| 012509 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:30am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595060.8 | 511192.3 | 57632 | 1.64041666667 | 12509 |
| 013178 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:31am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595061.1 | 511192.4 | 57634 | 1.64041666667 | 13178 |
| 012880 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:32am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595060.8 | 511194.1 | 57636 | 1.64041666667 | 12880 |
| 013380 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:33am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595063.0 | 511195.0 | 57638 | 1.64041666667 | 13380 |
| 013256 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:34am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595064.5 | 511196.1 | 57640 | 1.64041666667 | 13256 |
| 012991 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:35am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595065.7 | 511198.3 | 57642 | 1.64041666667 | 12991 |
| 013780 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:36am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595064.4 | 511200.3 | 57644 | 1.64041666667 | 13780 |
| 013421 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:37am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595063.5 | 511202.9 | 57646 | 1.64041666667 | 13421 |
| 014044 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:38am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595062.1 | 511204.1 | 57648 | 1.64041666667 | 14044 |
| 013495 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:39am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595062.0 | 511205.4 | 57650 | 1.64041666667 | 13495 |
| 013351 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:40am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595061.3 | 511205.2 | 57652 | 1.64041666667 | 13351 |
| 013090 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:41am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595061.0 | 511205.2 | 57654 | 1.64041666667 | 13090 |
| 014398 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:42am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595060.1 | 511207.1 | 57656 | 1.64041666667 | 14398 |
| 013371 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:43am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595057.7 | 511209.4 | 57658 | 1.64041666667 | 13371 |
| 013101 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:44am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595056.5 | 511211.8 | 57660 | 1.64041666667 | 13101 |
| 012919 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:45am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595056.6 | 511213.8 | 57662 | 1.64041666667 | 12919 |
| 013117 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:46am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595055.5 | 511215.6 | 57664 | 1.64041666667 | 13117 |
| 013303 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:48am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595056.1 | 511218.4 | 57667 | 1.64041666667 | 13303 |
| 013648 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:48am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595055.4 | 511220.7 | 57668 | 1.64041666667 | 13648 |
| 014044 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:49am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595055.4 | 511223.8 | 57670 | 1.64041666667 | 14044 |
| 014372 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:50am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595053.7 | 511225.8 | 57672 | 1.64041666667 | 14372 |
| 014632 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:52am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595052.6 | 511228.2 | 57675 | 1.64041666667 | 14632 |
| 013735 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:52am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595051.9 | 511230.3 | 57676 | 1.64041666667 | 13735 |
| 014536 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:54am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595050.6 | 511232.4 | 57679 | 1.64041666667 | 14536 |
| 013906 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:54am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595049.7 | 511234.2 | 57680 | 1.64041666667 | 13906 |
| 013335 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:56am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595047.0 | 511235.1 | 57683 | 1.64041666667 | 13335 |
| 013508 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:56am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595045.7 | 511236.8 | 57684 | 1.64041666667 | 13508 |
| 013531 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:58am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595043.3 | 511237.9 | 57687 | 1.64041666667 | 13531 |
| 012508 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:58am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595042.3 | 511239.9 | 57688 | 1.64041666667 | 12508 |
| 013786 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:59am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595040.6 | 511241.0 | 57690 | 1.64041666667 | 13786 |
| 013972 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:00am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595040.5 | 511241.1 | 57692 | 1.64041666667 | 13972 |
| 013642 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:01am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595040.5 | 511242.8 | 57694 | 1.64041666667 | 13642 |
| 013718 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:02am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595040.1 | 511245.1 | 57696 | 1.64041666667 | 13718 |
| 013896 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:04am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595039.8 | 511248.7 | 57699 | 1.64041666667 | 13896 |
| 013959 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:04am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595039.8 | 511251.6 | 57700 | 1.64041666667 | 13959 |
| 014407 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:05am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595038.7 | 511254.6 | 57702 | 1.64041666667 | 14407 |
| 014126 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:06am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595038.1 | 511257.4 | 57704 | 1.64041666667 | 14126 |
| 014111 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:08am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595037.0 | 511261.2 | 57707 | 1.64041666667 | 14111 |
| 012482 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:08am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595036.4 | 511263.5 | 57708 | 1.64041666667 | 12482 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013336 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:09am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595036.7 | 511266.7 | 57710 | 1.64041666667 | 13336 |
| 012114 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:10am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595035.3 | 511269.6 | 57712 | 1.64041666667 | 12114 |
| 012529 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:11am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595034.1 | 511272.6 | 57714 | 1.64041666667 | 12529 |
| 013475 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:12am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595033.9 | 511275.7 | 57716 | 1.64041666667 | 13475 |
| 014352 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:13am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595033.2 | 511278.5 | 57718 | 1.64041666667 | 14352 |
| 014065 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:14am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595033.5 | 511281.1 | 57720 | 1.64041666667 | 14065 |
| 015074 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:15am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595032.2 | 511284.2 | 57722 | 1.64041666667 | 15074 |
| 014239 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:16am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595030.6 | 511286.8 | 57724 | 1.64041666667 | 14239 |
| 013747 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:17am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595030.6 | 511289.5 | 57726 | 1.64041666667 | 13747 |
| 013215 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:18am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595030.3 | 511291.3 | 57728 | 1.64041666667 | 13215 |
| 012728 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:20am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595030.3 | 511291.5 | 57731 | 1.64041666667 | 12728 |
| 013377 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:20am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595030.4 | 511291.6 | 57732 | 1.64041666667 | 13377 |
| 012324 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:21am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595030.4 | 511291.9 | 57734 | 1.64041666667 | 12324 |
| 012295 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:22am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595031.2 | 511292.2 | 57736 | 1.64041666667 | 12295 |
| 011896 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:23am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595032.2 | 511294.0 | 57738 | 1.64041666667 | 11896 |
| 012189 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:24am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595033.5 | 511294.8 | 57740 | 1.64041666667 | 12189 |
| 012271 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:26am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595035.8 | 511296.0 | 57743 | 1.64041666667 | 12271 |
| 013592 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:26am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595037.9 | 511296.5 | 57744 | 1.64041666667 | 13592 |
| 013683 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:28am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595040.8 | 511297.2 | 57747 | 1.64041666667 | 13683 |
| 013412 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:28am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595043.4 | 511296.7 | 57748 | 1.64041666667 | 13412 |
| 014226 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:30am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595046.6 | 511297.2 | 57751 | 1.64041666667 | 14226 |
| 015600 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:30am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595047.6 | 511296.2 | 57752 | 1.64041666667 | 15600 |
| 015240 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:32am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595048.1 | 511296.4 | 57755 | 1.64041666667 | 15240 |
| 014730 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:32am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595047.9 | 511296.9 | 57756 | 1.64041666667 | 14730 |
| 015440 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:34am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595049.0 | 511299.4 | 57759 | 1.64041666667 | 15440 |
| 015142 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:34am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595048.6 | 511301.3 | 57760 | 1.64041666667 | 15142 |
| 015080 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:36am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595048.2 | 511304.4 | 57763 | 1.64041666667 | 15080 |
| 014655 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:36am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595047.0 | 511306.4 | 57764 | 1.64041666667 | 14655 |
| 014228 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:38am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595047.8 | 511307.9 | 57767 | 1.64041666667 | 14228 |
| 013471 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:38am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595048.4 | 511308.8 | 57768 | 1.64041666667 | 13471 |
| 013060 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:40am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595048.7 | 511308.4 | 57771 | 1.64041666667 | 13060 |
| 013631 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:40am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595048.6 | 511308.0 | 57772 | 1.64041666667 | 13631 |
| 014357 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:42am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595047.4 | 511306.8 | 57775 | 1.64041666667 | 14357 |
| 014008 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:42am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595045.8 | 511305.5 | 57776 | 1.64041666667 | 14008 |
| 013954 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:44am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595043.6 | 511303.1 | 57779 | 1.64041666667 | 13954 |
| 013444 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:44am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595041.1 | 511302.0 | 57780 | 1.64041666667 | 13444 |
| 012910 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:45am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595037.9 | 511299.5 | 57782 | 1.64041666667 | 12910 |
| 012714 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:46am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595036.3 | 511297.1 | 57784 | 1.64041666667 | 12714 |
| 013339 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:48am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595035.8 | 511293.2 | 57787 | 1.64041666667 | 13339 |
| 013938 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:48am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595035.7 | 511290.5 | 57788 | 1.64041666667 | 13938 |
| 013578 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:49am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595036.8 | 511287.7 | 57790 | 1.64041666667 | 13578 |
| 014695 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:50am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595037.5 | 511285.0 | 57792 | 1.64041666667 | 14695 |
| 013981 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:51am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595038.8 | 511282.2 | 57794 | 1.64041666667 | 13981 |
| 012896 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:52am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595040.5 | 511280.1 | 57796 | 1.64041666667 | 12896 |
| 012197 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:54am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595041.8 | 511276.8 | 57799 | 1.64041666667 | 12197 |
| 011113 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:54am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595043.9 | 511274.1 | 57800 | 1.64041666667 | 11113 |
| 012048 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:55am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595045.7 | 511272.1 | 57802 | 1.64041666667 | 12048 |
| 011382 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:56am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595047.1 | 511270.3 | 57804 | 1.64041666667 | 11382 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012410 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:58am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595049.2 | 511268.3 | 57807 | 1.64041666667 | 12410 |
| 012238 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:58am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595050.2 | 511266.5 | 57808 | 1.64041666667 | 12238 |
| 011901 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:59am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595052.2 | 511265.2 | 57810 | 1.64041666667 | 11901 |
| 012597 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:00am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595052.2 | 511264.9 | 57812 | 1.64041666667 | 12597 |
| 012606 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:01am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595052.1 | 511264.9 | 57814 | 1.64041666667 | 12606 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:02am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595052.1 | 511264.9 | 57816 | 1.64041666667 | 12431 |
| 011875 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:04am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595052.2 | 511264.9 | 57819 | 1.64041666667 | 11875 |
| 012177 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:04am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595052.4 | 511264.8 | 57820 | 1.64041666667 | 12177 |
| 012287 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:06am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595051.3 | 511263.0 | 57823 | 1.64041666667 | 12287 |
| 012214 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:06am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.9 | 511260.7 | 57824 | 1.64041666667 | 12214 |
| 012637 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:07am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595050.5 | 511258.3 | 57826 | 1.64041666667 | 12637 |
| 012583 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:08am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595050.1 | 511256.2 | 57828 | 1.64041666667 | 12583 |
| 012981 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:09am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595051.9 | 511254.5 | 57830 | 1.64041666667 | 12981 |
| 013144 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:10am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595052.5 | 511252.3 | 57832 | 1.64041666667 | 13144 |
| 013033 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:11am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595054.5 | 511250.9 | 57834 | 1.64041666667 | 13033 |
| 013533 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:12am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595057.3 | 511249.7 | 57836 | 1.64041666667 | 13533 |
| 012480 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:13am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595059.1 | 511247.0 | 57838 | 1.64041666667 | 12480 |
| 011677 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:14am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595059.8 | 511244.6 | 57840 | 1.64041666667 | 11677 |
| 012681 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:15am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595061.1 | 511242.1 | 57842 | 1.64041666667 | 12681 |
| 012353 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:16am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595060.8 | 511241.3 | 57844 | 1.64041666667 | 12353 |
| 012236 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:17am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595059.7 | 511240.5 | 57846 | 1.64041666667 | 12236 |
| 012875 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:18am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595058.2 | 511238.4 | 57848 | 1.64041666667 | 12875 |
| 013174 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:19am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595057.8 | 511236.4 | 57850 | 1.64041666667 | 13174 |
| 013598 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:20am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595057.0 | 511234.1 | 57852 | 1.64041666667 | 13598 |
| 013739 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:22am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595057.8 | 511231.0 | 57855 | 1.64041666667 | 13739 |
| 014065 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:22am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595057.6 | 511228.8 | 57856 | 1.64041666667 | 14065 |
| 013379 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:23am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595059.0 | 511226.2 | 57858 | 1.64041666667 | 13379 |
| 013076 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:24am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595059.8 | 511224.1 | 57860 | 1.64041666667 | 13076 |
| 012957 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:25am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595061.3 | 511221.1 | 57862 | 1.64041666667 | 12957 |
| 013468 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:26am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595062.7 | 511218.6 | 57864 | 1.64041666667 | 13468 |
| 012901 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:27am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595061.6 | 511215.9 | 57866 | 1.64041666667 | 12901 |
| 012311 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:28am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595061.5 | 511213.2 | 57868 | 1.64041666667 | 12311 |
| 012123 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:29am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595061.5 | 511210.1 | 57870 | 1.64041666667 | 12123 |
| 012339 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:30am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595062.4 | 511208.0 | 57872 | 1.64041666667 | 12339 |
| 013113 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:32am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595063.6 | 511205.2 | 57875 | 1.64041666667 | 13113 |
| 012543 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:32am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595064.1 | 511203.3 | 57876 | 1.64041666667 | 12543 |
| 012425 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:33am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595066.0 | 511200.8 | 57878 | 1.64041666667 | 12425 |
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:34am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595066.0 | 511198.1 | 57880 | 1.64041666667 | 12562 |
| 012428 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:36am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595067.0 | 511195.0 | 57883 | 1.64041666667 | 12428 |
| 012128 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:36am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595066.4 | 511193.6 | 57884 | 1.64041666667 | 12128 |
| 012124 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:37am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595065.9 | 511192.8 | 57886 | 1.64041666667 | 12124 |
| 012542 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:38am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595066.5 | 511192.2 | 57888 | 1.64041666667 | 12542 |
| 013287 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:39am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595068.7 | 511191.5 | 57890 | 1.64041666667 | 13287 |
| 013106 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:40am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595071.3 | 511192.4 | 57892 | 1.64041666667 | 13106 |
| 013132 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:41am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595073.1 | 511192.2 | 57894 | 1.64041666667 | 13132 |
| 013447 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:42am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595073.0 | 511192.4 | 57896 | 1.64041666667 | 13447 |
| 014066 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:43am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595072.9 | 511193.2 | 57898 | 1.64041666667 | 14066 |
| 014587 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:44am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595073.1 | 511195.1 | 57900 | 1.64041666667 | 14587 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013950 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:45am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595073.4 | 511198.5 | 57902 | 1.64041666667 | 13950 |
| 014184 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:46am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595072.4 | 511201.1 | 57904 | 1.64041666667 | 14184 |
| 013521 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:47am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595072.5 | 511204.7 | 57906 | 1.64041666667 | 13521 |
| 012848 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:48am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595071.9 | 511207.6 | 57908 | 1.64041666667 | 12848 |
| 012762 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:49am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595070.5 | 511210.7 | 57910 | 1.64041666667 | 12762 |
| 012211 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:50am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595070.1 | 511213.3 | 57912 | 1.64041666667 | 12211 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:51am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595067.7 | 511215.9 | 57914 | 1.64041666667 | 12163 |
| 012527 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:52am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595066.8 | 511218.2 | 57916 | 1.64041666667 | 12527 |
| 013241 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:53am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595065.0 | 511220.8 | 57918 | 1.64041666667 | 13241 |
| 013260 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:54am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595063.2 | 511222.9 | 57920 | 1.64041666667 | 13260 |
| 014149 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:55am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595063.2 | 511225.6 | 57922 | 1.64041666667 | 14149 |
| 013411 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:56am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595061.9 | 511227.7 | 57924 | 1.64041666667 | 13411 |
| 012869 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:57am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595060.1 | 511230.6 | 57926 | 1.64041666667 | 12869 |
| 013493 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:58am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595058.8 | 511232.5 | 57928 | 1.64041666667 | 13493 |
| 013080 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:59am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595057.0 | 511235.7 | 57930 | 1.64041666667 | 13080 |
| 012645 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:00am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595057.6 | 511237.9 | 57932 | 1.64041666667 | 12645 |
| 012723 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:02am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595058.2 | 511241.7 | 57935 | 1.64041666667 | 12723 |
| 012609 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:02am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595058.9 | 511243.8 | 57936 | 1.64041666667 | 12609 |
| 012402 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:03am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595058.9 | 511246.4 | 57938 | 1.64041666667 | 12402 |
| 011926 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:04am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595058.8 | 511248.7 | 57940 | 1.64041666667 | 11926 |
| 012423 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:05am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595059.9 | 511250.7 | 57942 | 1.64041666667 | 12423 |
| 012680 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:06am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595060.0 | 511251.1 | 57944 | 1.64041666667 | 12680 |
| 012503 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:07am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595058.5 | 511252.9 | 57946 | 1.64041666667 | 12503 |
| 012995 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:08am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595058.0 | 511255.8 | 57948 | 1.64041666667 | 12995 |
| 011914 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:09am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595055.4 | 511257.7 | 57950 | 1.64041666667 | 11914 |
| 011749 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:10am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595054.8 | 511259.9 | 57952 | 1.64041666667 | 11749 |
| 012309 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:11am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595053.7 | 511261.7 | 57954 | 1.64041666667 | 12309 |
| 012976 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:12am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595053.7 | 511262.4 | 57956 | 1.64041666667 | 12976 |
| 012264 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:13am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595053.0 | 511264.3 | 57958 | 1.64041666667 | 12264 |
| 011781 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:14am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595053.1 | 511266.5 | 57960 | 1.64041666667 | 11781 |
| 011734 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:16am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595052.1 | 511270.1 | 57963 | 1.64041666667 | 11734 |
| 012443 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:16am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595051.9 | 511273.1 | 57964 | 1.64041666667 | 12443 |
| 012091 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:18am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595052.3 | 511276.6 | 57967 | 1.64041666667 | 12091 |
| 012434 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:18am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595051.5 | 511279.1 | 57968 | 1.64041666667 | 12434 |
| 012034 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:20am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595051.7 | 511282.5 | 57971 | 1.64041666667 | 12034 |
| 012386 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:20am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595051.2 | 511284.7 | 57972 | 1.64041666667 | 12386 |
| 011835 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:21am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595050.8 | 511287.9 | 57974 | 1.64041666667 | 11835 |
| 012319 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:22am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595050.8 | 511290.8 | 57976 | 1.64041666667 | 12319 |
| 012915 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:24am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595049.7 | 511294.2 | 57979 | 1.64041666667 | 12915 |
| 013639 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:24am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595049.8 | 511296.6 | 57980 | 1.64041666667 | 13639 |
| 014399 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:25am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595048.7 | 511300.1 | 57982 | 1.64041666667 | 14399 |
| 014137 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:26am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595048.3 | 511302.9 | 57984 | 1.64041666667 | 14137 |
| 014589 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:27am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595049.6 | 511305.0 | 57986 | 1.64041666667 | 14589 |
| 014341 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:28am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595051.7 | 511305.7 | 57988 | 1.64041666667 | 14341 |
| 013579 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:29am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595053.9 | 511303.8 | 57990 | 1.64041666667 | 13579 |
| 012933 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:30am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595056.1 | 511302.1 | 57992 | 1.64041666667 | 12933 |
| 013207 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:31am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595057.3 | 511299.7 | 57994 | 1.64041666667 | 13207 |
| 012296 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:32am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595060.8 | 511297.8 | 57996 | 1.64041666667 | 12296 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013179 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:33am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595061.4 | 511295.3 | 57998 | 1.64041666667 | 13179 |
| 012686 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:34am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595062.6 | 511292.2 | 58000 | 1.64041666667 | 12686 |
| 012446 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:35am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.8 | 511288.8 | 58002 | 1.64041666667 | 12446 |
| 012648 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:36am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.1 | 511286.0 | 58004 | 1.64041666667 | 12648 |
| 012079 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:37am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595063.5 | 511282.7 | 58006 | 1.64041666667 | 12079 |
| 012675 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:38am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595063.5 | 511280.0 | 58008 | 1.64041666667 | 12675 |
| 012222 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:40am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595063.4 | 511276.7 | 58011 | 1.64041666667 | 12222 |
| 012087 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:40am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595064.6 | 511274.5 | 58012 | 1.64041666667 | 12087 |
| 012754 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:41am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595065.9 | 511271.6 | 58014 | 1.64041666667 | 12754 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:42am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595066.8 | 511269.4 | 58016 | 1.64041666667 | 12626 |
| 012622 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:43am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595069.1 | 511267.2 | 58018 | 1.64041666667 | 12622 |
| 012642 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:44am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595070.0 | 511265.0 | 58020 | 1.64041666667 | 12642 |
| 012616 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:45am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595071.3 | 511262.6 | 58022 | 1.64041666667 | 12616 |
| 012204 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:46am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595072.0 | 511260.9 | 58024 | 1.64041666667 | 12204 |
| 012025 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:47am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595074.2 | 511259.1 | 58026 | 1.64041666667 | 12025 |
| 012411 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:48am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595076.4 | 511257.9 | 58028 | 1.64041666667 | 12411 |
| 013289 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:49am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595077.2 | 511257.2 | 58030 | 1.64041666667 | 13289 |
| 012800 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:50am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595077.1 | 511257.1 | 58032 | 1.64041666667 | 12800 |
| 012727 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:51am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595077.3 | 511257.0 | 58034 | 1.64041666667 | 12727 |
| 012656 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:52am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595077.2 | 511257.0 | 58036 | 1.64041666667 | 12656 |
| 012797 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:53am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595077.1 | 511256.4 | 58038 | 1.64041666667 | 12797 |
| 012545 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:54am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595076.3 | 511255.0 | 58040 | 1.64041666667 | 12545 |
| 011662 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:55am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595075.0 | 511252.2 | 58042 | 1.64041666667 | 11662 |
| 011795 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:56am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595075.1 | 511249.7 | 58044 | 1.64041666667 | 11795 |
| 012237 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:57am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595074.2 | 511248.0 | 58046 | 1.64041666667 | 12237 |
| 012208 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:58am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595074.3 | 511247.7 | 58048 | 1.64041666667 | 12208 |
| 012349 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:59am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595074.8 | 511248.6 | 58050 | 1.64041666667 | 12349 |
| 011821 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:00am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595076.4 | 511248.5 | 58052 | 1.64041666667 | 11821 |
| 012319 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:01am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595077.5 | 511249.1 | 58054 | 1.64041666667 | 12319 |
| 012832 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:02am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595077.5 | 511249.2 | 58056 | 1.64041666667 | 12832 |
| 012708 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:03am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595077.3 | 511249.1 | 58058 | 1.64041666667 | 12708 |
| 012801 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:04am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595077.0 | 511249.1 | 58060 | 1.64041666667 | 12801 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:05am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595076.5 | 511249.3 | 58062 | 1.64041666667 | 12405 |
| 012243 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:06am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595074.3 | 511249.3 | 58064 | 1.64041666667 | 12243 |
| 011776 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:08am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.6 | 511249.1 | 58067 | 1.64041666667 | 11776 |
| 012451 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:08am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595073.7 | 511249.3 | 58068 | 1.64041666667 | 12451 |
| 012509 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:09am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595073.8 | 511249.3 | 58070 | 1.64041666667 | 12509 |
| 012616 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:10am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.9 | 511249.3 | 58072 | 1.64041666667 | 12616 |
| 012526 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:11am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.8 | 511249.2 | 58074 | 1.64041666667 | 12526 |
| 012783 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:12am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.8 | 511249.2 | 58076 | 1.64041666667 | 12783 |
| 012530 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:13am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.7 | 511249.2 | 58078 | 1.64041666667 | 12530 |
| 013071 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:14am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.7 | 511249.3 | 58080 | 1.64041666667 | 13071 |
| 012872 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:15am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595073.7 | 511249.3 | 58082 | 1.64041666667 | 12872 |
| 012986 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:16am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595073.7 | 511249.3 | 58084 | 1.64041666667 | 12986 |
| 012794 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:17am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595073.6 | 511249.3 | 58086 | 1.64041666667 | 12794 |
| 012199 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:18am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595073.6 | 511249.4 | 58088 | 1.64041666667 | 12199 |
| 012367 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:19am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595074.0 | 511249.5 | 58090 | 1.64041666667 | 12367 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:20am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595074.2 | 511249.6 | 58092 | 1.64041666667 | 12431 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012550 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:21am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595074.0 | 511249.6 | 58094 | 1.64041666667 | 12550 |
| 012774 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:22am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.9 | 511249.6 | 58096 | 1.64041666667 | 12774 |
| 012263 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:23am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.6 | 511249.4 | 58098 | 1.64041666667 | 12263 |
| 013160 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:24am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595073.3 | 511249.6 | 58100 | 1.64041666667 | 13160 |
| 012705 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:25am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595074.1 | 511251.1 | 58102 | 1.64041666667 | 12705 |
| 012066 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:26am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595074.4 | 511253.7 | 58104 | 1.64041666667 | 12066 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:27am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595076.8 | 511255.8 | 58106 | 1.64041666667 | 12247 |
| 012101 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:28am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595078.0 | 511257.7 | 58108 | 1.64041666667 | 12101 |
| 012522 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:29am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595078.5 | 511258.0 | 58110 | 1.64041666667 | 12522 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:30am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595078.4 | 511258.1 | 58112 | 1.64041666667 | 12803 |
| 013457 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:31am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595078.5 | 511258.1 | 58114 | 1.64041666667 | 13457 |
| 013164 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:32am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595078.5 | 511258.0 | 58116 | 1.64041666667 | 13164 |
| 013180 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:33am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595078.6 | 511258.1 | 58118 | 1.64041666667 | 13180 |
| 012236 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:34am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595078.6 | 511258.1 | 58120 | 1.64041666667 | 12236 |
| 012658 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:35am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595078.6 | 511258.0 | 58122 | 1.64041666667 | 12658 |
| 012797 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:36am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595078.6 | 511258.0 | 58124 | 1.64041666667 | 12797 |
| 012156 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:37am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595078.7 | 511258.1 | 58126 | 1.64041666667 | 12156 |
| 011825 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:38am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595079.2 | 511257.9 | 58128 | 1.64041666667 | 11825 |
| 011466 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:39am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595080.6 | 511256.5 | 58130 | 1.64041666667 | 11466 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:40am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595082.9 | 511256.9 | 58132 | 1.64041666667 | 12255 |
| 013193 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:41am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595086.2 | 511257.0 | 58134 | 1.64041666667 | 13193 |
| 013623 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:42am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595088.1 | 511256.5 | 58136 | 1.64041666667 | 13623 |
| 013318 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:43am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595090.4 | 511254.6 | 58138 | 1.64041666667 | 13318 |
| 013566 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:44am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595090.8 | 511252.6 | 58140 | 1.64041666667 | 13566 |
| 013361 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:45am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595092.5 | 511250.2 | 58142 | 1.64041666667 | 13361 |
| 013695 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:46am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595092.9 | 511247.7 | 58144 | 1.64041666667 | 13695 |
| 013651 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:47am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595095.1 | 511245.5 | 58146 | 1.64041666667 | 13651 |
| 014429 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:48am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595094.5 | 511244.0 | 58148 | 1.64041666667 | 14429 |
| 014003 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:49am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595092.9 | 511241.6 | 58150 | 1.64041666667 | 14003 |
| 012954 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:50am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595091.8 | 511240.4 | 58152 | 1.64041666667 | 12954 |
| 013167 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:51am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595091.5 | 511239.4 | 58154 | 1.64041666667 | 13167 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:52am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595091.5 | 511239.5 | 58156 | 1.64041666667 | 12378 |
| 012693 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:53am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595091.5 | 511239.9 | 58158 | 1.64041666667 | 12693 |
| 013267 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:54am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595091.5 | 511240.2 | 58160 | 1.64041666667 | 13267 |
| 013785 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:56am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595091.5 | 511240.3 | 58163 | 1.64041666667 | 13785 |
| 013649 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:56am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595091.6 | 511240.2 | 58164 | 1.64041666667 | 13649 |
| 013632 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:57am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595091.6 | 511240.2 | 58166 | 1.64041666667 | 13632 |
| 013661 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:58am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595091.5 | 511240.3 | 58168 | 1.64041666667 | 13661 |
| 013384 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:59am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595091.6 | 511239.4 | 58170 | 1.64041666667 | 13384 |
| 013806 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:00am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595090.9 | 511238.3 | 58172 | 1.64041666667 | 13806 |
| 013143 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:01am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595091.4 | 511236.0 | 58174 | 1.64041666667 | 13143 |
| 014420 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:02am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595092.1 | 511233.7 | 58176 | 1.64041666667 | 14420 |
| 013759 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:03am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595092.4 | 511230.3 | 58178 | 1.64041666667 | 13759 |
| 012929 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:04am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595092.5 | 511227.5 | 58180 | 1.64041666667 | 12929 |
| 013190 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:05am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595092.7 | 511224.1 | 58182 | 1.64041666667 | 13190 |
| 012144 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:06am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595092.6 | 511221.4 | 58184 | 1.64041666667 | 12144 |
| 012756 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:07am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595092.9 | 511217.8 | 58186 | 1.64041666667 | 12756 |
| 012568 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:08am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595093.2 | 511215.0 | 58188 | 1.64041666667 | 12568 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012724 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:09am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595092.2 | 511212.0 | 58190 | 1.64041666667 | 12724 |
| 012670 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:10am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595092.6 | 511210.0 | 58192 | 1.64041666667 | 12670 |
| 012617 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:11am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595093.1 | 511207.3 | 58194 | 1.64041666667 | 12617 |
| 012279 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:12am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595093.6 | 511205.2 | 58196 | 1.64041666667 | 12279 |
| 012105 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:13am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595095.6 | 511204.4 | 58198 | 1.64041666667 | 12105 |
| 012396 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:14am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595097.0 | 511204.6 | 58200 | 1.64041666667 | 12396 |
| 012095 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:15am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595099.1 | 511205.7 | 58202 | 1.64041666667 | 12095 |
| 012353 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:16am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595100.2 | 511207.9 | 58204 | 1.64041666667 | 12353 |
| 011853 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:17am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595102.3 | 511209.0 | 58206 | 1.64041666667 | 11853 |
| 011730 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:18am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595103.4 | 511210.1 | 58208 | 1.64041666667 | 11730 |
| 011773 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:19am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595104.5 | 511211.2 | 58210 | 1.64041666667 | 11773 |
| 012450 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:20am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595104.4 | 511211.5 | 58212 | 1.64041666667 | 12450 |
| 012058 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:21am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595103.9 | 511211.5 | 58214 | 1.64041666667 | 12058 |
| 012400 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:22am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595103.7 | 511212.0 | 58216 | 1.64041666667 | 12400 |
| 012570 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:23am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595103.1 | 511214.6 | 58218 | 1.64041666667 | 12570 |
| 013475 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:24am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595103.0 | 511217.2 | 58220 | 1.64041666667 | 13475 |
| 013482 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:25am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595102.4 | 511220.9 | 58222 | 1.64041666667 | 13482 |
| 013224 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:26am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595102.4 | 511223.7 | 58224 | 1.64041666667 | 13224 |
| 012561 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:27am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595101.2 | 511227.0 | 58226 | 1.64041666667 | 12561 |
| 012908 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:28am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595099.0 | 511229.1 | 58228 | 1.64041666667 | 12908 |
| 013448 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:29am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595098.3 | 511232.6 | 58230 | 1.64041666667 | 13448 |
| 013459 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:30am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595097.7 | 511235.2 | 58232 | 1.64041666667 | 13459 |
| 013248 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:31am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595098.0 | 511238.9 | 58234 | 1.64041666667 | 13248 |
| 014262 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:32am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595099.2 | 511241.4 | 58236 | 1.64041666667 | 14262 |
| 014022 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:33am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595097.9 | 511243.8 | 58238 | 1.64041666667 | 14022 |
| 013805 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:34am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595096.6 | 511246.2 | 58240 | 1.64041666667 | 13805 |
| 014598 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:35am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595094.4 | 511248.8 | 58242 | 1.64041666667 | 14598 |
| 014578 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:36am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595092.0 | 511250.2 | 58244 | 1.64041666667 | 14578 |
| 014128 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:37am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595090.9 | 511252.6 | 58246 | 1.64041666667 | 14128 |
| 014239 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:38am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595089.9 | 511254.9 | 58248 | 1.64041666667 | 14239 |
| 013567 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:39am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595089.7 | 511258.0 | 58250 | 1.64041666667 | 13567 |
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:40am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595088.2 | 511259.8 | 58252 | 1.64041666667 | 13451 |
| 013251 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:41am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595085.8 | 511261.7 | 58254 | 1.64041666667 | 13251 |
| 013049 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:42am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595084.2 | 511264.1 | 58256 | 1.64041666667 | 13049 |
| 013107 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:43am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595081.6 | 511265.7 | 58258 | 1.64041666667 | 13107 |
| 012758 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:44am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595080.0 | 511267.4 | 58260 | 1.64041666667 | 12758 |
| 012239 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:45am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595077.6 | 511268.2 | 58262 | 1.64041666667 | 12239 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:46am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595075.5 | 511268.1 | 58264 | 1.64041666667 | 12442 |
| 012458 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:47am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595072.9 | 511269.1 | 58266 | 1.64041666667 | 12458 |
| 012025 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:48am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595070.4 | 511270.3 | 58268 | 1.64041666667 | 12025 |
| 011804 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:49am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595067.9 | 511272.4 | 58270 | 1.64041666667 | 11804 |
| 011687 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:50am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595065.4 | 511273.9 | 58272 | 1.64041666667 | 11687 |
| 011929 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:51am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595062.7 | 511275.2 | 58274 | 1.64041666667 | 11929 |
| 011697 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:52am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595061.6 | 511276.9 | 58276 | 1.64041666667 | 11697 |
| 012092 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:53am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595060.0 | 511279.1 | 58278 | 1.64041666667 | 12092 |
| 012014 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:54am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595060.8 | 511281.6 | 58280 | 1.64041666667 | 12014 |
| 012218 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:55am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595061.4 | 511285.0 | 58282 | 1.64041666667 | 12218 |
| 011740 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:56am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595061.3 | 511287.8 | 58284 | 1.64041666667 | 11740 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:57am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595062.2 | 511290.8 | 58286 | 1.64041666667 | 12183 |
| 012186 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:58am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595061.8 | 511293.0 | 58288 | 1.64041666667 | 12186 |
| 012149 | 0 | GeoXH 6000 | 08/19/2015 | 11:01:59am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595062.5 | 511294.6 | 58290 | 1.64041666667 | 12149 |
| 011416 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:00am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595062.2 | 511295.0 | 58292 | 1.64041666667 | 11416 |
| 011566 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:01am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595062.1 | 511295.1 | 58294 | 1.64041666667 | 11566 |
| 011838 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:02am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595061.9 | 511295.1 | 58296 | 1.64041666667 | 11838 |
| 011624 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:03am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595061.0 | 511297.0 | 58298 | 1.64041666667 | 11624 |
| 012621 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:04am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595059.0 | 511300.0 | 58300 | 1.64041666667 | 12621 |
| 012754 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:05am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595057.7 | 511302.5 | 58302 | 1.64041666667 | 12754 |
| 013766 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:06am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595056.7 | 511302.8 | 58304 | 1.64041666667 | 13766 |
| 013421 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:07am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595056.5 | 511302.7 | 58306 | 1.64041666667 | 13421 |
| 013602 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:08am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595056.6 | 511302.8 | 58308 | 1.64041666667 | 13602 |
| 013996 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:09am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595056.5 | 511302.9 | 58310 | 1.64041666667 | 13996 |
| 013955 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:10am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595056.4 | 511302.9 | 58312 | 1.64041666667 | 13955 |
| 014067 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:11am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595056.2 | 511303.0 | 58314 | 1.64041666667 | 14067 |
| 013882 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:12am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595056.6 | 511303.8 | 58316 | 1.64041666667 | 13882 |
| 012774 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:13am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595055.0 | 511305.5 | 58318 | 1.64041666667 | 12774 |
| 012990 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:14am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595054.4 | 511307.3 | 58320 | 1.64041666667 | 12990 |
| 013509 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:15am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595053.0 | 511310.5 | 58322 | 1.64041666667 | 13509 |
| 012984 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:16am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595053.8 | 511312.5 | 58324 | 1.64041666667 | 12984 |
| 013086 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:17am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595054.6 | 511315.3 | 58326 | 1.64041666667 | 13086 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:18am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595055.1 | 511314.5 | 58328 | 1.64041666667 | 12768 |
| 013009 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:19am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595054.4 | 511314.5 | 58330 | 1.64041666667 | 13009 |
| 013100 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:20am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595053.5 | 511315.2 | 58332 | 1.64041666667 | 13100 |
| 013308 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:21am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595053.5 | 511315.2 | 58334 | 1.64041666667 | 13308 |
| 012616 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:22am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595055.1 | 511314.5 | 58336 | 1.64041666667 | 12616 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:23am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595057.8 | 511314.9 | 58338 | 1.64041666667 | 12106 |
| 012397 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:24am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595060.5 | 511315.0 | 58340 | 1.64041666667 | 12397 |
| 012898 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:25am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.2 | 511316.1 | 58342 | 1.64041666667 | 12898 |
| 012723 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:26am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.3 | 511316.1 | 58344 | 1.64041666667 | 12723 |
| 013471 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:27am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.4 | 511316.0 | 58346 | 1.64041666667 | 13471 |
| 013472 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:28am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.4 | 511316.0 | 58348 | 1.64041666667 | 13472 |
| 014253 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:29am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.3 | 511316.0 | 58350 | 1.64041666667 | 14253 |
| 013657 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:30am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595062.9 | 511315.6 | 58352 | 1.64041666667 | 13657 |
| 013502 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:31am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595063.0 | 511315.8 | 58354 | 1.64041666667 | 13502 |
| 012867 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:32am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.5 | 511316.0 | 58356 | 1.64041666667 | 12867 |
| 012728 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:33am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595063.5 | 511314.9 | 58358 | 1.64041666667 | 12728 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:34am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595064.3 | 511313.1 | 58360 | 1.64041666667 | 12454 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:35am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595064.7 | 511310.4 | 58362 | 1.64041666667 | 12255 |
| 013066 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:36am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595064.6 | 511307.7 | 58364 | 1.64041666667 | 13066 |
| 012997 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:37am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595064.1 | 511305.6 | 58366 | 1.64041666667 | 12997 |
| 012906 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:38am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595064.5 | 511304.5 | 58368 | 1.64041666667 | 12906 |
| 012952 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:39am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595064.7 | 511303.0 | 58370 | 1.64041666667 | 12952 |
| 013345 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:40am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595066.7 | 511300.6 | 58372 | 1.64041666667 | 13345 |
| 012029 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:41am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595068.1 | 511297.9 | 58374 | 1.64041666667 | 12029 |
| 012354 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:42am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595069.8 | 511296.9 | 58376 | 1.64041666667 | 12354 |
| 012116 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:43am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595072.2 | 511294.5 | 58378 | 1.64041666667 | 12116 |
| 011345 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:44am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595073.8 | 511293.1 | 58380 | 1.64041666667 | 11345 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010769 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:45am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595074.7 | 511289.3 | 58382 | 1.64041666667 | 10769 |
| 012245 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:46am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595075.1 | 511286.4 | 58384 | 1.64041666667 | 12245 |
| 012520 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:47am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595077.4 | 511283.9 | 58386 | 1.64041666667 | 12520 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:48am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595079.6 | 511280.9 | 58388 | 1.64041666667 | 12180 |
| 012258 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:49am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595081.1 | 511278.0 | 58390 | 1.64041666667 | 12258 |
| 012528 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:50am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595082.8 | 511275.2 | 58392 | 1.64041666667 | 12528 |
| 012274 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:51am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595084.7 | 511273.7 | 58394 | 1.64041666667 | 12274 |
| 012364 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:52am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595085.9 | 511272.4 | 58396 | 1.64041666667 | 12364 |
| 012610 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:53am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595088.0 | 511270.6 | 58398 | 1.64041666667 | 12610 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:54am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595089.3 | 511268.9 | 58400 | 1.64041666667 | 12133 |
| 012810 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:55am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595090.5 | 511266.0 | 58402 | 1.64041666667 | 12810 |
| 013288 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:56am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595092.4 | 511263.9 | 58404 | 1.64041666667 | 13288 |
| 013212 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:57am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595094.8 | 511260.9 | 58406 | 1.64041666667 | 13212 |
| 013799 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:58am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595096.8 | 511258.5 | 58408 | 1.64041666667 | 13799 |
| 014047 | 0 | GeoXH 6000 | 08/19/2015 | 11:02:59am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595099.5 | 511256.7 | 58410 | 1.64041666667 | 14047 |
| 013309 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:00am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595100.8 | 511254.2 | 58412 | 1.64041666667 | 13309 |
| 014633 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:01am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595102.5 | 511251.8 | 58414 | 1.64041666667 | 14633 |
| 015214 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:02am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595103.6 | 511249.9 | 58416 | 1.64041666667 | 15214 |
| 016132 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:03am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595104.2 | 511247.2 | 58418 | 1.64041666667 | 16132 |
| 016252 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:04am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595105.5 | 511246.0 | 58420 | 1.64041666667 | 16252 |
| 015599 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:05am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595105.7 | 511244.3 | 58422 | 1.64041666667 | 15599 |
| 015022 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:06am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595106.2 | 511243.9 | 58424 | 1.64041666667 | 15022 |
| 014180 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:07am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595106.7 | 511242.9 | 58426 | 1.64041666667 | 14180 |
| 013781 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:08am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595106.7 | 511240.7 | 58428 | 1.64041666667 | 13781 |
| 014254 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:09am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595105.6 | 511237.9 | 58430 | 1.64041666667 | 14254 |
| 013778 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:10am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595105.4 | 511235.8 | 58432 | 1.64041666667 | 13778 |
| 012985 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:11am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595105.9 | 511232.7 | 58434 | 1.64041666667 | 12985 |
| 013439 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:12am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595107.6 | 511230.8 | 58436 | 1.64041666667 | 13439 |
| 013019 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:13am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595110.0 | 511230.9 | 58438 | 1.64041666667 | 13019 |
| 012551 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:14am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595113.0 | 511230.7 | 58440 | 1.64041666667 | 12551 |
| 012400 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:15am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595115.5 | 511229.3 | 58442 | 1.64041666667 | 12400 |
| 012165 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:16am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595116.9 | 511226.7 | 58444 | 1.64041666667 | 12165 |
| 013007 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:17am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595117.3 | 511224.3 | 58446 | 1.64041666667 | 13007 |
| 012731 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:18am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595119.0 | 511222.6 | 58448 | 1.64041666667 | 12731 |
| 012666 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:19am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595119.8 | 511220.3 | 58450 | 1.64041666667 | 12666 |
| 012547 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:20am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595121.1 | 511219.2 | 58452 | 1.64041666667 | 12547 |
| 013658 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:21am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595122.3 | 511217.5 | 58454 | 1.64041666667 | 13658 |
| 013690 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:22am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595124.2 | 511217.3 | 58456 | 1.64041666667 | 13690 |
| 014473 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:23am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595126.3 | 511218.8 | 58458 | 1.64041666667 | 14473 |
| 014696 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:24am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595128.5 | 511219.7 | 58460 | 1.64041666667 | 14696 |
| 014574 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:25am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595129.4 | 511221.6 | 58462 | 1.64041666667 | 14574 |
| 013477 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:26am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595129.9 | 511223.1 | 58464 | 1.64041666667 | 13477 |
| 013393 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:27am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595129.5 | 511223.5 | 58466 | 1.64041666667 | 13393 |
| 012949 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:28am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595129.7 | 511224.5 | 58468 | 1.64041666667 | 12949 |
| 012316 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:29am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595128.7 | 511226.5 | 58470 | 1.64041666667 | 12316 |
| 013025 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:30am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595128.1 | 511228.6 | 58472 | 1.64041666667 | 13025 |
| 012089 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:31am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595127.4 | 511231.4 | 58474 | 1.64041666667 | 12089 |
| 012635 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:32am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595125.5 | 511232.8 | 58476 | 1.64041666667 | 12635 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013354 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:33am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595123.8 | 511235.7 | 58478 | 1.64041666667 | 13354 |
| 012829 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:34am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595122.9 | 511237.8 | 58480 | 1.64041666667 | 12829 |
| 011731 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:35am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595122.1 | 511240.0 | 58482 | 1.64041666667 | 11731 |
| 012209 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:36am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595122.2 | 511241.2 | 58484 | 1.64041666667 | 12209 |
| 012410 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:37am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595122.0 | 511240.7 | 58486 | 1.64041666667 | 12410 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:38am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595122.1 | 511240.8 | 58488 | 1.64041666667 | 12163 |
| 013096 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:39am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595122.0 | 511241.5 | 58490 | 1.64041666667 | 13096 |
| 013142 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:40am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595121.5 | 511242.7 | 58492 | 1.64041666667 | 13142 |
| 013204 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:41am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595121.1 | 511243.3 | 58494 | 1.64041666667 | 13204 |
| 011905 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:42am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595120.5 | 511243.9 | 58496 | 1.64041666667 | 11905 |
| 012066 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:43am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595119.5 | 511247.0 | 58498 | 1.64041666667 | 12066 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:44am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595119.4 | 511249.5 | 58500 | 1.64041666667 | 12840 |
| 012532 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:45am | Sensor | 1797-S0041-G-636-DTE | 6824.3 | 1595118.4 | 511252.9 | 58502 | 1.64041666667 | 12532 |
| 013177 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:46am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595117.4 | 511255.8 | 58504 | 1.64041666667 | 13177 |
| 012369 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:47am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595116.2 | 511259.0 | 58506 | 1.64041666667 | 12369 |
| 012590 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:48am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595115.1 | 511261.9 | 58508 | 1.64041666667 | 12590 |
| 012617 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:49am | Sensor | 1797-S0041-G-636-DTE | 6823.7 | 1595114.3 | 511265.2 | 58510 | 1.64041666667 | 12617 |
| 011642 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:50am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595114.8 | 511267.8 | 58512 | 1.64041666667 | 11642 |
| 012721 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:51am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595114.3 | 511269.6 | 58514 | 1.64041666667 | 12721 |
| 012383 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:52am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595113.7 | 511271.0 | 58516 | 1.64041666667 | 12383 |
| 011833 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:53am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595112.5 | 511273.8 | 58518 | 1.64041666667 | 11833 |
| 011208 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:54am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595110.9 | 511275.7 | 58520 | 1.64041666667 | 11208 |
| 011629 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:55am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595107.9 | 511277.2 | 58522 | 1.64041666667 | 11629 |
| 011941 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:56am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595106.8 | 511277.9 | 58524 | 1.64041666667 | 11941 |
| 011487 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:57am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595106.2 | 511278.1 | 58526 | 1.64041666667 | 11487 |
| 011381 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:58am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595106.0 | 511278.3 | 58528 | 1.64041666667 | 11381 |
| 011052 | 0 | GeoXH 6000 | 08/19/2015 | 11:03:59am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595107.2 | 511279.6 | 58530 | 1.64041666667 | 11052 |
| 011932 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:00am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595107.7 | 511281.3 | 58532 | 1.64041666667 | 11932 |
| 012501 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:01am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595108.8 | 511282.6 | 58534 | 1.64041666667 | 12501 |
| 013054 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:02am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595108.6 | 511284.6 | 58536 | 1.64041666667 | 13054 |
| 011798 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:03am | Sensor | 1797-S0041-G-636-DTE | 6824.5 | 1595107.9 | 511287.9 | 58538 | 1.64041666667 | 11798 |
| 011766 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:04am | Sensor | 1797-S0041-G-636-DTE | 6824.2 | 1595106.4 | 511291.2 | 58540 | 1.64041666667 | 11766 |
| 012356 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:05am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595104.0 | 511294.7 | 58542 | 1.64041666667 | 12356 |
| 012335 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:06am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595102.5 | 511297.7 | 58544 | 1.64041666667 | 12335 |
| 012181 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:07am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595102.5 | 511301.2 | 58546 | 1.64041666667 | 12181 |
| 012686 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:08am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595101.4 | 511304.1 | 58548 | 1.64041666667 | 12686 |
| 012348 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:09am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595100.6 | 511306.8 | 58550 | 1.64041666667 | 12348 |
| 011956 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:10am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595099.9 | 511309.1 | 58552 | 1.64041666667 | 11956 |
| 012553 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:11am | Sensor | 1797-S0041-G-636-DTE | 6823.9 | 1595098.2 | 511311.6 | 58554 | 1.64041666667 | 12553 |
| 012978 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:12am | Sensor | 1797-S0041-G-636-DTE | 6824.0 | 1595097.0 | 511314.6 | 58556 | 1.64041666667 | 12978 |
| 012723 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:13am | Sensor | 1797-S0041-G-636-DTE | 6824.1 | 1595095.0 | 511317.9 | 58558 | 1.64041666667 | 12723 |
| 012481 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:14am | Sensor | 1797-S0041-G-636-DTE | 6824.4 | 1595093.4 | 511319.3 | 58560 | 1.64041666667 | 12481 |
| 012488 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:15am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595092.3 | 511321.7 | 58562 | 1.64041666667 | 12488 |
| 012409 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:16am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595091.9 | 511324.4 | 58564 | 1.64041666667 | 12409 |
| 012065 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:17am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595093.0 | 511327.2 | 58566 | 1.64041666667 | 12065 |
| 012299 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:18am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595092.6 | 511329.2 | 58568 | 1.64041666667 | 12299 |
| 012228 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:19am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595092.2 | 511331.4 | 58570 | 1.64041666667 | 12228 |
| 012961 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:20am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595091.9 | 511332.5 | 58572 | 1.64041666667 | 12961 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012825 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:21am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595092.2 | 511332.9 | 58574 | 1.64041666667 | 12825 |
| 012599 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:22am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595092.4 | 511333.0 | 58576 | 1.64041666667 | 12599 |
| 012967 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:23am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595092.5 | 511332.9 | 58578 | 1.64041666667 | 12967 |
| 012701 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:24am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595092.4 | 511333.0 | 58580 | 1.64041666667 | 12701 |
| 012499 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:25am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595092.4 | 511333.0 | 58582 | 1.64041666667 | 12499 |
| 011966 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:26am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595092.5 | 511333.0 | 58584 | 1.64041666667 | 11966 |
| 012993 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:27am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595092.5 | 511332.9 | 58586 | 1.64041666667 | 12993 |
| 012393 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:28am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595092.2 | 511332.9 | 58588 | 1.64041666667 | 12393 |
| 012499 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:29am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595092.2 | 511332.9 | 58590 | 1.64041666667 | 12499 |
| 012595 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:30am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595092.6 | 511333.0 | 58592 | 1.64041666667 | 12595 |
| 012245 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:31am | Sensor | 1797-S0041-G-636-DTE | 6825.4 | 1595093.0 | 511332.7 | 58594 | 1.64041666667 | 12245 |
| 012138 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:32am | Sensor | 1797-S0041-G-636-DTE | 6825.5 | 1595091.5 | 511332.4 | 58596 | 1.64041666667 | 12138 |
| 012160 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:33am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595089.0 | 511331.6 | 58598 | 1.64041666667 | 12160 |
| 012592 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:34am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595086.6 | 511330.4 | 58600 | 1.64041666667 | 12592 |
| 012776 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:35am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595083.8 | 511328.5 | 58602 | 1.64041666667 | 12776 |
| 012436 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:36am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595081.9 | 511326.3 | 58604 | 1.64041666667 | 12436 |
| 011660 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:37am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595078.8 | 511323.7 | 58606 | 1.64041666667 | 11660 |
| 011846 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:38am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595076.5 | 511322.5 | 58608 | 1.64041666667 | 11846 |
| 011598 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:39am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595074.3 | 511320.7 | 58610 | 1.64041666667 | 11598 |
| 012261 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:40am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595073.1 | 511320.3 | 58612 | 1.64041666667 | 12261 |
| 012769 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:41am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595073.1 | 511320.2 | 58614 | 1.64041666667 | 12769 |
| 013453 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:42am | Sensor | 1797-S0041-G-636-DTE | 6825.3 | 1595073.6 | 511319.0 | 58616 | 1.64041666667 | 13453 |
| 012449 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:43am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595075.7 | 511317.5 | 58618 | 1.64041666667 | 12449 |
| 012613 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:44am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595077.5 | 511315.8 | 58620 | 1.64041666667 | 12613 |
| 013859 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:45am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595080.9 | 511313.2 | 58622 | 1.64041666667 | 13859 |
| 012851 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:46am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595083.3 | 511311.5 | 58624 | 1.64041666667 | 12851 |
| 012396 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:47am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595085.7 | 511308.3 | 58626 | 1.64041666667 | 12396 |
| 012282 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:48am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595085.4 | 511305.5 | 58628 | 1.64041666667 | 12282 |
| 012571 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:49am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595085.2 | 511301.9 | 58630 | 1.64041666667 | 12571 |
| 012254 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:50am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595085.9 | 511300.0 | 58632 | 1.64041666667 | 12254 |
| 012075 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:51am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595086.1 | 511299.3 | 58634 | 1.64041666667 | 12075 |
| 011412 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:52am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595086.2 | 511299.2 | 58636 | 1.64041666667 | 11412 |
| 011564 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:53am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595086.0 | 511298.1 | 58638 | 1.64041666667 | 11564 |
| 011410 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:54am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595086.1 | 511295.8 | 58640 | 1.64041666667 | 11410 |
| 011270 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:55am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595086.4 | 511292.5 | 58642 | 1.64041666667 | 11270 |
| 010914 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:56am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595087.3 | 511289.5 | 58644 | 1.64041666667 | 10914 |
| 012274 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:57am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595088.6 | 511286.0 | 58646 | 1.64041666667 | 12274 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:58am | Sensor | 1797-S0041-G-636-DTE | 6824.6 | 1595089.2 | 511283.1 | 58648 | 1.64041666667 | 12626 |
| 011812 | 0 | GeoXH 6000 | 08/19/2015 | 11:04:59am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595091.0 | 511279.7 | 58650 | 1.64041666667 | 11812 |
| 011399 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:00am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595092.8 | 511276.6 | 58652 | 1.64041666667 | 11399 |
| 012037 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:01am | Sensor | 1797-S0041-G-636-DTE | 6825.1 | 1595094.3 | 511274.2 | 58654 | 1.64041666667 | 12037 |
| 012711 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:02am | Sensor | 1797-S0041-G-636-DTE | 6825.2 | 1595094.0 | 511272.5 | 58656 | 1.64041666667 | 12711 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:03am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595095.1 | 511270.6 | 58658 | 1.64041666667 | 12760 |
| 013012 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:04am | Sensor | 1797-S0041-G-636-DTE | 6824.7 | 1595095.1 | 511267.5 | 58660 | 1.64041666667 | 13012 |
| 012629 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:05am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595095.1 | 511264.3 | 58662 | 1.64041666667 | 12629 |
| 012391 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:06am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595095.7 | 511261.0 | 58664 | 1.64041666667 | 12391 |
| 013510 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:07am | Sensor | 1797-S0041-G-636-DTE | 6824.9 | 1595096.4 | 511257.6 | 58666 | 1.64041666667 | 13510 |
| 012377 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:08am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595097.4 | 511254.6 | 58668 | 1.64041666667 | 12377 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013097 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:09am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595099.7 | 511251.9 | 58670 | 1.64041666667 | 13097 |
| 014057 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:10am | Sensor | 1797-S0041-G-636-DTE | 6824.8 | 1595101.7 | 511249.3 | 58672 | 1.64041666667 | 14057 |
| 015309 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:11am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595102.7 | 511246.4 | 58674 | 1.64041666667 | 15309 |
| 016216 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:12am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595104.4 | 511244.8 | 58676 | 1.64041666667 | 16216 |
| 018099 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:13am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595104.5 | 511244.2 | 58678 | 1.64041666667 | 18099 |
| 017238 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:14am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595104.1 | 511244.2 | 58680 | 1.64041666667 | 17238 |
| 016281 | 0 | GeoXH 6000 | 08/19/2015 | 11:05:15am | Sensor | 1797-S0041-G-636-DTE | 6825.0 | 1595104.0 | 511244.1 | 58682 | 1.64041666667 | 16281 |
| 013560 | 0 | GeoXH 6000 | 08/19/2015 | 10:17:54am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.2 | 510879.9 | 53414 | 1.64041666667 | 13560 |
| 013672 | 0 | GeoXH 6000 | 08/19/2015 | 10:17:55am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.2 | 510879.8 | 53417 | 1.64041666667 | 13672 |
| 013646 | 0 | GeoXH 6000 | 08/19/2015 | 10:17:56am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.1 | 510879.8 | 53419 | 1.64041666667 | 13646 |
| 012993 | 0 | GeoXH 6000 | 08/19/2015 | 10:17:57am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.1 | 510879.8 | 53421 | 1.64041666667 | 12993 |
| 013226 | 0 | GeoXH 6000 | 08/19/2015 | 10:17:58am | Sensor | 1797-S0040-905-G-ACK | 6817.0 | 1594818.1 | 510879.8 | 53423 | 1.64041666667 | 13226 |
| 013200 | 0 | GeoXH 6000 | 08/19/2015 | 10:17:59am | Sensor | 1797-S0040-905-G-ACK | 6817.0 | 1594818.1 | 510879.8 | 53425 | 1.64041666667 | 13200 |
| 012885 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:00am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.1 | 510879.8 | 53427 | 1.64041666667 | 12885 |
| 013487 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:01am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.1 | 510879.8 | 53429 | 1.64041666667 | 13487 |
| 014456 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:02am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.1 | 510879.8 | 53431 | 1.64041666667 | 14456 |
| 013779 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:03am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.1 | 510879.8 | 53433 | 1.64041666667 | 13779 |
| 014688 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:04am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.1 | 510879.8 | 53435 | 1.64041666667 | 14688 |
| 014817 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:05am | Sensor | 1797-S0040-905-G-ACK | 6817.0 | 1594818.2 | 510880.1 | 53437 | 1.64041666667 | 14817 |
| 013989 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:06am | Sensor | 1797-S0040-905-G-ACK | 6816.6 | 1594818.6 | 510880.8 | 53439 | 1.64041666667 | 13989 |
| 014244 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:07am | Sensor | 1797-S0040-905-G-ACK | 6815.9 | 1594818.9 | 510881.3 | 53441 | 1.64041666667 | 14244 |
| 013944 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:08am | Sensor | 1797-S0040-905-G-ACK | 6816.5 | 1594818.8 | 510880.9 | 53443 | 1.64041666667 | 13944 |
| 013574 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:09am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.5 | 510880.1 | 53445 | 1.64041666667 | 13574 |
| 013942 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:10am | Sensor | 1797-S0040-905-G-ACK | 6817.2 | 1594818.3 | 510879.9 | 53447 | 1.64041666667 | 13942 |
| 012965 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:11am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.2 | 510879.7 | 53449 | 1.64041666667 | 12965 |
| 013623 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:12am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.2 | 510879.7 | 53451 | 1.64041666667 | 13623 |
| 013460 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:13am | Sensor | 1797-S0040-905-G-ACK | 6817.0 | 1594818.2 | 510879.9 | 53453 | 1.64041666667 | 13460 |
| 012798 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:14am | Sensor | 1797-S0040-905-G-ACK | 6817.1 | 1594818.1 | 510879.7 | 53455 | 1.64041666667 | 12798 |
| 013064 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:15am | Sensor | 1797-S0040-905-G-ACK | 6817.2 | 1594818.1 | 510879.7 | 53457 | 1.64041666667 | 13064 |
| 013386 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:16am | Sensor | 1797-S0040-905-G-ACK | 6817.2 | 1594818.1 | 510879.9 | 53459 | 1.64041666667 | 13386 |
| 013837 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:17am | Sensor | 1797-S0040-905-G-ACK | 6817.2 | 1594818.7 | 510880.5 | 53461 | 1.64041666667 | 13837 |
| 013933 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:18am | Sensor | 1797-S0040-905-G-ACK | 6817.2 | 1594819.4 | 510880.4 | 53463 | 1.64041666667 | 13933 |
| 013905 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:19am | Sensor | 1797-S0040-905-G-ACK | 6817.2 | 1594821.1 | 510881.1 | 53465 | 1.64041666667 | 13905 |
| 013679 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:20am | Sensor | 1797-S0040-905-G-ACK | 6817.3 | 1594822.8 | 510881.6 | 53467 | 1.64041666667 | 13679 |
| 013912 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:21am | Sensor | 1797-S0040-905-G-ACK | 6817.2 | 1594825.0 | 510883.0 | 53469 | 1.64041666667 | 13912 |
| 013435 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:22am | Sensor | 1797-S0040-905-G-ACK | 6817.3 | 1594827.3 | 510883.8 | 53471 | 1.64041666667 | 13435 |
| 013752 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:23am | Sensor | 1797-S0040-905-G-ACK | 6817.4 | 1594830.1 | 510884.2 | 53473 | 1.64041666667 | 13752 |
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:24am | Sensor | 1797-S0040-905-G-ACK | 6817.4 | 1594832.6 | 510884.7 | 53475 | 1.64041666667 | 13795 |
| 013662 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:25am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594835.5 | 510884.9 | 53477 | 1.64041666667 | 13662 |
| 014555 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:26am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594837.2 | 510883.7 | 53479 | 1.64041666667 | 14555 |
| 015552 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:27am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594839.5 | 510881.4 | 53481 | 1.64041666667 | 15552 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:28am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594841.1 | 510879.4 | 53483 | 1.64041666667 | 14463 |
| 014315 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:29am | Sensor | 1797-S0040-905-G-ACK | 6817.4 | 1594841.9 | 510876.2 | 53485 | 1.64041666667 | 14315 |
| 014682 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:30am | Sensor | 1797-S0040-905-G-ACK | 6817.4 | 1594843.0 | 510874.0 | 53487 | 1.64041666667 | 14682 |
| 015226 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:31am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594845.2 | 510871.6 | 53489 | 1.64041666667 | 15226 |
| 014115 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:32am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594846.2 | 510869.2 | 53491 | 1.64041666667 | 14115 |
| 014397 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:33am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594847.3 | 510866.3 | 53493 | 1.64041666667 | 14397 |
| 014930 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:34am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594848.3 | 510864.5 | 53495 | 1.64041666667 | 14930 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014886 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:35am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594849.5 | 510862.8 | 53497 | 1.64041666667 | 14886 |
| 014921 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:36am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594851.0 | 510861.9 | 53499 | 1.64041666667 | 14921 |
| 014753 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:37am | Sensor | 1797-S0040-905-G-ACK | 6817.7 | 1594852.9 | 510859.7 | 53501 | 1.64041666667 | 14753 |
| 014703 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:38am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594854.9 | 510857.0 | 53503 | 1.64041666667 | 14703 |
| 014420 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:39am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594857.1 | 510854.7 | 53505 | 1.64041666667 | 14420 |
| 014336 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:40am | Sensor | 1797-S0040-905-G-ACK | 6818.0 | 1594858.3 | 510852.7 | 53507 | 1.64041666667 | 14336 |
| 014214 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:41am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594859.1 | 510849.8 | 53509 | 1.64041666667 | 14214 |
| 014138 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:42am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594860.0 | 510847.2 | 53511 | 1.64041666667 | 14138 |
| 013930 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:43am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594861.0 | 510844.8 | 53513 | 1.64041666667 | 13930 |
| 013955 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:44am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594861.4 | 510842.8 | 53515 | 1.64041666667 | 13955 |
| 013362 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:45am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594863.0 | 510840.2 | 53517 | 1.64041666667 | 13362 |
| 013051 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:46am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594863.8 | 510838.5 | 53519 | 1.64041666667 | 13051 |
| 013349 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:47am | Sensor | 1797-S0040-905-G-ACK | 6818.0 | 1594863.1 | 510835.7 | 53521 | 1.64041666667 | 13349 |
| 014873 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:48am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594862.6 | 510833.5 | 53523 | 1.64041666667 | 14873 |
| 013909 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:49am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594863.8 | 510830.8 | 53525 | 1.64041666667 | 13909 |
| 014056 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:50am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594864.8 | 510828.7 | 53527 | 1.64041666667 | 14056 |
| 013636 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:51am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1594865.3 | 510826.8 | 53529 | 1.64041666667 | 13636 |
| 013797 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:52am | Sensor | 1797-S0040-905-G-ACK | 6819.2 | 1594866.3 | 510824.8 | 53531 | 1.64041666667 | 13797 |
| 013769 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:53am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594867.3 | 510822.3 | 53533 | 1.64041666667 | 13769 |
| 013392 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:54am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594867.5 | 510819.8 | 53535 | 1.64041666667 | 13392 |
| 014890 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:55am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594868.3 | 510816.3 | 53537 | 1.64041666667 | 14890 |
| 015043 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:56am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594868.9 | 510813.7 | 53539 | 1.64041666667 | 15043 |
| 015294 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:57am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594869.0 | 510810.7 | 53541 | 1.64041666667 | 15294 |
| 015075 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:58am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594869.0 | 510808.5 | 53543 | 1.64041666667 | 15075 |
| 014420 | 0 | GeoXH 6000 | 08/19/2015 | 10:18:59am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594869.0 | 510805.1 | 53545 | 1.64041666667 | 14420 |
| 013196 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:00am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594869.1 | 510802.7 | 53547 | 1.64041666667 | 13196 |
| 014090 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:01am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594869.8 | 510799.9 | 53549 | 1.64041666667 | 14090 |
| 014428 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:02am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594871.0 | 510797.0 | 53551 | 1.64041666667 | 14428 |
| 015218 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:03am | Sensor | 1797-S0040-905-G-ACK | 6818.0 | 1594871.4 | 510794.2 | 53553 | 1.64041666667 | 15218 |
| 014613 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:04am | Sensor | 1797-S0040-905-G-ACK | 6818.0 | 1594871.4 | 510792.3 | 53555 | 1.64041666667 | 14613 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:05am | Sensor | 1797-S0040-905-G-ACK | 6817.7 | 1594872.4 | 510789.3 | 53557 | 1.64041666667 | 14737 |
| 014259 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:06am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594873.5 | 510786.7 | 53559 | 1.64041666667 | 14259 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:07am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594874.3 | 510783.2 | 53561 | 1.64041666667 | 13593 |
| 013916 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:08am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594875.1 | 510780.5 | 53563 | 1.64041666667 | 13916 |
| 014285 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:09am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594876.5 | 510777.9 | 53565 | 1.64041666667 | 14285 |
| 013428 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:10am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594877.6 | 510775.2 | 53567 | 1.64041666667 | 13428 |
| 014340 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:11am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594878.8 | 510772.4 | 53569 | 1.64041666667 | 14340 |
| 014194 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:12am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594880.3 | 510770.5 | 53571 | 1.64041666667 | 14194 |
| 014569 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:13am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594882.0 | 510768.5 | 53573 | 1.64041666667 | 14569 |
| 013887 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:14am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594882.6 | 510766.6 | 53575 | 1.64041666667 | 13887 |
| 013706 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:15am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594884.1 | 510764.1 | 53577 | 1.64041666667 | 13706 |
| 014115 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:16am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594885.6 | 510762.8 | 53579 | 1.64041666667 | 14115 |
| 015994 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:17am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594886.7 | 510760.5 | 53581 | 1.64041666667 | 15994 |
| 016437 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:18am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594887.9 | 510758.5 | 53583 | 1.64041666667 | 16437 |
| 015163 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:19am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594889.9 | 510756.0 | 53585 | 1.64041666667 | 15163 |
| 017004 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:20am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594891.6 | 510753.9 | 53587 | 1.64041666667 | 17004 |
| 016960 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:21am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594893.5 | 510751.4 | 53589 | 1.64041666667 | 16960 |
| 016012 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:21am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594895.3 | 510749.2 | 53590 | 1.64041666667 | 16012 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015412 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:23am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594897.8 | 510746.5 | 53593 | 1.64041666667 | 15412 |
| 014527 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:24am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594899.8 | 510744.0 | 53595 | 1.64041666667 | 14527 |
| 014441 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:25am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594901.8 | 510740.9 | 53597 | 1.64041666667 | 14441 |
| 015398 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:26am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594903.5 | 510738.7 | 53599 | 1.64041666667 | 15398 |
| 015561 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:27am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594905.5 | 510736.1 | 53601 | 1.64041666667 | 15561 |
| 014963 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:28am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594906.9 | 510733.7 | 53603 | 1.64041666667 | 14963 |
| 015857 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:29am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594908.2 | 510730.4 | 53605 | 1.64041666667 | 15857 |
| 015392 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:30am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594909.8 | 510728.2 | 53607 | 1.64041666667 | 15392 |
| 015835 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:31am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594912.6 | 510726.1 | 53609 | 1.64041666667 | 15835 |
| 016152 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:32am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594914.6 | 510724.7 | 53611 | 1.64041666667 | 16152 |
| 016668 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:33am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1594916.8 | 510721.8 | 53613 | 1.64041666667 | 16668 |
| 015683 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:34am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594918.6 | 510720.1 | 53615 | 1.64041666667 | 15683 |
| 015204 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:35am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1594921.7 | 510718.6 | 53617 | 1.64041666667 | 15204 |
| 015737 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:36am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1594923.8 | 510717.2 | 53619 | 1.64041666667 | 15737 |
| 015745 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:37am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594925.6 | 510714.6 | 53621 | 1.64041666667 | 15745 |
| 016364 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:38am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594927.1 | 510712.7 | 53623 | 1.64041666667 | 16364 |
| 016629 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:39am | Sensor | 1797-S0040-905-G-ACK | 6819.2 | 1594928.9 | 510710.5 | 53625 | 1.64041666667 | 16629 |
| 016921 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:40am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1594930.0 | 510707.9 | 53627 | 1.64041666667 | 16921 |
| 017085 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:41am | Sensor | 1797-S0040-905-G-ACK | 6819.3 | 1594931.5 | 510704.8 | 53629 | 1.64041666667 | 17085 |
| 016466 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:42am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1594932.6 | 510702.3 | 53631 | 1.64041666667 | 16466 |
| 015457 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:43am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1594933.8 | 510699.4 | 53633 | 1.64041666667 | 15457 |
| 016194 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:44am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1594934.9 | 510697.4 | 53635 | 1.64041666667 | 16194 |
| 014742 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:45am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1594936.3 | 510694.8 | 53637 | 1.64041666667 | 14742 |
| 014599 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:46am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1594938.4 | 510693.0 | 53639 | 1.64041666667 | 14599 |
| 014242 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:47am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1594940.7 | 510691.0 | 53641 | 1.64041666667 | 14242 |
| 013553 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:48am | Sensor | 1797-S0040-905-G-ACK | 6819.2 | 1594942.5 | 510688.8 | 53643 | 1.64041666667 | 13553 |
| 014344 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:49am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1594944.3 | 510686.5 | 53645 | 1.64041666667 | 14344 |
| 015073 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:50am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1594946.0 | 510684.1 | 53647 | 1.64041666667 | 15073 |
| 015701 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:51am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1594947.0 | 510682.0 | 53649 | 1.64041666667 | 15701 |
| 015192 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:52am | Sensor | 1797-S0040-905-G-ACK | 6819.6 | 1594947.5 | 510679.9 | 53651 | 1.64041666667 | 15192 |
| 015610 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:53am | Sensor | 1797-S0040-905-G-ACK | 6819.7 | 1594948.5 | 510677.6 | 53653 | 1.64041666667 | 15610 |
| 016348 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:54am | Sensor | 1797-S0040-905-G-ACK | 6819.7 | 1594950.1 | 510675.8 | 53655 | 1.64041666667 | 16348 |
| 015413 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:55am | Sensor | 1797-S0040-905-G-ACK | 6819.8 | 1594951.7 | 510673.3 | 53657 | 1.64041666667 | 15413 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:56am | Sensor | 1797-S0040-905-G-ACK | 6819.9 | 1594952.6 | 510671.7 | 53659 | 1.64041666667 | 14737 |
| 014455 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:57am | Sensor | 1797-S0040-905-G-ACK | 6819.8 | 1594954.8 | 510670.4 | 53661 | 1.64041666667 | 14455 |
| 015203 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:58am | Sensor | 1797-S0040-905-G-ACK | 6819.9 | 1594956.8 | 510668.5 | 53663 | 1.64041666667 | 15203 |
| 015324 | 0 | GeoXH 6000 | 08/19/2015 | 10:19:59am | Sensor | 1797-S0040-905-G-ACK | 6820.0 | 1594958.5 | 510666.9 | 53665 | 1.64041666667 | 15324 |
| 014342 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:00am | Sensor | 1797-S0040-905-G-ACK | 6820.0 | 1594960.4 | 510665.9 | 53667 | 1.64041666667 | 14342 |
| 014960 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:01am | Sensor | 1797-S0040-905-G-ACK | 6820.1 | 1594962.8 | 510664.2 | 53669 | 1.64041666667 | 14960 |
| 014625 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:02am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1594964.0 | 510662.9 | 53671 | 1.64041666667 | 14625 |
| 014969 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:03am | Sensor | 1797-S0040-905-G-ACK | 6820.1 | 1594967.1 | 510661.4 | 53673 | 1.64041666667 | 14969 |
| 015020 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:04am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1594969.1 | 510660.5 | 53675 | 1.64041666667 | 15020 |
| 014928 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:05am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1594971.5 | 510659.7 | 53677 | 1.64041666667 | 14928 |
| 015807 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:06am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1594973.6 | 510660.2 | 53679 | 1.64041666667 | 15807 |
| 016039 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:07am | Sensor | 1797-S0040-905-G-ACK | 6820.4 | 1594976.5 | 510660.7 | 53681 | 1.64041666667 | 16039 |
| 015884 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:08am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1594978.7 | 510660.6 | 53683 | 1.64041666667 | 15884 |
| 015182 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:09am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1594981.7 | 510661.3 | 53685 | 1.64041666667 | 15182 |
| 015387 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:10am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1594983.7 | 510661.5 | 53687 | 1.64041666667 | 15387 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014858 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:11am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1594985.7 | 510661.2 | 53689 | 1.64041666667 | 14858 |
| 015775 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:12am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1594988.2 | 510662.0 | 53691 | 1.64041666667 | 15775 |
| 015616 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:13am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1594991.5 | 510662.4 | 53693 | 1.64041666667 | 15616 |
| 015039 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:14am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1594993.8 | 510662.3 | 53695 | 1.64041666667 | 15039 |
| 014527 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:15am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1594996.8 | 510663.0 | 53697 | 1.64041666667 | 14527 |
| 014831 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:16am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1594999.1 | 510663.5 | 53699 | 1.64041666667 | 14831 |
| 015092 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:17am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595001.5 | 510663.8 | 53701 | 1.64041666667 | 15092 |
| 014909 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:18am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595003.9 | 510665.3 | 53703 | 1.64041666667 | 14909 |
| 014686 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:19am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595006.1 | 510666.5 | 53705 | 1.64041666667 | 14686 |
| 015521 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:20am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595007.9 | 510666.8 | 53707 | 1.64041666667 | 15521 |
| 015638 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:21am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595009.4 | 510667.8 | 53709 | 1.64041666667 | 15638 |
| 014706 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:22am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595010.7 | 510667.3 | 53711 | 1.64041666667 | 14706 |
| 014235 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:23am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595012.7 | 510667.7 | 53713 | 1.64041666667 | 14235 |
| 013722 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:24am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595014.2 | 510668.5 | 53715 | 1.64041666667 | 13722 |
| 014303 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:25am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595017.8 | 510668.9 | 53717 | 1.64041666667 | 14303 |
| 014600 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:26am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595020.5 | 510669.4 | 53719 | 1.64041666667 | 14600 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:27am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595023.4 | 510670.1 | 53721 | 1.64041666667 | 14355 |
| 014540 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:28am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595025.6 | 510670.3 | 53723 | 1.64041666667 | 14540 |
| 014936 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:29am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595028.7 | 510670.8 | 53725 | 1.64041666667 | 14936 |
| 015331 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:30am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595030.6 | 510671.4 | 53727 | 1.64041666667 | 15331 |
| 014789 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:31am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595033.3 | 510671.6 | 53729 | 1.64041666667 | 14789 |
| 015413 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:32am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595035.6 | 510671.4 | 53731 | 1.64041666667 | 15413 |
| 015172 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:33am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595038.3 | 510671.7 | 53733 | 1.64041666667 | 15172 |
| 015007 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:34am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595040.7 | 510671.3 | 53735 | 1.64041666667 | 15007 |
| 014831 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:35am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595043.8 | 510671.8 | 53737 | 1.64041666667 | 14831 |
| 014530 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:36am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595046.0 | 510673.0 | 53739 | 1.64041666667 | 14530 |
| 014120 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:37am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595048.2 | 510674.6 | 53741 | 1.64041666667 | 14120 |
| 015375 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:38am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595049.4 | 510675.8 | 53743 | 1.64041666667 | 15375 |
| 016486 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:39am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595051.8 | 510677.5 | 53745 | 1.64041666667 | 16486 |
| 015783 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:40am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595054.0 | 510677.6 | 53747 | 1.64041666667 | 15783 |
| 015455 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:41am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595056.9 | 510678.7 | 53749 | 1.64041666667 | 15455 |
| 014303 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:42am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595059.1 | 510680.0 | 53751 | 1.64041666667 | 14303 |
| 014473 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:43am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595062.0 | 510680.6 | 53753 | 1.64041666667 | 14473 |
| 013976 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:44am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595064.7 | 510681.0 | 53755 | 1.64041666667 | 13976 |
| 014086 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:45am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595067.1 | 510682.0 | 53757 | 1.64041666667 | 14086 |
| 015153 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:46am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595069.3 | 510682.4 | 53759 | 1.64041666667 | 15153 |
| 015558 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:47am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595071.8 | 510683.0 | 53761 | 1.64041666667 | 15558 |
| 014549 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:48am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595074.1 | 510684.3 | 53763 | 1.64041666667 | 14549 |
| 014446 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:49am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595076.8 | 510685.8 | 53765 | 1.64041666667 | 14446 |
| 014778 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:50am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595078.6 | 510686.5 | 53767 | 1.64041666667 | 14778 |
| 013848 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:51am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595081.3 | 510688.3 | 53769 | 1.64041666667 | 13848 |
| 014022 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:52am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595082.8 | 510690.0 | 53771 | 1.64041666667 | 14022 |
| 014097 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:53am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595084.9 | 510691.4 | 53773 | 1.64041666667 | 14097 |
| 014192 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:54am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595086.6 | 510693.0 | 53775 | 1.64041666667 | 14192 |
| 014215 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:55am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595089.1 | 510695.2 | 53777 | 1.64041666667 | 14215 |
| 015038 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:56am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595091.0 | 510696.1 | 53779 | 1.64041666667 | 15038 |
| 013926 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:57am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595093.0 | 510698.2 | 53781 | 1.64041666667 | 13926 |
| 014088 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:58am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595094.8 | 510699.7 | 53783 | 1.64041666667 | 14088 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014862 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:59am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595096.9 | 510700.6 | 53785 | 1.64041666667 | 14862 |
| 016017 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:00am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595098.8 | 510702.5 | 53787 | 1.64041666667 | 16017 |
| 015257 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:01am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595101.5 | 510703.9 | 53789 | 1.64041666667 | 15257 |
| 014492 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:02am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595103.6 | 510704.7 | 53791 | 1.64041666667 | 14492 |
| 014594 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:03am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595105.5 | 510706.0 | 53793 | 1.64041666667 | 14594 |
| 014554 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:04am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595106.9 | 510706.7 | 53795 | 1.64041666667 | 14554 |
| 014389 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:05am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595107.9 | 510708.2 | 53797 | 1.64041666667 | 14389 |
| 014506 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:06am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595107.7 | 510710.3 | 53799 | 1.64041666667 | 14506 |
| 014032 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:07am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595107.6 | 510712.4 | 53801 | 1.64041666667 | 14032 |
| 014185 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:08am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595106.7 | 510713.7 | 53803 | 1.64041666667 | 14185 |
| 015082 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:09am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595105.0 | 510714.5 | 53805 | 1.64041666667 | 15082 |
| 014228 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:10am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595103.2 | 510714.5 | 53807 | 1.64041666667 | 14228 |
| 013493 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:11am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595100.8 | 510713.5 | 53809 | 1.64041666667 | 13493 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:12am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595098.5 | 510713.4 | 53811 | 1.64041666667 | 12840 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:13am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595095.9 | 510713.8 | 53813 | 1.64041666667 | 12742 |
| 013355 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:14am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595094.1 | 510712.9 | 53815 | 1.64041666667 | 13355 |
| 013579 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:15am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595091.8 | 510712.3 | 53817 | 1.64041666667 | 13579 |
| 013803 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:16am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595090.1 | 510711.6 | 53819 | 1.64041666667 | 13803 |
| 013329 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:17am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595087.9 | 510710.6 | 53821 | 1.64041666667 | 13329 |
| 013715 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:18am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595086.0 | 510710.6 | 53823 | 1.64041666667 | 13715 |
| 013512 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:19am | Sensor | 1797-S0040-905-G-ACK | 6819.8 | 1595082.8 | 510710.1 | 53825 | 1.64041666667 | 13512 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:20am | Sensor | 1797-S0040-905-G-ACK | 6819.7 | 1595080.7 | 510709.7 | 53827 | 1.64041666667 | 14538 |
| 014890 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:21am | Sensor | 1797-S0040-905-G-ACK | 6819.6 | 1595078.2 | 510710.1 | 53829 | 1.64041666667 | 14890 |
| 013820 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:22am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595075.7 | 510709.3 | 53831 | 1.64041666667 | 13820 |
| 013414 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:23am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595072.9 | 510708.9 | 53833 | 1.64041666667 | 13414 |
| 013043 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:24am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595070.9 | 510708.6 | 53835 | 1.64041666667 | 13043 |
| 013479 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:25am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595069.0 | 510706.9 | 53837 | 1.64041666667 | 13479 |
| 013964 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:26am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1595066.9 | 510705.9 | 53839 | 1.64041666667 | 13964 |
| 012977 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:27am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1595064.5 | 510704.1 | 53841 | 1.64041666667 | 12977 |
| 013997 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:28am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595062.9 | 510702.2 | 53843 | 1.64041666667 | 13997 |
| 013806 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:29am | Sensor | 1797-S0040-905-G-ACK | 6819.3 | 1595060.4 | 510701.0 | 53845 | 1.64041666667 | 13806 |
| 013683 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:30am | Sensor | 1797-S0040-905-G-ACK | 6819.3 | 1595058.4 | 510699.6 | 53847 | 1.64041666667 | 13683 |
| 013404 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:31am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1595056.4 | 510697.7 | 53849 | 1.64041666667 | 13404 |
| 014237 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:32am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1595054.4 | 510697.1 | 53851 | 1.64041666667 | 14237 |
| 014263 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:33am | Sensor | 1797-S0040-905-G-ACK | 6819.3 | 1595052.5 | 510695.0 | 53853 | 1.64041666667 | 14263 |
| 014338 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:34am | Sensor | 1797-S0040-905-G-ACK | 6819.4 | 1595050.7 | 510693.6 | 53855 | 1.64041666667 | 14338 |
| 014590 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:35am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595048.6 | 510692.7 | 53857 | 1.64041666667 | 14590 |
| 013982 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:36am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595047.0 | 510691.2 | 53859 | 1.64041666667 | 13982 |
| 014772 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:37am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595044.2 | 510690.1 | 53861 | 1.64041666667 | 14772 |
| 014474 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:38am | Sensor | 1797-S0040-905-G-ACK | 6819.6 | 1595042.3 | 510689.5 | 53863 | 1.64041666667 | 14474 |
| 014029 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:39am | Sensor | 1797-S0040-905-G-ACK | 6820.0 | 1595040.3 | 510687.5 | 53865 | 1.64041666667 | 14029 |
| 013464 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:40am | Sensor | 1797-S0040-905-G-ACK | 6820.1 | 1595038.2 | 510686.7 | 53867 | 1.64041666667 | 13464 |
| 013468 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:41am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1595035.6 | 510685.5 | 53869 | 1.64041666667 | 13468 |
| 014056 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:42am | Sensor | 1797-S0040-905-G-ACK | 6820.4 | 1595033.8 | 510684.5 | 53871 | 1.64041666667 | 14056 |
| 014746 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:43am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595031.8 | 510684.7 | 53873 | 1.64041666667 | 14746 |
| 014917 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:44am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1595029.8 | 510684.3 | 53875 | 1.64041666667 | 14917 |
| 015028 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:45am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595026.8 | 510683.9 | 53877 | 1.64041666667 | 15028 |
| 014206 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:46am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595024.7 | 510683.9 | 53879 | 1.64041666667 | 14206 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013968 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:47am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595022.5 | 510682.6 | 53881 | 1.64041666667 | 13968 |
| 014112 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:48am | Sensor | 1797-S0040-905-G-ACK | 6820.4 | 1595020.4 | 510681.8 | 53883 | 1.64041666667 | 14112 |
| 013758 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:49am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595018.2 | 510680.9 | 53885 | 1.64041666667 | 13758 |
| 014406 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:50am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595016.6 | 510679.4 | 53887 | 1.64041666667 | 14406 |
| 014036 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:51am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595014.6 | 510678.5 | 53889 | 1.64041666667 | 14036 |
| 014187 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:52am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595013.6 | 510677.1 | 53891 | 1.64041666667 | 14187 |
| 014843 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:53am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595011.5 | 510675.5 | 53893 | 1.64041666667 | 14843 |
| 014304 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:54am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595009.7 | 510673.7 | 53895 | 1.64041666667 | 14304 |
| 014623 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:55am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595009.4 | 510672.5 | 53897 | 1.64041666667 | 14623 |
| 013828 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:56am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595007.9 | 510672.0 | 53899 | 1.64041666667 | 13828 |
| 014438 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:57am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595006.0 | 510669.7 | 53901 | 1.64041666667 | 14438 |
| 014406 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:58am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595004.5 | 510668.6 | 53903 | 1.64041666667 | 14406 |
| 014193 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:59am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595002.3 | 510667.5 | 53905 | 1.64041666667 | 14193 |
| 014786 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:00am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595001.1 | 510666.5 | 53907 | 1.64041666667 | 14786 |
| 014647 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:01am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1594999.2 | 510665.6 | 53909 | 1.64041666667 | 14647 |
| 014164 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:02am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1594998.9 | 510663.4 | 53911 | 1.64041666667 | 14164 |
| 014492 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:03am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1594998.4 | 510660.7 | 53913 | 1.64041666667 | 14492 |
| 014557 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:03am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1594998.0 | 510659.0 | 53914 | 1.64041666667 | 14557 |
| 014593 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:05am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1594998.5 | 510656.0 | 53917 | 1.64041666667 | 14593 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:06am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1594998.1 | 510653.8 | 53919 | 1.64041666667 | 14538 |
| 015588 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:07am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1594998.6 | 510651.5 | 53921 | 1.64041666667 | 15588 |
| 015540 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:08am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1594999.2 | 510649.7 | 53923 | 1.64041666667 | 15540 |
| 015454 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:09am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1594999.9 | 510647.7 | 53925 | 1.64041666667 | 15454 |
| 015322 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:10am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595001.5 | 510647.6 | 53927 | 1.64041666667 | 15322 |
| 014776 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:11am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595003.5 | 510647.9 | 53929 | 1.64041666667 | 14776 |
| 014334 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:12am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595005.2 | 510648.4 | 53931 | 1.64041666667 | 14334 |
| 015285 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:13am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595007.7 | 510649.6 | 53933 | 1.64041666667 | 15285 |
| 014605 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:14am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595009.7 | 510649.5 | 53935 | 1.64041666667 | 14605 |
| 014658 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:15am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595012.3 | 510650.7 | 53937 | 1.64041666667 | 14658 |
| 014027 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:16am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595014.5 | 510651.1 | 53939 | 1.64041666667 | 14027 |
| 013200 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:17am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595017.0 | 510651.0 | 53941 | 1.64041666667 | 13200 |
| 014460 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:18am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595019.3 | 510651.9 | 53943 | 1.64041666667 | 14460 |
| 015011 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:19am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595022.2 | 510652.6 | 53945 | 1.64041666667 | 15011 |
| 015081 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:20am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595024.4 | 510652.7 | 53947 | 1.64041666667 | 15081 |
| 015593 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:21am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595026.9 | 510654.1 | 53949 | 1.64041666667 | 15593 |
| 015386 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:22am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595029.7 | 510654.0 | 53951 | 1.64041666667 | 15386 |
| 015165 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:23am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595032.2 | 510653.9 | 53953 | 1.64041666667 | 15165 |
| 014815 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:23am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595034.0 | 510655.1 | 53954 | 1.64041666667 | 14815 |
| 014948 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:25am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595036.9 | 510655.8 | 53957 | 1.64041666667 | 14948 |
| 015286 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:26am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595039.0 | 510656.6 | 53959 | 1.64041666667 | 15286 |
| 015041 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:27am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595041.3 | 510658.5 | 53961 | 1.64041666667 | 15041 |
| 014618 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:28am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595043.5 | 510659.2 | 53963 | 1.64041666667 | 14618 |
| 014867 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:29am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595045.8 | 510660.6 | 53965 | 1.64041666667 | 14867 |
| 014483 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:30am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595048.0 | 510661.7 | 53967 | 1.64041666667 | 14483 |
| 015271 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:31am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595050.7 | 510661.6 | 53969 | 1.64041666667 | 15271 |
| 015317 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:31am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595052.9 | 510662.0 | 53970 | 1.64041666667 | 15317 |
| 015516 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:33am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595055.8 | 510663.0 | 53973 | 1.64041666667 | 15516 |
| 016003 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:34am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595058.1 | 510662.3 | 53975 | 1.64041666667 | 16003 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015571 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:35am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595061.3 | 510662.2 | 53977 | 1.64041666667 | 15571 |
| 015269 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:36am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595063.7 | 510662.1 | 53979 | 1.64041666667 | 15269 |
| 016156 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:37am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595066.2 | 510661.7 | 53981 | 1.64041666667 | 16156 |
| 016093 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:38am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595068.8 | 510662.2 | 53983 | 1.64041666667 | 16093 |
| 015389 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:39am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595071.7 | 510662.5 | 53985 | 1.64041666667 | 15389 |
| 015166 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:40am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595074.0 | 510662.9 | 53987 | 1.64041666667 | 15166 |
| 015251 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:41am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595076.7 | 510664.6 | 53989 | 1.64041666667 | 15251 |
| 014908 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:42am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595078.6 | 510665.1 | 53991 | 1.64041666667 | 14908 |
| 015871 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:43am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595081.7 | 510665.8 | 53993 | 1.64041666667 | 15871 |
| 015355 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:44am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595083.7 | 510666.8 | 53995 | 1.64041666667 | 15355 |
| 016497 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:45am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595086.2 | 510667.0 | 53997 | 1.64041666667 | 16497 |
| 016052 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:46am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595088.8 | 510667.7 | 53999 | 1.64041666667 | 16052 |
| 015247 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:47am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595091.4 | 510669.1 | 54001 | 1.64041666667 | 15247 |
| 014658 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:48am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595093.8 | 510669.5 | 54003 | 1.64041666667 | 14658 |
| 014958 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:49am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595096.1 | 510670.6 | 54005 | 1.64041666667 | 14958 |
| 014489 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:50am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595097.6 | 510672.0 | 54007 | 1.64041666667 | 14489 |
| 014727 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:51am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595099.4 | 510673.5 | 54009 | 1.64041666667 | 14727 |
| 015086 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:51am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595100.8 | 510675.2 | 54010 | 1.64041666667 | 15086 |
| 015243 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:53am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595103.1 | 510677.9 | 54013 | 1.64041666667 | 15243 |
| 015504 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:53am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595104.6 | 510678.5 | 54014 | 1.64041666667 | 15504 |
| 016289 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:55am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595106.5 | 510680.9 | 54017 | 1.64041666667 | 16289 |
| 016017 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:56am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595108.2 | 510682.6 | 54019 | 1.64041666667 | 16017 |
| 015737 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:57am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595110.6 | 510684.0 | 54021 | 1.64041666667 | 15737 |
| 015542 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:58am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595112.2 | 510686.0 | 54023 | 1.64041666667 | 15542 |
| 015515 | 0 | GeoXH 6000 | 08/19/2015 | 10:22:59am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595114.6 | 510687.4 | 54025 | 1.64041666667 | 15515 |
| 015994 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:00am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595116.8 | 510688.5 | 54027 | 1.64041666667 | 15994 |
| 015657 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:01am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595118.8 | 510690.5 | 54029 | 1.64041666667 | 15657 |
| 015159 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:02am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595120.8 | 510691.4 | 54031 | 1.64041666667 | 15159 |
| 015510 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:03am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595122.8 | 510691.3 | 54033 | 1.64041666667 | 15510 |
| 015339 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:04am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595124.8 | 510690.6 | 54035 | 1.64041666667 | 15339 |
| 015430 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:05am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595126.1 | 510688.1 | 54037 | 1.64041666667 | 15430 |
| 015699 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:06am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595126.4 | 510686.3 | 54039 | 1.64041666667 | 15699 |
| 015378 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:07am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595127.6 | 510684.3 | 54041 | 1.64041666667 | 15378 |
| 015295 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:07am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595127.5 | 510682.4 | 54042 | 1.64041666667 | 15295 |
| 015136 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:09am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595128.1 | 510679.8 | 54045 | 1.64041666667 | 15136 |
| 015076 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:09am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595126.8 | 510678.3 | 54046 | 1.64041666667 | 15076 |
| 014938 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:11am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595124.6 | 510677.7 | 54049 | 1.64041666667 | 14938 |
| 014147 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:12am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595122.6 | 510676.4 | 54051 | 1.64041666667 | 14147 |
| 014325 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:13am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595120.3 | 510676.4 | 54053 | 1.64041666667 | 14325 |
| 014290 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:14am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595118.1 | 510675.4 | 54055 | 1.64041666667 | 14290 |
| 014256 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:15am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595115.0 | 510674.4 | 54057 | 1.64041666667 | 14256 |
| 014626 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:16am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595113.1 | 510674.3 | 54059 | 1.64041666667 | 14626 |
| 015450 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:17am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595110.4 | 510673.3 | 54061 | 1.64041666667 | 15450 |
| 014518 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:18am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595108.3 | 510672.4 | 54063 | 1.64041666667 | 14518 |
| 015434 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:19am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595106.8 | 510671.1 | 54065 | 1.64041666667 | 15434 |
| 015266 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:20am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595105.8 | 510669.5 | 54067 | 1.64041666667 | 15266 |
| 016215 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:21am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595103.8 | 510668.3 | 54069 | 1.64041666667 | 16215 |
| 016283 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:22am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595102.3 | 510666.6 | 54071 | 1.64041666667 | 16283 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015677 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:23am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595100.1 | 510665.0 | 54073 | 1.64041666667 | 15677 |
| 016423 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:23am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595098.2 | 510664.4 | 54074 | 1.64041666667 | 16423 |
| 015530 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:25am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595096.0 | 510662.2 | 54077 | 1.64041666667 | 15530 |
| 015756 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:26am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595094.0 | 510661.0 | 54079 | 1.64041666667 | 15756 |
| 015207 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:27am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595091.4 | 510660.1 | 54081 | 1.64041666667 | 15207 |
| 014989 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:28am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595089.5 | 510658.3 | 54083 | 1.64041666667 | 14989 |
| 016044 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:29am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595086.7 | 510657.6 | 54085 | 1.64041666667 | 16044 |
| 016427 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:30am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595085.2 | 510656.9 | 54087 | 1.64041666667 | 16427 |
| 015562 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:31am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595082.7 | 510655.6 | 54089 | 1.64041666667 | 15562 |
| 016096 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:32am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595080.4 | 510655.3 | 54091 | 1.64041666667 | 16096 |
| 016419 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:33am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595078.0 | 510654.0 | 54093 | 1.64041666667 | 16419 |
| 016271 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:34am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595075.5 | 510653.1 | 54095 | 1.64041666667 | 16271 |
| 016615 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:35am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595073.0 | 510652.7 | 54097 | 1.64041666667 | 16615 |
| 016215 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:36am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595070.9 | 510651.5 | 54099 | 1.64041666667 | 16215 |
| 015939 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:37am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595068.4 | 510650.8 | 54101 | 1.64041666667 | 15939 |
| 015850 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:38am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595066.3 | 510650.2 | 54103 | 1.64041666667 | 15850 |
| 015486 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:39am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595063.5 | 510649.3 | 54105 | 1.64041666667 | 15486 |
| 015408 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:39am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595062.2 | 510649.3 | 54106 | 1.64041666667 | 15408 |
| 015042 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:41am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595059.7 | 510648.9 | 54109 | 1.64041666667 | 15042 |
| 015143 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:41am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595057.4 | 510648.2 | 54110 | 1.64041666667 | 15143 |
| 015403 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:43am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595054.3 | 510648.4 | 54113 | 1.64041666667 | 15403 |
| 016104 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:44am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595052.1 | 510647.9 | 54115 | 1.64041666667 | 16104 |
| 015343 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:45am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595048.9 | 510647.4 | 54117 | 1.64041666667 | 15343 |
| 015613 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:46am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595046.9 | 510647.7 | 54119 | 1.64041666667 | 15613 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:47am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595044.2 | 510646.4 | 54121 | 1.64041666667 | 14602 |
| 014664 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:48am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595041.7 | 510646.0 | 54123 | 1.64041666667 | 14664 |
| 014976 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:49am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595039.1 | 510645.6 | 54125 | 1.64041666667 | 14976 |
| 015181 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:50am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595037.3 | 510644.6 | 54127 | 1.64041666667 | 15181 |
| 015252 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:51am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595035.0 | 510644.4 | 54129 | 1.64041666667 | 15252 |
| 015134 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:52am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595033.1 | 510643.6 | 54131 | 1.64041666667 | 15134 |
| 015285 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:53am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595030.6 | 510642.6 | 54133 | 1.64041666667 | 15285 |
| 014710 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:54am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595029.0 | 510642.5 | 54135 | 1.64041666667 | 14710 |
| 016202 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:55am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595027.3 | 510640.6 | 54137 | 1.64041666667 | 16202 |
| 015038 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:56am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595025.7 | 510640.1 | 54139 | 1.64041666667 | 15038 |
| 014429 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:57am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595024.7 | 510638.7 | 54141 | 1.64041666667 | 14429 |
| 014266 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:58am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595022.7 | 510638.7 | 54143 | 1.64041666667 | 14266 |
| 014865 | 0 | GeoXH 6000 | 08/19/2015 | 10:23:59am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595020.6 | 510637.7 | 54145 | 1.64041666667 | 14865 |
| 014646 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:00am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595019.2 | 510637.2 | 54147 | 1.64041666667 | 14646 |
| 014763 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:01am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595016.7 | 510637.3 | 54149 | 1.64041666667 | 14763 |
| 015474 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:02am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595015.0 | 510636.3 | 54151 | 1.64041666667 | 15474 |
| 016032 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:03am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595012.7 | 510636.6 | 54153 | 1.64041666667 | 16032 |
| 017365 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:04am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595011.4 | 510635.8 | 54155 | 1.64041666667 | 17365 |
| 016803 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:05am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595010.3 | 510633.5 | 54157 | 1.64041666667 | 16803 |
| 015721 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:06am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595010.3 | 510632.1 | 54159 | 1.64041666667 | 15721 |
| 015615 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:07am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595009.8 | 510630.3 | 54161 | 1.64041666667 | 15615 |
| 015459 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:08am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595010.0 | 510628.3 | 54163 | 1.64041666667 | 15459 |
| 015768 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:09am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595009.7 | 510626.7 | 54165 | 1.64041666667 | 15768 |
| 014997 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:10am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595009.8 | 510625.6 | 54167 | 1.64041666667 | 14997 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014286 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:11am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595009.5 | 510623.5 | 54169 | 1.64041666667 | 14286 |
| 015363 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:12am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595009.4 | 510621.1 | 54171 | 1.64041666667 | 15363 |
| 015219 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:13am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595010.7 | 510619.2 | 54173 | 1.64041666667 | 15219 |
| 015483 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:13am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595011.8 | 510618.1 | 54174 | 1.64041666667 | 15483 |
| 016239 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:15am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595014.4 | 510618.0 | 54177 | 1.64041666667 | 16239 |
| 015712 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:16am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595016.6 | 510618.4 | 54179 | 1.64041666667 | 15712 |
| 015003 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:17am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595018.6 | 510618.7 | 54181 | 1.64041666667 | 15003 |
| 015789 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:18am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595020.2 | 510620.0 | 54183 | 1.64041666667 | 15789 |
| 015473 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:19am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595022.7 | 510620.9 | 54185 | 1.64041666667 | 15473 |
| 015769 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:20am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595024.3 | 510622.0 | 54187 | 1.64041666667 | 15769 |
| 015635 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:21am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595026.1 | 510623.8 | 54189 | 1.64041666667 | 15635 |
| 015327 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:22am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595028.1 | 510624.6 | 54191 | 1.64041666667 | 15327 |
| 014921 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:23am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595029.9 | 510626.5 | 54193 | 1.64041666667 | 14921 |
| 014738 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:24am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595031.8 | 510627.6 | 54195 | 1.64041666667 | 14738 |
| 014860 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:25am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595034.6 | 510628.9 | 54197 | 1.64041666667 | 14860 |
| 014598 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:26am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595036.0 | 510630.2 | 54199 | 1.64041666667 | 14598 |
| 014302 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:27am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595038.8 | 510631.1 | 54201 | 1.64041666667 | 14302 |
| 014367 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:28am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595040.6 | 510632.2 | 54203 | 1.64041666667 | 14367 |
| 014989 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:29am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595042.8 | 510633.5 | 54205 | 1.64041666667 | 14989 |
| 014536 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:30am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595045.1 | 510633.3 | 54207 | 1.64041666667 | 14536 |
| 014176 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:31am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595047.4 | 510634.2 | 54209 | 1.64041666667 | 14176 |
| 015594 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:32am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595050.1 | 510634.9 | 54211 | 1.64041666667 | 15594 |
| 016009 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:33am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595052.7 | 510635.0 | 54213 | 1.64041666667 | 16009 |
| 015282 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:34am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595054.8 | 510635.9 | 54215 | 1.64041666667 | 15282 |
| 015159 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:35am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595057.6 | 510636.5 | 54217 | 1.64041666667 | 15159 |
| 015389 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:36am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595059.6 | 510636.3 | 54219 | 1.64041666667 | 15389 |
| 015128 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:37am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595062.7 | 510637.3 | 54221 | 1.64041666667 | 15128 |
| 015514 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:38am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595065.3 | 510637.7 | 54223 | 1.64041666667 | 15514 |
| 015379 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:39am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595067.8 | 510637.9 | 54225 | 1.64041666667 | 15379 |
| 014546 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:39am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595069.7 | 510639.3 | 54226 | 1.64041666667 | 14546 |
| 014527 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:41am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595072.8 | 510640.3 | 54229 | 1.64041666667 | 14527 |
| 014261 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:41am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595074.9 | 510640.4 | 54230 | 1.64041666667 | 14261 |
| 014742 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:43am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595076.6 | 510641.6 | 54233 | 1.64041666667 | 14742 |
| 014982 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:43am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595077.1 | 510641.5 | 54234 | 1.64041666667 | 14982 |
| 015200 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:45am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595077.1 | 510641.9 | 54237 | 1.64041666667 | 15200 |
| 015472 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:46am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595076.8 | 510641.9 | 54239 | 1.64041666667 | 15472 |
| 014321 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:47am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595076.6 | 510640.7 | 54241 | 1.64041666667 | 14321 |
| 014213 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:48am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595076.6 | 510640.3 | 54243 | 1.64041666667 | 14213 |
| 015135 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:49am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595075.9 | 510640.0 | 54245 | 1.64041666667 | 15135 |
| 014970 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:50am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595076.4 | 510639.6 | 54247 | 1.64041666667 | 14970 |
| 014893 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:51am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595076.2 | 510639.6 | 54249 | 1.64041666667 | 14893 |
| 014640 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:52am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595075.1 | 510639.8 | 54251 | 1.64041666667 | 14640 |
| 014490 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:53am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595073.4 | 510640.4 | 54253 | 1.64041666667 | 14490 |
| 014180 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:54am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595073.1 | 510640.7 | 54255 | 1.64041666667 | 14180 |
| 014741 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:55am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595073.6 | 510640.5 | 54257 | 1.64041666667 | 14741 |
| 015049 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:56am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595075.5 | 510640.3 | 54259 | 1.64041666667 | 15049 |
| 015313 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:57am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595077.3 | 510642.1 | 54261 | 1.64041666667 | 15313 |
| 014988 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:58am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595079.3 | 510641.8 | 54263 | 1.64041666667 | 14988 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015376 | 0 | GeoXH 6000 | 08/19/2015 | 10:24:59am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595082.1 | 510642.5 | 54265 | 1.64041666667 | 15376 |
| 015841 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:00am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595084.1 | 510644.1 | 54267 | 1.64041666667 | 15841 |
| 015000 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:01am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595085.9 | 510644.9 | 54269 | 1.64041666667 | 15000 |
| 014558 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:02am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595087.7 | 510646.1 | 54271 | 1.64041666667 | 14558 |
| 014639 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:03am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595089.8 | 510647.5 | 54273 | 1.64041666667 | 14639 |
| 015247 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:04am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595091.8 | 510648.0 | 54275 | 1.64041666667 | 15247 |
| 014883 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:05am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595092.9 | 510649.6 | 54277 | 1.64041666667 | 14883 |
| 014859 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:06am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595094.5 | 510649.6 | 54279 | 1.64041666667 | 14859 |
| 014471 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:07am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595096.6 | 510650.8 | 54281 | 1.64041666667 | 14471 |
| 014875 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:08am | Sensor | 1797-S0040-905-G-ACK | 6822.8 | 1595099.0 | 510651.1 | 54283 | 1.64041666667 | 14875 |
| 015147 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:09am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595101.4 | 510651.8 | 54285 | 1.64041666667 | 15147 |
| 015517 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:10am | Sensor | 1797-S0040-905-G-ACK | 6822.8 | 1595103.9 | 510653.2 | 54287 | 1.64041666667 | 15517 |
| 015553 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:11am | Sensor | 1797-S0040-905-G-ACK | 6822.8 | 1595105.9 | 510653.4 | 54289 | 1.64041666667 | 15553 |
| 014831 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:12am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595108.0 | 510654.5 | 54291 | 1.64041666667 | 14831 |
| 015317 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:13am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595109.9 | 510656.4 | 54293 | 1.64041666667 | 15317 |
| 014721 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:14am | Sensor | 1797-S0040-905-G-ACK | 6822.8 | 1595111.8 | 510657.5 | 54295 | 1.64041666667 | 14721 |
| 015090 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:15am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595113.0 | 510659.3 | 54297 | 1.64041666667 | 15090 |
| 014578 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:16am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595114.8 | 510661.2 | 54299 | 1.64041666667 | 14578 |
| 016090 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:17am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595116.8 | 510662.5 | 54301 | 1.64041666667 | 16090 |
| 015335 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:17am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595118.8 | 510663.7 | 54302 | 1.64041666667 | 15335 |
| 015804 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:19am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595120.8 | 510665.8 | 54305 | 1.64041666667 | 15804 |
| 015534 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:20am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595123.7 | 510666.5 | 54307 | 1.64041666667 | 15534 |
| 015075 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:21am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595125.9 | 510667.2 | 54309 | 1.64041666667 | 15075 |
| 014742 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:22am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595128.1 | 510668.4 | 54311 | 1.64041666667 | 14742 |
| 014525 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:23am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595130.1 | 510666.8 | 54313 | 1.64041666667 | 14525 |
| 014538 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:23am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595131.0 | 510665.1 | 54314 | 1.64041666667 | 14538 |
| 014612 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:25am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595132.1 | 510662.4 | 54317 | 1.64041666667 | 14612 |
| 014857 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:26am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595131.6 | 510660.2 | 54319 | 1.64041666667 | 14857 |
| 015309 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:27am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595131.1 | 510658.1 | 54321 | 1.64041666667 | 15309 |
| 015376 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:28am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595129.4 | 510656.6 | 54323 | 1.64041666667 | 15376 |
| 015031 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:29am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595127.5 | 510655.8 | 54325 | 1.64041666667 | 15031 |
| 014845 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:30am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595125.6 | 510654.2 | 54327 | 1.64041666667 | 14845 |
| 015048 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:31am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595123.3 | 510653.6 | 54329 | 1.64041666667 | 15048 |
| 014149 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:32am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595121.1 | 510653.5 | 54331 | 1.64041666667 | 14149 |
| 014514 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:33am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595119.0 | 510652.3 | 54333 | 1.64041666667 | 14514 |
| 014846 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:34am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595116.7 | 510652.1 | 54335 | 1.64041666667 | 14846 |
| 015543 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:35am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595114.4 | 510651.2 | 54337 | 1.64041666667 | 15543 |
| 016183 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:36am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595112.8 | 510649.8 | 54339 | 1.64041666667 | 16183 |
| 015658 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:37am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595110.3 | 510649.4 | 54341 | 1.64041666667 | 15658 |
| 015287 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:38am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595108.7 | 510648.4 | 54343 | 1.64041666667 | 15287 |
| 015581 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:39am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595106.3 | 510646.6 | 54345 | 1.64041666667 | 15581 |
| 015619 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:40am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595104.1 | 510645.7 | 54347 | 1.64041666667 | 15619 |
| 014853 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:41am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595102.1 | 510644.0 | 54349 | 1.64041666667 | 14853 |
| 015285 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:42am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595100.0 | 510642.5 | 54351 | 1.64041666667 | 15285 |
| 015775 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:43am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595097.9 | 510641.9 | 54353 | 1.64041666667 | 15775 |
| 015301 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:44am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595095.9 | 510640.2 | 54355 | 1.64041666667 | 15301 |
| 015416 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:45am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595093.7 | 510639.2 | 54357 | 1.64041666667 | 15416 |
| 014837 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:46am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595091.5 | 510638.2 | 54359 | 1.64041666667 | 14837 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014421 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:47am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595089.4 | 510636.8 | 54361 | 1.64041666667 | 14421 |
| 015731 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:48am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595087.5 | 510636.3 | 54363 | 1.64041666667 | 15731 |
| 015674 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:49am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595085.3 | 510634.2 | 54365 | 1.64041666667 | 15674 |
| 015236 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:50am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595083.4 | 510632.7 | 54367 | 1.64041666667 | 15236 |
| 014540 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:51am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595081.4 | 510632.0 | 54369 | 1.64041666667 | 14540 |
| 014089 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:52am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595079.6 | 510630.5 | 54371 | 1.64041666667 | 14089 |
| 014360 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:53am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595077.2 | 510629.9 | 54373 | 1.64041666667 | 14360 |
| 014467 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:54am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595075.2 | 510629.6 | 54375 | 1.64041666667 | 14467 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:55am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595072.7 | 510628.7 | 54377 | 1.64041666667 | 14355 |
| 015102 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:56am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595070.2 | 510629.0 | 54379 | 1.64041666667 | 15102 |
| 014337 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:57am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595067.5 | 510628.6 | 54381 | 1.64041666667 | 14337 |
| 014920 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:58am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595065.0 | 510628.1 | 54383 | 1.64041666667 | 14920 |
| 015630 | 0 | GeoXH 6000 | 08/19/2015 | 10:25:59am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595062.2 | 510627.6 | 54385 | 1.64041666667 | 15630 |
| 014992 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:00am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595060.7 | 510626.4 | 54387 | 1.64041666667 | 14992 |
| 015683 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:01am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595058.2 | 510626.0 | 54389 | 1.64041666667 | 15683 |
| 015504 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:01am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595056.3 | 510625.7 | 54390 | 1.64041666667 | 15504 |
| 015958 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:03am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595054.1 | 510624.0 | 54393 | 1.64041666667 | 15958 |
| 015576 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:03am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595052.1 | 510623.6 | 54394 | 1.64041666667 | 15576 |
| 016359 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:05am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595049.2 | 510622.6 | 54397 | 1.64041666667 | 16359 |
| 016297 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:06am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595046.8 | 510621.7 | 54399 | 1.64041666667 | 16297 |
| 017199 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:07am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595044.2 | 510621.5 | 54401 | 1.64041666667 | 17199 |
| 016800 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:08am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595042.4 | 510620.5 | 54403 | 1.64041666667 | 16800 |
| 016080 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:09am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595040.0 | 510619.1 | 54405 | 1.64041666667 | 16080 |
| 015412 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:09am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595038.1 | 510618.9 | 54406 | 1.64041666667 | 15412 |
| 015217 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:11am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595036.1 | 510616.9 | 54409 | 1.64041666667 | 15217 |
| 015204 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:12am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595033.8 | 510616.2 | 54411 | 1.64041666667 | 15204 |
| 014665 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:13am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595031.8 | 510614.8 | 54413 | 1.64041666667 | 14665 |
| 014789 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:14am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595030.2 | 510613.9 | 54415 | 1.64041666667 | 14789 |
| 014836 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:15am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595028.6 | 510613.1 | 54417 | 1.64041666667 | 14836 |
| 015778 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:16am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595026.9 | 510611.9 | 54419 | 1.64041666667 | 15778 |
| 016982 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:17am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595025.4 | 510611.5 | 54421 | 1.64041666667 | 16982 |
| 016632 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:18am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595025.1 | 510610.8 | 54423 | 1.64041666667 | 16632 |
| 015708 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:19am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595025.2 | 510610.6 | 54425 | 1.64041666667 | 15708 |
| 016426 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:20am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595025.4 | 510610.4 | 54427 | 1.64041666667 | 16426 |
| 015704 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:21am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595025.3 | 510610.4 | 54429 | 1.64041666667 | 15704 |
| 015194 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:22am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595025.1 | 510610.5 | 54431 | 1.64041666667 | 15194 |
| 015746 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:23am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595024.1 | 510610.5 | 54433 | 1.64041666667 | 15746 |
| 016387 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:24am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595023.7 | 510609.7 | 54435 | 1.64041666667 | 16387 |
| 017145 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:25am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595022.8 | 510609.5 | 54437 | 1.64041666667 | 17145 |
| 017174 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:26am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595022.8 | 510608.7 | 54439 | 1.64041666667 | 17174 |
| 016305 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:27am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595022.9 | 510608.4 | 54441 | 1.64041666667 | 16305 |
| 016229 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:28am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595022.5 | 510609.2 | 54443 | 1.64041666667 | 16229 |
| 016719 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:29am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595022.4 | 510609.5 | 54445 | 1.64041666667 | 16719 |
| 016439 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:30am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595022.3 | 510609.4 | 54447 | 1.64041666667 | 16439 |
| 016807 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:31am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595021.8 | 510608.2 | 54449 | 1.64041666667 | 16807 |
| 016451 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:32am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595021.4 | 510607.9 | 54451 | 1.64041666667 | 16451 |
| 015831 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:33am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595020.7 | 510608.7 | 54453 | 1.64041666667 | 15831 |
| 015835 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:34am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595020.6 | 510608.9 | 54455 | 1.64041666667 | 15835 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015574 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:35am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595020.5 | 510608.8 | 54457 | 1.64041666667 | 15574 |
| 016230 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:36am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595019.6 | 510608.3 | 54459 | 1.64041666667 | 16230 |
| 016037 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:37am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595018.1 | 510608.3 | 54461 | 1.64041666667 | 16037 |
| 016153 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:38am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595017.4 | 510607.0 | 54463 | 1.64041666667 | 16153 |
| 016683 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:39am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595016.9 | 510604.8 | 54465 | 1.64041666667 | 16683 |
| 016284 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:39am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595017.8 | 510603.3 | 54466 | 1.64041666667 | 16284 |
| 015835 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:41am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595018.0 | 510601.2 | 54469 | 1.64041666667 | 15835 |
| 015529 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:41am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595018.8 | 510599.8 | 54470 | 1.64041666667 | 15529 |
| 015335 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:43am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595020.1 | 510598.1 | 54473 | 1.64041666667 | 15335 |
| 015676 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:43am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595020.9 | 510596.5 | 54474 | 1.64041666667 | 15676 |
| 016167 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:45am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595022.7 | 510596.2 | 54477 | 1.64041666667 | 16167 |
| 016159 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:46am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595024.2 | 510595.7 | 54479 | 1.64041666667 | 16159 |
| 015997 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:47am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595026.1 | 510596.6 | 54481 | 1.64041666667 | 15997 |
| 015981 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:48am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595027.6 | 510596.9 | 54483 | 1.64041666667 | 15981 |
| 015499 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:49am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595029.9 | 510598.3 | 54485 | 1.64041666667 | 15499 |
| 014891 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:50am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595032.0 | 510599.8 | 54487 | 1.64041666667 | 14891 |
| 015238 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:51am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595034.0 | 510600.2 | 54489 | 1.64041666667 | 15238 |
| 014954 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:52am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595035.5 | 510601.5 | 54491 | 1.64041666667 | 14954 |
| 014629 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:53am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595038.3 | 510602.5 | 54493 | 1.64041666667 | 14629 |
| 014739 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:54am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595040.7 | 510603.1 | 54495 | 1.64041666667 | 14739 |
| 014838 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:55am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595042.8 | 510604.6 | 54497 | 1.64041666667 | 14838 |
| 015914 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:55am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595044.6 | 510605.3 | 54498 | 1.64041666667 | 15914 |
| 015679 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:57am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595047.1 | 510606.5 | 54501 | 1.64041666667 | 15679 |
| 015712 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:58am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595048.3 | 510607.4 | 54503 | 1.64041666667 | 15712 |
| 014613 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:59am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595049.5 | 510607.5 | 54505 | 1.64041666667 | 14613 |
| 015787 | 0 | GeoXH 6000 | 08/19/2015 | 10:26:59am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595049.8 | 510607.6 | 54506 | 1.64041666667 | 15787 |
| 015075 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:01am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595049.9 | 510607.4 | 54509 | 1.64041666667 | 15075 |
| 016354 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:02am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595049.9 | 510607.3 | 54511 | 1.64041666667 | 16354 |
| 015769 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:03am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595050.4 | 510607.7 | 54513 | 1.64041666667 | 15769 |
| 015568 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:04am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595051.3 | 510608.5 | 54515 | 1.64041666667 | 15568 |
| 015124 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:05am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595052.4 | 510608.6 | 54517 | 1.64041666667 | 15124 |
| 014605 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:05am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595052.7 | 510609.4 | 54518 | 1.64041666667 | 14605 |
| 016465 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:07am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595054.6 | 510609.4 | 54521 | 1.64041666667 | 16465 |
| 016709 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:07am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595055.8 | 510610.5 | 54522 | 1.64041666667 | 16709 |
| 016546 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:09am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595057.6 | 510610.7 | 54525 | 1.64041666667 | 16546 |
| 016312 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:10am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595058.3 | 510611.8 | 54527 | 1.64041666667 | 16312 |
| 015910 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:11am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595059.4 | 510611.7 | 54529 | 1.64041666667 | 15910 |
| 015107 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:12am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595060.6 | 510612.5 | 54531 | 1.64041666667 | 15107 |
| 015630 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:13am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595062.1 | 510612.6 | 54533 | 1.64041666667 | 15630 |
| 016037 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:14am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595063.4 | 510613.5 | 54535 | 1.64041666667 | 16037 |
| 015801 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:15am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595065.0 | 510613.8 | 54537 | 1.64041666667 | 15801 |
| 015428 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:16am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595066.2 | 510615.1 | 54539 | 1.64041666667 | 15428 |
| 015705 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:17am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595068.0 | 510615.0 | 54541 | 1.64041666667 | 15705 |
| 015824 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:18am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595069.0 | 510616.1 | 54543 | 1.64041666667 | 15824 |
| 015921 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:19am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595070.8 | 510616.1 | 54545 | 1.64041666667 | 15921 |
| 016418 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:20am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595071.7 | 510617.5 | 54547 | 1.64041666667 | 16418 |
| 015925 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:21am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595074.1 | 510617.7 | 54549 | 1.64041666667 | 15925 |
| 016105 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:22am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595076.0 | 510619.0 | 54551 | 1.64041666667 | 16105 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015929 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:23am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595078.5 | 510619.5 | 54553 | 1.64041666667 | 15929 |
| 015327 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:24am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595080.7 | 510619.4 | 54555 | 1.64041666667 | 15327 |
| 015214 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:25am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595082.8 | 510620.4 | 54557 | 1.64041666667 | 15214 |
| 014370 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:26am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595085.3 | 510620.5 | 54559 | 1.64041666667 | 14370 |
| 016003 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:27am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595087.3 | 510621.7 | 54561 | 1.64041666667 | 16003 |
| 015737 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:28am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595089.4 | 510622.4 | 54563 | 1.64041666667 | 15737 |
| 015422 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:29am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595091.5 | 510622.4 | 54565 | 1.64041666667 | 15422 |
| 014630 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:30am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595093.3 | 510623.5 | 54567 | 1.64041666667 | 14630 |
| 014761 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:31am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595095.8 | 510623.9 | 54569 | 1.64041666667 | 14761 |
| 014911 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:31am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595097.9 | 510624.5 | 54570 | 1.64041666667 | 14911 |
| 014980 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:33am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595100.6 | 510626.0 | 54573 | 1.64041666667 | 14980 |
| 015371 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:34am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595102.7 | 510626.3 | 54575 | 1.64041666667 | 15371 |
| 014916 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:35am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595105.1 | 510627.9 | 54577 | 1.64041666667 | 14916 |
| 014600 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:35am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595107.2 | 510629.0 | 54578 | 1.64041666667 | 14600 |
| 014752 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:37am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595109.7 | 510629.4 | 54581 | 1.64041666667 | 14752 |
| 014658 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:38am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595111.6 | 510630.8 | 54583 | 1.64041666667 | 14658 |
| 014703 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:39am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595113.7 | 510631.6 | 54585 | 1.64041666667 | 14703 |
| 014817 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:39am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595115.7 | 510632.5 | 54586 | 1.64041666667 | 14817 |
| 014695 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:41am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595117.8 | 510634.1 | 54589 | 1.64041666667 | 14695 |
| 014686 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:41am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595119.9 | 510634.3 | 54590 | 1.64041666667 | 14686 |
| 015093 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:43am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595122.0 | 510635.9 | 54593 | 1.64041666667 | 15093 |
| 014145 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:44am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595124.2 | 510637.2 | 54595 | 1.64041666667 | 14145 |
| 014796 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:45am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595126.9 | 510638.4 | 54597 | 1.64041666667 | 14796 |
| 014413 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:46am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595128.6 | 510639.9 | 54599 | 1.64041666667 | 14413 |
| 014167 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:47am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595130.9 | 510640.8 | 54601 | 1.64041666667 | 14167 |
| 014074 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:48am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595133.0 | 510641.6 | 54603 | 1.64041666667 | 14074 |
| 014344 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:49am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595135.2 | 510642.4 | 54605 | 1.64041666667 | 14344 |
| 013588 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:50am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595137.0 | 510642.1 | 54607 | 1.64041666667 | 13588 |
| 013613 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:51am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595139.4 | 510641.6 | 54609 | 1.64041666667 | 13613 |
| 012922 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:51am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595140.3 | 510640.0 | 54610 | 1.64041666667 | 12922 |
| 014056 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:53am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595141.2 | 510637.8 | 54613 | 1.64041666667 | 14056 |
| 014221 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:53am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595142.1 | 510635.9 | 54614 | 1.64041666667 | 14221 |
| 013707 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:55am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595141.5 | 510633.8 | 54617 | 1.64041666667 | 13707 |
| 013515 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:56am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595141.5 | 510631.9 | 54619 | 1.64041666667 | 13515 |
| 013932 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:57am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595139.8 | 510632.2 | 54621 | 1.64041666667 | 13932 |
| 013732 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:58am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595138.5 | 510631.8 | 54623 | 1.64041666667 | 13732 |
| 014256 | 0 | GeoXH 6000 | 08/19/2015 | 10:27:59am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595136.6 | 510631.5 | 54625 | 1.64041666667 | 14256 |
| 014237 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:00am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595134.7 | 510630.7 | 54627 | 1.64041666667 | 14237 |
| 014210 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:01am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595132.9 | 510629.3 | 54629 | 1.64041666667 | 14210 |
| 014676 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:01am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595130.8 | 510629.3 | 54630 | 1.64041666667 | 14676 |
| 015425 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:03am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595128.6 | 510628.0 | 54633 | 1.64041666667 | 15425 |
| 016139 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:04am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595126.5 | 510627.2 | 54635 | 1.64041666667 | 16139 |
| 016383 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:05am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595124.3 | 510626.1 | 54637 | 1.64041666667 | 16383 |
| 015733 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:05am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595123.0 | 510624.5 | 54638 | 1.64041666667 | 15733 |
| 014917 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:07am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595120.5 | 510623.6 | 54641 | 1.64041666667 | 14917 |
| 014668 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:07am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595118.9 | 510622.8 | 54642 | 1.64041666667 | 14668 |
| 014948 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:09am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595116.6 | 510621.1 | 54645 | 1.64041666667 | 14948 |
| 015046 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:09am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595114.8 | 510621.2 | 54646 | 1.64041666667 | 15046 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015453 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:11am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595112.5 | 510620.2 | 54649 | 1.64041666667 | 15453 |
| 015547 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:11am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595110.5 | 510619.3 | 54650 | 1.64041666667 | 15547 |
| 015503 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:13am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595108.1 | 510618.5 | 54653 | 1.64041666667 | 15503 |
| 015575 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:13am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595106.6 | 510617.0 | 54654 | 1.64041666667 | 15575 |
| 015616 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:15am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595104.0 | 510616.4 | 54657 | 1.64041666667 | 15616 |
| 015864 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:15am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595102.5 | 510615.2 | 54658 | 1.64041666667 | 15864 |
| 016041 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:17am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595099.8 | 510614.0 | 54661 | 1.64041666667 | 16041 |
| 016290 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:18am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595097.7 | 510613.3 | 54663 | 1.64041666667 | 16290 |
| 015321 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:19am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595095.7 | 510612.2 | 54665 | 1.64041666667 | 15321 |
| 015338 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:19am | Sensor | 1797-S0040-905-G-ACK | 6822.8 | 1595093.7 | 510612.3 | 54666 | 1.64041666667 | 15338 |
| 015565 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:21am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595091.3 | 510610.9 | 54669 | 1.64041666667 | 15565 |
| 015730 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:21am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595089.3 | 510609.9 | 54670 | 1.64041666667 | 15730 |
| 015575 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:23am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595086.5 | 510609.5 | 54673 | 1.64041666667 | 15575 |
| 015571 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:23am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595084.7 | 510608.4 | 54674 | 1.64041666667 | 15571 |
| 015104 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:25am | Sensor | 1797-S0040-905-G-ACK | 6822.8 | 1595081.6 | 510608.0 | 54677 | 1.64041666667 | 15104 |
| 015906 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:25am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595079.8 | 510607.1 | 54678 | 1.64041666667 | 15906 |
| 015479 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:27am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595077.1 | 510606.1 | 54681 | 1.64041666667 | 15479 |
| 015795 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:27am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595075.2 | 510606.2 | 54682 | 1.64041666667 | 15795 |
| 015462 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:29am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595072.5 | 510604.7 | 54685 | 1.64041666667 | 15462 |
| 015694 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:29am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595070.5 | 510604.2 | 54686 | 1.64041666667 | 15694 |
| 015278 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:31am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595067.2 | 510603.7 | 54689 | 1.64041666667 | 15278 |
| 015404 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:31am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595065.8 | 510602.7 | 54690 | 1.64041666667 | 15404 |
| 014852 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:33am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595062.9 | 510602.3 | 54693 | 1.64041666667 | 14852 |
| 015539 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:33am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595060.8 | 510601.8 | 54694 | 1.64041666667 | 15539 |
| 016076 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:35am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595058.3 | 510600.1 | 54697 | 1.64041666667 | 16076 |
| 015830 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:36am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595056.6 | 510600.0 | 54699 | 1.64041666667 | 15830 |
| 015144 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:37am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595054.4 | 510598.5 | 54701 | 1.64041666667 | 15144 |
| 014976 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:37am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595052.8 | 510597.6 | 54702 | 1.64041666667 | 14976 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:39am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595049.9 | 510596.8 | 54705 | 1.64041666667 | 14049 |
| 014270 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:40am | Sensor | 1797-S0040-905-G-ACK | 6822.8 | 1595047.7 | 510596.2 | 54707 | 1.64041666667 | 14270 |
| 016299 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:41am | Sensor | 1797-S0040-905-G-ACK | 6823.0 | 1595045.3 | 510596.3 | 54709 | 1.64041666667 | 16299 |
| 015296 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:42am | Sensor | 1797-S0040-905-G-ACK | 6823.3 | 1595043.6 | 510595.4 | 54711 | 1.64041666667 | 15296 |
| 014791 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:43am | Sensor | 1797-S0040-905-G-ACK | 6823.5 | 1595042.4 | 510595.4 | 54713 | 1.64041666667 | 14791 |
| 015625 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:44am | Sensor | 1797-S0040-905-G-ACK | 6823.4 | 1595041.1 | 510594.2 | 54715 | 1.64041666667 | 15625 |
| 015186 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:45am | Sensor | 1797-S0040-905-G-ACK | 6823.4 | 1595039.3 | 510593.8 | 54717 | 1.64041666667 | 15186 |
| 015112 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:45am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595038.5 | 510592.5 | 54718 | 1.64041666667 | 15112 |
| 015633 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:47am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595036.2 | 510590.7 | 54721 | 1.64041666667 | 15633 |
| 015783 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:48am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595034.5 | 510589.4 | 54723 | 1.64041666667 | 15783 |
| 016776 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:49am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595033.4 | 510587.3 | 54725 | 1.64041666667 | 16776 |
| 016794 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:50am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595031.7 | 510586.5 | 54727 | 1.64041666667 | 16794 |
| 016541 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:51am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595031.3 | 510584.9 | 54729 | 1.64041666667 | 16541 |
| 015724 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:51am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595030.4 | 510583.4 | 54730 | 1.64041666667 | 15724 |
| 015557 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:53am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595031.3 | 510581.8 | 54733 | 1.64041666667 | 15557 |
| 016041 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:53am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595032.4 | 510580.5 | 54734 | 1.64041666667 | 16041 |
| 016470 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:55am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595033.4 | 510579.7 | 54737 | 1.64041666667 | 16470 |
| 015512 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:56am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595033.4 | 510578.2 | 54739 | 1.64041666667 | 15512 |
| 016060 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:57am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595034.0 | 510576.1 | 54741 | 1.64041666667 | 16060 |
| 016279 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:57am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595035.4 | 510574.8 | 54742 | 1.64041666667 | 16279 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015547 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:59am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595037.1 | 510573.6 | 54745 | 1.64041666667 | 15547 |
| 015855 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:00am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595038.7 | 510573.8 | 54747 | 1.64041666667 | 15855 |
| 015421 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:01am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595040.5 | 510573.5 | 54749 | 1.64041666667 | 15421 |
| 014726 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:01am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595041.6 | 510574.7 | 54750 | 1.64041666667 | 14726 |
| 015708 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:03am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595043.1 | 510577.1 | 54753 | 1.64041666667 | 15708 |
| 015203 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:03am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595044.4 | 510578.4 | 54754 | 1.64041666667 | 15203 |
| 015579 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:05am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595045.4 | 510580.7 | 54757 | 1.64041666667 | 15579 |
| 015393 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:05am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595047.1 | 510581.8 | 54758 | 1.64041666667 | 15393 |
| 015468 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:07am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595048.4 | 510583.7 | 54761 | 1.64041666667 | 15468 |
| 015286 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:07am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595050.3 | 510585.7 | 54762 | 1.64041666667 | 15286 |
| 014793 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:09am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595052.9 | 510586.8 | 54765 | 1.64041666667 | 14793 |
| 015311 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:09am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595054.3 | 510588.3 | 54766 | 1.64041666667 | 15311 |
| 015460 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:11am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595056.7 | 510589.2 | 54769 | 1.64041666667 | 15460 |
| 016188 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:11am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595058.2 | 510590.2 | 54770 | 1.64041666667 | 16188 |
| 016441 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:13am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595060.5 | 510591.3 | 54773 | 1.64041666667 | 16441 |
| 017535 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:13am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595062.4 | 510591.1 | 54774 | 1.64041666667 | 17535 |
| 017161 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:15am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595063.7 | 510591.6 | 54777 | 1.64041666667 | 17161 |
| 016965 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:16am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595063.3 | 510591.0 | 54779 | 1.64041666667 | 16965 |
| 016405 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:17am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595063.0 | 510590.9 | 54781 | 1.64041666667 | 16405 |
| 015858 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:18am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595063.9 | 510590.4 | 54783 | 1.64041666667 | 15858 |
| 016360 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:19am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595063.6 | 510590.3 | 54785 | 1.64041666667 | 16360 |
| 017032 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:20am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595062.9 | 510590.3 | 54787 | 1.64041666667 | 17032 |
| 016473 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:21am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595062.1 | 510591.3 | 54789 | 1.64041666667 | 16473 |
| 016091 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:22am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595061.3 | 510590.7 | 54791 | 1.64041666667 | 16091 |
| 015479 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:23am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595059.9 | 510590.8 | 54793 | 1.64041666667 | 15479 |
| 015149 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:24am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595058.7 | 510590.1 | 54795 | 1.64041666667 | 15149 |
| 015211 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:25am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595059.1 | 510589.9 | 54797 | 1.64041666667 | 15211 |
| 015719 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:26am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595060.1 | 510590.0 | 54799 | 1.64041666667 | 15719 |
| 014872 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:27am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595061.4 | 510590.2 | 54801 | 1.64041666667 | 14872 |
| 015340 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:28am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595062.2 | 510589.8 | 54803 | 1.64041666667 | 15340 |
| 014921 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:29am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595062.6 | 510589.6 | 54805 | 1.64041666667 | 14921 |
| 014250 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:29am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595062.6 | 510590.2 | 54806 | 1.64041666667 | 14250 |
| 014976 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:31am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595063.7 | 510590.8 | 54809 | 1.64041666667 | 14976 |
| 015901 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:32am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595064.6 | 510591.8 | 54811 | 1.64041666667 | 15901 |
| 015462 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:33am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595065.9 | 510592.0 | 54813 | 1.64041666667 | 15462 |
| 015965 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:33am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595066.8 | 510593.1 | 54814 | 1.64041666667 | 15965 |
| 015145 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:35am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595068.3 | 510593.2 | 54817 | 1.64041666667 | 15145 |
| 015134 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:36am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595069.3 | 510594.0 | 54819 | 1.64041666667 | 15134 |
| 015225 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:37am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595070.9 | 510594.2 | 54821 | 1.64041666667 | 15225 |
| 015929 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:38am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595072.0 | 510595.1 | 54823 | 1.64041666667 | 15929 |
| 015027 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:39am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595074.3 | 510595.9 | 54825 | 1.64041666667 | 15027 |
| 015098 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:40am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595075.7 | 510597.2 | 54827 | 1.64041666667 | 15098 |
| 014785 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:41am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595078.0 | 510597.7 | 54829 | 1.64041666667 | 14785 |
| 014946 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:41am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595079.9 | 510598.6 | 54830 | 1.64041666667 | 14946 |
| 015457 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:42am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595082.4 | 510600.0 | 54832 | 1.64041666667 | 15457 |
| 015242 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:43am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595084.4 | 510600.2 | 54834 | 1.64041666667 | 15242 |
| 015743 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:45am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595087.0 | 510601.9 | 54837 | 1.64041666667 | 15743 |
| 015583 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:45am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595089.1 | 510602.0 | 54838 | 1.64041666667 | 15583 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015935 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:47am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595091.8 | 510603.1 | 54841 | 1.64041666667 | 15935 |
| 017131 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:48am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595093.8 | 510604.4 | 54843 | 1.64041666667 | 17131 |
| 017136 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:49am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595096.1 | 510604.8 | 54845 | 1.64041666667 | 17136 |
| 016674 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:49am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595097.6 | 510606.3 | 54846 | 1.64041666667 | 16674 |
| 015821 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:51am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595099.8 | 510606.8 | 54849 | 1.64041666667 | 15821 |
| 014689 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:52am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595101.9 | 510607.9 | 54851 | 1.64041666667 | 14689 |
| 015095 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:53am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595104.7 | 510607.8 | 54853 | 1.64041666667 | 15095 |
| 015466 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:53am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595106.6 | 510607.1 | 54854 | 1.64041666667 | 15466 |
| 015592 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:55am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595109.5 | 510607.4 | 54857 | 1.64041666667 | 15592 |
| 014958 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:55am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595111.3 | 510606.8 | 54858 | 1.64041666667 | 14958 |
| 015231 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:57am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595114.0 | 510607.1 | 54861 | 1.64041666667 | 15231 |
| 015077 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:57am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595115.7 | 510608.6 | 54862 | 1.64041666667 | 15077 |
| 014953 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:59am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595118.7 | 510609.2 | 54865 | 1.64041666667 | 14953 |
| 014366 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:00am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595120.8 | 510610.0 | 54867 | 1.64041666667 | 14366 |
| 014906 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:00am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595122.7 | 510610.9 | 54868 | 1.64041666667 | 14906 |
| 015187 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:01am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595124.6 | 510611.2 | 54870 | 1.64041666667 | 15187 |
| 015210 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:03am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595126.5 | 510613.1 | 54873 | 1.64041666667 | 15210 |
| 015215 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:03am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595128.4 | 510614.2 | 54874 | 1.64041666667 | 15215 |
| 014911 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:05am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595130.8 | 510615.9 | 54877 | 1.64041666667 | 14911 |
| 014515 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:06am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595132.0 | 510617.7 | 54879 | 1.64041666667 | 14515 |
| 014569 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:07am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595133.8 | 510619.7 | 54881 | 1.64041666667 | 14569 |
| 014435 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:08am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595135.7 | 510620.7 | 54883 | 1.64041666667 | 14435 |
| 014555 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:09am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595137.7 | 510623.1 | 54885 | 1.64041666667 | 14555 |
| 014959 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:10am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595139.9 | 510624.6 | 54887 | 1.64041666667 | 14959 |
| 015247 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:11am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595142.1 | 510625.4 | 54889 | 1.64041666667 | 15247 |
| 014374 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:12am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595144.4 | 510626.5 | 54891 | 1.64041666667 | 14374 |
| 014400 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:13am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595147.0 | 510625.3 | 54893 | 1.64041666667 | 14400 |
| 014707 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:14am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595148.6 | 510624.3 | 54895 | 1.64041666667 | 14707 |
| 014993 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:15am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595150.0 | 510622.2 | 54897 | 1.64041666667 | 14993 |
| 016758 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:15am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595149.6 | 510620.9 | 54898 | 1.64041666667 | 16758 |
| 015779 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:16am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595150.5 | 510619.4 | 54900 | 1.64041666667 | 15779 |
| 016518 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:17am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595150.0 | 510617.8 | 54902 | 1.64041666667 | 16518 |
| 015381 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:18am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595150.6 | 510615.6 | 54904 | 1.64041666667 | 15381 |
| 015417 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:19am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595149.2 | 510615.4 | 54906 | 1.64041666667 | 15417 |
| 015212 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:21am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595147.3 | 510613.8 | 54909 | 1.64041666667 | 15212 |
| 014677 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:21am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595145.6 | 510613.9 | 54910 | 1.64041666667 | 14677 |
| 014600 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:23am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595143.0 | 510613.5 | 54913 | 1.64041666667 | 14600 |
| 014385 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:23am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595141.0 | 510612.9 | 54914 | 1.64041666667 | 14385 |
| 014751 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:25am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595138.8 | 510612.9 | 54917 | 1.64041666667 | 14751 |
| 015085 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:26am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595136.4 | 510612.2 | 54919 | 1.64041666667 | 15085 |
| 015093 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:27am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595133.7 | 510612.3 | 54921 | 1.64041666667 | 15093 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:28am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595131.5 | 510612.4 | 54923 | 1.64041666667 | 14737 |
| 015317 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:29am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595129.7 | 510612.3 | 54925 | 1.64041666667 | 15317 |
| 015058 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:30am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595128.3 | 510613.1 | 54927 | 1.64041666667 | 15058 |
| 015033 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:31am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595126.6 | 510611.5 | 54929 | 1.64041666667 | 15033 |
| 014846 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:31am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595124.8 | 510610.4 | 54930 | 1.64041666667 | 14846 |
| 014043 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:33am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595123.4 | 510609.0 | 54933 | 1.64041666667 | 14043 |
| 015317 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:33am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595122.5 | 510607.2 | 54934 | 1.64041666667 | 15317 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015148 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:34am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595120.8 | 510605.7 | 54936 | 1.64041666667 | 15148 |
| 014326 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:35am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595120.1 | 510603.5 | 54938 | 1.64041666667 | 14326 |
| 014456 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:37am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595118.3 | 510601.8 | 54941 | 1.64041666667 | 14456 |
| 014311 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:37am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595116.5 | 510600.8 | 54942 | 1.64041666667 | 14311 |
| 014200 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:39am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595114.2 | 510599.5 | 54945 | 1.64041666667 | 14200 |
| 014340 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:39am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595112.3 | 510599.6 | 54946 | 1.64041666667 | 14340 |
| 015048 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:41am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595109.3 | 510598.4 | 54949 | 1.64041666667 | 15048 |
| 015027 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:42am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595107.3 | 510597.6 | 54951 | 1.64041666667 | 15027 |
| 015075 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:43am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595104.9 | 510597.5 | 54953 | 1.64041666667 | 15075 |
| 015312 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:44am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595102.9 | 510596.1 | 54955 | 1.64041666667 | 15312 |
| 015258 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:45am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595100.6 | 510596.1 | 54957 | 1.64041666667 | 15258 |
| 015280 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:45am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595098.6 | 510595.7 | 54958 | 1.64041666667 | 15280 |
| 015097 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:47am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595096.3 | 510594.3 | 54961 | 1.64041666667 | 15097 |
| 015100 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:47am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595094.7 | 510594.0 | 54962 | 1.64041666667 | 15100 |
| 014876 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:49am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595093.2 | 510592.3 | 54965 | 1.64041666667 | 14876 |
| 014488 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:49am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595091.5 | 510591.6 | 54966 | 1.64041666667 | 14488 |
| 014809 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:51am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595089.5 | 510590.0 | 54969 | 1.64041666667 | 14809 |
| 014442 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:51am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595087.6 | 510589.3 | 54970 | 1.64041666667 | 14442 |
| 014319 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:53am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595085.3 | 510588.5 | 54973 | 1.64041666667 | 14319 |
| 015059 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:53am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595083.7 | 510587.4 | 54974 | 1.64041666667 | 15059 |
| 014133 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:55am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595081.6 | 510586.8 | 54977 | 1.64041666667 | 14133 |
| 014872 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:56am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595079.8 | 510585.6 | 54979 | 1.64041666667 | 14872 |
| 015641 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:57am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595078.1 | 510585.6 | 54981 | 1.64041666667 | 15641 |
| 015578 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:58am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595077.0 | 510584.7 | 54983 | 1.64041666667 | 15578 |
| 015880 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:59am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595075.5 | 510584.7 | 54985 | 1.64041666667 | 15880 |
| 016567 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:00am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595074.0 | 510583.6 | 54987 | 1.64041666667 | 16567 |
| 016294 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:01am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595071.8 | 510583.5 | 54989 | 1.64041666667 | 16294 |
| 015555 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:02am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595070.1 | 510582.5 | 54991 | 1.64041666667 | 15555 |
| 018072 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:03am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595067.8 | 510582.5 | 54993 | 1.64041666667 | 18072 |
| 016938 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:03am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595066.3 | 510581.8 | 54994 | 1.64041666667 | 16938 |
| 016345 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:05am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595064.4 | 510581.2 | 54997 | 1.64041666667 | 16345 |
| 015246 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:06am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595062.7 | 510580.0 | 54999 | 1.64041666667 | 15246 |
| 014253 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:07am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595060.5 | 510579.0 | 55001 | 1.64041666667 | 14253 |
| 013665 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:08am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595059.1 | 510579.0 | 55003 | 1.64041666667 | 13665 |
| 013784 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:09am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595056.9 | 510578.7 | 55005 | 1.64041666667 | 13784 |
| 013881 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:09am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595055.3 | 510579.0 | 55006 | 1.64041666667 | 13881 |
| 013845 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:11am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595053.0 | 510578.4 | 55009 | 1.64041666667 | 13845 |
| 014643 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:12am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595050.9 | 510578.6 | 55011 | 1.64041666667 | 14643 |
| 014596 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:13am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595048.5 | 510577.5 | 55013 | 1.64041666667 | 14596 |
| 014270 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:14am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595046.6 | 510577.2 | 55015 | 1.64041666667 | 14270 |
| 014087 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:15am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595045.0 | 510576.5 | 55017 | 1.64041666667 | 14087 |
| 015139 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:16am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595043.5 | 510574.7 | 55019 | 1.64041666667 | 15139 |
| 015123 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:17am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595041.6 | 510572.9 | 55021 | 1.64041666667 | 15123 |
| 014319 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:18am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595040.4 | 510571.8 | 55023 | 1.64041666667 | 14319 |
| 015607 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:19am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595039.1 | 510570.0 | 55025 | 1.64041666667 | 15607 |
| 015851 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:20am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595038.0 | 510568.7 | 55027 | 1.64041666667 | 15851 |
| 015464 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:21am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595038.2 | 510567.2 | 55029 | 1.64041666667 | 15464 |
| 015648 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:21am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595037.4 | 510566.9 | 55030 | 1.64041666667 | 15648 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015063 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:22am | Sensor | 1797-S0040-905-G-ACK | 6822.2 | 1595035.9 | 510565.8 | 55032 | 1.64041666667 | 15063 |
| 015140 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:23am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595035.7 | 510566.4 | 55034 | 1.64041666667 | 15140 |
| 015049 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:25am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595035.0 | 510567.3 | 55037 | 1.64041666667 | 15049 |
| 014465 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:26am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595036.1 | 510568.1 | 55039 | 1.64041666667 | 14465 |
| 015269 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:27am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595036.1 | 510569.9 | 55041 | 1.64041666667 | 15269 |
| 014581 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:27am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595037.5 | 510570.6 | 55042 | 1.64041666667 | 14581 |
| 014622 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:29am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595038.4 | 510572.2 | 55045 | 1.64041666667 | 14622 |
| 014839 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:29am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595040.0 | 510573.1 | 55046 | 1.64041666667 | 14839 |
| 014340 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:30am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595041.7 | 510574.4 | 55048 | 1.64041666667 | 14340 |
| 014508 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:32am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595042.1 | 510577.1 | 55051 | 1.64041666667 | 14508 |
| 014416 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:32am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595042.8 | 510579.0 | 55052 | 1.64041666667 | 14416 |
| 015541 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:33am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595042.3 | 510580.8 | 55054 | 1.64041666667 | 15541 |
| 015327 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:34am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595041.7 | 510583.0 | 55056 | 1.64041666667 | 15327 |
| 014966 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:35am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595041.6 | 510585.2 | 55058 | 1.64041666667 | 14966 |
| 015993 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:36am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595040.2 | 510586.9 | 55060 | 1.64041666667 | 15993 |
| 016451 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:37am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595040.3 | 510589.1 | 55062 | 1.64041666667 | 16451 |
| 016169 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:39am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595039.3 | 510591.7 | 55065 | 1.64041666667 | 16169 |
| 015260 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:40am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595039.6 | 510594.3 | 55067 | 1.64041666667 | 15260 |
| 015131 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:41am | Sensor | 1797-S0040-905-G-ACK | 6822.9 | 1595039.6 | 510595.4 | 55069 | 1.64041666667 | 15131 |
| 014954 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:42am | Sensor | 1797-S0040-905-G-ACK | 6822.9 | 1595038.5 | 510596.3 | 55071 | 1.64041666667 | 14954 |
| 015379 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:43am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595038.2 | 510598.5 | 55073 | 1.64041666667 | 15379 |
| 014928 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:44am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595037.4 | 510600.2 | 55075 | 1.64041666667 | 14928 |
| 014854 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:45am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595036.4 | 510603.0 | 55077 | 1.64041666667 | 14854 |
| 014468 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:45am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595036.4 | 510604.5 | 55078 | 1.64041666667 | 14468 |
| 014445 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:47am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595035.1 | 510606.6 | 55081 | 1.64041666667 | 14445 |
| 015236 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:47am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595034.8 | 510608.8 | 55082 | 1.64041666667 | 15236 |
| 015387 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:49am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595033.3 | 510611.2 | 55085 | 1.64041666667 | 15387 |
| 015465 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:50am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595032.2 | 510613.0 | 55087 | 1.64041666667 | 15465 |
| 015952 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:51am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595031.7 | 510615.2 | 55089 | 1.64041666667 | 15952 |
| 015798 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:51am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595030.0 | 510616.5 | 55090 | 1.64041666667 | 15798 |
| 015756 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:53am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595029.2 | 510618.7 | 55093 | 1.64041666667 | 15756 |
| 015245 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:53am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595028.3 | 510620.4 | 55094 | 1.64041666667 | 15245 |
| 015730 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:54am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595026.7 | 510622.3 | 55096 | 1.64041666667 | 15730 |
| 015238 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:55am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595026.2 | 510624.0 | 55098 | 1.64041666667 | 15238 |
| 015179 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:57am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595025.0 | 510625.7 | 55101 | 1.64041666667 | 15179 |
| 014800 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:57am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595025.3 | 510627.1 | 55102 | 1.64041666667 | 14800 |
| 014542 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:59am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595024.2 | 510628.6 | 55105 | 1.64041666667 | 14542 |
| 014987 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:59am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595024.2 | 510630.5 | 55106 | 1.64041666667 | 14987 |
| 015131 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:00am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595022.7 | 510632.6 | 55108 | 1.64041666667 | 15131 |
| 014654 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:01am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595022.9 | 510634.6 | 55110 | 1.64041666667 | 14654 |
| 015150 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:02am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595022.1 | 510636.6 | 55112 | 1.64041666667 | 15150 |
| 016037 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:03am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595021.3 | 510638.9 | 55114 | 1.64041666667 | 16037 |
| 014901 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:05am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595019.9 | 510641.5 | 55117 | 1.64041666667 | 14901 |
| 015304 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:06am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595018.3 | 510643.2 | 55119 | 1.64041666667 | 15304 |
| 015051 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:07am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595018.4 | 510645.8 | 55121 | 1.64041666667 | 15051 |
| 014518 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:08am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595018.2 | 510647.7 | 55123 | 1.64041666667 | 14518 |
| 014422 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:09am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595018.7 | 510649.9 | 55125 | 1.64041666667 | 14422 |
| 013542 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:09am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595018.2 | 510651.6 | 55126 | 1.64041666667 | 13542 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013730 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:11am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595017.4 | 510653.5 | 55129 | 1.64041666667 | 13730 |
| 013723 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:11am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595017.0 | 510655.2 | 55130 | 1.64041666667 | 13723 |
| 013831 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:13am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595015.0 | 510656.7 | 55133 | 1.64041666667 | 13831 |
| 014417 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:13am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595014.5 | 510658.9 | 55134 | 1.64041666667 | 14417 |
| 015227 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:15am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595012.7 | 510661.0 | 55137 | 1.64041666667 | 15227 |
| 015968 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:15am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595011.6 | 510662.5 | 55138 | 1.64041666667 | 15968 |
| 014809 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:17am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595010.6 | 510664.6 | 55141 | 1.64041666667 | 14809 |
| 015050 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:18am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595009.1 | 510666.0 | 55143 | 1.64041666667 | 15050 |
| 015598 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:19am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595008.3 | 510668.4 | 55145 | 1.64041666667 | 15598 |
| 015464 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:20am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595008.0 | 510670.2 | 55147 | 1.64041666667 | 15464 |
| 015126 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:21am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595007.6 | 510671.9 | 55149 | 1.64041666667 | 15126 |
| 014343 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:21am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595009.1 | 510672.7 | 55150 | 1.64041666667 | 14343 |
| 014825 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:23am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595010.9 | 510672.1 | 55153 | 1.64041666667 | 14825 |
| 015652 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:23am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595012.8 | 510672.6 | 55154 | 1.64041666667 | 15652 |
| 015081 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:25am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595014.9 | 510671.3 | 55157 | 1.64041666667 | 15081 |
| 014378 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:25am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595016.6 | 510670.0 | 55158 | 1.64041666667 | 14378 |
| 014013 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:27am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595017.7 | 510667.6 | 55161 | 1.64041666667 | 14013 |
| 015007 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:27am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595018.0 | 510665.8 | 55162 | 1.64041666667 | 15007 |
| 014554 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:29am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595020.1 | 510664.3 | 55165 | 1.64041666667 | 14554 |
| 014726 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:29am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595020.6 | 510662.8 | 55166 | 1.64041666667 | 14726 |
| 013736 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:31am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595022.3 | 510661.3 | 55169 | 1.64041666667 | 13736 |
| 015624 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:31am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595023.0 | 510659.6 | 55170 | 1.64041666667 | 15624 |
| 015351 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:32am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595023.7 | 510657.3 | 55172 | 1.64041666667 | 15351 |
| 015062 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:33am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595024.8 | 510655.2 | 55174 | 1.64041666667 | 15062 |
| 015530 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:35am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595024.9 | 510652.7 | 55177 | 1.64041666667 | 15530 |
| 015620 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:35am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595026.0 | 510651.3 | 55178 | 1.64041666667 | 15620 |
| 015656 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:37am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595026.2 | 510649.1 | 55181 | 1.64041666667 | 15656 |
| 015924 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:38am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595027.3 | 510647.1 | 55183 | 1.64041666667 | 15924 |
| 015745 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:39am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595027.4 | 510645.0 | 55185 | 1.64041666667 | 15745 |
| 015441 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:39am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595027.6 | 510643.1 | 55186 | 1.64041666667 | 15441 |
| 015435 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:41am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595028.0 | 510640.4 | 55189 | 1.64041666667 | 15435 |
| 015132 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:41am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595027.4 | 510638.6 | 55190 | 1.64041666667 | 15132 |
| 015157 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:43am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595027.9 | 510635.7 | 55193 | 1.64041666667 | 15157 |
| 014796 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:43am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595027.3 | 510633.9 | 55194 | 1.64041666667 | 14796 |
| 014885 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:45am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595027.7 | 510631.9 | 55197 | 1.64041666667 | 14885 |
| 015925 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:46am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595028.3 | 510630.0 | 55199 | 1.64041666667 | 15925 |
| 015040 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:47am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595028.6 | 510627.5 | 55201 | 1.64041666667 | 15040 |
| 014790 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:48am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595029.3 | 510625.7 | 55203 | 1.64041666667 | 14790 |
| 015054 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:49am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595028.9 | 510623.3 | 55205 | 1.64041666667 | 15054 |
| 015968 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:49am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595029.6 | 510621.4 | 55206 | 1.64041666667 | 15968 |
| 016639 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:51am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595029.2 | 510618.9 | 55209 | 1.64041666667 | 16639 |
| 016072 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:51am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595029.7 | 510617.4 | 55210 | 1.64041666667 | 16072 |
| 016015 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:53am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595030.7 | 510615.1 | 55213 | 1.64041666667 | 16015 |
| 015916 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:53am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595031.3 | 510613.4 | 55214 | 1.64041666667 | 15916 |
| 015747 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:55am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595033.1 | 510611.2 | 55217 | 1.64041666667 | 15747 |
| 014940 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:55am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595033.2 | 510609.4 | 55218 | 1.64041666667 | 14940 |
| 015686 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:57am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595035.2 | 510608.1 | 55221 | 1.64041666667 | 15686 |
| 015641 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:58am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595035.6 | 510606.5 | 55223 | 1.64041666667 | 15641 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015788 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:59am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595037.3 | 510604.7 | 55225 | 1.64041666667 | 15788 |
| 015825 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:00am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595037.7 | 510602.9 | 55227 | 1.64041666667 | 15825 |
| 014969 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:01am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595039.1 | 510600.8 | 55229 | 1.64041666667 | 14969 |
| 015845 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:01am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595039.8 | 510599.5 | 55230 | 1.64041666667 | 15845 |
| 015828 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:03am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595040.7 | 510597.8 | 55233 | 1.64041666667 | 15828 |
| 015578 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:03am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595042.3 | 510596.7 | 55234 | 1.64041666667 | 15578 |
| 015235 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:05am | Sensor | 1797-S0040-905-G-ACK | 6822.7 | 1595043.5 | 510594.9 | 55237 | 1.64041666667 | 15235 |
| 015289 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:06am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595045.1 | 510594.2 | 55239 | 1.64041666667 | 15289 |
| 014735 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:07am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595046.1 | 510591.0 | 55241 | 1.64041666667 | 14735 |
| 015158 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:08am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595045.9 | 510589.1 | 55243 | 1.64041666667 | 15158 |
| 015111 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:09am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595046.1 | 510586.4 | 55245 | 1.64041666667 | 15111 |
| 015085 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:10am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595045.5 | 510584.9 | 55247 | 1.64041666667 | 15085 |
| 015160 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:11am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595046.2 | 510582.5 | 55249 | 1.64041666667 | 15160 |
| 015442 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:12am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595045.7 | 510580.1 | 55251 | 1.64041666667 | 15442 |
| 014904 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:13am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595046.2 | 510578.0 | 55253 | 1.64041666667 | 14904 |
| 015463 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:14am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595046.2 | 510575.4 | 55255 | 1.64041666667 | 15463 |
| 015125 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:15am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595046.0 | 510573.2 | 55257 | 1.64041666667 | 15125 |
| 015558 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:15am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595047.3 | 510571.6 | 55258 | 1.64041666667 | 15558 |
| 015014 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:16am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595048.2 | 510569.6 | 55260 | 1.64041666667 | 15014 |
| 015877 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:17am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595049.8 | 510568.0 | 55262 | 1.64041666667 | 15877 |
| 015456 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:19am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595052.2 | 510566.9 | 55265 | 1.64041666667 | 15456 |
| 014611 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:19am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595053.5 | 510565.8 | 55266 | 1.64041666667 | 14611 |
| 013611 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:21am | Sensor | 1797-S0040-905-G-ACK | 6822.3 | 1595055.7 | 510565.9 | 55269 | 1.64041666667 | 13611 |
| 013919 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:22am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595057.3 | 510565.9 | 55271 | 1.64041666667 | 13919 |
| 014099 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:23am | Sensor | 1797-S0040-905-G-ACK | 6822.6 | 1595058.5 | 510566.6 | 55273 | 1.64041666667 | 14099 |
| 014096 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:23am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595060.2 | 510566.9 | 55274 | 1.64041666667 | 14096 |
| 015466 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:25am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595063.4 | 510567.1 | 55277 | 1.64041666667 | 15466 |
| 015277 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:26am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595065.6 | 510567.8 | 55279 | 1.64041666667 | 15277 |
| 015118 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:27am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595067.6 | 510567.7 | 55281 | 1.64041666667 | 15118 |
| 014256 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:28am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595068.5 | 510569.3 | 55283 | 1.64041666667 | 14256 |
| 014266 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:29am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595069.6 | 510571.6 | 55285 | 1.64041666667 | 14266 |
| 014017 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:30am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595070.1 | 510573.3 | 55287 | 1.64041666667 | 14017 |
| 014230 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:31am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595069.5 | 510575.2 | 55289 | 1.64041666667 | 14230 |
| 014686 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:31am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595070.0 | 510576.6 | 55290 | 1.64041666667 | 14686 |
| 014988 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:33am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595068.9 | 510579.2 | 55293 | 1.64041666667 | 14988 |
| 015278 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:33am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595068.9 | 510580.8 | 55294 | 1.64041666667 | 15278 |
| 014601 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:35am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595068.2 | 510583.8 | 55297 | 1.64041666667 | 14601 |
| 015226 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:35am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595067.4 | 510585.1 | 55298 | 1.64041666667 | 15226 |
| 015487 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:37am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595067.2 | 510587.4 | 55301 | 1.64041666667 | 15487 |
| 014771 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:37am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595065.8 | 510588.8 | 55302 | 1.64041666667 | 14771 |
| 014579 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:39am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595064.3 | 510590.7 | 55305 | 1.64041666667 | 14579 |
| 015573 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:39am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595063.4 | 510592.0 | 55306 | 1.64041666667 | 15573 |
| 015427 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:40am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595062.0 | 510594.0 | 55308 | 1.64041666667 | 15427 |
| 015532 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:41am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595061.6 | 510596.3 | 55310 | 1.64041666667 | 15532 |
| 015907 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:43am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595059.8 | 510598.4 | 55313 | 1.64041666667 | 15907 |
| 015232 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:43am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595059.0 | 510600.2 | 55314 | 1.64041666667 | 15232 |
| 015828 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:45am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595058.6 | 510602.8 | 55317 | 1.64041666667 | 15828 |
| 017168 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:45am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595057.8 | 510604.7 | 55318 | 1.64041666667 | 17168 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016662 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:47am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595058.3 | 510607.1 | 55321 | 1.64041666667 | 16662 |
| 015605 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:48am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595057.5 | 510609.0 | 55323 | 1.64041666667 | 15605 |
| 016060 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:49am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595057.6 | 510611.3 | 55325 | 1.64041666667 | 16060 |
| 016608 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:49am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595057.2 | 510613.2 | 55326 | 1.64041666667 | 16608 |
| 016340 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:50am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595056.2 | 510615.3 | 55328 | 1.64041666667 | 16340 |
| 016518 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:51am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595056.2 | 510617.4 | 55330 | 1.64041666667 | 16518 |
| 015629 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:52am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595054.8 | 510619.2 | 55332 | 1.64041666667 | 15629 |
| 015894 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:53am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595055.0 | 510621.2 | 55334 | 1.64041666667 | 15894 |
| 015862 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:54am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595054.4 | 510623.5 | 55336 | 1.64041666667 | 15862 |
| 015275 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:55am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595053.4 | 510625.6 | 55338 | 1.64041666667 | 15275 |
| 015717 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:57am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595053.1 | 510627.9 | 55341 | 1.64041666667 | 15717 |
| 015838 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:57am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595051.9 | 510629.6 | 55342 | 1.64041666667 | 15838 |
| 016296 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:59am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595051.9 | 510631.9 | 55345 | 1.64041666667 | 16296 |
| 016194 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:59am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595051.3 | 510634.0 | 55346 | 1.64041666667 | 16194 |
| 016279 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:01am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595050.0 | 510636.5 | 55349 | 1.64041666667 | 16279 |
| 015479 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:01am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595049.5 | 510638.2 | 55350 | 1.64041666667 | 15479 |
| 014820 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:03am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595047.6 | 510640.1 | 55353 | 1.64041666667 | 14820 |
| 015131 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:03am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595047.1 | 510641.8 | 55354 | 1.64041666667 | 15131 |
| 015523 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:05am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595046.3 | 510643.8 | 55357 | 1.64041666667 | 15523 |
| 016472 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:05am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595045.6 | 510646.0 | 55358 | 1.64041666667 | 16472 |
| 016645 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:06am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595045.5 | 510648.0 | 55360 | 1.64041666667 | 16645 |
| 015393 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:07am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595044.2 | 510649.8 | 55362 | 1.64041666667 | 15393 |
| 014786 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:08am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595043.6 | 510652.1 | 55364 | 1.64041666667 | 14786 |
| 015457 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:09am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595042.7 | 510653.9 | 55366 | 1.64041666667 | 15457 |
| 015737 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:10am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595041.3 | 510655.8 | 55368 | 1.64041666667 | 15737 |
| 016344 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:11am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595041.3 | 510658.1 | 55370 | 1.64041666667 | 16344 |
| 015591 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:12am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595040.4 | 510660.2 | 55372 | 1.64041666667 | 15591 |
| 015212 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:13am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595041.1 | 510662.1 | 55374 | 1.64041666667 | 15212 |
| 015029 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:15am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595040.4 | 510664.7 | 55377 | 1.64041666667 | 15029 |
| 014514 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:16am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595040.1 | 510666.6 | 55379 | 1.64041666667 | 14514 |
| 015184 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:17am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595039.9 | 510668.9 | 55381 | 1.64041666667 | 15184 |
| 014211 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:18am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595039.0 | 510670.5 | 55383 | 1.64041666667 | 14211 |
| 013776 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:19am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595039.7 | 510671.5 | 55385 | 1.64041666667 | 13776 |
| 014971 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:20am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595040.4 | 510672.9 | 55387 | 1.64041666667 | 14971 |
| 014991 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:21am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595042.1 | 510673.2 | 55389 | 1.64041666667 | 14991 |
| 015055 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:21am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595042.2 | 510675.3 | 55390 | 1.64041666667 | 15055 |
| 014948 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:22am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595042.9 | 510676.2 | 55392 | 1.64041666667 | 14948 |
| 013538 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:23am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595043.4 | 510677.9 | 55394 | 1.64041666667 | 13538 |
| 014103 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:25am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595044.9 | 510679.4 | 55397 | 1.64041666667 | 14103 |
| 014225 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:26am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595046.5 | 510679.5 | 55399 | 1.64041666667 | 14225 |
| 014819 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:27am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595048.5 | 510680.8 | 55401 | 1.64041666667 | 14819 |
| 015048 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:28am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595050.0 | 510680.7 | 55403 | 1.64041666667 | 15048 |
| 014809 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:29am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595052.2 | 510680.7 | 55405 | 1.64041666667 | 14809 |
| 015215 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:30am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595053.4 | 510679.5 | 55407 | 1.64041666667 | 15215 |
| 014393 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:31am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595053.3 | 510677.5 | 55409 | 1.64041666667 | 14393 |
| 014681 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:31am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595053.7 | 510675.7 | 55410 | 1.64041666667 | 14681 |
| 014595 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:33am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595053.0 | 510674.0 | 55413 | 1.64041666667 | 14595 |
| 014750 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:34am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595053.2 | 510672.5 | 55415 | 1.64041666667 | 14750 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014529 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:35am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595053.8 | 510670.5 | 55417 | 1.64041666667 | 14529 |
| 013925 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:36am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595053.4 | 510668.6 | 55419 | 1.64041666667 | 13925 |
| 014703 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:37am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595054.0 | 510666.5 | 55421 | 1.64041666667 | 14703 |
| 015583 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:37am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595053.8 | 510665.0 | 55422 | 1.64041666667 | 15583 |
| 015020 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:39am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595053.8 | 510663.2 | 55425 | 1.64041666667 | 15020 |
| 016031 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:39am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595054.1 | 510660.9 | 55426 | 1.64041666667 | 16031 |
| 016120 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:40am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595053.5 | 510659.0 | 55428 | 1.64041666667 | 16120 |
| 015510 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:41am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595053.9 | 510656.9 | 55430 | 1.64041666667 | 15510 |
| 014844 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:42am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595053.1 | 510654.8 | 55432 | 1.64041666667 | 14844 |
| 015467 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:43am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595053.5 | 510652.7 | 55434 | 1.64041666667 | 15467 |
| 015705 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:45am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595052.5 | 510650.4 | 55437 | 1.64041666667 | 15705 |
| 014819 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:45am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595052.9 | 510648.6 | 55438 | 1.64041666667 | 14819 |
| 014021 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:47am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595053.7 | 510645.2 | 55441 | 1.64041666667 | 14021 |
| 014321 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:47am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595053.9 | 510644.1 | 55442 | 1.64041666667 | 14321 |
| 015233 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:49am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595054.9 | 510642.6 | 55445 | 1.64041666667 | 15233 |
| 015026 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:49am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595054.9 | 510641.2 | 55446 | 1.64041666667 | 15026 |
| 014962 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:51am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595055.7 | 510639.3 | 55449 | 1.64041666667 | 14962 |
| 015181 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:51am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595055.0 | 510637.7 | 55450 | 1.64041666667 | 15181 |
| 015506 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:53am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595055.2 | 510634.8 | 55453 | 1.64041666667 | 15506 |
| 014407 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:54am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595055.9 | 510632.9 | 55455 | 1.64041666667 | 14407 |
| 014366 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:55am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595055.9 | 510630.8 | 55457 | 1.64041666667 | 14366 |
| 015581 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:55am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595056.7 | 510629.3 | 55458 | 1.64041666667 | 15581 |
| 015387 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:57am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595056.9 | 510626.7 | 55461 | 1.64041666667 | 15387 |
| 015487 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:57am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595058.1 | 510625.1 | 55462 | 1.64041666667 | 15487 |
| 015124 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:59am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595058.8 | 510622.6 | 55465 | 1.64041666667 | 15124 |
| 014942 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:59am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595059.3 | 510620.9 | 55466 | 1.64041666667 | 14942 |
| 015200 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:00am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595060.2 | 510618.9 | 55468 | 1.64041666667 | 15200 |
| 015442 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:01am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595060.5 | 510617.3 | 55470 | 1.64041666667 | 15442 |
| 014649 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:03am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595061.8 | 510615.3 | 55473 | 1.64041666667 | 14649 |
| 015222 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:03am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595061.5 | 510613.5 | 55474 | 1.64041666667 | 15222 |
| 016100 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:05am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595063.0 | 510611.3 | 55477 | 1.64041666667 | 16100 |
| 016091 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:05am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595062.7 | 510609.4 | 55478 | 1.64041666667 | 16091 |
| 015726 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:07am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595063.8 | 510607.2 | 55481 | 1.64041666667 | 15726 |
| 015656 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:08am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595064.0 | 510605.2 | 55483 | 1.64041666667 | 15656 |
| 014529 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:09am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595064.3 | 510602.9 | 55485 | 1.64041666667 | 14529 |
| 014240 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:09am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595065.2 | 510601.0 | 55486 | 1.64041666667 | 14240 |
| 014850 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:11am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595065.9 | 510598.7 | 55489 | 1.64041666667 | 14850 |
| 015058 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:11am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595067.0 | 510596.7 | 55490 | 1.64041666667 | 15058 |
| 014942 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:13am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595066.5 | 510594.2 | 55493 | 1.64041666667 | 14942 |
| 015380 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:13am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595067.5 | 510592.7 | 55494 | 1.64041666667 | 15380 |
| 015896 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:15am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595067.3 | 510590.2 | 55497 | 1.64041666667 | 15896 |
| 016036 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:15am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595067.9 | 510588.4 | 55498 | 1.64041666667 | 16036 |
| 016318 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:17am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595068.5 | 510585.3 | 55501 | 1.64041666667 | 16318 |
| 017174 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:17am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595068.5 | 510583.2 | 55502 | 1.64041666667 | 17174 |
| 015960 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:19am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595069.8 | 510580.9 | 55505 | 1.64041666667 | 15960 |
| 015352 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:19am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595070.1 | 510579.2 | 55506 | 1.64041666667 | 15352 |
| 014681 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:21am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595071.9 | 510577.7 | 55509 | 1.64041666667 | 14681 |
| 014880 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:21am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595073.3 | 510576.2 | 55510 | 1.64041666667 | 14880 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015202 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:22am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595075.0 | 510574.9 | 55512 | 1.64041666667 | 15202 |
| 014431 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:23am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595077.2 | 510574.0 | 55514 | 1.64041666667 | 14431 |
| 014080 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:24am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595079.0 | 510572.9 | 55516 | 1.64041666667 | 14080 |
| 014872 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:25am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595080.8 | 510573.0 | 55518 | 1.64041666667 | 14872 |
| 014636 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:27am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595083.2 | 510572.4 | 55521 | 1.64041666667 | 14636 |
| 014840 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:27am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595084.7 | 510572.7 | 55522 | 1.64041666667 | 14840 |
| 014752 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:28am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595086.5 | 510573.6 | 55524 | 1.64041666667 | 14752 |
| 014658 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:29am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595087.7 | 510574.7 | 55526 | 1.64041666667 | 14658 |
| 014478 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:30am | Sensor | 1797-S0040-905-G-ACK | 6822.4 | 1595087.7 | 510576.8 | 55528 | 1.64041666667 | 14478 |
| 014743 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:31am | Sensor | 1797-S0040-905-G-ACK | 6822.5 | 1595088.1 | 510578.4 | 55530 | 1.64041666667 | 14743 |
| 015283 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:33am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595087.8 | 510580.7 | 55533 | 1.64041666667 | 15283 |
| 015287 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:33am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595087.9 | 510583.2 | 55534 | 1.64041666667 | 15287 |
| 015348 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:34am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595088.9 | 510585.8 | 55536 | 1.64041666667 | 15348 |
| 015023 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:35am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595088.4 | 510587.8 | 55538 | 1.64041666667 | 15023 |
| 014571 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:37am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595089.0 | 510590.3 | 55541 | 1.64041666667 | 14571 |
| 014271 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:37am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595088.9 | 510592.2 | 55542 | 1.64041666667 | 14271 |
| 014222 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:39am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595088.6 | 510595.2 | 55545 | 1.64041666667 | 14222 |
| 013505 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:39am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595089.1 | 510597.1 | 55546 | 1.64041666667 | 13505 |
| 013641 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:41am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595088.5 | 510599.6 | 55549 | 1.64041666667 | 13641 |
| 014873 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:41am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595088.6 | 510601.6 | 55550 | 1.64041666667 | 14873 |
| 015101 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:43am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595088.7 | 510604.1 | 55553 | 1.64041666667 | 15101 |
| 015237 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:43am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595088.3 | 510606.4 | 55554 | 1.64041666667 | 15237 |
| 015485 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:45am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595088.9 | 510608.9 | 55557 | 1.64041666667 | 15485 |
| 016533 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:45am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595088.3 | 510610.8 | 55558 | 1.64041666667 | 16533 |
| 015922 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:47am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595088.7 | 510613.7 | 55561 | 1.64041666667 | 15922 |
| 015991 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:47am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595088.4 | 510615.7 | 55562 | 1.64041666667 | 15991 |
| 014590 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:49am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595088.3 | 510618.1 | 55565 | 1.64041666667 | 14590 |
| 015099 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:49am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595088.9 | 510620.0 | 55566 | 1.64041666667 | 15099 |
| 016406 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:50am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595087.9 | 510622.2 | 55568 | 1.64041666667 | 16406 |
| 016428 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:51am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595088.1 | 510624.2 | 55570 | 1.64041666667 | 16428 |
| 017086 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:52am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595087.2 | 510626.5 | 55572 | 1.64041666667 | 17086 |
| 016458 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:53am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595085.8 | 510628.6 | 55574 | 1.64041666667 | 16458 |
| 016113 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:55am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595085.6 | 510631.1 | 55577 | 1.64041666667 | 16113 |
| 015806 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:55am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595084.8 | 510633.0 | 55578 | 1.64041666667 | 15806 |
| 015611 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:57am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595084.8 | 510635.3 | 55581 | 1.64041666667 | 15611 |
| 014608 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:57am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595084.3 | 510637.2 | 55582 | 1.64041666667 | 14608 |
| 015207 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:59am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595083.3 | 510639.6 | 55585 | 1.64041666667 | 15207 |
| 014861 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:59am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595083.1 | 510641.7 | 55586 | 1.64041666667 | 14861 |
| 015439 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:00am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595081.7 | 510643.1 | 55588 | 1.64041666667 | 15439 |
| 015255 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:01am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595081.4 | 510645.0 | 55590 | 1.64041666667 | 15255 |
| 016470 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:02am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595080.4 | 510647.2 | 55592 | 1.64041666667 | 16470 |
| 016674 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:03am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595079.9 | 510649.2 | 55594 | 1.64041666667 | 16674 |
| 016639 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:05am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595079.6 | 510651.7 | 55597 | 1.64041666667 | 16639 |
| 015322 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:05am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595078.7 | 510653.4 | 55598 | 1.64041666667 | 15322 |
| 016313 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:07am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595079.1 | 510655.5 | 55601 | 1.64041666667 | 16313 |
| 016541 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:07am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595078.5 | 510657.6 | 55602 | 1.64041666667 | 16541 |
| 015552 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:09am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595078.8 | 510660.0 | 55605 | 1.64041666667 | 15552 |
| 015235 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:09am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595078.8 | 510662.0 | 55606 | 1.64041666667 | 15235 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014862 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:11am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595077.7 | 510664.4 | 55609 | 1.64041666667 | 14862 |
| 015305 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:11am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595077.8 | 510666.5 | 55610 | 1.64041666667 | 15305 |
| 014834 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:13am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595076.5 | 510668.7 | 55613 | 1.64041666667 | 14834 |
| 014696 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:13am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595076.2 | 510671.1 | 55614 | 1.64041666667 | 14696 |
| 014536 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:15am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595075.8 | 510673.7 | 55617 | 1.64041666667 | 14536 |
| 014769 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:15am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595075.2 | 510675.3 | 55618 | 1.64041666667 | 14769 |
| 014630 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:17am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595075.0 | 510677.3 | 55621 | 1.64041666667 | 14630 |
| 015227 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:18am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595074.1 | 510678.9 | 55623 | 1.64041666667 | 15227 |
| 014902 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:19am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595073.8 | 510681.2 | 55625 | 1.64041666667 | 14902 |
| 014810 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:19am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595072.8 | 510682.8 | 55626 | 1.64041666667 | 14810 |
| 014300 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:20am | Sensor | 1797-S0040-905-G-ACK | 6819.7 | 1595072.1 | 510685.0 | 55628 | 1.64041666667 | 14300 |
| 014434 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:22am | Sensor | 1797-S0040-905-G-ACK | 6819.3 | 1595072.0 | 510687.0 | 55631 | 1.64041666667 | 14434 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:23am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1595071.1 | 510689.6 | 55633 | 1.64041666667 | 13931 |
| 013686 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:24am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1595071.7 | 510691.7 | 55635 | 1.64041666667 | 13686 |
| 013166 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:25am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1595071.4 | 510694.2 | 55637 | 1.64041666667 | 13166 |
| 012993 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:26am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1595073.3 | 510696.0 | 55639 | 1.64041666667 | 12993 |
| 013331 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:27am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1595075.9 | 510696.7 | 55641 | 1.64041666667 | 13331 |
| 013094 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:28am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1595078.2 | 510697.3 | 55643 | 1.64041666667 | 13094 |
| 013275 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:29am | Sensor | 1797-S0040-905-G-ACK | 6819.6 | 1595079.8 | 510696.9 | 55645 | 1.64041666667 | 13275 |
| 014472 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:29am | Sensor | 1797-S0040-905-G-ACK | 6819.7 | 1595081.2 | 510697.0 | 55646 | 1.64041666667 | 14472 |
| 013555 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:31am | Sensor | 1797-S0040-905-G-ACK | 6820.0 | 1595082.8 | 510695.5 | 55649 | 1.64041666667 | 13555 |
| 014607 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:31am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1595083.4 | 510693.7 | 55650 | 1.64041666667 | 14607 |
| 013759 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:33am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595083.1 | 510691.2 | 55653 | 1.64041666667 | 13759 |
| 014309 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:34am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595082.3 | 510689.6 | 55655 | 1.64041666667 | 14309 |
| 013546 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:35am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595082.6 | 510687.2 | 55657 | 1.64041666667 | 13546 |
| 014700 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:36am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595082.0 | 510685.4 | 55659 | 1.64041666667 | 14700 |
| 014763 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:37am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595082.6 | 510683.4 | 55661 | 1.64041666667 | 14763 |
| 015264 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:37am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595082.9 | 510681.3 | 55662 | 1.64041666667 | 15264 |
| 014916 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:39am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595083.1 | 510678.7 | 55665 | 1.64041666667 | 14916 |
| 014623 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:40am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595084.3 | 510677.0 | 55667 | 1.64041666667 | 14623 |
| 015035 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:41am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595084.0 | 510674.8 | 55669 | 1.64041666667 | 15035 |
| 015439 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:42am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595084.7 | 510672.7 | 55671 | 1.64041666667 | 15439 |
| 015427 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:43am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595084.2 | 510670.9 | 55673 | 1.64041666667 | 15427 |
| 015675 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:43am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595084.5 | 510669.1 | 55674 | 1.64041666667 | 15675 |
| 015417 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:45am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595084.5 | 510666.4 | 55677 | 1.64041666667 | 15417 |
| 014964 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:45am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595084.0 | 510664.8 | 55678 | 1.64041666667 | 14964 |
| 015407 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:47am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595084.4 | 510662.2 | 55681 | 1.64041666667 | 15407 |
| 014794 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:47am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595083.9 | 510660.5 | 55682 | 1.64041666667 | 14794 |
| 015004 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:49am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595084.7 | 510657.9 | 55685 | 1.64041666667 | 15004 |
| 015257 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:49am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595084.7 | 510656.1 | 55686 | 1.64041666667 | 15257 |
| 015632 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:51am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595084.7 | 510653.4 | 55689 | 1.64041666667 | 15632 |
| 015715 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:51am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595085.7 | 510651.5 | 55690 | 1.64041666667 | 15715 |
| 015207 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:53am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595085.7 | 510648.9 | 55693 | 1.64041666667 | 15207 |
| 015581 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:54am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595086.3 | 510646.7 | 55695 | 1.64041666667 | 15581 |
| 014914 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:55am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595087.3 | 510644.5 | 55697 | 1.64041666667 | 14914 |
| 015784 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:56am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595088.1 | 510642.8 | 55699 | 1.64041666667 | 15784 |
| 015448 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:57am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595089.8 | 510640.4 | 55701 | 1.64041666667 | 15448 |
| 016017 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:58am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595090.0 | 510638.2 | 55703 | 1.64041666667 | 16017 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016149 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:59am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595090.8 | 510635.7 | 55705 | 1.64041666667 | 16149 |
| 016284 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:00am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595091.2 | 510633.4 | 55707 | 1.64041666667 | 16284 |
| 015512 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:01am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595091.4 | 510631.1 | 55709 | 1.64041666667 | 15512 |
| 015445 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:02am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595092.4 | 510629.4 | 55711 | 1.64041666667 | 15445 |
| 016165 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:03am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595092.1 | 510626.9 | 55713 | 1.64041666667 | 16165 |
| 015970 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:04am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595092.2 | 510624.5 | 55715 | 1.64041666667 | 15970 |
| 015291 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:05am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595092.9 | 510622.0 | 55717 | 1.64041666667 | 15291 |
| 015756 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:06am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595092.4 | 510620.1 | 55719 | 1.64041666667 | 15756 |
| 015627 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:07am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595093.4 | 510617.7 | 55721 | 1.64041666667 | 15627 |
| 016058 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:08am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595093.7 | 510615.4 | 55723 | 1.64041666667 | 16058 |
| 016502 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:09am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595094.3 | 510613.2 | 55725 | 1.64041666667 | 16502 |
| 016287 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:09am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595095.6 | 510611.3 | 55726 | 1.64041666667 | 16287 |
| 016204 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:11am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595095.9 | 510608.6 | 55729 | 1.64041666667 | 16204 |
| 016225 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:11am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595096.9 | 510606.8 | 55730 | 1.64041666667 | 16225 |
| 015704 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:12am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595097.6 | 510604.4 | 55732 | 1.64041666667 | 15704 |
| 015853 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:13am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595097.3 | 510602.4 | 55734 | 1.64041666667 | 15853 |
| 015930 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:14am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595098.2 | 510600.0 | 55736 | 1.64041666667 | 15930 |
| 015935 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:15am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595098.3 | 510598.1 | 55738 | 1.64041666667 | 15935 |
| 016298 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:16am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595099.6 | 510595.5 | 55740 | 1.64041666667 | 16298 |
| 016135 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:17am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595101.4 | 510595.2 | 55742 | 1.64041666667 | 16135 |
| 015713 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:18am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595104.0 | 510593.9 | 55744 | 1.64041666667 | 15713 |
| 014741 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:19am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595106.2 | 510593.6 | 55746 | 1.64041666667 | 14741 |
| 014674 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:20am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595108.2 | 510593.9 | 55748 | 1.64041666667 | 14674 |
| 014756 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:21am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595110.5 | 510594.8 | 55750 | 1.64041666667 | 14756 |
| 014077 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:23am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595111.6 | 510597.4 | 55753 | 1.64041666667 | 14077 |
| 014046 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:23am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595112.4 | 510599.1 | 55754 | 1.64041666667 | 14046 |
| 014613 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:25am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595113.8 | 510601.6 | 55757 | 1.64041666667 | 14613 |
| 015187 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:25am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595113.6 | 510603.5 | 55758 | 1.64041666667 | 15187 |
| 014130 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:27am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595114.4 | 510606.0 | 55761 | 1.64041666667 | 14130 |
| 014548 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:27am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595114.8 | 510608.2 | 55762 | 1.64041666667 | 14548 |
| 014888 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:29am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595114.4 | 510611.0 | 55765 | 1.64041666667 | 14888 |
| 014517 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:29am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595115.0 | 510612.9 | 55766 | 1.64041666667 | 14517 |
| 014203 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:31am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595114.6 | 510615.8 | 55769 | 1.64041666667 | 14203 |
| 014544 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:31am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595114.7 | 510617.6 | 55770 | 1.64041666667 | 14544 |
| 014878 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:32am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595115.6 | 510619.7 | 55772 | 1.64041666667 | 14878 |
| 015539 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:33am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595115.0 | 510622.1 | 55774 | 1.64041666667 | 15539 |
| 015618 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:34am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595115.2 | 510624.4 | 55776 | 1.64041666667 | 15618 |
| 016255 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:35am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595115.6 | 510626.8 | 55778 | 1.64041666667 | 16255 |
| 015833 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:37am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595115.2 | 510629.5 | 55781 | 1.64041666667 | 15833 |
| 015798 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:37am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595115.8 | 510631.1 | 55782 | 1.64041666667 | 15798 |
| 014759 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:39am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595115.4 | 510634.0 | 55785 | 1.64041666667 | 14759 |
| 014437 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:39am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595115.6 | 510636.0 | 55786 | 1.64041666667 | 14437 |
| 014256 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:41am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595116.2 | 510638.7 | 55789 | 1.64041666667 | 14256 |
| 015129 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:41am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595115.9 | 510640.5 | 55790 | 1.64041666667 | 15129 |
| 015402 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:43am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595116.6 | 510643.1 | 55793 | 1.64041666667 | 15402 |
| 014581 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:43am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595116.0 | 510645.2 | 55794 | 1.64041666667 | 14581 |
| 014869 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:45am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595115.7 | 510647.5 | 55797 | 1.64041666667 | 14869 |
| 014844 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:45am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595115.8 | 510649.5 | 55798 | 1.64041666667 | 14844 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014964 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:46am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595114.7 | 510652.3 | 55800 | 1.64041666667 | 14964 |
| 014643 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:47am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595114.9 | 510654.6 | 55802 | 1.64041666667 | 14643 |
| 015217 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:49am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595115.1 | 510657.2 | 55805 | 1.64041666667 | 15217 |
| 014679 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:49am | Sensor | 1797-S0040-905-G-ACK | 6821.9 | 1595114.6 | 510658.6 | 55806 | 1.64041666667 | 14679 |
| 015135 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:50am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595114.0 | 510660.7 | 55808 | 1.64041666667 | 15135 |
| 014591 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:51am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595113.3 | 510662.7 | 55810 | 1.64041666667 | 14591 |
| 014008 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:52am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595111.8 | 510665.1 | 55812 | 1.64041666667 | 14008 |
| 014839 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:53am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595111.7 | 510667.0 | 55814 | 1.64041666667 | 14839 |
| 014744 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:54am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595110.5 | 510669.1 | 55816 | 1.64041666667 | 14744 |
| 014804 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:55am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595109.3 | 510670.9 | 55818 | 1.64041666667 | 14804 |
| 014784 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:56am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595108.6 | 510673.4 | 55820 | 1.64041666667 | 14784 |
| 014196 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:57am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595107.0 | 510674.7 | 55822 | 1.64041666667 | 14196 |
| 015223 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:59am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595105.1 | 510676.5 | 55825 | 1.64041666667 | 15223 |
| 015627 | 0 | GeoXH 6000 | 08/19/2015 | 10:37:59am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595104.4 | 510678.4 | 55826 | 1.64041666667 | 15627 |
| 015915 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:01am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595102.4 | 510679.7 | 55829 | 1.64041666667 | 15915 |
| 015230 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:01am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595101.9 | 510681.4 | 55830 | 1.64041666667 | 15230 |
| 015549 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:03am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595100.2 | 510682.7 | 55833 | 1.64041666667 | 15549 |
| 015766 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:03am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595099.6 | 510684.2 | 55834 | 1.64041666667 | 15766 |
| 015296 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:05am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595098.9 | 510684.1 | 55837 | 1.64041666667 | 15296 |
| 014971 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:05am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595097.2 | 510684.7 | 55838 | 1.64041666667 | 14971 |
| 015299 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:07am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595095.3 | 510684.3 | 55841 | 1.64041666667 | 15299 |
| 014883 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:07am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595093.3 | 510683.9 | 55842 | 1.64041666667 | 14883 |
| 015069 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:08am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595091.2 | 510683.8 | 55844 | 1.64041666667 | 15069 |
| 015241 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:09am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595089.5 | 510682.6 | 55846 | 1.64041666667 | 15241 |
| 015555 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:10am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595087.5 | 510682.1 | 55848 | 1.64041666667 | 15555 |
| 015845 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:11am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595086.2 | 510680.2 | 55850 | 1.64041666667 | 15845 |
| 016240 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:12am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595083.7 | 510678.6 | 55852 | 1.64041666667 | 16240 |
| 015960 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:13am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595081.9 | 510677.3 | 55854 | 1.64041666667 | 15960 |
| 015532 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:15am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595080.5 | 510675.1 | 55857 | 1.64041666667 | 15532 |
| 015397 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:15am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595078.8 | 510674.7 | 55858 | 1.64041666667 | 15397 |
| 015966 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:16am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595077.1 | 510673.0 | 55860 | 1.64041666667 | 15966 |
| 016121 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:17am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595075.1 | 510672.1 | 55862 | 1.64041666667 | 16121 |
| 015765 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:18am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595072.5 | 510671.9 | 55864 | 1.64041666667 | 15765 |
| 014628 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:19am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595070.5 | 510671.6 | 55866 | 1.64041666667 | 14628 |
| 015428 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:20am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595068.5 | 510672.6 | 55868 | 1.64041666667 | 15428 |
| 015608 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:21am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595066.7 | 510672.9 | 55870 | 1.64041666667 | 15608 |
| 015679 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:22am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595064.7 | 510674.1 | 55872 | 1.64041666667 | 15679 |
| 014865 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:23am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595063.0 | 510674.7 | 55874 | 1.64041666667 | 14865 |
| 014196 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:25am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595060.8 | 510675.0 | 55877 | 1.64041666667 | 14196 |
| 014578 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:25am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595059.4 | 510675.4 | 55878 | 1.64041666667 | 14578 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:26am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595057.2 | 510674.0 | 55880 | 1.64041666667 | 14132 |
| 013207 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:27am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595055.3 | 510673.4 | 55882 | 1.64041666667 | 13207 |
| 013759 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:28am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595052.9 | 510672.2 | 55884 | 1.64041666667 | 13759 |
| 014887 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:29am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595050.6 | 510671.2 | 55886 | 1.64041666667 | 14887 |
| 015393 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:30am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595048.2 | 510671.3 | 55888 | 1.64041666667 | 15393 |
| 013976 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:31am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595046.4 | 510670.6 | 55890 | 1.64041666667 | 13976 |
| 014934 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:32am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595044.2 | 510670.5 | 55892 | 1.64041666667 | 14934 |
| 016155 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:33am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595042.1 | 510670.1 | 55894 | 1.64041666667 | 16155 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015342 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:34am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595040.3 | 510668.3 | 55896 | 1.64041666667 | 15342 |
| 014495 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:35am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595038.4 | 510668.0 | 55898 | 1.64041666667 | 14495 |
| 015481 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:36am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595036.5 | 510666.8 | 55900 | 1.64041666667 | 15481 |
| 014730 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:37am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595034.7 | 510665.7 | 55902 | 1.64041666667 | 14730 |
| 015748 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:39am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595032.6 | 510664.5 | 55905 | 1.64041666667 | 15748 |
| 014941 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:39am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595031.4 | 510663.0 | 55906 | 1.64041666667 | 14941 |
| 014464 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:40am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595029.4 | 510662.3 | 55908 | 1.64041666667 | 14464 |
| 014833 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:41am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595028.8 | 510660.5 | 55910 | 1.64041666667 | 14833 |
| 014411 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:42am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595026.9 | 510660.1 | 55912 | 1.64041666667 | 14411 |
| 015779 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:43am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595024.8 | 510659.3 | 55914 | 1.64041666667 | 15779 |
| 015138 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:45am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595022.0 | 510658.7 | 55917 | 1.64041666667 | 15138 |
| 015602 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:45am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595019.9 | 510658.9 | 55918 | 1.64041666667 | 15602 |
| 017056 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:47am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595017.5 | 510658.2 | 55921 | 1.64041666667 | 17056 |
| 015969 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:48am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595015.2 | 510658.5 | 55923 | 1.64041666667 | 15969 |
| 015972 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:49am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595013.1 | 510657.9 | 55925 | 1.64041666667 | 15972 |
| 015689 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:50am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595010.7 | 510657.5 | 55927 | 1.64041666667 | 15689 |
| 014878 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:50am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595008.7 | 510658.2 | 55928 | 1.64041666667 | 14878 |
| 014541 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:51am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595006.2 | 510658.8 | 55930 | 1.64041666667 | 14541 |
| 014637 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:52am | Sensor | 1797-S0040-905-G-ACK | 6820.4 | 1595004.6 | 510660.4 | 55932 | 1.64041666667 | 14637 |
| 014435 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:53am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595003.8 | 510662.4 | 55934 | 1.64041666667 | 14435 |
| 014330 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:54am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1595003.4 | 510665.1 | 55936 | 1.64041666667 | 14330 |
| 015905 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:55am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595004.1 | 510667.0 | 55938 | 1.64041666667 | 15905 |
| 015329 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:56am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595004.1 | 510669.4 | 55940 | 1.64041666667 | 15329 |
| 014135 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:57am | Sensor | 1797-S0040-905-G-ACK | 6820.4 | 1595004.8 | 510671.4 | 55942 | 1.64041666667 | 14135 |
| 014363 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:58am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595004.2 | 510674.3 | 55944 | 1.64041666667 | 14363 |
| 014657 | 0 | GeoXH 6000 | 08/19/2015 | 10:38:59am | Sensor | 1797-S0040-905-G-ACK | 6820.4 | 1595004.8 | 510675.4 | 55946 | 1.64041666667 | 14657 |
| 014192 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:01am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595005.6 | 510676.7 | 55949 | 1.64041666667 | 14192 |
| 013960 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:01am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595006.8 | 510676.8 | 55950 | 1.64041666667 | 13960 |
| 014445 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:02am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595009.3 | 510676.0 | 55952 | 1.64041666667 | 14445 |
| 014208 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:03am | Sensor | 1797-S0040-905-G-ACK | 6820.4 | 1595011.4 | 510676.2 | 55954 | 1.64041666667 | 14208 |
| 013459 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:04am | Sensor | 1797-S0040-905-G-ACK | 6820.4 | 1595013.6 | 510675.4 | 55956 | 1.64041666667 | 13459 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:05am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595015.0 | 510673.7 | 55958 | 1.64041666667 | 13931 |
| 014511 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:06am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595016.5 | 510673.2 | 55960 | 1.64041666667 | 14511 |
| 014207 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:07am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595018.1 | 510672.3 | 55962 | 1.64041666667 | 14207 |
| 014704 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:08am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595020.2 | 510672.5 | 55964 | 1.64041666667 | 14704 |
| 015373 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:09am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595021.9 | 510672.1 | 55966 | 1.64041666667 | 15373 |
| 014632 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:10am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595024.0 | 510672.7 | 55968 | 1.64041666667 | 14632 |
| 015213 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:11am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595025.4 | 510674.4 | 55970 | 1.64041666667 | 15213 |
| 014505 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:13am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595027.7 | 510675.0 | 55973 | 1.64041666667 | 14505 |
| 014324 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:13am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595029.9 | 510675.5 | 55974 | 1.64041666667 | 14324 |
| 014589 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:15am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595032.6 | 510676.1 | 55977 | 1.64041666667 | 14589 |
| 014926 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:15am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595034.2 | 510676.0 | 55978 | 1.64041666667 | 14926 |
| 015176 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:16am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595036.3 | 510676.8 | 55980 | 1.64041666667 | 15176 |
| 015406 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:17am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595038.9 | 510677.4 | 55982 | 1.64041666667 | 15406 |
| 015213 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:18am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595041.0 | 510677.3 | 55984 | 1.64041666667 | 15213 |
| 014647 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:19am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595042.6 | 510678.2 | 55986 | 1.64041666667 | 14647 |
| 014494 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:21am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595045.4 | 510679.1 | 55989 | 1.64041666667 | 14494 |
| 014130 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:21am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595047.2 | 510679.4 | 55990 | 1.64041666667 | 14130 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015238 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:22am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595049.2 | 510681.0 | 55992 | 1.64041666667 | 15238 |
| 014451 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:23am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1595050.9 | 510681.9 | 55994 | 1.64041666667 | 14451 |
| 014106 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:25am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1595053.2 | 510683.3 | 55997 | 1.64041666667 | 14106 |
| 014167 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:25am | Sensor | 1797-S0040-905-G-ACK | 6819.9 | 1595053.7 | 510684.7 | 55998 | 1.64041666667 | 14167 |
| 014149 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:27am | Sensor | 1797-S0040-905-G-ACK | 6819.7 | 1595055.3 | 510686.0 | 56001 | 1.64041666667 | 14149 |
| 014438 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:27am | Sensor | 1797-S0040-905-G-ACK | 6819.3 | 1595056.3 | 510687.2 | 56002 | 1.64041666667 | 14438 |
| 013739 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:29am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1595057.8 | 510689.8 | 56005 | 1.64041666667 | 13739 |
| 014141 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:29am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1595059.2 | 510691.2 | 56006 | 1.64041666667 | 14141 |
| 014456 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:31am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1595061.0 | 510692.2 | 56009 | 1.64041666667 | 14456 |
| 013907 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:31am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1595062.4 | 510693.7 | 56010 | 1.64041666667 | 13907 |
| 014587 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:33am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1595065.0 | 510693.2 | 56013 | 1.64041666667 | 14587 |
| 014565 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:33am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1595067.0 | 510692.5 | 56014 | 1.64041666667 | 14565 |
| 014343 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:35am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1595069.6 | 510691.5 | 56017 | 1.64041666667 | 14343 |
| 013633 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:35am | Sensor | 1797-S0040-905-G-ACK | 6819.2 | 1595071.1 | 510690.7 | 56018 | 1.64041666667 | 13633 |
| 014103 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:37am | Sensor | 1797-S0040-905-G-ACK | 6819.2 | 1595073.5 | 510690.9 | 56021 | 1.64041666667 | 14103 |
| 014210 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:37am | Sensor | 1797-S0040-905-G-ACK | 6819.3 | 1595075.6 | 510691.6 | 56022 | 1.64041666667 | 14210 |
| 014113 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:39am | Sensor | 1797-S0040-905-G-ACK | 6819.9 | 1595077.8 | 510691.8 | 56025 | 1.64041666667 | 14113 |
| 014006 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:39am | Sensor | 1797-S0040-905-G-ACK | 6820.1 | 1595078.9 | 510692.3 | 56026 | 1.64041666667 | 14006 |
| 014336 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:40am | Sensor | 1797-S0040-905-G-ACK | 6820.2 | 1595080.8 | 510693.6 | 56028 | 1.64041666667 | 14336 |
| 014236 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:41am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595082.8 | 510694.0 | 56030 | 1.64041666667 | 14236 |
| 014443 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:43am | Sensor | 1797-S0040-905-G-ACK | 6820.3 | 1595085.2 | 510695.9 | 56033 | 1.64041666667 | 14443 |
| 015181 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:43am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595086.8 | 510697.1 | 56034 | 1.64041666667 | 15181 |
| 015679 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:45am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595088.8 | 510697.9 | 56037 | 1.64041666667 | 15679 |
| 015929 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:45am | Sensor | 1797-S0040-905-G-ACK | 6820.9 | 1595090.5 | 510698.7 | 56038 | 1.64041666667 | 15929 |
| 014852 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:46am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595092.9 | 510698.9 | 56040 | 1.64041666667 | 14852 |
| 014759 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:47am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595094.9 | 510698.5 | 56042 | 1.64041666667 | 14759 |
| 015029 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:48am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595097.5 | 510698.1 | 56044 | 1.64041666667 | 15029 |
| 015174 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:49am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595098.5 | 510696.7 | 56046 | 1.64041666667 | 15174 |
| 016057 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:50am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595098.9 | 510694.6 | 56048 | 1.64041666667 | 16057 |
| 015767 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:51am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595097.8 | 510693.1 | 56050 | 1.64041666667 | 15767 |
| 015476 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:53am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595096.0 | 510693.1 | 56053 | 1.64041666667 | 15476 |
| 015110 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:53am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595095.1 | 510691.9 | 56054 | 1.64041666667 | 15110 |
| 015519 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:55am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595093.3 | 510690.3 | 56057 | 1.64041666667 | 15519 |
| 015285 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:55am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595091.7 | 510689.8 | 56058 | 1.64041666667 | 15285 |
| 015287 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:56am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595090.6 | 510687.8 | 56060 | 1.64041666667 | 15287 |
| 014666 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:57am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595089.4 | 510686.8 | 56062 | 1.64041666667 | 14666 |
| 014940 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:58am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595089.8 | 510684.8 | 56064 | 1.64041666667 | 14940 |
| 015063 | 0 | GeoXH 6000 | 08/19/2015 | 10:39:59am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595090.6 | 510683.2 | 56066 | 1.64041666667 | 15063 |
| 014796 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:01am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595091.1 | 510680.8 | 56069 | 1.64041666667 | 14796 |
| 014427 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:01am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595092.4 | 510679.3 | 56070 | 1.64041666667 | 14427 |
| 014708 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:03am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595092.5 | 510676.9 | 56073 | 1.64041666667 | 14708 |
| 015945 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:03am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595093.2 | 510675.2 | 56074 | 1.64041666667 | 15945 |
| 015329 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:05am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595093.7 | 510672.9 | 56077 | 1.64041666667 | 15329 |
| 016168 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:05am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595093.6 | 510670.8 | 56078 | 1.64041666667 | 16168 |
| 015746 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:06am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595094.6 | 510668.8 | 56080 | 1.64041666667 | 15746 |
| 014947 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:07am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595094.5 | 510667.0 | 56082 | 1.64041666667 | 14947 |
| 014303 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:08am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595095.3 | 510665.0 | 56084 | 1.64041666667 | 14303 |
| 014780 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:09am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595095.4 | 510663.2 | 56086 | 1.64041666667 | 14780 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013991 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:10am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595096.0 | 510660.8 | 56088 | 1.64041666667 | 13991 |
| 013967 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:11am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595096.4 | 510658.8 | 56090 | 1.64041666667 | 13967 |
| 014149 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:13am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595096.4 | 510656.9 | 56093 | 1.64041666667 | 14149 |
| 014086 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:13am | Sensor | 1797-S0040-905-G-ACK | 6822.1 | 1595097.4 | 510655.3 | 56094 | 1.64041666667 | 14086 |
| 014748 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:15am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595097.0 | 510653.2 | 56097 | 1.64041666667 | 14748 |
| 014363 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:15am | Sensor | 1797-S0040-905-G-ACK | 6822.0 | 1595098.0 | 510651.4 | 56098 | 1.64041666667 | 14363 |
| 015159 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:17am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595098.2 | 510649.1 | 56101 | 1.64041666667 | 15159 |
| 016215 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:17am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595099.2 | 510648.0 | 56102 | 1.64041666667 | 16215 |
| 014918 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:18am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595099.9 | 510645.5 | 56104 | 1.64041666667 | 14918 |
| 014196 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:19am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595100.1 | 510643.9 | 56106 | 1.64041666667 | 14196 |
| 014743 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:21am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595100.7 | 510641.5 | 56109 | 1.64041666667 | 14743 |
| 015545 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:21am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595100.4 | 510639.3 | 56110 | 1.64041666667 | 15545 |
| 015411 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:22am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595101.2 | 510637.1 | 56112 | 1.64041666667 | 15411 |
| 014976 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:23am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595100.6 | 510635.3 | 56114 | 1.64041666667 | 14976 |
| 015406 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:24am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595101.2 | 510633.3 | 56116 | 1.64041666667 | 15406 |
| 016556 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:25am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595100.9 | 510631.5 | 56118 | 1.64041666667 | 16556 |
| 015395 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:26am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595101.5 | 510629.2 | 56120 | 1.64041666667 | 15395 |
| 015162 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:27am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595101.6 | 510627.2 | 56122 | 1.64041666667 | 15162 |
| 014318 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:28am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595101.5 | 510624.8 | 56124 | 1.64041666667 | 14318 |
| 014257 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:29am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595102.4 | 510623.2 | 56126 | 1.64041666667 | 14257 |
| 014687 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:30am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595101.6 | 510621.2 | 56128 | 1.64041666667 | 14687 |
| 014906 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:31am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595102.3 | 510619.2 | 56130 | 1.64041666667 | 14906 |
| 016005 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:33am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595101.5 | 510617.3 | 56133 | 1.64041666667 | 16005 |
| 016015 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:33am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595102.1 | 510615.1 | 56134 | 1.64041666667 | 16015 |
| 015796 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:34am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595101.3 | 510613.6 | 56136 | 1.64041666667 | 15796 |
| 015695 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:35am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595100.9 | 510612.6 | 56138 | 1.64041666667 | 15695 |
| 014821 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:36am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595100.5 | 510614.3 | 56140 | 1.64041666667 | 14821 |
| 014869 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:37am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595100.5 | 510616.5 | 56142 | 1.64041666667 | 14869 |
| 014514 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:38am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595098.8 | 510618.5 | 56144 | 1.64041666667 | 14514 |
| 014809 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:39am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595097.1 | 510620.6 | 56146 | 1.64041666667 | 14809 |
| 015282 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:40am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595095.8 | 510622.9 | 56148 | 1.64041666667 | 15282 |
| 015346 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:41am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595093.9 | 510624.3 | 56150 | 1.64041666667 | 15346 |
| 014902 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:42am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595092.0 | 510626.1 | 56152 | 1.64041666667 | 14902 |
| 015327 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:43am | Sensor | 1797-S0040-905-G-ACK | 6821.8 | 1595091.0 | 510627.8 | 56154 | 1.64041666667 | 15327 |
| 015971 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:44am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595088.8 | 510629.1 | 56156 | 1.64041666667 | 15971 |
| 015584 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:45am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595087.6 | 510631.5 | 56158 | 1.64041666667 | 15584 |
| 015171 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:46am | Sensor | 1797-S0040-905-G-ACK | 6821.7 | 1595086.3 | 510633.5 | 56160 | 1.64041666667 | 15171 |
| 015006 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:47am | Sensor | 1797-S0040-905-G-ACK | 6821.6 | 1595084.4 | 510634.9 | 56162 | 1.64041666667 | 15006 |
| 014621 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:48am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595082.7 | 510636.8 | 56164 | 1.64041666667 | 14621 |
| 014614 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:49am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595081.2 | 510639.0 | 56166 | 1.64041666667 | 14614 |
| 015045 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:51am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595078.7 | 510640.1 | 56169 | 1.64041666667 | 15045 |
| 015408 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:51am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595077.1 | 510641.8 | 56170 | 1.64041666667 | 15408 |
| 014337 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:53am | Sensor | 1797-S0040-905-G-ACK | 6821.2 | 1595074.8 | 510643.0 | 56173 | 1.64041666667 | 14337 |
| 014364 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:53am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595072.7 | 510643.9 | 56174 | 1.64041666667 | 14364 |
| 014665 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:55am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595070.8 | 510645.7 | 56177 | 1.64041666667 | 14665 |
| 014999 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:55am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595068.4 | 510646.6 | 56178 | 1.64041666667 | 14999 |
| 015502 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:56am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595066.0 | 510647.8 | 56180 | 1.64041666667 | 15502 |
| 014922 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:57am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595064.5 | 510649.3 | 56182 | 1.64041666667 | 14922 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014791 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:58am | Sensor | 1797-S0040-905-G-ACK | 6821.5 | 1595062.0 | 510650.5 | 56184 | 1.64041666667 | 14791 |
| 015745 | 0 | GeoXH 6000 | 08/19/2015 | 10:40:59am | Sensor | 1797-S0040-905-G-ACK | 6821.4 | 1595060.7 | 510652.0 | 56186 | 1.64041666667 | 15745 |
| 015239 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:01am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595058.8 | 510654.1 | 56189 | 1.64041666667 | 15239 |
| 015442 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:01am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595056.7 | 510655.3 | 56190 | 1.64041666667 | 15442 |
| 015953 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:02am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595054.6 | 510657.2 | 56192 | 1.64041666667 | 15953 |
| 015708 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:03am | Sensor | 1797-S0040-905-G-ACK | 6821.1 | 1595052.8 | 510659.0 | 56194 | 1.64041666667 | 15708 |
| 015346 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:04am | Sensor | 1797-S0040-905-G-ACK | 6821.0 | 1595050.4 | 510660.7 | 56196 | 1.64041666667 | 15346 |
| 015022 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:05am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595048.9 | 510662.7 | 56198 | 1.64041666667 | 15022 |
| 014922 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:06am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595047.2 | 510665.0 | 56200 | 1.64041666667 | 14922 |
| 014941 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:07am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595045.2 | 510666.6 | 56202 | 1.64041666667 | 14941 |
| 014082 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:09am | Sensor | 1797-S0040-905-G-ACK | 6820.5 | 1595043.3 | 510668.8 | 56205 | 1.64041666667 | 14082 |
| 013898 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:09am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595041.7 | 510670.7 | 56206 | 1.64041666667 | 13898 |
| 014845 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:10am | Sensor | 1797-S0040-905-G-ACK | 6820.8 | 1595039.4 | 510672.1 | 56208 | 1.64041666667 | 14845 |
| 015100 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:11am | Sensor | 1797-S0040-905-G-ACK | 6821.3 | 1595038.3 | 510673.6 | 56210 | 1.64041666667 | 15100 |
| 014434 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:12am | Sensor | 1797-S0040-905-G-ACK | 6820.7 | 1595036.8 | 510675.2 | 56212 | 1.64041666667 | 14434 |
| 014065 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:13am | Sensor | 1797-S0040-905-G-ACK | 6820.6 | 1595034.8 | 510676.7 | 56214 | 1.64041666667 | 14065 |
| 013942 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:14am | Sensor | 1797-S0040-905-G-ACK | 6820.0 | 1595032.5 | 510678.5 | 56216 | 1.64041666667 | 13942 |
| 013992 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:15am | Sensor | 1797-S0040-905-G-ACK | 6820.0 | 1595030.9 | 510680.0 | 56218 | 1.64041666667 | 13992 |
| 013525 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:16am | Sensor | 1797-S0040-905-G-ACK | 6819.8 | 1595028.2 | 510681.4 | 56220 | 1.64041666667 | 13525 |
| 013630 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:17am | Sensor | 1797-S0040-905-G-ACK | 6819.5 | 1595026.8 | 510683.2 | 56222 | 1.64041666667 | 13630 |
| 014379 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:18am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1595024.9 | 510685.4 | 56224 | 1.64041666667 | 14379 |
| 014111 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:19am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1595023.0 | 510687.3 | 56226 | 1.64041666667 | 14111 |
| 013892 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:20am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1595021.7 | 510690.0 | 56228 | 1.64041666667 | 13892 |
| 014017 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:21am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1595020.1 | 510692.2 | 56230 | 1.64041666667 | 14017 |
| 014177 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:22am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1595017.6 | 510694.0 | 56232 | 1.64041666667 | 14177 |
| 014199 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:23am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1595015.9 | 510695.7 | 56234 | 1.64041666667 | 14199 |
| 014107 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:24am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1595013.9 | 510698.2 | 56236 | 1.64041666667 | 14107 |
| 014565 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:25am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1595011.6 | 510699.9 | 56238 | 1.64041666667 | 14565 |
| 014583 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:26am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1595009.8 | 510701.8 | 56240 | 1.64041666667 | 14583 |
| 014443 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:27am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1595008.0 | 510703.7 | 56242 | 1.64041666667 | 14443 |
| 013846 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:28am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1595005.8 | 510704.7 | 56244 | 1.64041666667 | 13846 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:29am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1595004.6 | 510706.7 | 56246 | 1.64041666667 | 12918 |
| 013506 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:30am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1595002.7 | 510708.3 | 56248 | 1.64041666667 | 13506 |
| 013882 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:31am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1595000.6 | 510709.5 | 56250 | 1.64041666667 | 13882 |
| 012954 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:32am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594999.6 | 510711.4 | 56252 | 1.64041666667 | 12954 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:33am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594998.1 | 510712.1 | 56254 | 1.64041666667 | 11959 |
| 011782 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:35am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594996.2 | 510713.4 | 56257 | 1.64041666667 | 11782 |
| 011224 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:35am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594995.4 | 510715.4 | 56258 | 1.64041666667 | 11224 |
| 010821 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:36am | Sensor | 1797-S0040-905-G-ACK | 6818.0 | 1594993.4 | 510717.0 | 56260 | 1.64041666667 | 10821 |
| 011104 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:37am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594991.6 | 510718.8 | 56262 | 1.64041666667 | 11104 |
| 011466 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:38am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594990.2 | 510721.2 | 56264 | 1.64041666667 | 11466 |
| 011445 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:39am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594988.7 | 510723.0 | 56266 | 1.64041666667 | 11445 |
| 011380 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:40am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594986.7 | 510725.2 | 56268 | 1.64041666667 | 11380 |
| 011546 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:41am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594986.0 | 510727.5 | 56270 | 1.64041666667 | 11546 |
| 011362 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:42am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594984.5 | 510729.6 | 56272 | 1.64041666667 | 11362 |
| 010658 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:43am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594982.4 | 510731.1 | 56274 | 1.64041666667 | 10658 |
| 010353 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:44am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594981.1 | 510733.5 | 56276 | 1.64041666667 | 10353 |
| 010796 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:45am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594979.4 | 510735.1 | 56278 | 1.64041666667 | 10796 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011090 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:46am | Sensor | 1797-S0040-905-G-ACK | 6818.0 | 1594977.0 | 510737.4 | 56280 | 1.64041666667 | 11090 |
| 011525 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:47am | Sensor | 1797-S0040-905-G-ACK | 6818.0 | 1594975.8 | 510739.3 | 56282 | 1.64041666667 | 11525 |
| 011771 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:48am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594973.8 | 510740.6 | 56284 | 1.64041666667 | 11771 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:49am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594972.0 | 510740.7 | 56286 | 1.64041666667 | 12163 |
| 012249 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:50am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594969.4 | 510741.0 | 56288 | 1.64041666667 | 12249 |
| 012358 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:51am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594966.8 | 510740.0 | 56290 | 1.64041666667 | 12358 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:52am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594963.7 | 510738.4 | 56292 | 1.64041666667 | 12163 |
| 012572 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:53am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594961.1 | 510737.9 | 56294 | 1.64041666667 | 12572 |
| 011647 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:54am | Sensor | 1797-S0040-905-G-ACK | 6817.9 | 1594957.8 | 510737.3 | 56296 | 1.64041666667 | 11647 |
| 012176 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:55am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594955.6 | 510736.8 | 56298 | 1.64041666667 | 12176 |
| 012361 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:56am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594953.2 | 510737.4 | 56300 | 1.64041666667 | 12361 |
| 012788 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:57am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1594951.5 | 510738.2 | 56302 | 1.64041666667 | 12788 |
| 013621 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:58am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594949.1 | 510739.1 | 56304 | 1.64041666667 | 13621 |
| 014651 | 0 | GeoXH 6000 | 08/19/2015 | 10:41:59am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594947.4 | 510741.0 | 56306 | 1.64041666667 | 14651 |
| 014421 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:00am | Sensor | 1797-S0040-905-G-ACK | 6819.3 | 1594946.3 | 510743.6 | 56308 | 1.64041666667 | 14421 |
| 014089 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:01am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1594944.8 | 510745.5 | 56310 | 1.64041666667 | 14089 |
| 013790 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:02am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594943.3 | 510748.0 | 56312 | 1.64041666667 | 13790 |
| 014034 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:03am | Sensor | 1797-S0040-905-G-ACK | 6819.2 | 1594942.5 | 510750.3 | 56314 | 1.64041666667 | 14034 |
| 014359 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:04am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1594940.3 | 510752.7 | 56316 | 1.64041666667 | 14359 |
| 015292 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:05am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594938.6 | 510754.5 | 56318 | 1.64041666667 | 15292 |
| 014887 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:06am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1594936.7 | 510756.7 | 56320 | 1.64041666667 | 14887 |
| 015491 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:07am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594934.2 | 510757.5 | 56322 | 1.64041666667 | 15491 |
| 015741 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:08am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594931.2 | 510758.0 | 56324 | 1.64041666667 | 15741 |
| 015252 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:09am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594929.2 | 510759.4 | 56326 | 1.64041666667 | 15252 |
| 014999 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:10am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594926.7 | 510761.0 | 56328 | 1.64041666667 | 14999 |
| 014759 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:11am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1594924.4 | 510762.1 | 56330 | 1.64041666667 | 14759 |
| 014842 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:12am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594922.9 | 510764.2 | 56332 | 1.64041666667 | 14842 |
| 015361 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:13am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594921.2 | 510765.8 | 56334 | 1.64041666667 | 15361 |
| 015503 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:14am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594919.0 | 510766.5 | 56336 | 1.64041666667 | 15503 |
| 015478 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:15am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594917.1 | 510767.6 | 56338 | 1.64041666667 | 15478 |
| 014886 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:16am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594915.3 | 510769.6 | 56340 | 1.64041666667 | 14886 |
| 015491 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:17am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594913.1 | 510770.2 | 56342 | 1.64041666667 | 15491 |
| 014961 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:18am | Sensor | 1797-S0040-905-G-ACK | 6818.8 | 1594911.3 | 510771.7 | 56344 | 1.64041666667 | 14961 |
| 014730 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:19am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594909.8 | 510773.6 | 56346 | 1.64041666667 | 14730 |
| 014946 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:20am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594908.0 | 510776.5 | 56348 | 1.64041666667 | 14946 |
| 015037 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:21am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594907.3 | 510779.1 | 56350 | 1.64041666667 | 15037 |
| 014931 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:23am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594906.7 | 510782.3 | 56353 | 1.64041666667 | 14931 |
| 015658 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:23am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594906.0 | 510784.7 | 56354 | 1.64041666667 | 15658 |
| 015288 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:24am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594904.6 | 510787.3 | 56356 | 1.64041666667 | 15288 |
| 014809 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:25am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594903.1 | 510789.2 | 56358 | 1.64041666667 | 14809 |
| 015477 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:26am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594901.5 | 510791.7 | 56360 | 1.64041666667 | 15477 |
| 016078 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:27am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594900.5 | 510793.6 | 56362 | 1.64041666667 | 16078 |
| 016177 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:28am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594898.6 | 510795.2 | 56364 | 1.64041666667 | 16177 |
| 016247 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:29am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594897.8 | 510797.3 | 56366 | 1.64041666667 | 16247 |
| 016488 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:30am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594899.0 | 510799.8 | 56368 | 1.64041666667 | 16488 |
| 015890 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:31am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594900.3 | 510801.8 | 56370 | 1.64041666667 | 15890 |
| 015403 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:33am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594901.4 | 510804.2 | 56373 | 1.64041666667 | 15403 |
| 016884 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:33am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594902.6 | 510806.3 | 56374 | 1.64041666667 | 16884 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017702 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:35am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594903.6 | 510809.1 | 56377 | 1.64041666667 | 17702 |
| 016902 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:35am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594903.7 | 510811.3 | 56378 | 1.64041666667 | 16902 |
| 015845 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:36am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594903.2 | 510814.0 | 56380 | 1.64041666667 | 15845 |
| 015138 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:37am | Sensor | 1797-S0040-905-G-ACK | 6818.1 | 1594902.7 | 510816.0 | 56382 | 1.64041666667 | 15138 |
| 015512 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:38am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594901.9 | 510818.3 | 56384 | 1.64041666667 | 15512 |
| 014823 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:39am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594901.0 | 510819.4 | 56386 | 1.64041666667 | 14823 |
| 013798 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:40am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594900.7 | 510819.6 | 56388 | 1.64041666667 | 13798 |
| 014706 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:41am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594900.7 | 510819.5 | 56390 | 1.64041666667 | 14706 |
| 014827 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:43am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594900.9 | 510819.7 | 56393 | 1.64041666667 | 14827 |
| 015900 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:43am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594901.5 | 510820.5 | 56394 | 1.64041666667 | 15900 |
| 015738 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:45am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594900.4 | 510823.2 | 56397 | 1.64041666667 | 15738 |
| 015438 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:45am | Sensor | 1797-S0040-905-G-ACK | 6818.7 | 1594899.0 | 510825.4 | 56398 | 1.64041666667 | 15438 |
| 015396 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:46am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594898.5 | 510827.2 | 56400 | 1.64041666667 | 15396 |
| 015305 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:47am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1594898.0 | 510827.9 | 56402 | 1.64041666667 | 15305 |
| 015704 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:48am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1594898.3 | 510828.5 | 56404 | 1.64041666667 | 15704 |
| 015553 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:49am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594897.6 | 510829.0 | 56406 | 1.64041666667 | 15553 |
| 015596 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:50am | Sensor | 1797-S0040-905-G-ACK | 6819.1 | 1594897.9 | 510830.2 | 56408 | 1.64041666667 | 15596 |
| 015313 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:51am | Sensor | 1797-S0040-905-G-ACK | 6819.0 | 1594897.1 | 510831.2 | 56410 | 1.64041666667 | 15313 |
| 015491 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:53am | Sensor | 1797-S0040-905-G-ACK | 6818.9 | 1594896.6 | 510833.0 | 56413 | 1.64041666667 | 15491 |
| 014608 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:53am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594895.5 | 510834.1 | 56414 | 1.64041666667 | 14608 |
| 015019 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:54am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594894.2 | 510836.3 | 56416 | 1.64041666667 | 15019 |
| 014415 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:55am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594892.7 | 510838.0 | 56418 | 1.64041666667 | 14415 |
| 014383 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:56am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594890.2 | 510839.7 | 56420 | 1.64041666667 | 14383 |
| 013663 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:57am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594887.8 | 510840.3 | 56422 | 1.64041666667 | 13663 |
| 013948 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:58am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594885.3 | 510841.3 | 56424 | 1.64041666667 | 13948 |
| 014228 | 0 | GeoXH 6000 | 08/19/2015 | 10:42:59am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594883.3 | 510842.3 | 56426 | 1.64041666667 | 14228 |
| 013981 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:00am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594880.7 | 510842.8 | 56428 | 1.64041666667 | 13981 |
| 012859 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:01am | Sensor | 1797-S0040-905-G-ACK | 6818.5 | 1594878.9 | 510843.6 | 56430 | 1.64041666667 | 12859 |
| 013121 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:02am | Sensor | 1797-S0040-905-G-ACK | 6818.6 | 1594876.8 | 510844.5 | 56432 | 1.64041666667 | 13121 |
| 013403 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:03am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594874.6 | 510844.5 | 56434 | 1.64041666667 | 13403 |
| 013321 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:05am | Sensor | 1797-S0040-905-G-ACK | 6818.4 | 1594871.5 | 510844.4 | 56437 | 1.64041666667 | 13321 |
| 013440 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:05am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594869.3 | 510845.1 | 56438 | 1.64041666667 | 13440 |
| 013365 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:06am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594866.0 | 510845.6 | 56440 | 1.64041666667 | 13365 |
| 014035 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:07am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594863.4 | 510845.5 | 56442 | 1.64041666667 | 14035 |
| 014352 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:08am | Sensor | 1797-S0040-905-G-ACK | 6818.3 | 1594860.4 | 510845.7 | 56444 | 1.64041666667 | 14352 |
| 013960 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:09am | Sensor | 1797-S0040-905-G-ACK | 6818.2 | 1594858.1 | 510846.6 | 56446 | 1.64041666667 | 13960 |
| 014392 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:10am | Sensor | 1797-S0040-905-G-ACK | 6817.6 | 1594855.2 | 510847.5 | 56448 | 1.64041666667 | 14392 |
| 014411 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:11am | Sensor | 1797-S0040-905-G-ACK | 6817.6 | 1594852.4 | 510848.8 | 56450 | 1.64041666667 | 14411 |
| 014383 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:12am | Sensor | 1797-S0040-905-G-ACK | 6817.7 | 1594850.0 | 510850.7 | 56452 | 1.64041666667 | 14383 |
| 014608 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:13am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594848.4 | 510852.2 | 56454 | 1.64041666667 | 14608 |
| 014179 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:14am | Sensor | 1797-S0040-905-G-ACK | 6817.8 | 1594846.5 | 510854.4 | 56456 | 1.64041666667 | 14179 |
| 014351 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:15am | Sensor | 1797-S0040-905-G-ACK | 6817.7 | 1594845.3 | 510856.5 | 56458 | 1.64041666667 | 14351 |
| 014800 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:16am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594843.7 | 510859.2 | 56460 | 1.64041666667 | 14800 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:17am | Sensor | 1797-S0040-905-G-ACK | 6817.3 | 1594842.2 | 510861.0 | 56462 | 1.64041666667 | 14737 |
| 014139 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:18am | Sensor | 1797-S0040-905-G-ACK | 6817.6 | 1594840.1 | 510863.1 | 56464 | 1.64041666667 | 14139 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:19am | Sensor | 1797-S0040-905-G-ACK | 6817.3 | 1594837.7 | 510863.9 | 56466 | 1.64041666667 | 13811 |
| 013708 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:20am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594834.6 | 510864.6 | 56468 | 1.64041666667 | 13708 |
| 014206 | 0 | GeoXH 6000 | 08/19/2015 | 10:43:21am | Sensor | 1797-S0040-905-G-ACK | 6817.5 | 1594834.6 | 510864.6 | 56471 | 1.64041666667 | 14206 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014170 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:39pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594605.1 | 512152.9 | 52117 | 1.64041666667 | 14170 |
| 013948 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:40pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594605.1 | 512152.9 | 52118 | 1.64041666667 | 13948 |
| 013283 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:40pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594605.1 | 512152.9 | 52119 | 1.64041666667 | 13283 |
| 014717 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:42pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594605.1 | 512152.9 | 52123 | 1.64041666667 | 14717 |
| 014008 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:43pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594604.8 | 512151.8 | 52125 | 1.64041666667 | 14008 |
| 013707 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:44pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594606.1 | 512151.7 | 52127 | 1.64041666667 | 13707 |
| 013365 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:44pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594607.4 | 512151.2 | 52128 | 1.64041666667 | 13365 |
| 013278 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:46pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594609.5 | 512152.1 | 52131 | 1.64041666667 | 13278 |
| 013514 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:46pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594611.2 | 512152.0 | 52132 | 1.64041666667 | 13514 |
| 013504 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:48pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594611.8 | 512152.7 | 52135 | 1.64041666667 | 13504 |
| 013476 | 0 | GeoXH 6000 | 08/19/2015 | 02:35:48pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594611.8 | 512153.3 | 52136 | 1.64041666667 | 13476 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:09pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512781.8 | 52137 | 1.64041666667 | 12056 |
| 011522 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:10pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52139 | 1.64041666667 | 11522 |
| 011618 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:11pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52141 | 1.64041666667 | 11618 |
| 011380 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:12pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52143 | 1.64041666667 | 11380 |
| 012049 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:13pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52145 | 1.64041666667 | 12049 |
| 012320 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:14pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52147 | 1.64041666667 | 12320 |
| 011640 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:15pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52149 | 1.64041666667 | 11640 |
| 011175 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:16pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52151 | 1.64041666667 | 11175 |
| 011596 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:17pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52153 | 1.64041666667 | 11596 |
| 010842 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:18pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52155 | 1.64041666667 | 10842 |
| 011461 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:19pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594607.7 | 512782.0 | 52157 | 1.64041666667 | 11461 |
| 011344 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:20pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594607.6 | 512782.0 | 52159 | 1.64041666667 | 11344 |
| 011556 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:21pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594607.6 | 512782.1 | 52161 | 1.64041666667 | 11556 |
| 012290 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:22pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594607.6 | 512782.2 | 52163 | 1.64041666667 | 12290 |
| 012620 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:23pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594607.7 | 512782.3 | 52165 | 1.64041666667 | 12620 |
| 012296 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:24pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594607.3 | 512782.2 | 52167 | 1.64041666667 | 12296 |
| 012129 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:25pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594606.5 | 512781.7 | 52169 | 1.64041666667 | 12129 |
| 012492 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:26pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594606.9 | 512781.9 | 52171 | 1.64041666667 | 12492 |
| 012172 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:27pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594607.8 | 512783.1 | 52173 | 1.64041666667 | 12172 |
| 012569 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:28pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594608.3 | 512783.1 | 52175 | 1.64041666667 | 12569 |
| 012792 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:29pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594609.5 | 512780.9 | 52177 | 1.64041666667 | 12792 |
| 012573 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:30pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594610.5 | 512778.7 | 52179 | 1.64041666667 | 12573 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:31pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594611.3 | 512775.8 | 52181 | 1.64041666667 | 12652 |
| 012689 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:32pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594610.1 | 512773.6 | 52183 | 1.64041666667 | 12689 |
| 012583 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:33pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594607.3 | 512771.9 | 52185 | 1.64041666667 | 12583 |
| 011765 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:34pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594604.1 | 512770.0 | 52187 | 1.64041666667 | 11765 |
| 012858 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:35pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594600.1 | 512767.6 | 52189 | 1.64041666667 | 12858 |
| 012752 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:36pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594596.6 | 512765.7 | 52191 | 1.64041666667 | 12752 |
| 012348 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:37pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594592.5 | 512763.9 | 52193 | 1.64041666667 | 12348 |
| 012046 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:38pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594588.9 | 512762.5 | 52195 | 1.64041666667 | 12046 |
| 012408 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:39pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594584.9 | 512760.8 | 52197 | 1.64041666667 | 12408 |
| 012559 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:40pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594581.5 | 512759.1 | 52199 | 1.64041666667 | 12559 |
| 012825 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:41pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594578.1 | 512757.1 | 52201 | 1.64041666667 | 12825 |
| 012134 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:42pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594575.3 | 512755.5 | 52203 | 1.64041666667 | 12134 |
| 012885 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594571.9 | 512754.2 | 52205 | 1.64041666667 | 12885 |
| 012955 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:44pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594568.9 | 512753.3 | 52207 | 1.64041666667 | 12955 |
| 012185 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:45pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594565.0 | 512752.0 | 52209 | 1.64041666667 | 12185 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012389 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:46pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594562.0 | 512750.9 | 52211 | 1.64041666667 | 12389 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:47pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594558.8 | 512749.8 | 52213 | 1.64041666667 | 12106 |
| 011602 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:48pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594556.0 | 512748.5 | 52215 | 1.64041666667 | 11602 |
| 012196 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:49pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594552.8 | 512746.9 | 52217 | 1.64041666667 | 12196 |
| 012477 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:50pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594549.5 | 512745.4 | 52219 | 1.64041666667 | 12477 |
| 011871 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:51pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594545.9 | 512744.1 | 52221 | 1.64041666667 | 11871 |
| 011275 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:52pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594542.8 | 512742.9 | 52223 | 1.64041666667 | 11275 |
| 011367 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:53pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594539.6 | 512741.4 | 52225 | 1.64041666667 | 11367 |
| 012101 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:54pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594536.7 | 512740.1 | 52227 | 1.64041666667 | 12101 |
| 012732 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:55pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594533.4 | 512739.3 | 52229 | 1.64041666667 | 12732 |
| 012719 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:56pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594530.6 | 512738.6 | 52231 | 1.64041666667 | 12719 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:57pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594527.2 | 512736.9 | 52233 | 1.64041666667 | 12787 |
| 013005 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:58pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594524.3 | 512735.4 | 52235 | 1.64041666667 | 13005 |
| 013045 | 0 | GeoXH 6000 | 08/19/2015 | 02:52:59pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594521.3 | 512734.3 | 52237 | 1.64041666667 | 13045 |
| 012798 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:00pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594519.0 | 512733.2 | 52239 | 1.64041666667 | 12798 |
| 012081 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:01pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594515.8 | 512731.8 | 52241 | 1.64041666667 | 12081 |
| 012698 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:02pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594513.4 | 512731.6 | 52243 | 1.64041666667 | 12698 |
| 012490 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:03pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594510.9 | 512732.2 | 52245 | 1.64041666667 | 12490 |
| 012367 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:04pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594509.1 | 512732.7 | 52247 | 1.64041666667 | 12367 |
| 012256 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:05pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594507.8 | 512734.2 | 52249 | 1.64041666667 | 12256 |
| 012864 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:06pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594506.5 | 512736.5 | 52251 | 1.64041666667 | 12864 |
| 012981 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:07pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594504.5 | 512739.8 | 52253 | 1.64041666667 | 12981 |
| 013564 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:08pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594503.3 | 512742.6 | 52255 | 1.64041666667 | 13564 |
| 012392 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:09pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594501.9 | 512746.5 | 52257 | 1.64041666667 | 12392 |
| 012986 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:10pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594500.5 | 512750.0 | 52259 | 1.64041666667 | 12986 |
| 012457 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:11pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594498.9 | 512754.2 | 52261 | 1.64041666667 | 12457 |
| 012587 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:12pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594497.9 | 512757.4 | 52263 | 1.64041666667 | 12587 |
| 012637 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:13pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594496.8 | 512761.7 | 52265 | 1.64041666667 | 12637 |
| 012456 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:14pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594495.7 | 512765.2 | 52267 | 1.64041666667 | 12456 |
| 012571 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:15pm | Sensor | 1797-S0039-G-636-DTE | 6826.9 | 1594494.3 | 512768.7 | 52269 | 1.64041666667 | 12571 |
| 012524 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:16pm | Sensor | 1797-S0039-G-636-DTE | 6826.2 | 1594492.1 | 512772.3 | 52271 | 1.64041666667 | 12524 |
| 013442 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:17pm | Sensor | 1797-S0039-G-636-DTE | 6826.0 | 1594489.7 | 512776.1 | 52273 | 1.64041666667 | 13442 |
| 013208 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:18pm | Sensor | 1797-S0039-G-636-DTE | 6826.0 | 1594487.8 | 512779.7 | 52275 | 1.64041666667 | 13208 |
| 012994 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:19pm | Sensor | 1797-S0039-G-636-DTE | 6825.8 | 1594485.7 | 512783.9 | 52277 | 1.64041666667 | 12994 |
| 012349 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:20pm | Sensor | 1797-S0039-G-636-DTE | 6825.9 | 1594484.5 | 512787.4 | 52279 | 1.64041666667 | 12349 |
| 011806 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:21pm | Sensor | 1797-S0039-G-636-DTE | 6825.9 | 1594483.6 | 512791.3 | 52281 | 1.64041666667 | 11806 |
| 011553 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:22pm | Sensor | 1797-S0039-G-636-DTE | 6825.8 | 1594482.2 | 512795.4 | 52283 | 1.64041666667 | 11553 |
| 011643 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:23pm | Sensor | 1797-S0039-G-636-DTE | 6825.6 | 1594480.2 | 512799.5 | 52285 | 1.64041666667 | 11643 |
| 011379 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:24pm | Sensor | 1797-S0039-G-636-DTE | 6825.7 | 1594478.3 | 512803.1 | 52287 | 1.64041666667 | 11379 |
| 012101 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:25pm | Sensor | 1797-S0039-G-636-DTE | 6825.7 | 1594476.4 | 512806.9 | 52289 | 1.64041666667 | 12101 |
| 011951 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:26pm | Sensor | 1797-S0039-G-636-DTE | 6825.8 | 1594474.5 | 512809.9 | 52291 | 1.64041666667 | 11951 |
| 012220 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:27pm | Sensor | 1797-S0039-G-636-DTE | 6826.0 | 1594472.3 | 512812.2 | 52293 | 1.64041666667 | 12220 |
| 012048 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:28pm | Sensor | 1797-S0039-G-636-DTE | 6826.4 | 1594471.0 | 512814.9 | 52295 | 1.64041666667 | 12048 |
| 011262 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:29pm | Sensor | 1797-S0039-G-636-DTE | 6827.0 | 1594470.5 | 512818.1 | 52297 | 1.64041666667 | 11262 |
| 011562 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:30pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594470.2 | 512821.0 | 52299 | 1.64041666667 | 11562 |
| 011131 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:31pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594469.7 | 512824.0 | 52301 | 1.64041666667 | 11131 |
| 011654 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:32pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594469.1 | 512826.8 | 52303 | 1.64041666667 | 11654 |
| 012382 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:33pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594469.8 | 512830.0 | 52305 | 1.64041666667 | 12382 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012507 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:34pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594471.9 | 512832.2 | 52307 | 1.64041666667 | 12507 |
| 012945 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:35pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594475.3 | 512834.3 | 52309 | 1.64041666667 | 12945 |
| 013462 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:36pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594478.7 | 512836.3 | 52311 | 1.64041666667 | 13462 |
| 012844 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:37pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594482.3 | 512838.4 | 52313 | 1.64041666667 | 12844 |
| 013052 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:38pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594485.3 | 512840.0 | 52315 | 1.64041666667 | 13052 |
| 012487 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:39pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594489.3 | 512841.2 | 52317 | 1.64041666667 | 12487 |
| 012619 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:40pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594492.9 | 512842.0 | 52319 | 1.64041666667 | 12619 |
| 012558 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:41pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594496.8 | 512843.4 | 52321 | 1.64041666667 | 12558 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:42pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594500.1 | 512844.9 | 52323 | 1.64041666667 | 12539 |
| 012498 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:43pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594503.3 | 512846.6 | 52325 | 1.64041666667 | 12498 |
| 012062 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:44pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594506.6 | 512848.2 | 52327 | 1.64041666667 | 12062 |
| 011780 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:45pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594509.6 | 512849.5 | 52329 | 1.64041666667 | 11780 |
| 012671 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:46pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594512.9 | 512850.9 | 52331 | 1.64041666667 | 12671 |
| 012137 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:47pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594516.0 | 512851.9 | 52333 | 1.64041666667 | 12137 |
| 011335 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:48pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594518.9 | 512852.8 | 52335 | 1.64041666667 | 11335 |
| 011566 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:49pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594522.5 | 512853.8 | 52337 | 1.64041666667 | 11566 |
| 012303 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:50pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594525.6 | 512854.7 | 52339 | 1.64041666667 | 12303 |
| 012455 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:51pm | Sensor | 1797-S0039-G-636-DTE | 6827.2 | 1594529.1 | 512856.2 | 52341 | 1.64041666667 | 12455 |
| 012458 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:52pm | Sensor | 1797-S0039-G-636-DTE | 6827.2 | 1594531.9 | 512857.0 | 52343 | 1.64041666667 | 12458 |
| 012445 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:53pm | Sensor | 1797-S0039-G-636-DTE | 6827.2 | 1594535.7 | 512857.7 | 52345 | 1.64041666667 | 12445 |
| 012685 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:54pm | Sensor | 1797-S0039-G-636-DTE | 6827.1 | 1594538.7 | 512858.4 | 52347 | 1.64041666667 | 12685 |
| 012610 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:55pm | Sensor | 1797-S0039-G-636-DTE | 6827.1 | 1594542.1 | 512859.1 | 52349 | 1.64041666667 | 12610 |
| 012081 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:56pm | Sensor | 1797-S0039-G-636-DTE | 6827.1 | 1594544.8 | 512859.7 | 52351 | 1.64041666667 | 12081 |
| 011880 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:57pm | Sensor | 1797-S0039-G-636-DTE | 6827.2 | 1594547.8 | 512861.2 | 52353 | 1.64041666667 | 11880 |
| 011835 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:58pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594550.5 | 512862.9 | 52355 | 1.64041666667 | 11835 |
| 012154 | 0 | GeoXH 6000 | 08/19/2015 | 02:53:59pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594553.4 | 512864.3 | 52357 | 1.64041666667 | 12154 |
| 012034 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:00pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594555.5 | 512865.5 | 52359 | 1.64041666667 | 12034 |
| 011667 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:01pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594558.3 | 512867.4 | 52361 | 1.64041666667 | 11667 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:02pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594560.4 | 512868.1 | 52363 | 1.64041666667 | 12960 |
| 012757 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:03pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594562.9 | 512868.5 | 52365 | 1.64041666667 | 12757 |
| 011841 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:04pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594564.6 | 512868.1 | 52367 | 1.64041666667 | 11841 |
| 012083 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:05pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594566.2 | 512865.9 | 52369 | 1.64041666667 | 12083 |
| 011364 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:06pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594568.1 | 512863.7 | 52371 | 1.64041666667 | 11364 |
| 011852 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:07pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594570.3 | 512861.0 | 52373 | 1.64041666667 | 11852 |
| 012464 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:08pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594572.0 | 512858.4 | 52375 | 1.64041666667 | 12464 |
| 011811 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:09pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594573.4 | 512855.7 | 52377 | 1.64041666667 | 11811 |
| 012081 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:10pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594574.9 | 512853.3 | 52379 | 1.64041666667 | 12081 |
| 012735 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:11pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594577.2 | 512849.8 | 52381 | 1.64041666667 | 12735 |
| 012871 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:12pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594579.2 | 512846.9 | 52383 | 1.64041666667 | 12871 |
| 013075 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:13pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594581.4 | 512844.3 | 52385 | 1.64041666667 | 13075 |
| 012739 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:14pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594583.1 | 512842.1 | 52387 | 1.64041666667 | 12739 |
| 012423 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:15pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594584.9 | 512838.9 | 52389 | 1.64041666667 | 12423 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:16pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594585.8 | 512836.6 | 52391 | 1.64041666667 | 12133 |
| 011640 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:17pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594586.6 | 512834.1 | 52393 | 1.64041666667 | 11640 |
| 012060 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:18pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594586.7 | 512833.5 | 52395 | 1.64041666667 | 12060 |
| 011838 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:19pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594586.7 | 512833.4 | 52397 | 1.64041666667 | 11838 |
| 012389 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:20pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594586.9 | 512833.3 | 52399 | 1.64041666667 | 12389 |
| 012504 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:21pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594587.2 | 512833.3 | 52401 | 1.64041666667 | 12504 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012358 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:22pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594587.4 | 512833.4 | 52403 | 1.64041666667 | 12358 |
| 012854 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:23pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594587.3 | 512833.4 | 52405 | 1.64041666667 | 12854 |
| 012780 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:24pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594587.3 | 512833.4 | 52407 | 1.64041666667 | 12780 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:25pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594587.4 | 512832.7 | 52409 | 1.64041666667 | 12378 |
| 012648 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:26pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594587.8 | 512831.0 | 52411 | 1.64041666667 | 12648 |
| 013564 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:27pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594589.1 | 512828.1 | 52413 | 1.64041666667 | 13564 |
| 012692 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:28pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594590.2 | 512825.4 | 52415 | 1.64041666667 | 12692 |
| 012457 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:29pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594592.2 | 512823.0 | 52417 | 1.64041666667 | 12457 |
| 012324 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:30pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594594.3 | 512821.1 | 52419 | 1.64041666667 | 12324 |
| 013757 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:31pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594596.5 | 512818.1 | 52421 | 1.64041666667 | 13757 |
| 013221 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:32pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594597.8 | 512815.4 | 52423 | 1.64041666667 | 13221 |
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:33pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594598.9 | 512812.2 | 52425 | 1.64041666667 | 12019 |
| 012491 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:34pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594599.7 | 512809.5 | 52427 | 1.64041666667 | 12491 |
| 012088 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:35pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594600.3 | 512806.3 | 52429 | 1.64041666667 | 12088 |
| 012799 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:36pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594601.4 | 512803.6 | 52431 | 1.64041666667 | 12799 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:37pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594603.5 | 512800.7 | 52433 | 1.64041666667 | 12652 |
| 012262 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:38pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594605.2 | 512798.0 | 52435 | 1.64041666667 | 12262 |
| 012244 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:39pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594606.7 | 512795.1 | 52437 | 1.64041666667 | 12244 |
| 012572 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:40pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594608.1 | 512792.3 | 52439 | 1.64041666667 | 12572 |
| 012029 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:41pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594608.9 | 512789.2 | 52441 | 1.64041666667 | 12029 |
| 012316 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:42pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594610.0 | 512786.3 | 52443 | 1.64041666667 | 12316 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594611.3 | 512783.3 | 52445 | 1.64041666667 | 12133 |
| 012735 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:44pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594611.8 | 512780.9 | 52447 | 1.64041666667 | 12735 |
| 012218 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:45pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594612.1 | 512778.5 | 52449 | 1.64041666667 | 12218 |
| 012347 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:46pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594611.7 | 512776.3 | 52451 | 1.64041666667 | 12347 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:47pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594609.7 | 512774.6 | 52453 | 1.64041666667 | 12420 |
| 013166 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:48pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594607.2 | 512773.4 | 52455 | 1.64041666667 | 13166 |
| 013518 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:49pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594604.4 | 512771.9 | 52457 | 1.64041666667 | 13518 |
| 012494 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:50pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594601.5 | 512770.4 | 52459 | 1.64041666667 | 12494 |
| 012443 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:51pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594598.4 | 512769.7 | 52461 | 1.64041666667 | 12443 |
| 012196 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:52pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594595.4 | 512769.3 | 52463 | 1.64041666667 | 12196 |
| 013010 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:53pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594591.7 | 512768.2 | 52465 | 1.64041666667 | 13010 |
| 012381 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:54pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594587.9 | 512767.2 | 52467 | 1.64041666667 | 12381 |
| 012394 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:55pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594583.8 | 512766.5 | 52469 | 1.64041666667 | 12394 |
| 012446 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:56pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594580.1 | 512765.8 | 52471 | 1.64041666667 | 12446 |
| 012176 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:57pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594576.1 | 512764.2 | 52473 | 1.64041666667 | 12176 |
| 012811 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:58pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594572.7 | 512762.4 | 52475 | 1.64041666667 | 12811 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 02:54:59pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594568.7 | 512760.9 | 52477 | 1.64041666667 | 12539 |
| 013375 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:00pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594565.0 | 512759.8 | 52479 | 1.64041666667 | 13375 |
| 011963 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:01pm | Sensor | 1797-S0039-G-636-DTE | 6828.7 | 1594561.0 | 512758.2 | 52481 | 1.64041666667 | 11963 |
| 012152 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:02pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594557.5 | 512756.4 | 52483 | 1.64041666667 | 12152 |
| 011853 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:03pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594553.9 | 512754.4 | 52485 | 1.64041666667 | 11853 |
| 011520 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:04pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594550.6 | 512752.8 | 52487 | 1.64041666667 | 11520 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:05pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594546.6 | 512751.6 | 52489 | 1.64041666667 | 12247 |
| 012154 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:06pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594543.1 | 512750.5 | 52491 | 1.64041666667 | 12154 |
| 011539 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:07pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594539.5 | 512748.9 | 52493 | 1.64041666667 | 11539 |
| 011508 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:08pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594536.5 | 512747.4 | 52495 | 1.64041666667 | 11508 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:09pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594533.0 | 512746.1 | 52497 | 1.64041666667 | 12743 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012913 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:10pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594529.9 | 512744.8 | 52499 | 1.64041666667 | 12913 |
| 012296 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:11pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594526.6 | 512743.1 | 52501 | 1.64041666667 | 12296 |
| 012399 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:12pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594523.7 | 512741.6 | 52503 | 1.64041666667 | 12399 |
| 011992 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:13pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594520.0 | 512740.4 | 52505 | 1.64041666667 | 11992 |
| 012363 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:14pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594516.9 | 512739.7 | 52507 | 1.64041666667 | 12363 |
| 012549 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:15pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594514.1 | 512738.5 | 52509 | 1.64041666667 | 12549 |
| 011873 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:16pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594511.1 | 512737.3 | 52511 | 1.64041666667 | 11873 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:17pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594507.6 | 512736.9 | 52513 | 1.64041666667 | 11959 |
| 011924 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:18pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594504.5 | 512737.3 | 52515 | 1.64041666667 | 11924 |
| 012190 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:19pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594501.5 | 512739.0 | 52517 | 1.64041666667 | 12190 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:20pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594499.8 | 512742.0 | 52519 | 1.64041666667 | 12917 |
| 013093 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:21pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594500.5 | 512745.3 | 52521 | 1.64041666667 | 13093 |
| 012412 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:22pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594503.1 | 512747.5 | 52523 | 1.64041666667 | 12412 |
| 012217 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:23pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594507.0 | 512749.6 | 52525 | 1.64041666667 | 12217 |
| 012429 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:24pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594510.4 | 512751.5 | 52527 | 1.64041666667 | 12429 |
| 012534 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:25pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594514.4 | 512753.4 | 52529 | 1.64041666667 | 12534 |
| 012570 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:26pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594518.1 | 512754.6 | 52531 | 1.64041666667 | 12570 |
| 012260 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:27pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594522.1 | 512755.7 | 52533 | 1.64041666667 | 12260 |
| 012859 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:28pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594525.3 | 512756.9 | 52535 | 1.64041666667 | 12859 |
| 012333 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:29pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594529.2 | 512759.0 | 52537 | 1.64041666667 | 12333 |
| 012907 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:30pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594532.6 | 512760.6 | 52539 | 1.64041666667 | 12907 |
| 012720 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:31pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594536.2 | 512761.8 | 52541 | 1.64041666667 | 12720 |
| 013065 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:32pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594539.6 | 512762.9 | 52543 | 1.64041666667 | 13065 |
| 013769 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:33pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594543.2 | 512764.3 | 52545 | 1.64041666667 | 13769 |
| 013752 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:34pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594546.3 | 512765.6 | 52547 | 1.64041666667 | 13752 |
| 012866 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:35pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594550.6 | 512767.3 | 52549 | 1.64041666667 | 12866 |
| 013072 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:36pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594553.9 | 512768.3 | 52551 | 1.64041666667 | 13072 |
| 014770 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:37pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594557.8 | 512769.4 | 52553 | 1.64041666667 | 14770 |
| 013731 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:38pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594561.4 | 512770.4 | 52555 | 1.64041666667 | 13731 |
| 012688 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:39pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594565.7 | 512771.8 | 52557 | 1.64041666667 | 12688 |
| 012274 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:40pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594569.4 | 512773.1 | 52559 | 1.64041666667 | 12274 |
| 012139 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:41pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594573.1 | 512774.0 | 52561 | 1.64041666667 | 12139 |
| 012326 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:42pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594576.6 | 512774.8 | 52563 | 1.64041666667 | 12326 |
| 011943 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594580.7 | 512775.9 | 52565 | 1.64041666667 | 11943 |
| 012193 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:44pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594584.8 | 512777.2 | 52567 | 1.64041666667 | 12193 |
| 013091 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:45pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594588.5 | 512778.4 | 52569 | 1.64041666667 | 13091 |
| 012756 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:46pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594591.8 | 512779.3 | 52571 | 1.64041666667 | 12756 |
| 012665 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:47pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594596.1 | 512780.0 | 52573 | 1.64041666667 | 12665 |
| 012404 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:48pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594599.1 | 512780.6 | 52575 | 1.64041666667 | 12404 |
| 012535 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:49pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594602.4 | 512781.6 | 52577 | 1.64041666667 | 12535 |
| 012158 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:50pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594605.3 | 512782.3 | 52579 | 1.64041666667 | 12158 |
| 012014 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:51pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594607.8 | 512783.6 | 52581 | 1.64041666667 | 12014 |
| 011617 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:52pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594608.7 | 512785.5 | 52583 | 1.64041666667 | 11617 |
| 011912 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:53pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594608.4 | 512788.5 | 52585 | 1.64041666667 | 11912 |
| 012341 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:54pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594607.5 | 512790.9 | 52587 | 1.64041666667 | 12341 |
| 013106 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:55pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594605.9 | 512792.8 | 52589 | 1.64041666667 | 13106 |
| 012472 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:56pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594603.5 | 512793.9 | 52591 | 1.64041666667 | 12472 |
| 012258 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:57pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594599.7 | 512794.2 | 52593 | 1.64041666667 | 12258 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012603 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:58pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594596.8 | 512793.4 | 52595 | 1.64041666667 | 12603 |
| 011784 | 0 | GeoXH 6000 | 08/19/2015 | 02:55:59pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594593.5 | 512791.4 | 52597 | 1.64041666667 | 11784 |
| 012591 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:00pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594590.4 | 512789.3 | 52599 | 1.64041666667 | 12591 |
| 011800 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:01pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594587.3 | 512787.6 | 52601 | 1.64041666667 | 11800 |
| 011955 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:02pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594584.7 | 512786.1 | 52603 | 1.64041666667 | 11955 |
| 012042 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:03pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594581.5 | 512784.1 | 52605 | 1.64041666667 | 12042 |
| 011708 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:04pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594578.6 | 512782.6 | 52607 | 1.64041666667 | 11708 |
| 011828 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:05pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594575.2 | 512781.6 | 52609 | 1.64041666667 | 11828 |
| 012436 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:06pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594571.9 | 512780.3 | 52611 | 1.64041666667 | 12436 |
| 012410 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:07pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594569.0 | 512778.2 | 52613 | 1.64041666667 | 12410 |
| 012905 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:08pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594565.7 | 512776.0 | 52615 | 1.64041666667 | 12905 |
| 012382 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:09pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594562.3 | 512774.0 | 52617 | 1.64041666667 | 12382 |
| 012327 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:10pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594559.1 | 512772.2 | 52619 | 1.64041666667 | 12327 |
| 012559 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:11pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594555.6 | 512770.1 | 52621 | 1.64041666667 | 12559 |
| 012209 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:12pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594552.9 | 512768.5 | 52623 | 1.64041666667 | 12209 |
| 012932 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:13pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594549.5 | 512766.7 | 52625 | 1.64041666667 | 12932 |
| 013169 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:14pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594546.6 | 512765.3 | 52627 | 1.64041666667 | 13169 |
| 012440 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:15pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594543.6 | 512763.7 | 52629 | 1.64041666667 | 12440 |
| 012862 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:16pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594540.7 | 512762.1 | 52631 | 1.64041666667 | 12862 |
| 012695 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:17pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594537.1 | 512760.8 | 52633 | 1.64041666667 | 12695 |
| 012098 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:18pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594533.5 | 512759.5 | 52635 | 1.64041666667 | 12098 |
| 012925 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:19pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594530.2 | 512757.6 | 52637 | 1.64041666667 | 12925 |
| 013255 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:20pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594527.3 | 512756.0 | 52639 | 1.64041666667 | 13255 |
| 013433 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:21pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594523.6 | 512754.2 | 52641 | 1.64041666667 | 13433 |
| 012836 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:22pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594520.1 | 512752.8 | 52643 | 1.64041666667 | 12836 |
| 013183 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:23pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594516.8 | 512751.5 | 52645 | 1.64041666667 | 13183 |
| 013070 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:24pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594514.1 | 512750.1 | 52647 | 1.64041666667 | 13070 |
| 013359 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:25pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594510.5 | 512748.2 | 52649 | 1.64041666667 | 13359 |
| 012187 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:26pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594507.7 | 512747.0 | 52651 | 1.64041666667 | 12187 |
| 013080 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:27pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594504.4 | 512746.3 | 52653 | 1.64041666667 | 13080 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:28pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594501.7 | 512747.2 | 52655 | 1.64041666667 | 12840 |
| 013125 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:29pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594499.8 | 512750.6 | 52657 | 1.64041666667 | 13125 |
| 012850 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:30pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594499.2 | 512753.9 | 52659 | 1.64041666667 | 12850 |
| 012808 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:31pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594500.1 | 512757.3 | 52661 | 1.64041666667 | 12808 |
| 013879 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:32pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594502.1 | 512759.1 | 52663 | 1.64041666667 | 13879 |
| 013575 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:33pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594505.8 | 512760.3 | 52665 | 1.64041666667 | 13575 |
| 012645 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:34pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594508.9 | 512761.3 | 52667 | 1.64041666667 | 12645 |
| 012310 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:35pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594512.5 | 512763.1 | 52669 | 1.64041666667 | 12310 |
| 013037 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:36pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594516.0 | 512765.0 | 52671 | 1.64041666667 | 13037 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:37pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594519.7 | 512766.5 | 52673 | 1.64041666667 | 12163 |
| 012887 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:38pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594522.5 | 512767.7 | 52675 | 1.64041666667 | 12887 |
| 012288 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:39pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594526.2 | 512769.5 | 52677 | 1.64041666667 | 12288 |
| 012365 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:40pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594529.5 | 512770.5 | 52679 | 1.64041666667 | 12365 |
| 012820 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:41pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594533.3 | 512770.7 | 52681 | 1.64041666667 | 12820 |
| 013136 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:42pm | Sensor | 1797-S0039-G-636-DTE | 6828.7 | 1594536.9 | 512771.0 | 52683 | 1.64041666667 | 13136 |
| 012054 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594540.5 | 512772.1 | 52685 | 1.64041666667 | 12054 |
| 012190 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:44pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594544.1 | 512773.5 | 52687 | 1.64041666667 | 12190 |
| 013288 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:45pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594548.2 | 512774.7 | 52689 | 1.64041666667 | 13288 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013369 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:46pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594551.5 | 512775.4 | 52691 | 1.64041666667 | 13369 |
| 011727 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:47pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594555.3 | 512776.2 | 52693 | 1.64041666667 | 11727 |
| 012874 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:48pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594558.3 | 512777.4 | 52695 | 1.64041666667 | 12874 |
| 013099 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:49pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594561.9 | 512778.9 | 52697 | 1.64041666667 | 13099 |
| 012783 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:50pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594565.1 | 512780.1 | 52699 | 1.64041666667 | 12783 |
| 011488 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:51pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594568.8 | 512781.8 | 52701 | 1.64041666667 | 11488 |
| 011367 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:52pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594571.8 | 512783.2 | 52703 | 1.64041666667 | 11367 |
| 011104 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:53pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594575.4 | 512785.3 | 52705 | 1.64041666667 | 11104 |
| 011436 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:54pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594578.3 | 512787.3 | 52707 | 1.64041666667 | 11436 |
| 011600 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:55pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594581.8 | 512789.8 | 52709 | 1.64041666667 | 11600 |
| 012450 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:56pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594584.8 | 512792.1 | 52711 | 1.64041666667 | 12450 |
| 013513 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:57pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594588.0 | 512794.9 | 52713 | 1.64041666667 | 13513 |
| 013503 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:58pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594590.7 | 512797.2 | 52715 | 1.64041666667 | 13503 |
| 013086 | 0 | GeoXH 6000 | 08/19/2015 | 02:56:59pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594593.5 | 512798.9 | 52717 | 1.64041666667 | 13086 |
| 013428 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:00pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594595.4 | 512799.7 | 52719 | 1.64041666667 | 13428 |
| 013388 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:01pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594596.6 | 512801.2 | 52721 | 1.64041666667 | 13388 |
| 012946 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:02pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594597.2 | 512803.1 | 52723 | 1.64041666667 | 12946 |
| 012404 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:03pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594597.1 | 512805.7 | 52725 | 1.64041666667 | 12404 |
| 012370 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:04pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594596.6 | 512807.0 | 52727 | 1.64041666667 | 12370 |
| 011983 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:05pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594595.1 | 512807.4 | 52729 | 1.64041666667 | 11983 |
| 011705 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:06pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594592.2 | 512806.7 | 52731 | 1.64041666667 | 11705 |
| 012254 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:07pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594589.2 | 512804.9 | 52733 | 1.64041666667 | 12254 |
| 011640 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:08pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594586.3 | 512803.1 | 52735 | 1.64041666667 | 11640 |
| 012360 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:09pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594583.1 | 512801.3 | 52737 | 1.64041666667 | 12360 |
| 013560 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:10pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594580.1 | 512799.9 | 52739 | 1.64041666667 | 13560 |
| 013192 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:11pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594576.8 | 512798.0 | 52741 | 1.64041666667 | 13192 |
| 013586 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:12pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594574.2 | 512796.1 | 52743 | 1.64041666667 | 13586 |
| 013034 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:13pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594570.9 | 512794.1 | 52745 | 1.64041666667 | 13034 |
| 013062 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:14pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594567.4 | 512792.8 | 52747 | 1.64041666667 | 13062 |
| 012177 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:15pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594563.6 | 512791.7 | 52749 | 1.64041666667 | 12177 |
| 011747 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:16pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594560.3 | 512789.6 | 52751 | 1.64041666667 | 11747 |
| 012847 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:17pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594557.4 | 512787.2 | 52753 | 1.64041666667 | 12847 |
| 013279 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:18pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594555.0 | 512785.3 | 52755 | 1.64041666667 | 13279 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:19pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594551.7 | 512783.3 | 52757 | 1.64041666667 | 13424 |
| 012651 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:20pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594548.2 | 512781.6 | 52759 | 1.64041666667 | 12651 |
| 012629 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:21pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594544.9 | 512780.1 | 52761 | 1.64041666667 | 12629 |
| 012751 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:22pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594541.9 | 512778.3 | 52763 | 1.64041666667 | 12751 |
| 013022 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:23pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594538.9 | 512775.5 | 52765 | 1.64041666667 | 13022 |
| 013497 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:24pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594536.4 | 512773.8 | 52767 | 1.64041666667 | 13497 |
| 012775 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:25pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594532.4 | 512772.7 | 52769 | 1.64041666667 | 12775 |
| 012481 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:26pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594528.0 | 512772.0 | 52771 | 1.64041666667 | 12481 |
| 012675 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:27pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594523.9 | 512771.0 | 52773 | 1.64041666667 | 12675 |
| 013370 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:28pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594520.7 | 512769.9 | 52775 | 1.64041666667 | 13370 |
| 012575 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:29pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594516.5 | 512768.8 | 52777 | 1.64041666667 | 12575 |
| 011566 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:30pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594512.7 | 512767.7 | 52779 | 1.64041666667 | 11566 |
| 012063 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:31pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594509.2 | 512766.0 | 52781 | 1.64041666667 | 12063 |
| 011833 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:32pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594506.3 | 512764.1 | 52783 | 1.64041666667 | 11833 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:33pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594503.2 | 512762.7 | 52785 | 1.64041666667 | 12401 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013140 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:34pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594500.4 | 512762.6 | 52787 | 1.64041666667 | 13140 |
| 012859 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:35pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594497.6 | 512765.1 | 52789 | 1.64041666667 | 12859 |
| 012243 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:36pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594496.3 | 512767.9 | 52791 | 1.64041666667 | 12243 |
| 012474 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:37pm | Sensor | 1797-S0039-G-636-DTE | 6827.2 | 1594495.9 | 512771.4 | 52793 | 1.64041666667 | 12474 |
| 012176 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:38pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594496.9 | 512774.1 | 52795 | 1.64041666667 | 12176 |
| 013112 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:39pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594499.4 | 512776.1 | 52797 | 1.64041666667 | 13112 |
| 013113 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:40pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594501.8 | 512777.1 | 52799 | 1.64041666667 | 13113 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:41pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594504.7 | 512778.6 | 52801 | 1.64041666667 | 12536 |
| 012946 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:42pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594507.5 | 512779.8 | 52803 | 1.64041666667 | 12946 |
| 013095 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594511.0 | 512779.8 | 52805 | 1.64041666667 | 13095 |
| 013508 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:44pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594513.8 | 512779.4 | 52807 | 1.64041666667 | 13508 |
| 013546 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:45pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594517.7 | 512779.7 | 52809 | 1.64041666667 | 13546 |
| 012899 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:46pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594521.0 | 512780.5 | 52811 | 1.64041666667 | 12899 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:47pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594524.8 | 512781.3 | 52813 | 1.64041666667 | 12056 |
| 012219 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:48pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594527.6 | 512782.2 | 52815 | 1.64041666667 | 12219 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:49pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594530.6 | 512783.7 | 52817 | 1.64041666667 | 12678 |
| 012538 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:50pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594532.4 | 512785.1 | 52819 | 1.64041666667 | 12538 |
| 012877 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:51pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594532.9 | 512785.6 | 52821 | 1.64041666667 | 12877 |
| 011818 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:52pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594532.9 | 512785.6 | 52823 | 1.64041666667 | 11818 |
| 012550 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:53pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594532.9 | 512785.7 | 52825 | 1.64041666667 | 12550 |
| 012714 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:54pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594532.8 | 512785.5 | 52827 | 1.64041666667 | 12714 |
| 013339 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:55pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594533.2 | 512785.3 | 52829 | 1.64041666667 | 13339 |
| 012581 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:56pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594535.0 | 512785.3 | 52831 | 1.64041666667 | 12581 |
| 013031 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:57pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594538.4 | 512786.2 | 52833 | 1.64041666667 | 13031 |
| 013300 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:58pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594542.1 | 512787.0 | 52835 | 1.64041666667 | 13300 |
| 013008 | 0 | GeoXH 6000 | 08/19/2015 | 02:57:59pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594545.5 | 512787.6 | 52837 | 1.64041666667 | 13008 |
| 012845 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:00pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594548.1 | 512788.5 | 52839 | 1.64041666667 | 12845 |
| 012738 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:01pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594551.6 | 512790.7 | 52841 | 1.64041666667 | 12738 |
| 013262 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:02pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594554.1 | 512792.1 | 52843 | 1.64041666667 | 13262 |
| 013077 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:03pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594556.8 | 512793.3 | 52845 | 1.64041666667 | 13077 |
| 012643 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:04pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594559.5 | 512794.3 | 52847 | 1.64041666667 | 12643 |
| 012564 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:05pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594563.4 | 512795.5 | 52849 | 1.64041666667 | 12564 |
| 012955 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:06pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594566.7 | 512796.9 | 52851 | 1.64041666667 | 12955 |
| 012882 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:07pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594570.5 | 512799.1 | 52853 | 1.64041666667 | 12882 |
| 012721 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:08pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594573.9 | 512801.0 | 52855 | 1.64041666667 | 12721 |
| 012480 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:09pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594577.5 | 512803.0 | 52857 | 1.64041666667 | 12480 |
| 012915 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:10pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594581.2 | 512805.4 | 52859 | 1.64041666667 | 12915 |
| 013264 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:11pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594584.3 | 512808.0 | 52861 | 1.64041666667 | 13264 |
| 013026 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:12pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594587.1 | 512809.9 | 52863 | 1.64041666667 | 13026 |
| 012847 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:13pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594590.7 | 512812.0 | 52865 | 1.64041666667 | 12847 |
| 012589 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:14pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594594.1 | 512814.4 | 52867 | 1.64041666667 | 12589 |
| 012953 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:15pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594596.7 | 512817.2 | 52869 | 1.64041666667 | 12953 |
| 013069 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:16pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594597.6 | 512820.1 | 52871 | 1.64041666667 | 13069 |
| 012721 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:17pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594597.2 | 512823.1 | 52873 | 1.64041666667 | 12721 |
| 012195 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:18pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594596.9 | 512825.6 | 52875 | 1.64041666667 | 12195 |
| 012440 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:19pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594596.1 | 512826.9 | 52877 | 1.64041666667 | 12440 |
| 012337 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:20pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594594.3 | 512826.7 | 52879 | 1.64041666667 | 12337 |
| 012527 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:21pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594591.1 | 512825.8 | 52881 | 1.64041666667 | 12527 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012446 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:22pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594588.6 | 512825.1 | 52883 | 1.64041666667 | 12446 |
| 012333 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:23pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594586.3 | 512824.0 | 52885 | 1.64041666667 | 12333 |
| 012480 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:24pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594584.3 | 512822.7 | 52887 | 1.64041666667 | 12480 |
| 011835 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:25pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594580.9 | 512822.2 | 52889 | 1.64041666667 | 11835 |
| 011119 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:26pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594578.0 | 512821.3 | 52891 | 1.64041666667 | 11119 |
| 011782 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:27pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594574.9 | 512819.7 | 52893 | 1.64041666667 | 11782 |
| 011675 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:28pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594572.6 | 512818.4 | 52895 | 1.64041666667 | 11675 |
| 012162 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:29pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594570.5 | 512817.1 | 52897 | 1.64041666667 | 12162 |
| 012503 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:30pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594568.6 | 512815.5 | 52899 | 1.64041666667 | 12503 |
| 012223 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:31pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594566.8 | 512813.1 | 52901 | 1.64041666667 | 12223 |
| 012170 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:32pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594565.0 | 512811.1 | 52903 | 1.64041666667 | 12170 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:33pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594562.4 | 512808.9 | 52905 | 1.64041666667 | 12163 |
| 012212 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:34pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594560.1 | 512807.4 | 52907 | 1.64041666667 | 12212 |
| 013011 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:35pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594556.9 | 512806.6 | 52909 | 1.64041666667 | 13011 |
| 012089 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:36pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594553.9 | 512806.2 | 52911 | 1.64041666667 | 12089 |
| 012192 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:37pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594551.7 | 512806.0 | 52913 | 1.64041666667 | 12192 |
| 011778 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:38pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594550.8 | 512806.1 | 52915 | 1.64041666667 | 11778 |
| 011650 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:39pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594550.7 | 512805.9 | 52917 | 1.64041666667 | 11650 |
| 011893 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:40pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594550.7 | 512805.9 | 52919 | 1.64041666667 | 11893 |
| 012945 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:41pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594550.5 | 512805.9 | 52921 | 1.64041666667 | 12945 |
| 011639 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:42pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594549.4 | 512805.7 | 52923 | 1.64041666667 | 11639 |
| 012277 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594546.7 | 512805.2 | 52925 | 1.64041666667 | 12277 |
| 012155 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:44pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594544.7 | 512805.1 | 52927 | 1.64041666667 | 12155 |
| 012335 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:45pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594543.4 | 512804.8 | 52929 | 1.64041666667 | 12335 |
| 011896 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:46pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594543.0 | 512804.5 | 52931 | 1.64041666667 | 11896 |
| 012219 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:47pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594542.4 | 512804.7 | 52933 | 1.64041666667 | 12219 |
| 012408 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:48pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594540.9 | 512805.4 | 52935 | 1.64041666667 | 12408 |
| 012259 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:49pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594539.4 | 512806.2 | 52937 | 1.64041666667 | 12259 |
| 012731 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:50pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594539.0 | 512806.2 | 52939 | 1.64041666667 | 12731 |
| 012523 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:51pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594539.7 | 512805.1 | 52941 | 1.64041666667 | 12523 |
| 012482 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:52pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594541.5 | 512803.1 | 52943 | 1.64041666667 | 12482 |
| 012631 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:53pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594542.9 | 512801.7 | 52945 | 1.64041666667 | 12631 |
| 012295 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:54pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594543.2 | 512800.9 | 52947 | 1.64041666667 | 12295 |
| 012421 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:55pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594543.2 | 512801.0 | 52949 | 1.64041666667 | 12421 |
| 012206 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:56pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594543.4 | 512800.9 | 52951 | 1.64041666667 | 12206 |
| 012228 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:57pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594543.5 | 512800.7 | 52953 | 1.64041666667 | 12228 |
| 012398 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:58pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594543.4 | 512800.3 | 52955 | 1.64041666667 | 12398 |
| 011826 | 0 | GeoXH 6000 | 08/19/2015 | 02:58:59pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594543.5 | 512798.9 | 52957 | 1.64041666667 | 11826 |
| 011925 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:00pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594544.7 | 512797.6 | 52959 | 1.64041666667 | 11925 |
| 012190 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:01pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594544.9 | 512797.5 | 52961 | 1.64041666667 | 12190 |
| 012129 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:02pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594544.8 | 512797.4 | 52963 | 1.64041666667 | 12129 |
| 012665 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:03pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594544.2 | 512798.6 | 52965 | 1.64041666667 | 12665 |
| 012741 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:04pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594542.9 | 512800.7 | 52967 | 1.64041666667 | 12741 |
| 013114 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:05pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594542.0 | 512802.2 | 52969 | 1.64041666667 | 13114 |
| 012979 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:06pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594542.2 | 512802.2 | 52971 | 1.64041666667 | 12979 |
| 012663 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:07pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594542.1 | 512802.1 | 52973 | 1.64041666667 | 12663 |
| 012508 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:08pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594542.1 | 512802.0 | 52975 | 1.64041666667 | 12508 |
| 012893 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:09pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594542.1 | 512802.1 | 52977 | 1.64041666667 | 12893 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012502 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:10pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594541.8 | 512801.9 | 52979 | 1.64041666667 | 12502 |
| 012027 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:11pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594541.0 | 512801.0 | 52981 | 1.64041666667 | 12027 |
| 012143 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:12pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594540.1 | 512800.4 | 52983 | 1.64041666667 | 12143 |
| 012830 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:13pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594539.7 | 512800.4 | 52985 | 1.64041666667 | 12830 |
| 012279 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:14pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594539.3 | 512800.3 | 52987 | 1.64041666667 | 12279 |
| 012487 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:15pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594538.9 | 512799.9 | 52989 | 1.64041666667 | 12487 |
| 012844 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:16pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594538.8 | 512799.9 | 52991 | 1.64041666667 | 12844 |
| 013127 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:17pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594538.6 | 512799.7 | 52993 | 1.64041666667 | 13127 |
| 013429 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:18pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594538.4 | 512799.5 | 52995 | 1.64041666667 | 13429 |
| 013238 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:19pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594538.1 | 512799.4 | 52997 | 1.64041666667 | 13238 |
| 013184 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:20pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594538.1 | 512799.5 | 52999 | 1.64041666667 | 13184 |
| 013123 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:21pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594538.0 | 512799.5 | 53001 | 1.64041666667 | 13123 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:22pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594538.1 | 512799.5 | 53003 | 1.64041666667 | 12917 |
| 012336 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:23pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594538.0 | 512799.4 | 53005 | 1.64041666667 | 12336 |
| 012879 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:24pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594538.0 | 512799.3 | 53007 | 1.64041666667 | 12879 |
| 013004 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:25pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.9 | 512799.3 | 53009 | 1.64041666667 | 13004 |
| 012910 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:26pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.9 | 512799.4 | 53011 | 1.64041666667 | 12910 |
| 013269 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:27pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.8 | 512799.4 | 53013 | 1.64041666667 | 13269 |
| 013621 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:28pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.8 | 512799.4 | 53015 | 1.64041666667 | 13621 |
| 013137 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:29pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.8 | 512799.3 | 53017 | 1.64041666667 | 13137 |
| 013457 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:30pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594537.8 | 512799.3 | 53019 | 1.64041666667 | 13457 |
| 012947 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:31pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594537.7 | 512799.3 | 53021 | 1.64041666667 | 12947 |
| 012697 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:32pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.7 | 512799.4 | 53023 | 1.64041666667 | 12697 |
| 013937 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:33pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.7 | 512799.4 | 53025 | 1.64041666667 | 13937 |
| 013592 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:34pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.8 | 512799.4 | 53027 | 1.64041666667 | 13592 |
| 013405 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:35pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.9 | 512799.3 | 53029 | 1.64041666667 | 13405 |
| 013525 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:36pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.9 | 512799.2 | 53031 | 1.64041666667 | 13525 |
| 013353 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:37pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.9 | 512799.2 | 53033 | 1.64041666667 | 13353 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:38pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.9 | 512799.2 | 53035 | 1.64041666667 | 12918 |
| 013004 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:39pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594537.9 | 512799.3 | 53037 | 1.64041666667 | 13004 |
| 012685 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:40pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594537.9 | 512799.4 | 53039 | 1.64041666667 | 12685 |
| 012692 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:41pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594537.9 | 512799.4 | 53041 | 1.64041666667 | 12692 |
| 012629 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:42pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594537.8 | 512799.5 | 53043 | 1.64041666667 | 12629 |
| 012774 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594537.8 | 512799.5 | 53045 | 1.64041666667 | 12774 |
| 012720 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:44pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594537.8 | 512799.5 | 53047 | 1.64041666667 | 12720 |
| 012585 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:45pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.7 | 512799.4 | 53049 | 1.64041666667 | 12585 |
| 012059 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:46pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594537.6 | 512799.3 | 53051 | 1.64041666667 | 12059 |
| 012153 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:47pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594537.6 | 512799.3 | 53053 | 1.64041666667 | 12153 |
| 012776 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:48pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594537.6 | 512799.4 | 53055 | 1.64041666667 | 12776 |
| 012271 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:49pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594537.7 | 512799.4 | 53057 | 1.64041666667 | 12271 |
| 013412 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:50pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594537.7 | 512799.5 | 53059 | 1.64041666667 | 13412 |
| 013664 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:51pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594537.7 | 512799.7 | 53061 | 1.64041666667 | 13664 |
| 013056 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:52pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594537.6 | 512799.8 | 53063 | 1.64041666667 | 13056 |
| 013831 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:53pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594537.4 | 512799.7 | 53065 | 1.64041666667 | 13831 |
| 013697 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:54pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594538.3 | 512800.1 | 53067 | 1.64041666667 | 13697 |
| 012835 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:55pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594539.7 | 512800.9 | 53069 | 1.64041666667 | 12835 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:56pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594539.0 | 512801.1 | 53071 | 1.64041666667 | 12454 |
| 013320 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:57pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594537.2 | 512800.5 | 53073 | 1.64041666667 | 13320 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013582 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:58pm | Sensor | 1797-S0039-G-636-DTE | 6828.7 | 1594535.3 | 512799.6 | 53075 | 1.64041666667 | 13582 |
| 012830 | 0 | GeoXH 6000 | 08/19/2015 | 02:59:59pm | Sensor | 1797-S0039-G-636-DTE | 6828.8 | 1594532.6 | 512797.4 | 53077 | 1.64041666667 | 12830 |
| 012632 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:00pm | Sensor | 1797-S0039-G-636-DTE | 6828.8 | 1594530.1 | 512795.5 | 53079 | 1.64041666667 | 12632 |
| 012243 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:01pm | Sensor | 1797-S0039-G-636-DTE | 6828.8 | 1594526.3 | 512793.6 | 53081 | 1.64041666667 | 12243 |
| 011499 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:02pm | Sensor | 1797-S0039-G-636-DTE | 6828.7 | 1594523.1 | 512792.5 | 53083 | 1.64041666667 | 11499 |
| 011770 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:03pm | Sensor | 1797-S0039-G-636-DTE | 6828.7 | 1594519.1 | 512791.8 | 53085 | 1.64041666667 | 11770 |
| 013018 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:04pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594515.7 | 512791.2 | 53087 | 1.64041666667 | 13018 |
| 012460 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:05pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594512.1 | 512791.6 | 53089 | 1.64041666667 | 12460 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:06pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594508.3 | 512792.1 | 53091 | 1.64041666667 | 12536 |
| 012069 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:07pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594504.8 | 512791.5 | 53093 | 1.64041666667 | 12069 |
| 013216 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:08pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594502.0 | 512790.3 | 53095 | 1.64041666667 | 13216 |
| 012879 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:09pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594499.3 | 512789.2 | 53097 | 1.64041666667 | 12879 |
| 012772 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:10pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594496.9 | 512788.0 | 53099 | 1.64041666667 | 12772 |
| 012517 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:11pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594495.5 | 512787.4 | 53101 | 1.64041666667 | 12517 |
| 012575 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:12pm | Sensor | 1797-S0039-G-636-DTE | 6826.9 | 1594493.0 | 512787.8 | 53103 | 1.64041666667 | 12575 |
| 011896 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:13pm | Sensor | 1797-S0039-G-636-DTE | 6826.4 | 1594489.1 | 512787.7 | 53105 | 1.64041666667 | 11896 |
| 011604 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:14pm | Sensor | 1797-S0039-G-636-DTE | 6826.3 | 1594486.2 | 512788.1 | 53107 | 1.64041666667 | 11604 |
| 012137 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:15pm | Sensor | 1797-S0039-G-636-DTE | 6826.2 | 1594484.3 | 512791.0 | 53109 | 1.64041666667 | 12137 |
| 012317 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:16pm | Sensor | 1797-S0039-G-636-DTE | 6826.2 | 1594483.8 | 512793.5 | 53111 | 1.64041666667 | 12317 |
| 012133 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:17pm | Sensor | 1797-S0039-G-636-DTE | 6826.1 | 1594484.8 | 512795.8 | 53113 | 1.64041666667 | 12133 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:18pm | Sensor | 1797-S0039-G-636-DTE | 6826.2 | 1594486.8 | 512797.1 | 53115 | 1.64041666667 | 12960 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:19pm | Sensor | 1797-S0039-G-636-DTE | 6826.3 | 1594490.1 | 512798.0 | 53117 | 1.64041666667 | 12180 |
| 011748 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:20pm | Sensor | 1797-S0039-G-636-DTE | 6826.8 | 1594493.1 | 512798.8 | 53119 | 1.64041666667 | 11748 |
| 012788 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:21pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594496.0 | 512800.0 | 53121 | 1.64041666667 | 12788 |
| 012346 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:22pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594497.8 | 512801.0 | 53123 | 1.64041666667 | 12346 |
| 011819 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:23pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594500.8 | 512802.8 | 53125 | 1.64041666667 | 11819 |
| 011493 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:24pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594503.7 | 512804.0 | 53127 | 1.64041666667 | 11493 |
| 012727 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:25pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594507.1 | 512804.5 | 53129 | 1.64041666667 | 12727 |
| 013031 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:26pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594510.5 | 512804.4 | 53131 | 1.64041666667 | 13031 |
| 012865 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:27pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594514.0 | 512804.9 | 53133 | 1.64041666667 | 12865 |
| 011774 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:28pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594517.6 | 512806.2 | 53135 | 1.64041666667 | 11774 |
| 012300 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:29pm | Sensor | 1797-S0039-G-636-DTE | 6828.8 | 1594521.2 | 512806.9 | 53137 | 1.64041666667 | 12300 |
| 011321 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:30pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594523.9 | 512807.2 | 53139 | 1.64041666667 | 11321 |
| 011730 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:31pm | Sensor | 1797-S0039-G-636-DTE | 6828.6 | 1594527.3 | 512808.4 | 53141 | 1.64041666667 | 11730 |
| 012366 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:32pm | Sensor | 1797-S0039-G-636-DTE | 6828.5 | 1594529.5 | 512810.1 | 53143 | 1.64041666667 | 12366 |
| 012836 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:33pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594532.9 | 512811.8 | 53145 | 1.64041666667 | 12836 |
| 012897 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:34pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594535.5 | 512813.3 | 53147 | 1.64041666667 | 12897 |
| 012775 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:35pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594538.4 | 512816.4 | 53149 | 1.64041666667 | 12775 |
| 012053 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:36pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594541.1 | 512819.0 | 53151 | 1.64041666667 | 12053 |
| 012120 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:37pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594544.7 | 512820.8 | 53153 | 1.64041666667 | 12120 |
| 012502 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:38pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594548.3 | 512822.5 | 53155 | 1.64041666667 | 12502 |
| 012635 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:39pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594551.5 | 512824.9 | 53157 | 1.64041666667 | 12635 |
| 012409 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:40pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594553.8 | 512827.3 | 53159 | 1.64041666667 | 12409 |
| 012215 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:41pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594556.3 | 512829.4 | 53161 | 1.64041666667 | 12215 |
| 012676 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:42pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594558.2 | 512830.1 | 53163 | 1.64041666667 | 12676 |
| 012335 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594560.6 | 512831.7 | 53165 | 1.64041666667 | 12335 |
| 012466 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:44pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594562.9 | 512834.0 | 53167 | 1.64041666667 | 12466 |
| 012659 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:45pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594565.3 | 512836.0 | 53169 | 1.64041666667 | 12659 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012468 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:46pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594567.9 | 512837.8 | 53171 | 1.64041666667 | 12468 |
| 012728 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:47pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594570.4 | 512839.6 | 53173 | 1.64041666667 | 12728 |
| 012447 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:48pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594572.5 | 512841.1 | 53175 | 1.64041666667 | 12447 |
| 012446 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:49pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594574.7 | 512843.7 | 53177 | 1.64041666667 | 12446 |
| 012048 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:50pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594576.7 | 512846.2 | 53179 | 1.64041666667 | 12048 |
| 012387 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:51pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594578.7 | 512848.7 | 53181 | 1.64041666667 | 12387 |
| 011617 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:52pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594579.8 | 512851.1 | 53183 | 1.64041666667 | 11617 |
| 012122 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:53pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594580.5 | 512853.7 | 53185 | 1.64041666667 | 12122 |
| 012001 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:54pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594580.4 | 512855.6 | 53187 | 1.64041666667 | 12001 |
| 011738 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:55pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594578.5 | 512857.3 | 53189 | 1.64041666667 | 11738 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:56pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594576.8 | 512858.1 | 53191 | 1.64041666667 | 12475 |
| 012664 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:57pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594574.8 | 512857.9 | 53193 | 1.64041666667 | 12664 |
| 012524 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:58pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594572.4 | 512856.2 | 53195 | 1.64041666667 | 12524 |
| 012294 | 0 | GeoXH 6000 | 08/19/2015 | 03:00:59pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594569.4 | 512853.8 | 53197 | 1.64041666667 | 12294 |
| 012210 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:00pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594567.1 | 512851.4 | 53199 | 1.64041666667 | 12210 |
| 012583 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:01pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594564.3 | 512848.4 | 53201 | 1.64041666667 | 12583 |
| 012253 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:02pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594561.1 | 512845.9 | 53203 | 1.64041666667 | 12253 |
| 012510 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:03pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594558.1 | 512843.3 | 53205 | 1.64041666667 | 12510 |
| 012352 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:04pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594555.8 | 512840.8 | 53207 | 1.64041666667 | 12352 |
| 012356 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:05pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594552.9 | 512837.7 | 53209 | 1.64041666667 | 12356 |
| 011653 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:06pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594550.1 | 512835.3 | 53211 | 1.64041666667 | 11653 |
| 011880 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:07pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594547.1 | 512833.7 | 53213 | 1.64041666667 | 11880 |
| 011700 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:08pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594543.8 | 512831.9 | 53215 | 1.64041666667 | 11700 |
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:09pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594540.6 | 512830.2 | 53217 | 1.64041666667 | 12183 |
| 011810 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:10pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594537.5 | 512828.7 | 53219 | 1.64041666667 | 11810 |
| 012411 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:11pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594534.2 | 512826.4 | 53221 | 1.64041666667 | 12411 |
| 012321 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:12pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594531.1 | 512824.1 | 53223 | 1.64041666667 | 12321 |
| 012075 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:13pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594527.5 | 512821.8 | 53225 | 1.64041666667 | 12075 |
| 013092 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:14pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594524.9 | 512819.8 | 53227 | 1.64041666667 | 13092 |
| 012824 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:15pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594521.8 | 512816.7 | 53229 | 1.64041666667 | 12824 |
| 012449 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:16pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594519.3 | 512814.7 | 53231 | 1.64041666667 | 12449 |
| 013092 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:17pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594515.6 | 512813.0 | 53233 | 1.64041666667 | 13092 |
| 012232 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:18pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594512.7 | 512811.5 | 53235 | 1.64041666667 | 12232 |
| 011620 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:19pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594509.8 | 512809.4 | 53237 | 1.64041666667 | 11620 |
| 011929 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:20pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594507.6 | 512807.5 | 53239 | 1.64041666667 | 11929 |
| 011862 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:21pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594504.9 | 512806.5 | 53241 | 1.64041666667 | 11862 |
| 010602 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:22pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594501.5 | 512806.3 | 53243 | 1.64041666667 | 10602 |
| 011514 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:23pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594497.3 | 512805.6 | 53245 | 1.64041666667 | 11514 |
| 011906 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:24pm | Sensor | 1797-S0039-G-636-DTE | 6826.5 | 1594493.5 | 512804.4 | 53247 | 1.64041666667 | 11906 |
| 012300 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:25pm | Sensor | 1797-S0039-G-636-DTE | 6826.1 | 1594488.9 | 512803.1 | 53249 | 1.64041666667 | 12300 |
| 011805 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:26pm | Sensor | 1797-S0039-G-636-DTE | 6826.1 | 1594484.5 | 512802.4 | 53251 | 1.64041666667 | 11805 |
| 012605 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:27pm | Sensor | 1797-S0039-G-636-DTE | 6826.0 | 1594481.0 | 512803.7 | 53253 | 1.64041666667 | 12605 |
| 012408 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:28pm | Sensor | 1797-S0039-G-636-DTE | 6826.0 | 1594479.2 | 512806.5 | 53255 | 1.64041666667 | 12408 |
| 012252 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:29pm | Sensor | 1797-S0039-G-636-DTE | 6826.1 | 1594479.4 | 512809.8 | 53257 | 1.64041666667 | 12252 |
| 012489 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:30pm | Sensor | 1797-S0039-G-636-DTE | 6826.5 | 1594482.1 | 512813.3 | 53259 | 1.64041666667 | 12489 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:31pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594486.0 | 512815.3 | 53261 | 1.64041666667 | 12056 |
| 011904 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:32pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594489.0 | 512816.1 | 53263 | 1.64041666667 | 11904 |
| 012231 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:33pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594492.6 | 512816.9 | 53265 | 1.64041666667 | 12231 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012617 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:34pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594496.4 | 512817.3 | 53267 | 1.64041666667 | 12617 |
| 012422 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:35pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594499.8 | 512818.1 | 53269 | 1.64041666667 | 12422 |
| 012920 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:36pm | Sensor | 1797-S0039-G-636-DTE | 6828.4 | 1594503.2 | 512819.9 | 53271 | 1.64041666667 | 12920 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:37pm | Sensor | 1797-S0039-G-636-DTE | 6828.3 | 1594506.5 | 512821.6 | 53273 | 1.64041666667 | 12840 |
| 012105 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:38pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594509.7 | 512823.1 | 53275 | 1.64041666667 | 12105 |
| 012389 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:39pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594513.8 | 512824.9 | 53277 | 1.64041666667 | 12389 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:40pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594517.3 | 512826.1 | 53279 | 1.64041666667 | 12803 |
| 012647 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:41pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594520.8 | 512827.6 | 53281 | 1.64041666667 | 12647 |
| 012409 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:42pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594524.5 | 512829.2 | 53283 | 1.64041666667 | 12409 |
| 012860 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594528.3 | 512830.2 | 53285 | 1.64041666667 | 12860 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:44pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594532.1 | 512831.0 | 53287 | 1.64041666667 | 12431 |
| 013142 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:45pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594536.2 | 512832.4 | 53289 | 1.64041666667 | 13142 |
| 013167 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:46pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594539.7 | 512833.9 | 53291 | 1.64041666667 | 13167 |
| 013091 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:47pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594543.9 | 512836.3 | 53293 | 1.64041666667 | 13091 |
| 013371 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:48pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594547.0 | 512838.3 | 53295 | 1.64041666667 | 13371 |
| 013484 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:49pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594550.0 | 512840.2 | 53297 | 1.64041666667 | 13484 |
| 013097 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:50pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594552.9 | 512842.8 | 53299 | 1.64041666667 | 13097 |
| 013014 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:51pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594555.7 | 512846.3 | 53301 | 1.64041666667 | 13014 |
| 012473 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:52pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594558.6 | 512849.4 | 53303 | 1.64041666667 | 12473 |
| 012326 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:53pm | Sensor | 1797-S0039-G-636-DTE | 6827.1 | 1594562.2 | 512851.8 | 53305 | 1.64041666667 | 12326 |
| 012153 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:54pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594565.6 | 512853.9 | 53307 | 1.64041666667 | 12153 |
| 011973 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:55pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594568.3 | 512856.0 | 53309 | 1.64041666667 | 11973 |
| 011880 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:56pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594569.8 | 512858.2 | 53311 | 1.64041666667 | 11880 |
| 011362 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:57pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594570.7 | 512860.5 | 53313 | 1.64041666667 | 11362 |
| 011439 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:58pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594571.0 | 512862.0 | 53315 | 1.64041666667 | 11439 |
| 011377 | 0 | GeoXH 6000 | 08/19/2015 | 03:01:59pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594570.2 | 512863.3 | 53317 | 1.64041666667 | 11377 |
| 011117 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:00pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594568.5 | 512864.0 | 53319 | 1.64041666667 | 11117 |
| 011721 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:01pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594565.2 | 512862.8 | 53321 | 1.64041666667 | 11721 |
| 011025 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:02pm | Sensor | 1797-S0039-G-636-DTE | 6827.6 | 1594562.2 | 512861.3 | 53323 | 1.64041666667 | 11025 |
| 010604 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:03pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594559.2 | 512859.8 | 53325 | 1.64041666667 | 10604 |
| 011282 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:04pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594556.5 | 512858.1 | 53327 | 1.64041666667 | 11282 |
| 012458 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:05pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594553.7 | 512856.3 | 53329 | 1.64041666667 | 12458 |
| 011800 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:06pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594550.3 | 512854.0 | 53331 | 1.64041666667 | 11800 |
| 011737 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:07pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594546.8 | 512852.1 | 53333 | 1.64041666667 | 11737 |
| 011755 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:08pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594543.4 | 512850.8 | 53335 | 1.64041666667 | 11755 |
| 012417 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:09pm | Sensor | 1797-S0039-G-636-DTE | 6827.3 | 1594539.7 | 512849.7 | 53337 | 1.64041666667 | 12417 |
| 013059 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:10pm | Sensor | 1797-S0039-G-636-DTE | 6827.4 | 1594536.3 | 512848.5 | 53339 | 1.64041666667 | 13059 |
| 012716 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:11pm | Sensor | 1797-S0039-G-636-DTE | 6827.5 | 1594532.9 | 512846.8 | 53341 | 1.64041666667 | 12716 |
| 013227 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:12pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594530.0 | 512845.7 | 53343 | 1.64041666667 | 13227 |
| 012758 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:13pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594526.1 | 512844.6 | 53345 | 1.64041666667 | 12758 |
| 013206 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:14pm | Sensor | 1797-S0039-G-636-DTE | 6827.8 | 1594523.2 | 512843.5 | 53347 | 1.64041666667 | 13206 |
| 012933 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:15pm | Sensor | 1797-S0039-G-636-DTE | 6827.7 | 1594520.0 | 512842.0 | 53349 | 1.64041666667 | 12933 |
| 012457 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:16pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594517.1 | 512840.9 | 53351 | 1.64041666667 | 12457 |
| 012610 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:17pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594514.5 | 512840.1 | 53353 | 1.64041666667 | 12610 |
| 012320 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:18pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594512.6 | 512839.1 | 53355 | 1.64041666667 | 12320 |
| 012382 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:19pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594511.9 | 512838.8 | 53357 | 1.64041666667 | 12382 |
| 012282 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:20pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594512.0 | 512838.5 | 53359 | 1.64041666667 | 12282 |
| 011694 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:21pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594511.6 | 512838.0 | 53361 | 1.64041666667 | 11694 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011580 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:22pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594509.8 | 512837.4 | 53363 | 1.64041666667 | 11580 |
| 011186 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:23pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594507.1 | 512836.0 | 53365 | 1.64041666667 | 11186 |
| 012030 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:24pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594503.8 | 512835.7 | 53367 | 1.64041666667 | 12030 |
| 012384 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:25pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594501.0 | 512834.6 | 53369 | 1.64041666667 | 12384 |
| 012808 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:26pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594498.3 | 512833.0 | 53371 | 1.64041666667 | 12808 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:27pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594495.1 | 512832.1 | 53373 | 1.64041666667 | 12454 |
| 012833 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:28pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594491.9 | 512831.1 | 53375 | 1.64041666667 | 12833 |
| 012483 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:29pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594488.9 | 512830.7 | 53377 | 1.64041666667 | 12483 |
| 012414 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:30pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594485.7 | 512829.5 | 53379 | 1.64041666667 | 12414 |
| 012315 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:31pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594482.7 | 512828.8 | 53381 | 1.64041666667 | 12315 |
| 012297 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:32pm | Sensor | 1797-S0039-G-636-DTE | 6828.2 | 1594479.5 | 512829.0 | 53383 | 1.64041666667 | 12297 |
| 012587 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:33pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594476.9 | 512828.7 | 53385 | 1.64041666667 | 12587 |
| 012645 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:34pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594474.2 | 512828.5 | 53387 | 1.64041666667 | 12645 |
| 012115 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:35pm | Sensor | 1797-S0039-G-636-DTE | 6828.1 | 1594472.4 | 512827.9 | 53389 | 1.64041666667 | 12115 |
| 011600 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:36pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594471.6 | 512827.1 | 53391 | 1.64041666667 | 11600 |
| 011340 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:37pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594470.3 | 512827.1 | 53393 | 1.64041666667 | 11340 |
| 011913 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:38pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594470.8 | 512827.1 | 53395 | 1.64041666667 | 11913 |
| 012191 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:39pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594470.7 | 512827.0 | 53397 | 1.64041666667 | 12191 |
| 012047 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:40pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594470.7 | 512827.0 | 53399 | 1.64041666667 | 12047 |
| 012514 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:41pm | Sensor | 1797-S0039-G-636-DTE | 6827.9 | 1594470.8 | 512827.0 | 53401 | 1.64041666667 | 12514 |
| 012409 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:42pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594470.8 | 512827.0 | 53403 | 1.64041666667 | 12409 |
| 012357 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:43pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594470.8 | 512827.0 | 53405 | 1.64041666667 | 12357 |
| 011893 | 0 | GeoXH 6000 | 08/19/2015 | 03:02:44pm | Sensor | 1797-S0039-G-636-DTE | 6828.0 | 1594470.8 | 512827.0 | 53408 | 1.64041666667 | 11893 |
| 013517 | 0 | GeoXH 6000 | 08/19/2015 | 02:10:27pm | Sensor | 1797-S0038-G-636-DTE | 6818.9 | 1593930.3 | 511900.4 | 50609 | 1.64041666667 | 13517 |
| 013566 | 0 | GeoXH 6000 | 08/19/2015 | 02:10:27pm | Sensor | 1797-S0038-G-636-DTE | 6818.9 | 1593930.3 | 511900.4 | 50610 | 1.64041666667 | 13566 |
| 014246 | 0 | GeoXH 6000 | 08/19/2015 | 02:10:28pm | Sensor | 1797-S0038-G-636-DTE | 6818.9 | 1593930.3 | 511900.4 | 50611 | 1.64041666667 | 14246 |
| 013661 | 0 | GeoXH 6000 | 08/19/2015 | 02:10:29pm | Sensor | 1797-S0038-G-636-DTE | 6818.9 | 1593930.3 | 511900.4 | 50613 | 1.64041666667 | 13661 |
| 013729 | 0 | GeoXH 6000 | 08/19/2015 | 02:10:30pm | Sensor | 1797-S0038-G-636-DTE | 6818.9 | 1593930.3 | 511900.4 | 50615 | 1.64041666667 | 13729 |
| 014075 | 0 | GeoXH 6000 | 08/19/2015 | 02:10:31pm | Sensor | 1797-S0038-G-636-DTE | 6818.9 | 1593930.3 | 511900.4 | 50617 | 1.64041666667 | 14075 |
| 013519 | 0 | GeoXH 6000 | 08/19/2015 | 02:10:32pm | Sensor | 1797-S0038-G-636-DTE | 6818.8 | 1593930.3 | 511900.4 | 50619 | 1.64041666667 | 13519 |
| 013908 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:31pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594565.5 | 512256.8 | 50622 | 1.64041666667 | 13908 |
| 013455 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:32pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594565.5 | 512256.8 | 50624 | 1.64041666667 | 13455 |
| 015204 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:33pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.5 | 512256.8 | 50626 | 1.64041666667 | 15204 |
| 014889 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:34pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.5 | 512256.7 | 50628 | 1.64041666667 | 14889 |
| 014600 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:35pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.5 | 512256.7 | 50630 | 1.64041666667 | 14600 |
| 013695 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:36pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.5 | 512256.7 | 50632 | 1.64041666667 | 13695 |
| 013688 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:37pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.5 | 512256.7 | 50634 | 1.64041666667 | 13688 |
| 013744 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:38pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.5 | 512256.7 | 50636 | 1.64041666667 | 13744 |
| 014414 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:39pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.5 | 512256.7 | 50638 | 1.64041666667 | 14414 |
| 014625 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:40pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.5 | 512256.7 | 50640 | 1.64041666667 | 14625 |
| 014474 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:41pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.4 | 512256.7 | 50642 | 1.64041666667 | 14474 |
| 014681 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:42pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.4 | 512256.7 | 50644 | 1.64041666667 | 14681 |
| 014176 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:43pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.4 | 512256.7 | 50646 | 1.64041666667 | 14176 |
| 014439 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:44pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.4 | 512256.7 | 50648 | 1.64041666667 | 14439 |
| 015239 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:45pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.4 | 512256.7 | 50650 | 1.64041666667 | 15239 |
| 015172 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:46pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.4 | 512256.8 | 50652 | 1.64041666667 | 15172 |
| 014264 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:47pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594565.3 | 512256.8 | 50654 | 1.64041666667 | 14264 |
| 014578 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:48pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594565.3 | 512256.8 | 50656 | 1.64041666667 | 14578 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:49pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594565.3 | 512256.8 | 50658 | 1.64041666667 | 13795 |
| 014585 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:50pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594565.2 | 512256.9 | 50660 | 1.64041666667 | 14585 |
| 014534 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:51pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594564.5 | 512256.9 | 50662 | 1.64041666667 | 14534 |
| 014467 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:52pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594562.0 | 512256.4 | 50664 | 1.64041666667 | 14467 |
| 014325 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:53pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594559.5 | 512254.9 | 50666 | 1.64041666667 | 14325 |
| 014913 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:54pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594557.2 | 512253.1 | 50668 | 1.64041666667 | 14913 |
| 014943 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:55pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594554.7 | 512251.5 | 50670 | 1.64041666667 | 14943 |
| 015125 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:56pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594551.4 | 512249.7 | 50672 | 1.64041666667 | 15125 |
| 015821 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:57pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594548.8 | 512249.0 | 50674 | 1.64041666667 | 15821 |
| 015416 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:58pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594545.4 | 512248.1 | 50676 | 1.64041666667 | 15416 |
| 014777 | 0 | GeoXH 6000 | 08/19/2015 | 02:22:59pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594542.5 | 512246.8 | 50678 | 1.64041666667 | 14777 |
| 014934 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:00pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594539.2 | 512245.5 | 50680 | 1.64041666667 | 14934 |
| 014400 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:01pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594536.1 | 512244.6 | 50682 | 1.64041666667 | 14400 |
| 013830 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:02pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594533.0 | 512243.4 | 50684 | 1.64041666667 | 13830 |
| 013329 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:03pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594530.4 | 512241.5 | 50686 | 1.64041666667 | 13329 |
| 013550 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:04pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594527.5 | 512239.4 | 50688 | 1.64041666667 | 13550 |
| 013734 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:05pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594524.6 | 512238.0 | 50690 | 1.64041666667 | 13734 |
| 014198 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:06pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594521.3 | 512236.6 | 50692 | 1.64041666667 | 14198 |
| 013716 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:07pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594518.5 | 512235.3 | 50694 | 1.64041666667 | 13716 |
| 013175 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:08pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594515.4 | 512234.1 | 50696 | 1.64041666667 | 13175 |
| 014018 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:09pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594512.9 | 512232.4 | 50698 | 1.64041666667 | 14018 |
| 013878 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:10pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594510.6 | 512231.0 | 50700 | 1.64041666667 | 13878 |
| 013274 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:11pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594508.1 | 512230.1 | 50702 | 1.64041666667 | 13274 |
| 013016 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:12pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594505.5 | 512228.4 | 50704 | 1.64041666667 | 13016 |
| 013599 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:13pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594503.0 | 512227.4 | 50706 | 1.64041666667 | 13599 |
| 014452 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:14pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594500.8 | 512227.5 | 50708 | 1.64041666667 | 14452 |
| 014407 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:15pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594498.5 | 512227.3 | 50710 | 1.64041666667 | 14407 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594496.0 | 512227.6 | 50712 | 1.64041666667 | 14463 |
| 014061 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:17pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594493.7 | 512227.4 | 50714 | 1.64041666667 | 14061 |
| 015169 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:18pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594491.1 | 512227.0 | 50716 | 1.64041666667 | 15169 |
| 014667 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:19pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594488.5 | 512226.4 | 50718 | 1.64041666667 | 14667 |
| 014925 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:20pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594485.9 | 512224.4 | 50720 | 1.64041666667 | 14925 |
| 013915 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:21pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594483.4 | 512222.8 | 50722 | 1.64041666667 | 13915 |
| 013700 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:22pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594481.6 | 512221.4 | 50724 | 1.64041666667 | 13700 |
| 013383 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:23pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594480.9 | 512219.6 | 50726 | 1.64041666667 | 13383 |
| 013461 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:24pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594480.1 | 512217.8 | 50728 | 1.64041666667 | 13461 |
| 013556 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:25pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594479.8 | 512216.3 | 50730 | 1.64041666667 | 13556 |
| 013175 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:26pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594478.6 | 512215.8 | 50732 | 1.64041666667 | 13175 |
| 013651 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:27pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594478.3 | 512215.4 | 50734 | 1.64041666667 | 13651 |
| 013844 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:28pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594478.2 | 512215.3 | 50736 | 1.64041666667 | 13844 |
| 013697 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:29pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594478.1 | 512214.9 | 50738 | 1.64041666667 | 13697 |
| 013637 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:30pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594477.8 | 512214.1 | 50740 | 1.64041666667 | 13637 |
| 013708 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:31pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594477.5 | 512213.8 | 50742 | 1.64041666667 | 13708 |
| 013741 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:32pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594476.4 | 512213.9 | 50744 | 1.64041666667 | 13741 |
| 013271 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:33pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594476.0 | 512214.3 | 50746 | 1.64041666667 | 13271 |
| 013503 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:34pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594476.0 | 512213.9 | 50748 | 1.64041666667 | 13503 |
| 014120 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:35pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594476.4 | 512212.4 | 50750 | 1.64041666667 | 14120 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:36pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594475.4 | 512211.8 | 50752 | 1.64041666667 | 14355 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014494 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:37pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594473.6 | 512210.2 | 50754 | 1.64041666667 | 14494 |
| 014423 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:38pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594472.3 | 512208.6 | 50756 | 1.64041666667 | 14423 |
| 013670 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:39pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594471.2 | 512207.7 | 50758 | 1.64041666667 | 13670 |
| 014417 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:40pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594471.5 | 512206.0 | 50760 | 1.64041666667 | 14417 |
| 013742 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:41pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594472.6 | 512203.3 | 50762 | 1.64041666667 | 13742 |
| 013595 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:42pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594473.9 | 512199.9 | 50764 | 1.64041666667 | 13595 |
| 014802 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:43pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594474.7 | 512197.4 | 50766 | 1.64041666667 | 14802 |
| 014288 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:44pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594475.9 | 512194.7 | 50768 | 1.64041666667 | 14288 |
| 013789 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:45pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594476.2 | 512192.1 | 50770 | 1.64041666667 | 13789 |
| 013809 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:46pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594476.6 | 512191.0 | 50772 | 1.64041666667 | 13809 |
| 014742 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:47pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594476.6 | 512189.8 | 50774 | 1.64041666667 | 14742 |
| 014405 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:48pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594477.0 | 512187.3 | 50776 | 1.64041666667 | 14405 |
| 014658 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:49pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594477.6 | 512185.4 | 50778 | 1.64041666667 | 14658 |
| 014837 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:50pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594479.4 | 512183.2 | 50780 | 1.64041666667 | 14837 |
| 014931 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:51pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594480.2 | 512180.8 | 50782 | 1.64041666667 | 14931 |
| 014998 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:52pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594481.5 | 512178.5 | 50784 | 1.64041666667 | 14998 |
| 014339 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:53pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594482.1 | 512176.1 | 50786 | 1.64041666667 | 14339 |
| 014741 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:54pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594483.3 | 512173.5 | 50788 | 1.64041666667 | 14741 |
| 014359 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:55pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594484.0 | 512170.8 | 50790 | 1.64041666667 | 14359 |
| 014984 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:56pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594485.6 | 512168.4 | 50792 | 1.64041666667 | 14984 |
| 014954 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:57pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594486.8 | 512166.1 | 50794 | 1.64041666667 | 14954 |
| 015199 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:58pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594488.4 | 512163.9 | 50796 | 1.64041666667 | 15199 |
| 014639 | 0 | GeoXH 6000 | 08/19/2015 | 02:23:59pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594489.3 | 512161.6 | 50798 | 1.64041666667 | 14639 |
| 015112 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:00pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594490.4 | 512159.0 | 50800 | 1.64041666667 | 15112 |
| 015303 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:01pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594491.1 | 512157.2 | 50802 | 1.64041666667 | 15303 |
| 014810 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:02pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594491.7 | 512155.3 | 50804 | 1.64041666667 | 14810 |
| 015973 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:03pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594492.5 | 512154.0 | 50806 | 1.64041666667 | 15973 |
| 014887 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:04pm | Sensor | 1797-S0038-G-636-DTE | 6824.4 | 1594493.9 | 512153.4 | 50808 | 1.64041666667 | 14887 |
| 014885 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:05pm | Sensor | 1797-S0038-G-636-DTE | 6824.4 | 1594494.0 | 512153.2 | 50810 | 1.64041666667 | 14885 |
| 014743 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:06pm | Sensor | 1797-S0038-G-636-DTE | 6824.4 | 1594493.9 | 512153.2 | 50812 | 1.64041666667 | 14743 |
| 015028 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:07pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594493.9 | 512153.2 | 50814 | 1.64041666667 | 15028 |
| 015091 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:08pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594493.8 | 512153.2 | 50816 | 1.64041666667 | 15091 |
| 015246 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:09pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594493.5 | 512152.4 | 50818 | 1.64041666667 | 15246 |
| 014178 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:10pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594492.0 | 512149.0 | 50820 | 1.64041666667 | 14178 |
| 014373 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:11pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594492.0 | 512146.8 | 50822 | 1.64041666667 | 14373 |
| 013627 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:12pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594494.2 | 512145.3 | 50824 | 1.64041666667 | 13627 |
| 013695 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:13pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594495.7 | 512142.9 | 50826 | 1.64041666667 | 13695 |
| 014648 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:14pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594497.5 | 512139.9 | 50828 | 1.64041666667 | 14648 |
| 014337 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:15pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594498.3 | 512137.6 | 50830 | 1.64041666667 | 14337 |
| 014312 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594499.9 | 512134.9 | 50832 | 1.64041666667 | 14312 |
| 013630 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:17pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594501.4 | 512132.6 | 50834 | 1.64041666667 | 13630 |
| 013502 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:18pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594502.7 | 512129.8 | 50836 | 1.64041666667 | 13502 |
| 013422 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:19pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594504.2 | 512127.5 | 50838 | 1.64041666667 | 13422 |
| 013565 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:20pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594505.2 | 512124.8 | 50840 | 1.64041666667 | 13565 |
| 013600 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:21pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594506.2 | 512122.4 | 50842 | 1.64041666667 | 13600 |
| 013552 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:22pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594507.4 | 512119.9 | 50844 | 1.64041666667 | 13552 |
| 013751 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:23pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594508.1 | 512117.4 | 50846 | 1.64041666667 | 13751 |
| 013495 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:24pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594509.4 | 512115.3 | 50848 | 1.64041666667 | 13495 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013958 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:25pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594510.4 | 512113.0 | 50850 | 1.64041666667 | 13958 |
| 014751 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:26pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594512.1 | 512111.5 | 50852 | 1.64041666667 | 14751 |
| 015047 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:27pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594514.4 | 512111.2 | 50854 | 1.64041666667 | 15047 |
| 015454 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:28pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594517.5 | 512111.6 | 50856 | 1.64041666667 | 15454 |
| 014625 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:29pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594520.0 | 512112.6 | 50858 | 1.64041666667 | 14625 |
| 014294 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:30pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594523.2 | 512113.9 | 50860 | 1.64041666667 | 14294 |
| 013763 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:31pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594525.8 | 512114.7 | 50862 | 1.64041666667 | 13763 |
| 013276 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:32pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594528.2 | 512116.0 | 50864 | 1.64041666667 | 13276 |
| 013468 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:33pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594530.6 | 512117.0 | 50866 | 1.64041666667 | 13468 |
| 014243 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:34pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594532.9 | 512118.9 | 50868 | 1.64041666667 | 14243 |
| 014364 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:35pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594535.4 | 512120.2 | 50870 | 1.64041666667 | 14364 |
| 014702 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:36pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594538.4 | 512121.1 | 50872 | 1.64041666667 | 14702 |
| 014382 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:37pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594540.9 | 512122.3 | 50874 | 1.64041666667 | 14382 |
| 014802 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:38pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594544.2 | 512122.9 | 50876 | 1.64041666667 | 14802 |
| 014799 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:39pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594546.7 | 512123.8 | 50878 | 1.64041666667 | 14799 |
| 015697 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:40pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594549.9 | 512125.4 | 50880 | 1.64041666667 | 15697 |
| 016029 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:41pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594552.2 | 512126.5 | 50882 | 1.64041666667 | 16029 |
| 014746 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:42pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594554.9 | 512128.1 | 50884 | 1.64041666667 | 14746 |
| 014400 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:43pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594557.6 | 512128.8 | 50886 | 1.64041666667 | 14400 |
| 014137 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:44pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594560.6 | 512130.0 | 50888 | 1.64041666667 | 14137 |
| 014672 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:45pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594563.2 | 512130.7 | 50890 | 1.64041666667 | 14672 |
| 014793 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:46pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594566.2 | 512131.6 | 50892 | 1.64041666667 | 14793 |
| 014216 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:47pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594568.4 | 512132.8 | 50894 | 1.64041666667 | 14216 |
| 014664 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:48pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594571.2 | 512133.5 | 50896 | 1.64041666667 | 14664 |
| 014863 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:49pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594573.7 | 512134.7 | 50898 | 1.64041666667 | 14863 |
| 014038 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:50pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594577.1 | 512135.2 | 50900 | 1.64041666667 | 14038 |
| 015036 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:51pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594579.9 | 512135.9 | 50902 | 1.64041666667 | 15036 |
| 015718 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:52pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594582.5 | 512137.3 | 50904 | 1.64041666667 | 15718 |
| 015944 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:53pm | Sensor | 1797-S0038-G-636-DTE | 6826.6 | 1594585.0 | 512138.5 | 50906 | 1.64041666667 | 15944 |
| 015051 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:54pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594587.4 | 512140.9 | 50908 | 1.64041666667 | 15051 |
| 014083 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:55pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594590.6 | 512142.6 | 50910 | 1.64041666667 | 14083 |
| 013877 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:56pm | Sensor | 1797-S0038-G-636-DTE | 6826.8 | 1594593.6 | 512144.7 | 50912 | 1.64041666667 | 13877 |
| 013581 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:57pm | Sensor | 1797-S0038-G-636-DTE | 6826.8 | 1594595.6 | 512146.4 | 50914 | 1.64041666667 | 13581 |
| 013256 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:58pm | Sensor | 1797-S0038-G-636-DTE | 6826.9 | 1594598.6 | 512147.8 | 50916 | 1.64041666667 | 13256 |
| 013674 | 0 | GeoXH 6000 | 08/19/2015 | 02:24:59pm | Sensor | 1797-S0038-G-636-DTE | 6826.9 | 1594601.1 | 512149.3 | 50918 | 1.64041666667 | 13674 |
| 014449 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:00pm | Sensor | 1797-S0038-G-636-DTE | 6827.1 | 1594604.0 | 512150.5 | 50920 | 1.64041666667 | 14449 |
| 014870 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:01pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594606.5 | 512151.5 | 50922 | 1.64041666667 | 14870 |
| 014124 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:02pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594609.0 | 512152.9 | 50924 | 1.64041666667 | 14124 |
| 014492 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:03pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594611.1 | 512153.6 | 50926 | 1.64041666667 | 14492 |
| 013799 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:04pm | Sensor | 1797-S0038-G-636-DTE | 6827.4 | 1594612.5 | 512155.5 | 50928 | 1.64041666667 | 13799 |
| 013830 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:05pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594614.3 | 512157.1 | 50930 | 1.64041666667 | 13830 |
| 013141 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:06pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594615.2 | 512159.2 | 50932 | 1.64041666667 | 13141 |
| 013714 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:07pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594614.8 | 512161.9 | 50934 | 1.64041666667 | 13714 |
| 013174 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:08pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594614.3 | 512164.6 | 50936 | 1.64041666667 | 13174 |
| 013373 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:09pm | Sensor | 1797-S0038-G-636-DTE | 6827.8 | 1594613.7 | 512167.1 | 50938 | 1.64041666667 | 13373 |
| 013635 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:10pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594611.8 | 512170.0 | 50940 | 1.64041666667 | 13635 |
| 013887 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:11pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594610.5 | 512172.6 | 50942 | 1.64041666667 | 13887 |
| 013159 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:12pm | Sensor | 1797-S0038-G-636-DTE | 6827.6 | 1594608.6 | 512175.0 | 50944 | 1.64041666667 | 13159 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013139 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:13pm | Sensor | 1797-S0038-G-636-DTE | 6827.6 | 1594606.7 | 512176.8 | 50946 | 1.64041666667 | 13139 |
| 013316 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:14pm | Sensor | 1797-S0038-G-636-DTE | 6827.8 | 1594605.9 | 512179.4 | 50948 | 1.64041666667 | 13316 |
| 013190 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:15pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594604.7 | 512181.9 | 50950 | 1.64041666667 | 13190 |
| 013119 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:16pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594603.7 | 512184.6 | 50952 | 1.64041666667 | 13119 |
| 013665 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:17pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594602.8 | 512187.1 | 50954 | 1.64041666667 | 13665 |
| 013844 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:18pm | Sensor | 1797-S0038-G-636-DTE | 6827.6 | 1594601.2 | 512189.9 | 50956 | 1.64041666667 | 13844 |
| 013577 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:19pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594600.4 | 512192.6 | 50958 | 1.64041666667 | 13577 |
| 013472 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:20pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594598.7 | 512195.4 | 50960 | 1.64041666667 | 13472 |
| 013833 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:21pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594597.1 | 512198.0 | 50962 | 1.64041666667 | 13833 |
| 012873 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:22pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594595.6 | 512201.0 | 50964 | 1.64041666667 | 12873 |
| 012581 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:23pm | Sensor | 1797-S0038-G-636-DTE | 6827.4 | 1594594.0 | 512203.5 | 50966 | 1.64041666667 | 12581 |
| 013744 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:24pm | Sensor | 1797-S0038-G-636-DTE | 6827.4 | 1594593.1 | 512206.4 | 50968 | 1.64041666667 | 13744 |
| 013851 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:25pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594592.0 | 512208.6 | 50970 | 1.64041666667 | 13851 |
| 014144 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:26pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594590.7 | 512211.3 | 50972 | 1.64041666667 | 14144 |
| 013821 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:27pm | Sensor | 1797-S0038-G-636-DTE | 6827.2 | 1594589.8 | 512214.0 | 50974 | 1.64041666667 | 13821 |
| 014576 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:28pm | Sensor | 1797-S0038-G-636-DTE | 6826.9 | 1594587.9 | 512216.9 | 50976 | 1.64041666667 | 14576 |
| 013359 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:29pm | Sensor | 1797-S0038-G-636-DTE | 6826.8 | 1594586.9 | 512219.0 | 50978 | 1.64041666667 | 13359 |
| 013942 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:30pm | Sensor | 1797-S0038-G-636-DTE | 6826.6 | 1594585.8 | 512221.2 | 50980 | 1.64041666667 | 13942 |
| 013317 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:31pm | Sensor | 1797-S0038-G-636-DTE | 6826.6 | 1594584.8 | 512223.8 | 50982 | 1.64041666667 | 13317 |
| 013378 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:32pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594583.9 | 512226.3 | 50984 | 1.64041666667 | 13378 |
| 013773 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:33pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594582.2 | 512228.8 | 50986 | 1.64041666667 | 13773 |
| 014159 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:34pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594580.7 | 512232.0 | 50988 | 1.64041666667 | 14159 |
| 014407 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:35pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594579.2 | 512235.3 | 50990 | 1.64041666667 | 14407 |
| 014846 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:36pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594577.3 | 512238.4 | 50992 | 1.64041666667 | 14846 |
| 014081 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:37pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594575.9 | 512241.3 | 50994 | 1.64041666667 | 14081 |
| 013478 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:38pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594574.7 | 512244.0 | 50996 | 1.64041666667 | 13478 |
| 013071 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:39pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594573.0 | 512246.7 | 50998 | 1.64041666667 | 13071 |
| 014357 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:40pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594571.8 | 512249.5 | 51000 | 1.64041666667 | 14357 |
| 013746 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:41pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594570.8 | 512251.7 | 51002 | 1.64041666667 | 13746 |
| 013402 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:42pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594569.4 | 512253.6 | 51004 | 1.64041666667 | 13402 |
| 014671 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:43pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594568.3 | 512255.0 | 51006 | 1.64041666667 | 14671 |
| 014800 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:44pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594566.7 | 512256.3 | 51008 | 1.64041666667 | 14800 |
| 014722 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:45pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594566.2 | 512257.9 | 51010 | 1.64041666667 | 14722 |
| 014289 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:46pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594566.3 | 512258.1 | 51012 | 1.64041666667 | 14289 |
| 014787 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:47pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594566.8 | 512257.6 | 51014 | 1.64041666667 | 14787 |
| 014175 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:48pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594567.4 | 512257.0 | 51016 | 1.64041666667 | 14175 |
| 014273 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:49pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594568.7 | 512255.9 | 51018 | 1.64041666667 | 14273 |
| 013991 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:50pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594570.9 | 512254.5 | 51020 | 1.64041666667 | 13991 |
| 013810 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:51pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594573.4 | 512253.4 | 51022 | 1.64041666667 | 13810 |
| 014563 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:52pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594575.2 | 512251.1 | 51024 | 1.64041666667 | 14563 |
| 014477 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:53pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594575.5 | 512248.3 | 51026 | 1.64041666667 | 14477 |
| 014068 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:54pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594575.4 | 512245.4 | 51028 | 1.64041666667 | 14068 |
| 014326 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:55pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594575.0 | 512242.6 | 51030 | 1.64041666667 | 14326 |
| 014268 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:56pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594575.8 | 512239.3 | 51032 | 1.64041666667 | 14268 |
| 014873 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:57pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594576.5 | 512236.3 | 51034 | 1.64041666667 | 14873 |
| 014253 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:58pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594577.2 | 512233.3 | 51036 | 1.64041666667 | 14253 |
| 014332 | 0 | GeoXH 6000 | 08/19/2015 | 02:25:59pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594578.4 | 512230.8 | 51038 | 1.64041666667 | 14332 |
| 014024 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:00pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594578.9 | 512227.4 | 51040 | 1.64041666667 | 14024 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015014 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:01pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594579.1 | 512224.6 | 51042 | 1.64041666667 | 15014 |
| 015570 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:02pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594579.5 | 512221.0 | 51044 | 1.64041666667 | 15570 |
| 014608 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:03pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594579.4 | 512217.8 | 51046 | 1.64041666667 | 14608 |
| 015499 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:04pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594579.4 | 512214.3 | 51048 | 1.64041666667 | 15499 |
| 015828 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:05pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594580.0 | 512211.5 | 51050 | 1.64041666667 | 15828 |
| 015008 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:06pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594580.2 | 512208.0 | 51052 | 1.64041666667 | 15008 |
| 015019 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:07pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594580.8 | 512204.3 | 51054 | 1.64041666667 | 15019 |
| 014666 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:08pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594581.8 | 512200.9 | 51056 | 1.64041666667 | 14666 |
| 014212 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:09pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594581.9 | 512197.3 | 51058 | 1.64041666667 | 14212 |
| 014872 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:10pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594582.1 | 512194.0 | 51060 | 1.64041666667 | 14872 |
| 014170 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:11pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594582.7 | 512190.6 | 51062 | 1.64041666667 | 14170 |
| 015140 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:12pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594583.0 | 512187.1 | 51064 | 1.64041666667 | 15140 |
| 015506 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:13pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594583.8 | 512183.6 | 51066 | 1.64041666667 | 15506 |
| 014445 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:14pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594584.9 | 512180.5 | 51068 | 1.64041666667 | 14445 |
| 014290 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:15pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594584.6 | 512177.4 | 51070 | 1.64041666667 | 14290 |
| 014525 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594584.5 | 512174.5 | 51072 | 1.64041666667 | 14525 |
| 014351 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:17pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594584.6 | 512172.0 | 51074 | 1.64041666667 | 14351 |
| 014560 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:18pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594583.9 | 512168.9 | 51076 | 1.64041666667 | 14560 |
| 014325 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:19pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594584.5 | 512166.3 | 51078 | 1.64041666667 | 14325 |
| 014140 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:20pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594584.2 | 512163.6 | 51080 | 1.64041666667 | 14140 |
| 014088 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:21pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594583.7 | 512161.1 | 51082 | 1.64041666667 | 14088 |
| 014247 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:22pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594583.7 | 512158.6 | 51084 | 1.64041666667 | 14247 |
| 014921 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:23pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594583.4 | 512157.4 | 51086 | 1.64041666667 | 14921 |
| 015008 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:24pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594582.8 | 512156.4 | 51088 | 1.64041666667 | 15008 |
| 015304 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:25pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594580.7 | 512156.0 | 51090 | 1.64041666667 | 15304 |
| 014339 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:26pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594577.1 | 512156.2 | 51092 | 1.64041666667 | 14339 |
| 013975 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:27pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594574.1 | 512155.7 | 51094 | 1.64041666667 | 13975 |
| 013711 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:28pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594571.5 | 512155.1 | 51096 | 1.64041666667 | 13711 |
| 014012 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:29pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594568.6 | 512155.8 | 51098 | 1.64041666667 | 14012 |
| 013664 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:30pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594565.5 | 512156.1 | 51100 | 1.64041666667 | 13664 |
| 013754 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:31pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594562.9 | 512156.1 | 51102 | 1.64041666667 | 13754 |
| 013976 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:32pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594560.2 | 512154.9 | 51104 | 1.64041666667 | 13976 |
| 013936 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:33pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594557.9 | 512153.5 | 51106 | 1.64041666667 | 13936 |
| 013772 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:34pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594554.5 | 512153.4 | 51108 | 1.64041666667 | 13772 |
| 013454 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:35pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594551.4 | 512153.3 | 51110 | 1.64041666667 | 13454 |
| 014108 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:36pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594548.3 | 512153.0 | 51112 | 1.64041666667 | 14108 |
| 014258 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:37pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594545.2 | 512153.2 | 51114 | 1.64041666667 | 14258 |
| 014927 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:38pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594542.0 | 512152.9 | 51116 | 1.64041666667 | 14927 |
| 014141 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:39pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594538.6 | 512152.8 | 51118 | 1.64041666667 | 14141 |
| 014164 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:40pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594535.9 | 512153.7 | 51120 | 1.64041666667 | 14164 |
| 013247 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:41pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594533.5 | 512153.9 | 51122 | 1.64041666667 | 13247 |
| 013579 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:42pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594530.7 | 512155.5 | 51124 | 1.64041666667 | 13579 |
| 014283 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:43pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594528.5 | 512156.1 | 51126 | 1.64041666667 | 14283 |
| 014882 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:44pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594525.3 | 512156.1 | 51128 | 1.64041666667 | 14882 |
| 014453 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:45pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594522.9 | 512155.7 | 51130 | 1.64041666667 | 14453 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:46pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594519.5 | 512154.6 | 51132 | 1.64041666667 | 14737 |
| 014665 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:47pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594517.3 | 512154.0 | 51134 | 1.64041666667 | 14665 |
| 015501 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:48pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594514.2 | 512153.1 | 51136 | 1.64041666667 | 15501 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014899 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:49pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594511.6 | 512153.7 | 51138 | 1.64041666667 | 14899 |
| 013938 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:50pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594508.6 | 512153.5 | 51140 | 1.64041666667 | 13938 |
| 014245 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:51pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594505.9 | 512153.7 | 51142 | 1.64041666667 | 14245 |
| 014680 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:52pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594503.2 | 512153.6 | 51144 | 1.64041666667 | 14680 |
| 015202 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:53pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594501.0 | 512153.3 | 51146 | 1.64041666667 | 15202 |
| 015226 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:54pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594498.5 | 512153.6 | 51148 | 1.64041666667 | 15226 |
| 014445 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:55pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594496.3 | 512153.4 | 51150 | 1.64041666667 | 14445 |
| 014155 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:56pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594493.5 | 512153.9 | 51152 | 1.64041666667 | 14155 |
| 014734 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:57pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594492.3 | 512153.6 | 51154 | 1.64041666667 | 14734 |
| 014655 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:58pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594492.0 | 512154.0 | 51156 | 1.64041666667 | 14655 |
| 015136 | 0 | GeoXH 6000 | 08/19/2015 | 02:26:59pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594491.1 | 512154.9 | 51158 | 1.64041666667 | 15136 |
| 014866 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:00pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594490.0 | 512156.0 | 51160 | 1.64041666667 | 14866 |
| 014670 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:01pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594490.2 | 512156.3 | 51162 | 1.64041666667 | 14670 |
| 014349 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:02pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594490.2 | 512156.3 | 51164 | 1.64041666667 | 14349 |
| 014259 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:03pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594490.1 | 512156.3 | 51166 | 1.64041666667 | 14259 |
| 015273 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:04pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594490.1 | 512156.3 | 51168 | 1.64041666667 | 15273 |
| 015483 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:05pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594490.1 | 512156.3 | 51170 | 1.64041666667 | 15483 |
| 015339 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:06pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594489.9 | 512156.2 | 51172 | 1.64041666667 | 15339 |
| 015063 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:07pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594489.9 | 512156.1 | 51174 | 1.64041666667 | 15063 |
| 014728 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:08pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594489.8 | 512156.0 | 51176 | 1.64041666667 | 14728 |
| 014449 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:09pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594490.0 | 512155.9 | 51178 | 1.64041666667 | 14449 |
| 014195 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:10pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594490.8 | 512156.3 | 51180 | 1.64041666667 | 14195 |
| 014607 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:11pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594491.1 | 512157.2 | 51182 | 1.64041666667 | 14607 |
| 014524 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:12pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594490.4 | 512159.8 | 51184 | 1.64041666667 | 14524 |
| 015317 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:13pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594489.9 | 512162.6 | 51186 | 1.64041666667 | 15317 |
| 013993 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:14pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594488.9 | 512165.8 | 51188 | 1.64041666667 | 13993 |
| 014688 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:15pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594488.0 | 512168.5 | 51190 | 1.64041666667 | 14688 |
| 015425 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:16pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594487.7 | 512171.5 | 51192 | 1.64041666667 | 15425 |
| 015014 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:17pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594486.7 | 512174.5 | 51194 | 1.64041666667 | 15014 |
| 015135 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:18pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594486.2 | 512177.5 | 51196 | 1.64041666667 | 15135 |
| 014596 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:19pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594485.5 | 512179.8 | 51198 | 1.64041666667 | 14596 |
| 014390 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:20pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594484.3 | 512182.9 | 51200 | 1.64041666667 | 14390 |
| 014664 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:21pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594484.1 | 512185.9 | 51202 | 1.64041666667 | 14664 |
| 014856 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:22pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594483.9 | 512188.7 | 51204 | 1.64041666667 | 14856 |
| 014139 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:23pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594485.7 | 512191.0 | 51206 | 1.64041666667 | 14139 |
| 013915 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:24pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594488.4 | 512192.8 | 51208 | 1.64041666667 | 13915 |
| 014495 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:25pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594491.0 | 512193.8 | 51210 | 1.64041666667 | 14495 |
| 014243 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:26pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594494.0 | 512194.0 | 51212 | 1.64041666667 | 14243 |
| 014184 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:27pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594496.9 | 512194.8 | 51214 | 1.64041666667 | 14184 |
| 014158 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:28pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594499.7 | 512195.5 | 51216 | 1.64041666667 | 14158 |
| 015007 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:29pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594502.4 | 512196.1 | 51218 | 1.64041666667 | 15007 |
| 014898 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:30pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594505.2 | 512197.1 | 51220 | 1.64041666667 | 14898 |
| 014470 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:31pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594508.4 | 512198.3 | 51222 | 1.64041666667 | 14470 |
| 013412 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:32pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594510.6 | 512200.2 | 51224 | 1.64041666667 | 13412 |
| 014474 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:33pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594512.2 | 512202.3 | 51226 | 1.64041666667 | 14474 |
| 014164 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:34pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594514.3 | 512204.1 | 51228 | 1.64041666667 | 14164 |
| 014455 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:35pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594515.4 | 512206.5 | 51230 | 1.64041666667 | 14455 |
| 014055 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:36pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594516.5 | 512208.9 | 51232 | 1.64041666667 | 14055 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013261 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:37pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594517.2 | 512211.3 | 51234 | 1.64041666667 | 13261 |
| 012844 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:38pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594517.9 | 512213.8 | 51236 | 1.64041666667 | 12844 |
| 013173 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:39pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594517.9 | 512216.2 | 51238 | 1.64041666667 | 13173 |
| 013350 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:40pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594516.9 | 512218.5 | 51240 | 1.64041666667 | 13350 |
| 013742 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:41pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594516.7 | 512221.0 | 51242 | 1.64041666667 | 13742 |
| 013557 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:42pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594516.0 | 512223.5 | 51244 | 1.64041666667 | 13557 |
| 013866 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:43pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594515.9 | 512225.5 | 51246 | 1.64041666667 | 13866 |
| 014114 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:44pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594515.6 | 512227.9 | 51248 | 1.64041666667 | 14114 |
| 013827 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:45pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594515.5 | 512229.7 | 51250 | 1.64041666667 | 13827 |
| 013425 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:46pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594516.1 | 512231.2 | 51252 | 1.64041666667 | 13425 |
| 014661 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:47pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594516.5 | 512232.6 | 51254 | 1.64041666667 | 14661 |
| 014382 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:48pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594518.2 | 512233.3 | 51256 | 1.64041666667 | 14382 |
| 014802 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:49pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594520.2 | 512234.6 | 51258 | 1.64041666667 | 14802 |
| 014213 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:50pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594523.2 | 512234.5 | 51260 | 1.64041666667 | 14213 |
| 014850 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:51pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594526.1 | 512235.2 | 51262 | 1.64041666667 | 14850 |
| 014683 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:52pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594528.6 | 512236.1 | 51264 | 1.64041666667 | 14683 |
| 014597 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:53pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594531.1 | 512236.5 | 51266 | 1.64041666667 | 14597 |
| 013475 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:54pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594533.5 | 512237.8 | 51268 | 1.64041666667 | 13475 |
| 012815 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:55pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594536.1 | 512238.9 | 51270 | 1.64041666667 | 12815 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:56pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594539.2 | 512240.1 | 51272 | 1.64041666667 | 12743 |
| 013543 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:57pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594541.5 | 512241.5 | 51274 | 1.64041666667 | 13543 |
| 013288 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:58pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594544.4 | 512242.3 | 51276 | 1.64041666667 | 13288 |
| 013182 | 0 | GeoXH 6000 | 08/19/2015 | 02:27:59pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594547.0 | 512243.8 | 51278 | 1.64041666667 | 13182 |
| 014007 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:00pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594549.8 | 512244.9 | 51280 | 1.64041666667 | 14007 |
| 014659 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:01pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594552.4 | 512246.1 | 51282 | 1.64041666667 | 14659 |
| 014350 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:02pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594554.6 | 512247.7 | 51284 | 1.64041666667 | 14350 |
| 014349 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:03pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594556.9 | 512248.7 | 51286 | 1.64041666667 | 14349 |
| 014806 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:04pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594559.9 | 512249.7 | 51288 | 1.64041666667 | 14806 |
| 013751 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:05pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594561.9 | 512249.8 | 51290 | 1.64041666667 | 13751 |
| 013990 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:06pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594564.7 | 512250.3 | 51292 | 1.64041666667 | 13990 |
| 014057 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:07pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594567.2 | 512250.8 | 51294 | 1.64041666667 | 14057 |
| 013832 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:08pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594568.6 | 512249.3 | 51296 | 1.64041666667 | 13832 |
| 014103 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:09pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594569.2 | 512248.9 | 51298 | 1.64041666667 | 14103 |
| 015043 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:10pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594569.3 | 512248.8 | 51300 | 1.64041666667 | 15043 |
| 015166 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:11pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594569.3 | 512248.7 | 51302 | 1.64041666667 | 15166 |
| 014546 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:12pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594569.1 | 512247.9 | 51304 | 1.64041666667 | 14546 |
| 014182 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:13pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594568.4 | 512245.8 | 51306 | 1.64041666667 | 14182 |
| 014592 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:14pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594568.8 | 512242.2 | 51308 | 1.64041666667 | 14592 |
| 014425 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:15pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594568.9 | 512238.9 | 51310 | 1.64041666667 | 14425 |
| 014347 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594569.2 | 512235.0 | 51312 | 1.64041666667 | 14347 |
| 014490 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:17pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594569.9 | 512231.8 | 51314 | 1.64041666667 | 14490 |
| 014173 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:18pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594570.5 | 512227.9 | 51316 | 1.64041666667 | 14173 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:19pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594570.7 | 512224.4 | 51318 | 1.64041666667 | 14602 |
| 014754 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:20pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594571.1 | 512220.2 | 51320 | 1.64041666667 | 14754 |
| 015349 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:21pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594571.6 | 512216.8 | 51322 | 1.64041666667 | 15349 |
| 014168 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:22pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594571.6 | 512212.6 | 51324 | 1.64041666667 | 14168 |
| 014622 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:23pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594571.7 | 512209.2 | 51326 | 1.64041666667 | 14622 |
| 014667 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:24pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594572.2 | 512205.2 | 51328 | 1.64041666667 | 14667 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014813 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:25pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594572.4 | 512201.7 | 51330 | 1.64041666667 | 14813 |
| 014940 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:26pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594572.5 | 512197.3 | 51332 | 1.64041666667 | 14940 |
| 014955 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:27pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594572.8 | 512193.3 | 51334 | 1.64041666667 | 14955 |
| 014984 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:28pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594573.4 | 512189.1 | 51336 | 1.64041666667 | 14984 |
| 014331 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:29pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594573.5 | 512185.4 | 51338 | 1.64041666667 | 14331 |
| 014519 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:30pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594573.0 | 512181.3 | 51340 | 1.64041666667 | 14519 |
| 014332 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:31pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594572.7 | 512178.1 | 51342 | 1.64041666667 | 14332 |
| 014196 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:32pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594572.8 | 512173.9 | 51344 | 1.64041666667 | 14196 |
| 013385 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:33pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594572.8 | 512171.0 | 51346 | 1.64041666667 | 13385 |
| 012682 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:34pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594572.1 | 512167.1 | 51348 | 1.64041666667 | 12682 |
| 013111 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:35pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594571.7 | 512163.5 | 51350 | 1.64041666667 | 13111 |
| 013577 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:36pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594571.7 | 512160.0 | 51352 | 1.64041666667 | 13577 |
| 013839 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:37pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594570.4 | 512157.1 | 51354 | 1.64041666667 | 13839 |
| 014925 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:38pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594568.1 | 512155.8 | 51356 | 1.64041666667 | 14925 |
| 014447 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:39pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594565.9 | 512156.8 | 51358 | 1.64041666667 | 14447 |
| 014494 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:40pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594564.2 | 512159.4 | 51360 | 1.64041666667 | 14494 |
| 014783 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:41pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594563.9 | 512162.6 | 51362 | 1.64041666667 | 14783 |
| 015380 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:42pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594563.3 | 512166.2 | 51364 | 1.64041666667 | 15380 |
| 014516 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:43pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594562.8 | 512170.0 | 51366 | 1.64041666667 | 14516 |
| 014735 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:44pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594562.7 | 512173.9 | 51368 | 1.64041666667 | 14735 |
| 014378 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:45pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594562.4 | 512177.5 | 51370 | 1.64041666667 | 14378 |
| 015025 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:46pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594561.9 | 512182.3 | 51372 | 1.64041666667 | 15025 |
| 014407 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:47pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594561.6 | 512185.8 | 51374 | 1.64041666667 | 14407 |
| 013998 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:48pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594561.9 | 512190.3 | 51376 | 1.64041666667 | 13998 |
| 013717 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:49pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594562.4 | 512193.7 | 51378 | 1.64041666667 | 13717 |
| 014923 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:50pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594562.7 | 512197.9 | 51380 | 1.64041666667 | 14923 |
| 014394 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:51pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594562.5 | 512201.8 | 51382 | 1.64041666667 | 14394 |
| 014966 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:52pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594562.1 | 512205.7 | 51384 | 1.64041666667 | 14966 |
| 014133 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:53pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594561.7 | 512209.3 | 51386 | 1.64041666667 | 14133 |
| 013987 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:54pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594560.9 | 512213.9 | 51388 | 1.64041666667 | 13987 |
| 014273 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:55pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594559.9 | 512217.5 | 51390 | 1.64041666667 | 14273 |
| 013848 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:56pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594558.7 | 512222.2 | 51392 | 1.64041666667 | 13848 |
| 014119 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:57pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594558.0 | 512226.4 | 51394 | 1.64041666667 | 14119 |
| 014745 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:58pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594557.5 | 512230.6 | 51396 | 1.64041666667 | 14745 |
| 014339 | 0 | GeoXH 6000 | 08/19/2015 | 02:28:59pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594556.6 | 512234.3 | 51398 | 1.64041666667 | 14339 |
| 014095 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:00pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594555.1 | 512238.1 | 51400 | 1.64041666667 | 14095 |
| 013906 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:01pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594554.2 | 512241.4 | 51402 | 1.64041666667 | 13906 |
| 013642 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:02pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594553.2 | 512245.4 | 51404 | 1.64041666667 | 13642 |
| 014108 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:03pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594552.0 | 512248.4 | 51406 | 1.64041666667 | 14108 |
| 014963 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:04pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594550.3 | 512250.4 | 51408 | 1.64041666667 | 14963 |
| 014957 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:05pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594548.3 | 512250.0 | 51410 | 1.64041666667 | 14957 |
| 013611 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:06pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594545.3 | 512248.2 | 51412 | 1.64041666667 | 13611 |
| 014308 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:07pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594544.1 | 512245.6 | 51414 | 1.64041666667 | 14308 |
| 013358 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:08pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594544.1 | 512241.5 | 51416 | 1.64041666667 | 13358 |
| 013041 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:09pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594544.2 | 512238.4 | 51418 | 1.64041666667 | 13041 |
| 014048 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:10pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594544.3 | 512234.6 | 51420 | 1.64041666667 | 14048 |
| 013489 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:11pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594544.9 | 512231.8 | 51422 | 1.64041666667 | 13489 |
| 014083 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:12pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594546.1 | 512228.5 | 51424 | 1.64041666667 | 14083 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013464 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:13pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594546.8 | 512225.0 | 51426 | 1.64041666667 | 13464 |
| 014128 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:14pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594547.7 | 512221.0 | 51428 | 1.64041666667 | 14128 |
| 013789 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:15pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594548.4 | 512218.3 | 51430 | 1.64041666667 | 13789 |
| 014206 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594549.0 | 512214.2 | 51432 | 1.64041666667 | 14206 |
| 014673 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:17pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594549.0 | 512211.0 | 51434 | 1.64041666667 | 14673 |
| 014943 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:18pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594549.2 | 512206.9 | 51436 | 1.64041666667 | 14943 |
| 014736 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:19pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594549.8 | 512203.6 | 51438 | 1.64041666667 | 14736 |
| 014086 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:20pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594550.7 | 512199.4 | 51440 | 1.64041666667 | 14086 |
| 015168 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:21pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594551.3 | 512196.0 | 51442 | 1.64041666667 | 15168 |
| 015229 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:22pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594552.0 | 512192.0 | 51444 | 1.64041666667 | 15229 |
| 015714 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:23pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594552.6 | 512188.8 | 51446 | 1.64041666667 | 15714 |
| 014284 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:24pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594553.1 | 512184.9 | 51448 | 1.64041666667 | 14284 |
| 013945 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:25pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594553.0 | 512181.5 | 51450 | 1.64041666667 | 13945 |
| 014586 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:26pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594553.0 | 512177.5 | 51452 | 1.64041666667 | 14586 |
| 014550 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:27pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594553.5 | 512173.8 | 51454 | 1.64041666667 | 14550 |
| 015061 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:28pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594553.8 | 512170.2 | 51456 | 1.64041666667 | 15061 |
| 014449 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:29pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594553.6 | 512167.3 | 51458 | 1.64041666667 | 14449 |
| 014330 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:30pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594553.4 | 512164.0 | 51460 | 1.64041666667 | 14330 |
| 014287 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:31pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594553.8 | 512160.7 | 51462 | 1.64041666667 | 14287 |
| 012974 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:32pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594553.8 | 512157.4 | 51464 | 1.64041666667 | 12974 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:33pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594552.5 | 512155.3 | 51466 | 1.64041666667 | 12975 |
| 013531 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:34pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594549.2 | 512154.5 | 51468 | 1.64041666667 | 13531 |
| 012666 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:35pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594546.6 | 512154.7 | 51470 | 1.64041666667 | 12666 |
| 013162 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:36pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594544.3 | 512156.8 | 51472 | 1.64041666667 | 13162 |
| 014603 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:37pm | Sensor | 1797-S0038-G-636-DTE | 6824.5 | 1594543.3 | 512159.6 | 51474 | 1.64041666667 | 14603 |
| 014807 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:38pm | Sensor | 1797-S0038-G-636-DTE | 6824.6 | 1594542.9 | 512163.5 | 51476 | 1.64041666667 | 14807 |
| 014404 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:39pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594543.0 | 512166.5 | 51478 | 1.64041666667 | 14404 |
| 014162 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:40pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594543.0 | 512170.2 | 51480 | 1.64041666667 | 14162 |
| 014708 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:41pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594542.8 | 512173.2 | 51482 | 1.64041666667 | 14708 |
| 014888 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:42pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594542.7 | 512176.9 | 51484 | 1.64041666667 | 14888 |
| 015049 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:43pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594542.3 | 512179.5 | 51486 | 1.64041666667 | 15049 |
| 014458 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:44pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594540.4 | 512182.3 | 51488 | 1.64041666667 | 14458 |
| 014357 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:45pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594538.6 | 512183.3 | 51490 | 1.64041666667 | 14357 |
| 014863 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:46pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594536.9 | 512184.1 | 51492 | 1.64041666667 | 14863 |
| 015073 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:47pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594536.4 | 512184.0 | 51494 | 1.64041666667 | 15073 |
| 015213 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:48pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594536.8 | 512184.0 | 51496 | 1.64041666667 | 15213 |
| 015465 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:49pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594537.7 | 512183.8 | 51498 | 1.64041666667 | 15465 |
| 014571 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:50pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594538.4 | 512183.0 | 51500 | 1.64041666667 | 14571 |
| 014181 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:51pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594538.5 | 512183.0 | 51502 | 1.64041666667 | 14181 |
| 014074 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:52pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594538.3 | 512183.0 | 51504 | 1.64041666667 | 14074 |
| 015094 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:53pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594538.4 | 512183.2 | 51506 | 1.64041666667 | 15094 |
| 013590 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:54pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594538.4 | 512183.2 | 51508 | 1.64041666667 | 13590 |
| 014664 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:55pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594538.4 | 512183.2 | 51510 | 1.64041666667 | 14664 |
| 014286 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:56pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594537.9 | 512183.9 | 51512 | 1.64041666667 | 14286 |
| 014433 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:57pm | Sensor | 1797-S0038-G-636-DTE | 6824.1 | 1594537.3 | 512184.7 | 51514 | 1.64041666667 | 14433 |
| 013781 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:58pm | Sensor | 1797-S0038-G-636-DTE | 6823.8 | 1594537.0 | 512185.0 | 51516 | 1.64041666667 | 13781 |
| 013662 | 0 | GeoXH 6000 | 08/19/2015 | 02:29:59pm | Sensor | 1797-S0038-G-636-DTE | 6824.3 | 1594537.3 | 512184.6 | 51518 | 1.64041666667 | 13662 |
| 013992 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:00pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594538.4 | 512184.2 | 51520 | 1.64041666667 | 13992 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014320 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:01pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594539.0 | 512185.7 | 51522 | 1.64041666667 | 14320 |
| 015285 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:02pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594539.1 | 512188.7 | 51524 | 1.64041666667 | 15285 |
| 014718 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:03pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594538.7 | 512192.4 | 51526 | 1.64041666667 | 14718 |
| 014586 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:04pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594538.5 | 512196.8 | 51528 | 1.64041666667 | 14586 |
| 014872 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:05pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594538.7 | 512200.3 | 51530 | 1.64041666667 | 14872 |
| 014620 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:06pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594539.0 | 512204.5 | 51532 | 1.64041666667 | 14620 |
| 014974 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:07pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594539.3 | 512209.1 | 51534 | 1.64041666667 | 14974 |
| 015607 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:08pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594539.7 | 512212.2 | 51536 | 1.64041666667 | 15607 |
| 015126 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:09pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594540.2 | 512215.3 | 51538 | 1.64041666667 | 15126 |
| 014434 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:10pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594541.0 | 512219.1 | 51540 | 1.64041666667 | 14434 |
| 013631 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:11pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594540.8 | 512223.0 | 51542 | 1.64041666667 | 13631 |
| 013765 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:12pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594540.2 | 512227.2 | 51544 | 1.64041666667 | 13765 |
| 013750 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:13pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594539.6 | 512230.4 | 51546 | 1.64041666667 | 13750 |
| 014214 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:14pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594539.2 | 512234.9 | 51548 | 1.64041666667 | 14214 |
| 014138 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:15pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594539.0 | 512238.5 | 51550 | 1.64041666667 | 14138 |
| 014695 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594538.8 | 512242.6 | 51552 | 1.64041666667 | 14695 |
| 013628 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:17pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594538.3 | 512244.8 | 51554 | 1.64041666667 | 13628 |
| 012533 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:18pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594535.4 | 512244.7 | 51556 | 1.64041666667 | 12533 |
| 012510 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:19pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594532.5 | 512243.9 | 51558 | 1.64041666667 | 12510 |
| 013262 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:20pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594529.8 | 512242.0 | 51560 | 1.64041666667 | 13262 |
| 012747 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:21pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594528.9 | 512239.2 | 51562 | 1.64041666667 | 12747 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:22pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594528.2 | 512235.4 | 51564 | 1.64041666667 | 13297 |
| 013442 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:23pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594528.0 | 512232.0 | 51566 | 1.64041666667 | 13442 |
| 012999 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:24pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594527.8 | 512227.9 | 51568 | 1.64041666667 | 12999 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:25pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594527.5 | 512224.7 | 51570 | 1.64041666667 | 13424 |
| 013791 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:26pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594527.6 | 512221.3 | 51572 | 1.64041666667 | 13791 |
| 014222 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:27pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594527.6 | 512217.8 | 51574 | 1.64041666667 | 14222 |
| 014352 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:28pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594527.8 | 512214.1 | 51576 | 1.64041666667 | 14352 |
| 014141 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:28pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594528.2 | 512211.0 | 51577 | 1.64041666667 | 14141 |
| 015041 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:30pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594528.4 | 512206.5 | 51580 | 1.64041666667 | 15041 |
| 015961 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:30pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594528.7 | 512203.6 | 51581 | 1.64041666667 | 15961 |
| 015450 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:32pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594528.9 | 512199.0 | 51584 | 1.64041666667 | 15450 |
| 014931 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:33pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594529.1 | 512195.8 | 51586 | 1.64041666667 | 14931 |
| 014841 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:34pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594529.7 | 512191.5 | 51588 | 1.64041666667 | 14841 |
| 015203 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:34pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594530.2 | 512188.4 | 51589 | 1.64041666667 | 15203 |
| 015706 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:36pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594530.8 | 512184.0 | 51592 | 1.64041666667 | 15706 |
| 015015 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:37pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594531.1 | 512181.0 | 51594 | 1.64041666667 | 15015 |
| 015691 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:38pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594531.7 | 512176.9 | 51596 | 1.64041666667 | 15691 |
| 015103 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:39pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594532.1 | 512173.7 | 51598 | 1.64041666667 | 15103 |
| 015298 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:40pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594532.4 | 512169.0 | 51600 | 1.64041666667 | 15298 |
| 014958 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:41pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594532.6 | 512166.0 | 51602 | 1.64041666667 | 14958 |
| 015006 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:42pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594533.5 | 512162.0 | 51604 | 1.64041666667 | 15006 |
| 014966 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:43pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594534.2 | 512159.6 | 51606 | 1.64041666667 | 14966 |
| 014418 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:44pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594533.6 | 512156.1 | 51608 | 1.64041666667 | 14418 |
| 015100 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:45pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594532.6 | 512154.5 | 51610 | 1.64041666667 | 15100 |
| 015243 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:46pm | Sensor | 1797-S0038-G-636-DTE | 6824.7 | 1594529.9 | 512154.2 | 51612 | 1.64041666667 | 15243 |
| 014559 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:47pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594527.7 | 512154.8 | 51614 | 1.64041666667 | 14559 |
| 014745 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:48pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594525.6 | 512158.3 | 51616 | 1.64041666667 | 14745 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014451 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:49pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594525.3 | 512161.4 | 51618 | 1.64041666667 | 14451 |
| 014549 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:50pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594524.6 | 512165.8 | 51620 | 1.64041666667 | 14549 |
| 014821 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:51pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594524.3 | 512168.7 | 51622 | 1.64041666667 | 14821 |
| 014704 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:52pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594524.5 | 512172.8 | 51624 | 1.64041666667 | 14704 |
| 014968 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:53pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594524.9 | 512175.5 | 51626 | 1.64041666667 | 14968 |
| 014360 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:54pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594524.9 | 512179.1 | 51628 | 1.64041666667 | 14360 |
| 014827 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:55pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594524.8 | 512182.1 | 51630 | 1.64041666667 | 14827 |
| 015097 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:56pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594525.5 | 512186.2 | 51632 | 1.64041666667 | 15097 |
| 014927 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:57pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594525.7 | 512189.3 | 51634 | 1.64041666667 | 14927 |
| 015079 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:58pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594525.5 | 512193.6 | 51636 | 1.64041666667 | 15079 |
| 015127 | 0 | GeoXH 6000 | 08/19/2015 | 02:30:59pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594525.3 | 512196.5 | 51638 | 1.64041666667 | 15127 |
| 015506 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:00pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594525.3 | 512200.0 | 51640 | 1.64041666667 | 15506 |
| 014872 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:01pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594524.9 | 512203.7 | 51642 | 1.64041666667 | 14872 |
| 014943 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:02pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594523.8 | 512207.6 | 51644 | 1.64041666667 | 14943 |
| 014825 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:02pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594522.7 | 512210.6 | 51645 | 1.64041666667 | 14825 |
| 014932 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:04pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594522.5 | 512215.3 | 51648 | 1.64041666667 | 14932 |
| 014189 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:05pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594522.6 | 512218.8 | 51650 | 1.64041666667 | 14189 |
| 014378 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:06pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594522.1 | 512223.2 | 51652 | 1.64041666667 | 14378 |
| 013735 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:07pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594521.7 | 512226.5 | 51654 | 1.64041666667 | 13735 |
| 013688 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:08pm | Sensor | 1797-S0038-G-636-DTE | 6825.4 | 1594521.6 | 512230.6 | 51656 | 1.64041666667 | 13688 |
| 014172 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:09pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594521.3 | 512233.4 | 51658 | 1.64041666667 | 14172 |
| 014444 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:10pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594520.6 | 512234.9 | 51660 | 1.64041666667 | 14444 |
| 014260 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:11pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594519.7 | 512235.1 | 51662 | 1.64041666667 | 14260 |
| 014673 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:12pm | Sensor | 1797-S0038-G-636-DTE | 6825.6 | 1594517.4 | 512233.3 | 51664 | 1.64041666667 | 14673 |
| 014224 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:13pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594516.0 | 512231.1 | 51666 | 1.64041666667 | 14224 |
| 013828 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:14pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594514.8 | 512228.2 | 51668 | 1.64041666667 | 13828 |
| 014386 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:15pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594514.5 | 512226.0 | 51670 | 1.64041666667 | 14386 |
| 014339 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.7 | 1594515.4 | 512223.4 | 51672 | 1.64041666667 | 14339 |
| 014523 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594515.8 | 512221.2 | 51673 | 1.64041666667 | 14523 |
| 015047 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:18pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594516.2 | 512217.9 | 51676 | 1.64041666667 | 15047 |
| 014253 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:19pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594517.1 | 512215.1 | 51678 | 1.64041666667 | 14253 |
| 014655 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:20pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594517.7 | 512210.9 | 51680 | 1.64041666667 | 14655 |
| 013726 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:21pm | Sensor | 1797-S0038-G-636-DTE | 6825.5 | 1594517.4 | 512207.9 | 51682 | 1.64041666667 | 13726 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:22pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594517.2 | 512204.2 | 51684 | 1.64041666667 | 13811 |
| 014301 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:23pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594517.3 | 512201.2 | 51686 | 1.64041666667 | 14301 |
| 014119 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:24pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594516.9 | 512197.7 | 51688 | 1.64041666667 | 14119 |
| 014414 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:25pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594516.8 | 512195.1 | 51690 | 1.64041666667 | 14414 |
| 014130 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:26pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594517.1 | 512191.1 | 51692 | 1.64041666667 | 14130 |
| 014646 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:27pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594517.0 | 512187.8 | 51694 | 1.64041666667 | 14646 |
| 014373 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:28pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594516.3 | 512184.0 | 51696 | 1.64041666667 | 14373 |
| 014160 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:29pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594516.3 | 512180.8 | 51698 | 1.64041666667 | 14160 |
| 014115 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:30pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594516.8 | 512176.9 | 51700 | 1.64041666667 | 14115 |
| 014554 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:31pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594517.0 | 512173.2 | 51702 | 1.64041666667 | 14554 |
| 014667 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:32pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594516.7 | 512169.6 | 51704 | 1.64041666667 | 14667 |
| 015615 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:33pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594516.6 | 512166.9 | 51706 | 1.64041666667 | 15615 |
| 015661 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:34pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594517.4 | 512164.0 | 51708 | 1.64041666667 | 15661 |
| 015214 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:35pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594517.9 | 512160.6 | 51710 | 1.64041666667 | 15214 |
| 014625 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:36pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594517.8 | 512157.2 | 51712 | 1.64041666667 | 14625 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014654 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:37pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594518.1 | 512153.8 | 51714 | 1.64041666667 | 14654 |
| 013380 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:38pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594517.7 | 512151.3 | 51716 | 1.64041666667 | 13380 |
| 013474 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:39pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594516.0 | 512151.2 | 51718 | 1.64041666667 | 13474 |
| 015169 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:40pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594512.8 | 512152.0 | 51720 | 1.64041666667 | 15169 |
| 014832 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:41pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594510.2 | 512154.5 | 51722 | 1.64041666667 | 14832 |
| 015213 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:42pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594509.2 | 512157.9 | 51724 | 1.64041666667 | 15213 |
| 014677 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:43pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594508.9 | 512161.6 | 51726 | 1.64041666667 | 14677 |
| 015711 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:44pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594508.9 | 512165.6 | 51728 | 1.64041666667 | 15711 |
| 015782 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:45pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594509.7 | 512168.9 | 51730 | 1.64041666667 | 15782 |
| 016205 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:46pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594510.3 | 512172.7 | 51732 | 1.64041666667 | 16205 |
| 015940 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:47pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594510.4 | 512176.0 | 51734 | 1.64041666667 | 15940 |
| 015131 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:48pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594510.2 | 512179.8 | 51736 | 1.64041666667 | 15131 |
| 014534 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:49pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594510.0 | 512183.3 | 51738 | 1.64041666667 | 14534 |
| 014887 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:50pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594510.1 | 512186.5 | 51740 | 1.64041666667 | 14887 |
| 015386 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:51pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594509.6 | 512190.0 | 51742 | 1.64041666667 | 15386 |
| 014685 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:52pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594508.8 | 512193.4 | 51744 | 1.64041666667 | 14685 |
| 015670 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:53pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594508.7 | 512196.3 | 51746 | 1.64041666667 | 15670 |
| 015954 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:54pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594508.2 | 512198.4 | 51748 | 1.64041666667 | 15954 |
| 016422 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:55pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594506.2 | 512199.0 | 51750 | 1.64041666667 | 16422 |
| 015177 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:56pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594503.8 | 512198.2 | 51752 | 1.64041666667 | 15177 |
| 014769 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:57pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594501.5 | 512196.5 | 51754 | 1.64041666667 | 14769 |
| 014360 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:58pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594501.2 | 512193.8 | 51756 | 1.64041666667 | 14360 |
| 013522 | 0 | GeoXH 6000 | 08/19/2015 | 02:31:58pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594501.6 | 512190.8 | 51757 | 1.64041666667 | 13522 |
| 013914 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:00pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594501.8 | 512186.6 | 51760 | 1.64041666667 | 13914 |
| 0144 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:01pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594502.3 | 512183.4 | 51762 | 1.64041666667 | 144 |
| 014205 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:02pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594503.0 | 512180.0 | 51764 | 1.64041666667 | 14205 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:03pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594503.1 | 512177.6 | 51766 | 1.64041666667 | 13811 |
| 014458 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:04pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594503.2 | 512173.7 | 51768 | 1.64041666667 | 14458 |
| 014260 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:05pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594503.4 | 512170.2 | 51770 | 1.64041666667 | 14260 |
| 014314 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:06pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594503.0 | 512166.2 | 51772 | 1.64041666667 | 14314 |
| 015634 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:07pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594502.5 | 512163.1 | 51774 | 1.64041666667 | 15634 |
| 015409 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:08pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594502.4 | 512158.9 | 51776 | 1.64041666667 | 15409 |
| 014827 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:09pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594502.9 | 512156.3 | 51778 | 1.64041666667 | 14827 |
| 014323 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:10pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594503.5 | 512153.6 | 51780 | 1.64041666667 | 14323 |
| 013734 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:11pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594503.0 | 512151.6 | 51782 | 1.64041666667 | 13734 |
| 014265 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:12pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594500.5 | 512151.5 | 51784 | 1.64041666667 | 14265 |
| 014227 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:13pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594498.1 | 512152.6 | 51786 | 1.64041666667 | 14227 |
| 014730 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:14pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594497.2 | 512156.1 | 51788 | 1.64041666667 | 14730 |
| 015755 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:15pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594497.2 | 512158.1 | 51790 | 1.64041666667 | 15755 |
| 015207 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:16pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594495.8 | 512162.0 | 51792 | 1.64041666667 | 15207 |
| 014876 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:17pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594495.0 | 512165.2 | 51794 | 1.64041666667 | 14876 |
| 014338 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:18pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594494.7 | 512168.8 | 51796 | 1.64041666667 | 14338 |
| 014170 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:19pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594494.6 | 512171.8 | 51798 | 1.64041666667 | 14170 |
| 014173 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:20pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594494.1 | 512175.6 | 51800 | 1.64041666667 | 14173 |
| 013792 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:21pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594493.5 | 512178.7 | 51802 | 1.64041666667 | 13792 |
| 013983 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:22pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594493.2 | 512182.2 | 51804 | 1.64041666667 | 13983 |
| 014473 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:23pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594493.1 | 512184.7 | 51806 | 1.64041666667 | 14473 |
| 016068 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:24pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594492.2 | 512188.0 | 51808 | 1.64041666667 | 16068 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015076 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:24pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594491.8 | 512190.2 | 51809 | 1.64041666667 | 15076 |
| 013992 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:26pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594492.0 | 512192.0 | 51812 | 1.64041666667 | 13992 |
| 014268 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:27pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594492.1 | 512193.0 | 51814 | 1.64041666667 | 14268 |
| 014506 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:28pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594493.2 | 512190.6 | 51816 | 1.64041666667 | 14506 |
| 014849 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:29pm | Sensor | 1797-S0038-G-636-DTE | 6825.3 | 1594493.6 | 512187.2 | 51818 | 1.64041666667 | 14849 |
| 015073 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:30pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594494.5 | 512183.1 | 51820 | 1.64041666667 | 15073 |
| 014718 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:31pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594495.4 | 512179.7 | 51822 | 1.64041666667 | 14718 |
| 015111 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:32pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594496.5 | 512175.0 | 51824 | 1.64041666667 | 15111 |
| 015662 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:33pm | Sensor | 1797-S0038-G-636-DTE | 6825.0 | 1594497.6 | 512171.2 | 51826 | 1.64041666667 | 15662 |
| 014487 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:34pm | Sensor | 1797-S0038-G-636-DTE | 6825.1 | 1594498.4 | 512167.0 | 51828 | 1.64041666667 | 14487 |
| 013834 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:35pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594499.0 | 512163.0 | 51830 | 1.64041666667 | 13834 |
| 013819 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:36pm | Sensor | 1797-S0038-G-636-DTE | 6824.8 | 1594499.9 | 512158.9 | 51832 | 1.64041666667 | 13819 |
| 014493 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:37pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594501.2 | 512156.0 | 51834 | 1.64041666667 | 14493 |
| 013770 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:38pm | Sensor | 1797-S0038-G-636-DTE | 6824.9 | 1594502.8 | 512151.9 | 51836 | 1.64041666667 | 13770 |
| 014645 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:39pm | Sensor | 1797-S0038-G-636-DTE | 6825.2 | 1594503.2 | 512148.6 | 51838 | 1.64041666667 | 14645 |
| 015333 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:40pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594503.6 | 512147.0 | 51840 | 1.64041666667 | 15333 |
| 014475 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:40pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594505.3 | 512146.1 | 51841 | 1.64041666667 | 14475 |
| 013414 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:42pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594509.7 | 512144.8 | 51844 | 1.64041666667 | 13414 |
| 013140 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:42pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594512.9 | 512143.9 | 51845 | 1.64041666667 | 13140 |
| 013151 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:44pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594517.8 | 512143.6 | 51848 | 1.64041666667 | 13151 |
| 013277 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:45pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594521.1 | 512143.9 | 51850 | 1.64041666667 | 13277 |
| 014106 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:46pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594525.0 | 512144.4 | 51852 | 1.64041666667 | 14106 |
| 013890 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:46pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594528.1 | 512144.1 | 51853 | 1.64041666667 | 13890 |
| 013693 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:48pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594533.1 | 512143.9 | 51856 | 1.64041666667 | 13693 |
| 014234 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:48pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594535.7 | 512144.0 | 51857 | 1.64041666667 | 14234 |
| 014434 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:50pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594540.5 | 512143.7 | 51860 | 1.64041666667 | 14434 |
| 014111 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:51pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594544.0 | 512143.3 | 51862 | 1.64041666667 | 14111 |
| 014058 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:52pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594548.0 | 512143.6 | 51864 | 1.64041666667 | 14058 |
| 014920 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:52pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594550.9 | 512143.9 | 51865 | 1.64041666667 | 14920 |
| 014662 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:54pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594555.2 | 512143.5 | 51868 | 1.64041666667 | 14662 |
| 014142 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:54pm | Sensor | 1797-S0038-G-636-DTE | 6826.7 | 1594558.1 | 512142.9 | 51869 | 1.64041666667 | 14142 |
| 013880 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:56pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594562.3 | 512142.6 | 51872 | 1.64041666667 | 13880 |
| 014647 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:56pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594565.5 | 512142.5 | 51873 | 1.64041666667 | 14647 |
| 014464 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:58pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594569.5 | 512142.1 | 51876 | 1.64041666667 | 14464 |
| 014398 | 0 | GeoXH 6000 | 08/19/2015 | 02:32:58pm | Sensor | 1797-S0038-G-636-DTE | 6826.7 | 1594572.5 | 512141.7 | 51877 | 1.64041666667 | 14398 |
| 014939 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:00pm | Sensor | 1797-S0038-G-636-DTE | 6826.6 | 1594576.8 | 512141.3 | 51880 | 1.64041666667 | 14939 |
| 015333 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:00pm | Sensor | 1797-S0038-G-636-DTE | 6826.8 | 1594579.1 | 512140.6 | 51881 | 1.64041666667 | 15333 |
| 014445 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:02pm | Sensor | 1797-S0038-G-636-DTE | 6827.0 | 1594580.4 | 512137.6 | 51884 | 1.64041666667 | 14445 |
| 014395 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:03pm | Sensor | 1797-S0038-G-636-DTE | 6826.9 | 1594580.5 | 512134.5 | 51886 | 1.64041666667 | 14395 |
| 014967 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:04pm | Sensor | 1797-S0038-G-636-DTE | 6826.8 | 1594577.0 | 512132.6 | 51888 | 1.64041666667 | 14967 |
| 014929 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:05pm | Sensor | 1797-S0038-G-636-DTE | 6826.8 | 1594573.6 | 512133.1 | 51890 | 1.64041666667 | 14929 |
| 014667 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:06pm | Sensor | 1797-S0038-G-636-DTE | 6826.6 | 1594569.8 | 512133.5 | 51892 | 1.64041666667 | 14667 |
| 015083 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:07pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594566.3 | 512133.7 | 51894 | 1.64041666667 | 15083 |
| 014679 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:08pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594561.3 | 512134.4 | 51896 | 1.64041666667 | 14679 |
| 014219 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:09pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594557.3 | 512135.0 | 51898 | 1.64041666667 | 14219 |
| 014883 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:10pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594552.7 | 512135.7 | 51900 | 1.64041666667 | 14883 |
| 015767 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:11pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594548.8 | 512135.8 | 51902 | 1.64041666667 | 15767 |
| 015566 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:12pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594544.5 | 512135.5 | 51904 | 1.64041666667 | 15566 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014673 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:13pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594541.2 | 512135.4 | 51906 | 1.64041666667 | 14673 |
| 016406 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:14pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594536.7 | 512135.3 | 51908 | 1.64041666667 | 16406 |
| 015746 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:15pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594533.4 | 512135.4 | 51910 | 1.64041666667 | 15746 |
| 015292 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:16pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594529.8 | 512135.1 | 51912 | 1.64041666667 | 15292 |
| 014324 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:17pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594526.7 | 512134.8 | 51914 | 1.64041666667 | 14324 |
| 014192 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:18pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594522.6 | 512135.5 | 51916 | 1.64041666667 | 14192 |
| 014628 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:19pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594519.8 | 512135.8 | 51918 | 1.64041666667 | 14628 |
| 015053 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:20pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594517.2 | 512133.5 | 51920 | 1.64041666667 | 15053 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:21pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594516.7 | 512131.0 | 51922 | 1.64041666667 | 14602 |
| 014071 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:22pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594518.4 | 512128.3 | 51924 | 1.64041666667 | 14071 |
| 013555 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:22pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594520.7 | 512127.3 | 51925 | 1.64041666667 | 13555 |
| 013872 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:24pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594525.2 | 512126.8 | 51928 | 1.64041666667 | 13872 |
| 013953 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:25pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594528.3 | 512126.0 | 51930 | 1.64041666667 | 13953 |
| 013721 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:26pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594532.0 | 512125.1 | 51932 | 1.64041666667 | 13721 |
| 013335 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:27pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594534.9 | 512125.3 | 51934 | 1.64041666667 | 13335 |
| 014018 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:28pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594539.4 | 512125.5 | 51936 | 1.64041666667 | 14018 |
| 014980 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:29pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594541.6 | 512125.2 | 51938 | 1.64041666667 | 14980 |
| 014224 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:30pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594544.9 | 512124.2 | 51940 | 1.64041666667 | 14224 |
| 014346 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:31pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594548.0 | 512123.2 | 51942 | 1.64041666667 | 14346 |
| 014219 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:32pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594550.0 | 512121.0 | 51944 | 1.64041666667 | 14219 |
| 015101 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:33pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594549.4 | 512118.7 | 51946 | 1.64041666667 | 15101 |
| 015416 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:34pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594546.1 | 512116.9 | 51948 | 1.64041666667 | 15416 |
| 014432 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:34pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594543.2 | 512116.4 | 51949 | 1.64041666667 | 14432 |
| 014980 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:36pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594539.5 | 512117.3 | 51952 | 1.64041666667 | 14980 |
| 014629 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:36pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594536.0 | 512117.4 | 51953 | 1.64041666667 | 14629 |
| 014401 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:37pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594532.6 | 512117.0 | 51955 | 1.64041666667 | 14401 |
| 014333 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:38pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594528.9 | 512116.9 | 51957 | 1.64041666667 | 14333 |
| 014077 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:39pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594525.6 | 512117.7 | 51959 | 1.64041666667 | 14077 |
| 013168 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:40pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594521.8 | 512118.0 | 51961 | 1.64041666667 | 13168 |
| 013594 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:42pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594518.1 | 512118.0 | 51964 | 1.64041666667 | 13594 |
| 014419 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:42pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594515.4 | 512119.0 | 51965 | 1.64041666667 | 14419 |
| 013788 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:44pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594512.4 | 512121.8 | 51968 | 1.64041666667 | 13788 |
| 013823 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:45pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594511.2 | 512125.1 | 51970 | 1.64041666667 | 13823 |
| 014105 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:46pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594510.9 | 512128.4 | 51972 | 1.64041666667 | 14105 |
| 014009 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:46pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594511.6 | 512130.8 | 51973 | 1.64041666667 | 14009 |
| 013737 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:48pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594512.4 | 512134.4 | 51976 | 1.64041666667 | 13737 |
| 014612 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:49pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594512.4 | 512137.8 | 51978 | 1.64041666667 | 14612 |
| 014707 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:50pm | Sensor | 1797-S0038-G-636-DTE | 6826.1 | 1594512.3 | 512140.0 | 51980 | 1.64041666667 | 14707 |
| 014092 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:51pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594512.4 | 512141.4 | 51982 | 1.64041666667 | 14092 |
| 013274 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:52pm | Sensor | 1797-S0038-G-636-DTE | 6825.9 | 1594512.0 | 512142.9 | 51984 | 1.64041666667 | 13274 |
| 013437 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:52pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594513.9 | 512143.2 | 51985 | 1.64041666667 | 13437 |
| 013415 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:54pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594518.3 | 512143.6 | 51988 | 1.64041666667 | 13415 |
| 013314 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:55pm | Sensor | 1797-S0038-G-636-DTE | 6825.8 | 1594522.3 | 512143.8 | 51990 | 1.64041666667 | 13314 |
| 013286 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:56pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594525.9 | 512143.8 | 51992 | 1.64041666667 | 13286 |
| 013578 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:57pm | Sensor | 1797-S0038-G-636-DTE | 6826.0 | 1594529.9 | 512143.5 | 51994 | 1.64041666667 | 13578 |
| 013923 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:58pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594534.1 | 512143.0 | 51996 | 1.64041666667 | 13923 |
| 014162 | 0 | GeoXH 6000 | 08/19/2015 | 02:33:59pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594538.3 | 512142.5 | 51998 | 1.64041666667 | 14162 |
| 013982 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:00pm | Sensor | 1797-S0038-G-636-DTE | 6826.2 | 1594542.5 | 512142.3 | 52000 | 1.64041666667 | 13982 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014015 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:00pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594545.7 | 512142.0 | 52001 | 1.64041666667 | 14015 |
| 014873 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:02pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594550.5 | 512141.6 | 52004 | 1.64041666667 | 14873 |
| 014778 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:03pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594553.9 | 512141.4 | 52006 | 1.64041666667 | 14778 |
| 014665 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:04pm | Sensor | 1797-S0038-G-636-DTE | 6826.5 | 1594558.4 | 512141.5 | 52008 | 1.64041666667 | 14665 |
| 014729 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:04pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594561.8 | 512141.7 | 52009 | 1.64041666667 | 14729 |
| 015800 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:06pm | Sensor | 1797-S0038-G-636-DTE | 6826.4 | 1594566.4 | 512142.0 | 52012 | 1.64041666667 | 15800 |
| 015412 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:07pm | Sensor | 1797-S0038-G-636-DTE | 6826.3 | 1594570.5 | 512142.1 | 52014 | 1.64041666667 | 15412 |
| 014752 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:08pm | Sensor | 1797-S0038-G-636-DTE | 6826.6 | 1594574.3 | 512141.6 | 52016 | 1.64041666667 | 14752 |
| 014440 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:08pm | Sensor | 1797-S0038-G-636-DTE | 6826.6 | 1594578.2 | 512141.7 | 52017 | 1.64041666667 | 14440 |
| 014572 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:10pm | Sensor | 1797-S0038-G-636-DTE | 6826.7 | 1594582.3 | 512142.3 | 52020 | 1.64041666667 | 14572 |
| 014647 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:10pm | Sensor | 1797-S0038-G-636-DTE | 6826.8 | 1594585.2 | 512142.5 | 52021 | 1.64041666667 | 14647 |
| 013856 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:12pm | Sensor | 1797-S0038-G-636-DTE | 6826.8 | 1594588.9 | 512142.8 | 52024 | 1.64041666667 | 13856 |
| 014086 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:12pm | Sensor | 1797-S0038-G-636-DTE | 6826.9 | 1594591.2 | 512143.7 | 52025 | 1.64041666667 | 14086 |
| 014418 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:13pm | Sensor | 1797-S0038-G-636-DTE | 6826.7 | 1594592.2 | 512147.2 | 52027 | 1.64041666667 | 14418 |
| 013870 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:14pm | Sensor | 1797-S0038-G-636-DTE | 6826.9 | 1594592.7 | 512151.0 | 52029 | 1.64041666667 | 13870 |
| 014327 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:15pm | Sensor | 1797-S0038-G-636-DTE | 6827.0 | 1594592.9 | 512155.5 | 52031 | 1.64041666667 | 14327 |
| 013594 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:16pm | Sensor | 1797-S0038-G-636-DTE | 6827.1 | 1594593.5 | 512159.7 | 52033 | 1.64041666667 | 13594 |
| 013886 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:18pm | Sensor | 1797-S0038-G-636-DTE | 6827.6 | 1594594.4 | 512163.8 | 52036 | 1.64041666667 | 13886 |
| 013646 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:18pm | Sensor | 1797-S0038-G-636-DTE | 6827.4 | 1594594.4 | 512167.1 | 52037 | 1.64041666667 | 13646 |
| 013181 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:20pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594594.3 | 512171.9 | 52040 | 1.64041666667 | 13181 |
| 014366 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:20pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594593.9 | 512175.1 | 52041 | 1.64041666667 | 14366 |
| 013818 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:22pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594593.7 | 512179.4 | 52044 | 1.64041666667 | 13818 |
| 014485 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:22pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594593.1 | 512183.2 | 52045 | 1.64041666667 | 14485 |
| 013690 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:24pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594592.5 | 512187.3 | 52048 | 1.64041666667 | 13690 |
| 015006 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:24pm | Sensor | 1797-S0038-G-636-DTE | 6827.4 | 1594592.2 | 512191.1 | 52049 | 1.64041666667 | 15006 |
| 013856 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:25pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594592.3 | 512195.1 | 52051 | 1.64041666667 | 13856 |
| 013306 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:26pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594592.4 | 512198.5 | 52053 | 1.64041666667 | 13306 |
| 013117 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:27pm | Sensor | 1797-S0038-G-636-DTE | 6827.4 | 1594591.8 | 512201.9 | 52055 | 1.64041666667 | 13117 |
| 013423 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:28pm | Sensor | 1797-S0038-G-636-DTE | 6827.4 | 1594591.2 | 512205.2 | 52057 | 1.64041666667 | 13423 |
| 013175 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:29pm | Sensor | 1797-S0038-G-636-DTE | 6827.6 | 1594591.4 | 512208.3 | 52059 | 1.64041666667 | 13175 |
| 013321 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:30pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594591.2 | 512211.1 | 52061 | 1.64041666667 | 13321 |
| 014903 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:32pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594593.0 | 512214.7 | 52064 | 1.64041666667 | 14903 |
| 014600 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:32pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594596.0 | 512214.0 | 52065 | 1.64041666667 | 14600 |
| 014407 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:33pm | Sensor | 1797-S0038-G-636-DTE | 6827.7 | 1594598.2 | 512211.2 | 52067 | 1.64041666667 | 14407 |
| 014104 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:34pm | Sensor | 1797-S0038-G-636-DTE | 6828.1 | 1594599.6 | 512207.9 | 52069 | 1.64041666667 | 14104 |
| 013873 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:36pm | Sensor | 1797-S0038-G-636-DTE | 6827.9 | 1594601.5 | 512203.4 | 52072 | 1.64041666667 | 13873 |
| 013361 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:36pm | Sensor | 1797-S0038-G-636-DTE | 6828.0 | 1594602.5 | 512200.2 | 52073 | 1.64041666667 | 13361 |
| 013793 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:38pm | Sensor | 1797-S0038-G-636-DTE | 6827.8 | 1594602.9 | 512195.3 | 52076 | 1.64041666667 | 13793 |
| 013466 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:38pm | Sensor | 1797-S0038-G-636-DTE | 6827.9 | 1594603.0 | 512192.5 | 52077 | 1.64041666667 | 13466 |
| 013395 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:40pm | Sensor | 1797-S0038-G-636-DTE | 6827.8 | 1594603.4 | 512187.5 | 52080 | 1.64041666667 | 13395 |
| 014037 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:40pm | Sensor | 1797-S0038-G-636-DTE | 6827.9 | 1594603.5 | 512184.7 | 52081 | 1.64041666667 | 14037 |
| 013948 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:42pm | Sensor | 1797-S0038-G-636-DTE | 6827.8 | 1594603.6 | 512180.3 | 52084 | 1.64041666667 | 13948 |
| 013081 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:43pm | Sensor | 1797-S0038-G-636-DTE | 6828.0 | 1594603.7 | 512177.2 | 52086 | 1.64041666667 | 13081 |
| 012488 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:44pm | Sensor | 1797-S0038-G-636-DTE | 6827.8 | 1594603.9 | 512173.0 | 52088 | 1.64041666667 | 12488 |
| 013857 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:44pm | Sensor | 1797-S0038-G-636-DTE | 6827.9 | 1594604.1 | 512170.0 | 52089 | 1.64041666667 | 13857 |
| 013952 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:46pm | Sensor | 1797-S0038-G-636-DTE | 6827.8 | 1594603.9 | 512166.7 | 52092 | 1.64041666667 | 13952 |
| 013660 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:47pm | Sensor | 1797-S0038-G-636-DTE | 6827.9 | 1594603.8 | 512163.4 | 52094 | 1.64041666667 | 13660 |
| 014576 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:48pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594604.8 | 512160.2 | 52096 | 1.64041666667 | 14576 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013801 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:49pm | Sensor | 1797-S0038-G-636-DTE | 6827.5 | 1594605.4 | 512157.4 | 52098 | 1.64041666667 | 13801 |
| 014026 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:50pm | Sensor | 1797-S0038-G-636-DTE | 6827.4 | 1594605.1 | 512154.8 | 52100 | 1.64041666667 | 14026 |
| 013874 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:51pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594605.4 | 512153.1 | 52102 | 1.64041666667 | 13874 |
| 013977 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:52pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594605.3 | 512153.1 | 52104 | 1.64041666667 | 13977 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:53pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594605.3 | 512153.0 | 52106 | 1.64041666667 | 12917 |
| 013453 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:54pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594605.2 | 512153.0 | 52108 | 1.64041666667 | 13453 |
| 013125 | 0 | GeoXH 6000 | 08/19/2015 | 02:34:54pm | Sensor | 1797-S0038-G-636-DTE | 6827.3 | 1594605.3 | 512152.9 | 52109 | 1.64041666667 | 13125 |
| 010807 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:11am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.0 | 510982.9 | 47232 | 1.64041666667 | 10807 |
| 010421 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:12am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.1 | 510982.9 | 47235 | 1.64041666667 | 10421 |
| 010842 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:13am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.3 | 510982.8 | 47237 | 1.64041666667 | 10842 |
| 010238 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:14am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.4 | 510982.8 | 47239 | 1.64041666667 | 10238 |
| 010754 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:15am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.4 | 510982.9 | 47241 | 1.64041666667 | 10754 |
| 011501 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:16am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.5 | 510982.9 | 47243 | 1.64041666667 | 11501 |
| 011059 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:17am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.5 | 510982.9 | 47245 | 1.64041666667 | 11059 |
| 010323 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:18am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.5 | 510982.8 | 47247 | 1.64041666667 | 10323 |
| 010239 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:19am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.5 | 510982.8 | 47249 | 1.64041666667 | 10239 |
| 010079 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:20am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.3 | 510982.2 | 47251 | 1.64041666667 | 10079 |
| 010575 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:21am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.2 | 510981.8 | 47253 | 1.64041666667 | 10575 |
| 010103 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:22am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.1 | 510982.5 | 47255 | 1.64041666667 | 10103 |
| 010055 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:23am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595097.7 | 510984.5 | 47257 | 1.64041666667 | 10055 |
| 010786 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:24am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595097.5 | 510987.4 | 47259 | 1.64041666667 | 10786 |
| 010814 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:25am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.1 | 510990.0 | 47261 | 1.64041666667 | 10814 |
| 011723 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:26am | Sensor | 1797-S0037-905-G-ACK | 6825.3 | 1595098.8 | 510993.2 | 47263 | 1.64041666667 | 11723 |
| 012594 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:27am | Sensor | 1797-S0037-905-G-ACK | 6825.2 | 1595098.8 | 510996.0 | 47265 | 1.64041666667 | 12594 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:28am | Sensor | 1797-S0037-905-G-ACK | 6825.2 | 1595098.4 | 510999.6 | 47267 | 1.64041666667 | 12521 |
| 012173 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:29am | Sensor | 1797-S0037-905-G-ACK | 6825.2 | 1595098.4 | 511003.0 | 47269 | 1.64041666667 | 12173 |
| 011955 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:30am | Sensor | 1797-S0037-905-G-ACK | 6825.1 | 1595098.8 | 511006.7 | 47271 | 1.64041666667 | 11955 |
| 012477 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:31am | Sensor | 1797-S0037-905-G-ACK | 6825.1 | 1595099.1 | 511010.2 | 47273 | 1.64041666667 | 12477 |
| 011946 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:32am | Sensor | 1797-S0037-905-G-ACK | 6825.0 | 1595099.5 | 511013.8 | 47275 | 1.64041666667 | 11946 |
| 012532 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:33am | Sensor | 1797-S0037-905-G-ACK | 6825.0 | 1595099.6 | 511017.0 | 47277 | 1.64041666667 | 12532 |
| 013064 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:34am | Sensor | 1797-S0037-905-G-ACK | 6825.0 | 1595099.4 | 511020.3 | 47279 | 1.64041666667 | 13064 |
| 013213 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:35am | Sensor | 1797-S0037-905-G-ACK | 6825.1 | 1595099.5 | 511022.4 | 47281 | 1.64041666667 | 13213 |
| 013755 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:36am | Sensor | 1797-S0037-905-G-ACK | 6825.0 | 1595099.6 | 511024.8 | 47283 | 1.64041666667 | 13755 |
| 013496 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:37am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.4 | 511026.8 | 47285 | 1.64041666667 | 13496 |
| 014272 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:38am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.2 | 511028.2 | 47287 | 1.64041666667 | 14272 |
| 015018 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:39am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.5 | 47289 | 1.64041666667 | 15018 |
| 015272 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:40am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.5 | 47291 | 1.64041666667 | 15272 |
| 013863 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:41am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.5 | 47293 | 1.64041666667 | 13863 |
| 013205 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:42am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.5 | 47295 | 1.64041666667 | 13205 |
| 013570 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:43am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.5 | 47297 | 1.64041666667 | 13570 |
| 013153 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:44am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.2 | 511028.5 | 47299 | 1.64041666667 | 13153 |
| 013848 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:45am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.5 | 47301 | 1.64041666667 | 13848 |
| 014255 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:46am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.5 | 47303 | 1.64041666667 | 14255 |
| 013958 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:47am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.6 | 47305 | 1.64041666667 | 13958 |
| 013604 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:48am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.6 | 47307 | 1.64041666667 | 13604 |
| 014222 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:49am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.6 | 47309 | 1.64041666667 | 14222 |
| 013767 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:50am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.6 | 47311 | 1.64041666667 | 13767 |
| 014951 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:51am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.5 | 47313 | 1.64041666667 | 14951 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014740 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:52am | Sensor | 1797-S0037-905-G-ACK | 6824.8 | 1595099.1 | 511028.8 | 47315 | 1.64041666667 | 14740 |
| 015168 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:53am | Sensor | 1797-S0037-905-G-ACK | 6824.7 | 1595099.6 | 511029.8 | 47317 | 1.64041666667 | 15168 |
| 014720 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:54am | Sensor | 1797-S0037-905-G-ACK | 6824.7 | 1595100.5 | 511032.0 | 47319 | 1.64041666667 | 14720 |
| 013440 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:55am | Sensor | 1797-S0037-905-G-ACK | 6824.7 | 1595100.8 | 511034.6 | 47321 | 1.64041666667 | 13440 |
| 013620 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:56am | Sensor | 1797-S0037-905-G-ACK | 6824.4 | 1595101.1 | 511037.7 | 47323 | 1.64041666667 | 13620 |
| 013503 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:57am | Sensor | 1797-S0037-905-G-ACK | 6824.3 | 1595101.7 | 511040.1 | 47325 | 1.64041666667 | 13503 |
| 012861 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:58am | Sensor | 1797-S0037-905-G-ACK | 6824.0 | 1595102.4 | 511043.4 | 47327 | 1.64041666667 | 12861 |
| 012596 | 0 | GeoXH 6000 | 08/19/2015 | 11:25:59am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595103.0 | 511046.3 | 47329 | 1.64041666667 | 12596 |
| 011803 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:00am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595103.6 | 511049.8 | 47331 | 1.64041666667 | 11803 |
| 012721 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:01am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595104.3 | 511052.7 | 47333 | 1.64041666667 | 12721 |
| 011858 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:02am | Sensor | 1797-S0037-905-G-ACK | 6823.8 | 1595105.4 | 511055.6 | 47335 | 1.64041666667 | 11858 |
| 012363 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:03am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595106.3 | 511058.0 | 47337 | 1.64041666667 | 12363 |
| 011994 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:04am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595107.1 | 511060.9 | 47339 | 1.64041666667 | 11994 |
| 013174 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:05am | Sensor | 1797-S0037-905-G-ACK | 6823.8 | 1595107.8 | 511063.2 | 47341 | 1.64041666667 | 13174 |
| 013372 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:06am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595108.7 | 511066.3 | 47343 | 1.64041666667 | 13372 |
| 013492 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:07am | Sensor | 1797-S0037-905-G-ACK | 6823.8 | 1595108.9 | 511069.0 | 47345 | 1.64041666667 | 13492 |
| 013417 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:08am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595108.7 | 511072.4 | 47347 | 1.64041666667 | 13417 |
| 014147 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:09am | Sensor | 1797-S0037-905-G-ACK | 6823.6 | 1595108.5 | 511074.8 | 47349 | 1.64041666667 | 14147 |
| 013185 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:10am | Sensor | 1797-S0037-905-G-ACK | 6823.6 | 1595107.5 | 511078.2 | 47351 | 1.64041666667 | 13185 |
| 013739 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:11am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595107.0 | 511080.9 | 47353 | 1.64041666667 | 13739 |
| 013631 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:12am | Sensor | 1797-S0037-905-G-ACK | 6823.6 | 1595106.1 | 511083.6 | 47355 | 1.64041666667 | 13631 |
| 014207 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:13am | Sensor | 1797-S0037-905-G-ACK | 6823.6 | 1595105.2 | 511086.0 | 47357 | 1.64041666667 | 14207 |
| 012709 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:14am | Sensor | 1797-S0037-905-G-ACK | 6823.4 | 1595103.6 | 511089.0 | 47359 | 1.64041666667 | 12709 |
| 013531 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:15am | Sensor | 1797-S0037-905-G-ACK | 6823.3 | 1595102.2 | 511091.3 | 47361 | 1.64041666667 | 13531 |
| 013109 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:16am | Sensor | 1797-S0037-905-G-ACK | 6823.3 | 1595100.3 | 511094.3 | 47363 | 1.64041666667 | 13109 |
| 013021 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:17am | Sensor | 1797-S0037-905-G-ACK | 6823.2 | 1595098.4 | 511097.0 | 47365 | 1.64041666667 | 13021 |
| 013819 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:18am | Sensor | 1797-S0037-905-G-ACK | 6823.4 | 1595096.4 | 511099.5 | 47367 | 1.64041666667 | 13819 |
| 013121 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:19am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595094.3 | 511101.1 | 47369 | 1.64041666667 | 13121 |
| 012878 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:20am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595092.1 | 511102.8 | 47371 | 1.64041666667 | 12878 |
| 012509 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:21am | Sensor | 1797-S0037-905-G-ACK | 6823.6 | 1595089.7 | 511104.8 | 47373 | 1.64041666667 | 12509 |
| 012908 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:22am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595086.6 | 511106.8 | 47375 | 1.64041666667 | 12908 |
| 013051 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:23am | Sensor | 1797-S0037-905-G-ACK | 6823.8 | 1595084.0 | 511107.9 | 47377 | 1.64041666667 | 13051 |
| 013266 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:24am | Sensor | 1797-S0037-905-G-ACK | 6823.9 | 1595080.7 | 511108.8 | 47379 | 1.64041666667 | 13266 |
| 012697 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:25am | Sensor | 1797-S0037-905-G-ACK | 6823.7 | 1595078.0 | 511109.6 | 47381 | 1.64041666667 | 12697 |
| 013232 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:26am | Sensor | 1797-S0037-905-G-ACK | 6823.6 | 1595075.0 | 511111.2 | 47383 | 1.64041666667 | 13232 |
| 013510 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:27am | Sensor | 1797-S0037-905-G-ACK | 6823.8 | 1595072.8 | 511113.0 | 47385 | 1.64041666667 | 13510 |
| 013562 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:28am | Sensor | 1797-S0037-905-G-ACK | 6824.1 | 1595070.4 | 511115.0 | 47387 | 1.64041666667 | 13562 |
| 013606 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:29am | Sensor | 1797-S0037-905-G-ACK | 6824.0 | 1595069.2 | 511116.9 | 47389 | 1.64041666667 | 13606 |
| 014021 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:30am | Sensor | 1797-S0037-905-G-ACK | 6823.5 | 1595068.8 | 511119.8 | 47391 | 1.64041666667 | 14021 |
| 013354 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:31am | Sensor | 1797-S0037-905-G-ACK | 6823.3 | 1595068.3 | 511122.5 | 47393 | 1.64041666667 | 13354 |
| 013841 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:32am | Sensor | 1797-S0037-905-G-ACK | 6823.2 | 1595066.6 | 511125.4 | 47395 | 1.64041666667 | 13841 |
| 012923 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:33am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1595064.5 | 511127.6 | 47397 | 1.64041666667 | 12923 |
| 012789 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:34am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1595062.0 | 511130.1 | 47399 | 1.64041666667 | 12789 |
| 012534 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:35am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1595060.2 | 511132.2 | 47401 | 1.64041666667 | 12534 |
| 012870 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:36am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1595058.5 | 511134.9 | 47403 | 1.64041666667 | 12870 |
| 012654 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:37am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1595057.0 | 511137.1 | 47405 | 1.64041666667 | 12654 |
| 012608 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:38am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1595054.7 | 511139.7 | 47407 | 1.64041666667 | 12608 |
| 011517 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:39am | Sensor | 1797-S0037-905-G-ACK | 6823.1 | 1595052.9 | 511141.3 | 47409 | 1.64041666667 | 11517 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013513 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:40am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1595051.0 | 511143.6 | 47411 | 1.64041666667 | 13513 |
| 012551 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:41am | Sensor | 1797-S0037-905-G-ACK | 6823.1 | 1595049.4 | 511145.8 | 47413 | 1.64041666667 | 12551 |
| 011747 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:42am | Sensor | 1797-S0037-905-G-ACK | 6823.1 | 1595047.5 | 511148.1 | 47415 | 1.64041666667 | 11747 |
| 011453 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:43am | Sensor | 1797-S0037-905-G-ACK | 6823.2 | 1595045.5 | 511149.4 | 47417 | 1.64041666667 | 11453 |
| 012367 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:44am | Sensor | 1797-S0037-905-G-ACK | 6823.1 | 1595042.6 | 511150.0 | 47419 | 1.64041666667 | 12367 |
| 011929 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:45am | Sensor | 1797-S0037-905-G-ACK | 6823.1 | 1595040.5 | 511149.9 | 47421 | 1.64041666667 | 11929 |
| 012537 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:46am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1595038.9 | 511148.4 | 47423 | 1.64041666667 | 12537 |
| 013082 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:47am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1595038.9 | 511145.7 | 47425 | 1.64041666667 | 13082 |
| 012871 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:48am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1595040.0 | 511142.3 | 47427 | 1.64041666667 | 12871 |
| 012203 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:49am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1595041.3 | 511139.3 | 47429 | 1.64041666667 | 12203 |
| 011632 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:50am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1595042.6 | 511136.0 | 47431 | 1.64041666667 | 11632 |
| 011605 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:51am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1595043.4 | 511133.0 | 47433 | 1.64041666667 | 11605 |
| 011733 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:52am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1595043.9 | 511129.3 | 47435 | 1.64041666667 | 11733 |
| 012967 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:53am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1595043.4 | 511126.3 | 47437 | 1.64041666667 | 12967 |
| 012964 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:54am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1595041.8 | 511122.8 | 47439 | 1.64041666667 | 12964 |
| 012797 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:55am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1595040.2 | 511120.1 | 47441 | 1.64041666667 | 12797 |
| 013378 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:56am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1595038.1 | 511117.3 | 47443 | 1.64041666667 | 13378 |
| 012610 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:57am | Sensor | 1797-S0037-905-G-ACK | 6823.1 | 1595036.0 | 511115.5 | 47445 | 1.64041666667 | 12610 |
| 012868 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:58am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1595033.0 | 511113.6 | 47447 | 1.64041666667 | 12868 |
| 012841 | 0 | GeoXH 6000 | 08/19/2015 | 11:26:59am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1595030.1 | 511112.1 | 47449 | 1.64041666667 | 12841 |
| 012428 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:00am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1595026.8 | 511110.4 | 47451 | 1.64041666667 | 12428 |
| 012075 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:01am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1595024.3 | 511109.0 | 47453 | 1.64041666667 | 12075 |
| 012042 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:02am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1595021.1 | 511107.0 | 47455 | 1.64041666667 | 12042 |
| 012819 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:03am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1595018.7 | 511105.2 | 47457 | 1.64041666667 | 12819 |
| 012558 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:04am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1595015.7 | 511102.5 | 47459 | 1.64041666667 | 12558 |
| 012344 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:05am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1595013.5 | 511100.8 | 47461 | 1.64041666667 | 12344 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:06am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1595010.2 | 511099.5 | 47463 | 1.64041666667 | 12021 |
| 013054 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:07am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1595007.3 | 511099.4 | 47465 | 1.64041666667 | 13054 |
| 012278 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:08am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1595003.9 | 511100.1 | 47467 | 1.64041666667 | 12278 |
| 011976 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:09am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1595001.3 | 511100.8 | 47469 | 1.64041666667 | 11976 |
| 011694 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:10am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594998.1 | 511102.3 | 47471 | 1.64041666667 | 11694 |
| 012090 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:11am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594995.9 | 511104.4 | 47473 | 1.64041666667 | 12090 |
| 012778 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:12am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594993.9 | 511107.3 | 47475 | 1.64041666667 | 12778 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:13am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594992.4 | 511109.7 | 47477 | 1.64041666667 | 12378 |
| 012062 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:14am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594990.2 | 511113.1 | 47479 | 1.64041666667 | 12062 |
| 011645 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:15am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594988.4 | 511115.7 | 47481 | 1.64041666667 | 11645 |
| 011583 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:16am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594986.0 | 511118.6 | 47483 | 1.64041666667 | 11583 |
| 011285 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:17am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594983.8 | 511120.8 | 47485 | 1.64041666667 | 11285 |
| 011545 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:18am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594981.0 | 511123.4 | 47487 | 1.64041666667 | 11545 |
| 011804 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:19am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594978.8 | 511125.6 | 47489 | 1.64041666667 | 11804 |
| 011305 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:20am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594976.1 | 511128.5 | 47491 | 1.64041666667 | 11305 |
| 011249 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:21am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594973.8 | 511130.7 | 47493 | 1.64041666667 | 11249 |
| 011097 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:22am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594970.9 | 511133.0 | 47495 | 1.64041666667 | 11097 |
| 011245 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:23am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594968.7 | 511134.7 | 47497 | 1.64041666667 | 11245 |
| 011575 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:24am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594965.8 | 511137.1 | 47499 | 1.64041666667 | 11575 |
| 011093 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:25am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594963.3 | 511139.3 | 47501 | 1.64041666667 | 11093 |
| 011557 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:26am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594960.6 | 511142.3 | 47503 | 1.64041666667 | 11557 |
| 012463 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:27am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594958.4 | 511144.8 | 47505 | 1.64041666667 | 12463 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012006 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:28am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594955.6 | 511147.7 | 47507 | 1.64041666667 | 12006 |
| 011666 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:29am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594953.2 | 511149.7 | 47509 | 1.64041666667 | 11666 |
| 011159 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:30am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594950.4 | 511151.6 | 47511 | 1.64041666667 | 11159 |
| 011415 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:31am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594947.6 | 511153.1 | 47513 | 1.64041666667 | 11415 |
| 011430 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:32am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594944.4 | 511155.2 | 47515 | 1.64041666667 | 11430 |
| 010562 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:33am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594941.8 | 511157.1 | 47517 | 1.64041666667 | 10562 |
| 010996 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:34am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594938.9 | 511159.5 | 47519 | 1.64041666667 | 10996 |
| 011442 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:35am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594936.5 | 511161.9 | 47521 | 1.64041666667 | 11442 |
| 011424 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:36am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594934.1 | 511164.8 | 47523 | 1.64041666667 | 11424 |
| 011148 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:37am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594932.0 | 511167.3 | 47525 | 1.64041666667 | 11148 |
| 011520 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:38am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594929.5 | 511170.3 | 47527 | 1.64041666667 | 11520 |
| 011032 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:39am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594927.3 | 511172.6 | 47529 | 1.64041666667 | 11032 |
| 010758 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:40am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594924.6 | 511175.5 | 47531 | 1.64041666667 | 10758 |
| 011204 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:41am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594922.3 | 511177.7 | 47533 | 1.64041666667 | 11204 |
| 011274 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:42am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594919.4 | 511180.3 | 47535 | 1.64041666667 | 11274 |
| 010767 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:43am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594916.9 | 511182.3 | 47537 | 1.64041666667 | 10767 |
| 011328 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:44am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594913.9 | 511184.5 | 47539 | 1.64041666667 | 11328 |
| 011405 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:45am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594911.5 | 511186.1 | 47541 | 1.64041666667 | 11405 |
| 011215 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:46am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594908.8 | 511188.1 | 47543 | 1.64041666667 | 11215 |
| 011858 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:47am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594906.6 | 511190.1 | 47545 | 1.64041666667 | 11858 |
| 011335 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:48am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594903.8 | 511192.5 | 47547 | 1.64041666667 | 11335 |
| 011101 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:49am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594901.4 | 511194.4 | 47549 | 1.64041666667 | 11101 |
| 010999 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:50am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594898.4 | 511197.0 | 47551 | 1.64041666667 | 10999 |
| 011302 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:51am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594895.7 | 511199.3 | 47553 | 1.64041666667 | 11302 |
| 010895 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:52am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594893.0 | 511201.5 | 47555 | 1.64041666667 | 10895 |
| 011250 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:53am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594890.4 | 511203.6 | 47557 | 1.64041666667 | 11250 |
| 010926 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:54am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594887.2 | 511205.8 | 47559 | 1.64041666667 | 10926 |
| 011921 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:55am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594884.6 | 511207.4 | 47561 | 1.64041666667 | 11921 |
| 011730 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:56am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594881.0 | 511209.6 | 47563 | 1.64041666667 | 11730 |
| 011076 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:57am | Sensor | 1797-S0037-905-G-ACK | 6821.0 | 1594878.3 | 511211.3 | 47565 | 1.64041666667 | 11076 |
| 011270 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:58am | Sensor | 1797-S0037-905-G-ACK | 6820.8 | 1594875.2 | 511213.7 | 47567 | 1.64041666667 | 11270 |
| 011904 | 0 | GeoXH 6000 | 08/19/2015 | 11:27:59am | Sensor | 1797-S0037-905-G-ACK | 6820.8 | 1594872.7 | 511215.9 | 47569 | 1.64041666667 | 11904 |
| 011939 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:00am | Sensor | 1797-S0037-905-G-ACK | 6820.9 | 1594869.9 | 511218.1 | 47571 | 1.64041666667 | 11939 |
| 011958 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:01am | Sensor | 1797-S0037-905-G-ACK | 6820.8 | 1594866.9 | 511220.1 | 47573 | 1.64041666667 | 11958 |
| 012344 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:02am | Sensor | 1797-S0037-905-G-ACK | 6820.7 | 1594863.5 | 511222.1 | 47575 | 1.64041666667 | 12344 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:03am | Sensor | 1797-S0037-905-G-ACK | 6820.7 | 1594860.5 | 511223.8 | 47577 | 1.64041666667 | 11953 |
| 011538 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:04am | Sensor | 1797-S0037-905-G-ACK | 6820.9 | 1594857.1 | 511225.7 | 47579 | 1.64041666667 | 11538 |
| 012273 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:05am | Sensor | 1797-S0037-905-G-ACK | 6820.9 | 1594854.3 | 511227.1 | 47581 | 1.64041666667 | 12273 |
| 011801 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:06am | Sensor | 1797-S0037-905-G-ACK | 6820.8 | 1594850.8 | 511228.8 | 47583 | 1.64041666667 | 11801 |
| 012113 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:07am | Sensor | 1797-S0037-905-G-ACK | 6821.0 | 1594848.2 | 511230.5 | 47585 | 1.64041666667 | 12113 |
| 011771 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:08am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594844.9 | 511232.6 | 47587 | 1.64041666667 | 11771 |
| 011738 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:09am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594842.4 | 511234.4 | 47589 | 1.64041666667 | 11738 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:10am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594839.7 | 511236.8 | 47591 | 1.64041666667 | 12045 |
| 012415 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:11am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594837.6 | 511238.9 | 47593 | 1.64041666667 | 12415 |
| 013808 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:12am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594834.7 | 511241.1 | 47595 | 1.64041666667 | 13808 |
| 012859 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:13am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594832.1 | 511242.6 | 47597 | 1.64041666667 | 12859 |
| 013346 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:14am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594828.8 | 511244.0 | 47599 | 1.64041666667 | 13346 |
| 013117 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:15am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594825.9 | 511244.9 | 47601 | 1.64041666667 | 13117 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012838 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:16am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594822.3 | 511245.9 | 47603 | 1.64041666667 | 12838 |
| 013019 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:17am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594819.4 | 511247.0 | 47605 | 1.64041666667 | 13019 |
| 012400 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:18am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594816.0 | 511248.9 | 47607 | 1.64041666667 | 12400 |
| 012225 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:19am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594814.0 | 511250.1 | 47609 | 1.64041666667 | 12225 |
| 012569 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:20am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594810.8 | 511251.7 | 47611 | 1.64041666667 | 12569 |
| 012590 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:21am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594807.7 | 511252.8 | 47613 | 1.64041666667 | 12590 |
| 012414 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:22am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594804.6 | 511253.8 | 47615 | 1.64041666667 | 12414 |
| 012143 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:23am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594801.5 | 511254.9 | 47617 | 1.64041666667 | 12143 |
| 013033 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:24am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594798.1 | 511256.2 | 47619 | 1.64041666667 | 13033 |
| 012161 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:25am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594794.8 | 511257.5 | 47621 | 1.64041666667 | 12161 |
| 013380 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:26am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594790.8 | 511259.0 | 47623 | 1.64041666667 | 13380 |
| 012349 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:27am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594788.0 | 511260.2 | 47625 | 1.64041666667 | 12349 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:28am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594784.3 | 511261.5 | 47627 | 1.64041666667 | 12106 |
| 013950 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:29am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594780.7 | 511262.4 | 47629 | 1.64041666667 | 13950 |
| 013306 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:30am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594776.9 | 511263.1 | 47631 | 1.64041666667 | 13306 |
| 012525 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:31am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594773.7 | 511263.8 | 47633 | 1.64041666667 | 12525 |
| 012190 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:32am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594770.0 | 511264.9 | 47635 | 1.64041666667 | 12190 |
| 011814 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:33am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594766.9 | 511266.1 | 47637 | 1.64041666667 | 11814 |
| 012068 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:34am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594763.4 | 511267.5 | 47639 | 1.64041666667 | 12068 |
| 012105 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:35am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594760.3 | 511268.5 | 47641 | 1.64041666667 | 12105 |
| 011744 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:36am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594756.3 | 511269.5 | 47643 | 1.64041666667 | 11744 |
| 012351 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:37am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594753.2 | 511270.0 | 47645 | 1.64041666667 | 12351 |
| 011762 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:38am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594748.9 | 511270.4 | 47647 | 1.64041666667 | 11762 |
| 011439 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:39am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594745.7 | 511270.7 | 47649 | 1.64041666667 | 11439 |
| 011969 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:40am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594742.0 | 511271.3 | 47651 | 1.64041666667 | 11969 |
| 011907 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:41am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594738.8 | 511271.9 | 47653 | 1.64041666667 | 11907 |
| 012218 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:42am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594735.0 | 511273.0 | 47655 | 1.64041666667 | 12218 |
| 012100 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:43am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594731.9 | 511273.9 | 47657 | 1.64041666667 | 12100 |
| 012153 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:44am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594728.0 | 511275.0 | 47659 | 1.64041666667 | 12153 |
| 012304 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:45am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594724.9 | 511275.6 | 47661 | 1.64041666667 | 12304 |
| 012621 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:46am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594720.9 | 511275.9 | 47663 | 1.64041666667 | 12621 |
| 012611 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:47am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594717.9 | 511275.9 | 47665 | 1.64041666667 | 12611 |
| 012981 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:48am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594714.3 | 511276.3 | 47667 | 1.64041666667 | 12981 |
| 013377 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:49am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594711.2 | 511276.8 | 47669 | 1.64041666667 | 13377 |
| 012962 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:50am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594707.5 | 511277.4 | 47671 | 1.64041666667 | 12962 |
| 013291 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:51am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594704.4 | 511277.9 | 47673 | 1.64041666667 | 13291 |
| 013918 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:52am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594700.8 | 511278.5 | 47675 | 1.64041666667 | 13918 |
| 013882 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:53am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594697.5 | 511279.0 | 47677 | 1.64041666667 | 13882 |
| 013576 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:54am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594693.7 | 511279.8 | 47679 | 1.64041666667 | 13576 |
| 012541 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:55am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594691.0 | 511280.5 | 47681 | 1.64041666667 | 12541 |
| 012477 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:56am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594687.4 | 511281.6 | 47683 | 1.64041666667 | 12477 |
| 012546 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:57am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594684.5 | 511282.6 | 47685 | 1.64041666667 | 12546 |
| 013529 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:58am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594681.0 | 511283.8 | 47687 | 1.64041666667 | 13529 |
| 013445 | 0 | GeoXH 6000 | 08/19/2015 | 11:28:59am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594677.9 | 511284.5 | 47689 | 1.64041666667 | 13445 |
| 013428 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:00am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594674.7 | 511285.2 | 47691 | 1.64041666667 | 13428 |
| 013200 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:01am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594672.1 | 511285.8 | 47693 | 1.64041666667 | 13200 |
| 012592 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:02am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594668.6 | 511286.6 | 47695 | 1.64041666667 | 12592 |
| 012663 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:03am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594665.8 | 511287.5 | 47697 | 1.64041666667 | 12663 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012980 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:04am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594662.1 | 511288.7 | 47699 | 1.64041666667 | 12980 |
| 012926 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:05am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594659.3 | 511289.3 | 47701 | 1.64041666667 | 12926 |
| 013316 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:06am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594655.8 | 511289.5 | 47703 | 1.64041666667 | 13316 |
| 013137 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:07am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594653.0 | 511289.4 | 47705 | 1.64041666667 | 13137 |
| 013420 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:08am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594649.6 | 511289.6 | 47707 | 1.64041666667 | 13420 |
| 013511 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:09am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594646.8 | 511289.7 | 47709 | 1.64041666667 | 13511 |
| 013232 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:10am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594643.5 | 511289.8 | 47711 | 1.64041666667 | 13232 |
| 013173 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:11am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594640.7 | 511290.1 | 47713 | 1.64041666667 | 13173 |
| 013005 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:12am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594637.8 | 511291.3 | 47715 | 1.64041666667 | 13005 |
| 012670 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:13am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594636.1 | 511293.2 | 47717 | 1.64041666667 | 12670 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:14am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594634.6 | 511295.9 | 47719 | 1.64041666667 | 12917 |
| 012613 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:15am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594633.5 | 511298.5 | 47721 | 1.64041666667 | 12613 |
| 012952 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:16am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594632.3 | 511301.4 | 47723 | 1.64041666667 | 12952 |
| 012033 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:17am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594631.6 | 511304.2 | 47725 | 1.64041666667 | 12033 |
| 012371 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:18am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594631.7 | 511306.8 | 47727 | 1.64041666667 | 12371 |
| 013358 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:19am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594632.8 | 511309.2 | 47729 | 1.64041666667 | 13358 |
| 012817 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:20am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594634.5 | 511311.6 | 47731 | 1.64041666667 | 12817 |
| 012932 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:21am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594635.2 | 511313.7 | 47733 | 1.64041666667 | 12932 |
| 012614 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:22am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594635.0 | 511316.6 | 47735 | 1.64041666667 | 12614 |
| 012938 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:23am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594634.6 | 511318.8 | 47737 | 1.64041666667 | 12938 |
| 012235 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:24am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594633.7 | 511321.3 | 47739 | 1.64041666667 | 12235 |
| 012064 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:25am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594632.5 | 511323.1 | 47741 | 1.64041666667 | 12064 |
| 012719 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:26am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594630.4 | 511325.2 | 47743 | 1.64041666667 | 12719 |
| 013507 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:27am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594628.3 | 511326.9 | 47745 | 1.64041666667 | 13507 |
| 012930 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:28am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594625.8 | 511328.0 | 47747 | 1.64041666667 | 12930 |
| 013513 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:29am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594623.4 | 511328.0 | 47749 | 1.64041666667 | 13513 |
| 013248 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:30am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594619.8 | 511326.9 | 47751 | 1.64041666667 | 13248 |
| 012747 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:31am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594617.0 | 511326.3 | 47753 | 1.64041666667 | 12747 |
| 013207 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:32am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594614.3 | 511325.6 | 47755 | 1.64041666667 | 13207 |
| 012851 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:33am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594611.7 | 511324.6 | 47757 | 1.64041666667 | 12851 |
| 012794 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:34am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594608.5 | 511323.1 | 47759 | 1.64041666667 | 12794 |
| 013646 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:35am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594606.2 | 511321.6 | 47761 | 1.64041666667 | 13646 |
| 013106 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:36am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594603.2 | 511319.2 | 47763 | 1.64041666667 | 13106 |
| 012967 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:37am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594600.6 | 511317.9 | 47765 | 1.64041666667 | 12967 |
| 013174 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:38am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594597.4 | 511317.7 | 47767 | 1.64041666667 | 13174 |
| 013830 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:39am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594594.2 | 511318.4 | 47769 | 1.64041666667 | 13830 |
| 013224 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:40am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594591.0 | 511319.6 | 47771 | 1.64041666667 | 13224 |
| 012959 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:41am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594588.1 | 511320.9 | 47773 | 1.64041666667 | 12959 |
| 013244 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:42am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594584.9 | 511322.8 | 47775 | 1.64041666667 | 13244 |
| 012745 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:43am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594582.2 | 511324.1 | 47777 | 1.64041666667 | 12745 |
| 013604 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:44am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594578.9 | 511325.4 | 47779 | 1.64041666667 | 13604 |
| 014777 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:45am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594576.0 | 511326.8 | 47781 | 1.64041666667 | 14777 |
| 015054 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:46am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594572.8 | 511328.6 | 47783 | 1.64041666667 | 15054 |
| 015030 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:47am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594570.1 | 511330.1 | 47785 | 1.64041666667 | 15030 |
| 015594 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:48am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594567.0 | 511331.8 | 47787 | 1.64041666667 | 15594 |
| 015094 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:49am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594564.4 | 511333.1 | 47789 | 1.64041666667 | 15094 |
| 015045 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:50am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594561.3 | 511334.1 | 47791 | 1.64041666667 | 15045 |
| 014920 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:51am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594558.8 | 511334.8 | 47793 | 1.64041666667 | 14920 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014790 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:52am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594555.7 | 511335.6 | 47795 | 1.64041666667 | 14790 |
| 014994 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:53am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594553.0 | 511336.6 | 47797 | 1.64041666667 | 14994 |
| 015139 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:54am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594549.8 | 511338.2 | 47799 | 1.64041666667 | 15139 |
| 015003 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:55am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594547.1 | 511339.6 | 47801 | 1.64041666667 | 15003 |
| 015084 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:56am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594544.0 | 511341.3 | 47803 | 1.64041666667 | 15084 |
| 014170 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:57am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594541.3 | 511342.9 | 47805 | 1.64041666667 | 14170 |
| 013460 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:58am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594538.1 | 511345.0 | 47807 | 1.64041666667 | 13460 |
| 013991 | 0 | GeoXH 6000 | 08/19/2015 | 11:29:59am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594535.8 | 511346.8 | 47809 | 1.64041666667 | 13991 |
| 013285 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:00am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594533.2 | 511349.2 | 47811 | 1.64041666667 | 13285 |
| 013128 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:01am | Sensor | 1797-S0037-905-G-ACK | 6821.1 | 1594531.0 | 511351.0 | 47813 | 1.64041666667 | 13128 |
| 013167 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:02am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594529.0 | 511353.0 | 47815 | 1.64041666667 | 13167 |
| 013721 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:03am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594527.9 | 511355.1 | 47817 | 1.64041666667 | 13721 |
| 013853 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:04am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594527.1 | 511357.7 | 47819 | 1.64041666667 | 13853 |
| 014827 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:05am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594526.8 | 511359.6 | 47821 | 1.64041666667 | 14827 |
| 015300 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:06am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594527.7 | 511362.0 | 47823 | 1.64041666667 | 15300 |
| 015701 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:07am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594529.1 | 511363.9 | 47825 | 1.64041666667 | 15701 |
| 014449 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:08am | Sensor | 1797-S0037-905-G-ACK | 6821.2 | 1594530.5 | 511366.2 | 47827 | 1.64041666667 | 14449 |
| 014570 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:09am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594531.3 | 511368.5 | 47829 | 1.64041666667 | 14570 |
| 013745 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:10am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594532.3 | 511371.3 | 47831 | 1.64041666667 | 13745 |
| 013409 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:11am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594533.3 | 511373.5 | 47833 | 1.64041666667 | 13409 |
| 013543 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:12am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594533.9 | 511376.1 | 47835 | 1.64041666667 | 13543 |
| 014135 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:13am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594534.0 | 511378.7 | 47837 | 1.64041666667 | 14135 |
| 014266 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:14am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594534.3 | 511381.5 | 47839 | 1.64041666667 | 14266 |
| 013889 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:15am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594534.4 | 511383.5 | 47841 | 1.64041666667 | 13889 |
| 014510 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:16am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594533.6 | 511386.2 | 47843 | 1.64041666667 | 14510 |
| 015032 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:17am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594532.5 | 511388.0 | 47845 | 1.64041666667 | 15032 |
| 014425 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:18am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594531.5 | 511389.9 | 47847 | 1.64041666667 | 14425 |
| 013214 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:19am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594530.9 | 511391.5 | 47849 | 1.64041666667 | 13214 |
| 013928 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:20am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594529.4 | 511393.7 | 47851 | 1.64041666667 | 13928 |
| 014727 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:21am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594528.0 | 511395.8 | 47853 | 1.64041666667 | 14727 |
| 014568 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:22am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594527.2 | 511398.6 | 47855 | 1.64041666667 | 14568 |
| 014562 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:23am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594526.4 | 511400.3 | 47857 | 1.64041666667 | 14562 |
| 015159 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:24am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594524.7 | 511402.5 | 47859 | 1.64041666667 | 15159 |
| 014137 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:25am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594523.5 | 511404.5 | 47861 | 1.64041666667 | 14137 |
| 014537 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:26am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594522.8 | 511407.3 | 47863 | 1.64041666667 | 14537 |
| 013749 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:27am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594522.2 | 511409.8 | 47865 | 1.64041666667 | 13749 |
| 013831 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:28am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594521.4 | 511412.8 | 47867 | 1.64041666667 | 13831 |
| 014327 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:29am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594521.0 | 511415.0 | 47869 | 1.64041666667 | 14327 |
| 014486 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:30am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594520.6 | 511417.9 | 47871 | 1.64041666667 | 14486 |
| 015356 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:31am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594520.0 | 511420.2 | 47873 | 1.64041666667 | 15356 |
| 014525 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:32am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594518.9 | 511422.9 | 47875 | 1.64041666667 | 14525 |
| 013998 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:33am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594517.9 | 511425.1 | 47877 | 1.64041666667 | 13998 |
| 013896 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:34am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594516.8 | 511427.9 | 47879 | 1.64041666667 | 13896 |
| 014619 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:35am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594515.8 | 511430.3 | 47881 | 1.64041666667 | 14619 |
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:36am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594514.2 | 511433.2 | 47883 | 1.64041666667 | 13795 |
| 014757 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:37am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594513.0 | 511435.6 | 47885 | 1.64041666667 | 14757 |
| 014668 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:38am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594511.7 | 511438.9 | 47887 | 1.64041666667 | 14668 |
| 014978 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:39am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594510.9 | 511441.7 | 47889 | 1.64041666667 | 14978 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015145 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:40am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594509.7 | 511445.0 | 47891 | 1.64041666667 | 15145 |
| 015914 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:41am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594508.5 | 511447.5 | 47893 | 1.64041666667 | 15914 |
| 016504 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:42am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594506.8 | 511450.0 | 47895 | 1.64041666667 | 16504 |
| 016363 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:43am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594505.4 | 511452.2 | 47897 | 1.64041666667 | 16363 |
| 017274 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:44am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594504.0 | 511454.9 | 47899 | 1.64041666667 | 17274 |
| 015844 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:45am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594503.2 | 511457.0 | 47901 | 1.64041666667 | 15844 |
| 015505 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:46am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594502.0 | 511459.3 | 47903 | 1.64041666667 | 15505 |
| 015314 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:47am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594501.0 | 511461.7 | 47905 | 1.64041666667 | 15314 |
| 016429 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:48am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594501.0 | 511463.7 | 47907 | 1.64041666667 | 16429 |
| 015466 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:49am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594501.6 | 511465.5 | 47909 | 1.64041666667 | 15466 |
| 015067 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:50am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594502.8 | 511468.0 | 47911 | 1.64041666667 | 15067 |
| 014797 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:51am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594503.9 | 511469.9 | 47913 | 1.64041666667 | 14797 |
| 014803 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:52am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594504.9 | 511472.2 | 47915 | 1.64041666667 | 14803 |
| 014979 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:53am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594505.4 | 511474.5 | 47917 | 1.64041666667 | 14979 |
| 014636 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:54am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594506.0 | 511477.3 | 47919 | 1.64041666667 | 14636 |
| 014570 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:55am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594506.7 | 511479.2 | 47921 | 1.64041666667 | 14570 |
| 015185 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:56am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594507.6 | 511481.8 | 47923 | 1.64041666667 | 15185 |
| 015232 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:57am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594508.0 | 511484.1 | 47925 | 1.64041666667 | 15232 |
| 014658 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:58am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594508.3 | 511487.1 | 47927 | 1.64041666667 | 14658 |
| 013802 | 0 | GeoXH 6000 | 08/19/2015 | 11:30:59am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594508.7 | 511489.3 | 47929 | 1.64041666667 | 13802 |
| 014379 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:00am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594509.5 | 511492.0 | 47931 | 1.64041666667 | 14379 |
| 013210 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:01am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594510.0 | 511493.8 | 47933 | 1.64041666667 | 13210 |
| 012951 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:02am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594510.2 | 511495.1 | 47935 | 1.64041666667 | 12951 |
| 013225 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:03am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594510.6 | 511495.7 | 47937 | 1.64041666667 | 13225 |
| 013626 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:04am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594511.8 | 511497.1 | 47939 | 1.64041666667 | 13626 |
| 014160 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:05am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594513.0 | 511498.8 | 47941 | 1.64041666667 | 14160 |
| 014587 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:06am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594514.6 | 511500.9 | 47943 | 1.64041666667 | 14587 |
| 013672 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:07am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594515.5 | 511502.9 | 47945 | 1.64041666667 | 13672 |
| 013181 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:08am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594516.8 | 511504.8 | 47947 | 1.64041666667 | 13181 |
| 013654 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:09am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594517.5 | 511506.4 | 47949 | 1.64041666667 | 13654 |
| 014145 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:10am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594518.3 | 511508.3 | 47951 | 1.64041666667 | 14145 |
| 013717 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:11am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594519.3 | 511509.6 | 47953 | 1.64041666667 | 13717 |
| 014083 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:12am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594520.0 | 511511.6 | 47955 | 1.64041666667 | 14083 |
| 014379 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:13am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594520.6 | 511512.9 | 47957 | 1.64041666667 | 14379 |
| 013571 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:14am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594521.3 | 511514.4 | 47959 | 1.64041666667 | 13571 |
| 013048 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:15am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594521.6 | 511516.1 | 47961 | 1.64041666667 | 13048 |
| 013219 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:16am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594522.0 | 511518.0 | 47963 | 1.64041666667 | 13219 |
| 013848 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:17am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594522.1 | 511519.8 | 47965 | 1.64041666667 | 13848 |
| 013429 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:18am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594522.7 | 511521.7 | 47967 | 1.64041666667 | 13429 |
| 013912 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:19am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594523.2 | 511523.3 | 47969 | 1.64041666667 | 13912 |
| 014010 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:20am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594523.7 | 511525.0 | 47971 | 1.64041666667 | 14010 |
| 014743 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:21am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594524.1 | 511526.3 | 47973 | 1.64041666667 | 14743 |
| 014165 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:22am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594524.5 | 511527.3 | 47975 | 1.64041666667 | 14165 |
| 013653 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:23am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594525.1 | 511527.6 | 47977 | 1.64041666667 | 13653 |
| 014092 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:24am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594525.1 | 511527.8 | 47979 | 1.64041666667 | 14092 |
| 013432 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:25am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.2 | 511527.8 | 47981 | 1.64041666667 | 13432 |
| 013345 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:26am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.9 | 47983 | 1.64041666667 | 13345 |
| 013334 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:27am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.0 | 511527.8 | 47985 | 1.64041666667 | 13334 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012870 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:28am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.0 | 511527.7 | 47987 | 1.64041666667 | 12870 |
| 012909 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:29am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.0 | 511527.7 | 47989 | 1.64041666667 | 12909 |
| 013074 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:30am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.0 | 511527.7 | 47991 | 1.64041666667 | 13074 |
| 013376 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:31am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 47993 | 1.64041666667 | 13376 |
| 013614 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:32am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 47995 | 1.64041666667 | 13614 |
| 013973 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:33am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 47997 | 1.64041666667 | 13973 |
| 013687 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:34am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 47999 | 1.64041666667 | 13687 |
| 013871 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:35am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 48001 | 1.64041666667 | 13871 |
| 013840 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:36am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 48003 | 1.64041666667 | 13840 |
| 013050 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:37am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 48005 | 1.64041666667 | 13050 |
| 013580 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:38am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 48007 | 1.64041666667 | 13580 |
| 013564 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:39am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 48009 | 1.64041666667 | 13564 |
| 012550 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:40am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 48011 | 1.64041666667 | 12550 |
| 013524 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:41am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 48013 | 1.64041666667 | 13524 |
| 013105 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:42am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.1 | 511527.7 | 48015 | 1.64041666667 | 13105 |
| 013154 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:43am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594525.0 | 511527.7 | 48017 | 1.64041666667 | 13154 |
| 013766 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:44am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594524.4 | 511528.2 | 48019 | 1.64041666667 | 13766 |
| 013751 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:45am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594524.0 | 511527.8 | 48021 | 1.64041666667 | 13751 |
| 013517 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:46am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594523.5 | 511525.7 | 48023 | 1.64041666667 | 13517 |
| 013033 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:47am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594522.8 | 511523.5 | 48025 | 1.64041666667 | 13033 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:48am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594521.8 | 511520.7 | 48027 | 1.64041666667 | 12401 |
| 013320 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:49am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594521.1 | 511518.3 | 48029 | 1.64041666667 | 13320 |
| 013223 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:50am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594520.2 | 511515.3 | 48031 | 1.64041666667 | 13223 |
| 013055 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:51am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594519.9 | 511513.0 | 48033 | 1.64041666667 | 13055 |
| 013103 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:52am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594520.1 | 511510.2 | 48035 | 1.64041666667 | 13103 |
| 013595 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:53am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594520.0 | 511507.8 | 48037 | 1.64041666667 | 13595 |
| 012747 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:54am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594519.4 | 511505.1 | 48039 | 1.64041666667 | 12747 |
| 012623 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:55am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594518.8 | 511502.9 | 48041 | 1.64041666667 | 12623 |
| 013303 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:56am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594518.9 | 511500.9 | 48043 | 1.64041666667 | 13303 |
| 012785 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:57am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594519.6 | 511499.5 | 48045 | 1.64041666667 | 12785 |
| 013236 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:58am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594520.0 | 511497.8 | 48047 | 1.64041666667 | 13236 |
| 012815 | 0 | GeoXH 6000 | 08/19/2015 | 11:31:59am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594520.1 | 511497.1 | 48049 | 1.64041666667 | 12815 |
| 013013 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:00am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594520.0 | 511497.1 | 48051 | 1.64041666667 | 13013 |
| 013762 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:01am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594520.1 | 511497.3 | 48053 | 1.64041666667 | 13762 |
| 013606 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:02am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594520.8 | 511498.0 | 48055 | 1.64041666667 | 13606 |
| 014268 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:03am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594521.6 | 511499.5 | 48057 | 1.64041666667 | 14268 |
| 013793 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:04am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594522.6 | 511501.5 | 48059 | 1.64041666667 | 13793 |
| 012866 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:05am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594523.9 | 511502.9 | 48061 | 1.64041666667 | 12866 |
| 013185 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:06am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594525.9 | 511504.5 | 48063 | 1.64041666667 | 13185 |
| 012824 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:07am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594527.3 | 511505.6 | 48065 | 1.64041666667 | 12824 |
| 012493 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:08am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594528.8 | 511507.4 | 48067 | 1.64041666667 | 12493 |
| 012165 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:09am | Sensor | 1797-S0037-905-G-ACK | 6821.3 | 1594529.4 | 511510.0 | 48069 | 1.64041666667 | 12165 |
| 011763 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:10am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594530.0 | 511512.7 | 48071 | 1.64041666667 | 11763 |
| 012354 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:11am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594531.0 | 511514.5 | 48073 | 1.64041666667 | 12354 |
| 013159 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:12am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594532.3 | 511516.8 | 48075 | 1.64041666667 | 13159 |
| 013484 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:13am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594532.8 | 511518.8 | 48077 | 1.64041666667 | 13484 |
| 013202 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:14am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594533.3 | 511520.8 | 48079 | 1.64041666667 | 13202 |
| 013359 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:15am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594533.7 | 511522.4 | 48081 | 1.64041666667 | 13359 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013649 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:16am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594534.0 | 511524.2 | 48083 | 1.64041666667 | 13649 |
| 013340 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:17am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594535.3 | 511525.6 | 48085 | 1.64041666667 | 13340 |
| 013203 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:18am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594537.9 | 511526.1 | 48087 | 1.64041666667 | 13203 |
| 012857 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:19am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594540.1 | 511525.8 | 48089 | 1.64041666667 | 12857 |
| 013914 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:20am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594542.4 | 511524.7 | 48091 | 1.64041666667 | 13914 |
| 015207 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:21am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594543.9 | 511524.5 | 48093 | 1.64041666667 | 15207 |
| 015011 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:22am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594546.0 | 511524.3 | 48095 | 1.64041666667 | 15011 |
| 014549 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:23am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594548.0 | 511523.8 | 48097 | 1.64041666667 | 14549 |
| 014033 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:24am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594550.3 | 511523.7 | 48099 | 1.64041666667 | 14033 |
| 014321 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:25am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594552.3 | 511523.8 | 48101 | 1.64041666667 | 14321 |
| 013853 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:26am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594555.2 | 511523.9 | 48103 | 1.64041666667 | 13853 |
| 013942 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:27am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594557.2 | 511524.2 | 48105 | 1.64041666667 | 13942 |
| 014480 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:28am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594559.2 | 511524.8 | 48107 | 1.64041666667 | 14480 |
| 014587 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:29am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594561.3 | 511525.2 | 48109 | 1.64041666667 | 14587 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:30am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594563.9 | 511525.3 | 48111 | 1.64041666667 | 14355 |
| 014457 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:31am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594566.1 | 511525.7 | 48113 | 1.64041666667 | 14457 |
| 014680 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:32am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594568.6 | 511525.8 | 48115 | 1.64041666667 | 14680 |
| 015075 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:33am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594570.7 | 511525.6 | 48117 | 1.64041666667 | 15075 |
| 014307 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594573.3 | 511525.9 | 48119 | 1.64041666667 | 14307 |
| 014302 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:35am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594575.4 | 511525.9 | 48121 | 1.64041666667 | 14302 |
| 015057 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:36am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594577.7 | 511526.3 | 48123 | 1.64041666667 | 15057 |
| 015655 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:37am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594579.6 | 511527.2 | 48125 | 1.64041666667 | 15655 |
| 016336 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:38am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594582.0 | 511528.2 | 48127 | 1.64041666667 | 16336 |
| 015879 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:39am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594583.8 | 511529.7 | 48129 | 1.64041666667 | 15879 |
| 015277 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:40am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594585.9 | 511531.5 | 48131 | 1.64041666667 | 15277 |
| 015538 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:41am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594587.8 | 511532.9 | 48133 | 1.64041666667 | 15538 |
| 015633 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:42am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594589.2 | 511534.6 | 48135 | 1.64041666667 | 15633 |
| 015528 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:43am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594590.5 | 511535.8 | 48137 | 1.64041666667 | 15528 |
| 015244 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:44am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594593.0 | 511536.5 | 48139 | 1.64041666667 | 15244 |
| 015317 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:45am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594594.7 | 511537.2 | 48141 | 1.64041666667 | 15317 |
| 015043 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:46am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594597.1 | 511538.1 | 48143 | 1.64041666667 | 15043 |
| 014402 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:47am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594598.9 | 511538.7 | 48145 | 1.64041666667 | 14402 |
| 014896 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:48am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594601.3 | 511540.0 | 48147 | 1.64041666667 | 14896 |
| 015256 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:49am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594603.2 | 511540.6 | 48149 | 1.64041666667 | 15256 |
| 015609 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:50am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594605.1 | 511541.5 | 48151 | 1.64041666667 | 15609 |
| 015635 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:51am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594606.8 | 511542.5 | 48153 | 1.64041666667 | 15635 |
| 015064 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:52am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594609.1 | 511543.2 | 48155 | 1.64041666667 | 15064 |
| 015359 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:53am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594610.9 | 511544.2 | 48157 | 1.64041666667 | 15359 |
| 015089 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:54am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594612.9 | 511545.1 | 48159 | 1.64041666667 | 15089 |
| 016115 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:55am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594614.4 | 511546.1 | 48161 | 1.64041666667 | 16115 |
| 016444 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:56am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594615.7 | 511548.0 | 48163 | 1.64041666667 | 16444 |
| 015497 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:57am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594616.8 | 511549.6 | 48165 | 1.64041666667 | 15497 |
| 014777 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:58am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594617.0 | 511551.5 | 48167 | 1.64041666667 | 14777 |
| 014695 | 0 | GeoXH 6000 | 08/19/2015 | 11:32:59am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594616.6 | 511553.1 | 48169 | 1.64041666667 | 14695 |
| 015150 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:00am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594615.7 | 511554.8 | 48171 | 1.64041666667 | 15150 |
| 015677 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:01am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594614.8 | 511556.4 | 48173 | 1.64041666667 | 15677 |
| 015036 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:02am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594613.9 | 511557.8 | 48175 | 1.64041666667 | 15036 |
| 015102 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:03am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594612.4 | 511557.9 | 48177 | 1.64041666667 | 15102 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016317 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:04am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594610.3 | 511557.7 | 48179 | 1.64041666667 | 16317 |
| 016131 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:05am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594608.6 | 511557.3 | 48181 | 1.64041666667 | 16131 |
| 016394 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:06am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594606.6 | 511556.8 | 48183 | 1.64041666667 | 16394 |
| 015491 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:07am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594604.9 | 511556.0 | 48185 | 1.64041666667 | 15491 |
| 014766 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:08am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594603.0 | 511554.9 | 48187 | 1.64041666667 | 14766 |
| 015198 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:09am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594601.4 | 511554.1 | 48189 | 1.64041666667 | 15198 |
| 015501 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:10am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594599.5 | 511552.3 | 48191 | 1.64041666667 | 15501 |
| 015357 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:11am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594598.0 | 511551.2 | 48193 | 1.64041666667 | 15357 |
| 015688 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:12am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594596.3 | 511549.7 | 48195 | 1.64041666667 | 15688 |
| 014817 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:13am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594594.9 | 511548.2 | 48197 | 1.64041666667 | 14817 |
| 014837 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:14am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594592.6 | 511547.2 | 48199 | 1.64041666667 | 14837 |
| 014616 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:15am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594590.8 | 511546.5 | 48201 | 1.64041666667 | 14616 |
| 014701 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:16am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594588.6 | 511546.2 | 48203 | 1.64041666667 | 14701 |
| 014599 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:17am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594586.9 | 511546.1 | 48205 | 1.64041666667 | 14599 |
| 013942 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:18am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594584.5 | 511545.5 | 48207 | 1.64041666667 | 13942 |
| 013580 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:19am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594582.5 | 511545.4 | 48209 | 1.64041666667 | 13580 |
| 014396 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:20am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594580.3 | 511544.8 | 48211 | 1.64041666667 | 14396 |
| 014825 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:21am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594578.4 | 511544.3 | 48213 | 1.64041666667 | 14825 |
| 015636 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:22am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594576.4 | 511543.8 | 48215 | 1.64041666667 | 15636 |
| 015268 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:23am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594574.7 | 511543.3 | 48217 | 1.64041666667 | 15268 |
| 014798 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:24am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594572.4 | 511542.7 | 48219 | 1.64041666667 | 14798 |
| 014489 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:25am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594570.6 | 511541.9 | 48221 | 1.64041666667 | 14489 |
| 014960 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:26am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594568.5 | 511541.2 | 48223 | 1.64041666667 | 14960 |
| 014812 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:27am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594566.8 | 511540.5 | 48225 | 1.64041666667 | 14812 |
| 015022 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:28am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594564.8 | 511539.6 | 48227 | 1.64041666667 | 15022 |
| 015320 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:29am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594563.1 | 511539.0 | 48229 | 1.64041666667 | 15320 |
| 015420 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:30am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594561.1 | 511537.7 | 48231 | 1.64041666667 | 15420 |
| 015881 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:31am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594559.5 | 511537.0 | 48233 | 1.64041666667 | 15881 |
| 015675 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:32am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594557.3 | 511536.4 | 48235 | 1.64041666667 | 15675 |
| 015477 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:33am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594555.5 | 511536.1 | 48237 | 1.64041666667 | 15477 |
| 014803 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:34am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594553.4 | 511535.8 | 48239 | 1.64041666667 | 14803 |
| 014882 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:35am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594551.6 | 511535.2 | 48241 | 1.64041666667 | 14882 |
| 014003 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:36am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594549.2 | 511534.9 | 48243 | 1.64041666667 | 14003 |
| 014124 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:37am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594547.2 | 511534.6 | 48245 | 1.64041666667 | 14124 |
| 013930 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:38am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594545.0 | 511534.4 | 48247 | 1.64041666667 | 13930 |
| 013738 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:39am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594543.4 | 511534.2 | 48249 | 1.64041666667 | 13738 |
| 012587 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:40am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594541.2 | 511533.9 | 48251 | 1.64041666667 | 12587 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:41am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594539.1 | 511533.9 | 48253 | 1.64041666667 | 12975 |
| 012533 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:42am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594536.4 | 511533.5 | 48255 | 1.64041666667 | 12533 |
| 013597 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:43am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594534.6 | 511533.7 | 48257 | 1.64041666667 | 13597 |
| 013326 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:44am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594532.4 | 511533.4 | 48259 | 1.64041666667 | 13326 |
| 013773 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:45am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594530.5 | 511533.1 | 48261 | 1.64041666667 | 13773 |
| 013635 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:46am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594528.2 | 511532.8 | 48263 | 1.64041666667 | 13635 |
| 012867 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:47am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594526.3 | 511532.1 | 48265 | 1.64041666667 | 12867 |
| 013800 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:48am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594523.8 | 511531.3 | 48267 | 1.64041666667 | 13800 |
| 013440 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:49am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594522.1 | 511530.4 | 48269 | 1.64041666667 | 13440 |
| 013267 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:50am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594520.1 | 511529.6 | 48271 | 1.64041666667 | 13267 |
| 012630 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:51am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594518.2 | 511529.0 | 48273 | 1.64041666667 | 12630 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012407 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:52am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594516.2 | 511528.0 | 48275 | 1.64041666667 | 12407 |
| 012176 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:53am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594514.6 | 511527.3 | 48277 | 1.64041666667 | 12176 |
| 012324 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:54am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594512.7 | 511525.9 | 48279 | 1.64041666667 | 12324 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:55am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594511.3 | 511525.1 | 48281 | 1.64041666667 | 12917 |
| 012118 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:56am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594509.5 | 511524.0 | 48283 | 1.64041666667 | 12118 |
| 013281 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:57am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594508.2 | 511523.2 | 48285 | 1.64041666667 | 13281 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:58am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594506.1 | 511522.3 | 48287 | 1.64041666667 | 12840 |
| 013620 | 0 | GeoXH 6000 | 08/19/2015 | 11:33:59am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594504.4 | 511521.3 | 48289 | 1.64041666667 | 13620 |
| 013331 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:00am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594502.2 | 511520.6 | 48291 | 1.64041666667 | 13331 |
| 013094 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:01am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594500.6 | 511519.9 | 48293 | 1.64041666667 | 13094 |
| 013657 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:02am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594499.2 | 511519.7 | 48295 | 1.64041666667 | 13657 |
| 013600 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:03am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594498.6 | 511520.9 | 48297 | 1.64041666667 | 13600 |
| 013425 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:04am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594499.6 | 511522.6 | 48299 | 1.64041666667 | 13425 |
| 013769 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:05am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594500.6 | 511523.9 | 48301 | 1.64041666667 | 13769 |
| 014367 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:06am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594501.1 | 511526.2 | 48303 | 1.64041666667 | 14367 |
| 013549 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:07am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594501.2 | 511527.7 | 48305 | 1.64041666667 | 13549 |
| 013411 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:08am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594500.4 | 511529.6 | 48307 | 1.64041666667 | 13411 |
| 014091 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:09am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594499.8 | 511531.2 | 48309 | 1.64041666667 | 14091 |
| 013131 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:10am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594499.0 | 511533.2 | 48311 | 1.64041666667 | 13131 |
| 013874 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:11am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594499.0 | 511534.6 | 48313 | 1.64041666667 | 13874 |
| 013534 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:12am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594500.0 | 511536.5 | 48315 | 1.64041666667 | 13534 |
| 013050 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:13am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594501.3 | 511537.3 | 48317 | 1.64041666667 | 13050 |
| 013445 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:14am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594503.4 | 511536.9 | 48319 | 1.64041666667 | 13445 |
| 013293 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:15am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594505.3 | 511536.6 | 48321 | 1.64041666667 | 13293 |
| 013275 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:16am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594507.3 | 511536.3 | 48323 | 1.64041666667 | 13275 |
| 014217 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:17am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594509.1 | 511536.5 | 48325 | 1.64041666667 | 14217 |
| 014139 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:18am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594511.0 | 511536.8 | 48327 | 1.64041666667 | 14139 |
| 013946 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:19am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594512.9 | 511536.9 | 48329 | 1.64041666667 | 13946 |
| 013904 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:20am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594515.1 | 511537.3 | 48331 | 1.64041666667 | 13904 |
| 013829 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:21am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594517.0 | 511537.3 | 48333 | 1.64041666667 | 13829 |
| 013868 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:22am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594519.4 | 511537.6 | 48335 | 1.64041666667 | 13868 |
| 012368 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:23am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594521.4 | 511537.7 | 48337 | 1.64041666667 | 12368 |
| 012079 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:24am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594523.5 | 511537.9 | 48339 | 1.64041666667 | 12079 |
| 011715 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:25am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594525.5 | 511538.8 | 48341 | 1.64041666667 | 11715 |
| 011847 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:26am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594527.7 | 511539.4 | 48343 | 1.64041666667 | 11847 |
| 011494 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:27am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594529.4 | 511539.9 | 48345 | 1.64041666667 | 11494 |
| 013402 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:28am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594531.8 | 511540.3 | 48347 | 1.64041666667 | 13402 |
| 013059 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:29am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594534.1 | 511540.4 | 48349 | 1.64041666667 | 13059 |
| 013690 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:30am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594536.6 | 511541.3 | 48351 | 1.64041666667 | 13690 |
| 013333 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:31am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594538.5 | 511542.3 | 48353 | 1.64041666667 | 13333 |
| 014250 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:32am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594540.2 | 511543.8 | 48355 | 1.64041666667 | 14250 |
| 013393 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:33am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594541.5 | 511544.9 | 48357 | 1.64041666667 | 13393 |
| 014246 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594543.1 | 511546.8 | 48359 | 1.64041666667 | 14246 |
| 014351 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:35am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594544.6 | 511547.9 | 48361 | 1.64041666667 | 14351 |
| 015625 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:36am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594546.5 | 511549.2 | 48363 | 1.64041666667 | 15625 |
| 015209 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:37am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594548.2 | 511550.3 | 48365 | 1.64041666667 | 15209 |
| 015050 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:38am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594550.6 | 511551.5 | 48367 | 1.64041666667 | 15050 |
| 014690 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:39am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594552.5 | 511552.8 | 48369 | 1.64041666667 | 14690 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014451 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:40am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594554.9 | 511553.9 | 48371 | 1.64041666667 | 14451 |
| 014061 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:41am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594556.5 | 511555.0 | 48373 | 1.64041666667 | 14061 |
| 014809 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:42am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594558.5 | 511555.8 | 48375 | 1.64041666667 | 14809 |
| 014570 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:43am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594560.5 | 511555.9 | 48377 | 1.64041666667 | 14570 |
| 014900 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:44am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594563.2 | 511556.2 | 48379 | 1.64041666667 | 14900 |
| 014546 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:45am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594565.3 | 511556.0 | 48381 | 1.64041666667 | 14546 |
| 015120 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:46am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594567.3 | 511556.5 | 48383 | 1.64041666667 | 15120 |
| 015015 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:47am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594569.1 | 511557.1 | 48385 | 1.64041666667 | 15015 |
| 015458 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:48am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594571.6 | 511557.2 | 48387 | 1.64041666667 | 15458 |
| 015265 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:49am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594573.9 | 511557.6 | 48389 | 1.64041666667 | 15265 |
| 014804 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:50am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594576.3 | 511557.4 | 48391 | 1.64041666667 | 14804 |
| 016922 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:51am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594578.2 | 511557.8 | 48393 | 1.64041666667 | 16922 |
| 016373 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:52am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594580.2 | 511558.1 | 48395 | 1.64041666667 | 16373 |
| 014887 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:53am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594582.2 | 511558.3 | 48397 | 1.64041666667 | 14887 |
| 015259 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:54am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594584.5 | 511558.8 | 48399 | 1.64041666667 | 15259 |
| 015693 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:55am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594586.4 | 511558.8 | 48401 | 1.64041666667 | 15693 |
| 015795 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:56am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594588.7 | 511559.1 | 48403 | 1.64041666667 | 15795 |
| 015356 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:57am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594590.7 | 511559.5 | 48405 | 1.64041666667 | 15356 |
| 015874 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:58am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594592.7 | 511560.5 | 48407 | 1.64041666667 | 15874 |
| 014824 | 0 | GeoXH 6000 | 08/19/2015 | 11:34:59am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594594.4 | 511561.6 | 48409 | 1.64041666667 | 14824 |
| 015096 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:00am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594596.3 | 511562.9 | 48411 | 1.64041666667 | 15096 |
| 014656 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:01am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594597.9 | 511564.4 | 48413 | 1.64041666667 | 14656 |
| 014356 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:02am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594600.0 | 511565.7 | 48415 | 1.64041666667 | 14356 |
| 014833 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:03am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594601.9 | 511566.5 | 48417 | 1.64041666667 | 14833 |
| 014478 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:04am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594604.0 | 511567.3 | 48419 | 1.64041666667 | 14478 |
| 015846 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:05am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594606.0 | 511567.5 | 48421 | 1.64041666667 | 15846 |
| 015101 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:06am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594608.6 | 511568.4 | 48423 | 1.64041666667 | 15101 |
| 016549 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:07am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594610.4 | 511568.9 | 48425 | 1.64041666667 | 16549 |
| 015954 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:08am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594611.4 | 511569.4 | 48427 | 1.64041666667 | 15954 |
| 016969 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:09am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594611.0 | 511570.9 | 48429 | 1.64041666667 | 16969 |
| 015770 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:10am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594610.0 | 511572.9 | 48431 | 1.64041666667 | 15770 |
| 015755 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:11am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594609.2 | 511574.7 | 48433 | 1.64041666667 | 15755 |
| 015012 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:12am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594608.0 | 511576.7 | 48435 | 1.64041666667 | 15012 |
| 014609 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:13am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594607.2 | 511578.3 | 48437 | 1.64041666667 | 14609 |
| 014105 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:14am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594606.8 | 511579.8 | 48439 | 1.64041666667 | 14105 |
| 014474 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:15am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594606.3 | 511580.4 | 48441 | 1.64041666667 | 14474 |
| 014734 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:16am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594605.0 | 511579.5 | 48443 | 1.64041666667 | 14734 |
| 014700 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:17am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594603.4 | 511578.6 | 48445 | 1.64041666667 | 14700 |
| 014704 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:18am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594601.5 | 511577.5 | 48447 | 1.64041666667 | 14704 |
| 014728 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:19am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594599.8 | 511576.6 | 48449 | 1.64041666667 | 14728 |
| 014637 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:20am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594597.7 | 511576.3 | 48451 | 1.64041666667 | 14637 |
| 014991 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:21am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594595.8 | 511575.7 | 48453 | 1.64041666667 | 14991 |
| 015595 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:22am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.8 | 511575.2 | 48455 | 1.64041666667 | 15595 |
| 015469 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:23am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594592.0 | 511574.7 | 48457 | 1.64041666667 | 15469 |
| 014814 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:24am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594589.8 | 511574.4 | 48459 | 1.64041666667 | 14814 |
| 014407 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:25am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594588.0 | 511574.1 | 48461 | 1.64041666667 | 14407 |
| 014329 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:26am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594585.9 | 511573.5 | 48463 | 1.64041666667 | 14329 |
| 015200 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:27am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594584.2 | 511573.0 | 48465 | 1.64041666667 | 15200 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016432 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:28am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594582.1 | 511572.0 | 48467 | 1.64041666667 | 16432 |
| 015626 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:29am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594580.3 | 511571.6 | 48469 | 1.64041666667 | 15626 |
| 015982 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:30am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594577.8 | 511570.7 | 48471 | 1.64041666667 | 15982 |
| 014742 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:31am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594576.0 | 511570.1 | 48473 | 1.64041666667 | 14742 |
| 014795 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:32am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594573.8 | 511569.5 | 48475 | 1.64041666667 | 14795 |
| 014434 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:33am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594571.8 | 511568.9 | 48477 | 1.64041666667 | 14434 |
| 014674 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:34am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594569.6 | 511568.6 | 48479 | 1.64041666667 | 14674 |
| 014096 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:35am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594567.6 | 511568.1 | 48481 | 1.64041666667 | 14096 |
| 013764 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:36am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594565.3 | 511567.9 | 48483 | 1.64041666667 | 13764 |
| 013270 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:37am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594563.4 | 511567.6 | 48485 | 1.64041666667 | 13270 |
| 014072 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:38am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594561.0 | 511567.3 | 48487 | 1.64041666667 | 14072 |
| 013465 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:39am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594559.3 | 511567.5 | 48489 | 1.64041666667 | 13465 |
| 013064 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:40am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594557.3 | 511567.8 | 48491 | 1.64041666667 | 13064 |
| 012876 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:41am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594555.7 | 511567.7 | 48493 | 1.64041666667 | 12876 |
| 013077 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:42am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594553.9 | 511566.9 | 48495 | 1.64041666667 | 13077 |
| 012523 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:43am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594552.0 | 511566.6 | 48497 | 1.64041666667 | 12523 |
| 013314 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:44am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594549.9 | 511566.7 | 48499 | 1.64041666667 | 13314 |
| 013317 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:45am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594548.3 | 511566.9 | 48501 | 1.64041666667 | 13317 |
| 012463 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:46am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594546.4 | 511567.8 | 48503 | 1.64041666667 | 12463 |
| 013025 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:47am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594544.8 | 511568.4 | 48505 | 1.64041666667 | 13025 |
| 012412 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:48am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594542.9 | 511568.8 | 48507 | 1.64041666667 | 12412 |
| 012876 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:49am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594541.5 | 511568.8 | 48509 | 1.64041666667 | 12876 |
| 012515 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:50am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594539.4 | 511568.7 | 48511 | 1.64041666667 | 12515 |
| 011465 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:51am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594537.6 | 511568.5 | 48513 | 1.64041666667 | 11465 |
| 011579 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:52am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594536.4 | 511568.6 | 48515 | 1.64041666667 | 11579 |
| 012805 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:53am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594535.7 | 511567.9 | 48517 | 1.64041666667 | 12805 |
| 012010 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:54am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594534.4 | 511567.7 | 48519 | 1.64041666667 | 12010 |
| 012478 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:55am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594533.2 | 511567.4 | 48521 | 1.64041666667 | 12478 |
| 012464 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:56am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594531.5 | 511567.2 | 48523 | 1.64041666667 | 12464 |
| 012058 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:57am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594530.1 | 511566.9 | 48525 | 1.64041666667 | 12058 |
| 012430 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:58am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594528.7 | 511566.1 | 48527 | 1.64041666667 | 12430 |
| 013232 | 0 | GeoXH 6000 | 08/19/2015 | 11:35:59am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594527.3 | 511565.2 | 48529 | 1.64041666667 | 13232 |
| 012910 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:00am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.4 | 511564.0 | 48531 | 1.64041666667 | 12910 |
| 012812 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:01am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594524.0 | 511562.9 | 48533 | 1.64041666667 | 12812 |
| 012434 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:02am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594522.6 | 511560.9 | 48535 | 1.64041666667 | 12434 |
| 012641 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:03am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594521.2 | 511559.7 | 48537 | 1.64041666667 | 12641 |
| 012248 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:04am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594519.6 | 511558.4 | 48539 | 1.64041666667 | 12248 |
| 012447 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:05am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594518.0 | 511557.3 | 48541 | 1.64041666667 | 12447 |
| 012026 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:06am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594516.2 | 511556.7 | 48543 | 1.64041666667 | 12026 |
| 011880 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:07am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594514.1 | 511555.8 | 48545 | 1.64041666667 | 11880 |
| 012082 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:08am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594512.0 | 511555.0 | 48547 | 1.64041666667 | 12082 |
| 011573 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:09am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594510.3 | 511554.0 | 48549 | 1.64041666667 | 11573 |
| 012592 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:10am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594508.4 | 511553.3 | 48551 | 1.64041666667 | 12592 |
| 013376 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:11am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594506.7 | 511552.2 | 48553 | 1.64041666667 | 13376 |
| 012751 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:12am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594504.7 | 511551.2 | 48555 | 1.64041666667 | 12751 |
| 012790 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:13am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594503.0 | 511550.6 | 48557 | 1.64041666667 | 12790 |
| 012692 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:14am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594501.0 | 511549.6 | 48559 | 1.64041666667 | 12692 |
| 012089 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:15am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594499.5 | 511548.9 | 48561 | 1.64041666667 | 12089 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011682 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:16am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594497.8 | 511547.8 | 48563 | 1.64041666667 | 11682 |
| 011971 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:17am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594495.9 | 511547.3 | 48565 | 1.64041666667 | 11971 |
| 012201 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:18am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594493.7 | 511546.4 | 48567 | 1.64041666667 | 12201 |
| 012338 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:19am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594491.7 | 511546.0 | 48569 | 1.64041666667 | 12338 |
| 013285 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:20am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594489.6 | 511545.8 | 48571 | 1.64041666667 | 13285 |
| 013758 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:21am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594487.5 | 511545.6 | 48573 | 1.64041666667 | 13758 |
| 013266 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:22am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594485.5 | 511545.3 | 48575 | 1.64041666667 | 13266 |
| 014107 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:23am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594483.8 | 511545.1 | 48577 | 1.64041666667 | 14107 |
| 014167 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:24am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594482.4 | 511546.7 | 48579 | 1.64041666667 | 14167 |
| 013436 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:25am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594482.1 | 511548.4 | 48581 | 1.64041666667 | 13436 |
| 013138 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:26am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594482.4 | 511550.5 | 48583 | 1.64041666667 | 13138 |
| 013083 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:27am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594482.2 | 511552.6 | 48585 | 1.64041666667 | 13083 |
| 014026 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:28am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594482.5 | 511554.5 | 48587 | 1.64041666667 | 14026 |
| 013072 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:29am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594483.0 | 511555.9 | 48589 | 1.64041666667 | 13072 |
| 013383 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:30am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594484.1 | 511556.6 | 48591 | 1.64041666667 | 13383 |
| 013040 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:31am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594485.7 | 511556.8 | 48593 | 1.64041666667 | 13040 |
| 012487 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:32am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594487.7 | 511556.5 | 48595 | 1.64041666667 | 12487 |
| 013211 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:33am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594489.5 | 511556.1 | 48597 | 1.64041666667 | 13211 |
| 013634 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:34am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594491.6 | 511556.3 | 48599 | 1.64041666667 | 13634 |
| 013099 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:35am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594493.5 | 511556.2 | 48601 | 1.64041666667 | 13099 |
| 012453 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:36am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594495.5 | 511556.3 | 48603 | 1.64041666667 | 12453 |
| 013695 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:37am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594497.4 | 511556.5 | 48605 | 1.64041666667 | 13695 |
| 012856 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:38am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594499.4 | 511557.1 | 48607 | 1.64041666667 | 12856 |
| 012376 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:39am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594500.8 | 511557.9 | 48609 | 1.64041666667 | 12376 |
| 013509 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:40am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594502.6 | 511558.9 | 48611 | 1.64041666667 | 13509 |
| 013644 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:41am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594504.4 | 511560.0 | 48613 | 1.64041666667 | 13644 |
| 013374 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:42am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594506.2 | 511560.8 | 48615 | 1.64041666667 | 13374 |
| 013493 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:43am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594507.8 | 511561.8 | 48617 | 1.64041666667 | 13493 |
| 012517 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:44am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594509.8 | 511562.5 | 48619 | 1.64041666667 | 12517 |
| 013498 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:45am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594511.7 | 511563.4 | 48621 | 1.64041666667 | 13498 |
| 013953 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:46am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594513.7 | 511564.2 | 48623 | 1.64041666667 | 13953 |
| 013346 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:47am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594515.4 | 511564.8 | 48625 | 1.64041666667 | 13346 |
| 013522 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:48am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594517.5 | 511565.7 | 48627 | 1.64041666667 | 13522 |
| 013373 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:49am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594519.1 | 511566.4 | 48629 | 1.64041666667 | 13373 |
| 012997 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:50am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594521.1 | 511567.4 | 48631 | 1.64041666667 | 12997 |
| 013341 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:51am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594522.9 | 511568.0 | 48633 | 1.64041666667 | 13341 |
| 013302 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:52am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594524.5 | 511569.3 | 48635 | 1.64041666667 | 13302 |
| 012529 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:53am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594525.9 | 511570.4 | 48637 | 1.64041666667 | 12529 |
| 012208 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:54am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594527.6 | 511571.6 | 48639 | 1.64041666667 | 12208 |
| 012357 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:55am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594529.3 | 511572.6 | 48641 | 1.64041666667 | 12357 |
| 012718 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:56am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594531.0 | 511573.7 | 48643 | 1.64041666667 | 12718 |
| 012749 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:57am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594532.6 | 511575.0 | 48645 | 1.64041666667 | 12749 |
| 013126 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:58am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594535.0 | 511575.8 | 48647 | 1.64041666667 | 13126 |
| 012543 | 0 | GeoXH 6000 | 08/19/2015 | 11:36:59am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594537.1 | 511577.0 | 48649 | 1.64041666667 | 12543 |
| 012980 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:00am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594539.0 | 511578.0 | 48651 | 1.64041666667 | 12980 |
| 012499 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:01am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594540.8 | 511578.7 | 48653 | 1.64041666667 | 12499 |
| 012828 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:02am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594543.0 | 511579.5 | 48655 | 1.64041666667 | 12828 |
| 012518 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:03am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594545.2 | 511579.2 | 48657 | 1.64041666667 | 12518 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013836 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:04am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594547.3 | 511579.0 | 48659 | 1.64041666667 | 13836 |
| 013678 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:05am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594549.1 | 511579.1 | 48661 | 1.64041666667 | 13678 |
| 013304 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:06am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594551.3 | 511578.9 | 48663 | 1.64041666667 | 13304 |
| 014346 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:07am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594553.5 | 511578.9 | 48665 | 1.64041666667 | 14346 |
| 014977 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:08am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594555.6 | 511578.3 | 48667 | 1.64041666667 | 14977 |
| 014109 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:09am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594557.5 | 511577.7 | 48669 | 1.64041666667 | 14109 |
| 013231 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:10am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594559.8 | 511577.4 | 48671 | 1.64041666667 | 13231 |
| 013277 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:11am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594561.8 | 511577.2 | 48673 | 1.64041666667 | 13277 |
| 012306 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:12am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594563.9 | 511578.0 | 48675 | 1.64041666667 | 12306 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:13am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594565.9 | 511578.7 | 48677 | 1.64041666667 | 12787 |
| 012832 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:14am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594567.7 | 511579.4 | 48679 | 1.64041666667 | 12832 |
| 013361 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:15am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594569.4 | 511580.1 | 48681 | 1.64041666667 | 13361 |
| 014243 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:16am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594571.6 | 511580.7 | 48683 | 1.64041666667 | 14243 |
| 014956 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:17am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594573.5 | 511581.5 | 48685 | 1.64041666667 | 14956 |
| 015163 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:18am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594575.6 | 511581.9 | 48687 | 1.64041666667 | 15163 |
| 014296 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:19am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594577.9 | 511582.3 | 48689 | 1.64041666667 | 14296 |
| 015121 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:20am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594580.3 | 511582.2 | 48691 | 1.64041666667 | 15121 |
| 015323 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:21am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594582.2 | 511581.9 | 48693 | 1.64041666667 | 15323 |
| 014777 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:22am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594583.9 | 511581.8 | 48695 | 1.64041666667 | 14777 |
| 014867 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:23am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594584.9 | 511581.5 | 48697 | 1.64041666667 | 14867 |
| 014197 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:24am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594586.3 | 511581.2 | 48699 | 1.64041666667 | 14197 |
| 014346 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:25am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594587.7 | 511580.7 | 48701 | 1.64041666667 | 14346 |
| 014317 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:26am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594590.3 | 511580.5 | 48703 | 1.64041666667 | 14317 |
| 013776 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:27am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594592.5 | 511580.1 | 48705 | 1.64041666667 | 13776 |
| 013816 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:28am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594594.5 | 511579.6 | 48707 | 1.64041666667 | 13816 |
| 014671 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:29am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594596.4 | 511579.9 | 48709 | 1.64041666667 | 14671 |
| 015475 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:30am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594598.8 | 511580.6 | 48711 | 1.64041666667 | 15475 |
| 015169 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:31am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594600.3 | 511581.7 | 48713 | 1.64041666667 | 15169 |
| 014555 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:32am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594601.8 | 511583.3 | 48715 | 1.64041666667 | 14555 |
| 014180 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:33am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594602.7 | 511584.7 | 48717 | 1.64041666667 | 14180 |
| 014313 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:34am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594603.1 | 511586.8 | 48719 | 1.64041666667 | 14313 |
| 013286 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:35am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594603.7 | 511588.6 | 48721 | 1.64041666667 | 13286 |
| 013871 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:36am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594604.1 | 511590.7 | 48723 | 1.64041666667 | 13871 |
| 014333 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:37am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594604.1 | 511592.6 | 48725 | 1.64041666667 | 14333 |
| 014985 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:38am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594603.4 | 511594.4 | 48727 | 1.64041666667 | 14985 |
| 014069 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:39am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594602.2 | 511595.8 | 48729 | 1.64041666667 | 14069 |
| 014603 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:40am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594601.0 | 511597.1 | 48731 | 1.64041666667 | 14603 |
| 014499 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:41am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594599.3 | 511597.7 | 48733 | 1.64041666667 | 14499 |
| 015618 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:42am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594597.3 | 511598.0 | 48735 | 1.64041666667 | 15618 |
| 015513 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:43am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594595.8 | 511597.8 | 48737 | 1.64041666667 | 15513 |
| 016511 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:44am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594594.5 | 511597.3 | 48739 | 1.64041666667 | 16511 |
| 015400 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:45am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.7 | 511597.3 | 48741 | 1.64041666667 | 15400 |
| 016245 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:46am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594594.0 | 511596.9 | 48743 | 1.64041666667 | 16245 |
| 015865 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:47am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.8 | 511596.8 | 48745 | 1.64041666667 | 15865 |
| 014879 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:48am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.5 | 511596.7 | 48747 | 1.64041666667 | 14879 |
| 015209 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:49am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.5 | 511596.7 | 48749 | 1.64041666667 | 15209 |
| 016325 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:50am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594593.5 | 511596.8 | 48751 | 1.64041666667 | 16325 |
| 016015 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:51am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594594.0 | 511597.0 | 48753 | 1.64041666667 | 16015 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014851 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:52am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594594.4 | 511597.0 | 48755 | 1.64041666667 | 14851 |
| 015366 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:53am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594594.5 | 511597.0 | 48757 | 1.64041666667 | 15366 |
| 015311 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:54am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594594.4 | 511596.9 | 48759 | 1.64041666667 | 15311 |
| 017200 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:55am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.9 | 511596.6 | 48761 | 1.64041666667 | 17200 |
| 017122 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:56am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.6 | 511596.3 | 48763 | 1.64041666667 | 17122 |
| 017483 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:57am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.5 | 511596.4 | 48765 | 1.64041666667 | 17483 |
| 017192 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:58am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.5 | 511596.7 | 48767 | 1.64041666667 | 17192 |
| 017605 | 0 | GeoXH 6000 | 08/19/2015 | 11:37:59am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.4 | 511596.9 | 48769 | 1.64041666667 | 17605 |
| 016270 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:00am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.1 | 511596.9 | 48771 | 1.64041666667 | 16270 |
| 015744 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:01am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594592.9 | 511596.7 | 48773 | 1.64041666667 | 15744 |
| 015711 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:02am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594592.9 | 511596.6 | 48775 | 1.64041666667 | 15711 |
| 016247 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:03am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594592.9 | 511596.7 | 48777 | 1.64041666667 | 16247 |
| 016151 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:04am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594592.6 | 511596.8 | 48779 | 1.64041666667 | 16151 |
| 016968 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:05am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594592.5 | 511596.8 | 48781 | 1.64041666667 | 16968 |
| 017291 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:06am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594592.7 | 511596.7 | 48783 | 1.64041666667 | 17291 |
| 017256 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:07am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594592.5 | 511596.8 | 48785 | 1.64041666667 | 17256 |
| 016832 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:08am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594591.8 | 511597.4 | 48787 | 1.64041666667 | 16832 |
| 016810 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:09am | Sensor | 1797-S0037-905-G-ACK | 6820.8 | 1594591.4 | 511598.0 | 48789 | 1.64041666667 | 16810 |
| 017263 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:10am | Sensor | 1797-S0037-905-G-ACK | 6820.6 | 1594591.3 | 511598.0 | 48791 | 1.64041666667 | 17263 |
| 016888 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:11am | Sensor | 1797-S0037-905-G-ACK | 6821.0 | 1594591.5 | 511597.8 | 48793 | 1.64041666667 | 16888 |
| 016647 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:12am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594592.4 | 511597.2 | 48795 | 1.64041666667 | 16647 |
| 017089 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:13am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594593.3 | 511596.8 | 48797 | 1.64041666667 | 17089 |
| 016340 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:14am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594593.6 | 511596.7 | 48799 | 1.64041666667 | 16340 |
| 015866 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:15am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.4 | 511596.3 | 48801 | 1.64041666667 | 15866 |
| 015135 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:16am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594592.1 | 511596.4 | 48803 | 1.64041666667 | 15135 |
| 015023 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:17am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594590.7 | 511596.6 | 48805 | 1.64041666667 | 15023 |
| 013693 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:18am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594588.6 | 511596.0 | 48807 | 1.64041666667 | 13693 |
| 013207 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:19am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594586.7 | 511595.7 | 48809 | 1.64041666667 | 13207 |
| 012619 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:20am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594584.7 | 511594.6 | 48811 | 1.64041666667 | 12619 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:21am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594582.9 | 511593.7 | 48813 | 1.64041666667 | 12760 |
| 013965 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:22am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594581.3 | 511592.6 | 48815 | 1.64041666667 | 13965 |
| 013578 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:23am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594579.8 | 511591.6 | 48817 | 1.64041666667 | 13578 |
| 013570 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:24am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594578.0 | 511590.6 | 48819 | 1.64041666667 | 13570 |
| 014083 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:25am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594576.5 | 511589.9 | 48821 | 1.64041666667 | 14083 |
| 015286 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:26am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594574.5 | 511589.8 | 48823 | 1.64041666667 | 15286 |
| 014868 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:27am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594572.8 | 511589.5 | 48825 | 1.64041666667 | 14868 |
| 014903 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:28am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594570.8 | 511589.6 | 48827 | 1.64041666667 | 14903 |
| 014443 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:29am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594569.0 | 511589.9 | 48829 | 1.64041666667 | 14443 |
| 014589 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:30am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594567.0 | 511590.9 | 48831 | 1.64041666667 | 14589 |
| 014131 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:31am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594565.4 | 511591.6 | 48833 | 1.64041666667 | 14131 |
| 013679 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:32am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594563.3 | 511592.0 | 48835 | 1.64041666667 | 13679 |
| 013544 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:33am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594561.8 | 511592.1 | 48837 | 1.64041666667 | 13544 |
| 012958 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:34am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594560.1 | 511591.4 | 48839 | 1.64041666667 | 12958 |
| 013597 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:35am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594558.3 | 511590.6 | 48841 | 1.64041666667 | 13597 |
| 013250 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:36am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594556.5 | 511589.5 | 48843 | 1.64041666667 | 13250 |
| 012628 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:37am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594554.7 | 511588.9 | 48845 | 1.64041666667 | 12628 |
| 014168 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:38am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594552.7 | 511587.9 | 48847 | 1.64041666667 | 14168 |
| 014629 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:39am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594550.9 | 511587.2 | 48849 | 1.64041666667 | 14629 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013764 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:40am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594548.7 | 511586.4 | 48851 | 1.64041666667 | 13764 |
| 013839 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:41am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594546.8 | 511585.7 | 48853 | 1.64041666667 | 13839 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:42am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594544.7 | 511585.0 | 48855 | 1.64041666667 | 12787 |
| 013335 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:43am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594543.1 | 511584.3 | 48857 | 1.64041666667 | 13335 |
| 013486 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:44am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594541.1 | 511583.8 | 48859 | 1.64041666667 | 13486 |
| 013511 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:45am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594539.2 | 511583.6 | 48861 | 1.64041666667 | 13511 |
| 014095 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:46am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594536.9 | 511584.2 | 48863 | 1.64041666667 | 14095 |
| 013185 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:47am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594535.2 | 511584.5 | 48865 | 1.64041666667 | 13185 |
| 012862 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:48am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594533.4 | 511584.6 | 48867 | 1.64041666667 | 12862 |
| 012815 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:49am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594531.9 | 511584.6 | 48869 | 1.64041666667 | 12815 |
| 013155 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:50am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594530.2 | 511584.2 | 48871 | 1.64041666667 | 13155 |
| 012552 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:51am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594528.4 | 511584.1 | 48873 | 1.64041666667 | 12552 |
| 013181 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:52am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594526.4 | 511583.3 | 48875 | 1.64041666667 | 13181 |
| 012221 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:53am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594524.5 | 511583.1 | 48877 | 1.64041666667 | 12221 |
| 012597 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:54am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594522.3 | 511582.7 | 48879 | 1.64041666667 | 12597 |
| 013431 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:55am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594520.5 | 511582.5 | 48881 | 1.64041666667 | 13431 |
| 013442 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:56am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594518.4 | 511582.0 | 48883 | 1.64041666667 | 13442 |
| 012968 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:57am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594516.8 | 511580.9 | 48885 | 1.64041666667 | 12968 |
| 013175 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:58am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594514.8 | 511580.1 | 48887 | 1.64041666667 | 13175 |
| 012135 | 0 | GeoXH 6000 | 08/19/2015 | 11:38:59am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594513.3 | 511579.2 | 48889 | 1.64041666667 | 12135 |
| 011941 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:00am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594511.5 | 511578.0 | 48891 | 1.64041666667 | 11941 |
| 011899 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:01am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594509.9 | 511576.9 | 48893 | 1.64041666667 | 11899 |
| 012386 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:02am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594508.3 | 511575.8 | 48895 | 1.64041666667 | 12386 |
| 012974 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:03am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594506.3 | 511575.4 | 48897 | 1.64041666667 | 12974 |
| 013298 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:04am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594504.2 | 511574.8 | 48899 | 1.64041666667 | 13298 |
| 012325 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:05am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594501.9 | 511574.7 | 48901 | 1.64041666667 | 12325 |
| 013008 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:06am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594499.9 | 511574.4 | 48903 | 1.64041666667 | 13008 |
| 012837 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:07am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594498.0 | 511574.0 | 48905 | 1.64041666667 | 12837 |
| 012208 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:08am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594496.1 | 511573.7 | 48907 | 1.64041666667 | 12208 |
| 012522 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:09am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594494.0 | 511573.0 | 48909 | 1.64041666667 | 12522 |
| 012526 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:10am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594491.9 | 511572.2 | 48911 | 1.64041666667 | 12526 |
| 012588 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:11am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594489.9 | 511571.5 | 48913 | 1.64041666667 | 12588 |
| 012278 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:12am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594487.8 | 511571.5 | 48915 | 1.64041666667 | 12278 |
| 013221 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:13am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594485.4 | 511571.3 | 48917 | 1.64041666667 | 13221 |
| 012327 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:14am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594483.1 | 511571.4 | 48919 | 1.64041666667 | 12327 |
| 013421 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:15am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594480.9 | 511571.3 | 48921 | 1.64041666667 | 13421 |
| 013234 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:16am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594479.1 | 511571.1 | 48923 | 1.64041666667 | 13234 |
| 012642 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:17am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594477.3 | 511571.1 | 48925 | 1.64041666667 | 12642 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:18am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594475.2 | 511570.8 | 48927 | 1.64041666667 | 12743 |
| 012860 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:19am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594473.3 | 511570.8 | 48929 | 1.64041666667 | 12860 |
| 013826 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:20am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594471.5 | 511571.0 | 48931 | 1.64041666667 | 13826 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:21am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594470.1 | 511572.1 | 48933 | 1.64041666667 | 12180 |
| 012633 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:22am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594468.7 | 511573.9 | 48935 | 1.64041666667 | 12633 |
| 012866 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:23am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594467.9 | 511575.4 | 48937 | 1.64041666667 | 12866 |
| 012195 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:24am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594467.5 | 511577.4 | 48939 | 1.64041666667 | 12195 |
| 011562 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:25am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594467.7 | 511579.2 | 48941 | 1.64041666667 | 11562 |
| 011798 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:26am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594468.2 | 511581.3 | 48943 | 1.64041666667 | 11798 |
| 012314 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:27am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594468.4 | 511583.4 | 48945 | 1.64041666667 | 12314 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013331 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:28am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594469.8 | 511585.0 | 48947 | 1.64041666667 | 13331 |
| 012944 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:29am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594471.4 | 511585.5 | 48949 | 1.64041666667 | 12944 |
| 012141 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:30am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594473.4 | 511584.6 | 48951 | 1.64041666667 | 12141 |
| 012064 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:31am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594475.1 | 511584.2 | 48953 | 1.64041666667 | 12064 |
| 012628 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:32am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594476.8 | 511583.7 | 48955 | 1.64041666667 | 12628 |
| 013628 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:33am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594478.4 | 511583.3 | 48957 | 1.64041666667 | 13628 |
| 013298 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594480.3 | 511582.7 | 48959 | 1.64041666667 | 13298 |
| 014005 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:35am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594481.9 | 511582.0 | 48961 | 1.64041666667 | 14005 |
| 013270 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:36am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594483.9 | 511581.3 | 48963 | 1.64041666667 | 13270 |
| 012902 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:37am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594485.6 | 511580.5 | 48965 | 1.64041666667 | 12902 |
| 012815 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:38am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594487.6 | 511579.7 | 48967 | 1.64041666667 | 12815 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:39am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594489.5 | 511578.8 | 48969 | 1.64041666667 | 12255 |
| 012174 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:40am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594491.6 | 511578.7 | 48971 | 1.64041666667 | 12174 |
| 011662 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:41am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594493.5 | 511579.2 | 48973 | 1.64041666667 | 11662 |
| 012252 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:42am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594495.8 | 511579.8 | 48975 | 1.64041666667 | 12252 |
| 011992 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:43am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594497.6 | 511580.7 | 48977 | 1.64041666667 | 11992 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:44am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594499.8 | 511581.4 | 48979 | 1.64041666667 | 12768 |
| 011922 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:45am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594501.5 | 511581.9 | 48981 | 1.64041666667 | 11922 |
| 012616 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:46am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594503.4 | 511583.2 | 48983 | 1.64041666667 | 12616 |
| 012684 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:47am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594505.4 | 511583.8 | 48985 | 1.64041666667 | 12684 |
| 013899 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:48am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594507.5 | 511585.1 | 48987 | 1.64041666667 | 13899 |
| 012836 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:49am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594509.6 | 511585.6 | 48989 | 1.64041666667 | 12836 |
| 012770 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:50am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594511.6 | 511586.4 | 48991 | 1.64041666667 | 12770 |
| 012028 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:51am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594513.2 | 511587.1 | 48993 | 1.64041666667 | 12028 |
| 011858 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:52am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594515.3 | 511587.7 | 48995 | 1.64041666667 | 11858 |
| 012723 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:53am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594517.4 | 511588.7 | 48997 | 1.64041666667 | 12723 |
| 012616 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:54am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594519.9 | 511589.4 | 48999 | 1.64041666667 | 12616 |
| 012369 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:55am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594522.0 | 511590.6 | 49001 | 1.64041666667 | 12369 |
| 012432 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:56am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594524.0 | 511592.0 | 49003 | 1.64041666667 | 12432 |
| 012896 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:57am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594525.8 | 511592.9 | 49005 | 1.64041666667 | 12896 |
| 012466 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:58am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594528.3 | 511594.1 | 49007 | 1.64041666667 | 12466 |
| 012390 | 0 | GeoXH 6000 | 08/19/2015 | 11:39:59am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594530.5 | 511594.5 | 49009 | 1.64041666667 | 12390 |
| 011341 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:00am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594533.1 | 511595.4 | 49011 | 1.64041666667 | 11341 |
| 012049 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:01am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594535.0 | 511596.2 | 49013 | 1.64041666667 | 12049 |
| 012035 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:02am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594537.4 | 511596.8 | 49015 | 1.64041666667 | 12035 |
| 012604 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:03am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594539.7 | 511597.8 | 49017 | 1.64041666667 | 12604 |
| 012497 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:04am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594542.0 | 511597.8 | 49019 | 1.64041666667 | 12497 |
| 012655 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:05am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594543.7 | 511598.1 | 49021 | 1.64041666667 | 12655 |
| 013051 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:06am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594545.5 | 511598.8 | 49023 | 1.64041666667 | 13051 |
| 012456 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:07am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594547.3 | 511599.3 | 49025 | 1.64041666667 | 12456 |
| 012999 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:08am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594549.4 | 511600.3 | 49027 | 1.64041666667 | 12999 |
| 013019 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:09am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594551.5 | 511600.8 | 49029 | 1.64041666667 | 13019 |
| 013758 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:10am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594554.0 | 511601.5 | 49031 | 1.64041666667 | 13758 |
| 014436 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:11am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594556.3 | 511601.4 | 49033 | 1.64041666667 | 14436 |
| 013588 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:12am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594558.8 | 511601.6 | 49035 | 1.64041666667 | 13588 |
| 013335 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:13am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594560.8 | 511602.0 | 49037 | 1.64041666667 | 13335 |
| 012781 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:14am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594563.1 | 511602.3 | 49039 | 1.64041666667 | 12781 |
| 013864 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:15am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594565.2 | 511602.8 | 49041 | 1.64041666667 | 13864 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013296 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:16am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594567.4 | 511603.0 | 49043 | 1.64041666667 | 13296 |
| 013284 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:17am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594569.5 | 511603.6 | 49045 | 1.64041666667 | 13284 |
| 014162 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:18am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594572.1 | 511603.6 | 49047 | 1.64041666667 | 14162 |
| 013786 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:19am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594574.3 | 511603.8 | 49049 | 1.64041666667 | 13786 |
| 014197 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:20am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594576.5 | 511604.3 | 49051 | 1.64041666667 | 14197 |
| 013491 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:21am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594578.5 | 511604.5 | 49053 | 1.64041666667 | 13491 |
| 013206 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:22am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594580.5 | 511605.2 | 49055 | 1.64041666667 | 13206 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:23am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594582.6 | 511605.4 | 49057 | 1.64041666667 | 13593 |
| 013751 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:24am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594584.9 | 511605.7 | 49059 | 1.64041666667 | 13751 |
| 013607 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:25am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594586.7 | 511605.9 | 49061 | 1.64041666667 | 13607 |
| 013714 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:26am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594588.5 | 511605.9 | 49063 | 1.64041666667 | 13714 |
| 013639 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:27am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594589.9 | 511606.8 | 49065 | 1.64041666667 | 13639 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:28am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594590.6 | 511608.0 | 49067 | 1.64041666667 | 12787 |
| 012825 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:29am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594589.8 | 511609.4 | 49069 | 1.64041666667 | 12825 |
| 012891 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:30am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594588.5 | 511611.2 | 49071 | 1.64041666667 | 12891 |
| 012974 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:31am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594587.2 | 511612.6 | 49073 | 1.64041666667 | 12974 |
| 013897 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:32am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594585.3 | 511614.1 | 49075 | 1.64041666667 | 13897 |
| 013090 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:33am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594584.1 | 511615.5 | 49077 | 1.64041666667 | 13090 |
| 012845 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:34am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594582.5 | 511616.8 | 49079 | 1.64041666667 | 12845 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:35am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594581.4 | 511617.5 | 49081 | 1.64041666667 | 12078 |
| 012164 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:36am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594580.9 | 511618.2 | 49083 | 1.64041666667 | 12164 |
| 012459 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:37am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594580.1 | 511618.0 | 49085 | 1.64041666667 | 12459 |
| 012318 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:38am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594578.2 | 511617.9 | 49087 | 1.64041666667 | 12318 |
| 012861 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:39am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594576.5 | 511617.4 | 49089 | 1.64041666667 | 12861 |
| 012874 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:40am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594574.4 | 511616.0 | 49091 | 1.64041666667 | 12874 |
| 012469 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:41am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594572.4 | 511615.2 | 49093 | 1.64041666667 | 12469 |
| 012624 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:42am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594570.3 | 511614.2 | 49095 | 1.64041666667 | 12624 |
| 012883 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:43am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594568.2 | 511613.5 | 49097 | 1.64041666667 | 12883 |
| 012819 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:44am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594566.0 | 511612.4 | 49099 | 1.64041666667 | 12819 |
| 012326 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:45am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594564.2 | 511611.3 | 49101 | 1.64041666667 | 12326 |
| 012326 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:46am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594562.0 | 511610.1 | 49103 | 1.64041666667 | 12326 |
| 012243 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:47am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594560.4 | 511608.6 | 49105 | 1.64041666667 | 12243 |
| 012857 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:48am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594558.4 | 511607.9 | 49107 | 1.64041666667 | 12857 |
| 013404 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:49am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594556.3 | 511607.5 | 49109 | 1.64041666667 | 13404 |
| 013772 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:50am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594553.9 | 511607.1 | 49111 | 1.64041666667 | 13772 |
| 013342 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:51am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594551.9 | 511607.0 | 49113 | 1.64041666667 | 13342 |
| 013565 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:52am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594549.2 | 511606.9 | 49115 | 1.64041666667 | 13565 |
| 012895 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:53am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594547.0 | 511607.4 | 49117 | 1.64041666667 | 12895 |
| 012728 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:54am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594544.7 | 511607.4 | 49119 | 1.64041666667 | 12728 |
| 013624 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:55am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594542.9 | 511607.3 | 49121 | 1.64041666667 | 13624 |
| 013529 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:56am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594540.5 | 511607.4 | 49123 | 1.64041666667 | 13529 |
| 013070 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:57am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594538.3 | 511606.8 | 49125 | 1.64041666667 | 13070 |
| 012834 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:58am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594536.0 | 511606.2 | 49127 | 1.64041666667 | 12834 |
| 013316 | 0 | GeoXH 6000 | 08/19/2015 | 11:40:59am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594534.1 | 511605.2 | 49129 | 1.64041666667 | 13316 |
| 013618 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:00am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594531.7 | 511603.8 | 49131 | 1.64041666667 | 13618 |
| 012985 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:01am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594529.8 | 511603.1 | 49133 | 1.64041666667 | 12985 |
| 012981 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:02am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594527.5 | 511602.0 | 49135 | 1.64041666667 | 12981 |
| 012447 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:03am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594525.5 | 511601.4 | 49137 | 1.64041666667 | 12447 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012356 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:04am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594523.3 | 511600.5 | 49139 | 1.64041666667 | 12356 |
| 012823 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:05am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594521.3 | 511600.2 | 49141 | 1.64041666667 | 12823 |
| 012215 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:06am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594518.7 | 511600.7 | 49143 | 1.64041666667 | 12215 |
| 011551 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:07am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594516.7 | 511600.4 | 49145 | 1.64041666667 | 11551 |
| 012317 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:08am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594514.5 | 511600.2 | 49147 | 1.64041666667 | 12317 |
| 011976 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:09am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594512.5 | 511600.0 | 49149 | 1.64041666667 | 11976 |
| 013089 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:10am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594510.3 | 511599.7 | 49151 | 1.64041666667 | 13089 |
| 012807 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:11am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594508.4 | 511599.5 | 49153 | 1.64041666667 | 12807 |
| 013301 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:12am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594506.2 | 511598.9 | 49155 | 1.64041666667 | 13301 |
| 012184 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:13am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594504.3 | 511598.5 | 49157 | 1.64041666667 | 12184 |
| 012914 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:14am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594502.5 | 511596.8 | 49159 | 1.64041666667 | 12914 |
| 013436 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:15am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594501.3 | 511595.3 | 49161 | 1.64041666667 | 13436 |
| 012763 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:16am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594499.7 | 511593.9 | 49163 | 1.64041666667 | 12763 |
| 013066 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:17am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594498.5 | 511592.5 | 49165 | 1.64041666667 | 13066 |
| 012352 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:18am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594496.2 | 511591.5 | 49167 | 1.64041666667 | 12352 |
| 012310 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:19am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594494.1 | 511590.3 | 49169 | 1.64041666667 | 12310 |
| 012429 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:20am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594491.8 | 511589.3 | 49171 | 1.64041666667 | 12429 |
| 012594 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:21am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594489.8 | 511588.9 | 49173 | 1.64041666667 | 12594 |
| 012064 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:22am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594487.4 | 511588.8 | 49175 | 1.64041666667 | 12064 |
| 011991 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:23am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594485.5 | 511589.2 | 49177 | 1.64041666667 | 11991 |
| 012017 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:24am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594483.1 | 511589.4 | 49179 | 1.64041666667 | 12017 |
| 012377 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:25am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594481.1 | 511590.0 | 49181 | 1.64041666667 | 12377 |
| 012392 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:26am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594479.0 | 511590.7 | 49183 | 1.64041666667 | 12392 |
| 012333 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:27am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594476.8 | 511590.9 | 49185 | 1.64041666667 | 12333 |
| 011790 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:28am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594474.7 | 511591.4 | 49187 | 1.64041666667 | 11790 |
| 011716 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:29am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594472.9 | 511591.6 | 49189 | 1.64041666667 | 11716 |
| 011698 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:30am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594470.9 | 511592.1 | 49191 | 1.64041666667 | 11698 |
| 012452 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:31am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594468.9 | 511592.2 | 49193 | 1.64041666667 | 12452 |
| 013042 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:32am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594466.4 | 511591.9 | 49195 | 1.64041666667 | 13042 |
| 012563 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:33am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594464.4 | 511591.8 | 49197 | 1.64041666667 | 12563 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:34am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594462.6 | 511591.4 | 49199 | 1.64041666667 | 14049 |
| 013130 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:35am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594461.0 | 511591.8 | 49201 | 1.64041666667 | 13130 |
| 012755 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:36am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594459.4 | 511592.9 | 49203 | 1.64041666667 | 12755 |
| 012177 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:37am | Sensor | 1797-S0037-905-G-ACK | 6821.4 | 1594458.5 | 511594.6 | 49205 | 1.64041666667 | 12177 |
| 011950 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:38am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594457.9 | 511596.7 | 49207 | 1.64041666667 | 11950 |
| 011739 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:39am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594457.8 | 511598.8 | 49209 | 1.64041666667 | 11739 |
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:40am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594458.8 | 511600.7 | 49211 | 1.64041666667 | 12183 |
| 012463 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:41am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594460.1 | 511601.6 | 49213 | 1.64041666667 | 12463 |
| 012335 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:42am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594462.1 | 511601.7 | 49215 | 1.64041666667 | 12335 |
| 011663 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:43am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594464.4 | 511602.1 | 49217 | 1.64041666667 | 11663 |
| 012185 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:44am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594466.6 | 511602.1 | 49219 | 1.64041666667 | 12185 |
| 012404 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:45am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594468.3 | 511602.1 | 49221 | 1.64041666667 | 12404 |
| 012625 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:46am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594470.0 | 511602.2 | 49223 | 1.64041666667 | 12625 |
| 012314 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:47am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594471.6 | 511601.6 | 49225 | 1.64041666667 | 12314 |
| 012184 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:48am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594473.6 | 511601.6 | 49227 | 1.64041666667 | 12184 |
| 012913 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:49am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594475.7 | 511601.4 | 49229 | 1.64041666667 | 12913 |
| 012176 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:50am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594477.8 | 511601.4 | 49231 | 1.64041666667 | 12176 |
| 011979 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:51am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594480.0 | 511601.4 | 49233 | 1.64041666667 | 11979 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012040 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:52am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594482.4 | 511601.1 | 49235 | 1.64041666667 | 12040 |
| 012847 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:53am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594484.5 | 511601.2 | 49237 | 1.64041666667 | 12847 |
| 012994 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:54am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594487.2 | 511600.8 | 49239 | 1.64041666667 | 12994 |
| 012334 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:55am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594489.4 | 511601.0 | 49241 | 1.64041666667 | 12334 |
| 012338 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:56am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594491.8 | 511601.2 | 49243 | 1.64041666667 | 12338 |
| 012730 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:57am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594493.9 | 511601.6 | 49245 | 1.64041666667 | 12730 |
| 012283 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:58am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594495.8 | 511602.1 | 49247 | 1.64041666667 | 12283 |
| 011619 | 0 | GeoXH 6000 | 08/19/2015 | 11:41:59am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594498.2 | 511602.5 | 49249 | 1.64041666667 | 11619 |
| 011816 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:00am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594500.6 | 511603.1 | 49251 | 1.64041666667 | 11816 |
| 012301 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:01am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594502.7 | 511603.2 | 49253 | 1.64041666667 | 12301 |
| 012739 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:02am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594504.9 | 511603.9 | 49255 | 1.64041666667 | 12739 |
| 012611 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:03am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594506.5 | 511605.0 | 49257 | 1.64041666667 | 12611 |
| 012463 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:04am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594508.6 | 511605.8 | 49259 | 1.64041666667 | 12463 |
| 012298 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:05am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594511.0 | 511606.9 | 49261 | 1.64041666667 | 12298 |
| 013375 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:06am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594513.3 | 511607.4 | 49263 | 1.64041666667 | 13375 |
| 013283 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:07am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594515.4 | 511608.1 | 49265 | 1.64041666667 | 13283 |
| 012054 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:08am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594517.5 | 511609.3 | 49267 | 1.64041666667 | 12054 |
| 012765 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:09am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594519.3 | 511610.2 | 49269 | 1.64041666667 | 12765 |
| 011748 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:10am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594521.4 | 511611.6 | 49271 | 1.64041666667 | 11748 |
| 012053 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:11am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594523.1 | 511612.6 | 49273 | 1.64041666667 | 12053 |
| 012555 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:12am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594525.1 | 511613.1 | 49275 | 1.64041666667 | 12555 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:13am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594527.2 | 511613.5 | 49277 | 1.64041666667 | 12626 |
| 012825 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:14am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594529.8 | 511613.3 | 49279 | 1.64041666667 | 12825 |
| 013079 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:15am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594531.9 | 511613.3 | 49281 | 1.64041666667 | 13079 |
| 013409 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:16am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594534.3 | 511613.1 | 49283 | 1.64041666667 | 13409 |
| 012327 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:17am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594536.4 | 511613.3 | 49285 | 1.64041666667 | 12327 |
| 012154 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:18am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594538.6 | 511613.5 | 49287 | 1.64041666667 | 12154 |
| 012469 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:19am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594540.8 | 511613.6 | 49289 | 1.64041666667 | 12469 |
| 012916 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:20am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594543.2 | 511614.2 | 49291 | 1.64041666667 | 12916 |
| 012935 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:21am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594545.1 | 511614.5 | 49293 | 1.64041666667 | 12935 |
| 012121 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:22am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594547.2 | 511615.7 | 49295 | 1.64041666667 | 12121 |
| 011880 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:23am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594549.5 | 511616.9 | 49297 | 1.64041666667 | 11880 |
| 012037 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:24am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594551.6 | 511618.2 | 49299 | 1.64041666667 | 12037 |
| 011841 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:25am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594553.4 | 511619.2 | 49301 | 1.64041666667 | 11841 |
| 012030 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:26am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594555.7 | 511619.8 | 49303 | 1.64041666667 | 12030 |
| 012099 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:27am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594557.7 | 511620.7 | 49305 | 1.64041666667 | 12099 |
| 012191 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:28am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594560.3 | 511621.0 | 49307 | 1.64041666667 | 12191 |
| 012293 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:29am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594562.2 | 511621.4 | 49309 | 1.64041666667 | 12293 |
| 012005 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:30am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594564.6 | 511621.7 | 49311 | 1.64041666667 | 12005 |
| 012730 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:31am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594566.5 | 511622.0 | 49313 | 1.64041666667 | 12730 |
| 012426 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:32am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594568.5 | 511622.9 | 49315 | 1.64041666667 | 12426 |
| 012502 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:33am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594570.7 | 511623.3 | 49317 | 1.64041666667 | 12502 |
| 012185 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594572.7 | 511624.0 | 49319 | 1.64041666667 | 12185 |
| 012156 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:35am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594574.6 | 511624.3 | 49321 | 1.64041666667 | 12156 |
| 012328 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:36am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594576.7 | 511625.3 | 49323 | 1.64041666667 | 12328 |
| 012462 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:37am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594578.0 | 511626.2 | 49325 | 1.64041666667 | 12462 |
| 013984 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:38am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594579.0 | 511627.1 | 49327 | 1.64041666667 | 13984 |
| 013446 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:39am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594579.1 | 511628.9 | 49329 | 1.64041666667 | 13446 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012611 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:40am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594578.6 | 511631.0 | 49331 | 1.64041666667 | 12611 |
| 013333 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:41am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594577.4 | 511632.8 | 49333 | 1.64041666667 | 13333 |
| 013702 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:42am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594576.1 | 511634.3 | 49335 | 1.64041666667 | 13702 |
| 013467 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:43am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594574.6 | 511635.5 | 49337 | 1.64041666667 | 13467 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:44am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594572.8 | 511636.8 | 49339 | 1.64041666667 | 12803 |
| 013516 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:45am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594571.3 | 511637.8 | 49341 | 1.64041666667 | 13516 |
| 013220 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:46am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594569.4 | 511638.0 | 49343 | 1.64041666667 | 13220 |
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:47am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594567.7 | 511637.9 | 49345 | 1.64041666667 | 13451 |
| 013956 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:48am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594565.9 | 511637.0 | 49347 | 1.64041666667 | 13956 |
| 013198 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:49am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594564.3 | 511635.6 | 49349 | 1.64041666667 | 13198 |
| 013319 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:50am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594563.4 | 511634.1 | 49351 | 1.64041666667 | 13319 |
| 012922 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:51am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594562.5 | 511632.4 | 49353 | 1.64041666667 | 12922 |
| 012893 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:52am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594560.8 | 511630.7 | 49355 | 1.64041666667 | 12893 |
| 013132 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:53am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594559.4 | 511629.5 | 49357 | 1.64041666667 | 13132 |
| 012914 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:54am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594557.1 | 511629.1 | 49359 | 1.64041666667 | 12914 |
| 012529 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:55am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594555.3 | 511629.0 | 49361 | 1.64041666667 | 12529 |
| 012567 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:56am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594553.0 | 511628.8 | 49363 | 1.64041666667 | 12567 |
| 012799 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:57am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594551.2 | 511628.5 | 49365 | 1.64041666667 | 12799 |
| 012869 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:58am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594549.3 | 511627.9 | 49367 | 1.64041666667 | 12869 |
| 012526 | 0 | GeoXH 6000 | 08/19/2015 | 11:42:59am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594546.9 | 511628.1 | 49369 | 1.64041666667 | 12526 |
| 012221 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:00am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594544.7 | 511628.5 | 49371 | 1.64041666667 | 12221 |
| 012285 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:01am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594542.9 | 511628.8 | 49373 | 1.64041666667 | 12285 |
| 012596 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:02am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594541.0 | 511629.0 | 49375 | 1.64041666667 | 12596 |
| 012148 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:03am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594539.9 | 511629.0 | 49377 | 1.64041666667 | 12148 |
| 012631 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:04am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594539.7 | 511629.6 | 49379 | 1.64041666667 | 12631 |
| 011837 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:05am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594539.7 | 511629.8 | 49381 | 1.64041666667 | 11837 |
| 012403 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:06am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594539.7 | 511629.6 | 49383 | 1.64041666667 | 12403 |
| 012834 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:07am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594539.3 | 511629.3 | 49385 | 1.64041666667 | 12834 |
| 013804 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:08am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594538.0 | 511628.6 | 49387 | 1.64041666667 | 13804 |
| 014237 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:09am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594536.2 | 511627.4 | 49389 | 1.64041666667 | 14237 |
| 013603 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:10am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594534.5 | 511626.3 | 49391 | 1.64041666667 | 13603 |
| 012737 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:11am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594533.3 | 511624.6 | 49393 | 1.64041666667 | 12737 |
| 012782 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:12am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594532.2 | 511622.8 | 49395 | 1.64041666667 | 12782 |
| 012492 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:13am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594531.1 | 511621.2 | 49397 | 1.64041666667 | 12492 |
| 011992 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:14am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594529.7 | 511620.2 | 49399 | 1.64041666667 | 11992 |
| 012783 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:15am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594527.6 | 511620.0 | 49401 | 1.64041666667 | 12783 |
| 012425 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:16am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594525.3 | 511619.4 | 49403 | 1.64041666667 | 12425 |
| 012464 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:17am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594523.3 | 511619.3 | 49405 | 1.64041666667 | 12464 |
| 012628 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:18am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594521.2 | 511619.3 | 49407 | 1.64041666667 | 12628 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:19am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594519.3 | 511619.3 | 49409 | 1.64041666667 | 12803 |
| 012482 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:20am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594517.2 | 511619.3 | 49411 | 1.64041666667 | 12482 |
| 012001 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:21am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594515.3 | 511619.0 | 49413 | 1.64041666667 | 12001 |
| 012375 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:22am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594513.3 | 511618.6 | 49415 | 1.64041666667 | 12375 |
| 012661 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:23am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594511.9 | 511617.6 | 49417 | 1.64041666667 | 12661 |
| 012109 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:24am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594509.9 | 511616.4 | 49419 | 1.64041666667 | 12109 |
| 012459 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:25am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594508.2 | 511615.5 | 49421 | 1.64041666667 | 12459 |
| 013023 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:26am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594506.4 | 511614.7 | 49423 | 1.64041666667 | 13023 |
| 013483 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:27am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594505.0 | 511613.9 | 49425 | 1.64041666667 | 13483 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013591 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:28am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594503.6 | 511612.9 | 49427 | 1.64041666667 | 13591 |
| 012557 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:29am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594502.2 | 511612.6 | 49429 | 1.64041666667 | 12557 |
| 012703 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:30am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594500.4 | 511612.1 | 49431 | 1.64041666667 | 12703 |
| 012628 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:31am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594498.8 | 511611.2 | 49433 | 1.64041666667 | 12628 |
| 012308 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:32am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594497.0 | 511610.2 | 49435 | 1.64041666667 | 12308 |
| 012908 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:33am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594495.3 | 511609.6 | 49437 | 1.64041666667 | 12908 |
| 013778 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594493.2 | 511608.5 | 49439 | 1.64041666667 | 13778 |
| 013525 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:35am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594491.5 | 511607.9 | 49441 | 1.64041666667 | 13525 |
| 012445 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:36am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594489.5 | 511606.8 | 49443 | 1.64041666667 | 12445 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:37am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594487.5 | 511606.0 | 49445 | 1.64041666667 | 12678 |
| 012861 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:38am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594485.5 | 511605.0 | 49447 | 1.64041666667 | 12861 |
| 013264 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:39am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594483.5 | 511604.4 | 49449 | 1.64041666667 | 13264 |
| 013506 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:40am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594481.0 | 511604.6 | 49451 | 1.64041666667 | 13506 |
| 012600 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:41am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594479.0 | 511604.4 | 49453 | 1.64041666667 | 12600 |
| 013260 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:42am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594476.7 | 511604.8 | 49455 | 1.64041666667 | 13260 |
| 013698 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:43am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594474.7 | 511604.7 | 49457 | 1.64041666667 | 13698 |
| 012385 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:44am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594472.6 | 511604.6 | 49459 | 1.64041666667 | 12385 |
| 012081 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:45am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594470.5 | 511604.4 | 49461 | 1.64041666667 | 12081 |
| 012421 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:46am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594468.4 | 511603.4 | 49463 | 1.64041666667 | 12421 |
| 011831 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:47am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594466.5 | 511603.2 | 49465 | 1.64041666667 | 11831 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:48am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594464.2 | 511603.4 | 49467 | 1.64041666667 | 12475 |
| 012004 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:49am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594462.4 | 511603.6 | 49469 | 1.64041666667 | 12004 |
| 012115 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:50am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594460.9 | 511603.8 | 49471 | 1.64041666667 | 12115 |
| 012357 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:51am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594459.3 | 511603.6 | 49473 | 1.64041666667 | 12357 |
| 011818 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:52am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594457.7 | 511604.1 | 49475 | 1.64041666667 | 11818 |
| 011448 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:53am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594457.4 | 511604.5 | 49477 | 1.64041666667 | 11448 |
| 011854 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:54am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594458.3 | 511605.0 | 49479 | 1.64041666667 | 11854 |
| 012188 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:55am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594458.4 | 511605.0 | 49481 | 1.64041666667 | 12188 |
| 012983 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:56am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594458.3 | 511604.8 | 49483 | 1.64041666667 | 12983 |
| 012673 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:57am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594458.1 | 511604.0 | 49485 | 1.64041666667 | 12673 |
| 012243 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:58am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594457.8 | 511602.3 | 49487 | 1.64041666667 | 12243 |
| 012782 | 0 | GeoXH 6000 | 08/19/2015 | 11:43:59am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594457.4 | 511600.6 | 49489 | 1.64041666667 | 12782 |
| 012612 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:00am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594456.9 | 511598.3 | 49491 | 1.64041666667 | 12612 |
| 012569 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:01am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594456.9 | 511596.4 | 49493 | 1.64041666667 | 12569 |
| 011952 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:02am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594457.6 | 511594.1 | 49495 | 1.64041666667 | 11952 |
| 011996 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:03am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594458.2 | 511592.2 | 49497 | 1.64041666667 | 11996 |
| 012665 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:04am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594459.3 | 511590.5 | 49499 | 1.64041666667 | 12665 |
| 012359 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:05am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594460.2 | 511589.2 | 49501 | 1.64041666667 | 12359 |
| 011977 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:06am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594461.6 | 511587.4 | 49503 | 1.64041666667 | 11977 |
| 013314 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:07am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594462.6 | 511585.7 | 49505 | 1.64041666667 | 13314 |
| 011922 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:08am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594463.4 | 511583.4 | 49507 | 1.64041666667 | 11922 |
| 011671 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:09am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594464.4 | 511581.6 | 49509 | 1.64041666667 | 11671 |
| 011395 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:10am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594464.8 | 511579.6 | 49511 | 1.64041666667 | 11395 |
| 011299 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:11am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594465.0 | 511577.8 | 49513 | 1.64041666667 | 11299 |
| 011478 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:12am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594465.5 | 511575.7 | 49515 | 1.64041666667 | 11478 |
| 012179 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:13am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594465.6 | 511573.6 | 49517 | 1.64041666667 | 12179 |
| 012183 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:14am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594466.1 | 511571.7 | 49519 | 1.64041666667 | 12183 |
| 011818 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:15am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594466.2 | 511569.8 | 49521 | 1.64041666667 | 11818 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011980 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:16am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594467.0 | 511567.0 | 49523 | 1.64041666667 | 11980 |
| 012498 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:17am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594467.3 | 511564.8 | 49525 | 1.64041666667 | 12498 |
| 013000 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:18am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594467.7 | 511562.6 | 49527 | 1.64041666667 | 13000 |
| 012397 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:19am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594468.4 | 511560.4 | 49529 | 1.64041666667 | 12397 |
| 012816 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:20am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594469.0 | 511558.1 | 49531 | 1.64041666667 | 12816 |
| 013051 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:21am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594470.2 | 511556.1 | 49533 | 1.64041666667 | 13051 |
| 012891 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:22am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594471.0 | 511554.0 | 49535 | 1.64041666667 | 12891 |
| 013491 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:23am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594471.8 | 511552.7 | 49537 | 1.64041666667 | 13491 |
| 012644 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:24am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594473.8 | 511551.5 | 49539 | 1.64041666667 | 12644 |
| 013157 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:25am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594475.6 | 511550.0 | 49541 | 1.64041666667 | 13157 |
| 012786 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:26am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594477.2 | 511548.6 | 49543 | 1.64041666667 | 12786 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:27am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594478.6 | 511547.5 | 49545 | 1.64041666667 | 12787 |
| 013395 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:28am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594479.7 | 511545.3 | 49547 | 1.64041666667 | 13395 |
| 013467 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:29am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594480.7 | 511543.4 | 49549 | 1.64041666667 | 13467 |
| 013372 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:30am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594481.5 | 511540.9 | 49551 | 1.64041666667 | 13372 |
| 013342 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:31am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594482.1 | 511538.8 | 49553 | 1.64041666667 | 13342 |
| 012942 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:32am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594483.1 | 511536.7 | 49555 | 1.64041666667 | 12942 |
| 012950 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:33am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594483.7 | 511534.7 | 49557 | 1.64041666667 | 12950 |
| 012497 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:34am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594484.6 | 511532.8 | 49559 | 1.64041666667 | 12497 |
| 012714 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:35am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594485.8 | 511531.0 | 49561 | 1.64041666667 | 12714 |
| 012229 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:36am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594486.8 | 511529.3 | 49563 | 1.64041666667 | 12229 |
| 012474 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:37am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594488.3 | 511527.7 | 49565 | 1.64041666667 | 12474 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:38am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594489.4 | 511526.1 | 49567 | 1.64041666667 | 12401 |
| 013215 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:39am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594490.5 | 511524.7 | 49569 | 1.64041666667 | 13215 |
| 013756 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:40am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594491.6 | 511522.6 | 49571 | 1.64041666667 | 13756 |
| 013925 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:41am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594492.7 | 511520.8 | 49573 | 1.64041666667 | 13925 |
| 013855 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:42am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594493.9 | 511518.9 | 49575 | 1.64041666667 | 13855 |
| 013028 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:43am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594494.5 | 511517.3 | 49577 | 1.64041666667 | 13028 |
| 012811 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:44am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594495.3 | 511515.7 | 49579 | 1.64041666667 | 12811 |
| 012981 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:45am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594495.9 | 511514.0 | 49581 | 1.64041666667 | 12981 |
| 013062 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:46am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594496.8 | 511512.2 | 49583 | 1.64041666667 | 13062 |
| 012499 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:47am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594497.1 | 511510.1 | 49585 | 1.64041666667 | 12499 |
| 011696 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:48am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594498.1 | 511508.1 | 49587 | 1.64041666667 | 11696 |
| 011049 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:49am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594498.9 | 511506.1 | 49589 | 1.64041666667 | 11049 |
| 012590 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:50am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594499.8 | 511504.2 | 49591 | 1.64041666667 | 12590 |
| 013179 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:51am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594500.6 | 511502.5 | 49593 | 1.64041666667 | 13179 |
| 014448 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:52am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594501.1 | 511500.5 | 49595 | 1.64041666667 | 14448 |
| 014689 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:53am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594501.9 | 511498.6 | 49597 | 1.64041666667 | 14689 |
| 014450 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:54am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594502.2 | 511496.7 | 49599 | 1.64041666667 | 14450 |
| 015508 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:55am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594502.9 | 511494.8 | 49601 | 1.64041666667 | 15508 |
| 015031 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:56am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594503.1 | 511492.8 | 49603 | 1.64041666667 | 15031 |
| 014890 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:57am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594503.6 | 511491.1 | 49605 | 1.64041666667 | 14890 |
| 014465 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:58am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594503.8 | 511489.4 | 49607 | 1.64041666667 | 14465 |
| 014819 | 0 | GeoXH 6000 | 08/19/2015 | 11:44:59am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594504.7 | 511488.2 | 49609 | 1.64041666667 | 14819 |
| 014628 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:00am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594506.2 | 511486.9 | 49611 | 1.64041666667 | 14628 |
| 015443 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:01am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594507.8 | 511486.7 | 49613 | 1.64041666667 | 15443 |
| 015452 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:02am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594509.6 | 511487.0 | 49615 | 1.64041666667 | 15452 |
| 015156 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:03am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594511.3 | 511487.5 | 49617 | 1.64041666667 | 15156 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015553 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:04am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594513.2 | 511487.8 | 49619 | 1.64041666667 | 15553 |
| 014201 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:05am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594514.8 | 511488.1 | 49621 | 1.64041666667 | 14201 |
| 014370 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:06am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594516.8 | 511488.8 | 49623 | 1.64041666667 | 14370 |
| 014593 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:07am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594518.1 | 511488.9 | 49625 | 1.64041666667 | 14593 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:08am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594519.0 | 511489.6 | 49627 | 1.64041666667 | 14463 |
| 014061 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:09am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594519.6 | 511491.0 | 49629 | 1.64041666667 | 14061 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:10am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594518.8 | 511492.9 | 49631 | 1.64041666667 | 13811 |
| 013506 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:11am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594518.5 | 511494.7 | 49633 | 1.64041666667 | 13506 |
| 013710 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:12am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594517.5 | 511496.4 | 49635 | 1.64041666667 | 13710 |
| 014431 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:13am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594516.4 | 511498.3 | 49637 | 1.64041666667 | 14431 |
| 014230 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:14am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594515.5 | 511500.3 | 49639 | 1.64041666667 | 14230 |
| 014724 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:15am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594514.9 | 511502.0 | 49641 | 1.64041666667 | 14724 |
| 013975 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:16am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594514.4 | 511503.9 | 49643 | 1.64041666667 | 13975 |
| 013568 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:17am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594513.4 | 511505.9 | 49645 | 1.64041666667 | 13568 |
| 013744 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:18am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594512.7 | 511508.3 | 49647 | 1.64041666667 | 13744 |
| 013724 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:19am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594511.8 | 511510.3 | 49649 | 1.64041666667 | 13724 |
| 013659 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:20am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594511.2 | 511512.5 | 49651 | 1.64041666667 | 13659 |
| 014006 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:21am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594510.6 | 511514.6 | 49653 | 1.64041666667 | 14006 |
| 013376 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:22am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594509.8 | 511516.6 | 49655 | 1.64041666667 | 13376 |
| 013314 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:23am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594509.6 | 511518.6 | 49657 | 1.64041666667 | 13314 |
| 013879 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:24am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594508.7 | 511520.9 | 49659 | 1.64041666667 | 13879 |
| 014677 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:25am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594507.8 | 511522.8 | 49661 | 1.64041666667 | 14677 |
| 014360 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:26am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594506.6 | 511524.7 | 49663 | 1.64041666667 | 14360 |
| 013358 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:27am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594505.6 | 511526.4 | 49665 | 1.64041666667 | 13358 |
| 013394 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:28am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594504.8 | 511528.5 | 49667 | 1.64041666667 | 13394 |
| 013391 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:29am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594503.5 | 511530.5 | 49669 | 1.64041666667 | 13391 |
| 013435 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:30am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594502.5 | 511532.3 | 49671 | 1.64041666667 | 13435 |
| 013497 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:31am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594501.4 | 511534.0 | 49673 | 1.64041666667 | 13497 |
| 013457 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:32am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594500.5 | 511536.0 | 49675 | 1.64041666667 | 13457 |
| 013217 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:33am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594499.8 | 511538.1 | 49677 | 1.64041666667 | 13217 |
| 012857 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594499.0 | 511540.4 | 49679 | 1.64041666667 | 12857 |
| 013584 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:35am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594498.9 | 511542.4 | 49681 | 1.64041666667 | 13584 |
| 013439 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:36am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594498.2 | 511544.9 | 49683 | 1.64041666667 | 13439 |
| 013312 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:37am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594497.9 | 511546.6 | 49685 | 1.64041666667 | 13312 |
| 013323 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:38am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594497.4 | 511548.7 | 49687 | 1.64041666667 | 13323 |
| 012879 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:39am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594496.6 | 511550.8 | 49689 | 1.64041666667 | 12879 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:40am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594496.0 | 511553.0 | 49691 | 1.64041666667 | 12787 |
| 013230 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:41am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594494.9 | 511554.8 | 49693 | 1.64041666667 | 13230 |
| 013629 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:42am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594494.1 | 511557.0 | 49695 | 1.64041666667 | 13629 |
| 013711 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:43am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594493.1 | 511558.8 | 49697 | 1.64041666667 | 13711 |
| 012992 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:44am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594492.2 | 511560.9 | 49699 | 1.64041666667 | 12992 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:45am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594491.5 | 511563.0 | 49701 | 1.64041666667 | 12768 |
| 012559 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:46am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594490.5 | 511565.0 | 49703 | 1.64041666667 | 12559 |
| 012892 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:47am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594490.1 | 511567.1 | 49705 | 1.64041666667 | 12892 |
| 013184 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:48am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594489.3 | 511569.3 | 49707 | 1.64041666667 | 13184 |
| 013311 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:49am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594488.6 | 511571.2 | 49709 | 1.64041666667 | 13311 |
| 013495 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:50am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594487.8 | 511572.9 | 49711 | 1.64041666667 | 13495 |
| 013051 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:51am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594486.3 | 511574.5 | 49713 | 1.64041666667 | 13051 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012643 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:52am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594485.1 | 511576.9 | 49715 | 1.64041666667 | 12643 |
| 011342 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:53am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594483.8 | 511578.7 | 49717 | 1.64041666667 | 11342 |
| 012215 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:54am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594482.2 | 511580.4 | 49719 | 1.64041666667 | 12215 |
| 013028 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:55am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594481.0 | 511582.3 | 49721 | 1.64041666667 | 13028 |
| 013043 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:56am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594479.7 | 511584.2 | 49723 | 1.64041666667 | 13043 |
| 012159 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:57am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594478.9 | 511586.3 | 49725 | 1.64041666667 | 12159 |
| 012322 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:58am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594477.4 | 511588.5 | 49727 | 1.64041666667 | 12322 |
| 011708 | 0 | GeoXH 6000 | 08/19/2015 | 11:45:59am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594476.3 | 511590.3 | 49729 | 1.64041666667 | 11708 |
| 011626 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:00am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594475.5 | 511592.2 | 49731 | 1.64041666667 | 11626 |
| 011924 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:01am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594474.5 | 511594.0 | 49733 | 1.64041666667 | 11924 |
| 011935 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:02am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594474.2 | 511596.1 | 49735 | 1.64041666667 | 11935 |
| 011513 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:03am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594474.6 | 511597.4 | 49737 | 1.64041666667 | 11513 |
| 011973 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:04am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594476.4 | 511598.1 | 49739 | 1.64041666667 | 11973 |
| 012285 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:05am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594478.6 | 511598.5 | 49741 | 1.64041666667 | 12285 |
| 012663 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:06am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594480.3 | 511599.3 | 49743 | 1.64041666667 | 12663 |
| 012155 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:07am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594481.6 | 511600.0 | 49745 | 1.64041666667 | 12155 |
| 012297 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:08am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594482.8 | 511601.4 | 49747 | 1.64041666667 | 12297 |
| 013712 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:09am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594483.9 | 511602.2 | 49749 | 1.64041666667 | 13712 |
| 012775 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:10am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594484.4 | 511603.3 | 49751 | 1.64041666667 | 12775 |
| 012188 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:11am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594484.7 | 511603.9 | 49753 | 1.64041666667 | 12188 |
| 012608 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:12am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594484.9 | 511604.0 | 49755 | 1.64041666667 | 12608 |
| 012417 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:13am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594485.3 | 511603.2 | 49757 | 1.64041666667 | 12417 |
| 011822 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:14am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594485.8 | 511601.8 | 49759 | 1.64041666667 | 11822 |
| 011780 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:15am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594486.4 | 511600.2 | 49761 | 1.64041666667 | 11780 |
| 012213 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:16am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594487.1 | 511598.5 | 49763 | 1.64041666667 | 12213 |
| 013027 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:17am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594487.5 | 511596.7 | 49765 | 1.64041666667 | 13027 |
| 012885 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:18am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594488.3 | 511594.6 | 49767 | 1.64041666667 | 12885 |
| 012258 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:19am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594488.4 | 511592.8 | 49769 | 1.64041666667 | 12258 |
| 012137 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:20am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594489.0 | 511590.9 | 49771 | 1.64041666667 | 12137 |
| 011710 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:21am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594489.3 | 511589.1 | 49773 | 1.64041666667 | 11710 |
| 011634 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:22am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594490.2 | 511586.9 | 49775 | 1.64041666667 | 11634 |
| 012116 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:23am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594490.5 | 511584.8 | 49777 | 1.64041666667 | 12116 |
| 012620 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:24am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594491.1 | 511582.3 | 49779 | 1.64041666667 | 12620 |
| 012229 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:25am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594491.5 | 511580.2 | 49781 | 1.64041666667 | 12229 |
| 012331 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:26am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594491.7 | 511578.4 | 49783 | 1.64041666667 | 12331 |
| 012179 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:27am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594492.8 | 511576.5 | 49785 | 1.64041666667 | 12179 |
| 011868 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:28am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594493.6 | 511574.3 | 49787 | 1.64041666667 | 11868 |
| 011415 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:29am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594494.6 | 511572.4 | 49789 | 1.64041666667 | 11415 |
| 011904 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:30am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594495.6 | 511570.0 | 49791 | 1.64041666667 | 11904 |
| 012231 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:31am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594497.0 | 511567.8 | 49793 | 1.64041666667 | 12231 |
| 012850 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:32am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594498.2 | 511566.0 | 49795 | 1.64041666667 | 12850 |
| 012785 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:33am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594498.7 | 511563.8 | 49797 | 1.64041666667 | 12785 |
| 013784 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594499.7 | 511561.7 | 49799 | 1.64041666667 | 13784 |
| 013588 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:35am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594500.6 | 511559.7 | 49801 | 1.64041666667 | 13588 |
| 014191 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:36am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594501.6 | 511557.7 | 49803 | 1.64041666667 | 14191 |
| 013787 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:37am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594503.2 | 511555.7 | 49805 | 1.64041666667 | 13787 |
| 013703 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:38am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594504.2 | 511553.7 | 49807 | 1.64041666667 | 13703 |
| 013280 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:39am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594505.5 | 511551.7 | 49809 | 1.64041666667 | 13280 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:40am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594506.3 | 511549.4 | 49811 | 1.64041666667 | 12247 |
| 013504 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:41am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594506.9 | 511547.7 | 49813 | 1.64041666667 | 13504 |
| 013483 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:42am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594507.8 | 511546.0 | 49815 | 1.64041666667 | 13483 |
| 013532 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:43am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594508.3 | 511543.9 | 49817 | 1.64041666667 | 13532 |
| 013379 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:44am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594509.5 | 511541.7 | 49819 | 1.64041666667 | 13379 |
| 013046 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:45am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594509.9 | 511539.3 | 49821 | 1.64041666667 | 13046 |
| 013488 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:46am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594510.6 | 511537.1 | 49823 | 1.64041666667 | 13488 |
| 013354 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:47am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594511.4 | 511535.3 | 49825 | 1.64041666667 | 13354 |
| 013609 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:48am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594511.9 | 511533.2 | 49827 | 1.64041666667 | 13609 |
| 013122 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:49am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594512.7 | 511531.1 | 49829 | 1.64041666667 | 13122 |
| 013666 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:50am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594513.0 | 511529.1 | 49831 | 1.64041666667 | 13666 |
| 013245 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:51am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594514.1 | 511527.3 | 49833 | 1.64041666667 | 13245 |
| 013247 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:52am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594515.2 | 511525.4 | 49835 | 1.64041666667 | 13247 |
| 012469 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:53am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594516.2 | 511523.6 | 49837 | 1.64041666667 | 12469 |
| 012954 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:54am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594517.2 | 511521.6 | 49839 | 1.64041666667 | 12954 |
| 013129 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:55am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594517.6 | 511519.8 | 49841 | 1.64041666667 | 13129 |
| 013175 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:56am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594518.6 | 511517.6 | 49843 | 1.64041666667 | 13175 |
| 013343 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:57am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594519.0 | 511515.4 | 49845 | 1.64041666667 | 13343 |
| 013310 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:58am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594519.9 | 511512.9 | 49847 | 1.64041666667 | 13310 |
| 013389 | 0 | GeoXH 6000 | 08/19/2015 | 11:46:59am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594520.5 | 511511.0 | 49849 | 1.64041666667 | 13389 |
| 013284 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:00am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594520.8 | 511508.7 | 49851 | 1.64041666667 | 13284 |
| 012902 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:01am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594521.3 | 511506.7 | 49853 | 1.64041666667 | 12902 |
| 012770 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:02am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594521.5 | 511504.6 | 49855 | 1.64041666667 | 12770 |
| 013393 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:03am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594522.0 | 511502.4 | 49857 | 1.64041666667 | 13393 |
| 013301 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:04am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594521.6 | 511500.2 | 49859 | 1.64041666667 | 13301 |
| 013001 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:05am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594521.4 | 511498.7 | 49861 | 1.64041666667 | 13001 |
| 013216 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:06am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594521.9 | 511497.5 | 49863 | 1.64041666667 | 13216 |
| 012804 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:07am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594522.0 | 511495.9 | 49865 | 1.64041666667 | 12804 |
| 012759 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:08am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594522.6 | 511494.2 | 49867 | 1.64041666667 | 12759 |
| 012870 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:09am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594523.0 | 511492.2 | 49869 | 1.64041666667 | 12870 |
| 013066 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:10am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594524.0 | 511490.6 | 49871 | 1.64041666667 | 13066 |
| 013275 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:11am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594525.3 | 511489.5 | 49873 | 1.64041666667 | 13275 |
| 013782 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:12am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594526.8 | 511488.8 | 49875 | 1.64041666667 | 13782 |
| 014052 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:13am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594528.4 | 511489.2 | 49877 | 1.64041666667 | 14052 |
| 013327 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:14am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594530.0 | 511489.3 | 49879 | 1.64041666667 | 13327 |
| 013601 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:15am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594531.7 | 511490.7 | 49881 | 1.64041666667 | 13601 |
| 013793 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:16am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594533.9 | 511491.5 | 49883 | 1.64041666667 | 13793 |
| 013218 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:17am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594535.6 | 511492.1 | 49885 | 1.64041666667 | 13218 |
| 013863 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:18am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594537.8 | 511492.3 | 49887 | 1.64041666667 | 13863 |
| 014083 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:19am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594539.8 | 511492.8 | 49889 | 1.64041666667 | 14083 |
| 014559 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:20am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594541.3 | 511493.5 | 49891 | 1.64041666667 | 14559 |
| 014662 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:21am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594542.5 | 511493.7 | 49893 | 1.64041666667 | 14662 |
| 015012 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:22am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594542.4 | 511493.4 | 49895 | 1.64041666667 | 15012 |
| 014894 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:23am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594542.9 | 511493.8 | 49897 | 1.64041666667 | 14894 |
| 014768 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:24am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594543.9 | 511495.4 | 49899 | 1.64041666667 | 14768 |
| 015484 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:25am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594544.7 | 511497.5 | 49901 | 1.64041666667 | 15484 |
| 015902 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:26am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594545.8 | 511499.3 | 49903 | 1.64041666667 | 15902 |
| 015650 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:27am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594546.9 | 511500.7 | 49905 | 1.64041666667 | 15650 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015328 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:28am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594547.8 | 511503.3 | 49907 | 1.64041666667 | 15328 |
| 015439 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:29am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594548.9 | 511505.5 | 49909 | 1.64041666667 | 15439 |
| 015735 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:30am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594549.9 | 511507.7 | 49911 | 1.64041666667 | 15735 |
| 015735 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:31am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594550.4 | 511509.8 | 49913 | 1.64041666667 | 15735 |
| 014768 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:32am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594551.2 | 511512.5 | 49915 | 1.64041666667 | 14768 |
| 013992 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:33am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594551.0 | 511514.7 | 49917 | 1.64041666667 | 13992 |
| 014350 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:34am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594550.0 | 511516.9 | 49919 | 1.64041666667 | 14350 |
| 013697 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:35am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594549.0 | 511519.0 | 49921 | 1.64041666667 | 13697 |
| 013637 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:36am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594547.0 | 511520.6 | 49923 | 1.64041666667 | 13637 |
| 013858 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:37am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594545.5 | 511522.2 | 49925 | 1.64041666667 | 13858 |
| 014613 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:38am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594543.6 | 511523.6 | 49927 | 1.64041666667 | 14613 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:39am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594542.1 | 511524.7 | 49929 | 1.64041666667 | 14737 |
| 013757 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:40am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594540.5 | 511526.3 | 49931 | 1.64041666667 | 13757 |
| 013326 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:41am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594538.8 | 511527.6 | 49933 | 1.64041666667 | 13326 |
| 013346 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:42am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594537.7 | 511529.5 | 49935 | 1.64041666667 | 13346 |
| 013987 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:43am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594536.6 | 511531.2 | 49937 | 1.64041666667 | 13987 |
| 013365 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:44am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594535.6 | 511533.2 | 49939 | 1.64041666667 | 13365 |
| 012550 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:45am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594534.7 | 511534.4 | 49941 | 1.64041666667 | 12550 |
| 012872 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:46am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594532.7 | 511535.8 | 49943 | 1.64041666667 | 12872 |
| 013308 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:47am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594531.5 | 511537.2 | 49945 | 1.64041666667 | 13308 |
| 013185 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:48am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594530.0 | 511539.1 | 49947 | 1.64041666667 | 13185 |
| 013409 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:49am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594529.5 | 511541.2 | 49949 | 1.64041666667 | 13409 |
| 012455 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:50am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594529.2 | 511543.1 | 49951 | 1.64041666667 | 12455 |
| 012218 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:51am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594528.2 | 511544.6 | 49953 | 1.64041666667 | 12218 |
| 012288 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:52am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594527.2 | 511546.5 | 49955 | 1.64041666667 | 12288 |
| 012387 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:53am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594526.1 | 511547.7 | 49957 | 1.64041666667 | 12387 |
| 011910 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:54am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594525.1 | 511549.6 | 49959 | 1.64041666667 | 11910 |
| 011912 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:55am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594523.8 | 511550.9 | 49961 | 1.64041666667 | 11912 |
| 012588 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:56am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594522.0 | 511552.9 | 49963 | 1.64041666667 | 12588 |
| 011693 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:57am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594521.1 | 511554.6 | 49965 | 1.64041666667 | 11693 |
| 012127 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:58am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594519.9 | 511556.4 | 49967 | 1.64041666667 | 12127 |
| 012124 | 0 | GeoXH 6000 | 08/19/2015 | 11:47:59am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594519.6 | 511558.7 | 49969 | 1.64041666667 | 12124 |
| 013037 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:00am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594518.5 | 511560.8 | 49971 | 1.64041666667 | 13037 |
| 012501 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:01am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594517.6 | 511562.5 | 49973 | 1.64041666667 | 12501 |
| 012469 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:02am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594517.0 | 511564.6 | 49975 | 1.64041666667 | 12469 |
| 013066 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:03am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594516.2 | 511566.4 | 49977 | 1.64041666667 | 13066 |
| 013335 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:04am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594515.8 | 511568.5 | 49979 | 1.64041666667 | 13335 |
| 013920 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:05am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594515.0 | 511570.7 | 49981 | 1.64041666667 | 13920 |
| 013290 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:06am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594514.9 | 511573.0 | 49983 | 1.64041666667 | 13290 |
| 013161 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:07am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594515.2 | 511575.0 | 49985 | 1.64041666667 | 13161 |
| 012278 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:08am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594515.1 | 511577.1 | 49987 | 1.64041666667 | 12278 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:09am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594515.1 | 511578.4 | 49989 | 1.64041666667 | 12021 |
| 012529 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:10am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594514.6 | 511580.5 | 49991 | 1.64041666667 | 12529 |
| 012140 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:11am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594514.3 | 511581.8 | 49993 | 1.64041666667 | 12140 |
| 013158 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:12am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594514.5 | 511583.5 | 49995 | 1.64041666667 | 13158 |
| 013627 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:13am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594514.2 | 511585.3 | 49997 | 1.64041666667 | 13627 |
| 013260 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:14am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594513.9 | 511587.0 | 49999 | 1.64041666667 | 13260 |
| 013338 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:15am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594513.1 | 511588.9 | 50001 | 1.64041666667 | 13338 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012970 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:16am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594512.4 | 511591.0 | 50003 | 1.64041666667 | 12970 |
| 013071 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:17am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594511.0 | 511592.7 | 50005 | 1.64041666667 | 13071 |
| 012842 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:18am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594509.7 | 511594.5 | 50007 | 1.64041666667 | 12842 |
| 012923 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:19am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594508.5 | 511595.9 | 50009 | 1.64041666667 | 12923 |
| 013352 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:20am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594507.1 | 511597.8 | 50011 | 1.64041666667 | 13352 |
| 012805 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:21am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594506.3 | 511599.7 | 50013 | 1.64041666667 | 12805 |
| 013068 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:22am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594504.8 | 511601.9 | 50015 | 1.64041666667 | 13068 |
| 013605 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:23am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594503.9 | 511603.7 | 50017 | 1.64041666667 | 13605 |
| 013135 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:24am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594503.2 | 511606.2 | 50019 | 1.64041666667 | 13135 |
| 012518 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:25am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594502.7 | 511608.6 | 50021 | 1.64041666667 | 12518 |
| 012202 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:26am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594503.1 | 511610.7 | 50023 | 1.64041666667 | 12202 |
| 011978 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:27am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594503.8 | 511612.1 | 50025 | 1.64041666667 | 11978 |
| 012430 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:28am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594504.2 | 511614.4 | 50027 | 1.64041666667 | 12430 |
| 013337 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:29am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594504.4 | 511616.2 | 50029 | 1.64041666667 | 13337 |
| 012924 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:30am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594503.9 | 511618.4 | 50031 | 1.64041666667 | 12924 |
| 012415 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:31am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594504.1 | 511620.7 | 50033 | 1.64041666667 | 12415 |
| 012751 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:32am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594504.2 | 511623.2 | 50035 | 1.64041666667 | 12751 |
| 013180 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:33am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594504.6 | 511624.8 | 50037 | 1.64041666667 | 13180 |
| 012191 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594506.7 | 511625.6 | 50039 | 1.64041666667 | 12191 |
| 012827 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:35am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594508.5 | 511626.6 | 50041 | 1.64041666667 | 12827 |
| 013050 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:36am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594510.3 | 511627.1 | 50043 | 1.64041666667 | 13050 |
| 012261 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:37am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594511.7 | 511628.0 | 50045 | 1.64041666667 | 12261 |
| 013181 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:38am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594513.6 | 511628.6 | 50047 | 1.64041666667 | 13181 |
| 012492 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:39am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594515.5 | 511629.0 | 50049 | 1.64041666667 | 12492 |
| 013709 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:40am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594517.2 | 511629.3 | 50051 | 1.64041666667 | 13709 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:41am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594517.8 | 511628.4 | 50053 | 1.64041666667 | 14049 |
| 012852 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:42am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594518.5 | 511627.0 | 50055 | 1.64041666667 | 12852 |
| 013229 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:43am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594518.0 | 511625.6 | 50057 | 1.64041666667 | 13229 |
| 013396 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:44am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594517.2 | 511624.0 | 50059 | 1.64041666667 | 13396 |
| 013078 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:45am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594516.4 | 511622.1 | 50061 | 1.64041666667 | 13078 |
| 013371 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:46am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594516.1 | 511620.2 | 50063 | 1.64041666667 | 13371 |
| 012786 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:47am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594515.7 | 511618.6 | 50065 | 1.64041666667 | 12786 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:48am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594515.7 | 511616.4 | 50067 | 1.64041666667 | 12742 |
| 012500 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:49am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594515.6 | 511614.6 | 50069 | 1.64041666667 | 12500 |
| 013878 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:50am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594515.9 | 511612.7 | 50071 | 1.64041666667 | 13878 |
| 014061 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:51am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594516.2 | 511610.3 | 50073 | 1.64041666667 | 14061 |
| 012994 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:52am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594516.7 | 511608.0 | 50075 | 1.64041666667 | 12994 |
| 013084 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:53am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594517.4 | 511606.2 | 50077 | 1.64041666667 | 13084 |
| 013082 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:54am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594518.0 | 511604.5 | 50079 | 1.64041666667 | 13082 |
| 014154 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:55am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594519.5 | 511603.1 | 50081 | 1.64041666667 | 14154 |
| 013526 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:56am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594520.8 | 511601.0 | 50083 | 1.64041666667 | 13526 |
| 012866 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:57am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594522.0 | 511598.9 | 50085 | 1.64041666667 | 12866 |
| 012824 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:58am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594523.0 | 511597.2 | 50087 | 1.64041666667 | 12824 |
| 013101 | 0 | GeoXH 6000 | 08/19/2015 | 11:48:59am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594523.7 | 511595.2 | 50089 | 1.64041666667 | 13101 |
| 012784 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:00am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594524.8 | 511593.3 | 50091 | 1.64041666667 | 12784 |
| 013318 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:01am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594525.4 | 511591.4 | 50093 | 1.64041666667 | 13318 |
| 012479 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:02am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594526.6 | 511589.4 | 50095 | 1.64041666667 | 12479 |
| 012704 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:03am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594527.3 | 511587.7 | 50097 | 1.64041666667 | 12704 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013094 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:04am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594528.1 | 511585.4 | 50099 | 1.64041666667 | 13094 |
| 012802 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:05am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594529.2 | 511583.4 | 50101 | 1.64041666667 | 12802 |
| 013261 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:06am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594529.8 | 511581.2 | 50103 | 1.64041666667 | 13261 |
| 012514 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:07am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594531.1 | 511579.2 | 50105 | 1.64041666667 | 12514 |
| 012717 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:08am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594532.0 | 511576.8 | 50107 | 1.64041666667 | 12717 |
| 012395 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:09am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594532.9 | 511574.3 | 50109 | 1.64041666667 | 12395 |
| 012560 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:10am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594533.5 | 511572.1 | 50111 | 1.64041666667 | 12560 |
| 012472 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:11am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594533.6 | 511570.1 | 50113 | 1.64041666667 | 12472 |
| 012978 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:12am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594534.7 | 511568.0 | 50115 | 1.64041666667 | 12978 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:13am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594535.4 | 511566.2 | 50117 | 1.64041666667 | 12768 |
| 012604 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:14am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594536.3 | 511564.0 | 50119 | 1.64041666667 | 12604 |
| 012917 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:15am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594536.9 | 511561.8 | 50121 | 1.64041666667 | 12917 |
| 012343 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:16am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594538.0 | 511559.7 | 50123 | 1.64041666667 | 12343 |
| 012553 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:17am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594539.4 | 511558.1 | 50125 | 1.64041666667 | 12553 |
| 012596 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:18am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594540.6 | 511556.4 | 50127 | 1.64041666667 | 12596 |
| 012298 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:19am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594542.0 | 511555.2 | 50129 | 1.64041666667 | 12298 |
| 012272 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:20am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594543.5 | 511553.4 | 50131 | 1.64041666667 | 12272 |
| 012633 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:21am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594545.0 | 511551.8 | 50133 | 1.64041666667 | 12633 |
| 013218 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:22am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594546.4 | 511549.6 | 50135 | 1.64041666667 | 13218 |
| 013218 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:23am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594547.7 | 511547.7 | 50137 | 1.64041666667 | 13218 |
| 013780 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:24am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594549.4 | 511546.0 | 50139 | 1.64041666667 | 13780 |
| 014283 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:25am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594550.5 | 511543.8 | 50141 | 1.64041666667 | 14283 |
| 014514 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:26am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594551.9 | 511541.8 | 50143 | 1.64041666667 | 14514 |
| 014082 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:27am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594552.9 | 511540.0 | 50145 | 1.64041666667 | 14082 |
| 014348 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:28am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594553.8 | 511537.8 | 50147 | 1.64041666667 | 14348 |
| 014881 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:29am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594555.2 | 511536.1 | 50149 | 1.64041666667 | 14881 |
| 014813 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:30am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594556.5 | 511533.9 | 50151 | 1.64041666667 | 14813 |
| 015172 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:31am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594557.8 | 511532.1 | 50153 | 1.64041666667 | 15172 |
| 014249 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:32am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594559.0 | 511530.1 | 50155 | 1.64041666667 | 14249 |
| 014982 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:33am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594559.5 | 511528.0 | 50157 | 1.64041666667 | 14982 |
| 014487 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:34am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594560.4 | 511525.9 | 50159 | 1.64041666667 | 14487 |
| 014404 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:35am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594561.1 | 511523.5 | 50161 | 1.64041666667 | 14404 |
| 014995 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:36am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594561.7 | 511521.4 | 50163 | 1.64041666667 | 14995 |
| 015702 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:37am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594562.7 | 511519.3 | 50165 | 1.64041666667 | 15702 |
| 015942 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:38am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594563.3 | 511516.9 | 50167 | 1.64041666667 | 15942 |
| 015305 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:39am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594564.1 | 511515.1 | 50169 | 1.64041666667 | 15305 |
| 014894 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:40am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594564.9 | 511513.0 | 50171 | 1.64041666667 | 14894 |
| 014470 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:41am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594565.6 | 511511.4 | 50173 | 1.64041666667 | 14470 |
| 015191 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:42am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594567.4 | 511510.5 | 50175 | 1.64041666667 | 15191 |
| 015070 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:43am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594569.3 | 511510.3 | 50177 | 1.64041666667 | 15070 |
| 015924 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:44am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594571.3 | 511511.2 | 50179 | 1.64041666667 | 15924 |
| 014972 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:45am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594573.0 | 511512.0 | 50181 | 1.64041666667 | 14972 |
| 014827 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:46am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1594575.3 | 511512.6 | 50183 | 1.64041666667 | 14827 |
| 014955 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:47am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594576.9 | 511513.5 | 50185 | 1.64041666667 | 14955 |
| 015574 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:48am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594579.3 | 511514.4 | 50187 | 1.64041666667 | 15574 |
| 016170 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:49am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594580.4 | 511515.7 | 50189 | 1.64041666667 | 16170 |
| 014788 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:50am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594580.7 | 511517.9 | 50191 | 1.64041666667 | 14788 |
| 015548 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:51am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594580.3 | 511520.0 | 50193 | 1.64041666667 | 15548 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015136 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:52am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1594579.3 | 511521.9 | 50195 | 1.64041666667 | 15136 |
| 015901 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:53am | Sensor | 1797-S0037-905-G-ACK | 6823.0 | 1594578.5 | 511523.9 | 50197 | 1.64041666667 | 15901 |
| 015687 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:54am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594576.9 | 511525.9 | 50199 | 1.64041666667 | 15687 |
| 014246 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:55am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594576.2 | 511528.1 | 50201 | 1.64041666667 | 14246 |
| 015393 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:56am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594575.5 | 511530.3 | 50203 | 1.64041666667 | 15393 |
| 016653 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:57am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594574.8 | 511532.2 | 50205 | 1.64041666667 | 16653 |
| 015645 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:58am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594574.3 | 511534.6 | 50207 | 1.64041666667 | 15645 |
| 015460 | 0 | GeoXH 6000 | 08/19/2015 | 11:49:59am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594573.4 | 511536.3 | 50209 | 1.64041666667 | 15460 |
| 015454 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:00am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594572.6 | 511538.5 | 50211 | 1.64041666667 | 15454 |
| 015225 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:01am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594571.9 | 511540.1 | 50213 | 1.64041666667 | 15225 |
| 015614 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:02am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594571.5 | 511541.1 | 50215 | 1.64041666667 | 15614 |
| 015315 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:03am | Sensor | 1797-S0037-905-G-ACK | 6822.9 | 1594571.4 | 511542.7 | 50217 | 1.64041666667 | 15315 |
| 015560 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:04am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594570.8 | 511544.6 | 50219 | 1.64041666667 | 15560 |
| 015562 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:05am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594570.7 | 511546.7 | 50221 | 1.64041666667 | 15562 |
| 015053 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:06am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594569.8 | 511548.9 | 50223 | 1.64041666667 | 15053 |
| 014340 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:07am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594568.8 | 511550.8 | 50225 | 1.64041666667 | 14340 |
| 014141 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:08am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594567.7 | 511552.8 | 50227 | 1.64041666667 | 14141 |
| 015672 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:09am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594566.2 | 511554.7 | 50229 | 1.64041666667 | 15672 |
| 015760 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:10am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594564.7 | 511556.5 | 50231 | 1.64041666667 | 15760 |
| 015255 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:11am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594563.3 | 511557.9 | 50233 | 1.64041666667 | 15255 |
| 014716 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:12am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594562.0 | 511559.7 | 50235 | 1.64041666667 | 14716 |
| 014615 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:13am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594561.0 | 511561.7 | 50237 | 1.64041666667 | 14615 |
| 015256 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:14am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594559.8 | 511563.8 | 50239 | 1.64041666667 | 15256 |
| 014664 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:15am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594559.2 | 511566.0 | 50241 | 1.64041666667 | 14664 |
| 013566 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:16am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594558.0 | 511568.4 | 50243 | 1.64041666667 | 13566 |
| 013076 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:17am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594557.1 | 511570.4 | 50245 | 1.64041666667 | 13076 |
| 013467 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:18am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594556.1 | 511572.7 | 50247 | 1.64041666667 | 13467 |
| 013635 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:19am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594555.1 | 511574.4 | 50249 | 1.64041666667 | 13635 |
| 014082 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:20am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594554.5 | 511577.1 | 50251 | 1.64041666667 | 14082 |
| 013929 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:21am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594553.5 | 511579.0 | 50253 | 1.64041666667 | 13929 |
| 014375 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:22am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594552.3 | 511581.0 | 50255 | 1.64041666667 | 14375 |
| 014071 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:23am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594551.4 | 511582.8 | 50257 | 1.64041666667 | 14071 |
| 013307 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:24am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594550.2 | 511584.9 | 50259 | 1.64041666667 | 13307 |
| 013732 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:25am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594549.9 | 511587.0 | 50261 | 1.64041666667 | 13732 |
| 013792 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:26am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594548.9 | 511589.3 | 50263 | 1.64041666667 | 13792 |
| 013690 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:27am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594548.1 | 511591.2 | 50265 | 1.64041666667 | 13690 |
| 013086 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:28am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594547.5 | 511593.7 | 50267 | 1.64041666667 | 13086 |
| 013046 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:29am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594546.7 | 511595.4 | 50269 | 1.64041666667 | 13046 |
| 012911 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:30am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594546.3 | 511597.8 | 50271 | 1.64041666667 | 12911 |
| 013397 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:31am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594545.6 | 511599.7 | 50273 | 1.64041666667 | 13397 |
| 012748 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:32am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594544.6 | 511602.2 | 50275 | 1.64041666667 | 12748 |
| 012391 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:33am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594543.9 | 511604.1 | 50277 | 1.64041666667 | 12391 |
| 013210 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:34am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594543.0 | 511606.3 | 50279 | 1.64041666667 | 13210 |
| 012665 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:35am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594542.6 | 511608.4 | 50281 | 1.64041666667 | 12665 |
| 012854 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:36am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594542.0 | 511611.0 | 50283 | 1.64041666667 | 12854 |
| 012758 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:37am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594541.0 | 511613.2 | 50285 | 1.64041666667 | 12758 |
| 013409 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:38am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594540.4 | 511615.8 | 50287 | 1.64041666667 | 13409 |
| 013782 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:39am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594539.6 | 511617.8 | 50289 | 1.64041666667 | 13782 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013565 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:40am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594538.5 | 511619.8 | 50291 | 1.64041666667 | 13565 |
| 013443 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:41am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594538.0 | 511621.5 | 50293 | 1.64041666667 | 13443 |
| 012751 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:42am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594536.6 | 511623.7 | 50295 | 1.64041666667 | 12751 |
| 013097 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:43am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594535.3 | 511625.8 | 50297 | 1.64041666667 | 13097 |
| 013495 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:44am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594534.5 | 511627.9 | 50299 | 1.64041666667 | 13495 |
| 013133 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:45am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594533.4 | 511629.6 | 50301 | 1.64041666667 | 13133 |
| 012397 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:46am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594532.7 | 511631.7 | 50303 | 1.64041666667 | 12397 |
| 011923 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:47am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594531.7 | 511633.7 | 50305 | 1.64041666667 | 11923 |
| 012392 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:48am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594531.1 | 511636.1 | 50307 | 1.64041666667 | 12392 |
| 011958 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:49am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594531.2 | 511638.1 | 50309 | 1.64041666667 | 11958 |
| 011766 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:50am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594531.2 | 511640.0 | 50311 | 1.64041666667 | 11766 |
| 011906 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:51am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594532.8 | 511640.9 | 50313 | 1.64041666667 | 11906 |
| 011864 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:52am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594534.7 | 511642.4 | 50315 | 1.64041666667 | 11864 |
| 013439 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:53am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594536.7 | 511643.0 | 50317 | 1.64041666667 | 13439 |
| 014467 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:54am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594539.1 | 511643.6 | 50319 | 1.64041666667 | 14467 |
| 013762 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:55am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594540.8 | 511644.3 | 50321 | 1.64041666667 | 13762 |
| 013351 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:56am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594542.9 | 511644.8 | 50323 | 1.64041666667 | 13351 |
| 013067 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:57am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594544.7 | 511646.0 | 50325 | 1.64041666667 | 13067 |
| 012923 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:58am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594546.7 | 511646.9 | 50327 | 1.64041666667 | 12923 |
| 012091 | 0 | GeoXH 6000 | 08/19/2015 | 11:50:59am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594548.2 | 511646.5 | 50329 | 1.64041666667 | 12091 |
| 013289 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:00am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594549.3 | 511645.3 | 50331 | 1.64041666667 | 13289 |
| 013805 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:01am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594549.1 | 511643.3 | 50333 | 1.64041666667 | 13805 |
| 013818 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:02am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594549.0 | 511641.1 | 50335 | 1.64041666667 | 13818 |
| 013405 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:03am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594548.8 | 511639.1 | 50337 | 1.64041666667 | 13405 |
| 013323 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:04am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594548.6 | 511637.0 | 50339 | 1.64041666667 | 13323 |
| 012954 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:05am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594548.9 | 511635.1 | 50341 | 1.64041666667 | 12954 |
| 013211 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:06am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594548.9 | 511632.6 | 50343 | 1.64041666667 | 13211 |
| 012726 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:07am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594549.4 | 511630.6 | 50345 | 1.64041666667 | 12726 |
| 012851 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:08am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594550.1 | 511628.4 | 50347 | 1.64041666667 | 12851 |
| 013273 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:09am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594550.4 | 511626.5 | 50349 | 1.64041666667 | 13273 |
| 013054 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:10am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594551.1 | 511624.2 | 50351 | 1.64041666667 | 13054 |
| 012210 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:11am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594551.2 | 511622.3 | 50353 | 1.64041666667 | 12210 |
| 012425 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:12am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594552.4 | 511620.0 | 50355 | 1.64041666667 | 12425 |
| 012149 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:13am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594553.6 | 511618.0 | 50357 | 1.64041666667 | 12149 |
| 012459 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:14am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594554.5 | 511616.1 | 50359 | 1.64041666667 | 12459 |
| 013833 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:15am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594555.6 | 511614.2 | 50361 | 1.64041666667 | 13833 |
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:16am | Sensor | 1797-S0037-905-G-ACK | 6821.9 | 1594556.0 | 511611.7 | 50363 | 1.64041666667 | 13451 |
| 013258 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:17am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594556.8 | 511609.5 | 50365 | 1.64041666667 | 13258 |
| 012640 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:18am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594557.4 | 511606.9 | 50367 | 1.64041666667 | 12640 |
| 012030 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:19am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594557.7 | 511605.2 | 50369 | 1.64041666667 | 12030 |
| 012707 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:20am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594558.6 | 511603.0 | 50371 | 1.64041666667 | 12707 |
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:21am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594558.9 | 511601.0 | 50373 | 1.64041666667 | 12562 |
| 011866 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:22am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594559.7 | 511598.3 | 50375 | 1.64041666667 | 11866 |
| 012510 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:23am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594560.2 | 511596.1 | 50377 | 1.64041666667 | 12510 |
| 012376 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:24am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594560.7 | 511593.5 | 50379 | 1.64041666667 | 12376 |
| 013524 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:25am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594561.3 | 511591.5 | 50381 | 1.64041666667 | 13524 |
| 014117 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:26am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594561.4 | 511589.3 | 50383 | 1.64041666667 | 14117 |
| 014151 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:27am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594561.8 | 511587.1 | 50385 | 1.64041666667 | 14151 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013945 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:28am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594562.4 | 511584.8 | 50387 | 1.64041666667 | 13945 |
| 014099 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:29am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594562.3 | 511582.1 | 50389 | 1.64041666667 | 14099 |
| 013098 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:30am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594562.7 | 511580.3 | 50391 | 1.64041666667 | 13098 |
| 013322 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:31am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594562.8 | 511578.3 | 50393 | 1.64041666667 | 13322 |
| 013216 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:32am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594563.3 | 511575.7 | 50395 | 1.64041666667 | 13216 |
| 013561 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:33am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594564.1 | 511574.1 | 50397 | 1.64041666667 | 13561 |
| 013883 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:34am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594565.1 | 511572.0 | 50399 | 1.64041666667 | 13883 |
| 013772 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:35am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594566.7 | 511570.5 | 50401 | 1.64041666667 | 13772 |
| 014354 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:36am | Sensor | 1797-S0037-905-G-ACK | 6822.3 | 1594568.3 | 511568.5 | 50403 | 1.64041666667 | 14354 |
| 014674 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:37am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594569.6 | 511567.1 | 50405 | 1.64041666667 | 14674 |
| 014696 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:38am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594571.5 | 511565.6 | 50407 | 1.64041666667 | 14696 |
| 014132 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:39am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594572.9 | 511564.1 | 50409 | 1.64041666667 | 14132 |
| 015276 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:40am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594574.7 | 511562.6 | 50411 | 1.64041666667 | 15276 |
| 015763 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:41am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594576.0 | 511561.0 | 50413 | 1.64041666667 | 15763 |
| 015909 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:42am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594576.7 | 511558.8 | 50415 | 1.64041666667 | 15909 |
| 014761 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:43am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594577.6 | 511557.0 | 50417 | 1.64041666667 | 14761 |
| 014708 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:44am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594578.0 | 511554.5 | 50419 | 1.64041666667 | 14708 |
| 015233 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:45am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594578.7 | 511552.5 | 50421 | 1.64041666667 | 15233 |
| 014366 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:46am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594579.5 | 511549.9 | 50423 | 1.64041666667 | 14366 |
| 014958 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:47am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594580.2 | 511548.0 | 50425 | 1.64041666667 | 14958 |
| 014181 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:48am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594581.6 | 511545.7 | 50427 | 1.64041666667 | 14181 |
| 014727 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:49am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594582.3 | 511543.6 | 50429 | 1.64041666667 | 14727 |
| 015769 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:50am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594583.1 | 511541.2 | 50431 | 1.64041666667 | 15769 |
| 015852 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:51am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594584.1 | 511539.1 | 50433 | 1.64041666667 | 15852 |
| 015554 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:52am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594584.6 | 511536.6 | 50435 | 1.64041666667 | 15554 |
| 015402 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:53am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594585.4 | 511534.4 | 50437 | 1.64041666667 | 15402 |
| 015788 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:54am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594586.4 | 511532.0 | 50439 | 1.64041666667 | 15788 |
| 015203 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:55am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594587.3 | 511530.1 | 50441 | 1.64041666667 | 15203 |
| 015152 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:56am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594588.8 | 511528.2 | 50443 | 1.64041666667 | 15152 |
| 015655 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:57am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594589.6 | 511526.4 | 50445 | 1.64041666667 | 15655 |
| 014731 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:58am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594590.8 | 511524.2 | 50447 | 1.64041666667 | 14731 |
| 014803 | 0 | GeoXH 6000 | 08/19/2015 | 11:51:59am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594591.9 | 511522.3 | 50449 | 1.64041666667 | 14803 |
| 014507 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:00am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594593.0 | 511520.6 | 50451 | 1.64041666667 | 14507 |
| 014467 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:01am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594594.6 | 511519.9 | 50453 | 1.64041666667 | 14467 |
| 014843 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:02am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594596.9 | 511519.8 | 50455 | 1.64041666667 | 14843 |
| 014762 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:03am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594598.7 | 511520.4 | 50457 | 1.64041666667 | 14762 |
| 014914 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:04am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594600.8 | 511520.9 | 50459 | 1.64041666667 | 14914 |
| 015334 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:05am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594602.7 | 511521.0 | 50461 | 1.64041666667 | 15334 |
| 016238 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:06am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594604.9 | 511522.1 | 50463 | 1.64041666667 | 16238 |
| 014901 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:07am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594606.7 | 511522.9 | 50465 | 1.64041666667 | 14901 |
| 014569 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:08am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594608.0 | 511524.4 | 50467 | 1.64041666667 | 14569 |
| 014090 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:09am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594608.9 | 511526.4 | 50469 | 1.64041666667 | 14090 |
| 014330 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:10am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594608.8 | 511528.2 | 50471 | 1.64041666667 | 14330 |
| 015276 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:11am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594607.9 | 511529.9 | 50473 | 1.64041666667 | 15276 |
| 014870 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:12am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594606.8 | 511531.6 | 50475 | 1.64041666667 | 14870 |
| 014559 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:13am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594605.1 | 511532.7 | 50477 | 1.64041666667 | 14559 |
| 015202 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:14am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594603.3 | 511534.2 | 50479 | 1.64041666667 | 15202 |
| 015323 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:15am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594601.8 | 511535.5 | 50481 | 1.64041666667 | 15323 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015062 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:16am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594600.5 | 511537.6 | 50483 | 1.64041666667 | 15062 |
| 015710 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:17am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594600.2 | 511539.6 | 50485 | 1.64041666667 | 15710 |
| 014761 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:18am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594599.9 | 511542.1 | 50487 | 1.64041666667 | 14761 |
| 014393 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:19am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594600.4 | 511543.9 | 50489 | 1.64041666667 | 14393 |
| 014501 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:20am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594600.5 | 511546.4 | 50491 | 1.64041666667 | 14501 |
| 014854 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:21am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594600.2 | 511548.2 | 50493 | 1.64041666667 | 14854 |
| 015015 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:22am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594599.9 | 511550.2 | 50495 | 1.64041666667 | 15015 |
| 014851 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:23am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594598.9 | 511551.9 | 50497 | 1.64041666667 | 14851 |
| 014406 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:24am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594598.1 | 511554.0 | 50499 | 1.64041666667 | 14406 |
| 015258 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:25am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594597.2 | 511555.8 | 50501 | 1.64041666667 | 15258 |
| 015340 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:26am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594596.2 | 511557.8 | 50503 | 1.64041666667 | 15340 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:27am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594595.5 | 511559.5 | 50505 | 1.64041666667 | 14463 |
| 015298 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:28am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594594.3 | 511561.3 | 50507 | 1.64041666667 | 15298 |
| 015145 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:29am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594593.6 | 511563.3 | 50509 | 1.64041666667 | 15145 |
| 015029 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:30am | Sensor | 1797-S0037-905-G-ACK | 6822.8 | 1594592.3 | 511565.0 | 50511 | 1.64041666667 | 15029 |
| 015436 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:31am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594591.2 | 511566.7 | 50513 | 1.64041666667 | 15436 |
| 015088 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:32am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594589.7 | 511568.5 | 50515 | 1.64041666667 | 15088 |
| 014734 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:33am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594588.6 | 511570.4 | 50517 | 1.64041666667 | 14734 |
| 014865 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:34am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594587.6 | 511572.7 | 50519 | 1.64041666667 | 14865 |
| 015299 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:35am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594586.8 | 511574.7 | 50521 | 1.64041666667 | 15299 |
| 015941 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:36am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594586.4 | 511576.8 | 50523 | 1.64041666667 | 15941 |
| 016676 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:37am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594585.6 | 511578.6 | 50525 | 1.64041666667 | 16676 |
| 015875 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:38am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594585.2 | 511581.2 | 50527 | 1.64041666667 | 15875 |
| 015267 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:39am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594584.7 | 511583.1 | 50529 | 1.64041666667 | 15267 |
| 015158 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:40am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594583.7 | 511585.3 | 50531 | 1.64041666667 | 15158 |
| 013881 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:41am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594583.3 | 511587.2 | 50533 | 1.64041666667 | 13881 |
| 014078 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:42am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594582.1 | 511589.7 | 50535 | 1.64041666667 | 14078 |
| 013941 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:43am | Sensor | 1797-S0037-905-G-ACK | 6822.7 | 1594581.5 | 511591.9 | 50537 | 1.64041666667 | 13941 |
| 012934 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:44am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594580.7 | 511594.2 | 50539 | 1.64041666667 | 12934 |
| 012863 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:45am | Sensor | 1797-S0037-905-G-ACK | 6822.6 | 1594579.9 | 511596.3 | 50541 | 1.64041666667 | 12863 |
| 014855 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:46am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594579.4 | 511598.8 | 50543 | 1.64041666667 | 14855 |
| 014416 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:47am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594578.5 | 511600.9 | 50545 | 1.64041666667 | 14416 |
| 015091 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:48am | Sensor | 1797-S0037-905-G-ACK | 6822.5 | 1594578.0 | 511603.1 | 50547 | 1.64041666667 | 15091 |
| 014729 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:49am | Sensor | 1797-S0037-905-G-ACK | 6822.4 | 1594577.7 | 511605.1 | 50549 | 1.64041666667 | 14729 |
| 013685 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:50am | Sensor | 1797-S0037-905-G-ACK | 6822.2 | 1594576.8 | 511608.0 | 50551 | 1.64041666667 | 13685 |
| 013548 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:51am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594576.8 | 511610.8 | 50553 | 1.64041666667 | 13548 |
| 012893 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:52am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594576.2 | 511613.7 | 50555 | 1.64041666667 | 12893 |
| 013485 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:53am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594575.8 | 511615.7 | 50557 | 1.64041666667 | 13485 |
| 013045 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:54am | Sensor | 1797-S0037-905-G-ACK | 6822.1 | 1594575.8 | 511618.5 | 50559 | 1.64041666667 | 13045 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:55am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594575.3 | 511620.7 | 50561 | 1.64041666667 | 12768 |
| 012462 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:56am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594575.2 | 511623.6 | 50563 | 1.64041666667 | 12462 |
| 012049 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:57am | Sensor | 1797-S0037-905-G-ACK | 6822.0 | 1594575.4 | 511625.5 | 50565 | 1.64041666667 | 12049 |
| 012680 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:58am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594575.4 | 511628.2 | 50567 | 1.64041666667 | 12680 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 11:52:59am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594575.7 | 511630.3 | 50569 | 1.64041666667 | 12420 |
| 012518 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:00am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594575.6 | 511632.5 | 50571 | 1.64041666667 | 12518 |
| 012321 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:01am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594574.7 | 511634.0 | 50573 | 1.64041666667 | 12321 |
| 012278 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:02am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594573.9 | 511635.9 | 50575 | 1.64041666667 | 12278 |
| 012389 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:03am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594572.1 | 511637.3 | 50577 | 1.64041666667 | 12389 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013163 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:04am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594569.8 | 511638.7 | 50579 | 1.64041666667 | 13163 |
| 013187 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:05am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594568.3 | 511639.9 | 50581 | 1.64041666667 | 13187 |
| 013357 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:06am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594566.2 | 511641.0 | 50583 | 1.64041666667 | 13357 |
| 013821 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:07am | Sensor | 1797-S0037-905-G-ACK | 6821.5 | 1594564.9 | 511642.1 | 50585 | 1.64041666667 | 13821 |
| 014704 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:08am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594563.0 | 511643.6 | 50587 | 1.64041666667 | 14704 |
| 013993 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:09am | Sensor | 1797-S0037-905-G-ACK | 6821.8 | 1594561.7 | 511645.0 | 50589 | 1.64041666667 | 13993 |
| 013624 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:10am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594560.8 | 511647.1 | 50591 | 1.64041666667 | 13624 |
| 012996 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:11am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594559.3 | 511648.9 | 50593 | 1.64041666667 | 12996 |
| 012755 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:12am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594557.8 | 511650.6 | 50595 | 1.64041666667 | 12755 |
| 014059 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:13am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594556.4 | 511652.2 | 50597 | 1.64041666667 | 14059 |
| 013473 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:14am | Sensor | 1797-S0037-905-G-ACK | 6821.7 | 1594554.2 | 511653.5 | 50599 | 1.64041666667 | 13473 |
| 014163 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:15am | Sensor | 1797-S0037-905-G-ACK | 6821.6 | 1594553.4 | 511654.4 | 50602 | 1.64041666667 | 14163 |
| 012827 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:45pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.2 | 511817.9 | 45965 | 1.64041666667 | 12827 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:46pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.2 | 511817.9 | 45966 | 1.64041666667 | 12180 |
| 012723 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:47pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.2 | 511817.9 | 45969 | 1.64041666667 | 12723 |
| 012122 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:48pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.3 | 511817.8 | 45971 | 1.64041666667 | 12122 |
| 013336 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:49pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.3 | 511817.8 | 45973 | 1.64041666667 | 13336 |
| 012451 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:50pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.3 | 511817.8 | 45975 | 1.64041666667 | 12451 |
| 012119 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.3 | 511817.8 | 45977 | 1.64041666667 | 12119 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:52pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.3 | 511817.8 | 45979 | 1.64041666667 | 12652 |
| 012756 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:53pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.2 | 511817.9 | 45981 | 1.64041666667 | 12756 |
| 012268 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:54pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.9 | 45983 | 1.64041666667 | 12268 |
| 012443 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:55pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.9 | 45985 | 1.64041666667 | 12443 |
| 012684 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:56pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 45987 | 1.64041666667 | 12684 |
| 012047 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:57pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 45989 | 1.64041666667 | 12047 |
| 012064 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:58pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 45991 | 1.64041666667 | 12064 |
| 011803 | 0 | GeoXH 6000 | 08/19/2015 | 01:50:59pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 45993 | 1.64041666667 | 11803 |
| 012144 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:00pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 45995 | 1.64041666667 | 12144 |
| 011751 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:01pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 45997 | 1.64041666667 | 11751 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:02pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 45999 | 1.64041666667 | 12475 |
| 011959 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:03pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.3 | 511817.8 | 46001 | 1.64041666667 | 11959 |
| 012690 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:04pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.3 | 511817.7 | 46003 | 1.64041666667 | 12690 |
| 012875 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:05pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.3 | 511817.8 | 46005 | 1.64041666667 | 12875 |
| 012327 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:06pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 46007 | 1.64041666667 | 12327 |
| 013046 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:07pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 46009 | 1.64041666667 | 13046 |
| 013278 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:08pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 46011 | 1.64041666667 | 13278 |
| 012786 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:09pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 46013 | 1.64041666667 | 12786 |
| 012435 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:10pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 46015 | 1.64041666667 | 12435 |
| 012762 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:11pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 46017 | 1.64041666667 | 12762 |
| 012848 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:12pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 46019 | 1.64041666667 | 12848 |
| 012447 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:13pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.9 | 46021 | 1.64041666667 | 12447 |
| 011869 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:14pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.8 | 46023 | 1.64041666667 | 11869 |
| 012083 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:15pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594002.2 | 511817.7 | 46025 | 1.64041666667 | 12083 |
| 012234 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:16pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.2 | 511817.7 | 46027 | 1.64041666667 | 12234 |
| 012357 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:17pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.2 | 511817.8 | 46029 | 1.64041666667 | 12357 |
| 011765 | 0 | GeoXH 6000 | 08/19/2015 | 01:51:18pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594002.3 | 511817.9 | 46031 | 1.64041666667 | 11765 |
| 010849 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:35pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.0 | 511843.6 | 46032 | 1.64041666667 | 10849 |
| 011562 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:37pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.0 | 511843.6 | 46035 | 1.64041666667 | 11562 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011319 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:38pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.6 | 46037 | 1.64041666667 | 11319 |
| 011407 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.0 | 511843.6 | 46039 | 1.64041666667 | 11407 |
| 011268 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.0 | 511843.6 | 46040 | 1.64041666667 | 11268 |
| 011888 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:41pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.0 | 511843.6 | 46043 | 1.64041666667 | 11888 |
| 012072 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:41pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.6 | 46044 | 1.64041666667 | 12072 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:43pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.0 | 511843.6 | 46047 | 1.64041666667 | 12760 |
| 012450 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:43pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.0 | 511843.6 | 46048 | 1.64041666667 | 12450 |
| 011413 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:45pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.5 | 46051 | 1.64041666667 | 11413 |
| 011392 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:46pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.5 | 46053 | 1.64041666667 | 11392 |
| 011411 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:47pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.5 | 46055 | 1.64041666667 | 11411 |
| 010566 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:48pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.5 | 46057 | 1.64041666667 | 10566 |
| 010488 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:49pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.5 | 46059 | 1.64041666667 | 10488 |
| 011457 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:49pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.5 | 46060 | 1.64041666667 | 11457 |
| 011319 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594078.1 | 511843.6 | 46063 | 1.64041666667 | 11319 |
| 011250 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594078.1 | 511843.6 | 46064 | 1.64041666667 | 11250 |
| 011278 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:52pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594078.0 | 511843.6 | 46066 | 1.64041666667 | 11278 |
| 011331 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:53pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594078.0 | 511843.5 | 46068 | 1.64041666667 | 11331 |
| 011451 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:55pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594077.8 | 511843.3 | 46071 | 1.64041666667 | 11451 |
| 011211 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:55pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594076.3 | 511843.4 | 46072 | 1.64041666667 | 11211 |
| 010806 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:57pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594071.5 | 511841.8 | 46075 | 1.64041666667 | 10806 |
| 011103 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:57pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594068.7 | 511841.0 | 46076 | 1.64041666667 | 11103 |
| 010925 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:58pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594064.1 | 511838.9 | 46078 | 1.64041666667 | 10925 |
| 011013 | 0 | GeoXH 6000 | 08/19/2015 | 01:59:59pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594060.5 | 511837.4 | 46080 | 1.64041666667 | 11013 |
| 010680 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:01pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.6 | 511837.1 | 46083 | 1.64041666667 | 10680 |
| 011122 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:01pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.5 | 511836.8 | 46084 | 1.64041666667 | 11122 |
| 011221 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:03pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.4 | 511836.9 | 46087 | 1.64041666667 | 11221 |
| 011314 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:03pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.4 | 511836.9 | 46088 | 1.64041666667 | 11314 |
| 011134 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:04pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.5 | 511836.7 | 46090 | 1.64041666667 | 11134 |
| 010965 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:05pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.5 | 511836.7 | 46092 | 1.64041666667 | 10965 |
| 010360 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:07pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.6 | 511836.7 | 46095 | 1.64041666667 | 10360 |
| 010747 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:07pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.6 | 511836.7 | 46096 | 1.64041666667 | 10747 |
| 011033 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:09pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.7 | 46099 | 1.64041666667 | 11033 |
| 011351 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:09pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.5 | 511836.6 | 46100 | 1.64041666667 | 11351 |
| 010750 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:11pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.6 | 46103 | 1.64041666667 | 10750 |
| 010472 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:11pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.6 | 46104 | 1.64041666667 | 10472 |
| 010690 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:12pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.7 | 46106 | 1.64041666667 | 10690 |
| 010753 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:13pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.4 | 511836.7 | 46108 | 1.64041666667 | 10753 |
| 010833 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:15pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.4 | 511836.6 | 46111 | 1.64041666667 | 10833 |
| 011494 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:15pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.6 | 46112 | 1.64041666667 | 11494 |
| 011347 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:16pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.7 | 46114 | 1.64041666667 | 11347 |
| 010740 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:17pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.7 | 46116 | 1.64041666667 | 10740 |
| 010174 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:18pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.6 | 511836.6 | 46118 | 1.64041666667 | 10174 |
| 010702 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:19pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.5 | 511836.5 | 46120 | 1.64041666667 | 10702 |
| 011007 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:20pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.5 | 511836.5 | 46122 | 1.64041666667 | 11007 |
| 011501 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:21pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.6 | 511836.5 | 46124 | 1.64041666667 | 11501 |
| 011389 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:22pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.5 | 46126 | 1.64041666667 | 11389 |
| 010734 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:23pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.6 | 511836.5 | 46128 | 1.64041666667 | 10734 |
| 011190 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:24pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.7 | 511836.5 | 46130 | 1.64041666667 | 11190 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010727 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:25pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46132 | 1.64041666667 | 10727 |
| 011659 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:26pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.6 | 511836.5 | 46134 | 1.64041666667 | 11659 |
| 011583 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:27pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.6 | 511836.5 | 46136 | 1.64041666667 | 11583 |
| 010985 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:28pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46138 | 1.64041666667 | 10985 |
| 010717 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:29pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46140 | 1.64041666667 | 10717 |
| 010858 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:30pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46142 | 1.64041666667 | 10858 |
| 010570 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:31pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46144 | 1.64041666667 | 10570 |
| 011503 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:32pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46146 | 1.64041666667 | 11503 |
| 011143 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:33pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46148 | 1.64041666667 | 11143 |
| 010985 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:34pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46150 | 1.64041666667 | 10985 |
| 011077 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:35pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.5 | 46152 | 1.64041666667 | 11077 |
| 010843 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:37pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.8 | 511836.5 | 46155 | 1.64041666667 | 10843 |
| 012054 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:37pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.8 | 511836.5 | 46156 | 1.64041666667 | 12054 |
| 011265 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.8 | 511836.5 | 46159 | 1.64041666667 | 11265 |
| 010184 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.8 | 511836.5 | 46160 | 1.64041666667 | 10184 |
| 010513 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:40pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.8 | 511836.6 | 46162 | 1.64041666667 | 10513 |
| 011688 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:41pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594058.7 | 511836.6 | 46164 | 1.64041666667 | 11688 |
| 011780 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:42pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594058.4 | 511836.6 | 46166 | 1.64041666667 | 11780 |
| 011591 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:43pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594057.5 | 511836.6 | 46168 | 1.64041666667 | 11591 |
| 011920 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:44pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594054.8 | 511834.9 | 46170 | 1.64041666667 | 11920 |
| 011295 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:45pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594051.9 | 511832.6 | 46172 | 1.64041666667 | 11295 |
| 011753 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:47pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594048.1 | 511830.0 | 46175 | 1.64041666667 | 11753 |
| 011831 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:47pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594044.9 | 511828.3 | 46176 | 1.64041666667 | 11831 |
| 012047 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:48pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594040.9 | 511826.6 | 46178 | 1.64041666667 | 12047 |
| 012371 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:49pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594036.8 | 511824.8 | 46180 | 1.64041666667 | 12371 |
| 011849 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594033.1 | 511822.3 | 46183 | 1.64041666667 | 11849 |
| 012260 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594030.1 | 511820.7 | 46184 | 1.64041666667 | 12260 |
| 012513 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:52pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594026.0 | 511818.8 | 46186 | 1.64041666667 | 12513 |
| 012866 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:53pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594022.6 | 511817.6 | 46188 | 1.64041666667 | 12866 |
| 013102 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:54pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594018.7 | 511816.3 | 46190 | 1.64041666667 | 13102 |
| 012620 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:55pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594015.7 | 511814.6 | 46192 | 1.64041666667 | 12620 |
| 012843 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:56pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594011.9 | 511812.3 | 46194 | 1.64041666667 | 12843 |
| 013314 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:57pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1594008.5 | 511810.4 | 46196 | 1.64041666667 | 13314 |
| 014044 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:58pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1594004.6 | 511809.2 | 46198 | 1.64041666667 | 14044 |
| 013682 | 0 | GeoXH 6000 | 08/19/2015 | 02:00:59pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1594001.1 | 511807.9 | 46200 | 1.64041666667 | 13682 |
| 013824 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:01pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593997.2 | 511805.8 | 46203 | 1.64041666667 | 13824 |
| 013003 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:01pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593994.1 | 511804.5 | 46204 | 1.64041666667 | 13003 |
| 012639 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:02pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593990.2 | 511803.4 | 46206 | 1.64041666667 | 12639 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:03pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593987.1 | 511802.5 | 46208 | 1.64041666667 | 12539 |
| 012048 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:04pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593983.5 | 511800.6 | 46210 | 1.64041666667 | 12048 |
| 012207 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:05pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593980.5 | 511799.5 | 46212 | 1.64041666667 | 12207 |
| 012221 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:06pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593977.7 | 511801.8 | 46214 | 1.64041666667 | 12221 |
| 013894 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:07pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593975.7 | 511804.8 | 46216 | 1.64041666667 | 13894 |
| 014483 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:08pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593973.1 | 511808.6 | 46218 | 1.64041666667 | 14483 |
| 013449 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:09pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593971.0 | 511811.9 | 46220 | 1.64041666667 | 13449 |
| 013115 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:10pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593969.3 | 511815.7 | 46222 | 1.64041666667 | 13115 |
| 012379 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:11pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593968.1 | 511818.9 | 46224 | 1.64041666667 | 12379 |
| 012731 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:12pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593966.2 | 511822.5 | 46226 | 1.64041666667 | 12731 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012598 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:13pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593964.4 | 511825.8 | 46228 | 1.64041666667 | 12598 |
| 013027 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:14pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593963.3 | 511829.6 | 46230 | 1.64041666667 | 13027 |
| 013080 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:15pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593962.0 | 511833.5 | 46232 | 1.64041666667 | 13080 |
| 012150 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:16pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593961.2 | 511837.4 | 46234 | 1.64041666667 | 12150 |
| 011784 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:17pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593960.1 | 511841.0 | 46236 | 1.64041666667 | 11784 |
| 013026 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:19pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593958.2 | 511845.0 | 46239 | 1.64041666667 | 13026 |
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:19pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593956.6 | 511847.5 | 46240 | 1.64041666667 | 12652 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:20pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593953.9 | 511850.7 | 46242 | 1.64041666667 | 12742 |
| 012289 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:21pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593951.8 | 511853.4 | 46244 | 1.64041666667 | 12289 |
| 012418 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:22pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593949.0 | 511857.0 | 46246 | 1.64041666667 | 12418 |
| 011770 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:23pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593946.9 | 511860.2 | 46248 | 1.64041666667 | 11770 |
| 012590 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:24pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593945.1 | 511864.4 | 46250 | 1.64041666667 | 12590 |
| 013052 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:25pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593943.3 | 511867.7 | 46252 | 1.64041666667 | 13052 |
| 013627 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:26pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593941.3 | 511871.1 | 46254 | 1.64041666667 | 13627 |
| 013710 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:27pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593939.2 | 511874.6 | 46256 | 1.64041666667 | 13710 |
| 013337 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:28pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593937.1 | 511877.5 | 46258 | 1.64041666667 | 13337 |
| 013809 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:29pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593935.5 | 511880.5 | 46260 | 1.64041666667 | 13809 |
| 014000 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:31pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593934.0 | 511884.7 | 46263 | 1.64041666667 | 14000 |
| 013282 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:31pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1593932.7 | 511887.5 | 46264 | 1.64041666667 | 13282 |
| 013336 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:32pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593931.1 | 511890.7 | 46266 | 1.64041666667 | 13336 |
| 013554 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:33pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593930.1 | 511893.9 | 46268 | 1.64041666667 | 13554 |
| 013279 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:34pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593929.4 | 511897.3 | 46270 | 1.64041666667 | 13279 |
| 012779 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:35pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593930.5 | 511899.6 | 46272 | 1.64041666667 | 12779 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:36pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1593933.4 | 511902.3 | 46274 | 1.64041666667 | 12768 |
| 012867 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:37pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593936.4 | 511904.5 | 46276 | 1.64041666667 | 12867 |
| 014257 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:39pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593940.5 | 511907.3 | 46279 | 1.64041666667 | 14257 |
| 013525 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:39pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593943.5 | 511908.5 | 46280 | 1.64041666667 | 13525 |
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:41pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593948.0 | 511910.2 | 46283 | 1.64041666667 | 13795 |
| 013954 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:41pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593950.7 | 511911.9 | 46284 | 1.64041666667 | 13954 |
| 014224 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:42pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593953.9 | 511914.1 | 46286 | 1.64041666667 | 14224 |
| 013851 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:43pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1593956.8 | 511915.7 | 46288 | 1.64041666667 | 13851 |
| 013941 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:44pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1593960.3 | 511917.7 | 46290 | 1.64041666667 | 13941 |
| 015177 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:45pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1593963.3 | 511919.4 | 46292 | 1.64041666667 | 15177 |
| 015534 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:46pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1593966.8 | 511921.4 | 46294 | 1.64041666667 | 15534 |
| 015158 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:47pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1593969.9 | 511922.5 | 46296 | 1.64041666667 | 15158 |
| 015126 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:48pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1593973.9 | 511923.9 | 46298 | 1.64041666667 | 15126 |
| 014546 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:49pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1593977.0 | 511925.3 | 46300 | 1.64041666667 | 14546 |
| 013387 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:50pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593981.0 | 511927.2 | 46302 | 1.64041666667 | 13387 |
| 013567 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:51pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593984.2 | 511928.8 | 46304 | 1.64041666667 | 13567 |
| 013564 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:52pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593987.9 | 511930.4 | 46306 | 1.64041666667 | 13564 |
| 013682 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:53pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1593990.9 | 511931.6 | 46308 | 1.64041666667 | 13682 |
| 013396 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:54pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593994.8 | 511933.9 | 46310 | 1.64041666667 | 13396 |
| 012808 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:55pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1593997.2 | 511935.8 | 46312 | 1.64041666667 | 12808 |
| 011749 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:56pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594000.7 | 511938.1 | 46314 | 1.64041666667 | 11749 |
| 011431 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:57pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594003.8 | 511939.2 | 46316 | 1.64041666667 | 11431 |
| 011485 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:58pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594007.4 | 511940.6 | 46318 | 1.64041666667 | 11485 |
| 011545 | 0 | GeoXH 6000 | 08/19/2015 | 02:01:59pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594010.2 | 511942.4 | 46320 | 1.64041666667 | 11545 |
| 011369 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:00pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594013.4 | 511944.6 | 46322 | 1.64041666667 | 11369 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011892 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:01pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594016.7 | 511946.1 | 46324 | 1.64041666667 | 11892 |
| 011909 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:02pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594020.2 | 511947.1 | 46326 | 1.64041666667 | 11909 |
| 013081 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:03pm | Sensor | 1797-S0036-G-636-DTE | 6820.3 | 1594023.0 | 511948.1 | 46328 | 1.64041666667 | 13081 |
| 012608 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:04pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594026.5 | 511949.8 | 46330 | 1.64041666667 | 12608 |
| 012312 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:05pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594030.0 | 511949.6 | 46332 | 1.64041666667 | 12312 |
| 012033 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:06pm | Sensor | 1797-S0036-G-636-DTE | 6820.3 | 1594032.5 | 511947.3 | 46334 | 1.64041666667 | 12033 |
| 013068 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:07pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594034.8 | 511944.9 | 46336 | 1.64041666667 | 13068 |
| 013141 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:08pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594037.6 | 511941.5 | 46338 | 1.64041666667 | 13141 |
| 013324 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:09pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594039.1 | 511938.5 | 46340 | 1.64041666667 | 13324 |
| 014927 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:10pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594040.2 | 511934.7 | 46342 | 1.64041666667 | 14927 |
| 014126 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:11pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594041.3 | 511931.2 | 46344 | 1.64041666667 | 14126 |
| 013556 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:12pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594042.9 | 511927.0 | 46346 | 1.64041666667 | 13556 |
| 012957 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:13pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594044.1 | 511923.2 | 46348 | 1.64041666667 | 12957 |
| 013258 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:14pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594045.0 | 511918.9 | 46350 | 1.64041666667 | 13258 |
| 012588 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:15pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594046.2 | 511915.7 | 46352 | 1.64041666667 | 12588 |
| 012068 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:16pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594048.0 | 511911.6 | 46354 | 1.64041666667 | 12068 |
| 012510 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:17pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594049.6 | 511908.6 | 46356 | 1.64041666667 | 12510 |
| 011290 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:18pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594051.6 | 511905.5 | 46358 | 1.64041666667 | 11290 |
| 012200 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:19pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594052.7 | 511902.2 | 46360 | 1.64041666667 | 12200 |
| 012165 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:20pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594053.6 | 511898.3 | 46362 | 1.64041666667 | 12165 |
| 011665 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:21pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594054.7 | 511894.9 | 46364 | 1.64041666667 | 11665 |
| 012622 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:22pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594056.4 | 511891.4 | 46366 | 1.64041666667 | 12622 |
| 012027 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:23pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594057.9 | 511888.5 | 46368 | 1.64041666667 | 12027 |
| 012262 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:25pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1594059.9 | 511884.4 | 46371 | 1.64041666667 | 12262 |
| 011705 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:25pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1594061.3 | 511881.4 | 46372 | 1.64041666667 | 11705 |
| 011406 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:26pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594063.0 | 511877.6 | 46374 | 1.64041666667 | 11406 |
| 011486 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:27pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1594064.3 | 511874.8 | 46376 | 1.64041666667 | 11486 |
| 012131 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:28pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594065.8 | 511871.0 | 46378 | 1.64041666667 | 12131 |
| 012306 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:29pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594066.8 | 511867.9 | 46380 | 1.64041666667 | 12306 |
| 012194 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:30pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594068.0 | 511864.3 | 46382 | 1.64041666667 | 12194 |
| 012034 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:31pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1594069.5 | 511861.1 | 46384 | 1.64041666667 | 12034 |
| 012694 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:32pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594071.7 | 511857.1 | 46386 | 1.64041666667 | 12694 |
| 012488 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:33pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594073.0 | 511853.7 | 46388 | 1.64041666667 | 12488 |
| 012619 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:34pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594074.0 | 511850.3 | 46390 | 1.64041666667 | 12619 |
| 011073 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:35pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594074.1 | 511847.7 | 46392 | 1.64041666667 | 11073 |
| 010541 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:36pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594072.3 | 511844.7 | 46394 | 1.64041666667 | 10541 |
| 010774 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:37pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594069.5 | 511842.9 | 46396 | 1.64041666667 | 10774 |
| 010808 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:38pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594065.8 | 511844.5 | 46398 | 1.64041666667 | 10808 |
| 011982 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594064.6 | 511847.4 | 46400 | 1.64041666667 | 11982 |
| 011967 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:40pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594062.8 | 511851.4 | 46402 | 1.64041666667 | 11967 |
| 012049 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:41pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594061.0 | 511854.8 | 46404 | 1.64041666667 | 12049 |
| 011967 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:42pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594058.7 | 511859.2 | 46406 | 1.64041666667 | 11967 |
| 011861 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:43pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1594057.5 | 511862.6 | 46408 | 1.64041666667 | 11861 |
| 011449 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:44pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1594056.7 | 511867.4 | 46410 | 1.64041666667 | 11449 |
| 012148 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:45pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1594056.4 | 511871.2 | 46412 | 1.64041666667 | 12148 |
| 011670 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:46pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594055.6 | 511875.6 | 46414 | 1.64041666667 | 11670 |
| 011454 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:47pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1594054.0 | 511879.2 | 46416 | 1.64041666667 | 11454 |
| 011190 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:48pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594051.2 | 511883.0 | 46418 | 1.64041666667 | 11190 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011522 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:49pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594048.7 | 511885.1 | 46420 | 1.64041666667 | 11522 |
| 012008 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:50pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594046.7 | 511888.5 | 46422 | 1.64041666667 | 12008 |
| 012117 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:51pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594045.8 | 511891.7 | 46424 | 1.64041666667 | 12117 |
| 012636 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:52pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594044.7 | 511895.6 | 46426 | 1.64041666667 | 12636 |
| 012282 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:53pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594043.6 | 511899.1 | 46428 | 1.64041666667 | 12282 |
| 012631 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:54pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594042.0 | 511903.3 | 46430 | 1.64041666667 | 12631 |
| 013352 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:55pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594040.9 | 511906.7 | 46432 | 1.64041666667 | 13352 |
| 012746 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:56pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594039.5 | 511911.5 | 46434 | 1.64041666667 | 12746 |
| 012412 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:57pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594038.1 | 511915.0 | 46436 | 1.64041666667 | 12412 |
| 012232 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:58pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594036.2 | 511919.0 | 46438 | 1.64041666667 | 12232 |
| 011455 | 0 | GeoXH 6000 | 08/19/2015 | 02:02:59pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594034.9 | 511922.1 | 46440 | 1.64041666667 | 11455 |
| 011506 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:00pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594033.9 | 511926.0 | 46442 | 1.64041666667 | 11506 |
| 011572 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:01pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594032.8 | 511929.5 | 46444 | 1.64041666667 | 11572 |
| 012787 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:02pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594031.1 | 511933.2 | 46446 | 1.64041666667 | 12787 |
| 013320 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:03pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594029.5 | 511936.5 | 46448 | 1.64041666667 | 13320 |
| 012922 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:04pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594028.1 | 511940.2 | 46450 | 1.64041666667 | 12922 |
| 012782 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:05pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594026.4 | 511943.2 | 46452 | 1.64041666667 | 12782 |
| 011810 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:06pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594023.9 | 511944.7 | 46454 | 1.64041666667 | 11810 |
| 012778 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:07pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594022.5 | 511944.5 | 46456 | 1.64041666667 | 12778 |
| 012528 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:08pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594021.2 | 511943.9 | 46458 | 1.64041666667 | 12528 |
| 012574 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:09pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594018.9 | 511943.3 | 46460 | 1.64041666667 | 12574 |
| 012060 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:10pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594017.2 | 511943.2 | 46462 | 1.64041666667 | 12060 |
| 011794 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:11pm | Sensor | 1797-S0036-G-636-DTE | 6820.2 | 1594017.2 | 511940.9 | 46464 | 1.64041666667 | 11794 |
| 011629 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:12pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594018.8 | 511937.9 | 46466 | 1.64041666667 | 11629 |
| 011783 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:13pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594020.5 | 511934.8 | 46468 | 1.64041666667 | 11783 |
| 012456 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:14pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594022.3 | 511930.9 | 46470 | 1.64041666667 | 12456 |
| 011619 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:15pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594023.7 | 511927.9 | 46472 | 1.64041666667 | 11619 |
| 011395 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:16pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594025.5 | 511924.4 | 46474 | 1.64041666667 | 11395 |
| 011067 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:17pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594026.7 | 511921.5 | 46476 | 1.64041666667 | 11067 |
| 011348 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:18pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594027.8 | 511917.8 | 46478 | 1.64041666667 | 11348 |
| 011453 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:19pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594028.8 | 511914.7 | 46480 | 1.64041666667 | 11453 |
| 011325 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:20pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594030.2 | 511911.2 | 46482 | 1.64041666667 | 11325 |
| 012677 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:21pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594031.6 | 511908.3 | 46484 | 1.64041666667 | 12677 |
| 012163 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:22pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594033.1 | 511904.9 | 46486 | 1.64041666667 | 12163 |
| 011529 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:23pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594034.5 | 511902.1 | 46488 | 1.64041666667 | 11529 |
| 012155 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:24pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594036.4 | 511898.8 | 46490 | 1.64041666667 | 12155 |
| 011749 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:25pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594038.0 | 511896.0 | 46492 | 1.64041666667 | 11749 |
| 013614 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:26pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594040.0 | 511892.6 | 46494 | 1.64041666667 | 13614 |
| 013380 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:27pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594041.3 | 511889.8 | 46496 | 1.64041666667 | 13380 |
| 013541 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:28pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594042.6 | 511886.2 | 46498 | 1.64041666667 | 13541 |
| 013729 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:29pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594044.2 | 511882.9 | 46500 | 1.64041666667 | 13729 |
| 012605 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:30pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594046.0 | 511879.3 | 46502 | 1.64041666667 | 12605 |
| 012123 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:31pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594047.2 | 511876.3 | 46504 | 1.64041666667 | 12123 |
| 011529 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:32pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594048.8 | 511872.6 | 46506 | 1.64041666667 | 11529 |
| 011407 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:33pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1594050.7 | 511869.6 | 46508 | 1.64041666667 | 11407 |
| 011421 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:34pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1594053.3 | 511865.5 | 46510 | 1.64041666667 | 11421 |
| 011419 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:35pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1594054.9 | 511862.8 | 46512 | 1.64041666667 | 11419 |
| 011643 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:36pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594056.9 | 511859.0 | 46514 | 1.64041666667 | 11643 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012144 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:37pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594058.5 | 511855.9 | 46516 | 1.64041666667 | 12144 |
| 011848 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:38pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594060.4 | 511852.1 | 46518 | 1.64041666667 | 11848 |
| 012132 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594061.9 | 511849.1 | 46520 | 1.64041666667 | 12132 |
| 011429 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:40pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594063.1 | 511845.1 | 46522 | 1.64041666667 | 11429 |
| 011169 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:41pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594063.7 | 511842.3 | 46524 | 1.64041666667 | 11169 |
| 012440 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:42pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594064.8 | 511839.4 | 46526 | 1.64041666667 | 12440 |
| 012502 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:43pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594064.8 | 511836.5 | 46528 | 1.64041666667 | 12502 |
| 012432 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:44pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594062.3 | 511833.4 | 46530 | 1.64041666667 | 12432 |
| 011726 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:45pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594060.6 | 511833.6 | 46532 | 1.64041666667 | 11726 |
| 011133 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:46pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594058.3 | 511835.4 | 46534 | 1.64041666667 | 11133 |
| 011220 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:47pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594056.5 | 511837.8 | 46536 | 1.64041666667 | 11220 |
| 011373 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:48pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594054.4 | 511841.6 | 46538 | 1.64041666667 | 11373 |
| 010800 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:49pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594053.4 | 511844.8 | 46540 | 1.64041666667 | 10800 |
| 010815 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:50pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594051.9 | 511848.7 | 46542 | 1.64041666667 | 10815 |
| 011356 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594050.6 | 511852.0 | 46544 | 1.64041666667 | 11356 |
| 011802 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:52pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594048.6 | 511856.3 | 46546 | 1.64041666667 | 11802 |
| 011821 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:53pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1594047.2 | 511859.6 | 46548 | 1.64041666667 | 11821 |
| 012634 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:54pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1594045.8 | 511863.4 | 46550 | 1.64041666667 | 12634 |
| 011997 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:55pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1594044.5 | 511866.6 | 46552 | 1.64041666667 | 11997 |
| 012965 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:56pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594042.7 | 511870.3 | 46554 | 1.64041666667 | 12965 |
| 012326 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:57pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594041.2 | 511872.9 | 46556 | 1.64041666667 | 12326 |
| 012603 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:58pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594039.6 | 511876.3 | 46558 | 1.64041666667 | 12603 |
| 012647 | 0 | GeoXH 6000 | 08/19/2015 | 02:03:59pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594038.3 | 511879.7 | 46560 | 1.64041666667 | 12647 |
| 012618 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:00pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594036.9 | 511883.5 | 46562 | 1.64041666667 | 12618 |
| 012693 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:01pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594035.3 | 511886.7 | 46564 | 1.64041666667 | 12693 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:02pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594033.0 | 511889.6 | 46566 | 1.64041666667 | 13297 |
| 012849 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:03pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594031.0 | 511892.3 | 46568 | 1.64041666667 | 12849 |
| 012238 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:04pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594029.1 | 511896.0 | 46570 | 1.64041666667 | 12238 |
| 012298 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:05pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594027.7 | 511899.0 | 46572 | 1.64041666667 | 12298 |
| 013345 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:06pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594025.4 | 511902.5 | 46574 | 1.64041666667 | 13345 |
| 013529 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:07pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594023.5 | 511905.4 | 46576 | 1.64041666667 | 13529 |
| 013827 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:08pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594021.9 | 511908.8 | 46578 | 1.64041666667 | 13827 |
| 013785 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:09pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594020.5 | 511912.0 | 46580 | 1.64041666667 | 13785 |
| 012929 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:10pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594018.7 | 511915.5 | 46582 | 1.64041666667 | 12929 |
| 012717 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:11pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594017.1 | 511918.2 | 46584 | 1.64041666667 | 12717 |
| 012846 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:12pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594015.4 | 511921.8 | 46586 | 1.64041666667 | 12846 |
| 012476 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:13pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594014.4 | 511924.9 | 46588 | 1.64041666667 | 12476 |
| 012545 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:14pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594013.4 | 511928.4 | 46590 | 1.64041666667 | 12545 |
| 011871 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:15pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594012.2 | 511931.2 | 46592 | 1.64041666667 | 11871 |
| 011673 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:16pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594010.6 | 511934.1 | 46594 | 1.64041666667 | 11673 |
| 011876 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:17pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594009.3 | 511936.2 | 46596 | 1.64041666667 | 11876 |
| 011592 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:18pm | Sensor | 1797-S0036-G-636-DTE | 6820.1 | 1594007.3 | 511938.4 | 46598 | 1.64041666667 | 11592 |
| 011711 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:19pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594005.3 | 511938.5 | 46600 | 1.64041666667 | 11711 |
| 012040 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:20pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594002.0 | 511938.2 | 46602 | 1.64041666667 | 12040 |
| 011475 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:21pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1593999.3 | 511937.9 | 46604 | 1.64041666667 | 11475 |
| 011772 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:22pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593997.2 | 511937.0 | 46606 | 1.64041666667 | 11772 |
| 012022 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:23pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1593996.8 | 511936.6 | 46608 | 1.64041666667 | 12022 |
| 011449 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:24pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593998.0 | 511934.8 | 46610 | 1.64041666667 | 11449 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010867 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:25pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1593999.2 | 511932.1 | 46612 | 1.64041666667 | 10867 |
| 011638 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:26pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594000.5 | 511928.5 | 46614 | 1.64041666667 | 11638 |
| 011736 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:27pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594001.5 | 511925.2 | 46616 | 1.64041666667 | 11736 |
| 012144 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:28pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594003.0 | 511921.2 | 46618 | 1.64041666667 | 12144 |
| 012508 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:29pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594004.7 | 511918.4 | 46620 | 1.64041666667 | 12508 |
| 012886 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:30pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594007.1 | 511914.7 | 46622 | 1.64041666667 | 12886 |
| 012363 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:31pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594008.7 | 511911.6 | 46624 | 1.64041666667 | 12363 |
| 011949 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:32pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594010.9 | 511907.6 | 46626 | 1.64041666667 | 11949 |
| 011769 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:33pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594012.5 | 511904.6 | 46628 | 1.64041666667 | 11769 |
| 012057 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:34pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594014.1 | 511900.8 | 46630 | 1.64041666667 | 12057 |
| 012430 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:35pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594015.2 | 511897.6 | 46632 | 1.64041666667 | 12430 |
| 012189 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:36pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594016.4 | 511893.5 | 46634 | 1.64041666667 | 12189 |
| 012189 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:37pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594017.7 | 511889.8 | 46636 | 1.64041666667 | 12189 |
| 013006 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:38pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594019.6 | 511885.4 | 46638 | 1.64041666667 | 13006 |
| 013361 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:39pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594021.1 | 511882.3 | 46640 | 1.64041666667 | 13361 |
| 013883 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:40pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594023.1 | 511878.5 | 46642 | 1.64041666667 | 13883 |
| 014004 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:41pm | Sensor | 1797-S0036-G-636-DTE | 6820.0 | 1594024.9 | 511875.2 | 46644 | 1.64041666667 | 14004 |
| 013299 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:42pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594027.1 | 511871.8 | 46646 | 1.64041666667 | 13299 |
| 012858 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:43pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594029.3 | 511868.8 | 46648 | 1.64041666667 | 12858 |
| 012925 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:44pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1594032.2 | 511865.4 | 46650 | 1.64041666667 | 12925 |
| 011778 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:45pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1594033.8 | 511862.0 | 46652 | 1.64041666667 | 11778 |
| 011935 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:46pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594035.5 | 511857.4 | 46654 | 1.64041666667 | 11935 |
| 011648 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:47pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594036.6 | 511853.6 | 46656 | 1.64041666667 | 11648 |
| 011757 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:48pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594038.3 | 511849.3 | 46658 | 1.64041666667 | 11757 |
| 011736 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:49pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594039.7 | 511845.9 | 46660 | 1.64041666667 | 11736 |
| 012091 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:50pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594041.7 | 511841.6 | 46662 | 1.64041666667 | 12091 |
| 011886 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594042.9 | 511838.4 | 46664 | 1.64041666667 | 11886 |
| 011703 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:52pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594044.3 | 511834.3 | 46666 | 1.64041666667 | 11703 |
| 011548 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:53pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594045.1 | 511831.5 | 46668 | 1.64041666667 | 11548 |
| 010838 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:54pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1594045.5 | 511828.0 | 46670 | 1.64041666667 | 10838 |
| 010956 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:55pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594043.9 | 511825.4 | 46672 | 1.64041666667 | 10956 |
| 010963 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:56pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594040.9 | 511823.5 | 46674 | 1.64041666667 | 10963 |
| 010734 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:57pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594038.7 | 511822.8 | 46676 | 1.64041666667 | 10734 |
| 010987 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:58pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594037.6 | 511822.8 | 46678 | 1.64041666667 | 10987 |
| 011498 | 0 | GeoXH 6000 | 08/19/2015 | 02:04:59pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594037.7 | 511823.1 | 46680 | 1.64041666667 | 11498 |
| 011462 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:00pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594036.6 | 511825.4 | 46682 | 1.64041666667 | 11462 |
| 012957 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:01pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594035.6 | 511828.3 | 46684 | 1.64041666667 | 12957 |
| 013183 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:02pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594034.3 | 511832.0 | 46686 | 1.64041666667 | 13183 |
| 012846 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:03pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594033.2 | 511835.0 | 46688 | 1.64041666667 | 12846 |
| 012528 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:04pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594032.1 | 511838.6 | 46690 | 1.64041666667 | 12528 |
| 012522 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:05pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594031.0 | 511841.5 | 46692 | 1.64041666667 | 12522 |
| 012451 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:06pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594029.6 | 511845.8 | 46694 | 1.64041666667 | 12451 |
| 013506 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:07pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594028.8 | 511849.1 | 46696 | 1.64041666667 | 13506 |
| 012997 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:08pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1594027.9 | 511853.0 | 46698 | 1.64041666667 | 12997 |
| 012868 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:09pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1594027.0 | 511856.6 | 46700 | 1.64041666667 | 12868 |
| 013096 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:10pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1594026.5 | 511861.0 | 46702 | 1.64041666667 | 13096 |
| 012654 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:11pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1594025.8 | 511864.7 | 46704 | 1.64041666667 | 12654 |
| 012877 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:12pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594025.1 | 511868.6 | 46706 | 1.64041666667 | 12877 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013153 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:13pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594024.1 | 511871.3 | 46708 | 1.64041666667 | 13153 |
| 012266 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:14pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594022.2 | 511874.6 | 46710 | 1.64041666667 | 12266 |
| 012337 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:15pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594020.3 | 511877.5 | 46712 | 1.64041666667 | 12337 |
| 011822 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:16pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594017.7 | 511881.1 | 46714 | 1.64041666667 | 11822 |
| 011825 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:17pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594015.5 | 511884.1 | 46716 | 1.64041666667 | 11825 |
| 012749 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:18pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594012.7 | 511888.0 | 46718 | 1.64041666667 | 12749 |
| 012683 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:19pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594010.5 | 511891.0 | 46720 | 1.64041666667 | 12683 |
| 011859 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:20pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1594008.0 | 511894.9 | 46722 | 1.64041666667 | 11859 |
| 012776 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:21pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594006.2 | 511898.2 | 46724 | 1.64041666667 | 12776 |
| 012939 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:22pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594004.4 | 511902.5 | 46726 | 1.64041666667 | 12939 |
| 012734 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:23pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1594002.6 | 511905.7 | 46728 | 1.64041666667 | 12734 |
| 012986 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:24pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594000.0 | 511909.8 | 46730 | 1.64041666667 | 12986 |
| 012900 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:25pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593998.6 | 511913.0 | 46732 | 1.64041666667 | 12900 |
| 012881 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:26pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593997.0 | 511917.0 | 46734 | 1.64041666667 | 12881 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:27pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1593995.5 | 511920.3 | 46736 | 1.64041666667 | 12255 |
| 012256 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:28pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593993.5 | 511924.0 | 46738 | 1.64041666667 | 12256 |
| 012504 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:29pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593991.4 | 511927.3 | 46740 | 1.64041666667 | 12504 |
| 012291 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:30pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593989.3 | 511930.9 | 46742 | 1.64041666667 | 12291 |
| 013243 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:31pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593988.3 | 511933.9 | 46744 | 1.64041666667 | 13243 |
| 013127 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:32pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593987.7 | 511936.5 | 46746 | 1.64041666667 | 13127 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:33pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593986.3 | 511937.5 | 46748 | 1.64041666667 | 13811 |
| 013799 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:34pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593983.8 | 511937.3 | 46750 | 1.64041666667 | 13799 |
| 012884 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:35pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593981.9 | 511936.4 | 46752 | 1.64041666667 | 12884 |
| 014192 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:36pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593980.5 | 511935.3 | 46754 | 1.64041666667 | 14192 |
| 013766 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:37pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593980.0 | 511934.9 | 46756 | 1.64041666667 | 13766 |
| 014126 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:38pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593980.0 | 511934.8 | 46758 | 1.64041666667 | 14126 |
| 013953 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:39pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1593980.1 | 511934.4 | 46760 | 1.64041666667 | 13953 |
| 013301 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:40pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1593980.7 | 511932.4 | 46762 | 1.64041666667 | 13301 |
| 012949 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:41pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593981.4 | 511929.3 | 46764 | 1.64041666667 | 12949 |
| 013381 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:42pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593982.1 | 511925.4 | 46766 | 1.64041666667 | 13381 |
| 013167 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:43pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593983.3 | 511921.8 | 46768 | 1.64041666667 | 13167 |
| 013579 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:44pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1593985.1 | 511917.9 | 46770 | 1.64041666667 | 13579 |
| 013255 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:45pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593986.9 | 511914.7 | 46772 | 1.64041666667 | 13255 |
| 013313 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:46pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593988.5 | 511911.1 | 46774 | 1.64041666667 | 13313 |
| 014111 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:47pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593989.8 | 511908.0 | 46776 | 1.64041666667 | 14111 |
| 014267 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:48pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593991.5 | 511904.6 | 46778 | 1.64041666667 | 14267 |
| 014423 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:49pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593993.4 | 511901.7 | 46780 | 1.64041666667 | 14423 |
| 014383 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:50pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593995.4 | 511898.1 | 46782 | 1.64041666667 | 14383 |
| 013220 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:51pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1593996.5 | 511895.0 | 46784 | 1.64041666667 | 13220 |
| 013263 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:52pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593997.4 | 511891.2 | 46786 | 1.64041666667 | 13263 |
| 012726 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:53pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593997.9 | 511888.4 | 46788 | 1.64041666667 | 12726 |
| 012281 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:54pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593998.0 | 511885.0 | 46790 | 1.64041666667 | 12281 |
| 012053 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:55pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593998.7 | 511882.2 | 46792 | 1.64041666667 | 12053 |
| 011640 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:56pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593999.8 | 511879.0 | 46794 | 1.64041666667 | 11640 |
| 011917 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:57pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594001.1 | 511876.4 | 46796 | 1.64041666667 | 11917 |
| 012703 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:58pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594002.5 | 511875.2 | 46798 | 1.64041666667 | 12703 |
| 012380 | 0 | GeoXH 6000 | 08/19/2015 | 02:05:59pm | Sensor | 1797-S0036-G-636-DTE | 6819.8 | 1594002.8 | 511874.7 | 46800 | 1.64041666667 | 12380 |
| 011981 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:00pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1594003.4 | 511874.7 | 46802 | 1.64041666667 | 11981 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012904 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:01pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594004.7 | 511876.1 | 46804 | 1.64041666667 | 12904 |
| 012426 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:02pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594005.2 | 511876.6 | 46806 | 1.64041666667 | 12426 |
| 012765 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:03pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594005.2 | 511876.5 | 46808 | 1.64041666667 | 12765 |
| 012565 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:04pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594005.2 | 511876.2 | 46810 | 1.64041666667 | 12565 |
| 012078 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:05pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594005.3 | 511876.2 | 46812 | 1.64041666667 | 12078 |
| 012283 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:06pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594005.2 | 511876.4 | 46814 | 1.64041666667 | 12283 |
| 012452 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:07pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594005.2 | 511876.5 | 46816 | 1.64041666667 | 12452 |
| 012659 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:08pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594005.2 | 511876.3 | 46818 | 1.64041666667 | 12659 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:09pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1594005.4 | 511875.2 | 46820 | 1.64041666667 | 12056 |
| 011784 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:10pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1594005.5 | 511874.3 | 46822 | 1.64041666667 | 11784 |
| 012568 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:11pm | Sensor | 1797-S0036-G-636-DTE | 6817.9 | 1594005.9 | 511874.3 | 46824 | 1.64041666667 | 12568 |
| 012259 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:12pm | Sensor | 1797-S0036-G-636-DTE | 6817.5 | 1594006.1 | 511874.2 | 46826 | 1.64041666667 | 12259 |
| 012596 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:13pm | Sensor | 1797-S0036-G-636-DTE | 6817.8 | 1594005.0 | 511875.4 | 46828 | 1.64041666667 | 12596 |
| 012147 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:14pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1594004.4 | 511876.2 | 46830 | 1.64041666667 | 12147 |
| 012120 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:15pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1594006.4 | 511875.0 | 46832 | 1.64041666667 | 12120 |
| 012420 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:16pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1594008.1 | 511872.6 | 46834 | 1.64041666667 | 12420 |
| 012431 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:17pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594009.7 | 511869.8 | 46836 | 1.64041666667 | 12431 |
| 012025 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:18pm | Sensor | 1797-S0036-G-636-DTE | 6819.9 | 1594011.6 | 511866.6 | 46838 | 1.64041666667 | 12025 |
| 012779 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:19pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594013.5 | 511864.0 | 46840 | 1.64041666667 | 12779 |
| 012813 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:20pm | Sensor | 1797-S0036-G-636-DTE | 6819.7 | 1594015.9 | 511861.1 | 46842 | 1.64041666667 | 12813 |
| 012360 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:21pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1594018.0 | 511858.6 | 46844 | 1.64041666667 | 12360 |
| 012540 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:22pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1594020.7 | 511855.5 | 46846 | 1.64041666667 | 12540 |
| 012453 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:23pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1594023.1 | 511852.7 | 46848 | 1.64041666667 | 12453 |
| 012840 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:24pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594025.3 | 511849.4 | 46850 | 1.64041666667 | 12840 |
| 012435 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:25pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594026.5 | 511846.3 | 46852 | 1.64041666667 | 12435 |
| 012139 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:26pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594027.6 | 511842.1 | 46854 | 1.64041666667 | 12139 |
| 011681 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:27pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1594027.9 | 511839.4 | 46856 | 1.64041666667 | 11681 |
| 011910 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:28pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594028.9 | 511835.5 | 46858 | 1.64041666667 | 11910 |
| 012362 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:29pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594030.1 | 511832.1 | 46860 | 1.64041666667 | 12362 |
| 012151 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:30pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594031.6 | 511828.0 | 46862 | 1.64041666667 | 12151 |
| 011605 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:31pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1594032.7 | 511825.3 | 46864 | 1.64041666667 | 11605 |
| 011748 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:32pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1594031.7 | 511822.0 | 46866 | 1.64041666667 | 11748 |
| 011880 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:33pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594029.8 | 511820.4 | 46868 | 1.64041666667 | 11880 |
| 011842 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:34pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1594026.2 | 511819.5 | 46870 | 1.64041666667 | 11842 |
| 010801 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:35pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594023.2 | 511821.3 | 46872 | 1.64041666667 | 10801 |
| 011715 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:36pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1594020.8 | 511824.7 | 46874 | 1.64041666667 | 11715 |
| 012447 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:37pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594019.0 | 511828.3 | 46876 | 1.64041666667 | 12447 |
| 012559 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:38pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594017.2 | 511832.0 | 46878 | 1.64041666667 | 12559 |
| 011909 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594015.5 | 511835.5 | 46880 | 1.64041666667 | 11909 |
| 012144 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:40pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1594013.7 | 511839.4 | 46882 | 1.64041666667 | 12144 |
| 011886 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:41pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1594011.9 | 511842.9 | 46884 | 1.64041666667 | 11886 |
| 011786 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:42pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1594009.6 | 511847.2 | 46886 | 1.64041666667 | 11786 |
| 012037 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:43pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1594007.9 | 511850.6 | 46888 | 1.64041666667 | 12037 |
| 012358 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:44pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1594006.3 | 511854.2 | 46890 | 1.64041666667 | 12358 |
| 012404 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:45pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1594004.4 | 511857.4 | 46892 | 1.64041666667 | 12404 |
| 012167 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:46pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1594001.8 | 511861.1 | 46894 | 1.64041666667 | 12167 |
| 011726 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:47pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593999.7 | 511864.2 | 46896 | 1.64041666667 | 11726 |
| 011546 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:48pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593997.8 | 511867.9 | 46898 | 1.64041666667 | 11546 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012119 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:49pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593996.1 | 511871.0 | 46900 | 1.64041666667 | 12119 |
| 011482 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:50pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593993.9 | 511874.5 | 46902 | 1.64041666667 | 11482 |
| 011311 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:51pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593991.9 | 511877.6 | 46904 | 1.64041666667 | 11311 |
| 011530 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:52pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593989.9 | 511881.3 | 46906 | 1.64041666667 | 11530 |
| 012170 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:53pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593988.6 | 511884.5 | 46908 | 1.64041666667 | 12170 |
| 012261 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:54pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593987.3 | 511888.0 | 46910 | 1.64041666667 | 12261 |
| 013376 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:55pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593986.0 | 511891.1 | 46912 | 1.64041666667 | 13376 |
| 013809 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:56pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593984.1 | 511894.8 | 46914 | 1.64041666667 | 13809 |
| 014255 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:57pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593982.6 | 511898.0 | 46916 | 1.64041666667 | 14255 |
| 013366 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:58pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593981.1 | 511901.8 | 46918 | 1.64041666667 | 13366 |
| 012783 | 0 | GeoXH 6000 | 08/19/2015 | 02:06:59pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593979.6 | 511904.8 | 46920 | 1.64041666667 | 12783 |
| 014060 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:00pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593977.4 | 511908.1 | 46922 | 1.64041666667 | 14060 |
| 012746 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:01pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593976.0 | 511910.9 | 46924 | 1.64041666667 | 12746 |
| 013087 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:02pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593974.6 | 511914.9 | 46926 | 1.64041666667 | 13087 |
| 013804 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:03pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1593973.6 | 511918.2 | 46928 | 1.64041666667 | 13804 |
| 013607 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:04pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593972.6 | 511921.2 | 46930 | 1.64041666667 | 13607 |
| 013661 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:05pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593971.4 | 511923.5 | 46932 | 1.64041666667 | 13661 |
| 013894 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:06pm | Sensor | 1797-S0036-G-636-DTE | 6819.6 | 1593970.2 | 511926.0 | 46934 | 1.64041666667 | 13894 |
| 014978 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:07pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593968.7 | 511927.5 | 46936 | 1.64041666667 | 14978 |
| 014755 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:08pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593966.6 | 511927.8 | 46938 | 1.64041666667 | 14755 |
| 014104 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:09pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593964.2 | 511927.0 | 46940 | 1.64041666667 | 14104 |
| 013671 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:10pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1593961.7 | 511925.5 | 46942 | 1.64041666667 | 13671 |
| 013600 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:11pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1593960.6 | 511924.0 | 46944 | 1.64041666667 | 13600 |
| 014115 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:12pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593959.9 | 511921.5 | 46946 | 1.64041666667 | 14115 |
| 013609 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:13pm | Sensor | 1797-S0036-G-636-DTE | 6819.5 | 1593960.0 | 511918.5 | 46948 | 1.64041666667 | 13609 |
| 013340 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:14pm | Sensor | 1797-S0036-G-636-DTE | 6819.4 | 1593961.1 | 511914.1 | 46950 | 1.64041666667 | 13340 |
| 013676 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:15pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593962.4 | 511910.8 | 46952 | 1.64041666667 | 13676 |
| 014030 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:16pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593964.4 | 511907.1 | 46954 | 1.64041666667 | 14030 |
| 014372 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:17pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593966.1 | 511903.8 | 46956 | 1.64041666667 | 14372 |
| 013942 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:18pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593968.1 | 511899.9 | 46958 | 1.64041666667 | 13942 |
| 014359 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:19pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593969.9 | 511896.8 | 46960 | 1.64041666667 | 14359 |
| 013072 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:20pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593972.4 | 511892.8 | 46962 | 1.64041666667 | 13072 |
| 013480 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:21pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593974.5 | 511889.4 | 46964 | 1.64041666667 | 13480 |
| 013747 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:22pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593976.4 | 511885.8 | 46966 | 1.64041666667 | 13747 |
| 013208 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:23pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593977.6 | 511882.4 | 46968 | 1.64041666667 | 13208 |
| 011742 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:24pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593978.9 | 511877.9 | 46970 | 1.64041666667 | 11742 |
| 012672 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:25pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593979.9 | 511874.4 | 46972 | 1.64041666667 | 12672 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:26pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593981.4 | 511870.3 | 46974 | 1.64041666667 | 12378 |
| 012602 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:27pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593982.8 | 511867.3 | 46976 | 1.64041666667 | 12602 |
| 012114 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:28pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593984.7 | 511863.4 | 46978 | 1.64041666667 | 12114 |
| 011396 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:29pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593986.2 | 511860.3 | 46980 | 1.64041666667 | 11396 |
| 011240 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:30pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593987.9 | 511856.2 | 46982 | 1.64041666667 | 11240 |
| 012195 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:31pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593989.4 | 511852.7 | 46984 | 1.64041666667 | 12195 |
| 011944 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:32pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593991.3 | 511849.0 | 46986 | 1.64041666667 | 11944 |
| 011384 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:33pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593993.0 | 511846.2 | 46988 | 1.64041666667 | 11384 |
| 011871 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:34pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593995.3 | 511842.3 | 46990 | 1.64041666667 | 11871 |
| 013157 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:35pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593997.0 | 511839.4 | 46992 | 1.64041666667 | 13157 |
| 013431 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:36pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593999.4 | 511835.4 | 46994 | 1.64041666667 | 13431 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012632 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:37pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1594001.2 | 511832.6 | 46996 | 1.64041666667 | 12632 |
| 012513 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:38pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1594003.3 | 511828.8 | 46998 | 1.64041666667 | 12513 |
| 012873 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1594004.7 | 511825.8 | 47000 | 1.64041666667 | 12873 |
| 012371 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:40pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1594005.9 | 511822.7 | 47002 | 1.64041666667 | 12371 |
| 012426 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:41pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1594007.2 | 511819.9 | 47004 | 1.64041666667 | 12426 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:42pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1594008.2 | 511816.6 | 47006 | 1.64041666667 | 12442 |
| 012878 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:43pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1594008.9 | 511813.8 | 47008 | 1.64041666667 | 12878 |
| 011902 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:44pm | Sensor | 1797-S0036-G-636-DTE | 6818.0 | 1594008.3 | 511810.4 | 47010 | 1.64041666667 | 11902 |
| 012462 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:45pm | Sensor | 1797-S0036-G-636-DTE | 6817.9 | 1594005.8 | 511808.4 | 47012 | 1.64041666667 | 12462 |
| 012185 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:46pm | Sensor | 1797-S0036-G-636-DTE | 6818.0 | 1594002.7 | 511807.4 | 47014 | 1.64041666667 | 12185 |
| 012426 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:47pm | Sensor | 1797-S0036-G-636-DTE | 6817.9 | 1594000.2 | 511807.3 | 47016 | 1.64041666667 | 12426 |
| 013425 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:48pm | Sensor | 1797-S0036-G-636-DTE | 6817.9 | 1593997.3 | 511809.4 | 47018 | 1.64041666667 | 13425 |
| 012936 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:49pm | Sensor | 1797-S0036-G-636-DTE | 6817.9 | 1593995.7 | 511812.2 | 47020 | 1.64041666667 | 12936 |
| 012736 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:50pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593994.0 | 511816.4 | 47022 | 1.64041666667 | 12736 |
| 011904 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593992.5 | 511819.5 | 47024 | 1.64041666667 | 11904 |
| 011653 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:52pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593990.1 | 511823.5 | 47026 | 1.64041666667 | 11653 |
| 011955 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:53pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593988.6 | 511826.8 | 47028 | 1.64041666667 | 11955 |
| 012004 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:54pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593987.0 | 511830.6 | 47030 | 1.64041666667 | 12004 |
| 012152 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:55pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593985.4 | 511834.0 | 47032 | 1.64041666667 | 12152 |
| 012641 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:56pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593983.6 | 511837.9 | 47034 | 1.64041666667 | 12641 |
| 012570 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:57pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593981.6 | 511841.5 | 47036 | 1.64041666667 | 12570 |
| 012735 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:58pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593979.4 | 511844.9 | 47038 | 1.64041666667 | 12735 |
| 012893 | 0 | GeoXH 6000 | 08/19/2015 | 02:07:59pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593977.6 | 511848.4 | 47040 | 1.64041666667 | 12893 |
| 013027 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:00pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593975.7 | 511852.6 | 47042 | 1.64041666667 | 13027 |
| 012698 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:01pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593974.3 | 511856.2 | 47044 | 1.64041666667 | 12698 |
| 013472 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:02pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593972.6 | 511860.5 | 47046 | 1.64041666667 | 13472 |
| 012018 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:03pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593971.1 | 511863.8 | 47048 | 1.64041666667 | 12018 |
| 012288 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:04pm | Sensor | 1797-S0036-G-636-DTE | 6818.7 | 1593969.1 | 511868.0 | 47050 | 1.64041666667 | 12288 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:05pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593967.2 | 511870.9 | 47052 | 1.64041666667 | 12454 |
| 012518 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:06pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593964.8 | 511874.6 | 47054 | 1.64041666667 | 12518 |
| 012291 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:07pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593963.0 | 511878.1 | 47056 | 1.64041666667 | 12291 |
| 012989 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:08pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593961.0 | 511882.1 | 47058 | 1.64041666667 | 12989 |
| 013591 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:09pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593959.4 | 511885.2 | 47060 | 1.64041666667 | 13591 |
| 013712 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:10pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593957.0 | 511889.3 | 47062 | 1.64041666667 | 13712 |
| 013286 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:11pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593955.3 | 511892.1 | 47064 | 1.64041666667 | 13286 |
| 013241 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:12pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593953.5 | 511895.8 | 47066 | 1.64041666667 | 13241 |
| 013688 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:13pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593952.3 | 511898.9 | 47068 | 1.64041666667 | 13688 |
| 013849 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:14pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593950.9 | 511902.4 | 47070 | 1.64041666667 | 13849 |
| 014082 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:15pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593949.4 | 511904.4 | 47072 | 1.64041666667 | 14082 |
| 014626 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:16pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593947.4 | 511907.3 | 47074 | 1.64041666667 | 14626 |
| 014400 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:17pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593946.0 | 511909.4 | 47076 | 1.64041666667 | 14400 |
| 015082 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:18pm | Sensor | 1797-S0036-G-636-DTE | 6819.3 | 1593943.4 | 511909.9 | 47078 | 1.64041666667 | 15082 |
| 014978 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:19pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593941.1 | 511908.8 | 47080 | 1.64041666667 | 14978 |
| 014545 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:20pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593939.5 | 511907.2 | 47082 | 1.64041666667 | 14545 |
| 014317 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:21pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593938.8 | 511906.0 | 47084 | 1.64041666667 | 14317 |
| 013505 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:22pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593938.8 | 511905.3 | 47086 | 1.64041666667 | 13505 |
| 013597 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:23pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593938.9 | 511905.2 | 47088 | 1.64041666667 | 13597 |
| 014000 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:24pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593938.9 | 511905.3 | 47090 | 1.64041666667 | 14000 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014078 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:25pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593938.9 | 511905.3 | 47092 | 1.64041666667 | 14078 |
| 014744 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:26pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593939.1 | 511904.5 | 47094 | 1.64041666667 | 14744 |
| 014023 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:27pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593940.1 | 511902.7 | 47096 | 1.64041666667 | 14023 |
| 014405 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:28pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593941.7 | 511899.1 | 47098 | 1.64041666667 | 14405 |
| 013758 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:29pm | Sensor | 1797-S0036-G-636-DTE | 6819.1 | 1593943.1 | 511895.8 | 47100 | 1.64041666667 | 13758 |
| 013911 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:30pm | Sensor | 1797-S0036-G-636-DTE | 6819.2 | 1593944.9 | 511891.7 | 47102 | 1.64041666667 | 13911 |
| 013720 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:31pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593946.9 | 511888.3 | 47104 | 1.64041666667 | 13720 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:32pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593949.2 | 511884.6 | 47106 | 1.64041666667 | 14602 |
| 014491 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:33pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593951.2 | 511880.8 | 47108 | 1.64041666667 | 14491 |
| 013514 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:34pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593953.3 | 511876.5 | 47110 | 1.64041666667 | 13514 |
| 013526 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:35pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593954.8 | 511873.1 | 47112 | 1.64041666667 | 13526 |
| 012986 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:36pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593956.5 | 511868.7 | 47114 | 1.64041666667 | 12986 |
| 012727 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:37pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593958.0 | 511864.9 | 47116 | 1.64041666667 | 12727 |
| 013534 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:38pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593959.9 | 511860.8 | 47118 | 1.64041666667 | 13534 |
| 013402 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:39pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593961.4 | 511857.4 | 47120 | 1.64041666667 | 13402 |
| 012579 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:40pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593963.0 | 511853.2 | 47122 | 1.64041666667 | 12579 |
| 012243 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:41pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593964.5 | 511850.0 | 47124 | 1.64041666667 | 12243 |
| 012286 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:42pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593966.6 | 511846.2 | 47126 | 1.64041666667 | 12286 |
| 012648 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:43pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593968.5 | 511843.1 | 47128 | 1.64041666667 | 12648 |
| 012695 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:44pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593970.6 | 511839.2 | 47130 | 1.64041666667 | 12695 |
| 012225 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:45pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593972.0 | 511836.1 | 47132 | 1.64041666667 | 12225 |
| 012157 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:46pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593973.4 | 511831.9 | 47134 | 1.64041666667 | 12157 |
| 012418 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:47pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593974.7 | 511828.6 | 47136 | 1.64041666667 | 12418 |
| 013233 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:48pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593976.4 | 511825.0 | 47138 | 1.64041666667 | 13233 |
| 013104 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:49pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593977.8 | 511821.6 | 47140 | 1.64041666667 | 13104 |
| 012610 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:50pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593978.9 | 511818.0 | 47142 | 1.64041666667 | 12610 |
| 013963 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:51pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593979.8 | 511814.6 | 47144 | 1.64041666667 | 13963 |
| 012767 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:52pm | Sensor | 1797-S0036-G-636-DTE | 6817.9 | 1593981.2 | 511810.6 | 47146 | 1.64041666667 | 12767 |
| 012513 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:53pm | Sensor | 1797-S0036-G-636-DTE | 6817.8 | 1593982.1 | 511807.4 | 47148 | 1.64041666667 | 12513 |
| 012671 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:54pm | Sensor | 1797-S0036-G-636-DTE | 6818.0 | 1593983.3 | 511804.0 | 47150 | 1.64041666667 | 12671 |
| 012407 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:55pm | Sensor | 1797-S0036-G-636-DTE | 6818.0 | 1593983.8 | 511801.7 | 47152 | 1.64041666667 | 12407 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:56pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593982.7 | 511800.5 | 47154 | 1.64041666667 | 12536 |
| 012039 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:57pm | Sensor | 1797-S0036-G-636-DTE | 6818.0 | 1593980.7 | 511801.0 | 47156 | 1.64041666667 | 12039 |
| 011332 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:58pm | Sensor | 1797-S0036-G-636-DTE | 6817.9 | 1593978.3 | 511803.6 | 47158 | 1.64041666667 | 11332 |
| 011842 | 0 | GeoXH 6000 | 08/19/2015 | 02:08:59pm | Sensor | 1797-S0036-G-636-DTE | 6817.9 | 1593976.4 | 511806.4 | 47160 | 1.64041666667 | 11842 |
| 011918 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:00pm | Sensor | 1797-S0036-G-636-DTE | 6818.0 | 1593974.3 | 511810.1 | 47162 | 1.64041666667 | 11918 |
| 011886 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:01pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593972.5 | 511813.8 | 47164 | 1.64041666667 | 11886 |
| 011891 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:02pm | Sensor | 1797-S0036-G-636-DTE | 6818.0 | 1593970.3 | 511818.1 | 47166 | 1.64041666667 | 11891 |
| 012216 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:03pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593968.6 | 511821.2 | 47168 | 1.64041666667 | 12216 |
| 012624 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:04pm | Sensor | 1797-S0036-G-636-DTE | 6818.2 | 1593966.3 | 511825.6 | 47170 | 1.64041666667 | 12624 |
| 011406 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:05pm | Sensor | 1797-S0036-G-636-DTE | 6818.1 | 1593964.4 | 511829.4 | 47172 | 1.64041666667 | 11406 |
| 011336 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:06pm | Sensor | 1797-S0036-G-636-DTE | 6818.0 | 1593962.5 | 511833.6 | 47174 | 1.64041666667 | 11336 |
| 012024 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:07pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593961.3 | 511837.0 | 47176 | 1.64041666667 | 12024 |
| 012036 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:08pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593959.7 | 511841.1 | 47178 | 1.64041666667 | 12036 |
| 012372 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:09pm | Sensor | 1797-S0036-G-636-DTE | 6818.3 | 1593958.5 | 511844.2 | 47180 | 1.64041666667 | 12372 |
| 012269 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:10pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593956.5 | 511848.1 | 47182 | 1.64041666667 | 12269 |
| 012001 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:11pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593954.6 | 511851.6 | 47184 | 1.64041666667 | 12001 |
| 012525 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:12pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593952.2 | 511855.7 | 47186 | 1.64041666667 | 12525 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013668 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:13pm | Sensor | 1797-S0036-G-636-DTE | 6818.5 | 1593950.4 | 511859.0 | 47188 | 1.64041666667 | 13668 |
| 014206 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:14pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593948.3 | 511862.8 | 47190 | 1.64041666667 | 14206 |
| 013473 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:15pm | Sensor | 1797-S0036-G-636-DTE | 6818.4 | 1593946.3 | 511866.3 | 47192 | 1.64041666667 | 13473 |
| 013751 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:16pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593944.4 | 511870.4 | 47194 | 1.64041666667 | 13751 |
| 013163 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:17pm | Sensor | 1797-S0036-G-636-DTE | 6818.6 | 1593943.0 | 511873.7 | 47196 | 1.64041666667 | 13163 |
| 012586 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:18pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593941.3 | 511877.7 | 47198 | 1.64041666667 | 12586 |
| 013267 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:19pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593940.3 | 511881.0 | 47200 | 1.64041666667 | 13267 |
| 013042 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:20pm | Sensor | 1797-S0036-G-636-DTE | 6818.8 | 1593938.9 | 511885.2 | 47202 | 1.64041666667 | 13042 |
| 013074 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:21pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593937.7 | 511888.1 | 47204 | 1.64041666667 | 13074 |
| 013046 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:22pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593936.3 | 511891.5 | 47206 | 1.64041666667 | 13046 |
| 013593 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:23pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593935.0 | 511894.1 | 47208 | 1.64041666667 | 13593 |
| 013706 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:24pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593933.0 | 511896.9 | 47210 | 1.64041666667 | 13706 |
| 013965 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:25pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593931.6 | 511898.3 | 47212 | 1.64041666667 | 13965 |
| 013982 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:26pm | Sensor | 1797-S0036-G-636-DTE | 6818.9 | 1593931.0 | 511899.2 | 47214 | 1.64041666667 | 13982 |
| 013640 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:27pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593931.0 | 511899.5 | 47216 | 1.64041666667 | 13640 |
| 013770 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:28pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593931.0 | 511899.6 | 47218 | 1.64041666667 | 13770 |
| 013858 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:29pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593931.0 | 511899.6 | 47220 | 1.64041666667 | 13858 |
| 014163 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:30pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593931.0 | 511899.6 | 47222 | 1.64041666667 | 14163 |
| 013816 | 0 | GeoXH 6000 | 08/19/2015 | 02:09:31pm | Sensor | 1797-S0036-G-636-DTE | 6819.0 | 1593931.0 | 511899.5 | 47224 | 1.64041666667 | 13816 |
| 015151 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:30pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1593798.3 | 511191.2 | 44469 | 1.64041666667 | 15151 |
| 014950 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:31pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1593798.3 | 511191.2 | 44470 | 1.64041666667 | 14950 |
| 014634 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:32pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1593798.3 | 511191.2 | 44473 | 1.64041666667 | 14634 |
| 014839 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:33pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1593798.3 | 511191.2 | 44475 | 1.64041666667 | 14839 |
| 014302 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:34pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1593798.3 | 511191.2 | 44477 | 1.64041666667 | 14302 |
| 012521 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:04pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594557.0 | 510469.7 | 44482 | 1.64041666667 | 12521 |
| 012075 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:05pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594557.0 | 510469.7 | 44484 | 1.64041666667 | 12075 |
| 011817 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:06pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594557.0 | 510469.7 | 44486 | 1.64041666667 | 11817 |
| 012205 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:07pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594557.0 | 510469.7 | 44488 | 1.64041666667 | 12205 |
| 011800 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:08pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594557.1 | 510469.6 | 44490 | 1.64041666667 | 11800 |
| 011625 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:09pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594557.2 | 510469.5 | 44492 | 1.64041666667 | 11625 |
| 011706 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:10pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594557.6 | 510469.4 | 44494 | 1.64041666667 | 11706 |
| 011962 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:11pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594558.1 | 510468.4 | 44496 | 1.64041666667 | 11962 |
| 012361 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:12pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594559.2 | 510465.7 | 44498 | 1.64041666667 | 12361 |
| 011820 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:13pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594560.9 | 510463.2 | 44500 | 1.64041666667 | 11820 |
| 011449 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:14pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594563.0 | 510459.2 | 44502 | 1.64041666667 | 11449 |
| 011915 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:15pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594564.4 | 510455.7 | 44504 | 1.64041666667 | 11915 |
| 011779 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:16pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594566.3 | 510451.5 | 44506 | 1.64041666667 | 11779 |
| 012018 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:17pm | Sensor | 1797-S0035-636-G-DTE | 6814.7 | 1594568.2 | 510448.0 | 44508 | 1.64041666667 | 12018 |
| 013360 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:18pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594570.7 | 510444.0 | 44510 | 1.64041666667 | 13360 |
| 013237 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:19pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594572.4 | 510440.6 | 44512 | 1.64041666667 | 13237 |
| 012741 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:20pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594574.4 | 510436.4 | 44514 | 1.64041666667 | 12741 |
| 011907 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:21pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594576.8 | 510432.7 | 44516 | 1.64041666667 | 11907 |
| 011377 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:22pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594579.4 | 510428.9 | 44518 | 1.64041666667 | 11377 |
| 012535 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:23pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594581.1 | 510425.6 | 44520 | 1.64041666667 | 12535 |
| 012571 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:24pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594582.6 | 510421.2 | 44522 | 1.64041666667 | 12571 |
| 011443 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:25pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594583.7 | 510417.8 | 44524 | 1.64041666667 | 11443 |
| 010637 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:26pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594585.3 | 510413.9 | 44526 | 1.64041666667 | 10637 |
| 010746 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:27pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594587.1 | 510410.1 | 44528 | 1.64041666667 | 10746 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010994 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:28pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594588.9 | 510406.5 | 44530 | 1.64041666667 | 10994 |
| 011194 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:29pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594590.7 | 510403.0 | 44532 | 1.64041666667 | 11194 |
| 011666 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:30pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594592.7 | 510399.2 | 44534 | 1.64041666667 | 11666 |
| 011767 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:31pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594594.0 | 510396.1 | 44536 | 1.64041666667 | 11767 |
| 012146 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:32pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594595.4 | 510392.1 | 44538 | 1.64041666667 | 12146 |
| 012345 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:33pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594597.0 | 510388.6 | 44540 | 1.64041666667 | 12345 |
| 012426 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:34pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594598.8 | 510385.2 | 44542 | 1.64041666667 | 12426 |
| 012682 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:35pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594599.8 | 510382.0 | 44544 | 1.64041666667 | 12682 |
| 012691 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:36pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594601.2 | 510378.9 | 44546 | 1.64041666667 | 12691 |
| 012471 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:37pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594602.4 | 510375.9 | 44548 | 1.64041666667 | 12471 |
| 012685 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:38pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594602.7 | 510372.6 | 44550 | 1.64041666667 | 12685 |
| 012663 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:39pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594603.2 | 510370.5 | 44552 | 1.64041666667 | 12663 |
| 012463 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:40pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594603.5 | 510367.6 | 44554 | 1.64041666667 | 12463 |
| 011682 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:41pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594602.1 | 510365.5 | 44556 | 1.64041666667 | 11682 |
| 012189 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:42pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594598.9 | 510363.5 | 44558 | 1.64041666667 | 12189 |
| 011641 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:43pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594596.5 | 510361.8 | 44560 | 1.64041666667 | 11641 |
| 011715 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:44pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594593.4 | 510360.3 | 44562 | 1.64041666667 | 11715 |
| 011945 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:45pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594590.7 | 510359.2 | 44564 | 1.64041666667 | 11945 |
| 012591 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:46pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594587.0 | 510357.3 | 44566 | 1.64041666667 | 12591 |
| 011860 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:47pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594583.8 | 510355.9 | 44568 | 1.64041666667 | 11860 |
| 011748 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:48pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594579.9 | 510354.8 | 44570 | 1.64041666667 | 11748 |
| 012038 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:49pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594576.8 | 510353.8 | 44572 | 1.64041666667 | 12038 |
| 011099 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:50pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594573.1 | 510351.6 | 44574 | 1.64041666667 | 11099 |
| 011066 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:51pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594570.2 | 510349.9 | 44576 | 1.64041666667 | 11066 |
| 011189 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:52pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594566.5 | 510347.9 | 44578 | 1.64041666667 | 11189 |
| 011011 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:53pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594563.6 | 510346.1 | 44580 | 1.64041666667 | 11011 |
| 011181 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:54pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594560.1 | 510343.8 | 44582 | 1.64041666667 | 11181 |
| 011524 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:55pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594557.5 | 510342.5 | 44584 | 1.64041666667 | 11524 |
| 011245 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:56pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594553.9 | 510341.1 | 44586 | 1.64041666667 | 11245 |
| 011395 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:57pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594550.9 | 510339.4 | 44588 | 1.64041666667 | 11395 |
| 011374 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:58pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594547.0 | 510337.5 | 44590 | 1.64041666667 | 11374 |
| 011813 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:59pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594543.5 | 510336.2 | 44592 | 1.64041666667 | 11813 |
| 012105 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:00pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594539.9 | 510334.7 | 44594 | 1.64041666667 | 12105 |
| 011984 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:01pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594537.0 | 510333.1 | 44596 | 1.64041666667 | 11984 |
| 012403 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:02pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594533.2 | 510331.5 | 44598 | 1.64041666667 | 12403 |
| 012039 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:03pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594529.7 | 510330.2 | 44600 | 1.64041666667 | 12039 |
| 012292 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:04pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594526.1 | 510328.6 | 44602 | 1.64041666667 | 12292 |
| 012059 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:05pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594522.8 | 510327.0 | 44604 | 1.64041666667 | 12059 |
| 011726 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:06pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594519.0 | 510325.6 | 44606 | 1.64041666667 | 11726 |
| 011786 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:07pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594516.1 | 510324.5 | 44608 | 1.64041666667 | 11786 |
| 011017 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:08pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594512.4 | 510322.7 | 44610 | 1.64041666667 | 11017 |
| 010847 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:09pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594509.7 | 510321.7 | 44612 | 1.64041666667 | 10847 |
| 011584 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:10pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594506.9 | 510321.0 | 44614 | 1.64041666667 | 11584 |
| 011886 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:11pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594504.4 | 510320.1 | 44616 | 1.64041666667 | 11886 |
| 012168 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:12pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594501.8 | 510320.0 | 44618 | 1.64041666667 | 12168 |
| 011764 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:13pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594501.1 | 510320.9 | 44620 | 1.64041666667 | 11764 |
| 012197 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:14pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594500.3 | 510321.9 | 44622 | 1.64041666667 | 12197 |
| 011496 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:15pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594499.2 | 510324.4 | 44624 | 1.64041666667 | 11496 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011079 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:16pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594497.2 | 510327.9 | 44626 | 1.64041666667 | 11079 |
| 011459 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:17pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594495.5 | 510330.8 | 44628 | 1.64041666667 | 11459 |
| 011276 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:18pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594493.8 | 510334.8 | 44630 | 1.64041666667 | 11276 |
| 010325 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:19pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594492.2 | 510338.1 | 44632 | 1.64041666667 | 10325 |
| 010443 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:20pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594490.0 | 510341.3 | 44634 | 1.64041666667 | 10443 |
| 011236 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:21pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594488.3 | 510343.8 | 44636 | 1.64041666667 | 11236 |
| 011533 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:22pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594487.1 | 510347.5 | 44638 | 1.64041666667 | 11533 |
| 011805 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:23pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594486.1 | 510350.8 | 44640 | 1.64041666667 | 11805 |
| 012940 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:24pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594484.3 | 510354.7 | 44642 | 1.64041666667 | 12940 |
| 012446 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:25pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594483.2 | 510358.0 | 44644 | 1.64041666667 | 12446 |
| 012228 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:26pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594482.2 | 510361.8 | 44646 | 1.64041666667 | 12228 |
| 011753 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:27pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594481.1 | 510364.2 | 44648 | 1.64041666667 | 11753 |
| 010893 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:28pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594479.1 | 510367.6 | 44650 | 1.64041666667 | 10893 |
| 011640 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:29pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594477.6 | 510370.7 | 44652 | 1.64041666667 | 11640 |
| 011467 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:30pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594475.5 | 510374.6 | 44654 | 1.64041666667 | 11467 |
| 010980 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:31pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594473.8 | 510377.6 | 44656 | 1.64041666667 | 10980 |
| 011921 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:32pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594471.9 | 510380.9 | 44658 | 1.64041666667 | 11921 |
| 012113 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:33pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594470.9 | 510384.0 | 44660 | 1.64041666667 | 12113 |
| 011861 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:34pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594469.6 | 510387.8 | 44662 | 1.64041666667 | 11861 |
| 011779 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:35pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594468.0 | 510390.4 | 44664 | 1.64041666667 | 11779 |
| 011351 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:36pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594466.6 | 510393.3 | 44666 | 1.64041666667 | 11351 |
| 011207 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:37pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594465.4 | 510396.4 | 44668 | 1.64041666667 | 11207 |
| 011531 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:38pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594463.8 | 510399.7 | 44670 | 1.64041666667 | 11531 |
| 011504 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:39pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594462.9 | 510402.7 | 44672 | 1.64041666667 | 11504 |
| 012981 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:40pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594462.0 | 510405.6 | 44674 | 1.64041666667 | 12981 |
| 012364 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:41pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594460.5 | 510408.4 | 44676 | 1.64041666667 | 12364 |
| 012287 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:42pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594459.2 | 510411.7 | 44678 | 1.64041666667 | 12287 |
| 011741 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:43pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594458.4 | 510414.4 | 44680 | 1.64041666667 | 11741 |
| 012139 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:44pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594457.4 | 510417.5 | 44682 | 1.64041666667 | 12139 |
| 011816 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:45pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594458.1 | 510419.7 | 44684 | 1.64041666667 | 11816 |
| 011529 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:46pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594460.6 | 510421.7 | 44686 | 1.64041666667 | 11529 |
| 012222 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:47pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594463.5 | 510423.5 | 44688 | 1.64041666667 | 12222 |
| 012117 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:48pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594467.3 | 510425.2 | 44690 | 1.64041666667 | 12117 |
| 012846 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:49pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594470.4 | 510426.6 | 44692 | 1.64041666667 | 12846 |
| 012918 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:50pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594473.5 | 510428.5 | 44694 | 1.64041666667 | 12918 |
| 012194 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:51pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594475.9 | 510429.8 | 44696 | 1.64041666667 | 12194 |
| 013166 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:52pm | Sensor | 1797-S0035-636-G-DTE | 6814.7 | 1594479.3 | 510431.2 | 44698 | 1.64041666667 | 13166 |
| 013428 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:53pm | Sensor | 1797-S0035-636-G-DTE | 6814.7 | 1594482.1 | 510432.6 | 44700 | 1.64041666667 | 13428 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:54pm | Sensor | 1797-S0035-636-G-DTE | 6814.9 | 1594486.0 | 510434.2 | 44702 | 1.64041666667 | 13471 |
| 012685 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:55pm | Sensor | 1797-S0035-636-G-DTE | 6815.0 | 1594489.3 | 510435.6 | 44704 | 1.64041666667 | 12685 |
| 013120 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:56pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594493.1 | 510438.0 | 44706 | 1.64041666667 | 13120 |
| 013807 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:57pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594496.2 | 510439.5 | 44708 | 1.64041666667 | 13807 |
| 013391 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:58pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594499.6 | 510441.0 | 44710 | 1.64041666667 | 13391 |
| 013233 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:59pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594502.7 | 510442.8 | 44712 | 1.64041666667 | 13233 |
| 013713 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:00pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594505.9 | 510444.6 | 44714 | 1.64041666667 | 13713 |
| 014561 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:01pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594509.0 | 510445.9 | 44716 | 1.64041666667 | 14561 |
| 014565 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:02pm | Sensor | 1797-S0035-636-G-DTE | 6816.0 | 1594512.3 | 510447.9 | 44718 | 1.64041666667 | 14565 |
| 015025 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:03pm | Sensor | 1797-S0035-636-G-DTE | 6816.1 | 1594514.8 | 510449.5 | 44720 | 1.64041666667 | 15025 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014797 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:04pm | Sensor | 1797-S0035-636-G-DTE | 6816.0 | 1594518.3 | 510451.0 | 44722 | 1.64041666667 | 14797 |
| 015883 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:05pm | Sensor | 1797-S0035-636-G-DTE | 6816.1 | 1594521.1 | 510452.5 | 44724 | 1.64041666667 | 15883 |
| 015272 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:06pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594524.4 | 510454.2 | 44726 | 1.64041666667 | 15272 |
| 016270 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:07pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594527.5 | 510455.0 | 44728 | 1.64041666667 | 16270 |
| 014552 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:08pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594531.3 | 510456.4 | 44730 | 1.64041666667 | 14552 |
| 013210 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:09pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594534.2 | 510458.1 | 44732 | 1.64041666667 | 13210 |
| 012358 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:10pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594537.8 | 510459.8 | 44734 | 1.64041666667 | 12358 |
| 011564 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:11pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594540.8 | 510460.9 | 44736 | 1.64041666667 | 11564 |
| 012017 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:12pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594544.3 | 510462.7 | 44738 | 1.64041666667 | 12017 |
| 011199 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:13pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594546.8 | 510464.0 | 44740 | 1.64041666667 | 11199 |
| 011145 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:14pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594550.3 | 510465.3 | 44742 | 1.64041666667 | 11145 |
| 011331 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:15pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594552.6 | 510466.8 | 44744 | 1.64041666667 | 11331 |
| 011646 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:16pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594555.0 | 510467.9 | 44746 | 1.64041666667 | 11646 |
| 011711 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:17pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594556.8 | 510467.9 | 44748 | 1.64041666667 | 11711 |
| 011770 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:18pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594558.0 | 510468.3 | 44750 | 1.64041666667 | 11770 |
| 012058 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:19pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594558.0 | 510468.3 | 44752 | 1.64041666667 | 12058 |
| 011552 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:20pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594558.1 | 510468.2 | 44754 | 1.64041666667 | 11552 |
| 012266 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:21pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594558.0 | 510468.0 | 44756 | 1.64041666667 | 12266 |
| 012374 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:22pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594557.3 | 510467.6 | 44758 | 1.64041666667 | 12374 |
| 012803 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:23pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594555.6 | 510467.3 | 44760 | 1.64041666667 | 12803 |
| 012796 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:24pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594553.2 | 510466.3 | 44762 | 1.64041666667 | 12796 |
| 012995 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:25pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594552.0 | 510466.5 | 44764 | 1.64041666667 | 12995 |
| 013070 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:26pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594551.7 | 510466.7 | 44766 | 1.64041666667 | 13070 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:27pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594552.1 | 510465.9 | 44768 | 1.64041666667 | 13442 |
| 013456 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:28pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594553.3 | 510463.8 | 44770 | 1.64041666667 | 13456 |
| 013134 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:29pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594554.8 | 510461.1 | 44772 | 1.64041666667 | 13134 |
| 013170 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:30pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594556.7 | 510457.8 | 44774 | 1.64041666667 | 13170 |
| 012830 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:31pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594558.0 | 510454.8 | 44776 | 1.64041666667 | 12830 |
| 012857 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:32pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594559.7 | 510451.0 | 44778 | 1.64041666667 | 12857 |
| 012962 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:33pm | Sensor | 1797-S0035-636-G-DTE | 6814.9 | 1594561.8 | 510447.4 | 44780 | 1.64041666667 | 12962 |
| 012316 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:34pm | Sensor | 1797-S0035-636-G-DTE | 6814.7 | 1594563.7 | 510443.7 | 44782 | 1.64041666667 | 12316 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:35pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594564.9 | 510440.4 | 44784 | 1.64041666667 | 12785 |
| 013199 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:36pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594566.6 | 510436.7 | 44786 | 1.64041666667 | 13199 |
| 014069 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:37pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594568.5 | 510433.3 | 44788 | 1.64041666667 | 14069 |
| 013599 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:38pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594569.9 | 510429.6 | 44790 | 1.64041666667 | 13599 |
| 012869 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:39pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594571.0 | 510426.7 | 44792 | 1.64041666667 | 12869 |
| 012789 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:40pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594572.8 | 510423.3 | 44794 | 1.64041666667 | 12789 |
| 012338 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:41pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594574.3 | 510420.3 | 44796 | 1.64041666667 | 12338 |
| 012760 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:42pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594575.9 | 510416.2 | 44798 | 1.64041666667 | 12760 |
| 012217 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:43pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594577.5 | 510413.1 | 44800 | 1.64041666667 | 12217 |
| 011725 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:44pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594579.6 | 510409.2 | 44802 | 1.64041666667 | 11725 |
| 011395 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:45pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594581.0 | 510405.6 | 44804 | 1.64041666667 | 11395 |
| 011779 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:46pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594582.4 | 510401.9 | 44806 | 1.64041666667 | 11779 |
| 011028 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:47pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594584.4 | 510398.4 | 44808 | 1.64041666667 | 11028 |
| 011806 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:48pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594586.0 | 510395.1 | 44810 | 1.64041666667 | 11806 |
| 012011 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:49pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594587.0 | 510391.7 | 44812 | 1.64041666667 | 12011 |
| 011811 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:50pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594588.9 | 510388.3 | 44814 | 1.64041666667 | 11811 |
| 011413 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:51pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594590.8 | 510385.4 | 44816 | 1.64041666667 | 11413 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011565 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:52pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594592.4 | 510381.8 | 44818 | 1.64041666667 | 11565 |
| 011163 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:53pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594594.1 | 510379.0 | 44820 | 1.64041666667 | 11163 |
| 012511 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:54pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594595.8 | 510375.7 | 44822 | 1.64041666667 | 12511 |
| 012595 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:55pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594596.8 | 510372.2 | 44824 | 1.64041666667 | 12595 |
| 012822 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:56pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594598.1 | 510368.8 | 44826 | 1.64041666667 | 12822 |
| 012972 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:57pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594599.2 | 510366.6 | 44828 | 1.64041666667 | 12972 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:58pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594599.3 | 510365.1 | 44830 | 1.64041666667 | 13132 |
| 012742 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:59pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594598.3 | 510363.9 | 44832 | 1.64041666667 | 12742 |
| 012919 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:00pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594596.3 | 510362.6 | 44834 | 1.64041666667 | 12919 |
| 012465 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:01pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594594.5 | 510361.9 | 44836 | 1.64041666667 | 12465 |
| 012381 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:02pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594593.6 | 510361.6 | 44838 | 1.64041666667 | 12381 |
| 011524 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:03pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594593.1 | 510362.5 | 44840 | 1.64041666667 | 11524 |
| 012010 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:04pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594591.3 | 510365.0 | 44842 | 1.64041666667 | 12010 |
| 013153 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:05pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594589.7 | 510368.1 | 44844 | 1.64041666667 | 13153 |
| 012723 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:06pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594588.2 | 510371.6 | 44846 | 1.64041666667 | 12723 |
| 012992 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:07pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594586.7 | 510374.5 | 44848 | 1.64041666667 | 12992 |
| 013259 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:08pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594584.5 | 510378.1 | 44850 | 1.64041666667 | 13259 |
| 013360 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:09pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594583.2 | 510381.2 | 44852 | 1.64041666667 | 13360 |
| 012975 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:10pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594581.1 | 510385.0 | 44854 | 1.64041666667 | 12975 |
| 012503 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:11pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594579.4 | 510388.6 | 44856 | 1.64041666667 | 12503 |
| 012680 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:12pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594578.1 | 510392.3 | 44858 | 1.64041666667 | 12680 |
| 012008 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:13pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594576.7 | 510395.2 | 44860 | 1.64041666667 | 12008 |
| 011757 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:14pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594574.4 | 510398.9 | 44862 | 1.64041666667 | 11757 |
| 011668 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:15pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594572.9 | 510402.5 | 44864 | 1.64041666667 | 11668 |
| 012496 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:16pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594571.7 | 510406.5 | 44866 | 1.64041666667 | 12496 |
| 012444 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:17pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594570.5 | 510409.7 | 44868 | 1.64041666667 | 12444 |
| 012647 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:18pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594568.7 | 510412.9 | 44870 | 1.64041666667 | 12647 |
| 012619 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:19pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594567.4 | 510416.1 | 44872 | 1.64041666667 | 12619 |
| 012393 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:20pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594566.0 | 510419.3 | 44874 | 1.64041666667 | 12393 |
| 011823 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:21pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594564.2 | 510422.8 | 44876 | 1.64041666667 | 11823 |
| 011570 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:22pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594562.7 | 510426.3 | 44878 | 1.64041666667 | 11570 |
| 011421 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:23pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594561.6 | 510430.2 | 44880 | 1.64041666667 | 11421 |
| 012259 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:24pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594560.0 | 510433.9 | 44882 | 1.64041666667 | 12259 |
| 012348 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:25pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594558.4 | 510436.7 | 44884 | 1.64041666667 | 12348 |
| 013201 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:26pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594556.9 | 510440.5 | 44886 | 1.64041666667 | 13201 |
| 013358 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:27pm | Sensor | 1797-S0035-636-G-DTE | 6814.7 | 1594555.5 | 510443.8 | 44888 | 1.64041666667 | 13358 |
| 014166 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:28pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594553.8 | 510447.3 | 44890 | 1.64041666667 | 14166 |
| 013421 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:29pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594552.5 | 510450.8 | 44892 | 1.64041666667 | 13421 |
| 013639 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:30pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594551.0 | 510454.4 | 44894 | 1.64041666667 | 13639 |
| 013169 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:31pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594549.4 | 510457.2 | 44896 | 1.64041666667 | 13169 |
| 012545 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:32pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594548.0 | 510460.5 | 44898 | 1.64041666667 | 12545 |
| 012321 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:33pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594546.9 | 510463.4 | 44900 | 1.64041666667 | 12321 |
| 011843 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:34pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594546.4 | 510465.4 | 44902 | 1.64041666667 | 11843 |
| 011184 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:35pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594546.0 | 510466.5 | 44904 | 1.64041666667 | 11184 |
| 011181 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:36pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594545.5 | 510467.1 | 44906 | 1.64041666667 | 11181 |
| 011344 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:37pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594543.9 | 510466.0 | 44908 | 1.64041666667 | 11344 |
| 011721 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:38pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594541.8 | 510464.9 | 44910 | 1.64041666667 | 11721 |
| 012068 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:39pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594540.6 | 510464.8 | 44912 | 1.64041666667 | 12068 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012255 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:40pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594540.9 | 510464.2 | 44914 | 1.64041666667 | 12255 |
| 012459 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:41pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594541.5 | 510462.4 | 44916 | 1.64041666667 | 12459 |
| 012550 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:42pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594543.0 | 510459.1 | 44918 | 1.64041666667 | 12550 |
| 012722 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:43pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594544.7 | 510456.1 | 44920 | 1.64041666667 | 12722 |
| 013118 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:44pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594546.0 | 510452.7 | 44922 | 1.64041666667 | 13118 |
| 012959 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:45pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594547.1 | 510449.6 | 44924 | 1.64041666667 | 12959 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:46pm | Sensor | 1797-S0035-636-G-DTE | 6814.9 | 1594548.9 | 510445.7 | 44926 | 1.64041666667 | 13094 |
| 012510 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:47pm | Sensor | 1797-S0035-636-G-DTE | 6814.7 | 1594550.8 | 510442.5 | 44928 | 1.64041666667 | 12510 |
| 012354 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:48pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594552.3 | 510438.9 | 44930 | 1.64041666667 | 12354 |
| 012304 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:49pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594553.7 | 510435.7 | 44932 | 1.64041666667 | 12304 |
| 011728 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:50pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594555.8 | 510432.0 | 44934 | 1.64041666667 | 11728 |
| 012200 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:51pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594557.5 | 510428.5 | 44936 | 1.64041666667 | 12200 |
| 012112 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:52pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594558.8 | 510424.5 | 44938 | 1.64041666667 | 12112 |
| 011395 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:53pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594560.2 | 510421.4 | 44940 | 1.64041666667 | 11395 |
| 011825 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:54pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594562.0 | 510418.8 | 44942 | 1.64041666667 | 11825 |
| 011504 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:55pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594563.3 | 510416.1 | 44944 | 1.64041666667 | 11504 |
| 012028 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:56pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594564.7 | 510412.6 | 44946 | 1.64041666667 | 12028 |
| 011663 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:57pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594566.4 | 510409.1 | 44948 | 1.64041666667 | 11663 |
| 011585 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:58pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594568.0 | 510405.5 | 44950 | 1.64041666667 | 11585 |
| 011002 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:59pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594569.2 | 510401.9 | 44952 | 1.64041666667 | 11002 |
| 011933 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:00pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594571.0 | 510398.5 | 44954 | 1.64041666667 | 11933 |
| 012577 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:01pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594572.7 | 510395.2 | 44956 | 1.64041666667 | 12577 |
| 011687 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:02pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594574.3 | 510391.3 | 44958 | 1.64041666667 | 11687 |
| 011681 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:03pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594575.7 | 510388.3 | 44960 | 1.64041666667 | 11681 |
| 012383 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:04pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594577.6 | 510384.4 | 44962 | 1.64041666667 | 12383 |
| 012118 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:05pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594578.5 | 510381.2 | 44964 | 1.64041666667 | 12118 |
| 012141 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:06pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594579.7 | 510377.4 | 44966 | 1.64041666667 | 12141 |
| 012019 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:07pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594581.4 | 510374.3 | 44968 | 1.64041666667 | 12019 |
| 011831 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:08pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594582.7 | 510370.6 | 44970 | 1.64041666667 | 11831 |
| 012047 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:09pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594583.7 | 510367.5 | 44972 | 1.64041666667 | 12047 |
| 011704 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:10pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594585.6 | 510363.5 | 44974 | 1.64041666667 | 11704 |
| 011188 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:11pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594586.8 | 510360.9 | 44976 | 1.64041666667 | 11188 |
| 011881 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:12pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594587.3 | 510357.9 | 44978 | 1.64041666667 | 11881 |
| 012938 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:13pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594587.0 | 510356.4 | 44980 | 1.64041666667 | 12938 |
| 013180 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:14pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594584.6 | 510355.0 | 44982 | 1.64041666667 | 13180 |
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:15pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594581.9 | 510354.2 | 44984 | 1.64041666667 | 12761 |
| 012683 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:16pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594579.6 | 510354.7 | 44986 | 1.64041666667 | 12683 |
| 012249 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:17pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594578.0 | 510357.0 | 44988 | 1.64041666667 | 12249 |
| 011727 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:18pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594576.1 | 510360.3 | 44990 | 1.64041666667 | 11727 |
| 012364 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:19pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594574.2 | 510363.2 | 44992 | 1.64041666667 | 12364 |
| 011417 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:20pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594572.4 | 510366.7 | 44994 | 1.64041666667 | 11417 |
| 011087 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:21pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594571.2 | 510369.5 | 44996 | 1.64041666667 | 11087 |
| 011546 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:22pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594569.3 | 510373.2 | 44998 | 1.64041666667 | 11546 |
| 010942 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:23pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594568.0 | 510376.4 | 45000 | 1.64041666667 | 10942 |
| 011292 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:24pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594566.5 | 510380.2 | 45002 | 1.64041666667 | 11292 |
| 011707 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:25pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594565.3 | 510382.9 | 45004 | 1.64041666667 | 11707 |
| 011790 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:26pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594564.6 | 510386.3 | 45006 | 1.64041666667 | 11790 |
| 011417 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:27pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594564.1 | 510389.8 | 45008 | 1.64041666667 | 11417 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010824 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:28pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594562.6 | 510393.6 | 45010 | 1.64041666667 | 10824 |
| 011339 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:29pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594561.4 | 510396.5 | 45012 | 1.64041666667 | 11339 |
| 010323 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:30pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594560.5 | 510400.2 | 45014 | 1.64041666667 | 10323 |
| 010816 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:31pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594559.2 | 510403.3 | 45016 | 1.64041666667 | 10816 |
| 011694 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:32pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594557.2 | 510406.6 | 45018 | 1.64041666667 | 11694 |
| 011918 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:33pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594555.7 | 510409.6 | 45020 | 1.64041666667 | 11918 |
| 011976 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:34pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594554.2 | 510412.5 | 45022 | 1.64041666667 | 11976 |
| 011656 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:35pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594552.3 | 510415.1 | 45024 | 1.64041666667 | 11656 |
| 010786 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:36pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594550.7 | 510418.6 | 45026 | 1.64041666667 | 10786 |
| 011122 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:37pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594549.9 | 510422.1 | 45028 | 1.64041666667 | 11122 |
| 011086 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:38pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594548.4 | 510425.9 | 45030 | 1.64041666667 | 11086 |
| 011388 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:39pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594546.9 | 510428.9 | 45032 | 1.64041666667 | 11388 |
| 011416 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:40pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594546.0 | 510433.0 | 45034 | 1.64041666667 | 11416 |
| 011716 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:41pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594544.8 | 510435.9 | 45036 | 1.64041666667 | 11716 |
| 012005 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:42pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594542.5 | 510438.8 | 45038 | 1.64041666667 | 12005 |
| 012273 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:43pm | Sensor | 1797-S0035-636-G-DTE | 6814.9 | 1594541.4 | 510441.4 | 45040 | 1.64041666667 | 12273 |
| 011966 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:44pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594540.2 | 510444.6 | 45042 | 1.64041666667 | 11966 |
| 012041 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:45pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594538.6 | 510447.2 | 45044 | 1.64041666667 | 12041 |
| 012165 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:46pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594537.4 | 510450.3 | 45046 | 1.64041666667 | 12165 |
| 011358 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:47pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594536.3 | 510452.8 | 45048 | 1.64041666667 | 11358 |
| 011759 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:48pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594534.8 | 510455.1 | 45050 | 1.64041666667 | 11759 |
| 011812 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:49pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594534.3 | 510456.7 | 45052 | 1.64041666667 | 11812 |
| 012786 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:50pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594533.9 | 510457.4 | 45054 | 1.64041666667 | 12786 |
| 012667 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:51pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594533.7 | 510457.7 | 45056 | 1.64041666667 | 12667 |
| 013140 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:52pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594532.8 | 510457.8 | 45058 | 1.64041666667 | 13140 |
| 012795 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:53pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594531.1 | 510457.3 | 45060 | 1.64041666667 | 12795 |
| 014435 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:54pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594528.8 | 510456.1 | 45062 | 1.64041666667 | 14435 |
| 014892 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:55pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594527.5 | 510456.2 | 45064 | 1.64041666667 | 14892 |
| 015142 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:56pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594526.3 | 510456.0 | 45066 | 1.64041666667 | 15142 |
| 014479 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:57pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594526.5 | 510455.4 | 45068 | 1.64041666667 | 14479 |
| 015450 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:58pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594526.9 | 510453.4 | 45070 | 1.64041666667 | 15450 |
| 016520 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:59pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594527.6 | 510450.8 | 45072 | 1.64041666667 | 16520 |
| 016455 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:00pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594529.1 | 510448.1 | 45074 | 1.64041666667 | 16455 |
| 015496 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:01pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594529.8 | 510446.7 | 45076 | 1.64041666667 | 15496 |
| 015009 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:02pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594529.1 | 510446.0 | 45078 | 1.64041666667 | 15009 |
| 015117 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:03pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594527.2 | 510446.1 | 45080 | 1.64041666667 | 15117 |
| 014571 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:04pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594525.2 | 510447.6 | 45082 | 1.64041666667 | 14571 |
| 016438 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:05pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594525.0 | 510449.4 | 45084 | 1.64041666667 | 16438 |
| 017294 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:06pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594526.1 | 510450.6 | 45086 | 1.64041666667 | 17294 |
| 017663 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:07pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594526.7 | 510449.9 | 45088 | 1.64041666667 | 17663 |
| 016933 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:08pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594527.2 | 510449.4 | 45090 | 1.64041666667 | 16933 |
| 016087 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:09pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594527.3 | 510449.5 | 45092 | 1.64041666667 | 16087 |
| 016256 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:10pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594526.7 | 510449.9 | 45094 | 1.64041666667 | 16256 |
| 016021 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:11pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594525.0 | 510450.4 | 45096 | 1.64041666667 | 16021 |
| 016669 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:12pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594524.2 | 510450.1 | 45098 | 1.64041666667 | 16669 |
| 017926 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:13pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594524.2 | 510449.3 | 45100 | 1.64041666667 | 17926 |
| 018318 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:14pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594523.7 | 510449.1 | 45102 | 1.64041666667 | 18318 |
| 020436 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:15pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594523.6 | 510449.1 | 45104 | 1.64041666667 | 20436 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 020420 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:16pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594523.7 | 510449.1 | 45106 | 1.64041666667 | 20420 |
| 020269 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:17pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594523.6 | 510449.3 | 45108 | 1.64041666667 | 20269 |
| 020468 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:18pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594523.5 | 510449.8 | 45110 | 1.64041666667 | 20468 |
| 020243 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:19pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594523.4 | 510450.1 | 45112 | 1.64041666667 | 20243 |
| 020657 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:20pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594523.3 | 510449.9 | 45114 | 1.64041666667 | 20657 |
| 020642 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:21pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594523.2 | 510449.7 | 45116 | 1.64041666667 | 20642 |
| 021181 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:22pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594522.6 | 510450.0 | 45118 | 1.64041666667 | 21181 |
| 021604 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:23pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594522.0 | 510450.6 | 45120 | 1.64041666667 | 21604 |
| 020522 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:24pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594522.0 | 510450.6 | 45122 | 1.64041666667 | 20522 |
| 021429 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:25pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594522.1 | 510450.4 | 45124 | 1.64041666667 | 21429 |
| 022133 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:26pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594523.0 | 510449.8 | 45126 | 1.64041666667 | 22133 |
| 020977 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:27pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594522.9 | 510449.7 | 45128 | 1.64041666667 | 20977 |
| 020432 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:28pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594522.8 | 510449.6 | 45130 | 1.64041666667 | 20432 |
| 019946 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:29pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594522.9 | 510449.5 | 45132 | 1.64041666667 | 19946 |
| 020414 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:30pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594522.9 | 510449.5 | 45134 | 1.64041666667 | 20414 |
| 020963 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:31pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594523.0 | 510449.5 | 45136 | 1.64041666667 | 20963 |
| 021706 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:32pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594523.0 | 510449.5 | 45138 | 1.64041666667 | 21706 |
| 020730 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:33pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594522.9 | 510449.5 | 45140 | 1.64041666667 | 20730 |
| 020488 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:34pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594522.9 | 510449.5 | 45142 | 1.64041666667 | 20488 |
| 020674 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:35pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594523.0 | 510449.5 | 45144 | 1.64041666667 | 20674 |
| 021589 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:36pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594523.0 | 510449.4 | 45146 | 1.64041666667 | 21589 |
| 020071 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:37pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594523.5 | 510449.5 | 45148 | 1.64041666667 | 20071 |
| 019435 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:38pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594524.8 | 510450.3 | 45150 | 1.64041666667 | 19435 |
| 018867 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:39pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594525.5 | 510450.3 | 45152 | 1.64041666667 | 18867 |
| 017587 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:40pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594526.1 | 510449.9 | 45154 | 1.64041666667 | 17587 |
| 016860 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:41pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594527.4 | 510449.9 | 45156 | 1.64041666667 | 16860 |
| 016241 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:42pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594529.2 | 510447.8 | 45158 | 1.64041666667 | 16241 |
| 014768 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:43pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594530.5 | 510444.8 | 45160 | 1.64041666667 | 14768 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:44pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594532.4 | 510441.2 | 45162 | 1.64041666667 | 14314 |
| 013107 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:45pm | Sensor | 1797-S0035-636-G-DTE | 6815.0 | 1594533.5 | 510438.3 | 45164 | 1.64041666667 | 13107 |
| 012900 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:46pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594534.3 | 510434.6 | 45166 | 1.64041666667 | 12900 |
| 012483 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:47pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594535.6 | 510431.6 | 45168 | 1.64041666667 | 12483 |
| 011882 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:48pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594537.6 | 510427.6 | 45170 | 1.64041666667 | 11882 |
| 011971 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:49pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594538.7 | 510424.2 | 45172 | 1.64041666667 | 11971 |
| 011638 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:50pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594540.0 | 510419.6 | 45174 | 1.64041666667 | 11638 |
| 011789 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:51pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594541.6 | 510416.1 | 45176 | 1.64041666667 | 11789 |
| 011521 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:52pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594543.3 | 510412.5 | 45178 | 1.64041666667 | 11521 |
| 011970 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:53pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594544.1 | 510409.3 | 45180 | 1.64041666667 | 11970 |
| 011638 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:54pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594544.7 | 510405.2 | 45182 | 1.64041666667 | 11638 |
| 011579 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:55pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594545.7 | 510402.1 | 45184 | 1.64041666667 | 11579 |
| 012034 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:56pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594547.9 | 510398.7 | 45186 | 1.64041666667 | 12034 |
| 011614 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:57pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594549.5 | 510395.4 | 45188 | 1.64041666667 | 11614 |
| 011108 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:58pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594551.2 | 510391.6 | 45190 | 1.64041666667 | 11108 |
| 010845 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:59pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594552.9 | 510388.5 | 45192 | 1.64041666667 | 10845 |
| 010510 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:00pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594554.6 | 510384.6 | 45194 | 1.64041666667 | 10510 |
| 010764 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:01pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594555.8 | 510381.6 | 45196 | 1.64041666667 | 10764 |
| 011042 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:02pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594557.9 | 510378.1 | 45198 | 1.64041666667 | 11042 |
| 010389 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:03pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594559.5 | 510375.4 | 45200 | 1.64041666667 | 10389 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011086 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:04pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594560.6 | 510371.4 | 45202 | 1.64041666667 | 11086 |
| 011816 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:05pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594562.0 | 510368.0 | 45204 | 1.64041666667 | 11816 |
| 011941 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:06pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594563.9 | 510364.1 | 45206 | 1.64041666667 | 11941 |
| 012372 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:07pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594565.1 | 510360.9 | 45208 | 1.64041666667 | 12372 |
| 011564 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:08pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594566.3 | 510357.5 | 45210 | 1.64041666667 | 11564 |
| 010937 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:09pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594568.1 | 510355.0 | 45212 | 1.64041666667 | 10937 |
| 010749 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:10pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594569.9 | 510352.2 | 45214 | 1.64041666667 | 10749 |
| 012166 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:11pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594570.9 | 510350.0 | 45216 | 1.64041666667 | 12166 |
| 011561 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:12pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594571.6 | 510347.9 | 45218 | 1.64041666667 | 11561 |
| 011685 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:13pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594570.0 | 510345.9 | 45220 | 1.64041666667 | 11685 |
| 012288 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:14pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594568.0 | 510343.6 | 45222 | 1.64041666667 | 12288 |
| 012522 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:15pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594565.8 | 510343.2 | 45224 | 1.64041666667 | 12522 |
| 012151 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:16pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594563.0 | 510345.2 | 45226 | 1.64041666667 | 12151 |
| 012730 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:17pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594561.2 | 510347.2 | 45228 | 1.64041666667 | 12730 |
| 011975 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:18pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594560.0 | 510349.9 | 45230 | 1.64041666667 | 11975 |
| 011678 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:19pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594558.4 | 510352.9 | 45232 | 1.64041666667 | 11678 |
| 011857 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:20pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594557.0 | 510356.0 | 45234 | 1.64041666667 | 11857 |
| 011057 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:21pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594556.1 | 510359.5 | 45236 | 1.64041666667 | 11057 |
| 010689 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:22pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594554.8 | 510362.8 | 45238 | 1.64041666667 | 10689 |
| 011420 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:23pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594553.1 | 510365.1 | 45240 | 1.64041666667 | 11420 |
| 011321 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:24pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594552.0 | 510368.3 | 45242 | 1.64041666667 | 11321 |
| 011453 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:25pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594550.9 | 510371.2 | 45244 | 1.64041666667 | 11453 |
| 011175 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:26pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594549.8 | 510373.7 | 45246 | 1.64041666667 | 11175 |
| 011956 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:27pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594549.5 | 510376.2 | 45248 | 1.64041666667 | 11956 |
| 011472 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:28pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594548.6 | 510378.9 | 45250 | 1.64041666667 | 11472 |
| 011291 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:29pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594548.2 | 510381.5 | 45252 | 1.64041666667 | 11291 |
| 010776 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:30pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594547.6 | 510383.9 | 45254 | 1.64041666667 | 10776 |
| 011266 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:31pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594545.9 | 510386.4 | 45256 | 1.64041666667 | 11266 |
| 010950 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:32pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594544.5 | 510389.1 | 45258 | 1.64041666667 | 10950 |
| 011656 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:33pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594543.3 | 510391.4 | 45260 | 1.64041666667 | 11656 |
| 011732 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:34pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594540.5 | 510393.7 | 45262 | 1.64041666667 | 11732 |
| 011294 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:35pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594539.0 | 510396.4 | 45264 | 1.64041666667 | 11294 |
| 011378 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:36pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594537.4 | 510399.9 | 45266 | 1.64041666667 | 11378 |
| 011567 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:37pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594535.6 | 510402.6 | 45268 | 1.64041666667 | 11567 |
| 010324 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:38pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594533.8 | 510405.9 | 45270 | 1.64041666667 | 10324 |
| 011620 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:39pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594532.9 | 510409.3 | 45272 | 1.64041666667 | 11620 |
| 010938 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:40pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594531.3 | 510412.7 | 45274 | 1.64041666667 | 10938 |
| 011268 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:41pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594529.6 | 510415.9 | 45276 | 1.64041666667 | 11268 |
| 011168 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:42pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594528.9 | 510419.5 | 45278 | 1.64041666667 | 11168 |
| 011884 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:43pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594528.4 | 510422.7 | 45280 | 1.64041666667 | 11884 |
| 012662 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:44pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594526.6 | 510426.3 | 45282 | 1.64041666667 | 12662 |
| 013257 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:45pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594524.9 | 510429.8 | 45284 | 1.64041666667 | 13257 |
| 013532 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:46pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594523.7 | 510434.0 | 45286 | 1.64041666667 | 13532 |
| 014647 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:47pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594522.5 | 510436.9 | 45288 | 1.64041666667 | 14647 |
| 015664 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:48pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594521.0 | 510439.9 | 45290 | 1.64041666667 | 15664 |
| 015786 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:49pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594520.5 | 510443.4 | 45292 | 1.64041666667 | 15786 |
| 016282 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:50pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594520.2 | 510446.3 | 45294 | 1.64041666667 | 16282 |
| 015728 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:51pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594519.9 | 510448.2 | 45296 | 1.64041666667 | 15728 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016302 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:52pm | Sensor | 1797-S0035-636-G-DTE | 6816.0 | 1594521.2 | 510448.9 | 45298 | 1.64041666667 | 16302 |
| 018110 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:53pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594520.9 | 510449.1 | 45300 | 1.64041666667 | 18110 |
| 016464 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:54pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594519.3 | 510450.1 | 45302 | 1.64041666667 | 16464 |
| 014976 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:55pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594518.2 | 510452.8 | 45304 | 1.64041666667 | 14976 |
| 015864 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:56pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594517.1 | 510455.5 | 45306 | 1.64041666667 | 15864 |
| 015673 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:57pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594516.5 | 510458.3 | 45308 | 1.64041666667 | 15673 |
| 015626 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:58pm | Sensor | 1797-S0035-636-G-DTE | 6816.0 | 1594516.1 | 510460.8 | 45310 | 1.64041666667 | 15626 |
| 015000 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:59pm | Sensor | 1797-S0035-636-G-DTE | 6816.0 | 1594514.9 | 510462.2 | 45312 | 1.64041666667 | 15000 |
| 015435 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:00pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594513.8 | 510462.3 | 45314 | 1.64041666667 | 15435 |
| 016107 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:01pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594511.8 | 510460.8 | 45316 | 1.64041666667 | 16107 |
| 016320 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:02pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594510.6 | 510459.6 | 45318 | 1.64041666667 | 16320 |
| 014932 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:03pm | Sensor | 1797-S0035-636-G-DTE | 6815.9 | 1594509.7 | 510458.9 | 45320 | 1.64041666667 | 14932 |
| 014767 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:04pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594509.6 | 510458.1 | 45322 | 1.64041666667 | 14767 |
| 014614 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:05pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594510.1 | 510455.5 | 45324 | 1.64041666667 | 14614 |
| 016080 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:06pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594510.6 | 510452.2 | 45326 | 1.64041666667 | 16080 |
| 016717 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:07pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594511.9 | 510448.6 | 45328 | 1.64041666667 | 16717 |
| 017541 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:08pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594513.2 | 510445.1 | 45330 | 1.64041666667 | 17541 |
| 018589 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:09pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594514.1 | 510441.9 | 45332 | 1.64041666667 | 18589 |
| 019306 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:10pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594515.9 | 510438.9 | 45334 | 1.64041666667 | 19306 |
| 020242 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:11pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594517.7 | 510436.2 | 45336 | 1.64041666667 | 20242 |
| 018811 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:12pm | Sensor | 1797-S0035-636-G-DTE | 6814.9 | 1594518.4 | 510432.7 | 45338 | 1.64041666667 | 18811 |
| 017309 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:13pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594519.6 | 510429.9 | 45340 | 1.64041666667 | 17309 |
| 016756 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:14pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594521.1 | 510426.8 | 45342 | 1.64041666667 | 16756 |
| 015627 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:15pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594521.8 | 510423.1 | 45344 | 1.64041666667 | 15627 |
| 013883 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:16pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594523.1 | 510419.7 | 45346 | 1.64041666667 | 13883 |
| 012886 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:17pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594524.7 | 510416.4 | 45348 | 1.64041666667 | 12886 |
| 012581 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:18pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594525.5 | 510412.6 | 45350 | 1.64041666667 | 12581 |
| 011134 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:19pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594526.6 | 510409.1 | 45352 | 1.64041666667 | 11134 |
| 011160 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:20pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594528.1 | 510406.1 | 45354 | 1.64041666667 | 11160 |
| 011070 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:21pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594529.0 | 510403.1 | 45356 | 1.64041666667 | 11070 |
| 010299 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:22pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594530.6 | 510400.0 | 45358 | 1.64041666667 | 10299 |
| 010286 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:23pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594532.2 | 510397.4 | 45360 | 1.64041666667 | 10286 |
| 010436 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:24pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594533.0 | 510393.9 | 45362 | 1.64041666667 | 10436 |
| 010692 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:25pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594534.0 | 510391.1 | 45364 | 1.64041666667 | 10692 |
| 010769 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:26pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594535.5 | 510388.3 | 45366 | 1.64041666667 | 10769 |
| 011128 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:27pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594536.4 | 510384.6 | 45368 | 1.64041666667 | 11128 |
| 011254 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:28pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594537.4 | 510381.4 | 45370 | 1.64041666667 | 11254 |
| 011310 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:29pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594538.5 | 510378.2 | 45372 | 1.64041666667 | 11310 |
| 011462 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:30pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594539.3 | 510374.5 | 45374 | 1.64041666667 | 11462 |
| 010797 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:31pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594540.7 | 510371.6 | 45376 | 1.64041666667 | 10797 |
| 010438 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:32pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594543.2 | 510368.9 | 45378 | 1.64041666667 | 10438 |
| 010881 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:33pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594544.9 | 510366.1 | 45380 | 1.64041666667 | 10881 |
| 011258 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:34pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594546.9 | 510363.0 | 45382 | 1.64041666667 | 11258 |
| 011695 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:35pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594549.2 | 510360.7 | 45384 | 1.64041666667 | 11695 |
| 012406 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:36pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594551.5 | 510357.6 | 45386 | 1.64041666667 | 12406 |
| 012498 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:37pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594552.8 | 510354.1 | 45388 | 1.64041666667 | 12498 |
| 011628 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:38pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594554.4 | 510350.7 | 45390 | 1.64041666667 | 11628 |
| 011985 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:39pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594555.9 | 510348.4 | 45392 | 1.64041666667 | 11985 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012224 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:40pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594556.0 | 510345.2 | 45394 | 1.64041666667 | 12224 |
| 011638 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:41pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594555.2 | 510342.8 | 45396 | 1.64041666667 | 11638 |
| 011534 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:42pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594552.6 | 510341.4 | 45398 | 1.64041666667 | 11534 |
| 012473 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:43pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594550.0 | 510340.4 | 45400 | 1.64041666667 | 12473 |
| 011771 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:44pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594546.6 | 510339.1 | 45402 | 1.64041666667 | 11771 |
| 012291 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:45pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594545.1 | 510338.7 | 45404 | 1.64041666667 | 12291 |
| 012058 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:46pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594545.2 | 510338.7 | 45406 | 1.64041666667 | 12058 |
| 012130 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:47pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594545.2 | 510338.8 | 45408 | 1.64041666667 | 12130 |
| 012463 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:48pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594545.1 | 510339.2 | 45410 | 1.64041666667 | 12463 |
| 012568 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:49pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594544.1 | 510340.2 | 45412 | 1.64041666667 | 12568 |
| 013174 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:50pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594542.3 | 510341.6 | 45414 | 1.64041666667 | 13174 |
| 012731 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:51pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594541.0 | 510344.3 | 45416 | 1.64041666667 | 12731 |
| 012737 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:52pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594540.3 | 510347.4 | 45418 | 1.64041666667 | 12737 |
| 012325 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:53pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594538.8 | 510350.6 | 45420 | 1.64041666667 | 12325 |
| 012063 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:54pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594538.0 | 510354.3 | 45422 | 1.64041666667 | 12063 |
| 012170 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:55pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594537.4 | 510357.7 | 45424 | 1.64041666667 | 12170 |
| 011713 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:56pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594536.0 | 510361.0 | 45426 | 1.64041666667 | 11713 |
| 012168 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:57pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594535.0 | 510364.3 | 45428 | 1.64041666667 | 12168 |
| 011915 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:58pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594534.5 | 510367.1 | 45430 | 1.64041666667 | 11915 |
| 011839 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:59pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594533.3 | 510370.0 | 45432 | 1.64041666667 | 11839 |
| 011670 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:00pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594532.4 | 510373.5 | 45434 | 1.64041666667 | 11670 |
| 011724 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:01pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594531.1 | 510376.7 | 45436 | 1.64041666667 | 11724 |
| 012017 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:02pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594529.5 | 510379.4 | 45438 | 1.64041666667 | 12017 |
| 011559 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:03pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594528.3 | 510382.4 | 45440 | 1.64041666667 | 11559 |
| 011535 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:04pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594526.7 | 510385.3 | 45442 | 1.64041666667 | 11535 |
| 012150 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:05pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594524.6 | 510388.1 | 45444 | 1.64041666667 | 12150 |
| 011979 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:06pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594523.0 | 510390.9 | 45446 | 1.64041666667 | 11979 |
| 011771 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:07pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594521.4 | 510394.1 | 45448 | 1.64041666667 | 11771 |
| 011901 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:08pm | Sensor | 1797-S0035-636-G-DTE | 6812.9 | 1594519.5 | 510397.1 | 45450 | 1.64041666667 | 11901 |
| 011299 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:09pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594518.6 | 510400.5 | 45452 | 1.64041666667 | 11299 |
| 011898 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:10pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594518.4 | 510403.8 | 45454 | 1.64041666667 | 11898 |
| 011253 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:11pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594517.5 | 510407.0 | 45456 | 1.64041666667 | 11253 |
| 012172 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:12pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594516.6 | 510410.6 | 45458 | 1.64041666667 | 12172 |
| 013027 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:13pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594516.1 | 510413.2 | 45460 | 1.64041666667 | 13027 |
| 014460 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:14pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594514.9 | 510415.8 | 45462 | 1.64041666667 | 14460 |
| 016616 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:15pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594514.2 | 510418.7 | 45464 | 1.64041666667 | 16616 |
| 017019 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:16pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594513.6 | 510420.9 | 45466 | 1.64041666667 | 17019 |
| 017560 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:17pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594512.8 | 510422.7 | 45468 | 1.64041666667 | 17560 |
| 017242 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:18pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594511.9 | 510425.3 | 45470 | 1.64041666667 | 17242 |
| 015879 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:19pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594510.5 | 510427.4 | 45472 | 1.64041666667 | 15879 |
| 015802 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:20pm | Sensor | 1797-S0035-636-G-DTE | 6815.0 | 1594508.8 | 510431.1 | 45474 | 1.64041666667 | 15802 |
| 016666 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:21pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594507.9 | 510432.6 | 45476 | 1.64041666667 | 16666 |
| 016064 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:22pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594506.5 | 510435.2 | 45478 | 1.64041666667 | 16064 |
| 015816 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:23pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594506.2 | 510438.0 | 45480 | 1.64041666667 | 15816 |
| 015729 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:24pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594504.5 | 510440.3 | 45482 | 1.64041666667 | 15729 |
| 014592 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:25pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594502.9 | 510442.7 | 45484 | 1.64041666667 | 14592 |
| 015543 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:26pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594502.2 | 510444.9 | 45486 | 1.64041666667 | 15543 |
| 015238 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:27pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594501.1 | 510446.8 | 45488 | 1.64041666667 | 15238 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014759 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:28pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594500.4 | 510448.1 | 45490 | 1.64041666667 | 14759 |
| 014422 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:29pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594498.7 | 510448.1 | 45492 | 1.64041666667 | 14422 |
| 013587 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:30pm | Sensor | 1797-S0035-636-G-DTE | 6815.4 | 1594496.2 | 510447.8 | 45494 | 1.64041666667 | 13587 |
| 013905 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:31pm | Sensor | 1797-S0035-636-G-DTE | 6815.3 | 1594494.4 | 510446.8 | 45496 | 1.64041666667 | 13905 |
| 013844 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:32pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594493.4 | 510445.4 | 45498 | 1.64041666667 | 13844 |
| 013202 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:33pm | Sensor | 1797-S0035-636-G-DTE | 6815.2 | 1594493.2 | 510444.6 | 45500 | 1.64041666667 | 13202 |
| 012608 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:34pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594494.1 | 510443.2 | 45502 | 1.64041666667 | 12608 |
| 012140 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:35pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594495.2 | 510440.2 | 45504 | 1.64041666667 | 12140 |
| 012033 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:36pm | Sensor | 1797-S0035-636-G-DTE | 6815.1 | 1594496.0 | 510436.8 | 45506 | 1.64041666667 | 12033 |
| 012071 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:37pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594497.9 | 510433.8 | 45508 | 1.64041666667 | 12071 |
| 013247 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:38pm | Sensor | 1797-S0035-636-G-DTE | 6814.9 | 1594499.7 | 510430.7 | 45510 | 1.64041666667 | 13247 |
| 013106 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:39pm | Sensor | 1797-S0035-636-G-DTE | 6815.0 | 1594501.1 | 510427.9 | 45512 | 1.64041666667 | 13106 |
| 013687 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:40pm | Sensor | 1797-S0035-636-G-DTE | 6814.7 | 1594502.8 | 510425.1 | 45514 | 1.64041666667 | 13687 |
| 014576 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:41pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594504.3 | 510422.1 | 45516 | 1.64041666667 | 14576 |
| 014897 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:42pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594505.5 | 510418.4 | 45518 | 1.64041666667 | 14897 |
| 016352 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:43pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594507.1 | 510415.6 | 45520 | 1.64041666667 | 16352 |
| 016210 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:44pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594508.5 | 510412.7 | 45522 | 1.64041666667 | 16210 |
| 015523 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:45pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594509.4 | 510410.1 | 45524 | 1.64041666667 | 15523 |
| 015699 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:46pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594511.0 | 510407.2 | 45526 | 1.64041666667 | 15699 |
| 014564 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:47pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594512.8 | 510404.4 | 45528 | 1.64041666667 | 14564 |
| 013121 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:48pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594515.1 | 510400.9 | 45530 | 1.64041666667 | 13121 |
| 012225 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:49pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594516.9 | 510397.6 | 45532 | 1.64041666667 | 12225 |
| 011647 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:50pm | Sensor | 1797-S0035-636-G-DTE | 6813.0 | 1594518.0 | 510393.7 | 45534 | 1.64041666667 | 11647 |
| 011223 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:51pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594518.5 | 510390.2 | 45536 | 1.64041666667 | 11223 |
| 010873 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:52pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594518.6 | 510386.4 | 45538 | 1.64041666667 | 10873 |
| 011418 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:53pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594519.7 | 510382.9 | 45540 | 1.64041666667 | 11418 |
| 011590 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:54pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594520.5 | 510379.9 | 45542 | 1.64041666667 | 11590 |
| 011282 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:55pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594521.0 | 510376.8 | 45544 | 1.64041666667 | 11282 |
| 011026 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:56pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594522.2 | 510373.7 | 45546 | 1.64041666667 | 11026 |
| 011557 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:57pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594523.3 | 510370.8 | 45548 | 1.64041666667 | 11557 |
| 010926 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:58pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594523.4 | 510367.4 | 45550 | 1.64041666667 | 10926 |
| 010653 | 0 | GeoXH 6000 | 08/18/2015 | 02:04:59pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594524.0 | 510363.8 | 45552 | 1.64041666667 | 10653 |
| 011032 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:00pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594525.1 | 510360.2 | 45554 | 1.64041666667 | 11032 |
| 010211 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:01pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594525.9 | 510356.5 | 45556 | 1.64041666667 | 10211 |
| 010723 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:02pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594526.9 | 510353.0 | 45558 | 1.64041666667 | 10723 |
| 011432 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:03pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594528.2 | 510349.9 | 45560 | 1.64041666667 | 11432 |
| 011035 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:04pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594528.8 | 510346.7 | 45562 | 1.64041666667 | 11035 |
| 011525 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:05pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594529.6 | 510343.7 | 45564 | 1.64041666667 | 11525 |
| 012242 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:06pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594531.4 | 510340.2 | 45566 | 1.64041666667 | 12242 |
| 012556 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:07pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594532.1 | 510336.9 | 45568 | 1.64041666667 | 12556 |
| 012290 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:08pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594532.1 | 510333.7 | 45570 | 1.64041666667 | 12290 |
| 011166 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:09pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594531.4 | 510330.7 | 45572 | 1.64041666667 | 11166 |
| 011598 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:10pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594527.9 | 510329.1 | 45574 | 1.64041666667 | 11598 |
| 012629 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:11pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594525.3 | 510328.7 | 45576 | 1.64041666667 | 12629 |
| 013126 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:12pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594523.8 | 510329.1 | 45578 | 1.64041666667 | 13126 |
| 012926 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:13pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594523.6 | 510331.3 | 45580 | 1.64041666667 | 12926 |
| 012138 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:14pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594522.1 | 510334.4 | 45582 | 1.64041666667 | 12138 |
| 012550 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:15pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594520.5 | 510338.4 | 45584 | 1.64041666667 | 12550 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012017 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:16pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594520.0 | 510342.1 | 45586 | 1.64041666667 | 12017 |
| 011942 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:17pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594519.0 | 510345.6 | 45588 | 1.64041666667 | 11942 |
| 011405 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:18pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594517.3 | 510348.9 | 45590 | 1.64041666667 | 11405 |
| 011665 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:19pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594516.2 | 510351.8 | 45592 | 1.64041666667 | 11665 |
| 011609 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:20pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594515.5 | 510355.4 | 45594 | 1.64041666667 | 11609 |
| 012245 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:21pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594514.7 | 510358.2 | 45596 | 1.64041666667 | 12245 |
| 012805 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:22pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594514.0 | 510361.9 | 45598 | 1.64041666667 | 12805 |
| 011748 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:23pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594513.5 | 510364.9 | 45600 | 1.64041666667 | 11748 |
| 011025 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:24pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594511.9 | 510368.8 | 45602 | 1.64041666667 | 11025 |
| 011872 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:25pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594510.8 | 510372.1 | 45604 | 1.64041666667 | 11872 |
| 011943 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:26pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594509.9 | 510375.3 | 45606 | 1.64041666667 | 11943 |
| 011203 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:27pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594508.5 | 510378.6 | 45608 | 1.64041666667 | 11203 |
| 011356 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:28pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594507.6 | 510382.3 | 45610 | 1.64041666667 | 11356 |
| 011210 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:29pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594507.3 | 510385.8 | 45612 | 1.64041666667 | 11210 |
| 011871 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:30pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594506.9 | 510388.9 | 45614 | 1.64041666667 | 11871 |
| 011485 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:31pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594506.8 | 510391.3 | 45616 | 1.64041666667 | 11485 |
| 010480 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:32pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594507.9 | 510393.4 | 45618 | 1.64041666667 | 10480 |
| 010680 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:33pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594507.8 | 510397.1 | 45620 | 1.64041666667 | 10680 |
| 011287 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:34pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594507.4 | 510400.5 | 45622 | 1.64041666667 | 11287 |
| 011179 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:35pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594506.8 | 510403.9 | 45624 | 1.64041666667 | 11179 |
| 012048 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:36pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594505.5 | 510407.7 | 45626 | 1.64041666667 | 12048 |
| 014209 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:37pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594503.8 | 510410.2 | 45628 | 1.64041666667 | 14209 |
| 014810 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:38pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594501.5 | 510413.3 | 45630 | 1.64041666667 | 14810 |
| 014917 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:39pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594501.0 | 510415.8 | 45632 | 1.64041666667 | 14917 |
| 015961 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:40pm | Sensor | 1797-S0035-636-G-DTE | 6814.4 | 1594498.5 | 510418.3 | 45634 | 1.64041666667 | 15961 |
| 015045 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:41pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594496.6 | 510420.6 | 45636 | 1.64041666667 | 15045 |
| 015948 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:42pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594494.5 | 510423.1 | 45638 | 1.64041666667 | 15948 |
| 014948 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:43pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594492.1 | 510425.1 | 45640 | 1.64041666667 | 14948 |
| 013995 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:44pm | Sensor | 1797-S0035-636-G-DTE | 6814.7 | 1594489.7 | 510428.1 | 45642 | 1.64041666667 | 13995 |
| 013212 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:45pm | Sensor | 1797-S0035-636-G-DTE | 6814.8 | 1594487.9 | 510430.2 | 45644 | 1.64041666667 | 13212 |
| 013942 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:46pm | Sensor | 1797-S0035-636-G-DTE | 6814.6 | 1594485.2 | 510431.5 | 45646 | 1.64041666667 | 13942 |
| 013760 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:47pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594483.2 | 510432.0 | 45648 | 1.64041666667 | 13760 |
| 013500 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:48pm | Sensor | 1797-S0035-636-G-DTE | 6814.5 | 1594481.1 | 510430.8 | 45650 | 1.64041666667 | 13500 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:49pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594480.6 | 510428.4 | 45652 | 1.64041666667 | 13436 |
| 012440 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:50pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594482.0 | 510424.2 | 45654 | 1.64041666667 | 12440 |
| 012030 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:51pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594483.6 | 510421.0 | 45656 | 1.64041666667 | 12030 |
| 012362 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:52pm | Sensor | 1797-S0035-636-G-DTE | 6814.3 | 1594485.5 | 510417.4 | 45658 | 1.64041666667 | 12362 |
| 012586 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:53pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594487.2 | 510414.8 | 45660 | 1.64041666667 | 12586 |
| 013237 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:54pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594489.1 | 510411.0 | 45662 | 1.64041666667 | 13237 |
| 014488 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:55pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594490.9 | 510408.4 | 45664 | 1.64041666667 | 14488 |
| 014187 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:56pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594493.3 | 510405.2 | 45666 | 1.64041666667 | 14187 |
| 013470 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:57pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594494.5 | 510401.7 | 45668 | 1.64041666667 | 13470 |
| 012924 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:58pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594495.9 | 510397.8 | 45670 | 1.64041666667 | 12924 |
| 012055 | 0 | GeoXH 6000 | 08/18/2015 | 02:05:59pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594497.5 | 510395.2 | 45672 | 1.64041666667 | 12055 |
| 012353 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:00pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594499.5 | 510392.9 | 45674 | 1.64041666667 | 12353 |
| 011778 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:01pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594500.7 | 510389.9 | 45676 | 1.64041666667 | 11778 |
| 011703 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:02pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594502.4 | 510386.5 | 45678 | 1.64041666667 | 11703 |
| 011773 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:03pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594503.4 | 510383.2 | 45680 | 1.64041666667 | 11773 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011219 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:04pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594504.1 | 510379.3 | 45682 | 1.64041666667 | 11219 |
| 011388 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:05pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594505.2 | 510376.1 | 45684 | 1.64041666667 | 11388 |
| 011603 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:06pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594506.8 | 510372.9 | 45686 | 1.64041666667 | 11603 |
| 011544 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:07pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594507.5 | 510369.8 | 45688 | 1.64041666667 | 11544 |
| 011181 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:08pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594508.8 | 510365.9 | 45690 | 1.64041666667 | 11181 |
| 010647 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:09pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594509.4 | 510362.7 | 45692 | 1.64041666667 | 10647 |
| 010511 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:10pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594509.3 | 510358.2 | 45694 | 1.64041666667 | 10511 |
| 011350 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:11pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594509.5 | 510354.9 | 45696 | 1.64041666667 | 11350 |
| 010854 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:12pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594510.6 | 510350.7 | 45698 | 1.64041666667 | 10854 |
| 010883 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:13pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594511.3 | 510347.6 | 45700 | 1.64041666667 | 10883 |
| 011064 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:14pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594512.2 | 510343.9 | 45702 | 1.64041666667 | 11064 |
| 011518 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:15pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594513.3 | 510340.8 | 45704 | 1.64041666667 | 11518 |
| 011076 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:16pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594514.2 | 510337.2 | 45706 | 1.64041666667 | 11076 |
| 011675 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:17pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594514.8 | 510334.4 | 45708 | 1.64041666667 | 11675 |
| 011517 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:18pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594516.3 | 510330.7 | 45710 | 1.64041666667 | 11517 |
| 011188 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:19pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594516.3 | 510328.4 | 45712 | 1.64041666667 | 11188 |
| 011483 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:20pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594513.9 | 510326.1 | 45714 | 1.64041666667 | 11483 |
| 011522 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:21pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594511.6 | 510324.7 | 45716 | 1.64041666667 | 11522 |
| 011948 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:22pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594509.6 | 510324.6 | 45718 | 1.64041666667 | 11948 |
| 012601 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:23pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594508.9 | 510324.7 | 45720 | 1.64041666667 | 12601 |
| 011610 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:24pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594508.8 | 510325.3 | 45722 | 1.64041666667 | 11610 |
| 012186 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:25pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594507.8 | 510326.4 | 45724 | 1.64041666667 | 12186 |
| 011654 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:26pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594506.2 | 510328.5 | 45726 | 1.64041666667 | 11654 |
| 011715 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:27pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594504.6 | 510330.8 | 45728 | 1.64041666667 | 11715 |
| 011135 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:28pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594503.8 | 510334.4 | 45730 | 1.64041666667 | 11135 |
| 011776 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:29pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594502.6 | 510337.1 | 45732 | 1.64041666667 | 11776 |
| 011326 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:30pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594501.2 | 510340.5 | 45734 | 1.64041666667 | 11326 |
| 010938 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:31pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594500.3 | 510343.3 | 45736 | 1.64041666667 | 10938 |
| 010495 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:32pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594498.7 | 510347.1 | 45738 | 1.64041666667 | 10495 |
| 010951 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:33pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594498.0 | 510349.7 | 45740 | 1.64041666667 | 10951 |
| 011005 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:34pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594497.5 | 510353.7 | 45742 | 1.64041666667 | 11005 |
| 011230 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:35pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594496.7 | 510356.7 | 45744 | 1.64041666667 | 11230 |
| 011132 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:36pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594495.5 | 510360.6 | 45746 | 1.64041666667 | 11132 |
| 011519 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:37pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594495.2 | 510363.7 | 45748 | 1.64041666667 | 11519 |
| 011519 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:38pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594494.0 | 510367.8 | 45750 | 1.64041666667 | 11519 |
| 012030 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:39pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594493.0 | 510370.9 | 45752 | 1.64041666667 | 12030 |
| 012609 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:40pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594492.8 | 510374.9 | 45754 | 1.64041666667 | 12609 |
| 011705 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:41pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594492.3 | 510377.2 | 45756 | 1.64041666667 | 11705 |
| 011856 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:42pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594491.9 | 510380.4 | 45758 | 1.64041666667 | 11856 |
| 011214 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:43pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594492.2 | 510383.5 | 45760 | 1.64041666667 | 11214 |
| 012330 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:44pm | Sensor | 1797-S0035-636-G-DTE | 6812.9 | 1594491.3 | 510387.0 | 45762 | 1.64041666667 | 12330 |
| 012577 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:45pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594490.0 | 510389.5 | 45764 | 1.64041666667 | 12577 |
| 011835 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:46pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594489.1 | 510393.0 | 45766 | 1.64041666667 | 11835 |
| 011209 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:47pm | Sensor | 1797-S0035-636-G-DTE | 6813.0 | 1594487.7 | 510395.6 | 45768 | 1.64041666667 | 11209 |
| 010910 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:48pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594486.4 | 510398.8 | 45770 | 1.64041666667 | 10910 |
| 011162 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:49pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594485.8 | 510401.7 | 45772 | 1.64041666667 | 11162 |
| 011498 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:50pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594484.1 | 510405.7 | 45774 | 1.64041666667 | 11498 |
| 011673 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:51pm | Sensor | 1797-S0035-636-G-DTE | 6814.0 | 1594482.9 | 510408.3 | 45776 | 1.64041666667 | 11673 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012146 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:52pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594482.0 | 510412.0 | 45778 | 1.64041666667 | 12146 |
| 012149 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:53pm | Sensor | 1797-S0035-636-G-DTE | 6814.2 | 1594480.6 | 510414.5 | 45780 | 1.64041666667 | 12149 |
| 012609 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:54pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594478.7 | 510417.9 | 45782 | 1.64041666667 | 12609 |
| 012582 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:55pm | Sensor | 1797-S0035-636-G-DTE | 6814.1 | 1594477.4 | 510420.7 | 45784 | 1.64041666667 | 12582 |
| 012507 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:56pm | Sensor | 1797-S0035-636-G-DTE | 6813.9 | 1594475.2 | 510423.5 | 45786 | 1.64041666667 | 12507 |
| 012315 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:57pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594473.4 | 510424.8 | 45788 | 1.64041666667 | 12315 |
| 012822 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:58pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594471.5 | 510426.5 | 45790 | 1.64041666667 | 12822 |
| 013197 | 0 | GeoXH 6000 | 08/18/2015 | 02:06:59pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594469.4 | 510426.4 | 45792 | 1.64041666667 | 13197 |
| 013161 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:00pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594467.3 | 510425.0 | 45794 | 1.64041666667 | 13161 |
| 012398 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:01pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594466.0 | 510424.5 | 45796 | 1.64041666667 | 12398 |
| 013394 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:02pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594466.1 | 510423.9 | 45798 | 1.64041666667 | 13394 |
| 013121 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:03pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594466.3 | 510421.9 | 45800 | 1.64041666667 | 13121 |
| 012683 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:04pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594467.8 | 510418.1 | 45802 | 1.64041666667 | 12683 |
| 012534 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:05pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594468.7 | 510415.0 | 45804 | 1.64041666667 | 12534 |
| 011933 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:06pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594469.6 | 510411.6 | 45806 | 1.64041666667 | 11933 |
| 011902 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:07pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594471.2 | 510408.8 | 45808 | 1.64041666667 | 11902 |
| 011532 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:08pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594472.9 | 510405.6 | 45810 | 1.64041666667 | 11532 |
| 011617 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:09pm | Sensor | 1797-S0035-636-G-DTE | 6813.7 | 1594473.1 | 510402.8 | 45812 | 1.64041666667 | 11617 |
| 011057 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:10pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594474.3 | 510398.9 | 45814 | 1.64041666667 | 11057 |
| 011537 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:11pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594475.2 | 510396.2 | 45816 | 1.64041666667 | 11537 |
| 011927 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:12pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594476.6 | 510392.3 | 45818 | 1.64041666667 | 11927 |
| 012124 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:13pm | Sensor | 1797-S0035-636-G-DTE | 6812.8 | 1594479.1 | 510389.2 | 45820 | 1.64041666667 | 12124 |
| 011297 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:14pm | Sensor | 1797-S0035-636-G-DTE | 6812.9 | 1594480.4 | 510386.4 | 45822 | 1.64041666667 | 11297 |
| 011777 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:15pm | Sensor | 1797-S0035-636-G-DTE | 6812.9 | 1594481.1 | 510383.6 | 45824 | 1.64041666667 | 11777 |
| 011807 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:16pm | Sensor | 1797-S0035-636-G-DTE | 6812.8 | 1594482.7 | 510380.1 | 45826 | 1.64041666667 | 11807 |
| 013129 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:17pm | Sensor | 1797-S0035-636-G-DTE | 6812.7 | 1594484.2 | 510377.3 | 45828 | 1.64041666667 | 13129 |
| 011787 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:18pm | Sensor | 1797-S0035-636-G-DTE | 6812.9 | 1594485.2 | 510373.6 | 45830 | 1.64041666667 | 11787 |
| 012050 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:19pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594486.2 | 510370.5 | 45832 | 1.64041666667 | 12050 |
| 011427 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:20pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594487.4 | 510368.2 | 45834 | 1.64041666667 | 11427 |
| 011400 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:21pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594488.3 | 510365.4 | 45836 | 1.64041666667 | 11400 |
| 010695 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:22pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594489.0 | 510362.9 | 45838 | 1.64041666667 | 10695 |
| 011566 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:23pm | Sensor | 1797-S0035-636-G-DTE | 6813.2 | 1594490.5 | 510359.5 | 45840 | 1.64041666667 | 11566 |
| 012183 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:24pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594491.8 | 510356.4 | 45842 | 1.64041666667 | 12183 |
| 012583 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:25pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594492.7 | 510353.5 | 45844 | 1.64041666667 | 12583 |
| 012245 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:26pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594494.4 | 510350.4 | 45846 | 1.64041666667 | 12245 |
| 012100 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:27pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594495.5 | 510347.6 | 45848 | 1.64041666667 | 12100 |
| 011299 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:28pm | Sensor | 1797-S0035-636-G-DTE | 6813.4 | 1594496.5 | 510344.0 | 45850 | 1.64041666667 | 11299 |
| 010870 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:29pm | Sensor | 1797-S0035-636-G-DTE | 6813.1 | 1594497.8 | 510341.3 | 45852 | 1.64041666667 | 10870 |
| 010914 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:30pm | Sensor | 1797-S0035-636-G-DTE | 6813.3 | 1594499.1 | 510337.4 | 45854 | 1.64041666667 | 10914 |
| 011224 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:31pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594500.1 | 510334.9 | 45856 | 1.64041666667 | 11224 |
| 011098 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:32pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594502.0 | 510332.4 | 45858 | 1.64041666667 | 11098 |
| 011838 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:33pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594502.6 | 510329.2 | 45860 | 1.64041666667 | 11838 |
| 011339 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:34pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594503.5 | 510326.1 | 45862 | 1.64041666667 | 11339 |
| 011410 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:35pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594504.4 | 510324.1 | 45864 | 1.64041666667 | 11410 |
| 011196 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:36pm | Sensor | 1797-S0035-636-G-DTE | 6813.8 | 1594504.1 | 510322.0 | 45866 | 1.64041666667 | 11196 |
| 011952 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:37pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594504.5 | 510320.3 | 45868 | 1.64041666667 | 11952 |
| 011981 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:38pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594504.4 | 510320.3 | 45870 | 1.64041666667 | 11981 |
| 011584 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:39pm | Sensor | 1797-S0035-636-G-DTE | 6813.6 | 1594504.4 | 510320.3 | 45872 | 1.64041666667 | 11584 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012246 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:40pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594504.3 | 510320.2 | 45874 | 1.64041666667 | 12246 |
| 012078 | 0 | GeoXH 6000 | 08/18/2015 | 02:07:41pm | Sensor | 1797-S0035-636-G-DTE | 6813.5 | 1594504.4 | 510320.3 | 45876 | 1.64041666667 | 12078 |
| 022425 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:01pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510448.7 | 45877 | 1.64041666667 | 22425 |
| 021449 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:02pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.8 | 510450.1 | 45879 | 1.64041666667 | 21449 |
| 021740 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:03pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.8 | 510450.2 | 45881 | 1.64041666667 | 21740 |
| 022721 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:04pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.8 | 510450.2 | 45883 | 1.64041666667 | 22721 |
| 022688 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:05pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.8 | 510450.1 | 45885 | 1.64041666667 | 22688 |
| 022467 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:06pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.8 | 510450.1 | 45887 | 1.64041666667 | 22467 |
| 021772 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:07pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.8 | 510450.0 | 45889 | 1.64041666667 | 21772 |
| 021547 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:08pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594521.8 | 510450.0 | 45891 | 1.64041666667 | 21547 |
| 020820 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:09pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594521.8 | 510450.1 | 45893 | 1.64041666667 | 20820 |
| 020756 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:10pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510450.1 | 45895 | 1.64041666667 | 20756 |
| 021080 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:11pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594521.8 | 510450.1 | 45897 | 1.64041666667 | 21080 |
| 021510 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:12pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594521.8 | 510450.1 | 45899 | 1.64041666667 | 21510 |
| 021737 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:13pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594521.8 | 510450.1 | 45901 | 1.64041666667 | 21737 |
| 021084 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:14pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594521.8 | 510450.1 | 45903 | 1.64041666667 | 21084 |
| 022127 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:15pm | Sensor | 1797-S0035-636-G-DTE | 6815.8 | 1594521.8 | 510450.0 | 45904 | 1.64041666667 | 22127 |
| 022140 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:25pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510449.9 | 45906 | 1.64041666667 | 22140 |
| 021836 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:26pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510449.9 | 45907 | 1.64041666667 | 21836 |
| 021972 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:27pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510449.9 | 45908 | 1.64041666667 | 21972 |
| 020999 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:28pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510449.9 | 45909 | 1.64041666667 | 20999 |
| 021945 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:29pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510449.9 | 45910 | 1.64041666667 | 21945 |
| 022656 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:30pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510450.0 | 45911 | 1.64041666667 | 22656 |
| 023064 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:30pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510450.0 | 45912 | 1.64041666667 | 23064 |
| 022176 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:32pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510450.0 | 45913 | 1.64041666667 | 22176 |
| 022966 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:32pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510450.0 | 45914 | 1.64041666667 | 22966 |
| 022721 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:34pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.6 | 510450.0 | 45915 | 1.64041666667 | 22721 |
| 022125 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:35pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510450.0 | 45916 | 1.64041666667 | 22125 |
| 022188 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:36pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45917 | 1.64041666667 | 22188 |
| 021885 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:37pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45918 | 1.64041666667 | 21885 |
| 021461 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:38pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510449.9 | 45919 | 1.64041666667 | 21461 |
| 021551 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:39pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510449.8 | 45920 | 1.64041666667 | 21551 |
| 021648 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:40pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510449.9 | 45921 | 1.64041666667 | 21648 |
| 021199 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:41pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510449.9 | 45922 | 1.64041666667 | 21199 |
| 021644 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:42pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510450.0 | 45923 | 1.64041666667 | 21644 |
| 021392 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:43pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510450.0 | 45924 | 1.64041666667 | 21392 |
| 022203 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:44pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510450.0 | 45925 | 1.64041666667 | 22203 |
| 020912 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:45pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45926 | 1.64041666667 | 20912 |
| 021265 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:46pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45927 | 1.64041666667 | 21265 |
| 022649 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:46pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45928 | 1.64041666667 | 22649 |
| 022872 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:48pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.8 | 45929 | 1.64041666667 | 22872 |
| 022586 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:48pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.8 | 45930 | 1.64041666667 | 22586 |
| 022184 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:50pm | Sensor | 1797-S0035-636-G-DTE | 6815.7 | 1594521.7 | 510449.8 | 45931 | 1.64041666667 | 22184 |
| 022589 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:51pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45932 | 1.64041666667 | 22589 |
| 022028 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:52pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45933 | 1.64041666667 | 22028 |
| 022036 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:53pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.9 | 45934 | 1.64041666667 | 22036 |
| 022572 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:54pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.9 | 45935 | 1.64041666667 | 22572 |
| 022567 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:55pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.9 | 45936 | 1.64041666667 | 22567 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 022241 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:56pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.8 | 45937 | 1.64041666667 | 22241 |
| 022958 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:57pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594521.6 | 510449.8 | 45938 | 1.64041666667 | 22958 |
| 022491 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:58pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.8 | 45939 | 1.64041666667 | 22491 |
| 022094 | 0 | GeoXH 6000 | 08/18/2015 | 02:09:58pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45940 | 1.64041666667 | 22094 |
| 021637 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:00pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45941 | 1.64041666667 | 21637 |
| 021141 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:00pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.8 | 45942 | 1.64041666667 | 21141 |
| 021717 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:02pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45943 | 1.64041666667 | 21717 |
| 022235 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:03pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45944 | 1.64041666667 | 22235 |
| 021980 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:04pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45945 | 1.64041666667 | 21980 |
| 021836 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:04pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.8 | 45946 | 1.64041666667 | 21836 |
| 021313 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:06pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.8 | 45947 | 1.64041666667 | 21313 |
| 021933 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:06pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.8 | 45948 | 1.64041666667 | 21933 |
| 022672 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:08pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.8 | 45949 | 1.64041666667 | 22672 |
| 022781 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:08pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.8 | 45950 | 1.64041666667 | 22781 |
| 022984 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:10pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.9 | 45951 | 1.64041666667 | 22984 |
| 022798 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:11pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.9 | 45952 | 1.64041666667 | 22798 |
| 023241 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:12pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.6 | 510449.8 | 45953 | 1.64041666667 | 23241 |
| 022426 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:13pm | Sensor | 1797-S0035-636-G-DTE | 6815.5 | 1594521.6 | 510449.8 | 45954 | 1.64041666667 | 22426 |
| 022124 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:14pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.8 | 45955 | 1.64041666667 | 22124 |
| 022217 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:15pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.8 | 45956 | 1.64041666667 | 22217 |
| 021460 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:16pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.7 | 45957 | 1.64041666667 | 21460 |
| 021431 | 0 | GeoXH 6000 | 08/18/2015 | 02:10:16pm | Sensor | 1797-S0035-636-G-DTE | 6815.6 | 1594521.7 | 510449.9 | 45958 | 1.64041666667 | 21431 |
| 020583 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:14am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509563.6 | 41106 | 1.64041666667 | 20583 |
| 020240 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:15am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.5 | 509563.5 | 41108 | 1.64041666667 | 20240 |
| 020377 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:16am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.5 | 509563.5 | 41111 | 1.64041666667 | 20377 |
| 020207 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:17am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.5 | 509563.5 | 41113 | 1.64041666667 | 20207 |
| 019406 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:18am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509563.5 | 41115 | 1.64041666667 | 19406 |
| 019646 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:19am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509563.5 | 41117 | 1.64041666667 | 19646 |
| 019458 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:21am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509563.5 | 41120 | 1.64041666667 | 19458 |
| 020448 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:21am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509563.5 | 41121 | 1.64041666667 | 20448 |
| 021124 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:23am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509563.5 | 41124 | 1.64041666667 | 21124 |
| 020957 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:23am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509563.5 | 41125 | 1.64041666667 | 20957 |
| 020773 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:24am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594140.4 | 509563.6 | 41127 | 1.64041666667 | 20773 |
| 020842 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:25am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594140.3 | 509563.9 | 41129 | 1.64041666667 | 20842 |
| 020461 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:26am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.4 | 509564.1 | 41131 | 1.64041666667 | 20461 |
| 021132 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:27am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.4 | 509564.1 | 41133 | 1.64041666667 | 21132 |
| 021239 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:28am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.5 | 509564.1 | 41135 | 1.64041666667 | 21239 |
| 020924 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:29am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594140.5 | 509564.1 | 41137 | 1.64041666667 | 20924 |
| 020402 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:30am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.5 | 509564.0 | 41139 | 1.64041666667 | 20402 |
| 020874 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:31am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.5 | 509564.0 | 41141 | 1.64041666667 | 20874 |
| 020584 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:32am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509564.0 | 41143 | 1.64041666667 | 20584 |
| 020628 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:33am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509564.0 | 41145 | 1.64041666667 | 20628 |
| 020903 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:34am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509564.0 | 41147 | 1.64041666667 | 20903 |
| 021065 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:35am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.6 | 509563.8 | 41149 | 1.64041666667 | 21065 |
| 021179 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:36am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594140.7 | 509563.4 | 41151 | 1.64041666667 | 21179 |
| 019826 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:37am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594140.7 | 509563.4 | 41153 | 1.64041666667 | 19826 |
| 020092 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:38am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594140.5 | 509563.9 | 41155 | 1.64041666667 | 20092 |
| 020159 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:39am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.3 | 509563.8 | 41157 | 1.64041666667 | 20159 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 020144 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:40am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.3 | 509563.8 | 41159 | 1.64041666667 | 20144 |
| 019656 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:41am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.2 | 509563.7 | 41161 | 1.64041666667 | 19656 |
| 020619 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:42am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594139.8 | 509563.5 | 41163 | 1.64041666667 | 20619 |
| 020110 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:43am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.1 | 509563.8 | 41165 | 1.64041666667 | 20110 |
| 019479 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:44am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594139.8 | 509564.0 | 41167 | 1.64041666667 | 19479 |
| 019507 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:45am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594139.8 | 509564.0 | 41169 | 1.64041666667 | 19507 |
| 019605 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:46am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594140.0 | 509564.0 | 41171 | 1.64041666667 | 19605 |
| 019060 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:47am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594139.9 | 509564.6 | 41173 | 1.64041666667 | 19060 |
| 019616 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:48am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594140.1 | 509566.2 | 41175 | 1.64041666667 | 19616 |
| 018721 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:49am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594140.6 | 509568.1 | 41177 | 1.64041666667 | 18721 |
| 018233 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:50am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594141.5 | 509570.7 | 41179 | 1.64041666667 | 18233 |
| 018356 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:51am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594142.1 | 509573.4 | 41181 | 1.64041666667 | 18356 |
| 017953 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:52am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594142.9 | 509576.6 | 41183 | 1.64041666667 | 17953 |
| 017388 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:53am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594144.1 | 509578.7 | 41185 | 1.64041666667 | 17388 |
| 017086 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:54am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594145.5 | 509578.9 | 41187 | 1.64041666667 | 17086 |
| 016744 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:55am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594145.8 | 509578.8 | 41189 | 1.64041666667 | 16744 |
| 017853 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:56am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594146.1 | 509579.5 | 41191 | 1.64041666667 | 17853 |
| 017632 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:57am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594147.0 | 509580.8 | 41193 | 1.64041666667 | 17632 |
| 017800 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:58am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594147.2 | 509581.1 | 41195 | 1.64041666667 | 17800 |
| 018727 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:59am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594147.1 | 509581.2 | 41197 | 1.64041666667 | 18727 |
| 019361 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:00am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594147.1 | 509580.8 | 41199 | 1.64041666667 | 19361 |
| 019238 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:01am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594146.9 | 509579.8 | 41201 | 1.64041666667 | 19238 |
| 019379 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:02am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594146.0 | 509580.3 | 41203 | 1.64041666667 | 19379 |
| 018326 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:03am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594145.9 | 509582.1 | 41205 | 1.64041666667 | 18326 |
| 017816 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:04am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594145.8 | 509584.9 | 41207 | 1.64041666667 | 17816 |
| 017289 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:05am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594145.3 | 509586.8 | 41209 | 1.64041666667 | 17289 |
| 016392 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:06am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594143.7 | 509588.6 | 41211 | 1.64041666667 | 16392 |
| 016601 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:07am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594142.5 | 509590.5 | 41213 | 1.64041666667 | 16601 |
| 016380 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:08am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594140.9 | 509593.0 | 41215 | 1.64041666667 | 16380 |
| 016624 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:09am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594139.4 | 509595.0 | 41217 | 1.64041666667 | 16624 |
| 016791 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:10am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594138.9 | 509598.2 | 41219 | 1.64041666667 | 16791 |
| 016397 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:11am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594138.7 | 509600.7 | 41221 | 1.64041666667 | 16397 |
| 015741 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:12am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594138.3 | 509603.8 | 41223 | 1.64041666667 | 15741 |
| 016136 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:13am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594139.7 | 509605.5 | 41225 | 1.64041666667 | 16136 |
| 015962 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:14am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594141.1 | 509608.0 | 41227 | 1.64041666667 | 15962 |
| 014941 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:15am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594142.6 | 509610.1 | 41229 | 1.64041666667 | 14941 |
| 015124 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:16am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594144.7 | 509612.2 | 41231 | 1.64041666667 | 15124 |
| 015647 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:17am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594146.2 | 509614.3 | 41233 | 1.64041666667 | 15647 |
| 016031 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:18am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594148.4 | 509616.1 | 41235 | 1.64041666667 | 16031 |
| 015828 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:19am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594149.6 | 509618.0 | 41237 | 1.64041666667 | 15828 |
| 015465 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:20am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594150.9 | 509619.7 | 41239 | 1.64041666667 | 15465 |
| 015224 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:21am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594151.3 | 509620.2 | 41241 | 1.64041666667 | 15224 |
| 015868 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:22am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594151.3 | 509620.2 | 41243 | 1.64041666667 | 15868 |
| 016043 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:23am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594151.3 | 509620.3 | 41245 | 1.64041666667 | 16043 |
| 015362 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:24am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594151.3 | 509620.3 | 41247 | 1.64041666667 | 15362 |
| 015008 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:25am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594151.2 | 509620.3 | 41249 | 1.64041666667 | 15008 |
| 014614 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:26am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594151.9 | 509619.3 | 41251 | 1.64041666667 | 14614 |
| 015623 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:27am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594154.0 | 509617.8 | 41253 | 1.64041666667 | 15623 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015935 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:28am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594155.6 | 509615.4 | 41255 | 1.64041666667 | 15935 |
| 015466 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:29am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594157.1 | 509613.0 | 41257 | 1.64041666667 | 15466 |
| 016297 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:30am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.2 | 509610.2 | 41259 | 1.64041666667 | 16297 |
| 015399 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:31am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594159.3 | 509608.8 | 41261 | 1.64041666667 | 15399 |
| 014992 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:32am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.7 | 509608.0 | 41263 | 1.64041666667 | 14992 |
| 015460 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:33am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.6 | 509608.0 | 41265 | 1.64041666667 | 15460 |
| 015431 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:35am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.1 | 509608.1 | 41268 | 1.64041666667 | 15431 |
| 015205 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:35am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.1 | 509608.3 | 41269 | 1.64041666667 | 15205 |
| 015468 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:36am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.1 | 509608.3 | 41271 | 1.64041666667 | 15468 |
| 015383 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:37am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.1 | 509608.4 | 41273 | 1.64041666667 | 15383 |
| 014900 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:38am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594159.1 | 509608.4 | 41275 | 1.64041666667 | 14900 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:39am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594159.1 | 509608.4 | 41277 | 1.64041666667 | 14591 |
| 014702 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:40am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.1 | 509608.4 | 41279 | 1.64041666667 | 14702 |
| 014390 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:41am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.0 | 509608.3 | 41281 | 1.64041666667 | 14390 |
| 014694 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:42am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594159.0 | 509608.3 | 41283 | 1.64041666667 | 14694 |
| 016020 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:43am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594159.8 | 509607.8 | 41285 | 1.64041666667 | 16020 |
| 015656 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:44am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594160.4 | 509605.9 | 41287 | 1.64041666667 | 15656 |
| 015766 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:45am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594161.7 | 509603.5 | 41289 | 1.64041666667 | 15766 |
| 015161 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:46am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594162.8 | 509600.9 | 41291 | 1.64041666667 | 15161 |
| 015773 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:47am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594164.7 | 509599.3 | 41293 | 1.64041666667 | 15773 |
| 015405 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:48am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594167.8 | 509598.7 | 41295 | 1.64041666667 | 15405 |
| 016030 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:49am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594170.8 | 509597.9 | 41297 | 1.64041666667 | 16030 |
| 016284 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:50am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594173.9 | 509596.6 | 41299 | 1.64041666667 | 16284 |
| 017117 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:51am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594176.5 | 509596.3 | 41301 | 1.64041666667 | 17117 |
| 016993 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:52am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594179.4 | 509595.4 | 41303 | 1.64041666667 | 16993 |
| 018138 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:53am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594181.6 | 509594.6 | 41305 | 1.64041666667 | 18138 |
| 017718 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:54am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594184.5 | 509594.5 | 41307 | 1.64041666667 | 17718 |
| 017939 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:55am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594186.4 | 509593.8 | 41309 | 1.64041666667 | 17939 |
| 016975 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:56am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594188.8 | 509594.1 | 41311 | 1.64041666667 | 16975 |
| 016778 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:57am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594190.5 | 509593.2 | 41313 | 1.64041666667 | 16778 |
| 017800 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:58am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594192.9 | 509592.5 | 41315 | 1.64041666667 | 17800 |
| 017895 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:59am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594195.4 | 509591.8 | 41317 | 1.64041666667 | 17895 |
| 016013 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:00am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594198.1 | 509590.2 | 41319 | 1.64041666667 | 16013 |
| 015832 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:01am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594200.5 | 509589.8 | 41321 | 1.64041666667 | 15832 |
| 015168 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:02am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594203.4 | 509588.5 | 41323 | 1.64041666667 | 15168 |
| 014854 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:03am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594206.4 | 509587.3 | 41325 | 1.64041666667 | 14854 |
| 014880 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:04am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594209.9 | 509587.1 | 41327 | 1.64041666667 | 14880 |
| 015547 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:05am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594212.1 | 509586.6 | 41329 | 1.64041666667 | 15547 |
| 015338 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:06am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594215.5 | 509586.2 | 41331 | 1.64041666667 | 15338 |
| 015025 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:07am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594218.1 | 509586.2 | 41333 | 1.64041666667 | 15025 |
| 015741 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:08am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594221.1 | 509585.3 | 41335 | 1.64041666667 | 15741 |
| 015447 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:09am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594224.2 | 509584.7 | 41337 | 1.64041666667 | 15447 |
| 015199 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:10am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594227.2 | 509584.8 | 41339 | 1.64041666667 | 15199 |
| 015179 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:11am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594229.3 | 509584.2 | 41341 | 1.64041666667 | 15179 |
| 015146 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:12am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594232.0 | 509584.0 | 41343 | 1.64041666667 | 15146 |
| 014797 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:13am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594234.6 | 509583.8 | 41345 | 1.64041666667 | 14797 |
| 014878 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:14am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594237.6 | 509583.8 | 41347 | 1.64041666667 | 14878 |
| 014661 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:15am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594240.3 | 509585.0 | 41349 | 1.64041666667 | 14661 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015184 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:16am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594243.4 | 509586.6 | 41351 | 1.64041666667 | 15184 |
| 014474 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:17am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594245.8 | 509587.3 | 41353 | 1.64041666667 | 14474 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:18am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594248.4 | 509589.1 | 41355 | 1.64041666667 | 13631 |
| 013922 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:19am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594250.3 | 509590.4 | 41357 | 1.64041666667 | 13922 |
| 014791 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:20am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594252.8 | 509592.3 | 41359 | 1.64041666667 | 14791 |
| 014650 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:21am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594255.0 | 509593.8 | 41361 | 1.64041666667 | 14650 |
| 013925 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:22am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594258.4 | 509594.8 | 41363 | 1.64041666667 | 13925 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:23am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594261.1 | 509595.2 | 41365 | 1.64041666667 | 14081 |
| 013995 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:24am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594264.1 | 509596.4 | 41367 | 1.64041666667 | 13995 |
| 013925 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:25am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594266.8 | 509597.5 | 41369 | 1.64041666667 | 13925 |
| 014725 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:26am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594269.8 | 509598.4 | 41371 | 1.64041666667 | 14725 |
| 014853 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:27am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594271.5 | 509599.7 | 41373 | 1.64041666667 | 14853 |
| 013785 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:28am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594272.7 | 509600.1 | 41375 | 1.64041666667 | 13785 |
| 014174 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:29am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594272.9 | 509600.3 | 41377 | 1.64041666667 | 14174 |
| 013987 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:30am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594275.4 | 509600.2 | 41379 | 1.64041666667 | 13987 |
| 014123 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:31am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594278.4 | 509600.7 | 41381 | 1.64041666667 | 14123 |
| 013344 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:32am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594282.1 | 509601.4 | 41383 | 1.64041666667 | 13344 |
| 013566 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:33am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594284.8 | 509600.4 | 41385 | 1.64041666667 | 13566 |
| 013676 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:34am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594288.2 | 509599.0 | 41387 | 1.64041666667 | 13676 |
| 013497 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:35am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594290.9 | 509599.2 | 41389 | 1.64041666667 | 13497 |
| 014087 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:36am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594294.3 | 509599.3 | 41391 | 1.64041666667 | 14087 |
| 014359 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:37am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594297.5 | 509599.6 | 41393 | 1.64041666667 | 14359 |
| 014264 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:38am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594300.7 | 509601.0 | 41395 | 1.64041666667 | 14264 |
| 015006 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:39am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594303.4 | 509601.8 | 41397 | 1.64041666667 | 15006 |
| 014696 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:40am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594306.8 | 509602.2 | 41399 | 1.64041666667 | 14696 |
| 015489 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:41am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594309.5 | 509603.0 | 41401 | 1.64041666667 | 15489 |
| 015972 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:42am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594312.6 | 509603.7 | 41403 | 1.64041666667 | 15972 |
| 014219 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:43am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594315.5 | 509604.2 | 41405 | 1.64041666667 | 14219 |
| 014118 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:44am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594318.6 | 509605.0 | 41407 | 1.64041666667 | 14118 |
| 013874 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:45am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594321.6 | 509605.9 | 41409 | 1.64041666667 | 13874 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:46am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594324.9 | 509607.1 | 41411 | 1.64041666667 | 14591 |
| 015355 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:47am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594327.8 | 509608.8 | 41413 | 1.64041666667 | 15355 |
| 016347 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:48am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594330.9 | 509610.8 | 41415 | 1.64041666667 | 16347 |
| 015967 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:49am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594333.0 | 509611.6 | 41417 | 1.64041666667 | 15967 |
| 015199 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:50am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594335.9 | 509613.2 | 41419 | 1.64041666667 | 15199 |
| 015937 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:51am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594338.2 | 509614.7 | 41421 | 1.64041666667 | 15937 |
| 014964 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:52am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594341.3 | 509615.9 | 41423 | 1.64041666667 | 14964 |
| 013900 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:53am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594343.9 | 509616.9 | 41425 | 1.64041666667 | 13900 |
| 013323 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:54am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594347.2 | 509618.3 | 41427 | 1.64041666667 | 13323 |
| 013839 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:55am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594350.1 | 509618.8 | 41429 | 1.64041666667 | 13839 |
| 014452 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:56am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594353.6 | 509619.2 | 41431 | 1.64041666667 | 14452 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:57am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594356.3 | 509620.0 | 41433 | 1.64041666667 | 14092 |
| 014024 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:58am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594359.4 | 509620.5 | 41435 | 1.64041666667 | 14024 |
| 014358 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:59am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594362.3 | 509620.8 | 41437 | 1.64041666667 | 14358 |
| 014742 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:00am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594364.9 | 509622.2 | 41439 | 1.64041666667 | 14742 |
| 014322 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:01am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594367.3 | 509623.0 | 41441 | 1.64041666667 | 14322 |
| 014648 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:02am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594370.4 | 509623.1 | 41443 | 1.64041666667 | 14648 |
| 014615 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:03am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594373.1 | 509623.6 | 41445 | 1.64041666667 | 14615 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014820 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:04am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594376.4 | 509624.3 | 41447 | 1.64041666667 | 14820 |
| 015004 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:05am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594378.8 | 509624.2 | 41449 | 1.64041666667 | 15004 |
| 015452 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:06am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594381.5 | 509624.9 | 41451 | 1.64041666667 | 15452 |
| 015344 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:07am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594384.5 | 509625.6 | 41453 | 1.64041666667 | 15344 |
| 015486 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:08am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594387.4 | 509625.7 | 41455 | 1.64041666667 | 15486 |
| 015558 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:09am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594389.7 | 509626.1 | 41457 | 1.64041666667 | 15558 |
| 015351 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:10am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594391.4 | 509627.1 | 41459 | 1.64041666667 | 15351 |
| 015775 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:11am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594391.8 | 509627.1 | 41461 | 1.64041666667 | 15775 |
| 015053 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:12am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594392.3 | 509627.4 | 41463 | 1.64041666667 | 15053 |
| 015427 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:13am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594393.4 | 509627.0 | 41465 | 1.64041666667 | 15427 |
| 015398 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:14am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594394.7 | 509627.7 | 41467 | 1.64041666667 | 15398 |
| 015029 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:15am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.1 | 509627.5 | 41469 | 1.64041666667 | 15029 |
| 015653 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:16am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.2 | 509627.2 | 41471 | 1.64041666667 | 15653 |
| 016155 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:17am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.3 | 509627.1 | 41473 | 1.64041666667 | 16155 |
| 015957 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:18am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.2 | 509627.1 | 41475 | 1.64041666667 | 15957 |
| 015163 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:19am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.1 | 509627.1 | 41477 | 1.64041666667 | 15163 |
| 015864 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:20am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.1 | 509627.1 | 41479 | 1.64041666667 | 15864 |
| 015621 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:21am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.1 | 509627.1 | 41481 | 1.64041666667 | 15621 |
| 014937 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:22am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594395.2 | 509627.1 | 41483 | 1.64041666667 | 14937 |
| 014507 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:23am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594395.1 | 509627.1 | 41485 | 1.64041666667 | 14507 |
| 014625 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:24am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.2 | 509627.1 | 41487 | 1.64041666667 | 14625 |
| 015441 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:25am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.1 | 509627.0 | 41489 | 1.64041666667 | 15441 |
| 015346 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:26am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.1 | 509627.0 | 41491 | 1.64041666667 | 15346 |
| 015427 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:27am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.1 | 509627.0 | 41493 | 1.64041666667 | 15427 |
| 015690 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:28am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.2 | 509627.1 | 41495 | 1.64041666667 | 15690 |
| 015043 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:29am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.2 | 509627.0 | 41497 | 1.64041666667 | 15043 |
| 015279 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:30am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.3 | 509627.0 | 41499 | 1.64041666667 | 15279 |
| 015359 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:31am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594395.5 | 509627.0 | 41501 | 1.64041666667 | 15359 |
| 015660 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:32am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594397.4 | 509628.4 | 41503 | 1.64041666667 | 15660 |
| 015243 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:33am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594399.9 | 509628.9 | 41505 | 1.64041666667 | 15243 |
| 016224 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:34am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594403.4 | 509629.6 | 41507 | 1.64041666667 | 16224 |
| 016056 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:35am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594406.1 | 509630.7 | 41509 | 1.64041666667 | 16056 |
| 016366 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:36am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594409.6 | 509631.9 | 41511 | 1.64041666667 | 16366 |
| 016173 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:37am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594412.4 | 509632.3 | 41513 | 1.64041666667 | 16173 |
| 016447 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:38am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594415.6 | 509632.9 | 41515 | 1.64041666667 | 16447 |
| 015919 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:39am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594418.2 | 509633.3 | 41517 | 1.64041666667 | 15919 |
| 015247 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:40am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594421.5 | 509633.4 | 41519 | 1.64041666667 | 15247 |
| 016129 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:41am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594423.7 | 509634.4 | 41521 | 1.64041666667 | 16129 |
| 015312 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:42am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594426.6 | 509635.2 | 41523 | 1.64041666667 | 15312 |
| 015536 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:43am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594429.3 | 509635.6 | 41525 | 1.64041666667 | 15536 |
| 016471 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:44am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594432.1 | 509637.0 | 41527 | 1.64041666667 | 16471 |
| 016637 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:45am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594434.9 | 509637.6 | 41529 | 1.64041666667 | 16637 |
| 017556 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:46am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594438.2 | 509637.8 | 41531 | 1.64041666667 | 17556 |
| 017473 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:47am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594441.0 | 509638.4 | 41533 | 1.64041666667 | 17473 |
| 015753 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:48am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594444.4 | 509639.3 | 41535 | 1.64041666667 | 15753 |
| 015438 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:49am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594447.1 | 509639.0 | 41537 | 1.64041666667 | 15438 |
| 014647 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:50am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594450.0 | 509639.8 | 41539 | 1.64041666667 | 14647 |
| 013481 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:51am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594452.7 | 509640.6 | 41541 | 1.64041666667 | 13481 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:52am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594455.7 | 509640.4 | 41543 | 1.64041666667 | 13320 |
| 013650 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:53am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594458.0 | 509641.0 | 41545 | 1.64041666667 | 13650 |
| 013430 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:54am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594460.9 | 509640.9 | 41547 | 1.64041666667 | 13430 |
| 013705 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:55am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594463.0 | 509639.6 | 41549 | 1.64041666667 | 13705 |
| 014916 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:56am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594465.7 | 509638.5 | 41551 | 1.64041666667 | 14916 |
| 014623 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:57am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594467.5 | 509637.1 | 41553 | 1.64041666667 | 14623 |
| 014195 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:58am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594470.0 | 509636.5 | 41555 | 1.64041666667 | 14195 |
| 014359 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:59am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594472.0 | 509635.8 | 41557 | 1.64041666667 | 14359 |
| 014977 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:00am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594474.9 | 509635.2 | 41559 | 1.64041666667 | 14977 |
| 015947 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:01am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594477.3 | 509635.2 | 41561 | 1.64041666667 | 15947 |
| 015420 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:02am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594479.8 | 509634.6 | 41563 | 1.64041666667 | 15420 |
| 015363 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:03am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594481.9 | 509635.3 | 41565 | 1.64041666667 | 15363 |
| 015962 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:04am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594484.4 | 509635.6 | 41567 | 1.64041666667 | 15962 |
| 015923 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:05am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594486.2 | 509636.5 | 41569 | 1.64041666667 | 15923 |
| 016509 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:06am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594488.8 | 509637.6 | 41571 | 1.64041666667 | 16509 |
| 016411 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:07am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594491.4 | 509637.8 | 41573 | 1.64041666667 | 16411 |
| 016446 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:08am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594493.8 | 509639.0 | 41575 | 1.64041666667 | 16446 |
| 017801 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:09am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594496.2 | 509639.0 | 41577 | 1.64041666667 | 17801 |
| 017610 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:10am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594497.9 | 509639.9 | 41579 | 1.64041666667 | 17610 |
| 018786 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:11am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594498.3 | 509639.7 | 41581 | 1.64041666667 | 18786 |
| 019544 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:12am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594498.4 | 509639.6 | 41583 | 1.64041666667 | 19544 |
| 019394 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:13am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594498.4 | 509639.7 | 41585 | 1.64041666667 | 19394 |
| 018754 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:14am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594498.5 | 509639.9 | 41587 | 1.64041666667 | 18754 |
| 018341 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:15am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594498.5 | 509639.6 | 41589 | 1.64041666667 | 18341 |
| 018867 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:16am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594498.7 | 509638.3 | 41591 | 1.64041666667 | 18867 |
| 018615 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:17am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594498.2 | 509638.5 | 41593 | 1.64041666667 | 18615 |
| 018271 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:18am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594497.3 | 509638.7 | 41595 | 1.64041666667 | 18271 |
| 017537 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:19am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594496.3 | 509638.4 | 41597 | 1.64041666667 | 17537 |
| 017380 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:20am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594496.3 | 509638.6 | 41599 | 1.64041666667 | 17380 |
| 017673 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:21am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594497.0 | 509639.5 | 41601 | 1.64041666667 | 17673 |
| 018513 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:22am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594498.4 | 509641.3 | 41603 | 1.64041666667 | 18513 |
| 018971 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:23am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594499.9 | 509641.5 | 41605 | 1.64041666667 | 18971 |
| 019499 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:24am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594501.6 | 509642.7 | 41607 | 1.64041666667 | 19499 |
| 018903 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:25am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594503.1 | 509643.0 | 41609 | 1.64041666667 | 18903 |
| 018350 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:26am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594505.0 | 509644.1 | 41611 | 1.64041666667 | 18350 |
| 017334 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:27am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594507.0 | 509644.7 | 41613 | 1.64041666667 | 17334 |
| 016680 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:28am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594509.6 | 509644.8 | 41615 | 1.64041666667 | 16680 |
| 017385 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:29am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594511.8 | 509645.5 | 41617 | 1.64041666667 | 17385 |
| 017511 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:30am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594514.2 | 509645.4 | 41619 | 1.64041666667 | 17511 |
| 016840 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:31am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594516.3 | 509645.9 | 41621 | 1.64041666667 | 16840 |
| 018600 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:32am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594518.6 | 509645.9 | 41623 | 1.64041666667 | 18600 |
| 018142 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:33am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594520.3 | 509646.1 | 41625 | 1.64041666667 | 18142 |
| 017960 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:34am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594522.5 | 509645.9 | 41627 | 1.64041666667 | 17960 |
| 017040 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:35am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594523.9 | 509645.7 | 41629 | 1.64041666667 | 17040 |
| 016005 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:36am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594525.5 | 509645.7 | 41631 | 1.64041666667 | 16005 |
| 016188 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:37am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594526.2 | 509645.6 | 41633 | 1.64041666667 | 16188 |
| 015705 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:38am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594526.5 | 509645.2 | 41635 | 1.64041666667 | 15705 |
| 016192 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:39am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594526.4 | 509644.9 | 41637 | 1.64041666667 | 16192 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016263 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:40am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594526.4 | 509644.9 | 41639 | 1.64041666667 | 16263 |
| 016505 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:41am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594526.6 | 509644.8 | 41641 | 1.64041666667 | 16505 |
| 016319 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:42am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594526.2 | 509645.1 | 41643 | 1.64041666667 | 16319 |
| 015562 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:43am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594525.2 | 509645.6 | 41645 | 1.64041666667 | 15562 |
| 015323 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:44am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594522.8 | 509645.8 | 41647 | 1.64041666667 | 15323 |
| 016554 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:45am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594520.2 | 509645.7 | 41649 | 1.64041666667 | 16554 |
| 017082 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:46am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594516.8 | 509645.6 | 41651 | 1.64041666667 | 17082 |
| 017806 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:47am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594514.0 | 509646.1 | 41653 | 1.64041666667 | 17806 |
| 017178 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:48am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594511.0 | 509646.5 | 41655 | 1.64041666667 | 17178 |
| 016135 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:49am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594508.9 | 509646.6 | 41657 | 1.64041666667 | 16135 |
| 015833 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:50am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594506.4 | 509647.6 | 41659 | 1.64041666667 | 15833 |
| 015776 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:51am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594505.6 | 509648.9 | 41661 | 1.64041666667 | 15776 |
| 015181 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:52am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594504.0 | 509650.2 | 41663 | 1.64041666667 | 15181 |
| 016204 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:53am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594503.0 | 509652.2 | 41665 | 1.64041666667 | 16204 |
| 015325 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:54am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594502.4 | 509654.0 | 41667 | 1.64041666667 | 15325 |
| 015603 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:55am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594502.0 | 509656.0 | 41669 | 1.64041666667 | 15603 |
| 015144 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:56am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594502.5 | 509658.6 | 41671 | 1.64041666667 | 15144 |
| 014841 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:57am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594502.6 | 509661.1 | 41673 | 1.64041666667 | 14841 |
| 015233 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:58am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594502.5 | 509663.4 | 41675 | 1.64041666667 | 15233 |
| 015363 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:59am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594502.6 | 509665.1 | 41677 | 1.64041666667 | 15363 |
| 014957 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:00am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594501.3 | 509666.3 | 41679 | 1.64041666667 | 14957 |
| 015395 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:01am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594500.2 | 509667.9 | 41681 | 1.64041666667 | 15395 |
| 014240 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:02am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594498.1 | 509668.9 | 41683 | 1.64041666667 | 14240 |
| 015007 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:03am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594496.3 | 509670.0 | 41685 | 1.64041666667 | 15007 |
| 013999 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:04am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594494.1 | 509670.8 | 41687 | 1.64041666667 | 13999 |
| 014129 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:05am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594491.5 | 509671.5 | 41689 | 1.64041666667 | 14129 |
| 014345 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:06am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594489.2 | 509673.0 | 41691 | 1.64041666667 | 14345 |
| 015209 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:07am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594487.1 | 509673.4 | 41693 | 1.64041666667 | 15209 |
| 015665 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:08am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594484.7 | 509674.4 | 41695 | 1.64041666667 | 15665 |
| 015569 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:09am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594483.2 | 509675.5 | 41697 | 1.64041666667 | 15569 |
| 016220 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:10am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594482.0 | 509677.6 | 41699 | 1.64041666667 | 16220 |
| 016226 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:11am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594481.6 | 509679.8 | 41701 | 1.64041666667 | 16226 |
| 015090 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:12am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594480.4 | 509680.9 | 41703 | 1.64041666667 | 15090 |
| 014923 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:13am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594480.8 | 509681.1 | 41705 | 1.64041666667 | 14923 |
| 014799 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:14am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594481.1 | 509681.2 | 41707 | 1.64041666667 | 14799 |
| 015757 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:15am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594481.1 | 509681.1 | 41709 | 1.64041666667 | 15757 |
| 015275 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:16am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594481.1 | 509681.1 | 41711 | 1.64041666667 | 15275 |
| 015170 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:17am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594481.2 | 509681.0 | 41713 | 1.64041666667 | 15170 |
| 015208 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:18am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594481.2 | 509680.9 | 41715 | 1.64041666667 | 15208 |
| 016399 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:19am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594481.2 | 509681.0 | 41717 | 1.64041666667 | 16399 |
| 016020 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:20am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594481.2 | 509681.0 | 41719 | 1.64041666667 | 16020 |
| 015483 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:21am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594481.2 | 509680.9 | 41721 | 1.64041666667 | 15483 |
| 015377 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:22am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594481.2 | 509681.0 | 41723 | 1.64041666667 | 15377 |
| 015084 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:23am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594481.1 | 509681.0 | 41725 | 1.64041666667 | 15084 |
| 015385 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:24am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594480.4 | 509681.1 | 41727 | 1.64041666667 | 15385 |
| 015801 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:25am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594479.4 | 509682.7 | 41729 | 1.64041666667 | 15801 |
| 015578 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:26am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594477.8 | 509684.0 | 41731 | 1.64041666667 | 15578 |
| 018663 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:27am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594476.6 | 509685.8 | 41733 | 1.64041666667 | 18663 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017592 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:28am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594474.8 | 509687.4 | 41735 | 1.64041666667 | 17592 |
| 017726 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:29am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594473.3 | 509689.5 | 41737 | 1.64041666667 | 17726 |
| 016541 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:30am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594472.4 | 509691.6 | 41739 | 1.64041666667 | 16541 |
| 015784 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:31am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594470.4 | 509693.1 | 41741 | 1.64041666667 | 15784 |
| 015441 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:32am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594468.4 | 509695.2 | 41743 | 1.64041666667 | 15441 |
| 015720 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:33am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594467.2 | 509696.9 | 41745 | 1.64041666667 | 15720 |
| 015367 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:34am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594466.3 | 509699.6 | 41747 | 1.64041666667 | 15367 |
| 015034 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:35am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594466.5 | 509701.6 | 41749 | 1.64041666667 | 15034 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:36am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594465.8 | 509704.2 | 41751 | 1.64041666667 | 14111 |
| 013975 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:37am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594465.8 | 509706.4 | 41753 | 1.64041666667 | 13975 |
| 013988 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:38am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594465.8 | 509709.0 | 41755 | 1.64041666667 | 13988 |
| 014993 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:39am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594465.5 | 509711.8 | 41757 | 1.64041666667 | 14993 |
| 014238 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:40am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594465.8 | 509714.1 | 41759 | 1.64041666667 | 14238 |
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:41am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594465.1 | 509716.0 | 41761 | 1.64041666667 | 14227 |
| 013515 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:42am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594464.8 | 509718.3 | 41763 | 1.64041666667 | 13515 |
| 013977 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:43am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594463.9 | 509720.4 | 41765 | 1.64041666667 | 13977 |
| 013202 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:44am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594463.8 | 509722.8 | 41767 | 1.64041666667 | 13202 |
| 013568 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:45am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594463.5 | 509725.0 | 41769 | 1.64041666667 | 13568 |
| 013489 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:46am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594462.8 | 509727.8 | 41771 | 1.64041666667 | 13489 |
| 012178 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:47am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594463.0 | 509729.9 | 41773 | 1.64041666667 | 12178 |
| 011627 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:48am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594461.8 | 509732.0 | 41775 | 1.64041666667 | 11627 |
| 012465 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:49am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594461.3 | 509734.1 | 41777 | 1.64041666667 | 12465 |
| 012787 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:50am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594460.7 | 509736.6 | 41779 | 1.64041666667 | 12787 |
| 012697 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:51am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594460.0 | 509739.4 | 41781 | 1.64041666667 | 12697 |
| 012685 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:52am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594459.8 | 509741.9 | 41783 | 1.64041666667 | 12685 |
| 012790 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:53am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594458.9 | 509744.1 | 41785 | 1.64041666667 | 12790 |
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:54am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594458.2 | 509746.2 | 41787 | 1.64041666667 | 13277 |
| 013483 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:55am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594457.2 | 509747.5 | 41789 | 1.64041666667 | 13483 |
| 012879 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:56am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594457.1 | 509749.1 | 41791 | 1.64041666667 | 12879 |
| 013034 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:57am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594456.7 | 509750.8 | 41793 | 1.64041666667 | 13034 |
| 013047 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:58am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594457.2 | 509752.7 | 41795 | 1.64041666667 | 13047 |
| 013406 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:59am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594457.1 | 509754.5 | 41797 | 1.64041666667 | 13406 |
| 013158 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:00am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594458.0 | 509755.3 | 41799 | 1.64041666667 | 13158 |
| 012719 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:01am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594459.4 | 509755.4 | 41801 | 1.64041666667 | 12719 |
| 012232 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:02am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594461.2 | 509754.6 | 41803 | 1.64041666667 | 12232 |
| 012903 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:03am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594462.6 | 509752.9 | 41805 | 1.64041666667 | 12903 |
| 013280 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:04am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594464.8 | 509751.3 | 41807 | 1.64041666667 | 13280 |
| 013207 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:05am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594466.2 | 509749.4 | 41809 | 1.64041666667 | 13207 |
| 013714 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:06am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594468.3 | 509747.9 | 41811 | 1.64041666667 | 13714 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:07am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594468.9 | 509746.2 | 41813 | 1.64041666667 | 14111 |
| 014350 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:08am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594470.0 | 509744.2 | 41815 | 1.64041666667 | 14350 |
| 014169 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:09am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594471.6 | 509742.4 | 41817 | 1.64041666667 | 14169 |
| 013340 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:10am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594472.8 | 509740.1 | 41819 | 1.64041666667 | 13340 |
| 013871 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:11am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594474.7 | 509738.2 | 41821 | 1.64041666667 | 13871 |
| 014185 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:12am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594476.0 | 509736.1 | 41823 | 1.64041666667 | 14185 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:13am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594477.6 | 509734.6 | 41825 | 1.64041666667 | 14324 |
| 014342 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:14am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594479.1 | 509732.3 | 41827 | 1.64041666667 | 14342 |
| 014150 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:15am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594479.8 | 509729.8 | 41829 | 1.64041666667 | 14150 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014477 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:16am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594481.3 | 509727.2 | 41831 | 1.64041666667 | 14477 |
| 015095 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:17am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594481.7 | 509725.2 | 41833 | 1.64041666667 | 15095 |
| 014859 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:18am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594483.1 | 509722.9 | 41835 | 1.64041666667 | 14859 |
| 014605 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:19am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594484.1 | 509720.9 | 41837 | 1.64041666667 | 14605 |
| 016615 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:20am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594485.2 | 509718.6 | 41839 | 1.64041666667 | 16615 |
| 015878 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:21am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594486.9 | 509717.3 | 41841 | 1.64041666667 | 15878 |
| 015044 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:22am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594488.1 | 509715.4 | 41843 | 1.64041666667 | 15044 |
| 015047 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:23am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594489.6 | 509714.9 | 41845 | 1.64041666667 | 15047 |
| 015364 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:24am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594491.0 | 509713.6 | 41847 | 1.64041666667 | 15364 |
| 015354 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:25am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594493.2 | 509712.2 | 41849 | 1.64041666667 | 15354 |
| 015919 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:26am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594493.9 | 509709.8 | 41851 | 1.64041666667 | 15919 |
| 015847 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:27am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594494.7 | 509707.5 | 41853 | 1.64041666667 | 15847 |
| 015356 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:28am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594496.2 | 509704.8 | 41855 | 1.64041666667 | 15356 |
| 015628 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:29am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594496.6 | 509702.8 | 41857 | 1.64041666667 | 15628 |
| 015608 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:30am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594497.9 | 509700.6 | 41859 | 1.64041666667 | 15608 |
| 015799 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:31am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594498.3 | 509698.3 | 41861 | 1.64041666667 | 15799 |
| 015060 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:32am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594499.1 | 509695.9 | 41863 | 1.64041666667 | 15060 |
| 014501 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:33am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594500.4 | 509693.4 | 41865 | 1.64041666667 | 14501 |
| 014659 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:34am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594501.2 | 509690.8 | 41867 | 1.64041666667 | 14659 |
| 014561 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:35am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594502.6 | 509688.9 | 41869 | 1.64041666667 | 14561 |
| 014790 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:36am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594503.4 | 509686.3 | 41871 | 1.64041666667 | 14790 |
| 015377 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:37am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594504.4 | 509684.3 | 41873 | 1.64041666667 | 15377 |
| 013787 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:38am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594505.8 | 509681.7 | 41875 | 1.64041666667 | 13787 |
| 014032 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:39am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594506.1 | 509679.5 | 41877 | 1.64041666667 | 14032 |
| 013998 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:40am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594507.2 | 509677.2 | 41879 | 1.64041666667 | 13998 |
| 013754 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:41am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594507.2 | 509675.2 | 41881 | 1.64041666667 | 13754 |
| 014794 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:42am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594508.3 | 509673.0 | 41883 | 1.64041666667 | 14794 |
| 015191 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:43am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594508.9 | 509670.7 | 41885 | 1.64041666667 | 15191 |
| 015212 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:44am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594509.5 | 509668.3 | 41887 | 1.64041666667 | 15212 |
| 015412 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:45am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594510.6 | 509666.9 | 41889 | 1.64041666667 | 15412 |
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:46am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594511.1 | 509665.2 | 41891 | 1.64041666667 | 14819 |
| 014711 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:47am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594511.9 | 509664.6 | 41893 | 1.64041666667 | 14711 |
| 015595 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:48am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594513.4 | 509663.6 | 41895 | 1.64041666667 | 15595 |
| 015259 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:49am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594514.8 | 509664.3 | 41897 | 1.64041666667 | 15259 |
| 015318 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:50am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594516.3 | 509664.9 | 41899 | 1.64041666667 | 15318 |
| 015681 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:51am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594517.0 | 509666.3 | 41901 | 1.64041666667 | 15681 |
| 015360 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:52am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594518.3 | 509667.8 | 41903 | 1.64041666667 | 15360 |
| 015893 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:53am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594519.6 | 509668.6 | 41905 | 1.64041666667 | 15893 |
| 015052 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:54am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594520.7 | 509669.3 | 41907 | 1.64041666667 | 15052 |
| 015067 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:55am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594521.2 | 509670.1 | 41909 | 1.64041666667 | 15067 |
| 015742 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:56am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594520.4 | 509671.5 | 41911 | 1.64041666667 | 15742 |
| 015380 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:57am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594519.6 | 509673.4 | 41913 | 1.64041666667 | 15380 |
| 015866 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:58am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594517.8 | 509674.9 | 41915 | 1.64041666667 | 15866 |
| 015825 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:59am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594516.6 | 509676.8 | 41917 | 1.64041666667 | 15825 |
| 015996 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:00am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594515.2 | 509679.0 | 41919 | 1.64041666667 | 15996 |
| 015433 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:01am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594513.3 | 509681.4 | 41921 | 1.64041666667 | 15433 |
| 015281 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:02am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594512.6 | 509683.9 | 41923 | 1.64041666667 | 15281 |
| 015645 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:03am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594511.0 | 509685.7 | 41925 | 1.64041666667 | 15645 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015475 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:04am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594509.9 | 509688.1 | 41927 | 1.64041666667 | 15475 |
| 014600 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:05am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594508.0 | 509689.5 | 41929 | 1.64041666667 | 14600 |
| 014190 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:06am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594505.7 | 509691.5 | 41931 | 1.64041666667 | 14190 |
| 014116 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:07am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594504.8 | 509693.5 | 41933 | 1.64041666667 | 14116 |
| 014135 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:08am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594502.6 | 509695.4 | 41935 | 1.64041666667 | 14135 |
| 014731 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:09am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594501.5 | 509697.2 | 41937 | 1.64041666667 | 14731 |
| 016004 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:10am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594500.2 | 509699.3 | 41939 | 1.64041666667 | 16004 |
| 016794 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:11am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594499.5 | 509701.6 | 41941 | 1.64041666667 | 16794 |
| 015439 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:12am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594500.0 | 509704.0 | 41943 | 1.64041666667 | 15439 |
| 014842 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:13am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594499.5 | 509706.6 | 41945 | 1.64041666667 | 14842 |
| 014393 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:14am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594499.4 | 509709.0 | 41947 | 1.64041666667 | 14393 |
| 014838 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:15am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594499.0 | 509710.5 | 41949 | 1.64041666667 | 14838 |
| 014632 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:16am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594498.8 | 509711.9 | 41951 | 1.64041666667 | 14632 |
| 015243 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:17am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594498.5 | 509712.4 | 41953 | 1.64041666667 | 15243 |
| 015781 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:18am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594498.6 | 509713.1 | 41955 | 1.64041666667 | 15781 |
| 014667 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:19am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594498.2 | 509714.7 | 41957 | 1.64041666667 | 14667 |
| 014512 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:20am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594497.7 | 509717.2 | 41959 | 1.64041666667 | 14512 |
| 014883 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:21am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594496.8 | 509719.7 | 41961 | 1.64041666667 | 14883 |
| 016044 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:22am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594495.1 | 509722.5 | 41963 | 1.64041666667 | 16044 |
| 015302 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:23am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594494.6 | 509724.6 | 41965 | 1.64041666667 | 15302 |
| 014862 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:24am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594493.5 | 509727.1 | 41967 | 1.64041666667 | 14862 |
| 015012 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:25am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594492.5 | 509729.5 | 41969 | 1.64041666667 | 15012 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:26am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594491.8 | 509732.0 | 41971 | 1.64041666667 | 14092 |
| 014032 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:27am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594490.6 | 509733.7 | 41973 | 1.64041666667 | 14032 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:28am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594489.6 | 509735.8 | 41975 | 1.64041666667 | 13953 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:29am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594488.3 | 509737.9 | 41977 | 1.64041666667 | 14283 |
| 015062 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:30am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594487.2 | 509740.4 | 41979 | 1.64041666667 | 15062 |
| 015589 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:31am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594486.2 | 509742.0 | 41981 | 1.64041666667 | 15589 |
| 015354 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:32am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594485.4 | 509742.4 | 41983 | 1.64041666667 | 15354 |
| 015131 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:33am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594486.2 | 509742.1 | 41985 | 1.64041666667 | 15131 |
| 014856 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:34am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594486.5 | 509742.0 | 41987 | 1.64041666667 | 14856 |
| 013891 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:35am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594486.5 | 509741.9 | 41989 | 1.64041666667 | 13891 |
| 013701 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:36am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594486.5 | 509741.9 | 41991 | 1.64041666667 | 13701 |
| 014614 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:37am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594486.5 | 509741.9 | 41993 | 1.64041666667 | 14614 |
| 014940 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:38am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594486.4 | 509741.9 | 41995 | 1.64041666667 | 14940 |
| 014306 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:39am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594486.4 | 509741.9 | 41997 | 1.64041666667 | 14306 |
| 014235 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:40am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594485.8 | 509742.2 | 41999 | 1.64041666667 | 14235 |
| 014719 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:41am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594485.1 | 509743.8 | 42001 | 1.64041666667 | 14719 |
| 014332 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:42am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594483.8 | 509746.2 | 42003 | 1.64041666667 | 14332 |
| 014857 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:43am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594482.2 | 509747.8 | 42005 | 1.64041666667 | 14857 |
| 015152 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:44am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594480.8 | 509750.1 | 42007 | 1.64041666667 | 15152 |
| 014935 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:45am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594479.3 | 509752.2 | 42009 | 1.64041666667 | 14935 |
| 014461 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:46am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594477.0 | 509754.8 | 42011 | 1.64041666667 | 14461 |
| 014471 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:47am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594476.0 | 509757.1 | 42013 | 1.64041666667 | 14471 |
| 014148 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:48am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594474.0 | 509759.5 | 42015 | 1.64041666667 | 14148 |
| 013838 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:49am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594472.2 | 509761.8 | 42017 | 1.64041666667 | 13838 |
| 012689 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:50am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594470.6 | 509764.2 | 42019 | 1.64041666667 | 12689 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:51am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594468.7 | 509765.7 | 42021 | 1.64041666667 | 12785 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012486 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:52am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594467.4 | 509768.0 | 42023 | 1.64041666667 | 12486 |
| 012896 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:53am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594466.1 | 509769.5 | 42025 | 1.64041666667 | 12896 |
| 012481 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:54am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594466.9 | 509771.3 | 42027 | 1.64041666667 | 12481 |
| 012870 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:55am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594468.4 | 509772.9 | 42029 | 1.64041666667 | 12870 |
| 012880 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:56am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594470.0 | 509775.2 | 42031 | 1.64041666667 | 12880 |
| 013125 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:57am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594471.5 | 509776.2 | 42033 | 1.64041666667 | 13125 |
| 012625 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:58am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594473.2 | 509778.0 | 42035 | 1.64041666667 | 12625 |
| 012989 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:59am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594475.0 | 509778.8 | 42037 | 1.64041666667 | 12989 |
| 012819 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:00am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594476.9 | 509780.2 | 42039 | 1.64041666667 | 12819 |
| 012715 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:01am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594478.8 | 509779.6 | 42041 | 1.64041666667 | 12715 |
| 012522 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:02am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594480.9 | 509777.9 | 42043 | 1.64041666667 | 12522 |
| 014079 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:03am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594482.5 | 509776.3 | 42045 | 1.64041666667 | 14079 |
| 013199 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:04am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594483.5 | 509774.3 | 42047 | 1.64041666667 | 13199 |
| 013162 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:05am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594484.6 | 509772.8 | 42049 | 1.64041666667 | 13162 |
| 013126 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:06am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594485.3 | 509770.5 | 42051 | 1.64041666667 | 13126 |
| 012941 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:07am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594485.7 | 509768.1 | 42053 | 1.64041666667 | 12941 |
| 013414 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:08am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594486.9 | 509765.7 | 42055 | 1.64041666667 | 13414 |
| 013450 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:09am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594487.3 | 509763.7 | 42057 | 1.64041666667 | 13450 |
| 013315 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:10am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594488.6 | 509761.4 | 42059 | 1.64041666667 | 13315 |
| 012837 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:11am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594489.1 | 509759.5 | 42061 | 1.64041666667 | 12837 |
| 013033 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:12am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594490.6 | 509757.6 | 42063 | 1.64041666667 | 13033 |
| 012438 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:13am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594492.1 | 509756.3 | 42065 | 1.64041666667 | 12438 |
| 012562 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:14am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594493.8 | 509754.1 | 42067 | 1.64041666667 | 12562 |
| 012841 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:15am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594495.6 | 509752.9 | 42069 | 1.64041666667 | 12841 |
| 013508 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:16am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594496.6 | 509750.6 | 42071 | 1.64041666667 | 13508 |
| 013538 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:17am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594498.1 | 509749.0 | 42073 | 1.64041666667 | 13538 |
| 014965 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:18am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594499.8 | 509746.9 | 42075 | 1.64041666667 | 14965 |
| 014838 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:19am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594500.8 | 509744.8 | 42077 | 1.64041666667 | 14838 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:20am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594502.5 | 509743.1 | 42079 | 1.64041666667 | 14324 |
| 014957 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:21am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594503.5 | 509741.1 | 42081 | 1.64041666667 | 14957 |
| 015088 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:22am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594505.1 | 509739.4 | 42083 | 1.64041666667 | 15088 |
| 014629 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:23am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594506.3 | 509737.3 | 42085 | 1.64041666667 | 14629 |
| 014716 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:24am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594507.7 | 509734.9 | 42087 | 1.64041666667 | 14716 |
| 014645 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:25am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594509.2 | 509733.1 | 42089 | 1.64041666667 | 14645 |
| 014673 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:26am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594510.1 | 509730.9 | 42091 | 1.64041666667 | 14673 |
| 015581 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:27am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594511.7 | 509729.1 | 42093 | 1.64041666667 | 15581 |
| 015491 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:28am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594512.8 | 509726.8 | 42095 | 1.64041666667 | 15491 |
| 015539 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:29am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594513.7 | 509724.5 | 42097 | 1.64041666667 | 15539 |
| 015280 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:30am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594515.2 | 509722.3 | 42099 | 1.64041666667 | 15280 |
| 015502 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:31am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594515.6 | 509719.8 | 42101 | 1.64041666667 | 15502 |
| 015222 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:32am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594516.6 | 509717.3 | 42103 | 1.64041666667 | 15222 |
| 014825 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:33am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594517.2 | 509715.4 | 42105 | 1.64041666667 | 14825 |
| 015314 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:34am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594518.2 | 509713.1 | 42107 | 1.64041666667 | 15314 |
| 015581 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:35am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594519.4 | 509711.4 | 42109 | 1.64041666667 | 15581 |
| 015664 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:36am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594520.2 | 509709.1 | 42111 | 1.64041666667 | 15664 |
| 015411 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:37am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594521.6 | 509707.3 | 42113 | 1.64041666667 | 15411 |
| 015216 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:38am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594522.6 | 509704.9 | 42115 | 1.64041666667 | 15216 |
| 015012 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:39am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594523.6 | 509703.0 | 42117 | 1.64041666667 | 15012 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015882 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:40am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594525.1 | 509700.1 | 42119 | 1.64041666667 | 15882 |
| 015489 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:41am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594525.4 | 509698.2 | 42121 | 1.64041666667 | 15489 |
| 016400 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:42am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594526.8 | 509696.0 | 42123 | 1.64041666667 | 16400 |
| 016155 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:43am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594527.3 | 509694.1 | 42125 | 1.64041666667 | 16155 |
| 016137 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:44am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594528.8 | 509692.0 | 42127 | 1.64041666667 | 16137 |
| 015039 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:45am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594529.9 | 509690.0 | 42129 | 1.64041666667 | 15039 |
| 014842 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:46am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594531.1 | 509688.4 | 42131 | 1.64041666667 | 14842 |
| 015301 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:47am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594532.3 | 509686.8 | 42133 | 1.64041666667 | 15301 |
| 016009 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:48am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594533.9 | 509685.0 | 42135 | 1.64041666667 | 16009 |
| 015650 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:49am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594535.3 | 509683.2 | 42137 | 1.64041666667 | 15650 |
| 015043 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:50am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594536.2 | 509680.9 | 42139 | 1.64041666667 | 15043 |
| 015677 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:51am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594537.8 | 509679.2 | 42141 | 1.64041666667 | 15677 |
| 015058 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:52am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594538.9 | 509676.8 | 42143 | 1.64041666667 | 15058 |
| 015340 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:53am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594539.9 | 509674.7 | 42145 | 1.64041666667 | 15340 |
| 015746 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:54am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594541.3 | 509672.9 | 42147 | 1.64041666667 | 15746 |
| 015577 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:55am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594542.0 | 509671.1 | 42149 | 1.64041666667 | 15577 |
| 015444 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:56am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594543.3 | 509671.1 | 42151 | 1.64041666667 | 15444 |
| 015647 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:57am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594544.9 | 509670.8 | 42153 | 1.64041666667 | 15647 |
| 015754 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:58am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594546.4 | 509671.6 | 42155 | 1.64041666667 | 15754 |
| 015064 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:59am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594547.9 | 509671.8 | 42157 | 1.64041666667 | 15064 |
| 014781 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:00am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594549.0 | 509672.5 | 42159 | 1.64041666667 | 14781 |
| 014599 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:01am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594549.9 | 509673.7 | 42161 | 1.64041666667 | 14599 |
| 014962 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:02am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594549.3 | 509675.5 | 42163 | 1.64041666667 | 14962 |
| 015248 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:03am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594548.3 | 509677.2 | 42165 | 1.64041666667 | 15248 |
| 015394 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:04am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594547.1 | 509679.6 | 42167 | 1.64041666667 | 15394 |
| 015109 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:05am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.7 | 509680.9 | 42169 | 1.64041666667 | 15109 |
| 015414 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:06am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594544.6 | 509683.1 | 42171 | 1.64041666667 | 15414 |
| 014730 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:07am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594543.1 | 509684.5 | 42173 | 1.64041666667 | 14730 |
| 014270 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:08am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594541.6 | 509686.5 | 42175 | 1.64041666667 | 14270 |
| 014492 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:09am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594540.3 | 509688.2 | 42177 | 1.64041666667 | 14492 |
| 014902 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:10am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.3 | 509690.0 | 42179 | 1.64041666667 | 14902 |
| 015552 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:11am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594537.3 | 509691.8 | 42181 | 1.64041666667 | 15552 |
| 016218 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:12am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.5 | 509693.7 | 42183 | 1.64041666667 | 16218 |
| 015685 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:13am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594534.2 | 509695.7 | 42185 | 1.64041666667 | 15685 |
| 016000 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:14am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594532.3 | 509697.6 | 42187 | 1.64041666667 | 16000 |
| 016732 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:15am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594530.7 | 509699.0 | 42189 | 1.64041666667 | 16732 |
| 016304 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:16am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594529.2 | 509701.2 | 42191 | 1.64041666667 | 16304 |
| 015966 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:17am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594527.2 | 509702.8 | 42193 | 1.64041666667 | 15966 |
| 016053 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:18am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594525.4 | 509704.7 | 42195 | 1.64041666667 | 16053 |
| 016245 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:19am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594524.2 | 509706.8 | 42197 | 1.64041666667 | 16245 |
| 016308 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:20am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594522.7 | 509709.4 | 42199 | 1.64041666667 | 16308 |
| 016223 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:21am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594522.5 | 509711.5 | 42201 | 1.64041666667 | 16223 |
| 015710 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:22am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594521.3 | 509714.0 | 42203 | 1.64041666667 | 15710 |
| 015714 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:23am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594521.0 | 509716.0 | 42205 | 1.64041666667 | 15714 |
| 016549 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:24am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594520.8 | 509718.8 | 42207 | 1.64041666667 | 16549 |
| 016239 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:25am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594520.1 | 509721.1 | 42209 | 1.64041666667 | 16239 |
| 016184 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:26am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594520.0 | 509723.9 | 42211 | 1.64041666667 | 16184 |
| 017158 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:27am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594519.6 | 509726.2 | 42213 | 1.64041666667 | 17158 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016477 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:28am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594519.1 | 509729.2 | 42215 | 1.64041666667 | 16477 |
| 016355 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:29am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594519.1 | 509731.0 | 42217 | 1.64041666667 | 16355 |
| 016767 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:30am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594518.1 | 509733.4 | 42219 | 1.64041666667 | 16767 |
| 016331 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:31am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594517.7 | 509735.7 | 42221 | 1.64041666667 | 16331 |
| 015839 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:32am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594516.9 | 509738.3 | 42223 | 1.64041666667 | 15839 |
| 016289 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:33am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594515.6 | 509740.7 | 42225 | 1.64041666667 | 16289 |
| 016482 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:34am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594515.2 | 509743.0 | 42227 | 1.64041666667 | 16482 |
| 015474 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:35am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594514.1 | 509745.2 | 42229 | 1.64041666667 | 15474 |
| 014929 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:36am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594512.6 | 509747.7 | 42231 | 1.64041666667 | 14929 |
| 014847 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:37am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594511.8 | 509749.6 | 42233 | 1.64041666667 | 14847 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:38am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594510.2 | 509751.4 | 42235 | 1.64041666667 | 14456 |
| 014622 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:39am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594509.2 | 509753.5 | 42237 | 1.64041666667 | 14622 |
| 014698 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:40am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594508.2 | 509756.1 | 42239 | 1.64041666667 | 14698 |
| 015295 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:41am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594506.8 | 509758.1 | 42241 | 1.64041666667 | 15295 |
| 015301 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:42am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594505.8 | 509760.7 | 42243 | 1.64041666667 | 15301 |
| 015986 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:43am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594504.4 | 509762.7 | 42245 | 1.64041666667 | 15986 |
| 015990 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:44am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594502.7 | 509765.2 | 42247 | 1.64041666667 | 15990 |
| 015144 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:45am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594501.7 | 509767.6 | 42249 | 1.64041666667 | 15144 |
| 015464 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:46am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594500.0 | 509769.8 | 42251 | 1.64041666667 | 15464 |
| 015606 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:47am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594498.8 | 509771.8 | 42253 | 1.64041666667 | 15606 |
| 015071 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:48am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594497.5 | 509774.6 | 42255 | 1.64041666667 | 15071 |
| 014110 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:49am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594496.0 | 509776.6 | 42257 | 1.64041666667 | 14110 |
| 014386 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:50am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594495.0 | 509779.0 | 42259 | 1.64041666667 | 14386 |
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:51am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594493.5 | 509780.7 | 42261 | 1.64041666667 | 13320 |
| 012517 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:52am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594491.7 | 509782.7 | 42263 | 1.64041666667 | 12517 |
| 012703 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:53am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594490.4 | 509784.6 | 42265 | 1.64041666667 | 12703 |
| 012215 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:54am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594488.6 | 509786.2 | 42267 | 1.64041666667 | 12215 |
| 013186 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:55am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594487.9 | 509788.1 | 42269 | 1.64041666667 | 13186 |
| 012292 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:56am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594488.0 | 509790.6 | 42271 | 1.64041666667 | 12292 |
| 012877 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:57am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594489.1 | 509792.5 | 42273 | 1.64041666667 | 12877 |
| 013115 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:58am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594491.3 | 509793.6 | 42275 | 1.64041666667 | 13115 |
| 012372 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:59am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594492.9 | 509795.2 | 42277 | 1.64041666667 | 12372 |
| 012164 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:00am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594495.1 | 509796.2 | 42279 | 1.64041666667 | 12164 |
| 012812 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:01am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594497.4 | 509796.1 | 42281 | 1.64041666667 | 12812 |
| 013529 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:02am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594500.0 | 509795.3 | 42283 | 1.64041666667 | 13529 |
| 013955 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:03am | Sensor | 1797-S0034-905-G-ACK | 6806.9 | 1594500.7 | 509793.5 | 42285 | 1.64041666667 | 13955 |
| 014104 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:04am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594502.3 | 509791.7 | 42287 | 1.64041666667 | 14104 |
| 015734 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:05am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594503.1 | 509789.6 | 42289 | 1.64041666667 | 15734 |
| 016387 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:06am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594504.2 | 509787.3 | 42291 | 1.64041666667 | 16387 |
| 018923 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:07am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594505.6 | 509785.5 | 42293 | 1.64041666667 | 18923 |
| 016996 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:08am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594506.2 | 509783.1 | 42295 | 1.64041666667 | 16996 |
| 016610 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:09am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594507.5 | 509781.4 | 42297 | 1.64041666667 | 16610 |
| 014968 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:10am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594508.8 | 509778.9 | 42299 | 1.64041666667 | 14968 |
| 015004 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:11am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594509.6 | 509776.8 | 42301 | 1.64041666667 | 15004 |
| 014935 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:12am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594511.2 | 509774.2 | 42303 | 1.64041666667 | 14935 |
| 014686 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:13am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594511.9 | 509772.4 | 42305 | 1.64041666667 | 14686 |
| 014186 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:14am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594513.5 | 509770.4 | 42307 | 1.64041666667 | 14186 |
| 013964 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:15am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594514.2 | 509768.5 | 42309 | 1.64041666667 | 13964 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013577 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:16am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594515.0 | 509766.1 | 42311 | 1.64041666667 | 13577 |
| 013127 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:17am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594516.0 | 509764.0 | 42313 | 1.64041666667 | 13127 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:18am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594516.5 | 509761.5 | 42315 | 1.64041666667 | 14111 |
| 013705 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:19am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594517.9 | 509759.9 | 42317 | 1.64041666667 | 13705 |
| 013739 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:20am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594519.0 | 509757.7 | 42319 | 1.64041666667 | 13739 |
| 013743 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:21am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594520.1 | 509756.0 | 42321 | 1.64041666667 | 13743 |
| 013558 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:22am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594521.5 | 509753.8 | 42323 | 1.64041666667 | 13558 |
| 014624 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:23am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594522.5 | 509751.8 | 42325 | 1.64041666667 | 14624 |
| 014481 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:24am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594524.2 | 509749.9 | 42327 | 1.64041666667 | 14481 |
| 014858 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:25am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594524.6 | 509747.8 | 42329 | 1.64041666667 | 14858 |
| 015685 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:26am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594525.5 | 509745.3 | 42331 | 1.64041666667 | 15685 |
| 015715 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:27am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594526.7 | 509742.9 | 42333 | 1.64041666667 | 15715 |
| 015747 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:28am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594527.6 | 509740.4 | 42335 | 1.64041666667 | 15747 |
| 016020 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:29am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594529.1 | 509738.8 | 42337 | 1.64041666667 | 16020 |
| 016323 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:30am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594530.2 | 509736.8 | 42339 | 1.64041666667 | 16323 |
| 016029 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:31am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594531.5 | 509734.9 | 42341 | 1.64041666667 | 16029 |
| 016651 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:32am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594533.2 | 509732.7 | 42343 | 1.64041666667 | 16651 |
| 017249 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:33am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594534.2 | 509730.7 | 42345 | 1.64041666667 | 17249 |
| 017780 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:34am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.7 | 509729.1 | 42347 | 1.64041666667 | 17780 |
| 018363 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:35am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.3 | 509728.8 | 42349 | 1.64041666667 | 18363 |
| 017499 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:36am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594535.2 | 509728.8 | 42351 | 1.64041666667 | 17499 |
| 017118 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:37am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594535.1 | 509728.8 | 42353 | 1.64041666667 | 17118 |
| 017571 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:38am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594535.1 | 509728.8 | 42355 | 1.64041666667 | 17571 |
| 016934 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:39am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.1 | 509728.8 | 42357 | 1.64041666667 | 16934 |
| 017662 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:40am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.2 | 509728.8 | 42359 | 1.64041666667 | 17662 |
| 016632 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:41am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.2 | 509728.8 | 42361 | 1.64041666667 | 16632 |
| 017328 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:42am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.2 | 509728.8 | 42363 | 1.64041666667 | 17328 |
| 017734 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:43am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.5 | 509728.9 | 42365 | 1.64041666667 | 17734 |
| 018368 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:44am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594536.1 | 509727.4 | 42367 | 1.64041666667 | 18368 |
| 018634 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:45am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594537.3 | 509726.3 | 42369 | 1.64041666667 | 18634 |
| 019917 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:46am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.0 | 509724.7 | 42371 | 1.64041666667 | 19917 |
| 019580 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:47am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.3 | 509724.2 | 42373 | 1.64041666667 | 19580 |
| 019376 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:48am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594538.1 | 509724.0 | 42375 | 1.64041666667 | 19376 |
| 019967 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:49am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594538.1 | 509723.6 | 42377 | 1.64041666667 | 19967 |
| 019743 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:50am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.1 | 509723.6 | 42379 | 1.64041666667 | 19743 |
| 019933 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:51am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.1 | 509723.7 | 42381 | 1.64041666667 | 19933 |
| 019635 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:52am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.2 | 509723.8 | 42383 | 1.64041666667 | 19635 |
| 020202 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:53am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.2 | 509723.8 | 42385 | 1.64041666667 | 20202 |
| 020543 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:54am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.1 | 509723.8 | 42387 | 1.64041666667 | 20543 |
| 021200 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:55am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.3 | 509723.8 | 42389 | 1.64041666667 | 21200 |
| 019703 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:56am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594538.2 | 509722.5 | 42391 | 1.64041666667 | 19703 |
| 019333 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:57am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594539.2 | 509721.0 | 42393 | 1.64041666667 | 19333 |
| 019739 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:58am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594540.2 | 509719.0 | 42395 | 1.64041666667 | 19739 |
| 019638 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:59am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594541.1 | 509717.0 | 42397 | 1.64041666667 | 19638 |
| 020294 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:00am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594542.8 | 509714.4 | 42399 | 1.64041666667 | 20294 |
| 020970 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:01am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594543.1 | 509712.8 | 42401 | 1.64041666667 | 20970 |
| 021463 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:02am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594543.5 | 509711.7 | 42403 | 1.64041666667 | 21463 |
| 022850 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:03am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594543.9 | 509711.7 | 42405 | 1.64041666667 | 22850 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 023938 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:04am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594544.3 | 509711.8 | 42407 | 1.64041666667 | 23938 |
| 025480 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:05am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594544.5 | 509711.9 | 42409 | 1.64041666667 | 25480 |
| 026107 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:06am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594544.5 | 509712.0 | 42411 | 1.64041666667 | 26107 |
| 025680 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:07am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594544.4 | 509712.0 | 42413 | 1.64041666667 | 25680 |
| 026055 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:08am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594544.4 | 509712.0 | 42415 | 1.64041666667 | 26055 |
| 025711 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:09am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594544.2 | 509711.7 | 42417 | 1.64041666667 | 25711 |
| 026057 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:10am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594544.1 | 509710.8 | 42419 | 1.64041666667 | 26057 |
| 025495 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:11am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594544.3 | 509710.5 | 42421 | 1.64041666667 | 25495 |
| 026880 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:12am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594544.7 | 509710.4 | 42423 | 1.64041666667 | 26880 |
| 026408 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:13am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594544.5 | 509710.5 | 42425 | 1.64041666667 | 26408 |
| 025017 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:14am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594544.4 | 509710.5 | 42427 | 1.64041666667 | 25017 |
| 026042 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:15am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.1 | 509710.5 | 42429 | 1.64041666667 | 26042 |
| 026191 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:16am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594546.1 | 509711.6 | 42431 | 1.64041666667 | 26191 |
| 025307 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:17am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594546.1 | 509711.9 | 42433 | 1.64041666667 | 25307 |
| 024975 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:18am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.9 | 509712.1 | 42435 | 1.64041666667 | 24975 |
| 025823 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:19am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.8 | 509712.1 | 42437 | 1.64041666667 | 25823 |
| 026848 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:20am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509711.6 | 42439 | 1.64041666667 | 26848 |
| 026299 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:21am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594544.9 | 509711.6 | 42441 | 1.64041666667 | 26299 |
| 026253 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:22am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.0 | 509711.6 | 42443 | 1.64041666667 | 26253 |
| 026625 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:23am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.2 | 509711.7 | 42445 | 1.64041666667 | 26625 |
| 027036 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:24am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594546.3 | 509712.2 | 42447 | 1.64041666667 | 27036 |
| 027193 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:25am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594546.2 | 509712.1 | 42449 | 1.64041666667 | 27193 |
| 026231 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:26am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594546.0 | 509711.3 | 42451 | 1.64041666667 | 26231 |
| 023972 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:27am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594546.4 | 509709.8 | 42453 | 1.64041666667 | 23972 |
| 022762 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:28am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594547.9 | 509708.0 | 42455 | 1.64041666667 | 22762 |
| 019951 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:29am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594548.0 | 509706.0 | 42457 | 1.64041666667 | 19951 |
| 018632 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:30am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594549.2 | 509704.0 | 42459 | 1.64041666667 | 18632 |
| 018423 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:31am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594550.0 | 509702.0 | 42461 | 1.64041666667 | 18423 |
| 016655 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:32am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594551.1 | 509698.8 | 42463 | 1.64041666667 | 16655 |
| 015961 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:33am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594552.1 | 509696.6 | 42465 | 1.64041666667 | 15961 |
| 014745 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:34am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594552.2 | 509693.7 | 42467 | 1.64041666667 | 14745 |
| 014692 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:35am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594553.3 | 509691.7 | 42469 | 1.64041666667 | 14692 |
| 014714 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:36am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594554.9 | 509689.2 | 42471 | 1.64041666667 | 14714 |
| 014779 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:37am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594555.8 | 509687.0 | 42473 | 1.64041666667 | 14779 |
| 014418 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:38am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594557.7 | 509684.6 | 42475 | 1.64041666667 | 14418 |
| 014883 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:39am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594558.6 | 509682.3 | 42477 | 1.64041666667 | 14883 |
| 014611 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:40am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594559.9 | 509679.8 | 42479 | 1.64041666667 | 14611 |
| 014181 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:41am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594561.4 | 509677.4 | 42481 | 1.64041666667 | 14181 |
| 014007 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:42am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594562.4 | 509674.8 | 42483 | 1.64041666667 | 14007 |
| 015544 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:43am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594563.7 | 509673.0 | 42485 | 1.64041666667 | 15544 |
| 015561 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:44am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594565.3 | 509670.7 | 42487 | 1.64041666667 | 15561 |
| 014918 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:45am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594566.2 | 509668.8 | 42489 | 1.64041666667 | 14918 |
| 015239 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:46am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594568.0 | 509668.4 | 42491 | 1.64041666667 | 15239 |
| 014489 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:47am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594569.5 | 509669.3 | 42493 | 1.64041666667 | 14489 |
| 013842 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:48am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594571.5 | 509670.5 | 42495 | 1.64041666667 | 13842 |
| 015016 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:49am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594572.4 | 509672.3 | 42497 | 1.64041666667 | 15016 |
| 014431 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:50am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594573.2 | 509674.3 | 42499 | 1.64041666667 | 14431 |
| 014808 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:51am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594572.7 | 509676.3 | 42501 | 1.64041666667 | 14808 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016039 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:52am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594571.2 | 509678.7 | 42503 | 1.64041666667 | 16039 |
| 015929 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:53am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594569.9 | 509680.8 | 42505 | 1.64041666667 | 15929 |
| 015523 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:54am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594567.8 | 509683.0 | 42507 | 1.64041666667 | 15523 |
| 016381 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:55am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594566.2 | 509685.3 | 42509 | 1.64041666667 | 16381 |
| 016219 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:56am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594564.9 | 509687.8 | 42511 | 1.64041666667 | 16219 |
| 016428 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:57am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594563.1 | 509689.6 | 42513 | 1.64041666667 | 16428 |
| 016643 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:58am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594561.7 | 509691.9 | 42515 | 1.64041666667 | 16643 |
| 016502 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:59am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594560.2 | 509693.9 | 42517 | 1.64041666667 | 16502 |
| 016849 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:00am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594558.2 | 509696.1 | 42519 | 1.64041666667 | 16849 |
| 016775 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:01am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594557.6 | 509698.4 | 42521 | 1.64041666667 | 16775 |
| 015991 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:02am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594556.7 | 509701.1 | 42523 | 1.64041666667 | 15991 |
| 015895 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:03am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594556.5 | 509703.6 | 42525 | 1.64041666667 | 15895 |
| 016298 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:04am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594556.5 | 509706.5 | 42527 | 1.64041666667 | 16298 |
| 016585 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:05am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594555.8 | 509708.7 | 42529 | 1.64041666667 | 16585 |
| 016626 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:06am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594555.4 | 509711.4 | 42531 | 1.64041666667 | 16626 |
| 015622 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:07am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594554.1 | 509713.6 | 42533 | 1.64041666667 | 15622 |
| 016257 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:08am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594552.6 | 509715.8 | 42535 | 1.64041666667 | 16257 |
| 016697 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:09am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594551.1 | 509718.0 | 42537 | 1.64041666667 | 16697 |
| 016592 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:10am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594549.3 | 509719.8 | 42539 | 1.64041666667 | 16592 |
| 017328 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:11am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594548.2 | 509721.8 | 42541 | 1.64041666667 | 17328 |
| 016924 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:12am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594546.2 | 509723.7 | 42543 | 1.64041666667 | 16924 |
| 016900 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:13am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594544.5 | 509725.6 | 42545 | 1.64041666667 | 16900 |
| 017261 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:14am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594542.7 | 509728.2 | 42547 | 1.64041666667 | 17261 |
| 016092 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:15am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594540.7 | 509729.9 | 42549 | 1.64041666667 | 16092 |
| 016326 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:16am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594538.8 | 509732.1 | 42551 | 1.64041666667 | 16326 |
| 017448 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:17am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594537.2 | 509733.9 | 42553 | 1.64041666667 | 17448 |
| 017187 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:18am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594535.0 | 509736.0 | 42555 | 1.64041666667 | 17187 |
| 018367 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:19am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594534.0 | 509738.2 | 42557 | 1.64041666667 | 18367 |
| 018566 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:20am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594532.8 | 509740.7 | 42559 | 1.64041666667 | 18566 |
| 018483 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:21am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594532.4 | 509742.9 | 42561 | 1.64041666667 | 18483 |
| 016757 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:22am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594531.2 | 509745.2 | 42563 | 1.64041666667 | 16757 |
| 015771 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:23am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594529.4 | 509747.4 | 42565 | 1.64041666667 | 15771 |
| 016041 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:24am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594528.3 | 509750.0 | 42567 | 1.64041666667 | 16041 |
| 016620 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:25am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594527.1 | 509752.1 | 42569 | 1.64041666667 | 16620 |
| 016024 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:26am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594525.7 | 509754.6 | 42571 | 1.64041666667 | 16024 |
| 015726 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:27am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594524.3 | 509756.8 | 42573 | 1.64041666667 | 15726 |
| 016143 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:28am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594522.4 | 509758.8 | 42575 | 1.64041666667 | 16143 |
| 015305 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:29am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594521.2 | 509760.8 | 42577 | 1.64041666667 | 15305 |
| 015937 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:30am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594519.3 | 509762.5 | 42579 | 1.64041666667 | 15937 |
| 015324 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:31am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594518.1 | 509764.0 | 42581 | 1.64041666667 | 15324 |
| 014702 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:32am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594516.2 | 509765.5 | 42583 | 1.64041666667 | 14702 |
| 015200 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:33am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594514.3 | 509767.2 | 42585 | 1.64041666667 | 15200 |
| 014947 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:34am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594513.1 | 509769.5 | 42587 | 1.64041666667 | 14947 |
| 015248 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:35am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594511.9 | 509771.3 | 42589 | 1.64041666667 | 15248 |
| 014569 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:36am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594511.3 | 509773.9 | 42591 | 1.64041666667 | 14569 |
| 014653 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:37am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594510.7 | 509776.1 | 42593 | 1.64041666667 | 14653 |
| 014264 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:38am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594510.2 | 509779.3 | 42595 | 1.64041666667 | 14264 |
| 014241 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:39am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594510.3 | 509781.8 | 42597 | 1.64041666667 | 14241 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014768 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:40am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594509.7 | 509784.5 | 42599 | 1.64041666667 | 14768 |
| 015769 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:41am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594509.7 | 509786.5 | 42601 | 1.64041666667 | 15769 |
| 016678 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:42am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594510.2 | 509788.9 | 42603 | 1.64041666667 | 16678 |
| 016693 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:43am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594511.8 | 509790.4 | 42605 | 1.64041666667 | 16693 |
| 015720 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:44am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594514.2 | 509790.5 | 42607 | 1.64041666667 | 15720 |
| 015975 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:45am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594516.7 | 509790.0 | 42609 | 1.64041666667 | 15975 |
| 015691 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:46am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594518.4 | 509788.0 | 42611 | 1.64041666667 | 15691 |
| 015253 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:47am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594520.0 | 509786.1 | 42613 | 1.64041666667 | 15253 |
| 014340 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:48am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594521.9 | 509783.8 | 42615 | 1.64041666667 | 14340 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:49am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594522.6 | 509781.8 | 42617 | 1.64041666667 | 14283 |
| 015114 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:50am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594524.2 | 509779.8 | 42619 | 1.64041666667 | 15114 |
| 014644 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:51am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594525.3 | 509777.7 | 42621 | 1.64041666667 | 14644 |
| 013757 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:52am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594526.8 | 509775.3 | 42623 | 1.64041666667 | 13757 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:53am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594528.2 | 509773.6 | 42625 | 1.64041666667 | 13491 |
| 013888 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:54am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594529.2 | 509771.4 | 42627 | 1.64041666667 | 13888 |
| 013767 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:55am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594531.2 | 509770.6 | 42629 | 1.64041666667 | 13767 |
| 014524 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:56am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594533.0 | 509768.8 | 42631 | 1.64041666667 | 14524 |
| 014822 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:57am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594534.4 | 509766.9 | 42633 | 1.64041666667 | 14822 |
| 015365 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:58am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594535.9 | 509764.2 | 42635 | 1.64041666667 | 15365 |
| 015182 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:59am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594536.0 | 509761.8 | 42637 | 1.64041666667 | 15182 |
| 015372 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:00am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594536.8 | 509759.0 | 42639 | 1.64041666667 | 15372 |
| 015929 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:01am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594537.4 | 509756.7 | 42641 | 1.64041666667 | 15929 |
| 015868 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:02am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594537.2 | 509753.8 | 42643 | 1.64041666667 | 15868 |
| 015593 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:03am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594537.8 | 509751.9 | 42645 | 1.64041666667 | 15593 |
| 015776 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:04am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594538.4 | 509749.1 | 42647 | 1.64041666667 | 15776 |
| 015766 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:05am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594539.3 | 509746.9 | 42649 | 1.64041666667 | 15766 |
| 015018 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:06am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594540.9 | 509743.9 | 42651 | 1.64041666667 | 15018 |
| 015738 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:07am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594541.4 | 509741.5 | 42653 | 1.64041666667 | 15738 |
| 015550 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:08am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594542.6 | 509739.1 | 42655 | 1.64041666667 | 15550 |
| 016547 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:09am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594543.7 | 509736.8 | 42657 | 1.64041666667 | 16547 |
| 016462 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:10am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594544.5 | 509733.9 | 42659 | 1.64041666667 | 16462 |
| 015170 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:11am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594545.4 | 509731.9 | 42661 | 1.64041666667 | 15170 |
| 015260 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:12am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594546.0 | 509729.4 | 42663 | 1.64041666667 | 15260 |
| 016451 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:13am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594546.9 | 509727.6 | 42665 | 1.64041666667 | 16451 |
| 015479 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:14am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594549.0 | 509725.4 | 42667 | 1.64041666667 | 15479 |
| 016552 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:15am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594550.7 | 509723.9 | 42669 | 1.64041666667 | 16552 |
| 016870 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:16am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594553.0 | 509722.7 | 42671 | 1.64041666667 | 16870 |
| 016074 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:17am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594554.5 | 509721.0 | 42673 | 1.64041666667 | 16074 |
| 015792 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:18am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594556.5 | 509718.6 | 42675 | 1.64041666667 | 15792 |
| 015858 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:19am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594558.2 | 509717.1 | 42677 | 1.64041666667 | 15858 |
| 015955 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:20am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594559.6 | 509714.9 | 42679 | 1.64041666667 | 15955 |
| 015844 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:21am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594561.7 | 509713.5 | 42681 | 1.64041666667 | 15844 |
| 016412 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:22am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594563.9 | 509711.6 | 42683 | 1.64041666667 | 16412 |
| 015854 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:23am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594565.4 | 509709.7 | 42685 | 1.64041666667 | 15854 |
| 016695 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:24am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594567.8 | 509707.7 | 42687 | 1.64041666667 | 16695 |
| 016553 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:25am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594569.0 | 509705.9 | 42689 | 1.64041666667 | 16553 |
| 014299 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:26am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594570.5 | 509703.7 | 42691 | 1.64041666667 | 14299 |
| 014043 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:27am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594572.1 | 509701.8 | 42693 | 1.64041666667 | 14043 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:28am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594572.4 | 509699.4 | 42695 | 1.64041666667 | 13974 |
| 014498 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:29am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594572.7 | 509697.2 | 42697 | 1.64041666667 | 14498 |
| 014545 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:30am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594572.9 | 509694.3 | 42699 | 1.64041666667 | 14545 |
| 014159 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:31am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594572.7 | 509692.4 | 42701 | 1.64041666667 | 14159 |
| 015344 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:32am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594573.6 | 509690.0 | 42703 | 1.64041666667 | 15344 |
| 014758 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:33am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594574.0 | 509688.1 | 42705 | 1.64041666667 | 14758 |
| 015134 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:34am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594575.9 | 509686.6 | 42707 | 1.64041666667 | 15134 |
| 015428 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:35am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594577.9 | 509685.9 | 42709 | 1.64041666667 | 15428 |
| 014888 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:36am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594580.1 | 509685.3 | 42711 | 1.64041666667 | 14888 |
| 014922 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:37am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594582.0 | 509685.9 | 42713 | 1.64041666667 | 14922 |
| 014348 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:38am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594584.4 | 509686.5 | 42715 | 1.64041666667 | 14348 |
| 014408 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:39am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594585.3 | 509687.8 | 42717 | 1.64041666667 | 14408 |
| 013917 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:40am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594586.0 | 509690.3 | 42719 | 1.64041666667 | 13917 |
| 014721 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:41am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594586.4 | 509692.3 | 42721 | 1.64041666667 | 14721 |
| 014468 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:42am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594586.0 | 509695.0 | 42723 | 1.64041666667 | 14468 |
| 014243 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:43am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594586.2 | 509696.9 | 42725 | 1.64041666667 | 14243 |
| 014821 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:44am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594585.6 | 509699.5 | 42727 | 1.64041666667 | 14821 |
| 014749 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:45am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594584.8 | 509701.7 | 42729 | 1.64041666667 | 14749 |
| 014416 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:46am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594583.9 | 509704.3 | 42731 | 1.64041666667 | 14416 |
| 015189 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:47am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594582.8 | 509706.3 | 42733 | 1.64041666667 | 15189 |
| 015556 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:48am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594581.9 | 509708.7 | 42735 | 1.64041666667 | 15556 |
| 015447 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:49am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594580.8 | 509710.1 | 42737 | 1.64041666667 | 15447 |
| 015395 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:50am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594578.5 | 509712.2 | 42739 | 1.64041666667 | 15395 |
| 014134 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:51am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594577.4 | 509714.2 | 42741 | 1.64041666667 | 14134 |
| 014085 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:52am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594575.6 | 509716.2 | 42743 | 1.64041666667 | 14085 |
| 014140 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:53am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594574.1 | 509718.2 | 42745 | 1.64041666667 | 14140 |
| 014809 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:54am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594572.8 | 509720.6 | 42747 | 1.64041666667 | 14809 |
| 014832 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:55am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594571.3 | 509722.2 | 42749 | 1.64041666667 | 14832 |
| 014073 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:56am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594570.1 | 509724.5 | 42751 | 1.64041666667 | 14073 |
| 013863 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:57am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594568.8 | 509726.8 | 42753 | 1.64041666667 | 13863 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:58am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594567.0 | 509729.6 | 42755 | 1.64041666667 | 14158 |
| 014909 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:59am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594566.4 | 509731.6 | 42757 | 1.64041666667 | 14909 |
| 013853 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:00am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594565.0 | 509734.0 | 42759 | 1.64041666667 | 13853 |
| 013102 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:01am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594564.1 | 509735.9 | 42761 | 1.64041666667 | 13102 |
| 013490 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:02am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594563.1 | 509738.7 | 42763 | 1.64041666667 | 13490 |
| 014443 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:03am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594562.0 | 509740.9 | 42765 | 1.64041666667 | 14443 |
| 013832 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:04am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594561.1 | 509743.3 | 42767 | 1.64041666667 | 13832 |
| 013548 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:05am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594559.9 | 509745.3 | 42769 | 1.64041666667 | 13548 |
| 013478 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:06am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594558.8 | 509748.2 | 42771 | 1.64041666667 | 13478 |
| 013634 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:07am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594558.1 | 509750.6 | 42773 | 1.64041666667 | 13634 |
| 013309 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:08am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594556.4 | 509753.1 | 42775 | 1.64041666667 | 13309 |
| 013681 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:09am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594555.3 | 509755.2 | 42777 | 1.64041666667 | 13681 |
| 013920 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:10am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594553.8 | 509757.9 | 42779 | 1.64041666667 | 13920 |
| 013680 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:11am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594552.4 | 509760.1 | 42781 | 1.64041666667 | 13680 |
| 014055 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:12am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594551.2 | 509762.7 | 42783 | 1.64041666667 | 14055 |
| 013058 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:13am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594549.9 | 509764.7 | 42785 | 1.64041666667 | 13058 |
| 013795 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:14am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594548.1 | 509767.0 | 42787 | 1.64041666667 | 13795 |
| 013790 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:15am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594547.2 | 509769.0 | 42789 | 1.64041666667 | 13790 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013696 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:16am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594545.6 | 509771.6 | 42791 | 1.64041666667 | 13696 |
| 013832 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:17am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594544.1 | 509773.7 | 42793 | 1.64041666667 | 13832 |
| 014275 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:18am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594542.5 | 509776.0 | 42795 | 1.64041666667 | 14275 |
| 014315 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:19am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594540.6 | 509777.4 | 42797 | 1.64041666667 | 14315 |
| 014539 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:20am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594539.1 | 509779.8 | 42799 | 1.64041666667 | 14539 |
| 014291 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:21am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594538.2 | 509782.3 | 42801 | 1.64041666667 | 14291 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:22am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594536.6 | 509785.2 | 42803 | 1.64041666667 | 13453 |
| 013170 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:23am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594536.2 | 509787.3 | 42805 | 1.64041666667 | 13170 |
| 012935 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:24am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594535.2 | 509789.7 | 42807 | 1.64041666667 | 12935 |
| 013126 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:25am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594533.9 | 509791.7 | 42809 | 1.64041666667 | 13126 |
| 012903 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:26am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594533.5 | 509794.3 | 42811 | 1.64041666667 | 12903 |
| 013948 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:27am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594533.8 | 509796.5 | 42813 | 1.64041666667 | 13948 |
| 014003 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:28am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594535.4 | 509798.1 | 42815 | 1.64041666667 | 14003 |
| 013434 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:29am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594537.5 | 509799.4 | 42817 | 1.64041666667 | 13434 |
| 013774 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:30am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594540.2 | 509800.8 | 42819 | 1.64041666667 | 13774 |
| 013830 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:31am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594542.0 | 509801.0 | 42821 | 1.64041666667 | 13830 |
| 013877 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:32am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594543.9 | 509801.0 | 42823 | 1.64041666667 | 13877 |
| 013776 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:33am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594545.1 | 509799.8 | 42825 | 1.64041666667 | 13776 |
| 013734 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:34am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594546.1 | 509797.2 | 42827 | 1.64041666667 | 13734 |
| 014040 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:35am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594547.6 | 509795.4 | 42829 | 1.64041666667 | 14040 |
| 014025 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:36am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594548.7 | 509793.1 | 42831 | 1.64041666667 | 14025 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:37am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594549.8 | 509791.5 | 42833 | 1.64041666667 | 14324 |
| 013562 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:38am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594551.5 | 509789.2 | 42835 | 1.64041666667 | 13562 |
| 014138 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:39am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594552.1 | 509787.1 | 42837 | 1.64041666667 | 14138 |
| 014515 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:40am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594553.3 | 509785.0 | 42839 | 1.64041666667 | 14515 |
| 014007 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:41am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594553.7 | 509783.0 | 42841 | 1.64041666667 | 14007 |
| 014989 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:42am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594553.9 | 509780.4 | 42843 | 1.64041666667 | 14989 |
| 015316 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:43am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594554.6 | 509777.9 | 42845 | 1.64041666667 | 15316 |
| 014900 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:44am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594554.9 | 509775.2 | 42847 | 1.64041666667 | 14900 |
| 013713 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:45am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594555.9 | 509773.2 | 42849 | 1.64041666667 | 13713 |
| 013399 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:46am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594557.2 | 509770.9 | 42851 | 1.64041666667 | 13399 |
| 014099 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:47am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594558.2 | 509768.9 | 42853 | 1.64041666667 | 14099 |
| 013593 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:48am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594560.0 | 509766.7 | 42855 | 1.64041666667 | 13593 |
| 014433 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:49am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594561.1 | 509764.5 | 42857 | 1.64041666667 | 14433 |
| 013909 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:50am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594562.6 | 509762.5 | 42859 | 1.64041666667 | 13909 |
| 015031 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:51am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594563.9 | 509760.7 | 42861 | 1.64041666667 | 15031 |
| 014132 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:52am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594565.1 | 509758.1 | 42863 | 1.64041666667 | 14132 |
| 014369 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:53am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594566.6 | 509756.2 | 42865 | 1.64041666667 | 14369 |
| 014998 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:54am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594567.4 | 509753.6 | 42867 | 1.64041666667 | 14998 |
| 015553 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:55am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594568.5 | 509751.6 | 42869 | 1.64041666667 | 15553 |
| 016226 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:56am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594569.8 | 509749.4 | 42871 | 1.64041666667 | 16226 |
| 015060 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:57am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594570.7 | 509747.4 | 42873 | 1.64041666667 | 15060 |
| 014696 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:58am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594572.4 | 509745.2 | 42875 | 1.64041666667 | 14696 |
| 014551 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:59am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594572.9 | 509743.1 | 42877 | 1.64041666667 | 14551 |
| 014890 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:00am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594573.5 | 509740.6 | 42879 | 1.64041666667 | 14890 |
| 014675 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:01am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594574.6 | 509738.3 | 42881 | 1.64041666667 | 14675 |
| 014870 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:02am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594576.1 | 509735.7 | 42883 | 1.64041666667 | 14870 |
| 014364 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:03am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594578.0 | 509734.1 | 42885 | 1.64041666667 | 14364 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014252 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:04am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594580.2 | 509732.2 | 42887 | 1.64041666667 | 14252 |
| 013949 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:05am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594581.9 | 509730.6 | 42889 | 1.64041666667 | 13949 |
| 013291 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:06am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594583.7 | 509728.4 | 42891 | 1.64041666667 | 13291 |
| 013821 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:07am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594584.7 | 509726.1 | 42893 | 1.64041666667 | 13821 |
| 013752 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:08am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594586.1 | 509723.7 | 42895 | 1.64041666667 | 13752 |
| 013765 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:09am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594587.6 | 509721.5 | 42897 | 1.64041666667 | 13765 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:10am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594588.6 | 509718.8 | 42899 | 1.64041666667 | 13915 |
| 015725 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:11am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594590.0 | 509716.8 | 42901 | 1.64041666667 | 15725 |
| 015617 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:12am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594591.6 | 509714.5 | 42903 | 1.64041666667 | 15617 |
| 016255 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:13am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594592.4 | 509712.3 | 42905 | 1.64041666667 | 16255 |
| 015068 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:14am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594593.7 | 509709.9 | 42907 | 1.64041666667 | 15068 |
| 014631 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:15am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594594.6 | 509707.7 | 42909 | 1.64041666667 | 14631 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:16am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594595.3 | 509705.9 | 42911 | 1.64041666667 | 14570 |
| 014593 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:17am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594596.6 | 509704.2 | 42913 | 1.64041666667 | 14593 |
| 014006 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:18am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594597.5 | 509702.5 | 42915 | 1.64041666667 | 14006 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:19am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594598.8 | 509701.5 | 42917 | 1.64041666667 | 14426 |
| 013762 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:20am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594600.9 | 509700.5 | 42919 | 1.64041666667 | 13762 |
| 013831 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:21am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594602.4 | 509701.2 | 42921 | 1.64041666667 | 13831 |
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:22am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594604.0 | 509702.7 | 42923 | 1.64041666667 | 13277 |
| 014136 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:23am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594605.5 | 509704.2 | 42925 | 1.64041666667 | 14136 |
| 014146 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:24am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594605.7 | 509706.0 | 42927 | 1.64041666667 | 14146 |
| 014722 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:25am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594605.9 | 509707.9 | 42929 | 1.64041666667 | 14722 |
| 014288 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:26am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594604.7 | 509709.7 | 42931 | 1.64041666667 | 14288 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:27am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594603.1 | 509711.2 | 42933 | 1.64041666667 | 14210 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:28am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594601.6 | 509713.1 | 42935 | 1.64041666667 | 14158 |
| 014669 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:29am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594599.7 | 509714.4 | 42937 | 1.64041666667 | 14669 |
| 014476 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:30am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594598.4 | 509716.4 | 42939 | 1.64041666667 | 14476 |
| 015050 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:31am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594597.5 | 509718.5 | 42941 | 1.64041666667 | 15050 |
| 014735 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:32am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594596.4 | 509721.0 | 42943 | 1.64041666667 | 14735 |
| 014686 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:33am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594596.0 | 509723.2 | 42945 | 1.64041666667 | 14686 |
| 014726 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:34am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594595.2 | 509725.9 | 42947 | 1.64041666667 | 14726 |
| 014494 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:35am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594594.3 | 509728.2 | 42949 | 1.64041666667 | 14494 |
| 015255 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:36am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594593.8 | 509730.7 | 42951 | 1.64041666667 | 15255 |
| 014903 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:37am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594592.6 | 509732.9 | 42953 | 1.64041666667 | 14903 |
| 014788 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:38am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594591.5 | 509735.6 | 42955 | 1.64041666667 | 14788 |
| 015248 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:39am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594590.7 | 509737.9 | 42957 | 1.64041666667 | 15248 |
| 015559 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:40am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594589.2 | 509740.4 | 42959 | 1.64041666667 | 15559 |
| 014452 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:41am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594588.4 | 509742.4 | 42961 | 1.64041666667 | 14452 |
| 014692 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:42am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594587.0 | 509744.9 | 42963 | 1.64041666667 | 14692 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:43am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594585.7 | 509747.2 | 42965 | 1.64041666667 | 14556 |
| 014278 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:44am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594585.1 | 509749.6 | 42967 | 1.64041666667 | 14278 |
| 014001 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:45am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594584.0 | 509751.0 | 42969 | 1.64041666667 | 14001 |
| 014243 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:46am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594583.4 | 509752.8 | 42971 | 1.64041666667 | 14243 |
| 014206 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:47am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594583.1 | 509753.5 | 42973 | 1.64041666667 | 14206 |
| 014688 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:48am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594582.5 | 509753.5 | 42975 | 1.64041666667 | 14688 |
| 014465 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:49am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594582.7 | 509754.3 | 42977 | 1.64041666667 | 14465 |
| 014474 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:50am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594581.8 | 509755.2 | 42979 | 1.64041666667 | 14474 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:51am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594580.9 | 509756.7 | 42981 | 1.64041666667 | 14081 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013950 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:52am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594579.4 | 509759.1 | 42983 | 1.64041666667 | 13950 |
| 014117 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:53am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594577.8 | 509761.3 | 42985 | 1.64041666667 | 14117 |
| 013528 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:54am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594576.7 | 509763.7 | 42987 | 1.64041666667 | 13528 |
| 013242 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:55am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594575.0 | 509765.6 | 42989 | 1.64041666667 | 13242 |
| 013613 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:56am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594572.8 | 509767.8 | 42991 | 1.64041666667 | 13613 |
| 012705 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:57am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594571.2 | 509769.8 | 42993 | 1.64041666667 | 12705 |
| 014091 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:58am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594569.1 | 509772.0 | 42995 | 1.64041666667 | 14091 |
| 013926 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:59am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594567.8 | 509774.3 | 42997 | 1.64041666667 | 13926 |
| 014051 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:00am | Sensor | 1797-S0034-905-G-ACK | 6807.0 | 1594566.5 | 509776.9 | 42999 | 1.64041666667 | 14051 |
| 013626 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:01am | Sensor | 1797-S0034-905-G-ACK | 6807.1 | 1594565.2 | 509779.1 | 43001 | 1.64041666667 | 13626 |
| 012892 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:02am | Sensor | 1797-S0034-905-G-ACK | 6807.1 | 1594564.4 | 509781.5 | 43003 | 1.64041666667 | 12892 |
| 012914 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:03am | Sensor | 1797-S0034-905-G-ACK | 6807.0 | 1594563.4 | 509783.5 | 43005 | 1.64041666667 | 12914 |
| 013519 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:04am | Sensor | 1797-S0034-905-G-ACK | 6806.9 | 1594562.1 | 509786.2 | 43007 | 1.64041666667 | 13519 |
| 014047 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:05am | Sensor | 1797-S0034-905-G-ACK | 6806.9 | 1594561.6 | 509788.6 | 43009 | 1.64041666667 | 14047 |
| 014171 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:06am | Sensor | 1797-S0034-905-G-ACK | 6806.9 | 1594560.2 | 509791.2 | 43011 | 1.64041666667 | 14171 |
| 014498 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:07am | Sensor | 1797-S0034-905-G-ACK | 6807.0 | 1594560.0 | 509793.3 | 43013 | 1.64041666667 | 14498 |
| 014936 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:08am | Sensor | 1797-S0034-905-G-ACK | 6807.1 | 1594558.9 | 509795.3 | 43015 | 1.64041666667 | 14936 |
| 014379 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:09am | Sensor | 1797-S0034-905-G-ACK | 6807.2 | 1594558.5 | 509797.0 | 43017 | 1.64041666667 | 14379 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:10am | Sensor | 1797-S0034-905-G-ACK | 6807.2 | 1594557.6 | 509798.4 | 43019 | 1.64041666667 | 14246 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:11am | Sensor | 1797-S0034-905-G-ACK | 6807.1 | 1594556.7 | 509800.0 | 43021 | 1.64041666667 | 13953 |
| 013548 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:12am | Sensor | 1797-S0034-905-G-ACK | 6807.0 | 1594555.0 | 509801.5 | 43023 | 1.64041666667 | 13548 |
| 013846 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:13am | Sensor | 1797-S0034-905-G-ACK | 6807.0 | 1594553.5 | 509801.8 | 43025 | 1.64041666667 | 13846 |
| 014471 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:14am | Sensor | 1797-S0034-905-G-ACK | 6806.9 | 1594551.5 | 509801.7 | 43027 | 1.64041666667 | 14471 |
| 014140 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:15am | Sensor | 1797-S0034-905-G-ACK | 6806.9 | 1594549.3 | 509800.8 | 43029 | 1.64041666667 | 14140 |
| 013053 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:16am | Sensor | 1797-S0034-905-G-ACK | 6807.1 | 1594546.7 | 509800.1 | 43031 | 1.64041666667 | 13053 |
| 013410 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:17am | Sensor | 1797-S0034-905-G-ACK | 6807.0 | 1594545.3 | 509798.8 | 43033 | 1.64041666667 | 13410 |
| 013265 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:18am | Sensor | 1797-S0034-905-G-ACK | 6806.9 | 1594543.2 | 509797.6 | 43035 | 1.64041666667 | 13265 |
| 013199 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:19am | Sensor | 1797-S0034-905-G-ACK | 6806.8 | 1594541.8 | 509796.2 | 43037 | 1.64041666667 | 13199 |
| 013785 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:20am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594540.8 | 509794.1 | 43039 | 1.64041666667 | 13785 |
| 013176 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:21am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594539.6 | 509792.4 | 43041 | 1.64041666667 | 13176 |
| 012939 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:22am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594538.6 | 509790.2 | 43043 | 1.64041666667 | 12939 |
| 013188 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:23am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594537.2 | 509789.3 | 43045 | 1.64041666667 | 13188 |
| 012998 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:24am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594535.6 | 509787.7 | 43047 | 1.64041666667 | 12998 |
| 014024 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:25am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594533.6 | 509786.4 | 43049 | 1.64041666667 | 14024 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:26am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594531.1 | 509785.9 | 43051 | 1.64041666667 | 14556 |
| 015605 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:27am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594529.0 | 509784.9 | 43053 | 1.64041666667 | 15605 |
| 015775 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:28am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594526.5 | 509784.7 | 43055 | 1.64041666667 | 15775 |
| 015301 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:29am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594524.5 | 509784.0 | 43057 | 1.64041666667 | 15301 |
| 014899 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:30am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594522.0 | 509783.5 | 43059 | 1.64041666667 | 14899 |
| 015281 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:31am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594519.5 | 509783.2 | 43061 | 1.64041666667 | 15281 |
| 015150 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:32am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594516.9 | 509782.2 | 43063 | 1.64041666667 | 15150 |
| 014837 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:33am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594514.9 | 509781.8 | 43065 | 1.64041666667 | 14837 |
| 014308 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:34am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594512.5 | 509780.8 | 43067 | 1.64041666667 | 14308 |
| 013808 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:35am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594510.1 | 509780.1 | 43069 | 1.64041666667 | 13808 |
| 013729 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:36am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594507.3 | 509780.1 | 43071 | 1.64041666667 | 13729 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:37am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594505.1 | 509779.5 | 43073 | 1.64041666667 | 14210 |
| 015080 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:38am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594502.4 | 509779.4 | 43075 | 1.64041666667 | 15080 |
| 014865 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:39am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594500.1 | 509779.2 | 43077 | 1.64041666667 | 14865 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014467 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:40am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594496.9 | 509778.3 | 43079 | 1.64041666667 | 14467 |
| 014032 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:41am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594494.3 | 509778.0 | 43081 | 1.64041666667 | 14032 |
| 013346 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:42am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594491.4 | 509777.4 | 43083 | 1.64041666667 | 13346 |
| 014377 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:43am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594488.9 | 509776.5 | 43085 | 1.64041666667 | 14377 |
| 013599 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:44am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594485.9 | 509775.9 | 43087 | 1.64041666667 | 13599 |
| 013417 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:45am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594483.7 | 509775.1 | 43089 | 1.64041666667 | 13417 |
| 013764 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:46am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594481.0 | 509773.8 | 43091 | 1.64041666667 | 13764 |
| 013472 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:47am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594478.9 | 509773.8 | 43093 | 1.64041666667 | 13472 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:48am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594477.3 | 509772.8 | 43095 | 1.64041666667 | 13301 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:49am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594475.8 | 509771.4 | 43097 | 1.64041666667 | 13436 |
| 013303 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:50am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594473.5 | 509769.7 | 43099 | 1.64041666667 | 13303 |
| 013633 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:51am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594472.2 | 509767.8 | 43101 | 1.64041666667 | 13633 |
| 013473 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:52am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594470.4 | 509766.2 | 43103 | 1.64041666667 | 13473 |
| 014021 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:53am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594469.4 | 509764.4 | 43105 | 1.64041666667 | 14021 |
| 013347 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:54am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594467.7 | 509762.1 | 43107 | 1.64041666667 | 13347 |
| 012945 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:55am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594465.9 | 509761.0 | 43109 | 1.64041666667 | 12945 |
| 014271 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:56am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594463.7 | 509759.5 | 43111 | 1.64041666667 | 14271 |
| 013263 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:57am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594461.5 | 509758.6 | 43113 | 1.64041666667 | 13263 |
| 012762 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:58am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594459.9 | 509756.1 | 43115 | 1.64041666667 | 12762 |
| 013479 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:59am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594458.3 | 509755.0 | 43117 | 1.64041666667 | 13479 |
| 013057 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:00am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594457.7 | 509753.5 | 43119 | 1.64041666667 | 13057 |
| 013854 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:01am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594458.3 | 509751.5 | 43121 | 1.64041666667 | 13854 |
| 013493 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:02am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594458.8 | 509748.7 | 43123 | 1.64041666667 | 13493 |
| 012990 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:03am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594459.3 | 509746.8 | 43125 | 1.64041666667 | 12990 |
| 013111 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:04am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594459.0 | 509744.3 | 43127 | 1.64041666667 | 13111 |
| 012198 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:05am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594460.0 | 509743.0 | 43129 | 1.64041666667 | 12198 |
| 012231 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:06am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594462.0 | 509741.8 | 43131 | 1.64041666667 | 12231 |
| 012580 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:07am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594464.0 | 509741.5 | 43133 | 1.64041666667 | 12580 |
| 012806 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:08am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594466.3 | 509742.0 | 43135 | 1.64041666667 | 12806 |
| 012933 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:09am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594468.1 | 509742.1 | 43137 | 1.64041666667 | 12933 |
| 013620 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:10am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594470.2 | 509743.0 | 43139 | 1.64041666667 | 13620 |
| 013578 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:11am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594472.5 | 509743.3 | 43141 | 1.64041666667 | 13578 |
| 013293 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:12am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594475.2 | 509743.5 | 43143 | 1.64041666667 | 13293 |
| 013627 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:13am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594477.7 | 509744.1 | 43145 | 1.64041666667 | 13627 |
| 014542 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:14am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594480.0 | 509744.3 | 43147 | 1.64041666667 | 14542 |
| 014472 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:15am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594482.0 | 509745.4 | 43149 | 1.64041666667 | 14472 |
| 014928 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:16am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594484.1 | 509746.4 | 43151 | 1.64041666667 | 14928 |
| 014764 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:17am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594486.2 | 509747.1 | 43153 | 1.64041666667 | 14764 |
| 014185 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:18am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594488.4 | 509748.5 | 43155 | 1.64041666667 | 14185 |
| 014879 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:19am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594490.4 | 509749.5 | 43157 | 1.64041666667 | 14879 |
| 014984 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:20am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594492.5 | 509751.3 | 43159 | 1.64041666667 | 14984 |
| 014068 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:21am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594494.2 | 509752.5 | 43161 | 1.64041666667 | 14068 |
| 015128 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:22am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594496.4 | 509754.0 | 43163 | 1.64041666667 | 15128 |
| 015259 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:23am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594498.3 | 509755.5 | 43165 | 1.64041666667 | 15259 |
| 015056 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:24am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594500.8 | 509756.6 | 43167 | 1.64041666667 | 15056 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:25am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594502.5 | 509758.0 | 43169 | 1.64041666667 | 14626 |
| 014017 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:26am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594505.0 | 509759.5 | 43171 | 1.64041666667 | 14017 |
| 014402 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:27am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594507.1 | 509760.8 | 43173 | 1.64041666667 | 14402 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014408 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:28am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594509.0 | 509762.9 | 43175 | 1.64041666667 | 14408 |
| 015379 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:29am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594510.7 | 509764.3 | 43177 | 1.64041666667 | 15379 |
| 014178 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:30am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594512.3 | 509766.4 | 43179 | 1.64041666667 | 14178 |
| 013435 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:31am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594513.8 | 509768.1 | 43181 | 1.64041666667 | 13435 |
| 013520 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:32am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594516.3 | 509769.8 | 43183 | 1.64041666667 | 13520 |
| 012412 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:33am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594517.5 | 509771.4 | 43185 | 1.64041666667 | 12412 |
| 013387 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:34am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594519.4 | 509773.5 | 43187 | 1.64041666667 | 13387 |
| 013987 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:35am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594521.1 | 509775.3 | 43189 | 1.64041666667 | 13987 |
| 013995 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:36am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594523.5 | 509777.4 | 43191 | 1.64041666667 | 13995 |
| 014472 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:37am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594525.6 | 509778.3 | 43193 | 1.64041666667 | 14472 |
| 014643 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:38am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594528.4 | 509779.4 | 43195 | 1.64041666667 | 14643 |
| 014357 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:39am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594530.6 | 509779.0 | 43197 | 1.64041666667 | 14357 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:40am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594533.4 | 509778.0 | 43199 | 1.64041666667 | 14458 |
| 014253 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:41am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594535.7 | 509777.2 | 43201 | 1.64041666667 | 14253 |
| 014279 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:42am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594537.7 | 509775.3 | 43203 | 1.64041666667 | 14279 |
| 014505 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:43am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594539.5 | 509774.0 | 43205 | 1.64041666667 | 14505 |
| 014369 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:44am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594541.3 | 509772.3 | 43207 | 1.64041666667 | 14369 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:45am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594542.9 | 509771.2 | 43209 | 1.64041666667 | 14570 |
| 014585 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:46am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594545.4 | 509770.9 | 43211 | 1.64041666667 | 14585 |
| 014377 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:47am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594547.4 | 509770.8 | 43213 | 1.64041666667 | 14377 |
| 014664 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:48am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594549.9 | 509771.4 | 43215 | 1.64041666667 | 14664 |
| 014098 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:49am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594551.7 | 509771.3 | 43217 | 1.64041666667 | 14098 |
| 013675 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:50am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594554.0 | 509770.9 | 43219 | 1.64041666667 | 13675 |
| 013745 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:51am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594556.2 | 509769.8 | 43221 | 1.64041666667 | 13745 |
| 014369 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:52am | Sensor | 1797-S0034-905-G-ACK | 6806.7 | 1594557.8 | 509767.6 | 43223 | 1.64041666667 | 14369 |
| 014660 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:53am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594559.4 | 509765.7 | 43225 | 1.64041666667 | 14660 |
| 015446 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:54am | Sensor | 1797-S0034-905-G-ACK | 6806.6 | 1594560.0 | 509763.6 | 43227 | 1.64041666667 | 15446 |
| 014238 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:55am | Sensor | 1797-S0034-905-G-ACK | 6806.5 | 1594560.2 | 509761.6 | 43229 | 1.64041666667 | 14238 |
| 014429 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:56am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594559.1 | 509759.7 | 43231 | 1.64041666667 | 14429 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:57am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594557.3 | 509759.3 | 43233 | 1.64041666667 | 13861 |
| 014172 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:58am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594554.8 | 509758.4 | 43235 | 1.64041666667 | 14172 |
| 013761 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:59am | Sensor | 1797-S0034-905-G-ACK | 6806.4 | 1594552.5 | 509758.3 | 43237 | 1.64041666667 | 13761 |
| 014048 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:00am | Sensor | 1797-S0034-905-G-ACK | 6806.3 | 1594550.3 | 509757.4 | 43239 | 1.64041666667 | 14048 |
| 014502 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:01am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594548.2 | 509756.8 | 43241 | 1.64041666667 | 14502 |
| 013977 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:02am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594546.2 | 509755.5 | 43243 | 1.64041666667 | 13977 |
| 014319 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:03am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594544.1 | 509754.4 | 43245 | 1.64041666667 | 14319 |
| 014430 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:04am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594541.3 | 509753.8 | 43247 | 1.64041666667 | 14430 |
| 016509 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:05am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594539.5 | 509752.8 | 43249 | 1.64041666667 | 16509 |
| 015766 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:06am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594537.1 | 509751.8 | 43251 | 1.64041666667 | 15766 |
| 015596 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:07am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594535.0 | 509750.6 | 43253 | 1.64041666667 | 15596 |
| 015785 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:08am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594532.2 | 509749.1 | 43255 | 1.64041666667 | 15785 |
| 016754 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:09am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594530.0 | 509748.9 | 43257 | 1.64041666667 | 16754 |
| 016061 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:10am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594527.3 | 509748.3 | 43259 | 1.64041666667 | 16061 |
| 017479 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:11am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594525.0 | 509748.0 | 43261 | 1.64041666667 | 17479 |
| 016605 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:12am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594522.4 | 509748.1 | 43263 | 1.64041666667 | 16605 |
| 016495 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:13am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594520.2 | 509747.6 | 43265 | 1.64041666667 | 16495 |
| 016426 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:14am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594517.6 | 509747.4 | 43267 | 1.64041666667 | 16426 |
| 016492 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:15am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594515.6 | 509746.4 | 43269 | 1.64041666667 | 16492 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015149 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:16am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594513.1 | 509745.9 | 43271 | 1.64041666667 | 15149 |
| 015226 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:17am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594510.7 | 509745.3 | 43273 | 1.64041666667 | 15226 |
| 015472 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:18am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594508.6 | 509744.2 | 43275 | 1.64041666667 | 15472 |
| 014980 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:19am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594507.1 | 509743.5 | 43277 | 1.64041666667 | 14980 |
| 015296 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:20am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594505.9 | 509741.7 | 43279 | 1.64041666667 | 15296 |
| 014971 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:21am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594504.4 | 509740.2 | 43281 | 1.64041666667 | 14971 |
| 016296 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:22am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594502.8 | 509738.6 | 43283 | 1.64041666667 | 16296 |
| 016291 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:23am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594501.3 | 509737.1 | 43285 | 1.64041666667 | 16291 |
| 015291 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:24am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594499.3 | 509735.6 | 43287 | 1.64041666667 | 15291 |
| 015599 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:25am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594497.4 | 509733.9 | 43289 | 1.64041666667 | 15599 |
| 015539 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:26am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594495.2 | 509732.4 | 43291 | 1.64041666667 | 15539 |
| 015296 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:27am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594493.2 | 509731.2 | 43293 | 1.64041666667 | 15296 |
| 015219 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:28am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594490.9 | 509729.4 | 43295 | 1.64041666667 | 15219 |
| 015700 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:29am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594489.2 | 509728.4 | 43297 | 1.64041666667 | 15700 |
| 014846 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:30am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594486.8 | 509726.7 | 43299 | 1.64041666667 | 14846 |
| 015491 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:31am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594484.9 | 509725.7 | 43301 | 1.64041666667 | 15491 |
| 015493 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:32am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594482.7 | 509724.5 | 43303 | 1.64041666667 | 15493 |
| 014535 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:33am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594481.2 | 509723.2 | 43305 | 1.64041666667 | 14535 |
| 013733 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:34am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594479.2 | 509721.8 | 43307 | 1.64041666667 | 13733 |
| 014040 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:35am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594478.4 | 509720.3 | 43309 | 1.64041666667 | 14040 |
| 014835 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:36am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594477.6 | 509718.2 | 43311 | 1.64041666667 | 14835 |
| 014014 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:37am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594477.9 | 509716.3 | 43313 | 1.64041666667 | 14014 |
| 013860 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:38am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594478.5 | 509713.9 | 43315 | 1.64041666667 | 13860 |
| 014156 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:39am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594478.8 | 509711.9 | 43317 | 1.64041666667 | 14156 |
| 013640 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:40am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594479.3 | 509709.9 | 43319 | 1.64041666667 | 13640 |
| 014452 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:41am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594479.8 | 509708.1 | 43321 | 1.64041666667 | 14452 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:42am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594480.9 | 509706.8 | 43323 | 1.64041666667 | 14324 |
| 014537 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:43am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594482.4 | 509705.5 | 43325 | 1.64041666667 | 14537 |
| 014965 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:44am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594484.5 | 509705.6 | 43327 | 1.64041666667 | 14965 |
| 014920 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:45am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594486.5 | 509706.6 | 43329 | 1.64041666667 | 14920 |
| 015727 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:46am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594488.8 | 509707.8 | 43331 | 1.64041666667 | 15727 |
| 014944 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:47am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594490.6 | 509708.9 | 43333 | 1.64041666667 | 14944 |
| 015726 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:48am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594492.9 | 509709.5 | 43335 | 1.64041666667 | 15726 |
| 015618 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:49am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594494.9 | 509710.5 | 43337 | 1.64041666667 | 15618 |
| 014965 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:50am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594497.1 | 509710.8 | 43339 | 1.64041666667 | 14965 |
| 014905 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:51am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594499.5 | 509711.4 | 43341 | 1.64041666667 | 14905 |
| 015569 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:52am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594501.9 | 509712.6 | 43343 | 1.64041666667 | 15569 |
| 015395 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:53am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594504.1 | 509713.3 | 43345 | 1.64041666667 | 15395 |
| 014937 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:54am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594505.9 | 509714.9 | 43347 | 1.64041666667 | 14937 |
| 014454 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:55am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594507.9 | 509715.7 | 43349 | 1.64041666667 | 14454 |
| 014370 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:56am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594510.3 | 509717.0 | 43351 | 1.64041666667 | 14370 |
| 014338 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:57am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594512.6 | 509718.1 | 43353 | 1.64041666667 | 14338 |
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:58am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594515.2 | 509718.6 | 43355 | 1.64041666667 | 13518 |
| 014578 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:59am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594517.2 | 509719.7 | 43357 | 1.64041666667 | 14578 |
| 015438 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:00am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594519.8 | 509720.3 | 43359 | 1.64041666667 | 15438 |
| 016018 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:01am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594522.0 | 509720.9 | 43361 | 1.64041666667 | 16018 |
| 017563 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:02am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594524.7 | 509722.0 | 43363 | 1.64041666667 | 17563 |
| 018512 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:03am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594527.1 | 509722.4 | 43365 | 1.64041666667 | 18512 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 018783 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:04am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594529.2 | 509723.4 | 43367 | 1.64041666667 | 18783 |
| 019190 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:05am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594531.0 | 509723.8 | 43369 | 1.64041666667 | 19190 |
| 018699 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:06am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594532.5 | 509725.1 | 43371 | 1.64041666667 | 18699 |
| 018161 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:07am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594533.9 | 509726.5 | 43373 | 1.64041666667 | 18161 |
| 017948 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:08am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594535.7 | 509728.3 | 43375 | 1.64041666667 | 17948 |
| 016890 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:09am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594537.4 | 509729.6 | 43377 | 1.64041666667 | 16890 |
| 017091 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:10am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594539.5 | 509730.5 | 43379 | 1.64041666667 | 17091 |
| 015861 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:11am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594541.2 | 509731.7 | 43381 | 1.64041666667 | 15861 |
| 016519 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:12am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594541.9 | 509732.0 | 43383 | 1.64041666667 | 16519 |
| 015899 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:13am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594541.8 | 509732.1 | 43385 | 1.64041666667 | 15899 |
| 017516 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:14am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594542.6 | 509731.6 | 43387 | 1.64041666667 | 17516 |
| 017382 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:15am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594543.9 | 509732.4 | 43389 | 1.64041666667 | 17382 |
| 016362 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:16am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594544.9 | 509733.1 | 43391 | 1.64041666667 | 16362 |
| 016381 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:17am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594545.6 | 509732.9 | 43393 | 1.64041666667 | 16381 |
| 016257 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:18am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594547.3 | 509732.9 | 43395 | 1.64041666667 | 16257 |
| 016142 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:19am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594549.5 | 509732.9 | 43397 | 1.64041666667 | 16142 |
| 015447 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:20am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594552.1 | 509733.7 | 43399 | 1.64041666667 | 15447 |
| 014674 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:21am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594554.2 | 509734.4 | 43401 | 1.64041666667 | 14674 |
| 013699 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:22am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594557.1 | 509735.4 | 43403 | 1.64041666667 | 13699 |
| 014073 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:23am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594559.0 | 509736.8 | 43405 | 1.64041666667 | 14073 |
| 014336 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:24am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594561.4 | 509737.9 | 43407 | 1.64041666667 | 14336 |
| 014251 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:25am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594563.3 | 509738.7 | 43409 | 1.64041666667 | 14251 |
| 014016 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:26am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594565.9 | 509739.9 | 43411 | 1.64041666667 | 14016 |
| 013659 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:27am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594568.2 | 509740.3 | 43413 | 1.64041666667 | 13659 |
| 013991 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:28am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594571.0 | 509741.6 | 43415 | 1.64041666667 | 13991 |
| 013757 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:29am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594573.4 | 509742.8 | 43417 | 1.64041666667 | 13757 |
| 013986 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:30am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594576.0 | 509743.4 | 43419 | 1.64041666667 | 13986 |
| 013829 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:31am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594578.5 | 509744.1 | 43421 | 1.64041666667 | 13829 |
| 013944 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:32am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594581.3 | 509744.3 | 43423 | 1.64041666667 | 13944 |
| 014016 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:33am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594583.5 | 509744.0 | 43425 | 1.64041666667 | 14016 |
| 013981 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:34am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594586.4 | 509743.2 | 43427 | 1.64041666667 | 13981 |
| 014389 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:35am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594587.6 | 509741.3 | 43429 | 1.64041666667 | 14389 |
| 014821 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:36am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594588.4 | 509739.0 | 43431 | 1.64041666667 | 14821 |
| 014442 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:37am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594588.7 | 509736.8 | 43433 | 1.64041666667 | 14442 |
| 014236 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:38am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594589.0 | 509734.3 | 43435 | 1.64041666667 | 14236 |
| 013565 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:39am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594588.4 | 509732.4 | 43437 | 1.64041666667 | 13565 |
| 013870 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:40am | Sensor | 1797-S0034-905-G-ACK | 6806.2 | 1594586.8 | 509731.3 | 43439 | 1.64041666667 | 13870 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:41am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594584.9 | 509730.1 | 43441 | 1.64041666667 | 13742 |
| 014060 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:42am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594582.7 | 509729.3 | 43443 | 1.64041666667 | 14060 |
| 014913 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:43am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594580.4 | 509729.0 | 43445 | 1.64041666667 | 14913 |
| 014981 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:44am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594577.6 | 509728.1 | 43447 | 1.64041666667 | 14981 |
| 014839 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:45am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594575.5 | 509727.7 | 43449 | 1.64041666667 | 14839 |
| 015255 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:46am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594572.9 | 509727.1 | 43451 | 1.64041666667 | 15255 |
| 014925 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:47am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594570.7 | 509726.7 | 43453 | 1.64041666667 | 14925 |
| 013930 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:48am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594568.5 | 509726.4 | 43455 | 1.64041666667 | 13930 |
| 014428 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:49am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594566.3 | 509725.4 | 43457 | 1.64041666667 | 14428 |
| 014558 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:50am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594564.1 | 509725.1 | 43459 | 1.64041666667 | 14558 |
| 014249 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:51am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594562.1 | 509724.2 | 43461 | 1.64041666667 | 14249 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013692 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:52am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594559.9 | 509723.5 | 43463 | 1.64041666667 | 13692 |
| 013904 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:53am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594557.6 | 509723.0 | 43465 | 1.64041666667 | 13904 |
| 015059 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:54am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594555.3 | 509722.0 | 43467 | 1.64041666667 | 15059 |
| 015318 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:55am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594553.0 | 509721.5 | 43469 | 1.64041666667 | 15318 |
| 015959 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:56am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594551.6 | 509720.5 | 43471 | 1.64041666667 | 15959 |
| 016177 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:57am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594550.0 | 509720.4 | 43473 | 1.64041666667 | 16177 |
| 017237 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:58am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594548.1 | 509719.5 | 43475 | 1.64041666667 | 17237 |
| 018380 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:59am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594546.4 | 509719.2 | 43477 | 1.64041666667 | 18380 |
| 018979 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:00am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594544.6 | 509718.5 | 43479 | 1.64041666667 | 18979 |
| 019668 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:01am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594543.1 | 509718.4 | 43481 | 1.64041666667 | 19668 |
| 019178 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:02am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594541.9 | 509718.0 | 43483 | 1.64041666667 | 19178 |
| 020560 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:03am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594540.8 | 509718.0 | 43485 | 1.64041666667 | 20560 |
| 020370 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:04am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594540.4 | 509718.4 | 43487 | 1.64041666667 | 20370 |
| 020698 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:05am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594540.7 | 509718.4 | 43489 | 1.64041666667 | 20698 |
| 020523 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:06am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594540.1 | 509718.3 | 43491 | 1.64041666667 | 20523 |
| 020244 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:07am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594539.4 | 509717.7 | 43493 | 1.64041666667 | 20244 |
| 021062 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:08am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594538.3 | 509717.3 | 43495 | 1.64041666667 | 21062 |
| 020952 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:09am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594537.5 | 509716.0 | 43497 | 1.64041666667 | 20952 |
| 022623 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:10am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594535.8 | 509715.2 | 43499 | 1.64041666667 | 22623 |
| 021710 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:11am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594534.4 | 509714.7 | 43501 | 1.64041666667 | 21710 |
| 020117 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:12am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594533.6 | 509715.2 | 43503 | 1.64041666667 | 20117 |
| 019446 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:13am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594533.5 | 509715.4 | 43505 | 1.64041666667 | 19446 |
| 019586 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:14am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594533.5 | 509715.4 | 43507 | 1.64041666667 | 19586 |
| 019237 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:15am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594533.7 | 509714.9 | 43509 | 1.64041666667 | 19237 |
| 018793 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:16am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594532.8 | 509714.6 | 43511 | 1.64041666667 | 18793 |
| 019181 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:17am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594531.1 | 509713.6 | 43513 | 1.64041666667 | 19181 |
| 018972 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:18am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594528.7 | 509712.7 | 43515 | 1.64041666667 | 18972 |
| 018689 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:19am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594526.5 | 509711.9 | 43517 | 1.64041666667 | 18689 |
| 016415 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:20am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594523.9 | 509710.1 | 43519 | 1.64041666667 | 16415 |
| 017161 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:21am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594521.8 | 509709.5 | 43521 | 1.64041666667 | 17161 |
| 016035 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:22am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594519.5 | 509708.5 | 43523 | 1.64041666667 | 16035 |
| 014975 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:23am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594517.4 | 509707.6 | 43525 | 1.64041666667 | 14975 |
| 014596 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:24am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594514.8 | 509707.2 | 43527 | 1.64041666667 | 14596 |
| 014607 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:25am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594512.6 | 509706.3 | 43529 | 1.64041666667 | 14607 |
| 014464 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:26am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594510.1 | 509705.5 | 43531 | 1.64041666667 | 14464 |
| 014346 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:27am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594507.7 | 509705.2 | 43533 | 1.64041666667 | 14346 |
| 015615 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:28am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594504.8 | 509704.2 | 43535 | 1.64041666667 | 15615 |
| 015570 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:29am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594502.6 | 509704.0 | 43537 | 1.64041666667 | 15570 |
| 016386 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:30am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594499.9 | 509704.1 | 43539 | 1.64041666667 | 16386 |
| 015854 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:31am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594497.4 | 509703.7 | 43541 | 1.64041666667 | 15854 |
| 015098 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:32am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594494.8 | 509703.9 | 43543 | 1.64041666667 | 15098 |
| 015070 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:33am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594493.0 | 509703.3 | 43545 | 1.64041666667 | 15070 |
| 015587 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:34am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594491.1 | 509702.0 | 43547 | 1.64041666667 | 15587 |
| 015337 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:35am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594489.3 | 509700.6 | 43549 | 1.64041666667 | 15337 |
| 014852 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:36am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594488.0 | 509698.1 | 43551 | 1.64041666667 | 14852 |
| 014789 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:37am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594487.7 | 509696.0 | 43553 | 1.64041666667 | 14789 |
| 015474 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:38am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594488.2 | 509693.6 | 43555 | 1.64041666667 | 15474 |
| 014501 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:39am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594489.4 | 509691.9 | 43557 | 1.64041666667 | 14501 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014187 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:40am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594490.2 | 509689.7 | 43559 | 1.64041666667 | 14187 |
| 014002 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:41am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594491.3 | 509688.2 | 43561 | 1.64041666667 | 14002 |
| 014371 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:42am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594492.7 | 509686.3 | 43563 | 1.64041666667 | 14371 |
| 014361 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:43am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594494.0 | 509684.7 | 43565 | 1.64041666667 | 14361 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:44am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594496.0 | 509683.7 | 43567 | 1.64041666667 | 14550 |
| 013547 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:45am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594498.0 | 509683.1 | 43569 | 1.64041666667 | 13547 |
| 013957 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:46am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594500.6 | 509683.6 | 43571 | 1.64041666667 | 13957 |
| 014713 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:47am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594503.1 | 509684.4 | 43573 | 1.64041666667 | 14713 |
| 015229 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:48am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594506.0 | 509685.2 | 43575 | 1.64041666667 | 15229 |
| 015008 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:49am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594508.3 | 509686.0 | 43577 | 1.64041666667 | 15008 |
| 015380 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:50am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594511.1 | 509686.7 | 43579 | 1.64041666667 | 15380 |
| 015881 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:51am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594513.6 | 509687.4 | 43581 | 1.64041666667 | 15881 |
| 016463 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:52am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594516.3 | 509688.5 | 43583 | 1.64041666667 | 16463 |
| 016168 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:53am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594518.6 | 509688.9 | 43585 | 1.64041666667 | 16168 |
| 015724 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:54am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594521.2 | 509690.1 | 43587 | 1.64041666667 | 15724 |
| 015647 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:55am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594523.7 | 509691.4 | 43589 | 1.64041666667 | 15647 |
| 014891 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:56am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594526.5 | 509692.4 | 43591 | 1.64041666667 | 14891 |
| 014211 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:57am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594529.0 | 509693.6 | 43593 | 1.64041666667 | 14211 |
| 014669 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:58am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594531.8 | 509694.7 | 43595 | 1.64041666667 | 14669 |
| 014506 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:59am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594534.0 | 509695.4 | 43597 | 1.64041666667 | 14506 |
| 015540 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:00am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594536.4 | 509696.8 | 43599 | 1.64041666667 | 15540 |
| 015483 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:01am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594538.5 | 509697.1 | 43601 | 1.64041666667 | 15483 |
| 014852 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:02am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594540.9 | 509698.0 | 43603 | 1.64041666667 | 14852 |
| 015201 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:03am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594543.0 | 509699.2 | 43605 | 1.64041666667 | 15201 |
| 015818 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:04am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.6 | 509699.8 | 43607 | 1.64041666667 | 15818 |
| 016285 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:05am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594546.9 | 509701.2 | 43609 | 1.64041666667 | 16285 |
| 016630 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:06am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594548.8 | 509701.8 | 43611 | 1.64041666667 | 16630 |
| 016322 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:07am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594550.7 | 509702.4 | 43613 | 1.64041666667 | 16322 |
| 017176 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:08am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594552.0 | 509702.4 | 43615 | 1.64041666667 | 17176 |
| 017394 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:09am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594551.9 | 509702.4 | 43617 | 1.64041666667 | 17394 |
| 017239 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:10am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594552.7 | 509703.2 | 43619 | 1.64041666667 | 17239 |
| 017669 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:11am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594554.1 | 509704.1 | 43621 | 1.64041666667 | 17669 |
| 017679 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:12am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594556.0 | 509705.1 | 43623 | 1.64041666667 | 17679 |
| 017002 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:13am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594557.8 | 509705.5 | 43625 | 1.64041666667 | 17002 |
| 016381 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:14am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594560.0 | 509706.6 | 43627 | 1.64041666667 | 16381 |
| 014614 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:15am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594561.9 | 509707.1 | 43629 | 1.64041666667 | 14614 |
| 015128 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:16am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594564.4 | 509707.8 | 43631 | 1.64041666667 | 15128 |
| 014854 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:17am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594566.8 | 509708.5 | 43633 | 1.64041666667 | 14854 |
| 014513 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:18am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594569.3 | 509708.8 | 43635 | 1.64041666667 | 14513 |
| 014598 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:19am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594571.6 | 509709.6 | 43637 | 1.64041666667 | 14598 |
| 014061 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:20am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594574.1 | 509710.3 | 43639 | 1.64041666667 | 14061 |
| 014479 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:21am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594576.4 | 509711.1 | 43641 | 1.64041666667 | 14479 |
| 014190 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:22am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594579.2 | 509712.1 | 43643 | 1.64041666667 | 14190 |
| 014131 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:23am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594581.2 | 509712.2 | 43645 | 1.64041666667 | 14131 |
| 014309 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:24am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594583.6 | 509713.2 | 43647 | 1.64041666667 | 14309 |
| 013538 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:25am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594585.8 | 509713.6 | 43649 | 1.64041666667 | 13538 |
| 014823 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:26am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594588.2 | 509714.2 | 43651 | 1.64041666667 | 14823 |
| 014803 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:27am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594590.6 | 509715.1 | 43653 | 1.64041666667 | 14803 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014619 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:28am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594593.2 | 509715.5 | 43655 | 1.64041666667 | 14619 |
| 014185 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:29am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594595.3 | 509716.3 | 43657 | 1.64041666667 | 14185 |
| 013762 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:30am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594597.4 | 509716.3 | 43659 | 1.64041666667 | 13762 |
| 013936 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:31am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594599.1 | 509715.9 | 43661 | 1.64041666667 | 13936 |
| 013711 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:32am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594599.6 | 509714.5 | 43663 | 1.64041666667 | 13711 |
| 013643 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:33am | Sensor | 1797-S0034-905-G-ACK | 6806.1 | 1594599.0 | 509712.6 | 43665 | 1.64041666667 | 13643 |
| 014448 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:34am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594598.1 | 509710.5 | 43667 | 1.64041666667 | 14448 |
| 014232 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:35am | Sensor | 1797-S0034-905-G-ACK | 6806.0 | 1594596.5 | 509709.4 | 43669 | 1.64041666667 | 14232 |
| 013983 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:36am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594594.7 | 509707.9 | 43671 | 1.64041666667 | 13983 |
| 014405 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:37am | Sensor | 1797-S0034-905-G-ACK | 6805.9 | 1594593.0 | 509707.3 | 43673 | 1.64041666667 | 14405 |
| 013893 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:38am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594590.7 | 509706.2 | 43675 | 1.64041666667 | 13893 |
| 014175 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:39am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594588.7 | 509705.4 | 43677 | 1.64041666667 | 14175 |
| 013463 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:40am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594586.3 | 509705.3 | 43679 | 1.64041666667 | 13463 |
| 014653 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:41am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594584.0 | 509704.8 | 43681 | 1.64041666667 | 14653 |
| 014985 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:42am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594581.9 | 509705.2 | 43683 | 1.64041666667 | 14985 |
| 014969 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:43am | Sensor | 1797-S0034-905-G-ACK | 6805.8 | 1594579.8 | 509705.1 | 43685 | 1.64041666667 | 14969 |
| 014870 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:44am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594577.5 | 509704.6 | 43687 | 1.64041666667 | 14870 |
| 015451 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:45am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594575.6 | 509703.7 | 43689 | 1.64041666667 | 15451 |
| 015374 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:46am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594573.5 | 509702.3 | 43691 | 1.64041666667 | 15374 |
| 015442 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:47am | Sensor | 1797-S0034-905-G-ACK | 6805.7 | 1594571.6 | 509701.5 | 43693 | 1.64041666667 | 15442 |
| 015264 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:48am | Sensor | 1797-S0034-905-G-ACK | 6805.6 | 1594569.3 | 509700.1 | 43695 | 1.64041666667 | 15264 |
| 015418 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:49am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594567.1 | 509698.9 | 43697 | 1.64041666667 | 15418 |
| 015798 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:50am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594564.7 | 509698.3 | 43699 | 1.64041666667 | 15798 |
| 015223 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:51am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594562.5 | 509697.3 | 43701 | 1.64041666667 | 15223 |
| 014991 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:52am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594560.3 | 509697.0 | 43703 | 1.64041666667 | 14991 |
| 015437 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:53am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594558.4 | 509696.4 | 43705 | 1.64041666667 | 15437 |
| 015733 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:54am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594556.0 | 509695.8 | 43707 | 1.64041666667 | 15733 |
| 016312 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:55am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594553.8 | 509695.2 | 43709 | 1.64041666667 | 16312 |
| 015761 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:56am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594551.5 | 509694.1 | 43711 | 1.64041666667 | 15761 |
| 016358 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:57am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594549.4 | 509693.7 | 43713 | 1.64041666667 | 16358 |
| 016244 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:58am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594546.9 | 509692.5 | 43715 | 1.64041666667 | 16244 |
| 015962 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:59am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594544.7 | 509691.3 | 43717 | 1.64041666667 | 15962 |
| 014918 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:00am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594542.4 | 509690.2 | 43719 | 1.64041666667 | 14918 |
| 014219 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:01am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594540.9 | 509688.8 | 43721 | 1.64041666667 | 14219 |
| 014943 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:02am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594538.9 | 509687.4 | 43723 | 1.64041666667 | 14943 |
| 015808 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:03am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594537.4 | 509686.1 | 43725 | 1.64041666667 | 15808 |
| 015019 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:04am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594535.2 | 509684.9 | 43727 | 1.64041666667 | 15019 |
| 015956 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:05am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594532.7 | 509684.4 | 43729 | 1.64041666667 | 15956 |
| 016310 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:06am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594530.7 | 509683.1 | 43731 | 1.64041666667 | 16310 |
| 014949 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:07am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594528.7 | 509682.4 | 43733 | 1.64041666667 | 14949 |
| 015061 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:08am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594526.6 | 509681.0 | 43735 | 1.64041666667 | 15061 |
| 014779 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:09am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594524.9 | 509679.9 | 43737 | 1.64041666667 | 14779 |
| 014748 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:10am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594522.8 | 509678.9 | 43739 | 1.64041666667 | 14748 |
| 015443 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:11am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594521.5 | 509677.5 | 43741 | 1.64041666667 | 15443 |
| 016202 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:12am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594519.8 | 509676.3 | 43743 | 1.64041666667 | 16202 |
| 015608 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:13am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594518.4 | 509674.8 | 43745 | 1.64041666667 | 15608 |
| 016647 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:14am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594516.4 | 509673.7 | 43747 | 1.64041666667 | 16647 |
| 015274 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:15am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594514.6 | 509672.8 | 43749 | 1.64041666667 | 15274 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015386 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:16am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594512.2 | 509671.4 | 43751 | 1.64041666667 | 15386 |
| 015247 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:17am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594510.3 | 509670.8 | 43753 | 1.64041666667 | 15247 |
| 014209 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:18am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594508.2 | 509669.4 | 43755 | 1.64041666667 | 14209 |
| 015072 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:19am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594506.4 | 509668.7 | 43757 | 1.64041666667 | 15072 |
| 014838 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:20am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594504.4 | 509667.4 | 43759 | 1.64041666667 | 14838 |
| 014399 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:21am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594502.5 | 509666.2 | 43761 | 1.64041666667 | 14399 |
| 014444 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:22am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594499.9 | 509665.3 | 43763 | 1.64041666667 | 14444 |
| 014717 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:23am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594497.7 | 509664.1 | 43765 | 1.64041666667 | 14717 |
| 015336 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:24am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594495.1 | 509663.6 | 43767 | 1.64041666667 | 15336 |
| 015489 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:25am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594492.6 | 509662.9 | 43769 | 1.64041666667 | 15489 |
| 014915 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:26am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594490.1 | 509662.1 | 43771 | 1.64041666667 | 14915 |
| 015319 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:27am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594487.6 | 509661.3 | 43773 | 1.64041666667 | 15319 |
| 014752 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:28am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594485.0 | 509659.7 | 43775 | 1.64041666667 | 14752 |
| 014298 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:29am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594483.0 | 509658.8 | 43777 | 1.64041666667 | 14298 |
| 015122 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:30am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594481.0 | 509657.2 | 43779 | 1.64041666667 | 15122 |
| 015129 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:31am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594478.8 | 509655.5 | 43781 | 1.64041666667 | 15129 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:32am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594476.2 | 509654.6 | 43783 | 1.64041666667 | 14067 |
| 014120 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:33am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594474.0 | 509653.8 | 43785 | 1.64041666667 | 14120 |
| 014085 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:34am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594471.4 | 509653.7 | 43787 | 1.64041666667 | 14085 |
| 013555 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:35am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594469.2 | 509653.3 | 43789 | 1.64041666667 | 13555 |
| 013805 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:36am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594466.3 | 509652.3 | 43791 | 1.64041666667 | 13805 |
| 013907 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:37am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594464.0 | 509651.8 | 43793 | 1.64041666667 | 13907 |
| 014663 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:38am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594461.5 | 509650.8 | 43795 | 1.64041666667 | 14663 |
| 014083 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:39am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594459.3 | 509650.0 | 43797 | 1.64041666667 | 14083 |
| 013921 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:40am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594456.4 | 509649.4 | 43799 | 1.64041666667 | 13921 |
| 014228 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:41am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594454.0 | 509648.5 | 43801 | 1.64041666667 | 14228 |
| 014521 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:42am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594451.6 | 509647.1 | 43803 | 1.64041666667 | 14521 |
| 014153 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:43am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594449.0 | 509646.4 | 43805 | 1.64041666667 | 14153 |
| 015086 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:44am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594446.4 | 509645.5 | 43807 | 1.64041666667 | 15086 |
| 015033 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:45am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594444.3 | 509644.1 | 43809 | 1.64041666667 | 15033 |
| 014388 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:46am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594442.2 | 509642.4 | 43811 | 1.64041666667 | 14388 |
| 015743 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:47am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594441.0 | 509640.4 | 43813 | 1.64041666667 | 15743 |
| 016985 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:48am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594439.5 | 509638.0 | 43815 | 1.64041666667 | 16985 |
| 018014 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:49am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594437.7 | 509636.1 | 43817 | 1.64041666667 | 18014 |
| 017940 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:50am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594435.8 | 509633.6 | 43819 | 1.64041666667 | 17940 |
| 017831 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:51am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594434.2 | 509631.6 | 43821 | 1.64041666667 | 17831 |
| 017785 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:52am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594432.2 | 509630.0 | 43823 | 1.64041666667 | 17785 |
| 016551 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:53am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594431.1 | 509628.0 | 43825 | 1.64041666667 | 16551 |
| 017253 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:54am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594429.8 | 509625.8 | 43827 | 1.64041666667 | 17253 |
| 016904 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:55am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594427.6 | 509624.2 | 43829 | 1.64041666667 | 16904 |
| 017961 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:56am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594425.1 | 509622.8 | 43831 | 1.64041666667 | 17961 |
| 018570 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:57am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594422.9 | 509621.4 | 43833 | 1.64041666667 | 18570 |
| 017646 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:58am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594420.3 | 509620.1 | 43835 | 1.64041666667 | 17646 |
| 017201 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:59am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594418.1 | 509619.2 | 43837 | 1.64041666667 | 17201 |
| 017783 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:00am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594416.0 | 509617.5 | 43839 | 1.64041666667 | 17783 |
| 018403 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:01am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594413.9 | 509616.4 | 43841 | 1.64041666667 | 18403 |
| 018931 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:02am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594411.4 | 509615.1 | 43843 | 1.64041666667 | 18931 |
| 018554 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:03am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594409.1 | 509613.8 | 43845 | 1.64041666667 | 18554 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016901 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:04am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594406.0 | 509613.0 | 43847 | 1.64041666667 | 16901 |
| 016032 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:05am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594403.9 | 509612.1 | 43849 | 1.64041666667 | 16032 |
| 014605 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:06am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594401.3 | 509609.9 | 43851 | 1.64041666667 | 14605 |
| 014215 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:07am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594399.2 | 509608.4 | 43853 | 1.64041666667 | 14215 |
| 013591 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:08am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594396.4 | 509607.6 | 43855 | 1.64041666667 | 13591 |
| 013667 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:09am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594393.6 | 509607.0 | 43857 | 1.64041666667 | 13667 |
| 014903 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:10am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594390.2 | 509606.2 | 43859 | 1.64041666667 | 14903 |
| 013805 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:11am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594387.7 | 509606.1 | 43861 | 1.64041666667 | 13805 |
| 013690 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:12am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594385.0 | 509605.3 | 43863 | 1.64041666667 | 13690 |
| 013123 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:13am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594382.3 | 509604.5 | 43865 | 1.64041666667 | 13123 |
| 013997 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:14am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594379.5 | 509604.3 | 43867 | 1.64041666667 | 13997 |
| 014383 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:15am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594377.1 | 509603.9 | 43869 | 1.64041666667 | 14383 |
| 014690 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:16am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594374.4 | 509603.7 | 43871 | 1.64041666667 | 14690 |
| 015036 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:17am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594372.0 | 509603.3 | 43873 | 1.64041666667 | 15036 |
| 015312 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:18am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594369.4 | 509602.0 | 43875 | 1.64041666667 | 15312 |
| 014523 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:19am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594367.1 | 509601.1 | 43877 | 1.64041666667 | 14523 |
| 014739 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:20am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594364.1 | 509600.6 | 43879 | 1.64041666667 | 14739 |
| 014141 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:21am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594361.5 | 509599.9 | 43881 | 1.64041666667 | 14141 |
| 013069 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:22am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594358.5 | 509599.4 | 43883 | 1.64041666667 | 13069 |
| 014904 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:23am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594356.0 | 509599.4 | 43885 | 1.64041666667 | 14904 |
| 015156 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:24am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594352.8 | 509598.8 | 43887 | 1.64041666667 | 15156 |
| 014412 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:25am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594350.4 | 509598.8 | 43889 | 1.64041666667 | 14412 |
| 014047 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:26am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594347.5 | 509599.6 | 43891 | 1.64041666667 | 14047 |
| 014089 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:27am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594344.8 | 509599.9 | 43893 | 1.64041666667 | 14089 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:28am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594341.4 | 509599.6 | 43895 | 1.64041666667 | 13595 |
| 013819 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:29am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594338.7 | 509599.5 | 43897 | 1.64041666667 | 13819 |
| 013286 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:30am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594335.5 | 509599.6 | 43899 | 1.64041666667 | 13286 |
| 014103 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:31am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594332.7 | 509599.5 | 43901 | 1.64041666667 | 14103 |
| 013978 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:32am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594329.5 | 509599.1 | 43903 | 1.64041666667 | 13978 |
| 014942 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:33am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594326.7 | 509598.8 | 43905 | 1.64041666667 | 14942 |
| 015110 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:34am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594323.5 | 509598.6 | 43907 | 1.64041666667 | 15110 |
| 015362 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:35am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594320.8 | 509598.1 | 43909 | 1.64041666667 | 15362 |
| 014146 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:36am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594317.7 | 509597.2 | 43911 | 1.64041666667 | 14146 |
| 014062 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:37am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594315.1 | 509596.4 | 43913 | 1.64041666667 | 14062 |
| 014705 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:38am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594312.0 | 509595.8 | 43915 | 1.64041666667 | 14705 |
| 013109 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:39am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594309.5 | 509595.3 | 43917 | 1.64041666667 | 13109 |
| 013013 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:40am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594306.6 | 509594.7 | 43919 | 1.64041666667 | 13013 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:41am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594304.2 | 509594.3 | 43921 | 1.64041666667 | 13560 |
| 013995 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:42am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594301.4 | 509594.7 | 43923 | 1.64041666667 | 13995 |
| 014517 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:43am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594298.6 | 509595.1 | 43925 | 1.64041666667 | 14517 |
| 014331 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:44am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594295.8 | 509594.6 | 43927 | 1.64041666667 | 14331 |
| 014563 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:45am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594293.5 | 509593.6 | 43929 | 1.64041666667 | 14563 |
| 014874 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:46am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594290.7 | 509592.3 | 43931 | 1.64041666667 | 14874 |
| 014779 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:47am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594288.5 | 509591.2 | 43933 | 1.64041666667 | 14779 |
| 014561 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:48am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594285.9 | 509589.5 | 43935 | 1.64041666667 | 14561 |
| 014018 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:49am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594283.4 | 509588.3 | 43937 | 1.64041666667 | 14018 |
| 014162 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:50am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594280.4 | 509587.0 | 43939 | 1.64041666667 | 14162 |
| 014679 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:51am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594277.9 | 509585.7 | 43941 | 1.64041666667 | 14679 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014654 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:52am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594274.7 | 509584.5 | 43943 | 1.64041666667 | 14654 |
| 014138 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:53am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594271.9 | 509583.9 | 43945 | 1.64041666667 | 14138 |
| 014410 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:54am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594268.6 | 509583.3 | 43947 | 1.64041666667 | 14410 |
| 014278 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:55am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594266.2 | 509582.5 | 43949 | 1.64041666667 | 14278 |
| 013529 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:56am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594263.1 | 509581.4 | 43951 | 1.64041666667 | 13529 |
| 014030 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:57am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594260.5 | 509580.7 | 43953 | 1.64041666667 | 14030 |
| 014267 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:58am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594257.5 | 509579.9 | 43955 | 1.64041666667 | 14267 |
| 014392 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:59am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594255.1 | 509578.9 | 43957 | 1.64041666667 | 14392 |
| 014291 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:00am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594252.0 | 509577.6 | 43959 | 1.64041666667 | 14291 |
| 015583 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:01am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594249.6 | 509576.7 | 43961 | 1.64041666667 | 15583 |
| 014285 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:02am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594246.5 | 509576.0 | 43963 | 1.64041666667 | 14285 |
| 013443 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:03am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594243.9 | 509575.4 | 43965 | 1.64041666667 | 13443 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:04am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594240.7 | 509574.7 | 43967 | 1.64041666667 | 13442 |
| 013756 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:05am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594238.3 | 509574.6 | 43969 | 1.64041666667 | 13756 |
| 014435 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:06am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594235.1 | 509574.8 | 43971 | 1.64041666667 | 14435 |
| 014434 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:07am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594232.4 | 509574.8 | 43973 | 1.64041666667 | 14434 |
| 014547 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:08am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594229.2 | 509574.3 | 43975 | 1.64041666667 | 14547 |
| 014100 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:09am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594226.5 | 509573.8 | 43977 | 1.64041666667 | 14100 |
| 014261 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:10am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594223.5 | 509573.5 | 43979 | 1.64041666667 | 14261 |
| 015042 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:11am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594220.8 | 509573.3 | 43981 | 1.64041666667 | 15042 |
| 015781 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:12am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594217.7 | 509572.6 | 43983 | 1.64041666667 | 15781 |
| 016346 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:13am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594215.1 | 509572.2 | 43985 | 1.64041666667 | 16346 |
| 016177 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:14am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594212.4 | 509572.0 | 43987 | 1.64041666667 | 16177 |
| 016210 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:15am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594209.8 | 509571.4 | 43989 | 1.64041666667 | 16210 |
| 016438 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:16am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594206.9 | 509570.3 | 43991 | 1.64041666667 | 16438 |
| 015666 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:17am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594204.7 | 509569.5 | 43993 | 1.64041666667 | 15666 |
| 015277 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:18am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594202.0 | 509568.9 | 43995 | 1.64041666667 | 15277 |
| 015186 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:19am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594199.7 | 509568.0 | 43997 | 1.64041666667 | 15186 |
| 015157 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:20am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594196.8 | 509566.5 | 43999 | 1.64041666667 | 15157 |
| 016033 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:21am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594194.4 | 509565.6 | 44001 | 1.64041666667 | 16033 |
| 015626 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:22am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594191.7 | 509565.0 | 44003 | 1.64041666667 | 15626 |
| 015675 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:23am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594189.4 | 509564.3 | 44005 | 1.64041666667 | 15675 |
| 015597 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:24am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594186.8 | 509563.8 | 44007 | 1.64041666667 | 15597 |
| 015688 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:25am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594184.9 | 509563.9 | 44009 | 1.64041666667 | 15688 |
| 015462 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:26am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594182.6 | 509563.4 | 44011 | 1.64041666667 | 15462 |
| 017645 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:27am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594180.6 | 509562.9 | 44013 | 1.64041666667 | 17645 |
| 017207 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:28am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594178.3 | 509562.5 | 44015 | 1.64041666667 | 17207 |
| 017764 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:29am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594177.4 | 509562.3 | 44017 | 1.64041666667 | 17764 |
| 018310 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:30am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594177.2 | 509562.3 | 44019 | 1.64041666667 | 18310 |
| 017807 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:31am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594177.2 | 509562.4 | 44021 | 1.64041666667 | 17807 |
| 018453 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:32am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594177.2 | 509562.3 | 44023 | 1.64041666667 | 18453 |
| 018367 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:33am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594177.3 | 509562.3 | 44025 | 1.64041666667 | 18367 |
| 018499 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:34am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594177.3 | 509561.8 | 44027 | 1.64041666667 | 18499 |
| 018528 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:35am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594176.6 | 509561.7 | 44029 | 1.64041666667 | 18528 |
| 019204 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:36am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594175.3 | 509561.1 | 44031 | 1.64041666667 | 19204 |
| 019367 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:37am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594174.7 | 509561.0 | 44033 | 1.64041666667 | 19367 |
| 019646 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:38am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594174.2 | 509561.5 | 44035 | 1.64041666667 | 19646 |
| 019578 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:39am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594174.2 | 509561.4 | 44037 | 1.64041666667 | 19578 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019405 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:40am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594174.6 | 509560.9 | 44039 | 1.64041666667 | 19405 |
| 020215 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:41am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594174.4 | 509561.2 | 44041 | 1.64041666667 | 20215 |
| 020498 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:42am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594174.2 | 509561.6 | 44043 | 1.64041666667 | 20498 |
| 020575 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:43am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594174.5 | 509561.3 | 44045 | 1.64041666667 | 20575 |
| 022006 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:44am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594174.7 | 509561.0 | 44047 | 1.64041666667 | 22006 |
| 021498 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:45am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594174.8 | 509560.9 | 44081 | 1.64041666667 | 21498 |
| 020032 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:12am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594140.7 | 509562.8 | 44083 | 1.64041666667 | 20032 |
| 020193 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:13am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594142.9 | 509564.1 | 44085 | 1.64041666667 | 20193 |
| 019848 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:14am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594144.8 | 509564.6 | 44087 | 1.64041666667 | 19848 |
| 020240 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:15am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594147.0 | 509565.7 | 44089 | 1.64041666667 | 20240 |
| 019845 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:16am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594149.1 | 509567.4 | 44091 | 1.64041666667 | 19845 |
| 020635 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:17am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594152.0 | 509568.5 | 44093 | 1.64041666667 | 20635 |
| 021117 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:18am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594155.2 | 509568.5 | 44095 | 1.64041666667 | 21117 |
| 021651 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:19am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594158.0 | 509569.1 | 44097 | 1.64041666667 | 21651 |
| 021718 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:20am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594160.9 | 509570.4 | 44099 | 1.64041666667 | 21718 |
| 022769 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:21am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594163.6 | 509572.4 | 44101 | 1.64041666667 | 22769 |
| 023097 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:22am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594165.7 | 509574.6 | 44103 | 1.64041666667 | 23097 |
| 023147 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:23am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594167.4 | 509576.9 | 44105 | 1.64041666667 | 23147 |
| 022575 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:24am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594169.5 | 509579.5 | 44107 | 1.64041666667 | 22575 |
| 021578 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:25am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594171.5 | 509581.8 | 44109 | 1.64041666667 | 21578 |
| 022023 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:26am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594174.0 | 509584.3 | 44111 | 1.64041666667 | 22023 |
| 020758 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:27am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594176.8 | 509586.5 | 44113 | 1.64041666667 | 20758 |
| 020166 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:28am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594178.9 | 509588.0 | 44115 | 1.64041666667 | 20166 |
| 019361 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:29am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594180.7 | 509589.4 | 44117 | 1.64041666667 | 19361 |
| 018518 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:30am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594182.5 | 509590.2 | 44119 | 1.64041666667 | 18518 |
| 016521 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:31am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594184.4 | 509591.5 | 44121 | 1.64041666667 | 16521 |
| 016845 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:32am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594186.5 | 509593.5 | 44123 | 1.64041666667 | 16845 |
| 016270 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:33am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594188.2 | 509595.3 | 44125 | 1.64041666667 | 16270 |
| 015879 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:34am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594189.8 | 509596.4 | 44127 | 1.64041666667 | 15879 |
| 015510 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:35am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594190.6 | 509596.5 | 44129 | 1.64041666667 | 15510 |
| 015466 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:36am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594190.8 | 509596.6 | 44131 | 1.64041666667 | 15466 |
| 015937 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:37am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594191.2 | 509596.8 | 44133 | 1.64041666667 | 15937 |
| 016967 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:38am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594193.0 | 509598.3 | 44135 | 1.64041666667 | 16967 |
| 016811 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:39am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594195.3 | 509599.7 | 44137 | 1.64041666667 | 16811 |
| 016739 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:40am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594197.9 | 509601.3 | 44139 | 1.64041666667 | 16739 |
| 016000 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:41am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594200.4 | 509602.5 | 44141 | 1.64041666667 | 16000 |
| 015750 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:42am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594203.9 | 509604.2 | 44143 | 1.64041666667 | 15750 |
| 015437 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:43am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594207.2 | 509605.6 | 44145 | 1.64041666667 | 15437 |
| 015321 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:44am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594211.0 | 509606.7 | 44147 | 1.64041666667 | 15321 |
| 014303 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:45am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594215.0 | 509607.7 | 44149 | 1.64041666667 | 14303 |
| 014585 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:46am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594219.1 | 509608.6 | 44151 | 1.64041666667 | 14585 |
| 014219 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:47am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594222.7 | 509609.4 | 44153 | 1.64041666667 | 14219 |
| 015288 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:48am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594226.7 | 509610.6 | 44155 | 1.64041666667 | 15288 |
| 015447 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:49am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594230.2 | 509611.7 | 44157 | 1.64041666667 | 15447 |
| 015289 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:50am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594234.4 | 509612.8 | 44159 | 1.64041666667 | 15289 |
| 016835 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:51am | Sensor | 1797-S0034-905-G-ACK | 6803.1 | 1594237.5 | 509613.7 | 44161 | 1.64041666667 | 16835 |
| 015807 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:52am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594241.4 | 509614.9 | 44163 | 1.64041666667 | 15807 |
| 014921 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:53am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594245.2 | 509615.9 | 44165 | 1.64041666667 | 14921 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014340 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:54am | Sensor | 1797-S0034-905-G-ACK | 6803.1 | 1594249.1 | 509616.7 | 44167 | 1.64041666667 | 14340 |
| 014674 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:55am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594252.9 | 509617.2 | 44169 | 1.64041666667 | 14674 |
| 015499 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:56am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594257.0 | 509617.7 | 44171 | 1.64041666667 | 15499 |
| 014688 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:57am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594260.7 | 509618.3 | 44173 | 1.64041666667 | 14688 |
| 014224 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:58am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594264.8 | 509619.2 | 44175 | 1.64041666667 | 14224 |
| 013986 | 0 | GeoXH 6000 | 08/18/2015 | 11:39:59am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594268.2 | 509620.1 | 44177 | 1.64041666667 | 13986 |
| 013785 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:00am | Sensor | 1797-S0034-905-G-ACK | 6802.9 | 1594272.5 | 509620.8 | 44179 | 1.64041666667 | 13785 |
| 014466 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:01am | Sensor | 1797-S0034-905-G-ACK | 6802.9 | 1594276.0 | 509620.5 | 44181 | 1.64041666667 | 14466 |
| 015495 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:02am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594280.1 | 509619.6 | 44183 | 1.64041666667 | 15495 |
| 014798 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:03am | Sensor | 1797-S0034-905-G-ACK | 6803.1 | 1594283.4 | 509618.7 | 44185 | 1.64041666667 | 14798 |
| 015216 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:04am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594287.3 | 509617.8 | 44187 | 1.64041666667 | 15216 |
| 015361 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:05am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594290.9 | 509617.4 | 44189 | 1.64041666667 | 15361 |
| 014573 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:06am | Sensor | 1797-S0034-905-G-ACK | 6802.9 | 1594294.5 | 509617.4 | 44191 | 1.64041666667 | 14573 |
| 014662 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:07am | Sensor | 1797-S0034-905-G-ACK | 6802.9 | 1594297.6 | 509617.7 | 44193 | 1.64041666667 | 14662 |
| 015297 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:08am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594301.3 | 509618.5 | 44195 | 1.64041666667 | 15297 |
| 015355 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:09am | Sensor | 1797-S0034-905-G-ACK | 6802.9 | 1594304.7 | 509619.4 | 44197 | 1.64041666667 | 15355 |
| 014764 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:10am | Sensor | 1797-S0034-905-G-ACK | 6802.9 | 1594309.0 | 509620.2 | 44199 | 1.64041666667 | 14764 |
| 015557 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:11am | Sensor | 1797-S0034-905-G-ACK | 6802.9 | 1594312.5 | 509620.6 | 44201 | 1.64041666667 | 15557 |
| 015411 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:12am | Sensor | 1797-S0034-905-G-ACK | 6803.1 | 1594316.6 | 509620.7 | 44203 | 1.64041666667 | 15411 |
| 014886 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:13am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594320.4 | 509620.3 | 44205 | 1.64041666667 | 14886 |
| 015371 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:14am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594324.4 | 509619.9 | 44207 | 1.64041666667 | 15371 |
| 016086 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:15am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594328.3 | 509619.9 | 44209 | 1.64041666667 | 16086 |
| 016076 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:16am | Sensor | 1797-S0034-905-G-ACK | 6802.9 | 1594332.4 | 509620.5 | 44211 | 1.64041666667 | 16076 |
| 015380 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:17am | Sensor | 1797-S0034-905-G-ACK | 6803.0 | 1594335.6 | 509622.0 | 44213 | 1.64041666667 | 15380 |
| 014036 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:18am | Sensor | 1797-S0034-905-G-ACK | 6803.1 | 1594338.7 | 509624.0 | 44215 | 1.64041666667 | 14036 |
| 014540 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:19am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594342.1 | 509625.6 | 44217 | 1.64041666667 | 14540 |
| 015011 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:20am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594345.6 | 509626.2 | 44219 | 1.64041666667 | 15011 |
| 014541 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:21am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594349.1 | 509625.9 | 44221 | 1.64041666667 | 14541 |
| 014952 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:22am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594352.9 | 509626.0 | 44223 | 1.64041666667 | 14952 |
| 014943 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:23am | Sensor | 1797-S0034-905-G-ACK | 6803.3 | 1594356.3 | 509627.0 | 44225 | 1.64041666667 | 14943 |
| 013745 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:24am | Sensor | 1797-S0034-905-G-ACK | 6803.1 | 1594359.8 | 509628.6 | 44227 | 1.64041666667 | 13745 |
| 014811 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:25am | Sensor | 1797-S0034-905-G-ACK | 6803.2 | 1594363.2 | 509630.0 | 44229 | 1.64041666667 | 14811 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:26am | Sensor | 1797-S0034-905-G-ACK | 6803.4 | 1594366.7 | 509631.4 | 44231 | 1.64041666667 | 14526 |
| 014096 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:27am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594369.6 | 509632.5 | 44233 | 1.64041666667 | 14096 |
| 013659 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:28am | Sensor | 1797-S0034-905-G-ACK | 6803.5 | 1594373.0 | 509633.7 | 44235 | 1.64041666667 | 13659 |
| 013015 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:29am | Sensor | 1797-S0034-905-G-ACK | 6803.7 | 1594376.0 | 509634.4 | 44237 | 1.64041666667 | 13015 |
| 012878 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:30am | Sensor | 1797-S0034-905-G-ACK | 6803.9 | 1594380.0 | 509634.9 | 44239 | 1.64041666667 | 12878 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:31am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594383.3 | 509635.2 | 44241 | 1.64041666667 | 13094 |
| 013290 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:32am | Sensor | 1797-S0034-905-G-ACK | 6803.8 | 1594386.7 | 509635.9 | 44243 | 1.64041666667 | 13290 |
| 013776 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:33am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594390.2 | 509636.5 | 44245 | 1.64041666667 | 13776 |
| 013876 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:34am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594394.1 | 509637.1 | 44247 | 1.64041666667 | 13876 |
| 014788 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:35am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594397.4 | 509637.7 | 44249 | 1.64041666667 | 14788 |
| 014415 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:36am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594400.9 | 509638.7 | 44251 | 1.64041666667 | 14415 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:37am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594403.9 | 509639.7 | 44253 | 1.64041666667 | 14078 |
| 014542 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:38am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594407.8 | 509640.8 | 44255 | 1.64041666667 | 14542 |
| 015319 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:39am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594411.2 | 509641.6 | 44257 | 1.64041666667 | 15319 |
| 014677 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:40am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594414.8 | 509642.5 | 44259 | 1.64041666667 | 14677 |
| 014173 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:41am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594418.5 | 509643.2 | 44261 | 1.64041666667 | 14173 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014775 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:42am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594422.2 | 509643.4 | 44263 | 1.64041666667 | 14775 |
| 015241 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:43am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594425.3 | 509643.2 | 44265 | 1.64041666667 | 15241 |
| 016598 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:44am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594429.1 | 509642.4 | 44267 | 1.64041666667 | 16598 |
| 016214 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:45am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594432.6 | 509641.4 | 44269 | 1.64041666667 | 16214 |
| 016597 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:46am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594435.9 | 509640.4 | 44271 | 1.64041666667 | 16597 |
| 016738 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:47am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594439.1 | 509639.8 | 44273 | 1.64041666667 | 16738 |
| 016818 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:48am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594442.1 | 509639.6 | 44275 | 1.64041666667 | 16818 |
| 015295 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:49am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594445.3 | 509639.7 | 44277 | 1.64041666667 | 15295 |
| 014903 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:50am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594448.9 | 509639.6 | 44279 | 1.64041666667 | 14903 |
| 013858 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:51am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594452.1 | 509640.2 | 44281 | 1.64041666667 | 13858 |
| 013967 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:52am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594455.9 | 509641.4 | 44283 | 1.64041666667 | 13967 |
| 014434 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:53am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594458.9 | 509642.8 | 44285 | 1.64041666667 | 14434 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:54am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594461.6 | 509644.4 | 44287 | 1.64041666667 | 14426 |
| 014302 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:55am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594464.1 | 509646.1 | 44289 | 1.64041666667 | 14302 |
| 014397 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:56am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594466.7 | 509648.3 | 44291 | 1.64041666667 | 14397 |
| 014811 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:57am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594469.2 | 509650.1 | 44293 | 1.64041666667 | 14811 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:58am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594472.5 | 509652.0 | 44295 | 1.64041666667 | 14556 |
| 014480 | 0 | GeoXH 6000 | 08/18/2015 | 11:40:59am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594475.5 | 509653.8 | 44297 | 1.64041666667 | 14480 |
| 015090 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:00am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594478.9 | 509655.3 | 44299 | 1.64041666667 | 15090 |
| 014533 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:01am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594482.0 | 509656.8 | 44301 | 1.64041666667 | 14533 |
| 014392 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:02am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594485.4 | 509658.5 | 44303 | 1.64041666667 | 14392 |
| 014913 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:03am | Sensor | 1797-S0034-905-G-ACK | 6804.1 | 1594488.3 | 509660.1 | 44305 | 1.64041666667 | 14913 |
| 014928 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:04am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594491.3 | 509662.1 | 44307 | 1.64041666667 | 14928 |
| 014757 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:05am | Sensor | 1797-S0034-905-G-ACK | 6804.2 | 1594493.9 | 509664.1 | 44309 | 1.64041666667 | 14757 |
| 015163 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:06am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594497.0 | 509665.7 | 44311 | 1.64041666667 | 15163 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:07am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594500.1 | 509666.6 | 44313 | 1.64041666667 | 14072 |
| 014875 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:08am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594503.4 | 509667.8 | 44315 | 1.64041666667 | 14875 |
| 014480 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:09am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594506.0 | 509669.0 | 44317 | 1.64041666667 | 14480 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:10am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594509.7 | 509670.6 | 44319 | 1.64041666667 | 14550 |
| 014146 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:11am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594512.7 | 509671.8 | 44321 | 1.64041666667 | 14146 |
| 014070 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:12am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594516.3 | 509673.2 | 44323 | 1.64041666667 | 14070 |
| 014724 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:13am | Sensor | 1797-S0034-905-G-ACK | 6804.3 | 1594519.4 | 509674.4 | 44325 | 1.64041666667 | 14724 |
| 015152 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:14am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594522.5 | 509675.3 | 44327 | 1.64041666667 | 15152 |
| 015386 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:15am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594525.5 | 509675.9 | 44329 | 1.64041666667 | 15386 |
| 014894 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:16am | Sensor | 1797-S0034-905-G-ACK | 6804.4 | 1594528.8 | 509676.3 | 44331 | 1.64041666667 | 14894 |
| 014933 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:17am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594531.5 | 509676.7 | 44333 | 1.64041666667 | 14933 |
| 015420 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:18am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594534.1 | 509677.5 | 44335 | 1.64041666667 | 15420 |
| 014996 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:19am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594536.1 | 509679.0 | 44337 | 1.64041666667 | 14996 |
| 015290 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:20am | Sensor | 1797-S0034-905-G-ACK | 6804.5 | 1594538.0 | 509681.4 | 44339 | 1.64041666667 | 15290 |
| 015163 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:21am | Sensor | 1797-S0034-905-G-ACK | 6804.7 | 1594539.2 | 509684.0 | 44341 | 1.64041666667 | 15163 |
| 015234 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:22am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594540.0 | 509686.6 | 44343 | 1.64041666667 | 15234 |
| 015236 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:23am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594540.5 | 509689.1 | 44345 | 1.64041666667 | 15236 |
| 015913 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:24am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594540.5 | 509691.4 | 44347 | 1.64041666667 | 15913 |
| 015273 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:25am | Sensor | 1797-S0034-905-G-ACK | 6804.8 | 1594540.5 | 509693.7 | 44349 | 1.64041666667 | 15273 |
| 014839 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:26am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594540.6 | 509696.4 | 44351 | 1.64041666667 | 14839 |
| 014647 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:27am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594540.5 | 509698.8 | 44353 | 1.64041666667 | 14647 |
| 014441 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:28am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594539.9 | 509700.6 | 44355 | 1.64041666667 | 14441 |
| 014355 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:29am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594538.9 | 509701.9 | 44357 | 1.64041666667 | 14355 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015447 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:30am | Sensor | 1797-S0034-905-G-ACK | 6804.9 | 1594536.8 | 509703.3 | 44359 | 1.64041666667 | 15447 |
| 015896 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:31am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594535.0 | 509704.5 | 44361 | 1.64041666667 | 15896 |
| 016269 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:32am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594534.1 | 509706.1 | 44363 | 1.64041666667 | 16269 |
| 017709 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:33am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594533.0 | 509707.4 | 44365 | 1.64041666667 | 17709 |
| 018083 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:34am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594531.4 | 509708.5 | 44367 | 1.64041666667 | 18083 |
| 017469 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:35am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594530.2 | 509709.6 | 44369 | 1.64041666667 | 17469 |
| 016831 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:36am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594529.0 | 509710.0 | 44371 | 1.64041666667 | 16831 |
| 015940 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:37am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594527.9 | 509710.9 | 44373 | 1.64041666667 | 15940 |
| 016833 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:38am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594526.8 | 509713.0 | 44375 | 1.64041666667 | 16833 |
| 016766 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:39am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594527.1 | 509715.2 | 44377 | 1.64041666667 | 16766 |
| 018888 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:40am | Sensor | 1797-S0034-905-G-ACK | 6805.0 | 1594528.8 | 509717.0 | 44379 | 1.64041666667 | 18888 |
| 019249 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:41am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594529.9 | 509717.8 | 44381 | 1.64041666667 | 19249 |
| 019235 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:42am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594529.8 | 509717.6 | 44383 | 1.64041666667 | 19235 |
| 019595 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:43am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594530.4 | 509718.2 | 44385 | 1.64041666667 | 19595 |
| 020539 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:44am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594531.5 | 509719.9 | 44387 | 1.64041666667 | 20539 |
| 020216 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:45am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594533.6 | 509720.7 | 44389 | 1.64041666667 | 20216 |
| 019066 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:46am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594535.7 | 509720.9 | 44391 | 1.64041666667 | 19066 |
| 018142 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:47am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594537.7 | 509720.7 | 44393 | 1.64041666667 | 18142 |
| 018552 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:48am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594539.4 | 509719.6 | 44395 | 1.64041666667 | 18552 |
| 020058 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:49am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594540.8 | 509717.5 | 44397 | 1.64041666667 | 20058 |
| 019608 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:50am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594542.3 | 509715.2 | 44399 | 1.64041666667 | 19608 |
| 021634 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:51am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594543.7 | 509713.3 | 44401 | 1.64041666667 | 21634 |
| 022526 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:52am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594544.5 | 509711.6 | 44403 | 1.64041666667 | 22526 |
| 023523 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:53am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594544.8 | 509710.7 | 44405 | 1.64041666667 | 23523 |
| 025419 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:54am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594545.4 | 509710.7 | 44407 | 1.64041666667 | 25419 |
| 024693 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:55am | Sensor | 1797-S0034-905-G-ACK | 6805.1 | 1594545.6 | 509710.5 | 44409 | 1.64041666667 | 24693 |
| 024960 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:56am | Sensor | 1797-S0034-905-G-ACK | 6804.6 | 1594545.8 | 509710.4 | 44411 | 1.64041666667 | 24960 |
| 025117 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:57am | Sensor | 1797-S0034-905-G-ACK | 6803.6 | 1594546.5 | 509710.6 | 44413 | 1.64041666667 | 25117 |
| 024748 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:58am | Sensor | 1797-S0034-905-G-ACK | 6804.0 | 1594546.3 | 509710.7 | 44415 | 1.64041666667 | 24748 |
| 024751 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:59am | Sensor | 1797-S0034-905-G-ACK | 6805.2 | 1594545.5 | 509710.7 | 44417 | 1.64041666667 | 24751 |
| 024407 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:00am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594545.1 | 509710.5 | 44419 | 1.64041666667 | 24407 |
| 024859 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:01am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594545.1 | 509710.5 | 44421 | 1.64041666667 | 24859 |
| 025376 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:02am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594545.1 | 509710.5 | 44423 | 1.64041666667 | 25376 |
| 025974 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:03am | Sensor | 1797-S0034-905-G-ACK | 6805.3 | 1594545.1 | 509710.5 | 44425 | 1.64041666667 | 25974 |
| 026677 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:04am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.5 | 44426 | 1.64041666667 | 26677 |
| 025671 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:05am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.2 | 509710.5 | 44427 | 1.64041666667 | 25671 |
| 025172 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:06am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.5 | 44428 | 1.64041666667 | 25172 |
| 025004 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:07am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.5 | 44429 | 1.64041666667 | 25004 |
| 026447 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:08am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.5 | 44430 | 1.64041666667 | 26447 |
| 026126 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:09am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.5 | 44431 | 1.64041666667 | 26126 |
| 025196 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:10am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.2 | 509710.5 | 44432 | 1.64041666667 | 25196 |
| 024950 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:11am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.2 | 509710.5 | 44433 | 1.64041666667 | 24950 |
| 025509 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:12am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.5 | 44434 | 1.64041666667 | 25509 |
| 024316 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:13am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.5 | 44435 | 1.64041666667 | 24316 |
| 024155 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:14am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.5 | 44436 | 1.64041666667 | 24155 |
| 024747 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:15am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.2 | 509710.5 | 44437 | 1.64041666667 | 24747 |
| 024307 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:16am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.5 | 44438 | 1.64041666667 | 24307 |
| 024690 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:17am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.4 | 44439 | 1.64041666667 | 24690 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 025798 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:18am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.4 | 44440 | 1.64041666667 | 25798 |
| 025709 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:19am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.4 | 44441 | 1.64041666667 | 25709 |
| 026393 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:20am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.4 | 44442 | 1.64041666667 | 26393 |
| 026104 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:21am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.1 | 509710.4 | 44443 | 1.64041666667 | 26104 |
| 026376 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:22am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.2 | 509710.4 | 44444 | 1.64041666667 | 26376 |
| 025239 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:23am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.2 | 509710.4 | 44445 | 1.64041666667 | 25239 |
| 024719 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:24am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.4 | 44446 | 1.64041666667 | 24719 |
| 025124 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:25am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.4 | 44447 | 1.64041666667 | 25124 |
| 025015 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:26am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.4 | 44448 | 1.64041666667 | 25015 |
| 025681 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:27am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.4 | 44449 | 1.64041666667 | 25681 |
| 025268 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:28am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.4 | 44450 | 1.64041666667 | 25268 |
| 025470 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:29am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.4 | 44451 | 1.64041666667 | 25470 |
| 024767 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:30am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.1 | 509710.4 | 44452 | 1.64041666667 | 24767 |
| 025294 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:31am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.1 | 509710.4 | 44454 | 1.64041666667 | 25294 |
| 026152 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:32am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.1 | 509710.4 | 44456 | 1.64041666667 | 26152 |
| 025788 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:33am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.4 | 44458 | 1.64041666667 | 25788 |
| 025966 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:34am | Sensor | 1797-S0034-905-G-ACK | 6805.5 | 1594545.2 | 509710.4 | 44460 | 1.64041666667 | 25966 |
| 025863 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:35am | Sensor | 1797-S0034-905-G-ACK | 6805.4 | 1594545.2 | 509710.4 | 44463 | 1.64041666667 | 25863 |
| 013566 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:41pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593755.5 | 511223.4 | 37972 | 1.64041666667 | 13566 |
| 013804 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:42pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593754.3 | 511224.0 | 37975 | 1.64041666667 | 13804 |
| 013286 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:43pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593752.9 | 511224.5 | 37977 | 1.64041666667 | 13286 |
| 013181 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:44pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593752.7 | 511225.3 | 37979 | 1.64041666667 | 13181 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:45pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593752.8 | 511225.6 | 37981 | 1.64041666667 | 14111 |
| 012685 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:46pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593752.4 | 511225.7 | 37983 | 1.64041666667 | 12685 |
| 013293 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:47pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593751.1 | 511226.2 | 37985 | 1.64041666667 | 13293 |
| 013020 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:48pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593749.4 | 511227.2 | 37987 | 1.64041666667 | 13020 |
| 012701 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593746.7 | 511228.5 | 37989 | 1.64041666667 | 12701 |
| 013406 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:50pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593744.0 | 511230.1 | 37991 | 1.64041666667 | 13406 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593741.3 | 511232.2 | 37993 | 1.64041666667 | 13301 |
| 013407 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:52pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593738.8 | 511234.2 | 37995 | 1.64041666667 | 13407 |
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593736.5 | 511236.0 | 37997 | 1.64041666667 | 13518 |
| 013687 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:54pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593733.8 | 511237.2 | 37999 | 1.64041666667 | 13687 |
| 014238 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593730.9 | 511238.5 | 38001 | 1.64041666667 | 14238 |
| 014107 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:56pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593729.0 | 511240.1 | 38003 | 1.64041666667 | 14107 |
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:57pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593727.3 | 511242.3 | 38005 | 1.64041666667 | 13320 |
| 013515 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:58pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593725.4 | 511244.3 | 38007 | 1.64041666667 | 13515 |
| 013572 | 0 | GeoXH 6000 | 08/18/2015 | 01:37:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593723.1 | 511246.6 | 38009 | 1.64041666667 | 13572 |
| 014197 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593721.2 | 511248.4 | 38011 | 1.64041666667 | 14197 |
| 014435 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:01pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593719.0 | 511250.1 | 38013 | 1.64041666667 | 14435 |
| 014315 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:02pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593716.7 | 511251.5 | 38015 | 1.64041666667 | 14315 |
| 014397 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:03pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593714.2 | 511253.0 | 38017 | 1.64041666667 | 14397 |
| 014166 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:04pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593712.2 | 511254.5 | 38019 | 1.64041666667 | 14166 |
| 013848 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:05pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593710.5 | 511256.1 | 38021 | 1.64041666667 | 13848 |
| 013977 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:06pm | Sensor | 1797-S0033-905-G-ACK | 6813.8 | 1593708.5 | 511257.7 | 38023 | 1.64041666667 | 13977 |
| 014619 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:07pm | Sensor | 1797-S0033-905-G-ACK | 6813.8 | 1593706.2 | 511259.9 | 38025 | 1.64041666667 | 14619 |
| 014351 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:08pm | Sensor | 1797-S0033-905-G-ACK | 6814.0 | 1593704.8 | 511261.8 | 38027 | 1.64041666667 | 14351 |
| 014567 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:09pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593703.6 | 511263.1 | 38029 | 1.64041666667 | 14567 |
| 015019 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:10pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593702.6 | 511263.3 | 38031 | 1.64041666667 | 15019 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014530 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:11pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593702.6 | 511263.3 | 38033 | 1.64041666667 | 14530 |
| 014938 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:12pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593702.6 | 511263.2 | 38035 | 1.64041666667 | 14938 |
| 015483 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:13pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593702.6 | 511263.2 | 38037 | 1.64041666667 | 15483 |
| 015256 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:14pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593702.6 | 511263.2 | 38039 | 1.64041666667 | 15256 |
| 014859 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:15pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593702.5 | 511263.1 | 38041 | 1.64041666667 | 14859 |
| 015228 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:16pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593702.7 | 511263.3 | 38043 | 1.64041666667 | 15228 |
| 014513 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593703.7 | 511263.9 | 38045 | 1.64041666667 | 14513 |
| 015356 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:18pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593705.7 | 511264.1 | 38047 | 1.64041666667 | 15356 |
| 014120 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.0 | 1593708.3 | 511262.4 | 38049 | 1.64041666667 | 14120 |
| 013875 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:20pm | Sensor | 1797-S0033-905-G-ACK | 6814.0 | 1593710.2 | 511260.2 | 38051 | 1.64041666667 | 13875 |
| 013647 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593712.0 | 511257.4 | 38053 | 1.64041666667 | 13647 |
| 013685 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:22pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593713.3 | 511255.5 | 38055 | 1.64041666667 | 13685 |
| 014272 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:23pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593715.2 | 511252.9 | 38057 | 1.64041666667 | 14272 |
| 014306 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:24pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593717.5 | 511251.0 | 38059 | 1.64041666667 | 14306 |
| 013357 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:25pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593720.5 | 511249.4 | 38061 | 1.64041666667 | 13357 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:26pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593722.8 | 511248.3 | 38063 | 1.64041666667 | 13738 |
| 013945 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:27pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593725.4 | 511246.8 | 38065 | 1.64041666667 | 13945 |
| 014376 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:28pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593727.5 | 511245.2 | 38067 | 1.64041666667 | 14376 |
| 013892 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593729.8 | 511243.8 | 38069 | 1.64041666667 | 13892 |
| 014144 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593732.1 | 511242.4 | 38071 | 1.64041666667 | 14144 |
| 013386 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:31pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593734.6 | 511240.8 | 38073 | 1.64041666667 | 13386 |
| 012697 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:32pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593737.0 | 511239.5 | 38075 | 1.64041666667 | 12697 |
| 013074 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:33pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593740.2 | 511238.1 | 38077 | 1.64041666667 | 13074 |
| 013437 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:34pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593742.9 | 511237.1 | 38079 | 1.64041666667 | 13437 |
| 013633 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593746.1 | 511235.9 | 38081 | 1.64041666667 | 13633 |
| 014223 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:36pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593748.8 | 511235.0 | 38083 | 1.64041666667 | 14223 |
| 013131 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:37pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593752.0 | 511233.9 | 38085 | 1.64041666667 | 13131 |
| 014083 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:38pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593755.0 | 511232.9 | 38087 | 1.64041666667 | 14083 |
| 014192 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:39pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593758.0 | 511231.8 | 38089 | 1.64041666667 | 14192 |
| 013405 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:40pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593760.5 | 511230.4 | 38091 | 1.64041666667 | 13405 |
| 012925 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:41pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593762.7 | 511228.4 | 38093 | 1.64041666667 | 12925 |
| 012783 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:42pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593764.9 | 511226.1 | 38095 | 1.64041666667 | 12783 |
| 014068 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:43pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593767.6 | 511224.1 | 38097 | 1.64041666667 | 14068 |
| 013868 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:44pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593770.4 | 511222.9 | 38099 | 1.64041666667 | 13868 |
| 013980 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:45pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593773.7 | 511221.1 | 38101 | 1.64041666667 | 13980 |
| 014509 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:46pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593776.4 | 511218.7 | 38103 | 1.64041666667 | 14509 |
| 013599 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:47pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593778.8 | 511216.3 | 38105 | 1.64041666667 | 13599 |
| 014219 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:48pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593780.8 | 511214.1 | 38107 | 1.64041666667 | 14219 |
| 014388 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593783.4 | 511211.5 | 38109 | 1.64041666667 | 14388 |
| 014168 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:50pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593785.3 | 511209.1 | 38111 | 1.64041666667 | 14168 |
| 014202 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593787.4 | 511207.1 | 38113 | 1.64041666667 | 14202 |
| 014656 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:52pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593789.5 | 511205.4 | 38115 | 1.64041666667 | 14656 |
| 014521 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593792.2 | 511203.7 | 38117 | 1.64041666667 | 14521 |
| 014483 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:54pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593794.7 | 511202.1 | 38119 | 1.64041666667 | 14483 |
| 014289 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.0 | 1593797.1 | 511200.3 | 38121 | 1.64041666667 | 14289 |
| 013655 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:56pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593798.7 | 511198.3 | 38123 | 1.64041666667 | 13655 |
| 014251 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:57pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593799.2 | 511196.4 | 38125 | 1.64041666667 | 14251 |
| 014683 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:58pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.2 | 511195.3 | 38127 | 1.64041666667 | 14683 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016352 | 0 | GeoXH 6000 | 08/18/2015 | 01:38:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.7 | 511194.9 | 38129 | 1.64041666667 | 16352 |
| 017425 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593799.8 | 511194.8 | 38131 | 1.64041666667 | 17425 |
| 017662 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:01pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593799.7 | 511194.9 | 38133 | 1.64041666667 | 17662 |
| 017457 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:02pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593799.1 | 511195.0 | 38135 | 1.64041666667 | 17457 |
| 017177 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:03pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593798.2 | 511195.1 | 38137 | 1.64041666667 | 17177 |
| 017949 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:04pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593797.2 | 511196.1 | 38139 | 1.64041666667 | 17949 |
| 016171 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:05pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593796.0 | 511197.3 | 38141 | 1.64041666667 | 16171 |
| 015276 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:06pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593795.7 | 511198.0 | 38143 | 1.64041666667 | 15276 |
| 014278 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:07pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593795.2 | 511198.9 | 38145 | 1.64041666667 | 14278 |
| 014046 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:08pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593795.0 | 511198.8 | 38147 | 1.64041666667 | 14046 |
| 014268 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:09pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593795.0 | 511198.8 | 38149 | 1.64041666667 | 14268 |
| 013643 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:10pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593795.1 | 511198.8 | 38151 | 1.64041666667 | 13643 |
| 013187 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:11pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593795.1 | 511198.9 | 38153 | 1.64041666667 | 13187 |
| 013102 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:12pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593795.1 | 511198.9 | 38155 | 1.64041666667 | 13102 |
| 013040 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:13pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593795.1 | 511198.9 | 38157 | 1.64041666667 | 13040 |
| 014160 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:14pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593795.1 | 511198.9 | 38159 | 1.64041666667 | 14160 |
| 013612 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:15pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593795.1 | 511198.9 | 38161 | 1.64041666667 | 13612 |
| 013852 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:16pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593795.0 | 511198.9 | 38163 | 1.64041666667 | 13852 |
| 014032 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593795.2 | 511198.8 | 38165 | 1.64041666667 | 14032 |
| 013473 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:18pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593795.3 | 511198.6 | 38167 | 1.64041666667 | 13473 |
| 013706 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593794.9 | 511199.1 | 38169 | 1.64041666667 | 13706 |
| 015119 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:20pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593794.9 | 511199.1 | 38171 | 1.64041666667 | 15119 |
| 013702 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593794.9 | 511199.1 | 38173 | 1.64041666667 | 13702 |
| 013070 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:22pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593794.9 | 511199.1 | 38175 | 1.64041666667 | 13070 |
| 013914 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:23pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593794.9 | 511199.1 | 38177 | 1.64041666667 | 13914 |
| 013076 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:24pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593794.9 | 511199.1 | 38179 | 1.64041666667 | 13076 |
| 014248 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:25pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593794.9 | 511199.1 | 38181 | 1.64041666667 | 14248 |
| 013444 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:26pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593794.9 | 511199.1 | 38183 | 1.64041666667 | 13444 |
| 013630 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:27pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593794.7 | 511199.1 | 38185 | 1.64041666667 | 13630 |
| 013539 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:28pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593794.7 | 511199.2 | 38187 | 1.64041666667 | 13539 |
| 014028 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593794.7 | 511199.2 | 38189 | 1.64041666667 | 14028 |
| 013658 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593794.7 | 511199.2 | 38191 | 1.64041666667 | 13658 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:31pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593794.7 | 511199.2 | 38193 | 1.64041666667 | 13038 |
| 013131 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:32pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593794.7 | 511199.2 | 38195 | 1.64041666667 | 13131 |
| 012974 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:33pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593794.9 | 511199.0 | 38197 | 1.64041666667 | 12974 |
| 013485 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:34pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593795.6 | 511198.2 | 38199 | 1.64041666667 | 13485 |
| 013975 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593796.5 | 511196.2 | 38201 | 1.64041666667 | 13975 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:36pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593797.8 | 511194.2 | 38203 | 1.64041666667 | 14266 |
| 015599 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:37pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593798.7 | 511192.3 | 38205 | 1.64041666667 | 15599 |
| 017430 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:38pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593799.3 | 511190.8 | 38207 | 1.64041666667 | 17430 |
| 018061 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:39pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.7 | 511190.0 | 38209 | 1.64041666667 | 18061 |
| 017757 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:40pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593799.6 | 511189.9 | 38211 | 1.64041666667 | 17757 |
| 017676 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:41pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.5 | 511190.2 | 38213 | 1.64041666667 | 17676 |
| 018155 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:42pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.4 | 511190.7 | 38215 | 1.64041666667 | 18155 |
| 018402 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:43pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.6 | 511190.9 | 38217 | 1.64041666667 | 18402 |
| 018698 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:44pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.8 | 511191.4 | 38219 | 1.64041666667 | 18698 |
| 019233 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:45pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.7 | 511191.6 | 38221 | 1.64041666667 | 19233 |
| 019398 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:46pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.3 | 511192.2 | 38223 | 1.64041666667 | 19398 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019416 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:47pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593798.9 | 511193.0 | 38225 | 1.64041666667 | 19416 |
| 019156 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:48pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593798.9 | 511194.0 | 38227 | 1.64041666667 | 19156 |
| 016940 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593798.8 | 511195.0 | 38229 | 1.64041666667 | 16940 |
| 015146 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:50pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.2 | 511196.0 | 38231 | 1.64041666667 | 15146 |
| 014407 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593799.4 | 511197.6 | 38233 | 1.64041666667 | 14407 |
| 013579 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:52pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593800.6 | 511198.3 | 38235 | 1.64041666667 | 13579 |
| 014095 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593802.2 | 511198.5 | 38237 | 1.64041666667 | 14095 |
| 014506 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:54pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593803.9 | 511199.8 | 38239 | 1.64041666667 | 14506 |
| 014430 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593805.8 | 511200.7 | 38241 | 1.64041666667 | 14430 |
| 014709 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:56pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593807.4 | 511201.8 | 38243 | 1.64041666667 | 14709 |
| 014416 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:57pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593809.5 | 511202.9 | 38245 | 1.64041666667 | 14416 |
| 015076 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:58pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593811.5 | 511203.7 | 38247 | 1.64041666667 | 15076 |
| 014608 | 0 | GeoXH 6000 | 08/18/2015 | 01:39:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593813.7 | 511205.3 | 38249 | 1.64041666667 | 14608 |
| 014239 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593815.2 | 511206.6 | 38251 | 1.64041666667 | 14239 |
| 014594 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:01pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593816.7 | 511209.1 | 38253 | 1.64041666667 | 14594 |
| 013887 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:02pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593817.4 | 511211.6 | 38255 | 1.64041666667 | 13887 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:03pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593819.0 | 511214.1 | 38257 | 1.64041666667 | 13766 |
| 013458 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:04pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593820.3 | 511215.9 | 38259 | 1.64041666667 | 13458 |
| 012490 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:05pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593821.8 | 511218.5 | 38261 | 1.64041666667 | 12490 |
| 013003 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:06pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593823.5 | 511220.5 | 38263 | 1.64041666667 | 13003 |
| 012812 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:07pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593824.9 | 511223.1 | 38265 | 1.64041666667 | 12812 |
| 014174 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:08pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593825.7 | 511225.7 | 38267 | 1.64041666667 | 14174 |
| 013335 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:09pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593827.6 | 511227.9 | 38269 | 1.64041666667 | 13335 |
| 013186 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:10pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593829.2 | 511229.3 | 38271 | 1.64041666667 | 13186 |
| 013207 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:11pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593830.9 | 511232.4 | 38273 | 1.64041666667 | 13207 |
| 013241 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:12pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593832.3 | 511234.6 | 38275 | 1.64041666667 | 13241 |
| 013793 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:13pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593834.5 | 511236.5 | 38277 | 1.64041666667 | 13793 |
| 013863 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:14pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593835.9 | 511238.3 | 38279 | 1.64041666667 | 13863 |
| 012981 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:15pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593837.8 | 511240.9 | 38281 | 1.64041666667 | 12981 |
| 012484 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:16pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593839.9 | 511242.9 | 38283 | 1.64041666667 | 12484 |
| 012505 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593841.6 | 511244.9 | 38285 | 1.64041666667 | 12505 |
| 012396 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:18pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593842.9 | 511247.2 | 38287 | 1.64041666667 | 12396 |
| 012065 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593844.9 | 511249.3 | 38289 | 1.64041666667 | 12065 |
| 011924 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:20pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593846.6 | 511250.9 | 38291 | 1.64041666667 | 11924 |
| 012520 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593848.3 | 511253.2 | 38293 | 1.64041666667 | 12520 |
| 011767 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:22pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593850.5 | 511254.7 | 38295 | 1.64041666667 | 11767 |
| 011899 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:23pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593852.6 | 511255.9 | 38297 | 1.64041666667 | 11899 |
| 011995 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:24pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593854.0 | 511257.6 | 38299 | 1.64041666667 | 11995 |
| 011975 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:25pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593856.5 | 511258.8 | 38301 | 1.64041666667 | 11975 |
| 011951 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:26pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593858.4 | 511259.8 | 38303 | 1.64041666667 | 11951 |
| 011619 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:27pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593860.7 | 511261.7 | 38305 | 1.64041666667 | 11619 |
| 011711 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:28pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593863.3 | 511262.6 | 38307 | 1.64041666667 | 11711 |
| 012392 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593865.8 | 511263.3 | 38309 | 1.64041666667 | 12392 |
| 012003 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593868.2 | 511264.3 | 38311 | 1.64041666667 | 12003 |
| 012624 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593870.8 | 511265.0 | 38313 | 1.64041666667 | 12624 |
| 011893 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593873.2 | 511265.9 | 38315 | 1.64041666667 | 11893 |
| 011677 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593875.7 | 511267.3 | 38317 | 1.64041666667 | 11677 |
| 011758 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593877.8 | 511268.6 | 38319 | 1.64041666667 | 11758 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011752 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593880.0 | 511270.0 | 38321 | 1.64041666667 | 11752 |
| 012873 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593881.7 | 511271.6 | 38323 | 1.64041666667 | 12873 |
| 013098 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593883.1 | 511273.8 | 38325 | 1.64041666667 | 13098 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593884.4 | 511276.0 | 38327 | 1.64041666667 | 13038 |
| 013573 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593886.1 | 511278.0 | 38329 | 1.64041666667 | 13573 |
| 013275 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593887.5 | 511280.2 | 38331 | 1.64041666667 | 13275 |
| 013797 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593889.4 | 511282.2 | 38333 | 1.64041666667 | 13797 |
| 013558 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593891.5 | 511283.5 | 38335 | 1.64041666667 | 13558 |
| 013926 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593893.7 | 511285.5 | 38337 | 1.64041666667 | 13926 |
| 013593 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593895.3 | 511287.6 | 38339 | 1.64041666667 | 13593 |
| 013496 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593897.4 | 511289.6 | 38341 | 1.64041666667 | 13496 |
| 013779 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593899.3 | 511291.3 | 38343 | 1.64041666667 | 13779 |
| 013421 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593900.9 | 511293.5 | 38345 | 1.64041666667 | 13421 |
| 014666 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593902.5 | 511295.2 | 38347 | 1.64041666667 | 14666 |
| 013650 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593904.2 | 511296.7 | 38349 | 1.64041666667 | 13650 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593905.6 | 511298.7 | 38351 | 1.64041666667 | 13595 |
| 013820 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593906.7 | 511300.0 | 38353 | 1.64041666667 | 13820 |
| 013323 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593906.9 | 511300.8 | 38355 | 1.64041666667 | 13323 |
| 013674 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593907.2 | 511300.7 | 38357 | 1.64041666667 | 13674 |
| 013407 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593907.2 | 511300.7 | 38359 | 1.64041666667 | 13407 |
| 013248 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593907.6 | 511300.6 | 38361 | 1.64041666667 | 13248 |
| 014045 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593908.2 | 511300.6 | 38363 | 1.64041666667 | 14045 |
| 013990 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593908.6 | 511301.5 | 38365 | 1.64041666667 | 13990 |
| 013262 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593909.3 | 511301.4 | 38367 | 1.64041666667 | 13262 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 01:40:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593910.5 | 511302.0 | 38369 | 1.64041666667 | 13595 |
| 013512 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593911.6 | 511302.5 | 38371 | 1.64041666667 | 13512 |
| 012970 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593913.2 | 511304.4 | 38373 | 1.64041666667 | 12970 |
| 013476 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593915.3 | 511305.1 | 38375 | 1.64041666667 | 13476 |
| 013160 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593917.6 | 511306.3 | 38377 | 1.64041666667 | 13160 |
| 014190 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593919.4 | 511307.8 | 38379 | 1.64041666667 | 14190 |
| 015332 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593921.7 | 511309.1 | 38381 | 1.64041666667 | 15332 |
| 014422 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593923.8 | 511310.9 | 38383 | 1.64041666667 | 14422 |
| 013879 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593925.7 | 511312.8 | 38385 | 1.64041666667 | 13879 |
| 012765 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593927.8 | 511313.9 | 38387 | 1.64041666667 | 12765 |
| 013097 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593930.4 | 511315.4 | 38389 | 1.64041666667 | 13097 |
| 013375 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593932.1 | 511317.5 | 38391 | 1.64041666667 | 13375 |
| 013088 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593934.2 | 511319.5 | 38393 | 1.64041666667 | 13088 |
| 013444 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593935.8 | 511321.0 | 38395 | 1.64041666667 | 13444 |
| 013457 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593937.8 | 511323.6 | 38397 | 1.64041666667 | 13457 |
| 014800 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593939.6 | 511324.9 | 38399 | 1.64041666667 | 14800 |
| 014070 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593942.2 | 511326.8 | 38401 | 1.64041666667 | 14070 |
| 013666 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593944.0 | 511328.3 | 38403 | 1.64041666667 | 13666 |
| 013515 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593946.5 | 511328.8 | 38405 | 1.64041666667 | 13515 |
| 013384 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593948.8 | 511329.9 | 38407 | 1.64041666667 | 13384 |
| 014414 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593951.6 | 511330.5 | 38409 | 1.64041666667 | 14414 |
| 015802 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.0 | 511331.7 | 38411 | 1.64041666667 | 15802 |
| 015136 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593956.1 | 511333.0 | 38413 | 1.64041666667 | 15136 |
| 014769 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593958.2 | 511333.5 | 38415 | 1.64041666667 | 14769 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015770 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593960.3 | 511334.8 | 38417 | 1.64041666667 | 15770 |
| 014833 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593962.3 | 511335.5 | 38419 | 1.64041666667 | 14833 |
| 015116 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593964.7 | 511336.0 | 38421 | 1.64041666667 | 15116 |
| 015958 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593966.6 | 511337.1 | 38423 | 1.64041666667 | 15958 |
| 015411 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593966.4 | 511337.1 | 38425 | 1.64041666667 | 15411 |
| 015216 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593966.6 | 511337.2 | 38427 | 1.64041666667 | 15216 |
| 014904 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593966.5 | 511337.3 | 38429 | 1.64041666667 | 14904 |
| 014668 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593966.6 | 511336.9 | 38431 | 1.64041666667 | 14668 |
| 014633 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593967.3 | 511336.8 | 38433 | 1.64041666667 | 14633 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593967.6 | 511337.1 | 38435 | 1.64041666667 | 14591 |
| 013975 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593968.0 | 511336.9 | 38437 | 1.64041666667 | 13975 |
| 013981 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593969.6 | 511336.3 | 38439 | 1.64041666667 | 13981 |
| 013811 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593972.4 | 511336.9 | 38441 | 1.64041666667 | 13811 |
| 014121 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593974.8 | 511337.4 | 38443 | 1.64041666667 | 14121 |
| 014235 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593977.3 | 511337.9 | 38445 | 1.64041666667 | 14235 |
| 014510 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593979.5 | 511339.5 | 38447 | 1.64041666667 | 14510 |
| 013967 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593981.9 | 511341.3 | 38449 | 1.64041666667 | 13967 |
| 014996 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593984.2 | 511342.4 | 38451 | 1.64041666667 | 14996 |
| 015140 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593986.6 | 511344.0 | 38453 | 1.64041666667 | 15140 |
| 014344 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593989.3 | 511344.8 | 38455 | 1.64041666667 | 14344 |
| 014203 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593992.1 | 511345.4 | 38457 | 1.64041666667 | 14203 |
| 013817 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593994.3 | 511346.8 | 38459 | 1.64041666667 | 13817 |
| 013697 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593997.0 | 511347.8 | 38461 | 1.64041666667 | 13697 |
| 014297 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:46pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593999.4 | 511349.2 | 38463 | 1.64041666667 | 14297 |
| 014169 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:47pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594001.3 | 511350.8 | 38465 | 1.64041666667 | 14169 |
| 013363 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:48pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594003.2 | 511351.7 | 38467 | 1.64041666667 | 13363 |
| 013539 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:49pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594005.6 | 511353.7 | 38469 | 1.64041666667 | 13539 |
| 013743 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:50pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594007.2 | 511355.2 | 38471 | 1.64041666667 | 13743 |
| 013610 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:51pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594010.0 | 511356.5 | 38473 | 1.64041666667 | 13610 |
| 014668 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:52pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594012.2 | 511357.6 | 38475 | 1.64041666667 | 14668 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:53pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594014.8 | 511359.4 | 38477 | 1.64041666667 | 13861 |
| 013755 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:54pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594017.3 | 511360.3 | 38479 | 1.64041666667 | 13755 |
| 014102 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:55pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594020.0 | 511361.8 | 38481 | 1.64041666667 | 14102 |
| 013647 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:56pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594022.2 | 511362.6 | 38483 | 1.64041666667 | 13647 |
| 013136 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:57pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594024.7 | 511362.2 | 38485 | 1.64041666667 | 13136 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:58pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594027.4 | 511362.7 | 38487 | 1.64041666667 | 13861 |
| 013977 | 0 | GeoXH 6000 | 08/18/2015 | 01:41:59pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594029.7 | 511363.6 | 38489 | 1.64041666667 | 13977 |
| 013322 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:00pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594031.1 | 511364.3 | 38491 | 1.64041666667 | 13322 |
| 013486 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:01pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594031.1 | 511365.6 | 38493 | 1.64041666667 | 13486 |
| 013511 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:02pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1594030.2 | 511367.7 | 38495 | 1.64041666667 | 13511 |
| 013202 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:03pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594029.0 | 511369.8 | 38497 | 1.64041666667 | 13202 |
| 013823 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:04pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594027.2 | 511371.4 | 38499 | 1.64041666667 | 13823 |
| 014361 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:05pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594026.4 | 511373.3 | 38501 | 1.64041666667 | 14361 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:06pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594025.5 | 511374.2 | 38503 | 1.64041666667 | 14078 |
| 014886 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:07pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594024.0 | 511373.7 | 38505 | 1.64041666667 | 14886 |
| 014036 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:08pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594022.2 | 511372.7 | 38507 | 1.64041666667 | 14036 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:09pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594019.9 | 511371.1 | 38509 | 1.64041666667 | 14570 |
| 015800 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:10pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594018.2 | 511369.3 | 38511 | 1.64041666667 | 15800 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015450 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:11pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594016.0 | 511368.1 | 38513 | 1.64041666667 | 15450 |
| 014976 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:12pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594013.9 | 511367.2 | 38515 | 1.64041666667 | 14976 |
| 014776 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:13pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594012.2 | 511366.1 | 38517 | 1.64041666667 | 14776 |
| 014529 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:14pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594010.2 | 511365.5 | 38519 | 1.64041666667 | 14529 |
| 014547 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:15pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594007.7 | 511364.5 | 38521 | 1.64041666667 | 14547 |
| 014475 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:16pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1594005.4 | 511363.9 | 38523 | 1.64041666667 | 14475 |
| 014645 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:17pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594003.0 | 511362.6 | 38525 | 1.64041666667 | 14645 |
| 014305 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:18pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1594000.8 | 511360.8 | 38527 | 1.64041666667 | 14305 |
| 014436 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593998.4 | 511359.5 | 38529 | 1.64041666667 | 14436 |
| 015238 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593995.9 | 511358.2 | 38531 | 1.64041666667 | 15238 |
| 014729 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593993.7 | 511355.9 | 38533 | 1.64041666667 | 14729 |
| 014165 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593991.5 | 511354.4 | 38535 | 1.64041666667 | 14165 |
| 013323 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593989.4 | 511352.6 | 38537 | 1.64041666667 | 13323 |
| 014049 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593987.8 | 511350.8 | 38539 | 1.64041666667 | 14049 |
| 015065 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593985.6 | 511349.3 | 38541 | 1.64041666667 | 15065 |
| 014804 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593983.9 | 511347.8 | 38543 | 1.64041666667 | 14804 |
| 015159 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593981.2 | 511345.9 | 38545 | 1.64041666667 | 15159 |
| 014212 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593979.3 | 511344.9 | 38547 | 1.64041666667 | 14212 |
| 015022 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593977.1 | 511343.1 | 38549 | 1.64041666667 | 15022 |
| 014329 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593974.7 | 511342.2 | 38551 | 1.64041666667 | 14329 |
| 014975 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593971.5 | 511342.5 | 38553 | 1.64041666667 | 14975 |
| 015188 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593969.2 | 511342.7 | 38555 | 1.64041666667 | 15188 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593966.5 | 511342.0 | 38557 | 1.64041666667 | 14626 |
| 015404 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593964.4 | 511342.0 | 38559 | 1.64041666667 | 15404 |
| 014852 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593961.6 | 511341.8 | 38561 | 1.64041666667 | 14852 |
| 014789 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593959.8 | 511341.1 | 38563 | 1.64041666667 | 14789 |
| 015054 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593957.4 | 511340.9 | 38565 | 1.64041666667 | 15054 |
| 014925 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593955.0 | 511340.9 | 38567 | 1.64041666667 | 14925 |
| 015318 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593952.3 | 511340.3 | 38569 | 1.64041666667 | 15318 |
| 015036 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593949.7 | 511340.9 | 38571 | 1.64041666667 | 15036 |
| 013970 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:41pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593947.0 | 511340.4 | 38573 | 1.64041666667 | 13970 |
| 014150 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593944.6 | 511339.3 | 38575 | 1.64041666667 | 14150 |
| 014905 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593942.3 | 511338.3 | 38577 | 1.64041666667 | 14905 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:44pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593940.4 | 511336.5 | 38579 | 1.64041666667 | 14526 |
| 013833 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:45pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593938.2 | 511335.1 | 38581 | 1.64041666667 | 13833 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:46pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593936.5 | 511333.6 | 38583 | 1.64041666667 | 13278 |
| 013424 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593934.7 | 511331.2 | 38585 | 1.64041666667 | 13424 |
| 014076 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593932.9 | 511330.2 | 38587 | 1.64041666667 | 14076 |
| 014450 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593931.0 | 511328.4 | 38589 | 1.64041666667 | 14450 |
| 014098 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593928.5 | 511327.5 | 38591 | 1.64041666667 | 14098 |
| 014770 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593926.3 | 511325.8 | 38593 | 1.64041666667 | 14770 |
| 015058 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593924.2 | 511324.1 | 38595 | 1.64041666667 | 15058 |
| 014703 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593921.9 | 511323.0 | 38597 | 1.64041666667 | 14703 |
| 013887 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593919.7 | 511321.2 | 38599 | 1.64041666667 | 13887 |
| 014471 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593917.6 | 511319.2 | 38601 | 1.64041666667 | 14471 |
| 014268 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593915.2 | 511317.6 | 38603 | 1.64041666667 | 14268 |
| 013620 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593912.8 | 511315.5 | 38605 | 1.64041666667 | 13620 |
| 013676 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593911.0 | 511313.9 | 38607 | 1.64041666667 | 13676 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014728 | 0 | GeoXH 6000 | 08/18/2015 | 01:42:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593908.4 | 511312.1 | 38609 | 1.64041666667 | 14728 |
| 014112 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593906.2 | 511310.4 | 38611 | 1.64041666667 | 14112 |
| 013780 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593903.9 | 511308.2 | 38613 | 1.64041666667 | 13780 |
| 013729 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593901.5 | 511306.5 | 38615 | 1.64041666667 | 13729 |
| 013722 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593898.5 | 511304.9 | 38617 | 1.64041666667 | 13722 |
| 014806 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593896.0 | 511303.2 | 38619 | 1.64041666667 | 14806 |
| 014381 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593892.7 | 511300.9 | 38621 | 1.64041666667 | 14381 |
| 014396 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593890.4 | 511299.2 | 38623 | 1.64041666667 | 14396 |
| 014600 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:07pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593887.2 | 511296.8 | 38625 | 1.64041666667 | 14600 |
| 013763 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593884.9 | 511295.3 | 38627 | 1.64041666667 | 13763 |
| 013156 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593882.1 | 511292.6 | 38629 | 1.64041666667 | 13156 |
| 013138 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:10pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593880.2 | 511289.8 | 38631 | 1.64041666667 | 13138 |
| 013712 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593878.6 | 511286.7 | 38633 | 1.64041666667 | 13712 |
| 012963 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:12pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593877.0 | 511283.7 | 38635 | 1.64041666667 | 12963 |
| 013022 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593875.2 | 511281.0 | 38637 | 1.64041666667 | 13022 |
| 013204 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593873.6 | 511278.4 | 38639 | 1.64041666667 | 13204 |
| 013382 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:15pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593871.8 | 511275.1 | 38641 | 1.64041666667 | 13382 |
| 013212 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593869.9 | 511272.4 | 38643 | 1.64041666667 | 13212 |
| 012314 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593867.7 | 511270.1 | 38645 | 1.64041666667 | 12314 |
| 012304 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593865.2 | 511268.3 | 38647 | 1.64041666667 | 12304 |
| 013026 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593862.9 | 511266.4 | 38649 | 1.64041666667 | 13026 |
| 012622 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:20pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593860.8 | 511264.0 | 38651 | 1.64041666667 | 12622 |
| 013572 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593858.7 | 511261.7 | 38653 | 1.64041666667 | 13572 |
| 012622 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:22pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593856.9 | 511259.8 | 38655 | 1.64041666667 | 12622 |
| 012222 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:23pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593854.5 | 511257.7 | 38657 | 1.64041666667 | 12222 |
| 012710 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:24pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593852.4 | 511256.0 | 38659 | 1.64041666667 | 12710 |
| 011942 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:25pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593849.7 | 511253.8 | 38661 | 1.64041666667 | 11942 |
| 012754 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:26pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593847.7 | 511251.8 | 38663 | 1.64041666667 | 12754 |
| 012769 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:27pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593845.1 | 511248.9 | 38665 | 1.64041666667 | 12769 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:28pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593842.7 | 511246.5 | 38667 | 1.64041666667 | 12853 |
| 012232 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593840.5 | 511244.7 | 38669 | 1.64041666667 | 12232 |
| 012085 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593837.8 | 511242.8 | 38671 | 1.64041666667 | 12085 |
| 012543 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:31pm | Sensor | 1797-S0033-905-G-ACK | 6813.9 | 1593835.2 | 511241.1 | 38673 | 1.64041666667 | 12543 |
| 012740 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:32pm | Sensor | 1797-S0033-905-G-ACK | 6812.6 | 1593834.3 | 511240.2 | 38675 | 1.64041666667 | 12740 |
| 012633 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:33pm | Sensor | 1797-S0033-905-G-ACK | 6812.4 | 1593834.1 | 511240.1 | 38677 | 1.64041666667 | 12633 |
| 013016 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:34pm | Sensor | 1797-S0033-905-G-ACK | 6812.5 | 1593834.0 | 511240.3 | 38679 | 1.64041666667 | 13016 |
| 013284 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:35pm | Sensor | 1797-S0033-905-G-ACK | 6812.4 | 1593833.9 | 511240.5 | 38681 | 1.64041666667 | 13284 |
| 013015 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:36pm | Sensor | 1797-S0033-905-G-ACK | 6812.5 | 1593834.1 | 511240.2 | 38683 | 1.64041666667 | 13015 |
| 012413 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:37pm | Sensor | 1797-S0033-905-G-ACK | 6813.5 | 1593834.2 | 511240.1 | 38685 | 1.64041666667 | 12413 |
| 012465 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:38pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593834.0 | 511239.9 | 38687 | 1.64041666667 | 12465 |
| 012689 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:39pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593832.4 | 511237.6 | 38689 | 1.64041666667 | 12689 |
| 013857 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:40pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593830.2 | 511235.1 | 38691 | 1.64041666667 | 13857 |
| 013345 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:41pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593827.7 | 511232.3 | 38693 | 1.64041666667 | 13345 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:42pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593826.0 | 511230.2 | 38695 | 1.64041666667 | 13491 |
| 013319 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:43pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593824.2 | 511227.2 | 38697 | 1.64041666667 | 13319 |
| 013657 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:44pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593822.3 | 511224.2 | 38699 | 1.64041666667 | 13657 |
| 014049 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:45pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593819.9 | 511221.7 | 38701 | 1.64041666667 | 14049 |
| 014330 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:46pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593817.2 | 511219.4 | 38703 | 1.64041666667 | 14330 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013925 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:47pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593814.3 | 511216.8 | 38705 | 1.64041666667 | 13925 |
| 013638 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:48pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593811.8 | 511214.4 | 38707 | 1.64041666667 | 13638 |
| 013409 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593809.2 | 511211.8 | 38709 | 1.64041666667 | 13409 |
| 012702 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:50pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593806.7 | 511209.0 | 38711 | 1.64041666667 | 12702 |
| 014052 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593804.5 | 511206.8 | 38713 | 1.64041666667 | 14052 |
| 013694 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:52pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593801.8 | 511204.9 | 38715 | 1.64041666667 | 13694 |
| 014063 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593798.6 | 511203.3 | 38717 | 1.64041666667 | 14063 |
| 014660 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:54pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593796.1 | 511202.2 | 38719 | 1.64041666667 | 14660 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593793.1 | 511200.8 | 38721 | 1.64041666667 | 14246 |
| 014793 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:56pm | Sensor | 1797-S0033-905-G-ACK | 6813.7 | 1593790.9 | 511199.7 | 38723 | 1.64041666667 | 14793 |
| 014538 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:57pm | Sensor | 1797-S0033-905-G-ACK | 6809.7 | 1593789.3 | 511199.2 | 38725 | 1.64041666667 | 14538 |
| 013728 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:58pm | Sensor | 1797-S0033-905-G-ACK | 6809.4 | 1593789.5 | 511198.2 | 38727 | 1.64041666667 | 13728 |
| 014149 | 0 | GeoXH 6000 | 08/18/2015 | 01:43:59pm | Sensor | 1797-S0033-905-G-ACK | 6809.3 | 1593789.1 | 511198.2 | 38729 | 1.64041666667 | 14149 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:00pm | Sensor | 1797-S0033-905-G-ACK | 6809.5 | 1593789.1 | 511198.4 | 38731 | 1.64041666667 | 13974 |
| 013185 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:01pm | Sensor | 1797-S0033-905-G-ACK | 6809.5 | 1593790.0 | 511198.8 | 38733 | 1.64041666667 | 13185 |
| 013821 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:02pm | Sensor | 1797-S0033-905-G-ACK | 6809.2 | 1593790.2 | 511198.6 | 38735 | 1.64041666667 | 13821 |
| 013069 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:03pm | Sensor | 1797-S0033-905-G-ACK | 6809.3 | 1593790.0 | 511198.6 | 38737 | 1.64041666667 | 13069 |
| 013014 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:04pm | Sensor | 1797-S0033-905-G-ACK | 6809.4 | 1593789.9 | 511198.7 | 38739 | 1.64041666667 | 13014 |
| 012922 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:05pm | Sensor | 1797-S0033-905-G-ACK | 6809.4 | 1593789.9 | 511198.7 | 38741 | 1.64041666667 | 12922 |
| 013239 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:06pm | Sensor | 1797-S0033-905-G-ACK | 6809.4 | 1593789.9 | 511198.7 | 38743 | 1.64041666667 | 13239 |
| 013304 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:07pm | Sensor | 1797-S0033-905-G-ACK | 6809.4 | 1593789.9 | 511198.7 | 38745 | 1.64041666667 | 13304 |
| 013423 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:08pm | Sensor | 1797-S0033-905-G-ACK | 6809.5 | 1593789.7 | 511198.6 | 38747 | 1.64041666667 | 13423 |
| 012808 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:09pm | Sensor | 1797-S0033-905-G-ACK | 6810.1 | 1593788.9 | 511198.2 | 38749 | 1.64041666667 | 12808 |
| 013009 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:10pm | Sensor | 1797-S0033-905-G-ACK | 6812.0 | 1593789.0 | 511198.7 | 38751 | 1.64041666667 | 13009 |
| 014023 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:11pm | Sensor | 1797-S0033-905-G-ACK | 6812.0 | 1593789.7 | 511199.6 | 38753 | 1.64041666667 | 14023 |
| 013910 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:12pm | Sensor | 1797-S0033-905-G-ACK | 6812.8 | 1593790.6 | 511201.8 | 38755 | 1.64041666667 | 13910 |
| 013862 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:13pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593791.9 | 511203.6 | 38757 | 1.64041666667 | 13862 |
| 013917 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:14pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.5 | 511205.2 | 38759 | 1.64041666667 | 13917 |
| 014541 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:15pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593795.0 | 511207.4 | 38761 | 1.64041666667 | 14541 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:16pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593797.2 | 511209.6 | 38763 | 1.64041666667 | 14456 |
| 013389 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593799.7 | 511211.4 | 38765 | 1.64041666667 | 13389 |
| 013246 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:18pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593801.8 | 511212.8 | 38767 | 1.64041666667 | 13246 |
| 013946 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593803.4 | 511214.2 | 38769 | 1.64041666667 | 13946 |
| 013544 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:20pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593805.2 | 511214.5 | 38771 | 1.64041666667 | 13544 |
| 014024 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593806.5 | 511215.2 | 38773 | 1.64041666667 | 14024 |
| 013603 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:22pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593807.1 | 511215.5 | 38775 | 1.64041666667 | 13603 |
| 013022 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:23pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593807.2 | 511215.6 | 38777 | 1.64041666667 | 13022 |
| 013549 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:24pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593807.3 | 511215.6 | 38779 | 1.64041666667 | 13549 |
| 013006 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:25pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593807.3 | 511215.6 | 38781 | 1.64041666667 | 13006 |
| 013796 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:26pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593807.2 | 511215.4 | 38783 | 1.64041666667 | 13796 |
| 013835 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:27pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593806.8 | 511214.3 | 38785 | 1.64041666667 | 13835 |
| 013827 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:28pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593806.1 | 511212.2 | 38787 | 1.64041666667 | 13827 |
| 013590 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593804.3 | 511210.2 | 38789 | 1.64041666667 | 13590 |
| 013434 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.2 | 1593802.2 | 511207.7 | 38791 | 1.64041666667 | 13434 |
| 014299 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:31pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593800.1 | 511205.3 | 38793 | 1.64041666667 | 14299 |
| 013548 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:32pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593797.7 | 511203.3 | 38795 | 1.64041666667 | 13548 |
| 013733 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:33pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593795.5 | 511201.2 | 38797 | 1.64041666667 | 13733 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:34pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593794.2 | 511199.5 | 38799 | 1.64041666667 | 13560 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.4 | 511198.0 | 38801 | 1.64041666667 | 14227 |
| 014490 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:36pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.3 | 511197.6 | 38803 | 1.64041666667 | 14490 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:37pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.3 | 511197.5 | 38805 | 1.64041666667 | 14526 |
| 014741 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:38pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.3 | 511197.5 | 38807 | 1.64041666667 | 14741 |
| 014449 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:39pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.3 | 511197.5 | 38809 | 1.64041666667 | 14449 |
| 013670 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:40pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.3 | 511197.5 | 38811 | 1.64041666667 | 13670 |
| 014852 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:41pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.4 | 511197.5 | 38813 | 1.64041666667 | 14852 |
| 013807 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:42pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593793.4 | 511197.5 | 38815 | 1.64041666667 | 13807 |
| 013691 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:43pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593793.4 | 511197.5 | 38817 | 1.64041666667 | 13691 |
| 013671 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:44pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593793.4 | 511198.0 | 38819 | 1.64041666667 | 13671 |
| 013360 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:45pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593793.6 | 511199.5 | 38821 | 1.64041666667 | 13360 |
| 013597 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:46pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593795.1 | 511200.3 | 38823 | 1.64041666667 | 13597 |
| 013993 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:47pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593797.1 | 511201.9 | 38825 | 1.64041666667 | 13993 |
| 013818 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:48pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593799.1 | 511204.1 | 38827 | 1.64041666667 | 13818 |
| 014695 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593801.1 | 511206.6 | 38829 | 1.64041666667 | 14695 |
| 014198 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:50pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593802.8 | 511209.5 | 38831 | 1.64041666667 | 14198 |
| 013477 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593804.6 | 511212.3 | 38833 | 1.64041666667 | 13477 |
| 013228 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:52pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593806.6 | 511215.1 | 38835 | 1.64041666667 | 13228 |
| 012668 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593808.5 | 511217.7 | 38837 | 1.64041666667 | 12668 |
| 013216 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:54pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593810.1 | 511220.4 | 38839 | 1.64041666667 | 13216 |
| 013659 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593811.2 | 511223.4 | 38841 | 1.64041666667 | 13659 |
| 013885 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:56pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593812.1 | 511226.1 | 38843 | 1.64041666667 | 13885 |
| 014680 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:57pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593813.3 | 511229.2 | 38845 | 1.64041666667 | 14680 |
| 013935 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:58pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593814.1 | 511231.6 | 38847 | 1.64041666667 | 13935 |
| 013763 | 0 | GeoXH 6000 | 08/18/2015 | 01:44:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593814.8 | 511235.4 | 38849 | 1.64041666667 | 13763 |
| 013682 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593815.4 | 511238.8 | 38851 | 1.64041666667 | 13682 |
| 013561 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:01pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593816.6 | 511241.7 | 38853 | 1.64041666667 | 13561 |
| 012735 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:02pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593817.9 | 511244.1 | 38855 | 1.64041666667 | 12735 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:03pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593819.2 | 511247.6 | 38857 | 1.64041666667 | 13043 |
| 014777 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:04pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593820.0 | 511250.2 | 38859 | 1.64041666667 | 14777 |
| 014792 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:05pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593821.4 | 511253.5 | 38861 | 1.64041666667 | 14792 |
| 014388 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:06pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593822.5 | 511256.0 | 38863 | 1.64041666667 | 14388 |
| 014003 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:07pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593823.7 | 511259.7 | 38865 | 1.64041666667 | 14003 |
| 013186 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:08pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593824.4 | 511262.5 | 38867 | 1.64041666667 | 13186 |
| 013995 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:09pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593825.6 | 511265.8 | 38869 | 1.64041666667 | 13995 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:10pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593827.2 | 511268.5 | 38871 | 1.64041666667 | 13782 |
| 013602 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:11pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593828.9 | 511271.0 | 38873 | 1.64041666667 | 13602 |
| 014161 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:12pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593830.6 | 511273.2 | 38875 | 1.64041666667 | 14161 |
| 013469 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:13pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593833.1 | 511275.7 | 38877 | 1.64041666667 | 13469 |
| 013148 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:14pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593835.3 | 511278.2 | 38879 | 1.64041666667 | 13148 |
| 012271 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:15pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593837.0 | 511281.2 | 38881 | 1.64041666667 | 12271 |
| 012107 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593837.9 | 511283.7 | 38883 | 1.64041666667 | 12107 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593839.8 | 511286.5 | 38885 | 1.64041666667 | 13050 |
| 013468 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593841.5 | 511288.4 | 38887 | 1.64041666667 | 13468 |
| 013178 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593843.7 | 511290.6 | 38889 | 1.64041666667 | 13178 |
| 013548 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593845.2 | 511293.2 | 38891 | 1.64041666667 | 13548 |
| 012840 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593846.6 | 511295.4 | 38893 | 1.64041666667 | 12840 |
| 013117 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593848.1 | 511297.3 | 38895 | 1.64041666667 | 13117 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012546 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593850.2 | 511299.7 | 38897 | 1.64041666667 | 12546 |
| 012712 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593852.0 | 511302.0 | 38899 | 1.64041666667 | 12712 |
| 013413 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593853.9 | 511304.4 | 38901 | 1.64041666667 | 13413 |
| 012915 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593855.7 | 511306.6 | 38903 | 1.64041666667 | 12915 |
| 013069 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593857.9 | 511309.7 | 38905 | 1.64041666667 | 13069 |
| 013456 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593859.4 | 511311.9 | 38907 | 1.64041666667 | 13456 |
| 014206 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593861.0 | 511314.7 | 38909 | 1.64041666667 | 14206 |
| 013331 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593862.2 | 511317.7 | 38911 | 1.64041666667 | 13331 |
| 014639 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:31pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593863.2 | 511320.6 | 38913 | 1.64041666667 | 14639 |
| 015074 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:32pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593864.4 | 511323.3 | 38915 | 1.64041666667 | 15074 |
| 014381 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:33pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593866.1 | 511326.4 | 38917 | 1.64041666667 | 14381 |
| 014449 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593867.7 | 511329.1 | 38919 | 1.64041666667 | 14449 |
| 014173 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593869.1 | 511331.9 | 38921 | 1.64041666667 | 14173 |
| 014647 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593870.1 | 511334.5 | 38923 | 1.64041666667 | 14647 |
| 014216 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593871.4 | 511336.5 | 38925 | 1.64041666667 | 14216 |
| 013276 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593873.7 | 511337.8 | 38927 | 1.64041666667 | 13276 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593876.4 | 511339.4 | 38929 | 1.64041666667 | 13595 |
| 015140 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593878.7 | 511340.9 | 38931 | 1.64041666667 | 15140 |
| 014463 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593881.3 | 511342.5 | 38933 | 1.64041666667 | 14463 |
| 014976 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593883.5 | 511343.4 | 38935 | 1.64041666667 | 14976 |
| 014454 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593886.5 | 511344.2 | 38937 | 1.64041666667 | 14454 |
| 013845 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593889.3 | 511345.5 | 38939 | 1.64041666667 | 13845 |
| 013308 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593891.9 | 511346.7 | 38941 | 1.64041666667 | 13308 |
| 013650 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593894.2 | 511346.7 | 38943 | 1.64041666667 | 13650 |
| 013761 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593897.4 | 511346.1 | 38945 | 1.64041666667 | 13761 |
| 013358 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593899.8 | 511345.4 | 38947 | 1.64041666667 | 13358 |
| 013356 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593903.1 | 511343.8 | 38949 | 1.64041666667 | 13356 |
| 012043 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593905.3 | 511342.1 | 38951 | 1.64041666667 | 12043 |
| 013074 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593907.1 | 511339.9 | 38953 | 1.64041666667 | 13074 |
| 013534 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593908.7 | 511337.6 | 38955 | 1.64041666667 | 13534 |
| 014167 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593910.2 | 511335.2 | 38957 | 1.64041666667 | 14167 |
| 014276 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593911.8 | 511332.7 | 38959 | 1.64041666667 | 14276 |
| 013130 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593913.4 | 511330.9 | 38961 | 1.64041666667 | 13130 |
| 014998 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593914.9 | 511329.7 | 38963 | 1.64041666667 | 14998 |
| 014219 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593916.5 | 511329.5 | 38965 | 1.64041666667 | 14219 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593917.3 | 511330.3 | 38967 | 1.64041666667 | 14456 |
| 014124 | 0 | GeoXH 6000 | 08/18/2015 | 01:45:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593918.3 | 511330.9 | 38969 | 1.64041666667 | 14124 |
| 013967 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593918.7 | 511331.6 | 38971 | 1.64041666667 | 13967 |
| 014636 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593919.9 | 511332.1 | 38973 | 1.64041666667 | 14636 |
| 014900 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593920.7 | 511332.8 | 38975 | 1.64041666667 | 14900 |
| 015191 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593921.9 | 511333.5 | 38977 | 1.64041666667 | 15191 |
| 014897 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593923.0 | 511334.5 | 38979 | 1.64041666667 | 14897 |
| 015467 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593925.1 | 511336.3 | 38981 | 1.64041666667 | 15467 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:06pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593927.0 | 511337.7 | 38983 | 1.64041666667 | 14655 |
| 014596 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593929.6 | 511339.4 | 38985 | 1.64041666667 | 14596 |
| 013992 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593931.4 | 511341.1 | 38987 | 1.64041666667 | 13992 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593934.2 | 511342.8 | 38989 | 1.64041666667 | 13766 |
| 013541 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593936.6 | 511343.6 | 38991 | 1.64041666667 | 13541 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015019 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593939.7 | 511344.9 | 38993 | 1.64041666667 | 15019 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593942.2 | 511346.3 | 38995 | 1.64041666667 | 14516 |
| 014502 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593944.7 | 511347.2 | 38997 | 1.64041666667 | 14502 |
| 014495 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593947.3 | 511348.5 | 38999 | 1.64041666667 | 14495 |
| 014596 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593949.5 | 511350.2 | 39001 | 1.64041666667 | 14596 |
| 014832 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593951.5 | 511351.2 | 39003 | 1.64041666667 | 14832 |
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.3 | 511352.8 | 39005 | 1.64041666667 | 13518 |
| 013469 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593956.3 | 511353.9 | 39007 | 1.64041666667 | 13469 |
| 014048 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593959.0 | 511354.7 | 39009 | 1.64041666667 | 14048 |
| 014060 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593961.2 | 511355.9 | 39011 | 1.64041666667 | 14060 |
| 013788 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593963.7 | 511357.7 | 39013 | 1.64041666667 | 13788 |
| 014821 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593966.4 | 511358.8 | 39015 | 1.64041666667 | 14821 |
| 015731 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593969.0 | 511359.5 | 39017 | 1.64041666667 | 15731 |
| 014271 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593971.3 | 511360.8 | 39019 | 1.64041666667 | 14271 |
| 014140 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593974.4 | 511361.9 | 39021 | 1.64041666667 | 14140 |
| 013803 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593976.6 | 511362.1 | 39023 | 1.64041666667 | 13803 |
| 014394 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593979.5 | 511363.5 | 39025 | 1.64041666667 | 14394 |
| 014689 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593982.0 | 511364.7 | 39027 | 1.64041666667 | 14689 |
| 014292 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593984.9 | 511365.3 | 39029 | 1.64041666667 | 14292 |
| 014767 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593987.3 | 511366.0 | 39031 | 1.64041666667 | 14767 |
| 014381 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593990.6 | 511366.4 | 39033 | 1.64041666667 | 14381 |
| 014247 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593992.8 | 511366.5 | 39035 | 1.64041666667 | 14247 |
| 014344 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593995.7 | 511367.4 | 39037 | 1.64041666667 | 14344 |
| 013888 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593997.8 | 511368.5 | 39039 | 1.64041666667 | 13888 |
| 014802 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:35pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1594001.2 | 511369.2 | 39041 | 1.64041666667 | 14802 |
| 014506 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:36pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594003.3 | 511369.9 | 39043 | 1.64041666667 | 14506 |
| 012862 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:37pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594005.8 | 511371.5 | 39045 | 1.64041666667 | 12862 |
| 013272 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:38pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594007.8 | 511372.3 | 39047 | 1.64041666667 | 13272 |
| 013645 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:39pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594010.3 | 511372.6 | 39049 | 1.64041666667 | 13645 |
| 013594 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:40pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594012.2 | 511373.6 | 39051 | 1.64041666667 | 13594 |
| 014842 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:41pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594014.5 | 511374.7 | 39053 | 1.64041666667 | 14842 |
| 015323 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:42pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594016.0 | 511375.6 | 39055 | 1.64041666667 | 15323 |
| 015174 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:43pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594018.0 | 511377.2 | 39057 | 1.64041666667 | 15174 |
| 014633 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:44pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594019.8 | 511378.5 | 39059 | 1.64041666667 | 14633 |
| 013901 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:45pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594022.4 | 511379.8 | 39061 | 1.64041666667 | 13901 |
| 013481 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:46pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594024.3 | 511380.5 | 39063 | 1.64041666667 | 13481 |
| 014663 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:47pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594025.8 | 511382.1 | 39065 | 1.64041666667 | 14663 |
| 014420 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:48pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594026.1 | 511384.0 | 39067 | 1.64041666667 | 14420 |
| 015424 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:49pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594026.6 | 511386.4 | 39069 | 1.64041666667 | 15424 |
| 015583 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:50pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594026.3 | 511388.3 | 39071 | 1.64041666667 | 15583 |
| 015035 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:51pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594025.5 | 511390.2 | 39073 | 1.64041666667 | 15035 |
| 015972 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:52pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594024.8 | 511390.9 | 39075 | 1.64041666667 | 15972 |
| 015022 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:53pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594022.7 | 511390.1 | 39077 | 1.64041666667 | 15022 |
| 014937 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:54pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594020.7 | 511389.3 | 39079 | 1.64041666667 | 14937 |
| 014649 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:55pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594018.6 | 511388.1 | 39081 | 1.64041666667 | 14649 |
| 014270 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:56pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594017.1 | 511386.9 | 39083 | 1.64041666667 | 14270 |
| 013952 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:57pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594014.8 | 511386.1 | 39085 | 1.64041666667 | 13952 |
| 013548 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:58pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594013.2 | 511385.2 | 39087 | 1.64041666667 | 13548 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013725 | 0 | GeoXH 6000 | 08/18/2015 | 01:46:59pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594011.6 | 511383.7 | 39089 | 1.64041666667 | 13725 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:00pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594010.0 | 511382.5 | 39091 | 1.64041666667 | 13915 |
| 013040 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:01pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594008.1 | 511380.4 | 39093 | 1.64041666667 | 13040 |
| 013800 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:02pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594006.2 | 511379.0 | 39095 | 1.64041666667 | 13800 |
| 014520 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:03pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594004.1 | 511378.1 | 39097 | 1.64041666667 | 14520 |
| 014835 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:04pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1594002.5 | 511376.5 | 39099 | 1.64041666667 | 14835 |
| 016354 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1594000.1 | 511375.2 | 39101 | 1.64041666667 | 16354 |
| 015034 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593997.9 | 511374.3 | 39103 | 1.64041666667 | 15034 |
| 015851 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593995.9 | 511372.6 | 39105 | 1.64041666667 | 15851 |
| 016566 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593994.1 | 511371.6 | 39107 | 1.64041666667 | 16566 |
| 016278 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593991.9 | 511371.1 | 39109 | 1.64041666667 | 16278 |
| 015074 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593990.0 | 511370.7 | 39111 | 1.64041666667 | 15074 |
| 014756 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593987.7 | 511370.8 | 39113 | 1.64041666667 | 14756 |
| 014533 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593985.8 | 511370.0 | 39115 | 1.64041666667 | 14533 |
| 014880 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593983.4 | 511369.5 | 39117 | 1.64041666667 | 14880 |
| 014902 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593981.4 | 511369.1 | 39119 | 1.64041666667 | 14902 |
| 015485 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593979.0 | 511367.9 | 39121 | 1.64041666667 | 15485 |
| 014545 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593977.1 | 511367.1 | 39123 | 1.64041666667 | 14545 |
| 015021 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593974.9 | 511365.5 | 39125 | 1.64041666667 | 15021 |
| 014307 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593972.9 | 511364.4 | 39127 | 1.64041666667 | 14307 |
| 013950 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593970.6 | 511363.4 | 39129 | 1.64041666667 | 13950 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593968.8 | 511362.4 | 39131 | 1.64041666667 | 13974 |
| 014468 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593966.4 | 511361.6 | 39133 | 1.64041666667 | 14468 |
| 014993 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593964.2 | 511360.4 | 39135 | 1.64041666667 | 14993 |
| 014381 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593961.9 | 511359.7 | 39137 | 1.64041666667 | 14381 |
| 015222 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593960.1 | 511359.0 | 39139 | 1.64041666667 | 15222 |
| 014464 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593958.3 | 511357.6 | 39141 | 1.64041666667 | 14464 |
| 013476 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593956.0 | 511357.7 | 39143 | 1.64041666667 | 13476 |
| 014060 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593953.1 | 511357.6 | 39145 | 1.64041666667 | 14060 |
| 014621 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593950.9 | 511358.3 | 39147 | 1.64041666667 | 14621 |
| 013984 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593947.9 | 511358.1 | 39149 | 1.64041666667 | 13984 |
| 014924 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593944.8 | 511357.7 | 39151 | 1.64041666667 | 14924 |
| 014327 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593942.0 | 511357.6 | 39153 | 1.64041666667 | 14327 |
| 013444 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:32pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593939.9 | 511357.0 | 39155 | 1.64041666667 | 13444 |
| 013209 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:33pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593937.3 | 511356.8 | 39157 | 1.64041666667 | 13209 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593935.8 | 511356.1 | 39159 | 1.64041666667 | 13295 |
| 013913 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593934.4 | 511354.0 | 39161 | 1.64041666667 | 13913 |
| 014088 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593932.4 | 511353.2 | 39163 | 1.64041666667 | 14088 |
| 013752 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:37pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593930.4 | 511351.5 | 39165 | 1.64041666667 | 13752 |
| 013563 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:38pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593928.7 | 511350.5 | 39167 | 1.64041666667 | 13563 |
| 013547 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593926.2 | 511349.2 | 39169 | 1.64041666667 | 13547 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593925.0 | 511347.8 | 39171 | 1.64041666667 | 14482 |
| 015211 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593922.7 | 511346.9 | 39173 | 1.64041666667 | 15211 |
| 015014 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593920.6 | 511346.1 | 39175 | 1.64041666667 | 15014 |
| 015802 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593918.2 | 511345.2 | 39177 | 1.64041666667 | 15802 |
| 015579 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593916.1 | 511345.3 | 39179 | 1.64041666667 | 15579 |
| 015910 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593913.5 | 511345.3 | 39181 | 1.64041666667 | 15910 |
| 015827 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593912.0 | 511346.8 | 39183 | 1.64041666667 | 15827 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593910.8 | 511349.1 | 39185 | 1.64041666667 | 14482 |
| 014559 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593909.7 | 511351.2 | 39187 | 1.64041666667 | 14559 |
| 015479 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593910.0 | 511353.3 | 39189 | 1.64041666667 | 15479 |
| 014617 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593910.9 | 511355.4 | 39191 | 1.64041666667 | 14617 |
| 014282 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593913.0 | 511356.5 | 39193 | 1.64041666667 | 14282 |
| 013808 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593914.7 | 511356.9 | 39195 | 1.64041666667 | 13808 |
| 014382 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593917.0 | 511358.1 | 39197 | 1.64041666667 | 14382 |
| 014907 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593919.1 | 511358.2 | 39199 | 1.64041666667 | 14907 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593921.8 | 511358.9 | 39201 | 1.64041666667 | 14655 |
| 014828 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593923.8 | 511359.4 | 39203 | 1.64041666667 | 14828 |
| 015466 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593926.3 | 511359.1 | 39205 | 1.64041666667 | 15466 |
| 015067 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:58pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593928.4 | 511359.9 | 39207 | 1.64041666667 | 15067 |
| 016575 | 0 | GeoXH 6000 | 08/18/2015 | 01:47:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593931.1 | 511360.7 | 39209 | 1.64041666667 | 16575 |
| 015533 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593932.9 | 511361.1 | 39211 | 1.64041666667 | 15533 |
| 014325 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:01pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593934.8 | 511362.8 | 39213 | 1.64041666667 | 14325 |
| 013375 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593936.9 | 511363.6 | 39215 | 1.64041666667 | 13375 |
| 013156 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:03pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593938.9 | 511365.1 | 39217 | 1.64041666667 | 13156 |
| 013820 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:04pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593941.0 | 511366.2 | 39219 | 1.64041666667 | 13820 |
| 014531 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:05pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593943.5 | 511367.3 | 39221 | 1.64041666667 | 14531 |
| 014046 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:06pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593945.6 | 511368.7 | 39223 | 1.64041666667 | 14046 |
| 013601 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593948.5 | 511369.3 | 39225 | 1.64041666667 | 13601 |
| 014333 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593950.4 | 511370.6 | 39227 | 1.64041666667 | 14333 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593952.7 | 511371.5 | 39229 | 1.64041666667 | 14655 |
| 014895 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593955.1 | 511371.9 | 39231 | 1.64041666667 | 14895 |
| 015211 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593957.9 | 511373.0 | 39233 | 1.64041666667 | 15211 |
| 014916 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593960.2 | 511373.5 | 39235 | 1.64041666667 | 14916 |
| 015538 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593962.4 | 511374.0 | 39237 | 1.64041666667 | 15538 |
| 015242 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593964.7 | 511375.3 | 39239 | 1.64041666667 | 15242 |
| 014439 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593967.6 | 511376.2 | 39241 | 1.64041666667 | 14439 |
| 014287 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593970.0 | 511376.3 | 39243 | 1.64041666667 | 14287 |
| 014073 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593972.9 | 511376.9 | 39245 | 1.64041666667 | 14073 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593975.0 | 511377.0 | 39247 | 1.64041666667 | 13766 |
| 013863 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593977.9 | 511377.8 | 39249 | 1.64041666667 | 13863 |
| 014608 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593980.4 | 511378.9 | 39251 | 1.64041666667 | 14608 |
| 014824 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593982.5 | 511379.4 | 39253 | 1.64041666667 | 14824 |
| 014691 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593984.2 | 511380.4 | 39255 | 1.64041666667 | 14691 |
| 015156 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593986.8 | 511381.4 | 39257 | 1.64041666667 | 15156 |
| 014975 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593988.9 | 511381.9 | 39259 | 1.64041666667 | 14975 |
| 014063 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593991.2 | 511383.3 | 39261 | 1.64041666667 | 14063 |
| 015253 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593993.0 | 511384.2 | 39263 | 1.64041666667 | 15253 |
| 014992 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593995.5 | 511385.3 | 39265 | 1.64041666667 | 14992 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593997.3 | 511386.6 | 39267 | 1.64041666667 | 14426 |
| 013934 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:29pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1594000.1 | 511387.5 | 39269 | 1.64041666667 | 13934 |
| 014003 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:30pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1594002.2 | 511388.8 | 39271 | 1.64041666667 | 14003 |
| 013899 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:31pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594004.2 | 511389.8 | 39273 | 1.64041666667 | 13899 |
| 013421 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:32pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594006.2 | 511390.2 | 39275 | 1.64041666667 | 13421 |
| 013789 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:33pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594008.3 | 511391.9 | 39277 | 1.64041666667 | 13789 |
| 014679 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:34pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594010.3 | 511393.0 | 39279 | 1.64041666667 | 14679 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014309 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:35pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594012.4 | 511393.7 | 39281 | 1.64041666667 | 14309 |
| 014004 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:36pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594014.5 | 511395.2 | 39283 | 1.64041666667 | 14004 |
| 013382 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:37pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594016.8 | 511396.7 | 39285 | 1.64041666667 | 13382 |
| 013910 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:38pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594018.4 | 511397.4 | 39287 | 1.64041666667 | 13910 |
| 014034 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:39pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594019.2 | 511399.2 | 39289 | 1.64041666667 | 14034 |
| 013699 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:40pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594019.0 | 511401.2 | 39291 | 1.64041666667 | 13699 |
| 013841 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:41pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594018.6 | 511403.6 | 39293 | 1.64041666667 | 13841 |
| 013163 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:42pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594017.5 | 511405.3 | 39295 | 1.64041666667 | 13163 |
| 013081 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:43pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594016.4 | 511407.3 | 39297 | 1.64041666667 | 13081 |
| 014715 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:44pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594014.9 | 511407.9 | 39299 | 1.64041666667 | 14715 |
| 014120 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:45pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594012.7 | 511407.6 | 39301 | 1.64041666667 | 14120 |
| 015607 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:46pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594010.4 | 511407.6 | 39303 | 1.64041666667 | 15607 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:47pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594007.9 | 511406.8 | 39305 | 1.64041666667 | 14591 |
| 014253 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:48pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594005.9 | 511406.1 | 39307 | 1.64041666667 | 14253 |
| 014445 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:49pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594004.0 | 511405.6 | 39309 | 1.64041666667 | 14445 |
| 013765 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:50pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594001.7 | 511404.5 | 39311 | 1.64041666667 | 13765 |
| 013563 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593999.3 | 511403.9 | 39313 | 1.64041666667 | 13563 |
| 013869 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593997.9 | 511402.9 | 39315 | 1.64041666667 | 13869 |
| 013936 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593995.2 | 511401.4 | 39317 | 1.64041666667 | 13936 |
| 014124 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593993.4 | 511400.3 | 39319 | 1.64041666667 | 14124 |
| 013787 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593991.4 | 511398.5 | 39321 | 1.64041666667 | 13787 |
| 014310 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593989.7 | 511397.2 | 39323 | 1.64041666667 | 14310 |
| 014469 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593988.0 | 511394.8 | 39325 | 1.64041666667 | 14469 |
| 014304 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593986.6 | 511393.3 | 39327 | 1.64041666667 | 14304 |
| 013948 | 0 | GeoXH 6000 | 08/18/2015 | 01:48:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593984.3 | 511391.5 | 39329 | 1.64041666667 | 13948 |
| 014401 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593982.9 | 511389.9 | 39331 | 1.64041666667 | 14401 |
| 014280 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593980.6 | 511389.0 | 39333 | 1.64041666667 | 14280 |
| 015015 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593978.4 | 511388.0 | 39335 | 1.64041666667 | 15015 |
| 014573 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593975.7 | 511386.8 | 39337 | 1.64041666667 | 14573 |
| 014250 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593973.4 | 511386.6 | 39339 | 1.64041666667 | 14250 |
| 013228 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593971.0 | 511385.4 | 39341 | 1.64041666667 | 13228 |
| 014011 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593968.8 | 511384.4 | 39343 | 1.64041666667 | 14011 |
| 013633 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593966.8 | 511383.4 | 39345 | 1.64041666667 | 13633 |
| 013743 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593965.1 | 511382.2 | 39347 | 1.64041666667 | 13743 |
| 014548 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593962.5 | 511382.3 | 39349 | 1.64041666667 | 14548 |
| 015451 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593960.0 | 511381.7 | 39351 | 1.64041666667 | 15451 |
| 014503 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593957.3 | 511381.1 | 39353 | 1.64041666667 | 14503 |
| 015148 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593955.3 | 511381.2 | 39355 | 1.64041666667 | 15148 |
| 016621 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593952.4 | 511380.4 | 39357 | 1.64041666667 | 16621 |
| 016215 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593950.3 | 511380.1 | 39359 | 1.64041666667 | 16215 |
| 015235 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593947.4 | 511379.9 | 39361 | 1.64041666667 | 15235 |
| 015559 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593945.0 | 511379.5 | 39363 | 1.64041666667 | 15559 |
| 015382 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593942.4 | 511379.7 | 39365 | 1.64041666667 | 15382 |
| 014675 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:18pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593940.3 | 511379.0 | 39367 | 1.64041666667 | 14675 |
| 014329 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593937.9 | 511377.8 | 39369 | 1.64041666667 | 14329 |
| 013070 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593936.1 | 511377.2 | 39371 | 1.64041666667 | 13070 |
| 013262 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593933.8 | 511376.4 | 39373 | 1.64041666667 | 13262 |
| 013182 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:22pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593932.0 | 511376.6 | 39375 | 1.64041666667 | 13182 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014502 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593929.4 | 511375.7 | 39377 | 1.64041666667 | 14502 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593927.2 | 511374.5 | 39379 | 1.64041666667 | 14210 |
| 013655 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593925.3 | 511373.3 | 39381 | 1.64041666667 | 13655 |
| 014139 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593924.2 | 511371.8 | 39383 | 1.64041666667 | 14139 |
| 014725 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593921.5 | 511370.5 | 39385 | 1.64041666667 | 14725 |
| 015393 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593919.5 | 511369.9 | 39387 | 1.64041666667 | 15393 |
| 014981 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593917.1 | 511368.4 | 39389 | 1.64041666667 | 14981 |
| 015559 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593914.8 | 511368.0 | 39391 | 1.64041666667 | 15559 |
| 016027 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593912.3 | 511367.0 | 39393 | 1.64041666667 | 16027 |
| 017115 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593910.2 | 511366.4 | 39395 | 1.64041666667 | 17115 |
| 015949 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593907.7 | 511366.2 | 39397 | 1.64041666667 | 15949 |
| 016194 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:34pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593905.8 | 511365.2 | 39399 | 1.64041666667 | 16194 |
| 015649 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593903.1 | 511365.0 | 39401 | 1.64041666667 | 15649 |
| 014997 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:36pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593901.3 | 511365.2 | 39403 | 1.64041666667 | 14997 |
| 015351 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:37pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593899.8 | 511367.1 | 39405 | 1.64041666667 | 15351 |
| 014747 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593899.1 | 511368.9 | 39407 | 1.64041666667 | 14747 |
| 014940 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:39pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593897.4 | 511370.8 | 39409 | 1.64041666667 | 14940 |
| 014756 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:40pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593896.8 | 511372.6 | 39411 | 1.64041666667 | 14756 |
| 014990 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:41pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593897.1 | 511375.4 | 39413 | 1.64041666667 | 14990 |
| 014672 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:42pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593898.1 | 511377.5 | 39415 | 1.64041666667 | 14672 |
| 014320 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:43pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593900.6 | 511378.5 | 39417 | 1.64041666667 | 14320 |
| 014685 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:44pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593902.6 | 511379.1 | 39419 | 1.64041666667 | 14685 |
| 015618 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593905.4 | 511378.9 | 39421 | 1.64041666667 | 15618 |
| 014912 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593907.2 | 511378.6 | 39423 | 1.64041666667 | 14912 |
| 014628 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593909.7 | 511378.9 | 39425 | 1.64041666667 | 14628 |
| 014933 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593911.7 | 511378.7 | 39427 | 1.64041666667 | 14933 |
| 014955 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593914.3 | 511379.1 | 39429 | 1.64041666667 | 14955 |
| 014367 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593916.6 | 511379.4 | 39431 | 1.64041666667 | 14367 |
| 015169 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593918.5 | 511379.4 | 39433 | 1.64041666667 | 15169 |
| 015567 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593920.5 | 511379.8 | 39435 | 1.64041666667 | 15567 |
| 015281 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593923.5 | 511380.5 | 39437 | 1.64041666667 | 15281 |
| 014618 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593925.8 | 511380.6 | 39439 | 1.64041666667 | 14618 |
| 014223 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593928.7 | 511381.7 | 39441 | 1.64041666667 | 14223 |
| 013767 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593931.1 | 511382.6 | 39443 | 1.64041666667 | 13767 |
| 013211 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593933.8 | 511383.0 | 39445 | 1.64041666667 | 13211 |
| 013206 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593935.8 | 511384.3 | 39447 | 1.64041666667 | 13206 |
| 013166 | 0 | GeoXH 6000 | 08/18/2015 | 01:49:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593938.7 | 511385.0 | 39449 | 1.64041666667 | 13166 |
| 014118 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593940.7 | 511385.8 | 39451 | 1.64041666667 | 14118 |
| 014039 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593943.3 | 511387.6 | 39453 | 1.64041666667 | 14039 |
| 014144 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593945.4 | 511388.3 | 39455 | 1.64041666667 | 14144 |
| 014646 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593948.0 | 511389.4 | 39457 | 1.64041666667 | 14646 |
| 014898 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593950.3 | 511389.8 | 39459 | 1.64041666667 | 14898 |
| 015130 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593952.9 | 511389.9 | 39461 | 1.64041666667 | 15130 |
| 014878 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593955.6 | 511390.7 | 39463 | 1.64041666667 | 14878 |
| 014834 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593958.1 | 511391.0 | 39465 | 1.64041666667 | 14834 |
| 014831 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593960.5 | 511391.6 | 39467 | 1.64041666667 | 14831 |
| 015167 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593962.9 | 511392.8 | 39469 | 1.64041666667 | 15167 |
| 015251 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593964.9 | 511393.3 | 39471 | 1.64041666667 | 15251 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015126 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593966.8 | 511394.6 | 39473 | 1.64041666667 | 15126 |
| 014853 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593969.2 | 511395.6 | 39475 | 1.64041666667 | 14853 |
| 014235 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593971.7 | 511396.1 | 39477 | 1.64041666667 | 14235 |
| 013632 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593974.3 | 511397.3 | 39479 | 1.64041666667 | 13632 |
| 013563 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593976.7 | 511397.4 | 39481 | 1.64041666667 | 13563 |
| 014656 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593978.6 | 511398.1 | 39483 | 1.64041666667 | 14656 |
| 014447 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593981.2 | 511399.3 | 39485 | 1.64041666667 | 14447 |
| 013976 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593983.1 | 511399.9 | 39487 | 1.64041666667 | 13976 |
| 014559 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593985.4 | 511401.6 | 39489 | 1.64041666667 | 14559 |
| 014009 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593987.2 | 511402.9 | 39491 | 1.64041666667 | 14009 |
| 014165 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:21pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593989.2 | 511404.0 | 39493 | 1.64041666667 | 14165 |
| 014163 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:22pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593990.7 | 511406.0 | 39495 | 1.64041666667 | 14163 |
| 014094 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:23pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593993.1 | 511407.7 | 39497 | 1.64041666667 | 14094 |
| 013432 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:24pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593994.8 | 511408.3 | 39499 | 1.64041666667 | 13432 |
| 013121 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:25pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593997.1 | 511409.8 | 39501 | 1.64041666667 | 13121 |
| 013545 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:26pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593999.4 | 511410.7 | 39503 | 1.64041666667 | 13545 |
| 014137 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:27pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594002.0 | 511412.0 | 39505 | 1.64041666667 | 14137 |
| 013697 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:28pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594003.9 | 511413.2 | 39507 | 1.64041666667 | 13697 |
| 013682 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:29pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1594006.4 | 511414.4 | 39509 | 1.64041666667 | 13682 |
| 013403 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:30pm | Sensor | 1797-S0033-905-G-ACK | 6816.8 | 1594008.5 | 511415.3 | 39511 | 1.64041666667 | 13403 |
| 013307 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:31pm | Sensor | 1797-S0033-905-G-ACK | 6816.8 | 1594010.5 | 511417.3 | 39513 | 1.64041666667 | 13307 |
| 014572 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:32pm | Sensor | 1797-S0033-905-G-ACK | 6816.8 | 1594012.0 | 511418.6 | 39515 | 1.64041666667 | 14572 |
| 013942 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:33pm | Sensor | 1797-S0033-905-G-ACK | 6816.9 | 1594012.8 | 511420.3 | 39517 | 1.64041666667 | 13942 |
| 013535 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:34pm | Sensor | 1797-S0033-905-G-ACK | 6816.8 | 1594012.2 | 511422.1 | 39519 | 1.64041666667 | 13535 |
| 013253 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:35pm | Sensor | 1797-S0033-905-G-ACK | 6816.7 | 1594011.1 | 511424.0 | 39521 | 1.64041666667 | 13253 |
| 013875 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:36pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1594010.1 | 511425.1 | 39523 | 1.64041666667 | 13875 |
| 013429 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:37pm | Sensor | 1797-S0033-905-G-ACK | 6816.7 | 1594007.8 | 511426.3 | 39525 | 1.64041666667 | 13429 |
| 013396 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:38pm | Sensor | 1797-S0033-905-G-ACK | 6816.7 | 1594006.5 | 511426.8 | 39527 | 1.64041666667 | 13396 |
| 013408 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:39pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1594004.8 | 511425.1 | 39529 | 1.64041666667 | 13408 |
| 013827 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:40pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1594003.0 | 511424.2 | 39531 | 1.64041666667 | 13827 |
| 013597 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:41pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594000.7 | 511423.1 | 39533 | 1.64041666667 | 13597 |
| 015036 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:42pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1593998.7 | 511421.8 | 39535 | 1.64041666667 | 15036 |
| 014353 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:43pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593996.2 | 511420.7 | 39537 | 1.64041666667 | 14353 |
| 014186 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:44pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593994.4 | 511419.3 | 39539 | 1.64041666667 | 14186 |
| 014504 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:45pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593991.8 | 511417.5 | 39541 | 1.64041666667 | 14504 |
| 013559 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:46pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593989.7 | 511416.6 | 39543 | 1.64041666667 | 13559 |
| 013642 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:47pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593987.9 | 511414.9 | 39545 | 1.64041666667 | 13642 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:48pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593985.9 | 511413.4 | 39547 | 1.64041666667 | 14626 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593983.2 | 511412.4 | 39549 | 1.64041666667 | 14092 |
| 015262 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593981.1 | 511411.3 | 39551 | 1.64041666667 | 15262 |
| 014209 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593978.6 | 511410.2 | 39553 | 1.64041666667 | 14209 |
| 014023 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593976.7 | 511409.6 | 39555 | 1.64041666667 | 14023 |
| 013730 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593974.1 | 511407.9 | 39557 | 1.64041666667 | 13730 |
| 013678 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593971.7 | 511407.2 | 39559 | 1.64041666667 | 13678 |
| 013836 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593969.2 | 511406.1 | 39561 | 1.64041666667 | 13836 |
| 013858 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593967.5 | 511404.3 | 39563 | 1.64041666667 | 13858 |
| 014012 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593964.8 | 511403.8 | 39565 | 1.64041666667 | 14012 |
| 013659 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593962.3 | 511403.4 | 39567 | 1.64041666667 | 13659 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013859 | 0 | GeoXH 6000 | 08/18/2015 | 01:50:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593959.8 | 511402.6 | 39569 | 1.64041666667 | 13859 |
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593957.7 | 511402.5 | 39571 | 1.64041666667 | 13518 |
| 014541 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593955.6 | 511401.4 | 39573 | 1.64041666667 | 14541 |
| 014659 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593953.1 | 511400.3 | 39575 | 1.64041666667 | 14659 |
| 014568 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593950.8 | 511400.1 | 39577 | 1.64041666667 | 14568 |
| 014172 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593948.4 | 511399.0 | 39579 | 1.64041666667 | 14172 |
| 014429 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593945.5 | 511398.9 | 39581 | 1.64041666667 | 14429 |
| 014904 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593943.1 | 511398.3 | 39583 | 1.64041666667 | 14904 |
| 015336 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593940.6 | 511397.6 | 39585 | 1.64041666667 | 15336 |
| 015609 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593938.4 | 511397.5 | 39587 | 1.64041666667 | 15609 |
| 014292 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593935.6 | 511396.9 | 39589 | 1.64041666667 | 14292 |
| 013719 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593933.1 | 511397.1 | 39591 | 1.64041666667 | 13719 |
| 013543 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593930.5 | 511396.8 | 39593 | 1.64041666667 | 13543 |
| 013047 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593928.4 | 511395.9 | 39595 | 1.64041666667 | 13047 |
| 013204 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593925.8 | 511395.7 | 39597 | 1.64041666667 | 13204 |
| 014717 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593923.9 | 511395.1 | 39599 | 1.64041666667 | 14717 |
| 013851 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593921.7 | 511393.9 | 39601 | 1.64041666667 | 13851 |
| 014638 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593919.4 | 511393.4 | 39603 | 1.64041666667 | 14638 |
| 014984 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593917.3 | 511391.9 | 39605 | 1.64041666667 | 14984 |
| 014358 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593915.3 | 511390.8 | 39607 | 1.64041666667 | 14358 |
| 014397 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593913.0 | 511390.2 | 39609 | 1.64041666667 | 14397 |
| 014316 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593911.0 | 511388.7 | 39611 | 1.64041666667 | 14316 |
| 013812 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593908.8 | 511387.6 | 39613 | 1.64041666667 | 13812 |
| 015209 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593907.0 | 511386.7 | 39615 | 1.64041666667 | 15209 |
| 014810 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593905.0 | 511384.9 | 39617 | 1.64041666667 | 14810 |
| 015313 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593902.9 | 511384.3 | 39619 | 1.64041666667 | 15313 |
| 014486 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593900.4 | 511382.9 | 39621 | 1.64041666667 | 14486 |
| 014163 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593898.6 | 511381.7 | 39623 | 1.64041666667 | 14163 |
| 014627 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:27pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593896.4 | 511383.1 | 39625 | 1.64041666667 | 14627 |
| 015007 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:28pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593894.8 | 511384.8 | 39627 | 1.64041666667 | 15007 |
| 014876 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593893.9 | 511386.9 | 39629 | 1.64041666667 | 14876 |
| 015328 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593893.8 | 511389.3 | 39631 | 1.64041666667 | 15328 |
| 015139 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593893.5 | 511392.2 | 39633 | 1.64041666667 | 15139 |
| 015131 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:32pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593894.4 | 511394.2 | 39635 | 1.64041666667 | 15131 |
| 014811 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:33pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593896.2 | 511396.4 | 39637 | 1.64041666667 | 14811 |
| 015246 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:34pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593897.7 | 511397.2 | 39639 | 1.64041666667 | 15246 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593900.3 | 511397.5 | 39641 | 1.64041666667 | 14516 |
| 013865 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:36pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593902.5 | 511398.0 | 39643 | 1.64041666667 | 13865 |
| 013814 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:37pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593904.8 | 511398.1 | 39645 | 1.64041666667 | 13814 |
| 015158 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:38pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593906.8 | 511399.4 | 39647 | 1.64041666667 | 15158 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:39pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593909.4 | 511400.5 | 39649 | 1.64041666667 | 14609 |
| 015387 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593911.4 | 511401.0 | 39651 | 1.64041666667 | 15387 |
| 014797 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593914.1 | 511402.0 | 39653 | 1.64041666667 | 14797 |
| 014316 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593916.5 | 511401.8 | 39655 | 1.64041666667 | 14316 |
| 013970 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593919.0 | 511401.6 | 39657 | 1.64041666667 | 13970 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593921.0 | 511402.3 | 39659 | 1.64041666667 | 13738 |
| 014020 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593923.4 | 511402.8 | 39661 | 1.64041666667 | 14020 |
| 014021 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593925.1 | 511403.3 | 39663 | 1.64041666667 | 14021 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014014 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593927.8 | 511405.0 | 39665 | 1.64041666667 | 14014 |
| 013635 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593929.8 | 511405.3 | 39667 | 1.64041666667 | 13635 |
| 013647 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593932.8 | 511405.4 | 39669 | 1.64041666667 | 13647 |
| 013781 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593934.8 | 511406.3 | 39671 | 1.64041666667 | 13781 |
| 013804 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593937.6 | 511406.7 | 39673 | 1.64041666667 | 13804 |
| 013547 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593939.6 | 511407.5 | 39675 | 1.64041666667 | 13547 |
| 013740 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593942.2 | 511408.7 | 39677 | 1.64041666667 | 13740 |
| 014164 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593944.5 | 511409.1 | 39679 | 1.64041666667 | 14164 |
| 013554 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593947.1 | 511410.1 | 39681 | 1.64041666667 | 13554 |
| 013857 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593948.9 | 511410.9 | 39683 | 1.64041666667 | 13857 |
| 013914 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593951.3 | 511411.3 | 39685 | 1.64041666667 | 13914 |
| 015274 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593953.5 | 511412.2 | 39687 | 1.64041666667 | 15274 |
| 014599 | 0 | GeoXH 6000 | 08/18/2015 | 01:51:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593956.2 | 511412.8 | 39689 | 1.64041666667 | 14599 |
| 013627 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593958.5 | 511413.4 | 39691 | 1.64041666667 | 13627 |
| 013447 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593961.0 | 511414.8 | 39693 | 1.64041666667 | 13447 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593962.9 | 511415.4 | 39695 | 1.64041666667 | 14246 |
| 013998 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593965.6 | 511416.0 | 39697 | 1.64041666667 | 13998 |
| 013904 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593967.9 | 511417.1 | 39699 | 1.64041666667 | 13904 |
| 014781 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593970.3 | 511417.6 | 39701 | 1.64041666667 | 14781 |
| 013939 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593972.0 | 511418.7 | 39703 | 1.64041666667 | 13939 |
| 014403 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593974.6 | 511420.4 | 39705 | 1.64041666667 | 14403 |
| 014139 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:08pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593976.7 | 511421.1 | 39707 | 1.64041666667 | 14139 |
| 014958 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593979.0 | 511422.6 | 39709 | 1.64041666667 | 14958 |
| 014504 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:10pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593980.9 | 511423.5 | 39711 | 1.64041666667 | 14504 |
| 014308 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:11pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593983.2 | 511424.9 | 39713 | 1.64041666667 | 14308 |
| 014686 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:12pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593984.3 | 511426.2 | 39715 | 1.64041666667 | 14686 |
| 014193 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:13pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593986.5 | 511427.6 | 39717 | 1.64041666667 | 14193 |
| 013796 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:14pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593987.9 | 511429.3 | 39719 | 1.64041666667 | 13796 |
| 014203 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:15pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593990.4 | 511431.2 | 39721 | 1.64041666667 | 14203 |
| 014596 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:16pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593992.4 | 511431.8 | 39723 | 1.64041666667 | 14596 |
| 014975 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:17pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593994.5 | 511433.4 | 39725 | 1.64041666667 | 14975 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:18pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593996.1 | 511434.3 | 39727 | 1.64041666667 | 13861 |
| 013414 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:19pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593997.3 | 511435.6 | 39729 | 1.64041666667 | 13414 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:20pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1593997.0 | 511437.3 | 39731 | 1.64041666667 | 13050 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:21pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593997.3 | 511439.4 | 39733 | 1.64041666667 | 13453 |
| 013342 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:22pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1593996.9 | 511441.4 | 39735 | 1.64041666667 | 13342 |
| 014097 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:23pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1593996.0 | 511444.1 | 39737 | 1.64041666667 | 14097 |
| 013780 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:24pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593995.8 | 511446.0 | 39739 | 1.64041666667 | 13780 |
| 013083 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:25pm | Sensor | 1797-S0033-905-G-ACK | 6816.7 | 1593994.5 | 511447.3 | 39741 | 1.64041666667 | 13083 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:26pm | Sensor | 1797-S0033-905-G-ACK | 6816.7 | 1593993.3 | 511447.9 | 39743 | 1.64041666667 | 13442 |
| 013606 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:27pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593991.1 | 511446.9 | 39745 | 1.64041666667 | 13606 |
| 013458 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:28pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593989.5 | 511445.6 | 39747 | 1.64041666667 | 13458 |
| 013848 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:29pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1593987.3 | 511444.7 | 39749 | 1.64041666667 | 13848 |
| 013954 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:30pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593985.8 | 511443.0 | 39751 | 1.64041666667 | 13954 |
| 013721 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:31pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593983.7 | 511441.5 | 39753 | 1.64041666667 | 13721 |
| 013718 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:32pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593981.9 | 511441.2 | 39755 | 1.64041666667 | 13718 |
| 014166 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:33pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593979.7 | 511440.1 | 39757 | 1.64041666667 | 14166 |
| 013331 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:34pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593978.0 | 511439.1 | 39759 | 1.64041666667 | 13331 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014654 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:35pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593976.0 | 511437.7 | 39761 | 1.64041666667 | 14654 |
| 014437 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593974.7 | 511436.1 | 39763 | 1.64041666667 | 14437 |
| 015043 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593973.2 | 511434.5 | 39765 | 1.64041666667 | 15043 |
| 014492 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593971.7 | 511433.3 | 39767 | 1.64041666667 | 14492 |
| 014369 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593970.5 | 511431.4 | 39769 | 1.64041666667 | 14369 |
| 015117 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593968.3 | 511430.8 | 39771 | 1.64041666667 | 15117 |
| 014953 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593965.7 | 511429.4 | 39773 | 1.64041666667 | 14953 |
| 014756 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593963.9 | 511428.1 | 39775 | 1.64041666667 | 14756 |
| 014615 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593961.5 | 511427.1 | 39777 | 1.64041666667 | 14615 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593959.8 | 511425.8 | 39779 | 1.64041666667 | 14078 |
| 014001 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593957.3 | 511424.1 | 39781 | 1.64041666667 | 14001 |
| 014573 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593955.3 | 511423.5 | 39783 | 1.64041666667 | 14573 |
| 014925 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593953.3 | 511421.5 | 39785 | 1.64041666667 | 14925 |
| 013998 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593951.3 | 511420.6 | 39787 | 1.64041666667 | 13998 |
| 015066 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593949.0 | 511418.9 | 39789 | 1.64041666667 | 15066 |
| 014400 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593947.1 | 511417.3 | 39791 | 1.64041666667 | 14400 |
| 014302 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593944.5 | 511416.2 | 39793 | 1.64041666667 | 14302 |
| 014780 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593943.2 | 511415.1 | 39795 | 1.64041666667 | 14780 |
| 013586 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593940.6 | 511414.1 | 39797 | 1.64041666667 | 13586 |
| 013724 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:54pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593938.9 | 511413.1 | 39799 | 1.64041666667 | 13724 |
| 014012 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593937.1 | 511411.5 | 39801 | 1.64041666667 | 14012 |
| 014182 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593935.5 | 511411.3 | 39803 | 1.64041666667 | 14182 |
| 013842 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593932.6 | 511411.2 | 39805 | 1.64041666667 | 13842 |
| 013808 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593930.9 | 511411.6 | 39807 | 1.64041666667 | 13808 |
| 014240 | 0 | GeoXH 6000 | 08/18/2015 | 01:52:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593928.8 | 511410.5 | 39809 | 1.64041666667 | 14240 |
| 013380 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593926.8 | 511410.3 | 39811 | 1.64041666667 | 13380 |
| 012783 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593924.5 | 511409.6 | 39813 | 1.64041666667 | 12783 |
| 013940 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:02pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593922.1 | 511409.1 | 39815 | 1.64041666667 | 13940 |
| 014044 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593919.8 | 511409.3 | 39817 | 1.64041666667 | 14044 |
| 014402 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593917.9 | 511409.1 | 39819 | 1.64041666667 | 14402 |
| 013793 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593915.5 | 511409.6 | 39821 | 1.64041666667 | 13793 |
| 013834 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:06pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593913.4 | 511409.0 | 39823 | 1.64041666667 | 13834 |
| 013849 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:07pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593910.6 | 511409.1 | 39825 | 1.64041666667 | 13849 |
| 013917 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:08pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593908.3 | 511409.4 | 39827 | 1.64041666667 | 13917 |
| 014001 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:09pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593905.6 | 511409.1 | 39829 | 1.64041666667 | 14001 |
| 014340 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:10pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593903.1 | 511409.6 | 39831 | 1.64041666667 | 14340 |
| 014014 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:11pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593900.8 | 511410.3 | 39833 | 1.64041666667 | 14014 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:12pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593898.9 | 511409.9 | 39835 | 1.64041666667 | 14092 |
| 014902 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:13pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593896.4 | 511409.5 | 39837 | 1.64041666667 | 14902 |
| 014270 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:14pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593894.5 | 511408.8 | 39839 | 1.64041666667 | 14270 |
| 013944 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:15pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593892.3 | 511407.5 | 39841 | 1.64041666667 | 13944 |
| 014398 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:16pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593890.3 | 511407.3 | 39843 | 1.64041666667 | 14398 |
| 014511 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593887.9 | 511406.2 | 39845 | 1.64041666667 | 14511 |
| 014538 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:18pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593886.2 | 511405.2 | 39847 | 1.64041666667 | 14538 |
| 014282 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593884.2 | 511405.5 | 39849 | 1.64041666667 | 14282 |
| 014034 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:20pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593883.7 | 511407.1 | 39851 | 1.64041666667 | 14034 |
| 013864 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593883.3 | 511409.4 | 39853 | 1.64041666667 | 13864 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:22pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593883.8 | 511411.3 | 39855 | 1.64041666667 | 13738 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013788 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:23pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593884.1 | 511414.1 | 39857 | 1.64041666667 | 13788 |
| 013815 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:24pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593884.5 | 511416.2 | 39859 | 1.64041666667 | 13815 |
| 014851 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:25pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593886.0 | 511418.5 | 39861 | 1.64041666667 | 14851 |
| 013829 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:26pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593887.4 | 511419.3 | 39863 | 1.64041666667 | 13829 |
| 014798 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:27pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593890.1 | 511419.1 | 39865 | 1.64041666667 | 14798 |
| 014579 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:28pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593892.2 | 511418.5 | 39867 | 1.64041666667 | 14579 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593894.5 | 511418.4 | 39869 | 1.64041666667 | 14246 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593896.4 | 511417.8 | 39871 | 1.64041666667 | 13953 |
| 015611 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:31pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593898.6 | 511417.8 | 39873 | 1.64041666667 | 15611 |
| 014864 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:32pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593900.5 | 511417.5 | 39875 | 1.64041666667 | 14864 |
| 014571 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:33pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593902.8 | 511417.5 | 39877 | 1.64041666667 | 14571 |
| 014691 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:34pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593905.0 | 511418.0 | 39879 | 1.64041666667 | 14691 |
| 014826 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593907.6 | 511417.4 | 39881 | 1.64041666667 | 14826 |
| 014745 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:36pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593909.3 | 511417.1 | 39883 | 1.64041666667 | 14745 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593912.0 | 511416.4 | 39885 | 1.64041666667 | 14609 |
| 014307 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593914.0 | 511415.4 | 39887 | 1.64041666667 | 14307 |
| 013845 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593916.5 | 511415.3 | 39889 | 1.64041666667 | 13845 |
| 013855 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593918.7 | 511415.2 | 39891 | 1.64041666667 | 13855 |
| 013876 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593921.1 | 511414.6 | 39893 | 1.64041666667 | 13876 |
| 014870 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593923.1 | 511415.0 | 39895 | 1.64041666667 | 14870 |
| 015039 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593925.4 | 511415.5 | 39897 | 1.64041666667 | 15039 |
| 014242 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593927.6 | 511415.2 | 39899 | 1.64041666667 | 14242 |
| 014281 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593930.2 | 511416.8 | 39901 | 1.64041666667 | 14281 |
| 014205 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:45pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593932.3 | 511417.4 | 39902 | 1.64041666667 | 14205 |
| 013503 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593935.4 | 511417.5 | 39905 | 1.64041666667 | 13503 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593937.5 | 511417.5 | 39907 | 1.64041666667 | 13738 |
| 013097 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593939.9 | 511417.3 | 39909 | 1.64041666667 | 13097 |
| 013195 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593942.4 | 511417.1 | 39911 | 1.64041666667 | 13195 |
| 013444 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593945.0 | 511418.0 | 39913 | 1.64041666667 | 13444 |
| 013000 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593947.2 | 511419.0 | 39915 | 1.64041666667 | 13000 |
| 012787 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593949.9 | 511419.2 | 39917 | 1.64041666667 | 12787 |
| 013568 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593951.5 | 511420.6 | 39919 | 1.64041666667 | 13568 |
| 014292 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593952.7 | 511422.1 | 39921 | 1.64041666667 | 14292 |
| 014616 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593953.7 | 511423.8 | 39923 | 1.64041666667 | 14616 |
| 013914 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.1 | 511425.9 | 39925 | 1.64041666667 | 13914 |
| 013706 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511426.8 | 39927 | 1.64041666667 | 13706 |
| 013710 | 0 | GeoXH 6000 | 08/18/2015 | 01:53:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593955.5 | 511428.4 | 39929 | 1.64041666667 | 13710 |
| 014777 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593957.6 | 511429.7 | 39931 | 1.64041666667 | 14777 |
| 014702 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593959.8 | 511431.2 | 39933 | 1.64041666667 | 14702 |
| 014382 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593961.7 | 511432.5 | 39935 | 1.64041666667 | 14382 |
| 014322 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593964.5 | 511432.1 | 39937 | 1.64041666667 | 14322 |
| 014769 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593966.7 | 511432.7 | 39939 | 1.64041666667 | 14769 |
| 014135 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593969.1 | 511433.6 | 39941 | 1.64041666667 | 14135 |
| 014333 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593971.2 | 511434.7 | 39943 | 1.64041666667 | 14333 |
| 013822 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593973.1 | 511436.7 | 39945 | 1.64041666667 | 13822 |
| 013932 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593974.9 | 511437.9 | 39947 | 1.64041666667 | 13932 |
| 014579 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593976.9 | 511439.3 | 39949 | 1.64041666667 | 14579 |
| 014373 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593977.7 | 511441.6 | 39951 | 1.64041666667 | 14373 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014317 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593979.6 | 511443.7 | 39953 | 1.64041666667 | 14317 |
| 014496 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:12pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593981.4 | 511445.2 | 39955 | 1.64041666667 | 14496 |
| 013396 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:13pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593982.9 | 511447.5 | 39957 | 1.64041666667 | 13396 |
| 013423 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:14pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593984.3 | 511449.0 | 39959 | 1.64041666667 | 13423 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:15pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593986.1 | 511450.8 | 39961 | 1.64041666667 | 14158 |
| 013903 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:16pm | Sensor | 1797-S0033-905-G-ACK | 6816.7 | 1593987.5 | 511452.7 | 39963 | 1.64041666667 | 13903 |
| 014646 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:17pm | Sensor | 1797-S0033-905-G-ACK | 6816.9 | 1593989.7 | 511454.1 | 39965 | 1.64041666667 | 14646 |
| 013586 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:18pm | Sensor | 1797-S0033-905-G-ACK | 6817.1 | 1593992.0 | 511455.0 | 39967 | 1.64041666667 | 13586 |
| 014182 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:19pm | Sensor | 1797-S0033-905-G-ACK | 6817.1 | 1593994.0 | 511456.1 | 39969 | 1.64041666667 | 14182 |
| 013947 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:20pm | Sensor | 1797-S0033-905-G-ACK | 6817.1 | 1593995.2 | 511456.8 | 39971 | 1.64041666667 | 13947 |
| 012855 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:21pm | Sensor | 1797-S0033-905-G-ACK | 6817.2 | 1593994.5 | 511458.7 | 39973 | 1.64041666667 | 12855 |
| 012661 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:22pm | Sensor | 1797-S0033-905-G-ACK | 6817.3 | 1593993.1 | 511460.2 | 39975 | 1.64041666667 | 12661 |
| 013774 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:23pm | Sensor | 1797-S0033-905-G-ACK | 6817.4 | 1593991.7 | 511462.3 | 39977 | 1.64041666667 | 13774 |
| 013103 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:24pm | Sensor | 1797-S0033-905-G-ACK | 6817.4 | 1593990.5 | 511463.6 | 39979 | 1.64041666667 | 13103 |
| 013078 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:25pm | Sensor | 1797-S0033-905-G-ACK | 6817.4 | 1593988.7 | 511463.6 | 39981 | 1.64041666667 | 13078 |
| 013319 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:26pm | Sensor | 1797-S0033-905-G-ACK | 6817.5 | 1593987.5 | 511463.6 | 39983 | 1.64041666667 | 13319 |
| 014264 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:27pm | Sensor | 1797-S0033-905-G-ACK | 6817.4 | 1593986.0 | 511462.8 | 39985 | 1.64041666667 | 14264 |
| 013558 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:28pm | Sensor | 1797-S0033-905-G-ACK | 6817.3 | 1593984.0 | 511461.9 | 39987 | 1.64041666667 | 13558 |
| 013739 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:29pm | Sensor | 1797-S0033-905-G-ACK | 6817.0 | 1593981.2 | 511461.2 | 39989 | 1.64041666667 | 13739 |
| 014313 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:30pm | Sensor | 1797-S0033-905-G-ACK | 6817.0 | 1593979.1 | 511460.9 | 39991 | 1.64041666667 | 14313 |
| 014208 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:31pm | Sensor | 1797-S0033-905-G-ACK | 6816.9 | 1593976.7 | 511459.6 | 39993 | 1.64041666667 | 14208 |
| 013872 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:32pm | Sensor | 1797-S0033-905-G-ACK | 6816.8 | 1593974.8 | 511459.2 | 39995 | 1.64041666667 | 13872 |
| 014575 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:33pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1593972.6 | 511458.1 | 39997 | 1.64041666667 | 14575 |
| 015451 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:33pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593970.7 | 511457.1 | 39998 | 1.64041666667 | 15451 |
| 015651 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:35pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593967.7 | 511456.2 | 40001 | 1.64041666667 | 15651 |
| 015081 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:36pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593966.1 | 511454.9 | 40003 | 1.64041666667 | 15081 |
| 015353 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593963.8 | 511453.8 | 40005 | 1.64041666667 | 15353 |
| 014621 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593961.9 | 511453.2 | 40007 | 1.64041666667 | 14621 |
| 013504 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593959.5 | 511451.5 | 40009 | 1.64041666667 | 13504 |
| 013303 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593956.9 | 511450.7 | 40011 | 1.64041666667 | 13303 |
| 013911 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593954.2 | 511449.3 | 40013 | 1.64041666667 | 13911 |
| 014312 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593952.4 | 511448.0 | 40015 | 1.64041666667 | 14312 |
| 015295 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593949.8 | 511447.5 | 40017 | 1.64041666667 | 15295 |
| 015226 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593947.9 | 511446.2 | 40019 | 1.64041666667 | 15226 |
| 014925 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593944.5 | 511444.5 | 40021 | 1.64041666667 | 14925 |
| 014365 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593942.4 | 511443.9 | 40023 | 1.64041666667 | 14365 |
| 013458 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:47pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593939.7 | 511442.1 | 40025 | 1.64041666667 | 13458 |
| 013637 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:48pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593937.7 | 511441.3 | 40027 | 1.64041666667 | 13637 |
| 013851 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593935.4 | 511440.1 | 40029 | 1.64041666667 | 13851 |
| 013723 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:50pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593933.4 | 511438.9 | 40031 | 1.64041666667 | 13723 |
| 014004 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593930.8 | 511437.8 | 40033 | 1.64041666667 | 14004 |
| 013600 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593928.3 | 511436.4 | 40035 | 1.64041666667 | 13600 |
| 014512 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593926.3 | 511435.9 | 40037 | 1.64041666667 | 14512 |
| 014666 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593924.0 | 511434.8 | 40039 | 1.64041666667 | 14666 |
| 014624 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593921.6 | 511433.4 | 40041 | 1.64041666667 | 14624 |
| 014459 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:56pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593919.8 | 511432.9 | 40043 | 1.64041666667 | 14459 |
| 015468 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:57pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593917.6 | 511431.0 | 40045 | 1.64041666667 | 15468 |
| 014520 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:58pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593915.8 | 511429.9 | 40047 | 1.64041666667 | 14520 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 01:54:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593913.5 | 511428.1 | 40049 | 1.64041666667 | 14482 |
| 014199 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593912.5 | 511426.2 | 40051 | 1.64041666667 | 14199 |
| 014737 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:01pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593910.9 | 511424.3 | 40053 | 1.64041666667 | 14737 |
| 015137 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:02pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593909.4 | 511422.7 | 40055 | 1.64041666667 | 15137 |
| 014814 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:03pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593907.9 | 511420.1 | 40057 | 1.64041666667 | 14814 |
| 015225 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:04pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593906.2 | 511419.0 | 40059 | 1.64041666667 | 15225 |
| 014954 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:05pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593904.9 | 511417.7 | 40061 | 1.64041666667 | 14954 |
| 014261 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:06pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593904.1 | 511417.2 | 40063 | 1.64041666667 | 14261 |
| 014157 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:07pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593902.8 | 511416.4 | 40065 | 1.64041666667 | 14157 |
| 013978 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:08pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593902.4 | 511416.5 | 40067 | 1.64041666667 | 13978 |
| 013735 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:09pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593902.4 | 511416.6 | 40069 | 1.64041666667 | 13735 |
| 013823 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:10pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593902.4 | 511416.5 | 40071 | 1.64041666667 | 13823 |
| 013948 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:11pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593902.7 | 511417.1 | 40073 | 1.64041666667 | 13948 |
| 014506 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:12pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593901.1 | 511417.1 | 40075 | 1.64041666667 | 14506 |
| 013904 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:13pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593898.9 | 511417.7 | 40077 | 1.64041666667 | 13904 |
| 015021 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:14pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593897.5 | 511418.6 | 40079 | 1.64041666667 | 15021 |
| 013902 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:15pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593896.3 | 511421.0 | 40081 | 1.64041666667 | 13902 |
| 014434 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:16pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593895.9 | 511422.9 | 40083 | 1.64041666667 | 14434 |
| 014037 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593895.3 | 511425.5 | 40085 | 1.64041666667 | 14037 |
| 013341 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:18pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593896.1 | 511427.4 | 40087 | 1.64041666667 | 13341 |
| 013669 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.4 | 1593898.3 | 511429.1 | 40089 | 1.64041666667 | 13669 |
| 013554 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:20pm | Sensor | 1797-S0033-905-G-ACK | 6814.5 | 1593900.2 | 511429.6 | 40091 | 1.64041666667 | 13554 |
| 013444 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593902.1 | 511428.2 | 40093 | 1.64041666667 | 13444 |
| 013142 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:22pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593903.8 | 511427.3 | 40095 | 1.64041666667 | 13142 |
| 014000 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:23pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593905.0 | 511425.4 | 40097 | 1.64041666667 | 14000 |
| 013387 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:24pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593906.7 | 511424.4 | 40099 | 1.64041666667 | 13387 |
| 013590 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:25pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593908.7 | 511423.5 | 40101 | 1.64041666667 | 13590 |
| 013832 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:26pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593910.1 | 511422.6 | 40103 | 1.64041666667 | 13832 |
| 013825 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:27pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593912.6 | 511423.0 | 40105 | 1.64041666667 | 13825 |
| 013619 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:28pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593914.3 | 511422.8 | 40107 | 1.64041666667 | 13619 |
| 014156 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:29pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593916.4 | 511423.8 | 40109 | 1.64041666667 | 14156 |
| 014472 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593918.2 | 511424.7 | 40111 | 1.64041666667 | 14472 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593920.4 | 511425.3 | 40113 | 1.64041666667 | 14081 |
| 014265 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593921.5 | 511426.5 | 40115 | 1.64041666667 | 14265 |
| 014977 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593923.8 | 511427.5 | 40117 | 1.64041666667 | 14977 |
| 014477 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593925.6 | 511428.6 | 40119 | 1.64041666667 | 14477 |
| 014615 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593927.2 | 511430.2 | 40121 | 1.64041666667 | 14615 |
| 014491 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593929.7 | 511430.5 | 40123 | 1.64041666667 | 14491 |
| 014729 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:37pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593932.0 | 511432.0 | 40125 | 1.64041666667 | 14729 |
| 015267 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:38pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593934.1 | 511432.8 | 40127 | 1.64041666667 | 15267 |
| 014588 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:39pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593937.1 | 511433.8 | 40129 | 1.64041666667 | 14588 |
| 015960 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593939.1 | 511434.6 | 40131 | 1.64041666667 | 15960 |
| 015592 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593941.5 | 511434.7 | 40133 | 1.64041666667 | 15592 |
| 015438 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:42pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593943.2 | 511435.7 | 40135 | 1.64041666667 | 15438 |
| 015381 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593945.2 | 511436.8 | 40137 | 1.64041666667 | 15381 |
| 015012 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593947.4 | 511438.2 | 40139 | 1.64041666667 | 15012 |
| 014422 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593949.2 | 511440.0 | 40141 | 1.64041666667 | 14422 |
| 015252 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593951.1 | 511441.0 | 40143 | 1.64041666667 | 15252 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014632 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593952.6 | 511442.9 | 40145 | 1.64041666667 | 14632 |
| 015145 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593954.7 | 511443.7 | 40147 | 1.64041666667 | 15145 |
| 015006 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593956.7 | 511444.9 | 40149 | 1.64041666667 | 15006 |
| 015581 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593958.4 | 511445.4 | 40151 | 1.64041666667 | 15581 |
| 014929 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593959.8 | 511446.6 | 40153 | 1.64041666667 | 14929 |
| 014877 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593961.8 | 511447.8 | 40155 | 1.64041666667 | 14877 |
| 015298 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593963.8 | 511449.1 | 40157 | 1.64041666667 | 15298 |
| 015265 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593965.3 | 511450.1 | 40159 | 1.64041666667 | 15265 |
| 014579 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593967.5 | 511450.5 | 40161 | 1.64041666667 | 14579 |
| 014261 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593968.7 | 511451.6 | 40163 | 1.64041666667 | 14261 |
| 014411 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:57pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593970.6 | 511452.2 | 40165 | 1.64041666667 | 14411 |
| 014249 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:58pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593971.4 | 511453.4 | 40167 | 1.64041666667 | 14249 |
| 014187 | 0 | GeoXH 6000 | 08/18/2015 | 01:55:59pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593973.7 | 511454.7 | 40169 | 1.64041666667 | 14187 |
| 014250 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:00pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1593975.6 | 511455.5 | 40171 | 1.64041666667 | 14250 |
| 013348 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:01pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593977.3 | 511456.7 | 40173 | 1.64041666667 | 13348 |
| 013741 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:02pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593979.0 | 511456.1 | 40175 | 1.64041666667 | 13741 |
| 014186 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:03pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593981.6 | 511455.5 | 40177 | 1.64041666667 | 14186 |
| 013912 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:04pm | Sensor | 1797-S0033-905-G-ACK | 6816.6 | 1593983.1 | 511454.1 | 40179 | 1.64041666667 | 13912 |
| 013361 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:05pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593983.2 | 511452.3 | 40181 | 1.64041666667 | 13361 |
| 014490 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:05pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593983.1 | 511450.3 | 40182 | 1.64041666667 | 14490 |
| 013813 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:07pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593980.8 | 511449.7 | 40185 | 1.64041666667 | 13813 |
| 013725 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:08pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593979.3 | 511448.6 | 40187 | 1.64041666667 | 13725 |
| 013473 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593978.0 | 511448.0 | 40189 | 1.64041666667 | 13473 |
| 013143 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593976.8 | 511446.7 | 40190 | 1.64041666667 | 13143 |
| 012913 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593976.1 | 511444.7 | 40193 | 1.64041666667 | 12913 |
| 013068 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593974.6 | 511444.9 | 40195 | 1.64041666667 | 13068 |
| 013936 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593972.7 | 511444.0 | 40197 | 1.64041666667 | 13936 |
| 014229 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593971.1 | 511443.7 | 40198 | 1.64041666667 | 14229 |
| 014881 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593969.0 | 511443.1 | 40201 | 1.64041666667 | 14881 |
| 014490 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593967.6 | 511441.7 | 40203 | 1.64041666667 | 14490 |
| 014638 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593965.3 | 511441.2 | 40205 | 1.64041666667 | 14638 |
| 015314 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593963.6 | 511440.9 | 40207 | 1.64041666667 | 15314 |
| 015911 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593961.7 | 511439.8 | 40209 | 1.64041666667 | 15911 |
| 015347 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593959.8 | 511439.7 | 40211 | 1.64041666667 | 15347 |
| 015383 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593958.2 | 511438.4 | 40213 | 1.64041666667 | 15383 |
| 014630 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593956.2 | 511437.7 | 40215 | 1.64041666667 | 14630 |
| 014087 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.5 | 511437.2 | 40217 | 1.64041666667 | 14087 |
| 014831 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593952.9 | 511436.6 | 40219 | 1.64041666667 | 14831 |
| 014462 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593950.7 | 511436.0 | 40221 | 1.64041666667 | 14462 |
| 014375 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593948.5 | 511435.0 | 40223 | 1.64041666667 | 14375 |
| 013696 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593946.2 | 511434.9 | 40225 | 1.64041666667 | 13696 |
| 014394 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593944.6 | 511434.1 | 40227 | 1.64041666667 | 14394 |
| 014156 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593942.1 | 511434.4 | 40229 | 1.64041666667 | 14156 |
| 013850 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:30pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593940.4 | 511434.3 | 40231 | 1.64041666667 | 13850 |
| 013843 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:31pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593938.1 | 511434.6 | 40233 | 1.64041666667 | 13843 |
| 014897 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593936.3 | 511435.3 | 40235 | 1.64041666667 | 14897 |
| 015317 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593934.8 | 511435.6 | 40237 | 1.64041666667 | 15317 |
| 015516 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593934.6 | 511436.0 | 40239 | 1.64041666667 | 15516 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015230 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593935.1 | 511434.3 | 40241 | 1.64041666667 | 15230 |
| 015077 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593936.0 | 511432.9 | 40242 | 1.64041666667 | 15077 |
| 014751 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593936.8 | 511430.8 | 40245 | 1.64041666667 | 14751 |
| 014252 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:38pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593937.6 | 511429.0 | 40247 | 1.64041666667 | 14252 |
| 015104 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:39pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593936.7 | 511427.3 | 40249 | 1.64041666667 | 15104 |
| 015411 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:40pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593935.7 | 511425.3 | 40251 | 1.64041666667 | 15411 |
| 015779 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:41pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593933.9 | 511424.1 | 40253 | 1.64041666667 | 15779 |
| 015565 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:42pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593932.3 | 511422.8 | 40255 | 1.64041666667 | 15565 |
| 014140 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:43pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593929.7 | 511423.5 | 40257 | 1.64041666667 | 14140 |
| 013864 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593927.7 | 511424.4 | 40259 | 1.64041666667 | 13864 |
| 014338 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593926.0 | 511425.1 | 40261 | 1.64041666667 | 14338 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593924.7 | 511425.8 | 40263 | 1.64041666667 | 13915 |
| 014442 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593922.7 | 511425.3 | 40265 | 1.64041666667 | 14442 |
| 014183 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593920.9 | 511425.5 | 40267 | 1.64041666667 | 14183 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593918.3 | 511424.8 | 40269 | 1.64041666667 | 13738 |
| 014178 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:50pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593915.7 | 511424.5 | 40271 | 1.64041666667 | 14178 |
| 013810 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593913.9 | 511425.7 | 40273 | 1.64041666667 | 13810 |
| 013895 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:52pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593912.1 | 511427.3 | 40275 | 1.64041666667 | 13895 |
| 014348 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593911.5 | 511429.6 | 40277 | 1.64041666667 | 14348 |
| 014213 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593911.6 | 511431.2 | 40279 | 1.64041666667 | 14213 |
| 014760 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593912.3 | 511432.3 | 40281 | 1.64041666667 | 14760 |
| 013710 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593913.4 | 511431.3 | 40283 | 1.64041666667 | 13710 |
| 013337 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593915.1 | 511429.7 | 40285 | 1.64041666667 | 13337 |
| 014109 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593915.3 | 511427.9 | 40287 | 1.64041666667 | 14109 |
| 014176 | 0 | GeoXH 6000 | 08/18/2015 | 01:56:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593916.2 | 511425.1 | 40289 | 1.64041666667 | 14176 |
| 014064 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593916.7 | 511423.1 | 40291 | 1.64041666667 | 14064 |
| 014083 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593916.5 | 511420.8 | 40293 | 1.64041666667 | 14083 |
| 014897 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593917.3 | 511418.7 | 40295 | 1.64041666667 | 14897 |
| 015047 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593917.7 | 511416.9 | 40297 | 1.64041666667 | 15047 |
| 014771 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593919.0 | 511416.0 | 40299 | 1.64041666667 | 14771 |
| 014159 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593921.8 | 511415.2 | 40301 | 1.64041666667 | 14159 |
| 014017 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593923.7 | 511414.5 | 40303 | 1.64041666667 | 14017 |
| 014357 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593925.9 | 511414.8 | 40305 | 1.64041666667 | 14357 |
| 013851 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593928.0 | 511414.4 | 40307 | 1.64041666667 | 13851 |
| 013596 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:09pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593930.1 | 511414.6 | 40309 | 1.64041666667 | 13596 |
| 014120 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593932.7 | 511416.0 | 40311 | 1.64041666667 | 14120 |
| 014055 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593934.9 | 511416.5 | 40313 | 1.64041666667 | 14055 |
| 013561 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593936.3 | 511418.2 | 40315 | 1.64041666667 | 13561 |
| 012968 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593938.4 | 511419.8 | 40317 | 1.64041666667 | 12968 |
| 013399 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593940.3 | 511421.6 | 40319 | 1.64041666667 | 13399 |
| 014640 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593941.7 | 511423.1 | 40321 | 1.64041666667 | 14640 |
| 014520 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593943.8 | 511423.3 | 40323 | 1.64041666667 | 14520 |
| 014152 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593945.9 | 511424.1 | 40325 | 1.64041666667 | 14152 |
| 014290 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593947.4 | 511424.3 | 40327 | 1.64041666667 | 14290 |
| 014638 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593950.1 | 511424.5 | 40329 | 1.64041666667 | 14638 |
| 014204 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593952.5 | 511425.2 | 40331 | 1.64041666667 | 14204 |
| 014357 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.5 | 511425.2 | 40333 | 1.64041666667 | 14357 |
| 014203 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593956.4 | 511425.7 | 40335 | 1.64041666667 | 14203 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014484 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593958.3 | 511424.4 | 40337 | 1.64041666667 | 14484 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593960.1 | 511423.0 | 40339 | 1.64041666667 | 14072 |
| 014613 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593961.6 | 511421.6 | 40341 | 1.64041666667 | 14613 |
| 014047 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593962.7 | 511419.8 | 40343 | 1.64041666667 | 14047 |
| 013796 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593964.9 | 511418.0 | 40345 | 1.64041666667 | 13796 |
| 013857 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593966.2 | 511416.3 | 40347 | 1.64041666667 | 13857 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593967.7 | 511414.1 | 40349 | 1.64041666667 | 14570 |
| 014398 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593969.3 | 511413.1 | 40351 | 1.64041666667 | 14398 |
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593970.9 | 511410.9 | 40353 | 1.64041666667 | 14819 |
| 014673 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593972.5 | 511410.0 | 40354 | 1.64041666667 | 14673 |
| 015056 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593975.7 | 511408.0 | 40357 | 1.64041666667 | 15056 |
| 015451 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593976.7 | 511407.3 | 40358 | 1.64041666667 | 15451 |
| 014601 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593979.4 | 511406.4 | 40361 | 1.64041666667 | 14601 |
| 013793 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593980.5 | 511405.1 | 40363 | 1.64041666667 | 13793 |
| 013443 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593982.7 | 511403.9 | 40365 | 1.64041666667 | 13443 |
| 013217 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593984.5 | 511403.0 | 40366 | 1.64041666667 | 13217 |
| 014499 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593985.8 | 511401.1 | 40369 | 1.64041666667 | 14499 |
| 013968 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593987.7 | 511399.9 | 40371 | 1.64041666667 | 13968 |
| 013467 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593989.0 | 511397.9 | 40373 | 1.64041666667 | 13467 |
| 013710 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:42pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593990.5 | 511396.0 | 40375 | 1.64041666667 | 13710 |
| 013682 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593992.4 | 511394.5 | 40377 | 1.64041666667 | 13682 |
| 014318 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593992.7 | 511392.5 | 40378 | 1.64041666667 | 14318 |
| 014721 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593994.1 | 511390.1 | 40381 | 1.64041666667 | 14721 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593994.6 | 511387.8 | 40383 | 1.64041666667 | 14266 |
| 013492 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593995.0 | 511385.2 | 40385 | 1.64041666667 | 13492 |
| 013964 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593996.3 | 511383.0 | 40387 | 1.64041666667 | 13964 |
| 014410 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593996.7 | 511380.4 | 40389 | 1.64041666667 | 14410 |
| 013820 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593997.2 | 511378.5 | 40391 | 1.64041666667 | 13820 |
| 013691 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593997.2 | 511376.1 | 40393 | 1.64041666667 | 13691 |
| 013394 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593995.4 | 511375.3 | 40395 | 1.64041666667 | 13394 |
| 014734 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593993.3 | 511373.9 | 40397 | 1.64041666667 | 14734 |
| 014392 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593991.7 | 511373.7 | 40398 | 1.64041666667 | 14392 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593989.8 | 511372.9 | 40401 | 1.64041666667 | 14246 |
| 013848 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593989.3 | 511371.3 | 40403 | 1.64041666667 | 13848 |
| 014337 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593989.0 | 511369.3 | 40405 | 1.64041666667 | 14337 |
| 014312 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593989.8 | 511367.2 | 40407 | 1.64041666667 | 14312 |
| 015115 | 0 | GeoXH 6000 | 08/18/2015 | 01:57:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593990.1 | 511364.8 | 40409 | 1.64041666667 | 15115 |
| 015177 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593989.8 | 511363.0 | 40411 | 1.64041666667 | 15177 |
| 014979 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593990.2 | 511360.6 | 40413 | 1.64041666667 | 14979 |
| 015573 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593988.5 | 511359.3 | 40415 | 1.64041666667 | 15573 |
| 014992 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593986.5 | 511358.2 | 40417 | 1.64041666667 | 14992 |
| 014381 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593984.8 | 511357.4 | 40419 | 1.64041666667 | 14381 |
| 014561 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593982.6 | 511358.0 | 40421 | 1.64041666667 | 14561 |
| 014521 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:06pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593980.5 | 511357.6 | 40423 | 1.64041666667 | 14521 |
| 014423 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593978.5 | 511358.2 | 40425 | 1.64041666667 | 14423 |
| 014383 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593976.8 | 511358.4 | 40427 | 1.64041666667 | 14383 |
| 014810 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593974.6 | 511357.7 | 40429 | 1.64041666667 | 14810 |
| 014720 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:10pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593972.8 | 511357.4 | 40431 | 1.64041666667 | 14720 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015480 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593971.5 | 511356.3 | 40433 | 1.64041666667 | 15480 |
| 014730 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593970.1 | 511355.1 | 40435 | 1.64041666667 | 14730 |
| 014338 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593969.5 | 511353.5 | 40437 | 1.64041666667 | 14338 |
| 013765 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593968.4 | 511352.6 | 40438 | 1.64041666667 | 13765 |
| 013975 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593967.1 | 511350.7 | 40441 | 1.64041666667 | 13975 |
| 014926 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593965.8 | 511349.1 | 40443 | 1.64041666667 | 14926 |
| 014261 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593963.9 | 511347.9 | 40445 | 1.64041666667 | 14261 |
| 015071 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593963.1 | 511346.2 | 40447 | 1.64041666667 | 15071 |
| 014335 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593961.2 | 511344.9 | 40449 | 1.64041666667 | 14335 |
| 014273 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593959.5 | 511344.6 | 40451 | 1.64041666667 | 14273 |
| 014981 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593957.4 | 511345.1 | 40453 | 1.64041666667 | 14981 |
| 015379 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593956.6 | 511346.9 | 40455 | 1.64041666667 | 15379 |
| 014636 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593955.9 | 511349.5 | 40457 | 1.64041666667 | 14636 |
| 014285 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593955.8 | 511351.5 | 40459 | 1.64041666667 | 14285 |
| 015138 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593956.2 | 511353.8 | 40461 | 1.64041666667 | 15138 |
| 014582 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593956.4 | 511355.7 | 40462 | 1.64041666667 | 14582 |
| 014817 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593956.6 | 511358.5 | 40465 | 1.64041666667 | 14817 |
| 015445 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593956.5 | 511360.9 | 40467 | 1.64041666667 | 15445 |
| 016015 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593955.7 | 511363.4 | 40469 | 1.64041666667 | 16015 |
| 015023 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.5 | 511365.1 | 40470 | 1.64041666667 | 15023 |
| 015410 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593953.7 | 511368.0 | 40473 | 1.64041666667 | 15410 |
| 015306 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593953.3 | 511370.3 | 40475 | 1.64041666667 | 15306 |
| 015802 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593952.4 | 511372.5 | 40477 | 1.64041666667 | 15802 |
| 015346 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593952.4 | 511374.1 | 40478 | 1.64041666667 | 15346 |
| 014317 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593952.3 | 511376.4 | 40481 | 1.64041666667 | 14317 |
| 014901 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593951.9 | 511378.1 | 40482 | 1.64041666667 | 14901 |
| 014329 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593952.6 | 511380.0 | 40485 | 1.64041666667 | 14329 |
| 014405 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593952.9 | 511381.8 | 40486 | 1.64041666667 | 14405 |
| 014838 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.8 | 511383.6 | 40489 | 1.64041666667 | 14838 |
| 015771 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593956.2 | 511384.8 | 40491 | 1.64041666667 | 15771 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593957.1 | 511386.6 | 40493 | 1.64041666667 | 14526 |
| 014718 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593958.0 | 511387.8 | 40494 | 1.64041666667 | 14718 |
| 014744 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593957.8 | 511389.6 | 40497 | 1.64041666667 | 14744 |
| 014488 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593957.0 | 511390.6 | 40499 | 1.64041666667 | 14488 |
| 014667 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593955.9 | 511391.5 | 40501 | 1.64041666667 | 14667 |
| 014850 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:46pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593955.2 | 511392.1 | 40503 | 1.64041666667 | 14850 |
| 016550 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593955.5 | 511392.5 | 40505 | 1.64041666667 | 16550 |
| 015752 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593955.1 | 511392.8 | 40506 | 1.64041666667 | 15752 |
| 014568 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.8 | 40509 | 1.64041666667 | 14568 |
| 013489 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593955.0 | 511392.9 | 40511 | 1.64041666667 | 13489 |
| 014015 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.9 | 40513 | 1.64041666667 | 14015 |
| 014056 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.8 | 40515 | 1.64041666667 | 14056 |
| 014994 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.8 | 40517 | 1.64041666667 | 14994 |
| 014884 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:54pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.9 | 40519 | 1.64041666667 | 14884 |
| 015122 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.9 | 40520 | 1.64041666667 | 15122 |
| 014873 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:56pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.8 | 40521 | 1.64041666667 | 14873 |
| 016061 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.8 | 40522 | 1.64041666667 | 16061 |
| 015904 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.8 | 40523 | 1.64041666667 | 15904 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015479 | 0 | GeoXH 6000 | 08/18/2015 | 01:58:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.8 | 40524 | 1.64041666667 | 15479 |
| 015509 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.8 | 511392.8 | 40525 | 1.64041666667 | 15509 |
| 015474 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.8 | 511392.8 | 40526 | 1.64041666667 | 15474 |
| 015371 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.8 | 511392.8 | 40527 | 1.64041666667 | 15371 |
| 014984 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.8 | 40528 | 1.64041666667 | 14984 |
| 014938 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.8 | 40529 | 1.64041666667 | 14938 |
| 014973 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.9 | 511392.9 | 40530 | 1.64041666667 | 14973 |
| 015014 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.8 | 511393.0 | 40531 | 1.64041666667 | 15014 |
| 014610 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.8 | 511392.9 | 40532 | 1.64041666667 | 14610 |
| 014496 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.9 | 40533 | 1.64041666667 | 14496 |
| 014191 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.9 | 40534 | 1.64041666667 | 14191 |
| 014792 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.9 | 40535 | 1.64041666667 | 14792 |
| 015078 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.8 | 511392.9 | 40536 | 1.64041666667 | 15078 |
| 014541 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:12pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.9 | 40537 | 1.64041666667 | 14541 |
| 014937 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.9 | 40538 | 1.64041666667 | 14937 |
| 014672 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.9 | 40539 | 1.64041666667 | 14672 |
| 014605 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593954.8 | 511392.9 | 40540 | 1.64041666667 | 14605 |
| 014148 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593954.8 | 511393.0 | 40541 | 1.64041666667 | 14148 |
| 014775 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.8 | 511392.9 | 40542 | 1.64041666667 | 14775 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593954.8 | 511392.9 | 40543 | 1.64041666667 | 14266 |
| 014512 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.8 | 40544 | 1.64041666667 | 14512 |
| 014268 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.8 | 511392.8 | 40545 | 1.64041666667 | 14268 |
| 014573 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.8 | 511392.8 | 40546 | 1.64041666667 | 14573 |
| 014280 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.9 | 40547 | 1.64041666667 | 14280 |
| 014392 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.9 | 40549 | 1.64041666667 | 14392 |
| 014365 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.9 | 40551 | 1.64041666667 | 14365 |
| 014688 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.8 | 40553 | 1.64041666667 | 14688 |
| 014142 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.8 | 40554 | 1.64041666667 | 14142 |
| 014847 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.8 | 40557 | 1.64041666667 | 14847 |
| 015971 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.9 | 40558 | 1.64041666667 | 15971 |
| 014571 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.6 | 511392.9 | 40561 | 1.64041666667 | 14571 |
| 013979 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.8 | 40563 | 1.64041666667 | 13979 |
| 014830 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.7 | 511392.8 | 40565 | 1.64041666667 | 14830 |
| 014957 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593954.7 | 511392.8 | 40566 | 1.64041666667 | 14957 |
| 014736 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.9 | 511392.9 | 40569 | 1.64041666667 | 14736 |
| 014851 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:34pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593956.2 | 511393.6 | 40571 | 1.64041666667 | 14851 |
| 014489 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593956.6 | 511393.6 | 40573 | 1.64041666667 | 14489 |
| 014960 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593955.7 | 511393.3 | 40574 | 1.64041666667 | 14960 |
| 015037 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593955.1 | 511393.0 | 40577 | 1.64041666667 | 15037 |
| 014443 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593955.7 | 511392.4 | 40579 | 1.64041666667 | 14443 |
| 014394 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593956.7 | 511393.4 | 40581 | 1.64041666667 | 14394 |
| 014592 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593956.8 | 511393.3 | 40583 | 1.64041666667 | 14592 |
| 014163 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593957.4 | 511391.9 | 40585 | 1.64041666667 | 14163 |
| 014371 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593958.0 | 511390.8 | 40586 | 1.64041666667 | 14371 |
| 014151 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593957.1 | 511389.4 | 40589 | 1.64041666667 | 14151 |
| 014290 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593956.0 | 511389.4 | 40590 | 1.64041666667 | 14290 |
| 015035 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593953.4 | 511390.5 | 40593 | 1.64041666667 | 15035 |
| 015042 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593952.9 | 511391.6 | 40594 | 1.64041666667 | 15042 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015256 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593950.9 | 511392.7 | 40597 | 1.64041666667 | 15256 |
| 014821 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:48pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593949.2 | 511393.5 | 40599 | 1.64041666667 | 14821 |
| 014539 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593947.3 | 511394.8 | 40601 | 1.64041666667 | 14539 |
| 014328 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593945.5 | 511394.9 | 40602 | 1.64041666667 | 14328 |
| 013977 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593943.9 | 511396.2 | 40605 | 1.64041666667 | 13977 |
| 013434 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593942.9 | 511397.3 | 40606 | 1.64041666667 | 13434 |
| 013812 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593942.1 | 511399.4 | 40609 | 1.64041666667 | 13812 |
| 014061 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593942.3 | 511400.9 | 40610 | 1.64041666667 | 14061 |
| 014307 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593942.3 | 511403.2 | 40613 | 1.64041666667 | 14307 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593942.0 | 511404.8 | 40614 | 1.64041666667 | 14092 |
| 014647 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593942.8 | 511407.2 | 40617 | 1.64041666667 | 14647 |
| 014404 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:58pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593942.2 | 511409.6 | 40619 | 1.64041666667 | 14404 |
| 014282 | 0 | GeoXH 6000 | 08/18/2015 | 01:59:59pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593942.2 | 511411.8 | 40621 | 1.64041666667 | 14282 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:00pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593942.3 | 511414.3 | 40623 | 1.64041666667 | 13861 |
| 014014 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593942.2 | 511416.3 | 40625 | 1.64041666667 | 14014 |
| 014528 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:02pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593942.5 | 511418.0 | 40627 | 1.64041666667 | 14528 |
| 015109 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:03pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593941.1 | 511419.0 | 40629 | 1.64041666667 | 15109 |
| 014154 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593939.3 | 511418.9 | 40631 | 1.64041666667 | 14154 |
| 014651 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593937.8 | 511417.8 | 40633 | 1.64041666667 | 14651 |
| 014916 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593937.9 | 511416.5 | 40634 | 1.64041666667 | 14916 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593937.1 | 511414.0 | 40637 | 1.64041666667 | 13738 |
| 013945 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:08pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593936.6 | 511412.3 | 40639 | 1.64041666667 | 13945 |
| 013784 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593935.4 | 511410.0 | 40641 | 1.64041666667 | 13784 |
| 015321 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593934.1 | 511408.6 | 40642 | 1.64041666667 | 15321 |
| 014318 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593934.0 | 511406.0 | 40645 | 1.64041666667 | 14318 |
| 013559 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593932.9 | 511404.4 | 40646 | 1.64041666667 | 13559 |
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593932.6 | 511402.0 | 40649 | 1.64041666667 | 14227 |
| 014160 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:14pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593932.9 | 511399.4 | 40651 | 1.64041666667 | 14160 |
| 015150 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593932.8 | 511396.9 | 40653 | 1.64041666667 | 15150 |
| 014837 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593933.6 | 511395.1 | 40654 | 1.64041666667 | 14837 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593933.9 | 511393.4 | 40657 | 1.64041666667 | 14458 |
| 013885 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:18pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593935.4 | 511393.0 | 40659 | 1.64041666667 | 13885 |
| 013690 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:19pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593937.9 | 511393.8 | 40661 | 1.64041666667 | 13690 |
| 013048 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:20pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593940.4 | 511394.1 | 40663 | 1.64041666667 | 13048 |
| 013437 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593942.9 | 511394.3 | 40665 | 1.64041666667 | 13437 |
| 013221 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:21pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593944.9 | 511395.2 | 40666 | 1.64041666667 | 13221 |
| 013661 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:23pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593947.7 | 511394.9 | 40669 | 1.64041666667 | 13661 |
| 014367 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593949.7 | 511394.4 | 40670 | 1.64041666667 | 14367 |
| 014884 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593952.6 | 511393.9 | 40673 | 1.64041666667 | 14884 |
| 014469 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593954.0 | 511393.3 | 40674 | 1.64041666667 | 14469 |
| 015601 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.5 | 511392.6 | 40677 | 1.64041666667 | 15601 |
| 015518 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:28pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.4 | 511392.4 | 40679 | 1.64041666667 | 15518 |
| 014669 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.3 | 511392.4 | 40681 | 1.64041666667 | 14669 |
| 014273 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:30pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593954.4 | 511392.4 | 40683 | 1.64041666667 | 14273 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593954.2 | 511392.1 | 40685 | 1.64041666667 | 14201 |
| 014475 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:32pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593954.1 | 511392.1 | 40687 | 1.64041666667 | 14475 |
| 014697 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593954.2 | 511392.2 | 40689 | 1.64041666667 | 14697 |
| 014027 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:34pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593955.8 | 511392.7 | 40691 | 1.64041666667 | 14027 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014018 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:35pm | Sensor | 1797-S0033-905-G-ACK | 6814.1 | 1593956.2 | 511392.6 | 40693 | 1.64041666667 | 14018 |
| 014590 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:35pm | Sensor | 1797-S0033-905-G-ACK | 6813.9 | 1593956.5 | 511392.5 | 40694 | 1.64041666667 | 14590 |
| 014874 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:37pm | Sensor | 1797-S0033-905-G-ACK | 6811.0 | 1593957.1 | 511392.4 | 40697 | 1.64041666667 | 14874 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:38pm | Sensor | 1797-S0033-905-G-ACK | 6810.6 | 1593957.1 | 511392.4 | 40699 | 1.64041666667 | 14456 |
| 014994 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:39pm | Sensor | 1797-S0033-905-G-ACK | 6810.7 | 1593957.1 | 511392.3 | 40701 | 1.64041666667 | 14994 |
| 014884 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:40pm | Sensor | 1797-S0033-905-G-ACK | 6811.0 | 1593957.0 | 511392.4 | 40703 | 1.64041666667 | 14884 |
| 014357 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:40pm | Sensor | 1797-S0033-905-G-ACK | 6812.4 | 1593956.2 | 511392.5 | 40704 | 1.64041666667 | 14357 |
| 014713 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:41pm | Sensor | 1797-S0033-905-G-ACK | 6812.7 | 1593956.1 | 511391.8 | 40706 | 1.64041666667 | 14713 |
| 014546 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:43pm | Sensor | 1797-S0033-905-G-ACK | 6812.9 | 1593956.6 | 511390.7 | 40709 | 1.64041666667 | 14546 |
| 013702 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:43pm | Sensor | 1797-S0033-905-G-ACK | 6812.9 | 1593957.3 | 511389.7 | 40710 | 1.64041666667 | 13702 |
| 014352 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:45pm | Sensor | 1797-S0033-905-G-ACK | 6813.2 | 1593956.5 | 511387.7 | 40713 | 1.64041666667 | 14352 |
| 014996 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593955.3 | 511385.5 | 40714 | 1.64041666667 | 14996 |
| 014862 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593953.1 | 511383.5 | 40717 | 1.64041666667 | 14862 |
| 014660 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593951.2 | 511382.8 | 40718 | 1.64041666667 | 14660 |
| 013713 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593948.1 | 511381.9 | 40721 | 1.64041666667 | 13713 |
| 013264 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593945.1 | 511381.1 | 40723 | 1.64041666667 | 13264 |
| 014038 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593941.8 | 511380.9 | 40725 | 1.64041666667 | 14038 |
| 014166 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:52pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593939.5 | 511380.4 | 40727 | 1.64041666667 | 14166 |
| 014651 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593937.3 | 511378.7 | 40729 | 1.64041666667 | 14651 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:54pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593935.4 | 511377.7 | 40731 | 1.64041666667 | 14158 |
| 014242 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593933.0 | 511376.9 | 40733 | 1.64041666667 | 14242 |
| 014101 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593931.4 | 511375.9 | 40734 | 1.64041666667 | 14101 |
| 013819 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593929.3 | 511375.2 | 40737 | 1.64041666667 | 13819 |
| 014733 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:58pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593928.2 | 511374.0 | 40739 | 1.64041666667 | 14733 |
| 014340 | 0 | GeoXH 6000 | 08/18/2015 | 02:00:59pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593928.8 | 511371.8 | 40741 | 1.64041666667 | 14340 |
| 014546 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:00pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593929.7 | 511370.3 | 40743 | 1.64041666667 | 14546 |
| 014542 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:01pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593930.8 | 511368.1 | 40745 | 1.64041666667 | 14542 |
| 013587 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:01pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593932.4 | 511366.7 | 40746 | 1.64041666667 | 13587 |
| 014535 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:03pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593933.4 | 511364.1 | 40749 | 1.64041666667 | 14535 |
| 015038 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:03pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593934.6 | 511362.2 | 40750 | 1.64041666667 | 15038 |
| 014759 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593936.0 | 511359.4 | 40753 | 1.64041666667 | 14759 |
| 014414 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:06pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593935.9 | 511357.3 | 40755 | 1.64041666667 | 14414 |
| 013508 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593936.2 | 511354.9 | 40757 | 1.64041666667 | 13508 |
| 013748 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593937.4 | 511353.2 | 40758 | 1.64041666667 | 13748 |
| 013246 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593937.8 | 511350.6 | 40761 | 1.64041666667 | 13246 |
| 013901 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:10pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593938.9 | 511349.0 | 40763 | 1.64041666667 | 13901 |
| 013931 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593939.1 | 511347.0 | 40765 | 1.64041666667 | 13931 |
| 014594 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:11pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593940.3 | 511345.3 | 40766 | 1.64041666667 | 14594 |
| 015086 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593942.3 | 511342.8 | 40769 | 1.64041666667 | 15086 |
| 014681 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593943.0 | 511341.1 | 40770 | 1.64041666667 | 14681 |
| 014145 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593945.3 | 511339.6 | 40773 | 1.64041666667 | 14145 |
| 014527 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593947.0 | 511338.6 | 40774 | 1.64041666667 | 14527 |
| 014276 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:17pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593949.7 | 511338.4 | 40777 | 1.64041666667 | 14276 |
| 014728 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:18pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593951.6 | 511338.5 | 40779 | 1.64041666667 | 14728 |
| 014554 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593953.9 | 511338.1 | 40781 | 1.64041666667 | 14554 |
| 013849 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593955.6 | 511339.1 | 40782 | 1.64041666667 | 13849 |
| 013827 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593958.0 | 511339.4 | 40785 | 1.64041666667 | 13827 |
| 013943 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593960.4 | 511340.0 | 40787 | 1.64041666667 | 13943 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013475 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593962.8 | 511340.8 | 40789 | 1.64041666667 | 13475 |
| 014907 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593964.9 | 511340.8 | 40790 | 1.64041666667 | 14907 |
| 015037 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593967.5 | 511342.0 | 40793 | 1.64041666667 | 15037 |
| 014398 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:26pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593969.3 | 511342.8 | 40795 | 1.64041666667 | 14398 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593970.7 | 511344.1 | 40797 | 1.64041666667 | 14609 |
| 014607 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593970.7 | 511346.3 | 40798 | 1.64041666667 | 14607 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593972.2 | 511348.1 | 40801 | 1.64041666667 | 14426 |
| 013710 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593972.9 | 511349.8 | 40802 | 1.64041666667 | 13710 |
| 014859 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593975.2 | 511351.5 | 40805 | 1.64041666667 | 14859 |
| 014223 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593976.8 | 511352.5 | 40806 | 1.64041666667 | 14223 |
| 014105 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593979.1 | 511354.0 | 40809 | 1.64041666667 | 14105 |
| 014519 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593980.9 | 511354.1 | 40810 | 1.64041666667 | 14519 |
| 014849 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593983.4 | 511355.3 | 40813 | 1.64041666667 | 14849 |
| 014420 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593985.3 | 511355.4 | 40814 | 1.64041666667 | 14420 |
| 014313 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593988.3 | 511354.9 | 40817 | 1.64041666667 | 14313 |
| 014239 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593990.6 | 511355.5 | 40818 | 1.64041666667 | 14239 |
| 014384 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593993.1 | 511354.5 | 40820 | 1.64041666667 | 14384 |
| 013693 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593995.7 | 511354.5 | 40822 | 1.64041666667 | 13693 |
| 014257 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:41pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593999.1 | 511354.5 | 40825 | 1.64041666667 | 14257 |
| 014395 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:41pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594000.8 | 511354.3 | 40826 | 1.64041666667 | 14395 |
| 014239 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:43pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1594003.3 | 511355.0 | 40829 | 1.64041666667 | 14239 |
| 015285 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:43pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594005.1 | 511355.0 | 40830 | 1.64041666667 | 15285 |
| 013975 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:44pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594007.3 | 511354.6 | 40832 | 1.64041666667 | 13975 |
| 014528 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:45pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594008.6 | 511355.8 | 40834 | 1.64041666667 | 14528 |
| 014667 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:47pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594010.3 | 511358.0 | 40837 | 1.64041666667 | 14667 |
| 014197 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:47pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594011.7 | 511359.6 | 40838 | 1.64041666667 | 14197 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:48pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594012.3 | 511362.1 | 40840 | 1.64041666667 | 14526 |
| 014711 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:49pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594013.2 | 511364.1 | 40842 | 1.64041666667 | 14711 |
| 014537 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:51pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594013.8 | 511367.1 | 40845 | 1.64041666667 | 14537 |
| 014432 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:51pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594012.7 | 511369.0 | 40846 | 1.64041666667 | 14432 |
| 015670 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:53pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594012.1 | 511371.8 | 40849 | 1.64041666667 | 15670 |
| 015624 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:53pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594011.4 | 511373.7 | 40850 | 1.64041666667 | 15624 |
| 014511 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:55pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594010.0 | 511376.3 | 40853 | 1.64041666667 | 14511 |
| 014432 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:55pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594009.8 | 511378.3 | 40854 | 1.64041666667 | 14432 |
| 014396 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:57pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594008.3 | 511380.8 | 40857 | 1.64041666667 | 14396 |
| 014015 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:57pm | Sensor | 1797-S0033-905-G-ACK | 6816.5 | 1594007.3 | 511382.9 | 40858 | 1.64041666667 | 14015 |
| 013801 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:59pm | Sensor | 1797-S0033-905-G-ACK | 6816.7 | 1594006.5 | 511385.3 | 40861 | 1.64041666667 | 13801 |
| 013793 | 0 | GeoXH 6000 | 08/18/2015 | 02:01:59pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594005.0 | 511387.0 | 40862 | 1.64041666667 | 13793 |
| 014883 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:01pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594003.6 | 511389.8 | 40865 | 1.64041666667 | 14883 |
| 014649 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:02pm | Sensor | 1797-S0033-905-G-ACK | 6816.7 | 1594003.1 | 511392.1 | 40867 | 1.64041666667 | 14649 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:03pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1594001.1 | 511394.6 | 40869 | 1.64041666667 | 14158 |
| 014233 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:03pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1594000.2 | 511396.6 | 40870 | 1.64041666667 | 14233 |
| 013729 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:05pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593999.6 | 511399.6 | 40873 | 1.64041666667 | 13729 |
| 014075 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:05pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593999.0 | 511401.3 | 40874 | 1.64041666667 | 14075 |
| 013632 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:07pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593998.8 | 511404.4 | 40877 | 1.64041666667 | 13632 |
| 014125 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:07pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593998.6 | 511406.6 | 40878 | 1.64041666667 | 14125 |
| 013803 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:09pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593997.2 | 511409.2 | 40881 | 1.64041666667 | 13803 |
| 013419 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:09pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593996.5 | 511411.2 | 40882 | 1.64041666667 | 13419 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013510 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:11pm | Sensor | 1797-S0033-905-G-ACK | 6816.4 | 1593995.9 | 511414.0 | 40885 | 1.64041666667 | 13510 |
| 013802 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:11pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593994.3 | 511415.5 | 40886 | 1.64041666667 | 13802 |
| 013681 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:13pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593992.9 | 511417.4 | 40889 | 1.64041666667 | 13681 |
| 013275 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:14pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593991.1 | 511418.3 | 40891 | 1.64041666667 | 13275 |
| 013850 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:15pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593988.6 | 511417.6 | 40893 | 1.64041666667 | 13850 |
| 014053 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:15pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593986.8 | 511417.6 | 40894 | 1.64041666667 | 14053 |
| 014175 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:17pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593984.8 | 511416.0 | 40897 | 1.64041666667 | 14175 |
| 014318 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:17pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593983.8 | 511414.2 | 40898 | 1.64041666667 | 14318 |
| 014279 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:19pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593981.5 | 511412.0 | 40901 | 1.64041666667 | 14279 |
| 014099 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593979.9 | 511410.6 | 40903 | 1.64041666667 | 14099 |
| 014576 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:21pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593977.5 | 511408.9 | 40905 | 1.64041666667 | 14576 |
| 014814 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:21pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593975.6 | 511407.9 | 40906 | 1.64041666667 | 14814 |
| 014737 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:22pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593973.5 | 511406.2 | 40908 | 1.64041666667 | 14737 |
| 014110 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593972.6 | 511403.7 | 40910 | 1.64041666667 | 14110 |
| 013562 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593971.8 | 511401.1 | 40912 | 1.64041666667 | 13562 |
| 014221 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593971.5 | 511398.8 | 40914 | 1.64041666667 | 14221 |
| 014179 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:27pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593971.7 | 511395.7 | 40917 | 1.64041666667 | 14179 |
| 013383 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593970.9 | 511393.6 | 40918 | 1.64041666667 | 13383 |
| 013085 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:29pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593969.2 | 511390.7 | 40921 | 1.64041666667 | 13085 |
| 013428 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593968.2 | 511388.4 | 40922 | 1.64041666667 | 13428 |
| 013433 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:30pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593967.3 | 511385.8 | 40924 | 1.64041666667 | 13433 |
| 014208 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593966.3 | 511383.4 | 40926 | 1.64041666667 | 14208 |
| 014502 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:33pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593965.3 | 511380.5 | 40929 | 1.64041666667 | 14502 |
| 014180 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:33pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593965.6 | 511378.4 | 40930 | 1.64041666667 | 14180 |
| 014973 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:35pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593965.1 | 511375.3 | 40933 | 1.64041666667 | 14973 |
| 015382 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:36pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593964.8 | 511373.0 | 40935 | 1.64041666667 | 15382 |
| 015260 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:37pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593964.7 | 511369.8 | 40937 | 1.64041666667 | 15260 |
| 014846 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:37pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593964.3 | 511367.6 | 40938 | 1.64041666667 | 14846 |
| 014598 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:39pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593962.9 | 511365.0 | 40941 | 1.64041666667 | 14598 |
| 014204 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:40pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593961.6 | 511362.5 | 40943 | 1.64041666667 | 14204 |
| 014125 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:40pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593960.3 | 511359.9 | 40944 | 1.64041666667 | 14125 |
| 013945 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:41pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593958.5 | 511357.7 | 40946 | 1.64041666667 | 13945 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593956.2 | 511355.3 | 40949 | 1.64041666667 | 14609 |
| 015582 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593954.5 | 511353.4 | 40950 | 1.64041666667 | 15582 |
| 015072 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:44pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593952.2 | 511351.0 | 40952 | 1.64041666667 | 15072 |
| 014276 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593949.9 | 511349.0 | 40954 | 1.64041666667 | 14276 |
| 014247 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593947.0 | 511346.6 | 40957 | 1.64041666667 | 14247 |
| 014614 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:47pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593944.9 | 511345.0 | 40958 | 1.64041666667 | 14614 |
| 014153 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593941.8 | 511343.0 | 40961 | 1.64041666667 | 14153 |
| 015078 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:49pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593939.3 | 511341.5 | 40962 | 1.64041666667 | 15078 |
| 014481 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:50pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593936.9 | 511339.9 | 40964 | 1.64041666667 | 14481 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:51pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593934.7 | 511338.3 | 40966 | 1.64041666667 | 14078 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593932.3 | 511335.9 | 40969 | 1.64041666667 | 14324 |
| 014342 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:53pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593930.9 | 511334.0 | 40970 | 1.64041666667 | 14342 |
| 014382 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593928.7 | 511331.2 | 40973 | 1.64041666667 | 14382 |
| 014045 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:55pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593927.0 | 511329.7 | 40974 | 1.64041666667 | 14045 |
| 014575 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:57pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593924.8 | 511327.8 | 40977 | 1.64041666667 | 14575 |
| 014806 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:57pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593923.0 | 511325.5 | 40978 | 1.64041666667 | 14806 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014921 | 0 | GeoXH 6000 | 08/18/2015 | 02:02:59pm | Sensor | 1797-S0033-905-G-ACK | 6816.1 | 1593921.1 | 511323.0 | 40981 | 1.64041666667 | 14921 |
| 014190 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:00pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593919.4 | 511320.5 | 40983 | 1.64041666667 | 14190 |
| 013307 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:01pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593917.1 | 511317.7 | 40985 | 1.64041666667 | 13307 |
| 013860 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:01pm | Sensor | 1797-S0033-905-G-ACK | 6816.3 | 1593915.3 | 511315.5 | 40986 | 1.64041666667 | 13860 |
| 014193 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:03pm | Sensor | 1797-S0033-905-G-ACK | 6816.2 | 1593912.6 | 511313.0 | 40989 | 1.64041666667 | 14193 |
| 014801 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:03pm | Sensor | 1797-S0033-905-G-ACK | 6816.0 | 1593910.3 | 511311.7 | 40990 | 1.64041666667 | 14801 |
| 014513 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:04pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593907.2 | 511309.8 | 40992 | 1.64041666667 | 14513 |
| 014291 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:05pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593904.7 | 511308.5 | 40994 | 1.64041666667 | 14291 |
| 015306 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.9 | 1593901.2 | 511306.6 | 40997 | 1.64041666667 | 15306 |
| 014659 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:07pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593899.2 | 511305.3 | 40998 | 1.64041666667 | 14659 |
| 014745 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:08pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593896.4 | 511303.2 | 41000 | 1.64041666667 | 14745 |
| 014497 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:09pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593893.9 | 511301.5 | 41002 | 1.64041666667 | 14497 |
| 014664 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593890.2 | 511299.5 | 41005 | 1.64041666667 | 14664 |
| 014129 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:11pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593888.3 | 511298.0 | 41006 | 1.64041666667 | 14129 |
| 013535 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593886.0 | 511295.5 | 41009 | 1.64041666667 | 13535 |
| 013253 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:13pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593884.2 | 511293.0 | 41010 | 1.64041666667 | 13253 |
| 013447 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:15pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593881.4 | 511289.9 | 41013 | 1.64041666667 | 13447 |
| 014284 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:16pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593879.2 | 511287.7 | 41015 | 1.64041666667 | 14284 |
| 013802 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593877.2 | 511285.2 | 41017 | 1.64041666667 | 13802 |
| 013403 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:17pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593875.8 | 511282.7 | 41018 | 1.64041666667 | 13403 |
| 013764 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:19pm | Sensor | 1797-S0033-905-G-ACK | 6815.8 | 1593874.6 | 511279.8 | 41021 | 1.64041666667 | 13764 |
| 013712 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593873.0 | 511277.1 | 41023 | 1.64041666667 | 13712 |
| 013488 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:20pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593871.1 | 511274.5 | 41024 | 1.64041666667 | 13488 |
| 013557 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:21pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593868.9 | 511272.3 | 41026 | 1.64041666667 | 13557 |
| 012523 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.6 | 1593866.0 | 511270.1 | 41029 | 1.64041666667 | 12523 |
| 013314 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:23pm | Sensor | 1797-S0033-905-G-ACK | 6815.7 | 1593863.9 | 511268.8 | 41030 | 1.64041666667 | 13314 |
| 012229 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:24pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593861.0 | 511267.0 | 41032 | 1.64041666667 | 12229 |
| 012264 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:25pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593858.6 | 511264.8 | 41034 | 1.64041666667 | 12264 |
| 011571 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593856.2 | 511262.1 | 41037 | 1.64041666667 | 11571 |
| 011856 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:27pm | Sensor | 1797-S0033-905-G-ACK | 6815.5 | 1593854.9 | 511260.3 | 41038 | 1.64041666667 | 11856 |
| 011244 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593852.8 | 511257.2 | 41041 | 1.64041666667 | 11244 |
| 011237 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:29pm | Sensor | 1797-S0033-905-G-ACK | 6815.4 | 1593851.1 | 511255.1 | 41042 | 1.64041666667 | 11237 |
| 012231 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593848.7 | 511252.3 | 41045 | 1.64041666667 | 12231 |
| 011455 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:31pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593846.8 | 511250.5 | 41046 | 1.64041666667 | 11455 |
| 011910 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:33pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593844.1 | 511247.7 | 41049 | 1.64041666667 | 11910 |
| 012017 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:34pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593841.8 | 511245.4 | 41051 | 1.64041666667 | 12017 |
| 012872 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:35pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593839.0 | 511243.1 | 41053 | 1.64041666667 | 12872 |
| 012340 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:36pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593836.7 | 511241.6 | 41055 | 1.64041666667 | 12340 |
| 012506 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:37pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593833.7 | 511239.7 | 41057 | 1.64041666667 | 12506 |
| 013170 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:38pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593831.4 | 511238.1 | 41059 | 1.64041666667 | 13170 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593828.5 | 511235.8 | 41061 | 1.64041666667 | 12785 |
| 013837 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:39pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593826.5 | 511234.1 | 41062 | 1.64041666667 | 13837 |
| 014000 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593823.5 | 511231.8 | 41065 | 1.64041666667 | 14000 |
| 014205 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:41pm | Sensor | 1797-S0033-905-G-ACK | 6815.2 | 1593821.4 | 511230.2 | 41066 | 1.64041666667 | 14205 |
| 013870 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.3 | 1593818.5 | 511228.0 | 41069 | 1.64041666667 | 13870 |
| 013007 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:43pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593816.7 | 511226.2 | 41070 | 1.64041666667 | 13007 |
| 012919 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.1 | 1593814.2 | 511223.1 | 41073 | 1.64041666667 | 12919 |
| 013177 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:45pm | Sensor | 1797-S0033-905-G-ACK | 6815.0 | 1593812.4 | 511221.1 | 41074 | 1.64041666667 | 13177 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:47pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593809.9 | 511218.9 | 41077 | 1.64041666667 | 13277 |
| 014517 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:48pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593807.5 | 511216.4 | 41079 | 1.64041666667 | 14517 |
| 014183 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:49pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593805.0 | 511213.6 | 41081 | 1.64041666667 | 14183 |
| 014923 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:50pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593803.4 | 511211.5 | 41083 | 1.64041666667 | 14923 |
| 014994 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:51pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593800.9 | 511209.6 | 41085 | 1.64041666667 | 14994 |
| 014359 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:52pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593798.7 | 511207.6 | 41087 | 1.64041666667 | 14359 |
| 014077 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:53pm | Sensor | 1797-S0033-905-G-ACK | 6814.9 | 1593796.1 | 511205.2 | 41089 | 1.64041666667 | 14077 |
| 014571 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:54pm | Sensor | 1797-S0033-905-G-ACK | 6814.7 | 1593793.9 | 511203.1 | 41091 | 1.64041666667 | 14571 |
| 015036 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:55pm | Sensor | 1797-S0033-905-G-ACK | 6814.8 | 1593792.2 | 511200.8 | 41093 | 1.64041666667 | 15036 |
| 015357 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:56pm | Sensor | 1797-S0033-905-G-ACK | 6814.6 | 1593791.7 | 511199.2 | 41095 | 1.64041666667 | 15357 |
| 012471 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:57pm | Sensor | 1797-S0033-905-G-ACK | 6814.3 | 1593790.5 | 511197.9 | 41097 | 1.64041666667 | 12471 |
| 010705 | 0 | GeoXH 6000 | 08/18/2015 | 02:03:57pm | Sensor | 1797-S0033-905-G-ACK | 6810.4 | 1593789.6 | 511197.4 | 41098 | 1.64041666667 | 10705 |
| 019284 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:28am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594134.8 | 509561.4 | 35451 | 1.64041666667 | 19284 |
| 018834 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:29am | Sensor | 1797-S0031-636-G-DTE | 6803.8 | 1594134.8 | 509561.5 | 35454 | 1.64041666667 | 18834 |
| 018447 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:30am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594134.7 | 509561.4 | 35456 | 1.64041666667 | 18447 |
| 019046 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:31am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594134.7 | 509561.5 | 35458 | 1.64041666667 | 19046 |
| 020021 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:32am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594134.7 | 509561.6 | 35460 | 1.64041666667 | 20021 |
| 020066 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:33am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.6 | 509561.6 | 35462 | 1.64041666667 | 20066 |
| 019575 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:34am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594134.7 | 509561.6 | 35464 | 1.64041666667 | 19575 |
| 019268 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:35am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.6 | 35466 | 1.64041666667 | 19268 |
| 019448 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:36am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594134.8 | 509561.6 | 35468 | 1.64041666667 | 19448 |
| 019086 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:37am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.8 | 509561.6 | 35470 | 1.64041666667 | 19086 |
| 018450 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:38am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594134.9 | 509561.8 | 35472 | 1.64041666667 | 18450 |
| 019146 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:39am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594134.7 | 509561.9 | 35474 | 1.64041666667 | 19146 |
| 020497 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:40am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594134.8 | 509561.8 | 35476 | 1.64041666667 | 20497 |
| 020064 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:40am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594134.8 | 509561.8 | 35477 | 1.64041666667 | 20064 |
| 020129 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:41am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594134.9 | 509561.8 | 35479 | 1.64041666667 | 20129 |
| 020172 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:42am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594134.9 | 509561.8 | 35481 | 1.64041666667 | 20172 |
| 020189 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:43am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594134.9 | 509561.8 | 35483 | 1.64041666667 | 20189 |
| 019179 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:45am | Sensor | 1797-S0031-636-G-DTE | 6804.1 | 1594134.8 | 509561.8 | 35486 | 1.64041666667 | 19179 |
| 019578 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:46am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594134.8 | 509561.8 | 35488 | 1.64041666667 | 19578 |
| 020117 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:47am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594134.7 | 509561.8 | 35490 | 1.64041666667 | 20117 |
| 019596 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:48am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594134.7 | 509561.8 | 35492 | 1.64041666667 | 19596 |
| 019888 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:49am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35494 | 1.64041666667 | 19888 |
| 019759 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:50am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35496 | 1.64041666667 | 19759 |
| 019109 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:51am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35498 | 1.64041666667 | 19109 |
| 019141 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:52am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35500 | 1.64041666667 | 19141 |
| 019077 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:52am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35501 | 1.64041666667 | 19077 |
| 019063 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:54am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35504 | 1.64041666667 | 19063 |
| 019513 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:55am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35506 | 1.64041666667 | 19513 |
| 018971 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:56am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35508 | 1.64041666667 | 18971 |
| 019033 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:57am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35510 | 1.64041666667 | 19033 |
| 019789 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:58am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.7 | 509561.8 | 35512 | 1.64041666667 | 19789 |
| 018871 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:58am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.6 | 509561.8 | 35513 | 1.64041666667 | 18871 |
| 018392 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:00am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594134.7 | 509561.8 | 35516 | 1.64041666667 | 18392 |
| 019068 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:01am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594134.7 | 509561.7 | 35518 | 1.64041666667 | 19068 |
| 019006 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:02am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.6 | 509561.9 | 35520 | 1.64041666667 | 19006 |
| 018498 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:03am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594134.7 | 509561.8 | 35522 | 1.64041666667 | 18498 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 018550 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:04am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1594135.7 | 509560.6 | 35524 | 1.64041666667 | 18550 |
| 018519 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:05am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594134.9 | 509560.4 | 35526 | 1.64041666667 | 18519 |
| 019537 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:06am | Sensor | 1797-S0031-636-G-DTE | 6797.1 | 1594134.4 | 509560.1 | 35528 | 1.64041666667 | 19537 |
| 019959 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:07am | Sensor | 1797-S0031-636-G-DTE | 6797.2 | 1594134.8 | 509559.5 | 35530 | 1.64041666667 | 19959 |
| 020340 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:08am | Sensor | 1797-S0031-636-G-DTE | 6797.0 | 1594134.2 | 509559.7 | 35532 | 1.64041666667 | 20340 |
| 020313 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:09am | Sensor | 1797-S0031-636-G-DTE | 6797.1 | 1594134.1 | 509559.8 | 35534 | 1.64041666667 | 20313 |
| 019743 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:10am | Sensor | 1797-S0031-636-G-DTE | 6800.5 | 1594134.4 | 509559.4 | 35536 | 1.64041666667 | 19743 |
| 020271 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:11am | Sensor | 1797-S0031-636-G-DTE | 6799.7 | 1594134.7 | 509559.4 | 35538 | 1.64041666667 | 20271 |
| 021295 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:12am | Sensor | 1797-S0031-636-G-DTE | 6800.0 | 1594134.6 | 509559.3 | 35540 | 1.64041666667 | 21295 |
| 021248 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:13am | Sensor | 1797-S0031-636-G-DTE | 6799.5 | 1594134.5 | 509559.5 | 35542 | 1.64041666667 | 21248 |
| 021469 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:14am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.7 | 509560.0 | 35544 | 1.64041666667 | 21469 |
| 022171 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:14am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.7 | 509560.1 | 35545 | 1.64041666667 | 22171 |
| 020781 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:16am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.6 | 509560.1 | 35548 | 1.64041666667 | 20781 |
| 020134 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:17am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.5 | 509560.1 | 35550 | 1.64041666667 | 20134 |
| 021008 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:18am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.5 | 509560.1 | 35552 | 1.64041666667 | 21008 |
| 021094 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:18am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.5 | 509560.2 | 35553 | 1.64041666667 | 21094 |
| 020753 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:20am | Sensor | 1797-S0031-636-G-DTE | 6796.5 | 1594133.4 | 509560.2 | 35556 | 1.64041666667 | 20753 |
| 020396 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:20am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.4 | 509560.1 | 35557 | 1.64041666667 | 20396 |
| 021132 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:22am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.4 | 509560.1 | 35560 | 1.64041666667 | 21132 |
| 020752 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:22am | Sensor | 1797-S0031-636-G-DTE | 6796.6 | 1594133.7 | 509559.6 | 35561 | 1.64041666667 | 20752 |
| 020680 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:24am | Sensor | 1797-S0031-636-G-DTE | 6796.8 | 1594133.7 | 509559.7 | 35564 | 1.64041666667 | 20680 |
| 020085 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:25am | Sensor | 1797-S0031-636-G-DTE | 6799.2 | 1594134.3 | 509559.4 | 35566 | 1.64041666667 | 20085 |
| 021415 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:26am | Sensor | 1797-S0031-636-G-DTE | 6799.4 | 1594134.3 | 509559.4 | 35568 | 1.64041666667 | 21415 |
| 021878 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:27am | Sensor | 1797-S0031-636-G-DTE | 6799.5 | 1594134.3 | 509559.4 | 35570 | 1.64041666667 | 21878 |
| 021569 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:28am | Sensor | 1797-S0031-636-G-DTE | 6799.6 | 1594134.3 | 509559.4 | 35572 | 1.64041666667 | 21569 |
| 020360 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:29am | Sensor | 1797-S0031-636-G-DTE | 6799.6 | 1594134.2 | 509559.4 | 35574 | 1.64041666667 | 20360 |
| 021255 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:30am | Sensor | 1797-S0031-636-G-DTE | 6799.3 | 1594134.1 | 509559.4 | 35576 | 1.64041666667 | 21255 |
| 021301 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:31am | Sensor | 1797-S0031-636-G-DTE | 6799.2 | 1594134.0 | 509559.4 | 35578 | 1.64041666667 | 21301 |
| 020576 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:32am | Sensor | 1797-S0031-636-G-DTE | 6798.9 | 1594134.0 | 509559.3 | 35580 | 1.64041666667 | 20576 |
| 021092 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:33am | Sensor | 1797-S0031-636-G-DTE | 6798.4 | 1594133.9 | 509559.2 | 35582 | 1.64041666667 | 21092 |
| 021037 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:34am | Sensor | 1797-S0031-636-G-DTE | 6797.5 | 1594133.8 | 509559.1 | 35584 | 1.64041666667 | 21037 |
| 021020 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:35am | Sensor | 1797-S0031-636-G-DTE | 6797.1 | 1594133.7 | 509559.7 | 35586 | 1.64041666667 | 21020 |
| 021281 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:36am | Sensor | 1797-S0031-636-G-DTE | 6797.1 | 1594133.8 | 509559.7 | 35588 | 1.64041666667 | 21281 |
| 021428 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:37am | Sensor | 1797-S0031-636-G-DTE | 6797.2 | 1594133.8 | 509559.7 | 35590 | 1.64041666667 | 21428 |
| 021638 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:38am | Sensor | 1797-S0031-636-G-DTE | 6797.9 | 1594134.0 | 509559.1 | 35592 | 1.64041666667 | 21638 |
| 021119 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:39am | Sensor | 1797-S0031-636-G-DTE | 6797.2 | 1594133.8 | 509559.7 | 35594 | 1.64041666667 | 21119 |
| 020324 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:40am | Sensor | 1797-S0031-636-G-DTE | 6796.4 | 1594133.8 | 509559.6 | 35596 | 1.64041666667 | 20324 |
| 021242 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:40am | Sensor | 1797-S0031-636-G-DTE | 6791.3 | 1594134.0 | 509559.6 | 35597 | 1.64041666667 | 21242 |
| 020679 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:42am | Sensor | 1797-S0031-636-G-DTE | 6797.9 | 1594133.3 | 509560.2 | 35600 | 1.64041666667 | 20679 |
| 020279 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:43am | Sensor | 1797-S0031-636-G-DTE | 6798.2 | 1594134.7 | 509561.1 | 35602 | 1.64041666667 | 20279 |
| 019364 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:44am | Sensor | 1797-S0031-636-G-DTE | 6798.4 | 1594135.1 | 509561.0 | 35604 | 1.64041666667 | 19364 |
| 018910 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:45am | Sensor | 1797-S0031-636-G-DTE | 6799.2 | 1594134.9 | 509560.9 | 35606 | 1.64041666667 | 18910 |
| 018564 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:46am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594135.3 | 509560.1 | 35608 | 1.64041666667 | 18564 |
| 018535 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:47am | Sensor | 1797-S0031-636-G-DTE | 6803.8 | 1594135.3 | 509560.0 | 35610 | 1.64041666667 | 18535 |
| 018931 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:48am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594135.6 | 509560.2 | 35612 | 1.64041666667 | 18931 |
| 018456 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:49am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594135.9 | 509560.5 | 35614 | 1.64041666667 | 18456 |
| 019329 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:50am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594135.8 | 509560.5 | 35616 | 1.64041666667 | 19329 |
| 019910 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:51am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594135.8 | 509560.6 | 35618 | 1.64041666667 | 19910 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019089 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:52am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1594136.0 | 509561.2 | 35620 | 1.64041666667 | 19089 |
| 019212 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:53am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594135.9 | 509561.1 | 35622 | 1.64041666667 | 19212 |
| 019034 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:54am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594135.9 | 509561.2 | 35624 | 1.64041666667 | 19034 |
| 019542 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:55am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594135.9 | 509561.2 | 35626 | 1.64041666667 | 19542 |
| 020284 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:56am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594135.9 | 509561.1 | 35628 | 1.64041666667 | 20284 |
| 019150 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:57am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594135.9 | 509561.1 | 35630 | 1.64041666667 | 19150 |
| 018579 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:58am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594135.9 | 509561.1 | 35632 | 1.64041666667 | 18579 |
| 018551 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:59am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594135.9 | 509561.1 | 35634 | 1.64041666667 | 18551 |
| 019067 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:00am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594136.0 | 509561.2 | 35636 | 1.64041666667 | 19067 |
| 019095 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:01am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594135.9 | 509561.6 | 35638 | 1.64041666667 | 19095 |
| 019223 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:02am | Sensor | 1797-S0031-636-G-DTE | 6804.6 | 1594134.5 | 509562.6 | 35640 | 1.64041666667 | 19223 |
| 018658 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:02am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594134.3 | 509563.8 | 35641 | 1.64041666667 | 18658 |
| 018948 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:04am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594134.8 | 509563.1 | 35644 | 1.64041666667 | 18948 |
| 019358 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:05am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594136.0 | 509562.1 | 35646 | 1.64041666667 | 19358 |
| 019259 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:06am | Sensor | 1797-S0031-636-G-DTE | 6804.6 | 1594135.9 | 509560.9 | 35648 | 1.64041666667 | 19259 |
| 019353 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:07am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594135.8 | 509561.3 | 35650 | 1.64041666667 | 19353 |
| 019481 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:08am | Sensor | 1797-S0031-636-G-DTE | 6804.6 | 1594136.6 | 509564.0 | 35652 | 1.64041666667 | 19481 |
| 018810 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:09am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594135.8 | 509567.3 | 35654 | 1.64041666667 | 18810 |
| 018426 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:10am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594133.7 | 509570.4 | 35656 | 1.64041666667 | 18426 |
| 018524 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:11am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594131.4 | 509573.9 | 35658 | 1.64041666667 | 18524 |
| 018182 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:12am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594128.7 | 509577.3 | 35660 | 1.64041666667 | 18182 |
| 018432 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:13am | Sensor | 1797-S0031-636-G-DTE | 6804.1 | 1594125.7 | 509580.1 | 35662 | 1.64041666667 | 18432 |
| 017381 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:14am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594122.5 | 509582.3 | 35664 | 1.64041666667 | 17381 |
| 016984 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:15am | Sensor | 1797-S0031-636-G-DTE | 6803.8 | 1594119.3 | 509583.8 | 35666 | 1.64041666667 | 16984 |
| 016708 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:16am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594116.2 | 509585.9 | 35668 | 1.64041666667 | 16708 |
| 016881 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:16am | Sensor | 1797-S0031-636-G-DTE | 6804.1 | 1594114.2 | 509588.0 | 35669 | 1.64041666667 | 16881 |
| 015055 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:18am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594111.2 | 509591.0 | 35672 | 1.64041666667 | 15055 |
| 015008 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:18am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594108.9 | 509593.1 | 35673 | 1.64041666667 | 15008 |
| 015019 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:20am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594105.9 | 509596.3 | 35676 | 1.64041666667 | 15019 |
| 015183 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:21am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594103.8 | 509598.8 | 35678 | 1.64041666667 | 15183 |
| 015298 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:22am | Sensor | 1797-S0031-636-G-DTE | 6803.8 | 1594100.8 | 509601.6 | 35680 | 1.64041666667 | 15298 |
| 015265 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:23am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594099.0 | 509603.9 | 35682 | 1.64041666667 | 15265 |
| 015194 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:24am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594096.5 | 509607.1 | 35684 | 1.64041666667 | 15194 |
| 014546 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:25am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594095.2 | 509609.4 | 35686 | 1.64041666667 | 14546 |
| 014580 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:26am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594093.5 | 509612.4 | 35688 | 1.64041666667 | 14580 |
| 014448 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:26am | Sensor | 1797-S0031-636-G-DTE | 6803.4 | 1594091.2 | 509615.0 | 35689 | 1.64041666667 | 14448 |
| 014105 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:28am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594088.1 | 509618.1 | 35692 | 1.64041666667 | 14105 |
| 014939 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:28am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594086.2 | 509620.0 | 35693 | 1.64041666667 | 14939 |
| 014365 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:30am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594082.2 | 509621.7 | 35696 | 1.64041666667 | 14365 |
| 014328 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:31am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594080.4 | 509622.2 | 35698 | 1.64041666667 | 14328 |
| 014929 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:32am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594080.5 | 509622.7 | 35700 | 1.64041666667 | 14929 |
| 015973 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:32am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594080.5 | 509622.6 | 35701 | 1.64041666667 | 15973 |
| 013971 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:38am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594080.4 | 509622.5 | 35704 | 1.64041666667 | 13971 |
| 014046 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:38am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1594080.4 | 509622.5 | 35705 | 1.64041666667 | 14046 |
| 013818 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:39am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594080.4 | 509622.6 | 35707 | 1.64041666667 | 13818 |
| 013600 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:40am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594080.4 | 509622.5 | 35709 | 1.64041666667 | 13600 |
| 013395 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:42am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594080.3 | 509622.5 | 35712 | 1.64041666667 | 13395 |
| 013842 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:43am | Sensor | 1797-S0031-636-G-DTE | 6803.5 | 1594079.2 | 509622.5 | 35714 | 1.64041666667 | 13842 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013508 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:44am | Sensor | 1797-S0031-636-G-DTE | 6803.4 | 1594076.1 | 509623.9 | 35716 | 1.64041666667 | 13508 |
| 013486 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:44am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594072.8 | 509625.7 | 35717 | 1.64041666667 | 13486 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:46am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594067.9 | 509628.7 | 35720 | 1.64041666667 | 13631 |
| 014012 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:46am | Sensor | 1797-S0031-636-G-DTE | 6803.6 | 1594064.6 | 509630.4 | 35721 | 1.64041666667 | 14012 |
| 014039 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:48am | Sensor | 1797-S0031-636-G-DTE | 6804.1 | 1594060.9 | 509632.6 | 35724 | 1.64041666667 | 14039 |
| 014084 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:48am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594057.5 | 509634.8 | 35725 | 1.64041666667 | 14084 |
| 014350 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:50am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594053.5 | 509638.1 | 35728 | 1.64041666667 | 14350 |
| 013719 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:50am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594050.8 | 509640.5 | 35729 | 1.64041666667 | 13719 |
| 014152 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:52am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594046.5 | 509643.4 | 35732 | 1.64041666667 | 14152 |
| 013923 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:52am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594043.5 | 509645.6 | 35733 | 1.64041666667 | 13923 |
| 014521 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:54am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594039.7 | 509648.8 | 35736 | 1.64041666667 | 14521 |
| 014663 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:54am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594036.6 | 509651.5 | 35737 | 1.64041666667 | 14663 |
| 014803 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:56am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594033.3 | 509655.2 | 35740 | 1.64041666667 | 14803 |
| 015324 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:57am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594031.4 | 509658.5 | 35742 | 1.64041666667 | 15324 |
| 015475 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:58am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594029.6 | 509663.5 | 35744 | 1.64041666667 | 15475 |
| 015499 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:59am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594027.9 | 509667.1 | 35746 | 1.64041666667 | 15499 |
| 015273 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:00am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594025.6 | 509671.6 | 35748 | 1.64041666667 | 15273 |
| 016031 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:00am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594024.3 | 509675.0 | 35749 | 1.64041666667 | 16031 |
| 015250 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:02am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594022.8 | 509680.2 | 35752 | 1.64041666667 | 15250 |
| 015260 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:03am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1594021.7 | 509684.0 | 35754 | 1.64041666667 | 15260 |
| 016024 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:04am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1594020.4 | 509689.4 | 35756 | 1.64041666667 | 16024 |
| 015738 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:05am | Sensor | 1797-S0031-636-G-DTE | 6804.1 | 1594019.6 | 509693.3 | 35758 | 1.64041666667 | 15738 |
| 015043 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:06am | Sensor | 1797-S0031-636-G-DTE | 6804.1 | 1594018.5 | 509697.7 | 35760 | 1.64041666667 | 15043 |
| 014469 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:06am | Sensor | 1797-S0031-636-G-DTE | 6804.4 | 1594017.0 | 509701.4 | 35761 | 1.64041666667 | 14469 |
| 014806 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:08am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594014.8 | 509706.6 | 35764 | 1.64041666667 | 14806 |
| 014343 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:09am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1594013.2 | 509710.0 | 35766 | 1.64041666667 | 14343 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:10am | Sensor | 1797-S0031-636-G-DTE | 6804.6 | 1594011.2 | 509714.7 | 35768 | 1.64041666667 | 14210 |
| 015158 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:10am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1594010.0 | 509718.2 | 35769 | 1.64041666667 | 15158 |
| 015055 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:12am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1594008.5 | 509722.8 | 35772 | 1.64041666667 | 15055 |
| 013906 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:12am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1594006.9 | 509726.7 | 35773 | 1.64041666667 | 13906 |
| 013784 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:14am | Sensor | 1797-S0031-636-G-DTE | 6804.8 | 1594005.5 | 509731.7 | 35776 | 1.64041666667 | 13784 |
| 014346 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:14am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1594004.4 | 509735.3 | 35777 | 1.64041666667 | 14346 |
| 013245 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:15am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1594003.3 | 509739.9 | 35779 | 1.64041666667 | 13245 |
| 013060 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:16am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1594002.2 | 509743.9 | 35781 | 1.64041666667 | 13060 |
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:18am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1594001.0 | 509748.9 | 35784 | 1.64041666667 | 13518 |
| 014189 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:18am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1594000.1 | 509752.7 | 35785 | 1.64041666667 | 14189 |
| 014289 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:20am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1593998.3 | 509757.6 | 35788 | 1.64041666667 | 14289 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:21am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1593997.0 | 509761.3 | 35790 | 1.64041666667 | 14067 |
| 013193 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:22am | Sensor | 1797-S0031-636-G-DTE | 6804.8 | 1593996.0 | 509765.5 | 35792 | 1.64041666667 | 13193 |
| 013173 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:22am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593996.0 | 509767.8 | 35793 | 1.64041666667 | 13173 |
| 012510 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:24am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593995.7 | 509768.7 | 35796 | 1.64041666667 | 12510 |
| 012249 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:25am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593995.7 | 509768.9 | 35798 | 1.64041666667 | 12249 |
| 012590 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:26am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593995.6 | 509768.8 | 35800 | 1.64041666667 | 12590 |
| 012474 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:26am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1593995.6 | 509768.6 | 35801 | 1.64041666667 | 12474 |
| 013084 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:28am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1593995.6 | 509768.6 | 35804 | 1.64041666667 | 13084 |
| 012520 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:28am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1593995.6 | 509768.6 | 35805 | 1.64041666667 | 12520 |
| 012352 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:30am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1593995.6 | 509768.6 | 35808 | 1.64041666667 | 12352 |
| 012183 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:31am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1593995.5 | 509769.5 | 35810 | 1.64041666667 | 12183 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012778 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:32am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593995.6 | 509771.7 | 35812 | 1.64041666667 | 12778 |
| 013487 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:32am | Sensor | 1797-S0031-636-G-DTE | 6804.8 | 1593993.7 | 509774.6 | 35813 | 1.64041666667 | 13487 |
| 013264 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:34am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1593991.9 | 509777.8 | 35816 | 1.64041666667 | 13264 |
| 012898 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:34am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593991.9 | 509779.1 | 35817 | 1.64041666667 | 12898 |
| 010941 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:37am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593886.4 | 510093.3 | 35825 | 1.64041666667 | 10941 |
| 010399 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:38am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593886.4 | 510093.4 | 35827 | 1.64041666667 | 10399 |
| 010777 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:39am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593886.4 | 510093.4 | 35829 | 1.64041666667 | 10777 |
| 010944 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:40am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593886.4 | 510093.3 | 35831 | 1.64041666667 | 10944 |
| 010874 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:41am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593886.6 | 510093.2 | 35833 | 1.64041666667 | 10874 |
| 010894 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:42am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593886.8 | 510093.2 | 35835 | 1.64041666667 | 10894 |
| 010537 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:43am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593886.6 | 510092.3 | 35837 | 1.64041666667 | 10537 |
| 010825 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:44am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593887.8 | 510091.3 | 35839 | 1.64041666667 | 10825 |
| 010139 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:45am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593889.1 | 510088.4 | 35841 | 1.64041666667 | 10139 |
| 010368 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:46am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.2 | 510086.3 | 35843 | 1.64041666667 | 10368 |
| 011232 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:47am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593891.0 | 510085.6 | 35845 | 1.64041666667 | 11232 |
| 011568 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:48am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.9 | 510085.6 | 35847 | 1.64041666667 | 11568 |
| 011352 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:49am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.8 | 510085.4 | 35849 | 1.64041666667 | 11352 |
| 011410 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:50am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593890.5 | 510085.1 | 35851 | 1.64041666667 | 11410 |
| 011721 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:51am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.4 | 510085.1 | 35853 | 1.64041666667 | 11721 |
| 011610 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:52am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593890.4 | 510085.3 | 35855 | 1.64041666667 | 11610 |
| 010664 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:53am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593890.5 | 510085.4 | 35857 | 1.64041666667 | 10664 |
| 011616 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:54am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.4 | 510085.3 | 35859 | 1.64041666667 | 11616 |
| 011694 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:55am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.4 | 510085.2 | 35861 | 1.64041666667 | 11694 |
| 011242 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:56am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.4 | 510085.3 | 35863 | 1.64041666667 | 11242 |
| 011971 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:57am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.6 | 510085.4 | 35865 | 1.64041666667 | 11971 |
| 011676 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:58am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.8 | 510085.4 | 35867 | 1.64041666667 | 11676 |
| 011638 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:59am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593890.7 | 510085.6 | 35869 | 1.64041666667 | 11638 |
| 011609 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:00am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593890.6 | 510085.7 | 35871 | 1.64041666667 | 11609 |
| 010505 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:01am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.7 | 510085.8 | 35873 | 1.64041666667 | 10505 |
| 010986 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:02am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.7 | 510085.7 | 35875 | 1.64041666667 | 10986 |
| 010762 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:03am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.8 | 510085.7 | 35877 | 1.64041666667 | 10762 |
| 010733 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:04am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593891.7 | 510086.2 | 35879 | 1.64041666667 | 10733 |
| 011865 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:05am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1593892.1 | 510086.2 | 35881 | 1.64041666667 | 11865 |
| 011916 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:06am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593891.0 | 510085.8 | 35883 | 1.64041666667 | 11916 |
| 011368 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:07am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.3 | 510085.4 | 35885 | 1.64041666667 | 11368 |
| 011277 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:08am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.4 | 510085.1 | 35887 | 1.64041666667 | 11277 |
| 010858 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:09am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.4 | 510085.1 | 35889 | 1.64041666667 | 10858 |
| 010660 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:10am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.6 | 510085.3 | 35891 | 1.64041666667 | 10660 |
| 010991 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:11am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.5 | 510085.4 | 35893 | 1.64041666667 | 10991 |
| 010495 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:12am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593890.8 | 510085.7 | 35895 | 1.64041666667 | 10495 |
| 010456 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:13am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593891.2 | 510086.0 | 35897 | 1.64041666667 | 10456 |
| 010734 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:14am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593891.2 | 510085.6 | 35899 | 1.64041666667 | 10734 |
| 010920 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:15am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593891.2 | 510085.1 | 35901 | 1.64041666667 | 10920 |
| 010965 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:16am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593891.2 | 510085.1 | 35903 | 1.64041666667 | 10965 |
| 010983 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:17am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593891.2 | 510085.4 | 35905 | 1.64041666667 | 10983 |
| 010213 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:18am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593891.3 | 510085.2 | 35907 | 1.64041666667 | 10213 |
| 010582 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:19am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593891.3 | 510085.1 | 35909 | 1.64041666667 | 10582 |
| 011337 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:20am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593891.2 | 510085.2 | 35911 | 1.64041666667 | 11337 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010974 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:21am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593891.2 | 510085.3 | 35913 | 1.64041666667 | 10974 |
| 010230 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:22am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593891.1 | 510085.4 | 35915 | 1.64041666667 | 10230 |
| 010022 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:23am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593890.9 | 510085.4 | 35917 | 1.64041666667 | 10022 |
| 009890 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:24am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593890.9 | 510085.4 | 35919 | 1.64041666667 | 9890 |
| 009680 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:25am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593890.7 | 510085.4 | 35921 | 1.64041666667 | 9680 |
| 009922 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:26am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593890.5 | 510085.3 | 35923 | 1.64041666667 | 9922 |
| 010621 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:27am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593890.4 | 510085.3 | 35925 | 1.64041666667 | 10621 |
| 010549 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:28am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593890.4 | 510085.3 | 35927 | 1.64041666667 | 10549 |
| 010876 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:29am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593890.7 | 510085.4 | 35929 | 1.64041666667 | 10876 |
| 011278 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:30am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593890.9 | 510084.7 | 35931 | 1.64041666667 | 11278 |
| 011271 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:31am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593891.6 | 510082.8 | 35933 | 1.64041666667 | 11271 |
| 011860 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:32am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593891.8 | 510080.3 | 35935 | 1.64041666667 | 11860 |
| 011208 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:33am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593892.9 | 510078.0 | 35937 | 1.64041666667 | 11208 |
| 011540 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:34am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593893.6 | 510075.8 | 35939 | 1.64041666667 | 11540 |
| 011463 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:35am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593895.1 | 510074.9 | 35941 | 1.64041666667 | 11463 |
| 011705 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:36am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593896.4 | 510073.8 | 35943 | 1.64041666667 | 11705 |
| 011939 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:37am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593898.9 | 510072.5 | 35945 | 1.64041666667 | 11939 |
| 011576 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:38am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593899.8 | 510070.7 | 35947 | 1.64041666667 | 11576 |
| 012009 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:39am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593901.1 | 510068.0 | 35949 | 1.64041666667 | 12009 |
| 011975 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:40am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593901.1 | 510065.6 | 35951 | 1.64041666667 | 11975 |
| 011948 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:41am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593902.2 | 510063.0 | 35953 | 1.64041666667 | 11948 |
| 011693 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:42am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593903.2 | 510060.5 | 35955 | 1.64041666667 | 11693 |
| 011895 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:43am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593904.2 | 510057.3 | 35957 | 1.64041666667 | 11895 |
| 011716 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:44am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593904.3 | 510053.8 | 35959 | 1.64041666667 | 11716 |
| 012035 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:45am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593903.4 | 510049.8 | 35961 | 1.64041666667 | 12035 |
| 012627 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:46am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593904.2 | 510047.6 | 35963 | 1.64041666667 | 12627 |
| 012375 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:47am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593904.5 | 510044.4 | 35965 | 1.64041666667 | 12375 |
| 012383 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:48am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593905.6 | 510042.1 | 35967 | 1.64041666667 | 12383 |
| 012650 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:49am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593906.9 | 510039.3 | 35969 | 1.64041666667 | 12650 |
| 012673 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:50am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593907.6 | 510036.5 | 35971 | 1.64041666667 | 12673 |
| 013511 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:51am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593909.2 | 510033.9 | 35973 | 1.64041666667 | 13511 |
| 012842 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:52am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593909.5 | 510031.1 | 35975 | 1.64041666667 | 12842 |
| 012946 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:53am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593910.8 | 510028.2 | 35977 | 1.64041666667 | 12946 |
| 012765 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:54am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593911.2 | 510026.0 | 35979 | 1.64041666667 | 12765 |
| 012625 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:55am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593912.3 | 510023.7 | 35981 | 1.64041666667 | 12625 |
| 012981 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:56am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593913.0 | 510021.7 | 35983 | 1.64041666667 | 12981 |
| 013549 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:57am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593914.0 | 510019.6 | 35985 | 1.64041666667 | 13549 |
| 012399 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:58am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593914.7 | 510017.7 | 35987 | 1.64041666667 | 12399 |
| 012907 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:59am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.6 | 510015.8 | 35989 | 1.64041666667 | 12907 |
| 012412 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:00am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.8 | 510015.2 | 35991 | 1.64041666667 | 12412 |
| 012637 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:01am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.6 | 510015.2 | 35993 | 1.64041666667 | 12637 |
| 012606 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:02am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.2 | 35995 | 1.64041666667 | 12606 |
| 012438 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:03am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.2 | 35997 | 1.64041666667 | 12438 |
| 013184 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:04am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 35999 | 1.64041666667 | 13184 |
| 013213 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:05am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 36001 | 1.64041666667 | 13213 |
| 012555 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:06am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 36003 | 1.64041666667 | 12555 |
| 011742 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:07am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 36005 | 1.64041666667 | 11742 |
| 012372 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:08am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 36007 | 1.64041666667 | 12372 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011422 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:09am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 36009 | 1.64041666667 | 11422 |
| 010819 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:10am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 36011 | 1.64041666667 | 10819 |
| 011501 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:11am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 36013 | 1.64041666667 | 11501 |
| 011786 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:12am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.3 | 36015 | 1.64041666667 | 11786 |
| 011842 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:13am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.6 | 510015.4 | 36017 | 1.64041666667 | 11842 |
| 011919 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:14am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.6 | 510015.4 | 36019 | 1.64041666667 | 11919 |
| 011527 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:15am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.6 | 510015.4 | 36021 | 1.64041666667 | 11527 |
| 012453 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:16am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.6 | 510015.4 | 36023 | 1.64041666667 | 12453 |
| 012082 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:17am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593915.6 | 510015.4 | 36025 | 1.64041666667 | 12082 |
| 012301 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:18am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593915.6 | 510015.4 | 36027 | 1.64041666667 | 12301 |
| 012702 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:19am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.7 | 510015.4 | 36029 | 1.64041666667 | 12702 |
| 012177 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:20am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593915.9 | 510014.9 | 36031 | 1.64041666667 | 12177 |
| 011709 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:21am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593916.2 | 510013.2 | 36033 | 1.64041666667 | 11709 |
| 012039 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:22am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593917.0 | 510010.9 | 36035 | 1.64041666667 | 12039 |
| 012209 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:23am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593918.8 | 510008.0 | 36037 | 1.64041666667 | 12209 |
| 012635 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:24am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593920.2 | 510005.1 | 36039 | 1.64041666667 | 12635 |
| 012334 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:25am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593921.7 | 510001.6 | 36041 | 1.64041666667 | 12334 |
| 012623 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:26am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593923.2 | 509998.7 | 36043 | 1.64041666667 | 12623 |
| 012733 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:27am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593923.9 | 509995.1 | 36045 | 1.64041666667 | 12733 |
| 013515 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:28am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593925.5 | 509992.8 | 36047 | 1.64041666667 | 13515 |
| 011982 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:29am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593927.5 | 509990.4 | 36049 | 1.64041666667 | 11982 |
| 012297 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:30am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593929.5 | 509988.2 | 36051 | 1.64041666667 | 12297 |
| 012677 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:31am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593932.2 | 509987.7 | 36053 | 1.64041666667 | 12677 |
| 013843 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:32am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593934.7 | 509987.8 | 36055 | 1.64041666667 | 13843 |
| 013607 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:33am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593937.0 | 509989.6 | 36057 | 1.64041666667 | 13607 |
| 012573 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:34am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593939.3 | 509991.0 | 36059 | 1.64041666667 | 12573 |
| 012615 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:35am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593942.5 | 509992.4 | 36061 | 1.64041666667 | 12615 |
| 012211 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:36am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593945.1 | 509994.1 | 36063 | 1.64041666667 | 12211 |
| 012366 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:37am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593948.7 | 509995.4 | 36065 | 1.64041666667 | 12366 |
| 011906 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:38am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593951.5 | 509996.3 | 36067 | 1.64041666667 | 11906 |
| 011549 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:39am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593954.5 | 509998.0 | 36069 | 1.64041666667 | 11549 |
| 011919 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:40am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593957.1 | 509998.7 | 36071 | 1.64041666667 | 11919 |
| 012037 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:41am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593960.4 | 510000.3 | 36073 | 1.64041666667 | 12037 |
| 012028 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:42am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593963.4 | 510001.7 | 36075 | 1.64041666667 | 12028 |
| 011251 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:43am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593966.8 | 510002.8 | 36077 | 1.64041666667 | 11251 |
| 011998 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:44am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593969.0 | 510004.5 | 36079 | 1.64041666667 | 11998 |
| 012621 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:45am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593972.1 | 510005.5 | 36081 | 1.64041666667 | 12621 |
| 012094 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:46am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593974.9 | 510005.9 | 36083 | 1.64041666667 | 12094 |
| 012210 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:47am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593978.1 | 510006.8 | 36085 | 1.64041666667 | 12210 |
| 011406 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:48am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593981.0 | 510007.2 | 36087 | 1.64041666667 | 11406 |
| 010773 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:49am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593983.3 | 510009.6 | 36089 | 1.64041666667 | 10773 |
| 010567 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:50am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593985.3 | 510011.3 | 36091 | 1.64041666667 | 10567 |
| 010931 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:51am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593988.0 | 510012.8 | 36093 | 1.64041666667 | 10931 |
| 010904 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:52am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593991.4 | 510014.7 | 36095 | 1.64041666667 | 10904 |
| 010708 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:53am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593994.8 | 510015.2 | 36097 | 1.64041666667 | 10708 |
| 011716 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:54am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593997.7 | 510016.6 | 36099 | 1.64041666667 | 11716 |
| 011637 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:55am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594000.7 | 510017.6 | 36101 | 1.64041666667 | 11637 |
| 011773 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:56am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594003.3 | 510018.6 | 36103 | 1.64041666667 | 11773 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010950 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:57am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594006.1 | 510020.4 | 36105 | 1.64041666667 | 10950 |
| 011994 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:58am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1594009.0 | 510021.7 | 36107 | 1.64041666667 | 11994 |
| 012049 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:59am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1594011.8 | 510023.9 | 36109 | 1.64041666667 | 12049 |
| 012305 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:00am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594014.2 | 510025.4 | 36111 | 1.64041666667 | 12305 |
| 012059 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:01am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1594017.5 | 510026.8 | 36113 | 1.64041666667 | 12059 |
| 012851 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:02am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1594019.5 | 510028.2 | 36115 | 1.64041666667 | 12851 |
| 012696 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:03am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594022.5 | 510029.3 | 36117 | 1.64041666667 | 12696 |
| 012841 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:04am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594024.8 | 510030.7 | 36119 | 1.64041666667 | 12841 |
| 012975 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:05am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1594027.9 | 510031.5 | 36121 | 1.64041666667 | 12975 |
| 012691 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:06am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594029.9 | 510032.5 | 36123 | 1.64041666667 | 12691 |
| 012771 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:07am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1594032.2 | 510033.6 | 36125 | 1.64041666667 | 12771 |
| 012689 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:08am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1594032.1 | 510035.1 | 36127 | 1.64041666667 | 12689 |
| 013182 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:09am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1594032.8 | 510037.3 | 36129 | 1.64041666667 | 13182 |
| 011585 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:10am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1594032.4 | 510037.4 | 36131 | 1.64041666667 | 11585 |
| 012599 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:11am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1594032.0 | 510038.9 | 36133 | 1.64041666667 | 12599 |
| 012382 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:12am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594031.1 | 510041.5 | 36135 | 1.64041666667 | 12382 |
| 012380 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:13am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594029.0 | 510044.6 | 36137 | 1.64041666667 | 12380 |
| 012011 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:14am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594027.9 | 510047.1 | 36139 | 1.64041666667 | 12011 |
| 011698 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:15am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594025.5 | 510049.9 | 36141 | 1.64041666667 | 11698 |
| 012340 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:16am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1594024.4 | 510052.3 | 36143 | 1.64041666667 | 12340 |
| 011861 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:17am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594022.5 | 510055.2 | 36145 | 1.64041666667 | 11861 |
| 011652 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:18am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594020.8 | 510058.5 | 36147 | 1.64041666667 | 11652 |
| 011849 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:19am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594020.3 | 510061.9 | 36149 | 1.64041666667 | 11849 |
| 011397 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:20am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594018.8 | 510064.2 | 36151 | 1.64041666667 | 11397 |
| 011346 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:21am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594017.8 | 510067.7 | 36153 | 1.64041666667 | 11346 |
| 012165 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:22am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594017.1 | 510071.1 | 36155 | 1.64041666667 | 12165 |
| 012025 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:23am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594015.8 | 510074.3 | 36157 | 1.64041666667 | 12025 |
| 011946 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:24am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594015.8 | 510077.3 | 36159 | 1.64041666667 | 11946 |
| 012127 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:25am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1594015.0 | 510080.0 | 36161 | 1.64041666667 | 12127 |
| 011675 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:26am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594015.0 | 510082.5 | 36163 | 1.64041666667 | 11675 |
| 011283 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:27am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594013.8 | 510085.1 | 36165 | 1.64041666667 | 11283 |
| 010959 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:28am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1594013.4 | 510087.4 | 36167 | 1.64041666667 | 10959 |
| 010882 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:29am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594011.9 | 510090.4 | 36169 | 1.64041666667 | 10882 |
| 011693 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:30am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1594011.3 | 510092.5 | 36171 | 1.64041666667 | 11693 |
| 011542 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:31am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1594010.1 | 510095.0 | 36173 | 1.64041666667 | 11542 |
| 011810 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:32am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1594009.7 | 510097.1 | 36175 | 1.64041666667 | 11810 |
| 011983 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:33am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1594008.7 | 510099.5 | 36177 | 1.64041666667 | 11983 |
| 013145 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:34am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1594008.2 | 510101.4 | 36179 | 1.64041666667 | 13145 |
| 012577 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:35am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1594007.4 | 510103.5 | 36181 | 1.64041666667 | 12577 |
| 012129 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:36am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1594007.5 | 510105.4 | 36183 | 1.64041666667 | 12129 |
| 011428 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:37am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1594005.9 | 510107.0 | 36185 | 1.64041666667 | 11428 |
| 011670 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:38am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1594004.4 | 510109.1 | 36187 | 1.64041666667 | 11670 |
| 012377 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:39am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1594002.1 | 510111.5 | 36189 | 1.64041666667 | 12377 |
| 012317 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:40am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1594000.0 | 510113.4 | 36191 | 1.64041666667 | 12317 |
| 012111 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:41am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593998.3 | 510116.0 | 36193 | 1.64041666667 | 12111 |
| 012955 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:42am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593996.3 | 510117.9 | 36195 | 1.64041666667 | 12955 |
| 012364 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:43am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593995.4 | 510120.6 | 36197 | 1.64041666667 | 12364 |
| 013045 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:44am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593994.1 | 510122.6 | 36199 | 1.64041666667 | 13045 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013473 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:45am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593992.8 | 510125.2 | 36201 | 1.64041666667 | 13473 |
| 013443 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:46am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593991.4 | 510127.1 | 36203 | 1.64041666667 | 13443 |
| 012939 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:47am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593990.3 | 510129.4 | 36205 | 1.64041666667 | 12939 |
| 012566 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:48am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593989.3 | 510131.1 | 36207 | 1.64041666667 | 12566 |
| 012363 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:49am | Sensor | 1797-S0031-636-G-DTE | 6804.9 | 1593988.4 | 510132.9 | 36209 | 1.64041666667 | 12363 |
| 012669 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:50am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1593987.2 | 510134.1 | 36211 | 1.64041666667 | 12669 |
| 012864 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:51am | Sensor | 1797-S0031-636-G-DTE | 6804.1 | 1593985.7 | 510135.2 | 36213 | 1.64041666667 | 12864 |
| 013393 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:52am | Sensor | 1797-S0031-636-G-DTE | 6804.0 | 1593984.0 | 510135.7 | 36215 | 1.64041666667 | 13393 |
| 012716 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:53am | Sensor | 1797-S0031-636-G-DTE | 6804.2 | 1593981.1 | 510135.1 | 36217 | 1.64041666667 | 12716 |
| 012343 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:54am | Sensor | 1797-S0031-636-G-DTE | 6804.5 | 1593978.4 | 510134.4 | 36219 | 1.64041666667 | 12343 |
| 012050 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:55am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1593975.9 | 510133.3 | 36221 | 1.64041666667 | 12050 |
| 011413 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:56am | Sensor | 1797-S0031-636-G-DTE | 6804.7 | 1593973.8 | 510132.5 | 36223 | 1.64041666667 | 11413 |
| 012270 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:57am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593971.5 | 510131.4 | 36225 | 1.64041666667 | 12270 |
| 011679 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:58am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593969.6 | 510130.3 | 36227 | 1.64041666667 | 11679 |
| 012164 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:59am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593967.0 | 510129.4 | 36229 | 1.64041666667 | 12164 |
| 011680 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:00am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593964.5 | 510128.1 | 36231 | 1.64041666667 | 11680 |
| 011962 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:01am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593961.3 | 510127.3 | 36233 | 1.64041666667 | 11962 |
| 012646 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:02am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593958.8 | 510126.2 | 36235 | 1.64041666667 | 12646 |
| 012798 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:03am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593955.7 | 510125.5 | 36237 | 1.64041666667 | 12798 |
| 012081 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:04am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593953.0 | 510124.9 | 36239 | 1.64041666667 | 12081 |
| 011318 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:05am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593950.2 | 510123.5 | 36241 | 1.64041666667 | 11318 |
| 011639 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:06am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593948.1 | 510122.9 | 36243 | 1.64041666667 | 11639 |
| 012052 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:07am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593945.3 | 510121.2 | 36245 | 1.64041666667 | 12052 |
| 012779 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:08am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593942.6 | 510120.2 | 36247 | 1.64041666667 | 12779 |
| 012596 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:09am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593939.3 | 510118.7 | 36249 | 1.64041666667 | 12596 |
| 012440 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:10am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593936.8 | 510117.0 | 36251 | 1.64041666667 | 12440 |
| 012540 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:11am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593933.5 | 510116.3 | 36253 | 1.64041666667 | 12540 |
| 011973 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:12am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593930.9 | 510114.9 | 36255 | 1.64041666667 | 11973 |
| 012157 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:13am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593927.8 | 510113.8 | 36257 | 1.64041666667 | 12157 |
| 011503 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:14am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593925.8 | 510112.1 | 36259 | 1.64041666667 | 11503 |
| 011271 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:15am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593923.2 | 510110.1 | 36261 | 1.64041666667 | 11271 |
| 011215 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:16am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593920.9 | 510108.9 | 36263 | 1.64041666667 | 11215 |
| 011468 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:17am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593917.6 | 510107.3 | 36265 | 1.64041666667 | 11468 |
| 012241 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:18am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593914.9 | 510106.8 | 36267 | 1.64041666667 | 12241 |
| 011783 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:19am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593912.1 | 510105.7 | 36269 | 1.64041666667 | 11783 |
| 012170 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:20am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593909.8 | 510105.2 | 36271 | 1.64041666667 | 12170 |
| 011248 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:21am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593907.3 | 510103.5 | 36273 | 1.64041666667 | 11248 |
| 010782 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:22am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593905.0 | 510102.5 | 36275 | 1.64041666667 | 10782 |
| 010737 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:23am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593901.9 | 510100.9 | 36277 | 1.64041666667 | 10737 |
| 010817 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:24am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593899.4 | 510099.3 | 36279 | 1.64041666667 | 10817 |
| 010719 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:25am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593896.3 | 510098.4 | 36281 | 1.64041666667 | 10719 |
| 010132 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:26am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593894.7 | 510096.7 | 36283 | 1.64041666667 | 10132 |
| 011122 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:27am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593892.2 | 510095.1 | 36285 | 1.64041666667 | 11122 |
| 011993 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:28am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593890.5 | 510093.8 | 36287 | 1.64041666667 | 11993 |
| 010953 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:29am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593888.4 | 510093.5 | 36289 | 1.64041666667 | 10953 |
| 010519 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:30am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593887.8 | 510093.5 | 36291 | 1.64041666667 | 10519 |
| 010777 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:31am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593888.2 | 510093.5 | 36293 | 1.64041666667 | 10777 |
| 011199 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:32am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593888.7 | 510093.5 | 36295 | 1.64041666667 | 11199 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011377 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:33am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593889.5 | 510091.7 | 36297 | 1.64041666667 | 11377 |
| 010809 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:34am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593890.6 | 510091.1 | 36299 | 1.64041666667 | 10809 |
| 010768 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:35am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593892.9 | 510090.9 | 36301 | 1.64041666667 | 10768 |
| 010189 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:36am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593895.1 | 510091.7 | 36303 | 1.64041666667 | 10189 |
| 012766 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:37am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593898.0 | 510092.7 | 36305 | 1.64041666667 | 12766 |
| 012335 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:38am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593900.4 | 510093.6 | 36307 | 1.64041666667 | 12335 |
| 011890 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:39am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593903.2 | 510094.8 | 36309 | 1.64041666667 | 11890 |
| 011435 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:40am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593905.7 | 510095.0 | 36311 | 1.64041666667 | 11435 |
| 011270 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:41am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593908.2 | 510096.1 | 36313 | 1.64041666667 | 11270 |
| 011844 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:42am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593910.4 | 510096.4 | 36315 | 1.64041666667 | 11844 |
| 012490 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:43am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593912.8 | 510097.7 | 36317 | 1.64041666667 | 12490 |
| 012193 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:44am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593915.3 | 510097.9 | 36319 | 1.64041666667 | 12193 |
| 011823 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:45am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593917.7 | 510099.3 | 36321 | 1.64041666667 | 11823 |
| 011683 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:46am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593919.6 | 510100.4 | 36323 | 1.64041666667 | 11683 |
| 012017 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:47am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593921.2 | 510102.9 | 36325 | 1.64041666667 | 12017 |
| 012482 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:48am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593922.9 | 510105.3 | 36327 | 1.64041666667 | 12482 |
| 012586 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:49am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593925.5 | 510107.0 | 36329 | 1.64041666667 | 12586 |
| 011857 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:50am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593928.0 | 510108.7 | 36331 | 1.64041666667 | 11857 |
| 011762 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:51am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593931.0 | 510109.7 | 36333 | 1.64041666667 | 11762 |
| 011663 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:52am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593933.5 | 510111.2 | 36335 | 1.64041666667 | 11663 |
| 011623 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:53am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593936.3 | 510111.9 | 36337 | 1.64041666667 | 11623 |
| 011878 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:54am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593938.6 | 510113.2 | 36339 | 1.64041666667 | 11878 |
| 011661 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:55am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593941.5 | 510114.2 | 36341 | 1.64041666667 | 11661 |
| 012387 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:56am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593943.9 | 510115.4 | 36343 | 1.64041666667 | 12387 |
| 012270 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:57am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593946.8 | 510116.9 | 36345 | 1.64041666667 | 12270 |
| 011874 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:58am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593949.1 | 510118.1 | 36347 | 1.64041666667 | 11874 |
| 012447 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:59am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593951.8 | 510119.8 | 36349 | 1.64041666667 | 12447 |
| 013353 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:00am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593954.4 | 510120.6 | 36351 | 1.64041666667 | 13353 |
| 012739 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:01am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593957.2 | 510122.3 | 36353 | 1.64041666667 | 12739 |
| 013053 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:02am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593959.7 | 510122.8 | 36355 | 1.64041666667 | 13053 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:03am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593962.2 | 510124.0 | 36357 | 1.64041666667 | 13050 |
| 012193 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:04am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593964.6 | 510124.8 | 36359 | 1.64041666667 | 12193 |
| 011561 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:05am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593967.6 | 510125.9 | 36361 | 1.64041666667 | 11561 |
| 011783 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:06am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593970.1 | 510126.7 | 36363 | 1.64041666667 | 11783 |
| 011870 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:07am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593973.2 | 510127.2 | 36365 | 1.64041666667 | 11870 |
| 011807 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:08am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593975.6 | 510127.8 | 36367 | 1.64041666667 | 11807 |
| 012034 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:09am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593978.7 | 510128.2 | 36369 | 1.64041666667 | 12034 |
| 011966 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:10am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593981.0 | 510129.2 | 36371 | 1.64041666667 | 11966 |
| 012701 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:11am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593983.8 | 510129.6 | 36373 | 1.64041666667 | 12701 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:12am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593986.2 | 510130.5 | 36375 | 1.64041666667 | 13301 |
| 012807 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:13am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593988.6 | 510129.9 | 36377 | 1.64041666667 | 12807 |
| 013594 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:14am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593990.2 | 510128.0 | 36379 | 1.64041666667 | 13594 |
| 012896 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:15am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593991.0 | 510125.5 | 36381 | 1.64041666667 | 12896 |
| 012549 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:16am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593991.8 | 510123.9 | 36383 | 1.64041666667 | 12549 |
| 011574 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:17am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593991.6 | 510122.4 | 36385 | 1.64041666667 | 11574 |
| 012397 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:18am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593990.4 | 510120.8 | 36387 | 1.64041666667 | 12397 |
| 012216 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:19am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593988.3 | 510120.5 | 36389 | 1.64041666667 | 12216 |
| 011979 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:20am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593986.0 | 510120.0 | 36391 | 1.64041666667 | 11979 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012070 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:21am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593982.9 | 510119.2 | 36393 | 1.64041666667 | 12070 |
| 013209 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:22am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593980.4 | 510118.4 | 36395 | 1.64041666667 | 13209 |
| 012838 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:23am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593977.9 | 510117.1 | 36397 | 1.64041666667 | 12838 |
| 012861 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:24am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593975.8 | 510116.2 | 36399 | 1.64041666667 | 12861 |
| 012799 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:25am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593972.9 | 510115.2 | 36401 | 1.64041666667 | 12799 |
| 012899 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:26am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593970.1 | 510115.2 | 36403 | 1.64041666667 | 12899 |
| 012903 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:27am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593967.3 | 510115.0 | 36405 | 1.64041666667 | 12903 |
| 012298 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:28am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593964.8 | 510115.1 | 36407 | 1.64041666667 | 12298 |
| 012077 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:29am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593961.8 | 510114.4 | 36409 | 1.64041666667 | 12077 |
| 012351 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:30am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593959.1 | 510114.0 | 36411 | 1.64041666667 | 12351 |
| 012535 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:31am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593956.3 | 510112.9 | 36413 | 1.64041666667 | 12535 |
| 012301 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:32am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593953.9 | 510112.4 | 36415 | 1.64041666667 | 12301 |
| 012356 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:33am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593951.2 | 510111.3 | 36417 | 1.64041666667 | 12356 |
| 012958 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:34am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593948.6 | 510110.6 | 36419 | 1.64041666667 | 12958 |
| 012936 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:35am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593945.9 | 510109.8 | 36421 | 1.64041666667 | 12936 |
| 013336 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:36am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593943.7 | 510109.4 | 36423 | 1.64041666667 | 13336 |
| 013104 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:37am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593941.1 | 510108.6 | 36425 | 1.64041666667 | 13104 |
| 011848 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:38am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593939.1 | 510108.3 | 36427 | 1.64041666667 | 11848 |
| 012012 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:39am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593936.8 | 510107.4 | 36429 | 1.64041666667 | 12012 |
| 012082 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:40am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593934.9 | 510106.7 | 36431 | 1.64041666667 | 12082 |
| 011881 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:41am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593933.0 | 510105.6 | 36433 | 1.64041666667 | 11881 |
| 011610 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:42am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593930.5 | 510104.0 | 36435 | 1.64041666667 | 11610 |
| 011751 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:43am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593927.5 | 510102.8 | 36437 | 1.64041666667 | 11751 |
| 011965 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:44am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593925.5 | 510101.1 | 36439 | 1.64041666667 | 11965 |
| 011988 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:45am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593922.9 | 510099.9 | 36441 | 1.64041666667 | 11988 |
| 011513 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:46am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593920.5 | 510098.5 | 36443 | 1.64041666667 | 11513 |
| 011396 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:47am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593917.5 | 510097.7 | 36445 | 1.64041666667 | 11396 |
| 012050 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:48am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593915.1 | 510096.6 | 36447 | 1.64041666667 | 12050 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:49am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593912.2 | 510095.7 | 36449 | 1.64041666667 | 12853 |
| 012292 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:50am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593909.6 | 510094.7 | 36451 | 1.64041666667 | 12292 |
| 012202 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:51am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593906.6 | 510093.1 | 36453 | 1.64041666667 | 12202 |
| 011213 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:52am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593904.3 | 510092.3 | 36455 | 1.64041666667 | 11213 |
| 011340 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:53am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593901.6 | 510090.6 | 36457 | 1.64041666667 | 11340 |
| 010916 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:54am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593899.4 | 510089.7 | 36459 | 1.64041666667 | 10916 |
| 010940 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:55am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593897.7 | 510087.7 | 36461 | 1.64041666667 | 10940 |
| 010744 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:56am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593896.5 | 510085.9 | 36463 | 1.64041666667 | 10744 |
| 010528 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:57am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593896.5 | 510084.1 | 36465 | 1.64041666667 | 10528 |
| 011599 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:58am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593896.4 | 510083.3 | 36467 | 1.64041666667 | 11599 |
| 011685 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:59am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593895.0 | 510082.1 | 36469 | 1.64041666667 | 11685 |
| 011545 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:00am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593893.1 | 510081.2 | 36471 | 1.64041666667 | 11545 |
| 011691 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:01am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593892.2 | 510079.7 | 36473 | 1.64041666667 | 11691 |
| 011654 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:02am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593892.3 | 510078.4 | 36475 | 1.64041666667 | 11654 |
| 012000 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:03am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593892.9 | 510077.3 | 36477 | 1.64041666667 | 12000 |
| 011685 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:04am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593893.2 | 510077.2 | 36479 | 1.64041666667 | 11685 |
| 011463 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:05am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593893.7 | 510077.0 | 36481 | 1.64041666667 | 11463 |
| 011218 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:06am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593895.0 | 510077.4 | 36483 | 1.64041666667 | 11218 |
| 011987 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:07am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593897.8 | 510077.8 | 36485 | 1.64041666667 | 11987 |
| 011475 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:08am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593900.3 | 510078.6 | 36487 | 1.64041666667 | 11475 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012687 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:09am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593902.9 | 510079.8 | 36489 | 1.64041666667 | 12687 |
| 012394 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:10am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593904.2 | 510080.5 | 36491 | 1.64041666667 | 12394 |
| 012716 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:11am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593904.7 | 510080.9 | 36493 | 1.64041666667 | 12716 |
| 011923 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:12am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593904.9 | 510080.5 | 36495 | 1.64041666667 | 11923 |
| 011679 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:13am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593904.8 | 510080.0 | 36497 | 1.64041666667 | 11679 |
| 011849 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:14am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593904.5 | 510080.0 | 36499 | 1.64041666667 | 11849 |
| 011652 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:15am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593904.5 | 510080.1 | 36501 | 1.64041666667 | 11652 |
| 012029 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:16am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593904.6 | 510080.1 | 36503 | 1.64041666667 | 12029 |
| 012766 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:17am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593904.7 | 510080.1 | 36505 | 1.64041666667 | 12766 |
| 011973 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:18am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593904.8 | 510080.5 | 36507 | 1.64041666667 | 11973 |
| 011520 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:19am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593906.2 | 510081.2 | 36509 | 1.64041666667 | 11520 |
| 010777 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:20am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593907.2 | 510082.1 | 36511 | 1.64041666667 | 10777 |
| 010697 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:21am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593908.7 | 510083.3 | 36513 | 1.64041666667 | 10697 |
| 011627 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:22am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593910.0 | 510084.9 | 36515 | 1.64041666667 | 11627 |
| 012577 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:23am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593912.1 | 510085.9 | 36517 | 1.64041666667 | 12577 |
| 012452 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:24am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593914.1 | 510087.1 | 36519 | 1.64041666667 | 12452 |
| 011527 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:25am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593917.0 | 510088.1 | 36521 | 1.64041666667 | 11527 |
| 011719 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:26am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593920.1 | 510088.3 | 36523 | 1.64041666667 | 11719 |
| 012667 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:27am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593922.2 | 510088.9 | 36525 | 1.64041666667 | 12667 |
| 012030 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:28am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593924.1 | 510089.6 | 36527 | 1.64041666667 | 12030 |
| 011829 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:29am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593926.3 | 510091.0 | 36529 | 1.64041666667 | 11829 |
| 011926 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:30am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593928.8 | 510091.6 | 36531 | 1.64041666667 | 11926 |
| 012438 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:31am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593931.1 | 510092.7 | 36533 | 1.64041666667 | 12438 |
| 013251 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:32am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593933.4 | 510093.5 | 36535 | 1.64041666667 | 13251 |
| 013206 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:33am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593935.8 | 510094.8 | 36537 | 1.64041666667 | 13206 |
| 012813 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:34am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593938.5 | 510095.3 | 36539 | 1.64041666667 | 12813 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:35am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593941.6 | 510095.6 | 36541 | 1.64041666667 | 13050 |
| 012275 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:36am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593943.8 | 510096.7 | 36543 | 1.64041666667 | 12275 |
| 011997 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:37am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593946.1 | 510097.4 | 36545 | 1.64041666667 | 11997 |
| 011481 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:38am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593947.7 | 510098.2 | 36547 | 1.64041666667 | 11481 |
| 012000 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:39am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593949.8 | 510098.9 | 36549 | 1.64041666667 | 12000 |
| 012000 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:40am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593951.7 | 510100.2 | 36551 | 1.64041666667 | 12000 |
| 011850 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:41am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593954.2 | 510101.7 | 36553 | 1.64041666667 | 11850 |
| 011998 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:42am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593956.0 | 510103.5 | 36555 | 1.64041666667 | 11998 |
| 012801 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:43am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593958.4 | 510105.3 | 36557 | 1.64041666667 | 12801 |
| 012758 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:44am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593960.8 | 510106.7 | 36559 | 1.64041666667 | 12758 |
| 012531 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:45am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593963.2 | 510108.4 | 36561 | 1.64041666667 | 12531 |
| 012809 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:46am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593964.1 | 510109.1 | 36563 | 1.64041666667 | 12809 |
| 012087 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:47am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.8 | 510108.7 | 36565 | 1.64041666667 | 12087 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:48am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.8 | 510108.3 | 36567 | 1.64041666667 | 12236 |
| 012148 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:49am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.7 | 510108.3 | 36569 | 1.64041666667 | 12148 |
| 012818 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:50am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.6 | 510108.4 | 36571 | 1.64041666667 | 12818 |
| 012918 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:51am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.6 | 510108.4 | 36573 | 1.64041666667 | 12918 |
| 012028 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:52am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.6 | 510108.4 | 36575 | 1.64041666667 | 12028 |
| 012173 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:53am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593964.7 | 510108.4 | 36577 | 1.64041666667 | 12173 |
| 012090 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:54am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.7 | 510108.4 | 36579 | 1.64041666667 | 12090 |
| 011998 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:55am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.7 | 510108.4 | 36581 | 1.64041666667 | 11998 |
| 011721 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:56am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593964.7 | 510108.4 | 36583 | 1.64041666667 | 11721 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011693 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:57am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.6 | 510108.5 | 36585 | 1.64041666667 | 11693 |
| 011430 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:58am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.5 | 510108.5 | 36587 | 1.64041666667 | 11430 |
| 010727 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:59am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593964.5 | 510108.5 | 36589 | 1.64041666667 | 10727 |
| 012528 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:00am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.5 | 510108.5 | 36591 | 1.64041666667 | 12528 |
| 012395 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:01am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.5 | 510108.5 | 36593 | 1.64041666667 | 12395 |
| 012582 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:02am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.4 | 510108.6 | 36595 | 1.64041666667 | 12582 |
| 013182 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:03am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.4 | 510108.6 | 36597 | 1.64041666667 | 13182 |
| 012762 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:04am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.5 | 510108.7 | 36599 | 1.64041666667 | 12762 |
| 012361 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:05am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.5 | 510108.8 | 36601 | 1.64041666667 | 12361 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:06am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.5 | 510108.9 | 36603 | 1.64041666667 | 13043 |
| 012527 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:07am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.4 | 510108.9 | 36605 | 1.64041666667 | 12527 |
| 012423 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:08am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.4 | 510109.0 | 36607 | 1.64041666667 | 12423 |
| 011691 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:09am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.4 | 510109.0 | 36609 | 1.64041666667 | 11691 |
| 011511 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:10am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.4 | 510109.0 | 36611 | 1.64041666667 | 11511 |
| 011170 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:11am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.4 | 510109.0 | 36613 | 1.64041666667 | 11170 |
| 012155 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:12am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.4 | 510109.0 | 36615 | 1.64041666667 | 12155 |
| 011832 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:13am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.3 | 510109.1 | 36617 | 1.64041666667 | 11832 |
| 012213 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:14am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.2 | 510109.1 | 36619 | 1.64041666667 | 12213 |
| 011625 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:15am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.2 | 510109.0 | 36621 | 1.64041666667 | 11625 |
| 012261 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:16am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.2 | 510109.1 | 36623 | 1.64041666667 | 12261 |
| 011779 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:17am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.3 | 510109.0 | 36625 | 1.64041666667 | 11779 |
| 011786 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:18am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593964.3 | 510108.9 | 36627 | 1.64041666667 | 11786 |
| 011287 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:19am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.4 | 510108.9 | 36629 | 1.64041666667 | 11287 |
| 011164 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:20am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.5 | 510108.8 | 36631 | 1.64041666667 | 11164 |
| 011244 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:21am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.5 | 510108.8 | 36633 | 1.64041666667 | 11244 |
| 011860 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:22am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.5 | 510108.7 | 36635 | 1.64041666667 | 11860 |
| 011816 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:23am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.5 | 510108.7 | 36637 | 1.64041666667 | 11816 |
| 011439 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:24am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.5 | 510108.7 | 36639 | 1.64041666667 | 11439 |
| 011129 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:25am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.5 | 510108.7 | 36641 | 1.64041666667 | 11129 |
| 012005 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:26am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.5 | 510108.7 | 36643 | 1.64041666667 | 12005 |
| 012408 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:27am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.4 | 510108.7 | 36645 | 1.64041666667 | 12408 |
| 011967 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:28am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.4 | 510108.7 | 36647 | 1.64041666667 | 11967 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:29am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.4 | 510108.7 | 36649 | 1.64041666667 | 13038 |
| 012997 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:30am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.5 | 510108.7 | 36651 | 1.64041666667 | 12997 |
| 012118 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:31am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.5 | 510108.7 | 36653 | 1.64041666667 | 12118 |
| 012104 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:32am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.5 | 510108.7 | 36655 | 1.64041666667 | 12104 |
| 012126 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:33am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.4 | 510108.7 | 36657 | 1.64041666667 | 12126 |
| 012161 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:34am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.3 | 510108.7 | 36659 | 1.64041666667 | 12161 |
| 011528 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:35am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.4 | 510108.7 | 36661 | 1.64041666667 | 11528 |
| 011134 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:36am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.4 | 510108.8 | 36663 | 1.64041666667 | 11134 |
| 011490 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:37am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.4 | 510108.8 | 36665 | 1.64041666667 | 11490 |
| 012006 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:38am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.4 | 510108.8 | 36667 | 1.64041666667 | 12006 |
| 012333 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:39am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.4 | 510108.7 | 36669 | 1.64041666667 | 12333 |
| 012202 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:40am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.6 | 510108.5 | 36671 | 1.64041666667 | 12202 |
| 012751 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:41am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593964.6 | 510108.7 | 36673 | 1.64041666667 | 12751 |
| 012242 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:42am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593964.6 | 510109.3 | 36675 | 1.64041666667 | 12242 |
| 012091 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:43am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593966.3 | 510109.8 | 36677 | 1.64041666667 | 12091 |
| 012044 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:44am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593968.4 | 510111.0 | 36679 | 1.64041666667 | 12044 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011649 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:45am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593970.7 | 510112.6 | 36681 | 1.64041666667 | 11649 |
| 011368 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:46am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593973.2 | 510113.9 | 36683 | 1.64041666667 | 11368 |
| 011584 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:47am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593975.6 | 510116.0 | 36685 | 1.64041666667 | 11584 |
| 012561 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:48am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593977.5 | 510117.4 | 36687 | 1.64041666667 | 12561 |
| 012150 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:49am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593980.5 | 510119.3 | 36689 | 1.64041666667 | 12150 |
| 012159 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:50am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593982.8 | 510120.7 | 36691 | 1.64041666667 | 12159 |
| 012195 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:51am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593985.7 | 510121.8 | 36693 | 1.64041666667 | 12195 |
| 012109 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:52am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593987.7 | 510122.9 | 36695 | 1.64041666667 | 12109 |
| 011994 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:53am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593990.4 | 510123.5 | 36697 | 1.64041666667 | 11994 |
| 012341 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:54am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593992.4 | 510124.0 | 36699 | 1.64041666667 | 12341 |
| 012994 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:55am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593994.0 | 510123.5 | 36701 | 1.64041666667 | 12994 |
| 012987 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:56am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593995.7 | 510121.7 | 36703 | 1.64041666667 | 12987 |
| 012052 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:57am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593996.2 | 510119.3 | 36705 | 1.64041666667 | 12052 |
| 012209 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:58am | Sensor | 1797-S0031-636-G-DTE | 6807.8 | 1593995.8 | 510117.0 | 36707 | 1.64041666667 | 12209 |
| 012148 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:59am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593994.1 | 510114.4 | 36709 | 1.64041666667 | 12148 |
| 012323 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:00am | Sensor | 1797-S0031-636-G-DTE | 6807.6 | 1593991.6 | 510113.1 | 36711 | 1.64041666667 | 12323 |
| 012579 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:01am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593988.7 | 510111.1 | 36713 | 1.64041666667 | 12579 |
| 012573 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:02am | Sensor | 1797-S0031-636-G-DTE | 6807.8 | 1593986.4 | 510110.0 | 36715 | 1.64041666667 | 12573 |
| 011857 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:03am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593984.0 | 510108.2 | 36717 | 1.64041666667 | 11857 |
| 011890 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:04am | Sensor | 1797-S0031-636-G-DTE | 6807.7 | 1593981.9 | 510106.9 | 36719 | 1.64041666667 | 11890 |
| 011765 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:05am | Sensor | 1797-S0031-636-G-DTE | 6807.5 | 1593978.8 | 510105.1 | 36721 | 1.64041666667 | 11765 |
| 011748 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:06am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593976.9 | 510103.4 | 36723 | 1.64041666667 | 11748 |
| 012750 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:07am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593974.3 | 510102.0 | 36725 | 1.64041666667 | 12750 |
| 012482 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:08am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593972.2 | 510100.7 | 36727 | 1.64041666667 | 12482 |
| 013036 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:09am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593969.8 | 510099.7 | 36729 | 1.64041666667 | 13036 |
| 012417 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:10am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593967.6 | 510098.4 | 36731 | 1.64041666667 | 12417 |
| 011290 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:11am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593965.0 | 510097.5 | 36733 | 1.64041666667 | 11290 |
| 011495 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:12am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593962.2 | 510097.0 | 36735 | 1.64041666667 | 11495 |
| 011596 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:13am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593959.4 | 510096.5 | 36737 | 1.64041666667 | 11596 |
| 011495 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:14am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593957.0 | 510096.3 | 36739 | 1.64041666667 | 11495 |
| 011731 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:15am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593953.6 | 510095.2 | 36741 | 1.64041666667 | 11731 |
| 012373 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:16am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593951.1 | 510094.6 | 36743 | 1.64041666667 | 12373 |
| 012877 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:17am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593948.2 | 510093.5 | 36745 | 1.64041666667 | 12877 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:18am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593946.0 | 510093.0 | 36747 | 1.64041666667 | 13453 |
| 012435 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:19am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593943.1 | 510092.0 | 36749 | 1.64041666667 | 12435 |
| 012649 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:20am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593940.5 | 510091.6 | 36751 | 1.64041666667 | 12649 |
| 012058 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:21am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593937.6 | 510091.3 | 36753 | 1.64041666667 | 12058 |
| 011657 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:22am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593934.9 | 510091.1 | 36755 | 1.64041666667 | 11657 |
| 011335 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:23am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593931.7 | 510091.4 | 36757 | 1.64041666667 | 11335 |
| 011325 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:24am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593929.1 | 510091.6 | 36759 | 1.64041666667 | 11325 |
| 011531 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:25am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593926.2 | 510091.3 | 36761 | 1.64041666667 | 11531 |
| 011256 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:26am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593924.4 | 510089.5 | 36763 | 1.64041666667 | 11256 |
| 012474 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:27am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593922.3 | 510087.4 | 36765 | 1.64041666667 | 12474 |
| 012461 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:28am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593921.0 | 510085.4 | 36767 | 1.64041666667 | 12461 |
| 013137 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:29am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593918.9 | 510083.5 | 36769 | 1.64041666667 | 13137 |
| 012632 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:30am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593916.7 | 510081.5 | 36771 | 1.64041666667 | 12632 |
| 012715 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:31am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593914.2 | 510079.7 | 36773 | 1.64041666667 | 12715 |
| 012042 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:32am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593912.3 | 510078.4 | 36775 | 1.64041666667 | 12042 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011521 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:33am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593910.0 | 510077.1 | 36777 | 1.64041666667 | 11521 |
| 011745 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:34am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593907.9 | 510075.7 | 36779 | 1.64041666667 | 11745 |
| 011992 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:35am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593906.0 | 510073.7 | 36781 | 1.64041666667 | 11992 |
| 011290 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:36am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593904.4 | 510071.5 | 36783 | 1.64041666667 | 11290 |
| 011721 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:37am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593904.0 | 510068.7 | 36785 | 1.64041666667 | 11721 |
| 011895 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:38am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593903.5 | 510066.7 | 36787 | 1.64041666667 | 11895 |
| 012556 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:39am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593902.9 | 510065.6 | 36789 | 1.64041666667 | 12556 |
| 011997 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:40am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593902.9 | 510065.5 | 36791 | 1.64041666667 | 11997 |
| 012156 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:41am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593903.2 | 510065.6 | 36793 | 1.64041666667 | 12156 |
| 011803 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:42am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593904.4 | 510065.3 | 36795 | 1.64041666667 | 11803 |
| 012069 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:43am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593906.4 | 510064.2 | 36797 | 1.64041666667 | 12069 |
| 012428 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:44am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593908.4 | 510064.0 | 36799 | 1.64041666667 | 12428 |
| 012181 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:45am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593911.4 | 510064.4 | 36801 | 1.64041666667 | 12181 |
| 013046 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:46am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593913.6 | 510065.4 | 36803 | 1.64041666667 | 13046 |
| 012588 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:47am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593916.1 | 510066.8 | 36805 | 1.64041666667 | 12588 |
| 012593 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:48am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593918.3 | 510067.8 | 36807 | 1.64041666667 | 12593 |
| 012386 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:49am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593920.8 | 510069.1 | 36809 | 1.64041666667 | 12386 |
| 012682 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:50am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593923.1 | 510070.1 | 36811 | 1.64041666667 | 12682 |
| 012563 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:51am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593925.7 | 510071.5 | 36813 | 1.64041666667 | 12563 |
| 012489 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:52am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593926.7 | 510072.1 | 36815 | 1.64041666667 | 12489 |
| 012005 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:53am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593927.0 | 510072.0 | 36817 | 1.64041666667 | 12005 |
| 012213 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:54am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593927.0 | 510071.9 | 36819 | 1.64041666667 | 12213 |
| 011625 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:55am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593927.2 | 510071.7 | 36821 | 1.64041666667 | 11625 |
| 012794 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:56am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593927.3 | 510071.6 | 36823 | 1.64041666667 | 12794 |
| 012671 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:57am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593927.1 | 510071.9 | 36825 | 1.64041666667 | 12671 |
| 012797 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:58am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593927.5 | 510072.3 | 36827 | 1.64041666667 | 12797 |
| 013933 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:59am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593929.2 | 510073.1 | 36829 | 1.64041666667 | 13933 |
| 012727 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:00am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593931.2 | 510074.2 | 36831 | 1.64041666667 | 12727 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:01am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593933.5 | 510076.0 | 36833 | 1.64041666667 | 12236 |
| 011263 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:02am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593935.4 | 510077.4 | 36835 | 1.64041666667 | 11263 |
| 011668 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:03am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593937.9 | 510079.1 | 36837 | 1.64041666667 | 11668 |
| 012690 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:04am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593939.3 | 510079.7 | 36839 | 1.64041666667 | 12690 |
| 012051 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:05am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593939.5 | 510079.5 | 36841 | 1.64041666667 | 12051 |
| 012066 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:06am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593938.8 | 510080.8 | 36843 | 1.64041666667 | 12066 |
| 012360 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:07am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593937.6 | 510082.6 | 36845 | 1.64041666667 | 12360 |
| 012225 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:08am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593936.3 | 510084.3 | 36847 | 1.64041666667 | 12225 |
| 012366 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:09am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593935.8 | 510085.6 | 36849 | 1.64041666667 | 12366 |
| 011816 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:10am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593937.3 | 510086.3 | 36851 | 1.64041666667 | 11816 |
| 011896 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:11am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593940.2 | 510086.1 | 36853 | 1.64041666667 | 11896 |
| 011679 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:12am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1593942.7 | 510086.5 | 36855 | 1.64041666667 | 11679 |
| 012142 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:13am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593945.5 | 510086.7 | 36857 | 1.64041666667 | 12142 |
| 012395 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:14am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593948.3 | 510086.7 | 36859 | 1.64041666667 | 12395 |
| 011719 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:15am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593951.2 | 510086.5 | 36861 | 1.64041666667 | 11719 |
| 010950 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:16am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593954.2 | 510086.3 | 36863 | 1.64041666667 | 10950 |
| 012031 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:17am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593957.4 | 510086.6 | 36865 | 1.64041666667 | 12031 |
| 012002 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:18am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593959.9 | 510086.2 | 36867 | 1.64041666667 | 12002 |
| 011919 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:19am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593962.6 | 510086.5 | 36869 | 1.64041666667 | 11919 |
| 012082 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:20am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593964.7 | 510086.9 | 36871 | 1.64041666667 | 12082 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011618 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:21am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593967.7 | 510087.6 | 36873 | 1.64041666667 | 11618 |
| 011395 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:22am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593970.3 | 510088.2 | 36875 | 1.64041666667 | 11395 |
| 011382 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:23am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593973.0 | 510089.0 | 36877 | 1.64041666667 | 11382 |
| 012005 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:24am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593975.6 | 510090.1 | 36879 | 1.64041666667 | 12005 |
| 011965 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:25am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593978.2 | 510091.5 | 36881 | 1.64041666667 | 11965 |
| 011605 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:26am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593980.2 | 510092.8 | 36883 | 1.64041666667 | 11605 |
| 010728 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:27am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593982.9 | 510093.5 | 36885 | 1.64041666667 | 10728 |
| 011089 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:28am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593985.1 | 510094.2 | 36887 | 1.64041666667 | 11089 |
| 012545 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:29am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1593987.8 | 510095.1 | 36889 | 1.64041666667 | 12545 |
| 012119 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:30am | Sensor | 1797-S0031-636-G-DTE | 6807.1 | 1593990.0 | 510096.2 | 36891 | 1.64041666667 | 12119 |
| 012967 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:31am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1593992.7 | 510097.5 | 36893 | 1.64041666667 | 12967 |
| 012979 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:32am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593994.9 | 510098.7 | 36895 | 1.64041666667 | 12979 |
| 011568 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:33am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1593997.4 | 510099.7 | 36897 | 1.64041666667 | 11568 |
| 011494 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:34am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1593999.5 | 510100.5 | 36899 | 1.64041666667 | 11494 |
| 011430 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:35am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1594001.1 | 510101.4 | 36901 | 1.64041666667 | 11430 |
| 011694 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:36am | Sensor | 1797-S0031-636-G-DTE | 6807.4 | 1594001.7 | 510100.8 | 36903 | 1.64041666667 | 11694 |
| 011573 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:37am | Sensor | 1797-S0031-636-G-DTE | 6807.3 | 1594002.8 | 510098.9 | 36905 | 1.64041666667 | 11573 |
| 011392 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:38am | Sensor | 1797-S0031-636-G-DTE | 6807.2 | 1594002.7 | 510097.0 | 36907 | 1.64041666667 | 11392 |
| 011125 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:39am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1594002.3 | 510094.5 | 36909 | 1.64041666667 | 11125 |
| 011583 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:40am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1594002.3 | 510093.5 | 36911 | 1.64041666667 | 11583 |
| 011533 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:41am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1594002.1 | 510093.6 | 36913 | 1.64041666667 | 11533 |
| 011700 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:42am | Sensor | 1797-S0031-636-G-DTE | 6807.0 | 1594001.8 | 510093.8 | 36915 | 1.64041666667 | 11700 |
| 011516 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:43am | Sensor | 1797-S0031-636-G-DTE | 6806.9 | 1594000.8 | 510093.0 | 36917 | 1.64041666667 | 11516 |
| 012050 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:44am | Sensor | 1797-S0031-636-G-DTE | 6806.8 | 1593999.0 | 510092.2 | 36919 | 1.64041666667 | 12050 |
| 011863 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:45am | Sensor | 1797-S0031-636-G-DTE | 6806.7 | 1593996.2 | 510090.6 | 36921 | 1.64041666667 | 11863 |
| 011870 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:46am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593993.9 | 510089.4 | 36923 | 1.64041666667 | 11870 |
| 012699 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:47am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593991.2 | 510088.3 | 36925 | 1.64041666667 | 12699 |
| 011898 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:48am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593988.5 | 510086.6 | 36927 | 1.64041666667 | 11898 |
| 011125 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:49am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593985.8 | 510085.1 | 36929 | 1.64041666667 | 11125 |
| 011658 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:50am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593983.7 | 510083.7 | 36931 | 1.64041666667 | 11658 |
| 011822 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:51am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593981.0 | 510082.8 | 36933 | 1.64041666667 | 11822 |
| 011952 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:52am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593978.3 | 510082.0 | 36935 | 1.64041666667 | 11952 |
| 011876 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:53am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593975.6 | 510081.0 | 36937 | 1.64041666667 | 11876 |
| 011382 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:54am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593973.6 | 510080.2 | 36939 | 1.64041666667 | 11382 |
| 011727 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:55am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593970.9 | 510079.1 | 36941 | 1.64041666667 | 11727 |
| 011329 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:56am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593969.1 | 510077.7 | 36943 | 1.64041666667 | 11329 |
| 011307 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:57am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593966.9 | 510076.2 | 36945 | 1.64041666667 | 11307 |
| 011760 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:58am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593965.2 | 510074.5 | 36947 | 1.64041666667 | 11760 |
| 011580 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:59am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593963.0 | 510072.9 | 36949 | 1.64041666667 | 11580 |
| 011373 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:00am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593960.9 | 510071.4 | 36951 | 1.64041666667 | 11373 |
| 011602 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:01am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593958.7 | 510070.3 | 36953 | 1.64041666667 | 11602 |
| 011941 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:02am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593956.5 | 510069.6 | 36955 | 1.64041666667 | 11941 |
| 012927 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:03am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593953.8 | 510069.3 | 36957 | 1.64041666667 | 12927 |
| 012941 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:04am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593951.4 | 510069.4 | 36959 | 1.64041666667 | 12941 |
| 012244 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:05am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593948.8 | 510069.3 | 36961 | 1.64041666667 | 12244 |
| 012977 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:06am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593946.1 | 510069.3 | 36963 | 1.64041666667 | 12977 |
| 013135 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:07am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593943.5 | 510069.1 | 36965 | 1.64041666667 | 13135 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:08am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593941.3 | 510068.7 | 36967 | 1.64041666667 | 13050 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012996 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:09am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593938.9 | 510068.1 | 36969 | 1.64041666667 | 12996 |
| 012057 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:10am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593936.7 | 510067.3 | 36971 | 1.64041666667 | 12057 |
| 012175 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:11am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593934.3 | 510066.1 | 36973 | 1.64041666667 | 12175 |
| 012196 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:12am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593931.5 | 510065.0 | 36975 | 1.64041666667 | 12196 |
| 011945 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:13am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593928.7 | 510063.7 | 36977 | 1.64041666667 | 11945 |
| 011279 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:14am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593926.2 | 510062.8 | 36979 | 1.64041666667 | 11279 |
| 011264 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:15am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593923.8 | 510061.7 | 36981 | 1.64041666667 | 11264 |
| 012254 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:16am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593921.4 | 510060.7 | 36983 | 1.64041666667 | 12254 |
| 012517 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:17am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593918.7 | 510059.4 | 36985 | 1.64041666667 | 12517 |
| 012981 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:18am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593916.7 | 510058.5 | 36987 | 1.64041666667 | 12981 |
| 013092 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:19am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593914.3 | 510057.1 | 36989 | 1.64041666667 | 13092 |
| 013454 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:20am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593912.0 | 510056.4 | 36991 | 1.64041666667 | 13454 |
| 013028 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:21am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593910.2 | 510055.6 | 36993 | 1.64041666667 | 13028 |
| 012135 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:22am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593908.6 | 510054.8 | 36995 | 1.64041666667 | 12135 |
| 012548 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:23am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593908.3 | 510053.7 | 36997 | 1.64041666667 | 12548 |
| 012001 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:24am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593908.9 | 510051.9 | 36999 | 1.64041666667 | 12001 |
| 011700 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:25am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593909.7 | 510049.4 | 37001 | 1.64041666667 | 11700 |
| 011989 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:26am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593910.5 | 510047.8 | 37003 | 1.64041666667 | 11989 |
| 011828 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:27am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593911.8 | 510047.0 | 37005 | 1.64041666667 | 11828 |
| 012616 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:28am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593913.9 | 510047.4 | 37007 | 1.64041666667 | 12616 |
| 012204 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:29am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593916.5 | 510048.2 | 37009 | 1.64041666667 | 12204 |
| 012684 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:30am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593918.4 | 510049.1 | 37011 | 1.64041666667 | 12684 |
| 011837 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:31am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593921.0 | 510049.9 | 37013 | 1.64041666667 | 11837 |
| 011473 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:32am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593923.2 | 510050.5 | 37015 | 1.64041666667 | 11473 |
| 011981 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:33am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593925.7 | 510051.7 | 37017 | 1.64041666667 | 11981 |
| 012214 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:34am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593927.4 | 510053.0 | 37019 | 1.64041666667 | 12214 |
| 012225 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:35am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593929.5 | 510054.7 | 37021 | 1.64041666667 | 12225 |
| 012449 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:36am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593931.5 | 510055.8 | 37023 | 1.64041666667 | 12449 |
| 012942 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:37am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593934.3 | 510057.4 | 37025 | 1.64041666667 | 12942 |
| 013445 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:38am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593936.8 | 510058.7 | 37027 | 1.64041666667 | 13445 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:39am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593939.5 | 510059.8 | 37029 | 1.64041666667 | 13038 |
| 012779 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:40am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593941.7 | 510060.5 | 37031 | 1.64041666667 | 12779 |
| 012468 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:41am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593944.6 | 510061.7 | 37033 | 1.64041666667 | 12468 |
| 012210 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:42am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593946.9 | 510062.3 | 37035 | 1.64041666667 | 12210 |
| 012268 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:43am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593949.7 | 510063.4 | 37037 | 1.64041666667 | 12268 |
| 012076 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:44am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593951.8 | 510063.8 | 37039 | 1.64041666667 | 12076 |
| 011750 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:45am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593954.5 | 510064.0 | 37041 | 1.64041666667 | 11750 |
| 011724 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:46am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593956.9 | 510064.3 | 37043 | 1.64041666667 | 11724 |
| 011672 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:47am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593959.8 | 510065.3 | 37045 | 1.64041666667 | 11672 |
| 012258 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:48am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593962.5 | 510066.0 | 37047 | 1.64041666667 | 12258 |
| 011995 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:49am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593965.2 | 510066.9 | 37049 | 1.64041666667 | 11995 |
| 011352 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:50am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593967.3 | 510067.7 | 37051 | 1.64041666667 | 11352 |
| 010968 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:51am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593970.2 | 510068.5 | 37053 | 1.64041666667 | 10968 |
| 010954 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:52am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593972.6 | 510069.0 | 37055 | 1.64041666667 | 10954 |
| 011292 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:53am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593975.2 | 510069.9 | 37057 | 1.64041666667 | 11292 |
| 011009 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:54am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593977.4 | 510070.7 | 37059 | 1.64041666667 | 11009 |
| 011120 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:55am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593979.9 | 510071.9 | 37061 | 1.64041666667 | 11120 |
| 011475 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:56am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593982.2 | 510073.1 | 37063 | 1.64041666667 | 11475 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011494 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:57am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593984.6 | 510074.5 | 37065 | 1.64041666667 | 11494 |
| 011475 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:58am | Sensor | 1797-S0031-636-G-DTE | 6806.6 | 1593986.6 | 510075.5 | 37067 | 1.64041666667 | 11475 |
| 011870 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:59am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593988.9 | 510076.5 | 37069 | 1.64041666667 | 11870 |
| 012234 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:00am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593990.8 | 510077.4 | 37071 | 1.64041666667 | 12234 |
| 011359 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:01am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1593993.1 | 510078.4 | 37073 | 1.64041666667 | 11359 |
| 011429 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:02am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593995.3 | 510079.2 | 37075 | 1.64041666667 | 11429 |
| 011431 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:03am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1593998.0 | 510079.6 | 37077 | 1.64041666667 | 11431 |
| 012520 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:04am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594000.0 | 510080.3 | 37079 | 1.64041666667 | 12520 |
| 011647 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:05am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594002.3 | 510081.3 | 37081 | 1.64041666667 | 11647 |
| 012244 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:06am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1594004.3 | 510082.2 | 37083 | 1.64041666667 | 12244 |
| 011695 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:07am | Sensor | 1797-S0031-636-G-DTE | 6806.5 | 1594006.8 | 510082.7 | 37085 | 1.64041666667 | 11695 |
| 011723 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:08am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594009.1 | 510083.0 | 37087 | 1.64041666667 | 11723 |
| 011567 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:09am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594011.6 | 510084.0 | 37089 | 1.64041666667 | 11567 |
| 012363 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:10am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594013.6 | 510084.9 | 37091 | 1.64041666667 | 12363 |
| 011582 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:11am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1594016.0 | 510085.7 | 37093 | 1.64041666667 | 11582 |
| 011360 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:12am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1594018.0 | 510085.0 | 37095 | 1.64041666667 | 11360 |
| 010792 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:13am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594019.9 | 510083.0 | 37097 | 1.64041666667 | 10792 |
| 011005 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:14am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594020.0 | 510081.4 | 37099 | 1.64041666667 | 11005 |
| 011943 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:15am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594018.4 | 510079.2 | 37101 | 1.64041666667 | 11943 |
| 011338 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:16am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594016.2 | 510077.8 | 37103 | 1.64041666667 | 11338 |
| 011432 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:17am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594013.3 | 510076.7 | 37105 | 1.64041666667 | 11432 |
| 011133 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:18am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594011.2 | 510075.6 | 37107 | 1.64041666667 | 11133 |
| 011257 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:19am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594009.3 | 510074.1 | 37109 | 1.64041666667 | 11257 |
| 012677 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:20am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594007.5 | 510072.9 | 37111 | 1.64041666667 | 12677 |
| 011653 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:21am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594005.1 | 510071.4 | 37113 | 1.64041666667 | 11653 |
| 011505 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:22am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594003.2 | 510070.3 | 37115 | 1.64041666667 | 11505 |
| 011189 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:23am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594000.7 | 510069.4 | 37117 | 1.64041666667 | 11189 |
| 011438 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:24am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593999.1 | 510068.7 | 37119 | 1.64041666667 | 11438 |
| 011309 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:25am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593996.5 | 510068.4 | 37121 | 1.64041666667 | 11309 |
| 011079 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:26am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593994.1 | 510068.2 | 37123 | 1.64041666667 | 11079 |
| 011669 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:27am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593991.5 | 510067.7 | 37125 | 1.64041666667 | 11669 |
| 012076 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:28am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593989.5 | 510067.0 | 37127 | 1.64041666667 | 12076 |
| 013835 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:29am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593987.0 | 510066.3 | 37129 | 1.64041666667 | 13835 |
| 014292 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:30am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.6 | 510065.8 | 37131 | 1.64041666667 | 14292 |
| 014467 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:31am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.1 | 510065.6 | 37133 | 1.64041666667 | 14467 |
| 016102 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:32am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.2 | 510065.8 | 37135 | 1.64041666667 | 16102 |
| 016985 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:33am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.4 | 510065.6 | 37137 | 1.64041666667 | 16985 |
| 016379 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:34am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.6 | 510065.4 | 37139 | 1.64041666667 | 16379 |
| 016968 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:35am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593985.6 | 510065.3 | 37141 | 1.64041666667 | 16968 |
| 018387 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:36am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593985.7 | 510065.4 | 37143 | 1.64041666667 | 18387 |
| 018255 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:37am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.5 | 510066.0 | 37145 | 1.64041666667 | 18255 |
| 018271 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:38am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.4 | 510066.3 | 37147 | 1.64041666667 | 18271 |
| 019375 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:39am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.5 | 510066.2 | 37149 | 1.64041666667 | 19375 |
| 019651 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:40am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.5 | 510066.2 | 37151 | 1.64041666667 | 19651 |
| 017811 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:41am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.5 | 510066.2 | 37153 | 1.64041666667 | 17811 |
| 018223 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:42am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.5 | 510066.2 | 37155 | 1.64041666667 | 18223 |
| 018088 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:43am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.5 | 510066.2 | 37157 | 1.64041666667 | 18088 |
| 017434 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:44am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.5 | 510066.1 | 37159 | 1.64041666667 | 17434 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017134 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:45am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.5 | 510066.1 | 37161 | 1.64041666667 | 17134 |
| 017051 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:46am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.4 | 510066.1 | 37163 | 1.64041666667 | 17051 |
| 018338 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:47am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.4 | 510066.1 | 37165 | 1.64041666667 | 18338 |
| 019435 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:48am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593985.4 | 510066.1 | 37167 | 1.64041666667 | 19435 |
| 020089 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:49am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.5 | 510066.1 | 37169 | 1.64041666667 | 20089 |
| 019325 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:50am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.5 | 510066.1 | 37171 | 1.64041666667 | 19325 |
| 018625 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:51am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.5 | 510066.1 | 37173 | 1.64041666667 | 18625 |
| 017399 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:52am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.5 | 510066.1 | 37175 | 1.64041666667 | 17399 |
| 017789 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:53am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.5 | 510066.1 | 37177 | 1.64041666667 | 17789 |
| 018241 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:54am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.5 | 510066.1 | 37179 | 1.64041666667 | 18241 |
| 018015 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:55am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593985.6 | 510066.1 | 37181 | 1.64041666667 | 18015 |
| 018151 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:56am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593985.7 | 510065.8 | 37183 | 1.64041666667 | 18151 |
| 018902 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:57am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593985.7 | 510064.9 | 37185 | 1.64041666667 | 18902 |
| 018410 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:58am | Sensor | 1797-S0031-636-G-DTE | 6804.8 | 1593985.5 | 510064.1 | 37187 | 1.64041666667 | 18410 |
| 018215 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:59am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593985.4 | 510064.4 | 37189 | 1.64041666667 | 18215 |
| 018339 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:00am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593984.6 | 510065.0 | 37191 | 1.64041666667 | 18339 |
| 017275 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:01am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593982.8 | 510064.7 | 37193 | 1.64041666667 | 17275 |
| 015545 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:02am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593981.1 | 510063.9 | 37195 | 1.64041666667 | 15545 |
| 014361 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:03am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593978.5 | 510062.7 | 37197 | 1.64041666667 | 14361 |
| 013553 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:04am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593976.0 | 510062.0 | 37199 | 1.64041666667 | 13553 |
| 013233 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:05am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593972.8 | 510061.8 | 37201 | 1.64041666667 | 13233 |
| 012506 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:06am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593970.1 | 510060.9 | 37203 | 1.64041666667 | 12506 |
| 012007 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:07am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593967.0 | 510060.3 | 37205 | 1.64041666667 | 12007 |
| 011891 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:08am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593964.4 | 510059.9 | 37207 | 1.64041666667 | 11891 |
| 011496 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:09am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593961.0 | 510059.6 | 37209 | 1.64041666667 | 11496 |
| 012012 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:10am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593958.1 | 510059.3 | 37211 | 1.64041666667 | 12012 |
| 011399 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:11am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593955.3 | 510058.2 | 37213 | 1.64041666667 | 11399 |
| 012097 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:12am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593952.6 | 510057.5 | 37215 | 1.64041666667 | 12097 |
| 010869 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:13am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593949.6 | 510056.6 | 37217 | 1.64041666667 | 10869 |
| 011086 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:14am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593946.9 | 510056.0 | 37219 | 1.64041666667 | 11086 |
| 012288 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:15am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593943.9 | 510055.4 | 37221 | 1.64041666667 | 12288 |
| 013114 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:16am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593941.5 | 510055.3 | 37223 | 1.64041666667 | 13114 |
| 014224 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:17am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593939.0 | 510055.4 | 37225 | 1.64041666667 | 14224 |
| 013896 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:18am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593936.8 | 510054.6 | 37227 | 1.64041666667 | 13896 |
| 013441 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:19am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593934.8 | 510053.6 | 37229 | 1.64041666667 | 13441 |
| 013470 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:20am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593932.8 | 510051.6 | 37231 | 1.64041666667 | 13470 |
| 013090 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:21am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593930.0 | 510050.0 | 37233 | 1.64041666667 | 13090 |
| 012875 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:22am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593928.0 | 510048.7 | 37235 | 1.64041666667 | 12875 |
| 012642 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:23am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593925.6 | 510047.2 | 37237 | 1.64041666667 | 12642 |
| 011986 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:24am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593923.5 | 510046.1 | 37239 | 1.64041666667 | 11986 |
| 011677 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:25am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593921.0 | 510044.2 | 37241 | 1.64041666667 | 11677 |
| 012786 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:26am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593919.3 | 510042.7 | 37243 | 1.64041666667 | 12786 |
| 012374 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:27am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593917.2 | 510041.2 | 37245 | 1.64041666667 | 12374 |
| 013410 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:28am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593915.5 | 510040.0 | 37247 | 1.64041666667 | 13410 |
| 012561 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:29am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593913.6 | 510038.3 | 37249 | 1.64041666667 | 12561 |
| 012623 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:30am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593911.9 | 510036.7 | 37251 | 1.64041666667 | 12623 |
| 012815 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:31am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593910.5 | 510035.1 | 37253 | 1.64041666667 | 12815 |
| 013343 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:32am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593909.3 | 510033.7 | 37255 | 1.64041666667 | 13343 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013348 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:33am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593909.2 | 510031.4 | 37257 | 1.64041666667 | 13348 |
| 012826 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:34am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593909.9 | 510029.4 | 37259 | 1.64041666667 | 12826 |
| 011969 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:35am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593910.8 | 510027.5 | 37261 | 1.64041666667 | 11969 |
| 012928 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:36am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593911.1 | 510027.0 | 37263 | 1.64041666667 | 12928 |
| 013196 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:37am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593911.4 | 510027.0 | 37265 | 1.64041666667 | 13196 |
| 013093 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:38am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593911.4 | 510026.9 | 37267 | 1.64041666667 | 13093 |
| 012847 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:39am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593911.2 | 510026.8 | 37269 | 1.64041666667 | 12847 |
| 012859 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:40am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593911.4 | 510026.7 | 37271 | 1.64041666667 | 12859 |
| 012243 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:41am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593911.9 | 510026.0 | 37273 | 1.64041666667 | 12243 |
| 012024 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:42am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593912.6 | 510025.1 | 37275 | 1.64041666667 | 12024 |
| 012171 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:43am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593914.1 | 510024.2 | 37277 | 1.64041666667 | 12171 |
| 012509 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:44am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593915.4 | 510024.2 | 37279 | 1.64041666667 | 12509 |
| 011933 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:45am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593917.0 | 510024.8 | 37281 | 1.64041666667 | 11933 |
| 012547 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:46am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593918.9 | 510025.7 | 37283 | 1.64041666667 | 12547 |
| 012330 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:47am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593920.8 | 510026.9 | 37285 | 1.64041666667 | 12330 |
| 012051 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:48am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593922.3 | 510028.1 | 37287 | 1.64041666667 | 12051 |
| 012508 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:49am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593922.7 | 510030.1 | 37289 | 1.64041666667 | 12508 |
| 012616 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:50am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593922.3 | 510032.0 | 37291 | 1.64041666667 | 12616 |
| 014124 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:51am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593921.3 | 510034.0 | 37293 | 1.64041666667 | 14124 |
| 012879 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:52am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593921.5 | 510036.1 | 37295 | 1.64041666667 | 12879 |
| 012930 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:53am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593922.9 | 510037.6 | 37297 | 1.64041666667 | 12930 |
| 012950 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:54am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593925.7 | 510038.2 | 37299 | 1.64041666667 | 12950 |
| 012722 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:55am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593928.4 | 510039.0 | 37301 | 1.64041666667 | 12722 |
| 012586 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:56am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593931.0 | 510040.5 | 37303 | 1.64041666667 | 12586 |
| 012404 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:57am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593934.2 | 510042.0 | 37305 | 1.64041666667 | 12404 |
| 012820 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:58am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593936.5 | 510043.5 | 37307 | 1.64041666667 | 12820 |
| 012663 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:59am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593939.2 | 510044.7 | 37309 | 1.64041666667 | 12663 |
| 013153 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:00am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593941.4 | 510045.9 | 37311 | 1.64041666667 | 13153 |
| 012911 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:01am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593944.1 | 510047.3 | 37313 | 1.64041666667 | 12911 |
| 012002 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:02am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593946.4 | 510048.1 | 37315 | 1.64041666667 | 12002 |
| 012009 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:03am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593949.5 | 510049.2 | 37317 | 1.64041666667 | 12009 |
| 012725 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:04am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593952.1 | 510049.5 | 37319 | 1.64041666667 | 12725 |
| 012505 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:05am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593955.1 | 510050.2 | 37321 | 1.64041666667 | 12505 |
| 013274 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:06am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593957.6 | 510050.5 | 37323 | 1.64041666667 | 13274 |
| 012281 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:07am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593960.2 | 510051.1 | 37325 | 1.64041666667 | 12281 |
| 012278 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:08am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593962.5 | 510052.1 | 37327 | 1.64041666667 | 12278 |
| 011676 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:09am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593965.5 | 510052.1 | 37329 | 1.64041666667 | 11676 |
| 012080 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:10am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593967.9 | 510052.3 | 37331 | 1.64041666667 | 12080 |
| 013147 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:11am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593971.1 | 510052.6 | 37333 | 1.64041666667 | 13147 |
| 012398 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:12am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593973.6 | 510053.1 | 37335 | 1.64041666667 | 12398 |
| 012321 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:13am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593976.3 | 510053.6 | 37337 | 1.64041666667 | 12321 |
| 012023 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:14am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593978.5 | 510053.7 | 37339 | 1.64041666667 | 12023 |
| 012305 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:15am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593981.3 | 510055.1 | 37341 | 1.64041666667 | 12305 |
| 011917 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:16am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593983.8 | 510055.5 | 37343 | 1.64041666667 | 11917 |
| 012005 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:17am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593987.1 | 510056.3 | 37345 | 1.64041666667 | 12005 |
| 011831 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:18am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593989.6 | 510056.9 | 37347 | 1.64041666667 | 11831 |
| 011417 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:19am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593992.7 | 510057.5 | 37349 | 1.64041666667 | 11417 |
| 012099 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:20am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593994.9 | 510058.2 | 37351 | 1.64041666667 | 12099 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011951 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:21am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593997.8 | 510058.9 | 37353 | 1.64041666667 | 11951 |
| 013075 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:22am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593999.9 | 510060.3 | 37355 | 1.64041666667 | 13075 |
| 012664 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:23am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594002.4 | 510062.0 | 37357 | 1.64041666667 | 12664 |
| 012486 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:24am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594004.7 | 510063.3 | 37359 | 1.64041666667 | 12486 |
| 012348 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:25am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594007.4 | 510064.2 | 37361 | 1.64041666667 | 12348 |
| 011446 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:26am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594009.9 | 510065.4 | 37363 | 1.64041666667 | 11446 |
| 011478 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:27am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594012.8 | 510067.1 | 37365 | 1.64041666667 | 11478 |
| 011571 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:28am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594015.1 | 510068.1 | 37367 | 1.64041666667 | 11571 |
| 012336 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:29am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594018.2 | 510069.2 | 37369 | 1.64041666667 | 12336 |
| 011521 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:30am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1594020.6 | 510068.5 | 37371 | 1.64041666667 | 11521 |
| 012661 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:31am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1594022.3 | 510066.4 | 37373 | 1.64041666667 | 12661 |
| 012379 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:32am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594022.7 | 510064.2 | 37375 | 1.64041666667 | 12379 |
| 011943 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:33am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594020.7 | 510061.3 | 37377 | 1.64041666667 | 11943 |
| 012538 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:34am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594018.5 | 510059.8 | 37379 | 1.64041666667 | 12538 |
| 011462 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:35am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594015.6 | 510058.3 | 37381 | 1.64041666667 | 11462 |
| 011180 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:36am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1594013.2 | 510056.6 | 37383 | 1.64041666667 | 11180 |
| 011148 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:37am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1594010.1 | 510055.1 | 37385 | 1.64041666667 | 11148 |
| 011026 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:38am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1594008.1 | 510053.6 | 37387 | 1.64041666667 | 11026 |
| 011940 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:39am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1594005.4 | 510051.9 | 37389 | 1.64041666667 | 11940 |
| 012213 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:40am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1594002.6 | 510050.6 | 37391 | 1.64041666667 | 12213 |
| 011422 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:41am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594000.0 | 510049.9 | 37393 | 1.64041666667 | 11422 |
| 011870 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:42am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593997.7 | 510049.3 | 37395 | 1.64041666667 | 11870 |
| 012272 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:43am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593994.7 | 510048.5 | 37397 | 1.64041666667 | 12272 |
| 011800 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:44am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593992.1 | 510047.7 | 37399 | 1.64041666667 | 11800 |
| 010950 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:45am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593989.5 | 510046.5 | 37401 | 1.64041666667 | 10950 |
| 010899 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:46am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593986.5 | 510045.6 | 37403 | 1.64041666667 | 10899 |
| 011411 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:47am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593983.5 | 510044.7 | 37405 | 1.64041666667 | 11411 |
| 011646 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:48am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593980.8 | 510044.2 | 37407 | 1.64041666667 | 11646 |
| 011561 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:49am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593977.7 | 510043.5 | 37409 | 1.64041666667 | 11561 |
| 012038 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:50am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593975.3 | 510042.6 | 37411 | 1.64041666667 | 12038 |
| 012051 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:51am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593972.0 | 510042.1 | 37413 | 1.64041666667 | 12051 |
| 013281 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:52am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593969.3 | 510041.8 | 37415 | 1.64041666667 | 13281 |
| 012893 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:53am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593966.6 | 510041.7 | 37417 | 1.64041666667 | 12893 |
| 012915 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:54am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593963.7 | 510041.4 | 37419 | 1.64041666667 | 12915 |
| 012259 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:55am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593960.9 | 510041.5 | 37421 | 1.64041666667 | 12259 |
| 011651 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:56am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593958.4 | 510041.2 | 37423 | 1.64041666667 | 11651 |
| 012516 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:57am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593956.2 | 510040.4 | 37425 | 1.64041666667 | 12516 |
| 013317 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:58am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593953.8 | 510038.8 | 37427 | 1.64041666667 | 13317 |
| 012336 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:59am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593951.1 | 510037.6 | 37429 | 1.64041666667 | 12336 |
| 011716 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:00am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593948.6 | 510036.8 | 37431 | 1.64041666667 | 11716 |
| 012463 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:01am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593945.4 | 510036.1 | 37433 | 1.64041666667 | 12463 |
| 013145 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:02am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593942.8 | 510036.0 | 37435 | 1.64041666667 | 13145 |
| 013506 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:03am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593939.8 | 510035.8 | 37437 | 1.64041666667 | 13506 |
| 014662 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:04am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593937.4 | 510035.9 | 37439 | 1.64041666667 | 14662 |
| 014180 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:05am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593934.3 | 510035.1 | 37441 | 1.64041666667 | 14180 |
| 014223 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:06am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593931.7 | 510034.7 | 37443 | 1.64041666667 | 14223 |
| 013663 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:07am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593928.9 | 510033.9 | 37445 | 1.64041666667 | 13663 |
| 012433 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:08am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593926.5 | 510033.4 | 37447 | 1.64041666667 | 12433 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012363 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:09am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593923.7 | 510032.1 | 37449 | 1.64041666667 | 12363 |
| 012587 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:10am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593921.4 | 510030.8 | 37451 | 1.64041666667 | 12587 |
| 012412 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:11am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593918.9 | 510029.3 | 37453 | 1.64041666667 | 12412 |
| 012427 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:12am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593917.1 | 510027.7 | 37455 | 1.64041666667 | 12427 |
| 013672 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:13am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593915.0 | 510026.6 | 37457 | 1.64041666667 | 13672 |
| 013001 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:14am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593913.0 | 510024.7 | 37459 | 1.64041666667 | 13001 |
| 013583 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:15am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593911.1 | 510023.2 | 37461 | 1.64041666667 | 13583 |
| 012890 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:16am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593910.6 | 510021.1 | 37463 | 1.64041666667 | 12890 |
| 012425 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:17am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593911.0 | 510019.2 | 37465 | 1.64041666667 | 12425 |
| 012254 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:18am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593912.1 | 510018.5 | 37467 | 1.64041666667 | 12254 |
| 011933 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:19am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593914.5 | 510018.2 | 37469 | 1.64041666667 | 11933 |
| 011400 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:20am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593916.9 | 510018.8 | 37471 | 1.64041666667 | 11400 |
| 012210 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:21am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593919.9 | 510018.9 | 37473 | 1.64041666667 | 12210 |
| 011983 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:22am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593922.5 | 510019.2 | 37475 | 1.64041666667 | 11983 |
| 011953 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:23am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593925.2 | 510020.4 | 37477 | 1.64041666667 | 11953 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:24am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593927.8 | 510021.2 | 37479 | 1.64041666667 | 13038 |
| 013529 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:25am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593930.6 | 510022.3 | 37481 | 1.64041666667 | 13529 |
| 013482 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:26am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593933.2 | 510023.1 | 37483 | 1.64041666667 | 13482 |
| 013501 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:27am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593936.2 | 510024.4 | 37485 | 1.64041666667 | 13501 |
| 013849 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:28am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593938.7 | 510025.5 | 37487 | 1.64041666667 | 13849 |
| 015155 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:29am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593941.9 | 510026.6 | 37489 | 1.64041666667 | 15155 |
| 015409 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:30am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593944.1 | 510027.7 | 37491 | 1.64041666667 | 15409 |
| 014510 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:31am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593947.0 | 510028.6 | 37493 | 1.64041666667 | 14510 |
| 014372 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:32am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593949.4 | 510029.7 | 37495 | 1.64041666667 | 14372 |
| 013154 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:33am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593952.4 | 510031.0 | 37497 | 1.64041666667 | 13154 |
| 013984 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:34am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593955.1 | 510031.9 | 37499 | 1.64041666667 | 13984 |
| 013138 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:35am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593958.0 | 510032.8 | 37501 | 1.64041666667 | 13138 |
| 013735 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:36am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593960.5 | 510033.1 | 37503 | 1.64041666667 | 13735 |
| 012901 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:37am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593963.7 | 510034.2 | 37505 | 1.64041666667 | 12901 |
| 012686 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:38am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593966.3 | 510034.5 | 37507 | 1.64041666667 | 12686 |
| 012618 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:39am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593969.3 | 510035.1 | 37509 | 1.64041666667 | 12618 |
| 012498 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:40am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593971.9 | 510036.1 | 37511 | 1.64041666667 | 12498 |
| 012557 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:41am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593974.8 | 510037.4 | 37513 | 1.64041666667 | 12557 |
| 012658 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:42am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593977.2 | 510038.9 | 37515 | 1.64041666667 | 12658 |
| 012311 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:43am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593980.2 | 510039.5 | 37517 | 1.64041666667 | 12311 |
| 012512 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:44am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593982.8 | 510040.2 | 37519 | 1.64041666667 | 12512 |
| 012701 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:45am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593985.6 | 510041.1 | 37521 | 1.64041666667 | 12701 |
| 013099 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:46am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593988.6 | 510041.9 | 37523 | 1.64041666667 | 13099 |
| 012791 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:47am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593991.7 | 510042.8 | 37525 | 1.64041666667 | 12791 |
| 012460 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:48am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593994.7 | 510043.7 | 37527 | 1.64041666667 | 12460 |
| 011913 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:49am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593997.6 | 510044.7 | 37529 | 1.64041666667 | 11913 |
| 011658 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:50am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1594000.1 | 510044.9 | 37531 | 1.64041666667 | 11658 |
| 011500 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:51am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594003.2 | 510045.8 | 37533 | 1.64041666667 | 11500 |
| 011659 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:52am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594006.0 | 510046.7 | 37535 | 1.64041666667 | 11659 |
| 011418 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:53am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594008.4 | 510048.4 | 37537 | 1.64041666667 | 11418 |
| 010915 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:54am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594010.4 | 510049.4 | 37539 | 1.64041666667 | 10915 |
| 010924 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:55am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594013.7 | 510049.8 | 37541 | 1.64041666667 | 10924 |
| 011477 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:56am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594016.9 | 510050.0 | 37543 | 1.64041666667 | 11477 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011571 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:57am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1594020.0 | 510050.1 | 37545 | 1.64041666667 | 11571 |
| 011699 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:58am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594022.7 | 510050.7 | 37547 | 1.64041666667 | 11699 |
| 011643 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:59am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594025.8 | 510050.5 | 37549 | 1.64041666667 | 11643 |
| 011334 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:00am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594028.1 | 510049.0 | 37551 | 1.64041666667 | 11334 |
| 011190 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:01am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594028.3 | 510046.2 | 37553 | 1.64041666667 | 11190 |
| 011259 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:02am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594027.0 | 510044.5 | 37555 | 1.64041666667 | 11259 |
| 011073 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:03am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594024.8 | 510042.7 | 37557 | 1.64041666667 | 11073 |
| 011171 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:04am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594022.4 | 510041.3 | 37559 | 1.64041666667 | 11171 |
| 011406 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:05am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594018.8 | 510040.2 | 37561 | 1.64041666667 | 11406 |
| 011261 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:06am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594016.3 | 510040.0 | 37563 | 1.64041666667 | 11261 |
| 011719 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:07am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594013.4 | 510039.3 | 37565 | 1.64041666667 | 11719 |
| 011497 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:08am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1594010.9 | 510038.5 | 37567 | 1.64041666667 | 11497 |
| 011604 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:09am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1594007.5 | 510036.2 | 37569 | 1.64041666667 | 11604 |
| 012602 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:10am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1594004.5 | 510035.0 | 37571 | 1.64041666667 | 12602 |
| 012766 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:11am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594001.2 | 510034.1 | 37573 | 1.64041666667 | 12766 |
| 012371 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:12am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593998.6 | 510032.5 | 37575 | 1.64041666667 | 12371 |
| 012411 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:13am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593995.4 | 510030.9 | 37577 | 1.64041666667 | 12411 |
| 011969 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:14am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593992.7 | 510029.6 | 37579 | 1.64041666667 | 11969 |
| 011885 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:15am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593989.7 | 510028.8 | 37581 | 1.64041666667 | 11885 |
| 011912 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:16am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593987.2 | 510028.4 | 37583 | 1.64041666667 | 11912 |
| 011058 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:17am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593984.1 | 510027.9 | 37585 | 1.64041666667 | 11058 |
| 011155 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:18am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593981.4 | 510027.3 | 37587 | 1.64041666667 | 11155 |
| 011532 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:19am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593978.5 | 510027.1 | 37589 | 1.64041666667 | 11532 |
| 011564 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:20am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593976.0 | 510026.8 | 37591 | 1.64041666667 | 11564 |
| 012302 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:21am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593973.1 | 510025.3 | 37593 | 1.64041666667 | 12302 |
| 012260 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:22am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593970.7 | 510024.1 | 37595 | 1.64041666667 | 12260 |
| 012581 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:23am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593967.6 | 510021.9 | 37597 | 1.64041666667 | 12581 |
| 012507 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:24am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593964.9 | 510020.9 | 37599 | 1.64041666667 | 12507 |
| 012907 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:25am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593962.1 | 510019.4 | 37601 | 1.64041666667 | 12907 |
| 012233 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:26am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593959.7 | 510018.0 | 37603 | 1.64041666667 | 12233 |
| 012168 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:27am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593956.6 | 510017.3 | 37605 | 1.64041666667 | 12168 |
| 012627 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:28am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593953.9 | 510016.9 | 37607 | 1.64041666667 | 12627 |
| 012907 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:29am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593951.1 | 510017.3 | 37609 | 1.64041666667 | 12907 |
| 013020 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:30am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593948.4 | 510016.9 | 37611 | 1.64041666667 | 13020 |
| 013286 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:31am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593945.3 | 510016.2 | 37613 | 1.64041666667 | 13286 |
| 012318 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:32am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593942.7 | 510015.4 | 37615 | 1.64041666667 | 12318 |
| 011534 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:33am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593939.6 | 510014.5 | 37617 | 1.64041666667 | 11534 |
| 010898 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:34am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593937.0 | 510013.9 | 37619 | 1.64041666667 | 10898 |
| 011185 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:35am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593934.3 | 510012.2 | 37621 | 1.64041666667 | 11185 |
| 011504 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:36am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593931.9 | 510010.9 | 37623 | 1.64041666667 | 11504 |
| 011931 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:37am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593929.3 | 510009.6 | 37625 | 1.64041666667 | 11931 |
| 012066 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:38am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593926.6 | 510008.9 | 37627 | 1.64041666667 | 12066 |
| 013004 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:39am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593924.7 | 510006.7 | 37629 | 1.64041666667 | 13004 |
| 012535 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:40am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593924.1 | 510004.2 | 37631 | 1.64041666667 | 12535 |
| 012923 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:41am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593924.7 | 510001.2 | 37633 | 1.64041666667 | 12923 |
| 013337 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:42am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593926.2 | 509998.4 | 37635 | 1.64041666667 | 13337 |
| 012107 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:43am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593927.3 | 509995.9 | 37637 | 1.64041666667 | 12107 |
| 012315 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:44am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593928.2 | 509994.1 | 37639 | 1.64041666667 | 12315 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012559 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:45am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593928.8 | 509993.6 | 37641 | 1.64041666667 | 12559 |
| 011655 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:46am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593928.7 | 509993.5 | 37643 | 1.64041666667 | 11655 |
| 011085 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:47am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593928.8 | 509993.6 | 37645 | 1.64041666667 | 11085 |
| 011621 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:48am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593928.8 | 509993.5 | 37647 | 1.64041666667 | 11621 |
| 012199 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:49am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593928.9 | 509993.4 | 37649 | 1.64041666667 | 12199 |
| 012044 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:50am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593928.7 | 509993.4 | 37651 | 1.64041666667 | 12044 |
| 011950 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:51am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593928.7 | 509993.7 | 37653 | 1.64041666667 | 11950 |
| 012054 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:52am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.9 | 509993.8 | 37655 | 1.64041666667 | 12054 |
| 012465 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:53am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593929.0 | 509993.8 | 37657 | 1.64041666667 | 12465 |
| 012314 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:54am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593929.0 | 509993.9 | 37659 | 1.64041666667 | 12314 |
| 012244 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:55am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593929.1 | 509993.8 | 37661 | 1.64041666667 | 12244 |
| 012332 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:56am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593929.0 | 509993.8 | 37663 | 1.64041666667 | 12332 |
| 012307 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:57am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593929.1 | 509993.7 | 37665 | 1.64041666667 | 12307 |
| 012030 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:58am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593929.1 | 509993.6 | 37667 | 1.64041666667 | 12030 |
| 012017 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:59am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593928.8 | 509993.5 | 37669 | 1.64041666667 | 12017 |
| 011942 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:00am | Sensor | 1797-S0031-636-G-DTE | 6805.2 | 1593928.6 | 509993.5 | 37671 | 1.64041666667 | 11942 |
| 011757 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:01am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.6 | 509993.5 | 37673 | 1.64041666667 | 11757 |
| 011788 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:02am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.6 | 509993.5 | 37675 | 1.64041666667 | 11788 |
| 012308 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:03am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.6 | 509993.6 | 37677 | 1.64041666667 | 12308 |
| 012143 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:04am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.7 | 509993.6 | 37679 | 1.64041666667 | 12143 |
| 012553 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:05am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.6 | 509993.7 | 37681 | 1.64041666667 | 12553 |
| 012626 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:06am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.7 | 509993.7 | 37683 | 1.64041666667 | 12626 |
| 012562 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:07am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593929.1 | 509993.6 | 37685 | 1.64041666667 | 12562 |
| 012496 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:08am | Sensor | 1797-S0031-636-G-DTE | 6804.6 | 1593930.1 | 509993.2 | 37687 | 1.64041666667 | 12496 |
| 012549 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:09am | Sensor | 1797-S0031-636-G-DTE | 6803.7 | 1593930.8 | 509993.0 | 37689 | 1.64041666667 | 12549 |
| 013313 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:10am | Sensor | 1797-S0031-636-G-DTE | 6804.3 | 1593930.1 | 509993.1 | 37691 | 1.64041666667 | 13313 |
| 012619 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:11am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.7 | 509993.4 | 37693 | 1.64041666667 | 12619 |
| 013323 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:12am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.4 | 509993.4 | 37695 | 1.64041666667 | 13323 |
| 013329 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:13am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.4 | 509993.3 | 37697 | 1.64041666667 | 13329 |
| 013092 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:14am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.5 | 509993.3 | 37699 | 1.64041666667 | 13092 |
| 013049 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:15am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593928.6 | 509993.5 | 37701 | 1.64041666667 | 13049 |
| 012410 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:16am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593929.1 | 509993.7 | 37703 | 1.64041666667 | 12410 |
| 011555 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:17am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593929.5 | 509993.8 | 37705 | 1.64041666667 | 11555 |
| 011967 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:18am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593929.3 | 509993.8 | 37707 | 1.64041666667 | 11967 |
| 013264 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:19am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593929.2 | 509993.7 | 37709 | 1.64041666667 | 13264 |
| 013033 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:20am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593929.1 | 509993.7 | 37711 | 1.64041666667 | 13033 |
| 012439 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:21am | Sensor | 1797-S0031-636-G-DTE | 6805.1 | 1593929.0 | 509993.6 | 37713 | 1.64041666667 | 12439 |
| 012907 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:22am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593928.9 | 509993.6 | 37715 | 1.64041666667 | 12907 |
| 012202 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:23am | Sensor | 1797-S0031-636-G-DTE | 6805.0 | 1593928.9 | 509993.6 | 37717 | 1.64041666667 | 12202 |
| 013950 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:05am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593927.5 | 509988.3 | 37719 | 1.64041666667 | 13950 |
| 012429 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:06am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593927.5 | 509988.3 | 37721 | 1.64041666667 | 12429 |
| 011626 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:07am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593927.7 | 509988.9 | 37723 | 1.64041666667 | 11626 |
| 011812 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:08am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593928.5 | 509990.4 | 37725 | 1.64041666667 | 11812 |
| 012329 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:09am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593929.4 | 509993.3 | 37727 | 1.64041666667 | 12329 |
| 012372 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:10am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593931.3 | 509995.0 | 37729 | 1.64041666667 | 12372 |
| 011189 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:11am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593934.0 | 509997.2 | 37731 | 1.64041666667 | 11189 |
| 011386 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:12am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593936.5 | 509998.8 | 37733 | 1.64041666667 | 11386 |
| 011550 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:13am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593939.8 | 509999.5 | 37735 | 1.64041666667 | 11550 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011289 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:14am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593942.0 | 510000.6 | 37737 | 1.64041666667 | 11289 |
| 011570 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:15am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593945.3 | 510001.9 | 37739 | 1.64041666667 | 11570 |
| 011270 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:16am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593948.0 | 510002.7 | 37741 | 1.64041666667 | 11270 |
| 012137 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:17am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593951.4 | 510004.8 | 37743 | 1.64041666667 | 12137 |
| 012669 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:18am | Sensor | 1797-S0031-636-G-DTE | 6805.4 | 1593954.5 | 510005.5 | 37745 | 1.64041666667 | 12669 |
| 011296 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:19am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593958.6 | 510006.9 | 37747 | 1.64041666667 | 11296 |
| 011022 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:20am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593961.6 | 510008.7 | 37749 | 1.64041666667 | 11022 |
| 011696 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:21am | Sensor | 1797-S0031-636-G-DTE | 6805.3 | 1593965.5 | 510010.4 | 37751 | 1.64041666667 | 11696 |
| 011761 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:22am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593969.0 | 510011.9 | 37753 | 1.64041666667 | 11761 |
| 012098 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:23am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593972.7 | 510014.4 | 37755 | 1.64041666667 | 12098 |
| 011958 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:24am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593974.9 | 510016.1 | 37757 | 1.64041666667 | 11958 |
| 012396 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:25am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593978.2 | 510018.3 | 37759 | 1.64041666667 | 12396 |
| 011563 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:26am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593981.5 | 510020.4 | 37761 | 1.64041666667 | 11563 |
| 012444 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:27am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593985.6 | 510022.4 | 37763 | 1.64041666667 | 12444 |
| 012303 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:28am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593989.0 | 510023.0 | 37765 | 1.64041666667 | 12303 |
| 011595 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:29am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593993.0 | 510024.0 | 37767 | 1.64041666667 | 11595 |
| 011247 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:30am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593995.5 | 510025.4 | 37769 | 1.64041666667 | 11247 |
| 011419 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:31am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593999.0 | 510026.9 | 37771 | 1.64041666667 | 11419 |
| 011590 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:32am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594002.1 | 510028.2 | 37773 | 1.64041666667 | 11590 |
| 011567 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:33am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594005.5 | 510030.1 | 37775 | 1.64041666667 | 11567 |
| 010984 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:34am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594008.1 | 510031.2 | 37777 | 1.64041666667 | 10984 |
| 011631 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:35am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594011.6 | 510032.3 | 37779 | 1.64041666667 | 11631 |
| 011785 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:36am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594014.3 | 510033.9 | 37781 | 1.64041666667 | 11785 |
| 011901 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:37am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594017.4 | 510036.1 | 37783 | 1.64041666667 | 11901 |
| 012057 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:38am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594019.9 | 510037.5 | 37785 | 1.64041666667 | 12057 |
| 012392 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:39am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594022.2 | 510039.7 | 37787 | 1.64041666667 | 12392 |
| 012468 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:40am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594024.3 | 510040.7 | 37789 | 1.64041666667 | 12468 |
| 011993 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:41am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594025.6 | 510040.5 | 37791 | 1.64041666667 | 11993 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:42am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594025.5 | 510040.5 | 37793 | 1.64041666667 | 12236 |
| 012012 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:43am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594024.8 | 510041.7 | 37795 | 1.64041666667 | 12012 |
| 012472 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:44am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594024.6 | 510044.0 | 37797 | 1.64041666667 | 12472 |
| 012498 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:45am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594024.0 | 510046.4 | 37799 | 1.64041666667 | 12498 |
| 012100 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:46am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594023.7 | 510046.9 | 37801 | 1.64041666667 | 12100 |
| 011441 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:47am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1594023.1 | 510047.0 | 37803 | 1.64041666667 | 11441 |
| 011453 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:48am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1594021.9 | 510047.2 | 37805 | 1.64041666667 | 11453 |
| 011295 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:49am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594019.0 | 510047.8 | 37807 | 1.64041666667 | 11295 |
| 011295 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:50am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594016.8 | 510048.0 | 37809 | 1.64041666667 | 11295 |
| 010764 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:51am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1594014.3 | 510046.8 | 37811 | 1.64041666667 | 10764 |
| 011462 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:52am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594012.2 | 510046.6 | 37813 | 1.64041666667 | 11462 |
| 012642 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:53am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1594011.2 | 510045.4 | 37815 | 1.64041666667 | 12642 |
| 011461 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:54am | Sensor | 1797-S0031-636-G-DTE | 6806.4 | 1594009.3 | 510045.7 | 37817 | 1.64041666667 | 11461 |
| 011149 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:55am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594007.2 | 510044.6 | 37819 | 1.64041666667 | 11149 |
| 010816 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:56am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1594005.2 | 510044.3 | 37821 | 1.64041666667 | 10816 |
| 010876 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:57am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1594003.8 | 510042.0 | 37823 | 1.64041666667 | 10876 |
| 010970 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:58am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594003.2 | 510039.7 | 37825 | 1.64041666667 | 10970 |
| 011623 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:59am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1594001.4 | 510037.4 | 37827 | 1.64041666667 | 11623 |
| 011360 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:00am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593999.1 | 510035.9 | 37829 | 1.64041666667 | 11360 |
| 010867 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:01am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593996.0 | 510034.8 | 37831 | 1.64041666667 | 10867 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010935 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:02am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593993.7 | 510033.9 | 37833 | 1.64041666667 | 10935 |
| 010516 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:03am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593990.6 | 510032.0 | 37835 | 1.64041666667 | 10516 |
| 011323 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:04am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593987.9 | 510031.3 | 37837 | 1.64041666667 | 11323 |
| 011934 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:05am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593985.2 | 510030.6 | 37839 | 1.64041666667 | 11934 |
| 011827 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:06am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593983.7 | 510028.9 | 37841 | 1.64041666667 | 11827 |
| 011798 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:07am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593982.0 | 510027.5 | 37843 | 1.64041666667 | 11798 |
| 011714 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:08am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593981.0 | 510025.7 | 37845 | 1.64041666667 | 11714 |
| 011981 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:09am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593978.3 | 510025.3 | 37847 | 1.64041666667 | 11981 |
| 011809 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:10am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593976.1 | 510026.3 | 37849 | 1.64041666667 | 11809 |
| 012523 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:11am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593972.9 | 510026.3 | 37851 | 1.64041666667 | 12523 |
| 013479 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:12am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593970.7 | 510026.1 | 37853 | 1.64041666667 | 13479 |
| 013889 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:13am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593967.3 | 510025.2 | 37855 | 1.64041666667 | 13889 |
| 013092 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:14am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593965.8 | 510024.1 | 37857 | 1.64041666667 | 13092 |
| 012884 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:15am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593963.3 | 510022.1 | 37859 | 1.64041666667 | 12884 |
| 013622 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:16am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593961.1 | 510020.8 | 37861 | 1.64041666667 | 13622 |
| 013632 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:17am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593958.8 | 510019.3 | 37863 | 1.64041666667 | 13632 |
| 012881 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:18am | Sensor | 1797-S0031-636-G-DTE | 6806.0 | 1593956.7 | 510018.9 | 37865 | 1.64041666667 | 12881 |
| 013103 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:19am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593954.1 | 510017.1 | 37867 | 1.64041666667 | 13103 |
| 012988 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:20am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593951.7 | 510016.4 | 37869 | 1.64041666667 | 12988 |
| 013005 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:21am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593948.0 | 510017.0 | 37871 | 1.64041666667 | 13005 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:22am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593945.3 | 510016.5 | 37873 | 1.64041666667 | 13278 |
| 012411 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:23am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593941.9 | 510015.9 | 37875 | 1.64041666667 | 12411 |
| 012404 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:24am | Sensor | 1797-S0031-636-G-DTE | 6805.7 | 1593939.4 | 510015.6 | 37877 | 1.64041666667 | 12404 |
| 011432 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:25am | Sensor | 1797-S0031-636-G-DTE | 6805.5 | 1593936.1 | 510014.3 | 37879 | 1.64041666667 | 11432 |
| 011133 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:26am | Sensor | 1797-S0031-636-G-DTE | 6805.6 | 1593933.3 | 510013.9 | 37881 | 1.64041666667 | 11133 |
| 011760 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:27am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593930.3 | 510013.1 | 37883 | 1.64041666667 | 11760 |
| 011497 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:28am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593928.4 | 510012.1 | 37885 | 1.64041666667 | 11497 |
| 011882 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:29am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593926.3 | 510011.5 | 37887 | 1.64041666667 | 11882 |
| 012308 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:30am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593925.2 | 510010.6 | 37889 | 1.64041666667 | 12308 |
| 011836 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:31am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593925.0 | 510010.6 | 37891 | 1.64041666667 | 11836 |
| 011960 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:32am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593924.8 | 510010.6 | 37893 | 1.64041666667 | 11960 |
| 011782 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:33am | Sensor | 1797-S0031-636-G-DTE | 6805.9 | 1593923.5 | 510011.1 | 37895 | 1.64041666667 | 11782 |
| 012282 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:34am | Sensor | 1797-S0031-636-G-DTE | 6805.8 | 1593921.6 | 510012.5 | 37897 | 1.64041666667 | 12282 |
| 012751 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:35am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593921.3 | 510015.9 | 37899 | 1.64041666667 | 12751 |
| 012655 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:36am | Sensor | 1797-S0031-636-G-DTE | 6806.1 | 1593922.3 | 510018.5 | 37901 | 1.64041666667 | 12655 |
| 012983 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:37am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593925.6 | 510019.8 | 37903 | 1.64041666667 | 12983 |
| 013168 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:38am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593928.2 | 510020.8 | 37905 | 1.64041666667 | 13168 |
| 013167 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:39am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593931.3 | 510022.1 | 37907 | 1.64041666667 | 13167 |
| 013076 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:40am | Sensor | 1797-S0031-636-G-DTE | 6806.3 | 1593934.1 | 510022.4 | 37909 | 1.64041666667 | 13076 |
| 013970 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:41am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593936.4 | 510023.0 | 37911 | 1.64041666667 | 13970 |
| 013273 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:42am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593937.5 | 510022.7 | 37913 | 1.64041666667 | 13273 |
| 013308 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:43am | Sensor | 1797-S0031-636-G-DTE | 6806.2 | 1593938.0 | 510022.9 | 37915 | 1.64041666667 | 13308 |
| 018120 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:41am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594131.9 | 509557.8 | 37916 | 1.64041666667 | 18120 |
| 018105 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:42am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.0 | 509557.6 | 37918 | 1.64041666667 | 18105 |
| 018614 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:43am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.0 | 509557.6 | 37920 | 1.64041666667 | 18614 |
| 018608 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:44am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.0 | 509557.6 | 37922 | 1.64041666667 | 18608 |
| 018229 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:45am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.0 | 509557.6 | 37924 | 1.64041666667 | 18229 |
| 018331 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:46am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.0 | 509557.6 | 37926 | 1.64041666667 | 18331 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019349 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:47am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.0 | 509557.6 | 37928 | 1.64041666667 | 19349 |
| 018278 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:48am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.1 | 509557.6 | 37930 | 1.64041666667 | 18278 |
| 018599 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:49am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.0 | 509557.6 | 37932 | 1.64041666667 | 18599 |
| 019087 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:50am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.1 | 509557.6 | 37934 | 1.64041666667 | 19087 |
| 018799 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:51am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.1 | 509557.6 | 37936 | 1.64041666667 | 18799 |
| 018479 | 0 | GeoXH 6000 | 08/18/2015 | 11:21:52am | Sensor | 1797-S0031-636-G-DTE | 6803.9 | 1594132.1 | 509557.6 | 37938 | 1.64041666667 | 18479 |
| 009343 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:31am | Sensor | 1797-S0031-636-G-DTE | 6791.9 | 1593932.3 | 509909.7 | 37961 | 1.64041666667 | 9343 |
| 008863 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:32am | Sensor | 1797-S0031-636-G-DTE | 6791.9 | 1593931.7 | 509911.3 | 37963 | 1.64041666667 | 8863 |
| 019537 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:33am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594140.2 | 509561.4 | 29463 | 1.64041666667 | 19537 |
| 021144 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:34am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594140.2 | 509561.4 | 29464 | 1.64041666667 | 21144 |
| 019296 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:36am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594140.2 | 509561.4 | 29468 | 1.64041666667 | 19296 |
| 019014 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:36am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594140.1 | 509561.4 | 29469 | 1.64041666667 | 19014 |
| 019783 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:38am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594140.2 | 509561.4 | 29472 | 1.64041666667 | 19783 |
| 019616 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:38am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594140.2 | 509561.4 | 29473 | 1.64041666667 | 19616 |
| 020834 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:39am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594140.2 | 509561.4 | 29475 | 1.64041666667 | 20834 |
| 023958 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:40am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29477 | 1.64041666667 | 23958 |
| 019699 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:41am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29479 | 1.64041666667 | 19699 |
| 018934 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:42am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29481 | 1.64041666667 | 18934 |
| 018593 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:43am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29483 | 1.64041666667 | 18593 |
| 021028 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:44am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29485 | 1.64041666667 | 21028 |
| 020737 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:45am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.2 | 509561.4 | 29487 | 1.64041666667 | 20737 |
| 018684 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:46am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29489 | 1.64041666667 | 18684 |
| 019131 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:47am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29491 | 1.64041666667 | 19131 |
| 019782 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:48am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29493 | 1.64041666667 | 19782 |
| 019225 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:49am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.2 | 509561.4 | 29495 | 1.64041666667 | 19225 |
| 019716 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:50am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.2 | 509561.4 | 29497 | 1.64041666667 | 19716 |
| 018369 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:51am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.1 | 509561.4 | 29499 | 1.64041666667 | 18369 |
| 020102 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:52am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.1 | 509561.4 | 29501 | 1.64041666667 | 20102 |
| 020025 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:53am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.1 | 509561.4 | 29503 | 1.64041666667 | 20025 |
| 020186 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:54am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.1 | 509561.3 | 29505 | 1.64041666667 | 20186 |
| 020616 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:55am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.1 | 509561.4 | 29507 | 1.64041666667 | 20616 |
| 020154 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:56am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.1 | 509561.3 | 29509 | 1.64041666667 | 20154 |
| 020938 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:57am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.1 | 509561.4 | 29511 | 1.64041666667 | 20938 |
| 020894 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:58am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.1 | 509561.4 | 29513 | 1.64041666667 | 20894 |
| 020613 | 0 | GeoXH 6000 | 08/18/2015 | 10:27:59am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.1 | 509561.4 | 29515 | 1.64041666667 | 20613 |
| 020663 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:00am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.9 | 509561.5 | 29517 | 1.64041666667 | 20663 |
| 020135 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:01am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.1 | 509561.6 | 29519 | 1.64041666667 | 20135 |
| 020574 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:02am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.0 | 509561.5 | 29521 | 1.64041666667 | 20574 |
| 019693 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:03am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.9 | 509561.2 | 29523 | 1.64041666667 | 19693 |
| 021303 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:04am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.9 | 509561.2 | 29525 | 1.64041666667 | 21303 |
| 018975 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:05am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.8 | 509561.2 | 29527 | 1.64041666667 | 18975 |
| 020373 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:06am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.9 | 509561.2 | 29529 | 1.64041666667 | 20373 |
| 020453 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:07am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.9 | 509561.2 | 29531 | 1.64041666667 | 20453 |
| 019573 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:08am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.9 | 509561.2 | 29533 | 1.64041666667 | 19573 |
| 018633 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:09am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.9 | 509561.2 | 29535 | 1.64041666667 | 18633 |
| 019358 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:10am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.9 | 509561.2 | 29537 | 1.64041666667 | 19358 |
| 019299 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:12am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.9 | 509561.2 | 29540 | 1.64041666667 | 19299 |
| 018775 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:12am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.9 | 509561.2 | 29541 | 1.64041666667 | 18775 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 020233 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:14am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.8 | 509561.3 | 29544 | 1.64041666667 | 20233 |
| 019998 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:14am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.9 | 509561.2 | 29545 | 1.64041666667 | 19998 |
| 020599 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:15am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594139.9 | 509561.0 | 29547 | 1.64041666667 | 20599 |
| 020659 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:16am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594140.1 | 509561.1 | 29549 | 1.64041666667 | 20659 |
| 021305 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:17am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594140.0 | 509560.9 | 29551 | 1.64041666667 | 21305 |
| 022726 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:18am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.9 | 509561.0 | 29553 | 1.64041666667 | 22726 |
| 022691 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:19am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.9 | 509561.0 | 29555 | 1.64041666667 | 22691 |
| 020463 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:20am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.9 | 509561.0 | 29557 | 1.64041666667 | 20463 |
| 021375 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:21am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.9 | 509560.9 | 29559 | 1.64041666667 | 21375 |
| 019683 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:22am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.9 | 509560.9 | 29561 | 1.64041666667 | 19683 |
| 021721 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:23am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.8 | 509560.9 | 29563 | 1.64041666667 | 21721 |
| 020310 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:24am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.9 | 509560.9 | 29565 | 1.64041666667 | 20310 |
| 020347 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:25am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.9 | 509560.9 | 29567 | 1.64041666667 | 20347 |
| 018707 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:26am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.8 | 509560.9 | 29569 | 1.64041666667 | 18707 |
| 020906 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:27am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.8 | 509560.9 | 29571 | 1.64041666667 | 20906 |
| 019596 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:28am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.6 | 509561.4 | 29573 | 1.64041666667 | 19596 |
| 019719 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:30am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.5 | 509561.5 | 29576 | 1.64041666667 | 19719 |
| 019659 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:30am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.5 | 509561.3 | 29577 | 1.64041666667 | 19659 |
| 019015 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:31am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.4 | 509561.2 | 29579 | 1.64041666667 | 19015 |
| 019813 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:32am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.4 | 509561.2 | 29581 | 1.64041666667 | 19813 |
| 020403 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:33am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.2 | 29583 | 1.64041666667 | 20403 |
| 020040 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:34am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.2 | 29585 | 1.64041666667 | 20040 |
| 019470 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:35am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.2 | 509561.3 | 29587 | 1.64041666667 | 19470 |
| 020677 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:36am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.3 | 29589 | 1.64041666667 | 20677 |
| 021039 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:37am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.3 | 509561.2 | 29591 | 1.64041666667 | 21039 |
| 021010 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:38am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.4 | 509561.2 | 29593 | 1.64041666667 | 21010 |
| 019982 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:39am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.4 | 509561.2 | 29595 | 1.64041666667 | 19982 |
| 019155 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:40am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.1 | 29597 | 1.64041666667 | 19155 |
| 018978 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:41am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.2 | 29599 | 1.64041666667 | 18978 |
| 020794 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:42am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.2 | 509561.2 | 29601 | 1.64041666667 | 20794 |
| 019868 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:43am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.2 | 509561.2 | 29603 | 1.64041666667 | 19868 |
| 020627 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:44am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.2 | 509561.2 | 29605 | 1.64041666667 | 20627 |
| 020126 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:45am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.2 | 29607 | 1.64041666667 | 20126 |
| 019131 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:46am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.2 | 29609 | 1.64041666667 | 19131 |
| 020383 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:47am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.2 | 29611 | 1.64041666667 | 20383 |
| 020635 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:48am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.0 | 29613 | 1.64041666667 | 20635 |
| 020009 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:49am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.1 | 509560.9 | 29615 | 1.64041666667 | 20009 |
| 021622 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:50am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.4 | 509561.2 | 29617 | 1.64041666667 | 21622 |
| 019745 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:51am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.5 | 509561.1 | 29619 | 1.64041666667 | 19745 |
| 020446 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:52am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.6 | 509561.1 | 29621 | 1.64041666667 | 20446 |
| 019871 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:53am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.6 | 509561.2 | 29623 | 1.64041666667 | 19871 |
| 021918 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:54am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.5 | 509561.2 | 29625 | 1.64041666667 | 21918 |
| 021109 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:55am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.5 | 509561.1 | 29627 | 1.64041666667 | 21109 |
| 020967 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:56am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.5 | 509561.1 | 29629 | 1.64041666667 | 20967 |
| 021172 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:57am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.5 | 509561.1 | 29631 | 1.64041666667 | 21172 |
| 021103 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:58am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594139.5 | 509561.1 | 29633 | 1.64041666667 | 21103 |
| 021925 | 0 | GeoXH 6000 | 08/18/2015 | 10:28:59am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.3 | 509561.2 | 29635 | 1.64041666667 | 21925 |
| 019461 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:00am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594138.9 | 509561.0 | 29637 | 1.64041666667 | 19461 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019445 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:01am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594138.9 | 509561.2 | 29639 | 1.64041666667 | 19445 |
| 022051 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:02am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.0 | 509561.3 | 29641 | 1.64041666667 | 22051 |
| 019972 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:03am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.0 | 509561.3 | 29643 | 1.64041666667 | 19972 |
| 019903 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:04am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594139.0 | 509561.3 | 29645 | 1.64041666667 | 19903 |
| 019946 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:05am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594139.0 | 509561.3 | 29647 | 1.64041666667 | 19946 |
| 020226 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:06am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594138.9 | 509561.3 | 29649 | 1.64041666667 | 20226 |
| 019186 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:07am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594138.8 | 509561.2 | 29651 | 1.64041666667 | 19186 |
| 019196 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:08am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594138.8 | 509560.8 | 29653 | 1.64041666667 | 19196 |
| 019919 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:09am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594138.4 | 509561.3 | 29655 | 1.64041666667 | 19919 |
| 020910 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:10am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594137.5 | 509562.0 | 29657 | 1.64041666667 | 20910 |
| 020017 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:11am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594136.2 | 509563.0 | 29659 | 1.64041666667 | 20017 |
| 019254 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:12am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594134.3 | 509564.9 | 29661 | 1.64041666667 | 19254 |
| 019903 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:13am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594132.7 | 509568.0 | 29663 | 1.64041666667 | 19903 |
| 019466 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:14am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594131.9 | 509571.4 | 29665 | 1.64041666667 | 19466 |
| 015786 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:15am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594131.1 | 509575.1 | 29667 | 1.64041666667 | 15786 |
| 016156 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:16am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594130.5 | 509578.3 | 29669 | 1.64041666667 | 16156 |
| 014599 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:17am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594130.1 | 509582.0 | 29671 | 1.64041666667 | 14599 |
| 017389 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:18am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594129.6 | 509585.4 | 29673 | 1.64041666667 | 17389 |
| 015717 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:19am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594128.9 | 509588.7 | 29675 | 1.64041666667 | 15717 |
| 014429 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:20am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594128.4 | 509591.6 | 29677 | 1.64041666667 | 14429 |
| 015787 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:21am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594128.1 | 509594.2 | 29679 | 1.64041666667 | 15787 |
| 016816 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:22am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594127.9 | 509595.3 | 29681 | 1.64041666667 | 16816 |
| 014674 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:23am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594127.8 | 509595.4 | 29683 | 1.64041666667 | 14674 |
| 015098 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:24am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594127.7 | 509595.4 | 29685 | 1.64041666667 | 15098 |
| 015354 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:25am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594127.5 | 509595.4 | 29687 | 1.64041666667 | 15354 |
| 015478 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:26am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594127.5 | 509595.5 | 29689 | 1.64041666667 | 15478 |
| 015179 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:27am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594127.4 | 509595.5 | 29691 | 1.64041666667 | 15179 |
| 015885 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:28am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594127.8 | 509596.6 | 29693 | 1.64041666667 | 15885 |
| 014771 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:29am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594128.0 | 509598.7 | 29695 | 1.64041666667 | 14771 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:30am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594128.0 | 509600.7 | 29697 | 1.64041666667 | 13742 |
| 014775 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:31am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594127.8 | 509602.3 | 29699 | 1.64041666667 | 14775 |
| 014973 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:32am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594128.0 | 509602.8 | 29701 | 1.64041666667 | 14973 |
| 014513 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:33am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594128.0 | 509602.8 | 29703 | 1.64041666667 | 14513 |
| 013918 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:34am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594127.9 | 509602.6 | 29705 | 1.64041666667 | 13918 |
| 015179 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:35am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594128.1 | 509602.6 | 29707 | 1.64041666667 | 15179 |
| 014835 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:36am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594127.9 | 509603.6 | 29709 | 1.64041666667 | 14835 |
| 016248 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:37am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594129.3 | 509605.0 | 29711 | 1.64041666667 | 16248 |
| 015642 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:38am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594131.3 | 509605.6 | 29713 | 1.64041666667 | 15642 |
| 015460 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:39am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594133.2 | 509605.2 | 29715 | 1.64041666667 | 15460 |
| 014575 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:40am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594135.2 | 509604.3 | 29717 | 1.64041666667 | 14575 |
| 014833 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:41am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594136.5 | 509602.6 | 29719 | 1.64041666667 | 14833 |
| 014178 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:42am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594138.3 | 509600.8 | 29721 | 1.64041666667 | 14178 |
| 015844 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:43am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594140.5 | 509598.5 | 29723 | 1.64041666667 | 15844 |
| 015001 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:44am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594141.9 | 509596.8 | 29725 | 1.64041666667 | 15001 |
| 014100 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:45am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594143.3 | 509594.9 | 29727 | 1.64041666667 | 14100 |
| 014805 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:46am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594144.1 | 509592.9 | 29729 | 1.64041666667 | 14805 |
| 014651 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:47am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594145.6 | 509590.9 | 29731 | 1.64041666667 | 14651 |
| 017163 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:48am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594146.5 | 509588.9 | 29733 | 1.64041666667 | 17163 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015630 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:49am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594147.0 | 509588.0 | 29735 | 1.64041666667 | 15630 |
| 014767 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:50am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594147.3 | 509587.8 | 29737 | 1.64041666667 | 14767 |
| 015032 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:51am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594147.6 | 509586.7 | 29739 | 1.64041666667 | 15032 |
| 015968 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:52am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594148.1 | 509585.2 | 29741 | 1.64041666667 | 15968 |
| 016772 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:53am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594148.4 | 509583.3 | 29743 | 1.64041666667 | 16772 |
| 017633 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:54am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594148.8 | 509582.5 | 29745 | 1.64041666667 | 17633 |
| 017908 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:55am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594148.9 | 509582.1 | 29747 | 1.64041666667 | 17908 |
| 017887 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:56am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594148.8 | 509582.1 | 29749 | 1.64041666667 | 17887 |
| 016471 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:57am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594148.9 | 509582.1 | 29751 | 1.64041666667 | 16471 |
| 016987 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:58am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594148.9 | 509582.1 | 29753 | 1.64041666667 | 16987 |
| 016847 | 0 | GeoXH 6000 | 08/18/2015 | 10:29:59am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594148.9 | 509582.0 | 29755 | 1.64041666667 | 16847 |
| 017861 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:00am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594149.2 | 509582.0 | 29757 | 1.64041666667 | 17861 |
| 018145 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:01am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594149.9 | 509580.4 | 29759 | 1.64041666667 | 18145 |
| 021306 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:02am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594151.5 | 509578.5 | 29761 | 1.64041666667 | 21306 |
| 020326 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:03am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594152.7 | 509576.0 | 29763 | 1.64041666667 | 20326 |
| 020063 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:04am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594154.1 | 509573.6 | 29765 | 1.64041666667 | 20063 |
| 021753 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:05am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594155.9 | 509570.6 | 29767 | 1.64041666667 | 21753 |
| 021128 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:06am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594156.9 | 509568.1 | 29769 | 1.64041666667 | 21128 |
| 022352 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:07am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594158.2 | 509564.7 | 29771 | 1.64041666667 | 22352 |
| 020018 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:08am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594159.6 | 509562.5 | 29773 | 1.64041666667 | 20018 |
| 021534 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:09am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594161.2 | 509559.4 | 29775 | 1.64041666667 | 21534 |
| 020593 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:10am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594162.1 | 509556.7 | 29777 | 1.64041666667 | 20593 |
| 022338 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:12am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594163.4 | 509553.9 | 29780 | 1.64041666667 | 22338 |
| 021784 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:12am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594164.3 | 509551.6 | 29781 | 1.64041666667 | 21784 |
| 023206 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:13am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594166.1 | 509548.8 | 29783 | 1.64041666667 | 23206 |
| 020471 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:14am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594167.7 | 509547.1 | 29785 | 1.64041666667 | 20471 |
| 022008 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:15am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594168.7 | 509545.2 | 29787 | 1.64041666667 | 22008 |
| 023112 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:16am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594169.5 | 509543.8 | 29789 | 1.64041666667 | 23112 |
| 021918 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:17am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594169.6 | 509543.0 | 29791 | 1.64041666667 | 21918 |
| 020689 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:18am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594169.5 | 509543.0 | 29793 | 1.64041666667 | 20689 |
| 019992 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:19am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594169.6 | 509543.0 | 29795 | 1.64041666667 | 19992 |
| 020898 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:20am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594169.7 | 509542.9 | 29797 | 1.64041666667 | 20898 |
| 021094 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:21am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594169.7 | 509542.8 | 29799 | 1.64041666667 | 21094 |
| 020693 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:22am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594168.5 | 509542.4 | 29801 | 1.64041666667 | 20693 |
| 021493 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:23am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594165.6 | 509541.8 | 29803 | 1.64041666667 | 21493 |
| 022203 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:24am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594163.5 | 509542.5 | 29805 | 1.64041666667 | 22203 |
| 020490 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:25am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594160.9 | 509543.5 | 29807 | 1.64041666667 | 20490 |
| 021112 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:26am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594158.4 | 509545.3 | 29809 | 1.64041666667 | 21112 |
| 020698 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:27am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594155.7 | 509547.3 | 29811 | 1.64041666667 | 20698 |
| 024374 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:28am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594153.1 | 509548.9 | 29813 | 1.64041666667 | 24374 |
| 022713 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:29am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594149.9 | 509551.3 | 29815 | 1.64041666667 | 22713 |
| 021608 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:30am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594147.7 | 509553.3 | 29817 | 1.64041666667 | 21608 |
| 020912 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:31am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594145.4 | 509555.2 | 29819 | 1.64041666667 | 20912 |
| 021038 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:32am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594143.5 | 509556.7 | 29821 | 1.64041666667 | 21038 |
| 021399 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:33am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594142.8 | 509558.2 | 29823 | 1.64041666667 | 21399 |
| 019870 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:34am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594142.5 | 509558.3 | 29825 | 1.64041666667 | 19870 |
| 020177 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:35am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594142.5 | 509558.3 | 29827 | 1.64041666667 | 20177 |
| 020764 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:36am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594142.5 | 509558.3 | 29829 | 1.64041666667 | 20764 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019831 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:37am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594142.5 | 509558.2 | 29831 | 1.64041666667 | 19831 |
| 020377 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:38am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594142.4 | 509558.1 | 29833 | 1.64041666667 | 20377 |
| 021714 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:39am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594141.9 | 509558.3 | 29835 | 1.64041666667 | 21714 |
| 019648 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:40am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594140.6 | 509559.6 | 29837 | 1.64041666667 | 19648 |
| 021262 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:41am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594138.0 | 509560.2 | 29839 | 1.64041666667 | 21262 |
| 020585 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:42am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1594136.0 | 509558.4 | 29841 | 1.64041666667 | 20585 |
| 019096 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:43am | Sensor | 1797-S0030-868-G-TJV | 6801.4 | 1594136.8 | 509557.8 | 29844 | 1.64041666667 | 19096 |
| 020104 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:44am | Sensor | 1797-S0030-868-G-TJV | 6801.0 | 1594137.6 | 509558.3 | 29846 | 1.64041666667 | 20104 |
| 022276 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:46am | Sensor | 1797-S0030-868-G-TJV | 6800.1 | 1594137.7 | 509557.5 | 29850 | 1.64041666667 | 22276 |
| 021679 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:46am | Sensor | 1797-S0030-868-G-TJV | 6800.6 | 1594137.7 | 509557.7 | 29851 | 1.64041666667 | 21679 |
| 021169 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:47am | Sensor | 1797-S0030-868-G-TJV | 6800.0 | 1594138.9 | 509558.2 | 29853 | 1.64041666667 | 21169 |
| 019482 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:48am | Sensor | 1797-S0030-868-G-TJV | 6801.0 | 1594139.2 | 509558.3 | 29855 | 1.64041666667 | 19482 |
| 018130 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:49am | Sensor | 1797-S0030-868-G-TJV | 6801.3 | 1594139.8 | 509559.1 | 29857 | 1.64041666667 | 18130 |
| 019022 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:50am | Sensor | 1797-S0030-868-G-TJV | 6801.0 | 1594139.1 | 509559.3 | 29859 | 1.64041666667 | 19022 |
| 019125 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:51am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594133.8 | 509560.1 | 29862 | 1.64041666667 | 19125 |
| 019121 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:52am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1594130.8 | 509560.7 | 29865 | 1.64041666667 | 19121 |
| 020620 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:53am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1594128.5 | 509561.2 | 29867 | 1.64041666667 | 20620 |
| 019195 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:54am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1594126.0 | 509561.6 | 29869 | 1.64041666667 | 19195 |
| 017668 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:55am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594122.6 | 509562.1 | 29871 | 1.64041666667 | 17668 |
| 016477 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:56am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594119.9 | 509562.4 | 29873 | 1.64041666667 | 16477 |
| 015729 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:57am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594116.7 | 509562.1 | 29875 | 1.64041666667 | 15729 |
| 017282 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:58am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594113.6 | 509561.4 | 29877 | 1.64041666667 | 17282 |
| 018060 | 0 | GeoXH 6000 | 08/18/2015 | 10:30:59am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594110.5 | 509561.3 | 29879 | 1.64041666667 | 18060 |
| 016290 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:00am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594107.6 | 509561.0 | 29881 | 1.64041666667 | 16290 |
| 014846 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:01am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594104.5 | 509559.6 | 29883 | 1.64041666667 | 14846 |
| 013341 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:02am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594101.3 | 509558.5 | 29885 | 1.64041666667 | 13341 |
| 014075 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:03am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594097.8 | 509557.6 | 29887 | 1.64041666667 | 14075 |
| 013898 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:04am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594095.2 | 509557.0 | 29889 | 1.64041666667 | 13898 |
| 012144 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:05am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594092.4 | 509556.9 | 29891 | 1.64041666667 | 12144 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:06am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594089.2 | 509557.0 | 29893 | 1.64041666667 | 14526 |
| 014011 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:07am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594086.2 | 509557.5 | 29895 | 1.64041666667 | 14011 |
| 012832 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:08am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594083.9 | 509557.1 | 29897 | 1.64041666667 | 12832 |
| 013018 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:09am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594080.7 | 509556.1 | 29899 | 1.64041666667 | 13018 |
| 012644 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:10am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594078.2 | 509555.4 | 29901 | 1.64041666667 | 12644 |
| 014171 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:11am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594074.9 | 509553.7 | 29903 | 1.64041666667 | 14171 |
| 013532 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:12am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594072.6 | 509552.1 | 29905 | 1.64041666667 | 13532 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:13am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594069.9 | 509550.1 | 29907 | 1.64041666667 | 13043 |
| 012380 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:14am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594067.5 | 509548.2 | 29909 | 1.64041666667 | 12380 |
| 012365 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:15am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594064.7 | 509546.4 | 29911 | 1.64041666667 | 12365 |
| 013201 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:16am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594062.3 | 509545.3 | 29913 | 1.64041666667 | 13201 |
| 012240 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:17am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594059.3 | 509544.4 | 29915 | 1.64041666667 | 12240 |
| 013350 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:18am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594056.4 | 509543.9 | 29917 | 1.64041666667 | 13350 |
| 012097 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:19am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594053.9 | 509544.5 | 29919 | 1.64041666667 | 12097 |
| 014124 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:20am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594051.8 | 509545.2 | 29921 | 1.64041666667 | 14124 |
| 012501 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:21am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594049.6 | 509546.1 | 29923 | 1.64041666667 | 12501 |
| 013625 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:22am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594047.7 | 509547.0 | 29925 | 1.64041666667 | 13625 |
| 014806 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:23am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594044.8 | 509547.7 | 29927 | 1.64041666667 | 14806 |
| 015911 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:24am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594041.9 | 509548.6 | 29929 | 1.64041666667 | 15911 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016278 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:25am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594038.0 | 509549.6 | 29931 | 1.64041666667 | 16278 |
| 015409 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:26am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594035.3 | 509550.0 | 29933 | 1.64041666667 | 15409 |
| 014442 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:27am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594031.6 | 509550.6 | 29935 | 1.64041666667 | 14442 |
| 013810 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:28am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594028.4 | 509551.1 | 29937 | 1.64041666667 | 13810 |
| 015362 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:29am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594024.7 | 509551.7 | 29939 | 1.64041666667 | 15362 |
| 015750 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:30am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594021.6 | 509551.9 | 29941 | 1.64041666667 | 15750 |
| 014407 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:31am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594018.1 | 509551.7 | 29943 | 1.64041666667 | 14407 |
| 014702 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:32am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594014.9 | 509550.8 | 29945 | 1.64041666667 | 14702 |
| 013725 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:33am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594011.0 | 509549.5 | 29947 | 1.64041666667 | 13725 |
| 014471 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:34am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594007.8 | 509549.1 | 29949 | 1.64041666667 | 14471 |
| 014268 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:35am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594004.3 | 509549.0 | 29951 | 1.64041666667 | 14268 |
| 014847 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:36am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594001.6 | 509548.3 | 29953 | 1.64041666667 | 14847 |
| 014991 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:37am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593998.4 | 509548.2 | 29955 | 1.64041666667 | 14991 |
| 013678 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:38am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593995.7 | 509549.3 | 29957 | 1.64041666667 | 13678 |
| 015809 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:39am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593992.7 | 509550.9 | 29959 | 1.64041666667 | 15809 |
| 015952 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:40am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593990.0 | 509552.4 | 29961 | 1.64041666667 | 15952 |
| 014488 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:41am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593987.2 | 509553.9 | 29963 | 1.64041666667 | 14488 |
| 014992 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:42am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593984.8 | 509554.4 | 29965 | 1.64041666667 | 14992 |
| 014638 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:43am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593981.7 | 509555.3 | 29967 | 1.64041666667 | 14638 |
| 015629 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:44am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593979.2 | 509556.6 | 29969 | 1.64041666667 | 15629 |
| 014497 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:45am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593976.6 | 509556.9 | 29971 | 1.64041666667 | 14497 |
| 013014 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:46am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593974.1 | 509557.7 | 29973 | 1.64041666667 | 13014 |
| 014443 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:47am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593971.4 | 509558.9 | 29975 | 1.64041666667 | 14443 |
| 014951 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:48am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593969.5 | 509558.2 | 29977 | 1.64041666667 | 14951 |
| 012947 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:49am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593966.9 | 509555.9 | 29979 | 1.64041666667 | 12947 |
| 014393 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:50am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593964.9 | 509553.9 | 29981 | 1.64041666667 | 14393 |
| 013889 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:51am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593963.6 | 509551.7 | 29983 | 1.64041666667 | 13889 |
| 012712 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:52am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593961.9 | 509549.8 | 29985 | 1.64041666667 | 12712 |
| 013408 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:53am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593959.8 | 509547.1 | 29987 | 1.64041666667 | 13408 |
| 011632 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:54am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593958.3 | 509545.1 | 29989 | 1.64041666667 | 11632 |
| 013018 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:55am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593956.1 | 509542.6 | 29991 | 1.64041666667 | 13018 |
| 012914 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:56am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593954.5 | 509540.5 | 29993 | 1.64041666667 | 12914 |
| 011868 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:57am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593952.1 | 509537.6 | 29995 | 1.64041666667 | 11868 |
| 013977 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:58am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593949.8 | 509535.3 | 29997 | 1.64041666667 | 13977 |
| 015164 | 0 | GeoXH 6000 | 08/18/2015 | 10:31:59am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593947.4 | 509532.5 | 29999 | 1.64041666667 | 15164 |
| 013061 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:00am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593945.6 | 509530.4 | 30001 | 1.64041666667 | 13061 |
| 011485 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:01am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593943.2 | 509527.7 | 30003 | 1.64041666667 | 11485 |
| 011991 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:02am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593941.2 | 509525.5 | 30005 | 1.64041666667 | 11991 |
| 014547 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:03am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.8 | 509523.1 | 30007 | 1.64041666667 | 14547 |
| 013687 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:04am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.2 | 509522.3 | 30009 | 1.64041666667 | 13687 |
| 013531 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:05am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.1 | 509522.2 | 30011 | 1.64041666667 | 13531 |
| 013672 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:06am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.1 | 509522.2 | 30013 | 1.64041666667 | 13672 |
| 012748 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:07am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.1 | 509522.2 | 30015 | 1.64041666667 | 12748 |
| 013897 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:08am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.1 | 509522.2 | 30017 | 1.64041666667 | 13897 |
| 013044 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:09am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.0 | 509522.2 | 30019 | 1.64041666667 | 13044 |
| 013581 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:10am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.0 | 509522.2 | 30021 | 1.64041666667 | 13581 |
| 013265 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:11am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.0 | 509522.2 | 30023 | 1.64041666667 | 13265 |
| 011146 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:12am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.0 | 509522.2 | 30025 | 1.64041666667 | 11146 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012086 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:13am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.0 | 509522.2 | 30027 | 1.64041666667 | 12086 |
| 012561 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:14am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.0 | 509522.2 | 30029 | 1.64041666667 | 12561 |
| 012350 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:15am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.1 | 509522.2 | 30031 | 1.64041666667 | 12350 |
| 011637 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:16am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593939.3 | 509522.2 | 30033 | 1.64041666667 | 11637 |
| 011249 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:17am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593939.4 | 509522.1 | 30035 | 1.64041666667 | 11249 |
| 012292 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:18am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593939.4 | 509522.0 | 30037 | 1.64041666667 | 12292 |
| 012313 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:19am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593939.4 | 509522.0 | 30039 | 1.64041666667 | 12313 |
| 011508 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:20am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593939.4 | 509522.0 | 30041 | 1.64041666667 | 11508 |
| 012207 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:21am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593939.4 | 509521.9 | 30043 | 1.64041666667 | 12207 |
| 012171 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:22am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593939.3 | 509521.7 | 30045 | 1.64041666667 | 12171 |
| 012373 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:23am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593938.4 | 509521.5 | 30047 | 1.64041666667 | 12373 |
| 012123 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:24am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593937.5 | 509520.2 | 30049 | 1.64041666667 | 12123 |
| 011580 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:25am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593935.7 | 509519.0 | 30051 | 1.64041666667 | 11580 |
| 011670 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:26am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593934.4 | 509517.3 | 30053 | 1.64041666667 | 11670 |
| 014343 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:27am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593932.6 | 509515.4 | 30055 | 1.64041666667 | 14343 |
| 014176 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:28am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593931.5 | 509513.9 | 30057 | 1.64041666667 | 14176 |
| 013234 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:29am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593929.7 | 509512.9 | 30059 | 1.64041666667 | 13234 |
| 013238 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:30am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593928.1 | 509511.1 | 30061 | 1.64041666667 | 13238 |
| 015489 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:31am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593926.4 | 509510.7 | 30063 | 1.64041666667 | 15489 |
| 015182 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:32am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593925.2 | 509509.3 | 30065 | 1.64041666667 | 15182 |
| 014385 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:33am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593923.9 | 509508.1 | 30067 | 1.64041666667 | 14385 |
| 011846 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:34am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593922.7 | 509506.6 | 30069 | 1.64041666667 | 11846 |
| 014241 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:35am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593921.4 | 509505.0 | 30071 | 1.64041666667 | 14241 |
| 013940 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:36am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593919.5 | 509504.2 | 30073 | 1.64041666667 | 13940 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:37am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593917.9 | 509502.5 | 30075 | 1.64041666667 | 13595 |
| 013118 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:38am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593916.3 | 509501.7 | 30077 | 1.64041666667 | 13118 |
| 012819 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:39am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593915.2 | 509499.7 | 30079 | 1.64041666667 | 12819 |
| 013495 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:40am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593913.4 | 509498.3 | 30081 | 1.64041666667 | 13495 |
| 012763 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:41am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593912.1 | 509496.1 | 30083 | 1.64041666667 | 12763 |
| 012701 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:42am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593910.6 | 509494.9 | 30085 | 1.64041666667 | 12701 |
| 012475 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:43am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593909.3 | 509492.9 | 30087 | 1.64041666667 | 12475 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:44am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593907.4 | 509491.9 | 30089 | 1.64041666667 | 14158 |
| 012389 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:45am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593905.6 | 509490.2 | 30091 | 1.64041666667 | 12389 |
| 010567 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:46am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593903.7 | 509489.6 | 30093 | 1.64041666667 | 10567 |
| 011941 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:47am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593901.7 | 509487.9 | 30095 | 1.64041666667 | 11941 |
| 012405 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:48am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593900.1 | 509486.8 | 30097 | 1.64041666667 | 12405 |
| 011891 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:49am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593898.5 | 509484.8 | 30099 | 1.64041666667 | 11891 |
| 011733 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:50am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593897.1 | 509483.9 | 30101 | 1.64041666667 | 11733 |
| 011513 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:51am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593896.7 | 509483.2 | 30103 | 1.64041666667 | 11513 |
| 010528 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:52am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593896.5 | 509483.2 | 30105 | 1.64041666667 | 10528 |
| 009742 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:53am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593896.6 | 509483.2 | 30107 | 1.64041666667 | 9742 |
| 010415 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:54am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593896.7 | 509483.2 | 30109 | 1.64041666667 | 10415 |
| 012623 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:55am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593896.7 | 509483.3 | 30111 | 1.64041666667 | 12623 |
| 011286 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:56am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593896.7 | 509483.3 | 30113 | 1.64041666667 | 11286 |
| 012721 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:57am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593896.4 | 509483.3 | 30115 | 1.64041666667 | 12721 |
| 012330 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:58am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593896.3 | 509483.7 | 30117 | 1.64041666667 | 12330 |
| 013072 | 0 | GeoXH 6000 | 08/18/2015 | 10:32:59am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593896.4 | 509483.8 | 30119 | 1.64041666667 | 13072 |
| 011518 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:00am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593896.3 | 509483.6 | 30121 | 1.64041666667 | 11518 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011939 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:01am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593896.3 | 509483.4 | 30123 | 1.64041666667 | 11939 |
| 011865 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:02am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593896.1 | 509483.0 | 30125 | 1.64041666667 | 11865 |
| 010076 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:03am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593894.7 | 509482.8 | 30127 | 1.64041666667 | 10076 |
| 012329 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:04am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593893.6 | 509481.6 | 30129 | 1.64041666667 | 12329 |
| 010642 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:05am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593891.5 | 509480.2 | 30131 | 1.64041666667 | 10642 |
| 011810 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:06am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593890.2 | 509479.0 | 30133 | 1.64041666667 | 11810 |
| 012252 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:07am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593888.7 | 509478.1 | 30135 | 1.64041666667 | 12252 |
| 012153 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:08am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593887.2 | 509476.9 | 30137 | 1.64041666667 | 12153 |
| 011498 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:09am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593885.2 | 509477.0 | 30139 | 1.64041666667 | 11498 |
| 011934 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:10am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593883.6 | 509476.1 | 30141 | 1.64041666667 | 11934 |
| 011263 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:11am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593881.8 | 509475.6 | 30143 | 1.64041666667 | 11263 |
| 011246 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:12am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593880.1 | 509474.3 | 30145 | 1.64041666667 | 11246 |
| 011721 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:13am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593878.8 | 509474.0 | 30147 | 1.64041666667 | 11721 |
| 011690 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:14am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593877.9 | 509475.0 | 30149 | 1.64041666667 | 11690 |
| 010632 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:15am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593877.2 | 509476.5 | 30151 | 1.64041666667 | 10632 |
| 012378 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:16am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593878.0 | 509478.0 | 30153 | 1.64041666667 | 12378 |
| 012634 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:17am | Sensor | 1797-S0030-868-G-TJV | 6802.5 | 1593877.8 | 509479.5 | 30155 | 1.64041666667 | 12634 |
| 011078 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:18am | Sensor | 1797-S0030-868-G-TJV | 6802.5 | 1593878.5 | 509481.1 | 30157 | 1.64041666667 | 11078 |
| 010689 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:19am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593878.3 | 509482.8 | 30159 | 1.64041666667 | 10689 |
| 011492 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:20am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593879.1 | 509484.4 | 30161 | 1.64041666667 | 11492 |
| 013583 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:21am | Sensor | 1797-S0030-868-G-TJV | 6802.2 | 1593878.7 | 509486.3 | 30163 | 1.64041666667 | 13583 |
| 014675 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:22am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593878.8 | 509487.8 | 30165 | 1.64041666667 | 14675 |
| 013569 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:23am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593878.1 | 509489.3 | 30167 | 1.64041666667 | 13569 |
| 011852 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:24am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593878.5 | 509490.2 | 30169 | 1.64041666667 | 11852 |
| 012083 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:25am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593878.3 | 509491.6 | 30171 | 1.64041666667 | 12083 |
| 011930 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:26am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593878.2 | 509492.0 | 30173 | 1.64041666667 | 11930 |
| 011682 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:27am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593878.9 | 509491.1 | 30175 | 1.64041666667 | 11682 |
| 011860 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:28am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593880.0 | 509490.2 | 30177 | 1.64041666667 | 11860 |
| 011695 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:29am | Sensor | 1797-S0030-868-G-TJV | 6802.5 | 1593881.1 | 509487.9 | 30179 | 1.64041666667 | 11695 |
| 013033 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:30am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593882.4 | 509486.8 | 30181 | 1.64041666667 | 13033 |
| 012048 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:31am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593884.8 | 509485.1 | 30183 | 1.64041666667 | 12048 |
| 011484 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:32am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593886.8 | 509484.4 | 30185 | 1.64041666667 | 11484 |
| 011350 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:33am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593888.5 | 509482.3 | 30187 | 1.64041666667 | 11350 |
| 011327 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:34am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593890.4 | 509481.4 | 30189 | 1.64041666667 | 11327 |
| 010931 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:35am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593893.3 | 509480.8 | 30191 | 1.64041666667 | 10931 |
| 013113 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:36am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593895.2 | 509480.6 | 30193 | 1.64041666667 | 13113 |
| 013508 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:37am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593897.3 | 509480.1 | 30195 | 1.64041666667 | 13508 |
| 012407 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:38am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593899.0 | 509479.6 | 30197 | 1.64041666667 | 12407 |
| 013181 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:39am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593901.4 | 509479.3 | 30199 | 1.64041666667 | 13181 |
| 013645 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:40am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593902.8 | 509478.6 | 30201 | 1.64041666667 | 13645 |
| 013401 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:41am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593904.5 | 509477.7 | 30203 | 1.64041666667 | 13401 |
| 013070 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:42am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593906.0 | 509476.8 | 30205 | 1.64041666667 | 13070 |
| 012807 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:43am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593908.6 | 509475.6 | 30207 | 1.64041666667 | 12807 |
| 011032 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:44am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593910.0 | 509475.3 | 30209 | 1.64041666667 | 11032 |
| 013318 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:45am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593912.0 | 509474.5 | 30211 | 1.64041666667 | 13318 |
| 013469 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:46am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593913.1 | 509474.0 | 30213 | 1.64041666667 | 13469 |
| 013117 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:47am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593914.9 | 509473.0 | 30215 | 1.64041666667 | 13117 |
| 012939 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:48am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593916.5 | 509472.9 | 30217 | 1.64041666667 | 12939 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014034 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:49am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593919.1 | 509473.1 | 30219 | 1.64041666667 | 14034 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:50am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593920.9 | 509473.4 | 30221 | 1.64041666667 | 13738 |
| 012434 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:51am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593923.2 | 509473.6 | 30223 | 1.64041666667 | 12434 |
| 013008 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:52am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593925.1 | 509474.5 | 30225 | 1.64041666667 | 13008 |
| 012252 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:53am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593926.9 | 509474.7 | 30227 | 1.64041666667 | 12252 |
| 013593 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:54am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593927.3 | 509474.7 | 30229 | 1.64041666667 | 13593 |
| 013508 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:55am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593927.2 | 509474.9 | 30231 | 1.64041666667 | 13508 |
| 012827 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:56am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593927.1 | 509474.9 | 30233 | 1.64041666667 | 12827 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:57am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593927.2 | 509475.0 | 30235 | 1.64041666667 | 13736 |
| 015644 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:58am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593927.2 | 509474.9 | 30237 | 1.64041666667 | 15644 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 10:33:59am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593927.2 | 509475.0 | 30239 | 1.64041666667 | 13301 |
| 012835 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:00am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593927.2 | 509475.0 | 30241 | 1.64041666667 | 12835 |
| 014218 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:01am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593927.1 | 509475.0 | 30243 | 1.64041666667 | 14218 |
| 013754 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:02am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593927.2 | 509475.0 | 30245 | 1.64041666667 | 13754 |
| 014178 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:03am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593927.2 | 509475.0 | 30247 | 1.64041666667 | 14178 |
| 014374 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:04am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593927.1 | 509475.0 | 30249 | 1.64041666667 | 14374 |
| 013583 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:05am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593927.1 | 509475.0 | 30251 | 1.64041666667 | 13583 |
| 013806 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:06am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593927.2 | 509475.1 | 30253 | 1.64041666667 | 13806 |
| 015631 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:07am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593927.3 | 509475.0 | 30255 | 1.64041666667 | 15631 |
| 014317 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:08am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593927.4 | 509475.0 | 30257 | 1.64041666667 | 14317 |
| 013179 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:09am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593928.9 | 509474.9 | 30259 | 1.64041666667 | 13179 |
| 013675 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:10am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593929.9 | 509475.7 | 30261 | 1.64041666667 | 13675 |
| 014518 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:11am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593932.1 | 509476.3 | 30263 | 1.64041666667 | 14518 |
| 015299 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:12am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593933.4 | 509477.5 | 30265 | 1.64041666667 | 15299 |
| 014115 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:13am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593935.6 | 509479.0 | 30267 | 1.64041666667 | 14115 |
| 016188 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:14am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593937.2 | 509479.9 | 30269 | 1.64041666667 | 16188 |
| 014997 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:15am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593939.6 | 509481.6 | 30271 | 1.64041666667 | 14997 |
| 013979 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:16am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593941.4 | 509482.3 | 30273 | 1.64041666667 | 13979 |
| 016665 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:17am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593943.8 | 509483.8 | 30275 | 1.64041666667 | 16665 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:18am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593945.5 | 509484.6 | 30277 | 1.64041666667 | 14516 |
| 013949 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:19am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593947.2 | 509486.5 | 30279 | 1.64041666667 | 13949 |
| 015787 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:20am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593948.5 | 509488.0 | 30281 | 1.64041666667 | 15787 |
| 014296 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:21am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593949.3 | 509490.1 | 30283 | 1.64041666667 | 14296 |
| 014794 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:22am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593950.2 | 509491.7 | 30285 | 1.64041666667 | 14794 |
| 013328 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:23am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593950.5 | 509494.3 | 30287 | 1.64041666667 | 13328 |
| 012032 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:24am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593951.3 | 509496.3 | 30289 | 1.64041666667 | 12032 |
| 012098 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:25am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593951.6 | 509498.7 | 30291 | 1.64041666667 | 12098 |
| 013224 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:26am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593952.8 | 509500.3 | 30293 | 1.64041666667 | 13224 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:27am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593953.9 | 509503.2 | 30295 | 1.64041666667 | 14556 |
| 013899 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:28am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593955.6 | 509504.5 | 30297 | 1.64041666667 | 13899 |
| 012204 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:29am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593957.0 | 509506.6 | 30299 | 1.64041666667 | 12204 |
| 014121 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:30am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593959.1 | 509508.0 | 30301 | 1.64041666667 | 14121 |
| 012560 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:31am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593961.2 | 509509.8 | 30303 | 1.64041666667 | 12560 |
| 012890 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:32am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593963.2 | 509510.8 | 30305 | 1.64041666667 | 12890 |
| 013392 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:33am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593965.1 | 509512.6 | 30307 | 1.64041666667 | 13392 |
| 012558 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:34am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593966.9 | 509513.6 | 30309 | 1.64041666667 | 12558 |
| 012499 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:35am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593969.0 | 509515.0 | 30311 | 1.64041666667 | 12499 |
| 015754 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:36am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593970.7 | 509516.0 | 30313 | 1.64041666667 | 15754 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012428 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:37am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593972.3 | 509518.0 | 30315 | 1.64041666667 | 12428 |
| 011297 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:38am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593973.6 | 509519.4 | 30317 | 1.64041666667 | 11297 |
| 010954 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:39am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593975.0 | 509521.1 | 30319 | 1.64041666667 | 10954 |
| 012098 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:40am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593976.7 | 509522.2 | 30321 | 1.64041666667 | 12098 |
| 011484 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:41am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593979.4 | 509523.5 | 30323 | 1.64041666667 | 11484 |
| 014091 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:42am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593981.4 | 509524.6 | 30325 | 1.64041666667 | 14091 |
| 014202 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:43am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593983.4 | 509525.6 | 30327 | 1.64041666667 | 14202 |
| 012610 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:44am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593985.4 | 509526.6 | 30329 | 1.64041666667 | 12610 |
| 013022 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:45am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593987.4 | 509526.8 | 30331 | 1.64041666667 | 13022 |
| 013185 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:46am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593988.2 | 509526.5 | 30333 | 1.64041666667 | 13185 |
| 012596 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:47am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593988.6 | 509525.4 | 30335 | 1.64041666667 | 12596 |
| 012779 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:48am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593989.1 | 509523.7 | 30337 | 1.64041666667 | 12779 |
| 014235 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:49am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593989.4 | 509521.4 | 30339 | 1.64041666667 | 14235 |
| 012378 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:50am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593990.5 | 509519.4 | 30341 | 1.64041666667 | 12378 |
| 011944 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:51am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593991.2 | 509516.9 | 30343 | 1.64041666667 | 11944 |
| 013186 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:52am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593992.3 | 509515.0 | 30345 | 1.64041666667 | 13186 |
| 013346 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:53am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593993.2 | 509512.6 | 30347 | 1.64041666667 | 13346 |
| 011826 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:54am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593994.2 | 509510.6 | 30349 | 1.64041666667 | 11826 |
| 012976 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:55am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593994.8 | 509507.7 | 30351 | 1.64041666667 | 12976 |
| 015604 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:56am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593995.7 | 509505.8 | 30353 | 1.64041666667 | 15604 |
| 014311 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:57am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593996.1 | 509503.2 | 30355 | 1.64041666667 | 14311 |
| 012367 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:58am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593997.4 | 509501.6 | 30357 | 1.64041666667 | 12367 |
| 012302 | 0 | GeoXH 6000 | 08/18/2015 | 10:34:59am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593998.3 | 509499.2 | 30359 | 1.64041666667 | 12302 |
| 012645 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:00am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593999.2 | 509497.6 | 30361 | 1.64041666667 | 12645 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:01am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594000.6 | 509494.7 | 30363 | 1.64041666667 | 14591 |
| 016068 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:02am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594001.6 | 509492.5 | 30365 | 1.64041666667 | 16068 |
| 015717 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:03am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594002.8 | 509489.4 | 30367 | 1.64041666667 | 15717 |
| 018839 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:04am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594003.2 | 509487.0 | 30369 | 1.64041666667 | 18839 |
| 017970 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:05am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594003.9 | 509484.6 | 30371 | 1.64041666667 | 17970 |
| 019102 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:06am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594003.9 | 509482.7 | 30373 | 1.64041666667 | 19102 |
| 019025 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:07am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594003.9 | 509480.6 | 30375 | 1.64041666667 | 19025 |
| 018826 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:08am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594003.8 | 509478.7 | 30377 | 1.64041666667 | 18826 |
| 021836 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:09am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594004.9 | 509476.8 | 30379 | 1.64041666667 | 21836 |
| 016679 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:10am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594005.7 | 509475.2 | 30381 | 1.64041666667 | 16679 |
| 016020 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:11am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594007.7 | 509473.2 | 30383 | 1.64041666667 | 16020 |
| 014985 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:12am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594008.5 | 509471.5 | 30385 | 1.64041666667 | 14985 |
| 015146 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:13am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594010.1 | 509469.5 | 30387 | 1.64041666667 | 15146 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:14am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594010.9 | 509467.4 | 30389 | 1.64041666667 | 14556 |
| 014229 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:15am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594012.7 | 509465.3 | 30391 | 1.64041666667 | 14229 |
| 012107 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:16am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594013.4 | 509463.4 | 30393 | 1.64041666667 | 12107 |
| 013466 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:17am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594014.7 | 509461.1 | 30395 | 1.64041666667 | 13466 |
| 014016 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:18am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1594015.4 | 509458.8 | 30397 | 1.64041666667 | 14016 |
| 012534 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:19am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594017.2 | 509456.9 | 30399 | 1.64041666667 | 12534 |
| 014593 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:20am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594018.3 | 509455.1 | 30401 | 1.64041666667 | 14593 |
| 013908 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:21am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594019.7 | 509453.1 | 30403 | 1.64041666667 | 13908 |
| 015147 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:22am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594020.8 | 509451.0 | 30405 | 1.64041666667 | 15147 |
| 013356 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:23am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594022.0 | 509448.9 | 30407 | 1.64041666667 | 13356 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:24am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594023.4 | 509446.7 | 30409 | 1.64041666667 | 13038 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013779 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:25am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594024.7 | 509444.8 | 30411 | 1.64041666667 | 13779 |
| 014305 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:26am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594026.1 | 509443.1 | 30413 | 1.64041666667 | 14305 |
| 014136 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:27am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594027.4 | 509440.9 | 30415 | 1.64041666667 | 14136 |
| 017004 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:28am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594028.7 | 509438.8 | 30417 | 1.64041666667 | 17004 |
| 013821 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:29am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594029.8 | 509436.5 | 30419 | 1.64041666667 | 13821 |
| 014195 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:30am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594031.5 | 509434.6 | 30421 | 1.64041666667 | 14195 |
| 016148 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:31am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594032.6 | 509432.1 | 30423 | 1.64041666667 | 16148 |
| 014777 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:32am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594033.9 | 509429.6 | 30425 | 1.64041666667 | 14777 |
| 014794 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:33am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594033.0 | 509428.1 | 30427 | 1.64041666667 | 14794 |
| 015248 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:34am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594031.5 | 509427.3 | 30429 | 1.64041666667 | 15248 |
| 016172 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:35am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594029.5 | 509427.7 | 30431 | 1.64041666667 | 16172 |
| 015563 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:36am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594028.4 | 509429.1 | 30433 | 1.64041666667 | 15563 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:37am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594026.7 | 509430.9 | 30435 | 1.64041666667 | 14210 |
| 014862 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:38am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594025.7 | 509433.1 | 30437 | 1.64041666667 | 14862 |
| 013225 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:39am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594023.9 | 509435.2 | 30439 | 1.64041666667 | 13225 |
| 013926 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:40am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594022.3 | 509437.3 | 30441 | 1.64041666667 | 13926 |
| 012991 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:41am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594020.7 | 509439.8 | 30443 | 1.64041666667 | 12991 |
| 013147 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:42am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594019.1 | 509441.8 | 30445 | 1.64041666667 | 13147 |
| 012737 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:43am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594017.9 | 509444.7 | 30447 | 1.64041666667 | 12737 |
| 013414 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:44am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594016.6 | 509446.6 | 30449 | 1.64041666667 | 13414 |
| 013763 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:45am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594015.3 | 509449.1 | 30451 | 1.64041666667 | 13763 |
| 013371 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:46am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594014.0 | 509451.0 | 30453 | 1.64041666667 | 13371 |
| 013992 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:47am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594012.8 | 509453.7 | 30455 | 1.64041666667 | 13992 |
| 014928 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:48am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594011.7 | 509455.9 | 30457 | 1.64041666667 | 14928 |
| 014262 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:49am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594010.3 | 509458.2 | 30459 | 1.64041666667 | 14262 |
| 015535 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:50am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594009.2 | 509460.8 | 30461 | 1.64041666667 | 15535 |
| 017054 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:51am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594008.0 | 509463.4 | 30463 | 1.64041666667 | 17054 |
| 014103 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:52am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594007.2 | 509465.9 | 30465 | 1.64041666667 | 14103 |
| 015735 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:53am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594005.4 | 509468.6 | 30467 | 1.64041666667 | 15735 |
| 016353 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:54am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594004.5 | 509471.0 | 30469 | 1.64041666667 | 16353 |
| 019388 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:55am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594003.0 | 509473.3 | 30471 | 1.64041666667 | 19388 |
| 018587 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:56am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594002.0 | 509475.7 | 30473 | 1.64041666667 | 18587 |
| 022466 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:57am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594001.2 | 509478.6 | 30475 | 1.64041666667 | 22466 |
| 021936 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:58am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593999.9 | 509480.8 | 30477 | 1.64041666667 | 21936 |
| 020214 | 0 | GeoXH 6000 | 08/18/2015 | 10:35:59am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593999.7 | 509483.0 | 30479 | 1.64041666667 | 20214 |
| 018867 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:00am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593999.7 | 509484.0 | 30481 | 1.64041666667 | 18867 |
| 019173 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:01am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594000.1 | 509483.4 | 30483 | 1.64041666667 | 19173 |
| 019013 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:02am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594000.2 | 509483.4 | 30485 | 1.64041666667 | 19013 |
| 018463 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:03am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594000.1 | 509483.4 | 30487 | 1.64041666667 | 18463 |
| 018716 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:04am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594000.0 | 509483.6 | 30489 | 1.64041666667 | 18716 |
| 017939 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:05am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1593999.8 | 509483.8 | 30491 | 1.64041666667 | 17939 |
| 020564 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:06am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593999.6 | 509484.2 | 30493 | 1.64041666667 | 20564 |
| 022751 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:07am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593998.9 | 509485.0 | 30495 | 1.64041666667 | 22751 |
| 022955 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:08am | Sensor | 1797-S0030-868-G-TJV | 6800.9 | 1593999.1 | 509484.8 | 30497 | 1.64041666667 | 22955 |
| 020599 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:09am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593998.8 | 509485.0 | 30499 | 1.64041666667 | 20599 |
| 021409 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:10am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593999.4 | 509484.7 | 30501 | 1.64041666667 | 21409 |
| 019662 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:11am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594000.0 | 509483.3 | 30503 | 1.64041666667 | 19662 |
| 020425 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:12am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593999.9 | 509483.2 | 30505 | 1.64041666667 | 20425 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 018486 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:13am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594000.0 | 509484.9 | 30507 | 1.64041666667 | 18486 |
| 015241 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:14am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593999.0 | 509486.9 | 30509 | 1.64041666667 | 15241 |
| 013890 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:15am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593997.5 | 509489.6 | 30511 | 1.64041666667 | 13890 |
| 014812 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:16am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593996.0 | 509491.2 | 30513 | 1.64041666667 | 14812 |
| 013663 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:17am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593994.6 | 509493.5 | 30515 | 1.64041666667 | 13663 |
| 015296 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:18am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593994.1 | 509495.0 | 30517 | 1.64041666667 | 15296 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:19am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593993.5 | 509497.3 | 30519 | 1.64041666667 | 14324 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:20am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593992.6 | 509500.1 | 30521 | 1.64041666667 | 14081 |
| 013960 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:21am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593990.8 | 509502.6 | 30523 | 1.64041666667 | 13960 |
| 013450 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:22am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593990.1 | 509504.9 | 30525 | 1.64041666667 | 13450 |
| 013682 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:23am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593988.9 | 509507.4 | 30527 | 1.64041666667 | 13682 |
| 013170 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:24am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593987.9 | 509510.0 | 30529 | 1.64041666667 | 13170 |
| 012592 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:25am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593986.7 | 509512.6 | 30531 | 1.64041666667 | 12592 |
| 013018 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:26am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593985.2 | 509515.3 | 30533 | 1.64041666667 | 13018 |
| 013304 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:27am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593984.2 | 509518.5 | 30535 | 1.64041666667 | 13304 |
| 012866 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:28am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593982.6 | 509520.7 | 30537 | 1.64041666667 | 12866 |
| 012306 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:29am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593981.2 | 509523.5 | 30539 | 1.64041666667 | 12306 |
| 013036 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:30am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593979.5 | 509525.3 | 30541 | 1.64041666667 | 13036 |
| 012499 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:31am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593977.9 | 509528.0 | 30543 | 1.64041666667 | 12499 |
| 014494 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:32am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593976.8 | 509530.6 | 30545 | 1.64041666667 | 14494 |
| 013343 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:33am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593974.9 | 509533.3 | 30547 | 1.64041666667 | 13343 |
| 015816 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:34am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593973.4 | 509535.1 | 30549 | 1.64041666667 | 15816 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:35am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593971.4 | 509535.4 | 30551 | 1.64041666667 | 13974 |
| 014743 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:36am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593969.5 | 509534.1 | 30553 | 1.64041666667 | 14743 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:37am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593969.5 | 509532.3 | 30555 | 1.64041666667 | 13436 |
| 014579 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:38am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593970.0 | 509530.2 | 30557 | 1.64041666667 | 14579 |
| 012284 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:39am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593971.7 | 509527.7 | 30559 | 1.64041666667 | 12284 |
| 012581 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:40am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593972.6 | 509525.6 | 30561 | 1.64041666667 | 12581 |
| 013495 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:41am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593974.0 | 509523.1 | 30563 | 1.64041666667 | 13495 |
| 014083 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:42am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593975.4 | 509521.1 | 30565 | 1.64041666667 | 14083 |
| 012431 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:43am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593977.2 | 509518.4 | 30567 | 1.64041666667 | 12431 |
| 013187 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:44am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593978.7 | 509516.1 | 30569 | 1.64041666667 | 13187 |
| 012056 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:45am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593979.6 | 509513.5 | 30571 | 1.64041666667 | 12056 |
| 012824 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:46am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593980.7 | 509511.8 | 30573 | 1.64041666667 | 12824 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:47am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593981.7 | 509509.4 | 30575 | 1.64041666667 | 14246 |
| 013131 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:48am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593982.6 | 509507.1 | 30577 | 1.64041666667 | 13131 |
| 013062 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:49am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593983.3 | 509504.3 | 30579 | 1.64041666667 | 13062 |
| 011725 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:50am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593984.3 | 509502.3 | 30581 | 1.64041666667 | 11725 |
| 012711 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:51am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593985.6 | 509499.8 | 30583 | 1.64041666667 | 12711 |
| 012777 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:52am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593986.7 | 509497.7 | 30585 | 1.64041666667 | 12777 |
| 013574 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:53am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593988.4 | 509494.9 | 30587 | 1.64041666667 | 13574 |
| 012423 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:54am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593989.2 | 509492.1 | 30589 | 1.64041666667 | 12423 |
| 013335 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:55am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593990.7 | 509489.3 | 30591 | 1.64041666667 | 13335 |
| 015213 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:56am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593991.3 | 509486.9 | 30593 | 1.64041666667 | 15213 |
| 014723 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:57am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593992.6 | 509484.3 | 30595 | 1.64041666667 | 14723 |
| 015231 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:58am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593993.4 | 509481.9 | 30597 | 1.64041666667 | 15231 |
| 015567 | 0 | GeoXH 6000 | 08/18/2015 | 10:36:59am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593994.8 | 509479.3 | 30599 | 1.64041666667 | 15567 |
| 016424 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:00am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593995.8 | 509476.9 | 30601 | 1.64041666667 | 16424 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017608 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:01am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593997.1 | 509473.8 | 30603 | 1.64041666667 | 17608 |
| 017662 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:02am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593998.4 | 509471.2 | 30605 | 1.64041666667 | 17662 |
| 020075 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:03am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593999.1 | 509468.6 | 30607 | 1.64041666667 | 20075 |
| 018578 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:04am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1593999.9 | 509466.3 | 30609 | 1.64041666667 | 18578 |
| 016764 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:05am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1594000.1 | 509463.6 | 30611 | 1.64041666667 | 16764 |
| 016671 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:06am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594001.0 | 509461.5 | 30613 | 1.64041666667 | 16671 |
| 016557 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:07am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594002.2 | 509458.5 | 30615 | 1.64041666667 | 16557 |
| 015989 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:08am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594003.7 | 509456.4 | 30617 | 1.64041666667 | 15989 |
| 014827 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:09am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594005.5 | 509453.4 | 30619 | 1.64041666667 | 14827 |
| 014686 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:10am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594006.3 | 509451.0 | 30621 | 1.64041666667 | 14686 |
| 015281 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:11am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594007.9 | 509448.2 | 30623 | 1.64041666667 | 15281 |
| 015250 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:12am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594008.5 | 509445.9 | 30625 | 1.64041666667 | 15250 |
| 015062 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:13am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594009.8 | 509443.6 | 30627 | 1.64041666667 | 15062 |
| 015645 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:14am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594010.6 | 509441.3 | 30629 | 1.64041666667 | 15645 |
| 013361 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:15am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594012.1 | 509439.0 | 30631 | 1.64041666667 | 13361 |
| 012940 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:16am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594013.3 | 509436.5 | 30633 | 1.64041666667 | 12940 |
| 012925 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:17am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594014.9 | 509433.9 | 30635 | 1.64041666667 | 12925 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:18am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594017.1 | 509431.8 | 30637 | 1.64041666667 | 13491 |
| 014952 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:19am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594018.1 | 509429.5 | 30639 | 1.64041666667 | 14952 |
| 014388 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:20am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594018.9 | 509426.9 | 30641 | 1.64041666667 | 14388 |
| 013857 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:21am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594019.3 | 509423.8 | 30643 | 1.64041666667 | 13857 |
| 015344 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:22am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594020.6 | 509421.7 | 30645 | 1.64041666667 | 15344 |
| 013796 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:23am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594020.7 | 509420.3 | 30647 | 1.64041666667 | 13796 |
| 012419 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:24am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594020.3 | 509418.5 | 30649 | 1.64041666667 | 12419 |
| 014264 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:25am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594020.1 | 509418.0 | 30651 | 1.64041666667 | 14264 |
| 012176 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:26am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594019.8 | 509418.2 | 30653 | 1.64041666667 | 12176 |
| 013484 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:27am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594018.5 | 509418.6 | 30655 | 1.64041666667 | 13484 |
| 013961 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:28am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594016.8 | 509418.5 | 30657 | 1.64041666667 | 13961 |
| 014170 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:29am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594014.0 | 509418.2 | 30659 | 1.64041666667 | 14170 |
| 015452 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:30am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594012.0 | 509418.5 | 30661 | 1.64041666667 | 15452 |
| 014123 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:31am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594009.2 | 509418.7 | 30663 | 1.64041666667 | 14123 |
| 013460 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:32am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594006.9 | 509419.6 | 30665 | 1.64041666667 | 13460 |
| 013055 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:33am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594003.9 | 509420.5 | 30667 | 1.64041666667 | 13055 |
| 014603 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:34am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594001.6 | 509421.6 | 30669 | 1.64041666667 | 14603 |
| 013281 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:35am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593998.9 | 509421.9 | 30671 | 1.64041666667 | 13281 |
| 014810 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:36am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593996.0 | 509421.5 | 30673 | 1.64041666667 | 14810 |
| 013812 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:37am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593993.2 | 509421.7 | 30675 | 1.64041666667 | 13812 |
| 012453 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:38am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593990.8 | 509421.3 | 30677 | 1.64041666667 | 12453 |
| 013913 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:39am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593987.6 | 509421.2 | 30679 | 1.64041666667 | 13913 |
| 013438 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:40am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593985.4 | 509420.5 | 30681 | 1.64041666667 | 13438 |
| 014159 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:41am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593982.4 | 509419.6 | 30683 | 1.64041666667 | 14159 |
| 014100 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:42am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593979.6 | 509419.2 | 30685 | 1.64041666667 | 14100 |
| 013545 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:43am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593977.0 | 509418.8 | 30687 | 1.64041666667 | 13545 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:44am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593974.4 | 509419.1 | 30689 | 1.64041666667 | 13526 |
| 013761 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:45am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593971.8 | 509418.5 | 30691 | 1.64041666667 | 13761 |
| 014600 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:46am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593969.5 | 509418.8 | 30693 | 1.64041666667 | 14600 |
| 013250 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:47am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593967.4 | 509419.0 | 30695 | 1.64041666667 | 13250 |
| 013032 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:48am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593965.7 | 509419.9 | 30697 | 1.64041666667 | 13032 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013098 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:49am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593963.3 | 509420.9 | 30699 | 1.64041666667 | 13098 |
| 014254 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:50am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593961.7 | 509422.1 | 30701 | 1.64041666667 | 14254 |
| 014453 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:51am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593960.3 | 509422.4 | 30703 | 1.64041666667 | 14453 |
| 014203 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:52am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593958.5 | 509422.4 | 30705 | 1.64041666667 | 14203 |
| 014531 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:53am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593956.1 | 509422.3 | 30707 | 1.64041666667 | 14531 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:54am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593954.0 | 509422.0 | 30709 | 1.64041666667 | 14072 |
| 016178 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:55am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593952.3 | 509420.6 | 30711 | 1.64041666667 | 16178 |
| 014574 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:56am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593950.3 | 509419.5 | 30713 | 1.64041666667 | 14574 |
| 015193 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:57am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593949.0 | 509417.3 | 30715 | 1.64041666667 | 15193 |
| 014118 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:58am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593947.0 | 509416.4 | 30717 | 1.64041666667 | 14118 |
| 013549 | 0 | GeoXH 6000 | 08/18/2015 | 10:37:59am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593944.7 | 509415.6 | 30719 | 1.64041666667 | 13549 |
| 014007 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:00am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593942.6 | 509415.1 | 30721 | 1.64041666667 | 14007 |
| 013762 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:01am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593940.8 | 509413.9 | 30723 | 1.64041666667 | 13762 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:02am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593938.7 | 509412.7 | 30725 | 1.64041666667 | 14570 |
| 015342 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:03am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593936.1 | 509411.4 | 30727 | 1.64041666667 | 15342 |
| 015715 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:04am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593934.3 | 509410.0 | 30729 | 1.64041666667 | 15715 |
| 017099 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:05am | Sensor | 1797-S0030-868-G-TJV | 6805.8 | 1593931.9 | 509409.4 | 30731 | 1.64041666667 | 17099 |
| 015314 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:06am | Sensor | 1797-S0030-868-G-TJV | 6806.1 | 1593930.0 | 509408.6 | 30733 | 1.64041666667 | 15314 |
| 013188 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:07am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1593927.6 | 509408.2 | 30735 | 1.64041666667 | 13188 |
| 013557 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:08am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593925.9 | 509407.5 | 30737 | 1.64041666667 | 13557 |
| 013589 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:09am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593923.3 | 509406.8 | 30739 | 1.64041666667 | 13589 |
| 014857 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:10am | Sensor | 1797-S0030-868-G-TJV | 6806.9 | 1593921.5 | 509405.9 | 30741 | 1.64041666667 | 14857 |
| 013494 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:11am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593919.0 | 509405.5 | 30743 | 1.64041666667 | 13494 |
| 013873 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:12am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593917.0 | 509405.0 | 30745 | 1.64041666667 | 13873 |
| 014838 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:13am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593914.4 | 509405.0 | 30747 | 1.64041666667 | 14838 |
| 014749 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:14am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593912.3 | 509405.1 | 30749 | 1.64041666667 | 14749 |
| 012957 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:15am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593910.9 | 509405.1 | 30751 | 1.64041666667 | 12957 |
| 013109 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:16am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593910.8 | 509404.8 | 30753 | 1.64041666667 | 13109 |
| 013777 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:17am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593910.1 | 509403.3 | 30755 | 1.64041666667 | 13777 |
| 014124 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:18am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593909.9 | 509402.7 | 30757 | 1.64041666667 | 14124 |
| 014121 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:19am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593910.9 | 509401.5 | 30759 | 1.64041666667 | 14121 |
| 013430 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:20am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593912.1 | 509401.0 | 30761 | 1.64041666667 | 13430 |
| 014847 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:21am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593914.1 | 509400.1 | 30763 | 1.64041666667 | 14847 |
| 013762 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:22am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593916.0 | 509399.4 | 30765 | 1.64041666667 | 13762 |
| 015530 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:23am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593918.6 | 509399.1 | 30767 | 1.64041666667 | 15530 |
| 014862 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:24am | Sensor | 1797-S0030-868-G-TJV | 6807.2 | 1593920.9 | 509399.1 | 30769 | 1.64041666667 | 14862 |
| 014065 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:25am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593923.1 | 509400.0 | 30771 | 1.64041666667 | 14065 |
| 012516 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:26am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593925.2 | 509400.9 | 30773 | 1.64041666667 | 12516 |
| 015309 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:27am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593927.4 | 509402.7 | 30775 | 1.64041666667 | 15309 |
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:28am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593929.5 | 509403.8 | 30777 | 1.64041666667 | 13277 |
| 014539 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:29am | Sensor | 1797-S0030-868-G-TJV | 6806.1 | 1593931.5 | 509405.6 | 30779 | 1.64041666667 | 14539 |
| 014824 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:30am | Sensor | 1797-S0030-868-G-TJV | 6805.9 | 1593933.3 | 509406.6 | 30781 | 1.64041666667 | 14824 |
| 014206 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:31am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593935.0 | 509407.9 | 30783 | 1.64041666667 | 14206 |
| 014063 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:32am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1593936.6 | 509408.9 | 30785 | 1.64041666667 | 14063 |
| 014463 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:33am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593938.7 | 509410.5 | 30787 | 1.64041666667 | 14463 |
| 014505 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:34am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593940.6 | 509411.9 | 30789 | 1.64041666667 | 14505 |
| 015446 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:35am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593942.2 | 509414.0 | 30791 | 1.64041666667 | 15446 |
| 013881 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:36am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593944.5 | 509415.3 | 30793 | 1.64041666667 | 13881 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013790 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:37am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593946.6 | 509417.0 | 30795 | 1.64041666667 | 13790 |
| 015447 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:38am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593948.5 | 509418.5 | 30797 | 1.64041666667 | 15447 |
| 015562 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:39am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593950.3 | 509421.0 | 30799 | 1.64041666667 | 15562 |
| 014060 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:40am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593952.0 | 509422.5 | 30801 | 1.64041666667 | 14060 |
| 016415 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:41am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593953.7 | 509424.0 | 30803 | 1.64041666667 | 16415 |
| 013943 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:42am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593955.9 | 509424.7 | 30805 | 1.64041666667 | 13943 |
| 013596 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:43am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593958.8 | 509425.2 | 30807 | 1.64041666667 | 13596 |
| 013509 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:44am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593961.1 | 509425.3 | 30809 | 1.64041666667 | 13509 |
| 014447 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:45am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593964.7 | 509424.4 | 30811 | 1.64041666667 | 14447 |
| 013901 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:46am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593966.9 | 509424.2 | 30813 | 1.64041666667 | 13901 |
| 014035 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:47am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593969.7 | 509424.0 | 30815 | 1.64041666667 | 14035 |
| 014339 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:48am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593971.6 | 509424.9 | 30817 | 1.64041666667 | 14339 |
| 015104 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:49am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593974.4 | 509425.4 | 30819 | 1.64041666667 | 15104 |
| 013376 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:50am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593976.7 | 509426.2 | 30821 | 1.64041666667 | 13376 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:51am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593979.5 | 509426.0 | 30823 | 1.64041666667 | 13094 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:52am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593981.8 | 509426.1 | 30825 | 1.64041666667 | 13953 |
| 012728 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:53am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593984.9 | 509426.9 | 30827 | 1.64041666667 | 12728 |
| 012782 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:54am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593987.6 | 509427.6 | 30829 | 1.64041666667 | 12782 |
| 013065 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:55am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593990.4 | 509428.9 | 30831 | 1.64041666667 | 13065 |
| 013886 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:56am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593992.8 | 509429.3 | 30833 | 1.64041666667 | 13886 |
| 014031 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:57am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593995.5 | 509430.1 | 30835 | 1.64041666667 | 14031 |
| 014938 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:58am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593997.9 | 509430.6 | 30837 | 1.64041666667 | 14938 |
| 014684 | 0 | GeoXH 6000 | 08/18/2015 | 10:38:59am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594000.5 | 509431.7 | 30839 | 1.64041666667 | 14684 |
| 014621 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:00am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594002.8 | 509432.7 | 30841 | 1.64041666667 | 14621 |
| 013405 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:01am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594005.2 | 509433.7 | 30843 | 1.64041666667 | 13405 |
| 012711 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:02am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594007.8 | 509434.7 | 30845 | 1.64041666667 | 12711 |
| 016227 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:03am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594010.2 | 509435.9 | 30847 | 1.64041666667 | 16227 |
| 013507 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:04am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594012.0 | 509437.5 | 30849 | 1.64041666667 | 13507 |
| 014836 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:05am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594014.3 | 509438.6 | 30851 | 1.64041666667 | 14836 |
| 016099 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:06am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594016.8 | 509439.6 | 30853 | 1.64041666667 | 16099 |
| 014284 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:07am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594018.6 | 509438.9 | 30855 | 1.64041666667 | 14284 |
| 013891 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:08am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594020.3 | 509437.2 | 30857 | 1.64041666667 | 13891 |
| 014032 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:09am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1594021.4 | 509434.5 | 30859 | 1.64041666667 | 14032 |
| 015958 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:10am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594022.6 | 509432.4 | 30861 | 1.64041666667 | 15958 |
| 014399 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:11am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594023.1 | 509429.8 | 30863 | 1.64041666667 | 14399 |
| 014700 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:12am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594024.1 | 509427.9 | 30865 | 1.64041666667 | 14700 |
| 013485 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:13am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594024.7 | 509425.9 | 30867 | 1.64041666667 | 13485 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:14am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594025.2 | 509424.5 | 30869 | 1.64041666667 | 13631 |
| 014747 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:15am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594023.7 | 509423.6 | 30871 | 1.64041666667 | 14747 |
| 013826 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:16am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594022.8 | 509422.6 | 30873 | 1.64041666667 | 13826 |
| 013896 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:17am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594020.8 | 509422.2 | 30875 | 1.64041666667 | 13896 |
| 014454 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:18am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594019.2 | 509421.2 | 30877 | 1.64041666667 | 14454 |
| 014263 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:19am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594017.2 | 509420.9 | 30879 | 1.64041666667 | 14263 |
| 013496 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:20am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594015.5 | 509420.6 | 30881 | 1.64041666667 | 13496 |
| 013004 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:21am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594013.0 | 509420.7 | 30883 | 1.64041666667 | 13004 |
| 013811 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:22am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594011.0 | 509420.1 | 30885 | 1.64041666667 | 13811 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:23am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594008.6 | 509420.0 | 30887 | 1.64041666667 | 13742 |
| 012945 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:24am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594006.2 | 509419.7 | 30889 | 1.64041666667 | 12945 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013826 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:25am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594004.1 | 509420.5 | 30891 | 1.64041666667 | 13826 |
| 012696 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:26am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594002.1 | 509421.2 | 30893 | 1.64041666667 | 12696 |
| 014334 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:27am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593999.7 | 509422.3 | 30895 | 1.64041666667 | 14334 |
| 014293 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:28am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593997.7 | 509423.3 | 30897 | 1.64041666667 | 14293 |
| 015933 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:29am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593995.6 | 509424.0 | 30899 | 1.64041666667 | 15933 |
| 016373 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:30am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593994.3 | 509424.8 | 30901 | 1.64041666667 | 16373 |
| 014683 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:31am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593993.4 | 509426.2 | 30903 | 1.64041666667 | 14683 |
| 013571 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:32am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593993.0 | 509427.4 | 30905 | 1.64041666667 | 13571 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:33am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.9 | 509428.3 | 30907 | 1.64041666667 | 13742 |
| 013875 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:34am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.9 | 509428.5 | 30909 | 1.64041666667 | 13875 |
| 013878 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:35am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593992.8 | 509428.4 | 30911 | 1.64041666667 | 13878 |
| 013429 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:36am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.8 | 509428.3 | 30913 | 1.64041666667 | 13429 |
| 012537 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:37am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.8 | 509428.3 | 30915 | 1.64041666667 | 12537 |
| 014504 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:38am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.8 | 509428.3 | 30917 | 1.64041666667 | 14504 |
| 012746 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:39am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.9 | 509428.2 | 30919 | 1.64041666667 | 12746 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:40am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.9 | 509428.1 | 30921 | 1.64041666667 | 13453 |
| 013816 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:41am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593993.0 | 509428.1 | 30923 | 1.64041666667 | 13816 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:42am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593993.0 | 509428.0 | 30925 | 1.64041666667 | 14314 |
| 013088 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:43am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593992.8 | 509428.0 | 30927 | 1.64041666667 | 13088 |
| 013262 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:44am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.2 | 509428.6 | 30929 | 1.64041666667 | 13262 |
| 013575 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:45am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593991.8 | 509428.8 | 30931 | 1.64041666667 | 13575 |
| 013893 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:46am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593991.8 | 509428.9 | 30933 | 1.64041666667 | 13893 |
| 012533 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:47am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593991.5 | 509429.0 | 30935 | 1.64041666667 | 12533 |
| 015013 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:48am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593991.4 | 509429.3 | 30937 | 1.64041666667 | 15013 |
| 014343 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:49am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593990.7 | 509429.4 | 30939 | 1.64041666667 | 14343 |
| 014805 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:50am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593988.8 | 509428.9 | 30941 | 1.64041666667 | 14805 |
| 014141 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:51am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593987.2 | 509427.4 | 30943 | 1.64041666667 | 14141 |
| 013165 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:52am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593985.6 | 509426.0 | 30945 | 1.64041666667 | 13165 |
| 012741 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:53am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593984.1 | 509424.2 | 30947 | 1.64041666667 | 12741 |
| 014195 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:54am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593982.3 | 509423.1 | 30949 | 1.64041666667 | 14195 |
| 015128 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:55am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593980.5 | 509421.8 | 30951 | 1.64041666667 | 15128 |
| 014312 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:56am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593978.7 | 509420.8 | 30953 | 1.64041666667 | 14312 |
| 013778 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:57am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593976.9 | 509420.0 | 30955 | 1.64041666667 | 13778 |
| 015744 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:58am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593975.6 | 509418.6 | 30957 | 1.64041666667 | 15744 |
| 013356 | 0 | GeoXH 6000 | 08/18/2015 | 10:39:59am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593974.2 | 509417.2 | 30959 | 1.64041666667 | 13356 |
| 014469 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:00am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593972.9 | 509415.6 | 30961 | 1.64041666667 | 14469 |
| 014507 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:01am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593970.8 | 509414.3 | 30963 | 1.64041666667 | 14507 |
| 015146 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:02am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593969.9 | 509412.9 | 30965 | 1.64041666667 | 15146 |
| 015486 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:03am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593968.6 | 509411.5 | 30967 | 1.64041666667 | 15486 |
| 014791 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:04am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593966.9 | 509410.7 | 30969 | 1.64041666667 | 14791 |
| 015697 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:05am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593964.7 | 509410.2 | 30971 | 1.64041666667 | 15697 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:06am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593962.9 | 509409.8 | 30973 | 1.64041666667 | 13974 |
| 013363 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:07am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593960.6 | 509409.4 | 30975 | 1.64041666667 | 13363 |
| 013931 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:08am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593958.8 | 509408.8 | 30977 | 1.64041666667 | 13931 |
| 013142 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:09am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593956.6 | 509408.4 | 30979 | 1.64041666667 | 13142 |
| 013905 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:10am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593954.8 | 509408.0 | 30981 | 1.64041666667 | 13905 |
| 012836 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:11am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593952.9 | 509407.6 | 30983 | 1.64041666667 | 12836 |
| 014759 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:12am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593951.3 | 509406.8 | 30985 | 1.64041666667 | 14759 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:13am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593949.6 | 509405.6 | 30987 | 1.64041666667 | 13320 |
| 013260 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:14am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593948.1 | 509404.3 | 30989 | 1.64041666667 | 13260 |
| 016425 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:15am | Sensor | 1797-S0030-868-G-TJV | 6805.3 | 1593946.3 | 509403.8 | 30991 | 1.64041666667 | 16425 |
| 013196 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:16am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593944.6 | 509402.7 | 30993 | 1.64041666667 | 13196 |
| 014579 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:17am | Sensor | 1797-S0030-868-G-TJV | 6805.8 | 1593942.3 | 509401.7 | 30995 | 1.64041666667 | 14579 |
| 013994 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:18am | Sensor | 1797-S0030-868-G-TJV | 6806.1 | 1593940.8 | 509400.4 | 30997 | 1.64041666667 | 13994 |
| 015648 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:19am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593938.7 | 509399.3 | 30999 | 1.64041666667 | 15648 |
| 012972 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:20am | Sensor | 1797-S0030-868-G-TJV | 6806.6 | 1593937.0 | 509398.2 | 31001 | 1.64041666667 | 12972 |
| 014403 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:21am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593934.8 | 509397.3 | 31003 | 1.64041666667 | 14403 |
| 015930 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:22am | Sensor | 1797-S0030-868-G-TJV | 6806.9 | 1593933.1 | 509396.6 | 31005 | 1.64041666667 | 15930 |
| 014002 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:23am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593930.9 | 509395.9 | 31007 | 1.64041666667 | 14002 |
| 014240 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:24am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593928.9 | 509394.8 | 31009 | 1.64041666667 | 14240 |
| 013100 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:25am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593926.7 | 509394.2 | 31011 | 1.64041666667 | 13100 |
| 013235 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:26am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593924.9 | 509393.6 | 31013 | 1.64041666667 | 13235 |
| 013268 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:27am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593922.5 | 509392.8 | 31015 | 1.64041666667 | 13268 |
| 013817 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:28am | Sensor | 1797-S0030-868-G-TJV | 6808.0 | 1593921.0 | 509392.2 | 31017 | 1.64041666667 | 13817 |
| 012754 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:29am | Sensor | 1797-S0030-868-G-TJV | 6808.0 | 1593920.4 | 509392.2 | 31019 | 1.64041666667 | 12754 |
| 013148 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:30am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593919.0 | 509393.4 | 31021 | 1.64041666667 | 13148 |
| 015617 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:31am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593918.9 | 509394.6 | 31023 | 1.64041666667 | 15617 |
| 015574 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:32am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593919.1 | 509395.8 | 31025 | 1.64041666667 | 15574 |
| 015143 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:33am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593920.3 | 509397.0 | 31027 | 1.64041666667 | 15143 |
| 015216 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:34am | Sensor | 1797-S0030-868-G-TJV | 6807.4 | 1593920.7 | 509398.6 | 31029 | 1.64041666667 | 15216 |
| 014874 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:35am | Sensor | 1797-S0030-868-G-TJV | 6807.2 | 1593921.8 | 509400.0 | 31031 | 1.64041666667 | 14874 |
| 014668 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:36am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593922.3 | 509400.9 | 31033 | 1.64041666667 | 14668 |
| 013867 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:37am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593922.6 | 509401.3 | 31035 | 1.64041666667 | 13867 |
| 014176 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:38am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593922.9 | 509399.9 | 31037 | 1.64041666667 | 14176 |
| 015184 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:39am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593923.4 | 509397.4 | 31039 | 1.64041666667 | 15184 |
| 014386 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:40am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593923.8 | 509394.8 | 31041 | 1.64041666667 | 14386 |
| 013616 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:41am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593924.2 | 509391.9 | 31043 | 1.64041666667 | 13616 |
| 014144 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:42am | Sensor | 1797-S0030-868-G-TJV | 6808.0 | 1593925.0 | 509389.9 | 31045 | 1.64041666667 | 14144 |
| 015116 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:43am | Sensor | 1797-S0030-868-G-TJV | 6808.2 | 1593926.2 | 509387.4 | 31047 | 1.64041666667 | 15116 |
| 013679 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:44am | Sensor | 1797-S0030-868-G-TJV | 6808.2 | 1593927.4 | 509386.0 | 31049 | 1.64041666667 | 13679 |
| 012779 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:45am | Sensor | 1797-S0030-868-G-TJV | 6808.2 | 1593929.7 | 509385.3 | 31051 | 1.64041666667 | 12779 |
| 013305 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:46am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593931.4 | 509385.8 | 31053 | 1.64041666667 | 13305 |
| 014216 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:47am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593933.8 | 509386.9 | 31055 | 1.64041666667 | 14216 |
| 013634 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:48am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593935.3 | 509387.9 | 31057 | 1.64041666667 | 13634 |
| 016068 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:49am | Sensor | 1797-S0030-868-G-TJV | 6807.4 | 1593937.3 | 509389.0 | 31059 | 1.64041666667 | 16068 |
| 015474 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:50am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593939.1 | 509389.9 | 31061 | 1.64041666667 | 15474 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:51am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593941.2 | 509391.2 | 31063 | 1.64041666667 | 14609 |
| 014842 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:52am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593942.8 | 509392.3 | 31065 | 1.64041666667 | 14842 |
| 013610 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:53am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593944.5 | 509394.2 | 31067 | 1.64041666667 | 13610 |
| 014532 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:54am | Sensor | 1797-S0030-868-G-TJV | 6805.8 | 1593946.6 | 509395.4 | 31069 | 1.64041666667 | 14532 |
| 014133 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:55am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593948.8 | 509397.0 | 31071 | 1.64041666667 | 14133 |
| 012533 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:56am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593950.7 | 509397.7 | 31073 | 1.64041666667 | 12533 |
| 013333 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:57am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1593952.9 | 509398.8 | 31075 | 1.64041666667 | 13333 |
| 013263 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:58am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593955.1 | 509399.5 | 31077 | 1.64041666667 | 13263 |
| 014115 | 0 | GeoXH 6000 | 08/18/2015 | 10:40:59am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593957.0 | 509400.6 | 31079 | 1.64041666667 | 14115 |
| 013698 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:00am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593958.9 | 509401.6 | 31081 | 1.64041666667 | 13698 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013534 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:01am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593961.6 | 509403.2 | 31083 | 1.64041666667 | 13534 |
| 013223 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:02am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593964.1 | 509404.2 | 31085 | 1.64041666667 | 13223 |
| 013746 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:03am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593967.0 | 509405.0 | 31087 | 1.64041666667 | 13746 |
| 013786 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:04am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593968.9 | 509406.3 | 31089 | 1.64041666667 | 13786 |
| 015626 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:05am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593971.5 | 509407.5 | 31091 | 1.64041666667 | 15626 |
| 014706 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:06am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593973.4 | 509409.0 | 31093 | 1.64041666667 | 14706 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:07am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593975.7 | 509410.3 | 31095 | 1.64041666667 | 14266 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:08am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593977.9 | 509411.3 | 31097 | 1.64041666667 | 13766 |
| 013011 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:09am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593980.4 | 509412.3 | 31099 | 1.64041666667 | 13011 |
| 013573 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:10am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593982.4 | 509413.5 | 31101 | 1.64041666667 | 13573 |
| 012543 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:11am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593985.2 | 509414.6 | 31103 | 1.64041666667 | 12543 |
| 010995 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:12am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593987.2 | 509415.8 | 31105 | 1.64041666667 | 10995 |
| 012528 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:13am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593989.7 | 509417.1 | 31107 | 1.64041666667 | 12528 |
| 013842 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:14am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593992.2 | 509417.9 | 31109 | 1.64041666667 | 13842 |
| 013840 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:15am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593995.3 | 509419.1 | 31111 | 1.64041666667 | 13840 |
| 013460 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:16am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593997.9 | 509419.9 | 31113 | 1.64041666667 | 13460 |
| 013787 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:17am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.9 | 509421.1 | 31115 | 1.64041666667 | 13787 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:18am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594003.3 | 509421.7 | 31117 | 1.64041666667 | 13436 |
| 015329 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:19am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594005.9 | 509423.0 | 31119 | 1.64041666667 | 15329 |
| 013732 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:20am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594008.2 | 509423.7 | 31121 | 1.64041666667 | 13732 |
| 014173 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:21am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594010.9 | 509424.9 | 31123 | 1.64041666667 | 14173 |
| 014703 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:22am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594013.3 | 509425.5 | 31125 | 1.64041666667 | 14703 |
| 013665 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:23am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594015.7 | 509426.9 | 31127 | 1.64041666667 | 13665 |
| 012446 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:24am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594017.8 | 509428.4 | 31129 | 1.64041666667 | 12446 |
| 015171 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:25am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594019.9 | 509429.3 | 31131 | 1.64041666667 | 15171 |
| 015343 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:26am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594020.4 | 509430.3 | 31133 | 1.64041666667 | 15343 |
| 013405 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:27am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594019.5 | 509431.8 | 31135 | 1.64041666667 | 13405 |
| 013311 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:28am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594017.8 | 509433.3 | 31137 | 1.64041666667 | 13311 |
| 013407 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:29am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594016.2 | 509435.7 | 31139 | 1.64041666667 | 13407 |
| 014662 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:30am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594014.5 | 509437.3 | 31141 | 1.64041666667 | 14662 |
| 015545 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:31am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594013.0 | 509439.3 | 31143 | 1.64041666667 | 15545 |
| 014446 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:32am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594011.4 | 509440.8 | 31145 | 1.64041666667 | 14446 |
| 013781 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:33am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594009.2 | 509442.8 | 31147 | 1.64041666667 | 13781 |
| 014725 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:34am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594007.0 | 509444.7 | 31149 | 1.64041666667 | 14725 |
| 014391 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:35am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594004.9 | 509447.1 | 31151 | 1.64041666667 | 14391 |
| 015267 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:36am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594003.5 | 509449.6 | 31153 | 1.64041666667 | 15267 |
| 015307 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:37am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594001.5 | 509452.5 | 31155 | 1.64041666667 | 15307 |
| 016066 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:38am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594000.6 | 509454.8 | 31157 | 1.64041666667 | 16066 |
| 015746 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:39am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593998.9 | 509457.3 | 31159 | 1.64041666667 | 15746 |
| 015846 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:40am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593997.7 | 509459.3 | 31161 | 1.64041666667 | 15846 |
| 016441 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:41am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593996.1 | 509462.2 | 31163 | 1.64041666667 | 16441 |
| 015990 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:42am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593994.9 | 509464.7 | 31165 | 1.64041666667 | 15990 |
| 016237 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:43am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593993.9 | 509467.6 | 31167 | 1.64041666667 | 16237 |
| 015009 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:44am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593992.7 | 509470.3 | 31169 | 1.64041666667 | 15009 |
| 015182 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:45am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593992.0 | 509473.6 | 31171 | 1.64041666667 | 15182 |
| 016425 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:46am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593991.2 | 509475.9 | 31173 | 1.64041666667 | 16425 |
| 016556 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:47am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593990.6 | 509479.0 | 31175 | 1.64041666667 | 16556 |
| 015329 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:48am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593989.7 | 509481.4 | 31177 | 1.64041666667 | 15329 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014242 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:49am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593988.4 | 509484.4 | 31179 | 1.64041666667 | 14242 |
| 014300 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:50am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593987.6 | 509487.0 | 31181 | 1.64041666667 | 14300 |
| 014345 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:51am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593986.4 | 509489.9 | 31183 | 1.64041666667 | 14345 |
| 012436 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:52am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593985.6 | 509492.7 | 31185 | 1.64041666667 | 12436 |
| 012109 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:53am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593983.9 | 509495.1 | 31187 | 1.64041666667 | 12109 |
| 013347 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:54am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593982.8 | 509497.0 | 31189 | 1.64041666667 | 13347 |
| 012427 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:55am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593981.3 | 509499.3 | 31191 | 1.64041666667 | 12427 |
| 011476 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:56am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593980.4 | 509501.7 | 31193 | 1.64041666667 | 11476 |
| 011479 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:57am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593979.4 | 509504.5 | 31195 | 1.64041666667 | 11479 |
| 014359 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:58am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593978.1 | 509506.9 | 31197 | 1.64041666667 | 14359 |
| 013970 | 0 | GeoXH 6000 | 08/18/2015 | 10:41:59am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593976.8 | 509509.7 | 31199 | 1.64041666667 | 13970 |
| 013812 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:00am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593975.3 | 509512.0 | 31201 | 1.64041666667 | 13812 |
| 014103 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:01am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593974.4 | 509514.6 | 31203 | 1.64041666667 | 14103 |
| 013185 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:02am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593973.5 | 509516.8 | 31205 | 1.64041666667 | 13185 |
| 013346 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:03am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593972.3 | 509519.7 | 31207 | 1.64041666667 | 13346 |
| 012306 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:04am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593971.0 | 509521.6 | 31209 | 1.64041666667 | 12306 |
| 013096 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:05am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593970.0 | 509523.6 | 31211 | 1.64041666667 | 13096 |
| 013774 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:06am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593969.5 | 509524.8 | 31213 | 1.64041666667 | 13774 |
| 013313 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:07am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593969.2 | 509525.5 | 31215 | 1.64041666667 | 13313 |
| 014218 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:08am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593969.6 | 509525.9 | 31217 | 1.64041666667 | 14218 |
| 015404 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:09am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593969.7 | 509525.9 | 31219 | 1.64041666667 | 15404 |
| 014021 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:10am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593969.2 | 509526.3 | 31221 | 1.64041666667 | 14021 |
| 013195 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:11am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593969.0 | 509526.7 | 31223 | 1.64041666667 | 13195 |
| 014368 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:12am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593968.5 | 509526.1 | 31225 | 1.64041666667 | 14368 |
| 012982 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:13am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593967.3 | 509525.4 | 31227 | 1.64041666667 | 12982 |
| 013445 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:14am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593965.5 | 509524.8 | 31229 | 1.64041666667 | 13445 |
| 013711 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:15am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593963.4 | 509524.7 | 31231 | 1.64041666667 | 13711 |
| 013927 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:16am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593961.2 | 509524.1 | 31233 | 1.64041666667 | 13927 |
| 012512 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:17am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593958.8 | 509523.3 | 31235 | 1.64041666667 | 12512 |
| 012938 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:18am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593956.9 | 509522.4 | 31237 | 1.64041666667 | 12938 |
| 012444 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:19am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593954.4 | 509521.6 | 31239 | 1.64041666667 | 12444 |
| 012591 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:20am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593952.4 | 509520.6 | 31241 | 1.64041666667 | 12591 |
| 012357 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:21am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593949.8 | 509520.0 | 31243 | 1.64041666667 | 12357 |
| 013919 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:22am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593947.5 | 509519.5 | 31245 | 1.64041666667 | 13919 |
| 012600 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:23am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593944.6 | 509519.2 | 31247 | 1.64041666667 | 12600 |
| 012840 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:24am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593942.5 | 509518.8 | 31249 | 1.64041666667 | 12840 |
| 013440 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:25am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593939.9 | 509518.5 | 31251 | 1.64041666667 | 13440 |
| 013650 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:26am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593937.4 | 509518.6 | 31253 | 1.64041666667 | 13650 |
| 014512 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:27am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593934.6 | 509518.5 | 31255 | 1.64041666667 | 14512 |
| 014878 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:28am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593932.3 | 509518.5 | 31257 | 1.64041666667 | 14878 |
| 013889 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:29am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593930.2 | 509517.5 | 31259 | 1.64041666667 | 13889 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:30am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593928.8 | 509516.4 | 31261 | 1.64041666667 | 14092 |
| 013933 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:31am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593927.2 | 509514.5 | 31263 | 1.64041666667 | 13933 |
| 013473 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:32am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593925.4 | 509513.4 | 31265 | 1.64041666667 | 13473 |
| 013928 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:33am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593923.5 | 509512.0 | 31267 | 1.64041666667 | 13928 |
| 012782 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:34am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593921.5 | 509511.2 | 31269 | 1.64041666667 | 12782 |
| 012285 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:35am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593919.1 | 509510.0 | 31271 | 1.64041666667 | 12285 |
| 013961 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:36am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593917.1 | 509509.2 | 31273 | 1.64041666667 | 13961 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014410 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:37am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593915.0 | 509508.1 | 31275 | 1.64041666667 | 14410 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:38am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593913.0 | 509507.3 | 31277 | 1.64041666667 | 13442 |
| 012720 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:39am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593910.7 | 509506.2 | 31279 | 1.64041666667 | 12720 |
| 014700 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:40am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593908.7 | 509505.6 | 31281 | 1.64041666667 | 14700 |
| 014625 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:41am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593906.4 | 509505.0 | 31283 | 1.64041666667 | 14625 |
| 012446 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:42am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593904.5 | 509504.7 | 31285 | 1.64041666667 | 12446 |
| 012291 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:43am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593902.8 | 509503.7 | 31287 | 1.64041666667 | 12291 |
| 011563 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:44am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593901.6 | 509502.4 | 31289 | 1.64041666667 | 11563 |
| 011350 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:45am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593900.4 | 509500.4 | 31291 | 1.64041666667 | 11350 |
| 011807 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:46am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593899.2 | 509498.6 | 31293 | 1.64041666667 | 11807 |
| 012551 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:47am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593898.3 | 509496.4 | 31295 | 1.64041666667 | 12551 |
| 011958 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:48am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593897.9 | 509495.8 | 31297 | 1.64041666667 | 11958 |
| 012289 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:49am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593896.9 | 509495.5 | 31299 | 1.64041666667 | 12289 |
| 012492 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:50am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593896.1 | 509494.3 | 31301 | 1.64041666667 | 12492 |
| 011643 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:51am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593894.7 | 509493.8 | 31303 | 1.64041666667 | 11643 |
| 012960 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:52am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593893.3 | 509492.7 | 31305 | 1.64041666667 | 12960 |
| 013740 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:53am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593891.1 | 509491.2 | 31307 | 1.64041666667 | 13740 |
| 012945 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:54am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593889.1 | 509490.1 | 31309 | 1.64041666667 | 12945 |
| 011516 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:55am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593887.2 | 509489.9 | 31311 | 1.64041666667 | 11516 |
| 013139 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:56am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593886.5 | 509490.3 | 31313 | 1.64041666667 | 13139 |
| 010935 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:57am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593885.5 | 509489.8 | 31315 | 1.64041666667 | 10935 |
| 012993 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:58am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593883.9 | 509489.2 | 31317 | 1.64041666667 | 12993 |
| 012758 | 0 | GeoXH 6000 | 08/18/2015 | 10:42:59am | Sensor | 1797-S0030-868-G-TJV | 6802.1 | 1593882.1 | 509488.4 | 31319 | 1.64041666667 | 12758 |
| 011949 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:00am | Sensor | 1797-S0030-868-G-TJV | 6802.1 | 1593879.8 | 509488.2 | 31321 | 1.64041666667 | 11949 |
| 012017 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:01am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593876.9 | 509488.6 | 31323 | 1.64041666667 | 12017 |
| 012784 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:02am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593876.1 | 509489.7 | 31325 | 1.64041666667 | 12784 |
| 012946 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:03am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593875.5 | 509490.9 | 31327 | 1.64041666667 | 12946 |
| 012266 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:04am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593875.2 | 509491.3 | 31329 | 1.64041666667 | 12266 |
| 011916 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:05am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593876.5 | 509491.3 | 31331 | 1.64041666667 | 11916 |
| 013749 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:06am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593877.6 | 509492.0 | 31333 | 1.64041666667 | 13749 |
| 012737 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:07am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593879.4 | 509492.8 | 31335 | 1.64041666667 | 12737 |
| 013144 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:08am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593880.5 | 509493.6 | 31337 | 1.64041666667 | 13144 |
| 013546 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:09am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593881.3 | 509494.7 | 31339 | 1.64041666667 | 13546 |
| 013076 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:10am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593882.1 | 509495.1 | 31341 | 1.64041666667 | 13076 |
| 011879 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:11am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593882.3 | 509495.6 | 31343 | 1.64041666667 | 11879 |
| 013020 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:12am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593881.8 | 509496.9 | 31345 | 1.64041666667 | 13020 |
| 012825 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:13am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593882.0 | 509497.5 | 31347 | 1.64041666667 | 12825 |
| 013316 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:14am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593882.9 | 509497.7 | 31349 | 1.64041666667 | 13316 |
| 012449 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:15am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593882.7 | 509498.5 | 31351 | 1.64041666667 | 12449 |
| 013522 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:16am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593882.4 | 509498.5 | 31353 | 1.64041666667 | 13522 |
| 011360 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:17am | Sensor | 1797-S0030-868-G-TJV | 6801.8 | 1593881.9 | 509498.9 | 31355 | 1.64041666667 | 11360 |
| 011030 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:18am | Sensor | 1797-S0030-868-G-TJV | 6801.7 | 1593882.3 | 509499.7 | 31357 | 1.64041666667 | 11030 |
| 012507 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:19am | Sensor | 1797-S0030-868-G-TJV | 6801.8 | 1593883.3 | 509500.4 | 31359 | 1.64041666667 | 12507 |
| 012307 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:20am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593883.7 | 509501.0 | 31361 | 1.64041666667 | 12307 |
| 012526 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:21am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593883.6 | 509501.0 | 31363 | 1.64041666667 | 12526 |
| 017441 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:22am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593883.5 | 509502.6 | 31365 | 1.64041666667 | 17441 |
| 012760 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:23am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593883.0 | 509503.8 | 31367 | 1.64041666667 | 12760 |
| 014230 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:24am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593883.1 | 509504.9 | 31369 | 1.64041666667 | 14230 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013187 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:25am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593883.6 | 509505.2 | 31371 | 1.64041666667 | 13187 |
| 014636 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:26am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593885.1 | 509505.8 | 31373 | 1.64041666667 | 14636 |
| 013559 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:27am | Sensor | 1797-S0030-868-G-TJV | 6802.1 | 1593885.9 | 509506.6 | 31375 | 1.64041666667 | 13559 |
| 012450 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:28am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593885.6 | 509507.0 | 31377 | 1.64041666667 | 12450 |
| 013642 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:29am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593885.4 | 509507.1 | 31379 | 1.64041666667 | 13642 |
| 012740 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:30am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593885.4 | 509507.2 | 31381 | 1.64041666667 | 12740 |
| 013955 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:31am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593885.4 | 509507.4 | 31383 | 1.64041666667 | 13955 |
| 011468 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:32am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593886.9 | 509507.2 | 31385 | 1.64041666667 | 11468 |
| 011207 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:33am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593889.5 | 509507.1 | 31387 | 1.64041666667 | 11207 |
| 012251 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:34am | Sensor | 1797-S0030-868-G-TJV | 6802.1 | 1593891.7 | 509506.1 | 31389 | 1.64041666667 | 12251 |
| 012483 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:35am | Sensor | 1797-S0030-868-G-TJV | 6802.1 | 1593894.2 | 509504.7 | 31391 | 1.64041666667 | 12483 |
| 012120 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:36am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593895.6 | 509503.3 | 31393 | 1.64041666667 | 12120 |
| 011310 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:37am | Sensor | 1797-S0030-868-G-TJV | 6802.5 | 1593897.3 | 509501.7 | 31395 | 1.64041666667 | 11310 |
| 013207 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:38am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593898.6 | 509499.9 | 31397 | 1.64041666667 | 13207 |
| 011912 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:39am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593899.8 | 509497.6 | 31399 | 1.64041666667 | 11912 |
| 011918 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:40am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593900.5 | 509495.7 | 31401 | 1.64041666667 | 11918 |
| 012309 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:41am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593901.1 | 509492.8 | 31403 | 1.64041666667 | 12309 |
| 012257 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:42am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593901.7 | 509491.6 | 31405 | 1.64041666667 | 12257 |
| 012484 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:43am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593902.6 | 509490.3 | 31407 | 1.64041666667 | 12484 |
| 014911 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:44am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593903.5 | 509489.8 | 31409 | 1.64041666667 | 14911 |
| 012577 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:45am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593905.2 | 509490.0 | 31411 | 1.64041666667 | 12577 |
| 012864 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:46am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593906.5 | 509491.0 | 31413 | 1.64041666667 | 12864 |
| 012006 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:47am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593908.3 | 509492.9 | 31415 | 1.64041666667 | 12006 |
| 012541 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:48am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593910.1 | 509494.8 | 31417 | 1.64041666667 | 12541 |
| 012795 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:49am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593911.6 | 509497.3 | 31419 | 1.64041666667 | 12795 |
| 012408 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:50am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593912.8 | 509499.2 | 31421 | 1.64041666667 | 12408 |
| 012462 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:51am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593914.4 | 509501.9 | 31423 | 1.64041666667 | 12462 |
| 012325 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:52am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593915.9 | 509503.6 | 31425 | 1.64041666667 | 12325 |
| 013851 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:53am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593917.9 | 509505.5 | 31427 | 1.64041666667 | 13851 |
| 013932 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:54am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593919.9 | 509506.6 | 31429 | 1.64041666667 | 13932 |
| 013293 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:55am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593922.5 | 509507.9 | 31431 | 1.64041666667 | 13293 |
| 015173 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:56am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593924.8 | 509509.5 | 31433 | 1.64041666667 | 15173 |
| 014743 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:57am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593927.7 | 509511.3 | 31435 | 1.64041666667 | 14743 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:58am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593929.5 | 509512.8 | 31437 | 1.64041666667 | 13436 |
| 013949 | 0 | GeoXH 6000 | 08/18/2015 | 10:43:59am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593931.7 | 509514.2 | 31439 | 1.64041666667 | 13949 |
| 013297 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:00am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593933.8 | 509515.5 | 31441 | 1.64041666667 | 13297 |
| 012384 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:01am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593936.2 | 509516.9 | 31443 | 1.64041666667 | 12384 |
| 011796 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:02am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593938.0 | 509518.0 | 31445 | 1.64041666667 | 11796 |
| 012699 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:03am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593940.5 | 509518.7 | 31447 | 1.64041666667 | 12699 |
| 012294 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:04am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593943.1 | 509518.8 | 31449 | 1.64041666667 | 12294 |
| 011833 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:05am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593946.0 | 509519.4 | 31451 | 1.64041666667 | 11833 |
| 012108 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:06am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593948.7 | 509519.9 | 31453 | 1.64041666667 | 12108 |
| 013167 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:07am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593951.8 | 509520.6 | 31455 | 1.64041666667 | 13167 |
| 011571 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:08am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593954.4 | 509520.6 | 31457 | 1.64041666667 | 11571 |
| 012703 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:09am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593957.7 | 509520.5 | 31459 | 1.64041666667 | 12703 |
| 012145 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:10am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593960.8 | 509520.9 | 31461 | 1.64041666667 | 12145 |
| 013866 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:11am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593964.1 | 509521.1 | 31463 | 1.64041666667 | 13866 |
| 013096 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:12am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593966.6 | 509521.7 | 31465 | 1.64041666667 | 13096 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015814 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:13am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593969.5 | 509522.4 | 31467 | 1.64041666667 | 15814 |
| 013883 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:14am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593972.1 | 509523.1 | 31469 | 1.64041666667 | 13883 |
| 012771 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:15am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593973.4 | 509523.9 | 31471 | 1.64041666667 | 12771 |
| 012372 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:16am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593974.1 | 509523.1 | 31473 | 1.64041666667 | 12372 |
| 012723 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:17am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593974.6 | 509520.7 | 31475 | 1.64041666667 | 12723 |
| 011460 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:18am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593973.6 | 509519.1 | 31477 | 1.64041666667 | 11460 |
| 011925 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:19am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593971.3 | 509517.7 | 31479 | 1.64041666667 | 11925 |
| 011921 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:20am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593968.9 | 509516.6 | 31481 | 1.64041666667 | 11921 |
| 013510 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:21am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593965.8 | 509515.6 | 31483 | 1.64041666667 | 13510 |
| 013667 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:22am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593963.6 | 509514.7 | 31485 | 1.64041666667 | 13667 |
| 012356 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:23am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593961.0 | 509514.3 | 31487 | 1.64041666667 | 12356 |
| 012479 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:24am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593958.7 | 509513.9 | 31489 | 1.64041666667 | 12479 |
| 012300 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:25am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593956.2 | 509513.8 | 31491 | 1.64041666667 | 12300 |
| 012375 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:26am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593954.1 | 509513.6 | 31493 | 1.64041666667 | 12375 |
| 012783 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:27am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593951.5 | 509513.7 | 31495 | 1.64041666667 | 12783 |
| 011715 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:28am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593949.3 | 509513.5 | 31497 | 1.64041666667 | 11715 |
| 014448 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:29am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593946.9 | 509513.4 | 31499 | 1.64041666667 | 14448 |
| 013272 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:30am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593945.5 | 509513.1 | 31501 | 1.64041666667 | 13272 |
| 012708 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:31am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593943.7 | 509512.0 | 31503 | 1.64041666667 | 12708 |
| 013947 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:32am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593942.3 | 509510.6 | 31505 | 1.64041666667 | 13947 |
| 013536 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:33am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593940.1 | 509509.5 | 31507 | 1.64041666667 | 13536 |
| 012174 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:34am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593938.0 | 509508.9 | 31509 | 1.64041666667 | 12174 |
| 012013 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:35am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593935.4 | 509508.4 | 31511 | 1.64041666667 | 12013 |
| 012873 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:36am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593933.3 | 509508.2 | 31513 | 1.64041666667 | 12873 |
| 011918 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:37am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593930.4 | 509507.3 | 31515 | 1.64041666667 | 11918 |
| 012219 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:38am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593928.0 | 509506.5 | 31517 | 1.64041666667 | 12219 |
| 013855 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:39am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593925.7 | 509505.4 | 31519 | 1.64041666667 | 13855 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:40am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593923.4 | 509504.2 | 31521 | 1.64041666667 | 12853 |
| 014493 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:41am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593921.2 | 509503.0 | 31523 | 1.64041666667 | 14493 |
| 015563 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:42am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593919.0 | 509502.6 | 31525 | 1.64041666667 | 15563 |
| 014540 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:43am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593916.6 | 509502.0 | 31527 | 1.64041666667 | 14540 |
| 013895 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:44am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593914.6 | 509501.7 | 31529 | 1.64041666667 | 13895 |
| 014723 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:45am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593912.6 | 509500.5 | 31531 | 1.64041666667 | 14723 |
| 012651 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:46am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593911.0 | 509499.0 | 31533 | 1.64041666667 | 12651 |
| 014292 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:47am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593909.6 | 509496.9 | 31535 | 1.64041666667 | 14292 |
| 012693 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:48am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593908.6 | 509495.0 | 31537 | 1.64041666667 | 12693 |
| 011993 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:49am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593907.5 | 509492.6 | 31539 | 1.64041666667 | 11993 |
| 011698 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:50am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593906.0 | 509491.0 | 31541 | 1.64041666667 | 11698 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:51am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593903.1 | 509490.1 | 31543 | 1.64041666667 | 14324 |
| 013001 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:52am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593901.4 | 509489.2 | 31545 | 1.64041666667 | 13001 |
| 011410 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:53am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593898.6 | 509487.6 | 31547 | 1.64041666667 | 11410 |
| 012602 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:54am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593896.6 | 509486.0 | 31549 | 1.64041666667 | 12602 |
| 012360 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:55am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593893.8 | 509484.8 | 31551 | 1.64041666667 | 12360 |
| 011100 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:56am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593892.0 | 509483.6 | 31553 | 1.64041666667 | 11100 |
| 012435 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:57am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593889.9 | 509482.2 | 31555 | 1.64041666667 | 12435 |
| 012078 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:58am | Sensor | 1797-S0030-868-G-TJV | 6802.5 | 1593888.1 | 509481.2 | 31557 | 1.64041666667 | 12078 |
| 011269 | 0 | GeoXH 6000 | 08/18/2015 | 10:44:59am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593885.5 | 509480.0 | 31559 | 1.64041666667 | 11269 |
| 011007 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:00am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593883.9 | 509478.7 | 31561 | 1.64041666667 | 11007 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012142 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:01am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593881.9 | 509477.3 | 31563 | 1.64041666667 | 12142 |
| 012305 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:02am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593880.9 | 509476.3 | 31565 | 1.64041666667 | 12305 |
| 012436 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:03am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593880.4 | 509473.8 | 31567 | 1.64041666667 | 12436 |
| 012199 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:04am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593880.3 | 509472.0 | 31569 | 1.64041666667 | 12199 |
| 012289 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:05am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593880.2 | 509469.8 | 31571 | 1.64041666667 | 12289 |
| 011922 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:06am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593881.4 | 509469.0 | 31573 | 1.64041666667 | 11922 |
| 014380 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:07am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593883.5 | 509468.1 | 31575 | 1.64041666667 | 14380 |
| 012895 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:08am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593885.3 | 509466.8 | 31577 | 1.64041666667 | 12895 |
| 013663 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:09am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593887.9 | 509465.7 | 31579 | 1.64041666667 | 13663 |
| 013616 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:10am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593889.9 | 509465.7 | 31581 | 1.64041666667 | 13616 |
| 013334 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:11am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593892.2 | 509466.2 | 31583 | 1.64041666667 | 13334 |
| 013473 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:12am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593894.5 | 509466.6 | 31585 | 1.64041666667 | 13473 |
| 013208 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:13am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593896.8 | 509467.5 | 31587 | 1.64041666667 | 13208 |
| 014342 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:14am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593898.4 | 509468.9 | 31589 | 1.64041666667 | 14342 |
| 013215 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:15am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593900.3 | 509470.8 | 31591 | 1.64041666667 | 13215 |
| 014463 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:16am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593902.6 | 509472.3 | 31593 | 1.64041666667 | 14463 |
| 012916 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:17am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593904.4 | 509473.9 | 31595 | 1.64041666667 | 12916 |
| 013399 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:18am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593905.8 | 509475.4 | 31597 | 1.64041666667 | 13399 |
| 013219 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:19am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593907.2 | 509477.6 | 31599 | 1.64041666667 | 13219 |
| 013985 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:20am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593908.8 | 509479.4 | 31601 | 1.64041666667 | 13985 |
| 013396 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:21am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593910.8 | 509481.4 | 31603 | 1.64041666667 | 13396 |
| 013159 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:22am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593912.7 | 509482.6 | 31605 | 1.64041666667 | 13159 |
| 013489 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:23am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593914.8 | 509484.2 | 31607 | 1.64041666667 | 13489 |
| 014502 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:24am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593916.7 | 509485.3 | 31609 | 1.64041666667 | 14502 |
| 014335 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:25am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593918.8 | 509486.8 | 31611 | 1.64041666667 | 14335 |
| 013124 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:26am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593920.8 | 509488.2 | 31613 | 1.64041666667 | 13124 |
| 012611 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:27am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593922.9 | 509490.1 | 31615 | 1.64041666667 | 12611 |
| 013292 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:28am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593925.1 | 509492.0 | 31617 | 1.64041666667 | 13292 |
| 012173 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:29am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593927.6 | 509493.8 | 31619 | 1.64041666667 | 12173 |
| 013033 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:30am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593929.7 | 509495.6 | 31621 | 1.64041666667 | 13033 |
| 013548 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:31am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593932.2 | 509497.2 | 31623 | 1.64041666667 | 13548 |
| 012807 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:32am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593934.0 | 509498.9 | 31625 | 1.64041666667 | 12807 |
| 012261 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:33am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593936.3 | 509500.4 | 31627 | 1.64041666667 | 12261 |
| 011675 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:34am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593937.7 | 509501.7 | 31629 | 1.64041666667 | 11675 |
| 013148 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:35am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593939.8 | 509503.8 | 31631 | 1.64041666667 | 13148 |
| 012557 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:36am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593941.5 | 509505.6 | 31633 | 1.64041666667 | 12557 |
| 011029 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:37am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593944.0 | 509507.1 | 31635 | 1.64041666667 | 11029 |
| 014097 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:38am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593946.0 | 509508.4 | 31637 | 1.64041666667 | 14097 |
| 015374 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:39am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593948.0 | 509510.1 | 31639 | 1.64041666667 | 15374 |
| 012813 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:40am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593950.0 | 509511.5 | 31641 | 1.64041666667 | 12813 |
| 014333 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:41am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593952.6 | 509512.7 | 31643 | 1.64041666667 | 14333 |
| 013663 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:42am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593954.7 | 509513.4 | 31645 | 1.64041666667 | 13663 |
| 012086 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:43am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593957.4 | 509514.7 | 31647 | 1.64041666667 | 12086 |
| 012343 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:44am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593960.0 | 509515.6 | 31649 | 1.64041666667 | 12343 |
| 012702 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:45am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593962.8 | 509516.4 | 31651 | 1.64041666667 | 12702 |
| 013165 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:46am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593965.1 | 509516.9 | 31653 | 1.64041666667 | 13165 |
| 012981 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:47am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593967.7 | 509518.1 | 31655 | 1.64041666667 | 12981 |
| 011855 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:48am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593970.0 | 509519.1 | 31657 | 1.64041666667 | 11855 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:49am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593972.8 | 509520.1 | 31659 | 1.64041666667 | 13043 |
| 012801 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:50am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593974.7 | 509519.7 | 31661 | 1.64041666667 | 12801 |
| 014180 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:51am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593975.9 | 509518.2 | 31663 | 1.64041666667 | 14180 |
| 014195 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:52am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593976.2 | 509516.6 | 31665 | 1.64041666667 | 14195 |
| 014108 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:53am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593975.6 | 509514.5 | 31667 | 1.64041666667 | 14108 |
| 013127 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:54am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593974.7 | 509512.7 | 31669 | 1.64041666667 | 13127 |
| 012251 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:55am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593973.3 | 509510.6 | 31671 | 1.64041666667 | 12251 |
| 012993 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:56am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593972.0 | 509509.2 | 31673 | 1.64041666667 | 12993 |
| 012188 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:57am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593970.3 | 509507.0 | 31675 | 1.64041666667 | 12188 |
| 014027 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:58am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593968.6 | 509505.2 | 31677 | 1.64041666667 | 14027 |
| 012806 | 0 | GeoXH 6000 | 08/18/2015 | 10:45:59am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593967.0 | 509503.4 | 31679 | 1.64041666667 | 12806 |
| 012261 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:00am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593965.2 | 509502.3 | 31681 | 1.64041666667 | 12261 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:01am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593962.6 | 509501.2 | 31683 | 1.64041666667 | 13595 |
| 012818 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:02am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593960.5 | 509501.2 | 31685 | 1.64041666667 | 12818 |
| 012384 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:03am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593958.2 | 509501.5 | 31687 | 1.64041666667 | 12384 |
| 014466 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:04am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593956.4 | 509502.1 | 31689 | 1.64041666667 | 14466 |
| 015856 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:05am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593954.2 | 509502.6 | 31691 | 1.64041666667 | 15856 |
| 012574 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:06am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593952.1 | 509502.6 | 31693 | 1.64041666667 | 12574 |
| 013433 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:07am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593949.7 | 509502.5 | 31695 | 1.64041666667 | 13433 |
| 011818 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:08am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593947.7 | 509501.6 | 31697 | 1.64041666667 | 11818 |
| 012434 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:09am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593945.3 | 509500.2 | 31699 | 1.64041666667 | 12434 |
| 013638 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:10am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593943.2 | 509499.1 | 31701 | 1.64041666667 | 13638 |
| 013489 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:11am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593940.7 | 509498.8 | 31703 | 1.64041666667 | 13489 |
| 011652 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:12am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593938.7 | 509498.6 | 31705 | 1.64041666667 | 11652 |
| 011643 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:13am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593935.8 | 509498.4 | 31707 | 1.64041666667 | 11643 |
| 013440 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:14am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593933.7 | 509497.7 | 31709 | 1.64041666667 | 13440 |
| 013350 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:15am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593931.2 | 509497.0 | 31711 | 1.64041666667 | 13350 |
| 015607 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:16am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593928.8 | 509496.7 | 31713 | 1.64041666667 | 15607 |
| 015662 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:17am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593926.1 | 509497.4 | 31715 | 1.64041666667 | 15662 |
| 014025 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:18am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593923.9 | 509497.8 | 31717 | 1.64041666667 | 14025 |
| 015926 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:19am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593921.2 | 509498.1 | 31719 | 1.64041666667 | 15926 |
| 013671 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:20am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593919.1 | 509497.7 | 31721 | 1.64041666667 | 13671 |
| 013348 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:21am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593916.4 | 509496.9 | 31723 | 1.64041666667 | 13348 |
| 013897 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:22am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593914.4 | 509496.5 | 31725 | 1.64041666667 | 13897 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:23am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593911.7 | 509495.8 | 31727 | 1.64041666667 | 13974 |
| 014113 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:24am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593910.0 | 509495.4 | 31729 | 1.64041666667 | 14113 |
| 013698 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:25am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593907.6 | 509494.8 | 31731 | 1.64041666667 | 13698 |
| 012004 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:26am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593905.6 | 509494.6 | 31733 | 1.64041666667 | 12004 |
| 013201 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:27am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593903.7 | 509494.1 | 31735 | 1.64041666667 | 13201 |
| 011430 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:28am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593902.8 | 509493.3 | 31737 | 1.64041666667 | 11430 |
| 011827 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:29am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593901.2 | 509492.0 | 31739 | 1.64041666667 | 11827 |
| 011507 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:30am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593899.9 | 509490.6 | 31741 | 1.64041666667 | 11507 |
| 012836 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:31am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593898.3 | 509488.8 | 31743 | 1.64041666667 | 12836 |
| 013169 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:32am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593897.2 | 509487.5 | 31745 | 1.64041666667 | 13169 |
| 011272 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:33am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593896.1 | 509485.4 | 31747 | 1.64041666667 | 11272 |
| 011158 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:34am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593895.5 | 509483.4 | 31749 | 1.64041666667 | 11158 |
| 011429 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:35am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593895.0 | 509480.5 | 31751 | 1.64041666667 | 11429 |
| 012817 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:36am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593894.4 | 509477.9 | 31753 | 1.64041666667 | 12817 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013764 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:37am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593894.2 | 509475.3 | 31755 | 1.64041666667 | 13764 |
| 013881 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:38am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593893.5 | 509473.2 | 31757 | 1.64041666667 | 13881 |
| 014720 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:39am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593893.0 | 509471.0 | 31759 | 1.64041666667 | 14720 |
| 015200 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:40am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593893.6 | 509468.8 | 31761 | 1.64041666667 | 15200 |
| 013760 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:41am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593893.7 | 509467.9 | 31763 | 1.64041666667 | 13760 |
| 014300 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:42am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593893.7 | 509467.8 | 31765 | 1.64041666667 | 14300 |
| 014885 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:43am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593893.8 | 509467.8 | 31767 | 1.64041666667 | 14885 |
| 013411 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:44am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593894.7 | 509467.6 | 31769 | 1.64041666667 | 13411 |
| 015232 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:45am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593896.8 | 509467.8 | 31771 | 1.64041666667 | 15232 |
| 012958 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:46am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593899.1 | 509468.2 | 31773 | 1.64041666667 | 12958 |
| 013349 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:47am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593901.8 | 509468.7 | 31775 | 1.64041666667 | 13349 |
| 014647 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:48am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593904.1 | 509469.5 | 31777 | 1.64041666667 | 14647 |
| 013591 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:49am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593907.0 | 509470.6 | 31779 | 1.64041666667 | 13591 |
| 014017 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:50am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593909.1 | 509471.5 | 31781 | 1.64041666667 | 14017 |
| 014844 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:51am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593911.7 | 509472.1 | 31783 | 1.64041666667 | 14844 |
| 012681 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:52am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593913.9 | 509472.3 | 31785 | 1.64041666667 | 12681 |
| 013910 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:53am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593916.6 | 509472.4 | 31787 | 1.64041666667 | 13910 |
| 012387 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:54am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593918.1 | 509472.8 | 31789 | 1.64041666667 | 12387 |
| 013117 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:55am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593920.2 | 509474.0 | 31791 | 1.64041666667 | 13117 |
| 013089 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:56am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593921.3 | 509475.5 | 31793 | 1.64041666667 | 13089 |
| 012842 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:57am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593923.0 | 509476.7 | 31795 | 1.64041666667 | 12842 |
| 013500 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:58am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593924.7 | 509477.8 | 31797 | 1.64041666667 | 13500 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 10:46:59am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593926.5 | 509479.7 | 31799 | 1.64041666667 | 14655 |
| 012903 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:00am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593927.6 | 509481.5 | 31801 | 1.64041666667 | 12903 |
| 013576 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:01am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593929.2 | 509483.6 | 31803 | 1.64041666667 | 13576 |
| 013804 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:02am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593930.9 | 509485.4 | 31805 | 1.64041666667 | 13804 |
| 013921 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:03am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593932.3 | 509487.8 | 31807 | 1.64041666667 | 13921 |
| 013170 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:04am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593934.0 | 509489.9 | 31809 | 1.64041666667 | 13170 |
| 012352 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:05am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593936.2 | 509491.9 | 31811 | 1.64041666667 | 12352 |
| 013078 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:06am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593938.2 | 509493.3 | 31813 | 1.64041666667 | 13078 |
| 013739 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:07am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593940.4 | 509494.9 | 31815 | 1.64041666667 | 13739 |
| 012825 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:08am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593942.2 | 509495.8 | 31817 | 1.64041666667 | 12825 |
| 013286 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:09am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593944.8 | 509496.7 | 31819 | 1.64041666667 | 13286 |
| 013701 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:10am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593946.9 | 509497.4 | 31821 | 1.64041666667 | 13701 |
| 013955 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:11am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593949.2 | 509498.8 | 31823 | 1.64041666667 | 13955 |
| 013178 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:12am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593951.0 | 509500.2 | 31825 | 1.64041666667 | 13178 |
| 014094 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:13am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593953.3 | 509501.8 | 31827 | 1.64041666667 | 14094 |
| 013393 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:14am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593955.2 | 509503.3 | 31829 | 1.64041666667 | 13393 |
| 013758 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:15am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593957.4 | 509504.6 | 31831 | 1.64041666667 | 13758 |
| 013519 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:16am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593959.4 | 509506.0 | 31833 | 1.64041666667 | 13519 |
| 013159 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:17am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593961.1 | 509507.8 | 31835 | 1.64041666667 | 13159 |
| 012380 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:18am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593962.8 | 509509.8 | 31837 | 1.64041666667 | 12380 |
| 011645 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:19am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593965.3 | 509511.5 | 31839 | 1.64041666667 | 11645 |
| 013231 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:20am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593967.4 | 509512.6 | 31841 | 1.64041666667 | 13231 |
| 012097 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:21am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593969.5 | 509513.4 | 31843 | 1.64041666667 | 12097 |
| 011664 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:22am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593970.7 | 509513.6 | 31845 | 1.64041666667 | 11664 |
| 013896 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:23am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593971.5 | 509512.9 | 31847 | 1.64041666667 | 13896 |
| 013734 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:24am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593971.2 | 509511.4 | 31849 | 1.64041666667 | 13734 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012403 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:25am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593970.9 | 509509.4 | 31851 | 1.64041666667 | 12403 |
| 012131 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:26am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593970.9 | 509507.5 | 31853 | 1.64041666667 | 12131 |
| 012542 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:27am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593971.4 | 509504.9 | 31855 | 1.64041666667 | 12542 |
| 014085 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:28am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593972.0 | 509503.1 | 31857 | 1.64041666667 | 14085 |
| 011651 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:29am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593973.3 | 509501.0 | 31859 | 1.64041666667 | 11651 |
| 013773 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:30am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593974.7 | 509498.8 | 31861 | 1.64041666667 | 13773 |
| 014453 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:31am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593976.0 | 509496.3 | 31863 | 1.64041666667 | 14453 |
| 013123 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:32am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593976.9 | 509494.4 | 31865 | 1.64041666667 | 13123 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:33am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593977.7 | 509491.6 | 31867 | 1.64041666667 | 13301 |
| 012505 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:34am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593978.3 | 509489.2 | 31869 | 1.64041666667 | 12505 |
| 013596 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:35am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593978.6 | 509486.1 | 31871 | 1.64041666667 | 13596 |
| 012969 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:36am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593979.0 | 509484.0 | 31873 | 1.64041666667 | 12969 |
| 014192 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:37am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593979.8 | 509481.5 | 31875 | 1.64041666667 | 14192 |
| 013718 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:38am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593981.1 | 509479.6 | 31877 | 1.64041666667 | 13718 |
| 015459 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:39am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593982.6 | 509477.7 | 31879 | 1.64041666667 | 15459 |
| 016105 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:40am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593983.9 | 509476.1 | 31881 | 1.64041666667 | 16105 |
| 014736 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:41am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593985.3 | 509473.8 | 31883 | 1.64041666667 | 14736 |
| 013764 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:42am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593986.3 | 509471.6 | 31885 | 1.64041666667 | 13764 |
| 014031 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:43am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593987.3 | 509469.2 | 31887 | 1.64041666667 | 14031 |
| 015117 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:44am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593988.4 | 509467.2 | 31889 | 1.64041666667 | 15117 |
| 015479 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:45am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593989.8 | 509465.3 | 31891 | 1.64041666667 | 15479 |
| 014820 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:46am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593990.7 | 509463.2 | 31893 | 1.64041666667 | 14820 |
| 015345 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:47am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593991.2 | 509460.6 | 31895 | 1.64041666667 | 15345 |
| 016736 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:48am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593991.7 | 509458.0 | 31897 | 1.64041666667 | 16736 |
| 017174 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:49am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593992.5 | 509455.4 | 31899 | 1.64041666667 | 17174 |
| 014883 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:50am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593992.9 | 509453.1 | 31901 | 1.64041666667 | 14883 |
| 014940 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:51am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593993.2 | 509450.8 | 31903 | 1.64041666667 | 14940 |
| 016575 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:52am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593993.4 | 509448.5 | 31905 | 1.64041666667 | 16575 |
| 017643 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:53am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593994.0 | 509446.2 | 31907 | 1.64041666667 | 17643 |
| 016891 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:54am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593994.9 | 509444.2 | 31909 | 1.64041666667 | 16891 |
| 017272 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:55am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593996.1 | 509442.0 | 31911 | 1.64041666667 | 17272 |
| 015988 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:56am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593997.2 | 509440.0 | 31913 | 1.64041666667 | 15988 |
| 015487 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:57am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593998.4 | 509437.7 | 31915 | 1.64041666667 | 15487 |
| 013801 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:58am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593999.2 | 509435.7 | 31917 | 1.64041666667 | 13801 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 10:47:59am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594000.4 | 509433.1 | 31919 | 1.64041666667 | 13050 |
| 013492 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:00am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594001.3 | 509430.9 | 31921 | 1.64041666667 | 13492 |
| 013543 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:01am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594002.2 | 509428.2 | 31923 | 1.64041666667 | 13543 |
| 013346 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:02am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594003.1 | 509425.7 | 31925 | 1.64041666667 | 13346 |
| 012996 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:03am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594003.9 | 509422.9 | 31927 | 1.64041666667 | 12996 |
| 013869 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:04am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594004.5 | 509420.9 | 31929 | 1.64041666667 | 13869 |
| 014657 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:05am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594004.7 | 509418.4 | 31931 | 1.64041666667 | 14657 |
| 014074 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:06am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594003.6 | 509416.3 | 31933 | 1.64041666667 | 14074 |
| 013808 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:07am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594002.3 | 509414.7 | 31935 | 1.64041666667 | 13808 |
| 013202 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:08am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594001.6 | 509414.3 | 31937 | 1.64041666667 | 13202 |
| 013380 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:09am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594001.0 | 509414.9 | 31939 | 1.64041666667 | 13380 |
| 014175 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:10am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.0 | 509416.1 | 31941 | 1.64041666667 | 14175 |
| 012483 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:11am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593998.8 | 509417.6 | 31943 | 1.64041666667 | 12483 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:12am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593998.1 | 509419.2 | 31945 | 1.64041666667 | 13471 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013567 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:13am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593997.6 | 509421.6 | 31947 | 1.64041666667 | 13567 |
| 012332 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:14am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593997.1 | 509423.6 | 31949 | 1.64041666667 | 12332 |
| 013763 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:15am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593996.5 | 509426.0 | 31951 | 1.64041666667 | 13763 |
| 014780 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:16am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593995.8 | 509428.0 | 31953 | 1.64041666667 | 14780 |
| 011945 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:17am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593994.8 | 509430.4 | 31955 | 1.64041666667 | 11945 |
| 013546 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:18am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593994.1 | 509432.5 | 31957 | 1.64041666667 | 13546 |
| 014276 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:19am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593993.2 | 509435.0 | 31959 | 1.64041666667 | 14276 |
| 014879 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:20am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593992.5 | 509437.3 | 31961 | 1.64041666667 | 14879 |
| 013740 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:21am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593992.2 | 509439.6 | 31963 | 1.64041666667 | 13740 |
| 013755 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:22am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593991.9 | 509442.0 | 31965 | 1.64041666667 | 13755 |
| 015168 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:23am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593991.3 | 509444.8 | 31967 | 1.64041666667 | 15168 |
| 013722 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:24am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593991.0 | 509447.0 | 31969 | 1.64041666667 | 13722 |
| 014050 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:25am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593990.6 | 509449.3 | 31971 | 1.64041666667 | 14050 |
| 013652 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:26am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593989.6 | 509451.1 | 31973 | 1.64041666667 | 13652 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:27am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593988.1 | 509453.1 | 31975 | 1.64041666667 | 13043 |
| 013970 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:28am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593986.7 | 509454.8 | 31977 | 1.64041666667 | 13970 |
| 013632 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:29am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593985.2 | 509456.7 | 31979 | 1.64041666667 | 13632 |
| 014376 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:30am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593984.2 | 509458.4 | 31981 | 1.64041666667 | 14376 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:31am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593983.3 | 509461.0 | 31983 | 1.64041666667 | 13782 |
| 014365 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:32am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593982.6 | 509463.0 | 31985 | 1.64041666667 | 14365 |
| 014991 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:33am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593982.0 | 509465.6 | 31987 | 1.64041666667 | 14991 |
| 013917 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:34am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593981.5 | 509467.9 | 31989 | 1.64041666667 | 13917 |
| 014669 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:35am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593981.1 | 509470.4 | 31991 | 1.64041666667 | 14669 |
| 015277 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:36am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593980.6 | 509472.3 | 31993 | 1.64041666667 | 15277 |
| 015579 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:37am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593979.7 | 509474.8 | 31995 | 1.64041666667 | 15579 |
| 014094 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:38am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593978.9 | 509477.2 | 31997 | 1.64041666667 | 14094 |
| 013183 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:39am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593978.2 | 509479.6 | 31999 | 1.64041666667 | 13183 |
| 014786 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:40am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593978.1 | 509481.7 | 32001 | 1.64041666667 | 14786 |
| 013836 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:41am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593977.9 | 509484.3 | 32003 | 1.64041666667 | 13836 |
| 016569 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:42am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593977.3 | 509486.5 | 32005 | 1.64041666667 | 16569 |
| 013532 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:43am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593976.4 | 509488.9 | 32007 | 1.64041666667 | 13532 |
| 015383 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:44am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593975.6 | 509490.8 | 32009 | 1.64041666667 | 15383 |
| 015275 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:45am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593974.1 | 509493.0 | 32011 | 1.64041666667 | 15275 |
| 015009 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:46am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593972.4 | 509494.8 | 32013 | 1.64041666667 | 15009 |
| 015392 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:47am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593971.0 | 509497.0 | 32015 | 1.64041666667 | 15392 |
| 012968 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:48am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593970.6 | 509499.0 | 32017 | 1.64041666667 | 12968 |
| 011822 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:49am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593970.0 | 509501.6 | 32019 | 1.64041666667 | 11822 |
| 012105 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:50am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593968.9 | 509503.7 | 32021 | 1.64041666667 | 12105 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:51am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593967.1 | 509506.0 | 32023 | 1.64041666667 | 12236 |
| 011699 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:52am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593965.6 | 509508.3 | 32025 | 1.64041666667 | 11699 |
| 012465 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:53am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593964.3 | 509511.4 | 32027 | 1.64041666667 | 12465 |
| 012836 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:54am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593963.4 | 509513.6 | 32029 | 1.64041666667 | 12836 |
| 014129 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:55am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593962.3 | 509516.1 | 32031 | 1.64041666667 | 14129 |
| 012412 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:56am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593961.3 | 509518.4 | 32033 | 1.64041666667 | 12412 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:57am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593960.4 | 509521.0 | 32035 | 1.64041666667 | 12853 |
| 012663 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:58am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593959.3 | 509522.9 | 32037 | 1.64041666667 | 12663 |
| 011355 | 0 | GeoXH 6000 | 08/18/2015 | 10:48:59am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593957.4 | 509523.9 | 32039 | 1.64041666667 | 11355 |
| 013698 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:00am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593955.8 | 509523.2 | 32041 | 1.64041666667 | 13698 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012904 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:01am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593954.4 | 509521.5 | 32043 | 1.64041666667 | 12904 |
| 012766 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:02am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593953.8 | 509519.5 | 32045 | 1.64041666667 | 12766 |
| 013841 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:03am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593953.5 | 509517.2 | 32047 | 1.64041666667 | 13841 |
| 012640 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:04am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593953.1 | 509515.1 | 32049 | 1.64041666667 | 12640 |
| 013300 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:05am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593953.4 | 509512.3 | 32051 | 1.64041666667 | 13300 |
| 012415 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:06am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593954.0 | 509510.2 | 32053 | 1.64041666667 | 12415 |
| 013723 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:07am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593954.7 | 509507.9 | 32055 | 1.64041666667 | 13723 |
| 012641 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:08am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593955.3 | 509505.7 | 32057 | 1.64041666667 | 12641 |
| 015460 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:09am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593956.1 | 509503.3 | 32059 | 1.64041666667 | 15460 |
| 014215 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:10am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593956.8 | 509501.3 | 32061 | 1.64041666667 | 14215 |
| 011653 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:11am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593957.7 | 509499.6 | 32063 | 1.64041666667 | 11653 |
| 012123 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:12am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593958.8 | 509498.3 | 32065 | 1.64041666667 | 12123 |
| 012510 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:13am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593960.1 | 509496.2 | 32067 | 1.64041666667 | 12510 |
| 012397 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:14am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593960.8 | 509494.2 | 32069 | 1.64041666667 | 12397 |
| 012009 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:15am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593961.5 | 509492.1 | 32071 | 1.64041666667 | 12009 |
| 011342 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:16am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593962.0 | 509490.5 | 32073 | 1.64041666667 | 11342 |
| 013395 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:17am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593962.6 | 509488.4 | 32075 | 1.64041666667 | 13395 |
| 015438 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:18am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593963.3 | 509486.6 | 32077 | 1.64041666667 | 15438 |
| 014629 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:19am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593964.2 | 509484.6 | 32079 | 1.64041666667 | 14629 |
| 015447 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:20am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593965.1 | 509483.2 | 32081 | 1.64041666667 | 15447 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:21am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593966.7 | 509481.3 | 32083 | 1.64041666667 | 14092 |
| 014263 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:22am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593968.2 | 509479.6 | 32085 | 1.64041666667 | 14263 |
| 013465 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:23am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593969.8 | 509477.9 | 32087 | 1.64041666667 | 13465 |
| 013416 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:24am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593971.0 | 509476.3 | 32089 | 1.64041666667 | 13416 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:25am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593972.7 | 509474.1 | 32091 | 1.64041666667 | 13974 |
| 013183 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:26am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593973.7 | 509472.0 | 32093 | 1.64041666667 | 13183 |
| 015536 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:27am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593974.2 | 509469.5 | 32095 | 1.64041666667 | 15536 |
| 015014 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:28am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593974.7 | 509467.4 | 32097 | 1.64041666667 | 15014 |
| 016443 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:29am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593975.7 | 509465.1 | 32099 | 1.64041666667 | 16443 |
| 015660 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:30am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593976.6 | 509463.2 | 32101 | 1.64041666667 | 15660 |
| 017655 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:31am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593977.6 | 509460.9 | 32103 | 1.64041666667 | 17655 |
| 015303 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:32am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593978.8 | 509459.1 | 32105 | 1.64041666667 | 15303 |
| 017026 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:33am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593979.9 | 509456.6 | 32107 | 1.64041666667 | 17026 |
| 017006 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:34am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593981.3 | 509454.3 | 32109 | 1.64041666667 | 17006 |
| 019551 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:35am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593982.4 | 509451.9 | 32111 | 1.64041666667 | 19551 |
| 018748 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:36am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593982.8 | 509450.3 | 32113 | 1.64041666667 | 18748 |
| 017977 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:37am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593983.2 | 509448.6 | 32115 | 1.64041666667 | 17977 |
| 016884 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:38am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593983.8 | 509446.8 | 32117 | 1.64041666667 | 16884 |
| 015501 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:39am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593984.8 | 509444.6 | 32119 | 1.64041666667 | 15501 |
| 015155 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:40am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593986.3 | 509442.7 | 32121 | 1.64041666667 | 15155 |
| 015368 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:41am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593987.9 | 509440.7 | 32123 | 1.64041666667 | 15368 |
| 015422 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:42am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593988.8 | 509438.6 | 32125 | 1.64041666667 | 15422 |
| 013665 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:43am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593989.8 | 509436.1 | 32127 | 1.64041666667 | 13665 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:44am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593990.7 | 509434.1 | 32129 | 1.64041666667 | 14246 |
| 013641 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:45am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593991.8 | 509431.7 | 32131 | 1.64041666667 | 13641 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:46am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593992.5 | 509429.5 | 32133 | 1.64041666667 | 14570 |
| 013392 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:47am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593993.4 | 509426.9 | 32135 | 1.64041666667 | 13392 |
| 013158 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:48am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593994.3 | 509424.7 | 32137 | 1.64041666667 | 13158 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011899 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:49am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593995.5 | 509422.4 | 32139 | 1.64041666667 | 11899 |
| 012754 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:50am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593996.4 | 509420.1 | 32141 | 1.64041666667 | 12754 |
| 013088 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:51am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593996.5 | 509417.4 | 32143 | 1.64041666667 | 13088 |
| 017342 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:52am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593995.2 | 509415.3 | 32145 | 1.64041666667 | 17342 |
| 015135 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:53am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593992.8 | 509414.5 | 32147 | 1.64041666667 | 15135 |
| 014107 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:54am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593990.7 | 509415.6 | 32149 | 1.64041666667 | 14107 |
| 011888 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:55am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593988.5 | 509417.4 | 32151 | 1.64041666667 | 11888 |
| 011882 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:56am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593987.1 | 509419.0 | 32153 | 1.64041666667 | 11882 |
| 012780 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:57am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593986.0 | 509421.2 | 32155 | 1.64041666667 | 12780 |
| 015315 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:58am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593985.0 | 509423.2 | 32157 | 1.64041666667 | 15315 |
| 014928 | 0 | GeoXH 6000 | 08/18/2015 | 10:49:59am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593983.9 | 509425.6 | 32159 | 1.64041666667 | 14928 |
| 013362 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:00am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593983.0 | 509427.4 | 32161 | 1.64041666667 | 13362 |
| 013570 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:01am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593981.7 | 509429.7 | 32163 | 1.64041666667 | 13570 |
| 015032 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:02am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593980.2 | 509432.0 | 32165 | 1.64041666667 | 15032 |
| 015068 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:03am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593979.2 | 509434.8 | 32167 | 1.64041666667 | 15068 |
| 013217 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:04am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593978.5 | 509436.9 | 32169 | 1.64041666667 | 13217 |
| 013474 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:05am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593977.7 | 509439.4 | 32171 | 1.64041666667 | 13474 |
| 015968 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:06am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593977.1 | 509441.3 | 32173 | 1.64041666667 | 15968 |
| 015452 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:07am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593976.0 | 509443.7 | 32175 | 1.64041666667 | 15452 |
| 015773 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:08am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593975.1 | 509445.9 | 32177 | 1.64041666667 | 15773 |
| 013903 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:09am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593973.8 | 509448.3 | 32179 | 1.64041666667 | 13903 |
| 016016 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:10am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593972.8 | 509450.6 | 32181 | 1.64041666667 | 16016 |
| 016034 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:11am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593971.4 | 509453.3 | 32183 | 1.64041666667 | 16034 |
| 015078 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:12am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593970.5 | 509455.6 | 32185 | 1.64041666667 | 15078 |
| 015349 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:13am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593969.5 | 509458.4 | 32187 | 1.64041666667 | 15349 |
| 014667 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:14am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593969.1 | 509460.6 | 32189 | 1.64041666667 | 14667 |
| 015877 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:15am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593968.9 | 509463.1 | 32191 | 1.64041666667 | 15877 |
| 018609 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:16am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593968.4 | 509465.7 | 32193 | 1.64041666667 | 18609 |
| 016502 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:17am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593967.8 | 509468.3 | 32195 | 1.64041666667 | 16502 |
| 017775 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:18am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593966.9 | 509470.1 | 32197 | 1.64041666667 | 17775 |
| 017313 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:19am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593965.9 | 509472.5 | 32199 | 1.64041666667 | 17313 |
| 015428 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:20am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593964.7 | 509474.6 | 32201 | 1.64041666667 | 15428 |
| 015197 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:21am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593963.7 | 509477.3 | 32203 | 1.64041666667 | 15197 |
| 014269 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:22am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593962.8 | 509479.5 | 32205 | 1.64041666667 | 14269 |
| 013557 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:23am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593961.6 | 509481.8 | 32207 | 1.64041666667 | 13557 |
| 013169 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:24am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593960.5 | 509483.8 | 32209 | 1.64041666667 | 13169 |
| 016882 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:25am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593958.9 | 509486.4 | 32211 | 1.64041666667 | 16882 |
| 014540 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:26am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593957.5 | 509488.5 | 32213 | 1.64041666667 | 14540 |
| 014075 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:27am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593956.3 | 509491.2 | 32215 | 1.64041666667 | 14075 |
| 012137 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:28am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593955.5 | 509493.4 | 32217 | 1.64041666667 | 12137 |
| 013187 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:29am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593954.3 | 509496.1 | 32219 | 1.64041666667 | 13187 |
| 012536 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:30am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593953.5 | 509498.6 | 32221 | 1.64041666667 | 12536 |
| 012614 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:31am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593952.2 | 509501.3 | 32223 | 1.64041666667 | 12614 |
| 013833 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:32am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593951.5 | 509503.9 | 32225 | 1.64041666667 | 13833 |
| 013028 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:33am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593950.6 | 509506.9 | 32227 | 1.64041666667 | 13028 |
| 014477 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:34am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593950.0 | 509509.2 | 32229 | 1.64041666667 | 14477 |
| 012499 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:35am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593949.5 | 509511.8 | 32231 | 1.64041666667 | 12499 |
| 012394 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:36am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593948.9 | 509514.2 | 32233 | 1.64041666667 | 12394 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011648 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:37am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593948.4 | 509517.1 | 32235 | 1.64041666667 | 11648 |
| 012752 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:38am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593947.5 | 509519.0 | 32237 | 1.64041666667 | 12752 |
| 013748 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:39am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593945.4 | 509520.6 | 32239 | 1.64041666667 | 13748 |
| 013727 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:40am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593943.1 | 509520.7 | 32241 | 1.64041666667 | 13727 |
| 013181 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:41am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593941.6 | 509519.4 | 32243 | 1.64041666667 | 13181 |
| 011635 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:42am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593941.1 | 509517.8 | 32245 | 1.64041666667 | 11635 |
| 013109 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:43am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593941.6 | 509515.9 | 32247 | 1.64041666667 | 13109 |
| 014497 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:44am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593942.1 | 509513.7 | 32249 | 1.64041666667 | 14497 |
| 014064 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:45am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593942.8 | 509511.3 | 32251 | 1.64041666667 | 14064 |
| 012726 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:46am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593943.4 | 509509.0 | 32253 | 1.64041666667 | 12726 |
| 012571 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:47am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593944.3 | 509506.6 | 32255 | 1.64041666667 | 12571 |
| 013462 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:48am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593944.8 | 509504.6 | 32257 | 1.64041666667 | 13462 |
| 013325 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:49am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593945.2 | 509501.9 | 32259 | 1.64041666667 | 13325 |
| 014851 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:50am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593945.8 | 509499.4 | 32261 | 1.64041666667 | 14851 |
| 015862 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:51am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593946.3 | 509496.6 | 32263 | 1.64041666667 | 15862 |
| 014405 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:52am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593947.0 | 509494.1 | 32265 | 1.64041666667 | 14405 |
| 013321 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:53am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593947.4 | 509491.3 | 32267 | 1.64041666667 | 13321 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:54am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593947.5 | 509489.2 | 32269 | 1.64041666667 | 13560 |
| 014850 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:55am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593947.6 | 509486.8 | 32271 | 1.64041666667 | 14850 |
| 014902 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:56am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593948.2 | 509484.5 | 32273 | 1.64041666667 | 14902 |
| 016415 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:57am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593949.4 | 509481.3 | 32275 | 1.64041666667 | 16415 |
| 018834 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:58am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593950.2 | 509479.2 | 32277 | 1.64041666667 | 18834 |
| 018298 | 0 | GeoXH 6000 | 08/18/2015 | 10:50:59am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593951.5 | 509477.0 | 32279 | 1.64041666667 | 18298 |
| 018494 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:00am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593952.6 | 509475.2 | 32281 | 1.64041666667 | 18494 |
| 018303 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:01am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593953.6 | 509473.3 | 32283 | 1.64041666667 | 18303 |
| 017565 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:02am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593954.3 | 509471.5 | 32285 | 1.64041666667 | 17565 |
| 015941 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:03am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593955.5 | 509469.7 | 32287 | 1.64041666667 | 15941 |
| 015385 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:04am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593956.8 | 509468.2 | 32289 | 1.64041666667 | 15385 |
| 014946 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:05am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593958.6 | 509466.8 | 32291 | 1.64041666667 | 14946 |
| 015316 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:06am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593960.4 | 509465.1 | 32293 | 1.64041666667 | 15316 |
| 018019 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:07am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593962.2 | 509463.2 | 32295 | 1.64041666667 | 18019 |
| 018184 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:08am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593963.6 | 509461.5 | 32297 | 1.64041666667 | 18184 |
| 016126 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:09am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593965.3 | 509459.7 | 32299 | 1.64041666667 | 16126 |
| 017531 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:10am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593966.7 | 509458.1 | 32301 | 1.64041666667 | 17531 |
| 016533 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:11am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593968.7 | 509456.1 | 32303 | 1.64041666667 | 16533 |
| 014753 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:12am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593970.1 | 509454.4 | 32305 | 1.64041666667 | 14753 |
| 014428 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:13am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593971.2 | 509452.5 | 32307 | 1.64041666667 | 14428 |
| 013507 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:14am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593971.8 | 509451.0 | 32309 | 1.64041666667 | 13507 |
| 013726 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:15am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593972.0 | 509448.7 | 32311 | 1.64041666667 | 13726 |
| 013571 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:16am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593972.0 | 509446.4 | 32313 | 1.64041666667 | 13571 |
| 014853 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:17am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593972.0 | 509444.2 | 32315 | 1.64041666667 | 14853 |
| 015953 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:18am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593972.2 | 509442.0 | 32317 | 1.64041666667 | 15953 |
| 014428 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:19am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593972.6 | 509439.7 | 32319 | 1.64041666667 | 14428 |
| 013807 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:20am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593973.1 | 509437.7 | 32321 | 1.64041666667 | 13807 |
| 013171 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:21am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593973.8 | 509435.3 | 32323 | 1.64041666667 | 13171 |
| 014062 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:22am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593974.7 | 509433.4 | 32325 | 1.64041666667 | 14062 |
| 013925 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:23am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593975.8 | 509431.3 | 32327 | 1.64041666667 | 13925 |
| 013951 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:24am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593976.7 | 509429.2 | 32329 | 1.64041666667 | 13951 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012907 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:25am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593977.3 | 509426.8 | 32331 | 1.64041666667 | 12907 |
| 014717 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:26am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593978.1 | 509424.9 | 32333 | 1.64041666667 | 14717 |
| 014149 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:27am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593979.1 | 509422.5 | 32335 | 1.64041666667 | 14149 |
| 014427 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:28am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593980.3 | 509420.3 | 32337 | 1.64041666667 | 14427 |
| 012607 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:29am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593981.3 | 509417.6 | 32339 | 1.64041666667 | 12607 |
| 012571 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:30am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593982.1 | 509415.7 | 32341 | 1.64041666667 | 12571 |
| 013642 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:31am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593982.9 | 509413.0 | 32343 | 1.64041666667 | 13642 |
| 016580 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:32am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593983.4 | 509410.3 | 32345 | 1.64041666667 | 16580 |
| 013925 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:33am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593983.1 | 509407.8 | 32347 | 1.64041666667 | 13925 |
| 013741 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:34am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593981.7 | 509406.3 | 32349 | 1.64041666667 | 13741 |
| 014865 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:35am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593979.5 | 509405.6 | 32351 | 1.64041666667 | 14865 |
| 012476 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:36am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593978.2 | 509406.7 | 32353 | 1.64041666667 | 12476 |
| 013619 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:37am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593976.9 | 509408.5 | 32355 | 1.64041666667 | 13619 |
| 015315 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:38am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593975.7 | 509410.0 | 32357 | 1.64041666667 | 15315 |
| 013158 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:39am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593973.7 | 509411.9 | 32359 | 1.64041666667 | 13158 |
| 015559 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:40am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593971.9 | 509413.3 | 32361 | 1.64041666667 | 15559 |
| 014389 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:41am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593970.0 | 509415.5 | 32363 | 1.64041666667 | 14389 |
| 014517 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:42am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593968.3 | 509417.3 | 32365 | 1.64041666667 | 14517 |
| 014009 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:43am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593967.1 | 509419.8 | 32367 | 1.64041666667 | 14009 |
| 014002 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:44am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593966.0 | 509421.9 | 32369 | 1.64041666667 | 14002 |
| 014000 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:45am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593964.4 | 509424.2 | 32371 | 1.64041666667 | 14000 |
| 012680 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:46am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593963.2 | 509425.8 | 32373 | 1.64041666667 | 12680 |
| 013760 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:47am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593962.4 | 509427.0 | 32375 | 1.64041666667 | 13760 |
| 015290 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:48am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593962.3 | 509428.2 | 32377 | 1.64041666667 | 15290 |
| 013872 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:49am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593962.7 | 509430.1 | 32379 | 1.64041666667 | 13872 |
| 013458 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:50am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593963.2 | 509431.5 | 32381 | 1.64041666667 | 13458 |
| 012934 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:51am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593963.8 | 509433.1 | 32383 | 1.64041666667 | 12934 |
| 014723 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:52am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593964.3 | 509435.0 | 32385 | 1.64041666667 | 14723 |
| 018051 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:53am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593963.9 | 509437.0 | 32387 | 1.64041666667 | 18051 |
| 015432 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:54am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593963.1 | 509438.8 | 32389 | 1.64041666667 | 15432 |
| 015048 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:55am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593961.9 | 509440.7 | 32391 | 1.64041666667 | 15048 |
| 013812 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:56am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593960.7 | 509442.6 | 32393 | 1.64041666667 | 13812 |
| 013623 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:57am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593959.6 | 509444.8 | 32395 | 1.64041666667 | 13623 |
| 015915 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:58am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593958.6 | 509446.6 | 32397 | 1.64041666667 | 15915 |
| 015198 | 0 | GeoXH 6000 | 08/18/2015 | 10:51:59am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593957.3 | 509448.6 | 32399 | 1.64041666667 | 15198 |
| 013789 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:00am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593956.5 | 509450.8 | 32401 | 1.64041666667 | 13789 |
| 014127 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:01am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593955.8 | 509453.0 | 32403 | 1.64041666667 | 14127 |
| 014182 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:02am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593955.2 | 509454.6 | 32405 | 1.64041666667 | 14182 |
| 015635 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:03am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593954.4 | 509455.7 | 32407 | 1.64041666667 | 15635 |
| 015218 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:04am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593954.6 | 509456.3 | 32409 | 1.64041666667 | 15218 |
| 013854 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:05am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593954.6 | 509456.4 | 32411 | 1.64041666667 | 13854 |
| 013363 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:06am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593954.6 | 509456.3 | 32413 | 1.64041666667 | 13363 |
| 016211 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:07am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593954.7 | 509456.3 | 32415 | 1.64041666667 | 16211 |
| 015452 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:08am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593954.3 | 509456.7 | 32417 | 1.64041666667 | 15452 |
| 013703 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:09am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593953.5 | 509458.1 | 32419 | 1.64041666667 | 13703 |
| 015605 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:10am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593952.9 | 509459.8 | 32421 | 1.64041666667 | 15605 |
| 014491 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:11am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593952.1 | 509462.0 | 32423 | 1.64041666667 | 14491 |
| 014152 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:12am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593951.2 | 509464.1 | 32425 | 1.64041666667 | 14152 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013888 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:13am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593950.3 | 509466.5 | 32427 | 1.64041666667 | 13888 |
| 014782 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:14am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593949.7 | 509468.4 | 32429 | 1.64041666667 | 14782 |
| 014825 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:15am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593948.8 | 509470.6 | 32431 | 1.64041666667 | 14825 |
| 016726 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:16am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593948.1 | 509472.8 | 32433 | 1.64041666667 | 16726 |
| 015941 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:17am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593947.2 | 509475.5 | 32435 | 1.64041666667 | 15941 |
| 016795 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:18am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593946.6 | 509477.8 | 32437 | 1.64041666667 | 16795 |
| 015809 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:19am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593945.8 | 509480.4 | 32439 | 1.64041666667 | 15809 |
| 014362 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:20am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593944.7 | 509482.7 | 32441 | 1.64041666667 | 14362 |
| 012920 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:21am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593943.6 | 509484.9 | 32443 | 1.64041666667 | 12920 |
| 013910 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:22am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593942.1 | 509486.8 | 32445 | 1.64041666667 | 13910 |
| 013377 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:23am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593940.7 | 509488.8 | 32447 | 1.64041666667 | 13377 |
| 012824 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:24am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593939.0 | 509490.7 | 32449 | 1.64041666667 | 12824 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:25am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593937.1 | 509493.3 | 32451 | 1.64041666667 | 14516 |
| 013469 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:26am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593935.7 | 509495.5 | 32453 | 1.64041666667 | 13469 |
| 011527 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:27am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593934.5 | 509497.8 | 32455 | 1.64041666667 | 11527 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:28am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593933.6 | 509500.1 | 32457 | 1.64041666667 | 13471 |
| 013597 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:29am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593932.3 | 509502.5 | 32459 | 1.64041666667 | 13597 |
| 012969 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:30am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593931.5 | 509504.4 | 32461 | 1.64041666667 | 12969 |
| 013532 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:31am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593930.1 | 509506.8 | 32463 | 1.64041666667 | 13532 |
| 012923 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:32am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593928.8 | 509509.1 | 32465 | 1.64041666667 | 12923 |
| 013970 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:33am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593927.9 | 509511.1 | 32467 | 1.64041666667 | 13970 |
| 013302 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:34am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593926.9 | 509512.7 | 32469 | 1.64041666667 | 13302 |
| 013195 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:35am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593925.4 | 509513.9 | 32471 | 1.64041666667 | 13195 |
| 014309 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:36am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593923.6 | 509513.4 | 32473 | 1.64041666667 | 14309 |
| 015757 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:37am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593922.1 | 509511.7 | 32475 | 1.64041666667 | 15757 |
| 014169 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:38am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593921.5 | 509509.5 | 32477 | 1.64041666667 | 14169 |
| 014372 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:39am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593921.3 | 509507.2 | 32479 | 1.64041666667 | 14372 |
| 013643 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:40am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593921.5 | 509505.2 | 32481 | 1.64041666667 | 13643 |
| 013490 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:41am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593921.5 | 509503.0 | 32483 | 1.64041666667 | 13490 |
| 013002 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:42am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593922.1 | 509501.1 | 32485 | 1.64041666667 | 13002 |
| 012670 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:43am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593922.9 | 509498.7 | 32487 | 1.64041666667 | 12670 |
| 014837 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:44am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593923.8 | 509496.7 | 32489 | 1.64041666667 | 14837 |
| 015049 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:45am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593924.8 | 509494.7 | 32491 | 1.64041666667 | 15049 |
| 013302 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:46am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593926.0 | 509492.6 | 32493 | 1.64041666667 | 13302 |
| 012655 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:47am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593927.1 | 509490.5 | 32495 | 1.64041666667 | 12655 |
| 013604 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:48am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593928.0 | 509488.7 | 32497 | 1.64041666667 | 13604 |
| 012641 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:49am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593928.9 | 509486.8 | 32499 | 1.64041666667 | 12641 |
| 013720 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:50am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593929.5 | 509485.4 | 32501 | 1.64041666667 | 13720 |
| 013780 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:51am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593929.9 | 509483.8 | 32503 | 1.64041666667 | 13780 |
| 015475 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:52am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593930.2 | 509481.9 | 32505 | 1.64041666667 | 15475 |
| 012718 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:53am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593931.5 | 509480.3 | 32507 | 1.64041666667 | 12718 |
| 013799 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:54am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593932.7 | 509479.0 | 32509 | 1.64041666667 | 13799 |
| 014310 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:55am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593933.6 | 509477.3 | 32511 | 1.64041666667 | 14310 |
| 013417 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:56am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593934.7 | 509475.8 | 32513 | 1.64041666667 | 13417 |
| 014364 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:57am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593936.2 | 509473.9 | 32515 | 1.64041666667 | 14364 |
| 013311 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:58am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593937.2 | 509472.4 | 32517 | 1.64041666667 | 13311 |
| 013587 | 0 | GeoXH 6000 | 08/18/2015 | 10:52:59am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593938.4 | 509470.3 | 32519 | 1.64041666667 | 13587 |
| 015217 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:00am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593939.5 | 509468.5 | 32521 | 1.64041666667 | 15217 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014334 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:01am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593940.4 | 509466.3 | 32523 | 1.64041666667 | 14334 |
| 013993 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:02am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593941.5 | 509464.5 | 32525 | 1.64041666667 | 13993 |
| 015978 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:03am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593943.2 | 509462.5 | 32527 | 1.64041666667 | 15978 |
| 015484 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:04am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593944.3 | 509460.9 | 32529 | 1.64041666667 | 15484 |
| 014281 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:05am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593944.7 | 509458.5 | 32531 | 1.64041666667 | 14281 |
| 013380 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:06am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593944.8 | 509456.7 | 32533 | 1.64041666667 | 13380 |
| 015225 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:07am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593945.2 | 509454.4 | 32535 | 1.64041666667 | 15225 |
| 014036 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:08am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593946.3 | 509452.4 | 32537 | 1.64041666667 | 14036 |
| 012959 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:09am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593947.6 | 509450.1 | 32539 | 1.64041666667 | 12959 |
| 014460 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:10am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593948.7 | 509448.3 | 32541 | 1.64041666667 | 14460 |
| 014295 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:11am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593949.8 | 509446.2 | 32543 | 1.64041666667 | 14295 |
| 015363 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:12am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593951.3 | 509444.5 | 32545 | 1.64041666667 | 15363 |
| 017460 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:13am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593952.5 | 509442.3 | 32547 | 1.64041666667 | 17460 |
| 015675 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:14am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593953.2 | 509440.0 | 32549 | 1.64041666667 | 15675 |
| 015048 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:15am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593953.2 | 509437.3 | 32551 | 1.64041666667 | 15048 |
| 014052 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:16am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593953.3 | 509435.1 | 32553 | 1.64041666667 | 14052 |
| 012543 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:17am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593953.7 | 509432.3 | 32555 | 1.64041666667 | 12543 |
| 013605 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:18am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593954.1 | 509430.2 | 32557 | 1.64041666667 | 13605 |
| 013421 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:19am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593955.4 | 509428.0 | 32559 | 1.64041666667 | 13421 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:20am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593956.4 | 509425.7 | 32561 | 1.64041666667 | 13915 |
| 013169 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:21am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593958.1 | 509423.3 | 32563 | 1.64041666667 | 13169 |
| 014002 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:22am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593959.3 | 509421.4 | 32565 | 1.64041666667 | 14002 |
| 013190 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:23am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593961.4 | 509419.4 | 32567 | 1.64041666667 | 13190 |
| 014127 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:24am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593962.7 | 509417.6 | 32569 | 1.64041666667 | 14127 |
| 017092 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:25am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593964.0 | 509415.4 | 32571 | 1.64041666667 | 17092 |
| 015163 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:26am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593964.9 | 509413.6 | 32573 | 1.64041666667 | 15163 |
| 014320 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:27am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593966.3 | 509411.2 | 32575 | 1.64041666667 | 14320 |
| 013930 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:28am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593967.5 | 509409.0 | 32577 | 1.64041666667 | 13930 |
| 014582 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:29am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593968.7 | 509406.3 | 32579 | 1.64041666667 | 14582 |
| 013035 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:30am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593969.4 | 509404.0 | 32581 | 1.64041666667 | 13035 |
| 014898 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:31am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593969.8 | 509401.3 | 32583 | 1.64041666667 | 14898 |
| 013444 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:32am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593969.6 | 509399.5 | 32585 | 1.64041666667 | 13444 |
| 015181 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:33am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593967.5 | 509398.0 | 32587 | 1.64041666667 | 15181 |
| 013965 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:34am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593965.5 | 509397.7 | 32589 | 1.64041666667 | 13965 |
| 013481 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:35am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593964.1 | 509398.9 | 32591 | 1.64041666667 | 13481 |
| 013630 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:36am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593963.0 | 509400.2 | 32593 | 1.64041666667 | 13630 |
| 013787 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:37am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593961.4 | 509401.9 | 32595 | 1.64041666667 | 13787 |
| 014036 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:38am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593960.1 | 509403.3 | 32597 | 1.64041666667 | 14036 |
| 013769 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:39am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593958.6 | 509405.6 | 32599 | 1.64041666667 | 13769 |
| 012082 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:40am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593957.6 | 509407.6 | 32601 | 1.64041666667 | 12082 |
| 012590 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:41am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593956.1 | 509409.6 | 32603 | 1.64041666667 | 12590 |
| 013227 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:42am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593954.7 | 509411.6 | 32605 | 1.64041666667 | 13227 |
| 012577 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:43am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593953.5 | 509413.6 | 32607 | 1.64041666667 | 12577 |
| 013074 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:44am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593953.1 | 509415.5 | 32609 | 1.64041666667 | 13074 |
| 014428 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:45am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593952.5 | 509417.9 | 32611 | 1.64041666667 | 14428 |
| 015817 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:46am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593952.3 | 509420.2 | 32613 | 1.64041666667 | 15817 |
| 014364 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:47am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593951.6 | 509422.8 | 32615 | 1.64041666667 | 14364 |
| 014241 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:48am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593951.3 | 509424.9 | 32617 | 1.64041666667 | 14241 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012890 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:49am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593950.8 | 509427.4 | 32619 | 1.64041666667 | 12890 |
| 012672 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:50am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593950.2 | 509429.7 | 32621 | 1.64041666667 | 12672 |
| 013008 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:51am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593949.3 | 509432.1 | 32623 | 1.64041666667 | 13008 |
| 013092 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:52am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593948.6 | 509434.1 | 32625 | 1.64041666667 | 13092 |
| 013293 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:53am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593948.3 | 509436.0 | 32627 | 1.64041666667 | 13293 |
| 014003 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:54am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593947.8 | 509437.6 | 32629 | 1.64041666667 | 14003 |
| 012890 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:55am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593947.1 | 509439.6 | 32631 | 1.64041666667 | 12890 |
| 014592 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:56am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593946.7 | 509441.6 | 32633 | 1.64041666667 | 14592 |
| 014148 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:57am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593946.1 | 509443.8 | 32635 | 1.64041666667 | 14148 |
| 013947 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:58am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593945.7 | 509445.9 | 32637 | 1.64041666667 | 13947 |
| 013836 | 0 | GeoXH 6000 | 08/18/2015 | 10:53:59am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593945.6 | 509448.3 | 32639 | 1.64041666667 | 13836 |
| 014319 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:00am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593944.9 | 509450.4 | 32641 | 1.64041666667 | 14319 |
| 016749 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:01am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593944.6 | 509452.7 | 32643 | 1.64041666667 | 16749 |
| 014597 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:02am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593943.7 | 509454.6 | 32645 | 1.64041666667 | 14597 |
| 014959 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:03am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593942.7 | 509455.9 | 32647 | 1.64041666667 | 14959 |
| 013489 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:04am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593940.9 | 509457.2 | 32649 | 1.64041666667 | 13489 |
| 014382 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:05am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593939.4 | 509459.1 | 32651 | 1.64041666667 | 14382 |
| 014575 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:06am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593938.1 | 509460.9 | 32653 | 1.64041666667 | 14575 |
| 013424 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:07am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593937.1 | 509462.7 | 32655 | 1.64041666667 | 13424 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:08am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593935.4 | 509464.0 | 32657 | 1.64041666667 | 13526 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:09am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593933.5 | 509465.5 | 32659 | 1.64041666667 | 13491 |
| 014232 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:10am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593932.0 | 509467.4 | 32661 | 1.64041666667 | 14232 |
| 013398 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:11am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593930.7 | 509469.7 | 32663 | 1.64041666667 | 13398 |
| 013159 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:12am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593929.8 | 509471.6 | 32665 | 1.64041666667 | 13159 |
| 013879 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:13am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593928.4 | 509473.8 | 32667 | 1.64041666667 | 13879 |
| 014300 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:14am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593927.5 | 509475.6 | 32669 | 1.64041666667 | 14300 |
| 013325 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:15am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593926.0 | 509477.6 | 32671 | 1.64041666667 | 13325 |
| 013771 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:16am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593924.8 | 509479.6 | 32673 | 1.64041666667 | 13771 |
| 013312 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:17am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593923.4 | 509482.1 | 32675 | 1.64041666667 | 13312 |
| 013228 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:18am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593922.7 | 509484.2 | 32677 | 1.64041666667 | 13228 |
| 013147 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:19am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593921.8 | 509486.5 | 32679 | 1.64041666667 | 13147 |
| 012796 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:20am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593921.3 | 509488.4 | 32681 | 1.64041666667 | 12796 |
| 011509 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:21am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593920.6 | 509490.9 | 32683 | 1.64041666667 | 11509 |
| 012807 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:22am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593920.0 | 509493.1 | 32685 | 1.64041666667 | 12807 |
| 012892 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:23am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593919.3 | 509495.6 | 32687 | 1.64041666667 | 12892 |
| 013333 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:24am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593919.0 | 509498.3 | 32689 | 1.64041666667 | 13333 |
| 015063 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:25am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593918.1 | 509500.5 | 32691 | 1.64041666667 | 15063 |
| 013845 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:26am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593916.7 | 509502.2 | 32693 | 1.64041666667 | 13845 |
| 012851 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:27am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593915.4 | 509503.2 | 32695 | 1.64041666667 | 12851 |
| 013353 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:28am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593913.3 | 509502.8 | 32697 | 1.64041666667 | 13353 |
| 012938 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:29am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593910.8 | 509502.0 | 32699 | 1.64041666667 | 12938 |
| 012354 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:30am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593910.0 | 509500.4 | 32701 | 1.64041666667 | 12354 |
| 014398 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:31am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593909.7 | 509497.9 | 32703 | 1.64041666667 | 14398 |
| 012719 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:32am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593909.5 | 509495.7 | 32705 | 1.64041666667 | 12719 |
| 014670 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:33am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593910.1 | 509493.5 | 32707 | 1.64041666667 | 14670 |
| 012967 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:34am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593910.9 | 509491.5 | 32709 | 1.64041666667 | 12967 |
| 011431 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:35am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593912.1 | 509489.2 | 32711 | 1.64041666667 | 11431 |
| 012757 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:36am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593913.2 | 509486.9 | 32713 | 1.64041666667 | 12757 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012759 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:37am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593914.4 | 509484.9 | 32715 | 1.64041666667 | 12759 |
| 012040 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:38am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593915.9 | 509483.5 | 32717 | 1.64041666667 | 12040 |
| 012760 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:39am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.7 | 509481.4 | 32719 | 1.64041666667 | 12760 |
| 012730 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:40am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593918.6 | 509479.7 | 32721 | 1.64041666667 | 12730 |
| 013022 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:41am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593918.3 | 509477.6 | 32723 | 1.64041666667 | 13022 |
| 013005 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:42am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593918.3 | 509476.0 | 32725 | 1.64041666667 | 13005 |
| 012071 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:43am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593918.1 | 509475.0 | 32727 | 1.64041666667 | 12071 |
| 013158 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:44am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.9 | 509475.1 | 32729 | 1.64041666667 | 13158 |
| 012379 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:45am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.3 | 32731 | 1.64041666667 | 12379 |
| 012154 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:46am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.4 | 32733 | 1.64041666667 | 12154 |
| 012398 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:47am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.5 | 32735 | 1.64041666667 | 12398 |
| 012669 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:48am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.5 | 32737 | 1.64041666667 | 12669 |
| 012587 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:49am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.5 | 32739 | 1.64041666667 | 12587 |
| 013556 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:50am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.5 | 32741 | 1.64041666667 | 13556 |
| 012389 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:51am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.5 | 32743 | 1.64041666667 | 12389 |
| 013717 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:52am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.5 | 32745 | 1.64041666667 | 13717 |
| 013569 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:53am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.5 | 32747 | 1.64041666667 | 13569 |
| 012542 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:54am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593917.8 | 509475.5 | 32749 | 1.64041666667 | 12542 |
| 013365 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:55am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593918.2 | 509475.3 | 32751 | 1.64041666667 | 13365 |
| 014771 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:56am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593919.0 | 509474.3 | 32753 | 1.64041666667 | 14771 |
| 016833 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:57am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593919.7 | 509473.1 | 32755 | 1.64041666667 | 16833 |
| 015728 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:58am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593919.3 | 509471.1 | 32757 | 1.64041666667 | 15728 |
| 013922 | 0 | GeoXH 6000 | 08/18/2015 | 10:54:59am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593919.0 | 509468.8 | 32759 | 1.64041666667 | 13922 |
| 014970 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:00am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593918.3 | 509467.1 | 32761 | 1.64041666667 | 14970 |
| 013672 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:01am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593918.4 | 509465.2 | 32763 | 1.64041666667 | 13672 |
| 012658 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:02am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593918.5 | 509463.1 | 32765 | 1.64041666667 | 12658 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:03am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593919.2 | 509461.1 | 32767 | 1.64041666667 | 13094 |
| 012423 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:04am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593919.7 | 509459.2 | 32769 | 1.64041666667 | 12423 |
| 013965 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:05am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593920.9 | 509457.1 | 32771 | 1.64041666667 | 13965 |
| 016301 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:06am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593922.0 | 509455.2 | 32773 | 1.64041666667 | 16301 |
| 014905 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:07am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593923.5 | 509453.6 | 32775 | 1.64041666667 | 14905 |
| 014886 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:08am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593925.0 | 509451.6 | 32777 | 1.64041666667 | 14886 |
| 015001 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:09am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593926.6 | 509449.6 | 32779 | 1.64041666667 | 15001 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:10am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593928.5 | 509447.5 | 32781 | 1.64041666667 | 14550 |
| 014257 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:11am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593930.2 | 509445.2 | 32783 | 1.64041666667 | 14257 |
| 015594 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:12am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593931.8 | 509443.1 | 32785 | 1.64041666667 | 15594 |
| 015568 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:13am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593933.0 | 509440.5 | 32787 | 1.64041666667 | 15568 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:14am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593934.1 | 509438.8 | 32789 | 1.64041666667 | 13972 |
| 013213 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:15am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593935.5 | 509436.5 | 32791 | 1.64041666667 | 13213 |
| 013503 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:16am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593937.0 | 509434.6 | 32793 | 1.64041666667 | 13503 |
| 013695 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:17am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593938.5 | 509432.4 | 32795 | 1.64041666667 | 13695 |
| 013353 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:18am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593940.0 | 509430.2 | 32797 | 1.64041666667 | 13353 |
| 014468 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:19am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593941.6 | 509428.0 | 32799 | 1.64041666667 | 14468 |
| 015257 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:20am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593942.4 | 509426.1 | 32801 | 1.64041666667 | 15257 |
| 014164 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:21am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593943.4 | 509423.7 | 32803 | 1.64041666667 | 14164 |
| 014971 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:22am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593943.4 | 509421.6 | 32805 | 1.64041666667 | 14971 |
| 014302 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:23am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593943.2 | 509419.1 | 32807 | 1.64041666667 | 14302 |
| 014435 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:24am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593942.7 | 509416.8 | 32809 | 1.64041666667 | 14435 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014409 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:25am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593942.7 | 509414.3 | 32811 | 1.64041666667 | 14409 |
| 013624 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:26am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593942.9 | 509412.0 | 32813 | 1.64041666667 | 13624 |
| 014573 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:27am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593943.7 | 509409.4 | 32815 | 1.64041666667 | 14573 |
| 012973 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:28am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593943.5 | 509407.4 | 32817 | 1.64041666667 | 12973 |
| 014583 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:29am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593943.7 | 509405.7 | 32819 | 1.64041666667 | 14583 |
| 013935 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:30am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593943.9 | 509403.8 | 32821 | 1.64041666667 | 13935 |
| 014163 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:31am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593944.2 | 509401.8 | 32823 | 1.64041666667 | 14163 |
| 015331 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:32am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593943.0 | 509400.1 | 32825 | 1.64041666667 | 15331 |
| 013792 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:33am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593941.0 | 509399.5 | 32827 | 1.64041666667 | 13792 |
| 015568 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:34am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593939.2 | 509400.0 | 32829 | 1.64041666667 | 15568 |
| 013612 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:35am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593937.4 | 509401.7 | 32831 | 1.64041666667 | 13612 |
| 013333 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:36am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1593935.9 | 509403.6 | 32833 | 1.64041666667 | 13333 |
| 015063 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:37am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1593934.6 | 509406.0 | 32835 | 1.64041666667 | 15063 |
| 014565 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:38am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593933.7 | 509408.1 | 32837 | 1.64041666667 | 14565 |
| 013271 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:39am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593932.6 | 509410.5 | 32839 | 1.64041666667 | 13271 |
| 014388 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:40am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593932.0 | 509412.5 | 32841 | 1.64041666667 | 14388 |
| 015627 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:41am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593930.9 | 509414.9 | 32843 | 1.64041666667 | 15627 |
| 014946 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:42am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593930.3 | 509417.3 | 32845 | 1.64041666667 | 14946 |
| 013516 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:43am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593929.4 | 509419.6 | 32847 | 1.64041666667 | 13516 |
| 014269 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:44am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593928.8 | 509421.6 | 32849 | 1.64041666667 | 14269 |
| 013587 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:45am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593928.2 | 509424.0 | 32851 | 1.64041666667 | 13587 |
| 014107 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:46am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593927.8 | 509426.0 | 32853 | 1.64041666667 | 14107 |
| 013456 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:47am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593927.2 | 509427.9 | 32855 | 1.64041666667 | 13456 |
| 012814 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:48am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593926.6 | 509429.5 | 32857 | 1.64041666667 | 12814 |
| 016043 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:49am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593926.0 | 509431.3 | 32859 | 1.64041666667 | 16043 |
| 015351 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:50am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593925.8 | 509433.6 | 32861 | 1.64041666667 | 15351 |
| 015567 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:51am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593925.1 | 509435.9 | 32863 | 1.64041666667 | 15567 |
| 014392 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:52am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593924.5 | 509438.2 | 32865 | 1.64041666667 | 14392 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:53am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593923.5 | 509440.3 | 32867 | 1.64041666667 | 13738 |
| 014624 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:54am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593922.3 | 509442.6 | 32869 | 1.64041666667 | 14624 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:55am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593921.4 | 509445.2 | 32871 | 1.64041666667 | 14246 |
| 013461 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:56am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593920.5 | 509447.3 | 32873 | 1.64041666667 | 13461 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:57am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593919.3 | 509449.4 | 32875 | 1.64041666667 | 13595 |
| 012968 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:58am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593918.0 | 509451.5 | 32877 | 1.64041666667 | 12968 |
| 014852 | 0 | GeoXH 6000 | 08/18/2015 | 10:55:59am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593917.2 | 509454.1 | 32879 | 1.64041666667 | 14852 |
| 015113 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:00am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593916.3 | 509456.3 | 32881 | 1.64041666667 | 15113 |
| 014698 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:01am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593915.3 | 509458.7 | 32883 | 1.64041666667 | 14698 |
| 013844 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:02am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593914.1 | 509460.7 | 32885 | 1.64041666667 | 13844 |
| 014021 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:03am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593913.2 | 509463.0 | 32887 | 1.64041666667 | 14021 |
| 014095 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:04am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593912.2 | 509465.3 | 32889 | 1.64041666667 | 14095 |
| 013303 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:05am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593911.7 | 509467.8 | 32891 | 1.64041666667 | 13303 |
| 013046 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:06am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593911.2 | 509469.5 | 32893 | 1.64041666667 | 13046 |
| 013521 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:07am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593910.1 | 509471.9 | 32895 | 1.64041666667 | 13521 |
| 017030 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:08am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593908.7 | 509474.2 | 32897 | 1.64041666667 | 17030 |
| 014727 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:09am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593907.5 | 509476.5 | 32899 | 1.64041666667 | 14727 |
| 015112 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:10am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593907.0 | 509479.1 | 32901 | 1.64041666667 | 15112 |
| 012688 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:11am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593906.4 | 509481.7 | 32903 | 1.64041666667 | 12688 |
| 014032 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:12am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593905.8 | 509483.8 | 32905 | 1.64041666667 | 14032 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013588 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:13am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593904.2 | 509486.1 | 32907 | 1.64041666667 | 13588 |
| 011977 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:14am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593902.9 | 509488.3 | 32909 | 1.64041666667 | 11977 |
| 013224 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:15am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593902.0 | 509490.0 | 32911 | 1.64041666667 | 13224 |
| 011646 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:16am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593901.2 | 509490.6 | 32913 | 1.64041666667 | 11646 |
| 012331 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:17am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593900.4 | 509490.5 | 32915 | 1.64041666667 | 12331 |
| 012802 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:18am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593899.4 | 509489.6 | 32917 | 1.64041666667 | 12802 |
| 014600 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:19am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593898.8 | 509488.0 | 32919 | 1.64041666667 | 14600 |
| 012890 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:20am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593898.8 | 509486.3 | 32921 | 1.64041666667 | 12890 |
| 011442 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:21am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593898.5 | 509484.1 | 32923 | 1.64041666667 | 11442 |
| 012370 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:22am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593898.3 | 509482.1 | 32925 | 1.64041666667 | 12370 |
| 012332 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:23am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593898.5 | 509479.7 | 32927 | 1.64041666667 | 12332 |
| 013913 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:24am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593899.2 | 509477.9 | 32929 | 1.64041666667 | 13913 |
| 014098 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:25am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593900.2 | 509476.2 | 32931 | 1.64041666667 | 14098 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:26am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593901.1 | 509474.6 | 32933 | 1.64041666667 | 13094 |
| 012153 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:27am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593901.7 | 509472.2 | 32935 | 1.64041666667 | 12153 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:28am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593902.4 | 509470.3 | 32937 | 1.64041666667 | 14078 |
| 014499 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:29am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593902.4 | 509468.0 | 32939 | 1.64041666667 | 14499 |
| 012475 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:30am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593902.5 | 509466.4 | 32941 | 1.64041666667 | 12475 |
| 012688 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:31am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593903.4 | 509464.4 | 32943 | 1.64041666667 | 12688 |
| 013282 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:32am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593904.5 | 509462.8 | 32945 | 1.64041666667 | 13282 |
| 012560 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:33am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593905.6 | 509460.7 | 32947 | 1.64041666667 | 12560 |
| 012800 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:34am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593906.6 | 509459.0 | 32949 | 1.64041666667 | 12800 |
| 012620 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:35am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593907.7 | 509456.6 | 32951 | 1.64041666667 | 12620 |
| 013865 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:36am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593908.2 | 509454.5 | 32953 | 1.64041666667 | 13865 |
| 014806 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:37am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593909.2 | 509452.2 | 32955 | 1.64041666667 | 14806 |
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:38am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593909.8 | 509450.2 | 32957 | 1.64041666667 | 12761 |
| 013630 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:39am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593911.1 | 509447.8 | 32959 | 1.64041666667 | 13630 |
| 016067 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:40am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593911.8 | 509445.5 | 32961 | 1.64041666667 | 16067 |
| 015596 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:41am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593912.4 | 509443.2 | 32963 | 1.64041666667 | 15596 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:42am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593912.6 | 509441.1 | 32965 | 1.64041666667 | 14609 |
| 015892 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:43am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593913.0 | 509438.4 | 32967 | 1.64041666667 | 15892 |
| 013693 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:44am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593913.1 | 509436.0 | 32969 | 1.64041666667 | 13693 |
| 013053 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:45am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593914.0 | 509433.4 | 32971 | 1.64041666667 | 13053 |
| 013373 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:46am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593914.3 | 509431.2 | 32973 | 1.64041666667 | 13373 |
| 012703 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:47am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593915.3 | 509428.9 | 32975 | 1.64041666667 | 12703 |
| 013916 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:48am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593915.9 | 509426.8 | 32977 | 1.64041666667 | 13916 |
| 014309 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:49am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593916.5 | 509424.5 | 32979 | 1.64041666667 | 14309 |
| 014137 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:50am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593916.7 | 509422.3 | 32981 | 1.64041666667 | 14137 |
| 013884 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:51am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593917.8 | 509420.2 | 32983 | 1.64041666667 | 13884 |
| 014691 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:52am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593918.9 | 509418.2 | 32985 | 1.64041666667 | 14691 |
| 014292 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:53am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593919.8 | 509416.5 | 32987 | 1.64041666667 | 14292 |
| 014313 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:54am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593920.5 | 509414.8 | 32989 | 1.64041666667 | 14313 |
| 015548 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:55am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593921.3 | 509412.5 | 32991 | 1.64041666667 | 15548 |
| 015317 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:56am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593922.2 | 509410.4 | 32993 | 1.64041666667 | 15317 |
| 013879 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:57am | Sensor | 1797-S0030-868-G-TJV | 6805.8 | 1593922.8 | 509408.0 | 32995 | 1.64041666667 | 13879 |
| 014179 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:58am | Sensor | 1797-S0030-868-G-TJV | 6805.9 | 1593923.8 | 509406.0 | 32997 | 1.64041666667 | 14179 |
| 014285 | 0 | GeoXH 6000 | 08/18/2015 | 10:56:59am | Sensor | 1797-S0030-868-G-TJV | 6806.1 | 1593924.2 | 509403.4 | 32999 | 1.64041666667 | 14285 |
| 015061 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:00am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593924.7 | 509401.5 | 33001 | 1.64041666667 | 15061 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013095 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:01am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593925.3 | 509398.8 | 33003 | 1.64041666667 | 13095 |
| 014253 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:02am | Sensor | 1797-S0030-868-G-TJV | 6806.6 | 1593925.6 | 509397.0 | 33005 | 1.64041666667 | 14253 |
| 013703 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:03am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593924.6 | 509395.3 | 33007 | 1.64041666667 | 13703 |
| 013656 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:04am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593922.5 | 509394.6 | 33009 | 1.64041666667 | 13656 |
| 014514 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:05am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593920.0 | 509394.8 | 33011 | 1.64041666667 | 14514 |
| 013798 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:06am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593918.4 | 509396.0 | 33013 | 1.64041666667 | 13798 |
| 015599 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:07am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593917.4 | 509398.2 | 33015 | 1.64041666667 | 15599 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:08am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593916.4 | 509400.1 | 33017 | 1.64041666667 | 14550 |
| 014887 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:09am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593915.5 | 509402.5 | 33019 | 1.64041666667 | 14887 |
| 014191 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:10am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593914.5 | 509404.7 | 33021 | 1.64041666667 | 14191 |
| 014797 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:11am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593914.5 | 509406.9 | 33023 | 1.64041666667 | 14797 |
| 013809 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:12am | Sensor | 1797-S0030-868-G-TJV | 6805.9 | 1593914.1 | 509409.2 | 33025 | 1.64041666667 | 13809 |
| 013892 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:13am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593914.1 | 509411.5 | 33027 | 1.64041666667 | 13892 |
| 014843 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:14am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593913.8 | 509414.0 | 33029 | 1.64041666667 | 14843 |
| 016250 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:15am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1593913.9 | 509416.4 | 33031 | 1.64041666667 | 16250 |
| 015282 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:16am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593913.3 | 509418.6 | 33033 | 1.64041666667 | 15282 |
| 014920 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:17am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593912.5 | 509421.5 | 33035 | 1.64041666667 | 14920 |
| 014800 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:18am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593912.0 | 509424.0 | 33037 | 1.64041666667 | 14800 |
| 013900 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:19am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593911.8 | 509426.1 | 33039 | 1.64041666667 | 13900 |
| 015085 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:20am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593911.8 | 509428.3 | 33041 | 1.64041666667 | 15085 |
| 013971 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:21am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593910.6 | 509430.7 | 33043 | 1.64041666667 | 13971 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:22am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593910.2 | 509432.9 | 33045 | 1.64041666667 | 13782 |
| 014815 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:23am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593909.7 | 509435.4 | 33047 | 1.64041666667 | 14815 |
| 013724 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:24am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593910.1 | 509437.7 | 33049 | 1.64041666667 | 13724 |
| 013391 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:25am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593909.7 | 509440.2 | 33051 | 1.64041666667 | 13391 |
| 013877 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:26am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593908.7 | 509442.4 | 33053 | 1.64041666667 | 13877 |
| 014719 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:27am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593906.8 | 509444.4 | 33055 | 1.64041666667 | 14719 |
| 012859 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:28am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593904.7 | 509446.0 | 33057 | 1.64041666667 | 12859 |
| 012635 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:29am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593902.9 | 509448.3 | 33059 | 1.64041666667 | 12635 |
| 014768 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:30am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593901.4 | 509450.1 | 33061 | 1.64041666667 | 14768 |
| 013292 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:31am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593900.1 | 509452.3 | 33063 | 1.64041666667 | 13292 |
| 014873 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:32am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593898.9 | 509454.0 | 33065 | 1.64041666667 | 14873 |
| 014668 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:33am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593898.3 | 509456.1 | 33067 | 1.64041666667 | 14668 |
| 015097 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:34am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593897.3 | 509457.9 | 33069 | 1.64041666667 | 15097 |
| 016644 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:35am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593896.1 | 509459.8 | 33071 | 1.64041666667 | 16644 |
| 014751 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:36am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593894.6 | 509461.1 | 33073 | 1.64041666667 | 14751 |
| 013947 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:37am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593892.8 | 509463.2 | 33075 | 1.64041666667 | 13947 |
| 012607 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:38am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593891.4 | 509465.3 | 33077 | 1.64041666667 | 12607 |
| 012751 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:39am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593890.1 | 509467.9 | 33079 | 1.64041666667 | 12751 |
| 013387 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:40am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593889.6 | 509469.9 | 33081 | 1.64041666667 | 13387 |
| 012917 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:41am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593888.1 | 509471.6 | 33083 | 1.64041666667 | 12917 |
| 012319 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:42am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593887.0 | 509473.3 | 33085 | 1.64041666667 | 12319 |
| 011659 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:43am | Sensor | 1797-S0030-868-G-TJV | 6802.1 | 1593885.5 | 509475.3 | 33087 | 1.64041666667 | 11659 |
| 010835 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:44am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593884.8 | 509477.7 | 33089 | 1.64041666667 | 10835 |
| 010688 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:45am | Sensor | 1797-S0030-868-G-TJV | 6801.7 | 1593883.8 | 509480.5 | 33091 | 1.64041666667 | 10688 |
| 011702 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:46am | Sensor | 1797-S0030-868-G-TJV | 6801.6 | 1593883.4 | 509483.0 | 33093 | 1.64041666667 | 11702 |
| 013005 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:47am | Sensor | 1797-S0030-868-G-TJV | 6801.6 | 1593882.5 | 509485.4 | 33095 | 1.64041666667 | 13005 |
| 014291 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:48am | Sensor | 1797-S0030-868-G-TJV | 6801.6 | 1593881.6 | 509487.0 | 33097 | 1.64041666667 | 14291 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013593 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:49am | Sensor | 1797-S0030-868-G-TJV | 6801.3 | 1593880.0 | 509488.9 | 33099 | 1.64041666667 | 13593 |
| 013868 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:50am | Sensor | 1797-S0030-868-G-TJV | 6801.4 | 1593879.2 | 509490.6 | 33101 | 1.64041666667 | 13868 |
| 012317 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:51am | Sensor | 1797-S0030-868-G-TJV | 6801.5 | 1593878.9 | 509492.1 | 33103 | 1.64041666667 | 12317 |
| 012619 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:52am | Sensor | 1797-S0030-868-G-TJV | 6801.4 | 1593877.3 | 509491.5 | 33105 | 1.64041666667 | 12619 |
| 010624 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:53am | Sensor | 1797-S0030-868-G-TJV | 6801.3 | 1593875.9 | 509490.0 | 33107 | 1.64041666667 | 10624 |
| 013156 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:54am | Sensor | 1797-S0030-868-G-TJV | 6801.4 | 1593875.1 | 509488.3 | 33109 | 1.64041666667 | 13156 |
| 012679 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:55am | Sensor | 1797-S0030-868-G-TJV | 6801.4 | 1593874.8 | 509486.6 | 33111 | 1.64041666667 | 12679 |
| 012529 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:56am | Sensor | 1797-S0030-868-G-TJV | 6801.4 | 1593874.2 | 509484.7 | 33113 | 1.64041666667 | 12529 |
| 011652 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:57am | Sensor | 1797-S0030-868-G-TJV | 6801.5 | 1593874.5 | 509483.0 | 33115 | 1.64041666667 | 11652 |
| 012063 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:58am | Sensor | 1797-S0030-868-G-TJV | 6801.6 | 1593875.1 | 509481.1 | 33117 | 1.64041666667 | 12063 |
| 012255 | 0 | GeoXH 6000 | 08/18/2015 | 10:57:59am | Sensor | 1797-S0030-868-G-TJV | 6801.7 | 1593876.2 | 509479.2 | 33119 | 1.64041666667 | 12255 |
| 012093 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:00am | Sensor | 1797-S0030-868-G-TJV | 6801.9 | 1593876.7 | 509477.1 | 33121 | 1.64041666667 | 12093 |
| 011303 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:01am | Sensor | 1797-S0030-868-G-TJV | 6802.1 | 1593877.5 | 509475.1 | 33123 | 1.64041666667 | 11303 |
| 012216 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:02am | Sensor | 1797-S0030-868-G-TJV | 6802.2 | 1593877.9 | 509473.3 | 33125 | 1.64041666667 | 12216 |
| 010854 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:03am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593878.8 | 509471.4 | 33127 | 1.64041666667 | 10854 |
| 010723 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:04am | Sensor | 1797-S0030-868-G-TJV | 6802.0 | 1593879.1 | 509469.4 | 33129 | 1.64041666667 | 10723 |
| 010151 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:05am | Sensor | 1797-S0030-868-G-TJV | 6802.2 | 1593880.0 | 509467.7 | 33131 | 1.64041666667 | 10151 |
| 012857 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:06am | Sensor | 1797-S0030-868-G-TJV | 6802.5 | 1593880.9 | 509466.0 | 33133 | 1.64041666667 | 12857 |
| 011944 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:07am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593882.2 | 509464.7 | 33135 | 1.64041666667 | 11944 |
| 012526 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:08am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593883.2 | 509463.4 | 33137 | 1.64041666667 | 12526 |
| 013271 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:09am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593884.7 | 509461.9 | 33139 | 1.64041666667 | 13271 |
| 014118 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:10am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593886.5 | 509460.4 | 33141 | 1.64041666667 | 14118 |
| 012829 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:11am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593888.6 | 509459.0 | 33143 | 1.64041666667 | 12829 |
| 012777 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:12am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593890.2 | 509457.6 | 33145 | 1.64041666667 | 12777 |
| 012584 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:13am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593891.8 | 509455.9 | 33147 | 1.64041666667 | 12584 |
| 015416 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:14am | Sensor | 1797-S0030-868-G-TJV | 6802.3 | 1593892.9 | 509454.1 | 33149 | 1.64041666667 | 15416 |
| 014024 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:15am | Sensor | 1797-S0030-868-G-TJV | 6802.4 | 1593893.5 | 509451.8 | 33151 | 1.64041666667 | 14024 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:16am | Sensor | 1797-S0030-868-G-TJV | 6802.5 | 1593894.1 | 509449.8 | 33153 | 1.64041666667 | 14246 |
| 015111 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:17am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593894.2 | 509447.8 | 33155 | 1.64041666667 | 15111 |
| 015777 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:18am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593894.4 | 509446.3 | 33157 | 1.64041666667 | 15777 |
| 014744 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:19am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593894.1 | 509444.6 | 33159 | 1.64041666667 | 14744 |
| 014066 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:20am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593894.5 | 509442.9 | 33161 | 1.64041666667 | 14066 |
| 014736 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:21am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593895.1 | 509440.7 | 33163 | 1.64041666667 | 14736 |
| 013644 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:22am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593895.8 | 509439.7 | 33165 | 1.64041666667 | 13644 |
| 013851 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:23am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593895.7 | 509439.0 | 33167 | 1.64041666667 | 13851 |
| 013452 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:24am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593895.9 | 509438.3 | 33169 | 1.64041666667 | 13452 |
| 013473 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:25am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593896.3 | 509437.9 | 33171 | 1.64041666667 | 13473 |
| 013088 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:26am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593896.1 | 509438.0 | 33173 | 1.64041666667 | 13088 |
| 012032 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:27am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593895.2 | 509438.4 | 33175 | 1.64041666667 | 12032 |
| 012938 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:28am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593894.0 | 509439.4 | 33177 | 1.64041666667 | 12938 |
| 012414 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:29am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593892.6 | 509440.7 | 33179 | 1.64041666667 | 12414 |
| 012883 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:30am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593891.4 | 509441.8 | 33181 | 1.64041666667 | 12883 |
| 014411 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:31am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593890.3 | 509442.9 | 33183 | 1.64041666667 | 14411 |
| 014042 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:32am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593889.7 | 509443.4 | 33185 | 1.64041666667 | 14042 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:33am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593889.6 | 509443.3 | 33187 | 1.64041666667 | 14550 |
| 014977 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:34am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593889.6 | 509443.1 | 33189 | 1.64041666667 | 14977 |
| 013404 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:35am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593889.5 | 509443.0 | 33191 | 1.64041666667 | 13404 |
| 013911 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:36am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593889.4 | 509443.1 | 33193 | 1.64041666667 | 13911 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013467 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:37am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593889.6 | 509443.7 | 33195 | 1.64041666667 | 13467 |
| 013627 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:38am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593889.7 | 509444.5 | 33197 | 1.64041666667 | 13627 |
| 013846 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:39am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593890.0 | 509445.8 | 33199 | 1.64041666667 | 13846 |
| 015401 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:40am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593890.2 | 509446.7 | 33201 | 1.64041666667 | 15401 |
| 013960 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:41am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593889.9 | 509447.6 | 33203 | 1.64041666667 | 13960 |
| 015790 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:42am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593889.6 | 509448.4 | 33205 | 1.64041666667 | 15790 |
| 013697 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:43am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593888.0 | 509448.0 | 33207 | 1.64041666667 | 13697 |
| 013954 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:44am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593886.1 | 509447.4 | 33209 | 1.64041666667 | 13954 |
| 014228 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:45am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593884.7 | 509446.4 | 33211 | 1.64041666667 | 14228 |
| 013577 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:46am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593883.2 | 509445.9 | 33213 | 1.64041666667 | 13577 |
| 014464 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:47am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593881.2 | 509445.1 | 33215 | 1.64041666667 | 14464 |
| 014356 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:48am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593879.6 | 509445.0 | 33217 | 1.64041666667 | 14356 |
| 014059 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:49am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593878.0 | 509444.7 | 33219 | 1.64041666667 | 14059 |
| 012994 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:50am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593876.6 | 509445.0 | 33221 | 1.64041666667 | 12994 |
| 013268 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:51am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593876.0 | 509444.6 | 33223 | 1.64041666667 | 13268 |
| 012917 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:52am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593875.9 | 509444.7 | 33225 | 1.64041666667 | 12917 |
| 013159 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:53am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593875.8 | 509444.8 | 33227 | 1.64041666667 | 13159 |
| 013129 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:54am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593875.3 | 509444.5 | 33229 | 1.64041666667 | 13129 |
| 013182 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:55am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593874.5 | 509444.0 | 33231 | 1.64041666667 | 13182 |
| 014245 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:56am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593874.3 | 509444.3 | 33233 | 1.64041666667 | 14245 |
| 013461 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:57am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593874.1 | 509445.2 | 33235 | 1.64041666667 | 13461 |
| 013625 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:58am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593874.0 | 509447.0 | 33237 | 1.64041666667 | 13625 |
| 013576 | 0 | GeoXH 6000 | 08/18/2015 | 10:58:59am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593873.3 | 509448.8 | 33239 | 1.64041666667 | 13576 |
| 012394 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:00am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593873.5 | 509450.5 | 33241 | 1.64041666667 | 12394 |
| 011318 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:01am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593873.6 | 509452.4 | 33243 | 1.64041666667 | 11318 |
| 012429 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:02am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593873.6 | 509454.5 | 33245 | 1.64041666667 | 12429 |
| 013517 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:03am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593873.3 | 509456.4 | 33247 | 1.64041666667 | 13517 |
| 015019 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:04am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593873.4 | 509457.1 | 33249 | 1.64041666667 | 15019 |
| 015154 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:05am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593872.7 | 509456.8 | 33251 | 1.64041666667 | 15154 |
| 013148 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:06am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593871.5 | 509456.4 | 33253 | 1.64041666667 | 13148 |
| 013517 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:07am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593871.8 | 509454.9 | 33255 | 1.64041666667 | 13517 |
| 013279 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:08am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593872.1 | 509453.2 | 33257 | 1.64041666667 | 13279 |
| 012529 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:09am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593872.6 | 509451.0 | 33259 | 1.64041666667 | 12529 |
| 013452 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:10am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593873.0 | 509449.2 | 33261 | 1.64041666667 | 13452 |
| 013203 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:11am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593873.9 | 509446.8 | 33263 | 1.64041666667 | 13203 |
| 012420 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:12am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593874.2 | 509445.0 | 33265 | 1.64041666667 | 12420 |
| 012495 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:13am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593874.5 | 509442.9 | 33267 | 1.64041666667 | 12495 |
| 012993 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:14am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593874.2 | 509440.9 | 33269 | 1.64041666667 | 12993 |
| 013028 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:15am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593874.9 | 509439.2 | 33271 | 1.64041666667 | 13028 |
| 013877 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:16am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593875.3 | 509437.8 | 33273 | 1.64041666667 | 13877 |
| 014269 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:17am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593876.3 | 509436.5 | 33275 | 1.64041666667 | 14269 |
| 013557 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:18am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593877.3 | 509434.9 | 33277 | 1.64041666667 | 13557 |
| 013859 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:19am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1593878.6 | 509433.5 | 33279 | 1.64041666667 | 13859 |
| 013485 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:20am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593879.7 | 509431.6 | 33281 | 1.64041666667 | 13485 |
| 013481 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:21am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593881.3 | 509429.7 | 33283 | 1.64041666667 | 13481 |
| 013930 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:22am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593881.8 | 509427.7 | 33285 | 1.64041666667 | 13930 |
| 013082 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:23am | Sensor | 1797-S0030-868-G-TJV | 6805.8 | 1593882.6 | 509425.2 | 33287 | 1.64041666667 | 13082 |
| 013260 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:24am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593883.4 | 509422.9 | 33289 | 1.64041666667 | 13260 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013545 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:25am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593884.8 | 509420.4 | 33291 | 1.64041666667 | 13545 |
| 013226 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:26am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593886.2 | 509418.1 | 33293 | 1.64041666667 | 13226 |
| 012606 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:27am | Sensor | 1797-S0030-868-G-TJV | 6806.6 | 1593887.2 | 509415.5 | 33295 | 1.64041666667 | 12606 |
| 013891 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:28am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593888.1 | 509413.5 | 33297 | 1.64041666667 | 13891 |
| 014422 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:29am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593888.7 | 509410.7 | 33299 | 1.64041666667 | 14422 |
| 015095 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:30am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593889.5 | 509408.9 | 33301 | 1.64041666667 | 15095 |
| 014154 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:31am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593890.1 | 509406.6 | 33303 | 1.64041666667 | 14154 |
| 012298 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:32am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593890.9 | 509404.8 | 33305 | 1.64041666667 | 12298 |
| 012824 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:33am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593891.5 | 509402.4 | 33307 | 1.64041666667 | 12824 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:34am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593892.7 | 509400.5 | 33309 | 1.64041666667 | 14426 |
| 015456 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:35am | Sensor | 1797-S0030-868-G-TJV | 6808.1 | 1593893.9 | 509398.4 | 33311 | 1.64041666667 | 15456 |
| 014244 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:36am | Sensor | 1797-S0030-868-G-TJV | 6808.1 | 1593895.4 | 509396.9 | 33313 | 1.64041666667 | 14244 |
| 012981 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:37am | Sensor | 1797-S0030-868-G-TJV | 6808.3 | 1593897.2 | 509394.5 | 33315 | 1.64041666667 | 12981 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:38am | Sensor | 1797-S0030-868-G-TJV | 6808.5 | 1593898.3 | 509392.2 | 33317 | 1.64041666667 | 13595 |
| 013688 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:39am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593899.0 | 509389.7 | 33319 | 1.64041666667 | 13688 |
| 013652 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:40am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593899.1 | 509387.7 | 33321 | 1.64041666667 | 13652 |
| 014513 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:41am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593899.5 | 509385.4 | 33323 | 1.64041666667 | 14513 |
| 012868 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:42am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593899.9 | 509383.6 | 33325 | 1.64041666667 | 12868 |
| 013447 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:43am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593901.0 | 509381.5 | 33327 | 1.64041666667 | 13447 |
| 014611 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:44am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593901.9 | 509379.2 | 33329 | 1.64041666667 | 14611 |
| 013042 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:45am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593903.3 | 509377.1 | 33331 | 1.64041666667 | 13042 |
| 015410 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:46am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593904.9 | 509374.5 | 33333 | 1.64041666667 | 15410 |
| 014262 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:47am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593906.2 | 509371.8 | 33335 | 1.64041666667 | 14262 |
| 014605 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:48am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593907.4 | 509369.6 | 33337 | 1.64041666667 | 14605 |
| 016581 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:49am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593908.6 | 509366.8 | 33339 | 1.64041666667 | 16581 |
| 014555 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:50am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593910.1 | 509364.7 | 33341 | 1.64041666667 | 14555 |
| 017648 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:51am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593911.5 | 509362.2 | 33343 | 1.64041666667 | 17648 |
| 015932 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:52am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593913.1 | 509360.3 | 33345 | 1.64041666667 | 15932 |
| 016613 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:53am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593915.0 | 509357.7 | 33347 | 1.64041666667 | 16613 |
| 016153 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:54am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593916.3 | 509355.8 | 33349 | 1.64041666667 | 16153 |
| 016098 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:55am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593918.0 | 509354.3 | 33351 | 1.64041666667 | 16098 |
| 017224 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:56am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593918.4 | 509352.4 | 33353 | 1.64041666667 | 17224 |
| 015796 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:57am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593918.8 | 509350.2 | 33355 | 1.64041666667 | 15796 |
| 016309 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:58am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593919.6 | 509348.5 | 33357 | 1.64041666667 | 16309 |
| 015747 | 0 | GeoXH 6000 | 08/18/2015 | 10:59:59am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593919.9 | 509346.1 | 33359 | 1.64041666667 | 15747 |
| 015667 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:00am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593920.5 | 509344.5 | 33361 | 1.64041666667 | 15667 |
| 015256 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:01am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593920.7 | 509342.1 | 33363 | 1.64041666667 | 15256 |
| 016054 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:02am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.3 | 509341.1 | 33365 | 1.64041666667 | 16054 |
| 016133 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:03am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593921.4 | 509340.8 | 33367 | 1.64041666667 | 16133 |
| 016813 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:04am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593921.4 | 509340.9 | 33369 | 1.64041666667 | 16813 |
| 016503 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:05am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.5 | 509341.0 | 33371 | 1.64041666667 | 16503 |
| 015105 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:06am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.7 | 509340.9 | 33373 | 1.64041666667 | 15105 |
| 016586 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:07am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.7 | 509340.9 | 33375 | 1.64041666667 | 16586 |
| 015636 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:08am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.7 | 509340.9 | 33377 | 1.64041666667 | 15636 |
| 015519 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:09am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.7 | 509341.0 | 33379 | 1.64041666667 | 15519 |
| 016269 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:10am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.7 | 509341.0 | 33381 | 1.64041666667 | 16269 |
| 015497 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:11am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.8 | 509341.0 | 33383 | 1.64041666667 | 15497 |
| 016414 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:12am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.8 | 509341.1 | 33385 | 1.64041666667 | 16414 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015533 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:13am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.8 | 509341.1 | 33387 | 1.64041666667 | 15533 |
| 017533 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:14am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.8 | 509341.0 | 33389 | 1.64041666667 | 17533 |
| 016533 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:15am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.8 | 509341.0 | 33391 | 1.64041666667 | 16533 |
| 016733 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:16am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.8 | 509341.0 | 33393 | 1.64041666667 | 16733 |
| 016213 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:17am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.6 | 509340.9 | 33395 | 1.64041666667 | 16213 |
| 015753 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:18am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.4 | 509340.8 | 33397 | 1.64041666667 | 15753 |
| 015458 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:19am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593921.5 | 509341.0 | 33399 | 1.64041666667 | 15458 |
| 016344 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:20am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593921.5 | 509340.9 | 33401 | 1.64041666667 | 16344 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:21am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593921.5 | 509340.9 | 33403 | 1.64041666667 | 14526 |
| 014823 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:22am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.5 | 509340.9 | 33405 | 1.64041666667 | 14823 |
| 015232 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:23am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.5 | 509340.9 | 33407 | 1.64041666667 | 15232 |
| 013168 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:24am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.6 | 509340.9 | 33409 | 1.64041666667 | 13168 |
| 015802 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:25am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.7 | 509340.9 | 33411 | 1.64041666667 | 15802 |
| 015020 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:26am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593921.9 | 509340.8 | 33413 | 1.64041666667 | 15020 |
| 014165 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:27am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593922.0 | 509340.8 | 33415 | 1.64041666667 | 14165 |
| 016921 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:28am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593922.0 | 509340.9 | 33417 | 1.64041666667 | 16921 |
| 015360 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:29am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593921.9 | 509340.8 | 33419 | 1.64041666667 | 15360 |
| 015690 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:30am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593921.7 | 509340.7 | 33421 | 1.64041666667 | 15690 |
| 014602 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:31am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593921.7 | 509340.7 | 33423 | 1.64041666667 | 14602 |
| 015170 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:32am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593921.8 | 509340.6 | 33425 | 1.64041666667 | 15170 |
| 017052 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:33am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593921.9 | 509339.8 | 33427 | 1.64041666667 | 17052 |
| 016023 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:34am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593922.0 | 509337.9 | 33429 | 1.64041666667 | 16023 |
| 017415 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:35am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593922.5 | 509335.4 | 33431 | 1.64041666667 | 17415 |
| 016053 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:36am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593923.1 | 509332.8 | 33433 | 1.64041666667 | 16053 |
| 015413 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:37am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593923.4 | 509329.8 | 33435 | 1.64041666667 | 15413 |
| 015823 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:38am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593924.7 | 509327.5 | 33437 | 1.64041666667 | 15823 |
| 015446 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:39am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593926.0 | 509325.0 | 33439 | 1.64041666667 | 15446 |
| 018081 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:40am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593927.8 | 509322.7 | 33441 | 1.64041666667 | 18081 |
| 017420 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:41am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593929.3 | 509320.0 | 33443 | 1.64041666667 | 17420 |
| 015995 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:42am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593929.9 | 509317.2 | 33445 | 1.64041666667 | 15995 |
| 017288 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:43am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593930.2 | 509315.3 | 33447 | 1.64041666667 | 17288 |
| 017672 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:44am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593928.2 | 509314.5 | 33449 | 1.64041666667 | 17672 |
| 018158 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:45am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593926.1 | 509314.2 | 33451 | 1.64041666667 | 18158 |
| 017079 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:46am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593924.3 | 509315.5 | 33453 | 1.64041666667 | 17079 |
| 017710 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:47am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593923.3 | 509317.5 | 33455 | 1.64041666667 | 17710 |
| 017867 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:48am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593922.4 | 509318.1 | 33457 | 1.64041666667 | 17867 |
| 014846 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:49am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593923.1 | 509317.3 | 33459 | 1.64041666667 | 14846 |
| 017241 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:50am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593925.4 | 509316.6 | 33461 | 1.64041666667 | 17241 |
| 018440 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:51am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593927.6 | 509315.3 | 33463 | 1.64041666667 | 18440 |
| 018650 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:52am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593930.3 | 509314.6 | 33465 | 1.64041666667 | 18650 |
| 019842 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:53am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593933.0 | 509313.4 | 33467 | 1.64041666667 | 19842 |
| 019300 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:54am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593935.7 | 509312.8 | 33469 | 1.64041666667 | 19300 |
| 022165 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:55am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593937.6 | 509313.0 | 33471 | 1.64041666667 | 22165 |
| 020871 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:56am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.3 | 33473 | 1.64041666667 | 20871 |
| 022137 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:57am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.3 | 33475 | 1.64041666667 | 22137 |
| 020234 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:58am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.0 | 509313.4 | 33477 | 1.64041666667 | 20234 |
| 021018 | 0 | GeoXH 6000 | 08/18/2015 | 11:00:59am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.3 | 33479 | 1.64041666667 | 21018 |
| 022834 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:00am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.0 | 509313.3 | 33481 | 1.64041666667 | 22834 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 023438 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:01am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.2 | 33483 | 1.64041666667 | 23438 |
| 022959 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:02am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.2 | 33485 | 1.64041666667 | 22959 |
| 022150 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:03am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.2 | 33487 | 1.64041666667 | 22150 |
| 021827 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:04am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.2 | 33489 | 1.64041666667 | 21827 |
| 024116 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:05am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.0 | 509313.2 | 33491 | 1.64041666667 | 24116 |
| 022139 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:06am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.0 | 509313.1 | 33493 | 1.64041666667 | 22139 |
| 022185 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:07am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.0 | 509313.2 | 33495 | 1.64041666667 | 22185 |
| 021506 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:08am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.0 | 509313.2 | 33497 | 1.64041666667 | 21506 |
| 022536 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:09am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.4 | 33499 | 1.64041666667 | 22536 |
| 023304 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:10am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.5 | 33501 | 1.64041666667 | 23304 |
| 021456 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:11am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.5 | 33503 | 1.64041666667 | 21456 |
| 021774 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:12am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.5 | 33505 | 1.64041666667 | 21774 |
| 022813 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:13am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.4 | 33507 | 1.64041666667 | 22813 |
| 022563 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:14am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.4 | 33509 | 1.64041666667 | 22563 |
| 024210 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:15am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.4 | 33511 | 1.64041666667 | 24210 |
| 023122 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:16am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.4 | 33513 | 1.64041666667 | 23122 |
| 020510 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:17am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.4 | 33515 | 1.64041666667 | 20510 |
| 021327 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:18am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.4 | 33517 | 1.64041666667 | 21327 |
| 021082 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:19am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.2 | 509313.4 | 33519 | 1.64041666667 | 21082 |
| 023930 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:20am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.2 | 509313.4 | 33521 | 1.64041666667 | 23930 |
| 023112 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:21am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.2 | 509313.4 | 33523 | 1.64041666667 | 23112 |
| 022398 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:22am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.2 | 509313.4 | 33525 | 1.64041666667 | 22398 |
| 023899 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:23am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.3 | 33527 | 1.64041666667 | 23899 |
| 022594 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:24am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.3 | 33529 | 1.64041666667 | 22594 |
| 023318 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:25am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.3 | 33531 | 1.64041666667 | 23318 |
| 023019 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:26am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.3 | 33533 | 1.64041666667 | 23019 |
| 022345 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:27am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.3 | 33535 | 1.64041666667 | 22345 |
| 021786 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:28am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.3 | 33537 | 1.64041666667 | 21786 |
| 024796 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:29am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.0 | 509313.2 | 33539 | 1.64041666667 | 24796 |
| 023059 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:30am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.2 | 33541 | 1.64041666667 | 23059 |
| 022984 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:31am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.2 | 33543 | 1.64041666667 | 22984 |
| 021886 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:32am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.3 | 33545 | 1.64041666667 | 21886 |
| 023321 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:33am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.3 | 33547 | 1.64041666667 | 23321 |
| 024220 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:34am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.3 | 33549 | 1.64041666667 | 24220 |
| 022015 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:35am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.1 | 509313.2 | 33551 | 1.64041666667 | 22015 |
| 022363 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:36am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.0 | 509313.3 | 33553 | 1.64041666667 | 22363 |
| 023201 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:37am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.4 | 33555 | 1.64041666667 | 23201 |
| 024310 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:38am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.9 | 33557 | 1.64041666667 | 24310 |
| 023837 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:39am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593939.1 | 509314.2 | 33559 | 1.64041666667 | 23837 |
| 024338 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:40am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509314.2 | 33561 | 1.64041666667 | 24338 |
| 024297 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:41am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593939.3 | 509314.4 | 33563 | 1.64041666667 | 24297 |
| 023414 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:42am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593939.2 | 509314.5 | 33565 | 1.64041666667 | 23414 |
| 021843 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:43am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593939.1 | 509314.8 | 33567 | 1.64041666667 | 21843 |
| 022020 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:44am | Sensor | 1797-S0030-868-G-TJV | 6808.6 | 1593939.1 | 509315.2 | 33569 | 1.64041666667 | 22020 |
| 022395 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:45am | Sensor | 1797-S0030-868-G-TJV | 6808.5 | 1593939.1 | 509315.2 | 33571 | 1.64041666667 | 22395 |
| 022308 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:46am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593939.2 | 509315.1 | 33573 | 1.64041666667 | 22308 |
| 024417 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:47am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593939.3 | 509314.7 | 33575 | 1.64041666667 | 24417 |
| 024074 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:48am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593939.3 | 509314.5 | 33577 | 1.64041666667 | 24074 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 025128 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:49am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593939.3 | 509314.4 | 33579 | 1.64041666667 | 25128 |
| 024462 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:50am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593939.3 | 509314.3 | 33581 | 1.64041666667 | 24462 |
| 023635 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:51am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593939.2 | 509314.3 | 33583 | 1.64041666667 | 23635 |
| 023849 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:52am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593939.2 | 509314.2 | 33585 | 1.64041666667 | 23849 |
| 022072 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:53am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593939.2 | 509314.2 | 33587 | 1.64041666667 | 22072 |
| 024748 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:54am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593939.2 | 509314.2 | 33589 | 1.64041666667 | 24748 |
| 024097 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:55am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593939.2 | 509314.3 | 33591 | 1.64041666667 | 24097 |
| 025344 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:56am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593939.2 | 509314.2 | 33593 | 1.64041666667 | 25344 |
| 023946 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:57am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593939.2 | 509314.2 | 33595 | 1.64041666667 | 23946 |
| 024496 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:58am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593939.0 | 509313.8 | 33597 | 1.64041666667 | 24496 |
| 022624 | 0 | GeoXH 6000 | 08/18/2015 | 11:01:59am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593938.7 | 509313.2 | 33599 | 1.64041666667 | 22624 |
| 022906 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:00am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593938.8 | 509313.1 | 33601 | 1.64041666667 | 22906 |
| 024626 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:01am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.0 | 509313.2 | 33603 | 1.64041666667 | 24626 |
| 023196 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:02am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593938.9 | 509313.2 | 33605 | 1.64041666667 | 23196 |
| 021519 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:03am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.0 | 509313.0 | 33607 | 1.64041666667 | 21519 |
| 021819 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:04am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.3 | 509313.1 | 33609 | 1.64041666667 | 21819 |
| 021865 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:05am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.9 | 509313.2 | 33611 | 1.64041666667 | 21865 |
| 022716 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:06am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593938.6 | 509313.1 | 33613 | 1.64041666667 | 22716 |
| 021339 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:07am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593938.4 | 509313.0 | 33615 | 1.64041666667 | 21339 |
| 022704 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:08am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.5 | 509313.2 | 33617 | 1.64041666667 | 22704 |
| 021966 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:09am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.6 | 509313.3 | 33619 | 1.64041666667 | 21966 |
| 022021 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:10am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.6 | 509313.3 | 33621 | 1.64041666667 | 22021 |
| 022875 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:11am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.7 | 509313.4 | 33623 | 1.64041666667 | 22875 |
| 021768 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:12am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.7 | 509313.3 | 33625 | 1.64041666667 | 21768 |
| 022722 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:13am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.7 | 509313.3 | 33627 | 1.64041666667 | 22722 |
| 023560 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:14am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.7 | 509313.4 | 33629 | 1.64041666667 | 23560 |
| 021460 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:15am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.7 | 509313.4 | 33631 | 1.64041666667 | 21460 |
| 023995 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:16am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.8 | 509313.4 | 33633 | 1.64041666667 | 23995 |
| 021208 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:17am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.8 | 509313.4 | 33635 | 1.64041666667 | 21208 |
| 021052 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:18am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.8 | 509313.3 | 33637 | 1.64041666667 | 21052 |
| 021253 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:19am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.8 | 509313.3 | 33639 | 1.64041666667 | 21253 |
| 021543 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:20am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593938.8 | 509313.4 | 33641 | 1.64041666667 | 21543 |
| 023115 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:21am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593938.8 | 509313.4 | 33643 | 1.64041666667 | 23115 |
| 023268 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:22am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593938.7 | 509313.5 | 33645 | 1.64041666667 | 23268 |
| 024027 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:23am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593938.9 | 509313.5 | 33647 | 1.64041666667 | 24027 |
| 022837 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:24am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.1 | 509313.4 | 33649 | 1.64041666667 | 22837 |
| 022359 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:25am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.2 | 509313.2 | 33651 | 1.64041666667 | 22359 |
| 021969 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:26am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.2 | 509313.2 | 33653 | 1.64041666667 | 21969 |
| 023222 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:27am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.2 | 509313.2 | 33655 | 1.64041666667 | 23222 |
| 023655 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:28am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593938.8 | 509313.2 | 33657 | 1.64041666667 | 23655 |
| 021483 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:29am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593938.3 | 509313.1 | 33659 | 1.64041666667 | 21483 |
| 022411 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:30am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593938.1 | 509313.3 | 33661 | 1.64041666667 | 22411 |
| 022582 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:31am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593938.3 | 509313.4 | 33663 | 1.64041666667 | 22582 |
| 021245 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:32am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593939.1 | 509313.4 | 33665 | 1.64041666667 | 21245 |
| 020431 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:33am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593940.0 | 509312.9 | 33667 | 1.64041666667 | 20431 |
| 022507 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:34am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.9 | 509313.0 | 33669 | 1.64041666667 | 22507 |
| 022397 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:35am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.8 | 509313.2 | 33671 | 1.64041666667 | 22397 |
| 020989 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:36am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.6 | 509313.4 | 33673 | 1.64041666667 | 20989 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 021867 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:37am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593939.8 | 509313.8 | 33675 | 1.64041666667 | 21867 |
| 021967 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:38am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593940.1 | 509314.0 | 33677 | 1.64041666667 | 21967 |
| 021031 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:39am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593940.4 | 509313.9 | 33679 | 1.64041666667 | 21031 |
| 021427 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:40am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593940.4 | 509313.9 | 33681 | 1.64041666667 | 21427 |
| 023177 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:41am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593940.3 | 509313.8 | 33683 | 1.64041666667 | 23177 |
| 023524 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:42am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593940.3 | 509313.8 | 33685 | 1.64041666667 | 23524 |
| 022231 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:43am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593940.2 | 509313.8 | 33687 | 1.64041666667 | 22231 |
| 022477 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:44am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593940.3 | 509314.1 | 33689 | 1.64041666667 | 22477 |
| 021849 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:45am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593940.3 | 509314.0 | 33691 | 1.64041666667 | 21849 |
| 021632 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:46am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593940.2 | 509314.1 | 33693 | 1.64041666667 | 21632 |
| 022178 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:47am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593940.5 | 509314.6 | 33695 | 1.64041666667 | 22178 |
| 021504 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:48am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593941.1 | 509314.9 | 33697 | 1.64041666667 | 21504 |
| 022326 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:49am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593941.6 | 509316.1 | 33699 | 1.64041666667 | 22326 |
| 020671 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:50am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593942.3 | 509316.9 | 33701 | 1.64041666667 | 20671 |
| 021487 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:51am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593942.1 | 509317.5 | 33703 | 1.64041666667 | 21487 |
| 019712 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:52am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593942.5 | 509318.6 | 33705 | 1.64041666667 | 19712 |
| 019538 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:53am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593942.6 | 509320.1 | 33707 | 1.64041666667 | 19538 |
| 019224 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:54am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593942.8 | 509322.0 | 33709 | 1.64041666667 | 19224 |
| 019356 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:55am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593942.7 | 509324.3 | 33711 | 1.64041666667 | 19356 |
| 019299 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:56am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593942.6 | 509326.3 | 33713 | 1.64041666667 | 19299 |
| 019434 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:57am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593941.8 | 509327.9 | 33715 | 1.64041666667 | 19434 |
| 016948 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:58am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593940.5 | 509329.8 | 33717 | 1.64041666667 | 16948 |
| 018307 | 0 | GeoXH 6000 | 08/18/2015 | 11:02:59am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593938.8 | 509331.5 | 33719 | 1.64041666667 | 18307 |
| 018226 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:00am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593936.7 | 509333.4 | 33721 | 1.64041666667 | 18226 |
| 017186 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:01am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593935.2 | 509335.5 | 33723 | 1.64041666667 | 17186 |
| 015096 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:02am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593934.0 | 509337.5 | 33725 | 1.64041666667 | 15096 |
| 015144 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:03am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593933.1 | 509339.7 | 33727 | 1.64041666667 | 15144 |
| 016566 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:04am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593932.0 | 509341.4 | 33729 | 1.64041666667 | 16566 |
| 014911 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:05am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593931.6 | 509343.2 | 33731 | 1.64041666667 | 14911 |
| 014887 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:06am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593930.7 | 509344.7 | 33733 | 1.64041666667 | 14887 |
| 016262 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:07am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593930.5 | 509347.2 | 33735 | 1.64041666667 | 16262 |
| 017565 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:08am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593930.3 | 509349.5 | 33737 | 1.64041666667 | 17565 |
| 015521 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:09am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593931.2 | 509351.8 | 33739 | 1.64041666667 | 15521 |
| 016300 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:10am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593931.1 | 509354.2 | 33741 | 1.64041666667 | 16300 |
| 014575 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:11am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593931.5 | 509356.1 | 33743 | 1.64041666667 | 14575 |
| 015583 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:12am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593931.5 | 509356.7 | 33745 | 1.64041666667 | 15583 |
| 017576 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:13am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593931.4 | 509356.7 | 33747 | 1.64041666667 | 17576 |
| 014264 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:14am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593931.6 | 509356.9 | 33749 | 1.64041666667 | 14264 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:15am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593932.2 | 509357.2 | 33751 | 1.64041666667 | 14516 |
| 014399 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:16am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593932.2 | 509358.2 | 33753 | 1.64041666667 | 14399 |
| 015689 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:17am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593932.5 | 509360.1 | 33755 | 1.64041666667 | 15689 |
| 014572 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:18am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593932.4 | 509361.9 | 33757 | 1.64041666667 | 14572 |
| 014413 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:19am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593931.8 | 509363.5 | 33759 | 1.64041666667 | 14413 |
| 014073 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:20am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593930.5 | 509364.7 | 33761 | 1.64041666667 | 14073 |
| 014468 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:21am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593928.6 | 509365.0 | 33763 | 1.64041666667 | 14468 |
| 015407 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:22am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593927.7 | 509366.9 | 33765 | 1.64041666667 | 15407 |
| 013331 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:23am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593926.6 | 509368.9 | 33767 | 1.64041666667 | 13331 |
| 014646 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:24am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593926.1 | 509371.7 | 33769 | 1.64041666667 | 14646 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016065 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:25am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593925.6 | 509374.1 | 33771 | 1.64041666667 | 16065 |
| 014846 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:26am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593924.7 | 509376.3 | 33773 | 1.64041666667 | 14846 |
| 015681 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:27am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593923.6 | 509378.5 | 33775 | 1.64041666667 | 15681 |
| 015410 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:28am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593922.1 | 509379.4 | 33777 | 1.64041666667 | 15410 |
| 014082 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:29am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593922.2 | 509379.5 | 33779 | 1.64041666667 | 14082 |
| 015010 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:30am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593921.9 | 509379.8 | 33781 | 1.64041666667 | 15010 |
| 013772 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:31am | Sensor | 1797-S0030-868-G-TJV | 6808.6 | 1593921.2 | 509381.8 | 33783 | 1.64041666667 | 13772 |
| 014183 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:32am | Sensor | 1797-S0030-868-G-TJV | 6808.4 | 1593920.3 | 509383.1 | 33785 | 1.64041666667 | 14183 |
| 015005 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:33am | Sensor | 1797-S0030-868-G-TJV | 6808.3 | 1593919.3 | 509385.5 | 33787 | 1.64041666667 | 15005 |
| 014431 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:34am | Sensor | 1797-S0030-868-G-TJV | 6808.0 | 1593918.2 | 509387.3 | 33789 | 1.64041666667 | 14431 |
| 014437 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:35am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593917.9 | 509389.7 | 33791 | 1.64041666667 | 14437 |
| 013449 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:36am | Sensor | 1797-S0030-868-G-TJV | 6807.2 | 1593917.9 | 509391.7 | 33793 | 1.64041666667 | 13449 |
| 013622 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:37am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593917.1 | 509394.0 | 33795 | 1.64041666667 | 13622 |
| 013935 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:38am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593916.5 | 509396.2 | 33797 | 1.64041666667 | 13935 |
| 014373 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:39am | Sensor | 1797-S0030-868-G-TJV | 6806.9 | 1593915.4 | 509398.3 | 33799 | 1.64041666667 | 14373 |
| 013823 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:40am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593914.7 | 509400.4 | 33801 | 1.64041666667 | 13823 |
| 014466 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:41am | Sensor | 1797-S0030-868-G-TJV | 6806.6 | 1593913.4 | 509403.0 | 33803 | 1.64041666667 | 14466 |
| 013876 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:42am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593912.8 | 509405.0 | 33805 | 1.64041666667 | 13876 |
| 014899 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:43am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593911.6 | 509406.5 | 33807 | 1.64041666667 | 14899 |
| 014614 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:44am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1593911.3 | 509408.3 | 33809 | 1.64041666667 | 14614 |
| 013163 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:45am | Sensor | 1797-S0030-868-G-TJV | 6806.1 | 1593909.5 | 509409.9 | 33811 | 1.64041666667 | 13163 |
| 013041 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:46am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593907.5 | 509411.6 | 33813 | 1.64041666667 | 13041 |
| 012740 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:47am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593905.6 | 509413.0 | 33815 | 1.64041666667 | 12740 |
| 013775 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:48am | Sensor | 1797-S0030-868-G-TJV | 6805.9 | 1593903.9 | 509414.9 | 33817 | 1.64041666667 | 13775 |
| 014123 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:49am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593903.0 | 509417.1 | 33819 | 1.64041666667 | 14123 |
| 014961 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:50am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1593902.0 | 509419.4 | 33821 | 1.64041666667 | 14961 |
| 013280 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:51am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593901.3 | 509421.9 | 33823 | 1.64041666667 | 13280 |
| 011060 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:52am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593899.9 | 509424.0 | 33825 | 1.64041666667 | 11060 |
| 013955 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:53am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593898.9 | 509426.6 | 33827 | 1.64041666667 | 13955 |
| 013268 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:54am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593897.8 | 509429.8 | 33829 | 1.64041666667 | 13268 |
| 012737 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:55am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593896.6 | 509432.6 | 33831 | 1.64041666667 | 12737 |
| 012874 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:56am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593895.8 | 509434.7 | 33833 | 1.64041666667 | 12874 |
| 013148 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:57am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593893.8 | 509435.4 | 33835 | 1.64041666667 | 13148 |
| 014837 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:58am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593891.6 | 509435.5 | 33837 | 1.64041666667 | 14837 |
| 013249 | 0 | GeoXH 6000 | 08/18/2015 | 11:03:59am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593890.2 | 509434.0 | 33839 | 1.64041666667 | 13249 |
| 015072 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:00am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593888.7 | 509432.3 | 33841 | 1.64041666667 | 15072 |
| 013728 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:01am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593887.8 | 509430.6 | 33843 | 1.64041666667 | 13728 |
| 014202 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:02am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1593887.1 | 509429.4 | 33845 | 1.64041666667 | 14202 |
| 013840 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:03am | Sensor | 1797-S0030-868-G-TJV | 6805.3 | 1593886.3 | 509427.7 | 33847 | 1.64041666667 | 13840 |
| 013210 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:04am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593885.6 | 509426.1 | 33849 | 1.64041666667 | 13210 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:05am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593885.5 | 509423.8 | 33851 | 1.64041666667 | 13442 |
| 014010 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:06am | Sensor | 1797-S0030-868-G-TJV | 6805.9 | 1593886.2 | 509422.2 | 33853 | 1.64041666667 | 14010 |
| 013192 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:07am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593887.7 | 509420.3 | 33855 | 1.64041666667 | 13192 |
| 014908 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:08am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593889.1 | 509418.6 | 33857 | 1.64041666667 | 14908 |
| 016237 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:09am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1593890.4 | 509416.9 | 33859 | 1.64041666667 | 16237 |
| 015849 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:10am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593891.5 | 509415.6 | 33861 | 1.64041666667 | 15849 |
| 012782 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:11am | Sensor | 1797-S0030-868-G-TJV | 6806.6 | 1593892.2 | 509412.9 | 33863 | 1.64041666667 | 12782 |
| 014535 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:12am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593892.8 | 509411.3 | 33865 | 1.64041666667 | 14535 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015033 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:13am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593893.0 | 509409.3 | 33867 | 1.64041666667 | 15033 |
| 013748 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:14am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593894.2 | 509407.6 | 33869 | 1.64041666667 | 13748 |
| 014957 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:15am | Sensor | 1797-S0030-868-G-TJV | 6807.2 | 1593894.8 | 509405.5 | 33871 | 1.64041666667 | 14957 |
| 013669 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:16am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593895.8 | 509404.1 | 33873 | 1.64041666667 | 13669 |
| 013977 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:17am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593896.0 | 509401.7 | 33875 | 1.64041666667 | 13977 |
| 013004 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:18am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593896.9 | 509400.4 | 33877 | 1.64041666667 | 13004 |
| 011951 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:19am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593897.1 | 509398.1 | 33879 | 1.64041666667 | 11951 |
| 013457 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:20am | Sensor | 1797-S0030-868-G-TJV | 6808.0 | 1593898.2 | 509396.7 | 33881 | 1.64041666667 | 13457 |
| 013324 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:21am | Sensor | 1797-S0030-868-G-TJV | 6808.3 | 1593898.8 | 509394.7 | 33883 | 1.64041666667 | 13324 |
| 013531 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:22am | Sensor | 1797-S0030-868-G-TJV | 6808.6 | 1593899.5 | 509393.5 | 33885 | 1.64041666667 | 13531 |
| 016042 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:23am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593900.2 | 509391.8 | 33887 | 1.64041666667 | 16042 |
| 015590 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:24am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593901.4 | 509391.0 | 33889 | 1.64041666667 | 15590 |
| 016167 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:25am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593902.2 | 509389.3 | 33891 | 1.64041666667 | 16167 |
| 015142 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:26am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593903.7 | 509388.3 | 33893 | 1.64041666667 | 15142 |
| 014465 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:27am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593905.5 | 509386.5 | 33895 | 1.64041666667 | 14465 |
| 013636 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:28am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593907.2 | 509385.3 | 33897 | 1.64041666667 | 13636 |
| 016489 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:29am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593908.1 | 509383.1 | 33899 | 1.64041666667 | 16489 |
| 015522 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:30am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593908.7 | 509381.5 | 33901 | 1.64041666667 | 15522 |
| 013750 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:31am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593909.2 | 509379.1 | 33903 | 1.64041666667 | 13750 |
| 013427 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:32am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593910.1 | 509377.0 | 33905 | 1.64041666667 | 13427 |
| 015326 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:33am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593911.1 | 509374.9 | 33907 | 1.64041666667 | 15326 |
| 016161 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:34am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593911.7 | 509373.0 | 33909 | 1.64041666667 | 16161 |
| 014390 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:35am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593912.4 | 509370.6 | 33911 | 1.64041666667 | 14390 |
| 015597 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:36am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593912.6 | 509368.6 | 33913 | 1.64041666667 | 15597 |
| 014939 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:37am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593913.6 | 509366.2 | 33915 | 1.64041666667 | 14939 |
| 014715 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:38am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593914.3 | 509364.2 | 33917 | 1.64041666667 | 14715 |
| 014958 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:39am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593916.3 | 509362.2 | 33919 | 1.64041666667 | 14958 |
| 013999 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:40am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593917.3 | 509360.3 | 33921 | 1.64041666667 | 13999 |
| 013129 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:41am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593919.1 | 509357.8 | 33923 | 1.64041666667 | 13129 |
| 016332 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:42am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593920.1 | 509356.0 | 33925 | 1.64041666667 | 16332 |
| 016713 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:43am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593921.2 | 509353.5 | 33927 | 1.64041666667 | 16713 |
| 016058 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:44am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593921.7 | 509351.9 | 33929 | 1.64041666667 | 16058 |
| 015324 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:45am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593922.8 | 509348.4 | 33931 | 1.64041666667 | 15324 |
| 017931 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:46am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593924.1 | 509346.7 | 33933 | 1.64041666667 | 17931 |
| 015222 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:47am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593925.0 | 509343.9 | 33935 | 1.64041666667 | 15222 |
| 015295 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:48am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593925.8 | 509341.7 | 33937 | 1.64041666667 | 15295 |
| 015404 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:49am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593926.2 | 509338.3 | 33939 | 1.64041666667 | 15404 |
| 016931 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:50am | Sensor | 1797-S0030-868-G-TJV | 6808.6 | 1593926.6 | 509335.9 | 33941 | 1.64041666667 | 16931 |
| 018392 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:51am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593926.7 | 509333.1 | 33943 | 1.64041666667 | 18392 |
| 016208 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:52am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593927.1 | 509330.7 | 33945 | 1.64041666667 | 16208 |
| 017492 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:53am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593928.7 | 509328.4 | 33947 | 1.64041666667 | 17492 |
| 016973 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:54am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593930.3 | 509326.8 | 33949 | 1.64041666667 | 16973 |
| 016183 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:55am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593932.7 | 509325.9 | 33951 | 1.64041666667 | 16183 |
| 015806 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:56am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593934.6 | 509325.5 | 33953 | 1.64041666667 | 15806 |
| 018471 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:57am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593936.3 | 509327.3 | 33955 | 1.64041666667 | 18471 |
| 017847 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:58am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593937.5 | 509329.1 | 33957 | 1.64041666667 | 17847 |
| 016492 | 0 | GeoXH 6000 | 08/18/2015 | 11:04:59am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593937.5 | 509331.3 | 33959 | 1.64041666667 | 16492 |
| 017353 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:00am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593937.7 | 509333.0 | 33961 | 1.64041666667 | 17353 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016908 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:01am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593936.3 | 509334.7 | 33963 | 1.64041666667 | 16908 |
| 016797 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:02am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593935.4 | 509336.4 | 33965 | 1.64041666667 | 16797 |
| 017789 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:03am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593933.5 | 509336.6 | 33967 | 1.64041666667 | 17789 |
| 016717 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:04am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593931.8 | 509337.4 | 33969 | 1.64041666667 | 16717 |
| 016599 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:05am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593930.3 | 509337.8 | 33971 | 1.64041666667 | 16599 |
| 015909 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:06am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593931.0 | 509339.3 | 33973 | 1.64041666667 | 15909 |
| 016307 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:07am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593931.9 | 509340.6 | 33975 | 1.64041666667 | 16307 |
| 016586 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:08am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593933.0 | 509341.4 | 33977 | 1.64041666667 | 16586 |
| 016266 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:09am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593934.0 | 509342.9 | 33979 | 1.64041666667 | 16266 |
| 015496 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:10am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593936.4 | 509344.5 | 33981 | 1.64041666667 | 15496 |
| 015634 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:11am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593937.9 | 509346.4 | 33983 | 1.64041666667 | 15634 |
| 017018 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:12am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593939.2 | 509347.7 | 33985 | 1.64041666667 | 17018 |
| 017394 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:13am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593939.1 | 509349.8 | 33987 | 1.64041666667 | 17394 |
| 015238 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:14am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593939.1 | 509351.6 | 33989 | 1.64041666667 | 15238 |
| 014639 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:15am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593938.9 | 509353.0 | 33991 | 1.64041666667 | 14639 |
| 014400 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:16am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593939.8 | 509354.5 | 33993 | 1.64041666667 | 14400 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:17am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593940.4 | 509355.1 | 33995 | 1.64041666667 | 13560 |
| 013800 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:18am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593940.7 | 509355.1 | 33997 | 1.64041666667 | 13800 |
| 013470 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:19am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593939.0 | 509355.5 | 33999 | 1.64041666667 | 13470 |
| 015007 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:20am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593937.2 | 509355.6 | 34001 | 1.64041666667 | 15007 |
| 014041 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:21am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593935.4 | 509356.3 | 34003 | 1.64041666667 | 14041 |
| 014850 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:22am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593933.7 | 509357.0 | 34005 | 1.64041666667 | 14850 |
| 014362 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:23am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593931.8 | 509358.4 | 34007 | 1.64041666667 | 14362 |
| 014180 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:24am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593930.1 | 509359.2 | 34009 | 1.64041666667 | 14180 |
| 014675 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:25am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593928.2 | 509360.5 | 34011 | 1.64041666667 | 14675 |
| 016538 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:26am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593926.3 | 509361.1 | 34013 | 1.64041666667 | 16538 |
| 015744 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:27am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593924.5 | 509362.7 | 34015 | 1.64041666667 | 15744 |
| 014226 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:28am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593923.0 | 509363.4 | 34017 | 1.64041666667 | 14226 |
| 014686 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:29am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593921.3 | 509364.9 | 34019 | 1.64041666667 | 14686 |
| 014921 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:30am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593920.1 | 509366.1 | 34021 | 1.64041666667 | 14921 |
| 014620 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:31am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593919.6 | 509368.1 | 34023 | 1.64041666667 | 14620 |
| 014875 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:32am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593918.9 | 509370.2 | 34025 | 1.64041666667 | 14875 |
| 015118 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:33am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593918.8 | 509372.4 | 34027 | 1.64041666667 | 15118 |
| 015029 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:34am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593918.6 | 509374.0 | 34029 | 1.64041666667 | 15029 |
| 014917 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:35am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593918.2 | 509376.1 | 34031 | 1.64041666667 | 14917 |
| 013989 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:36am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593917.8 | 509377.5 | 34033 | 1.64041666667 | 13989 |
| 012917 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:37am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593916.4 | 509379.5 | 34035 | 1.64041666667 | 12917 |
| 013909 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:38am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593915.8 | 509380.9 | 34037 | 1.64041666667 | 13909 |
| 014997 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:39am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593914.6 | 509382.8 | 34039 | 1.64041666667 | 14997 |
| 015179 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:40am | Sensor | 1797-S0030-868-G-TJV | 6808.7 | 1593914.4 | 509384.4 | 34041 | 1.64041666667 | 15179 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:41am | Sensor | 1797-S0030-868-G-TJV | 6808.4 | 1593913.7 | 509386.8 | 34043 | 1.64041666667 | 14655 |
| 015513 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:42am | Sensor | 1797-S0030-868-G-TJV | 6808.1 | 1593913.8 | 509388.6 | 34045 | 1.64041666667 | 15513 |
| 015518 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:43am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593913.3 | 509390.3 | 34047 | 1.64041666667 | 15518 |
| 013239 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:44am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593913.6 | 509392.2 | 34049 | 1.64041666667 | 13239 |
| 013870 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:45am | Sensor | 1797-S0030-868-G-TJV | 6807.4 | 1593913.7 | 509395.4 | 34051 | 1.64041666667 | 13870 |
| 013697 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:46am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593913.7 | 509397.4 | 34053 | 1.64041666667 | 13697 |
| 015184 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:47am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593912.6 | 509399.8 | 34055 | 1.64041666667 | 15184 |
| 012946 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:48am | Sensor | 1797-S0030-868-G-TJV | 6806.9 | 1593911.8 | 509401.5 | 34057 | 1.64041666667 | 12946 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014276 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:49am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593910.2 | 509403.2 | 34059 | 1.64041666667 | 14276 |
| 015179 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:50am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593909.6 | 509404.7 | 34061 | 1.64041666667 | 15179 |
| 015885 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:51am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593908.1 | 509405.1 | 34063 | 1.64041666667 | 15885 |
| 013181 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:52am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593906.4 | 509406.1 | 34065 | 1.64041666667 | 13181 |
| 014425 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:53am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593904.2 | 509406.2 | 34067 | 1.64041666667 | 14425 |
| 013746 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:54am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593902.9 | 509407.4 | 34069 | 1.64041666667 | 13746 |
| 014236 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:55am | Sensor | 1797-S0030-868-G-TJV | 6806.6 | 1593900.7 | 509408.6 | 34071 | 1.64041666667 | 14236 |
| 013999 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:56am | Sensor | 1797-S0030-868-G-TJV | 6806.6 | 1593899.3 | 509410.1 | 34073 | 1.64041666667 | 13999 |
| 013579 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:57am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593897.7 | 509411.9 | 34075 | 1.64041666667 | 13579 |
| 013235 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:58am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1593897.0 | 509413.8 | 34077 | 1.64041666667 | 13235 |
| 014288 | 0 | GeoXH 6000 | 08/18/2015 | 11:05:59am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593896.5 | 509416.2 | 34079 | 1.64041666667 | 14288 |
| 013502 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:00am | Sensor | 1797-S0030-868-G-TJV | 6805.8 | 1593895.9 | 509418.1 | 34081 | 1.64041666667 | 13502 |
| 013575 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:01am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593895.4 | 509420.7 | 34083 | 1.64041666667 | 13575 |
| 013113 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:02am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1593894.7 | 509422.7 | 34085 | 1.64041666667 | 13113 |
| 014288 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:03am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1593895.0 | 509425.3 | 34087 | 1.64041666667 | 14288 |
| 014222 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:04am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593895.1 | 509427.3 | 34089 | 1.64041666667 | 14222 |
| 014505 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:05am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593896.5 | 509429.4 | 34091 | 1.64041666667 | 14505 |
| 014546 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:06am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593897.5 | 509430.7 | 34093 | 1.64041666667 | 14546 |
| 014676 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:07am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593900.3 | 509430.5 | 34095 | 1.64041666667 | 14676 |
| 012249 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:08am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593902.6 | 509430.6 | 34097 | 1.64041666667 | 12249 |
| 013832 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:09am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593905.6 | 509429.4 | 34099 | 1.64041666667 | 13832 |
| 014588 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:10am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593908.2 | 509427.9 | 34101 | 1.64041666667 | 14588 |
| 014057 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:11am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593910.4 | 509425.9 | 34103 | 1.64041666667 | 14057 |
| 014944 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:12am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593911.3 | 509423.6 | 34105 | 1.64041666667 | 14944 |
| 014056 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:13am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593912.4 | 509421.6 | 34107 | 1.64041666667 | 14056 |
| 015334 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:14am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593913.0 | 509420.0 | 34109 | 1.64041666667 | 15334 |
| 014393 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:15am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593913.4 | 509417.8 | 34111 | 1.64041666667 | 14393 |
| 014848 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:16am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593913.7 | 509415.6 | 34113 | 1.64041666667 | 14848 |
| 014242 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:17am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593913.7 | 509412.9 | 34115 | 1.64041666667 | 14242 |
| 015080 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:18am | Sensor | 1797-S0030-868-G-TJV | 6805.8 | 1593914.0 | 509410.7 | 34117 | 1.64041666667 | 15080 |
| 017090 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:19am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593914.1 | 509408.4 | 34119 | 1.64041666667 | 17090 |
| 015625 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:20am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593914.5 | 509406.7 | 34121 | 1.64041666667 | 15625 |
| 014088 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:21am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593914.7 | 509403.9 | 34123 | 1.64041666667 | 14088 |
| 014022 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:22am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593915.4 | 509401.9 | 34125 | 1.64041666667 | 14022 |
| 014275 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:23am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593915.7 | 509399.1 | 34127 | 1.64041666667 | 14275 |
| 014009 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:24am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593916.2 | 509397.2 | 34129 | 1.64041666667 | 14009 |
| 015652 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:25am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593917.1 | 509395.4 | 34131 | 1.64041666667 | 15652 |
| 014413 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:26am | Sensor | 1797-S0030-868-G-TJV | 6807.2 | 1593918.5 | 509393.2 | 34133 | 1.64041666667 | 14413 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:27am | Sensor | 1797-S0030-868-G-TJV | 6807.4 | 1593920.3 | 509391.2 | 34135 | 1.64041666667 | 14283 |
| 013890 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:28am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593921.5 | 509389.1 | 34137 | 1.64041666667 | 13890 |
| 013942 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:29am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593922.9 | 509387.0 | 34139 | 1.64041666667 | 13942 |
| 012605 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:30am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593923.9 | 509384.9 | 34141 | 1.64041666667 | 12605 |
| 013681 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:31am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593925.4 | 509382.4 | 34143 | 1.64041666667 | 13681 |
| 014850 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:32am | Sensor | 1797-S0030-868-G-TJV | 6808.1 | 1593926.7 | 509381.3 | 34145 | 1.64041666667 | 14850 |
| 014812 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:33am | Sensor | 1797-S0030-868-G-TJV | 6808.3 | 1593928.1 | 509379.1 | 34147 | 1.64041666667 | 14812 |
| 013873 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:34am | Sensor | 1797-S0030-868-G-TJV | 6808.5 | 1593929.1 | 509377.7 | 34149 | 1.64041666667 | 13873 |
| 013968 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:35am | Sensor | 1797-S0030-868-G-TJV | 6808.7 | 1593930.5 | 509375.3 | 34151 | 1.64041666667 | 13968 |
| 014262 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:36am | Sensor | 1797-S0030-868-G-TJV | 6808.7 | 1593931.9 | 509373.6 | 34153 | 1.64041666667 | 14262 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014635 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:37am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593933.4 | 509371.2 | 34155 | 1.64041666667 | 14635 |
| 014789 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:38am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593934.7 | 509369.2 | 34157 | 1.64041666667 | 14789 |
| 014617 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:39am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593936.9 | 509367.1 | 34159 | 1.64041666667 | 14617 |
| 014334 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:40am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593938.0 | 509365.1 | 34161 | 1.64041666667 | 14334 |
| 015973 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:41am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593939.7 | 509362.7 | 34163 | 1.64041666667 | 15973 |
| 015783 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:42am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593940.4 | 509360.5 | 34165 | 1.64041666667 | 15783 |
| 013515 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:43am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593941.6 | 509358.0 | 34167 | 1.64041666667 | 13515 |
| 015678 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:44am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593942.9 | 509355.2 | 34169 | 1.64041666667 | 15678 |
| 015859 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:45am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593944.3 | 509352.6 | 34171 | 1.64041666667 | 15859 |
| 016175 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:46am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593945.8 | 509350.2 | 34173 | 1.64041666667 | 16175 |
| 016013 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:47am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593946.8 | 509347.3 | 34175 | 1.64041666667 | 16013 |
| 016303 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:48am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593948.3 | 509345.7 | 34177 | 1.64041666667 | 16303 |
| 017216 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:49am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593949.7 | 509343.0 | 34179 | 1.64041666667 | 17216 |
| 016124 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:50am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593950.8 | 509341.2 | 34181 | 1.64041666667 | 16124 |
| 015461 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:51am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593952.3 | 509338.7 | 34183 | 1.64041666667 | 15461 |
| 017095 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:52am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593953.2 | 509336.3 | 34185 | 1.64041666667 | 17095 |
| 015853 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:53am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593954.9 | 509333.5 | 34187 | 1.64041666667 | 15853 |
| 017043 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:54am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593955.5 | 509331.6 | 34189 | 1.64041666667 | 17043 |
| 017100 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:55am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593957.5 | 509330.8 | 34191 | 1.64041666667 | 17100 |
| 015495 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:56am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593960.1 | 509330.1 | 34193 | 1.64041666667 | 15495 |
| 016593 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:57am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593961.6 | 509331.3 | 34195 | 1.64041666667 | 16593 |
| 017108 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:58am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593961.7 | 509333.0 | 34197 | 1.64041666667 | 17108 |
| 015707 | 0 | GeoXH 6000 | 08/18/2015 | 11:06:59am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593962.4 | 509335.9 | 34199 | 1.64041666667 | 15707 |
| 015566 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:00am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593962.3 | 509338.1 | 34201 | 1.64041666667 | 15566 |
| 014991 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:01am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593962.0 | 509340.9 | 34203 | 1.64041666667 | 14991 |
| 016018 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:02am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593961.1 | 509343.8 | 34205 | 1.64041666667 | 16018 |
| 015914 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:03am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593959.7 | 509346.1 | 34207 | 1.64041666667 | 15914 |
| 014298 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:04am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593958.9 | 509348.3 | 34209 | 1.64041666667 | 14298 |
| 012634 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:05am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593957.1 | 509350.7 | 34211 | 1.64041666667 | 12634 |
| 014888 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:06am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593956.0 | 509353.0 | 34213 | 1.64041666667 | 14888 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:07am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593955.0 | 509355.7 | 34215 | 1.64041666667 | 13742 |
| 014985 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:08am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593953.7 | 509358.1 | 34217 | 1.64041666667 | 14985 |
| 016736 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:09am | Sensor | 1797-S0030-868-G-TJV | 6808.7 | 1593952.2 | 509360.7 | 34219 | 1.64041666667 | 16736 |
| 015614 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:10am | Sensor | 1797-S0030-868-G-TJV | 6808.6 | 1593950.5 | 509362.8 | 34221 | 1.64041666667 | 15614 |
| 015153 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:11am | Sensor | 1797-S0030-868-G-TJV | 6808.1 | 1593949.0 | 509365.8 | 34223 | 1.64041666667 | 15153 |
| 013838 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:12am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593947.9 | 509368.2 | 34225 | 1.64041666667 | 13838 |
| 014409 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:13am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593946.6 | 509370.5 | 34227 | 1.64041666667 | 14409 |
| 016832 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:14am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593946.2 | 509372.5 | 34229 | 1.64041666667 | 16832 |
| 016658 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:15am | Sensor | 1797-S0030-868-G-TJV | 6807.4 | 1593944.8 | 509375.3 | 34231 | 1.64041666667 | 16658 |
| 015654 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:16am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593944.3 | 509377.4 | 34233 | 1.64041666667 | 15654 |
| 013213 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:17am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593943.0 | 509380.2 | 34235 | 1.64041666667 | 13213 |
| 014733 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:18am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593941.9 | 509382.3 | 34237 | 1.64041666667 | 14733 |
| 015143 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:19am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593941.3 | 509385.1 | 34239 | 1.64041666667 | 15143 |
| 015215 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:20am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593940.3 | 509387.5 | 34241 | 1.64041666667 | 15215 |
| 014364 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:21am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593940.7 | 509389.6 | 34243 | 1.64041666667 | 14364 |
| 015141 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:22am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593942.0 | 509391.7 | 34245 | 1.64041666667 | 15141 |
| 016145 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:23am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593944.8 | 509390.5 | 34247 | 1.64041666667 | 16145 |
| 014836 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:24am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593946.6 | 509389.5 | 34249 | 1.64041666667 | 14836 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013969 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:25am | Sensor | 1797-S0030-868-G-TJV | 6806.1 | 1593947.8 | 509386.3 | 34251 | 1.64041666667 | 13969 |
| 013002 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:26am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593949.4 | 509384.5 | 34253 | 1.64041666667 | 13002 |
| 015790 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:27am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1593950.6 | 509381.7 | 34255 | 1.64041666667 | 15790 |
| 013775 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:28am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593951.7 | 509379.2 | 34257 | 1.64041666667 | 13775 |
| 014216 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:29am | Sensor | 1797-S0030-868-G-TJV | 6806.7 | 1593953.0 | 509376.4 | 34259 | 1.64041666667 | 14216 |
| 013754 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:30am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593954.1 | 509374.1 | 34261 | 1.64041666667 | 13754 |
| 013698 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:31am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593955.6 | 509372.0 | 34263 | 1.64041666667 | 13698 |
| 014344 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:32am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593956.5 | 509369.4 | 34265 | 1.64041666667 | 14344 |
| 015046 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:33am | Sensor | 1797-S0030-868-G-TJV | 6807.4 | 1593957.8 | 509366.9 | 34267 | 1.64041666667 | 15046 |
| 015101 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:34am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593958.7 | 509364.5 | 34269 | 1.64041666667 | 15101 |
| 013825 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:35am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593960.2 | 509361.4 | 34271 | 1.64041666667 | 13825 |
| 013896 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:36am | Sensor | 1797-S0030-868-G-TJV | 6808.2 | 1593961.4 | 509359.4 | 34273 | 1.64041666667 | 13896 |
| 016404 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:37am | Sensor | 1797-S0030-868-G-TJV | 6808.6 | 1593961.9 | 509357.1 | 34275 | 1.64041666667 | 16404 |
| 015471 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:38am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593963.2 | 509355.1 | 34277 | 1.64041666667 | 15471 |
| 015087 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:39am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593965.5 | 509352.0 | 34279 | 1.64041666667 | 15087 |
| 015382 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:40am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593966.6 | 509349.7 | 34281 | 1.64041666667 | 15382 |
| 015635 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:41am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593967.6 | 509347.0 | 34283 | 1.64041666667 | 15635 |
| 016568 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:42am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593968.0 | 509344.5 | 34285 | 1.64041666667 | 16568 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:43am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593968.8 | 509341.5 | 34287 | 1.64041666667 | 13742 |
| 016665 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:44am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593969.4 | 509338.9 | 34289 | 1.64041666667 | 16665 |
| 015416 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:45am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593970.4 | 509335.8 | 34291 | 1.64041666667 | 15416 |
| 014594 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:46am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593971.4 | 509334.4 | 34293 | 1.64041666667 | 14594 |
| 014238 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:47am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593973.5 | 509332.4 | 34295 | 1.64041666667 | 14238 |
| 014989 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:48am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593975.1 | 509333.2 | 34297 | 1.64041666667 | 14989 |
| 015537 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:49am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593975.9 | 509334.9 | 34299 | 1.64041666667 | 15537 |
| 015854 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:49am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593976.5 | 509336.9 | 34300 | 1.64041666667 | 15854 |
| 015723 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:51am | Sensor | 1797-S0030-868-G-TJV | 6810.0 | 1593975.7 | 509339.9 | 34303 | 1.64041666667 | 15723 |
| 013980 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:52am | Sensor | 1797-S0030-868-G-TJV | 6809.7 | 1593976.0 | 509342.3 | 34305 | 1.64041666667 | 13980 |
| 015495 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:53am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593976.1 | 509344.7 | 34307 | 1.64041666667 | 15495 |
| 016773 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:53am | Sensor | 1797-S0030-868-G-TJV | 6808.7 | 1593975.4 | 509346.6 | 34308 | 1.64041666667 | 16773 |
| 014243 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:55am | Sensor | 1797-S0030-868-G-TJV | 6808.4 | 1593974.9 | 509350.1 | 34311 | 1.64041666667 | 14243 |
| 017391 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:56am | Sensor | 1797-S0030-868-G-TJV | 6808.2 | 1593974.3 | 509351.7 | 34313 | 1.64041666667 | 17391 |
| 015477 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:57am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593974.5 | 509354.5 | 34315 | 1.64041666667 | 15477 |
| 015959 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:58am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593973.6 | 509356.3 | 34317 | 1.64041666667 | 15959 |
| 014580 | 0 | GeoXH 6000 | 08/18/2015 | 11:07:59am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593972.4 | 509358.4 | 34319 | 1.64041666667 | 14580 |
| 015315 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:00am | Sensor | 1797-S0030-868-G-TJV | 6807.2 | 1593970.6 | 509359.9 | 34321 | 1.64041666667 | 15315 |
| 014958 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:01am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593968.6 | 509361.6 | 34323 | 1.64041666667 | 14958 |
| 015679 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:02am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593967.4 | 509363.6 | 34325 | 1.64041666667 | 15679 |
| 014479 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:03am | Sensor | 1797-S0030-868-G-TJV | 6807.0 | 1593966.3 | 509365.7 | 34327 | 1.64041666667 | 14479 |
| 015230 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:04am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593966.1 | 509367.8 | 34329 | 1.64041666667 | 15230 |
| 014337 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:05am | Sensor | 1797-S0030-868-G-TJV | 6806.6 | 1593964.5 | 509370.7 | 34331 | 1.64041666667 | 14337 |
| 013214 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:06am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593964.0 | 509372.9 | 34333 | 1.64041666667 | 13214 |
| 013863 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:07am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1593963.1 | 509375.6 | 34335 | 1.64041666667 | 13863 |
| 013755 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:08am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593962.4 | 509378.2 | 34337 | 1.64041666667 | 13755 |
| 015438 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:09am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593961.4 | 509380.9 | 34339 | 1.64041666667 | 15438 |
| 014719 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:10am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593960.4 | 509382.8 | 34341 | 1.64041666667 | 14719 |
| 014180 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:11am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593959.3 | 509385.4 | 34343 | 1.64041666667 | 14180 |
| 013325 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:12am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593957.6 | 509387.5 | 34345 | 1.64041666667 | 13325 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013681 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:13am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593956.7 | 509390.6 | 34347 | 1.64041666667 | 13681 |
| 016950 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:14am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593956.0 | 509392.7 | 34349 | 1.64041666667 | 16950 |
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:15am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593955.2 | 509395.5 | 34351 | 1.64041666667 | 14227 |
| 015227 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:16am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593954.9 | 509397.4 | 34353 | 1.64041666667 | 15227 |
| 014756 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:17am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593953.3 | 509400.2 | 34355 | 1.64041666667 | 14756 |
| 014369 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:18am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593952.8 | 509402.4 | 34357 | 1.64041666667 | 14369 |
| 012532 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:19am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593953.3 | 509404.8 | 34359 | 1.64041666667 | 12532 |
| 013033 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:20am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593955.4 | 509405.3 | 34361 | 1.64041666667 | 13033 |
| 014208 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:21am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593958.9 | 509405.3 | 34363 | 1.64041666667 | 14208 |
| 014592 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:22am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593961.0 | 509404.4 | 34365 | 1.64041666667 | 14592 |
| 011898 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:23am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593961.6 | 509402.1 | 34367 | 1.64041666667 | 11898 |
| 013744 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:24am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593961.9 | 509399.4 | 34369 | 1.64041666667 | 13744 |
| 013336 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:25am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593961.9 | 509397.4 | 34371 | 1.64041666667 | 13336 |
| 014644 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:26am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593962.2 | 509395.7 | 34373 | 1.64041666667 | 14644 |
| 014371 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:27am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593962.7 | 509393.3 | 34375 | 1.64041666667 | 14371 |
| 01 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:28am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593963.5 | 509390.9 | 34377 | 1.64041666667 | 1 |
| 014683 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:29am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593964.8 | 509388.6 | 34379 | 1.64041666667 | 14683 |
| 013931 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:30am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593965.8 | 509386.2 | 34381 | 1.64041666667 | 13931 |
| 012242 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:31am | Sensor | 1797-S0030-868-G-TJV | 6805.3 | 1593966.8 | 509382.9 | 34383 | 1.64041666667 | 12242 |
| 013080 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:32am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593966.9 | 509380.3 | 34385 | 1.64041666667 | 13080 |
| 013020 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:33am | Sensor | 1797-S0030-868-G-TJV | 6805.9 | 1593967.4 | 509376.9 | 34387 | 1.64041666667 | 13020 |
| 015705 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:34am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593968.3 | 509375.1 | 34389 | 1.64041666667 | 15705 |
| 015596 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:35am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593968.8 | 509372.5 | 34391 | 1.64041666667 | 15596 |
| 015389 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:36am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1593969.6 | 509370.4 | 34393 | 1.64041666667 | 15389 |
| 014017 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:37am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593970.7 | 509367.7 | 34395 | 1.64041666667 | 14017 |
| 014694 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:38am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593972.2 | 509365.1 | 34397 | 1.64041666667 | 14694 |
| 014803 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:39am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593973.5 | 509362.3 | 34399 | 1.64041666667 | 14803 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:40am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593973.8 | 509360.1 | 34401 | 1.64041666667 | 14201 |
| 015250 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:41am | Sensor | 1797-S0030-868-G-TJV | 6807.2 | 1593974.6 | 509358.0 | 34403 | 1.64041666667 | 15250 |
| 015782 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:42am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593974.8 | 509355.5 | 34405 | 1.64041666667 | 15782 |
| 015015 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:43am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593976.1 | 509353.4 | 34407 | 1.64041666667 | 15015 |
| 014733 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:43am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593977.1 | 509351.3 | 34408 | 1.64041666667 | 14733 |
| 014963 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:45am | Sensor | 1797-S0030-868-G-TJV | 6808.2 | 1593978.1 | 509348.4 | 34411 | 1.64041666667 | 14963 |
| 015081 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:46am | Sensor | 1797-S0030-868-G-TJV | 6808.5 | 1593979.5 | 509346.3 | 34413 | 1.64041666667 | 15081 |
| 015950 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:47am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593980.1 | 509343.7 | 34415 | 1.64041666667 | 15950 |
| 015237 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:48am | Sensor | 1797-S0030-868-G-TJV | 6809.0 | 1593981.4 | 509341.6 | 34417 | 1.64041666667 | 15237 |
| 016049 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:49am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593982.0 | 509339.5 | 34419 | 1.64041666667 | 16049 |
| 015472 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:50am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593983.1 | 509337.4 | 34421 | 1.64041666667 | 15472 |
| 013558 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:51am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593984.6 | 509335.6 | 34423 | 1.64041666667 | 13558 |
| 014999 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:52am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593986.2 | 509334.5 | 34425 | 1.64041666667 | 14999 |
| 014880 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:53am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593988.1 | 509335.6 | 34427 | 1.64041666667 | 14880 |
| 016440 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:54am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593989.4 | 509337.4 | 34429 | 1.64041666667 | 16440 |
| 015450 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:55am | Sensor | 1797-S0030-868-G-TJV | 6808.5 | 1593989.1 | 509339.9 | 34431 | 1.64041666667 | 15450 |
| 016222 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:55am | Sensor | 1797-S0030-868-G-TJV | 6807.9 | 1593988.8 | 509342.0 | 34432 | 1.64041666667 | 16222 |
| 015125 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:57am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593988.2 | 509344.5 | 34435 | 1.64041666667 | 15125 |
| 015001 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:58am | Sensor | 1797-S0030-868-G-TJV | 6807.7 | 1593988.0 | 509346.2 | 34437 | 1.64041666667 | 15001 |
| 016260 | 0 | GeoXH 6000 | 08/18/2015 | 11:08:59am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593988.3 | 509348.9 | 34439 | 1.64041666667 | 16260 |
| 013695 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:00am | Sensor | 1797-S0030-868-G-TJV | 6806.9 | 1593988.6 | 509350.5 | 34441 | 1.64041666667 | 13695 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015063 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:01am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593987.9 | 509353.4 | 34443 | 1.64041666667 | 15063 |
| 014686 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:02am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593987.6 | 509356.4 | 34445 | 1.64041666667 | 14686 |
| 014711 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:03am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593987.7 | 509358.9 | 34447 | 1.64041666667 | 14711 |
| 014388 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:04am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593988.5 | 509361.5 | 34449 | 1.64041666667 | 14388 |
| 013887 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:05am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1593988.8 | 509364.2 | 34451 | 1.64041666667 | 13887 |
| 014961 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:06am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593987.5 | 509366.1 | 34453 | 1.64041666667 | 14961 |
| 014000 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:07am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1593987.0 | 509368.8 | 34455 | 1.64041666667 | 14000 |
| 013490 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:08am | Sensor | 1797-S0030-868-G-TJV | 6805.3 | 1593985.7 | 509370.8 | 34457 | 1.64041666667 | 13490 |
| 013872 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:09am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593984.7 | 509373.1 | 34459 | 1.64041666667 | 13872 |
| 013608 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:10am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593982.9 | 509375.0 | 34461 | 1.64041666667 | 13608 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:11am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593980.5 | 509377.0 | 34463 | 1.64041666667 | 13782 |
| 013555 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:12am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593978.6 | 509378.9 | 34465 | 1.64041666667 | 13555 |
| 013139 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:13am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593976.5 | 509380.7 | 34467 | 1.64041666667 | 13139 |
| 012584 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:14am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593975.9 | 509383.4 | 34469 | 1.64041666667 | 12584 |
| 013166 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:15am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593974.9 | 509386.0 | 34471 | 1.64041666667 | 13166 |
| 012861 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:16am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593974.3 | 509388.1 | 34473 | 1.64041666667 | 12861 |
| 013805 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:17am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593973.3 | 509390.4 | 34475 | 1.64041666667 | 13805 |
| 012931 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:18am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593972.0 | 509392.5 | 34477 | 1.64041666667 | 12931 |
| 012652 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:19am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593971.3 | 509395.4 | 34479 | 1.64041666667 | 12652 |
| 014293 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:20am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593970.2 | 509397.4 | 34481 | 1.64041666667 | 14293 |
| 014793 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:21am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593970.8 | 509400.3 | 34483 | 1.64041666667 | 14793 |
| 014468 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:22am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593971.3 | 509403.0 | 34485 | 1.64041666667 | 14468 |
| 014657 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:23am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593973.0 | 509404.8 | 34487 | 1.64041666667 | 14657 |
| 014164 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:24am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593975.8 | 509403.9 | 34489 | 1.64041666667 | 14164 |
| 014371 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:25am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593978.3 | 509402.2 | 34491 | 1.64041666667 | 14371 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:26am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593979.7 | 509400.4 | 34493 | 1.64041666667 | 14482 |
| 013880 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:27am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593980.5 | 509397.8 | 34495 | 1.64041666667 | 13880 |
| 014240 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:28am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593981.5 | 509396.1 | 34497 | 1.64041666667 | 14240 |
| 014180 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:29am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593981.9 | 509392.9 | 34499 | 1.64041666667 | 14180 |
| 015215 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:30am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593982.9 | 509390.8 | 34501 | 1.64041666667 | 15215 |
| 014783 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:31am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593983.6 | 509388.6 | 34503 | 1.64041666667 | 14783 |
| 015246 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:31am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593984.6 | 509387.4 | 34504 | 1.64041666667 | 15246 |
| 014251 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:33am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593985.6 | 509385.1 | 34507 | 1.64041666667 | 14251 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:34am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1593986.3 | 509383.3 | 34509 | 1.64041666667 | 13972 |
| 014503 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:35am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593987.5 | 509380.9 | 34511 | 1.64041666667 | 14503 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:36am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593987.8 | 509378.8 | 34513 | 1.64041666667 | 13736 |
| 013604 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:37am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593989.3 | 509377.0 | 34515 | 1.64041666667 | 13604 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:38am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593990.5 | 509374.7 | 34517 | 1.64041666667 | 14201 |
| 014410 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:39am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593992.3 | 509372.1 | 34519 | 1.64041666667 | 14410 |
| 013082 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:39am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593993.7 | 509369.9 | 34520 | 1.64041666667 | 13082 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:41am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1593994.9 | 509366.9 | 34523 | 1.64041666667 | 13050 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:41am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593996.3 | 509365.1 | 34524 | 1.64041666667 | 13972 |
| 012343 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:43am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593997.3 | 509362.0 | 34527 | 1.64041666667 | 12343 |
| 013706 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:43am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593998.6 | 509360.0 | 34528 | 1.64041666667 | 13706 |
| 013746 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:45am | Sensor | 1797-S0030-868-G-TJV | 6805.5 | 1593999.3 | 509356.8 | 34531 | 1.64041666667 | 13746 |
| 014326 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:46am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1594000.0 | 509354.2 | 34533 | 1.64041666667 | 14326 |
| 017381 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:47am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1594001.1 | 509351.9 | 34535 | 1.64041666667 | 17381 |
| 013585 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:48am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1594001.5 | 509349.6 | 34537 | 1.64041666667 | 13585 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014106 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:49am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1594002.8 | 509347.8 | 34539 | 1.64041666667 | 14106 |
| 014596 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:49am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1594003.1 | 509346.0 | 34540 | 1.64041666667 | 14596 |
| 014179 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:51am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1594005.0 | 509344.9 | 34543 | 1.64041666667 | 14179 |
| 013924 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:52am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1594007.2 | 509344.8 | 34545 | 1.64041666667 | 13924 |
| 013651 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:53am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1594008.9 | 509346.3 | 34547 | 1.64041666667 | 13651 |
| 014512 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:53am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1594009.1 | 509347.4 | 34548 | 1.64041666667 | 14512 |
| 013858 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:55am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1594009.7 | 509350.0 | 34551 | 1.64041666667 | 13858 |
| 015224 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:56am | Sensor | 1797-S0030-868-G-TJV | 6805.1 | 1594009.7 | 509352.1 | 34553 | 1.64041666667 | 15224 |
| 015086 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:57am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594009.1 | 509354.2 | 34555 | 1.64041666667 | 15086 |
| 014631 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:58am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594009.0 | 509356.6 | 34557 | 1.64041666667 | 14631 |
| 014337 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:59am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594008.0 | 509358.9 | 34559 | 1.64041666667 | 14337 |
| 012824 | 0 | GeoXH 6000 | 08/18/2015 | 11:09:59am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1594007.5 | 509361.3 | 34560 | 1.64041666667 | 12824 |
| 012956 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:01am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594006.5 | 509364.8 | 34563 | 1.64041666667 | 12956 |
| 012959 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:01am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594004.9 | 509366.4 | 34564 | 1.64041666667 | 12959 |
| 014579 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:03am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594003.9 | 509368.8 | 34567 | 1.64041666667 | 14579 |
| 015855 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:03am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594002.2 | 509370.6 | 34568 | 1.64041666667 | 15855 |
| 013353 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:05am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594001.2 | 509373.5 | 34571 | 1.64041666667 | 13353 |
| 014318 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:06am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594000.4 | 509376.1 | 34573 | 1.64041666667 | 14318 |
| 014679 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:07am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1593999.2 | 509378.5 | 34575 | 1.64041666667 | 14679 |
| 012850 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:08am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593998.4 | 509380.8 | 34577 | 1.64041666667 | 12850 |
| 014552 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:09am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593996.8 | 509382.8 | 34579 | 1.64041666667 | 14552 |
| 014528 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:10am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593996.4 | 509385.0 | 34581 | 1.64041666667 | 14528 |
| 013532 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:11am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1593994.9 | 509387.9 | 34583 | 1.64041666667 | 13532 |
| 012983 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:11am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1593993.9 | 509390.0 | 34584 | 1.64041666667 | 12983 |
| 015155 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:13am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1593992.8 | 509392.9 | 34587 | 1.64041666667 | 15155 |
| 013929 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:14am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593991.3 | 509395.1 | 34589 | 1.64041666667 | 13929 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:15am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593990.6 | 509397.9 | 34591 | 1.64041666667 | 13442 |
| 014220 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:16am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593989.3 | 509400.3 | 34593 | 1.64041666667 | 14220 |
| 015015 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:17am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593988.3 | 509403.0 | 34595 | 1.64041666667 | 15015 |
| 014103 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:18am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593986.9 | 509405.7 | 34597 | 1.64041666667 | 14103 |
| 014776 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:19am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593985.3 | 509407.9 | 34599 | 1.64041666667 | 14776 |
| 014104 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:20am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593984.9 | 509410.2 | 34601 | 1.64041666667 | 14104 |
| 012916 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:21am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593984.7 | 509412.6 | 34603 | 1.64041666667 | 12916 |
| 014719 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:22am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1593986.8 | 509413.1 | 34605 | 1.64041666667 | 14719 |
| 013999 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:23am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593989.1 | 509412.6 | 34607 | 1.64041666667 | 13999 |
| 013850 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:23am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593991.0 | 509411.7 | 34608 | 1.64041666667 | 13850 |
| 014112 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:25am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593993.0 | 509409.0 | 34611 | 1.64041666667 | 14112 |
| 014118 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:26am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593994.2 | 509406.9 | 34613 | 1.64041666667 | 14118 |
| 015919 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:27am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1593996.2 | 509404.3 | 34615 | 1.64041666667 | 15919 |
| 014359 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:27am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593997.3 | 509402.2 | 34616 | 1.64041666667 | 14359 |
| 013520 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:29am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593999.4 | 509400.0 | 34619 | 1.64041666667 | 13520 |
| 013040 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:30am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594000.3 | 509397.7 | 34621 | 1.64041666667 | 13040 |
| 013880 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:31am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1594001.7 | 509394.9 | 34623 | 1.64041666667 | 13880 |
| 013130 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:31am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1594002.5 | 509392.6 | 34624 | 1.64041666667 | 13130 |
| 013482 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:33am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1594002.9 | 509389.4 | 34627 | 1.64041666667 | 13482 |
| 015861 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:34am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1594003.9 | 509387.0 | 34629 | 1.64041666667 | 15861 |
| 015107 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:35am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1594003.7 | 509384.1 | 34631 | 1.64041666667 | 15107 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:35am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594004.5 | 509382.2 | 34632 | 1.64041666667 | 13766 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013851 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:37am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594004.2 | 509379.2 | 34635 | 1.64041666667 | 13851 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:37am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594004.8 | 509377.0 | 34636 | 1.64041666667 | 12853 |
| 014643 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:39am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594004.9 | 509374.2 | 34639 | 1.64041666667 | 14643 |
| 014790 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:39am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594005.8 | 509372.1 | 34640 | 1.64041666667 | 14790 |
| 014197 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:41am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594007.4 | 509369.2 | 34643 | 1.64041666667 | 14197 |
| 015069 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:42am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594007.2 | 509367.0 | 34645 | 1.64041666667 | 15069 |
| 015497 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:43am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594007.4 | 509364.9 | 34647 | 1.64041666667 | 15497 |
| 013654 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:44am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594007.1 | 509362.3 | 34649 | 1.64041666667 | 13654 |
| 013193 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:45am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1594007.9 | 509359.8 | 34651 | 1.64041666667 | 13193 |
| 014548 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:45am | Sensor | 1797-S0030-868-G-TJV | 6805.3 | 1594007.7 | 509357.9 | 34652 | 1.64041666667 | 14548 |
| 016027 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:47am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1594009.2 | 509356.1 | 34655 | 1.64041666667 | 16027 |
| 013396 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:48am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1594010.8 | 509355.2 | 34657 | 1.64041666667 | 13396 |
| 012889 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:49am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1594013.4 | 509355.6 | 34659 | 1.64041666667 | 12889 |
| 013302 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:49am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1594015.1 | 509356.6 | 34660 | 1.64041666667 | 13302 |
| 014995 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:51am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594016.6 | 509358.8 | 34663 | 1.64041666667 | 14995 |
| 014369 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:51am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594017.2 | 509360.3 | 34664 | 1.64041666667 | 14369 |
| 012862 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:53am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594017.4 | 509362.9 | 34667 | 1.64041666667 | 12862 |
| 014225 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:53am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594018.0 | 509364.9 | 34668 | 1.64041666667 | 14225 |
| 013486 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:55am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594017.7 | 509367.5 | 34671 | 1.64041666667 | 13486 |
| 013751 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:55am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594018.1 | 509369.7 | 34672 | 1.64041666667 | 13751 |
| 014868 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:57am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1594017.8 | 509372.0 | 34675 | 1.64041666667 | 14868 |
| 013707 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:58am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1594017.3 | 509374.7 | 34677 | 1.64041666667 | 13707 |
| 013596 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:59am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1594017.5 | 509377.7 | 34679 | 1.64041666667 | 13596 |
| 015039 | 0 | GeoXH 6000 | 08/18/2015 | 11:10:59am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1594017.1 | 509380.1 | 34680 | 1.64041666667 | 15039 |
| 015009 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:01am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1594016.9 | 509383.1 | 34683 | 1.64041666667 | 15009 |
| 014822 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:01am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594015.4 | 509384.7 | 34684 | 1.64041666667 | 14822 |
| 012615 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:03am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594014.6 | 509387.4 | 34687 | 1.64041666667 | 12615 |
| 013773 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:03am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594013.3 | 509390.2 | 34688 | 1.64041666667 | 13773 |
| 013373 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:05am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594012.3 | 509393.4 | 34691 | 1.64041666667 | 13373 |
| 013483 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:05am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594011.7 | 509395.9 | 34692 | 1.64041666667 | 13483 |
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:07am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594010.0 | 509398.3 | 34695 | 1.64041666667 | 12761 |
| 015820 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:08am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594009.2 | 509400.7 | 34697 | 1.64041666667 | 15820 |
| 014785 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:09am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594007.9 | 509403.3 | 34699 | 1.64041666667 | 14785 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:10am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594006.3 | 509406.0 | 34701 | 1.64041666667 | 14526 |
| 016141 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:11am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594005.1 | 509408.6 | 34703 | 1.64041666667 | 16141 |
| 013695 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:12am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594003.5 | 509410.3 | 34705 | 1.64041666667 | 13695 |
| 014763 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:13am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594002.7 | 509413.4 | 34707 | 1.64041666667 | 14763 |
| 013531 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:13am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594001.6 | 509415.3 | 34708 | 1.64041666667 | 13531 |
| 014332 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:15am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594000.9 | 509418.3 | 34711 | 1.64041666667 | 14332 |
| 014383 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:15am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594001.4 | 509420.7 | 34712 | 1.64041666667 | 14383 |
| 014966 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:17am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594003.0 | 509423.3 | 34715 | 1.64041666667 | 14966 |
| 012171 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:18am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594004.9 | 509423.5 | 34717 | 1.64041666667 | 12171 |
| 014862 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:19am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594006.7 | 509421.5 | 34719 | 1.64041666667 | 14862 |
| 014665 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:19am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594008.2 | 509420.1 | 34720 | 1.64041666667 | 14665 |
| 014916 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:21am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594009.8 | 509417.4 | 34723 | 1.64041666667 | 14916 |
| 013869 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:21am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594011.2 | 509415.9 | 34724 | 1.64041666667 | 13869 |
| 013667 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:23am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594012.1 | 509413.2 | 34727 | 1.64041666667 | 13667 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:23am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594013.4 | 509411.1 | 34728 | 1.64041666667 | 14516 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:25am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594014.8 | 509408.2 | 34731 | 1.64041666667 | 14819 |
| 015135 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:25am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594014.9 | 509405.9 | 34732 | 1.64041666667 | 15135 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:27am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594016.1 | 509403.4 | 34735 | 1.64041666667 | 14283 |
| 014190 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:27am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594016.4 | 509401.3 | 34736 | 1.64041666667 | 14190 |
| 013867 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:29am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594017.7 | 509398.6 | 34739 | 1.64041666667 | 13867 |
| 013907 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:30am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594018.0 | 509396.3 | 34741 | 1.64041666667 | 13907 |
| 015356 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:31am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594018.4 | 509393.7 | 34743 | 1.64041666667 | 15356 |
| 015059 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:31am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594018.8 | 509391.4 | 34744 | 1.64041666667 | 15059 |
| 013845 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:33am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594018.6 | 509388.0 | 34747 | 1.64041666667 | 13845 |
| 014171 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:33am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594019.1 | 509386.1 | 34748 | 1.64041666667 | 14171 |
| 014312 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:35am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594019.0 | 509383.0 | 34751 | 1.64041666667 | 14312 |
| 016298 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:36am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1594019.7 | 509380.7 | 34753 | 1.64041666667 | 16298 |
| 014694 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:37am | Sensor | 1797-S0030-868-G-TJV | 6802.7 | 1594020.8 | 509377.5 | 34755 | 1.64041666667 | 14694 |
| 014173 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:37am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1594021.3 | 509374.5 | 34756 | 1.64041666667 | 14173 |
| 014313 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:39am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594022.0 | 509371.4 | 34759 | 1.64041666667 | 14313 |
| 014528 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:39am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594021.9 | 509369.2 | 34760 | 1.64041666667 | 14528 |
| 015182 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:41am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594024.0 | 509366.8 | 34763 | 1.64041666667 | 15182 |
| 013875 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:41am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594025.2 | 509365.2 | 34764 | 1.64041666667 | 13875 |
| 012768 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:43am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594027.8 | 509364.7 | 34767 | 1.64041666667 | 12768 |
| 013602 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:44am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594029.7 | 509366.0 | 34769 | 1.64041666667 | 13602 |
| 014740 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:45am | Sensor | 1797-S0030-868-G-TJV | 6802.8 | 1594032.1 | 509368.3 | 34771 | 1.64041666667 | 14740 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:45am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1594032.3 | 509369.8 | 34772 | 1.64041666667 | 13915 |
| 014368 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:47am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594033.1 | 509372.3 | 34775 | 1.64041666667 | 14368 |
| 013822 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:48am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1594032.2 | 509372.9 | 34777 | 1.64041666667 | 13822 |
| 013115 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:49am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594030.0 | 509374.7 | 34779 | 1.64041666667 | 13115 |
| 016358 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:50am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594028.3 | 509375.1 | 34781 | 1.64041666667 | 16358 |
| 015429 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:51am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594026.1 | 509376.8 | 34783 | 1.64041666667 | 15429 |
| 015107 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:51am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594024.1 | 509377.7 | 34784 | 1.64041666667 | 15107 |
| 015806 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:52am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594022.0 | 509379.6 | 34786 | 1.64041666667 | 15806 |
| 015981 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:53am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594021.0 | 509382.1 | 34788 | 1.64041666667 | 15981 |
| 013475 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:55am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594018.7 | 509384.4 | 34791 | 1.64041666667 | 13475 |
| 013178 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:55am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594018.1 | 509386.3 | 34792 | 1.64041666667 | 13178 |
| 012564 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:57am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594017.2 | 509388.1 | 34795 | 1.64041666667 | 12564 |
| 012591 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:57am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594016.7 | 509389.1 | 34796 | 1.64041666667 | 12591 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 11:11:59am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594015.0 | 509389.0 | 34799 | 1.64041666667 | 14067 |
| 013297 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:00am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594013.3 | 509387.9 | 34801 | 1.64041666667 | 13297 |
| 014244 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:00am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1594010.9 | 509387.5 | 34802 | 1.64041666667 | 14244 |
| 014121 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:01am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1594008.6 | 509387.2 | 34804 | 1.64041666667 | 14121 |
| 017360 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:03am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1594005.5 | 509387.5 | 34807 | 1.64041666667 | 17360 |
| 015680 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:03am | Sensor | 1797-S0030-868-G-TJV | 6802.9 | 1594003.4 | 509388.4 | 34808 | 1.64041666667 | 15680 |
| 012980 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:05am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1594000.4 | 509389.6 | 34811 | 1.64041666667 | 12980 |
| 013655 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:05am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593999.1 | 509391.2 | 34812 | 1.64041666667 | 13655 |
| 013493 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:07am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593997.4 | 509393.3 | 34815 | 1.64041666667 | 13493 |
| 013273 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:07am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593997.0 | 509395.1 | 34816 | 1.64041666667 | 13273 |
| 012258 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:08am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593995.3 | 509394.8 | 34818 | 1.64041666667 | 12258 |
| 013984 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:10am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593992.5 | 509394.6 | 34821 | 1.64041666667 | 13984 |
| 014026 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:11am | Sensor | 1797-S0030-868-G-TJV | 6803.1 | 1593990.3 | 509393.1 | 34823 | 1.64041666667 | 14026 |
| 015866 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:11am | Sensor | 1797-S0030-868-G-TJV | 6803.0 | 1593988.1 | 509392.1 | 34824 | 1.64041666667 | 15866 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014826 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:12am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1593985.4 | 509391.5 | 34826 | 1.64041666667 | 14826 |
| 014386 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:13am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1593983.1 | 509390.4 | 34828 | 1.64041666667 | 14386 |
| 013046 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:15am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593979.2 | 509389.8 | 34831 | 1.64041666667 | 13046 |
| 013191 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:15am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1593977.1 | 509389.4 | 34832 | 1.64041666667 | 13191 |
| 015958 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:17am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1593974.5 | 509390.2 | 34835 | 1.64041666667 | 15958 |
| 014969 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:17am | Sensor | 1797-S0030-868-G-TJV | 6804.6 | 1593971.8 | 509389.9 | 34836 | 1.64041666667 | 14969 |
| 014992 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:19am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593969.0 | 509390.1 | 34839 | 1.64041666667 | 14992 |
| 015658 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:20am | Sensor | 1797-S0030-868-G-TJV | 6804.8 | 1593966.9 | 509391.0 | 34841 | 1.64041666667 | 15658 |
| 013964 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:20am | Sensor | 1797-S0030-868-G-TJV | 6805.0 | 1593965.2 | 509390.6 | 34842 | 1.64041666667 | 13964 |
| 013211 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:21am | Sensor | 1797-S0030-868-G-TJV | 6805.4 | 1593963.1 | 509389.9 | 34844 | 1.64041666667 | 13211 |
| 014252 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:22am | Sensor | 1797-S0030-868-G-TJV | 6805.6 | 1593962.3 | 509387.7 | 34846 | 1.64041666667 | 14252 |
| 013666 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:23am | Sensor | 1797-S0030-868-G-TJV | 6805.8 | 1593960.5 | 509386.1 | 34848 | 1.64041666667 | 13666 |
| 011203 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:24am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593959.3 | 509384.2 | 34850 | 1.64041666667 | 11203 |
| 012641 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:25am | Sensor | 1797-S0030-868-G-TJV | 6806.1 | 1593957.3 | 509382.2 | 34852 | 1.64041666667 | 12641 |
| 013870 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:27am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593954.6 | 509380.1 | 34855 | 1.64041666667 | 13870 |
| 013907 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:27am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593952.7 | 509379.0 | 34856 | 1.64041666667 | 13907 |
| 014576 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:29am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593949.9 | 509378.8 | 34859 | 1.64041666667 | 14576 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:29am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593948.1 | 509377.8 | 34860 | 1.64041666667 | 14324 |
| 014021 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:30am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593945.6 | 509378.1 | 34862 | 1.64041666667 | 14021 |
| 012985 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:31am | Sensor | 1797-S0030-868-G-TJV | 6807.5 | 1593943.5 | 509377.1 | 34864 | 1.64041666667 | 12985 |
| 014286 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:33am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593940.8 | 509376.8 | 34867 | 1.64041666667 | 14286 |
| 014221 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:33am | Sensor | 1797-S0030-868-G-TJV | 6808.0 | 1593939.2 | 509376.1 | 34868 | 1.64041666667 | 14221 |
| 013665 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:34am | Sensor | 1797-S0030-868-G-TJV | 6808.4 | 1593936.9 | 509374.4 | 34870 | 1.64041666667 | 13665 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:36am | Sensor | 1797-S0030-868-G-TJV | 6808.9 | 1593934.4 | 509373.7 | 34873 | 1.64041666667 | 13766 |
| 014001 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:37am | Sensor | 1797-S0030-868-G-TJV | 6808.8 | 1593932.9 | 509373.1 | 34875 | 1.64041666667 | 14001 |
| 015380 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:37am | Sensor | 1797-S0030-868-G-TJV | 6809.2 | 1593930.8 | 509373.0 | 34876 | 1.64041666667 | 15380 |
| 013775 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:39am | Sensor | 1797-S0030-868-G-TJV | 6809.8 | 1593929.0 | 509371.2 | 34879 | 1.64041666667 | 13775 |
| 015533 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:40am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593926.7 | 509370.0 | 34881 | 1.64041666667 | 15533 |
| 013993 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:41am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593925.0 | 509368.0 | 34883 | 1.64041666667 | 13993 |
| 014988 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:42am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593923.2 | 509366.8 | 34885 | 1.64041666667 | 14988 |
| 013197 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:43am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593920.0 | 509365.9 | 34887 | 1.64041666667 | 13197 |
| 013769 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:44am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593917.7 | 509365.4 | 34889 | 1.64041666667 | 13769 |
| 015232 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:45am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593915.1 | 509366.5 | 34891 | 1.64041666667 | 15232 |
| 014878 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:45am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593912.9 | 509367.1 | 34892 | 1.64041666667 | 14878 |
| 015419 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:47am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593910.8 | 509369.3 | 34895 | 1.64041666667 | 15419 |
| 015975 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:47am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593908.8 | 509371.2 | 34896 | 1.64041666667 | 15975 |
| 014763 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:49am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593906.7 | 509373.2 | 34899 | 1.64041666667 | 14763 |
| 014250 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:49am | Sensor | 1797-S0030-868-G-TJV | 6810.6 | 1593905.6 | 509375.4 | 34900 | 1.64041666667 | 14250 |
| 015412 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:50am | Sensor | 1797-S0030-868-G-TJV | 6810.7 | 1593904.0 | 509376.9 | 34902 | 1.64041666667 | 15412 |
| 014173 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:51am | Sensor | 1797-S0030-868-G-TJV | 6810.7 | 1593903.1 | 509378.6 | 34904 | 1.64041666667 | 14173 |
| 014163 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:53am | Sensor | 1797-S0030-868-G-TJV | 6810.7 | 1593902.7 | 509378.3 | 34907 | 1.64041666667 | 14163 |
| 014430 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:53am | Sensor | 1797-S0030-868-G-TJV | 6810.6 | 1593902.1 | 509376.5 | 34908 | 1.64041666667 | 14430 |
| 015727 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:55am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593904.0 | 509374.2 | 34911 | 1.64041666667 | 15727 |
| 014342 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:55am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593906.2 | 509373.5 | 34912 | 1.64041666667 | 14342 |
| 014505 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:56am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593909.5 | 509372.6 | 34914 | 1.64041666667 | 14505 |
| 016376 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:57am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593912.5 | 509371.9 | 34916 | 1.64041666667 | 16376 |
| 014594 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:59am | Sensor | 1797-S0030-868-G-TJV | 6810.6 | 1593916.0 | 509370.9 | 34919 | 1.64041666667 | 14594 |
| 015378 | 0 | GeoXH 6000 | 08/18/2015 | 11:12:59am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593918.6 | 509369.4 | 34920 | 1.64041666667 | 15378 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014584 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:01am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593921.8 | 509367.2 | 34923 | 1.64041666667 | 14584 |
| 014116 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:01am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593924.3 | 509366.2 | 34924 | 1.64041666667 | 14116 |
| 015649 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:02am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593927.5 | 509365.0 | 34926 | 1.64041666667 | 15649 |
| 014232 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:03am | Sensor | 1797-S0030-868-G-TJV | 6810.5 | 1593930.1 | 509363.8 | 34928 | 1.64041666667 | 14232 |
| 014628 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:04am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593933.2 | 509362.3 | 34930 | 1.64041666667 | 14628 |
| 015237 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:05am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593935.7 | 509360.1 | 34932 | 1.64041666667 | 15237 |
| 015149 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:06am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593937.9 | 509357.4 | 34934 | 1.64041666667 | 15149 |
| 015097 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:07am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593940.3 | 509355.2 | 34936 | 1.64041666667 | 15097 |
| 015234 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:09am | Sensor | 1797-S0030-868-G-TJV | 6810.2 | 1593943.5 | 509353.4 | 34939 | 1.64041666667 | 15234 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:09am | Sensor | 1797-S0030-868-G-TJV | 6810.1 | 1593945.5 | 509352.8 | 34940 | 1.64041666667 | 14458 |
| 013934 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:10am | Sensor | 1797-S0030-868-G-TJV | 6810.4 | 1593948.0 | 509353.2 | 34942 | 1.64041666667 | 13934 |
| 014853 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:11am | Sensor | 1797-S0030-868-G-TJV | 6810.3 | 1593949.7 | 509355.1 | 34944 | 1.64041666667 | 14853 |
| 013883 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:13am | Sensor | 1797-S0030-868-G-TJV | 6809.9 | 1593952.6 | 509356.7 | 34947 | 1.64041666667 | 13883 |
| 013670 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:13am | Sensor | 1797-S0030-868-G-TJV | 6809.1 | 1593954.2 | 509358.2 | 34948 | 1.64041666667 | 13670 |
| 017727 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:14am | Sensor | 1797-S0030-868-G-TJV | 6808.6 | 1593956.1 | 509360.5 | 34950 | 1.64041666667 | 17727 |
| 015832 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:15am | Sensor | 1797-S0030-868-G-TJV | 6808.2 | 1593958.6 | 509362.4 | 34952 | 1.64041666667 | 15832 |
| 015568 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:17am | Sensor | 1797-S0030-868-G-TJV | 6807.8 | 1593960.2 | 509364.9 | 34955 | 1.64041666667 | 15568 |
| 016012 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:18am | Sensor | 1797-S0030-868-G-TJV | 6807.6 | 1593962.5 | 509366.0 | 34957 | 1.64041666667 | 16012 |
| 016453 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:19am | Sensor | 1797-S0030-868-G-TJV | 6807.3 | 1593964.6 | 509367.6 | 34959 | 1.64041666667 | 16453 |
| 017823 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:19am | Sensor | 1797-S0030-868-G-TJV | 6807.1 | 1593966.7 | 509367.9 | 34960 | 1.64041666667 | 17823 |
| 017475 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:21am | Sensor | 1797-S0030-868-G-TJV | 6806.8 | 1593969.6 | 509369.2 | 34963 | 1.64041666667 | 17475 |
| 015648 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:21am | Sensor | 1797-S0030-868-G-TJV | 6806.4 | 1593972.0 | 509370.7 | 34964 | 1.64041666667 | 15648 |
| 015522 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:23am | Sensor | 1797-S0030-868-G-TJV | 6806.5 | 1593974.9 | 509371.0 | 34967 | 1.64041666667 | 15522 |
| 017500 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:23am | Sensor | 1797-S0030-868-G-TJV | 6806.3 | 1593976.7 | 509371.9 | 34968 | 1.64041666667 | 17500 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:25am | Sensor | 1797-S0030-868-G-TJV | 6806.2 | 1593979.6 | 509372.3 | 34971 | 1.64041666667 | 13915 |
| 014998 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:25am | Sensor | 1797-S0030-868-G-TJV | 6806.0 | 1593981.7 | 509373.4 | 34972 | 1.64041666667 | 14998 |
| 013739 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:27am | Sensor | 1797-S0030-868-G-TJV | 6805.7 | 1593984.7 | 509374.3 | 34975 | 1.64041666667 | 13739 |
| 012885 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:27am | Sensor | 1797-S0030-868-G-TJV | 6805.2 | 1593987.0 | 509375.3 | 34976 | 1.64041666667 | 12885 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:28am | Sensor | 1797-S0030-868-G-TJV | 6804.9 | 1593989.2 | 509376.9 | 34978 | 1.64041666667 | 13301 |
| 013255 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:29am | Sensor | 1797-S0030-868-G-TJV | 6804.7 | 1593991.8 | 509377.7 | 34980 | 1.64041666667 | 13255 |
| 015583 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:31am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1593993.9 | 509379.7 | 34983 | 1.64041666667 | 15583 |
| 014636 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:31am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1593995.6 | 509380.7 | 34984 | 1.64041666667 | 14636 |
| 014999 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:33am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1593997.3 | 509382.4 | 34987 | 1.64041666667 | 14999 |
| 013649 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:33am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1593999.6 | 509384.0 | 34988 | 1.64041666667 | 13649 |
| 013072 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:34am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594002.0 | 509386.0 | 34990 | 1.64041666667 | 13072 |
| 014908 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:35am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594004.2 | 509387.9 | 34992 | 1.64041666667 | 14908 |
| 014407 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:36am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594007.2 | 509389.1 | 34994 | 1.64041666667 | 14407 |
| 014131 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:37am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594008.8 | 509390.9 | 34996 | 1.64041666667 | 14131 |
| 012472 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:38am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594011.1 | 509392.1 | 34998 | 1.64041666667 | 12472 |
| 015538 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:39am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594013.0 | 509393.7 | 35000 | 1.64041666667 | 15538 |
| 014294 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:40am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594015.7 | 509395.2 | 35002 | 1.64041666667 | 14294 |
| 013413 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:41am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594017.9 | 509397.0 | 35004 | 1.64041666667 | 13413 |
| 013703 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:42am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594019.3 | 509399.3 | 35006 | 1.64041666667 | 13703 |
| 013325 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:43am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594021.4 | 509401.0 | 35008 | 1.64041666667 | 13325 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:44am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594023.4 | 509403.4 | 35010 | 1.64041666667 | 13471 |
| 013357 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:45am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594025.4 | 509404.7 | 35012 | 1.64041666667 | 13357 |
| 012189 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:46am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594028.0 | 509406.7 | 35014 | 1.64041666667 | 12189 |
| 014297 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:47am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594029.2 | 509409.1 | 35016 | 1.64041666667 | 14297 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014524 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:48am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594031.0 | 509411.2 | 35018 | 1.64041666667 | 14524 |
| 012601 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:49am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594032.0 | 509413.8 | 35020 | 1.64041666667 | 12601 |
| 012660 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:50am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594033.3 | 509416.5 | 35022 | 1.64041666667 | 12660 |
| 013485 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:51am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594034.9 | 509418.5 | 35024 | 1.64041666667 | 13485 |
| 013451 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:52am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594036.8 | 509421.1 | 35026 | 1.64041666667 | 13451 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:53am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594038.5 | 509423.2 | 35028 | 1.64041666667 | 14283 |
| 014430 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:54am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594039.4 | 509426.1 | 35030 | 1.64041666667 | 14430 |
| 013687 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:55am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594040.5 | 509428.9 | 35032 | 1.64041666667 | 13687 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:56am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594042.2 | 509432.0 | 35034 | 1.64041666667 | 13742 |
| 014911 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:57am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594043.1 | 509434.7 | 35036 | 1.64041666667 | 14911 |
| 013983 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:58am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594044.7 | 509437.3 | 35038 | 1.64041666667 | 13983 |
| 013186 | 0 | GeoXH 6000 | 08/18/2015 | 11:13:59am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594045.5 | 509440.1 | 35040 | 1.64041666667 | 13186 |
| 012416 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:00am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594045.9 | 509443.9 | 35042 | 1.64041666667 | 12416 |
| 012644 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:01am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594046.9 | 509446.4 | 35044 | 1.64041666667 | 12644 |
| 012671 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:02am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594047.9 | 509449.6 | 35046 | 1.64041666667 | 12671 |
| 012707 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:03am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594049.2 | 509452.7 | 35048 | 1.64041666667 | 12707 |
| 015326 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:04am | Sensor | 1797-S0030-868-G-TJV | 6804.5 | 1594051.0 | 509455.5 | 35050 | 1.64041666667 | 15326 |
| 015681 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:05am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594051.7 | 509458.1 | 35052 | 1.64041666667 | 15681 |
| 014030 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:06am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594053.1 | 509460.7 | 35054 | 1.64041666667 | 14030 |
| 014637 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:07am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594054.8 | 509463.4 | 35056 | 1.64041666667 | 14637 |
| 013349 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:08am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594056.6 | 509466.3 | 35058 | 1.64041666667 | 13349 |
| 012727 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:09am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594058.7 | 509468.5 | 35060 | 1.64041666667 | 12727 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:10am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594060.4 | 509471.4 | 35062 | 1.64041666667 | 13471 |
| 013657 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:11am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594062.2 | 509473.9 | 35064 | 1.64041666667 | 13657 |
| 015054 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:12am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594064.8 | 509476.3 | 35066 | 1.64041666667 | 15054 |
| 014353 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:13am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594067.1 | 509479.0 | 35068 | 1.64041666667 | 14353 |
| 012348 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:14am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594068.9 | 509481.9 | 35070 | 1.64041666667 | 12348 |
| 014127 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:15am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594071.1 | 509484.2 | 35072 | 1.64041666667 | 14127 |
| 012471 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:16am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594073.7 | 509486.5 | 35074 | 1.64041666667 | 12471 |
| 012148 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:17am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594076.0 | 509488.7 | 35076 | 1.64041666667 | 12148 |
| 012577 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:19am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594078.5 | 509491.3 | 35079 | 1.64041666667 | 12577 |
| 011634 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:19am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594080.2 | 509493.4 | 35080 | 1.64041666667 | 11634 |
| 013498 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:21am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594082.3 | 509496.8 | 35083 | 1.64041666667 | 13498 |
| 012194 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:21am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594084.3 | 509499.7 | 35084 | 1.64041666667 | 12194 |
| 013638 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:23am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594087.0 | 509502.2 | 35087 | 1.64041666667 | 13638 |
| 014149 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:23am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594089.4 | 509504.9 | 35088 | 1.64041666667 | 14149 |
| 012687 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:25am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594091.6 | 509508.0 | 35091 | 1.64041666667 | 12687 |
| 011632 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:25am | Sensor | 1797-S0030-868-G-TJV | 6803.2 | 1594093.5 | 509510.1 | 35092 | 1.64041666667 | 11632 |
| 012148 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:26am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594096.0 | 509512.3 | 35094 | 1.64041666667 | 12148 |
| 013237 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:27am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594099.1 | 509514.0 | 35096 | 1.64041666667 | 13237 |
| 014199 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:28am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594102.3 | 509515.8 | 35098 | 1.64041666667 | 14199 |
| 012129 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:29am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594104.6 | 509517.6 | 35100 | 1.64041666667 | 12129 |
| 012272 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:30am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594107.2 | 509520.2 | 35102 | 1.64041666667 | 12272 |
| 012368 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:31am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594108.9 | 509522.6 | 35104 | 1.64041666667 | 12368 |
| 013352 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:32am | Sensor | 1797-S0030-868-G-TJV | 6803.4 | 1594109.9 | 509526.4 | 35106 | 1.64041666667 | 13352 |
| 014588 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:33am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594110.6 | 509529.5 | 35108 | 1.64041666667 | 14588 |
| 014297 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:34am | Sensor | 1797-S0030-868-G-TJV | 6803.3 | 1594111.9 | 509533.5 | 35110 | 1.64041666667 | 14297 |
| 012904 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:35am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594113.0 | 509536.0 | 35112 | 1.64041666667 | 12904 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013696 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:36am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594114.7 | 509539.1 | 35114 | 1.64041666667 | 13696 |
| 013294 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:37am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594116.5 | 509541.9 | 35116 | 1.64041666667 | 13294 |
| 013673 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:38am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594118.5 | 509544.5 | 35118 | 1.64041666667 | 13673 |
| 016258 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:39am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594120.8 | 509547.1 | 35120 | 1.64041666667 | 16258 |
| 016964 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:41am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594123.2 | 509549.9 | 35123 | 1.64041666667 | 16964 |
| 017531 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:41am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594124.9 | 509551.4 | 35124 | 1.64041666667 | 17531 |
| 018542 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:42am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594127.5 | 509554.5 | 35126 | 1.64041666667 | 18542 |
| 020205 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:43am | Sensor | 1797-S0030-868-G-TJV | 6803.5 | 1594129.0 | 509557.3 | 35128 | 1.64041666667 | 20205 |
| 019331 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:45am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594131.2 | 509560.3 | 35131 | 1.64041666667 | 19331 |
| 020583 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:45am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594133.1 | 509562.2 | 35132 | 1.64041666667 | 20583 |
| 019905 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:46am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594135.8 | 509563.9 | 35134 | 1.64041666667 | 19905 |
| 019196 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:47am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594138.9 | 509564.2 | 35136 | 1.64041666667 | 19196 |
| 017909 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:48am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594141.9 | 509563.3 | 35138 | 1.64041666667 | 17909 |
| 021157 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:49am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594144.2 | 509562.9 | 35140 | 1.64041666667 | 21157 |
| 021699 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:50am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594147.6 | 509562.0 | 35142 | 1.64041666667 | 21699 |
| 020784 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:51am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594150.5 | 509561.9 | 35144 | 1.64041666667 | 20784 |
| 022956 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:52am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594153.4 | 509562.9 | 35146 | 1.64041666667 | 22956 |
| 020229 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:53am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594156.0 | 509564.4 | 35148 | 1.64041666667 | 20229 |
| 020567 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:54am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.1 | 509565.7 | 35150 | 1.64041666667 | 20567 |
| 019901 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:55am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.1 | 509565.6 | 35152 | 1.64041666667 | 19901 |
| 021325 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:56am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.6 | 35154 | 1.64041666667 | 21325 |
| 020001 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:57am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.5 | 35156 | 1.64041666667 | 20001 |
| 019730 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:58am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.5 | 35158 | 1.64041666667 | 19730 |
| 019482 | 0 | GeoXH 6000 | 08/18/2015 | 11:14:59am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594157.9 | 509565.5 | 35160 | 1.64041666667 | 19482 |
| 021160 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:00am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.6 | 35162 | 1.64041666667 | 21160 |
| 022090 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:01am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.5 | 35164 | 1.64041666667 | 22090 |
| 021992 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:02am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.6 | 35166 | 1.64041666667 | 21992 |
| 020198 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:03am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.6 | 35168 | 1.64041666667 | 20198 |
| 020709 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:04am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.6 | 35170 | 1.64041666667 | 20709 |
| 021587 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:05am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.6 | 35172 | 1.64041666667 | 21587 |
| 020486 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:07am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.6 | 35175 | 1.64041666667 | 20486 |
| 021861 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:07am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.0 | 509565.5 | 35176 | 1.64041666667 | 21861 |
| 021035 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:09am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.6 | 35179 | 1.64041666667 | 21035 |
| 021278 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:09am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.6 | 35180 | 1.64041666667 | 21278 |
| 022389 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:11am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.6 | 35183 | 1.64041666667 | 22389 |
| 021437 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:11am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.5 | 35184 | 1.64041666667 | 21437 |
| 021019 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:12am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.5 | 35186 | 1.64041666667 | 21019 |
| 020794 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:13am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.5 | 35188 | 1.64041666667 | 20794 |
| 022958 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:15am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.0 | 509565.5 | 35191 | 1.64041666667 | 22958 |
| 021489 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:15am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.4 | 35192 | 1.64041666667 | 21489 |
| 018782 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:16am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594157.9 | 509565.5 | 35194 | 1.64041666667 | 18782 |
| 019695 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:17am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.3 | 509565.6 | 35196 | 1.64041666667 | 19695 |
| 019983 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:19am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.4 | 509565.6 | 35199 | 1.64041666667 | 19983 |
| 022456 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:19am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.3 | 509565.6 | 35200 | 1.64041666667 | 22456 |
| 021994 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:20am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.2 | 509565.6 | 35202 | 1.64041666667 | 21994 |
| 021638 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:21am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.2 | 509565.5 | 35204 | 1.64041666667 | 21638 |
| 021549 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:22am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.3 | 509565.5 | 35206 | 1.64041666667 | 21549 |
| 021467 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:23am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.3 | 509565.5 | 35208 | 1.64041666667 | 21467 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 022796 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:24am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.4 | 509565.6 | 35210 | 1.64041666667 | 22796 |
| 021329 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:25am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.4 | 509565.9 | 35212 | 1.64041666667 | 21329 |
| 021862 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:26am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.2 | 509566.2 | 35214 | 1.64041666667 | 21862 |
| 020975 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:27am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.1 | 509566.2 | 35216 | 1.64041666667 | 20975 |
| 019583 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:28am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.2 | 509566.0 | 35218 | 1.64041666667 | 19583 |
| 019506 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:29am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.1 | 509565.9 | 35220 | 1.64041666667 | 19506 |
| 020446 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:30am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.1 | 509565.8 | 35222 | 1.64041666667 | 20446 |
| 021041 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:31am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.1 | 509565.8 | 35224 | 1.64041666667 | 21041 |
| 020200 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:33am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.1 | 509565.8 | 35227 | 1.64041666667 | 20200 |
| 021790 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:33am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.1 | 509565.8 | 35228 | 1.64041666667 | 21790 |
| 021857 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:35am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.1 | 509565.8 | 35231 | 1.64041666667 | 21857 |
| 022984 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:35am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.2 | 509565.7 | 35232 | 1.64041666667 | 22984 |
| 023356 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:36am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.2 | 509565.7 | 35234 | 1.64041666667 | 23356 |
| 021559 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:37am | Sensor | 1797-S0030-868-G-TJV | 6804.1 | 1594158.2 | 509565.7 | 35236 | 1.64041666667 | 21559 |
| 020719 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:38am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.2 | 509565.8 | 35238 | 1.64041666667 | 20719 |
| 020840 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:39am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.2 | 509565.8 | 35240 | 1.64041666667 | 20840 |
| 020000 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:41am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.4 | 509565.6 | 35243 | 1.64041666667 | 20000 |
| 019190 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:41am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.3 | 509565.7 | 35244 | 1.64041666667 | 19190 |
| 019797 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:43am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.4 | 509565.8 | 35247 | 1.64041666667 | 19797 |
| 021239 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:43am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.4 | 509565.8 | 35248 | 1.64041666667 | 21239 |
| 020580 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:45am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.3 | 509565.8 | 35251 | 1.64041666667 | 20580 |
| 019965 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:45am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594158.3 | 509565.8 | 35252 | 1.64041666667 | 19965 |
| 021281 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:46am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594158.3 | 509566.0 | 35254 | 1.64041666667 | 21281 |
| 022690 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:47am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594158.1 | 509566.4 | 35256 | 1.64041666667 | 22690 |
| 022202 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:48am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594159.3 | 509567.5 | 35258 | 1.64041666667 | 22202 |
| 021420 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:49am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594161.1 | 509568.5 | 35260 | 1.64041666667 | 21420 |
| 020655 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:50am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594161.0 | 509567.4 | 35262 | 1.64041666667 | 20655 |
| 021723 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:51am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594159.8 | 509565.4 | 35264 | 1.64041666667 | 21723 |
| 019261 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:52am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594157.9 | 509562.7 | 35266 | 1.64041666667 | 19261 |
| 021045 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:53am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594155.3 | 509560.9 | 35268 | 1.64041666667 | 21045 |
| 021041 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:54am | Sensor | 1797-S0030-868-G-TJV | 6804.3 | 1594152.5 | 509559.1 | 35270 | 1.64041666667 | 21041 |
| 021130 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:55am | Sensor | 1797-S0030-868-G-TJV | 6804.4 | 1594150.3 | 509557.9 | 35272 | 1.64041666667 | 21130 |
| 022262 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:56am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594147.2 | 509557.5 | 35274 | 1.64041666667 | 22262 |
| 020835 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:57am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594144.8 | 509557.4 | 35276 | 1.64041666667 | 20835 |
| 021468 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:58am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594142.0 | 509557.4 | 35278 | 1.64041666667 | 21468 |
| 020967 | 0 | GeoXH 6000 | 08/18/2015 | 11:15:59am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594140.6 | 509558.3 | 35280 | 1.64041666667 | 20967 |
| 020122 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:00am | Sensor | 1797-S0030-868-G-TJV | 6804.2 | 1594139.5 | 509558.7 | 35282 | 1.64041666667 | 20122 |
| 020720 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:01am | Sensor | 1797-S0030-868-G-TJV | 6802.6 | 1594138.2 | 509558.7 | 35284 | 1.64041666667 | 20720 |
| 020030 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:02am | Sensor | 1797-S0030-868-G-TJV | 6801.2 | 1594136.3 | 509560.7 | 35286 | 1.64041666667 | 20030 |
| 022257 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:03am | Sensor | 1797-S0030-868-G-TJV | 6802.5 | 1594133.0 | 509559.5 | 35288 | 1.64041666667 | 22257 |
| 022004 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:04am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594131.5 | 509557.4 | 35290 | 1.64041666667 | 22004 |
| 020171 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:05am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.6 | 509556.2 | 35292 | 1.64041666667 | 20171 |
| 019382 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:06am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.3 | 509555.6 | 35294 | 1.64041666667 | 19382 |
| 021615 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:07am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.2 | 509555.4 | 35296 | 1.64041666667 | 21615 |
| 019713 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:08am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594131.2 | 509555.6 | 35298 | 1.64041666667 | 19713 |
| 019448 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:09am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.2 | 509555.7 | 35300 | 1.64041666667 | 19448 |
| 019772 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:11am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.2 | 509555.7 | 35303 | 1.64041666667 | 19772 |
| 019433 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:11am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.2 | 509555.7 | 35304 | 1.64041666667 | 19433 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 020668 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:12am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.2 | 509555.6 | 35306 | 1.64041666667 | 20668 |
| 019717 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:13am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.3 | 509555.8 | 35308 | 1.64041666667 | 19717 |
| 019689 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:14am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594132.3 | 509556.0 | 35310 | 1.64041666667 | 19689 |
| 019532 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:15am | Sensor | 1797-S0030-868-G-TJV | 6803.7 | 1594131.6 | 509556.6 | 35312 | 1.64041666667 | 19532 |
| 021053 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:16am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594131.5 | 509556.8 | 35314 | 1.64041666667 | 21053 |
| 020473 | 0 | GeoXH 6000 | 08/18/2015 | 11:16:17am | Sensor | 1797-S0030-868-G-TJV | 6803.6 | 1594131.5 | 509556.9 | 35316 | 1.64041666667 | 20473 |
| 015512 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:14am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35327 | 1.64041666667 | 15512 |
| 018758 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:15am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1593999.9 | 509484.3 | 35329 | 1.64041666667 | 18758 |
| 017019 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:16am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35331 | 1.64041666667 | 17019 |
| 016855 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:17am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35333 | 1.64041666667 | 16855 |
| 017503 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:18am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35335 | 1.64041666667 | 17503 |
| 015866 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:19am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35337 | 1.64041666667 | 15866 |
| 017616 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:20am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35339 | 1.64041666667 | 17616 |
| 018144 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:21am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35341 | 1.64041666667 | 18144 |
| 018576 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:22am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35343 | 1.64041666667 | 18576 |
| 017274 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:23am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35345 | 1.64041666667 | 17274 |
| 015808 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:24am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.8 | 509484.3 | 35346 | 1.64041666667 | 15808 |
| 016042 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:25am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.8 | 509484.3 | 35347 | 1.64041666667 | 16042 |
| 017840 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:26am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.8 | 509484.3 | 35348 | 1.64041666667 | 17840 |
| 017210 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:27am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.8 | 509484.3 | 35349 | 1.64041666667 | 17210 |
| 016422 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:28am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593999.8 | 509484.3 | 35350 | 1.64041666667 | 16422 |
| 016975 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:29am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593999.8 | 509484.3 | 35351 | 1.64041666667 | 16975 |
| 016034 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:30am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593999.8 | 509484.3 | 35352 | 1.64041666667 | 16034 |
| 017988 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:31am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593999.9 | 509484.2 | 35353 | 1.64041666667 | 17988 |
| 016437 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:32am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.0 | 509484.0 | 35354 | 1.64041666667 | 16437 |
| 017159 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:33am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.1 | 509483.9 | 35355 | 1.64041666667 | 17159 |
| 017250 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:34am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.2 | 509483.9 | 35356 | 1.64041666667 | 17250 |
| 017632 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:35am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.2 | 509483.9 | 35357 | 1.64041666667 | 17632 |
| 017278 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:36am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.2 | 509484.0 | 35358 | 1.64041666667 | 17278 |
| 017609 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:37am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.2 | 509483.9 | 35359 | 1.64041666667 | 17609 |
| 017572 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:38am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.2 | 509483.9 | 35360 | 1.64041666667 | 17572 |
| 016873 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:39am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.2 | 509484.0 | 35361 | 1.64041666667 | 16873 |
| 017118 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:40am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.2 | 509484.0 | 35362 | 1.64041666667 | 17118 |
| 017299 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:41am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594000.2 | 509484.0 | 35363 | 1.64041666667 | 17299 |
| 016744 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:42am | Sensor | 1797-S0030-868-G-TJV | 6803.8 | 1594000.2 | 509483.8 | 35364 | 1.64041666667 | 16744 |
| 016246 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:43am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.1 | 509484.0 | 35365 | 1.64041666667 | 16246 |
| 016631 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:44am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.3 | 35366 | 1.64041666667 | 16631 |
| 017418 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:45am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35367 | 1.64041666667 | 17418 |
| 015634 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:46am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35368 | 1.64041666667 | 15634 |
| 017528 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:47am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35369 | 1.64041666667 | 17528 |
| 019562 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:48am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35370 | 1.64041666667 | 19562 |
| 018060 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:49am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.2 | 35371 | 1.64041666667 | 18060 |
| 018945 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:50am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1593999.9 | 509484.2 | 35372 | 1.64041666667 | 18945 |
| 019166 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:51am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35373 | 1.64041666667 | 19166 |
| 016581 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:52am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35374 | 1.64041666667 | 16581 |
| 016415 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:53am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35375 | 1.64041666667 | 16415 |
| 016643 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:54am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35376 | 1.64041666667 | 16643 |
| 018207 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:57am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.2 | 35377 | 1.64041666667 | 18207 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016702 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:58am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.0 | 509484.1 | 35379 | 1.64041666667 | 16702 |
| 016175 | 0 | GeoXH 6000 | 08/18/2015 | 11:34:59am | Sensor | 1797-S0030-868-G-TJV | 6803.9 | 1594000.1 | 509484.1 | 35381 | 1.64041666667 | 16175 |
| 017573 | 0 | GeoXH 6000 | 08/18/2015 | 11:35:00am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.1 | 509484.1 | 35383 | 1.64041666667 | 17573 |
| 017863 | 0 | GeoXH 6000 | 08/18/2015 | 11:35:01am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.1 | 509484.2 | 35385 | 1.64041666667 | 17863 |
| 017246 | 0 | GeoXH 6000 | 08/18/2015 | 11:35:02am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.1 | 509484.2 | 35387 | 1.64041666667 | 17246 |
| 016431 | 0 | GeoXH 6000 | 08/18/2015 | 11:35:03am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1594000.1 | 509484.2 | 35389 | 1.64041666667 | 16431 |
| 017037 | 0 | GeoXH 6000 | 08/18/2015 | 11:35:04am | Sensor | 1797-S0030-868-G-TJV | 6804.0 | 1593999.7 | 509483.0 | 35391 | 1.64041666667 | 17037 |
| 021670 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:28am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593940.2 | 509313.8 | 35392 | 1.64041666667 | 21670 |
| 023627 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:29am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593939.9 | 509313.4 | 35394 | 1.64041666667 | 23627 |
| 022436 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:30am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593939.9 | 509313.8 | 35396 | 1.64041666667 | 22436 |
| 021479 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:31am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593939.9 | 509313.7 | 35398 | 1.64041666667 | 21479 |
| 020820 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:32am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593939.9 | 509313.6 | 35400 | 1.64041666667 | 20820 |
| 021285 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:33am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593939.9 | 509313.6 | 35402 | 1.64041666667 | 21285 |
| 019961 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:34am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593940.0 | 509313.6 | 35404 | 1.64041666667 | 19961 |
| 020530 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:35am | Sensor | 1797-S0030-868-G-TJV | 6809.6 | 1593940.0 | 509313.6 | 35405 | 1.64041666667 | 20530 |
| 023522 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:36am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593940.0 | 509313.6 | 35406 | 1.64041666667 | 23522 |
| 022200 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:37am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593940.0 | 509313.6 | 35407 | 1.64041666667 | 22200 |
| 021000 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:38am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593939.9 | 509313.6 | 35408 | 1.64041666667 | 21000 |
| 019950 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:39am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593939.9 | 509313.6 | 35409 | 1.64041666667 | 19950 |
| 019477 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:40am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593939.9 | 509313.6 | 35410 | 1.64041666667 | 19477 |
| 022959 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:41am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593939.9 | 509313.6 | 35411 | 1.64041666667 | 22959 |
| 019960 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:42am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593940.1 | 509313.5 | 35412 | 1.64041666667 | 19960 |
| 019150 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:43am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593940.1 | 509313.3 | 35413 | 1.64041666667 | 19150 |
| 019427 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:44am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593939.9 | 509313.2 | 35414 | 1.64041666667 | 19427 |
| 018596 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:45am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593939.9 | 509313.2 | 35415 | 1.64041666667 | 18596 |
| 021479 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:46am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593939.8 | 509313.2 | 35416 | 1.64041666667 | 21479 |
| 019260 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:47am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593939.9 | 509313.2 | 35417 | 1.64041666667 | 19260 |
| 018405 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:48am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593939.9 | 509313.2 | 35418 | 1.64041666667 | 18405 |
| 020201 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:49am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593939.9 | 509313.2 | 35419 | 1.64041666667 | 20201 |
| 019810 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:50am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593940.0 | 509313.6 | 35420 | 1.64041666667 | 19810 |
| 020792 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:51am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593940.1 | 509313.9 | 35421 | 1.64041666667 | 20792 |
| 020498 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:52am | Sensor | 1797-S0030-868-G-TJV | 6809.5 | 1593940.1 | 509313.9 | 35422 | 1.64041666667 | 20498 |
| 019644 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:53am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593940.1 | 509313.9 | 35423 | 1.64041666667 | 19644 |
| 020691 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:54am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593940.1 | 509313.9 | 35424 | 1.64041666667 | 20691 |
| 022242 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:55am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593940.1 | 509313.9 | 35425 | 1.64041666667 | 22242 |
| 020530 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:56am | Sensor | 1797-S0030-868-G-TJV | 6809.4 | 1593940.1 | 509313.9 | 35426 | 1.64041666667 | 20530 |
| 019652 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:57am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.1 | 509313.9 | 35427 | 1.64041666667 | 19652 |
| 020183 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:58am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.1 | 509313.9 | 35428 | 1.64041666667 | 20183 |
| 018665 | 0 | GeoXH 6000 | 08/18/2015 | 11:36:59am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.2 | 509313.9 | 35429 | 1.64041666667 | 18665 |
| 021586 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:00am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.1 | 509313.9 | 35430 | 1.64041666667 | 21586 |
| 022226 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:01am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.1 | 509313.9 | 35431 | 1.64041666667 | 22226 |
| 020376 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:02am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.2 | 509313.9 | 35432 | 1.64041666667 | 20376 |
| 021654 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:03am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.2 | 509313.9 | 35433 | 1.64041666667 | 21654 |
| 022473 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:05am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.1 | 509313.9 | 35434 | 1.64041666667 | 22473 |
| 022298 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:06am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.1 | 509314.0 | 35436 | 1.64041666667 | 22298 |
| 020604 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:07am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.1 | 509314.0 | 35438 | 1.64041666667 | 20604 |
| 019221 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:08am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.2 | 509314.0 | 35440 | 1.64041666667 | 19221 |
| 020165 | 0 | GeoXH 6000 | 08/18/2015 | 11:37:09am | Sensor | 1797-S0030-868-G-TJV | 6809.3 | 1593940.2 | 509314.0 | 35442 | 1.64041666667 | 20165 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012439 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:34pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593438.1 | 511017.9 | 27381 | 1.64041666667 | 12439 |
| 012427 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:35pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593438.2 | 511018.0 | 27383 | 1.64041666667 | 12427 |
| 012390 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:36pm | Sensor | 1797-S0028-636-G-DTE | 6810.5 | 1593438.1 | 511017.9 | 27385 | 1.64041666667 | 12390 |
| 012279 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:37pm | Sensor | 1797-S0028-636-G-DTE | 6810.5 | 1593438.1 | 511017.9 | 27387 | 1.64041666667 | 12279 |
| 012202 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:38pm | Sensor | 1797-S0028-636-G-DTE | 6810.5 | 1593438.1 | 511017.9 | 27389 | 1.64041666667 | 12202 |
| 012323 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:39pm | Sensor | 1797-S0028-636-G-DTE | 6810.5 | 1593438.0 | 511017.9 | 27391 | 1.64041666667 | 12323 |
| 012204 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:40pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593438.0 | 511018.0 | 27393 | 1.64041666667 | 12204 |
| 012505 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:41pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593438.0 | 511018.0 | 27395 | 1.64041666667 | 12505 |
| 013386 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:42pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593438.1 | 511017.9 | 27397 | 1.64041666667 | 13386 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:43pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593438.2 | 511018.0 | 27399 | 1.64041666667 | 13560 |
| 012457 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:44pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593438.2 | 511018.3 | 27401 | 1.64041666667 | 12457 |
| 012354 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:45pm | Sensor | 1797-S0028-636-G-DTE | 6810.5 | 1593438.3 | 511018.3 | 27403 | 1.64041666667 | 12354 |
| 011832 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:46pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593439.4 | 511017.9 | 27405 | 1.64041666667 | 11832 |
| 012783 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:47pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593439.8 | 511017.2 | 27407 | 1.64041666667 | 12783 |
| 012073 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:48pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593439.8 | 511017.0 | 27409 | 1.64041666667 | 12073 |
| 011921 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:49pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593440.0 | 511017.3 | 27411 | 1.64041666667 | 11921 |
| 012180 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:50pm | Sensor | 1797-S0028-636-G-DTE | 6810.5 | 1593441.2 | 511019.1 | 27413 | 1.64041666667 | 12180 |
| 013294 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:51pm | Sensor | 1797-S0028-636-G-DTE | 6810.8 | 1593443.4 | 511020.4 | 27415 | 1.64041666667 | 13294 |
| 013162 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:52pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593447.4 | 511022.2 | 27417 | 1.64041666667 | 13162 |
| 012646 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:53pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593450.2 | 511024.7 | 27419 | 1.64041666667 | 12646 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:54pm | Sensor | 1797-S0028-636-G-DTE | 6810.5 | 1593452.2 | 511027.3 | 27421 | 1.64041666667 | 12236 |
| 013640 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:55pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593453.6 | 511028.9 | 27423 | 1.64041666667 | 13640 |
| 013222 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:56pm | Sensor | 1797-S0028-636-G-DTE | 6810.5 | 1593453.7 | 511030.0 | 27425 | 1.64041666667 | 13222 |
| 012402 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:57pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593452.2 | 511029.2 | 27427 | 1.64041666667 | 12402 |
| 012616 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:58pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593448.7 | 511027.0 | 27429 | 1.64041666667 | 12616 |
| 012346 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:59pm | Sensor | 1797-S0028-636-G-DTE | 6810.3 | 1593445.0 | 511025.3 | 27431 | 1.64041666667 | 12346 |
| 013012 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:00pm | Sensor | 1797-S0028-636-G-DTE | 6810.7 | 1593441.2 | 511024.1 | 27433 | 1.64041666667 | 13012 |
| 012554 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:01pm | Sensor | 1797-S0028-636-G-DTE | 6810.4 | 1593439.0 | 511022.6 | 27435 | 1.64041666667 | 12554 |
| 012597 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:02pm | Sensor | 1797-S0028-636-G-DTE | 6810.2 | 1593435.4 | 511019.6 | 27437 | 1.64041666667 | 12597 |
| 011915 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:03pm | Sensor | 1797-S0028-636-G-DTE | 6810.1 | 1593431.7 | 511017.9 | 27439 | 1.64041666667 | 11915 |
| 012830 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:04pm | Sensor | 1797-S0028-636-G-DTE | 6810.2 | 1593427.8 | 511016.7 | 27441 | 1.64041666667 | 12830 |
| 013719 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:05pm | Sensor | 1797-S0028-636-G-DTE | 6809.9 | 1593424.7 | 511015.3 | 27443 | 1.64041666667 | 13719 |
| 012690 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:06pm | Sensor | 1797-S0028-636-G-DTE | 6809.9 | 1593421.1 | 511013.3 | 27445 | 1.64041666667 | 12690 |
| 012545 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:07pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593417.7 | 511012.1 | 27447 | 1.64041666667 | 12545 |
| 012501 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.8 | 1593413.5 | 511010.2 | 27449 | 1.64041666667 | 12501 |
| 013317 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:09pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593410.8 | 511008.3 | 27451 | 1.64041666667 | 13317 |
| 012861 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:10pm | Sensor | 1797-S0028-636-G-DTE | 6809.8 | 1593406.8 | 511006.2 | 27453 | 1.64041666667 | 12861 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:11pm | Sensor | 1797-S0028-636-G-DTE | 6809.8 | 1593403.9 | 511005.3 | 27455 | 1.64041666667 | 13436 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:12pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593399.9 | 511002.8 | 27457 | 1.64041666667 | 12853 |
| 013312 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:13pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593397.1 | 511000.9 | 27459 | 1.64041666667 | 13312 |
| 014673 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:14pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593392.8 | 510999.7 | 27461 | 1.64041666667 | 14673 |
| 013833 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:15pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593390.0 | 510998.6 | 27463 | 1.64041666667 | 13833 |
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593386.9 | 510996.5 | 27465 | 1.64041666667 | 12761 |
| 013185 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:17pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593383.7 | 510994.9 | 27467 | 1.64041666667 | 13185 |
| 012524 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593380.2 | 510993.4 | 27469 | 1.64041666667 | 12524 |
| 012632 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593377.8 | 510991.4 | 27470 | 1.64041666667 | 12632 |
| 013676 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:20pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593374.1 | 510989.2 | 27473 | 1.64041666667 | 13676 |
| 013332 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:21pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593370.9 | 510988.6 | 27475 | 1.64041666667 | 13332 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013934 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:22pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593367.6 | 510987.0 | 27477 | 1.64041666667 | 13934 |
| 013373 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:22pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593365.0 | 510985.5 | 27478 | 1.64041666667 | 13373 |
| 013785 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593361.9 | 510984.8 | 27481 | 1.64041666667 | 13785 |
| 014684 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593359.5 | 510983.9 | 27482 | 1.64041666667 | 14684 |
| 013884 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593356.2 | 510983.4 | 27485 | 1.64041666667 | 13884 |
| 013217 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:27pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593354.3 | 510985.1 | 27487 | 1.64041666667 | 13217 |
| 012880 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593351.9 | 510987.5 | 27489 | 1.64041666667 | 12880 |
| 012517 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:29pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593349.8 | 510990.0 | 27491 | 1.64041666667 | 12517 |
| 013003 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:30pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593348.1 | 510993.3 | 27493 | 1.64041666667 | 13003 |
| 012429 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:30pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593346.5 | 510995.8 | 27494 | 1.64041666667 | 12429 |
| 011881 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:32pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593344.2 | 510999.3 | 27497 | 1.64041666667 | 11881 |
| 011865 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:32pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593343.2 | 511002.5 | 27498 | 1.64041666667 | 11865 |
| 011834 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:34pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593341.8 | 511006.7 | 27501 | 1.64041666667 | 11834 |
| 012769 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:35pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593339.7 | 511009.7 | 27503 | 1.64041666667 | 12769 |
| 012575 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:36pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593338.4 | 511012.8 | 27505 | 1.64041666667 | 12575 |
| 012406 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:37pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593337.5 | 511015.4 | 27507 | 1.64041666667 | 12406 |
| 012498 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:38pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593335.5 | 511019.0 | 27509 | 1.64041666667 | 12498 |
| 013068 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:39pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593334.3 | 511021.5 | 27511 | 1.64041666667 | 13068 |
| 013133 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:40pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593333.0 | 511025.6 | 27513 | 1.64041666667 | 13133 |
| 013125 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:41pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593331.5 | 511028.4 | 27515 | 1.64041666667 | 13125 |
| 012835 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593329.5 | 511031.7 | 27517 | 1.64041666667 | 12835 |
| 013077 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:43pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593328.3 | 511034.7 | 27519 | 1.64041666667 | 13077 |
| 013206 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:44pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593326.5 | 511038.2 | 27521 | 1.64041666667 | 13206 |
| 013166 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:45pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593324.7 | 511040.4 | 27523 | 1.64041666667 | 13166 |
| 013638 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:46pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593323.0 | 511043.7 | 27525 | 1.64041666667 | 13638 |
| 013379 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593322.0 | 511046.7 | 27526 | 1.64041666667 | 13379 |
| 012888 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:48pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593320.0 | 511050.1 | 27529 | 1.64041666667 | 12888 |
| 013399 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:49pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593318.3 | 511053.2 | 27531 | 1.64041666667 | 13399 |
| 013740 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593317.0 | 511056.9 | 27533 | 1.64041666667 | 13740 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:51pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593315.5 | 511060.0 | 27535 | 1.64041666667 | 13736 |
| 013854 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:52pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593313.9 | 511063.6 | 27537 | 1.64041666667 | 13854 |
| 013635 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:53pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593313.4 | 511066.9 | 27539 | 1.64041666667 | 13635 |
| 013714 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:54pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593311.7 | 511069.9 | 27541 | 1.64041666667 | 13714 |
| 013249 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:55pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593310.2 | 511072.5 | 27543 | 1.64041666667 | 13249 |
| 013378 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:56pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593309.4 | 511076.1 | 27545 | 1.64041666667 | 13378 |
| 013330 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:56pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593308.2 | 511078.8 | 27546 | 1.64041666667 | 13330 |
| 013528 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:58pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593305.9 | 511081.7 | 27549 | 1.64041666667 | 13528 |
| 013249 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:58pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593306.0 | 511084.8 | 27550 | 1.64041666667 | 13249 |
| 013633 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:00pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593308.8 | 511088.5 | 27553 | 1.64041666667 | 13633 |
| 013376 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:01pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593311.3 | 511090.7 | 27555 | 1.64041666667 | 13376 |
| 014446 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:02pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593315.4 | 511092.5 | 27557 | 1.64041666667 | 14446 |
| 015243 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:02pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593318.3 | 511093.5 | 27558 | 1.64041666667 | 15243 |
| 014537 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:04pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593321.9 | 511095.4 | 27561 | 1.64041666667 | 14537 |
| 014154 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:05pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593325.2 | 511096.8 | 27563 | 1.64041666667 | 14154 |
| 013887 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593328.9 | 511098.1 | 27565 | 1.64041666667 | 13887 |
| 014343 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:07pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593331.6 | 511099.7 | 27567 | 1.64041666667 | 14343 |
| 014533 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:08pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593335.5 | 511101.6 | 27569 | 1.64041666667 | 14533 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:09pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593338.5 | 511102.6 | 27571 | 1.64041666667 | 14092 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014969 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:10pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593342.2 | 511104.7 | 27573 | 1.64041666667 | 14969 |
| 014870 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:11pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593345.3 | 511106.4 | 27575 | 1.64041666667 | 14870 |
| 014724 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593349.1 | 511107.6 | 27577 | 1.64041666667 | 14724 |
| 015362 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:13pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593352.2 | 511109.0 | 27579 | 1.64041666667 | 15362 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:14pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593355.6 | 511110.9 | 27581 | 1.64041666667 | 14626 |
| 014430 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:14pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593358.5 | 511111.8 | 27582 | 1.64041666667 | 14430 |
| 014476 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:16pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593362.1 | 511113.5 | 27585 | 1.64041666667 | 14476 |
| 014593 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:17pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593364.8 | 511115.3 | 27587 | 1.64041666667 | 14593 |
| 014628 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:18pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593368.0 | 511116.5 | 27589 | 1.64041666667 | 14628 |
| 014348 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:18pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593371.1 | 511118.1 | 27590 | 1.64041666667 | 14348 |
| 013846 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:20pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593374.8 | 511119.7 | 27593 | 1.64041666667 | 13846 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:20pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593377.7 | 511120.0 | 27594 | 1.64041666667 | 13631 |
| 013240 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:22pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593381.3 | 511121.4 | 27597 | 1.64041666667 | 13240 |
| 014040 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:23pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593383.9 | 511123.0 | 27599 | 1.64041666667 | 14040 |
| 014640 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:24pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593387.6 | 511124.1 | 27601 | 1.64041666667 | 14640 |
| 014115 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:24pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593390.1 | 511125.4 | 27602 | 1.64041666667 | 14115 |
| 014194 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:26pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593393.4 | 511127.4 | 27605 | 1.64041666667 | 14194 |
| 014247 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:26pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593396.1 | 511128.1 | 27606 | 1.64041666667 | 14247 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593399.7 | 511129.9 | 27609 | 1.64041666667 | 13526 |
| 012626 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593402.1 | 511130.8 | 27610 | 1.64041666667 | 12626 |
| 013567 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:30pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593405.8 | 511131.0 | 27613 | 1.64041666667 | 13567 |
| 014119 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:31pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593408.9 | 511131.1 | 27615 | 1.64041666667 | 14119 |
| 013987 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:32pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593411.9 | 511128.9 | 27617 | 1.64041666667 | 13987 |
| 013365 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:33pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593413.4 | 511126.0 | 27619 | 1.64041666667 | 13365 |
| 013300 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:34pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593415.3 | 511122.6 | 27621 | 1.64041666667 | 13300 |
| 013451 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:34pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593416.6 | 511119.9 | 27622 | 1.64041666667 | 13451 |
| 013176 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:36pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593417.7 | 511116.4 | 27625 | 1.64041666667 | 13176 |
| 012504 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:36pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593419.7 | 511113.5 | 27626 | 1.64041666667 | 12504 |
| 012726 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:38pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593422.1 | 511110.3 | 27629 | 1.64041666667 | 12726 |
| 012836 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:38pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593423.1 | 511107.5 | 27630 | 1.64041666667 | 12836 |
| 012927 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:40pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593425.0 | 511102.7 | 27633 | 1.64041666667 | 12927 |
| 012101 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:41pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593426.7 | 511099.3 | 27635 | 1.64041666667 | 12101 |
| 011712 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593428.3 | 511094.9 | 27637 | 1.64041666667 | 11712 |
| 012670 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:43pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593429.1 | 511091.9 | 27639 | 1.64041666667 | 12670 |
| 012857 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:44pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593431.1 | 511087.8 | 27641 | 1.64041666667 | 12857 |
| 012984 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:45pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593432.4 | 511084.9 | 27643 | 1.64041666667 | 12984 |
| 012779 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593433.3 | 511080.9 | 27645 | 1.64041666667 | 12779 |
| 012370 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:47pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593434.8 | 511077.3 | 27647 | 1.64041666667 | 12370 |
| 012501 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593436.6 | 511073.8 | 27649 | 1.64041666667 | 12501 |
| 012791 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593438.0 | 511071.0 | 27650 | 1.64041666667 | 12791 |
| 012588 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:50pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593439.3 | 511067.2 | 27653 | 1.64041666667 | 12588 |
| 012600 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:51pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593440.5 | 511064.6 | 27655 | 1.64041666667 | 12600 |
| 013020 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:52pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593440.8 | 511062.0 | 27657 | 1.64041666667 | 13020 |
| 012626 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:52pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593440.8 | 511060.7 | 27658 | 1.64041666667 | 12626 |
| 012562 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:54pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593441.0 | 511060.5 | 27661 | 1.64041666667 | 12562 |
| 013201 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:55pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593442.1 | 511060.4 | 27663 | 1.64041666667 | 13201 |
| 013238 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:56pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593443.3 | 511057.9 | 27665 | 1.64041666667 | 13238 |
| 012441 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:56pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593444.3 | 511055.0 | 27666 | 1.64041666667 | 12441 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012825 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:58pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593446.9 | 511051.7 | 27669 | 1.64041666667 | 12825 |
| 012644 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:58pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593448.8 | 511048.9 | 27670 | 1.64041666667 | 12644 |
| 012280 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:00pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593450.0 | 511045.0 | 27673 | 1.64041666667 | 12280 |
| 011925 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:01pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593451.5 | 511042.0 | 27675 | 1.64041666667 | 11925 |
| 012213 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:02pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593453.2 | 511038.8 | 27677 | 1.64041666667 | 12213 |
| 011887 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:03pm | Sensor | 1797-S0028-636-G-DTE | 6809.8 | 1593453.6 | 511035.9 | 27679 | 1.64041666667 | 11887 |
| 012536 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:04pm | Sensor | 1797-S0028-636-G-DTE | 6810.0 | 1593454.8 | 511033.2 | 27681 | 1.64041666667 | 12536 |
| 012774 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:05pm | Sensor | 1797-S0028-636-G-DTE | 6809.9 | 1593455.1 | 511031.1 | 27683 | 1.64041666667 | 12774 |
| 012563 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:06pm | Sensor | 1797-S0028-636-G-DTE | 6809.8 | 1593454.3 | 511032.4 | 27685 | 1.64041666667 | 12563 |
| 012346 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:06pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593453.0 | 511034.1 | 27686 | 1.64041666667 | 12346 |
| 012277 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593453.1 | 511035.5 | 27689 | 1.64041666667 | 12277 |
| 012493 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593452.3 | 511036.0 | 27690 | 1.64041666667 | 12493 |
| 012397 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:10pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593450.2 | 511034.5 | 27693 | 1.64041666667 | 12397 |
| 011691 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:11pm | Sensor | 1797-S0028-636-G-DTE | 6809.8 | 1593447.8 | 511034.0 | 27695 | 1.64041666667 | 11691 |
| 011413 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:12pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593444.5 | 511031.6 | 27697 | 1.64041666667 | 11413 |
| 010875 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:13pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593441.8 | 511030.1 | 27699 | 1.64041666667 | 10875 |
| 011517 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:14pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593437.6 | 511029.4 | 27701 | 1.64041666667 | 11517 |
| 012613 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:15pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593434.3 | 511027.8 | 27703 | 1.64041666667 | 12613 |
| 011812 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593430.7 | 511025.7 | 27705 | 1.64041666667 | 11812 |
| 012629 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593427.4 | 511024.8 | 27706 | 1.64041666667 | 12629 |
| 012211 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593423.3 | 511023.7 | 27709 | 1.64041666667 | 12211 |
| 011609 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593420.5 | 511022.1 | 27710 | 1.64041666667 | 11609 |
| 011817 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:20pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593417.0 | 511019.5 | 27713 | 1.64041666667 | 11817 |
| 011320 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:21pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593414.2 | 511018.1 | 27715 | 1.64041666667 | 11320 |
| 011857 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:22pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593411.4 | 511016.3 | 27717 | 1.64041666667 | 11857 |
| 011919 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:23pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593408.5 | 511014.2 | 27719 | 1.64041666667 | 11919 |
| 012412 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593404.7 | 511013.1 | 27721 | 1.64041666667 | 12412 |
| 012419 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:25pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593401.8 | 511012.1 | 27723 | 1.64041666667 | 12419 |
| 012896 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593398.5 | 511010.3 | 27725 | 1.64041666667 | 12896 |
| 013276 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593396.0 | 511009.6 | 27726 | 1.64041666667 | 13276 |
| 013153 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593393.1 | 511007.8 | 27729 | 1.64041666667 | 13153 |
| 013188 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593391.3 | 511006.3 | 27730 | 1.64041666667 | 13188 |
| 012541 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:30pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593387.8 | 511005.2 | 27733 | 1.64041666667 | 12541 |
| 012476 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:30pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593385.7 | 511003.4 | 27734 | 1.64041666667 | 12476 |
| 012943 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:32pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593382.4 | 511001.7 | 27737 | 1.64041666667 | 12943 |
| 013310 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:33pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593379.4 | 511000.8 | 27739 | 1.64041666667 | 13310 |
| 012759 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:34pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593376.7 | 510998.6 | 27741 | 1.64041666667 | 12759 |
| 013162 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:35pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593373.9 | 510997.1 | 27743 | 1.64041666667 | 13162 |
| 013868 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:36pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593370.9 | 510995.5 | 27745 | 1.64041666667 | 13868 |
| 013621 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:36pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593368.8 | 510993.7 | 27746 | 1.64041666667 | 13621 |
| 013504 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:38pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593365.1 | 510992.7 | 27749 | 1.64041666667 | 13504 |
| 012981 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:38pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593362.6 | 510991.5 | 27750 | 1.64041666667 | 12981 |
| 013444 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:40pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593359.4 | 510989.5 | 27753 | 1.64041666667 | 13444 |
| 013795 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:40pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593356.8 | 510988.9 | 27754 | 1.64041666667 | 13795 |
| 012867 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593354.0 | 510987.6 | 27757 | 1.64041666667 | 12867 |
| 012690 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:43pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593352.3 | 510987.2 | 27759 | 1.64041666667 | 12690 |
| 012478 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:44pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593351.0 | 510989.8 | 27761 | 1.64041666667 | 12478 |
| 012966 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:44pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593349.4 | 510991.7 | 27762 | 1.64041666667 | 12966 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012506 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593350.4 | 510993.2 | 27765 | 1.64041666667 | 12506 |
| 012359 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593351.9 | 510994.7 | 27766 | 1.64041666667 | 12359 |
| 012165 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593355.1 | 510996.0 | 27769 | 1.64041666667 | 12165 |
| 011612 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593357.4 | 510997.6 | 27770 | 1.64041666667 | 11612 |
| 012674 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593360.5 | 510999.6 | 27773 | 1.64041666667 | 12674 |
| 012732 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593362.9 | 511000.3 | 27774 | 1.64041666667 | 12732 |
| 012509 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593365.8 | 511002.9 | 27777 | 1.64041666667 | 12509 |
| 012414 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593368.4 | 511004.7 | 27778 | 1.64041666667 | 12414 |
| 012742 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593372.8 | 511006.8 | 27781 | 1.64041666667 | 12742 |
| 013272 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593375.9 | 511008.1 | 27782 | 1.64041666667 | 13272 |
| 013308 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:55pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593379.2 | 511009.1 | 27784 | 1.64041666667 | 13308 |
| 013763 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:56pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593382.3 | 511009.2 | 27786 | 1.64041666667 | 13763 |
| 013284 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:57pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593385.3 | 511010.2 | 27788 | 1.64041666667 | 13284 |
| 013022 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593388.1 | 511011.0 | 27790 | 1.64041666667 | 13022 |
| 013910 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:00pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593392.0 | 511012.0 | 27793 | 1.64041666667 | 13910 |
| 012774 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:00pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593394.3 | 511013.7 | 27794 | 1.64041666667 | 12774 |
| 012983 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:02pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593397.7 | 511015.9 | 27797 | 1.64041666667 | 12983 |
| 012965 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:02pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593400.1 | 511016.9 | 27798 | 1.64041666667 | 12965 |
| 012520 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:04pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593403.3 | 511019.1 | 27801 | 1.64041666667 | 12520 |
| 012645 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:04pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593405.6 | 511020.3 | 27802 | 1.64041666667 | 12645 |
| 012438 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:05pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593408.6 | 511022.4 | 27804 | 1.64041666667 | 12438 |
| 012291 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593411.9 | 511025.3 | 27806 | 1.64041666667 | 12291 |
| 012021 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:07pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593415.6 | 511027.0 | 27808 | 1.64041666667 | 12021 |
| 012042 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593419.0 | 511028.9 | 27810 | 1.64041666667 | 12042 |
| 012263 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:09pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593421.4 | 511031.2 | 27812 | 1.64041666667 | 12263 |
| 012725 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:10pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593424.3 | 511031.3 | 27814 | 1.64041666667 | 12725 |
| 012806 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:12pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593428.0 | 511031.7 | 27817 | 1.64041666667 | 12806 |
| 013016 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:12pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593429.9 | 511032.9 | 27818 | 1.64041666667 | 13016 |
| 013036 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:13pm | Sensor | 1797-S0028-636-G-DTE | 6809.8 | 1593432.8 | 511033.6 | 27820 | 1.64041666667 | 13036 |
| 013460 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:14pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593435.4 | 511035.4 | 27822 | 1.64041666667 | 13460 |
| 012949 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593438.3 | 511037.9 | 27825 | 1.64041666667 | 12949 |
| 013148 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593440.8 | 511038.4 | 27826 | 1.64041666667 | 13148 |
| 012518 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593443.9 | 511040.2 | 27829 | 1.64041666667 | 12518 |
| 013154 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593445.7 | 511041.5 | 27830 | 1.64041666667 | 13154 |
| 012371 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:20pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593448.3 | 511042.4 | 27833 | 1.64041666667 | 12371 |
| 012411 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:20pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593448.0 | 511044.2 | 27834 | 1.64041666667 | 12411 |
| 012584 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:22pm | Sensor | 1797-S0028-636-G-DTE | 6809.7 | 1593448.3 | 511047.1 | 27837 | 1.64041666667 | 12584 |
| 012463 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:23pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593447.4 | 511048.8 | 27839 | 1.64041666667 | 12463 |
| 011863 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593447.3 | 511050.0 | 27841 | 1.64041666667 | 11863 |
| 011375 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:25pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593445.7 | 511049.4 | 27843 | 1.64041666667 | 11375 |
| 011596 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593443.4 | 511048.0 | 27845 | 1.64041666667 | 11596 |
| 012620 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593440.5 | 511047.3 | 27846 | 1.64041666667 | 12620 |
| 011808 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:27pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593437.0 | 511046.0 | 27848 | 1.64041666667 | 11808 |
| 012200 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:28pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593434.2 | 511044.4 | 27850 | 1.64041666667 | 12200 |
| 012697 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:30pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593430.3 | 511042.5 | 27853 | 1.64041666667 | 12697 |
| 012167 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:30pm | Sensor | 1797-S0028-636-G-DTE | 6809.6 | 1593428.2 | 511041.6 | 27854 | 1.64041666667 | 12167 |
| 012379 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:31pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593426.3 | 511039.2 | 27856 | 1.64041666667 | 12379 |
| 012498 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:32pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593423.8 | 511037.3 | 27858 | 1.64041666667 | 12498 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013052 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:33pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593420.5 | 511035.6 | 27860 | 1.64041666667 | 13052 |
| 012854 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:34pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593417.9 | 511034.0 | 27862 | 1.64041666667 | 12854 |
| 012728 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:35pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593414.8 | 511032.3 | 27864 | 1.64041666667 | 12728 |
| 012694 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:36pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593411.3 | 511030.6 | 27866 | 1.64041666667 | 12694 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:37pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593408.4 | 511028.4 | 27868 | 1.64041666667 | 13043 |
| 013111 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:38pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593405.7 | 511026.5 | 27870 | 1.64041666667 | 13111 |
| 012753 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:40pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593401.5 | 511024.4 | 27873 | 1.64041666667 | 12753 |
| 012626 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:40pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593399.7 | 511022.7 | 27874 | 1.64041666667 | 12626 |
| 012749 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593395.8 | 511019.3 | 27877 | 1.64041666667 | 12749 |
| 012984 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:42pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593393.8 | 511018.0 | 27878 | 1.64041666667 | 12984 |
| 012051 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:44pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593389.9 | 511013.8 | 27881 | 1.64041666667 | 12051 |
| 012786 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:45pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593388.3 | 511012.4 | 27883 | 1.64041666667 | 12786 |
| 012832 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:46pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593385.6 | 511010.7 | 27885 | 1.64041666667 | 12832 |
| 012873 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:47pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593384.8 | 511009.2 | 27887 | 1.64041666667 | 12873 |
| 013143 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593382.1 | 511009.3 | 27889 | 1.64041666667 | 13143 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593379.5 | 511009.1 | 27890 | 1.64041666667 | 13738 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593375.6 | 511010.1 | 27893 | 1.64041666667 | 14072 |
| 013833 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593372.7 | 511010.9 | 27894 | 1.64041666667 | 13833 |
| 013406 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593368.8 | 511010.1 | 27897 | 1.64041666667 | 13406 |
| 012978 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593365.6 | 511008.5 | 27898 | 1.64041666667 | 12978 |
| 013098 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593362.1 | 511007.0 | 27901 | 1.64041666667 | 13098 |
| 013150 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593359.0 | 511005.4 | 27902 | 1.64041666667 | 13150 |
| 012504 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:55pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593356.0 | 511003.4 | 27904 | 1.64041666667 | 12504 |
| 011638 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593352.4 | 511002.5 | 27906 | 1.64041666667 | 11638 |
| 011842 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:57pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593349.1 | 511001.8 | 27908 | 1.64041666667 | 11842 |
| 012256 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593346.6 | 511000.5 | 27910 | 1.64041666667 | 12256 |
| 012309 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:59pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593344.2 | 511002.4 | 27912 | 1.64041666667 | 12309 |
| 012848 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:00pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593342.2 | 511004.6 | 27914 | 1.64041666667 | 12848 |
| 013017 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:01pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593340.9 | 511007.2 | 27916 | 1.64041666667 | 13017 |
| 012572 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:02pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593341.1 | 511007.6 | 27918 | 1.64041666667 | 12572 |
| 013019 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:03pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593342.2 | 511007.8 | 27920 | 1.64041666667 | 13019 |
| 012746 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:04pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593344.2 | 511009.4 | 27922 | 1.64041666667 | 12746 |
| 012922 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:05pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593347.5 | 511011.4 | 27924 | 1.64041666667 | 12922 |
| 013096 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593350.3 | 511011.9 | 27926 | 1.64041666667 | 13096 |
| 012624 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:07pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593353.4 | 511013.9 | 27928 | 1.64041666667 | 12624 |
| 011773 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:08pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593356.6 | 511014.9 | 27930 | 1.64041666667 | 11773 |
| 012457 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:09pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593360.1 | 511015.7 | 27932 | 1.64041666667 | 12457 |
| 012512 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:10pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593362.5 | 511016.7 | 27934 | 1.64041666667 | 12512 |
| 012355 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:11pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593365.8 | 511017.3 | 27936 | 1.64041666667 | 12355 |
| 012357 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593368.6 | 511018.1 | 27938 | 1.64041666667 | 12357 |
| 012561 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:13pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593372.0 | 511018.9 | 27940 | 1.64041666667 | 12561 |
| 011925 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:14pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593375.2 | 511018.5 | 27942 | 1.64041666667 | 11925 |
| 012618 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:16pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593379.8 | 511018.4 | 27945 | 1.64041666667 | 12618 |
| 012610 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:16pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593382.4 | 511019.3 | 27946 | 1.64041666667 | 12610 |
| 012433 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:18pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593385.7 | 511019.9 | 27949 | 1.64041666667 | 12433 |
| 013166 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:18pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593388.1 | 511021.4 | 27950 | 1.64041666667 | 13166 |
| 013743 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:19pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593390.3 | 511024.5 | 27952 | 1.64041666667 | 13743 |
| 013490 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:20pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593393.1 | 511026.7 | 27954 | 1.64041666667 | 13490 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013011 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:21pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593396.3 | 511028.4 | 27956 | 1.64041666667 | 13011 |
| 012583 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:22pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593398.9 | 511030.5 | 27958 | 1.64041666667 | 12583 |
| 013220 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:24pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593402.3 | 511033.0 | 27961 | 1.64041666667 | 13220 |
| 012469 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593405.1 | 511034.3 | 27962 | 1.64041666667 | 12469 |
| 012654 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:25pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593408.2 | 511036.0 | 27964 | 1.64041666667 | 12654 |
| 012142 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:26pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593411.2 | 511037.4 | 27966 | 1.64041666667 | 12142 |
| 012215 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593415.1 | 511038.3 | 27969 | 1.64041666667 | 12215 |
| 011633 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593417.9 | 511039.5 | 27970 | 1.64041666667 | 11633 |
| 013031 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:29pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593421.2 | 511041.3 | 27972 | 1.64041666667 | 13031 |
| 012610 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:30pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593424.0 | 511042.3 | 27974 | 1.64041666667 | 12610 |
| 013153 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:31pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593426.7 | 511044.0 | 27976 | 1.64041666667 | 13153 |
| 013338 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:32pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593429.1 | 511045.4 | 27978 | 1.64041666667 | 13338 |
| 012730 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:33pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593432.2 | 511047.2 | 27980 | 1.64041666667 | 12730 |
| 012651 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:34pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593434.3 | 511048.8 | 27982 | 1.64041666667 | 12651 |
| 013153 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:35pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593436.8 | 511050.6 | 27984 | 1.64041666667 | 13153 |
| 012483 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:36pm | Sensor | 1797-S0028-636-G-DTE | 6809.5 | 1593439.2 | 511051.5 | 27986 | 1.64041666667 | 12483 |
| 011567 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:37pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593439.8 | 511053.6 | 27988 | 1.64041666667 | 11567 |
| 012664 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:38pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593440.6 | 511056.0 | 27990 | 1.64041666667 | 12664 |
| 013873 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:39pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593440.1 | 511058.1 | 27992 | 1.64041666667 | 13873 |
| 014186 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:40pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593439.8 | 511058.9 | 27994 | 1.64041666667 | 14186 |
| 014850 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:41pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593440.0 | 511058.9 | 27996 | 1.64041666667 | 14850 |
| 014143 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:42pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593439.8 | 511059.2 | 27998 | 1.64041666667 | 14143 |
| 014120 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:43pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593439.8 | 511059.3 | 28000 | 1.64041666667 | 14120 |
| 014197 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:44pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593439.8 | 511059.3 | 28002 | 1.64041666667 | 14197 |
| 013986 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:45pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593439.9 | 511059.3 | 28004 | 1.64041666667 | 13986 |
| 013575 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:46pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593439.7 | 511059.2 | 28006 | 1.64041666667 | 13575 |
| 012968 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593438.7 | 511058.5 | 28009 | 1.64041666667 | 12968 |
| 012267 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593438.7 | 511058.5 | 28010 | 1.64041666667 | 12267 |
| 013110 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:49pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593438.6 | 511058.5 | 28012 | 1.64041666667 | 13110 |
| 012977 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:51pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593438.6 | 511058.5 | 28015 | 1.64041666667 | 12977 |
| 012759 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593438.7 | 511058.5 | 28017 | 1.64041666667 | 12759 |
| 011955 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593438.8 | 511058.5 | 28018 | 1.64041666667 | 11955 |
| 011749 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593438.7 | 511058.5 | 28021 | 1.64041666667 | 11749 |
| 012099 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593438.6 | 511058.4 | 28022 | 1.64041666667 | 12099 |
| 013593 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593438.6 | 511058.5 | 28025 | 1.64041666667 | 13593 |
| 013128 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593438.7 | 511058.5 | 28026 | 1.64041666667 | 13128 |
| 013707 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593438.7 | 511058.5 | 28029 | 1.64041666667 | 13707 |
| 013275 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593438.6 | 511058.5 | 28030 | 1.64041666667 | 13275 |
| 012934 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:59pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593438.7 | 511058.5 | 28032 | 1.64041666667 | 12934 |
| 012488 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:00pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593438.7 | 511058.9 | 28034 | 1.64041666667 | 12488 |
| 012477 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:01pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593438.0 | 511059.1 | 28036 | 1.64041666667 | 12477 |
| 011751 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:02pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593435.9 | 511058.7 | 28038 | 1.64041666667 | 11751 |
| 012205 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:04pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593432.9 | 511056.4 | 28041 | 1.64041666667 | 12205 |
| 013075 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:04pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593430.3 | 511054.9 | 28042 | 1.64041666667 | 13075 |
| 012874 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:06pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593427.0 | 511052.5 | 28045 | 1.64041666667 | 12874 |
| 012184 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:06pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593425.2 | 511050.5 | 28046 | 1.64041666667 | 12184 |
| 012464 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593422.1 | 511049.5 | 28049 | 1.64041666667 | 12464 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593420.0 | 511049.1 | 28050 | 1.64041666667 | 12853 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012427 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:10pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593416.2 | 511048.4 | 28053 | 1.64041666667 | 12427 |
| 012450 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:10pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593413.5 | 511048.6 | 28054 | 1.64041666667 | 12450 |
| 012471 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593409.1 | 511047.9 | 28057 | 1.64041666667 | 12471 |
| 012662 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593406.6 | 511046.8 | 28058 | 1.64041666667 | 12662 |
| 013010 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:13pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593403.1 | 511045.0 | 28060 | 1.64041666667 | 13010 |
| 013310 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:14pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593400.0 | 511043.0 | 28062 | 1.64041666667 | 13310 |
| 012812 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:16pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593397.3 | 511040.8 | 28065 | 1.64041666667 | 12812 |
| 012757 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593394.6 | 511039.8 | 28066 | 1.64041666667 | 12757 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593391.5 | 511037.7 | 28069 | 1.64041666667 | 12785 |
| 012517 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593389.4 | 511035.8 | 28070 | 1.64041666667 | 12517 |
| 012973 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:20pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593385.9 | 511034.0 | 28073 | 1.64041666667 | 12973 |
| 012660 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:20pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593383.5 | 511032.2 | 28074 | 1.64041666667 | 12660 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:22pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593380.9 | 511029.2 | 28077 | 1.64041666667 | 12236 |
| 012080 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:22pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593378.4 | 511027.3 | 28078 | 1.64041666667 | 12080 |
| 012922 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:24pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593375.0 | 511024.3 | 28081 | 1.64041666667 | 12922 |
| 013201 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:24pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593373.2 | 511022.0 | 28082 | 1.64041666667 | 13201 |
| 012458 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:26pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593369.5 | 511019.7 | 28085 | 1.64041666667 | 12458 |
| 013420 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:26pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593366.7 | 511018.1 | 28086 | 1.64041666667 | 13420 |
| 012603 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:27pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593363.8 | 511015.6 | 28088 | 1.64041666667 | 12603 |
| 011702 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593360.9 | 511013.8 | 28090 | 1.64041666667 | 11702 |
| 011427 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:29pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593357.5 | 511011.9 | 28092 | 1.64041666667 | 11427 |
| 011347 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:30pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593355.3 | 511010.1 | 28094 | 1.64041666667 | 11347 |
| 011565 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:31pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593351.9 | 511008.6 | 28096 | 1.64041666667 | 11565 |
| 011935 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:32pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593348.8 | 511007.1 | 28098 | 1.64041666667 | 11935 |
| 011986 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:33pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593345.3 | 511005.6 | 28100 | 1.64041666667 | 11986 |
| 011572 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:34pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593342.8 | 511005.5 | 28102 | 1.64041666667 | 11572 |
| 012479 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:35pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593340.5 | 511006.7 | 28104 | 1.64041666667 | 12479 |
| 011429 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:36pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593338.9 | 511008.9 | 28106 | 1.64041666667 | 11429 |
| 011919 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:37pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593338.6 | 511011.7 | 28108 | 1.64041666667 | 11919 |
| 011909 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:38pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593336.9 | 511014.2 | 28110 | 1.64041666667 | 11909 |
| 011904 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:39pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593337.4 | 511014.9 | 28112 | 1.64041666667 | 11904 |
| 012411 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:40pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593337.7 | 511015.6 | 28114 | 1.64041666667 | 12411 |
| 012958 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:41pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593338.9 | 511016.8 | 28116 | 1.64041666667 | 12958 |
| 013679 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593340.9 | 511017.9 | 28118 | 1.64041666667 | 13679 |
| 013019 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:43pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593343.1 | 511020.2 | 28120 | 1.64041666667 | 13019 |
| 012656 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:44pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593345.9 | 511021.1 | 28122 | 1.64041666667 | 12656 |
| 013081 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:45pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593349.7 | 511022.0 | 28124 | 1.64041666667 | 13081 |
| 012818 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593352.5 | 511022.9 | 28126 | 1.64041666667 | 12818 |
| 012685 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:47pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593356.4 | 511022.8 | 28128 | 1.64041666667 | 12685 |
| 012633 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593359.6 | 511023.5 | 28130 | 1.64041666667 | 12633 |
| 013241 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:49pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593362.8 | 511025.3 | 28132 | 1.64041666667 | 13241 |
| 013013 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593365.9 | 511026.6 | 28134 | 1.64041666667 | 13013 |
| 012780 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:51pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593369.6 | 511027.5 | 28136 | 1.64041666667 | 12780 |
| 013428 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593372.3 | 511029.3 | 28138 | 1.64041666667 | 13428 |
| 012503 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:53pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593375.8 | 511031.8 | 28140 | 1.64041666667 | 12503 |
| 012110 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593378.7 | 511033.2 | 28142 | 1.64041666667 | 12110 |
| 012834 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:55pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593382.3 | 511035.3 | 28144 | 1.64041666667 | 12834 |
| 013474 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593384.7 | 511037.4 | 28146 | 1.64041666667 | 13474 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013189 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:57pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593388.1 | 511039.3 | 28148 | 1.64041666667 | 13189 |
| 012832 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593390.5 | 511041.5 | 28150 | 1.64041666667 | 12832 |
| 012718 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:59pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593393.3 | 511044.2 | 28152 | 1.64041666667 | 12718 |
| 012539 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:00pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593395.9 | 511045.6 | 28154 | 1.64041666667 | 12539 |
| 012322 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:01pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593398.8 | 511048.3 | 28156 | 1.64041666667 | 12322 |
| 012421 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:02pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593400.8 | 511050.0 | 28158 | 1.64041666667 | 12421 |
| 012844 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:03pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593401.7 | 511049.8 | 28160 | 1.64041666667 | 12844 |
| 012767 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:04pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593401.7 | 511050.1 | 28162 | 1.64041666667 | 12767 |
| 012589 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:06pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593404.0 | 511050.7 | 28165 | 1.64041666667 | 12589 |
| 012346 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593405.8 | 511051.8 | 28166 | 1.64041666667 | 12346 |
| 012547 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:07pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593408.1 | 511053.3 | 28168 | 1.64041666667 | 12547 |
| 012450 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593409.8 | 511053.5 | 28170 | 1.64041666667 | 12450 |
| 013138 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:09pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593412.3 | 511055.6 | 28172 | 1.64041666667 | 13138 |
| 012445 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:10pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593415.1 | 511056.9 | 28174 | 1.64041666667 | 12445 |
| 012610 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:11pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593418.3 | 511058.3 | 28176 | 1.64041666667 | 12610 |
| 014031 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:12pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593420.3 | 511060.1 | 28178 | 1.64041666667 | 14031 |
| 013052 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:13pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593423.6 | 511061.5 | 28180 | 1.64041666667 | 13052 |
| 013417 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:14pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593426.5 | 511062.4 | 28182 | 1.64041666667 | 13417 |
| 013179 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:15pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593429.3 | 511064.3 | 28184 | 1.64041666667 | 13179 |
| 013271 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593432.0 | 511065.0 | 28186 | 1.64041666667 | 13271 |
| 012865 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:17pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593435.4 | 511066.1 | 28188 | 1.64041666667 | 12865 |
| 013079 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593437.3 | 511067.3 | 28190 | 1.64041666667 | 13079 |
| 012779 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:19pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593439.8 | 511068.1 | 28192 | 1.64041666667 | 12779 |
| 012558 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:20pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593440.5 | 511069.7 | 28194 | 1.64041666667 | 12558 |
| 012209 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:21pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593440.9 | 511072.3 | 28196 | 1.64041666667 | 12209 |
| 012350 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:22pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593440.3 | 511074.7 | 28198 | 1.64041666667 | 12350 |
| 012399 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593437.9 | 511075.6 | 28201 | 1.64041666667 | 12399 |
| 012562 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593435.9 | 511075.0 | 28202 | 1.64041666667 | 12562 |
| 012436 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593432.6 | 511074.4 | 28205 | 1.64041666667 | 12436 |
| 012312 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593430.7 | 511072.5 | 28206 | 1.64041666667 | 12312 |
| 012798 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:27pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593428.1 | 511070.5 | 28208 | 1.64041666667 | 12798 |
| 012764 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:28pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593425.6 | 511069.3 | 28210 | 1.64041666667 | 12764 |
| 012377 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:29pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593423.3 | 511066.9 | 28212 | 1.64041666667 | 12377 |
| 012647 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:30pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593420.9 | 511065.8 | 28214 | 1.64041666667 | 12647 |
| 012694 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:31pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593418.0 | 511064.1 | 28216 | 1.64041666667 | 12694 |
| 012352 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:32pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593415.6 | 511062.6 | 28218 | 1.64041666667 | 12352 |
| 012513 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:33pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593412.1 | 511061.9 | 28220 | 1.64041666667 | 12513 |
| 012213 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:34pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593408.9 | 511060.9 | 28222 | 1.64041666667 | 12213 |
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:35pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593406.0 | 511059.3 | 28224 | 1.64041666667 | 13320 |
| 014220 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:36pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593403.2 | 511058.4 | 28226 | 1.64041666667 | 14220 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:37pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593399.9 | 511056.9 | 28228 | 1.64041666667 | 14111 |
| 013495 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:38pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593397.4 | 511055.8 | 28230 | 1.64041666667 | 13495 |
| 013576 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:39pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593394.2 | 511055.2 | 28232 | 1.64041666667 | 13576 |
| 013006 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:40pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593392.0 | 511053.7 | 28234 | 1.64041666667 | 13006 |
| 012611 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:41pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593388.7 | 511052.5 | 28236 | 1.64041666667 | 12611 |
| 013243 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593386.2 | 511051.5 | 28238 | 1.64041666667 | 13243 |
| 013112 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:43pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593383.3 | 511049.9 | 28240 | 1.64041666667 | 13112 |
| 013398 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:44pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593380.8 | 511049.6 | 28242 | 1.64041666667 | 13398 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012726 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:45pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593378.1 | 511047.7 | 28244 | 1.64041666667 | 12726 |
| 013136 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593375.7 | 511047.1 | 28246 | 1.64041666667 | 13136 |
| 013884 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:47pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593372.9 | 511046.6 | 28248 | 1.64041666667 | 13884 |
| 013503 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:48pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593371.2 | 511045.6 | 28250 | 1.64041666667 | 13503 |
| 012973 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:49pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593368.8 | 511044.2 | 28252 | 1.64041666667 | 12973 |
| 013605 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:50pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593367.3 | 511041.4 | 28254 | 1.64041666667 | 13605 |
| 012468 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:51pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593364.5 | 511039.5 | 28256 | 1.64041666667 | 12468 |
| 012278 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593362.3 | 511037.5 | 28258 | 1.64041666667 | 12278 |
| 012396 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:53pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593360.0 | 511035.1 | 28260 | 1.64041666667 | 12396 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593357.6 | 511033.8 | 28262 | 1.64041666667 | 12853 |
| 012877 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:55pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593354.6 | 511031.4 | 28264 | 1.64041666667 | 12877 |
| 012613 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593352.1 | 511029.7 | 28266 | 1.64041666667 | 12613 |
| 011985 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:57pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593348.7 | 511027.9 | 28268 | 1.64041666667 | 11985 |
| 013296 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593346.4 | 511026.1 | 28270 | 1.64041666667 | 13296 |
| 013666 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:59pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593344.3 | 511024.0 | 28272 | 1.64041666667 | 13666 |
| 013575 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:00pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593343.1 | 511023.9 | 28274 | 1.64041666667 | 13575 |
| 013763 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:01pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593341.4 | 511025.1 | 28276 | 1.64041666667 | 13763 |
| 013697 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:02pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593340.2 | 511027.2 | 28278 | 1.64041666667 | 13697 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:04pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593338.1 | 511029.9 | 28281 | 1.64041666667 | 13974 |
| 013478 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:04pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593338.1 | 511031.7 | 28282 | 1.64041666667 | 13478 |
| 013296 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593337.5 | 511034.6 | 28285 | 1.64041666667 | 13296 |
| 013021 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593338.2 | 511036.5 | 28286 | 1.64041666667 | 13021 |
| 012649 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:08pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593340.3 | 511038.9 | 28289 | 1.64041666667 | 12649 |
| 013258 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:08pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593341.3 | 511041.1 | 28290 | 1.64041666667 | 13258 |
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:09pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593343.7 | 511043.0 | 28292 | 1.64041666667 | 13277 |
| 012778 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:10pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593345.4 | 511044.6 | 28294 | 1.64041666667 | 12778 |
| 012827 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:11pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593346.6 | 511045.7 | 28296 | 1.64041666667 | 12827 |
| 013102 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593347.2 | 511045.8 | 28298 | 1.64041666667 | 13102 |
| 013175 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:13pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593348.8 | 511046.4 | 28300 | 1.64041666667 | 13175 |
| 013523 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:14pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593351.4 | 511046.6 | 28302 | 1.64041666667 | 13523 |
| 014117 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:15pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593354.8 | 511047.6 | 28304 | 1.64041666667 | 14117 |
| 013948 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593357.4 | 511049.0 | 28306 | 1.64041666667 | 13948 |
| 013058 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:17pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593359.9 | 511050.0 | 28308 | 1.64041666667 | 13058 |
| 013945 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:18pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593362.2 | 511051.8 | 28310 | 1.64041666667 | 13945 |
| 014639 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:19pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593364.9 | 511052.9 | 28312 | 1.64041666667 | 14639 |
| 014294 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:20pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593367.0 | 511053.5 | 28314 | 1.64041666667 | 14294 |
| 013778 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:21pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593369.4 | 511055.1 | 28316 | 1.64041666667 | 13778 |
| 013787 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:22pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593371.5 | 511055.4 | 28318 | 1.64041666667 | 13787 |
| 014483 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:23pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593373.9 | 511056.8 | 28320 | 1.64041666667 | 14483 |
| 014139 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593376.4 | 511057.5 | 28322 | 1.64041666667 | 14139 |
| 013571 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:25pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593378.6 | 511058.9 | 28324 | 1.64041666667 | 13571 |
| 013476 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593380.6 | 511059.7 | 28326 | 1.64041666667 | 13476 |
| 012695 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:27pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593383.2 | 511060.8 | 28328 | 1.64041666667 | 12695 |
| 012271 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:28pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593384.1 | 511061.1 | 28330 | 1.64041666667 | 12271 |
| 013262 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:29pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593384.3 | 511061.3 | 28332 | 1.64041666667 | 13262 |
| 013452 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:30pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593384.6 | 511060.6 | 28334 | 1.64041666667 | 13452 |
| 013274 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:31pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593383.6 | 511058.6 | 28336 | 1.64041666667 | 13274 |
| 012192 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:32pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593383.5 | 511057.6 | 28338 | 1.64041666667 | 12192 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011808 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:33pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593383.3 | 511057.5 | 28340 | 1.64041666667 | 11808 |
| 012334 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:34pm | Sensor | 1797-S0028-636-G-DTE | 6809.3 | 1593383.3 | 511057.6 | 28342 | 1.64041666667 | 12334 |
| 011858 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:35pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593383.6 | 511057.5 | 28344 | 1.64041666667 | 11858 |
| 012647 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:36pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593383.8 | 511056.8 | 28346 | 1.64041666667 | 12647 |
| 011704 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:37pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593383.4 | 511056.5 | 28348 | 1.64041666667 | 11704 |
| 011383 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:38pm | Sensor | 1797-S0028-636-G-DTE | 6809.4 | 1593383.6 | 511056.7 | 28350 | 1.64041666667 | 11383 |
| 011976 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:39pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593385.2 | 511056.9 | 28352 | 1.64041666667 | 11976 |
| 012106 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:40pm | Sensor | 1797-S0028-636-G-DTE | 6807.3 | 1593385.5 | 511057.0 | 28354 | 1.64041666667 | 12106 |
| 011842 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:41pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593384.2 | 511057.1 | 28356 | 1.64041666667 | 11842 |
| 012488 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593383.1 | 511056.7 | 28358 | 1.64041666667 | 12488 |
| 012725 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:43pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593383.5 | 511056.1 | 28360 | 1.64041666667 | 12725 |
| 012955 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:44pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593385.0 | 511056.4 | 28362 | 1.64041666667 | 12955 |
| 012522 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:45pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593387.9 | 511056.9 | 28364 | 1.64041666667 | 12522 |
| 012796 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593390.6 | 511058.8 | 28366 | 1.64041666667 | 12796 |
| 012358 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:47pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593393.4 | 511060.8 | 28368 | 1.64041666667 | 12358 |
| 012943 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593396.5 | 511061.9 | 28370 | 1.64041666667 | 12943 |
| 012666 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:49pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593399.8 | 511063.6 | 28372 | 1.64041666667 | 12666 |
| 012404 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593402.2 | 511065.2 | 28374 | 1.64041666667 | 12404 |
| 013255 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:51pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593405.3 | 511066.1 | 28376 | 1.64041666667 | 13255 |
| 013088 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593408.0 | 511068.0 | 28378 | 1.64041666667 | 13088 |
| 012567 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:53pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593411.3 | 511070.2 | 28380 | 1.64041666667 | 12567 |
| 012686 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:54pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593414.3 | 511071.2 | 28382 | 1.64041666667 | 12686 |
| 012783 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:55pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593417.6 | 511073.4 | 28384 | 1.64041666667 | 12783 |
| 013445 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593420.7 | 511075.3 | 28386 | 1.64041666667 | 13445 |
| 013151 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:57pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593424.0 | 511075.7 | 28388 | 1.64041666667 | 13151 |
| 012310 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593426.2 | 511077.0 | 28390 | 1.64041666667 | 12310 |
| 012166 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:59pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593429.4 | 511078.3 | 28392 | 1.64041666667 | 12166 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:00pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593432.4 | 511079.0 | 28394 | 1.64041666667 | 12236 |
| 012748 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:01pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593435.1 | 511080.7 | 28396 | 1.64041666667 | 12748 |
| 012630 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:02pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593437.5 | 511080.9 | 28398 | 1.64041666667 | 12630 |
| 012459 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:03pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593439.0 | 511082.4 | 28400 | 1.64041666667 | 12459 |
| 012003 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:04pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593439.7 | 511083.6 | 28402 | 1.64041666667 | 12003 |
| 011859 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:05pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593439.2 | 511085.5 | 28404 | 1.64041666667 | 11859 |
| 012648 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:06pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593438.3 | 511086.7 | 28406 | 1.64041666667 | 12648 |
| 012987 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:07pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593437.9 | 511088.8 | 28408 | 1.64041666667 | 12987 |
| 012585 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593437.8 | 511088.9 | 28410 | 1.64041666667 | 12585 |
| 012456 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:09pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593437.7 | 511088.7 | 28412 | 1.64041666667 | 12456 |
| 012512 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:10pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593437.0 | 511088.8 | 28414 | 1.64041666667 | 12512 |
| 012543 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:11pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593434.9 | 511088.2 | 28416 | 1.64041666667 | 12543 |
| 012748 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593432.8 | 511087.0 | 28418 | 1.64041666667 | 12748 |
| 013350 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:13pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593430.0 | 511086.0 | 28420 | 1.64041666667 | 13350 |
| 013329 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:14pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593427.4 | 511084.6 | 28422 | 1.64041666667 | 13329 |
| 013625 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:15pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593423.5 | 511083.1 | 28424 | 1.64041666667 | 13625 |
| 013139 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:16pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593420.8 | 511082.8 | 28426 | 1.64041666667 | 13139 |
| 013031 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:17pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593417.3 | 511080.9 | 28428 | 1.64041666667 | 13031 |
| 013555 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:18pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593414.5 | 511079.2 | 28430 | 1.64041666667 | 13555 |
| 013197 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:19pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593411.2 | 511078.1 | 28432 | 1.64041666667 | 13197 |
| 012508 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:20pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593408.9 | 511076.4 | 28434 | 1.64041666667 | 12508 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012661 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:21pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593405.6 | 511074.9 | 28436 | 1.64041666667 | 12661 |
| 012949 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:22pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593402.5 | 511074.1 | 28438 | 1.64041666667 | 12949 |
| 013059 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:23pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593399.6 | 511072.5 | 28440 | 1.64041666667 | 13059 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:24pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593396.8 | 511071.9 | 28442 | 1.64041666667 | 13278 |
| 013866 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:25pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593392.7 | 511070.5 | 28444 | 1.64041666667 | 13866 |
| 014287 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:26pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593390.4 | 511068.8 | 28446 | 1.64041666667 | 14287 |
| 013016 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:27pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593387.0 | 511066.8 | 28448 | 1.64041666667 | 13016 |
| 013231 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593384.6 | 511064.8 | 28450 | 1.64041666667 | 13231 |
| 013150 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:29pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593382.2 | 511062.5 | 28452 | 1.64041666667 | 13150 |
| 013404 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:30pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593379.6 | 511061.3 | 28454 | 1.64041666667 | 13404 |
| 012805 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:31pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593376.9 | 511059.1 | 28456 | 1.64041666667 | 12805 |
| 013263 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:32pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593374.0 | 511058.1 | 28458 | 1.64041666667 | 13263 |
| 013167 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:33pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593370.3 | 511057.3 | 28460 | 1.64041666667 | 13167 |
| 012619 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:34pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593368.0 | 511056.0 | 28462 | 1.64041666667 | 12619 |
| 012491 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:35pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593364.4 | 511055.0 | 28464 | 1.64041666667 | 12491 |
| 012973 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:36pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593361.8 | 511053.2 | 28466 | 1.64041666667 | 12973 |
| 013515 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:37pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593359.2 | 511050.8 | 28468 | 1.64041666667 | 13515 |
| 012994 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:38pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593356.3 | 511050.0 | 28470 | 1.64041666667 | 12994 |
| 013347 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:39pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593353.3 | 511048.4 | 28472 | 1.64041666667 | 13347 |
| 013792 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:40pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593351.0 | 511046.9 | 28474 | 1.64041666667 | 13792 |
| 012918 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:41pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593348.1 | 511046.6 | 28476 | 1.64041666667 | 12918 |
| 012944 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593345.5 | 511045.8 | 28478 | 1.64041666667 | 12944 |
| 012681 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:43pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593342.1 | 511045.4 | 28480 | 1.64041666667 | 12681 |
| 013575 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:44pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593339.6 | 511044.8 | 28482 | 1.64041666667 | 13575 |
| 014018 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:45pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593336.4 | 511043.1 | 28484 | 1.64041666667 | 14018 |
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:46pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593333.5 | 511042.0 | 28486 | 1.64041666667 | 13518 |
| 013626 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:47pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593330.4 | 511040.6 | 28488 | 1.64041666667 | 13626 |
| 013192 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:48pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593328.4 | 511039.0 | 28490 | 1.64041666667 | 13192 |
| 012730 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:49pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593325.5 | 511038.5 | 28492 | 1.64041666667 | 12730 |
| 012651 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:50pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593323.7 | 511037.2 | 28494 | 1.64041666667 | 12651 |
| 011893 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:51pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593321.3 | 511037.3 | 28496 | 1.64041666667 | 11893 |
| 011790 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:52pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593319.4 | 511038.7 | 28498 | 1.64041666667 | 11790 |
| 012159 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:53pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593317.5 | 511041.2 | 28500 | 1.64041666667 | 12159 |
| 011422 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:54pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593317.2 | 511042.9 | 28502 | 1.64041666667 | 11422 |
| 011562 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:55pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593318.0 | 511043.9 | 28504 | 1.64041666667 | 11562 |
| 011536 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:56pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593319.4 | 511044.8 | 28506 | 1.64041666667 | 11536 |
| 012211 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:57pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593322.3 | 511045.2 | 28508 | 1.64041666667 | 12211 |
| 012434 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:58pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593324.9 | 511046.6 | 28510 | 1.64041666667 | 12434 |
| 012619 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:59pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593327.9 | 511048.3 | 28512 | 1.64041666667 | 12619 |
| 012790 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:00pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593330.3 | 511049.1 | 28514 | 1.64041666667 | 12790 |
| 013269 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:01pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593333.4 | 511051.0 | 28516 | 1.64041666667 | 13269 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:02pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593335.6 | 511052.5 | 28518 | 1.64041666667 | 13861 |
| 013969 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:03pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593338.7 | 511054.2 | 28520 | 1.64041666667 | 13969 |
| 013618 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:04pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593341.2 | 511055.7 | 28522 | 1.64041666667 | 13618 |
| 013240 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:05pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593344.6 | 511057.3 | 28524 | 1.64041666667 | 13240 |
| 013192 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593346.9 | 511058.4 | 28526 | 1.64041666667 | 13192 |
| 013743 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:07pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593349.7 | 511059.8 | 28528 | 1.64041666667 | 13743 |
| 013565 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:08pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593352.4 | 511059.4 | 28530 | 1.64041666667 | 13565 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013930 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:09pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593356.2 | 511059.3 | 28532 | 1.64041666667 | 13930 |
| 012861 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:10pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593358.5 | 511059.8 | 28534 | 1.64041666667 | 12861 |
| 013496 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:11pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593362.0 | 511060.6 | 28536 | 1.64041666667 | 13496 |
| 013119 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593364.6 | 511062.3 | 28538 | 1.64041666667 | 13119 |
| 013777 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:13pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593367.5 | 511064.4 | 28540 | 1.64041666667 | 13777 |
| 014177 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:14pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593370.5 | 511065.7 | 28542 | 1.64041666667 | 14177 |
| 013757 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:15pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593373.6 | 511067.7 | 28544 | 1.64041666667 | 13757 |
| 013768 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:16pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593376.0 | 511069.7 | 28546 | 1.64041666667 | 13768 |
| 013954 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:17pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593379.2 | 511071.3 | 28548 | 1.64041666667 | 13954 |
| 013624 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:18pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593381.2 | 511073.1 | 28550 | 1.64041666667 | 13624 |
| 013918 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:19pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593383.6 | 511075.7 | 28552 | 1.64041666667 | 13918 |
| 013522 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:20pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593386.3 | 511077.4 | 28554 | 1.64041666667 | 13522 |
| 013883 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:21pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593389.1 | 511079.5 | 28556 | 1.64041666667 | 13883 |
| 014574 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:22pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593391.5 | 511080.9 | 28558 | 1.64041666667 | 14574 |
| 013770 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:23pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593394.8 | 511082.5 | 28560 | 1.64041666667 | 13770 |
| 013408 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:24pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593397.6 | 511083.4 | 28562 | 1.64041666667 | 13408 |
| 013767 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:25pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593400.8 | 511084.6 | 28564 | 1.64041666667 | 13767 |
| 013646 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593404.2 | 511085.3 | 28566 | 1.64041666667 | 13646 |
| 013593 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:27pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593407.8 | 511086.7 | 28568 | 1.64041666667 | 13593 |
| 013848 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593411.1 | 511088.7 | 28570 | 1.64041666667 | 13848 |
| 013610 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:29pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593414.6 | 511090.2 | 28572 | 1.64041666667 | 13610 |
| 013063 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:30pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593417.7 | 511091.3 | 28574 | 1.64041666667 | 13063 |
| 013393 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:31pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593421.1 | 511093.2 | 28576 | 1.64041666667 | 13393 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:32pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593423.9 | 511094.6 | 28578 | 1.64041666667 | 13526 |
| 013458 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:33pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593427.1 | 511095.9 | 28580 | 1.64041666667 | 13458 |
| 013368 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:34pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593429.1 | 511097.9 | 28582 | 1.64041666667 | 13368 |
| 013061 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:35pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593430.8 | 511099.6 | 28584 | 1.64041666667 | 13061 |
| 013519 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:36pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593430.6 | 511101.2 | 28586 | 1.64041666667 | 13519 |
| 012922 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:37pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593429.2 | 511102.8 | 28588 | 1.64041666667 | 12922 |
| 012691 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:38pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593427.9 | 511104.3 | 28590 | 1.64041666667 | 12691 |
| 012471 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:39pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593427.4 | 511104.8 | 28592 | 1.64041666667 | 12471 |
| 013577 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:40pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593427.1 | 511104.7 | 28594 | 1.64041666667 | 13577 |
| 013427 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:41pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593425.3 | 511103.9 | 28596 | 1.64041666667 | 13427 |
| 012937 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:42pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593422.6 | 511103.3 | 28598 | 1.64041666667 | 12937 |
| 012722 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:43pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593419.5 | 511102.3 | 28600 | 1.64041666667 | 12722 |
| 012999 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:44pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593416.9 | 511101.2 | 28602 | 1.64041666667 | 12999 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:45pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593414.4 | 511099.8 | 28604 | 1.64041666667 | 13094 |
| 012885 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593412.9 | 511097.6 | 28606 | 1.64041666667 | 12885 |
| 012813 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:47pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593409.7 | 511095.8 | 28608 | 1.64041666667 | 12813 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:48pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593406.7 | 511095.6 | 28610 | 1.64041666667 | 13050 |
| 014128 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:49pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593403.4 | 511095.1 | 28612 | 1.64041666667 | 14128 |
| 013737 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593400.9 | 511095.0 | 28614 | 1.64041666667 | 13737 |
| 013607 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:51pm | Sensor | 1797-S0028-636-G-DTE | 6809.2 | 1593397.5 | 511095.2 | 28616 | 1.64041666667 | 13607 |
| 014569 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:52pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593394.9 | 511093.7 | 28618 | 1.64041666667 | 14569 |
| 013985 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:53pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593392.0 | 511092.2 | 28620 | 1.64041666667 | 13985 |
| 013739 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:54pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593389.4 | 511091.4 | 28622 | 1.64041666667 | 13739 |
| 013008 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:55pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593387.1 | 511089.2 | 28624 | 1.64041666667 | 13008 |
| 013459 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593384.6 | 511087.4 | 28626 | 1.64041666667 | 13459 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013578 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:57pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593381.8 | 511085.2 | 28628 | 1.64041666667 | 13578 |
| 014350 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593379.8 | 511083.0 | 28630 | 1.64041666667 | 14350 |
| 014499 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:59pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593376.9 | 511081.6 | 28632 | 1.64041666667 | 14499 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:00pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593374.5 | 511080.9 | 28634 | 1.64041666667 | 13953 |
| 013908 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:01pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593371.3 | 511079.2 | 28636 | 1.64041666667 | 13908 |
| 013786 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:02pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593368.4 | 511078.1 | 28638 | 1.64041666667 | 13786 |
| 013687 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:03pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593364.9 | 511076.9 | 28640 | 1.64041666667 | 13687 |
| 013639 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:04pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593362.4 | 511075.4 | 28642 | 1.64041666667 | 13639 |
| 013807 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:05pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593359.1 | 511074.0 | 28644 | 1.64041666667 | 13807 |
| 013248 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593356.8 | 511072.7 | 28646 | 1.64041666667 | 13248 |
| 012882 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:07pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593354.5 | 511070.2 | 28648 | 1.64041666667 | 12882 |
| 012346 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:08pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593352.5 | 511068.4 | 28650 | 1.64041666667 | 12346 |
| 012517 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:09pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593350.0 | 511065.9 | 28652 | 1.64041666667 | 12517 |
| 013303 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:10pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593347.5 | 511063.7 | 28654 | 1.64041666667 | 13303 |
| 012838 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:11pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593344.2 | 511062.5 | 28656 | 1.64041666667 | 12838 |
| 012906 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:12pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593341.3 | 511061.0 | 28658 | 1.64041666667 | 12906 |
| 013252 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:13pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593338.3 | 511059.1 | 28660 | 1.64041666667 | 13252 |
| 013994 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:14pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593335.8 | 511057.8 | 28662 | 1.64041666667 | 13994 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:15pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593333.6 | 511055.2 | 28664 | 1.64041666667 | 13526 |
| 013893 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:16pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593331.7 | 511053.5 | 28666 | 1.64041666667 | 13893 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:17pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593329.3 | 511052.0 | 28668 | 1.64041666667 | 13560 |
| 013867 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:18pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593327.3 | 511050.4 | 28670 | 1.64041666667 | 13867 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:19pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593324.6 | 511049.5 | 28672 | 1.64041666667 | 14078 |
| 013724 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:20pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593322.6 | 511048.0 | 28674 | 1.64041666667 | 13724 |
| 013322 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:21pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593320.4 | 511048.7 | 28676 | 1.64041666667 | 13322 |
| 012983 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:22pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593318.0 | 511049.4 | 28678 | 1.64041666667 | 12983 |
| 012470 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:23pm | Sensor | 1797-S0028-636-G-DTE | 6807.4 | 1593315.6 | 511050.0 | 28680 | 1.64041666667 | 12470 |
| 012677 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:24pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593313.5 | 511050.8 | 28682 | 1.64041666667 | 12677 |
| 012328 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:25pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593312.0 | 511053.0 | 28684 | 1.64041666667 | 12328 |
| 012619 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:26pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593313.0 | 511054.5 | 28686 | 1.64041666667 | 12619 |
| 013023 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:27pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593314.0 | 511055.9 | 28688 | 1.64041666667 | 13023 |
| 012028 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:28pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593315.7 | 511056.8 | 28690 | 1.64041666667 | 12028 |
| 012510 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:29pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593318.1 | 511059.0 | 28692 | 1.64041666667 | 12510 |
| 012820 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:30pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593320.1 | 511060.6 | 28694 | 1.64041666667 | 12820 |
| 013781 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:31pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593323.1 | 511061.8 | 28696 | 1.64041666667 | 13781 |
| 014134 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:32pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593325.2 | 511062.9 | 28698 | 1.64041666667 | 14134 |
| 013688 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:33pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593328.6 | 511063.8 | 28700 | 1.64041666667 | 13688 |
| 013129 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:34pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593330.9 | 511064.7 | 28702 | 1.64041666667 | 13129 |
| 013775 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:35pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593334.0 | 511066.1 | 28704 | 1.64041666667 | 13775 |
| 013741 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:36pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593336.8 | 511066.4 | 28706 | 1.64041666667 | 13741 |
| 012806 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:37pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593339.9 | 511067.6 | 28708 | 1.64041666667 | 12806 |
| 012341 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:38pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593342.5 | 511068.4 | 28710 | 1.64041666667 | 12341 |
| 013219 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:39pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593345.8 | 511070.1 | 28712 | 1.64041666667 | 13219 |
| 012686 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:40pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593347.5 | 511072.0 | 28714 | 1.64041666667 | 12686 |
| 013098 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:41pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593350.3 | 511074.3 | 28716 | 1.64041666667 | 13098 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:42pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593352.4 | 511076.6 | 28718 | 1.64041666667 | 13038 |
| 013011 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:43pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593354.4 | 511079.4 | 28720 | 1.64041666667 | 13011 |
| 013679 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:44pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593356.9 | 511081.0 | 28722 | 1.64041666667 | 13679 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013702 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:45pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593360.1 | 511083.0 | 28724 | 1.64041666667 | 13702 |
| 013879 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:46pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593363.1 | 511084.6 | 28726 | 1.64041666667 | 13879 |
| 013980 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:47pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593366.6 | 511085.2 | 28728 | 1.64041666667 | 13980 |
| 014103 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:48pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593369.6 | 511086.3 | 28730 | 1.64041666667 | 14103 |
| 014353 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:49pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593372.5 | 511088.6 | 28732 | 1.64041666667 | 14353 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:50pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593375.1 | 511090.4 | 28734 | 1.64041666667 | 13953 |
| 013758 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:51pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593378.5 | 511092.8 | 28736 | 1.64041666667 | 13758 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:52pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593380.6 | 511094.7 | 28738 | 1.64041666667 | 13972 |
| 013056 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:53pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593383.8 | 511096.7 | 28740 | 1.64041666667 | 13056 |
| 012594 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:54pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593385.8 | 511098.2 | 28742 | 1.64041666667 | 12594 |
| 013031 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:55pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593387.5 | 511100.7 | 28744 | 1.64041666667 | 13031 |
| 012865 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593390.0 | 511102.9 | 28746 | 1.64041666667 | 12865 |
| 012622 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:57pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593393.3 | 511105.0 | 28748 | 1.64041666667 | 12622 |
| 014194 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:58pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593395.7 | 511107.2 | 28750 | 1.64041666667 | 14194 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:59pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593398.8 | 511109.0 | 28752 | 1.64041666667 | 14067 |
| 013260 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:00pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593401.7 | 511109.9 | 28754 | 1.64041666667 | 13260 |
| 013361 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:01pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593405.2 | 511111.5 | 28756 | 1.64041666667 | 13361 |
| 013343 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:02pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593407.9 | 511112.6 | 28758 | 1.64041666667 | 13343 |
| 013370 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:03pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593411.3 | 511113.8 | 28760 | 1.64041666667 | 13370 |
| 013303 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:04pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593413.7 | 511115.3 | 28762 | 1.64041666667 | 13303 |
| 013333 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:05pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593417.2 | 511116.6 | 28764 | 1.64041666667 | 13333 |
| 013852 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593418.9 | 511118.3 | 28766 | 1.64041666667 | 13852 |
| 013964 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:07pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593419.2 | 511120.8 | 28768 | 1.64041666667 | 13964 |
| 013967 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:08pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593417.6 | 511122.5 | 28770 | 1.64041666667 | 13967 |
| 014531 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:09pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593415.4 | 511121.7 | 28772 | 1.64041666667 | 14531 |
| 014226 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:10pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593412.7 | 511121.3 | 28774 | 1.64041666667 | 14226 |
| 014325 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:11pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593409.3 | 511120.2 | 28776 | 1.64041666667 | 14325 |
| 013930 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593406.4 | 511118.7 | 28778 | 1.64041666667 | 13930 |
| 013078 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:13pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593402.6 | 511117.6 | 28780 | 1.64041666667 | 13078 |
| 013559 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:14pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593399.7 | 511116.3 | 28782 | 1.64041666667 | 13559 |
| 013949 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:15pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593396.6 | 511114.6 | 28784 | 1.64041666667 | 13949 |
| 013014 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:16pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593393.8 | 511113.7 | 28786 | 1.64041666667 | 13014 |
| 012802 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:17pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593390.7 | 511112.0 | 28788 | 1.64041666667 | 12802 |
| 012736 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:18pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593388.0 | 511110.4 | 28790 | 1.64041666667 | 12736 |
| 012151 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:19pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593384.7 | 511108.8 | 28792 | 1.64041666667 | 12151 |
| 012565 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:20pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593382.1 | 511106.9 | 28794 | 1.64041666667 | 12565 |
| 012798 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:21pm | Sensor | 1797-S0028-636-G-DTE | 6808.5 | 1593378.6 | 511105.1 | 28796 | 1.64041666667 | 12798 |
| 013386 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:22pm | Sensor | 1797-S0028-636-G-DTE | 6808.6 | 1593375.8 | 511104.2 | 28798 | 1.64041666667 | 13386 |
| 013987 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:23pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593372.3 | 511102.6 | 28800 | 1.64041666667 | 13987 |
| 013357 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:24pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593369.4 | 511100.7 | 28802 | 1.64041666667 | 13357 |
| 013896 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:25pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593366.3 | 511099.4 | 28804 | 1.64041666667 | 13896 |
| 013441 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:26pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593363.3 | 511097.4 | 28806 | 1.64041666667 | 13441 |
| 014198 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:27pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593360.3 | 511094.8 | 28808 | 1.64041666667 | 14198 |
| 013034 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:28pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593357.6 | 511093.2 | 28810 | 1.64041666667 | 13034 |
| 013054 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:29pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593354.1 | 511091.0 | 28812 | 1.64041666667 | 13054 |
| 013365 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:30pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593351.7 | 511089.1 | 28814 | 1.64041666667 | 13365 |
| 014148 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:31pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593348.7 | 511087.3 | 28816 | 1.64041666667 | 14148 |
| 013568 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:32pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593346.1 | 511085.6 | 28818 | 1.64041666667 | 13568 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012582 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:33pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593343.0 | 511083.0 | 28820 | 1.64041666667 | 12582 |
| 012680 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:34pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593340.0 | 511081.1 | 28822 | 1.64041666667 | 12680 |
| 012367 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:35pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593335.9 | 511079.5 | 28824 | 1.64041666667 | 12367 |
| 013459 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:36pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593333.0 | 511077.9 | 28826 | 1.64041666667 | 13459 |
| 013045 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:37pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593329.7 | 511076.3 | 28828 | 1.64041666667 | 13045 |
| 013983 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:38pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593326.4 | 511075.6 | 28830 | 1.64041666667 | 13983 |
| 014143 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:39pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593323.2 | 511073.6 | 28832 | 1.64041666667 | 14143 |
| 013730 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:40pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593320.8 | 511072.0 | 28834 | 1.64041666667 | 13730 |
| 012635 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:41pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593317.6 | 511070.8 | 28836 | 1.64041666667 | 12635 |
| 012875 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:42pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593315.1 | 511069.5 | 28838 | 1.64041666667 | 12875 |
| 013249 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:43pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593312.0 | 511068.3 | 28840 | 1.64041666667 | 13249 |
| 012440 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:44pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593309.7 | 511068.0 | 28842 | 1.64041666667 | 12440 |
| 013117 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:45pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593306.2 | 511068.1 | 28844 | 1.64041666667 | 13117 |
| 013761 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:46pm | Sensor | 1797-S0028-636-G-DTE | 6807.8 | 1593305.2 | 511070.3 | 28846 | 1.64041666667 | 13761 |
| 013283 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:47pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593305.4 | 511073.6 | 28848 | 1.64041666667 | 13283 |
| 013726 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:48pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593306.1 | 511076.7 | 28850 | 1.64041666667 | 13726 |
| 013256 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:49pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593308.4 | 511079.1 | 28852 | 1.64041666667 | 13256 |
| 012999 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:50pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593310.7 | 511081.0 | 28854 | 1.64041666667 | 12999 |
| 013072 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:51pm | Sensor | 1797-S0028-636-G-DTE | 6807.5 | 1593313.8 | 511082.9 | 28856 | 1.64041666667 | 13072 |
| 013233 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:52pm | Sensor | 1797-S0028-636-G-DTE | 6807.6 | 1593316.6 | 511084.0 | 28858 | 1.64041666667 | 13233 |
| 013256 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:53pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593319.8 | 511085.9 | 28860 | 1.64041666667 | 13256 |
| 013209 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:54pm | Sensor | 1797-S0028-636-G-DTE | 6807.7 | 1593322.5 | 511087.0 | 28862 | 1.64041666667 | 13209 |
| 013370 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:55pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593325.7 | 511088.5 | 28864 | 1.64041666667 | 13370 |
| 013115 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:56pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593328.1 | 511089.9 | 28866 | 1.64041666667 | 13115 |
| 013790 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:57pm | Sensor | 1797-S0028-636-G-DTE | 6808.1 | 1593331.6 | 511091.0 | 28868 | 1.64041666667 | 13790 |
| 014649 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:58pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593334.6 | 511092.3 | 28870 | 1.64041666667 | 14649 |
| 015515 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:59pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593338.1 | 511093.7 | 28872 | 1.64041666667 | 15515 |
| 015334 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:00pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593340.9 | 511094.6 | 28874 | 1.64041666667 | 15334 |
| 014430 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:01pm | Sensor | 1797-S0028-636-G-DTE | 6807.9 | 1593344.2 | 511096.2 | 28876 | 1.64041666667 | 14430 |
| 014282 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:02pm | Sensor | 1797-S0028-636-G-DTE | 6808.0 | 1593347.0 | 511097.8 | 28878 | 1.64041666667 | 14282 |
| 013313 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:03pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593350.8 | 511098.7 | 28880 | 1.64041666667 | 13313 |
| 013594 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:04pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593353.5 | 511100.1 | 28882 | 1.64041666667 | 13594 |
| 013811 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:05pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593357.0 | 511102.5 | 28884 | 1.64041666667 | 13811 |
| 013454 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:06pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593359.2 | 511104.0 | 28886 | 1.64041666667 | 13454 |
| 013365 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:07pm | Sensor | 1797-S0028-636-G-DTE | 6808.3 | 1593361.9 | 511106.5 | 28888 | 1.64041666667 | 13365 |
| 012663 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:08pm | Sensor | 1797-S0028-636-G-DTE | 6808.2 | 1593364.6 | 511107.9 | 28890 | 1.64041666667 | 12663 |
| 012913 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:09pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593368.1 | 511109.1 | 28892 | 1.64041666667 | 12913 |
| 013383 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:10pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593370.5 | 511110.6 | 28894 | 1.64041666667 | 13383 |
| 013340 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:11pm | Sensor | 1797-S0028-636-G-DTE | 6808.4 | 1593373.7 | 511112.1 | 28896 | 1.64041666667 | 13340 |
| 012836 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:12pm | Sensor | 1797-S0028-636-G-DTE | 6808.7 | 1593376.8 | 511113.3 | 28898 | 1.64041666667 | 12836 |
| 012635 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:13pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593379.7 | 511114.8 | 28900 | 1.64041666667 | 12635 |
| 012522 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:14pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593382.5 | 511116.0 | 28902 | 1.64041666667 | 12522 |
| 013051 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:15pm | Sensor | 1797-S0028-636-G-DTE | 6808.8 | 1593385.5 | 511117.7 | 28904 | 1.64041666667 | 13051 |
| 013184 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:16pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593388.1 | 511119.4 | 28906 | 1.64041666667 | 13184 |
| 012861 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:17pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593391.3 | 511120.6 | 28908 | 1.64041666667 | 12861 |
| 012731 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:18pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593394.1 | 511121.8 | 28910 | 1.64041666667 | 12731 |
| 013124 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:19pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593397.2 | 511123.2 | 28912 | 1.64041666667 | 13124 |
| 013209 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:20pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593400.3 | 511124.0 | 28914 | 1.64041666667 | 13209 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:21pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593403.4 | 511125.7 | 28916 | 1.64041666667 | 13595 |
| 014059 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:22pm | Sensor | 1797-S0028-636-G-DTE | 6808.9 | 1593405.8 | 511126.8 | 28918 | 1.64041666667 | 14059 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:23pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593408.3 | 511127.4 | 28920 | 1.64041666667 | 13278 |
| 013454 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:24pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593409.0 | 511128.5 | 28922 | 1.64041666667 | 13454 |
| 013823 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:25pm | Sensor | 1797-S0028-636-G-DTE | 6809.1 | 1593410.3 | 511129.0 | 28924 | 1.64041666667 | 13823 |
| 013475 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:26pm | Sensor | 1797-S0028-636-G-DTE | 6809.0 | 1593410.5 | 511128.9 | 28926 | 1.64041666667 | 13475 |
| 008767 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:06am | Sensor | 1797-S0027-636-G-DTE | 6806.6 | 1593931.3 | 509915.2 | 25194 | 1.64041666667 | 8767 |
| 008636 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:07am | Sensor | 1797-S0027-636-G-DTE | 6807.2 | 1593931.0 | 509915.7 | 25196 | 1.64041666667 | 8636 |
| 008953 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:08am | Sensor | 1797-S0027-636-G-DTE | 6807.2 | 1593930.9 | 509915.7 | 25199 | 1.64041666667 | 8953 |
| 008658 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:09am | Sensor | 1797-S0027-636-G-DTE | 6795.8 | 1593932.4 | 509910.5 | 25201 | 1.64041666667 | 8658 |
| 008125 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:10am | Sensor | 1797-S0027-636-G-DTE | 6793.1 | 1593932.8 | 509908.7 | 25203 | 1.64041666667 | 8125 |
| 008020 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:11am | Sensor | 1797-S0027-636-G-DTE | 6793.1 | 1593932.8 | 509908.4 | 25205 | 1.64041666667 | 8020 |
| 008141 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:12am | Sensor | 1797-S0027-636-G-DTE | 6792.8 | 1593932.4 | 509909.4 | 25207 | 1.64041666667 | 8141 |
| 008419 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:13am | Sensor | 1797-S0027-636-G-DTE | 6793.3 | 1593932.9 | 509909.4 | 25209 | 1.64041666667 | 8419 |
| 008684 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:14am | Sensor | 1797-S0027-636-G-DTE | 6793.3 | 1593933.0 | 509909.4 | 25211 | 1.64041666667 | 8684 |
| 008199 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:15am | Sensor | 1797-S0027-636-G-DTE | 6793.4 | 1593933.4 | 509908.9 | 25213 | 1.64041666667 | 8199 |
| 009262 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:16am | Sensor | 1797-S0027-636-G-DTE | 6793.0 | 1593933.4 | 509908.7 | 25215 | 1.64041666667 | 9262 |
| 008840 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:17am | Sensor | 1797-S0027-636-G-DTE | 6792.6 | 1593933.0 | 509908.8 | 25217 | 1.64041666667 | 8840 |
| 008805 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:18am | Sensor | 1797-S0027-636-G-DTE | 6792.2 | 1593932.7 | 509908.9 | 25219 | 1.64041666667 | 8805 |
| 008747 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:19am | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593931.7 | 509915.3 | 25221 | 1.64041666667 | 8747 |
| 009263 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:20am | Sensor | 1797-S0027-636-G-DTE | 6807.3 | 1593931.6 | 509910.9 | 25223 | 1.64041666667 | 9263 |
| 009733 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:21am | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593933.9 | 509908.0 | 25226 | 1.64041666667 | 9733 |
| 009369 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:22am | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593933.8 | 509907.9 | 25229 | 1.64041666667 | 9369 |
| 009375 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:23am | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593934.6 | 509907.4 | 25231 | 1.64041666667 | 9375 |
| 009061 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:24am | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593932.3 | 509908.8 | 25233 | 1.64041666667 | 9061 |
| 009221 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:25am | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593931.6 | 509909.7 | 25235 | 1.64041666667 | 9221 |
| 009207 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:26am | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593931.7 | 509909.7 | 25237 | 1.64041666667 | 9207 |
| 009304 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:27am | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593931.2 | 509910.0 | 25239 | 1.64041666667 | 9304 |
| 010146 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:28am | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593930.2 | 509911.7 | 25241 | 1.64041666667 | 10146 |
| 009674 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:29am | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593929.1 | 509915.0 | 25243 | 1.64041666667 | 9674 |
| 009484 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:30am | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593928.9 | 509916.6 | 25245 | 1.64041666667 | 9484 |
| 011228 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:44pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.6 | 510468.3 | 25252 | 1.64041666667 | 11228 |
| 011048 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:45pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.5 | 510468.4 | 25254 | 1.64041666667 | 11048 |
| 011472 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:46pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.5 | 510468.4 | 25256 | 1.64041666667 | 11472 |
| 013083 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:47pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.5 | 510468.4 | 25258 | 1.64041666667 | 13083 |
| 011979 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:48pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.5 | 510468.3 | 25260 | 1.64041666667 | 11979 |
| 011980 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:49pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.5 | 510468.4 | 25262 | 1.64041666667 | 11980 |
| 011344 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:50pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593412.5 | 510468.5 | 25264 | 1.64041666667 | 11344 |
| 011908 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593412.4 | 510468.6 | 25266 | 1.64041666667 | 11908 |
| 011761 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:52pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593412.3 | 510468.7 | 25268 | 1.64041666667 | 11761 |
| 011843 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593412.3 | 510468.6 | 25270 | 1.64041666667 | 11843 |
| 011739 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:54pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593412.1 | 510468.6 | 25272 | 1.64041666667 | 11739 |
| 012130 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593411.2 | 510468.5 | 25274 | 1.64041666667 | 12130 |
| 011001 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:56pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593410.5 | 510468.5 | 25276 | 1.64041666667 | 11001 |
| 011858 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593410.8 | 510467.6 | 25278 | 1.64041666667 | 11858 |
| 011807 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:58pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593411.9 | 510465.2 | 25280 | 1.64041666667 | 11807 |
| 012296 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:59pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593413.7 | 510461.9 | 25282 | 1.64041666667 | 12296 |
| 012489 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:00pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593415.2 | 510458.8 | 25284 | 1.64041666667 | 12489 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012965 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:01pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593415.8 | 510454.7 | 25286 | 1.64041666667 | 12965 |
| 012828 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:02pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593415.5 | 510451.4 | 25288 | 1.64041666667 | 12828 |
| 012023 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:03pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593415.3 | 510449.6 | 25290 | 1.64041666667 | 12023 |
| 011480 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:04pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593415.3 | 510449.4 | 25292 | 1.64041666667 | 11480 |
| 011827 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:05pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593415.1 | 510449.4 | 25294 | 1.64041666667 | 11827 |
| 011670 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:06pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593415.1 | 510449.4 | 25296 | 1.64041666667 | 11670 |
| 011334 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:07pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593415.2 | 510449.4 | 25298 | 1.64041666667 | 11334 |
| 011453 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:08pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593415.3 | 510449.4 | 25300 | 1.64041666667 | 11453 |
| 012367 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:09pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593415.3 | 510449.3 | 25302 | 1.64041666667 | 12367 |
| 012469 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:10pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593415.4 | 510449.1 | 25304 | 1.64041666667 | 12469 |
| 012961 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593415.2 | 510447.8 | 25306 | 1.64041666667 | 12961 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:12pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593414.6 | 510445.3 | 25308 | 1.64041666667 | 13043 |
| 013359 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:13pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593415.1 | 510442.2 | 25310 | 1.64041666667 | 13359 |
| 013387 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:14pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593416.0 | 510439.1 | 25312 | 1.64041666667 | 13387 |
| 013305 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:15pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593417.1 | 510435.4 | 25314 | 1.64041666667 | 13305 |
| 012404 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:16pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593418.8 | 510432.3 | 25316 | 1.64041666667 | 12404 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:17pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593421.7 | 510429.0 | 25318 | 1.64041666667 | 13442 |
| 013351 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:18pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593424.0 | 510426.5 | 25320 | 1.64041666667 | 13351 |
| 013142 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593426.7 | 510422.6 | 25322 | 1.64041666667 | 13142 |
| 013055 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593428.8 | 510419.1 | 25324 | 1.64041666667 | 13055 |
| 013036 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593431.3 | 510415.4 | 25326 | 1.64041666667 | 13036 |
| 013032 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:22pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593433.3 | 510412.1 | 25328 | 1.64041666667 | 13032 |
| 013016 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593434.7 | 510407.9 | 25330 | 1.64041666667 | 13016 |
| 012459 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:24pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593435.7 | 510404.1 | 25332 | 1.64041666667 | 12459 |
| 013113 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593437.7 | 510400.1 | 25334 | 1.64041666667 | 13113 |
| 012423 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593439.6 | 510397.0 | 25336 | 1.64041666667 | 12423 |
| 012515 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:27pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593441.6 | 510392.8 | 25338 | 1.64041666667 | 12515 |
| 012702 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:28pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593442.9 | 510389.4 | 25340 | 1.64041666667 | 12702 |
| 012552 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593444.6 | 510385.4 | 25342 | 1.64041666667 | 12552 |
| 012633 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:30pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593445.8 | 510382.0 | 25344 | 1.64041666667 | 12633 |
| 012753 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593447.3 | 510378.0 | 25346 | 1.64041666667 | 12753 |
| 012934 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:32pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593448.8 | 510374.4 | 25348 | 1.64041666667 | 12934 |
| 012705 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:33pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593450.9 | 510371.4 | 25350 | 1.64041666667 | 12705 |
| 013154 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:34pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593452.2 | 510368.4 | 25352 | 1.64041666667 | 13154 |
| 012296 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:35pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593451.7 | 510365.0 | 25354 | 1.64041666667 | 12296 |
| 011619 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:36pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593449.0 | 510363.0 | 25356 | 1.64041666667 | 11619 |
| 012296 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593445.2 | 510361.1 | 25358 | 1.64041666667 | 12296 |
| 013771 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:38pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593441.9 | 510359.8 | 25360 | 1.64041666667 | 13771 |
| 012539 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593439.0 | 510359.2 | 25362 | 1.64041666667 | 12539 |
| 012168 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:40pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593438.0 | 510358.7 | 25364 | 1.64041666667 | 12168 |
| 012019 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593436.7 | 510357.1 | 25366 | 1.64041666667 | 12019 |
| 011861 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:42pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593433.9 | 510355.4 | 25368 | 1.64041666667 | 11861 |
| 012266 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593430.1 | 510354.0 | 25370 | 1.64041666667 | 12266 |
| 012015 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:44pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593427.0 | 510353.0 | 25372 | 1.64041666667 | 12015 |
| 012226 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:45pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593422.8 | 510351.1 | 25374 | 1.64041666667 | 12226 |
| 012532 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:46pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593419.7 | 510349.8 | 25376 | 1.64041666667 | 12532 |
| 013109 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:47pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593416.3 | 510349.0 | 25378 | 1.64041666667 | 13109 |
| 012444 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:48pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593413.7 | 510348.0 | 25380 | 1.64041666667 | 12444 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012954 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:49pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.3 | 510347.3 | 25382 | 1.64041666667 | 12954 |
| 012454 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:50pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.3 | 510347.6 | 25384 | 1.64041666667 | 12454 |
| 013290 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.0 | 510348.8 | 25386 | 1.64041666667 | 13290 |
| 013446 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:52pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.0 | 510350.2 | 25388 | 1.64041666667 | 13446 |
| 013338 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.3 | 510350.7 | 25390 | 1.64041666667 | 13338 |
| 013165 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:54pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.2 | 510350.6 | 25392 | 1.64041666667 | 13165 |
| 012753 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593412.2 | 510350.5 | 25394 | 1.64041666667 | 12753 |
| 012828 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:56pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593412.4 | 510349.8 | 25396 | 1.64041666667 | 12828 |
| 012226 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593412.4 | 510348.1 | 25398 | 1.64041666667 | 12226 |
| 012569 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:58pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593411.0 | 510347.1 | 25400 | 1.64041666667 | 12569 |
| 012500 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:59pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593408.1 | 510346.1 | 25402 | 1.64041666667 | 12500 |
| 012828 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:00pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593405.2 | 510344.3 | 25404 | 1.64041666667 | 12828 |
| 012158 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:01pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593402.0 | 510342.1 | 25406 | 1.64041666667 | 12158 |
| 013297 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:02pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593398.9 | 510340.8 | 25408 | 1.64041666667 | 13297 |
| 013112 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:03pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593395.9 | 510339.3 | 25410 | 1.64041666667 | 13112 |
| 012654 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:04pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593392.7 | 510337.3 | 25412 | 1.64041666667 | 12654 |
| 013176 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:05pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593389.5 | 510336.3 | 25414 | 1.64041666667 | 13176 |
| 014206 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:06pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593386.5 | 510335.5 | 25416 | 1.64041666667 | 14206 |
| 014463 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593383.4 | 510333.8 | 25418 | 1.64041666667 | 14463 |
| 013610 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:08pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593380.6 | 510332.7 | 25420 | 1.64041666667 | 13610 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:09pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593377.1 | 510331.8 | 25422 | 1.64041666667 | 13453 |
| 014145 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:10pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593374.6 | 510330.9 | 25424 | 1.64041666667 | 14145 |
| 013064 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:11pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593373.0 | 510330.6 | 25426 | 1.64041666667 | 13064 |
| 013123 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:12pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.8 | 510330.8 | 25428 | 1.64041666667 | 13123 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:13pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.7 | 510330.7 | 25430 | 1.64041666667 | 13442 |
| 012563 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:14pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.7 | 510330.7 | 25432 | 1.64041666667 | 12563 |
| 012332 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:15pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.8 | 510330.7 | 25434 | 1.64041666667 | 12332 |
| 012794 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:16pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.8 | 510330.7 | 25436 | 1.64041666667 | 12794 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:17pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.7 | 510330.7 | 25438 | 1.64041666667 | 13436 |
| 013183 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:18pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.7 | 510330.6 | 25440 | 1.64041666667 | 13183 |
| 013205 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.7 | 510330.7 | 25442 | 1.64041666667 | 13205 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.7 | 510330.7 | 25444 | 1.64041666667 | 13278 |
| 012486 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593372.7 | 510330.6 | 25446 | 1.64041666667 | 12486 |
| 013571 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:22pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593372.6 | 510330.6 | 25448 | 1.64041666667 | 13571 |
| 012726 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593372.1 | 510330.6 | 25450 | 1.64041666667 | 12726 |
| 012663 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:24pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593371.7 | 510330.5 | 25452 | 1.64041666667 | 12663 |
| 013228 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.7 | 510330.5 | 25454 | 1.64041666667 | 13228 |
| 012953 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.7 | 510330.4 | 25456 | 1.64041666667 | 12953 |
| 013758 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:27pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.6 | 510330.4 | 25458 | 1.64041666667 | 13758 |
| 013357 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:28pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.5 | 510330.4 | 25460 | 1.64041666667 | 13357 |
| 013580 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.5 | 510330.5 | 25462 | 1.64041666667 | 13580 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:30pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.6 | 510330.5 | 25464 | 1.64041666667 | 13436 |
| 012710 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.6 | 510330.5 | 25466 | 1.64041666667 | 12710 |
| 012714 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:32pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.6 | 510330.5 | 25468 | 1.64041666667 | 12714 |
| 013384 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:33pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.5 | 510330.4 | 25470 | 1.64041666667 | 13384 |
| 012793 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:34pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593371.6 | 510330.4 | 25472 | 1.64041666667 | 12793 |
| 013226 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:35pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593371.9 | 510330.2 | 25474 | 1.64041666667 | 13226 |
| 013695 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:36pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593371.8 | 510329.9 | 25476 | 1.64041666667 | 13695 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013478 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593369.8 | 510328.9 | 25478 | 1.64041666667 | 13478 |
| 013964 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:38pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593367.2 | 510326.5 | 25480 | 1.64041666667 | 13964 |
| 013329 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593363.8 | 510324.6 | 25482 | 1.64041666667 | 13329 |
| 013310 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:40pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593360.5 | 510323.7 | 25484 | 1.64041666667 | 13310 |
| 013487 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593357.3 | 510322.1 | 25486 | 1.64041666667 | 13487 |
| 013189 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:42pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593355.3 | 510320.8 | 25488 | 1.64041666667 | 13189 |
| 013276 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593353.1 | 510321.1 | 25490 | 1.64041666667 | 13276 |
| 013445 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:44pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593350.8 | 510322.7 | 25492 | 1.64041666667 | 13445 |
| 013113 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:45pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593348.5 | 510325.1 | 25494 | 1.64041666667 | 13113 |
| 012956 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:46pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593347.1 | 510328.3 | 25496 | 1.64041666667 | 12956 |
| 013445 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593345.6 | 510332.0 | 25498 | 1.64041666667 | 13445 |
| 013120 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:48pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593343.8 | 510335.4 | 25500 | 1.64041666667 | 13120 |
| 013140 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593341.9 | 510338.7 | 25502 | 1.64041666667 | 13140 |
| 012558 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:50pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593340.6 | 510342.1 | 25504 | 1.64041666667 | 12558 |
| 012839 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593339.2 | 510345.3 | 25506 | 1.64041666667 | 12839 |
| 012997 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593337.1 | 510348.2 | 25508 | 1.64041666667 | 12997 |
| 011773 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593335.5 | 510351.4 | 25510 | 1.64041666667 | 11773 |
| 012277 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:54pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593334.2 | 510354.2 | 25512 | 1.64041666667 | 12277 |
| 012748 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:55pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593332.2 | 510357.5 | 25514 | 1.64041666667 | 12748 |
| 012631 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:56pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593331.0 | 510360.8 | 25516 | 1.64041666667 | 12631 |
| 011935 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:57pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593330.3 | 510364.8 | 25518 | 1.64041666667 | 11935 |
| 011678 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:58pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593329.5 | 510367.8 | 25520 | 1.64041666667 | 11678 |
| 011684 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:59pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593328.0 | 510371.7 | 25522 | 1.64041666667 | 11684 |
| 011844 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:00pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593327.4 | 510374.7 | 25524 | 1.64041666667 | 11844 |
| 012280 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593326.9 | 510378.5 | 25526 | 1.64041666667 | 12280 |
| 012435 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:02pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593325.9 | 510381.7 | 25528 | 1.64041666667 | 12435 |
| 013467 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:03pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593324.4 | 510385.5 | 25530 | 1.64041666667 | 13467 |
| 012885 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:04pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593323.1 | 510389.1 | 25532 | 1.64041666667 | 12885 |
| 012363 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:05pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593321.5 | 510392.4 | 25534 | 1.64041666667 | 12363 |
| 012121 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:06pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593319.8 | 510395.7 | 25536 | 1.64041666667 | 12121 |
| 013275 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:07pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593318.4 | 510399.0 | 25538 | 1.64041666667 | 13275 |
| 012725 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:08pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593316.9 | 510401.4 | 25540 | 1.64041666667 | 12725 |
| 012168 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:09pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593314.5 | 510404.0 | 25542 | 1.64041666667 | 12168 |
| 011569 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:10pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593313.0 | 510406.5 | 25544 | 1.64041666667 | 11569 |
| 011645 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593311.8 | 510409.7 | 25546 | 1.64041666667 | 11645 |
| 012303 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:12pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593310.3 | 510412.4 | 25548 | 1.64041666667 | 12303 |
| 012200 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:13pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593308.3 | 510415.3 | 25550 | 1.64041666667 | 12200 |
| 011895 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:14pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593307.3 | 510419.2 | 25552 | 1.64041666667 | 11895 |
| 012391 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:15pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593307.0 | 510421.9 | 25554 | 1.64041666667 | 12391 |
| 012542 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:16pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593307.2 | 510424.4 | 25556 | 1.64041666667 | 12542 |
| 011997 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:17pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593308.5 | 510426.9 | 25558 | 1.64041666667 | 11997 |
| 012088 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:18pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593309.9 | 510427.8 | 25560 | 1.64041666667 | 12088 |
| 012417 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:19pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593311.5 | 510429.7 | 25562 | 1.64041666667 | 12417 |
| 012632 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:20pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593313.8 | 510431.0 | 25564 | 1.64041666667 | 12632 |
| 012453 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:21pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593316.3 | 510432.5 | 25566 | 1.64041666667 | 12453 |
| 012420 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:22pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593318.1 | 510434.1 | 25568 | 1.64041666667 | 12420 |
| 011861 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:23pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593320.6 | 510434.7 | 25570 | 1.64041666667 | 11861 |
| 011906 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:24pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593321.9 | 510435.0 | 25572 | 1.64041666667 | 11906 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011790 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:25pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593322.4 | 510434.8 | 25574 | 1.64041666667 | 11790 |
| 012122 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:26pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593322.1 | 510434.4 | 25576 | 1.64041666667 | 12122 |
| 011311 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593322.7 | 510434.2 | 25578 | 1.64041666667 | 11311 |
| 011680 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:28pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593323.1 | 510433.4 | 25580 | 1.64041666667 | 11680 |
| 013117 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:29pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593323.1 | 510430.5 | 25582 | 1.64041666667 | 13117 |
| 012493 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:30pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593324.0 | 510428.6 | 25584 | 1.64041666667 | 12493 |
| 013230 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:31pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593326.9 | 510426.7 | 25586 | 1.64041666667 | 13230 |
| 012594 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:32pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593329.1 | 510424.9 | 25588 | 1.64041666667 | 12594 |
| 012754 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593331.6 | 510422.7 | 25590 | 1.64041666667 | 12754 |
| 012956 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593333.8 | 510421.4 | 25592 | 1.64041666667 | 12956 |
| 013108 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593336.3 | 510419.9 | 25594 | 1.64041666667 | 13108 |
| 012361 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593338.7 | 510419.5 | 25596 | 1.64041666667 | 12361 |
| 012090 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593340.7 | 510419.7 | 25598 | 1.64041666667 | 12090 |
| 012178 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:38pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593341.4 | 510419.8 | 25600 | 1.64041666667 | 12178 |
| 011928 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593340.8 | 510421.0 | 25602 | 1.64041666667 | 11928 |
| 012266 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:40pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593340.7 | 510421.1 | 25604 | 1.64041666667 | 12266 |
| 011797 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593340.7 | 510421.1 | 25606 | 1.64041666667 | 11797 |
| 012898 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:42pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593340.7 | 510421.1 | 25608 | 1.64041666667 | 12898 |
| 013023 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593340.8 | 510421.1 | 25610 | 1.64041666667 | 13023 |
| 013070 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:44pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593341.4 | 510421.3 | 25612 | 1.64041666667 | 13070 |
| 013067 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:45pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593342.6 | 510422.5 | 25614 | 1.64041666667 | 13067 |
| 012345 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:46pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593343.3 | 510423.8 | 25616 | 1.64041666667 | 12345 |
| 011714 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593345.2 | 510425.4 | 25618 | 1.64041666667 | 11714 |
| 012184 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:48pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593347.3 | 510428.6 | 25620 | 1.64041666667 | 12184 |
| 012388 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593349.8 | 510431.4 | 25622 | 1.64041666667 | 12388 |
| 012181 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:50pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593352.4 | 510433.6 | 25624 | 1.64041666667 | 12181 |
| 011599 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593354.2 | 510436.9 | 25626 | 1.64041666667 | 11599 |
| 012284 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593355.8 | 510439.7 | 25628 | 1.64041666667 | 12284 |
| 012655 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593358.8 | 510441.8 | 25630 | 1.64041666667 | 12655 |
| 012863 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:54pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593361.4 | 510443.9 | 25632 | 1.64041666667 | 12863 |
| 012425 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:55pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593364.3 | 510446.3 | 25634 | 1.64041666667 | 12425 |
| 012082 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:56pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593367.1 | 510447.9 | 25636 | 1.64041666667 | 12082 |
| 012818 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593370.1 | 510450.5 | 25638 | 1.64041666667 | 12818 |
| 012595 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:58pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593372.3 | 510452.8 | 25640 | 1.64041666667 | 12595 |
| 012342 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593375.7 | 510454.7 | 25642 | 1.64041666667 | 12342 |
| 012477 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:00pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593378.5 | 510456.4 | 25644 | 1.64041666667 | 12477 |
| 012996 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.5 | 510458.9 | 25646 | 1.64041666667 | 12996 |
| 012485 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:02pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593384.0 | 510460.4 | 25648 | 1.64041666667 | 12485 |
| 012910 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:03pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593387.1 | 510462.2 | 25650 | 1.64041666667 | 12910 |
| 013479 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:04pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593389.4 | 510464.3 | 25652 | 1.64041666667 | 13479 |
| 011910 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:05pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593392.1 | 510465.9 | 25654 | 1.64041666667 | 11910 |
| 012129 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:06pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593394.4 | 510467.4 | 25656 | 1.64041666667 | 12129 |
| 011967 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593396.8 | 510468.8 | 25658 | 1.64041666667 | 11967 |
| 011186 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:08pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593399.7 | 510469.3 | 25660 | 1.64041666667 | 11186 |
| 010822 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:09pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593402.4 | 510470.1 | 25662 | 1.64041666667 | 10822 |
| 011120 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:10pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593404.0 | 510470.7 | 25664 | 1.64041666667 | 11120 |
| 011437 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:11pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593404.2 | 510470.5 | 25666 | 1.64041666667 | 11437 |
| 011743 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:12pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593404.3 | 510470.3 | 25668 | 1.64041666667 | 11743 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011856 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:13pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593404.8 | 510469.6 | 25670 | 1.64041666667 | 11856 |
| 011281 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:14pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.3 | 510469.1 | 25672 | 1.64041666667 | 11281 |
| 011220 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:15pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593405.2 | 510469.1 | 25674 | 1.64041666667 | 11220 |
| 011854 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:16pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593405.3 | 510469.1 | 25676 | 1.64041666667 | 11854 |
| 011190 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:17pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593405.3 | 510469.1 | 25678 | 1.64041666667 | 11190 |
| 010892 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:18pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593405.3 | 510469.2 | 25680 | 1.64041666667 | 10892 |
| 010634 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.4 | 510469.1 | 25682 | 1.64041666667 | 10634 |
| 010849 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.4 | 510469.1 | 25684 | 1.64041666667 | 10849 |
| 010722 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.4 | 510469.1 | 25686 | 1.64041666667 | 10722 |
| 010884 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:22pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.4 | 510469.1 | 25688 | 1.64041666667 | 10884 |
| 011087 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.1 | 25690 | 1.64041666667 | 11087 |
| 010661 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:24pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.1 | 25692 | 1.64041666667 | 10661 |
| 011442 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.2 | 25694 | 1.64041666667 | 11442 |
| 011003 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.6 | 510469.2 | 25696 | 1.64041666667 | 11003 |
| 010802 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:27pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593405.5 | 510469.2 | 25698 | 1.64041666667 | 10802 |
| 011333 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:28pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.2 | 25700 | 1.64041666667 | 11333 |
| 011415 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.5 | 510469.1 | 25702 | 1.64041666667 | 11415 |
| 011176 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:30pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.2 | 25704 | 1.64041666667 | 11176 |
| 010899 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.2 | 25706 | 1.64041666667 | 10899 |
| 010900 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:32pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.5 | 510469.2 | 25708 | 1.64041666667 | 10900 |
| 012394 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:33pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.5 | 510469.2 | 25710 | 1.64041666667 | 12394 |
| 011764 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:34pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.5 | 510469.2 | 25712 | 1.64041666667 | 11764 |
| 011979 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:35pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.2 | 25714 | 1.64041666667 | 11979 |
| 011928 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:36pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.2 | 25716 | 1.64041666667 | 11928 |
| 011689 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.4 | 510469.2 | 25718 | 1.64041666667 | 11689 |
| 011608 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:38pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.4 | 510469.2 | 25720 | 1.64041666667 | 11608 |
| 011561 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.4 | 510469.2 | 25722 | 1.64041666667 | 11561 |
| 011596 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:40pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.4 | 510469.2 | 25724 | 1.64041666667 | 11596 |
| 012072 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.5 | 510469.1 | 25726 | 1.64041666667 | 12072 |
| 012206 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:42pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.6 | 510469.2 | 25728 | 1.64041666667 | 12206 |
| 011853 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.7 | 510469.2 | 25730 | 1.64041666667 | 11853 |
| 011460 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:44pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.6 | 510469.2 | 25732 | 1.64041666667 | 11460 |
| 011868 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:45pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.6 | 510469.2 | 25734 | 1.64041666667 | 11868 |
| 011663 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:46pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.6 | 510469.3 | 25736 | 1.64041666667 | 11663 |
| 011143 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:47pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.5 | 510469.3 | 25738 | 1.64041666667 | 11143 |
| 010753 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:48pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593405.7 | 510469.3 | 25740 | 1.64041666667 | 10753 |
| 010938 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:49pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593406.2 | 510468.9 | 25742 | 1.64041666667 | 10938 |
| 011020 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:50pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593406.8 | 510467.4 | 25744 | 1.64041666667 | 11020 |
| 011381 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593407.8 | 510464.8 | 25746 | 1.64041666667 | 11381 |
| 011404 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:52pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593408.1 | 510462.5 | 25748 | 1.64041666667 | 11404 |
| 012295 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593409.1 | 510460.9 | 25750 | 1.64041666667 | 12295 |
| 011558 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:54pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593409.5 | 510460.3 | 25752 | 1.64041666667 | 11558 |
| 011699 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593408.8 | 510461.7 | 25754 | 1.64041666667 | 11699 |
| 011448 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:56pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593408.2 | 510463.4 | 25756 | 1.64041666667 | 11448 |
| 011254 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593408.1 | 510465.8 | 25758 | 1.64041666667 | 11254 |
| 012135 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:58pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593407.9 | 510467.6 | 25760 | 1.64041666667 | 12135 |
| 011453 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:59pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593408.1 | 510468.2 | 25762 | 1.64041666667 | 11453 |
| 011520 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:00pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593406.9 | 510467.0 | 25764 | 1.64041666667 | 11520 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011677 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:01pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593404.8 | 510465.3 | 25766 | 1.64041666667 | 11677 |
| 011038 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:02pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593402.3 | 510463.6 | 25768 | 1.64041666667 | 11038 |
| 010904 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:03pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593399.7 | 510461.4 | 25770 | 1.64041666667 | 10904 |
| 011271 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:04pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593397.5 | 510459.9 | 25772 | 1.64041666667 | 11271 |
| 011432 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:05pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593394.6 | 510458.5 | 25774 | 1.64041666667 | 11432 |
| 011411 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:06pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593392.5 | 510456.6 | 25776 | 1.64041666667 | 11411 |
| 011503 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:07pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593389.5 | 510454.8 | 25778 | 1.64041666667 | 11503 |
| 011488 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:08pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593387.1 | 510453.2 | 25780 | 1.64041666667 | 11488 |
| 011967 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:09pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593384.5 | 510451.4 | 25782 | 1.64041666667 | 11967 |
| 012041 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:10pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510450.7 | 25784 | 1.64041666667 | 12041 |
| 011940 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593378.8 | 510449.2 | 25786 | 1.64041666667 | 11940 |
| 011959 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:12pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593376.8 | 510447.5 | 25788 | 1.64041666667 | 11959 |
| 011812 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:13pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593374.0 | 510446.6 | 25790 | 1.64041666667 | 11812 |
| 012592 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:14pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593371.6 | 510445.0 | 25792 | 1.64041666667 | 12592 |
| 012348 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:15pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593368.3 | 510444.1 | 25794 | 1.64041666667 | 12348 |
| 012435 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:16pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593365.8 | 510442.4 | 25796 | 1.64041666667 | 12435 |
| 011915 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:17pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593363.7 | 510440.5 | 25798 | 1.64041666667 | 11915 |
| 012364 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:18pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593361.2 | 510439.7 | 25800 | 1.64041666667 | 12364 |
| 012355 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:19pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593359.3 | 510437.8 | 25802 | 1.64041666667 | 12355 |
| 012656 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:20pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593357.5 | 510435.7 | 25804 | 1.64041666667 | 12656 |
| 012110 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:21pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593355.9 | 510433.0 | 25806 | 1.64041666667 | 12110 |
| 011934 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:22pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593354.6 | 510430.2 | 25808 | 1.64041666667 | 11934 |
| 011670 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:23pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593352.4 | 510428.0 | 25810 | 1.64041666667 | 11670 |
| 012257 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:24pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593350.2 | 510425.4 | 25812 | 1.64041666667 | 12257 |
| 011949 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:25pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593348.0 | 510422.8 | 25814 | 1.64041666667 | 11949 |
| 012226 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:26pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593345.4 | 510420.9 | 25816 | 1.64041666667 | 12226 |
| 012120 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593343.3 | 510418.8 | 25818 | 1.64041666667 | 12120 |
| 011317 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:28pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593341.3 | 510417.2 | 25820 | 1.64041666667 | 11317 |
| 012538 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:29pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593338.8 | 510415.7 | 25822 | 1.64041666667 | 12538 |
| 012055 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:30pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593337.0 | 510413.2 | 25824 | 1.64041666667 | 12055 |
| 011858 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:31pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593334.6 | 510410.8 | 25826 | 1.64041666667 | 11858 |
| 012423 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:32pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593332.7 | 510409.2 | 25828 | 1.64041666667 | 12423 |
| 011833 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593330.5 | 510408.0 | 25830 | 1.64041666667 | 11833 |
| 011838 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593328.2 | 510408.8 | 25832 | 1.64041666667 | 11838 |
| 011849 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593326.2 | 510410.1 | 25834 | 1.64041666667 | 11849 |
| 011780 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593324.3 | 510411.5 | 25836 | 1.64041666667 | 11780 |
| 011313 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593322.0 | 510413.6 | 25838 | 1.64041666667 | 11313 |
| 011246 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:38pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593319.3 | 510415.6 | 25840 | 1.64041666667 | 11246 |
| 011456 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593317.2 | 510418.1 | 25842 | 1.64041666667 | 11456 |
| 011326 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:40pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593316.2 | 510420.9 | 25844 | 1.64041666667 | 11326 |
| 011741 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593316.1 | 510424.4 | 25846 | 1.64041666667 | 11741 |
| 012191 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:42pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593317.7 | 510426.2 | 25848 | 1.64041666667 | 12191 |
| 011673 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593320.8 | 510425.8 | 25850 | 1.64041666667 | 11673 |
| 011891 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:44pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593324.1 | 510424.3 | 25852 | 1.64041666667 | 11891 |
| 012133 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:45pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593326.9 | 510421.5 | 25854 | 1.64041666667 | 12133 |
| 012135 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:46pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593329.1 | 510419.4 | 25856 | 1.64041666667 | 12135 |
| 012496 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593330.7 | 510418.0 | 25858 | 1.64041666667 | 12496 |
| 011889 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:48pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593331.8 | 510415.7 | 25860 | 1.64041666667 | 11889 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012477 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593334.3 | 510413.5 | 25862 | 1.64041666667 | 12477 |
| 012418 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:50pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593335.5 | 510412.3 | 25864 | 1.64041666667 | 12418 |
| 012160 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593335.2 | 510411.9 | 25866 | 1.64041666667 | 12160 |
| 012217 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593334.4 | 510410.8 | 25868 | 1.64041666667 | 12217 |
| 011920 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593333.5 | 510407.8 | 25870 | 1.64041666667 | 11920 |
| 012375 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:54pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593332.9 | 510405.0 | 25872 | 1.64041666667 | 12375 |
| 012698 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:55pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593331.1 | 510402.6 | 25874 | 1.64041666667 | 12698 |
| 012228 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:56pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593330.1 | 510402.2 | 25876 | 1.64041666667 | 12228 |
| 012375 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593330.2 | 510401.2 | 25878 | 1.64041666667 | 12375 |
| 013036 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:58pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593328.9 | 510399.5 | 25880 | 1.64041666667 | 13036 |
| 013228 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:59pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593327.2 | 510397.3 | 25882 | 1.64041666667 | 13228 |
| 012915 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:00pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593324.9 | 510395.8 | 25884 | 1.64041666667 | 12915 |
| 012732 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593322.4 | 510394.8 | 25886 | 1.64041666667 | 12732 |
| 012667 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:02pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593321.4 | 510393.5 | 25888 | 1.64041666667 | 12667 |
| 012420 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:03pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593321.4 | 510394.0 | 25890 | 1.64041666667 | 12420 |
| 012363 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:04pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593321.1 | 510394.0 | 25892 | 1.64041666667 | 12363 |
| 012047 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:05pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593321.1 | 510393.9 | 25894 | 1.64041666667 | 12047 |
| 012319 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:06pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593320.5 | 510393.1 | 25896 | 1.64041666667 | 12319 |
| 011362 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:07pm | Sensor | 1797-S0027-636-G-DTE | 6802.6 | 1593319.0 | 510392.0 | 25898 | 1.64041666667 | 11362 |
| 011686 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:08pm | Sensor | 1797-S0027-636-G-DTE | 6802.5 | 1593318.0 | 510390.8 | 25900 | 1.64041666667 | 11686 |
| 011651 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:09pm | Sensor | 1797-S0027-636-G-DTE | 6802.5 | 1593317.3 | 510389.8 | 25902 | 1.64041666667 | 11651 |
| 011233 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:10pm | Sensor | 1797-S0027-636-G-DTE | 6802.5 | 1593316.9 | 510388.7 | 25904 | 1.64041666667 | 11233 |
| 011201 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:11pm | Sensor | 1797-S0027-636-G-DTE | 6802.5 | 1593316.7 | 510387.9 | 25906 | 1.64041666667 | 11201 |
| 011618 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:12pm | Sensor | 1797-S0027-636-G-DTE | 6802.5 | 1593316.7 | 510386.8 | 25908 | 1.64041666667 | 11618 |
| 012925 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:13pm | Sensor | 1797-S0027-636-G-DTE | 6802.5 | 1593316.4 | 510386.5 | 25910 | 1.64041666667 | 12925 |
| 012678 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:14pm | Sensor | 1797-S0027-636-G-DTE | 6802.5 | 1593316.6 | 510387.0 | 25912 | 1.64041666667 | 12678 |
| 011991 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:15pm | Sensor | 1797-S0027-636-G-DTE | 6802.6 | 1593318.3 | 510388.3 | 25914 | 1.64041666667 | 11991 |
| 012602 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:16pm | Sensor | 1797-S0027-636-G-DTE | 6802.6 | 1593320.2 | 510390.7 | 25916 | 1.64041666667 | 12602 |
| 012676 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:17pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593322.3 | 510392.7 | 25918 | 1.64041666667 | 12676 |
| 011998 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:18pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593324.9 | 510393.7 | 25920 | 1.64041666667 | 11998 |
| 012816 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:19pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593327.2 | 510394.9 | 25922 | 1.64041666667 | 12816 |
| 012564 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:20pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593329.6 | 510395.7 | 25924 | 1.64041666667 | 12564 |
| 012894 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:21pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593332.0 | 510396.9 | 25926 | 1.64041666667 | 12894 |
| 012045 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:22pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593334.0 | 510398.8 | 25928 | 1.64041666667 | 12045 |
| 012130 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:23pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593336.6 | 510400.1 | 25930 | 1.64041666667 | 12130 |
| 012336 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:24pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593338.5 | 510402.3 | 25932 | 1.64041666667 | 12336 |
| 011701 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:25pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593340.2 | 510404.4 | 25934 | 1.64041666667 | 11701 |
| 011697 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:26pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593342.0 | 510407.0 | 25936 | 1.64041666667 | 11697 |
| 011627 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593343.1 | 510410.2 | 25938 | 1.64041666667 | 11627 |
| 012045 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:28pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593344.8 | 510412.9 | 25940 | 1.64041666667 | 12045 |
| 011853 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:29pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593347.0 | 510415.0 | 25942 | 1.64041666667 | 11853 |
| 011820 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:30pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593349.1 | 510417.3 | 25944 | 1.64041666667 | 11820 |
| 011696 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:31pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593351.6 | 510419.5 | 25946 | 1.64041666667 | 11696 |
| 011836 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:32pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593354.4 | 510421.5 | 25948 | 1.64041666667 | 11836 |
| 011690 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593356.7 | 510424.0 | 25950 | 1.64041666667 | 11690 |
| 011856 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593358.5 | 510425.9 | 25952 | 1.64041666667 | 11856 |
| 011739 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593361.8 | 510427.5 | 25954 | 1.64041666667 | 11739 |
| 011620 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593364.4 | 510428.8 | 25956 | 1.64041666667 | 11620 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012221 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593367.1 | 510431.3 | 25958 | 1.64041666667 | 12221 |
| 012552 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:38pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593370.0 | 510432.9 | 25960 | 1.64041666667 | 12552 |
| 012363 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593373.3 | 510434.5 | 25962 | 1.64041666667 | 12363 |
| 012331 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:40pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593376.4 | 510436.9 | 25964 | 1.64041666667 | 12331 |
| 011189 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593379.2 | 510438.8 | 25966 | 1.64041666667 | 11189 |
| 012256 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:42pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593382.2 | 510440.5 | 25968 | 1.64041666667 | 12256 |
| 012256 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593384.7 | 510442.8 | 25970 | 1.64041666667 | 12256 |
| 011784 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:44pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593387.1 | 510444.9 | 25972 | 1.64041666667 | 11784 |
| 011001 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:45pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593390.1 | 510446.3 | 25974 | 1.64041666667 | 11001 |
| 010770 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:46pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593392.8 | 510448.1 | 25976 | 1.64041666667 | 10770 |
| 011938 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593396.0 | 510449.9 | 25978 | 1.64041666667 | 11938 |
| 011665 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:48pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593398.9 | 510451.1 | 25980 | 1.64041666667 | 11665 |
| 011189 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593401.4 | 510452.8 | 25982 | 1.64041666667 | 11189 |
| 011806 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:50pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593403.9 | 510454.4 | 25984 | 1.64041666667 | 11806 |
| 011703 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593406.6 | 510455.6 | 25986 | 1.64041666667 | 11703 |
| 011960 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593409.1 | 510457.0 | 25988 | 1.64041666667 | 11960 |
| 012263 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593411.6 | 510457.7 | 25990 | 1.64041666667 | 12263 |
| 012200 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:54pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593414.2 | 510457.3 | 25992 | 1.64041666667 | 12200 |
| 012435 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593417.1 | 510456.5 | 25994 | 1.64041666667 | 12435 |
| 012822 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:56pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593418.8 | 510454.2 | 25996 | 1.64041666667 | 12822 |
| 012657 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593419.6 | 510452.2 | 25998 | 1.64041666667 | 12657 |
| 013112 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:58pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593420.1 | 510450.4 | 26000 | 1.64041666667 | 13112 |
| 012850 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:59pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593419.9 | 510450.5 | 26002 | 1.64041666667 | 12850 |
| 012463 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:00pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593419.5 | 510450.7 | 26004 | 1.64041666667 | 12463 |
| 012658 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:01pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593418.9 | 510450.1 | 26006 | 1.64041666667 | 12658 |
| 012032 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:02pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593418.9 | 510449.9 | 26008 | 1.64041666667 | 12032 |
| 011868 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:03pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593419.0 | 510450.1 | 26010 | 1.64041666667 | 11868 |
| 011566 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:04pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593419.1 | 510450.1 | 26012 | 1.64041666667 | 11566 |
| 011568 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:05pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593419.0 | 510450.1 | 26014 | 1.64041666667 | 11568 |
| 012447 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:06pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593418.8 | 510450.1 | 26016 | 1.64041666667 | 12447 |
| 011936 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593418.1 | 510449.8 | 26018 | 1.64041666667 | 11936 |
| 012714 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:08pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593416.7 | 510448.8 | 26020 | 1.64041666667 | 12714 |
| 012649 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:09pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593414.2 | 510446.4 | 26022 | 1.64041666667 | 12649 |
| 012867 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:10pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593412.9 | 510445.1 | 26024 | 1.64041666667 | 12867 |
| 012053 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593412.8 | 510444.0 | 26026 | 1.64041666667 | 12053 |
| 011992 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:12pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593412.6 | 510443.8 | 26028 | 1.64041666667 | 11992 |
| 012550 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:13pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593411.6 | 510444.0 | 26030 | 1.64041666667 | 12550 |
| 012977 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:14pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593409.2 | 510444.0 | 26032 | 1.64041666667 | 12977 |
| 012459 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:15pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593406.1 | 510443.0 | 26034 | 1.64041666667 | 12459 |
| 011703 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:16pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593402.9 | 510442.1 | 26036 | 1.64041666667 | 11703 |
| 012875 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:17pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593399.9 | 510441.3 | 26038 | 1.64041666667 | 12875 |
| 012266 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:18pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593397.5 | 510439.6 | 26040 | 1.64041666667 | 12266 |
| 011728 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:19pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593394.5 | 510437.5 | 26042 | 1.64041666667 | 11728 |
| 011967 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:20pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593391.9 | 510436.2 | 26044 | 1.64041666667 | 11967 |
| 011374 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:21pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593388.8 | 510434.3 | 26046 | 1.64041666667 | 11374 |
| 011947 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:22pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593386.1 | 510433.5 | 26048 | 1.64041666667 | 11947 |
| 012060 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:23pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593382.6 | 510432.9 | 26050 | 1.64041666667 | 12060 |
| 011981 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:24pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593380.1 | 510431.5 | 26052 | 1.64041666667 | 11981 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011802 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:25pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593377.3 | 510430.0 | 26054 | 1.64041666667 | 11802 |
| 011866 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:26pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593374.0 | 510428.6 | 26056 | 1.64041666667 | 11866 |
| 011047 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593371.8 | 510427.4 | 26058 | 1.64041666667 | 11047 |
| 011351 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:28pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593369.2 | 510425.7 | 26060 | 1.64041666667 | 11351 |
| 012565 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:29pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593366.2 | 510423.7 | 26062 | 1.64041666667 | 12565 |
| 012115 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:30pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593364.2 | 510421.1 | 26064 | 1.64041666667 | 12115 |
| 012500 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:31pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593361.4 | 510418.0 | 26066 | 1.64041666667 | 12500 |
| 012225 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:32pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593358.9 | 510416.2 | 26068 | 1.64041666667 | 12225 |
| 011809 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593355.8 | 510413.1 | 26070 | 1.64041666667 | 11809 |
| 011863 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593354.1 | 510410.8 | 26072 | 1.64041666667 | 11863 |
| 011563 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593351.3 | 510408.0 | 26074 | 1.64041666667 | 11563 |
| 012264 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593349.2 | 510405.7 | 26076 | 1.64041666667 | 12264 |
| 012111 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593347.2 | 510402.5 | 26078 | 1.64041666667 | 12111 |
| 012467 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:38pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593345.0 | 510399.8 | 26080 | 1.64041666667 | 12467 |
| 013185 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593343.0 | 510397.7 | 26082 | 1.64041666667 | 13185 |
| 012584 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:40pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593341.1 | 510395.2 | 26084 | 1.64041666667 | 12584 |
| 013168 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593338.9 | 510393.0 | 26086 | 1.64041666667 | 13168 |
| 011794 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:42pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593337.8 | 510392.8 | 26088 | 1.64041666667 | 11794 |
| 011322 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593337.6 | 510391.6 | 26090 | 1.64041666667 | 11322 |
| 011513 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:44pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.4 | 510390.2 | 26092 | 1.64041666667 | 11513 |
| 011778 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:45pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593334.0 | 510388.5 | 26094 | 1.64041666667 | 11778 |
| 011665 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:46pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593332.5 | 510386.0 | 26096 | 1.64041666667 | 11665 |
| 012434 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:47pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593330.1 | 510383.1 | 26098 | 1.64041666667 | 12434 |
| 012214 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:48pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593328.2 | 510381.2 | 26100 | 1.64041666667 | 12214 |
| 012060 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:49pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593327.0 | 510378.9 | 26102 | 1.64041666667 | 12060 |
| 012596 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:50pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593326.0 | 510378.2 | 26104 | 1.64041666667 | 12596 |
| 012658 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:51pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593326.0 | 510377.8 | 26106 | 1.64041666667 | 12658 |
| 012820 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:52pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593326.2 | 510377.6 | 26108 | 1.64041666667 | 12820 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:53pm | Sensor | 1797-S0027-636-G-DTE | 6802.6 | 1593325.5 | 510376.9 | 26110 | 1.64041666667 | 12236 |
| 012425 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:54pm | Sensor | 1797-S0027-636-G-DTE | 6802.6 | 1593324.7 | 510375.4 | 26112 | 1.64041666667 | 12425 |
| 012494 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:55pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593324.0 | 510373.0 | 26114 | 1.64041666667 | 12494 |
| 012510 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:56pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593324.3 | 510370.6 | 26116 | 1.64041666667 | 12510 |
| 012212 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:57pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593324.0 | 510368.0 | 26118 | 1.64041666667 | 12212 |
| 012412 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:58pm | Sensor | 1797-S0027-636-G-DTE | 6802.5 | 1593325.2 | 510366.3 | 26120 | 1.64041666667 | 12412 |
| 012531 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:59pm | Sensor | 1797-S0027-636-G-DTE | 6802.6 | 1593327.5 | 510365.8 | 26122 | 1.64041666667 | 12531 |
| 012111 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:00pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593330.0 | 510366.2 | 26124 | 1.64041666667 | 12111 |
| 011380 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:01pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593332.6 | 510368.2 | 26126 | 1.64041666667 | 11380 |
| 012356 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:02pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593335.2 | 510369.3 | 26128 | 1.64041666667 | 12356 |
| 012650 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:03pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593337.5 | 510371.3 | 26130 | 1.64041666667 | 12650 |
| 012868 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:04pm | Sensor | 1797-S0027-636-G-DTE | 6802.7 | 1593338.7 | 510373.6 | 26132 | 1.64041666667 | 12868 |
| 012556 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:05pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593340.4 | 510376.0 | 26134 | 1.64041666667 | 12556 |
| 012342 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:06pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593340.7 | 510376.7 | 26136 | 1.64041666667 | 12342 |
| 012800 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:07pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593340.7 | 510376.6 | 26138 | 1.64041666667 | 12800 |
| 012652 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:08pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593340.7 | 510376.6 | 26140 | 1.64041666667 | 12652 |
| 012134 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:09pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593340.8 | 510376.5 | 26142 | 1.64041666667 | 12134 |
| 012953 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:10pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593340.8 | 510376.5 | 26144 | 1.64041666667 | 12953 |
| 013076 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:11pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593340.9 | 510376.4 | 26146 | 1.64041666667 | 13076 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:12pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593341.2 | 510376.0 | 26148 | 1.64041666667 | 12785 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012269 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:13pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593341.6 | 510376.1 | 26150 | 1.64041666667 | 12269 |
| 012091 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:14pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593342.7 | 510377.3 | 26152 | 1.64041666667 | 12091 |
| 012329 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:15pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593345.6 | 510380.6 | 26154 | 1.64041666667 | 12329 |
| 012710 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:16pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593348.0 | 510383.4 | 26156 | 1.64041666667 | 12710 |
| 012287 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:17pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593350.9 | 510385.9 | 26158 | 1.64041666667 | 12287 |
| 011808 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:18pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593352.6 | 510387.7 | 26160 | 1.64041666667 | 11808 |
| 011600 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:19pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593353.7 | 510390.4 | 26162 | 1.64041666667 | 11600 |
| 011767 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:20pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593355.4 | 510392.7 | 26164 | 1.64041666667 | 11767 |
| 012011 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:21pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593358.3 | 510394.9 | 26166 | 1.64041666667 | 12011 |
| 011916 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:22pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593360.0 | 510397.0 | 26168 | 1.64041666667 | 11916 |
| 012133 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:23pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593362.5 | 510399.3 | 26170 | 1.64041666667 | 12133 |
| 011827 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:24pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593364.3 | 510400.5 | 26172 | 1.64041666667 | 11827 |
| 012090 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:25pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593364.5 | 510404.7 | 26174 | 1.64041666667 | 12090 |
| 012185 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:26pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593365.3 | 510407.8 | 26176 | 1.64041666667 | 12185 |
| 012239 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593368.0 | 510411.0 | 26178 | 1.64041666667 | 12239 |
| 011962 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:28pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593369.6 | 510414.1 | 26180 | 1.64041666667 | 11962 |
| 011986 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:29pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593371.2 | 510417.0 | 26182 | 1.64041666667 | 11986 |
| 012277 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:30pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593373.2 | 510419.1 | 26184 | 1.64041666667 | 12277 |
| 012268 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:31pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593375.6 | 510422.5 | 26186 | 1.64041666667 | 12268 |
| 012376 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:32pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593377.3 | 510424.6 | 26188 | 1.64041666667 | 12376 |
| 011866 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593380.3 | 510426.9 | 26190 | 1.64041666667 | 11866 |
| 012300 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593382.5 | 510429.3 | 26192 | 1.64041666667 | 12300 |
| 011763 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593385.1 | 510431.3 | 26194 | 1.64041666667 | 11763 |
| 011342 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593387.8 | 510432.4 | 26196 | 1.64041666667 | 11342 |
| 011742 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593391.5 | 510434.4 | 26198 | 1.64041666667 | 11742 |
| 011367 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:38pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593394.5 | 510436.2 | 26200 | 1.64041666667 | 11367 |
| 012206 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593398.3 | 510438.0 | 26202 | 1.64041666667 | 12206 |
| 011928 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:40pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593400.6 | 510439.3 | 26204 | 1.64041666667 | 11928 |
| 011435 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593403.4 | 510441.5 | 26206 | 1.64041666667 | 11435 |
| 011794 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:42pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593406.2 | 510442.3 | 26208 | 1.64041666667 | 11794 |
| 013212 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593409.5 | 510444.0 | 26210 | 1.64041666667 | 13212 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:44pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593411.4 | 510445.5 | 26212 | 1.64041666667 | 13094 |
| 012435 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:45pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593413.7 | 510445.9 | 26214 | 1.64041666667 | 12435 |
| 012162 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:46pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593414.5 | 510446.5 | 26216 | 1.64041666667 | 12162 |
| 012346 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:47pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593414.4 | 510446.5 | 26218 | 1.64041666667 | 12346 |
| 011955 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:48pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593414.5 | 510446.5 | 26220 | 1.64041666667 | 11955 |
| 011862 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:49pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593414.8 | 510446.5 | 26222 | 1.64041666667 | 11862 |
| 011397 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:50pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593414.8 | 510446.5 | 26224 | 1.64041666667 | 11397 |
| 011653 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593415.5 | 510447.2 | 26226 | 1.64041666667 | 11653 |
| 012877 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:52pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593417.0 | 510448.1 | 26228 | 1.64041666667 | 12877 |
| 012996 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593418.9 | 510450.0 | 26230 | 1.64041666667 | 12996 |
| 013055 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:54pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593420.3 | 510450.9 | 26232 | 1.64041666667 | 13055 |
| 012991 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593420.7 | 510450.5 | 26234 | 1.64041666667 | 12991 |
| 012250 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:56pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593420.6 | 510450.7 | 26236 | 1.64041666667 | 12250 |
| 012065 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593420.7 | 510451.3 | 26238 | 1.64041666667 | 12065 |
| 012637 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:58pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593421.2 | 510452.6 | 26240 | 1.64041666667 | 12637 |
| 012058 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:59pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593421.4 | 510454.0 | 26242 | 1.64041666667 | 12058 |
| 011500 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:00pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593421.7 | 510454.0 | 26244 | 1.64041666667 | 11500 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012243 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:01pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593423.3 | 510453.4 | 26246 | 1.64041666667 | 12243 |
| 012317 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:02pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593425.0 | 510453.1 | 26248 | 1.64041666667 | 12317 |
| 012373 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:03pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593426.5 | 510451.9 | 26250 | 1.64041666667 | 12373 |
| 012652 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:04pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593428.6 | 510452.3 | 26252 | 1.64041666667 | 12652 |
| 013514 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:05pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593430.2 | 510452.4 | 26254 | 1.64041666667 | 13514 |
| 013609 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:06pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593430.8 | 510452.6 | 26256 | 1.64041666667 | 13609 |
| 013055 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593432.0 | 510452.2 | 26258 | 1.64041666667 | 13055 |
| 013178 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:08pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593433.2 | 510451.5 | 26260 | 1.64041666667 | 13178 |
| 012805 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:09pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593435.0 | 510450.6 | 26262 | 1.64041666667 | 12805 |
| 012610 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:10pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593435.7 | 510447.8 | 26264 | 1.64041666667 | 12610 |
| 012861 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:11pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593435.5 | 510444.8 | 26266 | 1.64041666667 | 12861 |
| 013924 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:12pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593436.1 | 510443.3 | 26268 | 1.64041666667 | 13924 |
| 013555 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:13pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593436.1 | 510443.3 | 26270 | 1.64041666667 | 13555 |
| 013399 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:14pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593436.0 | 510443.4 | 26272 | 1.64041666667 | 13399 |
| 012420 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:15pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593435.7 | 510443.6 | 26274 | 1.64041666667 | 12420 |
| 011981 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:16pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593435.3 | 510443.2 | 26276 | 1.64041666667 | 11981 |
| 013414 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:17pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593433.7 | 510440.8 | 26278 | 1.64041666667 | 13414 |
| 013140 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:18pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593431.7 | 510439.1 | 26280 | 1.64041666667 | 13140 |
| 013811 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593429.6 | 510436.9 | 26282 | 1.64041666667 | 13811 |
| 013626 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593428.3 | 510434.9 | 26284 | 1.64041666667 | 13626 |
| 012952 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593426.0 | 510432.8 | 26286 | 1.64041666667 | 12952 |
| 012678 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:22pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593424.7 | 510431.0 | 26288 | 1.64041666667 | 12678 |
| 012381 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593421.3 | 510430.5 | 26290 | 1.64041666667 | 12381 |
| 012642 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:24pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593418.6 | 510429.7 | 26292 | 1.64041666667 | 12642 |
| 012181 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593415.1 | 510428.6 | 26294 | 1.64041666667 | 12181 |
| 012619 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593412.7 | 510428.3 | 26296 | 1.64041666667 | 12619 |
| 012258 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593409.5 | 510426.6 | 26298 | 1.64041666667 | 12258 |
| 012100 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:28pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593406.7 | 510426.0 | 26300 | 1.64041666667 | 12100 |
| 011988 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:29pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593403.8 | 510425.5 | 26302 | 1.64041666667 | 11988 |
| 011723 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:30pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593400.9 | 510424.8 | 26304 | 1.64041666667 | 11723 |
| 012639 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:31pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593398.1 | 510424.6 | 26306 | 1.64041666667 | 12639 |
| 011805 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:32pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593396.0 | 510422.9 | 26308 | 1.64041666667 | 11805 |
| 011620 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593393.4 | 510420.5 | 26310 | 1.64041666667 | 11620 |
| 011861 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593391.7 | 510419.1 | 26312 | 1.64041666667 | 11861 |
| 012994 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593389.9 | 510416.7 | 26314 | 1.64041666667 | 12994 |
| 011876 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593387.9 | 510415.3 | 26316 | 1.64041666667 | 11876 |
| 011848 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593385.5 | 510413.0 | 26318 | 1.64041666667 | 11848 |
| 012072 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:38pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593383.8 | 510411.3 | 26320 | 1.64041666667 | 12072 |
| 011665 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593381.1 | 510409.4 | 26322 | 1.64041666667 | 11665 |
| 012719 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:40pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593379.2 | 510407.1 | 26324 | 1.64041666667 | 12719 |
| 013559 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593376.8 | 510405.0 | 26326 | 1.64041666667 | 13559 |
| 013237 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:42pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593374.7 | 510403.4 | 26328 | 1.64041666667 | 13237 |
| 012808 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593372.9 | 510400.3 | 26330 | 1.64041666667 | 12808 |
| 012439 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:44pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593371.4 | 510398.9 | 26332 | 1.64041666667 | 12439 |
| 011887 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:45pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593369.6 | 510396.0 | 26334 | 1.64041666667 | 11887 |
| 011411 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:46pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593368.6 | 510394.5 | 26336 | 1.64041666667 | 11411 |
| 011391 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593367.3 | 510393.5 | 26338 | 1.64041666667 | 11391 |
| 011522 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:48pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593367.2 | 510393.1 | 26340 | 1.64041666667 | 11522 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011394 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593366.8 | 510392.6 | 26342 | 1.64041666667 | 11394 |
| 012124 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:50pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593366.0 | 510391.5 | 26344 | 1.64041666667 | 12124 |
| 012947 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593363.8 | 510388.9 | 26346 | 1.64041666667 | 12947 |
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593361.9 | 510386.7 | 26348 | 1.64041666667 | 13320 |
| 013080 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593359.1 | 510384.4 | 26350 | 1.64041666667 | 13080 |
| 013822 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:54pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593357.2 | 510382.8 | 26352 | 1.64041666667 | 13822 |
| 013640 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:55pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593355.3 | 510379.7 | 26354 | 1.64041666667 | 13640 |
| 013537 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:56pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593353.8 | 510377.9 | 26356 | 1.64041666667 | 13537 |
| 013157 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593351.4 | 510375.5 | 26358 | 1.64041666667 | 13157 |
| 012366 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:58pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593349.2 | 510372.9 | 26360 | 1.64041666667 | 12366 |
| 012048 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593346.4 | 510370.7 | 26362 | 1.64041666667 | 12048 |
| 012259 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:00pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593344.0 | 510369.0 | 26364 | 1.64041666667 | 12259 |
| 012266 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593341.6 | 510366.6 | 26366 | 1.64041666667 | 12266 |
| 012194 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:02pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593339.4 | 510365.3 | 26368 | 1.64041666667 | 12194 |
| 012364 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:03pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593337.4 | 510363.6 | 26370 | 1.64041666667 | 12364 |
| 012355 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:04pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.9 | 510362.2 | 26372 | 1.64041666667 | 12355 |
| 011517 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:05pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.5 | 510362.4 | 26374 | 1.64041666667 | 11517 |
| 012996 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:06pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.5 | 510362.3 | 26376 | 1.64041666667 | 12996 |
| 013032 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:07pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.6 | 510361.9 | 26378 | 1.64041666667 | 13032 |
| 012311 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:08pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.6 | 510361.9 | 26380 | 1.64041666667 | 12311 |
| 012070 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:09pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.6 | 510361.9 | 26382 | 1.64041666667 | 12070 |
| 012601 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:10pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.7 | 510361.8 | 26384 | 1.64041666667 | 12601 |
| 012353 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:11pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.7 | 510361.8 | 26386 | 1.64041666667 | 12353 |
| 012858 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:12pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.6 | 510361.7 | 26388 | 1.64041666667 | 12858 |
| 012595 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:13pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593336.6 | 510361.9 | 26390 | 1.64041666667 | 12595 |
| 012552 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:14pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593336.2 | 510362.0 | 26392 | 1.64041666667 | 12552 |
| 013098 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:15pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593334.2 | 510360.9 | 26394 | 1.64041666667 | 13098 |
| 012775 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:16pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593331.8 | 510358.9 | 26396 | 1.64041666667 | 12775 |
| 012376 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:17pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593329.7 | 510356.6 | 26398 | 1.64041666667 | 12376 |
| 011994 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:18pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593327.5 | 510354.9 | 26400 | 1.64041666667 | 11994 |
| 012304 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:19pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593327.5 | 510352.6 | 26402 | 1.64041666667 | 12304 |
| 013386 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:20pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593328.4 | 510351.1 | 26404 | 1.64041666667 | 13386 |
| 013237 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:21pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593330.6 | 510350.7 | 26406 | 1.64041666667 | 13237 |
| 012726 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:22pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593333.0 | 510352.1 | 26408 | 1.64041666667 | 12726 |
| 012311 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:23pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593336.4 | 510353.3 | 26410 | 1.64041666667 | 12311 |
| 012992 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:24pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593339.3 | 510354.4 | 26412 | 1.64041666667 | 12992 |
| 012288 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:25pm | Sensor | 1797-S0027-636-G-DTE | 6802.9 | 1593342.4 | 510356.1 | 26414 | 1.64041666667 | 12288 |
| 012229 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:26pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593345.2 | 510357.7 | 26416 | 1.64041666667 | 12229 |
| 012421 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593348.5 | 510359.0 | 26418 | 1.64041666667 | 12421 |
| 012687 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:28pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593350.9 | 510360.5 | 26420 | 1.64041666667 | 12687 |
| 012881 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:29pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593354.1 | 510362.3 | 26422 | 1.64041666667 | 12881 |
| 012840 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:30pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593357.1 | 510363.8 | 26424 | 1.64041666667 | 12840 |
| 012615 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:31pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593359.7 | 510365.8 | 26426 | 1.64041666667 | 12615 |
| 012428 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:32pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593362.3 | 510366.9 | 26428 | 1.64041666667 | 12428 |
| 013621 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593364.9 | 510368.5 | 26430 | 1.64041666667 | 13621 |
| 013909 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593367.3 | 510370.1 | 26432 | 1.64041666667 | 13909 |
| 012901 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593369.6 | 510371.2 | 26434 | 1.64041666667 | 12901 |
| 012417 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593370.8 | 510373.4 | 26436 | 1.64041666667 | 12417 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012894 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593372.9 | 510376.2 | 26438 | 1.64041666667 | 12894 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:38pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593374.5 | 510378.4 | 26440 | 1.64041666667 | 13050 |
| 012658 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593375.8 | 510381.2 | 26442 | 1.64041666667 | 12658 |
| 011748 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:40pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593377.5 | 510383.3 | 26444 | 1.64041666667 | 11748 |
| 012885 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593379.2 | 510386.2 | 26446 | 1.64041666667 | 12885 |
| 012925 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:42pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593380.4 | 510387.5 | 26448 | 1.64041666667 | 12925 |
| 013030 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593382.5 | 510389.8 | 26450 | 1.64041666667 | 13030 |
| 013074 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:44pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593383.5 | 510391.9 | 26452 | 1.64041666667 | 13074 |
| 012357 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:45pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593384.5 | 510392.7 | 26454 | 1.64041666667 | 12357 |
| 012418 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:46pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593383.7 | 510393.7 | 26456 | 1.64041666667 | 12418 |
| 013750 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593382.6 | 510395.0 | 26458 | 1.64041666667 | 13750 |
| 013397 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:48pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593381.5 | 510394.5 | 26460 | 1.64041666667 | 13397 |
| 012658 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593380.7 | 510394.2 | 26462 | 1.64041666667 | 12658 |
| 012963 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:50pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593380.9 | 510393.9 | 26464 | 1.64041666667 | 12963 |
| 013111 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593380.4 | 510392.9 | 26466 | 1.64041666667 | 13111 |
| 013060 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593380.5 | 510392.9 | 26468 | 1.64041666667 | 13060 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593380.7 | 510392.8 | 26470 | 1.64041666667 | 13038 |
| 013124 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:54pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593380.7 | 510393.0 | 26472 | 1.64041666667 | 13124 |
| 013322 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:55pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593380.6 | 510392.8 | 26474 | 1.64041666667 | 13322 |
| 012744 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:56pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593380.6 | 510393.1 | 26476 | 1.64041666667 | 12744 |
| 012133 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.1 | 1593381.2 | 510393.1 | 26478 | 1.64041666667 | 12133 |
| 012247 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:58pm | Sensor | 1797-S0027-636-G-DTE | 6802.4 | 1593382.3 | 510393.2 | 26480 | 1.64041666667 | 12247 |
| 012926 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:59pm | Sensor | 1797-S0027-636-G-DTE | 6802.8 | 1593381.9 | 510393.4 | 26482 | 1.64041666667 | 12926 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:00pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593381.1 | 510393.5 | 26484 | 1.64041666667 | 13038 |
| 013034 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593383.0 | 510392.9 | 26486 | 1.64041666667 | 13034 |
| 012881 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:02pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593384.5 | 510393.3 | 26488 | 1.64041666667 | 12881 |
| 013201 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:03pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593387.1 | 510393.1 | 26490 | 1.64041666667 | 13201 |
| 012735 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:04pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593389.4 | 510394.4 | 26492 | 1.64041666667 | 12735 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:05pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593392.1 | 510395.8 | 26494 | 1.64041666667 | 13043 |
| 012939 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:06pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593394.8 | 510397.2 | 26496 | 1.64041666667 | 12939 |
| 012723 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:07pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593397.3 | 510399.8 | 26498 | 1.64041666667 | 12723 |
| 013142 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:08pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593399.5 | 510401.6 | 26500 | 1.64041666667 | 13142 |
| 013017 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:09pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593403.0 | 510402.4 | 26502 | 1.64041666667 | 13017 |
| 012849 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:10pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.1 | 510404.1 | 26504 | 1.64041666667 | 12849 |
| 012373 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593408.5 | 510405.6 | 26506 | 1.64041666667 | 12373 |
| 012224 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:12pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593412.2 | 510406.1 | 26508 | 1.64041666667 | 12224 |
| 012329 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:13pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593415.1 | 510408.1 | 26510 | 1.64041666667 | 12329 |
| 011330 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:14pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593416.8 | 510409.7 | 26512 | 1.64041666667 | 11330 |
| 011758 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:15pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593419.4 | 510411.2 | 26514 | 1.64041666667 | 11758 |
| 012 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:16pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593421.9 | 510412.8 | 26516 | 1.64041666667 | 12 |
| 012596 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:17pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593425.5 | 510412.7 | 26518 | 1.64041666667 | 12596 |
| 012328 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:18pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593428.4 | 510412.7 | 26520 | 1.64041666667 | 12328 |
| 012642 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593431.4 | 510412.7 | 26522 | 1.64041666667 | 12642 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593434.0 | 510411.8 | 26524 | 1.64041666667 | 13471 |
| 012212 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593437.0 | 510412.4 | 26526 | 1.64041666667 | 12212 |
| 012704 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:22pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593438.4 | 510413.4 | 26528 | 1.64041666667 | 12704 |
| 012801 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593439.5 | 510415.3 | 26530 | 1.64041666667 | 12801 |
| 013193 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:24pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593438.5 | 510417.7 | 26532 | 1.64041666667 | 13193 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013346 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593437.1 | 510419.8 | 26534 | 1.64041666667 | 13346 |
| 013934 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593435.1 | 510421.0 | 26536 | 1.64041666667 | 13934 |
| 013523 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:27pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593431.4 | 510420.9 | 26538 | 1.64041666667 | 13523 |
| 013014 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:28pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593428.6 | 510420.2 | 26540 | 1.64041666667 | 13014 |
| 013403 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593425.5 | 510419.3 | 26542 | 1.64041666667 | 13403 |
| 012444 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:30pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593422.9 | 510417.5 | 26544 | 1.64041666667 | 12444 |
| 012527 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593420.0 | 510416.3 | 26546 | 1.64041666667 | 12527 |
| 012821 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593417.2 | 510416.7 | 26547 | 1.64041666667 | 12821 |
| 012432 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593414.1 | 510415.3 | 26550 | 1.64041666667 | 12432 |
| 012513 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:34pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593411.9 | 510413.8 | 26552 | 1.64041666667 | 12513 |
| 012341 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:35pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593409.1 | 510412.9 | 26554 | 1.64041666667 | 12341 |
| 012379 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593407.6 | 510411.1 | 26556 | 1.64041666667 | 12379 |
| 013166 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593405.2 | 510409.7 | 26558 | 1.64041666667 | 13166 |
| 013046 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:38pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593402.1 | 510409.2 | 26560 | 1.64041666667 | 13046 |
| 012993 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593399.3 | 510408.7 | 26562 | 1.64041666667 | 12993 |
| 012956 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:40pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593396.3 | 510408.4 | 26564 | 1.64041666667 | 12956 |
| 012883 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593393.3 | 510407.3 | 26566 | 1.64041666667 | 12883 |
| 012016 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593390.2 | 510406.2 | 26567 | 1.64041666667 | 12016 |
| 011964 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593386.2 | 510405.1 | 26570 | 1.64041666667 | 11964 |
| 012400 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593384.0 | 510403.8 | 26571 | 1.64041666667 | 12400 |
| 011910 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:45pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593381.6 | 510401.4 | 26574 | 1.64041666667 | 11910 |
| 012916 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:46pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593379.0 | 510400.4 | 26576 | 1.64041666667 | 12916 |
| 011968 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593376.3 | 510399.7 | 26578 | 1.64041666667 | 11968 |
| 011922 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593374.6 | 510399.1 | 26579 | 1.64041666667 | 11922 |
| 011236 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593371.2 | 510399.8 | 26582 | 1.64041666667 | 11236 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593369.1 | 510399.3 | 26583 | 1.64041666667 | 12785 |
| 013116 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593366.5 | 510398.0 | 26586 | 1.64041666667 | 13116 |
| 012500 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593363.8 | 510398.4 | 26588 | 1.64041666667 | 12500 |
| 012664 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593361.3 | 510397.3 | 26590 | 1.64041666667 | 12664 |
| 012546 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:54pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593358.9 | 510396.7 | 26592 | 1.64041666667 | 12546 |
| 012832 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:55pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593358.3 | 510394.6 | 26594 | 1.64041666667 | 12832 |
| 013218 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:56pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593358.0 | 510392.7 | 26596 | 1.64041666667 | 13218 |
| 013315 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593359.9 | 510391.1 | 26598 | 1.64041666667 | 13315 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:58pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593361.7 | 510389.8 | 26600 | 1.64041666667 | 13782 |
| 013430 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593362.7 | 510386.8 | 26602 | 1.64041666667 | 13430 |
| 012421 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593362.4 | 510384.3 | 26603 | 1.64041666667 | 12421 |
| 013369 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593360.8 | 510382.5 | 26606 | 1.64041666667 | 13369 |
| 013190 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:02pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593360.4 | 510380.3 | 26608 | 1.64041666667 | 13190 |
| 012969 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:03pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593359.1 | 510377.6 | 26610 | 1.64041666667 | 12969 |
| 012590 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:04pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593356.1 | 510375.3 | 26612 | 1.64041666667 | 12590 |
| 013142 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:05pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593353.9 | 510372.0 | 26614 | 1.64041666667 | 13142 |
| 012635 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:05pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593353.7 | 510369.2 | 26615 | 1.64041666667 | 12635 |
| 012672 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:07pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593353.0 | 510364.9 | 26618 | 1.64041666667 | 12672 |
| 012610 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:07pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593351.8 | 510362.0 | 26619 | 1.64041666667 | 12610 |
| 012838 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:09pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593349.9 | 510357.6 | 26622 | 1.64041666667 | 12838 |
| 012479 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:09pm | Sensor | 1797-S0027-636-G-DTE | 6803.0 | 1593348.5 | 510354.5 | 26623 | 1.64041666667 | 12479 |
| 012142 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.2 | 1593346.2 | 510351.4 | 26626 | 1.64041666667 | 12142 |
| 011712 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593343.9 | 510350.0 | 26627 | 1.64041666667 | 11712 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012558 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:13pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593343.1 | 510346.8 | 26630 | 1.64041666667 | 12558 |
| 013026 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:14pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593342.6 | 510344.2 | 26632 | 1.64041666667 | 13026 |
| 013117 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:15pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593341.3 | 510340.6 | 26634 | 1.64041666667 | 13117 |
| 011916 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:16pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593341.4 | 510338.3 | 26636 | 1.64041666667 | 11916 |
| 013377 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:17pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593339.8 | 510335.4 | 26638 | 1.64041666667 | 13377 |
| 013667 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:18pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593338.9 | 510333.3 | 26640 | 1.64041666667 | 13667 |
| 013298 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593339.2 | 510330.8 | 26642 | 1.64041666667 | 13298 |
| 014020 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593339.2 | 510329.1 | 26644 | 1.64041666667 | 14020 |
| 014756 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593341.1 | 510329.0 | 26646 | 1.64041666667 | 14756 |
| 014060 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:22pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593343.2 | 510328.3 | 26648 | 1.64041666667 | 14060 |
| 013676 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593345.7 | 510328.3 | 26650 | 1.64041666667 | 13676 |
| 013993 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:24pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593347.4 | 510326.0 | 26652 | 1.64041666667 | 13993 |
| 012866 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593348.7 | 510323.9 | 26654 | 1.64041666667 | 12866 |
| 013102 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593350.1 | 510323.0 | 26656 | 1.64041666667 | 13102 |
| 013902 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:27pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593351.0 | 510322.3 | 26658 | 1.64041666667 | 13902 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:28pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593353.4 | 510322.5 | 26660 | 1.64041666667 | 13295 |
| 013321 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593356.2 | 510323.9 | 26662 | 1.64041666667 | 13321 |
| 012998 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:30pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593358.7 | 510325.2 | 26664 | 1.64041666667 | 12998 |
| 013476 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593362.0 | 510326.5 | 26666 | 1.64041666667 | 13476 |
| 013190 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593364.1 | 510328.3 | 26667 | 1.64041666667 | 13190 |
| 013307 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:33pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593367.7 | 510330.4 | 26670 | 1.64041666667 | 13307 |
| 014400 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:33pm | Sensor | 1797-S0027-636-G-DTE | 6805.0 | 1593370.3 | 510331.7 | 26671 | 1.64041666667 | 14400 |
| 014205 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:35pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593373.4 | 510333.9 | 26674 | 1.64041666667 | 14205 |
| 014155 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:35pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593376.1 | 510335.2 | 26675 | 1.64041666667 | 14155 |
| 013497 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593380.5 | 510336.9 | 26678 | 1.64041666667 | 13497 |
| 013232 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593383.5 | 510338.2 | 26679 | 1.64041666667 | 13232 |
| 012873 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593387.3 | 510339.8 | 26682 | 1.64041666667 | 12873 |
| 012708 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593390.2 | 510340.3 | 26683 | 1.64041666667 | 12708 |
| 013148 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593394.0 | 510342.0 | 26686 | 1.64041666667 | 13148 |
| 013581 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593396.4 | 510343.3 | 26687 | 1.64041666667 | 13581 |
| 013387 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593400.1 | 510345.4 | 26690 | 1.64041666667 | 13387 |
| 013040 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593403.0 | 510346.8 | 26691 | 1.64041666667 | 13040 |
| 013155 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:45pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593407.2 | 510348.7 | 26694 | 1.64041666667 | 13155 |
| 013309 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:46pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593410.2 | 510349.8 | 26696 | 1.64041666667 | 13309 |
| 014109 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:47pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593414.0 | 510350.6 | 26698 | 1.64041666667 | 14109 |
| 013576 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:48pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593417.4 | 510351.7 | 26700 | 1.64041666667 | 13576 |
| 013449 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:49pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593420.7 | 510353.1 | 26702 | 1.64041666667 | 13449 |
| 014015 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:50pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593423.8 | 510353.2 | 26704 | 1.64041666667 | 14015 |
| 013163 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593427.2 | 510355.4 | 26706 | 1.64041666667 | 13163 |
| 013007 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:52pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593429.9 | 510356.8 | 26708 | 1.64041666667 | 13007 |
| 013961 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593433.2 | 510358.2 | 26710 | 1.64041666667 | 13961 |
| 013298 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:54pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593435.9 | 510360.2 | 26712 | 1.64041666667 | 13298 |
| 014005 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593439.4 | 510361.5 | 26714 | 1.64041666667 | 14005 |
| 012670 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:56pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593442.2 | 510362.1 | 26716 | 1.64041666667 | 12670 |
| 013149 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593444.8 | 510363.8 | 26718 | 1.64041666667 | 13149 |
| 013134 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:58pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593447.1 | 510364.2 | 26720 | 1.64041666667 | 13134 |
| 012157 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:59pm | Sensor | 1797-S0027-636-G-DTE | 6805.1 | 1593449.0 | 510364.9 | 26722 | 1.64041666667 | 12157 |
| 012568 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:00pm | Sensor | 1797-S0027-636-G-DTE | 6805.2 | 1593450.1 | 510364.8 | 26724 | 1.64041666667 | 12568 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012942 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:01pm | Sensor | 1797-S0027-636-G-DTE | 6805.0 | 1593450.8 | 510366.7 | 26726 | 1.64041666667 | 12942 |
| 012972 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:01pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593451.1 | 510368.8 | 26727 | 1.64041666667 | 12972 |
| 012982 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:03pm | Sensor | 1797-S0027-636-G-DTE | 6805.1 | 1593451.2 | 510370.9 | 26730 | 1.64041666667 | 12982 |
| 014285 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:03pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593450.4 | 510371.9 | 26731 | 1.64041666667 | 14285 |
| 013315 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:05pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593450.2 | 510373.4 | 26734 | 1.64041666667 | 13315 |
| 012634 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:05pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593450.0 | 510373.1 | 26735 | 1.64041666667 | 12634 |
| 013062 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593450.1 | 510373.2 | 26738 | 1.64041666667 | 13062 |
| 013175 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:08pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593449.7 | 510373.5 | 26740 | 1.64041666667 | 13175 |
| 012833 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:09pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593447.1 | 510372.6 | 26742 | 1.64041666667 | 12833 |
| 012581 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:10pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593443.8 | 510372.3 | 26744 | 1.64041666667 | 12581 |
| 011832 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:11pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593439.9 | 510371.4 | 26746 | 1.64041666667 | 11832 |
| 011793 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:11pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593437.0 | 510369.9 | 26747 | 1.64041666667 | 11793 |
| 011673 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:12pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593433.2 | 510368.7 | 26749 | 1.64041666667 | 11673 |
| 011613 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:13pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593429.7 | 510368.6 | 26751 | 1.64041666667 | 11613 |
| 012975 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:15pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593426.0 | 510366.8 | 26754 | 1.64041666667 | 12975 |
| 012616 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:16pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593423.6 | 510365.4 | 26756 | 1.64041666667 | 12616 |
| 012631 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:17pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593420.4 | 510364.3 | 26758 | 1.64041666667 | 12631 |
| 012895 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:18pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593417.7 | 510362.6 | 26760 | 1.64041666667 | 12895 |
| 013021 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593414.2 | 510361.4 | 26762 | 1.64041666667 | 13021 |
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593411.4 | 510361.1 | 26763 | 1.64041666667 | 12761 |
| 013433 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593408.6 | 510359.9 | 26765 | 1.64041666667 | 13433 |
| 013346 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593405.1 | 510358.4 | 26767 | 1.64041666667 | 13346 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593401.0 | 510357.7 | 26770 | 1.64041666667 | 13132 |
| 013942 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593398.1 | 510356.7 | 26771 | 1.64041666667 | 13942 |
| 013804 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:24pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593395.4 | 510355.1 | 26773 | 1.64041666667 | 13804 |
| 013600 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593392.7 | 510354.5 | 26775 | 1.64041666667 | 13600 |
| 013657 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:27pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593390.1 | 510352.4 | 26778 | 1.64041666667 | 13657 |
| 013487 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593387.5 | 510351.6 | 26779 | 1.64041666667 | 13487 |
| 013834 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593384.0 | 510349.7 | 26782 | 1.64041666667 | 13834 |
| 014119 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:30pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593381.8 | 510347.4 | 26784 | 1.64041666667 | 14119 |
| 014234 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593378.8 | 510345.9 | 26786 | 1.64041666667 | 14234 |
| 014487 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:32pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593376.5 | 510344.3 | 26788 | 1.64041666667 | 14487 |
| 013863 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:33pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593373.8 | 510342.2 | 26790 | 1.64041666667 | 13863 |
| 013971 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593370.8 | 510341.3 | 26792 | 1.64041666667 | 13971 |
| 014308 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593368.2 | 510339.2 | 26794 | 1.64041666667 | 14308 |
| 014296 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:35pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593366.4 | 510337.7 | 26795 | 1.64041666667 | 14296 |
| 013876 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593363.5 | 510336.8 | 26798 | 1.64041666667 | 13876 |
| 013738 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593361.7 | 510335.8 | 26799 | 1.64041666667 | 13738 |
| 013517 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593358.6 | 510335.4 | 26802 | 1.64041666667 | 13517 |
| 013588 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593356.6 | 510334.2 | 26803 | 1.64041666667 | 13588 |
| 013883 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593353.7 | 510332.5 | 26806 | 1.64041666667 | 13883 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593351.8 | 510331.8 | 26807 | 1.64041666667 | 13742 |
| 013749 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593348.8 | 510330.3 | 26810 | 1.64041666667 | 13749 |
| 013554 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593347.0 | 510329.8 | 26811 | 1.64041666667 | 13554 |
| 013211 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:45pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593344.8 | 510329.3 | 26814 | 1.64041666667 | 13211 |
| 012884 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:46pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593343.2 | 510328.2 | 26816 | 1.64041666667 | 12884 |
| 013067 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:47pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593343.0 | 510328.5 | 26818 | 1.64041666667 | 13067 |
| 013830 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:48pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593342.9 | 510328.6 | 26820 | 1.64041666667 | 13830 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013517 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:49pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593343.1 | 510330.0 | 26822 | 1.64041666667 | 13517 |
| 013333 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:50pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593342.0 | 510331.9 | 26824 | 1.64041666667 | 13333 |
| 013650 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593341.6 | 510334.4 | 26826 | 1.64041666667 | 13650 |
| 013678 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593341.6 | 510336.4 | 26827 | 1.64041666667 | 13678 |
| 012861 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593343.2 | 510338.8 | 26830 | 1.64041666667 | 12861 |
| 013002 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593345.3 | 510339.6 | 26831 | 1.64041666667 | 13002 |
| 012796 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593348.4 | 510341.7 | 26834 | 1.64041666667 | 12796 |
| 012770 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:56pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593350.8 | 510342.2 | 26836 | 1.64041666667 | 12770 |
| 013145 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593354.4 | 510343.9 | 26838 | 1.64041666667 | 13145 |
| 012719 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593356.7 | 510345.9 | 26839 | 1.64041666667 | 12719 |
| 012420 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593360.5 | 510348.2 | 26842 | 1.64041666667 | 12420 |
| 013008 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:00pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593363.0 | 510349.7 | 26844 | 1.64041666667 | 13008 |
| 013309 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593365.5 | 510352.3 | 26846 | 1.64041666667 | 13309 |
| 013711 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593368.3 | 510353.8 | 26847 | 1.64041666667 | 13711 |
| 013412 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:03pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593372.0 | 510354.6 | 26850 | 1.64041666667 | 13412 |
| 013604 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:03pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593374.5 | 510355.8 | 26851 | 1.64041666667 | 13604 |
| 014035 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:05pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593378.6 | 510356.3 | 26854 | 1.64041666667 | 14035 |
| 013482 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:06pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593381.4 | 510356.5 | 26856 | 1.64041666667 | 13482 |
| 012998 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593384.6 | 510358.3 | 26858 | 1.64041666667 | 12998 |
| 012561 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593387.3 | 510358.9 | 26859 | 1.64041666667 | 12561 |
| 012428 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:09pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593391.6 | 510360.3 | 26862 | 1.64041666667 | 12428 |
| 012563 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:10pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593394.1 | 510361.6 | 26864 | 1.64041666667 | 12563 |
| 012744 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593397.8 | 510362.4 | 26866 | 1.64041666667 | 12744 |
| 013063 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:11pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593400.2 | 510363.0 | 26867 | 1.64041666667 | 13063 |
| 012951 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:13pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593403.6 | 510365.5 | 26870 | 1.64041666667 | 12951 |
| 012835 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:13pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593405.8 | 510366.4 | 26871 | 1.64041666667 | 12835 |
| 012852 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:15pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593409.8 | 510368.8 | 26874 | 1.64041666667 | 12852 |
| 013619 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:16pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593411.9 | 510370.8 | 26876 | 1.64041666667 | 13619 |
| 014313 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:17pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593414.9 | 510371.7 | 26878 | 1.64041666667 | 14313 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:18pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593417.8 | 510373.7 | 26880 | 1.64041666667 | 14111 |
| 013615 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593420.3 | 510375.5 | 26882 | 1.64041666667 | 13615 |
| 013141 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593423.1 | 510376.1 | 26884 | 1.64041666667 | 13141 |
| 012829 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593426.1 | 510377.6 | 26886 | 1.64041666667 | 12829 |
| 012774 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:22pm | Sensor | 1797-S0027-636-G-DTE | 6805.2 | 1593428.3 | 510378.6 | 26888 | 1.64041666667 | 12774 |
| 013342 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:23pm | Sensor | 1797-S0027-636-G-DTE | 6805.3 | 1593431.4 | 510379.1 | 26890 | 1.64041666667 | 13342 |
| 012912 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:24pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593433.9 | 510380.2 | 26892 | 1.64041666667 | 12912 |
| 012348 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593437.4 | 510381.2 | 26894 | 1.64041666667 | 12348 |
| 012496 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593439.7 | 510381.3 | 26896 | 1.64041666667 | 12496 |
| 012294 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:27pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593441.9 | 510382.6 | 26898 | 1.64041666667 | 12294 |
| 011782 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:28pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593442.4 | 510383.8 | 26900 | 1.64041666667 | 11782 |
| 013100 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593441.7 | 510386.3 | 26902 | 1.64041666667 | 13100 |
| 012281 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593440.4 | 510388.3 | 26903 | 1.64041666667 | 12281 |
| 012473 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593439.4 | 510389.2 | 26906 | 1.64041666667 | 12473 |
| 013151 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593438.8 | 510390.0 | 26907 | 1.64041666667 | 13151 |
| 013930 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:33pm | Sensor | 1797-S0027-636-G-DTE | 6805.0 | 1593436.6 | 510388.8 | 26910 | 1.64041666667 | 13930 |
| 013213 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:34pm | Sensor | 1797-S0027-636-G-DTE | 6805.1 | 1593434.0 | 510388.1 | 26912 | 1.64041666667 | 13213 |
| 013455 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:35pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593430.4 | 510385.9 | 26914 | 1.64041666667 | 13455 |
| 013103 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:36pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593428.1 | 510384.2 | 26916 | 1.64041666667 | 13103 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012845 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593424.3 | 510384.1 | 26918 | 1.64041666667 | 12845 |
| 012633 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593422.0 | 510383.3 | 26919 | 1.64041666667 | 12633 |
| 012536 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593418.8 | 510381.3 | 26922 | 1.64041666667 | 12536 |
| 013681 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593416.7 | 510380.6 | 26923 | 1.64041666667 | 13681 |
| 013485 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593414.0 | 510378.4 | 26926 | 1.64041666667 | 13485 |
| 013136 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593410.8 | 510378.1 | 26927 | 1.64041666667 | 13136 |
| 013606 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593407.4 | 510376.8 | 26930 | 1.64041666667 | 13606 |
| 013286 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593405.3 | 510375.4 | 26931 | 1.64041666667 | 13286 |
| 013451 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:45pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593402.2 | 510374.6 | 26934 | 1.64041666667 | 13451 |
| 013783 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:46pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593399.8 | 510372.9 | 26936 | 1.64041666667 | 13783 |
| 014105 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:47pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593396.7 | 510371.1 | 26938 | 1.64041666667 | 14105 |
| 014707 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:48pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593394.1 | 510370.4 | 26940 | 1.64041666667 | 14707 |
| 013665 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593391.4 | 510368.3 | 26942 | 1.64041666667 | 13665 |
| 013251 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:50pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593388.7 | 510367.0 | 26944 | 1.64041666667 | 13251 |
| 013416 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593385.8 | 510365.8 | 26946 | 1.64041666667 | 13416 |
| 012481 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593384.0 | 510364.1 | 26947 | 1.64041666667 | 12481 |
| 013306 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593380.9 | 510362.1 | 26950 | 1.64041666667 | 13306 |
| 013874 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593378.3 | 510361.1 | 26951 | 1.64041666667 | 13874 |
| 014839 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593375.2 | 510358.7 | 26954 | 1.64041666667 | 14839 |
| 014564 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593372.7 | 510357.5 | 26955 | 1.64041666667 | 14564 |
| 013652 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593369.7 | 510355.9 | 26958 | 1.64041666667 | 13652 |
| 012489 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593367.5 | 510354.1 | 26959 | 1.64041666667 | 12489 |
| 012144 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593363.9 | 510352.5 | 26962 | 1.64041666667 | 12144 |
| 012696 | 0 | GeoXH 6000 | 08/18/2015 | 12:22:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593361.5 | 510351.4 | 26963 | 1.64041666667 | 12696 |
| 012699 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593358.4 | 510349.3 | 26966 | 1.64041666667 | 12699 |
| 012543 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593355.2 | 510348.0 | 26967 | 1.64041666667 | 12543 |
| 013123 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:03pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593351.1 | 510346.2 | 26970 | 1.64041666667 | 13123 |
| 014094 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:04pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593348.4 | 510344.5 | 26972 | 1.64041666667 | 14094 |
| 013845 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:04pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593345.8 | 510343.2 | 26973 | 1.64041666667 | 13845 |
| 013938 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:05pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593343.4 | 510341.9 | 26975 | 1.64041666667 | 13938 |
| 013382 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:06pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593340.0 | 510340.4 | 26977 | 1.64041666667 | 13382 |
| 013212 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593337.6 | 510342.1 | 26979 | 1.64041666667 | 13212 |
| 013799 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:09pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593335.5 | 510345.6 | 26982 | 1.64041666667 | 13799 |
| 012667 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:09pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593335.3 | 510348.2 | 26983 | 1.64041666667 | 12667 |
| 012495 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:10pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593337.4 | 510349.9 | 26985 | 1.64041666667 | 12495 |
| 012601 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:11pm | Sensor | 1797-S0027-636-G-DTE | 6803.4 | 1593339.8 | 510352.1 | 26987 | 1.64041666667 | 12601 |
| 012390 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:12pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593342.8 | 510354.0 | 26989 | 1.64041666667 | 12390 |
| 012279 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:13pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593345.6 | 510355.1 | 26991 | 1.64041666667 | 12279 |
| 012420 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:15pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593348.6 | 510357.5 | 26994 | 1.64041666667 | 12420 |
| 011988 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:15pm | Sensor | 1797-S0027-636-G-DTE | 6803.3 | 1593351.4 | 510358.1 | 26995 | 1.64041666667 | 11988 |
| 012323 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:17pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593354.5 | 510358.8 | 26998 | 1.64041666667 | 12323 |
| 012534 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:18pm | Sensor | 1797-S0027-636-G-DTE | 6803.5 | 1593356.6 | 510360.3 | 27000 | 1.64041666667 | 12534 |
| 012938 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:19pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593358.3 | 510360.1 | 27002 | 1.64041666667 | 12938 |
| 012707 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:19pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593358.3 | 510360.2 | 27003 | 1.64041666667 | 12707 |
| 012465 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:21pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593358.7 | 510360.7 | 27006 | 1.64041666667 | 12465 |
| 014099 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:21pm | Sensor | 1797-S0027-636-G-DTE | 6803.6 | 1593359.6 | 510362.1 | 27007 | 1.64041666667 | 14099 |
| 014531 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:23pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593362.1 | 510363.3 | 27010 | 1.64041666667 | 14531 |
| 013963 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:23pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593364.6 | 510364.6 | 27011 | 1.64041666667 | 13963 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014679 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:25pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593368.2 | 510365.0 | 27014 | 1.64041666667 | 14679 |
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593370.6 | 510365.0 | 27016 | 1.64041666667 | 14227 |
| 013297 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593373.5 | 510366.4 | 27018 | 1.64041666667 | 13297 |
| 013817 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:27pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593375.9 | 510367.3 | 27019 | 1.64041666667 | 13817 |
| 013232 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593379.0 | 510368.0 | 27022 | 1.64041666667 | 13232 |
| 013548 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:30pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593381.4 | 510370.0 | 27024 | 1.64041666667 | 13548 |
| 013605 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:30pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593384.0 | 510370.7 | 27025 | 1.64041666667 | 13605 |
| 013541 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593386.4 | 510371.5 | 27027 | 1.64041666667 | 13541 |
| 013706 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:32pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593388.8 | 510373.2 | 27029 | 1.64041666667 | 13706 |
| 013447 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:33pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593390.9 | 510374.2 | 27031 | 1.64041666667 | 13447 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593392.8 | 510376.7 | 27033 | 1.64041666667 | 13301 |
| 012724 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:36pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593395.0 | 510379.2 | 27036 | 1.64041666667 | 12724 |
| 013525 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:37pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593398.1 | 510380.8 | 27038 | 1.64041666667 | 13525 |
| 012835 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593400.2 | 510382.8 | 27039 | 1.64041666667 | 12835 |
| 012927 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:38pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593402.7 | 510384.5 | 27041 | 1.64041666667 | 12927 |
| 012851 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:39pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593405.5 | 510385.6 | 27043 | 1.64041666667 | 12851 |
| 012576 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:40pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593408.8 | 510387.7 | 27045 | 1.64041666667 | 12576 |
| 012489 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:41pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593411.9 | 510390.0 | 27047 | 1.64041666667 | 12489 |
| 013737 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:43pm | Sensor | 1797-S0027-636-G-DTE | 6805.2 | 1593415.5 | 510391.6 | 27050 | 1.64041666667 | 13737 |
| 012985 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:43pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593417.8 | 510393.5 | 27051 | 1.64041666667 | 12985 |
| 012801 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:44pm | Sensor | 1797-S0027-636-G-DTE | 6805.0 | 1593421.7 | 510396.1 | 27053 | 1.64041666667 | 12801 |
| 011745 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:45pm | Sensor | 1797-S0027-636-G-DTE | 6805.0 | 1593424.6 | 510397.5 | 27055 | 1.64041666667 | 11745 |
| 012082 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:46pm | Sensor | 1797-S0027-636-G-DTE | 6805.2 | 1593427.9 | 510398.7 | 27057 | 1.64041666667 | 12082 |
| 012976 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:47pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593429.7 | 510400.7 | 27059 | 1.64041666667 | 12976 |
| 012871 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:48pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593433.0 | 510402.3 | 27061 | 1.64041666667 | 12871 |
| 012407 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:49pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593436.2 | 510403.4 | 27063 | 1.64041666667 | 12407 |
| 012716 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:50pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593439.0 | 510405.4 | 27065 | 1.64041666667 | 12716 |
| 013490 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:51pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593441.6 | 510406.5 | 27067 | 1.64041666667 | 13490 |
| 012688 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:52pm | Sensor | 1797-S0027-636-G-DTE | 6805.0 | 1593443.8 | 510406.7 | 27069 | 1.64041666667 | 12688 |
| 013189 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:53pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593443.7 | 510408.9 | 27071 | 1.64041666667 | 13189 |
| 012826 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593442.3 | 510411.5 | 27074 | 1.64041666667 | 12826 |
| 013237 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:55pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593441.5 | 510413.4 | 27075 | 1.64041666667 | 13237 |
| 012651 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.6 | 1593438.5 | 510413.4 | 27078 | 1.64041666667 | 12651 |
| 012501 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:57pm | Sensor | 1797-S0027-636-G-DTE | 6804.5 | 1593436.4 | 510412.8 | 27079 | 1.64041666667 | 12501 |
| 013122 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:58pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593433.2 | 510411.7 | 27081 | 1.64041666667 | 13122 |
| 013171 | 0 | GeoXH 6000 | 08/18/2015 | 12:23:59pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593431.5 | 510409.7 | 27083 | 1.64041666667 | 13171 |
| 012343 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:00pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593428.5 | 510406.9 | 27085 | 1.64041666667 | 12343 |
| 011781 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:01pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593425.7 | 510405.4 | 27087 | 1.64041666667 | 11781 |
| 012071 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:03pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593422.8 | 510403.7 | 27090 | 1.64041666667 | 12071 |
| 012573 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:03pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593421.0 | 510403.8 | 27091 | 1.64041666667 | 12573 |
| 013169 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:04pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593418.7 | 510402.8 | 27093 | 1.64041666667 | 13169 |
| 012523 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:05pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593416.3 | 510401.9 | 27095 | 1.64041666667 | 12523 |
| 012601 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:06pm | Sensor | 1797-S0027-636-G-DTE | 6804.7 | 1593413.1 | 510400.7 | 27097 | 1.64041666667 | 12601 |
| 012165 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:07pm | Sensor | 1797-S0027-636-G-DTE | 6804.8 | 1593411.7 | 510398.7 | 27099 | 1.64041666667 | 12165 |
| 012956 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:08pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593409.8 | 510398.7 | 27101 | 1.64041666667 | 12956 |
| 012297 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:09pm | Sensor | 1797-S0027-636-G-DTE | 6804.9 | 1593408.8 | 510397.1 | 27103 | 1.64041666667 | 12297 |
| 012970 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:10pm | Sensor | 1797-S0027-636-G-DTE | 6805.2 | 1593406.9 | 510395.8 | 27105 | 1.64041666667 | 12970 |
| 012770 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:11pm | Sensor | 1797-S0027-636-G-DTE | 6805.1 | 1593405.0 | 510393.9 | 27107 | 1.64041666667 | 12770 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012673 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:12pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593402.6 | 510392.2 | 27109 | 1.64041666667 | 12673 |
| 012768 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:13pm | Sensor | 1797-S0027-636-G-DTE | 6804.4 | 1593400.2 | 510390.4 | 27111 | 1.64041666667 | 12768 |
| 012350 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:14pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593398.1 | 510387.7 | 27113 | 1.64041666667 | 12350 |
| 012271 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:15pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593395.9 | 510385.7 | 27115 | 1.64041666667 | 12271 |
| 012303 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:17pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593393.1 | 510384.1 | 27118 | 1.64041666667 | 12303 |
| 012680 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:17pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593391.5 | 510381.8 | 27119 | 1.64041666667 | 12680 |
| 012825 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593388.6 | 510378.9 | 27122 | 1.64041666667 | 12825 |
| 013544 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:19pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593386.0 | 510377.8 | 27123 | 1.64041666667 | 13544 |
| 013446 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:20pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593383.5 | 510376.9 | 27125 | 1.64041666667 | 13446 |
| 013173 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:21pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593381.9 | 510374.8 | 27127 | 1.64041666667 | 13173 |
| 012615 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593379.9 | 510373.1 | 27130 | 1.64041666667 | 12615 |
| 013261 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:23pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593379.3 | 510371.0 | 27131 | 1.64041666667 | 13261 |
| 013136 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593377.3 | 510368.4 | 27134 | 1.64041666667 | 13136 |
| 013254 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:25pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593375.0 | 510368.2 | 27135 | 1.64041666667 | 13254 |
| 012008 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:26pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593371.6 | 510368.7 | 27137 | 1.64041666667 | 12008 |
| 011427 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:27pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593369.5 | 510370.5 | 27139 | 1.64041666667 | 11427 |
| 012885 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:28pm | Sensor | 1797-S0027-636-G-DTE | 6804.2 | 1593367.7 | 510372.5 | 27141 | 1.64041666667 | 12885 |
| 013345 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:29pm | Sensor | 1797-S0027-636-G-DTE | 6804.3 | 1593366.8 | 510375.4 | 27143 | 1.64041666667 | 13345 |
| 013762 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:30pm | Sensor | 1797-S0027-636-G-DTE | 6804.1 | 1593368.9 | 510378.1 | 27145 | 1.64041666667 | 13762 |
| 013943 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:31pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593369.8 | 510380.8 | 27147 | 1.64041666667 | 13943 |
| 013220 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:33pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593370.3 | 510384.3 | 27150 | 1.64041666667 | 13220 |
| 013691 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:33pm | Sensor | 1797-S0027-636-G-DTE | 6804.0 | 1593371.8 | 510386.6 | 27151 | 1.64041666667 | 13691 |
| 012891 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:34pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593373.0 | 510389.7 | 27153 | 1.64041666667 | 12891 |
| 012411 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:35pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593373.9 | 510392.0 | 27155 | 1.64041666667 | 12411 |
| 012554 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593375.9 | 510393.7 | 27158 | 1.64041666667 | 12554 |
| 012506 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:37pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593376.4 | 510395.5 | 27159 | 1.64041666667 | 12506 |
| 012622 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593376.5 | 510395.5 | 27162 | 1.64041666667 | 12622 |
| 012380 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:39pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593376.8 | 510395.1 | 27163 | 1.64041666667 | 12380 |
| 012483 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:40pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593378.3 | 510394.8 | 27165 | 1.64041666667 | 12483 |
| 012962 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:41pm | Sensor | 1797-S0027-636-G-DTE | 6803.7 | 1593379.2 | 510394.0 | 27167 | 1.64041666667 | 12962 |
| 012256 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593381.4 | 510393.7 | 27170 | 1.64041666667 | 12256 |
| 012519 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:43pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593381.3 | 510393.7 | 27171 | 1.64041666667 | 12519 |
| 011932 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:44pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593381.4 | 510393.6 | 27173 | 1.64041666667 | 11932 |
| 011879 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:45pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.2 | 510393.7 | 27175 | 1.64041666667 | 11879 |
| 011947 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:46pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.2 | 510393.6 | 27177 | 1.64041666667 | 11947 |
| 012367 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:47pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.2 | 510393.6 | 27179 | 1.64041666667 | 12367 |
| 011749 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:48pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.3 | 510393.6 | 27181 | 1.64041666667 | 11749 |
| 012039 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:49pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.3 | 510393.6 | 27183 | 1.64041666667 | 12039 |
| 011999 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.3 | 510393.6 | 27186 | 1.64041666667 | 11999 |
| 011392 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:51pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.3 | 510393.6 | 27187 | 1.64041666667 | 11392 |
| 011958 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.4 | 510393.6 | 27189 | 1.64041666667 | 11958 |
| 012554 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.4 | 510393.6 | 27191 | 1.64041666667 | 12554 |
| 013474 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:54pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.4 | 510393.7 | 27193 | 1.64041666667 | 13474 |
| 013174 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:55pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.4 | 510393.7 | 27195 | 1.64041666667 | 13174 |
| 013065 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:56pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.4 | 510393.7 | 27197 | 1.64041666667 | 13065 |
| 013296 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.4 | 510393.6 | 27199 | 1.64041666667 | 13296 |
| 012767 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:58pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.4 | 510393.7 | 27201 | 1.64041666667 | 12767 |
| 012303 | 0 | GeoXH 6000 | 08/18/2015 | 12:24:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593381.4 | 510393.7 | 27203 | 1.64041666667 | 12303 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011782 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510393.7 | 27261 | 1.64041666667 | 11782 |
| 012544 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:52pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510393.7 | 27262 | 1.64041666667 | 12544 |
| 011721 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:53pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510393.8 | 27263 | 1.64041666667 | 11721 |
| 013020 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:54pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510393.7 | 27264 | 1.64041666667 | 13020 |
| 012491 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:55pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510393.6 | 27265 | 1.64041666667 | 12491 |
| 012981 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:56pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510393.7 | 27266 | 1.64041666667 | 12981 |
| 012507 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:57pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593381.6 | 510393.7 | 27267 | 1.64041666667 | 12507 |
| 012540 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:58pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510393.7 | 27268 | 1.64041666667 | 12540 |
| 012251 | 0 | GeoXH 6000 | 08/18/2015 | 12:25:59pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.6 | 510393.7 | 27269 | 1.64041666667 | 12251 |
| 012051 | 0 | GeoXH 6000 | 08/18/2015 | 12:26:00pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.5 | 510393.7 | 27270 | 1.64041666667 | 12051 |
| 012186 | 0 | GeoXH 6000 | 08/18/2015 | 12:26:01pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.5 | 510393.7 | 27271 | 1.64041666667 | 12186 |
| 012149 | 0 | GeoXH 6000 | 08/18/2015 | 12:26:03pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.5 | 510393.7 | 27272 | 1.64041666667 | 12149 |
| 012308 | 0 | GeoXH 6000 | 08/18/2015 | 12:26:04pm | Sensor | 1797-S0027-636-G-DTE | 6803.8 | 1593381.5 | 510393.7 | 27273 | 1.64041666667 | 12308 |
| 012653 | 0 | GeoXH 6000 | 08/18/2015 | 12:26:05pm | Sensor | 1797-S0027-636-G-DTE | 6803.9 | 1593381.5 | 510393.6 | 27275 | 1.64041666667 | 12653 |
| 012196 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:09am | Sensor | 1797-S0026-905-G-ACK | 6806.4 | 1593227.4 | 510133.0 | 22573 | 1.64041666667 | 12196 |
| 011945 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:10am | Sensor | 1797-S0026-905-G-ACK | 6806.5 | 1593227.4 | 510133.0 | 22576 | 1.64041666667 | 11945 |
| 011864 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:11am | Sensor | 1797-S0026-905-G-ACK | 6806.5 | 1593227.3 | 510133.0 | 22578 | 1.64041666667 | 11864 |
| 011293 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:12am | Sensor | 1797-S0026-905-G-ACK | 6806.6 | 1593227.3 | 510133.1 | 22580 | 1.64041666667 | 11293 |
| 011730 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:13am | Sensor | 1797-S0026-905-G-ACK | 6806.7 | 1593227.2 | 510133.1 | 22582 | 1.64041666667 | 11730 |
| 011638 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:14am | Sensor | 1797-S0026-905-G-ACK | 6806.9 | 1593227.1 | 510133.2 | 22584 | 1.64041666667 | 11638 |
| 012794 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:15am | Sensor | 1797-S0026-905-G-ACK | 6807.3 | 1593226.9 | 510133.2 | 22586 | 1.64041666667 | 12794 |
| 012184 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:16am | Sensor | 1797-S0026-905-G-ACK | 6807.8 | 1593226.6 | 510133.3 | 22588 | 1.64041666667 | 12184 |
| 012291 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:17am | Sensor | 1797-S0026-905-G-ACK | 6808.5 | 1593226.3 | 510133.4 | 22590 | 1.64041666667 | 12291 |
| 012553 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:18am | Sensor | 1797-S0026-905-G-ACK | 6808.3 | 1593226.2 | 510133.8 | 22592 | 1.64041666667 | 12553 |
| 012371 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:19am | Sensor | 1797-S0026-905-G-ACK | 6807.2 | 1593226.0 | 510135.3 | 22594 | 1.64041666667 | 12371 |
| 012764 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:20am | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593229.1 | 510136.0 | 22596 | 1.64041666667 | 12764 |
| 011934 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:21am | Sensor | 1797-S0026-905-G-ACK | 6801.6 | 1593230.2 | 510136.0 | 22598 | 1.64041666667 | 11934 |
| 011408 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:22am | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593230.4 | 510136.8 | 22600 | 1.64041666667 | 11408 |
| 011149 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:23am | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593229.8 | 510135.4 | 22602 | 1.64041666667 | 11149 |
| 013449 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:24am | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593228.6 | 510135.0 | 22604 | 1.64041666667 | 13449 |
| 013670 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:25am | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593227.1 | 510134.1 | 22606 | 1.64041666667 | 13670 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:26am | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593225.4 | 510131.8 | 22608 | 1.64041666667 | 13442 |
| 013891 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:27am | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593223.9 | 510129.8 | 22610 | 1.64041666667 | 13891 |
| 014343 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:28am | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593220.6 | 510129.4 | 22612 | 1.64041666667 | 14343 |
| 014323 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:28am | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593219.0 | 510127.5 | 22613 | 1.64041666667 | 14323 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:30am | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593216.8 | 510124.4 | 22616 | 1.64041666667 | 14266 |
| 013267 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:31am | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593214.8 | 510123.2 | 22618 | 1.64041666667 | 13267 |
| 012712 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:32am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593212.4 | 510121.2 | 22620 | 1.64041666667 | 12712 |
| 012251 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:33am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593210.4 | 510119.5 | 22622 | 1.64041666667 | 12251 |
| 012186 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:34am | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593207.4 | 510118.8 | 22624 | 1.64041666667 | 12186 |
| 012352 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:35am | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593204.8 | 510117.7 | 22626 | 1.64041666667 | 12352 |
| 011643 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:36am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593202.2 | 510116.8 | 22628 | 1.64041666667 | 11643 |
| 011664 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:37am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593200.1 | 510116.5 | 22630 | 1.64041666667 | 11664 |
| 011758 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:38am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593198.3 | 510115.5 | 22632 | 1.64041666667 | 11758 |
| 011774 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:39am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593196.3 | 510114.8 | 22634 | 1.64041666667 | 11774 |
| 012210 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:40am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593193.7 | 510113.1 | 22636 | 1.64041666667 | 12210 |
| 011818 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:41am | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593191.9 | 510112.1 | 22638 | 1.64041666667 | 11818 |
| 012108 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:42am | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593189.2 | 510111.3 | 22640 | 1.64041666667 | 12108 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011918 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:43am | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593187.6 | 510110.8 | 22642 | 1.64041666667 | 11918 |
| 012051 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:44am | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593185.3 | 510110.3 | 22644 | 1.64041666667 | 12051 |
| 011931 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:45am | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593183.3 | 510109.7 | 22646 | 1.64041666667 | 11931 |
| 013244 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:46am | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593181.3 | 510107.9 | 22648 | 1.64041666667 | 13244 |
| 013367 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:47am | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593179.1 | 510106.1 | 22650 | 1.64041666667 | 13367 |
| 013076 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:48am | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593177.2 | 510104.2 | 22652 | 1.64041666667 | 13076 |
| 013963 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:49am | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593175.3 | 510101.7 | 22654 | 1.64041666667 | 13963 |
| 014499 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:50am | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593173.6 | 510099.6 | 22656 | 1.64041666667 | 14499 |
| 016083 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:51am | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593171.7 | 510098.7 | 22658 | 1.64041666667 | 16083 |
| 016764 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:52am | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593170.0 | 510098.3 | 22660 | 1.64041666667 | 16764 |
| 017267 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:53am | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593169.9 | 510098.4 | 22662 | 1.64041666667 | 17267 |
| 018232 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:54am | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593170.0 | 510097.9 | 22664 | 1.64041666667 | 18232 |
| 018393 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:55am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593169.4 | 510095.6 | 22666 | 1.64041666667 | 18393 |
| 018378 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:56am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593167.2 | 510094.2 | 22668 | 1.64041666667 | 18378 |
| 018018 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:57am | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593165.8 | 510092.8 | 22670 | 1.64041666667 | 18018 |
| 016637 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:58am | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593165.6 | 510090.3 | 22672 | 1.64041666667 | 16637 |
| 015051 | 0 | GeoXH 6000 | 08/18/2015 | 11:59:59am | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593165.3 | 510088.2 | 22674 | 1.64041666667 | 15051 |
| 013588 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593165.8 | 510084.8 | 22676 | 1.64041666667 | 13588 |
| 013066 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:01pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593166.6 | 510082.1 | 22678 | 1.64041666667 | 13066 |
| 012772 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593166.9 | 510079.5 | 22680 | 1.64041666667 | 12772 |
| 012974 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:03pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593167.4 | 510077.0 | 22682 | 1.64041666667 | 12974 |
| 013290 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593168.9 | 510074.3 | 22684 | 1.64041666667 | 13290 |
| 012973 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:05pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593169.5 | 510071.5 | 22686 | 1.64041666667 | 12973 |
| 012667 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:06pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593170.1 | 510068.9 | 22688 | 1.64041666667 | 12667 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:07pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593171.1 | 510066.4 | 22690 | 1.64041666667 | 13050 |
| 012516 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:08pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593171.7 | 510063.6 | 22692 | 1.64041666667 | 12516 |
| 012395 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:09pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593172.3 | 510061.0 | 22694 | 1.64041666667 | 12395 |
| 012334 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:10pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593173.6 | 510058.3 | 22696 | 1.64041666667 | 12334 |
| 011850 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:11pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593174.8 | 510055.8 | 22698 | 1.64041666667 | 11850 |
| 011796 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:12pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593175.2 | 510053.1 | 22700 | 1.64041666667 | 11796 |
| 012687 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:13pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593175.5 | 510050.4 | 22702 | 1.64041666667 | 12687 |
| 012394 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:14pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593175.5 | 510047.5 | 22704 | 1.64041666667 | 12394 |
| 011306 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:15pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593175.4 | 510045.1 | 22706 | 1.64041666667 | 11306 |
| 011790 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:16pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593176.0 | 510042.0 | 22708 | 1.64041666667 | 11790 |
| 011619 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:17pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593177.2 | 510039.3 | 22710 | 1.64041666667 | 11619 |
| 011838 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:18pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593178.3 | 510036.3 | 22712 | 1.64041666667 | 11838 |
| 012884 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:19pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593178.7 | 510034.1 | 22714 | 1.64041666667 | 12884 |
| 013247 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:20pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593179.7 | 510031.1 | 22716 | 1.64041666667 | 13247 |
| 013369 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:20pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593180.6 | 510028.6 | 22717 | 1.64041666667 | 13369 |
| 012897 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593181.5 | 510025.7 | 22720 | 1.64041666667 | 12897 |
| 013195 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593182.9 | 510023.7 | 22722 | 1.64041666667 | 13195 |
| 014509 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:24pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593183.5 | 510022.1 | 22724 | 1.64041666667 | 14509 |
| 013561 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:25pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593184.6 | 510019.9 | 22726 | 1.64041666667 | 13561 |
| 013283 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593186.0 | 510017.8 | 22728 | 1.64041666667 | 13283 |
| 012804 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:27pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593186.6 | 510015.7 | 22730 | 1.64041666667 | 12804 |
| 013405 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:28pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593187.5 | 510012.6 | 22732 | 1.64041666667 | 13405 |
| 013045 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:29pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593188.0 | 510010.1 | 22734 | 1.64041666667 | 13045 |
| 012670 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593189.2 | 510006.9 | 22736 | 1.64041666667 | 12670 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013457 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:31pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593190.0 | 510004.5 | 22738 | 1.64041666667 | 13457 |
| 013944 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:32pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593190.6 | 510001.1 | 22740 | 1.64041666667 | 13944 |
| 013371 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:33pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593190.8 | 509998.2 | 22742 | 1.64041666667 | 13371 |
| 012876 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593191.6 | 509994.9 | 22744 | 1.64041666667 | 12876 |
| 012905 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:35pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593192.1 | 509992.2 | 22746 | 1.64041666667 | 12905 |
| 013529 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593191.8 | 509988.8 | 22748 | 1.64041666667 | 13529 |
| 013962 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:37pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593192.0 | 509986.0 | 22750 | 1.64041666667 | 13962 |
| 013486 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593192.9 | 509982.5 | 22752 | 1.64041666667 | 13486 |
| 014448 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:39pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593192.9 | 509979.9 | 22754 | 1.64041666667 | 14448 |
| 013902 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593193.2 | 509976.3 | 22756 | 1.64041666667 | 13902 |
| 012972 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:41pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593193.7 | 509973.2 | 22758 | 1.64041666667 | 12972 |
| 013342 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593193.2 | 509970.3 | 22760 | 1.64041666667 | 13342 |
| 014052 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:43pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593193.1 | 509967.7 | 22762 | 1.64041666667 | 14052 |
| 013574 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593194.2 | 509964.1 | 22764 | 1.64041666667 | 13574 |
| 013770 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:45pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593194.6 | 509961.2 | 22766 | 1.64041666667 | 13770 |
| 014053 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593194.0 | 509957.6 | 22768 | 1.64041666667 | 14053 |
| 014115 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:47pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593193.4 | 509954.9 | 22770 | 1.64041666667 | 14115 |
| 014749 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593192.8 | 509951.5 | 22772 | 1.64041666667 | 14749 |
| 013426 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:49pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593192.0 | 509949.0 | 22774 | 1.64041666667 | 13426 |
| 013252 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593191.2 | 509945.5 | 22776 | 1.64041666667 | 13252 |
| 013049 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:51pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593191.3 | 509942.9 | 22778 | 1.64041666667 | 13049 |
| 013070 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:52pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593190.7 | 509939.5 | 22780 | 1.64041666667 | 13070 |
| 013457 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:53pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593190.1 | 509937.0 | 22782 | 1.64041666667 | 13457 |
| 013787 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593190.2 | 509933.6 | 22784 | 1.64041666667 | 13787 |
| 012847 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593190.4 | 509931.0 | 22786 | 1.64041666667 | 12847 |
| 012439 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593190.2 | 509928.1 | 22788 | 1.64041666667 | 12439 |
| 013402 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:57pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593190.2 | 509924.9 | 22790 | 1.64041666667 | 13402 |
| 013643 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:58pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593190.6 | 509921.9 | 22792 | 1.64041666667 | 13643 |
| 013307 | 0 | GeoXH 6000 | 08/18/2015 | 12:00:59pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593190.4 | 509919.8 | 22794 | 1.64041666667 | 13307 |
| 014077 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593191.0 | 509916.4 | 22796 | 1.64041666667 | 14077 |
| 014571 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:01pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593192.1 | 509913.3 | 22798 | 1.64041666667 | 14571 |
| 014204 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593193.0 | 509910.1 | 22800 | 1.64041666667 | 14204 |
| 014664 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:03pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593193.8 | 509907.4 | 22802 | 1.64041666667 | 14664 |
| 015134 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593195.7 | 509904.9 | 22804 | 1.64041666667 | 15134 |
| 014347 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:05pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593197.1 | 509902.6 | 22806 | 1.64041666667 | 14347 |
| 014498 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:06pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593197.9 | 509899.8 | 22808 | 1.64041666667 | 14498 |
| 014747 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:07pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593199.5 | 509897.1 | 22810 | 1.64041666667 | 14747 |
| 013020 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593201.3 | 509894.3 | 22812 | 1.64041666667 | 13020 |
| 013451 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:09pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593202.3 | 509891.3 | 22814 | 1.64041666667 | 13451 |
| 013671 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:10pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593203.7 | 509887.9 | 22816 | 1.64041666667 | 13671 |
| 013225 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:11pm | Sensor | 1797-S0026-905-G-ACK | 6801.8 | 1593205.2 | 509885.6 | 22818 | 1.64041666667 | 13225 |
| 013979 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:12pm | Sensor | 1797-S0026-905-G-ACK | 6801.7 | 1593206.8 | 509882.1 | 22820 | 1.64041666667 | 13979 |
| 013511 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:13pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593207.6 | 509879.5 | 22822 | 1.64041666667 | 13511 |
| 014110 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:14pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593208.4 | 509876.9 | 22824 | 1.64041666667 | 14110 |
| 014056 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:15pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593208.4 | 509874.2 | 22826 | 1.64041666667 | 14056 |
| 014769 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:16pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593209.1 | 509871.8 | 22828 | 1.64041666667 | 14769 |
| 015080 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:17pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593210.3 | 509869.7 | 22830 | 1.64041666667 | 15080 |
| 014355 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:18pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593212.2 | 509866.9 | 22832 | 1.64041666667 | 14355 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013722 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:19pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593213.8 | 509864.4 | 22834 | 1.64041666667 | 13722 |
| 013216 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:20pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593215.2 | 509861.8 | 22836 | 1.64041666667 | 13216 |
| 013516 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:21pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593216.1 | 509859.7 | 22838 | 1.64041666667 | 13516 |
| 013873 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:22pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593217.6 | 509856.3 | 22840 | 1.64041666667 | 13873 |
| 012858 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:22pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593218.1 | 509853.8 | 22841 | 1.64041666667 | 12858 |
| 012280 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:24pm | Sensor | 1797-S0026-905-G-ACK | 6801.9 | 1593217.6 | 509850.2 | 22844 | 1.64041666667 | 12280 |
| 012090 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:25pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593217.6 | 509847.3 | 22846 | 1.64041666667 | 12090 |
| 012988 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593218.0 | 509844.2 | 22848 | 1.64041666667 | 12988 |
| 013401 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:27pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593217.8 | 509840.9 | 22850 | 1.64041666667 | 13401 |
| 014365 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:28pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593216.8 | 509838.0 | 22852 | 1.64041666667 | 14365 |
| 014642 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:29pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593215.8 | 509835.3 | 22854 | 1.64041666667 | 14642 |
| 014446 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593214.6 | 509832.3 | 22856 | 1.64041666667 | 14446 |
| 014958 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:31pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593213.6 | 509829.8 | 22858 | 1.64041666667 | 14958 |
| 014174 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:32pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593213.4 | 509827.1 | 22860 | 1.64041666667 | 14174 |
| 014160 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:33pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593213.2 | 509824.8 | 22862 | 1.64041666667 | 14160 |
| 014190 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593212.9 | 509821.7 | 22864 | 1.64041666667 | 14190 |
| 014319 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:35pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593212.9 | 509819.3 | 22866 | 1.64041666667 | 14319 |
| 015030 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593213.6 | 509816.1 | 22868 | 1.64041666667 | 15030 |
| 014842 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593213.8 | 509813.2 | 22869 | 1.64041666667 | 14842 |
| 015224 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593213.4 | 509809.9 | 22872 | 1.64041666667 | 15224 |
| 016843 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:39pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593214.0 | 509807.2 | 22874 | 1.64041666667 | 16843 |
| 017102 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593215.3 | 509804.3 | 22876 | 1.64041666667 | 17102 |
| 016414 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:41pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593215.8 | 509801.3 | 22878 | 1.64041666667 | 16414 |
| 016358 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593216.6 | 509798.6 | 22880 | 1.64041666667 | 16358 |
| 017009 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:43pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593217.8 | 509796.5 | 22882 | 1.64041666667 | 17009 |
| 016362 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593218.6 | 509793.6 | 22884 | 1.64041666667 | 16362 |
| 015894 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:45pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593219.4 | 509791.8 | 22886 | 1.64041666667 | 15894 |
| 015622 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593220.8 | 509789.2 | 22888 | 1.64041666667 | 15622 |
| 015462 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:47pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593221.8 | 509787.0 | 22890 | 1.64041666667 | 15462 |
| 014240 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593223.4 | 509784.7 | 22892 | 1.64041666667 | 14240 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:49pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593225.2 | 509782.8 | 22894 | 1.64041666667 | 14092 |
| 014519 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593225.8 | 509780.6 | 22896 | 1.64041666667 | 14519 |
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:51pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593225.4 | 509778.4 | 22898 | 1.64041666667 | 14227 |
| 013725 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:52pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593224.5 | 509777.1 | 22900 | 1.64041666667 | 13725 |
| 013795 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:53pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593223.3 | 509776.1 | 22902 | 1.64041666667 | 13795 |
| 015110 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593223.5 | 509774.5 | 22904 | 1.64041666667 | 15110 |
| 015369 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593223.6 | 509773.3 | 22906 | 1.64041666667 | 15369 |
| 014727 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593224.3 | 509771.7 | 22908 | 1.64041666667 | 14727 |
| 014276 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:57pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593224.6 | 509770.6 | 22910 | 1.64041666667 | 14276 |
| 014278 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:58pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593225.2 | 509769.1 | 22912 | 1.64041666667 | 14278 |
| 015164 | 0 | GeoXH 6000 | 08/18/2015 | 12:01:59pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593225.3 | 509767.3 | 22914 | 1.64041666667 | 15164 |
| 015197 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593225.8 | 509764.7 | 22916 | 1.64041666667 | 15197 |
| 014848 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:01pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593225.3 | 509762.6 | 22918 | 1.64041666667 | 14848 |
| 014194 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593226.1 | 509760.6 | 22920 | 1.64041666667 | 14194 |
| 014164 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593227.7 | 509759.3 | 22921 | 1.64041666667 | 14164 |
| 014267 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:04pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593229.1 | 509757.5 | 22924 | 1.64041666667 | 14267 |
| 014145 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593230.9 | 509756.2 | 22925 | 1.64041666667 | 14145 |
| 015629 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593233.9 | 509754.8 | 22928 | 1.64041666667 | 15629 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015459 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593236.7 | 509753.3 | 22929 | 1.64041666667 | 15459 |
| 014613 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593239.5 | 509751.7 | 22932 | 1.64041666667 | 14613 |
| 014977 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:09pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593242.7 | 509750.2 | 22934 | 1.64041666667 | 14977 |
| 015174 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593245.8 | 509749.2 | 22936 | 1.64041666667 | 15174 |
| 015623 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593248.2 | 509748.4 | 22937 | 1.64041666667 | 15623 |
| 015973 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593251.3 | 509746.7 | 22940 | 1.64041666667 | 15973 |
| 015399 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:13pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593254.3 | 509745.7 | 22942 | 1.64041666667 | 15399 |
| 016261 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593257.4 | 509745.7 | 22944 | 1.64041666667 | 16261 |
| 015409 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593259.9 | 509745.2 | 22945 | 1.64041666667 | 15409 |
| 015770 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593262.9 | 509743.5 | 22948 | 1.64041666667 | 15770 |
| 015785 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:17pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593265.5 | 509742.4 | 22950 | 1.64041666667 | 15785 |
| 015824 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593268.4 | 509741.1 | 22952 | 1.64041666667 | 15824 |
| 015081 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593270.1 | 509739.8 | 22953 | 1.64041666667 | 15081 |
| 014303 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593273.5 | 509738.8 | 22956 | 1.64041666667 | 14303 |
| 013933 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593276.1 | 509738.8 | 22957 | 1.64041666667 | 13933 |
| 013770 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593279.3 | 509738.3 | 22960 | 1.64041666667 | 13770 |
| 014645 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593282.0 | 509737.5 | 22962 | 1.64041666667 | 14645 |
| 014590 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593284.8 | 509737.2 | 22964 | 1.64041666667 | 14590 |
| 015047 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593287.6 | 509737.0 | 22965 | 1.64041666667 | 15047 |
| 014524 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593290.5 | 509736.1 | 22968 | 1.64041666667 | 14524 |
| 014297 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593292.7 | 509735.4 | 22969 | 1.64041666667 | 14297 |
| 014177 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593295.9 | 509735.3 | 22972 | 1.64041666667 | 14177 |
| 014544 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:29pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593298.3 | 509735.4 | 22974 | 1.64041666667 | 14544 |
| 015209 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593301.2 | 509735.5 | 22976 | 1.64041666667 | 15209 |
| 014832 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593303.7 | 509736.0 | 22977 | 1.64041666667 | 14832 |
| 015070 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:32pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593307.0 | 509737.0 | 22980 | 1.64041666667 | 15070 |
| 015369 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:33pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593309.3 | 509736.5 | 22982 | 1.64041666667 | 15369 |
| 015253 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593311.6 | 509736.8 | 22984 | 1.64041666667 | 15253 |
| 015112 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593312.3 | 509737.6 | 22985 | 1.64041666667 | 15112 |
| 015415 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593313.2 | 509739.5 | 22988 | 1.64041666667 | 15415 |
| 016073 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593312.5 | 509741.9 | 22989 | 1.64041666667 | 16073 |
| 015978 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593311.4 | 509744.7 | 22992 | 1.64041666667 | 15978 |
| 015438 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:39pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593311.8 | 509747.4 | 22994 | 1.64041666667 | 15438 |
| 015434 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593311.9 | 509749.9 | 22996 | 1.64041666667 | 15434 |
| 017209 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:41pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593311.6 | 509752.7 | 22998 | 1.64041666667 | 17209 |
| 016617 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593311.9 | 509755.3 | 23000 | 1.64041666667 | 16617 |
| 017567 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:43pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593311.9 | 509757.7 | 23002 | 1.64041666667 | 17567 |
| 015994 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593312.0 | 509759.8 | 23004 | 1.64041666667 | 15994 |
| 016391 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:45pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593313.2 | 509760.2 | 23006 | 1.64041666667 | 16391 |
| 017537 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593315.8 | 509760.5 | 23008 | 1.64041666667 | 17537 |
| 016922 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:47pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593318.6 | 509760.0 | 23010 | 1.64041666667 | 16922 |
| 016576 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593321.2 | 509759.2 | 23012 | 1.64041666667 | 16576 |
| 016944 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593323.9 | 509759.5 | 23013 | 1.64041666667 | 16944 |
| 017226 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593327.5 | 509760.5 | 23016 | 1.64041666667 | 17226 |
| 017632 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:51pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593330.2 | 509760.7 | 23018 | 1.64041666667 | 17632 |
| 016803 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:52pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593332.8 | 509761.9 | 23020 | 1.64041666667 | 16803 |
| 016284 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:53pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593335.7 | 509763.0 | 23022 | 1.64041666667 | 16284 |
| 015362 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593338.5 | 509763.1 | 23024 | 1.64041666667 | 15362 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015173 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593341.0 | 509763.9 | 23026 | 1.64041666667 | 15173 |
| 015075 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593343.6 | 509764.6 | 23028 | 1.64041666667 | 15075 |
| 014847 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593345.7 | 509764.6 | 23029 | 1.64041666667 | 14847 |
| 014786 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593348.2 | 509766.7 | 23032 | 1.64041666667 | 14786 |
| 014400 | 0 | GeoXH 6000 | 08/18/2015 | 12:02:58pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593349.7 | 509767.9 | 23033 | 1.64041666667 | 14400 |
| 014400 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593352.5 | 509769.6 | 23036 | 1.64041666667 | 14400 |
| 014130 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593353.9 | 509771.2 | 23037 | 1.64041666667 | 14130 |
| 014188 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593356.8 | 509772.3 | 23040 | 1.64041666667 | 14188 |
| 014130 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:03pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593359.5 | 509773.6 | 23042 | 1.64041666667 | 14130 |
| 014721 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593362.2 | 509775.6 | 23044 | 1.64041666667 | 14721 |
| 014595 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:05pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593365.1 | 509776.8 | 23046 | 1.64041666667 | 14595 |
| 014360 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593367.9 | 509778.0 | 23048 | 1.64041666667 | 14360 |
| 014730 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:07pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593370.1 | 509779.4 | 23050 | 1.64041666667 | 14730 |
| 015276 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593373.3 | 509780.9 | 23052 | 1.64041666667 | 15276 |
| 014832 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:09pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593375.7 | 509781.8 | 23054 | 1.64041666667 | 14832 |
| 015303 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:10pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593378.5 | 509783.5 | 23056 | 1.64041666667 | 15303 |
| 014360 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:11pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593381.1 | 509784.7 | 23058 | 1.64041666667 | 14360 |
| 014302 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593384.1 | 509785.8 | 23060 | 1.64041666667 | 14302 |
| 014765 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:13pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593386.0 | 509787.1 | 23062 | 1.64041666667 | 14765 |
| 014395 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:14pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593389.5 | 509788.8 | 23064 | 1.64041666667 | 14395 |
| 014982 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593391.9 | 509789.6 | 23066 | 1.64041666667 | 14982 |
| 015102 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:16pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593394.9 | 509791.1 | 23068 | 1.64041666667 | 15102 |
| 015110 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:17pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593396.9 | 509792.0 | 23070 | 1.64041666667 | 15110 |
| 015534 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593399.6 | 509793.1 | 23072 | 1.64041666667 | 15534 |
| 016080 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:19pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593401.5 | 509794.6 | 23074 | 1.64041666667 | 16080 |
| 015682 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:20pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593404.5 | 509795.6 | 23076 | 1.64041666667 | 15682 |
| 015211 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:20pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593406.7 | 509795.9 | 23077 | 1.64041666667 | 15211 |
| 015359 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:22pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593409.4 | 509797.6 | 23080 | 1.64041666667 | 15359 |
| 014894 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:22pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593411.6 | 509798.3 | 23081 | 1.64041666667 | 14894 |
| 014063 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:24pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593414.6 | 509799.1 | 23084 | 1.64041666667 | 14063 |
| 014360 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:24pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593416.7 | 509800.2 | 23085 | 1.64041666667 | 14360 |
| 014775 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593418.5 | 509798.6 | 23088 | 1.64041666667 | 14775 |
| 013501 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593419.6 | 509796.9 | 23089 | 1.64041666667 | 13501 |
| 014501 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:28pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593420.6 | 509794.7 | 23092 | 1.64041666667 | 14501 |
| 015327 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593421.0 | 509792.6 | 23093 | 1.64041666667 | 15327 |
| 014906 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593422.5 | 509790.2 | 23096 | 1.64041666667 | 14906 |
| 013800 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:31pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593422.6 | 509788.7 | 23098 | 1.64041666667 | 13800 |
| 014145 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593422.7 | 509786.6 | 23100 | 1.64041666667 | 14145 |
| 013919 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:33pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593420.8 | 509786.3 | 23102 | 1.64041666667 | 13919 |
| 015067 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593418.4 | 509785.6 | 23104 | 1.64041666667 | 15067 |
| 014100 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:35pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593416.7 | 509784.3 | 23106 | 1.64041666667 | 14100 |
| 013901 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593414.6 | 509783.5 | 23108 | 1.64041666667 | 13901 |
| 014884 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593412.8 | 509782.4 | 23109 | 1.64041666667 | 14884 |
| 014357 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593410.0 | 509781.1 | 23112 | 1.64041666667 | 14357 |
| 014166 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:39pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593407.3 | 509781.2 | 23114 | 1.64041666667 | 14166 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593404.2 | 509780.3 | 23116 | 1.64041666667 | 14283 |
| 014417 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:41pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593402.4 | 509779.2 | 23118 | 1.64041666667 | 14417 |
| 013734 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593399.6 | 509778.3 | 23120 | 1.64041666667 | 13734 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014708 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:43pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593397.2 | 509777.4 | 23122 | 1.64041666667 | 14708 |
| 014100 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593395.1 | 509776.6 | 23124 | 1.64041666667 | 14100 |
| 013811 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593392.8 | 509776.2 | 23125 | 1.64041666667 | 13811 |
| 013881 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593390.1 | 509774.2 | 23128 | 1.64041666667 | 13881 |
| 013958 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:47pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593387.8 | 509772.7 | 23130 | 1.64041666667 | 13958 |
| 014864 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593385.2 | 509771.8 | 23132 | 1.64041666667 | 14864 |
| 015298 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593383.4 | 509770.6 | 23133 | 1.64041666667 | 15298 |
| 014478 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593380.2 | 509769.0 | 23136 | 1.64041666667 | 14478 |
| 014803 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593378.1 | 509768.5 | 23137 | 1.64041666667 | 14803 |
| 014874 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593374.9 | 509766.6 | 23140 | 1.64041666667 | 14874 |
| 016114 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:53pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593372.2 | 509765.6 | 23142 | 1.64041666667 | 16114 |
| 015236 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593369.8 | 509764.8 | 23144 | 1.64041666667 | 15236 |
| 015403 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593367.2 | 509763.6 | 23146 | 1.64041666667 | 15403 |
| 015069 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593364.7 | 509763.1 | 23148 | 1.64041666667 | 15069 |
| 014236 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:57pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593362.0 | 509762.2 | 23150 | 1.64041666667 | 14236 |
| 013670 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593359.5 | 509761.1 | 23152 | 1.64041666667 | 13670 |
| 013704 | 0 | GeoXH 6000 | 08/18/2015 | 12:03:59pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593357.7 | 509760.8 | 23154 | 1.64041666667 | 13704 |
| 014031 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593355.2 | 509759.1 | 23156 | 1.64041666667 | 14031 |
| 014245 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:01pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593352.5 | 509757.7 | 23158 | 1.64041666667 | 14245 |
| 015055 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593349.6 | 509756.8 | 23160 | 1.64041666667 | 15055 |
| 014903 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593347.5 | 509755.6 | 23161 | 1.64041666667 | 14903 |
| 015950 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593344.4 | 509754.8 | 23164 | 1.64041666667 | 15950 |
| 016495 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593341.7 | 509754.4 | 23165 | 1.64041666667 | 16495 |
| 017055 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593339.5 | 509752.9 | 23168 | 1.64041666667 | 17055 |
| 018496 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593338.8 | 509753.7 | 23169 | 1.64041666667 | 18496 |
| 017769 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593339.0 | 509752.7 | 23172 | 1.64041666667 | 17769 |
| 018342 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593338.4 | 509752.2 | 23173 | 1.64041666667 | 18342 |
| 016902 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593337.9 | 509751.3 | 23176 | 1.64041666667 | 16902 |
| 016235 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593337.6 | 509751.8 | 23177 | 1.64041666667 | 16235 |
| 016609 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593338.4 | 509751.3 | 23180 | 1.64041666667 | 16609 |
| 017510 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:13pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593338.7 | 509751.2 | 23182 | 1.64041666667 | 17510 |
| 017342 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593338.4 | 509751.5 | 23184 | 1.64041666667 | 17342 |
| 018252 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593338.1 | 509751.5 | 23186 | 1.64041666667 | 18252 |
| 018022 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593338.2 | 509750.9 | 23188 | 1.64041666667 | 18022 |
| 017322 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:17pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593337.7 | 509750.2 | 23190 | 1.64041666667 | 17322 |
| 016666 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593339.0 | 509749.2 | 23192 | 1.64041666667 | 16666 |
| 016372 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:19pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593339.0 | 509748.4 | 23194 | 1.64041666667 | 16372 |
| 016267 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593338.8 | 509747.9 | 23196 | 1.64041666667 | 16267 |
| 016852 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593337.8 | 509748.3 | 23197 | 1.64041666667 | 16852 |
| 015277 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593336.1 | 509748.6 | 23200 | 1.64041666667 | 15277 |
| 016363 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593336.3 | 509749.4 | 23202 | 1.64041666667 | 16363 |
| 016974 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593336.1 | 509749.9 | 23204 | 1.64041666667 | 16974 |
| 015660 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:25pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593335.4 | 509750.3 | 23206 | 1.64041666667 | 15660 |
| 016609 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593333.5 | 509751.0 | 23208 | 1.64041666667 | 16609 |
| 016047 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:27pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593331.9 | 509750.6 | 23210 | 1.64041666667 | 16047 |
| 016564 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593329.3 | 509749.3 | 23212 | 1.64041666667 | 16564 |
| 016937 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593327.5 | 509748.9 | 23213 | 1.64041666667 | 16937 |
| 017072 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593325.1 | 509746.7 | 23216 | 1.64041666667 | 17072 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016758 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593322.9 | 509745.2 | 23217 | 1.64041666667 | 16758 |
| 016506 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593320.1 | 509743.8 | 23220 | 1.64041666667 | 16506 |
| 015847 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:33pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593318.5 | 509742.0 | 23222 | 1.64041666667 | 15847 |
| 016991 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593316.3 | 509740.3 | 23224 | 1.64041666667 | 16991 |
| 017057 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:35pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593314.4 | 509739.2 | 23226 | 1.64041666667 | 17057 |
| 017417 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593313.8 | 509737.4 | 23228 | 1.64041666667 | 17417 |
| 017927 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593312.7 | 509737.0 | 23229 | 1.64041666667 | 17927 |
| 016834 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593310.0 | 509736.6 | 23232 | 1.64041666667 | 16834 |
| 016556 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593308.5 | 509736.1 | 23233 | 1.64041666667 | 16556 |
| 015695 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593306.9 | 509735.0 | 23236 | 1.64041666667 | 15695 |
| 014858 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:41pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593306.9 | 509733.5 | 23238 | 1.64041666667 | 14858 |
| 014643 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593306.2 | 509732.0 | 23240 | 1.64041666667 | 14643 |
| 015519 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593306.5 | 509730.5 | 23241 | 1.64041666667 | 15519 |
| 014932 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593306.7 | 509728.1 | 23244 | 1.64041666667 | 14932 |
| 014654 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593306.9 | 509726.6 | 23245 | 1.64041666667 | 14654 |
| 014025 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:46pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593308.2 | 509725.2 | 23248 | 1.64041666667 | 14025 |
| 014197 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:46pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593308.5 | 509723.5 | 23249 | 1.64041666667 | 14197 |
| 014338 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:48pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593310.0 | 509722.7 | 23252 | 1.64041666667 | 14338 |
| 014665 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593311.7 | 509723.1 | 23253 | 1.64041666667 | 14665 |
| 015216 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593314.4 | 509724.2 | 23256 | 1.64041666667 | 15216 |
| 014979 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:51pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593316.5 | 509726.2 | 23258 | 1.64041666667 | 14979 |
| 014801 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593318.5 | 509727.7 | 23260 | 1.64041666667 | 14801 |
| 014490 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:53pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593320.5 | 509728.8 | 23262 | 1.64041666667 | 14490 |
| 014218 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593323.3 | 509730.3 | 23264 | 1.64041666667 | 14218 |
| 014080 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593325.5 | 509730.5 | 23266 | 1.64041666667 | 14080 |
| 014925 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593328.2 | 509730.4 | 23268 | 1.64041666667 | 14925 |
| 014830 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593330.8 | 509731.1 | 23269 | 1.64041666667 | 14830 |
| 015737 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593333.9 | 509730.8 | 23272 | 1.64041666667 | 15737 |
| 016224 | 0 | GeoXH 6000 | 08/18/2015 | 12:04:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593336.1 | 509730.8 | 23273 | 1.64041666667 | 16224 |
| 016116 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593338.6 | 509731.8 | 23276 | 1.64041666667 | 16116 |
| 016618 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:01pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593340.8 | 509732.5 | 23278 | 1.64041666667 | 16618 |
| 015715 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593343.3 | 509734.1 | 23280 | 1.64041666667 | 15715 |
| 015927 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593345.5 | 509735.2 | 23281 | 1.64041666667 | 15927 |
| 016639 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593348.4 | 509735.7 | 23284 | 1.64041666667 | 16639 |
| 016064 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593350.8 | 509736.6 | 23285 | 1.64041666667 | 16064 |
| 015996 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593353.1 | 509738.0 | 23288 | 1.64041666667 | 15996 |
| 015935 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593355.0 | 509738.5 | 23289 | 1.64041666667 | 15935 |
| 016808 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593357.4 | 509740.6 | 23292 | 1.64041666667 | 16808 |
| 017352 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:09pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593359.6 | 509742.1 | 23294 | 1.64041666667 | 17352 |
| 017560 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593362.2 | 509743.7 | 23296 | 1.64041666667 | 17560 |
| 016252 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593363.9 | 509745.6 | 23297 | 1.64041666667 | 16252 |
| 015224 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593366.7 | 509746.8 | 23300 | 1.64041666667 | 15224 |
| 015081 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593368.9 | 509747.7 | 23301 | 1.64041666667 | 15081 |
| 014190 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593371.0 | 509749.5 | 23304 | 1.64041666667 | 14190 |
| 014462 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593373.1 | 509750.5 | 23305 | 1.64041666667 | 14462 |
| 016122 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593376.0 | 509752.1 | 23308 | 1.64041666667 | 16122 |
| 015631 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:17pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593378.2 | 509753.7 | 23310 | 1.64041666667 | 15631 |
| 015677 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593380.7 | 509754.6 | 23312 | 1.64041666667 | 15677 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015403 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:19pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593382.7 | 509756.0 | 23314 | 1.64041666667 | 15403 |
| 015144 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593385.7 | 509757.3 | 23316 | 1.64041666667 | 15144 |
| 015764 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:21pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593388.2 | 509757.9 | 23318 | 1.64041666667 | 15764 |
| 015527 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593390.6 | 509759.3 | 23320 | 1.64041666667 | 15527 |
| 015889 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:23pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593393.1 | 509760.4 | 23322 | 1.64041666667 | 15889 |
| 015875 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593395.6 | 509761.0 | 23324 | 1.64041666667 | 15875 |
| 015507 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:25pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593397.5 | 509762.7 | 23326 | 1.64041666667 | 15507 |
| 016162 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:25pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593399.9 | 509763.9 | 23327 | 1.64041666667 | 16162 |
| 014904 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:27pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593402.5 | 509765.3 | 23330 | 1.64041666667 | 14904 |
| 014931 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593405.3 | 509766.9 | 23332 | 1.64041666667 | 14931 |
| 014278 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593407.4 | 509767.3 | 23333 | 1.64041666667 | 14278 |
| 014114 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593409.6 | 509769.2 | 23336 | 1.64041666667 | 14114 |
| 013519 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593411.5 | 509770.6 | 23337 | 1.64041666667 | 13519 |
| 013574 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593414.1 | 509771.9 | 23340 | 1.64041666667 | 13574 |
| 013260 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593415.9 | 509773.5 | 23341 | 1.64041666667 | 13260 |
| 013654 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593418.7 | 509774.2 | 23344 | 1.64041666667 | 13654 |
| 013312 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593420.2 | 509773.3 | 23345 | 1.64041666667 | 13312 |
| 013481 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593422.5 | 509771.9 | 23348 | 1.64041666667 | 13481 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:37pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593423.1 | 509769.9 | 23350 | 1.64041666667 | 13560 |
| 014947 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593424.5 | 509768.2 | 23352 | 1.64041666667 | 14947 |
| 015930 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:39pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593425.4 | 509766.0 | 23354 | 1.64041666667 | 15930 |
| 015463 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593425.2 | 509763.8 | 23356 | 1.64041666667 | 15463 |
| 014623 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:41pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593425.5 | 509761.4 | 23358 | 1.64041666667 | 14623 |
| 015230 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593423.2 | 509759.4 | 23360 | 1.64041666667 | 15230 |
| 015189 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593421.4 | 509758.4 | 23361 | 1.64041666667 | 15189 |
| 015324 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593419.0 | 509757.0 | 23364 | 1.64041666667 | 15324 |
| 015602 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:45pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593417.2 | 509757.0 | 23366 | 1.64041666667 | 15602 |
| 015106 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593414.6 | 509757.1 | 23368 | 1.64041666667 | 15106 |
| 015584 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593412.3 | 509757.0 | 23369 | 1.64041666667 | 15584 |
| 016581 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593410.1 | 509758.1 | 23372 | 1.64041666667 | 16581 |
| 015867 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593408.2 | 509757.5 | 23373 | 1.64041666667 | 15867 |
| 014902 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593405.6 | 509756.7 | 23376 | 1.64041666667 | 14902 |
| 014870 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593403.5 | 509756.2 | 23377 | 1.64041666667 | 14870 |
| 014777 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593401.1 | 509754.6 | 23380 | 1.64041666667 | 14777 |
| 014582 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593398.7 | 509754.1 | 23381 | 1.64041666667 | 14582 |
| 014322 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593395.6 | 509753.0 | 23384 | 1.64041666667 | 14322 |
| 014776 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593393.5 | 509751.6 | 23385 | 1.64041666667 | 14776 |
| 014671 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593390.9 | 509750.8 | 23388 | 1.64041666667 | 14671 |
| 014687 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593389.0 | 509749.8 | 23389 | 1.64041666667 | 14687 |
| 013826 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593386.8 | 509747.8 | 23392 | 1.64041666667 | 13826 |
| 014032 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593384.9 | 509747.2 | 23393 | 1.64041666667 | 14032 |
| 014276 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593382.6 | 509745.5 | 23396 | 1.64041666667 | 14276 |
| 015215 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593380.7 | 509746.1 | 23397 | 1.64041666667 | 15215 |
| 016418 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593377.9 | 509744.8 | 23400 | 1.64041666667 | 16418 |
| 016443 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593375.7 | 509744.1 | 23401 | 1.64041666667 | 16443 |
| 015729 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593372.8 | 509743.4 | 23404 | 1.64041666667 | 15729 |
| 016025 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:05pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593370.9 | 509741.6 | 23406 | 1.64041666667 | 16025 |
| 015584 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593368.6 | 509739.6 | 23408 | 1.64041666667 | 15584 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015801 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593366.8 | 509738.6 | 23409 | 1.64041666667 | 15801 |
| 016875 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:07pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593364.7 | 509736.9 | 23411 | 1.64041666667 | 16875 |
| 016887 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593362.9 | 509735.4 | 23413 | 1.64041666667 | 16887 |
| 017029 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:10pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593360.2 | 509733.8 | 23416 | 1.64041666667 | 17029 |
| 017326 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593358.3 | 509732.2 | 23417 | 1.64041666667 | 17326 |
| 017096 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593355.3 | 509730.7 | 23420 | 1.64041666667 | 17096 |
| 016554 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593353.1 | 509730.2 | 23421 | 1.64041666667 | 16554 |
| 017164 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593350.5 | 509728.3 | 23424 | 1.64041666667 | 17164 |
| 017844 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593347.6 | 509726.8 | 23426 | 1.64041666667 | 17844 |
| 017725 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593344.9 | 509726.0 | 23428 | 1.64041666667 | 17725 |
| 017110 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593342.8 | 509725.0 | 23429 | 1.64041666667 | 17110 |
| 016202 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593339.8 | 509724.2 | 23432 | 1.64041666667 | 16202 |
| 015751 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593337.5 | 509723.9 | 23433 | 1.64041666667 | 15751 |
| 015115 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593334.1 | 509722.7 | 23436 | 1.64041666667 | 15115 |
| 014337 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593332.1 | 509721.8 | 23437 | 1.64041666667 | 14337 |
| 015279 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593329.1 | 509720.7 | 23440 | 1.64041666667 | 15279 |
| 015150 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593327.3 | 509719.4 | 23441 | 1.64041666667 | 15150 |
| 014926 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593324.2 | 509718.7 | 23444 | 1.64041666667 | 14926 |
| 015123 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:25pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593322.3 | 509718.5 | 23446 | 1.64041666667 | 15123 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:26pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593321.9 | 509716.5 | 23448 | 1.64041666667 | 13974 |
| 014033 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:27pm | Sensor | 1797-S0026-905-G-ACK | 6804.4 | 1593321.7 | 509714.4 | 23450 | 1.64041666667 | 14033 |
| 014598 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:28pm | Sensor | 1797-S0026-905-G-ACK | 6804.5 | 1593322.4 | 509712.7 | 23452 | 1.64041666667 | 14598 |
| 014729 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:29pm | Sensor | 1797-S0026-905-G-ACK | 6804.8 | 1593322.8 | 509710.3 | 23454 | 1.64041666667 | 14729 |
| 014172 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:30pm | Sensor | 1797-S0026-905-G-ACK | 6805.3 | 1593323.0 | 509708.0 | 23456 | 1.64041666667 | 14172 |
| 014002 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:30pm | Sensor | 1797-S0026-905-G-ACK | 6805.3 | 1593324.1 | 509707.0 | 23457 | 1.64041666667 | 14002 |
| 013883 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:32pm | Sensor | 1797-S0026-905-G-ACK | 6805.4 | 1593325.4 | 509705.6 | 23460 | 1.64041666667 | 13883 |
| 013142 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:33pm | Sensor | 1797-S0026-905-G-ACK | 6805.3 | 1593326.9 | 509705.7 | 23462 | 1.64041666667 | 13142 |
| 014090 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:34pm | Sensor | 1797-S0026-905-G-ACK | 6804.9 | 1593329.2 | 509706.8 | 23464 | 1.64041666667 | 14090 |
| 014720 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:35pm | Sensor | 1797-S0026-905-G-ACK | 6804.9 | 1593331.1 | 509707.2 | 23466 | 1.64041666667 | 14720 |
| 015247 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:36pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593333.1 | 509708.9 | 23468 | 1.64041666667 | 15247 |
| 015154 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:36pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593335.1 | 509710.2 | 23469 | 1.64041666667 | 15154 |
| 014794 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:38pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593337.5 | 509711.1 | 23472 | 1.64041666667 | 14794 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593339.3 | 509712.6 | 23473 | 1.64041666667 | 14314 |
| 013369 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593342.2 | 509713.5 | 23476 | 1.64041666667 | 13369 |
| 014660 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593344.6 | 509714.3 | 23477 | 1.64041666667 | 14660 |
| 014238 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593347.0 | 509715.8 | 23480 | 1.64041666667 | 14238 |
| 014272 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:43pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593349.8 | 509717.0 | 23482 | 1.64041666667 | 14272 |
| 015303 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593352.6 | 509718.3 | 23484 | 1.64041666667 | 15303 |
| 016835 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593354.0 | 509720.0 | 23485 | 1.64041666667 | 16835 |
| 017359 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593356.9 | 509721.2 | 23488 | 1.64041666667 | 17359 |
| 018570 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593359.0 | 509721.8 | 23489 | 1.64041666667 | 18570 |
| 017585 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:48pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593361.3 | 509723.1 | 23492 | 1.64041666667 | 17585 |
| 017249 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:49pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593363.7 | 509723.3 | 23494 | 1.64041666667 | 17249 |
| 017120 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:50pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593366.4 | 509724.2 | 23496 | 1.64041666667 | 17120 |
| 016267 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:50pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593368.8 | 509725.1 | 23497 | 1.64041666667 | 16267 |
| 017093 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:52pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593371.8 | 509725.5 | 23500 | 1.64041666667 | 17093 |
| 017017 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:53pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593374.2 | 509726.5 | 23502 | 1.64041666667 | 17017 |
| 016614 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593377.1 | 509728.1 | 23504 | 1.64041666667 | 16614 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015975 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:55pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593379.4 | 509729.0 | 23506 | 1.64041666667 | 15975 |
| 016081 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593381.8 | 509731.1 | 23508 | 1.64041666667 | 16081 |
| 015301 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593384.3 | 509732.4 | 23509 | 1.64041666667 | 15301 |
| 014793 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593387.3 | 509733.2 | 23512 | 1.64041666667 | 14793 |
| 014898 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593389.3 | 509734.6 | 23513 | 1.64041666667 | 14898 |
| 014448 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593391.9 | 509736.6 | 23516 | 1.64041666667 | 14448 |
| 015259 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:01pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593393.9 | 509737.7 | 23518 | 1.64041666667 | 15259 |
| 014471 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593395.9 | 509739.9 | 23520 | 1.64041666667 | 14471 |
| 013997 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593397.6 | 509741.1 | 23521 | 1.64041666667 | 13997 |
| 014023 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593399.7 | 509743.3 | 23524 | 1.64041666667 | 14023 |
| 014428 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:05pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593401.7 | 509745.7 | 23526 | 1.64041666667 | 14428 |
| 014580 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593403.7 | 509746.9 | 23528 | 1.64041666667 | 14580 |
| 014951 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593405.9 | 509748.4 | 23529 | 1.64041666667 | 14951 |
| 015475 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593408.1 | 509750.7 | 23532 | 1.64041666667 | 15475 |
| 014974 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:09pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593410.2 | 509751.8 | 23534 | 1.64041666667 | 14974 |
| 015008 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593413.0 | 509753.8 | 23536 | 1.64041666667 | 15008 |
| 015417 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:11pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593414.6 | 509755.3 | 23538 | 1.64041666667 | 15417 |
| 015437 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593417.2 | 509755.1 | 23540 | 1.64041666667 | 15437 |
| 016108 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:13pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593420.0 | 509754.7 | 23542 | 1.64041666667 | 16108 |
| 016178 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593422.9 | 509754.5 | 23544 | 1.64041666667 | 16178 |
| 015603 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593425.0 | 509754.2 | 23546 | 1.64041666667 | 15603 |
| 014784 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593427.4 | 509753.8 | 23548 | 1.64041666667 | 14784 |
| 014593 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:17pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593429.4 | 509755.0 | 23550 | 1.64041666667 | 14593 |
| 015483 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593431.8 | 509755.8 | 23552 | 1.64041666667 | 15483 |
| 014844 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:19pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593433.8 | 509755.9 | 23554 | 1.64041666667 | 14844 |
| 014800 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593436.4 | 509756.1 | 23556 | 1.64041666667 | 14800 |
| 015150 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593438.2 | 509755.1 | 23557 | 1.64041666667 | 15150 |
| 014789 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593440.5 | 509753.5 | 23560 | 1.64041666667 | 14789 |
| 015946 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593441.6 | 509751.4 | 23562 | 1.64041666667 | 15946 |
| 015210 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593441.5 | 509749.2 | 23564 | 1.64041666667 | 15210 |
| 015275 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593442.6 | 509747.6 | 23565 | 1.64041666667 | 15275 |
| 014247 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593441.0 | 509746.0 | 23568 | 1.64041666667 | 14247 |
| 014119 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593439.3 | 509744.6 | 23569 | 1.64041666667 | 14119 |
| 013499 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593436.1 | 509743.2 | 23572 | 1.64041666667 | 13499 |
| 015581 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:29pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593434.2 | 509742.8 | 23574 | 1.64041666667 | 15581 |
| 014966 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593431.9 | 509741.0 | 23576 | 1.64041666667 | 14966 |
| 014666 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593430.0 | 509740.0 | 23577 | 1.64041666667 | 14666 |
| 014100 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593427.4 | 509738.8 | 23580 | 1.64041666667 | 14100 |
| 014478 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593425.9 | 509737.4 | 23581 | 1.64041666667 | 14478 |
| 013844 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593423.4 | 509736.2 | 23584 | 1.64041666667 | 13844 |
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:35pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593421.3 | 509734.7 | 23586 | 1.64041666667 | 13277 |
| 013693 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593419.3 | 509732.9 | 23588 | 1.64041666667 | 13693 |
| 014617 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593417.5 | 509731.8 | 23589 | 1.64041666667 | 14617 |
| 015625 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593414.9 | 509730.0 | 23592 | 1.64041666667 | 15625 |
| 016476 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593413.1 | 509728.7 | 23593 | 1.64041666667 | 16476 |
| 017915 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:39pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593410.8 | 509727.6 | 23595 | 1.64041666667 | 17915 |
| 019707 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593409.0 | 509726.2 | 23597 | 1.64041666667 | 19707 |
| 019762 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593407.5 | 509725.6 | 23600 | 1.64041666667 | 19762 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 020356 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 23601 | 1.64041666667 | 20356 |
| 019190 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:43pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.3 | 509725.8 | 23603 | 1.64041666667 | 19190 |
| 019592 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:45pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593405.3 | 509726.2 | 23606 | 1.64041666667 | 19592 |
| 019233 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593405.7 | 509725.9 | 23608 | 1.64041666667 | 19233 |
| 020291 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593405.5 | 509726.2 | 23609 | 1.64041666667 | 20291 |
| 020151 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.3 | 509725.4 | 23612 | 1.64041666667 | 20151 |
| 019825 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.8 | 509725.8 | 23613 | 1.64041666667 | 19825 |
| 021171 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.8 | 509725.1 | 23616 | 1.64041666667 | 21171 |
| 020511 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.1 | 23617 | 1.64041666667 | 20511 |
| 020245 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.5 | 509725.0 | 23620 | 1.64041666667 | 20245 |
| 020710 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.5 | 509725.0 | 23621 | 1.64041666667 | 20710 |
| 019809 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509724.6 | 23624 | 1.64041666667 | 19809 |
| 019520 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:55pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.6 | 509724.3 | 23626 | 1.64041666667 | 19520 |
| 020220 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.9 | 509724.4 | 23628 | 1.64041666667 | 20220 |
| 020336 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.9 | 509724.4 | 23629 | 1.64041666667 | 20336 |
| 021046 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.8 | 509724.2 | 23632 | 1.64041666667 | 21046 |
| 020921 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.9 | 509724.4 | 23633 | 1.64041666667 | 20921 |
| 019868 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.7 | 509724.9 | 23636 | 1.64041666667 | 19868 |
| 019973 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:01pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.3 | 509726.3 | 23638 | 1.64041666667 | 19973 |
| 019845 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.1 | 509726.5 | 23640 | 1.64041666667 | 19845 |
| 020965 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.2 | 509726.5 | 23641 | 1.64041666667 | 20965 |
| 020035 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593408.0 | 509725.3 | 23644 | 1.64041666667 | 20035 |
| 018995 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593409.6 | 509725.5 | 23645 | 1.64041666667 | 18995 |
| 018649 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593410.5 | 509724.2 | 23648 | 1.64041666667 | 18649 |
| 017990 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:06pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593409.5 | 509723.6 | 23649 | 1.64041666667 | 17990 |
| 018122 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:08pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593407.3 | 509722.3 | 23652 | 1.64041666667 | 18122 |
| 017768 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593404.8 | 509722.4 | 23653 | 1.64041666667 | 17768 |
| 018192 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:09pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593402.0 | 509721.9 | 23655 | 1.64041666667 | 18192 |
| 018970 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:10pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593399.6 | 509720.9 | 23657 | 1.64041666667 | 18970 |
| 017496 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593396.2 | 509720.4 | 23660 | 1.64041666667 | 17496 |
| 017409 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:12pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593393.7 | 509720.5 | 23661 | 1.64041666667 | 17409 |
| 016752 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:13pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593391.6 | 509719.1 | 23663 | 1.64041666667 | 16752 |
| 015078 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:14pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593389.6 | 509718.3 | 23665 | 1.64041666667 | 15078 |
| 015831 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:16pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593386.5 | 509716.5 | 23668 | 1.64041666667 | 15831 |
| 016322 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:17pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593384.0 | 509715.1 | 23670 | 1.64041666667 | 16322 |
| 016276 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:18pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593381.3 | 509714.3 | 23672 | 1.64041666667 | 16276 |
| 017338 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593378.7 | 509713.3 | 23673 | 1.64041666667 | 17338 |
| 017387 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593375.9 | 509711.6 | 23676 | 1.64041666667 | 17387 |
| 017085 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593374.0 | 509711.4 | 23677 | 1.64041666667 | 17085 |
| 017425 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:22pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593372.3 | 509711.3 | 23680 | 1.64041666667 | 17425 |
| 016949 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593370.9 | 509709.5 | 23682 | 1.64041666667 | 16949 |
| 015534 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593368.9 | 509708.4 | 23684 | 1.64041666667 | 15534 |
| 015367 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593367.2 | 509707.1 | 23685 | 1.64041666667 | 15367 |
| 014764 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593365.1 | 509706.6 | 23688 | 1.64041666667 | 14764 |
| 014515 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:27pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593364.0 | 509705.0 | 23690 | 1.64041666667 | 14515 |
| 014239 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593361.9 | 509703.4 | 23692 | 1.64041666667 | 14239 |
| 014827 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:28pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593359.9 | 509701.8 | 23693 | 1.64041666667 | 14827 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:30pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593358.3 | 509700.1 | 23696 | 1.64041666667 | 14482 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014596 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:30pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593356.1 | 509699.4 | 23697 | 1.64041666667 | 14596 |
| 014525 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:32pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593353.6 | 509697.7 | 23700 | 1.64041666667 | 14525 |
| 015678 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:32pm | Sensor | 1797-S0026-905-G-ACK | 6804.8 | 1593352.3 | 509696.3 | 23701 | 1.64041666667 | 15678 |
| 015734 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:33pm | Sensor | 1797-S0026-905-G-ACK | 6805.2 | 1593350.2 | 509695.2 | 23703 | 1.64041666667 | 15734 |
| 015330 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:34pm | Sensor | 1797-S0026-905-G-ACK | 6805.5 | 1593347.8 | 509693.9 | 23705 | 1.64041666667 | 15330 |
| 014225 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:35pm | Sensor | 1797-S0026-905-G-ACK | 6805.8 | 1593345.8 | 509692.3 | 23707 | 1.64041666667 | 14225 |
| 013919 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:36pm | Sensor | 1797-S0026-905-G-ACK | 6806.0 | 1593343.6 | 509691.5 | 23709 | 1.64041666667 | 13919 |
| 013717 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:38pm | Sensor | 1797-S0026-905-G-ACK | 6806.2 | 1593341.2 | 509690.4 | 23712 | 1.64041666667 | 13717 |
| 013806 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:38pm | Sensor | 1797-S0026-905-G-ACK | 6806.4 | 1593339.7 | 509689.2 | 23713 | 1.64041666667 | 13806 |
| 013623 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:40pm | Sensor | 1797-S0026-905-G-ACK | 6806.7 | 1593337.3 | 509688.0 | 23716 | 1.64041666667 | 13623 |
| 013325 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:41pm | Sensor | 1797-S0026-905-G-ACK | 6806.8 | 1593336.1 | 509686.5 | 23718 | 1.64041666667 | 13325 |
| 013818 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:42pm | Sensor | 1797-S0026-905-G-ACK | 6807.3 | 1593334.3 | 509684.8 | 23720 | 1.64041666667 | 13818 |
| 013795 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:42pm | Sensor | 1797-S0026-905-G-ACK | 6807.7 | 1593332.8 | 509684.0 | 23721 | 1.64041666667 | 13795 |
| 012964 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:44pm | Sensor | 1797-S0026-905-G-ACK | 6807.9 | 1593333.0 | 509682.8 | 23724 | 1.64041666667 | 12964 |
| 012797 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:44pm | Sensor | 1797-S0026-905-G-ACK | 6808.1 | 1593333.6 | 509681.5 | 23725 | 1.64041666667 | 12797 |
| 012366 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:46pm | Sensor | 1797-S0026-905-G-ACK | 6808.1 | 1593335.1 | 509680.1 | 23728 | 1.64041666667 | 12366 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:46pm | Sensor | 1797-S0026-905-G-ACK | 6808.2 | 1593336.3 | 509678.3 | 23729 | 1.64041666667 | 13278 |
| 013709 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:48pm | Sensor | 1797-S0026-905-G-ACK | 6808.7 | 1593337.2 | 509676.3 | 23732 | 1.64041666667 | 13709 |
| 013606 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:48pm | Sensor | 1797-S0026-905-G-ACK | 6808.8 | 1593338.5 | 509675.0 | 23733 | 1.64041666667 | 13606 |
| 013241 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:50pm | Sensor | 1797-S0026-905-G-ACK | 6809.2 | 1593339.1 | 509673.4 | 23736 | 1.64041666667 | 13241 |
| 013155 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:50pm | Sensor | 1797-S0026-905-G-ACK | 6809.1 | 1593339.9 | 509673.2 | 23737 | 1.64041666667 | 13155 |
| 013602 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:52pm | Sensor | 1797-S0026-905-G-ACK | 6808.6 | 1593342.4 | 509673.8 | 23740 | 1.64041666667 | 13602 |
| 014236 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:52pm | Sensor | 1797-S0026-905-G-ACK | 6808.5 | 1593344.4 | 509674.3 | 23741 | 1.64041666667 | 14236 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:54pm | Sensor | 1797-S0026-905-G-ACK | 6807.9 | 1593346.0 | 509676.3 | 23744 | 1.64041666667 | 14158 |
| 014698 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:55pm | Sensor | 1797-S0026-905-G-ACK | 6807.3 | 1593348.2 | 509677.7 | 23746 | 1.64041666667 | 14698 |
| 013885 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:56pm | Sensor | 1797-S0026-905-G-ACK | 6807.0 | 1593350.7 | 509679.1 | 23748 | 1.64041666667 | 13885 |
| 013653 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:56pm | Sensor | 1797-S0026-905-G-ACK | 6806.8 | 1593352.6 | 509680.7 | 23749 | 1.64041666667 | 13653 |
| 013042 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:58pm | Sensor | 1797-S0026-905-G-ACK | 6806.4 | 1593355.5 | 509682.2 | 23752 | 1.64041666667 | 13042 |
| 013021 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:58pm | Sensor | 1797-S0026-905-G-ACK | 6806.6 | 1593357.8 | 509682.6 | 23753 | 1.64041666667 | 13021 |
| 013541 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:00pm | Sensor | 1797-S0026-905-G-ACK | 6806.2 | 1593360.2 | 509684.4 | 23756 | 1.64041666667 | 13541 |
| 014164 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:00pm | Sensor | 1797-S0026-905-G-ACK | 6805.7 | 1593362.0 | 509685.6 | 23757 | 1.64041666667 | 14164 |
| 015865 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:02pm | Sensor | 1797-S0026-905-G-ACK | 6805.5 | 1593364.6 | 509686.5 | 23760 | 1.64041666667 | 15865 |
| 016281 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:02pm | Sensor | 1797-S0026-905-G-ACK | 6805.1 | 1593366.0 | 509688.3 | 23761 | 1.64041666667 | 16281 |
| 015751 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:04pm | Sensor | 1797-S0026-905-G-ACK | 6804.4 | 1593368.7 | 509690.2 | 23764 | 1.64041666667 | 15751 |
| 015572 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:04pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593370.4 | 509691.8 | 23765 | 1.64041666667 | 15572 |
| 014969 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593372.0 | 509694.3 | 23768 | 1.64041666667 | 14969 |
| 015290 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593373.7 | 509695.3 | 23769 | 1.64041666667 | 15290 |
| 014053 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593375.9 | 509697.5 | 23772 | 1.64041666667 | 14053 |
| 015015 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593377.1 | 509699.8 | 23773 | 1.64041666667 | 15015 |
| 015128 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593379.5 | 509702.4 | 23776 | 1.64041666667 | 15128 |
| 014884 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593380.6 | 509704.8 | 23777 | 1.64041666667 | 14884 |
| 015377 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593383.5 | 509706.9 | 23780 | 1.64041666667 | 15377 |
| 015722 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:13pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593385.8 | 509708.1 | 23782 | 1.64041666667 | 15722 |
| 016396 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593388.2 | 509710.1 | 23784 | 1.64041666667 | 16396 |
| 016130 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593390.6 | 509711.1 | 23786 | 1.64041666667 | 16130 |
| 016183 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:16pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593393.5 | 509710.4 | 23788 | 1.64041666667 | 16183 |
| 016010 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:16pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593395.7 | 509711.0 | 23789 | 1.64041666667 | 16010 |
| 016386 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:17pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593398.8 | 509711.4 | 23791 | 1.64041666667 | 16386 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016109 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:18pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593401.2 | 509711.4 | 23793 | 1.64041666667 | 16109 |
| 015759 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:20pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593404.1 | 509712.4 | 23796 | 1.64041666667 | 15759 |
| 016897 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:20pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593406.2 | 509712.5 | 23797 | 1.64041666667 | 16897 |
| 017019 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593408.9 | 509714.0 | 23800 | 1.64041666667 | 17019 |
| 017651 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593410.7 | 509715.9 | 23802 | 1.64041666667 | 17651 |
| 016731 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593413.5 | 509717.0 | 23804 | 1.64041666667 | 16731 |
| 017008 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593415.8 | 509718.1 | 23805 | 1.64041666667 | 17008 |
| 018440 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593417.9 | 509720.0 | 23808 | 1.64041666667 | 18440 |
| 020077 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593420.3 | 509720.8 | 23809 | 1.64041666667 | 20077 |
| 019761 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:27pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593423.0 | 509721.8 | 23811 | 1.64041666667 | 19761 |
| 019185 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593424.8 | 509723.3 | 23813 | 1.64041666667 | 19185 |
| 018299 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593427.5 | 509724.7 | 23816 | 1.64041666667 | 18299 |
| 017081 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593429.6 | 509726.4 | 23817 | 1.64041666667 | 17081 |
| 015653 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593431.5 | 509728.8 | 23820 | 1.64041666667 | 15653 |
| 014662 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:33pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593433.3 | 509729.9 | 23822 | 1.64041666667 | 14662 |
| 014877 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593435.9 | 509732.0 | 23824 | 1.64041666667 | 14877 |
| 014271 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593437.8 | 509733.6 | 23825 | 1.64041666667 | 14271 |
| 013660 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593440.6 | 509734.3 | 23828 | 1.64041666667 | 13660 |
| 013406 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593442.7 | 509735.5 | 23829 | 1.64041666667 | 13406 |
| 014471 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593445.4 | 509737.4 | 23832 | 1.64041666667 | 14471 |
| 013937 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593447.5 | 509736.8 | 23833 | 1.64041666667 | 13937 |
| 015317 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593450.3 | 509735.5 | 23836 | 1.64041666667 | 15317 |
| 014653 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593451.7 | 509733.8 | 23837 | 1.64041666667 | 14653 |
| 014632 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593452.8 | 509731.3 | 23840 | 1.64041666667 | 14632 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593454.0 | 509729.8 | 23841 | 1.64041666667 | 14081 |
| 014303 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593454.9 | 509727.0 | 23844 | 1.64041666667 | 14303 |
| 014803 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593455.4 | 509725.0 | 23845 | 1.64041666667 | 14803 |
| 014911 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593455.6 | 509721.9 | 23848 | 1.64041666667 | 14911 |
| 015385 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593454.1 | 509720.8 | 23849 | 1.64041666667 | 15385 |
| 014991 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593451.4 | 509719.8 | 23852 | 1.64041666667 | 14991 |
| 015085 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593449.2 | 509718.5 | 23853 | 1.64041666667 | 15085 |
| 014883 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593446.2 | 509717.6 | 23856 | 1.64041666667 | 14883 |
| 016314 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:51pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593443.9 | 509717.2 | 23858 | 1.64041666667 | 16314 |
| 016421 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593441.2 | 509716.1 | 23860 | 1.64041666667 | 16421 |
| 017689 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593439.0 | 509716.1 | 23861 | 1.64041666667 | 17689 |
| 018568 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593436.1 | 509715.8 | 23864 | 1.64041666667 | 18568 |
| 017659 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:55pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593433.4 | 509715.1 | 23866 | 1.64041666667 | 17659 |
| 016623 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593430.5 | 509715.7 | 23868 | 1.64041666667 | 16623 |
| 016190 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593428.3 | 509715.9 | 23869 | 1.64041666667 | 16190 |
| 016757 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593424.8 | 509715.6 | 23872 | 1.64041666667 | 16757 |
| 018396 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:59pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593422.8 | 509716.1 | 23874 | 1.64041666667 | 18396 |
| 017960 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593420.6 | 509715.7 | 23876 | 1.64041666667 | 17960 |
| 017212 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:01pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593418.8 | 509714.8 | 23878 | 1.64041666667 | 17212 |
| 016837 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593416.4 | 509713.3 | 23880 | 1.64041666667 | 16837 |
| 015583 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593415.1 | 509712.0 | 23881 | 1.64041666667 | 15583 |
| 015995 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:03pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593413.5 | 509709.8 | 23883 | 1.64041666667 | 15995 |
| 014810 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:04pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593411.7 | 509708.5 | 23885 | 1.64041666667 | 14810 |
| 015403 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:05pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593409.5 | 509706.5 | 23887 | 1.64041666667 | 15403 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016036 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593407.2 | 509705.3 | 23889 | 1.64041666667 | 16036 |
| 017023 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:07pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593404.4 | 509704.7 | 23891 | 1.64041666667 | 17023 |
| 016108 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593402.3 | 509703.4 | 23893 | 1.64041666667 | 16108 |
| 016463 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593399.0 | 509702.3 | 23896 | 1.64041666667 | 16463 |
| 016070 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:11pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593396.5 | 509702.2 | 23898 | 1.64041666667 | 16070 |
| 016164 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593394.1 | 509700.9 | 23900 | 1.64041666667 | 16164 |
| 016832 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593392.4 | 509700.6 | 23901 | 1.64041666667 | 16832 |
| 016233 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593390.6 | 509698.2 | 23904 | 1.64041666667 | 16233 |
| 016241 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593388.9 | 509697.8 | 23905 | 1.64041666667 | 16241 |
| 015405 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593386.5 | 509696.4 | 23908 | 1.64041666667 | 15405 |
| 014740 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593384.5 | 509697.0 | 23909 | 1.64041666667 | 14740 |
| 014164 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593382.1 | 509697.3 | 23912 | 1.64041666667 | 14164 |
| 014304 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593380.1 | 509697.1 | 23913 | 1.64041666667 | 14304 |
| 014346 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593377.4 | 509695.2 | 23916 | 1.64041666667 | 14346 |
| 014497 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593376.5 | 509693.2 | 23917 | 1.64041666667 | 14497 |
| 014807 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593374.6 | 509691.2 | 23920 | 1.64041666667 | 14807 |
| 015266 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:22pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593373.1 | 509690.5 | 23921 | 1.64041666667 | 15266 |
| 016245 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:24pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593371.3 | 509688.2 | 23924 | 1.64041666667 | 16245 |
| 015677 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:24pm | Sensor | 1797-S0026-905-G-ACK | 6804.7 | 1593369.4 | 509686.9 | 23925 | 1.64041666667 | 15677 |
| 016738 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:26pm | Sensor | 1797-S0026-905-G-ACK | 6805.0 | 1593366.4 | 509685.7 | 23928 | 1.64041666667 | 16738 |
| 016285 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:26pm | Sensor | 1797-S0026-905-G-ACK | 6805.6 | 1593364.7 | 509684.4 | 23929 | 1.64041666667 | 16285 |
| 015025 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:27pm | Sensor | 1797-S0026-905-G-ACK | 6805.8 | 1593363.4 | 509682.2 | 23931 | 1.64041666667 | 15025 |
| 013777 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:28pm | Sensor | 1797-S0026-905-G-ACK | 6806.2 | 1593361.3 | 509681.0 | 23933 | 1.64041666667 | 13777 |
| 013314 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:29pm | Sensor | 1797-S0026-905-G-ACK | 6806.5 | 1593359.1 | 509679.3 | 23935 | 1.64041666667 | 13314 |
| 012544 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:30pm | Sensor | 1797-S0026-905-G-ACK | 6806.7 | 1593357.1 | 509677.2 | 23937 | 1.64041666667 | 12544 |
| 013431 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:32pm | Sensor | 1797-S0026-905-G-ACK | 6806.8 | 1593354.7 | 509675.9 | 23940 | 1.64041666667 | 13431 |
| 014215 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:32pm | Sensor | 1797-S0026-905-G-ACK | 6807.1 | 1593353.3 | 509674.6 | 23941 | 1.64041666667 | 14215 |
| 014191 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:34pm | Sensor | 1797-S0026-905-G-ACK | 6807.5 | 1593351.0 | 509672.6 | 23944 | 1.64041666667 | 14191 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:34pm | Sensor | 1797-S0026-905-G-ACK | 6808.0 | 1593349.1 | 509672.0 | 23945 | 1.64041666667 | 14072 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:35pm | Sensor | 1797-S0026-905-G-ACK | 6808.3 | 1593347.7 | 509670.5 | 23947 | 1.64041666667 | 13915 |
| 013850 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:36pm | Sensor | 1797-S0026-905-G-ACK | 6808.7 | 1593345.7 | 509669.5 | 23949 | 1.64041666667 | 13850 |
| 014390 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:37pm | Sensor | 1797-S0026-905-G-ACK | 6809.4 | 1593343.8 | 509668.3 | 23951 | 1.64041666667 | 14390 |
| 015084 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:38pm | Sensor | 1797-S0026-905-G-ACK | 6809.7 | 1593343.9 | 509668.2 | 23953 | 1.64041666667 | 15084 |
| 015782 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:40pm | Sensor | 1797-S0026-905-G-ACK | 6809.7 | 1593343.3 | 509667.0 | 23956 | 1.64041666667 | 15782 |
| 016107 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:40pm | Sensor | 1797-S0026-905-G-ACK | 6809.7 | 1593344.7 | 509666.0 | 23957 | 1.64041666667 | 16107 |
| 015773 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:42pm | Sensor | 1797-S0026-905-G-ACK | 6809.4 | 1593346.9 | 509664.3 | 23960 | 1.64041666667 | 15773 |
| 015652 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:42pm | Sensor | 1797-S0026-905-G-ACK | 6809.5 | 1593348.3 | 509663.3 | 23961 | 1.64041666667 | 15652 |
| 014722 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:44pm | Sensor | 1797-S0026-905-G-ACK | 6809.6 | 1593350.9 | 509662.8 | 23964 | 1.64041666667 | 14722 |
| 015383 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:44pm | Sensor | 1797-S0026-905-G-ACK | 6809.7 | 1593352.3 | 509661.6 | 23965 | 1.64041666667 | 15383 |
| 016123 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:46pm | Sensor | 1797-S0026-905-G-ACK | 6809.6 | 1593354.7 | 509660.6 | 23968 | 1.64041666667 | 16123 |
| 015872 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:46pm | Sensor | 1797-S0026-905-G-ACK | 6809.7 | 1593356.5 | 509660.1 | 23969 | 1.64041666667 | 15872 |
| 015325 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:48pm | Sensor | 1797-S0026-905-G-ACK | 6809.9 | 1593358.9 | 509660.3 | 23972 | 1.64041666667 | 15325 |
| 014193 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:48pm | Sensor | 1797-S0026-905-G-ACK | 6809.3 | 1593360.4 | 509661.0 | 23973 | 1.64041666667 | 14193 |
| 014058 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:50pm | Sensor | 1797-S0026-905-G-ACK | 6808.5 | 1593363.0 | 509662.2 | 23976 | 1.64041666667 | 14058 |
| 013263 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:51pm | Sensor | 1797-S0026-905-G-ACK | 6808.4 | 1593365.5 | 509663.0 | 23978 | 1.64041666667 | 13263 |
| 013655 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:52pm | Sensor | 1797-S0026-905-G-ACK | 6807.7 | 1593367.8 | 509664.9 | 23980 | 1.64041666667 | 13655 |
| 013223 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:52pm | Sensor | 1797-S0026-905-G-ACK | 6807.2 | 1593369.7 | 509666.3 | 23981 | 1.64041666667 | 13223 |
| 013678 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:54pm | Sensor | 1797-S0026-905-G-ACK | 6807.3 | 1593372.5 | 509667.5 | 23984 | 1.64041666667 | 13678 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013641 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:54pm | Sensor | 1797-S0026-905-G-ACK | 6807.1 | 1593373.9 | 509669.2 | 23985 | 1.64041666667 | 13641 |
| 013493 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:56pm | Sensor | 1797-S0026-905-G-ACK | 6806.4 | 1593376.7 | 509671.1 | 23988 | 1.64041666667 | 13493 |
| 013335 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:56pm | Sensor | 1797-S0026-905-G-ACK | 6806.4 | 1593378.5 | 509671.8 | 23989 | 1.64041666667 | 13335 |
| 013831 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:58pm | Sensor | 1797-S0026-905-G-ACK | 6806.0 | 1593381.1 | 509673.8 | 23992 | 1.64041666667 | 13831 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:58pm | Sensor | 1797-S0026-905-G-ACK | 6805.6 | 1593383.1 | 509674.8 | 23993 | 1.64041666667 | 14072 |
| 013578 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:00pm | Sensor | 1797-S0026-905-G-ACK | 6805.1 | 1593386.1 | 509676.3 | 23996 | 1.64041666667 | 13578 |
| 014245 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:00pm | Sensor | 1797-S0026-905-G-ACK | 6805.0 | 1593388.5 | 509677.9 | 23997 | 1.64041666667 | 14245 |
| 014523 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:02pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593391.7 | 509679.2 | 24000 | 1.64041666667 | 14523 |
| 014941 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:03pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593394.0 | 509679.8 | 24002 | 1.64041666667 | 14941 |
| 014779 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593396.6 | 509681.5 | 24004 | 1.64041666667 | 14779 |
| 014711 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593398.7 | 509682.4 | 24005 | 1.64041666667 | 14711 |
| 014515 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:05pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593401.1 | 509683.9 | 24007 | 1.64041666667 | 14515 |
| 016219 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593403.1 | 509685.8 | 24009 | 1.64041666667 | 16219 |
| 015956 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:07pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593405.8 | 509686.8 | 24011 | 1.64041666667 | 15956 |
| 016137 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593407.9 | 509688.1 | 24013 | 1.64041666667 | 16137 |
| 015520 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:09pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593410.5 | 509690.0 | 24015 | 1.64041666667 | 15520 |
| 016552 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593412.8 | 509690.9 | 24017 | 1.64041666667 | 16552 |
| 017493 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593415.4 | 509692.6 | 24020 | 1.64041666667 | 17493 |
| 017670 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593417.6 | 509694.1 | 24021 | 1.64041666667 | 17670 |
| 017612 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:14pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593420.2 | 509695.3 | 24024 | 1.64041666667 | 17612 |
| 017226 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:15pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593422.4 | 509696.9 | 24026 | 1.64041666667 | 17226 |
| 015787 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:16pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593425.5 | 509698.2 | 24028 | 1.64041666667 | 15787 |
| 014895 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:16pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593427.5 | 509698.7 | 24029 | 1.64041666667 | 14895 |
| 014783 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:18pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593430.1 | 509700.2 | 24032 | 1.64041666667 | 14783 |
| 015613 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593432.6 | 509701.5 | 24033 | 1.64041666667 | 15613 |
| 015075 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593435.1 | 509702.4 | 24036 | 1.64041666667 | 15075 |
| 014442 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593437.2 | 509704.1 | 24037 | 1.64041666667 | 14442 |
| 014536 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593439.5 | 509706.2 | 24040 | 1.64041666667 | 14536 |
| 014911 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593441.7 | 509707.9 | 24042 | 1.64041666667 | 14911 |
| 015422 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593443.7 | 509709.7 | 24044 | 1.64041666667 | 15422 |
| 016902 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593445.5 | 509711.7 | 24045 | 1.64041666667 | 16902 |
| 016190 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593448.6 | 509712.8 | 24048 | 1.64041666667 | 16190 |
| 014904 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593451.3 | 509713.3 | 24049 | 1.64041666667 | 14904 |
| 015479 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593454.0 | 509714.5 | 24052 | 1.64041666667 | 15479 |
| 015682 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593456.4 | 509714.9 | 24053 | 1.64041666667 | 15682 |
| 016336 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593459.4 | 509715.5 | 24056 | 1.64041666667 | 16336 |
| 015009 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593460.6 | 509716.6 | 24057 | 1.64041666667 | 15009 |
| 015170 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593462.3 | 509716.4 | 24060 | 1.64041666667 | 15170 |
| 015260 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593462.5 | 509716.4 | 24061 | 1.64041666667 | 15260 |
| 015634 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593462.0 | 509717.6 | 24064 | 1.64041666667 | 15634 |
| 016136 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593462.2 | 509718.9 | 24065 | 1.64041666667 | 16136 |
| 015684 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:35pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593460.7 | 509719.4 | 24067 | 1.64041666667 | 15684 |
| 015625 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593458.9 | 509719.4 | 24069 | 1.64041666667 | 15625 |
| 016049 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593456.5 | 509719.1 | 24072 | 1.64041666667 | 16049 |
| 015935 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593454.9 | 509718.9 | 24073 | 1.64041666667 | 15935 |
| 015556 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:39pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593453.3 | 509719.8 | 24075 | 1.64041666667 | 15556 |
| 015372 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593451.5 | 509720.7 | 24077 | 1.64041666667 | 15372 |
| 015179 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:41pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593450.3 | 509722.8 | 24079 | 1.64041666667 | 15179 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015131 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593448.4 | 509724.2 | 24081 | 1.64041666667 | 15131 |
| 014443 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:43pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593446.7 | 509726.2 | 24083 | 1.64041666667 | 14443 |
| 013922 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593445.4 | 509728.2 | 24085 | 1.64041666667 | 13922 |
| 013328 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:45pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593443.1 | 509729.8 | 24087 | 1.64041666667 | 13328 |
| 013707 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593441.9 | 509731.8 | 24089 | 1.64041666667 | 13707 |
| 013762 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:47pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593440.7 | 509734.5 | 24091 | 1.64041666667 | 13762 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593439.1 | 509736.7 | 24093 | 1.64041666667 | 14266 |
| 013327 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593437.5 | 509740.1 | 24096 | 1.64041666667 | 13327 |
| 014374 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:51pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593436.4 | 509742.5 | 24098 | 1.64041666667 | 14374 |
| 014880 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593434.4 | 509744.5 | 24100 | 1.64041666667 | 14880 |
| 014572 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:53pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593432.8 | 509746.7 | 24102 | 1.64041666667 | 14572 |
| 014917 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593431.6 | 509749.5 | 24104 | 1.64041666667 | 14917 |
| 014983 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593429.7 | 509751.6 | 24106 | 1.64041666667 | 14983 |
| 014030 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593427.5 | 509754.3 | 24108 | 1.64041666667 | 14030 |
| 013569 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593426.6 | 509756.3 | 24109 | 1.64041666667 | 13569 |
| 013648 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:58pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593424.4 | 509758.9 | 24112 | 1.64041666667 | 13648 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:59pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593422.2 | 509761.2 | 24114 | 1.64041666667 | 14081 |
| 014941 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593421.4 | 509764.0 | 24116 | 1.64041666667 | 14941 |
| 014479 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593420.6 | 509766.2 | 24117 | 1.64041666667 | 14479 |
| 014414 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593419.1 | 509769.3 | 24120 | 1.64041666667 | 14414 |
| 014303 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593418.2 | 509771.7 | 24121 | 1.64041666667 | 14303 |
| 013895 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593417.1 | 509774.6 | 24124 | 1.64041666667 | 13895 |
| 013598 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593415.5 | 509776.6 | 24125 | 1.64041666667 | 13598 |
| 013994 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:05pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593413.7 | 509779.3 | 24127 | 1.64041666667 | 13994 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:06pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593412.4 | 509781.6 | 24129 | 1.64041666667 | 14201 |
| 014566 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593410.0 | 509784.2 | 24132 | 1.64041666667 | 14566 |
| 014178 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593408.3 | 509786.2 | 24133 | 1.64041666667 | 14178 |
| 014373 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:09pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593406.9 | 509788.7 | 24135 | 1.64041666667 | 14373 |
| 013904 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:10pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593405.1 | 509790.6 | 24137 | 1.64041666667 | 13904 |
| 013709 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:12pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593402.6 | 509792.9 | 24140 | 1.64041666667 | 13709 |
| 014453 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:12pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593401.6 | 509795.0 | 24141 | 1.64041666667 | 14453 |
| 015742 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:13pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593399.8 | 509797.5 | 24143 | 1.64041666667 | 15742 |
| 015582 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:14pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593398.3 | 509799.8 | 24145 | 1.64041666667 | 15582 |
| 015897 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:15pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593397.8 | 509801.9 | 24147 | 1.64041666667 | 15897 |
| 016300 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:17pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593396.7 | 509803.7 | 24150 | 1.64041666667 | 16300 |
| 015873 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:18pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593396.2 | 509804.1 | 24152 | 1.64041666667 | 15873 |
| 016061 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:19pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593395.7 | 509803.5 | 24154 | 1.64041666667 | 16061 |
| 015447 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:20pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593394.5 | 509802.2 | 24156 | 1.64041666667 | 15447 |
| 015214 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:20pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593393.7 | 509800.8 | 24157 | 1.64041666667 | 15214 |
| 015322 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:22pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593394.5 | 509799.0 | 24160 | 1.64041666667 | 15322 |
| 015159 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:22pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593395.1 | 509797.3 | 24161 | 1.64041666667 | 15159 |
| 014954 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:24pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593397.0 | 509795.0 | 24164 | 1.64041666667 | 14954 |
| 014576 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:24pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593398.3 | 509793.5 | 24165 | 1.64041666667 | 14576 |
| 014972 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593399.3 | 509791.1 | 24168 | 1.64041666667 | 14972 |
| 014632 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593401.2 | 509789.4 | 24169 | 1.64041666667 | 14632 |
| 014013 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:28pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593403.4 | 509787.3 | 24172 | 1.64041666667 | 14013 |
| 014534 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:28pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593404.8 | 509785.4 | 24173 | 1.64041666667 | 14534 |
| 013688 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593406.8 | 509782.7 | 24176 | 1.64041666667 | 13688 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015154 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593406.8 | 509780.4 | 24177 | 1.64041666667 | 15154 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:32pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593407.0 | 509776.8 | 24180 | 1.64041666667 | 14314 |
| 013511 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:32pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593407.1 | 509774.4 | 24181 | 1.64041666667 | 13511 |
| 013495 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593405.0 | 509772.3 | 24184 | 1.64041666667 | 13495 |
| 013058 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593404.2 | 509770.1 | 24185 | 1.64041666667 | 13058 |
| 014358 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:35pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593403.6 | 509768.5 | 24187 | 1.64041666667 | 14358 |
| 014354 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593403.1 | 509766.2 | 24189 | 1.64041666667 | 14354 |
| 013841 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:37pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593403.5 | 509763.5 | 24191 | 1.64041666667 | 13841 |
| 013695 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593403.1 | 509761.2 | 24193 | 1.64041666667 | 13695 |
| 015084 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593403.8 | 509758.1 | 24196 | 1.64041666667 | 15084 |
| 014844 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593404.2 | 509755.7 | 24197 | 1.64041666667 | 14844 |
| 015137 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593403.5 | 509753.1 | 24200 | 1.64041666667 | 15137 |
| 013840 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593403.6 | 509750.8 | 24201 | 1.64041666667 | 13840 |
| 014565 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593403.2 | 509748.2 | 24204 | 1.64041666667 | 14565 |
| 015452 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593403.4 | 509746.0 | 24205 | 1.64041666667 | 15452 |
| 014444 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593405.0 | 509743.7 | 24208 | 1.64041666667 | 14444 |
| 015025 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593405.6 | 509741.9 | 24209 | 1.64041666667 | 15025 |
| 014984 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:47pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593407.0 | 509739.5 | 24211 | 1.64041666667 | 14984 |
| 014743 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593409.1 | 509738.6 | 24213 | 1.64041666667 | 14743 |
| 015463 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:49pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593411.3 | 509737.0 | 24215 | 1.64041666667 | 15463 |
| 015223 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593413.6 | 509736.0 | 24217 | 1.64041666667 | 15223 |
| 014990 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:51pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593416.7 | 509735.1 | 24219 | 1.64041666667 | 14990 |
| 014499 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:52pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593419.0 | 509733.8 | 24221 | 1.64041666667 | 14499 |
| 014808 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:53pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593421.1 | 509732.1 | 24223 | 1.64041666667 | 14808 |
| 014667 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593423.4 | 509731.8 | 24225 | 1.64041666667 | 14667 |
| 015622 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:55pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593426.0 | 509730.9 | 24227 | 1.64041666667 | 15622 |
| 015267 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593428.1 | 509729.6 | 24229 | 1.64041666667 | 15267 |
| 014933 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593430.2 | 509727.5 | 24232 | 1.64041666667 | 14933 |
| 014730 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593430.7 | 509725.6 | 24233 | 1.64041666667 | 14730 |
| 015778 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593432.1 | 509723.3 | 24236 | 1.64041666667 | 15778 |
| 016705 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593433.0 | 509721.1 | 24237 | 1.64041666667 | 16705 |
| 016679 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593433.1 | 509718.1 | 24240 | 1.64041666667 | 16679 |
| 016214 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593434.0 | 509716.1 | 24241 | 1.64041666667 | 16214 |
| 016283 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593435.3 | 509713.5 | 24244 | 1.64041666667 | 16283 |
| 015894 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:05pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593435.5 | 509711.2 | 24246 | 1.64041666667 | 15894 |
| 016005 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:05pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593435.6 | 509709.0 | 24247 | 1.64041666667 | 16005 |
| 015610 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593433.6 | 509708.5 | 24249 | 1.64041666667 | 15610 |
| 015598 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593430.7 | 509708.0 | 24252 | 1.64041666667 | 15598 |
| 017061 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593429.4 | 509708.7 | 24253 | 1.64041666667 | 17061 |
| 016969 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593426.6 | 509708.8 | 24256 | 1.64041666667 | 16969 |
| 015905 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593424.6 | 509708.3 | 24257 | 1.64041666667 | 15905 |
| 016364 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:11pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593422.1 | 509708.6 | 24259 | 1.64041666667 | 16364 |
| 016037 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593419.4 | 509708.2 | 24261 | 1.64041666667 | 16037 |
| 015996 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:13pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593416.5 | 509707.8 | 24263 | 1.64041666667 | 15996 |
| 015657 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593414.0 | 509707.9 | 24265 | 1.64041666667 | 15657 |
| 015107 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593411.4 | 509707.6 | 24267 | 1.64041666667 | 15107 |
| 014558 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593409.5 | 509708.4 | 24269 | 1.64041666667 | 14558 |
| 014646 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:17pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593407.4 | 509710.2 | 24271 | 1.64041666667 | 14646 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016556 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593405.7 | 509712.3 | 24273 | 1.64041666667 | 16556 |
| 016947 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:19pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593405.7 | 509714.7 | 24275 | 1.64041666667 | 16947 |
| 018068 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593404.9 | 509717.1 | 24277 | 1.64041666667 | 18068 |
| 017213 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593404.7 | 509720.0 | 24280 | 1.64041666667 | 17213 |
| 017700 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593404.9 | 509722.6 | 24281 | 1.64041666667 | 17700 |
| 018378 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593403.8 | 509725.0 | 24283 | 1.64041666667 | 18378 |
| 018063 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593403.1 | 509727.1 | 24285 | 1.64041666667 | 18063 |
| 017810 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593401.4 | 509729.2 | 24288 | 1.64041666667 | 17810 |
| 017698 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593399.2 | 509730.1 | 24289 | 1.64041666667 | 17698 |
| 016360 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593396.9 | 509731.2 | 24292 | 1.64041666667 | 16360 |
| 015555 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:28pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593394.6 | 509730.9 | 24293 | 1.64041666667 | 15555 |
| 015342 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593392.1 | 509730.2 | 24296 | 1.64041666667 | 15342 |
| 015845 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593390.2 | 509729.9 | 24297 | 1.64041666667 | 15845 |
| 014815 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:31pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593387.7 | 509729.2 | 24299 | 1.64041666667 | 14815 |
| 014348 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593385.5 | 509729.9 | 24301 | 1.64041666667 | 14348 |
| 014978 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:33pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593382.9 | 509730.4 | 24303 | 1.64041666667 | 14978 |
| 014178 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593380.4 | 509730.7 | 24305 | 1.64041666667 | 14178 |
| 014087 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593377.9 | 509731.5 | 24308 | 1.64041666667 | 14087 |
| 014809 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593375.9 | 509730.9 | 24309 | 1.64041666667 | 14809 |
| 014825 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:37pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593373.0 | 509730.0 | 24311 | 1.64041666667 | 14825 |
| 015704 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593370.5 | 509728.8 | 24313 | 1.64041666667 | 15704 |
| 016311 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:39pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593368.7 | 509727.0 | 24315 | 1.64041666667 | 16311 |
| 015895 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593366.8 | 509725.9 | 24317 | 1.64041666667 | 15895 |
| 015563 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:41pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593364.9 | 509724.3 | 24319 | 1.64041666667 | 15563 |
| 015857 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593362.7 | 509722.8 | 24321 | 1.64041666667 | 15857 |
| 016397 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:43pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593360.2 | 509722.7 | 24323 | 1.64041666667 | 16397 |
| 016176 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593357.9 | 509722.1 | 24325 | 1.64041666667 | 16176 |
| 016771 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:45pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593355.1 | 509723.5 | 24327 | 1.64041666667 | 16771 |
| 017136 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593354.5 | 509725.9 | 24329 | 1.64041666667 | 17136 |
| 016891 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:47pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593355.1 | 509728.4 | 24331 | 1.64041666667 | 16891 |
| 016986 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593355.2 | 509730.5 | 24333 | 1.64041666667 | 16986 |
| 017130 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:49pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593355.4 | 509732.6 | 24335 | 1.64041666667 | 17130 |
| 017023 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593354.9 | 509734.8 | 24337 | 1.64041666667 | 17023 |
| 015643 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:51pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593354.0 | 509737.3 | 24339 | 1.64041666667 | 15643 |
| 016471 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593353.3 | 509739.7 | 24341 | 1.64041666667 | 16471 |
| 015812 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593350.9 | 509741.8 | 24344 | 1.64041666667 | 15812 |
| 015779 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593349.3 | 509742.9 | 24345 | 1.64041666667 | 15779 |
| 016518 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:55pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593347.4 | 509744.5 | 24347 | 1.64041666667 | 16518 |
| 016821 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:57pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593344.6 | 509745.1 | 24350 | 1.64041666667 | 16821 |
| 016152 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:58pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593342.9 | 509746.9 | 24352 | 1.64041666667 | 16152 |
| 015798 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:58pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593341.4 | 509748.2 | 24353 | 1.64041666667 | 15798 |
| 016154 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:59pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593339.1 | 509749.2 | 24355 | 1.64041666667 | 16154 |
| 016894 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593338.5 | 509750.9 | 24357 | 1.64041666667 | 16894 |
| 016680 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593336.9 | 509752.7 | 24360 | 1.64041666667 | 16680 |
| 016057 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593336.9 | 509754.5 | 24361 | 1.64041666667 | 16057 |
| 015527 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593336.3 | 509757.4 | 24364 | 1.64041666667 | 15527 |
| 016196 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593335.3 | 509759.3 | 24365 | 1.64041666667 | 16196 |
| 015883 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:06pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593335.5 | 509761.7 | 24368 | 1.64041666667 | 15883 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015721 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:06pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593335.3 | 509763.8 | 24369 | 1.64041666667 | 15721 |
| 014678 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593335.8 | 509766.5 | 24372 | 1.64041666667 | 14678 |
| 014549 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593336.2 | 509768.7 | 24373 | 1.64041666667 | 14549 |
| 015773 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:09pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593336.1 | 509771.7 | 24375 | 1.64041666667 | 15773 |
| 014295 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:10pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593337.6 | 509772.9 | 24377 | 1.64041666667 | 14295 |
| 014491 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:11pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593340.2 | 509773.4 | 24379 | 1.64041666667 | 14491 |
| 014788 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:12pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593342.9 | 509773.2 | 24381 | 1.64041666667 | 14788 |
| 014371 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:13pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593345.0 | 509772.0 | 24383 | 1.64041666667 | 14371 |
| 013393 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:14pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593347.1 | 509771.8 | 24385 | 1.64041666667 | 13393 |
| 013459 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:15pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593349.6 | 509771.2 | 24387 | 1.64041666667 | 13459 |
| 013705 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:16pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593351.6 | 509769.9 | 24389 | 1.64041666667 | 13705 |
| 013552 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:17pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593354.1 | 509769.0 | 24391 | 1.64041666667 | 13552 |
| 014013 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:18pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593356.2 | 509767.7 | 24393 | 1.64041666667 | 14013 |
| 014392 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:19pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593358.3 | 509765.9 | 24395 | 1.64041666667 | 14392 |
| 014838 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:20pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593360.3 | 509765.4 | 24397 | 1.64041666667 | 14838 |
| 014331 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:21pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593362.7 | 509764.2 | 24399 | 1.64041666667 | 14331 |
| 014121 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:22pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593364.8 | 509762.9 | 24401 | 1.64041666667 | 14121 |
| 013005 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:23pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593367.4 | 509761.4 | 24403 | 1.64041666667 | 13005 |
| 013218 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:24pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593368.8 | 509759.5 | 24405 | 1.64041666667 | 13218 |
| 013300 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:25pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593371.3 | 509758.1 | 24407 | 1.64041666667 | 13300 |
| 014816 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593373.4 | 509757.0 | 24409 | 1.64041666667 | 14816 |
| 014221 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:27pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593375.1 | 509755.7 | 24411 | 1.64041666667 | 14221 |
| 014847 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:28pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593377.8 | 509755.3 | 24413 | 1.64041666667 | 14847 |
| 014126 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:29pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593380.2 | 509754.2 | 24415 | 1.64041666667 | 14126 |
| 014216 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593382.4 | 509754.3 | 24417 | 1.64041666667 | 14216 |
| 014011 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:31pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593385.6 | 509754.7 | 24419 | 1.64041666667 | 14011 |
| 014286 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593387.7 | 509754.3 | 24421 | 1.64041666667 | 14286 |
| 014133 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:33pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593390.7 | 509754.6 | 24423 | 1.64041666667 | 14133 |
| 014407 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593393.1 | 509754.8 | 24425 | 1.64041666667 | 14407 |
| 014569 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593396.1 | 509755.3 | 24428 | 1.64041666667 | 14569 |
| 014557 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593397.3 | 509756.6 | 24429 | 1.64041666667 | 14557 |
| 015066 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:37pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593398.6 | 509758.6 | 24431 | 1.64041666667 | 15066 |
| 015045 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593398.2 | 509760.8 | 24433 | 1.64041666667 | 15045 |
| 015370 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593396.6 | 509762.7 | 24436 | 1.64041666667 | 15370 |
| 015320 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593395.7 | 509764.1 | 24437 | 1.64041666667 | 15320 |
| 015877 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:41pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593393.4 | 509765.2 | 24439 | 1.64041666667 | 15877 |
| 015793 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593391.2 | 509766.2 | 24441 | 1.64041666667 | 15793 |
| 015184 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593388.4 | 509767.2 | 24444 | 1.64041666667 | 15184 |
| 015583 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593386.8 | 509766.9 | 24445 | 1.64041666667 | 15583 |
| 014863 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:45pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593384.4 | 509766.7 | 24447 | 1.64041666667 | 14863 |
| 014983 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593382.3 | 509765.9 | 24449 | 1.64041666667 | 14983 |
| 015583 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593379.6 | 509764.5 | 24452 | 1.64041666667 | 15583 |
| 015327 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593377.3 | 509764.4 | 24453 | 1.64041666667 | 15327 |
| 014854 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593374.1 | 509763.2 | 24456 | 1.64041666667 | 14854 |
| 015000 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593372.1 | 509762.5 | 24457 | 1.64041666667 | 15000 |
| 014392 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593369.5 | 509762.5 | 24460 | 1.64041666667 | 14392 |
| 014373 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:52pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593367.7 | 509761.6 | 24461 | 1.64041666667 | 14373 |
| 013950 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593365.3 | 509761.7 | 24464 | 1.64041666667 | 13950 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013817 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593364.2 | 509760.3 | 24465 | 1.64041666667 | 13817 |
| 014349 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593363.2 | 509758.0 | 24467 | 1.64041666667 | 14349 |
| 013831 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593362.4 | 509755.9 | 24469 | 1.64041666667 | 13831 |
| 014417 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:57pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593362.9 | 509753.6 | 24471 | 1.64041666667 | 14417 |
| 014552 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593362.7 | 509751.8 | 24473 | 1.64041666667 | 14552 |
| 013548 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:59pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593364.1 | 509749.8 | 24475 | 1.64041666667 | 13548 |
| 014956 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593365.2 | 509748.2 | 24477 | 1.64041666667 | 14956 |
| 014217 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:01pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593366.8 | 509746.0 | 24479 | 1.64041666667 | 14217 |
| 014117 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593368.7 | 509744.2 | 24481 | 1.64041666667 | 14117 |
| 015351 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:03pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593369.5 | 509741.9 | 24483 | 1.64041666667 | 15351 |
| 015227 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593370.6 | 509740.0 | 24485 | 1.64041666667 | 15227 |
| 015615 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593370.5 | 509737.9 | 24488 | 1.64041666667 | 15615 |
| 015638 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593369.3 | 509736.1 | 24489 | 1.64041666667 | 15638 |
| 016034 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:07pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593368.6 | 509733.7 | 24491 | 1.64041666667 | 16034 |
| 017006 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593367.6 | 509731.8 | 24493 | 1.64041666667 | 17006 |
| 016518 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:09pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593367.8 | 509729.7 | 24495 | 1.64041666667 | 16518 |
| 016889 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593368.0 | 509727.5 | 24497 | 1.64041666667 | 16889 |
| 016572 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:11pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593368.2 | 509725.0 | 24499 | 1.64041666667 | 16572 |
| 016334 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593369.3 | 509722.8 | 24501 | 1.64041666667 | 16334 |
| 015713 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:13pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593369.0 | 509720.3 | 24503 | 1.64041666667 | 15713 |
| 016743 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593369.4 | 509718.0 | 24505 | 1.64041666667 | 16743 |
| 017068 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593370.9 | 509715.7 | 24507 | 1.64041666667 | 17068 |
| 016733 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593372.2 | 509714.0 | 24509 | 1.64041666667 | 16733 |
| 016680 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:17pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593374.3 | 509712.6 | 24511 | 1.64041666667 | 16680 |
| 016822 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593376.2 | 509711.1 | 24513 | 1.64041666667 | 16822 |
| 016775 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:19pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593377.6 | 509709.0 | 24515 | 1.64041666667 | 16775 |
| 017221 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593379.5 | 509706.9 | 24517 | 1.64041666667 | 17221 |
| 016489 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:21pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593380.1 | 509704.6 | 24519 | 1.64041666667 | 16489 |
| 015777 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593379.5 | 509702.0 | 24521 | 1.64041666667 | 15777 |
| 015925 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593379.2 | 509699.2 | 24523 | 1.64041666667 | 15925 |
| 015460 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593378.0 | 509697.2 | 24525 | 1.64041666667 | 15460 |
| 015086 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:25pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593376.7 | 509694.7 | 24527 | 1.64041666667 | 15086 |
| 015063 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:26pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593377.0 | 509692.9 | 24529 | 1.64041666667 | 15063 |
| 015523 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:27pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593376.9 | 509690.8 | 24531 | 1.64041666667 | 15523 |
| 014987 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:28pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593377.6 | 509689.3 | 24533 | 1.64041666667 | 14987 |
| 015592 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:29pm | Sensor | 1797-S0026-905-G-ACK | 6804.4 | 1593378.8 | 509686.8 | 24535 | 1.64041666667 | 15592 |
| 015423 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:30pm | Sensor | 1797-S0026-905-G-ACK | 6804.7 | 1593379.6 | 509685.2 | 24537 | 1.64041666667 | 15423 |
| 014908 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:32pm | Sensor | 1797-S0026-905-G-ACK | 6804.8 | 1593381.4 | 509683.5 | 24540 | 1.64041666667 | 14908 |
| 015135 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:32pm | Sensor | 1797-S0026-905-G-ACK | 6804.9 | 1593382.1 | 509682.0 | 24541 | 1.64041666667 | 15135 |
| 015504 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:33pm | Sensor | 1797-S0026-905-G-ACK | 6805.3 | 1593383.3 | 509680.5 | 24543 | 1.64041666667 | 15504 |
| 014758 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:34pm | Sensor | 1797-S0026-905-G-ACK | 6805.2 | 1593385.4 | 509680.4 | 24545 | 1.64041666667 | 14758 |
| 014646 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:35pm | Sensor | 1797-S0026-905-G-ACK | 6805.0 | 1593388.0 | 509680.2 | 24547 | 1.64041666667 | 14646 |
| 014658 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:36pm | Sensor | 1797-S0026-905-G-ACK | 6804.7 | 1593389.9 | 509680.2 | 24549 | 1.64041666667 | 14658 |
| 015985 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:37pm | Sensor | 1797-S0026-905-G-ACK | 6804.6 | 1593392.4 | 509681.3 | 24551 | 1.64041666667 | 15985 |
| 014602 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:38pm | Sensor | 1797-S0026-905-G-ACK | 6804.4 | 1593394.8 | 509681.3 | 24553 | 1.64041666667 | 14602 |
| 014648 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:39pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593397.4 | 509681.4 | 24555 | 1.64041666667 | 14648 |
| 014944 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:40pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593398.9 | 509682.7 | 24557 | 1.64041666667 | 14944 |
| 015021 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:41pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593400.7 | 509683.5 | 24559 | 1.64041666667 | 15021 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014712 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593401.6 | 509685.2 | 24561 | 1.64041666667 | 14712 |
| 015348 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:43pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593402.9 | 509687.3 | 24563 | 1.64041666667 | 15348 |
| 015473 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593403.9 | 509688.8 | 24565 | 1.64041666667 | 15473 |
| 015641 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:45pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593404.8 | 509691.1 | 24567 | 1.64041666667 | 15641 |
| 016410 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.2 | 509692.6 | 24569 | 1.64041666667 | 16410 |
| 016281 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:47pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593406.8 | 509694.8 | 24571 | 1.64041666667 | 16281 |
| 016050 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593407.6 | 509696.5 | 24573 | 1.64041666667 | 16050 |
| 016596 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:49pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593408.3 | 509698.9 | 24575 | 1.64041666667 | 16596 |
| 016137 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:50pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593408.4 | 509701.1 | 24577 | 1.64041666667 | 16137 |
| 015632 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:51pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593408.8 | 509703.5 | 24579 | 1.64041666667 | 15632 |
| 015686 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:52pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593408.5 | 509705.8 | 24581 | 1.64041666667 | 15686 |
| 015416 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:53pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593408.9 | 509707.5 | 24583 | 1.64041666667 | 15416 |
| 014634 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:54pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593409.1 | 509709.2 | 24585 | 1.64041666667 | 14634 |
| 014869 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:55pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593411.1 | 509708.6 | 24587 | 1.64041666667 | 14869 |
| 014948 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:56pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593412.9 | 509707.5 | 24589 | 1.64041666667 | 14948 |
| 015526 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:57pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593415.0 | 509706.2 | 24591 | 1.64041666667 | 15526 |
| 015881 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:58pm | Sensor | 1797-S0026-905-G-ACK | 6804.4 | 1593416.5 | 509704.8 | 24593 | 1.64041666667 | 15881 |
| 015968 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:59pm | Sensor | 1797-S0026-905-G-ACK | 6804.4 | 1593418.4 | 509703.9 | 24595 | 1.64041666667 | 15968 |
| 015094 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:00pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593419.5 | 509702.2 | 24597 | 1.64041666667 | 15094 |
| 014588 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:01pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593419.9 | 509700.1 | 24599 | 1.64041666667 | 14588 |
| 016140 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:02pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593420.6 | 509698.1 | 24601 | 1.64041666667 | 16140 |
| 015439 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:03pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593420.7 | 509696.6 | 24603 | 1.64041666667 | 15439 |
| 016904 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:04pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593420.5 | 509696.1 | 24605 | 1.64041666667 | 16904 |
| 016536 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:05pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593420.7 | 509695.9 | 24607 | 1.64041666667 | 16536 |
| 015324 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:06pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593420.4 | 509696.6 | 24609 | 1.64041666667 | 15324 |
| 015107 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:07pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593419.2 | 509698.2 | 24611 | 1.64041666667 | 15107 |
| 015510 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:08pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593419.1 | 509700.1 | 24613 | 1.64041666667 | 15510 |
| 016097 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:09pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593418.1 | 509701.7 | 24615 | 1.64041666667 | 16097 |
| 016172 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:10pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593417.6 | 509703.2 | 24617 | 1.64041666667 | 16172 |
| 016214 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:12pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593416.1 | 509705.1 | 24620 | 1.64041666667 | 16214 |
| 015533 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:12pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593414.0 | 509706.5 | 24621 | 1.64041666667 | 15533 |
| 015127 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:14pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593412.6 | 509708.6 | 24624 | 1.64041666667 | 15127 |
| 015791 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593410.7 | 509710.0 | 24625 | 1.64041666667 | 15791 |
| 016300 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593408.4 | 509711.7 | 24627 | 1.64041666667 | 16300 |
| 016653 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:16pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593406.6 | 509713.4 | 24629 | 1.64041666667 | 16653 |
| 016957 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:17pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593404.4 | 509714.2 | 24631 | 1.64041666667 | 16957 |
| 016536 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:18pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593402.5 | 509715.0 | 24633 | 1.64041666667 | 16536 |
| 016246 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:19pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593400.5 | 509716.3 | 24635 | 1.64041666667 | 16246 |
| 016803 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:20pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593398.3 | 509716.6 | 24637 | 1.64041666667 | 16803 |
| 015767 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:21pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593396.1 | 509717.5 | 24639 | 1.64041666667 | 15767 |
| 015521 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:22pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593393.8 | 509717.9 | 24641 | 1.64041666667 | 15521 |
| 015638 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593391.2 | 509718.6 | 24643 | 1.64041666667 | 15638 |
| 016311 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593389.2 | 509719.2 | 24645 | 1.64041666667 | 16311 |
| 016697 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593386.7 | 509720.1 | 24648 | 1.64041666667 | 16697 |
| 016570 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593384.5 | 509720.3 | 24649 | 1.64041666667 | 16570 |
| 016700 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:27pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593382.3 | 509720.7 | 24651 | 1.64041666667 | 16700 |
| 017179 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593379.9 | 509720.3 | 24653 | 1.64041666667 | 17179 |
| 017815 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:29pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593377.4 | 509719.8 | 24655 | 1.64041666667 | 17815 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016868 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593375.4 | 509720.9 | 24657 | 1.64041666667 | 16868 |
| 016156 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:31pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593373.1 | 509722.1 | 24659 | 1.64041666667 | 16156 |
| 016625 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593371.7 | 509723.8 | 24661 | 1.64041666667 | 16625 |
| 017039 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:33pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593370.4 | 509725.7 | 24663 | 1.64041666667 | 17039 |
| 016567 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593369.5 | 509727.7 | 24665 | 1.64041666667 | 16567 |
| 016196 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593370.4 | 509730.0 | 24668 | 1.64041666667 | 16196 |
| 015268 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593370.5 | 509731.6 | 24669 | 1.64041666667 | 15268 |
| 015975 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593370.3 | 509731.5 | 24672 | 1.64041666667 | 15975 |
| 017131 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:38pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593368.6 | 509731.6 | 24673 | 1.64041666667 | 17131 |
| 016671 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:39pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593367.6 | 509729.7 | 24675 | 1.64041666667 | 16671 |
| 016540 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:40pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593366.6 | 509727.9 | 24677 | 1.64041666667 | 16540 |
| 016233 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:41pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593365.0 | 509726.4 | 24679 | 1.64041666667 | 16233 |
| 015829 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:42pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593364.2 | 509724.4 | 24681 | 1.64041666667 | 15829 |
| 016081 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:43pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593362.5 | 509723.4 | 24683 | 1.64041666667 | 16081 |
| 016628 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593360.9 | 509722.2 | 24685 | 1.64041666667 | 16628 |
| 017483 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:45pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593358.9 | 509721.9 | 24687 | 1.64041666667 | 17483 |
| 017094 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593357.2 | 509722.3 | 24689 | 1.64041666667 | 17094 |
| 016838 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:47pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593355.3 | 509721.3 | 24691 | 1.64041666667 | 16838 |
| 016079 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593353.2 | 509720.7 | 24693 | 1.64041666667 | 16079 |
| 015929 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:49pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593351.5 | 509718.9 | 24695 | 1.64041666667 | 15929 |
| 015620 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593349.7 | 509718.2 | 24697 | 1.64041666667 | 15620 |
| 015843 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:51pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593347.1 | 509717.3 | 24699 | 1.64041666667 | 15843 |
| 015489 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593344.9 | 509717.3 | 24701 | 1.64041666667 | 15489 |
| 015380 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593342.6 | 509718.1 | 24704 | 1.64041666667 | 15380 |
| 014861 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593341.3 | 509716.9 | 24705 | 1.64041666667 | 14861 |
| 014682 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593339.0 | 509715.3 | 24708 | 1.64041666667 | 14682 |
| 014551 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593337.6 | 509713.8 | 24709 | 1.64041666667 | 14551 |
| 014575 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593336.9 | 509711.7 | 24712 | 1.64041666667 | 14575 |
| 015383 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:58pm | Sensor | 1797-S0026-905-G-ACK | 6804.1 | 1593335.7 | 509710.6 | 24713 | 1.64041666667 | 15383 |
| 014300 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:59pm | Sensor | 1797-S0026-905-G-ACK | 6804.3 | 1593334.8 | 509709.2 | 24715 | 1.64041666667 | 14300 |
| 013916 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:00pm | Sensor | 1797-S0026-905-G-ACK | 6804.5 | 1593333.6 | 509708.2 | 24717 | 1.64041666667 | 13916 |
| 014488 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:01pm | Sensor | 1797-S0026-905-G-ACK | 6804.6 | 1593333.7 | 509706.5 | 24719 | 1.64041666667 | 14488 |
| 013864 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:02pm | Sensor | 1797-S0026-905-G-ACK | 6804.9 | 1593333.8 | 509704.9 | 24721 | 1.64041666667 | 13864 |
| 013506 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:03pm | Sensor | 1797-S0026-905-G-ACK | 6805.2 | 1593334.4 | 509703.0 | 24723 | 1.64041666667 | 13506 |
| 013125 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:04pm | Sensor | 1797-S0026-905-G-ACK | 6805.4 | 1593335.5 | 509701.4 | 24725 | 1.64041666667 | 13125 |
| 013045 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:05pm | Sensor | 1797-S0026-905-G-ACK | 6805.7 | 1593335.9 | 509699.7 | 24727 | 1.64041666667 | 13045 |
| 013105 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:06pm | Sensor | 1797-S0026-905-G-ACK | 6805.7 | 1593337.0 | 509698.8 | 24729 | 1.64041666667 | 13105 |
| 013566 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:07pm | Sensor | 1797-S0026-905-G-ACK | 6805.9 | 1593337.6 | 509697.7 | 24731 | 1.64041666667 | 13566 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:08pm | Sensor | 1797-S0026-905-G-ACK | 6805.6 | 1593338.8 | 509698.0 | 24733 | 1.64041666667 | 13301 |
| 013414 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:09pm | Sensor | 1797-S0026-905-G-ACK | 6805.4 | 1593340.6 | 509698.4 | 24735 | 1.64041666667 | 13414 |
| 015383 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:10pm | Sensor | 1797-S0026-905-G-ACK | 6805.3 | 1593342.2 | 509698.7 | 24737 | 1.64041666667 | 15383 |
| 015478 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:11pm | Sensor | 1797-S0026-905-G-ACK | 6804.8 | 1593343.5 | 509700.1 | 24739 | 1.64041666667 | 15478 |
| 015089 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:12pm | Sensor | 1797-S0026-905-G-ACK | 6804.7 | 1593345.6 | 509701.0 | 24741 | 1.64041666667 | 15089 |
| 015920 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:13pm | Sensor | 1797-S0026-905-G-ACK | 6804.2 | 1593347.5 | 509702.0 | 24743 | 1.64041666667 | 15920 |
| 014745 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:14pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593349.3 | 509703.4 | 24745 | 1.64041666667 | 14745 |
| 015501 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593351.8 | 509704.3 | 24748 | 1.64041666667 | 15501 |
| 015732 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:17pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593352.8 | 509706.2 | 24750 | 1.64041666667 | 15732 |
| 016559 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:17pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593354.7 | 509707.1 | 24751 | 1.64041666667 | 16559 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593356.4 | 509708.4 | 24753 | 1.64041666667 | 14819 |
| 013818 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593357.4 | 509709.9 | 24756 | 1.64041666667 | 13818 |
| 014410 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593358.1 | 509710.4 | 24757 | 1.64041666667 | 14410 |
| 015035 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593360.6 | 509712.0 | 24760 | 1.64041666667 | 15035 |
| 015080 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593362.6 | 509713.2 | 24761 | 1.64041666667 | 15080 |
| 014970 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593364.3 | 509714.2 | 24764 | 1.64041666667 | 14970 |
| 015350 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593365.7 | 509714.8 | 24765 | 1.64041666667 | 15350 |
| 016930 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:26pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593367.3 | 509716.7 | 24768 | 1.64041666667 | 16930 |
| 017143 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:26pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593368.7 | 509717.0 | 24769 | 1.64041666667 | 17143 |
| 016948 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:27pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593369.4 | 509718.3 | 24771 | 1.64041666667 | 16948 |
| 016223 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593369.5 | 509719.3 | 24773 | 1.64041666667 | 16223 |
| 016528 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:29pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593371.0 | 509720.0 | 24775 | 1.64041666667 | 16528 |
| 017419 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593373.1 | 509721.3 | 24777 | 1.64041666667 | 17419 |
| 016758 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:31pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593375.9 | 509722.4 | 24779 | 1.64041666667 | 16758 |
| 016484 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593378.3 | 509722.8 | 24781 | 1.64041666667 | 16484 |
| 016449 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:33pm | Sensor | 1797-S0026-905-G-ACK | 6804.0 | 1593381.7 | 509723.1 | 24783 | 1.64041666667 | 16449 |
| 016310 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593384.8 | 509723.3 | 24785 | 1.64041666667 | 16310 |
| 016404 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:35pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593388.2 | 509723.6 | 24787 | 1.64041666667 | 16404 |
| 017912 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593391.1 | 509724.0 | 24789 | 1.64041666667 | 17912 |
| 017231 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:37pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593394.3 | 509724.3 | 24791 | 1.64041666667 | 17231 |
| 016742 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593397.2 | 509724.4 | 24793 | 1.64041666667 | 16742 |
| 016167 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:39pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593400.4 | 509724.6 | 24795 | 1.64041666667 | 16167 |
| 015971 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.9 | 1593403.0 | 509725.1 | 24797 | 1.64041666667 | 15971 |
| 016784 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593405.3 | 509725.3 | 24800 | 1.64041666667 | 16784 |
| 019326 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:42pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.5 | 509724.6 | 24801 | 1.64041666667 | 19326 |
| 019968 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:43pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.4 | 509724.8 | 24803 | 1.64041666667 | 19968 |
| 021139 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:44pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509725.0 | 24805 | 1.64041666667 | 21139 |
| 020771 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:46pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24808 | 1.64041666667 | 20771 |
| 020886 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:47pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24810 | 1.64041666667 | 20886 |
| 021896 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24812 | 1.64041666667 | 21896 |
| 022081 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:48pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24813 | 1.64041666667 | 22081 |
| 022860 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24814 | 1.64041666667 | 22860 |
| 022946 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:50pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24815 | 1.64041666667 | 22946 |
| 023212 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:51pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24816 | 1.64041666667 | 23212 |
| 021682 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:52pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24817 | 1.64041666667 | 21682 |
| 022951 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:53pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24818 | 1.64041666667 | 22951 |
| 022997 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:54pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24819 | 1.64041666667 | 22997 |
| 021583 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:55pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24820 | 1.64041666667 | 21583 |
| 022565 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:56pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24821 | 1.64041666667 | 22565 |
| 022038 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24822 | 1.64041666667 | 22038 |
| 023204 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24823 | 1.64041666667 | 23204 |
| 023754 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:59pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24824 | 1.64041666667 | 23754 |
| 023757 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24825 | 1.64041666667 | 23757 |
| 024035 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:01pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24826 | 1.64041666667 | 24035 |
| 022895 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.7 | 509725.0 | 24827 | 1.64041666667 | 22895 |
| 022598 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:03pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24828 | 1.64041666667 | 22598 |
| 021524 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:04pm | Sensor | 1797-S0026-905-G-ACK | 6803.8 | 1593406.6 | 509725.0 | 24829 | 1.64041666667 | 21524 |
| 021842 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:05pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509725.0 | 24830 | 1.64041666667 | 21842 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 021511 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509725.0 | 24831 | 1.64041666667 | 21511 |
| 021475 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:07pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509725.0 | 24832 | 1.64041666667 | 21475 |
| 022062 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:08pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509725.0 | 24833 | 1.64041666667 | 22062 |
| 022047 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:09pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509725.0 | 24834 | 1.64041666667 | 22047 |
| 021139 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509725.0 | 24835 | 1.64041666667 | 21139 |
| 021978 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:11pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509725.0 | 24836 | 1.64041666667 | 21978 |
| 022817 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:12pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509724.9 | 24837 | 1.64041666667 | 22817 |
| 022060 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:13pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509724.9 | 24838 | 1.64041666667 | 22060 |
| 023051 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:14pm | Sensor | 1797-S0026-905-G-ACK | 6803.7 | 1593406.6 | 509724.9 | 24839 | 1.64041666667 | 23051 |
| 023159 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593406.6 | 509724.9 | 24840 | 1.64041666667 | 23159 |
| 023114 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:16pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593406.6 | 509725.0 | 24841 | 1.64041666667 | 23114 |
| 022163 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:18pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593406.2 | 509724.8 | 24842 | 1.64041666667 | 22163 |
| 021947 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:19pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593405.9 | 509724.6 | 24843 | 1.64041666667 | 21947 |
| 020655 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.6 | 1593406.3 | 509725.5 | 24845 | 1.64041666667 | 20655 |
| 018293 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:21pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593405.4 | 509727.1 | 24847 | 1.64041666667 | 18293 |
| 017535 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.5 | 1593404.9 | 509728.6 | 24849 | 1.64041666667 | 17535 |
| 017363 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593404.3 | 509730.5 | 24851 | 1.64041666667 | 17363 |
| 016577 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593403.4 | 509731.5 | 24853 | 1.64041666667 | 16577 |
| 016122 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:29pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593398.6 | 509736.7 | 24854 | 1.64041666667 | 16122 |
| 015331 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:30pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593397.5 | 509737.5 | 24856 | 1.64041666667 | 15331 |
| 014789 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593395.3 | 509739.6 | 24859 | 1.64041666667 | 14789 |
| 013081 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:32pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593394.3 | 509741.5 | 24860 | 1.64041666667 | 13081 |
| 014198 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:33pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593392.7 | 509744.2 | 24862 | 1.64041666667 | 14198 |
| 015539 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:34pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593391.7 | 509746.7 | 24864 | 1.64041666667 | 15539 |
| 014905 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:35pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593391.6 | 509749.3 | 24866 | 1.64041666667 | 14905 |
| 015022 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:36pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593390.6 | 509751.5 | 24868 | 1.64041666667 | 15022 |
| 014847 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:37pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593390.1 | 509754.2 | 24870 | 1.64041666667 | 14847 |
| 014636 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:38pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593390.1 | 509756.5 | 24872 | 1.64041666667 | 14636 |
| 015740 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:39pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593389.1 | 509759.0 | 24874 | 1.64041666667 | 15740 |
| 016624 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:40pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593389.0 | 509761.3 | 24876 | 1.64041666667 | 16624 |
| 015538 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:41pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593388.5 | 509764.3 | 24878 | 1.64041666667 | 15538 |
| 014568 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593387.6 | 509766.6 | 24880 | 1.64041666667 | 14568 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:43pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593387.2 | 509768.9 | 24882 | 1.64041666667 | 14591 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593385.7 | 509770.8 | 24884 | 1.64041666667 | 14283 |
| 014086 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:45pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593384.1 | 509773.2 | 24886 | 1.64041666667 | 14086 |
| 013556 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593383.2 | 509775.5 | 24888 | 1.64041666667 | 13556 |
| 013677 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:47pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593381.7 | 509777.9 | 24890 | 1.64041666667 | 13677 |
| 013558 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593380.8 | 509780.4 | 24892 | 1.64041666667 | 13558 |
| 013947 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:49pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593379.5 | 509782.9 | 24894 | 1.64041666667 | 13947 |
| 015487 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593377.7 | 509785.2 | 24896 | 1.64041666667 | 15487 |
| 015424 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:51pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593376.4 | 509787.8 | 24898 | 1.64041666667 | 15424 |
| 015681 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:52pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593374.9 | 509789.9 | 24900 | 1.64041666667 | 15681 |
| 015345 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:53pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593372.7 | 509792.6 | 24902 | 1.64041666667 | 15345 |
| 015607 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593371.6 | 509795.0 | 24904 | 1.64041666667 | 15607 |
| 016091 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593370.0 | 509797.9 | 24906 | 1.64041666667 | 16091 |
| 015966 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593368.1 | 509800.1 | 24908 | 1.64041666667 | 15966 |
| 015536 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:57pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593366.3 | 509802.7 | 24910 | 1.64041666667 | 15536 |
| 015519 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:58pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593365.3 | 509805.0 | 24912 | 1.64041666667 | 15519 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015157 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:59pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593363.3 | 509807.7 | 24914 | 1.64041666667 | 15157 |
| 015680 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593361.9 | 509809.9 | 24916 | 1.64041666667 | 15680 |
| 014790 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:01pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593360.6 | 509812.8 | 24918 | 1.64041666667 | 14790 |
| 014139 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593358.8 | 509815.4 | 24920 | 1.64041666667 | 14139 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:03pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593356.6 | 509817.8 | 24922 | 1.64041666667 | 13278 |
| 013641 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593355.1 | 509820.0 | 24924 | 1.64041666667 | 13641 |
| 013523 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:05pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593353.6 | 509823.1 | 24926 | 1.64041666667 | 13523 |
| 014642 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:06pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593352.9 | 509825.7 | 24928 | 1.64041666667 | 14642 |
| 014123 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593351.9 | 509829.1 | 24931 | 1.64041666667 | 14123 |
| 013082 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593350.7 | 509831.4 | 24932 | 1.64041666667 | 13082 |
| 013433 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:09pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593349.1 | 509833.7 | 24934 | 1.64041666667 | 13433 |
| 014261 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:10pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593347.1 | 509835.4 | 24936 | 1.64041666667 | 14261 |
| 015274 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:11pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593344.5 | 509837.3 | 24938 | 1.64041666667 | 15274 |
| 014449 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:12pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593341.9 | 509838.5 | 24940 | 1.64041666667 | 14449 |
| 015132 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:13pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593338.9 | 509839.8 | 24942 | 1.64041666667 | 15132 |
| 014887 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:14pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593336.8 | 509841.5 | 24944 | 1.64041666667 | 14887 |
| 015409 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:15pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593335.0 | 509844.0 | 24946 | 1.64041666667 | 15409 |
| 014667 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:16pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593333.0 | 509846.3 | 24948 | 1.64041666667 | 14667 |
| 014280 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:17pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593330.6 | 509848.5 | 24950 | 1.64041666667 | 14280 |
| 014257 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:18pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593329.6 | 509851.0 | 24952 | 1.64041666667 | 14257 |
| 016135 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:19pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593328.7 | 509853.9 | 24954 | 1.64041666667 | 16135 |
| 015233 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:20pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593327.0 | 509855.7 | 24956 | 1.64041666667 | 15233 |
| 015018 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:21pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593324.7 | 509858.2 | 24958 | 1.64041666667 | 15018 |
| 014785 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:22pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593323.4 | 509860.3 | 24960 | 1.64041666667 | 14785 |
| 015089 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:23pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593321.7 | 509863.0 | 24962 | 1.64041666667 | 15089 |
| 014977 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:24pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593320.1 | 509865.1 | 24964 | 1.64041666667 | 14977 |
| 014531 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:25pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593319.4 | 509867.4 | 24966 | 1.64041666667 | 14531 |
| 013461 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:26pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593318.1 | 509869.3 | 24968 | 1.64041666667 | 13461 |
| 013924 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:27pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593316.9 | 509872.0 | 24970 | 1.64041666667 | 13924 |
| 013532 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:28pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593316.0 | 509874.5 | 24972 | 1.64041666667 | 13532 |
| 014129 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:29pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593314.3 | 509877.3 | 24974 | 1.64041666667 | 14129 |
| 014488 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593313.5 | 509880.1 | 24976 | 1.64041666667 | 14488 |
| 014884 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:31pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593313.9 | 509882.8 | 24978 | 1.64041666667 | 14884 |
| 014995 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:32pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593314.2 | 509885.6 | 24980 | 1.64041666667 | 14995 |
| 015109 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:33pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593314.3 | 509888.8 | 24982 | 1.64041666667 | 15109 |
| 014761 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593314.8 | 509891.4 | 24984 | 1.64041666667 | 14761 |
| 012968 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:35pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593315.2 | 509894.6 | 24986 | 1.64041666667 | 12968 |
| 013669 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593315.1 | 509897.4 | 24988 | 1.64041666667 | 13669 |
| 013036 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:37pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593314.7 | 509900.6 | 24990 | 1.64041666667 | 13036 |
| 012680 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593314.5 | 509903.3 | 24992 | 1.64041666667 | 12680 |
| 012630 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:39pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593314.2 | 509906.4 | 24994 | 1.64041666667 | 12630 |
| 012714 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593313.6 | 509909.0 | 24996 | 1.64041666667 | 12714 |
| 012057 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:41pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593312.7 | 509912.0 | 24998 | 1.64041666667 | 12057 |
| 013329 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593312.7 | 509914.4 | 25000 | 1.64041666667 | 13329 |
| 012973 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:43pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593311.7 | 509917.6 | 25002 | 1.64041666667 | 12973 |
| 013102 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593310.8 | 509920.2 | 25004 | 1.64041666667 | 13102 |
| 013040 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:45pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593310.5 | 509923.5 | 25006 | 1.64041666667 | 13040 |
| 012877 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593309.7 | 509925.8 | 25008 | 1.64041666667 | 12877 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012673 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593307.9 | 509928.5 | 25011 | 1.64041666667 | 12673 |
| 012288 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593307.1 | 509930.7 | 25012 | 1.64041666667 | 12288 |
| 013182 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593306.6 | 509934.1 | 25015 | 1.64041666667 | 13182 |
| 012335 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593305.8 | 509936.4 | 25016 | 1.64041666667 | 12335 |
| 012466 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:51pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593305.9 | 509939.3 | 25018 | 1.64041666667 | 12466 |
| 013409 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:52pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593305.9 | 509941.9 | 25020 | 1.64041666667 | 13409 |
| 013078 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:53pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593304.5 | 509944.9 | 25022 | 1.64041666667 | 13078 |
| 012801 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593303.1 | 509947.3 | 25024 | 1.64041666667 | 12801 |
| 012863 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593301.9 | 509950.2 | 25026 | 1.64041666667 | 12863 |
| 013378 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593300.2 | 509952.3 | 25028 | 1.64041666667 | 13378 |
| 013450 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:57pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593298.5 | 509955.0 | 25030 | 1.64041666667 | 13450 |
| 012883 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:58pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593297.9 | 509957.4 | 25032 | 1.64041666667 | 12883 |
| 013621 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:59pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593296.2 | 509960.1 | 25034 | 1.64041666667 | 13621 |
| 013189 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:00pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593294.4 | 509962.1 | 25036 | 1.64041666667 | 13189 |
| 013164 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:01pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593292.5 | 509964.5 | 25038 | 1.64041666667 | 13164 |
| 012729 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:02pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593290.9 | 509966.5 | 25040 | 1.64041666667 | 12729 |
| 012515 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:03pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593288.7 | 509968.9 | 25042 | 1.64041666667 | 12515 |
| 011734 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593287.1 | 509971.1 | 25044 | 1.64041666667 | 11734 |
| 011460 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:05pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593285.8 | 509973.8 | 25046 | 1.64041666667 | 11460 |
| 011839 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:06pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593285.1 | 509975.7 | 25048 | 1.64041666667 | 11839 |
| 012059 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:07pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593283.4 | 509978.5 | 25050 | 1.64041666667 | 12059 |
| 012821 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593281.6 | 509981.0 | 25052 | 1.64041666667 | 12821 |
| 013031 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:09pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593280.5 | 509983.7 | 25054 | 1.64041666667 | 13031 |
| 012430 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:10pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593279.3 | 509986.1 | 25056 | 1.64041666667 | 12430 |
| 012362 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:11pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593277.5 | 509989.0 | 25058 | 1.64041666667 | 12362 |
| 012803 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:12pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593276.2 | 509991.5 | 25060 | 1.64041666667 | 12803 |
| 012744 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:13pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593275.6 | 509994.7 | 25062 | 1.64041666667 | 12744 |
| 012996 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:14pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593275.5 | 509997.7 | 25064 | 1.64041666667 | 12996 |
| 012868 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:15pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593275.1 | 510000.8 | 25066 | 1.64041666667 | 12868 |
| 013050 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:16pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593274.1 | 510003.3 | 25068 | 1.64041666667 | 13050 |
| 013273 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:17pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593272.6 | 510006.4 | 25070 | 1.64041666667 | 13273 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:18pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593271.5 | 510009.0 | 25072 | 1.64041666667 | 13953 |
| 012394 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:19pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593270.2 | 510011.9 | 25074 | 1.64041666667 | 12394 |
| 011899 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:20pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593269.4 | 510014.1 | 25076 | 1.64041666667 | 11899 |
| 011590 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:21pm | Sensor | 1797-S0026-905-G-ACK | 6803.0 | 1593268.1 | 510016.9 | 25078 | 1.64041666667 | 11590 |
| 012017 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:22pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593266.7 | 510019.3 | 25080 | 1.64041666667 | 12017 |
| 011724 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:23pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593265.0 | 510021.6 | 25082 | 1.64041666667 | 11724 |
| 012340 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:24pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593263.7 | 510023.8 | 25084 | 1.64041666667 | 12340 |
| 012258 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:25pm | Sensor | 1797-S0026-905-G-ACK | 6803.3 | 1593262.3 | 510026.5 | 25086 | 1.64041666667 | 12258 |
| 012453 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:26pm | Sensor | 1797-S0026-905-G-ACK | 6803.2 | 1593260.5 | 510028.4 | 25088 | 1.64041666667 | 12453 |
| 011422 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:27pm | Sensor | 1797-S0026-905-G-ACK | 6803.4 | 1593258.3 | 510030.0 | 25090 | 1.64041666667 | 11422 |
| 012297 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:28pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593256.4 | 510031.6 | 25092 | 1.64041666667 | 12297 |
| 011402 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:29pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593254.3 | 510033.8 | 25094 | 1.64041666667 | 11402 |
| 011626 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:30pm | Sensor | 1797-S0026-905-G-ACK | 6802.9 | 1593252.7 | 510035.7 | 25096 | 1.64041666667 | 11626 |
| 012179 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:31pm | Sensor | 1797-S0026-905-G-ACK | 6802.8 | 1593251.3 | 510038.3 | 25098 | 1.64041666667 | 12179 |
| 012671 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:32pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593250.3 | 510040.6 | 25100 | 1.64041666667 | 12671 |
| 012100 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:33pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593249.1 | 510043.7 | 25102 | 1.64041666667 | 12100 |
| 012528 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:34pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593247.8 | 510046.4 | 25104 | 1.64041666667 | 12528 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013534 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:35pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593246.2 | 510049.0 | 25106 | 1.64041666667 | 13534 |
| 012653 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:36pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593244.4 | 510051.5 | 25108 | 1.64041666667 | 12653 |
| 013005 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:37pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593242.8 | 510054.1 | 25110 | 1.64041666667 | 13005 |
| 012475 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:38pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593241.5 | 510056.4 | 25112 | 1.64041666667 | 12475 |
| 012214 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:39pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593240.4 | 510059.4 | 25114 | 1.64041666667 | 12214 |
| 014123 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:40pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593239.6 | 510062.1 | 25116 | 1.64041666667 | 14123 |
| 013749 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:41pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593238.5 | 510065.6 | 25118 | 1.64041666667 | 13749 |
| 013269 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:42pm | Sensor | 1797-S0026-905-G-ACK | 6802.5 | 1593237.8 | 510067.9 | 25120 | 1.64041666667 | 13269 |
| 012901 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:43pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593237.0 | 510071.1 | 25122 | 1.64041666667 | 12901 |
| 013032 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:44pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593236.5 | 510074.0 | 25124 | 1.64041666667 | 13032 |
| 013233 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:45pm | Sensor | 1797-S0026-905-G-ACK | 6802.3 | 1593235.8 | 510077.7 | 25126 | 1.64041666667 | 13233 |
| 013616 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:46pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593235.4 | 510080.4 | 25128 | 1.64041666667 | 13616 |
| 013599 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:47pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593234.4 | 510083.6 | 25130 | 1.64041666667 | 13599 |
| 013837 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:48pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593233.3 | 510086.1 | 25132 | 1.64041666667 | 13837 |
| 013078 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:49pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593231.7 | 510088.6 | 25134 | 1.64041666667 | 13078 |
| 013064 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:50pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593229.9 | 510090.7 | 25136 | 1.64041666667 | 13064 |
| 013288 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:51pm | Sensor | 1797-S0026-905-G-ACK | 6801.8 | 1593227.8 | 510093.5 | 25138 | 1.64041666667 | 13288 |
| 013122 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:52pm | Sensor | 1797-S0026-905-G-ACK | 6801.7 | 1593226.3 | 510095.3 | 25140 | 1.64041666667 | 13122 |
| 013261 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:53pm | Sensor | 1797-S0026-905-G-ACK | 6801.7 | 1593224.8 | 510097.5 | 25142 | 1.64041666667 | 13261 |
| 013436 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:54pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593223.5 | 510099.3 | 25144 | 1.64041666667 | 13436 |
| 012530 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:55pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593221.7 | 510101.0 | 25146 | 1.64041666667 | 12530 |
| 012351 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:56pm | Sensor | 1797-S0026-905-G-ACK | 6802.0 | 1593220.7 | 510103.0 | 25148 | 1.64041666667 | 12351 |
| 012205 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:57pm | Sensor | 1797-S0026-905-G-ACK | 6802.2 | 1593220.2 | 510105.6 | 25150 | 1.64041666667 | 12205 |
| 012993 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:58pm | Sensor | 1797-S0026-905-G-ACK | 6802.1 | 1593219.2 | 510108.3 | 25152 | 1.64041666667 | 12993 |
| 013391 | 0 | GeoXH 6000 | 08/18/2015 | 12:20:59pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593219.3 | 510111.5 | 25154 | 1.64041666667 | 13391 |
| 012542 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:00pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593220.0 | 510113.9 | 25156 | 1.64041666667 | 12542 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:01pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593220.7 | 510117.1 | 25158 | 1.64041666667 | 13295 |
| 013336 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:02pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593221.2 | 510120.1 | 25160 | 1.64041666667 | 13336 |
| 012909 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:03pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593221.9 | 510123.6 | 25162 | 1.64041666667 | 12909 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:04pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593222.5 | 510126.1 | 25164 | 1.64041666667 | 13043 |
| 013382 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:05pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593223.4 | 510128.9 | 25166 | 1.64041666667 | 13382 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:06pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593224.4 | 510130.5 | 25168 | 1.64041666667 | 12785 |
| 012974 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:07pm | Sensor | 1797-S0026-905-G-ACK | 6802.6 | 1593225.9 | 510133.0 | 25170 | 1.64041666667 | 12974 |
| 013162 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:08pm | Sensor | 1797-S0026-905-G-ACK | 6802.7 | 1593227.0 | 510135.5 | 25172 | 1.64041666667 | 13162 |
| 012466 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:10pm | Sensor | 1797-S0026-905-G-ACK | 6803.1 | 1593228.0 | 510137.3 | 25175 | 1.64041666667 | 12466 |
| 012487 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:10pm | Sensor | 1797-S0026-905-G-ACK | 6802.4 | 1593230.0 | 510137.3 | 25176 | 1.64041666667 | 12487 |
| 012581 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:11pm | Sensor | 1797-S0026-905-G-ACK | 6800.5 | 1593229.1 | 510137.6 | 25178 | 1.64041666667 | 12581 |
| 012042 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:12pm | Sensor | 1797-S0026-905-G-ACK | 6801.1 | 1593231.2 | 510138.3 | 25180 | 1.64041666667 | 12042 |
| 011956 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:13pm | Sensor | 1797-S0026-905-G-ACK | 6805.2 | 1593230.8 | 510138.7 | 25183 | 1.64041666667 | 11956 |
| 012522 | 0 | GeoXH 6000 | 08/18/2015 | 12:21:14pm | Sensor | 1797-S0026-905-G-ACK | 6805.3 | 1593230.9 | 510140.1 | 25185 | 1.64041666667 | 12522 |
| 013769 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593103.5 | 511223.3 | 19734 | 1.64041666667 | 13769 |
| 013505 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593103.5 | 511223.3 | 19736 | 1.64041666667 | 13505 |
| 013836 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593103.5 | 511223.3 | 19739 | 1.64041666667 | 13836 |
| 013753 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1593103.5 | 511223.3 | 19741 | 1.64041666667 | 13753 |
| 013923 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1593103.5 | 511223.3 | 19743 | 1.64041666667 | 13923 |
| 014199 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593103.5 | 511223.3 | 19745 | 1.64041666667 | 14199 |
| 014392 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1593103.6 | 511223.3 | 19747 | 1.64041666667 | 14392 |
| 013968 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1593103.5 | 511223.3 | 19749 | 1.64041666667 | 13968 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013407 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1593103.6 | 511223.2 | 19751 | 1.64041666667 | 13407 |
| 012933 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1593103.6 | 511223.2 | 19753 | 1.64041666667 | 12933 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593103.6 | 511223.3 | 19755 | 1.64041666667 | 14092 |
| 014069 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593103.6 | 511223.3 | 19757 | 1.64041666667 | 14069 |
| 013276 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593103.6 | 511223.3 | 19759 | 1.64041666667 | 13276 |
| 014083 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1593103.2 | 511224.0 | 19761 | 1.64041666667 | 14083 |
| 013389 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1593103.0 | 511226.0 | 19763 | 1.64041666667 | 13389 |
| 013853 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593102.0 | 511228.1 | 19765 | 1.64041666667 | 13853 |
| 014197 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1593100.4 | 511231.2 | 19767 | 1.64041666667 | 14197 |
| 014728 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1593099.4 | 511233.4 | 19769 | 1.64041666667 | 14728 |
| 014945 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1593098.8 | 511236.0 | 19771 | 1.64041666667 | 14945 |
| 014181 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1593098.7 | 511238.5 | 19773 | 1.64041666667 | 14181 |
| 015079 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1593098.7 | 511241.6 | 19775 | 1.64041666667 | 15079 |
| 014895 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:24pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593099.0 | 511243.8 | 19777 | 1.64041666667 | 14895 |
| 015660 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:25pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593099.3 | 511246.2 | 19779 | 1.64041666667 | 15660 |
| 015986 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:26pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593098.9 | 511248.1 | 19781 | 1.64041666667 | 15986 |
| 015382 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:27pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593097.5 | 511249.9 | 19783 | 1.64041666667 | 15382 |
| 015035 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:28pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1593095.8 | 511251.3 | 19785 | 1.64041666667 | 15035 |
| 015717 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:29pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1593093.4 | 511252.5 | 19787 | 1.64041666667 | 15717 |
| 015726 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:30pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593091.2 | 511253.1 | 19789 | 1.64041666667 | 15726 |
| 015656 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:31pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593088.4 | 511253.9 | 19791 | 1.64041666667 | 15656 |
| 015489 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:32pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593086.1 | 511255.2 | 19793 | 1.64041666667 | 15489 |
| 014922 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:33pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1593083.6 | 511256.7 | 19795 | 1.64041666667 | 14922 |
| 015646 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:34pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1593081.1 | 511258.0 | 19797 | 1.64041666667 | 15646 |
| 016248 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:35pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593078.5 | 511259.3 | 19799 | 1.64041666667 | 16248 |
| 016789 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:36pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593076.6 | 511260.3 | 19801 | 1.64041666667 | 16789 |
| 016381 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:37pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593073.9 | 511261.5 | 19803 | 1.64041666667 | 16381 |
| 016414 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:38pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593071.7 | 511262.4 | 19805 | 1.64041666667 | 16414 |
| 016080 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:39pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593069.3 | 511263.7 | 19807 | 1.64041666667 | 16080 |
| 015982 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:40pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593067.6 | 511265.0 | 19809 | 1.64041666667 | 15982 |
| 015987 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:41pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593065.4 | 511266.1 | 19811 | 1.64041666667 | 15987 |
| 015885 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:42pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593064.2 | 511266.8 | 19813 | 1.64041666667 | 15885 |
| 016263 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:43pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593063.8 | 511267.3 | 19815 | 1.64041666667 | 16263 |
| 015620 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:44pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593063.9 | 511267.4 | 19817 | 1.64041666667 | 15620 |
| 015161 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:45pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593063.9 | 511267.4 | 19819 | 1.64041666667 | 15161 |
| 016208 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:46pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593064.0 | 511267.5 | 19821 | 1.64041666667 | 16208 |
| 015889 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:47pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593064.0 | 511267.5 | 19823 | 1.64041666667 | 15889 |
| 015815 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:48pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593063.9 | 511267.6 | 19825 | 1.64041666667 | 15815 |
| 015443 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:49pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593063.9 | 511267.7 | 19827 | 1.64041666667 | 15443 |
| 015362 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:50pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593064.0 | 511267.7 | 19829 | 1.64041666667 | 15362 |
| 015548 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:51pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593064.0 | 511267.6 | 19831 | 1.64041666667 | 15548 |
| 014258 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:52pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593063.9 | 511267.6 | 19833 | 1.64041666667 | 14258 |
| 014545 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:53pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593063.9 | 511267.6 | 19835 | 1.64041666667 | 14545 |
| 015052 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:54pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593063.9 | 511267.6 | 19837 | 1.64041666667 | 15052 |
| 014984 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:55pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593063.7 | 511267.5 | 19839 | 1.64041666667 | 14984 |
| 015013 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:56pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593063.2 | 511267.4 | 19841 | 1.64041666667 | 15013 |
| 016020 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1593061.5 | 511268.2 | 19843 | 1.64041666667 | 16020 |
| 016121 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:58pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593059.9 | 511269.5 | 19845 | 1.64041666667 | 16121 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015510 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:59pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593057.8 | 511271.1 | 19847 | 1.64041666667 | 15510 |
| 015977 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:00pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593056.8 | 511272.6 | 19849 | 1.64041666667 | 15977 |
| 015234 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:01pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593056.5 | 511274.0 | 19851 | 1.64041666667 | 15234 |
| 015094 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:02pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593056.4 | 511274.5 | 19853 | 1.64041666667 | 15094 |
| 014805 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:03pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593056.5 | 511274.8 | 19855 | 1.64041666667 | 14805 |
| 015340 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:04pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593056.6 | 511274.8 | 19857 | 1.64041666667 | 15340 |
| 015514 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:05pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593056.5 | 511274.9 | 19859 | 1.64041666667 | 15514 |
| 015506 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:06pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593056.5 | 511274.9 | 19861 | 1.64041666667 | 15506 |
| 015457 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:07pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593056.5 | 511274.9 | 19863 | 1.64041666667 | 15457 |
| 015857 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:08pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593056.4 | 511275.0 | 19865 | 1.64041666667 | 15857 |
| 015444 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:09pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593054.9 | 511275.3 | 19867 | 1.64041666667 | 15444 |
| 016030 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:10pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593053.0 | 511276.2 | 19869 | 1.64041666667 | 16030 |
| 015279 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:11pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593050.3 | 511277.6 | 19871 | 1.64041666667 | 15279 |
| 015854 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:12pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593047.8 | 511279.1 | 19873 | 1.64041666667 | 15854 |
| 014948 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:13pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593044.8 | 511280.7 | 19875 | 1.64041666667 | 14948 |
| 013748 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:14pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593041.9 | 511281.7 | 19877 | 1.64041666667 | 13748 |
| 014903 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:15pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593038.8 | 511283.2 | 19879 | 1.64041666667 | 14903 |
| 014495 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:16pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593036.5 | 511284.4 | 19881 | 1.64041666667 | 14495 |
| 014236 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:17pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593033.4 | 511286.1 | 19883 | 1.64041666667 | 14236 |
| 014113 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:18pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593030.9 | 511287.2 | 19885 | 1.64041666667 | 14113 |
| 014073 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:19pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593027.4 | 511288.4 | 19887 | 1.64041666667 | 14073 |
| 014291 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:20pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593024.5 | 511289.3 | 19889 | 1.64041666667 | 14291 |
| 014759 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:21pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593021.4 | 511290.4 | 19891 | 1.64041666667 | 14759 |
| 015097 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1593018.8 | 511291.7 | 19893 | 1.64041666667 | 15097 |
| 014897 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:23pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593016.0 | 511293.3 | 19895 | 1.64041666667 | 14897 |
| 014649 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:24pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1593013.3 | 511294.7 | 19897 | 1.64041666667 | 14649 |
| 014450 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:25pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1593010.4 | 511295.9 | 19899 | 1.64041666667 | 14450 |
| 014713 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:26pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593007.6 | 511297.0 | 19901 | 1.64041666667 | 14713 |
| 014208 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:27pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1593005.0 | 511298.7 | 19903 | 1.64041666667 | 14208 |
| 014742 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1593002.4 | 511300.0 | 19905 | 1.64041666667 | 14742 |
| 014742 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:29pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592999.3 | 511300.8 | 19907 | 1.64041666667 | 14742 |
| 014405 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592996.3 | 511301.8 | 19909 | 1.64041666667 | 14405 |
| 014568 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:31pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592993.1 | 511302.8 | 19911 | 1.64041666667 | 14568 |
| 014862 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:32pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592990.3 | 511303.2 | 19913 | 1.64041666667 | 14862 |
| 014127 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592987.4 | 511303.8 | 19915 | 1.64041666667 | 14127 |
| 014156 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592984.8 | 511304.8 | 19917 | 1.64041666667 | 14156 |
| 014263 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592981.6 | 511306.0 | 19919 | 1.64041666667 | 14263 |
| 013918 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592978.7 | 511306.7 | 19921 | 1.64041666667 | 13918 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592975.6 | 511308.0 | 19923 | 1.64041666667 | 13491 |
| 013499 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592973.0 | 511309.4 | 19925 | 1.64041666667 | 13499 |
| 013428 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592970.1 | 511311.0 | 19927 | 1.64041666667 | 13428 |
| 014363 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592967.6 | 511312.2 | 19929 | 1.64041666667 | 14363 |
| 014311 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592964.3 | 511313.9 | 19931 | 1.64041666667 | 14311 |
| 013998 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592961.5 | 511315.4 | 19933 | 1.64041666667 | 13998 |
| 014436 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592958.5 | 511317.2 | 19935 | 1.64041666667 | 14436 |
| 014023 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592956.0 | 511318.9 | 19937 | 1.64041666667 | 14023 |
| 014225 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592953.1 | 511320.8 | 19939 | 1.64041666667 | 14225 |
| 014406 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592950.4 | 511322.3 | 19941 | 1.64041666667 | 14406 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013586 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592947.2 | 511323.4 | 19943 | 1.64041666667 | 13586 |
| 014085 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592944.7 | 511324.5 | 19945 | 1.64041666667 | 14085 |
| 014035 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592941.6 | 511326.1 | 19947 | 1.64041666667 | 14035 |
| 014517 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592938.7 | 511327.8 | 19949 | 1.64041666667 | 14517 |
| 013618 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592935.5 | 511329.3 | 19951 | 1.64041666667 | 13618 |
| 014350 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592932.7 | 511330.2 | 19953 | 1.64041666667 | 14350 |
| 013959 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592929.6 | 511331.5 | 19955 | 1.64041666667 | 13959 |
| 014025 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592926.8 | 511332.7 | 19957 | 1.64041666667 | 14025 |
| 014241 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592923.7 | 511333.6 | 19959 | 1.64041666667 | 14241 |
| 013703 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592921.6 | 511334.4 | 19961 | 1.64041666667 | 13703 |
| 013663 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592919.0 | 511336.1 | 19963 | 1.64041666667 | 13663 |
| 014368 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:58pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592916.6 | 511336.8 | 19965 | 1.64041666667 | 14368 |
| 013984 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592913.7 | 511337.8 | 19967 | 1.64041666667 | 13984 |
| 014391 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592911.7 | 511338.9 | 19969 | 1.64041666667 | 14391 |
| 014245 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592908.9 | 511339.9 | 19971 | 1.64041666667 | 14245 |
| 014650 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592907.1 | 511341.0 | 19973 | 1.64041666667 | 14650 |
| 014368 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592904.8 | 511342.1 | 19975 | 1.64041666667 | 14368 |
| 014059 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592902.5 | 511342.5 | 19977 | 1.64041666667 | 14059 |
| 013841 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592899.6 | 511343.5 | 19979 | 1.64041666667 | 13841 |
| 013980 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592896.9 | 511344.3 | 19981 | 1.64041666667 | 13980 |
| 013594 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592893.7 | 511344.7 | 19983 | 1.64041666667 | 13594 |
| 013114 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592891.0 | 511345.2 | 19985 | 1.64041666667 | 13114 |
| 013901 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592888.1 | 511346.2 | 19987 | 1.64041666667 | 13901 |
| 014089 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592885.1 | 511346.7 | 19989 | 1.64041666667 | 14089 |
| 014248 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592882.7 | 511348.1 | 19991 | 1.64041666667 | 14248 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592881.0 | 511349.9 | 19993 | 1.64041666667 | 14111 |
| 015288 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592879.4 | 511352.2 | 19995 | 1.64041666667 | 15288 |
| 014142 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592879.6 | 511353.8 | 19997 | 1.64041666667 | 14142 |
| 014344 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592879.5 | 511356.0 | 19999 | 1.64041666667 | 14344 |
| 014181 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592879.9 | 511357.7 | 20001 | 1.64041666667 | 14181 |
| 013669 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592880.2 | 511359.7 | 20003 | 1.64041666667 | 13669 |
| 013282 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592880.3 | 511361.5 | 20005 | 1.64041666667 | 13282 |
| 013313 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592880.9 | 511363.0 | 20007 | 1.64041666667 | 13313 |
| 013293 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592881.0 | 511363.4 | 20009 | 1.64041666667 | 13293 |
| 014317 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592880.0 | 511363.2 | 20011 | 1.64041666667 | 14317 |
| 014151 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592878.5 | 511363.0 | 20013 | 1.64041666667 | 14151 |
| 014042 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592876.4 | 511361.9 | 20015 | 1.64041666667 | 14042 |
| 014664 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592874.6 | 511360.5 | 20017 | 1.64041666667 | 14664 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592872.3 | 511360.1 | 20019 | 1.64041666667 | 14458 |
| 013780 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592870.1 | 511359.8 | 20021 | 1.64041666667 | 13780 |
| 014478 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592867.9 | 511360.0 | 20023 | 1.64041666667 | 14478 |
| 013949 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592865.8 | 511360.3 | 20025 | 1.64041666667 | 13949 |
| 014094 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592863.1 | 511359.8 | 20027 | 1.64041666667 | 14094 |
| 014700 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592861.0 | 511359.3 | 20029 | 1.64041666667 | 14700 |
| 013968 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592858.9 | 511358.2 | 20031 | 1.64041666667 | 13968 |
| 014360 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592857.3 | 511356.6 | 20033 | 1.64041666667 | 14360 |
| 014182 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592855.5 | 511355.3 | 20035 | 1.64041666667 | 14182 |
| 014405 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592854.1 | 511353.7 | 20037 | 1.64041666667 | 14405 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014793 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592852.7 | 511351.4 | 20039 | 1.64041666667 | 14793 |
| 014643 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592851.0 | 511349.8 | 20041 | 1.64041666667 | 14643 |
| 014537 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592848.8 | 511347.9 | 20043 | 1.64041666667 | 14537 |
| 014672 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592847.1 | 511346.6 | 20045 | 1.64041666667 | 14672 |
| 014485 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592844.5 | 511344.7 | 20047 | 1.64041666667 | 14485 |
| 015678 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592842.8 | 511343.2 | 20049 | 1.64041666667 | 15678 |
| 015119 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592840.4 | 511341.5 | 20051 | 1.64041666667 | 15119 |
| 014054 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:42pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592838.6 | 511340.1 | 20053 | 1.64041666667 | 14054 |
| 014340 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592836.5 | 511338.1 | 20055 | 1.64041666667 | 14340 |
| 014239 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592834.5 | 511336.8 | 20057 | 1.64041666667 | 14239 |
| 014752 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592832.7 | 511335.1 | 20059 | 1.64041666667 | 14752 |
| 013795 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592831.0 | 511333.6 | 20061 | 1.64041666667 | 13795 |
| 014082 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592829.6 | 511332.0 | 20063 | 1.64041666667 | 14082 |
| 015301 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592828.7 | 511329.9 | 20065 | 1.64041666667 | 15301 |
| 015424 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592827.4 | 511327.9 | 20067 | 1.64041666667 | 15424 |
| 015156 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592826.3 | 511325.9 | 20069 | 1.64041666667 | 15156 |
| 015560 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592824.5 | 511325.1 | 20071 | 1.64041666667 | 15560 |
| 014925 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592822.4 | 511324.6 | 20073 | 1.64041666667 | 14925 |
| 014590 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592819.9 | 511323.5 | 20075 | 1.64041666667 | 14590 |
| 015272 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592817.6 | 511323.2 | 20077 | 1.64041666667 | 15272 |
| 014905 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592815.3 | 511322.3 | 20079 | 1.64041666667 | 14905 |
| 014444 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592813.3 | 511321.3 | 20081 | 1.64041666667 | 14444 |
| 014710 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592810.9 | 511320.4 | 20083 | 1.64041666667 | 14710 |
| 014881 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592808.8 | 511319.3 | 20085 | 1.64041666667 | 14881 |
| 014153 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592806.4 | 511318.6 | 20087 | 1.64041666667 | 14153 |
| 014433 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592804.2 | 511317.8 | 20089 | 1.64041666667 | 14433 |
| 013826 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592801.5 | 511316.4 | 20091 | 1.64041666667 | 13826 |
| 014272 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:02pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592799.1 | 511316.1 | 20093 | 1.64041666667 | 14272 |
| 014800 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592796.2 | 511316.2 | 20095 | 1.64041666667 | 14800 |
| 014715 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:04pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592793.6 | 511316.2 | 20097 | 1.64041666667 | 14715 |
| 014487 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592790.8 | 511316.6 | 20099 | 1.64041666667 | 14487 |
| 014329 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592788.4 | 511316.5 | 20101 | 1.64041666667 | 14329 |
| 014525 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:07pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592785.5 | 511316.3 | 20103 | 1.64041666667 | 14525 |
| 014260 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592783.4 | 511316.5 | 20105 | 1.64041666667 | 14260 |
| 014996 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:09pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592781.1 | 511315.9 | 20107 | 1.64041666667 | 14996 |
| 014870 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:10pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592778.7 | 511315.3 | 20109 | 1.64041666667 | 14870 |
| 015002 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:11pm | Sensor | 1797-S0025-905-G-ACK | 6806.7 | 1592776.3 | 511315.0 | 20111 | 1.64041666667 | 15002 |
| 014701 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:12pm | Sensor | 1797-S0025-905-G-ACK | 6806.7 | 1592775.3 | 511314.3 | 20113 | 1.64041666667 | 14701 |
| 014846 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:13pm | Sensor | 1797-S0025-905-G-ACK | 6806.7 | 1592774.7 | 511312.5 | 20115 | 1.64041666667 | 14846 |
| 015401 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:14pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592774.2 | 511310.6 | 20117 | 1.64041666667 | 15401 |
| 015075 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:15pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592774.4 | 511308.6 | 20119 | 1.64041666667 | 15075 |
| 014472 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:16pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592774.3 | 511306.8 | 20121 | 1.64041666667 | 14472 |
| 015168 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:17pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592774.1 | 511306.3 | 20123 | 1.64041666667 | 15168 |
| 014502 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:18pm | Sensor | 1797-S0025-905-G-ACK | 6806.7 | 1592774.1 | 511306.6 | 20125 | 1.64041666667 | 14502 |
| 015260 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:19pm | Sensor | 1797-S0025-905-G-ACK | 6806.6 | 1592774.7 | 511307.5 | 20127 | 1.64041666667 | 15260 |
| 014928 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:20pm | Sensor | 1797-S0025-905-G-ACK | 6806.6 | 1592774.4 | 511308.8 | 20129 | 1.64041666667 | 14928 |
| 015057 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:21pm | Sensor | 1797-S0025-905-G-ACK | 6806.7 | 1592772.6 | 511310.9 | 20131 | 1.64041666667 | 15057 |
| 014773 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:22pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592772.0 | 511312.8 | 20133 | 1.64041666667 | 14773 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014701 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:23pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592771.5 | 511315.3 | 20135 | 1.64041666667 | 14701 |
| 014802 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:24pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592770.6 | 511317.5 | 20137 | 1.64041666667 | 14802 |
| 015526 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592770.4 | 511319.7 | 20139 | 1.64041666667 | 15526 |
| 015228 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:26pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592770.3 | 511322.0 | 20141 | 1.64041666667 | 15228 |
| 015316 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:27pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592771.4 | 511323.7 | 20143 | 1.64041666667 | 15316 |
| 015102 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:28pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592773.3 | 511324.6 | 20145 | 1.64041666667 | 15102 |
| 014787 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:29pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592776.1 | 511325.3 | 20147 | 1.64041666667 | 14787 |
| 014903 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:30pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592778.1 | 511325.0 | 20149 | 1.64041666667 | 14903 |
| 015050 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:31pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592780.6 | 511325.0 | 20151 | 1.64041666667 | 15050 |
| 014181 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:32pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592783.0 | 511325.7 | 20153 | 1.64041666667 | 14181 |
| 014216 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:33pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592785.4 | 511326.3 | 20155 | 1.64041666667 | 14216 |
| 013727 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592787.6 | 511326.8 | 20157 | 1.64041666667 | 13727 |
| 013676 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592790.0 | 511326.7 | 20159 | 1.64041666667 | 13676 |
| 013963 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592792.0 | 511327.1 | 20161 | 1.64041666667 | 13963 |
| 014656 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:37pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592794.5 | 511327.9 | 20163 | 1.64041666667 | 14656 |
| 014202 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:38pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592796.5 | 511328.6 | 20165 | 1.64041666667 | 14202 |
| 014748 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:39pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592798.8 | 511329.8 | 20167 | 1.64041666667 | 14748 |
| 015353 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:40pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592800.9 | 511330.5 | 20169 | 1.64041666667 | 15353 |
| 014733 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:41pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592803.2 | 511331.9 | 20171 | 1.64041666667 | 14733 |
| 014700 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:42pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592805.1 | 511333.1 | 20173 | 1.64041666667 | 14700 |
| 014763 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592807.5 | 511334.0 | 20175 | 1.64041666667 | 14763 |
| 015257 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592809.6 | 511335.3 | 20177 | 1.64041666667 | 15257 |
| 015399 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592811.8 | 511336.3 | 20179 | 1.64041666667 | 15399 |
| 014737 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592813.8 | 511337.4 | 20181 | 1.64041666667 | 14737 |
| 014942 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592816.4 | 511339.1 | 20183 | 1.64041666667 | 14942 |
| 014390 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592818.7 | 511339.9 | 20185 | 1.64041666667 | 14390 |
| 013636 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592821.3 | 511341.1 | 20187 | 1.64041666667 | 13636 |
| 013903 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592823.4 | 511342.2 | 20189 | 1.64041666667 | 13903 |
| 014983 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592826.2 | 511343.2 | 20191 | 1.64041666667 | 14983 |
| 014698 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592828.2 | 511344.5 | 20193 | 1.64041666667 | 14698 |
| 015715 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592830.8 | 511346.4 | 20195 | 1.64041666667 | 15715 |
| 015274 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592833.3 | 511347.8 | 20197 | 1.64041666667 | 15274 |
| 015334 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592835.8 | 511349.7 | 20199 | 1.64041666667 | 15334 |
| 014610 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592837.9 | 511350.8 | 20201 | 1.64041666667 | 14610 |
| 014376 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592840.6 | 511352.0 | 20203 | 1.64041666667 | 14376 |
| 014251 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592842.7 | 511353.4 | 20205 | 1.64041666667 | 14251 |
| 014804 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592845.1 | 511354.7 | 20207 | 1.64041666667 | 14804 |
| 014102 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592847.6 | 511355.7 | 20209 | 1.64041666667 | 14102 |
| 014300 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592850.4 | 511357.2 | 20211 | 1.64041666667 | 14300 |
| 014538 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592852.8 | 511358.3 | 20213 | 1.64041666667 | 14538 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592855.8 | 511359.6 | 20215 | 1.64041666667 | 13953 |
| 015056 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592858.2 | 511360.8 | 20217 | 1.64041666667 | 15056 |
| 015496 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592860.8 | 511361.4 | 20219 | 1.64041666667 | 15496 |
| 014664 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592863.0 | 511362.3 | 20221 | 1.64041666667 | 14664 |
| 013791 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592865.8 | 511363.9 | 20223 | 1.64041666667 | 13791 |
| 014035 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592868.2 | 511364.7 | 20225 | 1.64041666667 | 14035 |
| 013767 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592871.0 | 511365.6 | 20227 | 1.64041666667 | 13767 |
| 013796 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592873.6 | 511366.6 | 20229 | 1.64041666667 | 13796 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014705 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592876.1 | 511367.2 | 20231 | 1.64041666667 | 14705 |
| 014804 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592878.4 | 511368.4 | 20233 | 1.64041666667 | 14804 |
| 014665 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592881.0 | 511370.1 | 20235 | 1.64041666667 | 14665 |
| 015456 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592882.9 | 511370.9 | 20237 | 1.64041666667 | 15456 |
| 015256 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592883.7 | 511372.0 | 20239 | 1.64041666667 | 15256 |
| 015294 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592884.0 | 511373.5 | 20241 | 1.64041666667 | 15294 |
| 014955 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592883.5 | 511375.6 | 20243 | 1.64041666667 | 14955 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592882.8 | 511377.3 | 20245 | 1.64041666667 | 14210 |
| 014360 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592882.2 | 511379.2 | 20247 | 1.64041666667 | 14360 |
| 014137 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592881.4 | 511380.7 | 20249 | 1.64041666667 | 14137 |
| 014725 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592880.4 | 511382.8 | 20251 | 1.64041666667 | 14725 |
| 015273 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592879.3 | 511382.9 | 20253 | 1.64041666667 | 15273 |
| 014868 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592877.1 | 511382.1 | 20255 | 1.64041666667 | 14868 |
| 014191 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592875.2 | 511381.5 | 20257 | 1.64041666667 | 14191 |
| 014185 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592873.0 | 511380.2 | 20259 | 1.64041666667 | 14185 |
| 014714 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592871.1 | 511379.6 | 20261 | 1.64041666667 | 14714 |
| 016001 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592869.0 | 511378.7 | 20263 | 1.64041666667 | 16001 |
| 016283 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592866.7 | 511377.9 | 20265 | 1.64041666667 | 16283 |
| 015264 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592864.0 | 511377.6 | 20267 | 1.64041666667 | 15264 |
| 014811 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592861.9 | 511376.9 | 20269 | 1.64041666667 | 14811 |
| 015096 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592859.2 | 511376.4 | 20271 | 1.64041666667 | 15096 |
| 015234 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592857.0 | 511376.2 | 20273 | 1.64041666667 | 15234 |
| 015709 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592854.3 | 511375.6 | 20275 | 1.64041666667 | 15709 |
| 014453 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592852.2 | 511375.9 | 20277 | 1.64041666667 | 14453 |
| 014632 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592849.8 | 511375.9 | 20279 | 1.64041666667 | 14632 |
| 013833 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592847.3 | 511376.1 | 20281 | 1.64041666667 | 13833 |
| 014126 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592845.2 | 511377.1 | 20283 | 1.64041666667 | 14126 |
| 014486 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592844.3 | 511377.2 | 20285 | 1.64041666667 | 14486 |
| 014718 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592843.8 | 511377.2 | 20287 | 1.64041666667 | 14718 |
| 014871 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592844.5 | 511376.9 | 20289 | 1.64041666667 | 14871 |
| 014845 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592846.5 | 511376.3 | 20291 | 1.64041666667 | 14845 |
| 013863 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592848.2 | 511375.4 | 20293 | 1.64041666667 | 13863 |
| 013918 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592850.4 | 511374.4 | 20295 | 1.64041666667 | 13918 |
| 014473 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592852.1 | 511373.1 | 20297 | 1.64041666667 | 14473 |
| 014929 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592853.3 | 511370.8 | 20299 | 1.64041666667 | 14929 |
| 014637 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592853.8 | 511368.5 | 20301 | 1.64041666667 | 14637 |
| 014631 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592852.9 | 511366.3 | 20303 | 1.64041666667 | 14631 |
| 014380 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592850.9 | 511365.4 | 20305 | 1.64041666667 | 14380 |
| 013713 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592848.9 | 511364.0 | 20307 | 1.64041666667 | 13713 |
| 014389 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592847.4 | 511362.3 | 20309 | 1.64041666667 | 14389 |
| 014371 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592845.4 | 511361.0 | 20311 | 1.64041666667 | 14371 |
| 014901 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592843.6 | 511359.7 | 20313 | 1.64041666667 | 14901 |
| 015454 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592841.3 | 511358.5 | 20315 | 1.64041666667 | 15454 |
| 015098 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592839.5 | 511357.4 | 20317 | 1.64041666667 | 15098 |
| 015190 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592836.9 | 511355.2 | 20319 | 1.64041666667 | 15190 |
| 014964 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592834.9 | 511354.1 | 20321 | 1.64041666667 | 14964 |
| 015550 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592832.8 | 511352.4 | 20323 | 1.64041666667 | 15550 |
| 016104 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592831.2 | 511350.4 | 20325 | 1.64041666667 | 16104 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014751 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592829.4 | 511348.8 | 20327 | 1.64041666667 | 14751 |
| 014575 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592827.8 | 511347.1 | 20329 | 1.64041666667 | 14575 |
| 015053 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592826.3 | 511345.3 | 20331 | 1.64041666667 | 15053 |
| 014377 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:02pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592825.0 | 511344.3 | 20333 | 1.64041666667 | 14377 |
| 013855 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592823.2 | 511344.7 | 20335 | 1.64041666667 | 13855 |
| 014475 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:04pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592821.5 | 511345.7 | 20337 | 1.64041666667 | 14475 |
| 014930 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592819.2 | 511345.8 | 20339 | 1.64041666667 | 14930 |
| 014930 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592816.9 | 511345.7 | 20341 | 1.64041666667 | 14930 |
| 014473 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:07pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592814.5 | 511345.7 | 20343 | 1.64041666667 | 14473 |
| 014538 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592812.5 | 511344.5 | 20345 | 1.64041666667 | 14538 |
| 015378 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:09pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592810.3 | 511343.3 | 20347 | 1.64041666667 | 15378 |
| 016225 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:10pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592808.4 | 511341.9 | 20349 | 1.64041666667 | 16225 |
| 015464 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:11pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592806.2 | 511339.9 | 20351 | 1.64041666667 | 15464 |
| 015396 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:12pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592804.0 | 511338.5 | 20353 | 1.64041666667 | 15396 |
| 015072 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:13pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592801.3 | 511336.9 | 20355 | 1.64041666667 | 15072 |
| 014771 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:14pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592798.9 | 511334.9 | 20357 | 1.64041666667 | 14771 |
| 014466 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:15pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592796.3 | 511333.0 | 20359 | 1.64041666667 | 14466 |
| 013454 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:16pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592793.7 | 511331.6 | 20361 | 1.64041666667 | 13454 |
| 013583 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:17pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592791.3 | 511329.6 | 20363 | 1.64041666667 | 13583 |
| 014000 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:18pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592789.3 | 511328.5 | 20365 | 1.64041666667 | 14000 |
| 014317 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:19pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592786.8 | 511327.4 | 20367 | 1.64041666667 | 14317 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:20pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592784.7 | 511326.0 | 20369 | 1.64041666667 | 14556 |
| 014398 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:21pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592782.2 | 511324.8 | 20371 | 1.64041666667 | 14398 |
| 015096 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:22pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592780.9 | 511323.1 | 20373 | 1.64041666667 | 15096 |
| 015211 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:23pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592779.7 | 511320.4 | 20375 | 1.64041666667 | 15211 |
| 014234 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:24pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592778.5 | 511318.8 | 20377 | 1.64041666667 | 14234 |
| 014014 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:25pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592777.1 | 511316.7 | 20379 | 1.64041666667 | 14014 |
| 014707 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:26pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592775.9 | 511315.0 | 20381 | 1.64041666667 | 14707 |
| 014115 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:27pm | Sensor | 1797-S0025-905-G-ACK | 6806.7 | 1592774.3 | 511313.2 | 20383 | 1.64041666667 | 14115 |
| 014720 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:28pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592774.0 | 511311.3 | 20385 | 1.64041666667 | 14720 |
| 014182 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:29pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592773.3 | 511309.6 | 20387 | 1.64041666667 | 14182 |
| 014307 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:30pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592772.7 | 511310.1 | 20389 | 1.64041666667 | 14307 |
| 015023 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:31pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592772.2 | 511312.3 | 20391 | 1.64041666667 | 15023 |
| 014593 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:32pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592771.7 | 511314.5 | 20393 | 1.64041666667 | 14593 |
| 014921 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:33pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592771.0 | 511317.3 | 20395 | 1.64041666667 | 14921 |
| 015143 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:34pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592770.2 | 511319.6 | 20397 | 1.64041666667 | 15143 |
| 015598 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:35pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592769.9 | 511322.2 | 20399 | 1.64041666667 | 15598 |
| 014833 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:36pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592769.4 | 511324.6 | 20401 | 1.64041666667 | 14833 |
| 015184 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:37pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592768.8 | 511327.4 | 20403 | 1.64041666667 | 15184 |
| 015471 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:38pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592768.5 | 511329.8 | 20405 | 1.64041666667 | 15471 |
| 014477 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:39pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592768.4 | 511332.3 | 20407 | 1.64041666667 | 14477 |
| 013918 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:40pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592768.3 | 511334.8 | 20409 | 1.64041666667 | 13918 |
| 014429 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:41pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592768.9 | 511337.2 | 20411 | 1.64041666667 | 14429 |
| 014888 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:42pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592770.0 | 511338.8 | 20413 | 1.64041666667 | 14888 |
| 014345 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592772.2 | 511339.9 | 20415 | 1.64041666667 | 14345 |
| 014496 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592774.2 | 511340.7 | 20417 | 1.64041666667 | 14496 |
| 014784 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:45pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592776.7 | 511341.5 | 20419 | 1.64041666667 | 14784 |
| 015118 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592779.1 | 511341.9 | 20421 | 1.64041666667 | 15118 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015164 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592781.8 | 511342.6 | 20423 | 1.64041666667 | 15164 |
| 014965 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592784.1 | 511342.8 | 20425 | 1.64041666667 | 14965 |
| 015032 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592786.7 | 511343.2 | 20427 | 1.64041666667 | 15032 |
| 014688 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592788.5 | 511343.6 | 20429 | 1.64041666667 | 14688 |
| 013797 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592791.0 | 511344.2 | 20431 | 1.64041666667 | 13797 |
| 013686 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592792.7 | 511345.4 | 20433 | 1.64041666667 | 13686 |
| 014268 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592794.9 | 511346.9 | 20435 | 1.64041666667 | 14268 |
| 013958 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592796.8 | 511348.3 | 20437 | 1.64041666667 | 13958 |
| 014129 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592798.9 | 511350.2 | 20439 | 1.64041666667 | 14129 |
| 014127 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592801.0 | 511351.3 | 20441 | 1.64041666667 | 14127 |
| 013886 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592803.3 | 511352.7 | 20443 | 1.64041666667 | 13886 |
| 013968 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592805.6 | 511353.5 | 20445 | 1.64041666667 | 13968 |
| 013955 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592808.5 | 511354.1 | 20447 | 1.64041666667 | 13955 |
| 014952 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592811.4 | 511355.1 | 20449 | 1.64041666667 | 14952 |
| 015250 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592814.3 | 511355.9 | 20451 | 1.64041666667 | 15250 |
| 014758 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:02pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592816.8 | 511356.4 | 20453 | 1.64041666667 | 14758 |
| 014781 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592819.2 | 511357.7 | 20455 | 1.64041666667 | 14781 |
| 013917 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:04pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592821.5 | 511358.7 | 20457 | 1.64041666667 | 13917 |
| 014668 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592824.5 | 511359.4 | 20459 | 1.64041666667 | 14668 |
| 014731 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592826.9 | 511360.4 | 20461 | 1.64041666667 | 14731 |
| 014571 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:07pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592829.6 | 511361.1 | 20463 | 1.64041666667 | 14571 |
| 015208 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592831.7 | 511361.8 | 20465 | 1.64041666667 | 15208 |
| 015905 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:09pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592834.5 | 511363.5 | 20467 | 1.64041666667 | 15905 |
| 014879 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:10pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592836.6 | 511364.4 | 20469 | 1.64041666667 | 14879 |
| 014812 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:11pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592838.7 | 511365.9 | 20471 | 1.64041666667 | 14812 |
| 015194 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:12pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592840.6 | 511367.7 | 20473 | 1.64041666667 | 15194 |
| 015529 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592843.1 | 511368.9 | 20475 | 1.64041666667 | 15529 |
| 015470 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592845.2 | 511370.0 | 20477 | 1.64041666667 | 15470 |
| 014799 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592848.0 | 511371.7 | 20479 | 1.64041666667 | 14799 |
| 014332 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592850.6 | 511372.6 | 20481 | 1.64041666667 | 14332 |
| 015089 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592852.9 | 511373.8 | 20483 | 1.64041666667 | 15089 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592855.1 | 511374.5 | 20485 | 1.64041666667 | 14210 |
| 014578 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592857.6 | 511375.3 | 20487 | 1.64041666667 | 14578 |
| 014943 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592860.0 | 511376.9 | 20489 | 1.64041666667 | 14943 |
| 014457 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592862.5 | 511377.8 | 20491 | 1.64041666667 | 14457 |
| 015730 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592864.7 | 511378.8 | 20493 | 1.64041666667 | 15730 |
| 015830 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592867.6 | 511380.2 | 20495 | 1.64041666667 | 15830 |
| 015377 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592869.6 | 511380.7 | 20497 | 1.64041666667 | 15377 |
| 015962 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592871.9 | 511381.7 | 20499 | 1.64041666667 | 15962 |
| 014806 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592874.0 | 511382.5 | 20501 | 1.64041666667 | 14806 |
| 014883 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592876.6 | 511383.2 | 20503 | 1.64041666667 | 14883 |
| 014597 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592878.8 | 511384.2 | 20505 | 1.64041666667 | 14597 |
| 015110 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592880.8 | 511384.7 | 20507 | 1.64041666667 | 15110 |
| 015190 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592881.1 | 511385.7 | 20509 | 1.64041666667 | 15190 |
| 014064 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592880.7 | 511387.8 | 20511 | 1.64041666667 | 14064 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592880.3 | 511389.8 | 20513 | 1.64041666667 | 14158 |
| 014346 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592879.6 | 511392.0 | 20515 | 1.64041666667 | 14346 |
| 014025 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592879.4 | 511394.0 | 20517 | 1.64041666667 | 14025 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014331 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592879.1 | 511396.1 | 20519 | 1.64041666667 | 14331 |
| 014414 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592878.5 | 511397.3 | 20521 | 1.64041666667 | 14414 |
| 014497 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592877.0 | 511397.8 | 20523 | 1.64041666667 | 14497 |
| 015160 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592875.0 | 511397.6 | 20525 | 1.64041666667 | 15160 |
| 014902 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592872.8 | 511396.6 | 20527 | 1.64041666667 | 14902 |
| 015477 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592870.8 | 511396.0 | 20529 | 1.64041666667 | 15477 |
| 015358 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592868.5 | 511395.5 | 20531 | 1.64041666667 | 15358 |
| 014879 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592866.3 | 511394.7 | 20533 | 1.64041666667 | 14879 |
| 015404 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592863.9 | 511394.1 | 20535 | 1.64041666667 | 15404 |
| 014672 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592861.8 | 511393.0 | 20537 | 1.64041666667 | 14672 |
| 013758 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592859.5 | 511391.9 | 20539 | 1.64041666667 | 13758 |
| 014301 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592857.5 | 511391.3 | 20541 | 1.64041666667 | 14301 |
| 014352 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592854.9 | 511390.2 | 20543 | 1.64041666667 | 14352 |
| 014148 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592852.4 | 511389.3 | 20545 | 1.64041666667 | 14148 |
| 013868 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592849.8 | 511388.8 | 20547 | 1.64041666667 | 13868 |
| 013365 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592847.7 | 511387.8 | 20549 | 1.64041666667 | 13365 |
| 013991 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592845.2 | 511386.8 | 20551 | 1.64041666667 | 13991 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592842.8 | 511385.9 | 20553 | 1.64041666667 | 13915 |
| 013864 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592840.2 | 511384.7 | 20555 | 1.64041666667 | 13864 |
| 013724 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592837.9 | 511384.3 | 20557 | 1.64041666667 | 13724 |
| 013344 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592835.3 | 511383.5 | 20559 | 1.64041666667 | 13344 |
| 014114 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592833.3 | 511382.4 | 20561 | 1.64041666667 | 14114 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592831.2 | 511381.4 | 20563 | 1.64041666667 | 14516 |
| 014735 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592829.5 | 511380.1 | 20565 | 1.64041666667 | 14735 |
| 014836 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592827.6 | 511378.7 | 20567 | 1.64041666667 | 14836 |
| 015920 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592825.8 | 511377.6 | 20569 | 1.64041666667 | 15920 |
| 014107 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592823.9 | 511375.9 | 20571 | 1.64041666667 | 14107 |
| 013770 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:02pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592822.2 | 511374.9 | 20573 | 1.64041666667 | 13770 |
| 014571 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592820.0 | 511373.6 | 20575 | 1.64041666667 | 14571 |
| 015831 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:04pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592817.6 | 511372.2 | 20577 | 1.64041666667 | 15831 |
| 015805 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592815.0 | 511371.4 | 20579 | 1.64041666667 | 15805 |
| 015085 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592812.9 | 511370.4 | 20581 | 1.64041666667 | 15085 |
| 015048 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:07pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592810.4 | 511369.1 | 20583 | 1.64041666667 | 15048 |
| 014539 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592808.3 | 511368.3 | 20585 | 1.64041666667 | 14539 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:09pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592806.0 | 511366.9 | 20587 | 1.64041666667 | 14201 |
| 014288 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:10pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592803.6 | 511365.7 | 20589 | 1.64041666667 | 14288 |
| 014082 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:11pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592801.0 | 511364.5 | 20591 | 1.64041666667 | 14082 |
| 014056 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:12pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592798.8 | 511363.1 | 20593 | 1.64041666667 | 14056 |
| 014199 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:13pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592795.9 | 511362.1 | 20595 | 1.64041666667 | 14199 |
| 014669 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:14pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592793.5 | 511361.4 | 20597 | 1.64041666667 | 14669 |
| 014050 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:15pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592790.7 | 511360.0 | 20599 | 1.64041666667 | 14050 |
| 014106 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:16pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592788.3 | 511359.2 | 20601 | 1.64041666667 | 14106 |
| 015434 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:17pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592785.6 | 511358.3 | 20603 | 1.64041666667 | 15434 |
| 013947 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:18pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592783.3 | 511357.4 | 20605 | 1.64041666667 | 13947 |
| 014340 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:19pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592780.5 | 511356.9 | 20607 | 1.64041666667 | 14340 |
| 015258 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:20pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592778.4 | 511356.5 | 20609 | 1.64041666667 | 15258 |
| 015483 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:21pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592775.7 | 511355.7 | 20611 | 1.64041666667 | 15483 |
| 015122 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:22pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592773.1 | 511355.5 | 20613 | 1.64041666667 | 15122 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015102 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:23pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592770.6 | 511355.3 | 20615 | 1.64041666667 | 15102 |
| 014525 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:24pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592768.2 | 511355.1 | 20617 | 1.64041666667 | 14525 |
| 013405 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592765.6 | 511355.3 | 20619 | 1.64041666667 | 13405 |
| 013075 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:26pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592763.5 | 511355.0 | 20621 | 1.64041666667 | 13075 |
| 013655 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:27pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592760.8 | 511355.0 | 20623 | 1.64041666667 | 13655 |
| 013605 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:28pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592758.6 | 511355.7 | 20625 | 1.64041666667 | 13605 |
| 013233 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:29pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592756.7 | 511357.3 | 20627 | 1.64041666667 | 13233 |
| 013293 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:30pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592756.7 | 511359.2 | 20629 | 1.64041666667 | 13293 |
| 013380 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:31pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592757.1 | 511361.8 | 20631 | 1.64041666667 | 13380 |
| 013173 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:32pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592757.7 | 511364.0 | 20633 | 1.64041666667 | 13173 |
| 013897 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:33pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592759.7 | 511365.5 | 20635 | 1.64041666667 | 13897 |
| 012647 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592761.8 | 511366.5 | 20637 | 1.64041666667 | 12647 |
| 012521 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592764.1 | 511366.8 | 20639 | 1.64041666667 | 12521 |
| 013628 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592766.1 | 511367.0 | 20641 | 1.64041666667 | 13628 |
| 014138 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:37pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592768.8 | 511367.6 | 20643 | 1.64041666667 | 14138 |
| 014028 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:38pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592771.2 | 511367.7 | 20645 | 1.64041666667 | 14028 |
| 014295 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:39pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592773.8 | 511368.1 | 20647 | 1.64041666667 | 14295 |
| 014183 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:40pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592776.2 | 511368.6 | 20649 | 1.64041666667 | 14183 |
| 014511 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:41pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592778.9 | 511368.8 | 20651 | 1.64041666667 | 14511 |
| 015377 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:42pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592781.2 | 511369.5 | 20653 | 1.64041666667 | 15377 |
| 015782 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592783.5 | 511370.0 | 20655 | 1.64041666667 | 15782 |
| 016115 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592785.8 | 511370.1 | 20657 | 1.64041666667 | 16115 |
| 015162 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592788.5 | 511370.9 | 20659 | 1.64041666667 | 15162 |
| 014048 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592790.7 | 511371.3 | 20661 | 1.64041666667 | 14048 |
| 014494 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592793.3 | 511371.9 | 20663 | 1.64041666667 | 14494 |
| 014925 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592795.8 | 511372.6 | 20665 | 1.64041666667 | 14925 |
| 015588 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592798.2 | 511373.3 | 20667 | 1.64041666667 | 15588 |
| 014296 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592800.0 | 511374.3 | 20669 | 1.64041666667 | 14296 |
| 014499 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592802.5 | 511375.1 | 20671 | 1.64041666667 | 14499 |
| 014545 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592804.8 | 511375.8 | 20673 | 1.64041666667 | 14545 |
| 014939 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592807.3 | 511376.9 | 20675 | 1.64041666667 | 14939 |
| 014613 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592809.6 | 511377.7 | 20677 | 1.64041666667 | 14613 |
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592811.9 | 511378.8 | 20679 | 1.64041666667 | 14227 |
| 015510 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592814.1 | 511379.8 | 20681 | 1.64041666667 | 15510 |
| 015212 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592817.0 | 511380.6 | 20683 | 1.64041666667 | 15212 |
| 015142 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592819.0 | 511381.5 | 20685 | 1.64041666667 | 15142 |
| 014794 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592821.6 | 511382.5 | 20687 | 1.64041666667 | 14794 |
| 014089 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592824.1 | 511383.5 | 20689 | 1.64041666667 | 14089 |
| 015072 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592826.0 | 511385.2 | 20691 | 1.64041666667 | 15072 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592827.6 | 511386.3 | 20693 | 1.64041666667 | 14591 |
| 014170 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592829.3 | 511387.9 | 20695 | 1.64041666667 | 14170 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592830.8 | 511389.7 | 20697 | 1.64041666667 | 14458 |
| 014170 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592832.7 | 511391.1 | 20699 | 1.64041666667 | 14170 |
| 014263 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592834.5 | 511392.5 | 20701 | 1.64041666667 | 14263 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592836.7 | 511394.0 | 20703 | 1.64041666667 | 14210 |
| 015133 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592838.9 | 511395.0 | 20705 | 1.64041666667 | 15133 |
| 014752 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592841.3 | 511396.3 | 20707 | 1.64041666667 | 14752 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592843.5 | 511397.0 | 20709 | 1.64041666667 | 14283 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013787 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592846.0 | 511397.7 | 20711 | 1.64041666667 | 13787 |
| 013957 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592848.0 | 511398.0 | 20713 | 1.64041666667 | 13957 |
| 014661 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592850.6 | 511398.2 | 20715 | 1.64041666667 | 14661 |
| 014427 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592853.1 | 511398.8 | 20717 | 1.64041666667 | 14427 |
| 015262 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592855.4 | 511399.0 | 20719 | 1.64041666667 | 15262 |
| 013287 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592857.7 | 511399.2 | 20721 | 1.64041666667 | 13287 |
| 013294 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592860.4 | 511399.8 | 20723 | 1.64041666667 | 13294 |
| 013740 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592862.4 | 511400.3 | 20725 | 1.64041666667 | 13740 |
| 014291 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592864.6 | 511401.5 | 20727 | 1.64041666667 | 14291 |
| 014196 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592866.6 | 511402.5 | 20729 | 1.64041666667 | 14196 |
| 014533 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592868.0 | 511403.7 | 20731 | 1.64041666667 | 14533 |
| 014175 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592868.3 | 511405.8 | 20733 | 1.64041666667 | 14175 |
| 013823 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592868.4 | 511407.9 | 20735 | 1.64041666667 | 13823 |
| 013790 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592868.4 | 511409.2 | 20737 | 1.64041666667 | 13790 |
| 013809 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592868.1 | 511411.2 | 20739 | 1.64041666667 | 13809 |
| 013768 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592868.1 | 511412.3 | 20741 | 1.64041666667 | 13768 |
| 013834 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592868.2 | 511412.8 | 20743 | 1.64041666667 | 13834 |
| 014089 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592868.3 | 511412.9 | 20745 | 1.64041666667 | 14089 |
| 014090 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592867.7 | 511413.4 | 20747 | 1.64041666667 | 14090 |
| 014180 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592867.6 | 511413.6 | 20749 | 1.64041666667 | 14180 |
| 014329 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592867.8 | 511413.1 | 20751 | 1.64041666667 | 14329 |
| 014802 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592868.0 | 511413.1 | 20753 | 1.64041666667 | 14802 |
| 014799 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592868.2 | 511413.6 | 20755 | 1.64041666667 | 14799 |
| 015089 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592868.1 | 511414.0 | 20757 | 1.64041666667 | 15089 |
| 014442 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592867.6 | 511415.2 | 20759 | 1.64041666667 | 14442 |
| 014296 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592867.0 | 511416.2 | 20761 | 1.64041666667 | 14296 |
| 015226 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592865.7 | 511417.0 | 20763 | 1.64041666667 | 15226 |
| 014820 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592864.1 | 511416.6 | 20765 | 1.64041666667 | 14820 |
| 014013 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592862.1 | 511415.2 | 20767 | 1.64041666667 | 14013 |
| 014197 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592860.1 | 511414.2 | 20769 | 1.64041666667 | 14197 |
| 014623 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592857.9 | 511412.8 | 20771 | 1.64041666667 | 14623 |
| 014721 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592856.0 | 511411.7 | 20773 | 1.64041666667 | 14721 |
| 014333 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592853.7 | 511410.7 | 20775 | 1.64041666667 | 14333 |
| 013897 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592851.6 | 511409.4 | 20777 | 1.64041666667 | 13897 |
| 013194 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592849.3 | 511408.1 | 20779 | 1.64041666667 | 13194 |
| 013414 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592847.6 | 511407.0 | 20781 | 1.64041666667 | 13414 |
| 013935 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592845.9 | 511405.1 | 20783 | 1.64041666667 | 13935 |
| 014423 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592844.5 | 511403.9 | 20785 | 1.64041666667 | 14423 |
| 014196 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592842.5 | 511402.7 | 20787 | 1.64041666667 | 14196 |
| 014060 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592840.6 | 511402.3 | 20789 | 1.64041666667 | 14060 |
| 014381 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592838.2 | 511402.7 | 20791 | 1.64041666667 | 14381 |
| 014179 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592835.8 | 511402.8 | 20793 | 1.64041666667 | 14179 |
| 014831 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592833.1 | 511402.7 | 20795 | 1.64041666667 | 14831 |
| 014290 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592831.0 | 511402.3 | 20797 | 1.64041666667 | 14290 |
| 014743 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592828.8 | 511401.1 | 20799 | 1.64041666667 | 14743 |
| 014173 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592826.9 | 511400.0 | 20801 | 1.64041666667 | 14173 |
| 013754 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592824.7 | 511398.6 | 20803 | 1.64041666667 | 13754 |
| 013377 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592822.9 | 511396.9 | 20805 | 1.64041666667 | 13377 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013937 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592820.9 | 511395.3 | 20807 | 1.64041666667 | 13937 |
| 014724 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592819.2 | 511394.0 | 20809 | 1.64041666667 | 14724 |
| 013810 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592817.0 | 511392.1 | 20811 | 1.64041666667 | 13810 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:02pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592814.6 | 511390.9 | 20813 | 1.64041666667 | 13295 |
| 014003 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592812.1 | 511389.5 | 20815 | 1.64041666667 | 14003 |
| 013524 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:04pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592809.9 | 511388.2 | 20817 | 1.64041666667 | 13524 |
| 013412 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592807.3 | 511387.1 | 20819 | 1.64041666667 | 13412 |
| 012914 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592805.2 | 511385.8 | 20821 | 1.64041666667 | 12914 |
| 013137 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:07pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592803.1 | 511384.1 | 20823 | 1.64041666667 | 13137 |
| 013734 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592801.2 | 511382.8 | 20825 | 1.64041666667 | 13734 |
| 013605 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:09pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592799.2 | 511380.8 | 20827 | 1.64041666667 | 13605 |
| 013923 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:10pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592797.2 | 511379.1 | 20829 | 1.64041666667 | 13923 |
| 014169 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:11pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592794.6 | 511377.2 | 20831 | 1.64041666667 | 14169 |
| 014097 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:12pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592793.0 | 511375.5 | 20833 | 1.64041666667 | 14097 |
| 015085 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:13pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592790.8 | 511373.5 | 20835 | 1.64041666667 | 15085 |
| 014755 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:14pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592788.8 | 511372.0 | 20837 | 1.64041666667 | 14755 |
| 014989 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:15pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592786.7 | 511369.9 | 20839 | 1.64041666667 | 14989 |
| 014656 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:16pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592784.7 | 511368.6 | 20841 | 1.64041666667 | 14656 |
| 013502 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:17pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592782.0 | 511367.2 | 20843 | 1.64041666667 | 13502 |
| 013422 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:18pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592779.9 | 511365.8 | 20845 | 1.64041666667 | 13422 |
| 013730 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:19pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592777.8 | 511364.6 | 20847 | 1.64041666667 | 13730 |
| 013783 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:20pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592776.0 | 511364.0 | 20849 | 1.64041666667 | 13783 |
| 014233 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:21pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592773.1 | 511363.9 | 20851 | 1.64041666667 | 14233 |
| 014283 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:22pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592771.1 | 511364.5 | 20853 | 1.64041666667 | 14283 |
| 014139 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:23pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592768.5 | 511365.0 | 20855 | 1.64041666667 | 14139 |
| 014186 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:24pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592766.0 | 511364.7 | 20857 | 1.64041666667 | 14186 |
| 013544 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592763.4 | 511364.1 | 20859 | 1.64041666667 | 13544 |
| 013746 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:26pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592761.1 | 511363.7 | 20861 | 1.64041666667 | 13746 |
| 013890 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:27pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592758.3 | 511362.9 | 20863 | 1.64041666667 | 13890 |
| 014450 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:28pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592756.3 | 511362.5 | 20865 | 1.64041666667 | 14450 |
| 013685 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:29pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592753.8 | 511362.0 | 20867 | 1.64041666667 | 13685 |
| 013323 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:30pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592751.7 | 511362.4 | 20869 | 1.64041666667 | 13323 |
| 013337 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:31pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592749.7 | 511364.6 | 20871 | 1.64041666667 | 13337 |
| 013644 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:32pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592748.5 | 511366.7 | 20873 | 1.64041666667 | 13644 |
| 012962 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:33pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592748.3 | 511368.8 | 20875 | 1.64041666667 | 12962 |
| 012001 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592748.6 | 511371.0 | 20877 | 1.64041666667 | 12001 |
| 013208 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592749.6 | 511373.3 | 20879 | 1.64041666667 | 13208 |
| 013564 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592751.3 | 511374.6 | 20881 | 1.64041666667 | 13564 |
| 012925 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:37pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592753.6 | 511376.3 | 20883 | 1.64041666667 | 12925 |
| 013015 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:38pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592755.7 | 511377.7 | 20885 | 1.64041666667 | 13015 |
| 013178 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:39pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592758.0 | 511378.9 | 20887 | 1.64041666667 | 13178 |
| 013465 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:40pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592760.0 | 511380.4 | 20889 | 1.64041666667 | 13465 |
| 013634 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:41pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592762.5 | 511381.9 | 20891 | 1.64041666667 | 13634 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:42pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592764.9 | 511382.5 | 20893 | 1.64041666667 | 14314 |
| 014576 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592768.0 | 511383.4 | 20895 | 1.64041666667 | 14576 |
| 014574 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592770.2 | 511383.8 | 20897 | 1.64041666667 | 14574 |
| 014063 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592773.0 | 511384.2 | 20899 | 1.64041666667 | 14063 |
| 013685 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592775.4 | 511385.2 | 20901 | 1.64041666667 | 13685 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013398 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592778.0 | 511386.0 | 20903 | 1.64041666667 | 13398 |
| 013626 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592780.0 | 511386.9 | 20905 | 1.64041666667 | 13626 |
| 013830 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592782.7 | 511388.6 | 20907 | 1.64041666667 | 13830 |
| 013359 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592784.6 | 511389.4 | 20909 | 1.64041666667 | 13359 |
| 014174 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592786.9 | 511391.0 | 20911 | 1.64041666667 | 14174 |
| 013823 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592788.7 | 511392.2 | 20913 | 1.64041666667 | 13823 |
| 013978 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592791.3 | 511393.7 | 20915 | 1.64041666667 | 13978 |
| 013952 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592792.9 | 511395.4 | 20917 | 1.64041666667 | 13952 |
| 014163 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592794.8 | 511397.4 | 20919 | 1.64041666667 | 14163 |
| 013254 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592796.6 | 511398.9 | 20921 | 1.64041666667 | 13254 |
| 013943 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592798.8 | 511401.0 | 20923 | 1.64041666667 | 13943 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592800.6 | 511402.4 | 20925 | 1.64041666667 | 14458 |
| 014162 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592802.4 | 511404.0 | 20927 | 1.64041666667 | 14162 |
| 013794 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592804.0 | 511405.8 | 20929 | 1.64041666667 | 13794 |
| 013091 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592806.4 | 511407.4 | 20931 | 1.64041666667 | 13091 |
| 013581 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:02pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592808.5 | 511409.0 | 20933 | 1.64041666667 | 13581 |
| 013317 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592811.0 | 511410.8 | 20935 | 1.64041666667 | 13317 |
| 013513 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592813.4 | 511412.0 | 20937 | 1.64041666667 | 13513 |
| 014066 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592815.7 | 511413.4 | 20939 | 1.64041666667 | 14066 |
| 014850 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592817.8 | 511415.0 | 20941 | 1.64041666667 | 14850 |
| 014435 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592820.3 | 511416.4 | 20943 | 1.64041666667 | 14435 |
| 013992 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592822.4 | 511417.8 | 20945 | 1.64041666667 | 13992 |
| 013660 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592824.8 | 511419.4 | 20947 | 1.64041666667 | 13660 |
| 013774 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592827.2 | 511420.4 | 20949 | 1.64041666667 | 13774 |
| 013072 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592829.7 | 511421.4 | 20951 | 1.64041666667 | 13072 |
| 013556 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592832.4 | 511421.8 | 20953 | 1.64041666667 | 13556 |
| 013437 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592835.3 | 511421.4 | 20955 | 1.64041666667 | 13437 |
| 013153 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592837.8 | 511421.2 | 20957 | 1.64041666667 | 13153 |
| 014209 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592840.8 | 511421.0 | 20959 | 1.64041666667 | 14209 |
| 013647 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592843.2 | 511420.5 | 20961 | 1.64041666667 | 13647 |
| 013549 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592845.9 | 511420.7 | 20963 | 1.64041666667 | 13549 |
| 013351 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592847.9 | 511421.0 | 20965 | 1.64041666667 | 13351 |
| 012767 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592850.6 | 511421.3 | 20967 | 1.64041666667 | 12767 |
| 012461 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592852.4 | 511422.0 | 20969 | 1.64041666667 | 12461 |
| 012259 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592854.9 | 511422.8 | 20971 | 1.64041666667 | 12259 |
| 014103 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592857.0 | 511423.7 | 20973 | 1.64041666667 | 14103 |
| 013498 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592858.7 | 511425.2 | 20975 | 1.64041666667 | 13498 |
| 013563 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592859.7 | 511426.8 | 20977 | 1.64041666667 | 13563 |
| 013591 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592859.7 | 511429.1 | 20979 | 1.64041666667 | 13591 |
| 014273 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592859.3 | 511431.3 | 20981 | 1.64041666667 | 14273 |
| 013362 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592859.1 | 511433.7 | 20983 | 1.64041666667 | 13362 |
| 012976 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592858.5 | 511436.1 | 20985 | 1.64041666667 | 12976 |
| 012646 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592857.8 | 511438.6 | 20987 | 1.64041666667 | 12646 |
| 012431 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592857.3 | 511440.0 | 20989 | 1.64041666667 | 12431 |
| 012677 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592855.9 | 511440.0 | 20991 | 1.64041666667 | 12677 |
| 013378 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592854.1 | 511439.0 | 20993 | 1.64041666667 | 13378 |
| 013240 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592851.9 | 511437.7 | 20995 | 1.64041666667 | 13240 |
| 012997 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592850.1 | 511436.2 | 20997 | 1.64041666667 | 12997 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012951 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592848.1 | 511434.5 | 20999 | 1.64041666667 | 12951 |
| 012002 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592846.5 | 511433.2 | 21001 | 1.64041666667 | 12002 |
| 012234 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592844.5 | 511431.1 | 21003 | 1.64041666667 | 12234 |
| 012244 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592843.1 | 511430.0 | 21005 | 1.64041666667 | 12244 |
| 012857 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:39pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592842.4 | 511429.8 | 21007 | 1.64041666667 | 12857 |
| 013022 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592842.6 | 511429.9 | 21009 | 1.64041666667 | 13022 |
| 012590 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592841.5 | 511429.3 | 21011 | 1.64041666667 | 12590 |
| 011904 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592839.7 | 511428.5 | 21013 | 1.64041666667 | 11904 |
| 012268 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592837.6 | 511426.8 | 21015 | 1.64041666667 | 12268 |
| 011851 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592836.3 | 511425.4 | 21017 | 1.64041666667 | 11851 |
| 012846 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592834.3 | 511423.8 | 21019 | 1.64041666667 | 12846 |
| 013158 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592832.5 | 511422.6 | 21021 | 1.64041666667 | 13158 |
| 014294 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592830.1 | 511422.2 | 21023 | 1.64041666667 | 14294 |
| 014730 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592827.8 | 511422.2 | 21025 | 1.64041666667 | 14730 |
| 013813 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592825.0 | 511422.0 | 21027 | 1.64041666667 | 13813 |
| 013425 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592822.8 | 511422.1 | 21029 | 1.64041666667 | 13425 |
| 014181 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592820.8 | 511421.6 | 21031 | 1.64041666667 | 14181 |
| 013414 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592819.1 | 511421.3 | 21033 | 1.64041666667 | 13414 |
| 013350 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592816.6 | 511420.7 | 21035 | 1.64041666667 | 13350 |
| 013644 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592814.4 | 511419.9 | 21037 | 1.64041666667 | 13644 |
| 013420 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592811.8 | 511419.4 | 21039 | 1.64041666667 | 13420 |
| 013571 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592810.1 | 511418.4 | 21041 | 1.64041666667 | 13571 |
| 013289 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592808.1 | 511416.2 | 21043 | 1.64041666667 | 13289 |
| 012815 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:58pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592806.5 | 511414.7 | 21045 | 1.64041666667 | 12815 |
| 013493 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592804.6 | 511412.8 | 21047 | 1.64041666667 | 13493 |
| 013102 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592802.6 | 511410.9 | 21049 | 1.64041666667 | 13102 |
| 012642 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592800.6 | 511409.1 | 21051 | 1.64041666667 | 12642 |
| 013029 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:02pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592799.2 | 511407.1 | 21053 | 1.64041666667 | 13029 |
| 012938 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592797.1 | 511405.4 | 21055 | 1.64041666667 | 12938 |
| 012955 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:04pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592794.8 | 511404.5 | 21057 | 1.64041666667 | 12955 |
| 013272 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592792.0 | 511403.4 | 21059 | 1.64041666667 | 13272 |
| 013510 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592790.0 | 511403.1 | 21061 | 1.64041666667 | 13510 |
| 013502 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:07pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592787.4 | 511402.7 | 21063 | 1.64041666667 | 13502 |
| 013790 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592785.0 | 511401.8 | 21065 | 1.64041666667 | 13790 |
| 013651 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:09pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592782.3 | 511401.3 | 21067 | 1.64041666667 | 13651 |
| 013754 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:10pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592780.2 | 511400.8 | 21069 | 1.64041666667 | 13754 |
| 013646 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:11pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592777.3 | 511399.6 | 21071 | 1.64041666667 | 13646 |
| 014126 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:12pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592775.2 | 511399.0 | 21073 | 1.64041666667 | 14126 |
| 013488 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:13pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592772.9 | 511397.6 | 21075 | 1.64041666667 | 13488 |
| 013557 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:14pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592771.0 | 511395.7 | 21077 | 1.64041666667 | 13557 |
| 013258 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:15pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592768.8 | 511393.7 | 21079 | 1.64041666667 | 13258 |
| 013713 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:16pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592767.3 | 511392.1 | 21081 | 1.64041666667 | 13713 |
| 013773 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:17pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592765.5 | 511389.8 | 21083 | 1.64041666667 | 13773 |
| 013417 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:18pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592763.7 | 511387.9 | 21085 | 1.64041666667 | 13417 |
| 013562 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:19pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592761.8 | 511385.7 | 21087 | 1.64041666667 | 13562 |
| 014071 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:20pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592760.1 | 511383.9 | 21089 | 1.64041666667 | 14071 |
| 013030 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:21pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592757.4 | 511382.3 | 21091 | 1.64041666667 | 13030 |
| 012849 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:22pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592755.4 | 511381.3 | 21093 | 1.64041666667 | 12849 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:23pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592752.7 | 511380.1 | 21095 | 1.64041666667 | 13295 |
| 012983 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:24pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592750.1 | 511379.9 | 21097 | 1.64041666667 | 12983 |
| 012665 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592747.5 | 511380.3 | 21099 | 1.64041666667 | 12665 |
| 012869 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:26pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592745.6 | 511381.3 | 21101 | 1.64041666667 | 12869 |
| 013509 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592744.0 | 511383.5 | 21103 | 1.64041666667 | 13509 |
| 013246 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592743.2 | 511385.5 | 21105 | 1.64041666667 | 13246 |
| 013106 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592743.3 | 511388.2 | 21107 | 1.64041666667 | 13106 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592743.6 | 511390.3 | 21109 | 1.64041666667 | 13132 |
| 013619 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592744.3 | 511392.7 | 21111 | 1.64041666667 | 13619 |
| 013038 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592745.9 | 511394.6 | 21113 | 1.64041666667 | 13038 |
| 013784 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592747.5 | 511396.8 | 21115 | 1.64041666667 | 13784 |
| 014008 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592748.1 | 511398.3 | 21117 | 1.64041666667 | 14008 |
| 014652 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592748.5 | 511399.7 | 21119 | 1.64041666667 | 14652 |
| 013867 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592748.5 | 511399.9 | 21121 | 1.64041666667 | 13867 |
| 014760 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592749.1 | 511399.2 | 21123 | 1.64041666667 | 14760 |
| 014595 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592750.0 | 511399.5 | 21125 | 1.64041666667 | 14595 |
| 014622 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592751.4 | 511399.9 | 21127 | 1.64041666667 | 14622 |
| 013865 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592752.7 | 511400.8 | 21129 | 1.64041666667 | 13865 |
| 013431 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592754.9 | 511401.7 | 21131 | 1.64041666667 | 13431 |
| 012835 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592757.0 | 511402.2 | 21133 | 1.64041666667 | 12835 |
| 014172 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592759.6 | 511403.6 | 21135 | 1.64041666667 | 14172 |
| 014249 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592762.0 | 511404.0 | 21137 | 1.64041666667 | 14249 |
| 014022 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592764.8 | 511404.2 | 21139 | 1.64041666667 | 14022 |
| 014705 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592767.4 | 511404.8 | 21141 | 1.64041666667 | 14705 |
| 015149 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592770.5 | 511404.9 | 21143 | 1.64041666667 | 15149 |
| 014416 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592773.0 | 511405.4 | 21145 | 1.64041666667 | 14416 |
| 014761 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592775.8 | 511406.9 | 21147 | 1.64041666667 | 14761 |
| 014108 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592778.1 | 511407.9 | 21149 | 1.64041666667 | 14108 |
| 013733 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592780.6 | 511409.2 | 21151 | 1.64041666667 | 13733 |
| 014467 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592783.0 | 511411.0 | 21153 | 1.64041666667 | 14467 |
| 013575 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592785.4 | 511412.4 | 21155 | 1.64041666667 | 13575 |
| 013756 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592787.9 | 511413.7 | 21157 | 1.64041666667 | 13756 |
| 013707 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592790.1 | 511415.3 | 21159 | 1.64041666667 | 13707 |
| 013193 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592792.2 | 511416.4 | 21161 | 1.64041666667 | 13193 |
| 013323 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592794.6 | 511417.8 | 21163 | 1.64041666667 | 13323 |
| 014087 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:58pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592796.5 | 511419.4 | 21165 | 1.64041666667 | 14087 |
| 014329 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592799.1 | 511421.3 | 21167 | 1.64041666667 | 14329 |
| 013422 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592801.4 | 511422.6 | 21169 | 1.64041666667 | 13422 |
| 013190 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592803.7 | 511424.6 | 21171 | 1.64041666667 | 13190 |
| 013704 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592805.3 | 511426.0 | 21173 | 1.64041666667 | 13704 |
| 014286 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592807.7 | 511427.5 | 21175 | 1.64041666667 | 14286 |
| 013496 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592809.6 | 511429.4 | 21177 | 1.64041666667 | 13496 |
| 013486 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592811.6 | 511431.1 | 21179 | 1.64041666667 | 13486 |
| 013398 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592813.8 | 511432.5 | 21181 | 1.64041666667 | 13398 |
| 013064 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592816.4 | 511434.6 | 21183 | 1.64041666667 | 13064 |
| 011878 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592818.3 | 511436.1 | 21185 | 1.64041666667 | 11878 |
| 011819 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592820.7 | 511437.6 | 21187 | 1.64041666667 | 11819 |
| 012671 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592822.6 | 511439.1 | 21189 | 1.64041666667 | 12671 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012137 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:11pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592824.7 | 511441.2 | 21191 | 1.64041666667 | 12137 |
| 011964 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:12pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592826.6 | 511442.6 | 21193 | 1.64041666667 | 11964 |
| 012422 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:13pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592829.0 | 511444.1 | 21195 | 1.64041666667 | 12422 |
| 012410 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:14pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592831.2 | 511445.5 | 21197 | 1.64041666667 | 12410 |
| 012823 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:15pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592833.6 | 511446.4 | 21199 | 1.64041666667 | 12823 |
| 011750 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:16pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592836.0 | 511447.1 | 21201 | 1.64041666667 | 11750 |
| 011942 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:17pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592838.7 | 511448.5 | 21203 | 1.64041666667 | 11942 |
| 011720 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:18pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592841.0 | 511449.3 | 21205 | 1.64041666667 | 11720 |
| 011670 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:19pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592843.6 | 511449.8 | 21207 | 1.64041666667 | 11670 |
| 012489 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:20pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592845.6 | 511450.9 | 21209 | 1.64041666667 | 12489 |
| 011892 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:21pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592847.3 | 511452.1 | 21211 | 1.64041666667 | 11892 |
| 012607 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:22pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592848.1 | 511453.4 | 21213 | 1.64041666667 | 12607 |
| 013286 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:23pm | Sensor | 1797-S0025-905-G-ACK | 6809.6 | 1592847.2 | 511455.4 | 21215 | 1.64041666667 | 13286 |
| 012888 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:24pm | Sensor | 1797-S0025-905-G-ACK | 6809.6 | 1592845.8 | 511457.1 | 21217 | 1.64041666667 | 12888 |
| 011187 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:25pm | Sensor | 1797-S0025-905-G-ACK | 6809.7 | 1592844.0 | 511459.4 | 21219 | 1.64041666667 | 11187 |
| 011010 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:26pm | Sensor | 1797-S0025-905-G-ACK | 6809.7 | 1592842.2 | 511460.9 | 21221 | 1.64041666667 | 11010 |
| 010813 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:27pm | Sensor | 1797-S0025-905-G-ACK | 6809.6 | 1592840.2 | 511462.3 | 21223 | 1.64041666667 | 10813 |
| 010890 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:28pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592838.5 | 511462.8 | 21225 | 1.64041666667 | 10890 |
| 010430 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:29pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592836.5 | 511462.0 | 21227 | 1.64041666667 | 10430 |
| 010337 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:30pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592834.9 | 511461.1 | 21229 | 1.64041666667 | 10337 |
| 011319 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:31pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592832.7 | 511459.8 | 21231 | 1.64041666667 | 11319 |
| 011310 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:32pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592830.8 | 511458.2 | 21233 | 1.64041666667 | 11310 |
| 011499 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:33pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592828.6 | 511456.3 | 21235 | 1.64041666667 | 11499 |
| 011388 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:34pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592826.5 | 511455.0 | 21237 | 1.64041666667 | 11388 |
| 010920 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:35pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592824.2 | 511453.2 | 21239 | 1.64041666667 | 10920 |
| 011213 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:36pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592822.4 | 511451.5 | 21241 | 1.64041666667 | 11213 |
| 012247 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:37pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592819.7 | 511449.5 | 21243 | 1.64041666667 | 12247 |
| 011209 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:38pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592817.8 | 511447.9 | 21245 | 1.64041666667 | 11209 |
| 011210 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:39pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592815.6 | 511445.4 | 21247 | 1.64041666667 | 11210 |
| 011533 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:40pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592813.6 | 511443.6 | 21249 | 1.64041666667 | 11533 |
| 011992 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592811.4 | 511441.7 | 21251 | 1.64041666667 | 11992 |
| 011928 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592809.7 | 511439.5 | 21253 | 1.64041666667 | 11928 |
| 012237 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592807.8 | 511437.4 | 21255 | 1.64041666667 | 12237 |
| 011916 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592806.2 | 511435.4 | 21257 | 1.64041666667 | 11916 |
| 012207 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592804.8 | 511432.5 | 21259 | 1.64041666667 | 12207 |
| 013151 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592803.3 | 511430.5 | 21261 | 1.64041666667 | 13151 |
| 012835 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592800.9 | 511428.7 | 21263 | 1.64041666667 | 12835 |
| 013902 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592799.1 | 511427.1 | 21265 | 1.64041666667 | 13902 |
| 012950 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592796.6 | 511425.6 | 21267 | 1.64041666667 | 12950 |
| 013509 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592794.3 | 511424.7 | 21269 | 1.64041666667 | 13509 |
| 013336 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592791.9 | 511423.5 | 21271 | 1.64041666667 | 13336 |
| 013599 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592789.4 | 511422.3 | 21273 | 1.64041666667 | 13599 |
| 013537 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592786.7 | 511421.9 | 21275 | 1.64041666667 | 13537 |
| 013614 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592784.6 | 511421.0 | 21277 | 1.64041666667 | 13614 |
| 013553 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592782.5 | 511420.0 | 21279 | 1.64041666667 | 13553 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592780.0 | 511419.3 | 21281 | 1.64041666667 | 13766 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592777.2 | 511418.4 | 21283 | 1.64041666667 | 13736 |
| 013509 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592774.6 | 511417.9 | 21285 | 1.64041666667 | 13509 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013081 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592771.8 | 511418.0 | 21287 | 1.64041666667 | 13081 |
| 012773 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592769.3 | 511417.8 | 21289 | 1.64041666667 | 12773 |
| 014325 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592766.7 | 511417.5 | 21291 | 1.64041666667 | 14325 |
| 014207 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592764.1 | 511417.3 | 21293 | 1.64041666667 | 14207 |
| 013751 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592761.0 | 511416.2 | 21295 | 1.64041666667 | 13751 |
| 013758 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592758.9 | 511415.5 | 21297 | 1.64041666667 | 13758 |
| 013469 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592756.4 | 511414.5 | 21299 | 1.64041666667 | 13469 |
| 013021 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592754.3 | 511413.0 | 21301 | 1.64041666667 | 13021 |
| 012619 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592752.2 | 511411.7 | 21303 | 1.64041666667 | 12619 |
| 013421 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592750.6 | 511410.6 | 21305 | 1.64041666667 | 13421 |
| 013114 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592748.6 | 511409.7 | 21307 | 1.64041666667 | 13114 |
| 013316 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592747.2 | 511409.1 | 21309 | 1.64041666667 | 13316 |
| 014360 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592745.4 | 511408.4 | 21311 | 1.64041666667 | 14360 |
| 013117 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592743.5 | 511408.3 | 21313 | 1.64041666667 | 13117 |
| 012898 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592741.0 | 511408.0 | 21315 | 1.64041666667 | 12898 |
| 012948 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592739.5 | 511408.6 | 21317 | 1.64041666667 | 12948 |
| 012998 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592738.0 | 511410.4 | 21319 | 1.64041666667 | 12998 |
| 012681 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592737.3 | 511412.3 | 21321 | 1.64041666667 | 12681 |
| 013253 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592736.6 | 511414.5 | 21323 | 1.64041666667 | 13253 |
| 013507 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592735.9 | 511416.7 | 21325 | 1.64041666667 | 13507 |
| 013815 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592735.9 | 511419.2 | 21327 | 1.64041666667 | 13815 |
| 013931 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592736.3 | 511421.2 | 21329 | 1.64041666667 | 13931 |
| 013626 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592737.9 | 511423.1 | 21331 | 1.64041666667 | 13626 |
| 013245 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592740.1 | 511424.0 | 21333 | 1.64041666667 | 13245 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592742.7 | 511425.0 | 21335 | 1.64041666667 | 13278 |
| 014391 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592744.8 | 511425.3 | 21337 | 1.64041666667 | 14391 |
| 013720 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592747.7 | 511425.3 | 21339 | 1.64041666667 | 13720 |
| 013380 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592750.4 | 511424.9 | 21341 | 1.64041666667 | 13380 |
| 013488 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592753.1 | 511424.1 | 21343 | 1.64041666667 | 13488 |
| 013992 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592755.5 | 511424.0 | 21345 | 1.64041666667 | 13992 |
| 013705 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592758.4 | 511424.6 | 21347 | 1.64041666667 | 13705 |
| 013582 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592761.0 | 511425.2 | 21349 | 1.64041666667 | 13582 |
| 012574 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592763.5 | 511426.5 | 21351 | 1.64041666667 | 12574 |
| 012191 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592765.4 | 511428.4 | 21353 | 1.64041666667 | 12191 |
| 013260 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592767.8 | 511430.1 | 21355 | 1.64041666667 | 13260 |
| 013833 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592770.1 | 511431.7 | 21357 | 1.64041666667 | 13833 |
| 013894 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592772.2 | 511433.7 | 21359 | 1.64041666667 | 13894 |
| 013417 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592774.3 | 511435.0 | 21361 | 1.64041666667 | 13417 |
| 013247 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592777.1 | 511436.3 | 21363 | 1.64041666667 | 13247 |
| 013309 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592779.1 | 511437.9 | 21365 | 1.64041666667 | 13309 |
| 013629 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592781.5 | 511439.7 | 21367 | 1.64041666667 | 13629 |
| 013073 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592783.8 | 511440.9 | 21369 | 1.64041666667 | 13073 |
| 012656 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592786.1 | 511442.9 | 21371 | 1.64041666667 | 12656 |
| 013284 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592787.8 | 511444.5 | 21373 | 1.64041666667 | 13284 |
| 013022 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592790.3 | 511446.2 | 21375 | 1.64041666667 | 13022 |
| 012522 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592792.4 | 511447.9 | 21377 | 1.64041666667 | 12522 |
| 012129 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592794.6 | 511449.9 | 21379 | 1.64041666667 | 12129 |
| 012477 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592796.8 | 511451.1 | 21381 | 1.64041666667 | 12477 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012088 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592799.4 | 511452.7 | 21383 | 1.64041666667 | 12088 |
| 012589 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592801.3 | 511454.1 | 21385 | 1.64041666667 | 12589 |
| 012301 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:49pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592803.7 | 511455.6 | 21387 | 1.64041666667 | 12301 |
| 012657 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:50pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592805.7 | 511456.4 | 21389 | 1.64041666667 | 12657 |
| 012564 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:51pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592808.1 | 511456.8 | 21391 | 1.64041666667 | 12564 |
| 012767 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:52pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592809.7 | 511456.2 | 21393 | 1.64041666667 | 12767 |
| 012784 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:53pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592810.7 | 511454.1 | 21395 | 1.64041666667 | 12784 |
| 012636 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:54pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592811.4 | 511452.2 | 21397 | 1.64041666667 | 12636 |
| 012717 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:55pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592811.9 | 511449.9 | 21399 | 1.64041666667 | 12717 |
| 011863 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:56pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592812.6 | 511448.4 | 21401 | 1.64041666667 | 11863 |
| 011653 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:57pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592813.7 | 511446.8 | 21403 | 1.64041666667 | 11653 |
| 011250 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:58pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592814.1 | 511445.4 | 21405 | 1.64041666667 | 11250 |
| 010910 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:59pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592813.7 | 511445.2 | 21407 | 1.64041666667 | 10910 |
| 011447 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592813.7 | 511445.4 | 21409 | 1.64041666667 | 11447 |
| 011891 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592813.8 | 511444.3 | 21411 | 1.64041666667 | 11891 |
| 012029 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592814.0 | 511442.6 | 21413 | 1.64041666667 | 12029 |
| 012038 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592815.3 | 511440.2 | 21415 | 1.64041666667 | 12038 |
| 012682 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:04pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592816.0 | 511438.1 | 21417 | 1.64041666667 | 12682 |
| 012931 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592817.1 | 511435.6 | 21419 | 1.64041666667 | 12931 |
| 013251 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592818.5 | 511433.7 | 21421 | 1.64041666667 | 13251 |
| 013146 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592820.1 | 511431.1 | 21423 | 1.64041666667 | 13146 |
| 012892 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592821.1 | 511429.1 | 21425 | 1.64041666667 | 12892 |
| 012472 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592823.1 | 511426.7 | 21427 | 1.64041666667 | 12472 |
| 013165 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592824.0 | 511424.7 | 21429 | 1.64041666667 | 13165 |
| 012865 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592824.5 | 511421.5 | 21431 | 1.64041666667 | 12865 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592825.4 | 511419.4 | 21433 | 1.64041666667 | 13132 |
| 013499 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592826.7 | 511416.8 | 21435 | 1.64041666667 | 13499 |
| 013870 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592827.4 | 511414.7 | 21437 | 1.64041666667 | 13870 |
| 014754 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592828.9 | 511411.7 | 21439 | 1.64041666667 | 14754 |
| 014997 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592829.8 | 511409.6 | 21441 | 1.64041666667 | 14997 |
| 014128 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592830.8 | 511406.5 | 21443 | 1.64041666667 | 14128 |
| 014502 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592831.9 | 511404.2 | 21445 | 1.64041666667 | 14502 |
| 014787 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592833.0 | 511401.6 | 21447 | 1.64041666667 | 14787 |
| 014730 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592833.7 | 511399.3 | 21449 | 1.64041666667 | 14730 |
| 013933 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592835.1 | 511396.6 | 21451 | 1.64041666667 | 13933 |
| 013882 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592836.0 | 511394.5 | 21453 | 1.64041666667 | 13882 |
| 014791 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592837.0 | 511391.4 | 21455 | 1.64041666667 | 14791 |
| 014492 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592837.9 | 511389.1 | 21457 | 1.64041666667 | 14492 |
| 014279 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592838.7 | 511386.4 | 21459 | 1.64041666667 | 14279 |
| 014670 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592838.8 | 511383.9 | 21461 | 1.64041666667 | 14670 |
| 014431 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592839.3 | 511381.3 | 21463 | 1.64041666667 | 14431 |
| 014245 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592839.9 | 511378.8 | 21465 | 1.64041666667 | 14245 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592840.2 | 511375.9 | 21467 | 1.64041666667 | 13915 |
| 014030 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592840.8 | 511373.5 | 21469 | 1.64041666667 | 14030 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592841.7 | 511370.5 | 21471 | 1.64041666667 | 14626 |
| 014527 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592842.1 | 511368.3 | 21473 | 1.64041666667 | 14527 |
| 015454 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592843.1 | 511365.7 | 21475 | 1.64041666667 | 15454 |
| 015548 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592844.2 | 511363.4 | 21477 | 1.64041666667 | 15548 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015533 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592844.8 | 511360.7 | 21479 | 1.64041666667 | 15533 |
| 014737 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592845.5 | 511358.7 | 21481 | 1.64041666667 | 14737 |
| 014589 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592846.4 | 511356.4 | 21483 | 1.64041666667 | 14589 |
| 015016 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592847.0 | 511354.1 | 21485 | 1.64041666667 | 15016 |
| 014851 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592848.2 | 511352.2 | 21487 | 1.64041666667 | 14851 |
| 014091 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592849.5 | 511351.0 | 21489 | 1.64041666667 | 14091 |
| 014691 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592851.6 | 511350.5 | 21491 | 1.64041666667 | 14691 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592853.5 | 511351.1 | 21493 | 1.64041666667 | 14324 |
| 013509 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592855.4 | 511352.1 | 21495 | 1.64041666667 | 13509 |
| 014229 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592856.7 | 511353.7 | 21497 | 1.64041666667 | 14229 |
| 014296 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592857.9 | 511355.8 | 21499 | 1.64041666667 | 14296 |
| 013554 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592858.6 | 511357.5 | 21501 | 1.64041666667 | 13554 |
| 013939 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592857.8 | 511359.7 | 21503 | 1.64041666667 | 13939 |
| 013825 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592856.7 | 511361.5 | 21505 | 1.64041666667 | 13825 |
| 013634 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592855.2 | 511363.6 | 21507 | 1.64041666667 | 13634 |
| 013706 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592853.2 | 511365.5 | 21509 | 1.64041666667 | 13706 |
| 013312 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592851.9 | 511368.0 | 21511 | 1.64041666667 | 13312 |
| 013796 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592851.1 | 511370.0 | 21513 | 1.64041666667 | 13796 |
| 014120 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592849.2 | 511372.9 | 21515 | 1.64041666667 | 14120 |
| 014715 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592848.8 | 511375.2 | 21517 | 1.64041666667 | 14715 |
| 014569 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592848.7 | 511377.8 | 21519 | 1.64041666667 | 14569 |
| 014263 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592848.3 | 511380.4 | 21521 | 1.64041666667 | 14263 |
| 015605 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592848.5 | 511383.3 | 21523 | 1.64041666667 | 15605 |
| 015303 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:58pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592848.7 | 511385.7 | 21525 | 1.64041666667 | 15303 |
| 014780 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592848.6 | 511388.8 | 21527 | 1.64041666667 | 14780 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592849.0 | 511390.9 | 21529 | 1.64041666667 | 14081 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592849.4 | 511393.6 | 21531 | 1.64041666667 | 14655 |
| 015061 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592849.2 | 511396.2 | 21533 | 1.64041666667 | 15061 |
| 015949 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592848.7 | 511399.1 | 21535 | 1.64041666667 | 15949 |
| 014859 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592847.8 | 511401.3 | 21537 | 1.64041666667 | 14859 |
| 013750 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592846.5 | 511404.0 | 21539 | 1.64041666667 | 13750 |
| 014319 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592845.7 | 511406.2 | 21541 | 1.64041666667 | 14319 |
| 014025 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592844.3 | 511408.9 | 21543 | 1.64041666667 | 14025 |
| 014369 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592842.8 | 511410.8 | 21545 | 1.64041666667 | 14369 |
| 014232 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592841.4 | 511413.1 | 21547 | 1.64041666667 | 14232 |
| 014080 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592839.8 | 511415.3 | 21549 | 1.64041666667 | 14080 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592837.7 | 511417.6 | 21551 | 1.64041666667 | 14482 |
| 015054 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592836.3 | 511419.7 | 21553 | 1.64041666667 | 15054 |
| 014040 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592834.7 | 511421.9 | 21555 | 1.64041666667 | 14040 |
| 013995 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592833.1 | 511423.6 | 21557 | 1.64041666667 | 13995 |
| 012642 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:15pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592831.8 | 511425.3 | 21559 | 1.64041666667 | 12642 |
| 012856 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592830.0 | 511427.1 | 21561 | 1.64041666667 | 12856 |
| 012609 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592827.5 | 511429.2 | 21563 | 1.64041666667 | 12609 |
| 012852 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592825.9 | 511431.3 | 21565 | 1.64041666667 | 12852 |
| 012757 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:19pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592824.2 | 511433.9 | 21567 | 1.64041666667 | 12757 |
| 012238 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:20pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592822.7 | 511436.1 | 21569 | 1.64041666667 | 12238 |
| 012494 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.9 | 1592821.3 | 511439.2 | 21571 | 1.64041666667 | 12494 |
| 013282 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:22pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592821.0 | 511441.7 | 21573 | 1.64041666667 | 13282 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012714 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:23pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592820.1 | 511444.9 | 21575 | 1.64041666667 | 12714 |
| 012154 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:24pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592819.2 | 511446.9 | 21577 | 1.64041666667 | 12154 |
| 012034 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:25pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592818.3 | 511449.4 | 21579 | 1.64041666667 | 12034 |
| 011824 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:26pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592817.3 | 511451.9 | 21581 | 1.64041666667 | 11824 |
| 011616 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:27pm | Sensor | 1797-S0025-905-G-ACK | 6809.4 | 1592816.1 | 511454.6 | 21583 | 1.64041666667 | 11616 |
| 011626 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:28pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592815.9 | 511456.8 | 21585 | 1.64041666667 | 11626 |
| 011527 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:29pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592816.4 | 511459.4 | 21587 | 1.64041666667 | 11527 |
| 011801 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:30pm | Sensor | 1797-S0025-905-G-ACK | 6809.6 | 1592817.4 | 511461.4 | 21589 | 1.64041666667 | 11801 |
| 012030 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:31pm | Sensor | 1797-S0025-905-G-ACK | 6809.7 | 1592819.8 | 511463.0 | 21591 | 1.64041666667 | 12030 |
| 011672 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:32pm | Sensor | 1797-S0025-905-G-ACK | 6809.7 | 1592822.2 | 511463.6 | 21593 | 1.64041666667 | 11672 |
| 010765 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:33pm | Sensor | 1797-S0025-905-G-ACK | 6809.7 | 1592825.2 | 511464.3 | 21595 | 1.64041666667 | 10765 |
| 011770 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:34pm | Sensor | 1797-S0025-905-G-ACK | 6809.7 | 1592827.2 | 511463.8 | 21597 | 1.64041666667 | 11770 |
| 011856 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:35pm | Sensor | 1797-S0025-905-G-ACK | 6809.7 | 1592828.9 | 511461.5 | 21599 | 1.64041666667 | 11856 |
| 011491 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:36pm | Sensor | 1797-S0025-905-G-ACK | 6809.7 | 1592829.7 | 511459.2 | 21601 | 1.64041666667 | 11491 |
| 011954 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:37pm | Sensor | 1797-S0025-905-G-ACK | 6809.6 | 1592829.9 | 511456.4 | 21603 | 1.64041666667 | 11954 |
| 012821 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:38pm | Sensor | 1797-S0025-905-G-ACK | 6809.6 | 1592829.6 | 511454.4 | 21605 | 1.64041666667 | 12821 |
| 012582 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:39pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592829.9 | 511451.5 | 21607 | 1.64041666667 | 12582 |
| 012425 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:40pm | Sensor | 1797-S0025-905-G-ACK | 6809.5 | 1592830.1 | 511449.5 | 21609 | 1.64041666667 | 12425 |
| 012899 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:41pm | Sensor | 1797-S0025-905-G-ACK | 6809.4 | 1592830.4 | 511446.7 | 21611 | 1.64041666667 | 12899 |
| 012753 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:42pm | Sensor | 1797-S0025-905-G-ACK | 6809.4 | 1592831.3 | 511444.1 | 21613 | 1.64041666667 | 12753 |
| 012828 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:43pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592832.4 | 511441.5 | 21615 | 1.64041666667 | 12828 |
| 012901 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:44pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592833.0 | 511439.4 | 21617 | 1.64041666667 | 12901 |
| 013361 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:45pm | Sensor | 1797-S0025-905-G-ACK | 6809.3 | 1592834.3 | 511436.8 | 21619 | 1.64041666667 | 13361 |
| 013546 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:46pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592835.5 | 511435.0 | 21621 | 1.64041666667 | 13546 |
| 013582 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:47pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592836.8 | 511432.8 | 21623 | 1.64041666667 | 13582 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:48pm | Sensor | 1797-S0025-905-G-ACK | 6809.2 | 1592838.5 | 511431.3 | 21625 | 1.64041666667 | 13295 |
| 012203 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:49pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592840.5 | 511429.7 | 21627 | 1.64041666667 | 12203 |
| 011889 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:50pm | Sensor | 1797-S0025-905-G-ACK | 6809.1 | 1592842.2 | 511428.0 | 21629 | 1.64041666667 | 11889 |
| 012222 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:51pm | Sensor | 1797-S0025-905-G-ACK | 6809.0 | 1592844.1 | 511426.2 | 21631 | 1.64041666667 | 12222 |
| 012830 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592845.6 | 511424.0 | 21633 | 1.64041666667 | 12830 |
| 012992 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592846.7 | 511423.0 | 21635 | 1.64041666667 | 12992 |
| 012048 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592847.2 | 511423.0 | 21637 | 1.64041666667 | 12048 |
| 011734 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592847.2 | 511422.9 | 21639 | 1.64041666667 | 11734 |
| 012180 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592847.1 | 511422.9 | 21641 | 1.64041666667 | 12180 |
| 012956 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592847.2 | 511423.1 | 21643 | 1.64041666667 | 12956 |
| 012605 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:58pm | Sensor | 1797-S0025-905-G-ACK | 6805.8 | 1592847.2 | 511423.3 | 21645 | 1.64041666667 | 12605 |
| 012310 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:59pm | Sensor | 1797-S0025-905-G-ACK | 6804.1 | 1592847.1 | 511423.4 | 21647 | 1.64041666667 | 12310 |
| 012069 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:00pm | Sensor | 1797-S0025-905-G-ACK | 6804.9 | 1592847.1 | 511423.8 | 21649 | 1.64041666667 | 12069 |
| 012601 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592846.9 | 511423.3 | 21651 | 1.64041666667 | 12601 |
| 012473 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592847.3 | 511421.5 | 21653 | 1.64041666667 | 12473 |
| 013368 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592848.8 | 511419.3 | 21655 | 1.64041666667 | 13368 |
| 013205 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592849.7 | 511417.1 | 21657 | 1.64041666667 | 13205 |
| 013480 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592850.8 | 511414.2 | 21659 | 1.64041666667 | 13480 |
| 013672 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592852.5 | 511411.7 | 21661 | 1.64041666667 | 13672 |
| 013023 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592854.4 | 511409.3 | 21663 | 1.64041666667 | 13023 |
| 013367 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592855.5 | 511407.2 | 21665 | 1.64041666667 | 13367 |
| 014437 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592857.1 | 511404.9 | 21667 | 1.64041666667 | 14437 |
| 014945 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592858.8 | 511402.9 | 21669 | 1.64041666667 | 14945 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014804 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592860.1 | 511400.3 | 21671 | 1.64041666667 | 14804 |
| 014860 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592861.2 | 511398.2 | 21673 | 1.64041666667 | 14860 |
| 015093 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592862.5 | 511395.8 | 21675 | 1.64041666667 | 15093 |
| 014535 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592863.2 | 511393.5 | 21677 | 1.64041666667 | 14535 |
| 014363 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592864.4 | 511391.0 | 21679 | 1.64041666667 | 14363 |
| 014357 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592865.5 | 511388.8 | 21681 | 1.64041666667 | 14357 |
| 015223 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592866.2 | 511386.2 | 21683 | 1.64041666667 | 15223 |
| 014398 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592866.9 | 511384.4 | 21685 | 1.64041666667 | 14398 |
| 014804 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592868.4 | 511381.9 | 21687 | 1.64041666667 | 14804 |
| 014387 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592869.0 | 511380.0 | 21689 | 1.64041666667 | 14387 |
| 014002 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592869.8 | 511377.7 | 21691 | 1.64041666667 | 14002 |
| 014664 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592870.0 | 511375.6 | 21693 | 1.64041666667 | 14664 |
| 014181 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592869.0 | 511373.1 | 21695 | 1.64041666667 | 14181 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592868.0 | 511370.9 | 21697 | 1.64041666667 | 14314 |
| 015266 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592866.4 | 511368.6 | 21699 | 1.64041666667 | 15266 |
| 015202 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:26pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592864.8 | 511366.9 | 21701 | 1.64041666667 | 15202 |
| 013869 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592863.4 | 511364.7 | 21703 | 1.64041666667 | 13869 |
| 013943 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592861.9 | 511363.1 | 21705 | 1.64041666667 | 13943 |
| 013273 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:29pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592859.8 | 511361.7 | 21707 | 1.64041666667 | 13273 |
| 014043 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:30pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592857.7 | 511360.1 | 21709 | 1.64041666667 | 14043 |
| 014417 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592855.5 | 511358.9 | 21711 | 1.64041666667 | 14417 |
| 015047 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592853.7 | 511358.1 | 21713 | 1.64041666667 | 15047 |
| 015551 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:33pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592851.1 | 511356.7 | 21715 | 1.64041666667 | 15551 |
| 014657 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592848.8 | 511356.3 | 21717 | 1.64041666667 | 14657 |
| 014560 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592846.3 | 511356.1 | 21719 | 1.64041666667 | 14560 |
| 014520 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592844.0 | 511355.7 | 21721 | 1.64041666667 | 14520 |
| 014677 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:37pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592841.6 | 511355.9 | 21723 | 1.64041666667 | 14677 |
| 014781 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:38pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592840.0 | 511355.7 | 21725 | 1.64041666667 | 14781 |
| 014606 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:39pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592838.0 | 511354.4 | 21727 | 1.64041666667 | 14606 |
| 014921 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:40pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592836.1 | 511353.9 | 21729 | 1.64041666667 | 14921 |
| 014715 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:41pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592833.6 | 511354.6 | 21731 | 1.64041666667 | 14715 |
| 014375 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:42pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592832.2 | 511356.1 | 21733 | 1.64041666667 | 14375 |
| 015301 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592831.2 | 511358.5 | 21735 | 1.64041666667 | 15301 |
| 015139 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592830.1 | 511360.9 | 21737 | 1.64041666667 | 15139 |
| 015558 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592829.6 | 511363.5 | 21739 | 1.64041666667 | 15558 |
| 016109 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592829.4 | 511366.1 | 21741 | 1.64041666667 | 16109 |
| 014836 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592828.6 | 511368.6 | 21743 | 1.64041666667 | 14836 |
| 014555 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592827.9 | 511370.9 | 21745 | 1.64041666667 | 14555 |
| 014269 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592827.7 | 511373.9 | 21747 | 1.64041666667 | 14269 |
| 014829 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592827.0 | 511376.2 | 21749 | 1.64041666667 | 14829 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592826.4 | 511379.0 | 21751 | 1.64041666667 | 14626 |
| 013792 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592826.5 | 511381.7 | 21753 | 1.64041666667 | 13792 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592826.1 | 511384.7 | 21755 | 1.64041666667 | 13953 |
| 013496 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592825.8 | 511387.0 | 21757 | 1.64041666667 | 13496 |
| 014334 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592825.8 | 511390.0 | 21759 | 1.64041666667 | 14334 |
| 014040 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592825.4 | 511392.5 | 21761 | 1.64041666667 | 14040 |
| 013665 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592824.8 | 511395.3 | 21763 | 1.64041666667 | 13665 |
| 013514 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:58pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592824.0 | 511397.5 | 21765 | 1.64041666667 | 13514 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013789 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592822.0 | 511400.3 | 21767 | 1.64041666667 | 13789 |
| 014619 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592820.8 | 511402.3 | 21769 | 1.64041666667 | 14619 |
| 013825 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592820.1 | 511405.4 | 21771 | 1.64041666667 | 13825 |
| 014384 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592819.4 | 511407.6 | 21773 | 1.64041666667 | 14384 |
| 014143 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592817.9 | 511410.2 | 21775 | 1.64041666667 | 14143 |
| 014413 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592816.9 | 511412.6 | 21777 | 1.64041666667 | 14413 |
| 014715 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592815.6 | 511415.3 | 21779 | 1.64041666667 | 14715 |
| 014832 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592814.0 | 511417.7 | 21781 | 1.64041666667 | 14832 |
| 015010 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592812.7 | 511420.2 | 21783 | 1.64041666667 | 15010 |
| 014151 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592811.6 | 511422.5 | 21785 | 1.64041666667 | 14151 |
| 014822 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592810.1 | 511424.8 | 21787 | 1.64041666667 | 14822 |
| 014510 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592809.0 | 511426.9 | 21789 | 1.64041666667 | 14510 |
| 013697 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592807.9 | 511429.6 | 21791 | 1.64041666667 | 13697 |
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592806.6 | 511431.7 | 21793 | 1.64041666667 | 13277 |
| 012808 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592805.2 | 511434.1 | 21795 | 1.64041666667 | 12808 |
| 012867 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592804.2 | 511436.3 | 21797 | 1.64041666667 | 12867 |
| 012067 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592802.7 | 511438.8 | 21799 | 1.64041666667 | 12067 |
| 012495 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592801.4 | 511441.0 | 21801 | 1.64041666667 | 12495 |
| 013741 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592800.1 | 511443.1 | 21803 | 1.64041666667 | 13741 |
| 012229 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592798.5 | 511444.7 | 21805 | 1.64041666667 | 12229 |
| 012706 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592797.1 | 511446.2 | 21807 | 1.64041666667 | 12706 |
| 012607 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.8 | 1592795.8 | 511446.9 | 21809 | 1.64041666667 | 12607 |
| 013264 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1592794.2 | 511446.1 | 21811 | 1.64041666667 | 13264 |
| 012276 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592792.8 | 511444.9 | 21813 | 1.64041666667 | 12276 |
| 012927 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592790.9 | 511443.4 | 21815 | 1.64041666667 | 12927 |
| 012236 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592790.0 | 511442.0 | 21817 | 1.64041666667 | 12236 |
| 012740 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592789.6 | 511439.9 | 21819 | 1.64041666667 | 12740 |
| 013406 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592790.3 | 511438.3 | 21821 | 1.64041666667 | 13406 |
| 013106 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592792.4 | 511437.3 | 21823 | 1.64041666667 | 13106 |
| 013230 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592794.2 | 511436.5 | 21825 | 1.64041666667 | 13230 |
| 012721 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592796.4 | 511435.4 | 21827 | 1.64041666667 | 12721 |
| 012698 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592798.5 | 511434.5 | 21829 | 1.64041666667 | 12698 |
| 012760 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592800.7 | 511433.3 | 21831 | 1.64041666667 | 12760 |
| 012930 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592802.3 | 511431.7 | 21833 | 1.64041666667 | 12930 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592803.9 | 511429.6 | 21835 | 1.64041666667 | 12785 |
| 013034 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592804.6 | 511427.7 | 21837 | 1.64041666667 | 13034 |
| 012859 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592805.2 | 511425.4 | 21839 | 1.64041666667 | 12859 |
| 012603 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592806.1 | 511423.3 | 21841 | 1.64041666667 | 12603 |
| 014814 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592806.6 | 511421.1 | 21843 | 1.64041666667 | 14814 |
| 014318 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592807.8 | 511419.5 | 21845 | 1.64041666667 | 14318 |
| 014444 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592809.5 | 511417.7 | 21847 | 1.64041666667 | 14444 |
| 015512 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592810.6 | 511415.9 | 21849 | 1.64041666667 | 15512 |
| 014643 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592811.4 | 511413.4 | 21851 | 1.64041666667 | 14643 |
| 013831 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592811.2 | 511411.0 | 21853 | 1.64041666667 | 13831 |
| 013952 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592811.2 | 511408.7 | 21855 | 1.64041666667 | 13952 |
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592811.9 | 511406.6 | 21857 | 1.64041666667 | 13518 |
| 013611 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592812.5 | 511404.4 | 21859 | 1.64041666667 | 13611 |
| 014031 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592813.1 | 511402.5 | 21861 | 1.64041666667 | 14031 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014260 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592813.8 | 511400.0 | 21863 | 1.64041666667 | 14260 |
| 013286 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592813.6 | 511397.6 | 21865 | 1.64041666667 | 13286 |
| 015228 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592813.8 | 511394.8 | 21867 | 1.64041666667 | 15228 |
| 015473 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592813.8 | 511392.4 | 21869 | 1.64041666667 | 15473 |
| 013728 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592813.2 | 511389.6 | 21871 | 1.64041666667 | 13728 |
| 014097 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592813.1 | 511387.4 | 21873 | 1.64041666667 | 14097 |
| 013382 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592813.5 | 511385.1 | 21875 | 1.64041666667 | 13382 |
| 013857 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592814.0 | 511382.9 | 21877 | 1.64041666667 | 13857 |
| 014252 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592815.2 | 511380.6 | 21879 | 1.64041666667 | 14252 |
| 014504 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592816.2 | 511378.5 | 21881 | 1.64041666667 | 14504 |
| 014308 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592817.0 | 511376.0 | 21883 | 1.64041666667 | 14308 |
| 014116 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592818.2 | 511374.1 | 21885 | 1.64041666667 | 14116 |
| 014870 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592819.6 | 511371.7 | 21887 | 1.64041666667 | 14870 |
| 015309 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592820.6 | 511369.7 | 21889 | 1.64041666667 | 15309 |
| 014026 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:01pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592822.2 | 511367.3 | 21891 | 1.64041666667 | 14026 |
| 014917 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:02pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592823.1 | 511365.2 | 21893 | 1.64041666667 | 14917 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592823.9 | 511362.5 | 21895 | 1.64041666667 | 14458 |
| 015160 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:04pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592824.5 | 511360.3 | 21897 | 1.64041666667 | 15160 |
| 015045 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592824.0 | 511357.3 | 21899 | 1.64041666667 | 15045 |
| 015033 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592823.2 | 511355.1 | 21901 | 1.64041666667 | 15033 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:07pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592821.9 | 511352.8 | 21903 | 1.64041666667 | 13736 |
| 014739 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592820.1 | 511351.3 | 21905 | 1.64041666667 | 14739 |
| 014125 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:09pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592817.4 | 511350.0 | 21907 | 1.64041666667 | 14125 |
| 015243 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:10pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592815.1 | 511349.8 | 21909 | 1.64041666667 | 15243 |
| 014791 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:11pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592812.5 | 511350.4 | 21911 | 1.64041666667 | 14791 |
| 014463 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:12pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592809.9 | 511351.1 | 21913 | 1.64041666667 | 14463 |
| 015740 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:13pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592807.4 | 511352.6 | 21915 | 1.64041666667 | 15740 |
| 016203 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:14pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592805.9 | 511354.6 | 21917 | 1.64041666667 | 16203 |
| 015557 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:15pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592804.4 | 511357.2 | 21919 | 1.64041666667 | 15557 |
| 015553 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:16pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592803.8 | 511359.8 | 21921 | 1.64041666667 | 15553 |
| 015041 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:17pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592803.7 | 511362.4 | 21923 | 1.64041666667 | 15041 |
| 014115 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:18pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592803.3 | 511364.9 | 21925 | 1.64041666667 | 14115 |
| 014795 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:19pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592803.1 | 511367.3 | 21927 | 1.64041666667 | 14795 |
| 014517 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:20pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592802.8 | 511369.5 | 21929 | 1.64041666667 | 14517 |
| 014368 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:21pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592801.7 | 511372.2 | 21931 | 1.64041666667 | 14368 |
| 014307 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:22pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592800.8 | 511374.6 | 21933 | 1.64041666667 | 14307 |
| 014055 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:23pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592799.7 | 511377.1 | 21935 | 1.64041666667 | 14055 |
| 014521 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:24pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592798.2 | 511379.5 | 21937 | 1.64041666667 | 14521 |
| 014415 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592797.3 | 511381.8 | 21939 | 1.64041666667 | 14415 |
| 013981 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:26pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592796.4 | 511384.4 | 21941 | 1.64041666667 | 13981 |
| 014374 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:27pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592795.4 | 511386.9 | 21943 | 1.64041666667 | 14374 |
| 014040 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:28pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592794.9 | 511389.4 | 21945 | 1.64041666667 | 14040 |
| 013822 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:29pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592794.3 | 511392.2 | 21947 | 1.64041666667 | 13822 |
| 013895 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:30pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592793.4 | 511394.7 | 21949 | 1.64041666667 | 13895 |
| 014146 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:31pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592793.1 | 511397.7 | 21951 | 1.64041666667 | 14146 |
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592792.6 | 511400.0 | 21953 | 1.64041666667 | 14227 |
| 014377 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:33pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592792.0 | 511402.8 | 21955 | 1.64041666667 | 14377 |
| 013795 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592791.7 | 511405.1 | 21957 | 1.64041666667 | 13795 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013024 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592791.1 | 511407.7 | 21959 | 1.64041666667 | 13024 |
| 013274 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592790.5 | 511410.0 | 21961 | 1.64041666667 | 13274 |
| 013586 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592790.0 | 511412.5 | 21963 | 1.64041666667 | 13586 |
| 013155 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592789.1 | 511414.8 | 21965 | 1.64041666667 | 13155 |
| 013624 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592788.1 | 511417.3 | 21967 | 1.64041666667 | 13624 |
| 013701 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592787.2 | 511419.8 | 21969 | 1.64041666667 | 13701 |
| 013527 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592785.6 | 511422.4 | 21971 | 1.64041666667 | 13527 |
| 013578 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592784.2 | 511424.7 | 21973 | 1.64041666667 | 13578 |
| 013495 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592782.8 | 511427.3 | 21975 | 1.64041666667 | 13495 |
| 013073 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592781.6 | 511429.0 | 21977 | 1.64041666667 | 13073 |
| 012994 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592780.2 | 511430.9 | 21979 | 1.64041666667 | 12994 |
| 013511 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592778.7 | 511432.0 | 21981 | 1.64041666667 | 13511 |
| 013802 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592776.4 | 511431.7 | 21983 | 1.64041666667 | 13802 |
| 013074 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592774.4 | 511430.7 | 21985 | 1.64041666667 | 13074 |
| 013811 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592772.6 | 511429.4 | 21987 | 1.64041666667 | 13811 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592772.1 | 511427.5 | 21989 | 1.64041666667 | 13491 |
| 013964 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592772.9 | 511425.0 | 21991 | 1.64041666667 | 13964 |
| 013292 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592774.1 | 511423.2 | 21993 | 1.64041666667 | 13292 |
| 013109 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592776.2 | 511421.7 | 21995 | 1.64041666667 | 13109 |
| 012894 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592778.3 | 511420.3 | 21997 | 1.64041666667 | 12894 |
| 012390 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592780.4 | 511418.6 | 21999 | 1.64041666667 | 12390 |
| 012932 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592782.6 | 511417.3 | 22001 | 1.64041666667 | 12932 |
| 013454 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592784.9 | 511415.8 | 22003 | 1.64041666667 | 13454 |
| 014460 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:58pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592786.4 | 511414.1 | 22005 | 1.64041666667 | 14460 |
| 014321 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592787.8 | 511411.9 | 22007 | 1.64041666667 | 14321 |
| 014423 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:00pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592789.2 | 511409.7 | 22009 | 1.64041666667 | 14423 |
| 013880 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592790.2 | 511407.3 | 22011 | 1.64041666667 | 13880 |
| 013672 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592791.3 | 511405.2 | 22013 | 1.64041666667 | 13672 |
| 013871 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592792.0 | 511403.2 | 22015 | 1.64041666667 | 13871 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:04pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592792.3 | 511401.7 | 22017 | 1.64041666667 | 14072 |
| 014778 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592792.1 | 511400.1 | 22019 | 1.64041666667 | 14778 |
| 014635 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592791.4 | 511398.1 | 22021 | 1.64041666667 | 14635 |
| 014974 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:07pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592791.5 | 511395.6 | 22023 | 1.64041666667 | 14974 |
| 013545 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592791.8 | 511393.2 | 22025 | 1.64041666667 | 13545 |
| 013499 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:09pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592791.9 | 511390.6 | 22027 | 1.64041666667 | 13499 |
| 013383 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:10pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592792.3 | 511388.4 | 22029 | 1.64041666667 | 13383 |
| 013220 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:11pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592792.5 | 511385.8 | 22031 | 1.64041666667 | 13220 |
| 013676 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:12pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592792.2 | 511383.4 | 22033 | 1.64041666667 | 13676 |
| 014930 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:13pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592792.2 | 511380.7 | 22035 | 1.64041666667 | 14930 |
| 014758 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:14pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592791.9 | 511378.4 | 22037 | 1.64041666667 | 14758 |
| 013739 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:15pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592790.9 | 511375.9 | 22039 | 1.64041666667 | 13739 |
| 014140 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:16pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592790.6 | 511373.6 | 22041 | 1.64041666667 | 14140 |
| 013946 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:17pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592790.1 | 511370.3 | 22043 | 1.64041666667 | 13946 |
| 013867 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:18pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592789.3 | 511368.0 | 22045 | 1.64041666667 | 13867 |
| 014100 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:19pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592788.7 | 511365.3 | 22047 | 1.64041666667 | 14100 |
| 014891 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:20pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592788.7 | 511363.0 | 22049 | 1.64041666667 | 14891 |
| 014939 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:21pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592789.2 | 511360.6 | 22051 | 1.64041666667 | 14939 |
| 014725 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:22pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592790.3 | 511358.6 | 22053 | 1.64041666667 | 14725 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014605 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:23pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592792.0 | 511356.1 | 22055 | 1.64041666667 | 14605 |
| 014613 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:24pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592793.0 | 511354.1 | 22057 | 1.64041666667 | 14613 |
| 014430 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592794.7 | 511351.6 | 22059 | 1.64041666667 | 14430 |
| 014274 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:26pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592795.8 | 511349.6 | 22061 | 1.64041666667 | 14274 |
| 013654 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:27pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592796.6 | 511347.0 | 22063 | 1.64041666667 | 13654 |
| 014888 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:28pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592797.5 | 511344.3 | 22065 | 1.64041666667 | 14888 |
| 014689 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:29pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592797.6 | 511341.8 | 22067 | 1.64041666667 | 14689 |
| 015117 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:30pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592796.0 | 511339.7 | 22069 | 1.64041666667 | 15117 |
| 015096 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:31pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592793.6 | 511338.4 | 22071 | 1.64041666667 | 15096 |
| 014844 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:32pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592791.0 | 511338.6 | 22073 | 1.64041666667 | 14844 |
| 014162 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:33pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592789.3 | 511340.6 | 22075 | 1.64041666667 | 14162 |
| 014678 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592787.9 | 511342.9 | 22077 | 1.64041666667 | 14678 |
| 015104 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592786.9 | 511345.5 | 22079 | 1.64041666667 | 15104 |
| 015793 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592786.7 | 511347.8 | 22081 | 1.64041666667 | 15793 |
| 015506 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:37pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592786.1 | 511350.9 | 22083 | 1.64041666667 | 15506 |
| 014647 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:38pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592785.8 | 511353.6 | 22085 | 1.64041666667 | 14647 |
| 014681 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:39pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592785.7 | 511356.4 | 22087 | 1.64041666667 | 14681 |
| 014528 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:40pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592784.9 | 511358.7 | 22089 | 1.64041666667 | 14528 |
| 014659 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:41pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592783.8 | 511361.1 | 22091 | 1.64041666667 | 14659 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:42pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592783.0 | 511363.6 | 22093 | 1.64041666667 | 14456 |
| 015519 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592781.9 | 511366.2 | 22095 | 1.64041666667 | 15519 |
| 014909 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592780.8 | 511368.7 | 22097 | 1.64041666667 | 14909 |
| 014589 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592780.1 | 511371.5 | 22099 | 1.64041666667 | 14589 |
| 013816 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592779.3 | 511374.0 | 22101 | 1.64041666667 | 13816 |
| 013651 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592778.4 | 511376.9 | 22103 | 1.64041666667 | 13651 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592778.1 | 511379.6 | 22105 | 1.64041666667 | 14556 |
| 014810 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592777.5 | 511382.3 | 22107 | 1.64041666667 | 14810 |
| 015313 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592776.5 | 511384.7 | 22109 | 1.64041666667 | 15313 |
| 014643 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592775.9 | 511387.5 | 22111 | 1.64041666667 | 14643 |
| 014004 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592775.5 | 511389.9 | 22113 | 1.64041666667 | 14004 |
| 014815 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592774.4 | 511392.8 | 22115 | 1.64041666667 | 14815 |
| 013996 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:54pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592774.0 | 511395.3 | 22117 | 1.64041666667 | 13996 |
| 013475 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:55pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592773.6 | 511398.1 | 22119 | 1.64041666667 | 13475 |
| 013317 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:56pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592772.8 | 511400.6 | 22121 | 1.64041666667 | 13317 |
| 013056 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:57pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592772.4 | 511403.8 | 22123 | 1.64041666667 | 13056 |
| 013126 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:58pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592772.1 | 511406.5 | 22125 | 1.64041666667 | 13126 |
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:59pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592771.0 | 511409.3 | 22127 | 1.64041666667 | 12761 |
| 012728 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592769.7 | 511412.0 | 22129 | 1.64041666667 | 12728 |
| 013354 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592768.4 | 511414.8 | 22131 | 1.64041666667 | 13354 |
| 013699 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592767.3 | 511417.0 | 22133 | 1.64041666667 | 13699 |
| 014216 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592765.8 | 511419.9 | 22135 | 1.64041666667 | 14216 |
| 013779 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592764.9 | 511422.3 | 22137 | 1.64041666667 | 13779 |
| 014260 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592763.8 | 511425.0 | 22139 | 1.64041666667 | 14260 |
| 014906 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592762.8 | 511426.5 | 22141 | 1.64041666667 | 14906 |
| 013845 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592761.6 | 511427.4 | 22143 | 1.64041666667 | 13845 |
| 014432 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592759.6 | 511427.2 | 22145 | 1.64041666667 | 14432 |
| 014313 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592757.0 | 511426.6 | 22147 | 1.64041666667 | 14313 |
| 014163 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592755.5 | 511425.5 | 22149 | 1.64041666667 | 14163 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013292 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592754.8 | 511423.0 | 22151 | 1.64041666667 | 13292 |
| 012599 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592754.7 | 511420.4 | 22153 | 1.64041666667 | 12599 |
| 012764 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592755.1 | 511417.8 | 22155 | 1.64041666667 | 12764 |
| 012505 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592755.7 | 511415.2 | 22157 | 1.64041666667 | 12505 |
| 012929 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592755.9 | 511412.6 | 22159 | 1.64041666667 | 12929 |
| 012867 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592756.2 | 511410.5 | 22161 | 1.64041666667 | 12867 |
| 012653 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592757.1 | 511408.0 | 22163 | 1.64041666667 | 12653 |
| 012592 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592757.5 | 511406.0 | 22165 | 1.64041666667 | 12592 |
| 012790 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592758.5 | 511403.4 | 22167 | 1.64041666667 | 12790 |
| 012849 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592759.7 | 511401.5 | 22169 | 1.64041666667 | 12849 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592760.9 | 511398.9 | 22171 | 1.64041666667 | 13295 |
| 013636 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592762.2 | 511396.8 | 22173 | 1.64041666667 | 13636 |
| 013857 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592763.2 | 511394.5 | 22175 | 1.64041666667 | 13857 |
| 014057 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592763.7 | 511392.1 | 22177 | 1.64041666667 | 14057 |
| 012917 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592764.8 | 511389.2 | 22179 | 1.64041666667 | 12917 |
| 012733 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:26pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592765.9 | 511386.7 | 22181 | 1.64041666667 | 12733 |
| 012825 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:27pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592766.3 | 511384.0 | 22183 | 1.64041666667 | 12825 |
| 013139 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:28pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592766.0 | 511381.2 | 22185 | 1.64041666667 | 13139 |
| 013968 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:29pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592765.1 | 511378.1 | 22187 | 1.64041666667 | 13968 |
| 013227 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:30pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592764.3 | 511375.8 | 22189 | 1.64041666667 | 13227 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:31pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592763.7 | 511373.2 | 22191 | 1.64041666667 | 13132 |
| 014354 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:32pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592763.7 | 511370.7 | 22193 | 1.64041666667 | 14354 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:33pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592764.4 | 511367.8 | 22195 | 1.64041666667 | 13782 |
| 014209 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592765.0 | 511365.4 | 22197 | 1.64041666667 | 14209 |
| 014225 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592766.2 | 511363.0 | 22199 | 1.64041666667 | 14225 |
| 014414 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592767.3 | 511360.8 | 22201 | 1.64041666667 | 14414 |
| 014415 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:37pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592768.2 | 511358.1 | 22203 | 1.64041666667 | 14415 |
| 014401 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:38pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592769.1 | 511356.0 | 22205 | 1.64041666667 | 14401 |
| 014580 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:39pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592770.3 | 511353.2 | 22207 | 1.64041666667 | 14580 |
| 014996 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:40pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592770.8 | 511350.7 | 22209 | 1.64041666667 | 14996 |
| 014203 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:41pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592771.4 | 511348.2 | 22211 | 1.64041666667 | 14203 |
| 013764 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:42pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592772.0 | 511345.6 | 22213 | 1.64041666667 | 13764 |
| 014754 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592771.9 | 511343.2 | 22215 | 1.64041666667 | 14754 |
| 014449 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592772.0 | 511341.0 | 22217 | 1.64041666667 | 14449 |
| 014322 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592772.5 | 511338.9 | 22219 | 1.64041666667 | 14322 |
| 014754 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:46pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592772.8 | 511337.2 | 22221 | 1.64041666667 | 14754 |
| 014951 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:47pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592773.8 | 511335.3 | 22223 | 1.64041666667 | 14951 |
| 015617 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:48pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592774.9 | 511333.9 | 22225 | 1.64041666667 | 15617 |
| 014065 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:49pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592775.9 | 511333.6 | 22227 | 1.64041666667 | 14065 |
| 013911 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:50pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592777.3 | 511334.4 | 22229 | 1.64041666667 | 13911 |
| 013120 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:51pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592778.1 | 511335.2 | 22231 | 1.64041666667 | 13120 |
| 014010 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:52pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592778.2 | 511335.3 | 22233 | 1.64041666667 | 14010 |
| 013595 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:53pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592778.2 | 511335.2 | 22235 | 1.64041666667 | 13595 |
| 014945 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:54pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592778.2 | 511335.2 | 22237 | 1.64041666667 | 14945 |
| 014586 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:55pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592778.2 | 511335.2 | 22239 | 1.64041666667 | 14586 |
| 015067 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:56pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592778.2 | 511335.2 | 22241 | 1.64041666667 | 15067 |
| 015090 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:57pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592778.2 | 511335.2 | 22243 | 1.64041666667 | 15090 |
| 015433 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:58pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592778.2 | 511335.2 | 22245 | 1.64041666667 | 15433 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:59pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592778.2 | 511335.3 | 22247 | 1.64041666667 | 14516 |
| 015125 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:00pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592778.6 | 511335.1 | 22249 | 1.64041666667 | 15125 |
| 014950 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:01pm | Sensor | 1797-S0025-905-G-ACK | 6806.8 | 1592779.6 | 511335.6 | 22251 | 1.64041666667 | 14950 |
| 014477 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:02pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592780.8 | 511336.3 | 22253 | 1.64041666667 | 14477 |
| 014571 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:03pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592782.3 | 511337.6 | 22255 | 1.64041666667 | 14571 |
| 014241 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:04pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592783.9 | 511339.2 | 22257 | 1.64041666667 | 14241 |
| 014678 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:05pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592785.7 | 511340.1 | 22259 | 1.64041666667 | 14678 |
| 014204 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:06pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592787.3 | 511341.0 | 22261 | 1.64041666667 | 14204 |
| 014934 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:07pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592788.3 | 511341.6 | 22263 | 1.64041666667 | 14934 |
| 015165 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:08pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592788.6 | 511341.7 | 22265 | 1.64041666667 | 15165 |
| 015205 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:09pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592788.6 | 511341.8 | 22267 | 1.64041666667 | 15205 |
| 014958 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:10pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592788.6 | 511341.9 | 22269 | 1.64041666667 | 14958 |
| 015636 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:11pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592788.5 | 511341.9 | 22271 | 1.64041666667 | 15636 |
| 015650 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:12pm | Sensor | 1797-S0025-905-G-ACK | 6806.9 | 1592788.5 | 511341.9 | 22273 | 1.64041666667 | 15650 |
| 015628 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:13pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592788.8 | 511341.5 | 22275 | 1.64041666667 | 15628 |
| 015128 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:14pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592789.4 | 511341.4 | 22277 | 1.64041666667 | 15128 |
| 015289 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:15pm | Sensor | 1797-S0025-905-G-ACK | 6807.0 | 1592790.6 | 511342.0 | 22279 | 1.64041666667 | 15289 |
| 015050 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:16pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592791.7 | 511343.0 | 22281 | 1.64041666667 | 15050 |
| 014863 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:17pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592793.7 | 511344.8 | 22283 | 1.64041666667 | 14863 |
| 014443 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:18pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592795.4 | 511346.0 | 22285 | 1.64041666667 | 14443 |
| 013929 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:19pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592796.8 | 511348.1 | 22287 | 1.64041666667 | 13929 |
| 014847 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:20pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592797.7 | 511350.8 | 22289 | 1.64041666667 | 14847 |
| 014989 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:21pm | Sensor | 1797-S0025-905-G-ACK | 6807.1 | 1592798.7 | 511353.6 | 22291 | 1.64041666667 | 14989 |
| 015084 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:22pm | Sensor | 1797-S0025-905-G-ACK | 6807.2 | 1592799.7 | 511356.1 | 22293 | 1.64041666667 | 15084 |
| 015722 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:23pm | Sensor | 1797-S0025-905-G-ACK | 6807.3 | 1592800.2 | 511358.7 | 22295 | 1.64041666667 | 15722 |
| 015391 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:24pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592800.6 | 511360.1 | 22297 | 1.64041666667 | 15391 |
| 014605 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:25pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592801.1 | 511360.6 | 22299 | 1.64041666667 | 14605 |
| 014178 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:26pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592801.2 | 511360.7 | 22301 | 1.64041666667 | 14178 |
| 014440 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:27pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592801.1 | 511360.6 | 22303 | 1.64041666667 | 14440 |
| 013732 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:28pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592800.7 | 511360.7 | 22305 | 1.64041666667 | 13732 |
| 013957 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:29pm | Sensor | 1797-S0025-905-G-ACK | 6807.4 | 1592800.8 | 511361.5 | 22307 | 1.64041666667 | 13957 |
| 014023 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:30pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592801.0 | 511363.7 | 22309 | 1.64041666667 | 14023 |
| 014533 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:31pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592800.8 | 511366.2 | 22311 | 1.64041666667 | 14533 |
| 014800 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:32pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592800.9 | 511368.8 | 22313 | 1.64041666667 | 14800 |
| 015157 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:33pm | Sensor | 1797-S0025-905-G-ACK | 6807.5 | 1592800.7 | 511371.5 | 22315 | 1.64041666667 | 15157 |
| 015081 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.6 | 1592800.1 | 511374.2 | 22317 | 1.64041666667 | 15081 |
| 014288 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592799.9 | 511376.5 | 22319 | 1.64041666667 | 14288 |
| 014629 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592799.6 | 511378.5 | 22321 | 1.64041666667 | 14629 |
| 014304 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:37pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592799.0 | 511381.2 | 22323 | 1.64041666667 | 14304 |
| 014023 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:38pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592799.4 | 511383.6 | 22325 | 1.64041666667 | 14023 |
| 015163 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:39pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592800.8 | 511385.8 | 22327 | 1.64041666667 | 15163 |
| 014769 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:40pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592802.3 | 511387.1 | 22329 | 1.64041666667 | 14769 |
| 014060 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:41pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592803.7 | 511387.2 | 22331 | 1.64041666667 | 14060 |
| 014163 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592803.9 | 511387.0 | 22333 | 1.64041666667 | 14163 |
| 013854 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592803.9 | 511387.0 | 22335 | 1.64041666667 | 13854 |
| 014393 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592804.4 | 511387.3 | 22337 | 1.64041666667 | 14393 |
| 014748 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592805.4 | 511388.1 | 22339 | 1.64041666667 | 14748 |
| 015518 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.7 | 1592806.2 | 511388.9 | 22341 | 1.64041666667 | 15518 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015344 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:47pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592806.5 | 511390.3 | 22343 | 1.64041666667 | 15344 |
| 014601 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:48pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592806.1 | 511391.9 | 22345 | 1.64041666667 | 14601 |
| 013995 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:49pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.5 | 511393.0 | 22347 | 1.64041666667 | 13995 |
| 013392 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:50pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592804.4 | 511393.3 | 22349 | 1.64041666667 | 13392 |
| 014238 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:51pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592804.3 | 511392.4 | 22351 | 1.64041666667 | 14238 |
| 014864 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:52pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.1 | 511391.0 | 22353 | 1.64041666667 | 14864 |
| 014826 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:53pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.4 | 511389.5 | 22355 | 1.64041666667 | 14826 |
| 014362 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511388.9 | 22357 | 1.64041666667 | 14362 |
| 014221 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.3 | 511388.9 | 22359 | 1.64041666667 | 14221 |
| 013556 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.3 | 511389.2 | 22361 | 1.64041666667 | 13556 |
| 013783 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511390.1 | 22363 | 1.64041666667 | 13783 |
| 013903 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:58pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.3 | 511390.7 | 22365 | 1.64041666667 | 13903 |
| 014323 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.4 | 511390.9 | 22367 | 1.64041666667 | 14323 |
| 015054 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.4 | 511390.8 | 22369 | 1.64041666667 | 15054 |
| 014632 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.3 | 511390.5 | 22371 | 1.64041666667 | 14632 |
| 014583 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.1 | 511390.0 | 22373 | 1.64041666667 | 14583 |
| 014405 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.0 | 511389.8 | 22375 | 1.64041666667 | 14405 |
| 014095 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511389.7 | 22377 | 1.64041666667 | 14095 |
| 014236 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.3 | 511389.7 | 22379 | 1.64041666667 | 14236 |
| 013768 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.3 | 511389.7 | 22381 | 1.64041666667 | 13768 |
| 013691 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.3 | 511389.7 | 22383 | 1.64041666667 | 13691 |
| 013169 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.3 | 511389.7 | 22385 | 1.64041666667 | 13169 |
| 012890 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511389.7 | 22387 | 1.64041666667 | 12890 |
| 012493 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511389.7 | 22388 | 1.64041666667 | 12493 |
| 014437 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511389.7 | 22389 | 1.64041666667 | 14437 |
| 013633 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511389.7 | 22390 | 1.64041666667 | 13633 |
| 013271 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.7 | 22391 | 1.64041666667 | 13271 |
| 013330 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.7 | 22392 | 1.64041666667 | 13330 |
| 014285 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511389.7 | 22393 | 1.64041666667 | 14285 |
| 014441 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.7 | 22394 | 1.64041666667 | 14441 |
| 014235 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.8 | 22395 | 1.64041666667 | 14235 |
| 013790 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.8 | 22396 | 1.64041666667 | 13790 |
| 013329 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511389.7 | 22397 | 1.64041666667 | 13329 |
| 014015 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.3 | 511389.7 | 22398 | 1.64041666667 | 14015 |
| 015871 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.2 | 511389.8 | 22399 | 1.64041666667 | 15871 |
| 015265 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.3 | 511389.8 | 22400 | 1.64041666667 | 15265 |
| 015051 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.3 | 511389.8 | 22401 | 1.64041666667 | 15051 |
| 013926 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.3 | 511389.8 | 22402 | 1.64041666667 | 13926 |
| 014043 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.3 | 511389.8 | 22403 | 1.64041666667 | 14043 |
| 014454 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.3 | 511389.8 | 22404 | 1.64041666667 | 14454 |
| 014048 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.3 | 511389.8 | 22405 | 1.64041666667 | 14048 |
| 014149 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592805.3 | 511389.8 | 22406 | 1.64041666667 | 14149 |
| 013974 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.8 | 22407 | 1.64041666667 | 13974 |
| 013792 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.9 | 22408 | 1.64041666667 | 13792 |
| 014088 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.1 | 511389.9 | 22409 | 1.64041666667 | 14088 |
| 013332 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511390.0 | 22410 | 1.64041666667 | 13332 |
| 013649 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:33pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.2 | 511389.9 | 22411 | 1.64041666667 | 13649 |
| 014690 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:34pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.2 | 511389.9 | 22412 | 1.64041666667 | 14690 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015028 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:35pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.2 | 511389.9 | 22413 | 1.64041666667 | 15028 |
| 014483 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:36pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.2 | 511389.9 | 22414 | 1.64041666667 | 14483 |
| 014147 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:37pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.2 | 511389.9 | 22415 | 1.64041666667 | 14147 |
| 014474 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.1 | 511389.9 | 22416 | 1.64041666667 | 14474 |
| 014029 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.9 | 22418 | 1.64041666667 | 14029 |
| 013674 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592805.2 | 511389.9 | 22420 | 1.64041666667 | 13674 |
| 014044 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:42pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592805.7 | 511389.6 | 22422 | 1.64041666667 | 14044 |
| 013842 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592879.5 | 511350.1 | 22424 | 1.64041666667 | 13842 |
| 013321 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592881.9 | 511348.9 | 22426 | 1.64041666667 | 13321 |
| 013418 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:40pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592883.9 | 511348.3 | 22428 | 1.64041666667 | 13418 |
| 014020 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:41pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592886.9 | 511347.5 | 22430 | 1.64041666667 | 14020 |
| 013368 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:42pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592889.7 | 511346.6 | 22432 | 1.64041666667 | 13368 |
| 014045 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:43pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592892.9 | 511345.8 | 22434 | 1.64041666667 | 14045 |
| 013788 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:44pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592896.2 | 511345.2 | 22436 | 1.64041666667 | 13788 |
| 014948 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:45pm | Sensor | 1797-S0025-905-G-ACK | 6807.8 | 1592900.6 | 511343.7 | 22438 | 1.64041666667 | 14948 |
| 014573 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:46pm | Sensor | 1797-S0025-905-G-ACK | 6807.9 | 1592904.0 | 511342.2 | 22440 | 1.64041666667 | 14573 |
| 015007 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592907.6 | 511340.4 | 22442 | 1.64041666667 | 15007 |
| 014509 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592910.8 | 511338.8 | 22444 | 1.64041666667 | 14509 |
| 013891 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.0 | 1592914.2 | 511337.0 | 22446 | 1.64041666667 | 13891 |
| 013476 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:50pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592917.2 | 511335.5 | 22448 | 1.64041666667 | 13476 |
| 013625 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:51pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592920.8 | 511334.1 | 22450 | 1.64041666667 | 13625 |
| 013492 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:52pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592924.2 | 511333.1 | 22452 | 1.64041666667 | 13492 |
| 013364 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:53pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592928.1 | 511332.3 | 22454 | 1.64041666667 | 13364 |
| 013562 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:54pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1592931.7 | 511331.9 | 22456 | 1.64041666667 | 13562 |
| 014108 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:55pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592935.7 | 511331.1 | 22458 | 1.64041666667 | 14108 |
| 014303 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:56pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592939.1 | 511329.9 | 22460 | 1.64041666667 | 14303 |
| 013820 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:57pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592942.8 | 511328.4 | 22462 | 1.64041666667 | 13820 |
| 013759 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:58pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592946.1 | 511327.0 | 22464 | 1.64041666667 | 13759 |
| 014107 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:59pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592949.7 | 511325.3 | 22466 | 1.64041666667 | 14107 |
| 014040 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:00pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592952.5 | 511324.1 | 22468 | 1.64041666667 | 14040 |
| 014242 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:01pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592956.7 | 511322.1 | 22470 | 1.64041666667 | 14242 |
| 014851 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:02pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592959.9 | 511320.0 | 22472 | 1.64041666667 | 14851 |
| 014166 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:03pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592963.3 | 511317.0 | 22474 | 1.64041666667 | 14166 |
| 013143 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:04pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592965.7 | 511314.9 | 22476 | 1.64041666667 | 13143 |
| 013213 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:05pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592968.9 | 511312.5 | 22478 | 1.64041666667 | 13213 |
| 012202 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:06pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592971.2 | 511310.5 | 22480 | 1.64041666667 | 12202 |
| 013164 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:07pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592973.8 | 511308.5 | 22482 | 1.64041666667 | 13164 |
| 012842 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:08pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592976.4 | 511306.8 | 22484 | 1.64041666667 | 12842 |
| 013756 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:09pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1592979.6 | 511305.0 | 22486 | 1.64041666667 | 13756 |
| 014877 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:10pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1592982.5 | 511303.4 | 22488 | 1.64041666667 | 14877 |
| 015036 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:11pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592985.6 | 511301.4 | 22490 | 1.64041666667 | 15036 |
| 015553 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:12pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1592987.9 | 511299.4 | 22492 | 1.64041666667 | 15553 |
| 015551 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:13pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592990.6 | 511296.9 | 22494 | 1.64041666667 | 15551 |
| 015655 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:14pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1592993.0 | 511295.3 | 22496 | 1.64041666667 | 15655 |
| 015308 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:15pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592996.3 | 511293.9 | 22498 | 1.64041666667 | 15308 |
| 014813 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:16pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1592999.0 | 511293.3 | 22500 | 1.64041666667 | 14813 |
| 014085 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:17pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1593002.5 | 511292.4 | 22502 | 1.64041666667 | 14085 |
| 014335 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:18pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1593005.2 | 511291.5 | 22504 | 1.64041666667 | 14335 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013748 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:19pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1593008.4 | 511290.0 | 22506 | 1.64041666667 | 13748 |
| 013771 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:20pm | Sensor | 1797-S0025-905-G-ACK | 6808.7 | 1593011.0 | 511288.9 | 22508 | 1.64041666667 | 13771 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:21pm | Sensor | 1797-S0025-905-G-ACK | 6808.6 | 1593014.3 | 511287.8 | 22510 | 1.64041666667 | 13453 |
| 013942 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:22pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1593016.9 | 511286.9 | 22512 | 1.64041666667 | 13942 |
| 014075 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:23pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1593019.0 | 511286.1 | 22514 | 1.64041666667 | 14075 |
| 014487 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:24pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1593020.5 | 511286.0 | 22516 | 1.64041666667 | 14487 |
| 015011 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:25pm | Sensor | 1797-S0025-905-G-ACK | 6808.5 | 1593023.1 | 511285.1 | 22518 | 1.64041666667 | 15011 |
| 014159 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:26pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1593025.9 | 511283.4 | 22520 | 1.64041666667 | 14159 |
| 014287 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:27pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593029.5 | 511281.2 | 22522 | 1.64041666667 | 14287 |
| 014913 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:28pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593032.2 | 511279.5 | 22524 | 1.64041666667 | 14913 |
| 015094 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:29pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593035.8 | 511277.3 | 22526 | 1.64041666667 | 15094 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:30pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593038.6 | 511275.4 | 22528 | 1.64041666667 | 14655 |
| 015083 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:31pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593042.2 | 511273.1 | 22530 | 1.64041666667 | 15083 |
| 015039 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:32pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593044.8 | 511271.3 | 22532 | 1.64041666667 | 15039 |
| 015195 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:33pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593048.0 | 511269.1 | 22534 | 1.64041666667 | 15195 |
| 015034 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:34pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593051.1 | 511267.2 | 22536 | 1.64041666667 | 15034 |
| 014944 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:35pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593054.2 | 511265.7 | 22538 | 1.64041666667 | 14944 |
| 014781 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:36pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593057.3 | 511264.1 | 22540 | 1.64041666667 | 14781 |
| 015874 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:37pm | Sensor | 1797-S0025-905-G-ACK | 6808.4 | 1593060.4 | 511262.1 | 22542 | 1.64041666667 | 15874 |
| 016489 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:38pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593062.9 | 511260.2 | 22544 | 1.64041666667 | 16489 |
| 016347 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:39pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593065.7 | 511258.1 | 22546 | 1.64041666667 | 16347 |
| 015728 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:40pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593067.8 | 511256.8 | 22548 | 1.64041666667 | 15728 |
| 015349 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:41pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593070.8 | 511255.2 | 22550 | 1.64041666667 | 15349 |
| 014311 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:42pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593073.2 | 511253.8 | 22552 | 1.64041666667 | 14311 |
| 014912 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:43pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593076.1 | 511252.0 | 22554 | 1.64041666667 | 14912 |
| 014523 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:44pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593078.0 | 511250.5 | 22556 | 1.64041666667 | 14523 |
| 015032 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:45pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593079.7 | 511248.3 | 22558 | 1.64041666667 | 15032 |
| 015205 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:46pm | Sensor | 1797-S0025-905-G-ACK | 6808.3 | 1593081.4 | 511246.5 | 22560 | 1.64041666667 | 15205 |
| 016660 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:47pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593083.3 | 511245.1 | 22562 | 1.64041666667 | 16660 |
| 016946 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:48pm | Sensor | 1797-S0025-905-G-ACK | 6808.2 | 1593085.0 | 511243.5 | 22564 | 1.64041666667 | 16946 |
| 016477 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:49pm | Sensor | 1797-S0025-905-G-ACK | 6808.1 | 1593086.0 | 511242.4 | 22567 | 1.64041666667 | 16477 |
| 014504 | 0 | GeoXH 6000 | 08/18/2015 | 12:49:53pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593093.0 | 511229.5 | 15890 | 1.64041666667 | 14504 |
| 016406 | 0 | GeoXH 6000 | 08/18/2015 | 12:49:53pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593093.0 | 511229.5 | 15891 | 1.64041666667 | 16406 |
| 015891 | 0 | GeoXH 6000 | 08/18/2015 | 12:49:55pm | Sensor | 1797-S0024-G-TJV.cor | 6808.1 | 1593091.4 | 511228.6 | 15895 | 1.64041666667 | 15891 |
| 015222 | 0 | GeoXH 6000 | 08/18/2015 | 12:49:55pm | Sensor | 1797-S0024-G-TJV.cor | 6808.1 | 1593091.4 | 511228.7 | 15896 | 1.64041666667 | 15222 |
| 014065 | 0 | GeoXH 6000 | 08/18/2015 | 12:49:56pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593091.4 | 511228.6 | 15898 | 1.64041666667 | 14065 |
| 015786 | 0 | GeoXH 6000 | 08/18/2015 | 12:49:57pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593091.4 | 511228.6 | 15900 | 1.64041666667 | 15786 |
| 015496 | 0 | GeoXH 6000 | 08/18/2015 | 12:49:58pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593091.4 | 511228.6 | 15902 | 1.64041666667 | 15496 |
| 015064 | 0 | GeoXH 6000 | 08/18/2015 | 12:49:59pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593091.4 | 511228.6 | 15904 | 1.64041666667 | 15064 |
| 015046 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:00pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593091.4 | 511228.6 | 15906 | 1.64041666667 | 15046 |
| 013751 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:01pm | Sensor | 1797-S0024-G-TJV.cor | 6807.8 | 1593091.4 | 511228.6 | 15908 | 1.64041666667 | 13751 |
| 014808 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:02pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593091.4 | 511228.6 | 15910 | 1.64041666667 | 14808 |
| 015402 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:03pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593091.4 | 511228.7 | 15912 | 1.64041666667 | 15402 |
| 015370 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:04pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593091.5 | 511228.6 | 15914 | 1.64041666667 | 15370 |
| 014432 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:05pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593091.5 | 511228.6 | 15916 | 1.64041666667 | 14432 |
| 013958 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:07pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593091.5 | 511228.7 | 15919 | 1.64041666667 | 13958 |
| 014409 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:07pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593091.5 | 511228.7 | 15920 | 1.64041666667 | 14409 |
| 013622 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:09pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593091.5 | 511228.6 | 15923 | 1.64041666667 | 13622 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014475 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:09pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593091.6 | 511228.7 | 15924 | 1.64041666667 | 14475 |
| 014508 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:11pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593092.3 | 511228.9 | 15927 | 1.64041666667 | 14508 |
| 015687 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:11pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593092.1 | 511228.2 | 15928 | 1.64041666667 | 15687 |
| 013732 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:12pm | Sensor | 1797-S0024-G-TJV.cor | 6808.0 | 1593090.7 | 511227.7 | 15930 | 1.64041666667 | 13732 |
| 016303 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:13pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593090.2 | 511225.8 | 15932 | 1.64041666667 | 16303 |
| 014605 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:14pm | Sensor | 1797-S0024-G-TJV.cor | 6807.9 | 1593089.9 | 511223.3 | 15934 | 1.64041666667 | 14605 |
| 015171 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:15pm | Sensor | 1797-S0024-G-TJV.cor | 6807.3 | 1593089.8 | 511220.8 | 15936 | 1.64041666667 | 15171 |
| 015792 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:16pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1593090.2 | 511217.8 | 15938 | 1.64041666667 | 15792 |
| 014118 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:17pm | Sensor | 1797-S0024-G-TJV.cor | 6807.0 | 1593089.5 | 511214.7 | 15940 | 1.64041666667 | 14118 |
| 015589 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:18pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1593088.1 | 511211.2 | 15942 | 1.64041666667 | 15589 |
| 014034 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:19pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593085.7 | 511208.1 | 15944 | 1.64041666667 | 14034 |
| 013664 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:20pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1593082.6 | 511205.4 | 15946 | 1.64041666667 | 13664 |
| 012386 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:21pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593080.0 | 511204.2 | 15948 | 1.64041666667 | 12386 |
| 012876 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:22pm | Sensor | 1797-S0024-G-TJV.cor | 6806.9 | 1593076.4 | 511203.0 | 15950 | 1.64041666667 | 12876 |
| 012759 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:23pm | Sensor | 1797-S0024-G-TJV.cor | 6806.9 | 1593073.1 | 511201.6 | 15952 | 1.64041666667 | 12759 |
| 013359 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:24pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593069.7 | 511199.6 | 15954 | 1.64041666667 | 13359 |
| 013930 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:25pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593067.5 | 511197.7 | 15956 | 1.64041666667 | 13930 |
| 014012 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:26pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593064.4 | 511195.7 | 15958 | 1.64041666667 | 14012 |
| 014003 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:27pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1593062.1 | 511194.4 | 15960 | 1.64041666667 | 14003 |
| 013460 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:28pm | Sensor | 1797-S0024-G-TJV.cor | 6807.0 | 1593059.1 | 511193.7 | 15962 | 1.64041666667 | 13460 |
| 014375 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:29pm | Sensor | 1797-S0024-G-TJV.cor | 6806.9 | 1593056.3 | 511192.7 | 15964 | 1.64041666667 | 14375 |
| 015833 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:30pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1593053.7 | 511190.9 | 15966 | 1.64041666667 | 15833 |
| 013828 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:31pm | Sensor | 1797-S0024-G-TJV.cor | 6807.0 | 1593051.3 | 511189.9 | 15968 | 1.64041666667 | 13828 |
| 012967 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:32pm | Sensor | 1797-S0024-G-TJV.cor | 6806.7 | 1593048.2 | 511188.9 | 15970 | 1.64041666667 | 12967 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:33pm | Sensor | 1797-S0024-G-TJV.cor | 6806.7 | 1593045.4 | 511187.7 | 15972 | 1.64041666667 | 13861 |
| 013095 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:34pm | Sensor | 1797-S0024-G-TJV.cor | 6807.0 | 1593042.4 | 511187.1 | 15974 | 1.64041666667 | 13095 |
| 013803 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:35pm | Sensor | 1797-S0024-G-TJV.cor | 6806.8 | 1593040.7 | 511186.0 | 15976 | 1.64041666667 | 13803 |
| 014401 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:36pm | Sensor | 1797-S0024-G-TJV.cor | 6806.8 | 1593038.2 | 511184.3 | 15978 | 1.64041666667 | 14401 |
| 014880 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:37pm | Sensor | 1797-S0024-G-TJV.cor | 6806.9 | 1593035.5 | 511184.2 | 15980 | 1.64041666667 | 14880 |
| 015060 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:38pm | Sensor | 1797-S0024-G-TJV.cor | 6807.0 | 1593032.0 | 511183.3 | 15982 | 1.64041666667 | 15060 |
| 013935 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:39pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593030.0 | 511182.3 | 15984 | 1.64041666667 | 13935 |
| 012303 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:40pm | Sensor | 1797-S0024-G-TJV.cor | 6806.8 | 1593026.3 | 511181.1 | 15986 | 1.64041666667 | 12303 |
| 012586 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:41pm | Sensor | 1797-S0024-G-TJV.cor | 6807.0 | 1593022.9 | 511180.8 | 15988 | 1.64041666667 | 12586 |
| 013226 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:42pm | Sensor | 1797-S0024-G-TJV.cor | 6806.8 | 1593018.9 | 511180.7 | 15990 | 1.64041666667 | 13226 |
| 013956 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:43pm | Sensor | 1797-S0024-G-TJV.cor | 6806.9 | 1593015.6 | 511180.8 | 15992 | 1.64041666667 | 13956 |
| 012819 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:44pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1593011.3 | 511181.6 | 15994 | 1.64041666667 | 12819 |
| 013494 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:45pm | Sensor | 1797-S0024-G-TJV.cor | 6807.4 | 1593008.7 | 511183.0 | 15996 | 1.64041666667 | 13494 |
| 013693 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:46pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1593005.7 | 511185.0 | 15998 | 1.64041666667 | 13693 |
| 013653 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:47pm | Sensor | 1797-S0024-G-TJV.cor | 6807.3 | 1593003.3 | 511186.7 | 16000 | 1.64041666667 | 13653 |
| 017453 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:48pm | Sensor | 1797-S0024-G-TJV.cor | 6807.3 | 1593000.5 | 511188.5 | 16002 | 1.64041666667 | 17453 |
| 015613 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:49pm | Sensor | 1797-S0024-G-TJV.cor | 6807.4 | 1592997.6 | 511190.0 | 16004 | 1.64041666667 | 15613 |
| 015813 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:50pm | Sensor | 1797-S0024-G-TJV.cor | 6807.3 | 1592994.3 | 511190.8 | 16006 | 1.64041666667 | 15813 |
| 016463 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:51pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1592991.1 | 511191.5 | 16008 | 1.64041666667 | 16463 |
| 014555 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:52pm | Sensor | 1797-S0024-G-TJV.cor | 6807.4 | 1592988.1 | 511192.9 | 16010 | 1.64041666667 | 14555 |
| 016299 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:53pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1592985.5 | 511194.1 | 16012 | 1.64041666667 | 16299 |
| 015894 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:55pm | Sensor | 1797-S0024-G-TJV.cor | 6807.4 | 1592982.2 | 511193.5 | 16015 | 1.64041666667 | 15894 |
| 015973 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:55pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1592980.0 | 511191.5 | 16016 | 1.64041666667 | 15973 |
| 015393 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:56pm | Sensor | 1797-S0024-G-TJV.cor | 6807.3 | 1592977.5 | 511188.6 | 16018 | 1.64041666667 | 15393 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014288 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:57pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1592975.2 | 511185.8 | 16020 | 1.64041666667 | 14288 |
| 015092 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:58pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1592972.4 | 511182.9 | 16022 | 1.64041666667 | 15092 |
| 014033 | 0 | GeoXH 6000 | 08/18/2015 | 12:50:59pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1592969.5 | 511180.4 | 16024 | 1.64041666667 | 14033 |
| 013678 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:00pm | Sensor | 1797-S0024-G-TJV.cor | 6806.9 | 1592965.6 | 511177.8 | 16026 | 1.64041666667 | 13678 |
| 013619 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:01pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1592962.6 | 511176.4 | 16028 | 1.64041666667 | 13619 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:02pm | Sensor | 1797-S0024-G-TJV.cor | 6806.9 | 1592958.8 | 511174.8 | 16030 | 1.64041666667 | 14655 |
| 013143 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:03pm | Sensor | 1797-S0024-G-TJV.cor | 6807.2 | 1592955.5 | 511173.2 | 16032 | 1.64041666667 | 13143 |
| 013905 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:04pm | Sensor | 1797-S0024-G-TJV.cor | 6807.1 | 1592951.9 | 511171.0 | 16034 | 1.64041666667 | 13905 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:05pm | Sensor | 1797-S0024-G-TJV.cor | 6807.0 | 1592949.6 | 511168.7 | 16036 | 1.64041666667 | 13736 |
| 015734 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:06pm | Sensor | 1797-S0024-G-TJV.cor | 6807.0 | 1592946.7 | 511165.6 | 16038 | 1.64041666667 | 15734 |
| 014043 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:07pm | Sensor | 1797-S0024-G-TJV.cor | 6806.9 | 1592944.2 | 511162.6 | 16040 | 1.64041666667 | 14043 |
| 015390 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:08pm | Sensor | 1797-S0024-G-TJV.cor | 6806.8 | 1592941.7 | 511159.2 | 16042 | 1.64041666667 | 15390 |
| 015427 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:09pm | Sensor | 1797-S0024-G-TJV.cor | 6806.8 | 1592939.2 | 511156.3 | 16044 | 1.64041666667 | 15427 |
| 014147 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:10pm | Sensor | 1797-S0024-G-TJV.cor | 6806.5 | 1592936.0 | 511153.1 | 16046 | 1.64041666667 | 14147 |
| 014933 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:11pm | Sensor | 1797-S0024-G-TJV.cor | 6806.6 | 1592933.4 | 511150.6 | 16048 | 1.64041666667 | 14933 |
| 013416 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:12pm | Sensor | 1797-S0024-G-TJV.cor | 6806.3 | 1592930.4 | 511147.1 | 16050 | 1.64041666667 | 13416 |
| 013524 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:13pm | Sensor | 1797-S0024-G-TJV.cor | 6805.9 | 1592928.2 | 511144.2 | 16052 | 1.64041666667 | 13524 |
| 012591 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:15pm | Sensor | 1797-S0024-G-TJV.cor | 6806.1 | 1592925.2 | 511140.8 | 16055 | 1.64041666667 | 12591 |
| 012927 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:15pm | Sensor | 1797-S0024-G-TJV.cor | 6806.1 | 1592923.0 | 511138.8 | 16056 | 1.64041666667 | 12927 |
| 013552 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:16pm | Sensor | 1797-S0024-G-TJV.cor | 6806.0 | 1592919.9 | 511136.0 | 16058 | 1.64041666667 | 13552 |
| 013528 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:17pm | Sensor | 1797-S0024-G-TJV.cor | 6806.1 | 1592917.4 | 511133.5 | 16060 | 1.64041666667 | 13528 |
| 012382 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:18pm | Sensor | 1797-S0024-G-TJV.cor | 6806.0 | 1592914.5 | 511130.6 | 16062 | 1.64041666667 | 12382 |
| 011405 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:19pm | Sensor | 1797-S0024-G-TJV.cor | 6806.0 | 1592912.2 | 511128.2 | 16064 | 1.64041666667 | 11405 |
| 011581 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:20pm | Sensor | 1797-S0024-G-TJV.cor | 6805.9 | 1592908.9 | 511125.0 | 16066 | 1.64041666667 | 11581 |
| 012105 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:21pm | Sensor | 1797-S0024-G-TJV.cor | 6806.1 | 1592906.2 | 511122.5 | 16068 | 1.64041666667 | 12105 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:22pm | Sensor | 1797-S0024-G-TJV.cor | 6805.8 | 1592903.4 | 511119.4 | 16070 | 1.64041666667 | 13766 |
| 013431 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:23pm | Sensor | 1797-S0024-G-TJV.cor | 6805.7 | 1592901.7 | 511116.7 | 16072 | 1.64041666667 | 13431 |
| 012778 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:24pm | Sensor | 1797-S0024-G-TJV.cor | 6805.7 | 1592899.7 | 511113.4 | 16074 | 1.64041666667 | 12778 |
| 014504 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:25pm | Sensor | 1797-S0024-G-TJV.cor | 6805.6 | 1592898.0 | 511110.4 | 16076 | 1.64041666667 | 14504 |
| 011816 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:26pm | Sensor | 1797-S0024-G-TJV.cor | 6805.7 | 1592895.8 | 511106.9 | 16078 | 1.64041666667 | 11816 |
| 011294 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:27pm | Sensor | 1797-S0024-G-TJV.cor | 6805.5 | 1592894.0 | 511103.8 | 16080 | 1.64041666667 | 11294 |
| 012963 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:28pm | Sensor | 1797-S0024-G-TJV.cor | 6805.5 | 1592891.9 | 511100.2 | 16082 | 1.64041666667 | 12963 |
| 011940 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:29pm | Sensor | 1797-S0024-G-TJV.cor | 6805.7 | 1592889.6 | 511097.2 | 16084 | 1.64041666667 | 11940 |
| 012315 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:30pm | Sensor | 1797-S0024-G-TJV.cor | 6805.5 | 1592886.9 | 511094.0 | 16086 | 1.64041666667 | 12315 |
| 012858 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:31pm | Sensor | 1797-S0024-G-TJV.cor | 6805.6 | 1592884.3 | 511091.2 | 16088 | 1.64041666667 | 12858 |
| 013174 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:32pm | Sensor | 1797-S0024-G-TJV.cor | 6805.5 | 1592881.6 | 511087.9 | 16090 | 1.64041666667 | 13174 |
| 013853 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:33pm | Sensor | 1797-S0024-G-TJV.cor | 6805.4 | 1592879.8 | 511085.2 | 16092 | 1.64041666667 | 13853 |
| 015673 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:34pm | Sensor | 1797-S0024-G-TJV.cor | 6805.5 | 1592877.6 | 511081.8 | 16094 | 1.64041666667 | 15673 |
| 013668 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:35pm | Sensor | 1797-S0024-G-TJV.cor | 6805.4 | 1592875.5 | 511078.7 | 16096 | 1.64041666667 | 13668 |
| 013107 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:36pm | Sensor | 1797-S0024-G-TJV.cor | 6805.5 | 1592873.4 | 511076.0 | 16098 | 1.64041666667 | 13107 |
| 014346 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:37pm | Sensor | 1797-S0024-G-TJV.cor | 6805.4 | 1592871.1 | 511073.0 | 16100 | 1.64041666667 | 14346 |
| 014446 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:38pm | Sensor | 1797-S0024-G-TJV.cor | 6805.4 | 1592869.1 | 511069.7 | 16102 | 1.64041666667 | 14446 |
| 013001 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:39pm | Sensor | 1797-S0024-G-TJV.cor | 6805.4 | 1592867.3 | 511066.6 | 16104 | 1.64041666667 | 13001 |
| 013270 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:40pm | Sensor | 1797-S0024-G-TJV.cor | 6805.3 | 1592865.6 | 511063.5 | 16106 | 1.64041666667 | 13270 |
| 011927 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:41pm | Sensor | 1797-S0024-G-TJV.cor | 6805.2 | 1592863.8 | 511060.6 | 16108 | 1.64041666667 | 11927 |
| 014711 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:42pm | Sensor | 1797-S0024-G-TJV.cor | 6804.9 | 1592861.6 | 511056.8 | 16110 | 1.64041666667 | 14711 |
| 013788 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:43pm | Sensor | 1797-S0024-G-TJV.cor | 6805.1 | 1592860.0 | 511053.9 | 16112 | 1.64041666667 | 13788 |
| 012177 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:44pm | Sensor | 1797-S0024-G-TJV.cor | 6804.8 | 1592858.1 | 511050.4 | 16114 | 1.64041666667 | 12177 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011984 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:45pm | Sensor | 1797-S0024-G-TJV.cor | 6804.7 | 1592855.9 | 511047.0 | 16116 | 1.64041666667 | 11984 |
| 012386 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:46pm | Sensor | 1797-S0024-G-TJV.cor | 6804.6 | 1592853.6 | 511043.6 | 16118 | 1.64041666667 | 12386 |
| 012846 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:47pm | Sensor | 1797-S0024-G-TJV.cor | 6804.6 | 1592851.8 | 511040.8 | 16120 | 1.64041666667 | 12846 |
| 011911 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:48pm | Sensor | 1797-S0024-G-TJV.cor | 6804.8 | 1592850.1 | 511037.4 | 16122 | 1.64041666667 | 11911 |
| 011977 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:49pm | Sensor | 1797-S0024-G-TJV.cor | 6804.6 | 1592848.7 | 511033.9 | 16124 | 1.64041666667 | 11977 |
| 011634 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:50pm | Sensor | 1797-S0024-G-TJV.cor | 6804.5 | 1592847.4 | 511030.1 | 16126 | 1.64041666667 | 11634 |
| 012808 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:51pm | Sensor | 1797-S0024-G-TJV.cor | 6804.4 | 1592846.7 | 511026.6 | 16128 | 1.64041666667 | 12808 |
| 013492 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:52pm | Sensor | 1797-S0024-G-TJV.cor | 6804.5 | 1592846.1 | 511022.8 | 16130 | 1.64041666667 | 13492 |
| 011023 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:53pm | Sensor | 1797-S0024-G-TJV.cor | 6804.6 | 1592845.5 | 511019.1 | 16132 | 1.64041666667 | 11023 |
| 010825 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:54pm | Sensor | 1797-S0024-G-TJV.cor | 6804.4 | 1592845.2 | 511015.0 | 16134 | 1.64041666667 | 10825 |
| 013236 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:55pm | Sensor | 1797-S0024-G-TJV.cor | 6804.6 | 1592845.1 | 511011.4 | 16136 | 1.64041666667 | 13236 |
| 013599 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:56pm | Sensor | 1797-S0024-G-TJV.cor | 6804.6 | 1592844.9 | 511007.4 | 16138 | 1.64041666667 | 13599 |
| 013029 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:57pm | Sensor | 1797-S0024-G-TJV.cor | 6804.5 | 1592844.8 | 511004.2 | 16140 | 1.64041666667 | 13029 |
| 012917 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:58pm | Sensor | 1797-S0024-G-TJV.cor | 6804.5 | 1592844.8 | 511000.1 | 16142 | 1.64041666667 | 12917 |
| 012889 | 0 | GeoXH 6000 | 08/18/2015 | 12:51:59pm | Sensor | 1797-S0024-G-TJV.cor | 6804.5 | 1592844.5 | 510996.8 | 16144 | 1.64041666667 | 12889 |
| 012312 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:00pm | Sensor | 1797-S0024-G-TJV.cor | 6804.6 | 1592843.7 | 510992.6 | 16146 | 1.64041666667 | 12312 |
| 013188 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:01pm | Sensor | 1797-S0024-G-TJV.cor | 6804.4 | 1592843.5 | 510989.1 | 16148 | 1.64041666667 | 13188 |
| 012897 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:02pm | Sensor | 1797-S0024-G-TJV.cor | 6804.3 | 1592842.9 | 510984.9 | 16150 | 1.64041666667 | 12897 |
| 011234 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:03pm | Sensor | 1797-S0024-G-TJV.cor | 6804.0 | 1592841.3 | 510981.6 | 16152 | 1.64041666667 | 11234 |
| 010878 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:04pm | Sensor | 1797-S0024-G-TJV.cor | 6804.2 | 1592838.4 | 510978.8 | 16154 | 1.64041666667 | 10878 |
| 012289 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:05pm | Sensor | 1797-S0024-G-TJV.cor | 6803.9 | 1592836.0 | 510976.5 | 16156 | 1.64041666667 | 12289 |
| 012282 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:06pm | Sensor | 1797-S0024-G-TJV.cor | 6804.0 | 1592833.5 | 510973.7 | 16158 | 1.64041666667 | 12282 |
| 012250 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:07pm | Sensor | 1797-S0024-G-TJV.cor | 6803.9 | 1592831.3 | 510970.7 | 16160 | 1.64041666667 | 12250 |
| 011912 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:08pm | Sensor | 1797-S0024-G-TJV.cor | 6803.7 | 1592829.1 | 510967.0 | 16162 | 1.64041666667 | 11912 |
| 011168 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:09pm | Sensor | 1797-S0024-G-TJV.cor | 6804.0 | 1592827.1 | 510964.1 | 16164 | 1.64041666667 | 11168 |
| 014102 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:10pm | Sensor | 1797-S0024-G-TJV.cor | 6803.8 | 1592824.7 | 510960.9 | 16166 | 1.64041666667 | 14102 |
| 012811 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:11pm | Sensor | 1797-S0024-G-TJV.cor | 6803.8 | 1592822.8 | 510958.1 | 16168 | 1.64041666667 | 12811 |
| 014141 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:12pm | Sensor | 1797-S0024-G-TJV.cor | 6803.6 | 1592820.7 | 510955.0 | 16170 | 1.64041666667 | 14141 |
| 012025 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:13pm | Sensor | 1797-S0024-G-TJV.cor | 6803.7 | 1592819.2 | 510952.1 | 16172 | 1.64041666667 | 12025 |
| 013836 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:14pm | Sensor | 1797-S0024-G-TJV.cor | 6803.6 | 1592817.4 | 510948.5 | 16174 | 1.64041666667 | 13836 |
| 012519 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:15pm | Sensor | 1797-S0024-G-TJV.cor | 6803.7 | 1592816.3 | 510945.3 | 16176 | 1.64041666667 | 12519 |
| 012909 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:16pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592815.6 | 510941.1 | 16178 | 1.64041666667 | 12909 |
| 013997 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:17pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592814.6 | 510937.6 | 16180 | 1.64041666667 | 13997 |
| 013099 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:18pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592813.4 | 510933.2 | 16182 | 1.64041666667 | 13099 |
| 012004 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:19pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592812.4 | 510930.0 | 16184 | 1.64041666667 | 12004 |
| 012481 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:20pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592810.7 | 510926.3 | 16186 | 1.64041666667 | 12481 |
| 012420 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:21pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592808.9 | 510923.9 | 16188 | 1.64041666667 | 12420 |
| 013365 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:22pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592806.6 | 510920.5 | 16190 | 1.64041666667 | 13365 |
| 013001 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:23pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592805.3 | 510917.6 | 16192 | 1.64041666667 | 13001 |
| 013570 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:24pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592804.0 | 510913.9 | 16194 | 1.64041666667 | 13570 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:25pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592803.2 | 510911.2 | 16196 | 1.64041666667 | 14072 |
| 014258 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592802.3 | 510907.4 | 16198 | 1.64041666667 | 14258 |
| 012864 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:27pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592801.7 | 510904.4 | 16200 | 1.64041666667 | 12864 |
| 012876 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:28pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592800.7 | 510900.7 | 16202 | 1.64041666667 | 12876 |
| 012219 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:29pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592800.0 | 510896.7 | 16204 | 1.64041666667 | 12219 |
| 011964 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592798.8 | 510892.4 | 16206 | 1.64041666667 | 11964 |
| 012051 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592797.5 | 510888.8 | 16208 | 1.64041666667 | 12051 |
| 011622 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592795.4 | 510885.0 | 16210 | 1.64041666667 | 11622 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011125 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592793.5 | 510881.7 | 16212 | 1.64041666667 | 11125 |
| 012081 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592791.2 | 510878.4 | 16214 | 1.64041666667 | 12081 |
| 011570 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592789.0 | 510875.6 | 16216 | 1.64041666667 | 11570 |
| 012882 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592787.0 | 510872.5 | 16218 | 1.64041666667 | 12882 |
| 012670 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592785.3 | 510869.8 | 16220 | 1.64041666667 | 12670 |
| 011867 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592783.4 | 510866.8 | 16222 | 1.64041666667 | 11867 |
| 012146 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592782.0 | 510863.5 | 16224 | 1.64041666667 | 12146 |
| 011946 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592781.2 | 510859.8 | 16226 | 1.64041666667 | 11946 |
| 011686 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592780.0 | 510856.9 | 16228 | 1.64041666667 | 11686 |
| 012611 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592778.6 | 510854.7 | 16230 | 1.64041666667 | 12611 |
| 012663 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592778.5 | 510854.1 | 16232 | 1.64041666667 | 12663 |
| 013755 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592778.2 | 510854.1 | 16234 | 1.64041666667 | 13755 |
| 013188 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592778.2 | 510854.1 | 16236 | 1.64041666667 | 13188 |
| 011697 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592778.5 | 510854.3 | 16238 | 1.64041666667 | 11697 |
| 011264 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592779.1 | 510854.3 | 16240 | 1.64041666667 | 11264 |
| 011696 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592779.3 | 510854.2 | 16242 | 1.64041666667 | 11696 |
| 012584 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592779.2 | 510854.1 | 16244 | 1.64041666667 | 12584 |
| 011006 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592779.1 | 510853.9 | 16246 | 1.64041666667 | 11006 |
| 011661 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592779.1 | 510853.9 | 16248 | 1.64041666667 | 11661 |
| 012755 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592779.2 | 510853.9 | 16250 | 1.64041666667 | 12755 |
| 013358 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592779.2 | 510854.0 | 16252 | 1.64041666667 | 13358 |
| 011469 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592779.2 | 510854.0 | 16254 | 1.64041666667 | 11469 |
| 011657 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592779.3 | 510854.1 | 16256 | 1.64041666667 | 11657 |
| 012094 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592779.2 | 510854.0 | 16258 | 1.64041666667 | 12094 |
| 011903 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592779.2 | 510854.0 | 16260 | 1.64041666667 | 11903 |
| 013776 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592779.2 | 510854.0 | 16262 | 1.64041666667 | 13776 |
| 012174 | 0 | GeoXH 6000 | 08/18/2015 | 12:52:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592779.2 | 510853.8 | 16264 | 1.64041666667 | 12174 |
| 011713 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592778.7 | 510853.2 | 16266 | 1.64041666667 | 11713 |
| 010968 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592777.6 | 510851.3 | 16268 | 1.64041666667 | 10968 |
| 012102 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592776.2 | 510848.3 | 16270 | 1.64041666667 | 12102 |
| 011785 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592775.4 | 510845.3 | 16272 | 1.64041666667 | 11785 |
| 013056 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592774.6 | 510842.0 | 16274 | 1.64041666667 | 13056 |
| 013374 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592773.3 | 510839.1 | 16276 | 1.64041666667 | 13374 |
| 012523 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592771.6 | 510835.7 | 16278 | 1.64041666667 | 12523 |
| 012431 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592770.2 | 510832.9 | 16280 | 1.64041666667 | 12431 |
| 011417 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592767.9 | 510829.9 | 16282 | 1.64041666667 | 11417 |
| 012844 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592766.1 | 510827.3 | 16284 | 1.64041666667 | 12844 |
| 011341 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592764.2 | 510823.9 | 16286 | 1.64041666667 | 11341 |
| 011265 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592762.8 | 510821.2 | 16288 | 1.64041666667 | 11265 |
| 011066 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592761.0 | 510817.9 | 16290 | 1.64041666667 | 11066 |
| 011346 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592760.0 | 510815.3 | 16292 | 1.64041666667 | 11346 |
| 012916 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592759.7 | 510811.3 | 16294 | 1.64041666667 | 12916 |
| 011989 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592760.1 | 510808.6 | 16296 | 1.64041666667 | 11989 |
| 012837 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592761.0 | 510804.6 | 16298 | 1.64041666667 | 12837 |
| 014129 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592762.3 | 510801.1 | 16300 | 1.64041666667 | 14129 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592763.9 | 510797.2 | 16302 | 1.64041666667 | 13132 |
| 013003 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592765.6 | 510795.0 | 16304 | 1.64041666667 | 13003 |
| 015970 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:20pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592767.6 | 510791.4 | 16306 | 1.64041666667 | 15970 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:21pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592768.8 | 510788.5 | 16308 | 1.64041666667 | 13742 |
| 013635 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:22pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592770.5 | 510784.7 | 16310 | 1.64041666667 | 13635 |
| 013308 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:23pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592771.9 | 510782.1 | 16312 | 1.64041666667 | 13308 |
| 013857 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592773.9 | 510778.4 | 16314 | 1.64041666667 | 13857 |
| 015194 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592775.2 | 510775.3 | 16316 | 1.64041666667 | 15194 |
| 014028 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:26pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592777.1 | 510772.2 | 16318 | 1.64041666667 | 14028 |
| 013167 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:27pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592778.0 | 510771.1 | 16320 | 1.64041666667 | 13167 |
| 014241 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:28pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592778.2 | 510770.6 | 16322 | 1.64041666667 | 14241 |
| 013700 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:29pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592778.1 | 510770.5 | 16324 | 1.64041666667 | 13700 |
| 012635 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:30pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592778.3 | 510770.4 | 16326 | 1.64041666667 | 12635 |
| 014018 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:31pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592778.7 | 510770.1 | 16328 | 1.64041666667 | 14018 |
| 014784 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:32pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592780.1 | 510769.3 | 16330 | 1.64041666667 | 14784 |
| 014916 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:33pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592782.0 | 510767.8 | 16332 | 1.64041666667 | 14916 |
| 014799 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:34pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592784.4 | 510766.8 | 16334 | 1.64041666667 | 14799 |
| 013059 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:35pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592786.6 | 510766.7 | 16336 | 1.64041666667 | 13059 |
| 012865 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:36pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592789.2 | 510767.6 | 16338 | 1.64041666667 | 12865 |
| 013986 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:37pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592790.7 | 510769.8 | 16340 | 1.64041666667 | 13986 |
| 013306 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:38pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592792.6 | 510771.7 | 16342 | 1.64041666667 | 13306 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592794.0 | 510773.6 | 16344 | 1.64041666667 | 13736 |
| 014894 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592796.3 | 510776.1 | 16346 | 1.64041666667 | 14894 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592798.6 | 510777.5 | 16348 | 1.64041666667 | 13953 |
| 012488 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592801.1 | 510779.3 | 16350 | 1.64041666667 | 12488 |
| 012272 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592804.0 | 510780.1 | 16352 | 1.64041666667 | 12272 |
| 012758 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592806.2 | 510781.3 | 16354 | 1.64041666667 | 12758 |
| 012219 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592808.7 | 510782.3 | 16356 | 1.64041666667 | 12219 |
| 013165 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592811.2 | 510784.1 | 16358 | 1.64041666667 | 13165 |
| 013941 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592813.6 | 510786.2 | 16360 | 1.64041666667 | 13941 |
| 014765 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592815.9 | 510787.7 | 16362 | 1.64041666667 | 14765 |
| 015181 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592817.5 | 510789.5 | 16364 | 1.64041666667 | 15181 |
| 015585 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592819.6 | 510790.9 | 16366 | 1.64041666667 | 15585 |
| 013106 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592821.5 | 510792.7 | 16368 | 1.64041666667 | 13106 |
| 012606 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592823.8 | 510794.8 | 16370 | 1.64041666667 | 12606 |
| 012841 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592826.1 | 510796.3 | 16372 | 1.64041666667 | 12841 |
| 014640 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592828.3 | 510798.1 | 16374 | 1.64041666667 | 14640 |
| 012870 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592830.1 | 510799.1 | 16376 | 1.64041666667 | 12870 |
| 013447 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592832.2 | 510801.0 | 16378 | 1.64041666667 | 13447 |
| 012782 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:57pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592834.4 | 510801.5 | 16380 | 1.64041666667 | 12782 |
| 013335 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:58pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592836.0 | 510802.4 | 16382 | 1.64041666667 | 13335 |
| 012903 | 0 | GeoXH 6000 | 08/18/2015 | 12:53:59pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592835.9 | 510802.2 | 16384 | 1.64041666667 | 12903 |
| 012196 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592836.1 | 510801.6 | 16386 | 1.64041666667 | 12196 |
| 011809 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:01pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592836.0 | 510801.8 | 16388 | 1.64041666667 | 11809 |
| 011922 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:02pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592835.7 | 510801.8 | 16390 | 1.64041666667 | 11922 |
| 012130 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:03pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592837.2 | 510800.7 | 16392 | 1.64041666667 | 12130 |
| 012332 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:04pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592838.5 | 510798.3 | 16394 | 1.64041666667 | 12332 |
| 012653 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:05pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592838.9 | 510798.5 | 16396 | 1.64041666667 | 12653 |
| 011863 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:06pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592838.9 | 510798.7 | 16398 | 1.64041666667 | 11863 |
| 011846 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:07pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592838.8 | 510798.2 | 16400 | 1.64041666667 | 11846 |
| 012261 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:08pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592839.9 | 510796.6 | 16402 | 1.64041666667 | 12261 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014045 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:09pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.0 | 510794.0 | 16404 | 1.64041666667 | 14045 |
| 014041 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:10pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.4 | 510793.2 | 16406 | 1.64041666667 | 14041 |
| 014100 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:11pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.6 | 510793.2 | 16408 | 1.64041666667 | 14100 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:12pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.7 | 510793.3 | 16410 | 1.64041666667 | 14655 |
| 014943 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:13pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.7 | 510793.3 | 16412 | 1.64041666667 | 14943 |
| 014026 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:14pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.7 | 510793.3 | 16414 | 1.64041666667 | 14026 |
| 014786 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:15pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.8 | 510793.4 | 16416 | 1.64041666667 | 14786 |
| 015126 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:16pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.8 | 510793.3 | 16418 | 1.64041666667 | 15126 |
| 013621 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:17pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592842.0 | 510793.2 | 16420 | 1.64041666667 | 13621 |
| 014625 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592842.7 | 510791.8 | 16422 | 1.64041666667 | 14625 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592843.2 | 510792.8 | 16424 | 1.64041666667 | 14516 |
| 013739 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592843.3 | 510793.1 | 16426 | 1.64041666667 | 13739 |
| 014715 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592843.4 | 510793.1 | 16428 | 1.64041666667 | 14715 |
| 013578 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592843.0 | 510794.1 | 16430 | 1.64041666667 | 13578 |
| 013804 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:23pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592842.9 | 510794.2 | 16432 | 1.64041666667 | 13804 |
| 014581 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:24pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592842.4 | 510794.6 | 16434 | 1.64041666667 | 14581 |
| 013035 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:25pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592841.7 | 510795.3 | 16436 | 1.64041666667 | 13035 |
| 012888 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592841.6 | 510794.8 | 16438 | 1.64041666667 | 12888 |
| 014472 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592841.8 | 510794.5 | 16440 | 1.64041666667 | 14472 |
| 012408 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:28pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592841.4 | 510794.9 | 16442 | 1.64041666667 | 12408 |
| 012492 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:29pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592840.5 | 510796.0 | 16444 | 1.64041666667 | 12492 |
| 013593 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:30pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592839.3 | 510797.9 | 16446 | 1.64041666667 | 13593 |
| 013328 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:31pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592838.5 | 510799.2 | 16448 | 1.64041666667 | 13328 |
| 015062 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:32pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592837.9 | 510799.5 | 16450 | 1.64041666667 | 15062 |
| 013155 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:33pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592837.4 | 510798.6 | 16452 | 1.64041666667 | 13155 |
| 016338 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:34pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592836.2 | 510796.7 | 16454 | 1.64041666667 | 16338 |
| 014164 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:35pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592834.3 | 510794.9 | 16456 | 1.64041666667 | 14164 |
| 013801 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:36pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592832.2 | 510792.9 | 16458 | 1.64041666667 | 13801 |
| 015390 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:37pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592830.1 | 510791.9 | 16460 | 1.64041666667 | 15390 |
| 014677 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:38pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592828.3 | 510790.0 | 16462 | 1.64041666667 | 14677 |
| 013689 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592826.6 | 510787.9 | 16464 | 1.64041666667 | 13689 |
| 013622 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592825.0 | 510785.3 | 16466 | 1.64041666667 | 13622 |
| 013425 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592823.3 | 510783.1 | 16468 | 1.64041666667 | 13425 |
| 013076 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592820.7 | 510781.4 | 16470 | 1.64041666667 | 13076 |
| 012389 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592819.2 | 510779.7 | 16472 | 1.64041666667 | 12389 |
| 012787 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592816.8 | 510777.9 | 16474 | 1.64041666667 | 12787 |
| 012196 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592815.2 | 510776.0 | 16476 | 1.64041666667 | 12196 |
| 011929 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592813.8 | 510773.9 | 16478 | 1.64041666667 | 11929 |
| 013092 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592812.4 | 510772.4 | 16480 | 1.64041666667 | 13092 |
| 013893 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592810.8 | 510770.4 | 16482 | 1.64041666667 | 13893 |
| 014843 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592809.0 | 510769.3 | 16484 | 1.64041666667 | 14843 |
| 014090 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592806.6 | 510768.0 | 16486 | 1.64041666667 | 14090 |
| 013512 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592804.1 | 510767.7 | 16488 | 1.64041666667 | 13512 |
| 013878 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592801.8 | 510766.9 | 16490 | 1.64041666667 | 13878 |
| 014959 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592799.4 | 510766.5 | 16492 | 1.64041666667 | 14959 |
| 014359 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592796.7 | 510765.6 | 16494 | 1.64041666667 | 14359 |
| 013370 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592794.3 | 510765.0 | 16496 | 1.64041666667 | 13370 |
| 013392 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592791.5 | 510764.0 | 16498 | 1.64041666667 | 13392 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014418 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592789.1 | 510762.7 | 16500 | 1.64041666667 | 14418 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592786.4 | 510761.8 | 16502 | 1.64041666667 | 14314 |
| 015248 | 0 | GeoXH 6000 | 08/18/2015 | 12:54:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592783.8 | 510760.5 | 16504 | 1.64041666667 | 15248 |
| 014792 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592781.2 | 510759.9 | 16506 | 1.64041666667 | 14792 |
| 015518 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592778.9 | 510759.6 | 16508 | 1.64041666667 | 15518 |
| 014409 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592776.3 | 510759.0 | 16510 | 1.64041666667 | 14409 |
| 013772 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592773.9 | 510758.8 | 16512 | 1.64041666667 | 13772 |
| 013613 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592771.6 | 510758.2 | 16514 | 1.64041666667 | 13613 |
| 014293 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592769.3 | 510758.1 | 16516 | 1.64041666667 | 14293 |
| 015453 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592766.9 | 510757.2 | 16518 | 1.64041666667 | 15453 |
| 016133 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592764.4 | 510757.1 | 16520 | 1.64041666667 | 16133 |
| 012943 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592762.0 | 510756.3 | 16522 | 1.64041666667 | 12943 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592759.5 | 510755.9 | 16524 | 1.64041666667 | 13736 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592757.1 | 510755.1 | 16526 | 1.64041666667 | 13094 |
| 014193 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592754.7 | 510754.0 | 16528 | 1.64041666667 | 14193 |
| 013868 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592751.9 | 510753.4 | 16530 | 1.64041666667 | 13868 |
| 014957 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592750.2 | 510752.6 | 16532 | 1.64041666667 | 14957 |
| 013669 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592747.8 | 510752.1 | 16534 | 1.64041666667 | 13669 |
| 014037 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592745.9 | 510751.0 | 16536 | 1.64041666667 | 14037 |
| 013889 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592743.3 | 510750.4 | 16538 | 1.64041666667 | 13889 |
| 015382 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592741.2 | 510749.6 | 16540 | 1.64041666667 | 15382 |
| 016385 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592738.8 | 510748.9 | 16542 | 1.64041666667 | 16385 |
| 015136 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592736.5 | 510748.1 | 16544 | 1.64041666667 | 15136 |
| 014404 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592733.7 | 510747.4 | 16546 | 1.64041666667 | 14404 |
| 013951 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592731.2 | 510747.0 | 16548 | 1.64041666667 | 13951 |
| 014077 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592728.9 | 510746.2 | 16550 | 1.64041666667 | 14077 |
| 014139 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592727.6 | 510746.3 | 16552 | 1.64041666667 | 14139 |
| 014905 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592727.2 | 510746.6 | 16554 | 1.64041666667 | 14905 |
| 012816 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592727.2 | 510746.4 | 16556 | 1.64041666667 | 12816 |
| 013374 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592727.5 | 510746.2 | 16558 | 1.64041666667 | 13374 |
| 012943 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592727.3 | 510746.3 | 16560 | 1.64041666667 | 12943 |
| 013496 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592727.3 | 510746.7 | 16562 | 1.64041666667 | 13496 |
| 013754 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592727.3 | 510746.7 | 16564 | 1.64041666667 | 13754 |
| 014568 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592727.6 | 510746.7 | 16566 | 1.64041666667 | 14568 |
| 014442 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592727.6 | 510746.2 | 16568 | 1.64041666667 | 14442 |
| 013510 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592727.5 | 510743.1 | 16570 | 1.64041666667 | 13510 |
| 012557 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592727.2 | 510740.4 | 16572 | 1.64041666667 | 12557 |
| 016279 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592727.3 | 510739.9 | 16574 | 1.64041666667 | 16279 |
| 017359 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592728.0 | 510738.1 | 16576 | 1.64041666667 | 17359 |
| 015350 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592728.3 | 510735.2 | 16578 | 1.64041666667 | 15350 |
| 013167 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592728.3 | 510734.7 | 16580 | 1.64041666667 | 13167 |
| 013942 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592728.3 | 510734.6 | 16582 | 1.64041666667 | 13942 |
| 013865 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592728.3 | 510734.6 | 16584 | 1.64041666667 | 13865 |
| 015046 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592728.4 | 510734.6 | 16586 | 1.64041666667 | 15046 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592728.3 | 510734.6 | 16588 | 1.64041666667 | 13301 |
| 015835 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592728.4 | 510734.6 | 16590 | 1.64041666667 | 15835 |
| 015059 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592728.5 | 510734.7 | 16592 | 1.64041666667 | 15059 |
| 013214 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:44pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592728.7 | 510733.2 | 16594 | 1.64041666667 | 13214 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:45pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592728.6 | 510732.5 | 16596 | 1.64041666667 | 13953 |
| 013388 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:46pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592728.9 | 510733.6 | 16598 | 1.64041666667 | 13388 |
| 012227 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:47pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592729.0 | 510733.8 | 16600 | 1.64041666667 | 12227 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:48pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592729.0 | 510733.8 | 16602 | 1.64041666667 | 13526 |
| 013881 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:49pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592729.2 | 510733.6 | 16604 | 1.64041666667 | 13881 |
| 015290 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:50pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592728.8 | 510735.0 | 16606 | 1.64041666667 | 15290 |
| 013842 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:51pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592728.1 | 510735.9 | 16608 | 1.64041666667 | 13842 |
| 013030 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592727.5 | 510735.9 | 16610 | 1.64041666667 | 13030 |
| 013307 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592727.1 | 510737.4 | 16612 | 1.64041666667 | 13307 |
| 013856 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592726.8 | 510739.1 | 16614 | 1.64041666667 | 13856 |
| 013724 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592727.0 | 510740.3 | 16616 | 1.64041666667 | 13724 |
| 013871 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592727.5 | 510740.7 | 16618 | 1.64041666667 | 13871 |
| 014207 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592727.5 | 510741.0 | 16620 | 1.64041666667 | 14207 |
| 014981 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592729.5 | 510741.7 | 16622 | 1.64041666667 | 14981 |
| 014755 | 0 | GeoXH 6000 | 08/18/2015 | 12:55:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592732.0 | 510742.2 | 16624 | 1.64041666667 | 14755 |
| 013589 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592733.3 | 510742.8 | 16626 | 1.64041666667 | 13589 |
| 013147 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592735.5 | 510743.3 | 16628 | 1.64041666667 | 13147 |
| 015706 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:02pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592739.8 | 510745.5 | 16630 | 1.64041666667 | 15706 |
| 014036 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:03pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592741.8 | 510746.3 | 16632 | 1.64041666667 | 14036 |
| 014939 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:04pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592744.9 | 510747.2 | 16634 | 1.64041666667 | 14939 |
| 014145 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:05pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592747.8 | 510748.9 | 16636 | 1.64041666667 | 14145 |
| 014546 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:06pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592750.7 | 510750.2 | 16638 | 1.64041666667 | 14546 |
| 015186 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:07pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592753.3 | 510751.5 | 16640 | 1.64041666667 | 15186 |
| 015046 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:08pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592756.4 | 510752.7 | 16642 | 1.64041666667 | 15046 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:09pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592759.1 | 510753.4 | 16644 | 1.64041666667 | 14111 |
| 014058 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:10pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592762.0 | 510755.1 | 16646 | 1.64041666667 | 14058 |
| 015724 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:11pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592764.6 | 510756.3 | 16648 | 1.64041666667 | 15724 |
| 015991 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:12pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592767.4 | 510758.0 | 16650 | 1.64041666667 | 15991 |
| 014107 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:13pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592770.4 | 510759.3 | 16652 | 1.64041666667 | 14107 |
| 016037 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:14pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592773.6 | 510760.5 | 16654 | 1.64041666667 | 16037 |
| 013729 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592775.7 | 510761.6 | 16656 | 1.64041666667 | 13729 |
| 014862 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592778.7 | 510762.4 | 16658 | 1.64041666667 | 14862 |
| 014695 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592781.1 | 510763.8 | 16660 | 1.64041666667 | 14695 |
| 015554 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592784.5 | 510765.9 | 16662 | 1.64041666667 | 15554 |
| 015738 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592787.5 | 510766.6 | 16664 | 1.64041666667 | 15738 |
| 014284 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592790.6 | 510767.7 | 16666 | 1.64041666667 | 14284 |
| 012511 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:21pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592793.7 | 510768.7 | 16668 | 1.64041666667 | 12511 |
| 013087 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:22pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592796.9 | 510769.8 | 16670 | 1.64041666667 | 13087 |
| 012572 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592799.0 | 510771.3 | 16672 | 1.64041666667 | 12572 |
| 013043 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592802.3 | 510772.5 | 16674 | 1.64041666667 | 13043 |
| 011210 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592804.6 | 510773.7 | 16676 | 1.64041666667 | 11210 |
| 012132 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592807.3 | 510774.7 | 16678 | 1.64041666667 | 12132 |
| 013773 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592810.0 | 510775.5 | 16680 | 1.64041666667 | 13773 |
| 013673 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:28pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592812.9 | 510777.4 | 16682 | 1.64041666667 | 13673 |
| 012478 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592815.3 | 510778.2 | 16684 | 1.64041666667 | 12478 |
| 012959 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:30pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592818.1 | 510780.1 | 16686 | 1.64041666667 | 12959 |
| 013440 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592820.6 | 510781.3 | 16688 | 1.64041666667 | 13440 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592823.8 | 510782.5 | 16690 | 1.64041666667 | 14550 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012787 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592826.6 | 510783.8 | 16692 | 1.64041666667 | 12787 |
| 013006 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592829.6 | 510784.7 | 16694 | 1.64041666667 | 13006 |
| 013331 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:35pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592832.3 | 510786.2 | 16696 | 1.64041666667 | 13331 |
| 013533 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:36pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592835.2 | 510787.7 | 16698 | 1.64041666667 | 13533 |
| 013373 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:37pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592837.6 | 510789.1 | 16700 | 1.64041666667 | 13373 |
| 013273 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:38pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592839.9 | 510791.1 | 16702 | 1.64041666667 | 13273 |
| 013128 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592842.0 | 510791.7 | 16704 | 1.64041666667 | 13128 |
| 013212 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:40pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592844.2 | 510792.8 | 16706 | 1.64041666667 | 13212 |
| 015453 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:41pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592844.1 | 510793.6 | 16708 | 1.64041666667 | 15453 |
| 015083 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592845.4 | 510791.9 | 16710 | 1.64041666667 | 15083 |
| 015920 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:43pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592847.4 | 510790.5 | 16712 | 1.64041666667 | 15920 |
| 015890 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:44pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592848.0 | 510788.9 | 16714 | 1.64041666667 | 15890 |
| 014562 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592847.5 | 510787.9 | 16716 | 1.64041666667 | 14562 |
| 014590 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592849.3 | 510786.0 | 16718 | 1.64041666667 | 14590 |
| 014657 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:47pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592851.5 | 510783.1 | 16720 | 1.64041666667 | 14657 |
| 015424 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:48pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592852.4 | 510781.9 | 16722 | 1.64041666667 | 15424 |
| 014386 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:49pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592852.6 | 510782.2 | 16724 | 1.64041666667 | 14386 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:50pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592852.7 | 510782.4 | 16726 | 1.64041666667 | 14426 |
| 014706 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:51pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592852.7 | 510782.4 | 16728 | 1.64041666667 | 14706 |
| 017446 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:52pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592852.2 | 510783.7 | 16730 | 1.64041666667 | 17446 |
| 015671 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:53pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592851.6 | 510784.5 | 16732 | 1.64041666667 | 15671 |
| 014058 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:54pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592852.4 | 510784.4 | 16734 | 1.64041666667 | 14058 |
| 014554 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:55pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592853.2 | 510782.5 | 16736 | 1.64041666667 | 14554 |
| 013718 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:56pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592855.6 | 510780.3 | 16738 | 1.64041666667 | 13718 |
| 014139 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:57pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592856.7 | 510777.1 | 16740 | 1.64041666667 | 14139 |
| 012835 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:58pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592857.0 | 510773.9 | 16742 | 1.64041666667 | 12835 |
| 013798 | 0 | GeoXH 6000 | 08/18/2015 | 12:56:59pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592858.1 | 510771.9 | 16744 | 1.64041666667 | 13798 |
| 013679 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:00pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592859.0 | 510768.6 | 16746 | 1.64041666667 | 13679 |
| 013020 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:01pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592859.4 | 510765.9 | 16748 | 1.64041666667 | 13020 |
| 014985 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:02pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592860.7 | 510762.5 | 16750 | 1.64041666667 | 14985 |
| 014096 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:03pm | Sensor | 1797-S0024-G-TJV.cor | 6800.0 | 1592861.4 | 510759.9 | 16752 | 1.64041666667 | 14096 |
| 013844 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:04pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592862.6 | 510756.7 | 16754 | 1.64041666667 | 13844 |
| 013991 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:05pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592864.1 | 510753.6 | 16756 | 1.64041666667 | 13991 |
| 013937 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:06pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592864.7 | 510750.4 | 16758 | 1.64041666667 | 13937 |
| 013234 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592865.6 | 510747.7 | 16760 | 1.64041666667 | 13234 |
| 015608 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:08pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592866.8 | 510744.0 | 16762 | 1.64041666667 | 15608 |
| 013802 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:09pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592868.0 | 510741.0 | 16764 | 1.64041666667 | 13802 |
| 014730 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:10pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592869.4 | 510738.1 | 16766 | 1.64041666667 | 14730 |
| 012652 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:11pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592870.3 | 510735.1 | 16768 | 1.64041666667 | 12652 |
| 011833 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:12pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592871.5 | 510731.6 | 16770 | 1.64041666667 | 11833 |
| 012198 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:13pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592873.3 | 510728.7 | 16772 | 1.64041666667 | 12198 |
| 012769 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:14pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592874.5 | 510725.7 | 16774 | 1.64041666667 | 12769 |
| 014952 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592875.7 | 510722.8 | 16776 | 1.64041666667 | 14952 |
| 014748 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592876.5 | 510719.5 | 16778 | 1.64041666667 | 14748 |
| 014877 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592877.5 | 510716.5 | 16780 | 1.64041666667 | 14877 |
| 013799 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592879.0 | 510713.5 | 16782 | 1.64041666667 | 13799 |
| 013890 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592879.6 | 510711.0 | 16784 | 1.64041666667 | 13890 |
| 013762 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592881.1 | 510708.3 | 16786 | 1.64041666667 | 13762 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012350 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592882.5 | 510705.7 | 16788 | 1.64041666667 | 12350 |
| 015567 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592883.1 | 510702.2 | 16790 | 1.64041666667 | 15567 |
| 014782 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592884.2 | 510699.5 | 16792 | 1.64041666667 | 14782 |
| 013025 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592884.8 | 510696.3 | 16794 | 1.64041666667 | 13025 |
| 012106 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:25pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592885.5 | 510693.9 | 16796 | 1.64041666667 | 12106 |
| 014036 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592885.2 | 510693.3 | 16798 | 1.64041666667 | 14036 |
| 014219 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592884.7 | 510693.2 | 16800 | 1.64041666667 | 14219 |
| 014355 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:28pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592885.1 | 510693.4 | 16802 | 1.64041666667 | 14355 |
| 014928 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592884.1 | 510691.6 | 16804 | 1.64041666667 | 14928 |
| 014622 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:30pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592881.8 | 510689.5 | 16806 | 1.64041666667 | 14622 |
| 015535 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:31pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592880.9 | 510689.0 | 16808 | 1.64041666667 | 15535 |
| 013814 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592880.8 | 510688.9 | 16810 | 1.64041666667 | 13814 |
| 014913 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592880.6 | 510688.8 | 16812 | 1.64041666667 | 14913 |
| 014978 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:34pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592880.3 | 510688.3 | 16814 | 1.64041666667 | 14978 |
| 015144 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:35pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592878.8 | 510686.8 | 16816 | 1.64041666667 | 15144 |
| 014616 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:36pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592876.6 | 510684.6 | 16818 | 1.64041666667 | 14616 |
| 014454 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:37pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592876.3 | 510684.3 | 16820 | 1.64041666667 | 14454 |
| 014503 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:38pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592876.4 | 510684.3 | 16822 | 1.64041666667 | 14503 |
| 015836 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:39pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592876.3 | 510684.3 | 16824 | 1.64041666667 | 15836 |
| 015179 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592876.4 | 510684.3 | 16826 | 1.64041666667 | 15179 |
| 016544 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:41pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592875.7 | 510684.2 | 16828 | 1.64041666667 | 16544 |
| 013826 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:42pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592873.7 | 510683.6 | 16830 | 1.64041666667 | 13826 |
| 013056 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:43pm | Sensor | 1797-S0024-G-TJV.cor | 6799.0 | 1592875.6 | 510684.6 | 16832 | 1.64041666667 | 13056 |
| 015264 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:44pm | Sensor | 1797-S0024-G-TJV.cor | 6797.3 | 1592877.7 | 510685.1 | 16834 | 1.64041666667 | 15264 |
| 014436 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:45pm | Sensor | 1797-S0024-G-TJV.cor | 6798.3 | 1592877.9 | 510684.6 | 16836 | 1.64041666667 | 14436 |
| 013959 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:46pm | Sensor | 1797-S0024-G-TJV.cor | 6798.0 | 1592877.9 | 510684.4 | 16838 | 1.64041666667 | 13959 |
| 015999 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:47pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592877.6 | 510684.1 | 16840 | 1.64041666667 | 15999 |
| 016990 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:48pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592876.9 | 510683.9 | 16842 | 1.64041666667 | 16990 |
| 015077 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:49pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592878.5 | 510685.4 | 16844 | 1.64041666667 | 15077 |
| 014419 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:50pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592878.9 | 510687.0 | 16846 | 1.64041666667 | 14419 |
| 014344 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:51pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592878.8 | 510689.5 | 16848 | 1.64041666667 | 14344 |
| 014386 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:52pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592878.7 | 510692.9 | 16850 | 1.64041666667 | 14386 |
| 014876 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:53pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592877.5 | 510695.4 | 16852 | 1.64041666667 | 14876 |
| 015839 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592876.6 | 510698.2 | 16854 | 1.64041666667 | 15839 |
| 015870 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592875.6 | 510701.2 | 16856 | 1.64041666667 | 15870 |
| 016447 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:56pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592874.2 | 510705.2 | 16858 | 1.64041666667 | 16447 |
| 015001 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:57pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592873.7 | 510708.2 | 16860 | 1.64041666667 | 15001 |
| 013890 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:58pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592872.8 | 510711.4 | 16862 | 1.64041666667 | 13890 |
| 014422 | 0 | GeoXH 6000 | 08/18/2015 | 12:57:59pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592873.2 | 510714.8 | 16864 | 1.64041666667 | 14422 |
| 014585 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:00pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592872.4 | 510718.4 | 16866 | 1.64041666667 | 14585 |
| 013666 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:01pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592870.8 | 510721.4 | 16868 | 1.64041666667 | 13666 |
| 014366 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:02pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592869.4 | 510724.6 | 16870 | 1.64041666667 | 14366 |
| 012471 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:03pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592868.2 | 510727.1 | 16872 | 1.64041666667 | 12471 |
| 012838 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:04pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592866.3 | 510730.6 | 16874 | 1.64041666667 | 12838 |
| 014129 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:05pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592865.6 | 510733.8 | 16876 | 1.64041666667 | 14129 |
| 013492 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:06pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592864.2 | 510737.0 | 16878 | 1.64041666667 | 13492 |
| 013753 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592863.2 | 510739.8 | 16880 | 1.64041666667 | 13753 |
| 016158 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592861.9 | 510743.8 | 16882 | 1.64041666667 | 16158 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015409 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592860.9 | 510746.5 | 16884 | 1.64041666667 | 15409 |
| 014412 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592860.2 | 510749.8 | 16886 | 1.64041666667 | 14412 |
| 013023 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592859.4 | 510752.6 | 16888 | 1.64041666667 | 13023 |
| 011985 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592857.7 | 510755.9 | 16890 | 1.64041666667 | 11985 |
| 014156 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592857.0 | 510758.8 | 16892 | 1.64041666667 | 14156 |
| 013469 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592855.9 | 510761.9 | 16894 | 1.64041666667 | 13469 |
| 013717 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592855.2 | 510764.7 | 16896 | 1.64041666667 | 13717 |
| 015729 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592854.4 | 510767.9 | 16898 | 1.64041666667 | 15729 |
| 013922 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592853.4 | 510770.6 | 16900 | 1.64041666667 | 13922 |
| 013740 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592852.4 | 510773.5 | 16902 | 1.64041666667 | 13740 |
| 012825 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592851.0 | 510776.0 | 16904 | 1.64041666667 | 12825 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592850.5 | 510778.8 | 16906 | 1.64041666667 | 14246 |
| 014121 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592850.3 | 510780.9 | 16908 | 1.64041666667 | 14121 |
| 013550 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592850.9 | 510782.2 | 16910 | 1.64041666667 | 13550 |
| 014395 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592851.5 | 510782.9 | 16912 | 1.64041666667 | 14395 |
| 014114 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592852.0 | 510783.5 | 16914 | 1.64041666667 | 14114 |
| 013668 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:25pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592852.2 | 510783.7 | 16916 | 1.64041666667 | 13668 |
| 014037 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592852.1 | 510783.7 | 16918 | 1.64041666667 | 14037 |
| 014549 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592852.0 | 510783.5 | 16920 | 1.64041666667 | 14549 |
| 014947 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592851.6 | 510783.3 | 16922 | 1.64041666667 | 14947 |
| 013696 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592851.4 | 510782.9 | 16924 | 1.64041666667 | 13696 |
| 013984 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:30pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592852.2 | 510782.3 | 16926 | 1.64041666667 | 13984 |
| 016066 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:31pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592852.4 | 510782.5 | 16928 | 1.64041666667 | 16066 |
| 015986 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592852.5 | 510782.5 | 16930 | 1.64041666667 | 15986 |
| 014376 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592852.5 | 510783.0 | 16932 | 1.64041666667 | 14376 |
| 013134 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:34pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592852.1 | 510783.6 | 16934 | 1.64041666667 | 13134 |
| 014983 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:35pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592852.9 | 510782.7 | 16936 | 1.64041666667 | 14983 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:36pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592855.2 | 510780.4 | 16938 | 1.64041666667 | 14426 |
| 013596 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:37pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592856.1 | 510778.6 | 16940 | 1.64041666667 | 13596 |
| 013209 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:38pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592855.8 | 510779.3 | 16942 | 1.64041666667 | 13209 |
| 015032 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:39pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592855.2 | 510781.5 | 16944 | 1.64041666667 | 15032 |
| 016058 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:40pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592854.3 | 510782.8 | 16946 | 1.64041666667 | 16058 |
| 015024 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:41pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592853.5 | 510783.2 | 16948 | 1.64041666667 | 15024 |
| 014466 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:42pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592852.4 | 510783.9 | 16950 | 1.64041666667 | 14466 |
| 014416 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:43pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592851.8 | 510783.9 | 16952 | 1.64041666667 | 14416 |
| 014344 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:44pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592850.1 | 510782.9 | 16954 | 1.64041666667 | 14344 |
| 012976 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:45pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592848.0 | 510783.0 | 16956 | 1.64041666667 | 12976 |
| 015214 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592844.4 | 510781.9 | 16958 | 1.64041666667 | 15214 |
| 015293 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592841.3 | 510781.1 | 16960 | 1.64041666667 | 15293 |
| 013843 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:48pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592837.9 | 510780.8 | 16962 | 1.64041666667 | 13843 |
| 012941 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:49pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592835.2 | 510779.8 | 16964 | 1.64041666667 | 12941 |
| 013165 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:50pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592832.5 | 510779.2 | 16966 | 1.64041666667 | 13165 |
| 014271 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:51pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592829.5 | 510778.8 | 16968 | 1.64041666667 | 14271 |
| 014877 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:52pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592825.7 | 510777.5 | 16970 | 1.64041666667 | 14877 |
| 014459 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:53pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592822.9 | 510777.0 | 16972 | 1.64041666667 | 14459 |
| 014295 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:54pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592820.2 | 510775.7 | 16974 | 1.64041666667 | 14295 |
| 014343 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:55pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592817.3 | 510774.3 | 16976 | 1.64041666667 | 14343 |
| 012075 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:56pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592813.1 | 510773.1 | 16978 | 1.64041666667 | 12075 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:57pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592810.9 | 510771.7 | 16980 | 1.64041666667 | 13518 |
| 012649 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:58pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592807.8 | 510770.3 | 16982 | 1.64041666667 | 12649 |
| 015072 | 0 | GeoXH 6000 | 08/18/2015 | 12:58:59pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592805.1 | 510768.7 | 16984 | 1.64041666667 | 15072 |
| 013488 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:00pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592802.0 | 510767.1 | 16986 | 1.64041666667 | 13488 |
| 013632 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592798.9 | 510766.0 | 16988 | 1.64041666667 | 13632 |
| 016338 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592795.6 | 510764.5 | 16990 | 1.64041666667 | 16338 |
| 015664 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592792.5 | 510762.9 | 16992 | 1.64041666667 | 15664 |
| 013396 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592788.9 | 510761.5 | 16994 | 1.64041666667 | 13396 |
| 014209 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592786.4 | 510760.1 | 16996 | 1.64041666667 | 14209 |
| 014712 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592783.3 | 510758.7 | 16998 | 1.64041666667 | 14712 |
| 013068 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592779.9 | 510757.5 | 17000 | 1.64041666667 | 13068 |
| 014637 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:08pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592777.1 | 510755.7 | 17002 | 1.64041666667 | 14637 |
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:09pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592774.7 | 510754.3 | 17004 | 1.64041666667 | 14819 |
| 014505 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:10pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592771.7 | 510752.6 | 17006 | 1.64041666667 | 14505 |
| 015656 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:11pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592768.9 | 510750.5 | 17008 | 1.64041666667 | 15656 |
| 014204 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:12pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592765.7 | 510749.1 | 17010 | 1.64041666667 | 14204 |
| 014861 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:13pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592762.8 | 510747.5 | 17012 | 1.64041666667 | 14861 |
| 014125 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:14pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592759.7 | 510746.3 | 17014 | 1.64041666667 | 14125 |
| 014331 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592756.8 | 510745.5 | 17016 | 1.64041666667 | 14331 |
| 014142 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592753.3 | 510743.9 | 17018 | 1.64041666667 | 14142 |
| 015655 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592750.6 | 510743.2 | 17020 | 1.64041666667 | 15655 |
| 015734 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592747.5 | 510742.0 | 17022 | 1.64041666667 | 15734 |
| 015633 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592744.8 | 510740.3 | 17024 | 1.64041666667 | 15633 |
| 014888 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592740.9 | 510738.7 | 17026 | 1.64041666667 | 14888 |
| 015512 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592738.6 | 510737.6 | 17028 | 1.64041666667 | 15512 |
| 014228 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592735.5 | 510736.4 | 17030 | 1.64041666667 | 14228 |
| 013547 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592732.9 | 510735.5 | 17032 | 1.64041666667 | 13547 |
| 013016 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:24pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592729.9 | 510734.0 | 17034 | 1.64041666667 | 13016 |
| 013814 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:25pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592730.0 | 510733.3 | 17036 | 1.64041666667 | 13814 |
| 013983 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592729.9 | 510731.8 | 17038 | 1.64041666667 | 13983 |
| 014775 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592730.8 | 510728.9 | 17040 | 1.64041666667 | 14775 |
| 013053 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592730.9 | 510727.6 | 17042 | 1.64041666667 | 13053 |
| 015083 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592731.1 | 510726.6 | 17044 | 1.64041666667 | 15083 |
| 016611 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592731.8 | 510726.6 | 17046 | 1.64041666667 | 16611 |
| 015822 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:31pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592734.1 | 510723.1 | 17048 | 1.64041666667 | 15822 |
| 015895 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592734.5 | 510719.7 | 17050 | 1.64041666667 | 15895 |
| 015374 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:33pm | Sensor | 1797-S0024-G-TJV.cor | 6799.4 | 1592734.6 | 510719.0 | 17052 | 1.64041666667 | 15374 |
| 013983 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:34pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592733.6 | 510721.0 | 17054 | 1.64041666667 | 13983 |
| 014265 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:35pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592732.2 | 510722.3 | 17056 | 1.64041666667 | 14265 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:36pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592731.8 | 510724.5 | 17058 | 1.64041666667 | 14456 |
| 011924 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:37pm | Sensor | 1797-S0024-G-TJV.cor | 6800.0 | 1592731.6 | 510726.2 | 17060 | 1.64041666667 | 11924 |
| 014561 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:38pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592731.1 | 510726.9 | 17062 | 1.64041666667 | 14561 |
| 013630 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:39pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592731.0 | 510727.1 | 17064 | 1.64041666667 | 13630 |
| 016457 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:40pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592729.9 | 510728.2 | 17066 | 1.64041666667 | 16457 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:41pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592729.8 | 510728.3 | 17068 | 1.64041666667 | 14314 |
| 014288 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:42pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592730.2 | 510728.5 | 17070 | 1.64041666667 | 14288 |
| 013502 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:43pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592730.7 | 510728.4 | 17072 | 1.64041666667 | 13502 |
| 014385 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:44pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592731.9 | 510729.1 | 17074 | 1.64041666667 | 14385 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:45pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592732.7 | 510729.1 | 17076 | 1.64041666667 | 14246 |
| 014451 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:46pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592733.0 | 510729.2 | 17078 | 1.64041666667 | 14451 |
| 013543 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:47pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592733.7 | 510729.3 | 17080 | 1.64041666667 | 13543 |
| 013525 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:48pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592735.0 | 510729.9 | 17082 | 1.64041666667 | 13525 |
| 013521 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:49pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592736.8 | 510730.0 | 17084 | 1.64041666667 | 13521 |
| 013700 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:50pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592739.7 | 510730.6 | 17086 | 1.64041666667 | 13700 |
| 015485 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:51pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592742.3 | 510730.6 | 17088 | 1.64041666667 | 15485 |
| 014941 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:52pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592744.7 | 510731.5 | 17090 | 1.64041666667 | 14941 |
| 014175 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592747.2 | 510732.1 | 17092 | 1.64041666667 | 14175 |
| 015603 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592749.9 | 510732.9 | 17094 | 1.64041666667 | 15603 |
| 014041 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:55pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592752.4 | 510734.4 | 17096 | 1.64041666667 | 14041 |
| 013710 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592755.7 | 510735.4 | 17098 | 1.64041666667 | 13710 |
| 014287 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592758.1 | 510736.5 | 17100 | 1.64041666667 | 14287 |
| 015032 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592761.5 | 510737.7 | 17102 | 1.64041666667 | 15032 |
| 016328 | 0 | GeoXH 6000 | 08/18/2015 | 12:59:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592764.5 | 510738.5 | 17104 | 1.64041666667 | 16328 |
| 015032 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592767.7 | 510739.8 | 17106 | 1.64041666667 | 15032 |
| 013508 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592770.3 | 510740.5 | 17108 | 1.64041666667 | 13508 |
| 014147 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592773.1 | 510741.9 | 17110 | 1.64041666667 | 14147 |
| 014636 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592776.1 | 510743.3 | 17112 | 1.64041666667 | 14636 |
| 013889 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592779.7 | 510744.7 | 17114 | 1.64041666667 | 13889 |
| 013462 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592782.2 | 510746.1 | 17116 | 1.64041666667 | 13462 |
| 013775 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592785.7 | 510747.5 | 17118 | 1.64041666667 | 13775 |
| 013613 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592788.2 | 510748.6 | 17120 | 1.64041666667 | 13613 |
| 012793 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592791.8 | 510750.5 | 17122 | 1.64041666667 | 12793 |
| 012258 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592794.4 | 510751.4 | 17124 | 1.64041666667 | 12258 |
| 011854 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592797.3 | 510753.5 | 17126 | 1.64041666667 | 11854 |
| 012773 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592799.7 | 510754.8 | 17128 | 1.64041666667 | 12773 |
| 012883 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:12pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592802.9 | 510756.4 | 17130 | 1.64041666667 | 12883 |
| 014861 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:13pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592805.7 | 510758.2 | 17132 | 1.64041666667 | 14861 |
| 014485 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592808.5 | 510759.2 | 17134 | 1.64041666667 | 14485 |
| 014061 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592810.8 | 510760.7 | 17136 | 1.64041666667 | 14061 |
| 012785 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592813.9 | 510761.3 | 17138 | 1.64041666667 | 12785 |
| 012586 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592816.6 | 510762.2 | 17140 | 1.64041666667 | 12586 |
| 012416 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592819.8 | 510763.1 | 17142 | 1.64041666667 | 12416 |
| 013754 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592823.2 | 510763.6 | 17144 | 1.64041666667 | 13754 |
| 013578 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592825.9 | 510765.0 | 17146 | 1.64041666667 | 13578 |
| 011734 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592828.3 | 510766.0 | 17148 | 1.64041666667 | 11734 |
| 013883 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592831.6 | 510767.2 | 17150 | 1.64041666667 | 13883 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592834.6 | 510768.6 | 17152 | 1.64041666667 | 14081 |
| 014465 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592838.3 | 510769.5 | 17154 | 1.64041666667 | 14465 |
| 012886 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592840.5 | 510770.8 | 17156 | 1.64041666667 | 12886 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592843.2 | 510772.2 | 17158 | 1.64041666667 | 14081 |
| 012580 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592845.8 | 510773.7 | 17160 | 1.64041666667 | 12580 |
| 012595 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592848.9 | 510775.3 | 17162 | 1.64041666667 | 12595 |
| 012628 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592851.9 | 510776.8 | 17164 | 1.64041666667 | 12628 |
| 013177 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:30pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592854.3 | 510778.4 | 17166 | 1.64041666667 | 13177 |
| 012504 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:31pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592855.2 | 510778.9 | 17168 | 1.64041666667 | 12504 |
| 013956 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592855.4 | 510778.9 | 17170 | 1.64041666667 | 13956 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015309 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592855.8 | 510778.9 | 17172 | 1.64041666667 | 15309 |
| 015017 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:34pm | Sensor | 1797-S0024-G-TJV.cor | 6803.8 | 1592856.0 | 510778.9 | 17174 | 1.64041666667 | 15017 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:35pm | Sensor | 1797-S0024-G-TJV.cor | 6804.2 | 1592857.2 | 510776.6 | 17176 | 1.64041666667 | 14314 |
| 014828 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:36pm | Sensor | 1797-S0024-G-TJV.cor | 6804.2 | 1592857.5 | 510774.3 | 17178 | 1.64041666667 | 14828 |
| 014267 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:37pm | Sensor | 1797-S0024-G-TJV.cor | 6804.2 | 1592857.5 | 510774.1 | 17180 | 1.64041666667 | 14267 |
| 014396 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:38pm | Sensor | 1797-S0024-G-TJV.cor | 6804.2 | 1592857.5 | 510774.1 | 17182 | 1.64041666667 | 14396 |
| 014849 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:39pm | Sensor | 1797-S0024-G-TJV.cor | 6804.0 | 1592857.9 | 510773.9 | 17184 | 1.64041666667 | 14849 |
| 013822 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:40pm | Sensor | 1797-S0024-G-TJV.cor | 6804.0 | 1592859.5 | 510772.2 | 17186 | 1.64041666667 | 13822 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592861.0 | 510769.8 | 17188 | 1.64041666667 | 13295 |
| 013493 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592861.8 | 510768.7 | 17190 | 1.64041666667 | 13493 |
| 014113 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592861.8 | 510768.7 | 17192 | 1.64041666667 | 14113 |
| 012138 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:44pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592861.9 | 510768.3 | 17194 | 1.64041666667 | 12138 |
| 013354 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:45pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592860.1 | 510767.0 | 17196 | 1.64041666667 | 13354 |
| 014738 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592857.4 | 510766.0 | 17198 | 1.64041666667 | 14738 |
| 013794 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592855.7 | 510765.1 | 17200 | 1.64041666667 | 13794 |
| 012988 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:48pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592855.0 | 510764.8 | 17202 | 1.64041666667 | 12988 |
| 013447 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:49pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592854.8 | 510764.6 | 17204 | 1.64041666667 | 13447 |
| 014221 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592855.1 | 510764.5 | 17206 | 1.64041666667 | 14221 |
| 012615 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:51pm | Sensor | 1797-S0024-G-TJV.cor | 6798.3 | 1592854.4 | 510765.1 | 17208 | 1.64041666667 | 12615 |
| 012393 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:52pm | Sensor | 1797-S0024-G-TJV.cor | 6797.1 | 1592854.8 | 510765.9 | 17210 | 1.64041666667 | 12393 |
| 013838 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:53pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592857.4 | 510766.9 | 17212 | 1.64041666667 | 13838 |
| 014499 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:54pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592858.5 | 510767.2 | 17214 | 1.64041666667 | 14499 |
| 013435 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:55pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592858.8 | 510765.9 | 17216 | 1.64041666667 | 13435 |
| 013468 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:56pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592859.0 | 510764.1 | 17218 | 1.64041666667 | 13468 |
| 012367 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:57pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592859.4 | 510762.1 | 17220 | 1.64041666667 | 12367 |
| 012211 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:58pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592859.5 | 510758.9 | 17222 | 1.64041666667 | 12211 |
| 012562 | 0 | GeoXH 6000 | 08/18/2015 | 01:00:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592860.0 | 510756.4 | 17224 | 1.64041666667 | 12562 |
| 012800 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:00pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592859.3 | 510753.4 | 17226 | 1.64041666667 | 12800 |
| 016460 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:01pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592858.6 | 510750.0 | 17228 | 1.64041666667 | 16460 |
| 014465 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:02pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592858.7 | 510746.2 | 17230 | 1.64041666667 | 14465 |
| 014836 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:03pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592858.8 | 510743.8 | 17232 | 1.64041666667 | 14836 |
| 014839 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:04pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592858.6 | 510740.4 | 17234 | 1.64041666667 | 14839 |
| 015019 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:05pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592859.2 | 510736.7 | 17236 | 1.64041666667 | 15019 |
| 014405 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:06pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592859.8 | 510732.7 | 17238 | 1.64041666667 | 14405 |
| 013021 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592860.5 | 510730.0 | 17240 | 1.64041666667 | 13021 |
| 013965 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:08pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592861.5 | 510726.4 | 17242 | 1.64041666667 | 13965 |
| 013541 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:09pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592861.7 | 510723.2 | 17244 | 1.64041666667 | 13541 |
| 012355 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:10pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592862.4 | 510720.6 | 17246 | 1.64041666667 | 12355 |
| 012359 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:11pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592863.0 | 510718.2 | 17248 | 1.64041666667 | 12359 |
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:12pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592863.7 | 510714.4 | 17250 | 1.64041666667 | 14819 |
| 013545 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:13pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592864.8 | 510711.5 | 17252 | 1.64041666667 | 13545 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:14pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592866.0 | 510708.5 | 17254 | 1.64041666667 | 14456 |
| 014564 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:15pm | Sensor | 1797-S0024-G-TJV.cor | 6799.1 | 1592867.4 | 510705.5 | 17256 | 1.64041666667 | 14564 |
| 014681 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:16pm | Sensor | 1797-S0024-G-TJV.cor | 6798.6 | 1592869.3 | 510702.3 | 17258 | 1.64041666667 | 14681 |
| 013930 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:17pm | Sensor | 1797-S0024-G-TJV.cor | 6797.6 | 1592869.9 | 510699.7 | 17260 | 1.64041666667 | 13930 |
| 014672 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:18pm | Sensor | 1797-S0024-G-TJV.cor | 6796.8 | 1592870.8 | 510696.9 | 17262 | 1.64041666667 | 14672 |
| 016748 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:19pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592871.5 | 510694.1 | 17264 | 1.64041666667 | 16748 |
| 015467 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:20pm | Sensor | 1797-S0024-G-TJV.cor | 6795.9 | 1592872.6 | 510691.9 | 17266 | 1.64041666667 | 15467 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014876 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:21pm | Sensor | 1797-S0024-G-TJV.cor | 6794.6 | 1592873.5 | 510690.1 | 17268 | 1.64041666667 | 14876 |
| 014789 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:22pm | Sensor | 1797-S0024-G-TJV.cor | 6792.9 | 1592873.2 | 510687.2 | 17270 | 1.64041666667 | 14789 |
| 013537 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:23pm | Sensor | 1797-S0024-G-TJV.cor | 6798.7 | 1592873.6 | 510684.8 | 17272 | 1.64041666667 | 13537 |
| 013674 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592873.8 | 510684.5 | 17274 | 1.64041666667 | 13674 |
| 014968 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:25pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592871.9 | 510684.7 | 17276 | 1.64041666667 | 14968 |
| 015772 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:26pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592869.2 | 510683.9 | 17278 | 1.64041666667 | 15772 |
| 013393 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:27pm | Sensor | 1797-S0024-G-TJV.cor | 6800.0 | 1592869.0 | 510682.9 | 17280 | 1.64041666667 | 13393 |
| 015828 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:28pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592869.0 | 510683.2 | 17282 | 1.64041666667 | 15828 |
| 015687 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592867.0 | 510682.8 | 17284 | 1.64041666667 | 15687 |
| 017031 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:30pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592862.4 | 510682.2 | 17286 | 1.64041666667 | 17031 |
| 016438 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:31pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592860.9 | 510682.1 | 17288 | 1.64041666667 | 16438 |
| 015419 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592862.1 | 510681.3 | 17290 | 1.64041666667 | 15419 |
| 016515 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592863.7 | 510681.4 | 17292 | 1.64041666667 | 16515 |
| 014628 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:34pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592866.5 | 510681.5 | 17294 | 1.64041666667 | 14628 |
| 015297 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592867.5 | 510681.4 | 17296 | 1.64041666667 | 15297 |
| 015194 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592868.4 | 510682.3 | 17298 | 1.64041666667 | 15194 |
| 014208 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592868.5 | 510684.2 | 17300 | 1.64041666667 | 14208 |
| 014532 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592868.0 | 510687.6 | 17302 | 1.64041666667 | 14532 |
| 014133 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592867.9 | 510690.1 | 17304 | 1.64041666667 | 14133 |
| 014063 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592867.2 | 510693.0 | 17306 | 1.64041666667 | 14063 |
| 014495 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592866.7 | 510695.6 | 17308 | 1.64041666667 | 14495 |
| 014214 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592865.8 | 510698.5 | 17310 | 1.64041666667 | 14214 |
| 014503 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592865.3 | 510701.4 | 17312 | 1.64041666667 | 14503 |
| 014336 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592865.2 | 510704.8 | 17314 | 1.64041666667 | 14336 |
| 015628 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592864.6 | 510707.7 | 17316 | 1.64041666667 | 15628 |
| 014703 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592864.1 | 510710.8 | 17318 | 1.64041666667 | 14703 |
| 013335 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592863.4 | 510713.9 | 17320 | 1.64041666667 | 13335 |
| 015033 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592862.6 | 510716.9 | 17322 | 1.64041666667 | 15033 |
| 013118 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:49pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592862.3 | 510720.1 | 17324 | 1.64041666667 | 13118 |
| 015669 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592861.0 | 510723.0 | 17326 | 1.64041666667 | 15669 |
| 014194 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592860.2 | 510725.6 | 17328 | 1.64041666667 | 14194 |
| 012724 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592859.0 | 510728.6 | 17330 | 1.64041666667 | 12724 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592857.9 | 510731.5 | 17332 | 1.64041666667 | 13861 |
| 014565 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592857.4 | 510735.1 | 17334 | 1.64041666667 | 14565 |
| 013811 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592856.6 | 510737.6 | 17336 | 1.64041666667 | 13811 |
| 012993 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592855.8 | 510740.6 | 17338 | 1.64041666667 | 12993 |
| 012968 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592855.2 | 510743.0 | 17340 | 1.64041666667 | 12968 |
| 012812 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592854.4 | 510746.4 | 17342 | 1.64041666667 | 12812 |
| 013103 | 0 | GeoXH 6000 | 08/18/2015 | 01:01:59pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592854.3 | 510749.2 | 17344 | 1.64041666667 | 13103 |
| 011945 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:00pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592853.8 | 510752.6 | 17346 | 1.64041666667 | 11945 |
| 012016 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592853.3 | 510755.7 | 17348 | 1.64041666667 | 12016 |
| 012304 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592853.3 | 510759.2 | 17350 | 1.64041666667 | 12304 |
| 013576 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:03pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592853.0 | 510761.7 | 17352 | 1.64041666667 | 13576 |
| 013744 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:04pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592854.5 | 510764.1 | 17354 | 1.64041666667 | 13744 |
| 013772 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:05pm | Sensor | 1797-S0024-G-TJV.cor | 6803.6 | 1592855.1 | 510764.5 | 17356 | 1.64041666667 | 13772 |
| 013751 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:06pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592856.0 | 510764.5 | 17358 | 1.64041666667 | 13751 |
| 011748 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592855.9 | 510764.8 | 17360 | 1.64041666667 | 11748 |
| 012327 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592855.5 | 510765.2 | 17362 | 1.64041666667 | 12327 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013521 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592853.7 | 510764.3 | 17364 | 1.64041666667 | 13521 |
| 013010 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592852.7 | 510764.0 | 17366 | 1.64041666667 | 13010 |
| 012972 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592852.8 | 510764.2 | 17368 | 1.64041666667 | 12972 |
| 011853 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592852.4 | 510764.0 | 17370 | 1.64041666667 | 11853 |
| 010966 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592851.9 | 510763.4 | 17372 | 1.64041666667 | 10966 |
| 012980 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592852.0 | 510763.5 | 17374 | 1.64041666667 | 12980 |
| 012665 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592852.4 | 510763.4 | 17376 | 1.64041666667 | 12665 |
| 013906 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:16pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592852.5 | 510763.5 | 17378 | 1.64041666667 | 13906 |
| 014126 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:17pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592853.3 | 510763.5 | 17380 | 1.64041666667 | 14126 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:18pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592853.6 | 510763.6 | 17382 | 1.64041666667 | 13491 |
| 013723 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592854.1 | 510761.9 | 17384 | 1.64041666667 | 13723 |
| 012970 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592854.5 | 510759.3 | 17386 | 1.64041666667 | 12970 |
| 012452 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592854.6 | 510758.2 | 17388 | 1.64041666667 | 12452 |
| 013643 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592855.5 | 510757.4 | 17390 | 1.64041666667 | 13643 |
| 014960 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592856.7 | 510755.3 | 17392 | 1.64041666667 | 14960 |
| 013790 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592858.0 | 510754.2 | 17394 | 1.64041666667 | 13790 |
| 011397 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:25pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592858.8 | 510753.3 | 17396 | 1.64041666667 | 11397 |
| 012659 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:26pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592857.5 | 510752.3 | 17398 | 1.64041666667 | 12659 |
| 014085 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592856.6 | 510752.4 | 17400 | 1.64041666667 | 14085 |
| 013301 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:28pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592857.5 | 510754.2 | 17402 | 1.64041666667 | 13301 |
| 013075 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:29pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592857.8 | 510755.6 | 17404 | 1.64041666667 | 13075 |
| 012628 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:30pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592856.7 | 510756.9 | 17406 | 1.64041666667 | 12628 |
| 012277 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:31pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592854.8 | 510757.7 | 17408 | 1.64041666667 | 12277 |
| 013509 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:32pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592851.8 | 510758.4 | 17410 | 1.64041666667 | 13509 |
| 012197 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592848.4 | 510757.7 | 17412 | 1.64041666667 | 12197 |
| 012499 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592846.0 | 510757.8 | 17414 | 1.64041666667 | 12499 |
| 013564 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:35pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592843.8 | 510757.2 | 17416 | 1.64041666667 | 13564 |
| 012781 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:36pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592840.9 | 510755.6 | 17418 | 1.64041666667 | 12781 |
| 013755 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:37pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592838.2 | 510754.6 | 17420 | 1.64041666667 | 13755 |
| 015318 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592835.4 | 510752.7 | 17422 | 1.64041666667 | 15318 |
| 013189 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592833.0 | 510751.9 | 17424 | 1.64041666667 | 13189 |
| 013047 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:40pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592830.0 | 510750.9 | 17426 | 1.64041666667 | 13047 |
| 013822 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:41pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592827.3 | 510749.9 | 17428 | 1.64041666667 | 13822 |
| 014405 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:42pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592823.6 | 510748.8 | 17430 | 1.64041666667 | 14405 |
| 013651 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592821.0 | 510747.4 | 17432 | 1.64041666667 | 13651 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592818.1 | 510746.3 | 17434 | 1.64041666667 | 14092 |
| 014353 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592815.4 | 510745.4 | 17436 | 1.64041666667 | 14353 |
| 013728 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592811.6 | 510743.8 | 17438 | 1.64041666667 | 13728 |
| 012852 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:47pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592808.8 | 510743.1 | 17440 | 1.64041666667 | 12852 |
| 012483 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:48pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592805.7 | 510741.9 | 17442 | 1.64041666667 | 12483 |
| 015270 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:49pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592803.0 | 510740.9 | 17444 | 1.64041666667 | 15270 |
| 014347 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592799.1 | 510739.7 | 17446 | 1.64041666667 | 14347 |
| 013967 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592796.2 | 510738.6 | 17448 | 1.64041666667 | 13967 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592792.7 | 510737.9 | 17450 | 1.64041666667 | 13631 |
| 014508 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592789.9 | 510737.2 | 17452 | 1.64041666667 | 14508 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592786.4 | 510735.9 | 17454 | 1.64041666667 | 14067 |
| 012966 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592783.8 | 510735.4 | 17456 | 1.64041666667 | 12966 |
| 013981 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592780.6 | 510734.5 | 17458 | 1.64041666667 | 13981 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012615 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592778.1 | 510733.9 | 17460 | 1.64041666667 | 12615 |
| 014613 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592774.2 | 510733.3 | 17462 | 1.64041666667 | 14613 |
| 014723 | 0 | GeoXH 6000 | 08/18/2015 | 01:02:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592771.4 | 510732.3 | 17464 | 1.64041666667 | 14723 |
| 014241 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592768.4 | 510731.2 | 17466 | 1.64041666667 | 14241 |
| 014260 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592766.0 | 510730.1 | 17468 | 1.64041666667 | 14260 |
| 014682 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592762.3 | 510728.0 | 17470 | 1.64041666667 | 14682 |
| 015460 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592759.4 | 510726.9 | 17472 | 1.64041666667 | 15460 |
| 015925 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592756.5 | 510726.0 | 17474 | 1.64041666667 | 15925 |
| 013941 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592754.0 | 510725.0 | 17476 | 1.64041666667 | 13941 |
| 016475 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592750.8 | 510723.7 | 17478 | 1.64041666667 | 16475 |
| 015248 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592748.4 | 510722.0 | 17480 | 1.64041666667 | 15248 |
| 015602 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592745.7 | 510720.8 | 17482 | 1.64041666667 | 15602 |
| 017100 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592742.9 | 510719.6 | 17484 | 1.64041666667 | 17100 |
| 016095 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592740.1 | 510719.1 | 17486 | 1.64041666667 | 16095 |
| 014223 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:11pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592736.7 | 510718.8 | 17488 | 1.64041666667 | 14223 |
| 015046 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:12pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592735.1 | 510719.4 | 17490 | 1.64041666667 | 15046 |
| 015101 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:13pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592734.9 | 510719.5 | 17492 | 1.64041666667 | 15101 |
| 014455 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:14pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592735.4 | 510718.4 | 17494 | 1.64041666667 | 14455 |
| 014924 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:15pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592736.5 | 510716.1 | 17496 | 1.64041666667 | 14924 |
| 013781 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592736.6 | 510714.2 | 17498 | 1.64041666667 | 13781 |
| 015115 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:17pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592736.8 | 510714.3 | 17500 | 1.64041666667 | 15115 |
| 014938 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:18pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592738.2 | 510712.2 | 17502 | 1.64041666667 | 14938 |
| 014114 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:19pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592739.6 | 510709.0 | 17504 | 1.64041666667 | 14114 |
| 012198 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:20pm | Sensor | 1797-S0024-G-TJV.cor | 6799.5 | 1592739.9 | 510707.8 | 17506 | 1.64041666667 | 12198 |
| 014539 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:21pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592738.6 | 510709.0 | 17508 | 1.64041666667 | 14539 |
| 014344 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:22pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592737.9 | 510710.5 | 17510 | 1.64041666667 | 14344 |
| 015076 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:23pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592737.5 | 510711.6 | 17512 | 1.64041666667 | 15076 |
| 015199 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:24pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592737.7 | 510713.0 | 17514 | 1.64041666667 | 15199 |
| 015049 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:25pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592737.2 | 510714.1 | 17516 | 1.64041666667 | 15049 |
| 013152 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:26pm | Sensor | 1797-S0024-G-TJV.cor | 6800.0 | 1592736.8 | 510714.5 | 17518 | 1.64041666667 | 13152 |
| 013398 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:27pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592736.7 | 510714.5 | 17520 | 1.64041666667 | 13398 |
| 011959 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:28pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592737.2 | 510714.0 | 17522 | 1.64041666667 | 11959 |
| 014389 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592737.8 | 510713.9 | 17524 | 1.64041666667 | 14389 |
| 014217 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:30pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592740.0 | 510714.3 | 17526 | 1.64041666667 | 14217 |
| 014534 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592742.5 | 510715.2 | 17528 | 1.64041666667 | 14534 |
| 016023 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592745.4 | 510715.9 | 17530 | 1.64041666667 | 16023 |
| 016785 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592747.6 | 510716.7 | 17532 | 1.64041666667 | 16785 |
| 016946 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592750.6 | 510717.2 | 17534 | 1.64041666667 | 16946 |
| 014796 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592753.5 | 510717.5 | 17536 | 1.64041666667 | 14796 |
| 012969 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592757.0 | 510718.8 | 17538 | 1.64041666667 | 12969 |
| 013532 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592759.6 | 510719.4 | 17540 | 1.64041666667 | 13532 |
| 013913 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592762.5 | 510720.6 | 17542 | 1.64041666667 | 13913 |
| 012868 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:39pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592765.8 | 510722.4 | 17544 | 1.64041666667 | 12868 |
| 015487 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:40pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592769.4 | 510723.7 | 17546 | 1.64041666667 | 15487 |
| 012841 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:41pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592771.4 | 510724.2 | 17548 | 1.64041666667 | 12841 |
| 013260 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:42pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592773.8 | 510724.4 | 17550 | 1.64041666667 | 13260 |
| 014055 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592776.5 | 510725.3 | 17552 | 1.64041666667 | 14055 |
| 012453 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592779.8 | 510726.2 | 17554 | 1.64041666667 | 12453 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013223 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:45pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592783.5 | 510727.2 | 17556 | 1.64041666667 | 13223 |
| 013626 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592786.2 | 510728.1 | 17558 | 1.64041666667 | 13626 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592788.3 | 510728.7 | 17560 | 1.64041666667 | 14266 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592791.1 | 510729.6 | 17562 | 1.64041666667 | 14516 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592793.9 | 510730.6 | 17564 | 1.64041666667 | 14609 |
| 016162 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:50pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592797.2 | 510731.2 | 17566 | 1.64041666667 | 16162 |
| 014180 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:51pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592799.8 | 510731.9 | 17568 | 1.64041666667 | 14180 |
| 015635 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:52pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592802.6 | 510732.7 | 17570 | 1.64041666667 | 15635 |
| 015428 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:53pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592804.9 | 510733.6 | 17572 | 1.64041666667 | 15428 |
| 019397 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:54pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592808.0 | 510735.1 | 17574 | 1.64041666667 | 19397 |
| 017749 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:55pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592809.6 | 510735.4 | 17576 | 1.64041666667 | 17749 |
| 017727 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:56pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592809.6 | 510735.4 | 17578 | 1.64041666667 | 17727 |
| 020932 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:57pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592809.7 | 510736.5 | 17580 | 1.64041666667 | 20932 |
| 014563 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:58pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592809.5 | 510736.9 | 17582 | 1.64041666667 | 14563 |
| 018790 | 0 | GeoXH 6000 | 08/18/2015 | 01:03:59pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592808.3 | 510736.9 | 17584 | 1.64041666667 | 18790 |
| 017177 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:00pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592806.3 | 510737.3 | 17586 | 1.64041666667 | 17177 |
| 015874 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:01pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592804.8 | 510738.2 | 17588 | 1.64041666667 | 15874 |
| 013328 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:02pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592804.5 | 510738.7 | 17590 | 1.64041666667 | 13328 |
| 016202 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:03pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592806.1 | 510738.2 | 17592 | 1.64041666667 | 16202 |
| 017940 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:04pm | Sensor | 1797-S0024-G-TJV.cor | 6803.6 | 1592807.4 | 510736.8 | 17594 | 1.64041666667 | 17940 |
| 017205 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:05pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592809.1 | 510735.7 | 17596 | 1.64041666667 | 17205 |
| 016751 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:06pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592811.3 | 510735.7 | 17598 | 1.64041666667 | 16751 |
| 017118 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:07pm | Sensor | 1797-S0024-G-TJV.cor | 6798.9 | 1592811.8 | 510735.9 | 17600 | 1.64041666667 | 17118 |
| 016999 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:08pm | Sensor | 1797-S0024-G-TJV.cor | 6800.0 | 1592810.5 | 510735.8 | 17602 | 1.64041666667 | 16999 |
| 016279 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:09pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592809.3 | 510736.1 | 17604 | 1.64041666667 | 16279 |
| 015980 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:10pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592810.4 | 510736.1 | 17606 | 1.64041666667 | 15980 |
| 016355 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:11pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592812.6 | 510736.6 | 17608 | 1.64041666667 | 16355 |
| 012968 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:12pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592815.7 | 510737.4 | 17610 | 1.64041666667 | 12968 |
| 014882 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:13pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592818.4 | 510738.0 | 17612 | 1.64041666667 | 14882 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:14pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592821.9 | 510739.3 | 17614 | 1.64041666667 | 13560 |
| 011610 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:15pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592824.6 | 510740.1 | 17616 | 1.64041666667 | 11610 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:16pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592828.2 | 510741.4 | 17618 | 1.64041666667 | 14482 |
| 014090 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:17pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592830.8 | 510742.2 | 17620 | 1.64041666667 | 14090 |
| 012282 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:18pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592833.8 | 510742.9 | 17622 | 1.64041666667 | 12282 |
| 014770 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:19pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592836.4 | 510743.7 | 17624 | 1.64041666667 | 14770 |
| 013682 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592838.9 | 510744.1 | 17626 | 1.64041666667 | 13682 |
| 015870 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592841.4 | 510745.0 | 17628 | 1.64041666667 | 15870 |
| 015187 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592844.7 | 510745.7 | 17630 | 1.64041666667 | 15187 |
| 012887 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592846.8 | 510746.7 | 17632 | 1.64041666667 | 12887 |
| 012971 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:24pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592849.6 | 510749.1 | 17634 | 1.64041666667 | 12971 |
| 013563 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:25pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592852.0 | 510750.9 | 17636 | 1.64041666667 | 13563 |
| 012420 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592854.3 | 510752.4 | 17638 | 1.64041666667 | 12420 |
| 013635 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592855.7 | 510752.5 | 17640 | 1.64041666667 | 13635 |
| 012588 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:28pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592857.8 | 510753.2 | 17642 | 1.64041666667 | 12588 |
| 012207 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592857.7 | 510753.0 | 17644 | 1.64041666667 | 12207 |
| 010732 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592857.2 | 510752.7 | 17646 | 1.64041666667 | 10732 |
| 013063 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592857.7 | 510751.9 | 17648 | 1.64041666667 | 13063 |
| 013315 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592859.2 | 510749.5 | 17650 | 1.64041666667 | 13315 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014939 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592859.9 | 510747.4 | 17652 | 1.64041666667 | 14939 |
| 015044 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:34pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592859.7 | 510745.8 | 17654 | 1.64041666667 | 15044 |
| 013601 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:35pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592859.4 | 510744.6 | 17656 | 1.64041666667 | 13601 |
| 014740 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:36pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592859.5 | 510741.8 | 17658 | 1.64041666667 | 14740 |
| 014065 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:37pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592859.9 | 510739.2 | 17660 | 1.64041666667 | 14065 |
| 014946 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:38pm | Sensor | 1797-S0024-G-TJV.cor | 6799.5 | 1592860.2 | 510737.8 | 17662 | 1.64041666667 | 14946 |
| 013966 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:39pm | Sensor | 1797-S0024-G-TJV.cor | 6799.4 | 1592860.2 | 510737.7 | 17664 | 1.64041666667 | 13966 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:40pm | Sensor | 1797-S0024-G-TJV.cor | 6799.1 | 1592860.2 | 510737.7 | 17666 | 1.64041666667 | 14201 |
| 014290 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:41pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592860.6 | 510738.7 | 17668 | 1.64041666667 | 14290 |
| 013472 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:42pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592860.8 | 510740.1 | 17670 | 1.64041666667 | 13472 |
| 013756 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:43pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592860.2 | 510741.2 | 17672 | 1.64041666667 | 13756 |
| 014964 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:44pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592859.0 | 510742.9 | 17674 | 1.64041666667 | 14964 |
| 015861 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:45pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592857.1 | 510744.8 | 17676 | 1.64041666667 | 15861 |
| 014315 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:46pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592854.7 | 510745.2 | 17678 | 1.64041666667 | 14315 |
| 012908 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592852.1 | 510744.6 | 17680 | 1.64041666667 | 12908 |
| 013547 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592849.1 | 510743.7 | 17682 | 1.64041666667 | 13547 |
| 013766 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592846.5 | 510742.5 | 17684 | 1.64041666667 | 13766 |
| 014961 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592843.3 | 510741.4 | 17686 | 1.64041666667 | 14961 |
| 014420 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592840.6 | 510740.2 | 17688 | 1.64041666667 | 14420 |
| 013895 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592837.9 | 510739.3 | 17690 | 1.64041666667 | 13895 |
| 013433 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592835.0 | 510738.5 | 17692 | 1.64041666667 | 13433 |
| 013258 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592831.7 | 510737.4 | 17694 | 1.64041666667 | 13258 |
| 014084 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592829.1 | 510736.6 | 17696 | 1.64041666667 | 14084 |
| 012161 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592826.7 | 510735.5 | 17698 | 1.64041666667 | 12161 |
| 013510 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:57pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592824.5 | 510734.3 | 17700 | 1.64041666667 | 13510 |
| 013457 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:58pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592821.3 | 510733.0 | 17702 | 1.64041666667 | 13457 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 01:04:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592818.5 | 510731.9 | 17704 | 1.64041666667 | 14314 |
| 015788 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592815.5 | 510731.2 | 17706 | 1.64041666667 | 15788 |
| 017237 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592813.1 | 510730.3 | 17708 | 1.64041666667 | 17237 |
| 015739 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:02pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592811.1 | 510729.1 | 17710 | 1.64041666667 | 15739 |
| 014404 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:03pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592809.7 | 510727.5 | 17712 | 1.64041666667 | 14404 |
| 014581 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:04pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592806.9 | 510725.4 | 17714 | 1.64041666667 | 14581 |
| 014985 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:05pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592804.4 | 510724.9 | 17716 | 1.64041666667 | 14985 |
| 015266 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:06pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592801.2 | 510724.7 | 17718 | 1.64041666667 | 15266 |
| 014833 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592798.7 | 510724.9 | 17720 | 1.64041666667 | 14833 |
| 016989 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:08pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592795.8 | 510724.9 | 17722 | 1.64041666667 | 16989 |
| 015497 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:09pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592793.0 | 510724.0 | 17724 | 1.64041666667 | 15497 |
| 013984 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:10pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592789.3 | 510722.6 | 17726 | 1.64041666667 | 13984 |
| 014356 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:11pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592786.3 | 510721.2 | 17728 | 1.64041666667 | 14356 |
| 014929 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592783.0 | 510720.4 | 17730 | 1.64041666667 | 14929 |
| 014442 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:13pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592780.5 | 510719.9 | 17732 | 1.64041666667 | 14442 |
| 014320 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:14pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592777.5 | 510718.6 | 17734 | 1.64041666667 | 14320 |
| 015910 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:15pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592774.7 | 510718.0 | 17736 | 1.64041666667 | 15910 |
| 015197 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:16pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592771.7 | 510716.8 | 17738 | 1.64041666667 | 15197 |
| 015949 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592769.2 | 510716.0 | 17740 | 1.64041666667 | 15949 |
| 014037 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592766.5 | 510715.3 | 17742 | 1.64041666667 | 14037 |
| 014009 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592763.7 | 510714.2 | 17744 | 1.64041666667 | 14009 |
| 014332 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592760.1 | 510713.4 | 17746 | 1.64041666667 | 14332 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013993 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592757.5 | 510712.8 | 17748 | 1.64041666667 | 13993 |
| 014058 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592754.9 | 510713.0 | 17750 | 1.64041666667 | 14058 |
| 014464 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:23pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592752.8 | 510713.0 | 17752 | 1.64041666667 | 14464 |
| 015436 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:24pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592750.4 | 510712.7 | 17754 | 1.64041666667 | 15436 |
| 015469 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:25pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592747.8 | 510712.1 | 17756 | 1.64041666667 | 15469 |
| 016767 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:26pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592745.1 | 510710.6 | 17758 | 1.64041666667 | 16767 |
| 015442 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:27pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592742.2 | 510709.4 | 17760 | 1.64041666667 | 15442 |
| 016070 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:28pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592740.5 | 510708.2 | 17762 | 1.64041666667 | 16070 |
| 014877 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:29pm | Sensor | 1797-S0024-G-TJV.cor | 6799.5 | 1592741.1 | 510708.4 | 17764 | 1.64041666667 | 14877 |
| 014909 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:30pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592741.7 | 510708.2 | 17766 | 1.64041666667 | 14909 |
| 016177 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:31pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592742.5 | 510706.0 | 17768 | 1.64041666667 | 16177 |
| 015774 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:32pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592743.1 | 510703.9 | 17770 | 1.64041666667 | 15774 |
| 014533 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592742.8 | 510702.9 | 17772 | 1.64041666667 | 14533 |
| 013623 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:34pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592743.7 | 510702.4 | 17774 | 1.64041666667 | 13623 |
| 016365 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:35pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592745.5 | 510700.8 | 17776 | 1.64041666667 | 16365 |
| 015191 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:36pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592747.3 | 510697.9 | 17778 | 1.64041666667 | 15191 |
| 014088 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:37pm | Sensor | 1797-S0024-G-TJV.cor | 6798.8 | 1592748.0 | 510697.1 | 17780 | 1.64041666667 | 14088 |
| 014892 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:38pm | Sensor | 1797-S0024-G-TJV.cor | 6797.7 | 1592748.1 | 510697.2 | 17782 | 1.64041666667 | 14892 |
| 014373 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:39pm | Sensor | 1797-S0024-G-TJV.cor | 6798.7 | 1592747.8 | 510698.1 | 17784 | 1.64041666667 | 14373 |
| 015533 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:40pm | Sensor | 1797-S0024-G-TJV.cor | 6799.3 | 1592746.8 | 510699.4 | 17786 | 1.64041666667 | 15533 |
| 014653 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:41pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592747.1 | 510699.3 | 17788 | 1.64041666667 | 14653 |
| 014673 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:42pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592747.6 | 510698.5 | 17790 | 1.64041666667 | 14673 |
| 013718 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:43pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592748.0 | 510697.5 | 17792 | 1.64041666667 | 13718 |
| 014109 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:44pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592749.2 | 510696.0 | 17794 | 1.64041666667 | 14109 |
| 016187 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:45pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592751.1 | 510694.8 | 17796 | 1.64041666667 | 16187 |
| 016946 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:46pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592753.5 | 510692.8 | 17798 | 1.64041666667 | 16946 |
| 015546 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:47pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592755.5 | 510691.2 | 17800 | 1.64041666667 | 15546 |
| 017746 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:48pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592757.7 | 510688.6 | 17802 | 1.64041666667 | 17746 |
| 016676 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:49pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592759.3 | 510686.4 | 17804 | 1.64041666667 | 16676 |
| 016049 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:50pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592762.0 | 510683.6 | 17806 | 1.64041666667 | 16049 |
| 015352 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:51pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592763.8 | 510681.6 | 17808 | 1.64041666667 | 15352 |
| 014818 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:52pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592766.0 | 510679.2 | 17810 | 1.64041666667 | 14818 |
| 013964 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:53pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592768.5 | 510677.0 | 17812 | 1.64041666667 | 13964 |
| 012461 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:54pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592770.9 | 510674.3 | 17814 | 1.64041666667 | 12461 |
| 012865 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:55pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592772.8 | 510672.2 | 17816 | 1.64041666667 | 12865 |
| 012456 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:56pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592774.8 | 510669.7 | 17818 | 1.64041666667 | 12456 |
| 014034 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:57pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592776.1 | 510666.8 | 17820 | 1.64041666667 | 14034 |
| 014578 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:58pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592777.4 | 510663.7 | 17822 | 1.64041666667 | 14578 |
| 014234 | 0 | GeoXH 6000 | 08/18/2015 | 01:05:59pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592778.5 | 510660.9 | 17824 | 1.64041666667 | 14234 |
| 016248 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:00pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592779.8 | 510657.4 | 17826 | 1.64041666667 | 16248 |
| 014862 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:01pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592781.1 | 510654.7 | 17828 | 1.64041666667 | 14862 |
| 015535 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:02pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592782.4 | 510651.6 | 17830 | 1.64041666667 | 15535 |
| 014444 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:03pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592783.6 | 510649.3 | 17832 | 1.64041666667 | 14444 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:04pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592785.7 | 510648.9 | 17834 | 1.64041666667 | 14111 |
| 012917 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:05pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592787.4 | 510650.3 | 17836 | 1.64041666667 | 12917 |
| 014989 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:06pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592787.7 | 510653.1 | 17838 | 1.64041666667 | 14989 |
| 013977 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592786.5 | 510655.9 | 17840 | 1.64041666667 | 13977 |
| 014714 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:08pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592784.9 | 510658.7 | 17842 | 1.64041666667 | 14714 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014677 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:09pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592783.3 | 510661.0 | 17844 | 1.64041666667 | 14677 |
| 014989 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:10pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592781.2 | 510663.9 | 17846 | 1.64041666667 | 14989 |
| 013677 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:11pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592779.5 | 510666.7 | 17848 | 1.64041666667 | 13677 |
| 013079 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:12pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592777.3 | 510669.4 | 17850 | 1.64041666667 | 13079 |
| 013560 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:13pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592775.4 | 510672.0 | 17852 | 1.64041666667 | 13560 |
| 013980 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:14pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592773.2 | 510675.1 | 17854 | 1.64041666667 | 13980 |
| 014895 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592771.3 | 510677.2 | 17856 | 1.64041666667 | 14895 |
| 014103 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:16pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592769.5 | 510680.2 | 17858 | 1.64041666667 | 14103 |
| 013425 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:17pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592767.7 | 510682.6 | 17860 | 1.64041666667 | 13425 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:18pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592764.8 | 510685.3 | 17862 | 1.64041666667 | 14246 |
| 017211 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592763.0 | 510687.4 | 17864 | 1.64041666667 | 17211 |
| 016813 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592760.9 | 510689.8 | 17866 | 1.64041666667 | 16813 |
| 015726 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:21pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592758.8 | 510691.7 | 17868 | 1.64041666667 | 15726 |
| 016290 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592756.3 | 510694.2 | 17870 | 1.64041666667 | 16290 |
| 017482 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592754.2 | 510696.1 | 17872 | 1.64041666667 | 17482 |
| 015950 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592751.6 | 510698.2 | 17874 | 1.64041666667 | 15950 |
| 014307 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:25pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592749.3 | 510699.9 | 17876 | 1.64041666667 | 14307 |
| 015907 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592745.8 | 510701.7 | 17878 | 1.64041666667 | 15907 |
| 013816 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592744.1 | 510703.1 | 17880 | 1.64041666667 | 13816 |
| 013474 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:28pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592744.0 | 510704.3 | 17882 | 1.64041666667 | 13474 |
| 012677 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592745.3 | 510704.9 | 17884 | 1.64041666667 | 12677 |
| 014649 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:30pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592747.9 | 510705.4 | 17886 | 1.64041666667 | 14649 |
| 013472 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:31pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592751.0 | 510705.8 | 17888 | 1.64041666667 | 13472 |
| 013898 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592754.2 | 510706.6 | 17890 | 1.64041666667 | 13898 |
| 014064 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592757.4 | 510707.1 | 17892 | 1.64041666667 | 14064 |
| 013266 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:34pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592760.8 | 510707.9 | 17894 | 1.64041666667 | 13266 |
| 015496 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:35pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592764.0 | 510708.9 | 17896 | 1.64041666667 | 15496 |
| 012934 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:36pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592767.6 | 510709.7 | 17898 | 1.64041666667 | 12934 |
| 012713 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:37pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592770.5 | 510710.5 | 17900 | 1.64041666667 | 12713 |
| 013408 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:38pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592773.6 | 510711.5 | 17902 | 1.64041666667 | 13408 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:39pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592776.6 | 510712.4 | 17904 | 1.64041666667 | 14482 |
| 014450 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592780.3 | 510714.1 | 17906 | 1.64041666667 | 14450 |
| 014082 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592782.8 | 510715.2 | 17908 | 1.64041666667 | 14082 |
| 016240 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592785.7 | 510716.4 | 17910 | 1.64041666667 | 16240 |
| 015820 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592788.7 | 510717.6 | 17912 | 1.64041666667 | 15820 |
| 015415 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592792.5 | 510718.4 | 17914 | 1.64041666667 | 15415 |
| 014653 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592795.7 | 510719.0 | 17916 | 1.64041666667 | 14653 |
| 013623 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592799.1 | 510719.3 | 17918 | 1.64041666667 | 13623 |
| 015435 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592802.4 | 510719.5 | 17920 | 1.64041666667 | 15435 |
| 013458 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592805.5 | 510720.1 | 17922 | 1.64041666667 | 13458 |
| 013624 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592808.0 | 510720.4 | 17924 | 1.64041666667 | 13624 |
| 013846 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592811.1 | 510721.0 | 17926 | 1.64041666667 | 13846 |
| 013571 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:51pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592814.1 | 510722.2 | 17928 | 1.64041666667 | 13571 |
| 013923 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592817.3 | 510723.4 | 17930 | 1.64041666667 | 13923 |
| 017340 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592820.2 | 510724.5 | 17932 | 1.64041666667 | 17340 |
| 013305 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592823.8 | 510725.9 | 17934 | 1.64041666667 | 13305 |
| 013916 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592826.7 | 510726.6 | 17936 | 1.64041666667 | 13916 |
| 013409 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592830.0 | 510727.6 | 17938 | 1.64041666667 | 13409 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013942 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592832.8 | 510728.4 | 17940 | 1.64041666667 | 13942 |
| 014285 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592836.8 | 510729.5 | 17942 | 1.64041666667 | 14285 |
| 017101 | 0 | GeoXH 6000 | 08/18/2015 | 01:06:59pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592839.4 | 510730.7 | 17944 | 1.64041666667 | 17101 |
| 013665 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:00pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592842.5 | 510731.8 | 17946 | 1.64041666667 | 13665 |
| 015116 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:01pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592844.8 | 510732.6 | 17948 | 1.64041666667 | 15116 |
| 015059 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:02pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592848.2 | 510734.1 | 17950 | 1.64041666667 | 15059 |
| 014415 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:03pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592850.9 | 510735.1 | 17952 | 1.64041666667 | 14415 |
| 013593 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592853.5 | 510736.3 | 17954 | 1.64041666667 | 13593 |
| 013928 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592855.8 | 510737.4 | 17956 | 1.64041666667 | 13928 |
| 016232 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592858.6 | 510738.4 | 17958 | 1.64041666667 | 16232 |
| 013688 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592860.1 | 510738.9 | 17960 | 1.64041666667 | 13688 |
| 013412 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592860.8 | 510739.2 | 17962 | 1.64041666667 | 13412 |
| 013313 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592860.7 | 510739.4 | 17964 | 1.64041666667 | 13313 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592861.2 | 510739.9 | 17966 | 1.64041666667 | 14458 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592862.9 | 510740.7 | 17968 | 1.64041666667 | 13094 |
| 014883 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592863.8 | 510740.9 | 17970 | 1.64041666667 | 14883 |
| 014220 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592862.8 | 510739.7 | 17972 | 1.64041666667 | 14220 |
| 012915 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592860.9 | 510738.1 | 17974 | 1.64041666667 | 12915 |
| 012828 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592860.3 | 510736.3 | 17976 | 1.64041666667 | 12828 |
| 013617 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592860.5 | 510733.7 | 17978 | 1.64041666667 | 13617 |
| 014864 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:17pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592860.6 | 510732.9 | 17980 | 1.64041666667 | 14864 |
| 013706 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592861.5 | 510731.9 | 17982 | 1.64041666667 | 13706 |
| 014856 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592862.9 | 510729.3 | 17984 | 1.64041666667 | 14856 |
| 015144 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:20pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592864.0 | 510727.2 | 17986 | 1.64041666667 | 15144 |
| 013176 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:21pm | Sensor | 1797-S0024-G-TJV.cor | 6798.9 | 1592864.1 | 510726.8 | 17988 | 1.64041666667 | 13176 |
| 013554 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:22pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592863.9 | 510727.9 | 17990 | 1.64041666667 | 13554 |
| 013648 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:23pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592863.7 | 510729.0 | 17992 | 1.64041666667 | 13648 |
| 015022 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592862.8 | 510728.2 | 17994 | 1.64041666667 | 15022 |
| 014105 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:25pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592861.2 | 510727.3 | 17996 | 1.64041666667 | 14105 |
| 013726 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592859.3 | 510726.1 | 17998 | 1.64041666667 | 13726 |
| 014561 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592857.8 | 510725.0 | 18000 | 1.64041666667 | 14561 |
| 014410 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:28pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592855.7 | 510723.5 | 18002 | 1.64041666667 | 14410 |
| 014672 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592854.9 | 510720.9 | 18004 | 1.64041666667 | 14672 |
| 014318 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592854.4 | 510716.4 | 18006 | 1.64041666667 | 14318 |
| 014529 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592854.4 | 510713.6 | 18008 | 1.64041666667 | 14529 |
| 014552 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592855.4 | 510709.7 | 18010 | 1.64041666667 | 14552 |
| 015758 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592856.3 | 510707.2 | 18012 | 1.64041666667 | 15758 |
| 014259 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:34pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592857.0 | 510704.1 | 18014 | 1.64041666667 | 14259 |
| 013345 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:35pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592857.6 | 510700.9 | 18016 | 1.64041666667 | 13345 |
| 013986 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:36pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592857.7 | 510697.5 | 18018 | 1.64041666667 | 13986 |
| 014566 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:37pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592858.0 | 510694.8 | 18020 | 1.64041666667 | 14566 |
| 013961 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:38pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592859.1 | 510690.9 | 18022 | 1.64041666667 | 13961 |
| 013750 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:39pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592859.9 | 510688.2 | 18024 | 1.64041666667 | 13750 |
| 013937 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:40pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592861.0 | 510685.3 | 18026 | 1.64041666667 | 13937 |
| 014224 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:41pm | Sensor | 1797-S0024-G-TJV.cor | 6799.4 | 1592862.1 | 510683.0 | 18028 | 1.64041666667 | 14224 |
| 014836 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:42pm | Sensor | 1797-S0024-G-TJV.cor | 6799.5 | 1592861.7 | 510682.3 | 18030 | 1.64041666667 | 14836 |
| 014869 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:43pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592859.8 | 510681.7 | 18032 | 1.64041666667 | 14869 |
| 013767 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:44pm | Sensor | 1797-S0024-G-TJV.cor | 6799.4 | 1592856.6 | 510680.3 | 18034 | 1.64041666667 | 13767 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013852 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:45pm | Sensor | 1797-S0024-G-TJV.cor | 6798.8 | 1592853.5 | 510679.9 | 18036 | 1.64041666667 | 13852 |
| 013543 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:46pm | Sensor | 1797-S0024-G-TJV.cor | 6798.0 | 1592851.7 | 510680.0 | 18038 | 1.64041666667 | 13543 |
| 013525 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:47pm | Sensor | 1797-S0024-G-TJV.cor | 6798.6 | 1592852.6 | 510679.7 | 18040 | 1.64041666667 | 13525 |
| 013311 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:48pm | Sensor | 1797-S0024-G-TJV.cor | 6799.3 | 1592854.3 | 510679.7 | 18042 | 1.64041666667 | 13311 |
| 013317 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:49pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592856.1 | 510680.8 | 18044 | 1.64041666667 | 13317 |
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:50pm | Sensor | 1797-S0024-G-TJV.cor | 6799.1 | 1592857.8 | 510682.8 | 18046 | 1.64041666667 | 14819 |
| 015195 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:51pm | Sensor | 1797-S0024-G-TJV.cor | 6799.1 | 1592859.0 | 510685.1 | 18048 | 1.64041666667 | 15195 |
| 014448 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:52pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592859.0 | 510687.9 | 18050 | 1.64041666667 | 14448 |
| 015372 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:53pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592858.5 | 510689.8 | 18052 | 1.64041666667 | 15372 |
| 016113 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592858.3 | 510693.1 | 18054 | 1.64041666667 | 16113 |
| 016028 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592857.9 | 510695.8 | 18056 | 1.64041666667 | 16028 |
| 014747 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592857.8 | 510698.9 | 18058 | 1.64041666667 | 14747 |
| 014756 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592858.0 | 510701.9 | 18060 | 1.64041666667 | 14756 |
| 013619 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592858.1 | 510705.4 | 18062 | 1.64041666667 | 13619 |
| 014955 | 0 | GeoXH 6000 | 08/18/2015 | 01:07:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592858.5 | 510708.4 | 18064 | 1.64041666667 | 14955 |
| 013998 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592858.3 | 510711.6 | 18066 | 1.64041666667 | 13998 |
| 015229 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592858.1 | 510714.7 | 18068 | 1.64041666667 | 15229 |
| 014367 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592858.2 | 510718.3 | 18070 | 1.64041666667 | 14367 |
| 013672 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592858.2 | 510721.0 | 18072 | 1.64041666667 | 13672 |
| 015028 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592858.4 | 510724.2 | 18074 | 1.64041666667 | 15028 |
| 013387 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592858.8 | 510726.9 | 18076 | 1.64041666667 | 13387 |
| 016786 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592858.8 | 510729.4 | 18078 | 1.64041666667 | 16786 |
| 013016 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592857.7 | 510731.0 | 18080 | 1.64041666667 | 13016 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592856.7 | 510731.5 | 18082 | 1.64041666667 | 14324 |
| 013271 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592856.0 | 510731.7 | 18084 | 1.64041666667 | 13271 |
| 014087 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592854.4 | 510731.5 | 18086 | 1.64041666667 | 14087 |
| 013481 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592851.6 | 510730.5 | 18088 | 1.64041666667 | 13481 |
| 014050 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592848.0 | 510729.6 | 18090 | 1.64041666667 | 14050 |
| 013832 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:13pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592845.5 | 510729.3 | 18092 | 1.64041666667 | 13832 |
| 014018 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:14pm | Sensor | 1797-S0024-G-TJV.cor | 6799.1 | 1592842.6 | 510728.9 | 18094 | 1.64041666667 | 14018 |
| 016404 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:15pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592839.5 | 510727.7 | 18096 | 1.64041666667 | 16404 |
| 015561 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:16pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592835.7 | 510726.6 | 18098 | 1.64041666667 | 15561 |
| 015050 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:17pm | Sensor | 1797-S0024-G-TJV.cor | 6799.0 | 1592832.9 | 510726.3 | 18100 | 1.64041666667 | 15050 |
| 016542 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:18pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592829.5 | 510724.5 | 18102 | 1.64041666667 | 16542 |
| 015115 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592826.8 | 510723.0 | 18104 | 1.64041666667 | 15115 |
| 012749 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592823.5 | 510721.7 | 18106 | 1.64041666667 | 12749 |
| 015037 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592821.0 | 510720.3 | 18108 | 1.64041666667 | 15037 |
| 014559 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592817.9 | 510719.0 | 18110 | 1.64041666667 | 14559 |
| 015369 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592814.9 | 510718.1 | 18112 | 1.64041666667 | 15369 |
| 014162 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592810.9 | 510716.6 | 18114 | 1.64041666667 | 14162 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:25pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592808.3 | 510715.7 | 18116 | 1.64041666667 | 14550 |
| 014017 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592805.5 | 510714.8 | 18118 | 1.64041666667 | 14017 |
| 014184 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592802.8 | 510713.9 | 18120 | 1.64041666667 | 14184 |
| 014226 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:28pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592799.3 | 510713.5 | 18122 | 1.64041666667 | 14226 |
| 014236 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592796.2 | 510712.9 | 18124 | 1.64041666667 | 14236 |
| 015949 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:30pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592792.9 | 510712.5 | 18126 | 1.64041666667 | 15949 |
| 015207 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:31pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592790.3 | 510712.0 | 18128 | 1.64041666667 | 15207 |
| 013522 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:32pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592786.8 | 510710.7 | 18130 | 1.64041666667 | 13522 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015920 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592784.2 | 510710.0 | 18132 | 1.64041666667 | 15920 |
| 015320 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:34pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592781.2 | 510708.8 | 18134 | 1.64041666667 | 15320 |
| 014360 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:35pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592778.8 | 510707.5 | 18136 | 1.64041666667 | 14360 |
| 015020 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:36pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592774.9 | 510705.8 | 18138 | 1.64041666667 | 15020 |
| 016085 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:37pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592772.0 | 510704.5 | 18140 | 1.64041666667 | 16085 |
| 014641 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:38pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592768.8 | 510703.5 | 18142 | 1.64041666667 | 14641 |
| 014010 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:39pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592765.8 | 510702.9 | 18144 | 1.64041666667 | 14010 |
| 015112 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:40pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592762.4 | 510701.6 | 18146 | 1.64041666667 | 15112 |
| 016378 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:41pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592759.8 | 510700.7 | 18148 | 1.64041666667 | 16378 |
| 015134 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:42pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592756.6 | 510700.0 | 18150 | 1.64041666667 | 15134 |
| 014973 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:43pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592753.8 | 510699.4 | 18152 | 1.64041666667 | 14973 |
| 014693 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:44pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592750.8 | 510699.6 | 18154 | 1.64041666667 | 14693 |
| 015703 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:45pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592748.6 | 510698.7 | 18156 | 1.64041666667 | 15703 |
| 014696 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:46pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592748.6 | 510697.4 | 18158 | 1.64041666667 | 14696 |
| 015614 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:47pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592749.1 | 510696.4 | 18160 | 1.64041666667 | 15614 |
| 016953 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:48pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592749.2 | 510693.9 | 18162 | 1.64041666667 | 16953 |
| 015068 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:49pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592749.3 | 510692.4 | 18164 | 1.64041666667 | 15068 |
| 015977 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:50pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592749.8 | 510691.8 | 18166 | 1.64041666667 | 15977 |
| 013834 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:51pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592750.5 | 510690.1 | 18168 | 1.64041666667 | 13834 |
| 015488 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:52pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592751.4 | 510686.9 | 18170 | 1.64041666667 | 15488 |
| 014882 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:53pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592752.3 | 510686.6 | 18172 | 1.64041666667 | 14882 |
| 013830 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:54pm | Sensor | 1797-S0024-G-TJV.cor | 6797.9 | 1592753.4 | 510686.8 | 18174 | 1.64041666667 | 13830 |
| 014797 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:55pm | Sensor | 1797-S0024-G-TJV.cor | 6797.3 | 1592753.7 | 510686.5 | 18176 | 1.64041666667 | 14797 |
| 014619 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:56pm | Sensor | 1797-S0024-G-TJV.cor | 6798.0 | 1592752.9 | 510687.5 | 18178 | 1.64041666667 | 14619 |
| 012955 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:57pm | Sensor | 1797-S0024-G-TJV.cor | 6799.4 | 1592751.7 | 510688.5 | 18180 | 1.64041666667 | 12955 |
| 012988 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:58pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592751.0 | 510688.6 | 18182 | 1.64041666667 | 12988 |
| 015247 | 0 | GeoXH 6000 | 08/18/2015 | 01:08:59pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592751.9 | 510688.8 | 18184 | 1.64041666667 | 15247 |
| 016291 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:00pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592754.1 | 510688.4 | 18186 | 1.64041666667 | 16291 |
| 016192 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:01pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592756.5 | 510687.4 | 18188 | 1.64041666667 | 16192 |
| 014098 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:02pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592758.9 | 510684.9 | 18190 | 1.64041666667 | 14098 |
| 015464 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:03pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592761.3 | 510682.7 | 18192 | 1.64041666667 | 15464 |
| 014786 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:04pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592764.7 | 510680.4 | 18194 | 1.64041666667 | 14786 |
| 012936 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:05pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592766.6 | 510678.2 | 18196 | 1.64041666667 | 12936 |
| 015384 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:06pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592768.5 | 510674.9 | 18198 | 1.64041666667 | 15384 |
| 013266 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:07pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592769.9 | 510671.9 | 18200 | 1.64041666667 | 13266 |
| 014326 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:08pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592771.0 | 510668.6 | 18202 | 1.64041666667 | 14326 |
| 014141 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:09pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592771.8 | 510665.8 | 18204 | 1.64041666667 | 14141 |
| 014035 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:10pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592772.9 | 510661.9 | 18206 | 1.64041666667 | 14035 |
| 014249 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:11pm | Sensor | 1797-S0024-G-TJV.cor | 6800.0 | 1592773.7 | 510658.9 | 18208 | 1.64041666667 | 14249 |
| 016162 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:12pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592775.0 | 510656.0 | 18210 | 1.64041666667 | 16162 |
| 015050 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:13pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592776.1 | 510652.8 | 18212 | 1.64041666667 | 15050 |
| 015942 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:14pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592776.9 | 510649.1 | 18214 | 1.64041666667 | 15942 |
| 015025 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592778.2 | 510646.7 | 18216 | 1.64041666667 | 15025 |
| 015486 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592780.7 | 510644.8 | 18218 | 1.64041666667 | 15486 |
| 015511 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592783.3 | 510643.4 | 18220 | 1.64041666667 | 15511 |
| 015697 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592785.7 | 510642.8 | 18222 | 1.64041666667 | 15697 |
| 014904 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592788.4 | 510643.1 | 18224 | 1.64041666667 | 14904 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592791.4 | 510644.2 | 18226 | 1.64041666667 | 14556 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013989 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592793.8 | 510645.5 | 18228 | 1.64041666667 | 13989 |
| 014417 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592796.8 | 510646.8 | 18230 | 1.64041666667 | 14417 |
| 016264 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592798.5 | 510647.7 | 18232 | 1.64041666667 | 16264 |
| 014566 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592799.2 | 510650.0 | 18234 | 1.64041666667 | 14566 |
| 014111 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:25pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592798.3 | 510651.9 | 18236 | 1.64041666667 | 14111 |
| 016518 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592795.9 | 510654.1 | 18238 | 1.64041666667 | 16518 |
| 014959 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592793.8 | 510656.3 | 18240 | 1.64041666667 | 14959 |
| 013159 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:28pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592791.7 | 510658.6 | 18242 | 1.64041666667 | 13159 |
| 012530 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:29pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592789.7 | 510660.8 | 18244 | 1.64041666667 | 12530 |
| 014172 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:30pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592787.5 | 510663.8 | 18246 | 1.64041666667 | 14172 |
| 015513 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592785.8 | 510666.0 | 18248 | 1.64041666667 | 15513 |
| 015428 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592784.0 | 510668.3 | 18250 | 1.64041666667 | 15428 |
| 015977 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592782.5 | 510670.6 | 18252 | 1.64041666667 | 15977 |
| 015604 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:34pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592779.9 | 510673.0 | 18254 | 1.64041666667 | 15604 |
| 014701 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592777.8 | 510675.3 | 18256 | 1.64041666667 | 14701 |
| 016605 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592775.7 | 510678.0 | 18258 | 1.64041666667 | 16605 |
| 015251 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592774.3 | 510679.9 | 18260 | 1.64041666667 | 15251 |
| 017043 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592773.0 | 510682.9 | 18262 | 1.64041666667 | 17043 |
| 015240 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592771.6 | 510685.5 | 18264 | 1.64041666667 | 15240 |
| 016110 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592769.7 | 510688.4 | 18266 | 1.64041666667 | 16110 |
| 016567 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592767.8 | 510690.4 | 18268 | 1.64041666667 | 16567 |
| 015272 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592765.0 | 510692.3 | 18270 | 1.64041666667 | 15272 |
| 015098 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592762.5 | 510693.9 | 18272 | 1.64041666667 | 15098 |
| 013194 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592759.9 | 510694.7 | 18274 | 1.64041666667 | 13194 |
| 015688 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:45pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592757.7 | 510694.9 | 18276 | 1.64041666667 | 15688 |
| 015712 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:46pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592754.3 | 510694.7 | 18278 | 1.64041666667 | 15712 |
| 014098 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:47pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592751.6 | 510693.8 | 18280 | 1.64041666667 | 14098 |
| 014654 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592749.6 | 510692.9 | 18282 | 1.64041666667 | 14654 |
| 014043 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:49pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592749.6 | 510692.9 | 18284 | 1.64041666667 | 14043 |
| 013950 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:50pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592751.5 | 510693.3 | 18286 | 1.64041666667 | 13950 |
| 017437 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592753.7 | 510693.9 | 18288 | 1.64041666667 | 17437 |
| 014139 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592756.8 | 510694.5 | 18290 | 1.64041666667 | 14139 |
| 014605 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592760.0 | 510694.8 | 18292 | 1.64041666667 | 14605 |
| 015261 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592763.5 | 510695.6 | 18294 | 1.64041666667 | 15261 |
| 013985 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592766.4 | 510696.4 | 18296 | 1.64041666667 | 13985 |
| 012886 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592769.6 | 510697.4 | 18298 | 1.64041666667 | 12886 |
| 012941 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592772.4 | 510698.6 | 18300 | 1.64041666667 | 12941 |
| 012775 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592776.3 | 510699.5 | 18302 | 1.64041666667 | 12775 |
| 013874 | 0 | GeoXH 6000 | 08/18/2015 | 01:09:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592779.1 | 510700.2 | 18304 | 1.64041666667 | 13874 |
| 015438 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592782.3 | 510701.0 | 18306 | 1.64041666667 | 15438 |
| 015109 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592785.5 | 510701.7 | 18308 | 1.64041666667 | 15109 |
| 015117 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592788.8 | 510702.6 | 18310 | 1.64041666667 | 15117 |
| 016409 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592791.4 | 510703.3 | 18312 | 1.64041666667 | 16409 |
| 017392 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592794.7 | 510703.8 | 18314 | 1.64041666667 | 17392 |
| 017068 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592797.9 | 510704.8 | 18316 | 1.64041666667 | 17068 |
| 016207 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592801.2 | 510705.8 | 18318 | 1.64041666667 | 16207 |
| 016951 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592803.8 | 510706.7 | 18320 | 1.64041666667 | 16951 |
| 014797 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592806.9 | 510707.6 | 18322 | 1.64041666667 | 14797 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012699 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592809.8 | 510708.7 | 18324 | 1.64041666667 | 12699 |
| 014455 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592812.3 | 510710.5 | 18326 | 1.64041666667 | 14455 |
| 016873 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592814.7 | 510711.6 | 18328 | 1.64041666667 | 16873 |
| 016068 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592817.6 | 510712.2 | 18330 | 1.64041666667 | 16068 |
| 015234 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592820.1 | 510713.0 | 18332 | 1.64041666667 | 15234 |
| 014159 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592823.8 | 510714.0 | 18334 | 1.64041666667 | 14159 |
| 013290 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592826.9 | 510715.2 | 18336 | 1.64041666667 | 13290 |
| 014212 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592829.9 | 510715.8 | 18338 | 1.64041666667 | 14212 |
| 014173 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592832.4 | 510716.3 | 18340 | 1.64041666667 | 14173 |
| 015243 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592835.8 | 510717.4 | 18342 | 1.64041666667 | 15243 |
| 015421 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592838.5 | 510718.0 | 18344 | 1.64041666667 | 15421 |
| 015337 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592841.6 | 510718.9 | 18346 | 1.64041666667 | 15337 |
| 013674 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592844.2 | 510719.9 | 18348 | 1.64041666667 | 13674 |
| 015298 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592847.3 | 510721.1 | 18350 | 1.64041666667 | 15298 |
| 015629 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592850.1 | 510722.4 | 18352 | 1.64041666667 | 15629 |
| 014898 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592853.0 | 510723.3 | 18354 | 1.64041666667 | 14898 |
| 013864 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:25pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592855.2 | 510724.1 | 18356 | 1.64041666667 | 13864 |
| 015406 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592858.0 | 510725.0 | 18358 | 1.64041666667 | 15406 |
| 014801 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592860.7 | 510725.7 | 18360 | 1.64041666667 | 14801 |
| 013600 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592863.3 | 510726.2 | 18362 | 1.64041666667 | 13600 |
| 014860 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592864.4 | 510725.4 | 18364 | 1.64041666667 | 14860 |
| 013315 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592865.4 | 510723.1 | 18366 | 1.64041666667 | 13315 |
| 013618 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592866.1 | 510721.8 | 18368 | 1.64041666667 | 13618 |
| 013394 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592865.9 | 510721.3 | 18370 | 1.64041666667 | 13394 |
| 013668 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592866.3 | 510721.4 | 18372 | 1.64041666667 | 13668 |
| 013437 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:34pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592867.6 | 510720.2 | 18374 | 1.64041666667 | 13437 |
| 014069 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:35pm | Sensor | 1797-S0024-G-TJV.cor | 6798.3 | 1592869.1 | 510717.2 | 18376 | 1.64041666667 | 14069 |
| 013597 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:36pm | Sensor | 1797-S0024-G-TJV.cor | 6798.1 | 1592870.0 | 510715.9 | 18378 | 1.64041666667 | 13597 |
| 013929 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:37pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592869.9 | 510716.9 | 18380 | 1.64041666667 | 13929 |
| 014282 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:38pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592868.6 | 510718.6 | 18382 | 1.64041666667 | 14282 |
| 014970 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:39pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592867.2 | 510720.4 | 18384 | 1.64041666667 | 14970 |
| 013792 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:40pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592865.2 | 510721.9 | 18386 | 1.64041666667 | 13792 |
| 012988 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:41pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592862.6 | 510721.7 | 18388 | 1.64041666667 | 12988 |
| 012937 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:42pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592859.3 | 510721.2 | 18390 | 1.64041666667 | 12937 |
| 014394 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:43pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592856.4 | 510720.3 | 18392 | 1.64041666667 | 14394 |
| 013858 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:44pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592853.1 | 510719.1 | 18394 | 1.64041666667 | 13858 |
| 016124 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:45pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592850.7 | 510718.1 | 18396 | 1.64041666667 | 16124 |
| 013661 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:46pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592847.4 | 510716.5 | 18398 | 1.64041666667 | 13661 |
| 014125 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592844.2 | 510715.6 | 18400 | 1.64041666667 | 14125 |
| 013221 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592841.0 | 510714.8 | 18402 | 1.64041666667 | 13221 |
| 013745 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592838.3 | 510713.8 | 18404 | 1.64041666667 | 13745 |
| 012886 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592834.8 | 510712.7 | 18406 | 1.64041666667 | 12886 |
| 015911 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592832.4 | 510711.6 | 18408 | 1.64041666667 | 15911 |
| 015108 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592829.6 | 510709.9 | 18410 | 1.64041666667 | 15108 |
| 012597 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592827.2 | 510709.0 | 18412 | 1.64041666667 | 12597 |
| 015389 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592823.7 | 510707.9 | 18414 | 1.64041666667 | 15389 |
| 014527 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592820.5 | 510707.6 | 18416 | 1.64041666667 | 14527 |
| 012781 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592817.1 | 510707.1 | 18418 | 1.64041666667 | 12781 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014955 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592814.6 | 510706.3 | 18420 | 1.64041666667 | 14955 |
| 016578 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592811.2 | 510705.1 | 18422 | 1.64041666667 | 16578 |
| 017014 | 0 | GeoXH 6000 | 08/18/2015 | 01:10:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592808.9 | 510703.9 | 18424 | 1.64041666667 | 17014 |
| 017393 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592805.7 | 510702.7 | 18426 | 1.64041666667 | 17393 |
| 014818 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592803.6 | 510701.8 | 18428 | 1.64041666667 | 14818 |
| 014684 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592800.7 | 510700.5 | 18430 | 1.64041666667 | 14684 |
| 014471 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592798.2 | 510699.9 | 18432 | 1.64041666667 | 14471 |
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592794.9 | 510698.7 | 18434 | 1.64041666667 | 13277 |
| 014689 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592791.8 | 510698.0 | 18436 | 1.64041666667 | 14689 |
| 014262 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592788.6 | 510697.3 | 18438 | 1.64041666667 | 14262 |
| 014905 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592785.7 | 510696.2 | 18440 | 1.64041666667 | 14905 |
| 014106 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592782.4 | 510695.3 | 18442 | 1.64041666667 | 14106 |
| 014446 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592779.6 | 510694.2 | 18444 | 1.64041666667 | 14446 |
| 013781 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592776.5 | 510693.1 | 18446 | 1.64041666667 | 13781 |
| 014995 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592774.0 | 510692.2 | 18448 | 1.64041666667 | 14995 |
| 015479 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592770.8 | 510690.6 | 18450 | 1.64041666667 | 15479 |
| 015389 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592768.1 | 510689.6 | 18452 | 1.64041666667 | 15389 |
| 015157 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592765.5 | 510688.9 | 18454 | 1.64041666667 | 15157 |
| 016509 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:15pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592763.0 | 510688.6 | 18456 | 1.64041666667 | 16509 |
| 016667 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:16pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592759.6 | 510687.8 | 18458 | 1.64041666667 | 16667 |
| 015356 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592757.4 | 510686.5 | 18460 | 1.64041666667 | 15356 |
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592754.5 | 510685.9 | 18462 | 1.64041666667 | 14819 |
| 015675 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.3 | 1592754.1 | 510686.2 | 18464 | 1.64041666667 | 15675 |
| 013998 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592753.7 | 510686.0 | 18466 | 1.64041666667 | 13998 |
| 014179 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592751.7 | 510685.2 | 18468 | 1.64041666667 | 14179 |
| 013234 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592750.4 | 510683.6 | 18470 | 1.64041666667 | 13234 |
| 014108 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592750.4 | 510681.6 | 18472 | 1.64041666667 | 14108 |
| 013397 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:24pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592750.9 | 510680.0 | 18474 | 1.64041666667 | 13397 |
| 015559 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:25pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592751.1 | 510679.6 | 18476 | 1.64041666667 | 15559 |
| 015049 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592751.2 | 510680.0 | 18478 | 1.64041666667 | 15049 |
| 015852 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592751.7 | 510679.0 | 18480 | 1.64041666667 | 15852 |
| 013533 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:28pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592752.5 | 510676.1 | 18482 | 1.64041666667 | 13533 |
| 013553 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:29pm | Sensor | 1797-S0024-G-TJV.cor | 6797.6 | 1592752.7 | 510673.9 | 18484 | 1.64041666667 | 13553 |
| 012658 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:30pm | Sensor | 1797-S0024-G-TJV.cor | 6796.8 | 1592752.8 | 510673.0 | 18486 | 1.64041666667 | 12658 |
| 014264 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:31pm | Sensor | 1797-S0024-G-TJV.cor | 6798.3 | 1592752.3 | 510673.8 | 18488 | 1.64041666667 | 14264 |
| 013796 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:32pm | Sensor | 1797-S0024-G-TJV.cor | 6799.4 | 1592751.7 | 510675.7 | 18490 | 1.64041666667 | 13796 |
| 014789 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:33pm | Sensor | 1797-S0024-G-TJV.cor | 6798.3 | 1592751.5 | 510677.5 | 18492 | 1.64041666667 | 14789 |
| 013807 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:34pm | Sensor | 1797-S0024-G-TJV.cor | 6798.2 | 1592751.6 | 510679.0 | 18494 | 1.64041666667 | 13807 |
| 015331 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:35pm | Sensor | 1797-S0024-G-TJV.cor | 6798.2 | 1592753.0 | 510679.9 | 18496 | 1.64041666667 | 15331 |
| 014362 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:36pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592755.5 | 510680.6 | 18498 | 1.64041666667 | 14362 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592757.7 | 510681.2 | 18500 | 1.64041666667 | 14570 |
| 014622 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592760.8 | 510682.4 | 18502 | 1.64041666667 | 14622 |
| 015505 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592763.3 | 510683.2 | 18504 | 1.64041666667 | 15505 |
| 016326 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592766.5 | 510684.2 | 18506 | 1.64041666667 | 16326 |
| 014401 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592769.4 | 510684.4 | 18508 | 1.64041666667 | 14401 |
| 015150 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592772.6 | 510684.6 | 18510 | 1.64041666667 | 15150 |
| 014947 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592775.1 | 510685.1 | 18512 | 1.64041666667 | 14947 |
| 013307 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592778.0 | 510686.4 | 18514 | 1.64041666667 | 13307 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012326 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592780.8 | 510687.7 | 18516 | 1.64041666667 | 12326 |
| 013461 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:46pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592784.4 | 510688.6 | 18518 | 1.64041666667 | 13461 |
| 012485 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592786.8 | 510689.1 | 18520 | 1.64041666667 | 12485 |
| 014221 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592790.0 | 510690.1 | 18522 | 1.64041666667 | 14221 |
| 013605 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592792.4 | 510690.7 | 18524 | 1.64041666667 | 13605 |
| 013991 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592795.7 | 510692.1 | 18526 | 1.64041666667 | 13991 |
| 014718 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592798.1 | 510692.7 | 18528 | 1.64041666667 | 14718 |
| 016129 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592800.0 | 510693.1 | 18530 | 1.64041666667 | 16129 |
| 014262 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592800.6 | 510693.3 | 18532 | 1.64041666667 | 14262 |
| 012565 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592802.2 | 510693.3 | 18534 | 1.64041666667 | 12565 |
| 014511 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592804.5 | 510693.8 | 18536 | 1.64041666667 | 14511 |
| 015567 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592807.6 | 510694.8 | 18538 | 1.64041666667 | 15567 |
| 014984 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592810.7 | 510695.9 | 18540 | 1.64041666667 | 14984 |
| 014713 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592814.1 | 510697.5 | 18542 | 1.64041666667 | 14713 |
| 014598 | 0 | GeoXH 6000 | 08/18/2015 | 01:11:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592817.0 | 510698.4 | 18544 | 1.64041666667 | 14598 |
| 014059 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592820.0 | 510699.2 | 18546 | 1.64041666667 | 14059 |
| 014164 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592822.9 | 510700.3 | 18548 | 1.64041666667 | 14164 |
| 014731 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592826.3 | 510701.4 | 18550 | 1.64041666667 | 14731 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592829.1 | 510702.2 | 18552 | 1.64041666667 | 13972 |
| 015313 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592832.3 | 510703.3 | 18554 | 1.64041666667 | 15313 |
| 014688 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592835.4 | 510704.0 | 18556 | 1.64041666667 | 14688 |
| 016002 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592838.4 | 510704.9 | 18558 | 1.64041666667 | 16002 |
| 014200 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592840.8 | 510705.9 | 18560 | 1.64041666667 | 14200 |
| 014500 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592844.1 | 510706.9 | 18562 | 1.64041666667 | 14500 |
| 015565 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592846.7 | 510708.0 | 18564 | 1.64041666667 | 15565 |
| 013791 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592850.0 | 510709.4 | 18566 | 1.64041666667 | 13791 |
| 015117 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592852.4 | 510710.3 | 18568 | 1.64041666667 | 15117 |
| 014039 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592855.5 | 510711.6 | 18570 | 1.64041666667 | 14039 |
| 013350 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592858.5 | 510712.4 | 18572 | 1.64041666667 | 13350 |
| 012577 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592861.7 | 510713.7 | 18574 | 1.64041666667 | 12577 |
| 013404 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592864.3 | 510714.6 | 18576 | 1.64041666667 | 13404 |
| 012411 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592867.3 | 510715.0 | 18578 | 1.64041666667 | 12411 |
| 012582 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592868.9 | 510714.9 | 18580 | 1.64041666667 | 12582 |
| 013915 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592870.2 | 510713.9 | 18582 | 1.64041666667 | 13915 |
| 013289 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592870.7 | 510712.2 | 18584 | 1.64041666667 | 13289 |
| 013492 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592870.8 | 510710.2 | 18586 | 1.64041666667 | 13492 |
| 012553 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592870.8 | 510709.9 | 18588 | 1.64041666667 | 12553 |
| 013488 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592871.5 | 510709.3 | 18590 | 1.64041666667 | 13488 |
| 013272 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:23pm | Sensor | 1797-S0024-G-TJV.cor | 6800.8 | 1592872.7 | 510707.3 | 18592 | 1.64041666667 | 13272 |
| 014088 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:24pm | Sensor | 1797-S0024-G-TJV.cor | 6797.9 | 1592873.4 | 510704.7 | 18594 | 1.64041666667 | 14088 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:25pm | Sensor | 1797-S0024-G-TJV.cor | 6797.6 | 1592873.6 | 510703.5 | 18596 | 1.64041666667 | 13782 |
| 014515 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:26pm | Sensor | 1797-S0024-G-TJV.cor | 6800.6 | 1592873.8 | 510704.2 | 18598 | 1.64041666667 | 14515 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592873.2 | 510705.3 | 18600 | 1.64041666667 | 14609 |
| 012832 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592870.8 | 510707.4 | 18602 | 1.64041666667 | 12832 |
| 013048 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592868.3 | 510708.8 | 18604 | 1.64041666667 | 13048 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592864.9 | 510709.2 | 18606 | 1.64041666667 | 13972 |
| 016573 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592862.2 | 510709.0 | 18608 | 1.64041666667 | 16573 |
| 015453 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592859.3 | 510708.9 | 18610 | 1.64041666667 | 15453 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015023 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592856.8 | 510708.2 | 18612 | 1.64041666667 | 15023 |
| 014825 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592853.4 | 510707.2 | 18614 | 1.64041666667 | 14825 |
| 012856 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592850.8 | 510706.4 | 18616 | 1.64041666667 | 12856 |
| 013384 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592848.3 | 510705.4 | 18618 | 1.64041666667 | 13384 |
| 014146 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592845.6 | 510704.4 | 18620 | 1.64041666667 | 14146 |
| 015356 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592842.4 | 510702.8 | 18622 | 1.64041666667 | 15356 |
| 014849 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592839.6 | 510702.0 | 18624 | 1.64041666667 | 14849 |
| 013882 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592836.7 | 510701.2 | 18626 | 1.64041666667 | 13882 |
| 014660 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592833.8 | 510700.2 | 18628 | 1.64041666667 | 14660 |
| 015935 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592830.5 | 510699.7 | 18630 | 1.64041666667 | 15935 |
| 015473 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592827.9 | 510699.2 | 18632 | 1.64041666667 | 15473 |
| 013978 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592824.8 | 510698.5 | 18634 | 1.64041666667 | 13978 |
| 016724 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592822.2 | 510697.7 | 18636 | 1.64041666667 | 16724 |
| 015761 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592819.1 | 510696.1 | 18638 | 1.64041666667 | 15761 |
| 015040 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592816.4 | 510694.9 | 18640 | 1.64041666667 | 15040 |
| 015280 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592813.4 | 510693.4 | 18642 | 1.64041666667 | 15280 |
| 014290 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592810.8 | 510691.9 | 18644 | 1.64041666667 | 14290 |
| 014732 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592807.4 | 510690.6 | 18646 | 1.64041666667 | 14732 |
| 015173 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592804.7 | 510689.3 | 18648 | 1.64041666667 | 15173 |
| 015073 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592801.8 | 510687.8 | 18650 | 1.64041666667 | 15073 |
| 014358 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592799.3 | 510686.7 | 18652 | 1.64041666667 | 14358 |
| 013489 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592795.9 | 510685.3 | 18654 | 1.64041666667 | 13489 |
| 015672 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592792.9 | 510684.6 | 18656 | 1.64041666667 | 15672 |
| 015588 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592789.8 | 510683.8 | 18658 | 1.64041666667 | 15588 |
| 016017 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592787.8 | 510683.1 | 18660 | 1.64041666667 | 16017 |
| 015134 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592785.2 | 510682.4 | 18662 | 1.64041666667 | 15134 |
| 014763 | 0 | GeoXH 6000 | 08/18/2015 | 01:12:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592783.1 | 510681.8 | 18664 | 1.64041666667 | 14763 |
| 013170 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592780.4 | 510680.8 | 18666 | 1.64041666667 | 13170 |
| 013702 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592778.1 | 510679.4 | 18668 | 1.64041666667 | 13702 |
| 014045 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592775.4 | 510678.2 | 18670 | 1.64041666667 | 14045 |
| 015151 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592772.6 | 510677.2 | 18672 | 1.64041666667 | 15151 |
| 014377 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592769.6 | 510676.4 | 18674 | 1.64041666667 | 14377 |
| 014064 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592767.0 | 510675.7 | 18676 | 1.64041666667 | 14064 |
| 013536 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592763.9 | 510674.9 | 18678 | 1.64041666667 | 13536 |
| 013074 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592761.3 | 510674.6 | 18680 | 1.64041666667 | 13074 |
| 013018 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:08pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592758.0 | 510673.8 | 18682 | 1.64041666667 | 13018 |
| 013034 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592755.2 | 510673.1 | 18684 | 1.64041666667 | 13034 |
| 012768 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:10pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592752.8 | 510672.7 | 18686 | 1.64041666667 | 12768 |
| 013572 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:11pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592752.4 | 510672.6 | 18688 | 1.64041666667 | 13572 |
| 014763 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592753.1 | 510671.6 | 18690 | 1.64041666667 | 14763 |
| 012750 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592753.2 | 510669.3 | 18692 | 1.64041666667 | 12750 |
| 014047 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:14pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592753.3 | 510667.5 | 18694 | 1.64041666667 | 14047 |
| 014252 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592753.0 | 510667.0 | 18696 | 1.64041666667 | 14252 |
| 016433 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592753.5 | 510666.2 | 18698 | 1.64041666667 | 16433 |
| 014908 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592754.5 | 510663.9 | 18700 | 1.64041666667 | 14908 |
| 013927 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592755.1 | 510661.3 | 18702 | 1.64041666667 | 13927 |
| 013591 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:19pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592754.8 | 510661.3 | 18704 | 1.64041666667 | 13591 |
| 013867 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:20pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592753.4 | 510663.0 | 18706 | 1.64041666667 | 13867 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013997 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:21pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592752.7 | 510664.6 | 18708 | 1.64041666667 | 13997 |
| 013639 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592753.7 | 510666.8 | 18710 | 1.64041666667 | 13639 |
| 012769 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592755.7 | 510668.5 | 18712 | 1.64041666667 | 12769 |
| 014112 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592758.3 | 510669.5 | 18714 | 1.64041666667 | 14112 |
| 014088 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592760.7 | 510670.3 | 18716 | 1.64041666667 | 14088 |
| 013932 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592763.5 | 510671.5 | 18718 | 1.64041666667 | 13932 |
| 015153 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592766.3 | 510672.3 | 18720 | 1.64041666667 | 15153 |
| 013628 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592769.5 | 510673.2 | 18722 | 1.64041666667 | 13628 |
| 012647 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592771.7 | 510673.8 | 18724 | 1.64041666667 | 12647 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592774.7 | 510674.2 | 18726 | 1.64041666667 | 14201 |
| 015370 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592777.4 | 510675.0 | 18728 | 1.64041666667 | 15370 |
| 014792 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592780.4 | 510675.9 | 18730 | 1.64041666667 | 14792 |
| 015998 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592782.7 | 510677.1 | 18732 | 1.64041666667 | 15998 |
| 015939 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592785.4 | 510678.6 | 18734 | 1.64041666667 | 15939 |
| 016495 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592787.9 | 510679.7 | 18736 | 1.64041666667 | 16495 |
| 016723 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592791.0 | 510680.9 | 18738 | 1.64041666667 | 16723 |
| 016601 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592793.7 | 510681.5 | 18740 | 1.64041666667 | 16601 |
| 015790 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592796.6 | 510682.2 | 18742 | 1.64041666667 | 15790 |
| 018317 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592799.1 | 510682.6 | 18744 | 1.64041666667 | 18317 |
| 016639 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592802.0 | 510683.2 | 18746 | 1.64041666667 | 16639 |
| 016969 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592804.1 | 510683.8 | 18748 | 1.64041666667 | 16969 |
| 013662 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592806.9 | 510684.4 | 18750 | 1.64041666667 | 13662 |
| 013525 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592809.5 | 510685.2 | 18752 | 1.64041666667 | 13525 |
| 016041 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592812.6 | 510685.9 | 18754 | 1.64041666667 | 16041 |
| 015290 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592815.2 | 510686.8 | 18756 | 1.64041666667 | 15290 |
| 014082 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592818.4 | 510687.8 | 18758 | 1.64041666667 | 14082 |
| 013870 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592820.9 | 510688.6 | 18760 | 1.64041666667 | 13870 |
| 013967 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592823.6 | 510690.1 | 18762 | 1.64041666667 | 13967 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592826.5 | 510691.1 | 18764 | 1.64041666667 | 13631 |
| 013068 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592829.4 | 510692.1 | 18766 | 1.64041666667 | 13068 |
| 016407 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592831.9 | 510692.9 | 18768 | 1.64041666667 | 16407 |
| 013131 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592834.6 | 510693.5 | 18770 | 1.64041666667 | 13131 |
| 014533 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592837.2 | 510694.1 | 18772 | 1.64041666667 | 14533 |
| 014373 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592840.1 | 510694.7 | 18774 | 1.64041666667 | 14373 |
| 014963 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:55pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592842.5 | 510695.4 | 18776 | 1.64041666667 | 14963 |
| 013760 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592845.8 | 510696.4 | 18778 | 1.64041666667 | 13760 |
| 015020 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592848.7 | 510697.1 | 18780 | 1.64041666667 | 15020 |
| 014195 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592851.6 | 510698.0 | 18782 | 1.64041666667 | 14195 |
| 014468 | 0 | GeoXH 6000 | 08/18/2015 | 01:13:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592854.0 | 510698.8 | 18784 | 1.64041666667 | 14468 |
| 014087 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592857.0 | 510700.5 | 18786 | 1.64041666667 | 14087 |
| 014081 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592859.7 | 510701.7 | 18788 | 1.64041666667 | 14081 |
| 014410 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592862.3 | 510702.6 | 18790 | 1.64041666667 | 14410 |
| 014492 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592865.0 | 510703.1 | 18792 | 1.64041666667 | 14492 |
| 014723 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592868.2 | 510703.6 | 18794 | 1.64041666667 | 14723 |
| 013190 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592871.0 | 510704.1 | 18796 | 1.64041666667 | 13190 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592873.7 | 510704.2 | 18798 | 1.64041666667 | 14067 |
| 012877 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592874.1 | 510703.9 | 18800 | 1.64041666667 | 12877 |
| 014709 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:08pm | Sensor | 1797-S0024-G-TJV.cor | 6801.4 | 1592875.1 | 510701.8 | 18802 | 1.64041666667 | 14709 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014567 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:09pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592876.0 | 510700.3 | 18804 | 1.64041666667 | 14567 |
| 014051 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:10pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592876.6 | 510698.5 | 18806 | 1.64041666667 | 14051 |
| 013743 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:11pm | Sensor | 1797-S0024-G-TJV.cor | 6799.8 | 1592876.8 | 510695.3 | 18808 | 1.64041666667 | 13743 |
| 015165 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:12pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592876.9 | 510692.7 | 18810 | 1.64041666667 | 15165 |
| 014141 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:13pm | Sensor | 1797-S0024-G-TJV.cor | 6798.6 | 1592877.6 | 510693.5 | 18812 | 1.64041666667 | 14141 |
| 013825 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:14pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592877.5 | 510695.3 | 18814 | 1.64041666667 | 13825 |
| 015276 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:15pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592876.3 | 510696.4 | 18816 | 1.64041666667 | 15276 |
| 013989 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:16pm | Sensor | 1797-S0024-G-TJV.cor | 6800.3 | 1592874.1 | 510697.5 | 18818 | 1.64041666667 | 13989 |
| 015407 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592871.4 | 510697.7 | 18820 | 1.64041666667 | 15407 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:18pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592868.7 | 510698.1 | 18822 | 1.64041666667 | 14591 |
| 015528 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:19pm | Sensor | 1797-S0024-G-TJV.cor | 6798.8 | 1592866.0 | 510697.8 | 18824 | 1.64041666667 | 15528 |
| 014502 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:20pm | Sensor | 1797-S0024-G-TJV.cor | 6800.5 | 1592862.4 | 510696.8 | 18826 | 1.64041666667 | 14502 |
| 015265 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592859.2 | 510695.8 | 18828 | 1.64041666667 | 15265 |
| 014136 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592856.8 | 510695.4 | 18830 | 1.64041666667 | 14136 |
| 012864 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:23pm | Sensor | 1797-S0024-G-TJV.cor | 6798.7 | 1592854.7 | 510695.4 | 18832 | 1.64041666667 | 12864 |
| 014166 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:24pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592851.2 | 510693.9 | 18834 | 1.64041666667 | 14166 |
| 016231 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592847.8 | 510692.6 | 18836 | 1.64041666667 | 16231 |
| 014887 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592844.7 | 510691.9 | 18838 | 1.64041666667 | 14887 |
| 013562 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592841.9 | 510691.0 | 18840 | 1.64041666667 | 13562 |
| 014160 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592838.5 | 510690.2 | 18842 | 1.64041666667 | 14160 |
| 015390 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592835.5 | 510689.1 | 18844 | 1.64041666667 | 15390 |
| 014887 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592832.4 | 510688.2 | 18846 | 1.64041666667 | 14887 |
| 013532 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:31pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592829.8 | 510687.9 | 18848 | 1.64041666667 | 13532 |
| 013523 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:32pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592826.7 | 510687.3 | 18850 | 1.64041666667 | 13523 |
| 015980 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592824.1 | 510687.0 | 18852 | 1.64041666667 | 15980 |
| 015125 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592820.7 | 510686.1 | 18854 | 1.64041666667 | 15125 |
| 013951 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592817.9 | 510685.2 | 18856 | 1.64041666667 | 13951 |
| 014077 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:36pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592815.1 | 510684.2 | 18858 | 1.64041666667 | 14077 |
| 014949 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:37pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592812.3 | 510683.1 | 18860 | 1.64041666667 | 14949 |
| 015467 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592809.1 | 510682.0 | 18862 | 1.64041666667 | 15467 |
| 014486 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:39pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592806.4 | 510680.9 | 18864 | 1.64041666667 | 14486 |
| 015441 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:40pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592803.5 | 510679.9 | 18866 | 1.64041666667 | 15441 |
| 017450 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:41pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592801.2 | 510678.9 | 18868 | 1.64041666667 | 17450 |
| 016092 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:42pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592798.7 | 510677.2 | 18870 | 1.64041666667 | 16092 |
| 015363 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:43pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592796.2 | 510676.0 | 18872 | 1.64041666667 | 15363 |
| 015240 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:44pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592792.8 | 510674.7 | 18874 | 1.64041666667 | 15240 |
| 015690 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:45pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592790.3 | 510674.0 | 18876 | 1.64041666667 | 15690 |
| 016522 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:46pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592787.3 | 510673.4 | 18878 | 1.64041666667 | 16522 |
| 015650 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:47pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592784.4 | 510672.9 | 18880 | 1.64041666667 | 15650 |
| 016122 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:48pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592781.2 | 510672.7 | 18882 | 1.64041666667 | 16122 |
| 015010 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:49pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592778.4 | 510672.1 | 18884 | 1.64041666667 | 15010 |
| 013862 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:50pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592775.9 | 510671.1 | 18886 | 1.64041666667 | 13862 |
| 014145 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:51pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592773.4 | 510669.9 | 18888 | 1.64041666667 | 14145 |
| 013736 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:52pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592770.9 | 510668.3 | 18890 | 1.64041666667 | 13736 |
| 012674 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:53pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592768.3 | 510667.0 | 18892 | 1.64041666667 | 12674 |
| 013638 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:54pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592765.4 | 510665.6 | 18894 | 1.64041666667 | 13638 |
| 013339 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:55pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592762.9 | 510664.6 | 18896 | 1.64041666667 | 13339 |
| 012664 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:56pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592760.0 | 510663.8 | 18898 | 1.64041666667 | 12664 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013936 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:57pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592757.6 | 510662.7 | 18900 | 1.64041666667 | 13936 |
| 013144 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592755.6 | 510661.7 | 18902 | 1.64041666667 | 13144 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 01:14:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592755.2 | 510660.8 | 18904 | 1.64041666667 | 14266 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592756.5 | 510659.1 | 18906 | 1.64041666667 | 14426 |
| 014526 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:01pm | Sensor | 1797-S0024-G-TJV.cor | 6800.7 | 1592757.2 | 510657.7 | 18908 | 1.64041666667 | 14526 |
| 014041 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:02pm | Sensor | 1797-S0024-G-TJV.cor | 6798.0 | 1592757.5 | 510657.4 | 18910 | 1.64041666667 | 14041 |
| 015360 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:03pm | Sensor | 1797-S0024-G-TJV.cor | 6797.9 | 1592758.3 | 510656.5 | 18912 | 1.64041666667 | 15360 |
| 015090 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:04pm | Sensor | 1797-S0024-G-TJV.cor | 6799.5 | 1592759.5 | 510653.1 | 18914 | 1.64041666667 | 15090 |
| 014542 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:05pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592759.8 | 510650.3 | 18916 | 1.64041666667 | 14542 |
| 014555 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:06pm | Sensor | 1797-S0024-G-TJV.cor | 6799.3 | 1592760.1 | 510650.8 | 18918 | 1.64041666667 | 14555 |
| 013389 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:07pm | Sensor | 1797-S0024-G-TJV.cor | 6797.8 | 1592759.8 | 510652.7 | 18920 | 1.64041666667 | 13389 |
| 015677 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:08pm | Sensor | 1797-S0024-G-TJV.cor | 6798.0 | 1592758.8 | 510654.2 | 18922 | 1.64041666667 | 15677 |
| 013129 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:09pm | Sensor | 1797-S0024-G-TJV.cor | 6798.0 | 1592758.3 | 510654.9 | 18924 | 1.64041666667 | 13129 |
| 015042 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:10pm | Sensor | 1797-S0024-G-TJV.cor | 6798.0 | 1592757.8 | 510655.4 | 18926 | 1.64041666667 | 15042 |
| 014560 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:11pm | Sensor | 1797-S0024-G-TJV.cor | 6798.0 | 1592757.6 | 510655.2 | 18928 | 1.64041666667 | 14560 |
| 014380 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:12pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592757.1 | 510654.4 | 18930 | 1.64041666667 | 14380 |
| 013105 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592756.9 | 510654.1 | 18932 | 1.64041666667 | 13105 |
| 014256 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592758.6 | 510656.6 | 18934 | 1.64041666667 | 14256 |
| 014964 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592760.9 | 510658.0 | 18936 | 1.64041666667 | 14964 |
| 014421 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592763.9 | 510659.2 | 18938 | 1.64041666667 | 14421 |
| 015905 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592766.1 | 510660.1 | 18940 | 1.64041666667 | 15905 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592769.1 | 510660.2 | 18942 | 1.64041666667 | 14626 |
| 013136 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592771.9 | 510660.6 | 18944 | 1.64041666667 | 13136 |
| 014234 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592774.9 | 510661.3 | 18946 | 1.64041666667 | 14234 |
| 013908 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592777.5 | 510662.1 | 18948 | 1.64041666667 | 13908 |
| 015237 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:22pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592780.7 | 510663.6 | 18950 | 1.64041666667 | 15237 |
| 016859 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:23pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592783.3 | 510664.6 | 18952 | 1.64041666667 | 16859 |
| 015645 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592786.4 | 510665.4 | 18954 | 1.64041666667 | 15645 |
| 015551 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592788.9 | 510666.1 | 18956 | 1.64041666667 | 15551 |
| 015017 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:26pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592792.2 | 510666.7 | 18958 | 1.64041666667 | 15017 |
| 015334 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:27pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592795.1 | 510667.7 | 18960 | 1.64041666667 | 15334 |
| 017123 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592798.0 | 510668.8 | 18962 | 1.64041666667 | 17123 |
| 015561 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592800.7 | 510669.4 | 18964 | 1.64041666667 | 15561 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592803.8 | 510670.1 | 18966 | 1.64041666667 | 14570 |
| 014082 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:31pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592806.4 | 510670.2 | 18968 | 1.64041666667 | 14082 |
| 014200 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:32pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592809.7 | 510670.3 | 18970 | 1.64041666667 | 14200 |
| 013240 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:33pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592812.4 | 510670.6 | 18972 | 1.64041666667 | 13240 |
| 015640 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592815.4 | 510671.1 | 18974 | 1.64041666667 | 15640 |
| 015340 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592818.1 | 510672.5 | 18976 | 1.64041666667 | 15340 |
| 014845 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:36pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592821.0 | 510673.6 | 18978 | 1.64041666667 | 14845 |
| 013821 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592823.7 | 510674.6 | 18980 | 1.64041666667 | 13821 |
| 014555 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592826.4 | 510675.3 | 18982 | 1.64041666667 | 14555 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592828.9 | 510675.4 | 18984 | 1.64041666667 | 14078 |
| 013509 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592831.4 | 510675.7 | 18986 | 1.64041666667 | 13509 |
| 013367 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592833.6 | 510676.1 | 18988 | 1.64041666667 | 13367 |
| 014441 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592835.8 | 510677.0 | 18990 | 1.64041666667 | 14441 |
| 013750 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592837.5 | 510678.0 | 18992 | 1.64041666667 | 13750 |
| 015947 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592839.4 | 510679.1 | 18994 | 1.64041666667 | 15947 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014096 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592841.3 | 510679.9 | 18996 | 1.64041666667 | 14096 |
| 014204 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592843.5 | 510681.3 | 18998 | 1.64041666667 | 14204 |
| 014771 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:47pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592846.1 | 510682.6 | 19000 | 1.64041666667 | 14771 |
| 014492 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:48pm | Sensor | 1797-S0024-G-TJV.cor | 6798.5 | 1592849.6 | 510684.4 | 19002 | 1.64041666667 | 14492 |
| 014603 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:49pm | Sensor | 1797-S0024-G-TJV.cor | 6798.5 | 1592852.3 | 510685.1 | 19004 | 1.64041666667 | 14603 |
| 016310 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:50pm | Sensor | 1797-S0024-G-TJV.cor | 6798.5 | 1592855.2 | 510686.1 | 19006 | 1.64041666667 | 16310 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:51pm | Sensor | 1797-S0024-G-TJV.cor | 6798.7 | 1592857.6 | 510687.0 | 19008 | 1.64041666667 | 14067 |
| 015187 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:52pm | Sensor | 1797-S0024-G-TJV.cor | 6798.8 | 1592860.3 | 510688.0 | 19010 | 1.64041666667 | 15187 |
| 014536 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:53pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592862.3 | 510688.8 | 19012 | 1.64041666667 | 14536 |
| 014614 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:54pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592865.0 | 510689.6 | 19014 | 1.64041666667 | 14614 |
| 013973 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:55pm | Sensor | 1797-S0024-G-TJV.cor | 6799.0 | 1592868.2 | 510691.3 | 19016 | 1.64041666667 | 13973 |
| 014203 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:56pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592871.1 | 510692.5 | 19018 | 1.64041666667 | 14203 |
| 014561 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:57pm | Sensor | 1797-S0024-G-TJV.cor | 6799.4 | 1592873.5 | 510693.0 | 19020 | 1.64041666667 | 14561 |
| 015340 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:58pm | Sensor | 1797-S0024-G-TJV.cor | 6799.5 | 1592875.7 | 510693.5 | 19022 | 1.64041666667 | 15340 |
| 016855 | 0 | GeoXH 6000 | 08/18/2015 | 01:15:59pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592877.0 | 510693.1 | 19024 | 1.64041666667 | 16855 |
| 015253 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:00pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592877.4 | 510693.0 | 19026 | 1.64041666667 | 15253 |
| 015303 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:01pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592877.5 | 510693.2 | 19028 | 1.64041666667 | 15303 |
| 015795 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:02pm | Sensor | 1797-S0024-G-TJV.cor | 6798.7 | 1592877.1 | 510693.5 | 19030 | 1.64041666667 | 15795 |
| 015048 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:03pm | Sensor | 1797-S0024-G-TJV.cor | 6799.4 | 1592876.7 | 510693.4 | 19032 | 1.64041666667 | 15048 |
| 015402 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:04pm | Sensor | 1797-S0024-G-TJV.cor | 6799.7 | 1592878.3 | 510693.3 | 19034 | 1.64041666667 | 15402 |
| 013570 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:05pm | Sensor | 1797-S0024-G-TJV.cor | 6798.6 | 1592880.1 | 510693.1 | 19036 | 1.64041666667 | 13570 |
| 013802 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:06pm | Sensor | 1797-S0024-G-TJV.cor | 6797.9 | 1592880.7 | 510693.1 | 19038 | 1.64041666667 | 13802 |
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:07pm | Sensor | 1797-S0024-G-TJV.cor | 6798.7 | 1592879.6 | 510693.4 | 19040 | 1.64041666667 | 13320 |
| 013200 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:08pm | Sensor | 1797-S0024-G-TJV.cor | 6799.0 | 1592878.1 | 510693.9 | 19042 | 1.64041666667 | 13200 |
| 015660 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:09pm | Sensor | 1797-S0024-G-TJV.cor | 6799.0 | 1592878.5 | 510694.0 | 19044 | 1.64041666667 | 15660 |
| 013725 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:10pm | Sensor | 1797-S0024-G-TJV.cor | 6799.1 | 1592878.6 | 510693.6 | 19046 | 1.64041666667 | 13725 |
| 015442 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:11pm | Sensor | 1797-S0024-G-TJV.cor | 6799.3 | 1592877.8 | 510692.4 | 19048 | 1.64041666667 | 15442 |
| 015820 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:12pm | Sensor | 1797-S0024-G-TJV.cor | 6799.2 | 1592876.6 | 510691.1 | 19050 | 1.64041666667 | 15820 |
| 015205 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:13pm | Sensor | 1797-S0024-G-TJV.cor | 6800.4 | 1592874.0 | 510689.3 | 19052 | 1.64041666667 | 15205 |
| 015351 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592870.2 | 510687.4 | 19054 | 1.64041666667 | 15351 |
| 014877 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592867.8 | 510686.6 | 19056 | 1.64041666667 | 14877 |
| 016229 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592864.7 | 510685.7 | 19058 | 1.64041666667 | 16229 |
| 015847 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592862.5 | 510684.6 | 19060 | 1.64041666667 | 15847 |
| 014551 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592859.7 | 510683.2 | 19062 | 1.64041666667 | 14551 |
| 015097 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592857.5 | 510682.3 | 19064 | 1.64041666667 | 15097 |
| 017034 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592855.4 | 510681.0 | 19066 | 1.64041666667 | 17034 |
| 016588 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592853.5 | 510680.1 | 19068 | 1.64041666667 | 16588 |
| 014737 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592852.1 | 510679.0 | 19070 | 1.64041666667 | 14737 |
| 015414 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592851.6 | 510678.2 | 19072 | 1.64041666667 | 15414 |
| 014473 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592851.4 | 510678.0 | 19074 | 1.64041666667 | 14473 |
| 014448 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592851.5 | 510678.2 | 19076 | 1.64041666667 | 14448 |
| 014952 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592851.5 | 510678.3 | 19078 | 1.64041666667 | 14952 |
| 016698 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592851.7 | 510678.3 | 19080 | 1.64041666667 | 16698 |
| 015364 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592851.8 | 510678.9 | 19082 | 1.64041666667 | 15364 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592850.6 | 510680.1 | 19084 | 1.64041666667 | 13471 |
| 014137 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592848.4 | 510680.8 | 19086 | 1.64041666667 | 14137 |
| 014304 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592846.3 | 510681.3 | 19088 | 1.64041666667 | 14304 |
| 014466 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592843.9 | 510680.9 | 19090 | 1.64041666667 | 14466 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013906 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592842.1 | 510680.4 | 19092 | 1.64041666667 | 13906 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592840.1 | 510679.0 | 19094 | 1.64041666667 | 14456 |
| 016604 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592837.9 | 510677.5 | 19096 | 1.64041666667 | 16604 |
| 016001 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592835.3 | 510676.0 | 19098 | 1.64041666667 | 16001 |
| 014230 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592833.3 | 510675.2 | 19100 | 1.64041666667 | 14230 |
| 014957 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592830.4 | 510674.9 | 19102 | 1.64041666667 | 14957 |
| 015679 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:39pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592827.8 | 510674.3 | 19104 | 1.64041666667 | 15679 |
| 014959 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592824.5 | 510673.5 | 19106 | 1.64041666667 | 14959 |
| 014120 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592822.0 | 510672.9 | 19108 | 1.64041666667 | 14120 |
| 013610 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592819.6 | 510672.2 | 19110 | 1.64041666667 | 13610 |
| 014892 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592817.2 | 510671.7 | 19112 | 1.64041666667 | 14892 |
| 014793 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592814.6 | 510670.6 | 19114 | 1.64041666667 | 14793 |
| 014528 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592812.3 | 510669.5 | 19116 | 1.64041666667 | 14528 |
| 014492 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592809.8 | 510667.3 | 19118 | 1.64041666667 | 14492 |
| 016073 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592808.0 | 510666.0 | 19120 | 1.64041666667 | 16073 |
| 015628 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592805.4 | 510665.0 | 19122 | 1.64041666667 | 15628 |
| 014527 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592803.2 | 510664.2 | 19124 | 1.64041666667 | 14527 |
| 014251 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592800.8 | 510663.5 | 19126 | 1.64041666667 | 14251 |
| 014122 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592798.6 | 510662.6 | 19128 | 1.64041666667 | 14122 |
| 013880 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592796.0 | 510661.8 | 19130 | 1.64041666667 | 13880 |
| 013850 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592793.8 | 510660.6 | 19132 | 1.64041666667 | 13850 |
| 015162 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592791.1 | 510659.5 | 19134 | 1.64041666667 | 15162 |
| 015381 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:55pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592788.7 | 510658.5 | 19136 | 1.64041666667 | 15381 |
| 015707 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592785.9 | 510657.4 | 19138 | 1.64041666667 | 15707 |
| 014246 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592783.5 | 510656.9 | 19140 | 1.64041666667 | 14246 |
| 016401 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592780.7 | 510656.2 | 19142 | 1.64041666667 | 16401 |
| 014570 | 0 | GeoXH 6000 | 08/18/2015 | 01:16:59pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592778.5 | 510656.1 | 19144 | 1.64041666667 | 14570 |
| 014382 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592775.9 | 510655.7 | 19146 | 1.64041666667 | 14382 |
| 014845 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592773.6 | 510655.6 | 19148 | 1.64041666667 | 14845 |
| 014421 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592771.0 | 510655.1 | 19150 | 1.64041666667 | 14421 |
| 014195 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592768.6 | 510654.8 | 19152 | 1.64041666667 | 14195 |
| 016118 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592765.7 | 510653.9 | 19154 | 1.64041666667 | 16118 |
| 015459 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592763.8 | 510652.8 | 19156 | 1.64041666667 | 15459 |
| 015145 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592761.2 | 510651.6 | 19158 | 1.64041666667 | 15145 |
| 015636 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592759.7 | 510650.6 | 19160 | 1.64041666667 | 15636 |
| 015069 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592760.4 | 510650.8 | 19162 | 1.64041666667 | 15069 |
| 014417 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592759.8 | 510651.1 | 19164 | 1.64041666667 | 14417 |
| 014884 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592759.8 | 510651.2 | 19166 | 1.64041666667 | 14884 |
| 013891 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592759.8 | 510651.2 | 19168 | 1.64041666667 | 13891 |
| 014932 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592760.6 | 510651.5 | 19170 | 1.64041666667 | 14932 |
| 014893 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592762.2 | 510652.0 | 19172 | 1.64041666667 | 14893 |
| 015093 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592764.5 | 510652.4 | 19174 | 1.64041666667 | 15093 |
| 015203 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592766.8 | 510652.3 | 19176 | 1.64041666667 | 15203 |
| 014780 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592769.8 | 510652.4 | 19178 | 1.64041666667 | 14780 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592772.8 | 510652.1 | 19180 | 1.64041666667 | 13295 |
| 012653 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:18pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592776.2 | 510651.8 | 19182 | 1.64041666667 | 12653 |
| 012883 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592779.1 | 510652.0 | 19184 | 1.64041666667 | 12883 |
| 014021 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592782.7 | 510652.1 | 19186 | 1.64041666667 | 14021 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013975 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592785.6 | 510652.2 | 19188 | 1.64041666667 | 13975 |
| 014593 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592789.3 | 510652.4 | 19190 | 1.64041666667 | 14593 |
| 014058 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592792.2 | 510652.6 | 19192 | 1.64041666667 | 14058 |
| 014464 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592795.7 | 510653.3 | 19194 | 1.64041666667 | 14464 |
| 015226 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592798.5 | 510654.3 | 19196 | 1.64041666667 | 15226 |
| 014816 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592801.5 | 510655.7 | 19198 | 1.64041666667 | 14816 |
| 016184 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592804.2 | 510657.0 | 19200 | 1.64041666667 | 16184 |
| 015776 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:28pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592807.0 | 510658.9 | 19202 | 1.64041666667 | 15776 |
| 014024 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:29pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592809.1 | 510661.0 | 19204 | 1.64041666667 | 14024 |
| 014426 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592811.9 | 510663.5 | 19206 | 1.64041666667 | 14426 |
| 014436 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:31pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592813.9 | 510665.3 | 19208 | 1.64041666667 | 14436 |
| 013509 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592816.2 | 510668.2 | 19210 | 1.64041666667 | 13509 |
| 012887 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592817.9 | 510670.3 | 19212 | 1.64041666667 | 12887 |
| 012971 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592819.7 | 510672.7 | 19214 | 1.64041666667 | 12971 |
| 014643 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592820.3 | 510675.0 | 19216 | 1.64041666667 | 14643 |
| 012630 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592819.9 | 510677.7 | 19218 | 1.64041666667 | 12630 |
| 014647 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592819.1 | 510680.0 | 19220 | 1.64041666667 | 14647 |
| 013232 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592818.1 | 510682.5 | 19222 | 1.64041666667 | 13232 |
| 015878 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592816.8 | 510684.9 | 19224 | 1.64041666667 | 15878 |
| 017109 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592814.9 | 510687.1 | 19226 | 1.64041666667 | 17109 |
| 015287 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592813.1 | 510689.1 | 19228 | 1.64041666667 | 15287 |
| 015191 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592811.9 | 510691.8 | 19230 | 1.64041666667 | 15191 |
| 015648 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592811.0 | 510694.4 | 19232 | 1.64041666667 | 15648 |
| 014922 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:44pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592810.8 | 510697.7 | 19234 | 1.64041666667 | 14922 |
| 014350 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592811.3 | 510700.5 | 19236 | 1.64041666667 | 14350 |
| 015857 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592811.9 | 510703.0 | 19238 | 1.64041666667 | 15857 |
| 016234 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592812.6 | 510705.2 | 19240 | 1.64041666667 | 16234 |
| 014048 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592812.8 | 510708.2 | 19242 | 1.64041666667 | 14048 |
| 012872 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592812.9 | 510710.5 | 19244 | 1.64041666667 | 12872 |
| 013928 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592812.5 | 510713.7 | 19246 | 1.64041666667 | 13928 |
| 012692 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592812.3 | 510716.2 | 19248 | 1.64041666667 | 12692 |
| 014663 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592811.9 | 510719.6 | 19250 | 1.64041666667 | 14663 |
| 014015 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592811.4 | 510722.0 | 19252 | 1.64041666667 | 14015 |
| 015414 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592811.5 | 510724.7 | 19254 | 1.64041666667 | 15414 |
| 014473 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:55pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592811.1 | 510727.3 | 19256 | 1.64041666667 | 14473 |
| 017358 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:56pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592810.5 | 510730.0 | 19258 | 1.64041666667 | 17358 |
| 015319 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:57pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592809.5 | 510732.0 | 19260 | 1.64041666667 | 15319 |
| 017959 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:58pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592808.3 | 510734.5 | 19262 | 1.64041666667 | 17959 |
| 017720 | 0 | GeoXH 6000 | 08/18/2015 | 01:17:59pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592808.3 | 510736.8 | 19264 | 1.64041666667 | 17720 |
| 015260 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:00pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592808.1 | 510739.2 | 19266 | 1.64041666667 | 15260 |
| 013895 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:01pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592808.2 | 510741.6 | 19268 | 1.64041666667 | 13895 |
| 013433 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:02pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592807.9 | 510744.5 | 19270 | 1.64041666667 | 13433 |
| 013588 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:03pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592807.6 | 510746.7 | 19272 | 1.64041666667 | 13588 |
| 013147 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:04pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592807.1 | 510749.6 | 19274 | 1.64041666667 | 13147 |
| 013216 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:05pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592806.5 | 510751.4 | 19276 | 1.64041666667 | 13216 |
| 013534 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:06pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592806.5 | 510751.7 | 19278 | 1.64041666667 | 13534 |
| 012473 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592806.6 | 510751.0 | 19280 | 1.64041666667 | 12473 |
| 015058 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592807.1 | 510749.9 | 19282 | 1.64041666667 | 15058 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013694 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:09pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592808.2 | 510750.2 | 19284 | 1.64041666667 | 13694 |
| 013263 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:10pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592809.4 | 510751.6 | 19286 | 1.64041666667 | 13263 |
| 012225 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592811.3 | 510753.0 | 19288 | 1.64041666667 | 12225 |
| 015806 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592813.4 | 510754.6 | 19290 | 1.64041666667 | 15806 |
| 014421 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592815.2 | 510756.2 | 19292 | 1.64041666667 | 14421 |
| 015275 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592817.6 | 510757.5 | 19294 | 1.64041666667 | 15275 |
| 015608 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592819.8 | 510758.7 | 19296 | 1.64041666667 | 15608 |
| 014132 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:16pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592822.3 | 510759.1 | 19298 | 1.64041666667 | 14132 |
| 014003 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:17pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592824.3 | 510759.3 | 19300 | 1.64041666667 | 14003 |
| 014300 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:18pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592826.7 | 510759.3 | 19302 | 1.64041666667 | 14300 |
| 014855 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:19pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592828.6 | 510759.5 | 19304 | 1.64041666667 | 14855 |
| 014363 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:20pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592830.7 | 510759.7 | 19306 | 1.64041666667 | 14363 |
| 013431 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:21pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592832.7 | 510760.6 | 19308 | 1.64041666667 | 13431 |
| 013557 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592835.2 | 510761.6 | 19310 | 1.64041666667 | 13557 |
| 013589 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592837.1 | 510762.9 | 19312 | 1.64041666667 | 13589 |
| 013027 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592839.5 | 510764.2 | 19314 | 1.64041666667 | 13027 |
| 013396 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592841.9 | 510764.9 | 19316 | 1.64041666667 | 13396 |
| 015199 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:26pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592844.5 | 510765.3 | 19318 | 1.64041666667 | 15199 |
| 014959 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:27pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592846.7 | 510765.2 | 19320 | 1.64041666667 | 14959 |
| 013610 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:28pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592849.4 | 510765.7 | 19322 | 1.64041666667 | 13610 |
| 014322 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:29pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592851.3 | 510766.1 | 19324 | 1.64041666667 | 14322 |
| 013150 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:30pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592852.7 | 510767.4 | 19326 | 1.64041666667 | 13150 |
| 012047 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:31pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592853.7 | 510769.0 | 19328 | 1.64041666667 | 12047 |
| 012521 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:32pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592853.2 | 510771.3 | 19330 | 1.64041666667 | 12521 |
| 013420 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:33pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592852.5 | 510773.2 | 19332 | 1.64041666667 | 13420 |
| 012655 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:34pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592851.4 | 510774.8 | 19334 | 1.64041666667 | 12655 |
| 012763 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:35pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592850.7 | 510775.7 | 19336 | 1.64041666667 | 12763 |
| 013271 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:36pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592850.4 | 510776.7 | 19338 | 1.64041666667 | 13271 |
| 012947 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:37pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592850.0 | 510777.5 | 19340 | 1.64041666667 | 12947 |
| 013016 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:38pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592849.3 | 510778.0 | 19342 | 1.64041666667 | 13016 |
| 013784 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:39pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592849.1 | 510778.0 | 19344 | 1.64041666667 | 13784 |
| 014666 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:40pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592848.0 | 510777.7 | 19346 | 1.64041666667 | 14666 |
| 013416 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:41pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592846.8 | 510776.7 | 19348 | 1.64041666667 | 13416 |
| 013044 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:42pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592844.9 | 510775.9 | 19350 | 1.64041666667 | 13044 |
| 012831 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:43pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592843.6 | 510774.7 | 19352 | 1.64041666667 | 12831 |
| 013377 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:44pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592841.2 | 510773.6 | 19354 | 1.64041666667 | 13377 |
| 013574 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:45pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592839.6 | 510772.4 | 19356 | 1.64041666667 | 13574 |
| 014793 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:46pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592837.6 | 510771.1 | 19358 | 1.64041666667 | 14793 |
| 015578 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:47pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592836.2 | 510769.5 | 19360 | 1.64041666667 | 15578 |
| 014544 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:48pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592834.1 | 510767.4 | 19362 | 1.64041666667 | 14544 |
| 013866 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:49pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592832.3 | 510766.1 | 19364 | 1.64041666667 | 13866 |
| 012556 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:50pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592830.5 | 510765.0 | 19366 | 1.64041666667 | 12556 |
| 012799 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:51pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592828.7 | 510765.3 | 19368 | 1.64041666667 | 12799 |
| 014539 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:52pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592826.6 | 510765.7 | 19370 | 1.64041666667 | 14539 |
| 015215 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:53pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592824.6 | 510766.3 | 19372 | 1.64041666667 | 15215 |
| 013073 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:54pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592822.9 | 510766.9 | 19374 | 1.64041666667 | 13073 |
| 012718 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:55pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592822.2 | 510768.3 | 19376 | 1.64041666667 | 12718 |
| 013409 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:56pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592821.0 | 510769.8 | 19378 | 1.64041666667 | 13409 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015982 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:57pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592820.3 | 510771.0 | 19380 | 1.64041666667 | 15982 |
| 013355 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:58pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592818.7 | 510771.1 | 19382 | 1.64041666667 | 13355 |
| 012368 | 0 | GeoXH 6000 | 08/18/2015 | 01:18:59pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592816.3 | 510771.0 | 19384 | 1.64041666667 | 12368 |
| 012812 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592814.4 | 510770.5 | 19386 | 1.64041666667 | 12812 |
| 012863 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592813.3 | 510770.2 | 19388 | 1.64041666667 | 12863 |
| 012725 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:02pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592812.3 | 510770.1 | 19390 | 1.64041666667 | 12725 |
| 012271 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:03pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592810.7 | 510770.5 | 19392 | 1.64041666667 | 12271 |
| 012367 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:04pm | Sensor | 1797-S0024-G-TJV.cor | 6803.2 | 1592809.0 | 510771.5 | 19394 | 1.64041666667 | 12367 |
| 012182 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:05pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592807.5 | 510773.1 | 19396 | 1.64041666667 | 12182 |
| 012705 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592805.9 | 510774.9 | 19398 | 1.64041666667 | 12705 |
| 012716 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592804.8 | 510776.7 | 19400 | 1.64041666667 | 12716 |
| 012899 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592804.2 | 510778.6 | 19402 | 1.64041666667 | 12899 |
| 012855 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:09pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592803.9 | 510779.9 | 19404 | 1.64041666667 | 12855 |
| 011733 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:10pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592803.4 | 510780.3 | 19406 | 1.64041666667 | 11733 |
| 011693 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:11pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592802.5 | 510778.6 | 19408 | 1.64041666667 | 11693 |
| 012343 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:12pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592801.7 | 510776.3 | 19410 | 1.64041666667 | 12343 |
| 012506 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:13pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592801.4 | 510773.7 | 19412 | 1.64041666667 | 12506 |
| 012816 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:14pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592800.6 | 510771.2 | 19414 | 1.64041666667 | 12816 |
| 013914 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:15pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592799.8 | 510769.2 | 19416 | 1.64041666667 | 13914 |
| 013858 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:16pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592799.2 | 510767.1 | 19418 | 1.64041666667 | 13858 |
| 013334 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:17pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592798.5 | 510765.6 | 19420 | 1.64041666667 | 13334 |
| 014493 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:18pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592797.8 | 510764.2 | 19422 | 1.64041666667 | 14493 |
| 014573 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:19pm | Sensor | 1797-S0024-G-TJV.cor | 6803.5 | 1592796.9 | 510763.5 | 19424 | 1.64041666667 | 14573 |
| 012853 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:20pm | Sensor | 1797-S0024-G-TJV.cor | 6803.6 | 1592795.4 | 510763.3 | 19426 | 1.64041666667 | 12853 |
| 013263 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:21pm | Sensor | 1797-S0024-G-TJV.cor | 6803.6 | 1592794.0 | 510763.6 | 19428 | 1.64041666667 | 13263 |
| 013515 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:22pm | Sensor | 1797-S0024-G-TJV.cor | 6803.7 | 1592793.1 | 510764.2 | 19430 | 1.64041666667 | 13515 |
| 013458 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:23pm | Sensor | 1797-S0024-G-TJV.cor | 6803.8 | 1592793.1 | 510763.9 | 19432 | 1.64041666667 | 13458 |
| 015934 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:24pm | Sensor | 1797-S0024-G-TJV.cor | 6803.8 | 1592793.1 | 510763.8 | 19434 | 1.64041666667 | 15934 |
| 013913 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:25pm | Sensor | 1797-S0024-G-TJV.cor | 6803.8 | 1592793.0 | 510763.8 | 19436 | 1.64041666667 | 13913 |
| 012988 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:26pm | Sensor | 1797-S0024-G-TJV.cor | 6803.7 | 1592792.3 | 510763.3 | 19438 | 1.64041666667 | 12988 |
| 013357 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:27pm | Sensor | 1797-S0024-G-TJV.cor | 6803.8 | 1592791.0 | 510762.5 | 19440 | 1.64041666667 | 13357 |
| 015339 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:28pm | Sensor | 1797-S0024-G-TJV.cor | 6803.8 | 1592789.5 | 510761.6 | 19442 | 1.64041666667 | 15339 |
| 013374 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:29pm | Sensor | 1797-S0024-G-TJV.cor | 6803.6 | 1592787.8 | 510761.0 | 19444 | 1.64041666667 | 13374 |
| 014503 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:30pm | Sensor | 1797-S0024-G-TJV.cor | 6803.3 | 1592786.1 | 510760.1 | 19446 | 1.64041666667 | 14503 |
| 013826 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:31pm | Sensor | 1797-S0024-G-TJV.cor | 6803.4 | 1592784.5 | 510759.4 | 19448 | 1.64041666667 | 13826 |
| 013326 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:32pm | Sensor | 1797-S0024-G-TJV.cor | 6803.1 | 1592782.9 | 510757.9 | 19450 | 1.64041666667 | 13326 |
| 014371 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592781.1 | 510757.1 | 19452 | 1.64041666667 | 14371 |
| 015652 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592779.6 | 510755.2 | 19454 | 1.64041666667 | 15652 |
| 016633 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592777.7 | 510753.8 | 19456 | 1.64041666667 | 16633 |
| 014358 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592776.2 | 510752.1 | 19458 | 1.64041666667 | 14358 |
| 013489 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592774.3 | 510750.7 | 19460 | 1.64041666667 | 13489 |
| 015432 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592772.6 | 510749.1 | 19462 | 1.64041666667 | 15432 |
| 014538 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592771.3 | 510747.8 | 19464 | 1.64041666667 | 14538 |
| 012904 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592769.8 | 510746.2 | 19466 | 1.64041666667 | 12904 |
| 014326 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592768.1 | 510745.0 | 19468 | 1.64041666667 | 14326 |
| 014711 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592765.8 | 510744.2 | 19470 | 1.64041666667 | 14711 |
| 015318 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592763.8 | 510743.7 | 19472 | 1.64041666667 | 15318 |
| 014209 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592761.5 | 510744.2 | 19474 | 1.64041666667 | 14209 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013482 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:45pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592759.9 | 510744.5 | 19476 | 1.64041666667 | 13482 |
| 014230 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592757.6 | 510745.0 | 19478 | 1.64041666667 | 14230 |
| 016007 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592755.7 | 510744.9 | 19480 | 1.64041666667 | 16007 |
| 014591 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592753.7 | 510745.2 | 19482 | 1.64041666667 | 14591 |
| 014358 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592752.0 | 510745.2 | 19484 | 1.64041666667 | 14358 |
| 015379 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592750.6 | 510746.7 | 19486 | 1.64041666667 | 15379 |
| 014644 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:51pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592750.4 | 510748.9 | 19488 | 1.64041666667 | 14644 |
| 014221 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:52pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592751.3 | 510751.5 | 19490 | 1.64041666667 | 14221 |
| 014925 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:53pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592751.5 | 510753.7 | 19492 | 1.64041666667 | 14925 |
| 014501 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:54pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592750.5 | 510755.8 | 19494 | 1.64041666667 | 14501 |
| 015925 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:55pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592748.7 | 510757.1 | 19496 | 1.64041666667 | 15925 |
| 015201 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:56pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592745.6 | 510758.4 | 19498 | 1.64041666667 | 15201 |
| 013400 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:57pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592743.3 | 510760.1 | 19500 | 1.64041666667 | 13400 |
| 013340 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:58pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592741.6 | 510761.6 | 19502 | 1.64041666667 | 13340 |
| 013745 | 0 | GeoXH 6000 | 08/18/2015 | 01:19:59pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592741.2 | 510762.0 | 19504 | 1.64041666667 | 13745 |
| 013696 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:00pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592741.7 | 510761.2 | 19506 | 1.64041666667 | 13696 |
| 013324 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:01pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592742.4 | 510759.4 | 19508 | 1.64041666667 | 13324 |
| 013831 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:02pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592743.5 | 510757.7 | 19510 | 1.64041666667 | 13831 |
| 013177 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:03pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592743.8 | 510756.9 | 19512 | 1.64041666667 | 13177 |
| 014694 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:04pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592743.5 | 510757.1 | 19514 | 1.64041666667 | 14694 |
| 015313 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.5 | 1592743.8 | 510757.3 | 19516 | 1.64041666667 | 15313 |
| 014748 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592744.0 | 510757.6 | 19518 | 1.64041666667 | 14748 |
| 013377 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:07pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592744.3 | 510757.7 | 19520 | 1.64041666667 | 13377 |
| 015464 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:08pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592744.9 | 510757.6 | 19522 | 1.64041666667 | 15464 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:09pm | Sensor | 1797-S0024-G-TJV.cor | 6801.5 | 1592745.3 | 510757.2 | 19524 | 1.64041666667 | 13526 |
| 013911 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:10pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592746.4 | 510756.0 | 19526 | 1.64041666667 | 13911 |
| 013407 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:11pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592747.5 | 510755.4 | 19528 | 1.64041666667 | 13407 |
| 012532 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:12pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592749.1 | 510754.7 | 19530 | 1.64041666667 | 12532 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:13pm | Sensor | 1797-S0024-G-TJV.cor | 6798.3 | 1592750.8 | 510754.8 | 19532 | 1.64041666667 | 13453 |
| 012753 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:14pm | Sensor | 1797-S0024-G-TJV.cor | 6801.9 | 1592751.6 | 510753.8 | 19534 | 1.64041666667 | 12753 |
| 013358 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:15pm | Sensor | 1797-S0024-G-TJV.cor | 6801.8 | 1592752.9 | 510754.3 | 19536 | 1.64041666667 | 13358 |
| 013809 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:16pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592754.9 | 510755.1 | 19538 | 1.64041666667 | 13809 |
| 013232 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:17pm | Sensor | 1797-S0024-G-TJV.cor | 6801.6 | 1592756.4 | 510756.2 | 19540 | 1.64041666667 | 13232 |
| 014618 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:18pm | Sensor | 1797-S0024-G-TJV.cor | 6801.7 | 1592757.9 | 510757.8 | 19542 | 1.64041666667 | 14618 |
| 013914 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:19pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592758.8 | 510759.5 | 19544 | 1.64041666667 | 13914 |
| 013828 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:20pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592760.4 | 510761.2 | 19546 | 1.64041666667 | 13828 |
| 013927 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:21pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592761.7 | 510762.8 | 19548 | 1.64041666667 | 13927 |
| 015301 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:22pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592763.9 | 510763.7 | 19550 | 1.64041666667 | 15301 |
| 013755 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:23pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592765.8 | 510764.4 | 19552 | 1.64041666667 | 13755 |
| 013818 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:24pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592768.2 | 510764.5 | 19554 | 1.64041666667 | 13818 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:25pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592770.4 | 510764.4 | 19556 | 1.64041666667 | 14314 |
| 015308 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:26pm | Sensor | 1797-S0024-G-TJV.cor | 6800.1 | 1592773.2 | 510764.1 | 19558 | 1.64041666667 | 15308 |
| 014237 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:27pm | Sensor | 1797-S0024-G-TJV.cor | 6798.7 | 1592775.2 | 510763.5 | 19560 | 1.64041666667 | 14237 |
| 014569 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:28pm | Sensor | 1797-S0024-G-TJV.cor | 6800.2 | 1592776.9 | 510762.7 | 19562 | 1.64041666667 | 14569 |
| 013752 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:29pm | Sensor | 1797-S0024-G-TJV.cor | 6798.9 | 1592778.6 | 510763.4 | 19564 | 1.64041666667 | 13752 |
| 015708 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:30pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592778.8 | 510764.0 | 19566 | 1.64041666667 | 15708 |
| 015237 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:31pm | Sensor | 1797-S0024-G-TJV.cor | 6803.0 | 1592779.9 | 510765.4 | 19568 | 1.64041666667 | 15237 |
| 015569 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:32pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592780.3 | 510767.4 | 19570 | 1.64041666667 | 15569 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015382 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:33pm | Sensor | 1797-S0024-G-TJV.cor | 6802.9 | 1592780.8 | 510769.2 | 19572 | 1.64041666667 | 15382 |
| 014765 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:34pm | Sensor | 1797-S0024-G-TJV.cor | 6802.8 | 1592780.9 | 510771.5 | 19574 | 1.64041666667 | 14765 |
| 013261 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:35pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592781.8 | 510773.5 | 19576 | 1.64041666667 | 13261 |
| 013785 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:36pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592782.7 | 510775.9 | 19578 | 1.64041666667 | 13785 |
| 013976 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:37pm | Sensor | 1797-S0024-G-TJV.cor | 6802.3 | 1592783.9 | 510777.2 | 19580 | 1.64041666667 | 13976 |
| 012224 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:38pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592786.0 | 510778.5 | 19582 | 1.64041666667 | 12224 |
| 014516 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:39pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592787.8 | 510779.1 | 19584 | 1.64041666667 | 14516 |
| 014549 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:40pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592790.0 | 510779.2 | 19586 | 1.64041666667 | 14549 |
| 015367 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:41pm | Sensor | 1797-S0024-G-TJV.cor | 6802.1 | 1592791.5 | 510779.4 | 19588 | 1.64041666667 | 15367 |
| 014851 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:42pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592793.3 | 510779.3 | 19590 | 1.64041666667 | 14851 |
| 013912 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:43pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592794.7 | 510779.4 | 19592 | 1.64041666667 | 13912 |
| 014638 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:44pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592796.5 | 510779.4 | 19594 | 1.64041666667 | 14638 |
| 013619 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:45pm | Sensor | 1797-S0024-G-TJV.cor | 6801.0 | 1592798.3 | 510780.1 | 19596 | 1.64041666667 | 13619 |
| 014205 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:46pm | Sensor | 1797-S0024-G-TJV.cor | 6798.3 | 1592800.7 | 510781.9 | 19598 | 1.64041666667 | 14205 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:47pm | Sensor | 1797-S0024-G-TJV.cor | 6799.9 | 1592801.6 | 510783.2 | 19600 | 1.64041666667 | 13631 |
| 012947 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:48pm | Sensor | 1797-S0024-G-TJV.cor | 6796.2 | 1592803.9 | 510785.7 | 19602 | 1.64041666667 | 12947 |
| 013616 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:49pm | Sensor | 1797-S0024-G-TJV.cor | 6797.6 | 1592804.8 | 510787.6 | 19604 | 1.64041666667 | 13616 |
| 013484 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:50pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592806.1 | 510789.0 | 19606 | 1.64041666667 | 13484 |
| 013271 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:51pm | Sensor | 1797-S0024-G-TJV.cor | 6797.4 | 1592808.0 | 510791.0 | 19608 | 1.64041666667 | 13271 |
| 013727 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:52pm | Sensor | 1797-S0024-G-TJV.cor | 6799.6 | 1592810.0 | 510791.3 | 19610 | 1.64041666667 | 13727 |
| 013061 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:53pm | Sensor | 1797-S0024-G-TJV.cor | 6796.2 | 1592812.8 | 510792.2 | 19612 | 1.64041666667 | 13061 |
| 014185 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:54pm | Sensor | 1797-S0024-G-TJV.cor | 6796.3 | 1592814.8 | 510791.5 | 19614 | 1.64041666667 | 14185 |
| 012756 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:55pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592815.6 | 510791.7 | 19616 | 1.64041666667 | 12756 |
| 014469 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:56pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592815.2 | 510791.2 | 19618 | 1.64041666667 | 14469 |
| 014807 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:57pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592815.7 | 510790.7 | 19620 | 1.64041666667 | 14807 |
| 012881 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:58pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592815.0 | 510788.7 | 19622 | 1.64041666667 | 12881 |
| 011950 | 0 | GeoXH 6000 | 08/18/2015 | 01:20:59pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592814.4 | 510786.6 | 19624 | 1.64041666667 | 11950 |
| 013307 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:00pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592813.0 | 510784.1 | 19626 | 1.64041666667 | 13307 |
| 012686 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:01pm | Sensor | 1797-S0024-G-TJV.cor | 6796.3 | 1592812.0 | 510782.0 | 19628 | 1.64041666667 | 12686 |
| 012231 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:02pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592810.7 | 510779.2 | 19630 | 1.64041666667 | 12231 |
| 012028 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:03pm | Sensor | 1797-S0024-G-TJV.cor | 6796.4 | 1592810.1 | 510776.3 | 19632 | 1.64041666667 | 12028 |
| 012247 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:04pm | Sensor | 1797-S0024-G-TJV.cor | 6798.4 | 1592808.5 | 510772.7 | 19634 | 1.64041666667 | 12247 |
| 012361 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:05pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592806.8 | 510769.8 | 19636 | 1.64041666667 | 12361 |
| 012270 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:06pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592805.9 | 510767.1 | 19638 | 1.64041666667 | 12270 |
| 013297 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:07pm | Sensor | 1797-S0024-G-TJV.cor | 6802.0 | 1592804.8 | 510764.5 | 19640 | 1.64041666667 | 13297 |
| 014394 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:08pm | Sensor | 1797-S0024-G-TJV.cor | 6802.2 | 1592804.3 | 510761.4 | 19642 | 1.64041666667 | 14394 |
| 013948 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:09pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592804.6 | 510758.8 | 19644 | 1.64041666667 | 13948 |
| 013807 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:10pm | Sensor | 1797-S0024-G-TJV.cor | 6796.9 | 1592805.2 | 510756.0 | 19646 | 1.64041666667 | 13807 |
| 012631 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:11pm | Sensor | 1797-S0024-G-TJV.cor | 6796.9 | 1592805.4 | 510753.1 | 19648 | 1.64041666667 | 12631 |
| 013417 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:12pm | Sensor | 1797-S0024-G-TJV.cor | 6797.1 | 1592806.2 | 510750.2 | 19650 | 1.64041666667 | 13417 |
| 013614 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:13pm | Sensor | 1797-S0024-G-TJV.cor | 6797.2 | 1592806.8 | 510747.6 | 19652 | 1.64041666667 | 13614 |
| 011743 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:14pm | Sensor | 1797-S0024-G-TJV.cor | 6797.2 | 1592808.0 | 510744.8 | 19654 | 1.64041666667 | 11743 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:15pm | Sensor | 1797-S0024-G-TJV.cor | 6797.1 | 1592808.5 | 510742.7 | 19656 | 1.64041666667 | 13526 |
| 015831 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:16pm | Sensor | 1797-S0024-G-TJV.cor | 6797.0 | 1592809.4 | 510740.0 | 19658 | 1.64041666667 | 15831 |
| 016017 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:17pm | Sensor | 1797-S0024-G-TJV.cor | 6797.0 | 1592810.2 | 510738.4 | 19660 | 1.64041666667 | 16017 |
| 017954 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:18pm | Sensor | 1797-S0024-G-TJV.cor | 6797.0 | 1592810.4 | 510737.4 | 19662 | 1.64041666667 | 17954 |
| 016998 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:19pm | Sensor | 1797-S0024-G-TJV.cor | 6796.8 | 1592810.8 | 510737.5 | 19664 | 1.64041666667 | 16998 |
| 016549 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:20pm | Sensor | 1797-S0024-G-TJV.cor | 6796.8 | 1592810.7 | 510737.5 | 19666 | 1.64041666667 | 16549 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 016377 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:21pm | Sensor | 1797-S0024-G-TJV.cor | 6796.9 | 1592810.7 | 510737.5 | 19668 | 1.64041666667 | 16377 |
| 016124 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:22pm | Sensor | 1797-S0024-G-TJV.cor | 6796.9 | 1592810.7 | 510737.4 | 19670 | 1.64041666667 | 16124 |
| 017471 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:23pm | Sensor | 1797-S0024-G-TJV.cor | 6796.9 | 1592810.7 | 510737.4 | 19672 | 1.64041666667 | 17471 |
| 016637 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:24pm | Sensor | 1797-S0024-G-TJV.cor | 6796.8 | 1592810.7 | 510737.4 | 19674 | 1.64041666667 | 16637 |
| 017119 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:25pm | Sensor | 1797-S0024-G-TJV.cor | 6796.8 | 1592810.7 | 510737.5 | 19676 | 1.64041666667 | 17119 |
| 017209 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:26pm | Sensor | 1797-S0024-G-TJV.cor | 6796.8 | 1592810.7 | 510737.5 | 19678 | 1.64041666667 | 17209 |
| 017622 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:27pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.8 | 510737.6 | 19679 | 1.64041666667 | 17622 |
| 016585 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:28pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.7 | 510737.6 | 19680 | 1.64041666667 | 16585 |
| 018936 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:29pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.7 | 510737.6 | 19681 | 1.64041666667 | 18936 |
| 017814 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:30pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.7 | 510737.6 | 19682 | 1.64041666667 | 17814 |
| 019933 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:31pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.7 | 510737.6 | 19683 | 1.64041666667 | 19933 |
| 018843 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:32pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.7 | 510737.5 | 19684 | 1.64041666667 | 18843 |
| 018420 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:33pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.8 | 510737.6 | 19685 | 1.64041666667 | 18420 |
| 018195 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:34pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.8 | 510737.6 | 19686 | 1.64041666667 | 18195 |
| 017148 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:35pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.8 | 510737.6 | 19687 | 1.64041666667 | 17148 |
| 017997 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:36pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.8 | 510737.7 | 19688 | 1.64041666667 | 17997 |
| 016589 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:37pm | Sensor | 1797-S0024-G-TJV.cor | 6796.7 | 1592810.8 | 510737.7 | 19689 | 1.64041666667 | 16589 |
| 018517 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:38pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.8 | 510737.8 | 19690 | 1.64041666667 | 18517 |
| 019179 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:39pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.7 | 510738.0 | 19691 | 1.64041666667 | 19179 |
| 018414 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:40pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.7 | 510738.0 | 19692 | 1.64041666667 | 18414 |
| 017083 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:41pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.8 | 510738.0 | 19693 | 1.64041666667 | 17083 |
| 018581 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:42pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.8 | 510738.0 | 19694 | 1.64041666667 | 18581 |
| 018925 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:43pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.8 | 510738.0 | 19695 | 1.64041666667 | 18925 |
| 017931 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:44pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.8 | 510738.0 | 19696 | 1.64041666667 | 17931 |
| 018222 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:45pm | Sensor | 1797-S0024-G-TJV.cor | 6797.8 | 1592810.5 | 510737.8 | 19697 | 1.64041666667 | 18222 |
| 019435 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:46pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592809.6 | 510737.1 | 19698 | 1.64041666667 | 19435 |
| 017399 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:47pm | Sensor | 1797-S0024-G-TJV.cor | 6802.7 | 1592809.7 | 510737.1 | 19699 | 1.64041666667 | 17399 |
| 018659 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:48pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592809.6 | 510737.1 | 19700 | 1.64041666667 | 18659 |
| 017745 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:49pm | Sensor | 1797-S0024-G-TJV.cor | 6802.6 | 1592809.6 | 510737.1 | 19701 | 1.64041666667 | 17745 |
| 017456 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:50pm | Sensor | 1797-S0024-G-TJV.cor | 6802.4 | 1592809.6 | 510737.1 | 19702 | 1.64041666667 | 17456 |
| 016334 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:51pm | Sensor | 1797-S0024-G-TJV.cor | 6800.9 | 1592809.9 | 510737.3 | 19703 | 1.64041666667 | 16334 |
| 016653 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:52pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.8 | 510738.0 | 19704 | 1.64041666667 | 16653 |
| 017723 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:53pm | Sensor | 1797-S0024-G-TJV.cor | 6796.5 | 1592810.7 | 510738.0 | 19705 | 1.64041666667 | 17723 |
| 018530 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:54pm | Sensor | 1797-S0024-G-TJV.cor | 6798.7 | 1592810.3 | 510737.7 | 19706 | 1.64041666667 | 18530 |
| 016092 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:55pm | Sensor | 1797-S0024-G-TJV.cor | 6801.2 | 1592809.9 | 510737.3 | 19707 | 1.64041666667 | 16092 |
| 017793 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:56pm | Sensor | 1797-S0024-G-TJV.cor | 6796.5 | 1592810.7 | 510738.1 | 19708 | 1.64041666667 | 17793 |
| 016358 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:57pm | Sensor | 1797-S0024-G-TJV.cor | 6796.5 | 1592810.7 | 510738.1 | 19709 | 1.64041666667 | 16358 |
| 016359 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:58pm | Sensor | 1797-S0024-G-TJV.cor | 6798.1 | 1592810.4 | 510737.8 | 19710 | 1.64041666667 | 16359 |
| 018370 | 0 | GeoXH 6000 | 08/18/2015 | 01:21:59pm | Sensor | 1797-S0024-G-TJV.cor | 6801.1 | 1592809.8 | 510737.3 | 19711 | 1.64041666667 | 18370 |
| 018242 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:00pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.7 | 510738.0 | 19712 | 1.64041666667 | 18242 |
| 016860 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:01pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.7 | 510738.0 | 19713 | 1.64041666667 | 16860 |
| 017385 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:02pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.7 | 510738.0 | 19714 | 1.64041666667 | 17385 |
| 018044 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:06pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.6 | 510738.0 | 19715 | 1.64041666667 | 18044 |
| 018221 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:07pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.6 | 510738.0 | 19717 | 1.64041666667 | 18221 |
| 018265 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:08pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.7 | 510738.0 | 19719 | 1.64041666667 | 18265 |
| 018966 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:09pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.6 | 510737.9 | 19721 | 1.64041666667 | 18966 |
| 016591 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:10pm | Sensor | 1797-S0024-G-TJV.cor | 6796.6 | 1592810.6 | 510737.9 | 19723 | 1.64041666667 | 16591 |
| 017235 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:11pm | Sensor | 1797-S0024-G-TJV.cor | 6796.5 | 1592810.6 | 510737.9 | 19725 | 1.64041666667 | 17235 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017349 | 0 | GeoXH 6000 | 08/18/2015 | 01:22:12pm | Sensor | 1797-S0024-G-TJV.cor | 6796.5 | 1592810.6 | 510737.9 | 19728 | 1.64041666667 | 17349 |
| 012566 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:57am | Sensor | 1797-S0023-G-TJV.cor | 6782.4 | 1594134.5 | 509565.0 | 12450 | 1.64041666667 | 12566 |
| 013071 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:58am | Sensor | 1797-S0023-G-TJV.cor | 6782.3 | 1594135.0 | 509564.7 | 12453 | 1.64041666667 | 13071 |
| 013138 | 0 | GeoXH 6000 | 08/18/2015 | 11:41:59am | Sensor | 1797-S0023-G-TJV.cor | 6788.1 | 1594137.0 | 509563.1 | 12455 | 1.64041666667 | 13138 |
| 013604 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:00am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1594139.7 | 509560.6 | 12457 | 1.64041666667 | 13604 |
| 014351 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:01am | Sensor | 1797-S0023-G-TJV.cor | 6799.4 | 1594138.5 | 509560.9 | 12459 | 1.64041666667 | 14351 |
| 014897 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:02am | Sensor | 1797-S0023-G-TJV.cor | 6799.3 | 1594137.7 | 509560.8 | 12461 | 1.64041666667 | 14897 |
| 014944 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:03am | Sensor | 1797-S0023-G-TJV.cor | 6798.3 | 1594137.8 | 509560.9 | 12463 | 1.64041666667 | 14944 |
| 012226 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:04am | Sensor | 1797-S0023-G-TJV.cor | 6788.7 | 1594135.8 | 509562.0 | 12465 | 1.64041666667 | 12226 |
| 012566 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:05am | Sensor | 1797-S0023-G-TJV.cor | 6789.2 | 1594136.4 | 509561.8 | 12467 | 1.64041666667 | 12566 |
| 013281 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:06am | Sensor | 1797-S0023-G-TJV.cor | 6795.9 | 1594138.4 | 509561.1 | 12469 | 1.64041666667 | 13281 |
| 013580 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:07am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1594139.8 | 509561.1 | 12471 | 1.64041666667 | 13580 |
| 013715 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:08am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1594139.9 | 509561.4 | 12473 | 1.64041666667 | 13715 |
| 013388 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:09am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1594139.3 | 509560.4 | 12475 | 1.64041666667 | 13388 |
| 012437 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:10am | Sensor | 1797-S0023-G-TJV.cor | 6805.2 | 1594138.8 | 509559.6 | 12477 | 1.64041666667 | 12437 |
| 012769 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:11am | Sensor | 1797-S0023-G-TJV.cor | 6805.1 | 1594139.1 | 509559.5 | 12479 | 1.64041666667 | 12769 |
| 012642 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:12am | Sensor | 1797-S0023-G-TJV.cor | 6804.4 | 1594139.0 | 509559.5 | 12481 | 1.64041666667 | 12642 |
| 012640 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:13am | Sensor | 1797-S0023-G-TJV.cor | 6804.8 | 1594139.0 | 509559.4 | 12483 | 1.64041666667 | 12640 |
| 012940 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:14am | Sensor | 1797-S0023-G-TJV.cor | 6805.1 | 1594139.1 | 509559.1 | 12485 | 1.64041666667 | 12940 |
| 012655 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:15am | Sensor | 1797-S0023-G-TJV.cor | 6805.5 | 1594139.5 | 509558.9 | 12487 | 1.64041666667 | 12655 |
| 013963 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:16am | Sensor | 1797-S0023-G-TJV.cor | 6805.3 | 1594140.6 | 509559.6 | 12489 | 1.64041666667 | 13963 |
| 011861 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:17am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1594140.0 | 509561.0 | 12491 | 1.64041666667 | 11861 |
| 012355 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:18am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1594140.1 | 509561.0 | 12493 | 1.64041666667 | 12355 |
| 012868 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:19am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1594140.1 | 509561.0 | 12495 | 1.64041666667 | 12868 |
| 011347 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:20am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1594139.9 | 509561.0 | 12497 | 1.64041666667 | 11347 |
| 014176 | 0 | GeoXH 6000 | 08/18/2015 | 11:42:21am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1594139.9 | 509561.0 | 12499 | 1.64041666667 | 14176 |
| 012963 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:42am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1594076.5 | 509592.9 | 12502 | 1.64041666667 | 12963 |
| 015000 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:43am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1594075.6 | 509594.0 | 12504 | 1.64041666667 | 15000 |
| 017100 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:44am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1594073.6 | 509597.2 | 12506 | 1.64041666667 | 17100 |
| 015825 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:45am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1594071.7 | 509599.7 | 12508 | 1.64041666667 | 15825 |
| 014456 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:46am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1594068.7 | 509603.1 | 12510 | 1.64041666667 | 14456 |
| 014354 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:47am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1594066.2 | 509605.1 | 12512 | 1.64041666667 | 14354 |
| 015108 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:48am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1594062.5 | 509607.4 | 12514 | 1.64041666667 | 15108 |
| 014907 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:49am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1594059.3 | 509609.3 | 12516 | 1.64041666667 | 14907 |
| 015906 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:50am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1594055.3 | 509611.0 | 12518 | 1.64041666667 | 15906 |
| 014266 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:51am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1594051.5 | 509612.1 | 12520 | 1.64041666667 | 14266 |
| 015626 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:52am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1594047.4 | 509613.1 | 12522 | 1.64041666667 | 15626 |
| 014676 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:53am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1594043.9 | 509613.9 | 12524 | 1.64041666667 | 14676 |
| 016449 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:54am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1594039.2 | 509614.8 | 12526 | 1.64041666667 | 16449 |
| 016772 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:55am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1594035.6 | 509615.7 | 12528 | 1.64041666667 | 16772 |
| 016673 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:56am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1594031.1 | 509616.6 | 12530 | 1.64041666667 | 16673 |
| 014338 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:57am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1594027.3 | 509617.3 | 12532 | 1.64041666667 | 14338 |
| 014744 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:58am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1594022.8 | 509618.4 | 12534 | 1.64041666667 | 14744 |
| 015236 | 0 | GeoXH 6000 | 08/18/2015 | 11:46:59am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1594019.0 | 509619.8 | 12536 | 1.64041666667 | 15236 |
| 014519 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:00am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1594015.2 | 509621.8 | 12538 | 1.64041666667 | 14519 |
| 013259 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:01am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1594012.3 | 509623.8 | 12540 | 1.64041666667 | 13259 |
| 015105 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:02am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1594008.6 | 509626.5 | 12542 | 1.64041666667 | 15105 |
| 015176 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:03am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1594005.9 | 509628.5 | 12544 | 1.64041666667 | 15176 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014954 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:04am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1594001.6 | 509631.1 | 12546 | 1.64041666667 | 14954 |
| 015948 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:05am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593998.1 | 509633.1 | 12548 | 1.64041666667 | 15948 |
| 016227 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:06am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593993.9 | 509635.1 | 12550 | 1.64041666667 | 16227 |
| 013926 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:07am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593990.3 | 509637.0 | 12552 | 1.64041666667 | 13926 |
| 014521 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:08am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593986.0 | 509639.0 | 12554 | 1.64041666667 | 14521 |
| 014820 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:09am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593982.2 | 509640.6 | 12556 | 1.64041666667 | 14820 |
| 015465 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:10am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593978.0 | 509642.0 | 12558 | 1.64041666667 | 15465 |
| 015746 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:11am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593973.7 | 509643.2 | 12560 | 1.64041666667 | 15746 |
| 015636 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:12am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593969.4 | 509644.7 | 12562 | 1.64041666667 | 15636 |
| 015099 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:13am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593966.3 | 509646.3 | 12564 | 1.64041666667 | 15099 |
| 014364 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:14am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593962.0 | 509648.8 | 12566 | 1.64041666667 | 14364 |
| 013371 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:15am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593959.0 | 509650.6 | 12568 | 1.64041666667 | 13371 |
| 014772 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:16am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593955.5 | 509653.1 | 12570 | 1.64041666667 | 14772 |
| 015093 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:17am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593952.9 | 509655.3 | 12572 | 1.64041666667 | 15093 |
| 015443 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:18am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593949.4 | 509657.9 | 12574 | 1.64041666667 | 15443 |
| 015620 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:19am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593946.3 | 509660.3 | 12576 | 1.64041666667 | 15620 |
| 014975 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:20am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593942.5 | 509663.3 | 12578 | 1.64041666667 | 14975 |
| 014243 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:21am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593939.8 | 509665.8 | 12580 | 1.64041666667 | 14243 |
| 014511 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:22am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593936.7 | 509668.6 | 12582 | 1.64041666667 | 14511 |
| 014817 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:23am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593933.8 | 509671.0 | 12584 | 1.64041666667 | 14817 |
| 015764 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:24am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593931.1 | 509674.0 | 12586 | 1.64041666667 | 15764 |
| 014951 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:25am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1593928.9 | 509677.3 | 12588 | 1.64041666667 | 14951 |
| 013517 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:26am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593926.9 | 509681.3 | 12590 | 1.64041666667 | 13517 |
| 013789 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:27am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593925.4 | 509684.6 | 12592 | 1.64041666667 | 13789 |
| 014937 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:28am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593923.9 | 509688.4 | 12594 | 1.64041666667 | 14937 |
| 016514 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:29am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593922.3 | 509691.7 | 12596 | 1.64041666667 | 16514 |
| 015078 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:30am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1593919.9 | 509694.1 | 12598 | 1.64041666667 | 15078 |
| 014419 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:31am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593916.6 | 509695.1 | 12600 | 1.64041666667 | 14419 |
| 015664 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:32am | Sensor | 1797-S0023-G-TJV.cor | 6802.8 | 1593912.4 | 509696.3 | 12602 | 1.64041666667 | 15664 |
| 017566 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:33am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593909.0 | 509697.4 | 12604 | 1.64041666667 | 17566 |
| 016991 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:34am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1593905.1 | 509698.7 | 12606 | 1.64041666667 | 16991 |
| 015378 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:35am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1593902.4 | 509700.3 | 12608 | 1.64041666667 | 15378 |
| 018274 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:36am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593899.1 | 509703.1 | 12610 | 1.64041666667 | 18274 |
| 015098 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:37am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593896.7 | 509705.6 | 12612 | 1.64041666667 | 15098 |
| 015174 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:38am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593893.5 | 509708.7 | 12614 | 1.64041666667 | 15174 |
| 014773 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:39am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593891.1 | 509711.1 | 12616 | 1.64041666667 | 14773 |
| 014913 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:40am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593887.9 | 509714.1 | 12618 | 1.64041666667 | 14913 |
| 015368 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:41am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593885.2 | 509716.0 | 12620 | 1.64041666667 | 15368 |
| 016172 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:42am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593881.8 | 509718.4 | 12622 | 1.64041666667 | 16172 |
| 014843 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:43am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593878.6 | 509720.0 | 12624 | 1.64041666667 | 14843 |
| 015890 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:44am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593874.6 | 509721.4 | 12626 | 1.64041666667 | 15890 |
| 015462 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:45am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593871.1 | 509722.5 | 12628 | 1.64041666667 | 15462 |
| 016945 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:46am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593867.0 | 509723.6 | 12630 | 1.64041666667 | 16945 |
| 015156 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:47am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1593863.9 | 509724.6 | 12632 | 1.64041666667 | 15156 |
| 014889 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:48am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593860.3 | 509726.2 | 12634 | 1.64041666667 | 14889 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:49am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1593856.9 | 509728.0 | 12636 | 1.64041666667 | 13442 |
| 012330 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:50am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1593853.2 | 509730.5 | 12638 | 1.64041666667 | 12330 |
| 014032 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:51am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1593850.2 | 509732.8 | 12640 | 1.64041666667 | 14032 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015958 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:52am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593847.0 | 509735.7 | 12642 | 1.64041666667 | 15958 |
| 015629 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:53am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593844.1 | 509737.6 | 12644 | 1.64041666667 | 15629 |
| 015337 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:54am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593840.5 | 509739.4 | 12646 | 1.64041666667 | 15337 |
| 017394 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:55am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593837.5 | 509741.2 | 12648 | 1.64041666667 | 17394 |
| 014938 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:56am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593834.5 | 509743.8 | 12650 | 1.64041666667 | 14938 |
| 013904 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:57am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593832.5 | 509746.4 | 12652 | 1.64041666667 | 13904 |
| 014486 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:58am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593831.1 | 509750.1 | 12654 | 1.64041666667 | 14486 |
| 015171 | 0 | GeoXH 6000 | 08/18/2015 | 11:47:59am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593830.0 | 509753.5 | 12656 | 1.64041666667 | 15171 |
| 016662 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:00am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593829.0 | 509757.3 | 12658 | 1.64041666667 | 16662 |
| 017425 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:01am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593827.8 | 509760.6 | 12660 | 1.64041666667 | 17425 |
| 015366 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:02am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593825.6 | 509763.8 | 12662 | 1.64041666667 | 15366 |
| 015901 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:03am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593822.8 | 509765.8 | 12664 | 1.64041666667 | 15901 |
| 017055 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:04am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593819.0 | 509767.7 | 12666 | 1.64041666667 | 17055 |
| 015543 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:05am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593815.9 | 509769.3 | 12668 | 1.64041666667 | 15543 |
| 016726 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:06am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593812.7 | 509771.5 | 12670 | 1.64041666667 | 16726 |
| 016991 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:07am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593809.7 | 509773.8 | 12672 | 1.64041666667 | 16991 |
| 014688 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:08am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593806.8 | 509776.5 | 12674 | 1.64041666667 | 14688 |
| 016362 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:09am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593804.3 | 509779.3 | 12676 | 1.64041666667 | 16362 |
| 015790 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:10am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593801.0 | 509781.9 | 12678 | 1.64041666667 | 15790 |
| 014777 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:11am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593797.8 | 509783.3 | 12680 | 1.64041666667 | 14777 |
| 015214 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:12am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593793.9 | 509784.5 | 12682 | 1.64041666667 | 15214 |
| 016043 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:13am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593790.6 | 509785.2 | 12684 | 1.64041666667 | 16043 |
| 014271 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:14am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593786.6 | 509786.2 | 12686 | 1.64041666667 | 14271 |
| 017217 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:15am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593782.6 | 509787.4 | 12688 | 1.64041666667 | 17217 |
| 016394 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:16am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593778.5 | 509789.0 | 12690 | 1.64041666667 | 16394 |
| 015198 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:17am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593775.0 | 509790.1 | 12692 | 1.64041666667 | 15198 |
| 014659 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:18am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593771.0 | 509791.4 | 12694 | 1.64041666667 | 14659 |
| 014734 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:19am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593767.4 | 509792.4 | 12696 | 1.64041666667 | 14734 |
| 014423 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:20am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593763.2 | 509793.8 | 12698 | 1.64041666667 | 14423 |
| 014286 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:21am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593760.0 | 509794.9 | 12700 | 1.64041666667 | 14286 |
| 016891 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:22am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593756.0 | 509796.0 | 12702 | 1.64041666667 | 16891 |
| 015712 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:23am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593752.2 | 509797.3 | 12704 | 1.64041666667 | 15712 |
| 015088 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:24am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593748.3 | 509798.4 | 12706 | 1.64041666667 | 15088 |
| 017092 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:25am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593745.1 | 509799.4 | 12708 | 1.64041666667 | 17092 |
| 014503 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:26am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593741.3 | 509800.9 | 12710 | 1.64041666667 | 14503 |
| 015745 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:27am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593738.2 | 509802.3 | 12712 | 1.64041666667 | 15745 |
| 016236 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:28am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593734.3 | 509804.3 | 12714 | 1.64041666667 | 16236 |
| 016329 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:29am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1593731.1 | 509806.0 | 12716 | 1.64041666667 | 16329 |
| 016232 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:30am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1593727.8 | 509807.3 | 12718 | 1.64041666667 | 16232 |
| 015818 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:31am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593724.3 | 509808.3 | 12720 | 1.64041666667 | 15818 |
| 012804 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:32am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1593720.1 | 509808.9 | 12722 | 1.64041666667 | 12804 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:33am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593715.8 | 509809.3 | 12724 | 1.64041666667 | 13491 |
| 013602 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:34am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1593711.6 | 509810.0 | 12726 | 1.64041666667 | 13602 |
| 012910 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:35am | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1593708.0 | 509810.9 | 12728 | 1.64041666667 | 12910 |
| 012047 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:36am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1593704.0 | 509811.5 | 12730 | 1.64041666667 | 12047 |
| 012701 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:37am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593700.3 | 509812.1 | 12732 | 1.64041666667 | 12701 |
| 013135 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:38am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593696.4 | 509813.2 | 12734 | 1.64041666667 | 13135 |
| 014324 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:39am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593693.5 | 509814.6 | 12736 | 1.64041666667 | 14324 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:40am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593690.4 | 509817.1 | 12738 | 1.64041666667 | 12761 |
| 016870 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:41am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593687.7 | 509819.2 | 12740 | 1.64041666667 | 16870 |
| 018887 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:42am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593684.3 | 509821.5 | 12742 | 1.64041666667 | 18887 |
| 018641 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:43am | Sensor | 1797-S0023-G-TJV.cor | 6803.9 | 1593681.1 | 509822.9 | 12744 | 1.64041666667 | 18641 |
| 019930 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:44am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593677.2 | 509824.1 | 12746 | 1.64041666667 | 19930 |
| 021392 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:45am | Sensor | 1797-S0023-G-TJV.cor | 6803.9 | 1593673.4 | 509825.2 | 12748 | 1.64041666667 | 21392 |
| 019268 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:46am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593669.4 | 509826.2 | 12750 | 1.64041666667 | 19268 |
| 019247 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:47am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593666.5 | 509827.1 | 12752 | 1.64041666667 | 19247 |
| 017831 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:48am | Sensor | 1797-S0023-G-TJV.cor | 6804.0 | 1593663.1 | 509828.4 | 12754 | 1.64041666667 | 17831 |
| 017478 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:49am | Sensor | 1797-S0023-G-TJV.cor | 6804.0 | 1593660.4 | 509829.4 | 12756 | 1.64041666667 | 17478 |
| 016339 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:50am | Sensor | 1797-S0023-G-TJV.cor | 6804.1 | 1593657.5 | 509830.3 | 12758 | 1.64041666667 | 16339 |
| 014404 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:51am | Sensor | 1797-S0023-G-TJV.cor | 6803.9 | 1593654.9 | 509830.8 | 12760 | 1.64041666667 | 14404 |
| 013081 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:52am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593651.0 | 509830.4 | 12762 | 1.64041666667 | 13081 |
| 012990 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:53am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593647.7 | 509829.8 | 12764 | 1.64041666667 | 12990 |
| 012907 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:54am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593643.7 | 509829.3 | 12766 | 1.64041666667 | 12907 |
| 012467 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:55am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593641.1 | 509829.1 | 12768 | 1.64041666667 | 12467 |
| 012536 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:56am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593637.7 | 509828.5 | 12770 | 1.64041666667 | 12536 |
| 013034 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:57am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593634.8 | 509828.3 | 12772 | 1.64041666667 | 13034 |
| 013758 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:58am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593631.0 | 509828.7 | 12774 | 1.64041666667 | 13758 |
| 013399 | 0 | GeoXH 6000 | 08/18/2015 | 11:48:59am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593627.3 | 509829.3 | 12776 | 1.64041666667 | 13399 |
| 013849 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:00am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593623.5 | 509830.5 | 12778 | 1.64041666667 | 13849 |
| 015162 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:01am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593620.9 | 509832.3 | 12780 | 1.64041666667 | 15162 |
| 014470 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:02am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593618.5 | 509835.1 | 12782 | 1.64041666667 | 14470 |
| 013247 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:03am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593616.2 | 509837.5 | 12784 | 1.64041666667 | 13247 |
| 012791 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:04am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593612.8 | 509839.9 | 12786 | 1.64041666667 | 12791 |
| 012936 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:05am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593610.0 | 509842.1 | 12788 | 1.64041666667 | 12936 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:06am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593607.3 | 509845.0 | 12790 | 1.64041666667 | 13782 |
| 014215 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:07am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593605.2 | 509847.7 | 12792 | 1.64041666667 | 14215 |
| 012674 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:08am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593602.1 | 509850.4 | 12794 | 1.64041666667 | 12674 |
| 012378 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:09am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593599.3 | 509851.8 | 12796 | 1.64041666667 | 12378 |
| 011494 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:10am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593595.6 | 509853.7 | 12798 | 1.64041666667 | 11494 |
| 013163 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:11am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593592.1 | 509855.9 | 12800 | 1.64041666667 | 13163 |
| 012681 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:12am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593588.8 | 509857.8 | 12802 | 1.64041666667 | 12681 |
| 013850 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:13am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593585.2 | 509859.2 | 12804 | 1.64041666667 | 13850 |
| 013842 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:14am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593581.2 | 509861.2 | 12806 | 1.64041666667 | 13842 |
| 013390 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:15am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593577.9 | 509863.3 | 12808 | 1.64041666667 | 13390 |
| 014177 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:16am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593574.6 | 509865.5 | 12810 | 1.64041666667 | 14177 |
| 012304 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:17am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593571.4 | 509867.6 | 12812 | 1.64041666667 | 12304 |
| 011926 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:18am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593567.8 | 509869.9 | 12814 | 1.64041666667 | 11926 |
| 013271 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:19am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593564.7 | 509871.7 | 12816 | 1.64041666667 | 13271 |
| 013218 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:20am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593560.7 | 509873.2 | 12818 | 1.64041666667 | 13218 |
| 013504 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:21am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593557.7 | 509874.2 | 12820 | 1.64041666667 | 13504 |
| 013786 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:22am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593553.6 | 509876.2 | 12822 | 1.64041666667 | 13786 |
| 014036 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:23am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593550.3 | 509878.1 | 12824 | 1.64041666667 | 14036 |
| 011909 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:24am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593547.0 | 509879.7 | 12826 | 1.64041666667 | 11909 |
| 014227 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:25am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593543.7 | 509880.6 | 12828 | 1.64041666667 | 14227 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:26am | Sensor | 1797-S0023-G-TJV.cor | 6803.9 | 1593539.8 | 509881.1 | 12830 | 1.64041666667 | 14626 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:27am | Sensor | 1797-S0023-G-TJV.cor | 6803.8 | 1593536.1 | 509882.1 | 12832 | 1.64041666667 | 13526 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011991 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:28am | Sensor | 1797-S0023-G-TJV.cor | 6803.6 | 1593532.3 | 509883.4 | 12834 | 1.64041666667 | 11991 |
| 014428 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:29am | Sensor | 1797-S0023-G-TJV.cor | 6803.7 | 1593528.6 | 509884.6 | 12836 | 1.64041666667 | 14428 |
| 013597 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:30am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593523.6 | 509886.0 | 12838 | 1.64041666667 | 13597 |
| 013389 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:31am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593519.9 | 509887.3 | 12840 | 1.64041666667 | 13389 |
| 013547 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:32am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593516.1 | 509888.7 | 12842 | 1.64041666667 | 13547 |
| 014126 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:33am | Sensor | 1797-S0023-G-TJV.cor | 6803.5 | 1593513.2 | 509890.1 | 12844 | 1.64041666667 | 14126 |
| 013131 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:34am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593508.9 | 509891.5 | 12846 | 1.64041666667 | 13131 |
| 012733 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:35am | Sensor | 1797-S0023-G-TJV.cor | 6803.4 | 1593505.0 | 509892.5 | 12848 | 1.64041666667 | 12733 |
| 012603 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:36am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593500.9 | 509894.0 | 12850 | 1.64041666667 | 12603 |
| 011520 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:37am | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1593497.7 | 509895.6 | 12852 | 1.64041666667 | 11520 |
| 013140 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:38am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593494.3 | 509898.0 | 12854 | 1.64041666667 | 13140 |
| 013935 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:39am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593491.1 | 509900.3 | 12856 | 1.64041666667 | 13935 |
| 013683 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:40am | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1593488.0 | 509902.4 | 12858 | 1.64041666667 | 13683 |
| 012871 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:41am | Sensor | 1797-S0023-G-TJV.cor | 6803.1 | 1593484.8 | 509904.3 | 12860 | 1.64041666667 | 12871 |
| 012967 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:42am | Sensor | 1797-S0023-G-TJV.cor | 6802.9 | 1593481.5 | 509906.1 | 12862 | 1.64041666667 | 12967 |
| 012272 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:43am | Sensor | 1797-S0023-G-TJV.cor | 6802.8 | 1593478.3 | 509907.6 | 12864 | 1.64041666667 | 12272 |
| 012458 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:44am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593474.6 | 509909.0 | 12866 | 1.64041666667 | 12458 |
| 013104 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:45am | Sensor | 1797-S0023-G-TJV.cor | 6802.8 | 1593470.9 | 509910.3 | 12868 | 1.64041666667 | 13104 |
| 012366 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:46am | Sensor | 1797-S0023-G-TJV.cor | 6802.8 | 1593466.8 | 509911.5 | 12870 | 1.64041666667 | 12366 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:47am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593463.9 | 509913.3 | 12872 | 1.64041666667 | 13471 |
| 012187 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:48am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593461.4 | 509915.9 | 12874 | 1.64041666667 | 12187 |
| 011207 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:49am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593459.1 | 509918.5 | 12876 | 1.64041666667 | 11207 |
| 011441 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:50am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593456.4 | 509920.5 | 12878 | 1.64041666667 | 11441 |
| 013960 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:51am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593453.1 | 509922.1 | 12880 | 1.64041666667 | 13960 |
| 012130 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:52am | Sensor | 1797-S0023-G-TJV.cor | 6802.8 | 1593449.3 | 509923.9 | 12882 | 1.64041666667 | 12130 |
| 011042 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:53am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593446.0 | 509925.5 | 12884 | 1.64041666667 | 11042 |
| 011880 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:54am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593442.3 | 509927.1 | 12886 | 1.64041666667 | 11880 |
| 012270 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:55am | Sensor | 1797-S0023-G-TJV.cor | 6802.8 | 1593438.8 | 509928.3 | 12888 | 1.64041666667 | 12270 |
| 011077 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:56am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593434.4 | 509929.5 | 12890 | 1.64041666667 | 11077 |
| 012129 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:57am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593430.8 | 509930.8 | 12892 | 1.64041666667 | 12129 |
| 013712 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:58am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593426.9 | 509932.6 | 12894 | 1.64041666667 | 13712 |
| 012638 | 0 | GeoXH 6000 | 08/18/2015 | 11:49:59am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593423.5 | 509934.3 | 12896 | 1.64041666667 | 12638 |
| 010989 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:00am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593420.2 | 509936.2 | 12898 | 1.64041666667 | 10989 |
| 013127 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:01am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593417.0 | 509938.3 | 12900 | 1.64041666667 | 13127 |
| 013331 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:02am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593413.2 | 509940.5 | 12902 | 1.64041666667 | 13331 |
| 012633 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:03am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593410.0 | 509942.0 | 12904 | 1.64041666667 | 12633 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:04am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1593406.1 | 509944.3 | 12906 | 1.64041666667 | 14078 |
| 012729 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:05am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1593402.8 | 509946.2 | 12908 | 1.64041666667 | 12729 |
| 011912 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:06am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1593398.8 | 509948.3 | 12910 | 1.64041666667 | 11912 |
| 011978 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:07am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593395.1 | 509950.0 | 12912 | 1.64041666667 | 11978 |
| 011814 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:08am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593391.4 | 509951.5 | 12914 | 1.64041666667 | 11814 |
| 011233 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:09am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1593387.6 | 509952.7 | 12916 | 1.64041666667 | 11233 |
| 013128 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:10am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1593383.7 | 509954.0 | 12918 | 1.64041666667 | 13128 |
| 012552 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:11am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593380.4 | 509955.5 | 12920 | 1.64041666667 | 12552 |
| 012708 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:12am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593376.4 | 509956.8 | 12922 | 1.64041666667 | 12708 |
| 012147 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:13am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593373.0 | 509957.8 | 12924 | 1.64041666667 | 12147 |
| 012966 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:14am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593369.1 | 509959.4 | 12926 | 1.64041666667 | 12966 |
| 013771 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:15am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593365.6 | 509961.3 | 12928 | 1.64041666667 | 13771 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012172 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:16am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593362.2 | 509963.5 | 12930 | 1.64041666667 | 12172 |
| 012253 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:17am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593358.8 | 509966.1 | 12932 | 1.64041666667 | 12253 |
| 013383 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:18am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593355.6 | 509969.0 | 12934 | 1.64041666667 | 13383 |
| 012195 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:19am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593353.0 | 509971.2 | 12936 | 1.64041666667 | 12195 |
| 012948 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:20am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593349.7 | 509973.9 | 12938 | 1.64041666667 | 12948 |
| 012207 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:21am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593346.5 | 509975.7 | 12940 | 1.64041666667 | 12207 |
| 011932 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:22am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593343.1 | 509977.3 | 12942 | 1.64041666667 | 11932 |
| 013603 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:23am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593339.5 | 509978.1 | 12944 | 1.64041666667 | 13603 |
| 013870 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:24am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593335.4 | 509978.4 | 12946 | 1.64041666667 | 13870 |
| 013667 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:25am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593331.2 | 509979.0 | 12948 | 1.64041666667 | 13667 |
| 013256 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:26am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593327.0 | 509980.2 | 12950 | 1.64041666667 | 13256 |
| 011654 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:27am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593324.2 | 509981.6 | 12952 | 1.64041666667 | 11654 |
| 011463 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:28am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593320.6 | 509983.6 | 12954 | 1.64041666667 | 11463 |
| 011895 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:29am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593317.4 | 509985.4 | 12956 | 1.64041666667 | 11895 |
| 012063 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:30am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593314.4 | 509987.6 | 12958 | 1.64041666667 | 12063 |
| 012286 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:31am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593311.5 | 509989.5 | 12960 | 1.64041666667 | 12286 |
| 012221 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:32am | Sensor | 1797-S0023-G-TJV.cor | 6802.8 | 1593308.3 | 509991.6 | 12962 | 1.64041666667 | 12221 |
| 012355 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:33am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593305.6 | 509993.7 | 12964 | 1.64041666667 | 12355 |
| 012089 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:34am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593302.4 | 509996.3 | 12966 | 1.64041666667 | 12089 |
| 011872 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:35am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593299.7 | 509998.6 | 12968 | 1.64041666667 | 11872 |
| 013168 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:36am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593296.9 | 510001.1 | 12970 | 1.64041666667 | 13168 |
| 013282 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:37am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593294.6 | 510003.8 | 12972 | 1.64041666667 | 13282 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:38am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593291.8 | 510006.4 | 12974 | 1.64041666667 | 14210 |
| 013362 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:39am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593288.7 | 510008.1 | 12976 | 1.64041666667 | 13362 |
| 012760 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:40am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593285.4 | 510009.7 | 12978 | 1.64041666667 | 12760 |
| 013570 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:41am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593281.8 | 510010.8 | 12980 | 1.64041666667 | 13570 |
| 013382 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:42am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1593278.3 | 510011.3 | 12982 | 1.64041666667 | 13382 |
| 014805 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:43am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593274.6 | 510011.9 | 12984 | 1.64041666667 | 14805 |
| 012281 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:44am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593271.0 | 510013.1 | 12986 | 1.64041666667 | 12281 |
| 011920 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:45am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593268.0 | 510015.0 | 12988 | 1.64041666667 | 11920 |
| 010720 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:46am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593264.5 | 510016.7 | 12990 | 1.64041666667 | 10720 |
| 010900 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:47am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593261.2 | 510017.8 | 12992 | 1.64041666667 | 10900 |
| 012265 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:48am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593258.0 | 510019.1 | 12994 | 1.64041666667 | 12265 |
| 013416 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:49am | Sensor | 1797-S0023-G-TJV.cor | 6802.8 | 1593255.1 | 510020.3 | 12996 | 1.64041666667 | 13416 |
| 013044 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:50am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1593251.0 | 510021.3 | 12998 | 1.64041666667 | 13044 |
| 012561 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:51am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593247.5 | 510021.7 | 13000 | 1.64041666667 | 12561 |
| 012830 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:52am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593244.0 | 510022.2 | 13002 | 1.64041666667 | 12830 |
| 013287 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:53am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593240.5 | 510023.0 | 13004 | 1.64041666667 | 13287 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:54am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593236.3 | 510024.2 | 13006 | 1.64041666667 | 13132 |
| 012553 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:55am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593232.9 | 510025.0 | 13008 | 1.64041666667 | 12553 |
| 014568 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:56am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593228.9 | 510026.6 | 13010 | 1.64041666667 | 14568 |
| 012642 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:57am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593225.4 | 510028.4 | 13012 | 1.64041666667 | 12642 |
| 012400 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:58am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593221.6 | 510030.0 | 13014 | 1.64041666667 | 12400 |
| 012670 | 0 | GeoXH 6000 | 08/18/2015 | 11:50:59am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593218.6 | 510031.1 | 13016 | 1.64041666667 | 12670 |
| 011717 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:00am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593214.2 | 510032.0 | 13018 | 1.64041666667 | 11717 |
| 013549 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:01am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1593210.5 | 510032.9 | 13020 | 1.64041666667 | 13549 |
| 012027 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:02am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593206.5 | 510034.1 | 13022 | 1.64041666667 | 12027 |
| 013177 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:03am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593203.0 | 510035.1 | 13024 | 1.64041666667 | 13177 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013254 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:04am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593199.3 | 510036.5 | 13026 | 1.64041666667 | 13254 |
| 013063 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:05am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593195.8 | 510038.0 | 13028 | 1.64041666667 | 13063 |
| 012896 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:06am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1593191.9 | 510039.6 | 13030 | 1.64041666667 | 12896 |
| 012224 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:07am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1593188.7 | 510041.2 | 13032 | 1.64041666667 | 12224 |
| 012326 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:08am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593185.4 | 510043.8 | 13034 | 1.64041666667 | 12326 |
| 012591 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:09am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1593183.4 | 510046.3 | 13036 | 1.64041666667 | 12591 |
| 012447 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:10am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593180.9 | 510049.7 | 13038 | 1.64041666667 | 12447 |
| 011482 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:11am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593178.9 | 510052.3 | 13040 | 1.64041666667 | 11482 |
| 011960 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:12am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593176.5 | 510055.7 | 13042 | 1.64041666667 | 11960 |
| 011270 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:13am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593174.5 | 510058.5 | 13044 | 1.64041666667 | 11270 |
| 011067 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:14am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593171.8 | 510061.3 | 13046 | 1.64041666667 | 11067 |
| 013567 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:15am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593168.6 | 510063.3 | 13048 | 1.64041666667 | 13567 |
| 013621 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:16am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1593165.3 | 510064.6 | 13050 | 1.64041666667 | 13621 |
| 012615 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:17am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1593161.8 | 510065.4 | 13052 | 1.64041666667 | 12615 |
| 013173 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:18am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593158.1 | 510066.2 | 13054 | 1.64041666667 | 13173 |
| 013133 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:19am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593154.2 | 510067.2 | 13056 | 1.64041666667 | 13133 |
| 011983 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:20am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593150.4 | 510068.0 | 13058 | 1.64041666667 | 11983 |
| 012296 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:21am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593146.9 | 510068.6 | 13060 | 1.64041666667 | 12296 |
| 012944 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:22am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1593142.6 | 510069.3 | 13062 | 1.64041666667 | 12944 |
| 012896 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:23am | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1593138.9 | 510070.4 | 13064 | 1.64041666667 | 12896 |
| 013664 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:24am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1593135.2 | 510072.0 | 13066 | 1.64041666667 | 13664 |
| 012026 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:25am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1593131.8 | 510073.4 | 13068 | 1.64041666667 | 12026 |
| 014586 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:26am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1593128.3 | 510073.4 | 13070 | 1.64041666667 | 14586 |
| 015316 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:27am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1593125.8 | 510071.8 | 13072 | 1.64041666667 | 15316 |
| 014239 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:28am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1593122.1 | 510069.2 | 13074 | 1.64041666667 | 14239 |
| 012829 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:29am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1593118.7 | 510067.5 | 13076 | 1.64041666667 | 12829 |
| 013257 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:30am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1593114.3 | 510066.2 | 13078 | 1.64041666667 | 13257 |
| 013124 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:31am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1593111.1 | 510065.7 | 13080 | 1.64041666667 | 13124 |
| 013001 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:32am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1593107.3 | 510066.3 | 13082 | 1.64041666667 | 13001 |
| 013060 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:33am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1593104.9 | 510068.4 | 13084 | 1.64041666667 | 13060 |
| 012205 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:34am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1593102.7 | 510070.7 | 13086 | 1.64041666667 | 12205 |
| 013371 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:35am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1593100.8 | 510074.0 | 13088 | 1.64041666667 | 13371 |
| 014982 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:36am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593099.0 | 510076.6 | 13090 | 1.64041666667 | 14982 |
| 012805 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:37am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593097.0 | 510078.4 | 13092 | 1.64041666667 | 12805 |
| 015471 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:38am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593093.8 | 510081.4 | 13094 | 1.64041666667 | 15471 |
| 016437 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:39am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593091.6 | 510083.3 | 13096 | 1.64041666667 | 16437 |
| 016589 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:40am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1593088.5 | 510086.1 | 13098 | 1.64041666667 | 16589 |
| 015067 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:41am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1593086.1 | 510087.9 | 13100 | 1.64041666667 | 15067 |
| 014626 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:42am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1593082.9 | 510090.3 | 13102 | 1.64041666667 | 14626 |
| 014786 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:43am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1593079.9 | 510092.4 | 13104 | 1.64041666667 | 14786 |
| 013056 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:44am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1593076.6 | 510093.8 | 13106 | 1.64041666667 | 13056 |
| 013224 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:45am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1593073.7 | 510094.7 | 13108 | 1.64041666667 | 13224 |
| 013656 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:46am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1593070.2 | 510096.7 | 13110 | 1.64041666667 | 13656 |
| 016194 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:47am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1593068.1 | 510098.3 | 13112 | 1.64041666667 | 16194 |
| 016348 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:48am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1593065.4 | 510101.2 | 13114 | 1.64041666667 | 16348 |
| 013237 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:49am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1593063.3 | 510103.5 | 13116 | 1.64041666667 | 13237 |
| 013419 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:50am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1593060.4 | 510106.4 | 13118 | 1.64041666667 | 13419 |
| 012834 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:51am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1593057.8 | 510108.4 | 13120 | 1.64041666667 | 12834 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012958 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:52am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1593056.0 | 510110.6 | 13122 | 1.64041666667 | 12958 |
| 014819 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:53am | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1593054.4 | 510112.8 | 13124 | 1.64041666667 | 14819 |
| 013365 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:54am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1593050.9 | 510113.9 | 13126 | 1.64041666667 | 13365 |
| 013061 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:55am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1593047.9 | 510113.0 | 13128 | 1.64041666667 | 13061 |
| 013495 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:56am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1593044.5 | 510112.7 | 13130 | 1.64041666667 | 13495 |
| 014113 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:57am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593041.6 | 510113.3 | 13132 | 1.64041666667 | 14113 |
| 013848 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:58am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1593037.9 | 510114.4 | 13134 | 1.64041666667 | 13848 |
| 014202 | 0 | GeoXH 6000 | 08/18/2015 | 11:51:59am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593035.1 | 510115.7 | 13136 | 1.64041666667 | 14202 |
| 014560 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:00am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593031.6 | 510117.3 | 13138 | 1.64041666667 | 14560 |
| 014500 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:01am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593028.2 | 510118.4 | 13140 | 1.64041666667 | 14500 |
| 016225 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:02am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1593024.4 | 510118.8 | 13142 | 1.64041666667 | 16225 |
| 015696 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:03am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593021.4 | 510119.2 | 13144 | 1.64041666667 | 15696 |
| 015294 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:04am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593017.6 | 510120.6 | 13146 | 1.64041666667 | 15294 |
| 014353 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:05am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1593014.8 | 510121.9 | 13148 | 1.64041666667 | 14353 |
| 014268 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:06am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1593011.5 | 510123.2 | 13150 | 1.64041666667 | 14268 |
| 015297 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:07am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1593008.6 | 510124.6 | 13152 | 1.64041666667 | 15297 |
| 014744 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:08am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1593004.8 | 510125.3 | 13154 | 1.64041666667 | 14744 |
| 013196 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:09am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1593001.5 | 510125.0 | 13156 | 1.64041666667 | 13196 |
| 014669 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:10am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592998.2 | 510124.8 | 13158 | 1.64041666667 | 14669 |
| 014587 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:11am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592994.5 | 510125.3 | 13160 | 1.64041666667 | 14587 |
| 014686 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:12am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592991.1 | 510125.8 | 13162 | 1.64041666667 | 14686 |
| 015161 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:13am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592987.7 | 510125.7 | 13164 | 1.64041666667 | 15161 |
| 012400 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:14am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592983.9 | 510125.2 | 13166 | 1.64041666667 | 12400 |
| 012580 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:15am | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592980.9 | 510124.8 | 13168 | 1.64041666667 | 12580 |
| 013195 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:16am | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592976.9 | 510123.6 | 13170 | 1.64041666667 | 13195 |
| 012778 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:17am | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592973.3 | 510122.2 | 13172 | 1.64041666667 | 12778 |
| 013124 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:18am | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592970.4 | 510120.5 | 13174 | 1.64041666667 | 13124 |
| 015131 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:19am | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592967.9 | 510119.3 | 13176 | 1.64041666667 | 15131 |
| 013772 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:20am | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592965.6 | 510117.8 | 13178 | 1.64041666667 | 13772 |
| 012863 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:21am | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592964.4 | 510116.7 | 13180 | 1.64041666667 | 12863 |
| 014195 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:22am | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592962.4 | 510115.0 | 13182 | 1.64041666667 | 14195 |
| 013719 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:23am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592960.3 | 510114.3 | 13184 | 1.64041666667 | 13719 |
| 013209 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:24am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592957.4 | 510113.2 | 13186 | 1.64041666667 | 13209 |
| 014252 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:25am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592955.1 | 510113.4 | 13188 | 1.64041666667 | 14252 |
| 013103 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:26am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592951.7 | 510113.0 | 13190 | 1.64041666667 | 13103 |
| 013655 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:27am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592949.5 | 510113.1 | 13192 | 1.64041666667 | 13655 |
| 015174 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:28am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592946.3 | 510113.3 | 13194 | 1.64041666667 | 15174 |
| 013063 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:29am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592944.2 | 510113.0 | 13196 | 1.64041666667 | 13063 |
| 014606 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:30am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592941.1 | 510113.5 | 13198 | 1.64041666667 | 14606 |
| 013071 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:31am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592938.5 | 510113.8 | 13200 | 1.64041666667 | 13071 |
| 014757 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:32am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592935.6 | 510113.7 | 13202 | 1.64041666667 | 14757 |
| 013019 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:33am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592932.9 | 510114.1 | 13204 | 1.64041666667 | 13019 |
| 014085 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:34am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592930.1 | 510114.0 | 13206 | 1.64041666667 | 14085 |
| 013481 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:35am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592927.3 | 510114.1 | 13208 | 1.64041666667 | 13481 |
| 013390 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:36am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592924.2 | 510113.5 | 13210 | 1.64041666667 | 13390 |
| 013097 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:37am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592921.6 | 510113.0 | 13212 | 1.64041666667 | 13097 |
| 013504 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:38am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592918.5 | 510113.3 | 13214 | 1.64041666667 | 13504 |
| 013786 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:39am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592917.4 | 510113.2 | 13216 | 1.64041666667 | 13786 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012896 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:40am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592917.4 | 510113.3 | 13218 | 1.64041666667 | 12896 |
| 013094 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:41am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592917.5 | 510113.1 | 13220 | 1.64041666667 | 13094 |
| 013953 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:42am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592917.6 | 510113.0 | 13222 | 1.64041666667 | 13953 |
| 012968 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:43am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592917.7 | 510112.9 | 13224 | 1.64041666667 | 12968 |
| 013832 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:44am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592917.3 | 510113.1 | 13226 | 1.64041666667 | 13832 |
| 012878 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:45am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592916.4 | 510113.7 | 13228 | 1.64041666667 | 12878 |
| 013359 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:46am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592916.2 | 510113.7 | 13230 | 1.64041666667 | 13359 |
| 012010 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:47am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592916.3 | 510113.7 | 13232 | 1.64041666667 | 12010 |
| 012452 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:48am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592916.4 | 510113.6 | 13234 | 1.64041666667 | 12452 |
| 013793 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:49am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592916.4 | 510113.6 | 13236 | 1.64041666667 | 13793 |
| 014188 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:50am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592916.4 | 510113.6 | 13238 | 1.64041666667 | 14188 |
| 011947 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:51am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510113.0 | 13240 | 1.64041666667 | 11947 |
| 012586 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:52am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592916.5 | 510112.8 | 13242 | 1.64041666667 | 12586 |
| 013406 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:53am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592916.5 | 510112.8 | 13244 | 1.64041666667 | 13406 |
| 013101 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:54am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592916.5 | 510112.7 | 13246 | 1.64041666667 | 13101 |
| 013505 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:55am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592916.5 | 510112.8 | 13248 | 1.64041666667 | 13505 |
| 012766 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:56am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.8 | 13250 | 1.64041666667 | 12766 |
| 012851 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:57am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.9 | 13252 | 1.64041666667 | 12851 |
| 011613 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:58am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.8 | 13254 | 1.64041666667 | 11613 |
| 012743 | 0 | GeoXH 6000 | 08/18/2015 | 11:52:59am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.8 | 13256 | 1.64041666667 | 12743 |
| 012245 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:00am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.8 | 13258 | 1.64041666667 | 12245 |
| 012301 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:01am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.8 | 13260 | 1.64041666667 | 12301 |
| 012045 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:02am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.8 | 13262 | 1.64041666667 | 12045 |
| 012821 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:03am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.9 | 13264 | 1.64041666667 | 12821 |
| 013105 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:04am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.9 | 13266 | 1.64041666667 | 13105 |
| 013566 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:05am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.9 | 13268 | 1.64041666667 | 13566 |
| 013531 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:06am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592916.5 | 510112.8 | 13270 | 1.64041666667 | 13531 |
| 012712 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:07am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.5 | 510112.8 | 13272 | 1.64041666667 | 12712 |
| 014218 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:08am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592916.5 | 510112.6 | 13274 | 1.64041666667 | 14218 |
| 012494 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:08am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592916.0 | 510113.8 | 13275 | 1.64041666667 | 12494 |
| 012693 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:10am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592915.8 | 510113.9 | 13278 | 1.64041666667 | 12693 |
| 013133 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:11am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592915.9 | 510113.6 | 13280 | 1.64041666667 | 13133 |
| 015403 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:12am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.0 | 510113.5 | 13282 | 1.64041666667 | 15403 |
| 013691 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:13am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.0 | 510113.5 | 13284 | 1.64041666667 | 13691 |
| 014702 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:14am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.0 | 510113.5 | 13286 | 1.64041666667 | 14702 |
| 012885 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:15am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.0 | 510113.5 | 13288 | 1.64041666667 | 12885 |
| 011771 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:16am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.0 | 510113.5 | 13290 | 1.64041666667 | 11771 |
| 012483 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:17am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592916.0 | 510113.5 | 13292 | 1.64041666667 | 12483 |
| 015450 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:18am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592915.7 | 510113.5 | 13294 | 1.64041666667 | 15450 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:19am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592914.4 | 510113.5 | 13296 | 1.64041666667 | 13972 |
| 013693 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:20am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592912.0 | 510112.8 | 13298 | 1.64041666667 | 13693 |
| 012723 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:21am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592909.9 | 510111.3 | 13300 | 1.64041666667 | 12723 |
| 013920 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:22am | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592907.9 | 510110.6 | 13302 | 1.64041666667 | 13920 |
| 014850 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:23am | Sensor | 1797-S0023-G-TJV.cor | 6802.7 | 1592905.5 | 510109.6 | 13304 | 1.64041666667 | 14850 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:24am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592902.0 | 510109.2 | 13306 | 1.64041666667 | 14482 |
| 012170 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:25am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592898.7 | 510109.1 | 13308 | 1.64041666667 | 12170 |
| 012252 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:26am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592894.6 | 510109.0 | 13310 | 1.64041666667 | 12252 |
| 012393 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:27am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592891.6 | 510109.0 | 13312 | 1.64041666667 | 12393 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011228 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:28am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592887.6 | 510109.3 | 13314 | 1.64041666667 | 11228 |
| 012737 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:29am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592883.9 | 510109.8 | 13316 | 1.64041666667 | 12737 |
| 012904 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:30am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592880.2 | 510110.2 | 13318 | 1.64041666667 | 12904 |
| 012586 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:31am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592876.9 | 510110.6 | 13320 | 1.64041666667 | 12586 |
| 013586 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:32am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592873.1 | 510110.2 | 13322 | 1.64041666667 | 13586 |
| 014256 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:33am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592869.4 | 510110.0 | 13324 | 1.64041666667 | 14256 |
| 013854 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:34am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592865.5 | 510110.1 | 13326 | 1.64041666667 | 13854 |
| 013303 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:35am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592862.4 | 510109.3 | 13328 | 1.64041666667 | 13303 |
| 014816 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:36am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592859.4 | 510107.0 | 13330 | 1.64041666667 | 14816 |
| 014174 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:37am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592857.0 | 510105.1 | 13332 | 1.64041666667 | 14174 |
| 013653 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:38am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592853.8 | 510103.0 | 13334 | 1.64041666667 | 13653 |
| 014123 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:39am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592851.2 | 510101.2 | 13336 | 1.64041666667 | 14123 |
| 015020 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:40am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592849.7 | 510099.8 | 13338 | 1.64041666667 | 15020 |
| 015065 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:41am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592849.0 | 510099.2 | 13340 | 1.64041666667 | 15065 |
| 015526 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:42am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592848.1 | 510100.1 | 13342 | 1.64041666667 | 15526 |
| 013661 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:43am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592846.7 | 510102.5 | 13344 | 1.64041666667 | 13661 |
| 013585 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:44am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592845.5 | 510106.2 | 13346 | 1.64041666667 | 13585 |
| 013776 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:45am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592845.1 | 510109.4 | 13348 | 1.64041666667 | 13776 |
| 013314 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:46am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592844.6 | 510113.7 | 13350 | 1.64041666667 | 13314 |
| 015088 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:47am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592844.3 | 510117.1 | 13352 | 1.64041666667 | 15088 |
| 013372 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:48am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592844.5 | 510121.5 | 13354 | 1.64041666667 | 13372 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:49am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592844.3 | 510124.5 | 13356 | 1.64041666667 | 13453 |
| 012063 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:50am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592843.3 | 510128.6 | 13358 | 1.64041666667 | 12063 |
| 011295 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:51am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592842.6 | 510131.2 | 13360 | 1.64041666667 | 11295 |
| 013893 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:52am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592841.4 | 510134.6 | 13362 | 1.64041666667 | 13893 |
| 013613 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:53am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592839.9 | 510137.2 | 13364 | 1.64041666667 | 13613 |
| 013753 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:54am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592837.6 | 510139.9 | 13366 | 1.64041666667 | 13753 |
| 011088 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:55am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592836.2 | 510141.6 | 13368 | 1.64041666667 | 11088 |
| 015762 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:56am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592835.6 | 510142.9 | 13370 | 1.64041666667 | 15762 |
| 013030 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:57am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592835.3 | 510143.0 | 13372 | 1.64041666667 | 13030 |
| 013217 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:58am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592835.3 | 510143.0 | 13374 | 1.64041666667 | 13217 |
| 012964 | 0 | GeoXH 6000 | 08/18/2015 | 11:53:59am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592835.7 | 510143.1 | 13376 | 1.64041666667 | 12964 |
| 013111 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:00am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592835.6 | 510143.1 | 13378 | 1.64041666667 | 13111 |
| 013237 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:01am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592835.6 | 510143.1 | 13380 | 1.64041666667 | 13237 |
| 013209 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:02am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592836.2 | 510143.5 | 13382 | 1.64041666667 | 13209 |
| 013202 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:03am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592837.2 | 510144.5 | 13384 | 1.64041666667 | 13202 |
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:04am | Sensor | 1797-S0023-G-TJV.cor | 6800.8 | 1592837.6 | 510145.0 | 13386 | 1.64041666667 | 13320 |
| 014010 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:05am | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592837.7 | 510145.1 | 13388 | 1.64041666667 | 14010 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:06am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592836.1 | 510144.8 | 13390 | 1.64041666667 | 13132 |
| 014863 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:07am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592835.9 | 510144.3 | 13392 | 1.64041666667 | 14863 |
| 013976 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:08am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592836.2 | 510144.3 | 13394 | 1.64041666667 | 13976 |
| 013004 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:09am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592836.6 | 510144.8 | 13396 | 1.64041666667 | 13004 |
| 012461 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:10am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592836.8 | 510144.7 | 13398 | 1.64041666667 | 12461 |
| 013675 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:11am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592837.0 | 510143.7 | 13400 | 1.64041666667 | 13675 |
| 014788 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:12am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592837.8 | 510142.3 | 13402 | 1.64041666667 | 14788 |
| 014077 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:13am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592838.7 | 510140.8 | 13404 | 1.64041666667 | 14077 |
| 012759 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:14am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592839.9 | 510138.3 | 13406 | 1.64041666667 | 12759 |
| 012699 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:15am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592840.0 | 510135.9 | 13408 | 1.64041666667 | 12699 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012205 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:16am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592840.5 | 510133.4 | 13410 | 1.64041666667 | 12205 |
| 014151 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:17am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592840.0 | 510130.9 | 13412 | 1.64041666667 | 14151 |
| 012747 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:18am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592840.2 | 510127.8 | 13414 | 1.64041666667 | 12747 |
| 013567 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:19am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592840.1 | 510125.3 | 13416 | 1.64041666667 | 13567 |
| 012631 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:20am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592840.3 | 510122.0 | 13418 | 1.64041666667 | 12631 |
| 013867 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:21am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592840.9 | 510119.6 | 13420 | 1.64041666667 | 13867 |
| 014927 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:22am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592841.2 | 510116.5 | 13422 | 1.64041666667 | 14927 |
| 015371 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:23am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592842.1 | 510113.9 | 13424 | 1.64041666667 | 15371 |
| 012693 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:24am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592842.4 | 510111.0 | 13426 | 1.64041666667 | 12693 |
| 014903 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:25am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592843.1 | 510108.7 | 13428 | 1.64041666667 | 14903 |
| 015695 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:26am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592844.2 | 510105.9 | 13430 | 1.64041666667 | 15695 |
| 015654 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:27am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592844.8 | 510103.5 | 13432 | 1.64041666667 | 15654 |
| 014413 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:28am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592846.7 | 510101.2 | 13434 | 1.64041666667 | 14413 |
| 012783 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:29am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592847.9 | 510099.0 | 13436 | 1.64041666667 | 12783 |
| 013725 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:30am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592850.0 | 510096.3 | 13438 | 1.64041666667 | 13725 |
| 014531 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:31am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592851.4 | 510094.0 | 13440 | 1.64041666667 | 14531 |
| 014313 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:32am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592851.1 | 510091.1 | 13442 | 1.64041666667 | 14313 |
| 014048 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:33am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592853.0 | 510089.0 | 13444 | 1.64041666667 | 14048 |
| 014042 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:34am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592853.7 | 510086.9 | 13446 | 1.64041666667 | 14042 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:35am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592855.6 | 510085.7 | 13448 | 1.64041666667 | 14550 |
| 014917 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:36am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592858.2 | 510083.2 | 13450 | 1.64041666667 | 14917 |
| 015489 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:37am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592859.9 | 510080.9 | 13452 | 1.64041666667 | 15489 |
| 015272 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:38am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592861.3 | 510077.9 | 13454 | 1.64041666667 | 15272 |
| 013928 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:39am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592861.8 | 510074.9 | 13456 | 1.64041666667 | 13928 |
| 014102 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:40am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592863.2 | 510071.8 | 13458 | 1.64041666667 | 14102 |
| 013485 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:41am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592864.0 | 510068.9 | 13460 | 1.64041666667 | 13485 |
| 015041 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:42am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592865.0 | 510065.8 | 13462 | 1.64041666667 | 15041 |
| 014530 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:43am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592866.1 | 510064.1 | 13464 | 1.64041666667 | 14530 |
| 014912 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:44am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592867.5 | 510061.0 | 13466 | 1.64041666667 | 14912 |
| 013478 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:45am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592868.9 | 510059.0 | 13468 | 1.64041666667 | 13478 |
| 013659 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:46am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592870.4 | 510055.5 | 13470 | 1.64041666667 | 13659 |
| 013465 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:47am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592871.6 | 510053.0 | 13472 | 1.64041666667 | 13465 |
| 013206 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:48am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592873.2 | 510050.3 | 13474 | 1.64041666667 | 13206 |
| 014341 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:49am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592874.0 | 510047.9 | 13476 | 1.64041666667 | 14341 |
| 014895 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:50am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592875.9 | 510044.7 | 13478 | 1.64041666667 | 14895 |
| 012933 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:51am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592877.2 | 510041.9 | 13480 | 1.64041666667 | 12933 |
| 013253 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:52am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592878.0 | 510038.9 | 13482 | 1.64041666667 | 13253 |
| 012523 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:53am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592879.8 | 510036.5 | 13484 | 1.64041666667 | 12523 |
| 013511 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:54am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592881.2 | 510034.4 | 13486 | 1.64041666667 | 13511 |
| 013277 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:55am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592881.7 | 510034.1 | 13488 | 1.64041666667 | 13277 |
| 015289 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:56am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592881.6 | 510033.8 | 13490 | 1.64041666667 | 15289 |
| 013152 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:57am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592881.5 | 510033.6 | 13492 | 1.64041666667 | 13152 |
| 013278 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:58am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592881.5 | 510033.7 | 13494 | 1.64041666667 | 13278 |
| 012799 | 0 | GeoXH 6000 | 08/18/2015 | 11:54:59am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592881.5 | 510033.7 | 13496 | 1.64041666667 | 12799 |
| 014419 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:00am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592881.7 | 510033.6 | 13498 | 1.64041666667 | 14419 |
| 014435 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:01am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592883.0 | 510032.9 | 13500 | 1.64041666667 | 14435 |
| 014918 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:02am | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592883.2 | 510032.7 | 13502 | 1.64041666667 | 14918 |
| 014319 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:03am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592881.9 | 510033.7 | 13504 | 1.64041666667 | 14319 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012970 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:04am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592881.5 | 510033.7 | 13506 | 1.64041666667 | 12970 |
| 013982 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:05am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592882.4 | 510033.3 | 13508 | 1.64041666667 | 13982 |
| 013605 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:06am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592884.2 | 510033.6 | 13510 | 1.64041666667 | 13605 |
| 014261 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:07am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592885.0 | 510034.8 | 13512 | 1.64041666667 | 14261 |
| 015925 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:08am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592885.8 | 510035.9 | 13514 | 1.64041666667 | 15925 |
| 013821 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:09am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592885.4 | 510037.8 | 13516 | 1.64041666667 | 13821 |
| 013715 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:10am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592884.9 | 510041.3 | 13518 | 1.64041666667 | 13715 |
| 013628 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:11am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592884.0 | 510044.2 | 13520 | 1.64041666667 | 13628 |
| 012497 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:12am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592882.2 | 510046.7 | 13522 | 1.64041666667 | 12497 |
| 013654 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:13am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592881.6 | 510049.0 | 13524 | 1.64041666667 | 13654 |
| 013253 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:14am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592879.9 | 510052.2 | 13526 | 1.64041666667 | 13253 |
| 014143 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:15am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592878.4 | 510054.9 | 13528 | 1.64041666667 | 14143 |
| 013586 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:16am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592877.4 | 510058.5 | 13530 | 1.64041666667 | 13586 |
| 012966 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:17am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592876.5 | 510060.8 | 13532 | 1.64041666667 | 12966 |
| 013831 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:18am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592876.4 | 510064.0 | 13534 | 1.64041666667 | 13831 |
| 012487 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:19am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592876.3 | 510065.3 | 13536 | 1.64041666667 | 12487 |
| 012722 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:20am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592877.1 | 510065.3 | 13538 | 1.64041666667 | 12722 |
| 013500 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:21am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592877.8 | 510064.2 | 13540 | 1.64041666667 | 13500 |
| 014805 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:22am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592877.8 | 510061.1 | 13542 | 1.64041666667 | 14805 |
| 014291 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:23am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592878.7 | 510058.1 | 13544 | 1.64041666667 | 14291 |
| 014733 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:24am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592880.3 | 510054.1 | 13546 | 1.64041666667 | 14733 |
| 015593 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:25am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592881.3 | 510050.6 | 13548 | 1.64041666667 | 15593 |
| 014458 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:26am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592882.0 | 510046.4 | 13550 | 1.64041666667 | 14458 |
| 013874 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:27am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592882.0 | 510042.7 | 13552 | 1.64041666667 | 13874 |
| 013698 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:28am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592882.4 | 510039.1 | 13554 | 1.64041666667 | 13698 |
| 014194 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:29am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592882.9 | 510035.8 | 13556 | 1.64041666667 | 14194 |
| 013118 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:30am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592882.3 | 510033.1 | 13558 | 1.64041666667 | 13118 |
| 012909 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:31am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592882.0 | 510032.9 | 13560 | 1.64041666667 | 12909 |
| 014477 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:32am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592879.6 | 510030.0 | 13562 | 1.64041666667 | 14477 |
| 012859 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:33am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592877.1 | 510028.9 | 13564 | 1.64041666667 | 12859 |
| 012514 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:34am | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592876.8 | 510028.6 | 13566 | 1.64041666667 | 12514 |
| 014348 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:35am | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592876.8 | 510028.5 | 13568 | 1.64041666667 | 14348 |
| 014747 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:36am | Sensor | 1797-S0023-G-TJV.cor | 6800.6 | 1592877.6 | 510028.2 | 13570 | 1.64041666667 | 14747 |
| 014336 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:37am | Sensor | 1797-S0023-G-TJV.cor | 6800.2 | 1592877.1 | 510029.0 | 13572 | 1.64041666667 | 14336 |
| 014174 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:38am | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592877.8 | 510029.2 | 13574 | 1.64041666667 | 14174 |
| 014523 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:39am | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592878.4 | 510029.1 | 13576 | 1.64041666667 | 14523 |
| 012690 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:40am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592877.1 | 510029.5 | 13578 | 1.64041666667 | 12690 |
| 014992 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:41am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592876.1 | 510031.0 | 13580 | 1.64041666667 | 14992 |
| 014008 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:42am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592874.2 | 510033.9 | 13582 | 1.64041666667 | 14008 |
| 012652 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:43am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592871.8 | 510036.3 | 13584 | 1.64041666667 | 12652 |
| 013213 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:44am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592869.8 | 510040.0 | 13586 | 1.64041666667 | 13213 |
| 013743 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:45am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592868.8 | 510042.9 | 13588 | 1.64041666667 | 13743 |
| 014085 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:46am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592866.6 | 510046.2 | 13590 | 1.64041666667 | 14085 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:47am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592866.0 | 510048.6 | 13592 | 1.64041666667 | 13631 |
| 013458 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:48am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592864.7 | 510052.6 | 13594 | 1.64041666667 | 13458 |
| 013449 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:49am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592863.7 | 510054.8 | 13596 | 1.64041666667 | 13449 |
| 013486 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:50am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592863.0 | 510058.1 | 13598 | 1.64041666667 | 13486 |
| 015041 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:51am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592861.5 | 510061.2 | 13600 | 1.64041666667 | 15041 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013120 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:52am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592860.1 | 510064.2 | 13602 | 1.64041666667 | 13120 |
| 014410 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:53am | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592859.5 | 510066.7 | 13604 | 1.64041666667 | 14410 |
| 013232 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:54am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592857.2 | 510070.0 | 13606 | 1.64041666667 | 13232 |
| 013598 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:55am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592855.9 | 510072.6 | 13608 | 1.64041666667 | 13598 |
| 014919 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:56am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592854.6 | 510074.9 | 13610 | 1.64041666667 | 14919 |
| 015790 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:57am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592853.8 | 510077.6 | 13612 | 1.64041666667 | 15790 |
| 014177 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:58am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592852.8 | 510081.0 | 13614 | 1.64041666667 | 14177 |
| 013654 | 0 | GeoXH 6000 | 08/18/2015 | 11:55:59am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592851.9 | 510083.6 | 13616 | 1.64041666667 | 13654 |
| 013643 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:00am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592851.3 | 510086.8 | 13618 | 1.64041666667 | 13643 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:01am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592849.8 | 510089.7 | 13620 | 1.64041666667 | 14201 |
| 014975 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:02am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592848.7 | 510092.7 | 13622 | 1.64041666667 | 14975 |
| 015623 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:03am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592847.9 | 510095.6 | 13624 | 1.64041666667 | 15623 |
| 015306 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:04am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592846.5 | 510098.5 | 13626 | 1.64041666667 | 15306 |
| 014536 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:05am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592845.8 | 510101.4 | 13628 | 1.64041666667 | 14536 |
| 014524 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:06am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592843.9 | 510104.3 | 13630 | 1.64041666667 | 14524 |
| 016171 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:07am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592842.4 | 510107.5 | 13632 | 1.64041666667 | 16171 |
| 016042 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:08am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592841.6 | 510110.8 | 13634 | 1.64041666667 | 16042 |
| 016460 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:09am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592840.5 | 510113.4 | 13636 | 1.64041666667 | 16460 |
| 014765 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:10am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592839.3 | 510116.8 | 13638 | 1.64041666667 | 14765 |
| 013861 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:11am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592837.4 | 510120.0 | 13640 | 1.64041666667 | 13861 |
| 013575 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:12am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592835.7 | 510123.3 | 13642 | 1.64041666667 | 13575 |
| 014583 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:13am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592834.9 | 510125.8 | 13644 | 1.64041666667 | 14583 |
| 013246 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:14am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592833.1 | 510128.7 | 13646 | 1.64041666667 | 13246 |
| 015011 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:15am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592831.9 | 510131.4 | 13648 | 1.64041666667 | 15011 |
| 014763 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:16am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592832.4 | 510134.3 | 13650 | 1.64041666667 | 14763 |
| 013920 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:17am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592832.9 | 510137.3 | 13652 | 1.64041666667 | 13920 |
| 012060 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:18am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592834.3 | 510140.5 | 13654 | 1.64041666667 | 12060 |
| 012375 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:18am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592835.8 | 510142.2 | 13655 | 1.64041666667 | 12375 |
| 012483 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:20am | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592837.4 | 510144.4 | 13658 | 1.64041666667 | 12483 |
| 012061 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:20am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592835.7 | 510143.2 | 13659 | 1.64041666667 | 12061 |
| 013215 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:22am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592835.9 | 510140.3 | 13662 | 1.64041666667 | 13215 |
| 014553 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:23am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592834.1 | 510137.6 | 13664 | 1.64041666667 | 14553 |
| 013598 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:24am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592832.4 | 510135.7 | 13666 | 1.64041666667 | 13598 |
| 014439 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:25am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592832.1 | 510134.0 | 13668 | 1.64041666667 | 14439 |
| 013480 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:26am | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592830.8 | 510132.5 | 13670 | 1.64041666667 | 13480 |
| 013120 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:27am | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592830.8 | 510132.3 | 13672 | 1.64041666667 | 13120 |
| 012790 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:28am | Sensor | 1797-S0023-G-TJV.cor | 6800.3 | 1592830.9 | 510132.9 | 13674 | 1.64041666667 | 12790 |
| 015527 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:29am | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592831.0 | 510133.9 | 13676 | 1.64041666667 | 15527 |
| 016181 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:30am | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592830.6 | 510132.3 | 13678 | 1.64041666667 | 16181 |
| 014995 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:31am | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592828.0 | 510129.7 | 13680 | 1.64041666667 | 14995 |
| 015029 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:32am | Sensor | 1797-S0023-G-TJV.cor | 6800.2 | 1592826.2 | 510128.4 | 13682 | 1.64041666667 | 15029 |
| 013357 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:33am | Sensor | 1797-S0023-G-TJV.cor | 6800.0 | 1592825.9 | 510128.3 | 13684 | 1.64041666667 | 13357 |
| 013149 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:34am | Sensor | 1797-S0023-G-TJV.cor | 6800.6 | 1592826.2 | 510128.5 | 13686 | 1.64041666667 | 13149 |
| 014747 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:35am | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592827.2 | 510130.3 | 13688 | 1.64041666667 | 14747 |
| 013946 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:36am | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592827.2 | 510130.6 | 13690 | 1.64041666667 | 13946 |
| 014496 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:37am | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592827.1 | 510130.5 | 13692 | 1.64041666667 | 14496 |
| 015714 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:38am | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592826.9 | 510128.9 | 13694 | 1.64041666667 | 15714 |
| 014577 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:39am | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592826.4 | 510126.5 | 13696 | 1.64041666667 | 14577 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013252 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:40am | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592826.7 | 510123.3 | 13698 | 1.64041666667 | 13252 |
| 013723 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:41am | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592828.0 | 510120.6 | 13700 | 1.64041666667 | 13723 |
| 013690 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:42am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592828.7 | 510117.2 | 13702 | 1.64041666667 | 13690 |
| 012722 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:43am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592830.3 | 510114.1 | 13704 | 1.64041666667 | 12722 |
| 012720 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:44am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592831.8 | 510110.7 | 13706 | 1.64041666667 | 12720 |
| 013890 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:45am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592832.4 | 510108.0 | 13708 | 1.64041666667 | 13890 |
| 015202 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:46am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592834.0 | 510104.9 | 13710 | 1.64041666667 | 15202 |
| 013430 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:47am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592835.1 | 510101.8 | 13712 | 1.64041666667 | 13430 |
| 015027 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:48am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592836.4 | 510098.4 | 13714 | 1.64041666667 | 15027 |
| 014767 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:49am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592838.2 | 510096.0 | 13716 | 1.64041666667 | 14767 |
| 013561 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:50am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592839.1 | 510092.9 | 13718 | 1.64041666667 | 13561 |
| 012990 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:51am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592840.7 | 510090.3 | 13720 | 1.64041666667 | 12990 |
| 015247 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:52am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592842.2 | 510087.2 | 13722 | 1.64041666667 | 15247 |
| 013862 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:53am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592843.4 | 510084.0 | 13724 | 1.64041666667 | 13862 |
| 013635 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:54am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592844.3 | 510081.6 | 13726 | 1.64041666667 | 13635 |
| 014238 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:55am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592845.3 | 510078.7 | 13728 | 1.64041666667 | 14238 |
| 013159 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:56am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592847.1 | 510075.9 | 13730 | 1.64041666667 | 13159 |
| 012530 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:57am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592848.6 | 510073.2 | 13732 | 1.64041666667 | 12530 |
| 013542 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:58am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592849.9 | 510069.4 | 13734 | 1.64041666667 | 13542 |
| 013975 | 0 | GeoXH 6000 | 08/18/2015 | 11:56:59am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592851.4 | 510067.4 | 13736 | 1.64041666667 | 13975 |
| 013604 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:00am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592852.9 | 510064.6 | 13738 | 1.64041666667 | 13604 |
| 014411 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:01am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592854.8 | 510061.9 | 13740 | 1.64041666667 | 14411 |
| 014372 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:02am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592856.5 | 510059.2 | 13742 | 1.64041666667 | 14372 |
| 014723 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:03am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592857.7 | 510056.6 | 13744 | 1.64041666667 | 14723 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:04am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592859.5 | 510054.5 | 13746 | 1.64041666667 | 14210 |
| 015012 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:05am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592860.9 | 510051.6 | 13748 | 1.64041666667 | 15012 |
| 014943 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:06am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592862.7 | 510049.3 | 13750 | 1.64041666667 | 14943 |
| 013935 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:07am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592864.5 | 510046.3 | 13752 | 1.64041666667 | 13935 |
| 013743 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:08am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592866.0 | 510043.5 | 13754 | 1.64041666667 | 13743 |
| 015256 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:09am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592867.4 | 510041.5 | 13756 | 1.64041666667 | 15256 |
| 014764 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:10am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592868.5 | 510038.4 | 13758 | 1.64041666667 | 14764 |
| 015031 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:11am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592870.4 | 510036.1 | 13760 | 1.64041666667 | 15031 |
| 014197 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:12am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592872.1 | 510033.5 | 13762 | 1.64041666667 | 14197 |
| 014379 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:13am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592873.4 | 510031.7 | 13764 | 1.64041666667 | 14379 |
| 015295 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:14am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592875.6 | 510029.1 | 13766 | 1.64041666667 | 15295 |
| 016243 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:15am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592876.5 | 510027.9 | 13768 | 1.64041666667 | 16243 |
| 015521 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:16am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592876.4 | 510027.7 | 13770 | 1.64041666667 | 15521 |
| 014020 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:17am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592874.9 | 510028.0 | 13772 | 1.64041666667 | 14020 |
| 015895 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:18am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592873.0 | 510025.9 | 13774 | 1.64041666667 | 15895 |
| 014653 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:19am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592869.9 | 510024.4 | 13776 | 1.64041666667 | 14653 |
| 013713 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:20am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592867.3 | 510023.3 | 13778 | 1.64041666667 | 13713 |
| 013178 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:21am | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592865.3 | 510022.8 | 13780 | 1.64041666667 | 13178 |
| 013164 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:22am | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592866.0 | 510022.6 | 13782 | 1.64041666667 | 13164 |
| 011481 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:22am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592867.0 | 510022.9 | 13783 | 1.64041666667 | 11481 |
| 014240 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:24am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592866.9 | 510023.5 | 13786 | 1.64041666667 | 14240 |
| 013070 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:25am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592866.6 | 510023.8 | 13788 | 1.64041666667 | 13070 |
| 011607 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:26am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592866.1 | 510026.5 | 13790 | 1.64041666667 | 11607 |
| 013162 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:27am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592866.4 | 510029.5 | 13792 | 1.64041666667 | 13162 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013040 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:28am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592865.0 | 510031.9 | 13794 | 1.64041666667 | 13040 |
| 013940 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:28am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592864.1 | 510034.1 | 13795 | 1.64041666667 | 13940 |
| 013055 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:30am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592862.0 | 510037.2 | 13798 | 1.64041666667 | 13055 |
| 013523 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:31am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592860.4 | 510040.1 | 13800 | 1.64041666667 | 13523 |
| 013671 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:32am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592859.4 | 510043.4 | 13802 | 1.64041666667 | 13671 |
| 014367 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:32am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592858.0 | 510045.5 | 13803 | 1.64041666667 | 14367 |
| 014812 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:34am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592856.6 | 510049.1 | 13806 | 1.64041666667 | 14812 |
| 013783 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:35am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592855.6 | 510052.3 | 13808 | 1.64041666667 | 13783 |
| 014965 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:36am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592854.6 | 510054.9 | 13810 | 1.64041666667 | 14965 |
| 014451 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:37am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592853.9 | 510057.9 | 13812 | 1.64041666667 | 14451 |
| 013542 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:38am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592851.7 | 510060.9 | 13814 | 1.64041666667 | 13542 |
| 013465 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:39am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592850.4 | 510063.1 | 13816 | 1.64041666667 | 13465 |
| 014586 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:40am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592849.2 | 510066.4 | 13818 | 1.64041666667 | 14586 |
| 014416 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:41am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592847.7 | 510068.6 | 13820 | 1.64041666667 | 14416 |
| 014614 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:42am | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592846.2 | 510071.7 | 13822 | 1.64041666667 | 14614 |
| 013673 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:43am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592844.3 | 510074.4 | 13824 | 1.64041666667 | 13673 |
| 013888 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:44am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592842.5 | 510077.3 | 13826 | 1.64041666667 | 13888 |
| 014812 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:45am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592841.7 | 510080.2 | 13828 | 1.64041666667 | 14812 |
| 013933 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:46am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592840.4 | 510083.2 | 13830 | 1.64041666667 | 13933 |
| 015153 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:46am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592839.1 | 510085.6 | 13831 | 1.64041666667 | 15153 |
| 013508 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:48am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592837.9 | 510089.0 | 13834 | 1.64041666667 | 13508 |
| 013847 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:49am | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592836.9 | 510090.9 | 13836 | 1.64041666667 | 13847 |
| 013811 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:50am | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592836.4 | 510094.1 | 13838 | 1.64041666667 | 13811 |
| 012783 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:50am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592835.1 | 510096.5 | 13839 | 1.64041666667 | 12783 |
| 013635 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:52am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592833.3 | 510099.9 | 13842 | 1.64041666667 | 13635 |
| 012588 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:52am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592832.5 | 510102.4 | 13843 | 1.64041666667 | 12588 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:54am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592830.6 | 510105.4 | 13846 | 1.64041666667 | 14067 |
| 013417 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:55am | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592830.4 | 510107.4 | 13848 | 1.64041666667 | 13417 |
| 013494 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:56am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592828.2 | 510111.0 | 13850 | 1.64041666667 | 13494 |
| 014083 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:56am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592826.4 | 510112.9 | 13851 | 1.64041666667 | 14083 |
| 013631 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:58am | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592825.0 | 510116.0 | 13854 | 1.64041666667 | 13631 |
| 014477 | 0 | GeoXH 6000 | 08/18/2015 | 11:57:58am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592823.3 | 510118.3 | 13855 | 1.64041666667 | 14477 |
| 013309 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:00am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592821.2 | 510121.0 | 13858 | 1.64041666667 | 13309 |
| 012177 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:00am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592819.9 | 510123.2 | 13859 | 1.64041666667 | 12177 |
| 014714 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:02am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592817.6 | 510124.5 | 13862 | 1.64041666667 | 14714 |
| 014148 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:02am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592816.6 | 510125.3 | 13863 | 1.64041666667 | 14148 |
| 014367 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:04am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592815.3 | 510125.7 | 13866 | 1.64041666667 | 14367 |
| 012381 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:04am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592815.0 | 510125.1 | 13867 | 1.64041666667 | 12381 |
| 012365 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:06am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592815.1 | 510125.1 | 13870 | 1.64041666667 | 12365 |
| 013531 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:06am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592815.0 | 510125.2 | 13871 | 1.64041666667 | 13531 |
| 014332 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:08am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592816.0 | 510125.7 | 13874 | 1.64041666667 | 14332 |
| 014353 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:09am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592817.7 | 510125.9 | 13876 | 1.64041666667 | 14353 |
| 014778 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:10am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592820.5 | 510126.8 | 13878 | 1.64041666667 | 14778 |
| 013324 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:10am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592822.4 | 510127.5 | 13879 | 1.64041666667 | 13324 |
| 013771 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:12am | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592825.6 | 510127.7 | 13882 | 1.64041666667 | 13771 |
| 014152 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:13am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592825.6 | 510127.5 | 13884 | 1.64041666667 | 14152 |
| 013078 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:14am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592823.9 | 510127.3 | 13886 | 1.64041666667 | 13078 |
| 013499 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:15am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592820.4 | 510126.5 | 13888 | 1.64041666667 | 13499 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013665 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:16am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592817.8 | 510125.8 | 13890 | 1.64041666667 | 13665 |
| 012592 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:17am | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592816.5 | 510125.9 | 13892 | 1.64041666667 | 12592 |
| 013604 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:18am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592816.7 | 510126.0 | 13894 | 1.64041666667 | 13604 |
| 014831 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:18am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592816.5 | 510126.0 | 13895 | 1.64041666667 | 14831 |
| 013457 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:20am | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592815.6 | 510124.0 | 13898 | 1.64041666667 | 13457 |
| 014344 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:20am | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592813.9 | 510122.5 | 13899 | 1.64041666667 | 14344 |
| 013006 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:22am | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592811.4 | 510120.0 | 13902 | 1.64041666667 | 13006 |
| 014741 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:23am | Sensor | 1797-S0023-G-TJV.cor | 6800.6 | 1592811.0 | 510119.7 | 13904 | 1.64041666667 | 14741 |
| 014035 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:24am | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592812.1 | 510120.3 | 13906 | 1.64041666667 | 14035 |
| 016049 | 0 | GeoXH 6000 | 08/18/2015 | 11:58:24am | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592810.9 | 510119.3 | 13907 | 1.64041666667 | 16049 |
| 013620 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.6 | 510104.3 | 14326 | 1.64041666667 | 13620 |
| 013575 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.8 | 510104.1 | 14328 | 1.64041666667 | 13575 |
| 014373 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.8 | 510104.0 | 14330 | 1.64041666667 | 14373 |
| 013763 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592756.6 | 510104.0 | 14332 | 1.64041666667 | 13763 |
| 012650 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592756.5 | 510104.3 | 14334 | 1.64041666667 | 12650 |
| 012582 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.6 | 510104.2 | 14336 | 1.64041666667 | 12582 |
| 013315 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.6 | 510104.1 | 14338 | 1.64041666667 | 13315 |
| 012599 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.6 | 510104.0 | 14340 | 1.64041666667 | 12599 |
| 012719 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.6 | 510104.0 | 14342 | 1.64041666667 | 12719 |
| 012540 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.6 | 510104.1 | 14344 | 1.64041666667 | 12540 |
| 013335 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.6 | 510104.1 | 14346 | 1.64041666667 | 13335 |
| 012963 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.7 | 510104.1 | 14348 | 1.64041666667 | 12963 |
| 013500 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592757.5 | 510104.3 | 14350 | 1.64041666667 | 13500 |
| 012315 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592757.9 | 510104.2 | 14352 | 1.64041666667 | 12315 |
| 013128 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592757.6 | 510104.3 | 14354 | 1.64041666667 | 13128 |
| 014142 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592757.3 | 510104.3 | 14356 | 1.64041666667 | 14142 |
| 013075 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592757.4 | 510104.4 | 14358 | 1.64041666667 | 13075 |
| 014069 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592757.7 | 510105.0 | 14360 | 1.64041666667 | 14069 |
| 013807 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:40pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592758.3 | 510105.7 | 14362 | 1.64041666667 | 13807 |
| 014371 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592758.4 | 510105.1 | 14364 | 1.64041666667 | 14371 |
| 012922 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592758.9 | 510105.6 | 14366 | 1.64041666667 | 12922 |
| 014240 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592758.9 | 510105.8 | 14368 | 1.64041666667 | 14240 |
| 012230 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592758.9 | 510105.7 | 14370 | 1.64041666667 | 12230 |
| 010917 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592758.9 | 510105.8 | 14372 | 1.64041666667 | 10917 |
| 012479 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592758.9 | 510105.8 | 14374 | 1.64041666667 | 12479 |
| 012630 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592758.9 | 510105.8 | 14376 | 1.64041666667 | 12630 |
| 014407 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592758.9 | 510105.8 | 14378 | 1.64041666667 | 14407 |
| 013141 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592758.9 | 510105.8 | 14380 | 1.64041666667 | 13141 |
| 012105 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592758.9 | 510105.8 | 14382 | 1.64041666667 | 12105 |
| 014366 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592759.0 | 510105.7 | 14384 | 1.64041666667 | 14366 |
| 011901 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592759.0 | 510105.7 | 14386 | 1.64041666667 | 11901 |
| 013175 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592759.0 | 510105.8 | 14388 | 1.64041666667 | 13175 |
| 013613 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592759.0 | 510105.8 | 14390 | 1.64041666667 | 13613 |
| 012433 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592759.1 | 510105.8 | 14392 | 1.64041666667 | 12433 |
| 013788 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592759.6 | 510105.5 | 14394 | 1.64041666667 | 13788 |
| 015357 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592760.7 | 510104.5 | 14396 | 1.64041666667 | 15357 |
| 013289 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592761.3 | 510103.2 | 14398 | 1.64041666667 | 13289 |
| 013072 | 0 | GeoXH 6000 | 08/18/2015 | 12:05:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592762.0 | 510103.0 | 14400 | 1.64041666667 | 13072 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013978 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592762.0 | 510103.0 | 14402 | 1.64041666667 | 13978 |
| 012584 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592761.7 | 510102.5 | 14404 | 1.64041666667 | 12584 |
| 012176 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592761.7 | 510102.6 | 14406 | 1.64041666667 | 12176 |
| 013574 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592761.7 | 510102.7 | 14408 | 1.64041666667 | 13574 |
| 014343 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592761.7 | 510102.9 | 14410 | 1.64041666667 | 14343 |
| 013185 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592762.0 | 510103.2 | 14412 | 1.64041666667 | 13185 |
| 012596 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592762.2 | 510102.6 | 14414 | 1.64041666667 | 12596 |
| 014399 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:07pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592763.0 | 510100.8 | 14416 | 1.64041666667 | 14399 |
| 014940 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592763.4 | 510098.7 | 14418 | 1.64041666667 | 14940 |
| 014295 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:09pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592764.5 | 510096.6 | 14420 | 1.64041666667 | 14295 |
| 014373 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592765.0 | 510094.1 | 14422 | 1.64041666667 | 14373 |
| 015173 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592766.7 | 510092.2 | 14424 | 1.64041666667 | 15173 |
| 014173 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592767.7 | 510090.2 | 14426 | 1.64041666667 | 14173 |
| 015393 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592769.5 | 510088.3 | 14428 | 1.64041666667 | 15393 |
| 013898 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592770.7 | 510086.3 | 14430 | 1.64041666667 | 13898 |
| 013104 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:15pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592772.4 | 510084.3 | 14432 | 1.64041666667 | 13104 |
| 013386 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:16pm | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592773.7 | 510082.5 | 14434 | 1.64041666667 | 13386 |
| 012016 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:17pm | Sensor | 1797-S0023-G-TJV.cor | 6800.8 | 1592775.2 | 510080.5 | 14436 | 1.64041666667 | 12016 |
| 011704 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:18pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592776.4 | 510079.4 | 14438 | 1.64041666667 | 11704 |
| 013126 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592777.1 | 510076.9 | 14440 | 1.64041666667 | 13126 |
| 012881 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592778.3 | 510075.1 | 14442 | 1.64041666667 | 12881 |
| 014890 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592778.8 | 510072.8 | 14444 | 1.64041666667 | 14890 |
| 016562 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592780.3 | 510071.3 | 14446 | 1.64041666667 | 16562 |
| 014700 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592781.4 | 510069.1 | 14448 | 1.64041666667 | 14700 |
| 014985 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592782.9 | 510067.0 | 14450 | 1.64041666667 | 14985 |
| 014786 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592784.5 | 510064.3 | 14452 | 1.64041666667 | 14786 |
| 013356 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592786.0 | 510062.1 | 14454 | 1.64041666667 | 13356 |
| 012969 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592788.2 | 510059.4 | 14456 | 1.64041666667 | 12969 |
| 013562 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592789.2 | 510057.3 | 14458 | 1.64041666667 | 13562 |
| 014640 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592790.7 | 510055.2 | 14460 | 1.64041666667 | 14640 |
| 012900 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592791.9 | 510052.7 | 14462 | 1.64041666667 | 12900 |
| 014685 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592793.8 | 510050.6 | 14464 | 1.64041666667 | 14685 |
| 014201 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592795.1 | 510048.6 | 14466 | 1.64041666667 | 14201 |
| 014350 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592796.4 | 510046.5 | 14468 | 1.64041666667 | 14350 |
| 013355 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592798.5 | 510044.7 | 14470 | 1.64041666667 | 13355 |
| 012829 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592800.3 | 510042.2 | 14472 | 1.64041666667 | 12829 |
| 015777 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592802.2 | 510040.5 | 14474 | 1.64041666667 | 15777 |
| 015254 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592803.5 | 510037.8 | 14476 | 1.64041666667 | 15254 |
| 012993 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592805.1 | 510035.9 | 14478 | 1.64041666667 | 12993 |
| 012338 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592807.1 | 510033.1 | 14480 | 1.64041666667 | 12338 |
| 013134 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:40pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592808.3 | 510030.7 | 14482 | 1.64041666667 | 13134 |
| 013363 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592810.5 | 510028.4 | 14484 | 1.64041666667 | 13363 |
| 015071 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592811.6 | 510026.3 | 14486 | 1.64041666667 | 15071 |
| 012767 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592813.9 | 510023.7 | 14488 | 1.64041666667 | 12767 |
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592815.2 | 510021.4 | 14490 | 1.64041666667 | 12761 |
| 015520 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592817.1 | 510018.5 | 14492 | 1.64041666667 | 15520 |
| 015100 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592818.9 | 510016.9 | 14494 | 1.64041666667 | 15100 |
| 012025 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592820.6 | 510014.4 | 14496 | 1.64041666667 | 12025 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013416 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592822.5 | 510012.4 | 14498 | 1.64041666667 | 13416 |
| 014184 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592824.6 | 510009.5 | 14500 | 1.64041666667 | 14184 |
| 013026 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592826.0 | 510006.6 | 14502 | 1.64041666667 | 13026 |
| 014056 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592828.0 | 510004.2 | 14504 | 1.64041666667 | 14056 |
| 014644 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592828.9 | 510001.8 | 14506 | 1.64041666667 | 14644 |
| 015841 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592831.0 | 509999.9 | 14508 | 1.64041666667 | 15841 |
| 015300 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592831.7 | 509998.3 | 14510 | 1.64041666667 | 15300 |
| 016215 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592832.2 | 509996.8 | 14512 | 1.64041666667 | 16215 |
| 015903 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592832.6 | 509997.1 | 14514 | 1.64041666667 | 15903 |
| 016516 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592832.7 | 509997.8 | 14516 | 1.64041666667 | 16516 |
| 014149 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592832.6 | 509997.9 | 14518 | 1.64041666667 | 14149 |
| 013467 | 0 | GeoXH 6000 | 08/18/2015 | 12:06:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592831.4 | 509997.1 | 14520 | 1.64041666667 | 13467 |
| 014767 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592828.3 | 509995.3 | 14522 | 1.64041666667 | 14767 |
| 013231 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592826.6 | 509995.6 | 14524 | 1.64041666667 | 13231 |
| 013297 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592825.8 | 509995.6 | 14526 | 1.64041666667 | 13297 |
| 014634 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592826.0 | 509995.7 | 14528 | 1.64041666667 | 14634 |
| 013857 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592824.0 | 509994.3 | 14530 | 1.64041666667 | 13857 |
| 013957 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592819.7 | 509992.7 | 14532 | 1.64041666667 | 13957 |
| 014109 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:06pm | Sensor | 1797-S0023-G-TJV.cor | 6800.6 | 1592818.1 | 509992.7 | 14534 | 1.64041666667 | 14109 |
| 013427 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592819.2 | 509992.1 | 14536 | 1.64041666667 | 13427 |
| 014156 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592819.9 | 509992.4 | 14538 | 1.64041666667 | 14156 |
| 012599 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:09pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592821.9 | 509993.0 | 14540 | 1.64041666667 | 12599 |
| 012810 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:10pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592823.9 | 509993.6 | 14542 | 1.64041666667 | 12810 |
| 013402 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:11pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592826.2 | 509994.0 | 14544 | 1.64041666667 | 13402 |
| 013100 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:12pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592826.2 | 509995.4 | 14546 | 1.64041666667 | 13100 |
| 013355 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592825.5 | 509998.2 | 14548 | 1.64041666667 | 13355 |
| 014618 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592824.6 | 510000.6 | 14550 | 1.64041666667 | 14618 |
| 012744 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592822.6 | 510003.0 | 14552 | 1.64041666667 | 12744 |
| 014196 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592821.4 | 510005.5 | 14554 | 1.64041666667 | 14196 |
| 013119 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:17pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592819.4 | 510007.8 | 14556 | 1.64041666667 | 13119 |
| 014469 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592818.3 | 510009.9 | 14558 | 1.64041666667 | 14469 |
| 013727 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592817.1 | 510012.6 | 14560 | 1.64041666667 | 13727 |
| 014021 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592816.1 | 510014.3 | 14562 | 1.64041666667 | 14021 |
| 014185 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592814.8 | 510016.6 | 14564 | 1.64041666667 | 14185 |
| 013206 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592812.8 | 510018.3 | 14566 | 1.64041666667 | 13206 |
| 013291 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592811.5 | 510020.6 | 14568 | 1.64041666667 | 13291 |
| 012682 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592810.2 | 510022.3 | 14570 | 1.64041666667 | 12682 |
| 012260 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:25pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592809.6 | 510025.2 | 14572 | 1.64041666667 | 12260 |
| 013505 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592808.3 | 510026.8 | 14574 | 1.64041666667 | 13505 |
| 014176 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592806.6 | 510029.3 | 14576 | 1.64041666667 | 14176 |
| 013444 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592805.2 | 510031.0 | 14578 | 1.64041666667 | 13444 |
| 012271 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592802.9 | 510033.1 | 14580 | 1.64041666667 | 12271 |
| 012937 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592801.9 | 510034.9 | 14582 | 1.64041666667 | 12937 |
| 013104 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592799.7 | 510036.8 | 14584 | 1.64041666667 | 13104 |
| 013386 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592798.9 | 510038.8 | 14586 | 1.64041666667 | 13386 |
| 013546 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:33pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592797.8 | 510040.9 | 14588 | 1.64041666667 | 13546 |
| 012956 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:34pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592797.5 | 510041.4 | 14590 | 1.64041666667 | 12956 |
| 015719 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:35pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592797.5 | 510041.4 | 14592 | 1.64041666667 | 15719 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014910 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:36pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592797.6 | 510041.3 | 14594 | 1.64041666667 | 14910 |
| 014797 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592797.6 | 510041.3 | 14596 | 1.64041666667 | 14797 |
| 012969 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592797.8 | 510041.8 | 14598 | 1.64041666667 | 12969 |
| 012062 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:39pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592796.6 | 510042.5 | 14600 | 1.64041666667 | 12062 |
| 011655 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:40pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592795.3 | 510044.5 | 14602 | 1.64041666667 | 11655 |
| 013443 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592793.4 | 510046.4 | 14604 | 1.64041666667 | 13443 |
| 013201 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592791.2 | 510048.5 | 14606 | 1.64041666667 | 13201 |
| 014430 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592789.4 | 510051.7 | 14608 | 1.64041666667 | 14430 |
| 014377 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592787.5 | 510053.7 | 14610 | 1.64041666667 | 14377 |
| 013344 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592786.0 | 510056.5 | 14612 | 1.64041666667 | 13344 |
| 014586 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592784.4 | 510058.5 | 14614 | 1.64041666667 | 14586 |
| 014746 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592782.7 | 510060.0 | 14616 | 1.64041666667 | 14746 |
| 015626 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592782.3 | 510060.2 | 14618 | 1.64041666667 | 15626 |
| 014766 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592782.4 | 510060.2 | 14620 | 1.64041666667 | 14766 |
| 014221 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592782.6 | 510060.4 | 14622 | 1.64041666667 | 14221 |
| 014745 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592782.4 | 510060.4 | 14624 | 1.64041666667 | 14745 |
| 015626 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592781.9 | 510060.2 | 14626 | 1.64041666667 | 15626 |
| 015066 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592781.2 | 510062.3 | 14628 | 1.64041666667 | 15066 |
| 016426 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592779.8 | 510064.0 | 14630 | 1.64041666667 | 16426 |
| 015146 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592778.1 | 510067.0 | 14632 | 1.64041666667 | 15146 |
| 015156 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592777.0 | 510069.5 | 14634 | 1.64041666667 | 15156 |
| 014919 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592775.1 | 510071.8 | 14636 | 1.64041666667 | 14919 |
| 013959 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592774.1 | 510073.9 | 14638 | 1.64041666667 | 13959 |
| 013420 | 0 | GeoXH 6000 | 08/18/2015 | 12:07:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592772.3 | 510076.2 | 14640 | 1.64041666667 | 13420 |
| 013105 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:00pm | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592771.8 | 510077.8 | 14642 | 1.64041666667 | 13105 |
| 013566 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:01pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592770.0 | 510080.4 | 14644 | 1.64041666667 | 13566 |
| 015271 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592768.2 | 510082.1 | 14646 | 1.64041666667 | 15271 |
| 017107 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592767.1 | 510084.6 | 14648 | 1.64041666667 | 17107 |
| 015527 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592765.2 | 510085.8 | 14650 | 1.64041666667 | 15527 |
| 014021 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592764.0 | 510088.1 | 14652 | 1.64041666667 | 14021 |
| 014815 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592762.2 | 510090.0 | 14654 | 1.64041666667 | 14815 |
| 015644 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592760.3 | 510092.5 | 14656 | 1.64041666667 | 15644 |
| 013402 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592759.3 | 510094.6 | 14658 | 1.64041666667 | 13402 |
| 014110 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592757.3 | 510096.5 | 14660 | 1.64041666667 | 14110 |
| 013367 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592756.3 | 510098.4 | 14662 | 1.64041666667 | 13367 |
| 012371 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592754.3 | 510099.9 | 14664 | 1.64041666667 | 12371 |
| 012453 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592754.2 | 510100.4 | 14666 | 1.64041666667 | 12453 |
| 012083 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592754.4 | 510100.3 | 14668 | 1.64041666667 | 12083 |
| 013820 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592753.8 | 510100.7 | 14670 | 1.64041666667 | 13820 |
| 014555 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:15pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592752.9 | 510102.5 | 14672 | 1.64041666667 | 14555 |
| 013448 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592752.9 | 510102.9 | 14674 | 1.64041666667 | 13448 |
| 013022 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:17pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592752.8 | 510102.0 | 14676 | 1.64041666667 | 13022 |
| 012855 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:18pm | Sensor | 1797-S0023-G-TJV.cor | 6800.8 | 1592750.7 | 510101.4 | 14678 | 1.64041666667 | 12855 |
| 013023 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:19pm | Sensor | 1797-S0023-G-TJV.cor | 6800.6 | 1592749.0 | 510100.7 | 14680 | 1.64041666667 | 13023 |
| 013486 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:20pm | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592748.1 | 510101.0 | 14682 | 1.64041666667 | 13486 |
| 014141 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592746.9 | 510101.0 | 14684 | 1.64041666667 | 14141 |
| 013285 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592746.0 | 510099.2 | 14686 | 1.64041666667 | 13285 |
| 012921 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:23pm | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592743.9 | 510098.1 | 14688 | 1.64041666667 | 12921 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013640 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592744.0 | 510098.7 | 14690 | 1.64041666667 | 13640 |
| 012050 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592744.7 | 510100.3 | 14692 | 1.64041666667 | 12050 |
| 012072 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592744.9 | 510099.4 | 14694 | 1.64041666667 | 12072 |
| 012588 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592745.6 | 510098.1 | 14696 | 1.64041666667 | 12588 |
| 012957 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592745.6 | 510099.4 | 14698 | 1.64041666667 | 12957 |
| 012539 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592746.7 | 510100.3 | 14700 | 1.64041666667 | 12539 |
| 013365 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592748.1 | 510100.9 | 14702 | 1.64041666667 | 13365 |
| 012761 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592748.7 | 510100.3 | 14704 | 1.64041666667 | 12761 |
| 015130 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592749.4 | 510099.2 | 14706 | 1.64041666667 | 15130 |
| 013742 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592750.5 | 510097.6 | 14708 | 1.64041666667 | 13742 |
| 012075 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592752.0 | 510096.1 | 14710 | 1.64041666667 | 12075 |
| 011748 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592752.9 | 510093.9 | 14712 | 1.64041666667 | 11748 |
| 014187 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592754.3 | 510092.7 | 14714 | 1.64041666667 | 14187 |
| 014437 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592755.2 | 510090.7 | 14716 | 1.64041666667 | 14437 |
| 013119 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592756.5 | 510089.1 | 14718 | 1.64041666667 | 13119 |
| 013959 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592757.7 | 510086.7 | 14720 | 1.64041666667 | 13959 |
| 015490 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:40pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592758.8 | 510084.7 | 14722 | 1.64041666667 | 15490 |
| 013982 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592760.2 | 510082.2 | 14724 | 1.64041666667 | 13982 |
| 014805 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592760.9 | 510079.6 | 14726 | 1.64041666667 | 14805 |
| 019541 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592762.6 | 510077.3 | 14728 | 1.64041666667 | 19541 |
| 018865 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592762.7 | 510076.0 | 14730 | 1.64041666667 | 18865 |
| 021276 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592763.1 | 510075.5 | 14732 | 1.64041666667 | 21276 |
| 020289 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592762.0 | 510075.0 | 14734 | 1.64041666667 | 20289 |
| 018662 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592761.5 | 510073.8 | 14736 | 1.64041666667 | 18662 |
| 018855 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592760.9 | 510072.4 | 14738 | 1.64041666667 | 18855 |
| 017973 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592759.2 | 510070.1 | 14740 | 1.64041666667 | 17973 |
| 017933 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592758.0 | 510068.6 | 14742 | 1.64041666667 | 17933 |
| 017233 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592756.2 | 510067.1 | 14744 | 1.64041666667 | 17233 |
| 014748 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592754.7 | 510066.6 | 14746 | 1.64041666667 | 14748 |
| 016827 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592754.5 | 510068.2 | 14748 | 1.64041666667 | 16827 |
| 018066 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592755.0 | 510069.8 | 14750 | 1.64041666667 | 18066 |
| 016456 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592756.9 | 510072.0 | 14752 | 1.64041666667 | 16456 |
| 017494 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592758.5 | 510073.9 | 14754 | 1.64041666667 | 17494 |
| 020963 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592760.2 | 510075.7 | 14756 | 1.64041666667 | 20963 |
| 021531 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592761.6 | 510076.1 | 14758 | 1.64041666667 | 21531 |
| 018222 | 0 | GeoXH 6000 | 08/18/2015 | 12:08:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592761.0 | 510077.6 | 14760 | 1.64041666667 | 18222 |
| 019975 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592761.0 | 510079.3 | 14762 | 1.64041666667 | 19975 |
| 016274 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592762.0 | 510082.1 | 14764 | 1.64041666667 | 16274 |
| 015288 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592764.1 | 510082.0 | 14766 | 1.64041666667 | 15288 |
| 015912 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592767.7 | 510081.4 | 14768 | 1.64041666667 | 15912 |
| 014076 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592766.1 | 510080.5 | 14770 | 1.64041666667 | 14076 |
| 016489 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592764.8 | 510078.4 | 14772 | 1.64041666667 | 16489 |
| 016212 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592764.0 | 510078.4 | 14774 | 1.64041666667 | 16212 |
| 017223 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592762.9 | 510077.3 | 14776 | 1.64041666667 | 17223 |
| 018075 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592761.0 | 510077.3 | 14778 | 1.64041666667 | 18075 |
| 017028 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592760.7 | 510077.9 | 14780 | 1.64041666667 | 17028 |
| 017247 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592760.7 | 510078.1 | 14782 | 1.64041666667 | 17247 |
| 018982 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592760.7 | 510077.9 | 14784 | 1.64041666667 | 18982 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017705 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592760.5 | 510077.2 | 14786 | 1.64041666667 | 17705 |
| 020176 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592760.9 | 510076.4 | 14788 | 1.64041666667 | 20176 |
| 020104 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:14pm | Sensor | 1797-S0023-G-TJV.cor | 6800.8 | 1592761.1 | 510075.8 | 14790 | 1.64041666667 | 20104 |
| 021286 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:15pm | Sensor | 1797-S0023-G-TJV.cor | 6800.3 | 1592761.2 | 510075.5 | 14792 | 1.64041666667 | 21286 |
| 020681 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:16pm | Sensor | 1797-S0023-G-TJV.cor | 6800.4 | 1592761.1 | 510075.3 | 14794 | 1.64041666667 | 20681 |
| 021730 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:17pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592761.0 | 510075.5 | 14796 | 1.64041666667 | 21730 |
| 019862 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592760.8 | 510076.3 | 14798 | 1.64041666667 | 19862 |
| 018705 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592761.8 | 510077.0 | 14800 | 1.64041666667 | 18705 |
| 016706 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592761.6 | 510076.2 | 14802 | 1.64041666667 | 16706 |
| 017856 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592762.1 | 510074.6 | 14804 | 1.64041666667 | 17856 |
| 018534 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592763.0 | 510073.1 | 14806 | 1.64041666667 | 18534 |
| 018733 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592764.6 | 510071.2 | 14808 | 1.64041666667 | 18733 |
| 016593 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592765.4 | 510069.5 | 14810 | 1.64041666667 | 16593 |
| 017828 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592767.1 | 510068.2 | 14812 | 1.64041666667 | 17828 |
| 015527 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592768.5 | 510066.7 | 14814 | 1.64041666667 | 15527 |
| 014651 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592771.0 | 510064.8 | 14816 | 1.64041666667 | 14651 |
| 012303 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592772.7 | 510062.5 | 14818 | 1.64041666667 | 12303 |
| 014475 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592774.4 | 510060.1 | 14820 | 1.64041666667 | 14475 |
| 013998 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592776.0 | 510057.8 | 14822 | 1.64041666667 | 13998 |
| 013969 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592777.0 | 510055.0 | 14824 | 1.64041666667 | 13969 |
| 015192 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592778.3 | 510053.0 | 14826 | 1.64041666667 | 15192 |
| 013518 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592779.4 | 510050.0 | 14828 | 1.64041666667 | 13518 |
| 014269 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592780.7 | 510048.0 | 14830 | 1.64041666667 | 14269 |
| 013737 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592782.7 | 510045.2 | 14832 | 1.64041666667 | 13737 |
| 013708 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592784.1 | 510042.4 | 14834 | 1.64041666667 | 13708 |
| 013128 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592786.1 | 510040.2 | 14836 | 1.64041666667 | 13128 |
| 012882 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592787.2 | 510038.1 | 14838 | 1.64041666667 | 12882 |
| 014170 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592789.3 | 510036.1 | 14840 | 1.64041666667 | 14170 |
| 015212 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:40pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592790.5 | 510033.9 | 14842 | 1.64041666667 | 15212 |
| 012653 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:41pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592791.5 | 510032.2 | 14844 | 1.64041666667 | 12653 |
| 015283 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:42pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592792.1 | 510032.0 | 14846 | 1.64041666667 | 15283 |
| 015041 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592792.8 | 510029.7 | 14848 | 1.64041666667 | 15041 |
| 012220 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592794.1 | 510027.3 | 14850 | 1.64041666667 | 12220 |
| 012475 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592796.5 | 510024.7 | 14852 | 1.64041666667 | 12475 |
| 012088 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:46pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592797.7 | 510022.7 | 14854 | 1.64041666667 | 12088 |
| 012862 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:47pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592799.6 | 510020.5 | 14856 | 1.64041666667 | 12862 |
| 013655 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592801.1 | 510018.1 | 14858 | 1.64041666667 | 13655 |
| 012953 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592803.0 | 510015.3 | 14860 | 1.64041666667 | 12953 |
| 012748 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592805.3 | 510013.2 | 14862 | 1.64041666667 | 12748 |
| 013507 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592806.5 | 510010.8 | 14864 | 1.64041666667 | 13507 |
| 014176 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592808.1 | 510009.0 | 14866 | 1.64041666667 | 14176 |
| 013294 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592809.7 | 510006.5 | 14868 | 1.64041666667 | 13294 |
| 015233 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592811.5 | 510004.6 | 14870 | 1.64041666667 | 15233 |
| 015088 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592813.2 | 510002.0 | 14872 | 1.64041666667 | 15088 |
| 014302 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:56pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592814.3 | 509999.6 | 14874 | 1.64041666667 | 14302 |
| 014645 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:57pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592815.6 | 509997.2 | 14876 | 1.64041666667 | 14645 |
| 012871 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:58pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592816.6 | 509994.7 | 14878 | 1.64041666667 | 12871 |
| 014407 | 0 | GeoXH 6000 | 08/18/2015 | 12:09:59pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592818.5 | 509992.9 | 14880 | 1.64041666667 | 14407 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013172 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:00pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592818.7 | 509992.5 | 14882 | 1.64041666667 | 13172 |
| 013943 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:01pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592818.8 | 509992.3 | 14884 | 1.64041666667 | 13943 |
| 013145 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592818.8 | 509992.1 | 14886 | 1.64041666667 | 13145 |
| 014056 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:03pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592818.6 | 509992.0 | 14888 | 1.64041666667 | 14056 |
| 015004 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:04pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592818.6 | 509992.1 | 14890 | 1.64041666667 | 15004 |
| 014971 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:05pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592816.1 | 509991.9 | 14892 | 1.64041666667 | 14971 |
| 016042 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:06pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592813.9 | 509991.5 | 14894 | 1.64041666667 | 16042 |
| 013910 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:07pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592811.9 | 509992.2 | 14896 | 1.64041666667 | 13910 |
| 012747 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:08pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592811.5 | 509992.5 | 14898 | 1.64041666667 | 12747 |
| 014257 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:09pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592811.8 | 509992.3 | 14900 | 1.64041666667 | 14257 |
| 013194 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:10pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592810.2 | 509991.8 | 14902 | 1.64041666667 | 13194 |
| 013618 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:11pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592806.5 | 509990.9 | 14904 | 1.64041666667 | 13618 |
| 014144 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:12pm | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592805.0 | 509990.9 | 14906 | 1.64041666667 | 14144 |
| 012506 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:13pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592804.6 | 509990.9 | 14908 | 1.64041666667 | 12506 |
| 013116 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:14pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592803.8 | 509991.0 | 14910 | 1.64041666667 | 13116 |
| 013269 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592803.0 | 509991.4 | 14912 | 1.64041666667 | 13269 |
| 012707 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592803.8 | 509990.6 | 14914 | 1.64041666667 | 12707 |
| 013466 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:17pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592804.7 | 509989.6 | 14916 | 1.64041666667 | 13466 |
| 014616 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592806.0 | 509989.6 | 14918 | 1.64041666667 | 14616 |
| 013554 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592808.1 | 509990.4 | 14920 | 1.64041666667 | 13554 |
| 013138 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592810.6 | 509990.8 | 14922 | 1.64041666667 | 13138 |
| 014024 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592812.6 | 509992.0 | 14924 | 1.64041666667 | 14024 |
| 013556 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592812.0 | 509994.1 | 14926 | 1.64041666667 | 13556 |
| 014609 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592811.2 | 509996.5 | 14928 | 1.64041666667 | 14609 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592809.5 | 509998.4 | 14930 | 1.64041666667 | 14482 |
| 014960 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592808.0 | 510001.0 | 14932 | 1.64041666667 | 14960 |
| 015140 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592806.4 | 510003.0 | 14934 | 1.64041666667 | 15140 |
| 015155 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592804.6 | 510005.2 | 14936 | 1.64041666667 | 15155 |
| 016568 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592803.7 | 510007.2 | 14938 | 1.64041666667 | 16568 |
| 016052 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592803.3 | 510007.7 | 14940 | 1.64041666667 | 16052 |
| 014303 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592802.9 | 510008.2 | 14942 | 1.64041666667 | 14303 |
| 014735 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592802.2 | 510009.8 | 14944 | 1.64041666667 | 14735 |
| 013014 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592802.1 | 510010.3 | 14946 | 1.64041666667 | 13014 |
| 013573 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592801.8 | 510010.7 | 14948 | 1.64041666667 | 13573 |
| 015573 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592801.4 | 510012.7 | 14950 | 1.64041666667 | 15573 |
| 014183 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592800.1 | 510015.3 | 14952 | 1.64041666667 | 14183 |
| 012815 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592798.1 | 510017.5 | 14954 | 1.64041666667 | 12815 |
| 016434 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:37pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592796.6 | 510020.4 | 14956 | 1.64041666667 | 16434 |
| 012448 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592795.0 | 510022.3 | 14958 | 1.64041666667 | 12448 |
| 012712 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592793.2 | 510024.8 | 14960 | 1.64041666667 | 12712 |
| 013768 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:40pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592792.0 | 510027.0 | 14962 | 1.64041666667 | 13768 |
| 013702 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:41pm | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592790.9 | 510027.3 | 14964 | 1.64041666667 | 13702 |
| 014135 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:42pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592790.8 | 510027.2 | 14966 | 1.64041666667 | 14135 |
| 012563 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:43pm | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592790.6 | 510027.2 | 14968 | 1.64041666667 | 12563 |
| 014121 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:44pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592790.5 | 510028.1 | 14970 | 1.64041666667 | 14121 |
| 014780 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592789.1 | 510029.6 | 14972 | 1.64041666667 | 14780 |
| 012215 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592787.7 | 510031.6 | 14974 | 1.64041666667 | 12215 |
| 014843 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592786.0 | 510034.1 | 14976 | 1.64041666667 | 14843 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013221 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592783.9 | 510036.5 | 14978 | 1.64041666667 | 13221 |
| 014225 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592782.4 | 510039.1 | 14980 | 1.64041666667 | 14225 |
| 013636 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592780.6 | 510041.2 | 14982 | 1.64041666667 | 13636 |
| 012709 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592778.6 | 510044.0 | 14984 | 1.64041666667 | 12709 |
| 012477 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592777.0 | 510046.7 | 14986 | 1.64041666667 | 12477 |
| 012869 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592774.8 | 510049.0 | 14988 | 1.64041666667 | 12869 |
| 014077 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592773.3 | 510051.5 | 14990 | 1.64041666667 | 14077 |
| 016119 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592771.3 | 510053.4 | 14992 | 1.64041666667 | 16119 |
| 017199 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592769.7 | 510055.9 | 14994 | 1.64041666667 | 17199 |
| 015760 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592767.6 | 510058.0 | 14996 | 1.64041666667 | 15760 |
| 015700 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592765.8 | 510060.4 | 14998 | 1.64041666667 | 15700 |
| 015415 | 0 | GeoXH 6000 | 08/18/2015 | 12:10:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592764.0 | 510063.5 | 15000 | 1.64041666667 | 15415 |
| 016453 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592762.0 | 510065.5 | 15002 | 1.64041666667 | 16453 |
| 016203 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592760.7 | 510067.7 | 15004 | 1.64041666667 | 16203 |
| 019860 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592759.0 | 510069.1 | 15006 | 1.64041666667 | 19860 |
| 016995 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592757.5 | 510071.4 | 15008 | 1.64041666667 | 16995 |
| 017118 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.0 | 510073.6 | 15010 | 1.64041666667 | 17118 |
| 015769 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592754.4 | 510076.2 | 15012 | 1.64041666667 | 15769 |
| 016002 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592753.3 | 510078.5 | 15014 | 1.64041666667 | 16002 |
| 014500 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592751.2 | 510080.7 | 15016 | 1.64041666667 | 14500 |
| 014455 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592749.9 | 510082.6 | 15018 | 1.64041666667 | 14455 |
| 012823 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592748.2 | 510084.7 | 15020 | 1.64041666667 | 12823 |
| 014726 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592747.5 | 510086.1 | 15022 | 1.64041666667 | 14726 |
| 015021 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:11pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592746.0 | 510088.1 | 15024 | 1.64041666667 | 15021 |
| 015035 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:12pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592744.5 | 510089.8 | 15026 | 1.64041666667 | 15035 |
| 013688 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:13pm | Sensor | 1797-S0023-G-TJV.cor | 6800.5 | 1592742.6 | 510093.3 | 15028 | 1.64041666667 | 13688 |
| 014852 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:14pm | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592741.5 | 510095.5 | 15030 | 1.64041666667 | 14852 |
| 013193 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592741.7 | 510096.9 | 15032 | 1.64041666667 | 13193 |
| 011968 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592741.5 | 510097.5 | 15034 | 1.64041666667 | 11968 |
| 011662 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:17pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592741.9 | 510099.1 | 15036 | 1.64041666667 | 11662 |
| 013265 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592741.3 | 510099.2 | 15038 | 1.64041666667 | 13265 |
| 012826 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592742.1 | 510098.9 | 15040 | 1.64041666667 | 12826 |
| 012596 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592741.7 | 510097.6 | 15042 | 1.64041666667 | 12596 |
| 013019 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592740.3 | 510095.4 | 15044 | 1.64041666667 | 13019 |
| 013815 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592738.7 | 510094.5 | 15046 | 1.64041666667 | 13815 |
| 014583 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592737.6 | 510094.3 | 15048 | 1.64041666667 | 14583 |
| 013665 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592736.8 | 510092.9 | 15050 | 1.64041666667 | 13665 |
| 015476 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592733.9 | 510091.3 | 15052 | 1.64041666667 | 15476 |
| 016049 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592731.5 | 510090.7 | 15054 | 1.64041666667 | 16049 |
| 014272 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:27pm | Sensor | 1797-S0023-G-TJV.cor | 6800.4 | 1592729.9 | 510090.6 | 15056 | 1.64041666667 | 14272 |
| 012688 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592730.8 | 510092.2 | 15058 | 1.64041666667 | 12688 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592730.7 | 510093.5 | 15060 | 1.64041666667 | 13972 |
| 014203 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592731.7 | 510094.1 | 15062 | 1.64041666667 | 14203 |
| 012880 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592733.8 | 510093.4 | 15064 | 1.64041666667 | 12880 |
| 015040 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592736.0 | 510092.9 | 15066 | 1.64041666667 | 15040 |
| 014620 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592737.8 | 510091.0 | 15068 | 1.64041666667 | 14620 |
| 014575 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592739.3 | 510089.4 | 15070 | 1.64041666667 | 14575 |
| 013813 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:35pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592741.5 | 510087.6 | 15072 | 1.64041666667 | 13813 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014583 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:36pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592742.5 | 510085.3 | 15074 | 1.64041666667 | 14583 |
| 014655 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:37pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592743.8 | 510083.6 | 15076 | 1.64041666667 | 14655 |
| 013863 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592744.3 | 510081.4 | 15078 | 1.64041666667 | 13863 |
| 013876 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592746.0 | 510079.8 | 15080 | 1.64041666667 | 13876 |
| 014449 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:40pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592746.9 | 510078.2 | 15082 | 1.64041666667 | 14449 |
| 015102 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592748.7 | 510076.5 | 15084 | 1.64041666667 | 15102 |
| 014845 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592749.5 | 510074.7 | 15086 | 1.64041666667 | 14845 |
| 015291 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592750.6 | 510072.8 | 15088 | 1.64041666667 | 15291 |
| 015282 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:44pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592751.9 | 510070.7 | 15090 | 1.64041666667 | 15282 |
| 016300 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:45pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592753.0 | 510067.8 | 15092 | 1.64041666667 | 16300 |
| 014425 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592754.1 | 510065.8 | 15094 | 1.64041666667 | 14425 |
| 015876 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592754.7 | 510063.4 | 15096 | 1.64041666667 | 15876 |
| 016299 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592755.6 | 510061.5 | 15098 | 1.64041666667 | 16299 |
| 015564 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592755.8 | 510059.4 | 15100 | 1.64041666667 | 15564 |
| 015171 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592756.3 | 510056.9 | 15102 | 1.64041666667 | 15171 |
| 014742 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592758.1 | 510055.0 | 15104 | 1.64041666667 | 14742 |
| 017485 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592759.2 | 510053.4 | 15106 | 1.64041666667 | 17485 |
| 015651 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592761.1 | 510051.4 | 15108 | 1.64041666667 | 15651 |
| 015822 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592762.0 | 510049.2 | 15110 | 1.64041666667 | 15822 |
| 017425 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592763.5 | 510046.9 | 15112 | 1.64041666667 | 17425 |
| 016986 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592764.2 | 510044.9 | 15114 | 1.64041666667 | 16986 |
| 015646 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592765.6 | 510042.7 | 15116 | 1.64041666667 | 15646 |
| 013871 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592766.6 | 510040.2 | 15118 | 1.64041666667 | 13871 |
| 016578 | 0 | GeoXH 6000 | 08/18/2015 | 12:11:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592768.4 | 510037.4 | 15120 | 1.64041666667 | 16578 |
| 014824 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592769.9 | 510035.1 | 15122 | 1.64041666667 | 14824 |
| 013966 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592771.8 | 510032.1 | 15124 | 1.64041666667 | 13966 |
| 014411 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592773.8 | 510030.0 | 15126 | 1.64041666667 | 14411 |
| 014553 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592775.4 | 510027.4 | 15128 | 1.64041666667 | 14553 |
| 015188 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592777.1 | 510025.5 | 15130 | 1.64041666667 | 15188 |
| 013937 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592779.2 | 510023.0 | 15132 | 1.64041666667 | 13937 |
| 014374 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592780.9 | 510020.5 | 15134 | 1.64041666667 | 14374 |
| 012563 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592783.5 | 510018.2 | 15136 | 1.64041666667 | 12563 |
| 013491 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592784.9 | 510016.3 | 15138 | 1.64041666667 | 13491 |
| 013602 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592787.1 | 510013.6 | 15140 | 1.64041666667 | 13602 |
| 013300 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592788.1 | 510011.6 | 15142 | 1.64041666667 | 13300 |
| 014695 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592789.5 | 510008.7 | 15144 | 1.64041666667 | 14695 |
| 013273 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592791.4 | 510006.5 | 15146 | 1.64041666667 | 13273 |
| 014418 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592793.2 | 510004.1 | 15148 | 1.64041666667 | 14418 |
| 015094 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592795.1 | 510002.5 | 15150 | 1.64041666667 | 15094 |
| 014243 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592797.3 | 510000.1 | 15152 | 1.64041666667 | 14243 |
| 013221 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592799.1 | 509997.8 | 15154 | 1.64041666667 | 13221 |
| 013655 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:17pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592801.2 | 509995.7 | 15156 | 1.64041666667 | 13655 |
| 013163 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592802.1 | 509993.4 | 15158 | 1.64041666667 | 13163 |
| 015051 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592803.2 | 509990.8 | 15160 | 1.64041666667 | 15051 |
| 014592 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592803.5 | 509990.6 | 15162 | 1.64041666667 | 14592 |
| 013998 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592803.3 | 509991.7 | 15164 | 1.64041666667 | 13998 |
| 014149 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592802.5 | 509991.4 | 15166 | 1.64041666667 | 14149 |
| 012507 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592799.8 | 509991.0 | 15168 | 1.64041666667 | 12507 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014977 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592797.3 | 509991.1 | 15170 | 1.64041666667 | 14977 |
| 013314 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592795.6 | 509991.4 | 15172 | 1.64041666667 | 13314 |
| 013948 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592794.6 | 509991.2 | 15174 | 1.64041666667 | 13948 |
| 015367 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:27pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592791.5 | 509991.2 | 15176 | 1.64041666667 | 15367 |
| 013801 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592788.2 | 509991.7 | 15178 | 1.64041666667 | 13801 |
| 014040 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592787.0 | 509991.8 | 15180 | 1.64041666667 | 14040 |
| 014460 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592788.4 | 509991.2 | 15182 | 1.64041666667 | 14460 |
| 013995 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592788.6 | 509991.4 | 15184 | 1.64041666667 | 13995 |
| 011958 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592789.6 | 509991.4 | 15186 | 1.64041666667 | 11958 |
| 013249 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592791.5 | 509991.3 | 15188 | 1.64041666667 | 13249 |
| 012912 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592793.9 | 509990.9 | 15190 | 1.64041666667 | 12912 |
| 012858 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592796.1 | 509990.4 | 15192 | 1.64041666667 | 12858 |
| 013114 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592796.6 | 509989.6 | 15194 | 1.64041666667 | 13114 |
| 014078 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592796.7 | 509989.3 | 15196 | 1.64041666667 | 14078 |
| 012339 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592796.7 | 509989.3 | 15198 | 1.64041666667 | 12339 |
| 013885 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592796.6 | 509989.3 | 15200 | 1.64041666667 | 13885 |
| 013602 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:40pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592796.7 | 509990.1 | 15202 | 1.64041666667 | 13602 |
| 013790 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592795.7 | 509991.9 | 15204 | 1.64041666667 | 13790 |
| 014127 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592794.6 | 509994.0 | 15206 | 1.64041666667 | 14127 |
| 013162 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592793.0 | 509997.1 | 15208 | 1.64041666667 | 13162 |
| 013220 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592791.3 | 510000.1 | 15210 | 1.64041666667 | 13220 |
| 012755 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592790.2 | 510002.9 | 15212 | 1.64041666667 | 12755 |
| 013688 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592788.5 | 510005.3 | 15214 | 1.64041666667 | 13688 |
| 012512 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592786.2 | 510008.0 | 15216 | 1.64041666667 | 12512 |
| 013268 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592784.7 | 510010.3 | 15218 | 1.64041666667 | 13268 |
| 011627 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592782.6 | 510013.0 | 15220 | 1.64041666667 | 11627 |
| 014006 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592781.2 | 510015.2 | 15222 | 1.64041666667 | 14006 |
| 013191 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592779.1 | 510018.0 | 15224 | 1.64041666667 | 13191 |
| 012508 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592776.8 | 510020.2 | 15226 | 1.64041666667 | 12508 |
| 013297 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592774.9 | 510022.7 | 15228 | 1.64041666667 | 13297 |
| 012564 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592773.2 | 510024.7 | 15230 | 1.64041666667 | 12564 |
| 013311 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592771.5 | 510027.6 | 15232 | 1.64041666667 | 13311 |
| 014277 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592770.0 | 510030.2 | 15234 | 1.64041666667 | 14277 |
| 014849 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592767.9 | 510032.8 | 15236 | 1.64041666667 | 14849 |
| 014572 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592766.4 | 510035.1 | 15238 | 1.64041666667 | 14572 |
| 016243 | 0 | GeoXH 6000 | 08/18/2015 | 12:12:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592764.4 | 510038.0 | 15240 | 1.64041666667 | 16243 |
| 015040 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592763.4 | 510039.2 | 15242 | 1.64041666667 | 15040 |
| 014950 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592763.0 | 510039.5 | 15244 | 1.64041666667 | 14950 |
| 014417 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592762.8 | 510039.6 | 15246 | 1.64041666667 | 14417 |
| 013534 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592762.9 | 510039.5 | 15248 | 1.64041666667 | 13534 |
| 014273 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592762.8 | 510039.5 | 15250 | 1.64041666667 | 14273 |
| 015568 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592762.6 | 510039.5 | 15252 | 1.64041666667 | 15568 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592761.7 | 510040.8 | 15254 | 1.64041666667 | 14092 |
| 015103 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592759.7 | 510043.1 | 15256 | 1.64041666667 | 15103 |
| 016165 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592757.4 | 510045.3 | 15258 | 1.64041666667 | 16165 |
| 015651 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592755.3 | 510048.1 | 15260 | 1.64041666667 | 15651 |
| 014742 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592753.5 | 510050.2 | 15262 | 1.64041666667 | 14742 |
| 016375 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592752.2 | 510053.0 | 15264 | 1.64041666667 | 16375 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015194 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592750.9 | 510055.2 | 15266 | 1.64041666667 | 15194 |
| 013638 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592748.7 | 510057.9 | 15268 | 1.64041666667 | 13638 |
| 014689 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592747.0 | 510060.3 | 15270 | 1.64041666667 | 14689 |
| 013782 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592745.2 | 510062.4 | 15272 | 1.64041666667 | 13782 |
| 015025 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592744.3 | 510064.5 | 15274 | 1.64041666667 | 15025 |
| 014556 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:17pm | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592743.6 | 510067.2 | 15276 | 1.64041666667 | 14556 |
| 015579 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592742.0 | 510068.7 | 15278 | 1.64041666667 | 15579 |
| 014574 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:19pm | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592741.0 | 510071.0 | 15280 | 1.64041666667 | 14574 |
| 014773 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:20pm | Sensor | 1797-S0023-G-TJV.cor | 6800.8 | 1592739.6 | 510073.1 | 15282 | 1.64041666667 | 14773 |
| 015243 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592737.7 | 510076.3 | 15284 | 1.64041666667 | 15243 |
| 014550 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592736.3 | 510078.6 | 15286 | 1.64041666667 | 14550 |
| 015007 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592735.3 | 510080.8 | 15288 | 1.64041666667 | 15007 |
| 014342 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592734.9 | 510081.8 | 15290 | 1.64041666667 | 14342 |
| 015465 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592734.7 | 510082.1 | 15292 | 1.64041666667 | 15465 |
| 014846 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592734.6 | 510082.1 | 15294 | 1.64041666667 | 14846 |
| 015771 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592734.5 | 510082.1 | 15296 | 1.64041666667 | 15771 |
| 014713 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592734.4 | 510082.0 | 15298 | 1.64041666667 | 14713 |
| 015438 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592734.1 | 510082.3 | 15300 | 1.64041666667 | 15438 |
| 016219 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592733.9 | 510083.9 | 15302 | 1.64041666667 | 16219 |
| 014314 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592732.5 | 510085.6 | 15304 | 1.64041666667 | 14314 |
| 014318 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592730.7 | 510087.4 | 15306 | 1.64041666667 | 14318 |
| 013119 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592730.1 | 510089.4 | 15308 | 1.64041666667 | 13119 |
| 013030 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:34pm | Sensor | 1797-S0023-G-TJV.cor | 6800.8 | 1592729.8 | 510091.2 | 15310 | 1.64041666667 | 13030 |
| 013547 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592730.2 | 510091.3 | 15312 | 1.64041666667 | 13547 |
| 014096 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592730.5 | 510090.4 | 15314 | 1.64041666667 | 14096 |
| 014384 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:37pm | Sensor | 1797-S0023-G-TJV.cor | 6803.2 | 1592730.7 | 510090.1 | 15316 | 1.64041666667 | 14384 |
| 012896 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:38pm | Sensor | 1797-S0023-G-TJV.cor | 6803.0 | 1592727.4 | 510088.9 | 15318 | 1.64041666667 | 12896 |
| 013844 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592724.8 | 510088.6 | 15320 | 1.64041666667 | 13844 |
| 013541 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:40pm | Sensor | 1797-S0023-G-TJV.cor | 6803.3 | 1592726.2 | 510089.3 | 15322 | 1.64041666667 | 13541 |
| 013945 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:41pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592723.6 | 510087.7 | 15324 | 1.64041666667 | 13945 |
| 014286 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592720.3 | 510086.2 | 15326 | 1.64041666667 | 14286 |
| 014101 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:43pm | Sensor | 1797-S0023-G-TJV.cor | 6800.9 | 1592717.2 | 510085.3 | 15328 | 1.64041666667 | 14101 |
| 012885 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:44pm | Sensor | 1797-S0023-G-TJV.cor | 6800.7 | 1592715.9 | 510085.1 | 15330 | 1.64041666667 | 12885 |
| 012101 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592716.4 | 510085.7 | 15332 | 1.64041666667 | 12101 |
| 013135 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592717.3 | 510087.0 | 15334 | 1.64041666667 | 13135 |
| 014264 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592718.5 | 510086.9 | 15336 | 1.64041666667 | 14264 |
| 013526 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592720.1 | 510087.2 | 15338 | 1.64041666667 | 13526 |
| 012111 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592722.7 | 510088.1 | 15340 | 1.64041666667 | 12111 |
| 013497 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:50pm | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1592725.4 | 510087.8 | 15342 | 1.64041666667 | 13497 |
| 014174 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592726.8 | 510085.7 | 15344 | 1.64041666667 | 14174 |
| 014673 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592728.0 | 510083.0 | 15346 | 1.64041666667 | 14673 |
| 013328 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592729.0 | 510080.1 | 15348 | 1.64041666667 | 13328 |
| 013982 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592730.2 | 510077.6 | 15350 | 1.64041666667 | 13982 |
| 013395 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592731.1 | 510074.9 | 15352 | 1.64041666667 | 13395 |
| 015288 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592731.8 | 510072.4 | 15354 | 1.64041666667 | 15288 |
| 014202 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592733.3 | 510069.5 | 15356 | 1.64041666667 | 14202 |
| 014770 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592734.4 | 510066.7 | 15358 | 1.64041666667 | 14770 |
| 015602 | 0 | GeoXH 6000 | 08/18/2015 | 12:13:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592736.4 | 510064.3 | 15360 | 1.64041666667 | 15602 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015750 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592738.6 | 510062.2 | 15362 | 1.64041666667 | 15750 |
| 014047 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592740.6 | 510059.4 | 15364 | 1.64041666667 | 14047 |
| 015272 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592742.6 | 510057.4 | 15366 | 1.64041666667 | 15272 |
| 014288 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592744.7 | 510054.7 | 15368 | 1.64041666667 | 14288 |
| 015572 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592746.3 | 510052.5 | 15370 | 1.64041666667 | 15572 |
| 014213 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592748.7 | 510049.8 | 15372 | 1.64041666667 | 14213 |
| 014083 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592750.1 | 510047.4 | 15374 | 1.64041666667 | 14083 |
| 013961 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:07pm | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592752.8 | 510045.1 | 15376 | 1.64041666667 | 13961 |
| 014620 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592754.5 | 510041.9 | 15378 | 1.64041666667 | 14620 |
| 014155 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592755.8 | 510038.9 | 15380 | 1.64041666667 | 14155 |
| 013558 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592757.5 | 510037.0 | 15382 | 1.64041666667 | 13558 |
| 011459 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592759.4 | 510034.1 | 15384 | 1.64041666667 | 11459 |
| 012225 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592761.2 | 510031.5 | 15386 | 1.64041666667 | 12225 |
| 013706 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592763.5 | 510028.5 | 15388 | 1.64041666667 | 13706 |
| 014496 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592764.6 | 510025.9 | 15390 | 1.64041666667 | 14496 |
| 014004 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592766.2 | 510023.6 | 15392 | 1.64041666667 | 14004 |
| 013011 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592768.4 | 510020.9 | 15394 | 1.64041666667 | 13011 |
| 013332 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:17pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592770.4 | 510017.8 | 15396 | 1.64041666667 | 13332 |
| 012963 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592771.9 | 510015.6 | 15398 | 1.64041666667 | 12963 |
| 016890 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592773.7 | 510012.6 | 15400 | 1.64041666667 | 16890 |
| 013132 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592775.3 | 510010.4 | 15402 | 1.64041666667 | 13132 |
| 014353 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592777.9 | 510007.6 | 15404 | 1.64041666667 | 14353 |
| 012378 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592779.4 | 510005.2 | 15406 | 1.64041666667 | 12378 |
| 013474 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592780.8 | 510002.7 | 15408 | 1.64041666667 | 13474 |
| 013478 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592782.4 | 510000.1 | 15410 | 1.64041666667 | 13478 |
| 014949 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592784.3 | 509996.7 | 15412 | 1.64041666667 | 14949 |
| 014057 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592785.6 | 509994.8 | 15414 | 1.64041666667 | 14057 |
| 013234 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592787.1 | 509992.2 | 15416 | 1.64041666667 | 13234 |
| 014678 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592787.8 | 509991.6 | 15418 | 1.64041666667 | 14678 |
| 014469 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592787.4 | 509992.1 | 15420 | 1.64041666667 | 14469 |
| 014117 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592786.8 | 509991.5 | 15422 | 1.64041666667 | 14117 |
| 011569 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592786.3 | 509991.1 | 15424 | 1.64041666667 | 11569 |
| 013482 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592785.8 | 509991.2 | 15426 | 1.64041666667 | 13482 |
| 013330 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592783.7 | 509992.0 | 15428 | 1.64041666667 | 13330 |
| 013202 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592781.4 | 509994.0 | 15430 | 1.64041666667 | 13202 |
| 011820 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592779.3 | 509996.1 | 15432 | 1.64041666667 | 11820 |
| 013035 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592777.5 | 509998.1 | 15434 | 1.64041666667 | 13035 |
| 011838 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592775.3 | 510001.3 | 15436 | 1.64041666667 | 11838 |
| 012439 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592773.7 | 510003.6 | 15438 | 1.64041666667 | 12439 |
| 014600 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592772.4 | 510006.7 | 15440 | 1.64041666667 | 14600 |
| 013730 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:40pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592770.7 | 510009.8 | 15442 | 1.64041666667 | 13730 |
| 012702 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592768.4 | 510012.4 | 15444 | 1.64041666667 | 12702 |
| 012385 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592766.7 | 510014.9 | 15446 | 1.64041666667 | 12385 |
| 013086 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592764.6 | 510017.8 | 15448 | 1.64041666667 | 13086 |
| 014311 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592762.4 | 510020.2 | 15450 | 1.64041666667 | 14311 |
| 015277 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592760.5 | 510023.0 | 15452 | 1.64041666667 | 15277 |
| 016479 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592758.7 | 510025.3 | 15454 | 1.64041666667 | 16479 |
| 015130 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592755.9 | 510028.4 | 15456 | 1.64041666667 | 15130 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014045 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592754.3 | 510031.1 | 15458 | 1.64041666667 | 14045 |
| 014715 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592752.5 | 510034.1 | 15460 | 1.64041666667 | 14715 |
| 015468 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592750.7 | 510036.9 | 15462 | 1.64041666667 | 15468 |
| 016047 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592748.9 | 510039.7 | 15464 | 1.64041666667 | 16047 |
| 015112 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592746.7 | 510042.1 | 15466 | 1.64041666667 | 15112 |
| 014848 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592743.9 | 510045.2 | 15468 | 1.64041666667 | 14848 |
| 014272 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592742.6 | 510047.9 | 15470 | 1.64041666667 | 14272 |
| 012148 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592741.1 | 510051.2 | 15472 | 1.64041666667 | 12148 |
| 013627 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592739.3 | 510053.7 | 15474 | 1.64041666667 | 13627 |
| 015136 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592737.4 | 510056.7 | 15476 | 1.64041666667 | 15136 |
| 014974 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592735.4 | 510058.9 | 15478 | 1.64041666667 | 14974 |
| 016193 | 0 | GeoXH 6000 | 08/18/2015 | 12:14:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592732.9 | 510061.8 | 15480 | 1.64041666667 | 16193 |
| 017638 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592731.3 | 510065.0 | 15482 | 1.64041666667 | 17638 |
| 016889 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592729.6 | 510067.6 | 15484 | 1.64041666667 | 16889 |
| 016582 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592727.7 | 510070.2 | 15486 | 1.64041666667 | 16582 |
| 016205 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592725.7 | 510072.8 | 15488 | 1.64041666667 | 16205 |
| 014581 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592723.5 | 510074.9 | 15490 | 1.64041666667 | 14581 |
| 014505 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592721.5 | 510077.5 | 15492 | 1.64041666667 | 14505 |
| 012986 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592719.7 | 510080.3 | 15494 | 1.64041666667 | 12986 |
| 012336 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592717.6 | 510082.6 | 15496 | 1.64041666667 | 12336 |
| 012024 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592717.0 | 510084.0 | 15498 | 1.64041666667 | 12024 |
| 013206 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592716.2 | 510085.2 | 15500 | 1.64041666667 | 13206 |
| 012211 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592716.4 | 510084.8 | 15502 | 1.64041666667 | 12211 |
| 010882 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592716.3 | 510085.1 | 15504 | 1.64041666667 | 10882 |
| 011960 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592717.2 | 510085.5 | 15506 | 1.64041666667 | 11960 |
| 011930 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592719.4 | 510086.5 | 15508 | 1.64041666667 | 11930 |
| 012342 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592722.1 | 510087.4 | 15510 | 1.64041666667 | 12342 |
| 014305 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592725.2 | 510088.9 | 15512 | 1.64041666667 | 14305 |
| 013566 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592727.6 | 510090.5 | 15514 | 1.64041666667 | 13566 |
| 013231 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:17pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592730.1 | 510092.2 | 15516 | 1.64041666667 | 13231 |
| 015427 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592732.5 | 510094.2 | 15518 | 1.64041666667 | 15427 |
| 013487 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592735.5 | 510096.1 | 15520 | 1.64041666667 | 13487 |
| 014381 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592738.1 | 510097.0 | 15522 | 1.64041666667 | 14381 |
| 013255 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592740.4 | 510098.9 | 15524 | 1.64041666667 | 13255 |
| 013934 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592742.6 | 510100.6 | 15526 | 1.64041666667 | 13934 |
| 014133 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592745.6 | 510101.5 | 15528 | 1.64041666667 | 14133 |
| 012953 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592747.9 | 510102.6 | 15530 | 1.64041666667 | 12953 |
| 013708 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.0 | 1592751.2 | 510103.4 | 15532 | 1.64041666667 | 13708 |
| 012547 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592753.9 | 510103.3 | 15534 | 1.64041666667 | 12547 |
| 013216 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592757.3 | 510103.5 | 15536 | 1.64041666667 | 13216 |
| 013324 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592759.8 | 510104.1 | 15538 | 1.64041666667 | 13324 |
| 013651 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592763.0 | 510104.9 | 15540 | 1.64041666667 | 13651 |
| 014272 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592765.3 | 510105.8 | 15542 | 1.64041666667 | 14272 |
| 014158 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592768.4 | 510107.0 | 15544 | 1.64041666667 | 14158 |
| 013499 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592771.5 | 510107.6 | 15546 | 1.64041666667 | 13499 |
| 014625 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592774.6 | 510108.8 | 15548 | 1.64041666667 | 14625 |
| 015776 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592776.8 | 510109.4 | 15550 | 1.64041666667 | 15776 |
| 013514 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592780.3 | 510110.5 | 15552 | 1.64041666667 | 13514 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012708 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592782.4 | 510112.0 | 15554 | 1.64041666667 | 12708 |
| 012567 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592785.4 | 510113.6 | 15556 | 1.64041666667 | 12567 |
| 013701 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592788.3 | 510114.7 | 15558 | 1.64041666667 | 13701 |
| 014225 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592791.5 | 510116.6 | 15560 | 1.64041666667 | 14225 |
| 014116 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:40pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592794.0 | 510117.7 | 15562 | 1.64041666667 | 14116 |
| 012589 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592797.3 | 510119.3 | 15564 | 1.64041666667 | 12589 |
| 014067 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592800.2 | 510120.9 | 15566 | 1.64041666667 | 14067 |
| 015997 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592803.4 | 510122.1 | 15568 | 1.64041666667 | 15997 |
| 014799 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592806.6 | 510123.4 | 15570 | 1.64041666667 | 14799 |
| 014289 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592809.9 | 510125.0 | 15572 | 1.64041666667 | 14289 |
| 013892 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592812.5 | 510126.2 | 15574 | 1.64041666667 | 13892 |
| 012563 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592815.7 | 510127.6 | 15576 | 1.64041666667 | 12563 |
| 013820 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592818.9 | 510129.0 | 15578 | 1.64041666667 | 13820 |
| 014885 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592822.3 | 510130.3 | 15580 | 1.64041666667 | 14885 |
| 012961 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592825.1 | 510131.8 | 15582 | 1.64041666667 | 12961 |
| 014850 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592828.6 | 510133.7 | 15584 | 1.64041666667 | 14850 |
| 013822 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592831.4 | 510134.8 | 15586 | 1.64041666667 | 13822 |
| 013745 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592834.6 | 510136.4 | 15588 | 1.64041666667 | 13745 |
| 014566 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592837.0 | 510138.2 | 15590 | 1.64041666667 | 14566 |
| 015551 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592839.9 | 510139.8 | 15592 | 1.64041666667 | 15551 |
| 013638 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592842.3 | 510140.3 | 15594 | 1.64041666667 | 13638 |
| 012109 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592844.4 | 510139.0 | 15596 | 1.64041666667 | 12109 |
| 012417 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592843.8 | 510137.2 | 15598 | 1.64041666667 | 12417 |
| 011924 | 0 | GeoXH 6000 | 08/18/2015 | 12:15:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592841.3 | 510135.1 | 15600 | 1.64041666667 | 11924 |
| 012851 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592839.0 | 510133.8 | 15602 | 1.64041666667 | 12851 |
| 011942 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592836.0 | 510133.3 | 15604 | 1.64041666667 | 11942 |
| 011835 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592833.4 | 510132.9 | 15606 | 1.64041666667 | 11835 |
| 012048 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592830.2 | 510132.5 | 15608 | 1.64041666667 | 12048 |
| 016062 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592827.6 | 510132.5 | 15610 | 1.64041666667 | 16062 |
| 014215 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592824.7 | 510132.3 | 15612 | 1.64041666667 | 14215 |
| 014444 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592822.1 | 510132.5 | 15614 | 1.64041666667 | 14444 |
| 015401 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592819.4 | 510132.3 | 15616 | 1.64041666667 | 15401 |
| 016660 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592817.4 | 510132.6 | 15618 | 1.64041666667 | 16660 |
| 015055 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592815.0 | 510133.2 | 15620 | 1.64041666667 | 15055 |
| 014833 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592813.9 | 510134.5 | 15622 | 1.64041666667 | 14833 |
| 012918 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592813.4 | 510135.3 | 15624 | 1.64041666667 | 12918 |
| 013459 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592813.1 | 510135.2 | 15626 | 1.64041666667 | 13459 |
| 014104 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592811.6 | 510134.3 | 15628 | 1.64041666667 | 14104 |
| 013366 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592809.9 | 510132.8 | 15630 | 1.64041666667 | 13366 |
| 013001 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592808.0 | 510130.9 | 15632 | 1.64041666667 | 13001 |
| 012820 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592806.4 | 510129.5 | 15634 | 1.64041666667 | 12820 |
| 013645 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:17pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592804.6 | 510127.7 | 15636 | 1.64041666667 | 13645 |
| 014361 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592802.9 | 510126.1 | 15638 | 1.64041666667 | 14361 |
| 014210 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592801.3 | 510124.5 | 15640 | 1.64041666667 | 14210 |
| 013452 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:20pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592799.5 | 510123.4 | 15642 | 1.64041666667 | 13452 |
| 012753 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:21pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592797.7 | 510122.1 | 15644 | 1.64041666667 | 12753 |
| 015038 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:22pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592795.9 | 510121.2 | 15646 | 1.64041666667 | 15038 |
| 014469 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:23pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592793.4 | 510119.8 | 15648 | 1.64041666667 | 14469 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015107 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592791.4 | 510119.0 | 15650 | 1.64041666667 | 15107 |
| 015716 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592788.8 | 510118.4 | 15652 | 1.64041666667 | 15716 |
| 013199 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592786.6 | 510117.9 | 15654 | 1.64041666667 | 13199 |
| 013320 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592783.8 | 510118.1 | 15656 | 1.64041666667 | 13320 |
| 015660 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592782.0 | 510117.3 | 15658 | 1.64041666667 | 15660 |
| 013035 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592779.8 | 510115.6 | 15660 | 1.64041666667 | 13035 |
| 013368 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592778.3 | 510113.7 | 15662 | 1.64041666667 | 13368 |
| 012822 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:31pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592776.8 | 510110.9 | 15664 | 1.64041666667 | 12822 |
| 014245 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:32pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592775.5 | 510108.7 | 15666 | 1.64041666667 | 14245 |
| 013461 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:33pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592774.2 | 510105.9 | 15668 | 1.64041666667 | 13461 |
| 013565 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:34pm | Sensor | 1797-S0023-G-TJV.cor | 6801.1 | 1592773.7 | 510103.7 | 15670 | 1.64041666667 | 13565 |
| 013471 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:35pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592773.3 | 510100.9 | 15672 | 1.64041666667 | 13471 |
| 013267 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:36pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592774.1 | 510099.6 | 15674 | 1.64041666667 | 13267 |
| 013187 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:37pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592776.1 | 510099.2 | 15676 | 1.64041666667 | 13187 |
| 014096 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:38pm | Sensor | 1797-S0023-G-TJV.cor | 6801.2 | 1592777.8 | 510099.2 | 15678 | 1.64041666667 | 14096 |
| 014564 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:39pm | Sensor | 1797-S0023-G-TJV.cor | 6801.3 | 1592780.0 | 510099.8 | 15680 | 1.64041666667 | 14564 |
| 014801 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:40pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592782.4 | 510100.3 | 15682 | 1.64041666667 | 14801 |
| 014560 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:41pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592784.4 | 510101.2 | 15684 | 1.64041666667 | 14560 |
| 014830 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:42pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592786.5 | 510101.2 | 15686 | 1.64041666667 | 14830 |
| 014117 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592788.6 | 510101.8 | 15688 | 1.64041666667 | 14117 |
| 013369 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592790.6 | 510102.8 | 15690 | 1.64041666667 | 13369 |
| 012972 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592792.7 | 510104.1 | 15692 | 1.64041666667 | 12972 |
| 016203 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592794.3 | 510105.2 | 15694 | 1.64041666667 | 16203 |
| 014310 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592796.6 | 510106.7 | 15696 | 1.64041666667 | 14310 |
| 012187 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592798.1 | 510108.2 | 15698 | 1.64041666667 | 12187 |
| 013697 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592800.0 | 510109.7 | 15700 | 1.64041666667 | 13697 |
| 012154 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592801.6 | 510111.4 | 15702 | 1.64041666667 | 12154 |
| 013838 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592803.9 | 510112.4 | 15704 | 1.64041666667 | 13838 |
| 013689 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592805.9 | 510113.1 | 15706 | 1.64041666667 | 13689 |
| 013652 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592808.7 | 510114.2 | 15708 | 1.64041666667 | 13652 |
| 014273 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592810.9 | 510115.0 | 15710 | 1.64041666667 | 14273 |
| 014008 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592813.1 | 510116.3 | 15712 | 1.64041666667 | 14008 |
| 013552 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.5 | 1592815.2 | 510116.9 | 15714 | 1.64041666667 | 13552 |
| 015268 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.4 | 1592818.4 | 510117.3 | 15716 | 1.64041666667 | 15268 |
| 015997 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592820.1 | 510116.3 | 15718 | 1.64041666667 | 15997 |
| 013449 | 0 | GeoXH 6000 | 08/18/2015 | 12:16:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592820.8 | 510114.1 | 15720 | 1.64041666667 | 13449 |
| 013442 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592820.4 | 510112.4 | 15722 | 1.64041666667 | 13442 |
| 013770 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592820.0 | 510110.3 | 15724 | 1.64041666667 | 13770 |
| 014092 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592819.7 | 510108.3 | 15726 | 1.64041666667 | 14092 |
| 013453 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592819.7 | 510106.1 | 15728 | 1.64041666667 | 13453 |
| 013113 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592819.6 | 510104.2 | 15730 | 1.64041666667 | 13113 |
| 014498 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:05pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592820.0 | 510102.7 | 15732 | 1.64041666667 | 14498 |
| 013704 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592820.8 | 510101.1 | 15734 | 1.64041666667 | 13704 |
| 013356 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592822.1 | 510099.9 | 15736 | 1.64041666667 | 13356 |
| 012999 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592823.3 | 510098.6 | 15738 | 1.64041666667 | 12999 |
| 012969 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.9 | 1592824.5 | 510097.9 | 15740 | 1.64041666667 | 12969 |
| 013952 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:10pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592826.1 | 510097.4 | 15742 | 1.64041666667 | 13952 |
| 013808 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:11pm | Sensor | 1797-S0023-G-TJV.cor | 6802.0 | 1592827.9 | 510096.9 | 15744 | 1.64041666667 | 13808 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013472 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:12pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592829.2 | 510096.0 | 15746 | 1.64041666667 | 13472 |
| 013838 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:13pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592830.9 | 510094.8 | 15748 | 1.64041666667 | 13838 |
| 013629 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:14pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592831.9 | 510093.4 | 15750 | 1.64041666667 | 13629 |
| 014027 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:15pm | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592832.8 | 510091.3 | 15752 | 1.64041666667 | 14027 |
| 013616 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:16pm | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592833.2 | 510089.1 | 15754 | 1.64041666667 | 13616 |
| 013964 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:17pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592833.3 | 510086.8 | 15756 | 1.64041666667 | 13964 |
| 013211 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:18pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592833.5 | 510084.7 | 15758 | 1.64041666667 | 13211 |
| 014252 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:19pm | Sensor | 1797-S0023-G-TJV.cor | 6802.2 | 1592833.4 | 510082.8 | 15760 | 1.64041666667 | 14252 |
| 013493 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:20pm | Sensor | 1797-S0023-G-TJV.cor | 6802.1 | 1592833.5 | 510081.0 | 15762 | 1.64041666667 | 13493 |
| 014323 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:21pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592833.8 | 510078.6 | 15764 | 1.64041666667 | 14323 |
| 013931 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:22pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592834.6 | 510076.6 | 15766 | 1.64041666667 | 13931 |
| 015242 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:23pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592835.0 | 510074.5 | 15768 | 1.64041666667 | 15242 |
| 015780 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:24pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592835.5 | 510072.6 | 15770 | 1.64041666667 | 15780 |
| 015855 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:25pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592835.8 | 510070.4 | 15772 | 1.64041666667 | 15855 |
| 014313 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:26pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592836.4 | 510068.8 | 15774 | 1.64041666667 | 14313 |
| 012578 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:27pm | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1592837.5 | 510066.9 | 15776 | 1.64041666667 | 12578 |
| 015024 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:28pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592838.9 | 510065.6 | 15778 | 1.64041666667 | 15024 |
| 014496 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:29pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592840.7 | 510064.0 | 15780 | 1.64041666667 | 14496 |
| 015834 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:30pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592842.1 | 510062.4 | 15782 | 1.64041666667 | 15834 |
| 013378 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:31pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592843.2 | 510060.6 | 15784 | 1.64041666667 | 13378 |
| 012344 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:32pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592844.0 | 510059.2 | 15786 | 1.64041666667 | 12344 |
| 012536 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:33pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592845.2 | 510057.2 | 15788 | 1.64041666667 | 12536 |
| 013034 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:34pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592846.4 | 510055.9 | 15790 | 1.64041666667 | 13034 |
| 013608 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:35pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592847.7 | 510054.0 | 15792 | 1.64041666667 | 13608 |
| 014982 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:36pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592848.8 | 510052.1 | 15794 | 1.64041666667 | 14982 |
| 014455 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:37pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592850.2 | 510050.1 | 15796 | 1.64041666667 | 14455 |
| 013754 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:38pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592851.5 | 510048.1 | 15798 | 1.64041666667 | 13754 |
| 013128 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:39pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592853.2 | 510046.0 | 15800 | 1.64041666667 | 13128 |
| 015162 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:40pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592854.1 | 510044.3 | 15802 | 1.64041666667 | 15162 |
| 014800 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:41pm | Sensor | 1797-S0023-G-TJV.cor | 6802.3 | 1592855.4 | 510042.0 | 15804 | 1.64041666667 | 14800 |
| 014710 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:42pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592856.1 | 510039.9 | 15806 | 1.64041666667 | 14710 |
| 013097 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:43pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592856.7 | 510037.3 | 15808 | 1.64041666667 | 13097 |
| 012994 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:44pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592856.8 | 510035.2 | 15810 | 1.64041666667 | 12994 |
| 012728 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:45pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592857.4 | 510032.7 | 15812 | 1.64041666667 | 12728 |
| 012962 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:46pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592857.4 | 510030.5 | 15814 | 1.64041666667 | 12962 |
| 014400 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:47pm | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1592857.5 | 510029.4 | 15816 | 1.64041666667 | 14400 |
| 012030 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:48pm | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1592857.6 | 510029.4 | 15818 | 1.64041666667 | 12030 |
| 013357 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:49pm | Sensor | 1797-S0023-G-TJV.cor | 6802.6 | 1592857.7 | 510029.5 | 15820 | 1.64041666667 | 13357 |
| 012219 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:50pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592857.8 | 510029.7 | 15822 | 1.64041666667 | 12219 |
| 012175 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:51pm | Sensor | 1797-S0023-G-TJV.cor | 6802.5 | 1592857.9 | 510029.8 | 15824 | 1.64041666667 | 12175 |
| 013573 | 0 | GeoXH 6000 | 08/18/2015 | 12:17:52pm | Sensor | 1797-S0023-G-TJV.cor | 6802.4 | 1592858.0 | 510029.8 | 15826 | 1.64041666667 | 13573 |
| 020177 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:43pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.7 | 15829 | 1.64041666667 | 20177 |
| 021454 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:44pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.9 | 510075.7 | 15831 | 1.64041666667 | 21454 |
| 020573 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:45pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.9 | 510075.7 | 15833 | 1.64041666667 | 20573 |
| 019933 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:46pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.8 | 510075.7 | 15835 | 1.64041666667 | 19933 |
| 021453 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:47pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.9 | 510075.7 | 15837 | 1.64041666667 | 21453 |
| 020843 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:48pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.9 | 510075.7 | 15838 | 1.64041666667 | 20843 |
| 019190 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:49pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.8 | 510075.7 | 15839 | 1.64041666667 | 19190 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017007 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:50pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.8 | 510075.7 | 15840 | 1.64041666667 | 17007 |
| 018772 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:51pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.8 | 510075.7 | 15841 | 1.64041666667 | 18772 |
| 018913 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:52pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.8 | 510075.8 | 15842 | 1.64041666667 | 18913 |
| 020298 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:53pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.8 | 510075.8 | 15843 | 1.64041666667 | 20298 |
| 021274 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:54pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.8 | 510075.8 | 15844 | 1.64041666667 | 21274 |
| 022088 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:55pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.8 | 510075.8 | 15845 | 1.64041666667 | 22088 |
| 020402 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:56pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.8 | 510075.8 | 15846 | 1.64041666667 | 20402 |
| 019860 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:57pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.8 | 510075.8 | 15847 | 1.64041666667 | 19860 |
| 020145 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:58pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.6 | 15848 | 1.64041666667 | 20145 |
| 021896 | 0 | GeoXH 6000 | 08/18/2015 | 12:18:59pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592760.1 | 510075.3 | 15849 | 1.64041666667 | 21896 |
| 022364 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:00pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592760.0 | 510075.3 | 15850 | 1.64041666667 | 22364 |
| 019241 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:01pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592759.9 | 510075.4 | 15851 | 1.64041666667 | 19241 |
| 018910 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:02pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592759.9 | 510075.5 | 15852 | 1.64041666667 | 18910 |
| 020147 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:03pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592759.9 | 510075.4 | 15853 | 1.64041666667 | 20147 |
| 020306 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:04pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592759.9 | 510075.4 | 15854 | 1.64041666667 | 20306 |
| 020586 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:05pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592759.9 | 510075.4 | 15855 | 1.64041666667 | 20586 |
| 019606 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:06pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15856 | 1.64041666667 | 19606 |
| 020801 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:07pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15857 | 1.64041666667 | 20801 |
| 019690 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:08pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15858 | 1.64041666667 | 19690 |
| 018272 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:09pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15859 | 1.64041666667 | 18272 |
| 019538 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:10pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592759.9 | 510075.5 | 15860 | 1.64041666667 | 19538 |
| 019374 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:11pm | Sensor | 1797-S0023-G-TJV.cor | 6801.8 | 1592759.9 | 510075.5 | 15861 | 1.64041666667 | 19374 |
| 019453 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:12pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15862 | 1.64041666667 | 19453 |
| 021393 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:13pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15863 | 1.64041666667 | 21393 |
| 019778 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:14pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15864 | 1.64041666667 | 19778 |
| 019704 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:15pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592760.0 | 510075.5 | 15865 | 1.64041666667 | 19704 |
| 019806 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:16pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15866 | 1.64041666667 | 19806 |
| 019981 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:17pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15867 | 1.64041666667 | 19981 |
| 018975 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:18pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15868 | 1.64041666667 | 18975 |
| 020973 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:19pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.5 | 15869 | 1.64041666667 | 20973 |
| 021118 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:24pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.9 | 510075.6 | 15870 | 1.64041666667 | 21118 |
| 020579 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:25pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.7 | 510075.7 | 15872 | 1.64041666667 | 20579 |
| 018915 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:26pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.7 | 510075.8 | 15874 | 1.64041666667 | 18915 |
| 019698 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:27pm | Sensor | 1797-S0023-G-TJV.cor | 6801.7 | 1592759.6 | 510075.8 | 15876 | 1.64041666667 | 19698 |
| 018754 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:28pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.6 | 510075.9 | 15878 | 1.64041666667 | 18754 |
| 019598 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:29pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.6 | 510075.8 | 15880 | 1.64041666667 | 19598 |
| 019659 | 0 | GeoXH 6000 | 08/18/2015 | 12:19:30pm | Sensor | 1797-S0023-G-TJV.cor | 6801.6 | 1592759.6 | 510075.8 | 15882 | 1.64041666667 | 19659 |
| 013391 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:44am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594552.8 | 511654.6 | 10416 | 1.64041666667 | 13391 |
| 012955 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:45am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594552.8 | 511654.6 | 10419 | 1.64041666667 | 12955 |
| 012695 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:46am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.7 | 10421 | 1.64041666667 | 12695 |
| 012308 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:47am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.7 | 10423 | 1.64041666667 | 12308 |
| 012016 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:48am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.6 | 10425 | 1.64041666667 | 12016 |
| 012414 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:49am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.6 | 10427 | 1.64041666667 | 12414 |
| 012735 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:50am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.6 | 10429 | 1.64041666667 | 12735 |
| 012998 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:51am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594552.8 | 511654.6 | 10431 | 1.64041666667 | 12998 |
| 013146 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:52am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.6 | 10433 | 1.64041666667 | 13146 |
| 013245 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:53am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.6 | 10435 | 1.64041666667 | 13245 |
| 013465 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:54am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.6 | 10437 | 1.64041666667 | 13465 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013724 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:55am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.6 | 10439 | 1.64041666667 | 13724 |
| 012677 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:56am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.8 | 511654.6 | 10441 | 1.64041666667 | 12677 |
| 013648 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:57am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594552.7 | 511654.7 | 10443 | 1.64041666667 | 13648 |
| 014134 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:58am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594552.1 | 511655.3 | 10445 | 1.64041666667 | 14134 |
| 013680 | 0 | GeoXH 6000 | 08/19/2015 | 11:53:59am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594551.7 | 511655.3 | 10447 | 1.64041666667 | 13680 |
| 014385 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:00am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594551.7 | 511655.0 | 10449 | 1.64041666667 | 14385 |
| 014324 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:01am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.3 | 511655.9 | 10451 | 1.64041666667 | 14324 |
| 014290 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:02am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594552.2 | 511657.9 | 10453 | 1.64041666667 | 14290 |
| 013865 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:03am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594552.7 | 511659.6 | 10455 | 1.64041666667 | 13865 |
| 013559 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:04am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.4 | 511661.8 | 10457 | 1.64041666667 | 13559 |
| 012959 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:05am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594552.7 | 511663.7 | 10459 | 1.64041666667 | 12959 |
| 013087 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:06am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594551.9 | 511665.6 | 10461 | 1.64041666667 | 13087 |
| 013361 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:07am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594550.9 | 511667.2 | 10463 | 1.64041666667 | 13361 |
| 012938 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:08am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594549.6 | 511668.9 | 10465 | 1.64041666667 | 12938 |
| 013015 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:09am | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594547.8 | 511670.2 | 10467 | 1.64041666667 | 13015 |
| 012841 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:10am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594546.2 | 511671.9 | 10469 | 1.64041666667 | 12841 |
| 013103 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:11am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594544.8 | 511673.6 | 10471 | 1.64041666667 | 13103 |
| 013183 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:12am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594542.7 | 511675.0 | 10473 | 1.64041666667 | 13183 |
| 012793 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:13am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594541.4 | 511676.6 | 10475 | 1.64041666667 | 12793 |
| 013091 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:14am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594540.1 | 511678.8 | 10477 | 1.64041666667 | 13091 |
| 012748 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:15am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594538.9 | 511680.7 | 10479 | 1.64041666667 | 12748 |
| 012601 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:16am | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594538.2 | 511683.2 | 10481 | 1.64041666667 | 12601 |
| 013815 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:17am | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594537.3 | 511685.1 | 10483 | 1.64041666667 | 13815 |
| 013291 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:18am | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594536.7 | 511687.7 | 10485 | 1.64041666667 | 13291 |
| 013979 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:19am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594536.4 | 511689.8 | 10487 | 1.64041666667 | 13979 |
| 013795 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:20am | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594535.6 | 511692.1 | 10489 | 1.64041666667 | 13795 |
| 012815 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:21am | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594535.3 | 511694.4 | 10491 | 1.64041666667 | 12815 |
| 012368 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:22am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594534.5 | 511696.7 | 10493 | 1.64041666667 | 12368 |
| 012769 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:23am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594533.5 | 511698.3 | 10495 | 1.64041666667 | 12769 |
| 013483 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:24am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594532.5 | 511700.1 | 10497 | 1.64041666667 | 13483 |
| 013239 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:25am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594531.2 | 511701.5 | 10499 | 1.64041666667 | 13239 |
| 013687 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:26am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594530.0 | 511703.7 | 10501 | 1.64041666667 | 13687 |
| 012791 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:27am | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594529.0 | 511705.6 | 10503 | 1.64041666667 | 12791 |
| 012400 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:28am | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594527.8 | 511707.6 | 10505 | 1.64041666667 | 12400 |
| 012750 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:29am | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594527.2 | 511709.5 | 10507 | 1.64041666667 | 12750 |
| 013082 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:30am | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594525.9 | 511711.7 | 10509 | 1.64041666667 | 13082 |
| 012826 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:31am | Sensor | 1797-S0011-905-G-ACK | 6821.7 | 1594524.8 | 511713.4 | 10511 | 1.64041666667 | 12826 |
| 012674 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:32am | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594523.5 | 511715.3 | 10513 | 1.64041666667 | 12674 |
| 012319 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:33am | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594522.2 | 511716.7 | 10515 | 1.64041666667 | 12319 |
| 012562 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:34am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594521.0 | 511719.3 | 10517 | 1.64041666667 | 12562 |
| 011948 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:35am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594519.9 | 511721.1 | 10519 | 1.64041666667 | 11948 |
| 011881 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:36am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594518.6 | 511723.2 | 10521 | 1.64041666667 | 11881 |
| 011843 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:37am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594517.7 | 511725.1 | 10523 | 1.64041666667 | 11843 |
| 012061 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:38am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594516.4 | 511727.1 | 10525 | 1.64041666667 | 12061 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:39am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594515.9 | 511729.0 | 10527 | 1.64041666667 | 12454 |
| 012713 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:40am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594516.3 | 511731.5 | 10529 | 1.64041666667 | 12713 |
| 012303 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:41am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594516.3 | 511733.5 | 10531 | 1.64041666667 | 12303 |
| 012853 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:42am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594516.7 | 511735.8 | 10533 | 1.64041666667 | 12853 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012877 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:43am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594516.2 | 511737.9 | 10535 | 1.64041666667 | 12877 |
| 012313 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:44am | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594515.3 | 511739.9 | 10537 | 1.64041666667 | 12313 |
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:45am | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594514.9 | 511741.7 | 10539 | 1.64041666667 | 12401 |
| 012660 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:46am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594513.7 | 511743.6 | 10541 | 1.64041666667 | 12660 |
| 012011 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:47am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594513.1 | 511745.5 | 10543 | 1.64041666667 | 12011 |
| 012164 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:48am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594512.0 | 511747.9 | 10545 | 1.64041666667 | 12164 |
| 011882 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:49am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594511.0 | 511749.5 | 10547 | 1.64041666667 | 11882 |
| 012301 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:50am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594510.1 | 511751.4 | 10549 | 1.64041666667 | 12301 |
| 012754 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:51am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594508.8 | 511753.1 | 10551 | 1.64041666667 | 12754 |
| 012049 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:52am | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594507.6 | 511755.0 | 10553 | 1.64041666667 | 12049 |
| 011922 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:53am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594506.9 | 511756.9 | 10555 | 1.64041666667 | 11922 |
| 011514 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:54am | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594505.4 | 511758.7 | 10557 | 1.64041666667 | 11514 |
| 010984 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:55am | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594504.5 | 511760.7 | 10559 | 1.64041666667 | 10984 |
| 012103 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:56am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594502.8 | 511762.9 | 10561 | 1.64041666667 | 12103 |
| 011555 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:57am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594501.7 | 511764.9 | 10563 | 1.64041666667 | 11555 |
| 011592 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:58am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594501.5 | 511767.2 | 10565 | 1.64041666667 | 11592 |
| 011703 | 0 | GeoXH 6000 | 08/19/2015 | 11:54:59am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594501.1 | 511769.1 | 10567 | 1.64041666667 | 11703 |
| 011135 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:00am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594501.1 | 511771.2 | 10569 | 1.64041666667 | 11135 |
| 011093 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:01am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594500.4 | 511772.6 | 10571 | 1.64041666667 | 11093 |
| 010957 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:02am | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594499.2 | 511774.4 | 10573 | 1.64041666667 | 10957 |
| 011068 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:03am | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594498.7 | 511776.1 | 10575 | 1.64041666667 | 11068 |
| 011498 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:04am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594497.4 | 511777.9 | 10577 | 1.64041666667 | 11498 |
| 011463 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:05am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594496.2 | 511779.3 | 10579 | 1.64041666667 | 11463 |
| 010603 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:06am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594494.7 | 511781.1 | 10581 | 1.64041666667 | 10603 |
| 010959 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:07am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594493.5 | 511782.1 | 10583 | 1.64041666667 | 10959 |
| 010349 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:08am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594492.3 | 511783.4 | 10585 | 1.64041666667 | 10349 |
| 010884 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:09am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594490.4 | 511783.7 | 10587 | 1.64041666667 | 10884 |
| 010869 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:10am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594488.3 | 511784.8 | 10589 | 1.64041666667 | 10869 |
| 011206 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:11am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594486.6 | 511785.9 | 10591 | 1.64041666667 | 11206 |
| 011148 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:12am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594485.3 | 511787.5 | 10593 | 1.64041666667 | 11148 |
| 011581 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:13am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594484.9 | 511788.6 | 10595 | 1.64041666667 | 11581 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:14am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594484.2 | 511789.2 | 10597 | 1.64041666667 | 12056 |
| 011717 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:15am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594483.0 | 511789.7 | 10599 | 1.64041666667 | 11717 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:16am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594481.2 | 511789.8 | 10601 | 1.64041666667 | 11953 |
| 011291 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:17am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594479.7 | 511791.0 | 10603 | 1.64041666667 | 11291 |
| 011264 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:18am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594477.8 | 511792.8 | 10605 | 1.64041666667 | 11264 |
| 011728 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:19am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594477.2 | 511794.5 | 10607 | 1.64041666667 | 11728 |
| 012364 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:20am | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594478.0 | 511796.4 | 10609 | 1.64041666667 | 12364 |
| 011747 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:21am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594478.5 | 511798.3 | 10611 | 1.64041666667 | 11747 |
| 011175 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:22am | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594478.3 | 511800.4 | 10613 | 1.64041666667 | 11175 |
| 011033 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:23am | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594477.7 | 511801.9 | 10615 | 1.64041666667 | 11033 |
| 011171 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:24am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594476.5 | 511803.8 | 10617 | 1.64041666667 | 11171 |
| 010521 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:25am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594476.1 | 511805.6 | 10619 | 1.64041666667 | 10521 |
| 010515 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:26am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594475.3 | 511807.7 | 10621 | 1.64041666667 | 10515 |
| 010295 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:27am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594474.3 | 511809.3 | 10623 | 1.64041666667 | 10295 |
| 010613 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:28am | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594473.9 | 511811.6 | 10625 | 1.64041666667 | 10613 |
| 010777 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:29am | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594474.1 | 511813.1 | 10627 | 1.64041666667 | 10777 |
| 011057 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:30am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594474.0 | 511814.7 | 10629 | 1.64041666667 | 11057 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 010225 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:31am | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594473.6 | 511815.5 | 10631 | 1.64041666667 | 10225 |
| 011631 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:32am | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594472.0 | 511815.1 | 10633 | 1.64041666667 | 11631 |
| 010847 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:33am | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594470.8 | 511814.3 | 10635 | 1.64041666667 | 10847 |
| 010909 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:34am | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594469.3 | 511813.2 | 10637 | 1.64041666667 | 10909 |
| 010966 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:35am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594468.3 | 511811.2 | 10639 | 1.64041666667 | 10966 |
| 010856 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:36am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594467.6 | 511809.3 | 10641 | 1.64041666667 | 10856 |
| 010516 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:37am | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594467.8 | 511807.5 | 10643 | 1.64041666667 | 10516 |
| 010565 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:38am | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594468.1 | 511805.7 | 10645 | 1.64041666667 | 10565 |
| 010743 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:39am | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594468.2 | 511804.0 | 10647 | 1.64041666667 | 10743 |
| 010610 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:40am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594467.9 | 511802.3 | 10649 | 1.64041666667 | 10610 |
| 010783 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:41am | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594467.0 | 511801.2 | 10651 | 1.64041666667 | 10783 |
| 010633 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:42am | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594467.0 | 511799.6 | 10653 | 1.64041666667 | 10633 |
| 010946 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:43am | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594467.1 | 511798.0 | 10655 | 1.64041666667 | 10946 |
| 011309 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:44am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594467.6 | 511796.2 | 10657 | 1.64041666667 | 11309 |
| 011251 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:45am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594468.1 | 511794.6 | 10659 | 1.64041666667 | 11251 |
| 010161 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:46am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594467.7 | 511792.6 | 10661 | 1.64041666667 | 10161 |
| 010545 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:47am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594468.0 | 511790.5 | 10663 | 1.64041666667 | 10545 |
| 011077 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:48am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594468.3 | 511788.5 | 10665 | 1.64041666667 | 11077 |
| 010776 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:49am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594469.1 | 511786.6 | 10667 | 1.64041666667 | 10776 |
| 011206 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:50am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594470.3 | 511785.0 | 10669 | 1.64041666667 | 11206 |
| 011366 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:51am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594471.3 | 511783.2 | 10671 | 1.64041666667 | 11366 |
| 011801 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:52am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594473.0 | 511782.0 | 10673 | 1.64041666667 | 11801 |
| 012015 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:53am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594474.6 | 511780.3 | 10675 | 1.64041666667 | 12015 |
| 011633 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:54am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594475.7 | 511779.0 | 10677 | 1.64041666667 | 11633 |
| 011021 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:55am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594477.4 | 511777.7 | 10679 | 1.64041666667 | 11021 |
| 011014 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:56am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594478.6 | 511776.1 | 10681 | 1.64041666667 | 11014 |
| 011490 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:57am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594480.0 | 511774.8 | 10683 | 1.64041666667 | 11490 |
| 011398 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:58am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594481.8 | 511773.7 | 10685 | 1.64041666667 | 11398 |
| 010686 | 0 | GeoXH 6000 | 08/19/2015 | 11:55:59am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594482.9 | 511772.3 | 10687 | 1.64041666667 | 10686 |
| 010631 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:00am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594485.2 | 511771.4 | 10689 | 1.64041666667 | 10631 |
| 011687 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:01am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594487.0 | 511770.7 | 10691 | 1.64041666667 | 11687 |
| 011606 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:02am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594489.1 | 511770.0 | 10693 | 1.64041666667 | 11606 |
| 011021 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:03am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594491.1 | 511768.9 | 10695 | 1.64041666667 | 11021 |
| 011157 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:04am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594492.5 | 511766.9 | 10697 | 1.64041666667 | 11157 |
| 010753 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:05am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594493.9 | 511765.6 | 10699 | 1.64041666667 | 10753 |
| 011021 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:06am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594495.2 | 511763.6 | 10701 | 1.64041666667 | 11021 |
| 011922 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:07am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594496.2 | 511761.9 | 10703 | 1.64041666667 | 11922 |
| 012023 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:08am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594497.8 | 511760.0 | 10705 | 1.64041666667 | 12023 |
| 011608 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:09am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594498.2 | 511758.2 | 10707 | 1.64041666667 | 11608 |
| 011547 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:10am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594499.0 | 511755.8 | 10709 | 1.64041666667 | 11547 |
| 011167 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:11am | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594500.1 | 511754.0 | 10711 | 1.64041666667 | 11167 |
| 013241 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:12am | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594500.4 | 511751.9 | 10713 | 1.64041666667 | 13241 |
| 012046 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:13am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594500.6 | 511750.0 | 10715 | 1.64041666667 | 12046 |
| 011816 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:14am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594500.0 | 511747.4 | 10717 | 1.64041666667 | 11816 |
| 011266 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:15am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594500.0 | 511745.3 | 10719 | 1.64041666667 | 11266 |
| 011445 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:16am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594500.1 | 511742.8 | 10721 | 1.64041666667 | 11445 |
| 012047 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:17am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594500.0 | 511741.2 | 10723 | 1.64041666667 | 12047 |
| 013061 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:18am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594501.1 | 511739.3 | 10725 | 1.64041666667 | 13061 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012897 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:19am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594501.4 | 511737.6 | 10727 | 1.64041666667 | 12897 |
| 012609 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:20am | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594502.2 | 511735.4 | 10729 | 1.64041666667 | 12609 |
| 012388 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:21am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594502.6 | 511733.6 | 10731 | 1.64041666667 | 12388 |
| 012188 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:22am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594503.0 | 511732.0 | 10733 | 1.64041666667 | 12188 |
| 013163 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:23am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594503.8 | 511730.5 | 10735 | 1.64041666667 | 13163 |
| 012752 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:24am | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594504.6 | 511728.4 | 10737 | 1.64041666667 | 12752 |
| 012535 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:25am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594505.7 | 511726.7 | 10739 | 1.64041666667 | 12535 |
| 013261 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:26am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594506.4 | 511724.3 | 10741 | 1.64041666667 | 13261 |
| 013211 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:27am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594507.2 | 511722.4 | 10743 | 1.64041666667 | 13211 |
| 012839 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:28am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594508.1 | 511720.5 | 10745 | 1.64041666667 | 12839 |
| 012772 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:29am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594508.4 | 511718.6 | 10747 | 1.64041666667 | 12772 |
| 013207 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:30am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594509.2 | 511716.7 | 10749 | 1.64041666667 | 13207 |
| 012791 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:31am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594509.1 | 511715.0 | 10751 | 1.64041666667 | 12791 |
| 012062 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:32am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594510.0 | 511712.6 | 10753 | 1.64041666667 | 12062 |
| 011915 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:33am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594510.5 | 511710.7 | 10755 | 1.64041666667 | 11915 |
| 012372 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:34am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594511.1 | 511708.2 | 10757 | 1.64041666667 | 12372 |
| 011759 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:35am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594511.8 | 511706.5 | 10759 | 1.64041666667 | 11759 |
| 012547 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:36am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594512.0 | 511704.7 | 10761 | 1.64041666667 | 12547 |
| 012645 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:37am | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594513.2 | 511702.8 | 10763 | 1.64041666667 | 12645 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:38am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594513.9 | 511700.9 | 10765 | 1.64041666667 | 12918 |
| 012021 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:39am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594514.9 | 511699.2 | 10767 | 1.64041666667 | 12021 |
| 012889 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:40am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594515.9 | 511697.2 | 10769 | 1.64041666667 | 12889 |
| 013047 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:41am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594516.4 | 511695.5 | 10771 | 1.64041666667 | 13047 |
| 012686 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:42am | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594517.2 | 511693.6 | 10773 | 1.64041666667 | 12686 |
| 013811 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:43am | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594517.4 | 511691.7 | 10775 | 1.64041666667 | 13811 |
| 013619 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:44am | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594518.2 | 511689.6 | 10777 | 1.64041666667 | 13619 |
| 013668 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:45am | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594518.3 | 511687.7 | 10779 | 1.64041666667 | 13668 |
| 013560 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:46am | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594518.3 | 511686.1 | 10781 | 1.64041666667 | 13560 |
| 012833 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:47am | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594516.9 | 511685.3 | 10783 | 1.64041666667 | 12833 |
| 011921 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:48am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594515.1 | 511685.2 | 10785 | 1.64041666667 | 11921 |
| 011333 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:49am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594513.1 | 511685.5 | 10787 | 1.64041666667 | 11333 |
| 012307 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:50am | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594511.6 | 511685.9 | 10789 | 1.64041666667 | 12307 |
| 012307 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:51am | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594509.9 | 511685.2 | 10791 | 1.64041666667 | 12307 |
| 012173 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:52am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594507.8 | 511685.5 | 10793 | 1.64041666667 | 12173 |
| 011797 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:53am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594505.8 | 511685.2 | 10795 | 1.64041666667 | 11797 |
| 011653 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:54am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594504.4 | 511686.0 | 10797 | 1.64041666667 | 11653 |
| 011850 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:55am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594504.0 | 511687.9 | 10799 | 1.64041666667 | 11850 |
| 011503 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:56am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594503.6 | 511690.4 | 10801 | 1.64041666667 | 11503 |
| 011885 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:57am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594503.8 | 511692.8 | 10803 | 1.64041666667 | 11885 |
| 011853 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:58am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594503.7 | 511694.8 | 10805 | 1.64041666667 | 11853 |
| 011775 | 0 | GeoXH 6000 | 08/19/2015 | 11:56:59am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594503.1 | 511696.6 | 10807 | 1.64041666667 | 11775 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:00am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594503.0 | 511699.0 | 10809 | 1.64041666667 | 12180 |
| 012244 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:01am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594502.5 | 511701.1 | 10811 | 1.64041666667 | 12244 |
| 012737 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:02am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594501.5 | 511703.0 | 10813 | 1.64041666667 | 12737 |
| 012752 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:03am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594500.7 | 511704.7 | 10815 | 1.64041666667 | 12752 |
| 012805 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:04am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594499.6 | 511706.8 | 10817 | 1.64041666667 | 12805 |
| 012738 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:05am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594499.2 | 511708.9 | 10819 | 1.64041666667 | 12738 |
| 012205 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:06am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594498.9 | 511711.0 | 10821 | 1.64041666667 | 12205 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012895 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:07am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594498.0 | 511713.1 | 10823 | 1.64041666667 | 12895 |
| 012346 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:08am | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594497.7 | 511715.8 | 10825 | 1.64041666667 | 12346 |
| 010844 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:09am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594497.3 | 511717.8 | 10827 | 1.64041666667 | 10844 |
| 011290 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:10am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594495.8 | 511719.7 | 10829 | 1.64041666667 | 11290 |
| 012058 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:11am | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594495.1 | 511721.0 | 10831 | 1.64041666667 | 12058 |
| 011792 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:12am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594493.8 | 511722.0 | 10833 | 1.64041666667 | 11792 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:13am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594492.9 | 511723.5 | 10835 | 1.64041666667 | 12461 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:14am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594492.4 | 511725.4 | 10837 | 1.64041666667 | 12626 |
| 012697 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:15am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594492.0 | 511727.1 | 10839 | 1.64041666667 | 12697 |
| 012992 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:16am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594492.9 | 511729.0 | 10841 | 1.64041666667 | 12992 |
| 012265 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:17am | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594495.0 | 511730.8 | 10843 | 1.64041666667 | 12265 |
| 012554 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:18am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594496.1 | 511732.2 | 10845 | 1.64041666667 | 12554 |
| 012596 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:19am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594496.7 | 511733.6 | 10847 | 1.64041666667 | 12596 |
| 011760 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:20am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594496.9 | 511736.1 | 10849 | 1.64041666667 | 11760 |
| 012262 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:21am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594495.5 | 511737.7 | 10851 | 1.64041666667 | 12262 |
| 011600 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:22am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594493.3 | 511738.6 | 10853 | 1.64041666667 | 11600 |
| 011527 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:23am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594491.6 | 511739.9 | 10855 | 1.64041666667 | 11527 |
| 011711 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:24am | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594489.6 | 511741.6 | 10857 | 1.64041666667 | 11711 |
| 011365 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:25am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594487.8 | 511742.7 | 10859 | 1.64041666667 | 11365 |
| 011560 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:26am | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594486.6 | 511744.7 | 10861 | 1.64041666667 | 11560 |
| 011317 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:27am | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594486.1 | 511746.4 | 10863 | 1.64041666667 | 11317 |
| 010693 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:28am | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594486.0 | 511748.5 | 10865 | 1.64041666667 | 10693 |
| 010545 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:29am | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594486.5 | 511750.3 | 10867 | 1.64041666667 | 10545 |
| 011646 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:30am | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594486.5 | 511752.4 | 10869 | 1.64041666667 | 11646 |
| 012221 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:31am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594487.0 | 511754.0 | 10871 | 1.64041666667 | 12221 |
| 012034 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:32am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594486.7 | 511756.0 | 10873 | 1.64041666667 | 12034 |
| 012859 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:33am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594486.8 | 511757.5 | 10875 | 1.64041666667 | 12859 |
| 012056 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:34am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594487.0 | 511759.3 | 10877 | 1.64041666667 | 12056 |
| 011866 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:35am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594486.9 | 511760.9 | 10879 | 1.64041666667 | 11866 |
| 011310 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:36am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594486.4 | 511763.0 | 10881 | 1.64041666667 | 11310 |
| 011641 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:37am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594485.9 | 511765.0 | 10883 | 1.64041666667 | 11641 |
| 011836 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:38am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594485.3 | 511766.8 | 10885 | 1.64041666667 | 11836 |
| 011960 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:39am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594483.9 | 511768.0 | 10887 | 1.64041666667 | 11960 |
| 011760 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:40am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594482.3 | 511769.5 | 10889 | 1.64041666667 | 11760 |
| 012247 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:41am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594480.5 | 511770.3 | 10891 | 1.64041666667 | 12247 |
| 012131 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:42am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594478.4 | 511771.1 | 10893 | 1.64041666667 | 12131 |
| 012014 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:43am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594476.8 | 511771.6 | 10895 | 1.64041666667 | 12014 |
| 012060 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:44am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594474.8 | 511771.9 | 10897 | 1.64041666667 | 12060 |
| 012589 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:45am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594473.3 | 511773.1 | 10899 | 1.64041666667 | 12589 |
| 012158 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:46am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594471.6 | 511774.4 | 10901 | 1.64041666667 | 12158 |
| 012682 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:47am | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594470.3 | 511776.3 | 10903 | 1.64041666667 | 12682 |
| 012458 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:48am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594469.3 | 511777.9 | 10905 | 1.64041666667 | 12458 |
| 012524 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:49am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594467.8 | 511779.3 | 10907 | 1.64041666667 | 12524 |
| 012181 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:50am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594466.9 | 511781.2 | 10909 | 1.64041666667 | 12181 |
| 012837 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:51am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594465.6 | 511782.9 | 10911 | 1.64041666667 | 12837 |
| 012718 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:52am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594464.8 | 511784.7 | 10913 | 1.64041666667 | 12718 |
| 013229 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:53am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594464.1 | 511786.1 | 10915 | 1.64041666667 | 13229 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:54am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594462.7 | 511787.9 | 10917 | 1.64041666667 | 12106 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011707 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:55am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594461.7 | 511789.4 | 10919 | 1.64041666667 | 11707 |
| 011310 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:56am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594459.9 | 511790.7 | 10921 | 1.64041666667 | 11310 |
| 012182 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:57am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594458.6 | 511792.5 | 10923 | 1.64041666667 | 12182 |
| 012342 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:58am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594457.0 | 511794.3 | 10925 | 1.64041666667 | 12342 |
| 011960 | 0 | GeoXH 6000 | 08/19/2015 | 11:57:59am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594456.0 | 511795.7 | 10927 | 1.64041666667 | 11960 |
| 011850 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:00am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594455.4 | 511797.7 | 10929 | 1.64041666667 | 11850 |
| 011068 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:01am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594454.7 | 511798.9 | 10931 | 1.64041666667 | 11068 |
| 011025 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:02am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594454.6 | 511800.0 | 10933 | 1.64041666667 | 11025 |
| 010807 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:03am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594453.6 | 511799.7 | 10935 | 1.64041666667 | 10807 |
| 010639 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:04am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594452.1 | 511798.1 | 10937 | 1.64041666667 | 10639 |
| 011332 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:05am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594450.4 | 511797.5 | 10939 | 1.64041666667 | 11332 |
| 011669 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:06am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594449.2 | 511795.9 | 10941 | 1.64041666667 | 11669 |
| 011746 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:07am | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594447.5 | 511795.2 | 10943 | 1.64041666667 | 11746 |
| 012187 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:08am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594445.8 | 511794.0 | 10945 | 1.64041666667 | 12187 |
| 013380 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:09am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594444.5 | 511793.4 | 10947 | 1.64041666667 | 13380 |
| 012603 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:10am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594443.3 | 511792.4 | 10949 | 1.64041666667 | 12603 |
| 012527 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:11am | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594443.0 | 511792.1 | 10951 | 1.64041666667 | 12527 |
| 011531 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:12am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594444.1 | 511791.3 | 10953 | 1.64041666667 | 11531 |
| 011354 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:13am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594445.4 | 511790.5 | 10955 | 1.64041666667 | 11354 |
| 011314 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:14am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594446.7 | 511788.8 | 10957 | 1.64041666667 | 11314 |
| 010691 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:15am | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594448.2 | 511787.3 | 10959 | 1.64041666667 | 10691 |
| 011489 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:16am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594449.3 | 511785.4 | 10961 | 1.64041666667 | 11489 |
| 011480 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:17am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594451.1 | 511783.6 | 10963 | 1.64041666667 | 11480 |
| 011925 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:18am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594452.2 | 511781.8 | 10965 | 1.64041666667 | 11925 |
| 011455 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:19am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594453.0 | 511780.1 | 10967 | 1.64041666667 | 11455 |
| 012713 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:20am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594455.1 | 511778.5 | 10969 | 1.64041666667 | 12713 |
| 012371 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:21am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594456.0 | 511777.0 | 10971 | 1.64041666667 | 12371 |
| 011871 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:22am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594457.8 | 511775.2 | 10973 | 1.64041666667 | 11871 |
| 011740 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:23am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594459.2 | 511773.4 | 10975 | 1.64041666667 | 11740 |
| 011636 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:24am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594460.3 | 511771.4 | 10977 | 1.64041666667 | 11636 |
| 011645 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:25am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594462.1 | 511770.5 | 10979 | 1.64041666667 | 11645 |
| 012220 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:26am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594463.7 | 511768.5 | 10981 | 1.64041666667 | 12220 |
| 011636 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:27am | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594465.1 | 511766.9 | 10983 | 1.64041666667 | 11636 |
| 011968 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:28am | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594466.6 | 511765.2 | 10985 | 1.64041666667 | 11968 |
| 012042 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:29am | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594467.6 | 511763.5 | 10987 | 1.64041666667 | 12042 |
| 012248 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:30am | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594469.2 | 511761.9 | 10989 | 1.64041666667 | 12248 |
| 011487 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:31am | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594469.7 | 511760.2 | 10991 | 1.64041666667 | 11487 |
| 011291 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:32am | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594470.7 | 511757.8 | 10993 | 1.64041666667 | 11291 |
| 011264 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:33am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594471.8 | 511756.1 | 10995 | 1.64041666667 | 11264 |
| 010626 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:34am | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594472.7 | 511754.2 | 10997 | 1.64041666667 | 10626 |
| 012367 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:35am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594474.2 | 511753.2 | 10999 | 1.64041666667 | 12367 |
| 011981 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:36am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594476.1 | 511751.6 | 11001 | 1.64041666667 | 11981 |
| 011284 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:37am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594477.9 | 511750.1 | 11003 | 1.64041666667 | 11284 |
| 010570 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:38am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594479.6 | 511748.2 | 11005 | 1.64041666667 | 10570 |
| 010813 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:39am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594479.8 | 511746.2 | 11007 | 1.64041666667 | 10813 |
| 010890 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:40am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594479.6 | 511743.6 | 11009 | 1.64041666667 | 10890 |
| 011548 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:41am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594479.6 | 511741.6 | 11011 | 1.64041666667 | 11548 |
| 011505 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:42am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594478.9 | 511739.3 | 11013 | 1.64041666667 | 11505 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011647 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:43am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594478.6 | 511737.6 | 11015 | 1.64041666667 | 11647 |
| 011853 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:44am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594479.3 | 511735.6 | 11017 | 1.64041666667 | 11853 |
| 010095 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:45am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594479.7 | 511733.8 | 11019 | 1.64041666667 | 10095 |
| 011386 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:46am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594481.1 | 511731.8 | 11021 | 1.64041666667 | 11386 |
| 011834 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:47am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594482.2 | 511730.2 | 11023 | 1.64041666667 | 11834 |
| 012102 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:48am | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594482.8 | 511727.9 | 11025 | 1.64041666667 | 12102 |
| 011539 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:49am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594483.7 | 511726.2 | 11027 | 1.64041666667 | 11539 |
| 011748 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:50am | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594484.7 | 511724.5 | 11029 | 1.64041666667 | 11748 |
| 011896 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:51am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594485.6 | 511722.6 | 11031 | 1.64041666667 | 11896 |
| 012384 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:52am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594486.9 | 511720.6 | 11033 | 1.64041666667 | 12384 |
| 013183 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:53am | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594487.4 | 511719.5 | 11035 | 1.64041666667 | 13183 |
| 012200 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:54am | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594486.8 | 511718.0 | 11037 | 1.64041666667 | 12200 |
| 012435 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:55am | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594487.2 | 511716.6 | 11039 | 1.64041666667 | 12435 |
| 012087 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:56am | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594487.0 | 511714.6 | 11041 | 1.64041666667 | 12087 |
| 011929 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:57am | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594487.9 | 511712.6 | 11043 | 1.64041666667 | 11929 |
| 013190 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:58am | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594488.5 | 511710.3 | 11045 | 1.64041666667 | 13190 |
| 012489 | 0 | GeoXH 6000 | 08/19/2015 | 11:58:59am | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594489.2 | 511708.5 | 11047 | 1.64041666667 | 12489 |
| 012087 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:00am | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594490.8 | 511706.8 | 11049 | 1.64041666667 | 12087 |
| 012266 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:01am | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594492.1 | 511705.1 | 11051 | 1.64041666667 | 12266 |
| 012480 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:02am | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594494.2 | 511703.9 | 11053 | 1.64041666667 | 12480 |
| 012442 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:03am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594495.6 | 511702.5 | 11055 | 1.64041666667 | 12442 |
| 012369 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:04am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594496.7 | 511700.4 | 11057 | 1.64041666667 | 12369 |
| 012282 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:05am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594498.2 | 511699.1 | 11059 | 1.64041666667 | 12282 |
| 012106 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:06am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594498.8 | 511697.7 | 11061 | 1.64041666667 | 12106 |
| 011070 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:07am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594498.7 | 511696.5 | 11063 | 1.64041666667 | 11070 |
| 011619 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:08am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594497.9 | 511694.2 | 11065 | 1.64041666667 | 11619 |
| 011456 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:09am | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594496.8 | 511692.2 | 11067 | 1.64041666667 | 11456 |
| 011439 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:10am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594497.1 | 511690.0 | 11069 | 1.64041666667 | 11439 |
| 012142 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:11am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594497.1 | 511688.5 | 11071 | 1.64041666667 | 12142 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:12am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594497.3 | 511686.5 | 11073 | 1.64041666667 | 12454 |
| 011948 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:13am | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594497.8 | 511684.4 | 11075 | 1.64041666667 | 11948 |
| 012563 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:14am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594497.8 | 511682.2 | 11077 | 1.64041666667 | 12563 |
| 011927 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:15am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594497.4 | 511680.9 | 11079 | 1.64041666667 | 11927 |
| 011718 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:16am | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594495.5 | 511680.0 | 11081 | 1.64041666667 | 11718 |
| 011984 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:17am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594493.9 | 511680.2 | 11083 | 1.64041666667 | 11984 |
| 012111 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:18am | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594491.9 | 511679.5 | 11085 | 1.64041666667 | 12111 |
| 012340 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:19am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594489.7 | 511678.8 | 11087 | 1.64041666667 | 12340 |
| 011778 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:20am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594487.4 | 511678.7 | 11089 | 1.64041666667 | 11778 |
| 012145 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:21am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594485.6 | 511678.5 | 11091 | 1.64041666667 | 12145 |
| 011707 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:22am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594483.9 | 511679.2 | 11093 | 1.64041666667 | 11707 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:23am | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594483.9 | 511680.4 | 11095 | 1.64041666667 | 12045 |
| 012258 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:24am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594483.4 | 511682.3 | 11097 | 1.64041666667 | 12258 |
| 011980 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:25am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594483.1 | 511684.4 | 11099 | 1.64041666667 | 11980 |
| 011673 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:26am | Sensor | 1797-S0011-905-G-ACK | 6818.5 | 1594482.8 | 511686.8 | 11101 | 1.64041666667 | 11673 |
| 012011 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:27am | Sensor | 1797-S0011-905-G-ACK | 6818.5 | 1594482.4 | 511688.7 | 11103 | 1.64041666667 | 12011 |
| 012366 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:28am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594482.2 | 511690.9 | 11105 | 1.64041666667 | 12366 |
| 012498 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:29am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594482.2 | 511692.9 | 11107 | 1.64041666667 | 12498 |
| 011815 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:30am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594481.7 | 511695.2 | 11109 | 1.64041666667 | 11815 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012233 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:31am | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594481.8 | 511697.2 | 11111 | 1.64041666667 | 12233 |
| 012813 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:32am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594481.5 | 511699.6 | 11113 | 1.64041666667 | 12813 |
| 011932 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:33am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594481.3 | 511701.9 | 11115 | 1.64041666667 | 11932 |
| 011947 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:34am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594481.1 | 511704.3 | 11117 | 1.64041666667 | 11947 |
| 011235 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:35am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594480.6 | 511706.3 | 11119 | 1.64041666667 | 11235 |
| 011217 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:36am | Sensor | 1797-S0011-905-G-ACK | 6818.5 | 1594480.6 | 511708.7 | 11121 | 1.64041666667 | 11217 |
| 011394 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:37am | Sensor | 1797-S0011-905-G-ACK | 6818.5 | 1594479.7 | 511710.7 | 11123 | 1.64041666667 | 11394 |
| 010804 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:38am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594478.8 | 511712.6 | 11125 | 1.64041666667 | 10804 |
| 010990 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:39am | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594478.4 | 511714.7 | 11127 | 1.64041666667 | 10990 |
| 011604 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:40am | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594477.6 | 511716.8 | 11129 | 1.64041666667 | 11604 |
| 012557 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:41am | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594477.3 | 511719.0 | 11131 | 1.64041666667 | 12557 |
| 012493 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:42am | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594476.0 | 511720.9 | 11133 | 1.64041666667 | 12493 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:43am | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594474.9 | 511722.7 | 11135 | 1.64041666667 | 12960 |
| 012195 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:44am | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594474.1 | 511724.8 | 11137 | 1.64041666667 | 12195 |
| 011869 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:45am | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594473.1 | 511727.0 | 11139 | 1.64041666667 | 11869 |
| 011349 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:46am | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594472.5 | 511729.3 | 11141 | 1.64041666667 | 11349 |
| 011589 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:47am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594471.4 | 511731.2 | 11143 | 1.64041666667 | 11589 |
| 011986 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:48am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594470.1 | 511732.6 | 11145 | 1.64041666667 | 11986 |
| 011970 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:49am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594469.1 | 511734.4 | 11147 | 1.64041666667 | 11970 |
| 012388 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:50am | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594467.5 | 511736.4 | 11149 | 1.64041666667 | 12388 |
| 012915 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:51am | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594466.7 | 511738.2 | 11151 | 1.64041666667 | 12915 |
| 013430 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:52am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594465.8 | 511740.3 | 11153 | 1.64041666667 | 13430 |
| 013037 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:53am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594464.4 | 511742.2 | 11155 | 1.64041666667 | 13037 |
| 012680 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:54am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594463.6 | 511744.5 | 11157 | 1.64041666667 | 12680 |
| 012383 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:55am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594462.6 | 511746.5 | 11159 | 1.64041666667 | 12383 |
| 011990 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:56am | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594461.7 | 511748.7 | 11161 | 1.64041666667 | 11990 |
| 012197 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:57am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594460.8 | 511751.0 | 11163 | 1.64041666667 | 12197 |
| 012418 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:58am | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594460.1 | 511753.0 | 11165 | 1.64041666667 | 12418 |
| 011965 | 0 | GeoXH 6000 | 08/19/2015 | 11:59:59am | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594460.3 | 511755.1 | 11167 | 1.64041666667 | 11965 |
| 011463 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:00pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594460.0 | 511757.4 | 11169 | 1.64041666667 | 11463 |
| 011803 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:01pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594459.5 | 511759.7 | 11171 | 1.64041666667 | 11803 |
| 011964 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:02pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594459.1 | 511761.8 | 11173 | 1.64041666667 | 11964 |
| 012842 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:03pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594457.9 | 511763.8 | 11175 | 1.64041666667 | 12842 |
| 012586 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:04pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594457.3 | 511766.0 | 11177 | 1.64041666667 | 12586 |
| 012329 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:05pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594456.7 | 511767.9 | 11179 | 1.64041666667 | 12329 |
| 012388 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:06pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594455.4 | 511769.6 | 11181 | 1.64041666667 | 12388 |
| 012608 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:07pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594454.8 | 511771.9 | 11183 | 1.64041666667 | 12608 |
| 012904 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:08pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594454.0 | 511773.9 | 11185 | 1.64041666667 | 12904 |
| 012771 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:09pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594453.3 | 511776.1 | 11187 | 1.64041666667 | 12771 |
| 012629 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:10pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594452.4 | 511778.0 | 11189 | 1.64041666667 | 12629 |
| 014011 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:11pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594450.7 | 511778.9 | 11191 | 1.64041666667 | 14011 |
| 013258 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:12pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594448.9 | 511780.3 | 11193 | 1.64041666667 | 13258 |
| 012580 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:13pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594447.1 | 511781.7 | 11195 | 1.64041666667 | 12580 |
| 012731 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:14pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594445.6 | 511783.2 | 11197 | 1.64041666667 | 12731 |
| 012524 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:15pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594444.7 | 511784.9 | 11199 | 1.64041666667 | 12524 |
| 012624 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:16pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594443.3 | 511786.4 | 11201 | 1.64041666667 | 12624 |
| 012276 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:17pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594442.5 | 511788.4 | 11203 | 1.64041666667 | 12276 |
| 012320 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:18pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594441.5 | 511790.4 | 11205 | 1.64041666667 | 12320 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012555 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:19pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594441.5 | 511792.1 | 11207 | 1.64041666667 | 12555 |
| 012687 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:20pm | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594441.9 | 511793.7 | 11209 | 1.64041666667 | 12687 |
| 012611 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:21pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594440.7 | 511794.5 | 11211 | 1.64041666667 | 12611 |
| 012359 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:22pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594438.8 | 511795.3 | 11213 | 1.64041666667 | 12359 |
| 011947 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:23pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594437.0 | 511794.9 | 11215 | 1.64041666667 | 11947 |
| 012390 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:24pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594435.0 | 511795.1 | 11217 | 1.64041666667 | 12390 |
| 012182 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:25pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594432.8 | 511794.7 | 11219 | 1.64041666667 | 12182 |
| 013362 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:26pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594430.4 | 511794.3 | 11221 | 1.64041666667 | 13362 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:27pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594428.5 | 511794.1 | 11223 | 1.64041666667 | 12803 |
| 012482 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:28pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594427.1 | 511793.1 | 11225 | 1.64041666667 | 12482 |
| 011581 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:29pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594425.5 | 511792.7 | 11227 | 1.64041666667 | 11581 |
| 012326 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:30pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594425.5 | 511791.5 | 11229 | 1.64041666667 | 12326 |
| 012033 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:31pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594426.0 | 511789.9 | 11231 | 1.64041666667 | 12033 |
| 012124 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:32pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594425.8 | 511787.5 | 11233 | 1.64041666667 | 12124 |
| 012129 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:33pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594425.8 | 511785.0 | 11235 | 1.64041666667 | 12129 |
| 011540 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:34pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594425.5 | 511782.8 | 11237 | 1.64041666667 | 11540 |
| 011111 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:35pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594425.4 | 511780.7 | 11239 | 1.64041666667 | 11111 |
| 011342 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:36pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594426.4 | 511778.6 | 11241 | 1.64041666667 | 11342 |
| 012215 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:37pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594427.1 | 511776.5 | 11243 | 1.64041666667 | 12215 |
| 011716 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:38pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594427.9 | 511774.8 | 11245 | 1.64041666667 | 11716 |
| 011720 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:39pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594429.5 | 511773.1 | 11247 | 1.64041666667 | 11720 |
| 011370 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:40pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594430.4 | 511771.6 | 11249 | 1.64041666667 | 11370 |
| 011038 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:41pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594431.8 | 511770.2 | 11251 | 1.64041666667 | 11038 |
| 011196 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:42pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594433.6 | 511769.1 | 11253 | 1.64041666667 | 11196 |
| 010955 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:43pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594434.6 | 511767.4 | 11255 | 1.64041666667 | 10955 |
| 010985 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:44pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594436.2 | 511766.0 | 11257 | 1.64041666667 | 10985 |
| 010859 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:45pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594437.1 | 511764.6 | 11259 | 1.64041666667 | 10859 |
| 011545 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:46pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594437.7 | 511762.8 | 11261 | 1.64041666667 | 11545 |
| 012112 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:47pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594439.0 | 511761.1 | 11263 | 1.64041666667 | 12112 |
| 011793 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:48pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594440.2 | 511759.2 | 11265 | 1.64041666667 | 11793 |
| 011321 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:49pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594441.7 | 511757.7 | 11267 | 1.64041666667 | 11321 |
| 011280 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:50pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594443.2 | 511755.8 | 11269 | 1.64041666667 | 11280 |
| 011985 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:51pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594444.4 | 511754.4 | 11271 | 1.64041666667 | 11985 |
| 012066 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:52pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594446.1 | 511753.1 | 11273 | 1.64041666667 | 12066 |
| 011422 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:53pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594447.1 | 511751.6 | 11275 | 1.64041666667 | 11422 |
| 011315 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:54pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594448.6 | 511750.1 | 11277 | 1.64041666667 | 11315 |
| 011712 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:55pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594449.1 | 511747.8 | 11279 | 1.64041666667 | 11712 |
| 011118 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:56pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594449.4 | 511745.6 | 11281 | 1.64041666667 | 11118 |
| 011886 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:57pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594450.1 | 511743.4 | 11283 | 1.64041666667 | 11886 |
| 012356 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:58pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594450.2 | 511741.3 | 11285 | 1.64041666667 | 12356 |
| 012102 | 0 | GeoXH 6000 | 08/19/2015 | 12:00:59pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594450.8 | 511739.6 | 11287 | 1.64041666667 | 12102 |
| 012267 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:00pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594451.1 | 511737.9 | 11289 | 1.64041666667 | 12267 |
| 011820 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:01pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594451.5 | 511735.9 | 11291 | 1.64041666667 | 11820 |
| 012259 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:02pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594452.3 | 511733.7 | 11293 | 1.64041666667 | 12259 |
| 011688 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:03pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594452.3 | 511731.5 | 11295 | 1.64041666667 | 11688 |
| 012432 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:04pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594452.4 | 511729.5 | 11297 | 1.64041666667 | 12432 |
| 012010 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:05pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594452.4 | 511727.4 | 11299 | 1.64041666667 | 12010 |
| 012253 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:06pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594452.1 | 511726.4 | 11301 | 1.64041666667 | 12253 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012652 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:07pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594452.7 | 511726.0 | 11303 | 1.64041666667 | 12652 |
| 012584 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:08pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594453.3 | 511724.3 | 11305 | 1.64041666667 | 12584 |
| 012036 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:09pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594454.7 | 511722.7 | 11307 | 1.64041666667 | 12036 |
| 012920 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:10pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594455.5 | 511721.3 | 11309 | 1.64041666667 | 12920 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:11pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594456.7 | 511720.9 | 11311 | 1.64041666667 | 12742 |
| 013070 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:12pm | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594457.3 | 511719.5 | 11313 | 1.64041666667 | 13070 |
| 012842 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:13pm | Sensor | 1797-S0011-905-G-ACK | 6817.8 | 1594458.4 | 511719.1 | 11315 | 1.64041666667 | 12842 |
| 012953 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:14pm | Sensor | 1797-S0011-905-G-ACK | 6817.7 | 1594458.6 | 511719.0 | 11317 | 1.64041666667 | 12953 |
| 012985 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:15pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594457.9 | 511719.6 | 11319 | 1.64041666667 | 12985 |
| 012222 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:16pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594457.1 | 511719.3 | 11321 | 1.64041666667 | 12222 |
| 012447 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:17pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594457.3 | 511717.8 | 11323 | 1.64041666667 | 12447 |
| 012491 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:18pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594458.2 | 511715.8 | 11325 | 1.64041666667 | 12491 |
| 012419 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:19pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594459.7 | 511714.1 | 11327 | 1.64041666667 | 12419 |
| 012371 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:20pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594461.0 | 511712.4 | 11329 | 1.64041666667 | 12371 |
| 014143 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:21pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594462.4 | 511711.3 | 11331 | 1.64041666667 | 14143 |
| 013010 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:22pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594463.9 | 511709.4 | 11333 | 1.64041666667 | 13010 |
| 013273 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:23pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594465.3 | 511707.7 | 11335 | 1.64041666667 | 13273 |
| 013031 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:24pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594467.3 | 511706.1 | 11337 | 1.64041666667 | 13031 |
| 012353 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:25pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594468.8 | 511704.1 | 11339 | 1.64041666667 | 12353 |
| 011937 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:26pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594470.1 | 511702.4 | 11341 | 1.64041666667 | 11937 |
| 012024 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:27pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594470.9 | 511700.3 | 11343 | 1.64041666667 | 12024 |
| 011744 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:28pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594471.1 | 511698.1 | 11345 | 1.64041666667 | 11744 |
| 011376 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:29pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594470.9 | 511695.9 | 11347 | 1.64041666667 | 11376 |
| 012219 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:30pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594470.0 | 511693.9 | 11349 | 1.64041666667 | 12219 |
| 012243 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:31pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594469.8 | 511691.4 | 11351 | 1.64041666667 | 12243 |
| 012511 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:32pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594469.6 | 511689.1 | 11353 | 1.64041666667 | 12511 |
| 012595 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:33pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594469.4 | 511687.2 | 11355 | 1.64041666667 | 12595 |
| 013047 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:34pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594469.9 | 511684.8 | 11357 | 1.64041666667 | 13047 |
| 011741 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:35pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594469.9 | 511682.9 | 11359 | 1.64041666667 | 11741 |
| 011764 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:36pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594470.1 | 511681.8 | 11361 | 1.64041666667 | 11764 |
| 012100 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:37pm | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594469.9 | 511681.1 | 11363 | 1.64041666667 | 12100 |
| 011673 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:38pm | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594469.9 | 511680.0 | 11365 | 1.64041666667 | 11673 |
| 011329 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:39pm | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594470.0 | 511678.0 | 11367 | 1.64041666667 | 11329 |
| 011855 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:40pm | Sensor | 1797-S0011-905-G-ACK | 6820.3 | 1594469.8 | 511675.8 | 11369 | 1.64041666667 | 11855 |
| 011011 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:41pm | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594469.9 | 511674.0 | 11371 | 1.64041666667 | 11011 |
| 011278 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:42pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594469.5 | 511672.2 | 11373 | 1.64041666667 | 11278 |
| 011151 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:43pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594468.1 | 511671.4 | 11375 | 1.64041666667 | 11151 |
| 012745 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:44pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594466.2 | 511670.4 | 11377 | 1.64041666667 | 12745 |
| 012036 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:45pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594464.0 | 511669.6 | 11379 | 1.64041666667 | 12036 |
| 011503 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:46pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594462.2 | 511669.1 | 11381 | 1.64041666667 | 11503 |
| 011623 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:47pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594460.7 | 511668.3 | 11383 | 1.64041666667 | 11623 |
| 011960 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:48pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594458.7 | 511667.7 | 11385 | 1.64041666667 | 11960 |
| 011610 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:49pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594456.7 | 511668.0 | 11387 | 1.64041666667 | 11610 |
| 010639 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:50pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594455.0 | 511668.8 | 11389 | 1.64041666667 | 10639 |
| 010927 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:51pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594454.9 | 511670.6 | 11391 | 1.64041666667 | 10927 |
| 010991 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:52pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594454.1 | 511672.7 | 11393 | 1.64041666667 | 10991 |
| 011552 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:53pm | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594454.2 | 511674.5 | 11395 | 1.64041666667 | 11552 |
| 012536 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:54pm | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594454.5 | 511676.5 | 11397 | 1.64041666667 | 12536 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012384 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:55pm | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594455.9 | 511678.8 | 11399 | 1.64041666667 | 12384 |
| 011466 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:56pm | Sensor | 1797-S0011-905-G-ACK | 6820.1 | 1594457.7 | 511680.4 | 11401 | 1.64041666667 | 11466 |
| 011389 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:57pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594458.6 | 511681.9 | 11403 | 1.64041666667 | 11389 |
| 011746 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:58pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594460.0 | 511684.2 | 11405 | 1.64041666667 | 11746 |
| 012809 | 0 | GeoXH 6000 | 08/19/2015 | 12:01:59pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594461.0 | 511686.5 | 11407 | 1.64041666667 | 12809 |
| 012185 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:00pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594460.5 | 511688.8 | 11409 | 1.64041666667 | 12185 |
| 012756 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:01pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594459.6 | 511690.8 | 11411 | 1.64041666667 | 12756 |
| 012313 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:02pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594458.5 | 511692.8 | 11413 | 1.64041666667 | 12313 |
| 011171 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:03pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594457.2 | 511694.3 | 11415 | 1.64041666667 | 11171 |
| 011518 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:04pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594456.5 | 511696.4 | 11417 | 1.64041666667 | 11518 |
| 012254 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:05pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594455.4 | 511698.4 | 11419 | 1.64041666667 | 12254 |
| 011580 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:06pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594454.0 | 511700.1 | 11421 | 1.64041666667 | 11580 |
| 011119 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:07pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594453.1 | 511701.7 | 11423 | 1.64041666667 | 11119 |
| 011654 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:08pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594450.7 | 511703.3 | 11425 | 1.64041666667 | 11654 |
| 011610 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:09pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594449.2 | 511704.5 | 11427 | 1.64041666667 | 11610 |
| 011586 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:10pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594447.4 | 511706.4 | 11429 | 1.64041666667 | 11586 |
| 010822 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:11pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594445.8 | 511707.7 | 11431 | 1.64041666667 | 10822 |
| 011120 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:12pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594444.7 | 511709.5 | 11433 | 1.64041666667 | 11120 |
| 011070 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:13pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594443.3 | 511711.1 | 11435 | 1.64041666667 | 11070 |
| 010809 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:14pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594442.5 | 511713.0 | 11437 | 1.64041666667 | 10809 |
| 010610 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:15pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594442.0 | 511715.1 | 11439 | 1.64041666667 | 10610 |
| 010985 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:16pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594441.4 | 511717.4 | 11441 | 1.64041666667 | 10985 |
| 011497 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:17pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594441.9 | 511719.6 | 11443 | 1.64041666667 | 11497 |
| 011499 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:18pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594441.6 | 511721.7 | 11445 | 1.64041666667 | 11499 |
| 011208 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:19pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594441.3 | 511723.9 | 11447 | 1.64041666667 | 11208 |
| 010819 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:20pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594441.0 | 511725.9 | 11449 | 1.64041666667 | 10819 |
| 011163 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:21pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594439.6 | 511727.9 | 11451 | 1.64041666667 | 11163 |
| 011492 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:22pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594438.8 | 511729.9 | 11453 | 1.64041666667 | 11492 |
| 011159 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:23pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594438.3 | 511731.7 | 11455 | 1.64041666667 | 11159 |
| 012089 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:24pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594437.3 | 511733.4 | 11457 | 1.64041666667 | 12089 |
| 011540 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:25pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594436.8 | 511735.4 | 11459 | 1.64041666667 | 11540 |
| 010931 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:26pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594435.7 | 511737.0 | 11461 | 1.64041666667 | 10931 |
| 011391 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:27pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594435.0 | 511739.1 | 11463 | 1.64041666667 | 11391 |
| 011905 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:28pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594433.7 | 511740.5 | 11465 | 1.64041666667 | 11905 |
| 012741 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:29pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594433.3 | 511742.3 | 11467 | 1.64041666667 | 12741 |
| 011757 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:30pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594432.9 | 511744.6 | 11469 | 1.64041666667 | 11757 |
| 012216 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:31pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594432.8 | 511747.0 | 11471 | 1.64041666667 | 12216 |
| 011566 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:32pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594433.0 | 511749.4 | 11473 | 1.64041666667 | 11566 |
| 011831 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:33pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594431.8 | 511751.5 | 11475 | 1.64041666667 | 11831 |
| 011522 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:34pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594430.7 | 511753.5 | 11477 | 1.64041666667 | 11522 |
| 011469 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:35pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594429.6 | 511755.3 | 11479 | 1.64041666667 | 11469 |
| 010598 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:36pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594427.9 | 511756.6 | 11481 | 1.64041666667 | 10598 |
| 010529 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:37pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594426.9 | 511758.6 | 11483 | 1.64041666667 | 10529 |
| 010122 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:38pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594425.7 | 511760.5 | 11485 | 1.64041666667 | 10122 |
| 010194 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:39pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594424.6 | 511762.1 | 11487 | 1.64041666667 | 10194 |
| 011029 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:40pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594423.6 | 511764.0 | 11489 | 1.64041666667 | 11029 |
| 011236 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:41pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594421.7 | 511765.7 | 11491 | 1.64041666667 | 11236 |
| 011315 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:42pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594420.5 | 511767.5 | 11493 | 1.64041666667 | 11315 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011382 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:43pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594419.3 | 511769.5 | 11495 | 1.64041666667 | 11382 |
| 011045 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:44pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594417.3 | 511771.1 | 11497 | 1.64041666667 | 11045 |
| 011193 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:45pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594415.9 | 511773.1 | 11499 | 1.64041666667 | 11193 |
| 011156 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:46pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594414.6 | 511775.5 | 11501 | 1.64041666667 | 11156 |
| 010760 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:47pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594413.1 | 511777.5 | 11503 | 1.64041666667 | 10760 |
| 011055 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:48pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594412.0 | 511779.8 | 11505 | 1.64041666667 | 11055 |
| 011701 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:49pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594411.4 | 511782.0 | 11507 | 1.64041666667 | 11701 |
| 011419 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:50pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594410.4 | 511784.0 | 11509 | 1.64041666667 | 11419 |
| 011433 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:51pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594410.2 | 511786.0 | 11511 | 1.64041666667 | 11433 |
| 010961 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:52pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594409.5 | 511788.2 | 11513 | 1.64041666667 | 10961 |
| 012803 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:53pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594408.3 | 511789.4 | 11515 | 1.64041666667 | 12803 |
| 012511 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:54pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594406.7 | 511790.7 | 11517 | 1.64041666667 | 12511 |
| 012415 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:55pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594404.6 | 511790.9 | 11519 | 1.64041666667 | 12415 |
| 011558 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:56pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594402.5 | 511790.8 | 11521 | 1.64041666667 | 11558 |
| 010949 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:57pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594400.7 | 511791.0 | 11523 | 1.64041666667 | 10949 |
| 011836 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:58pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594399.0 | 511790.0 | 11525 | 1.64041666667 | 11836 |
| 011503 | 0 | GeoXH 6000 | 08/19/2015 | 12:02:59pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594397.7 | 511789.1 | 11527 | 1.64041666667 | 11503 |
| 011413 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:00pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594396.7 | 511787.5 | 11529 | 1.64041666667 | 11413 |
| 010979 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:01pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594396.1 | 511785.8 | 11531 | 1.64041666667 | 10979 |
| 010811 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:02pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594395.0 | 511783.7 | 11533 | 1.64041666667 | 10811 |
| 011348 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:03pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594395.1 | 511781.9 | 11535 | 1.64041666667 | 11348 |
| 011160 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:04pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594395.3 | 511780.3 | 11537 | 1.64041666667 | 11160 |
| 012465 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:05pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594396.4 | 511778.5 | 11539 | 1.64041666667 | 12465 |
| 012321 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:06pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594398.0 | 511777.1 | 11541 | 1.64041666667 | 12321 |
| 011768 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:07pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594399.3 | 511775.3 | 11543 | 1.64041666667 | 11768 |
| 011689 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:08pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594401.3 | 511774.0 | 11545 | 1.64041666667 | 11689 |
| 011525 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:09pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594402.9 | 511772.5 | 11547 | 1.64041666667 | 11525 |
| 011500 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:10pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594404.1 | 511770.6 | 11549 | 1.64041666667 | 11500 |
| 010849 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:11pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594405.6 | 511769.1 | 11551 | 1.64041666667 | 10849 |
| 011202 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:12pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594407.0 | 511767.6 | 11553 | 1.64041666667 | 11202 |
| 011109 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:13pm | Sensor | 1797-S0011-905-G-ACK | 6819.6 | 1594408.2 | 511765.8 | 11555 | 1.64041666667 | 11109 |
| 010891 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:14pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594410.0 | 511764.4 | 11557 | 1.64041666667 | 10891 |
| 010701 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:15pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594411.1 | 511762.5 | 11559 | 1.64041666667 | 10701 |
| 010744 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:16pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594412.2 | 511760.7 | 11561 | 1.64041666667 | 10744 |
| 010528 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:17pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594414.1 | 511759.2 | 11563 | 1.64041666667 | 10528 |
| 010955 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:18pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594415.4 | 511757.5 | 11565 | 1.64041666667 | 10955 |
| 011622 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:19pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594417.0 | 511755.9 | 11567 | 1.64041666667 | 11622 |
| 011150 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:20pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594418.7 | 511754.8 | 11569 | 1.64041666667 | 11150 |
| 011641 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:21pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594419.9 | 511753.2 | 11571 | 1.64041666667 | 11641 |
| 011048 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:22pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594421.5 | 511752.0 | 11573 | 1.64041666667 | 11048 |
| 011179 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:23pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594422.8 | 511750.6 | 11575 | 1.64041666667 | 11179 |
| 011321 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:24pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594424.0 | 511748.8 | 11577 | 1.64041666667 | 11321 |
| 012105 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:25pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594425.2 | 511747.4 | 11579 | 1.64041666667 | 12105 |
| 012029 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:26pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594425.7 | 511744.7 | 11581 | 1.64041666667 | 12029 |
| 012384 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:27pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594426.2 | 511742.5 | 11583 | 1.64041666667 | 12384 |
| 012426 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:28pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594427.3 | 511740.8 | 11585 | 1.64041666667 | 12426 |
| 012202 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:29pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594428.2 | 511739.1 | 11587 | 1.64041666667 | 12202 |
| 011888 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:30pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594429.8 | 511737.3 | 11589 | 1.64041666667 | 11888 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011877 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:31pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594431.2 | 511735.8 | 11591 | 1.64041666667 | 11877 |
| 012508 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:32pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594432.2 | 511733.8 | 11593 | 1.64041666667 | 12508 |
| 012226 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:33pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594433.7 | 511732.4 | 11595 | 1.64041666667 | 12226 |
| 011707 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:34pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594434.5 | 511730.2 | 11597 | 1.64041666667 | 11707 |
| 012045 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:35pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594434.3 | 511727.8 | 11599 | 1.64041666667 | 12045 |
| 012483 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:36pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594434.6 | 511725.5 | 11601 | 1.64041666667 | 12483 |
| 012421 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:37pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594434.5 | 511723.3 | 11603 | 1.64041666667 | 12421 |
| 011719 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:38pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594434.9 | 511721.0 | 11605 | 1.64041666667 | 11719 |
| 011340 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:39pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594434.9 | 511718.3 | 11607 | 1.64041666667 | 11340 |
| 010961 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:40pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594434.3 | 511716.5 | 11609 | 1.64041666667 | 10961 |
| 011775 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:41pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594433.9 | 511714.5 | 11611 | 1.64041666667 | 11775 |
| 011596 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:42pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594433.4 | 511712.7 | 11613 | 1.64041666667 | 11596 |
| 011255 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:43pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594433.2 | 511710.3 | 11615 | 1.64041666667 | 11255 |
| 011603 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:44pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594434.1 | 511708.1 | 11617 | 1.64041666667 | 11603 |
| 011642 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:45pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594434.3 | 511705.9 | 11619 | 1.64041666667 | 11642 |
| 011783 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:46pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594435.6 | 511703.7 | 11621 | 1.64041666667 | 11783 |
| 012208 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:47pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594436.5 | 511701.7 | 11623 | 1.64041666667 | 12208 |
| 011457 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:48pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594437.0 | 511699.7 | 11625 | 1.64041666667 | 11457 |
| 011927 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:49pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594438.5 | 511698.0 | 11627 | 1.64041666667 | 11927 |
| 012094 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:50pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594439.7 | 511696.3 | 11629 | 1.64041666667 | 12094 |
| 013110 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:51pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594441.1 | 511694.6 | 11631 | 1.64041666667 | 13110 |
| 012474 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:52pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594441.9 | 511692.8 | 11633 | 1.64041666667 | 12474 |
| 011712 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:53pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594441.5 | 511691.3 | 11635 | 1.64041666667 | 11712 |
| 011740 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:54pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594441.7 | 511690.0 | 11637 | 1.64041666667 | 11740 |
| 012019 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:55pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594441.6 | 511688.5 | 11639 | 1.64041666667 | 12019 |
| 011568 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:56pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594442.0 | 511686.7 | 11641 | 1.64041666667 | 11568 |
| 011157 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:57pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594442.2 | 511684.8 | 11643 | 1.64041666667 | 11157 |
| 010633 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:58pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594442.8 | 511683.2 | 11645 | 1.64041666667 | 10633 |
| 011193 | 0 | GeoXH 6000 | 08/19/2015 | 12:03:59pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594443.0 | 511682.8 | 11647 | 1.64041666667 | 11193 |
| 011299 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:00pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594442.8 | 511681.3 | 11649 | 1.64041666667 | 11299 |
| 011178 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:01pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594443.4 | 511680.3 | 11651 | 1.64041666667 | 11178 |
| 011237 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:02pm | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594443.6 | 511678.3 | 11653 | 1.64041666667 | 11237 |
| 010851 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:03pm | Sensor | 1797-S0011-905-G-ACK | 6820.2 | 1594444.0 | 511676.2 | 11655 | 1.64041666667 | 10851 |
| 011136 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:04pm | Sensor | 1797-S0011-905-G-ACK | 6820.5 | 1594444.1 | 511674.1 | 11657 | 1.64041666667 | 11136 |
| 011184 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:05pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594444.2 | 511671.9 | 11659 | 1.64041666667 | 11184 |
| 010963 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:06pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594444.8 | 511670.1 | 11661 | 1.64041666667 | 10963 |
| 011057 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:07pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594444.7 | 511668.3 | 11663 | 1.64041666667 | 11057 |
| 010907 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:08pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594444.8 | 511666.1 | 11665 | 1.64041666667 | 10907 |
| 011145 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:09pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594444.4 | 511664.2 | 11667 | 1.64041666667 | 11145 |
| 012119 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:10pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594444.4 | 511662.4 | 11669 | 1.64041666667 | 12119 |
| 011999 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:11pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594444.9 | 511661.0 | 11671 | 1.64041666667 | 11999 |
| 012695 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:12pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594443.8 | 511659.2 | 11673 | 1.64041666667 | 12695 |
| 012691 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:13pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594442.1 | 511658.0 | 11675 | 1.64041666667 | 12691 |
| 012493 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:14pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594439.5 | 511657.7 | 11677 | 1.64041666667 | 12493 |
| 012975 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:15pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594437.3 | 511658.2 | 11679 | 1.64041666667 | 12975 |
| 013276 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:16pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594434.9 | 511658.3 | 11681 | 1.64041666667 | 13276 |
| 013062 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:17pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594432.9 | 511658.6 | 11683 | 1.64041666667 | 13062 |
| 012432 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:18pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594431.5 | 511659.6 | 11685 | 1.64041666667 | 12432 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012663 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:19pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594430.0 | 511661.2 | 11687 | 1.64041666667 | 12663 |
| 011705 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:20pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594429.7 | 511662.7 | 11689 | 1.64041666667 | 11705 |
| 011599 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:21pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594429.3 | 511664.8 | 11691 | 1.64041666667 | 11599 |
| 011917 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:22pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594428.3 | 511667.1 | 11693 | 1.64041666667 | 11917 |
| 012118 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:23pm | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594428.0 | 511669.5 | 11695 | 1.64041666667 | 12118 |
| 012336 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:24pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594427.5 | 511671.6 | 11697 | 1.64041666667 | 12336 |
| 012774 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:25pm | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594426.8 | 511673.9 | 11699 | 1.64041666667 | 12774 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:26pm | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594427.6 | 511676.2 | 11701 | 1.64041666667 | 12405 |
| 012063 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:27pm | Sensor | 1797-S0011-905-G-ACK | 6819.9 | 1594428.1 | 511678.2 | 11703 | 1.64041666667 | 12063 |
| 011645 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:28pm | Sensor | 1797-S0011-905-G-ACK | 6819.7 | 1594429.0 | 511680.4 | 11705 | 1.64041666667 | 11645 |
| 011253 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:29pm | Sensor | 1797-S0011-905-G-ACK | 6819.5 | 1594429.7 | 511682.4 | 11707 | 1.64041666667 | 11253 |
| 011520 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:30pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594429.0 | 511684.7 | 11709 | 1.64041666667 | 11520 |
| 011827 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:31pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594428.7 | 511686.9 | 11711 | 1.64041666667 | 11827 |
| 012180 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:32pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594428.7 | 511688.8 | 11713 | 1.64041666667 | 12180 |
| 012671 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:33pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594428.5 | 511690.6 | 11715 | 1.64041666667 | 12671 |
| 013472 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:34pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594428.3 | 511692.7 | 11717 | 1.64041666667 | 13472 |
| 012866 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:35pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594427.7 | 511694.1 | 11719 | 1.64041666667 | 12866 |
| 012682 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:36pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594428.1 | 511696.2 | 11721 | 1.64041666667 | 12682 |
| 012601 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:37pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594428.4 | 511698.2 | 11723 | 1.64041666667 | 12601 |
| 011805 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:38pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594429.2 | 511700.1 | 11725 | 1.64041666667 | 11805 |
| 012123 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:39pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594428.7 | 511702.6 | 11727 | 1.64041666667 | 12123 |
| 011806 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:40pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594428.5 | 511704.7 | 11729 | 1.64041666667 | 11806 |
| 011831 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:41pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594428.3 | 511706.6 | 11731 | 1.64041666667 | 11831 |
| 012745 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:42pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594427.3 | 511708.2 | 11733 | 1.64041666667 | 12745 |
| 012201 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:43pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594426.5 | 511709.8 | 11735 | 1.64041666667 | 12201 |
| 012173 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:44pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594424.5 | 511711.5 | 11737 | 1.64041666667 | 12173 |
| 012165 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:45pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594423.0 | 511712.5 | 11739 | 1.64041666667 | 12165 |
| 012340 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:46pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594421.3 | 511713.9 | 11741 | 1.64041666667 | 12340 |
| 012333 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:47pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594419.3 | 511714.9 | 11743 | 1.64041666667 | 12333 |
| 012255 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:48pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594418.0 | 511716.6 | 11745 | 1.64041666667 | 12255 |
| 012661 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:49pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594416.4 | 511718.1 | 11747 | 1.64041666667 | 12661 |
| 011869 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:50pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594415.3 | 511720.4 | 11749 | 1.64041666667 | 11869 |
| 011596 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:51pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594414.9 | 511722.8 | 11751 | 1.64041666667 | 11596 |
| 011833 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:52pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594414.7 | 511724.8 | 11753 | 1.64041666667 | 11833 |
| 012873 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:53pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594415.3 | 511726.5 | 11755 | 1.64041666667 | 12873 |
| 012528 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:54pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594414.7 | 511728.5 | 11757 | 1.64041666667 | 12528 |
| 012125 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:55pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594413.5 | 511730.1 | 11759 | 1.64041666667 | 12125 |
| 011080 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:56pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594413.4 | 511732.3 | 11761 | 1.64041666667 | 11080 |
| 011250 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:57pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594413.5 | 511734.9 | 11763 | 1.64041666667 | 11250 |
| 011015 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:58pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594414.1 | 511736.9 | 11765 | 1.64041666667 | 11015 |
| 011184 | 0 | GeoXH 6000 | 08/19/2015 | 12:04:59pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594415.0 | 511738.8 | 11767 | 1.64041666667 | 11184 |
| 011241 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:00pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594414.5 | 511740.8 | 11769 | 1.64041666667 | 11241 |
| 011235 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:01pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594414.3 | 511742.4 | 11771 | 1.64041666667 | 11235 |
| 010962 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:02pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594413.3 | 511744.6 | 11773 | 1.64041666667 | 10962 |
| 011708 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:03pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594412.6 | 511746.9 | 11775 | 1.64041666667 | 11708 |
| 012548 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:04pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594412.0 | 511749.0 | 11777 | 1.64041666667 | 12548 |
| 011536 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:05pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594410.6 | 511751.1 | 11779 | 1.64041666667 | 11536 |
| 011514 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:06pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594409.2 | 511752.9 | 11781 | 1.64041666667 | 11514 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012401 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:07pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594408.2 | 511754.7 | 11783 | 1.64041666667 | 12401 |
| 012450 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:08pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594406.1 | 511756.6 | 11785 | 1.64041666667 | 12450 |
| 011953 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:09pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594404.3 | 511758.3 | 11787 | 1.64041666667 | 11953 |
| 011996 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:10pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594402.9 | 511760.3 | 11789 | 1.64041666667 | 11996 |
| 011248 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:11pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594401.3 | 511761.9 | 11791 | 1.64041666667 | 11248 |
| 011224 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:12pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594399.3 | 511764.2 | 11793 | 1.64041666667 | 11224 |
| 010551 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:13pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594398.2 | 511765.9 | 11795 | 1.64041666667 | 10551 |
| 010727 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:14pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594396.1 | 511767.8 | 11797 | 1.64041666667 | 10727 |
| 011381 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:15pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594395.0 | 511769.6 | 11799 | 1.64041666667 | 11381 |
| 011037 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:16pm | Sensor | 1797-S0011-905-G-ACK | 6819.3 | 1594394.0 | 511771.4 | 11801 | 1.64041666667 | 11037 |
| 011173 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:17pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594392.4 | 511772.4 | 11803 | 1.64041666667 | 11173 |
| 011437 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:18pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594390.8 | 511773.1 | 11805 | 1.64041666667 | 11437 |
| 011196 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:19pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594389.5 | 511773.5 | 11807 | 1.64041666667 | 11196 |
| 010887 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:20pm | Sensor | 1797-S0011-905-G-ACK | 6819.2 | 1594387.6 | 511772.4 | 11809 | 1.64041666667 | 10887 |
| 010999 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:21pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594386.0 | 511771.6 | 11811 | 1.64041666667 | 10999 |
| 011767 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:22pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594385.0 | 511769.9 | 11813 | 1.64041666667 | 11767 |
| 011285 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:23pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594384.7 | 511768.3 | 11815 | 1.64041666667 | 11285 |
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:24pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594384.6 | 511766.8 | 11817 | 1.64041666667 | 13451 |
| 012644 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:25pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594385.6 | 511765.5 | 11819 | 1.64041666667 | 12644 |
| 012812 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:26pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594386.0 | 511763.6 | 11821 | 1.64041666667 | 12812 |
| 012104 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:27pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594386.5 | 511761.8 | 11823 | 1.64041666667 | 12104 |
| 012906 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:28pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594387.8 | 511760.4 | 11825 | 1.64041666667 | 12906 |
| 012539 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:29pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594388.6 | 511758.9 | 11827 | 1.64041666667 | 12539 |
| 011951 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:30pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594390.4 | 511758.0 | 11829 | 1.64041666667 | 11951 |
| 012002 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:31pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594391.9 | 511756.8 | 11831 | 1.64041666667 | 12002 |
| 011723 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:32pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594393.6 | 511755.5 | 11833 | 1.64041666667 | 11723 |
| 011312 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:33pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594395.3 | 511753.8 | 11835 | 1.64041666667 | 11312 |
| 011658 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:34pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594396.6 | 511752.1 | 11837 | 1.64041666667 | 11658 |
| 011515 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:35pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594398.3 | 511751.3 | 11839 | 1.64041666667 | 11515 |
| 011622 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:36pm | Sensor | 1797-S0011-905-G-ACK | 6819.1 | 1594399.5 | 511749.6 | 11841 | 1.64041666667 | 11622 |
| 011795 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:37pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594401.1 | 511748.3 | 11843 | 1.64041666667 | 11795 |
| 012402 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:38pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594402.4 | 511747.0 | 11845 | 1.64041666667 | 12402 |
| 012076 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:39pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594403.7 | 511745.6 | 11847 | 1.64041666667 | 12076 |
| 011510 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:40pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594405.0 | 511743.5 | 11849 | 1.64041666667 | 11510 |
| 011642 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:41pm | Sensor | 1797-S0011-905-G-ACK | 6819.0 | 1594405.2 | 511741.5 | 11851 | 1.64041666667 | 11642 |
| 011573 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:42pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594405.7 | 511739.8 | 11853 | 1.64041666667 | 11573 |
| 011490 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:43pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594405.6 | 511738.7 | 11855 | 1.64041666667 | 11490 |
| 011795 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:44pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594405.1 | 511737.5 | 11857 | 1.64041666667 | 11795 |
| 012275 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:45pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594404.1 | 511735.8 | 11859 | 1.64041666667 | 12275 |
| 011719 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:46pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594402.8 | 511734.5 | 11861 | 1.64041666667 | 11719 |
| 011190 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:47pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594402.1 | 511732.6 | 11863 | 1.64041666667 | 11190 |
| 011176 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:48pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594402.0 | 511731.1 | 11865 | 1.64041666667 | 11176 |
| 011214 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:49pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594402.4 | 511729.3 | 11867 | 1.64041666667 | 11214 |
| 011700 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:50pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594403.0 | 511727.3 | 11869 | 1.64041666667 | 11700 |
| 011884 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:51pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594403.3 | 511725.3 | 11871 | 1.64041666667 | 11884 |
| 012294 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:52pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594404.0 | 511723.4 | 11873 | 1.64041666667 | 12294 |
| 012735 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:53pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594404.3 | 511721.9 | 11875 | 1.64041666667 | 12735 |
| 012496 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:54pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594405.5 | 511719.9 | 11877 | 1.64041666667 | 12496 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011821 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:55pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594405.9 | 511718.1 | 11879 | 1.64041666667 | 11821 |
| 012432 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:56pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594406.3 | 511715.6 | 11881 | 1.64041666667 | 12432 |
| 012655 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:57pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594407.0 | 511713.9 | 11883 | 1.64041666667 | 12655 |
| 012518 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:58pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594406.3 | 511711.3 | 11885 | 1.64041666667 | 12518 |
| 012246 | 0 | GeoXH 6000 | 08/19/2015 | 12:05:59pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594406.3 | 511709.7 | 11887 | 1.64041666667 | 12246 |
| 012266 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:00pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594405.8 | 511708.0 | 11889 | 1.64041666667 | 12266 |
| 013282 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:01pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594406.7 | 511706.5 | 11891 | 1.64041666667 | 13282 |
| 012653 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:02pm | Sensor | 1797-S0011-905-G-ACK | 6818.6 | 1594407.8 | 511704.2 | 11893 | 1.64041666667 | 12653 |
| 012645 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:03pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594408.4 | 511702.8 | 11895 | 1.64041666667 | 12645 |
| 012400 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:04pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594409.1 | 511701.0 | 11897 | 1.64041666667 | 12400 |
| 012465 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:05pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594410.4 | 511698.9 | 11899 | 1.64041666667 | 12465 |
| 011939 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:06pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594411.9 | 511697.3 | 11901 | 1.64041666667 | 11939 |
| 011351 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:07pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594413.1 | 511696.4 | 11903 | 1.64041666667 | 11351 |
| 011312 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:08pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594415.2 | 511695.7 | 11905 | 1.64041666667 | 11312 |
| 012010 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:09pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594416.6 | 511694.5 | 11907 | 1.64041666667 | 12010 |
| 011406 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:10pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594418.1 | 511693.1 | 11909 | 1.64041666667 | 11406 |
| 011268 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:11pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594419.5 | 511691.7 | 11911 | 1.64041666667 | 11268 |
| 011626 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:12pm | Sensor | 1797-S0011-905-G-ACK | 6818.7 | 1594420.9 | 511690.9 | 11913 | 1.64041666667 | 11626 |
| 011609 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:13pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594421.8 | 511689.1 | 11915 | 1.64041666667 | 11609 |
| 012043 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:14pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594423.7 | 511687.9 | 11917 | 1.64041666667 | 12043 |
| 012421 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:15pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594425.5 | 511686.6 | 11919 | 1.64041666667 | 12421 |
| 012567 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:16pm | Sensor | 1797-S0011-905-G-ACK | 6818.8 | 1594427.3 | 511685.2 | 11921 | 1.64041666667 | 12567 |
| 012551 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:17pm | Sensor | 1797-S0011-905-G-ACK | 6818.9 | 1594429.0 | 511683.7 | 11923 | 1.64041666667 | 12551 |
| 012565 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:18pm | Sensor | 1797-S0011-905-G-ACK | 6819.4 | 1594429.6 | 511682.4 | 11925 | 1.64041666667 | 12565 |
| 012070 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:19pm | Sensor | 1797-S0011-905-G-ACK | 6819.8 | 1594430.0 | 511680.7 | 11927 | 1.64041666667 | 12070 |
| 011574 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:20pm | Sensor | 1797-S0011-905-G-ACK | 6820.0 | 1594431.3 | 511678.2 | 11929 | 1.64041666667 | 11574 |
| 011873 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:21pm | Sensor | 1797-S0011-905-G-ACK | 6820.4 | 1594432.1 | 511676.2 | 11931 | 1.64041666667 | 11873 |
| 011906 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:22pm | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594433.2 | 511674.5 | 11933 | 1.64041666667 | 11906 |
| 012899 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:23pm | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594435.2 | 511673.0 | 11935 | 1.64041666667 | 12899 |
| 012123 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:24pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594437.1 | 511671.7 | 11937 | 1.64041666667 | 12123 |
| 011822 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:25pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594439.1 | 511670.5 | 11939 | 1.64041666667 | 11822 |
| 012462 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:26pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594441.5 | 511670.1 | 11941 | 1.64041666667 | 12462 |
| 012425 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:27pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594443.4 | 511669.6 | 11943 | 1.64041666667 | 12425 |
| 012621 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:28pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594445.4 | 511668.1 | 11945 | 1.64041666667 | 12621 |
| 012424 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:29pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594447.4 | 511667.3 | 11947 | 1.64041666667 | 12424 |
| 011496 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:30pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594450.0 | 511667.5 | 11949 | 1.64041666667 | 11496 |
| 011634 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:31pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594452.4 | 511667.6 | 11951 | 1.64041666667 | 11634 |
| 011966 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:32pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594454.9 | 511667.9 | 11953 | 1.64041666667 | 11966 |
| 013001 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:33pm | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594457.0 | 511668.6 | 11955 | 1.64041666667 | 13001 |
| 012855 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:34pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594459.9 | 511669.0 | 11957 | 1.64041666667 | 12855 |
| 012548 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:35pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594461.8 | 511668.9 | 11959 | 1.64041666667 | 12548 |
| 011986 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:36pm | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594464.7 | 511668.9 | 11961 | 1.64041666667 | 11986 |
| 012142 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:37pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594467.0 | 511668.6 | 11963 | 1.64041666667 | 12142 |
| 012207 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:38pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594469.8 | 511667.7 | 11965 | 1.64041666667 | 12207 |
| 012244 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:39pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594471.8 | 511667.1 | 11967 | 1.64041666667 | 12244 |
| 012167 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:40pm | Sensor | 1797-S0011-905-G-ACK | 6820.6 | 1594474.5 | 511666.7 | 11969 | 1.64041666667 | 12167 |
| 011606 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:41pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594476.5 | 511665.7 | 11971 | 1.64041666667 | 11606 |
| 012213 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:42pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594478.7 | 511664.8 | 11973 | 1.64041666667 | 12213 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012375 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:43pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594481.3 | 511664.4 | 11975 | 1.64041666667 | 12375 |
| 012473 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:44pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594483.6 | 511663.4 | 11977 | 1.64041666667 | 12473 |
| 012228 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:45pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594486.3 | 511662.6 | 11979 | 1.64041666667 | 12228 |
| 012938 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:46pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594489.0 | 511662.1 | 11981 | 1.64041666667 | 12938 |
| 013124 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:47pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594491.3 | 511661.1 | 11983 | 1.64041666667 | 13124 |
| 012213 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:48pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594494.1 | 511659.9 | 11985 | 1.64041666667 | 12213 |
| 012112 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:49pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594496.6 | 511659.4 | 11987 | 1.64041666667 | 12112 |
| 012378 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:50pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594499.0 | 511658.8 | 11989 | 1.64041666667 | 12378 |
| 011965 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:51pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594501.1 | 511658.1 | 11991 | 1.64041666667 | 11965 |
| 011695 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:52pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594504.2 | 511657.2 | 11993 | 1.64041666667 | 11695 |
| 012548 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:53pm | Sensor | 1797-S0011-905-G-ACK | 6820.7 | 1594506.5 | 511657.0 | 11995 | 1.64041666667 | 12548 |
| 013163 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:54pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594509.7 | 511656.5 | 11997 | 1.64041666667 | 13163 |
| 012887 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:55pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594511.8 | 511655.9 | 11999 | 1.64041666667 | 12887 |
| 012776 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:56pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594514.3 | 511655.4 | 12001 | 1.64041666667 | 12776 |
| 012609 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:57pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594517.1 | 511654.8 | 12003 | 1.64041666667 | 12609 |
| 012252 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:58pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594519.4 | 511653.5 | 12005 | 1.64041666667 | 12252 |
| 012037 | 0 | GeoXH 6000 | 08/19/2015 | 12:06:59pm | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594521.6 | 511651.9 | 12007 | 1.64041666667 | 12037 |
| 012231 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:00pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594524.6 | 511651.0 | 12009 | 1.64041666667 | 12231 |
| 011920 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:01pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594527.1 | 511650.5 | 12011 | 1.64041666667 | 11920 |
| 012405 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:02pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594529.2 | 511649.7 | 12013 | 1.64041666667 | 12405 |
| 012707 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:03pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594531.3 | 511648.6 | 12015 | 1.64041666667 | 12707 |
| 012578 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:04pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594534.1 | 511648.2 | 12017 | 1.64041666667 | 12578 |
| 011582 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:05pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594536.6 | 511647.9 | 12019 | 1.64041666667 | 11582 |
| 011690 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:06pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594539.3 | 511647.6 | 12021 | 1.64041666667 | 11690 |
| 011270 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:07pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594542.3 | 511647.6 | 12023 | 1.64041666667 | 11270 |
| 012212 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:08pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594545.4 | 511647.5 | 12025 | 1.64041666667 | 12212 |
| 012299 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:09pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594547.7 | 511646.9 | 12027 | 1.64041666667 | 12299 |
| 012131 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:10pm | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594550.8 | 511645.9 | 12029 | 1.64041666667 | 12131 |
| 012006 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:11pm | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594553.3 | 511645.6 | 12031 | 1.64041666667 | 12006 |
| 012408 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:12pm | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594556.7 | 511644.9 | 12033 | 1.64041666667 | 12408 |
| 012972 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:13pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594558.8 | 511644.3 | 12035 | 1.64041666667 | 12972 |
| 013139 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:14pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594561.6 | 511643.5 | 12037 | 1.64041666667 | 13139 |
| 013106 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:15pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594564.2 | 511642.9 | 12039 | 1.64041666667 | 13106 |
| 012209 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:16pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594567.1 | 511642.2 | 12041 | 1.64041666667 | 12209 |
| 012583 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:17pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594569.4 | 511641.1 | 12043 | 1.64041666667 | 12583 |
| 012927 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:18pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594572.1 | 511640.3 | 12045 | 1.64041666667 | 12927 |
| 012814 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:19pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594574.6 | 511639.6 | 12047 | 1.64041666667 | 12814 |
| 012945 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:20pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594578.2 | 511638.1 | 12049 | 1.64041666667 | 12945 |
| 012584 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:21pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594580.4 | 511637.2 | 12051 | 1.64041666667 | 12584 |
| 013116 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:22pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594583.8 | 511636.4 | 12053 | 1.64041666667 | 13116 |
| 013258 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:23pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594586.0 | 511636.2 | 12055 | 1.64041666667 | 13258 |
| 012467 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:24pm | Sensor | 1797-S0011-905-G-ACK | 6820.9 | 1594589.3 | 511636.1 | 12057 | 1.64041666667 | 12467 |
| 011505 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:25pm | Sensor | 1797-S0011-905-G-ACK | 6820.8 | 1594592.0 | 511635.7 | 12059 | 1.64041666667 | 11505 |
| 012127 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:26pm | Sensor | 1797-S0011-905-G-ACK | 6821.0 | 1594595.3 | 511634.9 | 12061 | 1.64041666667 | 12127 |
| 011411 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:27pm | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594597.9 | 511634.7 | 12063 | 1.64041666667 | 11411 |
| 012351 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:28pm | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594600.8 | 511634.7 | 12065 | 1.64041666667 | 12351 |
| 012310 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:29pm | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594603.2 | 511634.2 | 12067 | 1.64041666667 | 12310 |
| 012744 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:30pm | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594606.3 | 511633.2 | 12069 | 1.64041666667 | 12744 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013026 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:31pm | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594608.8 | 511632.4 | 12071 | 1.64041666667 | 13026 |
| 013455 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:32pm | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594611.5 | 511631.2 | 12073 | 1.64041666667 | 13455 |
| 014078 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:33pm | Sensor | 1797-S0011-905-G-ACK | 6821.3 | 1594613.6 | 511629.7 | 12075 | 1.64041666667 | 14078 |
| 014669 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:34pm | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594616.5 | 511627.9 | 12077 | 1.64041666667 | 14669 |
| 014603 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:35pm | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594619.1 | 511626.7 | 12079 | 1.64041666667 | 14603 |
| 013989 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:36pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594621.7 | 511625.7 | 12081 | 1.64041666667 | 13989 |
| 014559 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:37pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594624.6 | 511625.0 | 12083 | 1.64041666667 | 14559 |
| 015764 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:38pm | Sensor | 1797-S0011-905-G-ACK | 6821.7 | 1594627.6 | 511624.8 | 12085 | 1.64041666667 | 15764 |
| 014740 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:39pm | Sensor | 1797-S0011-905-G-ACK | 6821.7 | 1594630.8 | 511624.8 | 12087 | 1.64041666667 | 14740 |
| 014583 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:40pm | Sensor | 1797-S0011-905-G-ACK | 6821.8 | 1594633.7 | 511624.5 | 12089 | 1.64041666667 | 14583 |
| 014436 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:41pm | Sensor | 1797-S0011-905-G-ACK | 6821.8 | 1594636.1 | 511624.0 | 12091 | 1.64041666667 | 14436 |
| 014645 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:42pm | Sensor | 1797-S0011-905-G-ACK | 6821.9 | 1594639.6 | 511623.2 | 12093 | 1.64041666667 | 14645 |
| 014785 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:43pm | Sensor | 1797-S0011-905-G-ACK | 6821.9 | 1594641.9 | 511622.9 | 12095 | 1.64041666667 | 14785 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:44pm | Sensor | 1797-S0011-905-G-ACK | 6822.0 | 1594645.1 | 511621.9 | 12097 | 1.64041666667 | 14737 |
| 015407 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:45pm | Sensor | 1797-S0011-905-G-ACK | 6822.0 | 1594647.2 | 511620.2 | 12099 | 1.64041666667 | 15407 |
| 015228 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:46pm | Sensor | 1797-S0011-905-G-ACK | 6822.1 | 1594649.1 | 511618.2 | 12101 | 1.64041666667 | 15228 |
| 015368 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:47pm | Sensor | 1797-S0011-905-G-ACK | 6822.1 | 1594651.3 | 511616.1 | 12103 | 1.64041666667 | 15368 |
| 015672 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:48pm | Sensor | 1797-S0011-905-G-ACK | 6822.1 | 1594653.6 | 511614.3 | 12105 | 1.64041666667 | 15672 |
| 015790 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:49pm | Sensor | 1797-S0011-905-G-ACK | 6822.2 | 1594655.5 | 511612.3 | 12107 | 1.64041666667 | 15790 |
| 015144 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:50pm | Sensor | 1797-S0011-905-G-ACK | 6822.3 | 1594657.2 | 511610.2 | 12109 | 1.64041666667 | 15144 |
| 015419 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:51pm | Sensor | 1797-S0011-905-G-ACK | 6822.3 | 1594659.3 | 511608.0 | 12111 | 1.64041666667 | 15419 |
| 016300 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:52pm | Sensor | 1797-S0011-905-G-ACK | 6822.3 | 1594661.4 | 511606.0 | 12113 | 1.64041666667 | 16300 |
| 017531 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:53pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594663.2 | 511604.0 | 12115 | 1.64041666667 | 17531 |
| 018029 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:54pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594664.9 | 511601.5 | 12117 | 1.64041666667 | 18029 |
| 017731 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:55pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594666.7 | 511599.3 | 12119 | 1.64041666667 | 17731 |
| 017376 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:56pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594668.6 | 511597.3 | 12121 | 1.64041666667 | 17376 |
| 016719 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:57pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594670.1 | 511595.0 | 12123 | 1.64041666667 | 16719 |
| 017017 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:58pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594671.3 | 511592.5 | 12125 | 1.64041666667 | 17017 |
| 017282 | 0 | GeoXH 6000 | 08/19/2015 | 12:07:59pm | Sensor | 1797-S0011-905-G-ACK | 6822.7 | 1594672.7 | 511590.9 | 12127 | 1.64041666667 | 17282 |
| 018451 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:00pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594675.0 | 511589.2 | 12129 | 1.64041666667 | 18451 |
| 019401 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:01pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594677.1 | 511588.2 | 12131 | 1.64041666667 | 19401 |
| 018908 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:02pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594680.1 | 511587.0 | 12133 | 1.64041666667 | 18908 |
| 019005 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:03pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594682.4 | 511586.4 | 12135 | 1.64041666667 | 19005 |
| 017651 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:04pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594685.4 | 511585.6 | 12137 | 1.64041666667 | 17651 |
| 015763 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:05pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594687.4 | 511584.6 | 12139 | 1.64041666667 | 15763 |
| 015137 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:06pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594689.8 | 511582.7 | 12141 | 1.64041666667 | 15137 |
| 016127 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:07pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594691.5 | 511581.5 | 12143 | 1.64041666667 | 16127 |
| 015259 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:08pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594693.6 | 511580.0 | 12145 | 1.64041666667 | 15259 |
| 015108 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:09pm | Sensor | 1797-S0011-905-G-ACK | 6822.3 | 1594694.9 | 511578.2 | 12147 | 1.64041666667 | 15108 |
| 015788 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:10pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594696.9 | 511575.6 | 12149 | 1.64041666667 | 15788 |
| 014656 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:11pm | Sensor | 1797-S0011-905-G-ACK | 6822.3 | 1594698.7 | 511573.7 | 12151 | 1.64041666667 | 14656 |
| 014776 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:12pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594700.5 | 511572.0 | 12153 | 1.64041666667 | 14776 |
| 014956 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:13pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594702.1 | 511570.0 | 12155 | 1.64041666667 | 14956 |
| 014863 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:14pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594704.1 | 511567.9 | 12157 | 1.64041666667 | 14863 |
| 014773 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:15pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594706.0 | 511566.5 | 12159 | 1.64041666667 | 14773 |
| 014280 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:16pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594708.3 | 511564.1 | 12161 | 1.64041666667 | 14280 |
| 014610 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:17pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594709.9 | 511562.1 | 12163 | 1.64041666667 | 14610 |
| 014953 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:18pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594712.1 | 511559.9 | 12165 | 1.64041666667 | 14953 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014388 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:19pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594713.9 | 511558.2 | 12167 | 1.64041666667 | 14388 |
| 014131 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:20pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594715.9 | 511555.9 | 12169 | 1.64041666667 | 14131 |
| 014391 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:21pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594717.4 | 511553.9 | 12171 | 1.64041666667 | 14391 |
| 014327 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:22pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594720.0 | 511551.4 | 12173 | 1.64041666667 | 14327 |
| 014329 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:23pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594721.8 | 511550.3 | 12175 | 1.64041666667 | 14329 |
| 013670 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:24pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594724.0 | 511548.1 | 12177 | 1.64041666667 | 13670 |
| 014604 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:25pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594725.7 | 511546.1 | 12179 | 1.64041666667 | 14604 |
| 014387 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:26pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594727.7 | 511543.5 | 12181 | 1.64041666667 | 14387 |
| 014595 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:27pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594729.1 | 511541.5 | 12183 | 1.64041666667 | 14595 |
| 014705 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:28pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594730.2 | 511538.7 | 12185 | 1.64041666667 | 14705 |
| 014556 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:29pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594731.4 | 511536.2 | 12187 | 1.64041666667 | 14556 |
| 014908 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:30pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594733.4 | 511534.0 | 12189 | 1.64041666667 | 14908 |
| 015060 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:31pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594735.5 | 511531.9 | 12191 | 1.64041666667 | 15060 |
| 014929 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:32pm | Sensor | 1797-S0011-905-G-ACK | 6822.6 | 1594737.3 | 511529.6 | 12193 | 1.64041666667 | 14929 |
| 015125 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:33pm | Sensor | 1797-S0011-905-G-ACK | 6822.7 | 1594738.8 | 511527.6 | 12195 | 1.64041666667 | 15125 |
| 014290 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:34pm | Sensor | 1797-S0011-905-G-ACK | 6822.7 | 1594741.4 | 511525.4 | 12197 | 1.64041666667 | 14290 |
| 014083 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:35pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594743.3 | 511523.7 | 12199 | 1.64041666667 | 14083 |
| 014889 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:36pm | Sensor | 1797-S0011-905-G-ACK | 6822.9 | 1594745.5 | 511520.9 | 12201 | 1.64041666667 | 14889 |
| 014690 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:37pm | Sensor | 1797-S0011-905-G-ACK | 6822.9 | 1594747.2 | 511518.8 | 12203 | 1.64041666667 | 14690 |
| 014255 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:38pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594749.7 | 511517.1 | 12205 | 1.64041666667 | 14255 |
| 015429 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:39pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594752.0 | 511516.0 | 12207 | 1.64041666667 | 15429 |
| 015676 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:40pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594754.5 | 511513.7 | 12209 | 1.64041666667 | 15676 |
| 015643 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:41pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594756.1 | 511511.5 | 12211 | 1.64041666667 | 15643 |
| 015384 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:42pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594757.7 | 511508.7 | 12213 | 1.64041666667 | 15384 |
| 015546 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:43pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594759.4 | 511506.6 | 12215 | 1.64041666667 | 15546 |
| 016544 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:44pm | Sensor | 1797-S0011-905-G-ACK | 6823.1 | 1594761.6 | 511503.7 | 12217 | 1.64041666667 | 16544 |
| 015351 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:45pm | Sensor | 1797-S0011-905-G-ACK | 6823.1 | 1594762.6 | 511501.8 | 12219 | 1.64041666667 | 15351 |
| 014665 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:46pm | Sensor | 1797-S0011-905-G-ACK | 6823.2 | 1594763.6 | 511499.0 | 12221 | 1.64041666667 | 14665 |
| 014736 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:47pm | Sensor | 1797-S0011-905-G-ACK | 6823.2 | 1594765.1 | 511497.1 | 12223 | 1.64041666667 | 14736 |
| 013891 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:48pm | Sensor | 1797-S0011-905-G-ACK | 6823.4 | 1594767.4 | 511494.8 | 12225 | 1.64041666667 | 13891 |
| 014699 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:49pm | Sensor | 1797-S0011-905-G-ACK | 6823.5 | 1594769.0 | 511492.9 | 12227 | 1.64041666667 | 14699 |
| 014485 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:50pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594770.9 | 511490.6 | 12229 | 1.64041666667 | 14485 |
| 015445 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:51pm | Sensor | 1797-S0011-905-G-ACK | 6823.5 | 1594772.6 | 511488.8 | 12231 | 1.64041666667 | 15445 |
| 015025 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:52pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594774.4 | 511486.0 | 12233 | 1.64041666667 | 15025 |
| 013364 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:53pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594775.8 | 511483.7 | 12235 | 1.64041666667 | 13364 |
| 013840 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:54pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594777.9 | 511481.0 | 12237 | 1.64041666667 | 13840 |
| 014107 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:55pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594780.1 | 511479.3 | 12239 | 1.64041666667 | 14107 |
| 012945 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:56pm | Sensor | 1797-S0011-905-G-ACK | 6824.1 | 1594782.3 | 511478.4 | 12241 | 1.64041666667 | 12945 |
| 013102 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:57pm | Sensor | 1797-S0011-905-G-ACK | 6824.1 | 1594784.1 | 511477.6 | 12243 | 1.64041666667 | 13102 |
| 012627 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:58pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594787.0 | 511476.2 | 12245 | 1.64041666667 | 12627 |
| 012892 | 0 | GeoXH 6000 | 08/19/2015 | 12:08:59pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594789.6 | 511475.1 | 12247 | 1.64041666667 | 12892 |
| 013117 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:00pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594792.9 | 511473.8 | 12249 | 1.64041666667 | 13117 |
| 013131 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:01pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594795.3 | 511472.3 | 12251 | 1.64041666667 | 13131 |
| 012846 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:02pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594797.5 | 511470.5 | 12253 | 1.64041666667 | 12846 |
| 012228 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:03pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594799.6 | 511468.9 | 12255 | 1.64041666667 | 12228 |
| 012713 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:04pm | Sensor | 1797-S0011-905-G-ACK | 6823.8 | 1594801.7 | 511467.5 | 12257 | 1.64041666667 | 12713 |
| 012258 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:05pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594803.6 | 511465.6 | 12259 | 1.64041666667 | 12258 |
| 012775 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:06pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594805.0 | 511463.2 | 12261 | 1.64041666667 | 12775 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 013651 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:07pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594806.4 | 511461.2 | 12263 | 1.64041666667 | 13651 |
| 013333 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:08pm | Sensor | 1797-S0011-905-G-ACK | 6824.1 | 1594807.7 | 511458.4 | 12265 | 1.64041666667 | 13333 |
| 014287 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:09pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594808.8 | 511455.7 | 12267 | 1.64041666667 | 14287 |
| 014081 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:10pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594810.4 | 511453.5 | 12269 | 1.64041666667 | 14081 |
| 014221 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:11pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594812.3 | 511451.8 | 12271 | 1.64041666667 | 14221 |
| 014161 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:12pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594814.5 | 511449.7 | 12273 | 1.64041666667 | 14161 |
| 015240 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:13pm | Sensor | 1797-S0011-905-G-ACK | 6823.8 | 1594816.2 | 511448.0 | 12275 | 1.64041666667 | 15240 |
| 014663 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:14pm | Sensor | 1797-S0011-905-G-ACK | 6823.8 | 1594818.5 | 511445.9 | 12277 | 1.64041666667 | 14663 |
| 014053 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:15pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594820.4 | 511444.2 | 12279 | 1.64041666667 | 14053 |
| 013777 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:16pm | Sensor | 1797-S0011-905-G-ACK | 6823.8 | 1594822.3 | 511441.3 | 12281 | 1.64041666667 | 13777 |
| 014027 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:17pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594822.9 | 511439.3 | 12283 | 1.64041666667 | 14027 |
| 014310 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:18pm | Sensor | 1797-S0011-905-G-ACK | 6823.8 | 1594824.3 | 511436.2 | 12285 | 1.64041666667 | 14310 |
| 013269 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:19pm | Sensor | 1797-S0011-905-G-ACK | 6823.8 | 1594825.7 | 511433.9 | 12287 | 1.64041666667 | 13269 |
| 013764 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:20pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594827.1 | 511431.3 | 12289 | 1.64041666667 | 13764 |
| 013517 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:21pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594828.1 | 511429.1 | 12291 | 1.64041666667 | 13517 |
| 012673 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:22pm | Sensor | 1797-S0011-905-G-ACK | 6823.8 | 1594829.8 | 511425.9 | 12293 | 1.64041666667 | 12673 |
| 012468 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:23pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594831.1 | 511424.1 | 12295 | 1.64041666667 | 12468 |
| 012346 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:24pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594833.0 | 511421.6 | 12297 | 1.64041666667 | 12346 |
| 012764 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:25pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594835.1 | 511419.8 | 12299 | 1.64041666667 | 12764 |
| 012235 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:26pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594837.3 | 511417.9 | 12301 | 1.64041666667 | 12235 |
| 012709 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:27pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594839.0 | 511416.7 | 12303 | 1.64041666667 | 12709 |
| 013681 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:28pm | Sensor | 1797-S0011-905-G-ACK | 6824.2 | 1594841.7 | 511415.3 | 12305 | 1.64041666667 | 13681 |
| 013598 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:29pm | Sensor | 1797-S0011-905-G-ACK | 6824.5 | 1594843.2 | 511413.6 | 12307 | 1.64041666667 | 13598 |
| 012569 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:30pm | Sensor | 1797-S0011-905-G-ACK | 6825.0 | 1594844.5 | 511411.5 | 12309 | 1.64041666667 | 12569 |
| 013085 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:31pm | Sensor | 1797-S0011-905-G-ACK | 6825.0 | 1594845.5 | 511409.9 | 12311 | 1.64041666667 | 13085 |
| 013165 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:32pm | Sensor | 1797-S0011-905-G-ACK | 6824.8 | 1594845.8 | 511407.2 | 12313 | 1.64041666667 | 13165 |
| 012145 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:33pm | Sensor | 1797-S0011-905-G-ACK | 6824.7 | 1594845.5 | 511404.9 | 12315 | 1.64041666667 | 12145 |
| 011849 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:34pm | Sensor | 1797-S0011-905-G-ACK | 6824.5 | 1594844.7 | 511401.6 | 12317 | 1.64041666667 | 11849 |
| 012485 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:35pm | Sensor | 1797-S0011-905-G-ACK | 6824.4 | 1594843.8 | 511399.3 | 12319 | 1.64041666667 | 12485 |
| 012310 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:36pm | Sensor | 1797-S0011-905-G-ACK | 6824.3 | 1594842.4 | 511396.3 | 12321 | 1.64041666667 | 12310 |
| 013209 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:37pm | Sensor | 1797-S0011-905-G-ACK | 6824.1 | 1594841.7 | 511393.9 | 12323 | 1.64041666667 | 13209 |
| 013160 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:38pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594841.8 | 511390.7 | 12325 | 1.64041666667 | 13160 |
| 013770 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:39pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594842.3 | 511388.1 | 12327 | 1.64041666667 | 13770 |
| 013543 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:40pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594841.6 | 511385.4 | 12329 | 1.64041666667 | 13543 |
| 013768 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:41pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594840.0 | 511383.5 | 12331 | 1.64041666667 | 13768 |
| 015349 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:42pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594837.0 | 511381.3 | 12333 | 1.64041666667 | 15349 |
| 014902 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:43pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594835.1 | 511379.6 | 12335 | 1.64041666667 | 14902 |
| 014497 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:44pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594832.5 | 511377.4 | 12337 | 1.64041666667 | 14497 |
| 014079 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:45pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594830.5 | 511375.3 | 12339 | 1.64041666667 | 14079 |
| 014572 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:46pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594828.7 | 511372.8 | 12341 | 1.64041666667 | 14572 |
| 015127 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:47pm | Sensor | 1797-S0011-905-G-ACK | 6823.5 | 1594826.8 | 511370.4 | 12343 | 1.64041666667 | 15127 |
| 014943 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:48pm | Sensor | 1797-S0011-905-G-ACK | 6823.5 | 1594824.6 | 511368.2 | 12345 | 1.64041666667 | 14943 |
| 014458 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:49pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594823.1 | 511366.4 | 12347 | 1.64041666667 | 14458 |
| 013578 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:50pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594821.6 | 511363.5 | 12349 | 1.64041666667 | 13578 |
| 013112 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:51pm | Sensor | 1797-S0011-905-G-ACK | 6823.8 | 1594820.3 | 511361.2 | 12351 | 1.64041666667 | 13112 |
| 013571 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:52pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594818.7 | 511358.9 | 12353 | 1.64041666667 | 13571 |
| 012216 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:53pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594818.1 | 511357.2 | 12355 | 1.64041666667 | 12216 |
| 011589 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:54pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594818.0 | 511354.6 | 12357 | 1.64041666667 | 11589 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 011813 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:55pm | Sensor | 1797-S0011-905-G-ACK | 6823.5 | 1594817.0 | 511352.1 | 12359 | 1.64041666667 | 11813 |
| 012105 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:56pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594815.9 | 511349.0 | 12361 | 1.64041666667 | 12105 |
| 011789 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:57pm | Sensor | 1797-S0011-905-G-ACK | 6823.5 | 1594816.0 | 511346.4 | 12363 | 1.64041666667 | 11789 |
| 011664 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:58pm | Sensor | 1797-S0011-905-G-ACK | 6823.6 | 1594816.3 | 511344.0 | 12365 | 1.64041666667 | 11664 |
| 011061 | 0 | GeoXH 6000 | 08/19/2015 | 12:09:59pm | Sensor | 1797-S0011-905-G-ACK | 6823.7 | 1594817.1 | 511342.1 | 12367 | 1.64041666667 | 11061 |
| 010849 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:00pm | Sensor | 1797-S0011-905-G-ACK | 6823.9 | 1594819.4 | 511339.6 | 12369 | 1.64041666667 | 10849 |
| 011367 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:01pm | Sensor | 1797-S0011-905-G-ACK | 6824.0 | 1594820.4 | 511338.4 | 12371 | 1.64041666667 | 11367 |
| 010714 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:02pm | Sensor | 1797-S0011-905-G-ACK | 6823.3 | 1594820.8 | 511335.5 | 12373 | 1.64041666667 | 10714 |
| 011329 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:03pm | Sensor | 1797-S0011-905-G-ACK | 6822.9 | 1594821.0 | 511333.1 | 12375 | 1.64041666667 | 11329 |
| 011900 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:04pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594820.9 | 511329.9 | 12377 | 1.64041666667 | 11900 |
| 012236 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:05pm | Sensor | 1797-S0011-905-G-ACK | 6822.3 | 1594820.4 | 511327.1 | 12379 | 1.64041666667 | 12236 |
| 011795 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:06pm | Sensor | 1797-S0011-905-G-ACK | 6822.3 | 1594820.1 | 511324.0 | 12381 | 1.64041666667 | 11795 |
| 011712 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:07pm | Sensor | 1797-S0011-905-G-ACK | 6822.2 | 1594819.9 | 511321.6 | 12383 | 1.64041666667 | 11712 |
| 011928 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:08pm | Sensor | 1797-S0011-905-G-ACK | 6822.2 | 1594820.0 | 511318.4 | 12385 | 1.64041666667 | 11928 |
| 011592 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:09pm | Sensor | 1797-S0011-905-G-ACK | 6822.1 | 1594820.3 | 511315.6 | 12387 | 1.64041666667 | 11592 |
| 011560 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:10pm | Sensor | 1797-S0011-905-G-ACK | 6822.4 | 1594820.9 | 511312.6 | 12389 | 1.64041666667 | 11560 |
| 012000 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:11pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594821.1 | 511310.2 | 12391 | 1.64041666667 | 12000 |
| 012817 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:12pm | Sensor | 1797-S0011-905-G-ACK | 6822.8 | 1594821.2 | 511307.4 | 12393 | 1.64041666667 | 12817 |
| 013255 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:13pm | Sensor | 1797-S0011-905-G-ACK | 6822.5 | 1594821.6 | 511305.2 | 12395 | 1.64041666667 | 13255 |
| 012361 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:14pm | Sensor | 1797-S0011-905-G-ACK | 6821.9 | 1594822.3 | 511301.6 | 12397 | 1.64041666667 | 12361 |
| 011640 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:15pm | Sensor | 1797-S0011-905-G-ACK | 6821.9 | 1594822.8 | 511299.1 | 12399 | 1.64041666667 | 11640 |
| 011610 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:16pm | Sensor | 1797-S0011-905-G-ACK | 6821.8 | 1594822.8 | 511296.0 | 12401 | 1.64041666667 | 11610 |
| 011443 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:17pm | Sensor | 1797-S0011-905-G-ACK | 6822.0 | 1594822.5 | 511293.8 | 12403 | 1.64041666667 | 11443 |
| 011679 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:18pm | Sensor | 1797-S0011-905-G-ACK | 6822.2 | 1594822.0 | 511291.2 | 12405 | 1.64041666667 | 11679 |
| 011887 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:19pm | Sensor | 1797-S0011-905-G-ACK | 6822.2 | 1594821.0 | 511289.3 | 12407 | 1.64041666667 | 11887 |
| 011036 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:20pm | Sensor | 1797-S0011-905-G-ACK | 6821.9 | 1594819.2 | 511286.8 | 12409 | 1.64041666667 | 11036 |
| 011075 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:21pm | Sensor | 1797-S0011-905-G-ACK | 6821.8 | 1594818.8 | 511285.0 | 12411 | 1.64041666667 | 11075 |
| 011405 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:22pm | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594820.5 | 511282.1 | 12413 | 1.64041666667 | 11405 |
| 011050 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:23pm | Sensor | 1797-S0011-905-G-ACK | 6821.1 | 1594821.9 | 511279.7 | 12415 | 1.64041666667 | 11050 |
| 011458 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:24pm | Sensor | 1797-S0011-905-G-ACK | 6821.2 | 1594822.4 | 511277.2 | 12417 | 1.64041666667 | 11458 |
| 011973 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:25pm | Sensor | 1797-S0011-905-G-ACK | 6821.4 | 1594822.3 | 511275.2 | 12419 | 1.64041666667 | 11973 |
| 011459 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:26pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594822.4 | 511272.5 | 12421 | 1.64041666667 | 11459 |
| 011523 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:27pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594822.3 | 511270.2 | 12423 | 1.64041666667 | 11523 |
| 011927 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:28pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594821.3 | 511267.5 | 12425 | 1.64041666667 | 11927 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:29pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594819.9 | 511265.5 | 12427 | 1.64041666667 | 12626 |
| 012352 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:30pm | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594818.7 | 511262.3 | 12429 | 1.64041666667 | 12352 |
| 011905 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:31pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594818.4 | 511260.2 | 12431 | 1.64041666667 | 11905 |
| 012194 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:32pm | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594818.0 | 511257.5 | 12433 | 1.64041666667 | 12194 |
| 012386 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:33pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594818.0 | 511255.5 | 12435 | 1.64041666667 | 12386 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:34pm | Sensor | 1797-S0011-905-G-ACK | 6821.6 | 1594818.8 | 511253.3 | 12437 | 1.64041666667 | 12742 |
| 012987 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:35pm | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594819.1 | 511252.0 | 12439 | 1.64041666667 | 12987 |
| 013155 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:36pm | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594819.1 | 511250.8 | 12441 | 1.64041666667 | 13155 |
| 012845 | 0 | GeoXH 6000 | 08/19/2015 | 12:10:37pm | Sensor | 1797-S0011-905-G-ACK | 6821.5 | 1594819.1 | 511250.6 | 12444 | 1.64041666667 | 12845 |
| 013598 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:48am | Sensor | 1797-S0008-G-TJV.cor | 6814.5 | 1594820.3 | 510874.7 | 6664 | 1.64041666667 | 13598 |
| 014019 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:49am | Sensor | 1797-S0008-G-TJV.cor | 6814.5 | 1594820.3 | 510874.7 | 6667 | 1.64041666667 | 14019 |
| 013765 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:50am | Sensor | 1797-S0008-G-TJV.cor | 6814.5 | 1594820.2 | 510874.7 | 6669 | 1.64041666667 | 13765 |
| 014121 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:51am | Sensor | 1797-S0008-G-TJV.cor | 6814.5 | 1594820.2 | 510874.7 | 6671 | 1.64041666667 | 14121 |
| 013640 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:52am | Sensor | 1797-S0008-G-TJV.cor | 6814.5 | 1594820.2 | 510874.6 | 6673 | 1.64041666667 | 13640 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 015200 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:53am | Sensor | 1797-S0008-G-TJV.cor | 6814.5 | 1594820.2 | 510874.6 | 6675 | 1.64041666667 | 15200 |
| 015140 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:54am | Sensor | 1797-S0008-G-TJV.cor | 6814.4 | 1594820.3 | 510874.5 | 6677 | 1.64041666667 | 15140 |
| 013835 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:55am | Sensor | 1797-S0008-G-TJV.cor | 6814.4 | 1594820.4 | 510874.6 | 6679 | 1.64041666667 | 13835 |
| 013958 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:56am | Sensor | 1797-S0008-G-TJV.cor | 6814.4 | 1594820.3 | 510874.6 | 6681 | 1.64041666667 | 13958 |
| 013089 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:57am | Sensor | 1797-S0008-G-TJV.cor | 6814.4 | 1594820.3 | 510874.6 | 6683 | 1.64041666667 | 13089 |
| 014522 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:58am | Sensor | 1797-S0008-G-TJV.cor | 6814.4 | 1594820.3 | 510874.6 | 6685 | 1.64041666667 | 14522 |
| 013470 | 0 | GeoXH 6000 | 08/19/2015 | 10:20:59am | Sensor | 1797-S0008-G-TJV.cor | 6814.3 | 1594820.3 | 510874.6 | 6687 | 1.64041666667 | 13470 |
| 014137 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:00am | Sensor | 1797-S0008-G-TJV.cor | 6814.2 | 1594820.4 | 510874.5 | 6689 | 1.64041666667 | 14137 |
| 013524 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:01am | Sensor | 1797-S0008-G-TJV.cor | 6814.3 | 1594820.4 | 510874.5 | 6691 | 1.64041666667 | 13524 |
| 012201 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:02am | Sensor | 1797-S0008-G-TJV.cor | 6814.3 | 1594820.3 | 510874.5 | 6693 | 1.64041666667 | 12201 |
| 014030 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:03am | Sensor | 1797-S0008-G-TJV.cor | 6814.2 | 1594820.3 | 510874.5 | 6695 | 1.64041666667 | 14030 |
| 013737 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:04am | Sensor | 1797-S0008-G-TJV.cor | 6814.1 | 1594820.3 | 510874.5 | 6697 | 1.64041666667 | 13737 |
| 013364 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:05am | Sensor | 1797-S0008-G-TJV.cor | 6814.1 | 1594820.4 | 510874.5 | 6699 | 1.64041666667 | 13364 |
| 013511 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:06am | Sensor | 1797-S0008-G-TJV.cor | 6814.3 | 1594820.3 | 510874.5 | 6701 | 1.64041666667 | 13511 |
| 014267 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:07am | Sensor | 1797-S0008-G-TJV.cor | 6814.4 | 1594820.2 | 510874.5 | 6703 | 1.64041666667 | 14267 |
| 012566 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:08am | Sensor | 1797-S0008-G-TJV.cor | 6814.5 | 1594820.2 | 510874.5 | 6705 | 1.64041666667 | 12566 |
| 013551 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:09am | Sensor | 1797-S0008-G-TJV.cor | 6814.6 | 1594820.1 | 510874.5 | 6707 | 1.64041666667 | 13551 |
| 014398 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:10am | Sensor | 1797-S0008-G-TJV.cor | 6814.7 | 1594820.1 | 510874.6 | 6709 | 1.64041666667 | 14398 |
| 013199 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:11am | Sensor | 1797-S0008-G-TJV.cor | 6814.7 | 1594820.1 | 510874.6 | 6711 | 1.64041666667 | 13199 |
| 012300 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:12am | Sensor | 1797-S0008-G-TJV.cor | 6814.8 | 1594820.1 | 510874.6 | 6713 | 1.64041666667 | 12300 |
| 011925 | 0 | GeoXH 6000 | 08/19/2015 | 10:21:13am | Sensor | 1797-S0008-G-TJV.cor | 6814.7 | 1594820.1 | 510874.6 | 6715 | 1.64041666667 | 11925 |
| 014494 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:05am | Sensor | 1797-S0008-G-TJV.cor | 6818.0 | 1594848.3 | 510878.9 | 6720 | 1.64041666667 | 14494 |
| 013883 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:06am | Sensor | 1797-S0008-G-TJV.cor | 6818.0 | 1594849.1 | 510879.3 | 6722 | 1.64041666667 | 13883 |
| 013971 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:07am | Sensor | 1797-S0008-G-TJV.cor | 6818.1 | 1594852.3 | 510880.2 | 6724 | 1.64041666667 | 13971 |
| 013902 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:08am | Sensor | 1797-S0008-G-TJV.cor | 6818.1 | 1594855.4 | 510882.0 | 6726 | 1.64041666667 | 13902 |
| 014155 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:09am | Sensor | 1797-S0008-G-TJV.cor | 6818.2 | 1594858.3 | 510884.1 | 6728 | 1.64041666667 | 14155 |
| 014459 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:10am | Sensor | 1797-S0008-G-TJV.cor | 6818.4 | 1594861.4 | 510886.0 | 6730 | 1.64041666667 | 14459 |
| 014444 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:11am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1594865.0 | 510887.1 | 6732 | 1.64041666667 | 14444 |
| 015191 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:12am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1594868.3 | 510887.5 | 6734 | 1.64041666667 | 15191 |
| 014657 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:13am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1594872.0 | 510887.3 | 6736 | 1.64041666667 | 14657 |
| 013834 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:14am | Sensor | 1797-S0008-G-TJV.cor | 6819.0 | 1594875.6 | 510887.2 | 6738 | 1.64041666667 | 13834 |
| 014918 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:15am | Sensor | 1797-S0008-G-TJV.cor | 6819.1 | 1594879.1 | 510888.6 | 6740 | 1.64041666667 | 14918 |
| 014319 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:16am | Sensor | 1797-S0008-G-TJV.cor | 6819.2 | 1594881.6 | 510891.2 | 6742 | 1.64041666667 | 14319 |
| 014530 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:17am | Sensor | 1797-S0008-G-TJV.cor | 6819.2 | 1594884.0 | 510894.2 | 6744 | 1.64041666667 | 14530 |
| 014342 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:18am | Sensor | 1797-S0008-G-TJV.cor | 6819.3 | 1594886.5 | 510896.7 | 6746 | 1.64041666667 | 14342 |
| 013215 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:19am | Sensor | 1797-S0008-G-TJV.cor | 6819.6 | 1594889.2 | 510899.1 | 6748 | 1.64041666667 | 13215 |
| 013113 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:20am | Sensor | 1797-S0008-G-TJV.cor | 6819.9 | 1594891.4 | 510901.2 | 6750 | 1.64041666667 | 13113 |
| 014138 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:21am | Sensor | 1797-S0008-G-TJV.cor | 6820.3 | 1594894.2 | 510903.4 | 6752 | 1.64041666667 | 14138 |
| 013644 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:22am | Sensor | 1797-S0008-G-TJV.cor | 6820.5 | 1594896.7 | 510905.4 | 6754 | 1.64041666667 | 13644 |
| 014721 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:23am | Sensor | 1797-S0008-G-TJV.cor | 6820.6 | 1594898.9 | 510908.3 | 6756 | 1.64041666667 | 14721 |
| 014180 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:24am | Sensor | 1797-S0008-G-TJV.cor | 6820.6 | 1594900.4 | 510911.5 | 6758 | 1.64041666667 | 14180 |
| 014675 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:25am | Sensor | 1797-S0008-G-TJV.cor | 6820.7 | 1594901.9 | 510915.0 | 6760 | 1.64041666667 | 14675 |
| 013808 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:26am | Sensor | 1797-S0008-G-TJV.cor | 6820.8 | 1594904.2 | 510917.5 | 6762 | 1.64041666667 | 13808 |
| 014942 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:27am | Sensor | 1797-S0008-G-TJV.cor | 6820.8 | 1594907.0 | 510919.9 | 6764 | 1.64041666667 | 14942 |
| 014265 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:28am | Sensor | 1797-S0008-G-TJV.cor | 6820.9 | 1594908.8 | 510921.7 | 6766 | 1.64041666667 | 14265 |
| 014486 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:29am | Sensor | 1797-S0008-G-TJV.cor | 6821.0 | 1594909.6 | 510923.1 | 6768 | 1.64041666667 | 14486 |
| 013911 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:30am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594909.8 | 510923.3 | 6770 | 1.64041666667 | 13911 |
| 015208 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:31am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594909.8 | 510923.3 | 6772 | 1.64041666667 | 15208 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013672 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:32am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594909.9 | 510923.3 | 6774 | 1.64041666667 | 13672 |
| 016408 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:33am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594909.8 | 510923.4 | 6776 | 1.64041666667 | 16408 |
| 014662 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:34am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594909.9 | 510923.5 | 6778 | 1.64041666667 | 14662 |
| 014555 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:35am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594909.8 | 510923.5 | 6780 | 1.64041666667 | 14555 |
| 015638 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:36am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594909.7 | 510923.5 | 6782 | 1.64041666667 | 15638 |
| 015729 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:37am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594909.8 | 510923.6 | 6784 | 1.64041666667 | 15729 |
| 014282 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:38am | Sensor | 1797-S0008-G-TJV.cor | 6821.2 | 1594910.6 | 510924.1 | 6786 | 1.64041666667 | 14282 |
| 014280 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:39am | Sensor | 1797-S0008-G-TJV.cor | 6821.4 | 1594913.1 | 510926.0 | 6788 | 1.64041666667 | 14280 |
| 015600 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:40am | Sensor | 1797-S0008-G-TJV.cor | 6821.4 | 1594914.7 | 510928.1 | 6790 | 1.64041666667 | 15600 |
| 014280 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:41am | Sensor | 1797-S0008-G-TJV.cor | 6821.6 | 1594916.4 | 510930.5 | 6792 | 1.64041666667 | 14280 |
| 016020 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:42am | Sensor | 1797-S0008-G-TJV.cor | 6821.7 | 1594918.1 | 510932.1 | 6794 | 1.64041666667 | 16020 |
| 014445 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:43am | Sensor | 1797-S0008-G-TJV.cor | 6821.9 | 1594919.2 | 510933.9 | 6796 | 1.64041666667 | 14445 |
| 015161 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:44am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594919.4 | 510934.5 | 6798 | 1.64041666667 | 15161 |
| 015190 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:45am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.3 | 510934.5 | 6800 | 1.64041666667 | 15190 |
| 013757 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:46am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.3 | 510934.5 | 6802 | 1.64041666667 | 13757 |
| 014749 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:47am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.1 | 510934.5 | 6804 | 1.64041666667 | 14749 |
| 013767 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:48am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594919.0 | 510934.5 | 6806 | 1.64041666667 | 13767 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.0 | 510934.5 | 6808 | 1.64041666667 | 14602 |
| 014450 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:50am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.2 | 510934.3 | 6810 | 1.64041666667 | 14450 |
| 013392 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:51am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.3 | 510934.3 | 6812 | 1.64041666667 | 13392 |
| 014688 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:52am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.2 | 510934.4 | 6814 | 1.64041666667 | 14688 |
| 013812 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:53am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.2 | 510934.4 | 6816 | 1.64041666667 | 13812 |
| 013533 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:54am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.2 | 510934.3 | 6818 | 1.64041666667 | 13533 |
| 015143 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:55am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.2 | 510934.3 | 6820 | 1.64041666667 | 15143 |
| 014465 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:56am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.2 | 510934.3 | 6822 | 1.64041666667 | 14465 |
| 013276 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:57am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.1 | 510934.3 | 6824 | 1.64041666667 | 13276 |
| 014989 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:58am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.1 | 510934.3 | 6826 | 1.64041666667 | 14989 |
| 014277 | 0 | GeoXH 6000 | 08/19/2015 | 10:28:59am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.1 | 510934.3 | 6828 | 1.64041666667 | 14277 |
| 013739 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:00am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.1 | 510934.4 | 6830 | 1.64041666667 | 13739 |
| 013965 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:01am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.1 | 510934.4 | 6832 | 1.64041666667 | 13965 |
| 013121 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:02am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.1 | 510934.5 | 6834 | 1.64041666667 | 13121 |
| 013210 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:03am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.1 | 510934.4 | 6836 | 1.64041666667 | 13210 |
| 013712 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:04am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.5 | 510934.3 | 6838 | 1.64041666667 | 13712 |
| 013568 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:05am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594920.1 | 510935.1 | 6840 | 1.64041666667 | 13568 |
| 014582 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:06am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594920.7 | 510936.9 | 6842 | 1.64041666667 | 14582 |
| 013965 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:07am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594921.9 | 510939.5 | 6844 | 1.64041666667 | 13965 |
| 014141 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:08am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594922.8 | 510942.0 | 6846 | 1.64041666667 | 14141 |
| 013225 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:09am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594924.0 | 510944.7 | 6848 | 1.64041666667 | 13225 |
| 015576 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:10am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594925.5 | 510947.0 | 6850 | 1.64041666667 | 15576 |
| 014934 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:11am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594926.8 | 510949.8 | 6852 | 1.64041666667 | 14934 |
| 014623 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:12am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594927.2 | 510952.4 | 6854 | 1.64041666667 | 14623 |
| 013256 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:13am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594926.8 | 510954.7 | 6856 | 1.64041666667 | 13256 |
| 013664 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:14am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594925.2 | 510957.1 | 6858 | 1.64041666667 | 13664 |
| 014186 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:15am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594923.3 | 510958.9 | 6860 | 1.64041666667 | 14186 |
| 012756 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:16am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594922.2 | 510960.1 | 6862 | 1.64041666667 | 12756 |
| 014169 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:17am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594920.7 | 510961.5 | 6864 | 1.64041666667 | 14169 |
| 014072 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:18am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594919.7 | 510963.0 | 6866 | 1.64041666667 | 14072 |
| 011888 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:19am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594918.2 | 510964.8 | 6868 | 1.64041666667 | 11888 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013202 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:20am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.1 | 510966.5 | 6870 | 1.64041666667 | 13202 |
| 012690 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:21am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.9 | 510968.6 | 6872 | 1.64041666667 | 12690 |
| 013582 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:22am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.2 | 510970.1 | 6874 | 1.64041666667 | 13582 |
| 015185 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:23am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.0 | 510971.5 | 6876 | 1.64041666667 | 15185 |
| 014206 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:24am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594914.7 | 510972.1 | 6878 | 1.64041666667 | 14206 |
| 014621 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:25am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.0 | 510971.7 | 6880 | 1.64041666667 | 14621 |
| 014245 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:26am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.1 | 510971.8 | 6882 | 1.64041666667 | 14245 |
| 012951 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:27am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.0 | 510971.8 | 6884 | 1.64041666667 | 12951 |
| 012087 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:28am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.0 | 510971.8 | 6886 | 1.64041666667 | 12087 |
| 014092 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:29am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594915.0 | 510971.8 | 6888 | 1.64041666667 | 14092 |
| 014353 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:30am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594915.0 | 510971.8 | 6890 | 1.64041666667 | 14353 |
| 014238 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:31am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.2 | 510971.9 | 6892 | 1.64041666667 | 14238 |
| 012559 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:32am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.2 | 510971.9 | 6894 | 1.64041666667 | 12559 |
| 014029 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:33am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594915.1 | 510972.0 | 6896 | 1.64041666667 | 14029 |
| 013377 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:34am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594915.2 | 510972.0 | 6898 | 1.64041666667 | 13377 |
| 014234 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:35am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594915.2 | 510972.1 | 6900 | 1.64041666667 | 14234 |
| 013908 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:36am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594915.3 | 510972.2 | 6902 | 1.64041666667 | 13908 |
| 013437 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:37am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594915.0 | 510972.2 | 6904 | 1.64041666667 | 13437 |
| 013739 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:38am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.4 | 510972.0 | 6906 | 1.64041666667 | 13739 |
| 013065 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:39am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594915.7 | 510971.9 | 6908 | 1.64041666667 | 13065 |
| 014156 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:40am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594915.8 | 510972.2 | 6910 | 1.64041666667 | 14156 |
| 012899 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:41am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594916.0 | 510972.2 | 6912 | 1.64041666667 | 12899 |
| 012104 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:42am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594916.0 | 510972.4 | 6914 | 1.64041666667 | 12104 |
| 013496 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:43am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594916.0 | 510972.4 | 6916 | 1.64041666667 | 13496 |
| 014264 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:44am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594916.2 | 510971.5 | 6918 | 1.64041666667 | 14264 |
| 012836 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:45am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.2 | 510968.5 | 6920 | 1.64041666667 | 12836 |
| 014159 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:46am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594918.0 | 510967.4 | 6922 | 1.64041666667 | 14159 |
| 012599 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:47am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594918.1 | 510967.4 | 6924 | 1.64041666667 | 12599 |
| 012960 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:48am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594918.2 | 510967.4 | 6926 | 1.64041666667 | 12960 |
| 013440 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594918.1 | 510967.4 | 6928 | 1.64041666667 | 13440 |
| 014490 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:50am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594918.3 | 510967.1 | 6930 | 1.64041666667 | 14490 |
| 013732 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:51am | Sensor | 1797-S0008-G-TJV.cor | 6821.6 | 1594918.8 | 510965.8 | 6932 | 1.64041666667 | 13732 |
| 014533 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:52am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594918.9 | 510965.4 | 6934 | 1.64041666667 | 14533 |
| 014163 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:53am | Sensor | 1797-S0008-G-TJV.cor | 6821.2 | 1594918.9 | 510965.2 | 6936 | 1.64041666667 | 14163 |
| 014010 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:54am | Sensor | 1797-S0008-G-TJV.cor | 6821.2 | 1594918.9 | 510965.2 | 6938 | 1.64041666667 | 14010 |
| 012772 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:55am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594918.9 | 510965.2 | 6940 | 1.64041666667 | 12772 |
| 013153 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:56am | Sensor | 1797-S0008-G-TJV.cor | 6821.4 | 1594918.8 | 510965.6 | 6942 | 1.64041666667 | 13153 |
| 014178 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:57am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594918.6 | 510966.8 | 6944 | 1.64041666667 | 14178 |
| 013564 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:58am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594918.3 | 510967.3 | 6946 | 1.64041666667 | 13564 |
| 013831 | 0 | GeoXH 6000 | 08/19/2015 | 10:29:59am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594918.1 | 510967.5 | 6948 | 1.64041666667 | 13831 |
| 012487 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:00am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.7 | 510967.6 | 6950 | 1.64041666667 | 12487 |
| 012812 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:01am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594916.9 | 510967.4 | 6952 | 1.64041666667 | 12812 |
| 013313 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:02am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.1 | 510967.5 | 6954 | 1.64041666667 | 13313 |
| 014218 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:03am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.0 | 510967.3 | 6956 | 1.64041666667 | 14218 |
| 012254 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:04am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594916.9 | 510967.3 | 6958 | 1.64041666667 | 12254 |
| 012033 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:05am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.0 | 510967.4 | 6960 | 1.64041666667 | 12033 |
| 014318 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:06am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.2 | 510967.3 | 6962 | 1.64041666667 | 14318 |
| 012039 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:07am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.2 | 510966.8 | 6964 | 1.64041666667 | 12039 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012340 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:08am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594916.9 | 510967.2 | 6966 | 1.64041666667 | 12340 |
| 013435 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:09am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.2 | 510967.8 | 6968 | 1.64041666667 | 13435 |
| 012238 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:10am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.3 | 510967.9 | 6970 | 1.64041666667 | 12238 |
| 013499 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:11am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594917.3 | 510967.9 | 6972 | 1.64041666667 | 13499 |
| 013935 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:12am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594917.0 | 510967.6 | 6974 | 1.64041666667 | 13935 |
| 013083 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:13am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594916.7 | 510967.5 | 6976 | 1.64041666667 | 13083 |
| 013260 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:14am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594916.6 | 510967.5 | 6978 | 1.64041666667 | 13260 |
| 012615 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:15am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594916.2 | 510968.3 | 6980 | 1.64041666667 | 12615 |
| 012903 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:16am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594915.7 | 510970.2 | 6982 | 1.64041666667 | 12903 |
| 012976 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:17am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594914.8 | 510971.7 | 6984 | 1.64041666667 | 12976 |
| 014464 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:18am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594915.6 | 510972.3 | 6986 | 1.64041666667 | 14464 |
| 013306 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:19am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594917.6 | 510973.5 | 6988 | 1.64041666667 | 13306 |
| 013796 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:20am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594919.0 | 510974.6 | 6990 | 1.64041666667 | 13796 |
| 015329 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:21am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594921.5 | 510975.3 | 6992 | 1.64041666667 | 15329 |
| 013882 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:22am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594923.8 | 510975.8 | 6994 | 1.64041666667 | 13882 |
| 014960 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:23am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594926.6 | 510975.9 | 6996 | 1.64041666667 | 14960 |
| 012410 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:24am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594929.2 | 510976.0 | 6998 | 1.64041666667 | 12410 |
| 013842 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:25am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594931.6 | 510976.2 | 7000 | 1.64041666667 | 13842 |
| 014920 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:26am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594934.0 | 510976.1 | 7002 | 1.64041666667 | 14920 |
| 014860 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:27am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594936.4 | 510976.5 | 7004 | 1.64041666667 | 14860 |
| 013225 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:28am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594938.5 | 510976.6 | 7006 | 1.64041666667 | 13225 |
| 014616 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:29am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594941.1 | 510977.3 | 7008 | 1.64041666667 | 14616 |
| 013824 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:30am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594943.7 | 510977.8 | 7010 | 1.64041666667 | 13824 |
| 014406 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:31am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594946.0 | 510979.0 | 7012 | 1.64041666667 | 14406 |
| 012781 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:32am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594948.4 | 510980.1 | 7014 | 1.64041666667 | 12781 |
| 014085 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:33am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594950.8 | 510981.7 | 7016 | 1.64041666667 | 14085 |
| 012281 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:34am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594952.8 | 510982.8 | 7018 | 1.64041666667 | 12281 |
| 012760 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:35am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594954.9 | 510984.1 | 7020 | 1.64041666667 | 12760 |
| 013120 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:36am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594957.3 | 510985.8 | 7022 | 1.64041666667 | 13120 |
| 013900 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:37am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594960.0 | 510987.0 | 7024 | 1.64041666667 | 13900 |
| 012205 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:38am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594962.4 | 510988.2 | 7026 | 1.64041666667 | 12205 |
| 014451 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:39am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594965.1 | 510989.0 | 7028 | 1.64041666667 | 14451 |
| 015012 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:40am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594966.9 | 510990.0 | 7030 | 1.64041666667 | 15012 |
| 013743 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:41am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594969.4 | 510990.8 | 7032 | 1.64041666667 | 13743 |
| 014295 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:42am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594971.5 | 510991.8 | 7034 | 1.64041666667 | 14295 |
| 014433 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:43am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594974.1 | 510993.0 | 7036 | 1.64041666667 | 14433 |
| 014168 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:44am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594975.9 | 510994.2 | 7038 | 1.64041666667 | 14168 |
| 015182 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:45am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594978.0 | 510995.4 | 7040 | 1.64041666667 | 15182 |
| 014385 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1594979.8 | 510996.1 | 7042 | 1.64041666667 | 14385 |
| 014336 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1594981.7 | 510996.8 | 7044 | 1.64041666667 | 14336 |
| 013964 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594983.3 | 510997.7 | 7046 | 1.64041666667 | 13964 |
| 012941 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:49am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594985.1 | 510999.4 | 7048 | 1.64041666667 | 12941 |
| 013195 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:50am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594986.5 | 511000.7 | 7050 | 1.64041666667 | 13195 |
| 014008 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:51am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594988.3 | 511002.3 | 7052 | 1.64041666667 | 14008 |
| 015832 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594990.5 | 511003.7 | 7054 | 1.64041666667 | 15832 |
| 013048 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:53am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594992.9 | 511005.4 | 7056 | 1.64041666667 | 13048 |
| 014392 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:54am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594994.9 | 511006.6 | 7058 | 1.64041666667 | 14392 |
| 014158 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:55am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594996.8 | 511008.4 | 7060 | 1.64041666667 | 14158 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013799 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:56am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594998.3 | 511009.8 | 7062 | 1.64041666667 | 13799 |
| 013290 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594999.9 | 511011.2 | 7064 | 1.64041666667 | 13290 |
| 014632 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595002.3 | 511012.1 | 7066 | 1.64041666667 | 14632 |
| 013318 | 0 | GeoXH 6000 | 08/19/2015 | 10:30:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595004.5 | 511013.3 | 7068 | 1.64041666667 | 13318 |
| 014459 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595007.0 | 511014.2 | 7070 | 1.64041666667 | 14459 |
| 015735 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595009.0 | 511015.7 | 7072 | 1.64041666667 | 15735 |
| 014733 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:02am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595011.4 | 511016.8 | 7074 | 1.64041666667 | 14733 |
| 013343 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595013.6 | 511018.5 | 7076 | 1.64041666667 | 13343 |
| 015125 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595015.8 | 511019.7 | 7078 | 1.64041666667 | 15125 |
| 014641 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595018.0 | 511021.6 | 7080 | 1.64041666667 | 14641 |
| 013650 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595020.2 | 511022.8 | 7082 | 1.64041666667 | 13650 |
| 013162 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595022.4 | 511024.3 | 7084 | 1.64041666667 | 13162 |
| 013040 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:08am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595024.2 | 511025.4 | 7086 | 1.64041666667 | 13040 |
| 014390 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:09am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595025.7 | 511026.6 | 7088 | 1.64041666667 | 14390 |
| 014757 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:10am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595027.5 | 511028.2 | 7090 | 1.64041666667 | 14757 |
| 014039 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:11am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595029.3 | 511029.8 | 7092 | 1.64041666667 | 14039 |
| 014490 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:12am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595030.5 | 511031.4 | 7094 | 1.64041666667 | 14490 |
| 013342 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:13am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595031.3 | 511032.1 | 7096 | 1.64041666667 | 13342 |
| 012251 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:14am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595032.1 | 511032.1 | 7098 | 1.64041666667 | 12251 |
| 016036 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:15am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595032.3 | 511032.3 | 7100 | 1.64041666667 | 16036 |
| 013939 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:16am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595032.2 | 511031.9 | 7102 | 1.64041666667 | 13939 |
| 012634 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:17am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595032.2 | 511031.2 | 7104 | 1.64041666667 | 12634 |
| 015128 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:18am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595032.9 | 511030.4 | 7106 | 1.64041666667 | 15128 |
| 013472 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:19am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595034.8 | 511028.5 | 7108 | 1.64041666667 | 13472 |
| 013418 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595036.0 | 511027.6 | 7110 | 1.64041666667 | 13418 |
| 014214 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595036.1 | 511027.7 | 7112 | 1.64041666667 | 14214 |
| 014893 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595036.5 | 511027.2 | 7114 | 1.64041666667 | 14893 |
| 014523 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595038.2 | 511025.2 | 7116 | 1.64041666667 | 14523 |
| 013470 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:24am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595040.3 | 511024.2 | 7118 | 1.64041666667 | 13470 |
| 014227 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:25am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595040.4 | 511024.1 | 7120 | 1.64041666667 | 14227 |
| 013577 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:26am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595040.3 | 511024.0 | 7122 | 1.64041666667 | 13577 |
| 013234 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595040.2 | 511023.9 | 7124 | 1.64041666667 | 13234 |
| 014918 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595040.1 | 511023.8 | 7126 | 1.64041666667 | 14918 |
| 014889 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595040.2 | 511023.7 | 7128 | 1.64041666667 | 14889 |
| 014282 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:30am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595040.6 | 511023.4 | 7130 | 1.64041666667 | 14282 |
| 014190 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595040.6 | 511023.0 | 7132 | 1.64041666667 | 14190 |
| 013537 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:32am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595039.4 | 511023.2 | 7134 | 1.64041666667 | 13537 |
| 013854 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:33am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595040.1 | 511022.9 | 7136 | 1.64041666667 | 13854 |
| 013543 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:34am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595041.3 | 511021.9 | 7138 | 1.64041666667 | 13543 |
| 012836 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:35am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595041.2 | 511021.7 | 7140 | 1.64041666667 | 12836 |
| 013559 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:36am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595040.0 | 511022.4 | 7142 | 1.64041666667 | 13559 |
| 013019 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595039.8 | 511023.0 | 7144 | 1.64041666667 | 13019 |
| 012915 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595040.4 | 511023.6 | 7146 | 1.64041666667 | 12915 |
| 012768 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595040.8 | 511023.7 | 7148 | 1.64041666667 | 12768 |
| 012402 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595040.9 | 511023.5 | 7150 | 1.64041666667 | 12402 |
| 013360 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595040.9 | 511023.4 | 7152 | 1.64041666667 | 13360 |
| 013660 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595040.3 | 511023.9 | 7154 | 1.64041666667 | 13660 |
| 014455 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595038.5 | 511025.7 | 7156 | 1.64041666667 | 14455 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014743 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:44am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595037.1 | 511026.6 | 7158 | 1.64041666667 | 14743 |
| 012866 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595036.2 | 511027.7 | 7160 | 1.64041666667 | 12866 |
| 013776 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595036.2 | 511027.5 | 7162 | 1.64041666667 | 13776 |
| 014274 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595036.2 | 511027.8 | 7164 | 1.64041666667 | 14274 |
| 013078 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:48am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595035.8 | 511027.7 | 7166 | 1.64041666667 | 13078 |
| 012959 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:49am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595034.5 | 511026.8 | 7168 | 1.64041666667 | 12959 |
| 012630 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:50am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595033.1 | 511025.8 | 7170 | 1.64041666667 | 12630 |
| 014827 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:51am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595031.5 | 511023.8 | 7172 | 1.64041666667 | 14827 |
| 015136 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:52am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595030.0 | 511022.0 | 7174 | 1.64041666667 | 15136 |
| 013684 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595028.7 | 511019.9 | 7176 | 1.64041666667 | 13684 |
| 014581 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:54am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595026.9 | 511018.5 | 7178 | 1.64041666667 | 14581 |
| 015675 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:55am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595025.2 | 511017.0 | 7180 | 1.64041666667 | 15675 |
| 015378 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:56am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595023.0 | 511016.6 | 7182 | 1.64041666667 | 15378 |
| 014824 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595021.0 | 511015.5 | 7184 | 1.64041666667 | 14824 |
| 013936 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595018.7 | 511014.8 | 7186 | 1.64041666667 | 13936 |
| 013024 | 0 | GeoXH 6000 | 08/19/2015 | 10:31:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595016.8 | 511013.3 | 7188 | 1.64041666667 | 13024 |
| 015136 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595014.9 | 511012.2 | 7190 | 1.64041666667 | 15136 |
| 014884 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595013.9 | 511010.5 | 7192 | 1.64041666667 | 14884 |
| 014611 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:02am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595012.4 | 511009.3 | 7194 | 1.64041666667 | 14611 |
| 014842 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595011.6 | 511007.4 | 7196 | 1.64041666667 | 14842 |
| 014840 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595010.5 | 511005.9 | 7198 | 1.64041666667 | 14840 |
| 015110 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595009.6 | 511003.9 | 7200 | 1.64041666667 | 15110 |
| 015927 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595007.7 | 511002.7 | 7202 | 1.64041666667 | 15927 |
| 016222 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595006.5 | 511000.9 | 7204 | 1.64041666667 | 16222 |
| 017255 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595004.8 | 510999.3 | 7206 | 1.64041666667 | 17255 |
| 014843 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595003.7 | 510997.5 | 7208 | 1.64041666667 | 14843 |
| 013971 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595002.3 | 510995.8 | 7210 | 1.64041666667 | 13971 |
| 014142 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595001.3 | 510993.9 | 7212 | 1.64041666667 | 14142 |
| 015385 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:12am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595000.0 | 510992.1 | 7214 | 1.64041666667 | 15385 |
| 014496 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594999.0 | 510990.4 | 7216 | 1.64041666667 | 14496 |
| 014364 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594997.7 | 510988.7 | 7218 | 1.64041666667 | 14364 |
| 014181 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594996.7 | 510986.7 | 7220 | 1.64041666667 | 14181 |
| 014735 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594996.0 | 510985.6 | 7222 | 1.64041666667 | 14735 |
| 014063 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:17am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594995.3 | 510985.2 | 7224 | 1.64041666667 | 14063 |
| 014556 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:18am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594993.2 | 510984.5 | 7226 | 1.64041666667 | 14556 |
| 014049 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:19am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594991.6 | 510983.8 | 7228 | 1.64041666667 | 14049 |
| 014222 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1594989.2 | 510983.1 | 7230 | 1.64041666667 | 14222 |
| 014595 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1594988.3 | 510982.6 | 7232 | 1.64041666667 | 14595 |
| 013158 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1594987.4 | 510982.7 | 7234 | 1.64041666667 | 13158 |
| 011749 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1594987.2 | 510982.7 | 7236 | 1.64041666667 | 11749 |
| 012717 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:24am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1594987.5 | 510982.5 | 7238 | 1.64041666667 | 12717 |
| 013049 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:25am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1594987.5 | 510982.6 | 7240 | 1.64041666667 | 13049 |
| 012862 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:26am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1594987.2 | 510982.6 | 7242 | 1.64041666667 | 12862 |
| 013925 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1594986.2 | 510982.5 | 7244 | 1.64041666667 | 13925 |
| 011971 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1594984.5 | 510982.8 | 7246 | 1.64041666667 | 11971 |
| 013972 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:29am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594982.5 | 510982.8 | 7248 | 1.64041666667 | 13972 |
| 015343 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:30am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594979.8 | 510983.1 | 7250 | 1.64041666667 | 15343 |
| 014366 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:31am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594977.4 | 510982.6 | 7252 | 1.64041666667 | 14366 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014841 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:32am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594975.0 | 510982.7 | 7254 | 1.64041666667 | 14841 |
| 013370 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:33am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594972.9 | 510982.2 | 7256 | 1.64041666667 | 13370 |
| 013902 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:34am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594970.3 | 510982.3 | 7258 | 1.64041666667 | 13902 |
| 014125 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:35am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594968.4 | 510981.7 | 7260 | 1.64041666667 | 14125 |
| 013941 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:36am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594967.2 | 510981.4 | 7262 | 1.64041666667 | 13941 |
| 012695 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:37am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594966.8 | 510981.2 | 7264 | 1.64041666667 | 12695 |
| 012293 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:38am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594966.7 | 510982.2 | 7266 | 1.64041666667 | 12293 |
| 013363 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:39am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594965.0 | 510983.3 | 7268 | 1.64041666667 | 13363 |
| 012971 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:40am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594963.1 | 510984.5 | 7270 | 1.64041666667 | 12971 |
| 014012 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:41am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594961.3 | 510985.1 | 7272 | 1.64041666667 | 14012 |
| 014423 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:42am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594959.4 | 510986.3 | 7274 | 1.64041666667 | 14423 |
| 014045 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:43am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594957.4 | 510986.1 | 7276 | 1.64041666667 | 14045 |
| 013711 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:44am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594954.9 | 510985.8 | 7278 | 1.64041666667 | 13711 |
| 015247 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:45am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594952.4 | 510984.4 | 7280 | 1.64041666667 | 15247 |
| 013262 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:46am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594950.0 | 510983.3 | 7282 | 1.64041666667 | 13262 |
| 013305 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:47am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594947.9 | 510982.1 | 7284 | 1.64041666667 | 13305 |
| 012656 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:48am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594945.9 | 510980.6 | 7286 | 1.64041666667 | 12656 |
| 015044 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594943.9 | 510978.9 | 7288 | 1.64041666667 | 15044 |
| 014171 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:50am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594941.7 | 510977.1 | 7290 | 1.64041666667 | 14171 |
| 014102 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:51am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594938.9 | 510976.0 | 7292 | 1.64041666667 | 14102 |
| 013845 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:52am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594936.9 | 510974.4 | 7294 | 1.64041666667 | 13845 |
| 015161 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:53am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594934.1 | 510973.3 | 7296 | 1.64041666667 | 15161 |
| 014350 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:54am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594931.9 | 510971.9 | 7298 | 1.64041666667 | 14350 |
| 015077 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:55am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594929.4 | 510971.0 | 7300 | 1.64041666667 | 15077 |
| 013699 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:56am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594927.4 | 510969.7 | 7302 | 1.64041666667 | 13699 |
| 014464 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:57am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594924.8 | 510968.8 | 7304 | 1.64041666667 | 14464 |
| 013066 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:58am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594922.8 | 510967.4 | 7306 | 1.64041666667 | 13066 |
| 012926 | 0 | GeoXH 6000 | 08/19/2015 | 10:32:59am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594920.7 | 510966.5 | 7308 | 1.64041666667 | 12926 |
| 013911 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:00am | Sensor | 1797-S0008-G-TJV.cor | 6821.8 | 1594919.1 | 510965.8 | 7310 | 1.64041666667 | 13911 |
| 013528 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:01am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.2 | 510966.2 | 7312 | 1.64041666667 | 13528 |
| 013522 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:02am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594919.5 | 510966.8 | 7314 | 1.64041666667 | 13522 |
| 011330 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:03am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594919.5 | 510966.9 | 7316 | 1.64041666667 | 11330 |
| 011772 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:04am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.5 | 510967.1 | 7318 | 1.64041666667 | 11772 |
| 013683 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:05am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.5 | 510967.0 | 7320 | 1.64041666667 | 13683 |
| 013020 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:06am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.5 | 510967.0 | 7322 | 1.64041666667 | 13020 |
| 013095 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:07am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.5 | 510967.1 | 7324 | 1.64041666667 | 13095 |
| 012273 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:08am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.5 | 510967.0 | 7326 | 1.64041666667 | 12273 |
| 014558 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:09am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594919.4 | 510966.8 | 7328 | 1.64041666667 | 14558 |
| 013119 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:10am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594919.1 | 510966.1 | 7330 | 1.64041666667 | 13119 |
| 011500 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:11am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594919.2 | 510965.0 | 7332 | 1.64041666667 | 11500 |
| 012745 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:12am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594920.5 | 510962.7 | 7334 | 1.64041666667 | 12745 |
| 012906 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:13am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594921.1 | 510961.4 | 7336 | 1.64041666667 | 12906 |
| 013876 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:14am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594921.3 | 510961.5 | 7338 | 1.64041666667 | 13876 |
| 013099 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:15am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594921.4 | 510961.2 | 7340 | 1.64041666667 | 13099 |
| 012664 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:16am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594921.6 | 510959.9 | 7342 | 1.64041666667 | 12664 |
| 012646 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:17am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594923.0 | 510957.6 | 7344 | 1.64041666667 | 12646 |
| 013151 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:18am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594923.4 | 510955.5 | 7346 | 1.64041666667 | 13151 |
| 014508 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:19am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594923.6 | 510955.5 | 7348 | 1.64041666667 | 14508 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 015117 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:20am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594923.8 | 510955.5 | 7350 | 1.64041666667 | 15117 |
| 014369 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:21am | Sensor | 1797-S0008-G-TJV.cor | 6821.7 | 1594925.3 | 510954.9 | 7352 | 1.64041666667 | 14369 |
| 012832 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:22am | Sensor | 1797-S0008-G-TJV.cor | 6821.5 | 1594925.6 | 510954.8 | 7354 | 1.64041666667 | 12832 |
| 012628 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:23am | Sensor | 1797-S0008-G-TJV.cor | 6821.4 | 1594925.6 | 510954.8 | 7356 | 1.64041666667 | 12628 |
| 012727 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:24am | Sensor | 1797-S0008-G-TJV.cor | 6821.3 | 1594925.7 | 510954.7 | 7358 | 1.64041666667 | 12727 |
| 014581 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:25am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594925.9 | 510954.5 | 7360 | 1.64041666667 | 14581 |
| 014685 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:26am | Sensor | 1797-S0008-G-TJV.cor | 6821.1 | 1594925.9 | 510954.5 | 7362 | 1.64041666667 | 14685 |
| 012461 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:27am | Sensor | 1797-S0008-G-TJV.cor | 6820.7 | 1594926.0 | 510954.4 | 7364 | 1.64041666667 | 12461 |
| 011485 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:28am | Sensor | 1797-S0008-G-TJV.cor | 6820.6 | 1594926.1 | 510954.4 | 7366 | 1.64041666667 | 11485 |
| 012681 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:29am | Sensor | 1797-S0008-G-TJV.cor | 6820.3 | 1594926.1 | 510954.3 | 7368 | 1.64041666667 | 12681 |
| 013370 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:30am | Sensor | 1797-S0008-G-TJV.cor | 6820.5 | 1594926.0 | 510954.4 | 7370 | 1.64041666667 | 13370 |
| 011922 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:31am | Sensor | 1797-S0008-G-TJV.cor | 6821.2 | 1594925.6 | 510954.7 | 7372 | 1.64041666667 | 11922 |
| 012490 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:32am | Sensor | 1797-S0008-G-TJV.cor | 6821.6 | 1594925.2 | 510954.9 | 7374 | 1.64041666667 | 12490 |
| 015032 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:33am | Sensor | 1797-S0008-G-TJV.cor | 6821.6 | 1594925.0 | 510955.1 | 7376 | 1.64041666667 | 15032 |
| 012638 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:34am | Sensor | 1797-S0008-G-TJV.cor | 6821.5 | 1594925.2 | 510955.1 | 7378 | 1.64041666667 | 12638 |
| 013299 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:35am | Sensor | 1797-S0008-G-TJV.cor | 6820.7 | 1594925.9 | 510954.8 | 7380 | 1.64041666667 | 13299 |
| 012475 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:36am | Sensor | 1797-S0008-G-TJV.cor | 6820.0 | 1594926.3 | 510954.6 | 7382 | 1.64041666667 | 12475 |
| 012448 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:37am | Sensor | 1797-S0008-G-TJV.cor | 6820.4 | 1594926.2 | 510954.6 | 7384 | 1.64041666667 | 12448 |
| 012742 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:38am | Sensor | 1797-S0008-G-TJV.cor | 6821.8 | 1594925.3 | 510955.0 | 7386 | 1.64041666667 | 12742 |
| 014225 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:39am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594923.2 | 510955.5 | 7388 | 1.64041666667 | 14225 |
| 013036 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:40am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594922.7 | 510955.4 | 7390 | 1.64041666667 | 13036 |
| 014779 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:41am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594922.5 | 510955.9 | 7392 | 1.64041666667 | 14779 |
| 013774 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:42am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594922.4 | 510956.1 | 7394 | 1.64041666667 | 13774 |
| 012743 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:43am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594922.2 | 510956.7 | 7396 | 1.64041666667 | 12743 |
| 014886 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:44am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594921.4 | 510957.6 | 7398 | 1.64041666667 | 14886 |
| 013621 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:45am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594921.9 | 510960.1 | 7400 | 1.64041666667 | 13621 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:46am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594923.5 | 510962.1 | 7402 | 1.64041666667 | 14355 |
| 013878 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:47am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594926.3 | 510963.4 | 7404 | 1.64041666667 | 13878 |
| 015169 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:48am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594928.2 | 510964.7 | 7406 | 1.64041666667 | 15169 |
| 015402 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594930.9 | 510966.0 | 7408 | 1.64041666667 | 15402 |
| 014980 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:50am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594933.0 | 510967.5 | 7410 | 1.64041666667 | 14980 |
| 014725 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:51am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594935.2 | 510968.9 | 7412 | 1.64041666667 | 14725 |
| 015501 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:52am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594937.2 | 510970.1 | 7414 | 1.64041666667 | 15501 |
| 013535 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:53am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594939.9 | 510971.6 | 7416 | 1.64041666667 | 13535 |
| 013973 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:54am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594942.1 | 510972.7 | 7418 | 1.64041666667 | 13973 |
| 013093 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:55am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594944.5 | 510973.8 | 7420 | 1.64041666667 | 13093 |
| 013263 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:56am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594946.5 | 510974.5 | 7422 | 1.64041666667 | 13263 |
| 014175 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:57am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594949.5 | 510976.4 | 7424 | 1.64041666667 | 14175 |
| 012063 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:58am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594951.9 | 510977.5 | 7426 | 1.64041666667 | 12063 |
| 014116 | 0 | GeoXH 6000 | 08/19/2015 | 10:33:59am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594954.2 | 510979.0 | 7428 | 1.64041666667 | 14116 |
| 014809 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594956.1 | 510979.1 | 7430 | 1.64041666667 | 14809 |
| 014712 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594958.0 | 510980.7 | 7432 | 1.64041666667 | 14712 |
| 014448 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:02am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594960.2 | 510982.0 | 7434 | 1.64041666667 | 14448 |
| 014292 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594962.2 | 510983.9 | 7436 | 1.64041666667 | 14292 |
| 013533 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:04am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594964.3 | 510984.8 | 7438 | 1.64041666667 | 13533 |
| 013073 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:05am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594966.9 | 510986.5 | 7440 | 1.64041666667 | 13073 |
| 014458 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594969.2 | 510987.3 | 7442 | 1.64041666667 | 14458 |
| 014564 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594971.2 | 510989.0 | 7444 | 1.64041666667 | 14564 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594973.2 | 510990.3 | 7446 | 1.64041666667 | 13451 |
| 013382 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594975.2 | 510991.8 | 7448 | 1.64041666667 | 13382 |
| 013845 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594977.1 | 510992.5 | 7450 | 1.64041666667 | 13845 |
| 012551 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1594979.4 | 510993.7 | 7452 | 1.64041666667 | 12551 |
| 013128 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:12am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1594981.5 | 510994.4 | 7454 | 1.64041666667 | 13128 |
| 015012 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594984.0 | 510995.4 | 7456 | 1.64041666667 | 15012 |
| 014223 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594986.1 | 510996.4 | 7458 | 1.64041666667 | 14223 |
| 012855 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594988.5 | 510997.6 | 7460 | 1.64041666667 | 12855 |
| 013503 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594990.8 | 510998.8 | 7462 | 1.64041666667 | 13503 |
| 013996 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:17am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594993.1 | 511000.6 | 7464 | 1.64041666667 | 13996 |
| 015139 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:18am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594995.4 | 511002.2 | 7466 | 1.64041666667 | 15139 |
| 016654 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:19am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594997.9 | 511003.4 | 7468 | 1.64041666667 | 16654 |
| 015173 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:20am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595000.0 | 511004.2 | 7470 | 1.64041666667 | 15173 |
| 014563 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:21am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595003.0 | 511004.9 | 7472 | 1.64041666667 | 14563 |
| 013841 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:22am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595005.3 | 511006.2 | 7474 | 1.64041666667 | 13841 |
| 013360 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:23am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595008.0 | 511007.3 | 7476 | 1.64041666667 | 13360 |
| 012820 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:24am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595009.8 | 511008.6 | 7478 | 1.64041666667 | 12820 |
| 016315 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:25am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595012.4 | 511009.9 | 7480 | 1.64041666667 | 16315 |
| 014068 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:26am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595014.2 | 511011.6 | 7482 | 1.64041666667 | 14068 |
| 014017 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595016.8 | 511013.3 | 7484 | 1.64041666667 | 14017 |
| 014004 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:28am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595018.8 | 511014.6 | 7486 | 1.64041666667 | 14004 |
| 012831 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595021.8 | 511014.5 | 7488 | 1.64041666667 | 12831 |
| 013737 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:30am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595023.5 | 511014.9 | 7490 | 1.64041666667 | 13737 |
| 013574 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595026.3 | 511015.2 | 7492 | 1.64041666667 | 13574 |
| 015213 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595028.3 | 511016.1 | 7494 | 1.64041666667 | 15213 |
| 014273 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:33am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595031.0 | 511017.3 | 7496 | 1.64041666667 | 14273 |
| 013588 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:34am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595032.5 | 511018.9 | 7498 | 1.64041666667 | 13588 |
| 013297 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:35am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595034.8 | 511020.3 | 7500 | 1.64041666667 | 13297 |
| 012534 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:36am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595036.3 | 511021.2 | 7502 | 1.64041666667 | 12534 |
| 013303 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.0 | 511021.5 | 7504 | 1.64041666667 | 13303 |
| 012626 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595039.0 | 511022.4 | 7506 | 1.64041666667 | 12626 |
| 013956 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595039.1 | 511022.2 | 7508 | 1.64041666667 | 13956 |
| 015339 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595039.0 | 511022.1 | 7510 | 1.64041666667 | 15339 |
| 014094 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.9 | 511022.2 | 7512 | 1.64041666667 | 14094 |
| 014863 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595039.0 | 511022.1 | 7514 | 1.64041666667 | 14863 |
| 014456 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.8 | 511022.1 | 7516 | 1.64041666667 | 14456 |
| 013904 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:44am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.8 | 511022.1 | 7518 | 1.64041666667 | 13904 |
| 013346 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.7 | 511022.0 | 7520 | 1.64041666667 | 13346 |
| 014886 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.7 | 511021.9 | 7522 | 1.64041666667 | 14886 |
| 014341 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595038.7 | 511021.8 | 7524 | 1.64041666667 | 14341 |
| 015945 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:48am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.6 | 511021.8 | 7526 | 1.64041666667 | 15945 |
| 015086 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:49am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.7 | 511021.9 | 7528 | 1.64041666667 | 15086 |
| 013341 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:50am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.8 | 511022.0 | 7530 | 1.64041666667 | 13341 |
| 013925 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:51am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595039.0 | 511022.2 | 7532 | 1.64041666667 | 13925 |
| 014101 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595039.9 | 511022.6 | 7534 | 1.64041666667 | 14101 |
| 013965 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.7 | 511021.8 | 7536 | 1.64041666667 | 13965 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:54am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.3 | 511022.1 | 7538 | 1.64041666667 | 12521 |
| 014320 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:55am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.2 | 511022.1 | 7540 | 1.64041666667 | 14320 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013690 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:56am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.2 | 511022.0 | 7542 | 1.64041666667 | 13690 |
| 012962 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:57am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.2 | 511022.1 | 7544 | 1.64041666667 | 12962 |
| 013200 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:58am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.2 | 511022.1 | 7546 | 1.64041666667 | 13200 |
| 014550 | 0 | GeoXH 6000 | 08/19/2015 | 10:34:59am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.2 | 511022.1 | 7548 | 1.64041666667 | 14550 |
| 013087 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:00am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.2 | 511022.1 | 7550 | 1.64041666667 | 13087 |
| 014042 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:01am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.3 | 511022.1 | 7552 | 1.64041666667 | 14042 |
| 013890 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:02am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.3 | 511022.1 | 7554 | 1.64041666667 | 13890 |
| 013852 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:03am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.3 | 511022.1 | 7556 | 1.64041666667 | 13852 |
| 013363 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:04am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595038.3 | 511022.2 | 7558 | 1.64041666667 | 13363 |
| 014261 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:05am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.3 | 511022.2 | 7560 | 1.64041666667 | 14261 |
| 014095 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:06am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.4 | 511022.2 | 7562 | 1.64041666667 | 14095 |
| 013213 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:07am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.9 | 511022.1 | 7564 | 1.64041666667 | 13213 |
| 013893 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595039.4 | 511022.2 | 7566 | 1.64041666667 | 13893 |
| 015623 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595039.6 | 511022.2 | 7568 | 1.64041666667 | 15623 |
| 012935 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595039.8 | 511022.2 | 7570 | 1.64041666667 | 12935 |
| 013854 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595039.6 | 511022.2 | 7572 | 1.64041666667 | 13854 |
| 014863 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:12am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595039.5 | 511022.3 | 7574 | 1.64041666667 | 14863 |
| 015836 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595039.7 | 511022.2 | 7576 | 1.64041666667 | 15836 |
| 014339 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595039.8 | 511022.2 | 7578 | 1.64041666667 | 14339 |
| 013274 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595039.8 | 511022.2 | 7580 | 1.64041666667 | 13274 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595039.8 | 511022.2 | 7582 | 1.64041666667 | 12918 |
| 012709 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:17am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595039.8 | 511022.3 | 7584 | 1.64041666667 | 12709 |
| 014067 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:18am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595039.8 | 511022.3 | 7586 | 1.64041666667 | 14067 |
| 013717 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:19am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595039.7 | 511022.3 | 7588 | 1.64041666667 | 13717 |
| 013659 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:20am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595039.5 | 511022.3 | 7590 | 1.64041666667 | 13659 |
| 013914 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.9 | 511022.3 | 7592 | 1.64041666667 | 13914 |
| 013798 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.6 | 511022.1 | 7594 | 1.64041666667 | 13798 |
| 015059 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.5 | 511021.9 | 7596 | 1.64041666667 | 15059 |
| 013815 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:24am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.5 | 511021.9 | 7598 | 1.64041666667 | 13815 |
| 012543 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:25am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.4 | 511022.5 | 7600 | 1.64041666667 | 12543 |
| 015225 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:26am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.5 | 511022.4 | 7602 | 1.64041666667 | 15225 |
| 013256 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.6 | 511022.4 | 7604 | 1.64041666667 | 13256 |
| 013094 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595038.6 | 511022.2 | 7606 | 1.64041666667 | 13094 |
| 015033 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.4 | 511022.2 | 7608 | 1.64041666667 | 15033 |
| 012788 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:30am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.4 | 511022.2 | 7610 | 1.64041666667 | 12788 |
| 012497 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.6 | 511022.2 | 7612 | 1.64041666667 | 12497 |
| 012154 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.5 | 511022.3 | 7614 | 1.64041666667 | 12154 |
| 014678 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:33am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.6 | 511022.3 | 7616 | 1.64041666667 | 14678 |
| 014959 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:34am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.5 | 511021.8 | 7618 | 1.64041666667 | 14959 |
| 014440 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:35am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595040.4 | 511020.6 | 7620 | 1.64041666667 | 14440 |
| 013540 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:36am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595042.3 | 511019.0 | 7622 | 1.64041666667 | 13540 |
| 012415 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595043.3 | 511019.5 | 7624 | 1.64041666667 | 12415 |
| 013813 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.1 | 511019.6 | 7626 | 1.64041666667 | 13813 |
| 014343 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:39am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595044.3 | 511020.5 | 7628 | 1.64041666667 | 14343 |
| 013695 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.6 | 511020.2 | 7630 | 1.64041666667 | 13695 |
| 012753 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.4 | 511020.1 | 7632 | 1.64041666667 | 12753 |
| 013058 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.4 | 511019.9 | 7634 | 1.64041666667 | 13058 |
| 013434 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.4 | 511018.3 | 7636 | 1.64041666667 | 13434 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014818 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:44am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595047.1 | 511016.8 | 7638 | 1.64041666667 | 14818 |
| 014384 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595048.6 | 511015.4 | 7640 | 1.64041666667 | 14384 |
| 013556 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595049.4 | 511015.3 | 7642 | 1.64041666667 | 13556 |
| 012209 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:47am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595049.6 | 511014.6 | 7644 | 1.64041666667 | 12209 |
| 013162 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1595049.9 | 511013.7 | 7646 | 1.64041666667 | 13162 |
| 015110 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1595049.9 | 511013.6 | 7648 | 1.64041666667 | 15110 |
| 014817 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:50am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1595049.7 | 511013.5 | 7650 | 1.64041666667 | 14817 |
| 014114 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:51am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1595049.8 | 511013.3 | 7652 | 1.64041666667 | 14114 |
| 013818 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:52am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1595049.7 | 511013.4 | 7654 | 1.64041666667 | 13818 |
| 014434 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595049.6 | 511015.2 | 7656 | 1.64041666667 | 14434 |
| 013298 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:54am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595050.0 | 511015.7 | 7658 | 1.64041666667 | 13298 |
| 013134 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:55am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595049.6 | 511016.6 | 7660 | 1.64041666667 | 13134 |
| 012913 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:56am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595048.8 | 511016.5 | 7662 | 1.64041666667 | 12913 |
| 013278 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:57am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595046.6 | 511018.2 | 7664 | 1.64041666667 | 13278 |
| 014269 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:58am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.1 | 511019.0 | 7666 | 1.64041666667 | 14269 |
| 012837 | 0 | GeoXH 6000 | 08/19/2015 | 10:35:59am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.8 | 511019.7 | 7668 | 1.64041666667 | 12837 |
| 013679 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:00am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.2 | 511019.7 | 7670 | 1.64041666667 | 13679 |
| 014070 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:01am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.3 | 511019.7 | 7672 | 1.64041666667 | 14070 |
| 013417 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:02am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595045.3 | 511019.6 | 7674 | 1.64041666667 | 13417 |
| 014604 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:03am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.2 | 511019.5 | 7676 | 1.64041666667 | 14604 |
| 014121 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:04am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595045.2 | 511019.5 | 7678 | 1.64041666667 | 14121 |
| 015560 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:05am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595045.1 | 511019.6 | 7680 | 1.64041666667 | 15560 |
| 012650 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:06am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595045.0 | 511019.6 | 7682 | 1.64041666667 | 12650 |
| 014352 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:07am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.2 | 511019.6 | 7684 | 1.64041666667 | 14352 |
| 012408 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:08am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595045.5 | 511019.7 | 7686 | 1.64041666667 | 12408 |
| 011982 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:09am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595045.7 | 511019.5 | 7688 | 1.64041666667 | 11982 |
| 013285 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:10am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.4 | 511019.7 | 7690 | 1.64041666667 | 13285 |
| 012501 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:11am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.2 | 511019.7 | 7692 | 1.64041666667 | 12501 |
| 012185 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:12am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.2 | 511019.7 | 7694 | 1.64041666667 | 12185 |
| 011296 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:13am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.1 | 511019.7 | 7696 | 1.64041666667 | 11296 |
| 012574 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:14am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595045.0 | 511019.8 | 7698 | 1.64041666667 | 12574 |
| 012863 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:15am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.0 | 511019.8 | 7700 | 1.64041666667 | 12863 |
| 013896 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:16am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.8 | 511019.6 | 7702 | 1.64041666667 | 13896 |
| 013224 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:17am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.5 | 511019.6 | 7704 | 1.64041666667 | 13224 |
| 012096 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:18am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.7 | 511019.7 | 7706 | 1.64041666667 | 12096 |
| 013674 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:19am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.9 | 511019.8 | 7708 | 1.64041666667 | 13674 |
| 014368 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.2 | 511019.6 | 7710 | 1.64041666667 | 14368 |
| 013882 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.0 | 511019.7 | 7712 | 1.64041666667 | 13882 |
| 013310 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.1 | 511019.8 | 7714 | 1.64041666667 | 13310 |
| 012357 | 0 | GeoXH 6000 | 08/19/2015 | 10:36:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.3 | 511020.0 | 7720 | 1.64041666667 | 12357 |
| 013139 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:43am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595044.3 | 511019.1 | 7721 | 1.64041666667 | 13139 |
| 013905 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:44am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595044.3 | 511018.9 | 7723 | 1.64041666667 | 13905 |
| 015716 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:45am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595043.0 | 511018.7 | 7725 | 1.64041666667 | 15716 |
| 013829 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:46am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1595041.0 | 511017.7 | 7727 | 1.64041666667 | 13829 |
| 011377 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:47am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595038.5 | 511016.9 | 7729 | 1.64041666667 | 11377 |
| 015624 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595036.4 | 511015.4 | 7731 | 1.64041666667 | 15624 |
| 013416 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:49am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595033.9 | 511014.7 | 7733 | 1.64041666667 | 13416 |
| 013074 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:50am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595031.2 | 511013.7 | 7735 | 1.64041666667 | 13074 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 016018 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:51am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595028.6 | 511013.8 | 7737 | 1.64041666667 | 16018 |
| 014654 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1595026.1 | 511012.7 | 7739 | 1.64041666667 | 14654 |
| 013323 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:53am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595023.4 | 511012.0 | 7741 | 1.64041666667 | 13323 |
| 013320 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:54am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595021.4 | 511010.9 | 7743 | 1.64041666667 | 13320 |
| 014100 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:55am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1595019.7 | 511009.3 | 7745 | 1.64041666667 | 14100 |
| 013755 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:56am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595017.5 | 511007.2 | 7747 | 1.64041666667 | 13755 |
| 013968 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595016.0 | 511005.5 | 7749 | 1.64041666667 | 13968 |
| 015612 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595013.1 | 511004.5 | 7751 | 1.64041666667 | 15612 |
| 012546 | 0 | GeoXH 6000 | 08/19/2015 | 10:46:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595010.9 | 511003.4 | 7753 | 1.64041666667 | 12546 |
| 014453 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595008.3 | 511002.5 | 7755 | 1.64041666667 | 14453 |
| 012643 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595005.9 | 511001.6 | 7757 | 1.64041666667 | 12643 |
| 014771 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:02am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1595003.1 | 511000.2 | 7759 | 1.64041666667 | 14771 |
| 013592 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1595001.2 | 510999.0 | 7761 | 1.64041666667 | 13592 |
| 013598 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594999.0 | 510996.9 | 7763 | 1.64041666667 | 13598 |
| 014979 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594996.8 | 510995.6 | 7765 | 1.64041666667 | 14979 |
| 015205 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594995.0 | 510993.9 | 7767 | 1.64041666667 | 15205 |
| 013671 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594993.4 | 510992.9 | 7769 | 1.64041666667 | 13671 |
| 015297 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594991.8 | 510990.9 | 7771 | 1.64041666667 | 15297 |
| 013394 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594990.1 | 510989.2 | 7773 | 1.64041666667 | 13394 |
| 014748 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594988.5 | 510987.0 | 7775 | 1.64041666667 | 14748 |
| 014397 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1594986.5 | 510985.9 | 7777 | 1.64041666667 | 14397 |
| 014549 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:12am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594983.9 | 510985.0 | 7779 | 1.64041666667 | 14549 |
| 012487 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594981.3 | 510983.9 | 7781 | 1.64041666667 | 12487 |
| 012931 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:14am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594978.3 | 510983.0 | 7783 | 1.64041666667 | 12931 |
| 012712 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:15am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594976.0 | 510981.6 | 7785 | 1.64041666667 | 12712 |
| 013588 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:16am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594973.5 | 510980.5 | 7787 | 1.64041666667 | 13588 |
| 013537 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:17am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594971.6 | 510979.2 | 7789 | 1.64041666667 | 13537 |
| 013764 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:18am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594969.0 | 510978.1 | 7791 | 1.64041666667 | 13764 |
| 013191 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:19am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594966.8 | 510976.6 | 7793 | 1.64041666667 | 13191 |
| 013857 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:20am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594963.7 | 510975.6 | 7795 | 1.64041666667 | 13857 |
| 013694 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:21am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594961.7 | 510974.4 | 7797 | 1.64041666667 | 13694 |
| 014673 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:22am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594958.8 | 510972.2 | 7799 | 1.64041666667 | 14673 |
| 013598 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:23am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594956.7 | 510971.1 | 7801 | 1.64041666667 | 13598 |
| 014589 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:24am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594953.7 | 510969.5 | 7803 | 1.64041666667 | 14589 |
| 013757 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:25am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594951.2 | 510969.2 | 7805 | 1.64041666667 | 13757 |
| 013729 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:26am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594948.9 | 510968.2 | 7807 | 1.64041666667 | 13729 |
| 014382 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:27am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594946.4 | 510967.6 | 7809 | 1.64041666667 | 14382 |
| 012955 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:28am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594943.7 | 510966.4 | 7811 | 1.64041666667 | 12955 |
| 013229 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:29am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594941.0 | 510965.4 | 7813 | 1.64041666667 | 13229 |
| 012997 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:30am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594937.8 | 510964.5 | 7815 | 1.64041666667 | 12997 |
| 012849 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:31am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594935.2 | 510962.9 | 7817 | 1.64041666667 | 12849 |
| 014942 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:32am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594932.7 | 510961.4 | 7819 | 1.64041666667 | 14942 |
| 014655 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:33am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594930.8 | 510959.8 | 7821 | 1.64041666667 | 14655 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:34am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594928.3 | 510958.0 | 7823 | 1.64041666667 | 14463 |
| 013906 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:35am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594926.9 | 510956.3 | 7825 | 1.64041666667 | 13906 |
| 012116 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:36am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594925.3 | 510953.9 | 7827 | 1.64041666667 | 12116 |
| 014729 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:37am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594925.5 | 510953.8 | 7829 | 1.64041666667 | 14729 |
| 014242 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:38am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594926.9 | 510951.6 | 7831 | 1.64041666667 | 14242 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012560 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:39am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594927.8 | 510949.5 | 7833 | 1.64041666667 | 12560 |
| 014150 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:40am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594928.4 | 510948.9 | 7835 | 1.64041666667 | 14150 |
| 012927 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:41am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594929.2 | 510948.5 | 7837 | 1.64041666667 | 12927 |
| 013492 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:42am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594931.2 | 510946.2 | 7839 | 1.64041666667 | 13492 |
| 014293 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:43am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594932.6 | 510944.3 | 7841 | 1.64041666667 | 14293 |
| 016683 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:44am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594932.8 | 510943.9 | 7843 | 1.64041666667 | 16683 |
| 014160 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:45am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.0 | 7845 | 1.64041666667 | 14160 |
| 013740 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:46am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.0 | 7847 | 1.64041666667 | 13740 |
| 017385 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:47am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.1 | 7849 | 1.64041666667 | 17385 |
| 016976 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:48am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.1 | 7851 | 1.64041666667 | 16976 |
| 014624 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.9 | 510944.0 | 7853 | 1.64041666667 | 14624 |
| 015236 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:50am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594933.1 | 510943.7 | 7855 | 1.64041666667 | 15236 |
| 014129 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:51am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594933.1 | 510943.7 | 7857 | 1.64041666667 | 14129 |
| 014392 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:52am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594933.1 | 510943.8 | 7859 | 1.64041666667 | 14392 |
| 013438 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:53am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594933.0 | 510944.0 | 7861 | 1.64041666667 | 13438 |
| 013589 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:54am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.9 | 510944.0 | 7863 | 1.64041666667 | 13589 |
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:55am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.9 | 510944.0 | 7865 | 1.64041666667 | 12937 |
| 014394 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:56am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.9 | 510944.0 | 7867 | 1.64041666667 | 14394 |
| 014728 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:57am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.9 | 510944.0 | 7869 | 1.64041666667 | 14728 |
| 015562 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:58am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.9 | 510943.9 | 7871 | 1.64041666667 | 15562 |
| 015050 | 0 | GeoXH 6000 | 08/19/2015 | 10:47:59am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.0 | 7873 | 1.64041666667 | 15050 |
| 015642 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:00am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.1 | 7875 | 1.64041666667 | 15642 |
| 014800 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:01am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.7 | 510944.1 | 7877 | 1.64041666667 | 14800 |
| 014740 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:02am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.1 | 7879 | 1.64041666667 | 14740 |
| 014455 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:03am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.9 | 510944.0 | 7881 | 1.64041666667 | 14455 |
| 013783 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:04am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.9 | 510943.9 | 7883 | 1.64041666667 | 13783 |
| 015116 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:05am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594933.0 | 510943.3 | 7885 | 1.64041666667 | 15116 |
| 014009 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:06am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.9 | 510943.5 | 7887 | 1.64041666667 | 14009 |
| 013492 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:07am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.9 | 510944.0 | 7889 | 1.64041666667 | 13492 |
| 013933 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:08am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594933.0 | 510944.2 | 7891 | 1.64041666667 | 13933 |
| 015063 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:09am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594933.0 | 510944.2 | 7893 | 1.64041666667 | 15063 |
| 013305 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:10am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.2 | 7895 | 1.64041666667 | 13305 |
| 012926 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:11am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.7 | 510944.2 | 7897 | 1.64041666667 | 12926 |
| 015111 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:12am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.3 | 7899 | 1.64041666667 | 15111 |
| 013858 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:13am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.7 | 510944.2 | 7901 | 1.64041666667 | 13858 |
| 014924 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:14am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.7 | 510944.2 | 7903 | 1.64041666667 | 14924 |
| 013661 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:15am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.7 | 510944.2 | 7905 | 1.64041666667 | 13661 |
| 015235 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:16am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.2 | 7907 | 1.64041666667 | 15235 |
| 016288 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:17am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.2 | 7909 | 1.64041666667 | 16288 |
| 016432 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:18am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.2 | 7911 | 1.64041666667 | 16432 |
| 015748 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:19am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.2 | 7913 | 1.64041666667 | 15748 |
| 014677 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:20am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.7 | 510944.2 | 7915 | 1.64041666667 | 14677 |
| 015069 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:21am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.2 | 7917 | 1.64041666667 | 15069 |
| 015947 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:22am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594932.8 | 510944.2 | 7919 | 1.64041666667 | 15947 |
| 014876 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:23am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.2 | 7921 | 1.64041666667 | 14876 |
| 015209 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:24am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.7 | 510944.1 | 7923 | 1.64041666667 | 15209 |
| 016702 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:25am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.7 | 510944.1 | 7925 | 1.64041666667 | 16702 |
| 015395 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:26am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.7 | 510944.0 | 7927 | 1.64041666667 | 15395 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014318 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:27am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.9 | 510944.1 | 7929 | 1.64041666667 | 14318 |
| 014319 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:28am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594933.2 | 510944.0 | 7931 | 1.64041666667 | 14319 |
| 016390 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:29am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594933.2 | 510944.0 | 7933 | 1.64041666667 | 16390 |
| 015197 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:30am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594933.1 | 510944.1 | 7935 | 1.64041666667 | 15197 |
| 015109 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:31am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.9 | 510944.1 | 7937 | 1.64041666667 | 15109 |
| 014577 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:32am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594933.0 | 510944.2 | 7939 | 1.64041666667 | 14577 |
| 016064 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:33am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.1 | 7941 | 1.64041666667 | 16064 |
| 014516 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:34am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.1 | 7943 | 1.64041666667 | 14516 |
| 014189 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:35am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.2 | 7945 | 1.64041666667 | 14189 |
| 014617 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:36am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.2 | 7947 | 1.64041666667 | 14617 |
| 015414 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:37am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.2 | 7949 | 1.64041666667 | 15414 |
| 013603 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:38am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.2 | 7951 | 1.64041666667 | 13603 |
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:39am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.3 | 7953 | 1.64041666667 | 13451 |
| 015602 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:40am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594932.8 | 510944.2 | 7955 | 1.64041666667 | 15602 |
| 014790 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:41am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.1 | 7957 | 1.64041666667 | 14790 |
| 014737 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:42am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.2 | 7959 | 1.64041666667 | 14737 |
| 014694 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:43am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.2 | 7961 | 1.64041666667 | 14694 |
| 015073 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:44am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.2 | 7963 | 1.64041666667 | 15073 |
| 014928 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:45am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.2 | 7965 | 1.64041666667 | 14928 |
| 015432 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:46am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.2 | 7967 | 1.64041666667 | 15432 |
| 014718 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:47am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.2 | 7969 | 1.64041666667 | 14718 |
| 014749 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:48am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.2 | 7971 | 1.64041666667 | 14749 |
| 014967 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.8 | 510944.2 | 7973 | 1.64041666667 | 14967 |
| 014812 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:50am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594932.9 | 510944.2 | 7975 | 1.64041666667 | 14812 |
| 014773 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:51am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594932.9 | 510944.2 | 7977 | 1.64041666667 | 14773 |
| 012423 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:52am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594932.9 | 510944.2 | 7979 | 1.64041666667 | 12423 |
| 014131 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:53am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510944.2 | 7981 | 1.64041666667 | 14131 |
| 013856 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:54am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.8 | 510944.2 | 7983 | 1.64041666667 | 13856 |
| 013304 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:55am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.8 | 510944.2 | 7985 | 1.64041666667 | 13304 |
| 014186 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:56am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.8 | 510944.2 | 7987 | 1.64041666667 | 14186 |
| 015426 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:57am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.8 | 510944.2 | 7989 | 1.64041666667 | 15426 |
| 015586 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:58am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.8 | 510944.2 | 7991 | 1.64041666667 | 15586 |
| 014306 | 0 | GeoXH 6000 | 08/19/2015 | 10:48:59am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.8 | 510944.2 | 7993 | 1.64041666667 | 14306 |
| 013236 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:00am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594933.6 | 510944.1 | 7995 | 1.64041666667 | 13236 |
| 015369 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:01am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594934.3 | 510944.5 | 7997 | 1.64041666667 | 15369 |
| 014822 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:02am | Sensor | 1797-S0008-G-TJV.cor | 6821.5 | 1594934.7 | 510944.8 | 7999 | 1.64041666667 | 14822 |
| 014355 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:03am | Sensor | 1797-S0008-G-TJV.cor | 6821.2 | 1594934.8 | 510944.8 | 8001 | 1.64041666667 | 14355 |
| 014568 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:04am | Sensor | 1797-S0008-G-TJV.cor | 6821.0 | 1594935.0 | 510944.6 | 8003 | 1.64041666667 | 14568 |
| 014202 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:05am | Sensor | 1797-S0008-G-TJV.cor | 6821.0 | 1594935.1 | 510944.5 | 8005 | 1.64041666667 | 14202 |
| 014650 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:06am | Sensor | 1797-S0008-G-TJV.cor | 6821.9 | 1594934.8 | 510944.1 | 8007 | 1.64041666667 | 14650 |
| 014102 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:07am | Sensor | 1797-S0008-G-TJV.cor | 6821.6 | 1594935.0 | 510943.5 | 8009 | 1.64041666667 | 14102 |
| 013515 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:08am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594934.0 | 510943.6 | 8011 | 1.64041666667 | 13515 |
| 014808 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:09am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.9 | 510943.2 | 8013 | 1.64041666667 | 14808 |
| 014652 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:10am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.8 | 510942.6 | 8015 | 1.64041666667 | 14652 |
| 014463 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:11am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594932.1 | 510943.4 | 8017 | 1.64041666667 | 14463 |
| 013875 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:12am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594930.4 | 510945.1 | 8019 | 1.64041666667 | 13875 |
| 013218 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:13am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594928.9 | 510946.9 | 8021 | 1.64041666667 | 13218 |
| 014254 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:14am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594928.1 | 510948.6 | 8023 | 1.64041666667 | 14254 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012893 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:15am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594927.9 | 510948.9 | 8025 | 1.64041666667 | 12893 |
| 014263 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:16am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594928.0 | 510949.1 | 8027 | 1.64041666667 | 14263 |
| 013046 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:17am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594929.4 | 510949.8 | 8029 | 1.64041666667 | 13046 |
| 014061 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:18am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594930.9 | 510951.3 | 8031 | 1.64041666667 | 14061 |
| 014015 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:19am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594933.0 | 510953.3 | 8033 | 1.64041666667 | 14015 |
| 013673 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:20am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594934.9 | 510954.4 | 8035 | 1.64041666667 | 13673 |
| 013678 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:21am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594937.0 | 510955.6 | 8037 | 1.64041666667 | 13678 |
| 014249 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:22am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594939.3 | 510956.5 | 8039 | 1.64041666667 | 14249 |
| 014092 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:23am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594941.7 | 510958.0 | 8041 | 1.64041666667 | 14092 |
| 014323 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:24am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594944.7 | 510958.9 | 8043 | 1.64041666667 | 14323 |
| 013990 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:25am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594946.9 | 510960.3 | 8045 | 1.64041666667 | 13990 |
| 013817 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:26am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594949.2 | 510961.2 | 8047 | 1.64041666667 | 13817 |
| 015184 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:27am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594951.0 | 510962.7 | 8049 | 1.64041666667 | 15184 |
| 014476 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:28am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594952.9 | 510964.0 | 8051 | 1.64041666667 | 14476 |
| 014869 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:29am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594954.8 | 510965.4 | 8053 | 1.64041666667 | 14869 |
| 013557 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:30am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594957.7 | 510967.1 | 8055 | 1.64041666667 | 13557 |
| 014399 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:31am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594960.9 | 510968.0 | 8057 | 1.64041666667 | 14399 |
| 012600 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:32am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594963.8 | 510969.2 | 8059 | 1.64041666667 | 12600 |
| 012780 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:33am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594966.2 | 510969.8 | 8061 | 1.64041666667 | 12780 |
| 012765 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:34am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594968.7 | 510971.5 | 8063 | 1.64041666667 | 12765 |
| 014831 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:35am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594971.2 | 510972.9 | 8065 | 1.64041666667 | 14831 |
| 012767 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:36am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594974.4 | 510974.4 | 8067 | 1.64041666667 | 12767 |
| 014621 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:37am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594977.0 | 510975.7 | 8069 | 1.64041666667 | 14621 |
| 013195 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:38am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594980.2 | 510977.1 | 8071 | 1.64041666667 | 13195 |
| 015149 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:39am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594982.2 | 510978.5 | 8073 | 1.64041666667 | 15149 |
| 013537 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1594984.9 | 510979.9 | 8075 | 1.64041666667 | 13537 |
| 011844 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1594987.2 | 510980.9 | 8077 | 1.64041666667 | 11844 |
| 013281 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:42am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594989.8 | 510981.9 | 8079 | 1.64041666667 | 13281 |
| 013670 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:43am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594992.9 | 510982.9 | 8081 | 1.64041666667 | 13670 |
| 015027 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:44am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594995.9 | 510984.7 | 8083 | 1.64041666667 | 15027 |
| 013717 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:45am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594998.3 | 510985.9 | 8085 | 1.64041666667 | 13717 |
| 013149 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:46am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595001.1 | 510987.7 | 8087 | 1.64041666667 | 13149 |
| 014867 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:47am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595004.0 | 510989.7 | 8089 | 1.64041666667 | 14867 |
| 014726 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595007.0 | 510991.0 | 8091 | 1.64041666667 | 14726 |
| 015591 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:49am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595009.5 | 510992.6 | 8093 | 1.64041666667 | 15591 |
| 014818 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:50am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595012.7 | 510994.1 | 8095 | 1.64041666667 | 14818 |
| 016514 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:51am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595015.7 | 510995.4 | 8097 | 1.64041666667 | 16514 |
| 015618 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595018.3 | 510997.3 | 8099 | 1.64041666667 | 15618 |
| 015094 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595020.6 | 510999.0 | 8101 | 1.64041666667 | 15094 |
| 013793 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:54am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595022.8 | 511001.4 | 8103 | 1.64041666667 | 13793 |
| 012508 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:55am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595024.9 | 511003.1 | 8105 | 1.64041666667 | 12508 |
| 013087 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:56am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595027.4 | 511005.0 | 8107 | 1.64041666667 | 13087 |
| 012181 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595029.2 | 511006.3 | 8109 | 1.64041666667 | 12181 |
| 013035 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:58am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595031.8 | 511006.3 | 8111 | 1.64041666667 | 13035 |
| 012678 | 0 | GeoXH 6000 | 08/19/2015 | 10:49:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595034.2 | 511007.3 | 8113 | 1.64041666667 | 12678 |
| 013399 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595036.6 | 511008.7 | 8115 | 1.64041666667 | 13399 |
| 014450 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595039.2 | 511010.2 | 8117 | 1.64041666667 | 14450 |
| 013182 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:02am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595041.8 | 511011.2 | 8119 | 1.64041666667 | 13182 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013495 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:03am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595044.3 | 511011.5 | 8121 | 1.64041666667 | 13495 |
| 013604 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:04am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595047.1 | 511012.6 | 8123 | 1.64041666667 | 13604 |
| 013571 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595048.3 | 511013.6 | 8125 | 1.64041666667 | 13571 |
| 012902 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:06am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595047.2 | 511013.3 | 8127 | 1.64041666667 | 12902 |
| 014985 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:07am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595047.8 | 511012.8 | 8129 | 1.64041666667 | 14985 |
| 013016 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:08am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595050.1 | 511011.2 | 8131 | 1.64041666667 | 13016 |
| 012914 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:09am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595052.0 | 511009.3 | 8133 | 1.64041666667 | 12914 |
| 015468 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:10am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595052.3 | 511008.3 | 8135 | 1.64041666667 | 15468 |
| 013887 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:11am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595052.6 | 511008.1 | 8137 | 1.64041666667 | 13887 |
| 013641 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:12am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595054.6 | 511006.4 | 8139 | 1.64041666667 | 13641 |
| 013670 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:13am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595056.6 | 511004.8 | 8141 | 1.64041666667 | 13670 |
| 013587 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:14am | Sensor | 1797-S0008-G-TJV.cor | 6824.9 | 1595058.3 | 511002.8 | 8143 | 1.64041666667 | 13587 |
| 012307 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:15am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595059.2 | 511002.0 | 8145 | 1.64041666667 | 12307 |
| 013726 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:16am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595059.4 | 511001.7 | 8147 | 1.64041666667 | 13726 |
| 014081 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:17am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595059.7 | 511000.9 | 8149 | 1.64041666667 | 14081 |
| 013480 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:18am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595059.7 | 511000.4 | 8151 | 1.64041666667 | 13480 |
| 015370 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:19am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1595059.7 | 511000.1 | 8153 | 1.64041666667 | 15370 |
| 014702 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595059.7 | 511001.3 | 8155 | 1.64041666667 | 14702 |
| 012765 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595059.3 | 511002.3 | 8157 | 1.64041666667 | 12765 |
| 014411 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595057.3 | 511003.6 | 8159 | 1.64041666667 | 14411 |
| 013353 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595055.9 | 511005.4 | 8161 | 1.64041666667 | 13353 |
| 014228 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:24am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595054.0 | 511007.4 | 8163 | 1.64041666667 | 14228 |
| 013427 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:25am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595052.7 | 511007.5 | 8165 | 1.64041666667 | 13427 |
| 012806 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:26am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595050.1 | 511006.6 | 8167 | 1.64041666667 | 12806 |
| 014241 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595048.0 | 511005.1 | 8169 | 1.64041666667 | 14241 |
| 013700 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.7 | 511003.1 | 8171 | 1.64041666667 | 13700 |
| 013535 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595043.8 | 511001.8 | 8173 | 1.64041666667 | 13535 |
| 012773 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:30am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595041.7 | 510999.4 | 8175 | 1.64041666667 | 12773 |
| 013303 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595039.8 | 510997.9 | 8177 | 1.64041666667 | 13303 |
| 014666 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.1 | 510995.9 | 8179 | 1.64041666667 | 14666 |
| 014526 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:33am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595036.7 | 510994.3 | 8181 | 1.64041666667 | 14526 |
| 013891 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:34am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595036.0 | 510991.5 | 8183 | 1.64041666667 | 13891 |
| 013792 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:35am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595034.5 | 510990.1 | 8185 | 1.64041666667 | 13792 |
| 014578 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:36am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595033.3 | 510988.8 | 8187 | 1.64041666667 | 14578 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595031.4 | 510989.3 | 8189 | 1.64041666667 | 13424 |
| 015086 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595030.5 | 510988.9 | 8191 | 1.64041666667 | 15086 |
| 015291 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595028.7 | 510988.7 | 8193 | 1.64041666667 | 15291 |
| 014592 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595027.4 | 510987.7 | 8195 | 1.64041666667 | 14592 |
| 013338 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595025.2 | 510988.0 | 8197 | 1.64041666667 | 13338 |
| 013384 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595022.7 | 510987.5 | 8199 | 1.64041666667 | 13384 |
| 014386 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595020.5 | 510987.2 | 8201 | 1.64041666667 | 14386 |
| 015416 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:44am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595018.4 | 510985.9 | 8203 | 1.64041666667 | 15416 |
| 015134 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595016.0 | 510985.1 | 8205 | 1.64041666667 | 15134 |
| 015063 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595013.4 | 510983.8 | 8207 | 1.64041666667 | 15063 |
| 015105 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595011.2 | 510983.0 | 8209 | 1.64041666667 | 15105 |
| 015596 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:48am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595008.6 | 510982.3 | 8211 | 1.64041666667 | 15596 |
| 016499 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:49am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595006.2 | 510981.1 | 8213 | 1.64041666667 | 16499 |
| 015255 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:50am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595003.2 | 510979.8 | 8215 | 1.64041666667 | 15255 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012633 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:51am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595001.0 | 510978.2 | 8217 | 1.64041666667 | 12633 |
| 013538 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1594998.4 | 510977.1 | 8219 | 1.64041666667 | 13538 |
| 014694 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1594996.0 | 510975.7 | 8221 | 1.64041666667 | 14694 |
| 014683 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:54am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1594993.3 | 510974.2 | 8223 | 1.64041666667 | 14683 |
| 016691 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:55am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1594991.5 | 510973.3 | 8225 | 1.64041666667 | 16691 |
| 014552 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:56am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1594989.0 | 510971.7 | 8227 | 1.64041666667 | 14552 |
| 015248 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594986.4 | 510970.4 | 8229 | 1.64041666667 | 15248 |
| 014552 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594984.2 | 510968.5 | 8231 | 1.64041666667 | 14552 |
| 013358 | 0 | GeoXH 6000 | 08/19/2015 | 10:50:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594982.0 | 510967.3 | 8233 | 1.64041666667 | 13358 |
| 012639 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594979.4 | 510965.4 | 8235 | 1.64041666667 | 12639 |
| 013900 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594977.0 | 510964.3 | 8237 | 1.64041666667 | 13900 |
| 015325 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:02am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594974.2 | 510962.8 | 8239 | 1.64041666667 | 15325 |
| 015201 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594972.1 | 510961.5 | 8241 | 1.64041666667 | 15201 |
| 012920 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594969.1 | 510961.7 | 8243 | 1.64041666667 | 12920 |
| 013640 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594966.7 | 510961.7 | 8245 | 1.64041666667 | 13640 |
| 014660 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594964.2 | 510961.5 | 8247 | 1.64041666667 | 14660 |
| 014765 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594962.5 | 510960.0 | 8249 | 1.64041666667 | 14765 |
| 013171 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594961.0 | 510957.6 | 8251 | 1.64041666667 | 13171 |
| 014332 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594959.1 | 510955.9 | 8253 | 1.64041666667 | 14332 |
| 013963 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594956.4 | 510954.1 | 8255 | 1.64041666667 | 13963 |
| 013541 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594953.8 | 510953.6 | 8257 | 1.64041666667 | 13541 |
| 013735 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:12am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594950.8 | 510952.3 | 8259 | 1.64041666667 | 13735 |
| 013123 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594948.4 | 510951.1 | 8261 | 1.64041666667 | 13123 |
| 014711 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594945.6 | 510950.1 | 8263 | 1.64041666667 | 14711 |
| 013007 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594943.6 | 510948.6 | 8265 | 1.64041666667 | 13007 |
| 012341 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594940.4 | 510947.6 | 8267 | 1.64041666667 | 12341 |
| 012235 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:17am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594938.6 | 510946.4 | 8269 | 1.64041666667 | 12235 |
| 013469 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:18am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594935.8 | 510944.8 | 8271 | 1.64041666667 | 13469 |
| 013327 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:19am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594934.8 | 510944.1 | 8273 | 1.64041666667 | 13327 |
| 012481 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:20am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594934.6 | 510943.9 | 8275 | 1.64041666667 | 12481 |
| 015330 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:21am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594935.0 | 510944.4 | 8277 | 1.64041666667 | 15330 |
| 014932 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:22am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594935.9 | 510943.7 | 8279 | 1.64041666667 | 14932 |
| 015313 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:23am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594937.3 | 510941.8 | 8281 | 1.64041666667 | 15313 |
| 014358 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:24am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594939.3 | 510941.1 | 8283 | 1.64041666667 | 14358 |
| 016159 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:25am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594940.3 | 510940.2 | 8285 | 1.64041666667 | 16159 |
| 015109 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:26am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594940.4 | 510939.8 | 8287 | 1.64041666667 | 15109 |
| 016437 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:27am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594940.6 | 510939.5 | 8289 | 1.64041666667 | 16437 |
| 014429 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:28am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594941.3 | 510939.9 | 8291 | 1.64041666667 | 14429 |
| 014197 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:29am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594943.3 | 510938.7 | 8293 | 1.64041666667 | 14197 |
| 012039 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:30am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594945.9 | 510938.0 | 8295 | 1.64041666667 | 12039 |
| 013689 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:31am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594947.4 | 510937.1 | 8297 | 1.64041666667 | 13689 |
| 013562 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:32am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594948.4 | 510936.8 | 8299 | 1.64041666667 | 13562 |
| 015300 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:33am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594948.5 | 510936.8 | 8301 | 1.64041666667 | 15300 |
| 015225 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:34am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594947.6 | 510937.0 | 8303 | 1.64041666667 | 15225 |
| 012896 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:35am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594947.3 | 510937.0 | 8305 | 1.64041666667 | 12896 |
| 014444 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:36am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594947.4 | 510936.7 | 8307 | 1.64041666667 | 14444 |
| 013511 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:37am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594946.7 | 510935.4 | 8309 | 1.64041666667 | 13511 |
| 015047 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:38am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594945.5 | 510935.5 | 8311 | 1.64041666667 | 15047 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 015401 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:39am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594943.9 | 510935.2 | 8313 | 1.64041666667 | 15401 |
| 014830 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:40am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594942.8 | 510935.7 | 8315 | 1.64041666667 | 14830 |
| 015107 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:41am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594942.4 | 510937.1 | 8317 | 1.64041666667 | 15107 |
| 015566 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:42am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594942.2 | 510939.1 | 8319 | 1.64041666667 | 15566 |
| 013371 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:43am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594944.0 | 510940.3 | 8321 | 1.64041666667 | 13371 |
| 013243 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:44am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594947.0 | 510941.3 | 8323 | 1.64041666667 | 13243 |
| 014140 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:45am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594949.0 | 510942.8 | 8325 | 1.64041666667 | 14140 |
| 013765 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:46am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594951.6 | 510944.3 | 8327 | 1.64041666667 | 13765 |
| 014331 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:47am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594953.6 | 510945.8 | 8329 | 1.64041666667 | 14331 |
| 014052 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594956.1 | 510948.1 | 8331 | 1.64041666667 | 14052 |
| 013923 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:49am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594958.7 | 510949.7 | 8333 | 1.64041666667 | 13923 |
| 014910 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:50am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594961.4 | 510951.5 | 8335 | 1.64041666667 | 14910 |
| 014587 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:51am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594963.9 | 510952.0 | 8337 | 1.64041666667 | 14587 |
| 015077 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594966.2 | 510953.3 | 8339 | 1.64041666667 | 15077 |
| 015319 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:53am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594968.5 | 510954.2 | 8341 | 1.64041666667 | 15319 |
| 016159 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:54am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594971.1 | 510955.7 | 8343 | 1.64041666667 | 16159 |
| 014270 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:55am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594972.9 | 510957.8 | 8345 | 1.64041666667 | 14270 |
| 013947 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:56am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594974.5 | 510959.0 | 8347 | 1.64041666667 | 13947 |
| 013897 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594976.1 | 510959.9 | 8349 | 1.64041666667 | 13897 |
| 013764 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594977.6 | 510961.7 | 8351 | 1.64041666667 | 13764 |
| 014451 | 0 | GeoXH 6000 | 08/19/2015 | 10:51:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594979.7 | 510962.6 | 8353 | 1.64041666667 | 14451 |
| 013812 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:00am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594982.7 | 510963.7 | 8355 | 1.64041666667 | 13812 |
| 013113 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594985.3 | 510965.1 | 8357 | 1.64041666667 | 13113 |
| 014318 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:02am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594988.1 | 510965.9 | 8359 | 1.64041666667 | 14318 |
| 012939 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594989.7 | 510966.9 | 8361 | 1.64041666667 | 12939 |
| 013615 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594992.3 | 510968.3 | 8363 | 1.64041666667 | 13615 |
| 015103 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594995.3 | 510969.1 | 8365 | 1.64041666667 | 15103 |
| 014426 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594998.0 | 510970.4 | 8367 | 1.64041666667 | 14426 |
| 014286 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595000.5 | 510971.3 | 8369 | 1.64041666667 | 14286 |
| 014791 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595002.6 | 510972.9 | 8371 | 1.64041666667 | 14791 |
| 012967 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595004.9 | 510974.4 | 8373 | 1.64041666667 | 12967 |
| 014192 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595007.1 | 510975.8 | 8375 | 1.64041666667 | 14192 |
| 015218 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:11am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595009.2 | 510976.9 | 8377 | 1.64041666667 | 15218 |
| 013194 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:12am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595011.0 | 510978.4 | 8379 | 1.64041666667 | 13194 |
| 014008 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:13am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595013.0 | 510979.4 | 8381 | 1.64041666667 | 14008 |
| 013762 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:14am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595015.5 | 510980.6 | 8383 | 1.64041666667 | 13762 |
| 014660 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:15am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595017.9 | 510981.8 | 8385 | 1.64041666667 | 14660 |
| 014435 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:16am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595019.3 | 510983.7 | 8387 | 1.64041666667 | 14435 |
| 014528 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:17am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595021.5 | 510984.6 | 8389 | 1.64041666667 | 14528 |
| 014552 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:18am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595023.8 | 510986.3 | 8391 | 1.64041666667 | 14552 |
| 014468 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:19am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595026.4 | 510987.0 | 8393 | 1.64041666667 | 14468 |
| 014057 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595028.6 | 510988.9 | 8395 | 1.64041666667 | 14057 |
| 013504 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595030.7 | 510988.7 | 8397 | 1.64041666667 | 13504 |
| 013786 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595033.3 | 510989.1 | 8399 | 1.64041666667 | 13786 |
| 015566 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595035.7 | 510989.3 | 8401 | 1.64041666667 | 15566 |
| 014751 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:24am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595038.6 | 510990.2 | 8403 | 1.64041666667 | 14751 |
| 014218 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:25am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595041.5 | 510991.4 | 8405 | 1.64041666667 | 14218 |
| 014954 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:26am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595044.6 | 510992.0 | 8407 | 1.64041666667 | 14954 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014388 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595046.3 | 510993.5 | 8409 | 1.64041666667 | 14388 |
| 015297 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595048.7 | 510995.3 | 8411 | 1.64041666667 | 15297 |
| 014024 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595050.9 | 510997.0 | 8413 | 1.64041666667 | 14024 |
| 013496 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:30am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595053.8 | 510998.3 | 8415 | 1.64041666667 | 13496 |
| 014354 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595056.0 | 510999.3 | 8417 | 1.64041666667 | 14354 |
| 014448 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.9 | 1595057.8 | 511000.4 | 8419 | 1.64041666667 | 14448 |
| 014772 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:33am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595059.3 | 511001.0 | 8421 | 1.64041666667 | 14772 |
| 014373 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:34am | Sensor | 1797-S0008-G-TJV.cor | 6824.9 | 1595058.7 | 511000.9 | 8423 | 1.64041666667 | 14373 |
| 013133 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:35am | Sensor | 1797-S0008-G-TJV.cor | 6824.9 | 1595058.0 | 511000.9 | 8425 | 1.64041666667 | 13133 |
| 013903 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:36am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595057.8 | 511000.9 | 8427 | 1.64041666667 | 13903 |
| 012986 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:37am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595057.7 | 511000.8 | 8429 | 1.64041666667 | 12986 |
| 012966 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:38am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595057.7 | 511000.8 | 8431 | 1.64041666667 | 12966 |
| 013321 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:39am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595058.2 | 511001.0 | 8433 | 1.64041666667 | 13321 |
| 014430 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:40am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595059.0 | 511000.7 | 8435 | 1.64041666667 | 14430 |
| 014557 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:41am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595060.8 | 510999.2 | 8437 | 1.64041666667 | 14557 |
| 013839 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:42am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595062.2 | 510996.7 | 8439 | 1.64041666667 | 13839 |
| 012550 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:43am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595062.4 | 510996.0 | 8441 | 1.64041666667 | 12550 |
| 012617 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:44am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595063.7 | 510995.0 | 8443 | 1.64041666667 | 12617 |
| 013984 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:45am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595065.2 | 510993.0 | 8445 | 1.64041666667 | 13984 |
| 014626 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595067.5 | 510991.0 | 8447 | 1.64041666667 | 14626 |
| 014936 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595068.3 | 510990.5 | 8449 | 1.64041666667 | 14936 |
| 013664 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595068.6 | 510990.2 | 8451 | 1.64041666667 | 13664 |
| 015566 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:49am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595068.2 | 510990.3 | 8453 | 1.64041666667 | 15566 |
| 013821 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:50am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595067.3 | 510991.9 | 8455 | 1.64041666667 | 13821 |
| 014375 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:51am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595067.0 | 510993.0 | 8457 | 1.64041666667 | 14375 |
| 013313 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:52am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595065.8 | 510992.7 | 8459 | 1.64041666667 | 13313 |
| 012718 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:53am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595064.6 | 510994.2 | 8461 | 1.64041666667 | 12718 |
| 012209 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:54am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595063.1 | 510995.9 | 8463 | 1.64041666667 | 12209 |
| 012682 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:55am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595063.1 | 510995.7 | 8465 | 1.64041666667 | 12682 |
| 012980 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:56am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595062.7 | 510996.2 | 8467 | 1.64041666667 | 12980 |
| 013475 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:57am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595062.4 | 510996.5 | 8469 | 1.64041666667 | 13475 |
| 013508 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:58am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595062.3 | 510996.6 | 8471 | 1.64041666667 | 13508 |
| 014327 | 0 | GeoXH 6000 | 08/19/2015 | 10:52:59am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595062.2 | 510996.6 | 8473 | 1.64041666667 | 14327 |
| 014861 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:00am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595062.2 | 510996.8 | 8475 | 1.64041666667 | 14861 |
| 014275 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:01am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595062.2 | 510996.8 | 8477 | 1.64041666667 | 14275 |
| 016199 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:02am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595062.2 | 510996.7 | 8479 | 1.64041666667 | 16199 |
| 015149 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:03am | Sensor | 1797-S0008-G-TJV.cor | 6825.0 | 1595061.8 | 510996.5 | 8481 | 1.64041666667 | 15149 |
| 014797 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:04am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595060.4 | 510995.9 | 8483 | 1.64041666667 | 14797 |
| 014709 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:05am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595058.0 | 510995.3 | 8485 | 1.64041666667 | 14709 |
| 014267 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:06am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595055.8 | 510993.9 | 8487 | 1.64041666667 | 14267 |
| 013886 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:07am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595053.9 | 510993.0 | 8489 | 1.64041666667 | 13886 |
| 013521 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:08am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595051.7 | 510991.6 | 8491 | 1.64041666667 | 13521 |
| 012140 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:09am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595049.1 | 510990.2 | 8493 | 1.64041666667 | 12140 |
| 013895 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:10am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595046.1 | 510988.5 | 8495 | 1.64041666667 | 13895 |
| 014723 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:11am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595043.5 | 510986.6 | 8497 | 1.64041666667 | 14723 |
| 013521 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:12am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595040.8 | 510985.5 | 8499 | 1.64041666667 | 13521 |
| 014660 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:13am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595038.9 | 510984.2 | 8501 | 1.64041666667 | 14660 |
| 014615 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:14am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595036.3 | 510983.3 | 8503 | 1.64041666667 | 14615 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012863 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:15am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595035.0 | 510981.8 | 8505 | 1.64041666667 | 12863 |
| 013206 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:16am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595032.4 | 510980.6 | 8507 | 1.64041666667 | 13206 |
| 014851 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:17am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595030.2 | 510979.4 | 8509 | 1.64041666667 | 14851 |
| 015442 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:18am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595027.6 | 510978.1 | 8511 | 1.64041666667 | 15442 |
| 013640 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:19am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595025.3 | 510976.8 | 8513 | 1.64041666667 | 13640 |
| 015380 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595022.6 | 510975.0 | 8515 | 1.64041666667 | 15380 |
| 014165 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595020.1 | 510973.9 | 8517 | 1.64041666667 | 14165 |
| 013771 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595017.7 | 510972.5 | 8519 | 1.64041666667 | 13771 |
| 013912 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595015.4 | 510971.3 | 8521 | 1.64041666667 | 13912 |
| 013108 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:24am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595012.4 | 510969.5 | 8523 | 1.64041666667 | 13108 |
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:25am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595010.2 | 510967.9 | 8525 | 1.64041666667 | 12937 |
| 015414 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:26am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595007.0 | 510966.2 | 8527 | 1.64041666667 | 15414 |
| 014233 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595005.0 | 510964.7 | 8529 | 1.64041666667 | 14233 |
| 013998 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595002.2 | 510963.3 | 8531 | 1.64041666667 | 13998 |
| 014869 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:29am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594999.8 | 510962.0 | 8533 | 1.64041666667 | 14869 |
| 014097 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:30am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594997.2 | 510960.5 | 8535 | 1.64041666667 | 14097 |
| 013994 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:31am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594995.0 | 510959.3 | 8537 | 1.64041666667 | 13994 |
| 013638 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:32am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594992.7 | 510957.3 | 8539 | 1.64041666667 | 13638 |
| 014779 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:33am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594990.6 | 510956.0 | 8541 | 1.64041666667 | 14779 |
| 015544 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:34am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594988.5 | 510953.9 | 8543 | 1.64041666667 | 15544 |
| 014026 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:35am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594986.0 | 510952.8 | 8545 | 1.64041666667 | 14026 |
| 013796 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:36am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594983.3 | 510951.4 | 8547 | 1.64041666667 | 13796 |
| 015119 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:37am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594980.4 | 510950.1 | 8549 | 1.64041666667 | 15119 |
| 013860 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:38am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594977.1 | 510948.9 | 8551 | 1.64041666667 | 13860 |
| 012435 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:39am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594974.5 | 510947.6 | 8553 | 1.64041666667 | 12435 |
| 013878 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:40am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594971.7 | 510946.5 | 8555 | 1.64041666667 | 13878 |
| 014209 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:41am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594969.1 | 510945.1 | 8557 | 1.64041666667 | 14209 |
| 014592 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:42am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594966.2 | 510943.4 | 8559 | 1.64041666667 | 14592 |
| 015528 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:43am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594963.7 | 510942.0 | 8561 | 1.64041666667 | 15528 |
| 015792 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:44am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594961.2 | 510939.9 | 8563 | 1.64041666667 | 15792 |
| 014748 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:45am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594958.7 | 510939.1 | 8565 | 1.64041666667 | 14748 |
| 014427 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:46am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594956.4 | 510937.8 | 8567 | 1.64041666667 | 14427 |
| 014766 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:47am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594953.8 | 510936.9 | 8569 | 1.64041666667 | 14766 |
| 015391 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594951.2 | 510935.9 | 8571 | 1.64041666667 | 15391 |
| 015217 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594950.1 | 510935.4 | 8573 | 1.64041666667 | 15217 |
| 014274 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:50am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594950.8 | 510935.7 | 8575 | 1.64041666667 | 14274 |
| 013048 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:51am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594950.9 | 510936.3 | 8577 | 1.64041666667 | 13048 |
| 014362 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594951.2 | 510936.7 | 8579 | 1.64041666667 | 14362 |
| 014300 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:53am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594952.2 | 510935.7 | 8581 | 1.64041666667 | 14300 |
| 013655 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:54am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594954.7 | 510934.1 | 8583 | 1.64041666667 | 13655 |
| 013907 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:55am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594955.7 | 510933.5 | 8585 | 1.64041666667 | 13907 |
| 014428 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:56am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594956.5 | 510932.5 | 8587 | 1.64041666667 | 14428 |
| 013957 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594956.5 | 510932.0 | 8589 | 1.64041666667 | 13957 |
| 013809 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594956.3 | 510931.9 | 8591 | 1.64041666667 | 13809 |
| 012602 | 0 | GeoXH 6000 | 08/19/2015 | 10:53:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594956.4 | 510931.7 | 8593 | 1.64041666667 | 12602 |
| 014430 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594958.3 | 510931.1 | 8595 | 1.64041666667 | 14430 |
| 015517 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594960.6 | 510929.5 | 8597 | 1.64041666667 | 15517 |
| 014019 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:02am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594961.6 | 510929.1 | 8599 | 1.64041666667 | 14019 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014605 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594961.9 | 510929.3 | 8601 | 1.64041666667 | 14605 |
| 015441 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594962.0 | 510929.4 | 8603 | 1.64041666667 | 15441 |
| 015740 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594961.8 | 510929.4 | 8605 | 1.64041666667 | 15740 |
| 016025 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594961.6 | 510928.3 | 8607 | 1.64041666667 | 16025 |
| 014326 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594960.2 | 510928.5 | 8609 | 1.64041666667 | 14326 |
| 013751 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594957.3 | 510930.3 | 8611 | 1.64041666667 | 13751 |
| 012558 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594956.7 | 510931.6 | 8613 | 1.64041666667 | 12558 |
| 014959 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594957.6 | 510933.3 | 8615 | 1.64041666667 | 14959 |
| 013969 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594959.6 | 510934.2 | 8617 | 1.64041666667 | 13969 |
| 013692 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:12am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594961.6 | 510935.4 | 8619 | 1.64041666667 | 13692 |
| 013863 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594963.6 | 510936.4 | 8621 | 1.64041666667 | 13863 |
| 014115 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594966.5 | 510937.4 | 8623 | 1.64041666667 | 14115 |
| 013128 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594968.6 | 510938.7 | 8625 | 1.64041666667 | 13128 |
| 013782 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594971.0 | 510939.8 | 8627 | 1.64041666667 | 13782 |
| 014995 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:17am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594973.2 | 510941.1 | 8629 | 1.64041666667 | 14995 |
| 016169 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:18am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594975.7 | 510942.2 | 8631 | 1.64041666667 | 16169 |
| 015022 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:19am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594978.1 | 510943.1 | 8633 | 1.64041666667 | 15022 |
| 015455 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:20am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594981.1 | 510944.4 | 8635 | 1.64041666667 | 15455 |
| 014723 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:21am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594983.5 | 510945.2 | 8637 | 1.64041666667 | 14723 |
| 014031 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:22am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594985.9 | 510946.9 | 8639 | 1.64041666667 | 14031 |
| 013767 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:23am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594988.1 | 510948.5 | 8641 | 1.64041666667 | 13767 |
| 013222 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:24am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594990.9 | 510950.0 | 8643 | 1.64041666667 | 13222 |
| 014525 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:25am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594993.3 | 510951.8 | 8645 | 1.64041666667 | 14525 |
| 014161 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:26am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594996.2 | 510953.0 | 8647 | 1.64041666667 | 14161 |
| 014190 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:27am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594997.9 | 510954.4 | 8649 | 1.64041666667 | 14190 |
| 016027 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:28am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595000.5 | 510956.3 | 8651 | 1.64041666667 | 16027 |
| 015047 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:29am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595002.6 | 510957.9 | 8653 | 1.64041666667 | 15047 |
| 012521 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:30am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595004.8 | 510959.9 | 8655 | 1.64041666667 | 12521 |
| 014170 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595007.4 | 510961.1 | 8657 | 1.64041666667 | 14170 |
| 012932 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595009.6 | 510962.5 | 8659 | 1.64041666667 | 12932 |
| 014693 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:33am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595011.8 | 510963.7 | 8661 | 1.64041666667 | 14693 |
| 014443 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:34am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595014.7 | 510965.4 | 8663 | 1.64041666667 | 14443 |
| 012191 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:35am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595016.7 | 510967.0 | 8665 | 1.64041666667 | 12191 |
| 014297 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:36am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595019.5 | 510968.7 | 8667 | 1.64041666667 | 14297 |
| 015754 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595021.3 | 510970.3 | 8669 | 1.64041666667 | 15754 |
| 014828 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595024.0 | 510971.8 | 8671 | 1.64041666667 | 14828 |
| 014297 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595026.3 | 510973.1 | 8673 | 1.64041666667 | 14297 |
| 015874 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595029.0 | 510974.9 | 8675 | 1.64041666667 | 15874 |
| 014108 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595030.6 | 510975.6 | 8677 | 1.64041666667 | 14108 |
| 013907 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595032.4 | 510975.7 | 8679 | 1.64041666667 | 13907 |
| 014186 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595033.8 | 510976.2 | 8681 | 1.64041666667 | 14186 |
| 015336 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:44am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595036.2 | 510976.8 | 8683 | 1.64041666667 | 15336 |
| 014334 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.3 | 510977.8 | 8685 | 1.64041666667 | 14334 |
| 014743 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595041.1 | 510979.5 | 8687 | 1.64041666667 | 14743 |
| 014336 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595043.4 | 510980.1 | 8689 | 1.64041666667 | 14336 |
| 015614 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:48am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595045.8 | 510981.4 | 8691 | 1.64041666667 | 15614 |
| 015363 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:49am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595047.5 | 510981.8 | 8693 | 1.64041666667 | 15363 |
| 015060 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:50am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595048.2 | 510982.4 | 8695 | 1.64041666667 | 15060 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 015435 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:51am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595049.4 | 510982.3 | 8697 | 1.64041666667 | 15435 |
| 014898 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:52am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595051.4 | 510982.9 | 8699 | 1.64041666667 | 14898 |
| 015004 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595053.5 | 510983.6 | 8701 | 1.64041666667 | 15004 |
| 014131 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:54am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595056.4 | 510984.7 | 8703 | 1.64041666667 | 14131 |
| 013882 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:55am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595058.7 | 510986.3 | 8705 | 1.64041666667 | 13882 |
| 012440 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:56am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595061.5 | 510987.2 | 8707 | 1.64041666667 | 12440 |
| 012140 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:57am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595063.7 | 510988.4 | 8709 | 1.64041666667 | 12140 |
| 014075 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:58am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595066.1 | 510989.8 | 8711 | 1.64041666667 | 14075 |
| 015308 | 0 | GeoXH 6000 | 08/19/2015 | 10:54:59am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595066.5 | 510990.1 | 8713 | 1.64041666667 | 15308 |
| 012827 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:00am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595066.5 | 510989.9 | 8715 | 1.64041666667 | 12827 |
| 013676 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:01am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595067.9 | 510988.9 | 8717 | 1.64041666667 | 13676 |
| 014099 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:02am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595070.0 | 510986.4 | 8719 | 1.64041666667 | 14099 |
| 014685 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:03am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595070.7 | 510985.1 | 8721 | 1.64041666667 | 14685 |
| 013421 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:04am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595071.8 | 510984.3 | 8723 | 1.64041666667 | 13421 |
| 012685 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:05am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595073.5 | 510982.4 | 8725 | 1.64041666667 | 12685 |
| 012621 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:06am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595074.7 | 510981.3 | 8727 | 1.64041666667 | 12621 |
| 011975 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:07am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595075.5 | 510980.7 | 8729 | 1.64041666667 | 11975 |
| 012203 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:08am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595075.9 | 510979.9 | 8731 | 1.64041666667 | 12203 |
| 012441 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:09am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595076.6 | 510979.0 | 8733 | 1.64041666667 | 12441 |
| 012200 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1595077.2 | 510978.1 | 8735 | 1.64041666667 | 12200 |
| 013550 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1595077.3 | 510977.9 | 8737 | 1.64041666667 | 13550 |
| 014757 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:12am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1595077.4 | 510977.9 | 8739 | 1.64041666667 | 14757 |
| 012779 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595077.0 | 510978.2 | 8741 | 1.64041666667 | 12779 |
| 013455 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:14am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595075.8 | 510980.3 | 8743 | 1.64041666667 | 13455 |
| 012903 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:15am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595075.2 | 510981.6 | 8745 | 1.64041666667 | 12903 |
| 013935 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:16am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595074.6 | 510982.0 | 8747 | 1.64041666667 | 13935 |
| 013413 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:17am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595073.2 | 510982.8 | 8749 | 1.64041666667 | 13413 |
| 013133 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:18am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595071.5 | 510984.5 | 8751 | 1.64041666667 | 13133 |
| 013543 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:19am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595069.9 | 510985.2 | 8753 | 1.64041666667 | 13543 |
| 015146 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595067.3 | 510984.2 | 8755 | 1.64041666667 | 15146 |
| 015396 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595064.8 | 510983.3 | 8757 | 1.64041666667 | 15396 |
| 013599 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595062.2 | 510981.3 | 8759 | 1.64041666667 | 13599 |
| 014409 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595060.1 | 510979.2 | 8761 | 1.64041666667 | 14409 |
| 013532 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:24am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595057.4 | 510977.1 | 8763 | 1.64041666667 | 13532 |
| 014573 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:25am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595055.5 | 510975.7 | 8765 | 1.64041666667 | 14573 |
| 013093 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:26am | Sensor | 1797-S0008-G-TJV.cor | 6825.1 | 1595052.7 | 510974.5 | 8767 | 1.64041666667 | 13093 |
| 013653 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595050.1 | 510973.7 | 8769 | 1.64041666667 | 13653 |
| 012353 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595046.8 | 510972.9 | 8771 | 1.64041666667 | 12353 |
| 014848 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595044.5 | 510973.4 | 8773 | 1.64041666667 | 14848 |
| 015742 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:30am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595041.9 | 510972.8 | 8775 | 1.64041666667 | 15742 |
| 013865 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595039.9 | 510972.1 | 8777 | 1.64041666667 | 13865 |
| 015256 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595038.9 | 510970.3 | 8779 | 1.64041666667 | 15256 |
| 014764 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:33am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595038.5 | 510967.6 | 8781 | 1.64041666667 | 14764 |
| 013531 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:34am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595036.9 | 510964.8 | 8783 | 1.64041666667 | 13531 |
| 015172 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:35am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595035.0 | 510963.6 | 8785 | 1.64041666667 | 15172 |
| 014743 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:36am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595031.7 | 510963.2 | 8787 | 1.64041666667 | 14743 |
| 018746 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595029.1 | 510962.7 | 8789 | 1.64041666667 | 18746 |
| 013926 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:38am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595025.7 | 510961.9 | 8791 | 1.64041666667 | 13926 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013951 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595022.9 | 510961.7 | 8793 | 1.64041666667 | 13951 |
| 014377 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595020.0 | 510960.7 | 8795 | 1.64041666667 | 14377 |
| 017304 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595017.5 | 510960.7 | 8797 | 1.64041666667 | 17304 |
| 015876 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595015.1 | 510960.2 | 8799 | 1.64041666667 | 15876 |
| 013029 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595012.8 | 510959.8 | 8801 | 1.64041666667 | 13029 |
| 011957 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:44am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595009.7 | 510958.8 | 8803 | 1.64041666667 | 11957 |
| 012079 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595007.6 | 510957.7 | 8805 | 1.64041666667 | 12079 |
| 014389 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595004.6 | 510957.0 | 8807 | 1.64041666667 | 14389 |
| 013557 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:47am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595002.4 | 510956.2 | 8809 | 1.64041666667 | 13557 |
| 013739 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594999.8 | 510954.4 | 8811 | 1.64041666667 | 13739 |
| 012075 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:49am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594997.2 | 510953.3 | 8813 | 1.64041666667 | 12075 |
| 014238 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:50am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594994.6 | 510951.4 | 8815 | 1.64041666667 | 14238 |
| 012709 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:51am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594992.3 | 510950.6 | 8817 | 1.64041666667 | 12709 |
| 014247 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594989.9 | 510948.9 | 8819 | 1.64041666667 | 14247 |
| 014152 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:53am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594987.6 | 510947.5 | 8821 | 1.64041666667 | 14152 |
| 016468 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:54am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594984.7 | 510945.6 | 8823 | 1.64041666667 | 16468 |
| 015547 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:55am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594982.4 | 510943.8 | 8825 | 1.64041666667 | 15547 |
| 015586 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:56am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594979.4 | 510942.1 | 8827 | 1.64041666667 | 15586 |
| 016706 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594977.5 | 510940.5 | 8829 | 1.64041666667 | 16706 |
| 014736 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594974.7 | 510938.9 | 8831 | 1.64041666667 | 14736 |
| 014484 | 0 | GeoXH 6000 | 08/19/2015 | 10:55:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594972.4 | 510937.5 | 8833 | 1.64041666667 | 14484 |
| 014361 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594969.8 | 510935.3 | 8835 | 1.64041666667 | 14361 |
| 015170 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594967.4 | 510933.9 | 8837 | 1.64041666667 | 15170 |
| 013722 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:02am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594965.7 | 510932.3 | 8839 | 1.64041666667 | 13722 |
| 012730 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594964.0 | 510930.9 | 8841 | 1.64041666667 | 12730 |
| 012842 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594964.0 | 510930.8 | 8843 | 1.64041666667 | 12842 |
| 014520 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594964.8 | 510931.4 | 8845 | 1.64041666667 | 14520 |
| 015750 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594967.0 | 510929.9 | 8847 | 1.64041666667 | 15750 |
| 014317 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594968.6 | 510928.8 | 8849 | 1.64041666667 | 14317 |
| 012969 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594969.2 | 510928.6 | 8851 | 1.64041666667 | 12969 |
| 013412 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594969.6 | 510927.7 | 8853 | 1.64041666667 | 13412 |
| 013433 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594971.1 | 510926.2 | 8855 | 1.64041666667 | 13433 |
| 012298 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594972.7 | 510924.1 | 8857 | 1.64041666667 | 12298 |
| 014504 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:12am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594973.2 | 510923.0 | 8859 | 1.64041666667 | 14504 |
| 012832 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594973.7 | 510923.2 | 8861 | 1.64041666667 | 12832 |
| 013244 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594974.1 | 510923.3 | 8863 | 1.64041666667 | 13244 |
| 013481 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594973.4 | 510922.9 | 8865 | 1.64041666667 | 13481 |
| 013990 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594971.9 | 510924.1 | 8867 | 1.64041666667 | 13990 |
| 012017 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:17am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594969.9 | 510925.4 | 8869 | 1.64041666667 | 12017 |
| 012724 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:18am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594970.3 | 510927.3 | 8871 | 1.64041666667 | 12724 |
| 012721 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:19am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594971.4 | 510929.3 | 8873 | 1.64041666667 | 12721 |
| 014610 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:20am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594973.3 | 510930.5 | 8875 | 1.64041666667 | 14610 |
| 014482 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:21am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594974.7 | 510931.6 | 8877 | 1.64041666667 | 14482 |
| 013430 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:22am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594976.7 | 510932.9 | 8879 | 1.64041666667 | 13430 |
| 014577 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:23am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594978.8 | 510933.8 | 8881 | 1.64041666667 | 14577 |
| 013424 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:24am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594981.4 | 510935.1 | 8883 | 1.64041666667 | 13424 |
| 015026 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:25am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594983.3 | 510935.8 | 8885 | 1.64041666667 | 15026 |
| 015936 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:26am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1594985.9 | 510937.1 | 8887 | 1.64041666667 | 15936 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014064 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1594988.5 | 510938.0 | 8889 | 1.64041666667 | 14064 |
| 013626 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1594991.6 | 510939.3 | 8891 | 1.64041666667 | 13626 |
| 013216 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1594994.2 | 510940.3 | 8893 | 1.64041666667 | 13216 |
| 013864 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:30am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1594997.1 | 510941.4 | 8895 | 1.64041666667 | 13864 |
| 014446 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:31am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595000.1 | 510942.8 | 8897 | 1.64041666667 | 14446 |
| 014981 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595003.0 | 510943.8 | 8899 | 1.64041666667 | 14981 |
| 015145 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:33am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595005.2 | 510945.0 | 8901 | 1.64041666667 | 15145 |
| 015876 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:34am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595008.2 | 510946.2 | 8903 | 1.64041666667 | 15876 |
| 014709 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:35am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595010.7 | 510946.4 | 8905 | 1.64041666667 | 14709 |
| 013427 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:36am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595013.4 | 510947.1 | 8907 | 1.64041666667 | 13427 |
| 014156 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595015.9 | 510947.7 | 8909 | 1.64041666667 | 14156 |
| 015659 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595018.4 | 510949.0 | 8911 | 1.64041666667 | 15659 |
| 013995 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595021.1 | 510950.3 | 8913 | 1.64041666667 | 13995 |
| 015108 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595023.8 | 510952.2 | 8915 | 1.64041666667 | 15108 |
| 014577 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595026.1 | 510954.0 | 8917 | 1.64041666667 | 14577 |
| 015854 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595028.9 | 510955.6 | 8919 | 1.64041666667 | 15854 |
| 015243 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595031.2 | 510957.0 | 8921 | 1.64041666667 | 15243 |
| 013650 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:44am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595034.2 | 510958.5 | 8923 | 1.64041666667 | 13650 |
| 015472 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595036.6 | 510959.5 | 8925 | 1.64041666667 | 15472 |
| 012988 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595039.5 | 510960.5 | 8927 | 1.64041666667 | 12988 |
| 012727 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595041.7 | 510960.9 | 8929 | 1.64041666667 | 12727 |
| 014611 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:48am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595043.8 | 510961.4 | 8931 | 1.64041666667 | 14611 |
| 014752 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:49am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595045.8 | 510962.4 | 8933 | 1.64041666667 | 14752 |
| 015118 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:50am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595047.8 | 510963.9 | 8935 | 1.64041666667 | 15118 |
| 013919 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:51am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595050.1 | 510964.8 | 8937 | 1.64041666667 | 13919 |
| 014340 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:52am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595052.9 | 510965.7 | 8939 | 1.64041666667 | 14340 |
| 012945 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595055.2 | 510965.8 | 8941 | 1.64041666667 | 12945 |
| 012506 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:54am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595058.0 | 510966.5 | 8943 | 1.64041666667 | 12506 |
| 013566 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:55am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595060.7 | 510968.2 | 8945 | 1.64041666667 | 13566 |
| 014671 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:56am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595063.7 | 510969.4 | 8947 | 1.64041666667 | 14671 |
| 013417 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:57am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595065.5 | 510970.5 | 8949 | 1.64041666667 | 13417 |
| 015504 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:58am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595067.0 | 510971.5 | 8951 | 1.64041666667 | 15504 |
| 015936 | 0 | GeoXH 6000 | 08/19/2015 | 10:56:59am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595068.6 | 510972.7 | 8953 | 1.64041666667 | 15936 |
| 014664 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:00am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595071.0 | 510974.1 | 8955 | 1.64041666667 | 14664 |
| 014946 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:01am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595072.8 | 510975.5 | 8957 | 1.64041666667 | 14946 |
| 015346 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:02am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595075.2 | 510977.2 | 8959 | 1.64041666667 | 15346 |
| 013766 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:03am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595076.0 | 510977.6 | 8961 | 1.64041666667 | 13766 |
| 014361 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:04am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595075.8 | 510977.3 | 8963 | 1.64041666667 | 14361 |
| 011180 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:05am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595074.4 | 510977.2 | 8965 | 1.64041666667 | 11180 |
| 014585 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:06am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595073.8 | 510976.9 | 8967 | 1.64041666667 | 14585 |
| 013832 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:07am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595073.9 | 510976.8 | 8969 | 1.64041666667 | 13832 |
| 012454 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:08am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595074.0 | 510976.8 | 8971 | 1.64041666667 | 12454 |
| 013253 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:09am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595074.0 | 510976.8 | 8973 | 1.64041666667 | 13253 |
| 011593 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:10am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595074.0 | 510976.8 | 8975 | 1.64041666667 | 11593 |
| 012918 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:11am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595074.0 | 510976.8 | 8977 | 1.64041666667 | 12918 |
| 013849 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:12am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595074.1 | 510976.9 | 8979 | 1.64041666667 | 13849 |
| 012732 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:13am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595074.3 | 510976.8 | 8981 | 1.64041666667 | 12732 |
| 012423 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:14am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595074.4 | 510975.4 | 8983 | 1.64041666667 | 12423 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012675 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:15am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595074.6 | 510972.7 | 8985 | 1.64041666667 | 12675 |
| 012648 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:16am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595075.1 | 510970.5 | 8987 | 1.64041666667 | 12648 |
| 012582 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:17am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595075.3 | 510970.0 | 8989 | 1.64041666667 | 12582 |
| 012415 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:18am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595075.3 | 510969.7 | 8991 | 1.64041666667 | 12415 |
| 012164 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:19am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595075.4 | 510967.9 | 8993 | 1.64041666667 | 12164 |
| 013451 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595075.4 | 510965.0 | 8995 | 1.64041666667 | 13451 |
| 014072 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595075.5 | 510963.5 | 8997 | 1.64041666667 | 14072 |
| 012128 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595075.8 | 510963.5 | 8999 | 1.64041666667 | 12128 |
| 010652 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595075.9 | 510963.7 | 9001 | 1.64041666667 | 10652 |
| 012353 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:24am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1595075.8 | 510962.9 | 9003 | 1.64041666667 | 12353 |
| 012058 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:25am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1595075.9 | 510962.3 | 9005 | 1.64041666667 | 12058 |
| 012284 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:26am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1595075.8 | 510962.3 | 9007 | 1.64041666667 | 12284 |
| 014171 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595076.1 | 510963.9 | 9009 | 1.64041666667 | 14171 |
| 013982 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595076.6 | 510965.9 | 9011 | 1.64041666667 | 13982 |
| 014325 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595075.8 | 510966.9 | 9013 | 1.64041666667 | 14325 |
| 013361 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:30am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595074.2 | 510967.8 | 9015 | 1.64041666667 | 13361 |
| 014680 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595071.5 | 510968.0 | 9017 | 1.64041666667 | 14680 |
| 013450 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595068.9 | 510967.1 | 9019 | 1.64041666667 | 13450 |
| 014312 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:33am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595066.6 | 510965.6 | 9021 | 1.64041666667 | 14312 |
| 014318 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:34am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595063.3 | 510964.2 | 9023 | 1.64041666667 | 14318 |
| 012909 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:35am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595061.2 | 510963.1 | 9025 | 1.64041666667 | 12909 |
| 013787 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:36am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595058.4 | 510962.0 | 9027 | 1.64041666667 | 13787 |
| 014516 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595056.2 | 510961.1 | 9029 | 1.64041666667 | 14516 |
| 014549 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595054.0 | 510959.9 | 9031 | 1.64041666667 | 14549 |
| 016447 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595052.1 | 510959.0 | 9033 | 1.64041666667 | 16447 |
| 014971 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595050.4 | 510958.3 | 9035 | 1.64041666667 | 14971 |
| 014482 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595048.9 | 510957.8 | 9037 | 1.64041666667 | 14482 |
| 014450 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595047.3 | 510956.7 | 9039 | 1.64041666667 | 14450 |
| 015222 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595045.4 | 510955.7 | 9041 | 1.64041666667 | 15222 |
| 015055 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:44am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595042.8 | 510954.3 | 9043 | 1.64041666667 | 15055 |
| 014234 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595040.7 | 510953.6 | 9045 | 1.64041666667 | 14234 |
| 014808 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595038.1 | 510952.5 | 9047 | 1.64041666667 | 14808 |
| 015372 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595036.0 | 510951.3 | 9049 | 1.64041666667 | 15372 |
| 014883 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:48am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595033.1 | 510950.0 | 9051 | 1.64041666667 | 14883 |
| 014940 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:49am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595030.8 | 510948.5 | 9053 | 1.64041666667 | 14940 |
| 013695 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:50am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595028.5 | 510946.9 | 9055 | 1.64041666667 | 13695 |
| 015573 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:51am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595026.7 | 510945.4 | 9057 | 1.64041666667 | 15573 |
| 015203 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:52am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595024.3 | 510944.2 | 9059 | 1.64041666667 | 15203 |
| 012441 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595022.1 | 510943.1 | 9061 | 1.64041666667 | 12441 |
| 013880 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:54am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595019.5 | 510941.7 | 9063 | 1.64041666667 | 13880 |
| 015620 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:55am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595016.8 | 510940.7 | 9065 | 1.64041666667 | 15620 |
| 016235 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:56am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595014.0 | 510939.3 | 9067 | 1.64041666667 | 16235 |
| 014288 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:57am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595011.5 | 510938.5 | 9069 | 1.64041666667 | 14288 |
| 014882 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:58am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595009.0 | 510937.6 | 9071 | 1.64041666667 | 14882 |
| 013740 | 0 | GeoXH 6000 | 08/19/2015 | 10:57:59am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595006.6 | 510936.2 | 9073 | 1.64041666667 | 13740 |
| 013095 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595003.6 | 510934.9 | 9075 | 1.64041666667 | 13095 |
| 013983 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:01am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595001.2 | 510933.4 | 9077 | 1.64041666667 | 13983 |
| 014476 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:02am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1594998.1 | 510932.2 | 9079 | 1.64041666667 | 14476 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 015199 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:03am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594995.6 | 510931.3 | 9081 | 1.64041666667 | 15199 |
| 013849 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594992.3 | 510929.9 | 9083 | 1.64041666667 | 13849 |
| 013782 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1594989.2 | 510929.0 | 9085 | 1.64041666667 | 13782 |
| 014065 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1594986.3 | 510927.6 | 9087 | 1.64041666667 | 14065 |
| 014616 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594983.5 | 510926.6 | 9089 | 1.64041666667 | 14616 |
| 013944 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594980.4 | 510925.8 | 9091 | 1.64041666667 | 13944 |
| 012936 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:09am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594978.4 | 510924.7 | 9093 | 1.64041666667 | 12936 |
| 013044 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:10am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594976.9 | 510924.0 | 9095 | 1.64041666667 | 13044 |
| 014391 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:11am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594977.5 | 510923.3 | 9097 | 1.64041666667 | 14391 |
| 014277 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:12am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594979.5 | 510920.9 | 9099 | 1.64041666667 | 14277 |
| 014069 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594980.5 | 510919.6 | 9101 | 1.64041666667 | 14069 |
| 014677 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594981.0 | 510918.8 | 9103 | 1.64041666667 | 14677 |
| 014559 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594982.3 | 510917.4 | 9105 | 1.64041666667 | 14559 |
| 014679 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594984.5 | 510915.0 | 9107 | 1.64041666667 | 14679 |
| 014260 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:17am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594986.2 | 510913.7 | 9109 | 1.64041666667 | 14260 |
| 013225 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:18am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594987.0 | 510913.3 | 9111 | 1.64041666667 | 13225 |
| 013746 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:19am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1594987.0 | 510913.2 | 9113 | 1.64041666667 | 13746 |
| 013906 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:20am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1594986.6 | 510913.2 | 9115 | 1.64041666667 | 13906 |
| 014156 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:21am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594985.2 | 510913.3 | 9117 | 1.64041666667 | 14156 |
| 013109 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:22am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594984.4 | 510913.3 | 9119 | 1.64041666667 | 13109 |
| 013627 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:23am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594984.2 | 510913.1 | 9121 | 1.64041666667 | 13627 |
| 013726 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:24am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594983.0 | 510914.5 | 9123 | 1.64041666667 | 13726 |
| 013931 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:25am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594982.4 | 510916.7 | 9125 | 1.64041666667 | 13931 |
| 013713 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:26am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594983.5 | 510918.7 | 9127 | 1.64041666667 | 13713 |
| 014168 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:27am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594985.6 | 510920.2 | 9129 | 1.64041666667 | 14168 |
| 014522 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:28am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594988.3 | 510921.8 | 9131 | 1.64041666667 | 14522 |
| 014520 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:29am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594990.7 | 510923.4 | 9133 | 1.64041666667 | 14520 |
| 013020 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:30am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594993.7 | 510924.5 | 9135 | 1.64041666667 | 13020 |
| 013785 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:31am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1594996.1 | 510925.3 | 9137 | 1.64041666667 | 13785 |
| 013376 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:32am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1594998.9 | 510926.2 | 9139 | 1.64041666667 | 13376 |
| 013964 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:33am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595001.7 | 510927.2 | 9141 | 1.64041666667 | 13964 |
| 014381 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:34am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595004.6 | 510928.8 | 9143 | 1.64041666667 | 14381 |
| 015325 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:35am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595007.0 | 510930.0 | 9145 | 1.64041666667 | 15325 |
| 016041 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:36am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595009.6 | 510931.6 | 9147 | 1.64041666667 | 16041 |
| 014690 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:37am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595012.1 | 510933.4 | 9149 | 1.64041666667 | 14690 |
| 014592 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595015.0 | 510934.7 | 9151 | 1.64041666667 | 14592 |
| 014568 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595017.4 | 510935.9 | 9153 | 1.64041666667 | 14568 |
| 016122 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595019.8 | 510936.3 | 9155 | 1.64041666667 | 16122 |
| 015250 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595021.5 | 510936.7 | 9157 | 1.64041666667 | 15250 |
| 014462 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595024.0 | 510938.2 | 9159 | 1.64041666667 | 14462 |
| 015735 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:43am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595026.6 | 510939.8 | 9161 | 1.64041666667 | 15735 |
| 015753 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:44am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595029.2 | 510941.9 | 9163 | 1.64041666667 | 15753 |
| 014768 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595031.4 | 510943.1 | 9165 | 1.64041666667 | 14768 |
| 015722 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595034.1 | 510944.5 | 9167 | 1.64041666667 | 15722 |
| 015510 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595036.3 | 510945.2 | 9169 | 1.64041666667 | 15510 |
| 014917 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:48am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595038.9 | 510945.5 | 9171 | 1.64041666667 | 14917 |
| 016029 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:49am | Sensor | 1797-S0008-G-TJV.cor | 6823.7 | 1595041.0 | 510945.7 | 9173 | 1.64041666667 | 16029 |
| 014147 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:50am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595043.8 | 510946.2 | 9175 | 1.64041666667 | 14147 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013946 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:51am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595046.0 | 510947.2 | 9177 | 1.64041666667 | 13946 |
| 015036 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:52am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595048.6 | 510948.2 | 9179 | 1.64041666667 | 15036 |
| 013899 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:53am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595050.6 | 510949.4 | 9181 | 1.64041666667 | 13899 |
| 013764 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:54am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595052.7 | 510950.8 | 9183 | 1.64041666667 | 13764 |
| 014121 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:55am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595054.7 | 510952.3 | 9185 | 1.64041666667 | 14121 |
| 015950 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:56am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595056.9 | 510953.7 | 9187 | 1.64041666667 | 15950 |
| 012837 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:57am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595059.0 | 510955.2 | 9189 | 1.64041666667 | 12837 |
| 014489 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595061.9 | 510957.1 | 9191 | 1.64041666667 | 14489 |
| 012682 | 0 | GeoXH 6000 | 08/19/2015 | 10:58:59am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595064.4 | 510958.3 | 9193 | 1.64041666667 | 12682 |
| 016040 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:00am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595067.0 | 510960.0 | 9195 | 1.64041666667 | 16040 |
| 014720 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:01am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595069.3 | 510961.3 | 9197 | 1.64041666667 | 14720 |
| 013040 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:02am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595071.3 | 510962.8 | 9199 | 1.64041666667 | 13040 |
| 014360 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:03am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595073.8 | 510963.8 | 9201 | 1.64041666667 | 14360 |
| 011930 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:04am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595074.2 | 510964.6 | 9203 | 1.64041666667 | 11930 |
| 013585 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:05am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595074.3 | 510964.9 | 9205 | 1.64041666667 | 13585 |
| 011238 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:06am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595074.4 | 510964.8 | 9207 | 1.64041666667 | 11238 |
| 012229 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:07am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595074.7 | 510963.6 | 9209 | 1.64041666667 | 12229 |
| 013707 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:08am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595076.0 | 510960.5 | 9211 | 1.64041666667 | 13707 |
| 013717 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:09am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595076.6 | 510958.9 | 9213 | 1.64041666667 | 13717 |
| 013719 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:10am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595077.2 | 510958.1 | 9215 | 1.64041666667 | 13719 |
| 013149 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:11am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595077.9 | 510956.0 | 9217 | 1.64041666667 | 13149 |
| 012767 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:12am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595078.6 | 510953.8 | 9219 | 1.64041666667 | 12767 |
| 012311 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:13am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595078.9 | 510952.2 | 9221 | 1.64041666667 | 12311 |
| 013008 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595079.4 | 510950.5 | 9223 | 1.64041666667 | 13008 |
| 013272 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1595079.7 | 510949.9 | 9225 | 1.64041666667 | 13272 |
| 013038 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1595079.8 | 510949.8 | 9227 | 1.64041666667 | 13038 |
| 013819 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:17am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1595079.8 | 510949.7 | 9229 | 1.64041666667 | 13819 |
| 014404 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:18am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595079.0 | 510950.8 | 9231 | 1.64041666667 | 14404 |
| 013321 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:19am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595078.5 | 510952.1 | 9233 | 1.64041666667 | 13321 |
| 012750 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:20am | Sensor | 1797-S0008-G-TJV.cor | 6824.5 | 1595078.3 | 510954.1 | 9235 | 1.64041666667 | 12750 |
| 012937 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:21am | Sensor | 1797-S0008-G-TJV.cor | 6824.7 | 1595077.5 | 510956.6 | 9237 | 1.64041666667 | 12937 |
| 013344 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:22am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595075.8 | 510957.6 | 9239 | 1.64041666667 | 13344 |
| 012066 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:23am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595073.6 | 510957.4 | 9241 | 1.64041666667 | 12066 |
| 014176 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:24am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595070.5 | 510956.7 | 9243 | 1.64041666667 | 14176 |
| 014734 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:25am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595068.5 | 510955.2 | 9245 | 1.64041666667 | 14734 |
| 013073 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:26am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595066.3 | 510953.7 | 9247 | 1.64041666667 | 13073 |
| 012868 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:27am | Sensor | 1797-S0008-G-TJV.cor | 6824.3 | 1595064.3 | 510952.4 | 9249 | 1.64041666667 | 12868 |
| 012337 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:28am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595061.6 | 510951.0 | 9251 | 1.64041666667 | 12337 |
| 013254 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:29am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595059.3 | 510949.8 | 9253 | 1.64041666667 | 13254 |
| 012373 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:30am | Sensor | 1797-S0008-G-TJV.cor | 6824.6 | 1595056.7 | 510948.5 | 9255 | 1.64041666667 | 12373 |
| 011343 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:31am | Sensor | 1797-S0008-G-TJV.cor | 6824.8 | 1595055.0 | 510948.1 | 9257 | 1.64041666667 | 11343 |
| 013455 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:32am | Sensor | 1797-S0008-G-TJV.cor | 6824.4 | 1595052.9 | 510947.2 | 9259 | 1.64041666667 | 13455 |
| 014703 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:33am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595050.2 | 510946.6 | 9261 | 1.64041666667 | 14703 |
| 013396 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:34am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595047.6 | 510945.4 | 9263 | 1.64041666667 | 13396 |
| 014119 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:35am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595045.5 | 510944.3 | 9265 | 1.64041666667 | 14119 |
| 015349 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:36am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595042.8 | 510942.9 | 9267 | 1.64041666667 | 15349 |
| 015897 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:37am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595040.3 | 510941.3 | 9269 | 1.64041666667 | 15897 |
| 016034 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:38am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595037.4 | 510939.7 | 9271 | 1.64041666667 | 16034 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 016488 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:39am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595035.5 | 510938.3 | 9273 | 1.64041666667 | 16488 |
| 015882 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:40am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595033.4 | 510937.2 | 9275 | 1.64041666667 | 15882 |
| 015400 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:41am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595031.5 | 510936.4 | 9277 | 1.64041666667 | 15400 |
| 015040 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:42am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595029.3 | 510936.0 | 9279 | 1.64041666667 | 15040 |
| 014380 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:43am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595027.3 | 510936.2 | 9281 | 1.64041666667 | 14380 |
| 015235 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:44am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595024.9 | 510935.7 | 9283 | 1.64041666667 | 15235 |
| 015478 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:45am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595022.8 | 510934.5 | 9285 | 1.64041666667 | 15478 |
| 014729 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:46am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595021.3 | 510932.6 | 9287 | 1.64041666667 | 14729 |
| 018502 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:47am | Sensor | 1797-S0008-G-TJV.cor | 6824.2 | 1595019.5 | 510931.1 | 9289 | 1.64041666667 | 18502 |
| 017645 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:48am | Sensor | 1797-S0008-G-TJV.cor | 6824.1 | 1595017.2 | 510929.4 | 9291 | 1.64041666667 | 17645 |
| 015031 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:49am | Sensor | 1797-S0008-G-TJV.cor | 6824.0 | 1595015.3 | 510927.8 | 9293 | 1.64041666667 | 15031 |
| 014887 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:50am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595012.8 | 510925.9 | 9295 | 1.64041666667 | 14887 |
| 013442 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:51am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595010.6 | 510923.9 | 9297 | 1.64041666667 | 13442 |
| 014730 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:52am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595007.8 | 510922.2 | 9299 | 1.64041666667 | 14730 |
| 015112 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:53am | Sensor | 1797-S0008-G-TJV.cor | 6823.9 | 1595005.8 | 510920.8 | 9301 | 1.64041666667 | 15112 |
| 015328 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:54am | Sensor | 1797-S0008-G-TJV.cor | 6823.8 | 1595003.0 | 510919.4 | 9303 | 1.64041666667 | 15328 |
| 014602 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:55am | Sensor | 1797-S0008-G-TJV.cor | 6823.6 | 1595000.7 | 510918.3 | 9305 | 1.64041666667 | 14602 |
| 016460 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:56am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594997.8 | 510916.7 | 9307 | 1.64041666667 | 16460 |
| 014255 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:57am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594995.0 | 510915.9 | 9309 | 1.64041666667 | 14255 |
| 014063 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:58am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594991.9 | 510914.6 | 9311 | 1.64041666667 | 14063 |
| 014736 | 0 | GeoXH 6000 | 08/19/2015 | 10:59:59am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594989.4 | 510913.6 | 9313 | 1.64041666667 | 14736 |
| 013164 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:00am | Sensor | 1797-S0008-G-TJV.cor | 6823.1 | 1594986.7 | 510912.5 | 9315 | 1.64041666667 | 13164 |
| 014661 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:01am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1594985.6 | 510911.3 | 9317 | 1.64041666667 | 14661 |
| 015005 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:02am | Sensor | 1797-S0008-G-TJV.cor | 6821.8 | 1594986.1 | 510911.6 | 9319 | 1.64041666667 | 15005 |
| 015811 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:03am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594986.4 | 510912.1 | 9321 | 1.64041666667 | 15811 |
| 014962 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:04am | Sensor | 1797-S0008-G-TJV.cor | 6823.5 | 1594987.3 | 510911.1 | 9323 | 1.64041666667 | 14962 |
| 015530 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:05am | Sensor | 1797-S0008-G-TJV.cor | 6823.4 | 1594989.2 | 510909.5 | 9325 | 1.64041666667 | 15530 |
| 014232 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:06am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594990.7 | 510908.6 | 9327 | 1.64041666667 | 14232 |
| 014238 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:07am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594990.9 | 510908.2 | 9329 | 1.64041666667 | 14238 |
| 014359 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:08am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594992.0 | 510906.1 | 9331 | 1.64041666667 | 14359 |
| 015769 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:09am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594993.8 | 510903.2 | 9333 | 1.64041666667 | 15769 |
| 016872 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:10am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594994.8 | 510901.6 | 9335 | 1.64041666667 | 16872 |
| 015918 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:11am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594994.8 | 510901.4 | 9337 | 1.64041666667 | 15918 |
| 014239 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:12am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594994.1 | 510902.2 | 9339 | 1.64041666667 | 14239 |
| 015079 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:13am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594993.6 | 510902.8 | 9341 | 1.64041666667 | 15079 |
| 014390 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:14am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594993.6 | 510902.9 | 9343 | 1.64041666667 | 14390 |
| 014067 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:15am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594993.3 | 510903.2 | 9345 | 1.64041666667 | 14067 |
| 014797 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:16am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594993.0 | 510903.4 | 9347 | 1.64041666667 | 14797 |
| 012729 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:17am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594993.0 | 510903.4 | 9349 | 1.64041666667 | 12729 |
| 013142 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:18am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594993.0 | 510903.4 | 9351 | 1.64041666667 | 13142 |
| 013545 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:19am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594993.1 | 510903.4 | 9353 | 1.64041666667 | 13545 |
| 014336 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:20am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594993.5 | 510903.1 | 9355 | 1.64041666667 | 14336 |
| 014054 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:21am | Sensor | 1797-S0008-G-TJV.cor | 6822.9 | 1594993.7 | 510902.3 | 9357 | 1.64041666667 | 14054 |
| 014643 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:22am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594994.0 | 510902.7 | 9359 | 1.64041666667 | 14643 |
| 015150 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:23am | Sensor | 1797-S0008-G-TJV.cor | 6823.3 | 1594993.5 | 510903.8 | 9361 | 1.64041666667 | 15150 |
| 014017 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:24am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594991.4 | 510904.3 | 9363 | 1.64041666667 | 14017 |
| 013404 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:25am | Sensor | 1797-S0008-G-TJV.cor | 6823.2 | 1594988.8 | 510904.6 | 9365 | 1.64041666667 | 13404 |
| 013011 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:26am | Sensor | 1797-S0008-G-TJV.cor | 6823.0 | 1594985.5 | 510904.5 | 9367 | 1.64041666667 | 13011 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 012732 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:27am | Sensor | 1797-S0008-G-TJV.cor | 6822.8 | 1594982.9 | 510903.0 | 9369 | 1.64041666667 | 12732 |
| 015993 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:28am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594979.8 | 510901.2 | 9371 | 1.64041666667 | 15993 |
| 013778 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:29am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594978.2 | 510899.8 | 9373 | 1.64041666667 | 13778 |
| 013494 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:30am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1594976.1 | 510898.2 | 9375 | 1.64041666667 | 13494 |
| 013153 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:31am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594974.4 | 510896.5 | 9377 | 1.64041666667 | 13153 |
| 015138 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:32am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1594972.9 | 510894.7 | 9379 | 1.64041666667 | 15138 |
| 014164 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:33am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594972.0 | 510893.2 | 9381 | 1.64041666667 | 14164 |
| 013051 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:34am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594971.7 | 510892.5 | 9383 | 1.64041666667 | 13051 |
| 012172 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:35am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1594971.5 | 510892.0 | 9385 | 1.64041666667 | 12172 |
| 014353 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:36am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594970.8 | 510890.4 | 9387 | 1.64041666667 | 14353 |
| 012348 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:37am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594969.6 | 510888.4 | 9389 | 1.64041666667 | 12348 |
| 011247 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:38am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1594968.7 | 510885.7 | 9391 | 1.64041666667 | 11247 |
| 015021 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:39am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594968.0 | 510883.7 | 9393 | 1.64041666667 | 15021 |
| 013835 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:40am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594967.3 | 510881.6 | 9395 | 1.64041666667 | 13835 |
| 012338 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:41am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594966.9 | 510880.6 | 9397 | 1.64041666667 | 12338 |
| 012864 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:42am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594967.5 | 510879.9 | 9399 | 1.64041666667 | 12864 |
| 013626 | 0 | GeoXH 6000 | 08/19/2015 | 11:00:43am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1594968.8 | 510880.2 | 9401 | 1.64041666667 | 13626 |
| 023710 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:27am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1595026.1 | 510858.0 | 9979 | 1.64041666667 | 23710 |
| 025007 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:27am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1595026.1 | 510858.0 | 9980 | 1.64041666667 | 25007 |
| 025931 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:28am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1595026.1 | 510858.0 | 9981 | 1.64041666667 | 25931 |
| 026943 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:29am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1595026.1 | 510858.0 | 9982 | 1.64041666667 | 26943 |
| 025425 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:30am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1595026.1 | 510858.1 | 9983 | 1.64041666667 | 25425 |
| 024836 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:31am | Sensor | 1797-S0008-G-TJV.cor | 6822.7 | 1595026.1 | 510858.1 | 9984 | 1.64041666667 | 24836 |
| 023849 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:32am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1595026.1 | 510858.1 | 9985 | 1.64041666667 | 23849 |
| 026812 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:33am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1595026.1 | 510858.1 | 9986 | 1.64041666667 | 26812 |
| 025946 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:34am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1595026.1 | 510858.1 | 9987 | 1.64041666667 | 25946 |
| 026988 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:35am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1595026.1 | 510858.1 | 9988 | 1.64041666667 | 26988 |
| 027327 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:36am | Sensor | 1797-S0008-G-TJV.cor | 6822.6 | 1595026.1 | 510858.1 | 9989 | 1.64041666667 | 27327 |
| 026601 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:37am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1595026.1 | 510858.1 | 9990 | 1.64041666667 | 26601 |
| 028640 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:38am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1595026.1 | 510858.1 | 9991 | 1.64041666667 | 28640 |
| 024680 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:39am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1595026.1 | 510858.2 | 9992 | 1.64041666667 | 24680 |
| 024020 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:40am | Sensor | 1797-S0008-G-TJV.cor | 6822.5 | 1595026.1 | 510858.2 | 9993 | 1.64041666667 | 24020 |
| 025535 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:41am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1595026.1 | 510858.2 | 9994 | 1.64041666667 | 25535 |
| 025583 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:42am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1595026.1 | 510858.2 | 9995 | 1.64041666667 | 25583 |
| 026256 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:43am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1595026.1 | 510858.2 | 9996 | 1.64041666667 | 26256 |
| 027054 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:44am | Sensor | 1797-S0008-G-TJV.cor | 6822.4 | 1595026.1 | 510858.2 | 9997 | 1.64041666667 | 27054 |
| 024763 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:45am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1595026.2 | 510858.2 | 9998 | 1.64041666667 | 24763 |
| 024581 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:46am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1595026.2 | 510858.2 | 9999 | 1.64041666667 | 24581 |
| 028435 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:47am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1595026.2 | 510858.2 | 10000 | 1.64041666667 | 28435 |
| 025708 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:48am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1595026.2 | 510858.2 | 10001 | 1.64041666667 | 25708 |
| 026587 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:49am | Sensor | 1797-S0008-G-TJV.cor | 6822.3 | 1595026.2 | 510858.3 | 10002 | 1.64041666667 | 26587 |
| 026446 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:50am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1595026.2 | 510858.3 | 10003 | 1.64041666667 | 26446 |
| 025331 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:51am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1595026.2 | 510858.3 | 10004 | 1.64041666667 | 25331 |
| 024243 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:52am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1595026.2 | 510858.3 | 10005 | 1.64041666667 | 24243 |
| 024510 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:53am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1595026.2 | 510858.3 | 10006 | 1.64041666667 | 24510 |
| 025837 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:54am | Sensor | 1797-S0008-G-TJV.cor | 6822.2 | 1595026.2 | 510858.3 | 10007 | 1.64041666667 | 25837 |
| 026169 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:55am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1595026.2 | 510858.3 | 10008 | 1.64041666667 | 26169 |
| 024152 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:56am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1595026.2 | 510858.3 | 10009 | 1.64041666667 | 24152 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 025928 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:57am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1595026.2 | 510858.3 | 10010 | 1.64041666667 | 25928 |
| 025772 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:58am | Sensor | 1797-S0008-G-TJV.cor | 6822.1 | 1595026.2 | 510858.4 | 10011 | 1.64041666667 | 25772 |
| 026063 | 0 | GeoXH 6000 | 08/19/2015 | 11:10:59am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1595026.2 | 510858.4 | 10012 | 1.64041666667 | 26063 |
| 024791 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:00am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1595026.2 | 510858.4 | 10013 | 1.64041666667 | 24791 |
| 025614 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:01am | Sensor | 1797-S0008-G-TJV.cor | 6822.0 | 1595026.2 | 510858.4 | 10014 | 1.64041666667 | 25614 |
| 027973 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:05am | Sensor | 1797-S0008-G-TJV.cor | 6821.9 | 1595026.2 | 510858.4 | 10015 | 1.64041666667 | 27973 |
| 025893 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:06am | Sensor | 1797-S0008-G-TJV.cor | 6819.7 | 1595026.3 | 510858.0 | 10017 | 1.64041666667 | 25893 |
| 023753 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:07am | Sensor | 1797-S0008-G-TJV.cor | 6816.3 | 1595026.9 | 510857.5 | 10020 | 1.64041666667 | 23753 |
| 026098 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:08am | Sensor | 1797-S0008-G-TJV.cor | 6816.5 | 1595027.2 | 510859.0 | 10022 | 1.64041666667 | 26098 |
| 025364 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:09am | Sensor | 1797-S0008-G-TJV.cor | 6816.2 | 1595026.3 | 510860.5 | 10024 | 1.64041666667 | 25364 |
| 026231 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:10am | Sensor | 1797-S0008-G-TJV.cor | 6815.3 | 1595027.3 | 510859.5 | 10026 | 1.64041666667 | 26231 |
| 025367 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:11am | Sensor | 1797-S0008-G-TJV.cor | 6815.2 | 1595027.3 | 510859.6 | 10028 | 1.64041666667 | 25367 |
| 025151 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:12am | Sensor | 1797-S0008-G-TJV.cor | 6815.5 | 1595027.2 | 510859.8 | 10030 | 1.64041666667 | 25151 |
| 024828 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:13am | Sensor | 1797-S0008-G-TJV.cor | 6815.2 | 1595027.1 | 510860.1 | 10032 | 1.64041666667 | 24828 |
| 022857 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:14am | Sensor | 1797-S0008-G-TJV.cor | 6815.0 | 1595027.0 | 510860.5 | 10034 | 1.64041666667 | 22857 |
| 026864 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:15am | Sensor | 1797-S0008-G-TJV.cor | 6816.1 | 1595027.0 | 510860.1 | 10036 | 1.64041666667 | 26864 |
| 025736 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:16am | Sensor | 1797-S0008-G-TJV.cor | 6816.2 | 1595026.9 | 510860.2 | 10038 | 1.64041666667 | 25736 |
| 025274 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:17am | Sensor | 1797-S0008-G-TJV.cor | 6816.3 | 1595026.9 | 510860.3 | 10040 | 1.64041666667 | 25274 |
| 025488 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:18am | Sensor | 1797-S0008-G-TJV.cor | 6816.3 | 1595026.9 | 510860.4 | 10042 | 1.64041666667 | 25488 |
| 024822 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:19am | Sensor | 1797-S0008-G-TJV.cor | 6816.2 | 1595026.9 | 510860.3 | 10044 | 1.64041666667 | 24822 |
| 024085 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:20am | Sensor | 1797-S0008-G-TJV.cor | 6816.2 | 1595027.0 | 510860.3 | 10046 | 1.64041666667 | 24085 |
| 025011 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:21am | Sensor | 1797-S0008-G-TJV.cor | 6816.2 | 1595027.0 | 510860.3 | 10048 | 1.64041666667 | 25011 |
| 026262 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:22am | Sensor | 1797-S0008-G-TJV.cor | 6816.2 | 1595027.1 | 510860.3 | 10050 | 1.64041666667 | 26262 |
| 025645 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:23am | Sensor | 1797-S0008-G-TJV.cor | 6816.2 | 1595027.1 | 510860.2 | 10052 | 1.64041666667 | 25645 |
| 024381 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:24am | Sensor | 1797-S0008-G-TJV.cor | 6816.3 | 1595027.1 | 510860.3 | 10054 | 1.64041666667 | 24381 |
| 024395 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:25am | Sensor | 1797-S0008-G-TJV.cor | 6816.4 | 1595027.1 | 510860.3 | 10056 | 1.64041666667 | 24395 |
| 025448 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:26am | Sensor | 1797-S0008-G-TJV.cor | 6816.4 | 1595027.1 | 510860.3 | 10058 | 1.64041666667 | 25448 |
| 025022 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:27am | Sensor | 1797-S0008-G-TJV.cor | 6816.4 | 1595027.1 | 510860.3 | 10060 | 1.64041666667 | 25022 |
| 025605 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:28am | Sensor | 1797-S0008-G-TJV.cor | 6816.5 | 1595027.0 | 510860.3 | 10062 | 1.64041666667 | 25605 |
| 026231 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:29am | Sensor | 1797-S0008-G-TJV.cor | 6816.5 | 1595027.0 | 510860.4 | 10064 | 1.64041666667 | 26231 |
| 026058 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:30am | Sensor | 1797-S0008-G-TJV.cor | 6816.5 | 1595027.0 | 510860.4 | 10066 | 1.64041666667 | 26058 |
| 026404 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:31am | Sensor | 1797-S0008-G-TJV.cor | 6816.6 | 1595027.0 | 510860.5 | 10068 | 1.64041666667 | 26404 |
| 025021 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:32am | Sensor | 1797-S0008-G-TJV.cor | 6816.6 | 1595027.0 | 510860.5 | 10070 | 1.64041666667 | 25021 |
| 024315 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:33am | Sensor | 1797-S0008-G-TJV.cor | 6816.6 | 1595027.0 | 510860.4 | 10072 | 1.64041666667 | 24315 |
| 025698 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:34am | Sensor | 1797-S0008-G-TJV.cor | 6816.6 | 1595027.0 | 510860.3 | 10074 | 1.64041666667 | 25698 |
| 025114 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:35am | Sensor | 1797-S0008-G-TJV.cor | 6816.6 | 1595027.0 | 510860.3 | 10076 | 1.64041666667 | 25114 |
| 026348 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:36am | Sensor | 1797-S0008-G-TJV.cor | 6816.7 | 1595027.0 | 510860.3 | 10078 | 1.64041666667 | 26348 |
| 025427 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:37am | Sensor | 1797-S0008-G-TJV.cor | 6816.6 | 1595027.0 | 510860.2 | 10080 | 1.64041666667 | 25427 |
| 027476 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:38am | Sensor | 1797-S0008-G-TJV.cor | 6816.7 | 1595027.0 | 510860.2 | 10082 | 1.64041666667 | 27476 |
| 026009 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:39am | Sensor | 1797-S0008-G-TJV.cor | 6816.7 | 1595027.0 | 510860.1 | 10084 | 1.64041666667 | 26009 |
| 025252 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:40am | Sensor | 1797-S0008-G-TJV.cor | 6816.7 | 1595027.0 | 510860.1 | 10086 | 1.64041666667 | 25252 |
| 025603 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:41am | Sensor | 1797-S0008-G-TJV.cor | 6816.8 | 1595027.0 | 510860.1 | 10088 | 1.64041666667 | 25603 |
| 025120 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:42am | Sensor | 1797-S0008-G-TJV.cor | 6816.9 | 1595027.0 | 510860.1 | 10090 | 1.64041666667 | 25120 |
| 025330 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:43am | Sensor | 1797-S0008-G-TJV.cor | 6817.0 | 1595027.0 | 510860.1 | 10092 | 1.64041666667 | 25330 |
| 023942 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:44am | Sensor | 1797-S0008-G-TJV.cor | 6817.1 | 1595027.1 | 510860.1 | 10094 | 1.64041666667 | 23942 |
| 024825 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:45am | Sensor | 1797-S0008-G-TJV.cor | 6817.2 | 1595027.1 | 510860.1 | 10096 | 1.64041666667 | 24825 |
| 025196 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:46am | Sensor | 1797-S0008-G-TJV.cor | 6817.3 | 1595027.1 | 510860.1 | 10098 | 1.64041666667 | 25196 |
| 023609 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:47am | Sensor | 1797-S0008-G-TJV.cor | 6817.3 | 1595027.1 | 510860.0 | 10100 | 1.64041666667 | 23609 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 025372 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:48am | Sensor | 1797-S0008-G-TJV.cor | 6817.4 | 1595027.1 | 510860.1 | 10102 | 1.64041666667 | 25372 |
| 025393 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:49am | Sensor | 1797-S0008-G-TJV.cor | 6817.4 | 1595027.1 | 510860.1 | 10104 | 1.64041666667 | 25393 |
| 025068 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:50am | Sensor | 1797-S0008-G-TJV.cor | 6817.5 | 1595027.1 | 510860.1 | 10106 | 1.64041666667 | 25068 |
| 027417 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:51am | Sensor | 1797-S0008-G-TJV.cor | 6817.5 | 1595027.1 | 510860.0 | 10108 | 1.64041666667 | 27417 |
| 024794 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:52am | Sensor | 1797-S0008-G-TJV.cor | 6817.6 | 1595027.1 | 510860.0 | 10110 | 1.64041666667 | 24794 |
| 026118 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:53am | Sensor | 1797-S0008-G-TJV.cor | 6817.6 | 1595027.1 | 510860.1 | 10112 | 1.64041666667 | 26118 |
| 024199 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:54am | Sensor | 1797-S0008-G-TJV.cor | 6817.7 | 1595027.1 | 510860.0 | 10114 | 1.64041666667 | 24199 |
| 023539 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:55am | Sensor | 1797-S0008-G-TJV.cor | 6817.7 | 1595027.1 | 510860.0 | 10116 | 1.64041666667 | 23539 |
| 025475 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:56am | Sensor | 1797-S0008-G-TJV.cor | 6817.8 | 1595027.2 | 510860.0 | 10118 | 1.64041666667 | 25475 |
| 024818 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:57am | Sensor | 1797-S0008-G-TJV.cor | 6817.8 | 1595027.2 | 510860.0 | 10120 | 1.64041666667 | 24818 |
| 024624 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:58am | Sensor | 1797-S0008-G-TJV.cor | 6817.8 | 1595027.2 | 510859.9 | 10122 | 1.64041666667 | 24624 |
| 024846 | 0 | GeoXH 6000 | 08/19/2015 | 11:11:59am | Sensor | 1797-S0008-G-TJV.cor | 6817.8 | 1595027.2 | 510859.9 | 10124 | 1.64041666667 | 24846 |
| 025501 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:00am | Sensor | 1797-S0008-G-TJV.cor | 6817.9 | 1595027.2 | 510859.9 | 10126 | 1.64041666667 | 25501 |
| 025515 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:01am | Sensor | 1797-S0008-G-TJV.cor | 6818.0 | 1595027.2 | 510859.9 | 10128 | 1.64041666667 | 25515 |
| 025278 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:02am | Sensor | 1797-S0008-G-TJV.cor | 6818.0 | 1595027.2 | 510859.9 | 10130 | 1.64041666667 | 25278 |
| 025819 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:03am | Sensor | 1797-S0008-G-TJV.cor | 6817.7 | 1595026.9 | 510860.1 | 10132 | 1.64041666667 | 25819 |
| 025535 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:04am | Sensor | 1797-S0008-G-TJV.cor | 6816.8 | 1595026.2 | 510860.2 | 10134 | 1.64041666667 | 25535 |
| 026063 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:05am | Sensor | 1797-S0008-G-TJV.cor | 6816.6 | 1595026.2 | 510860.0 | 10136 | 1.64041666667 | 26063 |
| 025746 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:06am | Sensor | 1797-S0008-G-TJV.cor | 6816.7 | 1595026.1 | 510860.6 | 10138 | 1.64041666667 | 25746 |
| 024436 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:07am | Sensor | 1797-S0008-G-TJV.cor | 6816.7 | 1595026.1 | 510860.5 | 10140 | 1.64041666667 | 24436 |
| 026029 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:08am | Sensor | 1797-S0008-G-TJV.cor | 6816.7 | 1595026.1 | 510860.6 | 10142 | 1.64041666667 | 26029 |
| 023577 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:09am | Sensor | 1797-S0008-G-TJV.cor | 6816.6 | 1595026.0 | 510860.6 | 10144 | 1.64041666667 | 23577 |
| 025034 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:10am | Sensor | 1797-S0008-G-TJV.cor | 6816.7 | 1595026.2 | 510860.5 | 10146 | 1.64041666667 | 25034 |
| 026328 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:11am | Sensor | 1797-S0008-G-TJV.cor | 6816.5 | 1595026.2 | 510860.1 | 10148 | 1.64041666667 | 26328 |
| 025872 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:12am | Sensor | 1797-S0008-G-TJV.cor | 6816.9 | 1595026.5 | 510859.8 | 10150 | 1.64041666667 | 25872 |
| 026178 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:13am | Sensor | 1797-S0008-G-TJV.cor | 6818.0 | 1595027.0 | 510859.7 | 10152 | 1.64041666667 | 26178 |
| 026074 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:14am | Sensor | 1797-S0008-G-TJV.cor | 6817.6 | 1595027.2 | 510859.9 | 10154 | 1.64041666667 | 26074 |
| 024038 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:15am | Sensor | 1797-S0008-G-TJV.cor | 6817.4 | 1595027.6 | 510860.4 | 10156 | 1.64041666667 | 24038 |
| 025239 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:16am | Sensor | 1797-S0008-G-TJV.cor | 6817.2 | 1595028.3 | 510860.6 | 10158 | 1.64041666667 | 25239 |
| 026890 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:17am | Sensor | 1797-S0008-G-TJV.cor | 6817.4 | 1595028.3 | 510860.6 | 10160 | 1.64041666667 | 26890 |
| 024722 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:18am | Sensor | 1797-S0008-G-TJV.cor | 6817.6 | 1595028.3 | 510860.6 | 10162 | 1.64041666667 | 24722 |
| 027120 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:19am | Sensor | 1797-S0008-G-TJV.cor | 6817.8 | 1595028.4 | 510860.7 | 10164 | 1.64041666667 | 27120 |
| 026880 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:20am | Sensor | 1797-S0008-G-TJV.cor | 6817.9 | 1595028.4 | 510860.7 | 10166 | 1.64041666667 | 26880 |
| 025680 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:21am | Sensor | 1797-S0008-G-TJV.cor | 6818.0 | 1595028.4 | 510860.8 | 10168 | 1.64041666667 | 25680 |
| 024120 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:22am | Sensor | 1797-S0008-G-TJV.cor | 6818.2 | 1595028.4 | 510860.8 | 10170 | 1.64041666667 | 24120 |
| 023460 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:23am | Sensor | 1797-S0008-G-TJV.cor | 6818.3 | 1595028.4 | 510860.9 | 10172 | 1.64041666667 | 23460 |
| 024105 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:24am | Sensor | 1797-S0008-G-TJV.cor | 6818.4 | 1595028.4 | 510860.9 | 10174 | 1.64041666667 | 24105 |
| 026726 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:25am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.5 | 510861.0 | 10176 | 1.64041666667 | 26726 |
| 025281 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:26am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.5 | 510861.0 | 10178 | 1.64041666667 | 25281 |
| 024080 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:27am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.5 | 510861.0 | 10180 | 1.64041666667 | 24080 |
| 024290 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:28am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.5 | 510861.0 | 10182 | 1.64041666667 | 24290 |
| 026712 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:29am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.5 | 510861.0 | 10184 | 1.64041666667 | 26712 |
| 027138 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:30am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.5 | 510861.0 | 10185 | 1.64041666667 | 27138 |
| 027154 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:31am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.5 | 510861.1 | 10186 | 1.64041666667 | 27154 |
| 026108 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:32am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1595028.5 | 510861.1 | 10187 | 1.64041666667 | 26108 |
| 025217 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:33am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.4 | 510861.2 | 10188 | 1.64041666667 | 25217 |
| 024454 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:34am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.4 | 510861.2 | 10189 | 1.64041666667 | 24454 |
| 025253 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:35am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.4 | 510861.2 | 10190 | 1.64041666667 | 25253 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 025693 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:36am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.4 | 510861.2 | 10191 | 1.64041666667 | 25693 |
| 026583 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:37am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.4 | 510861.2 | 10192 | 1.64041666667 | 26583 |
| 026595 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:38am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.4 | 510861.2 | 10193 | 1.64041666667 | 26595 |
| 025908 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:39am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.4 | 510861.2 | 10194 | 1.64041666667 | 25908 |
| 024267 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:40am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.4 | 510861.2 | 10195 | 1.64041666667 | 24267 |
| 026917 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:41am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.4 | 510861.3 | 10196 | 1.64041666667 | 26917 |
| 025959 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:42am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.4 | 510861.3 | 10197 | 1.64041666667 | 25959 |
| 024639 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:43am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.4 | 510861.3 | 10198 | 1.64041666667 | 24639 |
| 024520 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:44am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.3 | 510861.3 | 10199 | 1.64041666667 | 24520 |
| 025840 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:45am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.3 | 510861.3 | 10200 | 1.64041666667 | 25840 |
| 026620 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:46am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.3 | 510861.3 | 10201 | 1.64041666667 | 26620 |
| 026245 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:47am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.3 | 510861.3 | 10202 | 1.64041666667 | 26245 |
| 025911 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:48am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.3 | 510861.3 | 10203 | 1.64041666667 | 25911 |
| 027717 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:49am | Sensor | 1797-S0008-G-TJV.cor | 6818.9 | 1595028.3 | 510861.3 | 10204 | 1.64041666667 | 27717 |
| 025919 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:50am | Sensor | 1797-S0008-G-TJV.cor | 6819.0 | 1595028.3 | 510861.2 | 10205 | 1.64041666667 | 25919 |
| 025830 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:51am | Sensor | 1797-S0008-G-TJV.cor | 6819.0 | 1595028.3 | 510861.3 | 10206 | 1.64041666667 | 25830 |
| 028087 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:52am | Sensor | 1797-S0008-G-TJV.cor | 6819.1 | 1595028.3 | 510861.3 | 10207 | 1.64041666667 | 28087 |
| 025683 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:53am | Sensor | 1797-S0008-G-TJV.cor | 6819.1 | 1595028.3 | 510861.3 | 10208 | 1.64041666667 | 25683 |
| 027450 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:54am | Sensor | 1797-S0008-G-TJV.cor | 6819.0 | 1595028.3 | 510861.2 | 10209 | 1.64041666667 | 27450 |
| 027202 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:55am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.3 | 510861.2 | 10210 | 1.64041666667 | 27202 |
| 027290 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:56am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.3 | 510861.2 | 10211 | 1.64041666667 | 27290 |
| 024132 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:57am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.3 | 510861.2 | 10212 | 1.64041666667 | 24132 |
| 025593 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:58am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.3 | 510861.2 | 10213 | 1.64041666667 | 25593 |
| 025568 | 0 | GeoXH 6000 | 08/19/2015 | 11:12:59am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.3 | 510861.1 | 10214 | 1.64041666667 | 25568 |
| 025562 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:00am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.3 | 510861.0 | 10215 | 1.64041666667 | 25562 |
| 024270 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:01am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.3 | 510860.9 | 10216 | 1.64041666667 | 24270 |
| 025477 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:02am | Sensor | 1797-S0008-G-TJV.cor | 6818.8 | 1595028.3 | 510860.9 | 10217 | 1.64041666667 | 25477 |
| 026979 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:03am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1595028.3 | 510860.8 | 10218 | 1.64041666667 | 26979 |
| 026695 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:04am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1595028.3 | 510860.8 | 10219 | 1.64041666667 | 26695 |
| 026383 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:05am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1595028.2 | 510860.7 | 10220 | 1.64041666667 | 26383 |
| 024986 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:06am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1595028.2 | 510860.7 | 10221 | 1.64041666667 | 24986 |
| 024966 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:07am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1595028.2 | 510860.7 | 10222 | 1.64041666667 | 24966 |
| 024151 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:08am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1595028.2 | 510860.7 | 10223 | 1.64041666667 | 24151 |
| 025507 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:09am | Sensor | 1797-S0008-G-TJV.cor | 6818.7 | 1595028.2 | 510860.6 | 10224 | 1.64041666667 | 25507 |
| 027377 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:10am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.1 | 510860.6 | 10225 | 1.64041666667 | 27377 |
| 026284 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:11am | Sensor | 1797-S0008-G-TJV.cor | 6817.9 | 1595028.2 | 510860.3 | 10226 | 1.64041666667 | 26284 |
| 025385 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:20am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.0 | 510860.5 | 10232 | 1.64041666667 | 25385 |
| 026026 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:20am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.0 | 510860.5 | 10233 | 1.64041666667 | 26026 |
| 025496 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:20am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.0 | 510860.5 | 10234 | 1.64041666667 | 25496 |
| 025694 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:21am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.0 | 510860.5 | 10235 | 1.64041666667 | 25694 |
| 023463 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:22am | Sensor | 1797-S0008-G-TJV.cor | 6818.6 | 1595028.0 | 510860.5 | 10236 | 1.64041666667 | 23463 |
| 024975 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:23am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.0 | 510860.4 | 10237 | 1.64041666667 | 24975 |
| 027633 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:24am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.0 | 510860.4 | 10238 | 1.64041666667 | 27633 |
| 026318 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:25am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.0 | 510860.4 | 10239 | 1.64041666667 | 26318 |
| 025719 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:26am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.0 | 510860.4 | 10240 | 1.64041666667 | 25719 |
| 025420 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:27am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.0 | 510860.4 | 10241 | 1.64041666667 | 25420 |
| 023995 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:28am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.0 | 510860.4 | 10242 | 1.64041666667 | 23995 |
| 024328 | 0 | GeoXH 6000 | 08/19/2015 | 11:13:29am | Sensor | 1797-S0008-G-TJV.cor | 6818.5 | 1595028.0 | 510860.4 | 10243 | 1.64041666667 | 24328 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 025001 | 0 | GeoXH 6000 | 08/19/2015 | 11:22:53am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.8 | 10292 | 1.64041666667 | 25001 |
| 024370 | 0 | GeoXH 6000 | 08/19/2015 | 11:22:54am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.8 | 10293 | 1.64041666667 | 24370 |
| 025592 | 0 | GeoXH 6000 | 08/19/2015 | 11:22:55am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.8 | 10294 | 1.64041666667 | 25592 |
| 024728 | 0 | GeoXH 6000 | 08/19/2015 | 11:22:56am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.7 | 10295 | 1.64041666667 | 24728 |
| 025622 | 0 | GeoXH 6000 | 08/19/2015 | 11:22:57am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.7 | 10296 | 1.64041666667 | 25622 |
| 026085 | 0 | GeoXH 6000 | 08/19/2015 | 11:22:58am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.7 | 10297 | 1.64041666667 | 26085 |
| 025181 | 0 | GeoXH 6000 | 08/19/2015 | 11:22:59am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.7 | 10298 | 1.64041666667 | 25181 |
| 024865 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:00am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.7 | 10299 | 1.64041666667 | 24865 |
| 024516 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:01am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.7 | 510853.7 | 10300 | 1.64041666667 | 24516 |
| 023469 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:02am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595027.7 | 510853.7 | 10301 | 1.64041666667 | 23469 |
| 024737 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:03am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595027.7 | 510853.7 | 10302 | 1.64041666667 | 24737 |
| 025024 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:04am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595027.7 | 510853.6 | 10303 | 1.64041666667 | 25024 |
| 024046 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:05am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595027.7 | 510853.6 | 10305 | 1.64041666667 | 24046 |
| 026381 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:06am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595027.8 | 510853.4 | 10307 | 1.64041666667 | 26381 |
| 026845 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:07am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595027.8 | 510853.2 | 10309 | 1.64041666667 | 26845 |
| 025671 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:08am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595027.9 | 510853.1 | 10311 | 1.64041666667 | 25671 |
| 026157 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:09am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595027.9 | 510853.0 | 10313 | 1.64041666667 | 26157 |
| 024329 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:10am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595027.9 | 510852.9 | 10315 | 1.64041666667 | 24329 |
| 025822 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:11am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595027.9 | 510852.8 | 10317 | 1.64041666667 | 25822 |
| 026315 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:12am | Sensor | 1797-S0008-G-TJV.cor | 6812.4 | 1595028.0 | 510852.6 | 10319 | 1.64041666667 | 26315 |
| 025688 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:13am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595028.0 | 510852.6 | 10321 | 1.64041666667 | 25688 |
| 024452 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:14am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595028.0 | 510852.5 | 10323 | 1.64041666667 | 24452 |
| 024953 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:15am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595028.1 | 510852.4 | 10325 | 1.64041666667 | 24953 |
| 025498 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:16am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595028.1 | 510852.4 | 10327 | 1.64041666667 | 25498 |
| 024974 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:17am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595028.1 | 510852.2 | 10329 | 1.64041666667 | 24974 |
| 024183 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:18am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595028.1 | 510852.3 | 10331 | 1.64041666667 | 24183 |
| 024915 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:19am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595028.1 | 510852.3 | 10333 | 1.64041666667 | 24915 |
| 025668 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:20am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595028.1 | 510852.3 | 10335 | 1.64041666667 | 25668 |
| 024807 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:21am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595028.1 | 510852.2 | 10337 | 1.64041666667 | 24807 |
| 026812 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:22am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595028.2 | 510852.1 | 10339 | 1.64041666667 | 26812 |
| 026323 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:23am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595028.2 | 510852.1 | 10341 | 1.64041666667 | 26323 |
| 024430 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:24am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595028.2 | 510851.8 | 10343 | 1.64041666667 | 24430 |
| 024677 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:25am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595028.2 | 510851.7 | 10345 | 1.64041666667 | 24677 |
| 023749 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:26am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595028.3 | 510851.5 | 10347 | 1.64041666667 | 23749 |
| 024537 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:27am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595028.3 | 510851.3 | 10349 | 1.64041666667 | 24537 |
| 023504 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:28am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595028.4 | 510851.2 | 10351 | 1.64041666667 | 23504 |
| 025976 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:29am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595028.4 | 510851.1 | 10353 | 1.64041666667 | 25976 |
| 025244 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:30am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595028.4 | 510851.0 | 10355 | 1.64041666667 | 25244 |
| 024581 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:31am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595028.5 | 510850.8 | 10357 | 1.64041666667 | 24581 |
| 026605 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:32am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595028.5 | 510850.8 | 10359 | 1.64041666667 | 26605 |
| 025911 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:33am | Sensor | 1797-S0008-G-TJV.cor | 6812.9 | 1595028.6 | 510851.1 | 10361 | 1.64041666667 | 25911 |
| 028137 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:34am | Sensor | 1797-S0008-G-TJV.cor | 6812.3 | 1595028.5 | 510853.1 | 10363 | 1.64041666667 | 28137 |
| 025874 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:35am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595027.7 | 510853.5 | 10365 | 1.64041666667 | 25874 |
| 025488 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:36am | Sensor | 1797-S0008-G-TJV.cor | 6812.4 | 1595026.8 | 510856.2 | 10367 | 1.64041666667 | 25488 |
| 025242 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:37am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595026.7 | 510856.2 | 10369 | 1.64041666667 | 25242 |
| 025900 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:38am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595026.8 | 510856.4 | 10371 | 1.64041666667 | 25900 |
| 023665 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:39am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595026.8 | 510856.2 | 10373 | 1.64041666667 | 23665 |
| 026526 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:40am | Sensor | 1797-S0008-G-TJV.cor | 6812.5 | 1595026.9 | 510856.1 | 10376 | 1.64041666667 | 26526 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 025201 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:41am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595026.9 | 510856.1 | 10378 | 1.64041666667 | 25201 |
| 023490 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:42am | Sensor | 1797-S0008-G-TJV.cor | 6812.6 | 1595026.9 | 510856.1 | 10380 | 1.64041666667 | 23490 |
| 026002 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:43am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595026.9 | 510856.1 | 10382 | 1.64041666667 | 26002 |
| 025880 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:44am | Sensor | 1797-S0008-G-TJV.cor | 6812.7 | 1595026.9 | 510856.0 | 10384 | 1.64041666667 | 25880 |
| 025790 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:45am | Sensor | 1797-S0008-G-TJV.cor | 6812.8 | 1595027.0 | 510856.0 | 10386 | 1.64041666667 | 25790 |
| 025167 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:46am | Sensor | 1797-S0008-G-TJV.cor | 6812.9 | 1595027.0 | 510856.0 | 10388 | 1.64041666667 | 25167 |
| 023992 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:47am | Sensor | 1797-S0008-G-TJV.cor | 6813.0 | 1595027.0 | 510855.9 | 10390 | 1.64041666667 | 23992 |
| 025288 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:48am | Sensor | 1797-S0008-G-TJV.cor | 6813.1 | 1595027.0 | 510856.1 | 10392 | 1.64041666667 | 25288 |
| 026422 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:49am | Sensor | 1797-S0008-G-TJV.cor | 6813.1 | 1595027.0 | 510855.9 | 10394 | 1.64041666667 | 26422 |
| 024845 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:50am | Sensor | 1797-S0008-G-TJV.cor | 6813.2 | 1595027.1 | 510855.9 | 10396 | 1.64041666667 | 24845 |
| 026671 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:51am | Sensor | 1797-S0008-G-TJV.cor | 6813.2 | 1595027.1 | 510855.9 | 10398 | 1.64041666667 | 26671 |
| 027097 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:52am | Sensor | 1797-S0008-G-TJV.cor | 6813.3 | 1595027.1 | 510855.9 | 10400 | 1.64041666667 | 27097 |
| 025374 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:53am | Sensor | 1797-S0008-G-TJV.cor | 6813.4 | 1595027.1 | 510855.9 | 10402 | 1.64041666667 | 25374 |
| 025753 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:54am | Sensor | 1797-S0008-G-TJV.cor | 6813.4 | 1595027.1 | 510855.9 | 10404 | 1.64041666667 | 25753 |
| 028788 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:55am | Sensor | 1797-S0008-G-TJV.cor | 6813.5 | 1595027.1 | 510855.9 | 10406 | 1.64041666667 | 28788 |
| 025827 | 0 | GeoXH 6000 | 08/19/2015 | 11:23:56am | Sensor | 1797-S0008-G-TJV.cor | 6813.6 | 1595027.1 | 510856.0 | 10409 | 1.64041666667 | 25827 |
| 012794 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:27am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.1 | 512350.3 | 1095 | 1.64041666667 | 12794 |
| 014538 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:28am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.2 | 512350.2 | 1098 | 1.64041666667 | 14538 |
| 014914 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:29am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.2 | 512350.2 | 1100 | 1.64041666667 | 14914 |
| 014168 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:30am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.2 | 512350.2 | 1102 | 1.64041666667 | 14168 |
| 013262 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:31am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.2 | 512350.2 | 1104 | 1.64041666667 | 13262 |
| 014475 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:32am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.2 | 512350.2 | 1106 | 1.64041666667 | 14475 |
| 014538 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:33am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.2 | 512350.2 | 1108 | 1.64041666667 | 14538 |
| 013264 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:34am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.1 | 1110 | 1.64041666667 | 13264 |
| 012886 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:35am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.1 | 1112 | 1.64041666667 | 12886 |
| 013571 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:36am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.1 | 1114 | 1.64041666667 | 13571 |
| 013533 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:37am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.1 | 1116 | 1.64041666667 | 13533 |
| 012953 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:38am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.2 | 1118 | 1.64041666667 | 12953 |
| 013108 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:39am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.1 | 1120 | 1.64041666667 | 13108 |
| 013597 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:40am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.2 | 512350.2 | 1122 | 1.64041666667 | 13597 |
| 013599 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:41am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.1 | 1124 | 1.64041666667 | 13599 |
| 013299 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:42am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.0 | 1126 | 1.64041666667 | 13299 |
| 013405 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:43am | Sensor | 1797-S0002-G-TJV.cor | 6849.1 | 1596623.2 | 512350.0 | 1128 | 1.64041666667 | 13405 |
| 013071 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:44am | Sensor | 1797-S0002-G-TJV.cor | 6849.1 | 1596623.2 | 512350.1 | 1130 | 1.64041666667 | 13071 |
| 013107 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:45am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.1 | 1132 | 1.64041666667 | 13107 |
| 012997 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:46am | Sensor | 1797-S0002-G-TJV.cor | 6849.2 | 1596623.2 | 512350.2 | 1134 | 1.64041666667 | 12997 |
| 013629 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:47am | Sensor | 1797-S0002-G-TJV.cor | 6849.3 | 1596623.2 | 512350.1 | 1136 | 1.64041666667 | 13629 |
| 014207 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:48am | Sensor | 1797-S0002-G-TJV.cor | 6849.5 | 1596623.4 | 512350.0 | 1138 | 1.64041666667 | 14207 |
| 015311 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:49am | Sensor | 1797-S0002-G-TJV.cor | 6849.6 | 1596623.4 | 512349.9 | 1140 | 1.64041666667 | 15311 |
| 012768 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:50am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596623.9 | 512349.9 | 1142 | 1.64041666667 | 12768 |
| 013572 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:51am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596624.1 | 512349.9 | 1144 | 1.64041666667 | 13572 |
| 013413 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:52am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596624.3 | 512349.8 | 1146 | 1.64041666667 | 13413 |
| 012113 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:53am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596624.2 | 512349.7 | 1148 | 1.64041666667 | 12113 |
| 012928 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:54am | Sensor | 1797-S0002-G-TJV.cor | 6849.7 | 1596624.1 | 512349.6 | 1150 | 1.64041666667 | 12928 |
| 013372 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:55am | Sensor | 1797-S0002-G-TJV.cor | 6849.6 | 1596624.1 | 512349.5 | 1152 | 1.64041666667 | 13372 |
| 013093 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:56am | Sensor | 1797-S0002-G-TJV.cor | 6849.5 | 1596624.1 | 512349.7 | 1154 | 1.64041666667 | 13093 |
| 014343 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:57am | Sensor | 1797-S0002-G-TJV.cor | 6849.6 | 1596624.0 | 512349.8 | 1156 | 1.64041666667 | 14343 |
| 013515 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:58am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596624.6 | 512349.7 | 1158 | 1.64041666667 | 13515 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013218 | 0 | GeoXH 6000 | 08/20/2015 | 11:48:59am | Sensor | 1797-S0002-G-TJV.cor | 6849.7 | 1596624.7 | 512349.4 | 1160 | 1.64041666667 | 13218 |
| 014164 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:00am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596623.7 | 512348.9 | 1162 | 1.64041666667 | 14164 |
| 014371 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:01am | Sensor | 1797-S0002-G-TJV.cor | 6849.6 | 1596623.6 | 512349.1 | 1164 | 1.64041666667 | 14371 |
| 013042 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:02am | Sensor | 1797-S0002-G-TJV.cor | 6849.6 | 1596623.7 | 512349.0 | 1166 | 1.64041666667 | 13042 |
| 013790 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:03am | Sensor | 1797-S0002-G-TJV.cor | 6849.5 | 1596623.4 | 512349.1 | 1168 | 1.64041666667 | 13790 |
| 013647 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:04am | Sensor | 1797-S0002-G-TJV.cor | 6849.6 | 1596623.4 | 512349.3 | 1170 | 1.64041666667 | 13647 |
| 013522 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:05am | Sensor | 1797-S0002-G-TJV.cor | 6849.6 | 1596624.1 | 512349.1 | 1172 | 1.64041666667 | 13522 |
| 014090 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:06am | Sensor | 1797-S0002-G-TJV.cor | 6849.4 | 1596625.7 | 512347.9 | 1174 | 1.64041666667 | 14090 |
| 012642 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:07am | Sensor | 1797-S0002-G-TJV.cor | 6849.4 | 1596627.5 | 512346.7 | 1176 | 1.64041666667 | 12642 |
| 012280 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:08am | Sensor | 1797-S0002-G-TJV.cor | 6849.5 | 1596629.5 | 512345.3 | 1178 | 1.64041666667 | 12280 |
| 012400 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:09am | Sensor | 1797-S0002-G-TJV.cor | 6849.6 | 1596631.6 | 512344.6 | 1180 | 1.64041666667 | 12400 |
| 012610 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:10am | Sensor | 1797-S0002-G-TJV.cor | 6849.7 | 1596634.1 | 512343.6 | 1182 | 1.64041666667 | 12610 |
| 014132 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:11am | Sensor | 1797-S0002-G-TJV.cor | 6849.7 | 1596636.5 | 512342.8 | 1184 | 1.64041666667 | 14132 |
| 013883 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:12am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596639.3 | 512342.0 | 1186 | 1.64041666667 | 13883 |
| 014960 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:13am | Sensor | 1797-S0002-G-TJV.cor | 6849.9 | 1596641.7 | 512341.2 | 1188 | 1.64041666667 | 14960 |
| 013550 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:14am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596644.3 | 512340.8 | 1190 | 1.64041666667 | 13550 |
| 012147 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:15am | Sensor | 1797-S0002-G-TJV.cor | 6849.7 | 1596647.3 | 512340.2 | 1192 | 1.64041666667 | 12147 |
| 011977 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:16am | Sensor | 1797-S0002-G-TJV.cor | 6849.7 | 1596650.7 | 512339.7 | 1194 | 1.64041666667 | 11977 |
| 012654 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:17am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596653.9 | 512338.9 | 1196 | 1.64041666667 | 12654 |
| 013663 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:18am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596657.1 | 512337.7 | 1198 | 1.64041666667 | 13663 |
| 013196 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:19am | Sensor | 1797-S0002-G-TJV.cor | 6849.9 | 1596660.3 | 512336.8 | 1200 | 1.64041666667 | 13196 |
| 013229 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:20am | Sensor | 1797-S0002-G-TJV.cor | 6849.9 | 1596663.1 | 512336.0 | 1202 | 1.64041666667 | 13229 |
| 016537 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:21am | Sensor | 1797-S0002-G-TJV.cor | 6849.8 | 1596666.5 | 512334.5 | 1204 | 1.64041666667 | 16537 |
| 014874 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:22am | Sensor | 1797-S0002-G-TJV.cor | 6850.1 | 1596668.9 | 512332.1 | 1206 | 1.64041666667 | 14874 |
| 013258 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:23am | Sensor | 1797-S0002-G-TJV.cor | 6850.1 | 1596670.7 | 512329.7 | 1208 | 1.64041666667 | 13258 |
| 013214 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:24am | Sensor | 1797-S0002-G-TJV.cor | 6850.2 | 1596671.5 | 512326.9 | 1210 | 1.64041666667 | 13214 |
| 012903 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:25am | Sensor | 1797-S0002-G-TJV.cor | 6850.3 | 1596672.3 | 512323.9 | 1212 | 1.64041666667 | 12903 |
| 014925 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:26am | Sensor | 1797-S0002-G-TJV.cor | 6850.4 | 1596673.2 | 512321.0 | 1214 | 1.64041666667 | 14925 |
| 014171 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:27am | Sensor | 1797-S0002-G-TJV.cor | 6850.3 | 1596673.4 | 512317.7 | 1216 | 1.64041666667 | 14171 |
| 013683 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:28am | Sensor | 1797-S0002-G-TJV.cor | 6850.5 | 1596673.2 | 512314.0 | 1218 | 1.64041666667 | 13683 |
| 013530 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:29am | Sensor | 1797-S0002-G-TJV.cor | 6850.5 | 1596672.7 | 512311.0 | 1220 | 1.64041666667 | 13530 |
| 014182 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:30am | Sensor | 1797-S0002-G-TJV.cor | 6850.5 | 1596671.7 | 512308.3 | 1222 | 1.64041666667 | 14182 |
| 013355 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:31am | Sensor | 1797-S0002-G-TJV.cor | 6850.8 | 1596670.8 | 512306.0 | 1224 | 1.64041666667 | 13355 |
| 012309 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:32am | Sensor | 1797-S0002-G-TJV.cor | 6851.0 | 1596670.8 | 512303.7 | 1226 | 1.64041666667 | 12309 |
| 011447 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:33am | Sensor | 1797-S0002-G-TJV.cor | 6850.9 | 1596670.8 | 512301.1 | 1228 | 1.64041666667 | 11447 |
| 014921 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:34am | Sensor | 1797-S0002-G-TJV.cor | 6851.0 | 1596671.4 | 512298.3 | 1230 | 1.64041666667 | 14921 |
| 012820 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:35am | Sensor | 1797-S0002-G-TJV.cor | 6851.2 | 1596672.1 | 512296.0 | 1232 | 1.64041666667 | 12820 |
| 016075 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:36am | Sensor | 1797-S0002-G-TJV.cor | 6851.4 | 1596673.4 | 512293.6 | 1234 | 1.64041666667 | 16075 |
| 014248 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:37am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596674.9 | 512291.8 | 1236 | 1.64041666667 | 14248 |
| 013552 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:38am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596676.6 | 512289.4 | 1238 | 1.64041666667 | 13552 |
| 013708 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:39am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596678.5 | 512287.5 | 1240 | 1.64041666667 | 13708 |
| 014527 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:40am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596680.4 | 512285.1 | 1242 | 1.64041666667 | 14527 |
| 015541 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:41am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596681.7 | 512282.1 | 1244 | 1.64041666667 | 15541 |
| 013755 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:42am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596682.7 | 512278.8 | 1246 | 1.64041666667 | 13755 |
| 012318 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:43am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596684.0 | 512276.1 | 1248 | 1.64041666667 | 12318 |
| 013849 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:44am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596685.6 | 512272.9 | 1250 | 1.64041666667 | 13849 |
| 013602 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:45am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596687.0 | 512270.0 | 1252 | 1.64041666667 | 13602 |
| 014530 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:46am | Sensor | 1797-S0002-G-TJV.cor | 6851.4 | 1596688.6 | 512267.3 | 1254 | 1.64041666667 | 14530 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014702 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:47am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596690.1 | 512264.5 | 1256 | 1.64041666667 | 14702 |
| 014685 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:48am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596691.9 | 512261.2 | 1258 | 1.64041666667 | 14685 |
| 014951 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:49am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596693.8 | 512258.3 | 1260 | 1.64041666667 | 14951 |
| 014958 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:50am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.3 | 512255.2 | 1262 | 1.64041666667 | 14958 |
| 014989 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:51am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.9 | 512251.7 | 1264 | 1.64041666667 | 14989 |
| 014787 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:52am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.7 | 512248.2 | 1266 | 1.64041666667 | 14787 |
| 016057 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:53am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.6 | 512244.5 | 1268 | 1.64041666667 | 16057 |
| 015534 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:54am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.6 | 512241.2 | 1270 | 1.64041666667 | 15534 |
| 015583 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:55am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.4 | 512237.8 | 1272 | 1.64041666667 | 15583 |
| 015386 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:56am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.5 | 512234.7 | 1274 | 1.64041666667 | 15386 |
| 015546 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:57am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.7 | 1276 | 1.64041666667 | 15546 |
| 014926 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:58am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.5 | 512233.6 | 1278 | 1.64041666667 | 14926 |
| 015161 | 0 | GeoXH 6000 | 08/20/2015 | 11:49:59am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.5 | 1280 | 1.64041666667 | 15161 |
| 014620 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:00am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.6 | 1282 | 1.64041666667 | 14620 |
| 013195 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:01am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.6 | 1284 | 1.64041666667 | 13195 |
| 013888 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:02am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.6 | 1286 | 1.64041666667 | 13888 |
| 015952 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:03am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.6 | 1288 | 1.64041666667 | 15952 |
| 015118 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:04am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.7 | 1290 | 1.64041666667 | 15118 |
| 014669 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:05am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.7 | 1292 | 1.64041666667 | 14669 |
| 014767 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:06am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.7 | 1294 | 1.64041666667 | 14767 |
| 014491 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:07am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.5 | 512233.5 | 1296 | 1.64041666667 | 14491 |
| 013552 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:08am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512233.5 | 1298 | 1.64041666667 | 13552 |
| 014308 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:09am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.7 | 512233.5 | 1300 | 1.64041666667 | 14308 |
| 014527 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:10am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.5 | 512233.3 | 1302 | 1.64041666667 | 14527 |
| 012511 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:11am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.6 | 512233.2 | 1304 | 1.64041666667 | 12511 |
| 014137 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:12am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.5 | 512233.1 | 1306 | 1.64041666667 | 14137 |
| 013884 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:13am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.1 | 512233.4 | 1308 | 1.64041666667 | 13884 |
| 013341 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:14am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.2 | 512233.2 | 1310 | 1.64041666667 | 13341 |
| 013985 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:15am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596695.1 | 512232.3 | 1312 | 1.64041666667 | 13985 |
| 014116 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:16am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596695.2 | 512229.9 | 1314 | 1.64041666667 | 14116 |
| 015019 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:17am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.1 | 512226.7 | 1316 | 1.64041666667 | 15019 |
| 015754 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:18am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596695.3 | 512223.4 | 1318 | 1.64041666667 | 15754 |
| 014378 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:19am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596695.6 | 512220.4 | 1320 | 1.64041666667 | 14378 |
| 015414 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:20am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596696.0 | 512216.9 | 1322 | 1.64041666667 | 15414 |
| 013513 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:21am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596696.9 | 512213.6 | 1324 | 1.64041666667 | 13513 |
| 014418 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:22am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596698.2 | 512209.7 | 1326 | 1.64041666667 | 14418 |
| 014464 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:23am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596699.3 | 512206.0 | 1328 | 1.64041666667 | 14464 |
| 014116 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:24am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596700.0 | 512202.6 | 1330 | 1.64041666667 | 14116 |
| 014779 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:25am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596700.5 | 512199.2 | 1332 | 1.64041666667 | 14779 |
| 013564 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:26am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596700.4 | 512195.5 | 1334 | 1.64041666667 | 13564 |
| 015061 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:27am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596700.0 | 512192.0 | 1336 | 1.64041666667 | 15061 |
| 014025 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:28am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596699.1 | 512188.9 | 1338 | 1.64041666667 | 14025 |
| 013616 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:29am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596698.0 | 512185.4 | 1340 | 1.64041666667 | 13616 |
| 014504 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:30am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596696.4 | 512181.5 | 1342 | 1.64041666667 | 14504 |
| 013916 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:31am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596695.7 | 512178.1 | 1344 | 1.64041666667 | 13916 |
| 014399 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:32am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596695.5 | 512174.5 | 1346 | 1.64041666667 | 14399 |
| 013259 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:33am | Sensor | 1797-S0002-G-TJV.cor | 6851.4 | 1596695.3 | 512171.0 | 1348 | 1.64041666667 | 13259 |
| 015135 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:34am | Sensor | 1797-S0002-G-TJV.cor | 6851.4 | 1596694.9 | 512167.1 | 1350 | 1.64041666667 | 15135 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 015213 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:35am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596694.5 | 512164.1 | 1352 | 1.64041666667 | 15213 |
| 014303 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:36am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596693.8 | 512160.4 | 1354 | 1.64041666667 | 14303 |
| 015185 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:37am | Sensor | 1797-S0002-G-TJV.cor | 6851.4 | 1596693.1 | 512156.8 | 1356 | 1.64041666667 | 15185 |
| 013906 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:38am | Sensor | 1797-S0002-G-TJV.cor | 6851.4 | 1596692.0 | 512153.1 | 1358 | 1.64041666667 | 13906 |
| 014726 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:39am | Sensor | 1797-S0002-G-TJV.cor | 6851.4 | 1596691.0 | 512150.1 | 1360 | 1.64041666667 | 14726 |
| 014781 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:40am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596690.2 | 512146.4 | 1362 | 1.64041666667 | 14781 |
| 013385 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:41am | Sensor | 1797-S0002-G-TJV.cor | 6851.2 | 1596689.9 | 512143.8 | 1364 | 1.64041666667 | 13385 |
| 015196 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:42am | Sensor | 1797-S0002-G-TJV.cor | 6851.2 | 1596689.2 | 512139.9 | 1366 | 1.64041666667 | 15196 |
| 015109 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:43am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596689.0 | 512136.7 | 1368 | 1.64041666667 | 15109 |
| 015207 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:44am | Sensor | 1797-S0002-G-TJV.cor | 6851.2 | 1596689.3 | 512132.8 | 1370 | 1.64041666667 | 15207 |
| 015172 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:45am | Sensor | 1797-S0002-G-TJV.cor | 6851.1 | 1596689.5 | 512129.5 | 1372 | 1.64041666667 | 15172 |
| 014233 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:46am | Sensor | 1797-S0002-G-TJV.cor | 6851.1 | 1596689.5 | 512125.8 | 1374 | 1.64041666667 | 14233 |
| 014148 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:47am | Sensor | 1797-S0002-G-TJV.cor | 6851.1 | 1596690.3 | 512122.8 | 1376 | 1.64041666667 | 14148 |
| 015897 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:48am | Sensor | 1797-S0002-G-TJV.cor | 6851.1 | 1596691.6 | 512119.3 | 1378 | 1.64041666667 | 15897 |
| 015704 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:49am | Sensor | 1797-S0002-G-TJV.cor | 6851.1 | 1596692.3 | 512116.2 | 1380 | 1.64041666667 | 15704 |
| 013226 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:50am | Sensor | 1797-S0002-G-TJV.cor | 6851.1 | 1596692.6 | 512112.5 | 1382 | 1.64041666667 | 13226 |
| 013716 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:51am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596693.1 | 512109.2 | 1384 | 1.64041666667 | 13716 |
| 015459 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:52am | Sensor | 1797-S0002-G-TJV.cor | 6851.2 | 1596694.0 | 512105.4 | 1386 | 1.64041666667 | 15459 |
| 015564 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:53am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596694.8 | 512102.5 | 1388 | 1.64041666667 | 15564 |
| 015381 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:54am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596695.9 | 512098.7 | 1390 | 1.64041666667 | 15381 |
| 015365 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:55am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596696.9 | 512096.0 | 1392 | 1.64041666667 | 15365 |
| 014911 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:56am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596698.9 | 512093.0 | 1394 | 1.64041666667 | 14911 |
| 014617 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:57am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596700.8 | 512090.9 | 1396 | 1.64041666667 | 14617 |
| 014934 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:58am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596703.4 | 512088.0 | 1398 | 1.64041666667 | 14934 |
| 015493 | 0 | GeoXH 6000 | 08/20/2015 | 11:50:59am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596705.4 | 512085.9 | 1400 | 1.64041666667 | 15493 |
| 015753 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:00am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596708.5 | 512083.5 | 1402 | 1.64041666667 | 15753 |
| 015008 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:01am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596710.6 | 512080.9 | 1404 | 1.64041666667 | 15008 |
| 015542 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:02am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596712.3 | 512077.3 | 1406 | 1.64041666667 | 15542 |
| 015195 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:03am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596713.7 | 512074.3 | 1408 | 1.64041666667 | 15195 |
| 013548 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:04am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596715.3 | 512070.9 | 1410 | 1.64041666667 | 13548 |
| 014457 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:05am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596716.4 | 512068.5 | 1412 | 1.64041666667 | 14457 |
| 014114 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:06am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596718.0 | 512064.8 | 1414 | 1.64041666667 | 14114 |
| 014508 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:07am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596719.5 | 512061.8 | 1416 | 1.64041666667 | 14508 |
| 014757 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:08am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596721.7 | 512058.2 | 1418 | 1.64041666667 | 14757 |
| 013619 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:09am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596723.1 | 512055.8 | 1420 | 1.64041666667 | 13619 |
| 014325 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:10am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596724.6 | 512052.0 | 1422 | 1.64041666667 | 14325 |
| 014561 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:11am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596725.6 | 512048.9 | 1424 | 1.64041666667 | 14561 |
| 013300 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:12am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596727.2 | 512045.3 | 1426 | 1.64041666667 | 13300 |
| 016495 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:13am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596728.8 | 512042.3 | 1428 | 1.64041666667 | 16495 |
| 015793 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:14am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596730.1 | 512038.6 | 1430 | 1.64041666667 | 15793 |
| 016218 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:15am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596731.1 | 512035.9 | 1432 | 1.64041666667 | 16218 |
| 014704 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:16am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596732.8 | 512032.1 | 1434 | 1.64041666667 | 14704 |
| 015046 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:17am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596734.5 | 512028.7 | 1436 | 1.64041666667 | 15046 |
| 015761 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:18am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596735.7 | 512024.7 | 1438 | 1.64041666667 | 15761 |
| 017380 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:19am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596736.4 | 512021.0 | 1440 | 1.64041666667 | 17380 |
| 019105 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:20am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596737.4 | 512017.3 | 1442 | 1.64041666667 | 19105 |
| 016416 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:21am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596738.5 | 512013.9 | 1444 | 1.64041666667 | 16416 |
| 016494 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:22am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596740.2 | 512010.3 | 1446 | 1.64041666667 | 16494 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 016483 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:23am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596741.2 | 512007.3 | 1448 | 1.64041666667 | 16483 |
| 019181 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:24am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596741.5 | 512003.2 | 1450 | 1.64041666667 | 19181 |
| 017005 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:25am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596741.0 | 511999.5 | 1452 | 1.64041666667 | 17005 |
| 016731 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:26am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596740.2 | 511995.7 | 1454 | 1.64041666667 | 16731 |
| 015972 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:27am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596739.7 | 511992.7 | 1456 | 1.64041666667 | 15972 |
| 016593 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:28am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596739.4 | 511989.1 | 1458 | 1.64041666667 | 16593 |
| 016808 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:29am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596739.6 | 511986.0 | 1460 | 1.64041666667 | 16808 |
| 017102 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:30am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596739.8 | 511982.2 | 1462 | 1.64041666667 | 17102 |
| 012855 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:31am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596739.4 | 511978.9 | 1464 | 1.64041666667 | 12855 |
| 012243 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:32am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.9 | 511975.3 | 1466 | 1.64041666667 | 12243 |
| 013051 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:33am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.8 | 511972.8 | 1468 | 1.64041666667 | 13051 |
| 012832 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:34am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.6 | 511971.7 | 1470 | 1.64041666667 | 12832 |
| 013408 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:35am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.4 | 511971.8 | 1472 | 1.64041666667 | 13408 |
| 012742 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:36am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.3 | 511972.0 | 1474 | 1.64041666667 | 12742 |
| 013745 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:37am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.3 | 511972.2 | 1476 | 1.64041666667 | 13745 |
| 013516 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:38am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596736.2 | 511972.5 | 1478 | 1.64041666667 | 13516 |
| 011719 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:39am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596736.7 | 511972.9 | 1480 | 1.64041666667 | 11719 |
| 012709 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:40am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.4 | 511973.9 | 1482 | 1.64041666667 | 12709 |
| 011427 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:41am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596739.7 | 511975.9 | 1484 | 1.64041666667 | 11427 |
| 013177 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:42am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596740.5 | 511978.5 | 1486 | 1.64041666667 | 13177 |
| 011904 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:43am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596741.5 | 511980.9 | 1488 | 1.64041666667 | 11904 |
| 013926 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:44am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596742.5 | 511983.4 | 1490 | 1.64041666667 | 13926 |
| 012181 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:45am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596743.4 | 511985.3 | 1492 | 1.64041666667 | 12181 |
| 013845 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:46am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596744.4 | 511987.9 | 1494 | 1.64041666667 | 13845 |
| 013241 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:47am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596744.9 | 511990.2 | 1496 | 1.64041666667 | 13241 |
| 013420 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:48am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596745.4 | 511991.9 | 1498 | 1.64041666667 | 13420 |
| 013165 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:49am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596746.9 | 511992.0 | 1500 | 1.64041666667 | 13165 |
| 011931 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:50am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596748.0 | 511991.3 | 1502 | 1.64041666667 | 11931 |
| 013752 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:51am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596747.3 | 511989.1 | 1504 | 1.64041666667 | 13752 |
| 013278 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:52am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596745.8 | 511986.1 | 1506 | 1.64041666667 | 13278 |
| 013489 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:53am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596744.1 | 511983.7 | 1508 | 1.64041666667 | 13489 |
| 013002 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:54am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596742.1 | 511981.3 | 1510 | 1.64041666667 | 13002 |
| 012220 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:55am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596740.3 | 511978.7 | 1512 | 1.64041666667 | 12220 |
| 010795 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:56am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596738.9 | 511976.4 | 1514 | 1.64041666667 | 10795 |
| 011788 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:57am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596738.0 | 511974.6 | 1516 | 1.64041666667 | 11788 |
| 011617 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:58am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596737.6 | 511973.7 | 1518 | 1.64041666667 | 11617 |
| 012204 | 0 | GeoXH 6000 | 08/20/2015 | 11:51:59am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.7 | 511974.4 | 1520 | 1.64041666667 | 12204 |
| 012081 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:00am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.8 | 511974.4 | 1522 | 1.64041666667 | 12081 |
| 012620 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:01am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.6 | 511974.2 | 1524 | 1.64041666667 | 12620 |
| 011015 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:02am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596738.0 | 511974.5 | 1526 | 1.64041666667 | 11015 |
| 012083 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:03am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596732.2 | 511974.2 | 1528 | 1.64041666667 | 12083 |
| 011511 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:04am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.5 | 511974.3 | 1530 | 1.64041666667 | 11511 |
| 012117 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:05am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.8 | 511974.1 | 1532 | 1.64041666667 | 12117 |
| 011429 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:06am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.7 | 511974.2 | 1534 | 1.64041666667 | 11429 |
| 012067 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:07am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.7 | 511974.1 | 1536 | 1.64041666667 | 12067 |
| 011716 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:08am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.8 | 511974.0 | 1538 | 1.64041666667 | 11716 |
| 011719 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:09am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.8 | 511974.0 | 1540 | 1.64041666667 | 11719 |
| 012199 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:10am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.8 | 511973.9 | 1542 | 1.64041666667 | 12199 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 011330 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:11am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.9 | 511974.0 | 1544 | 1.64041666667 | 11330 |
| 011982 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:12am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.9 | 511973.9 | 1546 | 1.64041666667 | 11982 |
| 012355 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:13am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.9 | 1548 | 1.64041666667 | 12355 |
| 012389 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:14am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.9 | 1550 | 1.64041666667 | 12389 |
| 011227 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:15am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.9 | 1552 | 1.64041666667 | 11227 |
| 010276 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:16am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.9 | 1554 | 1.64041666667 | 10276 |
| 012559 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:17am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.8 | 511974.0 | 1556 | 1.64041666667 | 12559 |
| 011179 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:18am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.7 | 511974.0 | 1558 | 1.64041666667 | 11179 |
| 011795 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:19am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.7 | 511974.0 | 1560 | 1.64041666667 | 11795 |
| 012698 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:20am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.9 | 511973.9 | 1562 | 1.64041666667 | 12698 |
| 012234 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:21am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596738.0 | 511974.0 | 1564 | 1.64041666667 | 12234 |
| 011908 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:22am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.9 | 511974.2 | 1566 | 1.64041666667 | 11908 |
| 011227 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:23am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.8 | 511974.0 | 1568 | 1.64041666667 | 11227 |
| 010276 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:24am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.8 | 1570 | 1.64041666667 | 10276 |
| 011989 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:25am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.9 | 511973.7 | 1572 | 1.64041666667 | 11989 |
| 012537 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:26am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596737.9 | 511973.7 | 1574 | 1.64041666667 | 12537 |
| 011114 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:27am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.8 | 1576 | 1.64041666667 | 11114 |
| 012168 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:28am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.7 | 1578 | 1.64041666667 | 12168 |
| 011532 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:29am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596737.8 | 511973.7 | 1580 | 1.64041666667 | 11532 |
| 009903 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:30am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596737.8 | 511973.7 | 1582 | 1.64041666667 | 9903 |
| 011385 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:31am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.7 | 511973.7 | 1584 | 1.64041666667 | 11385 |
| 011726 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:32am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.7 | 511973.7 | 1586 | 1.64041666667 | 11726 |
| 011601 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:33am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.7 | 1588 | 1.64041666667 | 11601 |
| 014150 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:34am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.7 | 511973.6 | 1590 | 1.64041666667 | 14150 |
| 012537 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:35am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.7 | 511973.6 | 1592 | 1.64041666667 | 12537 |
| 010304 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:36am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.6 | 1594 | 1.64041666667 | 10304 |
| 010406 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:37am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.6 | 1596 | 1.64041666667 | 10406 |
| 010641 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:38am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.6 | 1598 | 1.64041666667 | 10641 |
| 011960 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:39am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.6 | 1600 | 1.64041666667 | 11960 |
| 012440 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:40am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.6 | 1602 | 1.64041666667 | 12440 |
| 011660 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:41am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596737.8 | 511973.7 | 1604 | 1.64041666667 | 11660 |
| 011705 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:42am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.7 | 511973.9 | 1606 | 1.64041666667 | 11705 |
| 011566 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:43am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.8 | 511973.7 | 1608 | 1.64041666667 | 11566 |
| 011141 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:44am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596737.7 | 511973.8 | 1610 | 1.64041666667 | 11141 |
| 010915 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:45am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596737.6 | 511974.1 | 1612 | 1.64041666667 | 10915 |
| 011429 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:46am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596737.3 | 511974.2 | 1614 | 1.64041666667 | 11429 |
| 010417 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:47am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596736.8 | 511974.2 | 1616 | 1.64041666667 | 10417 |
| 012564 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:48am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596737.8 | 511974.1 | 1618 | 1.64041666667 | 12564 |
| 012681 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:49am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596738.3 | 511974.8 | 1620 | 1.64041666667 | 12681 |
| 010430 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:50am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596738.0 | 511974.5 | 1622 | 1.64041666667 | 10430 |
| 012267 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:51am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596738.1 | 511974.5 | 1624 | 1.64041666667 | 12267 |
| 011497 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:52am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596738.2 | 511974.8 | 1626 | 1.64041666667 | 11497 |
| 011244 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:53am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596738.2 | 511974.9 | 1628 | 1.64041666667 | 11244 |
| 012381 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:54am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596738.2 | 511974.8 | 1630 | 1.64041666667 | 12381 |
| 012305 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:55am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596738.2 | 511974.9 | 1632 | 1.64041666667 | 12305 |
| 010396 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:56am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596738.2 | 511974.9 | 1634 | 1.64041666667 | 10396 |
| 010549 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:57am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596738.2 | 511974.9 | 1636 | 1.64041666667 | 10549 |
| 011007 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:58am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596738.2 | 511974.9 | 1638 | 1.64041666667 | 11007 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 010972 | 0 | GeoXH 6000 | 08/20/2015 | 11:52:59am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596738.2 | 511974.9 | 1640 | 1.64041666667 | 10972 |
| 010723 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:00am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596738.2 | 511974.9 | 1642 | 1.64041666667 | 10723 |
| 011650 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:01am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596738.2 | 511974.9 | 1644 | 1.64041666667 | 11650 |
| 011432 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:02am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596738.1 | 511974.6 | 1646 | 1.64041666667 | 11432 |
| 011198 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:03am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596737.9 | 511974.2 | 1648 | 1.64041666667 | 11198 |
| 012069 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:04am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.8 | 511974.1 | 1650 | 1.64041666667 | 12069 |
| 013157 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:05am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.9 | 511974.3 | 1652 | 1.64041666667 | 13157 |
| 012979 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:06am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.8 | 511974.3 | 1654 | 1.64041666667 | 12979 |
| 011764 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:07am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.8 | 511974.3 | 1656 | 1.64041666667 | 11764 |
| 012241 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:08am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.9 | 511974.3 | 1658 | 1.64041666667 | 12241 |
| 009900 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:09am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.0 | 511974.2 | 1660 | 1.64041666667 | 9900 |
| 010755 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:10am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596738.0 | 511973.9 | 1662 | 1.64041666667 | 10755 |
| 011658 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:11am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596738.0 | 511973.2 | 1664 | 1.64041666667 | 11658 |
| 012574 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:12am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.1 | 511974.1 | 1666 | 1.64041666667 | 12574 |
| 013373 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:13am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596738.2 | 511975.0 | 1668 | 1.64041666667 | 13373 |
| 012373 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:14am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.3 | 511974.1 | 1670 | 1.64041666667 | 12373 |
| 013053 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:15am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.1 | 511974.5 | 1672 | 1.64041666667 | 13053 |
| 011513 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:16am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.9 | 511974.6 | 1674 | 1.64041666667 | 11513 |
| 013738 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:17am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.8 | 511974.2 | 1676 | 1.64041666667 | 13738 |
| 014684 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:18am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.9 | 511974.1 | 1678 | 1.64041666667 | 14684 |
| 013421 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:19am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.0 | 511974.2 | 1680 | 1.64041666667 | 13421 |
| 011785 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:20am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.9 | 511974.3 | 1682 | 1.64041666667 | 11785 |
| 012366 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:21am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.0 | 511974.3 | 1684 | 1.64041666667 | 12366 |
| 012181 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:22am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.0 | 511974.3 | 1686 | 1.64041666667 | 12181 |
| 012075 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:23am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.9 | 511974.3 | 1688 | 1.64041666667 | 12075 |
| 011538 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:24am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.7 | 511974.2 | 1690 | 1.64041666667 | 11538 |
| 012274 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:25am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.7 | 511974.4 | 1692 | 1.64041666667 | 12274 |
| 013118 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:26am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.7 | 511975.7 | 1694 | 1.64041666667 | 13118 |
| 011889 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:27am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596738.0 | 511977.0 | 1696 | 1.64041666667 | 11889 |
| 012992 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:28am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596739.1 | 511979.0 | 1698 | 1.64041666667 | 12992 |
| 014198 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:29am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596739.1 | 511980.7 | 1700 | 1.64041666667 | 14198 |
| 016389 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:30am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596739.5 | 511983.0 | 1702 | 1.64041666667 | 16389 |
| 015767 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:31am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596739.7 | 511985.2 | 1704 | 1.64041666667 | 15767 |
| 016571 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:32am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596739.9 | 511987.3 | 1706 | 1.64041666667 | 16571 |
| 016773 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:33am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596738.8 | 511988.9 | 1708 | 1.64041666667 | 16773 |
| 016973 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:34am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596737.1 | 511991.0 | 1710 | 1.64041666667 | 16973 |
| 015583 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:35am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596734.9 | 511992.6 | 1712 | 1.64041666667 | 15583 |
| 014066 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:36am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596732.6 | 511993.1 | 1714 | 1.64041666667 | 14066 |
| 012216 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:37am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596730.0 | 511993.8 | 1716 | 1.64041666667 | 12216 |
| 011454 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:38am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596727.6 | 511992.8 | 1718 | 1.64041666667 | 11454 |
| 012493 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:39am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596725.8 | 511991.8 | 1720 | 1.64041666667 | 12493 |
| 013353 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:40am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596724.8 | 511990.0 | 1722 | 1.64041666667 | 13353 |
| 010868 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:41am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596723.7 | 511988.2 | 1724 | 1.64041666667 | 10868 |
| 012137 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:42am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596722.7 | 511986.7 | 1726 | 1.64041666667 | 12137 |
| 012304 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:43am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596722.3 | 511985.9 | 1728 | 1.64041666667 | 12304 |
| 013546 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:44am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596722.8 | 511985.7 | 1730 | 1.64041666667 | 13546 |
| 013016 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:45am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596723.1 | 511985.6 | 1732 | 1.64041666667 | 13016 |
| 013574 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:46am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596722.9 | 511985.7 | 1734 | 1.64041666667 | 13574 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012183 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:47am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596722.8 | 511985.8 | 1736 | 1.64041666667 | 12183 |
| 012405 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:48am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596722.8 | 511985.8 | 1738 | 1.64041666667 | 12405 |
| 012521 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:49am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596722.8 | 511985.9 | 1740 | 1.64041666667 | 12521 |
| 011980 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:50am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596722.3 | 511986.0 | 1742 | 1.64041666667 | 11980 |
| 011810 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:51am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596722.6 | 511985.6 | 1744 | 1.64041666667 | 11810 |
| 012786 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:52am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596723.1 | 511985.3 | 1746 | 1.64041666667 | 12786 |
| 011986 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:53am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596723.9 | 511984.2 | 1748 | 1.64041666667 | 11986 |
| 012806 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596725.6 | 511982.0 | 1750 | 1.64041666667 | 12806 |
| 012531 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:55am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596727.1 | 511980.9 | 1752 | 1.64041666667 | 12531 |
| 011713 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596727.2 | 511980.8 | 1754 | 1.64041666667 | 11713 |
| 011298 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:57am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596727.2 | 511980.8 | 1756 | 1.64041666667 | 11298 |
| 013054 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:58am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596727.2 | 511980.8 | 1758 | 1.64041666667 | 13054 |
| 013793 | 0 | GeoXH 6000 | 08/20/2015 | 11:53:59am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596727.2 | 511980.8 | 1760 | 1.64041666667 | 13793 |
| 012928 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:00am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596727.2 | 511980.9 | 1762 | 1.64041666667 | 12928 |
| 012832 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:01am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596727.2 | 511980.9 | 1764 | 1.64041666667 | 12832 |
| 012358 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:02am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596727.5 | 511980.6 | 1766 | 1.64041666667 | 12358 |
| 013829 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:03am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596728.5 | 511980.0 | 1768 | 1.64041666667 | 13829 |
| 013957 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:04am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596729.0 | 511979.9 | 1770 | 1.64041666667 | 13957 |
| 012159 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:05am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596729.1 | 511979.6 | 1772 | 1.64041666667 | 12159 |
| 012579 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:06am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596726.6 | 511980.4 | 1774 | 1.64041666667 | 12579 |
| 013075 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:07am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596726.4 | 511980.6 | 1776 | 1.64041666667 | 13075 |
| 011818 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:08am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596726.0 | 511982.2 | 1778 | 1.64041666667 | 11818 |
| 011984 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:09am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596725.1 | 511984.0 | 1780 | 1.64041666667 | 11984 |
| 012356 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:10am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596724.1 | 511985.6 | 1782 | 1.64041666667 | 12356 |
| 012089 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:11am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596723.6 | 511985.7 | 1784 | 1.64041666667 | 12089 |
| 013282 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:12am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596723.1 | 511986.4 | 1786 | 1.64041666667 | 13282 |
| 013370 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:13am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596723.5 | 511986.3 | 1788 | 1.64041666667 | 13370 |
| 012942 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:14am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596722.8 | 511986.1 | 1790 | 1.64041666667 | 12942 |
| 012025 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:15am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596722.1 | 511985.4 | 1792 | 1.64041666667 | 12025 |
| 012456 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:16am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596720.9 | 511984.3 | 1794 | 1.64041666667 | 12456 |
| 012414 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:17am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596719.2 | 511983.0 | 1796 | 1.64041666667 | 12414 |
| 012253 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:18am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596717.6 | 511982.1 | 1798 | 1.64041666667 | 12253 |
| 014973 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:19am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596715.5 | 511980.4 | 1800 | 1.64041666667 | 14973 |
| 013613 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:20am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596713.5 | 511978.8 | 1802 | 1.64041666667 | 13613 |
| 017773 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:21am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596712.3 | 511977.5 | 1804 | 1.64041666667 | 17773 |
| 014643 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:22am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596711.5 | 511976.3 | 1806 | 1.64041666667 | 14643 |
| 016230 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:23am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596711.0 | 511975.8 | 1808 | 1.64041666667 | 16230 |
| 017677 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:24am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596711.2 | 511976.9 | 1810 | 1.64041666667 | 17677 |
| 019359 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:25am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596711.2 | 511978.0 | 1812 | 1.64041666667 | 19359 |
| 016390 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:26am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596711.5 | 511978.7 | 1814 | 1.64041666667 | 16390 |
| 019427 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:27am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596711.6 | 511979.3 | 1816 | 1.64041666667 | 19427 |
| 019316 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:28am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596712.4 | 511980.6 | 1818 | 1.64041666667 | 19316 |
| 016739 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:29am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596712.8 | 511980.8 | 1820 | 1.64041666667 | 16739 |
| 015525 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:30am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596713.0 | 511980.9 | 1822 | 1.64041666667 | 15525 |
| 016541 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:31am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596713.0 | 511980.8 | 1824 | 1.64041666667 | 16541 |
| 017305 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:32am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596711.2 | 511980.1 | 1826 | 1.64041666667 | 17305 |
| 015366 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:32am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596710.1 | 511979.5 | 1827 | 1.64041666667 | 15366 |
| 014731 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:34am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596710.0 | 511979.4 | 1830 | 1.64041666667 | 14731 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 015352 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:35am | Sensor | 1797-S0002-G-TJV.cor | 6851.5 | 1596710.0 | 511979.4 | 1832 | 1.64041666667 | 15352 |
| 015088 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:36am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596711.6 | 511980.0 | 1834 | 1.64041666667 | 15088 |
| 015742 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:37am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596712.7 | 511980.6 | 1836 | 1.64041666667 | 15742 |
| 014105 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:38am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596712.9 | 511978.7 | 1838 | 1.64041666667 | 14105 |
| 013156 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:39am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596713.4 | 511977.5 | 1840 | 1.64041666667 | 13156 |
| 013369 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:40am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596712.7 | 511977.2 | 1842 | 1.64041666667 | 13369 |
| 015522 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:41am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596711.3 | 511976.4 | 1844 | 1.64041666667 | 15522 |
| 015790 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:42am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596710.2 | 511974.4 | 1846 | 1.64041666667 | 15790 |
| 014147 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:43am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596708.3 | 511973.0 | 1848 | 1.64041666667 | 14147 |
| 013196 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:44am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596706.4 | 511970.9 | 1850 | 1.64041666667 | 13196 |
| 014459 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:45am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596704.5 | 511969.1 | 1852 | 1.64041666667 | 14459 |
| 014895 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:46am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596702.7 | 511967.3 | 1854 | 1.64041666667 | 14895 |
| 015573 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:47am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596701.4 | 511965.6 | 1856 | 1.64041666667 | 15573 |
| 014153 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:48am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596698.8 | 511964.1 | 1858 | 1.64041666667 | 14153 |
| 016378 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:49am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596697.1 | 511962.8 | 1860 | 1.64041666667 | 16378 |
| 015434 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:50am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596694.9 | 511961.9 | 1862 | 1.64041666667 | 15434 |
| 013998 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:51am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596693.8 | 511960.4 | 1864 | 1.64041666667 | 13998 |
| 015409 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:52am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596693.4 | 511960.3 | 1866 | 1.64041666667 | 15409 |
| 015132 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:53am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596693.5 | 511960.2 | 1868 | 1.64041666667 | 15132 |
| 014013 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596693.5 | 511960.2 | 1870 | 1.64041666667 | 14013 |
| 015803 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596693.5 | 511960.2 | 1871 | 1.64041666667 | 15803 |
| 016190 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596693.5 | 511960.2 | 1874 | 1.64041666667 | 16190 |
| 015417 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596693.4 | 511960.3 | 1875 | 1.64041666667 | 15417 |
| 015254 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:58am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596693.4 | 511960.3 | 1878 | 1.64041666667 | 15254 |
| 013953 | 0 | GeoXH 6000 | 08/20/2015 | 11:54:59am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596692.8 | 511960.8 | 1880 | 1.64041666667 | 13953 |
| 014288 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:00am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596691.0 | 511961.2 | 1882 | 1.64041666667 | 14288 |
| 011672 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:01am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596689.7 | 511961.7 | 1884 | 1.64041666667 | 11672 |
| 012338 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:02am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596687.3 | 511962.8 | 1886 | 1.64041666667 | 12338 |
| 011604 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:03am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596685.6 | 511963.3 | 1888 | 1.64041666667 | 11604 |
| 011721 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:04am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596682.7 | 511963.7 | 1890 | 1.64041666667 | 11721 |
| 010940 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:05am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596681.0 | 511963.9 | 1892 | 1.64041666667 | 10940 |
| 011075 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:06am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596678.7 | 511964.2 | 1894 | 1.64041666667 | 11075 |
| 011708 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:07am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596676.7 | 511964.9 | 1896 | 1.64041666667 | 11708 |
| 012647 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:08am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596673.7 | 511965.4 | 1898 | 1.64041666667 | 12647 |
| 011831 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:08am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596671.7 | 511966.0 | 1899 | 1.64041666667 | 11831 |
| 013428 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:10am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596669.2 | 511965.9 | 1902 | 1.64041666667 | 13428 |
| 012447 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:11am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596667.1 | 511966.8 | 1904 | 1.64041666667 | 12447 |
| 012681 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:12am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596665.6 | 511966.1 | 1906 | 1.64041666667 | 12681 |
| 012350 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:13am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596664.1 | 511965.0 | 1908 | 1.64041666667 | 12350 |
| 013587 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:14am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596662.6 | 511963.4 | 1910 | 1.64041666667 | 13587 |
| 012217 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:14am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596660.8 | 511962.6 | 1911 | 1.64041666667 | 12217 |
| 013014 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:16am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596660.2 | 511960.9 | 1914 | 1.64041666667 | 13014 |
| 014653 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:17am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596658.1 | 511959.6 | 1916 | 1.64041666667 | 14653 |
| 013533 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:18am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596656.6 | 511958.0 | 1918 | 1.64041666667 | 13533 |
| 012533 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:18am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596654.6 | 511957.2 | 1919 | 1.64041666667 | 12533 |
| 012373 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:20am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596653.3 | 511955.0 | 1922 | 1.64041666667 | 12373 |
| 011913 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:21am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596651.3 | 511954.0 | 1924 | 1.64041666667 | 11913 |
| 012338 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:22am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596649.8 | 511952.2 | 1926 | 1.64041666667 | 12338 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012234 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:23am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596647.8 | 511951.9 | 1928 | 1.64041666667 | 12234 |
| 013378 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:24am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596647.0 | 511950.3 | 1930 | 1.64041666667 | 13378 |
| 012104 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:25am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596645.3 | 511948.5 | 1932 | 1.64041666667 | 12104 |
| 012716 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:26am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596644.4 | 511946.6 | 1934 | 1.64041666667 | 12716 |
| 013019 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:27am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596643.0 | 511945.0 | 1936 | 1.64041666667 | 13019 |
| 012014 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:28am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596641.9 | 511943.0 | 1938 | 1.64041666667 | 12014 |
| 011133 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:29am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596640.2 | 511941.4 | 1940 | 1.64041666667 | 11133 |
| 011933 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:30am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596639.5 | 511939.8 | 1942 | 1.64041666667 | 11933 |
| 013063 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:31am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596638.2 | 511937.9 | 1944 | 1.64041666667 | 13063 |
| 013556 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:32am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596636.8 | 511936.9 | 1946 | 1.64041666667 | 13556 |
| 014069 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:33am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596634.8 | 511936.3 | 1948 | 1.64041666667 | 14069 |
| 012937 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:34am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596633.0 | 511935.4 | 1950 | 1.64041666667 | 12937 |
| 012204 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:35am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596631.6 | 511933.8 | 1952 | 1.64041666667 | 12204 |
| 012561 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:36am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596630.7 | 511932.3 | 1954 | 1.64041666667 | 12561 |
| 012440 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:37am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596628.9 | 511931.3 | 1956 | 1.64041666667 | 12440 |
| 012530 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:38am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596627.1 | 511930.1 | 1958 | 1.64041666667 | 12530 |
| 011982 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:39am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596625.1 | 511928.9 | 1960 | 1.64041666667 | 11982 |
| 014215 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:40am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596623.6 | 511927.3 | 1962 | 1.64041666667 | 14215 |
| 015104 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:41am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596622.4 | 511926.2 | 1964 | 1.64041666667 | 15104 |
| 015536 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:42am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596622.0 | 511926.1 | 1966 | 1.64041666667 | 15536 |
| 013664 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:43am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596620.2 | 511927.6 | 1968 | 1.64041666667 | 13664 |
| 013616 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:44am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596617.9 | 511929.1 | 1970 | 1.64041666667 | 13616 |
| 011804 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:45am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596616.5 | 511931.1 | 1972 | 1.64041666667 | 11804 |
| 011651 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:46am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596614.9 | 511932.8 | 1974 | 1.64041666667 | 11651 |
| 011342 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:47am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596614.4 | 511935.5 | 1976 | 1.64041666667 | 11342 |
| 012795 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:48am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596613.7 | 511937.5 | 1978 | 1.64041666667 | 12795 |
| 011748 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:48am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.8 | 511938.9 | 1979 | 1.64041666667 | 11748 |
| 011967 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:50am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596612.9 | 511940.1 | 1982 | 1.64041666667 | 11967 |
| 011722 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:51am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596612.9 | 511940.2 | 1984 | 1.64041666667 | 11722 |
| 010670 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:52am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596612.9 | 511940.1 | 1986 | 1.64041666667 | 10670 |
| 011637 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:53am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.0 | 511940.1 | 1988 | 1.64041666667 | 11637 |
| 011159 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:54am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.4 | 511940.0 | 1990 | 1.64041666667 | 11159 |
| 010319 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:55am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.8 | 511939.8 | 1992 | 1.64041666667 | 10319 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:56am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.3 | 511940.2 | 1994 | 1.64041666667 | 11205 |
| 010751 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:57am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.3 | 511940.2 | 1996 | 1.64041666667 | 10751 |
| 010487 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:58am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.5 | 511940.3 | 1998 | 1.64041666667 | 10487 |
| 011651 | 0 | GeoXH 6000 | 08/20/2015 | 11:55:58am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.5 | 511940.3 | 1999 | 1.64041666667 | 11651 |
| 011403 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:00am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.6 | 511940.3 | 2002 | 1.64041666667 | 11403 |
| 011370 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:01am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.6 | 511940.3 | 2004 | 1.64041666667 | 11370 |
| 012112 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:02am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.8 | 511940.3 | 2006 | 1.64041666667 | 12112 |
| 011788 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:03am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596614.0 | 511940.4 | 2008 | 1.64041666667 | 11788 |
| 010657 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:04am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596613.7 | 511941.1 | 2010 | 1.64041666667 | 10657 |
| 010074 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:05am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596613.6 | 511941.1 | 2012 | 1.64041666667 | 10074 |
| 011248 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:06am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596613.7 | 511941.3 | 2014 | 1.64041666667 | 11248 |
| 011032 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:07am | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596614.0 | 511940.7 | 2016 | 1.64041666667 | 11032 |
| 011818 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:08am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596614.0 | 511938.0 | 2018 | 1.64041666667 | 11818 |
| 011534 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:08am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596614.7 | 511936.5 | 2019 | 1.64041666667 | 11534 |
| 012543 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:10am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596615.0 | 511935.7 | 2022 | 1.64041666667 | 12543 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 011985 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:11am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596615.9 | 511935.5 | 2024 | 1.64041666667 | 11985 |
| 011246 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:12am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596615.8 | 511935.7 | 2026 | 1.64041666667 | 11246 |
| 012171 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:13am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596615.9 | 511935.6 | 2028 | 1.64041666667 | 12171 |
| 011083 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:14am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596615.9 | 511935.6 | 2030 | 1.64041666667 | 11083 |
| 011170 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:14am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596615.5 | 511935.6 | 2031 | 1.64041666667 | 11170 |
| 011792 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:16am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596614.6 | 511935.8 | 2034 | 1.64041666667 | 11792 |
| 013808 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:17am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596615.5 | 511935.4 | 2036 | 1.64041666667 | 13808 |
| 012752 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:18am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596615.0 | 511936.3 | 2038 | 1.64041666667 | 12752 |
| 012008 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:19am | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596614.7 | 511937.7 | 2040 | 1.64041666667 | 12008 |
| 011342 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:20am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596614.2 | 511939.5 | 2042 | 1.64041666667 | 11342 |
| 011385 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:21am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596614.3 | 511939.5 | 2044 | 1.64041666667 | 11385 |
| 011066 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:22am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596614.3 | 511939.8 | 2046 | 1.64041666667 | 11066 |
| 011166 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:23am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596614.4 | 511940.3 | 2048 | 1.64041666667 | 11166 |
| 010951 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:24am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596616.0 | 511940.3 | 2050 | 1.64041666667 | 10951 |
| 011437 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:25am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596618.2 | 511941.2 | 2052 | 1.64041666667 | 11437 |
| 011859 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:26am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596621.1 | 511941.8 | 2054 | 1.64041666667 | 11859 |
| 011665 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:27am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596623.0 | 511943.1 | 2056 | 1.64041666667 | 11665 |
| 010776 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:28am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596625.7 | 511944.2 | 2058 | 1.64041666667 | 10776 |
| 011154 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:29am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596627.7 | 511945.0 | 2060 | 1.64041666667 | 11154 |
| 012928 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:30am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596630.3 | 511945.0 | 2062 | 1.64041666667 | 12928 |
| 014752 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:31am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596632.6 | 511945.8 | 2064 | 1.64041666667 | 14752 |
| 014938 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:32am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596635.7 | 511946.2 | 2066 | 1.64041666667 | 14938 |
| 013004 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:33am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596637.7 | 511947.0 | 2068 | 1.64041666667 | 13004 |
| 012551 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:34am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596640.0 | 511948.0 | 2070 | 1.64041666667 | 12551 |
| 012887 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:35am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596642.4 | 511948.0 | 2072 | 1.64041666667 | 12887 |
| 012671 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:36am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596645.1 | 511948.9 | 2074 | 1.64041666667 | 12671 |
| 011298 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:36am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596647.0 | 511948.6 | 2075 | 1.64041666667 | 11298 |
| 011704 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:38am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596649.3 | 511948.4 | 2078 | 1.64041666667 | 11704 |
| 010666 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:38am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596651.8 | 511947.8 | 2079 | 1.64041666667 | 10666 |
| 012626 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:40am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596654.9 | 511948.4 | 2082 | 1.64041666667 | 12626 |
| 011676 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:41am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596657.4 | 511948.9 | 2084 | 1.64041666667 | 11676 |
| 011169 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:42am | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596659.0 | 511950.5 | 2086 | 1.64041666667 | 11169 |
| 013532 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:43am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596661.3 | 511951.9 | 2088 | 1.64041666667 | 13532 |
| 013793 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:44am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596663.2 | 511953.8 | 2090 | 1.64041666667 | 13793 |
| 011968 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:45am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596665.2 | 511954.3 | 2092 | 1.64041666667 | 11968 |
| 011932 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:46am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596666.8 | 511955.4 | 2094 | 1.64041666667 | 11932 |
| 012403 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:47am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596668.9 | 511955.6 | 2096 | 1.64041666667 | 12403 |
| 011770 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:48am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596671.7 | 511956.5 | 2098 | 1.64041666667 | 11770 |
| 012332 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:49am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596673.9 | 511956.5 | 2100 | 1.64041666667 | 12332 |
| 012803 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:50am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596675.7 | 511957.9 | 2102 | 1.64041666667 | 12803 |
| 010790 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:50am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596677.6 | 511959.2 | 2103 | 1.64041666667 | 10790 |
| 010677 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:52am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596679.6 | 511960.4 | 2106 | 1.64041666667 | 10677 |
| 011669 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:53am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596682.2 | 511961.3 | 2108 | 1.64041666667 | 11669 |
| 011917 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596684.6 | 511962.1 | 2110 | 1.64041666667 | 11917 |
| 010599 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596687.0 | 511963.0 | 2111 | 1.64041666667 | 10599 |
| 013509 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596689.8 | 511962.4 | 2114 | 1.64041666667 | 13509 |
| 014987 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596691.4 | 511964.1 | 2115 | 1.64041666667 | 14987 |
| 016946 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:58am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596694.0 | 511965.3 | 2118 | 1.64041666667 | 16946 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 019536 | 0 | GeoXH 6000 | 08/20/2015 | 11:56:58am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596695.5 | 511966.7 | 2119 | 1.64041666667 | 19536 |
| 017154 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:00am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596698.3 | 511968.1 | 2122 | 1.64041666667 | 17154 |
| 016918 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:01am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596700.4 | 511969.4 | 2124 | 1.64041666667 | 16918 |
| 014189 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:02am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596703.2 | 511970.2 | 2126 | 1.64041666667 | 14189 |
| 014737 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:02am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596704.8 | 511971.2 | 2127 | 1.64041666667 | 14737 |
| 012654 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:04am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596707.6 | 511972.6 | 2130 | 1.64041666667 | 12654 |
| 012823 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:05am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596709.6 | 511973.5 | 2132 | 1.64041666667 | 12823 |
| 012356 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:06am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596711.6 | 511975.1 | 2134 | 1.64041666667 | 12356 |
| 013649 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:07am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596713.3 | 511975.8 | 2136 | 1.64041666667 | 13649 |
| 013042 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:08am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596715.6 | 511976.3 | 2138 | 1.64041666667 | 13042 |
| 014450 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:09am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596717.8 | 511975.9 | 2140 | 1.64041666667 | 14450 |
| 014412 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:10am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596719.9 | 511976.9 | 2142 | 1.64041666667 | 14412 |
| 014103 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:10am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596722.1 | 511977.1 | 2143 | 1.64041666667 | 14103 |
| 012345 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:12am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596724.6 | 511978.6 | 2146 | 1.64041666667 | 12345 |
| 013526 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:13am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596726.8 | 511979.6 | 2148 | 1.64041666667 | 13526 |
| 013101 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:14am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596727.8 | 511980.6 | 2150 | 1.64041666667 | 13101 |
| 014045 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:15am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596726.9 | 511981.4 | 2152 | 1.64041666667 | 14045 |
| 013801 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:16am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596729.5 | 511980.7 | 2154 | 1.64041666667 | 13801 |
| 012660 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:16am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596731.1 | 511981.3 | 2155 | 1.64041666667 | 12660 |
| 012555 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:18am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596731.8 | 511979.2 | 2158 | 1.64041666667 | 12555 |
| 013668 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:18am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596733.6 | 511978.0 | 2159 | 1.64041666667 | 13668 |
| 012477 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:20am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596733.6 | 511976.3 | 2162 | 1.64041666667 | 12477 |
| 012779 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:21am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596733.7 | 511975.6 | 2164 | 1.64041666667 | 12779 |
| 012825 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:22am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596734.0 | 511975.9 | 2166 | 1.64041666667 | 12825 |
| 012596 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:23am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596735.9 | 511973.8 | 2168 | 1.64041666667 | 12596 |
| 013019 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:24am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.2 | 511971.2 | 2170 | 1.64041666667 | 13019 |
| 012764 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:25am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596738.8 | 511969.9 | 2172 | 1.64041666667 | 12764 |
| 011861 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:26am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596739.5 | 511969.2 | 2174 | 1.64041666667 | 11861 |
| 011875 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:27am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596739.6 | 511969.0 | 2176 | 1.64041666667 | 11875 |
| 014008 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:28am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596739.6 | 511969.0 | 2178 | 1.64041666667 | 14008 |
| 012622 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:28am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596739.5 | 511969.0 | 2179 | 1.64041666667 | 12622 |
| 011585 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:30am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596737.0 | 511970.5 | 2182 | 1.64041666667 | 11585 |
| 012106 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:30am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596737.6 | 511970.3 | 2183 | 1.64041666667 | 12106 |
| 012776 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:32am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596737.1 | 511970.2 | 2186 | 1.64041666667 | 12776 |
| 013424 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:33am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.2 | 511969.9 | 2188 | 1.64041666667 | 13424 |
| 013886 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:34am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596736.9 | 511970.0 | 2190 | 1.64041666667 | 13886 |
| 013581 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:34am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596736.8 | 511970.0 | 2191 | 1.64041666667 | 13581 |
| 013745 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:36am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596736.8 | 511970.2 | 2194 | 1.64041666667 | 13745 |
| 013156 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:37am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596736.8 | 511970.2 | 2196 | 1.64041666667 | 13156 |
| 013519 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:38am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596736.6 | 511970.6 | 2198 | 1.64041666667 | 13519 |
| 013009 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:38am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596735.8 | 511972.6 | 2199 | 1.64041666667 | 13009 |
| 013572 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:40am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596734.3 | 511974.9 | 2202 | 1.64041666667 | 13572 |
| 012213 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:41am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596732.7 | 511974.8 | 2204 | 1.64041666667 | 12213 |
| 012653 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:41am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596730.0 | 511974.7 | 2205 | 1.64041666667 | 12653 |
| 012523 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:42am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596727.4 | 511973.9 | 2207 | 1.64041666667 | 12523 |
| 012371 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:44am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596724.7 | 511972.5 | 2210 | 1.64041666667 | 12371 |
| 014792 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:44am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596722.6 | 511971.8 | 2211 | 1.64041666667 | 14792 |
| 013958 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:45am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596719.9 | 511971.0 | 2213 | 1.64041666667 | 13958 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013809 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:46am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596717.3 | 511971.0 | 2215 | 1.64041666667 | 13809 |
| 013202 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:48am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596714.3 | 511969.8 | 2218 | 1.64041666667 | 13202 |
| 012660 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:48am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596711.8 | 511969.3 | 2219 | 1.64041666667 | 12660 |
| 013635 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:50am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596709.0 | 511967.8 | 2222 | 1.64041666667 | 13635 |
| 013308 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:51am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596706.4 | 511966.9 | 2224 | 1.64041666667 | 13308 |
| 014277 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:52am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596704.0 | 511965.9 | 2226 | 1.64041666667 | 14277 |
| 015929 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:53am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596701.1 | 511964.7 | 2228 | 1.64041666667 | 15929 |
| 015142 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596698.7 | 511963.9 | 2230 | 1.64041666667 | 15142 |
| 017495 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596696.8 | 511962.8 | 2231 | 1.64041666667 | 17495 |
| 015833 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596694.0 | 511962.5 | 2234 | 1.64041666667 | 15833 |
| 014398 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596692.0 | 511961.5 | 2235 | 1.64041666667 | 14398 |
| 014279 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:58am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596689.1 | 511961.7 | 2238 | 1.64041666667 | 14279 |
| 013170 | 0 | GeoXH 6000 | 08/20/2015 | 11:57:58am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596687.1 | 511960.7 | 2239 | 1.64041666667 | 13170 |
| 011392 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:00am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596683.8 | 511960.8 | 2242 | 1.64041666667 | 11392 |
| 010108 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:01am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596681.2 | 511959.8 | 2244 | 1.64041666667 | 10108 |
| 011707 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:02am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596678.9 | 511958.8 | 2246 | 1.64041666667 | 11707 |
| 013336 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:02am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596676.5 | 511957.8 | 2247 | 1.64041666667 | 13336 |
| 012094 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:04am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596674.1 | 511956.4 | 2250 | 1.64041666667 | 12094 |
| 011843 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:05am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596671.5 | 511956.2 | 2252 | 1.64041666667 | 11843 |
| 009411 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:06am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596668.9 | 511955.1 | 2254 | 1.64041666667 | 9411 |
| 009522 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:07am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596666.1 | 511954.7 | 2256 | 1.64041666667 | 9522 |
| 012310 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:08am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596663.8 | 511953.2 | 2258 | 1.64041666667 | 12310 |
| 010217 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:08am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596661.8 | 511952.6 | 2259 | 1.64041666667 | 10217 |
| 011734 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:10am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596659.7 | 511950.6 | 2262 | 1.64041666667 | 11734 |
| 010913 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:10am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596658.0 | 511948.8 | 2263 | 1.64041666667 | 10913 |
| 012418 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:12am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596655.4 | 511947.8 | 2266 | 1.64041666667 | 12418 |
| 010754 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:13am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596653.3 | 511946.9 | 2268 | 1.64041666667 | 10754 |
| 010848 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:14am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596650.9 | 511947.7 | 2270 | 1.64041666667 | 10848 |
| 011352 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:14am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596649.3 | 511947.4 | 2271 | 1.64041666667 | 11352 |
| 013518 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:16am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596646.8 | 511947.0 | 2274 | 1.64041666667 | 13518 |
| 011599 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:17am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596645.0 | 511945.6 | 2276 | 1.64041666667 | 11599 |
| 012259 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:18am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596643.0 | 511944.5 | 2278 | 1.64041666667 | 12259 |
| 011975 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:19am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596640.5 | 511944.2 | 2280 | 1.64041666667 | 11975 |
| 012023 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:20am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596637.5 | 511944.4 | 2282 | 1.64041666667 | 12023 |
| 011946 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:21am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596634.9 | 511943.9 | 2284 | 1.64041666667 | 11946 |
| 011566 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:22am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596632.5 | 511943.8 | 2286 | 1.64041666667 | 11566 |
| 010451 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:23am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596630.0 | 511942.4 | 2288 | 1.64041666667 | 10451 |
| 012183 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:24am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596627.7 | 511941.2 | 2290 | 1.64041666667 | 12183 |
| 012405 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:25am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596625.9 | 511939.3 | 2292 | 1.64041666667 | 12405 |
| 011801 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:26am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596623.5 | 511938.5 | 2294 | 1.64041666667 | 11801 |
| 011020 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:26am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596621.6 | 511936.7 | 2295 | 1.64041666667 | 11020 |
| 012055 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:28am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596620.9 | 511936.5 | 2298 | 1.64041666667 | 12055 |
| 012163 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:28am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596619.0 | 511936.6 | 2299 | 1.64041666667 | 12163 |
| 011741 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:30am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596618.3 | 511935.2 | 2302 | 1.64041666667 | 11741 |
| 012205 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:30am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596617.9 | 511934.8 | 2303 | 1.64041666667 | 12205 |
| 011271 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:32am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596615.3 | 511934.2 | 2306 | 1.64041666667 | 11271 |
| 010467 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:32am | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596613.2 | 511933.7 | 2307 | 1.64041666667 | 10467 |
| 011167 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:34am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596611.2 | 511933.2 | 2310 | 1.64041666667 | 11167 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 010711 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:34am | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596610.2 | 511932.3 | 2311 | 1.64041666667 | 10711 |
| 012547 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:36am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596609.9 | 511930.8 | 2314 | 1.64041666667 | 12547 |
| 012197 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:36am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596610.4 | 511928.3 | 2315 | 1.64041666667 | 12197 |
| 013429 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:38am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596611.9 | 511925.9 | 2318 | 1.64041666667 | 13429 |
| 013977 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:38am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596612.4 | 511924.5 | 2319 | 1.64041666667 | 13977 |
| 012374 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:40am | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596612.3 | 511924.9 | 2322 | 1.64041666667 | 12374 |
| 012933 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:40am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596611.5 | 511925.6 | 2323 | 1.64041666667 | 12933 |
| 013013 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:42am | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596612.6 | 511924.6 | 2326 | 1.64041666667 | 13013 |
| 015193 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:42am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596613.0 | 511922.6 | 2327 | 1.64041666667 | 15193 |
| 013758 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:44am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596615.6 | 511920.7 | 2330 | 1.64041666667 | 13758 |
| 014419 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:44am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596615.7 | 511919.2 | 2331 | 1.64041666667 | 14419 |
| 015034 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:46am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596615.5 | 511919.6 | 2334 | 1.64041666667 | 15034 |
| 014978 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:46am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596615.7 | 511919.6 | 2335 | 1.64041666667 | 14978 |
| 014844 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:48am | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596617.3 | 511918.2 | 2338 | 1.64041666667 | 14844 |
| 013791 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:48am | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596617.6 | 511918.1 | 2339 | 1.64041666667 | 13791 |
| 014847 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:50am | Sensor | 1797-S0002-G-TJV.cor | 6851.7 | 1596617.6 | 511918.0 | 2342 | 1.64041666667 | 14847 |
| 015112 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:50am | Sensor | 1797-S0002-G-TJV.cor | 6851.4 | 1596617.7 | 511917.9 | 2343 | 1.64041666667 | 15112 |
| 013978 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:52am | Sensor | 1797-S0002-G-TJV.cor | 6851.3 | 1596617.8 | 511917.8 | 2346 | 1.64041666667 | 13978 |
| 012314 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:53am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596616.6 | 511918.3 | 2348 | 1.64041666667 | 12314 |
| 012288 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596614.1 | 511919.1 | 2350 | 1.64041666667 | 12288 |
| 012822 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:54am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596613.2 | 511920.3 | 2351 | 1.64041666667 | 12822 |
| 012655 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596612.7 | 511922.1 | 2354 | 1.64041666667 | 12655 |
| 012524 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:56am | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596612.0 | 511923.9 | 2355 | 1.64041666667 | 12524 |
| 014051 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:58am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596614.0 | 511924.7 | 2358 | 1.64041666667 | 14051 |
| 015152 | 0 | GeoXH 6000 | 08/20/2015 | 11:58:58am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596615.4 | 511925.5 | 2359 | 1.64041666667 | 15152 |
| 014018 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:00am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596618.5 | 511925.9 | 2362 | 1.64041666667 | 14018 |
| 013434 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:00am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596620.3 | 511927.0 | 2363 | 1.64041666667 | 13434 |
| 014428 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:02am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596622.7 | 511927.5 | 2366 | 1.64041666667 | 14428 |
| 014317 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:02am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596623.9 | 511928.6 | 2367 | 1.64041666667 | 14317 |
| 013119 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:04am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596625.9 | 511928.7 | 2370 | 1.64041666667 | 13119 |
| 011769 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:05am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596627.5 | 511930.1 | 2372 | 1.64041666667 | 11769 |
| 011342 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:05am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596630.0 | 511930.9 | 2373 | 1.64041666667 | 11342 |
| 012915 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:06am | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596632.4 | 511931.8 | 2375 | 1.64041666667 | 12915 |
| 015138 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:07am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596634.6 | 511933.5 | 2377 | 1.64041666667 | 15138 |
| 014104 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:08am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596636.8 | 511933.9 | 2379 | 1.64041666667 | 14104 |
| 011896 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:09am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596639.4 | 511935.0 | 2381 | 1.64041666667 | 11896 |
| 012274 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:11am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596642.0 | 511935.2 | 2384 | 1.64041666667 | 12274 |
| 011108 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:12am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596643.9 | 511936.3 | 2386 | 1.64041666667 | 11108 |
| 013217 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:12am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596645.6 | 511936.0 | 2387 | 1.64041666667 | 13217 |
| 012124 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:14am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596647.7 | 511937.1 | 2390 | 1.64041666667 | 12124 |
| 013531 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:14am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596649.5 | 511937.7 | 2391 | 1.64041666667 | 13531 |
| 011722 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:16am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596652.4 | 511938.8 | 2394 | 1.64041666667 | 11722 |
| 011780 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:16am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596654.6 | 511939.1 | 2395 | 1.64041666667 | 11780 |
| 010745 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:18am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596656.9 | 511941.0 | 2398 | 1.64041666667 | 10745 |
| 011416 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:18am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596659.0 | 511941.5 | 2399 | 1.64041666667 | 11416 |
| 012754 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:20am | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596660.7 | 511943.6 | 2402 | 1.64041666667 | 12754 |
| 010718 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:20am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596662.5 | 511944.4 | 2403 | 1.64041666667 | 10718 |
| 010569 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:22am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596664.0 | 511946.4 | 2406 | 1.64041666667 | 10569 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 010712 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:22am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596666.1 | 511946.8 | 2407 | 1.64041666667 | 10712 |
| 011888 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:24am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596668.1 | 511948.1 | 2410 | 1.64041666667 | 11888 |
| 012332 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:24am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596670.7 | 511948.5 | 2411 | 1.64041666667 | 12332 |
| 011903 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:26am | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596672.9 | 511950.3 | 2414 | 1.64041666667 | 11903 |
| 011495 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:26am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596675.0 | 511951.0 | 2415 | 1.64041666667 | 11495 |
| 012324 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:28am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596676.5 | 511952.3 | 2418 | 1.64041666667 | 12324 |
| 012651 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:28am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596677.1 | 511952.3 | 2419 | 1.64041666667 | 12651 |
| 011982 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:30am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596676.9 | 511953.9 | 2422 | 1.64041666667 | 11982 |
| 013375 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:30am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596676.6 | 511953.8 | 2423 | 1.64041666667 | 13375 |
| 012824 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:32am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596677.8 | 511952.5 | 2426 | 1.64041666667 | 12824 |
| 010646 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:33am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596679.3 | 511950.6 | 2428 | 1.64041666667 | 10646 |
| 012051 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:34am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596681.1 | 511951.3 | 2430 | 1.64041666667 | 12051 |
| 011742 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:34am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596683.2 | 511951.7 | 2431 | 1.64041666667 | 11742 |
| 012115 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:36am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596685.5 | 511952.9 | 2434 | 1.64041666667 | 12115 |
| 012569 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:36am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596687.9 | 511953.5 | 2435 | 1.64041666667 | 12569 |
| 015562 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:38am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596690.9 | 511954.3 | 2438 | 1.64041666667 | 15562 |
| 014480 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:38am | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596693.5 | 511955.6 | 2439 | 1.64041666667 | 14480 |
| 015860 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:39am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596696.2 | 511956.5 | 2441 | 1.64041666667 | 15860 |
| 014015 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:40am | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596697.9 | 511958.1 | 2443 | 1.64041666667 | 14015 |
| 015653 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:41am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596700.3 | 511958.9 | 2445 | 1.64041666667 | 15653 |
| 014863 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:42am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596702.1 | 511960.3 | 2447 | 1.64041666667 | 14863 |
| 014726 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:43am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596704.7 | 511961.0 | 2449 | 1.64041666667 | 14726 |
| 014541 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:44am | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596706.5 | 511962.5 | 2451 | 1.64041666667 | 14541 |
| 014945 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:45am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596709.0 | 511963.5 | 2453 | 1.64041666667 | 14945 |
| 012856 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:46am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596711.3 | 511964.7 | 2455 | 1.64041666667 | 12856 |
| 012484 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:47am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596714.2 | 511964.8 | 2457 | 1.64041666667 | 12484 |
| 012301 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:48am | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596716.7 | 511964.9 | 2459 | 1.64041666667 | 12301 |
| 014865 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:49am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596719.4 | 511965.1 | 2461 | 1.64041666667 | 14865 |
| 014666 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:50am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596721.8 | 511965.5 | 2463 | 1.64041666667 | 14666 |
| 016026 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:52am | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596724.6 | 511966.6 | 2466 | 1.64041666667 | 16026 |
| 015946 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:52am | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596726.7 | 511966.8 | 2467 | 1.64041666667 | 15946 |
| 015836 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:54am | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596729.0 | 511967.9 | 2470 | 1.64041666667 | 15836 |
| 013619 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:54am | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596731.2 | 511967.4 | 2471 | 1.64041666667 | 13619 |
| 017115 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:56am | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596734.2 | 511968.6 | 2474 | 1.64041666667 | 17115 |
| 015648 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:56am | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596736.1 | 511968.6 | 2475 | 1.64041666667 | 15648 |
| 014592 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:57am | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596737.6 | 511970.3 | 2477 | 1.64041666667 | 14592 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:58am | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596738.9 | 511970.1 | 2479 | 1.64041666667 | 11928 |
| 012192 | 0 | GeoXH 6000 | 08/20/2015 | 11:59:59am | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596739.0 | 511969.6 | 2481 | 1.64041666667 | 12192 |
| 012888 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596739.1 | 511970.7 | 2483 | 1.64041666667 | 12888 |
| 012342 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596739.1 | 511969.7 | 2485 | 1.64041666667 | 12342 |
| 013525 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596740.2 | 511967.8 | 2487 | 1.64041666667 | 13525 |
| 012201 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596740.7 | 511964.8 | 2490 | 1.64041666667 | 12201 |
| 012590 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596740.9 | 511964.1 | 2491 | 1.64041666667 | 12590 |
| 011217 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596740.9 | 511964.1 | 2494 | 1.64041666667 | 11217 |
| 012614 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596740.9 | 511964.3 | 2495 | 1.64041666667 | 12614 |
| 011223 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596741.5 | 511963.1 | 2497 | 1.64041666667 | 11223 |
| 011985 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596742.5 | 511960.5 | 2499 | 1.64041666667 | 11985 |
| 013496 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596743.5 | 511958.8 | 2501 | 1.64041666667 | 13496 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013064 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596745.4 | 511956.9 | 2503 | 1.64041666667 | 13064 |
| 014846 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:11pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596745.9 | 511956.5 | 2505 | 1.64041666667 | 14846 |
| 012621 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:12pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596745.8 | 511956.7 | 2507 | 1.64041666667 | 12621 |
| 012515 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:13pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596745.9 | 511956.7 | 2509 | 1.64041666667 | 12515 |
| 013328 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:14pm | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596746.1 | 511956.3 | 2511 | 1.64041666667 | 13328 |
| 013412 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:15pm | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596746.3 | 511956.1 | 2513 | 1.64041666667 | 13412 |
| 014723 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596747.0 | 511955.3 | 2515 | 1.64041666667 | 14723 |
| 012560 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:18pm | Sensor | 1797-S0002-G-TJV.cor | 6855.1 | 1596745.5 | 511956.2 | 2518 | 1.64041666667 | 12560 |
| 013160 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:18pm | Sensor | 1797-S0002-G-TJV.cor | 6855.1 | 1596744.5 | 511956.6 | 2519 | 1.64041666667 | 13160 |
| 014030 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:19pm | Sensor | 1797-S0002-G-TJV.cor | 6855.1 | 1596744.6 | 511958.1 | 2521 | 1.64041666667 | 14030 |
| 012087 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:20pm | Sensor | 1797-S0002-G-TJV.cor | 6855.1 | 1596743.4 | 511959.9 | 2523 | 1.64041666667 | 12087 |
| 013102 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596741.3 | 511963.4 | 2526 | 1.64041666667 | 13102 |
| 011945 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596740.3 | 511964.4 | 2527 | 1.64041666667 | 11945 |
| 013276 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596739.9 | 511964.6 | 2530 | 1.64041666667 | 13276 |
| 013969 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596740.0 | 511964.5 | 2531 | 1.64041666667 | 13969 |
| 015162 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596740.0 | 511964.5 | 2533 | 1.64041666667 | 15162 |
| 014020 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596740.0 | 511964.4 | 2535 | 1.64041666667 | 14020 |
| 014245 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596737.9 | 511963.8 | 2538 | 1.64041666667 | 14245 |
| 014871 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596735.9 | 511962.6 | 2539 | 1.64041666667 | 14871 |
| 015387 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596732.9 | 511962.4 | 2542 | 1.64041666667 | 15387 |
| 017287 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596730.7 | 511961.4 | 2543 | 1.64041666667 | 17287 |
| 018331 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596728.3 | 511960.6 | 2545 | 1.64041666667 | 18331 |
| 018502 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596726.8 | 511960.0 | 2547 | 1.64041666667 | 18502 |
| 016745 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:33pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596724.8 | 511959.9 | 2549 | 1.64041666667 | 16745 |
| 014536 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:34pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596723.4 | 511959.8 | 2551 | 1.64041666667 | 14536 |
| 013294 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596722.0 | 511960.1 | 2553 | 1.64041666667 | 13294 |
| 015713 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596722.4 | 511960.0 | 2555 | 1.64041666667 | 15713 |
| 016828 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596722.9 | 511959.9 | 2557 | 1.64041666667 | 16828 |
| 016387 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596723.8 | 511958.5 | 2559 | 1.64041666667 | 16387 |
| 015136 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596724.5 | 511959.5 | 2561 | 1.64041666667 | 15136 |
| 016174 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596727.5 | 511960.2 | 2563 | 1.64041666667 | 16174 |
| 016793 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:42pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596728.0 | 511960.2 | 2566 | 1.64041666667 | 16793 |
| 016528 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:42pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596728.3 | 511960.1 | 2567 | 1.64041666667 | 16528 |
| 017272 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596726.2 | 511959.1 | 2570 | 1.64041666667 | 17272 |
| 017668 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596725.8 | 511958.4 | 2571 | 1.64041666667 | 17668 |
| 017017 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596724.3 | 511958.7 | 2573 | 1.64041666667 | 17017 |
| 014724 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596722.9 | 511958.2 | 2575 | 1.64041666667 | 14724 |
| 013731 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596720.3 | 511957.3 | 2577 | 1.64041666667 | 13731 |
| 013932 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596718.3 | 511956.5 | 2579 | 1.64041666667 | 13932 |
| 014163 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596716.2 | 511955.5 | 2581 | 1.64041666667 | 14163 |
| 013050 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596714.3 | 511955.1 | 2583 | 1.64041666667 | 13050 |
| 011692 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:51pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596711.6 | 511954.0 | 2585 | 1.64041666667 | 11692 |
| 012223 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:52pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596709.8 | 511953.9 | 2587 | 1.64041666667 | 12223 |
| 013556 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:54pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596708.5 | 511953.9 | 2590 | 1.64041666667 | 13556 |
| 013919 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596706.8 | 511952.2 | 2591 | 1.64041666667 | 13919 |
| 013799 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596704.0 | 511951.3 | 2594 | 1.64041666667 | 13799 |
| 015840 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596702.0 | 511949.2 | 2595 | 1.64041666667 | 15840 |
| 016050 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596699.7 | 511949.2 | 2598 | 1.64041666667 | 16050 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 015052 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:59pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596697.8 | 511948.9 | 2600 | 1.64041666667 | 15052 |
| 014113 | 0 | GeoXH 6000 | 08/20/2015 | 12:00:59pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596695.5 | 511948.6 | 2601 | 1.64041666667 | 14113 |
| 015468 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:00pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596693.4 | 511947.9 | 2603 | 1.64041666667 | 15468 |
| 015867 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:01pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596690.6 | 511946.2 | 2605 | 1.64041666667 | 15867 |
| 014196 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:02pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596688.2 | 511945.8 | 2607 | 1.64041666667 | 14196 |
| 011289 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:03pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596685.5 | 511944.5 | 2609 | 1.64041666667 | 11289 |
| 012692 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596683.0 | 511943.9 | 2611 | 1.64041666667 | 12692 |
| 011393 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596680.7 | 511942.2 | 2614 | 1.64041666667 | 11393 |
| 013858 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596679.0 | 511941.8 | 2615 | 1.64041666667 | 13858 |
| 014324 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596677.6 | 511939.7 | 2617 | 1.64041666667 | 14324 |
| 013691 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596674.7 | 511938.9 | 2619 | 1.64041666667 | 13691 |
| 011582 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596672.5 | 511937.4 | 2621 | 1.64041666667 | 11582 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596670.2 | 511937.7 | 2623 | 1.64041666667 | 11205 |
| 011201 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:11pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596667.9 | 511936.8 | 2625 | 1.64041666667 | 11201 |
| 011320 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:12pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596665.5 | 511936.2 | 2627 | 1.64041666667 | 11320 |
| 011470 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:14pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596662.6 | 511934.4 | 2630 | 1.64041666667 | 11470 |
| 010955 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:14pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596660.4 | 511933.6 | 2631 | 1.64041666667 | 10955 |
| 010984 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:15pm | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596658.1 | 511932.8 | 2633 | 1.64041666667 | 10984 |
| 011266 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:16pm | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596655.6 | 511931.9 | 2635 | 1.64041666667 | 11266 |
| 010286 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:17pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596653.0 | 511931.4 | 2637 | 1.64041666667 | 10286 |
| 010731 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:18pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596650.9 | 511930.6 | 2639 | 1.64041666667 | 10731 |
| 011623 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:19pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596648.0 | 511930.3 | 2641 | 1.64041666667 | 11623 |
| 011545 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:20pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596646.0 | 511929.7 | 2643 | 1.64041666667 | 11545 |
| 010896 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:21pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596643.8 | 511930.1 | 2645 | 1.64041666667 | 10896 |
| 010434 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:22pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596641.8 | 511929.1 | 2647 | 1.64041666667 | 10434 |
| 011398 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:24pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596639.0 | 511928.7 | 2650 | 1.64041666667 | 11398 |
| 013349 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:24pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596637.8 | 511927.4 | 2651 | 1.64041666667 | 13349 |
| 015367 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:26pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596635.1 | 511926.8 | 2654 | 1.64041666667 | 15367 |
| 013471 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:26pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596633.5 | 511925.3 | 2655 | 1.64041666667 | 13471 |
| 015067 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:28pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596630.7 | 511924.7 | 2658 | 1.64041666667 | 15067 |
| 013517 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:28pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596628.7 | 511923.2 | 2659 | 1.64041666667 | 13517 |
| 015739 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:30pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596626.1 | 511923.0 | 2662 | 1.64041666667 | 15739 |
| 016714 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:30pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596624.5 | 511921.4 | 2663 | 1.64041666667 | 16714 |
| 015488 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:31pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596622.1 | 511921.0 | 2665 | 1.64041666667 | 15488 |
| 014042 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:32pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596620.7 | 511919.2 | 2667 | 1.64041666667 | 14042 |
| 014790 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:33pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596618.4 | 511917.9 | 2669 | 1.64041666667 | 14790 |
| 015127 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:34pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596617.1 | 511917.0 | 2671 | 1.64041666667 | 15127 |
| 014132 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:35pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596617.8 | 511917.4 | 2673 | 1.64041666667 | 14132 |
| 013883 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:36pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596618.6 | 511915.3 | 2675 | 1.64041666667 | 13883 |
| 014180 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:37pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596618.7 | 511912.5 | 2677 | 1.64041666667 | 14180 |
| 015305 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:38pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596620.1 | 511912.1 | 2679 | 1.64041666667 | 15305 |
| 014686 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:40pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596620.7 | 511912.0 | 2682 | 1.64041666667 | 14686 |
| 014183 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:40pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596620.9 | 511911.9 | 2683 | 1.64041666667 | 14183 |
| 015018 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:42pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596620.6 | 511911.9 | 2686 | 1.64041666667 | 15018 |
| 015814 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:42pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596621.3 | 511909.6 | 2687 | 1.64041666667 | 15814 |
| 015743 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:44pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596623.1 | 511907.4 | 2690 | 1.64041666667 | 15743 |
| 015126 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:44pm | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596624.5 | 511904.8 | 2691 | 1.64041666667 | 15126 |
| 018031 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:46pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596624.7 | 511904.4 | 2694 | 1.64041666667 | 18031 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 016447 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:46pm | Sensor | 1797-S0002-G-TJV.cor | 6851.6 | 1596624.7 | 511904.1 | 2695 | 1.64041666667 | 16447 |
| 016142 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:47pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596624.5 | 511904.2 | 2697 | 1.64041666667 | 16142 |
| 015705 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:48pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596622.7 | 511905.1 | 2699 | 1.64041666667 | 15705 |
| 015506 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:49pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596621.4 | 511905.7 | 2701 | 1.64041666667 | 15506 |
| 015456 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:50pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596621.3 | 511907.5 | 2703 | 1.64041666667 | 15456 |
| 014784 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:51pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596619.8 | 511909.9 | 2705 | 1.64041666667 | 14784 |
| 014466 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:52pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596618.7 | 511911.6 | 2707 | 1.64041666667 | 14466 |
| 014296 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:54pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596618.6 | 511911.7 | 2710 | 1.64041666667 | 14296 |
| 013868 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:54pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596619.4 | 511911.5 | 2711 | 1.64041666667 | 13868 |
| 015368 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:55pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596619.3 | 511911.6 | 2713 | 1.64041666667 | 15368 |
| 016502 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:56pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596619.2 | 511911.6 | 2715 | 1.64041666667 | 16502 |
| 015225 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:57pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596619.8 | 511911.4 | 2717 | 1.64041666667 | 15225 |
| 015446 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:58pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596620.5 | 511912.1 | 2719 | 1.64041666667 | 15446 |
| 013761 | 0 | GeoXH 6000 | 08/20/2015 | 12:01:59pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596622.6 | 511912.9 | 2721 | 1.64041666667 | 13761 |
| 015290 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:00pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596624.8 | 511914.4 | 2723 | 1.64041666667 | 15290 |
| 014652 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:02pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596627.5 | 511915.3 | 2726 | 1.64041666667 | 14652 |
| 015243 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:02pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596629.6 | 511916.5 | 2727 | 1.64041666667 | 15243 |
| 015810 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:04pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596632.5 | 511917.1 | 2730 | 1.64041666667 | 15810 |
| 015982 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596634.0 | 511918.7 | 2731 | 1.64041666667 | 15982 |
| 014495 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596636.4 | 511919.6 | 2733 | 1.64041666667 | 14495 |
| 013494 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:06pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596637.8 | 511921.2 | 2735 | 1.64041666667 | 13494 |
| 014893 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:07pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596640.4 | 511921.9 | 2737 | 1.64041666667 | 14893 |
| 015603 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:08pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596642.3 | 511923.2 | 2739 | 1.64041666667 | 15603 |
| 011970 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:10pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596644.5 | 511923.0 | 2742 | 1.64041666667 | 11970 |
| 011572 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:10pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596645.9 | 511923.5 | 2743 | 1.64041666667 | 11572 |
| 012733 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:11pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596646.8 | 511923.7 | 2745 | 1.64041666667 | 12733 |
| 012753 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:12pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596646.6 | 511923.8 | 2747 | 1.64041666667 | 12753 |
| 010598 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:13pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596646.6 | 511923.8 | 2749 | 1.64041666667 | 10598 |
| 012129 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:14pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596646.6 | 511923.8 | 2751 | 1.64041666667 | 12129 |
| 012602 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:15pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596646.7 | 511924.1 | 2753 | 1.64041666667 | 12602 |
| 012330 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:16pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596646.7 | 511924.4 | 2755 | 1.64041666667 | 12330 |
| 011902 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:18pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596647.7 | 511923.7 | 2758 | 1.64041666667 | 11902 |
| 013115 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596649.2 | 511922.6 | 2759 | 1.64041666667 | 13115 |
| 011949 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596649.7 | 511923.0 | 2761 | 1.64041666667 | 11949 |
| 011837 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:20pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596651.9 | 511920.1 | 2763 | 1.64041666667 | 11837 |
| 011539 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:21pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596652.6 | 511919.3 | 2765 | 1.64041666667 | 11539 |
| 010774 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:22pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596652.6 | 511919.1 | 2767 | 1.64041666667 | 10774 |
| 010673 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596651.2 | 511920.2 | 2769 | 1.64041666667 | 10673 |
| 011368 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:24pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596650.2 | 511920.7 | 2771 | 1.64041666667 | 11368 |
| 010492 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:25pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596650.2 | 511922.9 | 2773 | 1.64041666667 | 10492 |
| 011053 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:26pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596649.3 | 511924.5 | 2775 | 1.64041666667 | 11053 |
| 010353 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:28pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596650.3 | 511924.5 | 2778 | 1.64041666667 | 10353 |
| 010688 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:28pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596651.9 | 511925.7 | 2779 | 1.64041666667 | 10688 |
| 010772 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:29pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596654.4 | 511926.9 | 2781 | 1.64041666667 | 10772 |
| 011386 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:30pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596656.8 | 511927.9 | 2783 | 1.64041666667 | 11386 |
| 011413 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:31pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596660.2 | 511928.8 | 2785 | 1.64041666667 | 11413 |
| 011193 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:32pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596662.6 | 511929.2 | 2787 | 1.64041666667 | 11193 |
| 010568 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:33pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596665.8 | 511930.3 | 2789 | 1.64041666667 | 10568 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 009812 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:34pm | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596668.6 | 511930.4 | 2791 | 1.64041666667 | 9812 |
| 011513 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:35pm | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596671.7 | 511931.0 | 2793 | 1.64041666667 | 11513 |
| 013438 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:36pm | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596674.1 | 511930.5 | 2795 | 1.64041666667 | 13438 |
| 012269 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:37pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596676.8 | 511931.2 | 2797 | 1.64041666667 | 12269 |
| 013147 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:38pm | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596679.5 | 511931.4 | 2799 | 1.64041666667 | 13147 |
| 012856 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:39pm | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596682.1 | 511932.0 | 2801 | 1.64041666667 | 12856 |
| 012004 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:40pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596684.3 | 511931.8 | 2803 | 1.64041666667 | 12004 |
| 011491 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:41pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596686.6 | 511932.9 | 2805 | 1.64041666667 | 11491 |
| 012412 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:42pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596688.8 | 511933.7 | 2807 | 1.64041666667 | 12412 |
| 014263 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:43pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596690.8 | 511934.8 | 2809 | 1.64041666667 | 14263 |
| 015926 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:44pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596693.0 | 511935.9 | 2811 | 1.64041666667 | 15926 |
| 016641 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:45pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596695.0 | 511936.5 | 2813 | 1.64041666667 | 16641 |
| 013730 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:46pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596696.7 | 511937.1 | 2815 | 1.64041666667 | 13730 |
| 014892 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:47pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596697.9 | 511938.1 | 2817 | 1.64041666667 | 14892 |
| 017493 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596699.9 | 511938.9 | 2819 | 1.64041666667 | 17493 |
| 017723 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596700.7 | 511940.1 | 2821 | 1.64041666667 | 17723 |
| 018290 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596702.7 | 511939.9 | 2823 | 1.64041666667 | 18290 |
| 015432 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:51pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596703.8 | 511940.2 | 2825 | 1.64041666667 | 15432 |
| 014328 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:52pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596705.8 | 511941.6 | 2827 | 1.64041666667 | 14328 |
| 014442 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596708.1 | 511941.4 | 2829 | 1.64041666667 | 14442 |
| 013240 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596708.5 | 511941.3 | 2831 | 1.64041666667 | 13240 |
| 010930 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596709.8 | 511942.0 | 2833 | 1.64041666667 | 10930 |
| 012242 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596711.7 | 511942.6 | 2835 | 1.64041666667 | 12242 |
| 012420 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:57pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596713.2 | 511944.3 | 2837 | 1.64041666667 | 12420 |
| 014295 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596714.8 | 511945.0 | 2839 | 1.64041666667 | 14295 |
| 012783 | 0 | GeoXH 6000 | 08/20/2015 | 12:02:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596716.6 | 511946.0 | 2841 | 1.64041666667 | 12783 |
| 014776 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596718.6 | 511947.0 | 2843 | 1.64041666667 | 14776 |
| 014044 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596721.0 | 511948.4 | 2845 | 1.64041666667 | 14044 |
| 016561 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596723.0 | 511950.0 | 2847 | 1.64041666667 | 16561 |
| 020010 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:03pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596725.6 | 511950.7 | 2849 | 1.64041666667 | 20010 |
| 017452 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596727.6 | 511951.8 | 2851 | 1.64041666667 | 17452 |
| 017953 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596730.4 | 511952.2 | 2853 | 1.64041666667 | 17953 |
| 017838 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596732.3 | 511953.6 | 2855 | 1.64041666667 | 17838 |
| 016939 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596734.8 | 511954.0 | 2857 | 1.64041666667 | 16939 |
| 012844 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596736.4 | 511955.3 | 2859 | 1.64041666667 | 12844 |
| 010771 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596738.9 | 511955.9 | 2861 | 1.64041666667 | 10771 |
| 012802 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596741.1 | 511956.9 | 2863 | 1.64041666667 | 12802 |
| 013430 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:11pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596743.6 | 511956.9 | 2865 | 1.64041666667 | 13430 |
| 013257 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:12pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596745.4 | 511956.1 | 2867 | 1.64041666667 | 13257 |
| 013994 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596744.7 | 511956.5 | 2869 | 1.64041666667 | 13994 |
| 014958 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596744.8 | 511957.1 | 2871 | 1.64041666667 | 14958 |
| 013759 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596744.9 | 511957.4 | 2873 | 1.64041666667 | 13759 |
| 013039 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596745.0 | 511957.2 | 2875 | 1.64041666667 | 13039 |
| 012440 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:17pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596745.3 | 511954.3 | 2877 | 1.64041666667 | 12440 |
| 010670 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596746.2 | 511952.1 | 2879 | 1.64041666667 | 10670 |
| 010647 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596746.4 | 511950.5 | 2881 | 1.64041666667 | 10647 |
| 011692 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596746.8 | 511949.8 | 2883 | 1.64041666667 | 11692 |
| 011323 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:21pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596746.7 | 511950.0 | 2885 | 1.64041666667 | 11323 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012250 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596746.5 | 511948.4 | 2887 | 1.64041666667 | 12250 |
| 011402 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596747.9 | 511946.1 | 2889 | 1.64041666667 | 11402 |
| 011340 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596749.0 | 511943.4 | 2891 | 1.64041666667 | 11340 |
| 010605 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596749.8 | 511944.0 | 2893 | 1.64041666667 | 10605 |
| 010331 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596749.8 | 511943.9 | 2895 | 1.64041666667 | 10331 |
| 011463 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596749.8 | 511944.0 | 2897 | 1.64041666667 | 11463 |
| 010875 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596749.7 | 511944.0 | 2899 | 1.64041666667 | 10875 |
| 010308 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:29pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596749.7 | 511944.1 | 2901 | 1.64041666667 | 10308 |
| 012237 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596749.6 | 511943.6 | 2903 | 1.64041666667 | 12237 |
| 011819 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596750.8 | 511943.0 | 2905 | 1.64041666667 | 11819 |
| 012375 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596750.2 | 511943.7 | 2907 | 1.64041666667 | 12375 |
| 011853 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:33pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596748.8 | 511944.6 | 2909 | 1.64041666667 | 11853 |
| 011843 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:34pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596747.9 | 511946.1 | 2911 | 1.64041666667 | 11843 |
| 011540 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596746.6 | 511948.0 | 2913 | 1.64041666667 | 11540 |
| 010325 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596745.3 | 511949.9 | 2915 | 1.64041666667 | 10325 |
| 011131 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596742.9 | 511949.4 | 2917 | 1.64041666667 | 11131 |
| 010792 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596740.7 | 511948.8 | 2919 | 1.64041666667 | 10792 |
| 011788 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596740.3 | 511948.4 | 2921 | 1.64041666667 | 11788 |
| 010747 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596740.0 | 511948.6 | 2923 | 1.64041666667 | 10747 |
| 012376 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:41pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596738.7 | 511947.5 | 2925 | 1.64041666667 | 12376 |
| 011494 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:42pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596736.4 | 511947.0 | 2927 | 1.64041666667 | 11494 |
| 011633 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:43pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596733.8 | 511946.2 | 2929 | 1.64041666667 | 11633 |
| 013768 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596731.5 | 511945.6 | 2931 | 1.64041666667 | 13768 |
| 016492 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596728.8 | 511944.6 | 2933 | 1.64041666667 | 16492 |
| 017203 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596726.6 | 511943.3 | 2935 | 1.64041666667 | 17203 |
| 017650 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596723.8 | 511942.9 | 2937 | 1.64041666667 | 17650 |
| 016412 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596721.9 | 511942.0 | 2939 | 1.64041666667 | 16412 |
| 014933 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596719.1 | 511941.4 | 2941 | 1.64041666667 | 14933 |
| 013213 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596718.0 | 511939.9 | 2943 | 1.64041666667 | 13213 |
| 012603 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:51pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596716.0 | 511939.0 | 2945 | 1.64041666667 | 12603 |
| 011850 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:52pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596714.4 | 511938.1 | 2947 | 1.64041666667 | 11850 |
| 011572 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596711.9 | 511938.5 | 2949 | 1.64041666667 | 11572 |
| 010693 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596711.4 | 511936.8 | 2951 | 1.64041666667 | 10693 |
| 011523 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596709.4 | 511934.9 | 2953 | 1.64041666667 | 11523 |
| 010560 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596708.3 | 511933.5 | 2955 | 1.64041666667 | 10560 |
| 011970 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:57pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596705.9 | 511932.9 | 2957 | 1.64041666667 | 11970 |
| 011632 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:58pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596703.9 | 511932.1 | 2959 | 1.64041666667 | 11632 |
| 012298 | 0 | GeoXH 6000 | 08/20/2015 | 12:03:59pm | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596701.0 | 511930.8 | 2961 | 1.64041666667 | 12298 |
| 011834 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:00pm | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596698.2 | 511930.1 | 2963 | 1.64041666667 | 11834 |
| 010608 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:01pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596695.2 | 511928.7 | 2965 | 1.64041666667 | 10608 |
| 011442 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:02pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596692.6 | 511928.4 | 2967 | 1.64041666667 | 11442 |
| 011740 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:03pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596689.6 | 511927.2 | 2969 | 1.64041666667 | 11740 |
| 011155 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:04pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596687.1 | 511927.3 | 2971 | 1.64041666667 | 11155 |
| 011668 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:05pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596684.3 | 511926.5 | 2973 | 1.64041666667 | 11668 |
| 011827 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:06pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596682.0 | 511926.9 | 2975 | 1.64041666667 | 11827 |
| 012226 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:07pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596679.5 | 511926.4 | 2977 | 1.64041666667 | 12226 |
| 011366 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:08pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596676.8 | 511926.4 | 2979 | 1.64041666667 | 11366 |
| 013011 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:09pm | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596673.9 | 511925.2 | 2981 | 1.64041666667 | 13011 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 011053 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:10pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596671.6 | 511924.4 | 2983 | 1.64041666667 | 11053 |
| 011373 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:11pm | Sensor | 1797-S0002-G-TJV.cor | 6851.8 | 1596668.9 | 511923.6 | 2985 | 1.64041666667 | 11373 |
| 011303 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:12pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596666.5 | 511922.7 | 2987 | 1.64041666667 | 11303 |
| 010625 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:13pm | Sensor | 1797-S0002-G-TJV.cor | 6852.0 | 1596663.8 | 511921.8 | 2989 | 1.64041666667 | 10625 |
| 011506 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:14pm | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596661.9 | 511920.5 | 2991 | 1.64041666667 | 11506 |
| 010466 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:15pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596659.4 | 511919.6 | 2993 | 1.64041666667 | 10466 |
| 011436 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:16pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596658.2 | 511918.7 | 2995 | 1.64041666667 | 11436 |
| 010329 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:17pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596656.6 | 511917.9 | 2997 | 1.64041666667 | 10329 |
| 011582 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:18pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596655.3 | 511917.9 | 2999 | 1.64041666667 | 11582 |
| 010545 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:19pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596654.6 | 511917.4 | 3001 | 1.64041666667 | 10545 |
| 010886 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:20pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596655.2 | 511917.8 | 3003 | 1.64041666667 | 10886 |
| 010041 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:21pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596655.5 | 511918.0 | 3005 | 1.64041666667 | 10041 |
| 011810 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:22pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596655.1 | 511917.9 | 3007 | 1.64041666667 | 11810 |
| 011202 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:23pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596655.1 | 511918.2 | 3009 | 1.64041666667 | 11202 |
| 012070 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:24pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596655.2 | 511917.8 | 3011 | 1.64041666667 | 12070 |
| 010277 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:25pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596655.6 | 511915.8 | 3013 | 1.64041666667 | 10277 |
| 011209 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:26pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596655.3 | 511912.7 | 3015 | 1.64041666667 | 11209 |
| 011052 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:27pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596655.0 | 511913.0 | 3017 | 1.64041666667 | 11052 |
| 011283 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:28pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596655.1 | 511914.6 | 3019 | 1.64041666667 | 11283 |
| 011160 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:29pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596655.7 | 511916.6 | 3021 | 1.64041666667 | 11160 |
| 010860 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:30pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596654.7 | 511918.0 | 3023 | 1.64041666667 | 10860 |
| 011025 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:31pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596652.8 | 511917.9 | 3025 | 1.64041666667 | 11025 |
| 010646 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:32pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596651.4 | 511918.1 | 3027 | 1.64041666667 | 10646 |
| 012021 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:33pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596649.7 | 511917.3 | 3029 | 1.64041666667 | 12021 |
| 010685 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:34pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596648.4 | 511915.9 | 3031 | 1.64041666667 | 10685 |
| 010921 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596646.2 | 511914.0 | 3033 | 1.64041666667 | 10921 |
| 012840 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596645.0 | 511911.9 | 3035 | 1.64041666667 | 12840 |
| 012780 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596643.1 | 511912.3 | 3037 | 1.64041666667 | 12780 |
| 013875 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:38pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596641.8 | 511911.3 | 3039 | 1.64041666667 | 13875 |
| 016368 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:40pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596638.9 | 511910.8 | 3042 | 1.64041666667 | 16368 |
| 016182 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:40pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596637.1 | 511910.3 | 3043 | 1.64041666667 | 16182 |
| 017005 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:41pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596635.5 | 511910.6 | 3045 | 1.64041666667 | 17005 |
| 017181 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:42pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596634.8 | 511910.6 | 3047 | 1.64041666667 | 17181 |
| 016835 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:43pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596633.6 | 511910.9 | 3049 | 1.64041666667 | 16835 |
| 015608 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:44pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596631.9 | 511910.1 | 3051 | 1.64041666667 | 15608 |
| 015752 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:45pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596630.0 | 511908.5 | 3053 | 1.64041666667 | 15752 |
| 016028 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:46pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596628.4 | 511907.7 | 3055 | 1.64041666667 | 16028 |
| 018227 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:47pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596626.9 | 511906.1 | 3057 | 1.64041666667 | 18227 |
| 018356 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:48pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596625.1 | 511904.9 | 3059 | 1.64041666667 | 18356 |
| 017729 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:49pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596623.9 | 511904.3 | 3061 | 1.64041666667 | 17729 |
| 015472 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:50pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596624.3 | 511904.3 | 3063 | 1.64041666667 | 15472 |
| 016558 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:51pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596623.1 | 511903.1 | 3065 | 1.64041666667 | 16558 |
| 018509 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:52pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596620.8 | 511901.8 | 3067 | 1.64041666667 | 18509 |
| 017437 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:53pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596618.1 | 511900.8 | 3069 | 1.64041666667 | 17437 |
| 017619 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:54pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596617.3 | 511901.1 | 3071 | 1.64041666667 | 17619 |
| 017184 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:55pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596616.8 | 511902.2 | 3073 | 1.64041666667 | 17184 |
| 015336 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:56pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596618.4 | 511902.3 | 3075 | 1.64041666667 | 15336 |
| 018384 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:57pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596619.9 | 511903.2 | 3077 | 1.64041666667 | 18384 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 017106 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:58pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596621.8 | 511903.4 | 3079 | 1.64041666667 | 17106 |
| 017866 | 0 | GeoXH 6000 | 08/20/2015 | 12:04:59pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596623.8 | 511904.2 | 3081 | 1.64041666667 | 17866 |
| 016436 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:00pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596624.3 | 511903.9 | 3083 | 1.64041666667 | 16436 |
| 016169 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:01pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596625.7 | 511901.2 | 3085 | 1.64041666667 | 16169 |
| 018172 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:02pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596626.8 | 511900.1 | 3087 | 1.64041666667 | 18172 |
| 019723 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:03pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596627.4 | 511899.5 | 3089 | 1.64041666667 | 19723 |
| 018220 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:04pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596627.1 | 511899.0 | 3091 | 1.64041666667 | 18220 |
| 018385 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596627.4 | 511896.3 | 3093 | 1.64041666667 | 18385 |
| 019176 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596628.5 | 511894.3 | 3095 | 1.64041666667 | 19176 |
| 020694 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:07pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596629.2 | 511891.2 | 3097 | 1.64041666667 | 20694 |
| 020607 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:08pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596629.4 | 511890.9 | 3099 | 1.64041666667 | 20607 |
| 019976 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:09pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596629.6 | 511890.9 | 3101 | 1.64041666667 | 19976 |
| 019454 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:10pm | Sensor | 1797-S0002-G-TJV.cor | 6851.9 | 1596629.6 | 511890.5 | 3103 | 1.64041666667 | 19454 |
| 019203 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:11pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596629.6 | 511890.8 | 3105 | 1.64041666667 | 19203 |
| 018930 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596628.0 | 511892.5 | 3107 | 1.64041666667 | 18930 |
| 017752 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596627.8 | 511892.3 | 3109 | 1.64041666667 | 17752 |
| 018628 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596627.3 | 511893.0 | 3111 | 1.64041666667 | 18628 |
| 018007 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596627.1 | 511893.8 | 3113 | 1.64041666667 | 18007 |
| 016921 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596626.5 | 511896.5 | 3115 | 1.64041666667 | 16921 |
| 017400 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:17pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596626.3 | 511898.8 | 3117 | 1.64041666667 | 17400 |
| 016920 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596625.9 | 511899.9 | 3119 | 1.64041666667 | 16920 |
| 017940 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596627.6 | 511900.5 | 3121 | 1.64041666667 | 17940 |
| 017715 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596629.3 | 511901.8 | 3123 | 1.64041666667 | 17715 |
| 015318 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:21pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596631.8 | 511902.3 | 3125 | 1.64041666667 | 15318 |
| 016759 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596633.6 | 511903.4 | 3127 | 1.64041666667 | 16759 |
| 015620 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596636.2 | 511903.9 | 3129 | 1.64041666667 | 15620 |
| 014495 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596637.9 | 511905.1 | 3131 | 1.64041666667 | 14495 |
| 015203 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596640.7 | 511905.6 | 3133 | 1.64041666667 | 15203 |
| 013461 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596642.3 | 511906.8 | 3135 | 1.64041666667 | 13461 |
| 012755 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596644.4 | 511906.5 | 3137 | 1.64041666667 | 12755 |
| 011468 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596645.9 | 511907.8 | 3139 | 1.64041666667 | 11468 |
| 012557 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:29pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596648.4 | 511908.2 | 3141 | 1.64041666667 | 12557 |
| 012169 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596650.0 | 511909.1 | 3143 | 1.64041666667 | 12169 |
| 009942 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596652.0 | 511909.4 | 3145 | 1.64041666667 | 9942 |
| 010885 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:32pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596653.8 | 511909.9 | 3147 | 1.64041666667 | 10885 |
| 011631 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:33pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596654.1 | 511910.5 | 3149 | 1.64041666667 | 11631 |
| 012957 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:34pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596654.2 | 511910.6 | 3151 | 1.64041666667 | 12957 |
| 011309 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596654.1 | 511907.2 | 3153 | 1.64041666667 | 11309 |
| 010117 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596654.9 | 511906.1 | 3155 | 1.64041666667 | 10117 |
| 010149 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596656.7 | 511905.1 | 3157 | 1.64041666667 | 10149 |
| 011357 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596656.1 | 511905.0 | 3159 | 1.64041666667 | 11357 |
| 010789 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:39pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596655.1 | 511905.7 | 3161 | 1.64041666667 | 10789 |
| 011757 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:40pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596653.7 | 511908.0 | 3163 | 1.64041666667 | 11757 |
| 011909 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:41pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596653.1 | 511909.2 | 3165 | 1.64041666667 | 11909 |
| 012097 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:42pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596655.3 | 511910.3 | 3167 | 1.64041666667 | 12097 |
| 009354 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:43pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596657.8 | 511911.5 | 3169 | 1.64041666667 | 9354 |
| 010558 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:44pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596660.3 | 511912.3 | 3171 | 1.64041666667 | 10558 |
| 011399 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:45pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596663.0 | 511913.0 | 3173 | 1.64041666667 | 11399 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 011400 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:46pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596665.8 | 511913.4 | 3175 | 1.64041666667 | 11400 |
| 011160 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:47pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596669.0 | 511913.9 | 3177 | 1.64041666667 | 11160 |
| 011670 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:48pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596671.7 | 511914.9 | 3179 | 1.64041666667 | 11670 |
| 010267 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:49pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596674.9 | 511915.4 | 3181 | 1.64041666667 | 10267 |
| 009856 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:50pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596676.9 | 511916.4 | 3183 | 1.64041666667 | 9856 |
| 010474 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:51pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596679.6 | 511917.2 | 3185 | 1.64041666667 | 10474 |
| 011828 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:52pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596681.8 | 511918.5 | 3187 | 1.64041666667 | 11828 |
| 009857 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:53pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596684.7 | 511919.4 | 3189 | 1.64041666667 | 9857 |
| 009334 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:54pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596687.1 | 511920.4 | 3191 | 1.64041666667 | 9334 |
| 010343 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:55pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596689.9 | 511921.4 | 3193 | 1.64041666667 | 10343 |
| 011436 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:56pm | Sensor | 1797-S0002-G-TJV.cor | 6852.2 | 1596692.6 | 511922.3 | 3195 | 1.64041666667 | 11436 |
| 012819 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:57pm | Sensor | 1797-S0002-G-TJV.cor | 6852.1 | 1596695.6 | 511923.6 | 3197 | 1.64041666667 | 12819 |
| 011424 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:58pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596697.9 | 511923.9 | 3199 | 1.64041666667 | 11424 |
| 012666 | 0 | GeoXH 6000 | 08/20/2015 | 12:05:59pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596700.7 | 511924.7 | 3201 | 1.64041666667 | 12666 |
| 011926 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:00pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596703.2 | 511925.0 | 3203 | 1.64041666667 | 11926 |
| 010271 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:01pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596705.8 | 511925.6 | 3205 | 1.64041666667 | 10271 |
| 010278 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:02pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596708.4 | 511925.6 | 3207 | 1.64041666667 | 10278 |
| 011449 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:03pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596711.0 | 511926.6 | 3209 | 1.64041666667 | 11449 |
| 012042 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:04pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596713.3 | 511927.1 | 3211 | 1.64041666667 | 12042 |
| 010960 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:05pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596716.2 | 511927.3 | 3213 | 1.64041666667 | 10960 |
| 011440 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:06pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596718.7 | 511927.7 | 3215 | 1.64041666667 | 11440 |
| 011800 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:07pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596721.4 | 511928.0 | 3217 | 1.64041666667 | 11800 |
| 010930 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:08pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596723.5 | 511928.8 | 3219 | 1.64041666667 | 10930 |
| 009992 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596725.3 | 511929.7 | 3221 | 1.64041666667 | 9992 |
| 009668 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596727.4 | 511930.6 | 3223 | 1.64041666667 | 9668 |
| 011207 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:11pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596730.2 | 511931.5 | 3225 | 1.64041666667 | 11207 |
| 010601 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596732.0 | 511932.3 | 3227 | 1.64041666667 | 10601 |
| 011290 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596734.5 | 511932.6 | 3229 | 1.64041666667 | 11290 |
| 012212 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596736.8 | 511933.5 | 3231 | 1.64041666667 | 12212 |
| 011543 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596739.7 | 511934.2 | 3233 | 1.64041666667 | 11543 |
| 010655 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596741.1 | 511935.2 | 3235 | 1.64041666667 | 10655 |
| 011874 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:17pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596743.6 | 511936.3 | 3237 | 1.64041666667 | 11874 |
| 011458 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596745.3 | 511938.2 | 3239 | 1.64041666667 | 11458 |
| 011234 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596747.5 | 511939.2 | 3241 | 1.64041666667 | 11234 |
| 011118 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596748.2 | 511940.7 | 3243 | 1.64041666667 | 11118 |
| 009589 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:21pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596748.3 | 511941.2 | 3245 | 1.64041666667 | 9589 |
| 011607 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596748.0 | 511940.5 | 3247 | 1.64041666667 | 11607 |
| 010462 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596747.8 | 511939.3 | 3249 | 1.64041666667 | 10462 |
| 010025 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596749.5 | 511938.4 | 3251 | 1.64041666667 | 10025 |
| 011596 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596751.6 | 511936.5 | 3253 | 1.64041666667 | 11596 |
| 011539 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596752.1 | 511935.8 | 3255 | 1.64041666667 | 11539 |
| 010654 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596752.2 | 511935.6 | 3257 | 1.64041666667 | 10654 |
| 009293 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596752.6 | 511935.3 | 3259 | 1.64041666667 | 9293 |
| 011683 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:29pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596754.7 | 511934.6 | 3261 | 1.64041666667 | 11683 |
| 011651 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596756.1 | 511932.1 | 3263 | 1.64041666667 | 11651 |
| 011342 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:31pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596757.3 | 511930.5 | 3265 | 1.64041666667 | 11342 |
| 012135 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596757.7 | 511928.3 | 3267 | 1.64041666667 | 12135 |
| 012093 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:33pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596757.0 | 511929.6 | 3269 | 1.64041666667 | 12093 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 010943 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:34pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596757.0 | 511930.3 | 3271 | 1.64041666667 | 10943 |
| 011796 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596756.7 | 511931.9 | 3273 | 1.64041666667 | 11796 |
| 012459 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596755.4 | 511933.1 | 3275 | 1.64041666667 | 12459 |
| 010584 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596753.7 | 511933.8 | 3277 | 1.64041666667 | 10584 |
| 010776 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596751.2 | 511934.8 | 3279 | 1.64041666667 | 10776 |
| 009774 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596749.9 | 511934.0 | 3281 | 1.64041666667 | 9774 |
| 010393 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596748.7 | 511933.1 | 3283 | 1.64041666667 | 10393 |
| 010308 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:41pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596747.3 | 511931.6 | 3285 | 1.64041666667 | 10308 |
| 010407 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:42pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596745.0 | 511931.6 | 3287 | 1.64041666667 | 10407 |
| 010431 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:43pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596742.0 | 511931.4 | 3289 | 1.64041666667 | 10431 |
| 010918 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596740.7 | 511931.8 | 3291 | 1.64041666667 | 10918 |
| 011339 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596738.6 | 511930.7 | 3293 | 1.64041666667 | 11339 |
| 012135 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596736.2 | 511929.8 | 3295 | 1.64041666667 | 12135 |
| 011883 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596733.9 | 511927.7 | 3297 | 1.64041666667 | 11883 |
| 011160 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596731.5 | 511927.0 | 3299 | 1.64041666667 | 11160 |
| 010680 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:49pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596729.2 | 511925.2 | 3301 | 1.64041666667 | 10680 |
| 011250 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:50pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596726.7 | 511924.6 | 3303 | 1.64041666667 | 11250 |
| 010342 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:51pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596724.2 | 511923.5 | 3305 | 1.64041666667 | 10342 |
| 010415 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:52pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596721.7 | 511922.9 | 3307 | 1.64041666667 | 10415 |
| 011604 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:53pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596719.0 | 511922.1 | 3309 | 1.64041666667 | 11604 |
| 012501 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:54pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596716.7 | 511921.3 | 3311 | 1.64041666667 | 12501 |
| 011435 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:55pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596713.9 | 511920.8 | 3313 | 1.64041666667 | 11435 |
| 011588 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:56pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596711.8 | 511920.2 | 3315 | 1.64041666667 | 11588 |
| 010637 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:57pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596708.7 | 511919.5 | 3317 | 1.64041666667 | 10637 |
| 012409 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:58pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596706.5 | 511918.5 | 3319 | 1.64041666667 | 12409 |
| 012312 | 0 | GeoXH 6000 | 08/20/2015 | 12:06:59pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596703.6 | 511918.8 | 3321 | 1.64041666667 | 12312 |
| 011988 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:00pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596701.4 | 511918.3 | 3323 | 1.64041666667 | 11988 |
| 012297 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:01pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596698.5 | 511918.6 | 3325 | 1.64041666667 | 12297 |
| 012404 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:02pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596696.1 | 511918.1 | 3327 | 1.64041666667 | 12404 |
| 011471 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:03pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596693.5 | 511917.5 | 3329 | 1.64041666667 | 11471 |
| 012647 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:04pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596691.5 | 511917.1 | 3331 | 1.64041666667 | 12647 |
| 010751 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:05pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596688.8 | 511916.8 | 3333 | 1.64041666667 | 10751 |
| 011058 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:06pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596686.1 | 511916.4 | 3335 | 1.64041666667 | 11058 |
| 011374 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:07pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596683.6 | 511915.2 | 3337 | 1.64041666667 | 11374 |
| 010883 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:08pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596681.1 | 511914.4 | 3339 | 1.64041666667 | 10883 |
| 013011 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:09pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596678.5 | 511912.7 | 3341 | 1.64041666667 | 13011 |
| 010722 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:10pm | Sensor | 1797-S0002-G-TJV.cor | 6852.4 | 1596676.1 | 511911.5 | 3343 | 1.64041666667 | 10722 |
| 011650 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:11pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596673.1 | 511910.4 | 3345 | 1.64041666667 | 11650 |
| 010772 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:12pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596670.7 | 511909.4 | 3347 | 1.64041666667 | 10772 |
| 012173 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:13pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596667.6 | 511909.0 | 3349 | 1.64041666667 | 12173 |
| 009673 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:14pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596665.7 | 511908.1 | 3351 | 1.64041666667 | 9673 |
| 009498 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:15pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596663.5 | 511907.9 | 3353 | 1.64041666667 | 9498 |
| 010474 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:16pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596662.4 | 511906.7 | 3355 | 1.64041666667 | 10474 |
| 010688 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:17pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596660.9 | 511905.9 | 3357 | 1.64041666667 | 10688 |
| 011072 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:18pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596660.7 | 511905.7 | 3359 | 1.64041666667 | 11072 |
| 010178 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:19pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596660.8 | 511905.7 | 3361 | 1.64041666667 | 10178 |
| 010884 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:20pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596660.5 | 511905.8 | 3363 | 1.64041666667 | 10884 |
| 010761 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:21pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596661.7 | 511904.0 | 3365 | 1.64041666667 | 10761 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 010520 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:22pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596663.3 | 511901.1 | 3367 | 1.64041666667 | 10520 |
| 011060 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:23pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596665.1 | 511899.5 | 3369 | 1.64041666667 | 11060 |
| 013085 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:24pm | Sensor | 1797-S0002-G-TJV.cor | 6852.3 | 1596666.0 | 511899.0 | 3371 | 1.64041666667 | 13085 |
| 012301 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596664.5 | 511899.9 | 3373 | 1.64041666667 | 12301 |
| 011595 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:26pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596664.3 | 511901.1 | 3375 | 1.64041666667 | 11595 |
| 010788 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:27pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596664.0 | 511903.5 | 3377 | 1.64041666667 | 10788 |
| 010497 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:28pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596663.1 | 511905.1 | 3379 | 1.64041666667 | 10497 |
| 009674 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:29pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596661.9 | 511904.5 | 3381 | 1.64041666667 | 9674 |
| 011118 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:30pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596659.8 | 511904.3 | 3383 | 1.64041666667 | 11118 |
| 011629 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596658.9 | 511903.8 | 3385 | 1.64041666667 | 11629 |
| 012897 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:32pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596658.3 | 511903.1 | 3387 | 1.64041666667 | 12897 |
| 011504 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:33pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596656.5 | 511902.5 | 3389 | 1.64041666667 | 11504 |
| 010046 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:34pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596655.5 | 511902.1 | 3391 | 1.64041666667 | 10046 |
| 011721 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596653.8 | 511902.2 | 3393 | 1.64041666667 | 11721 |
| 011720 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596653.2 | 511900.8 | 3395 | 1.64041666667 | 11720 |
| 011870 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596651.1 | 511900.4 | 3397 | 1.64041666667 | 11870 |
| 012807 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596649.6 | 511898.9 | 3399 | 1.64041666667 | 12807 |
| 014422 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596647.5 | 511897.9 | 3401 | 1.64041666667 | 14422 |
| 013745 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596645.8 | 511896.8 | 3403 | 1.64041666667 | 13745 |
| 012766 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:41pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596643.0 | 511896.7 | 3405 | 1.64041666667 | 12766 |
| 013661 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:42pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596641.5 | 511895.7 | 3407 | 1.64041666667 | 13661 |
| 013585 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:43pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596639.1 | 511895.1 | 3409 | 1.64041666667 | 13585 |
| 014766 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596637.4 | 511893.9 | 3411 | 1.64041666667 | 14766 |
| 016531 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596634.7 | 511893.2 | 3413 | 1.64041666667 | 16531 |
| 016065 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596632.6 | 511892.3 | 3415 | 1.64041666667 | 16065 |
| 018718 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596630.7 | 511891.0 | 3417 | 1.64041666667 | 18718 |
| 019169 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596629.0 | 511890.4 | 3419 | 1.64041666667 | 19169 |
| 019702 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596628.4 | 511890.4 | 3421 | 1.64041666667 | 19702 |
| 018335 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596628.6 | 511889.9 | 3423 | 1.64041666667 | 18335 |
| 017513 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:51pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596626.8 | 511888.9 | 3425 | 1.64041666667 | 17513 |
| 015838 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:52pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596625.1 | 511887.4 | 3427 | 1.64041666667 | 15838 |
| 016529 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596622.9 | 511885.8 | 3429 | 1.64041666667 | 16529 |
| 015082 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596621.0 | 511883.8 | 3431 | 1.64041666667 | 15082 |
| 016490 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596618.6 | 511882.2 | 3433 | 1.64041666667 | 16490 |
| 015282 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596617.2 | 511880.6 | 3435 | 1.64041666667 | 15282 |
| 015820 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:57pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596616.5 | 511879.3 | 3437 | 1.64041666667 | 15820 |
| 016015 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596618.0 | 511879.4 | 3439 | 1.64041666667 | 16015 |
| 015493 | 0 | GeoXH 6000 | 08/20/2015 | 12:07:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596619.8 | 511881.6 | 3441 | 1.64041666667 | 15493 |
| 016323 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596621.5 | 511883.9 | 3443 | 1.64041666667 | 16323 |
| 015690 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596623.8 | 511886.1 | 3445 | 1.64041666667 | 15690 |
| 016192 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596625.1 | 511888.0 | 3447 | 1.64041666667 | 16192 |
| 018388 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:03pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596627.1 | 511889.4 | 3449 | 1.64041666667 | 18388 |
| 019447 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596628.4 | 511890.0 | 3451 | 1.64041666667 | 19447 |
| 018601 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596629.3 | 511890.0 | 3453 | 1.64041666667 | 18601 |
| 018420 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596629.8 | 511890.1 | 3455 | 1.64041666667 | 18420 |
| 018045 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596630.2 | 511889.8 | 3457 | 1.64041666667 | 18045 |
| 018281 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596631.9 | 511887.7 | 3459 | 1.64041666667 | 18281 |
| 015580 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596634.0 | 511886.3 | 3461 | 1.64041666667 | 15580 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014485 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596634.8 | 511885.9 | 3463 | 1.64041666667 | 14485 |
| 014301 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:11pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596634.6 | 511886.0 | 3465 | 1.64041666667 | 14301 |
| 014885 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596635.8 | 511884.2 | 3467 | 1.64041666667 | 14885 |
| 013441 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596637.8 | 511882.7 | 3469 | 1.64041666667 | 13441 |
| 014460 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596638.3 | 511882.0 | 3471 | 1.64041666667 | 14460 |
| 012345 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596638.5 | 511882.0 | 3473 | 1.64041666667 | 12345 |
| 013406 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596638.4 | 511881.9 | 3475 | 1.64041666667 | 13406 |
| 013701 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:17pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596637.8 | 511881.4 | 3477 | 1.64041666667 | 13701 |
| 013325 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596636.9 | 511881.6 | 3479 | 1.64041666667 | 13325 |
| 013171 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596636.0 | 511883.5 | 3481 | 1.64041666667 | 13171 |
| 014962 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596635.1 | 511885.3 | 3483 | 1.64041666667 | 14962 |
| 017420 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:21pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596634.5 | 511885.8 | 3485 | 1.64041666667 | 17420 |
| 016475 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596634.2 | 511886.0 | 3487 | 1.64041666667 | 16475 |
| 014978 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596635.5 | 511886.2 | 3489 | 1.64041666667 | 14978 |
| 014634 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596636.8 | 511887.5 | 3491 | 1.64041666667 | 14634 |
| 014398 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596639.6 | 511888.3 | 3493 | 1.64041666667 | 14398 |
| 013499 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596641.6 | 511889.2 | 3495 | 1.64041666667 | 13499 |
| 011865 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596644.4 | 511889.8 | 3497 | 1.64041666667 | 11865 |
| 012296 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596646.7 | 511890.8 | 3499 | 1.64041666667 | 12296 |
| 011924 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:29pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596649.8 | 511892.4 | 3501 | 1.64041666667 | 11924 |
| 011351 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596652.2 | 511893.4 | 3503 | 1.64041666667 | 11351 |
| 011657 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:31pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596655.0 | 511894.8 | 3505 | 1.64041666667 | 11657 |
| 013294 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596657.4 | 511895.0 | 3507 | 1.64041666667 | 13294 |
| 012623 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:33pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596659.6 | 511895.8 | 3509 | 1.64041666667 | 12623 |
| 012216 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:34pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596661.7 | 511896.5 | 3511 | 1.64041666667 | 12216 |
| 010944 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596663.7 | 511898.3 | 3513 | 1.64041666667 | 10944 |
| 011736 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596664.5 | 511898.8 | 3515 | 1.64041666667 | 11736 |
| 011754 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596664.1 | 511897.3 | 3517 | 1.64041666667 | 11754 |
| 012478 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596665.3 | 511896.1 | 3519 | 1.64041666667 | 12478 |
| 012479 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596667.9 | 511894.6 | 3521 | 1.64041666667 | 12479 |
| 013080 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596667.1 | 511893.9 | 3523 | 1.64041666667 | 13080 |
| 013470 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:41pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596666.5 | 511895.6 | 3525 | 1.64041666667 | 13470 |
| 013357 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:42pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596665.0 | 511897.7 | 3527 | 1.64041666667 | 13357 |
| 011889 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:43pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596666.0 | 511899.2 | 3529 | 1.64041666667 | 11889 |
| 011552 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596667.6 | 511900.9 | 3531 | 1.64041666667 | 11552 |
| 010688 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596670.3 | 511902.1 | 3533 | 1.64041666667 | 10688 |
| 010592 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:46pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596672.8 | 511903.2 | 3535 | 1.64041666667 | 10592 |
| 010538 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:47pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596675.7 | 511904.4 | 3537 | 1.64041666667 | 10538 |
| 011994 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:48pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596678.8 | 511905.0 | 3539 | 1.64041666667 | 11994 |
| 011188 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:49pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596681.8 | 511906.1 | 3541 | 1.64041666667 | 11188 |
| 010627 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:50pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596684.4 | 511906.1 | 3543 | 1.64041666667 | 10627 |
| 010966 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:51pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596687.1 | 511906.6 | 3545 | 1.64041666667 | 10966 |
| 011321 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:52pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596689.5 | 511906.2 | 3547 | 1.64041666667 | 11321 |
| 010300 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:53pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596692.2 | 511906.7 | 3549 | 1.64041666667 | 10300 |
| 011575 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:54pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596694.9 | 511906.8 | 3551 | 1.64041666667 | 11575 |
| 012013 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596697.3 | 511907.7 | 3553 | 1.64041666667 | 12013 |
| 010743 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596699.4 | 511908.7 | 3555 | 1.64041666667 | 10743 |
| 011685 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:57pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596702.0 | 511909.6 | 3557 | 1.64041666667 | 11685 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012701 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596704.3 | 511911.0 | 3559 | 1.64041666667 | 12701 |
| 012865 | 0 | GeoXH 6000 | 08/20/2015 | 12:08:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596707.3 | 511911.8 | 3561 | 1.64041666667 | 12865 |
| 011376 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596709.4 | 511912.9 | 3563 | 1.64041666667 | 11376 |
| 011154 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596712.0 | 511913.0 | 3565 | 1.64041666667 | 11154 |
| 011758 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596714.0 | 511913.7 | 3567 | 1.64041666667 | 11758 |
| 011309 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:03pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596716.6 | 511914.1 | 3569 | 1.64041666667 | 11309 |
| 011917 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596718.6 | 511915.0 | 3571 | 1.64041666667 | 11917 |
| 011259 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596721.4 | 511915.9 | 3573 | 1.64041666667 | 11259 |
| 011394 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596722.9 | 511917.4 | 3575 | 1.64041666667 | 11394 |
| 009748 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596725.2 | 511918.8 | 3577 | 1.64041666667 | 9748 |
| 011137 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596727.2 | 511920.3 | 3579 | 1.64041666667 | 11137 |
| 010584 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596729.6 | 511921.3 | 3581 | 1.64041666667 | 10584 |
| 012186 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596732.1 | 511921.8 | 3583 | 1.64041666667 | 12186 |
| 011146 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:11pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596734.6 | 511922.0 | 3585 | 1.64041666667 | 11146 |
| 011786 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.5 | 511921.9 | 3587 | 1.64041666667 | 11786 |
| 011406 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596740.2 | 511922.4 | 3589 | 1.64041666667 | 11406 |
| 010921 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596742.2 | 511922.3 | 3591 | 1.64041666667 | 10921 |
| 010800 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596744.5 | 511922.7 | 3593 | 1.64041666667 | 10800 |
| 011490 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:16pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596746.4 | 511922.8 | 3595 | 1.64041666667 | 11490 |
| 012682 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:17pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596748.0 | 511923.9 | 3597 | 1.64041666667 | 12682 |
| 011960 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:18pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596749.9 | 511924.5 | 3599 | 1.64041666667 | 11960 |
| 011690 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:19pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596752.2 | 511926.1 | 3601 | 1.64041666667 | 11690 |
| 010332 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:20pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596754.4 | 511926.5 | 3603 | 1.64041666667 | 10332 |
| 011013 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596756.5 | 511927.0 | 3605 | 1.64041666667 | 11013 |
| 012466 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596756.3 | 511926.9 | 3607 | 1.64041666667 | 12466 |
| 012028 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596756.7 | 511925.8 | 3609 | 1.64041666667 | 12028 |
| 011617 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:24pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596757.5 | 511923.6 | 3611 | 1.64041666667 | 11617 |
| 011004 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:25pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596758.1 | 511921.4 | 3613 | 1.64041666667 | 11004 |
| 010341 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:26pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596758.0 | 511920.8 | 3615 | 1.64041666667 | 10341 |
| 010325 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:27pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596758.4 | 511920.6 | 3617 | 1.64041666667 | 10325 |
| 010711 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596759.7 | 511918.6 | 3619 | 1.64041666667 | 10711 |
| 012037 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596761.1 | 511916.2 | 3621 | 1.64041666667 | 12037 |
| 011319 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:30pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596761.7 | 511915.4 | 3623 | 1.64041666667 | 11319 |
| 011410 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:31pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596762.0 | 511915.2 | 3625 | 1.64041666667 | 11410 |
| 014222 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:32pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596762.3 | 511914.9 | 3627 | 1.64041666667 | 14222 |
| 011685 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:33pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596762.7 | 511914.7 | 3629 | 1.64041666667 | 11685 |
| 011711 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:34pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596762.1 | 511915.0 | 3631 | 1.64041666667 | 11711 |
| 011928 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:35pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596761.6 | 511914.9 | 3633 | 1.64041666667 | 11928 |
| 010812 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:36pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596761.3 | 511916.1 | 3635 | 1.64041666667 | 10812 |
| 010743 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:37pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596760.2 | 511917.9 | 3637 | 1.64041666667 | 10743 |
| 009915 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:38pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596759.1 | 511919.6 | 3639 | 1.64041666667 | 9915 |
| 009918 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:39pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596758.3 | 511920.5 | 3641 | 1.64041666667 | 9918 |
| 008839 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:40pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596757.3 | 511920.1 | 3643 | 1.64041666667 | 8839 |
| 010010 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:41pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596755.0 | 511919.8 | 3645 | 1.64041666667 | 10010 |
| 011922 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:42pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596753.1 | 511919.1 | 3647 | 1.64041666667 | 11922 |
| 009820 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:43pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596750.7 | 511919.1 | 3649 | 1.64041666667 | 9820 |
| 011275 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:44pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596749.2 | 511918.2 | 3651 | 1.64041666667 | 11275 |
| 010798 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:45pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596746.8 | 511917.7 | 3653 | 1.64041666667 | 10798 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 011339 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596744.3 | 511916.9 | 3655 | 1.64041666667 | 11339 |
| 013215 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596741.6 | 511917.0 | 3657 | 1.64041666667 | 13215 |
| 012303 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596739.1 | 511916.8 | 3659 | 1.64041666667 | 12303 |
| 012945 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.6 | 511916.1 | 3661 | 1.64041666667 | 12945 |
| 012626 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596734.4 | 511914.9 | 3663 | 1.64041666667 | 12626 |
| 013086 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:51pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596731.7 | 511913.5 | 3665 | 1.64041666667 | 13086 |
| 011611 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:52pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596729.2 | 511913.5 | 3667 | 1.64041666667 | 11611 |
| 011812 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596726.5 | 511912.6 | 3669 | 1.64041666667 | 11812 |
| 010993 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596724.0 | 511912.0 | 3671 | 1.64041666667 | 10993 |
| 012198 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596721.7 | 511910.6 | 3673 | 1.64041666667 | 12198 |
| 012919 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596719.4 | 511910.0 | 3675 | 1.64041666667 | 12919 |
| 012739 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:57pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596716.9 | 511908.9 | 3677 | 1.64041666667 | 12739 |
| 011645 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596714.3 | 511907.9 | 3679 | 1.64041666667 | 11645 |
| 011581 | 0 | GeoXH 6000 | 08/20/2015 | 12:09:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596712.0 | 511907.0 | 3681 | 1.64041666667 | 11581 |
| 013635 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:00pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596709.6 | 511905.8 | 3683 | 1.64041666667 | 13635 |
| 011418 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:01pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596707.1 | 511905.3 | 3685 | 1.64041666667 | 11418 |
| 011254 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:02pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596704.8 | 511904.4 | 3687 | 1.64041666667 | 11254 |
| 013253 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:03pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596701.7 | 511904.0 | 3689 | 1.64041666667 | 13253 |
| 012733 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:04pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596699.5 | 511903.3 | 3691 | 1.64041666667 | 12733 |
| 011403 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:05pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596696.4 | 511903.4 | 3693 | 1.64041666667 | 11403 |
| 011610 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:06pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596694.6 | 511902.6 | 3695 | 1.64041666667 | 11610 |
| 011962 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:07pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596692.0 | 511902.1 | 3697 | 1.64041666667 | 11962 |
| 011510 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:08pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596689.8 | 511900.9 | 3699 | 1.64041666667 | 11510 |
| 011157 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:09pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596687.2 | 511900.2 | 3701 | 1.64041666667 | 11157 |
| 010289 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:10pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596685.3 | 511899.0 | 3703 | 1.64041666667 | 10289 |
| 011572 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:11pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596682.8 | 511898.0 | 3705 | 1.64041666667 | 11572 |
| 011023 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596680.6 | 511897.4 | 3707 | 1.64041666667 | 11023 |
| 012235 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596678.2 | 511897.1 | 3709 | 1.64041666667 | 12235 |
| 012059 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596676.2 | 511896.5 | 3711 | 1.64041666667 | 12059 |
| 012284 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596674.4 | 511895.5 | 3713 | 1.64041666667 | 12284 |
| 012821 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596673.0 | 511894.5 | 3715 | 1.64041666667 | 12821 |
| 013045 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:17pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596672.7 | 511894.1 | 3717 | 1.64041666667 | 13045 |
| 012951 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596672.7 | 511895.0 | 3719 | 1.64041666667 | 12951 |
| 012207 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596673.4 | 511894.6 | 3721 | 1.64041666667 | 12207 |
| 013942 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:20pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596673.4 | 511894.7 | 3723 | 1.64041666667 | 13942 |
| 013565 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596673.6 | 511894.7 | 3725 | 1.64041666667 | 13565 |
| 012991 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596673.9 | 511893.7 | 3727 | 1.64041666667 | 12991 |
| 012847 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596674.1 | 511892.1 | 3729 | 1.64041666667 | 12847 |
| 011222 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596675.0 | 511889.9 | 3731 | 1.64041666667 | 11222 |
| 012165 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596675.7 | 511888.4 | 3733 | 1.64041666667 | 12165 |
| 014081 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596675.6 | 511888.6 | 3735 | 1.64041666667 | 14081 |
| 012670 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:27pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596674.7 | 511890.3 | 3737 | 1.64041666667 | 12670 |
| 012617 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596674.3 | 511891.9 | 3739 | 1.64041666667 | 12617 |
| 012514 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596672.9 | 511893.5 | 3741 | 1.64041666667 | 12514 |
| 013748 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596670.3 | 511893.1 | 3743 | 1.64041666667 | 13748 |
| 013067 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596667.1 | 511893.6 | 3745 | 1.64041666667 | 13067 |
| 012356 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596665.4 | 511893.1 | 3747 | 1.64041666667 | 12356 |
| 012929 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:33pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596663.1 | 511893.1 | 3749 | 1.64041666667 | 12929 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012772 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:34pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596661.6 | 511891.8 | 3751 | 1.64041666667 | 12772 |
| 012163 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596659.3 | 511890.5 | 3753 | 1.64041666667 | 12163 |
| 012400 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596657.7 | 511889.3 | 3755 | 1.64041666667 | 12400 |
| 013900 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596655.9 | 511888.3 | 3757 | 1.64041666667 | 13900 |
| 012895 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596653.7 | 511887.9 | 3759 | 1.64041666667 | 12895 |
| 013423 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:39pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596651.5 | 511886.6 | 3761 | 1.64041666667 | 13423 |
| 013136 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:40pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596649.5 | 511886.0 | 3763 | 1.64041666667 | 13136 |
| 013484 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:41pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596647.5 | 511884.7 | 3765 | 1.64041666667 | 13484 |
| 012671 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:42pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596645.3 | 511884.1 | 3767 | 1.64041666667 | 12671 |
| 013277 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:43pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596643.8 | 511882.9 | 3769 | 1.64041666667 | 13277 |
| 013069 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:44pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596642.0 | 511881.9 | 3771 | 1.64041666667 | 13069 |
| 011277 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:45pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596640.6 | 511880.9 | 3773 | 1.64041666667 | 11277 |
| 012929 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:46pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596640.3 | 511881.1 | 3775 | 1.64041666667 | 12929 |
| 012652 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:47pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596640.5 | 511880.9 | 3777 | 1.64041666667 | 12652 |
| 013573 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:48pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596640.7 | 511880.9 | 3779 | 1.64041666667 | 13573 |
| 012093 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:49pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596640.7 | 511881.2 | 3781 | 1.64041666667 | 12093 |
| 012503 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:50pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596641.0 | 511880.7 | 3783 | 1.64041666667 | 12503 |
| 012605 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:51pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596641.5 | 511879.9 | 3785 | 1.64041666667 | 12605 |
| 012781 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:52pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596642.8 | 511878.4 | 3787 | 1.64041666667 | 12781 |
| 013125 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596644.4 | 511877.2 | 3789 | 1.64041666667 | 13125 |
| 014201 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:54pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596644.9 | 511877.0 | 3791 | 1.64041666667 | 14201 |
| 014710 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:55pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596644.3 | 511877.2 | 3793 | 1.64041666667 | 14710 |
| 013547 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:56pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596645.7 | 511876.1 | 3795 | 1.64041666667 | 13547 |
| 013376 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:57pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596646.9 | 511873.3 | 3797 | 1.64041666667 | 13376 |
| 012614 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:58pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596648.1 | 511872.5 | 3799 | 1.64041666667 | 12614 |
| 013893 | 0 | GeoXH 6000 | 08/20/2015 | 12:10:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596650.6 | 511871.3 | 3801 | 1.64041666667 | 13893 |
| 013043 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596651.4 | 511871.1 | 3803 | 1.64041666667 | 13043 |
| 013700 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596652.0 | 511870.9 | 3805 | 1.64041666667 | 13700 |
| 014105 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596651.3 | 511871.0 | 3807 | 1.64041666667 | 14105 |
| 016126 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:03pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596649.4 | 511870.4 | 3809 | 1.64041666667 | 16126 |
| 013991 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:04pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596648.8 | 511870.3 | 3811 | 1.64041666667 | 13991 |
| 012468 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:05pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596648.7 | 511871.4 | 3813 | 1.64041666667 | 12468 |
| 012117 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:06pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596647.4 | 511872.6 | 3815 | 1.64041666667 | 12117 |
| 013199 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:07pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596646.1 | 511874.7 | 3817 | 1.64041666667 | 13199 |
| 012600 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:08pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596645.2 | 511876.1 | 3819 | 1.64041666667 | 12600 |
| 012480 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:09pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596644.7 | 511876.5 | 3821 | 1.64041666667 | 12480 |
| 014280 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:10pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596644.7 | 511876.6 | 3823 | 1.64041666667 | 14280 |
| 013800 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:11pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596645.3 | 511876.4 | 3825 | 1.64041666667 | 13800 |
| 012540 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:12pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596646.4 | 511876.8 | 3827 | 1.64041666667 | 12540 |
| 012795 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:13pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596648.3 | 511877.7 | 3829 | 1.64041666667 | 12795 |
| 013038 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:14pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596650.4 | 511879.1 | 3831 | 1.64041666667 | 13038 |
| 012979 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:15pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596652.8 | 511879.9 | 3833 | 1.64041666667 | 12979 |
| 013504 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:16pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596654.6 | 511881.2 | 3835 | 1.64041666667 | 13504 |
| 013276 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:17pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596657.1 | 511882.3 | 3837 | 1.64041666667 | 13276 |
| 016999 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:18pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596659.4 | 511883.4 | 3839 | 1.64041666667 | 16999 |
| 014239 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:19pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596661.7 | 511883.7 | 3841 | 1.64041666667 | 14239 |
| 014060 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596663.9 | 511884.5 | 3843 | 1.64041666667 | 14060 |
| 013475 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596666.9 | 511884.8 | 3845 | 1.64041666667 | 13475 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013358 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596668.7 | 511885.6 | 3847 | 1.64041666667 | 13358 |
| 012609 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596671.3 | 511886.2 | 3849 | 1.64041666667 | 12609 |
| 013142 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596673.4 | 511887.4 | 3851 | 1.64041666667 | 13142 |
| 014415 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596674.4 | 511887.9 | 3853 | 1.64041666667 | 14415 |
| 013683 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596673.8 | 511887.2 | 3855 | 1.64041666667 | 13683 |
| 013771 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596673.6 | 511887.2 | 3857 | 1.64041666667 | 13771 |
| 014062 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596673.5 | 511887.1 | 3859 | 1.64041666667 | 14062 |
| 012965 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:29pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596673.6 | 511886.7 | 3861 | 1.64041666667 | 12965 |
| 013591 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596674.7 | 511886.9 | 3863 | 1.64041666667 | 13591 |
| 013057 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596677.3 | 511887.9 | 3865 | 1.64041666667 | 13057 |
| 012804 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596679.5 | 511888.9 | 3867 | 1.64041666667 | 12804 |
| 012651 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:33pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596682.1 | 511890.3 | 3869 | 1.64041666667 | 12651 |
| 013062 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:34pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596684.9 | 511891.2 | 3871 | 1.64041666667 | 13062 |
| 013975 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596687.9 | 511892.3 | 3873 | 1.64041666667 | 13975 |
| 014924 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:36pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596690.9 | 511893.2 | 3875 | 1.64041666667 | 14924 |
| 013241 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596693.8 | 511893.9 | 3877 | 1.64041666667 | 13241 |
| 012670 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596696.2 | 511895.1 | 3879 | 1.64041666667 | 12670 |
| 011327 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596699.4 | 511896.2 | 3881 | 1.64041666667 | 11327 |
| 012341 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596701.8 | 511897.2 | 3883 | 1.64041666667 | 12341 |
| 011545 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:41pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596704.6 | 511897.6 | 3885 | 1.64041666667 | 11545 |
| 011976 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:42pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596706.9 | 511898.0 | 3887 | 1.64041666667 | 11976 |
| 011304 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:43pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596710.0 | 511898.3 | 3889 | 1.64041666667 | 11304 |
| 011796 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:44pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596712.8 | 511898.8 | 3891 | 1.64041666667 | 11796 |
| 011799 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:45pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596715.9 | 511899.8 | 3893 | 1.64041666667 | 11799 |
| 012339 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:46pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596718.3 | 511900.3 | 3895 | 1.64041666667 | 12339 |
| 010705 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596720.8 | 511901.6 | 3897 | 1.64041666667 | 10705 |
| 012306 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596723.1 | 511901.9 | 3899 | 1.64041666667 | 12306 |
| 011206 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596725.8 | 511902.4 | 3901 | 1.64041666667 | 11206 |
| 010241 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596728.2 | 511901.9 | 3903 | 1.64041666667 | 10241 |
| 011350 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:51pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596730.5 | 511902.0 | 3905 | 1.64041666667 | 11350 |
| 011327 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:52pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596732.8 | 511901.8 | 3907 | 1.64041666667 | 11327 |
| 011441 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596735.4 | 511902.3 | 3909 | 1.64041666667 | 11441 |
| 012040 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596737.8 | 511903.1 | 3911 | 1.64041666667 | 12040 |
| 011200 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596740.3 | 511903.8 | 3913 | 1.64041666667 | 11200 |
| 011380 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596742.2 | 511905.5 | 3915 | 1.64041666667 | 11380 |
| 011485 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:57pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596744.5 | 511906.4 | 3917 | 1.64041666667 | 11485 |
| 010791 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596746.4 | 511907.4 | 3919 | 1.64041666667 | 10791 |
| 011817 | 0 | GeoXH 6000 | 08/20/2015 | 12:11:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596748.7 | 511908.3 | 3921 | 1.64041666667 | 11817 |
| 011054 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:00pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596750.2 | 511909.1 | 3923 | 1.64041666667 | 11054 |
| 011403 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:01pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596752.3 | 511908.9 | 3925 | 1.64041666667 | 11403 |
| 011160 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:02pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596754.1 | 511909.7 | 3927 | 1.64041666667 | 11160 |
| 011190 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:03pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596756.2 | 511910.6 | 3929 | 1.64041666667 | 11190 |
| 011797 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:04pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596757.6 | 511912.1 | 3931 | 1.64041666667 | 11797 |
| 012219 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:05pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596759.6 | 511912.6 | 3933 | 1.64041666667 | 12219 |
| 011935 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:06pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596761.2 | 511913.2 | 3935 | 1.64041666667 | 11935 |
| 012253 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:07pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596761.9 | 511913.2 | 3937 | 1.64041666667 | 12253 |
| 012423 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:08pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596761.9 | 511913.2 | 3939 | 1.64041666667 | 12423 |
| 012135 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:09pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596761.8 | 511913.2 | 3941 | 1.64041666667 | 12135 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012753 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:10pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596761.8 | 511913.2 | 3943 | 1.64041666667 | 12753 |
| 013538 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:11pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596761.8 | 511913.4 | 3945 | 1.64041666667 | 13538 |
| 013044 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:12pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596763.4 | 511913.9 | 3947 | 1.64041666667 | 13044 |
| 013071 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:13pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596764.0 | 511913.9 | 3949 | 1.64041666667 | 13071 |
| 012387 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:14pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596762.6 | 511913.6 | 3951 | 1.64041666667 | 12387 |
| 012577 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:15pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596762.4 | 511913.4 | 3953 | 1.64041666667 | 12577 |
| 013404 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:16pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596764.0 | 511912.5 | 3955 | 1.64041666667 | 13404 |
| 011661 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:17pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596766.0 | 511910.1 | 3957 | 1.64041666667 | 11661 |
| 012725 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:18pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596766.8 | 511908.9 | 3959 | 1.64041666667 | 12725 |
| 010501 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:19pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596767.0 | 511908.2 | 3961 | 1.64041666667 | 10501 |
| 011085 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:20pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596767.9 | 511906.9 | 3963 | 1.64041666667 | 11085 |
| 011321 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596768.7 | 511904.5 | 3965 | 1.64041666667 | 11321 |
| 012160 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596769.5 | 511903.6 | 3967 | 1.64041666667 | 12160 |
| 011740 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596769.9 | 511903.6 | 3969 | 1.64041666667 | 11740 |
| 011905 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:24pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596770.3 | 511902.3 | 3971 | 1.64041666667 | 11905 |
| 011766 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:25pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596770.7 | 511901.3 | 3973 | 1.64041666667 | 11766 |
| 011011 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596770.9 | 511900.9 | 3975 | 1.64041666667 | 11011 |
| 011542 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596771.2 | 511900.8 | 3977 | 1.64041666667 | 11542 |
| 010715 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596770.7 | 511901.5 | 3979 | 1.64041666667 | 10715 |
| 011439 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596769.4 | 511902.4 | 3981 | 1.64041666667 | 11439 |
| 011019 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:30pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596769.3 | 511904.0 | 3983 | 1.64041666667 | 11019 |
| 012355 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:31pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596768.5 | 511905.9 | 3985 | 1.64041666667 | 12355 |
| 011998 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:32pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596767.1 | 511907.0 | 3987 | 1.64041666667 | 11998 |
| 012239 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:33pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596764.5 | 511907.6 | 3989 | 1.64041666667 | 12239 |
| 012210 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:34pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596761.9 | 511907.1 | 3991 | 1.64041666667 | 12210 |
| 011092 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:35pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596759.0 | 511906.6 | 3993 | 1.64041666667 | 11092 |
| 011173 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:36pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596757.1 | 511906.4 | 3995 | 1.64041666667 | 11173 |
| 010113 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:37pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596755.0 | 511905.7 | 3997 | 1.64041666667 | 10113 |
| 010178 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:38pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596753.2 | 511904.6 | 3999 | 1.64041666667 | 10178 |
| 012084 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:39pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596751.3 | 511902.8 | 4001 | 1.64041666667 | 12084 |
| 011661 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596749.3 | 511901.7 | 4003 | 1.64041666667 | 11661 |
| 010865 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:41pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596746.5 | 511900.5 | 4005 | 1.64041666667 | 10865 |
| 011296 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:42pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596743.7 | 511900.7 | 4007 | 1.64041666667 | 11296 |
| 010954 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:43pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596741.3 | 511900.0 | 4009 | 1.64041666667 | 10954 |
| 010598 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596739.1 | 511899.5 | 4011 | 1.64041666667 | 10598 |
| 009189 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596736.8 | 511898.3 | 4013 | 1.64041666667 | 9189 |
| 009917 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596734.7 | 511897.4 | 4015 | 1.64041666667 | 9917 |
| 010099 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596732.5 | 511896.1 | 4017 | 1.64041666667 | 10099 |
| 010834 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596730.0 | 511895.0 | 4019 | 1.64041666667 | 10834 |
| 012368 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596727.4 | 511893.7 | 4021 | 1.64041666667 | 12368 |
| 011282 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:50pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596724.8 | 511892.5 | 4023 | 1.64041666667 | 11282 |
| 010350 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:51pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596721.6 | 511891.9 | 4025 | 1.64041666667 | 10350 |
| 013837 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:52pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596719.3 | 511891.3 | 4027 | 1.64041666667 | 13837 |
| 012729 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:53pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596716.7 | 511890.9 | 4029 | 1.64041666667 | 12729 |
| 013682 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:54pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596714.6 | 511890.1 | 4031 | 1.64041666667 | 13682 |
| 015210 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:55pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596711.9 | 511889.8 | 4033 | 1.64041666667 | 15210 |
| 013492 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:56pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596709.9 | 511889.2 | 4035 | 1.64041666667 | 13492 |
| 014293 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:57pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596707.2 | 511888.5 | 4037 | 1.64041666667 | 14293 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013533 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596705.2 | 511887.8 | 4039 | 1.64041666667 | 13533 |
| 015293 | 0 | GeoXH 6000 | 08/20/2015 | 12:12:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596702.8 | 511886.8 | 4041 | 1.64041666667 | 15293 |
| 014563 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596700.3 | 511886.0 | 4043 | 1.64041666667 | 14563 |
| 013511 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596698.2 | 511884.8 | 4045 | 1.64041666667 | 13511 |
| 012527 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596696.0 | 511884.2 | 4047 | 1.64041666667 | 12527 |
| 013151 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:03pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596693.7 | 511883.1 | 4049 | 1.64041666667 | 13151 |
| 017118 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:04pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596691.5 | 511882.3 | 4051 | 1.64041666667 | 17118 |
| 017869 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:05pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596689.0 | 511881.4 | 4053 | 1.64041666667 | 17869 |
| 019437 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:06pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596686.5 | 511880.7 | 4055 | 1.64041666667 | 19437 |
| 017519 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596683.8 | 511880.4 | 4057 | 1.64041666667 | 17519 |
| 016500 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596681.1 | 511879.7 | 4059 | 1.64041666667 | 16500 |
| 016395 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596678.0 | 511879.5 | 4061 | 1.64041666667 | 16395 |
| 017178 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596675.8 | 511878.5 | 4063 | 1.64041666667 | 17178 |
| 016024 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:11pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596673.3 | 511877.6 | 4065 | 1.64041666667 | 16024 |
| 014206 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596671.2 | 511876.5 | 4067 | 1.64041666667 | 14206 |
| 013991 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596668.5 | 511876.1 | 4069 | 1.64041666667 | 13991 |
| 014748 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596666.2 | 511875.9 | 4071 | 1.64041666667 | 14748 |
| 014427 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596663.1 | 511875.1 | 4073 | 1.64041666667 | 14427 |
| 017226 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596660.8 | 511874.5 | 4075 | 1.64041666667 | 17226 |
| 016246 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:17pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596658.2 | 511873.3 | 4077 | 1.64041666667 | 16246 |
| 016511 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596656.0 | 511872.8 | 4079 | 1.64041666667 | 16511 |
| 015708 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596654.0 | 511871.6 | 4081 | 1.64041666667 | 15708 |
| 014517 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596651.9 | 511870.5 | 4083 | 1.64041666667 | 14517 |
| 015359 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:21pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596651.4 | 511870.4 | 4085 | 1.64041666667 | 15359 |
| 015690 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596652.7 | 511869.2 | 4087 | 1.64041666667 | 15690 |
| 014122 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596654.1 | 511866.5 | 4089 | 1.64041666667 | 14122 |
| 014720 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596655.1 | 511866.1 | 4091 | 1.64041666667 | 14720 |
| 016490 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596655.9 | 511866.0 | 4093 | 1.64041666667 | 16490 |
| 016662 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596655.8 | 511866.1 | 4095 | 1.64041666667 | 16662 |
| 015865 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596655.9 | 511865.9 | 4097 | 1.64041666667 | 15865 |
| 015726 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596656.9 | 511864.0 | 4099 | 1.64041666667 | 15726 |
| 015961 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596659.2 | 511861.8 | 4101 | 1.64041666667 | 15961 |
| 015570 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596661.1 | 511860.1 | 4103 | 1.64041666667 | 15570 |
| 015202 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596662.4 | 511858.9 | 4105 | 1.64041666667 | 15202 |
| 016070 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:32pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596662.7 | 511858.7 | 4107 | 1.64041666667 | 16070 |
| 015207 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:33pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596662.9 | 511858.7 | 4109 | 1.64041666667 | 15207 |
| 016282 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:34pm | Sensor | 1797-S0002-G-TJV.cor | 6852.5 | 1596663.0 | 511858.7 | 4111 | 1.64041666667 | 16282 |
| 015950 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596661.8 | 511859.3 | 4113 | 1.64041666667 | 15950 |
| 015477 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:36pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596660.5 | 511859.8 | 4115 | 1.64041666667 | 15477 |
| 016019 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:37pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596660.5 | 511860.8 | 4117 | 1.64041666667 | 16019 |
| 018075 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:38pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596659.6 | 511861.7 | 4119 | 1.64041666667 | 18075 |
| 017658 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596657.8 | 511863.3 | 4121 | 1.64041666667 | 17658 |
| 016564 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596656.5 | 511863.7 | 4123 | 1.64041666667 | 16564 |
| 016171 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:41pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596656.0 | 511863.7 | 4125 | 1.64041666667 | 16171 |
| 018232 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:42pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596656.0 | 511863.9 | 4127 | 1.64041666667 | 18232 |
| 016768 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:43pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596656.0 | 511863.9 | 4129 | 1.64041666667 | 16768 |
| 016072 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596655.8 | 511864.1 | 4131 | 1.64041666667 | 16072 |
| 016888 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596655.8 | 511864.1 | 4133 | 1.64041666667 | 16888 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 016552 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596655.9 | 511864.1 | 4135 | 1.64041666667 | 16552 |
| 017038 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596656.1 | 511864.3 | 4137 | 1.64041666667 | 17038 |
| 016469 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596656.3 | 511865.0 | 4139 | 1.64041666667 | 16469 |
| 016837 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596658.0 | 511865.9 | 4141 | 1.64041666667 | 16837 |
| 014919 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596659.8 | 511867.2 | 4143 | 1.64041666667 | 14919 |
| 014919 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:51pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596662.3 | 511868.6 | 4145 | 1.64041666667 | 14919 |
| 015910 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:52pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596664.6 | 511870.0 | 4147 | 1.64041666667 | 15910 |
| 017057 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596667.3 | 511871.3 | 4149 | 1.64041666667 | 17057 |
| 017224 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596670.0 | 511872.0 | 4151 | 1.64041666667 | 17224 |
| 014986 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596673.1 | 511873.2 | 4153 | 1.64041666667 | 14986 |
| 015026 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596675.6 | 511873.7 | 4155 | 1.64041666667 | 15026 |
| 017226 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:57pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596678.4 | 511874.8 | 4157 | 1.64041666667 | 17226 |
| 018316 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596680.6 | 511874.9 | 4159 | 1.64041666667 | 18316 |
| 018319 | 0 | GeoXH 6000 | 08/20/2015 | 12:13:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596683.2 | 511875.6 | 4161 | 1.64041666667 | 18319 |
| 017179 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596685.4 | 511876.1 | 4163 | 1.64041666667 | 17179 |
| 019835 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596688.0 | 511877.2 | 4165 | 1.64041666667 | 19835 |
| 019238 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596690.0 | 511878.2 | 4167 | 1.64041666667 | 19238 |
| 016149 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:03pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596692.8 | 511879.3 | 4169 | 1.64041666667 | 16149 |
| 015797 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:04pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596695.2 | 511880.4 | 4171 | 1.64041666667 | 15797 |
| 014719 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:05pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596698.0 | 511880.9 | 4173 | 1.64041666667 | 14719 |
| 013849 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:06pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596700.4 | 511881.6 | 4175 | 1.64041666667 | 13849 |
| 013362 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596703.3 | 511882.2 | 4177 | 1.64041666667 | 13362 |
| 014230 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596705.7 | 511882.8 | 4179 | 1.64041666667 | 14230 |
| 014147 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596708.7 | 511883.9 | 4181 | 1.64041666667 | 14147 |
| 014066 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596711.4 | 511884.7 | 4183 | 1.64041666667 | 14066 |
| 014616 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:11pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596714.0 | 511886.1 | 4185 | 1.64041666667 | 14616 |
| 013554 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596716.6 | 511886.9 | 4187 | 1.64041666667 | 13554 |
| 012088 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596719.0 | 511887.6 | 4189 | 1.64041666667 | 12088 |
| 013822 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596721.5 | 511887.8 | 4191 | 1.64041666667 | 13822 |
| 013535 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:15pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596724.4 | 511888.4 | 4193 | 1.64041666667 | 13535 |
| 014063 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:16pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596727.1 | 511889.3 | 4195 | 1.64041666667 | 14063 |
| 013506 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:17pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596730.0 | 511890.2 | 4197 | 1.64041666667 | 13506 |
| 012076 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596732.5 | 511891.1 | 4199 | 1.64041666667 | 12076 |
| 011659 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596735.2 | 511891.6 | 4201 | 1.64041666667 | 11659 |
| 010114 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596737.3 | 511892.3 | 4203 | 1.64041666667 | 10114 |
| 010598 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:21pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596740.1 | 511892.8 | 4205 | 1.64041666667 | 10598 |
| 011949 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596742.3 | 511893.7 | 4207 | 1.64041666667 | 11949 |
| 011687 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596744.6 | 511894.0 | 4209 | 1.64041666667 | 11687 |
| 010691 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596746.8 | 511894.1 | 4211 | 1.64041666667 | 10691 |
| 012543 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596748.8 | 511894.3 | 4213 | 1.64041666667 | 12543 |
| 010875 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:26pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596750.6 | 511894.8 | 4215 | 1.64041666667 | 10875 |
| 012648 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:27pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596752.8 | 511895.5 | 4217 | 1.64041666667 | 12648 |
| 010632 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596755.2 | 511896.1 | 4219 | 1.64041666667 | 10632 |
| 010788 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596757.5 | 511897.1 | 4221 | 1.64041666667 | 10788 |
| 010227 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:30pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596759.6 | 511897.9 | 4223 | 1.64041666667 | 10227 |
| 010866 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:31pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596762.2 | 511899.5 | 4225 | 1.64041666667 | 10866 |
| 011176 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:32pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596764.4 | 511900.6 | 4227 | 1.64041666667 | 11176 |
| 011644 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:33pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596767.2 | 511901.5 | 4229 | 1.64041666667 | 11644 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 011821 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:34pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596769.3 | 511901.5 | 4231 | 1.64041666667 | 11821 |
| 012315 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:35pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596769.7 | 511902.2 | 4233 | 1.64041666667 | 12315 |
| 010878 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:36pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596769.6 | 511902.7 | 4235 | 1.64041666667 | 10878 |
| 010519 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:37pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596769.8 | 511900.5 | 4237 | 1.64041666667 | 10519 |
| 011150 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:38pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596770.3 | 511897.9 | 4239 | 1.64041666667 | 11150 |
| 010947 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:39pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596770.4 | 511896.5 | 4241 | 1.64041666667 | 10947 |
| 011137 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:40pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596770.2 | 511896.0 | 4243 | 1.64041666667 | 11137 |
| 010524 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:41pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596770.9 | 511894.7 | 4245 | 1.64041666667 | 10524 |
| 010311 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:42pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596771.6 | 511892.2 | 4247 | 1.64041666667 | 10311 |
| 011337 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:43pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596772.4 | 511889.5 | 4249 | 1.64041666667 | 11337 |
| 010274 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:44pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596773.1 | 511888.0 | 4251 | 1.64041666667 | 10274 |
| 011718 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596773.4 | 511887.6 | 4253 | 1.64041666667 | 11718 |
| 013039 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596773.4 | 511887.6 | 4255 | 1.64041666667 | 13039 |
| 010879 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:47pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596772.6 | 511889.0 | 4257 | 1.64041666667 | 10879 |
| 011480 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:48pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596772.8 | 511889.7 | 4259 | 1.64041666667 | 11480 |
| 011330 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:49pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596772.7 | 511890.9 | 4261 | 1.64041666667 | 11330 |
| 011322 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:50pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596772.5 | 511892.9 | 4263 | 1.64041666667 | 11322 |
| 011650 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:51pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596771.5 | 511894.5 | 4265 | 1.64041666667 | 11650 |
| 014642 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:52pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596770.2 | 511895.5 | 4267 | 1.64041666667 | 14642 |
| 012750 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:53pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596768.0 | 511896.1 | 4269 | 1.64041666667 | 12750 |
| 012577 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:54pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596766.1 | 511895.5 | 4271 | 1.64041666667 | 12577 |
| 014094 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:55pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596763.4 | 511895.1 | 4273 | 1.64041666667 | 14094 |
| 012883 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:56pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596761.2 | 511894.6 | 4275 | 1.64041666667 | 12883 |
| 011561 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:57pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596758.5 | 511894.4 | 4277 | 1.64041666667 | 11561 |
| 010840 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:58pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596756.7 | 511893.1 | 4279 | 1.64041666667 | 10840 |
| 012220 | 0 | GeoXH 6000 | 08/20/2015 | 12:14:59pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596754.4 | 511891.5 | 4281 | 1.64041666667 | 12220 |
| 012925 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:00pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596752.2 | 511890.8 | 4283 | 1.64041666667 | 12925 |
| 013131 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:01pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596749.5 | 511890.0 | 4285 | 1.64041666667 | 13131 |
| 012522 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596747.0 | 511889.4 | 4287 | 1.64041666667 | 12522 |
| 012790 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:03pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596744.4 | 511888.2 | 4289 | 1.64041666667 | 12790 |
| 012137 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596742.0 | 511887.8 | 4291 | 1.64041666667 | 12137 |
| 011464 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596739.2 | 511887.3 | 4293 | 1.64041666667 | 11464 |
| 012796 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596736.9 | 511887.1 | 4295 | 1.64041666667 | 12796 |
| 011629 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596734.2 | 511886.5 | 4297 | 1.64041666667 | 11629 |
| 015237 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596731.9 | 511885.9 | 4299 | 1.64041666667 | 15237 |
| 013349 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596729.2 | 511884.9 | 4301 | 1.64041666667 | 13349 |
| 012487 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596726.9 | 511883.3 | 4303 | 1.64041666667 | 12487 |
| 013051 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:11pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596724.8 | 511882.0 | 4305 | 1.64041666667 | 13051 |
| 013882 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:12pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596723.3 | 511881.0 | 4307 | 1.64041666667 | 13882 |
| 015440 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:13pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596721.0 | 511880.4 | 4309 | 1.64041666667 | 15440 |
| 016340 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:14pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596718.8 | 511879.4 | 4311 | 1.64041666667 | 16340 |
| 015245 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:15pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596716.2 | 511879.0 | 4313 | 1.64041666667 | 15245 |
| 015361 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:16pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596713.9 | 511878.5 | 4315 | 1.64041666667 | 15361 |
| 015660 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:17pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596711.1 | 511877.7 | 4317 | 1.64041666667 | 15660 |
| 018645 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:18pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596708.2 | 511876.7 | 4319 | 1.64041666667 | 18645 |
| 016691 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:19pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596705.7 | 511875.4 | 4321 | 1.64041666667 | 16691 |
| 016743 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:20pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596703.2 | 511874.4 | 4323 | 1.64041666667 | 16743 |
| 019155 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596700.6 | 511873.1 | 4325 | 1.64041666667 | 19155 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 018888 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596698.3 | 511872.4 | 4327 | 1.64041666667 | 18888 |
| 016092 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596695.6 | 511871.5 | 4329 | 1.64041666667 | 16092 |
| 015273 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:24pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596693.1 | 511870.7 | 4331 | 1.64041666667 | 15273 |
| 015878 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:25pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596690.2 | 511869.9 | 4333 | 1.64041666667 | 15878 |
| 017499 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:26pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596687.7 | 511869.0 | 4335 | 1.64041666667 | 17499 |
| 018505 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:27pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596684.8 | 511868.4 | 4337 | 1.64041666667 | 18505 |
| 017856 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596682.3 | 511867.4 | 4339 | 1.64041666667 | 17856 |
| 016674 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596679.7 | 511866.5 | 4341 | 1.64041666667 | 16674 |
| 016348 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:30pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596677.5 | 511865.4 | 4343 | 1.64041666667 | 16348 |
| 015997 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:31pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596674.8 | 511864.3 | 4345 | 1.64041666667 | 15997 |
| 015099 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:32pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596672.5 | 511863.6 | 4347 | 1.64041666667 | 15099 |
| 014994 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:33pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596669.4 | 511862.4 | 4349 | 1.64041666667 | 14994 |
| 014518 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:34pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596667.0 | 511861.8 | 4351 | 1.64041666667 | 14518 |
| 016289 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:35pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596664.8 | 511860.9 | 4353 | 1.64041666667 | 16289 |
| 016702 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596662.8 | 511859.3 | 4355 | 1.64041666667 | 16702 |
| 015155 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:37pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596662.3 | 511858.5 | 4357 | 1.64041666667 | 15155 |
| 014408 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:38pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596662.7 | 511857.6 | 4359 | 1.64041666667 | 14408 |
| 015782 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:39pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596663.1 | 511855.2 | 4361 | 1.64041666667 | 15782 |
| 014775 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:40pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596664.3 | 511853.6 | 4363 | 1.64041666667 | 14775 |
| 014523 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:41pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596665.2 | 511852.7 | 4365 | 1.64041666667 | 14523 |
| 013831 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:42pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596665.3 | 511852.7 | 4367 | 1.64041666667 | 13831 |
| 014047 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:43pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596665.5 | 511852.4 | 4369 | 1.64041666667 | 14047 |
| 015122 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:44pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596666.5 | 511850.6 | 4371 | 1.64041666667 | 15122 |
| 015300 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:45pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596668.3 | 511848.0 | 4373 | 1.64041666667 | 15300 |
| 014625 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:46pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596669.5 | 511846.8 | 4375 | 1.64041666667 | 14625 |
| 013466 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596671.0 | 511845.5 | 4377 | 1.64041666667 | 13466 |
| 013776 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596671.6 | 511845.1 | 4379 | 1.64041666667 | 13776 |
| 014184 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596671.9 | 511844.8 | 4381 | 1.64041666667 | 14184 |
| 014826 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596671.5 | 511844.9 | 4383 | 1.64041666667 | 14826 |
| 013156 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:51pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596669.3 | 511845.6 | 4385 | 1.64041666667 | 13156 |
| 013609 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:52pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596668.6 | 511846.7 | 4387 | 1.64041666667 | 13609 |
| 013302 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:53pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596668.1 | 511848.7 | 4389 | 1.64041666667 | 13302 |
| 014545 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:54pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596667.7 | 511850.8 | 4391 | 1.64041666667 | 14545 |
| 014466 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:55pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596666.2 | 511852.4 | 4393 | 1.64041666667 | 14466 |
| 015406 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:56pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596665.8 | 511852.6 | 4395 | 1.64041666667 | 15406 |
| 014891 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:57pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596667.3 | 511852.7 | 4397 | 1.64041666667 | 14891 |
| 014163 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:58pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596669.1 | 511853.4 | 4399 | 1.64041666667 | 14163 |
| 014520 | 0 | GeoXH 6000 | 08/20/2015 | 12:15:59pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596671.6 | 511855.3 | 4401 | 1.64041666667 | 14520 |
| 015750 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:00pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596674.2 | 511856.7 | 4403 | 1.64041666667 | 15750 |
| 017527 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:01pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596676.5 | 511858.1 | 4405 | 1.64041666667 | 17527 |
| 015692 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:02pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596679.0 | 511858.9 | 4407 | 1.64041666667 | 15692 |
| 014783 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:03pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596681.7 | 511859.8 | 4409 | 1.64041666667 | 14783 |
| 016595 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:04pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596684.4 | 511860.4 | 4411 | 1.64041666667 | 16595 |
| 014829 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:05pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596687.4 | 511861.2 | 4413 | 1.64041666667 | 14829 |
| 016457 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:06pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596689.8 | 511862.5 | 4415 | 1.64041666667 | 16457 |
| 015964 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:07pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596692.6 | 511863.7 | 4417 | 1.64041666667 | 15964 |
| 017851 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:08pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596694.7 | 511864.9 | 4419 | 1.64041666667 | 17851 |
| 018502 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:09pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596697.5 | 511865.5 | 4421 | 1.64041666667 | 18502 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 017945 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:10pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596699.7 | 511865.7 | 4423 | 1.64041666667 | 17945 |
| 018796 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:11pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596702.9 | 511866.4 | 4425 | 1.64041666667 | 18796 |
| 016969 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:12pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596705.5 | 511866.9 | 4427 | 1.64041666667 | 16969 |
| 016782 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:13pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596708.4 | 511868.0 | 4429 | 1.64041666667 | 16782 |
| 016915 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:14pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596710.5 | 511868.5 | 4431 | 1.64041666667 | 16915 |
| 017129 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:15pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596713.3 | 511869.7 | 4433 | 1.64041666667 | 17129 |
| 015802 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:16pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596715.4 | 511870.6 | 4435 | 1.64041666667 | 15802 |
| 014510 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:17pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596718.2 | 511871.3 | 4437 | 1.64041666667 | 14510 |
| 014637 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:18pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596720.8 | 511872.0 | 4439 | 1.64041666667 | 14637 |
| 014549 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:19pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596723.9 | 511872.4 | 4441 | 1.64041666667 | 14549 |
| 014107 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:20pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596726.2 | 511873.2 | 4443 | 1.64041666667 | 14107 |
| 015706 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596728.8 | 511873.6 | 4445 | 1.64041666667 | 15706 |
| 012776 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596731.2 | 511874.3 | 4447 | 1.64041666667 | 12776 |
| 012134 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596734.4 | 511875.8 | 4449 | 1.64041666667 | 12134 |
| 013233 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:24pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596737.0 | 511876.7 | 4451 | 1.64041666667 | 13233 |
| 012938 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:25pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596739.7 | 511877.7 | 4453 | 1.64041666667 | 12938 |
| 013284 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:26pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596742.0 | 511878.2 | 4455 | 1.64041666667 | 13284 |
| 012801 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:27pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596744.6 | 511879.4 | 4457 | 1.64041666667 | 12801 |
| 012500 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596746.4 | 511880.3 | 4459 | 1.64041666667 | 12500 |
| 012845 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596749.2 | 511881.5 | 4461 | 1.64041666667 | 12845 |
| 012571 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:30pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596751.6 | 511882.1 | 4463 | 1.64041666667 | 12571 |
| 013162 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:31pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596755.0 | 511882.6 | 4465 | 1.64041666667 | 13162 |
| 014960 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:32pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596757.2 | 511883.3 | 4467 | 1.64041666667 | 14960 |
| 014210 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:33pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596760.0 | 511884.2 | 4469 | 1.64041666667 | 14210 |
| 012852 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:34pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596762.2 | 511885.2 | 4471 | 1.64041666667 | 12852 |
| 011583 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:35pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596765.0 | 511886.2 | 4473 | 1.64041666667 | 11583 |
| 012105 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:36pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596767.5 | 511887.0 | 4475 | 1.64041666667 | 12105 |
| 012776 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:37pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596770.1 | 511888.1 | 4477 | 1.64041666667 | 12776 |
| 011384 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:38pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596771.0 | 511888.5 | 4479 | 1.64041666667 | 11384 |
| 010946 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:39pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596771.1 | 511888.6 | 4481 | 1.64041666667 | 10946 |
| 011946 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:40pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596771.0 | 511888.6 | 4483 | 1.64041666667 | 11946 |
| 011416 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:41pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596770.9 | 511888.6 | 4485 | 1.64041666667 | 11416 |
| 010654 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:42pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596771.4 | 511888.7 | 4487 | 1.64041666667 | 10654 |
| 012803 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:43pm | Sensor | 1797-S0002-G-TJV.cor | 6855.0 | 1596772.9 | 511887.9 | 4489 | 1.64041666667 | 12803 |
| 012741 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:44pm | Sensor | 1797-S0002-G-TJV.cor | 6855.7 | 1596772.7 | 511887.7 | 4491 | 1.64041666667 | 12741 |
| 011135 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:45pm | Sensor | 1797-S0002-G-TJV.cor | 6855.2 | 1596772.2 | 511887.7 | 4493 | 1.64041666667 | 11135 |
| 011243 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:46pm | Sensor | 1797-S0002-G-TJV.cor | 6854.8 | 1596773.2 | 511886.3 | 4495 | 1.64041666667 | 11243 |
| 011931 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:47pm | Sensor | 1797-S0002-G-TJV.cor | 6854.8 | 1596774.2 | 511884.0 | 4497 | 1.64041666667 | 11931 |
| 011772 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:48pm | Sensor | 1797-S0002-G-TJV.cor | 6854.8 | 1596774.7 | 511883.3 | 4499 | 1.64041666667 | 11772 |
| 010203 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:49pm | Sensor | 1797-S0002-G-TJV.cor | 6854.8 | 1596775.1 | 511881.7 | 4501 | 1.64041666667 | 10203 |
| 009960 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:50pm | Sensor | 1797-S0002-G-TJV.cor | 6854.8 | 1596775.6 | 511879.8 | 4503 | 1.64041666667 | 9960 |
| 010050 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:51pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596776.1 | 511876.3 | 4505 | 1.64041666667 | 10050 |
| 011272 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:52pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596776.2 | 511874.8 | 4507 | 1.64041666667 | 11272 |
| 011608 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:53pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596775.8 | 511876.0 | 4509 | 1.64041666667 | 11608 |
| 011692 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:54pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596776.4 | 511877.3 | 4511 | 1.64041666667 | 11692 |
| 010003 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:55pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596776.6 | 511878.9 | 4513 | 1.64041666667 | 10003 |
| 011020 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:56pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596775.6 | 511880.6 | 4515 | 1.64041666667 | 11020 |
| 012325 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:57pm | Sensor | 1797-S0002-G-TJV.cor | 6854.8 | 1596773.6 | 511881.6 | 4517 | 1.64041666667 | 12325 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 011211 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:58pm | Sensor | 1797-S0002-G-TJV.cor | 6854.9 | 1596771.5 | 511881.7 | 4519 | 1.64041666667 | 11211 |
| 011712 | 0 | GeoXH 6000 | 08/20/2015 | 12:16:59pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596768.9 | 511881.5 | 4521 | 1.64041666667 | 11712 |
| 011508 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:00pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596766.7 | 511880.1 | 4523 | 1.64041666667 | 11508 |
| 013707 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:01pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596763.8 | 511879.0 | 4525 | 1.64041666667 | 13707 |
| 014616 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:02pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596761.3 | 511878.2 | 4527 | 1.64041666667 | 14616 |
| 014994 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:03pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596758.5 | 511877.5 | 4529 | 1.64041666667 | 14994 |
| 014998 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:04pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596756.1 | 511876.8 | 4531 | 1.64041666667 | 14998 |
| 014159 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:05pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596753.0 | 511875.8 | 4533 | 1.64041666667 | 14159 |
| 013170 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:06pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596750.2 | 511875.5 | 4535 | 1.64041666667 | 13170 |
| 012922 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:07pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596747.6 | 511874.9 | 4537 | 1.64041666667 | 12922 |
| 013520 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:08pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596745.2 | 511874.2 | 4539 | 1.64041666667 | 13520 |
| 012830 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:09pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596742.0 | 511873.2 | 4541 | 1.64041666667 | 12830 |
| 014247 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:10pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596739.1 | 511872.2 | 4543 | 1.64041666667 | 14247 |
| 013762 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:11pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596735.9 | 511871.4 | 4545 | 1.64041666667 | 13762 |
| 013181 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:12pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596733.5 | 511870.3 | 4547 | 1.64041666667 | 13181 |
| 011067 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:13pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596730.7 | 511869.5 | 4549 | 1.64041666667 | 11067 |
| 014557 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:14pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596728.2 | 511868.9 | 4551 | 1.64041666667 | 14557 |
| 014529 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:15pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596725.1 | 511868.0 | 4553 | 1.64041666667 | 14529 |
| 015992 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:16pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596722.4 | 511867.7 | 4555 | 1.64041666667 | 15992 |
| 014948 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:17pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596719.5 | 511866.6 | 4557 | 1.64041666667 | 14948 |
| 013697 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:18pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596717.3 | 511865.5 | 4559 | 1.64041666667 | 13697 |
| 016744 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:19pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596714.9 | 511863.8 | 4561 | 1.64041666667 | 16744 |
| 016936 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:20pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596712.7 | 511862.1 | 4563 | 1.64041666667 | 16936 |
| 017404 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596709.3 | 511860.6 | 4565 | 1.64041666667 | 17404 |
| 017221 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596706.9 | 511859.5 | 4567 | 1.64041666667 | 17221 |
| 015315 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596703.9 | 511858.7 | 4569 | 1.64041666667 | 15315 |
| 015198 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:24pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596701.6 | 511857.8 | 4571 | 1.64041666667 | 15198 |
| 013909 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:25pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596698.7 | 511856.7 | 4573 | 1.64041666667 | 13909 |
| 014817 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:26pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596696.2 | 511856.2 | 4575 | 1.64041666667 | 14817 |
| 015734 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:27pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596693.4 | 511855.1 | 4577 | 1.64041666667 | 15734 |
| 013173 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596691.1 | 511854.2 | 4579 | 1.64041666667 | 13173 |
| 015353 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596688.8 | 511852.5 | 4581 | 1.64041666667 | 15353 |
| 015898 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:30pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596686.6 | 511851.5 | 4583 | 1.64041666667 | 15898 |
| 015674 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:31pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596684.0 | 511850.5 | 4585 | 1.64041666667 | 15674 |
| 015348 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:32pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596681.8 | 511849.7 | 4587 | 1.64041666667 | 15348 |
| 014937 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:33pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596678.6 | 511848.8 | 4589 | 1.64041666667 | 14937 |
| 013844 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:34pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596676.2 | 511847.5 | 4591 | 1.64041666667 | 13844 |
| 014591 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:35pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596672.7 | 511845.6 | 4593 | 1.64041666667 | 14591 |
| 015707 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596671.2 | 511844.6 | 4595 | 1.64041666667 | 15707 |
| 017036 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:37pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596672.0 | 511843.8 | 4597 | 1.64041666667 | 17036 |
| 015329 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:38pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596672.9 | 511842.1 | 4599 | 1.64041666667 | 15329 |
| 014782 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:39pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596674.2 | 511841.3 | 4601 | 1.64041666667 | 14782 |
| 014255 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:40pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596675.2 | 511841.2 | 4603 | 1.64041666667 | 14255 |
| 014393 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:41pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596676.1 | 511841.4 | 4605 | 1.64041666667 | 14393 |
| 012928 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:42pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596677.8 | 511841.8 | 4607 | 1.64041666667 | 12928 |
| 014062 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:43pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596680.3 | 511842.3 | 4609 | 1.64041666667 | 14062 |
| 014435 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:44pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596682.7 | 511843.6 | 4611 | 1.64041666667 | 14435 |
| 013988 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:45pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596685.5 | 511844.8 | 4613 | 1.64041666667 | 13988 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 014717 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:46pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596687.7 | 511846.0 | 4615 | 1.64041666667 | 14717 |
| 015079 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:47pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596690.4 | 511847.3 | 4617 | 1.64041666667 | 15079 |
| 017299 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:48pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596692.8 | 511848.3 | 4619 | 1.64041666667 | 17299 |
| 016085 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:49pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596695.8 | 511849.9 | 4621 | 1.64041666667 | 16085 |
| 015151 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:50pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596698.7 | 511851.1 | 4623 | 1.64041666667 | 15151 |
| 014107 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:51pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596701.6 | 511852.4 | 4625 | 1.64041666667 | 14107 |
| 014627 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:52pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596704.1 | 511853.3 | 4627 | 1.64041666667 | 14627 |
| 014546 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:53pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596707.1 | 511854.4 | 4629 | 1.64041666667 | 14546 |
| 016056 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:54pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596709.8 | 511855.9 | 4631 | 1.64041666667 | 16056 |
| 015954 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:55pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596713.0 | 511856.6 | 4633 | 1.64041666667 | 15954 |
| 014098 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:56pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596715.7 | 511857.0 | 4635 | 1.64041666667 | 14098 |
| 015194 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:57pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596718.9 | 511857.4 | 4637 | 1.64041666667 | 15194 |
| 013848 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:58pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596721.5 | 511857.9 | 4639 | 1.64041666667 | 13848 |
| 013992 | 0 | GeoXH 6000 | 08/20/2015 | 12:17:59pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596724.2 | 511859.0 | 4641 | 1.64041666667 | 13992 |
| 013458 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:00pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596726.5 | 511860.0 | 4643 | 1.64041666667 | 13458 |
| 013234 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:01pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596729.2 | 511861.6 | 4645 | 1.64041666667 | 13234 |
| 012428 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:02pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596731.8 | 511862.5 | 4647 | 1.64041666667 | 12428 |
| 012197 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:03pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596735.1 | 511863.2 | 4649 | 1.64041666667 | 12197 |
| 012019 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:04pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596737.7 | 511864.2 | 4651 | 1.64041666667 | 12019 |
| 013144 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:05pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596740.6 | 511864.7 | 4653 | 1.64041666667 | 13144 |
| 011536 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:06pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596743.0 | 511865.2 | 4655 | 1.64041666667 | 11536 |
| 013084 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:07pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596746.0 | 511865.5 | 4657 | 1.64041666667 | 13084 |
| 012901 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:08pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596748.4 | 511866.0 | 4659 | 1.64041666667 | 12901 |
| 014175 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:09pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596751.0 | 511867.6 | 4661 | 1.64041666667 | 14175 |
| 013863 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:10pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596753.1 | 511868.8 | 4663 | 1.64041666667 | 13863 |
| 014296 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:11pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596755.6 | 511870.3 | 4665 | 1.64041666667 | 14296 |
| 014074 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:12pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596757.7 | 511870.7 | 4667 | 1.64041666667 | 14074 |
| 013298 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:13pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596760.7 | 511871.0 | 4669 | 1.64041666667 | 13298 |
| 014274 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:14pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596763.3 | 511871.4 | 4671 | 1.64041666667 | 14274 |
| 013198 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:15pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596766.7 | 511871.6 | 4673 | 1.64041666667 | 13198 |
| 011849 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:16pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596769.1 | 511872.3 | 4675 | 1.64041666667 | 11849 |
| 010672 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:17pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596771.6 | 511873.0 | 4677 | 1.64041666667 | 10672 |
| 012238 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:18pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596773.5 | 511873.7 | 4679 | 1.64041666667 | 12238 |
| 012359 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:19pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596775.1 | 511874.9 | 4681 | 1.64041666667 | 12359 |
| 010800 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:20pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596774.7 | 511874.7 | 4683 | 1.64041666667 | 10800 |
| 011190 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596773.3 | 511874.4 | 4685 | 1.64041666667 | 11190 |
| 012037 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596772.1 | 511874.0 | 4687 | 1.64041666667 | 12037 |
| 011409 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596770.0 | 511872.9 | 4689 | 1.64041666667 | 11409 |
| 012002 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:24pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596767.9 | 511871.9 | 4691 | 1.64041666667 | 12002 |
| 013560 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:25pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596765.3 | 511871.4 | 4693 | 1.64041666667 | 13560 |
| 012540 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:26pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596763.1 | 511871.0 | 4695 | 1.64041666667 | 12540 |
| 013635 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:27pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596760.4 | 511870.1 | 4697 | 1.64041666667 | 13635 |
| 015018 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596757.8 | 511869.6 | 4699 | 1.64041666667 | 15018 |
| 013714 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596755.3 | 511869.0 | 4701 | 1.64041666667 | 13714 |
| 014168 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:30pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596753.2 | 511868.2 | 4703 | 1.64041666667 | 14168 |
| 015452 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:31pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596750.6 | 511867.2 | 4705 | 1.64041666667 | 15452 |
| 015263 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:32pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596748.3 | 511867.0 | 4707 | 1.64041666667 | 15263 |
| 012725 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:33pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596745.3 | 511866.9 | 4709 | 1.64041666667 | 12725 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 013351 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:34pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596742.8 | 511866.7 | 4711 | 1.64041666667 | 13351 |
| 012397 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:35pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596739.8 | 511866.8 | 4713 | 1.64041666667 | 12397 |
| 011169 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:36pm | Sensor | 1797-S0002-G-TJV.cor | 6854.7 | 1596737.4 | 511867.1 | 4715 | 1.64041666667 | 11169 |
| 013802 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:37pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596734.4 | 511868.0 | 4717 | 1.64041666667 | 13802 |
| 012600 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:38pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596731.9 | 511868.8 | 4719 | 1.64041666667 | 12600 |
| 013500 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:39pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596729.3 | 511868.8 | 4721 | 1.64041666667 | 13500 |
| 014115 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:40pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596726.9 | 511868.5 | 4723 | 1.64041666667 | 14115 |
| 014208 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:41pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596723.9 | 511868.6 | 4725 | 1.64041666667 | 14208 |
| 015312 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:42pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596721.2 | 511868.8 | 4727 | 1.64041666667 | 15312 |
| 016638 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:43pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596718.6 | 511869.6 | 4729 | 1.64041666667 | 16638 |
| 015649 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:44pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596715.9 | 511869.9 | 4731 | 1.64041666667 | 15649 |
| 016662 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:45pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596712.7 | 511869.8 | 4733 | 1.64041666667 | 16662 |
| 017965 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:46pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596710.1 | 511870.1 | 4735 | 1.64041666667 | 17965 |
| 018381 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:47pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596706.8 | 511870.5 | 4737 | 1.64041666667 | 18381 |
| 017645 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:48pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596704.1 | 511870.8 | 4739 | 1.64041666667 | 17645 |
| 019681 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:49pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596701.1 | 511871.7 | 4741 | 1.64041666667 | 19681 |
| 019590 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:50pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596698.3 | 511872.1 | 4743 | 1.64041666667 | 19590 |
| 017767 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:51pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596694.9 | 511872.0 | 4745 | 1.64041666667 | 17767 |
| 017012 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:52pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596692.3 | 511872.4 | 4747 | 1.64041666667 | 17012 |
| 017453 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:53pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596689.1 | 511873.2 | 4749 | 1.64041666667 | 17453 |
| 017623 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:54pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596686.5 | 511873.5 | 4751 | 1.64041666667 | 17623 |
| 016826 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:55pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596683.2 | 511874.0 | 4753 | 1.64041666667 | 16826 |
| 017706 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596680.4 | 511874.5 | 4755 | 1.64041666667 | 17706 |
| 015736 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:57pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596677.1 | 511874.9 | 4757 | 1.64041666667 | 15736 |
| 015274 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596674.2 | 511875.3 | 4759 | 1.64041666667 | 15274 |
| 015308 | 0 | GeoXH 6000 | 08/20/2015 | 12:18:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596671.1 | 511876.1 | 4761 | 1.64041666667 | 15308 |
| 015347 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596668.7 | 511876.6 | 4763 | 1.64041666667 | 15347 |
| 013556 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596665.7 | 511877.9 | 4765 | 1.64041666667 | 13556 |
| 012569 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596664.9 | 511880.0 | 4767 | 1.64041666667 | 12569 |
| 013042 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:03pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596666.3 | 511882.3 | 4769 | 1.64041666667 | 13042 |
| 013310 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596669.0 | 511882.7 | 4771 | 1.64041666667 | 13310 |
| 015327 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596672.6 | 511881.5 | 4773 | 1.64041666667 | 15327 |
| 013732 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596675.1 | 511880.6 | 4775 | 1.64041666667 | 13732 |
| 014473 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596678.5 | 511879.7 | 4777 | 1.64041666667 | 14473 |
| 016638 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:08pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596681.0 | 511878.9 | 4779 | 1.64041666667 | 16638 |
| 016159 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:09pm | Sensor | 1797-S0002-G-TJV.cor | 6854.0 | 1596684.3 | 511878.0 | 4781 | 1.64041666667 | 16159 |
| 016009 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:10pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596687.3 | 511877.5 | 4783 | 1.64041666667 | 16009 |
| 018852 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:11pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596690.6 | 511876.6 | 4785 | 1.64041666667 | 18852 |
| 016773 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:12pm | Sensor | 1797-S0002-G-TJV.cor | 6854.2 | 1596693.4 | 511876.0 | 4787 | 1.64041666667 | 16773 |
| 017543 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:13pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596696.7 | 511875.3 | 4789 | 1.64041666667 | 17543 |
| 018065 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:14pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596699.5 | 511874.4 | 4791 | 1.64041666667 | 18065 |
| 019696 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:15pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596702.7 | 511874.0 | 4793 | 1.64041666667 | 19696 |
| 016654 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:16pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596706.0 | 511874.2 | 4795 | 1.64041666667 | 16654 |
| 017933 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:17pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596709.1 | 511873.9 | 4797 | 1.64041666667 | 17933 |
| 018883 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:18pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596712.1 | 511873.2 | 4799 | 1.64041666667 | 18883 |
| 016301 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:19pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596715.5 | 511872.9 | 4801 | 1.64041666667 | 16301 |
| 014815 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:20pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596718.4 | 511873.1 | 4803 | 1.64041666667 | 14815 |
| 015043 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:21pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596720.9 | 511874.5 | 4805 | 1.64041666667 | 15043 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 016451 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:22pm | Sensor | 1797-S0002-G-TJV.cor | 6854.6 | 1596720.8 | 511876.5 | 4807 | 1.64041666667 | 16451 |
| 017612 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:23pm | Sensor | 1797-S0002-G-TJV.cor | 6854.5 | 1596718.7 | 511878.2 | 4809 | 1.64041666667 | 17612 |
| 017453 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:24pm | Sensor | 1797-S0002-G-TJV.cor | 6854.4 | 1596715.8 | 511879.2 | 4811 | 1.64041666667 | 17453 |
| 016933 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:25pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596712.5 | 511879.6 | 4813 | 1.64041666667 | 16933 |
| 017403 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:26pm | Sensor | 1797-S0002-G-TJV.cor | 6854.3 | 1596709.3 | 511879.8 | 4815 | 1.64041666667 | 17403 |
| 014850 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:27pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596705.8 | 511880.1 | 4817 | 1.64041666667 | 14850 |
| 013402 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:28pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596703.1 | 511880.6 | 4819 | 1.64041666667 | 13402 |
| 014480 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:29pm | Sensor | 1797-S0002-G-TJV.cor | 6854.1 | 1596699.9 | 511881.6 | 4821 | 1.64041666667 | 14480 |
| 014600 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596697.4 | 511883.3 | 4823 | 1.64041666667 | 14600 |
| 013430 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596696.4 | 511886.3 | 4825 | 1.64041666667 | 13430 |
| 012357 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596697.5 | 511889.2 | 4827 | 1.64041666667 | 12357 |
| 013649 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:33pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596699.7 | 511891.8 | 4829 | 1.64041666667 | 13649 |
| 015082 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:34pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596702.1 | 511893.7 | 4831 | 1.64041666667 | 15082 |
| 012860 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:35pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596704.5 | 511895.6 | 4833 | 1.64041666667 | 12860 |
| 010655 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:36pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596706.5 | 511898.1 | 4835 | 1.64041666667 | 10655 |
| 011813 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:37pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596708.0 | 511901.3 | 4837 | 1.64041666667 | 11813 |
| 012553 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:38pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596709.2 | 511904.0 | 4839 | 1.64041666667 | 12553 |
| 013038 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:39pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596710.5 | 511907.1 | 4841 | 1.64041666667 | 13038 |
| 011719 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:40pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596711.1 | 511909.9 | 4843 | 1.64041666667 | 11719 |
| 011239 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:41pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596711.4 | 511913.1 | 4845 | 1.64041666667 | 11239 |
| 010610 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:42pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596712.1 | 511916.3 | 4847 | 1.64041666667 | 10610 |
| 010572 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:43pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596713.1 | 511919.5 | 4849 | 1.64041666667 | 10572 |
| 011523 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:44pm | Sensor | 1797-S0002-G-TJV.cor | 6852.7 | 1596714.1 | 511922.3 | 4851 | 1.64041666667 | 11523 |
| 011010 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:45pm | Sensor | 1797-S0002-G-TJV.cor | 6852.6 | 1596715.4 | 511925.4 | 4853 | 1.64041666667 | 11010 |
| 011392 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:46pm | Sensor | 1797-S0002-G-TJV.cor | 6852.8 | 1596716.1 | 511928.5 | 4855 | 1.64041666667 | 11392 |
| 011068 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596715.6 | 511931.1 | 4857 | 1.64041666667 | 11068 |
| 012157 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596715.4 | 511933.2 | 4859 | 1.64041666667 | 12157 |
| 011109 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596715.8 | 511935.6 | 4861 | 1.64041666667 | 11109 |
| 010937 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596717.0 | 511937.8 | 4863 | 1.64041666667 | 10937 |
| 013054 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:51pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596719.2 | 511939.7 | 4865 | 1.64041666667 | 13054 |
| 015983 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:52pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596721.5 | 511941.2 | 4867 | 1.64041666667 | 15983 |
| 017646 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596724.2 | 511941.9 | 4869 | 1.64041666667 | 17646 |
| 017341 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596727.3 | 511941.9 | 4871 | 1.64041666667 | 17341 |
| 015825 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596730.4 | 511942.1 | 4873 | 1.64041666667 | 15825 |
| 012356 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596733.1 | 511942.5 | 4875 | 1.64041666667 | 12356 |
| 012389 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:57pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596736.1 | 511943.6 | 4877 | 1.64041666667 | 12389 |
| 010957 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596737.0 | 511945.0 | 4879 | 1.64041666667 | 10957 |
| 011709 | 0 | GeoXH 6000 | 08/20/2015 | 12:19:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596735.7 | 511947.2 | 4881 | 1.64041666667 | 11709 |
| 011567 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596733.3 | 511948.6 | 4883 | 1.64041666667 | 11567 |
| 012131 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596730.4 | 511949.1 | 4885 | 1.64041666667 | 12131 |
| 012813 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596728.0 | 511949.0 | 4887 | 1.64041666667 | 12813 |
| 015083 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:03pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596724.7 | 511948.6 | 4889 | 1.64041666667 | 15083 |
| 017750 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:04pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596722.0 | 511947.8 | 4891 | 1.64041666667 | 17750 |
| 013437 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596718.7 | 511946.9 | 4893 | 1.64041666667 | 13437 |
| 012659 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596716.4 | 511947.1 | 4895 | 1.64041666667 | 12659 |
| 011205 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596714.9 | 511949.0 | 4897 | 1.64041666667 | 11205 |
| 010481 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596715.9 | 511950.7 | 4899 | 1.64041666667 | 10481 |
| 010990 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596718.8 | 511952.2 | 4901 | 1.64041666667 | 10990 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|------|---------------|-------|
| 012647 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596721.5 | 511953.1 | 4903 | 1.64041666667 | 12647 |
| 014051 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:11pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596724.8 | 511953.6 | 4905 | 1.64041666667 | 14051 |
| 018543 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596727.8 | 511953.6 | 4907 | 1.64041666667 | 18543 |
| 018975 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596731.1 | 511953.7 | 4909 | 1.64041666667 | 18975 |
| 018333 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.9 | 1596734.0 | 511954.0 | 4911 | 1.64041666667 | 18333 |
| 016643 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596737.6 | 511954.9 | 4913 | 1.64041666667 | 16643 |
| 014031 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596740.3 | 511955.9 | 4915 | 1.64041666667 | 14031 |
| 012777 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:17pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596742.3 | 511957.9 | 4917 | 1.64041666667 | 12777 |
| 012704 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596742.5 | 511960.2 | 4919 | 1.64041666667 | 12704 |
| 013016 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596740.3 | 511962.1 | 4921 | 1.64041666667 | 13016 |
| 014594 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596737.4 | 511962.6 | 4923 | 1.64041666667 | 14594 |
| 015918 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:21pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596733.8 | 511962.7 | 4925 | 1.64041666667 | 15918 |
| 020959 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596731.0 | 511962.4 | 4927 | 1.64041666667 | 20959 |
| 020179 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596727.3 | 511961.2 | 4929 | 1.64041666667 | 20179 |
| 018035 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596724.6 | 511959.8 | 4931 | 1.64041666667 | 18035 |
| 014948 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596721.6 | 511958.5 | 4933 | 1.64041666667 | 14948 |
| 015407 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596718.7 | 511957.6 | 4935 | 1.64041666667 | 15407 |
| 014261 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596715.4 | 511956.8 | 4937 | 1.64041666667 | 14261 |
| 011905 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596712.9 | 511957.0 | 4939 | 1.64041666667 | 11905 |
| 014796 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:29pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596712.0 | 511958.6 | 4941 | 1.64041666667 | 14796 |
| 013509 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596713.0 | 511960.3 | 4943 | 1.64041666667 | 13509 |
| 014417 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596715.8 | 511962.0 | 4945 | 1.64041666667 | 14417 |
| 015454 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596718.5 | 511962.9 | 4947 | 1.64041666667 | 15454 |
| 015533 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:33pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596721.3 | 511964.2 | 4949 | 1.64041666667 | 15533 |
| 015583 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:34pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596723.9 | 511965.8 | 4951 | 1.64041666667 | 15583 |
| 015506 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596726.5 | 511967.9 | 4953 | 1.64041666667 | 15506 |
| 015096 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596728.9 | 511969.8 | 4955 | 1.64041666667 | 15096 |
| 012294 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596731.6 | 511971.6 | 4957 | 1.64041666667 | 12294 |
| 012613 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596733.3 | 511973.1 | 4959 | 1.64041666667 | 12613 |
| 012333 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596733.3 | 511975.1 | 4961 | 1.64041666667 | 12333 |
| 011843 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596731.0 | 511976.5 | 4963 | 1.64041666667 | 11843 |
| 012920 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:41pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596727.7 | 511976.5 | 4965 | 1.64041666667 | 12920 |
| 012530 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:42pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596725.0 | 511976.3 | 4967 | 1.64041666667 | 12530 |
| 012492 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:43pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596721.8 | 511975.7 | 4969 | 1.64041666667 | 12492 |
| 010623 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:44pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596719.0 | 511974.4 | 4971 | 1.64041666667 | 10623 |
| 011925 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:45pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596716.1 | 511973.3 | 4973 | 1.64041666667 | 11925 |
| 011111 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:46pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596713.2 | 511972.8 | 4975 | 1.64041666667 | 11111 |
| 013428 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:47pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596710.1 | 511973.5 | 4977 | 1.64041666667 | 13428 |
| 013917 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:48pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596708.9 | 511975.5 | 4979 | 1.64041666667 | 13917 |
| 022169 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:49pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596709.2 | 511978.6 | 4981 | 1.64041666667 | 22169 |
| 021622 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:50pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596710.0 | 511980.5 | 4983 | 1.64041666667 | 21622 |
| 021275 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:51pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596711.1 | 511981.5 | 4985 | 1.64041666667 | 21275 |
| 022268 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:52pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596711.4 | 511982.0 | 4987 | 1.64041666667 | 22268 |
| 019427 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:53pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596712.5 | 511983.0 | 4989 | 1.64041666667 | 19427 |
| 016496 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:54pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596714.6 | 511984.3 | 4991 | 1.64041666667 | 16496 |
| 015254 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:55pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596715.9 | 511986.3 | 4993 | 1.64041666667 | 15254 |
| 017373 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:56pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596715.3 | 511987.9 | 4995 | 1.64041666667 | 17373 |
| 018383 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:57pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596712.7 | 511988.4 | 4997 | 1.64041666667 | 18383 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019685 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:58pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596710.0 | 511988.0 | 4999 | 1.64041666667 | 19685 |
| 018361 | 0 | GeoXH 6000 | 08/20/2015 | 12:20:59pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596706.8 | 511987.4 | 5001 | 1.64041666667 | 18361 |
| 018240 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:00pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596704.4 | 511986.6 | 5003 | 1.64041666667 | 18240 |
| 016860 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:01pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596701.5 | 511984.8 | 5005 | 1.64041666667 | 16860 |
| 014295 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:02pm | Sensor | 1797-S0002-G-TJV.cor | 6853.0 | 1596699.6 | 511983.0 | 5007 | 1.64041666667 | 14295 |
| 012993 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:03pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596698.8 | 511980.0 | 5009 | 1.64041666667 | 12993 |
| 011498 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:04pm | Sensor | 1797-S0002-G-TJV.cor | 6852.9 | 1596700.0 | 511978.3 | 5011 | 1.64041666667 | 11498 |
| 012474 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:05pm | Sensor | 1797-S0002-G-TJV.cor | 6853.1 | 1596702.8 | 511977.6 | 5013 | 1.64041666667 | 12474 |
| 017818 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:06pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596706.0 | 511978.0 | 5015 | 1.64041666667 | 17818 |
| 022484 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:07pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596709.1 | 511978.5 | 5017 | 1.64041666667 | 22484 |
| 021491 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:08pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596711.0 | 511978.1 | 5019 | 1.64041666667 | 21491 |
| 016982 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:09pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596711.9 | 511976.2 | 5021 | 1.64041666667 | 16982 |
| 013215 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:10pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596712.6 | 511974.0 | 5023 | 1.64041666667 | 13215 |
| 012693 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:11pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596713.8 | 511971.3 | 5025 | 1.64041666667 | 12693 |
| 013583 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:12pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596715.1 | 511969.0 | 5027 | 1.64041666667 | 13583 |
| 014916 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:13pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596716.8 | 511966.7 | 5029 | 1.64041666667 | 14916 |
| 013359 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:14pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596718.3 | 511965.1 | 5031 | 1.64041666667 | 13359 |
| 013359 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:15pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596720.8 | 511964.5 | 5033 | 1.64041666667 | 13359 |
| 014080 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:16pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596723.2 | 511965.0 | 5035 | 1.64041666667 | 14080 |
| 015340 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:17pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596725.7 | 511966.4 | 5037 | 1.64041666667 | 15340 |
| 016315 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:18pm | Sensor | 1797-S0002-G-TJV.cor | 6853.8 | 1596727.7 | 511968.7 | 5039 | 1.64041666667 | 16315 |
| 014908 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:19pm | Sensor | 1797-S0002-G-TJV.cor | 6853.7 | 1596729.7 | 511971.1 | 5041 | 1.64041666667 | 14908 |
| 012997 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:20pm | Sensor | 1797-S0002-G-TJV.cor | 6853.6 | 1596731.9 | 511972.6 | 5043 | 1.64041666667 | 12997 |
| 013329 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:21pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596734.5 | 511973.5 | 5045 | 1.64041666667 | 13329 |
| 011732 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:22pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596735.8 | 511974.2 | 5047 | 1.64041666667 | 11732 |
| 009983 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:23pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.3 | 511974.8 | 5049 | 1.64041666667 | 9983 |
| 010895 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:24pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.1 | 511974.9 | 5051 | 1.64041666667 | 10895 |
| 010734 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:25pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596735.9 | 511974.9 | 5053 | 1.64041666667 | 10734 |
| 011233 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:26pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596735.9 | 511974.9 | 5055 | 1.64041666667 | 11233 |
| 010428 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:27pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596735.9 | 511974.9 | 5057 | 1.64041666667 | 10428 |
| 011607 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:28pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596736.0 | 511974.9 | 5059 | 1.64041666667 | 11607 |
| 011301 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:29pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596736.2 | 511975.1 | 5061 | 1.64041666667 | 11301 |
| 012035 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:30pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596736.4 | 511975.2 | 5063 | 1.64041666667 | 12035 |
| 010268 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:31pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596736.3 | 511975.0 | 5065 | 1.64041666667 | 10268 |
| 010937 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:32pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596736.0 | 511974.7 | 5067 | 1.64041666667 | 10937 |
| 012454 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:33pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596735.9 | 511974.8 | 5069 | 1.64041666667 | 12454 |
| 011933 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:34pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596736.0 | 511975.0 | 5071 | 1.64041666667 | 11933 |
| 010783 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:35pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596736.2 | 511975.2 | 5073 | 1.64041666667 | 10783 |
| 011156 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:36pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596736.2 | 511975.1 | 5075 | 1.64041666667 | 11156 |
| 011189 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:37pm | Sensor | 1797-S0002-G-TJV.cor | 6853.3 | 1596736.2 | 511975.1 | 5077 | 1.64041666667 | 11189 |
| 010417 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:38pm | Sensor | 1797-S0002-G-TJV.cor | 6853.2 | 1596736.3 | 511975.1 | 5079 | 1.64041666667 | 10417 |
| 010224 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:39pm | Sensor | 1797-S0002-G-TJV.cor | 6853.4 | 1596736.2 | 511975.2 | 5081 | 1.64041666667 | 10224 |
| 012456 | 0 | GeoXH 6000 | 08/20/2015 | 12:21:40pm | Sensor | 1797-S0002-G-TJV.cor | 6853.5 | 1596736.2 | 511975.3 | 5083 | 1.64041666667 | 12456 |
| 016927 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:32pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593828.9 | 510796.3 | 28952 | 1.64041666667 | 16927 |
| 017191 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:33pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593828.9 | 510796.2 | 28955 | 1.64041666667 | 17191 |
| 018757 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:34pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593828.9 | 510796.2 | 28957 | 1.64041666667 | 18757 |
| 017679 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:35pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593828.9 | 510796.3 | 28959 | 1.64041666667 | 17679 |
| 017170 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:36pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593828.9 | 510796.2 | 28961 | 1.64041666667 | 17170 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015692 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:37pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593829.0 | 510796.2 | 28963 | 1.64041666667 | 15692 |
| 016703 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:38pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593829.6 | 510796.5 | 28965 | 1.64041666667 | 16703 |
| 017045 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:39pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593829.8 | 510796.5 | 28967 | 1.64041666667 | 17045 |
| 015091 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:40pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593829.8 | 510796.5 | 28969 | 1.64041666667 | 15091 |
| 015262 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:41pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593829.9 | 510796.5 | 28971 | 1.64041666667 | 15262 |
| 014495 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:42pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593829.9 | 510796.5 | 28973 | 1.64041666667 | 14495 |
| 015714 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:43pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593829.9 | 510796.5 | 28975 | 1.64041666667 | 15714 |
| 018478 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:44pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593829.7 | 510795.9 | 28977 | 1.64041666667 | 18478 |
| 017999 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:45pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593829.5 | 510795.4 | 28979 | 1.64041666667 | 17999 |
| 016740 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:46pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593828.5 | 510795.2 | 28981 | 1.64041666667 | 16740 |
| 019005 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:47pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593827.9 | 510795.0 | 28983 | 1.64041666667 | 19005 |
| 018581 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:48pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593827.8 | 510795.2 | 28985 | 1.64041666667 | 18581 |
| 018865 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:49pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593828.2 | 510795.3 | 28987 | 1.64041666667 | 18865 |
| 018276 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:50pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593828.1 | 510794.4 | 28989 | 1.64041666667 | 18276 |
| 018669 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:51pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593826.6 | 510793.2 | 28991 | 1.64041666667 | 18669 |
| 022097 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:52pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593824.8 | 510791.3 | 28993 | 1.64041666667 | 22097 |
| 023914 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:53pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593822.9 | 510789.6 | 28995 | 1.64041666667 | 23914 |
| 029108 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:54pm | Sensor | 1797-S0029-G-TJV.cor | 6811.0 | 1593821.2 | 510787.8 | 28997 | 1.64041666667 | 29108 |
| 028097 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:55pm | Sensor | 1797-S0029-G-TJV.cor | 6810.7 | 1593819.4 | 510785.8 | 28999 | 1.64041666667 | 28097 |
| 025894 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:56pm | Sensor | 1797-S0029-G-TJV.cor | 6810.8 | 1593816.7 | 510784.2 | 29001 | 1.64041666667 | 25894 |
| 024173 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:57pm | Sensor | 1797-S0029-G-TJV.cor | 6810.6 | 1593814.8 | 510782.7 | 29003 | 1.64041666667 | 24173 |
| 021493 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:58pm | Sensor | 1797-S0029-G-TJV.cor | 6810.9 | 1593812.6 | 510781.4 | 29005 | 1.64041666667 | 21493 |
| 021963 | 0 | GeoXH 6000 | 08/18/2015 | 02:29:59pm | Sensor | 1797-S0029-G-TJV.cor | 6810.9 | 1593811.0 | 510779.8 | 29007 | 1.64041666667 | 21963 |
| 018570 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:00pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593808.5 | 510778.2 | 29009 | 1.64041666667 | 18570 |
| 016762 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:01pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593806.9 | 510777.2 | 29011 | 1.64041666667 | 16762 |
| 018440 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:02pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593805.6 | 510776.3 | 29013 | 1.64041666667 | 18440 |
| 020450 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:03pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593805.3 | 510776.2 | 29015 | 1.64041666667 | 20450 |
| 019332 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:04pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593805.2 | 510776.1 | 29017 | 1.64041666667 | 19332 |
| 020373 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:05pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593805.2 | 510776.1 | 29019 | 1.64041666667 | 20373 |
| 018923 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:06pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593805.2 | 510776.1 | 29021 | 1.64041666667 | 18923 |
| 019100 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:07pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593805.3 | 510776.0 | 29023 | 1.64041666667 | 19100 |
| 021455 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:08pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593805.0 | 510776.2 | 29025 | 1.64041666667 | 21455 |
| 020963 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:09pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593804.0 | 510777.6 | 29027 | 1.64041666667 | 20963 |
| 019461 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:10pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593804.9 | 510779.9 | 29029 | 1.64041666667 | 19461 |
| 020405 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:11pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593806.5 | 510782.4 | 29031 | 1.64041666667 | 20405 |
| 023851 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:12pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593809.0 | 510785.0 | 29033 | 1.64041666667 | 23851 |
| 023062 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:13pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593811.5 | 510786.4 | 29035 | 1.64041666667 | 23062 |
| 023345 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:14pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593814.0 | 510788.6 | 29037 | 1.64041666667 | 23345 |
| 024976 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:15pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593816.3 | 510790.7 | 29039 | 1.64041666667 | 24976 |
| 025594 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:16pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593819.0 | 510792.9 | 29041 | 1.64041666667 | 25594 |
| 023858 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:17pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593820.9 | 510794.6 | 29043 | 1.64041666667 | 23858 |
| 019614 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:18pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593823.6 | 510796.5 | 29045 | 1.64041666667 | 19614 |
| 018703 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:19pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593825.3 | 510798.3 | 29047 | 1.64041666667 | 18703 |
| 017876 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:20pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593828.2 | 510800.8 | 29049 | 1.64041666667 | 17876 |
| 014249 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:21pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593830.7 | 510801.9 | 29051 | 1.64041666667 | 14249 |
| 013972 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:22pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593833.1 | 510803.9 | 29053 | 1.64041666667 | 13972 |
| 014323 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:23pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593835.4 | 510805.0 | 29055 | 1.64041666667 | 14323 |
| 016840 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:24pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593838.2 | 510806.6 | 29057 | 1.64041666667 | 16840 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 015670 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:25pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593840.6 | 510808.3 | 29059 | 1.64041666667 | 15670 |
| 014417 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:26pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593843.4 | 510809.9 | 29061 | 1.64041666667 | 14417 |
| 015754 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:27pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593845.4 | 510811.7 | 29063 | 1.64041666667 | 15754 |
| 016478 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:28pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593846.3 | 510813.0 | 29065 | 1.64041666667 | 16478 |
| 014229 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:29pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593844.7 | 510813.2 | 29067 | 1.64041666667 | 14229 |
| 014177 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:30pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593841.8 | 510812.4 | 29069 | 1.64041666667 | 14177 |
| 014644 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:31pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593839.7 | 510810.9 | 29071 | 1.64041666667 | 14644 |
| 013321 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:32pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593837.2 | 510809.2 | 29073 | 1.64041666667 | 13321 |
| 015570 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:33pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593834.9 | 510807.3 | 29075 | 1.64041666667 | 15570 |
| 014482 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:34pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593832.2 | 510804.9 | 29077 | 1.64041666667 | 14482 |
| 014990 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:35pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593829.7 | 510803.2 | 29079 | 1.64041666667 | 14990 |
| 014637 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:36pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593827.3 | 510800.8 | 29081 | 1.64041666667 | 14637 |
| 015959 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:37pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593825.1 | 510798.4 | 29083 | 1.64041666667 | 15959 |
| 016980 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:38pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593822.5 | 510796.2 | 29085 | 1.64041666667 | 16980 |
| 021435 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:39pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593820.8 | 510794.0 | 29087 | 1.64041666667 | 21435 |
| 024078 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:40pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593818.6 | 510791.1 | 29089 | 1.64041666667 | 24078 |
| 023899 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:41pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593816.4 | 510789.2 | 29091 | 1.64041666667 | 23899 |
| 023764 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:42pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593814.1 | 510786.8 | 29093 | 1.64041666667 | 23764 |
| 024571 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:43pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593811.7 | 510785.1 | 29095 | 1.64041666667 | 24571 |
| 021262 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:44pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593808.9 | 510783.4 | 29097 | 1.64041666667 | 21262 |
| 020885 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:45pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593806.9 | 510781.6 | 29099 | 1.64041666667 | 20885 |
| 020101 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:46pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593804.6 | 510779.9 | 29101 | 1.64041666667 | 20101 |
| 019635 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:47pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593802.1 | 510778.4 | 29103 | 1.64041666667 | 19635 |
| 020568 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:48pm | Sensor | 1797-S0029-G-TJV.cor | 6811.0 | 1593798.9 | 510778.7 | 29105 | 1.64041666667 | 20568 |
| 021942 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:49pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593798.6 | 510780.9 | 29107 | 1.64041666667 | 21942 |
| 021865 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:50pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593800.1 | 510783.8 | 29109 | 1.64041666667 | 21865 |
| 021216 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:51pm | Sensor | 1797-S0029-G-TJV.cor | 6811.1 | 1593801.0 | 510786.4 | 29111 | 1.64041666667 | 21216 |
| 023694 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:52pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593802.8 | 510789.0 | 29113 | 1.64041666667 | 23694 |
| 020443 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:53pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593804.4 | 510791.2 | 29115 | 1.64041666667 | 20443 |
| 018491 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:54pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593806.4 | 510794.0 | 29117 | 1.64041666667 | 18491 |
| 014822 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:55pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593808.3 | 510795.8 | 29119 | 1.64041666667 | 14822 |
| 014565 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:56pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593810.5 | 510798.1 | 29121 | 1.64041666667 | 14565 |
| 014441 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:57pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593812.8 | 510800.2 | 29123 | 1.64041666667 | 14441 |
| 016660 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:58pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593815.8 | 510802.2 | 29125 | 1.64041666667 | 16660 |
| 017455 | 0 | GeoXH 6000 | 08/18/2015 | 02:30:59pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593817.7 | 510804.1 | 29127 | 1.64041666667 | 17455 |
| 016783 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:00pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593820.4 | 510806.4 | 29129 | 1.64041666667 | 16783 |
| 015086 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:01pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593823.2 | 510808.2 | 29131 | 1.64041666667 | 15086 |
| 013461 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:02pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593825.8 | 510809.9 | 29133 | 1.64041666667 | 13461 |
| 014495 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:03pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593828.7 | 510811.4 | 29135 | 1.64041666667 | 14495 |
| 013823 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:04pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593831.9 | 510813.1 | 29137 | 1.64041666667 | 13823 |
| 012546 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:05pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593834.4 | 510814.8 | 29139 | 1.64041666667 | 12546 |
| 012436 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:06pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593837.1 | 510816.6 | 29141 | 1.64041666667 | 12436 |
| 013099 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:07pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593837.7 | 510818.2 | 29143 | 1.64041666667 | 13099 |
| 011674 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:08pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593836.7 | 510819.7 | 29145 | 1.64041666667 | 11674 |
| 012278 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:09pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593834.5 | 510819.9 | 29147 | 1.64041666667 | 12278 |
| 012759 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:10pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593831.7 | 510819.4 | 29149 | 1.64041666667 | 12759 |
| 014560 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:11pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593829.6 | 510818.2 | 29151 | 1.64041666667 | 14560 |
| 016240 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:12pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593826.4 | 510816.5 | 29153 | 1.64041666667 | 16240 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 017260 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:13pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593823.5 | 510815.0 | 29155 | 1.64041666667 | 17260 |
| 015145 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:14pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593820.8 | 510813.1 | 29157 | 1.64041666667 | 15145 |
| 014886 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:15pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593818.4 | 510811.5 | 29159 | 1.64041666667 | 14886 |
| 016081 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:16pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593815.2 | 510809.5 | 29161 | 1.64041666667 | 16081 |
| 016650 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:17pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593813.0 | 510807.7 | 29163 | 1.64041666667 | 16650 |
| 017002 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:18pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593810.2 | 510805.8 | 29165 | 1.64041666667 | 17002 |
| 013400 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:19pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593808.0 | 510803.7 | 29167 | 1.64041666667 | 13400 |
| 014240 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:20pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593806.0 | 510800.8 | 29169 | 1.64041666667 | 14240 |
| 011870 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:21pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593804.2 | 510798.6 | 29171 | 1.64041666667 | 11870 |
| 014277 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:22pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593801.8 | 510796.1 | 29173 | 1.64041666667 | 14277 |
| 019349 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:23pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593799.9 | 510794.0 | 29175 | 1.64041666667 | 19349 |
| 020497 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:24pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593797.2 | 510792.0 | 29177 | 1.64041666667 | 20497 |
| 018864 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:25pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593794.9 | 510790.5 | 29179 | 1.64041666667 | 18864 |
| 018576 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:26pm | Sensor | 1797-S0029-G-TJV.cor | 6810.9 | 1593792.1 | 510788.2 | 29181 | 1.64041666667 | 18576 |
| 022344 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:27pm | Sensor | 1797-S0029-G-TJV.cor | 6810.9 | 1593789.5 | 510786.4 | 29183 | 1.64041666667 | 22344 |
| 020106 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:28pm | Sensor | 1797-S0029-G-TJV.cor | 6810.9 | 1593787.5 | 510784.4 | 29185 | 1.64041666667 | 20106 |
| 021376 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:29pm | Sensor | 1797-S0029-G-TJV.cor | 6810.6 | 1593785.3 | 510782.3 | 29187 | 1.64041666667 | 21376 |
| 021244 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:30pm | Sensor | 1797-S0029-G-TJV.cor | 6810.5 | 1593782.5 | 510780.6 | 29189 | 1.64041666667 | 21244 |
| 019111 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:31pm | Sensor | 1797-S0029-G-TJV.cor | 6810.6 | 1593780.4 | 510779.0 | 29191 | 1.64041666667 | 19111 |
| 016447 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:32pm | Sensor | 1797-S0029-G-TJV.cor | 6810.5 | 1593777.8 | 510777.6 | 29193 | 1.64041666667 | 16447 |
| 013892 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:33pm | Sensor | 1797-S0029-G-TJV.cor | 6810.4 | 1593775.0 | 510775.8 | 29195 | 1.64041666667 | 13892 |
| 012893 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:34pm | Sensor | 1797-S0029-G-TJV.cor | 6810.3 | 1593771.8 | 510775.6 | 29197 | 1.64041666667 | 12893 |
| 011653 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:35pm | Sensor | 1797-S0029-G-TJV.cor | 6810.5 | 1593769.5 | 510777.3 | 29199 | 1.64041666667 | 11653 |
| 015693 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:36pm | Sensor | 1797-S0029-G-TJV.cor | 6810.6 | 1593767.9 | 510779.7 | 29201 | 1.64041666667 | 15693 |
| 016343 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:37pm | Sensor | 1797-S0029-G-TJV.cor | 6810.8 | 1593768.4 | 510781.8 | 29203 | 1.64041666667 | 16343 |
| 016115 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:38pm | Sensor | 1797-S0029-G-TJV.cor | 6810.9 | 1593770.5 | 510783.7 | 29205 | 1.64041666667 | 16115 |
| 018939 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:39pm | Sensor | 1797-S0029-G-TJV.cor | 6810.9 | 1593772.7 | 510785.9 | 29207 | 1.64041666667 | 18939 |
| 022434 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:40pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593775.1 | 510788.3 | 29209 | 1.64041666667 | 22434 |
| 021958 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:41pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593777.3 | 510789.9 | 29211 | 1.64041666667 | 21958 |
| 021239 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:42pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593779.9 | 510792.1 | 29213 | 1.64041666667 | 21239 |
| 020910 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:43pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593782.3 | 510794.2 | 29215 | 1.64041666667 | 20910 |
| 018937 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:44pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593785.2 | 510796.4 | 29217 | 1.64041666667 | 18937 |
| 019434 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:45pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593787.4 | 510798.3 | 29219 | 1.64041666667 | 19434 |
| 020518 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:46pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593790.3 | 510800.8 | 29221 | 1.64041666667 | 20518 |
| 016739 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:47pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593792.6 | 510802.6 | 29223 | 1.64041666667 | 16739 |
| 014145 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:48pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593795.1 | 510805.0 | 29225 | 1.64041666667 | 14145 |
| 011726 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:49pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593797.4 | 510806.9 | 29227 | 1.64041666667 | 11726 |
| 012051 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:50pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593800.1 | 510808.9 | 29229 | 1.64041666667 | 12051 |
| 012252 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:51pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593802.2 | 510811.0 | 29231 | 1.64041666667 | 12252 |
| 013653 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:52pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593804.9 | 510813.0 | 29233 | 1.64041666667 | 13653 |
| 015983 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:53pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593807.7 | 510815.2 | 29235 | 1.64041666667 | 15983 |
| 013295 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:54pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593810.3 | 510817.8 | 29237 | 1.64041666667 | 13295 |
| 015084 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:55pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593812.5 | 510819.4 | 29239 | 1.64041666667 | 15084 |
| 014691 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:56pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593815.6 | 510822.0 | 29241 | 1.64041666667 | 14691 |
| 014652 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:57pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593817.5 | 510823.9 | 29243 | 1.64041666667 | 14652 |
| 012573 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:58pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593820.1 | 510826.1 | 29245 | 1.64041666667 | 12573 |
| 012803 | 0 | GeoXH 6000 | 08/18/2015 | 02:31:59pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593821.8 | 510827.9 | 29247 | 1.64041666667 | 12803 |
| 013580 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:00pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593822.3 | 510828.8 | 29249 | 1.64041666667 | 13580 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 014525 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:01pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593821.4 | 510827.9 | 29251 | 1.64041666667 | 14525 |
| 014611 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:02pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593820.2 | 510824.7 | 29253 | 1.64041666667 | 14611 |
| 013762 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:03pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593820.2 | 510821.9 | 29255 | 1.64041666667 | 13762 |
| 013370 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:04pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593820.6 | 510818.0 | 29257 | 1.64041666667 | 13370 |
| 015102 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:05pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593820.7 | 510815.0 | 29259 | 1.64041666667 | 15102 |
| 015835 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:06pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593821.2 | 510811.3 | 29261 | 1.64041666667 | 15835 |
| 014519 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:07pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593821.5 | 510807.6 | 29263 | 1.64041666667 | 14519 |
| 014219 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:08pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593821.6 | 510803.7 | 29265 | 1.64041666667 | 14219 |
| 016815 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:09pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593821.6 | 510800.3 | 29267 | 1.64041666667 | 16815 |
| 018003 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:10pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593821.5 | 510796.5 | 29269 | 1.64041666667 | 18003 |
| 021210 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:11pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593821.3 | 510793.3 | 29271 | 1.64041666667 | 21210 |
| 026032 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:12pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593821.7 | 510789.7 | 29273 | 1.64041666667 | 26032 |
| 028918 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:13pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593821.9 | 510786.3 | 29275 | 1.64041666667 | 28918 |
| 027479 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:14pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593821.8 | 510782.5 | 29277 | 1.64041666667 | 27479 |
| 026070 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:15pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593821.9 | 510779.7 | 29279 | 1.64041666667 | 26070 |
| 023437 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:16pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593822.3 | 510775.7 | 29281 | 1.64041666667 | 23437 |
| 016899 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:17pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593822.1 | 510772.3 | 29283 | 1.64041666667 | 16899 |
| 015744 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:18pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593821.9 | 510769.1 | 29285 | 1.64041666667 | 15744 |
| 014376 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:19pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593821.8 | 510765.8 | 29287 | 1.64041666667 | 14376 |
| 014934 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:20pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593821.8 | 510762.6 | 29289 | 1.64041666667 | 14934 |
| 013963 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:21pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593822.5 | 510760.5 | 29291 | 1.64041666667 | 13963 |
| 011591 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:22pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593823.5 | 510758.7 | 29293 | 1.64041666667 | 11591 |
| 013547 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:23pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593825.6 | 510758.5 | 29295 | 1.64041666667 | 13547 |
| 014006 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:24pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593828.5 | 510760.3 | 29297 | 1.64041666667 | 14006 |
| 012081 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:25pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593830.3 | 510762.4 | 29299 | 1.64041666667 | 12081 |
| 014960 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:26pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593832.9 | 510764.6 | 29301 | 1.64041666667 | 14960 |
| 012650 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:27pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593835.2 | 510766.4 | 29303 | 1.64041666667 | 12650 |
| 011682 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:28pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593838.2 | 510768.8 | 29305 | 1.64041666667 | 11682 |
| 012580 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:29pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593840.6 | 510770.2 | 29307 | 1.64041666667 | 12580 |
| 016045 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:30pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593843.1 | 510771.9 | 29309 | 1.64041666667 | 16045 |
| 014661 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:31pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593845.7 | 510773.9 | 29311 | 1.64041666667 | 14661 |
| 016295 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:32pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593848.5 | 510776.3 | 29313 | 1.64041666667 | 16295 |
| 015713 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:33pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593850.8 | 510779.0 | 29315 | 1.64041666667 | 15713 |
| 014938 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:34pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593853.4 | 510781.4 | 29317 | 1.64041666667 | 14938 |
| 015164 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:35pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593856.3 | 510783.6 | 29319 | 1.64041666667 | 15164 |
| 015191 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:36pm | Sensor | 1797-S0029-G-TJV.cor | 6812.3 | 1593858.8 | 510786.2 | 29321 | 1.64041666667 | 15191 |
| 015737 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:37pm | Sensor | 1797-S0029-G-TJV.cor | 6812.3 | 1593861.3 | 510787.9 | 29323 | 1.64041666667 | 15737 |
| 016834 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:38pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593864.4 | 510789.8 | 29325 | 1.64041666667 | 16834 |
| 016988 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:39pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593865.5 | 510792.1 | 29327 | 1.64041666667 | 16988 |
| 016907 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:40pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593865.7 | 510793.9 | 29329 | 1.64041666667 | 16907 |
| 017576 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:41pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593864.4 | 510794.3 | 29331 | 1.64041666667 | 17576 |
| 015404 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:42pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593862.1 | 510793.2 | 29333 | 1.64041666667 | 15404 |
| 016691 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:43pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593859.8 | 510791.9 | 29335 | 1.64041666667 | 16691 |
| 014912 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:44pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593856.7 | 510790.2 | 29337 | 1.64041666667 | 14912 |
| 015668 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:45pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593854.5 | 510788.7 | 29339 | 1.64041666667 | 15668 |
| 016607 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:46pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593851.5 | 510787.0 | 29341 | 1.64041666667 | 16607 |
| 014441 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:47pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593848.5 | 510785.5 | 29343 | 1.64041666667 | 14441 |
| 017590 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:48pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593845.9 | 510783.5 | 29345 | 1.64041666667 | 17590 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 019307 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:49pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593843.6 | 510781.6 | 29347 | 1.64041666667 | 19307 |
| 016796 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:50pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593840.3 | 510779.1 | 29349 | 1.64041666667 | 16796 |
| 020039 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:51pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593838.2 | 510777.2 | 29351 | 1.64041666667 | 20039 |
| 018660 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:52pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593835.1 | 510775.7 | 29353 | 1.64041666667 | 18660 |
| 017685 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:53pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593832.8 | 510774.2 | 29355 | 1.64041666667 | 17685 |
| 017081 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:54pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593830.0 | 510772.0 | 29357 | 1.64041666667 | 17081 |
| 015520 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:55pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593827.6 | 510770.4 | 29359 | 1.64041666667 | 15520 |
| 012850 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:56pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593824.8 | 510768.2 | 29361 | 1.64041666667 | 12850 |
| 014072 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:57pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593822.7 | 510765.9 | 29363 | 1.64041666667 | 14072 |
| 015548 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:58pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593820.0 | 510763.7 | 29365 | 1.64041666667 | 15548 |
| 014117 | 0 | GeoXH 6000 | 08/18/2015 | 02:32:59pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593817.6 | 510762.2 | 29367 | 1.64041666667 | 14117 |
| 013699 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:00pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593814.9 | 510762.3 | 29369 | 1.64041666667 | 13699 |
| 015604 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:01pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593814.0 | 510764.7 | 29371 | 1.64041666667 | 15604 |
| 018001 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:02pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593815.1 | 510767.9 | 29373 | 1.64041666667 | 18001 |
| 017520 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:03pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593816.7 | 510770.7 | 29375 | 1.64041666667 | 17520 |
| 017100 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:04pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593818.8 | 510772.9 | 29377 | 1.64041666667 | 17100 |
| 019335 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:05pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593821.5 | 510775.2 | 29379 | 1.64041666667 | 19335 |
| 022803 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:06pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593823.9 | 510777.8 | 29381 | 1.64041666667 | 22803 |
| 025501 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:07pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593826.0 | 510779.5 | 29383 | 1.64041666667 | 25501 |
| 024675 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:08pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593828.2 | 510781.6 | 29385 | 1.64041666667 | 24675 |
| 024048 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:09pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593830.3 | 510783.5 | 29387 | 1.64041666667 | 24048 |
| 020592 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:10pm | Sensor | 1797-S0029-G-TJV.cor | 6811.8 | 1593833.2 | 510785.6 | 29389 | 1.64041666667 | 20592 |
| 018918 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:11pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593835.0 | 510787.7 | 29391 | 1.64041666667 | 18918 |
| 017839 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:12pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593837.7 | 510789.9 | 29393 | 1.64041666667 | 17839 |
| 015739 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:13pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593840.6 | 510791.8 | 29395 | 1.64041666667 | 15739 |
| 015395 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:14pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593843.2 | 510794.1 | 29397 | 1.64041666667 | 15395 |
| 017498 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:15pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593845.5 | 510795.7 | 29399 | 1.64041666667 | 17498 |
| 018744 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:16pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593848.5 | 510798.2 | 29401 | 1.64041666667 | 18744 |
| 019536 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:17pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593850.3 | 510800.3 | 29403 | 1.64041666667 | 19536 |
| 017274 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:18pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593852.7 | 510802.3 | 29405 | 1.64041666667 | 17274 |
| 018418 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:19pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593854.0 | 510804.2 | 29407 | 1.64041666667 | 18418 |
| 019874 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:20pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593854.5 | 510805.9 | 29409 | 1.64041666667 | 19874 |
| 017508 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:21pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593852.5 | 510806.6 | 29411 | 1.64041666667 | 17508 |
| 017397 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:22pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593849.6 | 510806.3 | 29413 | 1.64041666667 | 17397 |
| 014939 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:23pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593847.3 | 510805.0 | 29415 | 1.64041666667 | 14939 |
| 016245 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:24pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593844.6 | 510803.4 | 29417 | 1.64041666667 | 16245 |
| 015071 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:25pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593842.7 | 510801.6 | 29419 | 1.64041666667 | 15071 |
| 015677 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:26pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593840.1 | 510799.4 | 29421 | 1.64041666667 | 15677 |
| 015889 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:27pm | Sensor | 1797-S0029-G-TJV.cor | 6812.1 | 1593837.8 | 510797.5 | 29423 | 1.64041666667 | 15889 |
| 014262 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:28pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593835.4 | 510795.5 | 29425 | 1.64041666667 | 14262 |
| 017065 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:29pm | Sensor | 1797-S0029-G-TJV.cor | 6812.2 | 1593833.1 | 510794.2 | 29427 | 1.64041666667 | 17065 |
| 015456 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:30pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593830.1 | 510792.2 | 29429 | 1.64041666667 | 15456 |
| 017574 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:31pm | Sensor | 1797-S0029-G-TJV.cor | 6812.0 | 1593828.0 | 510790.1 | 29431 | 1.64041666667 | 17574 |
| 023443 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:32pm | Sensor | 1797-S0029-G-TJV.cor | 6811.9 | 1593825.5 | 510788.0 | 29433 | 1.64041666667 | 23443 |
| 027281 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:33pm | Sensor | 1797-S0029-G-TJV.cor | 6811.7 | 1593823.6 | 510786.3 | 29435 | 1.64041666667 | 27281 |
| 028300 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:34pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593821.1 | 510784.0 | 29437 | 1.64041666667 | 28300 |
| 027355 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:35pm | Sensor | 1797-S0029-G-TJV.cor | 6811.4 | 1593819.0 | 510782.4 | 29439 | 1.64041666667 | 27355 |
| 024088 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:36pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593816.8 | 510780.3 | 29441 | 1.64041666667 | 24088 |

| | | | | | | | | | | | | |
|--------|---|------------|------------|------------|--------|----------------------|--------|-----------|----------|-------|---------------|-------|
| 022124 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:37pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593814.9 | 510778.5 | 29443 | 1.64041666667 | 22124 |
| 020150 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:38pm | Sensor | 1797-S0029-G-TJV.cor | 6811.2 | 1593812.8 | 510776.4 | 29445 | 1.64041666667 | 20150 |
| 021147 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:39pm | Sensor | 1797-S0029-G-TJV.cor | 6811.3 | 1593812.2 | 510774.7 | 29447 | 1.64041666667 | 21147 |
| 018757 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:40pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593813.0 | 510773.1 | 29449 | 1.64041666667 | 18757 |
| 016119 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:41pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593814.7 | 510772.8 | 29451 | 1.64041666667 | 16119 |
| 017019 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:42pm | Sensor | 1797-S0029-G-TJV.cor | 6811.5 | 1593816.6 | 510773.5 | 29453 | 1.64041666667 | 17019 |
| 017485 | 0 | GeoXH 6000 | 08/18/2015 | 02:33:43pm | Sensor | 1797-S0029-G-TJV.cor | 6811.6 | 1593817.1 | 510773.8 | 29455 | 1.64041666667 | 17485 |