

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

March 13, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT UNIT A1 - REPORTABLE DEFICIENCY - RPV SHIELD
WALL - WELD DEFICIENCIES (NCR HNP-A-087)

Initial report of the subject deficiency was made to R. W. Wright,
NRC-OIE, Region II, on February 15, 1980. In compliance with
paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the first
interim report of the subject deficiency. TVA anticipates transmitting
the final report on or before May 30, 1980. If you have any questions
regarding this matter, please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager

Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555 ✓

Boia
5/11