



VERMONT YANKEE NUCLEAR POWER CORPORATION

SEVENTY SEVEN GROVE STREET
RUTLAND, VERMONT 05701

B.3.2.1

REPLY TO: WYV 80-42
ENGINEERING OFFICE
TURNPIKE ROAD

WESTBORO, MASSACHUSETTS 01581
TELEPHONE 617-366-9011

March 14, 1980

United States Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Office of Nuclear Reactor Regulation
Mr. Thomas A. Ippolito, Chief
Operating Reactors Branch #3
Division of Operating Reactors

References: 1. License No. DPR-28 (Docket 50-271)
2. USNRC Letter, dated December 13, 1979, Ippolito
to Groce
3. VYNPC Letter VYV-2364, dated December 13, 1972,
Jones to Directorate of Licensing (attached)

Subject: Loss of Offsite Power

Dear Sir:

In response to NRC's Request for Information, Reference (2), the following
is submitted:

- A. Loss of off-site power events at Vermont Yankee where less than all off-site power sources were lost is tabulated in the attached table.
- B. Vermont Yankee has not experienced an event which caused the concurrent loss of all off-site power sources.
- C. There are no other loss of off-site power events other than those events noted in item (A) above.

We trust that the above supplied information adequately addresses the requests contained in Reference (2); however, should you desire any additional information, do not hesitate to call.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

for *RJWanczyk*
W. F. Conway
Manager of Operations

RJW:cjp

8003190644