

**Florida
Power**
CORPORATION

March 17, 1980

File: 3-0-3-a-3

Mr. Darrell G. Eisenhut
Acting Director
Division of Operating Reactors
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Crystal River Unit No. 3
Docket No. 50-302
Operating License No. DPR-72
Cracks in Keyway and Bore Sections of Westinghouse
1800 rpm Low Pressure Turbines

Dear Mr. Eisenhut:

On February 27, 1980, Florida Power Corporation received your letter of February 25, 1980 requesting full UT inspection of LP rotor discs within 20 days of the date of your letter, or prior to restart if our unit was not operating.

The purpose of this letter is to inform you that since Crystal River Unit 3 is presently in a refueling outage, Westinghouse will perform a full UT inspection. Therefore, prior to the plant returning to power we will provide you with the information you requested.

Should you have any questions concerning this subject, please contact this office.

Very truly yours,

FLORIDA POWER CORPORATION

Ronald M. Bright
Acting Manager
Nuclear Support Services

RMBemhF02D3


STATE OF FLORIDA
COUNTY OF PINELLAS

R. M. Bright states that he is the Acting Manager, Nuclear Support Services, of Florida Power Corporation; that he is authorized on the part of said company to sign and file with the Nuclear Regulatory Commission the information attached hereto; and that all such statements made and matters set forth therein are true and correct to the best of his knowledge, information and belief.



R. M. Bright

Subscribed and sworn to before me, a Notary Public in and for the State and County above named, this 17th day of March, 1980.



Notary Public

Notary Public, State of Florida at Large,
My Commission Expires: August 8, 1983

CameronNotary 3(D12)